

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: February 4, 2021

Final Estimate Number	Contract ID 200117-F06	Pay Period Start February 2, 2021 Original Contract Amount \$3,235,828.41
21	Prime Contractor Parking Lot Maintenance, L	LC Pay Period End February 4, 2021 Net Change Order Amount \$146,276.64
21		Current Contract Amount \$3,382,105.05

Approval Date		By User
March 10, 2021	Generated and Approved (and should be considered Draft) at the Project Office Level by	lewisj1
March 11, 2021	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	holdtc
March 17, 2021	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete		
December 1, 2020	December 1, 2020	December 1, 2020	100.00%		

Contract Informational Dates										
Date Description	Original Completion Date	Current Completion Date								
Acceptance Date	January 19, 2021	January 19, 2021								
Awarded Date	February 5, 2020	February 5, 2020								
Letting Date	January 17, 2020	January 17, 2020								
Notice to Proceed Date	April 6, 2020	April 6, 2020								
Open to Traffic Date										
Work Began	April 20, 2020	April 20, 2020								

Date Description	Original Completion Date	Current Completion Date	Days Remaining on Milestone	Diary Charge Days
Milestone - Calendar Time Total days allowed once bridge work begins	July 21, 2020	July 21, 2020	Milestone Complete	

Milestones

Contract Total Pay For Estimate No. 21											
		This Estimate	Previous	To Date							
200117-F06											
	Total Posted Items Pay	\$0.00	\$3,382,105.07	\$3,382,105.07							
	Gross Item Adjustments	\$0.00	\$202.15	\$202.15							
	Incentive	\$0.00	\$0.00	\$0.00							
	Disincentive	\$0.00	\$0.00	\$0.00							
	Liquidated Damage	\$0.00	\$0.00	\$0.00							
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00							
			\$3,382,307.22	\$3,382,307.22							
Contract Total Pay	yable This Estimate:	\$0.00									

Items Paid This Estimate Period

No Data Available

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

No Data Available

Revision 4/1/2020 Page 1 of 19



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					С	ontract Project Information	n
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
S501(60) and bridge		Resurface and bridge rehabilitation	A	ST CHARLES	from Route 61 to I-70		
Γotals by J	Job Numbe	rs					
J6S3319					This Estimate	Previous	To Date
		Posted Item Pay Gross Item Adjustments			\$0.00 \$0.00	\$3,382,105.07 \$202.15	\$3,382,105.07 \$202.15
			Gross	Item Pay	\$0.00	\$3,382,307.22	\$3,382,307.22
	Incent	tive			\$0.00	\$0.00	\$0.00
	Disino	entive			\$0.00	\$0.00	\$0.00
	Liquid	lated Damages	\$		\$0.00	\$0.00	\$0.00
	Other	Contract Adiu	stments		\$0.00	\$0.00	\$0.00

Revision 4/1/2020 Page 2 of 19





Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period No Exceptions Exist on Contract

Revision 4/1/2020 Page 3 of 19



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	eport Generated date and can differ from the posted amo Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200117-F06	J6S3319	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$56,000.00	\$56,000.00
		0001	0020	2063000	CLASS 3 EXCAVATION	12.00	-8.00	4.00	CUYD	4.00	\$75.00	\$300.00
		0001	0030	2153000	SHAPING SLOPES, CLASS III	5.00	0.00	5.00	100F	5.00	\$900.00	\$4,500.00
		0001	0040	5041000	CONCRETE APPROACH PAVEMENT	920.30	0.00	920.30	SQYD	920.30	\$75.00	\$69,022.50
		0001	0050	6094010	DRAIN BASIN	2.00	0.00	2.00	EA	2.00	\$4,400.00	\$8,800.00
		0001	0060	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	7.00	0.00	7.00	CUYD	7.00	\$27.00	\$189.00
		0001	0070	6096041	PLACING TYPE 1 ROCK DITCH LINER	7.00	0.00	7.00	CUYD	7.00	\$105.00	\$735.00
		0001	0080	6116010A	SLOPE PROTECTION	222.00	-110.00	112.00	SQYD	112.00	\$110.00	\$12,320.00
		0001	0090	6122012	IMPACT ATTENUATOR 55 MPH (SAND BARREL ARRAY)	2.00	0.00	2.00	EA	2.00	\$3,010.00	\$6,020.00
		0001	0100	6122020	REPLACEMENT SAND BARREL	3.00	-3.00	0.00	EA	0.00	\$396.00	\$0.00
		0001	0110	6122030	IMPACT ATTENUATOR (RELOCATION)	2.00	0.00	2.00	EA	2.00	\$687.00	\$1,374.00
		0001	0120	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$6,000.00	\$12,000.00
		0001	0130	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	3,536.00	103.00	3,639.00	SQYD	3,639.00	\$165.00	\$600,435.00
		0001	0140	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	444.00	-444.00	0.00	SQYD	0.00	\$20.00	\$0.00
		0001	0150	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	354.00	-354.00	0.00	SQYD	0.00	\$2.50	\$0.00
		0001	0160	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	14,694.00	0.00	14,694.00	LF	14,694.00	\$3.00	\$44,082.00
		0001	0170	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	4,450.00	0.00	4,450.00	EA	4,450.00	\$5.75	\$25,587.50
		0001	0180	6131017	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	28.00	0.00	28.00	EA	28.00	\$3.75	\$105.00
		0001	0190	6131018	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	451.00	0.00	451.00	EA	451.00	\$2.45	\$1,104.95
		0001	0200	6139911	MISC.REMOVAL, FURNISHING AND PLACING HOT POLYMER CONCRETE PATCHING FOR CLASS A PARTIAL DEPTH PVMT REPAIR	401,792.00	49,342.00	451,134.00	LB	451,134.00	\$3.35	\$1,511,298.90
		0001	0210	6161005	CONSTRUCTION SIGNS	798.00	0.00	798.00	SQFT	798.00	\$8.00	\$6,384.00
		0001	0220	6161008	ADVANCED WARNING RAIL SYSTEM	22.00	0.00	22.00	EA	22.00	\$35.00	\$770.00
		0001	0230	6161009	FLAG ASSEMBLY	15.00	-15.00	0.00	EA	0.00	\$25.00	\$0.00
		0001	0240	6161025	CHANNELIZER (TRIM LINE)	364.00	0.00	364.00	EA	364.00	\$20.00	\$7,280.00
		0001	0250	6161030	TYPE III MOVEABLE BARRICADE	8.00	-8.00	0.00	EA	0.00	\$100.00	\$0.00
		0001	0260	6161033	DIRECTIONAL INDICATOR BARRICADE	44.00	0.00	44.00	EA	44.00	\$65.00	\$2,860.00
		0001	0270	6161040	FLASHING ARROW PANEL	3.00	0.00	3.00	EA	3.00	\$850.00	\$2,550.00
		0001	0280	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN (CONTRACTOR FURNISHED / RETAINED	2.00	0.00	2.00	EA	2.00	\$2,800.00	\$5,600.00
		0001	0290	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	1,050.00	0.00	1,050.00	LF	1,050.00	\$21.94	\$23,037.00
		0001	0300	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	1,050.00	0.00	1,050.00	LF	1,050.00	\$7.02	\$7,369.95
		0001	0310	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$168,321.54	\$168,321.54
		0001	0320	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	3.00	0.00	3.00	EA	3.00	\$350.00	\$1,050.00
		0001	0330	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	5,511.00	0.00	5,511.00	LF	5,511.00	\$1.00	\$5,511.00
		0001	0340	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	8,663.00	0.00	8,663.00	LF	8,663.00	\$1.00	\$8,663.00
		0001	0350	6205440A	TEMPORARY NON-REMOVABLE MARKING TAPE LEFT/RIGHT ARROW	1.00	0.00	1.00	EA	1.00	\$300.00	\$300.00
		0001	0360	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	6,220.00	0.00	6,220.00	LF	6,220.00	\$0.25	\$1,555.00
		0001	0370	6206001C		9,952.00	0.00	9,952.00	LF	9,952.00	\$0.25	\$2,488.00
		0001	0380	6207001	PAVEMENT MARKING REMOVAL	25,370.00	0.00	25,370.00	LF	25,370.00	\$0.75	\$19,027.50
		0001	0390	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	5.00	0.00	5.00	EA	5.00	\$100.00	\$500.00
		0001	0400	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$1,500.00	\$1,500.00
		0001	0410	8051000A	SEEDING - COOL SEASON MIXTURES	0.10	-0.10	0.00	ACRE	0.00	\$10,000.00	\$0.00
		0001	0420	8061005	ROCK DITCH CHECK	60.00	-60.00	0.00	LF	0.00	\$50.00	\$0.00
		0001	0430	8061016	SEDIMENT REMOVAL	8.00	-8.00	0.00	CUYD	0.00	\$31.25	\$0.00

Page 4 of 19 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200117-F06	J6S3319	0001	0440	8061019	SILT FENCE	405.00	-210.00	195.00	LF	195.00	\$2.26	\$440.70
		0010	0450	6061060	MGS GUARDRAIL	213.00	0.00	213.00	LF	213.00	\$21.00	\$4,473.00
		0010	0460	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	2,650.00	0.00	2,650.00	LF	2,650.00	\$23.00	\$60,950.00
		0010	0470	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	4.00	0.00	4.00	EA	4.00	\$3,000.00	\$12,000.00
		0010	0480	6061080	MGS END ANCHOR	1.00	0.00	1.00	EA	1.00	\$1,000.00	\$1,000.00
		0010	0490	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	5.00	0.00	5.00	EA	5.00	\$2,800.00	\$14,000.00
		0070	0500	2161000	SCARIFICATION OF BRIDGE DECK	3,003.00	0.00	3,003.00	SQYD	3,003.00	\$6.67	\$20,030.01
		0070	0510	2161503	REMOVAL OF EXISTING DECK REPAIR	25.00	0.00	25.00	SQFT	25.00	\$71.00	\$1,775.00
		0070	0520	2169903	MISC.Remove and Replace Barrier Curb	10.00	1.00	11.00	LF	11.00	\$350.00	\$3,850.00
		0070	0530	2169904	MISC.Removal of Existing Approach Slab	4,784.00	0.00	4,784.00	SQFT	4,784.00	\$6.00	\$28,704.00
		0070	0540	5031010A	BRIDGE APPROACH SLAB (MAJOR ROAD)	330.00	0.00	330.00	SQYD	330.00	\$275.00	\$90,750.00
		0070	0550	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	3,003.00	0.00	3,003.00	SQYD	3,003.00	\$85.00	\$255,255.00
		0070	0070 0560 7031004 DIAMOND GRINDING		3,003.00	-3,003.00	0.00	SQYD	0.00	\$6.32	\$0.00	
		0070 0570 7039902 0070 0580 7040102		7039902	MISC.Pile Encasement	25.00	0.00	25.00	EA	25.00	\$2,300.00	\$57,500.00
				7040102	SUBSTRUCTURE REPAIR (UNFORMED)	200.00	-195.50	4.50	SQFT	4.50	\$15.00	\$67.50
		0070	0590	7040106	FULL DEPTH REPAIR	200.00	-200.00	0.00	SQFT	0.00	\$40.00	\$0.00
		0070	0600	7040109	TOTAL SURFACE HYDRO DEMOLITION	3,003.00	0.00	3,003.00	SQYD	3,003.00	\$43.00	\$129,129.00
		0070	0610	7040113	CLEANING AND EPOXY COATING	CLEANING AND EPOXY COATING 2,116.00 0.00 2,116.00 SQFT 2,116.00				2,116.00	\$15.00	\$31,740.00
		0070	0620	7040117	MONOLITHIC DECK REPAIR	41.00	33.00	74.00	CUYD	74.00	\$700.00	\$51,800.00
					Pate as of Report Generated Date							\$3,382,105.05
200117-F06 Ove	erall - Total	Value Post	ted to Dat	te as of Repo	ort Generated Date							\$3,382,105.05

Revision 4/1/2020 Page 5 of 19



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 4/1/2020 Page 6 of 19



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks						
0040	CONCRETE APPROACH PAVEMENT	Material		5	Jun 15, 2020	SYSTEM	(\$34,509.75)							
										6	Jul 1, 2020	SYSTEM	(\$34,509.75)	
				7	Jul 16, 2020	SYSTEM	(\$69,022.50)							
				8	Aug 4, 2020	SYSTEM	(\$69,022.50)							
				9	Aug 18, 2020	SYSTEM	(\$69,022.50)							
				10	Sep 2, 2020	SYSTEM	(\$69,022.50)							
				11	Sep 16, 2020	SYSTEM	(\$69,022.50)							
				11	Sep 16, 2020	SYSTEM	\$69,022.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user dukesm1 overridding Payment Estimate Exception 7 on the current Payment Estimate.						
				12	Oct 1, 2020	SYSTEM	(\$69,022.50)							
				12	Oct 2, 2020	SYSTEM	\$69,022.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user dukesm1 overridding Payment Estimate Exception 6 on the current Payment Estimate.						
				13	Oct 16, 2020	SYSTEM	(\$69,022.50)							
				13	Oct 16, 2020	SYSTEM	\$69,022.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user dukesm1 overridding Payment Estimate Exception 6 on the current Payment Estimate.						
				14	Nov 2, 2020	SYSTEM	(\$69,022.50)							
				14	Nov 2, 2020	SYSTEM	\$69,022.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user dukesm1 overridding Payment Estimate Exception 6 on the current Payment Estimate.						
				15	Nov 16, 2020	SYSTEM	(\$69,022.50)							
				15	Nov 16, 2020	SYSTEM	\$69,022.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user dukesm1 overridding Payment Estimate Exception 6 on the current Payment Estimate.						
				16	Dec 3, 2020	SYSTEM	(\$69,022.50)							
				16	Dec 3, 2020	SYSTEM	\$69,022.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user dukesm1 overridding Payment Estimate Exception 5 on the current Payment Estimate.						
				17	Dec 16, 2020	SYSTEM	(\$69,022.50)							
				17	Dec 16, 2020	SYSTEM	\$69,022.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user dukesm1 overridding Payment Estimate Exception 4 on the current Payment Estimate.						
				18	Jan 4, 2021	SYSTEM	(\$69,022.50)							
				18	Jan 4, 2021	SYSTEM	\$69,022.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user dukesm1 overridding Payment Estimate Exception 7 on the current Payment Estimate.						
				19	Jan 19, 2021	SYSTEM	(\$69,022.50)							
				19	Jan 19, 2021	SYSTEM	\$69,022.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user dukesm1 overridding Payment Estimate Exception 7 on the current Payment Estimate.						
				20	Feb 2, 2021	SYSTEM	(\$69,022.50)							
				20	Feb 2, 2021	SYSTEM	\$69,022.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user dukesm1						

Revision 4/1/2020 Page 7 of 19



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0040	CONCRETE APPROACH PAVEMENT						overridding Payment Estimate Exception 1 on the current Payment Estimate.	
		- Total				(\$345,109.50)		
	Material - Total						(\$345,109.50)	
	CONCRETE APPROACH PAVEMENT	MaterialCredit		6	Jul 1, 2020	SYSTEM	\$34,509.75	
				7	Jul 16, 2020	SYSTEM	\$34,509.75	
				8	Aug 4, 2020	SYSTEM	\$69,022.50	
				9	Aug 18, 2020	SYSTEM	\$69,022.50	
				10	Sep 2, 2020	SYSTEM	\$69,022.50	
				11	Sep 16, 2020	SYSTEM	\$69,022.50	
			- Total				\$345,109.50	
	MaterialCredit - Total						\$345,109.50	
0040 -	Total						\$0.00	
0050	DRAIN BASIN	Material		11	Sep 16, 2020	SYSTEM	(\$8,800.00)	
				11	Sep 16, 2020	SYSTEM	\$8,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user dukesm1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$8,800.00)	
				12	Oct 2, 2020	SYSTEM	\$8,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user dukesm1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				13	Oct 16, 2020	SYSTEM	(\$8,800.00)	
				13	Oct 16, 2020	SYSTEM	\$8,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user dukesm1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
		- Total				\$0.00		
	Material - Total						\$0.00	
0050 -	Total						\$0.00	
0060	FURNISHING TYPE 1 ROCK DITCH LINER	Material		11	Sep 16, 2020	SYSTEM	(\$189.00)	
				11	Sep 16, 2020	SYSTEM	\$189.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user dukesm1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$189.00)	
				12	Oct 2, 2020	SYSTEM	\$189.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user dukesm1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total					\$0.00		
0060 -	Total						\$0.00	
0800	SLOPE PROTECTION	Material		8	Aug 4, 2020	SYSTEM	(\$12,320.00)	
				9	Aug 18, 2020	SYSTEM	(\$12,320.00)	
				10	Sep 2, 2020	SYSTEM	(\$12,320.00)	
				11	Sep 16, 2020	SYSTEM	(\$12,320.00)	
				12	Oct 1, 2020	SYSTEM	(\$12,320.00)	

Revision 4/1/2020 Page 8 of 19



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0800	SLOPE PROTECTION	Material		13	Oct 16, 2020	SYSTEM	(\$12,320.00)	
				14	Nov 2, 2020	SYSTEM	(\$12,320.00)	
				15	Nov 16, 2020	SYSTEM	(\$12,320.00)	
				16	Dec 3, 2020	SYSTEM	(\$12,320.00)	
				17	Dec 16, 2020	SYSTEM	(\$12,320.00)	
				18	Jan 4, 2021	SYSTEM	(\$12,320.00)	
				18	Jan 4, 2021	SYSTEM	\$12,320.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user dukesm1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				19	Jan 19, 2021	SYSTEM	(\$12,320.00)	
				19	Jan 19, 2021	SYSTEM	\$12,320.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user dukesm1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
			- Total				(\$123,200.00)	
	Material - Total						(\$123,200.00)	
	SLOPE PROTECTION	MaterialCredit		9	Aug 18, 2020	SYSTEM	\$12,320.00	
				10	Sep 2, 2020	SYSTEM	\$12,320.00	
				11	Sep 16, 2020	SYSTEM	\$12,320.00	
				12	Oct 1, 2020	SYSTEM	\$12,320.00	
				13	Oct 16, 2020	SYSTEM	\$12,320.00	
				14	Nov 2, 2020	SYSTEM	\$12,320.00	
				15	Nov 16, 2020	SYSTEM	\$12,320.00	
				16	Dec 3, 2020	SYSTEM	\$12,320.00	
				17	Dec 16, 2020	SYSTEM	\$12,320.00	
				18	Jan 4, 2021	SYSTEM	\$12,320.00	
	MetariclCredit Total		- Total				\$123,200.00	
0000	MaterialCredit - Total						\$123,200.00	
	Total	Motorial		10	So= 0	ever-1	\$0.00	
0130	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material		10	Sep 2, 2020	SYSTEM	(\$583,440.00)	
				11	Sep 16, 2020	SYSTEM	(\$583,440.00)	
				11	Sep 16, 2020	SYSTEM	\$583,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user dukesm1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$583,440.00)	
				12	Oct 2, 2020	SYSTEM	\$583,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user dukesm1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
				13	Oct 16, 2020	SYSTEM	(\$583,440.00)	
				13	Oct 16, 2020	SYSTEM	\$583,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user dukesm1 overridding Payment Estimate Exception 18 on the current

Revision 4/1/2020 Page 9 of 19



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
		Туре	Adjustment Type	Number	Date	Ву		
0130	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT	Material						Payment Estimate.
	REPAIR			14	Nov 2, 2020	SYSTEM	(\$583,440.00)	
				14	Nov 2, 2020	SYSTEM	\$583,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user dukesm1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				15	Nov 16, 2020	SYSTEM	(\$583,440.00)	
				15	Nov 16, 2020	SYSTEM	\$583,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user dukesm1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				16	Dec 3, 2020	SYSTEM	(\$229,147.88)	
				16	Dec 3, 2020	SYSTEM	\$229,147.88	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user dukesm1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				17	Dec 16, 2020	SYSTEM	(\$229,147.88)	
				17	Dec 16, 2020	SYSTEM	\$229,147.88	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user dukesm1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
			- Total				(\$583,440.00)	
	Material - Total						(\$583,440.00)	
	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	MaterialCredit		11	Sep 16, 2020	SYSTEM	\$583,440.00	
			- Total				\$583,440.00	
	MaterialCredit - Total						\$583,440.00	
							\$505,440.00	
0130 -	Total						\$0.00	
0130 - 0170	Total DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material		9	Aug 18, 2020	SYSTEM		
	Total DOWEL BAR (DRILLING, FURNISHING	Material		9		SYSTEM SYSTEM	\$0.00	
	Total DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material			2020 Sep 2,		\$0.00 (\$9,890.00)	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user dukesm1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
	Total DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material		10	2020 Sep 2, 2020 Sep 2,	SYSTEM	\$0.00 (\$9,890.00) (\$25,587.50)	Payment Estimate Item Adjustment (0007) due to user dukesm1 overridding Payment Estimate Exception 19 on the current
	Total DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material		10	2020 Sep 2, 2020 Sep 2, 2020 Sep 16,	SYSTEM	\$0.00 (\$9,890.00) (\$25,587.50) \$25,587.50	Payment Estimate Item Adjustment (0007) due to user dukesm1 overridding Payment Estimate Exception 19 on the current
	Total DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material		10 10 11	2020 Sep 2, 2020 Sep 2, 2020 Sep 16, 2020 Sep 16,	SYSTEM SYSTEM	\$0.00 (\$9,890.00) (\$25,587.50) \$25,587.50	Payment Estimate Item Adjustment (0007) due to user dukesm1 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user dukesm1 overridding Payment Estimate Exception 23 on the current
	Total DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material		10 10 11 11	2020 Sep 2, 2020 Sep 2, 2020 Sep 16, 2020 Sep 16, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 (\$9,890.00) (\$25,587.50) \$25,587.50 (\$25,587.50) \$25,587.50	Payment Estimate Item Adjustment (0007) due to user dukesm1 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user dukesm1 overridding Payment Estimate Exception 23 on the current
	Total DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material		10 10 11 11 11	2020 Sep 2, 2020 Sep 2, 2020 Sep 16, 2020 Sep 16, 2020 Oct 1, 2020 Oct 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$9,890.00) (\$25,587.50) \$25,587.50 (\$25,587.50) \$25,587.50	Payment Estimate Item Adjustment (0007) due to user dukesm1 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user dukesm1 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user dukesm1 overridding Payment Estimate Exception 22 on the current
	Total DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material		10 10 11 11 12 12	2020 Sep 2, 2020 Sep 2, 2020 Sep 16, 2020 Oct 1, 2020 Oct 2, 2020 Oct 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$9,890.00) (\$25,587.50) \$25,587.50 (\$25,587.50) \$25,587.50 (\$25,587.50)	Payment Estimate Item Adjustment (0007) due to user dukesm1 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user dukesm1 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user dukesm1 overridding Payment Estimate Exception 22 on the current
	Total DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material		10 10 11 11 11 12 12 13 13	2020 Sep 2, 2020 Sep 2, 2020 Sep 16, 2020 Sep 16, 2020 Oct 1, 2020 Oct 2, 2020 Oct 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$9,890.00) (\$25,587.50) \$25,587.50 (\$25,587.50) \$25,587.50 (\$25,587.50)	Payment Estimate Item Adjustment (0007) due to user dukesm1 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user dukesm1 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user dukesm1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user dukesm1 overridding Payment Estimate Item Adjustment (0006) due to user dukesm1 overridding Payment Estimate Exception 20 on the current
	Total DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material		10 10 11 11 12 12 13 13 13	2020 Sep 2, 2020 Sep 2, 2020 Sep 16, 2020 Sep 16, 2020 Oct 1, 2020 Oct 2, 2020 Oct 16, 2020 Nov 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$9,890.00) (\$25,587.50) \$25,587.50 (\$25,587.50) \$25,587.50 (\$25,587.50) \$25,587.50	Payment Estimate Item Adjustment (0007) due to user dukesm1 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user dukesm1 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user dukesm1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user dukesm1 overridding Payment Estimate Item Adjustment (0006) due to user dukesm1 overridding Payment Estimate Exception 20 on the current
	Total DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material		10 10 11 11 11 12 12 13 13 14	2020 Sep 2, 2020 Sep 2, 2020 Sep 16, 2020 Sep 16, 2020 Oct 1, 2020 Oct 2, 2020 Nov 2, 2020 Nov 2,	SYSTEM	\$0.00 (\$9,890.00) (\$25,587.50) \$25,587.50 (\$25,587.50) \$25,587.50 (\$25,587.50) \$25,587.50 (\$25,587.50)	Payment Estimate Item Adjustment (0007) due to user dukesm1 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user dukesm1 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user dukesm1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user dukesm1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user dukesm1 overridding Payment Estimate Item Adjustment (0005) due to user dukesm1 overridding Payment Estimate Item Adjustment (0005) due to user dukesm1 overridding Payment Estimate Item Adjustment (0005) due to user dukesm1 overridding Payment Estimate Exception 16 on the current

Revision 4/1/2020 Page 10 of 19



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0170	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material						overridding Payment Estimate Exception 15 on the current Payment Estimate.
	PAVEMENT REPAIR			16	Dec 3, 2020	SYSTEM	(\$25,587.50)	
				16	Dec 3, 2020	SYSTEM	\$25,587.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user dukesm1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				17	Dec 16, 2020	SYSTEM	(\$25,587.50)	
				17	Dec 16, 2020	SYSTEM	\$25,587.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user dukesm1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				18	Jan 4, 2021	SYSTEM	(\$25,587.50)	
				18	Jan 4, 2021	SYSTEM	\$25,587.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user dukesm1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				19	Jan 19, 2021	SYSTEM	(\$25,587.50)	
				19	Jan 19, 2021	SYSTEM	\$25,587.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user dukesm1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
			- Total				(\$9,890.00)	
	Material - Total						(\$9,890.00)	
	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	MaterialCredit		10	Sep 2, 2020	SYSTEM	\$9,890.00	
			- Total				\$9,890.00	
	MaterialCredit - Total						\$9,890.00	
0170 -	- Total						\$0.00	
0180	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	Material		9	Aug 18,	SYSTEM	(\$45.00)	
					2020	->		
	FULL DEPTH PAVEMENT REPAIR			10	2020 Sep 2, 2020	SYSTEM	(\$105.00)	
	FULL DEPTH PAVEMENT REPAIR			10	Sep 2,	SYSTEM		This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user dukesm1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
	FULL DEPTH PAVEMENT REPAIR				Sep 2, 2020 Sep 2,		(\$105.00)	Payment Estimate Item Adjustment (0009) due to user dukesm1 overridding Payment Estimate Exception 21 on the current
	FULL DEPTH PAVEMENT REPAIR			10	Sep 2, 2020 Sep 2, 2020 Sep 16,	SYSTEM	(\$105.00) \$105.00	Payment Estimate Item Adjustment (0009) due to user dukesm1 overridding Payment Estimate Exception 21 on the current
	FULL DEPTH PAVEMENT REPAIR			10	Sep 2, 2020 Sep 2, 2020 Sep 16, 2020 Sep 16,	SYSTEM	(\$105.00) \$105.00 (\$105.00)	Payment Estimate Item Adjustment (0009) due to user dukesm1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user dukesm1 overridding Payment Estimate Exception 25 on the current
	FULL DEPTH PAVEMENT REPAIR			10	Sep 2, 2020 Sep 2, 2020 Sep 16, 2020 Sep 16, 2020	SYSTEM SYSTEM	(\$105.00) \$105.00 (\$105.00) \$105.00	Payment Estimate Item Adjustment (0009) due to user dukesm1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user dukesm1 overridding Payment Estimate Exception 25 on the current
	FULL DEPTH PAVEMENT REPAIR			10 11 11 12	Sep 2, 2020 Sep 2, 2020 Sep 16, 2020 Sep 16, 2020 Oct 1, 2020 Oct 2,	SYSTEM SYSTEM SYSTEM	(\$105.00) \$105.00 (\$105.00) \$105.00	Payment Estimate Item Adjustment (0009) due to user dukesm1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user dukesm1 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user dukesm1 overridding Payment Estimate Exception 24 on the current
	FULL DEPTH PAVEMENT REPAIR			10 11 11 12 12	Sep 2, 2020 Sep 2, 2020 Sep 16, 2020 Oct 1, 2020 Oct 2, 2020	SYSTEM SYSTEM SYSTEM SYSTEM	(\$105.00) \$105.00 (\$105.00) \$105.00 (\$105.00)	Payment Estimate Item Adjustment (0009) due to user dukesm1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user dukesm1 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user dukesm1 overridding Payment Estimate Exception 24 on the current
	FULL DEPTH PAVEMENT REPAIR			10 11 11 12 12	Sep 2, 2020 Sep 2, 2020 Sep 16, 2020 Sep 16, 2020 Oct 1, 2020 Oct 2, 2020 Oct 16, 2020 Oct 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$105.00) \$105.00 (\$105.00) \$105.00 (\$105.00) \$105.00	Payment Estimate Item Adjustment (0009) due to user dukesm1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user dukesm1 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user dukesm1 overridding Payment Estimate Exception 24 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user dukesm1 overridding Payment Estimate Item Adjustment (0007) due to user dukesm1 overridding Payment Estimate Exception 22 on the current
	FULL DEPTH PAVEMENT REPAIR			10 11 11 12 12 13	Sep 2, 2020 Sep 2, 2020 Sep 16, 2020 Sep 16, 2020 Oct 1, 2020 Oct 2, 2020 Oct 16, 2020 Nov 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$105.00) \$105.00 (\$105.00) \$105.00 (\$105.00) \$105.00	Payment Estimate Item Adjustment (0009) due to user dukesm1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user dukesm1 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user dukesm1 overridding Payment Estimate Exception 24 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user dukesm1 overridding Payment Estimate Item Adjustment (0007) due to user dukesm1 overridding Payment Estimate Exception 22 on the current
	FULL DEPTH PAVEMENT REPAIR			10 11 11 12 12 13 13	Sep 2, 2020 Sep 2, 2020 Sep 16, 2020 Sep 16, 2020 Oct 1, 2020 Oct 2, 2020 Oct 16, 2020 Nov 2, 2020 Nov 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$105.00) \$105.00 (\$105.00) \$105.00 (\$105.00) \$105.00 (\$105.00)	Payment Estimate Item Adjustment (0009) due to user dukesm1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user dukesm1 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user dukesm1 overridding Payment Estimate Exception 24 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user dukesm1 overridding Payment Estimate Exception 22 on the current Payment Estimate.

Revision 4/1/2020 Page 11 of 19



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0180	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	Material			2020			Payment Estimate Item Adjustment (0006) due to user dukesm1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
				16	Dec 3, 2020	SYSTEM	(\$105.00)	
				16	Dec 3, 2020	SYSTEM	\$105.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user dukesm1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				17	Dec 16, 2020	SYSTEM	(\$105.00)	
				17	Dec 16, 2020	SYSTEM	\$105.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user dukesm1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				18	Jan 4, 2021	SYSTEM	(\$105.00)	
				18	Jan 4, 2021	SYSTEM	\$105.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user dukesm1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				19	Jan 19, 2021	SYSTEM	(\$105.00)	
				19	Jan 19, 2021	SYSTEM	\$105.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user dukesm1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
			- Total				(\$45.00)	
	Material - Total						(\$45.00)	
	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	MaterialCredit		10	Sep 2, 2020	SYSTEM	\$45.00	
			- Total				\$45.00	
	Material Overlite Tatal							
	MaterialCredit - Total						\$45.00	
0180 -	Total						\$45.00 \$0.00	
0180 -		Material		9	Aug 18, 2020	SYSTEM	\$0.00 (\$485.10)	
	Total TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material		9		SYSTEM SYSTEM	\$0.00	
	Total TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material			2020 Sep 2,		\$0.00 (\$485.10)	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user dukesm1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
	Total TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material		10	2020 Sep 2, 2020 Sep 2,	SYSTEM	\$0.00 (\$485.10) (\$1,104.95)	Payment Estimate Item Adjustment (0011) due to user dukesm1 overridding Payment Estimate Exception 24 on the current
	Total TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material		10	2020 Sep 2, 2020 Sep 2, 2020 Sep 16,	SYSTEM	\$0.00 (\$485.10) (\$1,104.95) \$1,104.95	Payment Estimate Item Adjustment (0011) due to user dukesm1 overridding Payment Estimate Exception 24 on the current
	Total TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material		10 10 11	2020 Sep 2, 2020 Sep 2, 2020 Sep 16, 2020 Sep 16,	SYSTEM SYSTEM SYSTEM	\$0.00 (\$485.10) (\$1,104.95) \$1,104.95	Payment Estimate Item Adjustment (0011) due to user dukesm1 overridding Payment Estimate Exception 24 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user dukesm1 overridding Payment Estimate Exception 27 on the current
	Total TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material		10 10 11 11	2020 Sep 2, 2020 Sep 2, 2020 Sep 16, 2020 Sep 16, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 (\$485.10) (\$1,104.95) \$1,104.95 (\$1,104.95)	Payment Estimate Item Adjustment (0011) due to user dukesm1 overridding Payment Estimate Exception 24 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user dukesm1 overridding Payment Estimate Exception 27 on the current
	Total TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material		10 10 11 11 12	2020 Sep 2, 2020 Sep 2, 2020 Sep 16, 2020 Sep 16, 2020 Oct 1, 2020 Oct 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$485.10) (\$1,104.95) \$1,104.95 (\$1,104.95) (\$1,104.95)	Payment Estimate Item Adjustment (0011) due to user dukesm1 overridding Payment Estimate Exception 24 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user dukesm1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user dukesm1 overridding Payment Estimate Exception 26 on the current
	Total TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material		10 10 11 11 12 12	2020 Sep 2, 2020 Sep 2, 2020 Sep 16, 2020 Sep 16, 2020 Oct 1, 2020 Oct 2, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$485.10) (\$1,104.95) \$1,104.95 (\$1,104.95) \$1,104.95 \$1,104.95	Payment Estimate Item Adjustment (0011) due to user dukesm1 overridding Payment Estimate Exception 24 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user dukesm1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user dukesm1 overridding Payment Estimate Exception 26 on the current
	Total TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material		10 10 11 11 11 12 12 12 13	2020 Sep 2, 2020 Sep 2, 2020 Sep 16, 2020 Sep 16, 2020 Oct 1, 2020 Oct 2, 2020 Oct 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$485.10) (\$1,104.95) \$1,104.95 (\$1,104.95) \$1,104.95 (\$1,104.95)	Payment Estimate Item Adjustment (0011) due to user dukesm1 overridding Payment Estimate Exception 24 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user dukesm1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user dukesm1 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user dukesm1 overridding Payment Estimate Exception 24 on the current
	Total TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material		10 10 11 11 12 12 13	2020 Sep 2, 2020 Sep 2, 2020 Sep 16, 2020 Oct 1, 2020 Oct 2, 2020 Oct 16, 2020 Nov 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$485.10) (\$1,104.95) \$1,104.95 (\$1,104.95) \$1,104.95 (\$1,104.95) \$1,104.95	Payment Estimate Item Adjustment (0011) due to user dukesm1 overridding Payment Estimate Exception 24 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user dukesm1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user dukesm1 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user dukesm1 overridding Payment Estimate Exception 24 on the current

Revision 4/1/2020 Page 12 of 19



Type Adjustment Number Date E	Created Amount	Remarks
	Ву	
0190 TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	YSTEM \$1,104.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user dukesm1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
16 Dec 3, SYS 2020	YSTEM (\$1,104.95)	
16 Dec 3, 2020 SYS	YSTEM \$1,104.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user dukesm1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
17 Dec 16, SYS 2020	YSTEM (\$1,104.95)	
17 Dec 16, SYS	YSTEM \$1,104.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user dukesm1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
18 Jan 4, SYS	YSTEM (\$1,104.95)	
18 Jan 4, SYS 2021	YSTEM \$1,104.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user dukesm1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
19 Jan 19, SYS	YSTEM (\$1,104.95)	
19 Jan 19, SYS 2021	YSTEM \$1,104.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user dukesm1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
- Total	(\$485.10)	
Material - Total	(\$485.10)	
	YSTEM \$485.10	
TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	φ+65.10	
INSTALLATION) FOR FULL DEPTH 2020	\$485.10	
INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS) - Total MaterialCredit - Total		
INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS) - Total MaterialCredit - Total 0190 - Total	\$485.10 \$485.10 \$0.00	
INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS) - Total MaterialCredit - Total 0200 MISC. REMOVAL, FURNISHING AND PLACING HOT POLYMER CONCRETE Overrun Overrun 8 Aug 4, 2020	\$485.10 \$485.10	
INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS) - Total MaterialCredit - Total 0190 - Total 0200 MISC. REMOVAL, FURNISHING AND PLACING HOT POLYMER CONCRETE PATCHING FOR CLASS A PARTIAL	\$485.10 \$485.10 \$0.00	
INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS) - Total MaterialCredit - Total 0190 - Total 0200 MISC. REMOVAL, FURNISHING AND PLACING HOT POLYMER CONCRETE PATCHING FOR CLASS A PARTIAL DEPTH PVMT REPAIR 9 Aug 18, 2020	\$485.10 \$485.10 \$0.00 \$9.00 \$9.00 \$117,819.50	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',3.35000 - 3.35000, 'is applied (if non-zero).
INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS) - Total	\$485.10 \$485.10 \$0.00 YSTEM (\$117,819.50) YSTEM (\$47,476.20)	quantity on all previous payment estimates. Price Adjustments
NSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS) - Total	\$485.10 \$485.10 \$0.00 YSTEM (\$117,819.50) YSTEM (\$47,476.20) YSTEM \$165,295.70	quantity on all previous payment estimates. Price Adjustments
INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS) - Total MaterialCredit - Total 0190 - Total 0200 MISC. REMOVAL, FURNISHING AND PLACING HOT POLYMER CONCRETE PATCHING FOR CLASS A PARTIAL DEPTH PVMT REPAIR 0200 DEPTH PVMT REPAIR 0200 Overrun - Total	\$485.10 \$485.10 \$0.00 YSTEM (\$117,819.50) YSTEM (\$47,476.20) YSTEM \$165,295.70	quantity on all previous payment estimates. Price Adjustments
INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS) 2020	\$485.10 \$485.10 \$0.00 YSTEM (\$117,819.50) YSTEM (\$47,476.20) YSTEM \$165,295.70 \$0.00 \$0.00	quantity on all previous payment estimates. Price Adjustments
INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS) - Total	\$485.10 \$485.10 \$0.00 \$117,819.50) YSTEM (\$47,476.20) YSTEM \$165,295.70 \$0.00 \$0.00	quantity on all previous payment estimates. Price Adjustments
NSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS) - Total	\$485.10 \$485.10 \$0.00 YSTEM (\$117,819.50) YSTEM (\$47,476.20) YSTEM \$165,295.70 \$0.00 \$0.00 \$0.00 YSTEM (\$1,050.00)	quantity on all previous payment estimatés. Price Adjustments of ',3.35000 - 3.35000, 'is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user dukesm1 overridding Payment Estimate Exception 30 on the current
NSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS) - Total	\$485.10 \$485.10 \$0.00 \$117,819.50) YSTEM (\$117,819.50) YSTEM \$165,295.70 \$0.00 \$0.00 \$0.00 YSTEM (\$1,050.00) YSTEM \$1,050.00	quantity on all previous payment estimatés. Price Adjustments of ',3.35000 - 3.35000, 'is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user dukesm1 overridding Payment Estimate Exception 30 on the current
NSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS) - Total	\$485.10 \$485.10 \$0.00 \$117,819.50) YSTEM (\$117,819.50) YSTEM (\$47,476.20) YSTEM \$165,295.70 \$0.00 \$0.00 \$0.00 YSTEM (\$1,050.00) YSTEM \$1,050.00	quantity on all previous payment estimates. Price Adjustments of ',3.35000 - 3.35000, 'is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user dukesm1 overridding Payment Estimate Exception 30 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user dukesm1 overridding Payment Estimate Exception 29 on the current
INSTALLATION) FOR FULL DEPTH 2020 2020	\$485.10 \$485.10 \$0.00 YSTEM (\$117,819.50) YSTEM (\$47,476.20) YSTEM \$165,295.70 \$0.00 \$0.00 \$0.00 YSTEM (\$1,050.00) YSTEM \$1,050.00 YSTEM (\$1,050.00)	quantity on all previous payment estimates. Price Adjustments of ',3.35000 - 3.35000, 'is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user dukesm1 overridding Payment Estimate Exception 30 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user dukesm1 overridding Payment Estimate Exception 29 on the current
INSTÂLLATION) FOR FULL DEPTH 2020 2020	\$485.10 \$485.10 \$0.00 \$117,819.50) YSTEM (\$117,819.50) YSTEM (\$47,476.20) YSTEM \$165,295.70 \$0.00 \$0.00 \$0.00 YSTEM (\$1,050.00) YSTEM (\$1,050.00) YSTEM \$1,050.00 YSTEM (\$1,050.00)	quantity on all previous payment estimates. Price Adjustments of ',3.35000 - 3.35000, 'is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user dukesm1 overridding Payment Estimate Exception 30 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user dukesm1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user dukesm1 overridding Payment Estimate Item Adjustment (0009) due to user dukesm1 overridding Payment Estimate Exception 27 on the current
NSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS) - Total	\$485.10 \$485.10 \$485.10 \$0.00 YSTEM (\$117,819.50) YSTEM (\$47,476.20) YSTEM \$165,295.70 \$0.00 \$0.00 \$0.00 YSTEM (\$1,050.00) YSTEM (\$1,050.00) YSTEM \$1,050.00 YSTEM (\$1,050.00) YSTEM \$1,050.00 YSTEM \$1,050.00	quantity on all previous payment estimates. Price Adjustments of ',3.35000 - 3.35000, 'is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user dukesm1 overridding Payment Estimate Exception 30 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user dukesm1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user dukesm1 overridding Payment Estimate Item Adjustment (0009) due to user dukesm1 overridding Payment Estimate Exception 27 on the current

Revision 4/1/2020 Page 13 of 19



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0330	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	Material		3	May 18, 2020	SYSTEM	(\$2,591.00)	
			- Total				(\$2,591.00)	
	Material - Total						(\$2,591.00)	
	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	MaterialCredit		4	Jun 2, 2020	SYSTEM	\$2,591.00	
			- Total				\$2,591.00	
	MaterialCredit - Total						\$2,591.00	
0330 -	Total						\$0.00	
0340	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	Material		3	May 18, 2020	SYSTEM	(\$4,163.00)	
			- Total				(\$4,163.00)	
	Material - Total						(\$4,163.00)	
	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	MaterialCredit		4	Jun 2, 2020	SYSTEM	\$4,163.00	
			- Total				\$4,163.00	
	MaterialCredit - Total						\$4,163.00	
0340 -	Total						\$0.00	
0350	TEMPORARY NON-REMOVABLE MARKING TAPE LEFT/RIGHT ARROW	Material		3	May 18, 2020	SYSTEM	(\$300.00)	
			- Total				(\$300.00)	
	Material - Total						(\$300.00)	
	TEMPORARY NON-REMOVABLE MARKING TAPE LEFT/RIGHT ARROW	MaterialCredit		4	Jun 2, 2020	SYSTEM	\$300.00	
			- Total				\$300.00	
	MaterialCredit - Total						\$300.00	
0350 -	Total						\$0.00	
0360	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		11	Sep 16, 2020	SYSTEM	(\$1,555.00)	
	BENDO			11	Sep 16, 2020	SYSTEM	\$1,555.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user dukesm1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$1,555.00)	
				12	Oct 2, 2020	SYSTEM	\$1,555.00	This adjustment offsets the original system-generated Overrun Payment Estimate Ilem Adjustment (0013) due to user dukesm1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Other Item Adjustment	REFL	15	Nov 16, 2020	dukesm1	\$77.75	This item adjustment is to pay a bonus for the Retroreflectivity results.
	BEADS			18	Jan 4, 2021	dukesm1	(\$77.76)	
				20	Feb 2, 2021	dukesm1	\$77.76	This item adjustment is to pay the retroreflectivity bonus
			REFL - Tota	ı			\$77.75	
	Other Item Adjustment - Total						\$77.75	
0360 -							\$77.75	
0370	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		11	Sep 16, 2020	SYSTEM	(\$2,488.00)	
	·			11	Sep 16, 2020	SYSTEM	\$2,488.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user dukesm1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$2,488.00)	
				12	Oct 2, 2020	SYSTEM	\$2,488.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user dukesm1 overridding Payment Estimate Exception 32 on the current Payment Estimate.

Revision 4/1/2020 Page 14 of 19



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0370		Material	- Total				\$0.00	
	Material - Total						\$0.00	
	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING	Other Item Adjustment	REFL	15	Nov 16, 2020	dukesm1	\$124.40	This item adjustment is to pay a bonus for the Retroreflectivity results.
	PAINT, TYPE P BEADS			18	Jan 4, 2021	dukesm1	(\$124.41)	
				20	Feb 2, 2021	dukesm1	\$124.41	This item adjustment is to pay the retroreflectivity bonus
			REFL - Tota	ıl			\$124.40	
	Other Item Adjustment - Total						\$124.40	
0370 -							\$124.40	
0410	SEEDING - COOL SEASON MIXTURES	Material		11	Sep 16, 2020	SYSTEM	(\$200.00)	
				12	Oct 1, 2020	SYSTEM	(\$200.00)	
				13	Oct 16, 2020	SYSTEM	(\$200.00)	
				14	Nov 2, 2020	SYSTEM	(\$200.00)	
				15	Nov 16, 2020	SYSTEM	(\$200.00)	
			- Total				(\$1,000.00)	
	Material - Total						(\$1,000.00)	
	SEEDING - COOL SEASON MIXTURES MaterialCre	MaterialCredit		12	Oct 1, 2020	SYSTEM	\$200.00	
				13	Oct 16, 2020	SYSTEM	\$200.00	
				14	Nov 2, 2020	SYSTEM	\$200.00	
				15	Nov 16, 2020	SYSTEM	\$200.00	
			- Total	16	Dec 3, 2020	SYSTEM	\$200.00	
	Material October 7 - 4-1		- I otal				\$1,000.00	
0410 -	MaterialCredit - Total						\$1,000.00	
0410 -	SILT FENCE	Material		11	Sep 16, 2020	SYSTEM	\$0.00 (\$214.70)	
				12	Oct 1, 2020	SYSTEM	(\$214.70)	
				13	Oct 16, 2020	SYSTEM	(\$214.70)	
				14	Nov 2, 2020	SYSTEM	(\$214.70)	
				15	Nov 16, 2020	SYSTEM	(\$214.70)	
				17	Dec 16, 2020	SYSTEM	(\$440.70)	
				17	Dec 16, 2020	SYSTEM	\$440.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user dukesm1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
		- Total						
	Material - Total						(\$1,073.50)	
	SILT FENCE	MaterialCredit		12	Oct 1, 2020	SYSTEM	\$214.70	
			13	Oct 16, 2020	SYSTEM	\$214.70		
				14	Nov 2, 2020	SYSTEM	\$214.70	
				15	Nov 16, 2020	SYSTEM	\$214.70	

Revision 4/1/2020 Page 15 of 19



Mag GUANGRAUL R P P P P P P P P P	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
Part		·			Number	Date	Ву		
Maint Main	0440	SILT FENCE	MaterialCredit		16		SYSTEM	\$214.70	
MISS GUARDINAL Part				- Total				\$1,073.50	
Mode		MaterialCredit - Total						\$1,073.50	
Section Sect	0440 -	Total						\$0.00	
Part	0450	MGS GUARDRAIL			2		SYSTEM	\$2,270.58	
Construction Stockspile - Total					8		SYSTEM	(\$2,270.58)	
May A STEM STAND				- Total				\$0.00	
Mag Sura Ranku		Construction Stockpile - Total						\$0.00	
No. SPACING Page	0450 -	Total						\$0.00	
Part	0460				2		SYSTEM	\$33,204.50	
Page					5		SYSTEM	(\$11,602.78)	
					7		SYSTEM	(\$20,048.00)	
Note					8		SYSTEM	(\$1,553.72)	
MGS BRIDGE APPROACH TRANSITION Section (EXTENDED CURB) Section (- Total				\$0.00	
MSS BRIDGE APPROACH TRANSITION Section (EXTENDED CURR) Solicityle Page		Construction Stockpile - Total						\$0.00	
SECTION (EXTENDED CURB) Slockpile	0460 -	Total						\$0.00	
Page	0470				2		SYSTEM	\$6,200.00	
Construction Stockpile - Total					5		SYSTEM	(\$3,100.00)	
Construction Stockpile - Total South Sou					7		SYSTEM	(\$3,100.00)	
Note				- Total				\$0.00	
MGS END ANCHOR MGS		Construction Stockpile - Total						\$0.00	
Stockpile Page	0470 -	Total						\$0.00	
Construction Stockpile - Total S0.00	0480	MGS END ANCHOR			2		SYSTEM	\$535.00	
Construction Stockpile - Total TYPE A CRASHWORTHY END TERMINAL (MASH) Construction Stockpile Total Total Construction Stockpile Total Construction Stockpile - Total MISC. Remove and Replace Barrier Curb MISC. Remove and Replace Barrier Curb Doverrun - Total Construction Stockpile - Total Overrun - Total Construction Stockpile - Total So.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user dukesm1 overridding Payment Estimate Exception 5 on the current Payment Estimate Exception 5 on the current Payment Estimate Stockpile (if non-zero). Doverrun - Total Overrun - Total Overrun - Total So.00 Overrun - Total Overrun - Total Overrun - Total					7		SYSTEM	(\$535.00)	
Type A Crashworthy end remained the Adjustment generated Stockpile 2				- Total				\$0.00	
TYPE A CRASHWORTHY END TERMINAL (MASH) To Jun 15, 2020 Type and Estimate Item Adjustment generated Stockpile Transaction Transaction Transaction Total Total Total Type A CRASHWORTHY END TERMINAL (MASH) Transaction Transaction Transaction Transaction Transaction Total Type A CRASHWORTHY END TERMINAL (MASH) Transaction Transaction Transaction Transaction Transaction Total Type A CRASHWORTHY END TERMINAL (MASH) Transaction Transaction Payment Estimate Item Adjustment generated Stockpile Transaction Transaction		Construction Stockpile - Total						\$0.00	
Construction Stockpile	0480 -	Total						\$0.00	
2020 Transaction	0490				2	May 4, 2020	SYSTEM	\$7,550.00	
Construction Stockpile - Total S0.00 Construction Stockpile - Total S0.00 MISC. Remove and Replace Barrier Curb MISC. Remove and Replace Barrier Curb Description Stockpile - Total S0.00 Transaction S0.00 MISC. Remove and Replace Barrier Curb Description Stockpile - Total S0.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user dukesm1 overridding Payment Estimate Exception 5 on the current Payment Estimate Exception 5 on the current Payment Estimate Signal System Syst					5		SYSTEM	(\$1,510.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
Construction Stockpile - Total Sto.00 MISC. Remove and Replace Barrier Curb MISC. Remove and					8	Aug 4, 2020	SYSTEM	(\$6,040.00)	
MISC. Remove and Replace Barrier Curb Overrun Overrun 4				- Total				\$0.00	
MISC. Remove and Replace Barrier Curb Overrun A		Construction Stockpile - Total						\$0.00	
2020 4 Jun 2, 2020 SYSTEM \$350.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user dukesm1 overridding Payment Estimate Exception 5 on the current Payment Estimate. 5 Jun 15, 2020 SYSTEM (\$350.00) Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). 12 Oct 1, 2020 SYSTEM \$350.00 Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',350.00000 - 350.00000, 'is applied (if non-zero).	0490 -	Total						\$0.00	
2020 Payment Estimate Item Adjustment (0001) due to user dukesm1 overridding Payment Estimate Exception 5 on the current Payment Estimate Exception 5 on the current Payment Estimate. 5 Jun 15, 2020 Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). 12 Oct 1, 2020 SYSTEM \$350.00 Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',350.00000 - 350.00000, 'is applied (if non-zero).	0520	MISC. Remove and Replace Barrier Curb	Overrun	Overrun	4		SYSTEM	(\$350.00)	
2020 payment estimates of '0.00000' is applied (if non-zero). 12 Oct 1, 2020 Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',350.00000 - 350.00000, 'is applied (if non-zero). Overrun - Total \$0.00					4		SYSTEM	\$350.00	Payment Estimate Item Adjustment (0001) due to user dukesm1 overridding Payment Estimate Exception 5 on the current
2020 quantity on all previous payment estimatés. Price Adjustments of ',350.00000 - 350.00000, 'is applied (if non-zero). Overrun - Total \$0.00							SYSTEM	(\$350.00)	payment estimates of '0.00000' is applied (if non-zero).
							SYSTEM	\$350.00	quantity on all previous payment estimates. Price Adjustments
Overrun - Total \$0.00				Overrun - T	otal			\$0.00	
		Overrun - Total						\$0.00	

Revision 4/1/2020 Page 16 of 19



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0520 -	Total						\$0.00	
0540	BRIDGE APPROACH SLAB (MAJOR ROAD)	Material		5	Jun 15, 2020	SYSTEM	(\$45,375.00)	
				6	Jul 1, 2020	SYSTEM	(\$45,375.00)	
				7	Jul 16, 2020	SYSTEM	(\$90,750.00)	
				8	Aug 4, 2020	SYSTEM	(\$90,750.00)	
				9	Aug 18, 2020	SYSTEM	(\$90,750.00)	
				10	Sep 2, 2020	SYSTEM	(\$90,750.00)	
				10	Sep 2, 2020	SYSTEM	\$90,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user dukesm1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$90,750.00)	
				11	Sep 16, 2020	SYSTEM	\$90,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user dukesm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$90,750.00)	
				12	Oct 2, 2020	SYSTEM	\$90,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user dukesm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				13	Oct 16, 2020	SYSTEM	(\$90,750.00)	
				13	Oct 16, 2020	SYSTEM	\$90,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user dukesm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				14	Nov 2, 2020	SYSTEM	(\$90,750.00)	
				14	Nov 2, 2020	SYSTEM	\$90,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user dukesm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				15	Nov 16, 2020	SYSTEM	(\$90,750.00)	
				15	Nov 16, 2020	SYSTEM	\$90,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user dukesm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				16	Dec 3, 2020	SYSTEM	(\$90,750.00)	
				16	Dec 3, 2020	SYSTEM	\$90,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user dukesm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				17	Dec 16, 2020	SYSTEM	(\$90,750.00)	
				17	Dec 16, 2020	SYSTEM	\$90,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user dukesm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				18	Jan 4, 2021	SYSTEM	(\$90,750.00)	
				18	Jan 4, 2021	SYSTEM	\$90,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user dukesm1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				19	Jan 19, 2021	SYSTEM	(\$90,750.00)	
				19	Jan 19, 2021	SYSTEM	\$90,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user dukesm1 overridding Payment Estimate Exception 2 on the current

Revision 4/1/2020 Page 17 of 19



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0540	BRIDGE APPROACH SLAB (MAJOR ROAD)	Material	1350					Payment Estimate.
			- Total				(\$363,000.00)	
	Material - Total						(\$363,000.00)	
	BRIDGE APPROACH SLAB (MAJOR ROAD)	MaterialCredit		6	Jul 1, 2020	SYSTEM	\$45,375.00	
				7	Jul 16, 2020	SYSTEM	\$45,375.00	
				8	Aug 4, 2020	SYSTEM	\$90,750.00	
				9	Aug 18, 2020	SYSTEM	\$90,750.00	
			- Total	10	Sep 2, 2020	SYSTEM	\$90,750.00	
	MaterialCredit - Total		- Iotai				\$363,000.00	
0540	Total						\$363,000.00 \$0.00	
0550	LATEX MODIFIED CONCRETE WEARING SURFACE	Material		4	Jun 2, 2020	SYSTEM		
				5	Jun 15, 2020	SYSTEM	(\$127,627.50)	
				6	Jul 1, 2020	SYSTEM	(\$255,255.00)	
				7	Jul 16, 2020	SYSTEM	(\$102,101.83)	
				8	Aug 4, 2020	SYSTEM	(\$102,101.83)	
				8	Aug 4, 2020	SYSTEM	\$102,101.83	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user dukesm1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$102,101.83)	
				9	Aug 18, 2020	SYSTEM	\$102,101.83	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user brookw1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
				10	Sep 2, 2020	SYSTEM	(\$102,101.83)	
				10	Sep 2, 2020	SYSTEM	\$102,101.83	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user dukesm1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$102,101.83)	
				11	Sep 16, 2020	SYSTEM	\$102,101.83	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user dukesm1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$102,101.83)	
				12	Oct 2, 2020	SYSTEM	\$102,101.83	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user dukesm1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				13	Oct 16, 2020	SYSTEM	(\$102,101.83)	
				13	Oct 16, 2020	SYSTEM	\$102,101.83	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user dukesm1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
			- Total				(\$612,611.83)	
	Material - Total						(\$612,611.83)	
	LATEX MODIFIED CONCRETE WEARING SURFACE	MaterialCredit		5	Jun 15, 2020	SYSTEM	\$127,627.50	
				6	Jul 1,	SYSTEM	\$127,627.50	

Revision 4/1/2020 Page 18 of 19



1.5	D	A -1:	041	F-4	0	0	A	Demonto
Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0550	LATEX MODIFIED CONCRETE WEARING	MaterialCredit			2020			
	SURFACE			7	Jul 16, 2020	SYSTEM	\$255,255.00	
				8	Aug 4, 2020	SYSTEM	\$102,101.83	
			- Total				\$612,611.83	
	MaterialCredit - Total						\$612,611.83	
0550 -	Total						\$0.00	
0580	SUBSTRUCTURE REPAIR (UNFORMED)	Material		11	Sep 16, 2020	SYSTEM	(\$67.50)	
			- Total				(\$67.50)	
	Material - Total						(\$67.50)	
	SUBSTRUCTURE REPAIR (UNFORMED)	MaterialCredit		12	Oct 1, 2020	SYSTEM	\$67.50	
			- Total				\$67.50	
	MaterialCredit - Total						\$67.50	
0580 -	Total						\$0.00	
0610	CLEANING AND EPOXY COATING	Material		11	Sep 16, 2020	SYSTEM	(\$31,740.00)	
				12	Oct 1, 2020	SYSTEM	(\$31,740.00)	
				13	Oct 16, 2020	SYSTEM	(\$31,740.00)	
				14	Nov 2, 2020	SYSTEM	(\$31,740.00)	
				15	Nov 16, 2020	SYSTEM	(\$31,740.00)	
				16	Dec 3, 2020	SYSTEM	(\$31,740.00)	
				16	Dec 3, 2020	SYSTEM	\$31,740.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user dukesm1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
			- Total				(\$158,700.00)	
	Material - Total						(\$158,700.00)	
	CLEANING AND EPOXY COATING	MaterialCredit		12	Oct 1, 2020	SYSTEM	\$31,740.00	
				13	Oct 16, 2020	SYSTEM	\$31,740.00	
				14	Nov 2, 2020	SYSTEM	\$31,740.00	
				15	Nov 16, 2020	SYSTEM	\$31,740.00	
				16	Dec 3, 2020	SYSTEM	\$31,740.00	
			- Total				\$158,700.00	
	MaterialCredit - Total						\$158,700.00	
0610 -							\$0.00	
0620	MONOLITHIC DECK REPAIR	Overrun	Overrun		Aug 4, 2020	SYSTEM	(\$23,100.00)	
				11	Sep 16, 2020	SYSTEM	\$23,100.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',700.00000 - 700.00000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0620 -	Total						\$0.00	
Overa	II - Total						\$202.15	

Revision 4/1/2020 Page 19 of 19