

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: December 15, 2020

Progress Estimate Number	Contract ID	200117-G05	Pay Period Start	December 2, 2020	Original Contract Amou	nt\$4,676,970.64
14	Prime Contractor	Capital Paving & Construction, LLC	Pay Period End	December 15, 2020	Net Change Order Amount Current Contract Amoun	\$97,751.15 nt \$4,774,721.79

Approval Date		By User
December 16, 2020	Generated and Approved (and should be considered Draft) at the Project Office Level by	MARKHS
December 17, 2020	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	roeged1
December 18, 2020	Reviewed and Approved at the Central Office Controllers Office Level by	greggd1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
December 1, 2021	December 1, 2021		47.64%

Contract Informational Dates Milestones

Date Description	Original Completion Date	Current Completion Date
Acceptance Date		
Awarded Date	February 5, 2020	February 5, 2020
Letting Date	January 17, 2020	January 17, 2020
Notice to Proceed Date	March 9, 2020	March 9, 2020
Open to Traffic Date		
Work Began Date		

Date Description	Original Completion Date	Current Completion Date	Days Remaining on Milestone	Diary Charge Days
Milestone - Completion Date	October 19, 2020	October 19, 2020	-59	

Contract Total Pa	y For Estimate No. 14			
		This Estimate	Previous	To Date
200117-G05				
	Total Posted Items Pay	\$35,822.70	\$2,239,042.27	\$2,274,864.97
	Gross Item Adjustments	\$0.00	(\$1,000.00)	(\$1,000.00)
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
			\$2,238,042.27	\$2,273,864.97
Contract Total Pay	yable This Estimate:	\$35,822.70		

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount		
J7S3203	0600	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	SQFT	\$134.700	220	\$29,634.00		
	0610	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	TONS	\$136.000	3.8	\$516.80		
	0710	6161047	TYPE III OBJECT MARKER	EA	\$234.300	4	\$937.20		
	0740	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$0.580	3,844	\$2,229.52		
	0750	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$0.580	775	\$449.50		
	0840	9031270A	2 IN. PSST POST - 12 GA.	LF	\$23.840	42	\$1,001.28		
	0850	9039902	MISC. RELOCATE AND REMOUNT EXISTING SIGN ON NEW PSST	EA	\$527.200	2	\$1,054.40		
Project J7S	oject J7S3203 - Total								
Overall - To	Overall - Total								

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Revision 4/1/2020 Page 1 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: December 15, 2020

Progress Estimate Number
14 Contract ID 200117-G05 Pay Period Start December 2, 2020 Original Contract Amount \$4,676,970.64
Prime Contractor LLC Pay Period End December 15, 2020 Original Contract Amount \$4,676,970.64
Pay Period End December 15, 2020 Original Contract Amount \$4,676,970.64
Pay Period End December 15, 2020 Original Contract Amount \$4,676,970.64
Current Contract Amount \$4,774,721.79

CONCRETE WEARING SURFACE Baseline Concrete Wearing Surface LATEX MODIFIED CONCRETE WEARING SURFACE CONCRETE WEARING SURFACE Baseline Concrete Wearing Surface CONCRETE Wearing Surface CONCRETE Wearing Surface This adjustment (0002) due to user markhs overridding Payment Estimate Exception 2 on the current Payment Estimate Item Adjustment (0003) due to user markhs overridding Payment Estimate Item Adjustment (0003) due to user markhs overridding Payment Estimate Item Adjustment (0003) due to user markhs overridding Payment Estimate Exception 3 on the current Payment Estimate. CURB BLOCKOUT Material CURB BLOCKOUT Material This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user markhs overridding Payment Estimate Exception 4 on the current Payment Estimate Item Adjustment (0004) due to user markhs		Adjustmer amount
generated Overrun Payment Estimate Item Adjustment (001) due to user markhs overridding Payment Estimate Exception 1 on the current Payment Estimate. 0890 LATEX MODIFIED CONCRETE WEARING SURFACE 0990 CLASS B-2 CONCRETE Material 0900 CLASS B-2 CONCRETE Material 0900 CLASS B-2 CONCRETE Material This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0003) due to user markhs overridding Payment Estimate Exception 3 on the current Payment Estimate Exception 3 on the current Payment Estimate. 0910 CURB BLOCKOUT Material This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0003) due to user markhs overridding Payment Estimate Exception 3 on the current Payment Estimate Exception 4 on the current Payment Estimate Item Adjustment (0004) due to user markhs overridding Payment Estimate Exception 4 on the current Payment Estimate Exception 5 on the current Payment Estimate Exception 5 on the current Payment Estimate Exception 6 on the current Payment Estimate Exception 6 on the current Payment Estimate Item Adjustment (0004) due to user markhs overridding Payment Estimate Item Adjustment (0004) due to user markhs overridding Payment Estimate Item Adjustment (0005) due to user markhs	Material -34 \$440.60 (\$	(\$14,980.4
CONCRETE WEARING SURFACE 890 LATEX MODIFIED CONCRETE WEARING SURFACE 800 CONCRETE WEARING SURFACE 900 CLASS B-2 CONCRETE 900 MATERIAL	generated Overrun Payment Estimate Item Adjustment (0001) due to user markhs overridding Payment Estimate Exception 1 on	\$14,980.4
CONCRETE WEARING SURFACE Generated Overrun Payment Estimate Item Adjustment (0002) due to user markhs overridding Payment Estimate Exception 2 on the current Payment Estimate. O900 CLASS B-2 CONCRETE Material O900 CLASS B-2 CONCRETE Material This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user markhs overridding Payment Estimate Exception 3 on the current Payment Estimate. O910 CURB BLOCKOUT Material O910 CURB BLOCKOUT Material This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user markhs overridding Payment Estimate Exception 4 on the current Payment Estimate. O950 MONOLITHIC DECK REPAIR Material This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment Estimate Item Adjustment Estimate Exception 4 on the current Payment Estimate Item Adjustment Estimate Item Estimate Item Adjustment Option Deck Repair Material This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment Estimate Item Adjustment (0005) due to user markhs	Material -4,935 \$85.85 (\$43	(\$423,669.7
O900 CLASS B-2 CONCRETE Material This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0003) due to user markhs overridding Payment Estimate Exception 3 on the current Payment Estimate. O910 CURB BLOCKOUT Material -3,467 \$51.31 (O910 CURB BLOCKOUT Material This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0004) due to user markhs overridding Payment Estimate Exception 4 on the current Payment Estimate. O950 MONOLITHIC DECK REPAIR Material This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment Offsets the original system- generated Overrun Payment Estimate Item Adjustment (0005) due to user markhs	generated Overrun Payment Estimate Item Adjustment (0002) due to user markhs overridding Payment Estimate Exception 2 on	\$423,669.7
generated Overrun Payment Estimate Item Adjustment (0003) due to user markhs overridding Payment Estimate Exception 3 on the current Payment Estimate. O910 CURB BLOCKOUT Material O910 CURB BLOCKOUT Material This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0004) due to user markhs overridding Payment Estimate Exception 4 on the current Payment Estimate. O950 MONOLITHIC DECK REPAIR Material This adjustment offsets the original system- generated Overrun Payment Estimate. 76 \$700.00 This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0005) due to user markhs	Material -11.6 \$5,438.00 (\$6	(\$63,080.8
0910 CURB BLOCKOUT Material This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0004) due to user markhs overridding Payment Estimate Exception 4 on the current Payment Estimate. 0950 MONOLITHIC DECK REPAIR Material This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0005) due to user markhs	generated Overrun Payment Estimate Item Adjustment (0003) due to user markhs overridding Payment Estimate Exception 3 on	\$63,080.8
generated Overrun Payment Estimate Item Adjustment (0004) due to user markhs overridding Payment Estimate Exception 4 on the current Payment Estimate. O950 MONOLITHIC DECK REPAIR Material This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0005) due to user markhs	Material -3,467 \$51.31 (\$1	(\$177,891.7
0950 MONOLITHIC DECK REPAIR Material This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0005) due to user markhs	generated Overrun Payment Estimate Item Adjustment (0004) due to user markhs overridding Payment Estimate Exception 4 on	\$177,891.7
generated Overrun Payment Estimate Item Adjustment (0005) due to user markhs	Material -76 \$700.00 (\$	(\$53,200.0
overridding Payment Estimate Exception 8 on the current Payment Estimate.	generated Overrun Payment Estimate Item Adjustment (0005) due to user markhs overridding Payment Estimate Exception 8 on	\$53,200.0

Revision 4/1/2020 Page 2 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Information				
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work			
J7S3202	FAS S602(9)	Bridge rehabilitation	С	ST CLAIR	over Truman Lake, east of Lowry City, 5.5 miles east of Route 13					
J7S3203	FAS S601(93)	Bridge rehabilitation	ZZ	ST CLAIR	over Truman Lake					
Totals by .	Job Numbe	ers								
J7S3202	Posted Item Pay Gross Item Adjustments Gross Item Pay			Item Pay	This Estimate \$0.00 \$0.00 \$0.00	Previous \$0.00 \$0.00 \$0.00	To Date \$0.00 \$0.00 \$0.00			
	Incentive Disincentive Liquidated Damages Other Contract Adjustments				\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00			
J7S3203		d Item Pay Item Adjustm		Item Pay	This Estimate \$35,822.70 \$0.00 \$35,822.70	Previous \$2,239,042.27 (\$1,000.00) \$2,238,042.27	To Date \$2,274,864.97 (\$1,000.00) \$2,273,864.97			
	Incentive Disincentive Liquidated Damages Other Contract Adjustments				\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00			

Revision 4/1/2020 Page 3 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J7S3203, Item 2169903, Project Item Line Number 0880, Material Set 2169903, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	All remaining exceptions on this project involve concrete testing. Many 28 day cylinders made involve more than one line item but were only reported for one line item. These reports will be adjusted and eliminate the exceptions prior to the next pay estimate.	MARKHS	Overridden
Estimate Exception Type: Insufficient Materials: Project J7S3203, Item 5052000, Project Item Line Number 0890, Material Set 505200096, Material 0505CCLATX - Bridge Deck Concrete, Latex, Acceptance Action Generic 0505CCLATX is insufficient.	All remaining exceptions on this project involve concrete testing. Many 28 day cylinders made involve more than one line item but were only reported for one line item. These reports will be adjusted and eliminate the exceptions prior to the next pay estimate.	MARKHS	Overridden
Estimate Exception Type: Insufficient Materials: Project J7S3203, Item 7034214, Project Item Line Number 0900, Material Set 703421496, Material 0501CCB2MDA - Concrete, Modified B-2 w/Air, Acceptance Action Generic 0501CCB2MDA is insufficient.	All remaining exceptions on this project involve concrete testing. Many 28 day cylinders made involve more than one line item but were only reported for one line item. These reports will be adjusted and eliminate the exceptions prior to the next pay estimate.	MARKHS	Overridden
Estimate Exception Type: Insufficient Materials: Project J7S3203, Item 7034600, Project Item Line Number 0910, Material Set 703460096, Material 1039ERRAS - Epoxy Bonding Agent-Resin Anchor Systems, Acceptance Action Generic 1039ERRAS is insufficient.	All remaining exceptions on this project involve concrete testing. Many 28 day cylinders made involve more than one line item but were only reported for one line item. These reports will be adjusted and eliminate the exceptions prior to the next pay estimate.	MARKHS	Overridden
Estimate Exception Type: Insufficient Materials: Project J7S3203, Item 7034600, Project Item Line Number 0910, Material Set 703460096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	All remaining exceptions on this project involve concrete testing. Many 28 day cylinders made involve more than one line item but were only reported for one line item. These reports will be adjusted and eliminate the exceptions prior to the next pay estimate.	MARKHS	Overridden
Estimate Exception Type: Insufficient Materials: Project J7S3203, Item 7034600, Project Item Line Number 0910, Material Set 703460096, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	All remaining exceptions on this project involve concrete testing. Many 28 day cylinders made involve more than one line item but were only reported for one line item. These reports will be adjusted and eliminate the exceptions prior to the next pay estimate.	MARKHS	Overridden
Estimate Exception Type: Insufficient Materials: Project J7S3203, Item 7034600, Project Item Line Number 0910, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	All remaining exceptions on this project involve concrete testing. Many 28 day cylinders made involve more than one line item but were only reported for one line item. These reports will be adjusted and eliminate the exceptions prior to the next pay estimate.	MARKHS	Overridden
Estimate Exception Type: Insufficient Materials: Project J7S3203, Item 7040117, Project Item Line Number 0950, Material Set 7040117, Material 0505CCLATX - Bridge Deck Concrete, Latex, Acceptance Action Generic 0505CCLATX is insufficient.	All remaining exceptions on this project involve concrete testing. Many 28 day cylinders made involve more than one line item but were only reported for one line item. These reports will be adjusted and eliminate the exceptions prior to the next pay estimate.	MARKHS	Overridden

Revision 4/1/2020 Page 4 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Contract .CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POST To Date (See rep generated date
117-G05	J7S3202	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.00	\$5,242.00	\$0
		0001	0020	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	200.00	0.00	200.00	SQFT	0.00	\$134.70	\$0
		0001	0030	2153000	SHAPING SLOPES, CLASS III	23.00	0.00	23.00	100F	0.00	\$530.60	\$0
		0001	0040	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	15.00	0.00	15.00	TONS	0.00	\$136.00	\$0
		0001	0050	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	22.00	0.00	22.00	TONS	0.00	\$311.50	\$0
		0001	0060	4071005	TACK COAT	89.00	0.00	89.00	GAL	0.00	\$3.09	\$0
		0001	0070	6113020	FURNISHING TYPE 2 ROCK BLANKET	477.00	0.00	477.00	CUYD	0.00	\$47.71	\$0
		0001	0080	6113040	PLACING TYPE 2 ROCK BLANKET	477.00	0.00	477.00	CUYD	0.00	\$19.84	\$
		0001	0090	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$585.70	\$
		0001	0100	6161005	CONSTRUCTION SIGNS	626.00	0.00	626.00	SQFT	0.00	\$9.66	
		0001	0110	6161008	ADVANCED WARNING RAIL SYSTEM	4.00	0.00	4.00	EA	0.00	\$93.72	
		0001	0120	6161009	FLAG ASSEMBLY	2.00	0.00	2.00	EA	0.00	\$23.43	4
		0001	0130	6161012	BUOYS (BOATS KEEP OUT)	30.00	0.00	30.00	EA	0.00	\$246.00	5
		0001	0140	6161013	BUOYS (NO WAKE)	34.00	0.00	34.00	EA	0.00	\$246.00	;
		0001	0150	6161014	SPECIAL SIGN ASSEMBLY (BOATS KEEP OUT)	4.00	0.00	4.00	EA	0.00	\$1,289.00	:
		0001	0160	6161031	TYPE III MOVEABLE BARRICADE WITH LIGHTS	10.00	0.00	10.00	EA	0.00	\$210.90	
		0001	0170	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	0.00	\$5,272.00	
		0001	0180	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.00	\$104,383.00	
		0001	0190	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	4,012.00	0.00	4,012.00	LF	0.00	\$0.58	
		0001	0200	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	502.00	0.00	502.00	LF	0.00	\$0.58	
		0001	0210	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	716.00	0.00	716.00	SQYD	0.00	\$4.18	
		0001	0220	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$1,852.00	
		0001	0230	8051000A	SEEDING - COOL SEASON MIXTURES	0.90	0.00	0.90	ACRE	0.00	\$4,452.00	
		0001	0240	8061005	ROCK DITCH CHECK	20.00	0.00	20.00	LF	0.00	\$46.86	
		0001	0250	8061016	SEDIMENT REMOVAL	3.00	0.00	3.00	CUYD	0.00	\$247.10	
		0001	0260	8061019	SILT FENCE	107.00	0.00	107.00	LF	0.00	\$5.27	
		0001	0270	8061050	TYPE C BERM	225.00	0.00	225.00	LF	0.00	\$37.72	
		0010	0280	6061060	MGS GUARDRAIL	1,825.00	0.00	1,825.00	LF	0.00	\$22.08	
		0010	0290	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	138.00	0.00	138.00	LF	0.00	\$29.23	
		0010	0300	6061069	MGS BRIDGE APPROACH TRANSITION SECTION	4.00	0.00	4.00	EA	0.00	\$2,899.00	
		0010	0310	6063014	(REGULAR/NO CURB) TYPE A CRASHWORTHY END TERMINAL (MASH)	4.00	0.00	4.00	EA	0.00	\$2,870.00	
		0040	0320	9031010	CONCRETE FOOTINGS, EMBEDDED	0.50	0.00	0.50	CUYD	0.00	\$2,929.00	
		0040	0330	9031270A	2 IN. PSST POST - 12 GA.	96.00	0.00	96.00	LF	0.00	\$14.64	
		0040	0340	9031273	POST ANCHOR FOR 2 IN. PSST - 7 GA.	18.00	0.00	18.00	LF	0.00	\$55.18	
		0040	0350	9035004A	SH-FLAT SHEET	23.00	0.00	23.00	SQFT	0.00	\$48.90	
		0070	0360	2161000	SCARIFICATION OF BRIDGE DECK	5,176.00	0.00	5,176.00	SQYD	0.00	\$5.85	
		0070	0370	2161503	REMOVAL OF EXISTING DECK REPAIR	2,500.00	0.00	2,500.00	SQFT	0.00	\$18.00	
		0070	0380	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT	104.00	0.00	104.00	LF	0.00	\$329.70	
		0070	0390	2169903	CONCRETE MISC.Remove and Replace Curb and Parapet	34.00	0.00	34.00	LF	0.00	\$440.60	
		0070	0400	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	5,185.00	0.00	5,185.00	SQYD	0.00	\$83.51	
		0070	0400	7034214	CLASS B-2 CONCRETE	11.60	0.00	11.60	CUYD	0.00	\$5,438.00	
		0070	0410	7034214	CURB BLOCKOUT	3,637.00	0.00	3,637.00	LF	0.00	\$5,436.00	
		0070	0420	7034600	FULL DEPTH REPAIR	3,300.00	0.00	3,300.00	SQFT	0.00	\$34.00	
		0070	0400	7040100	TOLE DEL TITTLE AIIX	3,300.00	0.00	0,000.00	JQF I	0.00	ψ34.00	

Revision 4/1/2020 Page 5 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repo generated date)
00117-G05	J7S3202	0070	0450	7040113	CLEANING AND EPOXY COATING	3,845.00	0.00	3,845.00	SQFT	0.00	\$11.89	\$0.0
		0070	0460	7040117	MONOLITHIC DECK REPAIR	44.00	0.00	44.00	CUYD	0.00	\$700.00	\$0.0
		0070	0470	7101000	REINFORCING STEEL (EPOXY COATED)	1,830.00	0.00	1,830.00	LB	0.00	\$2.96	\$0.0
		0070	0480	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$3,565.00	\$0.0
		0070	0490	7120900	EXPANSION DEVICE (FINGER PLATE)	52.00	0.00	52.00	LF	0.00	\$1,996.00	\$0.0
		0070	0500	7121251	HINGE MODIFICATION	8.00	0.00	8.00	EA	0.00	\$41,513.00	\$0.0
		0070	0510	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	3,300.00	0.00	3,300.00	SQFT	0.00	\$124.80	\$0.0
		0070	0520	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	3,300.00	0.00	3,300.00	SQFT	0.00	\$2.37	\$0.
		0070	0530	7125385A	INTERMEDIATE FIELD COAT (SYSTEM H)	3,700.00	0.00	3,700.00	SQFT	0.00	\$1.24	\$0.
		0070	0540	7125390A	FINISH FIELD COAT (SYSTEM H)	3,700.00	0.00	3,700.00	SQFT	0.00	\$1.24	\$0.
		0070	0550	7129902	MISC.Expansion Device Drainage Trough System	2.00	0.00	2.00	EA	0.00	\$19,828.00	\$0
		0070	0560	7129902	MISC.Relocate lateral Diagonal Bracing	2.00	0.00	2.00	EA	0.00	\$6,293.00	\$0
		0070	0570	7163000	TYPE N PTFE BEARING	8.00	0.00	8.00	EA	0.00	\$2,324.00	\$0
		0070	0580	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	52.00	0.00	52.00	LF	0.00	\$455.90	\$0
		0070	5001	7129901	MISC.Hinge Modification Design Change Bridge A37912 Route C	0.00	1.00	1.00	LS	0.00	\$8,083.20	\$0
		0001	5002	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	0.00	111.10	111.10	SQYD	0.00	\$11.00	\$0
		0070	5003	7129902	MISC.Bridge A3791 Drainage Trough Design Change	0.00	2.00	2.00	EA	0.00	\$10,267.11	\$0
	Project J				ate as of Report Generated Date						,	\$0
	J7S3203	0001	0590	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$3,836.00	\$3,836
		0001	0600	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	220.00	0.00	220.00	SQFT	220.00	\$134.70	\$29,634
		0001	0610	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	3.80	0.00	3.80	TONS	3.80	\$136.00	\$516
		0001	0620	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	14.20	0.00	14.20	TONS	14.20	\$413.60	\$5,873
		0001	0630	4071005	TACK COAT	35.00	0.00	35.00	GAL	0.00	\$3.09	\$0
		0001	0640	6161005	CONSTRUCTION SIGNS	747.00	45.00	792.00	SQFT	792.00	\$9.66	\$7,650
		0001	0650	6161008	ADVANCED WARNING RAIL SYSTEM	4.00	0.00	4.00	EA	4.00	\$93.72	\$374
		0001	0660	6161009	FLAG ASSEMBLY	2.00	0.00	2.00	EA	2.00	\$23.43	\$46
		0001	0670	6161012	BUOYS (BOATS KEEP OUT)	30.00	0.00	30.00	EA	22.00	\$246.00	\$5,412
		0001	0680	6161013	BUOYS (NO WAKE)	34.00	0.00	34.00	EA	14.00	\$246.00	\$3,444
		0001	0690	6161014	SPECIAL SIGN ASSEMBLY (BOATS KEEP OUT)	4.00	0.00	4.00	EA	4.00	\$1,289.00	\$5,156
		0001	0700	6161031	TYPE III MOVEABLE BARRICADE WITH LIGHTS	12.00	0.00	12.00	EA	12.00	\$210.90	\$2,530
		0001	0710	6161047	TYPE III OBJECT MARKER	4.00	0.00	4.00	EA	4.00	\$234.30	\$937
		0001	0720	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR	2.00	1.00	3.00	EA	3.00	\$5,272.00	\$15,816
		0001	0730	6181000	RETAINED MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$104,627.00	\$104,627
		0001	0740	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	3,844.00	0.00	3,844.00	LF	3,844.00	\$0.58	\$2,229
		0001	0750	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	775.00	0.00	775.00	LF	775.00	\$0.58	\$449
		0001	0760	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$1,852.00	\$1,852
		0001	0770	8051000A	SEEDING - COOL SEASON MIXTURES	1.00	0.00	1.00	ACRE	0.00	\$3,983.00	\$0
		0001	0780	8061016	SEDIMENT REMOVAL	18.00	0.00	18.00	CUYD	0.00	\$41.18	\$0
		0001	0790	8061019	SILT FENCE	1,800.00	0.00	1,800.00	LF	1,800.00	\$3.28	\$5,904
		0001	0800	2153000	SHAPING SLOPES, CLASS III	4.00	0.00	4.00	100F	4.00	\$814.10	\$3,256
		0010	0810	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	1,200.00	0.00	1,200.00	LF	1,200.00	\$25.18	\$30,210
		0010	0820	6061069	MGS BRIDGE APPROACH TRANSITION SECTION	4.00	0.00	4.00	EA	4.00	\$2,899.00	\$11,596
		0010	0830	6063014	(REGULAR/NO CURB) TYPE A CRASHWORTHY END TERMINAL (MASH)	4.00	0.00	4.00	EA	4.00	\$2,899.00	\$11,390
			0000	JUUJU 14	THE A GRADITIVORTHE LIND TERMINAL (MACH)	4.00	0.00	4.00	EM	4.00	ΨΖ,010.00	φ11,400

Revision 4/1/2020 Page 6 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract .CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
117-G05	J7S3203	0040	0850	9039902	MISC. RELOCATE AND REMOUNT EXISTING SIGN ON NEW PSST	2.00	0.00	2.00	EA	2.00	\$527.20	\$1,054.40
		0070	0860	2161000	SCARIFICATION OF BRIDGE DECK	4,926.00	0.00	4,926.00	SQYD	4,926.00	\$6.14	\$30,245.64
		0070	0870	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	104.00	0.00	104.00	LF	104.00	\$323.80	\$33,675.20
		0070	0880	2169903	MISC.Remove and Replace Curb and Parapet	34.00	0.00	34.00	LF	34.00	\$440.60	\$14,980.40
		0070	0890	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	4,935.00	0.00	4,935.00	SQYD	4,935.00	\$85.85	\$423,669.75
		0070	0900	7034214	CLASS B-2 CONCRETE	11.60	0.00	11.60	CUYD	11.60	\$5,438.00	\$63,080.80
		0070	0910	7034600	CURB BLOCKOUT	3,467.00	0.00	3,467.00	LF	3,467.00	\$51.31	\$177,891.77
		0070	0920	7040106	FULL DEPTH REPAIR	450.00	-450.00	0.00	SQFT	0.00	\$47.20	\$0.00
0070 0930 7040109 TOTAL SURF		TOTAL SURFACE HYDRO DEMOLITION	4,926.00	0.00	4,926.00	SQYD	4,926.00	\$31.75	\$156,400.50			
	0070 0940 7040113 CLEANING A		7040113	CLEANING AND EPOXY COATING	3,010.00	0.00	3,010.00	SQFT	3,010.00	\$11.89	\$35,788.90	
		0070	0950	7040117	MONOLITHIC DECK REPAIR	29.00	47.00	76.00	CUYD	76.00	\$700.00	\$53,200.00
		0070	0960	7101000	REINFORCING STEEL (EPOXY COATED)	1,830.00	0.00	1,830.00	LB	1,830.00	\$2.96	\$5,416.80
		0070	0970	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	1.00	\$3,565.00	\$3,565.00
		0070	0980	7120900	EXPANSION DEVICE (FINGER PLATE)	52.00	0.00	52.00	LF	52.00	\$1,996.00	\$103,792.00
		0070	0990	7121251	HINGE MODIFICATION	8.00	0.00	8.00	EA	8.00	\$41,513.00	\$332,104.00
		0070	1000	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	3,400.00	0.00	3,400.00	SQFT	3,400.00	\$124.80	\$424,320.0
		0070	1010	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	3,400.00	0.00	3,400.00	SQFT	3,400.00	\$2.37	\$8,058.0
		0070	1020	7125385A	INTERMEDIATE FIELD COAT (SYSTEM H)	3,800.00	0.00	3,800.00	SQFT	3,800.00	\$1.24	\$4,712.00
		0070	1030	7125390A	FINISH FIELD COAT (SYSTEM H)	3,800.00	0.00	3,800.00	SQFT	3,800.00	\$1.24	\$4,712.00
		0070	1040	7129902	MISC.Expansion Device Drainage Trough	2.00	0.00	2.00	EA	2.00	\$19,828.00	\$39,656.00
		0070	1050	7129902	MISC.Relocate Lateral Diagonal Bracing	2.00	0.00	2.00	EA	2.00	\$6,293.00	\$12,586.00
		0070	1060	7163000	TYPE N PTFE BEARING	8.00	0.00	8.00	EA	8.00	\$2,233.00	\$17,864.00
		0070	1070	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	52.00	0.00	52.00	LF	52.00	\$455.90	\$23,706.80
		0070	5101	7129901	MISC.Hinge Modification Design Change Br. A38822 Route ZZ	0.00	1.00	1.00	LS	1.00	\$17,904.00	\$17,904.00
		0070	5102	7129901	MISC.Cost of accelerated delivery of hinge modification material	0.00	1.00	1.00	LS	1.00	\$1,800.00	\$1,800.00
		0001	5103	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	0.00	122.20	122.20	SQYD	122.20	\$11.00	\$1,344.20
		0070	5104	6189901	MISC.Additional mobilization for Bridge A3882 hinge modifications	0.00	1.00	1.00	LS	1.00	\$8,962.51	\$8,962.5
		0070	5105	7129902	MISC.Bridge A3882 Drainage Trough Design Change	0.00	2.00	2.00	EA	2.00	\$10,267.11	\$20,534.22
	Project J	7S3203 - To	otal Value	Posted to D	late as of Report Generated Date							\$2,274,864.97
17-G05 Ove	erall - Total	Value Pos	ted to Da	te as of Repo	ort Generated Date							\$2,274,864.9

Revision 4/1/2020 Page 7 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J7S3203

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0600	2024043	REMOVAL OF MISCELLANEOUS ACM NON-FRIABLE	12/2/20	12/15/20	220.00	SQFT	Bridge A38882 - Report on file from subcontractor is SharePoint.	Bent 1		Bent 12		
0610	3049910	MISC. AGGREGATE FOR BASE	12/2/20	12/15/20	3.80	TONS	Installed at guardrail locations as shown on plans.	bent 1		bent 12		
0710	6161047	TYPE III OBJECT MARKER	12/2/20	12/15/20	4.00	EA	Route ZZ Bridge A3882 installed as plans directed.	end bent 1		end bent 12		
0740	6206000C	4 IN. WHITE WATERBORNE PAVEMENT MARKING	12/2/20	12/15/20	3,844.00	LF	Route ZZ - Bridge A3882 as shown on plans.	Bridge approach bt#1		Bridge Appr. bt#12		
0750	6206001C	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	12/2/20	12/15/20	775.00	LF	Route ZZ - Bridge A3882 as shown on plans.	Br. Appr. Bent #1		Br. Appr. Bent #12		
0780	8061016	SEDIMENT REMOVAL	12/2/20	12/15/20	0.00	CUYD	100% underrun.	n/a		n/a		
0840	9031270A	2 IN. PSST POST - 12 GA.	12/2/20	12/15/20	42.00	LF	(6) 7' posts for object markers and Truman Lake signs	Bent 1 br. A3882		Bent 12 Br. A3882		
0850	9039902	MISC.	12/2/20	12/15/20	2.00	EA	Remount of Truman Lake Signs at bridge ends	Br. A3882 bent 1		Br. A3882 bent 12		
0920	7040106	FULL DEPTH REPAIR	12/2/20	12/15/20	0.00	SQFT	100% underrun - bridge A3882 - Route ZZ	n/a		n/a		

The information below this line are details from Line Item agency views. No Agency View Details Exist

Revision 4/1/2020 Page 8 of 14



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0620	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE	Material		13	Dec 1, 2020	SYSTEM	(\$5,873.12)	
	LEVELING)			13	Dec 2, 2020	SYSTEM	\$5,873.12	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user markhs overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Other Item Adjustment	ACAD	13	Dec 2, 2020	RKHS	\$33.47	This adjustment zeros out a system adjustment error for AC index. This line item exceeded plan quantity and the adjustment for fuel and AC for asphalt will be made once that Change Order is approved.
			ACAD - Tota	al			\$33.47	
	Other Item Adjustment - Total						\$33.47	
	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Price		13	Dec 1, 2020	SYSTEM	(\$33.47)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			- Total				(\$33.47)	
	Price - Total						(\$33.47)	
0620 -	Total						\$0.00	
0640	CONSTRUCTION SIGNS	Material		3	Jun 30, 2020	SYSTEM	(\$7,216.02)	
				3	Jun 30, 2020	SYSTEM	\$7,216.02	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user markhs overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0640 -	Total						\$0.00	
0650	ADVANCED WARNING RAIL SYSTEM	Material		3	Jun 30, 2020	SYSTEM	(\$374.88)	
				3	Jun 30, 2020	SYSTEM	\$374.88	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user markhs overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0650 -	Total						\$0.00	
0660	FLAG ASSEMBLY	Material		3	Jun 30, 2020	SYSTEM	(\$46.86)	
				3	Jun 30, 2020	SYSTEM	\$46.86	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user markhs overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0660 -	Total						\$0.00	
0670	BUOYS (BOATS KEEP OUT)	Material		3	Jun 30, 2020	SYSTEM	(\$7,380.00)	
				3	Jun 30, 2020	SYSTEM	\$7,380.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user markhs overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0670 -	Total						\$0.00	
0680	BUOYS (NO WAKE)	Material		3	Jun 30, 2020	SYSTEM	(\$8,364.00)	
				3	Jun 30, 2020	SYSTEM	\$8,364.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user markhs overridding Payment Estimate Exception 5 on the current Payment Estimate.
	- Total						\$0.00	
	Material - Total						\$0.00	
0680 -							\$0.00	
0690	SPECIAL SIGN ASSEMBLY (BOATS KEEP OUT)	Material		3	Jun 30, 2020	SYSTEM	(\$5,156.00)	
	(3	Jun 30,	SYSTEM	\$5,156.00	This adjustment offsets the original system-generated Overrun Payment

Revision 4/1/2020 Page 9 of 14



		1						
Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0690	SPECIAL SIGN ASSEMBLY (BOATS KEEP OUT)	Material			2020			Estimate Item Adjustment (0006) due to user markhs overridding Payment Estimate Exception 6 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0690 -	- Total						\$0.00	
0700	TYPE III MOVEABLE BARRICADE WITH LIGHTS	Material		3	Jun 30, 2020	SYSTEM	(\$2,530.80)	
				3	Jun 30, 2020	SYSTEM	\$2,530.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user markhs overridding Payment Estimate Exception 7 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0700 -	· Total						\$0.00	
0720	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION	Material		3	Jun 30, 2020	SYSTEM	(\$10,544.00)	
	INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED			3	Jun 30, 2020	SYSTEM	\$10,544.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user markhs overridding Payment Estimate Exception 8 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	Other Item Adjustment	OTHR	12	Nov 17, 2020	RKHS	(\$5,272.00)	An adjustment was made on Pay Estimate 11 in the amount of \$5272.00 to provide prompt payment for this item that was on a pending Change order and could not be paid under the line item. This adjustment zeros that adjustment as the Change Order is approved and the item is paid on this Pay Estimate.
			OTHR - Tota	al			(\$5,272.00)	
	Other Item Adjustment - Total						(\$5,272.00)	
	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	Overrun	Overrun	11	Nov 2, 2020	RKHS	\$5,272.00	This line item adjustments is being created to provide payment to the contractor for a Changeable Message Board that is currently pending on a Change Order. This adjustment will be removed once the pending Change Order is approved.
			Overrun - T	otal			\$5,272.00	
	Overrun - Total						\$5,272.00	
0720 -	- Total						\$0.00	
0810	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	Material		13	Dec 1, 2020	SYSTEM	(\$30,216.00)	
				13	Dec 2, 2020	SYSTEM	\$30,216.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user markhs overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0810 -	- Total						\$0.00	
0820	MGS BRIDGE APPROACH TRANSITION SECTION	Material		13	Dec 1, 2020	SYSTEM	(\$11,596.00)	
	(REGULAR/NO CURB)			13	Dec 2, 2020	SYSTEM	\$11,596.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user markhs overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0820 -	- Total						\$0.00	
0880	MISC. Remove and Replace Curb and Parapet	Material		12	Nov 17, 2020	SYSTEM	(\$14,980.40)	
				12	Nov 17, 2020	SYSTEM	\$14,980.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user markhs overridding Payment Estimate Exception 2 on the current Payment Estimate.
				13	Dec 1, 2020	SYSTEM	(\$14,980.40)	
				13	Dec 2, 2020	SYSTEM	\$14,980.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user markhs overridding Payment Estimate Exception 1 on the current Payment Estimate.
				14	Dec 15, 2020	SYSTEM	(\$14,980.40)	

Revision 4/1/2020 Page 10 of 14



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0880	MISC. Remove and Replace Curb and Parapet	Material		14	Dec 16, 2020	SYSTEM	\$14,980.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user markhs overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0880 -	Total						\$0.00	
0890	LATEX MODIFIED CONCRETE WEARING SURFACE	Material		7	Sep 2, 2020	SYSTEM	(\$143,884.60)	
				7	Sep 2, 2020	SYSTEM	\$143,884.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user markhs overridding Payment Estimate Exception 1 on the current Payment Estimate.
				8	Sep 16, 2020	SYSTEM	(\$143,884.60)	
				8	Sep 16, 2020	SYSTEM	\$143,884.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user markhs overridding Payment Estimate Exception 1 on the current Payment Estimate.
				9	Sep 30, 2020	SYSTEM	(\$143,884.60)	
				9	Sep 30, 2020	SYSTEM	\$143,884.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user markhs overridding Payment Estimate Exception 1 on the current Payment Estimate.
				10	Oct 16, 2020	SYSTEM	(\$193,505.90)	
				10	Oct 16, 2020	SYSTEM	\$193,505.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user markhs overridding Payment Estimate Exception 1 on the current Payment Estimate.
				11	Nov 2, 2020	SYSTEM	(\$423,669.75)	
				11	Nov 2, 2020	SYSTEM	\$423,669.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user markhs overridding Payment Estimate Exception 1 on the current Payment Estimate.
				12	Nov 17, 2020	SYSTEM	(\$423,669.75)	
				12	Nov 17, 2020	SYSTEM	\$423,669.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user markhs overridding Payment Estimate Exception 3 on the current Payment Estimate.
				13	Dec 1, 2020	SYSTEM	(\$423,669.75)	
				13	Dec 2, 2020	SYSTEM	\$423,669.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user markhs overridding Payment Estimate Exception 3 on the current Payment Estimate.
				14	Dec 15, 2020	SYSTEM	(\$423,669.75)	
				14	Dec 16, 2020	SYSTEM	\$423,669.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user markhs overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0890 -	Total						\$0.00	
0900	CLASS B-2 CONCRETE	Material		3	Jun 30, 2020	SYSTEM	(\$16,314.00)	
				3	Jun 30, 2020	SYSTEM	\$16,314.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user markhs overridding Payment Estimate Exception 9 on the current Payment Estimate.
				4	Jul 15, 2020	SYSTEM	(\$16,314.00)	
				5	Aug 3, 2020	SYSTEM	(\$16,314.00)	
				6	Aug 17, 2020	SYSTEM	(\$16,314.00)	
				6	Aug 17, 2020	SYSTEM	\$16,314.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user markhs overridding Payment Estimate Exception 1 on the current Payment Estimate.
				7	Sep 2, 2020	SYSTEM	(\$31,540.40)	
				7	Sep 2,	SYSTEM	\$31,540.40	This adjustment offsets the original system-generated Overrun Payment

Revision 4/1/2020 Page 11 of 14



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0900	CLASS B-2 CONCRETE	Material	.,,,,		2020			Estimate Item Adjustment (0002) due to user markhs overridding Payment Estimate Exception 5 on the current Payment Estimate.
				8	Sep 16, 2020	SYSTEM	(\$31,540.40)	
				8	Sep 16, 2020	SYSTEM	\$31,540.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user markhs overridding Payment Estimate Exception 5 on the current Payment Estimate.
				9	Sep 30, 2020	SYSTEM	(\$63,080.80)	
				9	Sep 30, 2020	SYSTEM	\$63,080.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user markhs overridding Payment Estimate Exception 2 on the current Payment Estimate.
				10	Oct 16, 2020	SYSTEM	(\$63,080.80)	
				10	Oct 16, 2020	SYSTEM	\$63,080.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user markhs overridding Payment Estimate Exception 2 on the current Payment Estimate.
				11	Nov 2, 2020	SYSTEM	(\$63,080.80)	
				11	Nov 2, 2020	SYSTEM	\$63,080.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user markhs overridding Payment Estimate Exception 2 on the current Payment Estimate.
				12	Nov 17, 2020	SYSTEM	(\$63,080.80)	
				12	Nov 17, 2020	SYSTEM	\$63,080.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user markhs overridding Payment Estimate Exception 4 on the current Payment Estimate.
				13	Dec 1, 2020	SYSTEM	(\$63,080.80)	
				13	Dec 2, 2020	SYSTEM	\$63,080.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user markhs overridding Payment Estimate Exception 6 on the current Payment Estimate.
				14	Dec 15, 2020	SYSTEM	(\$63,080.80)	
				14	Dec 16, 2020	SYSTEM	\$63,080.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user markhs overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				(\$32,628.00)	
	Material - Total CLASS B-2 CONCRETE	MaterialCredit		5	Aug 3,	SYSTEM	(\$32,628.00) \$16,314.00	
	OBNOOD E CONONETE	Waterlatereal			2020			
				6	Aug 17, 2020	SYSTEM	\$16,314.00	
	MaterialCredit - Total		- Total				\$32,628.00 \$32,628.00	
	CLASS B-2 CONCRETE	Other Item Adjustment	PCCS	9	Sep 30, 2020	RKHS	(\$1,000.00)	Adjustment made as per agreed reduction in pay as per NCR #1.
			PCCS - Tota	ıl			(\$1,000.00)	
	Other Item Adjustment - Total						(\$1,000.00)	
0900 -						01/0	(\$1,000.00)	
0910	CURB BLOCKOUT	Material		12	Nov 17, 2020	SYSTEM	(\$133,406.00)	This allowance of the base of the state of t
				12	Nov 17, 2020	SYSTEM	\$133,406.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user markhs overridding Payment Estimate Exception 5 on the current Payment Estimate.
				13	Dec 1, 2020	SYSTEM	(\$177,891.77)	
				13	Dec 2, 2020	SYSTEM	\$177,891.77	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user markhs overridding Payment Estimate Exception 7 on the current Payment Estimate.
				14	Dec 15, 2020	SYSTEM	(\$177,891.77)	
				14	Dec 16, 2020	SYSTEM	\$177,891.77	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user markhs overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	

Revision 4/1/2020 Page 12 of 14



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0910	Material - Total						\$0.00	
0910 -	Total						\$0.00	
0940	CLEANING AND EPOXY COATING	Material		13	Dec 1, 2020	SYSTEM	(\$35,788.90)	
				13	Dec 2, 2020	SYSTEM	\$35,788.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user markhs overridding Payment Estimate Exception 11 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0940 -	Total						\$0.00	
0950	0950 MONOLITHIC DECK REPAIR	Material		8	Sep 16, 2020	SYSTEM	(\$20,300.00)	
				8	Sep 16, 2020	SYSTEM	\$20,300.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user markhs overridding Payment Estimate Exception 6 on the current Payment Estimate.
				9	Sep 30, 2020	SYSTEM	(\$20,300.00)	
				9	Sep 30, 2020	SYSTEM	\$20,300.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user markhs overridding Payment Estimate Exception 3 on the current Payment Estimate.
				10	Oct 16, 2020	SYSTEM	(\$20,300.00)	
				10	Oct 16, 2020	SYSTEM	\$20,300.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user markhs overridding Payment Estimate Exception 3 on the current Payment Estimate.
				11	Nov 2, 2020	SYSTEM	(\$20,300.00)	
				11	Nov 2, 2020	SYSTEM	\$20,300.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user markhs overridding Payment Estimate Exception 3 on the current Payment Estimate.
				12	Nov 17, 2020	SYSTEM	(\$53,200.00)	
				12	Nov 17, 2020	SYSTEM	\$53,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user markhs overridding Payment Estimate Exception 9 on the current Payment Estimate.
				13	Dec 1, 2020	SYSTEM	(\$53,200.00)	
				13	Dec 2, 2020	SYSTEM	\$53,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user markhs overridding Payment Estimate Exception 12 on the current Payment Estimate.
				14	Dec 15, 2020	SYSTEM	(\$53,200.00)	
				14	Dec 16, 2020	SYSTEM	\$53,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user markhs overridding Payment Estimate Exception 8 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0950 -	Total						\$0.00	
0970	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	Material		12	Nov 17, 2020	SYSTEM	(\$3,565.00)	
	FIERS (EPUXY)			12	Nov 17, 2020	SYSTEM	\$3,565.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user markhs overridding Payment Estimate Exception 10 on the current Payment Estimate.
				13	Dec 1, 2020	SYSTEM	(\$3,565.00)	
				13	Dec 2, 2020	SYSTEM	\$3,565.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user markhs overridding Payment Estimate Exception 13 on the current Payment Estimate.
			- Total				\$0.00	Estimate Exception to on the outron cayment Estimate.
	Material - Total		Total				\$0.00	
0970 -							\$0.00	
0980		Material		6	Aug 17,	SYSTEM	(\$51,896.00)	
0900	PLATE)	Material		6	Aug 17, 2020	SYSTEM	\$51,896.00	This adjustment offsets the original system-generated Overrun Payment
				U	Aug 17, 2020	JIJIEW	ψυ 1,080.UU	Estimate Item Adjustment (0003) due to user markhs overridding Payment

Revision 4/1/2020 Page 13 of 14



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
0980	EXPANSION DEVICE (FINGER PLATE)	Material						Estimate Exception 2 on the current Payment Estimate.	
			- Total				\$0.00		
	Material - Total						\$0.00		
0980 -	· Total						\$0.00		
0990	HINGE MODIFICATION	Material		5	Aug 3, 2020	SYSTEM	(\$124,539.00)		
				5	Aug 4, 2020	SYSTEM	\$124,539.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user markhs overridding Payment Estimate Exception 2 on the current Payment Estimate.	
			- Total				\$0.00		
	Material - Total						\$0.00		
0990 -	· Total						\$0.00		
1020	INTERMEDIATE FIELD COAT (SYSTEM H)	Material		12	Nov 17, 2020	SYSTEM	(\$4,712.00)		
				12	Nov 17, 2020	SYSTEM	\$4,712.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user markhs overridding Payment Estimate Exception 11 on the current Payment Estimate.	
				13	Dec 1, 2020	SYSTEM	(\$4,712.00)		
				13	Dec 2, 2020	SYSTEM	\$4,712.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user markhs overridding Payment Estimate Exception 14 on the current Payment Estimate.	
			- Total				\$0.00		
	Material - Total						\$0.00		
1020 -	Total						\$0.00		
1030	FINISH FIELD COAT (SYSTEM H)	Material		12	Nov 17, 2020	SYSTEM	(\$4,712.00)		
					12	Nov 17, 2020	SYSTEM	\$4,712.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user markhs overridding Payment Estimate Exception 12 on the current Payment Estimate.
				13	Dec 1, 2020	SYSTEM	(\$4,712.00)		
				13	Dec 2, 2020	SYSTEM	\$4,712.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user markhs overridding Payment Estimate Exception 15 on the current Payment Estimate.	
			- Total				\$0.00		
	Material - Total						\$0.00		
1030 -	·Total						\$0.00		
1040	MISC. Expansion Device Drainage Trough	Material		13	Dec 1, 2020	SYSTEM	(\$39,656.00)		
				13	Dec 2, 2020	SYSTEM	\$39,656.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user markhs overridding Payment Estimate Exception 16 on the current Payment Estimate.	
			- Total				\$0.00		
	Material - Total						\$0.00		
1040 -	Material - Total Total						\$0.00 \$0.00		

Revision 4/1/2020 Page 14 of 14