

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: July 1, 2021

| Progress Estima 26 | Progress Estimate Number 26 | | 200117-H05 Joe's Bridge & Grading, I | | | Original Contract Amount Net Change Order Amount Current Contract Amount | \$2,905,526.67 (\$757.48) \$2,904,769.19 | |
|-----------------------|--------------------------------|-------------|--|-----------------------------|--------------------|--|--|--|
| Approval Date | | | | | | | By User | |
| July 1, 2021 | | | Generated and Approve | the Project Office Level by | stottt1 | | | |
| July 1, 2021 | | R | eviewed and Approved (a | nd should be considere | ed Draft) at the I | Resident Engineer Level by | HILLSD1 | |
| July 2, 2021 | | | Reviewed and Approved at the Central Office Controllers Office Le | | | | | |
| Original Comp | letion Date | Current Com | Current Completion Date Actual Completion Date % of Current Contract Amo | | | | | |
| December | 1, 2021 | Decembe | er 1, 2021 | | | 100.00% | | |

| Co | Contract Informational Dates | | | | | | | | | | |
|--------------------------------|------------------------------|----------------------------------|--|--|--|--|--|--|--|--|--|
| Date Description | Original Completion Date | No Milestones Exist for Contract | | | | | | | | | |
| Acceptance Date | | | | | | | | | | | |
| Awarded Date | February 5, 2020 | February 5, 2020 | | | | | | | | | |
| Letting Date | January 17, 2020 | January 17, 2020 | | | | | | | | | |
| Notice to Proceed Date | March 9, 2020 | March 9, 2020 | | | | | | | | | |
| Open to Traffic Date - 9S3331 | December 22, 2020 | December 22, 2020 | | | | | | | | | |
| Open to Traffic Date - 9S3332 | May 1, 2021 | May 1, 2021 | | | | | | | | | |
| Open to Traffic Date - J9S3222 | November 23, 2020 | November 23, 2020 | | | | | | | | | |
| Open to Traffic Date - J9S3227 | September 24, 2020 | September 24, 2020 | | | | | | | | | |
| Open to Traffic Date - J9S3331 | December 22, 2020 | December 22, 2020 | | | | | | | | | |
| Open to Traffic Date - J9S3333 | August 11, 2020 | August 11, 2020 | | | | | | | | | |

| Contract Total Pa | ay For Estimate No. 26 | | | | |
|-------------------|----------------------------|---------------|----------------|----------------|--|
| | | This Estimate | Previous | To Date | |
| 200117-H05 | | | | | |
| | Total Posted Items Pay | \$0.00 | \$2,904,769.24 | \$2,904,769.24 | |
| | Gross Item Adjustments | \$10,200.00 | (\$14,059.47) | (\$3,859.47) | |
| | Incentive | \$0.00 | \$0.00 | \$0.00 | |
| | Disincentive | \$0.00 | \$0.00 | \$0.00 | |
| | Liquidated Damage | \$0.00 | \$0.00 | \$0.00 | |
| | Other Contract Adjustments | \$0.00 | \$0.00 | \$0.00 | |
| | | | \$2,890,709.77 | \$2,900,909.77 | |
| Contract Total Pa | ayable This Estimate: | \$10,200.00 | | | |

Items Paid This Estimate Period

No Data Available Contract Adjustments This Estimate

| | | tments Exist on Contract | | | | | | |
|-------------------|----------------|-----------------------------------|--------------------------|--|--|------------------------|---------------------------------------|----------------------|
| Line Item | <u>Adjustr</u> | ments This Estimate | | | | | | |
| Project Number | Line No. | Item Description | Adjustment Type | Other Item Adjustment Type | Comments | Adjustment Quantity | Line Item Adjustment Unit Price | Adjustment amount |
| J9S3220 | 0220 | SEEDING - COOL SEASON MIXTURES | Other Item Adjustment | Material Discrepancy Payment Adjustment | stottt1 Payment made for acceptable seed growth | | | \$3,400.00 |
| | 0250 | TEMPORARY SEEDING AND MULCHING | MaterialCredit | | | 1 | \$900.00 | \$900.00 |
| | 0250 | TEMPORARY SEEDING AND MULCHING | Material | | | -1 | \$900.00 | (\$900.00) |
| J9S3222 | 0850 | SEEDING - COOL SEASON MIXTURES | Other Item Adjustment | Material Discrepancy Payment Adjustment | stottt1 Payment made for acceptable seed growth | | | \$3,400.00 |
| J9S3331 | 1600 | SEEDING - COOL SEASON MIXTURES | Other Item Adjustment | Material Discrepancy Payment Adjustment | stottt1 Payment made for acceptable seed growth | | | \$3,400.00 |

Page 1 of 24 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: July 1, 2021

| Progre | | imate Number 26 | Contract ID Prime Contr | 200117-I ractor Joe's Bri | | | | Amount (\$7 | 905,526.67 57.48) 904,769.19 |
|-------------------|-------------|--------------------|--|------------------------------|--|---|------------------------|---------------------------------------|------------------------------------|
| Project Number | Line No. | Item Desc | ription | Adjustment Type | Other Item Adjustment Type | Comments | Adjustment Quantity | Line Item Adjustment Unit Price | Adjustment amount |
| J9S3332 | 2210 | SEEDING - CO | SEEDING - COOL SEASON MIXTURES Adjustment Adjustment Adjustment Adjustment Adjustment Stottt1 Material Discrepancy Payment Adjustment Adjustment Stottt1 The pay item is being deducted due to missing material certifications. Contractor has been contacted. | | | | | | \$3,400.00 |
| | 2210 | SEEDING - CO | OL SEASON MIXTURES | Other Item Adjustment | Material Discrepancy Payment Adjustment | stottt1 This item being deducted due to missing material certification as required by specification. | | | (\$3,400.00) |
| Total | | | | | | | | | \$10,200.00 |

Revision 4/1/2020 Page 2 of 24



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

| | | | | | (| Contract Project Information | |
|-------------------|----------------------------|------------------------|---------|----------|--------------------------|------------------------------|--------------------------------|
| Project Number | Federal Proj. Number | Project Description | Route | County | | | Location of Work |
| J9S3220 | FAS S701(49) | Bridge Replacement | СС | PEMISCOT | 1.3 miles north of Rout | te A | |
| J9S3222 | FAS S701(48) | Bridge replacement | Α | PEMISCOT | 1.5 miles north of Brag | g City | |
| J9S3227 | FAS S701(47) | Bridge replacement | Т | PEMISCOT | 4 miles southeast of H | ayward | |
| J9S3331 | FAS S702(51) | Bridge replacement | А | PEMISCOT | 0.5 miles north of Rout | te K intersection | |
| J9S3332 | FAS S702(50) | Bridge replacement | 153 | PEMISCOT | 0.25 east of Route EE | intersection | |
| J9S3333 | FAS S702(49) | Bridge replacement | С | PEMISCOT | 5 miles west of Steele | | |
| otals by J | Job Numbe | ers | | | | | |
| J9S3220 | | | | | This Estimate | Barrella con | T- D-4- |
| 0000220 | - | d 16 | | | This Estimate | Previous | To Date |
| | | d Item Pay | | | \$0.00 | \$568,886.43 | \$568,886.43 |
| | Gross | Item Adjustme | | | \$3,400.00 | (\$4,300.00) | (\$900.00) |
| | | | Gross | Item Pay | \$3,400.00 | \$564,586.43 | \$567,986.43 |
| | | 41 | | | #0.00 | #0.00 | #0.00 |
| | Incen | | | | \$0.00 | \$0.00 | \$0.00 |
| | | centive | | | \$0.00 | \$0.00 | \$0.00 |
| | | dated Damages | | | \$0.00 \$0.00 | \$0.00 \$32.00 | \$0.00 \$32.00 |
| | Otner | Contract Adjus | sinents | | φυ.υυ | Φ32.00 | \$32.00 |
| J9S3222 | | | | | This Estimate | Previous | To Date |
| JJ00222 | Posto | d Item Pay | | | \$0.00 | \$465,076.07 | \$465,076.07 |
| | | i item Adjustme | onte | | \$3,400.00 | (\$3,263.55) | \$136.45 |
| | 31088 | Aujustilit | | Item Pay | \$3,400.00 \$3,400.00 | \$461,812.52 | \$465,212.52 |
| | | | 0.035 | ay | ψο, του.υυ | ψ-το 1, Ο 12.02 | ψ-100,2 12.02 |
| | Incen | tive | | | \$0.00 | \$0.00 | \$0.00 |
| | | centive | | | \$0.00 | \$0.00 | \$0.00 |
| | | dated Damages | | | \$0.00 | \$0.00 | \$0.00 |
| | | Contract Adjus | | | \$0.00 | \$12.00 | \$12.00 |
| 1000000 | | | | | | | |
| J9S3227 | | | | | This Estimate | Previous | To Date |
| | | d Item Pay | | | \$0.00 | \$377,268.94 | \$377,268.94 |
| | Gross | Item Adjustme | | | \$0.00 | \$189.34 | \$189.34 |
| | | | Gross | Item Pay | \$0.00 | \$377,458.28 | \$377,458.28 |
| | Incen | tive | | | \$0.00 | \$0.00 | \$0.00 |
| | | centive | | | \$0.00 | \$0.00 | \$0.00 |
| | | dated Damages | | | \$0.00 | \$0.00 | \$0.00 |
| | | Contract Adjus | | | \$0.00 | (\$72.00) | (\$72.00) |
| | Diriel | - Jimadi Aujus | | | ψ0.00 | (ψ1 Σ.00) | (412.00) |
| J9S3331 | | | | | This Estimate | Previous | To Date |
| | Poste | d Item Pay | | | \$0.00 | \$370,365.33 | \$370,365.33 |
| | | Item Adjustme | ents | | \$3,400.00 | (\$3,400.00) | \$0.00 |
| | | , | | Item Pay | \$3,400.00 | \$366,965.33 | \$370,365.33 |
| | | | | | | | |
| | Incen | | | | \$0.00 | \$0.00 | \$0.00 |
| | | entive | | | \$0.00 | \$0.00 | \$0.00 |
| | | lated Damages | | | \$0.00 | \$0.00 | \$0.00 |
| | Other | Contract Adjus | stments | | \$0.00 | \$36.00 | \$36.00 |
| J9S3332 | | | | | This Cative - 4 | Droviews | To Date |
| usosssZ | Posts | d Itom Pou | | | This Estimate | Previous \$704 106 37 | To Date \$794,106.37 |
| | | d Item Pay | onte | | \$0.00 | \$794,106.37 (\$3,400.00) | |
| | Gross | Item Adjustme | | Item Pay | \$0.00 | | (\$3,400.00) \$790.706.37 |
| | | | Gross | nem Pay | \$0.00 | \$790,706.37 | \$790,706.37 |
| | Incen | tive | | | \$0.00 | \$0.00 | \$0.00 |
| | | centive | | | \$0.00 | \$0.00 | \$0.00 |
| | | dated Damages | | | \$0.00 | \$0.00 | \$0.00 |
| | | Contract Adjus | | | \$0.00 | \$172.00 | \$172.00 |
| | | | | | | | |
| J9S3333 | | | | | This Estimate | Previous | To Date |
| | | d Item Pay | | | \$0.00 | \$329,066.10 | \$329,066.10 |
| | Gross | Item Adjustme | | | \$0.00 | \$114.74 | \$114.74 |
| | | | Gross | Item Pay | \$0.00 | \$329,180.84 | \$329,180.84 |
| | | 41 | | | #0.00 | #0.00 | CO. OO |
| | Incen | | | | \$0.00 | \$0.00 | \$0.00 |
| | | centive | | | \$0.00 | \$0.00 | \$0.00 |
| | | dated Damages | | | \$0.00 | \$0.00 | \$0.00 |
| | Other | Contract Adjus | stments | | \$0.00 | (\$180.00) | (\$180.00) |

Revision 4/1/2020 Page 3 of 24



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

| Exceptions / Discrepencies | Explanation | Entered By | Status |
|--|---|---------------|--------------|
| Estimate Exception Type: Insufficient Materials: Project J9S3220, Item 8061017, Project Item Line Number 0250, Material Set 806101796, Material 0802MLST - Mulch Straw (Vegetative Mulch), Acceptance Action Generic 0802MLST is insufficient. | stottt1 Material Certification has not been provided | stottt1 | Acknowledged |
| Estimate Exception Type: Insufficient Materials: Project J9S3220, Item 8061017, Project Item Line Number 0250, Material Set 806101796, Material 0805SD - Grass Seed -Seed, Acceptance Action Generic 0805SD is insufficient. | stottt1 Material Certification has not been provided | stottt1 | Acknowledged |
| Estimate Exception Type: Insufficient Materials: Project J9S3220, Item 8061017, Project Item Line Number 0250, Material Set 806101796, Material 0801FZ - Fertilizer, Acceptance Action Generic 0801FZ is insufficient. | stottt1 Material Certification has not been provided | stottt1 | Acknowledged |

Revision 4/1/2020 Page 4 of 24



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Note: Posted Q | uantities | and Valu | es are b | pased on R | eport Generated date and can differ from the posted am | ount at the | time the | Estimate wa | s Genei | rated. | | |
|-------------------------|----------------|----------|-------------|--------------|--|-----------------|------------------------|------------------------------|---------|------------------------------------|-------------|--|
| Contract Nm.CONTRACT | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTED To Date (See report generated date) |
| 200117-H05 | J9S3220 | 0001 | 0010 | 2022010 | REMOVAL OF IMPROVEMENTS | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$5,000.00 | \$5,000.00 |
| | | 0001 | 0020 | 2064000 | POROUS BACKFILL | 89.00 | -16.00 | 73.00 | CUYD | 73.00 | \$82.00 | \$5,986.00 |
| | | 0001 | 0030 | 2079909 | MISC.MODIFIED LINEAR GRADING CLASS 2 | 6.10 | 0.00 | 6.10 | STA | 6.10 | \$2,400.00 | \$14,640.00 |
| | | 0001 | 0040 | 3040506 | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) | 912.00 | 0.00 | 912.00 | SQYD | 912.00 | \$14.00 | \$12,768.00 |
| | | 0001 | 0050 | 3105002 | GRAVEL (A) OR CRUSHED STONE (B) | 42.00 | 0.00 | 42.00 | TONS | 42.00 | \$30.00 | \$1,260.00 |
| | | 0001 | 0060 | 4039905 | MISC.OPTIONAL PAVEMENT | 911.20 | 0.00 | 911.20 | SQYD | 911.20 | \$52.94 | \$48,238.93 |
| | | 0001 | 0070 | 6096020 | FURNISHING TYPE 2 ROCK DITCH LINER | 323.00 | 0.00 | 323.00 | CUYD | 323.00 | \$20.00 | \$6,460.00 |
| | | 0001 | 0080 | 6096042 | PLACING TYPE 2 ROCK DITCH LINER | 323.00 | 0.00 | 323.00 | CUYD | 323.00 | \$32.00 | \$10,336.00 |
| | | 0001 | 0090 | 6113020 | FURNISHING TYPE 2 ROCK BLANKET | 313.00 | 0.00 | 313.00 | CUYD | 313.00 | \$20.00 | \$6,260.00 |
| | | 0001 | 0100 | 6113040 | PLACING TYPE 2 ROCK BLANKET | 313.00 | 0.00 | 313.00 | CUYD | 313.00 | \$32.00 | \$10,016.00 |
| | | 0001 | 0110 | 6149902 | MISC.24" FLAP GATE | 4.00 | 0.00 | 4.00 | EA | 4.00 | \$800.00 | \$3,200.00 |
| | | 0001 | 0120 | 6161005 | CONSTRUCTION SIGNS | 109.00 | 0.00 | 109.00 | SQFT | 109.00 | \$9.00 | \$981.00 |
| | | 0001 | 0130 | 6161008 | ADVANCED WARNING RAIL SYSTEM | 4.00 | 0.00 | 4.00 | EA | 4.00 | \$35.00 | \$140.00 |
| | | 0001 | 0140 | 6161009 | FLAG ASSEMBLY | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$20.00 | \$40.00 |
| | | 0001 | 0150 | 6161030 | TYPE III MOVEABLE BARRICADE | 4.00 | 0.00 | 4.00 | EA | 4.00 | \$120.00 | \$480.00 |
| | | 0001 | 0160 | 6161031 | TYPE III MOVEABLE BARRICADE WITH LIGHTS | 6.00 | 0.00 | 6.00 | EA | 6.00 | \$185.00 | \$1,110.00 |
| | | 0001 | 0170 | 6161098A | CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$3,000.00 | \$6,000.00 |
| | | 0001 | 0180 | 6181000 | MOBILIZATION | 1.00 | -1.00 | 0.00 | LS | 0.00 | \$50,000.00 | \$0.00 |
| | | 0001 | 0181 | 6181000 | MOBILIZATION | 0.00 | 1.00 | 1.00 | LS | 1.00 | \$41,283.50 | \$41,283.50 |
| | | 0001 | 0190 | 6240103A | PERMANENT EROSION CONTROL GEOTEXTILE | 1,205.00 | 0.00 | 1,205.00 | SQYD | 1,205.00 | \$3.00 | \$3,615.00 |
| | | 0001 | 0200 | 6274000 | CONTRACTOR FURNISHED SURVEYING AND STAKING | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$6,000.00 | \$6,000.00 |
| | | 0001 | 0210 | 7250424 | 24 IN. PIPE GROUP C | 211.00 | 0.00 | 211.00 | LF | 211.00 | \$42.00 | \$8,862.00 |
| | | 0001 | 0220 | 8051000A | SEEDING - COOL SEASON MIXTURES | 1.00 | 0.00 | 1.00 | ACRE | 1.00 | \$3,400.00 | \$3,400.00 |
| | | 0001 | 0230 | 8061005 | ROCK DITCH CHECK | 72.00 | -72.00 | 0.00 | LF | 0.00 | \$25.00 | \$0.00 |
| | | 0001 | 0240 | 8061016 | SEDIMENT REMOVAL | 9.00 | -9.00 | 0.00 | CUYD | 0.00 | \$5.00 | \$0.00 |
| | | 0001 | 0250 | 8061017 | TEMPORARY SEEDING AND MULCHING | 1.00 | 0.00 | 1.00 | ACRE | 1.00 | \$900.00 | \$900.00 |
| | | 0001 | 0260 | 8061019 | SILT FENCE | 250.00 | -250.00 | 0.00 | LF | 0.00 | \$4.50 | \$0.00 |
| | | 0001 | 0270 | 8061050 | TYPE C BERM | 200.00 | 0.00 | 200.00 | LF | 200.00 | \$10.00 | \$2,000.00 |
| | | 0040 | 0280 | 9031270A | 2 IN. PSST POST - 12 GA. | 48.00 | 0.00 | 48.00 | LF | 48.00 | \$20.00 | \$960.00 |
| | | 0040 | 0290 | 9031271 | POST ANCHOR FOR 2 IN. PSST - 12 GA. | 36.00 | 0.00 | 36.00 | LF | 36.00 | \$45.00 | \$1,620.00 |
| | | 0040 | 0300 | 9035069A | SHF-FLAT SHEET FLUORESCENT | 36.00 | 0.00 | 36.00 | SQFT | 36.00 | \$30.00 | \$1,080.00 |
| | | 0070 | 0310 | 2061000 | CLASS 1 EXCAVATION | 70.00 | 66.00 | 136.00 | CUYD | 136.00 | \$25.00 | \$3,400.00 |
| | | 0070 | 0320 | 2160500 | REMOVAL OF BRIDGES | 1.00 | 0.00 | 1.00 | LS | | \$30,000.00 | \$30,000.00 |
| | | 0070 | 0330 | 5031011A | BRIDGE APPROACH SLAB (MINOR ROAD) | 109.00 | 0.00 | 109.00 | SQYD | 109.00 | \$150.00 | \$16,350.00 |
| | | 0070 | 0340 | 7021314 | GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN) | 370.00 | -8.00 | 362.00 | LF | 362.00 | \$98.00 | \$35,476.00 |
| | | 0070 | 0350 | 7025001 | DYNAMIC PILE TESTING | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$3,750.00 | \$7,500.00 |
| | | 0070 | 0360 | 7027000 | PILE POINT REINFORCEMENT | 10.00 | 4.00 | 14.00 | EA | 14.00 | \$575.00 | \$8,050.00 |
| | | 0070 | 0370 | 7032003 | CLASS B CONCRETE (SUBSTRUCTURE) | 23.60 | 0.00 | 23.60 | CUYD | 23.60 | \$1,000.00 | \$23,600.00 |
| | | 0070 | 0380 | 7034215 | SAFETY BARRIER CURB | 205.00 | 0.00 | 205.00 | LF | 205.00 | \$95.00 | \$19,475.00 |
| | | 0070 | 0390 | 7034213 | SLAB ON CONCRETE NU-GIRDER | 244.00 | 0.00 | 244.00 | SQYD | 244.00 | \$360.00 | \$87,840.00 |
| | | | 0400 | 7056021 | NU 35, PRESTRESSED CONCRETE NU-GIRDER | 242.00 | 0.00 | 242.00 | LF | 242.00 | \$305.00 | \$73,810.00 |
| | | 0070 | 0410 | 7123610 | SLAB DRAIN | 14.00 | 0.00 | 14.00 | EA | 14.00 | \$305.00 | \$4,550.00 |
| | | 0070 | 0410 | 7151001 | VERTICAL DRAIN AT END BENTS | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$1,500.00 | \$3,000.00 |
| | | 0070 | | | | | | | | | | \$900.00 |
| | | 0070 | 0430 | 7161000 | PLAIN NEOPRENE BEARING PAD | 6.00 | 0.00 | 6.00 | EA | 6.00 | \$150.00 | |
| | | 0001 | 5001 | 6189901 | MISC.Mobilization | 0.00 | 1.00 | 1.00 | LS | 1.00 | \$52,299.00 | \$52,299.00 |

Page 5 of 24 Revision 4/1/2020



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| _ | Project J9 J9S3222 | 9S3220 - To | | | | | | | | Qty | | generated date) |
|---|-----------------------|-------------|------|----------|--|----------|---------|----------|------|----------|-------------|-----------------|
| J | J9S3222 | | | | ate as of Report Generated Date | | | | | | | \$568,886.43 |
| | | 0001 | 0590 | 2022010 | REMOVAL OF IMPROVEMENTS | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$5,000.00 | \$5,000.00 |
| | | 0001 | 0600 | 2064000 | POROUS BACKFILL | 89.00 | -13.00 | 76.00 | CUYD | 76.00 | \$85.00 | \$6,460.00 |
| | | 0001 | 0610 | 2079909 | MISC.MODIFIED LINEAR GRADING CLASS 2 | 7.10 | -0.20 | 6.90 | STA | 6.90 | \$2,400.00 | \$16,560.00 |
| | | 0001 | 0620 | 3040506 | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) | 1,184.00 | -43.00 | 1,141.00 | SQYD | 1,141.00 | \$14.00 | \$15,974.00 |
| | | 0001 | 0630 | 3105002 | GRAVEL (A) OR CRUSHED STONE (B) | 48.00 | 0.00 | 48.00 | TONS | 48.00 | \$30.00 | \$1,440.00 |
| | | 0001 | 0640 | 4039905 | MISC.OPTIONAL PAVEMENT | 1,183.40 | -43.00 | 1,140.40 | SQYD | 1,140.40 | \$48.91 | \$55,776.96 |
| | | 0001 | 0650 | 6096020 | FURNISHING TYPE 2 ROCK DITCH LINER | 60.00 | 0.00 | 60.00 | CUYD | 60.00 | \$20.00 | \$1,200.00 |
| | | 0001 | 0660 | 6096042 | PLACING TYPE 2 ROCK DITCH LINER | 60.00 | 0.00 | 60.00 | CUYD | 60.00 | \$32.00 | \$1,920.00 |
| | | 0001 | 0670 | 6097000 | ROCK LINING | 8.00 | 0.00 | 8.00 | CUYD | 8.00 | \$60.00 | \$480.00 |
| | | 0001 | 0680 | 6113020 | FURNISHING TYPE 2 ROCK BLANKET | 254.00 | 0.00 | 254.00 | CUYD | 254.00 | \$20.00 | \$5,080.00 |
| | | 0001 | 0690 | 6113040 | PLACING TYPE 2 ROCK BLANKET | 254.00 | 0.00 | 254.00 | CUYD | 254.00 | \$32.00 | \$8,128.00 |
| | | 0001 | 0700 | 6149902 | MISC.24 " FLAP GATE | 1.00 | 0.00 | 1.00 | EA | 1.00 | \$800.00 | \$800.00 |
| | | 0001 | 0710 | 6149902 | MISC.30" FLAP GATE | 1.00 | 0.00 | 1.00 | EA | 1.00 | \$1,025.00 | \$1,025.00 |
| | | 0001 | 0720 | 6161005 | CONSTRUCTION SIGNS | 205.00 | 0.00 | 205.00 | SQFT | 205.00 | \$8.00 | \$1,640.00 |
| | | 0001 | 0730 | 6161008 | ADVANCED WARNING RAIL SYSTEM | 4.00 | 0.00 | 4.00 | EA | 4.00 | \$35.00 | \$140.00 |
| | | 0001 | 0740 | 6161009 | FLAG ASSEMBLY | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$20.00 | \$40.00 |
| | | 0001 | 0750 | 6161030 | TYPE III MOVEABLE BARRICADE | 4.00 | 0.00 | 4.00 | EA | 4.00 | \$120.00 | \$480.00 |
| | | 0001 | 0760 | 6161031 | TYPE III MOVEABLE BARRICADE WITH LIGHTS | 6.00 | 0.00 | 6.00 | EA | 6.00 | \$185.00 | \$1,110.00 |
| | | 0001 | 0770 | 6161098A | CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$3,000.00 | \$6,000.00 |
| | | 0001 | 0780 | 6181000 | MOBILIZATION | 1.00 | -1.00 | 0.00 | LS | 0.00 | \$50,000.00 | \$0.00 |
| | | 0001 | 0781 | 6181000 | MOBILIZATION | 0.00 | 1.00 | 1.00 | LS | 1.00 | \$41,283.50 | \$41,283.50 |
| | | 0001 | 0790 | 6206000C | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | 1,260.00 | -40.00 | 1,220.00 | LF | 1,220.00 | \$2.20 | \$2,684.00 |
| | | 0001 | 0800 | 6206001C | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | 158.00 | 12.00 | 170.00 | LF | 170.00 | \$2.20 | \$374.00 |
| | | 0001 | 0810 | 6240103A | PERMANENT EROSION CONTROL GEOTEXTILE | 583.00 | 0.00 | 583.00 | SQYD | 583.00 | \$3.00 | \$1,749.00 |
| | | 0001 | 0820 | 6274000 | CONTRACTOR FURNISHED SURVEYING AND STAKING | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$6,000.00 | \$6,000.00 |
| | | 0001 | 0830 | 7250424 | 24 IN. PIPE GROUP C | 66.00 | 0.00 | 66.00 | LF | 66.00 | \$42.00 | \$2,772.00 |
| | | 0001 | 0840 | 7250430 | 30 IN. PIPE GROUP C | 51.00 | 0.00 | 51.00 | LF | 51.00 | \$48.00 | \$2,448.00 |
| | | 0001 | 0850 | 8051000A | SEEDING - COOL SEASON MIXTURES | 1.00 | 0.00 | 1.00 | ACRE | 1.00 | \$3,400.00 | \$3,400.00 |
| | | 0001 | 0860 | 8061005 | ROCK DITCH CHECK | 72.00 | -72.00 | 0.00 | LF | 0.00 | \$25.00 | \$0.00 |
| | | 0001 | 0870 | 8061016 | SEDIMENT REMOVAL | 10.00 | -10.00 | 0.00 | CUYD | 0.00 | \$5.00 | \$0.00 |
| | | 0001 | 0880 | 8061017 | TEMPORARY SEEDING AND MULCHING | 1.00 | -1.00 | 0.00 | ACRE | 0.00 | \$900.00 | \$0.00 |
| | | 0001 | 0890 | 8061019 | SILT FENCE | 320.00 | -320.00 | 0.00 | LF | 0.00 | \$4.50 | \$0.00 |
| | | 0001 | 0900 | 8061050 | TYPE C BERM | 140.00 | 0.00 | 140.00 | LF | 140.00 | \$10.00 | \$1,400.00 |
| | | 0040 | 0910 | 9031270A | 2 IN. PSST POST - 12 GA. | 48.00 | 0.00 | 48.00 | LF | 48.00 | \$20.00 | \$960.00 |
| | | 0040 | 0920 | 9031271 | POST ANCHOR FOR 2 IN. PSST - 12 GA. | 36.00 | 0.00 | 36.00 | LF | 36.00 | \$45.00 | \$1,620.00 |
| | | 0040 | 0930 | 9035069A | SHF-FLAT SHEET FLUORESCENT | 36.00 | 0.00 | 36.00 | SQFT | 36.00 | \$30.00 | \$1,080.00 |
| | | 0070 | 0940 | 2061000 | CLASS 1 EXCAVATION | 110.00 | 24.00 | 134.00 | CUYD | 134.00 | \$25.00 | \$3,350.00 |
| | | 0070 | 0950 | 2160500 | REMOVAL OF BRIDGES | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$30,000.00 | \$30,000.00 |
| | | 0070 | 0960 | 5031011A | BRIDGE APPROACH SLAB (MINOR ROAD) | 111.00 | 0.00 | 111.00 | SQYD | 111.00 | \$150.00 | \$16,650.00 |
| | | 0070 | 0970 | 7021316 | GALVANIZED CAST-IN-PLACE CONCRETE PILES (16 IN) | 200.00 | 125.00 | 325.00 | LF | 325.00 | \$102.00 | \$33,150.00 |
| | | 0070 | 0980 | 7025001 | DYNAMIC PILE TESTING | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$3,750.00 | \$7,500.00 |
| | | 0070 | 0990 | 7032003 | CLASS B CONCRETE (SUBSTRUCTURE) | 24.00 | 0.00 | 24.00 | CUYD | 24.00 | \$1,000.00 | \$24,000.00 |
| | | 0070 | 1000 | 7034213 | SLAB ON CONCRETE I-GIRDER | 197.00 | 0.00 | 197.00 | SQYD | 197.00 | \$385.00 | \$75,845.00 |
| | | 0070 | 1010 | 7034215 | SAFETY BARRIER CURB | 168.00 | 0.00 | 168.00 | LF | 168.00 | \$112.00 | \$18,816.00 |

Revision 4/1/2020 Page 6 of 24



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract m.CONTRACT | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTED To Date (See report generated date) |
|------------------------|-----------------------|------------|-------------|------------------------|--|-----------------|------------------------|------------------------------|------|------------------------------------|-------------|--|
| 00117-H05 | J9S3222 | 0070 | 1020 | 7056002 | TYPE 4 (45 IN.), PRESTRESSED CONCRETE I-GIRDER | 195.00 | 0.00 | 195.00 | LF | 195.00 | \$248.00 | \$48,360.00 |
| | | 0070 | 1030 | 7123301 | STEEL INTERMEDIATE DIAPHRAGM FOR P/S CONCRETE GIRDERS | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$700.00 | \$1,400.00 |
| | | 0070 | 1040 | 7123610 | SLAB DRAIN | 10.00 | 0.00 | 10.00 | EA | 10.00 | \$350.00 | \$3,500.00 |
| | | 0070 | 1050 | 7151001 | VERTICAL DRAIN AT END BENTS | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$1,500.00 | \$3,000.00 |
| | | 0070 | 1060 | 7161000 | PLAIN NEOPRENE BEARING PAD | 6.00 | 0.00 | 6.00 | EA | 6.00 | \$150.00 | \$900.00 |
| | | 0070 | 5101 | 7059901 | MISC.Increase strand size 0.5" to 0.6" | 0.00 | 1.00 | 1.00 | LS | 1.00 | \$600.00 | \$600.00 |
| | | 0070 | 5102 | 7059901 | MISC.Additional Strand and Increase of Tensile Bar Size From #5 to #6 | 0.00 | 1.00 | 1.00 | LS | 1.00 | \$550.00 | \$550.00 |
| | | 0070 | 5103 | 7101000 | REINFORCING STEEL (EPOXY COATED) | 0.00 | 305.00 | 305.00 | LB | 305.00 | \$3.29 | \$1,003.45 |
| | | 0070 | 5104 | 7101000 | REINFORCING STEEL (EPOXY COATED) | 0.00 | 391.00 | 391.00 | LB | 391.00 | \$3.65 | \$1,427.15 |
| | Project J | S3222 - To | otal Value | Posted to D | ate as of Report Generated Date | | | | | | | \$465,076.06 |
| | J9S3227 | 0001 | 1070 | 2022010 | REMOVAL OF IMPROVEMENTS | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$35,000.00 | \$35,000.00 |
| | | 0001 | 1080 | 2063300 | CLASS 4 EXCAVATION | 103.00 | 0.00 | 103.00 | CUYD | 103.00 | \$35.00 | \$3,605.00 |
| | | 0001 | 1090 | 2064000 | POROUS BACKFILL | 30.00 | 30.00 | 60.00 | CUYD | 60.00 | \$90.00 | \$5,400.00 |
| | | 0001 | 1100 | 2069901 | MISC.DEWATERING | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$30,000.00 | \$30,000.00 |
| | | 0001 | 1110 | 2079909 | MISC.MODIFIED LINEAR GRADING CLASS 2 | 16.70 | 0.00 | 16.70 | STA | 16.70 | \$2,650.00 | \$44,255.00 |
| | | 0001 | 1120 | 3040506 | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) | 1,294.00 | 0.00 | 1,294.00 | SQYD | 1,294.00 | \$14.00 | \$18,116.00 |
| | | 0001 | 1130 | 4019905 | MISC.OPTIONAL PAVEMENT | 1,109.00 | 0.00 | 1,109.00 | SQYD | 1,109.00 | \$38.26 | \$42,430.34 |
| | | 0001 | 1140 | 6097000 | ROCK LINING | 35.00 | 4.00 | 39.00 | CUYD | 39.00 | \$60.00 | \$2,340.00 |
| | | 0001 | 1150 | 6113020 | FURNISHING TYPE 2 ROCK BLANKET | 144.00 | -58.00 | 86.00 | CUYD | 86.00 | \$20.00 | \$1,720.00 |
| | | 0001 | 1160 | 6113040 | PLACING TYPE 2 ROCK BLANKET | 144.00 | -58.00 | 86.00 | CUYD | 86.00 | \$35.00 | \$3,010.00 |
| | | 0001 | 1170 | 6161005 | CONSTRUCTION SIGNS | 183.00 | -10.00 | 173.00 | SQFT | 173.00 | \$8.00 | \$1,384.00 |
| | | 0001 | 1180 | 6161008 | ADVANCED WARNING RAIL SYSTEM | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$35.00 | \$70.00 |
| | | 0001 | 1190 | 6161009 | FLAG ASSEMBLY | 4.00 | 0.00 | 4.00 | EA | 4.00 | \$20.00 | \$80.00 |
| | | 0001 | 1200 | 6161031 | TYPE III MOVEABLE BARRICADE WITH LIGHTS | 6.00 | 0.00 | 6.00 | EA | 6.00 | \$185.00 | \$1,110.00 |
| | | 0001 | 1210 | 6161052 | WARNING LIGHT, TYPE B | 4.00 | 0.00 | 4.00 | EA | 4.00 | \$80.00 | \$320.00 |
| | | 0001 | 1220 | 6161098A | CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$3,000.00 | \$6,000.00 |
| | | 0001 | 1230 | 6181000 | MOBILIZATION | 1.00 | -1.00 | 0.00 | LS | 0.00 | \$40,000.00 | \$0.00 |
| | | 0001 | 1231 | 6181000 | MOBILIZATION | 0.00 | 1.00 | 1.00 | LS | 1.00 | \$31,283.50 | \$31,283.50 |
| | | 0001 | 1240 | 6206000C | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | 935.00 | 595.00 | 1,530.00 | LF | 1,530.00 | \$2.20 | \$3,366.00 |
| | | 0001 | 1250 | 6206001C | 4 IN, YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | 423.00 | 0.00 | 423.00 | LF | 423.00 | \$2.20 | \$930.60 |
| | | 0001 | 1260 | 6207001 | PAVEMENT MARKING REMOVAL | 685.00 | 0.00 | 685.00 | LF | 685.00 | \$0.50 | \$342.50 |
| | | 0001 | 1270 | 6240103A | PERMANENT EROSION CONTROL GEOTEXTILE | 210.00 | -12.00 | 198.00 | SQYD | 198.00 | \$3.00 | \$594.00 |
| | | 0001 | 1280 | 6274000 | CONTRACTOR FURNISHED SURVEYING AND STAKING | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$6,000.00 | \$6,000.00 |
| | | 0001 | 1290 | 7034041 | CLASS B-1 CONCRETE (CULVERTS) | 131.40 | -131.40 | 0.00 | CUYD | 0.00 | \$800.00 | \$0.00 |
| | | 0001 | 1300 | 7061030 | REINFORCING STEEL (CULVERTS) | 9,080.00 | 8,590.00 | 17,670.00 | LB | 17,670.00 | \$1.50 | \$26,505.00 |
| | | 0001 | 1310 | 8051000A | SEEDING - COOL SEASON MIXTURES | 1.00 | 0.00 | 1.00 | ACRE | 1.00 | \$3,400.00 | \$3,400.00 |
| | | 0001 | 1320 | 8061005 | ROCK DITCH CHECK | 45.00 | -22.00 | 23.00 | LF | 23.00 | \$25.00 | \$575.00 |
| | | 0001 | 1330 | 8061017 | TEMPORARY SEEDING AND MULCHING | 1.00 | -1.00 | 0.00 | ACRE | 0.00 | \$900.00 | \$0.00 |
| | | 0001 | 1340 | 8061019 | SILT FENCE | 867.00 | -154.00 | 713.00 | LF | 713.00 | \$3.50 | \$2,495.50 |
| | | 0001 | 5301 | 7034041 | CLASS B-1 CONCRETE (CULVERTS) | 0.00 | 95.90 | 95.90 | CUYD | 95.90 | \$1,065.00 | \$102,133.50 |
| | | 0001 | 5302 | 7061030 | REINFORCING STEEL (CULVERTS) | 0.00 | 8,005.00 | 8,005.00 | LB | 8,005.00 | \$0.60 | \$4,803.00 |
| | Project J9 J9S3331 | 0001 | tal Value | Posted to D 2022010 | ate as of Report Generated Date REMOVAL OF IMPROVEMENTS | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$5,000.00 | \$377,268.94 \$5,000.00 |
| | 5555551 | 0001 | 1360 | 2064000 | POROUS BACKFILL | 39.00 | 10.00 | 49.00 | CUYD | 49.00 | \$85.00 | \$4,165.00 |
| | | 0001 | 1370 | 2079909 | MISC.MODIFIED LINEAR GRADING CL 2 | 3.20 | 0.00 | 3.20 | STA | 3.20 | \$2,400.00 | \$7,680.00 |
| | | 0001 | 1070 | 2010000 | MISSINGSHIED ENGLY GIVIDING GE 2 | 5.20 | 0.00 | 5.20 | JIA | 5.20 | ΨΣ, 700.00 | 97,000.00 |

Page 7 of 24 Revision 4/1/2020



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| ote: Posted Q | uantities | and value | es are b | ased on R | eport Generated date and can differ from the posted amo | ount at the | time the i | stimate wa | s Gener | ated. | | |
|-------------------------|----------------|-----------|-------------|--------------|--|-----------------|------------------------|------------------------------|---------|------------------------------------|-------------|--|
| Contract Nm.CONTRACT | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTED To Date (See report generated date) |
| 200117-H05 | J9S3331 | 0001 | 1380 | 3040506 | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) | 131.00 | 0.00 | 131.00 | SQYD | 131.00 | \$14.00 | \$1,834.00 |
| | | 0001 | 1390 | 3105002 | GRAVEL (A) OR CRUSHED STONE (B) | 80.00 | 0.00 | 80.00 | TONS | 80.00 | \$30.00 | \$2,400.00 |
| | | 0001 | 1400 | 4019905 | MISC.OPTIONAL PAVEMENT | 131.00 | 0.00 | 131.00 | SQYD | 131.00 | \$72.22 | \$9,460.82 |
| | | 0001 | 1410 | 6113020 | FURNISHING TYPE 2 ROCK BLANKET | 370.00 | 0.00 | 370.00 | CUYD | 370.00 | \$20.00 | \$7,400.00 |
| | | 0001 | 1420 | 6113040 | PLACING TYPE 2 ROCK BLANKET | 370.00 | 0.00 | 370.00 | CUYD | 370.00 | \$35.00 | \$12,950.00 |
| | | 0001 | 1430 | 6149902 | MISC.24 IN FLAP GATE | 1.00 | 0.00 | 1.00 | EA | 1.00 | \$800.00 | \$800.00 |
| | | 0001 | 1440 | 6149902 | MISC.30 IN FLAP GATE | 1.00 | 0.00 | 1.00 | EA | 1.00 | \$1,050.00 | \$1,050.00 |
| | | 0001 | 1450 | 6149902 | MISC.36 IN FLAP GATE | 1.00 | 0.00 | 1.00 | EA | 1.00 | \$1,200.00 | \$1,200.00 |
| | | 0001 | 1460 | 6161005 | CONSTRUCTION SIGNS | 205.00 | 0.00 | 205.00 | SQFT | 205.00 | \$8.00 | \$1,640.00 |
| | | 0001 | 1470 | 6161008 | ADVANCED WARNING RAIL SYSTEM | 4.00 | 0.00 | 4.00 | EA | 4.00 | \$35.00 | \$140.00 |
| | | 0001 | 1480 | 6161009 | FLAG ASSEMBLY | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$20.00 | \$40.00 |
| | | 0001 | 1490 | 6161030 | TYPE III MOVEABLE BARRICADE | 6.00 | 0.00 | 6.00 | EA | 6.00 | \$120.00 | \$720.00 |
| | | 0001 | 1500 | 6161052 | WARNING LIGHT, TYPE B | 4.00 | 0.00 | 4.00 | EA | 4.00 | \$80.00 | \$320.00 |
| | | 0001 | 1510 | 6161098A | CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$3,000.00 | \$6,000.00 |
| | | 0001 | 1520 | 6181000 | MOBILIZATION | 1.00 | -1.00 | 0.00 | LS | 0.00 | \$50,000.00 | \$0.00 |
| | | 0001 | 1521 | 6181000 | MOBILIZATION | 0.00 | 1.00 | 1.00 | LS | 1.00 | \$41,283.50 | \$41,283.50 |
| | | 0001 | 1530 | 6206000C | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | 295.00 | 3.00 | 298.00 | LF | 298.00 | \$8.75 | \$2,607.50 |
| | | 0001 | 1540 | 6206001C | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | 37.00 | 13.00 | 50.00 | LF | 50.00 | \$8.75 | \$437.50 |
| | | 0001 | 1550 | 6240103A | PERMANENT EROSION CONTROL GEOTEXTILE | 767.00 | 0.00 | 767.00 | SQYD | 767.00 | \$3.00 | \$2,301.00 |
| | | 0001 | 1560 | 6274000 | CONTRACTOR FURNISHED SURVEYING AND STAKING | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$6,000.00 | \$6,000.00 |
| | | 0001 | 1570 | 7250424 | 24 IN. PIPE GROUP C | 64.00 | 0.00 | 64.00 | LF | 64.00 | \$42.00 | \$2,688.00 |
| | | 0001 | 1580 | 7250430 | 30 IN. PIPE GROUP C | 65.00 | 0.00 | 65.00 | LF | 65.00 | \$48.00 | \$3,120.00 |
| | | 0001 | 1590 | 7250436 | 36 IN. PIPE GROUP C | 59.00 | 0.00 | 59.00 | LF | 59.00 | \$60.00 | \$3,540.00 |
| | | 0001 | 1600 | 8051000A | SEEDING - COOL SEASON MIXTURES | 1.00 | 0.00 | 1.00 | ACRE | 1.00 | \$3,400.00 | \$3,400.00 |
| | | 0001 | 1610 | 8061005 | ROCK DITCH CHECK | 49.00 | -49.00 | 0.00 | LF | 0.00 | \$25.00 | \$0.00 |
| | | 0001 | 1620 | 8061016 | SEDIMENT REMOVAL | 6.00 | -6.00 | 0.00 | CUYD | 0.00 | \$5.00 | \$0.00 |
| | | 0001 | 1630 | 8061017 | TEMPORARY SEEDING AND MULCHING | 1.00 | -1.00 | 0.00 | ACRE | 0.00 | \$900.00 | \$0.00 |
| | | 0001 | 1640 | 8061019 | SILT FENCE | 129.00 | -129.00 | 0.00 | LF | 0.00 | \$5.50 | \$0.00 |
| | | 0001 | 1650 | 8061050 | TYPE C BERM | 173.00 | 0.00 | 173.00 | LF | 173.00 | \$10.00 | \$1,730.00 |
| | | 0040 | 1660 | 9031270A | 2 IN. PSST POST - 12 GA. | 48.00 | 0.00 | 48.00 | LF | 48.00 | \$20.00 | \$960.00 |
| | | 0040 | 1670 | 9031271 | POST ANCHOR FOR 2 IN. PSST - 12 GA. | 36.00 | 0.00 | 36.00 | LF | 36.00 | \$45.00 | \$1,620.00 |
| | | 0040 | 1680 | 9035069A | SHF-FLAT SHEET FLUORESCENT | 36.00 | 0.00 | 36.00 | SQFT | 36.00 | \$30.00 | \$1,080.00 |
| | | 0070 | 1690 | 2061000 | CLASS 1 EXCAVATION | 60.00 | 0.00 | 60.00 | CUYD | 60.00 | \$25.00 | \$1,500.00 |
| | | 0070 | 1700 | 2160500 | REMOVAL OF BRIDGES | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$30,000.00 | \$30,000.00 |
| | | 0070 | 1710 | 5031011A | BRIDGE APPROACH SLAB (MINOR ROAD) | 111.00 | 0.00 | 111.00 | SQYD | 111.00 | \$150.00 | \$16,650.00 |
| | | 0070 | 1720 | 7021314 | GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN) | 352.00 | -68.00 | 284.00 | LF | 284.00 | \$75.00 | \$21,300.00 |
| | | 0070 | 1730 | 7025001 | DYNAMIC PILE TESTING | 1.00 | 1.00 | 2.00 | EA | 2.00 | \$3,750.00 | \$7,500.00 |
| | | 0070 | 1740 | 7027000 | PILE POINT REINFORCEMENT | 8.00 | 0.00 | 8.00 | EA | 8.00 | \$575.00 | \$4,600.00 |
| | | 0070 | 1750 | 7032003 | CLASS B CONCRETE (SUBSTRUCTURE) | 22.20 | 0.00 | 22.20 | CUYD | 22.20 | \$1,000.00 | \$22,200.00 |
| | | 0070 | 1760 | 7034215 | SAFETY BARRIER CURB | 135.00 | 0.00 | 135.00 | LF | 135.00 | \$112.00 | \$15,120.00 |
| | | 0070 | 1770 | 7034222 | SLAB ON CONCRETE BEAM | 156.00 | 0.00 | 156.00 | SQYD | 156.00 | \$395.00 | \$61,620.00 |
| | | 0070 | 1780 | 7056049 | 21 IN., PRESTRESSED CONCRETE SPREAD BOX BEAM | 152.00 | 0.00 | 152.00 | LF | 152.00 | \$329.00 | \$50,008.00 |
| | | 0070 | 1790 | 7123610 | SLAB DRAIN | 8.00 | 0.00 | 8.00 | EA | 8.00 | \$300.00 | \$2,400.00 |
| | | 0070 | 1800 | 7151001 | VERTICAL DRAIN AT END BENTS | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$1,500.00 | \$3,000.00 |
| | | | | | | | | | | | | |

Revision 4/1/2020 Page 8 of 24



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract Nm.CONTRACT | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTED To Date (See report generated date) |
|-------------------------|----------------|-------------|-------------|--------------|--|-----------------|------------------------|------------------------------|------|------------------------------------|-------------|--|
| 200117-H05 | Project J | 9S3331 - To | otal Value | Posted to D | late as of Report Generated Date | | | | | | | \$370,365.32 |
| | J9S3332 | 0001 | 1960 | 2022010 | REMOVAL OF IMPROVEMENTS | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$5,000.00 | \$5,000.00 |
| | | 0001 | 1970 | 2064000 | POROUS BACKFILL | 39.00 | 11.00 | 50.00 | CUYD | 50.00 | \$85.00 | \$4,250.00 |
| | | 0001 | 1980 | 2079909 | MISC.MODIFIED LINEAR GRADING CL 2 | 7.10 | 1.00 | 8.10 | STA | 8.10 | \$2,400.00 | \$19,440.00 |
| | | 0001 | 1990 | 3040506 | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) | 1,257.40 | 0.00 | 1,257.40 | SQYD | 1,257.40 | \$14.00 | \$17,603.60 |
| | | 0001 | 2000 | 3105002 | GRAVEL (A) OR CRUSHED STONE (B) | 75.00 | 0.00 | 75.00 | TONS | 75.00 | \$30.00 | \$2,250.00 |
| | | 0001 | 2010 | 4011209 | BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) | 12.60 | 0.00 | 12.60 | TONS | 12.60 | \$130.70 | \$1,646.82 |
| | | 0001 | 2020 | 4013000 | BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE) | 37.30 | -31.80 | 5.50 | TONS | 5.50 | \$109.61 | \$602.86 |
| | | 0001 | 2030 | 4019905 | MISC.OPTIONAL PAVEMENT | 1,242.50 | 0.00 | 1,242.50 | SQYD | 1,242.50 | \$49.48 | \$61,478.90 |
| | | 0001 | 2040 | 4071005 | TACK COAT | 12.00 | 0.00 | 12.00 | GAL | 12.00 | \$28.66 | \$343.92 |
| | | 0001 | 2050 | 6113020 | FURNISHING TYPE 2 ROCK BLANKET | 603.00 | 0.00 | 603.00 | CUYD | 603.00 | \$20.00 | \$12,060.00 |
| | | 0001 | 2060 | 6113040 | PLACING TYPE 2 ROCK BLANKET | 603.00 | 0.00 | 603.00 | CUYD | 603.00 | \$32.00 | \$19,296.00 |
| | | 0001 | 2070 | 6149902 | MISC.36 IN FLAP GATE | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$1,100.00 | \$2,200.00 |
| | | 0001 | 2080 | 6161005 | CONSTRUCTION SIGNS | 572.00 | 32.00 | 604.00 | SQFT | 604.00 | \$6.50 | \$3,926.00 |
| | | 0001 | 2090 | 6161008 | ADVANCED WARNING RAIL SYSTEM | 4.00 | 0.00 | 4.00 | EA | 4.00 | \$35.00 | \$140.00 |
| | | 0001 | 2100 | 6161009 | FLAG ASSEMBLY | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$20.00 | \$40.00 |
| | | 0001 | 2110 | 6161030 | TYPE III MOVEABLE BARRICADE | 10.00 | 0.00 | 10.00 | EA | 10.00 | \$120.00 | \$1,200.00 |
| | | 0001 | 2120 | 6161052 | WARNING LIGHT, TYPE B | 8.00 | 0.00 | 8.00 | EA | 8.00 | \$80.00 | \$640.00 |
| | | 0001 | 2130 | 6161098A | CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$3,000.00 | \$6,000.00 |
| | | 0001 | 2140 | 6181000 | MOBILIZATION | 1.00 | -1.00 | 0.00 | LS | 0.00 | \$70,000.00 | \$0.00 |
| | | 0001 | 2141 | 6181000 | MOBILIZATION | 0.00 | 1.00 | 1.00 | LS | 1.00 | \$61,283.50 | \$61,283.50 |
| | | 0001 | 2150 | 6206000C | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | 1,460.00 | 33.00 | 1,493.00 | LF | 1,493.00 | \$1.10 | \$1,642.30 |
| | | 0001 | 2160 | 6206001C | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | 789.00 | 61.00 | 850.00 | LF | 850.00 | \$1.10 | \$935.00 |
| | | 0001 | 2170 | 6221001 | COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS) | 117.00 | 0.00 | 117.00 | SQYD | 117.00 | \$29.09 | \$3,403.53 |
| | | 0001 | 2180 | 6240103A | PERMANENT EROSION CONTROL GEOTEXTILE | 1,107.00 | 0.00 | 1,107.00 | SQYD | 1,107.00 | \$3.00 | \$3,321.00 |
| | | 0001 | 2190 | 6274000 | CONTRACTOR FURNISHED SURVEYING AND STAKING | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$6,000.00 | \$6,000.00 |
| | | 0001 | 2200 | 7250436 | 36 IN. PIPE GROUP C | 201.00 | 0.00 | 201.00 | LF | 201.00 | \$60.00 | \$12,060.00 |
| | | 0001 | 2210 | 8051000A | SEEDING - COOL SEASON MIXTURES | 1.00 | 0.00 | 1.00 | ACRE | 1.00 | \$3,400.00 | \$3,400.00 |
| | | 0001 | 2220 | 8061005 | ROCK DITCH CHECK | 58.00 | -58.00 | 0.00 | LF | 0.00 | \$25.00 | \$0.00 |
| | | 0001 | 2230 | 8061016 | SEDIMENT REMOVAL | 12.00 | -12.00 | 0.00 | CUYD | 0.00 | \$5.00 | \$0.00 |
| | | 0001 | 2240 | 8061017 | TEMPORARY SEEDING AND MULCHING | 1.00 | -1.00 | 0.00 | ACRE | 0.00 | \$900.00 | \$0.00 |
| | | 0001 | 2250 | 8061019 | SILT FENCE | 757.00 | -757.00 | 0.00 | LF | 0.00 | \$3.50 | \$0.00 |
| | | 0001 | 2260 | 8061050 | TYPE C BERM | 241.00 | 0.00 | 241.00 | LF | 241.00 | \$10.00 | \$2,410.00 |
| | | 0010 | 2270 | 6061060 | MGS GUARDRAIL | 113.00 | 0.00 | 113.00 | LF | 113.00 | \$30.00 | \$3,390.00 |
| | | 0010 | 2280 | 6061069 | MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB) | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$3,200.00 | \$6,400.00 |
| | | 0010 | 2290 | 6063014 | TYPE A CRASHWORTHY END TERMINAL (MASH) | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$3,000.00 | \$6,000.00 |
| | | 0010 | 2300 | 6063017 | TYPE C CRASHWORTHY END TERMINAL | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$16,000.00 | \$32,000.00 |
| | | 0070 | 2310 | 2061000 | CLASS 1 EXCAVATION | 60.00 | 42.00 | 102.00 | CUYD | 102.00 | \$25.00 | \$2,550.00 |
| | | 0070 | 2320 | 2160500 | REMOVAL OF BRIDGES | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$40,000.00 | \$40,000.00 |
| | | 0070 | 2330 | 5031011A | BRIDGE APPROACH SLAB (MINOR ROAD) | 122.00 | 0.00 | 122.00 | SQYD | 122.00 | \$150.00 | \$18,300.00 |
| | | 0070 | 2340 | 7021316 | GALVANIZED CAST-IN-PLACE CONCRETE PILES (16 IN) | 820.00 | -59.00 | 761.00 | LF | 761.00 | \$92.00 | \$70,012.00 |
| | | 0070 | 2350 | 7025001 | DYNAMIC PILE TESTING | 4.00 | 0.00 | 4.00 | EA | 4.00 | \$3,750.00 | \$15,000.00 |
| | | 0070 | 2360 | 7027000 | PILE POINT REINFORCEMENT | 18.00 | 0.00 | 18.00 | EA | 18.00 | \$650.00 | \$11,700.00 |
| | | 0070 | 2370 | 7032003 | CLASS B CONCRETE (SUBSTRUCTURE) | 39.40 | 0.00 | 39.40 | CUYD | 39.40 | \$1,000.00 | \$39,400.00 |
| | | 0070 | 2380 | 7034215 | SAFETY BARRIER CURB | 273.00 | 0.00 | 273.00 | LF | 273.00 | \$112.00 | \$30,576.00 |
| Revision 4/1/203 | | 3370 | | | | | | | | | =3 | Page 9 of 24 |

Page 9 of 24 Revision 4/1/2020



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| lote: Posted Q | uantities | and Valu | es are b | ased on R | eport Generated date and can differ from the posted am | ount at the | time the i | stimate wa | s Gener | ated. | | |
|-------------------------|----------------|-------------|-------------|--------------|--|-----------------|------------------------|------------------------------|---------|------------------------------------|-------------|--|
| Contract Nm.CONTRACT | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTED To Date (See report generated date) |
| 200117-H05 | J9S3332 | 0070 | 2390 | 7034222 | SLAB ON CONCRETE BEAM | 393.00 | 0.00 | 393.00 | SQYD | 393.00 | \$350.00 | \$137,550.00 |
| | | 0070 | 2400 | 7056049 | 21 IN., PRESTRESSED CONCRETE SPREAD BOX BEAM | 361.00 | 0.00 | 361.00 | LF | 361.00 | \$305.00 | \$110,105.00 |
| | | 0070 | 2410 | 7061060 | REINFORCING STEEL (BRIDGES) | 3,420.00 | 0.00 | 3,420.00 | LB | 3,420.00 | \$1.50 | \$5,130.00 |
| | | 0070 | 2420 | 7123610 | SLAB DRAIN | 20.00 | 0.00 | 20.00 | EA | 20.00 | \$300.00 | \$6,000.00 |
| | | 0070 | 2430 | 7151001 | VERTICAL DRAIN AT END BENTS | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$1,500.00 | \$3,000.00 |
| | | 0070 | 2440 | 7161000 | PLAIN NEOPRENE BEARING PAD | 18.00 | 0.00 | 18.00 | EA | 18.00 | \$150.00 | \$2,700.00 |
| | | 0001 | 5502 | 2129909 | MISC.SHOULDERING 3" MINUS ROCK | 0.00 | 1.00 | 1.00 | STA | 1.00 | \$1,719.93 | \$1,719.93 |
| | Project J | 9S3332 - To | otal Value | Posted to D | ate as of Report Generated Date | | | | | | | \$794,106.36 |
| | J9S3333 | 0001 | 2450 | 2022010 | REMOVAL OF IMPROVEMENTS | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$35,000.00 | \$35,000.00 |
| | | 0001 | 2460 | 2063300 | CLASS 4 EXCAVATION | 92.00 | 0.00 | 92.00 | CUYD | 92.00 | \$35.00 | \$3,220.00 |
| | | 0001 | 2470 | 2064000 | POROUS BACKFILL | 33.00 | 33.00 | 66.00 | CUYD | 66.00 | \$85.00 | \$5,610.00 |
| | | 0001 | 2480 | 2069901 | MISC.DEWATERING | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$30,000.00 | \$30,000.00 |
| | | 0001 | 2490 | 2079909 | MISC.MODIFIED LINEAR GRADING CLASS 2 | 5.20 | 0.00 | 5.20 | STA | 5.20 | \$3,400.00 | \$17,680.00 |
| | | 0001 | 2500 | 3040506 | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) | 417.00 | 0.00 | 417.00 | SQYD | 417.00 | \$14.00 | \$5,838.00 |
| | | 0001 | 2510 | 3105002 | GRAVEL (A) OR CRUSHED STONE (B) | 25.00 | 0.00 | 25.00 | TONS | 25.00 | \$30.00 | \$750.00 |
| | | 0001 | 2520 | 4019905 | MISC.OPTIONAL PAVEMENT | 384.50 | 0.00 | 384.50 | SQYD | 384.50 | \$45.57 | \$17,521.66 |
| | | 0001 | 2530 | 6097000 | ROCK LINING | 37.00 | 0.00 | 37.00 | CUYD | 37.00 | \$60.00 | \$2,220.00 |
| | | 0001 | 2540 | 6113020 | FURNISHING TYPE 2 ROCK BLANKET | 219.00 | 0.00 | 219.00 | CUYD | 219.00 | \$20.00 | \$4,380.00 |
| | | 0001 | 2550 | 6113040 | PLACING TYPE 2 ROCK BLANKET | 219.00 | 0.00 | 219.00 | CUYD | 219.00 | \$35.00 | \$7,665.00 |
| | | 0001 | 2560 | 6149902 | MISC.24" FLAP GATE | 2.00 | -1.00 | 1.00 | EA | 1.00 | \$800.00 | \$800.00 |
| | | 0001 | 2570 | 6149902 | MISC.48" FLAP GATE | 1.00 | 0.00 | 1.00 | EA | 1.00 | \$1,500.00 | \$1,500.00 |
| | | 0001 | 2580 | 6161005 | CONSTRUCTION SIGNS | 324.00 | 27.00 | 351.00 | SQFT | 351.00 | \$6.50 | \$2,281.50 |
| | | 0001 | 2590 | 6161008 | ADVANCED WARNING RAIL SYSTEM | 1.00 | 1.00 | 2.00 | EA | 2.00 | \$35.00 | \$70.00 |
| | | 0001 | 2600 | 6161009 | FLAG ASSEMBLY | 2.00 | 2.00 | 4.00 | EA | 4.00 | \$20.00 | \$80.00 |
| | | | 2610 | 6161031 | TYPE III MOVEABLE BARRICADE WITH LIGHTS | 6.00 | 0.00 | 6.00 | EA | 6.00 | \$185.00 | |
| | | 0001 | | | | | | | | | | \$1,110.00 |
| | | 0001 | 2620 | 6161052 | WARNING LIGHT, TYPE B | 4.00 | 0.00 | 4.00 | EA | 4.00 | \$80.00 | \$320.00 |
| | | 0001 | 2630 | 6161098A | CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$3,000.00 | \$6,000.00 |
| | | 0001 | 2640 | 6181000 | MOBILIZATION | 1.00 | -1.00 | 0.00 | LS | 0.00 | \$60,000.00 | \$0.00 |
| | | 0001 | 2641 | 6181000 | MOBILIZATION | 0.00 | 1.00 | 1.00 | LS | 1.00 | \$51,283.50 | \$51,283.50 |
| | | 0001 | 2650 | 6206000C | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | 3,246.00 | 54.00 | 3,300.00 | LF | 3,300.00 | \$0.60 | \$1,980.00 |
| | | 0001 | 2660 | 6206001C | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | 1,019.00 | -9.00 | 1,010.00 | LF | 1,010.00 | \$0.60 | \$606.00 |
| | | 0001 | 2670 | 6207001 | PAVEMENT MARKING REMOVAL | 984.00 | 470.00 | 1,454.00 | LF | 1,454.00 | \$0.50 | \$727.00 |
| | | 0001 | 2680 | 6240103A | PERMANENT EROSION CONTROL GEOTEXTILE | 298.00 | 18.00 | 316.00 | SQYD | 316.00 | \$3.00 | \$948.00 |
| | | 0001 | 2690 | 6274000 | CONTRACTOR FURNISHED SURVEYING AND STAKING | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$6,000.00 | \$6,000.00 |
| | | 0001 | 2700 | 7034041 | CLASS B-1 CONCRETE (CULVERTS) | 123.80 | -123.80 | 0.00 | CUYD | 0.00 | \$800.00 | \$0.00 |
| | | 0001 | 2710 | 7061030 | REINFORCING STEEL (CULVERTS) | 21,980.00 | -6,570.00 | 15,410.00 | LB | 15,410.00 | \$1.50 | \$23,115.00 |
| | | 0001 | 2720 | 8051000A | SEEDING - COOL SEASON MIXTURES | 1.00 | 0.00 | 1.00 | ACRE | 1.00 | \$3,400.00 | \$3,400.00 |
| | | 0001 | 2730 | 8061005 | ROCK DITCH CHECK | 45.00 | -33.00 | 12.00 | LF | 12.00 | \$25.00 | \$300.00 |
| | | 0001 | 2740 | 8061017 | TEMPORARY SEEDING AND MULCHING | 1.00 | -1.00 | 0.00 | ACRE | 0.00 | \$900.00 | \$0.00 |
| | | 0001 | 2750 | 8061019 | SILT FENCE | 337.00 | -22.00 | 315.00 | LF | 315.00 | \$4.50 | \$1,417.50 |
| | | 0001 | 5601 | 6149902 | MISC.32" Flap Gate | 0.00 | 1.00 | 1.00 | EA | 1.00 | \$1,312.50 | \$1,312.50 |
| | | 0001 | 5602 | 7259902 | MISC.REMOVAL & INSTALLATION OF 48" CMP | 0.00 | 1.00 | 1.00 | EA | 1.00 | \$3,100.00 | \$3,100.00 |
| | | | 5603 | 3109907 | MISC.WEDGE OF ROCK ACROSS BOX CULVERT TOP | 0.00 | 7.00 | 7.00 | CUYD | 7.00 | \$67.06 | \$469.42 |
| | | 0001 | | | | | | | | | | |
| | | 0001 | 5604 | 6096020 | FURNISHING TYPE 2 ROCK DITCH LINER | 0.00 | 6.00 | 6.00 | CUYD | 6.00 | \$40.00 | \$240.00 |
| | | 0001 | 5605 | 6096042 | PLACING TYPE 2 ROCK DITCH LINER | 0.00 | 6.00 | 6.00 | CUYD | 6.00 | \$40.00 | \$240.00 |

Revision 4/1/2020 Page 10 of 24



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract Nm.CONTRACT | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTED To Date (See report generated date) |
|---|----------------|------------|-------------|--------------|----------------------------------|-----------------|------------------------|------------------------------|------|------------------------------------|------------|--|
| 200117-H05 | J9S3333 | 0001 | 5606 | 7034041 | CLASS B-1 CONCRETE (CULVERTS) | 0.00 | 85.00 | 85.00 | CUYD | 85.00 | \$1,065.00 | \$90,525.00 |
| | | 0001 | 5607 | 7061030 | REINFORCING STEEL (CULVERTS) | 0.00 | 2,260.00 | 2,260.00 | LB | 2,260.00 | \$0.60 | \$1,356.00 |
| | Project J | S3333 - To | tal Value | Posted to D | Date as of Report Generated Date | | | | | | | \$329,066.08 |
| 200117-H05 Overall - Total Value Posted to Date as of Report Generated Date | | | | | | | | | | \$2,904,769.19 | | |

Revision 4/1/2020 Page 11 of 24



2580 - Total

Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

 $\underline{\textbf{The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.}$

The information below this line are details for Construction Signs (if applicable). Line DWR Total Quantity Posted Sign Information Station SF SF Each Total SF Project Log Mile Location Number Special Number Date For DWR Date Each Special Sign of Items Sign to Post Sign J9S3333 2580 July 6, 159 R11-4 60x30 12.50 ROAD Rte.F northbound @ 12.5 .25 12.5 2020 CLOSED TO THRU TRAFFIC R11-4 60x30 12.50 ROAD 10.076 Rte. 164 westbound 12.5 12.5 CLOSED TO THRU TRAFFIC R11-4 60x30 12.50 ROAD CLOSED TO THRU TRAFFIC 18.81 Rte. J eastbound 1.00 12.5 12.5 R11-4 60x30 12.50 ROAD CLOSED TO THRU TRAFFIC 2.976 Rte. C southbound 12.5 12.5 R11-4 60x30 12.50 ROAD CLOSED TO THRU TRAFFIC Rte. 164 eastbound 12.5 21.758 12.5 WO20-3a 4x4 16.00 ROAD 567+00 Rt of Rte. C 16 1.00 16 CLOSED 500 FT R11-2 48x30 10.00 ROAD 572+00 10 C/L 1.00 10 CLOSED R11-2 48x30 10.00 ROAD CLOSED 575+00 C/L 1.00 10 10 WO20-3 48x48 16.00 ROAD 10+00 Rte F from 1.00 16 16 CLOSED AHEAD intersection WO20-3a 4x4 16.00 ROAD CLOSED 500 FT 5+00 Rte. F from 1.00 16 16 intersection of Rte. 164 WO20-3 48x48 16.00 ROAD CLOSED AHEAD 562+00 Rt of Rte. C 16 1.00 16 R11-4 60x30 12.50 ROAD CLOSED TO THRU TRAFFIC 3.703 Rte. J eastbound 1.00 12.5 12.5

Revision 4/1/2020 Page 12 of 24



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|--------------------------------------|--------------------------|-----------------------------|----------------|-----------------|---------------|--------------|---|
| J9S3220 | 0181 | MOBILIZATION | Other Item Adjustment | OTHR | 2 | Apr 1, 2020 | stottt1 | \$2,905.50 | stottt1 04/01/2020 I missed an invoice for Bond Payment on Change Order 0001. A line item adjustment is being made to pay total invoice quantity of \$17,433.00. An amount of \$2905.50 will be made for each mobilization line number. When work begins the line item adjustment will be deducted. |
| | | | | | 19 | Mar 16, 2021 | stottt1 | (\$2,905.50) | stottt1 04/01/2020 I missed an invoice for Bond Payment on Change Order 0001. A line item adjustment is being made to pay total invoice quantity of \$17,433.00. An amount of \$2905.50 will be made for each mobilization line number. When work begins the line item adjustment will be deducted. |
| | | | | OTHR - Tota | il | | | \$0.00 | |
| | | | Other Item Adj | ustment - To | tal | | | \$0.00 | |
| | 0181 - | Total | | | | | | \$0.00 | |
| | 0220 | SEEDING - COOL SEASON MIXTURES | Other Item Adjustment | MDPA | 22 | May 3, 2021 | stottt1 | (\$3,400.00) | stottt1 Payment removed for seed growth. Application was not according to specifications |
| | | | | | 26 | Jul 1, 2021 | stottt1 | \$3,400.00 | stottt1 Payment made for acceptable seed growth |
| | | | | MDPA - Tota | al | | | \$0.00 | |
| | | | Other Item Adj | | | | | \$0.00 | |
| | 0220 | Total | - Allo - Rolli - All | | | | | \$0.00 | |
| | 0250 | TEMPORARY SEEDING AND | Material | | 17 | Feb 16, 2021 | SYSTEM | (\$900.00) | |
| | | MULCHING | | | 18 | Mar 1, 2021 | SYSTEM | (\$900.00) | |
| | | | | | 19 | Mar 16, 2021 | SYSTEM | \$900.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user stottt1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | | 19 | Mar 16, 2021 | SYSTEM | (\$900.00) | |
| | | | | | 20 | Apr 1, 2021 | SYSTEM | (\$900.00) | |
| | | | | | 21 | Apr 16, 2021 | SYSTEM | (\$900.00) | |
| | | | | | 22 | May 3, 2021 | SYSTEM | (\$900.00) | |
| | | | | | 23 | May 17, 2021 | SYSTEM | (\$900.00) | |
| | | | | | 24 | Jun 1, 2021 | SYSTEM | (\$900.00) | |
| | | | | | 25 | Jun 16, 2021 | SYSTEM | (\$900.00) | |
| | | | | - Total | 26 | Jul 1, 2021 | SYSTEM | (\$900.00) | |
| | | | Material - Tota | | | | | (\$8,100.00) | |
| | | | MaterialCredit | | 18 | Mar 1, 2021 | SYSTEM | \$900.00 | |
| | | | | | 19 | Mar 16, 2021 | SYSTEM | \$900.00 | |
| | | | | | 21 | Apr 16, 2021 | SYSTEM | \$900.00 | |
| | | | | | 22 | May 3, 2021 | SYSTEM | \$900.00 | |
| | | | | | 23 | May 17, 2021 | SYSTEM | \$900.00 | |
| | | | | | 24 | Jun 1, 2021 | SYSTEM | \$900.00 | |
| | | | | | 25 | Jun 16, 2021 | SYSTEM | \$900.00 | |
| | | | | | 26 | Jul 1, 2021 | SYSTEM | \$900.00 | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|-----------|--------|--|--------------------------|-----------------------------|----------------|-----------------|---------------|---------------|---|
| J9S3220 | 0250 | TEMPORARY SEEDING AND | MaterialCredit | - Total | | | | \$7,200.00 | |
| | | MULCHING | MaterialCredit | - Total | | | | \$7,200.00 | |
| | 0250 - | Total | | | | | | (\$900.00) | |
| | 0340 | GALVANIZED CIP CONCR PILES (14 IN) | Material | | 13 | Dec 17, 2020 | SYSTEM | \$35,476.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stottt1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 13 | Dec 17, 2020 | SYSTEM | (\$35,476.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | ı | | | | \$0.00 | |
| | 0340 - | · Total | | | | | | \$0.00 | |
| | 0360 | PILE POINT REINFORCEMENT | Overrun | Overrun | 13 | Dec 17, 2020 | SYSTEM | \$2,300.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user stottt1 overridding Payment Estimate Exception 24 on the current Payment Estimate. |
| | | | | | 13 | Dec 17, 2020 | SYSTEM | (\$2,300.00) | |
| | | | | | 14 | Jan 4, 2021 | SYSTEM | (\$2,300.00) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). |
| | | | | | 14 | Jan 4, 2021 | SYSTEM | \$2,300.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user stottt1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | Overrun - To | otal | | | \$0.00 | |
| | | | Overrun - Tota | ıl | | | | \$0.00 | |
| | 0360 - | · Total | | | | | | \$0.00 | |
| | 0370 | CLASS B CONCRETE (SUBSTRUCTURE) | Material | | 13 | Dec 17, 2020 | SYSTEM | \$23,600.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user stottt1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | | 13 | Dec 17, 2020 | SYSTEM | (\$23,600.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | ıl | | | | \$0.00 | |
| | 0370 - | · Total | | | | | | \$0.00 | |
| | 0380 | SAFETY BARRIER CURB | Material | | 16 | Feb 1, 2021 | SYSTEM | \$19,475.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user stottt1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 16 | Feb 1, 2021 | SYSTEM | (\$19,475.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | ı | | | | \$0.00 | |
| | 0380 - | | | | | | | \$0.00 | |
| | 0390 | SLAB ON CONCRETE NU- GIRDER | Material | | 14 | Jan 4, 2021 | SYSTEM | \$30,744.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user stottt1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 14 | Jan 4, 2021 | SYSTEM | (\$30,744.00) | |
| | | | | | 15 | Jan 19, 2021 | SYSTEM | \$87,840.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user stottt1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | | 15 | Jan 19, 2021 | SYSTEM | (\$87,840.00) | |
| | | | | | 16 | Feb 1, 2021 | SYSTEM | \$87,840.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user stottt1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | | 16 | Feb 1, 2021 | SYSTEM | (\$87,840.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | ıl | | | | \$0.00 | |
| | 0390 - | · Total | | | | | | \$0.00 | |
| J9S3220 - | Total | | | | | | | (\$900.00) | |
| J9S3222 | 0781 | MOBILIZATION | Other Item Adjustment | OTHR | 2 | Apr 1, 2020 | stottt1 | \$2,905.50 | stottt1 04/01/2020 I missed an invoice for Bond Payment on Change Order 0001. A line item adjustment is being made to pay total invoice quantity of \$17,433.00. An amount of \$2905.50 will be made for each mobilization line |



| roject | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | | | | |
|--------|--------|--|--------------------------|-------------------------------|----------------|---|------------------|--|--|-----------------|--------|---------------|--|
| 3222 | 0781 | MOBILIZATION | Other Item | OTHR | | | | | number. When work begins the line item adjustment will be deducted. | | | | |
| | | | Adjustment | | 7 | Sep 16, 2020 | stottt1 | (\$2,905.50) | Payments for mobilization have been made. See line item adjustment for Estimate 0002 April 1, 2020 | | | | |
| | | | | OTHR - Tota | al | | | \$0.00 | | | | | |
| | | | Other Item Ad | justment - To | tal | | | \$0.00 | | | | | |
| | 0781 - | Total | | | | | | \$0.00 | | | | | |
| | 0790 | 4 IN. WHITE WATERBORNE PAVEMENT | Other Item Adjustment | REFL | | Jan 4, 2021 | stottt1 | \$134.20 | 105% - 0 to 0.1 105% - 0.1 to 0.155 | | | | |
| | | MARKING | | REFL - Tota | ı | | | \$134.20 | | | | | |
| | | | Other Item Ad | ljustment - To | tal | | | \$134.20 | | | | | |
| | 0790 - | | | | | | | \$134.20 | | | | | |
| | 0800 | 4 IN. YELLOW WATERBORNE PAVEMENT | Other Item Adjustment | REFL | | Jan 4, 2021 | stottt1 | \$2.25 | 105% - 0.1 to 0.155 | | | | |
| | | MARKING | | REFL - Tota | ı | | | \$2.25 | | | | | |
| | | | Other Item Ad | justment - To | tal | | | \$2.25 | | | | | |
| | 0800 - | | | | | | | \$2.25 | | | | | |
| | 0850 | SEEDING - COOL SEASON MIXTURES | Other Item Adjustment | MDPA | 26 | Jul 1, 2021 | stottt1 | \$3,400.00 | stottt1 Payment made for acceptable seed growth | | | | |
| | | WIIXTORES | | MDPA - Tot | al | | | \$3,400.00 | | | | | |
| | | | | QMDS | 14 | Jan 4, 2021 | stottt1 | (\$3,400.00) | The contractor did not follow all specification requirements. Paper mulch (tack) or acceptable alternate was not used. Payment will be made when acceptable growth is achieved | | | | |
| | | | | QMDS - Tot | QMDS - Total | | | (\$3,400.00) | | | | | |
| | | | Other Item Ad | Other Item Adjustment - Total | | | | \$0.00 | | | | | |
| | 0850 - | | | | | | | \$0.00 | | | | | |
| | 0940 | | Overrun | Overrun | 14 | Jan 4, 2021 | SYSTEM | \$600.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user stottt1 overridding Payment Estimate Exception 4 on the current Payment Estimate. | | | | |
| | | | | | 14 | Jan 4, 2021 | SYSTEM | (\$600.00) | | | | | |
| | | | | Overrun - Total | | | | \$0.00 | | | | | |
| | | | Overrun - Tota | al | | | | \$0.00 | | | | | |
| | 0940 - | | | | | | | \$0.00 | | | | | |
| | 0960 | BRIDGE APPROACH SLAB (MINOR ROAD) | Material | | 12 | Dec 2, 2020 | SYSTEM | \$16,650.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user stottt1 overridding Payment Estimate Exception 1 on the current Payment Estimate. | | | | |
| | | | | | 12 | Dec 2, 2020 | SYSTEM | (\$16,650.00) | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | |
| | | | Material - Tota | al | | | | \$0.00 | | | | | |
| | 0960 - | | | | | | | \$0.00 | | | | | |
| | 0970 | GALVANIZED CIP CONCR PILES (16 IN) | Material | | 7 | Sep 16, 2020 | SYSTEM | \$21,930.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stottt1 overridding Payment Estimate Exception 1 on the current Payment Estimate. | | | | |
| | | CONCR PILES (16 | | | | | | | 7 | Sep 16, 2020 | SYSTEM | (\$21,930.00) | |
| | | | | | | 2020 | | | | | | | |
| | | | | - Total | | 2020 | | \$0.00 | | | | | |
| | | | Material - Tota | al | | | | \$0.00 \$0.00 | | | | | |
| | | | Material - Tota | | 7 | Sep 16, 2020 | SYSTEM | | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 8 on the current Payment Estimate. | | | | |
| | | | | al | 7 | Sep 16, | SYSTEM | \$0.00 | Estimate Item Adjustment (0001) overridding Payment Estimate Exception 8 | | | | |
| | | | | al | 7 | Sep 16, 2020 Sep 16, 2020 Oct 1, 2020 | SYSTEM SYSTEM | \$0.00 \$1,530.00 (\$1,530.00) (\$1,530.00) | Estimate Item Adjustment (0001) overridding Payment Estimate Exception 8 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). | | | | |
| | | | | al | 7 | Sep 16, 2020 Sep 16, 2020 Oct 1, | SYSTEM | \$0.00 \$1,530.00 (\$1,530.00) | Estimate Item Adjustment (0001) overridding Payment Estimate Exception 8 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates | | | | |
| | | | | al | 7 8 9 | Sep 16, 2020 Sep 16, 2020 Oct 1, 2020 Oct 15, | SYSTEM SYSTEM | \$0.00 \$1,530.00 (\$1,530.00) (\$1,530.00) | Estimate Item Adjustment (0001) overridding Payment Estimate Exception 8 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',102.00000 - 102.00000, | | | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | | | | |
|---------|--------|---------------------------------------|--------------------|-----------------------------|----------------|-----------------|----------------|---------------|---|-----------------|--------|-------------|---|
| J9S3222 | 0970 - | Total | | | | | | \$0.00 | | | | | |
| | 0990 | CLASS B CONCRETE (SUBSTRUCTURE) | Material | | 7 | Sep 16, 2020 | SYSTEM | \$12,000.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user stottt1 overridding Payment Estimate Exception 2 on the current Payment Estimate. | | | | |
| | | | | | 7 | Sep 16, 2020 | SYSTEM | (\$12,000.00) | | | | | |
| | | | | | 8 | Oct 1, 2020 | SYSTEM | \$12,000.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stottt1 overridding Payment Estimate Exception 1 on the current Payment Estimate. | | | | |
| | | | | | 8 | Oct 1, 2020 | SYSTEM | (\$12,000.00) | | | | | |
| | | | | | 9 | Oct 15, 2020 | SYSTEM | \$24,000.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user stottt1 overridding Payment Estimate Exception 1 on the current Payment Estimate. | | | | |
| | | | | | 9 | Oct 15, 2020 | SYSTEM | (\$24,000.00) | , | | | | |
| | | | | - Total | | 2020 | | \$0.00 | | | | | |
| | | | Material - Tota | | | | | \$0.00 | | | | | |
| | 0990 - | Total | | | | | | \$0.00 | | | | | |
| | 1000 | SLAB ON CONCRETE I- GIRDER | Material | | 7 | Sep 16, 2020 | SYSTEM | \$1,540.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user stottt1 overridding Payment Estimate Exception 3 on the current Payment Estimate. | | | | |
| | | | | | 7 | Sep 16, 2020 | SYSTEM | (\$1,540.00) | | | | | |
| | | | | | 8 | Oct 1, 2020 | SYSTEM | \$1,540.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user stottt1 overridding Payment Estimate Exception 2 on the current Payment Estimate. | | | | |
| | | | | | 8 | Oct 1, 2020 | SYSTEM | (\$1,540.00) | | | | | |
| | | | | | 9 | Oct 15, 2020 | SYSTEM | \$18,249.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user stottt1 overridding Payment Estimate Exception 2 on the current Payment Estimate. | | | | |
| | | | | | 9 | Oct 15, 2020 | SYSTEM | (\$18,249.00) | | | | | |
| | | | | | 10 | Nov 2, 2020 | SYSTEM | \$75,845.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user stottt1 overridding Payment Estimate Exception 1 on the current Payment Estimate. | | | | |
| | | | | | | 10 | Nov 2, 2020 | SYSTEM | (\$75,845.00) | | | | |
| | | | | | | | | | 11 | Nov 16, 2020 | SYSTEM | \$75,845.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user stottt1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 11 | Nov 16, 2020 | SYSTEM | (\$75,845.00) | | | | | |
| | | | | | 12 | Dec 2, 2020 | SYSTEM | \$75,845.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stottt1 overridding Payment Estimate Exception 2 on the current Payment Estimate. | | | | |
| | | | | | 12 | Dec 2, 2020 | SYSTEM | (\$75,845.00) | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | |
| | | | Material - Tota | | | | | \$0.00 | | | | | |
| | 1000 - | Total | | | | | | \$0.00 | | | | | |
| | 1010 | SAFETY BARRIER CURB | Material | | 10 | Nov 2, 2020 | SYSTEM | \$18,816.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user stottt1 overridding Payment Estimate Exception 4 on the current Payment Estimate. | | | | |
| | | | | | 10 | Nov 2, 2020 | SYSTEM | (\$18,816.00) | | | | | |
| | | | | | 11 | Nov 16, 2020 | SYSTEM | \$18,816.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stottt1 overridding Payment Estimate Exception 4 on the current Payment Estimate. | | | | |
| | | | | | 11 | Nov 16, 2020 | SYSTEM | (\$18,816.00) | | | | | |
| | | | | | 12 | Dec 2, 2020 | SYSTEM | \$18,816.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user stottt1 overridding Payment Estimate Exception 4 on the current Payment Estimate. | | | | |
| | | | | | 12 | Dec 2, | SYSTEM | (\$18,816.00) | | | | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|-----------|--------|--|--------------------------|-----------------------------|----------------|-----------------|---------------|--------------|---|
| J9S3222 | 1010 | SAFETY BARRIER CURB | Material | | | 2020 | | | |
| | | COND | | - Total | | | | \$0.00 | |
| | | | Material - Tota | ıl | | | | \$0.00 | |
| | 1010 - | Total | | | | | | \$0.00 | |
| | 1040 | SLAB DRAIN | Material | | 9 | Oct 15, 2020 | SYSTEM | \$3,500.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stottt1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | | | 9 | Oct 15, 2020 | SYSTEM | (\$3,500.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | ı | | | | \$0.00 | |
| | 1040 - | Total | | | | | | \$0.00 | |
| | 1060 | PLAIN NEOPRENE BEARING PAD | Material | | 9 | Oct 15, 2020 | SYSTEM | \$900.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user stottt1 overridding Payment Estimate Exception 7 on the current Payment Estimate. |
| | | | | | 9 | Oct 15, 2020 | SYSTEM | (\$900.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | 1 | | | | \$0.00 | |
| | 1060 - | Total | | | | | | \$0.00 | |
| | 5103 | REINFORCING STEEL (EPOXY COATED) | Material | | 13 | Dec 17, 2020 | SYSTEM | \$1,003.45 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user stottt1 overridding Payment Estimate Exception 17 on the current Payment Estimate. |
| | | | | | 13 | Dec 17, 2020 | SYSTEM | (\$1,003.45) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | ı | | | | \$0.00 | |
| | 5103 - | Total | | | | | | \$0.00 | |
| | 5104 | REINFORCING STEEL (EPOXY COATED) | Material | | 13 | Dec 17, 2020 | SYSTEM | \$1,427.15 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stottt1 overridding Payment Estimate Exception 10 on the current Payment Estimate. |
| | | | | | 13 | Dec 17, 2020 | SYSTEM | (\$1,427.15) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | ı | | | | \$0.00 | |
| | 5104 - | Total | | | | | | \$0.00 | |
| J9S3222 - | Total | | | | | | | \$136.45 | |
| J9S3227 | 1140 | ROCK LINING | Overrun | Overrun | 8 | Oct 1, 2020 | SYSTEM | (\$2,340.00) | |
| | | | | | 10 | Nov 2, 2020 | SYSTEM | \$2,340.00 | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',60.00000 - 60.00000, 'is applied (if non-zero). |
| | | | | Overrun - T | otal | | | \$0.00 | |
| | | | Overrun - Tota | ıl | | | | \$0.00 | |
| | 1140 - | Total | | | | | | \$0.00 | |
| | 1231 | MOBILIZATION | Other Item Adjustment | OTHR | 2 | Apr 1, 2020 | stottt1 | \$2,905.50 | stottt1 04/01/2020 I missed an invoice for Bond Payment on Change Order 0001. A line item adjustment is being made to pay total invoice quantity of \$17,433.00. An amount of \$2905.50 will be made for each mobilization line number. When work begins the line item adjustment will be deducted. |
| | | | | | 7 | Sep 16, 2020 | stottt1 | (\$2,905.50) | Payments for mobilization have been made. See line item adjustment for Estimate 0002 April 1, 2020 |
| | | | | OTHR - Tota | al | | | \$0.00 | |
| | | | Other Item Ad | justment - To | tal | | | \$0.00 | |
| | 1231 - | Total | | | | | | \$0.00 | |
| | 1240 | 4 IN. WHITE WATERBORNE | Other Item Adjustment | REFL | 8 | Oct 1, 2020 | stottt1 | (\$673.20) | 20% until reflectivity testing is completed according to specifications |
| | | PAVEMENT MARKING | | | 10 | Nov 2, 2020 | stottt1 | \$168.30 | Left stripe - 0 to .10444 = 105% = 84.15 Right stripe - 0 to .10444 = 105% = 84.15 |
| | | | | | 11 | Nov 16, 2020 | stottt1 | \$673.20 | Reflectivity testing complete 20% is being added back to contract |

MoDOT

Line Item Adjustments by Estimate

| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|-----------|---------|--------------------------------------|--------------------------|-----------------------------|---------------------|-----------------|---------------|---------------|---|
| J9S3227 | 1240 | 4 IN. WHITE WATERBORNE | Other Item Adjustment | REFL - Tota | ıl | | | \$168.30 | |
| | | PAVEMENT MARKING | Other Item Ad | justment - To | tal | | | \$168.30 | |
| | | | Overrun | Overrun | 8 | Oct 1, 2020 | SYSTEM | (\$1,309.00) | |
| | | | | | 9 | Oct 15, 2020 | SYSTEM | \$1,309.00 | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',2.20000 - 2.20000, 'is applied (if non-zero). |
| | | | | Overrun - T | otal | | | \$0.00 | |
| | | | Overrun - Tota | al | | | | \$0.00 | |
| | 1240 - | · Total | | | | | | \$168.30 | |
| | 1250 | | Other Item Adjustment | REFL | 8 | Oct 1, 2020 | stottt1 | (\$186.12) | 20% until reflectivity testing is completed according to specifications |
| | | PAVEMENT MARKING | | | 10 | Nov 2, 2020 | stottt1 | \$21.04 | Intermittent dash 0 to 1.0444 = 105% = 21.04 |
| | | | | | 11 | Nov 16, 2020 | stottt1 | \$186.12 | Reflectivity testing complete 20% is being added back to contract |
| | | | | REFL - Tota | ıl | | | \$21.04 | |
| | | | Other Item Ad | justment - To | tal | | | \$21.04 | |
| | 1250 - | · Total | | | | | | \$21.04 | |
| | 1290 | CLASS B-1 CONCRETE (CULVERTS) | Material | | 5 | Aug 16, 2020 | SYSTEM | \$38,400.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user stottt1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | | 5 | Aug 16, 2020 | SYSTEM | (\$38,400.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | ı | | | | \$0.00 | |
| | 1290 - | · Total | | | | | | \$0.00 | |
| | 1310 | SEEDING - COOL SEASON MIXTURES | Cother Item Adjustment | QMDS | 8 | Oct 1, 2020 | stottt1 | (\$3,400.00) | 100% deduction due to subcontractor not performing all required work according to specification. No paper mulch was used. Deduction will be reversed when seed growth obtained |
| | | | | | 12 Dec 2, s 2020 | | stottt1 | \$3,400.00 | Full payment for Estimate 0008 line adjustment |
| | | | | QMDS - Tot | al | | | \$0.00 | |
| | | | Other Item Ad | justment - To | tal | | | \$0.00 | |
| | 1310 - | · Total | | | | | | \$0.00 | |
| J9S3227 - | - Total | | | | | | | \$189.34 | |
| J9S3331 | 1400 | MISC. | Material | | 13 | Dec 17, 2020 | SYSTEM | \$9,460.82 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user stottt1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 13 | Dec 17, 2020 | SYSTEM | (\$9,460.82) | |
| | | | | | 14 | Jan 4, 2021 | SYSTEM | \$9,460.82 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user stottt1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 14 | Jan 4, 2021 | SYSTEM | (\$9,460.82) | |
| | | | | 15 | 15 J | Jan 19, 2021 | SYSTEM | \$9,460.82 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user stottt1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 15 | Jan 19, 2021 | SYSTEM | (\$9,460.82) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | ıl | | | | \$0.00 | |
| | 1400 - | · Total | | | | | | \$0.00 | |
| | 1521 | MOBILIZATION | Other Item Adjustment | | 2 | Apr 1, 2020 | stottt1 | \$2,905.50 | stottt1 04/01/2020 I missed an invoice for Bond Payment on Change Order 0001. A line item adjustment is being made to pay total invoice quantity of \$17,433.00. An amount of \$2905.50 will be made for each mobilization line number. When work begins the line item adjustment will be deducted. |
| | | | | | 19 | Mar 16, 2021 | stottt1 | (\$2,905.50) | stottt1 04/01/2020 I missed an invoice for Bond Payment on Change Order 0001. A line item adjustment is being made to pay total invoice |



| oject | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|-------|--------|--|-------------------------------|-----------------------------|----------------|-----------------|---------------|---------------|---|
| 3331 | 1521 | MOBILIZATION | Other Item Adjustment | OTHR | | | | | quantity of \$17,433.00. An amount of \$2905.50 will be made for each mobilization line number. When work begins the line item adjustment will be deducted. |
| | | | | OTHR - Tota | al | | | \$0.00 | |
| | | | Other Item Ad | justment - To | tal | | | \$0.00 | |
| | 1521 - | Total | | | | | | \$0.00 | |
| | 1530 | 4 IN. WHITE WATERBORNE PAVEMENT MARKING | Overrun | Overrun | 14 | Jan 4, 2021 | SYSTEM | \$26.25 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user stottt1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | | 14 | Jan 4, 2021 | SYSTEM | (\$26.25) | |
| | | | | Overrun - T | otal | | | \$0.00 | |
| | | | Overrun - Tota | ıl | | | | \$0.00 | |
| | 1530 - | Total | | | | | | \$0.00 | |
| | 1540 | 4 IN. YELLOW WATERBORNE PAVEMENT | Overrun | Overrun | 14 | Jan 4, 2021 | SYSTEM | \$113.75 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user stottt1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | MARKING | | | 14 | Jan 4, 2021 | SYSTEM | (\$113.75) | |
| | | | | Overrun - To | otal | | | \$0.00 | |
| | | | Overrun - Tota | ıl | | | | \$0.00 | |
| | 1540 - | Total | | | | | | \$0.00 | |
| | 1600 | SEEDING - COOL | Other Item Adjustment | MDPA | 26 | Jul 1, 2021 | stottt1 | \$3,400.00 | stottt1 Payment made for acceptable seed growth |
| | | SEASON MIXTURES | Aujustinont | MDPA - Tot | | 2021 | | \$3,400.00 | a symmetriade for acceptable seed growth |
| | | | | QMDS | | Jan 4, 2021 | stottt1 | (\$3,400.00) | The contractor did not follow all specification requirements. Paper mulch (tack) or acceptable alternate was not used. Payment will be made when acceptable growth is achieved |
| | | | | QMDS - Tot | al | | | (\$3,400.00) | |
| | | | Other Item Ad | justment - To | tal | | | \$0.00 | |
| | 1600 - | Total | Other Rein Adjustment - Total | | | | | \$0.00 | |
| | 1710 | BRIDGE APPROACH SLAB (MINOR ROAD) | Material | | 13 | Dec 17, 2020 | SYSTEM | \$16,650.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user stottt1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | | 13 | Dec 17, 2020 | SYSTEM | (\$16,650.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | ı | | | | \$0.00 | |
| | 1710 - | Total | | | | | | \$0.00 | |
| | 1720 | GALVANIZED CIP CONCR PILES (14 IN) | Material | | 11 | Nov 16, 2020 | SYSTEM | \$21,300.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user stottt1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 11 | Nov 16, 2020 | SYSTEM | (\$21,300.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | | | | | \$0.00 | |
| | 1720 - | Total | | | | | | \$0.00 | |
| | 1770 | SLAB ON CONCRETE BEAM | Material | | 12 | Dec 2, 2020 | SYSTEM | \$33,891.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user stottt1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | | 12 | Dec 2, 2020 | SYSTEM | (\$33,891.00) | |
| | | | | | 13 | Dec 17, 2020 | SYSTEM | \$33,891.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user stottt1 overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | | | 13 | Dec 17, 2020 | SYSTEM | (\$33,891.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | | | | | \$0.00 | |
| | 1770 - | Total | | | | | | \$0.00 | |
| _ | | | | | | | | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|-----------|--------|---------------------------------------|--------------------------|-----------------------------|----------------|-----------------|---------------|---------------|---|
| J9S3331 - | Total | | | | | | | \$0.00 | |
| J9S3332 | 2040 | TACK COAT | Material | | 22 | May 3, 2021 | SYSTEM | (\$343.92) | |
| | | | | | 23 | May 17, 2021 | SYSTEM | \$343.92 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user stottt1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 23 | May 17, 2021 | SYSTEM | (\$343.92) | |
| | | | | - Total | | | | (\$343.92) | |
| | | | Material - Tota | ı | | | | (\$343.92) | |
| | | | MaterialCredit | | 23 | May 17, 2021 | SYSTEM | \$343.92 | |
| | | | | - Total | | | | \$343.92 | |
| | | | MaterialCredit | - Total | | | | \$343.92 | |
| | 2040 - | Total | | | | | | \$0.00 | |
| | 2141 | MOBILIZATION | Other Item Adjustment | OTHR | | Apr 1, 2020 | stottt1 | \$2,905.50 | stottt1 04/01/2020 I missed an invoice for Bond Payment on Change Order 0001. A line item adjustment is being made to pay total invoice quantity of \$17,433.00. An amount of \$2905.50 will be made for each mobilization line number. When work begins the line item adjustment will be deducted. |
| | | | | | 21 | Apr 16, 2021 | stottt1 | (\$2,905.50) | Payments for mobilization have been made. See line item adjustment for Estimate 0002 April 1, 2020 |
| | | | | OTHR - Tota | | | | \$0.00 | |
| | | | Other Item Ad | ustment - To | tal | | | \$0.00 | |
| | 2141 - | Total | | | | | | \$0.00 | |
| | 2150 | 4 IN. WHITE WATERBORNE PAVEMENT | Other Item Adjustment | REFL | 22 | May 3, 2021 | stottt1 | (\$326.00) | stottt1 20% deduct until reflectivity can be tested |
| | | MARKING | | | 24 | Jun 1, 2021 | stottt1 | \$326.00 | stottt1 - reflectivity tests complete. 100% pay |
| | | | | REFL - Tota | | | | \$0.00 | |
| | | | Other Item Ad | ustment - To | tal | | | \$0.00 | |
| | | | Overrun | Overrun | | May 3, 2021 | SYSTEM | (\$24.20) | |
| | | | | | 24 | Jun 1, 2021 | SYSTEM | \$24.20 | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',1.10000 - 1.10000, 'is applied (if non-zero). |
| | | | | Overrun - T | otal | | | \$0.00 | |
| | | | Overrun - Tota | d | | | | \$0.00 | |
| | 2150 - | Total | | | | | | \$0.00 | |
| | 2160 | 4 IN. YELLOW WATERBORNE | Other Item Adjustment | REFL | 22 | May 3, 2021 | stottt1 | (\$185.00) | stottt1 20% deduct until reflectivity can be tested |
| | | PAVEMENT MARKING | | | 24 | Jun 1, 2021 | stottt1 | \$185.00 | stottt1 - reflectivity tests complete. 100% pay |
| | | | | REFL - Tota | | | | \$0.00 | |
| | | | Other Item Ad | ustment - To | tal | | | \$0.00 | |
| | | | Overrun | Overrun | | May 3, 2021 | SYSTEM | (\$59.40) | |
| | | | | | 24 | Jun 1, 2021 | SYSTEM | \$59.40 | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',1.10000 - 1.10000, 'is applied (if non-zero). |
| | | | | Overrun - T | otal | | | \$0.00 | |
| | | | Overrun - Tota | ıl | | | | \$0.00 | |
| | 2160 - | | | | | | | \$0.00 | |
| | 2200 | 36 IN. PIPE CULVERT GROUP C | Material | | 20 | Apr 1, 2021 | SYSTEM | \$12,060.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user stottt1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 20 | Apr 1, 2021 | SYSTEM | (\$12,060.00) | |
| | | | | | 21 | Apr 16, 2021 | SYSTEM | (\$12,060.00) | |
| | | | | | 22 | May 3, | SYSTEM | \$12,060.00 | This adjustment offsets the original system-generated Material Payment |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|---------------------------------------|-----------------------------------|-----------------------------|----------------|-----------------|---------------|-----------------------|--|
| J9S3332 | 2200 | 36 IN. PIPE CULVERT GROUP | Material | | | 2021 | | | Estimate Item Adjustment (0008) due to user stottt1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | С | | | 22 | May 3, 2021 | SYSTEM | (\$12,060.00) | |
| | | | | - Total | | | | (\$12,060.00) | |
| | | | Material - Tota | | | | | (\$12,060.00) | |
| | | | MaterialCredit | | 22 | May 3, | SYSTEM | \$12,060.00 | |
| | | | | | | 2021 | | | |
| | | | | - Total | | | | \$12,060.00 | |
| | | | MaterialCredit | - Total | | | | \$12,060.00 | |
| | 2200 - | | | | | | | \$0.00 | |
| | 2210 | SEEDING - COOL SEASON MIXTURES | Other Item Adjustment | MDPA | 25 | Jun 16, 2021 | stottt1 | (\$3,400.00) | stottt1 The pay item is being deducted due to missing material certifications. Contractor has been contacted. |
| | | | | | 26 | Jul 1, 2021 | SYSTEM | \$3,400.00 | stottt1 The pay item is being deducted due to missing material certifications. Contractor has been contacted. |
| | | | | | 26 | Jul 1, 2021 | stottt1 | (\$3,400.00) | stottt1 This item being deducted due to missing material certification as required by specification. |
| | | | | MDPA - Tot | al | | | (\$3,400.00) | |
| | | | Other Item Adj | ustment - To | tal | | | (\$3,400.00) | |
| | 2210 - | Total | | | | | | (\$3,400.00) | |
| | 2300 | TYPE C CRASHWORTHY END TERMINAL | Construction Stockpile | | 22 | May 3, 2021 | SYSTEM | (\$16,350.00) | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | LIND TERMINAL | | - Total | | | | (\$16,350.00) | |
| | | | Construction S | Stockpile - To | otal | | | (\$16,350.00) | |
| | | S | Construction Stockpile STMI | | 1 | Mar 16, 2020 | SYSTEM | \$16,350.00 | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | | | - Total | | | | \$16,350.00 | |
| | | | Construction | Stockpile STI | MI - Total | | | \$16,350.00 | |
| | 2340 | Total GALVANIZED CIP CONCR PILES (16 | Material | | 18 | Mar 1, 2021 | SYSTEM | \$0.00 \$34,960.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user stottt1 overridding Payment |
| | | IN) | | | 18 | Mar 1, | SYSTEM | (\$34,960.00) | Estimate Exception 1 on the current Payment Estimate. |
| | | | | | | 2021 | | A0.00 | |
| | | | | - Total | | | | \$0.00 | |
| | 2340 - | Total | Material - Tota | | | | | \$0.00 | |
| | 2340 - | SAFETY BARRIER CURB | Material | | 20 | Apr 1, 2021 | SYSTEM | \$0.00 \$30,576.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user stottt1 overridding Payment |
| | | | | | 20 | Apr 1, | SYSTEM | (\$30,576.00) | Estimate Exception 1 on the current Payment Estimate. |
| | | | | - Total | | 2021 | | \$0.00 | |
| | | | Material - Tota | | | | | \$0.00 | |
| | 2380 - | Total | material - Tota | | | | | \$0.00 | |
| | 2390 | SLAB ON CONCRETE BEAM | Material | | 19 | Mar 16, 2021 | SYSTEM | \$27,650.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user stottt1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 19 | Mar 16, 2021 | SYSTEM | (\$27,650.00) | |
| | | | | | 20 | Apr 1, 2021 | SYSTEM | \$137,550.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user stottt1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 20 | Apr 1, 2021 | SYSTEM | (\$137,550.00) | |
| | | | | | 21 | Apr 16, 2021 | SYSTEM | \$137,550.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user stottt1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 21 | Apr 16, | SYSTEM | (\$137,550.00) | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|-----------|----------------|--------------------------------------|--------------------------|-----------------------------|------------------|-----------------|---------------|--------------|---|
| J9S3332 | 2390 | SLAB ON | Material | Турс | | 2021 | | | |
| | | CONCRETE BEAM | | - Total | | | | \$0.00 | |
| | | | Material - Tota | | | | | \$0.00 | |
| | 2390 - | Total | | | | | | \$0.00 | |
| J9S3332 - | Total | | | | | | | (\$3,400.00) | |
| J9S3333 | 2470 | POROUS BACKFILL | Material | | 5 | Aug 16, 2020 | SYSTEM | \$2,805.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stottt1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 5 | Aug 16, 2020 | SYSTEM | (\$2,805.00) | |
| | | | | | 15 | Jan 19, 2021 | SYSTEM | \$2,805.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user stottt1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 15 | Jan 19, 2021 | SYSTEM | (\$2,805.00) | |
| | | | | | 16 | Feb 1, 2021 | SYSTEM | \$2,805.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user stottt1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 16 | Feb 1, 2021 | SYSTEM | (\$2,805.00) | |
| | | | | | 17 | Feb 16, 2021 | SYSTEM | \$5,610.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user stottt1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 17 | Feb 16, 2021 | SYSTEM | (\$5,610.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | ı | | | | \$0.00 | |
| | 2470 - | Total | | | | | | \$0.00 | |
| | 2500 | AGGREGATE FOR BASE (6 IN. | | | 4 | Aug 3, 2020 | SYSTEM | \$2,926.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user stottt1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 4 Aug 3, SY 2020 | | | (\$2,926.00) | |
| | | | | Total | | | | | |
| | | | Material - Tota | ı | | | | \$0.00 | |
| | 2500 - | Total | | | | | | \$0.00 | |
| | 2540 | FURNISHING TYPE 2 ROCK BLANKET | Material | | 4 | Aug 3, 2020 | SYSTEM | \$4,366.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stottt1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 4 | Aug 3, 2020 | SYSTEM | (\$4,366.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | ıl | | | | \$0.00 | |
| | 2540 - | Total | | | | | | \$0.00 | |
| | 2641 | MOBILIZATION | Other Item Adjustment | OTHR | 2 | Apr 1, 2020 | stottt1 | \$2,905.50 | stottt1 04/01/2020 I missed an invoice for Bond Payment on Change Order 0001. A line item adjustment is being made to pay total invoice quantity of \$17,433.00. An amount of \$2905.50 will be made for each mobilization line number. When work begins the line item adjustment will be deducted. |
| | | | | | 7 | Sep 16, 2020 | stottt1 | (\$2,905.50) | Payments for mobilization have been made. See line item adjustment for Estimate 0002 April 1, 2020 |
| | | | | OTHR - Tota | al | | | \$0.00 | |
| | | | Other Item Adj | justment - To | tal | | | \$0.00 | |
| | 2641 - | Total | | | | | | \$0.00 | |
| | 2650 | WATERBORNE | Other Item Adjustment | REFL | 5 | Aug 16, 2020 | stottt1 | (\$396.00) | stottt1 20% deduct until retroreflectivity testing can be completed |
| | | | | | 7 | Sep 16, 2020 | stottt1 | \$463.32 | Reflectivity testing is complete 20% paid for completion of testing - \$396.00 105% payment for reflectivity testing of white stripe - \$67.32 (See excel sheet for breakdown) |
| | | | | REFL - Tota | | | | \$67.32 | |
| | | | Other Item Adj | | | | | \$67.32 | |
| | 26 <u>50</u> - | Total | | | | | | \$67.32 | |
| | | | | | | | | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|-----------|--------------|--------------------------------------|-------------------------------|-----------------------------|----------------|-----------------|---------------|---------------|---|
| J9S3333 | 2660 | 4 IN. YELLOW WATERBORNE | Other Item Adjustment | REFL | 5 | Aug 16, 2020 | stottt1 | (\$121.20) | stottt1 20% deduct until retroreflectivity testing can be completed |
| | | PAVEMENT MARKING | | | 7 | Sep 16, 2020 | stottt1 | \$168.62 | Reflectivity testing is complete 20% paid for completion of testing - \$121.20 105% payment for reflectivity testing of yellow stripe - \$47.42 (See excel sheet for breakdown) |
| | | | | REFL - Tota | 1 | | | \$47.42 | |
| | | | Other Item Adjustment - Total | | | | | \$47.42 | |
| | 2660 - | | | | | | | \$47.42 | |
| | 2700 | CLASS B-1 CONCRETE (CULVERTS) | Material | | 3 | Jul 15, 2020 | SYSTEM | \$39,776.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user stott11 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 3 | Jul 15, 2020 | SYSTEM | (\$39,776.00) | |
| | | | | | 4 | Aug 3, 2020 | SYSTEM | \$99,040.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user stottt1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | | 4 | Aug 3, 2020 | SYSTEM | (\$99,040.00) | |
| | | | | | 5 | Aug 16, 2020 | SYSTEM | \$99,040.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user stottt1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 5 | Aug 16, 2020 | SYSTEM | (\$99,040.00) | |
| | | | | | 13 | Dec 17, 2020 | SYSTEM | \$99,040.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user stottt1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | | | 13 | Dec 17, 2020 | SYSTEM | (\$99,040.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | ı | | | | \$0.00 | |
| | 2700 - | Total | | | | | | \$0.00 | |
| | 2710 | REINFORCING STEEL (CULVERTS) | Material | | 3 | Jul 15, 2020 | SYSTEM | \$20,341.50 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stott1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 3 | Jul 15, 2020 | SYSTEM | (\$20,341.50) | |
| | | | | | 4 | Aug 3, 2020 | SYSTEM | \$32,970.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user stott1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | | | 4 | Aug 3, 2020 | SYSTEM | (\$32,970.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | | | | | \$0.00 | |
| | 2710 - | Total | | | | | | \$0.00 | |
| | 2720 | SEEDING - COOL SEASON MIXTURES | Other Item Adjustment | QMDS | 5 | Aug 16, 2020 | stottt1 | (\$3,400.00) | stottt1 Actual quantity of work performed was 0.2 acres. Work was completed while inspectors were not present with performance in question. Growth will be evaluated at 60 days to determine acceptance of work performed |
| | | | | | 12 | Dec 2, 2020 | stottt1 | \$3,400.00 | Full payment made for line adjustment on Estimate 0005 |
| | | | | QMDS - Total | | | | \$0.00 | |
| | | | Other Item Adjustment - Total | | | | | \$0.00 | |
| | 2720 - | 2720 - Total | | | | | | | |
| | 2730 | ROCK DITCH CHECK | Material | | 3 | Jul 15, 2020 | SYSTEM | \$300.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user stottt1 overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | | | | | 3 | Jul 15, 2020 | SYSTEM | (\$300.00) | |
| | | | | - Total | - Total | | | \$0.00 | |
| | | | Material - Total | | | | | \$0.00 | |
| | 2730 - Total | | | | | | | | |
| J9S3333 - | Total | | | | | | | \$114.74 | |



Jul 2, 2021

| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|-----------|-------|-------------|--------------------|-----------------------------|----------------|-----------------|---------------|--------|---------|
| Overall - | Total | | | | | (\$3,859.47) | | | |