87.50%



Missouri Department of Transportation Contractor's Pay Estimate Summary

December 1, 2020

Pay Estimate Created Date: August 17, 2020

Progress Estima	ate Number	Contract ID Prime Contractor	200117-H06 Joe's Bridge & Gradir			Original Contract Amount Net Change Order Amount Current Contract Amount	nt \$30,189.20		
Approval Date							By User		
August 17, 2020	Generated and Approved (and should be considered Draft) at the Project Office Level by								
August 17, 2020		F	Reviewed and Approve	d (and should be conside	red Draft) at the F	Resident Engineer Level by	holtb1		
August 19, 2020	ugust 19, 2020 Reviewed and Approved at the Central Office Controllers Office Level by								
Original Comp	letion Date	Current Cor	mpletion Date	Actual Completion Da	ite %	of Current Contract Amour	nt Complete		

No Milestones Exist for Contract

December 1, 2020

Contract Total Pay For	Estimate No. 11				
		This Estimate	Previous	To Date	
200117-H06					
	Total Posted Items Pay	\$64,000.00	\$1,707,471.56	\$1,771,471.56	
	Gross Item Adjustments	(\$32,700.00)	\$65,573.11	\$32,873.11	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
			\$1,773,044.67	\$1,804,344.67	
Contract Total Payable	This Estimate:	\$31,300.00			

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J9S3279	1720	6063017	TYPE C CRASHWORTHY END TERMINAL	EA	\$16,000.000	4	\$64,000.00
Project J9S3279	- Total						\$64,000.00
Overall - Total							\$64,000.00

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Project umber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
S3263	0160	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-1,000	\$1.20	(\$1,200.00
	0160	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	1,000	\$1.20	\$1,200.00
	0170	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-621	\$1.20	(\$745.20
	0170	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	621	\$1.20	\$745.20
	0420	SAFETY BARRIER CURB	Material			-135	\$120.00	(\$16,200.00
	0420	SAFETY BARRIER CURB	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 32 on the current Payment Estimate.	135	\$120.00	\$16,200.00
	0430	SLAB ON CONCRETE BEAM	Material			-156	\$390.00	(\$60,840.00
	0430	SLAB ON CONCRETE BEAM	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0006) due to user leez1	156	\$390.00	\$60,840.00

Revision 4/1/2020 Page 1 of 36



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 17, 2020

Progress Estimate Number
11 Contract ID 200117-H06 Pay Period Start August 2, 2020 Original Contract Amount \$1,994,330.06 Pay Period End August 15, 2020 Original Contract Amount \$30,189.20 Current Contract Amount \$2,024,519.26

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9S3263					overridding Payment Estimate Exception 35 on the current Payment Estimate.			
J9S3264	0640	Type Adjustment Type Overridding Payment Estimate Exception 35 on the current Payment Estimate Payment	\$1.20	(\$1,256.40)				
	0640	WATERBORNE PAVEMENT MARKING PAINT, TYPE P	Material		generated Overrun Payment Estimate Item Adjustment (0015) due to user leez1 overridding Payment Estimate Exception 2 on	1,047	\$1.20	\$1,256.40
	0650	WATERBORNE PAVEMENT MARKING PAINT, TYPE P	Material			-482	\$1.20	(\$578.40)
	0650	WATERBORNE PAVEMENT MARKING PAINT, TYPE P	Material		generated Overrun Payment Estimate Item Adjustment (0016) due to user leez1 overridding Payment Estimate Exception 8 on	482	\$1.20	\$578.40
	0870		Material			-153	\$425.00	(\$65,025.00)
	0870		Material		generated Overrun Payment Estimate Item Adjustment (0009) due to user leez1 overridding Payment Estimate Exception 18	153	\$425.00	\$65,025.00
	0880	SAFETY BARRIER CURB	Material			-151	\$120.00	(\$18,120.00)
	0880	SAFETY BARRIER CURB	Material		generated Overrun Payment Estimate Item Adjustment (0010) due to user leez1 overridding Payment Estimate Exception 27	151	\$120.00	\$18,120.00
J9S3278	1280	PLACE CONCRETE PILES	Material			-420	\$98.00	(\$41,160.00)
	1280	PLACE CONCRETE PILES	Material		generated Overrun Payment Estimate Item Adjustment (0013) due to user leez1 overridding Payment Estimate Exception 13	420	\$98.00	\$41,160.00
	1300		Material			-24.4	\$1,000.00	(\$24,400.00
	1300		Material		generated Overrun Payment Estimate Item Adjustment (0014) due to user leez1 overridding Payment Estimate Exception 17	24.4	\$1,000.00	\$24,400.00
	1310	SAFETY BARRIER CURB	Material			-140	\$120.00	(\$16,800.00)
	1310	SAFETY BARRIER CURB	Material		generated Overrun Payment Estimate Item Adjustment (0007) due to user leez1 overridding Payment Estimate Exception 33	140	\$120.00	\$16,800.00
	1320	SLAB ON CONCRETE BEAM	Material			-156	\$400.00	(\$62,400.00)
	1320	SLAB ON CONCRETE BEAM	Material		generated Overrun Payment Estimate Item Adjustment (0008) due to user leez1 overridding Payment Estimate Exception 36	156	\$400.00	\$62,400.00

Revision 4/1/2020 Page 2 of 36



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 17, 2020

Progress Estimate Number
11 Contract ID 200117-H06 Prime Contractor Joe's Bridge & Grading, Inc.

Pay Period Start August 2, 2020 Original Contract Amount August 15, 2020 Original Contract Amount S1,994,330.06 Pay Period End August 15, 2020 Current Contract Amount S2,024,519.26

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9S3279	1620	24 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION	Material			-2	\$350.00	(\$700.00)
	1620	24 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0019) due to user leez1 overridding Payment Estimate Exception 43 on the current Payment Estimate.	2	\$350.00	\$700.00
	1720	TYPE C CRASHWORTHY END TERMINAL	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$32,700.00)
	1720	TYPE C CRASHWORTHY END TERMINAL	Material			-4	\$16,000.00	(\$64,000.00)
	1720	TYPE C CRASHWORTHY END TERMINAL	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	4	\$16,000.00	\$64,000.00
	1760	GALVANIZED CAST-IN- PLACE CONCRETE PILES (14 IN)	Material			-505	\$75.00	(\$37,875.00)
	1760	GALVANIZED CAST-IN- PLACE CONCRETE PILES (14 IN)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0017) due to user leez1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	505	\$75.00	\$37,875.00
	1790	CLASS B CONCRETE (SUBSTRUCTURE)	Material			-24.1	\$1,000.00	(\$24,100.00)
	1790	CLASS B CONCRETE (SUBSTRUCTURE)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0018) due to user leez1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	24.1	\$1,000.00	\$24,100.00
	1800	SLAB ON CONCRETE I- GIRDER	Material			-170	\$400.00	(\$68,000.00)
	1800	SLAB ON CONCRETE I- GIRDER	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0011) due to user leez1 overridding Payment Estimate Exception 19 on the current Payment Estimate.	170	\$400.00	\$68,000.00
	1810	SAFETY BARRIER CURB	Material			-153	\$120.00	(\$18,360.00)
	1810	SAFETY BARRIER CURB	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0012) due to user leez1 overridding Payment Estimate Exception 28 on the current Payment Estimate.	153	\$120.00	\$18,360.00
Total								(\$32,700.00)

Revision 4/1/2020 Page 3 of 36



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					C	Contract Project Information	on
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J9S3263	Proj. Description						
J9S3264			91	STODDARD	3 Miles East of Bell City	r, MO	
J9S3278			91	SCOTT	from 0.04 miles west of	Rte CC/91 intersection	
J9S3279			91	SCOTT	fom 1.8 miles west of R	te CC/91 intersection	
Γotals by .	Job Numbe	ers					
J9S3263					This Estimate	Provious	To Date
5500200	Poste	ed Item Pay					
			Gros	s Item Pay	\$0.00	\$459,843.77	\$459,843.77
	Incen	itive			\$0.00	\$0.00	\$0.00
	Other	r Contract Adji	ustments	8	\$0.00	\$0.00	\$0.00
J9S3264					This Estimate	Previous	To Date
	Poste	ed Item Pay					
	Gross	s Item Adjustn					
			Gros	s Item Pay	\$0.00	\$486,540.15	\$486,540.15
	Incen	itive			\$0.00	\$0.00	\$0.00
	Liqui	dated Damage			\$0.00	\$0.00	\$0.00
	Other	r Contract Adj	ustments	S	\$0.00	\$0.00	\$0.00
J9S3278					This Estimate	Provious	To Date
0000210	Poste	ed Item Pav					
			nents				
				s Item Pay			
	Incon	ntivo			00.00	90.00	00.02
			s				
				s			
J9S3279					This Fallows	Dd	T. D.4.
1953279	Docto	d Itom Boy					
			nents				
	0.00			s Item Pay			
				-	· · ·	,	· '
			s				
				s			
	C.7101	- Januar Auj		-	ψο.οο	+0.00	ψ0.00

Revision 4/1/2020 Page 4 of 36



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			1
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J9S3279, Item 6063017, Project Item Line Number 1720, Material Set 606301796, Material 1040GRCWC - Crashworthy End Terminal Type C, Acceptance Action Generic 1040GRCWC is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3264, Item 6206000C, Project Item Line Number 0640, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3264, Item 6206000C, Project Item Line Number 0640, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3263, Item 6206000C, Project Item Line Number 0160, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3263, Item 6206000C, Project Item Line Number 0160, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3263, Item 6206001C, Project Item Line Number 0170, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3263, Item 6206001C, Project Item Line Number 0170, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3264, Item 6206001C, Project Item Line Number 0650, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3264, Item 6206001C, Project Item Line Number 0650, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3279, Item 7021314, Project Item Line Number 1760, Material Set 702131496, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3279, Item 7021314, Project Item Line Number 1760, Material Set 702131496, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3279, Item 7021314, Project Item Line Number 1760, Material Set 702131496, Material 0501CCB1 - Concrete, Class B-1 No Air, Acceptance Action Generic 0501CCB1 is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3278, Item 7021314, Project Item Line Number 1280, Material Set 702131496, Material 0501CCB1 - Concrete, Class B-1 No Air, Acceptance Action Generic 0501CCB1 is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3279, Item 7032003, Project Item Line Number 1790, Material Set 703200396, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3279, Item 7032003, Project Item Line Number 1790, Material Set 703200396, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3279, Item 7032003, Project Item Line Number 1790, Material Set 703200396, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3278, Item 7032003, Project Item Line Number 1300, Material Set 703200396, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3264, Item 7034213, Project Item Line Number 0870, Material Set 703421396, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3279, Item 7034213, Project Item Line Number 1800, Material Set 703421396, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3279, Item 7034213, Project Item Line Number 1800, Material Set 703421396, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3279, Item 7034213, Project Item Line Number 1800, Material Set 703421396, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3279, Item 7034213, Project Item Line Number 1800, Material Set 703421396, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3279, Item 7034213, Project Item Line Number 1800, Material Set 703421396, Material 1036RSDFEC42M22 - Rein Steel EC No. 7/M22 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3279, Item 7034213, Project Item Line Number 1800, Material Set 703421396, Material 1036RSDFPL42M13 - Reinforcing Steel No. 4/M13 Gr 60/M420	No Remark was entered by Engineer	leez1	Overridden

Revision 4/1/2020 Page 5 of 36



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			1
Exceptions / Discrepencies	Explanation	Entered By	Status
@, Acceptance Action Generic ReSteelBars is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J9S3279, Item 7034213, Project Item Line Number 1800, Material Set 703421396, Material 1036RSDFPL42M19 - Reinforcing Steel No. 6/M19 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3279, Item 7034213, Project Item Line Number 1800, Material Set 703421396, Material 1036RSDFPL42M25 - Reinforcing Steel No. 8/M25 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3264, Item 7034215, Project Item Line Number 0880, Material Set 703421596, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3279, Item 7034215, Project Item Line Number 1810, Material Set 703421596, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3279, Item 7034215, Project Item Line Number 1810, Material Set 703421596, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3279, Item 7034215, Project Item Line Number 1810, Material Set 703421596, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3279, Item 7034215, Project Item Line Number 1810, Material Set 703421596, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3263, Item 7034215, Project Item Line Number 0420, Material Set 703421596, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3278, Item 7034215, Project Item Line Number 1310, Material Set 703421596, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3278, Item 7034215, Project Item Line Number 1310, Material Set 703421596, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3263, Item 7034222, Project Item Line Number 0430, Material Set 703422296, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3278, Item 7034222, Project Item Line Number 1320, Material Set 703422296, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3278, Item 7034222, Project Item Line Number 1320, Material Set 703422296, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3278, Item 7034222, Project Item Line Number 1320, Material Set 703422296, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3278, Item 7034222, Project Item Line Number 1320, Material Set 703422296, Material 1036RSDFEC42M22 - Rein Steel EC No. 7/M22 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3278, Item 7034222, Project Item Line Number 1320, Material Set 703422296, Material 1036RSDFPL42M13 - Reinforcing Steel No. 4/M13 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3278, Item 7034222, Project Item Line Number 1320, Material Set 703422296, Material 1036RSDFPL42M19 - Reinforcing Steel No. 6/M19 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3278, Item 7034222, Project Item Line Number 1320, Material Set 703422296, Material 1036RSDFPL42M25 - Reinforcing Steel No. 8/M25 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3279, Item 7320824A, Project Item Line Number 1620, Material Set 7320824A96, Material 1020ESZN - Flared End Section Zinc galvanized steel, Acceptance Action Generic PipeDrainageMisc is insufficient.	No Remark was entered by Engineer	leez1	Overridden

Revision 4/1/2020 Page 6 of 36



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	eport Generated date and can differ from the posted amo Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved	Unit Price	Total Value POSTED To Date (See report generated date)
200117-H06	J9S3263	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	Qty 1.00	\$4,000.00	\$4,000.00
		0001	0020	2064000	POROUS BACKFILL	54.00	0.00	54.00	CUYD	54.00	\$68.00	\$3,672.00
		0001	0030	2079909	MISC.MODIFIED LINEAR GRADING, CLASS 2	1.70	0.00	1.70	STA	1.70	\$2,400.00	\$4,080.00
		0001	0040	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	195.00	0.00	195.00	SQYD	195.00	\$14.00	\$2,730.00
		0001	0050	3105002	GRAVEL (A) OR CRUSHED STONE (B)	84.00	0.00	84.00	TONS	84.00	\$25.00	\$2,100.00
		0001	0060	4019905	MISC.OPTIONAL PAVEMENT	194.80	0.00	194.80	SQYD	194.80	\$59.45	\$11,580.86
		0001	0070	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	1,224.00	0.00	1,224.00	CUYD	125.00	\$20.00	\$2,500.00
		0001	0080	6096041	PLACING TYPE 1 ROCK DITCH LINER	1,224.00	0.00	1,224.00	CUYD	125.00	\$36.00	\$4,500.00
		0001	0090	6113020	FURNISHING TYPE 2 ROCK BLANKET	289.00	0.00	289.00	CUYD	289.00	\$20.00	\$5,780.00
		0001	0100	6113040	PLACING TYPE 2 ROCK BLANKET	289.00	0.00	289.00	CUYD	289.00	\$30.00	\$8,670.00
		0001	0110	6161005	CONSTRUCTION SIGNS	676.00	0.00	676.00	SQFT	676.00	\$4.00	\$2,704.00
		0001	0120	6161008	ADVANCED WARNING RAIL SYSTEM	4.00	0.00	4.00	EA	4.00	\$35.00	\$140.00
		0001	0130	6161009	FLAG ASSEMBLY	2.00	0.00	2.00	EA	2.00	\$20.00	\$40.00
		0001	0140	6161030	TYPE III MOVEABLE BARRICADE	10.00	0.00	10.00	EA	10.00	\$125.00	\$1,250.00
		0001	0150	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$70,000.00	\$0.00
		0001	0151	6181000	MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$58,034.00	\$58,034.00
		0001	0160	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,000.00	0.00	1,000.00	LF	1,000.00	\$1.20	\$1,200.00
		0001	0170	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	528.00	93.00	621.00	LF	621.00	\$1.20	\$745.20
		0001	0180	6207001	PAVEMENT MARKING REMOVAL	2,800.00	0.00	2,800.00	LF	2,800.00	\$0.50	\$1,400.00
		0001	0190	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	433.00	0.00	433.00	SQYD	433.00	\$3.00	\$1,299.00
		0001	0200	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$6,000.00	\$6,000.00
		0001	0210	7250418	18 IN. PIPE GROUP C	102.00	0.00	102.00	LF	102.00	\$35.00	\$3,570.00
		0001	0220	7250430	30 IN. PIPE GROUP C	72.00	0.00	72.00	LF	72.00	\$45.00	\$3,240.00
		0001	0230	7250448	48 IN. PIPE GROUP C	91.00	0.00	91.00	LF	91.00	\$67.00	\$6,097.00
		0001	0240	7259902	MISC.FLAP GATE 18"	1.00	0.00	1.00	EA	1.00	\$800.00	\$800.00
		0001	0250	7259902	MISC.FLAP GATE 48"	1.00	0.00	1.00	EA	1.00	\$1,500.00	\$1,500.00
		0001	0260	7320818A	18 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION	1.00	0.00	1.00	EA	1.00	\$285.00	\$285.00
		0001	0270	7320830A	30 IN, OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION	2.00	0.00	2.00	EA	2.00	\$575.00	\$1,150.00
		0001	0280	7320848A	48 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION	1.00	0.00	1.00	EA	1.00	\$1,575.00	\$1,575.00
		0001	0290	8051000A	SEEDING - COOL SEASON MIXTURES	1.00	0.00	1.00	ACRE	0.10	\$3,400.00	\$340.00
		0001	0300	8061005	ROCK DITCH CHECK	48.00	-48.00	0.00	LF	0.00	\$22.50	\$0.00
		0001	0310	8061016	SEDIMENT REMOVAL	4.00	-4.00	0.00	CUYD	0.00	\$5.00	\$0.00
		0001	0320	8061019	SILT FENCE	419.00	-419.00	0.00	LF	0.00	\$3.50	\$0.00
		0001	0330	8061050	TYPE C BERM	168.00	0.00	168.00	LF	168.00	\$10.00	\$1,680.00
		0010	0340	6063017	TYPE C CRASHWORTHY END TERMINAL	4.00	0.00	4.00	EA	4.00	\$16,000.00	\$64,000.00
		0070	0350	2061000	CLASS 1 EXCAVATION	60.00	0.00	60.00	CUYD	60.00	\$25.00	\$1,500.00
		0070	0360	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$30,000.00	\$30,000.00
		0070	0370	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	110.00	0.00	110.00	SQYD	110.00	\$77.00	\$8,470.00
		0070	0380	7021314	GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN)	216.00	72.00	288.00	LF	288.00	\$90.00	\$25,920.00
		0070	0390	7025001	DYNAMIC PILE TESTING	2.00	0.00	2.00	EA	2.00	\$3,750.00	\$7,500.00
		0070	0400	7027000	PILE POINT REINFORCEMENT	8.00	2.00	10.00	EA	10.00	\$575.00	\$5,750.00
		0070	0410	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	22.40	0.00	22.40	CUYD	22.40	\$1,000.00	\$22,400.00
		0070	0420	7034215	SAFETY BARRIER CURB	135.00	0.00	135.00	LF	135.00	\$120.00	\$16,200.00
		0070	0430	7034222	SLAB ON CONCRETE BEAM	156.00	0.00	156.00	SQYD	156.00	\$390.00	\$60,840.00

Revision 4/1/2020 Page 7 of 36



Total Paid / All Items / All Estimates (Including this Estimate)

Contract n.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTI To Date (See repo generated date)
)117-H06	J9S3263	0070	0440	7056049	21 IN., PRESTRESSED CONCRETE SPREAD BOX BEAM	152.00	0.00	152.00	LF	152.00	\$325.00	\$49,400.
		0070	0450	7123610	SLAB DRAIN	10.00	0.00	10.00	EA	10.00	\$285.00	\$2,850.
		0070	0460	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	2.00	\$1,200.00	\$2,400
		0070	0470	7161000	PLAIN NEOPRENE BEARING PAD	6.00	0.00	6.00	EA	6.00	\$150.00	\$900
		0001	5001	6189901	MISC.Contract Bond Payment	0.00	1.00	1.00	LS	1.00	\$11,966.00	\$11,966.
		0070	5002	7025004	DYNAMIC PILE RESTRIKE TESTING	0.00	2.00	2.00	EA	2.00	\$3,500.00	\$7,000
	Project J	9S3263 - To	otal Value	Posted to D	ate as of Report Generated Date							\$459,758
	J9S3264	0001	0480	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$4,000.00	\$4,000
		0001	0490	2064000	POROUS BACKFILL	71.00	0.00	71.00	CUYD	71.00	\$68.00	\$4,82
		0001	0500	2079909	MISC. MODIFIED LINEAR GRADING CLASS 2	2.80	0.00	2.80	STA	2.80	\$2,400.00	\$6,720
		0001	0510	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	221.00	0.00	221.00	SQYD	221.00	\$14.00	\$3,09
		0001	0520	3105002	GRAVEL (A) OR CRUSHED STONE (B)	6.00	0.00	6.00	TONS	6.00	\$30.00	\$180
		0001	0530	4019905	MISC.OPTIONAL PAVEMENT	221.00	0.00	221.00	SQYD	221.00	\$59.45	\$13,138
		0001	0540	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	67.00	0.00	67.00	CUYD	67.00	\$28.00	\$1,876
		0001	0550	6096041	PLACING TYPE 1 ROCK DITCH LINER	67.00	0.00	67.00	CUYD	67.00	\$30.00	\$2,01
		0001	0560	6113020	FURNISHING TYPE 2 ROCK BLANKET	470.00	0.00	470.00	CUYD	470.00	\$20.00	\$9,40
		0001	0570	6113040	PLACING TYPE 2 ROCK BLANKET	470.00	0.00	470.00	CUYD	470.00	\$30.00	\$14,10
		0001	0580	6161005	CONSTRUCTION SIGNS	621.00	0.00	621.00	SQFT	621.00	\$4.00	\$2,48
		0001	0590	6161008	ADVANCED WARNING RAIL SYSTEM	4.00	0.00	4.00	EA	4.00	\$35.00	\$14
		0001	0600	6161009	FLAG ASSEMBLY	4.00	0.00	4.00	EA	4.00	\$20.00	\$8
		0001	0610	6161030	TYPE III MOVEABLE BARRICADE	10.00	0.00	10.00	EA	10.00	\$125.00	\$1,25
		0001	0620	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$2,800.00	\$5,60
		0001	0630	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$70,000.00	\$
		0001	0631	6181000	MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$58,034.00	\$58,03
		0001	0640	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,014.00	33.00	1,047.00	LF	1,047.00	\$1.20	\$1,25
		0001	0650	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	482.00	0.00	482.00	LF	482.00	\$1.20	\$57
		0001	0660	6207001	PAVEMENT MARKING REMOVAL	3,441.00	0.00	3,441.00	LF	3,441.00	\$0.50	\$1,72
		0001	0670	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	662.00	0.00	662.00	SQYD	662.00	\$3.00	\$1,98
		0001	0680	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$6,000.00	\$6,00
		0001	0690	7250418	18 IN. PIPE GROUP C	97.00	0.00	97.00	LF	97.00	\$35.00	\$3,39
		0001	0700	7250424	24 IN. PIPE GROUP C	35.00	0.00	35.00	LF	35.00	\$42.00	\$1,47
		0001	0710	7250430	30 IN. PIPE GROUP C	130.00	0.00	130.00	LF	130.00	\$48.00	\$6,24
		0001	0720	7320818A	18 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION	1.00	0.00	1.00	EA	1.00	\$285.00	\$28
		0001	0730	7320824A	24 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION	1.00	0.00	1.00	EA	1.00	\$385.00	\$38
		0001	0740	7320830A	30 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION	2.00	0.00	2.00	EA	2.00	\$575.00	\$1,15
		0001	0750	8051000A	SEEDING - COOL SEASON MIXTURES	1.00	0.00	1.00	ACRE	0.06	\$3,400.00	\$18
		0001	0760	8061005	ROCK DITCH CHECK	40.00	-40.00	0.00	LF	0.00	\$22.50	\$
		0001	0770	8061016	SEDIMENT REMOVAL	9.00	-9.00	0.00	CUYD	0.00	\$5.00	\$
		0001	0780	8061019	SILT FENCE	505.00	-505.00	0.00	LF	0.00	\$3.50	\$
		0001	0790	8061050	TYPE C BERM	245.00	0.00	245.00	LF	245.00	\$10.00	\$2,45
		0010	0800	6063017	TYPE C CRASHWORTHY END TERMINAL	4.00	0.00	4.00	EA	4.00	\$16,000.00	\$64,00
		0070	0810	2061000	CLASS 1 EXCAVATION	80.00	0.00	80.00	CUYD	80.00	\$25.00	\$2,00
		0070	0820	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$30,000.00	\$30,00
		0070	0830	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	112.00	0.00	112.00	SQYD	112.00	\$77.00	\$8,62

Revision 4/1/2020 Page 8 of 36



Total Paid / All Items / All Estimates (Including this Estimate)

Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
117-H06	J9S3264	0070	0840	7021314	GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN)	400.00	0.00	400.00	LF	400.00	\$98.00	\$39,200.0
		0070	0850	7025001	DYNAMIC PILE TESTING	2.00	0.00	2.00	EA	2.00	\$3,750.00	\$7,500.0
		0070	0860	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	41.60	0.00	41.60	CUYD	41.60	\$1,000.00	\$41,600.0
		0070	0870	7034213	SLAB ON CONCRETE I-GIRDER	153.00	0.00	153.00	SQYD	153.00	\$425.00	\$65,025.0
		0070	0880	7034215	SAFETY BARRIER CURB	151.00	0.00	151.00	LF	151.00	\$120.00	\$18,120.0
		0070	0890	7056000	TYPE 2 (32 IN.), PRESTRESSED CONCRETE I-GIRDER	150.00	0.00	150.00	LF	150.00	\$240.00	\$36,000.0
		0070	0900	7123610	SLAB DRAIN	8.00	0.00	8.00	EA	8.00	\$310.00	\$2,480.0
		0070	0910	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	2.00	\$1,500.00	\$3,000.0
		0070	0920	7161000	PLAIN NEOPRENE BEARING PAD	6.00	0.00	6.00	EA	6.00	\$150.00	\$900.0
		0001	5101	6189901	MISC.Contract Bond Payment	0.00	1.00	1.00	LS	1.00	\$11,966.00	\$11,966.0
		0001	5102	7329902	MISC.FLAP GATE FOR 30in. PIPE	0.00	2.00	2.00	EA	2.00	\$1,000.00	\$2,000.0
	Project J9	S3264 - To	tal Value	Posted to D	ate as of Report Generated Date							\$486,452.7
	J9S3278	0001	0930	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$4,000.00	\$4,000.0
		0001	0940	2064000	POROUS BACKFILL	54.00	0.00	54.00	CUYD	54.00	\$68.00	\$3,672.0
		0001	0950	2079909	MISC.MODIFIED LINEAR GRADING, CLASS 2	3.60	0.00	3.60	STA	0.00	\$2,400.00	\$0.0
		0001	0960	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	1,308.00	0.00	1,308.00	SQYD	0.00	\$14.00	\$0.0
		0001	0965	3049905	MISC.RIGID GEOGRID TO ENHANCE AGGREGATE	654.00	0.00	654.00	SQYD	0.00	\$3.00	\$0.0
		0001	0970	4019905	MISC.OPTIONAL PAVEMENT	654.00	0.00	654.00	SQYD	0.00	\$57.90	\$0.0
		0001	0980	6057000	AGGREGATE DRAIN	31.00	0.00	31.00	LF	0.00	\$25.00	\$0.0
		0001	0990	6113020	FURNISHING TYPE 2 ROCK BLANKET	364.00	0.00	364.00	CUYD	364.00	\$20.00	\$7,280.0
		0001	1000	6113040	PLACING TYPE 2 ROCK BLANKET	364.00	0.00	364.00	CUYD	364.00	\$30.00	\$10,920.0
		0001	1010	6161005	CONSTRUCTION SIGNS	656.00	39.00	695.00	SQFT	695.00	\$4.00	\$2,780.0
		0001	1020	6161008	ADVANCED WARNING RAIL SYSTEM	4.00	0.00	4.00	EA	4.00	\$35.00	\$140.0
		0001	1030	6161009	FLAG ASSEMBLY	4.00	0.00	4.00	EA	4.00	\$20.00	\$80.0
		0001	1040	6161030	TYPE III MOVEABLE BARRICADE	8.00	0.00	8.00	EA	8.00	\$125.00	\$1,000.0
		0001	1050	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$75,000.00	\$0.0
		0001	1051	6181000	MOBILIZATION	0.00	1.00	1.00	LS	0.75	\$63,034.00	\$47,275.5
		0001	1060	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	949.00	0.00	949.00	LF	0.00	\$1.20	\$0.0
		0001	1070	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	558.00	0.00	558.00	LF	0.00	\$1.20	\$0.0
		0001	1080	6207001	PAVEMENT MARKING REMOVAL	2,652.00	0.00	2,652.00	LF	0.00	\$0.50	\$0.0
		0001	1100	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	546.00	0.00	546.00	SQYD	546.00	\$3.00	\$1,638.0
		0001	1110	6240104A	SEPARATION GEOTEXTILE	714.00	0.00	714.00	SQYD	0.00	\$3.00	\$0.0
		0001	1120	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$6,000.00	\$6,000.0
		0001	1130	7250415	15 IN. PIPE GROUP C	60.00	0.00	60.00	LF	60.00	\$32.00	\$1,920.0
		0001	1140	7250424	24 IN. PIPE GROUP C	80.00	0.00	80.00	LF	80.00	\$42.00	\$3,360.0
		0001	1150	7259902	MISC.FLAP GATE FOR 15 IN. PIPE	1.00	0.00	1.00	EA	1.00	\$750.00	\$750.0
		0001	1160	7259902	MISC.FLAP GATE FOR 24 IN. PIPE	1.00	0.00	1.00	EA	1.00	\$800.00	\$800.0
		0001	1170	7320815A	15 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END	1.00	0.00	1.00	EA	1.00	\$250.00	\$250.0
		0001	1180	7320824A	SECTION 24 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END	1.00	0.00	1.00	EA	1.00	\$350.00	\$350.0
		0001	1190	8051000A	SECTION SEEDING - COOL SEASON MIXTURES	1.00	0.00	1.00	ACRE	0.00	\$3,400.00	\$0.0
		0001	1200	8061005	ROCK DITCH CHECK	96.00	0.00	96.00	LF	0.00	\$22.50	\$0.0
		0001	1210	8061016	SEDIMENT REMOVAL	30.00	0.00	30.00	CUYD	0.00	\$5.00	\$0.0
		0001	1220	8061019	SILT FENCE	330.00	0.00	330.00	LF	0.00	\$4.50	\$0.0
		0001	1230	8061050	TYPE C BERM	232.00	0.00	232.00	LF	0.00	\$10.00	\$0.0
		0001	.200	3331000	= 3 55	202.00	0.00	202.00		0.00	ψ10.00	Ψ0.0

Revision 4/1/2020 Page 9 of 36



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Im.CONTRACT	Quantities and Values are based on Report Generated date and can differ from the Project Category Line Item No. Code Description					Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved	Unit Price	Total Value POSTE To Date (See report generated date)
00117-H06	J9S3278	0070	1250	2061000	CLASS 1 EXCAVATION	70.00	0.00	70.00	CUYD	Qty 70.00	\$25.00	\$1,750.0
00117-1100	0300270	0070	1260	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$30,000.00	\$30.000.0
		0070	1270	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	110.00	0.00	110.00	SQYD	0.00	\$77.00	\$0.0
		0070	1280	7021314	GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN)	420.00	0.00	420.00	LF	420.00	\$98.00	\$41,160.0
		0070	1290	7025001	DYNAMIC PILE TESTING	2.00	0.00	2.00	EA	2.00	\$3,750.00	\$7,500.0
		0070	1300	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	24.40	0.00	24.40	CUYD	24.40	\$1,000.00	\$24,400.0
		0070	1310	7034215	SAFETY BARRIER CURB	140.00	0.00	140.00	LF	140.00	\$120.00	\$16,800.0
			1320	7034213	SLAB ON CONCRETE BEAM	156.00	0.00	156.00	SQYD	156.00	\$400.00	\$62,400.
		0070	1330	7056049	21 IN., PRESTRESSED CONCRETE SPREAD BOX BEAM	152.00	0.00	152.00	LF	152.00	\$325.00	\$49,400.
		0070										
		0070	1340	7123610	SLAB DRAIN	10.00	0.00	10.00	EA	10.00	\$285.00	\$2,850
		0070	1350	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	2.00	\$1,500.00	\$3,000
		0070	1360	7161000	PLAIN NEOPRENE BEARING PAD	6.00	0.00	6.00	EA	6.00	\$150.00	\$900
		0001	5201	6189901	MISC.Contract Bond Payment	0.00	1.00	1.00	LS	1.00	\$11,966.00	\$11,966
	Project J9 J9S3279	9S3278 - To	tal Value	2022010	ate as of Report Generated Date REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$4,000.00	\$344,341 \$4,000
	0000270	0001	1380	2063000	CLASS 3 EXCAVATION	45.00	0.00	45.00	CUYD	45.00	\$25.00	\$1,125
		0001	1390	2064000	POROUS BACKFILL	52.00	0.00	52.00	CUYD	52.00	\$68.00	\$3,536
			1400	2079909	MISC.Mod. Linear Grading Class 2	1.80	0.00	1.80	STA	1.80	\$2,400.00	\$4,320
		0001		3040506	<u> </u>							
		0001	1410		TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	205.00	0.00	205.00	SQYD	205.00	\$14.00	\$2,870
		0001	1420	3105002	GRAVEL (A) OR CRUSHED STONE (B)	9.00	0.00	9.00	TONS	9.00	\$30.00	\$270
		0001	1430	5029905	MISC.Optional Pavement	205.00	0.00	205.00	SQYD	205.00	\$59.45	\$12,187
		0001	1440	6044012	PIPE COLLAR, TYPE B	2.00	0.00	2.00	EA	2.00	\$1,000.00	\$2,000
		0001	1450	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	11.00	0.00	11.00	CUYD	11.00	\$20.00	\$220
		0001	1460	6096041	PLACING TYPE 1 ROCK DITCH LINER	11.00	0.00	11.00	CUYD	11.00	\$30.00	\$330
		0001	1470	6113020	FURNISHING TYPE 2 ROCK BLANKET	332.00	0.00	332.00	CUYD	332.00	\$20.00	\$6,640
		0001	1480	6113040	PLACING TYPE 2 ROCK BLANKET	332.00	0.00	332.00	CUYD	332.00	\$30.00	\$9,960
		0001	1490	6161005	CONSTRUCTION SIGNS	706.00	0.00	706.00	SQFT	706.00	\$5.50	\$3,883
		0001	1500	6161008	ADVANCED WARNING RAIL SYSTEM	4.00	0.00	4.00	EA	4.00	\$35.00	\$140
		0001	1510	6161009	FLAG ASSEMBLY	4.00	0.00	4.00	EA	4.00	\$20.00	\$80
		0001	1520	6161030	TYPE III MOVEABLE BARRICADE	10.00	0.00	10.00	EA	10.00	\$125.00	\$1,250
		0001	1530	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$2,800.00	\$5,600
		0001	1540	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$70,000.00	\$0
		0001	1541	6181000	MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$58,034.00	\$58,034
		0001	1550	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,852.00	0.00	1,852.00	LF	0.00	\$1.10	\$0
		0001	1560	6206001C	4 IN, YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	560.00	0.00	560.00	LF	0.00	\$1.10	\$0
		0001	1570	6207001	PAVEMENT MARKING REMOVAL	4,094.00	0.00	4,094.00	LF	0.00	\$0.50	\$0
		0001	1580	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	498.00	0.00	498.00	SQYD	498.00	\$3.00	\$1,494
		0001	1590	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$6,000.00	\$6,000
		0001	1600	7250424	24 IN. PIPE GROUP C	111.00	0.00	111.00	LF	111.00	\$35.00	\$3,885
		0001	1610	7250430	30 IN. PIPE GROUP C	182.00	-182.00	0.00	LF	0.00	\$48.00	\$0
		0001	1620	7320824A	24 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION	2.00	0.00	2.00	EA	2.00	\$350.00	\$700
		0001	1630	7320830A	30 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION	2.00	-2.00	0.00	EA	0.00	\$550.00	\$0
		0001	1640	7329902	MISC.FLAP GATE FOR 24in. PIPE	1.00	0.00	1.00	EA	1.00	\$800.00	\$800
		0001	1650	7329902	MISC.FLAP GATE FOR 36in. PIPE	2.00	0.00	2.00	EA	2.00	\$1,075.00	\$2,150

Page 10 of 36 Revision 4/1/2020



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200117-H06	J9S3279	0001	1660	8051000A	SEEDING - COOL SEASON MIXTURES	1.00	0.00	1.00	ACRE	0.00	\$3,400.00	\$0.00
		0001	1670	8061005	ROCK DITCH CHECK	48.00	0.00	48.00	LF	0.00	\$22.50	\$0.00
		0001	1680	8061016	SEDIMENT REMOVAL	7.00	0.00	7.00	CUYD	0.00	\$5.00	\$0.00
		0001	1690	8061019	SILT FENCE	234.00	0.00	234.00	LF	0.00	\$4.50	\$0.00
		0001	1700	8061050	TYPE C BERM	277.00	0.00	277.00	LF	0.00	\$10.00	\$0.00
		0001	1710	8064140	TYPE 3B EROSION CONTROL BLANKET	539.00	0.00	539.00	SQYD	0.00	\$3.00	\$0.00
		0010	1720	6063017	TYPE C CRASHWORTHY END TERMINAL	4.00	0.00	4.00	EA	4.00	\$16,000.00	\$64,000.00
		0070	1730	2061000	CLASS 1 EXCAVATION	75.00	0.00	75.00	CUYD	75.00	\$25.00	\$1,875.00
		0070	1740	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$30,000.00	\$30,000.00
		0070	1750	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	107.00	0.00	107.00	SQYD	107.00	\$77.00	\$8,239.00
		0070	1760	7021314	GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN)	280.00	225.00	505.00	LF	505.00	\$75.00	\$37,875.00
		0070	1770	7025001	DYNAMIC PILE TESTING	2.00	0.00	2.00	EA	2.00	\$3,750.00	\$7,500.00
		0070	1780	7027000	PILE POINT REINFORCEMENT	10.00	0.00	10.00	EA	10.00	\$560.00	\$5,600.00
		0070	1790	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	24.10	0.00	24.10	CUYD	24.10	\$1,000.00	\$24,100.00
		0070	1800	7034213	SLAB ON CONCRETE I-GIRDER	170.00	0.00	170.00	SQYD	170.00	\$400.00	\$68,000.00
		0070	1810	7034215	SAFETY BARRIER CURB	153.00	0.00	153.00	LF	153.00	\$120.00	\$18,360.00
		0070	1820	7056000	TYPE 2 (32 IN.), PRESTRESSED CONCRETE I-GIRDER	223.00	0.00	223.00	LF	223.00	\$231.00	\$51,513.00
		0070	1830	7123301	STEEL INTERMEDIATE DIAPHRAGM FOR P/S CONCRETE GIRDERS	3.00	0.00	3.00	EA	3.00	\$575.00	\$1,725.00
		0070	1840	7123610	SLAB DRAIN	10.00	0.00	10.00	EA	10.00	\$300.00	\$3,000.00
		0070	1850	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	2.00	\$1,500.00	\$3,000.00
		0070	1860	7161000	PLAIN NEOPRENE BEARING PAD	8.00	0.00	8.00	EA	8.00	\$150.00	\$1,200.00
		0001	5301	6189901	MISC.Contract Bond Payment	0.00	1.00	1.00	LS	1.00	\$11,966.00	\$11,966.00
		0001	5302	7250436	36 IN. PIPE GROUP C	0.00	182.00	182.00	LF	182.00	\$56.00	\$10,192.00
		0001	5303	7320836A	36 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION	0.00	2.00	2.00	EA	2.00	\$650.00	\$1,300.00
	Project J	9S3279 - To	otal Value	Posted to D	late as of Report Generated Date							\$480,919.25
200117-H06 Ove	erall - Total	Value Pos	ted to Da	te as of Repo	ort Generated Date							\$1,771,471.56

Page 11 of 36 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J9S3279

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
1720	6063017	TYPE C CRASHWORTHY END TERMINAL	8/3/20	8/17/20	4.00	EA	Bridge A8772 MO 91	12+29.50	RT/LT of CL	13+56	CL	CWET Locations: 2 West: Sta 12+29.5 LT & RT 2 East: Sta 13+31 LT & RT

The information below this line are details from Line Item agency views. No Agency View Details Exist

Revision 4/1/2020 Page 12 of 36



Line	Description of the control of the co	A discort	041	F .	0 1	0 1 /	A 1	D I
	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0020	POROUS BACKFILL	Material		5	May 18, 2020	SYSTEM	(\$3,672.00)	
				5	May 18, 2020	SYSTEM	\$3,672.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				6	Jun 2, 2020	SYSTEM	(\$3,672.00)	
				6	Jun 2, 2020	SYSTEM	\$3,672.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				7	Jun 16, 2020	SYSTEM	(\$3,672.00)	
				7	Jun 16, 2020	SYSTEM	\$3,672.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				8	Jul 1, 2020	SYSTEM	(\$3,672.00)	
				8	Jul 1, 2020	SYSTEM	\$3,672.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				9	Jul 16, 2020	SYSTEM	(\$3,672.00)	
				9	Jul 16, 2020	SYSTEM	\$3,672.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				10	Aug 3, 2020	SYSTEM	(\$3,672.00)	
				10	Aug 3, 2020	SYSTEM	\$3,672.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user leez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	- Total						\$0.00	
0040	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		5	May 18, 2020	SYSTEM	(\$2,730.00)	
				5	May 18,			
				3	2020	SYSTEM	\$2,730.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				6		SYSTEM	(\$2,730.00)	Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 6 on the current
					2020 Jun 2,			Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 6 on the current
				6	Jun 2, 2020 Jun 2,	SYSTEM	(\$2,730.00)	Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 5 on the current
				6	Jun 2, 2020 Jun 2, 2020 Jun 16,	SYSTEM	(\$2,730.00) \$2,730.00	Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 5 on the current
				6 6 7	Jun 2, 2020 Jun 2, 2020 Jun 16, 2020 Jun 16,	SYSTEM SYSTEM SYSTEM	(\$2,730.00) \$2,730.00 (\$2,730.00)	Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 6 on the current
				6 6 7 7 7	Jun 2, 2020 Jun 2, 2020 Jun 16, 2020 Jun 16, 2020 Jul 11,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$2,730.00) \$2,730.00 (\$2,730.00) \$2,730.00	Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 6 on the current
				6 6 7 7	Jun 2, 2020 Jun 2, 2020 Jun 16, 2020 Jun 16, 2020 Jul 1, 2020 Jul 1,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$2,730.00) \$2,730.00 (\$2,730.00) \$2,730.00 (\$2,730.00)	Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 6 on the current
				6 6 7 7 8 8	Jun 2, 2020 Jun 2, 2020 Jun 16, 2020 Jun 16, 2020 Jul 1, 2020 Jul 1, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$2,730.00) \$2,730.00 (\$2,730.00) \$2,730.00 (\$2,730.00)	Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 6 on the current

Revision 4/1/2020 Page 13 of 36



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0040	Material - Total						\$0.00	
0040 -	Total						\$0.00	
0050	GRAVEL (A) OR CRUSHED STONE (B)	Material		8	Jul 1, 2020	SYSTEM	(\$2,100.00)	
				8	Jul 1, 2020	SYSTEM	\$2,100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				9	Jul 16, 2020	SYSTEM	(\$2,100.00)	
				9	Jul 16, 2020	SYSTEM	\$2,100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				10	Aug 3, 2020	SYSTEM	(\$2,100.00)	
				10	Aug 3, 2020	SYSTEM	\$2,100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0050 -							\$0.00	
0070	FURNISHING TYPE 1 ROCK DITCH LINER	Material		6	Jun 2, 2020	SYSTEM	(\$400.00)	
				6	Jun 2, 2020	SYSTEM	\$400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
				7	Jun 16, 2020	SYSTEM	(\$400.00)	
				7	Jun 16, 2020	SYSTEM	\$400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				8	Jul 1, 2020	SYSTEM	(\$400.00)	
				8	Jul 1, 2020	SYSTEM	\$400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				9	Jul 16, 2020	SYSTEM	(\$2,500.00)	
				9	Jul 16, 2020	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0070 -	Total						\$0.00	
0110	CONSTRUCTION SIGNS	Material		1	Mar 16, 2020	SYSTEM	(\$2,704.00)	
				1	Mar 16, 2020	SYSTEM	\$2,704.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0110 -	Total						\$0.00	
0120	ADVANCED WARNING RAIL SYSTEM	Material		1	Mar 16, 2020	SYSTEM	(\$140.00)	
				1	Mar 16, 2020	SYSTEM	\$140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 2 on the current
								Payment Estimate.

Revision 4/1/2020 Page 14 of 36



Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
0120	Material - Total		Туре				\$0.00	
0120							\$0.00	
	FLAG ASSEMBLY	Material		4	Mar 16	SYSTEM		
0130	FLAG ASSEMBLY	Material		1	Mar 16, 2020	SYSTEM	(\$40.00)	
				1	Mar 16, 2020	SYSTEM	\$40.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0130 -	Total						\$0.00	
0140	TYPE III MOVEABLE BARRICADE	Material		1	Mar 16, 2020	SYSTEM	(\$1,250.00)	
				1	Mar 16, 2020	SYSTEM	\$1,250.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0140 -	Total						\$0.00	
0160	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P	Material		8	Jul 1, 2020	SYSTEM	(\$600.00)	
	BEADS			8	Jul 1, 2020	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user leez1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
				9	Jul 16, 2020	SYSTEM	(\$1,200.00)	
				9	Jul 16, 2020	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
				10	Aug 3, 2020	SYSTEM	(\$1,200.00)	
				10	Aug 3, 2020	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				11	Aug 17, 2020	SYSTEM	(\$1,200.00)	
				11	Aug 17, 2020	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Other Item Adjustment	REFL	9	Jul 16, 2020	leez1	\$60.00	Retroreflectivity adjustment for 4" white stripe. Stripe exceeded specifications and paying bonus. Results and calculations can be found on eProjects.
			REFL - Tota	ı			\$60.00	
	Other Item Adjustment - Total						\$60.00	
0160 -	Total						\$60.00	
0170	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P	Material		8	Jul 1, 2020	SYSTEM	(\$316.80)	
	BEADS			8	Jul 1, 2020	SYSTEM	\$316.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user leez1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
				9	Jul 16, 2020	SYSTEM	(\$633.60)	
				9	Jul 16, 2020	SYSTEM	\$633.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user leez1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
				10	Aug 3, 2020	SYSTEM	(\$745.20)	

Revision 4/1/2020 Page 15 of 36



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0170	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		10	Aug 3, 2020	SYSTEM	\$745.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
				11	Aug 17, 2020	SYSTEM	(\$745.20)	
				11	Aug 17, 2020	SYSTEM	\$745.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Other Item Adjustment	REFL	9	Jul 16, 2020	leez1	\$25.71	Retroreflectivity adjustment for 4" yellow stripe. Stripe exceeded specifications and paying bonus. Results and calculations can be found on eProjects.
			REFL - Tota	ıl			\$25.71	
	Other Item Adjustment - Total						\$25.71	
0170 -	Total						\$25.71	
0210	18 IN. PIPE GROUP C	Material		4	May 4, 2020	SYSTEM	(\$3,570.00)	
				4	May 4, 2020	SYSTEM	\$3,570.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user leez1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
				5	May 18, 2020	SYSTEM	(\$3,570.00)	
				5	May 18, 2020	SYSTEM	\$3,570.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 62 on the current Payment Estimate.
				6	Jun 2, 2020	SYSTEM	(\$3,570.00)	
				6	Jun 2, 2020	SYSTEM	\$3,570.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 61 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0210 -	Total						\$0.00	
0220	30 IN. PIPE GROUP C	Material		4	May 4, 2020	SYSTEM	(\$3,240.00)	
				4	May 4, 2020	SYSTEM	\$3,240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
				5	May 18, 2020	SYSTEM	(\$3,240.00)	
				5	May 18, 2020	SYSTEM	\$3,240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 65 on the current Payment Estimate.
				6	Jun 2, 2020	SYSTEM	(\$3,240.00)	
				6	Jun 2, 2020	SYSTEM	\$3,240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 64 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0220 -	Total						\$0.00	
0230	48 IN. PIPE GROUP C	Material		4	May 4, 2020	SYSTEM	(\$6,097.00)	
				4	May 4, 2020	SYSTEM	\$6,097.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
				5	May 18,	SYSTEM	(\$6,097.00)	

Revision 4/1/2020 Page 16 of 36



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0230	48 IN. PIPE GROUP C	Material			2020			
				5	May 18, 2020	SYSTEM	\$6,097.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 67 on the current Payment Estimate.
				6	Jun 2, 2020	SYSTEM	(\$6,097.00)	
				6	Jun 2, 2020	SYSTEM	\$6,097.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user leez1 overridding Payment Estimate Exception 66 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0230 -	Total						\$0.00	
0240	MISC. FLAP GATE 18"	Material		4	May 4, 2020	SYSTEM	(\$800.00)	
				4	May 4, 2020	SYSTEM	\$800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 35 on the current Payment Estimate.
				5	May 18, 2020	SYSTEM	(\$800.00)	
				5	May 18, 2020	SYSTEM	\$800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user leez1 overridding Payment Estimate Exception 68 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0240 -	Total						\$0.00	
0250	MISC. FLAP GATE 48"	Material		4	May 4, 2020	SYSTEM	(\$1,500.00)	
				4	May 4, 2020	SYSTEM	\$1,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
				5	May 18, 2020	SYSTEM	(\$1,500.00)	
				5	May 18, 2020	SYSTEM	\$1,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user leez1 overridding Payment Estimate Exception 69 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0250 -	Total						\$0.00	
0260	18 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION	Material		4	May 4, 2020	SYSTEM	(\$285.00)	
				4	May 4, 2020	SYSTEM	\$285.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user leez1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
				5	May 18, 2020	SYSTEM	(\$285.00)	
				5	May 18, 2020	SYSTEM	\$285.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user leez1 overridding Payment Estimate Exception 70 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0260 -	Total						\$0.00	
0270	30 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION	Material		4	May 4, 2020	SYSTEM	(\$1,150.00)	
				4	May 4, 2020	SYSTEM	\$1,150.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user leez1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
				5	May 18,	SYSTEM	(\$1,150.00)	

Revision 4/1/2020 Page 17 of 36



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0270	30 IN. OR ALLOWED SUBSTITUTE GROUP	Material			2020			
	C FLARED END SECTION			5	May 18, 2020	SYSTEM	\$1,150.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user leez1 overridding Payment Estimate Exception 71 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0270 -	- Total						\$0.00	
0280	48 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION	Material		4	May 4, 2020	SYSTEM	(\$1,575.00)	
				4	May 4, 2020	SYSTEM	\$1,575.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user leez1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
				5	May 18, 2020	SYSTEM	(\$1,575.00)	
				5	May 18, 2020	SYSTEM	\$1,575.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user leez1 overridding Payment Estimate Exception 72 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0280 -	- Total						\$0.00	
0290	SEEDING - COOL SEASON MIXTURES	Material		9	Jul 16, 2020	SYSTEM	(\$340.00)	
				9	Jul 16, 2020	SYSTEM	\$340.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user leez1 overridding Payment Estimate Exception 96 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	- Total						\$0.00	
0330	- Total TYPE C BERM	Material		8	Jul 1, 2020	SYSTEM	(\$1,680.00)	
		Material		8		SYSTEM		This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user leez1 overridding Payment Estimate Exception 76 on the current Payment Estimate.
		Material		8	2020 Jul 1,		(\$1,680.00)	Payment Estimate Item Adjustment (0008) due to user leez1 overridding Payment Estimate Exception 76 on the current Payment Estimate.
		Material		8	2020 Jul 1, 2020 Jul 16,	SYSTEM	(\$1,680.00) \$1,680.00	Payment Estimate Item Adjustment (0008) due to user leez1 overridding Payment Estimate Exception 76 on the current
		Material		8	2020 Jul 1, 2020 Jul 16, 2020 Jul 16,	SYSTEM	(\$1,680.00) \$1,680.00 (\$1,680.00) \$1,680.00	Payment Estimate Item Adjustment (0008) due to user leez1 overridding Payment Estimate Exception 76 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user leez1 overridding Payment Estimate Exception 100 on the current
		Material		9	Jul 16, 2020 Jul 16, 2020 Jul 16, 2020 Aug 3,	SYSTEM SYSTEM SYSTEM	(\$1,680.00) \$1,680.00 (\$1,680.00) \$1,680.00	Payment Estimate Item Adjustment (0008) due to user leez1 overridding Payment Estimate Exception 76 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user leez1 overridding Payment Estimate Exception 100 on the current
	TYPE C BERM	Material	- Total	9 9	2020 Jul 1, 2020 Jul 16, 2020 Jul 16, 2020 Aug 3, 2020	SYSTEM SYSTEM SYSTEM	(\$1,680.00) \$1,680.00 (\$1,680.00) \$1,680.00	Payment Estimate Item Adjustment (0008) due to user leez1 overridding Payment Estimate Exception 76 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user leez1 overridding Payment Estimate Exception 100 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 56 on the current
0330	TYPE C BERM	Material	- Total	9 9	2020 Jul 1, 2020 Jul 16, 2020 Jul 16, 2020 Aug 3, 2020	SYSTEM SYSTEM SYSTEM	(\$1,680.00) \$1,680.00 (\$1,680.00) \$1,680.00 \$1,680.00	Payment Estimate Item Adjustment (0008) due to user leez1 overridding Payment Estimate Exception 76 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user leez1 overridding Payment Estimate Exception 100 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 56 on the current
0330	TYPE C BERM	Material	- Total	9 9	2020 Jul 1, 2020 Jul 16, 2020 Jul 16, 2020 Aug 3, 2020	SYSTEM SYSTEM SYSTEM	(\$1,680.00) \$1,680.00 (\$1,680.00) \$1,680.00 (\$1,680.00) \$1,680.00	Payment Estimate Item Adjustment (0008) due to user leez1 overridding Payment Estimate Exception 76 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user leez1 overridding Payment Estimate Exception 100 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 56 on the current
0330	TYPE C BERM	Material Construction Stockpile	- Total	9 9 10 10	2020 Jul 1, 2020 Jul 16, 2020 Jul 16, 2020 Aug 3, 2020 Mar 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,680.00) \$1,680.00 (\$1,680.00) \$1,680.00 (\$1,680.00) \$1,680.00 \$0.00 \$0.00 \$32,700.00	Payment Estimate Item Adjustment (0008) due to user leez1 overridding Payment Estimate Exception 76 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user leez1 overridding Payment Estimate Exception 100 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 56 on the current Payment Estimate. Payment Estimate Item Adjustment generated Stockpile Transaction
0330	Material - Total	Construction		9 9 10 10	2020 Jul 1, 2020 Jul 16, 2020 Jul 16, 2020 Aug 3, 2020 Aug 3, 2020	SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,680.00) \$1,680.00 (\$1,680.00) \$1,680.00 (\$1,680.00) \$1,680.00 \$0.00 \$0.00 \$32,700.00 (\$32,700.00)	Payment Estimate Item Adjustment (0008) due to user leez1 overridding Payment Estimate Exception 76 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user leez1 overridding Payment Estimate Exception 100 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 56 on the current Payment Estimate.
0330	Material - Total Total TYPE C CRASHWORTHY END TERMINAL	Construction	- Total	9 9 10 10	2020 Jul 1, 2020 Jul 16, 2020 Jul 16, 2020 Aug 3, 2020 Aug 3, 2020 Mar 16, 2020 Jul 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,680.00) \$1,680.00 (\$1,680.00) \$1,680.00 (\$1,680.00) \$1,680.00 \$0.00 \$0.00 \$32,700.00 (\$32,700.00)	Payment Estimate Item Adjustment (0008) due to user leez1 overridding Payment Estimate Exception 76 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user leez1 overridding Payment Estimate Exception 100 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 56 on the current Payment Estimate. Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile
0330 - 0330 - 0340	Material - Total Total TYPE C CRASHWORTHY END TERMINAL Construction Stockpile - Total	Construction		9 9 10 10	2020 Jul 1, 2020 Jul 16, 2020 Jul 16, 2020 Aug 3, 2020 Aug 3, 2020 Mar 16, 2020 Jul 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,680.00) \$1,680.00 (\$1,680.00) \$1,680.00 (\$1,680.00) \$1,680.00 \$0.00 \$0.00 \$32,700.00) \$0.00 \$0.00 \$0.00	Payment Estimate Item Adjustment (0008) due to user leez1 overridding Payment Estimate Exception 76 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user leez1 overridding Payment Estimate Exception 100 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 56 on the current Payment Estimate. Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile
0330 - 0330 - 0340	Material - Total Total TYPE C CRASHWORTHY END TERMINAL	Construction		9 9 10 10	2020 Jul 1, 2020 Jul 16, 2020 Jul 16, 2020 Aug 3, 2020 Aug 3, 2020 Mar 16, 2020 Jul 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,680.00) \$1,680.00 (\$1,680.00) \$1,680.00 (\$1,680.00) \$1,680.00 \$0.00 \$0.00 \$32,700.00 (\$32,700.00)	Payment Estimate Item Adjustment (0008) due to user leez1 overridding Payment Estimate Exception 76 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user leez1 overridding Payment Estimate Exception 100 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 56 on the current Payment Estimate. Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile
0330 - 0330 - 0340	Material - Total Total TYPE C CRASHWORTHY END TERMINAL Construction Stockpile - Total Total	Construction Stockpile		9 9 10 10	2020 Jul 1, 2020 Jul 16, 2020 Jul 16, 2020 Aug 3, 2020 Mar 16, 2020 Jul 11, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,680.00) \$1,680.00 (\$1,680.00) \$1,680.00 \$1,680.00 \$0.00 \$0.00 \$32,700.00) \$0.00 \$0.00 \$0.00 \$0.00	Payment Estimate Item Adjustment (0008) due to user leez1 overridding Payment Estimate Exception 76 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user leez1 overridding Payment Estimate Exception 100 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 56 on the current Payment Estimate. Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile

Revision 4/1/2020 Page 18 of 36



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0370	BRIDGE APPROACH SLAB (MINOR ROAD)	Material						Payment Estimate.
				6	Jun 2, 2020	SYSTEM	(\$4,235.00)	
				6	Jun 2, 2020	SYSTEM	\$4,235.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user leez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0370 -	Total						\$0.00	
0380	GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN)	Material		1	Mar 16, 2020	SYSTEM	(\$6,120.00)	
				1	Mar 16, 2020	SYSTEM	\$6,120.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user leez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				2	Apr 2, 2020	SYSTEM	(\$25,290.00)	
				2	Apr 2, 2020	SYSTEM	\$25,290.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				3	Apr 16, 2020	SYSTEM	(\$25,920.00)	
				3	Apr 16, 2020	SYSTEM	\$25,920.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				4	May 4, 2020	SYSTEM	(\$25,920.00)	
				4	May 4, 2020	SYSTEM	\$25,920.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				5	May 18, 2020	SYSTEM	(\$25,920.00)	
				5	May 18, 2020	SYSTEM	\$25,920.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user leez1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
				6	Jun 2, 2020	SYSTEM	(\$25,920.00)	
				6	Jun 2, 2020	SYSTEM	\$25,920.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user leez1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
				7	Jun 16, 2020	SYSTEM	(\$25,920.00)	
				7	Jun 16, 2020	SYSTEM	\$25,920.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
				8	Jul 1, 2020	SYSTEM	(\$25,920.00)	
				8	Jul 1, 2020	SYSTEM	\$25,920.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user leez1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
				9	Jul 16, 2020	SYSTEM	(\$25,920.00)	
				9	Jul 16, 2020	SYSTEM	\$25,920.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user leez1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN)	Overrun	Overrun	2	Apr 2, 2020	SYSTEM	\$5,850.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 5 on the current Payment Estimate.

Revision 4/1/2020 Page 19 of 36



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks											
0380	GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN)	Overrun	Overrun	2	Apr 2, 2020	SYSTEM	(\$5,850.00)												
			Overrun - T	otal			\$0.00												
	Overrun - Total						\$0.00												
0380 -	Total						\$0.00												
0400	PILE POINT REINFORCEMENT	Material		1	Mar 16, 2020	SYSTEM	(\$4,600.00)												
				1	Mar 16, 2020	SYSTEM	\$4,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user leez1 overridding Payment Estimate Exception 10 on the current Payment Estimate.											
				2	Apr 2, 2020	SYSTEM	(\$5,750.00)												
				2	Apr 2, 2020	SYSTEM	\$5,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.											
			- Total				\$0.00												
	Material - Total						\$0.00												
	PILE POINT REINFORCEMENT	Overrun	Overrun	2	Apr 2, 2020	SYSTEM	\$1,150.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 6 on the current Payment Estimate.											
				2	Apr 2, 2020	SYSTEM	(\$1,150.00)												
			Overrun - T	otal			\$0.00												
	Overrun - Total						\$0.00												
0400 -	Total						\$0.00												
0410	CLASS B CONCRETE (SUBSTRUCTURE)	Material		3	Apr 16, 2020	SYSTEM	(\$22,400.00)												
						3	Apr 16, 2020	SYSTEM	\$22,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 10 on the current Payment Estimate.									
					4	May 4, 2020	SYSTEM	(\$22,400.00)											
				4	May 4, 2020	SYSTEM	\$22,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user lee21 overridding Payment Estimate Exception 10 on the current Payment Estimate.											
				5	May 18, 2020	SYSTEM	(\$22,400.00)												
				5	May 18, 2020	SYSTEM	\$22,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user leez1 overridding Payment Estimate Exception 29 on the current Payment Estimate.											
				6	Jun 2, 2020	SYSTEM	(\$22,400.00)												
				6	Jun 2, 2020	SYSTEM	\$22,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user leez1 overridding Payment Estimate Exception 30 on the current Payment Estimate.											
				7	Jun 16, 2020	SYSTEM	(\$22,400.00)												
															7	Jun 16, 2020	SYSTEM	\$22,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
				8	Jul 1, 2020	SYSTEM	(\$22,400.00)												
									8	8	8	8	Jul 1, 2020	SYSTEM	\$22,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user leez1 overridding Payment Estimate Exception 37 on the current Payment Estimate.			
				9	Jul 16, 2020	SYSTEM	(\$22,400.00)												
				9	Jul 16, 2020	SYSTEM	\$22,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user leez1 overridding Payment Estimate Exception 51 on the current											

Revision 4/1/2020 Page 20 of 36



Type Type	
0410 CLASS B CONCRETE (SUBSTRUCTURE) Material	Payment Estimate.
- Total \$	\$0.00
Material - Total \$	\$0.00
0410 - Total \$	\$0.00
0420 SAFETY BARRIER CURB Material 5 May 18, 2020 \$SYSTEM (\$16,20	00.00)
5 May 18, SYSTEM \$16,20	70.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user leez1 overridding Payment Estimate Exception 45 on the current Payment Estimate.
6 Jun 2, 2020 (\$16,20	00.00)
6 Jun 2, 2020 \$16,20	D0.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user leez1 overridding Payment Estimate Exception 44 on the current Payment Estimate.
7 Jun 16, 2020 (\$16,20	00.00)
7 Jun 16, 2020 \$16,20	D0.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user leez1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
8 Jul 1, SYSTEM (\$16,20	00.00)
8 Jul 1, 2020 \$16,20	On Discossible 20.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user leez1 overridding Payment Estimate Exception 64 on the current Payment Estimate.
9 Jul 16, 2020 (\$16,20	00.00)
9 Jul 16, 2020 \$16,20	On Discossible 20.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user leez1 overridding Payment Estimate Exception 79 on the current Payment Estimate.
10 Aug 3, 2020 (\$16,20	00.00)
10 Aug 3, SYSTEM \$16,20	On On This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user leez1 overridding Payment Estimate Exception 43 on the current Payment Estimate.
11 Aug 17, 2020 (\$16,20	00.00)
11 Aug 17, SYSTEM \$16,20	On On This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
	\$0.00
	\$0.00
0420 - Total \$	\$0.00
0430 SLAB ON CONCRETE BEAM Material 3 Apr 16, 2020 SYSTEM (\$24,33)	36.00)
3 Apr 16, SYSTEM \$24,33	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
4 May 4, 2020 (\$60,84	40.00)
4 May 4, 2020 SYSTEM \$60,84	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user leez1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
5 May 18, 2020 (\$60,84	40.00)
5 May 18, SYSTEM \$60,84	40.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user leez1 overridding Payment Estimate Exception 55 on the current Payment Estimate.

Revision 4/1/2020 Page 21 of 36



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
		Туре	Adjustment Type	Number	Date	Ву		
0430	SLAB ON CONCRETE BEAM	Material		6	Jun 2, 2020	SYSTEM	\$60,840.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user leez1 overridding Payment Estimate Exception 54 on the current Payment Estimate.
				7	Jun 16, 2020	SYSTEM	(\$60,840.00)	
				7	Jun 16, 2020	SYSTEM	\$60,840.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user leez1 overridding Payment Estimate Exception 41 on the current Payment Estimate.
				8	Jul 1, 2020	SYSTEM	(\$60,840.00)	
				8	Jul 1, 2020	SYSTEM	\$60,840.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user leez1 overridding Payment Estimate Exception 67 on the current Payment Estimate.
				9	Jul 16, 2020	SYSTEM	(\$60,840.00)	
				9	Jul 16, 2020	SYSTEM	\$60,840.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user leez1 overridding Payment Estimate Exception 82 on the current Payment Estimate.
				10	Aug 3, 2020	SYSTEM	(\$60,840.00)	
				10	Aug 3, 2020	SYSTEM	\$60,840.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user leez1 overridding Payment Estimate Exception 46 on the current Payment Estimate.
				11	Aug 17, 2020	SYSTEM	(\$60,840.00)	
				11	Aug 17, 2020	SYSTEM	\$60,840.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user leez1 overridding Payment Estimate Exception 35 on the current
								Payment Estimate.
			- Total				\$0.00	Payment Estimate.
0.420	Material - Total		- Total				\$0.00	Payment Estimate.
0430 · 0490	Material - Total - Total POROUS BACKFILL	Material	- Total	5	May 18,	SYSTEM		Payment Estimate.
	- Total	Material	- Total	5	May 18, 2020 May 18, 2020	SYSTEM SYSTEM	\$0.00 \$0.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
	- Total	Material	- Total		2020 May 18,		\$0.00 \$0.00 (\$4,828.00)	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user leez1 overridding Payment Estimate Exception 3 on the current
	- Total	Material	- Total	5	2020 May 18, 2020 Jun 2,	SYSTEM	\$0.00 \$0.00 (\$4,828.00) \$4,828.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user leez1 overridding Payment Estimate Exception 3 on the current
	- Total	Material	- Total	5	2020 May 18, 2020 Jun 2, 2020 Jun 2,	SYSTEM	\$0.00 \$0.00 (\$4,828.00) \$4,828.00 (\$4,828.00)	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user leez1 overridding Payment Estimate Exception 3 on the current
	- Total	Material	- Total	5 6 6	2020 May 18, 2020 Jun 2, 2020 Jun 2, 2020 Jun 16,	SYSTEM SYSTEM	\$0.00 \$0.00 (\$4,828.00) \$4,828.00 (\$4,828.00)	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user leez1 overridding Payment Estimate Exception 3 on the current
	- Total	Material	- Total	5 6 6	2020 May 18, 2020 Jun 2, 2020 Jun 2, 2020 Jun 16, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$4,828.00) \$4,828.00 (\$4,828.00) (\$4,828.00)	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user leez1 overridding Payment Estimate Exception 1 on the current
	- Total	Material	- Total	5 6 6 7 7	2020 May 18, 2020 Jun 2, 2020 Jun 16, 2020 Jun 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$4,828.00) \$4,828.00 (\$4,828.00) \$4,828.00 (\$4,828.00)	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user leez1 overridding Payment Estimate Exception 1 on the current
	- Total	Material	- Total	5 6 6 7 7	2020 May 18, 2020 Jun 2, 2020 Jun 16, 2020 Jun 16, 2020 Jul 1, 2020 Jul 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$4,828.00) \$4,828.00 (\$4,828.00) \$4,828.00 (\$4,828.00)	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user leez1 overridding Payment Estimate Item Adjustment (0021) due to user leez1 overridding Payment Estimate Exception 1 on the current
	- Total	Material	- Total	5 6 6 7 7 8 8	2020 May 18, 2020 Jun 2, 2020 Jun 16, 2020 Jul 1, 2020 Jul 1, 2020 Jul 1, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$4,828.00) \$4,828.00 (\$4,828.00) \$4,828.00 (\$4,828.00) \$4,828.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user leez1 overridding Payment Estimate Item Adjustment (0021) due to user leez1 overridding Payment Estimate Exception 1 on the current
	- Total	Material	- Total	5 6 6 7 7 8 8	2020 May 18, 2020 Jun 2, 2020 Jun 16, 2020 Jul 1, 2020 Jul 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$4,828.00) \$4,828.00 (\$4,828.00) (\$4,828.00) (\$4,828.00) (\$4,828.00)	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.

Revision 4/1/2020 Page 22 of 36



Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
0490	POROUS BACKFILL	Material	Туре		2020			Payment Estimate Item Adjustment (0014) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	r aymon Lounato.
	Material - Total		- Total				\$0.00	
0490 -	· Total						\$0.00	
0510	TYPE 5 AGGREGATE FOR BASE (6 IN.	Material		5	May 18,	SYSTEM	(\$3,094.00)	
00.0	THICK)	material			2020	0.0.2	(ψο,σο ποσ)	
				5	May 18, 2020	SYSTEM	\$3,094.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				6	Jun 2, 2020	SYSTEM	(\$3,094.00)	
				6	Jun 2, 2020	SYSTEM	\$3,094.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user leez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				7	Jun 16, 2020	SYSTEM	(\$3,094.00)	
				7	Jun 16, 2020	SYSTEM	\$3,094.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				8	Jul 1, 2020	SYSTEM	(\$3,094.00)	
				8	Jul 1, 2020	SYSTEM	\$3,094.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				9	Jul 16, 2020	SYSTEM	(\$3,094.00)	
				9	Jul 16, 2020	SYSTEM	\$3,094.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user leez1
					2020			overridding Payment Estimate Exception 8 on the current Payment Estimate.
			- Total		2020		\$0.00	overridding Payment Estimate Exception 8 on the current
	Material - Total		- Total		2020		\$0.00 \$0.00	overridding Payment Estimate Exception 8 on the current
0510 -	Material - Total Total		- Total		2020			overridding Payment Estimate Exception 8 on the current
0510 - 0520		Material	- Total	8	Jul 1, 2020	SYSTEM	\$0.00	overridding Payment Estimate Exception 8 on the current
	Total	Material	- Total	8	Jul 1,	SYSTEM	\$0.00 \$0.00	overridding Payment Estimate Exception 8 on the current
	Total	Material	- Total		Jul 1, 2020 Jul 1,		\$0.00 \$0.00 (\$180.00)	overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user leez1 overridding Payment Estimate Exception 7 on the current
	Total	Material	- Total	8	Jul 1, 2020 Jul 1, 2020 Jul 16,	SYSTEM	\$0.00 \$0.00 (\$180.00) \$180.00	overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user leez1 overridding Payment Estimate Exception 7 on the current
	Total	Material	- Total	9	Jul 1, 2020 Jul 1, 2020 Jul 16, 2020 Jul 16,	SYSTEM	\$0.00 \$0.00 (\$180.00) \$180.00	overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user leez1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user leez1 overridding Payment Estimate Exception 10 on the current
	Total	Material	- Total	9	Jul 1, 2020 Jul 1, 2020 Jul 16, 2020 Jul 16, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$180.00) \$180.00 (\$180.00)	overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user leez1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user leez1 overridding Payment Estimate Exception 10 on the current
	Total	Material	- Total	9 9 10	Jul 1, 2020 Jul 1, 2020 Jul 16, 2020 Jul 16, 2020 Aug 3, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$180.00) \$180.00 (\$180.00) (\$180.00)	overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user leez1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user leez1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user leez1 overridding Payment Estimate Exception 10 on the current
	Total	Material		9 9 10	Jul 1, 2020 Jul 1, 2020 Jul 16, 2020 Jul 16, 2020 Aug 3, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$180.00) \$180.00 (\$180.00) \$180.00 (\$180.00)	overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user leez1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user leez1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user leez1 overridding Payment Estimate Exception 10 on the current
0520	Total GRAVEL (A) OR CRUSHED STONE (B)	Material		9 9 10	Jul 1, 2020 Jul 1, 2020 Jul 16, 2020 Jul 16, 2020 Aug 3, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$180.00) \$180.00 (\$180.00) \$180.00 \$180.00	overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user leez1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user leez1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user leez1 overridding Payment Estimate Exception 10 on the current
0520	GRAVEL (A) OR CRUSHED STONE (B)			9 9 10	Jul 1, 2020 Jul 1, 2020 Jul 16, 2020 Jul 16, 2020 Aug 3, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$180.00) \$180.00 (\$180.00) \$180.00 \$180.00 \$0.00	overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user leez1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user leez1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user leez1 overridding Payment Estimate Exception 10 on the current
0520	Total GRAVEL (A) OR CRUSHED STONE (B) Material - Total Total			9 9 10 10	Jul 1, 2020 Jul 1, 2020 Jul 16, 2020 Jul 16, 2020 Aug 3, 2020 Aug 3, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$180.00) \$180.00 (\$180.00) \$180.00 \$180.00 \$0.00 \$0.00	overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user leez1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user leez1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user leez1 overridding Payment Estimate Exception 10 on the current

Revision 4/1/2020 Page 23 of 36



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0540	FURNISHING TYPE 1 ROCK DITCH LINER	Material		7	Jun 16, 2020	SYSTEM	\$1,876.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user leez1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				8	Jul 1, 2020	SYSTEM	(\$1,876.00)	
				8	Jul 1, 2020	SYSTEM	\$1,876.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user leez1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				9	Jul 16, 2020	SYSTEM	(\$1,876.00)	
				9	Jul 16, 2020	SYSTEM	\$1,876.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user leez1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0540 -	Total						\$0.00	
0620	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED.	Material		1	Mar 16, 2020	SYSTEM	(\$5,600.00)	
	CONTRACTOR RETAINED			1	Mar 16, 2020	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0620 -	Total						\$0.00	
0640	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P	Material		8	Jul 1, 2020	SYSTEM	(\$608.40)	
	BEADS			8	Jul 1, 2020	SYSTEM	\$608.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user leez1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
				9	Jul 16, 2020	SYSTEM	(\$1,216.80)	
				9	Jul 16, 2020	SYSTEM	\$1,216.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user leez1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
				10	Aug 3, 2020	SYSTEM	(\$1,256.40)	
				10	Aug 3, 2020	SYSTEM	\$1,256.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user leez1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				11	Aug 17, 2020	SYSTEM	(\$1,256.40)	
				11	Aug 17, 2020	SYSTEM	\$1,256.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user leez1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Other Item Adjustment	REFL		Jul 16, 2020	leez1	\$62.82	Retroreflectivity adjustment for 4" white stripe. Stripe exceeded specifications and paying bonus. Results and calculations can be found on eProjects.
			REFL - Tota	ıl			\$62.82	
	Other Item Adjustment - Total						\$62.82	
0640 -							\$62.82	
0650	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		8	Jul 1, 2020	SYSTEM	(\$289.20)	
	BEAUS			8	Jul 1, 2020	SYSTEM	\$289.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user leez1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
				9	Jul 16,	SYSTEM	(\$578.40)	

Revision 4/1/2020 Page 24 of 36



Section PAMEMENT MARKING PAIN CRARGE Part PAMEMENT MARKING PAIN CRARGE Part P	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
## ADS 9	0650		Material			2020			
1					9		SYSTEM	\$578.40	Payment Estimate Item Adjustment (0022) due to user leez1 overridding Payment Estimate Exception 28 on the current
					10		SYSTEM	(\$578.40)	
1					10		SYSTEM	\$578.40	Payment Estimate Item Adjustment (0017) due to user leez1 overridding Payment Estimate Exception 18 on the current
Polyment Estimate Item Agustrenic (2015) us to user leveral overroting Programme Estimate Exception 3 on the current Programme Estimate Item Agustrenic (2015) use to user leveral 2020 Section 3 on the current Programme Estimate Item Agustrenic (2015) use to user leveral 2020 Section 3 on the current Programme Estimate Item Agustrenic (2015) use to user leveral 2020 Section 3 on the current Programme Estimate Item Agustrenic (2015) use to user leveral 2020 Section 3 on the current Programme Estimate Item Agustrenic (2015) use to user leveral 2020 Section 3 on the current Programme Estimate Item Agustrenic (2015) use to user leveral 2020 Section 3 on the current Programme Estimate Item Agustrenic (2015) use to user leveral 2020 Section 3 on the current Programme Estimate Item Agustrenic (2015) use to user leveral 2020 Section 3 on the current Programme Estimate Item Agustrenic (2015) use to user leveral 2020 Section 3 on the current Programme Estimate Item Agustrenic (2015) use to user leveral 2020 Section 3 on the current Programme Estimate Item Agustrenic (2015) use to user leveral 2020 Section 3 on the current Programme Estimate Item Agustrenic (2015) use to user leveral 2020 Section 3 on the current Programme Estimate Item Agustrenic (2015) user leveral 2020 Section 3 on the current Programme Estimate Item Agustrenic (2015) user leveral 2020 Section 3 on the current Programme Estimate Item Agustrenic (2015) user leveral 2020 Section 3 on the current Programme Estimate Item Agustrenic (2015) user leveral 2020 Section 3 on the current Programme Estimate Item Agustrenic (2015) user leveral 2020 Section 3 on the current Programme Estimate Item Agustrenic (2015) user leveral 2020 Section 3 on the current Programme Estimate Item Agustrenic Item 4 (2015) user leveral 2020 Section 3 on the current					11		SYSTEM	(\$578.40)	
Material - Total					11		SYSTEM	\$578.40	Payment Estimate Item Adjustment (0016) due to user leez1 overridding Payment Estimate Exception 8 on the current
A IN YELLOW STANDARD WATERGOODE Adjustment STayle accorded performance and paying borus. Results and calculations can be 1922. Stayle accorded performance and paying borus. Results and calculations can be 1924.58				- Total				\$0.00	
PAVEMENT MARKING PAINT, TOTE BEADS Adjustment DEADS PAVEMENT PAVEM		Material - Total						\$0.00	
Other Ham Adjustment - Total \$24.58		PAVEMENT MARKING PAINT, TYPE P		REFL	9		leez1	\$24.58	specifications and paying bonus. Results and calculations can be
18 IN, PIPE GROUP C Material				REFL - Tota	al			\$24.58	
16 IN. PIPE GROUP C Material		Other Item Adjustment - Total						\$24.58	
A	0650 -	- Total						\$24.58	
2020 Payment Estimate Item Adjustment (0013) due to user least overridding Payment Estimate Exception 30 on the current Payment Estimate.	0690	18 IN. PIPE GROUP C	Material		4		SYSTEM	(\$3,395.00)	
2020 5 May 18 SYSTEM \$3,395.00 This adjustment offsets the original system-generated Overrun Payment Estimate Exception 62 on the current Payment Estimate Exception 63 on the current Payment Estimate Exception 62 on the current Payment Estimate Exception 63 on the current Payment Estimate Exception 63 on the current Payment Estimate Exception 64 on the current Payment Estimate Exception 64 on the current Payment Estimate Exception 65 on the current Paymen					4		SYSTEM	\$3,395.00	Payment Estimate Item Adjustment (0013) due to user leez1 overridding Payment Estimate Exception 30 on the current
2020 Payment Estimate Item Adjustment (1021) due to user leez1 overridding Payment Estimate Exception 63 on the current Payment Estimate Exception 63 on the current Payment Estimate Exception 63 on the current Payment Estimate Item Adjustment (1018) due to user leez1 overridding Payment Estimate Exception 62 on the current Payment Estimate Item Adjustment (1018) due to user leez1 overridding Payment Estimate Exception 62 on the current Payment Estimate Item Adjustment (1014) due to user leez1 overridding Payment Estimate Exception 31 on the current Payment Estimate Item Adjustment (1002) due to user leez1 overridding Payment Estimate Exception 64 on the current Payment Estimate Exception 63 on the current Payment Estimate Estimate Exception 63 on the current Payment Estimate Exception 63 on the current Payment Estimate Estimate Estimate Exception 63 on the current Payment Estimate Estimate Estimate Exception 63 on the current Payment Estimate Estimate Estimate Estimate Exception 64 on the current Paym					5		SYSTEM	(\$3,395.00)	
2020 SYSTEM \$3,395.00 This adjustment offsets the original system-generated Overrun Payment Estimate Exception 62 on the current Payment Estimate Exception 62 on the current Payment Estimate Exception 62 on the current Payment Estimate Exception 62 on the current Payment Estimate Exception 62 on the current Payment Estimate Exception 62 on the current Payment Estimate Exception 62 on the current Payment Estimate Exception 62 on the current Payment Estimate Exception 62 on the current Payment Estimate Exception 62 on the current Payment Estimate Exception 62 on the current Payment Estimate Exception 63 on the current Payment Estimate Exception 64 on the current Payment Estimate Exception 63 on the current Payment Estimate Exception 64 on the current Payment Estima					5		SYSTEM	\$3,395.00	Payment Estimate Item Adjustment (0021) due to user leez1 overridding Payment Estimate Exception 63 on the current
Payment Estimate Item Adjustment (0018) due to user leez1					6		SYSTEM	(\$3,395.00)	
Material - Total S0.00					6		SYSTEM	\$3,395.00	Payment Estimate Item Adjustment (0018) due to user leez1 overridding Payment Estimate Exception 62 on the current
				- Total				\$0.00	
Material - Total Material A May 4, 2020 SYSTEM (\$1,470.00)		Material - Total						\$0.00	
2020 4 May 4, 2020 5 May 18, 27STEM 2020 5 May 18, 2020 5 May 18, 2020 6 Jun 2, 2020 8 \$1,470.00 This adjustment offsets the original system-generated Overrun Payment Estimate Exception 64 on the current Payment Estimate Exception 63 on the current Payment Estimate Exception 64 on the current Payment Estimate Exception 63 on the current Payment Estimate Exception 64 on the current Payment Estimate Exception 63 on the current Payment Estimate Exception 64 on the current Payment Estimate Exception 64 on the current Payment Estimate Exception 65 on th	0690 -	- Total						\$0.00	
2020 Payment Estimate Item Adjustment (0014) due to user leez1 overridding Payment Estimate Exception 31 on the current Payment Estimate Exception 31 on the current Payment Estimate Exception 31 on the current Payment Estimate Item Adjustment (0012) due to user leez1 overridding Payment Estimate Exception 64 on the current Payment Estimate Exception 64 on the current Payment Estimate Exception 64 on the current Payment Estimate Item Adjustment (0012) due to user leez1 overridding Payment Estimate Exception 64 on the current Payment Estimate Item Adjustment (0019) due to user leez1 overridding Payment Estimate Exception 63 on the current Payment Estimate Exception 63 on the current Payment Estimate Exception 63 on the current Payment Estimate. -Total	0700	24 IN. PIPE GROUP C	Material		4		SYSTEM	(\$1,470.00)	
5 May 18, 2020 \$1,470.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user leez1 overridding Payment Estimate Exception 64 on the current Payment Estimate Exception 64 on the current Payment Estimate Exception 64 on the current Payment Estimate Item Adjustment (0019) due to user leez1 overridding Payment Estimate Item Adjustment (0019) due to user leez1 overridding Payment Estimate Exception 63 on the current Payment Estimate. - Total \$0.00 Material - Total \$0.00					4		SYSTEM	\$1,470.00	Payment Estimate Item Adjustment (0014) due to user leez1 overridding Payment Estimate Exception 31 on the current
Payment Estimate Item Adjustment (0022) due to user leez1 overridding Payment Estimate Exception 64 on the current Payment Estimate Exception 64 on the current Payment Estimate. 6 Jun 2, 2020 6 Jun 2, SYSTEM \$1,470.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user leez1 overridding Payment Estimate Exception 63 on the current Payment Estimate. - Total \$0.00 Material - Total \$0.00					5		SYSTEM	(\$1,470.00)	
2020 6 Jun 2, 2020 8 \$1,470.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user leez1 overridding Payment Estimate Exception 63 on the current Payment Estimate. - Total \$0.00 Material - Total \$0.00					5		SYSTEM	\$1,470.00	Payment Estimate Item Adjustment (0022) due to user leez1 overridding Payment Estimate Exception 64 on the current
Payment Estimate Item Adjustment (0019) due to user leez1 overridding Payment Estimate Exception 63 on the current Payment Estimate. - Total \$0.00 Material - Total \$0.00					6		SYSTEM	(\$1,470.00)	
Material - Total \$0.00					6		SYSTEM	\$1,470.00	Payment Estimate Item Adjustment (0019) due to user leez1 overridding Payment Estimate Exception 63 on the current
				- Total				\$0.00	
0700 Total		Material - Total						\$0.00	
0/00 - Folds \$0.00	0700 -	- Total						\$0.00	

Revision 4/1/2020 Page 25 of 36



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0710	30 IN. PIPE GROUP C	Material		4	May 4, 2020	SYSTEM	(\$6,240.00)	
				4	May 4, 2020	SYSTEM	\$6,240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user leez1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
				5	May 18, 2020	SYSTEM	(\$6,240.00)	
				5	May 18, 2020	SYSTEM	\$6,240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user leez1 overridding Payment Estimate Exception 66 on the current Payment Estimate.
				6	Jun 2, 2020	SYSTEM	(\$6,240.00)	
				6	Jun 2, 2020	SYSTEM	\$6,240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user leez1 overridding Payment Estimate Exception 65 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0710 -	Total						\$0.00	
0750	SEEDING - COOL SEASON MIXTURES	Material		9	Jul 16, 2020	SYSTEM	(\$187.00)	
				9	Jul 16, 2020	SYSTEM	\$187.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user leez1 overridding Payment Estimate Exception 93 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0750 -	Total						\$0.00	
0790	TYPE C BERM	Material		8	Jul 1, 2020	SYSTEM	(\$2,450.00)	
				8	Jul 1, 2020	SYSTEM	\$2,450.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user leez1 overridding Payment Estimate Exception 75 on the current Payment Estimate.
				9	Jul 16, 2020	SYSTEM	(\$2,450.00)	
				9	Jul 16, 2020	SYSTEM	\$2,450.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user leez1 overridding Payment Estimate Exception 101 on the current Payment Estimate.
				10	Aug 3, 2020	SYSTEM	(\$2,450.00)	
				10	Aug 3, 2020	SYSTEM	\$2,450.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user leez1 overridding Payment Estimate Exception 57 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0790 -	Total						\$0.00	
0800	TYPE C CRASHWORTHY END TERMINAL	Construction Stockpile		1	Mar 16, 2020	SYSTEM	\$32,700.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				8	Jul 1, 2020	SYSTEM	(\$32,700.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
0800 -	Total						\$0.00	
0830	BRIDGE APPROACH SLAB (MINOR ROAD)	Material		5	May 18, 2020	SYSTEM	(\$4,312.00)	
				5	May 18, 2020	SYSTEM	\$4,312.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user leez1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
				6	Jun 2, 2020	SYSTEM	(\$4,312.00)	

Revision 4/1/2020 Page 26 of 36



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0830	BRIDGE APPROACH SLAB (MINOR ROAD)	Material		6	Jun 2, 2020	SYSTEM	\$4,312.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user leez1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0830 -	· Total						\$0.00	
0840	GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN)	Material		3	Apr 16, 2020	SYSTEM	(\$39,200.00)	
				3	Apr 16, 2020	SYSTEM	\$39,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				4	May 4, 2020	SYSTEM	(\$39,200.00)	
				4	May 4, 2020	SYSTEM	\$39,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				5	May 18, 2020	SYSTEM	(\$39,200.00)	
				5	May 18, 2020	SYSTEM	\$39,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user leez1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
				6	Jun 2, 2020	SYSTEM	(\$39,200.00)	
				6	Jun 2, 2020	SYSTEM	\$39,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user leez1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
				7	Jun 16, 2020	SYSTEM	(\$39,200.00)	
				7	Jun 16, 2020	SYSTEM	\$39,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user leez1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				8	Jul 1, 2020	SYSTEM	(\$39,200.00)	
				8	Jul 1, 2020	SYSTEM	\$39,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user leez1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
				9	Jul 16, 2020	SYSTEM	(\$39,200.00)	
				9	Jul 16, 2020	SYSTEM	\$39,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user leez1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0840 -	· Total						\$0.00	
0860	CLASS B CONCRETE (SUBSTRUCTURE)	Material		3	Apr 16, 2020	SYSTEM	(\$41,600.00)	
				3	Apr 16, 2020	SYSTEM	\$41,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user leez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				4	May 4, 2020	SYSTEM	(\$41,600.00)	
				4	May 4, 2020	SYSTEM	\$41,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user leez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				5	May 18, 2020	SYSTEM	(\$41,600.00)	
				5	May 18, 2020	SYSTEM	\$41,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user leez1 overridding Payment Estimate Exception 31 on the current

Revision 4/1/2020 Page 27 of 36



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
	-	Туре	Adjustment Type		Date	Ву		
0860	CLASS B CONCRETE (SUBSTRUCTURE)	Material						Payment Estimate.
				6	Jun 2, 2020	SYSTEM	(\$41,600.00)	
				6	Jun 2, 2020	SYSTEM	\$41,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user leez1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
				7	Jun 16, 2020	SYSTEM	(\$41,600.00)	
				7	Jun 16, 2020	SYSTEM	\$41,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user leez1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
				8	Jul 1, 2020	SYSTEM	(\$41,600.00)	
				8	Jul 1, 2020	SYSTEM	\$41,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user leez1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
				9	Jul 16, 2020	SYSTEM	(\$41,600.00)	
				9	Jul 16, 2020	SYSTEM	\$41,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user leez1 overridding Payment Estimate Exception 48 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0860 -	Total						\$0.00	
0870	SLAB ON CONCRETE I-GIRDER	Material		3	Apr 16, 2020	SYSTEM	(\$26,010.00)	
				3	Apr 16, 2020	SYSTEM	\$26,010.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				4	May 4, 2020	SYSTEM	(\$65,025.00)	
				4	May 4, 2020	SYSTEM	\$65,025.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user leez1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				5	May 18, 2020	SYSTEM	(\$65,025.00)	
				5	May 18, 2020	SYSTEM	\$65,025.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user leez1 overridding Payment Estimate Exception 35 on the current Payment Estimate.
				6	Jun 2, 2020	SYSTEM	(\$65,025.00)	
				6	Jun 2, 2020	SYSTEM	\$65,025.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user leez1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
				7	Jun 16, 2020	SYSTEM	(\$65,025.00)	
				7	Jun 16, 2020	SYSTEM	\$65,025.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user leez1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
				8	Jul 1, 2020	SYSTEM	(\$65,025.00)	
				8	Jul 1, 2020	SYSTEM	\$65,025.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user leez1 overridding Payment Estimate Exception 42 on the current Payment Estimate.
				9	Jul 16, 2020	SYSTEM	(\$65,025.00)	
				9	Jul 16, 2020	SYSTEM	\$65,025.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user leez1 overridding Payment Estimate Exception 52 on the current Payment Estimate.

Revision 4/1/2020 Page 28 of 36



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
	2-2-1	Туре	Adjustment Type	Number	Date	Ву		
0870	SLAB ON CONCRETE I-GIRDER	Material		10	Aug 3, 2020	SYSTEM	(\$65,025.00)	
				10	Aug 3, 2020	SYSTEM	\$65,025.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user leez1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
				11	Aug 17, 2020	SYSTEM	(\$65,025.00)	
				11	Aug 17, 2020	SYSTEM	\$65,025.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user leez1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	Total	Matarial		-	M 40	OVOTEM	\$0.00	
0880	SAFETY BARRIER CURB	Material		5	May 18, 2020	SYSTEM	(\$18,120.00)	
				5	May 18, 2020	SYSTEM	\$18,120.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user leez1 overridding Payment Estimate Exception 49 on the current Payment Estimate.
				6	Jun 2, 2020	SYSTEM	(\$18,120.00)	
				6	Jun 2, 2020	SYSTEM	\$18,120.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user leez1 overridding Payment Estimate Exception 48 on the current Payment Estimate.
				7	Jun 16, 2020	SYSTEM	(\$18,120.00)	
				7	Jun 16, 2020	SYSTEM	\$18,120.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user leez1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
				8	Jul 1, 2020	SYSTEM	(\$18,120.00)	
				8	Jul 1, 2020	SYSTEM	\$18,120.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user leez1 overridding Payment Estimate Exception 59 on the current Payment Estimate.
				9	Jul 16, 2020	SYSTEM	(\$18,120.00)	
				9	Jul 16, 2020	SYSTEM	\$18,120.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user leez1 overridding Payment Estimate Exception 69 on the current Payment Estimate.
				10	Aug 3, 2020	SYSTEM	(\$18,120.00)	
				10	Aug 3, 2020	SYSTEM	\$18,120.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user leez1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
				11	Aug 17, 2020	SYSTEM	(\$18,120.00)	
				11	Aug 17, 2020	SYSTEM	\$18,120.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user leez1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	Total						\$0.00	
0940	POROUS BACKFILL	Material		10	Aug 3, 2020	SYSTEM	(\$3,672.00)	
				10	Aug 3, 2020	SYSTEM	\$3,672.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	

Revision 4/1/2020 Page 29 of 36



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0940 -	Total						\$0.00	
0990	FURNISHING TYPE 2 ROCK BLANKET	Material		9	Jul 16, 2020	SYSTEM	(\$7,280.00)	
				9	Jul 16, 2020	SYSTEM	\$7,280.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user leez1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0990 -	Total						\$0.00	
1010	CONSTRUCTION SIGNS	Material		8	Jul 1, 2020	SYSTEM	(\$2,624.00)	
				8	Jul 1, 2020	SYSTEM	\$2,624.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user leez1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				9	Jul 16, 2020	SYSTEM	(\$2,624.00)	
				9	Jul 16, 2020	SYSTEM	\$2,624.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user leez1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1010 -	Total						\$0.00	
1020	ADVANCED WARNING RAIL SYSTEM	Material		8	Jul 1, 2020	SYSTEM	(\$140.00)	
				8	Jul 1, 2020	SYSTEM	\$140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user leez1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				9	Jul 16, 2020	SYSTEM	(\$140.00)	
				9	Jul 16, 2020	SYSTEM	\$140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user leez1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1020 -	Total						\$0.00	
1030	FLAG ASSEMBLY	Material		8	Jul 1, 2020	SYSTEM	(\$80.00)	
				8	Jul 1, 2020	SYSTEM	\$80.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user leez1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				9	Jul 16, 2020	SYSTEM	(\$80.00)	
				9	Jul 16, 2020	SYSTEM	\$80.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user leez1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1030 -	Total						\$0.00	
1040	TYPE III MOVEABLE BARRICADE	Material		8	Jul 1, 2020	SYSTEM	(\$1,000.00)	
				8	Jul 1, 2020	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user leez1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
				9	Jul 16, 2020	SYSTEM	(\$1,000.00)	
				9	Jul 16, 2020	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user leez1 overridding Payment Estimate Exception 21 on the current Payment Estimate.

Revision 4/1/2020 Page 30 of 36



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1040		Material	- Total				\$0.00	
	Material - Total						\$0.00	
1040 -	Total						\$0.00	
1130	15 IN. PIPE GROUP C	Material		9	Jul 16, 2020	SYSTEM	(\$1,920.00)	
				9	Jul 16, 2020	SYSTEM	\$1,920.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user leez1 overridding Payment Estimate Exception 89 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1130 -	Total						\$0.00	
1140	24 IN. PIPE GROUP C	Material		9	Jul 16, 2020	SYSTEM	(\$3,360.00)	
				9	Jul 16, 2020	SYSTEM	\$3,360.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user leez1 overridding Payment Estimate Exception 90 on the current Payment Estimate.
				10	Aug 3, 2020	SYSTEM	(\$3,360.00)	
				10	Aug 3, 2020	SYSTEM	\$3,360.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user leez1 overridding Payment Estimate Exception 54 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1140 -	Total						\$0.00	
1240	TYPE C CRASHWORTHY END TERMINAL	Construction Stockpile		1	Mar 16, 2020	SYSTEM	\$32,700.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$32,700.00	
	Construction Stockpile - Total						\$32,700.00	
1240 -	Total						\$32,700.00	
1280	GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN)	Material		8	Jul 1, 2020	SYSTEM	(\$24,794.00)	
				8	Jul 1, 2020	SYSTEM	\$24,794.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user leez1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
				9	Jul 16, 2020	SYSTEM	(\$41,160.00)	
				9	Jul 16, 2020	SYSTEM	\$41,160.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0034) due to user leez1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
				10	Aug 3, 2020	SYSTEM	(\$41,160.00)	
				10	Aug 3, 2020	SYSTEM	\$41,160.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user leez1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
				11	Aug 17, 2020	SYSTEM	(\$41,160.00)	
				11	Aug 17, 2020	SYSTEM	\$41,160.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user leez1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1280 -	Total						\$0.00	
1300	CLASS B CONCRETE (SUBSTRUCTURE)	Material		9	Jul 16, 2020	SYSTEM	(\$24,400.00)	
				9	Jul 16, 2020	SYSTEM	\$24,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0035) due to user leez1 overridding Payment Estimate Exception 44 on the current Payment Estimate.

Revision 4/1/2020 Page 31 of 36



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
	2300.19.00.	Туре	Adjustment Type		Date	By	. Should	, contains
1300	CLASS B CONCRETE (SUBSTRUCTURE)	Material		10	Aug 3, 2020	SYSTEM	(\$24,400.00)	
				10	Aug 3, 2020	SYSTEM	\$24,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user leez1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
				11	Aug 17, 2020	SYSTEM	(\$24,400.00)	
				11	Aug 17, 2020	SYSTEM	\$24,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user leez1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	·Total						\$0.00	
1310	SAFETY BARRIER CURB	Material		10	Aug 3, 2020		(\$16,800.00)	
				10	Aug 3, 2020	SYSTEM	\$16,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user leez1 overridding Payment Estimate Exception 44 on the current Payment Estimate.
				11	Aug 17, 2020	SYSTEM	(\$16,800.00)	
				11	Aug 17, 2020	SYSTEM	\$16,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user leez1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	·Total						\$0.00	
1320	SLAB ON CONCRETE BEAM	Material		10	Aug 3, 2020	SYSTEM	(\$62,400.00)	
				10	Aug 3, 2020	SYSTEM	\$62,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user leez1 overridding Payment Estimate Exception 47 on the current Payment Estimate.
				11	Aug 17, 2020	SYSTEM	(\$62,400.00)	
				11	Aug 17, 2020	SYSTEM	\$62,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user leez1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	·Total						\$0.00	
1390	POROUS BACKFILL	Material		9	Jul 16, 2020	SYSTEM	(\$3,536.00)	
				9	Jul 16, 2020	SYSTEM	\$3,536.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0036) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				10	Aug 3, 2020	SYSTEM	(\$3,536.00)	
				10	Aug 3, 2020	SYSTEM	\$3,536.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	·Total						\$0.00	
1410	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		9	Jul 16, 2020	SYSTEM	(\$2,870.00)	
				9	Jul 16, 2020	SYSTEM	\$2,870.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0037) due to user leez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
			- Total				\$0.00	
2	on 4/1/2020							Page 32 of 3

Revision 4/1/2020 Page 32 of 36



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1410	Material - Total						\$0.00	
1410 -	Total						\$0.00	
1420	GRAVEL (A) OR CRUSHED STONE (B)	Material		10	Aug 3, 2020	SYSTEM	(\$270.00)	
				10	Aug 3, 2020	SYSTEM	\$270.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user leez1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1420 -							\$0.00	
1440	PIPE COLLAR, TYPE B	Material		7	Jun 16, 2020	SYSTEM	(\$1,000.00)	
				7	Jun 16, 2020	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user leez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				8	Jul 1, 2020	SYSTEM	(\$1,000.00)	
				8	Jul 1, 2020	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0034) due to user leez1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				9	Jul 16, 2020	SYSTEM	(\$2,000.00)	
				9	Jul 16, 2020	SYSTEM	\$2,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0038) due to user leez1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1440 -	Total						\$0.00	
1450	FURNISHING TYPE 1 ROCK DITCH LINER	Material		9	Jul 16, 2020	SYSTEM	(\$220.00)	
				9	Jul 16, 2020	SYSTEM	\$220.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0039) due to user leez1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1450 -	Total						\$0.00	
1620	24 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION	Material		7	Jun 16, 2020	SYSTEM	(\$350.00)	
				7	Jun 16, 2020	SYSTEM	\$350.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user leez1 overridding Payment Estimate Exception 47 on the current Payment Estimate.
				8	Jul 1, 2020	SYSTEM	(\$350.00)	
				8	Jul 1, 2020	SYSTEM	\$350.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0035) due to user leez1 overridding Payment Estimate Exception 74 on the current Payment Estimate.
				9		SYSTEM	\$350.00 (\$700.00)	Payment Estimate Item Adjustment (0035) due to user leez1 overridding Payment Estimate Exception 74 on the current
					2020 Jul 16,			Payment Estimate Item Adjustment (0035) due to user leez1 overridding Payment Estimate Exception 74 on the current
				9	Jul 16, 2020 Jul 16,	SYSTEM	(\$700.00)	Payment Estimate Item Adjustment (0035) due to user leez1 overridding Payment Estimate Exception 74 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0040) due to user leez1 overridding Payment Estimate Exception 91 on the current
				9	Jul 16, 2020 Jul 16, 2020 Aug 3,	SYSTEM	(\$700.00) \$700.00	Payment Estimate Item Adjustment (0035) due to user leez1 overridding Payment Estimate Exception 74 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0040) due to user leez1 overridding Payment Estimate Exception 91 on the current

Revision 4/1/2020 Page 33 of 36



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1620	24 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION	Material		11	Aug 17, 2020	SYSTEM	\$700.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user leez1 overridding Payment Estimate Exception 43 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1620 -	Total						\$0.00	
1720	TYPE C CRASHWORTHY END TERMINAL	Construction Stockpile		1	Mar 16, 2020	SYSTEM	\$32,700.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				11	Aug 17, 2020	SYSTEM	(\$32,700.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		- Total				\$0.00		
	Construction Stockpile - Total						\$0.00	
	TYPE C CRASHWORTHY END TERMINAL	Material		11	Aug 17, 2020	SYSTEM	(\$64,000.00)	
				11	Aug 17, 2020	SYSTEM	\$64,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		- Total				\$0.00		
	Material - Total						\$0.00	
1720 -	Total						\$0.00	
1760	GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN)	Material		6	Jun 2, 2020	SYSTEM	(\$21,000.00)	
				6	Jun 2, 2020	SYSTEM	\$21,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user leez1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
				7	Jun 16, 2020	SYSTEM	(\$37,875.00)	
				7	Jun 16, 2020	SYSTEM	\$37,875.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user leez1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				8	Jul 1, 2020	SYSTEM	(\$37,875.00)	
				8	Jul 1, 2020	SYSTEM	\$37,875.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user leez1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
				9	Jul 16, 2020	SYSTEM	(\$37,875.00)	
				9	Jul 16, 2020	SYSTEM	\$37,875.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0041) due to user leez1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
				10	Aug 3, 2020	SYSTEM	(\$37,875.00)	
				10	Aug 3, 2020	SYSTEM	\$37,875.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user leez1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
				11	Aug 17, 2020	SYSTEM	(\$37,875.00)	
				11	Aug 17, 2020	SYSTEM	\$37,875.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user leez1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1760 -	Total						\$0.00	
1790	CLASS B CONCRETE (SUBSTRUCTURE)	Material		7	Jun 16, 2020	SYSTEM	(\$24,100.00)	
				7	Jun 16, 2020	SYSTEM	\$24,100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user leez1 overridding Payment Estimate Exception 20 on the current Payment Estimate.

Revision 4/1/2020 Page 34 of 36



Lina	Description	A diugtes and	Other	E-+	Crostad	Crostad	Amarint	Domestre
Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1790	CLASS B CONCRETE (SUBSTRUCTURE)	Material		8	Jul 1, 2020	SYSTEM	(\$24,100.00)	
				8	Jul 1, 2020	SYSTEM	\$24,100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user leez1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
				9	Jul 16, 2020	SYSTEM	(\$24,100.00)	
				9	Jul 16, 2020	SYSTEM	\$24,100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0042) due to user leez1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
				10	Aug 3, 2020	SYSTEM	(\$24,100.00)	
				10	Aug 3, 2020	SYSTEM	\$24,100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user leez1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
				11	Aug 17, 2020	SYSTEM	(\$24,100.00)	
				11	Aug 17, 2020	SYSTEM	\$24,100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user leez1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1790 -	Total						\$0.00	
1800	SLAB ON CONCRETE I-GIRDER	Material		8	Jul 1, 2020	SYSTEM	(\$68,000.00)	
				8	Jul 1, 2020	SYSTEM	\$68,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user leez1 overridding Payment Estimate Exception 51 on the current Payment Estimate.
				9	Jul 16, 2020	SYSTEM	(\$68,000.00)	
				9	Jul 16, 2020	SYSTEM	\$68,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user leez1 overridding Payment Estimate Exception 61 on the current Payment Estimate.
				10	Aug 3, 2020	SYSTEM	(\$68,000.00)	
				10	Aug 3, 2020	SYSTEM	\$68,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user leez1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
				11	Aug 17, 2020	SYSTEM	(\$68,000.00)	
				11	Aug 17, 2020	SYSTEM	\$68,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user leez1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1800 -	Total						\$0.00	
1810	SAFETY BARRIER CURB	Material		9	Jul 16, 2020	SYSTEM	(\$18,360.00)	
				9	Jul 16, 2020	SYSTEM	\$18,360.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user leez1 overridding Payment Estimate Exception 74 on the current Payment Estimate.
				10	Aug 3, 2020	SYSTEM	(\$18,360.00)	
				10	Aug 3, 2020	SYSTEM	\$18,360.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user leez1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
				11	Aug 17, 2020	SYSTEM	(\$18,360.00)	
				11	Aug 17,	SYSTEM	\$18,360.00	This adjustment offsets the original system-generated Overrun

Revision 4/1/2020 Page 35 of 36



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1810	SAFETY BARRIER CURB	Material			2020			Payment Estimate Item Adjustment (0012) due to user leez1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
		- Total				\$0.00		
	Material - Total						\$0.00	
1810 -	810 - Total						\$0.00	
1830	STEEL INTERMEDIATE DIAPHRAGM FOR P/S CONCRETE GIRDERS	Material		8	Jul 1, 2020	SYSTEM	(\$1,725.00)	
				8	Jul 1, 2020	SYSTEM	\$1,725.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user leez1 overridding Payment Estimate Exception 73 on the current Payment Estimate.
				9	Jul 16, 2020	SYSTEM	(\$1,725.00)	
				9	Jul 16, 2020	SYSTEM	\$1,725.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0043) due to user leez1 overridding Payment Estimate Exception 88 on the current Payment Estimate.
	- Total						\$0.00	
	Material - Total						\$0.00	
1830 - Total							\$0.00	
Overall - Total							\$32,873.11	

Revision 4/1/2020 Page 36 of 36