

Pay Estimate Created Date: December 16, 2020

Progress Estin		Contract ID Prime Contractor	200117-H07 Apex Paving Co.	•	December 2, 2020 December 15, 202		\$8,709,119.25 \$775,080.27 \$9,484,199.52
Approval Date							By User
December 16, 2020			Generated and Ap	proved (and should	be considered Draf	t) at the Project Office Level by	woodsk1
December 17, 2020		Rev	iewed and Approve	ed (and should be c	onsidered Draft) at	he Resident Engineer Level by	holtb1
December 18, 2020			Re	eviewed and Approv	red at the Central O	ffice Controllers Office Level by	greggd1
Original Comp	oletion Date	Current Comp	letion Date	Actual Complet	ion Date	% of Current Contract Amou	nt Complete
July 1, 2	2021	July 1, 2	2021			56.89%	

No Milestones Exist for Contract

Contract Total Pa	ay For Estimate No. 17			
		This Estimate	Previous	To Date
200117-H07				
	Total Posted Items Pay	\$514,837.92	\$4,880,906.73	\$5,395,744.65
	Gross Item Adjustments	\$15.06	\$155,082.21	\$155,097.27
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	•		\$5,035,988.94	\$5,550,841.92
Contract Total Pa	ayable This Estimate:	\$514,852.98		

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J9I3553	0210	6161025	CHANNELIZER (TRIM LINE)	EA	\$15.000	123	\$1,845.00
	0780	7040104	HALF-SOLE REPAIR	SQFT	\$107.410	1,872	\$201,071.52
	0820	7040104	HALF-SOLE REPAIR	SQFT	\$107.410	2,564	\$275,399.24
	5004	7040107	SLAB EDGE REPAIR (BRIDGES)	LF	\$245.390	22	\$5,398.58
	5005	7040107	SLAB EDGE REPAIR (BRIDGES)	LF	\$245.390	31	\$7,607.09
Project J9I355	3 - Total						\$491,321.43
J9S3571	0870	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	TONS	\$56.260	325.5	\$18,312.63
	0880	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	TONS	\$60.510	86	\$5,203.86
Project J9S35	71 - Total						\$23,516.49
Overall - Tota							\$514,837.92

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

		stments Exist on Contract						
Line Item	<u>Adjust</u>	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9I3553	0020	MISC.	Material			-1,642	\$32.62	(\$53,562.04)
	0020	MISC.	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	1,642	\$32.62	\$53,562.04
	0050	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Material			-1,585.9	\$57.84	(\$91,728.46)
	0050	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 3 on	1,585.9	\$57.84	\$91,728.46

Revision 4/1/2020 Page 1 of 61



Pay Estimate Created Date: December 16, 2020

Progress Estimate Number	Contract ID			,	Original Contract Amount	, ,
17	Prime Contractor	Apex Paving Co.	Pay Period End	December 15, 2020	Net Change Order Amount	\$775,080.27
11					Current Contract Amount	\$9,484,199.52

er	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
53					the current Payment Estimate.			
	0100	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material			-489.9	\$185.16	(\$90,709.88)
	0100	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	489.9	\$185.16	\$90,709.88
	0110	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	Material			-10	\$10.00	(\$100.00)
	0110	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	10	\$10.00	\$100.00
	0120	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	Material			-10	\$10.00	(\$100.00)
	0120	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	10	\$10.00	\$100.00
	0140	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material			-822	\$10.00	(\$8,220.00)
	0140	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	822	\$10.00	\$8,220.00
	0410	SEAL COAT AGGREGATE, GRADE B1	Material			-265	\$5.00	(\$1,325.00)
	0410	SEAL COAT AGGREGATE, GRADE B1	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	265	\$5.00	\$1,325.00
	0420	CURB BLOCKOUT	Material			-170	\$196.14	(\$33,343.80)
	0420	CURB BLOCKOUT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 33 on the current Payment Estimate.	170	\$196.14	\$33,343.80
	0430	HALF-SOLE REPAIR	Material			-755	\$97.74	(\$73,793.70)
	0430	HALF-SOLE REPAIR	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 52 on the current Payment Estimate.	755	\$97.74	\$73,793.70
	0460	SEAL COAT AGGREGATE, GRADE B1	Material			-288	\$5.00	(\$1,440.00)
	0460	SEAL COAT AGGREGATE, GRADE B1	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1	288	\$5.00	\$1,440.00

Revision 4/1/2020 Page 2 of 61



Pay Estimate Created Date: December 16, 2020

Progress Estimate Number	Contract ID			,	Original Contract Amount	, ,
17	Prime Contractor	Apex Paving Co.	Pay Period End	December 15, 2020	Net Change Order Amount	\$775,080.27
11					Current Contract Amount	\$9,484,199.52

ect	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
553					overridding Payment Estimate Exception 6 on the current Payment Estimate.			
	0470	CURB BLOCKOUT	Material			-185	\$193.61	(\$35,817.85)
	0470	CURB BLOCKOUT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.	185	\$193.61	\$35,817.85
	0480	HALF-SOLE REPAIR	Material			-723	\$96.76	(\$69,957.48)
	0480	HALF-SOLE REPAIR	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 47 on the current Payment Estimate.	723	\$96.76	\$69,957.48
	0520	CURB BLOCKOUT	Material			-170	\$196.14	(\$33,343.80)
	0520	CURB BLOCKOUT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 27 on the current Payment Estimate.	170	\$196.14	\$33,343.80
	0530	HALF-SOLE REPAIR	Material			-853	\$97.74	(\$83,372.22)
	0530	HALF-SOLE REPAIR	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 51 on the current Payment Estimate.	853	\$97.74	\$83,372.22
	0570	CURB BLOCKOUT	Material			-155	\$199.15	(\$30,868.25)
	0570	CURB BLOCKOUT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate.	155	\$199.15	\$30,868.25
	0780	HALF-SOLE REPAIR	Material			-2,272	\$107.41	(\$244,035.52)
	0780	HALF-SOLE REPAIR	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 46 on the current Payment Estimate.	2,272	\$107.41	\$244,035.52
	0820	HALF-SOLE REPAIR	Material			-2,964	\$107.41	(\$318,363.24)
	0820	HALF-SOLE REPAIR	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 45 on the current Payment Estimate.	2,964	\$107.41	\$318,363.24
	5004	SLAB EDGE REPAIR (BRIDGES)	Material			-22	\$245.39	(\$5,398.58)
	5004	SLAB EDGE REPAIR (BRIDGES)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 55 on the current Payment Estimate.	22	\$245.39	\$5,398.58
	5005	SLAB EDGE REPAIR (BRIDGES)	Material			-31	\$245.39	(\$7,607.09)
	5005	SLAB EDGE REPAIR (BRIDGES)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 56 on the current Payment Estimate.	31	\$245.39	\$7,607.09

Revision 4/1/2020 Page 3 of 61



Pay Estimate Created Date: December 16, 2020

Progress Estimate Number	Contract ID			,		\$8,709,119.25
17	Prime Contractor	Apex Paving Co.	Pay Period End	December 15, 2020	Net Change Order Amount	\$775,080.27
"					Current Contract Amount	\$9,484,199.52

ject nber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
3571	0850	MISC.	Material			-1,817.86	\$35.59	(\$64,697.64
	0850	MISC.	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	1,817.86	\$35.59	\$64,697.64
	0870	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Other Item Adjustment	Asphalt Cement Price Adjustment	*See Attached AC Price Index Adjustment Sheet.			\$8.06
	0880	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Other Item Adjustment	Asphalt Cement Price Adjustment	*See Attached AC Price Index Adjustment Sheet.			\$7.00
	0900	BITUMINOUS FOG SEAL	Material			-4,800	\$4.15	(\$19,920.00
	0900	BITUMINOUS FOG SEAL	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	4,800	\$4.15	\$19,920.00
	0990	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	Material			-1,212	\$2.00	(\$2,424.00
	0990	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	1,212	\$2.00	\$2,424.00
	1000	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	Material			-2,000	\$2.00	(\$4,000.00
	1000	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	2,000	\$2.00	\$4,000.00
	1010	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	Material			-24	\$10.00	(\$240.00
	1010	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	24	\$10.00	\$240.00
	1020	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-114,312	\$0.11	(\$12,574.32
	1020	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	114,312	\$0.11	\$12,574.32
	1030	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-31,999	\$0.11	(\$3,519.89
	1030	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1	31,999	\$0.11	\$3,519.89

Revision 4/1/2020 Page 4 of 61

\$15.06



Total

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: December 16, 2020

Progr		timate Number 17	Contract IE Prime Con	2001 tractor Apex	I17-H07 x Paving Co.	Pay Period Start Pay Period End	December 2, 2020 December 15, 2020	Net Cl	al Contract A hange Order nt Contract A	Amount \$	8,709,119.25 775,080.27 9,484,199.52
Project Number	Line No.	Item Desc	ription	Adjustment Type	Other Item Adjustment Type		Comments		Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9S3571			BEADS				yment Estimate Excep ne current Payment Es				
	1140	SEAL COAT A	GGREGATE, GRADE B1	Material					-287	\$5.00	(\$1,435.00)
	1140	SEAL COAT AG	GGREGATE, GRADE B1	Material		generated Ove Adjustment overridding Payn	nt offsets the original serrun Payment Estimat t (0027) due to user w nent Estimate Excepti ne current Payment Es	nte Item oodsk1 on 5 on	287	\$5.00	\$1,435.00
	1150		TRUCTURE JNFORMED)	Material					-31	\$311.16	(\$9,645.96)
	1150		TRUCTURE JNFORMED)	Material		generated Ove Adjustment overridding Pay	nt offsets the original s errun Payment Estima t (0028) due to user w yment Estimate Excep ne current Payment Es	ote Item oodsk1 otion 44	31	\$311.16	\$9,645.96
	1160	SLAB ED	GE REPAIR (BRIDGES)	Material					-60	\$245.39	(\$14,723.40)
	1160	SLAB EC	OGE REPAIR (BRIDGES)	Material		generated Ove Adjustment overridding Pay	nt offsets the original serrun Payment Estimat t (0029) due to user w yment Estimate Excep ne current Payment Es	oodsk1 otion 57	60	\$245.39	\$14,723.40

Revision 4/1/2020 Page 5 of 61



					Cor	ntract Project Information	1
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J9I3553	FAF 60-4(86)	Resurface	60	SCOTT	from I-57 to Spring Creek	k	
J9S3571	FAS S703(31)	Resurface	69	MISSISSIPPI	from I-57 to Bridge K095	0	
Totals by	Job Numbe	rs					
J9I3553		d Item Pay Item Adjustm		s Item Pay	This Estimate \$491,321.43 \$0.00 \$491,321.43	Previous \$3,206,823.00 \$84,634.26 \$3,291,457.26	To Date \$3,698,144.43 \$84,634.26 \$3,782,778.69
	Liquid	tive centive lated Damages Contract Adju		i	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00
J9S3571		d Item Pay Item Adjustm		s Item Pay	This Estimate \$23,516.49 \$15.06 \$23,531.55	Previous \$1,674,083.73 \$70,447.95 \$1,744,531.68	To Date \$1,697,600.22 \$70,463.01 \$1,768,063.23
	Liquid	tive centive lated Damages Contract Adiu			\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00

Revision 4/1/2020 Page 6 of 61



Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J9S3571, Item 3049910, Project Item Line Number 0850, Material Set 304991096, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 3049910, Project Item Line Number 0020, Material Set 304991096, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 4030103, Project Item Line Number 0050, Material Set 403010396, Material 0403SP125CLG - Superpave 12.5 mm, Des C 80 Gyros, Acceptance Action Generic AspHigh is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 4094011, Project Item Line Number 0410, Material Set 409401196, Material 1003GB - Aggregate for Seal Coat Grade B1, Acceptance Action Generic 1003GB is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3571, Item 4094011, Project Item Line Number 1140, Material Set 409401196, Material 1003GB - Aggregate for Seal Coat Grade B1, Acceptance Action Generic 1003GB is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 4094011, Project Item Line Number 0460, Material Set 409401196, Material 1003GB - Aggregate for Seal Coat Grade B1, Acceptance Action Generic 1003GB is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3571, Item 4134000, Project Item Line Number 0900, Material Set 413400096, Material 1015EACSS1H - Emulsified Asphalt CSS-1H, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 6131010, Project Item Line Number 0100, Material Set 613101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 6131010, Project Item Line Number 0100, Material Set 613101096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 6131010, Project Item Line Number 0100, Material Set 613101096, Material 0501CCPAEA - Concrete, Pavement HES w/Air, Acceptance Action 0501CCPAEA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 6131012, Project Item Line Number 0110, Material Set 613101296, Material 0200XXCS - Compacted Soil for Subgrade orEmbankment, Acceptance Action Generic 0200XXCS is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 6131013, Project Item Line Number 0120, Material Set 613101396, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 6131015, Project Item Line Number 0140, Material Set 613101596, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3571, Item 6205301B, Project Item Line Number 0990, Material Set 6205301B96, Material 1048PMT - Marking Tape, Acceptance Action Generic 1048PMT is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3571, Item 6205303B, Project Item Line Number 1000, Material Set 6205303B96, Material 1048PMT - Marking Tape, Acceptance Action Generic 1048PMT is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3571, Item 6205309, Project Item Line Number 1010, Material Set 620530996, Material 1048PMT - Marking Tape, Acceptance Action Generic 1048PMT is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3571, Item 6206000C, Project Item Line Number 1020, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3571, Item 6206000C, Project Item Line Number 1020, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3571, Item 6206001C, Project Item Line Number 1030, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3571, Item 6206001C, Project Item Line Number 1030, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 1039ERRAS - Epoxy Bonding Agent-Resin Anchor Systems, Acceptance Action Generic 1039ERRAS is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action	No Remark was entered by Engineer	woodsk1	Overridden

Revision 4/1/2020 Page 7 of 61



Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Generic 0501CCB1.A is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J913553, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913553, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0520, Material Set 703460096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7034600, Project Item Line Number 0520, Material Set 703460096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0520, Material Set 703460096, Material 1039ERRAS - Epoxy Bonding Agent-Resin Anchor Systems, Acceptance Action Generic 1039ERRAS is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0520, Material Set 703460096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913553, Item 7034600, Project Item Line Number 0520, Material Set 703460096, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913553, Item 7034600, Project Item Line Number 0520, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913553, Item 7034600, Project Item Line Number 0420, Material Set 703460096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7034600, Project Item Line Number 0420, Material Set 703460096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913553, Item 7034600, Project Item Line Number 0420, Material Set 703460096, Material 1039ERRAS - Epoxy Bonding Agent-Resin Anchor Systems, Acceptance Action Generic 1039ERRAS is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913553, Item 7034600, Project Item Line Number 0420, Material Set 703460096, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0420, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0470, Material Set 703460096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7034600, Project Item Line Number 0470, Material Set 703460096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0470, Material Set 703460096, Material 1039ERRAS - Epoxy Bonding Agent-Resin Anchor Systems, Acceptance Action Generic 1039ERRAS is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0470, Material Set 703460096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7034600, Project Item Line Number 0470, Material Set 703460096, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0470, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3571, Item 7040103, Project Item Line Number 1150, Material Set 704010396, Material 4066SPSM - Special Provision Special Mortar, Acceptance Action Generic 4066SPSM is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7040104, Project Item Line Number 0820, Material Set 704010496, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7040104, Project Item Line Number 0780, Material Set 704010496, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7040104, Project Item Line Number 0480, Material Set 704010496, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7040104, Project Item Line Number	No Remark was entered by Engineer	woodsk1	Overridden

Revision 4/1/2020 Page 8 of 61



Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
0480, Material Set 704010496, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7040104, Project Item Line Number 0480, Material Set 704010496, Material 0500XX - Concrete Plant Inspection Review, Acceptance Action Generic 0500XX is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7040104, Project Item Line Number 0480, Material Set 704010496, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7040104, Project Item Line Number 0530, Material Set 704010496, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7040104, Project Item Line Number 0430, Material Set 704010496, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7040104, Project Item Line Number 0430, Material Set 704010496, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7040104, Project Item Line Number 0430, Material Set 704010496, Material 0500XX - Concrete Plant Inspection Review, Acceptance Action Generic 0500XX is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7040107, Project Item Line Number 5004, Material Set 704010796, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7040107, Project Item Line Number 5005, Material Set 704010796, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3571, Item 7040107, Project Item Line Number 1160, Material Set 704010796, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden

Revision 4/1/2020 Page 9 of 61



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200117-H07	J9I3553	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.26	\$36,000.00	\$9,504.00
		0001	0020	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	6,032.50	0.00	6,032.50	TONS	1,642.00	\$32.62	\$53,562.04
		0001	0030	3105002	GRAVEL (A) OR CRUSHED STONE (B)	17.00	0.00	17.00	TONS	0.00	\$18.91	\$0.00
		0001	0040	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	16,232.80	0.00	16,232.80	TONS	6,568.80	\$56.39	\$370,414.63
		0001	0050	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	62,977.90	0.00	62,977.90	TONS	25,585.90	\$57.84	\$1,479,888.46
		0001	0060	4071005	TACK COAT	60,125.00	0.00	60,125.00	GAL	22,653.00	\$2.14	\$48,477.42
		0001	0070	4134000	BITUMINOUS FOG SEAL	5,508.00	0.00	5,508.00	GAL	0.00	\$5.11	\$0.00
		0001	0080	6083003	3 IN. CONCRETE MEDIAN STRIP	2,330.00	0.00	2,330.00	SQYD	0.00	\$67.62	\$0.00
		0001	0090	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$500.00	\$0.00
		0001	0100	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	642.70	0.00	642.70	SQYD	566.80	\$185.16	\$104,948.69
		0001	0110	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	64.00	0.00	64.00	SQYD	10.00	\$10.00	\$100.00
		0001	0120	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	64.00	0.00	64.00	SQYD	10.00	\$10.00	\$100.00
		0001	0130	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	2,204.00	0.00	2,204.00	LF	1,665.00	\$6.00	\$9,990.00
		0001	0140	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	1,180.00	0.00	1,180.00	EA	822.00	\$10.00	\$8,220.00
		0001	0150	6131017	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	10.00	0.00	10.00	EA	1.00	\$10.00	\$10.00
		0001	0160	6133020	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	13.10	0.00	13.10	TONS	0.00	\$532.33	\$0.00
		0001	0170	6133021	REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	28.00	0.00	28.00	SQYD	0.00	\$103.80	\$0.00
		0001	0180	6161005	CONSTRUCTION SIGNS	3,888.00	0.00	3,888.00	SQFT	2,948.00	\$6.50	\$19,162.00
		0001	0190	6161008	ADVANCED WARNING RAIL SYSTEM	2.00	0.00	2.00	EA	0.00	\$45.00	\$0.00
		0001	0200	6161009	FLAG ASSEMBLY	4.00	0.00	4.00	EA	0.00	\$20.00	\$0.00
		0001	0210	6161025	CHANNELIZER (TRIM LINE)	712.00	0.00	712.00	EA	385.00	\$15.00	\$5,775.00
		0001	0220	6161030	TYPE III MOVEABLE BARRICADE	45.00	0.00	45.00	EA	0.00	\$100.00	\$0.00
		0001	0230	6161033	DIRECTIONAL INDICATOR BARRICADE	133.00	0.00	133.00	EA	76.00	\$35.00	\$2,660.00
		0001	0240	6161040	FLASHING ARROW PANEL	8.00	0.00	8.00	EA	4.00	\$400.00	\$1,600.00
		0001	0250	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$3,500.00	\$7,000.00
		0001	0260	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$208,790.05	\$208,790.05
		0001	0270	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	205,637.00	0.00	205,637.00	LF	0.00	\$0.23	\$0.00
		0001	0280	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	161,998.00	0.00	161,998.00	LF	0.00	\$0.23	\$0.00
		0001	0290	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	2,400.00	0.00	2,400.00	LF	0.00	\$1.00	\$0.00
		0001	0300	6209901	MISC.TEMPORARY PAVEMENT MARKING PAINT	1.00	0.00	1.00	LS	1.00	\$15,000.00	\$15,000.00
		0001	0310	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	18,810.00	0.00	18,810.00	SQYD	5,824.60	\$6.49	\$37,801.65
		0001	0320	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	22,495.00	0.00	22,495.00	SQYD	11,824.00	\$7.25	\$85,724.00
		0001	0330	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	3,038.00	0.00	3,038.00	STA	0.00	\$18.75	\$0.00
		0001	0340	7034001	CLASS B-1 CONCRETE	3.30	0.00	3.30	CUYD	0.00	\$2,400.00	\$0.00
		0010	0350	6061060	MGS GUARDRAIL	8,050.00	0.00	8,050.00	LF	4,350.00	\$20.00	\$87,000.00
		0010	0360	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	24.00	0.00	24.00	EA	10.00	\$2,900.00	\$29,000.00
		0010	0370	6061080	MGS END ANCHOR	6.00	0.00	6.00	EA	6.00	\$1,000.00	\$6,000.00
		0010	0380	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	30.00	0.00	30.00	EA	16.00	\$2,700.00	\$43,200.00
		0040	0390	9031220	PIPE POSTS	820.00	0.00	820.00	LB	0.00	\$6.00	\$0.00
		0070	0400	4091048	EMULSIFIED ASPHALT, SEAL COAT	106.00	0.00	106.00	GAL	106.00	\$5.00	\$530.00
		0070	0410	4094011	SEAL COAT AGGREGATE, GRADE B1	265.00	0.00	265.00	SQYD	265.00	\$5.00	\$1,325.00
		0070	0420	7034600	CURB BLOCKOUT	170.00	0.00	170.00	LF	170.00	\$196.14	\$33,343.80
		0070	0430	7040104	HALF-SOLE REPAIR	240.00	515.00	755.00	SQFT	755.00	\$97.74	\$73,793.70
		0070	0440	7040113	CLEANING AND EPOXY COATING	584.00	0.00	584.00	SQFT	584.00	\$13.00	\$7,592.00

Revision 4/1/2020 Page 10 of 61



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

ct Proje RACT No	ct Catego			Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
7 J9I35	53 0071	0450	4091048	EMULSIFIED ASPHALT, SEAL COAT	115.00	0.00	115.00	GAL	115.00	\$5.00	\$575.00
	0071	0460	4094011	SEAL COAT AGGREGATE, GRADE B1	288.00	0.00	288.00	SQYD	288.00	\$5.00	\$1,440.00
	0071	0470	7034600	CURB BLOCKOUT	185.00	0.00	185.00	LF	185.00	\$193.61	\$35,817.85
	0071	0480	7040104	HALF-SOLE REPAIR	260.00	463.00	723.00	SQFT	723.00	\$96.76	\$69,957.48
	0071	0490	7040113	CLEANING AND EPOXY COATING	628.00	0.00	628.00	SQFT	628.00	\$13.00	\$8,164.00
	0072	0500	4091048	EMULSIFIED ASPHALT, SEAL COAT	106.00	0.00	106.00	GAL	0.00	\$5.00	\$0.00
	0072	0510	4094011	SEAL COAT AGGREGATE, GRADE B1	265.00	0.00	265.00	SQYD	0.00	\$5.00	\$0.00
	0072	0520	7034600	CURB BLOCKOUT	170.00	0.00	170.00	LF	170.00	\$196.14	\$33,343.80
	0072	0530	7040104	HALF-SOLE REPAIR	240.00	613.00	853.00	SQFT	853.00	\$97.74	\$83,372.22
	0072	0540	7040113	CLEANING AND EPOXY COATING	584.00	0.00	584.00	SQFT	0.00	\$13.00	\$0.00
	0073	0550	4091048	EMULSIFIED ASPHALT, SEAL COAT	96.00	0.00	96.00	GAL	0.00	\$5.00	\$0.00
	0073	0560	4094011	SEAL COAT AGGREGATE, GRADE B1	241.00	0.00	241.00	SQYD	0.00	\$5.00	\$0.00
	0073	0570	7034600	CURB BLOCKOUT	155.00	0.00	155.00	LF	155.00	\$199.15	\$30,868.25
	0073	0580	7040104	HALF-SOLE REPAIR	220.00	545.00	765.00	SQFT	765.00	\$98.90	\$75,658.50
	0073	0590	7040113	CLEANING AND EPOXY COATING	534.00	0.00	534.00	SQFT	0.00	\$13.00	\$0.00
	0073	0600	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT	56.00	0.00	56.00	LF	0.00	\$325.00	\$0.00
	0074			CONCRETE							
	0074	0610	2169903	MISC.Remove and Replace Curb	16.00	0.00	16.00	LF	0.00	\$300.00	\$0.00
	0074	0620	4091048	EMULSIFIED ASPHALT, SEAL COAT	348.00	0.00	348.00	GAL	0.00	\$5.00	\$0.00
	0074	0630	4094011	SEAL COAT AGGREGATE, GRADE B1	870.00	0.00	870.00	SQYD	0.00	\$5.00	\$0.00
	0074	0640	7034214	CLASS B-2 CONCRETE	5.60	0.00	5.60	CUYD	0.00	\$5,218.44	\$0.00
	0074	0650	7034600	CURB BLOCKOUT	560.00	0.00	560.00	LF	0.00	\$181.01	\$0.00
	0074	0660	7040104	HALF-SOLE REPAIR	230.00	0.00	230.00	SQFT	0.00	\$98.30	\$0.00
	0074	0670	7040113	CLEANING AND EPOXY COATING	1,971.00	0.00	1,971.00	SQFT	0.00	\$13.00	\$0.00
	0074	0680	7101000	REINFORCING STEEL (EPOXY COATED)	1,820.00	0.00	1,820.00	LB	0.00	\$5.00	\$0.00
	0074	0690	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$5,000.00	\$0.00
	0074	0700	7174001	PREFORMED SILICONE OR EPDM EXPANSION JOINT SYSTEM	56.00	0.00	56.00	LF	0.00	\$75.00	\$0.00
	0075	0710	4091048	EMULSIFIED ASPHALT, SEAL COAT	162.00	0.00	162.00	GAL	0.00	\$5.00	\$0.00
	0075	0720	4094011	SEAL COAT AGGREGATE, GRADE B1	406.00	0.00	406.00	SQYD	0.00	\$5.00	\$0.00
	0075	0730	7034600	CURB BLOCKOUT	261.00	0.00	261.00	LF	0.00	\$189.97	\$0.00
	0075	0740	7040104	HALF-SOLE REPAIR	370.00	0.00	370.00	SQFT	0.00	\$98.22	\$0.00
	0075	0750	7040113	CLEANING AND EPOXY COATING	1,100.00	0.00	1,100.00	SQFT	0.00	\$13.00	\$0.00
	0076	0760	4091048	EMULSIFIED ASPHALT, SEAL COAT	185.00	0.00	185.00	GAL	0.00	\$5.00	\$0.00
	0076	0770	4094011	SEAL COAT AGGREGATE, GRADE B1	463.00	0.00	463.00	SQYD	0.00	\$5.00	\$0.00
	0076	0780	7040104	HALF-SOLE REPAIR	400.00	1,872.00	2,272.00	SQFT	2,272.00	\$107.41	\$244,035.52
	0076	0790	7040113	CLEANING AND EPOXY COATING	989.00	0.00	989.00	SQFT	0.00	\$13.00	\$0.00
	0077	0800	4091048	EMULSIFIED ASPHALT, SEAL COAT	185.00	0.00	185.00	GAL	0.00	\$5.00	\$0.00
	0077	0810	4094011	SEAL COAT AGGREGATE, GRADE B1	463.00	0.00	463.00	SQYD	0.00	\$5.00	\$0.00
	0077	0820	7040104	HALF-SOLE REPAIR	400.00	2,564.00	2,964.00	SQFT	2,964.00	\$107.41	\$318,363.24
	0077	0830	7040113	CLEANING AND EPOXY COATING	989.00	0.00	989.00	SQFT	0.00	\$13.00	\$0.00
	0001	5001	6162004	TEMPORARY SHORT-TERM RUMBLE STRIPS	0.00	4.00	4.00	EA	4.00	\$2,362.50	\$9,450.00
	0001	5002	6161010	RELOCATED SIGNS	0.00	268.00	268.00	SQFT	268.00	\$6.83	\$1,830.44
	0001	5003	6129902	MISC.TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)		22,800.00	22,800.00	EA	21,750.00	\$1.00	\$21,750.00
	0076	5004	7040107	SLAB EDGE REPAIR (BRIDGES)	0.00	22.00	22.00	LF	22.00	\$245.39	\$5,398.58
	0076	5005	7040107	SLAB EDGE REPAIR (BRIDGES)	0.00	31.00	31.00	LF	31.00	\$245.39	\$7,607.09
Proje				ate as of Report Generated Date							\$3,698,144.41
1 10]0	71 0001	0840	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$2,600.00	\$2,600.00

Revision 4/1/2020 Page 11 of 61



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

ontract ONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
7-H07	J9S3571	0001	0850	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	2,161.00	0.00	2,161.00	TONS	1,817.86	\$35.59	\$64,697.64
		0001	0860	3105002	GRAVEL (A) OR CRUSHED STONE (B)	350.00	0.00	350.00	TONS	0.00	\$44.12	\$0.00
		0001	0870	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	3,194.60	325.50	3,520.10	TONS	3,520.10	\$56.26	\$198,040.83
		0001	0880	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	17,210.20	86.00	17,296.20	TONS	17,255.60	\$60.51	\$1,044,136.36
		0001	0890	4071005	TACK COAT	14,965.00	0.00	14,965.00	GAL	12,730.00	\$2.14	\$27,242.20
		0001	0900	4134000	BITUMINOUS FOG SEAL	2,033.00	3,767.00	5,800.00	GAL	4,800.00	\$4.15	\$19,920.00
		0001	0910	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	4.00	0.00	4.00	EA	4.00	\$250.00	\$1,000.00
		0001	0920	6161005	CONSTRUCTION SIGNS	2,364.00	0.00	2,364.00	SQFT	2,364.00	\$6.50	\$15,366.00
		0001	0930	6161009	FLAG ASSEMBLY	7.00	0.00	7.00	EA	7.00	\$20.00	\$140.00
		0001	0940	6161025	CHANNELIZER (TRIM LINE)	186.00	0.00	186.00	EA	40.00	\$15.00	\$600.00
		0001	0950	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$3,500.00	\$7,000.00
		0001	0960	6162000A	WORK ZONE TRAFFIC SIGNAL SYSTEM	1.00	0.00	1.00	EA	1.00	\$8,400.00	\$8,400.00
		0001	0970	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	2.00	0.00	2.00	EA	2.00	\$1,800.00	\$3,600.00
		0001	0980	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$107,079.93	\$107,079.93
		0001	0990	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	1,212.00	0.00	1,212.00	LF	1,212.00	\$2.00	\$2,424.00
		0001	1000	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	2,000.00	0.00	2,000.00	LF	2,000.00	\$2.00	\$4,000.00
		0001	1010	6205309	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	24.00	0.00	24.00	LF	24.00	\$10.00	\$240.00
		0001	1020	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	114,312.00	0.00	114,312.00	LF	114,312.00	\$0.11	\$12,574.32
		0001	1030	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	31,999.00	0.00	31,999.00	LF	31,999.00	\$0.11	\$3,519.89
		0001	1040	6207001	PAVEMENT MARKING REMOVAL	4,006.00	0.00	4,006.00	LF	4,006.00	\$2.00	\$8,012.00
		0001	1050	6209901	MISC.TEMPORARY PAVEMENT MARKING PAINT	1.00	0.00	1.00	LS	0.00	\$0.00	\$0.00
		0001	1060	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	266.00	0.00	266.00	SQYD	266.00	\$8.76	\$2,330.16
		0001	1070	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	3,431.00	0.00	3,431.00	SQYD	3,431.00	\$9.00	\$30,879.00
		0010	1080	6061060	MGS GUARDRAIL	140.00	0.00	140.00	LF	140.00	\$22.00	\$3,080.00
		0010	1090	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	4.00	0.00	4.00	EA	4.00	\$3,000.00	\$12,000.00
		0010	1100	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	4.00	0.00	4.00	EA	4.00	\$2,900.00	\$11,600.00
		0070	1110	2169902	MISC.Removal of Existing End Post	4.00	0.00	4.00	EA	4.00	\$1,250.00	\$5,000.00
		0070	1120	2169903	MISC.Removal of Existing Curb and Guardrail	166.00	0.00	166.00	LF	166.00	\$125.00	\$20,750.00
		0070	1130	4091048	EMULSIFIED ASPHALT, SEAL COAT	115.00	0.00	115.00	GAL	115.00	\$5.00	\$575.00
		0070	1140	4094011	SEAL COAT AGGREGATE, GRADE B1	287.00	0.00	287.00	SQYD	287.00	\$5.00	\$1,435.00
		0070	1150	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	20.00	11.00	31.00	SQFT	31.00	\$311.16	\$9,645.96
		0070	1160	7040107	SLAB EDGE REPAIR (BRIDGES)	60.00	0.00	60.00	LF	60.00	\$245.39	\$14,723.40
		0070	1170	7040113	CLEANING AND EPOXY COATING	308.00	0.00	308.00	SQFT	308.00	\$13.00	\$4,004.00
		0070	1180	7134000	BRIDGE GUARDRAIL (THRIE BEAM)	178.00	0.00	178.00	LF	178.00	\$286.43	\$50,984.54
	Project J	9S3571 - To	otal Value	Posted to D	ate as of Report Generated Date							\$1,697,600.22
-H07 Ove	rall - Total	Value Post	ted to Dat	te as of Repo	ort Generated Date							\$5,395,744.63

Page 12 of 61 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J9I3553

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0210	6161025	CHANNELIZER (TRIM LINE)	12/8/20	12/8/20	123.00	EA	Rte 60 WBL	51.00		53.962		Scott Brooks counted channelizers during the four lane drop set up used for concrete repairs and bridge work. Those quantities totaled £62 channelizers. Scott Brooks and did not count channelizers used during paving operations. Apex/Road Rumer stated that 365 channelizers were used during paving operations. Apex/Road Rumer stated that 365 channelizers were used during paving and bridge work, since Scott Brooks cannot dispute this claim 123 channelizers will be paid bringing the total used to date to 365.
0780	7040104	HALF-SOLE REPAIR	12/14/20	12/16/20	1,872.00	SQFT	Route 60. Bridge L0955.	31.168		31.168		Route 60. Bridge L0955.
0820	7040104	HALF-SOLE REPAIR	12/14/20	12/16/20	2,564.00	SQFT	Route 60. Bridge L0956.	29.461		29.461		Route 60. Bridge L0956.
5004	7040107	SLAB EDGE REPAIR (BRIDGES)	12/14/20	12/16/20	22.00	LF	Route 60. Bridge L0955.	31.168		31.168		Route 60. Bridge L0955.
5005	7040107	SLAB EDGE REPAIR (BRIDGES)	12/14/20	12/16/20	31.00	LF	Route 60. Bridge L0956.	29.461		29.461		Route 60. Bridge L0956.

Project: J9S3571

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0870	4011209	BIT. PAVEMENT MIXTURE PG64-22 (BP-1)	12/14/20	12/16/20	325.50	TONS	Route 60/62.	330.021		340.846		Route 60/62.
0880	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	12/14/20	12/16/20	86.00	TONS	Route 60/62.	331.021		340.846		Route 60/62.

The information below this line are details from Line Item agency views. No Agency View Details Exist

Revision 4/1/2020 Page 13 of 61



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0020	MISC. PERMANENT AGGREGATE EDGE TREATMENT	Material		15	Nov 17, 2020	SYSTEM	(\$53,562.04)	
				15	Nov 17, 2020	SYSTEM	\$53,562.04	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				16	Dec 2, 2020	SYSTEM	(\$53,562.04)	
				16	Dec 2, 2020	SYSTEM	\$53,562.04	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				17	Dec 16, 2020	SYSTEM	(\$53,562.04)	
				17	Dec 16, 2020	SYSTEM	\$53,562.04	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0020 -	· Total						\$0.00	
0040	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Other Item Adjustment	ACAD	13	Oct 16, 2020	woodsk1	(\$930.40)	*See Attached AC Price Index Adjustment Sheet.
				14	Nov 2, 2020	woodsk1	(\$10,471.20)	*See Attached AC Price Index Adjustment Sheet.
				15	Nov 17, 2020	woodsk1	(\$1,874.88)	The Combination Of Adjustments For This Line Item Are As Follows:
								Asphalt Cement Price Adjustment:
								-1874.88 For BP-1
								-332.17 For SP-125
								TSR Adjustment (For SP-125):
								Lot 1A-3B \$0.00
								Lot 3C-5D \$0.00
								Lot 6A-6F \$9,692.65
								Pay Factor Adjustments (For SP-125):
								Lot 1 \$11,568.00
								Lot 2 \$3,701.76
								Lot 3 \$11,568.00
								Lot 4 \$11,568.00
								Lot 5 \$11,568.00
								Lot 6 \$15,831.33
			ACAD - Tota	al			(\$13,276.48)	
	Other Item Adjustment - Total						(\$13,276.48)	
0040	· Total						(\$13,276.48)	
0050	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Material		13	Oct 16, 2020	SYSTEM	(\$1,147,840.58)	
				13	Oct 16, 2020	SYSTEM	\$1,147,840.58	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				14	Nov 2, 2020	SYSTEM	(\$1,472,195.74)	
				14	Nov 2, 2020	SYSTEM	\$1,472,195.74	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.

Revision 4/1/2020 Page 14 of 61



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0050	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Material		15	Nov 17, 2020	SYSTEM	(\$1,479,888.46)	
				15	Nov 17, 2020	SYSTEM	\$1,479,888.46	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				16	Dec 2, 2020	SYSTEM	(\$91,728.46)	
				16	Dec 2, 2020	SYSTEM	\$91,728.46	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				17	Dec 16, 2020	SYSTEM	(\$91,728.46)	
				17	Dec 16, 2020	SYSTEM	\$91,728.46	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Other Item Adjustment	ACAD	13	Oct 16, 2020	woodsk1	(\$45,891.79)	*See Attached AC Price Index Adjustment Sheet.
				14	Nov 2, 2020	woodsk1	(\$12,968.04)	*See Attached AC Price Index Adjustment Sheet.
			ACAD - Tota	al			(\$58,859.83)	
	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)		BITM	15	Nov 17, 2020	woodsk1	\$75,165.57	The Combination Of Adjustments For This Line Item Are As Follows:
								Asphalt Cement Price Adjustment:
								-1874.88 For BP-1
								-332.17 For SP-125
								TSR Adjustment (For SP-125):
								Lot 1A-3B \$0.00
								Lot 3C-5D \$0.00
								Lot 6A-6F \$9,692.65
								2010/10/
								Pay Factor Adjustments (For SP-125):
								Lot 1 \$11,568.00
								Lot 2 \$3,701.76
								Lot 3 \$11,568.00
								Lot 4 \$11,568.00
								Lot 5 \$11,568.00
								Lot 6 \$15,831.33
			BITM - Tota				\$75,165.57	
	Other Item Adjustment - Total						\$16,305.74	
	- Total					a	\$16,305.74	
0100	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material		6	Jul 2, 2020	SYSTEM	(\$46,901.03)	
				6	Jul 2, 2020	SYSTEM	\$46,901.03	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$69,305.39)	
				7	Jul 16, 2020	SYSTEM	\$69,305.39	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.

Revision 4/1/2020 Page 15 of 61



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0100	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH	Material		8	Aug 3, 2020	SYSTEM	(\$69,305.39)	
	PAVEMENT REPAIR			8	Aug 3, 2020	SYSTEM	\$69,305.39	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$69,305.39)	
				9	Aug 18, 2020	SYSTEM	\$69,305.39	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$69,305.39)	
				10	Sep 3, 2020	SYSTEM	\$69,305.39	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$84,951.41)	
				11	Sep 16, 2020	SYSTEM	\$84,951.41	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$90,709.88)	
				12	Oct 1, 2020	SYSTEM	\$90,709.88	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				13	Oct 16, 2020	SYSTEM	(\$90,709.88)	
				13	Oct 16, 2020	SYSTEM	\$90,709.88	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				14	Nov 2, 2020	SYSTEM	(\$90,709.88)	
				14	Nov 2, 2020	SYSTEM	\$90,709.88	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				15	Nov 17, 2020	SYSTEM	(\$90,709.88)	
				15	Nov 17, 2020	SYSTEM	\$90,709.88	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				16	Dec 2, 2020	SYSTEM	(\$90,709.88)	
				16	Dec 2, 2020	SYSTEM	\$90,709.88	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				17	Dec 16, 2020	SYSTEM	(\$90,709.88)	
				17	Dec 16, 2020	SYSTEM	\$90,709.88	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
	Metadal Tatal		- Total				\$0.00	
0100	Material - Total						\$0.00	
0100 -	- Total SUBGRADE COMPACTION (6 IN.	Material		6	Jul 2,	SYSTEM	\$0.00 (\$16.00)	
	DEPTH) (PAVEMENT REPAIR)			6	Jul 2, 2020	SYSTEM	\$16.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				7	Jul 16,	SYSTEM	(\$100.00)	. Symon Edunate.

Revision 4/1/2020 Page 16 of 61



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0110	SUBGRADE COMPACTION (6 IN.	Material			2020			
	DEPTH) (PAVEMENT REPAIR)			7	Jul 16, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$100.00)	
				8	Aug 3, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$100.00)	
				9	Aug 18, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 35 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$100.00)	
				10	Sep 3, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$100.00)	
				11	Sep 16, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$100.00)	
				12	Oct 1, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				13	Oct 16, 2020	SYSTEM	(\$100.00)	
				13	Oct 16, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				14	Nov 2, 2020	SYSTEM	(\$100.00)	
				14	Nov 2, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				15	Nov 17, 2020	SYSTEM	(\$100.00)	
				15	Nov 17, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				16	Dec 2, 2020	SYSTEM	(\$100.00)	
				16	Dec 2, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				17	Dec 16, 2020	SYSTEM	(\$100.00)	
				17	Dec 16, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	- Total						\$0.00	
0120	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	Material		6	Jul 2, 2020	SYSTEM	(\$16.00)	

Revision 4/1/2020 Page 17 of 61



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks									
0120	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	Material	.,,,,,	6	Jul 2, 2020	SYSTEM	\$16.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.									
				7	Jul 16, 2020	SYSTEM	(\$100.00)										
				7	Jul 16, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.									
				8	Aug 3, 2020	SYSTEM	(\$100.00)										
				8	Aug 3, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.									
				9	Aug 18, 2020	SYSTEM	(\$100.00)										
				9	Aug 18, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 36 on the current Payment Estimate.									
				10	Sep 3, 2020	SYSTEM	(\$100.00)										
				10	Sep 3, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 22 on the current Payment Estimate.									
				11	Sep 16, 2020	SYSTEM	(\$100.00)										
													11	Sep 16, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$100.00)										
				12	Oct 1, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 10 on the current Payment Estimate.									
				13	Oct 16, 2020	SYSTEM	(\$100.00)										
				13	Oct 16, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.									
				14	Nov 2, 2020	SYSTEM	(\$100.00)										
				14	Nov 2, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.									
				15	Nov 17, 2020	SYSTEM	(\$100.00)										
				15	Nov 17, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.									
				16	Dec 2, 2020	SYSTEM	(\$100.00)										
				16	Dec 2, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.									
				17	Dec 16, 2020	SYSTEM	(\$100.00)										
				17	Dec 16, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.									
			- Total				\$0.00										

Revision 4/1/2020 Page 18 of 61



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks										
0120	Material - Total						\$0.00											
0120 -	- Total						\$0.00											
0140	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material		6	Jul 2, 2020	SYSTEM	(\$2,000.00)											
	PAVEMENTINEPAIN			6	Jul 2, 2020	SYSTEM	\$2,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.										
				7	Jul 16, 2020	SYSTEM	(\$5,650.00)											
					7	Jul 16, 2020	SYSTEM	\$5,650.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.									
				8	Aug 3, 2020	SYSTEM	(\$5,650.00)											
				8	Aug 3, 2020	SYSTEM	\$5,650.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.										
				9	Aug 18, 2020	SYSTEM	(\$5,650.00)											
				9	Aug 18, 2020	SYSTEM	\$5,650.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 37 on the current Payment Estimate.										
				10	Sep 3, 2020	SYSTEM	(\$5,650.00)											
				10	Sep 3, 2020	SYSTEM	\$5,650.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 23 on the current Payment Estimate.										
				11	Sep 16, 2020	SYSTEM	(\$7,480.00)											
					11	Sep 16, 2020	SYSTEM	\$7,480.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 22 on the current Payment Estimate.									
				12	Oct 1, 2020	SYSTEM	(\$8,220.00)											
				12	Oct 1, 2020	SYSTEM	\$8,220.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.										
				13	Oct 16, 2020	SYSTEM	(\$8,220.00)											
				13	Oct 16, 2020	SYSTEM	\$8,220.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.										
				14	Nov 2, 2020	SYSTEM	(\$8,220.00)											
				14	Nov 2, 2020	SYSTEM	\$8,220.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.										
				15	Nov 17, 2020	SYSTEM	(\$8,220.00)											
				15	Nov 17, 2020	SYSTEM	\$8,220.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.										
				16	Dec 2, 2020	SYSTEM	(\$8,220.00)											
															16	Dec 2, 2020	SYSTEM	\$8,220.00
				17	Dec 16, 2020	SYSTEM	(\$8,220.00)											

Revision 4/1/2020 Page 19 of 61



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0140	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material		17	Dec 16, 2020	SYSTEM	\$8,220.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0140 -	Total						\$0.00	
0150	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	Material		7	Jul 16, 2020	SYSTEM	(\$10.00)	
	TOLE SET THE TAXABLE TRACE AND			7	Jul 16, 2020	SYSTEM	\$10.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$10.00)	
				8	Aug 3, 2020	SYSTEM	\$10.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$10.00)	
				9	Aug 18, 2020	SYSTEM	\$10.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$10.00)	
				10	Sep 3, 2020	SYSTEM	\$10.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$10.00)	
				11	Sep 16, 2020	SYSTEM	\$10.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$10.00)	
				12	Oct 1, 2020	SYSTEM	\$10.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				13	Oct 16, 2020	SYSTEM	(\$10.00)	
				13	Oct 16, 2020	SYSTEM	\$10.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				14	Nov 2, 2020	SYSTEM	(\$10.00)	
				14	Nov 2, 2020	SYSTEM	\$10.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				15	Nov 17, 2020	SYSTEM	(\$10.00)	
				15	Nov 17, 2020	SYSTEM	\$10.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
				16	Dec 2, 2020	SYSTEM	(\$10.00)	
				16	Dec 2, 2020	SYSTEM	\$10.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	

Revision 4/1/2020 Page 20 of 61



ine	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
150 -	Total						\$0.00			
180	CONSTRUCTION SIGNS	Material		1	Apr 16, 2020	SYSTEM	(\$2,450.50)			
				2	May 4, 2020	SYSTEM	(\$3,861.00)			
				2	May 4, 2020	SYSTEM	\$3,861.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodskroverridding Payment Estimate Exception 8 on the current Payment Estimate.		
				3	May 19, 2020	SYSTEM	(\$3,861.00)			
				3	May 19, 2020	SYSTEM	\$3,861.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user woodsk overridding Payment Estimate Exception 8 on the current Payment Estimate.		
				4	Jun 3, 2020	SYSTEM	(\$3,939.00)			
				4	Jun 3, 2020	SYSTEM	\$3,939.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk overridding Payment Estimate Exception 9 on the current Payment Estimate.		
				5	Jun 16, 2020	SYSTEM	(\$3,939.00)			
				5	Jun 16, 2020	SYSTEM	\$3,939.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user woodsk overridding Payment Estimate Exception 9 on the current Payment Estimate.		
				6	Jul 2, 2020	SYSTEM	(\$6,389.50)			
					6	Jul 2, 2020	SYSTEM	\$6,389.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk overridding Payment Estimate Exception 15 on the current Payment Estimate.	
				7	Jul 16, 2020	SYSTEM	(\$6,389.50)			
				7	Jul 16, 2020	SYSTEM	\$6,389.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk overridding Payment Estimate Exception 16 on the current Payment Estimate.		
				8	Aug 3, 2020	SYSTEM	(\$9,360.00)			
						8	Aug 3, 2020	SYSTEM	\$9,360.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk overridding Payment Estimate Exception 16 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$9,360.00)			
				9	Aug 18, 2020	SYSTEM	\$9,360.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk overridding Payment Estimate Exception 40 on the current Payment Estimate.		
				10	Sep 3, 2020	SYSTEM	(\$9,360.00)			
				10	Sep 3, 2020	SYSTEM	\$9,360.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk overridding Payment Estimate Exception 27 on the current Payment Estimate.		
			- Total				(\$2,450.50)			
	Material - Total						(\$2,450.50)			
	CONSTRUCTION SIGNS	MaterialCredit		2	May 4, 2020	SYSTEM	\$2,450.50			
			- Total				\$2,450.50			
	MaterialCredit - Total						\$2,450.50			
	CONSTRUCTION SIGNS	Other Item Adjustment	MDPA	1	Apr 16, 2020	woodsk1	\$2,450.50			
				2	May 4, 2020	woodsk1	(\$2,450.50)	This adjustment is being added to balance line item 0180 discrepancy amount.		
			MDPA - Tota	al			\$0.00			

Revision 4/1/2020 Page 21 of 61



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks							
0180	Other Item Adjustment - Total						\$0.00								
0180 -	Total						\$0.00								
0210	CHANNELIZER (TRIM LINE)	Material		1	Apr 16, 2020	SYSTEM	(\$1,215.00)								
				2	May 4, 2020	SYSTEM	(\$1,215.00)								
				2	May 4, 2020	SYSTEM	\$1,215.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 10 on the current Payment Estimate.							
				3	May 19, 2020	SYSTEM	(\$1,215.00)								
											3	May 19, 2020	SYSTEM	\$1,215.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				4	Jun 3, 2020	SYSTEM	(\$1,980.00)								
				4	Jun 3, 2020	SYSTEM	\$1,980.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.							
				5	Jun 16, 2020	SYSTEM	(\$1,980.00)								
				5	Jun 16, 2020	SYSTEM	\$1,980.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.							
					6	Jul 2, 2020	SYSTEM	(\$3,930.00)							
				6	Jul 2, 2020	SYSTEM	\$3,930.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.							
				7	Jul 16, 2020	SYSTEM	(\$3,930.00)								
						7	Jul 16, 2020	SYSTEM	\$3,930.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 20 on the current Payment Estimate.					
				8	Aug 3, 2020	SYSTEM	(\$3,930.00)								
				8	Aug 3, 2020	SYSTEM	\$3,930.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 20 on the current Payment Estimate.							
				9	Aug 18, 2020	SYSTEM	(\$3,930.00)								
				9	Aug 18, 2020	SYSTEM	\$3,930.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 44 on the current Payment Estimate.							
				10	Sep 3, 2020	SYSTEM	(\$3,930.00)								
				10	Sep 3, 2020	SYSTEM	\$3,930.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 30 on the current Payment Estimate.							
			- Total				(\$1,215.00)								
	Material - Total						(\$1,215.00)								
	CHANNELIZER (TRIM LINE)	MaterialCredit		2	May 4, 2020	SYSTEM	\$1,215.00								
			- Total				\$1,215.00								
	MaterialCredit - Total						\$1,215.00								
	CHANNELIZER (TRIM LINE)	Other Item Adjustment	MDPA	1	Apr 16, 2020	woodsk1	\$1,215.00								
				2	May 4, 2020	woodsk1	(\$1,215.00)	This adjustment is being added to balance line item 0220 discrepancy amount.							

Revision 4/1/2020 Page 22 of 61



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0210		Other Item Adjustment	MDPA - Tota	al			\$0.00	
	Other Item Adjustment - Total	,					\$0.00	
0210 -	Total						\$0.00	
0230	DIRECTIONAL INDICATOR BARRICADE	Material		1	Apr 16, 2020	SYSTEM	(\$665.00)	
				2	May 4, 2020	SYSTEM	(\$665.00)	
				2	May 4, 2020	SYSTEM	\$665.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				3	May 19, 2020	SYSTEM	(\$665.00)	
				3	May 19, 2020	SYSTEM	\$665.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				4	Jun 3, 2020	SYSTEM	(\$665.00)	
				4	Jun 3, 2020	SYSTEM	\$665.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				5	Jun 16, 2020	SYSTEM	(\$665.00)	
				5	Jun 16, 2020	SYSTEM	\$665.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				6	Jul 2, 2020	SYSTEM	(\$1,995.00)	
				6	Jul 2, 2020	SYSTEM	\$1,995.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$2,660.00)	
				7	Jul 16, 2020	SYSTEM	\$2,660.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$2,660.00)	
				8	Aug 3, 2020	SYSTEM	\$2,660.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$2,660.00)	
				9	Aug 18, 2020	SYSTEM	\$2,660.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 45 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$2,660.00)	
				10	Sep 3, 2020	SYSTEM	\$2,660.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
			- Total				(\$665.00)	
	Material - Total						(\$665.00)	
	DIRECTIONAL INDICATOR BARRICADE	MaterialCredit		2	May 4, 2020	SYSTEM	\$665.00	
			- Total				\$665.00	
	MaterialCredit - Total						\$665.00	
	DIRECTIONAL INDICATOR BARRICADE	Other Item Adjustment	MDPA	1	Apr 16, 2020	woodsk1	\$665.00	

Revision 4/1/2020 Page 23 of 61



2020 Payment Estimate Item Adjusti overridding Payment Estimate 3 May 19, SYSTEM (\$400.00)	ginal system-generated Overrun ment (0009) due to user woodsk1 Exception 12 on the current ginal system-generated Overrun
Other Item Adjustment - Total \$0.00	ment (0009) due to user woodsk1 Exception 12 on the current ginal system-generated Overrun
D230 - Total S0.00 S0.00	ment (0009) due to user woodsk1 Exception 12 on the current ginal system-generated Overrun
1	ment (0009) due to user woodsk1 Exception 12 on the current ginal system-generated Overrun
2 May 4, 2020 2 May 4, 2020 2 May 4, 2020 3 May 19, SYSTEM (\$400.00) 2 May 19, SYSTEM (\$400.00) This adjustment offsets the original payment Estimate Item Adjustro overridding Payment Estimate 3 May 19, SYSTEM (\$400.00)	ment (0009) due to user woodsk1 Exception 12 on the current ginal system-generated Overrun
2 May 4, 2020 2 May 4, 2020 3 May 19, SYSTEM (\$400.00) This adjustment offsets the original payment Estimate Item Adjustro overridding Payment Estimate Payment Estimate.	ment (0009) due to user woodsk1 Exception 12 on the current ginal system-generated Overrun
2020 Payment Estimate Item Adjusti overridding Payment Estimate 3 May 19, SYSTEM (\$400.00)	ment (0009) due to user woodsk1 Exception 12 on the current ginal system-generated Overrun
2020	
	ment (0004) due to user woodsk1
4 Jun 3, 2020 SYSTEM (\$400.00)	
	ginal system-generated Overrun ment (0005) due to user woodsk1 Exception 14 on the current
5 Jun 16, SYSTEM (\$400.00)	
	ginal system-generated Overrun ment (0004) due to user woodsk1 Exception 14 on the current
6 Jul 2, SYSTEM (\$1,200.00)	
	ginal system-generated Overrun ment (0009) due to user woodsk1 Exception 20 on the current
7 Jul 16, SYSTEM (\$1,600.00)	
	ginal system-generated Overrun ment (0009) due to user woodsk1 Exception 22 on the current
8 Aug 3, SYSTEM (\$1,600.00)	
	ginal system-generated Overrun ment (0010) due to user woodsk1 Exception 22 on the current
9 Aug 18, SYSTEM (\$1,600.00)	
	ginal system-generated Overrun ment (0009) due to user woodsk1 Exception 46 on the current
10 Sep 3, SYSTEM (\$1,600.00)	
2020 Payment Estimate Item Adjusti overridding Payment Estimate Payment Estimate.	ginal system-generated Overrun ment (0010) due to user woodsk1 Exception 32 on the current
- Total (\$400.00)	
Material - Total (\$400.00)	
FLASHING ARROW PANEL MaterialCredit 2 May 4, 2020 \$400.00	
- Total \$400.00	
Material Credit - Total \$400.00	
FLASHING ARROW PANEL Other Item MDPA 1 Apr 16, woodsk1 \$400.00	

Revision 4/1/2020 Page 24 of 61



е	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
0	FLASHING ARROW PANEL	Adjustment	MDPA		2020							
				2	May 4, 2020	woodsk1	(\$400.00)	This adjustment is being added to balance line item 0240 discrepancy amount.				
			MDPA - Tot	al			\$0.00					
_	Other Item Adjustment - Total						\$0.00					
-	Total						\$0.00					
0	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR	Material		1	Apr 16, 2020	SYSTEM	(\$3,500.00)					
	FURNISHED, CONTRACTOR RETAINED			2	May 4, 2020	SYSTEM	(\$3,500.00)					
				2	May 4, 2020	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Overrur Payment Estimate Item Adjustment (0011) due to user woods overridding Payment Estimate Exception 13 on the current Payment Estimate.				
				3	May 19, 2020	SYSTEM	(\$3,500.00)					
				3	May 19, 2020	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Overrur Payment Estimate Item Adjustment (0005) due to user woods overridding Payment Estimate Exception 13 on the current Payment Estimate.				
				4	Jun 3, 2020	SYSTEM	(\$3,500.00)					
				4	Jun 3, 2020	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Overrur Payment Estimate Item Adjustment (0006) due to user woods overridding Payment Estimate Exception 15 on the current Payment Estimate.				
				5	Jun 16, 2020	SYSTEM	(\$3,500.00)					
				5	Jun 16, 2020	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Overru Payment Estimate Item Adjustment (0005) due to user woods overridding Payment Estimate Exception 15 on the current Payment Estimate.				
								6	Jul 2, 2020	SYSTEM	(\$3,500.00)	
				6	Jul 2, 2020	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Overru Payment Estimate Item Adjustment (0010) due to user woods overridding Payment Estimate Exception 21 on the current Payment Estimate.				
				7	Jul 16, 2020	SYSTEM	(\$7,000.00)					
				7	Jul 16, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overru Payment Estimate Item Adjustment (0010) due to user woods overridding Payment Estimate Exception 24 on the current Payment Estimate.				
				8	Aug 3, 2020	SYSTEM	(\$7,000.00)					
				8	Aug 3, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overru Payment Estimate Item Adjustment (0011) due to user woods overridding Payment Estimate Exception 24 on the current Payment Estimate.				
				9	Aug 18, 2020	SYSTEM	(\$7,000.00)					
				9	Aug 18, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overru Payment Estimate Item Adjustment (0010) due to user woods overridding Payment Estimate Exception 48 on the current Payment Estimate.				
				10	Sep 3, 2020	SYSTEM	(\$7,000.00)					
				10	Sep 3, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overru Payment Estimate Item Adjustment (0011) due to user woods overridding Payment Estimate Exception 34 on the current Payment Estimate.				
			- Total				(\$3,500.00)					
	Material - Total						(\$3,500.00)					
	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	MaterialCredit		2	May 4, 2020	SYSTEM	\$3,500.00					
			- Total				\$3,500.00					

Revision 4/1/2020 Page 25 of 61



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0250	MaterialCredit - Total						\$3,500.00	
	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION	Other Item Adjustment	MDPA	1	Apr 16, 2020	woodsk1	\$3,500.00	
	INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED			2	May 4, 2020	woodsk1	(\$3,500.00)	This adjustment is being added to balance line item 0250 discrepancy amount.
			MDPA - Tota	al			\$0.00	
	Other Item Adjustment - Total						\$0.00	
0250 -	Total						\$0.00	
0350	MGS GUARDRAIL	Construction Stockpile		1	Apr 16, 2020	SYSTEM	\$85,893.50	Payment Estimate Item Adjustment generated Stockpile Transaction
				4	Jun 3, 2020	SYSTEM	(\$5,068.25)	Payment Estimate Item Adjustment generated Stockpile Transaction
				6	Jul 2, 2020	SYSTEM	(\$4,001.25)	Payment Estimate Item Adjustment generated Stockpile Transaction
				10	Sep 3, 2020	SYSTEM	(\$5,068.25)	Payment Estimate Item Adjustment generated Stockpile Transaction
				11	Sep 16, 2020	SYSTEM	(\$4,001.25)	Payment Estimate Item Adjustment generated Stockpile Transaction
				12	Oct 1, 2020	SYSTEM	(\$15,204.75)	Payment Estimate Item Adjustment generated Stockpile Transaction
				14	Nov 2, 2020	SYSTEM	(\$13,070.75)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$39,479.00	
	Construction Stockpile - Total						\$39,479.00	
0350 -	Total						\$39,479.00	
0360	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	Construction Stockpile		1	Apr 16, 2020	SYSTEM	\$35,976.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				4	Jun 3, 2020	SYSTEM	(\$2,998.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				6	Jul 2, 2020	SYSTEM	(\$2,998.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				10	Sep 3, 2020	SYSTEM	(\$2,998.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				11	Sep 16, 2020	SYSTEM	(\$2,998.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				14	Nov 2, 2020	SYSTEM	(\$2,998.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$20,986.00	
	Construction Stockpile - Total						\$20,986.00	
0360 -	Total						\$20,986.00	
0370	MGS END ANCHOR	Construction Stockpile		1	Apr 16, 2020	SYSTEM	\$3,210.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				12	Oct 1, 2020	SYSTEM	(\$3,210.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
0370 -	Total						\$0.00	
0380	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		1	Apr 16, 2020	SYSTEM	\$45,300.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				4	Jun 3, 2020	SYSTEM	(\$3,020.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				6	Jul 2, 2020	SYSTEM	(\$3,020.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				10	Sep 3, 2020	SYSTEM	(\$3,020.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				11	Sep 16, 2020	SYSTEM	(\$3,020.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			12	Oct 1, 2020	SYSTEM	(\$9,060.00)	Payment Estimate Item Adjustment generated Stockpile Transaction	
				14	Nov 2, 2020	SYSTEM	(\$3,020.00)	Payment Estimate Item Adjustment generated Stockpile Transaction

Revision 4/1/2020 Page 26 of 61



Pergenetal Estimate Exception Pergenetal Estimate Pergenetal Pergenetal Perg		Remarks		Amount	Created By	Created Date	Est. Number	Other Adjustment Type	Adjustment Type	Description	Line
Description			00	\$21,140.00				- Total			0380
Section Sect			00	\$21,140.00						Construction Stockpile - Total	
2020 9 Aug 18, SYSTEM \$205.00 This adjustment offsets the original system Phymnet Estimate Exception Phymnet Estimate E			00	\$21,140.00						- Total	0380 -
Payment Estimate Exception Program (2011 Payment Estimate Internal plantage (2011 Payment Estimate Intern			00)	(\$265.00)	SYSTEM		9		Material	EMULSIFIED ASPHALT, SEAL COAT	0400
SEAL COAT AGGREGATE, GRADE B1 Material 9 Aug 18, 2020 5 SYSTEM \$662.50 9 Aug 18, 2020 5 SYSTEM \$662.50 10 Sep 3, 2020 5 SYSTEM \$662.50 10 Sep 3, 3 SYSTEM \$1,325.00 10 Sep 3, 2020 5 SYSTEM \$1,325.00 11 Sep 16, 5 SYSTEM \$1,325.00 12 Oct 1, 2020 5 SYSTEM \$1,325.00 13 Sep 16, 5 SYSTEM \$1,325.00 14 Sep 16, 5 SYSTEM \$1,325.00 15 Sep 17, 5 SYSTEM \$1,325.00 16 Sep 18, 5 SYSTEM \$1,325.00 17 Sep 18, 5 SYSTEM \$1,325.00 18 Sep 18, 5 SYSTEM \$1,325.00 19 Sep 19, 5 SYSTEM \$1,325.00 10 Sep 3, 5 SYSTEM \$1,325.00 11 Sep 16, 5 SYSTEM \$1,325.00 12 Oct 1, 5 SYSTEM \$1,325.00 13 Oct 16, 5 SYSTEM \$1,325.00 14 Nov 2, 5 SYSTEM \$1,325.00 15 Nov 17, 5 SYSTEM \$1,325.00 16 De-2, 5 SYSTEM \$1,325.00 17 Nov 17, 5 SYSTEM \$1,325.00 18 SySTEM \$1,325.00 19 SySTEM \$1,325.00 19 SySTEM \$1,325.00 10 SySTEM \$1,325.00 11 SySTEM \$1,325.00 12 Oct 1, 5 SYSTEM \$1,325.00 13 Oct 16, 5 SYSTEM \$1,325.00 14 Nov 2, 5 SYSTEM \$1,325.00 15 Nov 17, 5 SYSTEM \$1,325.00 16 De-2, 5 SYSTEM \$1,325.00 17 De-16, 5 SYSTEM \$1,325.00 18 De-2, 5 SYSTEM \$1,325.00 19 De-16, 5 SYSTEM \$1,325.00 10 De-16, 5 SYSTEM \$1,325.00 11 De-16, 5 SYSTEM \$1,325.00 12 De-16, 5 SYSTEM \$1,325.00 13 De-16, 5 SYSTEM \$1,325.00 14 De-16, 5 SYSTEM \$1,325.00 15 De-16, 5 SYSTEM \$1,325.00 16 De-2, 5 SYSTEM \$1,325.00 17 De-16, 5 SYSTEM \$1,325.00 18 De-16, 5 SYSTEM \$1,325.00 19 De-16, 5 SYSTEM \$1,325.00 10 De-16, 5 SYSTEM \$1,325.00 11 De-16, 5 SYSTEM \$1,325.00 12 De-16, 5 SYSTEM \$1,325.00 13 De-16, 5 SYSTEM \$1,325.00 14 De-16, 5 SYSTEM \$1,325.00 15 De-16, 5 SYSTEM \$1,325.00 16 De-2, 5 SYSTEM \$1,3	11) due to user woodsk1	This adjustment offsets the original system-generated Payment Estimate Item Adjustment (0011) due to use overridding Payment Estimate Exception 19 on the cu Payment Estimate.		\$265.00	SYSTEM		9				
SEAL COAT AGGREGATE, GRADE B1			00	\$0.00				- Total			
SEAL COAT AGGREGATE, GRADE B1 Material			00	\$0.00						Material - Total	
2020 9			00	\$0.00						- Total	0400 -
2020 System Sys			50)	(\$662.50)	SYSTEM		9		Material	SEAL COAT AGGREGATE, GRADE B1	0410
10	12) due to user woodsk1	This adjustment offsets the original system-generated Payment Estimate Item Adjustment (0012) due to use overridding Payment Estimate Exception 26 on the cu Payment Estimate.		\$662.50	SYSTEM		9				
2020			00)	(\$1,325.00)	SYSTEM		10				
11	13) due to user woodsk1	This adjustment offsets the original system-generated Payment Estimate Item Adjustment (0013) due to use overridding Payment Estimate Exception 12 on the cu Payment Estimate.		\$1,325.00	SYSTEM		10				
2020 Payment Estimate Item Adjustment (0008 overridding Payment Estimate Exception Payment Estimate Item Adjustment (0008 overridding Payment Estimate Item Adjustment (0008 overridding Payment Estimate Exception Payment Estimate Item Adjustment (0008 overridding Payment Estimate Exception Payment Estimate Item Adjustment (0007 overridding Payment Estimate Item Adjustment (0008 overridding Payment Estimate Item Adjustment I			00)	(\$1,325.00)	SYSTEM		11				
2020	08) due to user woodsk1	This adjustment offsets the original system-generated Payment Estimate Item Adjustment (0008) due to use overridding Payment Estimate Exception 12 on the cur Payment Estimate.		\$1,325.00	SYSTEM		11				
2020 Payment Estimate Item Adjustment (0008 overridding Payment Estimate Exception Payment Estimate Exception Payment Estimate Exception Payment Estimate Exception Payment Estimate Payment Estimate Exception Payment Estimate Item Adjustment (0007 overridding Payment Estimate Estimate Exception Payment Estimate Exception P			00)	(\$1,325.00)	SYSTEM		12				
13	08) due to user woodsk1	This adjustment offsets the original system-generated Payment Estimate Item Adjustment (0008) due to use overridding Payment Estimate Exception 2 on the cur Payment Estimate.		\$1,325.00	SYSTEM		12				
2020 Payment Estimate Item Adjustment (0007 overridding Payment Estimate Exception-Payment Estimate Exception-Payment Estimate Exception-Payment Estimate Item Adjustment (0008 overridding Payment Estimate Item Adjustment (0008 overridding Payment Estimate Exception-Payment Estimate Exception-Payment Estimate Exception-Payment Estimate Exception-Payment Estimate Exception-Payment Estimate Item Adjustment (0008 overridding Payment Estimate Exception-Payment Estimate Item Adjustment (0008 overridding Payment Estimate Item Adjustment (0008 overridding Payment Estimate Item Adjustment (0008 overridding Payment Estimate Exception-Payment Estimate Item Adjustment (0008 overridding Payment Estimate Exception-Payment Estimate Item Adjustment (0008 overridding Payment Estimate Exception-Payment Estimate Exception-Payment Estimate Item Adjustment (0008 overridding Payment Estimate Exception-Payment Estimat			00)	(\$1,325.00)	SYSTEM		13				
2020 14 Nov 2, 2020 15 Nov 17, 2020 16 Dec 2, 2020 17 Dec 16, 2020 18 1,325.00 19 SYSTEM \$1,325.00 This adjustment offsets the original syster Payment Estimate Exception Payment Estimate Exception Payment Estimate Exception Payment Estimate Item Adjustment (0008 overridding Payment Estimate Exception Payment Estimate Item Adjustment (0008 overridding Payment Estimate Exception Payment Estimate Exception Payment Estimate Exception Payment Estimate Exception Payment Estimate Item Adjustment (0008 overridding Payment Estimate Exception Payment Estimate Item Adjustment (0008 overridding Payment Estimate Exception Payment Estimate Exception Payment Estimate Item Adjustment (0008 overridding Payment Estimate Exception Payment Estimate Payment Paymen	07) due to user woodsk1	This adjustment offsets the original system-generated Payment Estimate Item Adjustment (0007) due to use overridding Payment Estimate Exception 4 on the cur Payment Estimate.		\$1,325.00	SYSTEM		13				
2020 Payment Estimate Item Adjustment (0009 overridding Payment Estimate Exception Payment Estimate Exception Payment Estimate Exception Payment Estimate Exception Payment Estimate Item Adjustment (0008 overridding Payment Estimate Item Adjustment (0008 overridding Payment Estimate Exception Payment Estimate Exception Payment Estimate Exception Payment Estimate Item Adjustment (0008 overridding Payment Estimate Exception Payment Estimate Exception Payment Estimate Item Adjustment (0008 overridding Payment Estimate Exception Payment Estimate Item Adjustment (0008 overridding Payment Estimate Item Adjustment (000			00)	(\$1,325.00)	SYSTEM		14				
15 Nov 17, 2020 \$1,325.00 This adjustment offsets the original syster Payment Estimate Item Adjustment (0008 overridding Payment Estimate Exception Payment Estimate Exception Payment Estimate Exception Payment Estimate. 16 Dec 2, 2020 \$16 Payment Estimate Exception Payment Estimate Item Adjustment (0008 overridding Payment Estimate Item Adjustment (0008 overridding Payment Estimate Exception Payment Estimate Exception Payment Estimate. 17 Dec 16, SYSTEM \$1,325.00 \$1,325.00 \$2020 \$1,325.00 \$2020 \$1,325.00 \$2020 \$1,325.00 \$2020 \$1,325.00 \$2020 \$1,325.00 \$2020 \$1,325.00 \$2020 \$1,325.00 \$2020 \$1,325.00 \$2020 \$2020 \$1,325.00 \$2020	09) due to user woodsk1	This adjustment offsets the original system-generated Payment Estimate Item Adjustment (0009) due to use overridding Payment Estimate Exception 4 on the cur Payment Estimate.		\$1,325.00	SYSTEM		14				
2020 Payment Estimate Item Adjustment (0008 overridding Payment Estimate Exception Payment Estimate Exception Payment Estimate Exception Payment Estimate. 16 Dec 2, 2020 16 Dec 2, 2020 This adjustment offsets the original syster Payment Estimate Item Adjustment (0008 overridding Payment Estimate Exception Payment Estimate Exception Payment Estimate. 17 Dec 16, 2020 This adjustment offsets the original syster Payment Estimate Exception Payment Estimate Exception Payment Estimate.			00)	(\$1,325.00)	SYSTEM		15				
2020 16 Dec 2, 2020 SYSTEM \$1,325.00 This adjustment offsets the original syster Payment Estimate Item Adjustment (0008 overridding Payment Estimate Exception Payment Estimate. 17 Dec 16, 2020 17 Dec 16, SYSTEM \$1,325.00 This adjustment offsets the original syster Payment Estimate.	08) due to user woodsk1	This adjustment offsets the original system-generated Payment Estimate Item Adjustment (0008) due to use overridding Payment Estimate Exception 4 on the cur Payment Estimate.		\$1,325.00	SYSTEM		15				
2020 Payment Estimate Item Adjustment (0008 overridding Payment Estimate Exception Payment Estimate Exception Payment Estimate Exception Payment Estimate. 17 Dec 16, 2020 17 Dec 16, SYSTEM \$1,325.00 This adjustment offsets the original syster Payment Estimate Item Adjustment (0007)			00)	(\$1,325.00)	SYSTEM		16				
2020 17 Dec 16, SYSTEM \$1,325.00 This adjustment offsets the original syster 2020 2020 Payment Estimate Item Adjustment (0007	08) due to user woodsk1	This adjustment offsets the original system-generated Payment Estimate Item Adjustment (0008) due to use overridding Payment Estimate Exception 4 on the cur Payment Estimate.		\$1,325.00	SYSTEM		16				
2020 Payment Estimate Item Adjustment (0007			00)	(\$1,325.00)	SYSTEM		17				
overridding Payment Estimate Exception Payment Estimate.	07) due to user woodsk1	This adjustment offsets the original system-generated Payment Estimate Item Adjustment (0007) due to use overridding Payment Estimate Exception 4 on the cur Payment Estimate.		\$1,325.00	SYSTEM		17				
- Total \$0.00			00	\$0.00				- Total			
Material - Total \$0.00			00	\$0.00						Material - Total	

Revision 4/1/2020 Page 27 of 61



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks							
0410 -	- Total						\$0.00								
0420	CURB BLOCKOUT	Material		2	May 4, 2020	SYSTEM	(\$11,278.05)								
				2	May 4, 2020	SYSTEM	\$11,278.05	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.							
				3	May 19, 2020	SYSTEM	(\$16,671.90)								
				3	May 19, 2020	SYSTEM	\$16,671.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.							
				4	Jun 3, 2020	SYSTEM	(\$16,671.90)								
				4	Jun 3, 2020	SYSTEM	\$16,671.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 26 on the current Payment Estimate.							
				5	Jun 16, 2020	SYSTEM	(\$16,671.90)								
				5	Jun 16, 2020	SYSTEM	\$16,671.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 26 on the current Payment Estimate.							
				6	Jul 2, 2020	SYSTEM	(\$33,343.80)								
				6	Jul 2, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.							
											7	Jul 16, 2020	SYSTEM	(\$33,343.80)	
				7	Jul 16, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 34 on the current Payment Estimate.							
				8	Aug 3, 2020	SYSTEM	(\$33,343.80)								
				8	Aug 3, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 40 on the current Payment Estimate.							
				9	Aug 18, 2020	SYSTEM	(\$33,343.80)								
				9	Aug 18, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 76 on the current Payment Estimate.							
				10	Sep 3, 2020	SYSTEM	(\$33,343.80)								
				10	Sep 3, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 62 on the current Payment Estimate.							
				11	Sep 16, 2020	SYSTEM	(\$33,343.80)								
				11	Sep 16, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 50 on the current Payment Estimate.							
				12	Oct 1, 2020	SYSTEM	(\$33,343.80)								
				12	Oct 1, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 26 on the current Payment Estimate.							
				13	Oct 16, 2020	SYSTEM	(\$33,343.80)								
				13	Oct 16, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1							

Revision 4/1/2020 Page 28 of 61



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
0420	CURB BLOCKOUT	Material						overridding Payment Estimate Exception 27 on the current Payment Estimate.				
				14	Nov 2, 2020	SYSTEM	(\$33,343.80)					
				14	Nov 2, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 28 on the current Payment Estimate.				
				15	Nov 17, 2020	SYSTEM	(\$33,343.80)					
				15	Nov 17, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 29 on the current Payment Estimate.				
				16	Dec 2, 2020	SYSTEM	(\$33,343.80)					
				16	Dec 2, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 29 on the current Payment Estimate.				
				17	Dec 16, 2020	SYSTEM	(\$33,343.80)					
				17	Dec 16, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 33 on the current Payment Estimate.				
			- Total				\$0.00					
	Material - Total						\$0.00					
0420 -		Meterial		2	May 10	CVCTEM	\$0.00					
0430	HALF-SOLE REPAIR	Material		3	May 19, 2020	SYSTEM	(\$12,412.98)	This distance of the sixted seasons and the				
				3	May 19, 2020	SYSTEM	\$12,412.98	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.				
				4	Jun 3, 2020	SYSTEM	(\$23,457.60)					
				4	Jun 3, 2020	SYSTEM	\$23,457.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 39 on the current Payment Estimate.				
				5	Jun 16, 2020	SYSTEM	(\$37,727.64)					
				5	Jun 16, 2020	SYSTEM	\$37,727.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 39 on the current Payment Estimate.				
				6	Jul 2, 2020	SYSTEM	(\$67,440.60)					
				6	Jul 2, 2020	SYSTEM	\$67,440.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 49 on the current Payment Estimate.				
				7	Jul 16, 2020	SYSTEM	(\$67,440.60)					
				7	Jul 16, 2020	SYSTEM	\$67,440.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 52 on the current Payment Estimate.				
				8	Aug 3, 2020	SYSTEM	(\$67,440.60)					
								8	Aug 3, 2020	SYSTEM	\$67,440.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 52 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$67,440.60)					
				9	Aug 18, 2020	SYSTEM	\$67,440.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 87 on the current				

Revision 4/1/2020 Page 29 of 61



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks		
		Туре	Adjustment Type	Number	Date	Ву				
0430	HALF-SOLE REPAIR	Material						Payment Estimate.		
				10	Sep 3, 2020	SYSTEM	(\$67,440.60)			
				10	Sep 3, 2020	SYSTEM	\$67,440.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 73 on the current Payment Estimate.		
				11	Sep 16, 2020	SYSTEM	(\$67,440.60)			
				11	Sep 16, 2020	SYSTEM	\$67,440.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 62 on the current Payment Estimate.		
				12	Oct 1, 2020	SYSTEM	(\$73,793.70)			
				12	Oct 1, 2020	SYSTEM	\$73,793.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 45 on the current Payment Estimate.		
				13	Oct 16, 2020	SYSTEM	(\$73,793.70)			
				13	Oct 16, 2020	SYSTEM	\$73,793.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 46 on the current Payment Estimate.		
				14	Nov 2, 2020	SYSTEM	(\$73,793.70)			
						14	Nov 2, 2020	SYSTEM	\$73,793.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 47 on the current Payment Estimate.
				15	Nov 17, 2020	SYSTEM	(\$73,793.70)			
				15	Nov 17, 2020	SYSTEM	\$73,793.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 48 on the current Payment Estimate.		
				16	Dec 2, 2020	SYSTEM	(\$73,793.70)			
				16	Dec 2, 2020	SYSTEM	\$73,793.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 48 on the current Payment Estimate.		
				17	Dec 16, 2020	SYSTEM	(\$73,793.70)			
				17	Dec 16, 2020	SYSTEM	\$73,793.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 52 on the current Payment Estimate.		
			- Total				\$0.00			
	Material - Total						\$0.00			
0430 -	- Total						\$0.00			
0450	EMULSIFIED ASPHALT, SEAL COAT	Material		9	Aug 18, 2020	SYSTEM	(\$287.50)			
				9	Aug 18, 2020	SYSTEM	\$287.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.		
			- Total				\$0.00			
	Material - Total						\$0.00			
	- Total					0)/	\$0.00			
0460	SEAL COAT AGGREGATE, GRADE B1	Material		9	Aug 18, 2020	SYSTEM	(\$720.00)			
				9	Aug 18, 2020	SYSTEM	\$720.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 27 on the current Payment Estimate.		
				10	Sep 3, 2020	SYSTEM	(\$1,440.00)			

Revision 4/1/2020 Page 30 of 61



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
0460	SEAL COAT AGGREGATE, GRADE B1	Material		10	Sep 3, 2020	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.		
				11	Sep 16, 2020	SYSTEM	(\$1,440.00)			
				11	Sep 16, 2020	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.		
				12	Oct 1, 2020	SYSTEM	(\$1,440.00)			
				12	Oct 1, 2020	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.		
				13	Oct 16, 2020	SYSTEM	(\$1,440.00)			
				13	Oct 16, 2020	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.		
				14	Nov 2, 2020	SYSTEM	(\$1,440.00)			
					14	Nov 2, 2020	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
							15	Nov 17, 2020	SYSTEM	(\$1,440.00)
				15	Nov 17, 2020	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 6 on the current Payment Estimate.		
				16	Dec 2, 2020	SYSTEM	(\$1,440.00)			
				16	Dec 2, 2020	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 6 on the current Payment Estimate.		
				17	Dec 16, 2020	SYSTEM	(\$1,440.00)			
				17	Dec 16, 2020	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 6 on the current Payment Estimate.		
			- Total				\$0.00			
0.460	Material - Total						\$0.00			
0460 -	- Total CURB BLOCKOUT	Material		3	May 19,	SYSTEM	\$0.00 (\$12,100.62)			
					2020			This allows the first the significant state of		
				3	May 19, 2020	SYSTEM	\$12,100.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 25 on the current Payment Estimate.		
				4	Jun 3, 2020	SYSTEM	(\$17,908.92)			
				4	Jun 3, 2020	SYSTEM	\$17,908.92	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.		
				5	Jun 16, 2020	SYSTEM	(\$17,908.92)			
						5	Jun 16, 2020	SYSTEM	\$17,908.92	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
								6	Jul 2, 2020	SYSTEM
				6	Jul 2,	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Overrun		

Revision 4/1/2020 Page 31 of 61



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks											
0470	CURB BLOCKOUT	Material			2020			Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.											
				7	Jul 16, 2020	SYSTEM	(\$35,817.85)												
					7	Jul 16, 2020	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 40 on the current Payment Estimate.										
				8	Aug 3, 2020	SYSTEM	(\$35,817.85)												
				8	Aug 3, 2020	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 34 on the current Payment Estimate.											
				9	Aug 18, 2020	SYSTEM	(\$35,817.85)												
					9	Aug 18, 2020	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 64 on the current Payment Estimate.										
				10	Sep 3, 2020	SYSTEM	(\$35,817.85)												
				10	Sep 3, 2020	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 50 on the current Payment Estimate.											
				11	Sep 16, 2020	SYSTEM	(\$35,817.85)												
											11	Sep 16, 2020	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.				
				12	Oct 1, 2020	SYSTEM	(\$35,817.85)												
				12	Oct 1, 2020	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 37 on the current Payment Estimate.											
						13	Oct 16, 2020	SYSTEM	(\$35,817.85)										
				13	Oct 16, 2020	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.											
															14	Nov 2, 2020	SYSTEM	(\$35,817.85)	
					14	Nov 2, 2020	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 39 on the current Payment Estimate.										
				15	Nov 17, 2020	SYSTEM	(\$35,817.85)												
				15	Nov 17, 2020	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 40 on the current Payment Estimate.											
							16	Dec 2, 2020	SYSTEM	(\$35,817.85)									
					16	Dec 2, 2020	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 40 on the current Payment Estimate.										
							17	Dec 16, 2020	SYSTEM	(\$35,817.85)									
				17	Dec 16, 2020	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.											
			- Total				\$0.00												
	Material - Total						\$0.00												

Revision 4/1/2020 Page 32 of 61



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks											
0470 -	- Total						\$0.00												
0480	HALF-SOLE REPAIR	Material		3	May 19, 2020	SYSTEM	(\$4,160.68)												
				3	May 19, 2020	SYSTEM	\$4,160.68	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 31 on the current Payment Estimate.											
				4	Jun 3, 2020	SYSTEM	(\$25,157.60)												
				4	Jun 3, 2020	SYSTEM	\$25,157.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.											
				5	Jun 16, 2020	SYSTEM	(\$41,510.04)												
					5	Jun 16, 2020	SYSTEM	\$41,510.04	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.										
				6	Jul 2, 2020	SYSTEM	(\$69,183.40)												
					6	Jul 2, 2020	SYSTEM	\$69,183.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 45 on the current Payment Estimate.										
						7	Jul 16, 2020	SYSTEM	(\$69,183.40)										
						7	Jul 16, 2020	SYSTEM	\$69,183.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 48 on the current Payment Estimate.									
				8	Aug 3, 2020	SYSTEM	(\$69,183.40)												
					8	Aug 3, 2020	SYSTEM	\$69,183.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 48 on the current Payment Estimate.										
						9	Aug 18, 2020	SYSTEM	(\$69,183.40)										
				9	Aug 18, 2020	SYSTEM	\$69,183.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 83 on the current Payment Estimate.											
				10	Sep 3, 2020	SYSTEM	(\$69,183.40)												
							10	Sep 3, 2020	SYSTEM	\$69,183.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 69 on the current Payment Estimate.								
											11	Sep 16, 2020	SYSTEM	(\$69,183.40)					
																		11	Sep 16, 2020
				12	Oct 1, 2020	SYSTEM	(\$69,957.48)												
												12	Oct 1, 2020	SYSTEM	\$69,957.48	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 50 on the current Payment Estimate.			
				13	Oct 16, 2020	SYSTEM	(\$69,957.48)												
									13	Oct 16, 2020	SYSTEM	\$69,957.48	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 51 on the current Payment Estimate.						
				14	Nov 2, 2020	SYSTEM	(\$69,957.48)												
				14	Nov 2, 2020	SYSTEM	\$69,957.48	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1											

Revision 4/1/2020 Page 33 of 61



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
0480	80 HALF-SOLE REPAIR	Material						overridding Payment Estimate Exception 52 on the current Payment Estimate.		
				15	Nov 17, 2020	SYSTEM	(\$69,957.48)			
				15	Nov 17, 2020	SYSTEM	\$69,957.48	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 53 on the current Payment Estimate.		
				16	Dec 2, 2020	SYSTEM	(\$69,957.48)			
				16	Dec 2, 2020	SYSTEM	\$69,957.48	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 53 on the current Payment Estimate.		
				17	Dec 16, 2020	SYSTEM	(\$69,957.48)			
				17	Dec 16, 2020	SYSTEM	\$69,957.48	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 47 on the current Payment Estimate.		
			- Total				\$0.00			
	Material - Total						\$0.00			
	Total	Material		9	Aug 10	SYSTEM	\$0.00			
0520	CURB BLOCKOUT	Material			Aug 18, 2020		(\$16,671.90)			
						9	Aug 18, 2020	SYSTEM	\$16,671.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 70 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$16,671.90)			
				10	Sep 3, 2020	SYSTEM	\$16,671.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 56 on the current Payment Estimate.		
				11	Sep 16, 2020	SYSTEM	(\$33,343.80)			
				11	Sep 16, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 44 on the current Payment Estimate.		
				12	Oct 1, 2020	SYSTEM	(\$33,343.80)			
						12	Oct 1, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
						13	Oct 16, 2020	SYSTEM	(\$33,343.80)	
						13	Oct 16, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
				14	Nov 2, 2020	SYSTEM	(\$33,343.80)			
				14	Nov 2, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 33 on the current Payment Estimate.		
				15	Nov 17, 2020	SYSTEM	(\$33,343.80)			
					15	Nov 17, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 34 on the current Payment Estimate.	
				16	Dec 2, 2020	SYSTEM	(\$33,343.80)			
				16	Dec 2, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 34 on the current		

Revision 4/1/2020 Page 34 of 61



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0520	CURB BLOCKOUT	Material						Payment Estimate.
				17	Dec 16, 2020	SYSTEM	(\$33,343.80)	
				17	Dec 16, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0520 -	· Total						\$0.00	
0530	HALF-SOLE REPAIR	Material		7	Jul 16, 2020	SYSTEM	(\$8,503.38)	
				7	Jul 16, 2020	SYSTEM	\$8,503.38	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 47 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$8,503.38)	
				8	Aug 3, 2020	SYSTEM	\$8,503.38	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 47 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$23,457.60)	
				9	Aug 18, 2020	SYSTEM	\$23,457.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 82 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$23,457.60)	
				10	Sep 3, 2020	SYSTEM	\$23,457.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 68 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$23,457.60)	
				11	Sep 16, 2020	SYSTEM	\$23,457.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 57 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$83,372.22)	
				12	Oct 1, 2020	SYSTEM	\$83,372.22	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 49 on the current Payment Estimate.
				13	Oct 16, 2020	SYSTEM	(\$83,372.22)	
				13	Oct 16, 2020	SYSTEM	\$83,372.22	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 50 on the current Payment Estimate.
				14	Nov 2, 2020	SYSTEM	(\$83,372.22)	
				14	Nov 2, 2020	SYSTEM	\$83,372.22	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 51 on the current Payment Estimate.
				15	Nov 17, 2020	SYSTEM	(\$83,372.22)	
				15	Nov 17, 2020	SYSTEM	\$83,372.22	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 52 on the current Payment Estimate.
				16	Dec 2, 2020	SYSTEM	(\$83,372.22)	
				16	Dec 2, 2020	SYSTEM	\$83,372.22	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 52 on the current Payment Estimate.

Revision 4/1/2020 Page 35 of 61



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0530	HALF-SOLE REPAIR	Material		17	Dec 16, 2020	SYSTEM	(\$83,372.22)	
				17	Dec 16, 2020	SYSTEM	\$83,372.22	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 51 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0530 -	·Total						\$0.00	
0570	CURB BLOCKOUT	Material		9	Aug 18, 2020	SYSTEM	(\$15,434.12)	
				9	Aug 18, 2020	SYSTEM	\$15,434.12	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 58 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$15,434.12)	
				10	Sep 3, 2020	SYSTEM	\$15,434.12	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 44 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$30,868.25)	
				11	Sep 16, 2020	SYSTEM	\$30,868.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$30,868.25)	
				12	Oct 1, 2020	SYSTEM	\$30,868.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
				13	Oct 16, 2020	SYSTEM	(\$30,868.25)	
				13	Oct 16, 2020	SYSTEM	\$30,868.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
				14	Nov 2, 2020	SYSTEM	(\$30,868.25)	
				14	Nov 2, 2020	SYSTEM	\$30,868.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
				15	Nov 17, 2020	SYSTEM	(\$30,868.25)	
				15	Nov 17, 2020	SYSTEM	\$30,868.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
				16	Dec 2, 2020	SYSTEM	(\$30,868.25)	
				16	Dec 2, 2020	SYSTEM	\$30,868.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
				17	Dec 16, 2020	SYSTEM	(\$30,868.25)	
				17	Dec 16, 2020	SYSTEM	\$30,868.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0570 -	Total						\$0.00	
0580	HALF-SOLE REPAIR	Material		7	Jul 16, 2020	SYSTEM	(\$21,758.00)	
	on 4/1/2020			7	Jul 16,	SYSTEM	\$21,758.00	This adjustment offsets the original system-generated Overrun

Revision 4/1/2020 Page 36 of 61



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0580	HALF-SOLE REPAIR	Material			2020			Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 55 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$21,758.00)	
				8	Aug 3, 2020	SYSTEM	\$21,758.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 55 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$21,758.00)	
				9	Aug 18, 2020	SYSTEM	\$21,758.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 90 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$21,758.00)	
				10	Sep 3, 2020	SYSTEM	\$21,758.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 76 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$21,758.00)	
				11	Sep 16, 2020	SYSTEM	\$21,758.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 65 on the current Payment Estimate.
			- Total				\$0.00	
0500	Material - Total - Total						\$0.00	
0780		Material		11	Sep 16,	SYSTEM	\$0.00 (\$2,577.84)	
				11	2020 Sep 16, 2020	SYSTEM	\$2,577.84	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 56 on the current Payment Estimate.
				12	Oct 1,	OVOTEN		. aymon zoumato.
						SYSTEM	(\$14,607.76)	
				12	Oct 1, 2020	SYSTEM	(\$14,607.76) \$14,607.76	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 44 on the current Payment Estimate.
				12	2020 Oct 1,			Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 44 on the current
					2020 Oct 1, 2020 Oct 16,	SYSTEM	\$14,607.76	Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 44 on the current
				13	2020 Oct 1, 2020 Oct 16, 2020 Oct 16,	SYSTEM	\$14,607.76 (\$42,964.00)	Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 44 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 45 on the current
				13	2020 Oct 1, 2020 Oct 16, 2020 Oct 16, 2020 Nov 2,	SYSTEM SYSTEM SYSTEM	\$14,607.76 (\$42,964.00) \$42,964.00	Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 44 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 45 on the current
				13	2020 Oct 1, 2020 Oct 16, 2020 Oct 16, 2020 Nov 2, 2020 Nov 2,	SYSTEM SYSTEM SYSTEM	\$14,607.76 (\$42,964.00) \$42,964.00	Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 44 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 45 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 46 on the current
				13 13 14	2020 Oct 1, 2020 Oct 16, 2020 Oct 16, 2020 Nov 2, 2020 Nov 2, 2020 Nov 17,	SYSTEM SYSTEM SYSTEM SYSTEM	\$14,607.76 (\$42,964.00) \$42,964.00 (\$42,964.00)	Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 44 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 45 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 46 on the current
				13 13 14 14 15	2020 Oct 1, 2020 Oct 16, 2020 Oct 16, 2020 Nov 2, 2020 Nov 2, 2020 Nov 17, 2020 Nov 17,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$14,607.76 (\$42,964.00) \$42,964.00 (\$42,964.00) (\$42,964.00)	Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 44 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 45 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 46 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 47 on the current
				13 13 14 14 15 15	2020 Oct 1, 2020 Oct 16, 2020 Oct 16, 2020 Nov 2, 2020 Nov 17, 2020 Nov 17, 2020 Dec 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$14,607.76 (\$42,964.00) \$42,964.00 (\$42,964.00) \$42,964.00 (\$42,964.00)	Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 44 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 45 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 46 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 47 on the current
				13 13 14 14 15 15	2020 Oct 1, 2020 Oct 16, 2020 Oct 16, 2020 Nov 2, 2020 Nov 17, 2020 Dec 2, 2020 Dec 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$14,607.76 (\$42,964.00) \$42,964.00 (\$42,964.00) \$42,964.00 (\$42,964.00) \$42,964.00	Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 44 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 45 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 46 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 47 on the current Payment Estimate.

Revision 4/1/2020 Page 37 of 61



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0780	HALF-SOLE REPAIR	Material						overridding Payment Estimate Exception 46 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0780 -	· Total						\$0.00	
0820	HALF-SOLE REPAIR	Material		11	Sep 16, 2020	SYSTEM	(\$3,007.48)	
				11	Sep 16, 2020	SYSTEM	\$3,007.48	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 66 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$42,964.00)	
				12	Oct 1, 2020	SYSTEM	\$42,964.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 48 on the current Payment Estimate.
				13	Oct 16, 2020	SYSTEM	(\$42,964.00)	
				13	Oct 16, 2020	SYSTEM	\$42,964.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 49 on the current Payment Estimate.
				14	Nov 2, 2020	SYSTEM	(\$42,964.00)	
				14	Nov 2, 2020	SYSTEM	\$42,964.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 50 on the current Payment Estimate.
				15	Nov 17, 2020	SYSTEM	(\$42,964.00)	
				15	Nov 17, 2020	SYSTEM	\$42,964.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 51 on the current Payment Estimate.
				16	Dec 2, 2020	SYSTEM	(\$42,964.00)	
				16	Dec 2, 2020	SYSTEM	\$42,964.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 51 on the current Payment Estimate.
				17	Dec 16, 2020	SYSTEM	(\$318,363.24)	
				17	Dec 16, 2020	SYSTEM	\$318,363.24	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 45 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0820	· Total						\$0.00	
0850	MISC. PERMANENT AGGREGATE EDGE TREATMENT	Material		2	May 4, 2020	SYSTEM	(\$17,901.77)	
				2	May 4, 2020	SYSTEM	\$17,901.77	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				3	May 19, 2020	SYSTEM	(\$42,591.62)	
				3	May 19, 2020	SYSTEM	\$42,591.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				4	Jun 3, 2020	SYSTEM	(\$42,591.62)	
				4	Jun 3, 2020	SYSTEM	\$42,591.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
	4/4/0000			5	Jun 16,	SYSTEM	(\$42,591.62)	

Revision 4/1/2020 Page 38 of 61



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																														
0850	MISC. PERMANENT AGGREGATE EDGE	Material	7.5		2020																																	
	TREATMENT			5	Jun 16, 2020	SYSTEM	\$42,591.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																														
				6	Jul 2, 2020	SYSTEM	(\$42,591.62)																															
				6	Jul 2, 2020	SYSTEM	\$42,591.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																														
				7	Jul 16, 2020	SYSTEM	(\$42,591.62)																															
				7	Jul 16, 2020	SYSTEM	\$42,591.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																														
				8	Aug 3, 2020	SYSTEM	(\$42,591.62)																															
				8	Aug 3, 2020	SYSTEM	\$42,591.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																														
				9	Aug 18, 2020	SYSTEM	(\$42,591.62)																															
				9	Aug 18, 2020	SYSTEM	\$42,591.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																														
				10	Sep 3, 2020	SYSTEM	(\$48,392.79)																															
			10	Sep 3, 2020	SYSTEM	\$48,392.79	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																															
				11	Sep 16, 2020	SYSTEM	(\$48,392.79)																															
				11	Sep 16, 2020	SYSTEM	\$48,392.79	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																														
				12	Oct 1, 2020	SYSTEM	(\$64,697.64)																															
				12	Oct 1, 2020	SYSTEM	\$64,697.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																														
				13	Oct 16, 2020	SYSTEM	(\$64,697.64)																															
				13	Oct 16, 2020	SYSTEM	\$64,697.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																														
																																		14	Nov 2, 2020	SYSTEM	(\$64,697.64)	
				14	Nov 2, 2020	SYSTEM	\$64,697.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																														
																							15	Nov 17, 2020	SYSTEM	(\$64,697.64)												
				15	Nov 17, 2020	SYSTEM	\$64,697.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																														
				16	Dec 2, 2020	SYSTEM	(\$64,697.64)																															
				16	Dec 2, 2020	SYSTEM	\$64,697.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																														

Revision 4/1/2020 Page 39 of 61



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0850	MISC. PERMANENT AGGREGATE EDGE TREATMENT	Material		17	Dec 16, 2020	SYSTEM	(\$64,697.64)	
				17	Dec 16, 2020	SYSTEM	\$64,697.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0850 -	- Total						\$0.00	
0870	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Other Item Adjustment	ACAD	2	May 4, 2020	woodsk1	\$460.98	
				17	Dec 16, 2020	woodsk1	\$8.06	*See Attached AC Price Index Adjustment Sheet.
			ACAD - Tota	al			\$469.04	
	Other Item Adjustment - Total						\$469.04	
0870 -	- Total						\$469.04	
0880	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Material		2	May 4, 2020	SYSTEM	(\$456,638.72)	
				2	May 4, 2020	SYSTEM	\$456,638.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				3	May 19, 2020	SYSTEM	(\$456,638.72)	
				3	May 19, 2020	SYSTEM	\$456,638.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				4	Jun 3, 2020	SYSTEM	(\$456,638.72)	
				4	Jun 3, 2020	SYSTEM	\$456,638.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				5	Jun 16, 2020	SYSTEM	(\$456,638.72)	
				5	Jun 16, 2020	SYSTEM	\$456,638.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				6	Jul 2, 2020	SYSTEM	(\$456,638.72)	
				6	Jul 2, 2020	SYSTEM	\$456,638.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$940,718.72)	
				7	Jul 16, 2020	SYSTEM	\$940,718.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$940,718.72)	
				8	Aug 3, 2020	SYSTEM	\$940,718.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$940,718.72)	
				9	Aug 18, 2020	SYSTEM	\$940,718.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$1,038,932.50)	
				10	Sep 3, 2020	SYSTEM	\$1,038,932.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 2 on the current

Revision 4/1/2020 Page 40 of 61



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0880	ASPHALTIC CONCRETE MIXTURE PG	Material						Payment Estimate.
	70-22 (SP125C MIX)			11	Sep 16,	SYSTEM	(\$1,038,932.50)	
				11	2020 Sep 16, 2020	SYSTEM	\$1,038,932.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1
								overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Other Item Adjustment	ACAD	1	Apr 16, 2020	woodsk1	\$1,227.35	
				2	May 4, 2020	woodsk1	\$1,493.29	
				17	Dec 16, 2020	woodsk1	\$7.00	*See Attached AC Price Index Adjustment Sheet.
			ACAD - Tota	al			\$2,727.64	
	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)		BITM	8	Aug 3, 2020	woodsk1	\$66,845.91	TSR #001 Payment Adjustment. Lot #001 \$18,153.00
	70-22 (3F 1230 MIX)				2020			TSR #002 Payment Adjustment. Lot #004 \$10,068.56
								Lot 1 Bonus Payment Adjustment \$12,102.00
								Lot 2 Bonus Payment Adjustment \$6,051.00
								Lot 3 Bonus Payment Adjustment \$12,102.00
								Lot 4 Bonus Payment Adjustment \$8,369.35
								Total Bituminous Pay Factor Adjustment For Line Item Posting #0880 \$66,845.91
			BITM - Tota	1			\$66,845.91	
	Other Item Adjustment - Total						\$69,573.55	
0880 -	Total						\$69,573.55	
0890	TACK COAT	Material		1	Apr 16, 2020	SYSTEM	(\$10,486.00)	
					2020			
				2	May 4, 2020	SYSTEM	(\$24,460.20)	
				2	May 4,	SYSTEM	(\$24,460.20) \$24,460.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					May 4, 2020 May 4,		,	Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 3 on the current
				2	May 4, 2020 May 4, 2020 May 19,	SYSTEM	\$24,460.20	Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 3 on the current
				2	May 4, 2020 May 4, 2020 May 19, 2020 May 19,	SYSTEM	\$24,460.20 (\$24,460.20)	Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 3 on the current
				3 3	May 4, 2020 May 4, 2020 May 19, 2020 May 19, 2020	SYSTEM SYSTEM	\$24,460.20 (\$24,460.20) \$24,460.20	Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 3 on the current
				3 3 4	May 4, 2020 May 4, 2020 May 19, 2020 May 19, 2020 Jun 3, 2020 Jun 3,	SYSTEM SYSTEM SYSTEM	\$24,460.20 (\$24,460.20) \$24,460.20	Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 3 on the current
				3 3 4 4	May 4, 2020 May 4, 2020 May 19, 2020 May 19, 2020 Jun 3, 2020 Jun 3, 2020 Jun 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$24,460.20 (\$24,460.20) \$24,460.20 (\$24,460.20)	Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 3 on the current
				2 3 3 4 4	May 4, 2020 May 4, 2020 May 19, 2020 May 19, 2020 Jun 3, 2020 Jun 3, 2020 Jun 16, 2020 Jun 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$24,460.20 (\$24,460.20) \$24,460.20 (\$24,460.20) (\$24,460.20)	Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 3 on the current
				2 3 3 4 4 5 5	May 4, 2020 May 4, 2020 May 19, 2020 May 19, 2020 Jun 3, 2020 Jun 16, 2020 Jul 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$24,460.20 (\$24,460.20) \$24,460.20 (\$24,460.20) \$24,460.20 (\$24,460.20)	Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 3 on the current
				2 3 3 4 4 5 5	May 4, 2020 May 4, 2020 May 19, 2020 May 19, 2020 Jun 3, 2020 Jun 16, 2020 Jul 2, 2020 Jul 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$24,460.20 (\$24,460.20) \$24,460.20 (\$24,460.20) \$24,460.20 (\$24,460.20)	Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.

Revision 4/1/2020 Page 41 of 61



Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
0890	TACK COAT	Material	Туре			_,		overridding Payment Estimate Exception 3 on the current
0090	TACK COAT	iviaterial						Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$24,460.20)	
				8	Aug 3, 2020	SYSTEM	\$24,460.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$24,460.20)	
				9	Aug 18, 2020	SYSTEM	\$24,460.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$27,242.20)	
				10	Sep 3, 2020	SYSTEM	\$27,242.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$27,242.20)	
				11	Sep 16, 2020	SYSTEM	\$27,242.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				(\$10,486.00)	
	Material - Total						(\$10,486.00)	
	TACK COAT	MaterialCredit		2	May 4, 2020	SYSTEM	\$10,486.00	
			- Total				\$10,486.00	
	MaterialCredit - Total						\$10,486.00	
	TACK COAT	Other Item Adjustment	MDPA	1	Apr 16, 2020	woodsk1	\$10,486.00	
				2	May 4, 2020	woodsk1	(\$10,486.00)	This adjustment is being added to balance line item 0890 discrepancy amount.
			MDPA - Tot	al			\$0.00	
	Other Item Adjustment - Total						\$0.00	
	- Total						\$0.00	
0900	BITUMINOUS FOG SEAL	Material		2	May 4, 2020	SYSTEM	(\$4,565.00)	
				2	May 4, 2020	SYSTEM	\$4,565.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				3	May 19, 2020	SYSTEM	(\$8,436.95)	
				3	May 19, 2020	SYSTEM	\$8,436.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				4	Jun 3, 2020	SYSTEM	(\$8,436.95)	
				4	Jun 3, 2020	SYSTEM	\$8,436.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				5	Jun 16, 2020	SYSTEM	(\$8,436.95)	
				5	Jun 16, 2020	SYSTEM	\$8,436.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				6	Jul 2, 2020	SYSTEM	(\$8,436.95)	
				6	Jul 2, 2020	SYSTEM	\$8,436.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 5 on the current

Revision 4/1/2020 Page 42 of 61



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0900	BITUMINOUS FOG SEAL	Material						Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$8,436.95)	
				7	Jul 16, 2020	SYSTEM	\$8,436.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$8,436.95)	
				8	Aug 3, 2020	SYSTEM	\$8,436.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$8,436.95)	
				9	Aug 18, 2020	SYSTEM	\$8,436.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$10,511.95)	
				10	Sep 3, 2020	SYSTEM	\$10,511.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$10,511.95)	
				11	Sep 16, 2020	SYSTEM	\$10,511.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$19,920.00)	
				12	Oct 1, 2020	SYSTEM	\$19,920.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				13	Oct 16, 2020	SYSTEM	(\$19,920.00)	
				13	Oct 16, 2020	SYSTEM	\$19,920.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				14	Nov 2, 2020	SYSTEM	(\$19,920.00)	
				14	Nov 2, 2020	SYSTEM	\$19,920.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				15	Nov 17, 2020	SYSTEM	(\$19,920.00)	
				15	Nov 17, 2020	SYSTEM	\$19,920.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				16	Dec 2, 2020	SYSTEM	(\$19,920.00)	
				16	Dec 2, 2020	SYSTEM	\$19,920.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				17	Dec 16, 2020	SYSTEM	(\$19,920.00)	
				17	Dec 16, 2020	SYSTEM	\$19,920.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0900 -	Total						\$0.00	

Revision 4/1/2020 Page 43 of 61



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0910	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	Material		4	Jun 3, 2020	SYSTEM	(\$1,000.00)	
				4	Jun 3, 2020	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				5	Jun 16, 2020	SYSTEM	(\$1,000.00)	
				5	Jun 16, 2020	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				6	Jul 2, 2020	SYSTEM	(\$1,000.00)	
				6	Jul 2, 2020	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$1,000.00)	
				7	Jul 16, 2020	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$1,000.00)	
				8	Aug 3, 2020	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$1,000.00)	
				9	Aug 18, 2020	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$1,000.00)	
				10	Sep 3, 2020	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0910 -	- Total CONSTRUCTION SIGNS	Material		1	Apr 16,	SYSTEM	\$0.00 (\$15,366.00)	
				2	2020 May 4,	SYSTEM	(\$15,366.00)	
				2	2020 May 4, 2020	SYSTEM	\$15,366.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				3	May 19, 2020	SYSTEM	(\$15,366.00)	
				3	May 19, 2020	SYSTEM	\$15,366.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				4	Jun 3, 2020	SYSTEM	(\$15,366.00)	
				4	Jun 3, 2020	SYSTEM	\$15,366.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				5	Jun 16, 2020	SYSTEM	(\$15,366.00)	
				5	Jun 16, 2020	SYSTEM	\$15,366.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 8 on the current

Revision 4/1/2020 Page 44 of 61



6 Jul 2, 2020 SYSTEM (\$15,366.00) 6 Jul 2, 2020 SYSTEM \$15,366.00 This adju	
6 Jul 2, 2020 SYSTEM \$15,366.00 This adju Payment overriddin Payment	t Estimate.
2020 Payment overriddin Payment	
7 Jul 16, SYSTEM (\$15,366.00)	ustment offsets the original system-generated Overrun Estimate Item Adjustment (0023) due to user woodsk1 ng Payment Estimate Exception 14 on the current Estimate.
2020	
2020 Payment overriddir	istment offsets the original system-generated Overrun t Estimate Item Adjustment (0022) due to user woodsk1 ng Payment Estimate Exception 17 on the current t Estimate.
8 Aug 3, 2020 (\$15,366.00)	
2020 Payment overriddir	ustment offsets the original system-generated Overrun t Estimate Item Adjustment (0024) due to user woodsk1 ng Payment Estimate Exception 17 on the current t Estimate.
9 Aug 18, 2020 (\$15,366.00)	
2020 Payment overriddir	ustment offsets the original system-generated Overrun testimate Item Adjustment (0028) due to user woodsk1 ng Payment Estimate Exception 41 on the current Estimate.
10 Sep 3, SYSTEM (\$15,366.00)	
2020 Payment overriddir	Istment offsets the original system-generated Overrun Estimate Item Adjustment (0030) due to user woodsk1 ng Payment Estimate Exception 26 on the current Estimate.
- Total (\$15,366.00)	
Material - Total (\$15,366.00)	
CONSTRUCTION SIGNS MaterialCredit 2 May 4, 2020 \$15,366.00	
- Total \$15,366.00	
MaterialCredit - Total \$15,366.00	
CONSTRUCTION SIGNS Other Item Adjustment MDPA 1 Apr 16, 2020 woodsk1 \$15,366.00	
	ustment is being added to balance line item 0920 ncy amount.
MDPA - Total \$0.00	
Other Item Adjustment - Total \$0.00	
0920 - Total \$0.00	
0930 FLAG ASSEMBLY Material 1 Apr 16, 2020 (\$140.00)	
2 May 4, SYSTEM (\$140.00)	
2020 Payment	ustment offsets the original system-generated Overrun Estimate Item Adjustment (0021) due to user woodsk1 ng Payment Estimate Exception 9 on the current Estimate.
3 May 19, 2020 (\$140.00) 3 May 19, 2020 SYSTEM \$140.00 Payment 2020 Payment 3 Yes EM \$140.00 Payment overriddin	ustment offsets the original system-generated Overrun testimate Item Adjustment (0015) due to user woodsk1 ng Payment Estimate Exception 9 on the current Estimate.
3 May 19, 2020 (\$140.00) 3 May 19, 2020 SYSTEM \$140.00 Payment 2020 Payment 3 Yes EM \$140.00 Payment overriddin	t Estimate Item Adjustment (0015) due to user woodsk1 ng Payment Estimate Exception 9 on the current
Payment	t Estimate Item Adjustment (0015) due to user woodsk1 ng Payment Estimate Exception 9 on the current
Payment	Estimate Item Adjustment (0015) due to user woodsk1 ng Payment Estimate Exception 9 on the current Estimate. Ustment offsets the original system-generated Overrun the Estimate Item Adjustment (0020) due to user woodsk1 ng Payment Estimate Exception 10 on the current

Revision 4/1/2020 Page 45 of 61



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
	Восктриот	Туре	Adjustment Type		Date	Ву	, anount	Nomano
0930	FLAG ASSEMBLY	Material			2020			Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				6	Jul 2, 2020	SYSTEM	(\$140.00)	
				6	Jul 2, 2020	SYSTEM	\$140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$140.00)	
				7	Jul 16, 2020	SYSTEM	\$140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$140.00)	
				8	Aug 3, 2020	SYSTEM	\$140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$140.00)	
				9	Aug 18, 2020	SYSTEM	\$140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user woodsk1 overridding Payment Estimate Exception 42 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$140.00)	
				10	Sep 3, 2020	SYSTEM	\$140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user woodsk1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
			- Total				(\$140.00)	
	Material - Total						(\$140.00)	
	FLAG ASSEMBLY							
	FLAG ASSEMBLY	MaterialCredit		2	May 4, 2020	SYSTEM	\$140.00	
	FLAG ASSEMBLY	MaterialCredit	- Total	2		SYSTEM	\$140.00 \$140.00	
	MaterialCredit - Total	MaterialCredit					\$140.00 \$140.00	
		MaterialCredit Other Item Adjustment	- Total			SYSTEM woodsk1	\$140.00	
	MaterialCredit - Total	Other Item			2020 Apr 16,		\$140.00 \$140.00	This adjustment is being added to balance line item 0180 discrepancy amount.
	MaterialCredit - Total	Other Item		1 2	Apr 16, 2020 May 4,	woodsk1	\$140.00 \$140.00 \$140.00	
	MaterialCredit - Total	Other Item	MDPA	1 2	Apr 16, 2020 May 4,	woodsk1	\$140.00 \$140.00 \$140.00 (\$140.00)	
0930 -	MaterialCredit - Total FLAG ASSEMBLY Other Item Adjustment - Total	Other Item	MDPA	1 2	Apr 16, 2020 May 4,	woodsk1	\$140.00 \$140.00 \$140.00 (\$140.00)	
0930 - 0940	MaterialCredit - Total FLAG ASSEMBLY Other Item Adjustment - Total	Other Item Adjustment	MDPA	1 2	Apr 16, 2020 May 4,	woodsk1	\$140.00 \$140.00 \$140.00 (\$140.00) \$0.00	
	MaterialCredit - Total FLAG ASSEMBLY Other Item Adjustment - Total Total	Other Item Adjustment	MDPA	1 2	2020 Apr 16, 2020 May 4, 2020	woodsk1	\$140.00 \$140.00 \$140.00 (\$140.00) \$0.00 \$0.00	
	MaterialCredit - Total FLAG ASSEMBLY Other Item Adjustment - Total Total	Other Item Adjustment	MDPA	1 2 al	Apr 16, 2020 May 4, 2020 Jun 3, 2020 Jun 3,	woodsk1 woodsk1 SYSTEM	\$140.00 \$140.00 \$140.00 (\$140.00) \$0.00 \$0.00 (\$600.00)	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 11 on the current
	MaterialCredit - Total FLAG ASSEMBLY Other Item Adjustment - Total Total	Other Item Adjustment	MDPA	1 2 al 4 4 4	Apr 16, 2020 May 4, 2020 Jun 3, 2020 Jun 3, 2020 Jun 16,	woodsk1 woodsk1 SYSTEM	\$140.00 \$140.00 \$140.00 (\$140.00) \$0.00 \$0.00 (\$600.00)	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 11 on the current
	MaterialCredit - Total FLAG ASSEMBLY Other Item Adjustment - Total Total	Other Item Adjustment	MDPA	1 2 al 4 4 5	2020 Apr 16, 2020 May 4, 2020 Jun 3, 2020 Jun 3, 2020 Jun 16, 2020 Jun 16,	woodsk1 woodsk1 SYSTEM SYSTEM	\$140.00 \$140.00 \$140.00 (\$140.00) \$0.00 \$0.00 (\$600.00) (\$600.00)	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 12 on the current
	MaterialCredit - Total FLAG ASSEMBLY Other Item Adjustment - Total Total	Other Item Adjustment	MDPA	1 2 al 4 4 5 5 5	2020 Apr 16, 2020 May 4, 2020 Jun 3, 2020 Jun 16, 2020 Jun 16, 2020 Jul 2,	woodsk1 woodsk1 SYSTEM SYSTEM SYSTEM SYSTEM	\$140.00 \$140.00 \$140.00 (\$140.00) \$0.00 \$0.00 (\$600.00) \$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 12 on the current
	MaterialCredit - Total FLAG ASSEMBLY Other Item Adjustment - Total Total	Other Item Adjustment	MDPA	1 2 al 4 4 5 5 5 6	Jun 3, 2020 Jun 16, 2020 Jun 16, 2020 Jun 16, 2020 Jul 2, 2020 Jul 2, 2020	woodsk1 woodsk1 SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$140.00 \$140.00 \$140.00 (\$140.00) \$0.00 \$0.00 (\$600.00) \$600.00 (\$600.00)	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 18 on the current

Revision 4/1/2020 Page 46 of 61



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																						
0940	CHANNELIZER (TRIM LINE)	Material						overridding Payment Estimate Exception 19 on the current Payment Estimate.																						
				8	Aug 3, 2020	SYSTEM	(\$600.00)																							
				8	Aug 3, 2020	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.																						
				9	Aug 18, 2020	SYSTEM	(\$600.00)																							
				9	Aug 18, 2020	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user woodsk1 overridding Payment Estimate Exception 43 on the current Payment Estimate.																						
				10	Sep 3, 2020	SYSTEM	(\$600.00)																							
				10	Sep 3, 2020	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user woodsk1 overridding Payment Estimate Exception 29 on the current Payment Estimate.																						
			- Total				\$0.00																							
	Material - Total						\$0.00																							
0940 -	Total						\$0.00																							
0950	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR	Material		1	Apr 16, 2020	SYSTEM	(\$7,000.00)																							
	FURNISHED, CONTRACTOR RETAINED			2	May 4, 2020	SYSTEM	(\$7,000.00)																							
									2	May 4, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.																	
							3	May 19, 2020	SYSTEM	(\$7,000.00)																				
				3	May 19, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.																						
				4	Jun 3, 2020	SYSTEM	(\$7,000.00)																							
				4	Jun 3, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.																						
				5	Jun 16, 2020	SYSTEM	(\$7,000.00)																							
				5	Jun 16, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.																						
				6	Jul 2, 2020	SYSTEM	(\$7,000.00)																							
																										6	Jul 2, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$7,000.00)																							
				7	Jul 16, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 23 on the current Payment Estimate.																						
				8	Aug 3, 2020	SYSTEM	(\$7,000.00)																							
				8	Aug 3, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overridding Payment Estimate Exception 23 on the current Payment Estimate.																						
				9	Aug 18, 2020	SYSTEM	(\$7,000.00)																							

Revision 4/1/2020 Page 47 of 61



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0950	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	Material		9	Aug 18, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user woodsk1 overridding Payment Estimate Exception 47 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$7,000.00)	
				10	Sep 3, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
			- Total				(\$7,000.00)	
	Material - Total						(\$7,000.00)	
	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	MaterialCredit		2	May 4, 2020	SYSTEM	\$7,000.00	
			- Total				\$7,000.00	
	MaterialCredit - Total						\$7,000.00	
	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION	Other Item Adjustment	MDPA	1	Apr 16, 2020	woodsk1	\$7,000.00	
	INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED			2	May 4, 2020	woodsk1	(\$7,000.00)	This adjustment is being added to balance line item 0950 discrepancy amount.
			MDPA - Tota	al			\$0.00	
	Other Item Adjustment - Total						\$0.00	
0950 -	Total						\$0.00	
0960	WORK ZONE TRAFFIC SIGNAL SYSTEM	Material		4	Jun 3, 2020	SYSTEM	(\$8,400.00)	
				4	Jun 3, 2020	SYSTEM	\$8,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
				5	Jun 16, 2020	SYSTEM	(\$8,400.00)	
				5	Jun 16, 2020	SYSTEM	\$8,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
				6	Jul 2, 2020	SYSTEM	(\$8,400.00)	
				6	Jul 2, 2020	SYSTEM	\$8,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$8,400.00)	
				7	Jul 16, 2020	SYSTEM	\$8,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$8,400.00)	
				8	Aug 3, 2020	SYSTEM	\$8,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$8,400.00)	
				9	Aug 18, 2020	SYSTEM	\$8,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user woodsk1 overridding Payment Estimate Exception 49 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$8,400.00)	
				10	Sep 3, 2020	SYSTEM	\$8,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0034) due to user woodsk1 overridding Payment Estimate Exception 35 on the current Payment Estimate.
			- Total				\$0.00	

Revision 4/1/2020 Page 48 of 61



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																															
0960	Material - Total						\$0.00																																
0960 -	- Total						\$0.00																																
0970	TEMPORARY LONG-TERM RUMBLE STRIPS	Material		4	Jun 3, 2020	SYSTEM	(\$3,600.00)																																
				4	Jun 3, 2020	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.																															
				5	Jun 16, 2020	SYSTEM	(\$3,600.00)																																
				5	Jun 16, 2020	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.																															
				6	Jul 2, 2020	SYSTEM	(\$3,600.00)																																
				6	Jul 2, 2020	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overridding Payment Estimate Exception 24 on the current Payment Estimate.																															
				7	Jul 16, 2020	SYSTEM	(\$3,600.00)																																
				7	Jul 16, 2020	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overridding Payment Estimate Exception 26 on the current Payment Estimate.																															
				8	Aug 3, 2020	SYSTEM	(\$3,600.00)																																
				8	Aug 3, 2020	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user woodsk1 overridding Payment Estimate Exception 26 on the current Payment Estimate.																															
				9	Aug 18, 2020	SYSTEM	(\$3,600.00)																																
					9	Aug 18, 2020	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 50 on the current Payment Estimate.																														
				10	Sep 3, 2020	SYSTEM	(\$3,600.00)																																
				10	Sep 3, 2020	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0035) due to user woodsk1 overridding Payment Estimate Exception 36 on the current Payment Estimate.																															
			- Total				\$0.00																																
	Material - Total						\$0.00																																
0970 -	- Total						\$0.00																																
0990	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	Material		4	Jun 3, 2020	SYSTEM	(\$2,424.00)																																
														4	Jun 3, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.																					
				5	Jun 16, 2020	SYSTEM	(\$2,424.00)																																
				5	Jun 16, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.																															
				6	Jul 2, 2020	SYSTEM	(\$2,424.00)																																
																																			6	Jul 2, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user woodsk1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
																																					7	Jul 16, 2020	SYSTEM
				7	Jul 16, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1																															

Revision 4/1/2020 Page 49 of 61



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0990	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	Material						overridding Payment Estimate Exception 27 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$2,424.00)	
				8	Aug 3, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user woodsk1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$2,424.00)	
				9	Aug 18, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0034) due to user woodsk1 overridding Payment Estimate Exception 51 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$2,424.00)	
				10	Sep 3, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0036) due to user woodsk1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$2,424.00)	
				11	Sep 16, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$2,424.00)	
				12	Oct 1, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				13	Oct 16, 2020	SYSTEM	(\$2,424.00)	
				13	Oct 16, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				14	Nov 2, 2020	SYSTEM	(\$2,424.00)	
				14	Nov 2, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
				15	Nov 17, 2020	SYSTEM	(\$2,424.00)	
				15	Nov 17, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
				16	Dec 2, 2020	SYSTEM	(\$2,424.00)	
				16	Dec 2, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
				17	Dec 16, 2020	SYSTEM	(\$2,424.00)	
				17	Dec 16, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1000	TEMPORARY REMOVABLE MARKING	Material		4	Jun 3,	SYSTEM	\$0.00 (\$4,000.00)	
	TAPE 4 IN., YELLOW			4	Jun 3, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 20 on the current

Revision 4/1/2020 Page 50 of 61



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
1000	TEMPORARY REMOVABLE MARKING	Material						Payment Estimate.	
	TAPE 4 IN., YELLOW			5	Jun 16, 2020	SYSTEM	(\$4,000.00)		
				5	Jun 16, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 20 on the current Payment Estimate.	
				6	Jul 2, 2020	SYSTEM	(\$4,000.00)		
				6	Jul 2, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user woodsk1 overridding Payment Estimate Exception 26 on the current Payment Estimate.	
				7	Jul 16, 2020	SYSTEM	(\$4,000.00)		
				7	Jul 16, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user woodsk1 overridding Payment Estimate Exception 28 on the current Payment Estimate.	
				8	Aug 3, 2020	SYSTEM	(\$4,000.00)		
				8	Aug 3, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user woodsk1 overridding Payment Estimate Exception 28 on the current Payment Estimate.	
				9	Aug 18, 2020	SYSTEM	(\$4,000.00)		
				9	Aug 18, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0035) due to user woodsk1 overridding Payment Estimate Exception 52 on the current Payment Estimate.	
				10	Sep 3, 2020	SYSTEM	(\$4,000.00)		
					10	Sep 3, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0037) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$4,000.00)		
				11	Sep 16, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overridding Payment Estimate Exception 26 on the current Payment Estimate.	
				12	Oct 1, 2020	SYSTEM	(\$4,000.00)		
				12	Oct 1, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	
				13	Oct 16, 2020	SYSTEM	(\$4,000.00)		
				13	Oct 16, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	
				14	Nov 2, 2020	SYSTEM	(\$4,000.00)		
				14	Nov 2, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	
				15	Nov 17, 2020	SYSTEM	(\$4,000.00)		
				15	Nov 17, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	
				16	Dec 2, 2020	SYSTEM	(\$4,000.00)		
				16	Dec 2, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1	

Revision 4/1/2020 Page 51 of 61



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
1000	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	Material						overridding Payment Estimate Exception 17 on the current Payment Estimate.		
				17	Dec 16, 2020	SYSTEM	(\$4,000.00)			
				17	Dec 16, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.		
			- Total				\$0.00			
	Material - Total						\$0.00			
1000 -	Total						\$0.00			
1010	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	Material		4	Jun 3, 2020	SYSTEM	(\$240.00)			
				4	Jun 3, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate.		
				5	Jun 16, 2020	SYSTEM	(\$240.00)			
				5	Jun 16, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate.		
				6	Jul 2, 2020	SYSTEM	(\$240.00)			
				6	Jul 2, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 27 on the current Payment Estimate.		
				7	Jul 16, 2020	SYSTEM	(\$240.00)			
				7	Jul 16, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user woodsk1 overridding Payment Estimate Exception 29 on the current Payment Estimate.		
				8	Aug 3, 2020	SYSTEM	(\$240.00)			
				8	Aug 3, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 29 on the current Payment Estimate.		
				9	Aug 18, 2020	SYSTEM	(\$240.00)			
				9	Aug 18, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0036) due to user woodsk1 overridding Payment Estimate Exception 53 on the current Payment Estimate.		
				10	Sep 3, 2020	SYSTEM	(\$240.00)			
						10	Sep 3, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
			11	Sep 16, 2020	SYSTEM	(\$240.00)				
				11	Sep 16, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 27 on the current Payment Estimate.		
				12	Oct 1, 2020	SYSTEM	(\$240.00)			
					12	Oct 1, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	
				13	Oct 16, 2020	SYSTEM	(\$240.00)			
				13	Oct 16, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 16 on the current		

Revision 4/1/2020 Page 52 of 61



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks											
1010	TEMPORARY REMOVABLE MARKING	Material						Payment Estimate.											
	TAPE, 24 IN., WHITE			14	Nov 2, 2020	SYSTEM	(\$240.00)												
				14	Nov 2, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.											
				15	Nov 17, 2020	SYSTEM	(\$240.00)												
				15	Nov 17, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.											
				16	Dec 2, 2020	SYSTEM	(\$240.00)												
				16	Dec 2, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.											
				17	Dec 16, 2020	SYSTEM	(\$240.00)												
				17	Dec 16, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.											
			- Total				\$0.00												
	Material - Total						\$0.00												
1010 -	Total						\$0.00												
1020	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		3	May 19, 2020	SYSTEM	(\$6,270.00)												
	BEAUS					3	May 19, 2020	SYSTEM	\$6,270.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.									
					4	Jun 3, 2020	SYSTEM	(\$6,270.00)											
				4	Jun 3, 2020	SYSTEM	\$6,270.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overridding Payment Estimate Exception 22 on the current Payment Estimate.											
				5	Jun 16, 2020	SYSTEM	(\$6,270.00)												
				5	Jun 16, 2020	SYSTEM	\$6,270.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 22 on the current Payment Estimate.											
				6	Jul 2, 2020	SYSTEM	(\$6,270.00)												
					6	Jul 2, 2020	SYSTEM	\$6,270.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user woodsk1 overridding Payment Estimate Exception 28 on the current Payment Estimate.										
															7	Jul 16, 2020	SYSTEM	(\$6,270.00)	
															7	Jul 16, 2020	SYSTEM	\$6,270.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user woodsk1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$6,270.00)												
													8	Aug 3, 2020	SYSTEM	\$6,270.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user woodsk1 overridding Payment Estimate Exception 30 on the current Payment Estimate.		
														į	5	!		,	9
				9	Aug 18, 2020	SYSTEM	\$6,270.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0037) due to user woodsk1 overridding Payment Estimate Exception 54 on the current Payment Estimate.											

Revision 4/1/2020 Page 53 of 61



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1020	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P	Material		10	Sep 3, 2020	SYSTEM	(\$12,574.32)	
	BEADS			10	Sep 3, 2020	SYSTEM	\$12,574.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0038) due to user woodsk1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$12,574.32)	
				11	Sep 16, 2020	SYSTEM	\$12,574.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$12,574.32)	
				12	Oct 1, 2020	SYSTEM	\$12,574.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
				13	Oct 16, 2020	SYSTEM	(\$12,574.32)	
				13	Oct 16, 2020	SYSTEM	\$12,574.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
				14	Nov 2, 2020	SYSTEM	(\$12,574.32)	
				14	Nov 2, 2020	SYSTEM	\$12,574.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
				15	Nov 17, 2020	SYSTEM	(\$12,574.32)	
				15	Nov 17, 2020	SYSTEM	\$12,574.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
				16	Dec 2, 2020	SYSTEM	(\$12,574.32)	
				16	Dec 2, 2020	SYSTEM	\$12,574.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
				17	Dec 16, 2020	SYSTEM	(\$12,574.32)	
				17	Dec 16, 2020	SYSTEM	\$12,574.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total 4 IN. WHITE STANDARD WATERBORNE	Other Item	REFL	10	Sep 3,	woodsk1	\$0.00 \$153.21	Yellow:
	PAVEMENT MARKING PAINT, TYPE P BEADS	Adjustment	IXLI	10	2020	WOOUSKI	ψ133.21	63.78% @ 105 = (102,369 x .6378) = (65,290.9' @ 105% Pay Adjustment) = (65,290.9 x .0055) = \$359.10
								32.14% @ 100 = (102,369 x .3214) = (32,901.4' @ 100% Pay) *(Also Includes 2nd Mobilization & Application)
								4.08% @ 80 = (102,369 x .0408) = (4,176.7' @ 80% Pay Adjustment) = (4,176.7 x .088) = -\$91.89
								Total Adjustment = \$267.21
								White:
								92.28%@ 105 = (30,488 x.9228) = (28,134.3' @ 105% Pay Adjustment) = (28,134.3 x.0055) = \$154.74
								7.2%@ 100 = (30,488 x .0720) = (2,195.1' @ 100% Pay)

Revision 4/1/2020 Page 54 of 61



Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
1020		Other Item	Туре					*(Also Includes 2nd Mobilization & Application)
1020		Adjustment						0.52%@80 = (30,488 x .0052) = (158.5' @ 80% Pay Adjustment) = (158.5 x .088) = -\$1.53
								Total Adjustment = \$153.21
								* Remaining Quantity From 2nd Mobilization & Application Paid @ 100%
			REFL - Tota	ı			\$153.21	
	Other Item Adjustment - Total						\$153.21	
1020 -	- Total						\$153.21	
1030	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		3	May 19, 2020	SYSTEM	(\$1,760.00)	
				3	May 19, 2020	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
				4	Jun 3, 2020	SYSTEM	(\$1,760.00)	
				4	Jun 3, 2020	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
				5	Jun 16, 2020	SYSTEM	(\$1,760.00)	
				5	Jun 16, 2020	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
				6	Jul 2, 2020	SYSTEM	(\$1,760.00)	
				6	Jul 2, 2020	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user woodsk1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$1,760.00)	
				7	Jul 16, 2020	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$1,760.00)	
				8	Aug 3, 2020	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$1,760.00)	
				9	Aug 18, 2020	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0038) due to user woodsk1 overridding Payment Estimate Exception 56 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$3,519.89)	
				10	Sep 3, 2020	SYSTEM	\$3,519.89	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0039) due to user woodsk1 overridding Payment Estimate Exception 42 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$3,519.89)	
				11	Sep 16, 2020	SYSTEM	\$3,519.89	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user woodsk1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
				12	Oct 1,	SYSTEM	(\$3,519.89)	

Revision 4/1/2020 Page 55 of 61



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1030	4 IN. YELLOW STANDARD	Material			2020			
	WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS			12	Oct 1, 2020	SYSTEM	\$3,519.89	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
				13	Oct 16, 2020	SYSTEM	(\$3,519.89)	
				13	Oct 16, 2020	SYSTEM	\$3,519.89	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
				14	Nov 2, 2020	SYSTEM	(\$3,519.89)	
				14	Nov 2, 2020	SYSTEM	\$3,519.89	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
				15	Nov 17, 2020	SYSTEM	(\$3,519.89)	
				15	Nov 17, 2020	SYSTEM	\$3,519.89	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
				16	Dec 2, 2020	SYSTEM	(\$3,519.89)	
				16	Dec 2, 2020	SYSTEM	\$3,519.89	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
				17	Dec 16, 2020	SYSTEM	(\$3,519.89)	
				17	Dec 16, 2020	SYSTEM	\$3,519.89	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 19 on the current
								Payment Estimate.
			- Total				\$0.00	Payment Estimate.
	Material - Total						\$0.00	
	Material - Total 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Other Item Adjustment	- Total	10	Sep 3, 2020	woodsk1		Yellow: 63.78% @ 105 = (102,369 x .6378) = (65,290.9' @ 105% Pay Adjustment) = (65,290.9 x .0055) = \$359.10
	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING			10		woodsk1	\$0.00	Yellow: 63.78% @ 105 = (102,369 x .6378) = (65,290.9' @ 105%
	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING			10		woodsk1	\$0.00	Yellow: 63.78% @ 105 = (102,369 x .6378) = (65,290.9' @ 105% Pay Adjustment) = (65,290.9 x .0055) = \$359.10 32.14% @ 100 = (102,369 x .3214) = (32,901.4' @ 100%
	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING			10		woodsk1	\$0.00	Yellow: 63.78% @ 105 = (102,369 x .6378) = (65,290.9' @ 105% Pay Adjustment) = (65,290.9 x .0055) = \$359.10 32.14% @ 100 = (102,369 x .3214) = (32,901.4' @ 100% Pay) *(Also Includes 2nd Mobilization & Application) 4.08% @ 80 = (102,369 x .0408) = (4,176.7' @ 80% Pay
	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING			10		woodsk1	\$0.00	Yellow: 63.78% @ 105 = (102,369 x .6378) = (65,290.9' @ 105% Pay Adjustment) = (65,290.9 x .0055) = \$359.10 32.14% @ 100 = (102,369 x .3214) = (32,901.4' @ 100% Pay) *(Also Includes 2nd Mobilization & Application) 4.08% @ 80 = (102,369 x .0408) = (4,176.7' @ 80% Pay Adjustment) = (4,176.7 x .088) = -\$91.89 Total Adjustment = \$267.21
	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING			10		woodsk1	\$0.00	Yellow: 63.78% @ 105 = (102,369 x .6378) = (65,290.9' @ 105% Pay Adjustment) = (65,290.9 x .0055) = \$359.10 32.14% @ 100 = (102,369 x .3214) = (32,901.4' @ 100% Pay) *(Also Includes 2nd Mobilization & Application) 4.08% @ 80 = (102,369 x .0408) = (4,176.7' @ 80% Pay Adjustment) = (4,176.7 x .088) = -\$91.89 Total Adjustment = \$267.21
	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING			10		woodsk1	\$0.00	Yellow: 63.78% @ 105 = (102,369 x .6378) = (65,290.9' @ 105% Pay Adjustment) = (65,290.9 x .0055) = \$359.10 32.14% @ 100 = (102,369 x .3214) = (32,901.4' @ 100% Pay) *(Also Includes 2nd Mobilization & Application) 4.08% @ 80 = (102,369 x .0408) = (4,176.7' @ 80% Pay Adjustment) = (4,176.7 x .088) = -\$91.89 Total Adjustment = \$267.21 White: 92.28%@ 105 = (30,488 x .9228) = (28,134.3' @ 105% Pay Adjustment) = (28,134.3 x .0055) = \$154.74
	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING			10		woodsk1	\$0.00	Yellow: 63.78% @ 105 = (102,369 x .6378) = (65,290.9' @ 105% Pay Adjustment) = (65,290.9 x .0055) = \$359.10 32.14% @ 100 = (102,369 x .3214) = (32,901.4' @ 100% Pay) *(Also Includes 2nd Mobilization & Application) 4.08% @ 80 = (102,369 x .0408) = (4,176.7' @ 80% Pay Adjustment) = (4,176.7 x .088) = -\$91.89 Total Adjustment = \$267.21 White: 92.28%@ 105 = (30,488 x .9228) = (28,134.3' @ 105% Pay Adjustment) = (28,134.3 x .0055) = \$154.74 7.2%@ 100 = (30,488 x .0720) = (2,195.1' @ 100% Pay) *(Also Includes 2nd Mobilization & Application)
	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING			10		woodsk1	\$0.00	Yellow: 63.78% @ 105 = (102,369 x .6378) = (65,290.9' @ 105% Pay Adjustment) = (65,290.9 x .0055) = \$359.10 32.14% @ 100 = (102,369 x .3214) = (32,901.4' @ 100% Pay) *(Also Includes 2nd Mobilization & Application) 4.08% @ 80 = (102,369 x .0408) = (4,176.7' @ 80% Pay Adjustment) = (4,176.7 x .088) = -\$91.89 Total Adjustment = \$267.21 White: 92.28%@ 105 = (30,488 x .9228) = (28,134.3' @ 105% Pay Adjustment) = (28,134.3 x .0055) = \$154.74 7.2%@ 100 = (30,488 x .0720) = (2,195.1' @ 100% Pay)
	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING			10		woodsk1	\$0.00	Yellow: 63.78% @ 105 = (102,369 x .6378) = (65,290.9' @ 105% Pay Adjustment) = (65,290.9 x .0055) = \$359.10 32.14% @ 100 = (102,369 x .3214) = (32,901.4' @ 100% Pay) *(Also Includes 2nd Mobilization & Application) 4.08% @ 80 = (102,369 x .0408) = (4,176.7' @ 80% Pay Adjustment) = (4,176.7 x .088) = -\$91.89 Total Adjustment = \$267.21 White: 92.28%@ 105 = (30,488 x .9228) = (28,134.3' @ 105% Pay Adjustment) = (28,134.3 x .0055) = \$154.74 7.2%@ 100 = (30,488 x .0720) = (2,195.1' @ 100% Pay) *(Also Includes 2nd Mobilization & Application) 0.52%@80 = (30,488 x .0052) = (158.5' @ 80% Pay
	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING			10		woodsk1	\$0.00	Yellow: 63.78% @ 105 = (102,369 x .6378) = (65,290.9' @ 105% Pay Adjustment) = (65,290.9 x .0055) = \$359.10 32.14% @ 100 = (102,369 x .3214) = (32,901.4' @ 100% Pay) *(Also Includes 2nd Mobilization & Application) 4.08% @ 80 = (102,369 x .0408) = (4,176.7' @ 80% Pay Adjustment) = (4,176.7 x .088) = -\$91.89 Total Adjustment = \$267.21 White: 92.28%@ 105 = (30,488 x .9228) = (28,134.3' @ 105% Pay Adjustment) = (28,134.3 x .0055) = \$154.74 7.2%@ 100 = (30,488 x .0720) = (2,195.1' @ 100% Pay) *(Also Includes 2nd Mobilization & Application) 0.52%@80 = (30,488 x .0052) = (158.5' @ 80% Pay Adjustment) = (158.5 x .088) = -\$1.53

Revision 4/1/2020 Page 56 of 61



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
1030	Other Item Adjustment - Total						\$267.21			
1030 -	Total						\$267.21			
1080	MGS GUARDRAIL	Construction Stockpile		1	Apr 16, 2020	SYSTEM	\$1,493.80	Payment Estimate Item Adjustment generated Stockpile Transaction		
				8	Aug 3, 2020	SYSTEM	(\$1,493.80)	Payment Estimate Item Adjustment generated Stockpile Transaction		
			- Total				\$0.00			
	Construction Stockpile - Total						\$0.00			
1080 -	Total						\$0.00			
1090	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	Construction Stockpile		1	Apr 16, 2020	SYSTEM	\$5,996.00	Payment Estimate Item Adjustment generated Stockpile Transaction		
				8	Aug 3, 2020	SYSTEM	(\$5,996.00)	Payment Estimate Item Adjustment generated Stockpile Transaction		
			- Total				\$0.00			
	Construction Stockpile - Total						\$0.00			
1090 -	Total						\$0.00			
1100	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		1	Apr 16, 2020	SYSTEM	\$6,040.00	Payment Estimate Item Adjustment generated Stockpile Transaction		
				8	Aug 3, 2020	SYSTEM	(\$6,040.00)	Payment Estimate Item Adjustment generated Stockpile Transaction		
			- Total				\$0.00			
	Construction Stockpile - Total						\$0.00			
1100 -	Total						\$0.00			
1130	EMULSIFIED ASPHALT, SEAL COAT	Material		9	Aug 18, 2020	SYSTEM	(\$575.00)			
				9	Aug 18, 2020	SYSTEM	\$575.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0039) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.		
						10	Sep 3, 2020	SYSTEM	(\$575.00)	
				10	Sep 3, 2020	SYSTEM	\$575.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0040) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.		
				11	Sep 16, 2020	SYSTEM	(\$575.00)			
				11	Sep 16, 2020	SYSTEM	\$575.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.		
			- Total				\$0.00			
	Material - Total						\$0.00			
1130 -							\$0.00			
1140	SEAL COAT AGGREGATE, GRADE B1	Material		9	Aug 18, 2020	SYSTEM	(\$1,435.00)			
				9	Aug 18, 2020	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0040) due to user woodsk1 overridding Payment Estimate Exception 28 on the current Payment Estimate.		
				10	Sep 3, 2020	SYSTEM	(\$1,435.00)			
				10	Sep 3, 2020	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0041) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.		
				11	Sep 16, 2020	SYSTEM	(\$1,435.00)			
				11	Sep 16, 2020	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.		
				12	Oct 1, 2020	SYSTEM	(\$1,435.00)			

Revision 4/1/2020 Page 57 of 61



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1140	SEAL COAT AGGREGATE, GRADE B1	Material		12	Oct 1, 2020	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				13	Oct 16, 2020	SYSTEM	(\$1,435.00)	
				13	Oct 16, 2020	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				14	Nov 2, 2020	SYSTEM	(\$1,435.00)	
				14	Nov 2, 2020	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				15	Nov 17, 2020	SYSTEM	(\$1,435.00)	
				15	Nov 17, 2020	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				16	Dec 2, 2020	SYSTEM	(\$1,435.00)	
				16	Dec 2, 2020	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				17	Dec 16, 2020	SYSTEM	(\$1,435.00)	
				17	Dec 16, 2020	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
			Total				Ψ0.00	
1140 -	Material - Total		Total				\$0.00	
1140 - 1150	Total SUPERSTRUCTURE REPAIR	Material	Total	6	Jul 2, 2020	SYSTEM		
	Total	Material	1 3 1 1	6	Jul 2, 2020 Jul 2, 2020	SYSTEM SYSTEM	\$0.00 \$0.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 44 on the current Payment Estimate.
	Total SUPERSTRUCTURE REPAIR	Material	10141		2020 Jul 2,		\$0.00 \$0.00 (\$3,111.60)	Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 44 on the current
	Total SUPERSTRUCTURE REPAIR	Material		6	2020 Jul 2, 2020 Jul 16,	SYSTEM	\$0.00 \$0.00 (\$3,111.60) \$3,111.60	Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 44 on the current
	Total SUPERSTRUCTURE REPAIR	Material		7	Jul 16, 2020 Jul 16, 2020 Jul 16,	SYSTEM	\$0.00 \$0.00 (\$3,111.60) \$3,111.60 (\$6,223.20)	Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 44 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 46 on the current
	Total SUPERSTRUCTURE REPAIR	Material		7	Jul 16, 2020 Jul 16, 2020 Jul 16, 2020 Aug 3,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,111.60) \$3,111.60 (\$6,223.20) \$6,223.20	Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 44 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 46 on the current
	Total SUPERSTRUCTURE REPAIR	Material		7 7 8	2020 Jul 2, 2020 Jul 16, 2020 Jul 16, 2020 Aug 3, 2020 Aug 3,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,111.60) \$3,111.60 (\$6,223.20) \$6,223.20	Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 44 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 46 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0036) due to user woodsk1 overridding Payment Estimate Exception 46 on the current
	Total SUPERSTRUCTURE REPAIR	Material		6 7 7 8 8	2020 Jul 2, 2020 Jul 16, 2020 Jul 16, 2020 Aug 3, 2020 Aug 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,111.60) \$3,111.60 (\$6,223.20) \$6,223.20 (\$6,223.20)	Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 44 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 46 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0036) due to user woodsk1 overridding Payment Estimate Exception 46 on the current
	Total SUPERSTRUCTURE REPAIR	Material		6 7 7 8 8 9	2020 Jul 2, 2020 Jul 16, 2020 Jul 16, 2020 Aug 3, 2020 Aug 18, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,111.60) \$3,111.60 (\$6,223.20) \$6,223.20 (\$6,223.20) \$6,223.20	Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 44 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 46 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0036) due to user woodsk1 overridding Payment Estimate Exception 46 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0041) due to user woodsk1 overridding Payment Estimate Item Adjustment (0041) due to user woodsk1 overridding Payment Estimate Exception 81 on the current
	Total SUPERSTRUCTURE REPAIR	Material		6 7 7 8 8 8 9	2020 Jul 2, 2020 Jul 16, 2020 Jul 16, 2020 Aug 3, 2020 Aug 18, 2020 Aug 18, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,111.60) \$3,111.60 (\$6,223.20) \$6,223.20 (\$6,223.20) \$6,223.20 (\$6,223.20)	Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 44 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 46 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0036) due to user woodsk1 overridding Payment Estimate Exception 46 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0041) due to user woodsk1 overridding Payment Estimate Item Adjustment (0041) due to user woodsk1 overridding Payment Estimate Exception 81 on the current
	Total SUPERSTRUCTURE REPAIR	Material		6 7 7 8 8 8 9 9	2020 Jul 2, 2020 Jul 16, 2020 Jul 16, 2020 Aug 3, 2020 Aug 18, 2020 Aug 18, 2020 Sep 3, 2020 Sep 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,111.60) \$3,111.60 (\$6,223.20) \$6,223.20 (\$6,223.20) \$6,223.20 (\$6,223.20) \$6,223.20	Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 44 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 46 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0036) due to user woodsk1 overridding Payment Estimate Exception 46 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0041) due to user woodsk1 overridding Payment Estimate Exception 81 on the current Payment Estimate.

Revision 4/1/2020 Page 58 of 61



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1150	SUPERSTRUCTURE REPAIR (UNFORMED)	Material			2020			Payment Estimate Item Adjustment (0032) due to user woodsk1 overridding Payment Estimate Exception 55 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$9,645.96)	
				12	Oct 1, 2020	SYSTEM	\$9,645.96	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overridding Payment Estimate Exception 43 on the current Payment Estimate.
				13	Oct 16, 2020	SYSTEM	(\$9,645.96)	
				13	Oct 16, 2020	SYSTEM	\$9,645.96	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 44 on the current Payment Estimate.
				14	Nov 2, 2020	SYSTEM	(\$9,645.96)	
				14	Nov 2, 2020	SYSTEM	\$9,645.96	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user woodsk1 overridding Payment Estimate Exception 45 on the current Payment Estimate.
				15	Nov 17, 2020	SYSTEM	(\$9,645.96)	
				15	Nov 17, 2020	SYSTEM	\$9,645.96	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overridding Payment Estimate Exception 46 on the current Payment Estimate.
				16	Dec 2, 2020	SYSTEM	(\$9,645.96)	
				16	Dec 2, 2020	SYSTEM	\$9,645.96	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overridding Payment Estimate Exception 46 on the current Payment Estimate.
				17	Dec 16, 2020	SYSTEM	(\$9,645.96)	
				17	Dec 16, 2020	SYSTEM	\$9,645.96	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overridding Payment Estimate Exception 44 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	Total			_		0) (0 = = 1)	\$0.00	
1160	SLAB EDGE REPAIR (BRIDGES)	Material		5	Jun 16, 2020	SYSTEM	(\$7,361.70)	
				5	Jun 16, 2020	SYSTEM	\$7,361.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
				6	Jul 2, 2020	SYSTEM	(\$7,361.70)	
				6	Jul 2, 2020	SYSTEM	\$7,361.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0034) due to user woodsk1 overridding Payment Estimate Exception 52 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$14,723.40)	
				7	Jul 16, 2020	SYSTEM	\$14,723.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0034) due to user woodsk1 overridding Payment Estimate Exception 56 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$14,723.40)	
				8	Aug 3, 2020	SYSTEM	\$14,723.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0037) due to user woodsk1 overridding Payment Estimate Exception 56 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$14,723.40)	

Revision 4/1/2020 Page 59 of 61



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
1160	SLAB EDGE REPAIR (BRIDGES)	Material						overridding Payment Estimate Exception 91 on the current Payment Estimate.	
				10	Sep 3, 2020	SYSTEM	(\$14,723.40)		
				10	Sep 3, 2020	SYSTEM	\$14,723.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0043) due to user woodsk1 overridding Payment Estimate Exception 77 on the current Payment Estimate.	
				11	Sep 16, 2020	SYSTEM	(\$14,723.40)		
				11	Sep 16, 2020	SYSTEM	\$14,723.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 67 on the current Payment Estimate.	
				12	Oct 1, 2020	SYSTEM	(\$14,723.40)		
					12	Oct 1, 2020	SYSTEM	\$14,723.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user woodsk1 overridding Payment Estimate Exception 54 on the current Payment Estimate.
				13	Oct 16, 2020	SYSTEM	(\$14,723.40)		
				13	Oct 16, 2020	SYSTEM	\$14,723.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overridding Payment Estimate Exception 55 on the current Payment Estimate.	
				14	Nov 2, 2020	SYSTEM	(\$14,723.40)		
				14	Nov 2, 2020	SYSTEM	\$14,723.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user woodsk1 overridding Payment Estimate Exception 56 on the current Payment Estimate.	
				15	Nov 17, 2020	SYSTEM	(\$14,723.40)		
				15	Nov 17, 2020	SYSTEM	\$14,723.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overridding Payment Estimate Exception 57 on the current Payment Estimate.	
				16	Dec 2, 2020	SYSTEM	(\$14,723.40)		
				16	Dec 2, 2020	SYSTEM	\$14,723.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overridding Payment Estimate Exception 57 on the current Payment Estimate.	
				17	Dec 16, 2020	SYSTEM	(\$14,723.40)		
				17	Dec 16, 2020	SYSTEM	\$14,723.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user woodsk1 overridding Payment Estimate Exception 57 on the current Payment Estimate.	
	Material Tatal		- Total				\$0.00		
1160 -	Material - Total						\$0.00 \$0.00		
1180 -	BRIDGE GUARDRAIL (THRIE BEAM)	Construction Stockpile		2	May 4, 2020	SYSTEM	\$29,370.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
		Otookhiic		6	Jul 2, 2020	SYSTEM	(\$14,685.00)	Payment Estimate Item Adjustment generated Stockpile Transaction	
				8	Aug 3, 2020	SYSTEM	(\$14,685.00)	Payment Estimate Item Adjustment generated Stockpile Transaction	
			- Total				\$0.00		
	Construction Stockpile - Total						\$0.00		
1180 -							\$0.00		
5004	SLAB EDGE REPAIR (BRIDGES)	Material		17	Dec 16, 2020	SYSTEM	(\$5,398.58)		
				17	Dec 16, 2020	SYSTEM	\$5,398.58	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 55 on the current Payment Estimate.	

Revision 4/1/2020 Page 60 of 61



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
5004		Material - Total					\$0.00	
	Material - Total					\$0.00		
5004 - Total						\$0.00		
5005	SLAB EDGE REPAIR (BRIDGES)	Material		17	Dec 16, 2020	SYSTEM	(\$7,607.09)	
				17	Dec 16, 2020	SYSTEM	\$7,607.09	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 56 on the current Payment Estimate.
	- Total					\$0.00		
	Material - Total						\$0.00	
5005 - Total							\$0.00	
Overall - Total							\$155,097.27	

Revision 4/1/2020 Page 61 of 61