



**Missouri Department of Transportation
Contractor's Pay Estimate Summary**

Report Generated on February 3, 2021

Pay Estimate Created Date: February 1, 2021

Progress Estimate Number 20	Contract ID 200117-H07 Prime Contractor Apex Paving Co.	Pay Period Start January 16, 2021 Pay Period End February 1, 2021	Original Contract Amount \$8,709,119.25 Net Change Order Amount \$834,905.88 Current Contract Amount \$9,544,025.13
---------------------------------------	--	--	--

Approval Date		By User
February 1, 2021	Generated and Approved (and should be considered Draft) at the Project Office Level by	woodsk1
February 1, 2021	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	bolli1
February 3, 2021	Reviewed and Approved at the Central Office Controllers Office Level by	greggd1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
July 1, 2021	July 1, 2021		57.40%

No Milestones Exist for Contract

Contract Total Pay For Estimate No. 20			
	This Estimate	Previous	To Date
200117-H07			
Total Posted Items Pay	\$54,297.98	\$5,423,988.90	\$5,478,286.88
Gross Item Adjustments	\$0.00	\$154,999.19	\$154,999.19
Incentive	\$0.00	\$0.00	\$0.00
Disincentive	\$0.00	\$0.00	\$0.00
Liquidated Damage	\$0.00	\$0.00	\$0.00
Other Contract Adjustments	\$0.00	\$0.00	\$0.00
		\$5,578,988.09	\$5,633,286.07
Contract Total Payable This Estimate:	\$54,297.98		

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J9I3553	5006	6189901	MISC.Additional Mobilization-Rumble Strip	LS	\$3,000.000	1	\$3,000.00
Project J9I3553 - Total							\$3,000.00
J9S3571	1160	7040107	SLAB EDGE REPAIR (BRIDGES)	LF	\$245.390	2	\$490.78
	5100	7040104	HALF-SOLE REPAIR	SQFT	\$112.780	360	\$40,600.80
	5110	7040106	FULL DEPTH REPAIR	SQFT	\$157.500	50	\$7,875.00
	5120	7049902	MISC.FORCE ACCOUNT(bolting deck and steel plates)	EA	\$1.000	2,331.4	\$2,331.40
Project J9S3571 - Total							\$51,297.98
Overall - Total							\$54,297.98

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item Adjustments This Estimate

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9I3553	0050	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Material			-1,585.9	\$57.84	(\$91,728.46)
	0050	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Material		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user woodsk1 overriding Payment Estimate Exception 1 on the current Payment Estimate.	1,585.9	\$57.84	\$91,728.46
	0100	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material			-489.9	\$185.16	(\$90,709.88)
	0100	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overriding Payment Estimate Exception 7 on the current Payment Estimate.	489.9	\$185.16	\$90,709.88
	0410	SEAL COAT AGGREGATE,	Material			-265	\$5.00	(\$1,325.00)



**Missouri Department of Transportation
Contractor's Pay Estimate Summary**

Report Generated on February 3, 2021

Pay Estimate Created Date: February 1, 2021

Progress Estimate Number 20	Contract ID 200117-H07 Prime Contractor Apex Paving Co.	Pay Period Start January 16, 2021 Pay Period End February 1, 2021	Original Contract Amount \$8,709,119.25 Net Change Order Amount \$834,905.88 Current Contract Amount \$9,544,025.13
---------------------------------------	--	--	--

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9I3553		GRADE B1						
	0410	SEAL COAT AGGREGATE, GRADE B1	Material		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overriding Payment Estimate Exception 2 on the current Payment Estimate.	265	\$5.00	\$1,325.00
	0420	CURB BLOCKOUT	Material			-170	\$196.14	(\$33,343.80)
	0420	CURB BLOCKOUT	Material		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overriding Payment Estimate Exception 10 on the current Payment Estimate.	170	\$196.14	\$33,343.80
	0430	HALF-SOLE REPAIR	Material			-755	\$97.74	(\$73,793.70)
	0430	HALF-SOLE REPAIR	Material		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overriding Payment Estimate Exception 33 on the current Payment Estimate.	755	\$97.74	\$73,793.70
	0460	SEAL COAT AGGREGATE, GRADE B1	Material			-288	\$5.00	(\$1,440.00)
	0460	SEAL COAT AGGREGATE, GRADE B1	Material		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overriding Payment Estimate Exception 3 on the current Payment Estimate.	288	\$5.00	\$1,440.00
	0470	CURB BLOCKOUT	Material			-185	\$193.61	(\$35,817.85)
	0470	CURB BLOCKOUT	Material		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overriding Payment Estimate Exception 15 on the current Payment Estimate.	185	\$193.61	\$35,817.85
	0480	HALF-SOLE REPAIR	Material			-723	\$96.76	(\$69,957.48)
	0480	HALF-SOLE REPAIR	Material		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overriding Payment Estimate Exception 36 on the current Payment Estimate.	723	\$96.76	\$69,957.48
	0510	SEAL COAT AGGREGATE, GRADE B1	Material			-265	\$5.00	(\$1,325.00)
	0510	SEAL COAT AGGREGATE, GRADE B1	Material		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overriding Payment Estimate Exception 4 on the current Payment Estimate.	265	\$5.00	\$1,325.00
	0520	CURB BLOCKOUT	Material			-170	\$196.14	(\$33,343.80)
	0520	CURB BLOCKOUT	Material		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overriding Payment Estimate Exception 21 on the current Payment Estimate.	170	\$196.14	\$33,343.80
	0530	HALF-SOLE REPAIR	Material			-853	\$97.74	(\$83,372.22)
	0530	HALF-SOLE REPAIR	Material		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overriding Payment Estimate Exception 40 on the current Payment Estimate.	853	\$97.74	\$83,372.22
	0560	SEAL COAT AGGREGATE,	Material			-241	\$5.00	(\$1,205.00)



**Missouri Department of Transportation
Contractor's Pay Estimate Summary**

Report Generated on February 3, 2021

Pay Estimate Created Date: February 1, 2021

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
Progress Estimate Number 20		Contract ID 200117-H07 Prime Contractor Apex Paving Co.		Pay Period Start January 16, 2021 Pay Period End February 1, 2021		Original Contract Amount \$8,709,119.25 Net Change Order Amount \$834,905.88 Current Contract Amount \$9,544,025.13		
J9I3553		GRADE B1						
	0560	SEAL COAT AGGREGATE, GRADE B1	Material		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user woodsk1 overriding Payment Estimate Exception 5 on the current Payment Estimate.	241	\$5.00	\$1,205.00
	0570	CURB BLOCKOUT	Material			-155	\$199.15	(\$30,868.25)
	0570	CURB BLOCKOUT	Material		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overriding Payment Estimate Exception 27 on the current Payment Estimate.	155	\$199.15	\$30,868.25
J9S3571	1140	SEAL COAT AGGREGATE, GRADE B1	Material			-287	\$5.00	(\$1,435.00)
	1140	SEAL COAT AGGREGATE, GRADE B1	Material		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user woodsk1 overriding Payment Estimate Exception 6 on the current Payment Estimate.	287	\$5.00	\$1,435.00
Total								\$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

Report Generated on February 3, 2021

Contract Project Information					
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work
J9I3553	FAF 60-4(86)	Resurface	60	SCOTT	from I-57 to Spring Creek
J9S3571	FAS S703(31)	Resurface	69	MISSISSIPPI	from I-57 to Bridge K0950

Totals by Job Numbers				
J9I3553		This Estimate	Previous	To Date
	Posted Item Pay	\$3,000.00	\$3,726,388.68	\$3,729,388.68
	Gross Item Adjustments	\$0.00	\$84,557.15	\$84,557.15
	Gross Item Pay	\$3,000.00	\$3,810,945.83	\$3,813,945.83
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damages	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
J9S3571		This Estimate	Previous	To Date
	Posted Item Pay	\$51,297.98	\$1,697,600.22	\$1,748,898.20
	Gross Item Adjustments	\$0.00	\$70,442.04	\$70,442.04
	Gross Item Pay	\$51,297.98	\$1,768,042.26	\$1,819,340.24
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damages	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Report Generated on February 3, 2021

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepancies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 4030103, Project Item Line Number 0050, Material Set 403010396, Material 0403SP125CLG - Superpave 12.5 mm, Des C 80 Gyros, Acceptance Action Generic AspHigh is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 4094011, Project Item Line Number 0410, Material Set 409401196, Material 1003GB - Aggregate for Seal Coat Grade B1, Acceptance Action Generic 1003GB is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 4094011, Project Item Line Number 0460, Material Set 409401196, Material 1003GB - Aggregate for Seal Coat Grade B1, Acceptance Action Generic 1003GB is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 4094011, Project Item Line Number 0510, Material Set 409401196, Material 1003GB - Aggregate for Seal Coat Grade B1, Acceptance Action Generic 1003GB is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 4094011, Project Item Line Number 0560, Material Set 409401196, Material 1003GB - Aggregate for Seal Coat Grade B1, Acceptance Action Generic 1003GB is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3571, Item 4094011, Project Item Line Number 1140, Material Set 409401196, Material 1003GB - Aggregate for Seal Coat Grade B1, Acceptance Action Generic 1003GB is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 6131010, Project Item Line Number 0100, Material Set 613101096, Material 1005FACCNS..CA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNS..CA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 6131010, Project Item Line Number 0100, Material Set 613101096, Material 100510..CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510..CPCMLD is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 6131010, Project Item Line Number 0100, Material Set 613101096, Material 0501CCPAEA - Concrete, Pavement HES w/Air, Acceptance Action 0501CCPAEA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7034600, Project Item Line Number 0420, Material Set 703460096, Material 1039ERRAS - Epoxy Bonding Agent-Resin Anchor Systems, Acceptance Action Generic 1039ERRAS is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7034600, Project Item Line Number 0420, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7034600, Project Item Line Number 0420, Material Set 703460096, Material 1005FACCNS..CA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNS..CA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7034600, Project Item Line Number 0420, Material Set 703460096, Material 100510..CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510..CPCMLD is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7034600, Project Item Line Number 0420, Material Set 703460096, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7034600, Project Item Line Number 0470, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7034600, Project Item Line Number 0470, Material Set 703460096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7034600, Project Item Line Number 0470, Material Set 703460096, Material 1005FACCNS..CA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNS..CA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7034600, Project Item Line Number 0470, Material Set 703460096, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7034600, Project Item Line Number 0470, Material Set 703460096, Material 100510..CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510..CPCMLD is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7034600, Project Item Line Number 0470, Material Set 703460096, Material 1039ERRAS - Epoxy Bonding Agent-Resin Anchor Systems, Acceptance Action Generic 1039ERRAS is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7034600, Project Item Line Number 0520, Material Set 703460096, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7034600, Project Item Line Number 0520, Material Set 703460096, Material 1039ERRAS - Epoxy Bonding Agent-Resin Anchor Systems, Acceptance Action Generic 1039ERRAS is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7034600, Project Item Line Number 0520, Material Set 703460096, Material 1005FACCNS..CA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNS..CA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7034600, Project Item Line Number 0520, Material Set 703460096, Material 100510..CPCMLD - PCCP or Masonry 1" Max LS/DO,	No Remark was entered by Engineer	woodsk1	Overridden



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Report Generated on February 3, 2021

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepancies	Explanation	Entered By	Status
Acceptance Action Generic 100510..CPCMLD is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7034600, Project Item Line Number 0520, Material Set 703460096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7034600, Project Item Line Number 0520, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 1039ERRAS - Epoxy Bonding Agent-Resin Anchor Systems, Acceptance Action Generic 1039ERRAS is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 100510..CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510..CPCMLD is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 1005FACCNS..CA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNS..CA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7040104, Project Item Line Number 0430, Material Set 704010496, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7040104, Project Item Line Number 0430, Material Set 704010496, Material 0500XX - Concrete Plant Inspection Review, Acceptance Action Generic 0500XX is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7040104, Project Item Line Number 0430, Material Set 704010496, Material 1005FACCNS..CA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNS..CA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7040104, Project Item Line Number 0480, Material Set 704010496, Material 1005FACCNS..CA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNS..CA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7040104, Project Item Line Number 0480, Material Set 704010496, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7040104, Project Item Line Number 0480, Material Set 704010496, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7040104, Project Item Line Number 0480, Material Set 704010496, Material 0500XX - Concrete Plant Inspection Review, Acceptance Action Generic 0500XX is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7040104, Project Item Line Number 0530, Material Set 704010496, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Contract Line Items and Total Paid for All Estimates**

Report Generated on February 3, 2021

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200117-H07	J913553	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.26	\$36,000.00	\$9,504.00
		0001	0020	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	6,032.50	0.00	6,032.50	TONS	1,642.00	\$32.62	\$53,562.04
		0001	0030	3105002	GRAVEL (A) OR CRUSHED STONE (B)	17.00	0.00	17.00	TONS	0.00	\$18.91	\$0.00
		0001	0040	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	16,232.80	0.00	16,232.80	TONS	6,568.80	\$56.39	\$370,414.63
		0001	0050	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	62,977.90	0.00	62,977.90	TONS	25,585.90	\$57.84	\$1,479,888.46
		0001	0060	4071005	TACK COAT	60,125.00	0.00	60,125.00	GAL	22,653.00	\$2.14	\$48,477.42
		0001	0070	4134000	BITUMINOUS FOG SEAL	5,508.00	0.00	5,508.00	GAL	0.00	\$5.11	\$0.00
		0001	0080	6083003	3 IN. CONCRETE MEDIAN STRIP	2,330.00	0.00	2,330.00	SQYD	0.00	\$67.62	\$0.00
		0001	0090	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$500.00	\$0.00
		0001	0100	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	642.70	0.00	642.70	SQYD	566.80	\$185.16	\$104,948.69
		0001	0110	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	64.00	0.00	64.00	SQYD	10.00	\$10.00	\$100.00
		0001	0120	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	64.00	0.00	64.00	SQYD	10.00	\$10.00	\$100.00
		0001	0130	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	2,204.00	0.00	2,204.00	LF	1,665.00	\$6.00	\$9,990.00
		0001	0140	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	1,180.00	0.00	1,180.00	EA	822.00	\$10.00	\$8,220.00
		0001	0150	6131017	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	10.00	0.00	10.00	EA	1.00	\$10.00	\$10.00
		0001	0160	6133020	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	13.10	0.00	13.10	TONS	0.00	\$532.33	\$0.00
		0001	0170	6133021	REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	28.00	0.00	28.00	SQYD	0.00	\$103.80	\$0.00
		0001	0180	6161005	CONSTRUCTION SIGNS	3,888.00	0.00	3,888.00	SQFT	2,948.00	\$6.50	\$19,162.00
		0001	0190	6161008	ADVANCED WARNING RAIL SYSTEM	2.00	0.00	2.00	EA	0.00	\$45.00	\$0.00
		0001	0200	6161009	FLAG ASSEMBLY	4.00	0.00	4.00	EA	0.00	\$20.00	\$0.00
		0001	0210	6161025	CHANNELIZER (TRIM LINE)	712.00	0.00	712.00	EA	385.00	\$15.00	\$5,775.00
		0001	0220	6161030	TYPE III MOVEABLE BARRICADE	45.00	0.00	45.00	EA	0.00	\$100.00	\$0.00
		0001	0230	6161033	DIRECTIONAL INDICATOR BARRICADE	133.00	0.00	133.00	EA	76.00	\$35.00	\$2,660.00
		0001	0240	6161040	FLASHING ARROW PANEL	8.00	0.00	8.00	EA	4.00	\$400.00	\$1,600.00
		0001	0250	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$3,500.00	\$7,000.00
		0001	0260	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$208,790.05	\$208,790.05
		0001	0270	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	205,637.00	0.00	205,637.00	LF	0.00	\$0.23	\$0.00
		0001	0280	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	161,998.00	0.00	161,998.00	LF	0.00	\$0.23	\$0.00
		0001	0290	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	2,400.00	0.00	2,400.00	LF	0.00	\$1.00	\$0.00
		0001	0300	6209901	MISC.TEMPORARY PAVEMENT MARKING PAINT	1.00	0.00	1.00	LS	1.00	\$15,000.00	\$15,000.00
		0001	0310	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	18,810.00	0.00	18,810.00	SQYD	5,824.60	\$6.49	\$37,801.65
		0001	0320	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	22,495.00	0.00	22,495.00	SQYD	11,824.00	\$7.25	\$85,724.00
		0001	0330	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	3,038.00	0.00	3,038.00	STA	1,162.00	\$18.75	\$21,787.50
		0001	0340	7034001	CLASS B-1 CONCRETE	3.30	0.00	3.30	CUYD	0.00	\$2,400.00	\$0.00
		0010	0350	6061060	MGS GUARDRAIL	8,050.00	0.00	8,050.00	LF	4,350.00	\$20.00	\$87,000.00
		0010	0360	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	24.00	0.00	24.00	EA	10.00	\$2,900.00	\$29,000.00
		0010	0370	6061080	MGS END ANCHOR	6.00	0.00	6.00	EA	6.00	\$1,000.00	\$6,000.00
		0010	0380	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	30.00	0.00	30.00	EA	16.00	\$2,700.00	\$43,200.00
		0040	0390	9031220	PIPE POSTS	820.00	0.00	820.00	LB	0.00	\$6.00	\$0.00
		0070	0400	4091048	EMULSIFIED ASPHALT, SEAL COAT	106.00	0.00	106.00	GAL	106.00	\$5.00	\$530.00
		0070	0410	4094011	SEAL COAT AGGREGATE, GRADE B1	265.00	0.00	265.00	SQYD	265.00	\$5.00	\$1,325.00
		0070	0420	7034600	CURB BLOCKOUT	170.00	0.00	170.00	LF	170.00	\$196.14	\$33,343.80
		0070	0430	7040104	HALF-SOLE REPAIR	240.00	515.00	755.00	SQFT	755.00	\$97.74	\$73,793.70
		0070	0440	7040113	CLEANING AND EPOXY COATING	584.00	0.00	584.00	SQFT	584.00	\$13.00	\$7,592.00



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Contract Line Items and Total Paid for All Estimates**

Report Generated on February 3, 2021

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200117-H07	J9I3553	0071	0450	4091048	EMULSIFIED ASPHALT, SEAL COAT	115.00	0.00	115.00	GAL	115.00	\$5.00	\$575.00
		0071	0460	4094011	SEAL COAT AGGREGATE, GRADE B1	288.00	0.00	288.00	SQYD	288.00	\$5.00	\$1,440.00
		0071	0470	7034600	CURB BLOCKOUT	185.00	0.00	185.00	LF	185.00	\$193.61	\$35,817.85
		0071	0480	7040104	HALF-SOLE REPAIR	260.00	463.00	723.00	SQFT	723.00	\$96.76	\$69,957.48
		0071	0490	7040113	CLEANING AND EPOXY COATING	628.00	0.00	628.00	SQFT	628.00	\$13.00	\$8,164.00
		0072	0500	4091048	EMULSIFIED ASPHALT, SEAL COAT	106.00	0.00	106.00	GAL	106.00	\$5.00	\$530.00
		0072	0510	4094011	SEAL COAT AGGREGATE, GRADE B1	265.00	0.00	265.00	SQYD	265.00	\$5.00	\$1,325.00
		0072	0520	7034600	CURB BLOCKOUT	170.00	0.00	170.00	LF	170.00	\$196.14	\$33,343.80
		0072	0530	7040104	HALF-SOLE REPAIR	240.00	613.00	853.00	SQFT	853.00	\$97.74	\$83,372.22
		0072	0540	7040113	CLEANING AND EPOXY COATING	584.00	0.00	584.00	SQFT	0.00	\$13.00	\$0.00
		0073	0550	4091048	EMULSIFIED ASPHALT, SEAL COAT	96.00	0.00	96.00	GAL	96.00	\$5.00	\$480.00
		0073	0560	4094011	SEAL COAT AGGREGATE, GRADE B1	241.00	0.00	241.00	SQYD	241.00	\$5.00	\$1,205.00
		0073	0570	7034600	CURB BLOCKOUT	155.00	0.00	155.00	LF	155.00	\$199.15	\$30,868.25
		0073	0580	7040104	HALF-SOLE REPAIR	220.00	545.00	765.00	SQFT	765.00	\$98.90	\$75,658.50
		0073	0590	7040113	CLEANING AND EPOXY COATING	534.00	0.00	534.00	SQFT	0.00	\$13.00	\$0.00
		0074	0600	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	56.00	0.00	56.00	LF	0.00	\$325.00	\$0.00
		0074	0610	2169903	MISC.Remove and Replace Curb	16.00	0.00	16.00	LF	0.00	\$300.00	\$0.00
		0074	0620	4091048	EMULSIFIED ASPHALT, SEAL COAT	348.00	0.00	348.00	GAL	0.00	\$5.00	\$0.00
		0074	0630	4094011	SEAL COAT AGGREGATE, GRADE B1	870.00	0.00	870.00	SQYD	0.00	\$5.00	\$0.00
		0074	0640	7034214	CLASS B-2 CONCRETE	5.60	0.00	5.60	CUYD	0.00	\$5,218.44	\$0.00
		0074	0650	7034600	CURB BLOCKOUT	560.00	0.00	560.00	LF	0.00	\$181.01	\$0.00
		0074	0660	7040104	HALF-SOLE REPAIR	230.00	0.00	230.00	SQFT	0.00	\$98.30	\$0.00
		0074	0670	7040113	CLEANING AND EPOXY COATING	1,971.00	0.00	1,971.00	SQFT	0.00	\$13.00	\$0.00
		0074	0680	7101000	REINFORCING STEEL (EPOXY COATED)	1,820.00	0.00	1,820.00	LB	0.00	\$5.00	\$0.00
		0074	0690	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$5,000.00	\$0.00
		0074	0700	7174001	PREFORMED SILICONE OR EPDM EXPANSION JOINT SYSTEM	56.00	0.00	56.00	LF	0.00	\$75.00	\$0.00
		0075	0710	4091048	EMULSIFIED ASPHALT, SEAL COAT	162.00	0.00	162.00	GAL	0.00	\$5.00	\$0.00
		0075	0720	4094011	SEAL COAT AGGREGATE, GRADE B1	406.00	0.00	406.00	SQYD	0.00	\$5.00	\$0.00
		0075	0730	7034600	CURB BLOCKOUT	261.00	0.00	261.00	LF	0.00	\$189.97	\$0.00
		0075	0740	7040104	HALF-SOLE REPAIR	370.00	0.00	370.00	SQFT	0.00	\$98.22	\$0.00
		0075	0750	7040113	CLEANING AND EPOXY COATING	1,100.00	0.00	1,100.00	SQFT	0.00	\$13.00	\$0.00
		0076	0760	4091048	EMULSIFIED ASPHALT, SEAL COAT	185.00	0.00	185.00	GAL	0.00	\$5.00	\$0.00
		0076	0770	4094011	SEAL COAT AGGREGATE, GRADE B1	463.00	0.00	463.00	SQYD	0.00	\$5.00	\$0.00
		0076	0780	7040104	HALF-SOLE REPAIR	400.00	1,872.00	2,272.00	SQFT	2,272.00	\$107.41	\$244,035.52
		0076	0790	7040113	CLEANING AND EPOXY COATING	989.00	0.00	989.00	SQFT	0.00	\$13.00	\$0.00
		0077	0800	4091048	EMULSIFIED ASPHALT, SEAL COAT	185.00	0.00	185.00	GAL	0.00	\$5.00	\$0.00
		0077	0810	4094011	SEAL COAT AGGREGATE, GRADE B1	463.00	0.00	463.00	SQYD	0.00	\$5.00	\$0.00
		0077	0820	7040104	HALF-SOLE REPAIR	400.00	2,564.00	2,964.00	SQFT	2,964.00	\$107.41	\$318,363.24
		0077	0830	7040113	CLEANING AND EPOXY COATING	989.00	0.00	989.00	SQFT	0.00	\$13.00	\$0.00
		0001	5001	6162004	TEMPORARY SHORT-TERM RUMBLE STRIPS	0.00	4.00	4.00	EA	4.00	\$2,362.50	\$9,450.00
		0001	5002	6161010	RELOCATED SIGNS	0.00	804.00	804.00	SQFT	268.00	\$6.83	\$1,830.44
		0001	5003	6129902	MISC.TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	0.00	24,666.75	24,666.75	EA	24,666.75	\$1.00	\$24,666.75
		0076	5004	7040107	SLAB EDGE REPAIR (BRIDGES)	0.00	22.00	22.00	LF	22.00	\$245.39	\$5,398.58
		0077	5005	7040107	SLAB EDGE REPAIR (BRIDGES)	0.00	31.00	31.00	LF	31.00	\$245.39	\$7,607.09
		0001	5006	6189901	MISC.Additional Mobilization-Rumble Strip	0.00	1.00	1.00	LS	1.00	\$3,000.00	\$3,000.00
Project J9I3553 - Total Value Posted to Date as of Report Generated Date												\$3,729,388.66



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Contract Line Items and Total Paid for All Estimates**

Report Generated on February 3, 2021

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200117-H07	J9S3571	0001	0840	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$2,600.00	\$2,600.00
		0001	0850	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	2,161.00	0.00	2,161.00	TONS	1,817.86	\$35.59	\$64,697.64
		0001	0860	3105002	GRAVEL (A) OR CRUSHED STONE (B)	350.00	0.00	350.00	TONS	0.00	\$44.12	\$0.00
		0001	0870	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	3,194.60	325.50	3,520.10	TONS	3,520.10	\$56.26	\$198,040.83
		0001	0880	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	17,210.20	86.00	17,296.20	TONS	17,255.60	\$60.51	\$1,044,136.36
		0001	0890	4071005	TACK COAT	14,965.00	0.00	14,965.00	GAL	12,730.00	\$2.14	\$27,242.20
		0001	0900	4134000	BITUMINOUS FOG SEAL	2,033.00	3,767.00	5,800.00	GAL	4,800.00	\$4.15	\$19,920.00
		0001	0910	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	4.00	0.00	4.00	EA	4.00	\$250.00	\$1,000.00
		0001	0920	6161005	CONSTRUCTION SIGNS	2,364.00	0.00	2,364.00	SQFT	2,364.00	\$6.50	\$15,366.00
		0001	0930	6161009	FLAG ASSEMBLY	7.00	0.00	7.00	EA	7.00	\$20.00	\$140.00
		0001	0940	6161025	CHANNELIZER (TRIM LINE)	186.00	0.00	186.00	EA	40.00	\$15.00	\$600.00
		0001	0950	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$3,500.00	\$7,000.00
		0001	0960	6162000A	WORK ZONE TRAFFIC SIGNAL SYSTEM	1.00	0.00	1.00	EA	1.00	\$8,400.00	\$8,400.00
		0001	0970	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	2.00	0.00	2.00	EA	2.00	\$1,800.00	\$3,600.00
		0001	0980	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$107,079.93	\$107,079.93
		0001	0990	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	1,212.00	0.00	1,212.00	LF	1,212.00	\$2.00	\$2,424.00
		0001	1000	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	2,000.00	0.00	2,000.00	LF	2,000.00	\$2.00	\$4,000.00
		0001	1010	6205309	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	24.00	0.00	24.00	LF	24.00	\$10.00	\$240.00
		0001	1020	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	114,312.00	0.00	114,312.00	LF	114,312.00	\$0.11	\$12,574.32
		0001	1030	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	31,999.00	0.00	31,999.00	LF	31,999.00	\$0.11	\$3,519.89
		0001	1040	6207001	PAVEMENT MARKING REMOVAL	4,006.00	0.00	4,006.00	LF	4,006.00	\$2.00	\$8,012.00
		0001	1050	6209901	MISC.TEMPORARY PAVEMENT MARKING PAINT	1.00	0.00	1.00	LS	0.00	\$0.00	\$0.00
		0001	1060	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	266.00	0.00	266.00	SQYD	266.00	\$8.76	\$2,330.16
		0001	1070	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	3,431.00	0.00	3,431.00	SQYD	3,431.00	\$9.00	\$30,879.00
		0010	1080	6061060	MGS GUARDRAIL	140.00	0.00	140.00	LF	140.00	\$22.00	\$3,080.00
		0010	1090	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	4.00	0.00	4.00	EA	4.00	\$3,000.00	\$12,000.00
		0010	1100	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	4.00	0.00	4.00	EA	4.00	\$2,900.00	\$11,600.00
		0070	1110	2169902	MISC.Removal of Existing End Post	4.00	0.00	4.00	EA	4.00	\$1,250.00	\$5,000.00
		0070	1120	2169903	MISC.Removal of Existing Curb and Guardrail	166.00	0.00	166.00	LF	166.00	\$125.00	\$20,750.00
		0070	1130	4091048	EMULSIFIED ASPHALT, SEAL COAT	115.00	0.00	115.00	GAL	115.00	\$5.00	\$575.00
		0070	1140	4094011	SEAL COAT AGGREGATE, GRADE B1	287.00	0.00	287.00	SQYD	287.00	\$5.00	\$1,435.00
		0070	1150	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	20.00	11.00	31.00	SQFT	31.00	\$311.16	\$9,645.96
		0070	1160	7040107	SLAB EDGE REPAIR (BRIDGES)	60.00	2.00	62.00	LF	62.00	\$245.39	\$15,214.18
		0070	1170	7040113	CLEANING AND EPOXY COATING	308.00	0.00	308.00	SQFT	308.00	\$13.00	\$4,004.00
		0070	1180	7134000	BRIDGE GUARDRAIL (THRIE BEAM)	178.00	0.00	178.00	LF	178.00	\$286.43	\$50,984.54
0070	5100	7040104	HALF-SOLE REPAIR	0.00	360.00	360.00	SQFT	360.00	\$112.78	\$40,600.80		
0070	5110	7040106	FULL DEPTH REPAIR	0.00	50.00	50.00	SQFT	50.00	\$157.50	\$7,875.00		
0070	5120	7049902	MISC.FORCE ACCOUNT(bolting deck and steel plates)	0.00	2,331.40	2,331.40	EA	2,331.40	\$1.00	\$2,331.40		
Project J9S3571 - Total Value Posted to Date as of Report Generated Date												\$1,748,898.20
200117-H07 Overall - Total Value Posted to Date as of Report Generated Date												\$5,478,286.86



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Installed Locations of Paid Line Items (This Estimate Only)**

Report Generated on February 3, 2021

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J913553

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/Log Mile	Offset/Distance	To Station/Log Mile	Offset/Distance	Comments
5006	6189901	MISC.	1/29/21	2/1/21	1.00	LS	Route 60.		1		2	Route 60.

Project: J9S3571

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/Log Mile	Offset/Distance	To Station/Log Mile	Offset/Distance	Comments
1160	7040107	SLAB EDGE REPAIR (BRIDGES)	1/29/21	2/1/21	2.00	LF	Route 60/62. Bridge F0058.	331.341		331.358		Route 60/62. Bridge F0058.
5100	7040104	HALF-SOLE REPAIR	1/29/21	2/1/21	360.00	SQFT	Route 60/62. Bridge F0058.	331.341		331.358		Route 60/62. Bridge F0058.
5110	7040106	FULL DEPTH REPAIR	1/29/21	2/1/21	50.00	SQFT	Route 60/62. Bridge F0058.	331.341		331.358		Route 60/62. Bridge F0058.
5120	7049902	MISC.	1/29/21	2/1/21	2,331.40	EA	Route 60/62. Bridge F0058.	331.341		331.358		Route 60/62. Bridge F0058.

The information below this line are details for Construction Signs (if applicable).

Project	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
J913553	0180	April 14, 2020	377	WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD	40.91	Left/Right	2.00	16				32
				CONST-3A 60x48 20.00 FINE SIGN	41.099	Left/Right	2.00	20		40		
				GO20-2 48x24 8.00 END ROAD WORK	45.40	Left/Right	2.00	8		16		
				R2-1 36x48 12.00 SPEED LIMIT XX	45.20	Left/Right	2.00	12		24		
				R4-2 36x48 12.00 PASS WITH CARE	45.00	Left/Right	2.00	12		24		
				G020-5aP 36x24 6.00 WORK ZONE (PLAQUE)	45.00	Left/Right	2.00	6		12		
				WO8-15 48x48 16.00 GROOVED PAVEMENT	44.044	Left/Right	2.00	16		32		
				WO8-15p 30x24 5.00 MOTORCYCLE (PLAQUE)	44.044	Left/Right	2.00	5		10		
				WO8-15 48x48 16.00 GROOVED PAVEMENT	42.268	Left/Right	2.00	16		32		
				WO8-15p 30x24 5.00 MOTORCYCLE (PLAQUE)	42.268	Left/Right	2.00	5		10		
				R2-1 36x48 12.00 SPEED LIMIT XX	41.90	Left/Right	2.00	12		24		
				CONST-3X 56x12 4.67 SPEEDING/PASSING (PLATE)	41.099	Left/Right	2.00	4.67		9.34		
				G020-5aP 36x24 6.00 WORK ZONE (PLAQUE)	41.29	Left/Right	2.00	6		12		
				R4-1 36x48 12.00 DO NOT PASS	41.29	Left/Right	2.00	12		24		
				WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD	41.47	Left/Right	2.00	16		32		
				WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED	41.76	Left	1.00	16		16		
				WO4-1aR 48x48 16.00 MERGE (SYMBOL FROM RIGHT)	41.76	Right	1.00	16		16		
				G020-5aP 36x24 6.00 WORK ZONE (PLAQUE)	41.90	Left/Right	2.00	6		12		
		April 20, 2020	217	CONST-3A 60x48 20.00 FINE SIGN	42.87	Westbound Rte 60 LT/RT	2.00	20	40			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD	42.68	Westbound Rte 60 LT/RT	2.00	16	32			
				G020-5aP 36x24 6.00 WORK ZONE (PLAQUE)	43.68	Westbound Rte 60 LT/RT	2.00	6	12			
				WO4-1aR 48x48 16.00 MERGE (SYMBOL FROM RIGHT)	43.54	Westbound Rte 60 LT	1.00	16	16			
				R2-1 36x48 12.00 SPEED LIMIT XX	43.68	Westbound Rte 60 LT/RT	2.00	12	24			
				WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD	43.25	Westbound Rte 60 LT/RT	2.00	16	32			
				R4-1 36x48 12.00 DO NOT PASS	43.06	Westbound Rte 60 LT/RT	2.00	12	24			
				G020-5aP 36x24 6.00 WORK ZONE (PLAQUE)	43.06	Westbound Rte 60 LT/RT	2.00	6	12			
				CONST-3X 56x12 4.67 SPEEDING/PASSING (PLATE)	42.87	Westbound Rte 60 LT/RT	2.00	4.67	9.34			
				WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED	43.54	Westbound Rte 60 RT	1.00	16	16			
				May 18, 2020	12	R3-7L 30x30 6.25 LEFT LANE MUST TURN LEFT	43.044	RT and LT	2.00	6.25	12.5	
						June 24, 2020	377	R4-1 36x48 12.00 DO NOT PASS	37.263	RT/LT	2.00	12.00
		G020-5aP 36x24 6.00 WORK ZONE (PLAQUE)	37.263					RT/LT	2.00	6.00	12	
		CONST-3A 60x48 20.00 FINE SIGN	37.059	RT/LT	2.00	20.00	40					
		WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD	36.853	RT/LT	2.00	16.00	32					
		GO20-2 48x24 8.00 END ROAD WORK	39.66	RT/LT	2.00	8.00	16					
		R2-1 36x48 12.00 SPEED LIMIT XX	39.47	RT/LT	2.00	12.00	24					
		G020-5aP 36x24 6.00 WORK ZONE (PLAQUE)	39.284	RT/LT	2.00	6.00	12					
		R4-2 36x48 12.00 PASS WITH CARE	39.284	RT/LT	2.00	12.00	24					
		WO8-15p 30x24 5.00 MOTORCYCLE (PLAQUE)	37.941	RT/LT	4.00	5.00	20					
		WO8-15 48x48 16.00 GROOVED PAVEMENT	37.941	RT/LT	4.00	16.00	64					
		G020-5aP 36x24 6.00 WORK ZONE (PLAQUE)	37.899	RT/LT	2.00	6.00	12					
		R2-1 36x48 12.00 SPEED LIMIT XX	37.899	RT/LT	2.00	12.00	24					



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Installed Locations of Paid Line Items (This Estimate Only)**

Report Generated on February 3, 2021

**The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.
The information below this line are details for Construction Signs (if applicable).**

Project	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post		
J913553	0180	June 24, 2020	377	W04-1aR 48x48 16.00 MERGE (SYMBOL FROM RIGHT)		37.695	LT	1.00	16		16.00	16		
				W020-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		37.695	RT	1.00	16	16.00	16			
				W020-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD		37.473	RT/LT	2.00	16	16.00	32			
				CONST-3X 56x12 4.67 SPEEDING/PASSING (PLATE)		37.059	RT/LT	2.00	4.67	4.67	9.34			
		June 25, 2020	0	W03-2 48x48 16.00 YIELD AHEAD (SYMBOL)	24.525	24.525	I-55 To Route 60 Ramp	1.00	16	16.00	16			
				R1-2 48 TRI 6.93 YIELD	24.548	24.548	I-55 To Route 60 Ramp	1	6.93	6.93	6.93			
				W04-1R 48x48 16.00 MERGE (SYMBOL FROM RIGHT)	24.567	24.567	Exit 66B Ramp	1.00	16	16.00	16			
				R4-2 36x48 12.00 PASS WITH CARE	25.358	25.358	Route 60 End Of Work Zone	2.00	12	12.00	24			
				E05-1 36x48 12.00 GORE EXIT	24.407	24.407	Exit 66B Ramp	1.00	12	12.00	12			
				R1-2 48 TRI 6.93 YIELD	24.262	24.262	Exit 66B Ramp	1.00	6.93	6.93	6.93			
				R2-1 36x48 12.00 SPEED LIMIT XX	24.198	24.198	Exit 66B Ramp	1.00	12	12.00	12			
				W03-2 48x48 16.00 YIELD AHEAD (SYMBOL)	24.205	24.025	Exit 66B Ramp	1.00	16	16.00	16			
				W020-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD	1.4	1.4	I-57	2.00	16	16.00	32			
				CONST-3X 56x12 4.67 SPEEDING/PASSING (PLATE)	1.2	1.2	I-57	2.00	4.67	4.67	9.34			
				CONST-3A 60x48 20.00 FINE SIGN	1.2	1.2	I-57	2.00	20	20.00	40			
				R4-1 36x48 12.00 DO NOT PASS	1.0	1.0	I-57	2.00	12	12.00	24			
				W020-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD	0.8	0.8	I-57	2.00	16	16.00	32			
				W04-1aL 48x48 16.00 MERGE (SYMBOL FROM LEFT)	0.6	0.6	I-57	1.00	16	16.00	16			
				W020-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED	0.6	0.6	I-57	1.00	16	16.00	16			
				R2-1 36x48 12.00 SPEED LIMIT XX	0.2	0.2	I-57	2.00	12	12.00	24			
				W05-1 48x48 16.00 ROAD/BRIDGE/RAMP NARROWS	0.2	0.2	I-55 To Route 60 Ramp	1.00	16	16.00	16			
				R2-1 36x48 12.00 SPEED LIMIT XX	25.557	25.557	Route 60 End Of Work Zone	2.00	12	12.00	24			
				W020-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD	0.2	0.2	I-55 To Route 60 Ramp	1.00	16	16.00	16			
				W020-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD	0.2	0.2	Exit 66B Ramp	1.00	16	16.00	16			
				W05-1 48x48 16.00 ROAD/BRIDGE/RAMP NARROWS	0.2	0.2	Exit 66B Ramp	1.00	16	16.00	16			
				June 30, 2020	0	R2-1 36x48 12.00 SPEED LIMIT XX	33.5	33.5	Route 60	2.00	12	12.00	24	
						W020-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED	33.70	33.70	Route 60	1.00	16	16.00	16	
						W04-1aL 48x48 16.00 MERGE (SYMBOL FROM LEFT)	33.70	33.70	Route 60	1.00	16	16.00	16	
						W020-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD	33.89	33.89	Route 60	2.00	16	16.00	32	
						R4-1 36x48 12.00 DO NOT PASS	34.19	34.19	Route 60	2.00	12	12.00	24	
						CONST-3A 60x48 20.00 FINE SIGN	34.49	34.49	Route 60	2.00	20	20.00	40	
						W020-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD	34.79	34.79	Route 60	2.00	16	16.00	32	
						R4-2 36x48 12.00 PASS WITH CARE	35.2	35.2	Route 60	2.00	12	12.00	24	
						R2-1 36x48 12.00 SPEED LIMIT XX	35.5	35.5	Route 60	2.00	12	12.00	24	
						September 8, 2020	84	W08-15p 30x24 5.00 MOTORCYCLE (PLAQUE)		29.461	Bridge L0956	2.00	5	10
								W08-15 48x48 16.00 GROOVED PAVEMENT		31.168	Bridge L0955	2.00	16	32
								W08-15p 30x24 5.00 MOTORCYCLE (PLAQUE)		31.168	Bridge L0955	2.00	5	10
								W08-15 48x48 16.00 GROOVED PAVEMENT		29.461	Bridge L0956	2.00	16	32
						September 23, 2020	222	W08-1 48x48 16.00 BUMP		45.896	East of Bridge B0548	2.00	16	32
				W08-15 48x48 16.00 GROOVED PAVEMENT				45.896	East of Bridge B0548	2.00	16	32		
		W08-15p 30x24 5.00 MOTORCYCLE (PLAQUE)		46.507	East of A0030			2.00	5	10				
		W08-1 48x48 16.00 BUMP		46.507	East of Bridge A0030			2.00	16	32				
		W08-15 48x48 16.00 GROOVED PAVEMENT		46.507	East of A0030			2.00	16	32				
		W08-15p 30x24 5.00 MOTORCYCLE (PLAQUE)		45.896	East of Bridge B0548			2.00	5	10				
		See Special Sign Details						0.00						
		W08-1 48x48 16.00 BUMP		43.085	West of Rte FF (Stoddard)			2.00	16	32				
		W08-15p 30x24 5.00 MOTORCYCLE (PLAQUE)		43.085	West of Rte FF (Stoddard)			2.00	5	10				
		W08-15 48x48 16.00 GROOVED PAVEMENT		43.085	West of Rte FF (Stoddard)			2.00	16	32				
		October 2, 2020	303	W08-15 48x48 16.00 GROOVED PAVEMENT		43.042	Route 60	1.00	16	16				
				W08-1 48x48 16.00 BUMP		43.042	Route 60	1.00	16	16				
				W08-11 48x48 16.00 UNEVEN LANES		46.179	Route 60	2.00	16	32				
				W08-17 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		45.138	Route 60	2.00	16	32				



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Installed Locations of Paid Line Items (This Estimate Only)**

Report Generated on February 3, 2021

**The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.
The information below this line are details for Construction Signs (if applicable).**

Project	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post				
J913553	0180	October 2, 2020	303	W08-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)		45.138	Route 60	2.00	5			10				
				W020-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		45.041	Route 60 Side Road	2.00	16			32				
				W08-11 LANES		44.129	Route 60	2.00	16			32				
				W08-17 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		43.084	Route 60	2.00	16			32				
				W08-11 48x48 16.00 UNEVEN LANES		43.061	Route 60	2.00	16			32				
				W020-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		43.042	Route 60	2.00	16			32				
				W08-15p 30x24 5.00 MOTORCYCLE (PLAQUE)		43.042	Route 60	1.00	5			5				
				See Special Sign Details		1	A									
				October 5, 2020	80	W08-11 48x48 16.00 UNEVEN LANES		46.171	Westbound Driving Lane	2.00	16					32
						W08-11 48x48 16.00 UNEVEN LANES		48.184	Westbound Driving Lane	2.00	16					32
		W08-1 48x48 16.00 BUMP				48.472	Westbound Driving Lane	1.00	16					16		
		October 9, 2020	115	R1-2 48 TRI 6.93 YIELD		49.089	Route 60	1.00	6.93					6.93		
				W03-2 48x48 16.00 YIELD AHEAD (SYMBOL)		49.089	Route 60	1.00	16					16		
				W08-1 48x48 16.00 BUMP		50.481	Route 60	1.00	16					16		
				See Special Sign Details		1	A									
				W08-11 48x48 16.00 UNEVEN LANES		49.289	Route 60	1.00	16					16		
				W08-17 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		49.289	Route 60	1.00	16					16		
				W08-11 48x48 16.00 UNEVEN LANES		50.241	Route 60	2.00	16					32		
		October 13, 2020	524	EO5-1 36x48 12.00 GORE EXIT		48.755	Route 60	1.00	12					12		
				W08-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)		45.137		2.00	5					10		
				W08-17 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		43.097		2.00	16					32		
				W08-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)		43.097		2.00	5					10		
				W08-17 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		45.137		2.00	16					32		
				W020-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD			Rte F North/South	2.00	16					32		
				W020-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD			Rte 60 WB near 153 intersection	2.00	16					32		
				W020-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD			Co Rd 717 North/South	2.00	16					32		
				W020-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD			Rte ZZ South	1.00	16					16		
				W020-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD			Rte FF South	1.00	16					16		
				W08-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)		47.151		2.00	5					10		
				W08-17 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		47.151		2.00	16					32		
				W08-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)		47.947		2.00	5					10		
				W08-17 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		47.947		2.00	16					32		
				W08-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)		49.282		2.00	5					10		
				W08-17 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		49.282		2.00	16					32		
				W020-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		49.346		2.00	16					32		
				W08-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)		51.212		2.00	5					10		
				W08-17 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		51.212		2.00	16					32		
				W020-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD			Co RD 449	1.00	16					16		
				W020-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD			Co RD 531 North	1.00	16					16		
				W020-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD			Co Rd 731 South	1.00	16					16		
				W020-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD			One-Mile Rd	1.00	16					16		
		W020-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD			Rte 25 On-Ramp	1.00	16					16				
		W020-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD			Rte AD Ramp	1.00	16					16				
		W020-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD			Rte FF North	1.00	16					16				
		October 14, 2020	148	W08-17 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		52.325		2.00	16					32		
				W08-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)		52.325		2.00	5					10		
				W08-11 48x48 16.00 UNEVEN LANES		52.304		2.00	16					32		
				W08-11 48x48 16.00 UNEVEN LANES		50.234		2.00	16					32		
				W08-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)		53.334		2.00	5					10		
		W08-17 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		53.334		2.00	16					32				

0180 - Total

3051.65



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0020	MISC. PERMANENT AGGREGATE EDGE TREATMENT	Material		15	Nov 17, 2020	SYSTEM	(\$53,562.04)	
				15	Nov 17, 2020	SYSTEM	\$53,562.04	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user woodsk1 overriding Payment Estimate Exception 1 on the current Payment Estimate.
				16	Dec 2, 2020	SYSTEM	(\$53,562.04)	
				16	Dec 2, 2020	SYSTEM	\$53,562.04	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user woodsk1 overriding Payment Estimate Exception 1 on the current Payment Estimate.
				17	Dec 16, 2020	SYSTEM	(\$53,562.04)	
				17	Dec 16, 2020	SYSTEM	\$53,562.04	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user woodsk1 overriding Payment Estimate Exception 2 on the current Payment Estimate.
				18	Jan 4, 2021	SYSTEM	(\$53,562.04)	
				18	Jan 4, 2021	SYSTEM	\$53,562.04	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user woodsk1 overriding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
Material - Total							\$0.00	
0020 - Total							\$0.00	
0040	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Other Item Adjustment	ACAD	13	Oct 16, 2020	woodsk1	(\$930.40)	*See Attached AC Price Index Adjustment Sheet.
				14	Nov 2, 2020	woodsk1	(\$10,471.20)	*See Attached AC Price Index Adjustment Sheet.
				15	Nov 17, 2020	woodsk1	(\$1,874.88)	The Combination Of Adjustments For This Line Item Are As Follows: Asphalt Cement Price Adjustment: -1874.88 For BP-1 -332.17 For SP-125 TSR Adjustment (For SP-125): Lot 1A-3B \$0.00 Lot 3C-5D \$0.00 Lot 6A-6F \$9,692.65 Pay Factor Adjustments (For SP-125): Lot 1 \$11,568.00 Lot 2 \$3,701.76 Lot 3 \$11,568.00 Lot 4 \$11,568.00 Lot 5 \$11,568.00 Lot 6 \$15,831.33
							ACAD - Total	
Other Item Adjustment - Total							(\$13,276.48)	
0040 - Total							(\$13,276.48)	
0050	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Material		13	Oct 16, 2020	SYSTEM	(\$1,147,840.58)	
				13	Oct 16, 2020	SYSTEM	\$1,147,840.58	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user woodsk1 overriding Payment Estimate Exception 2 on the current Payment Estimate.



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0050	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Material		14	Nov 2, 2020	SYSTEM	(\$1,472,195.74)	
				14	Nov 2, 2020	SYSTEM	\$1,472,195.74	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overriding Payment Estimate Exception 2 on the current Payment Estimate.
				15	Nov 17, 2020	SYSTEM	(\$1,479,888.46)	
				15	Nov 17, 2020	SYSTEM	\$1,479,888.46	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overriding Payment Estimate Exception 3 on the current Payment Estimate.
				16	Dec 2, 2020	SYSTEM	(\$91,728.46)	
				16	Dec 2, 2020	SYSTEM	\$91,728.46	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overriding Payment Estimate Exception 3 on the current Payment Estimate.
				17	Dec 16, 2020	SYSTEM	(\$91,728.46)	
				17	Dec 16, 2020	SYSTEM	\$91,728.46	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overriding Payment Estimate Exception 3 on the current Payment Estimate.
				18	Jan 4, 2021	SYSTEM	(\$91,728.46)	
				18	Jan 4, 2021	SYSTEM	\$91,728.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user woodsk1 overriding Payment Estimate Exception 3 on the current Payment Estimate.
				19	Jan 20, 2021	SYSTEM	(\$91,728.46)	
				19	Jan 20, 2021	SYSTEM	\$91,728.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user woodsk1 overriding Payment Estimate Exception 1 on the current Payment Estimate.
				20	Feb 1, 2021	SYSTEM	(\$91,728.46)	
				20	Feb 1, 2021	SYSTEM	\$91,728.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user woodsk1 overriding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
Material - Total							\$0.00	
	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Other Item Adjustment	ACAD	13	Oct 16, 2020	woodsk1	(\$45,891.79)	*See Attached AC Price Index Adjustment Sheet.
				14	Nov 2, 2020	woodsk1	(\$12,968.04)	*See Attached AC Price Index Adjustment Sheet.
			ACAD - Total				(\$58,859.83)	
	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)		BITM	15	Nov 17, 2020	woodsk1	\$75,165.57	The Combination Of Adjustments For This Line Item Are As Follows: Asphalt Cement Price Adjustment: -1874.88 For BP-1 -332.17 For SP-125 TSR Adjustment (For SP-125): Lot 1A-3B \$0.00 Lot 3C-5D \$0.00 Lot 6A-6F \$9,692.65 Pay Factor Adjustments (For SP-125): Lot 1 \$11,568.00



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0050		Other Item Adjustment					Lot 2 \$3,701.76	
							Lot 3 \$11,568.00	
							Lot 4 \$11,568.00	
							Lot 5 \$11,568.00	
							Lot 6 \$15,831.33	
							BITM - Total	
Other Item Adjustment - Total							\$16,305.74	
0050 - Total							\$16,305.74	
0100	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material		6	Jul 2, 2020	SYSTEM	(\$46,901.03)	
				6	Jul 2, 2020	SYSTEM	\$46,901.03	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overriding Payment Estimate Exception 8 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$69,305.39)	
				7	Jul 16, 2020	SYSTEM	\$69,305.39	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user woodsk1 overriding Payment Estimate Exception 8 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$69,305.39)	
				8	Aug 3, 2020	SYSTEM	\$69,305.39	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overriding Payment Estimate Exception 8 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$69,305.39)	
				9	Aug 18, 2020	SYSTEM	\$69,305.39	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user woodsk1 overriding Payment Estimate Exception 32 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$69,305.39)	
				10	Sep 3, 2020	SYSTEM	\$69,305.39	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overriding Payment Estimate Exception 18 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$84,951.41)	
				11	Sep 16, 2020	SYSTEM	\$84,951.41	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overriding Payment Estimate Exception 17 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$90,709.88)	
				12	Oct 1, 2020	SYSTEM	\$90,709.88	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overriding Payment Estimate Exception 6 on the current Payment Estimate.
				13	Oct 16, 2020	SYSTEM	(\$90,709.88)	
				13	Oct 16, 2020	SYSTEM	\$90,709.88	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overriding Payment Estimate Exception 7 on the current Payment Estimate.
				14	Nov 2, 2020	SYSTEM	(\$90,709.88)	
				14	Nov 2, 2020	SYSTEM	\$90,709.88	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overriding Payment Estimate Exception 7 on the current Payment Estimate.
				15	Nov 17, 2020	SYSTEM	(\$90,709.88)	
				15	Nov 17, 2020	SYSTEM	\$90,709.88	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overriding Payment Estimate Exception 8 on the current Payment Estimate.



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0100	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material		16	Dec 2, 2020	SYSTEM	(\$90,709.88)	
				16	Dec 2, 2020	SYSTEM	\$90,709.88	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overriding Payment Estimate Exception 8 on the current Payment Estimate.
				17	Dec 16, 2020	SYSTEM	(\$90,709.88)	
				17	Dec 16, 2020	SYSTEM	\$90,709.88	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overriding Payment Estimate Exception 8 on the current Payment Estimate.
				18	Jan 4, 2021	SYSTEM	(\$90,709.88)	
				18	Jan 4, 2021	SYSTEM	\$90,709.88	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overriding Payment Estimate Exception 8 on the current Payment Estimate.
				19	Jan 20, 2021	SYSTEM	(\$90,709.88)	
				19	Jan 20, 2021	SYSTEM	\$90,709.88	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overriding Payment Estimate Exception 7 on the current Payment Estimate.
				20	Feb 1, 2021	SYSTEM	(\$90,709.88)	
				20	Feb 1, 2021	SYSTEM	\$90,709.88	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overriding Payment Estimate Exception 7 on the current Payment Estimate.
			- Total				\$0.00	
Material - Total							\$0.00	
0100 - Total							\$0.00	
0110	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	Material		6	Jul 2, 2020	SYSTEM	(\$16.00)	
				6	Jul 2, 2020	SYSTEM	\$16.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overriding Payment Estimate Exception 11 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$100.00)	
				7	Jul 16, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overriding Payment Estimate Exception 11 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$100.00)	
				8	Aug 3, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overriding Payment Estimate Exception 11 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$100.00)	
				9	Aug 18, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overriding Payment Estimate Exception 35 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$100.00)	
				10	Sep 3, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overriding Payment Estimate Exception 21 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$100.00)	
				11	Sep 16, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overriding Payment Estimate Exception 20 on the current Payment Estimate.
	12	Oct 1, 2020	SYSTEM	(\$100.00)				



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0110	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	Material			2020			
				12	Oct 1, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overriding Payment Estimate Exception 9 on the current Payment Estimate.
				13	Oct 16, 2020	SYSTEM	(\$100.00)	
				13	Oct 16, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overriding Payment Estimate Exception 10 on the current Payment Estimate.
				14	Nov 2, 2020	SYSTEM	(\$100.00)	
				14	Nov 2, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overriding Payment Estimate Exception 11 on the current Payment Estimate.
				15	Nov 17, 2020	SYSTEM	(\$100.00)	
				15	Nov 17, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overriding Payment Estimate Exception 12 on the current Payment Estimate.
				16	Dec 2, 2020	SYSTEM	(\$100.00)	
				16	Dec 2, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overriding Payment Estimate Exception 12 on the current Payment Estimate.
				17	Dec 16, 2020	SYSTEM	(\$100.00)	
				17	Dec 16, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overriding Payment Estimate Exception 11 on the current Payment Estimate.
				18	Jan 4, 2021	SYSTEM	(\$100.00)	
				18	Jan 4, 2021	SYSTEM	\$100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user woodsk1 overriding Payment Estimate Exception 11 on the current Payment Estimate.
						- Total		
	Material - Total						\$0.00	
0110 - Total							\$0.00	
0120	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	Material		6	Jul 2, 2020	SYSTEM	(\$16.00)	
				6	Jul 2, 2020	SYSTEM	\$16.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overriding Payment Estimate Exception 12 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$100.00)	
				7	Jul 16, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overriding Payment Estimate Exception 12 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$100.00)	
				8	Aug 3, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overriding Payment Estimate Exception 12 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$100.00)	
				9	Aug 18, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overriding Payment Estimate Exception 36 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$100.00)	



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0120	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	Material		10	Sep 3, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overriding Payment Estimate Exception 22 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$100.00)	
				11	Sep 16, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overriding Payment Estimate Exception 21 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$100.00)	
				12	Oct 1, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overriding Payment Estimate Exception 10 on the current Payment Estimate.
				13	Oct 16, 2020	SYSTEM	(\$100.00)	
				13	Oct 16, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overriding Payment Estimate Exception 11 on the current Payment Estimate.
				14	Nov 2, 2020	SYSTEM	(\$100.00)	
				14	Nov 2, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overriding Payment Estimate Exception 12 on the current Payment Estimate.
				15	Nov 17, 2020	SYSTEM	(\$100.00)	
				15	Nov 17, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overriding Payment Estimate Exception 13 on the current Payment Estimate.
				16	Dec 2, 2020	SYSTEM	(\$100.00)	
				16	Dec 2, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overriding Payment Estimate Exception 13 on the current Payment Estimate.
				17	Dec 16, 2020	SYSTEM	(\$100.00)	
				17	Dec 16, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overriding Payment Estimate Exception 12 on the current Payment Estimate.
				18	Jan 4, 2021	SYSTEM	(\$100.00)	
				18	Jan 4, 2021	SYSTEM	\$100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overriding Payment Estimate Exception 12 on the current Payment Estimate.
				- Total				
Material - Total							\$0.00	
0120 - Total							\$0.00	
0140	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material		6	Jul 2, 2020	SYSTEM	(\$2,000.00)	
				6	Jul 2, 2020	SYSTEM	\$2,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overriding Payment Estimate Exception 13 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$5,650.00)	
				7	Jul 16, 2020	SYSTEM	\$5,650.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overriding Payment Estimate Exception 13 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$5,650.00)	
				8	Aug 3, 2020	SYSTEM	\$5,650.00	This adjustment offsets the original system-generated Overrun



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0140	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material			2020			Payment Estimate Item Adjustment (0005) due to user woodsk1 overriding Payment Estimate Exception 13 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$5,650.00)	
				9	Aug 18, 2020	SYSTEM	\$5,650.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overriding Payment Estimate Exception 37 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$5,650.00)	
				10	Sep 3, 2020	SYSTEM	\$5,650.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overriding Payment Estimate Exception 23 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$7,480.00)	
				11	Sep 16, 2020	SYSTEM	\$7,480.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overriding Payment Estimate Exception 22 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$8,220.00)	
				12	Oct 1, 2020	SYSTEM	\$8,220.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overriding Payment Estimate Exception 11 on the current Payment Estimate.
				13	Oct 16, 2020	SYSTEM	(\$8,220.00)	
				13	Oct 16, 2020	SYSTEM	\$8,220.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overriding Payment Estimate Exception 12 on the current Payment Estimate.
				14	Nov 2, 2020	SYSTEM	(\$8,220.00)	
				14	Nov 2, 2020	SYSTEM	\$8,220.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overriding Payment Estimate Exception 13 on the current Payment Estimate.
				15	Nov 17, 2020	SYSTEM	(\$8,220.00)	
				15	Nov 17, 2020	SYSTEM	\$8,220.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overriding Payment Estimate Exception 14 on the current Payment Estimate.
				16	Dec 2, 2020	SYSTEM	(\$8,220.00)	
				16	Dec 2, 2020	SYSTEM	\$8,220.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overriding Payment Estimate Exception 14 on the current Payment Estimate.
				17	Dec 16, 2020	SYSTEM	(\$8,220.00)	
				17	Dec 16, 2020	SYSTEM	\$8,220.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overriding Payment Estimate Exception 13 on the current Payment Estimate.
				18	Jan 4, 2021	SYSTEM	(\$8,220.00)	
18	Jan 4, 2021	SYSTEM	\$8,220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user woodsk1 overriding Payment Estimate Exception 13 on the current Payment Estimate.				
			- Total				\$0.00	
Material - Total							\$0.00	
0140 - Total							\$0.00	
0150	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	Material		7	Jul 16, 2020	SYSTEM	(\$10.00)	
				7	Jul 16, 2020	SYSTEM	\$10.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0150	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	Material						overriding Payment Estimate Exception 14 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$10.00)	
				8	Aug 3, 2020	SYSTEM	\$10.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overriding Payment Estimate Exception 14 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$10.00)	
				9	Aug 18, 2020	SYSTEM	\$10.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overriding Payment Estimate Exception 38 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$10.00)	
				10	Sep 3, 2020	SYSTEM	\$10.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overriding Payment Estimate Exception 24 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$10.00)	
				11	Sep 16, 2020	SYSTEM	\$10.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overriding Payment Estimate Exception 23 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$10.00)	
				12	Oct 1, 2020	SYSTEM	\$10.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overriding Payment Estimate Exception 12 on the current Payment Estimate.
				13	Oct 16, 2020	SYSTEM	(\$10.00)	
				13	Oct 16, 2020	SYSTEM	\$10.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overriding Payment Estimate Exception 13 on the current Payment Estimate.
				14	Nov 2, 2020	SYSTEM	(\$10.00)	
				14	Nov 2, 2020	SYSTEM	\$10.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overriding Payment Estimate Exception 14 on the current Payment Estimate.
				15	Nov 17, 2020	SYSTEM	(\$10.00)	
				15	Nov 17, 2020	SYSTEM	\$10.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overriding Payment Estimate Exception 15 on the current Payment Estimate.
				16	Dec 2, 2020	SYSTEM	(\$10.00)	
				16	Dec 2, 2020	SYSTEM	\$10.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overriding Payment Estimate Exception 15 on the current Payment Estimate.
						- Total		
	Material - Total						\$0.00	
0150 - Total							\$0.00	
0180	CONSTRUCTION SIGNS	Material		1	Apr 16, 2020	SYSTEM	(\$2,450.50)	
				2	May 4, 2020	SYSTEM	(\$3,861.00)	
				2	May 4, 2020	SYSTEM	\$3,861.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overriding Payment Estimate Exception 8 on the current Payment Estimate.
				3	May 19, 2020	SYSTEM	(\$3,861.00)	



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
0180	CONSTRUCTION SIGNS	Material		3	May 19, 2020	SYSTEM	\$3,861.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user woodsk1 overriding Payment Estimate Exception 8 on the current Payment Estimate.			
				4	Jun 3, 2020	SYSTEM	(\$3,939.00)				
				4	Jun 3, 2020	SYSTEM	\$3,939.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overriding Payment Estimate Exception 9 on the current Payment Estimate.			
				5	Jun 16, 2020	SYSTEM	(\$3,939.00)				
				5	Jun 16, 2020	SYSTEM	\$3,939.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user woodsk1 overriding Payment Estimate Exception 9 on the current Payment Estimate.			
				6	Jul 2, 2020	SYSTEM	(\$6,389.50)				
				6	Jul 2, 2020	SYSTEM	\$6,389.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overriding Payment Estimate Exception 15 on the current Payment Estimate.			
				7	Jul 16, 2020	SYSTEM	(\$6,389.50)				
				7	Jul 16, 2020	SYSTEM	\$6,389.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overriding Payment Estimate Exception 16 on the current Payment Estimate.			
				8	Aug 3, 2020	SYSTEM	(\$9,360.00)				
				8	Aug 3, 2020	SYSTEM	\$9,360.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overriding Payment Estimate Exception 16 on the current Payment Estimate.			
				9	Aug 18, 2020	SYSTEM	(\$9,360.00)				
				9	Aug 18, 2020	SYSTEM	\$9,360.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overriding Payment Estimate Exception 40 on the current Payment Estimate.			
				10	Sep 3, 2020	SYSTEM	(\$9,360.00)				
				10	Sep 3, 2020	SYSTEM	\$9,360.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overriding Payment Estimate Exception 27 on the current Payment Estimate.			
						- Total				(\$2,450.50)	
						Material - Total				(\$2,450.50)	
	CONSTRUCTION SIGNS	MaterialCredit		2	May 4, 2020	SYSTEM	\$2,450.50				
			- Total				\$2,450.50				
			MaterialCredit - Total				\$2,450.50				
	CONSTRUCTION SIGNS	Other Item Adjustment	MDPA	1	Apr 16, 2020	woodsk1	\$2,450.50				
				2	May 4, 2020	woodsk1	(\$2,450.50)	This adjustment is being added to balance line item 0180 discrepancy amount.			
			MDPA - Total				\$0.00				
			Other Item Adjustment - Total				\$0.00				
			0180 - Total				\$0.00				
0210	CHANNELIZER (TRIM LINE)	Material		1	Apr 16, 2020	SYSTEM	(\$1,215.00)				
				2	May 4, 2020	SYSTEM	(\$1,215.00)				
				2	May 4, 2020	SYSTEM	\$1,215.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overriding Payment Estimate Exception 10 on the current Payment Estimate.			
				3	May 19, 2020	SYSTEM	(\$1,215.00)				



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0210	CHANNELIZER (TRIM LINE)	Material			2020			
				3	May 19, 2020	SYSTEM	\$1,215.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overriding Payment Estimate Exception 10 on the current Payment Estimate.
				4	Jun 3, 2020	SYSTEM	(\$1,980.00)	
				4	Jun 3, 2020	SYSTEM	\$1,980.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overriding Payment Estimate Exception 12 on the current Payment Estimate.
				5	Jun 16, 2020	SYSTEM	(\$1,980.00)	
				5	Jun 16, 2020	SYSTEM	\$1,980.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overriding Payment Estimate Exception 11 on the current Payment Estimate.
				6	Jul 2, 2020	SYSTEM	(\$3,930.00)	
				6	Jul 2, 2020	SYSTEM	\$3,930.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overriding Payment Estimate Exception 17 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$3,930.00)	
				7	Jul 16, 2020	SYSTEM	\$3,930.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overriding Payment Estimate Exception 20 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$3,930.00)	
				8	Aug 3, 2020	SYSTEM	\$3,930.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overriding Payment Estimate Exception 20 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$3,930.00)	
				9	Aug 18, 2020	SYSTEM	\$3,930.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overriding Payment Estimate Exception 44 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$3,930.00)	
				10	Sep 3, 2020	SYSTEM	\$3,930.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overriding Payment Estimate Exception 30 on the current Payment Estimate.
						- Total		
			Material - Total				(\$1,215.00)	
	CHANNELIZER (TRIM LINE)	MaterialCredit		2	May 4, 2020	SYSTEM	\$1,215.00	
			- Total				\$1,215.00	
			MaterialCredit - Total				\$1,215.00	
	CHANNELIZER (TRIM LINE)	Other Item Adjustment	MDPA	1	Apr 16, 2020	woodsk1	\$1,215.00	
				2	May 4, 2020	woodsk1	(\$1,215.00)	This adjustment is being added to balance line item 0220 discrepancy amount.
			MDPA - Total				\$0.00	
			Other Item Adjustment - Total				\$0.00	
			0210 - Total				\$0.00	
0230	DIRECTIONAL INDICATOR BARRICADE	Material		1	Apr 16, 2020	SYSTEM	(\$665.00)	
				2	May 4, 2020	SYSTEM	(\$665.00)	
				2	May 4, 2020	SYSTEM	\$665.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overriding Payment Estimate Exception 11 on the current Payment Estimate.



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0230	DIRECTIONAL INDICATOR BARRICADE	Material		3	May 19, 2020	SYSTEM	(\$665.00)	
				3	May 19, 2020	SYSTEM	\$665.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overriding Payment Estimate Exception 11 on the current Payment Estimate.
				4	Jun 3, 2020	SYSTEM	(\$665.00)	
				4	Jun 3, 2020	SYSTEM	\$665.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overriding Payment Estimate Exception 13 on the current Payment Estimate.
				5	Jun 16, 2020	SYSTEM	(\$665.00)	
				5	Jun 16, 2020	SYSTEM	\$665.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overriding Payment Estimate Exception 13 on the current Payment Estimate.
				6	Jul 2, 2020	SYSTEM	(\$1,995.00)	
				6	Jul 2, 2020	SYSTEM	\$1,995.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overriding Payment Estimate Exception 19 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$2,660.00)	
				7	Jul 16, 2020	SYSTEM	\$2,660.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overriding Payment Estimate Exception 21 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$2,660.00)	
				8	Aug 3, 2020	SYSTEM	\$2,660.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overriding Payment Estimate Exception 21 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$2,660.00)	
				9	Aug 18, 2020	SYSTEM	\$2,660.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overriding Payment Estimate Exception 45 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$2,660.00)	
				10	Sep 3, 2020	SYSTEM	\$2,660.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overriding Payment Estimate Exception 31 on the current Payment Estimate.
						- Total		
							(\$665.00)	
	DIRECTIONAL INDICATOR BARRICADE	MaterialCredit		2	May 4, 2020	SYSTEM	\$665.00	
							\$665.00	
							\$665.00	
	DIRECTIONAL INDICATOR BARRICADE	Other Item Adjustment	MDPA	1	Apr 16, 2020	woodsk1	\$665.00	
				2	May 4, 2020	woodsk1	(\$665.00)	This adjustment is being added to balance line item 0230 discrepancy amount.
							\$0.00	
							\$0.00	
							\$0.00	
							\$0.00	
							\$0.00	
							\$0.00	
0240	FLASHING ARROW PANEL	Material		1	Apr 16, 2020	SYSTEM	(\$400.00)	
				2	May 4, 2020	SYSTEM	(\$400.00)	
				2	May 4, 2020	SYSTEM	\$400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overriding Payment Estimate Exception 12 on the current



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
0240	FLASHING ARROW PANEL	Material						Payment Estimate.			
				3	May 19, 2020	SYSTEM	(\$400.00)				
					3	May 19, 2020	SYSTEM	\$400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overriding Payment Estimate Exception 12 on the current Payment Estimate.		
					4	Jun 3, 2020	SYSTEM	(\$400.00)			
					4	Jun 3, 2020	SYSTEM	\$400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overriding Payment Estimate Exception 14 on the current Payment Estimate.		
					5	Jun 16, 2020	SYSTEM	(\$400.00)			
					5	Jun 16, 2020	SYSTEM	\$400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overriding Payment Estimate Exception 14 on the current Payment Estimate.		
					6	Jul 2, 2020	SYSTEM	(\$1,200.00)			
					6	Jul 2, 2020	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overriding Payment Estimate Exception 20 on the current Payment Estimate.		
					7	Jul 16, 2020	SYSTEM	(\$1,600.00)			
					7	Jul 16, 2020	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overriding Payment Estimate Exception 22 on the current Payment Estimate.		
					8	Aug 3, 2020	SYSTEM	(\$1,600.00)			
					8	Aug 3, 2020	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overriding Payment Estimate Exception 22 on the current Payment Estimate.		
					9	Aug 18, 2020	SYSTEM	(\$1,600.00)			
					9	Aug 18, 2020	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overriding Payment Estimate Exception 46 on the current Payment Estimate.		
					10	Sep 3, 2020	SYSTEM	(\$1,600.00)			
					10	Sep 3, 2020	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overriding Payment Estimate Exception 32 on the current Payment Estimate.		
						- Total				(\$400.00)	
						Material - Total				(\$400.00)	
				FLASHING ARROW PANEL	MaterialCredit		2	May 4, 2020	SYSTEM	\$400.00	
				- Total				\$400.00			
			MaterialCredit - Total				\$400.00				
	FLASHING ARROW PANEL	Other Item Adjustment	MDPA	1	Apr 16, 2020	woodsk1	\$400.00				
				2	May 4, 2020	woodsk1	(\$400.00)	This adjustment is being added to balance line item 0240 discrepancy amount.			
			MDPA - Total				\$0.00				
			Other Item Adjustment - Total				\$0.00				
			0240 - Total				\$0.00				
0250	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	Material		1	Apr 16, 2020	SYSTEM	(\$3,500.00)				
				2	May 4, 2020	SYSTEM	(\$3,500.00)				
				2	May 4, 2020	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Overrun			



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0250	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	Material			2020			Payment Estimate Item Adjustment (0011) due to user woodsk1 overriding Payment Estimate Exception 13 on the current Payment Estimate.
				3	May 19, 2020	SYSTEM	(\$3,500.00)	
				3	May 19, 2020	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overriding Payment Estimate Exception 13 on the current Payment Estimate.
				4	Jun 3, 2020	SYSTEM	(\$3,500.00)	
				4	Jun 3, 2020	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overriding Payment Estimate Exception 15 on the current Payment Estimate.
				5	Jun 16, 2020	SYSTEM	(\$3,500.00)	
				5	Jun 16, 2020	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overriding Payment Estimate Exception 15 on the current Payment Estimate.
				6	Jul 2, 2020	SYSTEM	(\$3,500.00)	
				6	Jul 2, 2020	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overriding Payment Estimate Exception 21 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$7,000.00)	
				7	Jul 16, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overriding Payment Estimate Exception 24 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$7,000.00)	
				8	Aug 3, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overriding Payment Estimate Exception 24 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$7,000.00)	
				9	Aug 18, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overriding Payment Estimate Exception 48 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$7,000.00)	
				10	Sep 3, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overriding Payment Estimate Exception 34 on the current Payment Estimate.
			- Total				(\$3,500.00)	
	Material - Total						(\$3,500.00)	
	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	MaterialCredit		2	May 4, 2020	SYSTEM	\$3,500.00	
			- Total				\$3,500.00	
	MaterialCredit - Total						\$3,500.00	
	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	Other Item Adjustment	MDPA	1	Apr 16, 2020	woodsk1	\$3,500.00	
				2	May 4, 2020	woodsk1	(\$3,500.00)	This adjustment is being added to balance line item 0250 discrepancy amount.
			MDPA - Total				\$0.00	
	Other Item Adjustment - Total						\$0.00	
	0250 - Total						\$0.00	
0350	MGS GUARDRAIL	Construction Stockpile		1	Apr 16, 2020	SYSTEM	\$85,893.50	Payment Estimate Item Adjustment generated Stockpile Transaction



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0350	MGS GUARDRAIL	Construction Stockpile		4	Jun 3, 2020	SYSTEM	(\$5,068.25)	Payment Estimate Item Adjustment generated Stockpile Transaction
				6	Jul 2, 2020	SYSTEM	(\$4,001.25)	Payment Estimate Item Adjustment generated Stockpile Transaction
				10	Sep 3, 2020	SYSTEM	(\$5,068.25)	Payment Estimate Item Adjustment generated Stockpile Transaction
				11	Sep 16, 2020	SYSTEM	(\$4,001.25)	Payment Estimate Item Adjustment generated Stockpile Transaction
				12	Oct 1, 2020	SYSTEM	(\$15,204.75)	Payment Estimate Item Adjustment generated Stockpile Transaction
				14	Nov 2, 2020	SYSTEM	(\$13,070.75)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				
Construction Stockpile - Total							\$39,479.00	
0350 - Total							\$39,479.00	
0360	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	Construction Stockpile		1	Apr 16, 2020	SYSTEM	\$35,976.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				4	Jun 3, 2020	SYSTEM	(\$2,998.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				6	Jul 2, 2020	SYSTEM	(\$2,998.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				10	Sep 3, 2020	SYSTEM	(\$2,998.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				11	Sep 16, 2020	SYSTEM	(\$2,998.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				14	Nov 2, 2020	SYSTEM	(\$2,998.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				
Construction Stockpile - Total							\$20,986.00	
0360 - Total							\$20,986.00	
0370	MGS END ANCHOR	Construction Stockpile		1	Apr 16, 2020	SYSTEM	\$3,210.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				12	Oct 1, 2020	SYSTEM	(\$3,210.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				
Construction Stockpile - Total							\$0.00	
0370 - Total							\$0.00	
0380	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		1	Apr 16, 2020	SYSTEM	\$45,300.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				4	Jun 3, 2020	SYSTEM	(\$3,020.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				6	Jul 2, 2020	SYSTEM	(\$3,020.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				10	Sep 3, 2020	SYSTEM	(\$3,020.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				11	Sep 16, 2020	SYSTEM	(\$3,020.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				12	Oct 1, 2020	SYSTEM	(\$9,060.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				14	Nov 2, 2020	SYSTEM	(\$3,020.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
- Total						\$21,140.00		
Construction Stockpile - Total							\$21,140.00	
0380 - Total							\$21,140.00	
0400	EMULSIFIED ASPHALT, SEAL COAT	Material		9	Aug 18, 2020	SYSTEM	(\$265.00)	
				9	Aug 18, 2020	SYSTEM	\$265.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overriding Payment Estimate Exception 19 on the current Payment Estimate.
				- Total				
Material - Total							\$0.00	



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0400	EMULSIFIED ASPHALT, SEAL COAT	Other Item Adjustment	ACAD	19	Jan 20, 2021	woodsk1	(\$19.32)	AC Seal Coat Adjustment. August 17th, 2020 placement date.
							ACAD - Total	
	Other Item Adjustment - Total	(\$19.32)						
0400 - Total							(\$19.32)	
0410	SEAL COAT AGGREGATE, GRADE B1	Material		9	Aug 18, 2020	SYSTEM	(\$662.50)	
				9	Aug 18, 2020	SYSTEM	\$662.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overriding Payment Estimate Exception 26 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$1,325.00)	
				10	Sep 3, 2020	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overriding Payment Estimate Exception 12 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$1,325.00)	
				11	Sep 16, 2020	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overriding Payment Estimate Exception 12 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$1,325.00)	
				12	Oct 1, 2020	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overriding Payment Estimate Exception 2 on the current Payment Estimate.
				13	Oct 16, 2020	SYSTEM	(\$1,325.00)	
				13	Oct 16, 2020	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overriding Payment Estimate Exception 4 on the current Payment Estimate.
				14	Nov 2, 2020	SYSTEM	(\$1,325.00)	
				14	Nov 2, 2020	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overriding Payment Estimate Exception 4 on the current Payment Estimate.
				15	Nov 17, 2020	SYSTEM	(\$1,325.00)	
				15	Nov 17, 2020	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overriding Payment Estimate Exception 4 on the current Payment Estimate.
				16	Dec 2, 2020	SYSTEM	(\$1,325.00)	
				16	Dec 2, 2020	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overriding Payment Estimate Exception 4 on the current Payment Estimate.
				17	Dec 16, 2020	SYSTEM	(\$1,325.00)	
				17	Dec 16, 2020	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overriding Payment Estimate Exception 4 on the current Payment Estimate.
				18	Jan 4, 2021	SYSTEM	(\$1,325.00)	
				18	Jan 4, 2021	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overriding Payment Estimate Exception 4 on the current Payment Estimate.
	19	Jan 20, 2021	SYSTEM	(\$1,325.00)				
	19	Jan 20, 2021	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overriding Payment Estimate Exception 2 on the current			



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0410	SEAL COAT AGGREGATE, GRADE B1	Material						Payment Estimate.
				20	Feb 1, 2021	SYSTEM	(\$1,325.00)	
				20	Feb 1, 2021	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overriding Payment Estimate Exception 2 on the current Payment Estimate.
				- Total				
Material - Total							\$0.00	
0410 - Total							\$0.00	
0420	CURB BLOCKOUT	Material		2	May 4, 2020	SYSTEM	(\$11,278.05)	
				2	May 4, 2020	SYSTEM	\$11,278.05	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overriding Payment Estimate Exception 15 on the current Payment Estimate.
				3	May 19, 2020	SYSTEM	(\$16,671.90)	
				3	May 19, 2020	SYSTEM	\$16,671.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overriding Payment Estimate Exception 19 on the current Payment Estimate.
				4	Jun 3, 2020	SYSTEM	(\$16,671.90)	
				4	Jun 3, 2020	SYSTEM	\$16,671.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overriding Payment Estimate Exception 26 on the current Payment Estimate.
				5	Jun 16, 2020	SYSTEM	(\$16,671.90)	
				5	Jun 16, 2020	SYSTEM	\$16,671.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overriding Payment Estimate Exception 26 on the current Payment Estimate.
				6	Jul 2, 2020	SYSTEM	(\$33,343.80)	
				6	Jul 2, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overriding Payment Estimate Exception 32 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$33,343.80)	
				7	Jul 16, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overriding Payment Estimate Exception 34 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$33,343.80)	
				8	Aug 3, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overriding Payment Estimate Exception 40 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$33,343.80)	
				9	Aug 18, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overriding Payment Estimate Exception 76 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$33,343.80)	
				10	Sep 3, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overriding Payment Estimate Exception 62 on the current Payment Estimate.
11	Sep 16, 2020	SYSTEM	(\$33,343.80)					
11	Sep 16, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overriding Payment Estimate Exception 50 on the current Payment Estimate.				



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
0420	CURB BLOCKOUT	Material		12	Oct 1, 2020	SYSTEM	(\$33,343.80)					
				12	Oct 1, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overriding Payment Estimate Exception 26 on the current Payment Estimate.				
				13	Oct 16, 2020	SYSTEM	(\$33,343.80)					
				13	Oct 16, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overriding Payment Estimate Exception 27 on the current Payment Estimate.				
				14	Nov 2, 2020	SYSTEM	(\$33,343.80)					
				14	Nov 2, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overriding Payment Estimate Exception 28 on the current Payment Estimate.				
				15	Nov 17, 2020	SYSTEM	(\$33,343.80)					
				15	Nov 17, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overriding Payment Estimate Exception 29 on the current Payment Estimate.				
				16	Dec 2, 2020	SYSTEM	(\$33,343.80)					
				16	Dec 2, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overriding Payment Estimate Exception 29 on the current Payment Estimate.				
				17	Dec 16, 2020	SYSTEM	(\$33,343.80)					
				17	Dec 16, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overriding Payment Estimate Exception 33 on the current Payment Estimate.				
				18	Jan 4, 2021	SYSTEM	(\$33,343.80)					
				18	Jan 4, 2021	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overriding Payment Estimate Exception 21 on the current Payment Estimate.				
				19	Jan 20, 2021	SYSTEM	(\$33,343.80)					
				19	Jan 20, 2021	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overriding Payment Estimate Exception 10 on the current Payment Estimate.				
				20	Feb 1, 2021	SYSTEM	(\$33,343.80)					
				20	Feb 1, 2021	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overriding Payment Estimate Exception 10 on the current Payment Estimate.				
							- Total				\$0.00	
				Material - Total							\$0.00	
0420 - Total							\$0.00					
0430	HALF-SOLE REPAIR	Material		3	May 19, 2020	SYSTEM	(\$12,412.98)					
				3	May 19, 2020	SYSTEM	\$12,412.98	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overriding Payment Estimate Exception 32 on the current Payment Estimate.				
				4	Jun 3, 2020	SYSTEM	(\$23,457.60)					
				4	Jun 3, 2020	SYSTEM	\$23,457.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overriding Payment Estimate Exception 39 on the current Payment Estimate.				
				5	Jun 16, 2020	SYSTEM	(\$37,727.64)					



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0430	HALF-SOLE REPAIR	Material			2020			
				5	Jun 16, 2020	SYSTEM	\$37,727.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overriding Payment Estimate Exception 39 on the current Payment Estimate.
				6	Jul 2, 2020	SYSTEM	(\$67,440.60)	
				6	Jul 2, 2020	SYSTEM	\$67,440.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overriding Payment Estimate Exception 49 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$67,440.60)	
				7	Jul 16, 2020	SYSTEM	\$67,440.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overriding Payment Estimate Exception 52 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$67,440.60)	
				8	Aug 3, 2020	SYSTEM	\$67,440.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overriding Payment Estimate Exception 52 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$67,440.60)	
				9	Aug 18, 2020	SYSTEM	\$67,440.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overriding Payment Estimate Exception 87 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$67,440.60)	
				10	Sep 3, 2020	SYSTEM	\$67,440.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overriding Payment Estimate Exception 73 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$67,440.60)	
				11	Sep 16, 2020	SYSTEM	\$67,440.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overriding Payment Estimate Exception 62 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$73,793.70)	
				12	Oct 1, 2020	SYSTEM	\$73,793.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overriding Payment Estimate Exception 45 on the current Payment Estimate.
				13	Oct 16, 2020	SYSTEM	(\$73,793.70)	
				13	Oct 16, 2020	SYSTEM	\$73,793.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overriding Payment Estimate Exception 46 on the current Payment Estimate.
				14	Nov 2, 2020	SYSTEM	(\$73,793.70)	
				14	Nov 2, 2020	SYSTEM	\$73,793.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overriding Payment Estimate Exception 47 on the current Payment Estimate.
	15	Nov 17, 2020	SYSTEM	(\$73,793.70)				
	15	Nov 17, 2020	SYSTEM	\$73,793.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overriding Payment Estimate Exception 48 on the current Payment Estimate.			
	16	Dec 2, 2020	SYSTEM	(\$73,793.70)				
	16	Dec 2, 2020	SYSTEM	\$73,793.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overriding Payment Estimate Exception 48 on the current Payment Estimate.			



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
0430	HALF-SOLE REPAIR	Material		17	Dec 16, 2020	SYSTEM	(\$73,793.70)					
				17	Dec 16, 2020	SYSTEM	\$73,793.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overriding Payment Estimate Exception 52 on the current Payment Estimate.				
				18	Jan 4, 2021	SYSTEM	(\$73,793.70)					
				18	Jan 4, 2021	SYSTEM	\$73,793.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overriding Payment Estimate Exception 45 on the current Payment Estimate.				
				19	Jan 20, 2021	SYSTEM	(\$73,793.70)					
				19	Jan 20, 2021	SYSTEM	\$73,793.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overriding Payment Estimate Exception 33 on the current Payment Estimate.				
				20	Feb 1, 2021	SYSTEM	(\$73,793.70)					
				20	Feb 1, 2021	SYSTEM	\$73,793.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overriding Payment Estimate Exception 33 on the current Payment Estimate.				
- Total							\$0.00					
Material - Total							\$0.00					
0430 - Total							\$0.00					
0450	EMULSIFIED ASPHALT, SEAL COAT	Material		9	Aug 18, 2020	SYSTEM	(\$287.50)					
				9	Aug 18, 2020	SYSTEM	\$287.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overriding Payment Estimate Exception 5 on the current Payment Estimate.				
				- Total							\$0.00	
				Material - Total							\$0.00	
				EMULSIFIED ASPHALT, SEAL COAT	Other Item Adjustment	ACAD	19	Jan 20, 2021	woodsk1	(\$20.96)	AC Seal Coat Adjustment. August 17th, 2020 placement date.	
ACAD - Total							(\$20.96)					
Other Item Adjustment - Total							(\$20.96)					
0450 - Total							(\$20.96)					
0460	SEAL COAT AGGREGATE, GRADE B1	Material		9	Aug 18, 2020	SYSTEM	(\$720.00)					
				9	Aug 18, 2020	SYSTEM	\$720.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overriding Payment Estimate Exception 27 on the current Payment Estimate.				
				10	Sep 3, 2020	SYSTEM	(\$1,440.00)					
				10	Sep 3, 2020	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overriding Payment Estimate Exception 13 on the current Payment Estimate.				
				11	Sep 16, 2020	SYSTEM	(\$1,440.00)					
				11	Sep 16, 2020	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overriding Payment Estimate Exception 13 on the current Payment Estimate.				
				12	Oct 1, 2020	SYSTEM	(\$1,440.00)					
				12	Oct 1, 2020	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overriding Payment Estimate Exception 4 on the current Payment Estimate.				
				13	Oct 16, 2020	SYSTEM	(\$1,440.00)					
				13	Oct 16, 2020	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1				



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0460	SEAL COAT AGGREGATE, GRADE B1	Material						overriding Payment Estimate Exception 5 on the current Payment Estimate.
				14	Nov 2, 2020	SYSTEM	(\$1,440.00)	
				14	Nov 2, 2020	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overriding Payment Estimate Exception 5 on the current Payment Estimate.
				15	Nov 17, 2020	SYSTEM	(\$1,440.00)	
				15	Nov 17, 2020	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overriding Payment Estimate Exception 6 on the current Payment Estimate.
				16	Dec 2, 2020	SYSTEM	(\$1,440.00)	
				16	Dec 2, 2020	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overriding Payment Estimate Exception 6 on the current Payment Estimate.
				17	Dec 16, 2020	SYSTEM	(\$1,440.00)	
				17	Dec 16, 2020	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overriding Payment Estimate Exception 6 on the current Payment Estimate.
				18	Jan 4, 2021	SYSTEM	(\$1,440.00)	
				18	Jan 4, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overriding Payment Estimate Exception 5 on the current Payment Estimate.
				19	Jan 20, 2021	SYSTEM	(\$1,440.00)	
				19	Jan 20, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overriding Payment Estimate Exception 3 on the current Payment Estimate.
				20	Feb 1, 2021	SYSTEM	(\$1,440.00)	
				20	Feb 1, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overriding Payment Estimate Exception 3 on the current Payment Estimate.
						- Total		
	Material - Total						\$0.00	
0460 - Total							\$0.00	
0470	CURB BLOCKOUT	Material		3	May 19, 2020	SYSTEM	(\$12,100.62)	
				3	May 19, 2020	SYSTEM	\$12,100.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overriding Payment Estimate Exception 25 on the current Payment Estimate.
				4	Jun 3, 2020	SYSTEM	(\$17,908.92)	
				4	Jun 3, 2020	SYSTEM	\$17,908.92	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overriding Payment Estimate Exception 32 on the current Payment Estimate.
				5	Jun 16, 2020	SYSTEM	(\$17,908.92)	
				5	Jun 16, 2020	SYSTEM	\$17,908.92	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overriding Payment Estimate Exception 32 on the current Payment Estimate.
				6	Jul 2, 2020	SYSTEM	(\$35,817.85)	
				6	Jul 2, 2020	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overriding Payment Estimate Exception 38 on the current



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0470	CURB BLOCKOUT	Material						Payment Estimate.
			7	Jul 16, 2020	SYSTEM	(\$35,817.85)		
			7	Jul 16, 2020	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overriding Payment Estimate Exception 40 on the current Payment Estimate.	
			8	Aug 3, 2020	SYSTEM	(\$35,817.85)		
			8	Aug 3, 2020	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overriding Payment Estimate Exception 34 on the current Payment Estimate.	
			9	Aug 18, 2020	SYSTEM	(\$35,817.85)		
			9	Aug 18, 2020	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overriding Payment Estimate Exception 64 on the current Payment Estimate.	
			10	Sep 3, 2020	SYSTEM	(\$35,817.85)		
			10	Sep 3, 2020	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overriding Payment Estimate Exception 50 on the current Payment Estimate.	
			11	Sep 16, 2020	SYSTEM	(\$35,817.85)		
			11	Sep 16, 2020	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overriding Payment Estimate Exception 38 on the current Payment Estimate.	
			12	Oct 1, 2020	SYSTEM	(\$35,817.85)		
			12	Oct 1, 2020	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overriding Payment Estimate Exception 37 on the current Payment Estimate.	
			13	Oct 16, 2020	SYSTEM	(\$35,817.85)		
			13	Oct 16, 2020	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overriding Payment Estimate Exception 38 on the current Payment Estimate.	
			14	Nov 2, 2020	SYSTEM	(\$35,817.85)		
			14	Nov 2, 2020	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overriding Payment Estimate Exception 39 on the current Payment Estimate.	
			15	Nov 17, 2020	SYSTEM	(\$35,817.85)		
			15	Nov 17, 2020	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overriding Payment Estimate Exception 40 on the current Payment Estimate.	
			16	Dec 2, 2020	SYSTEM	(\$35,817.85)		
16	Dec 2, 2020	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overriding Payment Estimate Exception 40 on the current Payment Estimate.				
17	Dec 16, 2020	SYSTEM	(\$35,817.85)					
17	Dec 16, 2020	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overriding Payment Estimate Exception 38 on the current Payment Estimate.				
18	Jan 4, 2021	SYSTEM	(\$35,817.85)					
18	Jan 4, 2021	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1				



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0470	CURB BLOCKOUT	Material						overriding Payment Estimate Exception 26 on the current Payment Estimate.
				19	Jan 20, 2021	SYSTEM	(\$35,817.85)	
				19	Jan 20, 2021	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overriding Payment Estimate Exception 15 on the current Payment Estimate.
				20	Feb 1, 2021	SYSTEM	(\$35,817.85)	
				20	Feb 1, 2021	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overriding Payment Estimate Exception 15 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	0470 - Total						\$0.00	
0480	HALF-SOLE REPAIR	Material		3	May 19, 2020	SYSTEM	(\$4,160.68)	
				3	May 19, 2020	SYSTEM	\$4,160.68	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overriding Payment Estimate Exception 31 on the current Payment Estimate.
				4	Jun 3, 2020	SYSTEM	(\$25,157.60)	
				4	Jun 3, 2020	SYSTEM	\$25,157.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overriding Payment Estimate Exception 38 on the current Payment Estimate.
				5	Jun 16, 2020	SYSTEM	(\$41,510.04)	
				5	Jun 16, 2020	SYSTEM	\$41,510.04	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overriding Payment Estimate Exception 38 on the current Payment Estimate.
				6	Jul 2, 2020	SYSTEM	(\$69,183.40)	
				6	Jul 2, 2020	SYSTEM	\$69,183.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overriding Payment Estimate Exception 45 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$69,183.40)	
				7	Jul 16, 2020	SYSTEM	\$69,183.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overriding Payment Estimate Exception 48 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$69,183.40)	
				8	Aug 3, 2020	SYSTEM	\$69,183.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overriding Payment Estimate Exception 48 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$69,183.40)	
				9	Aug 18, 2020	SYSTEM	\$69,183.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overriding Payment Estimate Exception 83 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$69,183.40)	
				10	Sep 3, 2020	SYSTEM	\$69,183.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overriding Payment Estimate Exception 69 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$69,183.40)	
	11	Sep 16, 2020	SYSTEM	\$69,183.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overriding Payment Estimate Exception 58 on the current			



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
0480	HALF-SOLE REPAIR	Material						Payment Estimate.	
			12	Oct 1, 2020	SYSTEM	(\$69,957.48)			
			12	Oct 1, 2020	SYSTEM	\$69,957.48	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overriding Payment Estimate Exception 50 on the current Payment Estimate.		
			13	Oct 16, 2020	SYSTEM	(\$69,957.48)			
			13	Oct 16, 2020	SYSTEM	\$69,957.48	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overriding Payment Estimate Exception 51 on the current Payment Estimate.		
			14	Nov 2, 2020	SYSTEM	(\$69,957.48)			
			14	Nov 2, 2020	SYSTEM	\$69,957.48	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overriding Payment Estimate Exception 52 on the current Payment Estimate.		
			15	Nov 17, 2020	SYSTEM	(\$69,957.48)			
			15	Nov 17, 2020	SYSTEM	\$69,957.48	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overriding Payment Estimate Exception 53 on the current Payment Estimate.		
			16	Dec 2, 2020	SYSTEM	(\$69,957.48)			
			16	Dec 2, 2020	SYSTEM	\$69,957.48	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overriding Payment Estimate Exception 53 on the current Payment Estimate.		
			17	Dec 16, 2020	SYSTEM	(\$69,957.48)			
			17	Dec 16, 2020	SYSTEM	\$69,957.48	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overriding Payment Estimate Exception 47 on the current Payment Estimate.		
			18	Jan 4, 2021	SYSTEM	(\$69,957.48)			
			18	Jan 4, 2021	SYSTEM	\$69,957.48	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overriding Payment Estimate Exception 50 on the current Payment Estimate.		
			19	Jan 20, 2021	SYSTEM	(\$69,957.48)			
			19	Jan 20, 2021	SYSTEM	\$69,957.48	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overriding Payment Estimate Exception 36 on the current Payment Estimate.		
			20	Feb 1, 2021	SYSTEM	(\$69,957.48)			
			20	Feb 1, 2021	SYSTEM	\$69,957.48	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overriding Payment Estimate Exception 36 on the current Payment Estimate.		
						- Total			
	Material - Total						\$0.00		
0480 - Total							\$0.00		
0500	EMULSIFIED ASPHALT, SEAL COAT	Other Item Adjustment	ACAD	19	Jan 20, 2021	woodsk1	(\$19.33)	AC Seal Coat Adjustment. September 25th 2020 placement date.	
			ACAD - Total					(\$19.33)	
			Other Item Adjustment - Total					(\$19.33)	
0500 - Total							(\$19.33)		
0510	SEAL COAT AGGREGATE, GRADE B1	Material		19	Jan 20, 2021	SYSTEM	(\$1,325.00)		
				19	Jan 20, 2021	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overriding Payment Estimate Exception 4 on the current Payment Estimate.	



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0510	SEAL COAT AGGREGATE, GRADE B1	Material		20	Feb 1, 2021	SYSTEM	(\$1,325.00)	
				20	Feb 1, 2021	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overriding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total					
Material - Total							\$0.00	
0510 - Total							\$0.00	
0520	CURB BLOCKOUT	Material		9	Aug 18, 2020	SYSTEM	(\$16,671.90)	
				9	Aug 18, 2020	SYSTEM	\$16,671.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overriding Payment Estimate Exception 70 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$16,671.90)	
				10	Sep 3, 2020	SYSTEM	\$16,671.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overriding Payment Estimate Exception 56 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$33,343.80)	
				11	Sep 16, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overriding Payment Estimate Exception 44 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$33,343.80)	
				12	Oct 1, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overriding Payment Estimate Exception 31 on the current Payment Estimate.
				13	Oct 16, 2020	SYSTEM	(\$33,343.80)	
				13	Oct 16, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overriding Payment Estimate Exception 32 on the current Payment Estimate.
				14	Nov 2, 2020	SYSTEM	(\$33,343.80)	
				14	Nov 2, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overriding Payment Estimate Exception 33 on the current Payment Estimate.
				15	Nov 17, 2020	SYSTEM	(\$33,343.80)	
				15	Nov 17, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overriding Payment Estimate Exception 34 on the current Payment Estimate.
				16	Dec 2, 2020	SYSTEM	(\$33,343.80)	
				16	Dec 2, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overriding Payment Estimate Exception 34 on the current Payment Estimate.
				17	Dec 16, 2020	SYSTEM	(\$33,343.80)	
				17	Dec 16, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overriding Payment Estimate Exception 27 on the current Payment Estimate.
				18	Jan 4, 2021	SYSTEM	(\$33,343.80)	
	18	Jan 4, 2021	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user woodsk1 overriding Payment Estimate Exception 32 on the current Payment Estimate.			
	19	Jan 20, 2021	SYSTEM	(\$33,343.80)				



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0520	CURB BLOCKOUT	Material			2021			
				19	Jan 20, 2021	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overriding Payment Estimate Exception 21 on the current Payment Estimate.
				20	Feb 1, 2021	SYSTEM	(\$33,343.80)	
				20	Feb 1, 2021	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overriding Payment Estimate Exception 21 on the current Payment Estimate.
			- Total					
Material - Total							\$0.00	
0520 - Total							\$0.00	
0530	HALF-SOLE REPAIR	Material		7	Jul 16, 2020	SYSTEM	(\$8,503.38)	
				7	Jul 16, 2020	SYSTEM	\$8,503.38	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overriding Payment Estimate Exception 47 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$8,503.38)	
				8	Aug 3, 2020	SYSTEM	\$8,503.38	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overriding Payment Estimate Exception 47 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$23,457.60)	
				9	Aug 18, 2020	SYSTEM	\$23,457.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overriding Payment Estimate Exception 82 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$23,457.60)	
				10	Sep 3, 2020	SYSTEM	\$23,457.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overriding Payment Estimate Exception 68 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$23,457.60)	
				11	Sep 16, 2020	SYSTEM	\$23,457.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overriding Payment Estimate Exception 57 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$83,372.22)	
				12	Oct 1, 2020	SYSTEM	\$83,372.22	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overriding Payment Estimate Exception 49 on the current Payment Estimate.
				13	Oct 16, 2020	SYSTEM	(\$83,372.22)	
				13	Oct 16, 2020	SYSTEM	\$83,372.22	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overriding Payment Estimate Exception 50 on the current Payment Estimate.
				14	Nov 2, 2020	SYSTEM	(\$83,372.22)	
				14	Nov 2, 2020	SYSTEM	\$83,372.22	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overriding Payment Estimate Exception 51 on the current Payment Estimate.
	15	Nov 17, 2020	SYSTEM	(\$83,372.22)				
	15	Nov 17, 2020	SYSTEM	\$83,372.22	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overriding Payment Estimate Exception 52 on the current Payment Estimate.			
	16	Dec 2, 2020	SYSTEM	(\$83,372.22)				



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
0530	HALF-SOLE REPAIR	Material		16	Dec 2, 2020	SYSTEM	\$83,372.22	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overriding Payment Estimate Exception 52 on the current Payment Estimate.	
				17	Dec 16, 2020	SYSTEM	(\$83,372.22)		
				17	Dec 16, 2020	SYSTEM	\$83,372.22	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overriding Payment Estimate Exception 51 on the current Payment Estimate.	
				18	Jan 4, 2021	SYSTEM	(\$83,372.22)		
				18	Jan 4, 2021	SYSTEM	\$83,372.22	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overriding Payment Estimate Exception 54 on the current Payment Estimate.	
				19	Jan 20, 2021	SYSTEM	(\$83,372.22)		
				19	Jan 20, 2021	SYSTEM	\$83,372.22	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overriding Payment Estimate Exception 40 on the current Payment Estimate.	
				20	Feb 1, 2021	SYSTEM	(\$83,372.22)		
				20	Feb 1, 2021	SYSTEM	\$83,372.22	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overriding Payment Estimate Exception 40 on the current Payment Estimate.	
							- Total		
Material - Total							\$0.00		
0530 - Total							\$0.00		
0550	EMULSIFIED ASPHALT, SEAL COAT	Other Item Adjustment	ACAD	19	Jan 20, 2021	woodsk1	(\$17.50)	AC Seal Coat Adjustment. September 25th, 2020 placement date.	
							ACAD - Total	(\$17.50)	
				Other Item Adjustment - Total					
0550 - Total							(\$17.50)		
0560	SEAL COAT AGGREGATE, GRADE B1	Material		19	Jan 20, 2021	SYSTEM	(\$1,205.00)		
				19	Jan 20, 2021	SYSTEM	\$1,205.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user woodsk1 overriding Payment Estimate Exception 5 on the current Payment Estimate.	
				20	Feb 1, 2021	SYSTEM	(\$1,205.00)		
				20	Feb 1, 2021	SYSTEM	\$1,205.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user woodsk1 overriding Payment Estimate Exception 5 on the current Payment Estimate.	
							- Total		
Material - Total							\$0.00		
0560 - Total							\$0.00		
0570	CURB BLOCKOUT	Material		9	Aug 18, 2020	SYSTEM	(\$15,434.12)		
				9	Aug 18, 2020	SYSTEM	\$15,434.12	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overriding Payment Estimate Exception 58 on the current Payment Estimate.	
				10	Sep 3, 2020	SYSTEM	(\$15,434.12)		
				10	Sep 3, 2020	SYSTEM	\$15,434.12	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overriding Payment Estimate Exception 44 on the current Payment Estimate.	
				11	Sep 16, 2020	SYSTEM	(\$30,868.25)		
				11	Sep 16, 2020	SYSTEM	\$30,868.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overriding Payment Estimate Exception 32 on the current	



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0570	CURB BLOCKOUT	Material						Payment Estimate.
			12	Oct 1, 2020	SYSTEM	(\$30,868.25)		
			12	Oct 1, 2020	SYSTEM	\$30,868.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overriding Payment Estimate Exception 20 on the current Payment Estimate.	
			13	Oct 16, 2020	SYSTEM	(\$30,868.25)		
			13	Oct 16, 2020	SYSTEM	\$30,868.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overriding Payment Estimate Exception 21 on the current Payment Estimate.	
			14	Nov 2, 2020	SYSTEM	(\$30,868.25)		
			14	Nov 2, 2020	SYSTEM	\$30,868.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overriding Payment Estimate Exception 22 on the current Payment Estimate.	
			15	Nov 17, 2020	SYSTEM	(\$30,868.25)		
			15	Nov 17, 2020	SYSTEM	\$30,868.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overriding Payment Estimate Exception 23 on the current Payment Estimate.	
			16	Dec 2, 2020	SYSTEM	(\$30,868.25)		
			16	Dec 2, 2020	SYSTEM	\$30,868.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overriding Payment Estimate Exception 23 on the current Payment Estimate.	
			17	Dec 16, 2020	SYSTEM	(\$30,868.25)		
			17	Dec 16, 2020	SYSTEM	\$30,868.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overriding Payment Estimate Exception 21 on the current Payment Estimate.	
			18	Jan 4, 2021	SYSTEM	(\$30,868.25)		
			18	Jan 4, 2021	SYSTEM	\$30,868.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user woodsk1 overriding Payment Estimate Exception 38 on the current Payment Estimate.	
			19	Jan 20, 2021	SYSTEM	(\$30,868.25)		
			19	Jan 20, 2021	SYSTEM	\$30,868.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overriding Payment Estimate Exception 27 on the current Payment Estimate.	
			20	Feb 1, 2021	SYSTEM	(\$30,868.25)		
			20	Feb 1, 2021	SYSTEM	\$30,868.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overriding Payment Estimate Exception 27 on the current Payment Estimate.	
						- Total		
	Material - Total						\$0.00	
0570 - Total							\$0.00	
0580	HALF-SOLE REPAIR	Material		7	Jul 16, 2020	SYSTEM	(\$21,758.00)	
			7	Jul 16, 2020	SYSTEM	\$21,758.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overriding Payment Estimate Exception 55 on the current Payment Estimate.	
			8	Aug 3, 2020	SYSTEM	(\$21,758.00)		
			8	Aug 3, 2020	SYSTEM	\$21,758.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overriding Payment Estimate Exception 55 on the current Payment Estimate.	



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0580	HALF-SOLE REPAIR	Material		9	Aug 18, 2020	SYSTEM	(\$21,758.00)	
				9	Aug 18, 2020	SYSTEM	\$21,758.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overriding Payment Estimate Exception 90 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$21,758.00)	
				10	Sep 3, 2020	SYSTEM	\$21,758.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overriding Payment Estimate Exception 76 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$21,758.00)	
				11	Sep 16, 2020	SYSTEM	\$21,758.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overriding Payment Estimate Exception 65 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0580 - Total							\$0.00	
0780	HALF-SOLE REPAIR	Material		11	Sep 16, 2020	SYSTEM	(\$2,577.84)	
				11	Sep 16, 2020	SYSTEM	\$2,577.84	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overriding Payment Estimate Exception 56 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$14,607.76)	
				12	Oct 1, 2020	SYSTEM	\$14,607.76	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overriding Payment Estimate Exception 44 on the current Payment Estimate.
				13	Oct 16, 2020	SYSTEM	(\$42,964.00)	
				13	Oct 16, 2020	SYSTEM	\$42,964.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overriding Payment Estimate Exception 45 on the current Payment Estimate.
				14	Nov 2, 2020	SYSTEM	(\$42,964.00)	
				14	Nov 2, 2020	SYSTEM	\$42,964.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overriding Payment Estimate Exception 46 on the current Payment Estimate.
				15	Nov 17, 2020	SYSTEM	(\$42,964.00)	
				15	Nov 17, 2020	SYSTEM	\$42,964.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overriding Payment Estimate Exception 47 on the current Payment Estimate.
				16	Dec 2, 2020	SYSTEM	(\$42,964.00)	
				16	Dec 2, 2020	SYSTEM	\$42,964.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overriding Payment Estimate Exception 47 on the current Payment Estimate.
				17	Dec 16, 2020	SYSTEM	(\$244,035.52)	
				17	Dec 16, 2020	SYSTEM	\$244,035.52	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overriding Payment Estimate Exception 46 on the current Payment Estimate.
	18	Jan 4, 2021	SYSTEM	(\$244,035.52)				
	18	Jan 4, 2021	SYSTEM	\$244,035.52	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overriding Payment Estimate Exception 48 on the current Payment Estimate.			
			- Total				\$0.00	



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
0780	Material - Total						\$0.00				
0780 - Total							\$0.00				
0820	HALF-SOLE REPAIR	Material		11	Sep 16, 2020	SYSTEM	(\$3,007.48)				
				11	Sep 16, 2020	SYSTEM	\$3,007.48	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overriding Payment Estimate Exception 66 on the current Payment Estimate.			
				12	Oct 1, 2020	SYSTEM	(\$42,964.00)				
				12	Oct 1, 2020	SYSTEM	\$42,964.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overriding Payment Estimate Exception 48 on the current Payment Estimate.			
				13	Oct 16, 2020	SYSTEM	(\$42,964.00)				
				13	Oct 16, 2020	SYSTEM	\$42,964.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overriding Payment Estimate Exception 49 on the current Payment Estimate.			
				14	Nov 2, 2020	SYSTEM	(\$42,964.00)				
				14	Nov 2, 2020	SYSTEM	\$42,964.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overriding Payment Estimate Exception 50 on the current Payment Estimate.			
				15	Nov 17, 2020	SYSTEM	(\$42,964.00)				
				15	Nov 17, 2020	SYSTEM	\$42,964.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overriding Payment Estimate Exception 51 on the current Payment Estimate.			
				16	Dec 2, 2020	SYSTEM	(\$42,964.00)				
				16	Dec 2, 2020	SYSTEM	\$42,964.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overriding Payment Estimate Exception 51 on the current Payment Estimate.			
				17	Dec 16, 2020	SYSTEM	(\$318,363.24)				
				17	Dec 16, 2020	SYSTEM	\$318,363.24	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overriding Payment Estimate Exception 45 on the current Payment Estimate.			
				18	Jan 4, 2021	SYSTEM	(\$318,363.24)				
				18	Jan 4, 2021	SYSTEM	\$318,363.24	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overriding Payment Estimate Exception 49 on the current Payment Estimate.			
										- Total	\$0.00
			Material - Total							\$0.00	
0820 - Total							\$0.00				
0850	MISC. PERMANENT AGGREGATE EDGE TREATMENT	Material		2	May 4, 2020	SYSTEM	(\$17,901.77)				
				2	May 4, 2020	SYSTEM	\$17,901.77	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overriding Payment Estimate Exception 1 on the current Payment Estimate.			
				3	May 19, 2020	SYSTEM	(\$42,591.62)				
				3	May 19, 2020	SYSTEM	\$42,591.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overriding Payment Estimate Exception 1 on the current Payment Estimate.			
				4	Jun 3, 2020	SYSTEM	(\$42,591.62)				
				4	Jun 3, 2020	SYSTEM	\$42,591.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1			



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
0850	MISC. PERMANENT AGGREGATE EDGE TREATMENT	Material						overriding Payment Estimate Exception 1 on the current Payment Estimate.	
				5	Jun 16, 2020	SYSTEM	(\$42,591.62)		
				5	Jun 16, 2020	SYSTEM	\$42,591.62		This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overriding Payment Estimate Exception 1 on the current Payment Estimate.
				6	Jul 2, 2020	SYSTEM	(\$42,591.62)		
				6	Jul 2, 2020	SYSTEM	\$42,591.62		This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overriding Payment Estimate Exception 1 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$42,591.62)		
				7	Jul 16, 2020	SYSTEM	\$42,591.62		This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overriding Payment Estimate Exception 1 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$42,591.62)		
				8	Aug 3, 2020	SYSTEM	\$42,591.62		This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overriding Payment Estimate Exception 1 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$42,591.62)		
				9	Aug 18, 2020	SYSTEM	\$42,591.62		This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overriding Payment Estimate Exception 1 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$48,392.79)		
				10	Sep 3, 2020	SYSTEM	\$48,392.79		This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overriding Payment Estimate Exception 1 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$48,392.79)		
				11	Sep 16, 2020	SYSTEM	\$48,392.79		This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overriding Payment Estimate Exception 1 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$64,697.64)		
				12	Oct 1, 2020	SYSTEM	\$64,697.64		This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overriding Payment Estimate Exception 1 on the current Payment Estimate.
				13	Oct 16, 2020	SYSTEM	(\$64,697.64)		
				13	Oct 16, 2020	SYSTEM	\$64,697.64		This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overriding Payment Estimate Exception 1 on the current Payment Estimate.
				14	Nov 2, 2020	SYSTEM	(\$64,697.64)		
14	Nov 2, 2020	SYSTEM	\$64,697.64		This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overriding Payment Estimate Exception 1 on the current Payment Estimate.				
15	Nov 17, 2020	SYSTEM	(\$64,697.64)						
15	Nov 17, 2020	SYSTEM	\$64,697.64		This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overriding Payment Estimate Exception 2 on the current Payment Estimate.				
16	Dec 2, 2020	SYSTEM	(\$64,697.64)						
16	Dec 2, 2020	SYSTEM	\$64,697.64		This adjustment offsets the original system-generated Overrun				



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0850	MISC. PERMANENT AGGREGATE EDGE TREATMENT	Material			2020			Payment Estimate Item Adjustment (0019) due to user woodsk1 overriding Payment Estimate Exception 2 on the current Payment Estimate.
				17	Dec 16, 2020	SYSTEM	(\$64,697.64)	
				17	Dec 16, 2020	SYSTEM	\$64,697.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overriding Payment Estimate Exception 1 on the current Payment Estimate.
				18	Jan 4, 2021	SYSTEM	(\$64,697.64)	
				18	Jan 4, 2021	SYSTEM	\$64,697.64	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user woodsk1 overriding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0850 - Total							\$0.00	
0870	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Other Item Adjustment	ACAD	2	May 4, 2020	woodsk1	\$460.98	
				17	Dec 16, 2020	woodsk1	\$8.06	*See Attached AC Price Index Adjustment Sheet.
			ACAD - Total				\$469.04	
	Other Item Adjustment - Total						\$469.04	
0870 - Total							\$469.04	
0880	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Material		2	May 4, 2020	SYSTEM	(\$456,638.72)	
				2	May 4, 2020	SYSTEM	\$456,638.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overriding Payment Estimate Exception 2 on the current Payment Estimate.
				3	May 19, 2020	SYSTEM	(\$456,638.72)	
				3	May 19, 2020	SYSTEM	\$456,638.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overriding Payment Estimate Exception 2 on the current Payment Estimate.
				4	Jun 3, 2020	SYSTEM	(\$456,638.72)	
				4	Jun 3, 2020	SYSTEM	\$456,638.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overriding Payment Estimate Exception 2 on the current Payment Estimate.
				5	Jun 16, 2020	SYSTEM	(\$456,638.72)	
				5	Jun 16, 2020	SYSTEM	\$456,638.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overriding Payment Estimate Exception 2 on the current Payment Estimate.
				6	Jul 2, 2020	SYSTEM	(\$456,638.72)	
				6	Jul 2, 2020	SYSTEM	\$456,638.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overriding Payment Estimate Exception 2 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$940,718.72)	
				7	Jul 16, 2020	SYSTEM	\$940,718.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overriding Payment Estimate Exception 2 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$940,718.72)	
8	Aug 3, 2020	SYSTEM	\$940,718.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overriding Payment Estimate Exception 2 on the current Payment Estimate.				
9	Aug 18, 2020	SYSTEM	(\$940,718.72)					



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
0880	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Material		9	Aug 18, 2020	SYSTEM	\$940,718.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overriding Payment Estimate Exception 2 on the current Payment Estimate.				
				10	Sep 3, 2020	SYSTEM	(\$1,038,932.50)					
				10	Sep 3, 2020	SYSTEM	\$1,038,932.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overriding Payment Estimate Exception 2 on the current Payment Estimate.				
				11	Sep 16, 2020	SYSTEM	(\$1,038,932.50)					
				11	Sep 16, 2020	SYSTEM	\$1,038,932.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overriding Payment Estimate Exception 2 on the current Payment Estimate.				
			- Total							\$0.00		
			Material - Total							\$0.00		
			ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Other Item Adjustment	ACAD	1	Apr 16, 2020	woodsk1	\$1,227.35			
						2	May 4, 2020	woodsk1	\$1,493.29			
						17	Dec 16, 2020	woodsk1	\$7.00	*See Attached AC Price Index Adjustment Sheet.		
ACAD - Total							\$2,727.64					
ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)			BITM	8	Aug 3, 2020	woodsk1	\$66,845.91	TSR #001 Payment Adjustment. Lot #001 \$18,153.00 TSR #002 Payment Adjustment. Lot #004 \$10,068.56 Lot 1 Bonus Payment Adjustment \$12,102.00 Lot 2 Bonus Payment Adjustment \$6,051.00 Lot 3 Bonus Payment Adjustment \$12,102.00 Lot 4 Bonus Payment Adjustment \$8,369.35 Total Bituminous Pay Factor Adjustment For Line Item Posting #0880 \$66,845.91				
				BITM - Total							\$66,845.91	
				Other Item Adjustment - Total							\$69,573.55	
				0880 - Total							\$69,573.55	
				0890	TACK COAT	Material		1	Apr 16, 2020	SYSTEM	(\$10,486.00)	
								2	May 4, 2020	SYSTEM	(\$24,460.20)	
								2	May 4, 2020	SYSTEM	\$24,460.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overriding Payment Estimate Exception 3 on the current Payment Estimate.
								3	May 19, 2020	SYSTEM	(\$24,460.20)	
								3	May 19, 2020	SYSTEM	\$24,460.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overriding Payment Estimate Exception 3 on the current Payment Estimate.
								4	Jun 3, 2020	SYSTEM	(\$24,460.20)	
	4	Jun 3, 2020	SYSTEM				\$24,460.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overriding Payment Estimate Exception 3 on the current Payment Estimate.				
	5	Jun 16, 2020	SYSTEM				(\$24,460.20)					
	5	Jun 16, 2020	SYSTEM				\$24,460.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overriding Payment Estimate Exception 3 on the current Payment Estimate.				
	6	Jul 2, 2020	SYSTEM				(\$24,460.20)					



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
0890	TACK COAT	Material		6	Jul 2, 2020	SYSTEM	\$24,460.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overriding Payment Estimate Exception 3 on the current Payment Estimate.				
				7	Jul 16, 2020	SYSTEM	(\$24,460.20)					
				7	Jul 16, 2020	SYSTEM	\$24,460.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overriding Payment Estimate Exception 3 on the current Payment Estimate.				
				8	Aug 3, 2020	SYSTEM	(\$24,460.20)					
				8	Aug 3, 2020	SYSTEM	\$24,460.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overriding Payment Estimate Exception 3 on the current Payment Estimate.				
				9	Aug 18, 2020	SYSTEM	(\$24,460.20)					
				9	Aug 18, 2020	SYSTEM	\$24,460.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overriding Payment Estimate Exception 3 on the current Payment Estimate.				
				10	Sep 3, 2020	SYSTEM	(\$27,242.20)					
				10	Sep 3, 2020	SYSTEM	\$27,242.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overriding Payment Estimate Exception 3 on the current Payment Estimate.				
				11	Sep 16, 2020	SYSTEM	(\$27,242.20)					
				11	Sep 16, 2020	SYSTEM	\$27,242.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overriding Payment Estimate Exception 3 on the current Payment Estimate.				
				- Total							(\$10,486.00)	
				Material - Total							(\$10,486.00)	
	TACK COAT	MaterialCredit		2	May 4, 2020	SYSTEM	\$10,486.00					
- Total							\$10,486.00					
MaterialCredit - Total							\$10,486.00					
	TACK COAT	Other Item Adjustment	MDPA	1	Apr 16, 2020	woodsk1	\$10,486.00					
				2	May 4, 2020	woodsk1	(\$10,486.00)	This adjustment is being added to balance line item 0890 discrepancy amount.				
MDPA - Total							\$0.00					
Other Item Adjustment - Total							\$0.00					
0890 - Total							\$0.00					
0900	BITUMINOUS FOG SEAL	Material		2	May 4, 2020	SYSTEM	(\$4,565.00)					
				2	May 4, 2020	SYSTEM	\$4,565.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overriding Payment Estimate Exception 5 on the current Payment Estimate.				
				3	May 19, 2020	SYSTEM	(\$8,436.95)					
				3	May 19, 2020	SYSTEM	\$8,436.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overriding Payment Estimate Exception 5 on the current Payment Estimate.				
				4	Jun 3, 2020	SYSTEM	(\$8,436.95)					
				4	Jun 3, 2020	SYSTEM	\$8,436.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overriding Payment Estimate Exception 5 on the current Payment Estimate.				
				5	Jun 16, 2020	SYSTEM	(\$8,436.95)					
				5	Jun 16, 2020	SYSTEM	\$8,436.95	This adjustment offsets the original system-generated Overrun				



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0900	BITUMINOUS FOG SEAL	Material			2020			Payment Estimate Item Adjustment (0013) due to user woodsk1 overriding Payment Estimate Exception 5 on the current Payment Estimate.
				6	Jul 2, 2020	SYSTEM	(\$8,436.95)	
				6	Jul 2, 2020	SYSTEM	\$8,436.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overriding Payment Estimate Exception 5 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$8,436.95)	
				7	Jul 16, 2020	SYSTEM	\$8,436.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overriding Payment Estimate Exception 5 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$8,436.95)	
				8	Aug 3, 2020	SYSTEM	\$8,436.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overriding Payment Estimate Exception 5 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$8,436.95)	
				9	Aug 18, 2020	SYSTEM	\$8,436.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overriding Payment Estimate Exception 29 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$10,511.95)	
				10	Sep 3, 2020	SYSTEM	\$10,511.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overriding Payment Estimate Exception 15 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$10,511.95)	
				11	Sep 16, 2020	SYSTEM	\$10,511.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overriding Payment Estimate Exception 15 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$19,920.00)	
				12	Oct 1, 2020	SYSTEM	\$19,920.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overriding Payment Estimate Exception 5 on the current Payment Estimate.
				13	Oct 16, 2020	SYSTEM	(\$19,920.00)	
				13	Oct 16, 2020	SYSTEM	\$19,920.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overriding Payment Estimate Exception 6 on the current Payment Estimate.
14	Nov 2, 2020	SYSTEM	(\$19,920.00)					
14	Nov 2, 2020	SYSTEM	\$19,920.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overriding Payment Estimate Exception 6 on the current Payment Estimate.				
15	Nov 17, 2020	SYSTEM	(\$19,920.00)					
15	Nov 17, 2020	SYSTEM	\$19,920.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overriding Payment Estimate Exception 7 on the current Payment Estimate.				
16	Dec 2, 2020	SYSTEM	(\$19,920.00)					
16	Dec 2, 2020	SYSTEM	\$19,920.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overriding Payment Estimate Exception 7 on the current Payment Estimate.				
17	Dec 16, 2020	SYSTEM	(\$19,920.00)					



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0900	BITUMINOUS FOG SEAL	Material		17	Dec 16, 2020	SYSTEM	\$19,920.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overriding Payment Estimate Exception 7 on the current Payment Estimate.
				18	Jan 4, 2021	SYSTEM	(\$19,920.00)	
				18	Jan 4, 2021	SYSTEM	\$19,920.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user woodsk1 overriding Payment Estimate Exception 7 on the current Payment Estimate.
				- Total				
Material - Total							\$0.00	
0900 - Total							\$0.00	
0910	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	Material		4	Jun 3, 2020	SYSTEM	(\$1,000.00)	
				4	Jun 3, 2020	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overriding Payment Estimate Exception 7 on the current Payment Estimate.
				5	Jun 16, 2020	SYSTEM	(\$1,000.00)	
				5	Jun 16, 2020	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overriding Payment Estimate Exception 7 on the current Payment Estimate.
				6	Jul 2, 2020	SYSTEM	(\$1,000.00)	
				6	Jul 2, 2020	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overriding Payment Estimate Exception 7 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$1,000.00)	
				7	Jul 16, 2020	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overriding Payment Estimate Exception 7 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$1,000.00)	
				8	Aug 3, 2020	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overriding Payment Estimate Exception 7 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$1,000.00)	
				9	Aug 18, 2020	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overriding Payment Estimate Exception 31 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$1,000.00)	
				10	Sep 3, 2020	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user woodsk1 overriding Payment Estimate Exception 17 on the current Payment Estimate.
- Total							\$0.00	
Material - Total							\$0.00	
0910 - Total							\$0.00	
0920	CONSTRUCTION SIGNS	Material		1	Apr 16, 2020	SYSTEM	(\$15,366.00)	
				2	May 4, 2020	SYSTEM	(\$15,366.00)	
				2	May 4, 2020	SYSTEM	\$15,366.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overriding Payment Estimate Exception 7 on the current Payment Estimate.
				3	May 19, 2020	SYSTEM	(\$15,366.00)	
				3	May 19, 2020	SYSTEM	\$15,366.00	This adjustment offsets the original system-generated Overrun



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
0920	CONSTRUCTION SIGNS	Material			2020			Payment Estimate Item Adjustment (0014) due to user woodsk1 overriding Payment Estimate Exception 7 on the current Payment Estimate.			
			4	Jun 3, 2020	SYSTEM	(\$15,366.00)					
			4	Jun 3, 2020	SYSTEM	\$15,366.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overriding Payment Estimate Exception 8 on the current Payment Estimate.				
			5	Jun 16, 2020	SYSTEM	(\$15,366.00)					
			5	Jun 16, 2020	SYSTEM	\$15,366.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overriding Payment Estimate Exception 8 on the current Payment Estimate.				
			6	Jul 2, 2020	SYSTEM	(\$15,366.00)					
			6	Jul 2, 2020	SYSTEM	\$15,366.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overriding Payment Estimate Exception 14 on the current Payment Estimate.				
			7	Jul 16, 2020	SYSTEM	(\$15,366.00)					
			7	Jul 16, 2020	SYSTEM	\$15,366.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overriding Payment Estimate Exception 17 on the current Payment Estimate.				
			8	Aug 3, 2020	SYSTEM	(\$15,366.00)					
			8	Aug 3, 2020	SYSTEM	\$15,366.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overriding Payment Estimate Exception 17 on the current Payment Estimate.				
			9	Aug 18, 2020	SYSTEM	(\$15,366.00)					
			9	Aug 18, 2020	SYSTEM	\$15,366.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overriding Payment Estimate Exception 41 on the current Payment Estimate.				
			10	Sep 3, 2020	SYSTEM	(\$15,366.00)					
			10	Sep 3, 2020	SYSTEM	\$15,366.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user woodsk1 overriding Payment Estimate Exception 26 on the current Payment Estimate.				
			- Total							(\$15,366.00)	
			Material - Total							(\$15,366.00)	
	CONSTRUCTION SIGNS	MaterialCredit		2	May 4, 2020	SYSTEM	\$15,366.00				
- Total							\$15,366.00				
MaterialCredit - Total							\$15,366.00				
	CONSTRUCTION SIGNS	Other Item Adjustment	MDPA	1	Apr 16, 2020	woodsk1	\$15,366.00				
				2	May 4, 2020	woodsk1	(\$15,366.00)	This adjustment is being added to balance line item 0920 discrepancy amount.			
MDPA - Total							\$0.00				
Other Item Adjustment - Total							\$0.00				
0920 - Total							\$0.00				
0930	FLAG ASSEMBLY	Material		1	Apr 16, 2020	SYSTEM	(\$140.00)				
				2	May 4, 2020	SYSTEM	(\$140.00)				
				2	May 4, 2020	SYSTEM	\$140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overriding Payment Estimate Exception 9 on the current Payment Estimate.			
				3	May 19, 2020	SYSTEM	(\$140.00)				



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
0930	FLAG ASSEMBLY	Material		3	May 19, 2020	SYSTEM	\$140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overriding Payment Estimate Exception 9 on the current Payment Estimate.			
				4	Jun 3, 2020	SYSTEM	(\$140.00)				
				4	Jun 3, 2020	SYSTEM	\$140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overriding Payment Estimate Exception 10 on the current Payment Estimate.			
				5	Jun 16, 2020	SYSTEM	(\$140.00)				
				5	Jun 16, 2020	SYSTEM	\$140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overriding Payment Estimate Exception 10 on the current Payment Estimate.			
				6	Jul 2, 2020	SYSTEM	(\$140.00)				
				6	Jul 2, 2020	SYSTEM	\$140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overriding Payment Estimate Exception 16 on the current Payment Estimate.			
				7	Jul 16, 2020	SYSTEM	(\$140.00)				
				7	Jul 16, 2020	SYSTEM	\$140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overriding Payment Estimate Exception 18 on the current Payment Estimate.			
				8	Aug 3, 2020	SYSTEM	(\$140.00)				
				8	Aug 3, 2020	SYSTEM	\$140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overriding Payment Estimate Exception 18 on the current Payment Estimate.			
				9	Aug 18, 2020	SYSTEM	(\$140.00)				
				9	Aug 18, 2020	SYSTEM	\$140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user woodsk1 overriding Payment Estimate Exception 42 on the current Payment Estimate.			
				10	Sep 3, 2020	SYSTEM	(\$140.00)				
				10	Sep 3, 2020	SYSTEM	\$140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user woodsk1 overriding Payment Estimate Exception 28 on the current Payment Estimate.			
						- Total				(\$140.00)	
						Material - Total				(\$140.00)	
	FLAG ASSEMBLY	MaterialCredit		2	May 4, 2020	SYSTEM	\$140.00				
				- Total			\$140.00				
			MaterialCredit - Total				\$140.00				
	FLAG ASSEMBLY	Other Item Adjustment	MDPA	1	Apr 16, 2020	woodsk1	\$140.00				
				2	May 4, 2020	woodsk1	(\$140.00)	This adjustment is being added to balance line item 0180 discrepancy amount.			
			MDPA - Total				\$0.00				
			Other Item Adjustment - Total				\$0.00				
			0930 - Total				\$0.00				
0940	CHANNELIZER (TRIM LINE)	Material		4	Jun 3, 2020	SYSTEM	(\$600.00)				
				4	Jun 3, 2020	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overriding Payment Estimate Exception 11 on the current Payment Estimate.			
				5	Jun 16, 2020	SYSTEM	(\$600.00)				
				5	Jun 16, 2020	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun			



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0940	CHANNELIZER (TRIM LINE)	Material			2020			Payment Estimate Item Adjustment (0017) due to user woodsk1 overriding Payment Estimate Exception 12 on the current Payment Estimate.
			6	Jul 2, 2020	SYSTEM	(\$600.00)		
			6	Jul 2, 2020	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overriding Payment Estimate Exception 18 on the current Payment Estimate.	
			7	Jul 16, 2020	SYSTEM	(\$600.00)		
			7	Jul 16, 2020	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overriding Payment Estimate Exception 19 on the current Payment Estimate.	
			8	Aug 3, 2020	SYSTEM	(\$600.00)		
			8	Aug 3, 2020	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overriding Payment Estimate Exception 19 on the current Payment Estimate.	
			9	Aug 18, 2020	SYSTEM	(\$600.00)		
			9	Aug 18, 2020	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user woodsk1 overriding Payment Estimate Exception 43 on the current Payment Estimate.	
			10	Sep 3, 2020	SYSTEM	(\$600.00)		
			10	Sep 3, 2020	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user woodsk1 overriding Payment Estimate Exception 29 on the current Payment Estimate.	
						- Total		
	Material - Total						\$0.00	
0940 - Total							\$0.00	
0950	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	Material		1	Apr 16, 2020	SYSTEM	(\$7,000.00)	
				2	May 4, 2020	SYSTEM	(\$7,000.00)	
				2	May 4, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overriding Payment Estimate Exception 14 on the current Payment Estimate.
				3	May 19, 2020	SYSTEM	(\$7,000.00)	
				3	May 19, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overriding Payment Estimate Exception 14 on the current Payment Estimate.
				4	Jun 3, 2020	SYSTEM	(\$7,000.00)	
				4	Jun 3, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overriding Payment Estimate Exception 16 on the current Payment Estimate.
				5	Jun 16, 2020	SYSTEM	(\$7,000.00)	
				5	Jun 16, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overriding Payment Estimate Exception 16 on the current Payment Estimate.
				6	Jul 2, 2020	SYSTEM	(\$7,000.00)	
				6	Jul 2, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overriding Payment Estimate Exception 22 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$7,000.00)	



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0950	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	Material		7	Jul 16, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overriding Payment Estimate Exception 23 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$7,000.00)	
				8	Aug 3, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overriding Payment Estimate Exception 23 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$7,000.00)	
				9	Aug 18, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user woodsk1 overriding Payment Estimate Exception 47 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$7,000.00)	
				10	Sep 3, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user woodsk1 overriding Payment Estimate Exception 33 on the current Payment Estimate.
- Total							(\$7,000.00)	
Material - Total							(\$7,000.00)	
0950	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	MaterialCredit		2	May 4, 2020	SYSTEM	\$7,000.00	
				- Total				
MaterialCredit - Total							\$7,000.00	
0950	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	Other Item Adjustment	MDPA	1	Apr 16, 2020	woodsk1	\$7,000.00	
				2	May 4, 2020	woodsk1	(\$7,000.00)	This adjustment is being added to balance line item 0950 discrepancy amount.
				MDPA - Total				
Other Item Adjustment - Total							\$0.00	
0950 - Total							\$0.00	
0960	WORK ZONE TRAFFIC SIGNAL SYSTEM	Material		4	Jun 3, 2020	SYSTEM	(\$8,400.00)	
				4	Jun 3, 2020	SYSTEM	\$8,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overriding Payment Estimate Exception 17 on the current Payment Estimate.
				5	Jun 16, 2020	SYSTEM	(\$8,400.00)	
				5	Jun 16, 2020	SYSTEM	\$8,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overriding Payment Estimate Exception 17 on the current Payment Estimate.
				6	Jul 2, 2020	SYSTEM	(\$8,400.00)	
				6	Jul 2, 2020	SYSTEM	\$8,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overriding Payment Estimate Exception 23 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$8,400.00)	
				7	Jul 16, 2020	SYSTEM	\$8,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overriding Payment Estimate Exception 25 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$8,400.00)	
				8	Aug 3, 2020	SYSTEM	\$8,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overriding Payment Estimate Exception 25 on the current Payment Estimate.
0960				9	Aug 18, 2020	SYSTEM	(\$8,400.00)	



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0960	WORK ZONE TRAFFIC SIGNAL SYSTEM	Material		9	Aug 18, 2020	SYSTEM	\$8,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user woodsk1 overriding Payment Estimate Exception 49 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$8,400.00)	
				10	Sep 3, 2020	SYSTEM	\$8,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0034) due to user woodsk1 overriding Payment Estimate Exception 35 on the current Payment Estimate.
				- Total				
Material - Total							\$0.00	
0960 - Total							\$0.00	
0970	TEMPORARY LONG-TERM RUMBLE STRIPS	Material		4	Jun 3, 2020	SYSTEM	(\$3,600.00)	
				4	Jun 3, 2020	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overriding Payment Estimate Exception 18 on the current Payment Estimate.
				5	Jun 16, 2020	SYSTEM	(\$3,600.00)	
				5	Jun 16, 2020	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overriding Payment Estimate Exception 18 on the current Payment Estimate.
				6	Jul 2, 2020	SYSTEM	(\$3,600.00)	
				6	Jul 2, 2020	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overriding Payment Estimate Exception 24 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$3,600.00)	
				7	Jul 16, 2020	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overriding Payment Estimate Exception 26 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$3,600.00)	
				8	Aug 3, 2020	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user woodsk1 overriding Payment Estimate Exception 26 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$3,600.00)	
				9	Aug 18, 2020	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user woodsk1 overriding Payment Estimate Exception 50 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$3,600.00)	
				10	Sep 3, 2020	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0035) due to user woodsk1 overriding Payment Estimate Exception 36 on the current Payment Estimate.
- Total							\$0.00	
Material - Total							\$0.00	
0970 - Total							\$0.00	
0990	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	Material		4	Jun 3, 2020	SYSTEM	(\$2,424.00)	
				4	Jun 3, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overriding Payment Estimate Exception 19 on the current Payment Estimate.
				5	Jun 16, 2020	SYSTEM	(\$2,424.00)	
				5	Jun 16, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overriding Payment Estimate Exception 19 on the current



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0990	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	Material						Payment Estimate.
				6	Jul 2, 2020	SYSTEM	(\$2,424.00)	
				6	Jul 2, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user woodsk1 overriding Payment Estimate Exception 25 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$2,424.00)	
				7	Jul 16, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overriding Payment Estimate Exception 27 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$2,424.00)	
				8	Aug 3, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user woodsk1 overriding Payment Estimate Exception 27 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$2,424.00)	
				9	Aug 18, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0034) due to user woodsk1 overriding Payment Estimate Exception 51 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$2,424.00)	
				10	Sep 3, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0036) due to user woodsk1 overriding Payment Estimate Exception 37 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$2,424.00)	
				11	Sep 16, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overriding Payment Estimate Exception 25 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$2,424.00)	
				12	Oct 1, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overriding Payment Estimate Exception 13 on the current Payment Estimate.
				13	Oct 16, 2020	SYSTEM	(\$2,424.00)	
				13	Oct 16, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overriding Payment Estimate Exception 14 on the current Payment Estimate.
				14	Nov 2, 2020	SYSTEM	(\$2,424.00)	
				14	Nov 2, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overriding Payment Estimate Exception 15 on the current Payment Estimate.
				15	Nov 17, 2020	SYSTEM	(\$2,424.00)	
15	Nov 17, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overriding Payment Estimate Exception 16 on the current Payment Estimate.				
16	Dec 2, 2020	SYSTEM	(\$2,424.00)					
16	Dec 2, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overriding Payment Estimate Exception 16 on the current Payment Estimate.				
17	Dec 16, 2020	SYSTEM	(\$2,424.00)					
17	Dec 16, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1				



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0990	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	Material						overriding Payment Estimate Exception 14 on the current Payment Estimate.
				18	Jan 4, 2021	SYSTEM	(\$2,424.00)	
				18	Jan 4, 2021	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user woodsk1 overriding Payment Estimate Exception 14 on the current Payment Estimate.
			- Total					
Material - Total							\$0.00	
0990 - Total							\$0.00	
1000	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	Material		4	Jun 3, 2020	SYSTEM	(\$4,000.00)	
				4	Jun 3, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overriding Payment Estimate Exception 20 on the current Payment Estimate.
				5	Jun 16, 2020	SYSTEM	(\$4,000.00)	
				5	Jun 16, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overriding Payment Estimate Exception 20 on the current Payment Estimate.
				6	Jul 2, 2020	SYSTEM	(\$4,000.00)	
				6	Jul 2, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user woodsk1 overriding Payment Estimate Exception 26 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$4,000.00)	
				7	Jul 16, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user woodsk1 overriding Payment Estimate Exception 28 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$4,000.00)	
				8	Aug 3, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user woodsk1 overriding Payment Estimate Exception 28 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$4,000.00)	
				9	Aug 18, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0035) due to user woodsk1 overriding Payment Estimate Exception 52 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$4,000.00)	
				10	Sep 3, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0037) due to user woodsk1 overriding Payment Estimate Exception 38 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$4,000.00)	
				11	Sep 16, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overriding Payment Estimate Exception 26 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$4,000.00)	
				12	Oct 1, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overriding Payment Estimate Exception 14 on the current Payment Estimate.
	13	Oct 16, 2020	SYSTEM	(\$4,000.00)				
	13	Oct 16, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overriding Payment Estimate Exception 15 on the current			



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
1000	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	Material						Payment Estimate.			
			14	Nov 2, 2020	SYSTEM	(\$4,000.00)					
			14	Nov 2, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overriding Payment Estimate Exception 16 on the current Payment Estimate.				
			15	Nov 17, 2020	SYSTEM	(\$4,000.00)					
			15	Nov 17, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overriding Payment Estimate Exception 17 on the current Payment Estimate.				
			16	Dec 2, 2020	SYSTEM	(\$4,000.00)					
			16	Dec 2, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overriding Payment Estimate Exception 17 on the current Payment Estimate.				
			17	Dec 16, 2020	SYSTEM	(\$4,000.00)					
			17	Dec 16, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overriding Payment Estimate Exception 15 on the current Payment Estimate.				
			18	Jan 4, 2021	SYSTEM	(\$4,000.00)					
			18	Jan 4, 2021	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user woodsk1 overriding Payment Estimate Exception 15 on the current Payment Estimate.				
						- Total				\$0.00	
			Material - Total							\$0.00	
1000 - Total							\$0.00				
1010	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	Material		4	Jun 3, 2020	SYSTEM	(\$240.00)				
			4	Jun 3, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overriding Payment Estimate Exception 21 on the current Payment Estimate.				
			5	Jun 16, 2020	SYSTEM	(\$240.00)					
			5	Jun 16, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overriding Payment Estimate Exception 21 on the current Payment Estimate.				
			6	Jul 2, 2020	SYSTEM	(\$240.00)					
			6	Jul 2, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overriding Payment Estimate Exception 27 on the current Payment Estimate.				
			7	Jul 16, 2020	SYSTEM	(\$240.00)					
			7	Jul 16, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user woodsk1 overriding Payment Estimate Exception 29 on the current Payment Estimate.				
			8	Aug 3, 2020	SYSTEM	(\$240.00)					
			8	Aug 3, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overriding Payment Estimate Exception 29 on the current Payment Estimate.				
			9	Aug 18, 2020	SYSTEM	(\$240.00)					
			9	Aug 18, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0036) due to user woodsk1 overriding Payment Estimate Exception 53 on the current Payment Estimate.				



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
1010	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	Material		10	Sep 3, 2020	SYSTEM	(\$240.00)					
				10	Sep 3, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overriding Payment Estimate Exception 39 on the current Payment Estimate.				
				11	Sep 16, 2020	SYSTEM	(\$240.00)					
				11	Sep 16, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overriding Payment Estimate Exception 27 on the current Payment Estimate.				
				12	Oct 1, 2020	SYSTEM	(\$240.00)					
				12	Oct 1, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overriding Payment Estimate Exception 15 on the current Payment Estimate.				
				13	Oct 16, 2020	SYSTEM	(\$240.00)					
				13	Oct 16, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overriding Payment Estimate Exception 16 on the current Payment Estimate.				
				14	Nov 2, 2020	SYSTEM	(\$240.00)					
				14	Nov 2, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overriding Payment Estimate Exception 17 on the current Payment Estimate.				
				15	Nov 17, 2020	SYSTEM	(\$240.00)					
				15	Nov 17, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overriding Payment Estimate Exception 18 on the current Payment Estimate.				
				16	Dec 2, 2020	SYSTEM	(\$240.00)					
				16	Dec 2, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overriding Payment Estimate Exception 18 on the current Payment Estimate.				
				17	Dec 16, 2020	SYSTEM	(\$240.00)					
				17	Dec 16, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overriding Payment Estimate Exception 16 on the current Payment Estimate.				
				18	Jan 4, 2021	SYSTEM	(\$240.00)					
				18	Jan 4, 2021	SYSTEM	\$240.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user woodsk1 overriding Payment Estimate Exception 16 on the current Payment Estimate.				
							- Total				\$0.00	
				Material - Total							\$0.00	
1010 - Total							\$0.00					
1020	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		3	May 19, 2020	SYSTEM	(\$6,270.00)					
				3	May 19, 2020	SYSTEM	\$6,270.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overriding Payment Estimate Exception 15 on the current Payment Estimate.				
				4	Jun 3, 2020	SYSTEM	(\$6,270.00)					
				4	Jun 3, 2020	SYSTEM	\$6,270.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overriding Payment Estimate Exception 22 on the current Payment Estimate.				
				5	Jun 16, 2020	SYSTEM	(\$6,270.00)					



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1020	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			2020			
				5	Jun 16, 2020	SYSTEM	\$6,270.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overriding Payment Estimate Exception 22 on the current Payment Estimate.
				6	Jul 2, 2020	SYSTEM	(\$6,270.00)	
				6	Jul 2, 2020	SYSTEM	\$6,270.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user woodsk1 overriding Payment Estimate Exception 28 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$6,270.00)	
				7	Jul 16, 2020	SYSTEM	\$6,270.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user woodsk1 overriding Payment Estimate Exception 30 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$6,270.00)	
				8	Aug 3, 2020	SYSTEM	\$6,270.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user woodsk1 overriding Payment Estimate Exception 30 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$6,270.00)	
				9	Aug 18, 2020	SYSTEM	\$6,270.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0037) due to user woodsk1 overriding Payment Estimate Exception 54 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$12,574.32)	
				10	Sep 3, 2020	SYSTEM	\$12,574.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0038) due to user woodsk1 overriding Payment Estimate Exception 40 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$12,574.32)	
				11	Sep 16, 2020	SYSTEM	\$12,574.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overriding Payment Estimate Exception 28 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$12,574.32)	
				12	Oct 1, 2020	SYSTEM	\$12,574.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overriding Payment Estimate Exception 16 on the current Payment Estimate.
				13	Oct 16, 2020	SYSTEM	(\$12,574.32)	
				13	Oct 16, 2020	SYSTEM	\$12,574.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overriding Payment Estimate Exception 17 on the current Payment Estimate.
				14	Nov 2, 2020	SYSTEM	(\$12,574.32)	
				14	Nov 2, 2020	SYSTEM	\$12,574.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overriding Payment Estimate Exception 18 on the current Payment Estimate.
	15	Nov 17, 2020	SYSTEM	(\$12,574.32)				
	15	Nov 17, 2020	SYSTEM	\$12,574.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overriding Payment Estimate Exception 19 on the current Payment Estimate.			
	16	Dec 2, 2020	SYSTEM	(\$12,574.32)				
	16	Dec 2, 2020	SYSTEM	\$12,574.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overriding Payment Estimate Exception 19 on the current Payment Estimate.			



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1020	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		17	Dec 16, 2020	SYSTEM	(\$12,574.32)	
				17	Dec 16, 2020	SYSTEM	\$12,574.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overriding Payment Estimate Exception 17 on the current Payment Estimate.
				18	Jan 4, 2021	SYSTEM	(\$12,574.32)	
				18	Jan 4, 2021	SYSTEM	\$12,574.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user woodsk1 overriding Payment Estimate Exception 17 on the current Payment Estimate.
- Total							\$0.00	
Material - Total							\$0.00	
	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Other Item Adjustment	REFL	10	Sep 3, 2020	woodsk1	\$153.21	Yellow: $63.78\% @ 105 = (102,369 \times .6378) = (65,290.9' @ 105\% \text{ Pay Adjustment}) = (65,290.9 \times .0055) = \359.10 $32.14\% @ 100 = (102,369 \times .3214) = (32,901.4' @ 100\% \text{ Pay}) *(\text{Also Includes 2nd Mobilization \& Application})$ $4.08\% @ 80 = (102,369 \times .0408) = (4,176.7' @ 80\% \text{ Pay Adjustment}) = (4,176.7 \times .088) = -\91.89 Total Adjustment = \$267.21 White: $92.28\% @ 105 = (30,488 \times .9228) = (28,134.3' @ 105\% \text{ Pay Adjustment}) = (28,134.3 \times .0055) = \154.74 $7.2\% @ 100 = (30,488 \times .0720) = (2,195.1' @ 100\% \text{ Pay}) *(\text{Also Includes 2nd Mobilization \& Application})$ $0.52\% @ 80 = (30,488 \times .0052) = (158.5' @ 80\% \text{ Pay Adjustment}) = (158.5 \times .088) = -\1.53 Total Adjustment = \$153.21 * Remaining Quantity From 2nd Mobilization & Application Paid @ 100%
REFL - Total							\$153.21	
Other Item Adjustment - Total							\$153.21	
1020 - Total							\$153.21	
1030	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		3	May 19, 2020	SYSTEM	(\$1,760.00)	
				3	May 19, 2020	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overriding Payment Estimate Exception 17 on the current Payment Estimate.
				4	Jun 3, 2020	SYSTEM	(\$1,760.00)	
				4	Jun 3, 2020	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overriding Payment Estimate Exception 24 on the current Payment Estimate.
				5	Jun 16, 2020	SYSTEM	(\$1,760.00)	
				5	Jun 16, 2020	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overriding Payment Estimate Exception 24 on the current Payment Estimate.
				6	Jul 2, 2020	SYSTEM	(\$1,760.00)	



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1030	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		6	Jul 2, 2020	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user woodsk1 overriding Payment Estimate Exception 30 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$1,760.00)	
				7	Jul 16, 2020	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user woodsk1 overriding Payment Estimate Exception 32 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$1,760.00)	
				8	Aug 3, 2020	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user woodsk1 overriding Payment Estimate Exception 32 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$1,760.00)	
				9	Aug 18, 2020	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0038) due to user woodsk1 overriding Payment Estimate Exception 56 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$3,519.89)	
				10	Sep 3, 2020	SYSTEM	\$3,519.89	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0039) due to user woodsk1 overriding Payment Estimate Exception 42 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$3,519.89)	
				11	Sep 16, 2020	SYSTEM	\$3,519.89	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user woodsk1 overriding Payment Estimate Exception 30 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$3,519.89)	
				12	Oct 1, 2020	SYSTEM	\$3,519.89	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overriding Payment Estimate Exception 18 on the current Payment Estimate.
				13	Oct 16, 2020	SYSTEM	(\$3,519.89)	
				13	Oct 16, 2020	SYSTEM	\$3,519.89	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overriding Payment Estimate Exception 19 on the current Payment Estimate.
				14	Nov 2, 2020	SYSTEM	(\$3,519.89)	
				14	Nov 2, 2020	SYSTEM	\$3,519.89	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overriding Payment Estimate Exception 20 on the current Payment Estimate.
				15	Nov 17, 2020	SYSTEM	(\$3,519.89)	
15	Nov 17, 2020	SYSTEM	\$3,519.89	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overriding Payment Estimate Exception 21 on the current Payment Estimate.				
16	Dec 2, 2020	SYSTEM	(\$3,519.89)					
16	Dec 2, 2020	SYSTEM	\$3,519.89	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overriding Payment Estimate Exception 21 on the current Payment Estimate.				
17	Dec 16, 2020	SYSTEM	(\$3,519.89)					
17	Dec 16, 2020	SYSTEM	\$3,519.89	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overriding Payment Estimate Exception 19 on the current Payment Estimate.				
18	Jan 4, 2021	SYSTEM	(\$3,519.89)					



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1030	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		18	Jan 4, 2021	SYSTEM	\$3,519.89	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user woodsk1 overriding Payment Estimate Exception 19 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Other Item Adjustment	REFL	10	Sep 3, 2020	woodsk1	\$267.21	Yellow: $63.78\% @ 105 = (102,369 \times .6378) = (65,290.9' @ 105\% \text{ Pay Adjustment}) = (65,290.9 \times .0055) = \359.10 $32.14\% @ 100 = (102,369 \times .3214) = (32,901.4' @ 100\% \text{ Pay}) *(\text{Also Includes 2nd Mobilization \& Application})$ $4.08\% @ 80 = (102,369 \times .0408) = (4,176.7' @ 80\% \text{ Pay Adjustment}) = (4,176.7 \times .088) = -\91.89 Total Adjustment = \$267.21 White: $92.28\% @ 105 = (30,488 \times .9228) = (28,134.3' @ 105\% \text{ Pay Adjustment}) = (28,134.3 \times .0055) = \154.74 $7.2\% @ 100 = (30,488 \times .0720) = (2,195.1' @ 100\% \text{ Pay}) *(\text{Also Includes 2nd Mobilization \& Application})$ $0.52\% @ 80 = (30,488 \times .0052) = (158.5' @ 80\% \text{ Pay Adjustment}) = (158.5 \times .088) = -\1.53 Total Adjustment = \$153.21 * Remaining Quantity From 2nd Mobilization & Application Paid @ 100%
			REFL - Total				\$267.21	
	Other Item Adjustment - Total						\$267.21	
1030 - Total							\$267.21	
1080	MGS GUARDRAIL	Construction Stockpile		1	Apr 16, 2020	SYSTEM	\$1,493.80	Payment Estimate Item Adjustment generated Stockpile Transaction
				8	Aug 3, 2020	SYSTEM	(\$1,493.80)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
1080 - Total							\$0.00	
1090	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	Construction Stockpile		1	Apr 16, 2020	SYSTEM	\$5,996.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				8	Aug 3, 2020	SYSTEM	(\$5,996.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
1090 - Total							\$0.00	
1100	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		1	Apr 16, 2020	SYSTEM	\$6,040.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				8	Aug 3, 2020	SYSTEM	(\$6,040.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
1100 - Total							\$0.00	
1130	EMULSIFIED ASPHALT, SEAL COAT	Material		9	Aug 18, 2020	SYSTEM	(\$575.00)	
				9	Aug 18, 2020	SYSTEM	\$575.00	This adjustment offsets the original system-generated Overrun



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
1130	EMULSIFIED ASPHALT, SEAL COAT	Material			2020			Payment Estimate Item Adjustment (0039) due to user woodsk1 overriding Payment Estimate Exception 12 on the current Payment Estimate.	
				10	Sep 3, 2020	SYSTEM	(\$575.00)		
				10	Sep 3, 2020	SYSTEM	\$575.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0040) due to user woodsk1 overriding Payment Estimate Exception 5 on the current Payment Estimate.	
				11	Sep 16, 2020	SYSTEM	(\$575.00)		
				11	Sep 16, 2020	SYSTEM	\$575.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user woodsk1 overriding Payment Estimate Exception 5 on the current Payment Estimate.	
				- Total				\$0.00	
	Material - Total							\$0.00	
		EMULSIFIED ASPHALT, SEAL COAT	Other Item Adjustment	ACAD	19	Jan 20, 2021	woodsk1	(\$20.97)	AC Seal Coat Adjustment. August 10th, 2020 placement date.
				ACAD - Total				(\$20.97)	
	Other Item Adjustment - Total							(\$20.97)	
1130 - Total							(\$20.97)		
1140	SEAL COAT AGGREGATE, GRADE B1	Material		9	Aug 18, 2020	SYSTEM	(\$1,435.00)		
				9	Aug 18, 2020	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0040) due to user woodsk1 overriding Payment Estimate Exception 28 on the current Payment Estimate.	
				10	Sep 3, 2020	SYSTEM	(\$1,435.00)		
				10	Sep 3, 2020	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0041) due to user woodsk1 overriding Payment Estimate Exception 14 on the current Payment Estimate.	
				11	Sep 16, 2020	SYSTEM	(\$1,435.00)		
				11	Sep 16, 2020	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user woodsk1 overriding Payment Estimate Exception 14 on the current Payment Estimate.	
				12	Oct 1, 2020	SYSTEM	(\$1,435.00)		
				12	Oct 1, 2020	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overriding Payment Estimate Exception 3 on the current Payment Estimate.	
				13	Oct 16, 2020	SYSTEM	(\$1,435.00)		
				13	Oct 16, 2020	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overriding Payment Estimate Exception 3 on the current Payment Estimate.	
				14	Nov 2, 2020	SYSTEM	(\$1,435.00)		
				14	Nov 2, 2020	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overriding Payment Estimate Exception 3 on the current Payment Estimate.	
				15	Nov 17, 2020	SYSTEM	(\$1,435.00)		
				15	Nov 17, 2020	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overriding Payment Estimate Exception 5 on the current Payment Estimate.	
				16	Dec 2, 2020	SYSTEM	(\$1,435.00)		
				16	Dec 2, 2020	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overriding Payment Estimate Exception 5 on the current	



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1140	SEAL COAT AGGREGATE, GRADE B1	Material						Payment Estimate.
				17	Dec 16, 2020	SYSTEM	(\$1,435.00)	
				17	Dec 16, 2020	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overriding Payment Estimate Exception 5 on the current Payment Estimate.
				18	Jan 4, 2021	SYSTEM	(\$1,435.00)	
				18	Jan 4, 2021	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user woodsk1 overriding Payment Estimate Exception 6 on the current Payment Estimate.
				19	Jan 20, 2021	SYSTEM	(\$1,435.00)	
				19	Jan 20, 2021	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user woodsk1 overriding Payment Estimate Exception 6 on the current Payment Estimate.
				20	Feb 1, 2021	SYSTEM	(\$1,435.00)	
				20	Feb 1, 2021	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user woodsk1 overriding Payment Estimate Exception 6 on the current Payment Estimate.
							- Total	
Material - Total							\$0.00	
1140 - Total							\$0.00	
1150	SUPERSTRUCTURE REPAIR (UNFORMED)	Material		6	Jul 2, 2020	SYSTEM	(\$3,111.60)	
				6	Jul 2, 2020	SYSTEM	\$3,111.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user woodsk1 overriding Payment Estimate Exception 44 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$6,223.20)	
				7	Jul 16, 2020	SYSTEM	\$6,223.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user woodsk1 overriding Payment Estimate Exception 46 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$6,223.20)	
				8	Aug 3, 2020	SYSTEM	\$6,223.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0036) due to user woodsk1 overriding Payment Estimate Exception 46 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$6,223.20)	
				9	Aug 18, 2020	SYSTEM	\$6,223.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0041) due to user woodsk1 overriding Payment Estimate Exception 81 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$6,223.20)	
				10	Sep 3, 2020	SYSTEM	\$6,223.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0042) due to user woodsk1 overriding Payment Estimate Exception 67 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$6,223.20)	
				11	Sep 16, 2020	SYSTEM	\$6,223.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user woodsk1 overriding Payment Estimate Exception 55 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$9,645.96)	
				12	Oct 1, 2020	SYSTEM	\$9,645.96	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overriding Payment Estimate Exception 43 on the current Payment Estimate.



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1150	SUPERSTRUCTURE REPAIR (UNFORMED)	Material		13	Oct 16, 2020	SYSTEM	(\$9,645.96)	
				13	Oct 16, 2020	SYSTEM	\$9,645.96	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overriding Payment Estimate Exception 44 on the current Payment Estimate.
				14	Nov 2, 2020	SYSTEM	(\$9,645.96)	
				14	Nov 2, 2020	SYSTEM	\$9,645.96	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user woodsk1 overriding Payment Estimate Exception 45 on the current Payment Estimate.
				15	Nov 17, 2020	SYSTEM	(\$9,645.96)	
				15	Nov 17, 2020	SYSTEM	\$9,645.96	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overriding Payment Estimate Exception 46 on the current Payment Estimate.
				16	Dec 2, 2020	SYSTEM	(\$9,645.96)	
				16	Dec 2, 2020	SYSTEM	\$9,645.96	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overriding Payment Estimate Exception 46 on the current Payment Estimate.
				17	Dec 16, 2020	SYSTEM	(\$9,645.96)	
				17	Dec 16, 2020	SYSTEM	\$9,645.96	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overriding Payment Estimate Exception 44 on the current Payment Estimate.
				18	Jan 4, 2021	SYSTEM	(\$9,645.96)	
				18	Jan 4, 2021	SYSTEM	\$9,645.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user woodsk1 overriding Payment Estimate Exception 44 on the current Payment Estimate.
							- Total	
Material - Total							\$0.00	
1150 - Total							\$0.00	
1160	SLAB EDGE REPAIR (BRIDGES)	Material		5	Jun 16, 2020	SYSTEM	(\$7,361.70)	
				5	Jun 16, 2020	SYSTEM	\$7,361.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overriding Payment Estimate Exception 40 on the current Payment Estimate.
				6	Jul 2, 2020	SYSTEM	(\$7,361.70)	
				6	Jul 2, 2020	SYSTEM	\$7,361.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0034) due to user woodsk1 overriding Payment Estimate Exception 52 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$14,723.40)	
				7	Jul 16, 2020	SYSTEM	\$14,723.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0034) due to user woodsk1 overriding Payment Estimate Exception 56 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$14,723.40)	
				8	Aug 3, 2020	SYSTEM	\$14,723.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0037) due to user woodsk1 overriding Payment Estimate Exception 56 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$14,723.40)	
				9	Aug 18, 2020	SYSTEM	\$14,723.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0042) due to user woodsk1 overriding Payment Estimate Exception 91 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$14,723.40)	



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
1160	SLAB EDGE REPAIR (BRIDGES)	Material			2020							
				10	Sep 3, 2020	SYSTEM	\$14,723.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0043) due to user woodsk1 overriding Payment Estimate Exception 77 on the current Payment Estimate.				
				11	Sep 16, 2020	SYSTEM	(\$14,723.40)					
				11	Sep 16, 2020	SYSTEM	\$14,723.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user woodsk1 overriding Payment Estimate Exception 67 on the current Payment Estimate.				
				12	Oct 1, 2020	SYSTEM	(\$14,723.40)					
				12	Oct 1, 2020	SYSTEM	\$14,723.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user woodsk1 overriding Payment Estimate Exception 54 on the current Payment Estimate.				
				13	Oct 16, 2020	SYSTEM	(\$14,723.40)					
				13	Oct 16, 2020	SYSTEM	\$14,723.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overriding Payment Estimate Exception 55 on the current Payment Estimate.				
				14	Nov 2, 2020	SYSTEM	(\$14,723.40)					
				14	Nov 2, 2020	SYSTEM	\$14,723.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user woodsk1 overriding Payment Estimate Exception 56 on the current Payment Estimate.				
				15	Nov 17, 2020	SYSTEM	(\$14,723.40)					
				15	Nov 17, 2020	SYSTEM	\$14,723.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overriding Payment Estimate Exception 57 on the current Payment Estimate.				
				16	Dec 2, 2020	SYSTEM	(\$14,723.40)					
				16	Dec 2, 2020	SYSTEM	\$14,723.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overriding Payment Estimate Exception 57 on the current Payment Estimate.				
				17	Dec 16, 2020	SYSTEM	(\$14,723.40)					
				17	Dec 16, 2020	SYSTEM	\$14,723.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user woodsk1 overriding Payment Estimate Exception 57 on the current Payment Estimate.				
				18	Jan 4, 2021	SYSTEM	(\$14,723.40)					
				18	Jan 4, 2021	SYSTEM	\$14,723.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user woodsk1 overriding Payment Estimate Exception 57 on the current Payment Estimate.				
				- Total							\$0.00	
				Material - Total							\$0.00	
1160 - Total							\$0.00					
1180	BRIDGE GUARDRAIL (THRIE BEAM)	Construction Stockpile		2	May 4, 2020	SYSTEM	\$29,370.00	Payment Estimate Item Adjustment generated Stockpile Transaction				
				6	Jul 2, 2020	SYSTEM	(\$14,685.00)	Payment Estimate Item Adjustment generated Stockpile Transaction				
				8	Aug 3, 2020	SYSTEM	(\$14,685.00)	Payment Estimate Item Adjustment generated Stockpile Transaction				
				- Total							\$0.00	
Construction Stockpile - Total							\$0.00					
1180 - Total							\$0.00					
5004	SLAB EDGE REPAIR (BRIDGES)	Material		17	Dec 16, 2020	SYSTEM	(\$5,398.58)					
				17	Dec 16, 2020	SYSTEM	\$5,398.58	This adjustment offsets the original system-generated Overrun				



**Missouri Department of Transportation
Contractor's Pay Estimate Summary
Line Item Adjustments - All Estimates**

Report Generated on February 3, 2021

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
5004	SLAB EDGE REPAIR (BRIDGES)	Material			2020			Payment Estimate Item Adjustment (0018) due to user woodsk1 overriding Payment Estimate Exception 55 on the current Payment Estimate.
				18	Jan 4, 2021	SYSTEM	(\$5,398.58)	
				18	Jan 4, 2021	SYSTEM	\$5,398.58	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user woodsk1 overriding Payment Estimate Exception 56 on the current Payment Estimate.
				- Total				
Material - Total							\$0.00	
5004 - Total							\$0.00	
5005	SLAB EDGE REPAIR (BRIDGES)	Material		17	Dec 16, 2020	SYSTEM	(\$7,607.09)	
				17	Dec 16, 2020	SYSTEM	\$7,607.09	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overriding Payment Estimate Exception 56 on the current Payment Estimate.
				18	Jan 4, 2021	SYSTEM	(\$7,607.09)	
				18	Jan 4, 2021	SYSTEM	\$7,607.09	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user woodsk1 overriding Payment Estimate Exception 55 on the current Payment Estimate.
- Total							\$0.00	
Material - Total							\$0.00	
5005 - Total							\$0.00	
Overall - Total							\$154,999.19	