

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: March 16, 2021

Progress Estimate Number 23 Contrac			200117-H07 or Apex Paving		Period Start Period End	March 2 March 1		Original Contract Amount Net Change Order Amount Current Contract Amount	\$8,709,119.25 \$834,905.88 \$9,544,025.13
Approval Date									By User
March 16, 2021			Generated and	Approved	(and should b	e consider	ed Draft)	at the Project Office Level by	woodsk1
March 16, 2021	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by								bollis1
March 17, 2021	Reviewed and Approved at the Central Office Controllers Office Level by								
Original Completio	n Date	Current Com	pletion Date	ual Completion Date %			% of Current Contract Amou	nt Complete	
July 1, 2021 Septemb			er 7, 2021					58.89%	
	es		ı	/lilestones	3				
Date Description	Original C	Completion Date	Current Completion Date		No Milestones Exist for Conf		or Contra	ct	
Acceptance Date									
Awarded Date	February 5	5, 2020	February 5, 2020						
Letting Date	January 1	7, 2020	January 17, 2020						
Notice to Proceed Date	April 6, 20	20	April 6, 2020						
Open to Traffic Date									
Work Began Date									

Contract Total Pay For Estimate No. 23			
	This Estimate	Previous	To Date
200117-H07			
Total Posted Items Pay	\$138,359.62	\$5,481,947.76	\$5,620,307.38
Gross Item Adjustments	(\$67,077.75)	\$154,999.19	\$87,921.44
Incentive	\$0.00	\$0.00	\$0.00
Disincentive	\$0.00	\$0.00	\$0.00
Liquidated Damage	\$0.00	\$0.00	\$0.00
Other Contract Adjustments	\$0.00	\$0.00	\$0.00
		\$5,636,946.95	\$5,708,228.82
Contract Total Payable This Estimate:	\$71,281.87		

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J9I3553	0310	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	SQYD	\$6.490	638	\$4,140.62
	0320	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	SQYD	\$7.250	1,244	\$9,019.00
	0350	6061060	MGS GUARDRAIL	LF	\$20.000	3,325	\$66,500.00
	0360	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	EA	\$2,900.000	10	\$29,000.00
	0380	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	EA	\$2,700.000	11	\$29,700.00
Project J9I	3553 - Tot	al					\$138,359.62
Overall - T	otal						\$138,359.62

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item	<u>Adjust</u>	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9I3553	0050	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Material			-1,585.9	\$57.84	(\$91,728.46)
	0050	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	1,585.9	\$57.84	\$91,728.46

Revision 4/1/2020 Page 1 of 70



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: March 16, 2021

ect ber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
553	0100	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material			-489.9	\$185.16	(\$90,709.88
	0100	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	489.9	\$185.16	\$90,709.88		
	0350	MGS GUARDRAIL	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$35,477.75
	0360	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$14,990.00
	0380	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$16,610.00
	0410	SEAL COAT AGGREGATE, GRADE B1	Material			-265	\$5.00	(\$1,325.00
	0410	SEAL COAT AGGREGATE, GRADE B1	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	265	\$5.00	\$1,325.00
	0420	CURB BLOCKOUT	Material			-170	\$196.14	(\$33,343.80
	0420	CURB BLOCKOUT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	170	\$196.14	\$33,343.80
	0430	HALF-SOLE REPAIR	Material			-755	\$97.74	(\$73,793.70
	0430	HALF-SOLE REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 33 on the current Payment Estimate.	755	\$97.74	\$73,793.70
	0460	SEAL COAT AGGREGATE, GRADE B1	Material			-288	\$5.00	(\$1,440.00
	0460	SEAL COAT AGGREGATE, GRADE B1	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	288	\$5.00	\$1,440.00
	0470	CURB BLOCKOUT	Material			-185	\$193.61	(\$35,817.85
	0470	CURB BLOCKOUT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	185	\$193.61	\$35,817.85
	0480	HALF-SOLE REPAIR	Material			-723	\$96.76	(\$69,957.48
	0480	HALF-SOLE REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 36 on the current Payment Estimate.	723	\$96.76	\$69,957.48
	0510	SEAL COAT AGGREGATE, GRADE B1	Material			-265	\$5.00	(\$1,325.00
	0510	SEAL COAT AGGREGATE, GRADE B1	Material		This adjustment offsets the original system- generated Material Payment Estimate Item	265	\$5.00	\$1,325.00

Revision 4/1/2020 Page 2 of 70



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: March 16, 2021

Progress Estimate Number 23 Contra		Pay Period Start Pay Period End March 15, 2021 Orig March 15, 2021 Orig Curr	
------------------------------------	--	--	--

C	0520 0520 0520 0530 0530	CURB BLOCKOUT CURB BLOCKOUT HALF-SOLE REPAIR HALF-SOLE REPAIR	Material Material Material		Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original systemgenerated Material Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate Estimate.	-170 170	\$196.14 \$196.14	(\$33,343.80 \$33,343.80
C	0520	CURB BLOCKOUT HALF-SOLE REPAIR	Material		generated Material Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 21			
С	0530	HALF-SOLE REPAIR			generated Material Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 21	170	\$196.14	\$33,343.80
			Material		,			
C	0530	HALF-SOLE REPAIR	0530 HALF-SOLE REPAIR Material			-853	\$97.74	(\$83,372.22
			Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 40 on the current Payment Estimate.	853	\$97.74	\$83,372.22
C	0560	SEAL COAT AGGREGATE, GRADE B1	Material			-241	\$5.00	(\$1,205.00)
C	0560	SEAL COAT AGGREGATE, GRADE B1	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	241	\$5.00	\$1,205.00
C	0570	CURB BLOCKOUT	Material			-155	\$199.15	(\$30,868.25
C	0570	CURB BLOCKOUT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 27 on the current Payment Estimate.	155	\$199.15	\$30,868.25
19S3571 1	1140	SEAL COAT AGGREGATE, GRADE B1	Material			-287	\$5.00	(\$1,435.00)
1	1140	SEAL COAT AGGREGATE, GRADE B1	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	287	\$5.00	\$1,435.00

Revision 4/1/2020 Page 3 of 70



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Co	ontract Project Information	1					
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work					
J9I3553	FAF 60-4(86)	Resurface	60	SCOTT	from I-57 to Spring Cree	ek						
J9S3571	FAS S703(31) Resurface 69 MISSISSIPPI f				from I-57 to Bridge K099	m I-57 to Bridge K0950						
Γotals by .	Job Numbe	rs										
J9I3553		d Item Pay Item Adjustm			This Estimate \$138,359.62 (\$67,077.75)	Previous \$3,733,049.56 \$84,557.15	To Date \$3,871,409.18 \$17,479.40					
	Liquid	tive centive lated Damages Contract Adju	S	s Item Pay	\$71,281.87 \$0.00 \$0.00 \$0.00 \$0.00	\$3,817,606.71 \$0.00 \$0.00 \$0.00 \$0.00	\$3,888,888.58 \$0.00 \$0.00 \$0.00 \$0.00					
J9S3571	Poste	d Item Pay Item Adjustm	ents	s Item Pay	This Estimate \$0.00 \$0.00 \$0.00	Previous \$1,748,898.20 \$70,442.04 \$1,819,340.24	To Date \$1,748,898.20 \$70,442.04 \$1,819,340.24					
	Liquid	tive centive lated Damages Contract Adiu			\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00					

Revision 4/1/2020 Page 4 of 70



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Estimate Exception Type: Insufficient Materials: Project J913553, Item 4030103, Project Item Line Number 0050, Material Set 403010398, Material 1003GB + Aggregate for Seal Coat Grade B1, Acceptance Action Generic Australia (1003GB - Aggregate for Seal Coat Grade B1, Acceptance Action Generic 1003GB is insufficient Materials: Project J913553, Item 4094011, Project Item Line Number 04010, Material Set 409401196, Material 1003GB - Aggregate for Seal Coat Grade B1, Acceptance Action Generic 1003GB is insufficient Materials: Project J913553, Item 4094011, Project Item Line Number 0406, Material Set 409401196, Material 1003GB - Aggregate for Seal Coat Grade B1, Acceptance Action 0400, Material Set 409401196, Material 1003GB - Aggregate for Seal Coat Grade B1, Acceptance Action 0400, Material Set 409401196, Material 1003GB - Aggregate for Seal Coat Grade B1, Acceptance Action 0400, Material Set 409401196, Material 1003GB - Aggregate for Seal Coat Grade B1, Acceptance Action 0400, Material Set 409401196, Material 1003GB - Aggregate for Seal Coat Grade B1, Acceptance Action 0400, Material Set 409401196, Material 1003GB - Aggregate for Seal Coat Grade B1, Acceptance Action 04000 Seal Seal Seal Seal Coat Grade B1, Acceptance Action 04000 Seal Seal Seal Seal Coat Grade B1, Acceptance Action 04000 Seal Seal Seal Seal Seal Coat Grade B1, Acceptance Action 04000 Seal Seal Seal Seal Seal Seal Seal Seal
0050, Material Set 403010396, Material O403SP125CLG - Superpave 12.5 mm, Des C 80 Gyros, Acceptance Action Generic AspHigh is insufficient. Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 4094011, Project Item Line Number O410, Material Set 409401196, Material 1003GB - Aggregate for Seal Coat Grade B1, Acceptance Action Generic 1003GB is insufficient. Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 4094011, Project Item Line Number O460, Material Set 409401196, Material 1003GB - Aggregate for Seal Coat Grade B1, Acceptance Action Generic 1003GB is insufficient. Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 4094011, Project Item Line Number O510, Material Set 409401196, Material 1003GB - Aggregate for Seal Coat Grade B1, Acceptance Action Generic 1003GB is insufficient. Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 4094011, Project Item Line Number O560, Material Set 409401196, Material 5et 409401196, Material Set 50940196,
Q410, Material Set 409401196, Material 1003GB - Ággregate for Seal Coat Grade B1, Acceptance Action Generic 1003GB is insufficient.
Q460, Material Set 409401196, Material 1003GB - Aggregate for Seal Coat Grade B1, Acceptance Action Generic 1003GB is insufficient.
OS10, Material Set 409401196, Material 1003GB - Ággregate for Seal Coat Grade B1, Acceptance Action Generic 1003GB is insufficient. Estimate Exception Type: Insufficient Materials: Project J913553, Item 4094011, Project Item Line Number 0560, Material Set 409401196, Material 1003GB - Aggregate for Seal Coat Grade B1, Acceptance Action Generic 1003GB is insufficient. Estimate Exception Type: Insufficient Materials: Project J935571, Item 4094011, Project Item Line Number 1140, Material Set 409401196, Material 1003GB - Aggregate for Seal Coat Grade B1, Acceptance Action Generic 1003GB is insufficient. Estimate Exception Type: Insufficient Materials: Project J913553, Item 6131010, Project Item Line Number 1000, Material Set 613101096, Material 100510. CPCMLD is insufficient. Estimate Exception Type: Insufficient Materials: Project J913553, Item 6131010, Project Item Line Number 1010, Material Set 613101096, Material Set 513101096, Material Set 51310109
0560, Material Set 409401196, Material 1003GB - Ággregate for Seal Coat Grade B1, Acceptance Action Generic 1003GB is insufficient. Estimate Exception Type: Insufficient Materials: Project J9S3571, Item 4094011, Project Item Line Number 1140, Material Set 409401196, Material 1003GB - Aggregate for Seal Coat Grade B1, Acceptance Action Generic 1003GB is insufficient. Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 6131010, Project Item Line Number 0100, Material Set 613101096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient. Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 6131010, Project Item Line Number 0100, Material Set 613101096, Material 0501CCPAEA - Concrete, Pavement HES w/Air, Acceptance Action 0501CCPAEA is insufficient. Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 6131010, Project Item Line Number 0100, Material Set 613101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient. Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 6131010, Project Item Line Number 0100, Material Set 613101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient. Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7034600, Project Item Line Number 0420, Material Set 703460096, Material 1039ERRAS - Epoxy Bonding Agent-Resin Anchor Systems,
Number 1140, Material Set 409401196, Material 1003GB - Aggregate for Seal Coat Grade B1, Acceptance Action Generic 1003GB is insufficient. Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 6131010, Project Item Line Number 0100, Material Set 613101096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient. Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 6131010, Project Item Line Number 0100, Material Set 613101096, Material 0501CCPAEA - Concrete, Pavement HES w/Air, Acceptance Action 0501CCPAEA is insufficient. Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 6131010, Project Item Line Number 0100, Material Set 613101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient. Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 6131010, Project Item Line Number 0100, Material Set 703460096, Material 1035FACCNSCA is insufficient. Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0420, Material Set 703460096, Material 1039ERRAS - Epoxy Bonding Agent-Resin Anchor Systems,
0100, Material Set 613101096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient. Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 6131010, Project Item Line Number 0100, Material Set 613101096, Material 0501CCPAEA - Concrete, Pavement HES w/Air, Acceptance Action 0501CCPAEA is insufficient. Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 6131010, Project Item Line Number 0100, Material Set 613101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient. Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0420, Material Set 703460096, Material 1039ERRAS - Epoxy Bonding Agent-Resin Anchor Systems,
0100, Material Set 613101096, Material 0501CCPAEA - Concrete, Pavement HES w/Air, Acceptance Action 0501CCPAEA is insufficient. Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 6131010, Project Item Line Number 0100, Material Set 613101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient. Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0420, Material Set 703460096, Material 1039ERRAS - Epoxy Bonding Agent-Resin Anchor Systems,
0100, Material Set 613101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient. Estimate Exception Type: Insufficient Materials: Project J913553, Item 7034600, Project Item Line Number 0420, Material Set 703460096, Material 1039ERRAS - Epoxy Bonding Agent-Resin Anchor Systems,
0420, Material Set 703460096, Material 1039ERRAS - Epoxy Bonding Agent-Resin Anchor Systems,
Estimate Exception Type: Insufficient Materials: Project J913553, Item 7034600, Project Item Line Number 0420, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.
Estimate Exception Type: Insufficient Materials: Project J913553, Item 7034600, Project Item Line Number 0420, Material Set 703460096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0420, Material Set 703460096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.
Estimate Exception Type: Insufficient Materials: Project J913553, Item 7034600, Project Item Line Number 0420, Material Set 703460096, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.
Estimate Exception Type: Insufficient Materials: Project J913553, Item 7034600, Project Item Line Number 0470, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.
Estimate Exception Type: Insufficient Materials: Project J913553, Item 7034600, Project Item Line Number 0470, Material Set 703460096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.
Estimate Exception Type: Insufficient Materials: Project J913553, Item 7034600, Project Item Line Number 0470, Material Set 703460096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.
Estimate Exception Type: Insufficient Materials: Project J913553, Item 7034600, Project Item Line Number 0470, Material Set 703460096, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0470, Material Set 703460096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0470, Material Set 703460096, Material 1039ERRAS - Epoxy Bonding Agent-Resin Anchor Systems, Acceptance Action Generic 1039ERRAS is insufficient.
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0520, Material Set 703460096, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.
Estimate Exception Type: Insufficient Materials: Project J913553, Item 7034600, Project Item Line Number 0520, Material Set 703460096, Material 1039ERRAS - Epoxy Bonding Agent-Resin Anchor Systems, Acceptance Action Generic 1039ERRAS is insufficient.
Estimate Exception Type: Insufficient Materials: Project J913553, Item 7034600, Project Item Line Number 0520, Material Set 703460096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0520, Material Set 703460096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO,

Revision 4/1/2020 Page 5 of 70



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) Time Estimate Ferrou			
Exceptions / Discrepencies	Explanation	Entered By	Status
Acceptance Action Generic 100510CPCMLD is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0520, Material Set 703460096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0520, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913553, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 1039ERRAS - Epoxy Bonding Agent-Resin Anchor Systems, Acceptance Action Generic 1039ERRAS is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913553, Item 7040104, Project Item Line Number 0430, Material Set 704010496, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7040104, Project Item Line Number 0430, Material Set 704010496, Material 0500XX - Concrete Plant Inspection Review, Acceptance Action Generic 0500XX is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7040104, Project Item Line Number 0430, Material Set 704010496, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7040104, Project Item Line Number 0480, Material Set 704010496, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7040104, Project Item Line Number 0480, Material Set 704010496, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7040104, Project Item Line Number 0480, Material Set 704010496, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7040104, Project Item Line Number 0480, Material Set 704010496, Material 0500XX - Concrete Plant Inspection Review, Acceptance Action Generic 0500XX is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7040104, Project Item Line Number 0530, Material Set 704010496, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden

Revision 4/1/2020 Page 6 of 70



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200117-H07	J9I3553	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.26	\$36,000.00	\$9,504.00
		0001	0020	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	6,032.50	0.00	6,032.50	TONS	1,642.00	\$32.62	\$53,562.04
		0001	0030	3105002	GRAVEL (A) OR CRUSHED STONE (B)	17.00	0.00	17.00	TONS	0.00	\$18.91	\$0.00
		0001	0040	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	16,232.80	0.00	16,232.80	TONS	6,568.80	\$56.39	\$370,414.63
		0001	0050	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	62,977.90	0.00	62,977.90	TONS	25,585.90	\$57.84	\$1,479,888.46
		0001	0060	4071005	TACK COAT	60,125.00	0.00	60,125.00	GAL	22,653.00	\$2.14	\$48,477.42
		0001	0070	4134000	BITUMINOUS FOG SEAL	5,508.00	0.00	5,508.00	GAL	0.00	\$5.11	\$0.00
		0001	0080	6083003	3 IN. CONCRETE MEDIAN STRIP	2,330.00	0.00	2,330.00	SQYD	0.00	\$67.62	\$0.00
		0001	0090	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$500.00	\$0.00
		0001	0100	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	642.70	0.00	642.70	SQYD	566.80	\$185.16	\$104,948.69
		0001	0110	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	64.00	0.00	64.00	SQYD	10.00	\$10.00	\$100.00
		0001	0120	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	64.00	0.00	64.00	SQYD	10.00	\$10.00	\$100.00
		0001	0130	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	2,204.00	0.00	2,204.00	LF	1,665.00	\$6.00	\$9,990.00
		0001	0140	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	1,180.00	0.00	1,180.00	EA	822.00	\$10.00	\$8,220.00
		0001	0150	6131017	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	10.00	0.00	10.00	EA	1.00	\$10.00	\$10.00
		0001	0160	6133020	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	13.10	0.00	13.10	TONS	0.00	\$532.33	\$0.00
		0001	0170	6133021	REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	28.00	0.00	28.00	SQYD	0.00	\$103.80	\$0.00
		0001	0180	6161005	CONSTRUCTION SIGNS	3,888.00	0.00	3,888.00	SQFT	2,948.00	\$6.50	\$19,162.00
		0001	0190	6161008	ADVANCED WARNING RAIL SYSTEM	2.00	0.00	2.00	EA	0.00	\$45.00	\$0.00
		0001	0200	6161009	FLAG ASSEMBLY	4.00	0.00	4.00	EA	0.00	\$20.00	\$0.00
		0001	0210	6161025	CHANNELIZER (TRIM LINE)	712.00	0.00	712.00	EA	385.00	\$15.00	\$5,775.00
		0001	0220	6161030	TYPE III MOVEABLE BARRICADE	45.00	0.00	45.00	EA	0.00	\$100.00	\$0.00
		0001	0230	6161033	DIRECTIONAL INDICATOR BARRICADE	133.00	0.00	133.00	EA	76.00	\$35.00	\$2,660.00
		0001	0240	6161040	FLASHING ARROW PANEL	8.00	0.00	8.00	EA	4.00	\$400.00	\$1,600.00
		0001	0250	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$3,500.00	\$7,000.00
		0001	0260	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$208,790.05	\$208,790.05
		0001	0270	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	205,637.00	0.00	205,637.00	LF	0.00	\$0.23	\$0.00
		0001	0280	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	161,998.00	0.00	161,998.00	LF	0.00	\$0.23	\$0.00
		0001	0290	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	2,400.00	0.00	2,400.00	LF	0.00	\$1.00	\$0.00
		0001	0300	6209901	MISC.TEMPORARY PAVEMENT MARKING PAINT	1.00	0.00	1.00	LS	1.00	\$15,000.00	\$15,000.00
		0001	0310	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	18,810.00	0.00	18,810.00	SQYD	6,462.60	\$6.49	\$41,942.27
		0001	0320	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	22,495.00	0.00	22,495.00	SQYD	13,068.00	\$7.25	\$94,743.00
		0001	0330	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	3,038.00	0.00	3,038.00	STA	1,162.00	\$18.75	\$21,787.50
		0001	0340	7034001	CLASS B-1 CONCRETE	3.30	0.00	3.30	CUYD	0.00	\$2,400.00	\$0.00
		0010	0350	6061060	MGS GUARDRAIL	8,050.00	0.00	8,050.00	LF	7,675.00	\$20.00	\$153,500.00
		0010	0360	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	24.00	0.00	24.00	EA	20.00	\$2,900.00	\$58,000.00
		0010	0370	6061080	MGS END ANCHOR	6.00	0.00	6.00	EA	6.00	\$1,000.00	\$6,000.00
		0010	0380	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	30.00	0.00	30.00	EA	27.00	\$2,700.00	\$72,900.00
		0040	0390	9031220	PIPE POSTS	820.00	0.00	820.00	LB	0.00	\$6.00	\$0.00
		0070	0400	4091048	EMULSIFIED ASPHALT, SEAL COAT	106.00	0.00	106.00	GAL	106.00	\$5.00	\$530.00
		0070	0410	4094011	SEAL COAT AGGREGATE, GRADE B1	265.00	0.00	265.00	SQYD	265.00	\$5.00	\$1,325.00
		0070	0420	7034600	CURB BLOCKOUT	170.00	0.00	170.00	LF	170.00	\$196.14	\$33,343.80
		0070	0430	7040104	HALF-SOLE REPAIR	240.00	515.00	755.00	SQFT	755.00	\$97.74	\$73,793.70
		0070	0440	7040113	CLEANING AND EPOXY COATING	584.00	0.00	584.00	SQFT	584.00	\$13.00	\$7,592.00

Page 7 of 70 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200117-H07	J9I3553	0071	0450	4091048	EMULSIFIED ASPHALT, SEAL COAT	115.00	0.00	115.00	GAL	115.00	\$5.00	\$575.00
		0071	0460	4094011	SEAL COAT AGGREGATE, GRADE B1	288.00	0.00	288.00	SQYD	288.00	\$5.00	\$1,440.00
		0071	0470	7034600	CURB BLOCKOUT	185.00	0.00	185.00	LF	185.00	\$193.61	\$35,817.85
		0071	0480	7040104	HALF-SOLE REPAIR	260.00	463.00	723.00	SQFT	723.00	\$96.76	\$69,957.48
		0071	0490	7040113	CLEANING AND EPOXY COATING	628.00	0.00	628.00	SQFT	628.00	\$13.00	\$8,164.00
		0072	0500	4091048	EMULSIFIED ASPHALT, SEAL COAT	106.00	0.00	106.00	GAL	106.00	\$5.00	\$530.00
		0072	0510	4094011	SEAL COAT AGGREGATE, GRADE B1	265.00	0.00	265.00	SQYD	265.00	\$5.00	\$1,325.00
		0072	0520	7034600	CURB BLOCKOUT	170.00	0.00	170.00	LF	170.00	\$196.14	\$33,343.80
		0072	0530	7040104	HALF-SOLE REPAIR	240.00	613.00	853.00	SQFT	853.00	\$97.74	\$83,372.22
		0072	0540	7040113	CLEANING AND EPOXY COATING	584.00	0.00	584.00	SQFT	0.00	\$13.00	\$0.00
		0073	0550	4091048	EMULSIFIED ASPHALT, SEAL COAT	96.00	0.00	96.00	GAL	96.00	\$5.00	\$480.00
		0073	0560	4094011	SEAL COAT AGGREGATE, GRADE B1	241.00	0.00	241.00	SQYD	241.00	\$5.00	\$1,205.00
		0073	0570	7034600	CURB BLOCKOUT	155.00	0.00	155.00	LF	155.00	\$199.15	\$30,868.25
		0073	0580	7040104	HALF-SOLE REPAIR	220.00	545.00	765.00	SQFT	765.00	\$98.90	\$75,658.50
		0073	0590	7040113	CLEANING AND EPOXY COATING	534.00	0.00	534.00	SQFT	0.00	\$13.00	\$0.00
		0074	0600	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	56.00	0.00	56.00	LF	0.00	\$325.00	\$0.00
		0074	0610	2169903	MISC.Remove and Replace Curb	16.00	0.00	16.00	LF	0.00	\$300.00	\$0.00
		0074	0620	4091048	EMULSIFIED ASPHALT, SEAL COAT	348.00	0.00	348.00	GAL	0.00	\$5.00	\$0.00
		0074	0630	4094011	SEAL COAT AGGREGATE, GRADE B1	870.00	0.00	870.00	SQYD	0.00	\$5.00	\$0.00
		0074	0640	7034214	CLASS B-2 CONCRETE	5.60	0.00	5.60	CUYD	0.00	\$5,218.44	\$0.00
		0074	0650	7034600	CURB BLOCKOUT	560.00	0.00	560.00	LF	0.00	\$181.01	\$0.00
		0074	0660	7040104	HALF-SOLE REPAIR	230.00	0.00	230.00	SQFT	0.00	\$98.30	\$0.00
		0074	0670	7040113	CLEANING AND EPOXY COATING	1,971.00	0.00	1,971.00	SQFT	0.00	\$13.00	\$0.00
		0074	0680	7101000	REINFORCING STEEL (EPOXY COATED)	1,820.00	0.00	1,820.00	LB	0.00	\$5.00	\$0.00
		0074	0690	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$5,000.00	\$0.00
		0074	0700	7174001	PREFORMED SILICONE OR EPDM EXPANSION JOINT SYSTEM	56.00	0.00	56.00	LF	0.00	\$75.00	\$0.00
		0075	0710	4091048	EMULSIFIED ASPHALT, SEAL COAT	162.00	0.00	162.00	GAL	0.00	\$5.00	\$0.00
		0075	0720	4094011	SEAL COAT AGGREGATE, GRADE B1	406.00	0.00	406.00	SQYD	0.00	\$5.00	\$0.00
		0075	0730	7034600	CURB BLOCKOUT	261.00	0.00	261.00	LF	0.00	\$189.97	\$0.00
		0075	0740	7040104	HALF-SOLE REPAIR	370.00	0.00	370.00	SQFT	0.00	\$98.22	\$0.00
		0075	0750	7040113	CLEANING AND EPOXY COATING	1,100.00	0.00	1,100.00	SQFT	0.00	\$13.00	\$0.00
		0076	0760	4091048	EMULSIFIED ASPHALT, SEAL COAT	185.00	0.00	185.00	GAL	0.00	\$5.00	\$0.00
		0076	0770	4094011	SEAL COAT AGGREGATE, GRADE B1	463.00	0.00	463.00	SQYD	0.00	\$5.00	\$0.00
		0076	0780	7040104	HALF-SOLE REPAIR	400.00	1,872.00	2,272.00	SQFT	2,272.00	\$107.41	\$244,035.52
		0076	0790	7040113	CLEANING AND EPOXY COATING	989.00	0.00	989.00	SQFT	0.00	\$13.00	\$0.00
		0077	0800	4091048	EMULSIFIED ASPHALT, SEAL COAT	185.00	0.00	185.00	GAL	0.00	\$5.00	\$0.00
		0077	0810	4094011	SEAL COAT AGGREGATE, GRADE B1	463.00	0.00	463.00	SQYD	0.00	\$5.00	\$0.00
		0077	0820	7040104	HALF-SOLE REPAIR	400.00	2,564.00	2,964.00	SQFT	2,964.00	\$107.41	\$318,363.24
		0077	0830	7040113	CLEANING AND EPOXY COATING	989.00	0.00	989.00	SQFT	0.00	\$13.00	\$0.00
		0001	5001	6162004	TEMPORARY SHORT-TERM RUMBLE STRIPS	0.00	4.00	4.00	EA	4.00	\$2,362.50	\$9,450.00
		0001	5002	6161010	RELOCATED SIGNS	0.00	804.00	804.00	SQFT	804.00	\$6.83	\$5,491.32
		0001	5003	6129902	MISC.TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)		24,666.75	24,666.75	EA	24,666.75	\$1.00	\$24,666.75
		0076	5004	7040107	SLAB EDGE REPAIR (BRIDGES)	0.00	22.00	22.00	LF	22.00	\$245.39	\$5,398.58
		0077	5005	7040107	SLAB EDGE REPAIR (BRIDGES)	0.00	31.00	31.00	LF	31.00	\$245.39	\$7,607.09
		0001	5006	6189901	MISC.Additional Mobilization-Rumble Strip	0.00	1.00	1.00	LS	1.00	\$3,000.00	\$3,000.00
	Project J	9135 <u>53 - To</u>	al Val <u>ue</u>	Posted to Da	ate as of Report Generated Date							\$3,871,409.16

Revision 4/1/2020 Page 8 of 70



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200117-H07	J9S3571	0001	0840	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$2,600.00	\$2,600.00
		0001	0850	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	2,161.00	0.00	2,161.00	TONS	1,817.86	\$35.59	\$64,697.64
		0001	0860	3105002	GRAVEL (A) OR CRUSHED STONE (B)	350.00	0.00	350.00	TONS	0.00	\$44.12	\$0.00
		0001	0870	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	3,194.60	325.50	3,520.10	TONS	3,520.10	\$56.26	\$198,040.83
		0001	0880	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	17,210.20	86.00	17,296.20	TONS	17,255.60	\$60.51	\$1,044,136.36
		0001	0890	4071005	TACK COAT	14,965.00	0.00	14,965.00	GAL	12,730.00	\$2.14	\$27,242.20
		0001	0900	4134000	BITUMINOUS FOG SEAL	2,033.00	3,767.00	5,800.00	GAL	4,800.00	\$4.15	\$19,920.00
		0001	0910	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	4.00	0.00	4.00	EA	4.00	\$250.00	\$1,000.00
		0001	0920	6161005	CONSTRUCTION SIGNS	2,364.00	0.00	2,364.00	SQFT	2,364.00	\$6.50	\$15,366.00
		0001	0930	6161009	FLAG ASSEMBLY	7.00	0.00	7.00	EA	7.00	\$20.00	\$140.00
		0001	0940	6161025	CHANNELIZER (TRIM LINE)	186.00	0.00	186.00	EA	40.00	\$15.00	\$600.00
		0001	0950	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$3,500.00	\$7,000.00
		0001	0960	6162000A	WORK ZONE TRAFFIC SIGNAL SYSTEM	1.00	0.00	1.00	EA	1.00	\$8,400.00	\$8,400.00
		0001	0970	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	2.00	0.00	2.00	EA	2.00	\$1,800.00	\$3,600.00
		0001	0980	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$107,079.93	\$107,079.93
		0001	0990	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	1,212.00	0.00	1,212.00	LF	1,212.00	\$2.00	\$2,424.00
		0001	1000	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	2,000.00	0.00	2,000.00	LF	2,000.00	\$2.00	\$4,000.00
		0001	1010	6205309	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	24.00	0.00	24.00	LF	24.00	\$10.00	\$240.00
		0001	1020	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	114,312.00	0.00	114,312.00	LF	114,312.00	\$0.11	\$12,574.32
		0001	1030	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	31,999.00	0.00	31,999.00	LF	31,999.00	\$0.11	\$3,519.89
		0001	1040	6207001	PAVEMENT MARKING REMOVAL	4,006.00	0.00	4,006.00	LF	4,006.00	\$2.00	\$8,012.00
		0001	1050	6209901	MISC.TEMPORARY PAVEMENT MARKING PAINT	1.00	0.00	1.00	LS	0.00	\$0.00	\$0.00
		0001	1060	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	266.00	0.00	266.00	SQYD	266.00	\$8.76	\$2,330.16
		0001	1070	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	3,431.00	0.00	3,431.00	SQYD	3,431.00	\$9.00	\$30,879.00
		0010	1080	6061060	MGS GUARDRAIL	140.00	0.00	140.00	LF	140.00	\$22.00	\$3,080.00
		0010	1090	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	4.00	0.00	4.00	EA	4.00	\$3,000.00	\$12,000.00
		0010	1100	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	4.00	0.00	4.00	EA	4.00	\$2,900.00	\$11,600.00
		0070	1110	2169902	MISC.Removal of Existing End Post	4.00	0.00	4.00	EA	4.00	\$1,250.00	\$5,000.00
		0070	1120	2169903	MISC.Removal of Existing Curb and Guardrail	166.00	0.00	166.00	LF	166.00	\$125.00	\$20,750.00
		0070	1130	4091048	EMULSIFIED ASPHALT, SEAL COAT	115.00	0.00	115.00	GAL	115.00	\$5.00	\$575.00
		0070	1140	4094011	SEAL COAT AGGREGATE, GRADE B1	287.00	0.00	287.00	SQYD	287.00	\$5.00	\$1,435.00
		0070	1150	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	20.00	11.00	31.00	SQFT	31.00	\$311.16	\$9,645.96
		0070	1160	7040107	SLAB EDGE REPAIR (BRIDGES)	60.00	2.00	62.00	LF	62.00	\$245.39	\$15,214.18
		0070	1170	7040113	CLEANING AND EPOXY COATING	308.00	0.00	308.00	SQFT	308.00	\$13.00	\$4,004.00
		0070	1180	7134000	BRIDGE GUARDRAIL (THRIE BEAM)	178.00	0.00	178.00	LF	178.00	\$286.43	\$50,984.54
		0070	5100	7040104	HALF-SOLE REPAIR	0.00	360.00	360.00	SQFT	360.00	\$112.78	\$40,600.80
		0070	5110	7040106	FULL DEPTH REPAIR	0.00	50.00	50.00	SQFT	50.00	\$157.50	\$7,875.00
		0070	5120	7049902	MISC.FORCE ACCOUNT(bolting deck and steel plates)	0.00	2,331.40	2,331.40	EA	2,331.40	\$1.00	\$2,331.40
	Project J	9S3571 - To	otal Value	Posted to D	Date as of Report Generated Date							\$1,748,898.20
200117-H07 Ove	erall - Total	Value Pos	ted to Da	te as of Repo	ort Generated Date							\$5,620,307.36

Page 9 of 70 Revision 4/1/2020



The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work,

Project: 1913553

Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0310	6221001	COLDMILLING BIT. PAVT FOR REM OF SURF.	3/8/21	3/15/21	202.00	SQYD	Bridge L0953 Passing Lane	33.956		33.956		Plan width incorrect, actual width 28'-0" +/- 130 LF x 14 LF = 1820 SF / 9 = 202.2 SY, Pay = 202.0 SY
				3/15/21	436.00	SQYD	Bridge L0927 Passing Lane	35.679		35.679		Plan width incorrect, actual width 28'-0" +/- 280 LF x 14 LF = 3920 SF / 9 = 435.6 SY, Pay = 436.0 SY
0320	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	3/8/21	3/15/21	622.00	SQYD	Bridge L0927 Passing Lane	35.679		35.679		2(175 LF) x 16 LF = 5600.00 SF / 9 = 622.22 SY, Pay 622.00 SY
				3/15/21	622.00	SQYD	Bridge L0953 Passing Lane	33.956		33.956		2(175 LF) x 16 LF = 5600.00 SF / 9 = 622.22 SY, Pay 622.00 SY
0350	6061060	MGS GUARDRAIL	3/1/21	3/3/21	212.50	LF	Bridge A5086 Driving Lane	27.334		27.334		
				3/3/21	237.50		Bridge A0237 Driving Lane	28.038		28.038		
			3/2/21	3/3/21	287.50	LF	Bridge A5086 Passing Lane	27.334		27.334		
				3/3/21	337.50	LF	Bridge A5086 Passing Lane	28.038		28.038		
			3/3/21	3/8/21	312.50		Bridge L0955 Passing Lane	31.168		31.168		
				3/8/21	312.50	LF	Bridge L0956 Passing Lane	29.461		29.461		
			3/4/21	3/8/21	212.50	LF	Bridge L0955 Driving Lane	31.168		31.168		
				3/8/21	212.50	LF	Driving Lane	29.461		29.461		
			3/8/21	3/15/21	175.00	LF	Additional Work In the driving lane on the east side of bridge for Rte 25.	47.47		47.47		
			3/9/21	3/15/21	625.00	LF	Bridge A0030 Driving Lane Off End This is additional work.	46.58		46.58		
				3/15/21	400.00		West of Rte F. This is additional work	53.449		53.449		
0360	6061069	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	3/1/21	3/3/21	1.00	EA	Driving Lane	28.038		28.038		
				3/3/21	1.00		Bridge A5086 Driving Lane	27.334		27.334		
			3/2/21		1.00		Bridge A0237 Passing Lane	27.334		27.334		
				3/3/21	1.00	EA	Bridge A0237 Passing Lane	28.038		28.038		
			3/3/21	3/8/21	1.00	EA	Bridge L0955 Passing Lane	31.168		31.168		
				3/8/21	1.00		Bridge L0956 Passing Lane	29.461		29.461		
			3/4/21		1.00		Bridge L0955 Driving Lane	31.168		31.168		
				3/8/21	1.00	EA	Bridge L0956 Driving Lane	29.461		29.461		
			3/8/21	3/15/21	1.00	EA	Additional Work In the driving lane on the east side of bridge for Rte 25.	47.47		47.47		
			3/9/21	3/15/21	1.00	EA	Bridge A0030 Driving Lane Off End This is additional work.	46.58		46.58		
0370	6061080	MGS END ANCHOR	3/9/21	3/15/21	1.00	EA	Bridge A0030 Driving Lane Off End This is additional work.	46.58		46.58		
			3/10/21	3/15/21	1.00	EA	West of Rte 25 On-Ramp. This is additional work.	48.472		48.472		
			3/11/21		1.00		West of Rte F. This is additional work This payment entry addresses overpayment for line item	53.449		53.449		This payment entry addresses overpayment for line ite
			3/13/21	3/10/21	-3.00	EA	0370. The current overages will be paid via upcoming change	27.334		53.962		0370. The current overages will be paid via upcoming chang
0380	6063014	TYPE A CRSHWTHY END TERMINAL (MASH)	3/1/21	3/3/21	1.00	EA	order. Bridge A0237	28.038		28.038		order.
				3/3/21	1.00	EA	Bridge A5086 Driving Lane	27.334		27.334		
			3/2/21	3/3/21	1.00	EA	Bridge A0237 Passing Lane	28.038		28.038		
				3/3/21	1.00	EA	Bridge A5086 Passing Lane	27.334		27.334		
			3/3/21	3/8/21	1.00	EA	Bridge L0955 Passing Lane	31.168		31.168		
				3/8/21	1.00	EA	Bridge L0956 Passing Lane	29.461		29.461		
			3/4/21	3/8/21	1.00	EA	Bridge L0955 Driving Lane	31.168		31.168		
				3/8/21	1.00	EA	Bridge L0956 Driving Lane	29.461		29.461		
			3/8/21	3/15/21	1.00	EA	Additional Work In the driving lane on the east side of bridge for Rte 25.	47.47		47.47		
				3/15/21	1.00		West of Rte 25 On-Ramp. This is additional work.	47.847		47.847		

The information below this line are details for Construction Signs (if applicable).

Project	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
J913553	0180	April 14, 2020	377	WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		40.91	Left/Right	2.00	16			32
				CONST-3A 60x48 20.00 FINE SIGN		41.099	Left/Right	2.00	20			40
				GO20-2 48x24 8.00 END ROAD WORK		45.40	Left/Right	2.00	8			16
				R2-1 36x48 12.00 SPEED LIMIT XX		45.20	Left/Right	2.00	12			24
				R4-2 36x48 12.00 PASS WITH CARE		45.00	Left/Right	2.00	12			24

Revision 4/1/2020 Page 10 of 70



The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work. The information below this line are details for Construction Signs (if applicable).

		details for Construction Signature	- 1								
ect Line Numbe	DWR Date	Total Quantity Posted For DWF Date	R Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF t Post
53 0180	April 14, 2020	377	G020-5aP 36x24 6.00 WORK ZONE		45.00	Left/Right	2.00	6			
			(PLAQUE) WO8-15 48x48 16.00 GROOVED		44.044	Left/Right	2.00	16			
			PAVEMENT WO8-15p 30x24 5.00		44.044	Left/Right	2.00	5			
			MOTORCYCLE (PLAQUE) WO8-15 48x48 16.00 GROOVED		42.268	Left/Right	2.00	16			
			PAVEMENT WO8-15p 30x24 5.00		42.268	Left/Right	2.00	5			
			MOTORCYCLE (PLAQUE) R2-1 36x48 12.00 SPEED LIMIT		41.90	Left/Right	2.00	12			
			xx								
			CONST-3X 56x12 4.67 SPEEDING/PASSING (PLATE)		41.099	Left/Right	2.00	4.67			Ş
			G020-5aP 36x24 6.00 WORK ZONE (PLAQUE)		41.29	Left/Right	2.00	6			
			R4-1 36x48 12.00 DO NOT PASS WO20-5 48x48 16.00		41.29	Left/Right Left/Right	2.00	12			
			RIGHT/CENTER/LEFT LANE CLOSED AHEAD			Lowers	2.00	10			
			WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		41.76	Left	1.00	16			
			WO4-1aR 48x48 16.00 MERGE (SYMBOL FROM RIGHT)		41.76	Right	1.00	16			
			G020-5aP 36x24 6.00 WORK ZONE (PLAQUE)		41.90	Left/Right	2.00	6			
	April 20, 2020	217	CONST-3A 60x48 20.00 FINE SIGN		42.87	Westbound Rte 60 LT/RT	2.00	20			
			WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		42.68	Westbound Rte 60 LT/RT	2.00	16			
			G020-5aP 36x24 6.00 WORK ZONE (PLAQUE)		43.68	Westbound Rte 60 LT/RT	2.00	6			
			WO4-1aR 48x48 16.00 MERGE (SYMBOL FROM RIGHT)		43.54	Westbound Rte 60 LT	1.00	16			
			R2-1 36x48 12.00 SPEED LIMIT XX		43.68	Westbound Rte 60 LT/RT	2.00	12			
			WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD		43.25	Westbound Rte 60 LT/RT	2.00	16			
			R4-1 36x48 12.00 DO NOT PASS		43.06	Westbound Rte 60 LT/RT	2.00	12			
			G020-5aP 36x24 6.00 WORK ZONE (PLAQUE) CONST-3X 56x12 4.67		43.06	Westbound Rte 60 LT/RT Westbound Rte 60 LT/RT	2.00	4.67			
			SPEEDING/PASSING (PLATE) WO20-6a 48x48 16.00		43.54	Westbound Rte 60 RT	1.00	16			
	M 40, 2020	12	RIGHT/CENTER/LEFT LANE CLOSED R3-7L 30x30 6.25 LEFT LANE		43.044	RT and LT	2.00	6.25			
	May 18, 2020		MUST TURN LEFT								
	June 24, 2020	377	R4-1 36x48 12.00 DO NOT PASS G020-5aP 36x24 6.00 WORK ZONE		37.263 37.263	RT/LT RT/LT	2.00	12		12.00	
			(PLAQUE) CONST-3A 60x48 20.00 FINE SIGN		37.059	RT/LT	2.00	20		20.00	
			WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		36.853	RT/LT	2.00	16		16.00	
			GO20-2 48x24 8.00 END ROAD WORK		39.66	RT/LT	2.00	8		8.00	
			R2-1 36x48 12.00 SPEED LIMIT		39.47	RT/LT	2.00	12		12.00	
			XX G020-5aP 36x24 6.00 WORK ZONE		39.284	RT/LT	2.00	6		6.00	
			(PLAQUE) R4-2 36x48 12.00 PASS WITH		39.284	RT/LT	2.00	12		12.00	
			CARE WO8-15p 30x24 5.00		37.941	RT/LT	4.00	5	Bridges L0923 and	5.00	
			MOTORCYCLE (PLAQUE) WO8-15 48x48 16.00 GROOVED		37.941	RT/LT	4.00	16	L0924 Bridges L0923 and	16.00	
			PAVEMENT G020-5aP 36x24 6.00 WORK ZONE		37.899	RT/LT	2.00	6	L0924	6.00	
			(PLAQUE) R2-1 36x48 12.00 SPEED LIMIT		37.899	RT/LT	2.00	12		12.00	
			XX WO4-1aR 48x48 16.00 MERGE		37.695	LT	1.00	16		16.00	
			(SYMBOL FROM RIGHT)								
			WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		37.695	RT	1.00	16		16.00	
			WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD		37.473	RT/LT	2.00	16		16.00	
			CONST-3X 56x12 4.67 SPEEDING/PASSING (PLATE)		37.059	RT/LT	2.00	4.67		4.67	
	June 25, 2020	0	WO3-2 48x48 16.00 YIELD AHEAD (SYMBOL)			I-55 To Route 60 Ramp	1.00	16		16.00	
			R1-2 48 TRI 6.93 YIELD WO4-1R 48x48 16.00 MERGE		24.548 24.567	I-55 To Route 60 Ramp Exit 66B Ramp	1 1.00	6.93		6.93	
			(SYMBOL FROM RIGHT)								
			R4-2 36x48 12.00 PASS WITH CARE		25.358	Route 60 End Of Work Zone	2.00	12		12.00	
			EO5-1 36x48 12.00 GORE EXIT R1-2 48 TRI 6.93 YIELD		24.407	Exit 66B Ramp Exit 66B Ramp	1.00	12 6.93		12.00	
			R2-1 36x48 12.00 SPEED LIMIT XX		24.198	Exit 66B Ramp	1.00	12		12.00	
			WO3-2 48x48 16.00 YIELD AHEAD (SYMBOL)	24.205	24.025	Exit 66B Ramp	1.00	16		16.00	
			WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD	1.4	1.4	1-57	2.00	16		16.00	
			CONST-3X 56x12 4.67	1.2	1.2	1-57	2.00	4.67		4.67	
			SPEEDING/PASSING (PLATE)								

Revision 4/1/2020 Page 11 of 70



The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work. The information below this line are details for Construction Signs (if applicable).

	mation be		details for Construction Signs									
oject	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
3553	0180	June 25, 2020	0	R4-1 36x48 12.00 DO NOT PASS	1.0	1.0	I-57	2.00	12		12.00	24
				WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD	0.8	0.8	1-57	2.00	16		16.00	3:
				WO4-1aL 48x48 16.00 MERGE	0.6	0.6	I-57	1.00	16		16.00	1
				(SYMBOL FROM LEFT) WO20-6a 48x48 16.00	0.6	0.6	1-57	1.00	16		16.00	16
				RIGHT/CENTER/LEFT LANE CLOSED								
				R2-1 36x48 12.00 SPEED LIMIT XX	0.2	0.2	1-57	2.00	12		12.00	24
				WO5-1 48x48 16.00 ROAD/BRIDGE/RAMP NARROWS	0.2	0.2	I-55 To Route 60 Ramp	1.00	16		16.00	16
				R2-1 36x48 12.00 SPEED LIMIT XX	25.557	25.557	Route 60 End Of Work Zone	2.00	12		12.00	24
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD	0.2	0.2	I-55 To Route 60 Ramp	1.00	16		16.00	10
				WO20-1 48x48 16.00	0.2	0.2	Exit 66B Ramp	1.00	16		16.00	10
				WO5-1 48x48 16.00	0.2	0.2	Exit 66B Ramp	1.00	16		16.00	1
		June 30, 2020	0	ROAD/BRIDGE/RAMP NARROWS R2-1 36x48 12:00 SPEED LIMIT	33.5	33.5	Route 60	2.00	12		12.00	2.
		0410 00, 2020		XX								
				WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED	33.70	33.70	Route 60	1.00	16		16.00	1
				WO4-1aL 48x48 16.00 MERGE (SYMBOL FROM LEFT)	33.70	33.70	Route 60	1.00	16		16.00	1
				WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED	33.89	33.89	Route 60	2.00	16		16.00	3.
				AHEAD	04.40	04.40	D 4 00	0.00	40		40.00	
				R4-1 36x48 12.00 DO NOT PASS CONST-3A 60x48 20.00 FINE SIGN	34.19	34.19 34.49	Route 60 Route 60	2.00	12		12.00	2
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD	34.79	34.79	Route 60	2.00	16		16.00	3
				R4-2 36x48 12.00 PASS WITH	35.2	35.2	Route 60	2.00	12		12.00	2-
				R2-1 36x48 12.00 SPEED LIMIT	35.5	35.5	Route 60	2.00	12		12.00	2-
		September 8, 2020	84	XX WO8-15p 30x24 5.00			Bridge L0956	2.00	5			1
		September 6, 2020	64	MOTORCYCLE (PLAQUE)		29.461						
				WO8-15 48x48 16.00 GROOVED PAVEMENT		31.168	Bridge L0955	2.00	16			3.
				WO8-15p 30x24 5.00 MOTORCYCLE (PLAQUE)		31.168	Bridge L0955	2.00	5			1
				WO8-15 48x48 16.00 GROOVED PAVEMENT		29.461	Bridge L0956	2.00	16			3.
		September 23,	222	WO8-1 48x48 16.00 BUMP		45.896	East of Bridge B0548	2.00	16			3:
		2020		WO8-15 48x48 16.00 GROOVED PAVEMENT		45.896	East of Bridge B0548	2.00	16			3
				WO8-15p 30x24 5.00 MOTORCYCLE (PLAQUE)		46.507	East of A0030	2.00	5			1
				WO8-1 48x48 16.00 BUMP		46.507	East of Bridge A0030	2.00	16			3
				WO8-15 48x48 16.00 GROOVED PAVEMENT		46.507	East of A0030	2.00	16			3
				WO8-15p 30x24 5.00 MOTORCYCLE (PLAQUE)		45.896	East of Bridge B0548	2.00	5			1
				See Special Sign Details				0.00				
				WO8-1 48x48 16.00 BUMP		43.085	West of Rte FF (Stoddard)	2.00	16			3
				WO8-15p 30x24 5.00 MOTORCYCLE (PLAQUE)		43.085	West of Rte FF (Stoddard)	2.00	5			1
				WO8-15 48x48 16.00 GROOVED PAVEMENT		43.085	West of Rte FF (Stoddard)	2.00	16			3
		October 2, 2020	303	WO8-15 48x48 16.00 GROOVED PAVEMENT		43.042	Route 60	1.00	16			1
				WO8-1 48x48 16.00 BUMP		43.042	Route 60	1.00	16			1
				WO8-11 48x48 16.00 UNEVEN LANES		46.179	Route 60	2.00	16			3
				WO8-17 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		45.138	Route 60	2.00	16			3
				WO8-17p 30x24 5.00 SHOULDER		45.138	Route 60	2.00	5			1
				DROP-OFF (PLAQUE)		45.041	Route 60 Side Road	2.00	16			3
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD								
				WO8-11 48x48 16.00 UNEVEN LANES		44.129	Route 60	2.00	16			3
				WO8-17 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		43.084	Route 60	2.00	16			3
				WO8-11 48x48 16.00 UNEVEN LANES		43.061	Route 60	2.00	16			3
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		43.042	Route 60	2.00	16			3
				WO8-15p 30x24 5.00		43.042	Route 60	1.00	5			
				MOTORCYCLE (PLAQUE) See Special Sign Details		1	A					
		October 5, 2020	80	WO8-11 48x48 16.00 UNEVEN LANES		46.171	Westbound Driving Lane	2.00	16			3
				WO8-11 48x48 16.00 UNEVEN		48.184	Westbound Driving Lane	2.00	16			
								1.00	16			
				WO8-1 48x48 16.00 BUMP		48.472	Westbound Driving Lane	1.00	10			
		October 9, 2020	115			48.472 49.089	Westbound Driving Lane Route 60	1.00	6.93			
		October 9, 2020	115	WO8-1 48x48 16.00 BUMP								6.9
		October 9, 2020	115	WO8-1 48x48 16.00 BUMP R1-2 48 TRI 6.93 YIELD WO3-2 48x48 16.00 YIELD AHEAD		49.089	Route 60	1.00	6.93			1) 6.9 1)

Revision 4/1/2020 Page 12 of 70



The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work. The information below this line are details for Construction Signs (if applicable).

oject	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
3553	0180	October 9, 2020	115	LANES								
				WO8-17 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		49.289	Route 60	1.00	16			
				WO8-11 48x48 16.00 UNEVEN LANES		50.241	Route 60	2.00	16			
				EO5-1 36x48 12.00 GORE EXIT		48.755	Route 60	1.00	12			
		October 13, 2020	524	WO8-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)		45.137		2.00	5			
				WO8-17 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		43.097		2.00	16			
				WO8-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)		43.097		2.00	5			
				WO8-17 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		45.137		2.00	16			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD			Rte F North/South	2.00	16			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD			Rte 60 WB near 153 intersection	2.00	16			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD			Co Rd 717 North/South	2.00	16			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD			Rte ZZ South	1.00	16			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD			Rte FF South	1.00	16			
				WO8-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)		47.151		2.00	5			
				WO8-17 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		47.151		2.00	16			
				WO8-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)		47.947		2.00	5			
				WO8-17 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		47.947		2.00	16			
				WO8-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)		49.282		2.00	5			
				WO8-17 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		49.282		2.00	16			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		49.346		2.00	16			
				WO8-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)		51.212		2.00	5			
				WO8-17 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		51.212		2.00	16			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD			Co RD 449	1.00	16			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD			Co RD 531 North	1.00	16			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD			Co Rd 731 South	1.00	16			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD			One-Mile Rd	1.00	16			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD			Rte 25 On-Ramp	1.00	16			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD			Rte AD Ramp	1.00	16			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD			Rte FF North	1.00	16			
		October 14, 2020	148	WO8-17 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		52.325		2.00	16			
				WO8-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)		52.325		2.00	5			
				WO8-11 48x48 16.00 UNEVEN LANES		52.304		2.00	16			
				WO8-11 48x48 16.00 UNEVEN LANES		50.234		2.00	16			
				WO8-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)		53.334		2.00	5			
				WO8-17 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		53.334		2.00	16			

Revision 4/1/2020 Page 13 of 70



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0020	MISC. PERMANENT AGGREGATE EDGE TREATMENT	Material	,,	15	Nov 17, 2020	SYSTEM	(\$53,562.04)	
				15	Nov 17, 2020	SYSTEM	\$53,562.04	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				16	Dec 2, 2020	SYSTEM	(\$53,562.04)	
				16	Dec 2, 2020	SYSTEM	\$53,562.04	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				17	Dec 16, 2020	SYSTEM	(\$53,562.04)	
				17	Dec 16, 2020	SYSTEM	\$53,562.04	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				18	Jan 4, 2021	SYSTEM	(\$53,562.04)	
				18	Jan 4, 2021	SYSTEM	\$53,562.04	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0020 -	- Total						\$0.00	
0040	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Other Item Adjustment	ACAD	13	Oct 16, 2020	woodsk1	(\$930.40)	*See Attached AC Price Index Adjustment Sheet.
				14	Nov 2, 2020	woodsk1	(\$10,471.20)	*See Attached AC Price Index Adjustment Sheet.
				15	Nov 17, 2020	woodsk1	(\$1,874.88)	The Combination Of Adjustments For This Line Item Are As Follows:
								Asphalt Cement Price Adjustment:
								-1874.88 For BP-1
								-332.17 For SP-125
								TSR Adjustment (For SP-125):
								Lot 1A-3B \$0.00
								Lot 3C-5D \$0.00
								Lot 6A-6F \$9,692.65
								E01 0A-01 \$5,052.00
								Pay Factor Adjustments (For SP-125):
								Lot 1 \$11,568.00
								Lot 2 \$3,701.76
								Lot 3 \$11,568.00
								Lot 4 \$11,568.00
								Lot 5 \$11,568.00
			ACAD - Tot	al			(\$13,276.48)	Lot 6 \$15,831.33
	Other Item Adjustment - Total		100				(\$13,276.48)	
0040 -	· Total						(\$13,276.48)	
0050	ASPHALTIC CONCRETE MIXTURE PG	Material		13	Oct 16,	SYSTEM		
	70-22 (SP125C MIX)			10	2020	0)/0=		
				13	Oct 16, 2020	SYSTEM	\$1,147,840.58	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.

Revision 4/1/2020 Page 14 of 70



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0050	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Material		14	Nov 2, 2020	SYSTEM	(\$1,472,195.74)	
				14	Nov 2, 2020	SYSTEM	\$1,472,195.74	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				15	Nov 17, 2020	SYSTEM	(\$1,479,888.46)	
				15	Nov 17, 2020	SYSTEM	\$1,479,888.46	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				16	Dec 2, 2020	SYSTEM	(\$91,728.46)	
				16	Dec 2, 2020	SYSTEM	\$91,728.46	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				17	Dec 16, 2020	SYSTEM	(\$91,728.46)	
				17	Dec 16, 2020	SYSTEM	\$91,728.46	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				18	Jan 4, 2021	SYSTEM	(\$91,728.46)	
				18	Jan 4, 2021	SYSTEM	\$91,728.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				19	Jan 20, 2021	SYSTEM	(\$91,728.46)	
				19	Jan 20, 2021	SYSTEM	\$91,728.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				20	Feb 1, 2021	SYSTEM	(\$91,728.46)	
				20	Feb 1, 2021	SYSTEM	\$91,728.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				21	Feb 16, 2021	SYSTEM	(\$91,728.46)	
				21	Feb 16, 2021	SYSTEM	\$91,728.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				22	Mar 2, 2021	SYSTEM	(\$91,728.46)	
				22	Mar 2, 2021	SYSTEM	\$91,728.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				23	Mar 16, 2021	SYSTEM	(\$91,728.46)	
				23	Mar 16, 2021	SYSTEM	\$91,728.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total	011 "		40	0		\$0.00	10. 40. 1. 1.0.0.
	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Other Item Adjustment	ACAD	13	Oct 16, 2020	woodsk1	(\$45,891.79)	*See Attached AC Price Index Adjustment Sheet.
				14	Nov 2, 2020	woodsk1	(\$12,968.04)	*See Attached AC Price Index Adjustment Sheet.
			ACAD - Tota	al			(\$58,859.83)	
	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)		BITM	15	Nov 17, 2020	woodsk1	\$75,165.57	The Combination Of Adjustments For This Line Item Are As Follows:

Revision 4/1/2020 Page 15 of 70



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0050		Other Item	, ,,					Asphalt Cement Price Adjustment:
		Adjustment						-1874.88 For BP-1
								-332.17 For SP-125
								TSR Adjustment (For SP-125):
								Lot 1A-3B \$0.00
								Lot 3C-5D \$0.00
								Lot 6A-6F \$9,692.65
								Pay Factor Adjustments (For SP-125):
								Lot 1 \$11,568.00
								Lot 2 \$3,701.76
								Lot 3 \$11,568.00
								Lot 4 \$11,568.00
								Lot 5 \$11,568.00
								Lot 6 \$15,831.33
			BITM - Total				\$75,165.57	
	Other Item Adjustment - Total						\$16,305.74	
0050 -							\$16,305.74	
0100	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material		6	Jul 2, 2020	SYSTEM	(\$46,901.03)	This adjustment offsets the original system was assed Organia
				0	Jul 2, 2020	STSTEM	\$46,901.03	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$69,305.39)	
				7	Jul 16, 2020	SYSTEM	\$69,305.39	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$69,305.39)	
				8	Aug 3, 2020	SYSTEM	\$69,305.39	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$69,305.39)	
				9	Aug 18, 2020	SYSTEM	\$69,305.39	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$69,305.39)	
				10	Sep 3, 2020	SYSTEM	\$69,305.39	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$84,951.41)	
				11	Sep 16, 2020	SYSTEM	\$84,951.41	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$90,709.88)	
				12	Oct 1, 2020	SYSTEM	\$90,709.88	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 6 on the current

Revision 4/1/2020 Page 16 of 70



Payment Editinate Exception 7 on the current	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
10	0100		Material						Payment Estimate.
Poyment Estimate from Agustament (2002) as one would one minimal programmer (2007) and the current February Symptoms Estimate Exception / on the current February Symptoms (2007) and the current Symptoms (2007) and to super woods (2007) and the current Symptoms (2007) and to super woods (2007) and the current Symptoms (200					13		SYSTEM	(\$90,709.88)	
14					13		SYSTEM	\$90,709.88	
200					14		SYSTEM	(\$90,709.88)	
15					14		SYSTEM	\$90,709.88	
Payment Estimate Item Adjustment (0003) due to user woods overriding Payment Estimate Exception 8 on the current Payment Estimate Exception 6 on the current Payment Estimate Exception 7 on the cur					15		SYSTEM	(\$90,709.88)	
15					15		SYSTEM	\$90,709.88	
2020 Payment Estimate Item Adjustment (0003) due to user woods overriding Payment Estimate Exception 8 on the current Payment Estimate Exception 8 on the current Payment Estimate Item Adjustment (0003) due to user woods overriding Payment Estimate Exception 6 on the current Payment Estimate Item Adjustment (0003) due to user woods overriding Payment Estimate Item Adjustment (0003) due to user woods overriding Payment Estimate Item Adjustment (0003) due to user woods overriding Payment Estimate Item Adjustment (0004) due to user woods overriding Payment Estimate Item Adjustment (0004) due to user woods overriding Payment Estimate Item Adjustment (0004) due to user woods overriding Payment Estimate Item Adjustment (0003) due to user woods overriding Payment Estimate Item Adjustment (0003) due to user woods overriding Payment Estimate Item Adjustment (0003) due to user woods overriding Payment Estimate Item Adjustment (0003) due to user woods overriding Payment Estimate Exception 7 on the current Payment Estimate Item Adjustment (0003) due to user woods overriding Payment Estimate Exception 7 on the current Payment Estimate Item Adjustment (0003) due to user woods overriding Payment Estimate Exception 7 on the current Payment Estimate Item Adjustment (0003) due to user woods overriding Payment Estimate Exception 7 on the current Payment Estimate Item Adjustment (0003) due to user woods overriding Payment Estimate Exception 7 on the current Payment Estimate Item Adjustment (0003) due to user woods overriding Payment Estimate Exception 7 on the current Payment Estimate Item Adjustment (0003) due to user woods overriding Payment Estimate Exception 7 on the current Payment Estimate Item Adjustment (0003) due to user woods overriding Payment Estimate Exception 7 on the current Payment Estimate Item Adjustment (0003) due to user woods overriding Payment Estimate Exception 7 on the current Payment Estimate Item Adjustment (0003) due to user woods overriding Payment Estimate Exception 7 on the current Payment Item Ite					16		SYSTEM	(\$90,709.88)	
17					16		SYSTEM	\$90,709.88	
Payment Estimate Item Adjustment (0003) due to user woods overridding Payment Estimate Exception 8 on the current Payment Estimate Exception 9 on the current Payment Estimate Exception 7 on the current Payment Estimate Exception 9 on the current Payment Estimate Exception 7 on the current Payment Estimate Exception 7 on the current Payment Estimate Exception 9 on the current Payment Estimate Item Adjustment (0003) due to user woods overridding Payment Estimate Exception 7 on the current Payment Estimate Item Adjustment (0003) due to user woods overridding Payment Estimate Exception 9 on the current Payment Estimate Item Adjustment (0003) due to user woods overridding Payment Estimate Item Adjustment (0003) due to user woods overridding Payment Estimate Item Adjustment (0003) due to user woods overridd					17		SYSTEM	(\$90,709.88)	
18					17		SYSTEM	\$90,709.88	
2021 Payment Estimate Item Adjustment (0004) due to user woods overridding Payment Estimate Exception 8 on the current Payment Estimate Item Adjustment (0003) due to user woods overridding Payment Estimate Exception 7 on the current Payme					18		SYSTEM	(\$90,709.88)	
2021 19 Jan 20, 2021 2					18		SYSTEM	\$90,709.88	
2021 Payment Estimate Item Adjustment (0003) due to user woods overridding Payment Estimate Exception 7 on the current Payment Estimate Exception 7 on					19		SYSTEM	(\$90,709.88)	
2021 20 Feb 1, 2021 20 Feb 1, 2021 20 Feb 16, 2021 21 Feb 16, 2021 21 Feb 16, 2021 21 Feb 16, 2021 22 Mar 2, 2021 22 Mar 2, 2021 23 Mar 16, 2021 24 Mar 16, 2021 25 Mar 16, 2021 26 Mar 16, 2021 27 Mar 16, 2021 28 Mar 16, 2021 29 Mar 16, 2021 20 Mar 16, 2021 20 Mar 16, 2021 20 Mar 16, 2021 21 Mar 16, 2021 22 Mar 16, 2021 23 Mar 16, 2021 24 Mar 16, 2021 25 Mar 16, 2021 26 Mar 2, 2021 27 Mar 16, 2021 28 Mar 16, 2021 29 Mar 2, 2021 20 Mar 2, 2021 20 Mar 3, 2021 20 Mar 4, 2021 21 Mar 4, 2021 22 Mar 5, 2021 23 Mar 6, 2021 24 Mar 6, 2021 25 Mar 6, 2021 26 Mar 6, 2021 27 Mar 7, 2007,09.88 28 Mar 16, 2021 29 Mar 16, 2021 20 Mar 16, 2021 20 Mar 16, 2021 20 Mar 16, 2021 21 Mar 16, 2021 22 Mar 16, 2021 23 Mar 16, 2021 24 Mar 16, 2021 25 Mar 16, 2021 26 Mar 16, 2021 27 Mar 16, 2021 28 Mar 16, 2021 29 Mar 16, 2021 20 Mar 16, 2021 20 Mar 16, 2021 20 Mar 16, 2021 21 Mar 16, 2021 22 Mar 16, 2021 23 Mar 16, 2021 24 Mar 16, 2021 25 Mar 16, 2021 26 Mar 16, 2021 27 Mar 16, 2021 28 Mar 16, 2021 29 Mar 16, 2021 20 Mar 16, 2021 20 Mar 16, 2021 20 Mar 16, 2021 21 Mar 16, 2021 22 Mar 16, 2021 23 Mar 16, 2021 24 Mar 16, 2021 25 Mar 16, 2021 26 Mar 16, 2021 27 Mar 16, 2021 28 Mar 16, 2021 29 Mar 16, 2021 20					19		SYSTEM	\$90,709.88	
2021 Payment Estimate Item Adjustment (0003) due to user woods overridding Payment Estimate Exception 7 on the current Payment Estimate Exception 7 on the current Payment Estimate Exception 7 on the current Payment Estimate Item Adjustment (0003) due to user woods overridding Payment Estimate Item Adjustment (0003) due to user woods overridding Payment Estimate Exception 7 on the current Payment Estimate Exception 7 on the current Payment Estimate Item Adjustment (0003) due to user woods overridding Payment Estimate Item Adjustment (0003) due to user woods overridding Payment Estimate Item Adjustment (0003) due to user woods overridding Payment Estimate Exception 7 on the current Payment Estimate Exception 7 on the current Payment Estimate Item Adjustment (0003) due to user woods overridding Payment Estimate Item Adjustment (0003) due to user woods overridding Payment Estimate Item Adjustment (0003) due to user woods overridding Payment Estimate Item Adjustment (0003) due to user woods overridding Payment Estimate Item Adjustment (0003) due to user woods overridding Payment Estimate Item Adjustment (0003) due to user woods overridding Payment Estimate Item Adjustment (0003) due to user woods overridding Payment Estimate Item Adjustment (0003) due to user woods overridding Payment Estimate Exception 7 on the current Payment Estimate Exception 7 on the current Payment Estimate Item Adjustment (0003) due to user woods overridding Payment Estimate Exception 7 on the current Payment Estimate Except					20		SYSTEM	(\$90,709.88)	
2021 21 Feb 16, 2021 22 Mar 2, 2021 22 Mar 2, 2021 23 Mar 16, 2021 24 SYSTEM \$90,709.88 This adjustment offsets the original system-generated Material Payment Estimate Estimate Exception 7 on the current Payment Estimate Item Adjustment (0003) due to user woodst overridding Payment Estimate Estimate Exception 7 on the current Payment Estimate Item Adjustment (0003) due to user woodst overridding Payment Estimate Item Adjustment (0003) due to user woodst overridding Payment Estimate Exception 7 on the current Payment Estimate Exception 7 on the current Payment Estimate Item Adjustment (0003) due to user woodst overridding Payment Estimate Exception 7 on the current Payment Estimate Item Adjustment (0003) due to user woodst overridding Payment Estimate Item Adjustment (0003) due to user woodst overridding Payment Estimate Item Adjustment (0003) due to user woodst overridding Payment Estimate Exception 7 on the current Payment Estimate					20		SYSTEM	\$90,709.88	
2021 Payment Estimate Item Adjustment (0003) due to user woodst overridding Payment Estimate Exception 7 on the current Payment Estimate Exception 7 on the current Payment Estimate Exception 7 on the current Payment Estimate Estimate Exception 7 on the current Payment Estimate Item Adjustment (0003) due to user woodst overridding Payment Estimate Exception 7 on the current Payment Estimate Exception 7 on the current Payment Estimate Exception 7 on the current Payment Estimate Item Adjustment (0003) due to user woodst overridding Payment Estimate Item Adjustment (0003) due to user woodst overridding Payment Estimate Item Adjustment (0003) due to user woodst overridding Payment Estimate Item Adjustment (0003) due to user woodst overridding Payment Estimate Exception 7 on the current Payment Estimate Item Adjustment (0003) due to user woodst overridding Payment Estimate Exception 7 on the current Payment Estimate.					21		SYSTEM	(\$90,709.88)	
2021 22 Mar 2, 2021 23 Mar 16, 2021 23 Mar 16, 2021 24 SYSTEM \$90,709.88 25 SYSTEM \$90,709.88 26 SYSTEM \$90,709.88 27 SYSTEM \$90,709.88 28 Mar 16, 2021 29 Mar 16, 2021 20 Mar 16, 2021 20 Mar 16, 2021 20 Mar 16, 2021 21 SYSTEM \$90,709.88 22 SYSTEM \$90,709.88 23 Mar 16, 2021 24 SYSTEM \$90,709.88 25 SYSTEM \$90,709.88 26 SYSTEM \$90,709.88 27 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsly overridding Payment Estimate Exception 7 on the current Payment Estimate. 28 SYSTEM \$0,000 29 Material - Total \$0.00					21		SYSTEM	\$90,709.88	
Payment Estimate Item Adjustment (0003) due to user woods overridding Payment Estimate Exception 7 on the current Payment Estimate. 23 Mar 16, 2021 23 Mar 16, SYSTEM (\$90,709.88) 23 Mar 16, 2021 3 Mar 16, 2021 3 SYSTEM \$90,709.88 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woods overridding Payment Estimate Exception 7 on the current Payment Estimate. - Total \$ 0.00 Material - Total					22		SYSTEM	(\$90,709.88)	
2021 23 Mar 16, SYSTEM \$90,709.88 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsloverridding Payment Estimate Exception 7 on the current Payment Estimate. - Total \$0.00 Material - Total \$0.00					22		SYSTEM	\$90,709.88	
Payment Estimate Item Adjustment (0003) due to user woodsloverridding Payment Estimate Exception 7 on the current Payment Estimate. - Total \$0.00 Material - Total \$0.00					23		SYSTEM	(\$90,709.88)	
Material - Total \$0.00					23		SYSTEM		
				- Total				\$0.00	
0100 - Total \$0.00		Material - Total						\$0.00	
	0100	- Total						\$0.00	

Revision 4/1/2020 Page 17 of 70



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0110	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	Material	. , , p =	6	Jul 2, 2020	SYSTEM	(\$16.00)	
				6	Jul 2, 2020	SYSTEM	\$16.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$100.00)	
				7	Jul 16, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$100.00)	
				8	Aug 3, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$100.00)	
				9	Aug 18, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 35 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$100.00)	
				10	Sep 3, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$100.00)	
				11	Sep 16, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$100.00)	
				12	Oct 1, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				13	Oct 16, 2020	SYSTEM	(\$100.00)	
				13	Oct 16, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				14	Nov 2, 2020	SYSTEM	(\$100.00)	
				14	Nov 2, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				15	Nov 17, 2020	SYSTEM	(\$100.00)	
				15	Nov 17, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				16	Dec 2, 2020	SYSTEM	(\$100.00)	
				16	Dec 2, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				17	Dec 16, 2020	SYSTEM	(\$100.00)	
				17	Dec 16, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.

Revision 4/1/2020 Page 18 of 70



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
0110	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	Material		18	Jan 4, 2021	SYSTEM	(\$100.00)					
				18	Jan 4, 2021	SYSTEM	\$100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.				
			- Total				\$0.00					
	Material - Total						\$0.00					
0110 -							\$0.00					
0120	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	Material		6	Jul 2, 2020	SYSTEM	(\$16.00)					
				6	Jul 2, 2020	SYSTEM	\$16.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.				
				7	Jul 16, 2020	SYSTEM	(\$100.00)					
								7	Jul 16, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
											8	Aug 3, 2020
				8	Aug 3, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.				
				9	Aug 18, 2020	SYSTEM	(\$100.00)					
				9	Aug 18, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 36 on the current Payment Estimate.				
						10	Sep 3, 2020	SYSTEM	(\$100.00)			
				10	Sep 3, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 22 on the current Payment Estimate.				
				11	Sep 16, 2020	SYSTEM	(\$100.00)					
				11	Sep 16, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate.				
				12	Oct 1, 2020	SYSTEM	(\$100.00)					
								12	Oct 1, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				13	Oct 16, 2020	SYSTEM	(\$100.00)					
				13	Oct 16, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.				
				14	Nov 2, 2020	SYSTEM	(\$100.00)					
				14	Nov 2, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.				
				15	Nov 17, 2020	SYSTEM	(\$100.00)					
				15	Nov 17, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.				
				16	Dec 2,	SYSTEM	(\$100.00)					

Revision 4/1/2020 Page 19 of 70



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks																								
5		Туре	Adjustment Type		Date	Ву																										
0120	TYPE 1 OR 5 AGGREGATE FOR BASE (4	Material			2020																											
	IN. THICK) (PAVEMENT REPAIR)			16	Dec 2, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.																								
				17	Dec 16, 2020	SYSTEM	(\$100.00)																									
				17	Dec 16, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.																								
				18	Jan 4, 2021	SYSTEM	(\$100.00)																									
				18	Jan 4, 2021	SYSTEM	\$100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.																								
			- Total				\$0.00																									
	Material - Total						\$0.00																									
0120 -	- Total						\$0.00																									
0140	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material		6	Jul 2, 2020	SYSTEM	(\$2,000.00)																									
	PAVEMENT REPAIR			6	Jul 2, 2020	SYSTEM	\$2,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.																								
				7	Jul 16, 2020	SYSTEM	(\$5,650.00)																									
					7	Jul 16, 2020	SYSTEM	\$5,650.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.																							
										8	Aug 3, 2020	SYSTEM	(\$5,650.00)																			
				8	Aug 3, 2020	SYSTEM	\$5,650.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.																								
				9	Aug 18, 2020	SYSTEM	(\$5,650.00)																									
				9	Aug 18, 2020	SYSTEM	\$5,650.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 37 on the current Payment Estimate.																								
																					10	Sep 3, 2020	SYSTEM	(\$5,650.00)								
							10	Sep 3, 2020	SYSTEM	\$5,650.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 23 on the current Payment Estimate.																					
																			11	Sep 16, 2020	SYSTEM	(\$7,480.00)										
																												11	Sep 16, 2020	SYSTEM	\$7,480.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
																													12	Oct 1, 2020	SYSTEM	(\$8,220.00)
															12	Oct 1, 2020	SYSTEM	\$8,220.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.													
				13	Oct 16, 2020	SYSTEM	(\$8,220.00)																									
																13	Oct 16, 2020	SYSTEM	\$8,220.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.												
				14	Nov 2, 2020	SYSTEM	(\$8,220.00)																									

Revision 4/1/2020 Page 20 of 70



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
	Description	Type	Adjustment Type	Number	Date	By	Amount	Remains
0140	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material		14	Nov 2, 2020	SYSTEM	\$8,220.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				15	Nov 17, 2020	SYSTEM	(\$8,220.00)	
				15	Nov 17, 2020	SYSTEM	\$8,220.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				16	Dec 2, 2020	SYSTEM	(\$8,220.00)	
				16	Dec 2, 2020	SYSTEM	\$8,220.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				17	Dec 16, 2020	SYSTEM	(\$8,220.00)	
				17	Dec 16, 2020	SYSTEM	\$8,220.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				18	Jan 4, 2021	SYSTEM	(\$8,220.00)	
				18	Jan 4, 2021	SYSTEM	\$8,220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0140 -	- Total						\$0.00	
0150	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR	Material		7	Jul 16, 2020	SYSTEM	(\$10.00)	
	FULL DEPTH PAVEMENT RÉPAIR			7	Jul 16, 2020	SYSTEM	\$10.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1
								overridding Payment Estimate Exception 14 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$10.00)	
				8		SYSTEM	(\$10.00) \$10.00	
					2020 Aug 3,		` ,	Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 14 on the current
				8	2020 Aug 3, 2020	SYSTEM	\$10.00	Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 14 on the current
				8	2020 Aug 3, 2020 Aug 18, 2020 Aug 18,	SYSTEM	\$10.00 (\$10.00)	Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 38 on the current
				9	2020 Aug 3, 2020 Aug 18, 2020 Aug 18, 2020	SYSTEM SYSTEM	\$10.00 (\$10.00) \$10.00	Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 38 on the current
				9 9 10	2020 Aug 3, 2020 Aug 18, 2020 Aug 18, 2020 Sep 3, 2020	SYSTEM SYSTEM SYSTEM	\$10.00 (\$10.00) \$10.00	Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 24 on the current
				9 9 10 10	2020 Aug 3, 2020 Aug 18, 2020 Aug 18, 2020 Sep 3, 2020 Sep 3, 2020 Sep 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$10.00 (\$10.00) \$10.00 (\$10.00)	Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 24 on the current
				9 9 10 10	2020 Aug 3, 2020 Aug 18, 2020 Aug 18, 2020 Sep 3, 2020 Sep 16, 2020 Sep 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$10.00 (\$10.00) \$10.00 (\$10.00)	Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
				9 9 10 10 11 11 11	2020 Aug 3, 2020 Aug 18, 2020 Aug 18, 2020 Sep 3, 2020 Sep 16, 2020 Oct 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$10.00 (\$10.00) \$10.00 (\$10.00) (\$10.00)	Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
				9 9 10 10 11 11 11 12	2020 Aug 3, 2020 Aug 18, 2020 Aug 18, 2020 Sep 3, 2020 Sep 16, 2020 Oct 1, 2020 Oct 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$10.00 (\$10.00) \$10.00 (\$10.00) \$10.00 (\$10.00)	Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 24 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 23 on the current Payment Estimate.

Revision 4/1/2020 Page 21 of 70



				_																								
Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																				
0150	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	Material			2020			Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.																				
				14	Nov 2, 2020	SYSTEM	(\$10.00)																					
				14	Nov 2, 2020	SYSTEM	\$10.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.																				
				15	Nov 17, 2020	SYSTEM	(\$10.00)																					
				15	Nov 17, 2020	SYSTEM	\$10.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.																				
				16	Dec 2, 2020	SYSTEM	(\$10.00)																					
				16	Dec 2, 2020	SYSTEM	\$10.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.																				
			- Total				\$0.00																					
	Material - Total						\$0.00																					
0150	- Total						\$0.00																					
0180	CONSTRUCTION SIGNS	Material		1	Apr 16, 2020	SYSTEM	(\$2,450.50)																					
				2	May 4, 2020	SYSTEM	(\$3,861.00)																					
				2	May 4, 2020	SYSTEM	\$3,861.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.																				
				3	May 19, 2020	SYSTEM	(\$3,861.00)																					
				3	May 19, 2020	SYSTEM	\$3,861.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.																				
				4	Jun 3, 2020	SYSTEM	(\$3,939.00)																					
				4	Jun 3, 2020	SYSTEM	\$3,939.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 9 on the current Payment Estimate.																				
				5	Jun 16, 2020	SYSTEM	(\$3,939.00)																					
				5	Jun 16, 2020	SYSTEM	\$3,939.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 9 on the current Payment Estimate.																				
				6	Jul 2, 2020	SYSTEM	(\$6,389.50)																					
				6	Jul 2, 2020	SYSTEM	\$6,389.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.																				
				7	Jul 16, 2020	SYSTEM	(\$6,389.50)																					
				7	Jul 16, 2020	SYSTEM	\$6,389.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.																				
				8	Aug 3, 2020	SYSTEM	(\$9,360.00)																					
																								8	Aug 3, 2020	SYSTEM	\$9,360.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$9,360.00)																					

Revision 4/1/2020 Page 22 of 70



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks											
0180	CONSTRUCTION SIGNS	Material	, ,,	9	Aug 18, 2020	SYSTEM	\$9,360.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 40 on the current Payment Estimate.											
				10	Sep 3, 2020	SYSTEM	(\$9,360.00)												
				10	Sep 3, 2020	SYSTEM	\$9,360.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 27 on the current Payment Estimate.											
			- Total				(\$2,450.50)												
	Material - Total						(\$2,450.50)												
	CONSTRUCTION SIGNS	MaterialCredit		2	May 4, 2020	SYSTEM	\$2,450.50												
			- Total				\$2,450.50												
	MaterialCredit - Total						\$2,450.50												
	CONSTRUCTION SIGNS	Other Item Adjustment	MDPA	1	Apr 16, 2020	woodsk1	\$2,450.50												
				2	May 4, 2020	woodsk1	(\$2,450.50)	This adjustment is being added to balance line item 0180 discrepancy amount.											
			MDPA - Tot	al			\$0.00												
	Other Item Adjustment - Total						\$0.00												
0180	- Total						\$0.00												
0210	CHANNELIZER (TRIM LINE)	Material		1	Apr 16, 2020	SYSTEM	(\$1,215.00)												
				2	May 4, 2020	SYSTEM	(\$1,215.00)												
				2	May 4, 2020	SYSTEM	\$1,215.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 10 on the current Payment Estimate.											
				3	May 19, 2020	SYSTEM	(\$1,215.00)												
				3	May 19, 2020	SYSTEM	\$1,215.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 10 on the current Payment Estimate.											
												4	Jun 3, 2020	SYSTEM	(\$1,980.00)				
						4	Jun 3, 2020	SYSTEM	\$1,980.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.									
				5	Jun 16, 2020	SYSTEM	(\$1,980.00)												
													5	Jun 16, 2020	SYSTEM	\$1,980.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.		
				6	Jul 2, 2020	SYSTEM	(\$3,930.00)												
															6	Jul 2, 2020	SYSTEM	\$3,930.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$3,930.00)												
									7	Jul 16, 2020	SYSTEM	\$3,930.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 20 on the current Payment Estimate.						
				8	Aug 3, 2020	SYSTEM	(\$3,930.00)												
											8	Aug 3, 2020	SYSTEM	\$3,930.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 20 on the current Payment Estimate.				
				9	Aug 18,	SYSTEM	(\$3,930.00)												

Revision 4/1/2020 Page 23 of 70



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks													
0210	CHANNELIZER (TRIM LINE)	Material			2020																
	` '			9	Aug 18, 2020	SYSTEM	\$3,930.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 44 on the current Payment Estimate.													
				10	Sep 3, 2020	SYSTEM	(\$3,930.00)														
				10	Sep 3, 2020	SYSTEM	\$3,930.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 30 on the current Payment Estimate.													
			- Total				(\$1,215.00)														
	Material - Total						(\$1,215.00)														
	CHANNELIZER (TRIM LINE)	MaterialCredit		2	May 4, 2020	SYSTEM	\$1,215.00														
			- Total				\$1,215.00														
	MaterialCredit - Total						\$1,215.00														
	CHANNELIZER (TRIM LINE)	Other Item Adjustment	MDPA	1	Apr 16, 2020	woodsk1	\$1,215.00														
		·		2	May 4, 2020	woodsk1	(\$1,215.00)	This adjustment is being added to balance line item 0220 discrepancy amount.													
			MDPA - Tot	al			\$0.00														
	Other Item Adjustment - Total						\$0.00														
0210 -	· Total						\$0.00														
0230	DIRECTIONAL INDICATOR BARRICADE	Material		1	Apr 16, 2020	SYSTEM	(\$665.00)														
				2	May 4, 2020	SYSTEM	(\$665.00)														
				2	May 4, 2020	SYSTEM	\$665.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.													
				3	May 19, 2020	SYSTEM	(\$665.00)														
				3	May 19, 2020	SYSTEM	\$665.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.													
				4	Jun 3, 2020	SYSTEM	(\$665.00)														
				4	Jun 3, 2020	SYSTEM	\$665.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.													
				5	Jun 16, 2020	SYSTEM	(\$665.00)														
															5	Jun 16, 2020	SYSTEM	\$665.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.		
				6	Jul 2, 2020	SYSTEM	(\$1,995.00)														
																	6	Jul 2, 2020	SYSTEM	\$1,995.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$2,660.00)														
				7	Jul 16, 2020	SYSTEM	\$2,660.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate.													
				8	Aug 3, 2020	SYSTEM	(\$2,660.00)														
				8	Aug 3, 2020	SYSTEM	\$2,660.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate.													

Revision 4/1/2020 Page 24 of 70



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																
0230	DIRECTIONAL INDICATOR BARRICADE	Material	,	9	Aug 18, 2020	SYSTEM	(\$2,660.00)																	
				9	Aug 18, 2020	SYSTEM	\$2,660.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 45 on the current Payment Estimate.																
				10	Sep 3, 2020	SYSTEM	(\$2,660.00)																	
				10	Sep 3, 2020	SYSTEM	\$2,660.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 31 on the current Payment Estimate.																
			- Total				(\$665.00)																	
	Material - Total						(\$665.00)																	
	DIRECTIONAL INDICATOR BARRICADE	MaterialCredit		2	May 4, 2020	SYSTEM	\$665.00																	
			- Total				\$665.00																	
	MaterialCredit - Total						\$665.00																	
	DIRECTIONAL INDICATOR BARRICADE	Other Item Adjustment	MDPA	1	Apr 16, 2020	woodsk1	\$665.00																	
				2	May 4, 2020	woodsk1	(\$665.00)	This adjustment is being added to balance line item 0230 discrepancy amount.																
			MDPA - Tot	al			\$0.00																	
	Other Item Adjustment - Total						\$0.00																	
0230 -	· Total						\$0.00																	
0240	FLASHING ARROW PANEL	Material		1	Apr 16, 2020	SYSTEM	(\$400.00)																	
				2	May 4, 2020	SYSTEM	(\$400.00)																	
				2	May 4, 2020	SYSTEM	\$400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.																
					3	May 19, 2020	SYSTEM	(\$400.00)																
				3	May 19, 2020	SYSTEM	\$400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.																
				4	Jun 3, 2020	SYSTEM	(\$400.00)																	
													4	Jun 3, 2020	SYSTEM	\$400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.							
				5	Jun 16, 2020	SYSTEM	(\$400.00)																	
													5	Jun 16, 2020	SYSTEM	\$400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.							
					6	Jul 2, 2020	SYSTEM	(\$1,200.00)																
																						6	Jul 2, 2020	SYSTEM
				7	Jul 16, 2020	SYSTEM	(\$1,600.00)																	
										7	Jul 16, 2020	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 22 on the current Payment Estimate.										
				8	Aug 3, 2020	SYSTEM	(\$1,600.00)																	
				8	Aug 3, 2020	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 22 on the current																

Revision 4/1/2020 Page 25 of 70



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
0240	FLASHING ARROW PANEL	Material						Payment Estimate.		
				9	Aug 18, 2020	SYSTEM	(\$1,600.00)			
				9	Aug 18, 2020	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 46 on the current Payment Estimate.		
				10	Sep 3, 2020	SYSTEM	(\$1,600.00)			
				10	Sep 3, 2020	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.		
			- Total				(\$400.00)			
	Material - Total						(\$400.00)			
	FLASHING ARROW PANEL	MaterialCredit		2	May 4, 2020	SYSTEM	\$400.00			
			- Total				\$400.00			
	MaterialCredit - Total						\$400.00			
	FLASHING ARROW PANEL	Other Item Adjustment	MDPA	1	Apr 16, 2020	woodsk1	\$400.00			
				2	May 4, 2020	woodsk1	(\$400.00)	This adjustment is being added to balance line item 0240 discrepancy amount.		
			MDPA - Tota	al			\$0.00			
	Other Item Adjustment - Total						\$0.00			
0240 -	·Total						\$0.00			
0250	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	Material		1	Apr 16, 2020	SYSTEM	(\$3,500.00)			
				2	May 4, 2020	SYSTEM	(\$3,500.00)			
				2	May 4, 2020	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.		
				3	May 19, 2020	SYSTEM	(\$3,500.00)			
				3	May 19, 2020	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.		
				4	Jun 3, 2020	SYSTEM	(\$3,500.00)			
				4	Jun 3, 2020	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.		
				5	Jun 16, 2020	SYSTEM	(\$3,500.00)			
						5	Jun 16, 2020	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
							6	Jul 2, 2020	SYSTEM	(\$3,500.00)
				6	Jul 2, 2020	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate.		
				7	Jul 16, 2020	SYSTEM	(\$7,000.00)			
				7	Jul 16, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 24 on the current Payment Estimate.		
				8	Aug 3, 2020	SYSTEM	(\$7,000.00)			
				8	Aug 3,	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun		

Revision 4/1/2020 Page 26 of 70



CHANGERSEE RESACTE SIGN Not provided Published COMMINACTOR RETAINED Published COMMINACTOR R	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
	0250	WITHOUT COMMUNICATION INTERFACE, CONTRACTOR	Material			2020			overridding Payment Estimate Exception 24 on the current
Page		FURNISHED, CONTRACTOR RETAINED			9		SYSTEM	(\$7,000.00)	
					9	Aug 18,	SYSTEM	\$7,000.00	Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 48 on the current
Page					10		SYSTEM	(\$7,000.00)	
Material - Total					10		SYSTEM	\$7,000.00	Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 34 on the current
CHANGEARR LINESANCE SIGN MaterialCredit MaterialCredit Total				- Total				(\$3,500.00)	
Name		Material - Total						(\$3,500.00)	
MaterialCredit - Total		WITHOUT COMMUNICATION INTERFACE, CONTRACTOR	MaterialCredit		2		SYSTEM	\$3,500.00	
CHANGEAGE MESSACE SIGN Adjustment Adju				- Total				\$3,500.00	
MITHOUT COMMUNICATION Adjustment 2020 2 May 4		MaterialCredit - Total						\$3,500.00	
FURNISHED, CONTRACTOR RETAINED 2 May 4, woodsk1 (83,500.00) This adjustment is being added to balance line item 0250 of contraction 10.000 10.		WITHOUT COMMUNICATION		MDPA	1		woodsk1	\$3,500.00	
					2		woodsk1	(\$3,500.00)	
No.				MDPA - Tot	al			\$0.00	
Mass		Other Item Adjustment - Total						\$0.00	
Stockpile	0250 -	Total						\$0.00	
Aprile Payment Estimate Item Adjustment generated Stockpile	0350	MGS GUARDRAIL			1		SYSTEM	\$85,893.50	
					4		SYSTEM	(\$5,068.25)	
1					6		SYSTEM	(\$4,001.25)	
2020 Transaction Transac					10		SYSTEM	(\$5,068.25)	
2020 Transaction					11		SYSTEM	(\$4,001.25)	
2020 Transaction					12		SYSTEM	(\$15,204.75)	
Construction Stockpile - Total S4,001.25					14		SYSTEM	(\$13,070.75)	
Section Stockpile - Total Section (REGULAR/NO CURB) Section (REGULAR/NO CURB)					23		SYSTEM	(\$35,477.75)	
MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB) Apr 16, 2020 SYSTEM \$35,976.00 Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Payment Estimate Item Adjustment generated Stockpile Payment Estimate Item Adjustment generated Stockpile Payment Estimate Item Adjustment generate				- Total				\$4,001.25	
MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB) Note that the properties of the properties o		Construction Stockpile - Total						\$4,001.25	
SECTION (REGULAR/NO CURB) Stockpile 2020 Transaction Transaction Transaction Transaction Transaction Transaction Payment Estimate Item Adjustment generated Stockpile Transaction Sep 3, 2020 SYSTEM (\$2,998.00) Payment Estimate Item Adjustment generated Stockpile Transaction Sep 3, 2020 SYSTEM (\$2,998.00) Payment Estimate Item Adjustment generated Stockpile Transaction Sep 16, 2020 SYSTEM (\$2,998.00) Payment Estimate Item Adjustment generated Stockpile Transaction Nov 2, 2020 SYSTEM (\$2,998.00) Payment Estimate Item Adjustment generated Stockpile Transaction Mar 16, 2021 SYSTEM (\$14,990.00) Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction	0350 -	Total						\$4,001.25	
2020 Transaction 6 Jul 2, 2020 SYSTEM (\$2,998.00) Payment Estimate Item Adjustment generated Stockpile Transaction 10 Sep 3, 2020 Payment Estimate Item Adjustment generated Stockpile Transaction 11 Sep 16, 2020 SYSTEM (\$2,998.00) Payment Estimate Item Adjustment generated Stockpile Transaction 11 Sep 16, 2020 Payment Estimate Item Adjustment generated Stockpile Transaction 14 Nov 2, 2020 SYSTEM (\$2,998.00) Payment Estimate Item Adjustment generated Stockpile Transaction 23 Mar 16, 2021 SYSTEM (\$14,990.00) Payment Estimate Item Adjustment generated Stockpile Transaction	0360				1		SYSTEM	\$35,976.00	
2020 Transaction 10 Sep 3, 2020 SySTEM (\$2,998.00) Payment Estimate Item Adjustment generated Stockpile Transaction 11 Sep 16, 2020 SySTEM (\$2,998.00) Payment Estimate Item Adjustment generated Stockpile Transaction 14 Nov 2, 2020 SySTEM (\$2,998.00) Payment Estimate Item Adjustment generated Stockpile Transaction 23 Mar 16, 2021 SySTEM (\$14,990.00) Payment Estimate Item Adjustment generated Stockpile Transaction					4		SYSTEM	(\$2,998.00)	
2020 Transaction 11 Sep 16, 2020 (\$2,998.00) Payment Estimate Item Adjustment generated Stockpile Transaction 14 Nov 2, 2020 (\$2,998.00) Payment Estimate Item Adjustment generated Stockpile Transaction 23 Mar 16, 2021 (\$14,990.00) Payment Estimate Item Adjustment generated Stockpile Transaction					6		SYSTEM	(\$2,998.00)	
2020 Transaction 14 Nov 2, 2020 (\$2,998.00) Payment Estimate Item Adjustment generated Stockpile Transaction 23 Mar 16, 2021 (\$14,990.00) Payment Estimate Item Adjustment generated Stockpile Transaction					10		SYSTEM	(\$2,998.00)	
2020 Transaction 23 Mar 16, 2021 (\$14,990.00) Payment Estimate Item Adjustment generated Stockpile Transaction					11		SYSTEM	(\$2,998.00)	
2021 Transaction					14		SYSTEM	(\$2,998.00)	
- Total \$5,996.00					23		SYSTEM	(\$14,990.00)	
				- Total				\$5,996.00	

Revision 4/1/2020 Page 27 of 70



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0360	Construction Stockpile - Total						\$5,996.00	
0360 -	· Total						\$5,996.00	
0370	MGS END ANCHOR	Construction Stockpile		1	Apr 16, 2020	SYSTEM	\$3,210.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				12	Oct 1, 2020	SYSTEM	(\$3,210.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
0370 -	· Total						\$0.00	
0380	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		1	Apr 16, 2020	SYSTEM	\$45,300.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				4	Jun 3, 2020	SYSTEM	(\$3,020.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				6	Jul 2, 2020	SYSTEM	(\$3,020.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				10	Sep 3, 2020	SYSTEM	(\$3,020.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				11	Sep 16, 2020	SYSTEM	(\$3,020.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				12	Oct 1, 2020	SYSTEM	(\$9,060.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				14	Nov 2, 2020	SYSTEM	(\$3,020.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				23	Mar 16, 2021	SYSTEM	(\$16,610.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$4,530.00	
	Construction Stockpile - Total						\$4,530.00	
0380 -	Total						\$4,530.00	
0400	EMULSIFIED ASPHALT, SEAL COAT	Material		9	Aug 18, 2020	SYSTEM	(\$265.00)	
				9	Aug 18, 2020	SYSTEM	\$265.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	EMULSIFIED ASPHALT, SEAL COAT	Other Item Adjustment	ACAD	19	Jan 20, 2021	woodsk1	(\$19.32)	AC Seal Coat Adjustment. August 17th, 2020 placement date.
			ACAD - Tota	al			(\$19.32)	
	Other Item Adjustment - Total						(\$19.32)	
0400 -	Total						(\$19.32)	
0410	SEAL COAT AGGREGATE, GRADE B1	Material		9	Aug 18, 2020	SYSTEM	(\$662.50)	
				9	Aug 18, 2020	SYSTEM	\$662.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$1,325.00)	
				10	Sep 3, 2020	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$1,325.00)	
				11	Sep 16, 2020	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$1,325.00)	
				12	Oct 1, 2020	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 2 on the current

Revision 4/1/2020 Page 28 of 70



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks														
0410	SEAL COAT AGGREGATE, GRADE B1	Material						Payment Estimate.														
				13	Oct 16, 2020	SYSTEM	(\$1,325.00)															
				13	Oct 16, 2020	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.														
				14	Nov 2, 2020	SYSTEM	(\$1,325.00)															
				14	Nov 2, 2020	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.														
				15	Nov 17, 2020	SYSTEM	(\$1,325.00)															
				15	Nov 17, 2020	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.														
				16	Dec 2, 2020	SYSTEM	(\$1,325.00)															
				16	Dec 2, 2020	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.														
				17	Dec 16, 2020	SYSTEM	(\$1,325.00)															
				17	Dec 16, 2020	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.														
				18	Jan 4, 2021	SYSTEM	(\$1,325.00)															
				18	Jan 4, 2021	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.														
					19	Jan 20, 2021	SYSTEM	(\$1,325.00)														
				19	Jan 20, 2021	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.														
				20	Feb 1, 2021	SYSTEM	(\$1,325.00)															
				20	Feb 1, 2021	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.														
				21	Feb 16, 2021	SYSTEM	(\$1,325.00)															
				21	Feb 16, 2021	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.														
				22	Mar 2, 2021	SYSTEM	(\$1,325.00)															
																		22	Mar 2, 2021	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					23	Mar 16, 2021	SYSTEM	(\$1,325.00)														
									SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.											
			- Total				\$0.00															
	Material - Total						\$0.00															
0410 -	Total						\$0.00															

Revision 4/1/2020 Page 29 of 70



Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks									
0420	CURB BLOCKOUT	Material	Туре	2	May 4,	SYSTEM	(\$11,278.05)										
				2	2020 May 4, 2020	SYSTEM	\$11,278.05	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.									
				3	May 19, 2020	SYSTEM	(\$16,671.90)										
				3	May 19, 2020	SYSTEM	\$16,671.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.									
				4	Jun 3, 2020	SYSTEM	(\$16,671.90)										
				4	Jun 3, 2020	SYSTEM	\$16,671.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 26 on the current Payment Estimate.									
				5	Jun 16, 2020	SYSTEM	(\$16,671.90)										
				5	Jun 16, 2020	SYSTEM	\$16,671.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 26 on the current Payment Estimate.									
				6	Jul 2, 2020	SYSTEM	(\$33,343.80)										
				6	Jul 2, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.									
				7	Jul 16, 2020	SYSTEM	(\$33,343.80)										
					7	Jul 16, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 34 on the current Payment Estimate.								
					8	Aug 3, 2020	SYSTEM	(\$33,343.80)									
				8	Aug 3, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 40 on the current Payment Estimate.									
				9	Aug 18, 2020	SYSTEM	(\$33,343.80)										
				9	Aug 18, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 76 on the current Payment Estimate.									
				10	Sep 3, 2020	SYSTEM	(\$33,343.80)										
				10	Sep 3, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 62 on the current Payment Estimate.									
				11	Sep 16, 2020	SYSTEM	(\$33,343.80)										
							11	Sep 16, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 50 on the current Payment Estimate.						
													12	Oct 1, 2020	SYSTEM	(\$33,343.80)	
					13	Oct 16, 2020	SYSTEM	(\$33,343.80)									
				13	Oct 16, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 27 on the current Payment Estimate.									

Revision 4/1/2020 Page 30 of 70



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0420	CURB BLOCKOUT	Material		14	Nov 2, 2020	SYSTEM	(\$33,343.80)	
				14	Nov 2, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
				15	Nov 17, 2020	SYSTEM	(\$33,343.80)	
			15	Nov 17, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 29 on the current Payment Estimate.	
				16	Dec 2, 2020	SYSTEM	(\$33,343.80)	
				16	Dec 2, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
				17	Dec 16, 2020	SYSTEM	(\$33,343.80)	
				17	Dec 16, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
				18	Jan 4, 2021	SYSTEM	(\$33,343.80)	
				18	Jan 4, 2021	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
				19	Jan 20, 2021	SYSTEM	(\$33,343.80)	
				19	Jan 20, 2021	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				20	Feb 1, 2021	SYSTEM	(\$33,343.80)	
				20	Feb 1, 2021	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				21	Feb 16, 2021	SYSTEM	(\$33,343.80)	
				21	Feb 16, 2021	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				22	Mar 2, 2021	SYSTEM	(\$33,343.80)	
				22	Mar 2, 2021	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				23	Mar 16, 2021	SYSTEM	(\$33,343.80)	
				23	Mar 16, 2021	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
	Material - Total		- Total				\$0.00	
0.420							\$0.00	
0420	- Total HALF-SOLE REPAIR	Material		3	May 19,	SYSTEM	\$0.00 (\$12,412.98)	
				3	2020 May 19, 2020	SYSTEM	\$12,412.98	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 32 on the current
				4	Jun 3,	SYSTEM	(\$23,457.60)	Payment Estimate.

Revision 4/1/2020 Page 31 of 70



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks												
0430	HALF-SOLE REPAIR	Material			2020															
				4	Jun 3, 2020	SYSTEM	\$23,457.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 39 on the current Payment Estimate.												
				5	Jun 16, 2020	SYSTEM	(\$37,727.64)													
				5	Jun 16, 2020	SYSTEM	\$37,727.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 39 on the current Payment Estimate.												
				6	Jul 2, 2020	SYSTEM	(\$67,440.60)													
				6	Jul 2, 2020	SYSTEM	\$67,440.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 49 on the current Payment Estimate.												
				7	Jul 16, 2020	SYSTEM	(\$67,440.60)													
				7	Jul 16, 2020	SYSTEM	\$67,440.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 52 on the current Payment Estimate.												
				8	Aug 3, 2020	SYSTEM	(\$67,440.60)													
																8	Aug 3, 2020	SYSTEM	\$67,440.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 52 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$67,440.60)													
				9	Aug 18, 2020	SYSTEM	\$67,440.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 87 on the current Payment Estimate.												
				10	Sep 3, 2020	SYSTEM	(\$67,440.60)													
			10	Sep 3, 2020	SYSTEM	\$67,440.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 73 on the current Payment Estimate.													
				11	Sep 16, 2020	SYSTEM	(\$67,440.60)													
				11	Sep 16, 2020	SYSTEM	\$67,440.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 62 on the current Payment Estimate.												
					12	Oct 1, 2020	SYSTEM	(\$73,793.70)												
				12	Oct 1, 2020	SYSTEM	\$73,793.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 45 on the current Payment Estimate.												
				13	Oct 16, 2020	SYSTEM	(\$73,793.70)													
					13	Oct 16, 2020	SYSTEM	\$73,793.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 46 on the current Payment Estimate.											
				14	Nov 2, 2020	SYSTEM	(\$73,793.70)													
					14	Nov 2, 2020	SYSTEM	\$73,793.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 47 on the current Payment Estimate.											
				15	Nov 17, 2020	SYSTEM	(\$73,793.70)													
				15	Nov 17, 2020	SYSTEM	\$73,793.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 48 on the current Payment Estimate.												

Revision 4/1/2020 Page 32 of 70



	5	A 11	011					
Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0430	HALF-SOLE REPAIR	Material		16	Dec 2, 2020	SYSTEM	(\$73,793.70)	
				16	Dec 2, 2020	SYSTEM	\$73,793.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 48 on the current Payment Estimate.
				17	Dec 16, 2020	SYSTEM	(\$73,793.70)	
				17	Dec 16, 2020	SYSTEM	\$73,793.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 52 on the current Payment Estimate.
				18	Jan 4, 2021	SYSTEM	(\$73,793.70)	
				18	Jan 4, 2021	SYSTEM	\$73,793.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 45 on the current Payment Estimate.
				19	Jan 20, 2021	SYSTEM	(\$73,793.70)	
				19	Jan 20, 2021	SYSTEM	\$73,793.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
				20	Feb 1, 2021	SYSTEM	(\$73,793.70)	
				20	Feb 1, 2021	SYSTEM	\$73,793.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
				21	Feb 16, 2021	SYSTEM	(\$73,793.70)	
				21	Feb 16, 2021	SYSTEM	\$73,793.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
				22	Mar 2, 2021	SYSTEM	(\$73,793.70)	
				22	Mar 2, 2021	SYSTEM	\$73,793.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
				23	Mar 16, 2021	SYSTEM	(\$73,793.70)	
				23	Mar 16, 2021	SYSTEM	\$73,793.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0430 - 0450	Total EMULSIFIED ASPHALT, SEAL COAT	Material		9	Aug 18,	SYSTEM	\$0.00 (\$287.50)	
				9	2020 Aug 18, 2020	SYSTEM	\$287.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1
								overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total	011 11		40			\$0.00	400 40 44 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4
	EMULSIFIED ASPHALT, SEAL COAT	Other Item Adjustment	ACAD		Jan 20, 2021	woodsk1	(\$20.96)	AC Seal Coat Adjustment. August 17th, 2020 placement date.
		ACAD - Total				(\$20.96)		
	Other Item Adjustment - Total						(\$20.96)	
0450 -							(\$20.96)	
0460	SEAL COAT AGGREGATE, GRADE B1	Material		9	Aug 18, 2020	SYSTEM	(\$720.00)	
				9	Aug 18, 2020	SYSTEM	\$720.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1

Revision 4/1/2020 Page 33 of 70



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																		
0460	SEAL COAT AGGREGATE, GRADE B1	Material	, ,,					overridding Payment Estimate Exception 27 on the current Payment Estimate.																		
					10	Sep 3, 2020	SYSTEM	(\$1,440.00)																		
				10	Sep 3, 2020	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.																		
				11	Sep 16, 2020	SYSTEM	(\$1,440.00)																			
					11	Sep 16, 2020	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.																	
				12	Oct 1, 2020	SYSTEM	(\$1,440.00)																			
				12	Oct 1, 2020	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.																		
				13	Oct 16, 2020	SYSTEM	(\$1,440.00)																			
				13	Oct 16, 2020	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.																		
													14	Nov 2, 2020	SYSTEM	(\$1,440.00)										
				14	Nov 2, 2020	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.																		
				15	Nov 17, 2020	SYSTEM	(\$1,440.00)																			
				15	Nov 17, 2020	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 6 on the current Payment Estimate.																		
				16	Dec 2, 2020	SYSTEM	(\$1,440.00)																			
				16	Dec 2, 2020	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 6 on the current Payment Estimate.																		
				17	Dec 16, 2020	SYSTEM	(\$1,440.00)																			
						17	Dec 16, 2020	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 6 on the current Payment Estimate.																
				18	Jan 4, 2021	SYSTEM	(\$1,440.00)																			
																						18	Jan 4, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
						19	Jan 20, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.																
				20	Feb 1, 2021	SYSTEM	(\$1,440.00)																			
				20	Feb 1, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.																		
				21	Feb 16, 2021	SYSTEM	(\$1,440.00)																			
				21	Feb 16,	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material																		

Revision 4/1/2020 Page 34 of 70



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks								
0460	SEAL COAT AGGREGATE, GRADE B1	Material			2021			Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.								
				22	Mar 2, 2021	SYSTEM	(\$1,440.00)									
				22	Mar 2, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.								
				23	Mar 16, 2021	SYSTEM	(\$1,440.00)									
				23	Mar 16, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.								
			- Total				\$0.00									
	Material - Total						\$0.00									
0460 -						ava==:	\$0.00									
0470	CURB BLOCKOUT	Material		3	May 19, 2020	SYSTEM	(\$12,100.62)									
				3	May 19, 2020	SYSTEM	\$12,100.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 25 on the current Payment Estimate.								
				4	Jun 3, 2020	SYSTEM	(\$17,908.92)									
												4	Jun 3, 2020	SYSTEM	\$17,908.92	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
				5	Jun 16, 2020	SYSTEM	(\$17,908.92)									
				5	Jun 16, 2020	SYSTEM	\$17,908.92	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.								
				6	Jul 2, 2020	SYSTEM	(\$35,817.85)									
				6	Jul 2, 2020	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.								
				7	Jul 16, 2020	SYSTEM	(\$35,817.85)									
						7	Jul 16, 2020	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 40 on the current Payment Estimate.						
				8	Aug 3, 2020	SYSTEM	(\$35,817.85)									
											8	Aug 3, 2020	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 34 on the current Payment Estimate.	
										9	Aug 18, 2020	SYSTEM	(\$35,817.85)			
				9	Aug 18, 2020	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 64 on the current Payment Estimate.								
				10	Sep 3, 2020	SYSTEM	(\$35,817.85)									
						10	Sep 3, 2020	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 50 on the current Payment Estimate.						
				11	Sep 16, 2020	SYSTEM	(\$35,817.85)									
				11	Sep 16, 2020	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1								

Revision 4/1/2020 Page 35 of 70



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																							
0470	CURB BLOCKOUT	Material						overridding Payment Estimate Exception 38 on the current Payment Estimate.																							
				12	Oct 1, 2020	SYSTEM	(\$35,817.85)																								
				12	Oct 1, 2020	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 37 on the current Payment Estimate.																							
				13	Oct 16, 2020	SYSTEM	(\$35,817.85)																								
				13	Oct 16, 2020	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.																							
				14	Nov 2, 2020	SYSTEM	(\$35,817.85)																								
				14	Nov 2, 2020	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 39 on the current Payment Estimate.																							
				15	Nov 17, 2020	SYSTEM	(\$35,817.85)																								
				15	Nov 17, 2020	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 40 on the current Payment Estimate.																							
						16	Dec 2, 2020	SYSTEM	(\$35,817.85)																						
					16	Dec 2, 2020	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 40 on the current Payment Estimate.																						
				17	Dec 16, 2020	SYSTEM	(\$35,817.85)																								
				17	Dec 16, 2020	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.																							
				18	Jan 4, 2021	SYSTEM	(\$35,817.85)																								
				18	Jan 4, 2021	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 26 on the current Payment Estimate.																							
				19	Jan 20, 2021	SYSTEM	(\$35,817.85)																								
				19	Jan 20, 2021	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.																							
				20	Feb 1, 2021	SYSTEM	(\$35,817.85)																								
																											20	Feb 1, 2021	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
																						21	Feb 16, 2021	SYSTEM	(\$35,817.85)						
					21	Feb 16, 2021	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.																						
				22	Mar 2, 2021	SYSTEM	(\$35,817.85)																								
													22	Mar 2, 2021	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.														
				23	Mar 16, 2021	SYSTEM	(\$35,817.85)																								
				23	Mar 16,	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Material																							

Revision 4/1/2020 Page 36 of 70



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0470	CURB BLOCKOUT	Material			2021			Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0470 -	- Total						\$0.00	
0480	HALF-SOLE REPAIR	Material		3	May 19, 2020	SYSTEM	(\$4,160.68)	
				3	May 19, 2020	SYSTEM	\$4,160.68	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
				4	Jun 3, 2020	SYSTEM	(\$25,157.60)	
				4	Jun 3, 2020	SYSTEM	\$25,157.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
				5	Jun 16, 2020	SYSTEM	(\$41,510.04)	
				5	Jun 16, 2020	SYSTEM	\$41,510.04	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
				6	Jul 2, 2020	SYSTEM	(\$69,183.40)	
				6	Jul 2, 2020	SYSTEM	\$69,183.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 45 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$69,183.40)	
				7	Jul 16, 2020	SYSTEM	\$69,183.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 48 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$69,183.40)	
				8	Aug 3, 2020	SYSTEM	\$69,183.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 48 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$69,183.40)	
				9	Aug 18, 2020	SYSTEM	\$69,183.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 83 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$69,183.40)	
				10	Sep 3, 2020	SYSTEM	\$69,183.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 69 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$69,183.40)	
				11	Sep 16, 2020	SYSTEM	\$69,183.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 58 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$69,957.48)	
				12	Oct 1, 2020	SYSTEM	\$69,957.48	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 50 on the current Payment Estimate.
				13	Oct 16, 2020	SYSTEM	(\$69,957.48)	
				13	Oct 16, 2020	SYSTEM	\$69,957.48	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1

Revision 4/1/2020 Page 37 of 70



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0480	HALF-SOLE REPAIR	Material						overridding Payment Estimate Exception 51 on the current Payment Estimate.
				14	Nov 2, 2020	SYSTEM	(\$69,957.48)	
				14	Nov 2, 2020	SYSTEM	\$69,957.48	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 52 on the current Payment Estimate.
				15	Nov 17, 2020	SYSTEM	(\$69,957.48)	
				15	Nov 17, 2020	SYSTEM	\$69,957.48	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 53 on the current Payment Estimate.
				16	Dec 2, 2020	SYSTEM	(\$69,957.48)	
				16	Dec 2, 2020	SYSTEM	\$69,957.48	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 53 on the current Payment Estimate.
				17	Dec 16, 2020	SYSTEM	(\$69,957.48)	
				17	Dec 16, 2020	SYSTEM	\$69,957.48	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 47 on the current Payment Estimate.
				18	Jan 4, 2021	SYSTEM	(\$69,957.48)	
				18	Jan 4, 2021	SYSTEM	\$69,957.48	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 50 on the current Payment Estimate.
				19	Jan 20, 2021	SYSTEM	(\$69,957.48)	
				19	Jan 20, 2021	SYSTEM	\$69,957.48	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
				20	Feb 1, 2021	SYSTEM	(\$69,957.48)	
				20	Feb 1, 2021	SYSTEM	\$69,957.48	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
				21	Feb 16, 2021	SYSTEM	(\$69,957.48)	
				21	Feb 16, 2021	SYSTEM	\$69,957.48	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
				22	Mar 2, 2021	SYSTEM	(\$69,957.48)	
				22	Mar 2, 2021	SYSTEM	\$69,957.48	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
				23	Mar 16, 2021	SYSTEM	(\$69,957.48)	
				23	Mar 16, 2021	SYSTEM	\$69,957.48	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
			- Total				\$0.00	
0.400	Material - Total						\$0.00	
0480 -	- Total EMULSIFIED ASPHALT, SEAL COAT	Other Item	ACAD	19	Jan 20, 2021	woodsk1	\$0.00 (\$19.33)	AC Seal Coat Adjustment. September 25th 2020 placement
		Adjustment	ACAD - Tota	al	2021		(\$19.33)	date.
	Other Item Adjustment - Total						(\$19.33)	

Revision 4/1/2020 Page 38 of 70



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0500 -	Total						(\$19.33)	
0510	SEAL COAT AGGREGATE, GRADE B1	Material		19	Jan 20, 2021	SYSTEM	(\$1,325.00)	
				19	Jan 20, 2021	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				20	Feb 1, 2021	SYSTEM	(\$1,325.00)	
				20	Feb 1, 2021	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				21	Feb 16, 2021	SYSTEM	(\$1,325.00)	
				21	Feb 16, 2021	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				22	Mar 2, 2021	SYSTEM	(\$1,325.00)	
				22	Mar 2, 2021	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				23	Mar 16, 2021	SYSTEM	(\$1,325.00)	
				23	Mar 16, 2021	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0510 -							\$0.00	
0520	CURB BLOCKOUT	Material		9	Aug 18, 2020	SYSTEM	(\$16,671.90)	
				9	Aug 18, 2020	SYSTEM	\$16,671.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 70 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$16,671.90)	
				10	Sep 3, 2020	SYSTEM	\$16,671.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 56 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$33,343.80)	
				11	Sep 16, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 44 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$33,343.80)	
				12	Oct 1, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
				13	Oct 16, 2020	SYSTEM	(\$33,343.80)	
				13	Oct 16, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
				14	Nov 2, 2020	SYSTEM	(\$33,343.80)	
				14	Nov 2, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 33 on the current Payment Estimate.

Revision 4/1/2020 Page 39 of 70



Section	
16	
16	o user woodsk1
2020 Payment Estimate Majustreent (0011) due to eventiding Payment Estimate Exception 34 on Payment Estimate Exception 27 on Payment Estimate Exception 35 on Pay	
17	o user woodsk1
18	
18	o user woodsk1
2021 Payment Estimate tem Adjustment (0011) due to overridding Payment Estimate Exception 32 on Payment Estimate Item Adjustment (0008) due to overridding Payment Estimate Exception 21 on Payment Estimate Exception 22 on Exception 22 on Payment Estimate Except	
2021	o user woodsk1
2021 Payment Estimate Item Adjustment (0008) due toverridding Payment Estimate Exception 21 on Payment 21 on Payment 22 on Payment 22 on Payment 23 on Payment 23 on Payment 24 on Payment 25 on Payment 25 on Payment 25 on Paymen	
2021 2021	o user woodsk1
2021 Payment Estimate Item Adjustment (0008) due to overridding Payment Estimate Exception 21 on in Payment Estimate Item Adjustment (0008) due to overridding Payment Estimate Exception 21 on in Payment Estimate Exception 22 on in Payment Estimate Exception 23 on in Payment Estimate Exception 24 on in Payment 25 on in Payment Estimate Exception 24 on in Payment 25 on in Pa	
2021	o user woodsk1
2021 Payment Estimate Item Adjustment (0008) due to overridding Payment Estimate Exception 21 on in Payment Estimate Exception 21 on in Payment Estimate Exception 21 on in Payment Estimate Item Adjustment (0008) due to overridding Payment Estimate Item Adjustment (0008) due to overridding Payment Estimate Exception 21 on in Payment Estimate Item Adjustment (0013) due to overridding Payment Estimate Exception 21 on in Payment Estimate Item Adjustment (0013) due to overridding Payment Estimate Exception 21 on in Payment Estimate Exception 22 on in Payment Estimate Exception 22 on in Payment Estimate Exception 23 on in Payment Estimate Exception 24 on in Payment Estimate Exception 25 on in Payment Estimate Exception 25 on in Payment Estimate Exception 25 on in Payment Estimate Item Adjustment (0013) due in Payment Estimate Exception 25 on in Payment Estimate Exception 25 on in Pay	
2021	o user woodsk1
2021 Payment Estimate Item Adjustment (0008) due to overridding Payment Estimate Exception 21 on item Payment Estimate Exception 21 on item Payment Estimate Exception 21 on item Payment Estimate Payment Estimate Item Adjustment (0013) due to overridding Payment Estimate Item Adjustment (0013) due to overridding Payment Estimate Exception 21 on item Payment Estimate Exception 21 on item Payment Estimate Payment Estimate Exception 21 on item Payment Estimate Exception 21 on item Payment Estimate Payment Estimate Exception 21 on item Payment Estimate Exception 21 on item Payment Estimate Payment Estimate Exception 21 on item Payment Estimate Exception 21 on item Payment Estimate Item Adjustment (0015) due item Payment Estimate Item Adjustment (0015) due overridding Payment Estimate Item Adjustment (0015) due overridding Payment Estimate Exception 47 on item Payment Estimate Item Adjustment (0015) due overridding	
2021 23	o user woodsk1
2021 Payment Estimate Item Adjustment (0013) due overridding Payment Estimate Exception 21 on in Payment Estimate Exception 21 on in Payment Estimate. \$0.00	
Material - Total	o user woodsk1
10520 - Total \$0.00	
Description of the property	
7 Jul 16, 2020 \$\ 2020	
2020 Payment Estimate Item Adjustment (0015) due overridding Payment Estimate Exception 47 on	
	o user woodsk1
8 Aug 3, 2020 SYSTEM (\$8,503.38)	
8 Aug 3, 2020 \$8,503.38 This adjustment offsets the original system-gene Payment Estimate Item Adjustment (0016) due to overridding Payment Estimate Exception 47 on the Payment Estimate.	o user woodsk1
9 Aug 18, SYSTEM (\$23,457.60)	

Revision 4/1/2020 Page 40 of 70



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																											
0530	HALF-SOLE REPAIR	Material			2020																														
				9	Aug 18, 2020	SYSTEM	\$23,457.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 82 on the current Payment Estimate.																											
									10	Sep 3, 2020	SYSTEM	(\$23,457.60)																							
				10	Sep 3, 2020	SYSTEM	\$23,457.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 68 on the current Payment Estimate.																											
				11	Sep 16, 2020	SYSTEM	(\$23,457.60)																												
				11	Sep 16, 2020	SYSTEM	\$23,457.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 57 on the current Payment Estimate.																											
								12	Oct 1, 2020	SYSTEM	(\$83,372.22)																								
						12	Oct 1, 2020	SYSTEM	\$83,372.22	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 49 on the current Payment Estimate.																									
					13	Oct 16, 2020	SYSTEM	(\$83,372.22)																											
				13	Oct 16, 2020	SYSTEM	\$83,372.22	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 50 on the current Payment Estimate.																											
					14	Nov 2, 2020	SYSTEM	(\$83,372.22)																											
				14	Nov 2, 2020	SYSTEM	\$83,372.22	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 51 on the current Payment Estimate.																											
					15	Nov 17, 2020	SYSTEM	(\$83,372.22)																											
				15	Nov 17, 2020	SYSTEM	\$83,372.22	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 52 on the current Payment Estimate.																											
						16	Dec 2, 2020	SYSTEM	(\$83,372.22)																										
				16	Dec 2, 2020	SYSTEM	\$83,372.22	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 52 on the current Payment Estimate.																											
																			17	Dec 16, 2020	SYSTEM	(\$83,372.22)													
									17	Dec 16, 2020	SYSTEM	\$83,372.22	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 51 on the current Payment Estimate.																						
									18	Jan 4, 2021	SYSTEM	(\$83,372.22)																							
													1	1		18	Jan 4, 2021	SYSTEM	\$83,372.22	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 54 on the current Payment Estimate.															
															19	Jan 20, 2021	SYSTEM	(\$83,372.22)																	
															1																				
								;									:																		
				20	Feb 1, 2021	SYSTEM	\$83,372.22	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 40 on the current Payment Estimate.																											

Revision 4/1/2020 Page 41 of 70



	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0530	HALF-SOLE REPAIR	Material		21	Feb 16, 2021	SYSTEM	(\$83,372.22)	
				21	Feb 16, 2021	SYSTEM	\$83,372.22	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
				22	Mar 2, 2021	SYSTEM	(\$83,372.22)	
				22	Mar 2, 2021	SYSTEM	\$83,372.22	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
				23	Mar 16, 2021	SYSTEM	(\$83,372.22)	
				23	Mar 16, 2021	SYSTEM	\$83,372.22	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0530 -	Total						\$0.00	
0550	EMULSIFIED ASPHALT, SEAL COAT	Other Item Adjustment	ACAD	19	Jan 20, 2021	woodsk1	(\$17.50)	AC Seal Coat Adjustment. September 25th, 2020 placement date.
			ACAD - Tota	al			(\$17.50)	
	Other Item Adjustment - Total						(\$17.50)	
0550 -	Total						(\$17.50)	
0560	SEAL COAT AGGREGATE, GRADE B1	Material		19	Jan 20, 2021	SYSTEM	(\$1,205.00)	
				19	Jan 20, 2021	SYSTEM	\$1,205.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				20	Feb 1, 2021	SYSTEM	(\$1,205.00)	
				20	Feb 1, 2021	SYSTEM	\$1,205.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 5 on the current
								Payment Estimate.
				21	Feb 16, 2021	SYSTEM	(\$1,205.00)	
				21		SYSTEM	(\$1,205.00) \$1,205.00	
					2021 Feb 16,			Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 5 on the current
				21	2021 Feb 16, 2021 Mar 2,	SYSTEM	\$1,205.00	Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 5 on the current
				21	2021 Feb 16, 2021 Mar 2, 2021 Mar 2,	SYSTEM	\$1,205.00 (\$1,205.00)	Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 5 on the current
				21 22 22	2021 Feb 16, 2021 Mar 2, 2021 Mar 2, 2021	SYSTEM SYSTEM SYSTEM	\$1,205.00 (\$1,205.00) \$1,205.00	Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 5 on the current
			- Total	22 22 23	2021 Feb 16, 2021 Mar 2, 2021 Mar 2, 2021 Mar 16, 2021 Mar 16, 2021	SYSTEM SYSTEM SYSTEM	\$1,205.00 (\$1,205.00) \$1,205.00	Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 5 on the current
	Material - Total		- Total	22 22 23	2021 Feb 16, 2021 Mar 2, 2021 Mar 2, 2021 Mar 16, 2021 Mar 16, 2021	SYSTEM SYSTEM SYSTEM	\$1,205.00 (\$1,205.00) \$1,205.00 (\$1,205.00)	Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 5 on the current
0560 -			- Total	22 22 23	2021 Feb 16, 2021 Mar 2, 2021 Mar 2, 2021 Mar 16, 2021 Mar 16, 2021	SYSTEM SYSTEM SYSTEM	\$1,205.00 (\$1,205.00) \$1,205.00 (\$1,205.00) \$1,205.00	Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 5 on the current
0560 - 0570		Material	- Total	22 22 23	2021 Feb 16, 2021 Mar 2, 2021 Mar 2, 2021 Mar 16, 2021 Mar 16, 2021	SYSTEM SYSTEM SYSTEM	\$1,205.00 (\$1,205.00) \$1,205.00 (\$1,205.00) \$1,205.00 \$0.00	Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 5 on the current
	Total	Material	- Total	21 22 22 23 23	2021 Feb 16, 2021 Mar 2, 2021 Mar 16, 2021 Mar 16, 2021 Aug 18, 4ug 18,	SYSTEM SYSTEM SYSTEM SYSTEM	\$1,205.00 (\$1,205.00) \$1,205.00 (\$1,205.00) \$1,205.00 \$0.00 \$0.00	Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 5 on the current

Revision 4/1/2020 Page 42 of 70



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																																							
0570	CURB BLOCKOUT	Material	, ,,	10	Sep 3, 2020	SYSTEM	\$15,434.12	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 44 on the current Payment Estimate.																																							
					11	Sep 16, 2020	SYSTEM	(\$30,868.25)																																							
				11	Sep 16, 2020	SYSTEM	\$30,868.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.																																							
											12	Oct 1, 2020	SYSTEM	(\$30,868.25)																																	
				12	Oct 1, 2020	SYSTEM	\$30,868.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 20 on the current Payment Estimate.																																							
												13	Oct 16, 2020	SYSTEM	(\$30,868.25)																																
				13	Oct 16, 2020	SYSTEM	\$30,868.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate.																																							
										14	Nov 2, 2020	SYSTEM	(\$30,868.25)																																		
				14	Nov 2, 2020	SYSTEM	\$30,868.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 22 on the current Payment Estimate.																																							
				15	Nov 17, 2020	SYSTEM	(\$30,868.25)																																								
						15	Nov 17, 2020	SYSTEM	\$30,868.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 23 on the current Payment Estimate.																																					
											16	Dec 2, 2020	SYSTEM	(\$30,868.25)																																	
				16	Dec 2, 2020	SYSTEM	\$30,868.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 23 on the current Payment Estimate.																																							
						17	Dec 16, 2020	SYSTEM	(\$30,868.25)																																						
				17	Dec 16, 2020	SYSTEM	\$30,868.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate.																																							
																													18	Jan 4, 2021	SYSTEM	(\$30,868.25)															
						18	Jan 4, 2021	SYSTEM	\$30,868.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.																																					
				2:	2:			2	2	2				2	2:	20	20	2																	19	Jan 20, 2021	SYSTEM	(\$30,868.25)									
																					2	2	2	2				:		2	19	Jan 20, 2021	SYSTEM	\$30,868.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 27 on the current Payment Estimate.												
																															2	20	20	20	Feb 1, 2021	SYSTEM	(\$30,868.25)										
																																						2'	21	21	21		20	Feb 1, 2021	SYSTEM	\$30,868.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
																																											21	2	2		
				21	Feb 16, 2021	SYSTEM	\$30,868.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 27 on the current Payment Estimate.																																							
				22	Mar 2, 2021	SYSTEM	(\$30,868.25)																																								

Revision 4/1/2020 Page 43 of 70



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
20	Boostipuo.:	Туре	Adjustment Type	Number	Date	Ву	7 41104111	·
0570	CURB BLOCKOUT	Material		22	Mar 2, 2021	SYSTEM	\$30,868.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
				23	Mar 16, 2021	SYSTEM	(\$30,868.25)	
				23	Mar 16, 2021	SYSTEM	\$30,868.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0570 -	- Total						\$0.00	
0580	HALF-SOLE REPAIR	Material		7	Jul 16, 2020	SYSTEM	(\$21,758.00)	
				7	Jul 16, 2020	SYSTEM	\$21,758.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 55 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$21,758.00)	
				8	Aug 3, 2020	SYSTEM	\$21,758.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 55 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$21,758.00)	
				9	Aug 18, 2020	SYSTEM	\$21,758.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 90 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$21,758.00)	
				10	Sep 3, 2020	SYSTEM	\$21,758.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 76 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$21,758.00)	
				11	Sep 16, 2020	SYSTEM	\$21,758.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 65 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0580 -	- Total						\$0.00	
0780	HALF-SOLE REPAIR	Material		11	Sep 16, 2020	SYSTEM	(\$2,577.84)	
				11	Sep 16, 2020	SYSTEM	\$2,577.84	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 56 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$14,607.76)	
				12	Oct 1, 2020	SYSTEM	\$14,607.76	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 44 on the current Payment Estimate.
				13	Oct 16, 2020	SYSTEM	(\$42,964.00)	
				13	Oct 16, 2020	SYSTEM	\$42,964.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 45 on the current Payment Estimate.
				14	Nov 2, 2020	SYSTEM	(\$42,964.00)	
				14	Nov 2, 2020	SYSTEM	\$42,964.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 46 on the current

Revision 4/1/2020 Page 44 of 70



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks									
0780	HALF-SOLE REPAIR	Material						Payment Estimate.									
				15	Nov 17, 2020	SYSTEM	(\$42,964.00)										
				15	Nov 17, 2020	SYSTEM	\$42,964.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 47 on the current Payment Estimate.									
				16	Dec 2, 2020	SYSTEM	(\$42,964.00)										
				16	Dec 2, 2020	SYSTEM	\$42,964.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 47 on the current Payment Estimate.									
				17	Dec 16, 2020	SYSTEM	(\$244,035.52)										
				17	Dec 16, 2020	SYSTEM	\$244,035.52	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 46 on the current Payment Estimate.									
				18	Jan 4, 2021	SYSTEM	(\$244,035.52)										
				18	Jan 4, 2021	SYSTEM	\$244,035.52	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 48 on the current Payment Estimate.									
			- Total				\$0.00										
	Material - Total						\$0.00										
0780 -	- Total						\$0.00										
0820	HALF-SOLE REPAIR	Material		11	Sep 16, 2020	SYSTEM	(\$3,007.48)										
				11	Sep 16, 2020	SYSTEM	\$3,007.48	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 66 on the current Payment Estimate.									
					12	Oct 1, 2020	SYSTEM	(\$42,964.00)									
				12	Oct 1, 2020	SYSTEM	\$42,964.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 48 on the current Payment Estimate.									
				13	Oct 16, 2020	SYSTEM	(\$42,964.00)										
				13	Oct 16, 2020	SYSTEM	\$42,964.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 49 on the current Payment Estimate.									
				14	Nov 2, 2020	SYSTEM	(\$42,964.00)										
				14	Nov 2, 2020	SYSTEM	\$42,964.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 50 on the current Payment Estimate.									
				15	Nov 17, 2020	SYSTEM	(\$42,964.00)										
							15	Nov 17, 2020	SYSTEM	\$42,964.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 51 on the current Payment Estimate.						
				16	Dec 2, 2020	SYSTEM	(\$42,964.00)										
													16	Dec 2, 2020	SYSTEM	\$42,964.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 51 on the current Payment Estimate.
													17	Dec 16, 2020	SYSTEM	(\$318,363.24)	
				17	Dec 16, 2020	SYSTEM	\$318,363.24	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 45 on the current Payment Estimate.									

Revision 4/1/2020 Page 45 of 70



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
0820	HALF-SOLE REPAIR	Material		18	Jan 4, 2021	SYSTEM	(\$318,363.24)		
				18	Jan 4, 2021	SYSTEM	\$318,363.24	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 49 on the current Payment Estimate.	
			- Total				\$0.00		
	Material - Total						\$0.00		
0820 -	· Total						\$0.00		
0850	MISC. PERMANENT AGGREGATE EDGE TREATMENT	Material		2	May 4, 2020	SYSTEM	(\$17,901.77)		
				2	May 4, 2020	SYSTEM	\$17,901.77	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
				3	May 19, 2020	SYSTEM	(\$42,591.62)		
				3	May 19, 2020	SYSTEM	\$42,591.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
				4	Jun 3, 2020	SYSTEM	(\$42,591.62)		
				4	Jun 3, 2020	SYSTEM	\$42,591.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
				5	Jun 16, 2020	SYSTEM	(\$42,591.62)		
					5	Jun 16, 2020	SYSTEM	\$42,591.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				6	Jul 2, 2020	SYSTEM	(\$42,591.62)		
				6	Jul 2, 2020	SYSTEM	\$42,591.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
				7	Jul 16, 2020	SYSTEM	(\$42,591.62)		
				7	Jul 16, 2020	SYSTEM	\$42,591.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
				8	Aug 3, 2020	SYSTEM	(\$42,591.62)		
				8	Aug 3, 2020	SYSTEM	\$42,591.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
				9	Aug 18, 2020	SYSTEM	(\$42,591.62)		
				9	Aug 18, 2020	SYSTEM	\$42,591.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
				10	Sep 3, 2020	SYSTEM	(\$48,392.79)		
				10	Sep 3, 2020	SYSTEM	\$48,392.79	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
				11	Sep 16, 2020	SYSTEM	(\$48,392.79)		
				11	Sep 16, 2020	SYSTEM	\$48,392.79	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
				12	Oct 1,	SYSTEM	(\$64,697.64)		

Revision 4/1/2020 Page 46 of 70



1.	5	A di	CII	F 4	0	0- 1	Δ.	
Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0850	MISC. PERMANENT AGGREGATE EDGE	Material			2020			
	TREATMENT			12	Oct 1, 2020	SYSTEM	\$64,697.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				13	Oct 16, 2020	SYSTEM	(\$64,697.64)	
				13	Oct 16, 2020	SYSTEM	\$64,697.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				14	Nov 2, 2020	SYSTEM	(\$64,697.64)	
				14	Nov 2, 2020	SYSTEM	\$64,697.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				15	Nov 17, 2020	SYSTEM	(\$64,697.64)	
				15	Nov 17, 2020	SYSTEM	\$64,697.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				16	Dec 2, 2020	SYSTEM	(\$64,697.64)	
				16	Dec 2, 2020	SYSTEM	\$64,697.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				17	Dec 16, 2020	SYSTEM	(\$64,697.64)	
				17	Dec 16, 2020	SYSTEM	\$64,697.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				18	Jan 4, 2021	SYSTEM	(\$64,697.64)	
				18	Jan 4, 2021	SYSTEM	\$64,697.64	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0850 -							\$0.00	
0870	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Other Item Adjustment	ACAD	2	May 4, 2020	woodsk1	\$460.98	
				17	Dec 16, 2020	woodsk1	\$8.06	*See Attached AC Price Index Adjustment Sheet.
			ACAD - Tota	al			\$469.04	
	Other Item Adjustment - Total						\$469.04	
0870 -	Total						\$469.04	
0880	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Material		2	May 4, 2020	SYSTEM	(\$456,638.72)	
				2	May 4, 2020	SYSTEM	\$456,638.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				3	May 19, 2020	SYSTEM	(\$456,638.72)	
				3	May 19, 2020	SYSTEM	\$456,638.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				4	Jun 3, 2020	SYSTEM	(\$456,638.72)	
				4	Jun 3, 2020	SYSTEM	\$456,638.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.

Revision 4/1/2020 Page 47 of 70



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0880	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Material		5	Jun 16, 2020	SYSTEM	(\$456,638.72)	
				5	Jun 16, 2020	SYSTEM	\$456,638.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				6	Jul 2, 2020	SYSTEM	(\$456,638.72)	
				6	Jul 2, 2020	SYSTEM	\$456,638.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$940,718.72)	
				7	Jul 16, 2020	SYSTEM	\$940,718.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$940,718.72)	
				8	Aug 3, 2020	SYSTEM	\$940,718.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$940,718.72)	
				9	Aug 18, 2020	SYSTEM	\$940,718.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$1,038,932.50)	
				10	Sep 3, 2020	SYSTEM	\$1,038,932.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$1,038,932.50)	
				11	Sep 16, 2020	SYSTEM	\$1,038,932.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Other Item Adjustment	ACAD	1	Apr 16, 2020	woodsk1	\$1,227.35	
				2	May 4, 2020	woodsk1	\$1,493.29	
				17	Dec 16, 2020	woodsk1	\$7.00	*See Attached AC Price Index Adjustment Sheet.
			ACAD - Tot	al			\$2,727.64	
	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)		BITM	8	Aug 3, 2020	woodsk1	\$66,845.91	TSR #001 Payment Adjustment. Lot #001 \$18,153.00
	76 22 (6. 1256 11114)				2020			TSR #002 Payment Adjustment. Lot #004 \$10,068.56
								Lot 1 Bonus Payment Adjustment \$12,102.00
								Lot 2 Bonus Payment Adjustment \$6,051.00
								Lot 3 Bonus Payment Adjustment \$12,102.00
								Lot 4 Bonus Payment Adjustment \$8,369.35
								Total Bituminous Pay Factor Adjustment For Line Item Posting #0880 \$66,845.91
			BITM - Tota	ı			\$66,845.91	
0000	Other Item Adjustment - Total						\$69,573.55	
	- Total	Motoric		1	Apr 10	CVCTCA	\$69,573.55	
0890	TACK COAT	Material		1	Apr 16, 2020	SYSTEM	(\$10,486.00)	

Revision 4/1/2020 Page 48 of 70



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
0890	TACK COAT	Material	.,,,,,	2	May 4, 2020	SYSTEM	(\$24,460.20)			
				2	May 4, 2020	SYSTEM	\$24,460.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.		
				3	May 19, 2020	SYSTEM	(\$24,460.20)			
				3	May 19, 2020	SYSTEM	\$24,460.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.		
				4	Jun 3, 2020	SYSTEM	(\$24,460.20)			
						4	Jun 3, 2020	SYSTEM	\$24,460.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
						5	Jun 16, 2020	SYSTEM	(\$24,460.20)	
						5	Jun 16, 2020	SYSTEM	\$24,460.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				6	Jul 2, 2020	SYSTEM	(\$24,460.20)			
				6	Jul 2, 2020	SYSTEM	\$24,460.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.		
						7	Jul 16, 2020	SYSTEM	(\$24,460.20)	
					7	Jul 16, 2020	SYSTEM	\$24,460.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	
					8	Aug 3, 2020	SYSTEM	(\$24,460.20)		
				8	Aug 3, 2020	SYSTEM	\$24,460.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.		
				9	Aug 18, 2020	SYSTEM	(\$24,460.20)			
				9	Aug 18, 2020	SYSTEM	\$24,460.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.		
				10	Sep 3, 2020	SYSTEM	(\$27,242.20)			
				10	Sep 3, 2020	SYSTEM	\$27,242.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.		
				11	Sep 16, 2020	SYSTEM	(\$27,242.20)			
				11	Sep 16, 2020	SYSTEM	\$27,242.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.		
			- Total				(\$10,486.00)			
	Material - Total						(\$10,486.00)			
	TACK COAT	MaterialCredit		2	May 4, 2020	SYSTEM	\$10,486.00			
			- Total				\$10,486.00			
	MaterialCredit - Total						\$10,486.00			
	TACK COAT	Other Item Adjustment	MDPA		Apr 16, 2020	woodsk1	\$10,486.00			
				2	May 4,	woodsk1	(\$10,486.00)	This adjustment is being added to balance line item 0890		

Revision 4/1/2020 Page 49 of 70



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
0890	TACK COAT	Other Item	MDPA		2020			discrepancy amount.				
		Adjustment	MDPA - Tota	al			\$0.00					
	Other Item Adjustment - Total						\$0.00					
0890 -	Total						\$0.00					
0900	BITUMINOUS FOG SEAL	Material		2	May 4, 2020	SYSTEM	(\$4,565.00)					
				2	May 4, 2020	SYSTEM	\$4,565.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.				
				3	May 19, 2020	SYSTEM	(\$8,436.95)					
				3	May 19, 2020	SYSTEM	\$8,436.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.				
				4	Jun 3, 2020	SYSTEM	(\$8,436.95)					
				4	Jun 3, 2020	SYSTEM	\$8,436.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.				
				5	Jun 16, 2020	SYSTEM	(\$8,436.95)					
				5	Jun 16, 2020	SYSTEM	\$8,436.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.				
				6	Jul 2, 2020	SYSTEM	(\$8,436.95)					
				6	Jul 2, 2020	SYSTEM	\$8,436.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.				
				7	Jul 16, 2020	SYSTEM	(\$8,436.95)					
				7	Jul 16, 2020	SYSTEM	\$8,436.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.				
				8	Aug 3, 2020	SYSTEM	(\$8,436.95)					
				8	Aug 3, 2020	SYSTEM	\$8,436.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.				
								9	Aug 18, 2020	SYSTEM	(\$8,436.95)	
					9	Aug 18, 2020	SYSTEM	\$8,436.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 29 on the current Payment Estimate.			
				10	Sep 3, 2020	SYSTEM	(\$10,511.95)					
					10	Sep 3, 2020	SYSTEM	\$10,511.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.			
				11	Sep 16, 2020	SYSTEM	(\$10,511.95)					
				11	Sep 16, 2020	SYSTEM	\$10,511.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.				
				12	Oct 1, 2020	SYSTEM	(\$19,920.00)					
				12	Oct 1, 2020	SYSTEM	\$19,920.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.				

Revision 4/1/2020 Page 50 of 70



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
0900	BITUMINOUS FOG SEAL	Material		13	Oct 16, 2020	SYSTEM	(\$19,920.00)		
				13	Oct 16, 2020	SYSTEM	\$19,920.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	
				14	Nov 2, 2020	SYSTEM	(\$19,920.00)		
				14	Nov 2, 2020	SYSTEM	\$19,920.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	
				15	Nov 17, 2020	SYSTEM	(\$19,920.00)		
				15	Nov 17, 2020	SYSTEM	\$19,920.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
				16	Dec 2, 2020	SYSTEM	(\$19,920.00)		
				16	Dec 2, 2020	SYSTEM	\$19,920.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
				17	Dec 16, 2020	SYSTEM	(\$19,920.00)		
				17	Dec 16, 2020	SYSTEM	\$19,920.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
					18	Jan 4, 2021	SYSTEM	(\$19,920.00)	
				18	Jan 4, 2021	SYSTEM	\$19,920.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
			- Total				\$0.00		
	Material - Total						\$0.00		
0900 -	Total						\$0.00		
0910	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	Material		4	Jun 3, 2020	SYSTEM	(\$1,000.00)		
				4	Jun 3, 2020	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
				5		SYSTEM	\$1,000.00 (\$1,000.00)	Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 7 on the current	
					2020 Jun 16,			Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 7 on the current	
				5	Jun 16, 2020 Jun 16,	SYSTEM	(\$1,000.00)	Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 7 on the current	
				5	Jun 16, 2020 Jun 16, 2020 Jul 2,	SYSTEM	(\$1,000.00) \$1,000.00	Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 7 on the current	
				5 5	Jun 16, 2020 Jun 16, 2020 Jul 2, 2020 Jul 2,	SYSTEM SYSTEM SYSTEM	(\$1,000.00) \$1,000.00 (\$1,000.00)	Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 7 on the current	
				5 5 6 6	2020 Jun 16, 2020 Jun 16, 2020 Jul 2, 2020 Jul 2, 2020 Jul 16,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,000.00) \$1,000.00 (\$1,000.00) \$1,000.00	Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 7 on the current	
				5 5 6 6	2020 Jun 16, 2020 Jun 16, 2020 Jul 2, 2020 Jul 2, 2020 Jul 16, 2020 Jul 16, 2020 Jul 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,000.00) \$1,000.00 (\$1,000.00) \$1,000.00	Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 7 on the current	
				5 5 6 6 7 7	2020 Jun 16, 2020 Jun 16, 2020 Jul 2, 2020 Jul 16, 2020 Jul 16, 2020 Aug 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,000.00) \$1,000.00 (\$1,000.00) \$1,000.00 (\$1,000.00)	Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 7 on the current	

Revision 4/1/2020 Page 51 of 70



Line	Description	Adjustment	Other Adjustment	Est. Number	Created	Created	Amount	Remarks													
		Туре	Type	Number	Date	Ву															
0910	TRUCK OR TRAILER MOUNTED	Material			2020																
	ATTENUATOR (TMA)			9	Aug 18, 2020	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overridding Payment Estimate Exception 31 on the current Payment Estimate.													
				10	Sep 3, 2020	SYSTEM	(\$1,000.00)														
				10	Sep 3, 2020	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.													
			- Total				\$0.00														
	Material - Total						\$0.00														
0910 -	· Total						\$0.00														
0920	CONSTRUCTION SIGNS	GNS Material		1	Apr 16, 2020	SYSTEM	(\$15,366.00)														
					2	May 4, 2020	SYSTEM	(\$15,366.00)													
				2	May 4, 2020	SYSTEM	\$15,366.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate.													
						3	May 19, 2020	SYSTEM	(\$15,366.00)												
					3	May 19, 2020	SYSTEM	\$15,366.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate.												
				4	Jun 3, 2020	SYSTEM	(\$15,366.00)														
				4	Jun 3, 2020	SYSTEM	\$15,366.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.													
				5	Jun 16, 2020	SYSTEM	(\$15,366.00)														
				5	Jun 16, 2020	SYSTEM	\$15,366.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.													
				6	Jul 2, 2020	SYSTEM	(\$15,366.00)														
						6	Jul 2, 2020	SYSTEM	\$15,366.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.											
																	7	Jul 16, 2020	SYSTEM	(\$15,366.00)	
						7	Jul 16, 2020	SYSTEM	\$15,366.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.											
								8	Aug 3, 2020	SYSTEM	(\$15,366.00)										
				8	Aug 3, 2020	SYSTEM	\$15,366.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.													
				9	Aug 18, 2020	SYSTEM	(\$15,366.00)														
				9	Aug 18, 2020	SYSTEM	\$15,366.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overridding Payment Estimate Exception 41 on the current Payment Estimate.													
				10	Sep 3, 2020	SYSTEM	(\$15,366.00)														
				10	Sep 3, 2020	SYSTEM	\$15,366.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user woodsk1 overridding Payment Estimate Exception 26 on the current Payment Estimate.													

Revision 4/1/2020 Page 52 of 70



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks											
0920		Material	- Total				(\$15,366.00)												
	Material - Total						(\$15,366.00)												
	CONSTRUCTION SIGNS	MaterialCredit		2	May 4, 2020	SYSTEM	\$15,366.00												
			- Total				\$15,366.00												
	MaterialCredit - Total						\$15,366.00												
	CONSTRUCTION SIGNS	Other Item Adjustment	MDPA	1	Apr 16, 2020	woodsk1	\$15,366.00												
				2	May 4, 2020	woodsk1	(\$15,366.00)	This adjustment is being added to balance line item 0920 discrepancy amount.											
			MDPA - Tot	al			\$0.00												
	Other Item Adjustment - Total						\$0.00												
0920 -	- Total						\$0.00												
0930	FLAG ASSEMBLY	Material		1	Apr 16, 2020	SYSTEM	(\$140.00)												
				2	May 4, 2020	SYSTEM	(\$140.00)												
									2	May 4, 2020	SYSTEM	\$140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 9 on the current Payment Estimate.						
				3	May 19, 2020	SYSTEM	(\$140.00)												
				3	May 19, 2020	SYSTEM	\$140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 9 on the current Payment Estimate.											
					4	Jun 3, 2020	SYSTEM	(\$140.00)											
					4	Jun 3, 2020	SYSTEM	\$140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 10 on the current Payment Estimate.										
										5	Jun 16, 2020	SYSTEM	(\$140.00)						
				5	Jun 16, 2020	SYSTEM	\$140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 10 on the current Payment Estimate.											
				6	Jul 2, 2020	SYSTEM	(\$140.00)												
				6	Jul 2, 2020	SYSTEM	\$140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.											
				7	Jul 16, 2020	SYSTEM	(\$140.00)												
															7	Jul 16, 2020	SYSTEM	\$140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$140.00)												
					8	Aug 3, 2020	SYSTEM	\$140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.										
				9	Aug 18, 2020	SYSTEM	(\$140.00)												
				9	Aug 18, 2020	SYSTEM	\$140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user woodsk1 overridding Payment Estimate Exception 42 on the current Payment Estimate.											
				10	Sep 3, 2020	SYSTEM	(\$140.00)												
					10	Sep 3, 2020	SYSTEM	\$140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user woodsk1 overridding Payment Estimate Exception 28 on the current										

Revision 4/1/2020 Page 53 of 70



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0930	FLAG ASSEMBLY	Material						Payment Estimate.
			- Total				(\$140.00)	
	Material - Total						(\$140.00)	
	FLAG ASSEMBLY	MaterialCredit		2	May 4, 2020	SYSTEM	\$140.00	
			- Total				\$140.00	
	MaterialCredit - Total						\$140.00	
	FLAG ASSEMBLY	Other Item Adjustment	MDPA	1	Apr 16, 2020	woodsk1	\$140.00	
				2	May 4, 2020	woodsk1	(\$140.00)	This adjustment is being added to balance line item 0180 discrepancy amount.
			MDPA - Tota	al			\$0.00	
	Other Item Adjustment - Total						\$0.00	
	·Total						\$0.00	
0940	CHANNELIZER (TRIM LINE)	Material		4	Jun 3, 2020	SYSTEM	(\$600.00)	
				4	Jun 3, 2020	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				5	Jun 16, 2020	SYSTEM	(\$600.00)	
				5	Jun 16, 2020	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				6	Jul 2, 2020	SYSTEM	(\$600.00)	
				6	Jul 2, 2020	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$600.00)	
				7	Jul 16, 2020	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$600.00)	
				8	Aug 3, 2020	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$600.00)	
				9	Aug 18, 2020	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user woodsk1 overridding Payment Estimate Exception 43 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$600.00)	
				10	Sep 3, 2020	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user woodsk1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0940 -	Total						\$0.00	
0950	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE CONTRACTOR	Material		1	Apr 16, 2020	SYSTEM	(\$7,000.00)	
	INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED			2	May 4, 2020	SYSTEM	(\$7,000.00)	
				2	May 4, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 14 on the current

Revision 4/1/2020 Page 54 of 70



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks		
LIIIO	Bessipaeri	Туре	Adjustment Type		Date	Ву	7 tillount	Tomano		
0950	CHANGEABLE MESSAGE SIGN	Material	Турс					Payment Estimate.		
0000	WITHOUT COMMUNICATION INTERFACE, CONTRACTOR	matorial		3	May 19,	SYSTEM	(\$7,000.00)	- aymon zounate.		
	FURNISHED, CONTRACTOR RETAINED				2020		(41,522122)			
				3	May 19, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.		
				4	Jun 3, 2020	SYSTEM	(\$7,000.00)			
				4	Jun 3, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.		
				5	Jun 16, 2020	SYSTEM	(\$7,000.00)			
						5	Jun 16, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
				6	Jul 2, 2020	SYSTEM	(\$7,000.00)			
				6	Jul 2, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 22 on the current Payment Estimate.		
				7	Jul 16, 2020	SYSTEM	(\$7,000.00)			
					7	Jul 16, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 23 on the current Payment Estimate.	
				8	Aug 3, 2020	SYSTEM	(\$7,000.00)			
				8	Aug 3, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overridding Payment Estimate Exception 23 on the current Payment Estimate.		
						9	Aug 18, 2020	SYSTEM	(\$7,000.00)	
				9	Aug 18, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user woodsk1 overridding Payment Estimate Exception 47 on the current Payment Estimate.		
				10	Sep 3, 2020	SYSTEM	(\$7,000.00)			
				10	Sep 3, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 33 on the current Payment Estimate.		
			- Total				(\$7,000.00)			
	Material - Total						(\$7,000.00)			
	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	MaterialCredit		2	May 4, 2020	SYSTEM	\$7,000.00			
			- Total				\$7,000.00			
	MaterialCredit - Total						\$7,000.00			
	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION	Other Item Adjustment	MDPA	1	Apr 16, 2020	woodsk1	\$7,000.00			
	INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED			2	May 4, 2020	woodsk1	(\$7,000.00)	This adjustment is being added to balance line item 0950 discrepancy amount.		
			MDPA - Tot	al			\$0.00			
	Other Item Adjustment - Total						\$0.00			
0950	- Total						\$0.00			
0960	WORK ZONE TRAFFIC SIGNAL SYSTEM	Material		4	Jun 3, 2020	SYSTEM	(\$8,400.00)			
					2020					

Revision 4/1/2020 Page 55 of 70



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks								
0960	WORK ZONE TRAFFIC SIGNAL SYSTEM	Material						overridding Payment Estimate Exception 17 on the current Payment Estimate.								
				5	Jun 16, 2020	SYSTEM	(\$8,400.00)									
				5	Jun 16, 2020	SYSTEM	\$8,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.								
				6	Jul 2, 2020	SYSTEM	(\$8,400.00)									
				6	Jul 2, 2020	SYSTEM	\$8,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overridding Payment Estimate Exception 23 on the current Payment Estimate.								
				7	Jul 16, 2020	SYSTEM	(\$8,400.00)									
				7	Jul 16, 2020	SYSTEM	\$8,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 25 on the current Payment Estimate.								
				8	Aug 3, 2020	SYSTEM	(\$8,400.00)									
				8	Aug 3, 2020	SYSTEM	\$8,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overridding Payment Estimate Exception 25 on the current Payment Estimate.								
				9	Aug 18, 2020	SYSTEM	(\$8,400.00)									
				9	Aug 18, 2020	SYSTEM	\$8,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user woodsk1 overridding Payment Estimate Exception 49 on the current Payment Estimate.								
				10	Sep 3, 2020	SYSTEM	(\$8,400.00)									
				10	Sep 3, 2020	SYSTEM	\$8,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0034) due to user woodsk1 overridding Payment Estimate Exception 35 on the current Payment Estimate.								
			- Total				\$0.00									
0060	Material - Total Total						\$0.00 \$0.00									
0970	TEMPORARY LONG-TERM RUMBLE STRIPS	Material		4	Jun 3, 2020	SYSTEM	(\$3,600.00)									
				4	Jun 3, 2020	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.								
										5	Jun 16, 2020	SYSTEM	(\$3,600.00)			
												5	Jun 16, 2020	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
															6	Jul 2, 2020
				6	Jul 2, 2020	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overridding Payment Estimate Exception 24 on the current Payment Estimate.								
				7	Jul 16, 2020	SYSTEM	(\$3,600.00)									
					7	Jul 16, 2020	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overridding Payment Estimate Exception 26 on the current Payment Estimate.							
				8	Aug 3, 2020	SYSTEM	(\$3,600.00)									
				8	Aug 3, 2020	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user woodsk1 overridding Payment Estimate Exception 26 on the current								

Revision 4/1/2020 Page 56 of 70



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks									
0970	TEMPORARY LONG-TERM RUMBLE	Material	Type					Payment Estimate.									
0370	STRIPS	Waterial		9	Aug 18, 2020	SYSTEM	(\$3,600.00)	r dynion Esundo.									
				9	Aug 18, 2020	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 50 on the current Payment Estimate.									
				10	Sep 3, 2020	SYSTEM	(\$3,600.00)										
				10	Sep 3, 2020	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0035) due to user woodsk1 overridding Payment Estimate Exception 36 on the current Payment Estimate.									
			- Total				\$0.00										
	Material - Total						\$0.00										
0970	- Total						\$0.00										
0990	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	Material		4	Jun 3, 2020	SYSTEM	(\$2,424.00)										
									4	Jun 3, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.				
						5	Jun 16, 2020	SYSTEM	(\$2,424.00)								
				5	Jun 16, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.									
				6	Jul 2, 2020	SYSTEM	(\$2,424.00)										
				6	Jul 2, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user woodsk1 overridding Payment Estimate Exception 25 on the current Payment Estimate.									
								7	Jul 16, 2020	SYSTEM	(\$2,424.00)						
				7	Jul 16, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overridding Payment Estimate Exception 27 on the current Payment Estimate.									
				8	Aug 3, 2020	SYSTEM	(\$2,424.00)										
				8	Aug 3, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user woodsk1 overridding Payment Estimate Exception 27 on the current Payment Estimate.									
								\$					9	Aug 18, 2020	SYSTEM	(\$2,424.00)	
												9	Aug 18, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0034) due to user woodsk1 overridding Payment Estimate Exception 51 on the current Payment Estimate.	
							10	Sep 3, 2020	SYSTEM	(\$2,424.00)							
													10	Sep 3, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0036) due to user woodsk1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$2,424.00)										
				11	Sep 16, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 25 on the current Payment Estimate.									
				12	Oct 1, 2020	SYSTEM	(\$2,424.00)										
							12	Oct 1, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.						

Revision 4/1/2020 Page 57 of 70



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
0990	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	Material		13	Oct 16, 2020	SYSTEM	(\$2,424.00)					
				13	Oct 16, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.				
				14	Nov 2, 2020	SYSTEM	(\$2,424.00)					
				14	Nov 2, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.				
				15	Nov 17, 2020	SYSTEM	(\$2,424.00)					
				15	Nov 17, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.				
				16	Dec 2, 2020	SYSTEM	(\$2,424.00)					
				16	Dec 2, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.				
				17	Dec 16, 2020	SYSTEM	(\$2,424.00)					
				17	Dec 16, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.				
				18	Jan 4, 2021	SYSTEM	(\$2,424.00)					
				18	Jan 4, 2021	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.				
			- Total				\$0.00					
0990	Material - Total - Total						\$0.00 \$0.00					
1000	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	Material		4	Jun 3, 2020	SYSTEM	(\$4,000.00)					
				4	Jun 3, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 20 on the current Payment Estimate.				
				5	Jun 16, 2020	SYSTEM	(\$4,000.00)					
				5	Jun 16, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 20 on the current Payment Estimate.				
				6	Jul 2, 2020	SYSTEM	(\$4,000.00)					
								6	Jul 2, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user woodsk1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$4,000.00)					
				7	Jul 16, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user woodsk1 overridding Payment Estimate Exception 28 on the current Payment Estimate.				
				8	Aug 3, 2020	SYSTEM	(\$4,000.00)					
				8	Aug 3, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user woodsk1 overridding Payment Estimate Exception 28 on the current Payment Estimate.				
				9	Aug 18,	SYSTEM	(\$4,000.00)					

Revision 4/1/2020 Page 58 of 70



The Part Cream Promoted Program Part Cream Program Part Part Par	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks											
9	1000		Material			2020														
10		TAPE 4 IN., YELLOW			9		SYSTEM	\$4,000.00	Payment Estimate Item Adjustment (0035) due to user woodsk1 overridding Payment Estimate Exception 52 on the current											
Payment Estimate them Aglijustiment (0027) due to user woodskill operated (0027) and the outlet of Septimal Payment Estimate Exception 38 on the outlet of Septimal Payment Estimate Exception 38 on the outlet of Septimal Payment Estimate Exception 38 on the outlet of Septimal Payment Estimate Exception 38 on the outlet of Septimal Payment Estimate Exception 38 on the outlet of Septimal Payment Estimate Exception 38 on the outlet of Septimal Payment Estimate Inter Aglijustiment (0027) due to user woodskill operated and the payment Estimate Inter Aglijustiment (0027) due to user woodskill operated payment Estimate Inter Aglijustiment (0027) due to user woodskill operated payment Estimate Inter Aglijustiment (0027) due to user woodskill operated payment Estimate Inter Aglijustiment (0027) due to user woodskill operated payment Estimate Inter Aglijustiment (0027) due to user woodskill operated payment Estimate Inter Aglijustiment (0027) due to user woodskill operated payment Estimate Inter Aglijustiment (0027) due to user woodskill operated payment Estimate Inter Aglijustiment (0027) due to user woodskill operated payment Estimate Inter Aglijustiment (0027) due to user woodskill operated payment Estimate Inter Aglijustiment (0027) due to user woodskill operated payment Internated					10		SYSTEM	(\$4,000.00)												
11					10		SYSTEM	\$4,000.00	Payment Estimate Item Adjustment (0037) due to user woodsk1 overridding Payment Estimate Exception 38 on the current											
2020 Payment Estimate Exception 20 part to the current 2027 jule to user woodst					11		SYSTEM	(\$4,000.00)												
12					11		SYSTEM	\$4,000.00	Payment Estimate Item Adjustment (0027) due to user woodsk1 overridding Payment Estimate Exception 26 on the current											
2000 Payment Estimate Item Adjustment (0023) due to user woodskt overridding Payment Estimate Exception 14 on the current Payment Estimate Exception 15 on the current Payment Estimate Exception 15 on the current Payment Estimate Estimate Exception 15 on the current Payment Estimate Estimate Exception 15 on the current Payment Estimate Estimate Exception 16 on the current Payment Estimate Estimate Exception 16 on the current Payment Estimate Estimate Exception 16 on the current Payment Estimate Estimate Exception 17 on the current Payment Estimate Estimate Exception 17 on the current Payment Estimate Exception 18 on the current Payment Estimate Exception 18 on the current Payment Estimate Exception 19 on the current Payment Esti					12		SYSTEM	(\$4,000.00)												
13					12		SYSTEM	\$4,000.00	Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 14 on the current											
2020 Payment Estimate Item Adjustment (0021) due to user woodskit overridding Payment Estimate Exception 15 on the current Payment Estimate Exception 15 on the current Payment Estimate Exception 15 on the current Payment Estimate Item Adjustment (0025) due to user woodskit overridding Payment Estimate Item Adjustment (0025) due to user woodskit overridding Payment Estimate Exception 16 on the current Payment Estimate Item Adjustment (0025) due to user woodskit overridding Payment Estimate Item Adjustment (0025) due to user woodskit overridding Payment Estimate Item Adjustment (0025) due to user woodskit overridding Payment Estimate Item Adjustment (0021) due to user woodskit overridding Payment Estimate Item Adjustment (0021) due to user woodskit overridding Payment Estimate Item Adjustment (0021) due to user woodskit overridding Payment Estimate Item Adjustment (0021) due to user woodskit overridding Payment Estimate Item Adjustment (0021) due to user woodskit overridding Payment Estimate Item Adjustment (0021) due to user woodskit overridding Payment Estimate Item Adjustment (0023) due to user woodskit overridding Payment Estimate Item Adjustment (0023) due to user woodskit overridding Payment Estimate Item Adjustment (0023) due to user woodskit overridding Payment Estimate Item Adjustment (0023) due to user woodskit overridding Payment Estimate Item Adjustment (0023) due to user woodskit overridding Payment Estimate Item Adjustment (0023) due to user woodskit overridding Payment Estimate Item Adjustment (0023) due to user woodskit overridding Payment Estimate Item Adjustment (0023) due to user woodskit overridding Payment Estimate Item Adjustment (0023) due to user woodskit overridding Payment Estimate Item Adjustment (0023) due to user woodskit overridding Payment Estimate Item Adjustment (0023) due to user woodskit overridding Payment Estimate Item Adjustment (013) due to user woodskit overridding Payment Estimate Item Adjustment (013) due to user woodskit overridding Payment Estimate Item Adjustment (13		SYSTEM	(\$4,000.00)												
14					13		SYSTEM	\$4,000.00	Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 15 on the current											
2020 Payment Estimate Item Adjustment (0025) due to user woodsk1							14		SYSTEM	(\$4,000.00)										
15						14		SYSTEM	\$4,000.00	Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 16 on the current										
2020 Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Pay					15		SYSTEM	(\$4,000.00)												
16					15		SYSTEM	\$4,000.00	Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 17 on the current											
2020 Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate Exception 21 on the current Pay							16		SYSTEM	(\$4,000.00)										
17						16		SYSTEM	\$4,000.00	Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 17 on the current										
2020 Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.																17		SYSTEM	(\$4,000.00)	
2021 18 Jan 4, 2021 \$4,000.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate. - Total \$0.00 Material - Total \$0.00 1000 - Total \$0.00 TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE 4 Jun 3, 2020 4 Jun 3, 2020 4 Jun 3, 2020 5 Jun 16, SYSTEM \$240.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estim								17		SYSTEM	\$4,000.00	Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 15 on the current								
Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate. - Total S0.00 Material - Total S0.00 TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE 4 Jun 3, 2020 4 Jun 3, 2020 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate. 5 Jun 16, SYSTEM (\$240.00)								18		SYSTEM	(\$4,000.00)									
Material - Total \$0.00							18		SYSTEM	\$4,000.00	Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 15 on the current									
1000 - Total TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE 4 Jun 3, 2020 4 Jun 3, 2020 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate. 5 Jun 16, SYSTEM (\$240.00)				- Total				\$0.00												
TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE 4 Jun 3, 2020 4 Jun 3, 2020 5 Jun 16, SYSTEM (\$240.00) 1010 TEMPORARY REMOVABLE MARKING (\$240.00) This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate.	1000																			
4 Jun 3, 2020 SYSTEM \$240.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate. 5 Jun 16, SYSTEM (\$240.00)		TEMPORARY REMOVABLE MARKING	Material		4		SYSTEM													
5 Jun 16, SYSTEM (\$240.00)					4	Jun 3,	SYSTEM	\$240.00	Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 21 on the current											
					5		SYSTEM	(\$240.00)	,											

Revision 4/1/2020 Page 59 of 70



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks								
1010	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	Material		5	Jun 16, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate.								
				6	Jul 2, 2020	SYSTEM	(\$240.00)									
				6	Jul 2, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 27 on the current Payment Estimate.								
				7	Jul 16, 2020	SYSTEM	(\$240.00)									
				7	Jul 16, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user woodsk1 overridding Payment Estimate Exception 29 on the current Payment Estimate.								
				8	Aug 3, 2020	SYSTEM	(\$240.00)									
				8	Aug 3, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 29 on the current Payment Estimate.								
				9	Aug 18, 2020	SYSTEM	(\$240.00)									
				9	Aug 18, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0036) due to user woodsk1 overridding Payment Estimate Exception 53 on the current Payment Estimate.								
				10	Sep 3, 2020	SYSTEM	(\$240.00)									
				10	Sep 3, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 39 on the current Payment Estimate.								
				11	Sep 16, 2020	SYSTEM	(\$240.00)									
				11	Sep 16, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 27 on the current Payment Estimate.								
				12	Oct 1, 2020	SYSTEM	(\$240.00)									
				12	Oct 1, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.								
				13	Oct 16, 2020	SYSTEM	(\$240.00)									
				13	Oct 16, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.								
				14	Nov 2, 2020	SYSTEM	(\$240.00)									
												14	Nov 2, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
				15	Nov 17, 2020	SYSTEM	(\$240.00)									
				15	Nov 17, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.								
				16	Dec 2, 2020	SYSTEM	(\$240.00)									
				16	Dec 2, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.								
				17	Dec 16, 2020	SYSTEM	(\$240.00)									

Revision 4/1/2020 Page 60 of 70



Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
1010	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	Material	Туре	17	Dec 16, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
				18	Jan 4, 2021	SYSTEM	(\$240.00)	
			18	Jan 4, 2021	SYSTEM	\$240.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	
			- Total				\$0.00	
	Material - Total						\$0.00	
1010 -	Total						\$0.00	
1020	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P	Material		3	May 19, 2020	SYSTEM	(\$6,270.00)	
	BEADS			3	May 19, 2020	SYSTEM	\$6,270.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
				4	Jun 3, 2020	SYSTEM	(\$6,270.00)	
				4	Jun 3, 2020	SYSTEM	\$6,270.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
				5	Jun 16, 2020	SYSTEM	(\$6,270.00)	
				5	Jun 16, 2020	SYSTEM	\$6,270.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
				6	Jul 2, 2020	SYSTEM	(\$6,270.00)	
				6	Jul 2, 2020	SYSTEM	\$6,270.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user woodsk1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$6,270.00)	
				7	Jul 16, 2020	SYSTEM	\$6,270.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user woodsk1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$6,270.00)	
				8	Aug 3, 2020	SYSTEM	\$6,270.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user woodsk1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$6,270.00)	
				9	Aug 18, 2020	SYSTEM	\$6,270.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0037) due to user woodsk1 overridding Payment Estimate Exception 54 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$12,574.32)	
				10	Sep 3, 2020	SYSTEM	\$12,574.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0038) due to user woodsk1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$12,574.32)	
				11	Sep 16, 2020	SYSTEM	\$12,574.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$12,574.32)	
				12	Oct 1,	SYSTEM	\$12,574.32	This adjustment offsets the original system-generated Overrun

Revision 4/1/2020 Page 61 of 70



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1020	20 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			2020			Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
				13	Oct 16, 2020	SYSTEM	(\$12,574.32)	
				13	Oct 16, 2020	SYSTEM	\$12,574.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
				14	Nov 2, 2020	SYSTEM	(\$12,574.32)	
				14	Nov 2, 2020	SYSTEM	\$12,574.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
				15	Nov 17, 2020	SYSTEM	(\$12,574.32)	
				15	Nov 17, 2020	SYSTEM	\$12,574.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
				16	Dec 2, 2020	SYSTEM	(\$12,574.32)	
				16	Dec 2, 2020	SYSTEM	\$12,574.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
				17	Dec 16, 2020	SYSTEM	(\$12,574.32)	
				17	Dec 16, 2020	SYSTEM	\$12,574.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
				18	Jan 4, 2021	SYSTEM	(\$12,574.32)	
				18	Jan 4, 2021	SYSTEM	\$12,574.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total 4 IN, WHITE STANDARD WATERBORNE	Other Item	REFL	10	Sep 3,	woodsk1	\$0.00 \$153.21	Yellow:
	PAVEMENT MARKING PAINT, TYPE P BEADS	Adjustment	KLIL	10	2020	WOOUSKI	ψ133.21	63.78% @ 105 = (102,369 x .6378) = (65,290.9' @ 105% Pay Adjustment) = (65,290.9 x .0055) = \$359.10
								32.14% @ 100 = (102,369 x .3214) = (32,901.4' @ 100% Pay) *(Also Includes 2nd Mobilization & Application)
								4.08% @ 80 = (102,369 x .0408) = (4,176.7' @ 80% Pay Adjustment) = (4,176.7 x .088) = -\$91.89
								Total Adjustment = \$267.21
								White:
								92.28%@ 105 = (30,488 x .9228) = (28,134.3' @ 105% Pay
								Adjustment) = (28,134.3 x .0055) = \$154.74 7.2%@ 100 = (30,488 x .0720) = (2,195.1* @ 100% Pay)
								*(Also Includes 2nd Mobilization & Application) 0.52%@80 = (30,488 x .0052) = (158.5' @ 80% Pay
								Adjustment) = (158.5 x .088) = -\$1.53
								Total Adjustment = \$153.21

Revision 4/1/2020 Page 62 of 70



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
1020		Other Item Adjustment						* Remaining Quantity From 2nd Mobilization & Application Paid @ 100%		
			REFL - Tota	ıl			\$153.21			
	Other Item Adjustment - Total						\$153.21			
1020 -	Total						\$153.21			
1030	WATERBORNE PAVEMENT MARKING	Material		3	May 19, 2020	SYSTEM	(\$1,760.00)			
	PAINT, TYPE P BEADS			3	May 19, 2020	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.		
				4	Jun 3, 2020	SYSTEM	(\$1,760.00)			
				4	Jun 3, 2020	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overridding Payment Estimate Exception 24 on the current Payment Estimate.		
				5	Jun 16, 2020	SYSTEM	(\$1,760.00)			
				5	Jun 16, 2020	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 24 on the current Payment Estimate.		
				6	Jul 2, 2020	SYSTEM	(\$1,760.00)			
				6	Jul 2, 2020	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user woodsk1 overridding Payment Estimate Exception 30 on the current Payment Estimate.		
				7	Jul 16, 2020	SYSTEM	(\$1,760.00)			
				7	Jul 16, 2020	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.		
						8	Aug 3, 2020	SYSTEM	(\$1,760.00)	
				8	Aug 3, 2020	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.		
				9	Aug 18, 2020	SYSTEM	(\$1,760.00)			
				9	Aug 18, 2020	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0038) due to user woodsk1 overridding Payment Estimate Exception 56 on the current Payment Estimate.		
				10	Sep 3, 2020	SYSTEM	(\$3,519.89)			
				10	Sep 3, 2020	SYSTEM	\$3,519.89	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0039) due to user woodsk1 overridding Payment Estimate Exception 42 on the current Payment Estimate.		
				11	Sep 16, 2020	SYSTEM	(\$3,519.89)			
				11	Sep 16, 2020	SYSTEM	\$3,519.89	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user woodsk1 overridding Payment Estimate Exception 30 on the current Payment Estimate.		
				12	Oct 1, 2020	SYSTEM	(\$3,519.89)			
				12	Oct 1, 2020	SYSTEM	\$3,519.89	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.		
				13	Oct 16, 2020	SYSTEM	(\$3,519.89)			
				13	Oct 16, 2020	SYSTEM	\$3,519.89	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 19 on the current		

Revision 4/1/2020 Page 63 of 70



Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
			Type					
1030	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING	Material					(44 - 14 - 44)	Payment Estimate.
	PAINT, TYPE P BEADS			14	Nov 2, 2020	SYSTEM	(\$3,519.89)	
				14	Nov 2, 2020	SYSTEM	\$3,519.89	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
				15	Nov 17, 2020	SYSTEM	(\$3,519.89)	
				15	Nov 17, 2020	SYSTEM	\$3,519.89	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
				16	Dec 2, 2020	SYSTEM	(\$3,519.89)	
				16	Dec 2, 2020	SYSTEM	\$3,519.89	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
				17	Dec 16, 2020	SYSTEM	(\$3,519.89)	
				17	Dec 16, 2020	SYSTEM	\$3,519.89	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
				18	Jan 4, 2021	SYSTEM	(\$3,519.89)	
				18	Jan 4, 2021	SYSTEM	\$3,519.89	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Other Item Adjustment	REFL	10	Sep 3, 2020	woodsk1	\$267.21	Yellow: 63.78% @ 105 = (102,369 x .6378) = (65,290.9' @ 105%
								Pay Adjustment) = (65,290.9 x .0055) = \$359.10 32.14% @ 100 = (102,369 x .3214) = (32,901.4' @ 100%
								Pay) *(Also Includes 2nd Mobilization & Application) 4.08% @ 80 = (102,369 x .0408) = (4,176.7' @ 80% Pay
								Adjustment) = (4,176.7 x .088) = -\$91.89
								Total Adjustment = \$267.21
								White:
								92.28%@ 105 = (30,488 x .9228) = (28,134.3' @ 105% Pay Adjustment) = (28,134.3 x .0055) = \$154.74
								7.2%@ 100 = (30,488 x .0720) = (2,195.1' @ 100% Pay) *(Also Includes 2nd Mobilization & Application)
								0.52%@80 = (30,488 x .0052) = (158.5' @ 80% Pay Adjustment) = (158.5 x .088) = -\$1.53
								Total Adjustment = \$153.21
								* Remaining Quantity From 2nd Mobilization & Application Paid @ 100%
			REFL - Tota	ıl			\$267.21	
4000	Other Item Adjustment - Total						\$267.21	
1030 -	Total MGS GUARDRAIL	Construction		1	Apr 16,	SYSTEM	\$267.21 \$1,493.80	Payment Estimate Item Adjustment generated Stockpile
1000	MGS GUARDRAIL	CONSTRUCTION		1	Αрι 10,	SISIEIVI	φ1,493.00	r ayment Estimate item Adjustment generated Stockpile

Revision 4/1/2020 Page 64 of 70



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
		Туре	Adjustment Type	Number	Date	Ву		
1080	MGS GUARDRAIL	Stockpile			2020			Transaction
				8	Aug 3, 2020	SYSTEM	(\$1,493.80)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
	· Total						\$0.00	
1090	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	Construction Stockpile		1	Apr 16, 2020	SYSTEM	\$5,996.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				8	Aug 3, 2020	SYSTEM	(\$5,996.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
1090 -	Total						\$0.00	
1100	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		1	Apr 16, 2020	SYSTEM	\$6,040.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				8	Aug 3, 2020	SYSTEM	(\$6,040.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
1100 -	·Total						\$0.00	
1130	EMULSIFIED ASPHALT, SEAL COAT	Material		9	Aug 18, 2020	SYSTEM	(\$575.00)	
				9	Aug 18, 2020	SYSTEM	\$575.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0039) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$575.00)	
				10	Sep 3, 2020	SYSTEM	\$575.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0040) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$575.00)	
				11	Sep 16, 2020	SYSTEM	\$575.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	EMULSIFIED ASPHALT, SEAL COAT	Other Item Adjustment	ACAD	19	Jan 20, 2021	woodsk1	(\$20.97)	AC Seal Coat Adjustment. August 10th, 2020 placement date.
			ACAD - Tota	al			(\$20.97)	
	Other Item Adjustment - Total						(\$20.97)	
1130 -	· Total						(\$20.97)	
1140	SEAL COAT AGGREGATE, GRADE B1	Material		9	Aug 18, 2020	SYSTEM	(\$1,435.00)	
				9	Aug 18, 2020	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0040) due to user woodsk1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$1,435.00)	
				10	Sep 3, 2020	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0041) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$1,435.00)	
				11	Sep 16, 2020	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				12	Oct 1,	SYSTEM	(\$1,435.00)	

Revision 4/1/2020 Page 65 of 70



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																		
1140	SEAL COAT AGGREGATE, GRADE B1	Material			2020																					
				12	Oct 1, 2020	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.																		
				13	Oct 16, 2020	SYSTEM	(\$1,435.00)																			
				13	Oct 16, 2020	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.																		
				14	Nov 2, 2020	SYSTEM	(\$1,435.00)																			
				14	Nov 2, 2020	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.																		
				15	Nov 17, 2020	SYSTEM	(\$1,435.00)																			
				15	Nov 17, 2020	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.																		
				16	Dec 2, 2020	SYSTEM	(\$1,435.00)																			
				16	Dec 2, 2020	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.																		
					17	Dec 16, 2020	SYSTEM	(\$1,435.00)																		
				17	Dec 16, 2020	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.																		
				18	Jan 4, 2021	SYSTEM	(\$1,435.00)																			
				18	Jan 4, 2021	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user woodsk1 overridding Payment Estimate Exception 6 on the current Payment Estimate.																		
				19	Jan 20, 2021	SYSTEM	(\$1,435.00)																			
				19	Jan 20, 2021	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 6 on the current Payment Estimate.																		
				20	Feb 1, 2021	SYSTEM	(\$1,435.00)																			
				20	Feb 1, 2021	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 6 on the current Payment Estimate.																		
				21	Feb 16, 2021	SYSTEM	(\$1,435.00)																			
				21	Feb 16, 2021	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 6 on the current Payment Estimate.																		
				22	Mar 2, 2021	SYSTEM	(\$1,435.00)																			
				22	Mar 2, 2021	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 6 on the current Payment Estimate.																		
																	;						23	Mar 16, 2021	SYSTEM	(\$1,435.00)
				23	Mar 16, 2021	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 6 on the current Payment Estimate.																		

Revision 4/1/2020 Page 66 of 70



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1140		Material	- Total				\$0.00	
	Material - Total						\$0.00	
1140 -	Total						\$0.00	
1150	150 SUPERSTRUCTURE REPAIR (UNFORMED)	Material		6	Jul 2, 2020	SYSTEM	(\$3,111.60)	
				6	Jul 2, 2020	SYSTEM	\$3,111.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 44 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$6,223.20)	
				7	Jul 16, 2020	SYSTEM	\$6,223.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 46 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$6,223.20)	
				8	Aug 3, 2020	SYSTEM	\$6,223.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0036) due to user woodsk1 overridding Payment Estimate Exception 46 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$6,223.20)	
				9	Aug 18, 2020	SYSTEM	\$6,223.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0041) due to user woodsk1 overridding Payment Estimate Exception 81 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$6,223.20)	
				10	Sep 3, 2020	SYSTEM	\$6,223.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0042) due to user woodsk1 overridding Payment Estimate Exception 67 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$6,223.20)	
				11	Sep 16, 2020	SYSTEM	\$6,223.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user woodsk1 overridding Payment Estimate Exception 55 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$9,645.96)	
				12	Oct 1, 2020	SYSTEM	\$9,645.96	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overridding Payment Estimate Exception 43 on the current Payment Estimate.
				13	Oct 16, 2020	SYSTEM	(\$9,645.96)	
				13	Oct 16, 2020	SYSTEM	\$9,645.96	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 44 on the current Payment Estimate.
				14	Nov 2, 2020	SYSTEM	(\$9,645.96)	
				14	Nov 2, 2020	SYSTEM	\$9,645.96	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user woodsk1 overridding Payment Estimate Exception 45 on the current Payment Estimate.
				15	Nov 17, 2020	SYSTEM	(\$9,645.96)	
				15	Nov 17, 2020	SYSTEM	\$9,645.96	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overridding Payment Estimate Exception 46 on the current Payment Estimate.
				16	Dec 2, 2020	SYSTEM	(\$9,645.96)	
				16	Dec 2, 2020	SYSTEM	\$9,645.96	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overridding Payment Estimate Exception 46 on the current Payment Estimate.
				17	Dec 16,	SYSTEM	(\$9,645.96)	

Revision 4/1/2020 Page 67 of 70



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks														
1150	SUPERSTRUCTURE REPAIR	Material			2020																	
	(UNFORMED)			17	Dec 16, 2020	SYSTEM	\$9,645.96	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overridding Payment Estimate Exception 44 on the current Payment Estimate.														
				18	Jan 4, 2021	SYSTEM	(\$9,645.96)															
				18	Jan 4, 2021	SYSTEM	\$9,645.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user woodsk1 overridding Payment Estimate Exception 44 on the current Payment Estimate.														
			- Total				\$0.00															
	Material - Total						\$0.00															
1150	- Total						\$0.00															
1160	SLAB EDGE REPAIR (BRIDGES)	Material		5	Jun 16, 2020	SYSTEM	(\$7,361.70)															
				5	Jun 16, 2020	SYSTEM	\$7,361.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 40 on the current Payment Estimate.														
				6	Jul 2, 2020	SYSTEM	(\$7,361.70)															
				6	Jul 2, 2020	SYSTEM	\$7,361.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0034) due to user woodsk1 overridding Payment Estimate Exception 52 on the current Payment Estimate.														
				7	Jul 16, 2020	SYSTEM	(\$14,723.40)															
				7	Jul 16, 2020	SYSTEM	\$14,723.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0034) due to user woodsk1 overridding Payment Estimate Exception 56 on the current Payment Estimate.														
				8	Aug 3, 2020	SYSTEM	(\$14,723.40)															
				8	Aug 3, 2020	SYSTEM	\$14,723.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0037) due to user woodsk1 overridding Payment Estimate Exception 56 on the current Payment Estimate.														
				9	Aug 18, 2020	SYSTEM	(\$14,723.40)															
				9	Aug 18, 2020	SYSTEM	\$14,723.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0042) due to user woodsk1 overridding Payment Estimate Exception 91 on the current Payment Estimate.														
				10	Sep 3, 2020	SYSTEM	(\$14,723.40)															
				10	Sep 3, 2020	SYSTEM	\$14,723.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0043) due to user woodsk1 overridding Payment Estimate Exception 77 on the current Payment Estimate.														
				11	Sep 16, 2020	SYSTEM	(\$14,723.40)															
																			11	Sep 16, 2020	SYSTEM	\$14,723.40
				12	Oct 1, 2020	SYSTEM	(\$14,723.40)															
				12	Oct 1, 2020	SYSTEM	\$14,723.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user woodsk1 overridding Payment Estimate Exception 54 on the current Payment Estimate.														
				13	Oct 16, 2020	SYSTEM	(\$14,723.40)															
				13	Oct 16, 2020	SYSTEM	\$14,723.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overridding Payment Estimate Exception 55 on the current Payment Estimate.														
				14	Nov 2, 2020	SYSTEM	(\$14,723.40)															

Revision 4/1/2020 Page 68 of 70



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1160	SLAB EDGE REPAIR (BRIDGES)	Material	Турс	14	Nov 2, 2020	SYSTEM	\$14,723.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user woodsk1 overridding Payment Estimate Exception 56 on the current Payment Estimate.
				15	Nov 17, 2020	SYSTEM	(\$14,723.40)	
				15	Nov 17, 2020	SYSTEM	\$14,723.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overridding Payment Estimate Exception 57 on the current Payment Estimate.
				16	Dec 2, 2020	SYSTEM	(\$14,723.40)	
				16	Dec 2, 2020	SYSTEM	\$14,723.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overridding Payment Estimate Exception 57 on the current Payment Estimate.
				17	Dec 16, 2020	SYSTEM	(\$14,723.40)	
				17	Dec 16, 2020	SYSTEM	\$14,723.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user woodsk1 overridding Payment Estimate Exception 57 on the current Payment Estimate.
				18	Jan 4, 2021	SYSTEM	(\$14,723.40)	
				18	Jan 4, 2021	SYSTEM	\$14,723.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user woodsk1 overridding Payment Estimate Exception 57 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	Total						\$0.00	
1180	BRIDGE GUARDRAIL (THRIE BEAM)	Construction Stockpile		2	May 4, 2020	SYSTEM	\$29,370.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				6	Jul 2, 2020	SYSTEM	(\$14,685.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				8	Aug 3, 2020	SYSTEM	(\$14,685.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
1180 -							\$0.00	
5004	SLAB EDGE REPAIR (BRIDGES)	Material		17	Dec 16, 2020	SYSTEM	(\$5,398.58)	
				17	Dec 16, 2020	SYSTEM	\$5,398.58	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 55 on the current Payment Estimate.
				18	Jan 4, 2021	SYSTEM	(\$5,398.58)	
				18	Jan 4, 2021	SYSTEM	\$5,398.58	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 56 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
5004 -							\$0.00	
5005	SLAB EDGE REPAIR (BRIDGES)	Material		17	Dec 16, 2020	SYSTEM	(\$7,607.09)	
				17	Dec 16, 2020	SYSTEM	\$7,607.09	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 56 on the current Payment Estimate.
				18	Jan 4, 2021	SYSTEM	(\$7,607.09)	
				18	Jan 4, 2021	SYSTEM	\$7,607.09	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 55 on the current Payment Estimate.

Revision 4/1/2020 Page 69 of 70



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
5005		Material	- Total				\$0.00	
	Material - Total						\$0.00	
5005 -	· Total				\$0.00			
Overa	ıll - Total				\$87,921.44			

Revision 4/1/2020 Page 70 of 70