

Pay Estimate Created Date: June 16, 2021

\$8,709,119.25 \$1,421,791.48 \$10,130,910.73	• •	Pay Period Start June 2, 2 Pay Period End June 15,	200117-H07 Apex Paving Co.	Contract ID Prime Contractor	Progress Estimate Number 29			
By User						Approval Date		
woodsk	Oraft) at the Project Office Level by	Generated and Approved (and should be considered Draft) at the Project Office Level by						
bollis	at the Resident Engineer Level by	d (and should be considered D	riewed and Approve	Rev		June 17, 2021		
greggd	l Office Controllers Office Level by	viewed and Approved at the Ce	Re			June 21, 2021		
ınt Complete	% of Current Contract Amo	Actual Completion Date	etion Date	Current Comple	pletion Date	Original Comp		
	77 58%		2021	September 7	2021	July 1.2		

	Contract Informational Dates								
Date Description	Original Completion Date	<b>Current Completion Date</b>	No Milestones Exist for Contract						
Acceptance Date									
Awarded Date	February 5, 2020	February 5, 2020							
Letting Date	January 17, 2020	January 17, 2020							
Notice to Proceed Date	April 6, 2020	April 6, 2020							
Open to Traffic Date									
Work Began Date									

Contract Total Pay For Estimate No. 29										
		This Estimate	Previous	To Date						
200117-H07										
	Total Posted Items Pay	\$725,450.48	\$7,134,097.74	\$7,859,548.22						
	Gross Item Adjustments	\$4,081.37	\$121,278.87	\$125,360.24						
	Incentive	\$0.00	\$0.00	\$0.00						
	Disincentive	\$0.00	\$0.00	\$0.00						
	Liquidated Damage	\$0.00	\$0.00	\$0.00						
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00						
	•		\$7,255,376.61	\$7,984,908.46						
Contract Total Pavable This Estimate:		\$729.531.85								

#### **Items Paid This Estimate Period**

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J9I3553	0040	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	TONS	\$56.390	1,654	\$93,269.06
	0050	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	TONS	\$57.840	6,261.8	\$362,182.51
	0060	4071005	TACK COAT	GAL	\$2.140	4,300	\$9,202.00
	0070	4134000	BITUMINOUS FOG SEAL	GAL	\$5.110	550	\$2,810.50
	0310	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	SQYD	\$6.490	3,765.4	\$24,437.45
	0320	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	SQYD	\$7.250	832	\$6,032.00
	0360	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	EA	\$2,900.000	2	\$5,800.00
	0380	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	EA	\$2,700.000	1	\$2,700.00
	0650	7034600	CURB BLOCKOUT	LF	\$181.010	231.84	\$41,965.36
	0660	7040104	HALF-SOLE REPAIR	SQFT	\$98.300	1,241	\$121,990.30
	0740	7040104	HALF-SOLE REPAIR	SQFT	\$98.220	415	\$40,761.30
	0750	7040113	CLEANING AND EPOXY COATING	SQFT	\$13.000	1,100	\$14,300.00
Project J9I	3553 - Tota	al					\$725,450.48
Overall - T	otal						\$725,450.48

#### Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Revision 4/1/2020 Page 1 of 77



Pay Estimate Created Date: June 16, 2021

Progress Estimate Number	Contract ID	200117-H07	•	,	<b>9</b>	\$8,709,119.25
29	Prime Contractor	Apex Paving Co.	Pay Period End	June 15, 2021	Net Change Order Amount	\$1,421,791.48
29					Current Contract Amount	\$10,130,910.73

Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
3 0040	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Material			-8,370.8	\$56.39	(\$472,029.41
0040	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	8,370.8	\$56.39	\$472,029.41
0040	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Other Item Adjustment		AC Adjustment.			\$793.92
0050	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Material			-51,550.3	\$57.84	(\$2,981,669.35
0050	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	51,550.3	\$57.84	\$2,981,669.35
0050	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Other Item Adjustment	Asphalt Cement Price Adjustment	AC Adjustment.			\$3,287.45
0100	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material			-565.8	\$185.16	(\$104,763.53
0100	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	565.8	\$185.16	\$104,763.53
0360	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$2,998.00
0360	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	Other Item Adjustment	Stockpiled Materials Adjustment	Reapplies stockpile adjustment that was generated initially with no overall pay being given.  The line item was paid then reduced due to overrun and change order anticipated to address payment.			\$2,998.00
				This adjustment corrects the stockpile deduction since no pay is being made in general.			
0380	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$1,510.00
0380	TYPE A CRASHWORTHY END TERMINAL (MASH)	Other Item Adjustment	Stockpiled Materials Adjustment	Reapplies stockpile adjustment that was generated initially with no overall pay being given.  The line item was paid then reduced due to overrun and change order anticipated to address payment.  This adjustment corrects the stockpile			\$1,510.00
				deduction since no pay is being made in general.			
0410	SEAL COAT AGGREGATE, GRADE B1	Material			-265	\$5.00	(\$1,325.00
0410	SEAL COAT AGGREGATE, GRADE B1	Material		This adjustment offsets the original system- generated Material Payment Estimate Item	265	\$5.00	\$1,325.00

Revision 4/1/2020 Page 2 of 77



Pay Estimate Created Date: June 16, 2021

Progress Estimate Number
29

Contract ID
200117-H07
Pay Period Start
June 2, 2021
Prime Contract Amount
Apex Paving Co.
Pay Period End
June 15, 2021
Pay Period End
June 15, 2021
Net Change Order Amount
Current Contract Amount
\$8,709,119.25
Net Change Order Amount
\$1,421,791.48

t Line		Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
3				Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 6 on the current Payment Estimate.			
042	CURB BLOCKOUT	Material			-170	\$196.14	(\$33,343.80
042	CURB BLOCKOUT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 22 on the current Payment Estimate.	170	\$196.14	\$33,343.80
043	HALF-SOLE REPAIR	Material			-755	\$97.74	(\$73,793.70
043	HALF-SOLE REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 52 on the current Payment Estimate.	755	\$97.74	\$73,793.70
046	SEAL COAT AGGREGATE, GRADE B1	Material			-288	\$5.00	(\$1,440.00
046	SEAL COAT AGGREGATE, GRADE B1	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	288	\$5.00	\$1,440.00
047	CURB BLOCKOUT	Material			-185	\$193.61	(\$35,817.85
047	CURB BLOCKOUT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 26 on the current Payment Estimate.	185	\$193.61	\$35,817.85
048	HALF-SOLE REPAIR	Material			-723	\$96.76	(\$69,957.48
048	HALF-SOLE REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 55 on the current Payment Estimate.	723	\$96.76	\$69,957.48
051	SEAL COAT AGGREGATE, GRADE B1	Material			-265	\$5.00	(\$1,325.00
051	SEAL COAT AGGREGATE, GRADE B1	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	265	\$5.00	\$1,325.00
052	CURB BLOCKOUT	Material			-170	\$196.14	(\$33,343.80
052	CURB BLOCKOUT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 31 on the current Payment Estimate.	170	\$196.14	\$33,343.80
053	HALF-SOLE REPAIR	Material			-853	\$97.74	(\$83,372.22
053	HALF-SOLE REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 59 on the current Payment Estimate.	853	\$97.74	\$83,372.22
056	SEAL COAT AGGREGATE, GRADE B1	Material			-241	\$5.00	(\$1,205.00
056	SEAL COAT AGGREGATE, GRADE B1	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	241	\$5.00	\$1,205.00

Revision 4/1/2020 Page 3 of 77



Pay Estimate Created Date: June 16, 2021

Progress Estimate Number
29

Contract ID 200117-H07 Pay Period Start June 2, 2021 Original Contract Amount \$8,709,119.25
Pay Period End June 15, 2021 Original Contract Amount \$1,421,791.48
Current Contract Amount \$1,421,791.48

ect ber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
553	0570	CURB BLOCKOUT	Material			-155	\$199.15	(\$30,868.25
	0570	CURB BLOCKOUT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 36 on the current Payment Estimate.	155	\$199.15	\$30,868.25
	0640	CLASS B-2 CONCRETE	Material			-3.26	\$5,218.44	(\$17,012.11
	0640	CLASS B-2 CONCRETE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.	3.26	\$5,218.44	\$17,012.11
	0650	CURB BLOCKOUT	Material			-280	\$181.01	(\$50,682.80
	0650	CURB BLOCKOUT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 41 on the current Payment Estimate.	280	\$181.01	\$50,682.80
	0680	REINFORCING STEEL (EPOXY COATED)	Material			-909	\$5.00	(\$4,545.00)
	0680	REINFORCING STEEL (EPOXY COATED)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 62 on the current Payment Estimate.	909	\$5.00	\$4,545.00
	0730	CURB BLOCKOUT	Material			-261	\$189.97	(\$49,582.17
	0730	CURB BLOCKOUT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 47 on the current Payment Estimate.	261	\$189.97	\$49,582.17
	0770	SEAL COAT AGGREGATE, GRADE B1	Material			-463	\$5.00	(\$2,315.00
	0770	SEAL COAT AGGREGATE, GRADE B1	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	463	\$5.00	\$2,315.00
	0810	SEAL COAT AGGREGATE, GRADE B1	Material			-463	\$5.00	(\$2,315.00
	0810	SEAL COAT AGGREGATE, GRADE B1	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	463	\$5.00	\$2,315.00
	5007	TEMPORARY LONG-TERM RUMBLE STRIPS	Material			-12	\$1,800.00	(\$21,600.00)
	5007	TEMPORARY LONG-TERM RUMBLE STRIPS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.	12	\$1,800.00	\$21,600.00
	5008	MISC.	Material			-300	\$8.40	(\$2,520.00
	5008	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	300	\$8.40	\$2,520.00
	5009	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN.	Material			-325	\$29.40	(\$9,555.00)

Revision 4/1/2020 Page 4 of 77



Pay Estimate Created Date: June 16, 2021

Prog	ress Es	stimate Number 29	Contract Prime Co		0117-H07 ex Paving Co.	Pay Period Start Pay Period End	June 2, 2021 June 15, 2021	Net Cha	Contract Annge Order A Contract An	mount \$1	,709,119.25 ,421,791.48 0,130,910.73
Project Number	Line No.	Item Description		Adjustment Type	Other Item Adjustment Type	Comments			Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9I3553			SPACING			This adjustment offsets the original system generated Material Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate					
	5009	MGS GUARDF POSTS, 6		Material					325	\$29.40	\$9,555.00
J9S3571	1140	140 SEAL COAT AGGREGATE, Material -2 GRADE B1		-287	\$5.00	(\$1,435.00					
	1140	SEAL COAT AGG	BREGATE, BRADE B1	Material		This adjustment offsets the original system generated Material Payment Estimate Iter Adjustment (0023) due to user woodsk overridding Payment Estimate Exception 1 on the current Payment Estimate			287	\$5.00	\$1,435.00
Total											\$4 081 37

Revision 4/1/2020 Page 5 of 77



					Cor	ntract Project Information	1					
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work							
J9I3553	FAF 60-4(86)	Resurface	60	SCOTT	from I-57 to Spring Creek	rom I-57 to Spring Creek						
J9S3571	FAS S703(31)	Resurface	69	MISSISSIPPI	from I-57 to Bridge K095	from I-57 to Bridge K0950						
Totals by .	Job Numbe	rs										
J9l3553		Posted Item Pay Gross Item Adjustments Gross Item Pay			This Estimate \$725,450.48 \$4,081.37 \$729,531.85	Previous \$5,385,199.54 \$50,836.83 \$5,436,036.37	To Date \$6,110,650.02 \$54,918.20 \$6,165,568.22					
	Liquid	tive centive lated Damages Contract Adju			\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00					
		Posted Item Pay Gross Item Adjustments Gross Item Pay		This Estimate \$0.00 \$0.00 <b>\$0.00</b>	Previous \$1,748,898.20 \$70,442.04 <b>\$1,819,340.24</b>	To Date \$1,748,898.20 \$70,442.04 <b>\$1,819,340.24</b>						
	Liquid	tive centive lated Damages Contract Adju			\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00					

Revision 4/1/2020 Page 6 of 77



### **Exceptions (Discrepancies) This Estimate Period**

Exceptions (Discrepancies) This Estimate Period  Exceptions / Discrepancies	Explanation	Entered	Status
Exceptions / Discrependes	Ехріанацон	By	Status
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 2159903, Project Item Line Number 5008, Material Set 215990396, Material 3304AGBS - Aggregate Base JSP, Acceptance Action Generic 3304AGBS is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 4011209, Project Item Line Number 0040, Material Set 401120996, Material 1015ACPG6422 - PG 64-22 Performance Gr Asph.Binder, Acceptance Action Generic 1015ACPG6422 is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 4011209, Project Item Line Number 0040, Material Set 401120996, Material 0401BPPMBP1 - Plant Mix for Bit Pavement BP-1, Acceptance Action Generic AspLow is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 4030103, Project Item Line Number 0050, Material Set 403010396, Material 1015ACPG6422H - PG 64-22H Performance Gr. Asph. Binder, Acceptance Action Generic 1015ACPG6422H is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 4030103, Project Item Line Number 0050, Material Set 403010396, Material 0403SP125CLG - Superpave 12.5 mm, Des C 80 Gyros, Acceptance Action Generic AspHigh is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 4094011, Project Item Line Number 0410, Material Set 409401196, Material 1003GB - Aggregate for Seal Coat Grade B1, Acceptance Action Generic 1003GB is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 4094011, Project Item Line Number 0770, Material Set 409401196, Material 1003GB - Aggregate for Seal Coat Grade B1, Acceptance Action Generic 1003GB is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 4094011, Project Item Line Number 0810, Material Set 409401196, Material 1003GB - Aggregate for Seal Coat Grade B1, Acceptance Action Generic 1003GB is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 4094011, Project Item Line Number 0460, Material Set 409401196, Material 1003GB - Aggregate for Seal Coat Grade B1, Acceptance Action Generic 1003GB is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 4094011, Project Item Line Number 0510, Material Set 409401196, Material 1003GB - Aggregate for Seal Coat Grade B1, Acceptance Action Generic 1003GB is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 4094011, Project Item Line Number 0560, Material Set 409401196, Material 1003GB - Aggregate for Seal Coat Grade B1, Acceptance Action Generic 1003GB is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3571, Item 4094011, Project Item Line Number 1140, Material Set 409401196, Material 1003GB - Aggregate for Seal Coat Grade B1, Acceptance Action Generic 1003GB is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 6061061, Project Item Line Number 5009, Material Set 606106196, Material 1065DE - Delineators, Acceptance Action Generic 1065DE is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 6061061, Project Item Line Number 5009, Material Set 606106196, Material 1040GRSRCAT2 - Steel Beam for Class A Type 2 Guard Rail, Acceptance Action Generic 1040GRSRCAT2 is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 6131010, Project Item Line Number 0100, Material Set 613101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 6131010, Project Item Line Number 0100, Material Set 613101096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 6131010, Project Item Line Number 0100, Material Set 613101096, Material 0501CCPAEA - Concrete, Pavement HES w/Air, Acceptance Action 0501CCPAEA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 6162002, Project Item Line Number 5007, Material Set 616200296, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034214, Project Item Line Number 0640, Material Set 703421496, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034214, Project Item Line Number 0640, Material Set 703421496, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034214, Project Item Line Number 0640, Material Set 703421496, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913553, Item 7034600, Project Item Line Number 0420, Material Set 703460096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913553, Item 7034600, Project Item Line Number 0420, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7034600, Project Item Line Number 0420, Material Set 703460096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO,	No Remark was entered by Engineer	woodsk1	Overridden

Revision 4/1/2020 Page 7 of 77



### **Exceptions (Discrepancies) This Estimate Period**

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Acceptance Action Generic 100510CPCMLD is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J913553, Item 7034600, Project Item Line Number 0420, Material Set 703460096, Material 1039ERRAS - Epoxy Bonding Agent-Resin Anchor Systems, Acceptance Action Generic 1039ERRAS is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0470, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0470, Material Set 703460096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913553, Item 7034600, Project Item Line Number 0470, Material Set 703460096, Material 1039ERRAS - Epoxy Bonding Agent-Resin Anchor Systems, Acceptance Action Generic 1039ERRAS is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0470, Material Set 703460096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0470, Material Set 703460096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913553, Item 7034600, Project Item Line Number 0520, Material Set 703460096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0520, Material Set 703460096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0520, Material Set 703460096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913553, Item 7034600, Project Item Line Number 0520, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913553, Item 7034600, Project Item Line Number 0520, Material Set 703460096, Material 1039ERRAS - Epoxy Bonding Agent-Resin Anchor Systems, Acceptance Action Generic 1039ERRAS is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 1039ERRAS - Epoxy Bonding Agent-Resin Anchor Systems, Acceptance Action Generic 1039ERRAS is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0650, Material Set 703460096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0650, Material Set 703460096, Material 1039ERRAS - Epoxy Bonding Agent-Resin Anchor Systems, Acceptance Action Generic 1039ERRAS is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0650, Material Set 703460096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0650, Material Set 703460096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913553, Item 7034600, Project Item Line Number 0650, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0650, Material Set 703460096, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0730, Material Set 703460096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7034600, Project Item Line Number	No Remark was entered by Engineer	woodsk1	Overridden
			D 0 1-

Revision 4/1/2020 Page 8 of 77



### **Exceptions (Discrepancies) This Estimate Period**

Exceptions (Discrepancies) This Estimate Feriou			
Exceptions / Discrepencies	Explanation	Entered By	Status
0730, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0730, Material Set 703460096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0730, Material Set 703460096, Material 1039ERRAS - Epoxy Bonding Agent-Resin Anchor Systems, Acceptance Action Generic 1039ERRAS is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7034600, Project Item Line Number 0730, Material Set 703460096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7040104, Project Item Line Number 0430, Material Set 704010496, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7040104, Project Item Line Number 0430, Material Set 704010496, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7040104, Project Item Line Number 0430, Material Set 704010496, Material 0500XX - Concrete Plant Inspection Review, Acceptance Action Generic 0500XX is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7040104, Project Item Line Number 0480, Material Set 704010496, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7040104, Project Item Line Number 0480, Material Set 704010496, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7040104, Project Item Line Number 0480, Material Set 704010496, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7040104, Project Item Line Number 0480, Material Set 704010496, Material 0500XX - Concrete Plant Inspection Review, Acceptance Action Generic 0500XX is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7040104, Project Item Line Number 0530, Material Set 704010496, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7040104, Project Item Line Number 0740, Material Set 704010496, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7040106, Project Item Line Number 5010, Material Set 704010696, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7101000, Project Item Line Number 0680, Material Set 710100096, Material 1036RSSRECAB - Epoxy Ctd Sprl Stl Rein for Anch Bolts @, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden

Revision 4/1/2020 Page 9 of 77



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Im.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
00117-H07	J9I3553	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.26	\$36,000.00	\$9,504.00
		0001	0020	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	6,032.50	0.00	6,032.50	TONS	1,642.00	\$32.62	\$53,562.04
		0001	0030	3105002	GRAVEL (A) OR CRUSHED STONE (B)	17.00	0.00	17.00	TONS	0.00	\$18.91	\$0.00
		0001	0040	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	16,232.80	0.00	16,232.80	TONS	8,370.80	\$56.39	\$472,029.41
		0001	0050	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	62,977.90	0.00	62,977.90	TONS	51,550.30	\$57.84	\$2,981,669.35
		0001	0060	4071005	TACK COAT	60,125.00	0.00	60,125.00	GAL	40,847.00	\$2.14	\$87,412.58
		0001	0070	4134000	BITUMINOUS FOG SEAL	5,508.00	0.00	5,508.00	GAL	550.00	\$5.11	\$2,810.50
		0001	0080	6083003	3 IN. CONCRETE MEDIAN STRIP	2,330.00	0.00	2,330.00	SQYD	0.00	\$67.62	\$0.00
		0001	0090	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$500.00	\$0.00
		0001	0100	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	642.70	0.00	642.70	SQYD	642.70	\$185.16	\$119,002.33
		0001	0110	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	64.00	0.00	64.00	SQYD	10.00	\$10.00	\$100.00
		0001	0120	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	64.00	0.00	64.00	SQYD	10.00	\$10.00	\$100.00
		0001	0130	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	2,204.00	0.00	2,204.00	LF	2,026.00	\$6.00	\$12,156.00
		0001	0140	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	1,180.00	0.00	1,180.00	EA	952.00	\$10.00	\$9,520.00
		0001	0150	6131017	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	10.00	0.00	10.00	EA	2.00	\$10.00	\$20.00
		0001	0160	6133020	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	13.10	0.00	13.10	TONS	0.00	\$532.33	\$0.00
		0001	0170	6133021	REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	28.00	0.00	28.00	SQYD	0.00	\$103.80	\$0.00
		0001	0180	6161005	CONSTRUCTION SIGNS	3,888.00	0.00	3,888.00	SQFT	3,445.00	\$6.50	\$22,392.50
		0001	0190	6161008	ADVANCED WARNING RAIL SYSTEM	2.00	0.00	2.00	EA	0.00	\$45.00	\$0.00
		0001	0200	6161009	FLAG ASSEMBLY	4.00	0.00	4.00	EA	0.00	\$20.00	\$0.0
		0001	0210	6161025	CHANNELIZER (TRIM LINE)	712.00	0.00	712.00	EA	385.00	\$15.00	\$5,775.0
		0001	0220	6161030	TYPE III MOVEABLE BARRICADE	45.00	0.00	45.00	EA	0.00	\$100.00	\$0.00
		0001	0230	6161033	DIRECTIONAL INDICATOR BARRICADE	133.00	0.00	133.00	EA	76.00	\$35.00	\$2,660.0
		0001	0240	6161040	FLASHING ARROW PANEL	8.00	0.00	8.00	EA	4.00	\$400.00	\$1,600.0
		0001	0250	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$3,500.00	\$7,000.00
		0001	0260	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$208,790.05	\$208,790.05
		0001	0270	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	205,637.00	0.00	205,637.00	LF	0.00	\$0.23	\$0.00
		0001	0280	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	161,998.00	0.00	161,998.00	LF	0.00	\$0.23	\$0.0
		0001	0290	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	2,400.00	0.00	2,400.00	LF	0.00	\$1.00	\$0.00
		0001	0300	6209901	MISC.TEMPORARY PAVEMENT MARKING PAINT	1.00	0.00	1.00	LS	1.00	\$15,000.00	\$15,000.0
		0001	0310	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	18,810.00	0.00	18,810.00	SQYD	15,497.50	\$6.49	\$100,578.7
		0001	0320	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	22,495.00	0.00	22,495.00	SQYD	22,495.00	\$7.25	\$163,088.7
		0001	0330	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	3,038.00	0.00	3,038.00	STA	1,162.00	\$18.75	\$21,787.5
		0001	0340	7034001	CLASS B-1 CONCRETE	3.30	0.00	3.30	CUYD	0.00	\$2,400.00	\$0.0
		0010	0350	6061060	MGS GUARDRAIL	8,050.00	0.00	8,050.00	LF	8,050.00	\$20.00	\$161,000.0
		0010	0360	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	24.00	0.00	24.00	EA	24.00	\$2,900.00	\$69,600.0
		0010	0370	6061080	MGS END ANCHOR	6.00	3.00	9.00	EA	9.00	\$1,000.00	\$9,000.0
		0010	0380	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	30.00	0.00	30.00	EA	30.00	\$2,700.00	\$81,000.00
		0040	0390	9031220	PIPE POSTS	820.00	0.00	820.00	LB	0.00	\$6.00	\$0.00
		0070	0400	4091048	EMULSIFIED ASPHALT, SEAL COAT	106.00	0.00	106.00	GAL	106.00	\$5.00	\$530.00
		0070	0410	4094011	SEAL COAT AGGREGATE, GRADE B1	265.00	0.00	265.00	SQYD	265.00	\$5.00	\$1,325.0
		0070	0420	7034600	CURB BLOCKOUT	170.00	0.00	170.00	LF	170.00	\$196.14	\$33,343.80
		0070	0430	7040104	HALF-SOLE REPAIR	240.00	515.00	755.00	SQFT	755.00	\$97.74	\$73,793.70
		0070	0440	7040113	CLEANING AND EPOXY COATING	584.00	0.00	584.00	SQFT	584.00	\$13.00	\$7,592.00

Revision 4/1/2020 Page 10 of 77



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200117-H07	J9I3553	0071	0450	4091048	EMULSIFIED ASPHALT, SEAL COAT	115.00	0.00	115.00	GAL	115.00	\$5.00	\$575.00
		0071	0460	4094011	SEAL COAT AGGREGATE, GRADE B1	288.00	0.00	288.00	SQYD	288.00	\$5.00	\$1,440.00
		0071	0470	7034600	CURB BLOCKOUT	185.00	0.00	185.00	LF	185.00	\$193.61	\$35,817.85
		0071	0480	7040104	HALF-SOLE REPAIR	260.00	463.00	723.00	SQFT	723.00	\$96.76	\$69,957.48
		0071	0490	7040113	CLEANING AND EPOXY COATING	628.00	0.00	628.00	SQFT	628.00	\$13.00	\$8,164.00
		0072	0500	4091048	EMULSIFIED ASPHALT, SEAL COAT	106.00	0.00	106.00	GAL	106.00	\$5.00	\$530.00
		0072	0510	4094011	SEAL COAT AGGREGATE, GRADE B1	265.00	0.00	265.00	SQYD	265.00	\$5.00	\$1,325.00
		0072	0520	7034600	CURB BLOCKOUT	170.00	0.00	170.00	LF	170.00	\$196.14	\$33,343.80
		0072	0530	7040104	HALF-SOLE REPAIR	240.00	613.00	853.00	SQFT	853.00	\$97.74	\$83,372.22
		0072	0540	7040113	CLEANING AND EPOXY COATING	584.00	0.00	584.00	SQFT	0.00	\$13.00	\$0.00
		0073	0550	4091048	EMULSIFIED ASPHALT, SEAL COAT	96.00	0.00	96.00	GAL	96.00	\$5.00	\$480.00
		0073	0560	4094011	SEAL COAT AGGREGATE, GRADE B1	241.00	0.00	241.00	SQYD	241.00	\$5.00	\$1,205.00
		0073	0570	7034600	CURB BLOCKOUT	155.00	0.00	155.00	LF	155.00	\$199.15	\$30,868.25
		0073	0580	7040104	HALF-SOLE REPAIR	220.00	545.00	765.00	SQFT	765.00	\$98.90	\$75,658.50
		0073	0590	7040113	CLEANING AND EPOXY COATING	534.00	0.00	534.00	SQFT	0.00	\$13.00	\$0.00
		0074	0600	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	56.00	0.00	56.00	LF	28.00	\$325.00	\$9,100.00
		0074	0610	2169903	MISC.Remove and Replace Curb	16.00	0.00	16.00	LF	8.00	\$300.00	\$2,400.00
		0074	0620	4091048	EMULSIFIED ASPHALT, SEAL COAT	348.00	0.00	348.00	GAL	0.00	\$5.00	\$0.00
		0074	0630	4094011	SEAL COAT AGGREGATE, GRADE B1	870.00	0.00	870.00	SQYD	0.00	\$5.00	\$0.00
		0074	0640	7034214	CLASS B-2 CONCRETE	5.60	0.00	5.60	CUYD	3.26	\$5,218.44	\$17,012.11
		0074	0650	7034600	CURB BLOCKOUT	560.00	0.00	560.00	LF	280.00	\$181.01	\$50,682.80
		0074	0660	7040104	HALF-SOLE REPAIR	230.00	4,700.00	4,930.00	SQFT	1,471.00	\$98.30	\$144,599.30
		0074	0670	7040113	CLEANING AND EPOXY COATING	1,971.00	0.00	1,971.00	SQFT	0.00	\$13.00	\$0.00
		0074	0680	7101000	REINFORCING STEEL (EPOXY COATED)	1,820.00	0.00	1,820.00	LB	909.00	\$5.00	\$4,545.00
		0074	0690	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$5,000.00	\$0.00
		0074	0700	7174001	PREFORMED SILICONE OR EPDM EXPANSION JOINT SYSTEM	56.00	0.00	56.00	LF	0.00	\$75.00	\$0.00
		0075	0710	4091048	EMULSIFIED ASPHALT, SEAL COAT	162.00	0.00	162.00	GAL	0.00	\$5.00	\$0.00
		0075	0720	4094011	SEAL COAT AGGREGATE, GRADE B1	406.00	0.00	406.00	SQYD	0.00	\$5.00	\$0.00
		0075	0730	7034600	CURB BLOCKOUT	261.00	0.00	261.00	LF	261.00	\$189.97	\$49,582.17
		0075	0740	7040104	HALF-SOLE REPAIR	370.00	830.00	1,200.00	SQFT	785.00	\$98.22	\$77,102.70
		0075	0750	7040113	CLEANING AND EPOXY COATING	1,100.00	0.00	1,100.00	SQFT	1,100.00	\$13.00	\$14,300.00
		0076	0760	4091048	EMULSIFIED ASPHALT, SEAL COAT	185.00	0.00	185.00	GAL	185.00	\$5.00	\$925.00
		0076	0770	4094011	SEAL COAT AGGREGATE, GRADE B1	463.00	0.00	463.00	SQYD	463.00	\$5.00	\$2,315.00
		0076	0780	7040104	HALF-SOLE REPAIR	400.00	1,872.00	2,272.00	SQFT	2,272.00	\$107.41	\$244,035.52
		0076	0790	7040113	CLEANING AND EPOXY COATING	989.00	0.00	989.00	SQFT	0.00	\$13.00	\$0.00
		0077	0800	4091048	EMULSIFIED ASPHALT, SEAL COAT	185.00	0.00	185.00	GAL	185.00	\$5.00	\$925.00
		0077	0810	4094011	SEAL COAT AGGREGATE, GRADE B1	463.00	0.00	463.00	SQYD	463.00	\$5.00	\$2,315.00
		0077	0820	7040104	HALF-SOLE REPAIR	400.00	2,564.00	2,964.00	SQFT	2,964.00	\$107.41	\$318,363.24
		0077	0830	7040113	CLEANING AND EPOXY COATING	989.00	0.00	989.00	SQFT	0.00	\$13.00	\$0.00
		0001	5001	6162004	TEMPORARY SHORT-TERM RUMBLE STRIPS	0.00	4.00	4.00	EA	4.00	\$2,362.50	\$9,450.00
		0001	5002	6161010	RELOCATED SIGNS	0.00	804.00	804.00	SQFT	804.00	\$6.83	\$5,491.32
		0001	5003	6129902	MISC.TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	0.00	24,666.75	24,666.75	EA	24,666.75	\$1.00	\$24,666.75
		0076	5004	7040107	SLAB EDGE REPAIR (BRIDGES)	0.00	22.00	22.00	LF	22.00	\$245.39	\$5,398.58
		0077	5005	7040107	SLAB EDGE REPAIR (BRIDGES)	0.00	31.00	31.00	LF	31.00	\$245.39	\$7,607.09
		0001	5006	6189901	MISC.Additional Mobilization-Rumble Strip	0.00	1.00	1.00	LS	1.00	\$3,000.00	\$3,000.00

Revision 4/1/2020 Page 11 of 77



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200117-H07	J9I3553	0001	5008	2159903		0.00	300.00	300.00	LF	300.00	\$8.40	\$2,520.00
		0010	5009	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	0.00	325.00	325.00	LF	325.00	\$29.40	\$9,555.00
		0075	5010	7040106	FULL DEPTH REPAIR	0.00	53.00	53.00	SQFT	53.00	\$126.00	\$6,678.00
	Project J	913553 - To	tal Value	Posted to D	ate as of Report Generated Date							\$6,110,649.98
	J9S3571	0001	0840	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$2,600.00	\$2,600.00
		0001	0850	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	2,161.00	0.00	2,161.00	TONS	1,817.86	\$35.59	\$64,697.64
		0001	0860	3105002	GRAVEL (A) OR CRUSHED STONE (B)	350.00	0.00	350.00	TONS	0.00	\$44.12	\$0.00
		0001	0870	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	3,194.60	325.50	3,520.10	TONS	3,520.10	\$56.26	\$198,040.83
		0001	0880	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	17,210.20	86.00	17,296.20	TONS	17,255.60	\$60.51	\$1,044,136.36
		0001	0890	4071005	TACK COAT	14,965.00	0.00	14,965.00	GAL	12,730.00	\$2.14	\$27,242.20
		0001	0900	4134000	BITUMINOUS FOG SEAL	2,033.00	3,767.00	5,800.00	GAL	4,800.00	\$4.15	\$19,920.00
		0001	0910	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	4.00	0.00	4.00	EA	4.00	\$250.00	\$1,000.00
		0001	0920	6161005	CONSTRUCTION SIGNS	2,364.00	0.00	2,364.00	SQFT	2,364.00	\$6.50	\$15,366.00
		0001	0930	6161009	FLAG ASSEMBLY	7.00	0.00	7.00	EA	7.00	\$20.00	\$140.00
		0001	0940	6161025	CHANNELIZER (TRIM LINE)	186.00	0.00	186.00	EA	40.00	\$15.00	\$600.00
		0001	0950	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$3,500.00	\$7,000.00
		0001	0960	6162000A	WORK ZONE TRAFFIC SIGNAL SYSTEM	1.00	0.00	1.00	EA	1.00	\$8,400.00	\$8,400.00
		0001	0970	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	2.00	0.00	2.00	EA	2.00	\$1,800.00	\$3,600.00
		0001	0980	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$107,079.93	\$107,079.93
		0001	0990	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	1,212.00	0.00	1,212.00	LF	1,212.00	\$2.00	\$2,424.00
		0001	1000	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	2,000.00	0.00	2,000.00	LF	2,000.00	\$2.00	\$4,000.00
		0001	1010	6205309	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	24.00	0.00	24.00	LF	24.00	\$10.00	\$240.00
		0001	1020	6206000C	PAINT, TYPE P BEADS	114,312.00	0.00	114,312.00	LF	114,312.00	\$0.11	\$12,574.32
		0001	1030	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	31,999.00	0.00	31,999.00	LF	31,999.00	\$0.11	\$3,519.89
		0001	1040	6207001	PAVEMENT MARKING REMOVAL	4,006.00	0.00	4,006.00	LF	4,006.00	\$2.00	\$8,012.00
		0001	1050	6209901	MISC.TEMPORARY PAVEMENT MARKING PAINT	1.00	0.00	1.00	LS	0.00	\$0.00	\$0.00
		0001	1060	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	266.00	0.00	266.00	SQYD	266.00	\$8.76	\$2,330.16
		0001	1070	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	3,431.00	0.00	3,431.00	SQYD	3,431.00	\$9.00	\$30,879.00
		0010	1080	6061060	MGS GUARDRAIL	140.00	0.00	140.00	LF	140.00	\$22.00	\$3,080.00
		0010	1090	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	4.00	0.00	4.00	EA	4.00	\$3,000.00	\$12,000.00
		0010	1100	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	4.00	0.00	4.00	EA	4.00	\$2,900.00	\$11,600.00
		0070	1110	2169902	MISC.Removal of Existing End Post	4.00	0.00	4.00	EA	4.00	\$1,250.00	\$5,000.00
		0070	1120	2169903	MISC.Removal of Existing Curb and Guardrail	166.00	0.00	166.00	LF	166.00	\$125.00	\$20,750.00
		0070	1130	4091048	EMULSIFIED ASPHALT, SEAL COAT	115.00	0.00	115.00	GAL	115.00	\$5.00	\$575.00
		0070	1140	4094011	SEAL COAT AGGREGATE, GRADE B1	287.00	0.00	287.00	SQYD	287.00	\$5.00	\$1,435.00
		0070	1150	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	20.00	11.00	31.00	SQFT	31.00	\$311.16	\$9,645.96
		0070	1160	7040107	SLAB EDGE REPAIR (BRIDGES)	60.00	2.00	62.00	LF	62.00	\$245.39	\$15,214.18
		0070	1170	7040113	CLEANING AND EPOXY COATING	308.00	0.00	308.00	SQFT	308.00	\$13.00	\$4,004.00
		0070	1180	7134000	BRIDGE GUARDRAIL (THRIE BEAM)	178.00	0.00	178.00	LF	178.00	\$286.43	\$50,984.54
		0070	5100	7040104	HALF-SOLE REPAIR	0.00	360.00	360.00	SQFT	360.00	\$112.78	\$40,600.80
		0070	5110	7040106	FULL DEPTH REPAIR	0.00	50.00	50.00	SQFT	50.00	\$157.50	\$7,875.00
		0070	5120	7049902	MISC.FORCE ACCOUNT(bolting deck and steel plates)	0.00	2,331.40	2,331.40	EA	2,331.40	\$1.00	\$2,331.40
	Project J	9S3571 - To	otal Value	Posted to I	Date as of Report Generated Date							\$1,748,898.20
200117-H07 Ove	erall - Total	Value Post	ted to Da	te as of Rep	ort Generated Date							\$7,859,548.17

Page 12 of 77 Revision 4/1/2020



### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J9I3553

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0040	4011209	BIT. PAVEMENT MIXTURE PG64-22 (BP-1)	6/15/21	6/16/21	1,654.00	TONS	WBDL Shoulders.	24.622		53.962		WBDL Shoulders.
0050	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C	6/4/21	6/16/21	1,714.10	TONS	Route 60 WBPL.	39.914		43.098		Route 60 WBPL.
		MIX)	6/5/21	6/16/21	1,322.60	TONS	Route 60 WBPL.	39.317		43.098		Route 60 WBPL.
			6/9/21	6/16/21	1,897.20	TONS	Route 60 WBDL.	40.951		43.059		Route 60 WBDL.
			6/10/21	6/16/21	277.20	TONS	Various Intersections.	24.622		53.962		Various Intersections.
			6/11/21	6/16/21	721.40	TONS	Various Intersections.	24.622		53.962		Various Intersections.
			6/12/21	6/16/21	329.30	TONS	Various Intersections.	24.622		53.962		Various Intersections.
0060	4071005	TACK COAT	6/4/21	6/16/21	800.00	GAL	Route 60 WBPL.	39.914		43.098		Route 60 WBPL.
			6/5/21	6/16/21	700.00	GAL		39.317		43.098		Route 60 WBPL.
			6/9/21	6/16/21	1,100.00	GAL		40.951		43.059		Route 60 WBDL.
			6/10/21	6/16/21	300.00 600.00	GAL	Various Intersections.	24.622		53.962 53.962		Various Intersections.  Various Intersections.
			6/12/21	6/16/21	300.00	GAL	Various Intersections.  Various Intersections.	24.622		53.962		Various Intersections.
			6/15/21	6/16/21	500.00	GAL	WBDL Shoulders.	24.622		53.962		WBDL Shoulders.
0070	4134000	BITUMINOUS FOG SEAL	6/11/21	6/16/21	550.00	GAL	Route 60/61 Interchange On and Off ramps.	44.044		44.201		Route 60/61 Interchange On and Off ramps.
							Route 60/61 Interchange shoulder areas at overpass locations.					Route 60/61 Interchange shoulder areas at overpass locations.
0310	6221001	COLDMILLING BIT. PAVT FOR REM OF SURF.	6/10/21	6/15/21	436.00	SQYD	Bridge L0927 Driving Lane	35.679		35.732		Plan Width incorrect, actual width = 28'-0" +/- 280 LF x 14 LF = 3920 SF / 9 = 435.6 SY Pay = 436.0 SY
			6/12/21	6/16/21	3,329.40	SQYD	US 61 On and Off Ramps	44.041		44.101		US 61 On and Off Ramps
							Off-Ramp = 1364 LF x 8 FT = 1212.4 SY					Off-Ramp = 1364 LF x 8 FT = 1212.4 SY
							On-Ramp = 2117 LF x 9 FT = 2117.0 SY					On-Ramp = 2117 LF x 9 FT = 2117.0 SY
												US 61 On and Off Ramps
												Off-Ramp = 1364 LF x 8 FT = 1212.4 SY
0000	0004040	MODIFIED OO DAWY IN OVERTILE TRANSPIROUS	0/0/04	6/16/21	00.40	001/0	L M 0.4 500 TO . L M 50 050 DT    T 05 WD	04.000		50.000		On-Ramp = 2117 LF x 9 FT = 2117.0 SY
0320	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	6/3/21	6/16/21	69.40	SQYD	LM 24.522 TO LM 53.952 RT/LT OF WBL	24.622		53.962		LM 24.522 TO LM 53.952 RT/LT OF WBL
							25x25 Plan Size					25x25 Plan Size
							69.4 SY					69.4 SY
							Route FF Location					Route FF Location
			6/10/21	6/15/21	856.00	SQYD	Bridge L0927 Driving Lane	35.679		35.732		2(175 LF) x 22 LF = 7700 SF / 9 = 855.6 SY Pay = 856 SY
			6/15/21	6/16/21	-93.40	SQYD	Overrun to be addressed via Change Order.	1		2		Overrun to be addressed via Change Order.
0350	6061060	MGS GUARDRAIL	6/2/21	6/14/21	287.50	LF	Bridge L0953 Driving Lane	33.956		33.956		
				6/14/21	287.50	LF	Bridge L0953 Passing Lane	33.956		33.956		
							Previously Installed					
			6/3/21	6/14/21	287.50		Bridge L0927 Passing Lane	35.679		35.679		
			6/15/21	6/16/21	-862.50	LF	This Line Item entry addresses over payment (Brooks, S.) for the following dates.	24.622		53.962		This Line Item entry addresses over payment (Brooks, S for the following dates.
							6-02-2021 ; -575					6-02-2021 ; -575
							6-03-2021 ; -287.5					6-03-2021 ; -287.5
							Total = 862.5					Total = 862.5
0200	0004000	MOS BRIDGE ADD. TRANS SEC (DECANO CURR)	0/0/04	0144104	4.00		Change order will address additional line item quantity.	22.050		22.050		Change order will address additional line item quantity.
0360	6061069	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	6/2/21	6/14/21	1.00	EA	Bridge L0953 Driving Lane Bridge L0953 Passing Lane	33.956 33.956		33.956 33.956		
				0/14/21	1.00	EA	Previously Installed	33.930		33.930		
			6/3/21	6/14/21	1.00	EA	Bridge L0927 Passing Lane	35.679		35.679		
			6/15/21	6/16/21	-1.00	EA	This Line Item entry addresses over payment (Brooks, S.)	24.622		53.962		This Line Item entry addresses over payment (Brooks, 5 for the following dates.
							for the following dates.					•
							6-02-2021 ; -1					6-02-2021 ; -1
							Total = 1					Total = 1
							Change order will address additional line item quantity.					Change order will address additional line item quantity.
0380	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	6/2/21	6/14/21	1.00	EA	Bridge L0953 Driving Lane	33.956		33.956		
				6/14/21	1.00	EA	Bridge L0953 Passing Lane Previously Installed	33.956		33.956		
			6/3/21	6/14/21	1.00	FΔ	Bridge L0927 Passing Lane	35.679		35.679		
			6/15/21		-2.00	EA	This Line Item entry addresses over payment (Brooks, S.)	24.622		53.962		This Line Item entry addresses over payment (Brooks,
							for the following dates.					for the following dates.
							6-02-2021 ; -2					6-02-2021 ; -2
							Total = 1					Total = 1
							Change order will address additional line item quantity.					Change order will address additional line item quantity.
0650	7034600	CURB BLOCKOUT	6/7/21	6/14/21	56.68	LF	Bridge L0927 Passing Lane	35.679		35.679		
							Curb Blockout Span 2 Placed 5/28/21					
				6/14/21	56.68	LF	Bridge L0927 Passing Lane	35.679		35.679		
							Curb Blockout Span 4					
				6/14/21	70.00	LF	Bridge L0927 Passing Lane Curb Blockout Span 3	35.679		35.679		
							Placed 6/4/21					
			6/9/21	6/14/21	48.48	LF	Bridge L0927 Passing Lane Curb Blockout Span 5	35.679		35.679		
0660	7040104	HALF-SOLE REPAIR	6/15/21	6/16/21	1,241.00	SQFT	This Line Item entry addresses overpayment from	1		2		This Line Item entry addresses overpayment from
							(Brooks, S.) for the following dates.					(Brooks, S.) for the following dates.
							5-06-2021 ; -701					5-06-2021 ; -701
							5-07-2021 ; -348					5-07-2021 ; -348

Revision 4/1/2020 Page 13 of 77



The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
							Total = 1241					Total = 1241
0740	7040104	HALF-SOLE REPAIR	6/15/21	6/16/21	415.00	SQFT	This Line Item entry addresses overpayment from (Brooks, S.) for the following dates.	1		2		This Line Item entry addresses overpayment from (Brooks, S.) for the following dates.
							5-11-2021 ; -415					5-11-2021 ; -415
							Total = 415					Total = 415
0750	7040113	CLEANING AND EPOXY COATING	6/15/21	6/16/21	1,100.00	SQFT	Bridge L09531 Items - J9I3553	33.956		33.956		Bridge L09531 Items - J9I3553

roject	Line Number	DWR Date	re details for Construction S  Total Quantity Posted For DWR  Date	Signs (if applicable). Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
13553	0180	April 14, 2020	Date 377	WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		40.91	Left/Right	2.00	Sign 16		sign	Post 3
				CONST-3A 60x48 20.00 FINE SIGN		41.099	Left/Right	2.00	20			
				GO20-2 48x24 8.00 END ROAD WORK		45.40	Left/Right	2.00	8			
				R2-1 36x48 12.00 SPEED LIMIT XX		45.20	Left/Right	2.00	12			
				R4-2 36x48 12.00 PASS WITH CARE		45.00	Left/Right	2.00	12			
				G020-5aP 36x24 6.00 WORK ZONE (PLAQUE)		45.00	Left/Right	2.00	6			
				WO8-15 48x48 16.00 GROOVED PAVEMENT		44.044	Left/Right	2.00	16			
				WO8-15p 30x24 5.00 MOTORCYCLE (PLAQUE)		44.044	Left/Right	2.00	5			
				WO8-15 48x48 16.00 GROOVED PAVEMENT		42.268	Left/Right	2.00	16			
				WO8-15p 30x24 5.00		42.268	Left/Right	2.00	5			
				MOTORCYCLE (PLAQUE)  R2-1 36x48 12.00 SPEED LIMIT		41.90	Left/Right	2.00	12			
				XX CONST-3X 56x12 4.67		41.099	Left/Right	2.00	4.67			9.
				SPEEDING/PASSING (PLATE) G020-5aP 36x24 6.00 WORK ZONE		41.29	Left/Right	2.00	6			
				(PLAQUE) R4-1 36x48 12.00 DO NOT PASS		41.29	Left/Right	2.00	12			
				WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		41.47	Left/Right	2.00	16			
				AHEAD WO20-6a 48x48 16.00		41.76	Left	1.00	16			
				RIGHT/CENTER/LEFT LANE CLOSED WO4-1aR 48x48 16.00 MERGE		41.76	Right	1.00	16			
				(SYMBOL FROM RIGHT)  G020-5aP 36x24 6.00 WORK ZONE		41.90	Left/Right	2.00	6			
		A 20 2020	247	(PLAQUE)								
		April 20, 2020	217	CONST-3A 60x48 20.00 FINE SIGN WO20-1 48x48 16.00		42.87 42.68	Westbound Rte 60 LT/RT Westbound Rte 60 LT/RT	2.00	16			
				ROAD/BRIDGE/RAMP WORK AHEAD G020-5aP 36x24 6.00 WORK ZONE		43.68	Westbound Rte 60 LT/RT	2.00	6			
				(PLAQUE) WO4-1aR 48x48 16.00 MERGE		43.54	Westbound Rte 60 LT	1.00	16			
				(SYMBOL FROM RIGHT)  R2-1 36x48 12.00 SPEED LIMIT		43.68	Westbound Rte 60 LT/RT	2.00	12			
				XX WO20-5 48x48 16.00		43.25	Westbound Rte 60 LT/RT	2.00	16			
				RIGHT/CENTER/LEFT LANE CLOSED AHEAD								
				R4-1 36x48 12.00 DO NOT PASS G020-5aP 36x24 6.00 WORK ZONE		43.06 43.06	Westbound Rte 60 LT/RT Westbound Rte 60 LT/RT	2.00	12 6			
				(PLAQUE) CONST-3X 56x12 4.67		42.87	Westbound Rte 60 LT/RT	2.00	4.67			g
				SPEEDING/PASSING (PLATE)  WO20-6a 48x48 16.00		43.54	Westbound Rte 60 RT	1.00	16			
		14 40 0000	10	RIGHT/CENTER/LEFT LANE CLOSED								
		May 18, 2020	12	R3-7L 30x30 6.25 LEFT LANE MUST TURN LEFT		43.044	RT and LT	2.00	6.25			1
		June 24, 2020	377	WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD		37.473	RT/LT	2.00	16		16.00	
				GO20-2 48x24 8.00 END ROAD WORK		39.66	RT/LT	2.00	8		8.00	
				R4-1 36x48 12.00 DO NOT PASS		37.263	RT/LT	2.00	12		12.00	
				CONST-3X 56x12 4.67 SPEEDING/PASSING (PLATE)		37.059	RT/LT	2.00	4.67		4.67	9
				CONST-3A 60x48 20.00 FINE SIGN WO20-1 48x48 16.00		37.059 36.853	RT/LT RT/LT	2.00	20 16		20.00	
				ROAD/BRIDGE/RAMP WORK AHEAD				2.00			16.00	
				WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		37.695	RT	1.00	16		16.00	
				WO4-1aR 48x48 16.00 MERGE (SYMBOL FROM RIGHT)		37.695	LT	1.00	16		16.00	
				R2-1 36x48 12.00 SPEED LIMIT XX		37.899	RT/LT	2.00	12		12.00	
				G020-5aP 36x24 6.00 WORK ZONE (PLAQUE)		37.899	RT/LT	2.00	6		6.00	
				WO8-15 48x48 16.00 GROOVED PAVEMENT		37.941	RT/LT	4.00	16	Bridges L0923 and L0924	16.00	
				WO8-15p 30x24 5.00 MOTORCYCLE (PLAQUE)		37.941	RT/LT	4.00	5	Bridges L0923 and L0924	5.00	
				R4-2 36x48 12.00 PASS WITH CARE		39.284	RT/LT	2.00	12		12.00	
				G020-5aP 36x24 6.00 WORK ZONE (PLAQUE)		39.284	RT/LT	2.00	6		6.00	

Revision 4/1/2020 Page 14 of 77



The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line are details for Construction Signs (if published).

ect Line Numbe	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
53 0180	June 24, 2020	377	R2-1 36x48 12.00 SPEED LIMIT XX		39.47	RT/LT	2.00	12		12.00	2
			G020-5aP 36x24 6.00 WORK ZONE		37.263	RT/LT	2.00	6		6.00	1
	June 25, 2020	0	(PLAQUE) WO20-6a 48x48 16.00	0.6	0.6	I-57	1.00	16		16.00	1
			RIGHT/CENTER/LEFT LANE CLOSED  R2-1 36x48 12:00 SPEED LIMIT	0.2	0.2	1-57	2.00	12		12.00	2
			XX								
			WO5-1 48x48 16.00 ROAD/BRIDGE/RAMP NARROWS	0.2	0.2	I-55 To Route 60 Ramp	1.00	16		16.00	
			WO5-1 48x48 16.00 ROAD/BRIDGE/RAMP NARROWS	0.2	0.2	Exit 66B Ramp	1.00	16		16.00	
			WO20-1 48x48 16.00	0.2	0.2	I-55 To Route 60 Ramp	1.00	16		16.00	
			WO20-1 48x48 16.00	0.2	0.2	Exit 66B Ramp	1.00	16		16.00	
			ROAD/BRIDGE/RAMP WORK AHEAD WO4-1aL 48x48 16.00 MERGE	0.6	0.6	1-57	1.00	16		16.00	
			(SYMBOL FROM LEFT)								
			R2-1 36x48 12.00 SPEED LIMIT XX	25.557	25.557	Route 60 End Of Work Zone	2.00	12		12.00	
			R4-2 36x48 12.00 PASS WITH CARE	25.358	25.358	Route 60 End Of Work Zone	2.00	12		12.00	
			WO4-1R 48x48 16.00 MERGE	24.567	24.567	Exit 66B Ramp	1.00	16		16.00	
			(SYMBOL FROM RIGHT) R1-2 48 TRI 6.93 YIELD	24.548	24.548	I-55 To Route 60 Ramp	1	6.93		6.93	6
			WO3-2 48x48 16.00 YIELD AHEAD (SYMBOL)	24.525	24.525	I-55 To Route 60 Ramp	1.00	16		16.00	
			E05-1 36x48 12.00 GORE EXIT	24.407	24.407	Exit 66B Ramp	1.00	12		12.00	
			R1-2 48 TRI 6.93 YIELD		24.262	Exit 66B Ramp	1.00	6.93		6.93	
			R2-1 36x48 12.00 SPEED LIMIT XX	24.198	24.198	Exit 66B Ramp	1.00	12		12.00	
			WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD	0.8	0.8	1-57	2.00	16		16.00	
			R4-1 36x48 12.00 DO NOT PASS	1.0	1.0	I-57	2.00	12		12.00	
			CONST-3A 60x48 20.00 FINE SIGN	1.2	1.2	i-57	2.00	20		20.00	
			CONST-3X 56x12 4.67 SPEEDING/PASSING (PLATE)	1.2	1.2	I-57	2.00	4.67		4.67	
			WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD	1.4	1.4	I-57	2.00	16		16.00	
			WO3-2 48x48 16.00 YIELD AHEAD (SYMBOL)	24.205	24.025	Exit 66B Ramp	1.00	16		16.00	
	June 30, 2020	0	WO20-6a 48x48 16.00	33.70	33.70	Route 60	1.00	16		16.00	
			RIGHT/CENTER/LEFT LANE CLOSED  R2-1 36x48 12:00 SPEED LIMIT	33.5	33.5	Route 60	2.00	12		12.00	
			xx								
			R4-2 36x48 12.00 PASS WITH CARE	35.2	35.2	Route 60	2.00	12		12.00	
			WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD	34.79	34.79	Route 60	2.00	16		16.00	
			R2-1 36x48 12.00 SPEED LIMIT	35.5	35.5	Route 60	2.00	12		12.00	
			XX R4-1 36x48 12.00 DO NOT PASS	34.19	34.19	Route 60	2.00	12		12.00	
			WO20-5 48x48 16.00	33.89	33.89	Route 60	2.00	16		16.00	
			RIGHT/CENTER/LEFT LANE CLOSED AHEAD								
			WO4-1aL 48x48 16.00 MERGE (SYMBOL FROM LEFT)	33.70	33.70	Route 60	1.00	16		16.00	
			CONST-3A 60x48 20.00 FINE SIGN	34.49	34.49	Route 60	2.00	20		20.00	
	September 8, 2020	84	WO8-15p 30x24 5.00 MOTORCYCLE (PLAQUE)		29.461	Bridge L0956	2.00	5			
			WO8-15 48x48 16.00 GROOVED PAVEMENT		31.168	Bridge L0955	2.00	16			
			WO8-15p 30x24 5.00 MOTORCYCLE (PLAQUE)		31.168	Bridge L0955	2.00	5			
			WO8-15 48x48 16.00 GROOVED		29.461	Bridge L0956	2.00	16			
	September 23,	222	PAVEMENT WO8-15p 30x24 5.00		43.085	West of Rte FF (Stoddard)	2.00	5			
	2020	222	MOTORCYCLE (PLAQUE)			` ′					
			WO8-1 48x48 16.00 BUMP WO8-15 48x48 16.00 GROOVED		43.085 43.085	West of Rte FF (Stoddard) West of Rte FF (Stoddard)	2.00	16			
			PAVEMENT		43.005		2.00				
			WO8-15p 30x24 5.00 MOTORCYCLE (PLAQUE)		45.896	East of Bridge B0548	2.00	5			
			WO8-1 48x48 16.00 BUMP		45.896	East of Bridge B0548	2.00	16			
			WO8-15 48x48 16.00 GROOVED PAVEMENT		45.896	East of Bridge B0548	2.00	16			
			WO8-15p 30x24 5.00 MOTORCYCLE (PLAQUE)		46.507	East of A0030	2.00	5			
			WO8-1 48x48 16.00 BUMP		46.507	East of Bridge A0030	2.00	16			
			WO8-15 48x48 16.00 GROOVED PAVEMENT		46.507	East of A0030	2.00	16			
			See Special Sign Details				0.00				
	October 2, 2020	303	WO8-15 48x48 16.00 GROOVED PAVEMENT		43.042	Route 60	1.00	16			
			WO8-1 48x48 16.00 BUMP		43.042	Route 60	1.00	16			
			WO8-11 48x48 16.00 UNEVEN LANES		46.179	Route 60	2.00	16			
			WO8-17 48x48 16.00 SHOULDER		45.138	Route 60	2.00	16			
			DROP-OFF (SYMBOL)  WO8-17p 30x24 5.00 SHOULDER		45.138	Route 60	2.00	5			
			WO8-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)								
			WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		45.041	Route 60 Side Road	2.00	16			

Revision 4/1/2020 Page 15 of 77



The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line are details for Construction Signs (if published).

Num	e DWR Date per	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
0180	October 2, 2020	303	WO8-11 48x48 16.00 UNEVEN LANES		44.129	Route 60	2.00	16			32
			WO8-17 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		43.084	Route 60	2.00	16			3.
			WO8-11 48x48 16.00 UNEVEN LANES		43.061	Route 60	2.00	16			32
			WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		43.042	Route 60	2.00	16			32
			WO8-15p 30x24 5.00 MOTORCYCLE (PLAQUE)		43.042	Route 60	1.00	5			
			See Special Sign Details		1	A					
	October 5, 2020	80	WO8-11 48x48 16.00 UNEVEN LANES		46.171	Westbound Driving Lane	2.00	16			32
			WO8-11 48x48 16.00 UNEVEN LANES		48.184	Westbound Driving Lane	2.00	16			32
	0-4-1 0. 2020	445	WO8-1 48x48 16.00 BUMP R1-2 48 TRI 6.93 YIELD		48.472	Westbound Driving Lane	1.00	16 6.93			10
	October 9, 2020	115	WO3-2 48x48 16.00 YIELD AHEAD		49.089 49.089	Route 60	1.00	16			6.9
			(SYMBOL) WO8-1 48x48 16.00 BUMP		50.481	Route 60	1.00	16			10
			See Special Sign Details		1	A	1.00	40			
			WO8-11 48x48 16.00 UNEVEN LANES		49.289	Route 60	1.00	16			1
			WO8-17 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		49.289	Route 60	1.00	16			16
			WO8-11 48x48 16.00 UNEVEN LANES		50.241	Route 60	2.00	16			32
	October 13, 2020	524	EO5-1 36x48 12.00 GORE EXIT WO8-17p 30x24 5.00 SHOULDER		48.755 45.137	Route 60	1.00	12			10
			DROP-OFF (PLAQUE) W08-17 48x48 16.00 SHOULDER		43.097		2.00	16			33
			DROP-OFF (SYMBOL)  WO8-17p 30x24 5.00 SHOULDER		43.097		2.00	5			1
			DROP-OFF (PLAQUE)  WO8-17		45.137		2.00	16			3:
			DROP-OFF (SYMBOL)		40.107	D. 5.1. 11.10. 11					
			WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD			Rte F North/South	2.00	16			3
			WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD			Rte 60 WB near 153 intersection	2.00	16			3
			WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD			Co Rd 717 North/South	2.00	16			3
			WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD			Rte ZZ South	1.00	16			1
			WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD			Rte FF South	1.00	16			1
			WO8-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)		47.151		2.00	5			1
			WO8-17 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		47.151		2.00	16			3:
			WO8-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)		47.947		2.00	5			10
			WO8-17 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		47.947		2.00	16			32
			WO8-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)		49.282		2.00	5			1
			WO8-17 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		49.282		2.00	16			3
			WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		49.346		2.00	16			3
			WO8-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)		51.212		2.00	5			1
			WO8-17 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		51.212		2.00	16			3:
			WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD			Co RD 449	1.00	16			1
			WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD			Co RD 531 North	1.00	16			1
			WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD			Co Rd 731 South	1.00	16			1
			WO20-1 48x48 16.00			One-Mile Rd	1.00	16			1
			ROAD/BRIDGE/RAMP WORK AHEAD WO20-1 48x48 16.00			Rte 25 On-Ramp	1.00	16			1
			ROAD/BRIDGE/RAMP WORK AHEAD WO20-1 48x48 16.00			Rte AD Ramp	1.00	16			1
			ROAD/BRIDGE/RAMP WORK AHEAD WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD			Rte FF North	1.00	16			1
	October 14, 2020	148	ROAD/BRIDGE/RAMP WORK AHEAD  WO8-17 48x48 16.00 SHOULDER		52.325		2.00	16			3
			DROP-OFF (SYMBOL) W08-17p 30x24 5.00 SHOULDER		52.325		2.00	5			1
			DROP-OFF (PLAQUE)  W08-11		52.304		2.00	16			3
			LANES  WO8-11 48x48 16.00 UNEVEN		50.234						
			LANES				2.00	16			3
			WO8-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)		53.334		2.00	5			1
			WO8-17 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		53.334		2.00	16			3
	April 26, 2021	217	WO8-15p 30x24 5.00 MOTORCYCLE (PLAQUE)		I-55 South Accel Ramp	RT	1.00	5			
			WO8-15 48x48 16.00 GROOVED		I-55 South Accel Ramp	RT	1.00	16			16

Revision 4/1/2020 Page 16 of 77



The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line are details for Construction State (if applicable).

roject	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
13553	0180	April 26, 2021	217	WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		I-55 South Accel Ramp	RT	1.00	16			1
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		I-55 North Accel Ramp	RT	1.00	16			1
				WO8-1 48x48 16.00 BUMP		22.170	DL/PL	2.00	16			3.
				WO8-15 48x48 16.00 GROOVED PAVEMENT		25.788	DL/PL	2.00	16			3
				WO8-15p 30x24 5.00 MOTORCYCLE (PLAQUE)		25.788	DL/PL	2.00	5			1
				WO8-15 48x48 16.00 GROOVED PAVEMENT		22.248	DL/PL	2.00	16			32
				WO8-15p 30x24 5.00 MOTORCYCLE (PLAQUE)		22.248	DL/PL	2.00	5			10
				WO8-1 48x48 16.00 BUMP		25.838	DL/PL	2.00	16			3:
	April 27, 2021	280	WO8-15 48x48 16.00 GROOVED PAVEMENT		33.835	DL/PL	2.00	16			3	
				WO8-15p 30x24 5.00 MOTORCYCLE (PLAQUE)		33.835	DL/PL	2.00	5			1
				WO8-1 48x48 16.00 BUMP		27.943	DL/PL	2.00	16			3
				WO8-15 48x48 16.00 GROOVED PAVEMENT		27.897	DL/PL	2.00	16			3.
				WO8-15p 30x24 5.00 MOTORCYCLE (PLAQUE)		27.897	DL/PL	2.00	5			1
				WO8-15 48x48 16.00 GROOVED PAVEMENT		27.689	DL/PL	2.00	16			32
				WO8-15p 30x24 5.00 MOTORCYCLE (PLAQUE)		27.689	DL/PL	2.00	5			10
				WO8-1 48x48 16.00 BUMP		27.635	DL/PL	2.00	16			33
				WO8-1 48x48 16.00 BUMP		27.018	DL/PL	2.00	16			3:
				WO8-15 48x48 16.00 GROOVED PAVEMENT		26.974	DL/PL	2.00	16			3
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		Rte 61 South Accel Ramp	RT	1.00	16			1
				WO8-15p 30x24 5.00 MOTORCYCLE (PLAQUE)		26.974	DL/PL	2.00	5			10
	0180 - Total											3548.6

Revision 4/1/2020 Page 17 of 77



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3553	0020	MISC. AGGREGATE FOR BASE	Material		15	Nov 17, 2020	SYSTEM	\$53,562.04	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					15	Nov 17, 2020	SYSTEM	(\$53,562.04)	
					16	Dec 2, 2020	SYSTEM	\$53,562.04	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					16	Dec 2, 2020	SYSTEM	(\$53,562.04)	
					17	Dec 16, 2020	SYSTEM	\$53,562.04	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					17	Dec 16, 2020	SYSTEM	(\$53,562.04)	,
					18	Jan 4, 2021	SYSTEM	\$53,562.04	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					18	Jan 4, 2021	SYSTEM	(\$53,562.04)	
				- Total		2021		\$0.00	
			Material - Tota	ı				\$0.00	
	0020 -	- Total						\$0.00	
	0040	BIT. PAVEMENT MIXTURE PG64-22 (BP-1)	Material		27	May 17, 2021	SYSTEM	\$378,760.35	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					27	May 17, 2021	SYSTEM	(\$378,760.35)	
					28	Jun 2, 2021	SYSTEM	\$378,760.35	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					28	Jun 2, 2021	SYSTEM	(\$378,760.35)	
					29	Jun 16, 2021	SYSTEM	\$472,029.41	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					29	Jun 16, 2021	SYSTEM	(\$472,029.41)	
				- Total				\$0.00	
			Material - Tota	1				\$0.00	
			Other Item Adjustment	ACAD	13	Oct 16, 2020	woodsk1	(\$930.40)	*See Attached AC Price Index Adjustment Sheet.
					14	Nov 2, 2020	woodsk1	(\$10,471.20)	*See Attached AC Price Index Adjustment Sheet.
					15	Nov 17,	woodsk1	(\$1,874.88)	The Combination Of Adjustments For This Line Item Are As Follows:
						2020			Asphalt Cement Price Adjustment:
									-1874.88 For BP-1
									-332.17 For SP-125
									TCD Adjustment /Fee CD 405)
									TSR Adjustment (For SP-125): Lot 1A-3B \$0.00
									Lot 3C-5D \$0.00
									Lot 6A-6F \$9,692.65
									Pay Factor Adjustments (For SP-125):
									Lot 1 \$11,568.00
									Lot 2 \$3,701.76
									Lot 3 \$11,568.00
									Lot 4 \$11,568.00



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3553	0040	BIT. PAVEMENT MIXTURE PG64-22	Other Item Adjustment	ACAD					Lot 5 \$11,568.00
		(BP-1)	, tajaoanon						Lot 6 \$15,831.33
					27	May 17, 2021	woodsk1	(\$11.84)	AC Adjustment applies to asphalt placed on this payment period.
					29	Jun 17, 2021	woodsk1	\$793.92	AC Adjustment.
				ACAD - Tota	al			(\$12,494.40)	
			Other Item Ad	justment - To	tal			(\$12,494.40)	
	0040 -	Total						(\$12,494.40)	
	0050	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Material		13	Oct 16, 2020	SYSTEM	\$1,147,840.58	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
		(=: :=== ::,			13	Oct 16, 2020	SYSTEM	(\$1,147,840.58)	
					14	Nov 2, 2020	SYSTEM	\$1,472,195.74	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					14	Nov 2, 2020	SYSTEM	(\$1,472,195.74)	
					15	Nov 17, 2020	SYSTEM	\$1,479,888.46	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					15	Nov 17, 2020	SYSTEM	(\$1,479,888.46)	
					16	Dec 2, 2020	SYSTEM	\$91,728.46	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					16	Dec 2, 2020	SYSTEM	(\$91,728.46)	
					17	Dec 16, 2020	SYSTEM	\$91,728.46	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					17	Dec 16, 2020	SYSTEM	(\$91,728.46)	
					18	Jan 4, 2021	SYSTEM	\$91,728.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					18	Jan 4, 2021	SYSTEM	(\$91,728.46)	
					19	Jan 20, 2021	SYSTEM	\$91,728.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					19	Jan 20, 2021	SYSTEM	(\$91,728.46)	
					20	Feb 1, 2021	SYSTEM	\$91,728.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					20	Feb 1, 2021	SYSTEM	(\$91,728.46)	·
					21	Feb 16, 2021	SYSTEM	\$91,728.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					21	Feb 16, 2021	SYSTEM	(\$91,728.46)	
					22	Mar 2, 2021	SYSTEM	\$91,728.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment
					22	Mar 2, 2021	SYSTEM	(\$91,728.46)	Estimate Exception 1 on the current Payment Estimate.
					23	Mar 16, 2021	SYSTEM	\$91,728.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					23	Mar 16, 2021	SYSTEM	(\$91,728.46)	. ,
					24	Apr 2, 2021	SYSTEM	\$91,728.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					24	Apr 2,	SYSTEM	(\$91,728.46)	Zroopion . Shallo surrout ayrion Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3553	0050	ASPHALTIC	Material			2021			
		CONCRETE MIXTURE PG 70-22 (SP125C MIX)			25	Apr 16, 2021	SYSTEM	\$91,728.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					25	Apr 16, 2021	SYSTEM	(\$91,728.46)	
					26	May 3, 2021	SYSTEM	\$91,728.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					26	May 3, 2021	SYSTEM	(\$91,728.46)	
					27	May 17, 2021	SYSTEM	\$1,772,483.66	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					27	May 17, 2021	SYSTEM	(\$1,772,483.66)	
					28	Jun 2, 2021	SYSTEM	\$2,619,486.84	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					28	Jun 2, 2021	SYSTEM	(\$2,619,486.84)	
					29	Jun 16, 2021	SYSTEM	\$2,981,669.35	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					29	Jun 16, 2021	SYSTEM	(\$2,981,669.35)	
				- Total				\$0.00	
			Material - Tota	ı				\$0.00	
			Other Item Adjustment	ACAD	13	Oct 16, 2020	woodsk1	(\$45,891.79)	*See Attached AC Price Index Adjustment Sheet.
					14	Nov 2, 2020	woodsk1	(\$12,968.04)	*See Attached AC Price Index Adjustment Sheet.
					27	May 17, 2021	woodsk1	(\$442.64)	
					28	Jun 2, 2021	woodsk1	(\$1,281.34)	
					29	Jun 17, 2021	woodsk1	\$3,287.45	AC Adjustment.
				ACAD - Tota		=		(\$57,296.36)	
				BITM	15	Nov 17, 2020	woodsk1	\$75,165.57	The Combination Of Adjustments For This Line Item Are As Follows:  Asphalt Cement Price Adjustment:
									-1874.88 For BP-1
									-332.17 For SP-125
									TSR Adjustment (For SP-125):
									Lot 1A-3B \$0.00
									Lot 3C-5D \$0.00
									Lot 6A-6F \$9,692.65
									Pay Factor Adjustments (For SP-125):
									Lot 1 \$11,568.00
									Lot 2 \$3,701.76
									Lot 3 \$11,568.00
									Lot 4 \$11,568.00
									Lot 5 \$11,568.00
									Lot 6 \$15,831.33
				BITM - Tota				\$75,165.57	
				OTHR	28	Jun 2,	woodsk1	\$45,115.20	Pay factors for 200117-H07



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
J9I3553	0050	ASPHALTIC	Other Item	Туре		2021			
		CONCRETE MIXTURE PG 70-22	Adjustment						Lot 1 105% \$11,568.00
		(SP125C MIX)							Lot 2 105% \$11,568.00
									Lot 3 105% \$11,568.00
									Lot 4 104.5% \$10,411.20
			ou k	OTHR - Tota				\$45,115.20	
	0050 -	Total	Other Item Ad	ljustment - 10	tal			\$62,984.41 \$62,984.41	
	0100	FURN & PLACE	Material		6	Jul 2,	SYSTEM	\$46,901.03	This adjustment offsets the original system-generated Overrun Payment
	0.00	CONC MATL FOR FULL DEPTH	material			2020			Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					6	Jul 2, 2020	SYSTEM	(\$46,901.03)	
					7	Jul 16, 2020	SYSTEM	\$69,305.39	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					7	Jul 16, 2020	SYSTEM	(\$69,305.39)	
					8	Aug 3, 2020	SYSTEM	\$69,305.39	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					8	Aug 3, 2020	SYSTEM	(\$69,305.39)	
					9	Aug 18, 2020	SYSTEM	\$69,305.39	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					9	Aug 18, 2020	SYSTEM	(\$69,305.39)	
					10	Sep 3, 2020	SYSTEM	\$69,305.39	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					10	Sep 3, 2020	SYSTEM	(\$69,305.39)	
					11	Sep 16, 2020	SYSTEM	\$84,951.41	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					11	Sep 16, 2020	SYSTEM	(\$84,951.41)	
					12	Oct 1, 2020	SYSTEM	\$90,709.88	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					12	Oct 1, 2020	SYSTEM	(\$90,709.88)	
					13	Oct 16, 2020	SYSTEM	\$90,709.88	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					13	Oct 16, 2020	SYSTEM	(\$90,709.88)	
					14	Nov 2, 2020	SYSTEM	\$90,709.88	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					14	Nov 2, 2020	SYSTEM	(\$90,709.88)	
					15	Nov 17, 2020	SYSTEM	\$90,709.88	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					15	Nov 17, 2020	SYSTEM	(\$90,709.88)	
					16	Dec 2, 2020	SYSTEM	\$90,709.88	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					16	Dec 2, 2020	SYSTEM	(\$90,709.88)	
					17	Dec 16, 2020	SYSTEM	\$90,709.88	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					17	Dec 16,	SYSTEM	(\$90,709.88)	



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
553	0100	FURN & PLACE CONC MATL FOR	Material			2020			
		FULL DEPTH			18	Jan 4, 2021	SYSTEM	\$90,709.88	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payme Estimate Exception 8 on the current Payment Estimate.
					18	Jan 4, 2021	SYSTEM	(\$90,709.88)	
					19	Jan 20, 2021	SYSTEM	\$90,709.88	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payme Estimate Exception 7 on the current Payment Estimate.
					19	Jan 20, 2021	SYSTEM	(\$90,709.88)	
					20	Feb 1, 2021	SYSTEM	\$90,709.88	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payme Estimate Exception 7 on the current Payment Estimate.
					20	Feb 1, 2021	SYSTEM	(\$90,709.88)	
					21	Feb 16, 2021	SYSTEM	\$90,709.88	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payme Estimate Exception 7 on the current Payment Estimate.
					21	Feb 16, 2021	SYSTEM	(\$90,709.88)	
					22	Mar 2, 2021	SYSTEM	\$90,709.88	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payme Estimate Exception 7 on the current Payment Estimate.
					22	Mar 2, 2021	SYSTEM	(\$90,709.88)	. ,
					23	Mar 16, 2021	SYSTEM	\$90,709.88	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payme Estimate Exception 7 on the current Payment Estimate.
					23	Mar 16, 2021	SYSTEM	(\$90,709.88)	
					24	Apr 2, 2021	SYSTEM	\$90,709.88	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payme Estimate Exception 7 on the current Payment Estimate.
					24	Apr 2, 2021	SYSTEM	(\$90,709.88)	
					25	Apr 16, 2021	SYSTEM	\$90,709.88	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payme Estimate Exception 7 on the current Payment Estimate.
					25	Apr 16, 2021	SYSTEM	(\$90,709.88)	
					26	May 3, 2021	SYSTEM	\$104,763.53	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payme Estimate Exception 10 on the current Payment Estimate.
					26	May 3, 2021	SYSTEM	(\$104,763.53)	
					27	May 17, 2021	SYSTEM	\$104,763.53	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payme Estimate Exception 14 on the current Payment Estimate.
					27	May 17, 2021	SYSTEM	(\$104,763.53)	
					28	Jun 2, 2021	SYSTEM	\$104,763.53	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payme Estimate Exception 14 on the current Payment Estimate.
					28	Jun 2, 2021	SYSTEM	(\$104,763.53)	
					29	Jun 16, 2021	SYSTEM	\$104,763.53	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payme Estimate Exception 15 on the current Payment Estimate.
					29	Jun 16, 2021	SYSTEM	(\$104,763.53)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0100 -							\$0.00	
	0110	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEM	Material		6	Jul 2, 2020	SYSTEM	\$16.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payme Estimate Exception 11 on the current Payment Estimate.
					6	Jul 2,	SYSTEM	(\$16.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3553	0110	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEM	Material		7	Jul 16, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					7	Jul 16, 2020	SYSTEM	(\$100.00)	
					8	Aug 3, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					8	Aug 3, 2020	SYSTEM	(\$100.00)	
					9	Aug 18, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 35 on the current Payment Estimate.
					9	Aug 18, 2020	SYSTEM	(\$100.00)	
					10	Sep 3, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					10	Sep 3, 2020	SYSTEM	(\$100.00)	
					11	Sep 16, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					11	Sep 16, 2020	SYSTEM	(\$100.00)	
					12	Oct 1, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					12	Oct 1, 2020	SYSTEM	(\$100.00)	
					13	Oct 16, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					13	Oct 16, 2020	SYSTEM	(\$100.00)	
					14	Nov 2, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					14	Nov 2, 2020	SYSTEM	(\$100.00)	
					15	Nov 17, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					15	Nov 17, 2020	SYSTEM	(\$100.00)	
					16	Dec 2, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					16	Dec 2, 2020	SYSTEM	(\$100.00)	
					17	Dec 16, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					17	Dec 16, 2020	SYSTEM	(\$100.00)	
					18	Jan 4, 2021	SYSTEM	\$100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					18	Jan 4, 2021	SYSTEM	(\$100.00)	
				- Total				\$0.00	
	0110 -	Total	Material - Tota					\$0.00 \$0.00	
	0110 -	TYPE 1 OR 5	Material		6	Jul 2,	SYSTEM	\$16.00	This adjustment offsets the original system-generated Overrun Payment
		AGGREGATE FOR BASE (4 IN. TH				2020	0.40==-	(	Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					6	Jul 2, 2020	SYSTEM	(\$16.00)	
					7	Jul 16,	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3553	0120	TYPE 1 OR 5 AGGREGATE FOR	Material			2020			Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
		BASE (4 IN. TH			7	Jul 16, 2020	SYSTEM	(\$100.00)	
					8	Aug 3, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					8	Aug 3, 2020	SYSTEM	(\$100.00)	
					9	Aug 18, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					9	Aug 18, 2020	SYSTEM	(\$100.00)	
					10	Sep 3, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					10	Sep 3, 2020	SYSTEM	(\$100.00)	
					11	Sep 16, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					11	Sep 16, 2020	SYSTEM	(\$100.00)	
					12	Oct 1, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					12	Oct 1, 2020	SYSTEM	(\$100.00)	
					13	Oct 16, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					13	Oct 16, 2020	SYSTEM	(\$100.00)	
					14	Nov 2, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					14	Nov 2, 2020	SYSTEM	(\$100.00)	
					15	Nov 17, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					15	Nov 17, 2020	SYSTEM	(\$100.00)	
					16	Dec 2, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					16	Dec 2, 2020	SYSTEM	(\$100.00)	
					17	Dec 16, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					17	Dec 16, 2020	SYSTEM	(\$100.00)	
					18	Jan 4, 2021	SYSTEM	\$100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					18	Jan 4, 2021	SYSTEM	(\$100.00)	
				- Total				\$0.00	
	0420-	Total	Material - Tota					\$0.00	
	0120 -							\$0.00	
	0140	DOWEL BAR (DRILLING, FURNISHING AND INST	Material		6	Jul 2, 2020	SYSTEM	\$2,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					6	Jul 2, 2020	SYSTEM	(\$2,000.00)	
					7	Jul 16, 2020	SYSTEM	\$5,650.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3553	0140	DOWEL BAR	Material						Estimate Exception 13 on the current Payment Estimate.
		(DRILLING, FURNISHING AND			7	Jul 16, 2020	SYSTEM	(\$5,650.00)	
		INST			8	Aug 3, 2020	SYSTEM	\$5,650.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					8	Aug 3, 2020	SYSTEM	(\$5,650.00)	Estimate Exception to on the same in a symbolic Estimate.
					9	Aug 18, 2020	SYSTEM	\$5,650.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
					9	Aug 18, 2020	SYSTEM	(\$5,650.00)	
					10	Sep 3, 2020	SYSTEM	\$5,650.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					10	Sep 3, 2020	SYSTEM	(\$5,650.00)	
					11	Sep 16, 2020	SYSTEM	\$7,480.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					11	Sep 16, 2020	SYSTEM	(\$7,480.00)	
					12	Oct 1, 2020	SYSTEM	\$8,220.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					12	Oct 1, 2020	SYSTEM	(\$8,220.00)	
					13	Oct 16, 2020	SYSTEM	\$8,220.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					13	Oct 16, 2020	SYSTEM	(\$8,220.00)	
					14	Nov 2, 2020	SYSTEM	\$8,220.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					14	Nov 2, 2020	SYSTEM	(\$8,220.00)	
					15	Nov 17, 2020	SYSTEM	\$8,220.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					15	Nov 17, 2020	SYSTEM	(\$8,220.00)	
					16	Dec 2, 2020	SYSTEM	\$8,220.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					16	Dec 2, 2020	SYSTEM	(\$8,220.00)	
					17	Dec 16, 2020	SYSTEM	\$8,220.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					17	Dec 16, 2020	SYSTEM	(\$8,220.00)	
					18	Jan 4, 2021	SYSTEM	\$8,220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					18	Jan 4, 2021	SYSTEM	(\$8,220.00)	
				- Total				\$0.00	
			Material - Tota	ı				\$0.00	
	0140 - 0150	Total  DOWEL BAR	Material		7	Jul 16,	SYSTEM	\$0.00 \$10.00	This adjustment offsets the original system-generated Overrun Payment
		(FURNISH AND INSTALL WITH BASK			7	2020	CVCTEA	(640.00)	Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					7	Jul 16, 2020	SYSTEM	(\$10.00)	
					8	Aug 3, 2020	SYSTEM	\$10.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3553	0150	DOWEL BAR (FURNISH AND	Material		8	Aug 3, 2020	SYSTEM	(\$10.00)	
		INSTALL WITH BASK			9	Aug 18, 2020	SYSTEM	\$10.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
					9	Aug 18, 2020	SYSTEM	(\$10.00)	
					10	Sep 3, 2020	SYSTEM	\$10.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					10	Sep 3, 2020	SYSTEM	(\$10.00)	
					11	Sep 16, 2020	SYSTEM	\$10.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					11	Sep 16, 2020	SYSTEM	(\$10.00)	
					12	Oct 1, 2020	SYSTEM	\$10.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					12	Oct 1, 2020	SYSTEM	(\$10.00)	
					13	Oct 16, 2020	SYSTEM	\$10.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					13	Oct 16, 2020	SYSTEM	(\$10.00)	
					14	Nov 2, 2020	SYSTEM	\$10.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					14	Nov 2, 2020	SYSTEM	(\$10.00)	
					15	Nov 17, 2020	SYSTEM	\$10.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					15	Nov 17, 2020	SYSTEM	(\$10.00)	
					16	Dec 2, 2020	SYSTEM	\$10.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					16	Dec 2, 2020	SYSTEM	(\$10.00)	
				- Total				\$0.00	
			Material - Tota	<u> </u>				\$0.00	
	0150 - 0180	CONSTRUCTION	Material		1	Apr 16,	SYSTEM	\$0.00 (\$2,450.50)	
		SIGNS			2	2020 May 4, 2020	SYSTEM	\$3,861.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment
					2	May 4,	SYSTEM	(\$3,861.00)	Estimate Exception 8 on the current Payment Estimate.
					3	2020 May 19,	SYSTEM	\$3,861.00	This adjustment offsets the original system-generated Overrun Payment
						2020			Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					3	May 19, 2020	SYSTEM	(\$3,861.00)	
					4	Jun 3, 2020	SYSTEM	\$3,939.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					4	Jun 3, 2020	SYSTEM	(\$3,939.00)	
					5	Jun 16, 2020	SYSTEM	\$3,939.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					5	Jun 16, 2020	SYSTEM	(\$3,939.00)	
					6	Jul 2, 2020	SYSTEM	\$6,389.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
Project	Line	Description	Type	Adjustment Type	Number	Date	By	Amount	Remains
J9I3553	0180	CONSTRUCTION	Material						Estimate Exception 15 on the current Payment Estimate.
		SIGNS			6	Jul 2, 2020	SYSTEM	(\$6,389.50)	
					7	Jul 16, 2020	SYSTEM	\$6,389.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					7	Jul 16, 2020	SYSTEM	(\$6,389.50)	
					8	Aug 3, 2020	SYSTEM	\$9,360.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					8	Aug 3, 2020	SYSTEM	(\$9,360.00)	
					9	Aug 18, 2020	SYSTEM	\$9,360.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
					9	Aug 18, 2020	SYSTEM	(\$9,360.00)	
					10	Sep 3, 2020	SYSTEM	\$9,360.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					10	Sep 3, 2020	SYSTEM	(\$9,360.00)	
				- Total		2020		(\$2,450.50)	
			Material - Tota					(\$2,450.50)	
			MaterialCredit		2	May 4,	SYSTEM	\$2,450.50	
			MaterialOredit	- Total		2020	STOTEW		
			MotorialCrestit					\$2,450.50	
			MaterialCredit		1	Apr 40	woodska	\$2,450.50	
			Other Item Adjustment	MDPA		Apr 16, 2020	woodsk1	\$2,450.50	This adjustment is being added to belong line item 0400 discussions
				MDDA T	2	May 4, 2020	woodsk1	(\$2,450.50)	This adjustment is being added to balance line item 0180 discrepancy amount.
			Other Item And	MDPA - Tota				\$0.00	
	0180 -	Total	Other Item Ad	justinent - 10	ıtaı			\$0.00 \$0.00	
	0180 -	CHANNELIZER (TRIM LINE)	Material		1	Apr 16, 2020	SYSTEM	(\$1,215.00)	
		(TAINI LINE)			2	May 4, 2020	SYSTEM	\$1,215.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					2	May 4, 2020	SYSTEM	(\$1,215.00)	
					3	May 19, 2020	SYSTEM	\$1,215.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					3	May 19, 2020	SYSTEM	(\$1,215.00)	
					4	Jun 3, 2020	SYSTEM	\$1,980.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					4	Jun 3, 2020	SYSTEM	(\$1,980.00)	
					5	Jun 16, 2020	SYSTEM	\$1,980.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					5	Jun 16, 2020	SYSTEM	(\$1,980.00)	
					6	Jul 2, 2020	SYSTEM	\$3,930.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					6	Jul 2, 2020	SYSTEM	(\$3,930.00)	



				1					
Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3553	0210	CHANNELIZER (TRIM LINE)	Material		7	Jul 16, 2020	SYSTEM	(\$3,930.00)	
					8	Aug 3, 2020	SYSTEM	\$3,930.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					8	Aug 3, 2020	SYSTEM	(\$3,930.00)	
					9	Aug 18, 2020	SYSTEM	\$3,930.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 44 on the current Payment Estimate.
					9	Aug 18, 2020	SYSTEM	(\$3,930.00)	
					10	Sep 3, 2020	SYSTEM	\$3,930.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment
					10	Sep 3,	SYSTEM	(\$3,930.00)	Estimate Exception 30 on the current Payment Estimate.
				- Total		2020		(04.045.00)	
			Material - Tota					(\$1,215.00)	
			MaterialCredit	''-	2	May 4,	SYSTEM	(\$1,215.00) \$1,215.00	
			MaterialOredit			2020	STOTEW		
				- Total				\$1,215.00	
			MaterialCredit		4	A 12		\$1,215.00	
			Other Item Adjustment	MDPA		Apr 16, 2020	woodsk1	\$1,215.00	
					2	May 4, 2020	woodsk1	(\$1,215.00)	This adjustment is being added to balance line item 0220 discrepancy amount.
				MDPA - Tot				\$0.00	
			Other Item Ad	justment - To	tal			\$0.00	
	0210 -	Total						\$0.00	
	0230	DIRECTIONAL INDICATOR BARRICADE	Material		1	Apr 16, 2020	SYSTEM	(\$665.00)	
		BARRIOADE			2	May 4, 2020	SYSTEM	\$665.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					2	May 4, 2020	SYSTEM	(\$665.00)	
					3	May 19, 2020	SYSTEM	\$665.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					3	May 19, 2020	SYSTEM	(\$665.00)	
					4	Jun 3, 2020	SYSTEM	\$665.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					4	Jun 3, 2020	SYSTEM	(\$665.00)	
					5	Jun 16, 2020	SYSTEM	\$665.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					5	Jun 16, 2020	SYSTEM	(\$665.00)	•
					6	Jul 2, 2020	SYSTEM	\$1,995.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					6	Jul 2, 2020	SYSTEM	(\$1,995.00)	
					7	Jul 16, 2020	SYSTEM	\$2,660.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					7	Jul 16, 2020	SYSTEM	(\$2,660.00)	
					8	Aug 3, 2020	SYSTEM	\$2,660.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					8	Aug 3, 2020	SYSTEM	(\$2,660.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3553	0230	DIRECTIONAL INDICATOR BARRICADE	Material		9	Aug 18, 2020	SYSTEM	\$2,660.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 45 on the current Payment Estimate.
					9	Aug 18, 2020	SYSTEM	(\$2,660.00)	
					10	Sep 3, 2020	SYSTEM	\$2,660.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					10	Sep 3, 2020	SYSTEM	(\$2,660.00)	
				- Total		2020		(\$665.00)	
			Material - Tota					(\$665.00)	
			MaterialCredit		2	May 4, 2020	SYSTEM	\$665.00	
				- Total				\$665.00	
			MaterialCredit	- Total				\$665.00	
			Other Item Adjustment	MDPA	1	Apr 16, 2020	woodsk1	\$665.00	
					2	May 4, 2020	woodsk1	(\$665.00)	This adjustment is being added to balance line item 0230 discrepancy amount.
				MDPA - Tota	al			\$0.00	
			Other Item Ad	justment - To	tal			\$0.00	
	0230 -	Total						\$0.00	
	0240	FLASHING ARROW PANEL	Material		1	Apr 16, 2020	SYSTEM	(\$400.00)	
		TANLL			2	May 4, 2020	SYSTEM	\$400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment
					2	May 4, 2020	SYSTEM	(\$400.00)	Estimate Exception 12 on the current Payment Estimate.
					3	May 19, 2020	SYSTEM	\$400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					3	May 19, 2020	SYSTEM	(\$400.00)	Estimate Exception 12 on the current rayment Estimate.
					4	Jun 3, 2020	SYSTEM	\$400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					4	Jun 3, 2020	SYSTEM	(\$400.00)	
					5	Jun 16, 2020	SYSTEM	\$400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					5	Jun 16, 2020	SYSTEM	(\$400.00)	
					6	Jul 2, 2020	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					6	Jul 2, 2020	SYSTEM	(\$1,200.00)	
					7	Jul 16, 2020	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					7	Jul 16, 2020	SYSTEM	(\$1,600.00)	
					8	Aug 3, 2020	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					8	Aug 3, 2020	SYSTEM	(\$1,600.00)	
					9	Aug 18, 2020	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 46 on the current Payment Estimate.
					9	Aug 18, 2020	SYSTEM	(\$1,600.00)	
					10	Sep 3, 2020	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3553	0240	FLASHING ARROW	Material						Estimate Exception 32 on the current Payment Estimate.
		PANEL			10	Sep 3, 2020	SYSTEM	(\$1,600.00)	
				- Total				(\$400.00)	
			Material - Tota	ıl				(\$400.00)	
			MaterialCredit		2	May 4, 2020	SYSTEM	\$400.00	
				- Total				\$400.00	
			MaterialCredit					\$400.00	
			Other Item Adjustment	MDPA		Apr 16, 2020	woodsk1	\$400.00	
					2	May 4, 2020	woodsk1	(\$400.00)	This adjustment is being added to balance line item 0240 discrepancy amount.
				MDPA - Tot	al			\$0.00	
			Other Item Ad	justment - To	tal			\$0.00	
	0240 -	Total						\$0.00	
	0250	CMS W/O COMMUNICATION INTERFACE, CONT	Material		1	Apr 16, 2020	SYSTEM	(\$3,500.00)	
		F/			2	May 4, 2020	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					2	May 4, 2020	SYSTEM	(\$3,500.00)	
					3	May 19, 2020	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					3	May 19, 2020	SYSTEM	(\$3,500.00)	
					4	Jun 3, 2020	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					4	Jun 3, 2020	SYSTEM	(\$3,500.00)	
					5	Jun 16, 2020	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					5	Jun 16, 2020	SYSTEM	(\$3,500.00)	
					6	Jul 2, 2020	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					6	Jul 2, 2020	SYSTEM	(\$3,500.00)	
					7	Jul 16, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					7	Jul 16, 2020	SYSTEM	(\$7,000.00)	
					8	Aug 3, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					8	Aug 3, 2020	SYSTEM	(\$7,000.00)	· · · · · · · · · · · · · · · · · · ·
					9	Aug 18, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 48 on the current Payment Estimate.
					9	Aug 18, 2020	SYSTEM	(\$7,000.00)	
					10	Sep 3, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
					10	Sep 3, 2020	SYSTEM	(\$7,000.00)	
				- Total		2020		(\$3,500.00)	
			Material - Tota					(\$3,500.00)	
					2	May 4	CVCTEM		
			MaterialCredit		2	May 4,	SYSTEM	\$3,500.00	



John	on on on
NTERFACE, CONT   F/   MaterialCredit - Total   S3,500.00	on on on
Other Item Adjustment    MDPA   1	on on on
Adjustment   2020   2   May 4, woodsk1 (\$3,500.00)   This adjustment is being added to balance line item 0250 discrepa	on on on
MDPA - Total   S0.00	on on on
Other Item Adjustment - Total  \$0.00    MGS GUARDRAIL   Construction Stockpile   4	on on
Solution   Stockpile   Support   S	on on
MGS GUARDRAIL  Construction Stockpile  4 Jun 3, 2020 (\$5,068.25) Payment Estimate Item Adjustment generated Stockpile Transaction (\$4,001.25) Payment Estimate Item Adjustment generated Stockpile Transaction (\$1,000) Payment Estimate Item Adjustment generated	on on
Stockpile    2020	on on
2020  10 Sep 3, 2020  11 Sep 16, 27STEM (\$4,001.25) Payment Estimate Item Adjustment generated Stockpile Transaction  12 Oct 1, 27STEM (\$15,204.75) Payment Estimate Item Adjustment generated Stockpile Transaction  14 Nov 2, 2020  15 SYSTEM (\$13,070.75) Payment Estimate Item Adjustment generated Stockpile Transaction  16 System (\$13,070.75) Payment Estimate Item Adjustment generated Stockpile Transaction  17 System (\$13,070.75) Payment Estimate Item Adjustment generated Stockpile Transaction  18 System (\$35,477.75) Payment Estimate Item Adjustment generated Stockpile Transaction  2020 System (\$4,001.25) Payment Estimate Item Adjustment generated Stockpile Transaction  2021 System (\$4,001.25) Payment Estimate Item Adjustment generated Stockpile Transaction  2021 System (\$4,001.25) Payment Estimate Item Adjustment generated Stockpile Transaction  2021 System (\$4,001.25) Payment Estimate Item Adjustment generated Stockpile Transaction  2021 System (\$4,001.25) Payment Estimate Item Adjustment generated Stockpile Transaction  2021 System (\$4,001.25) Payment Estimate Item Adjustment generated Stockpile Transaction  2021 System (\$4,001.25) Payment Estimate Item Adjustment generated Stockpile Transaction  2021 System (\$4,001.25) Payment Estimate Item Adjustment generated Stockpile Transaction  2021 System (\$4,001.25) Payment Estimate Item Adjustment generated Stockpile Transaction  2021 System (\$4,001.25) Payment Estimate Item Adjustment generated Stockpile Transaction  2021 System (\$4,001.25) Payment Estimate Item Adjustment generated Stockpile Transaction  2021 System (\$4,001.25) Payment Estimate Item Adjustment generated Stockpile Transaction  2021 System (\$4,001.25) Payment Estimate Item Adjustment generated Stockpile Transaction  2021 System (\$4,001.25) Payment Estimate Item Adjustment generated Stockpile Transaction  2021 System (\$4,001.25) Payment Estimate Item Adjustment generated Stockpile Transaction  2021 System (\$4,001.25) Payment Estimate Item Adjustment generated Stockpile Transaction  2021 System (\$4,001.	on
2020  11 Sep 16, SYSTEM (\$4,001.25) Payment Estimate Item Adjustment generated Stockpile Transaction  12 Oct 1, SYSTEM (\$15,204.75) Payment Estimate Item Adjustment generated Stockpile Transaction  14 Nov 2, SYSTEM (\$13,070.75) Payment Estimate Item Adjustment generated Stockpile Transaction  23 Mar 16, SYSTEM (\$35,477.75) Payment Estimate Item Adjustment generated Stockpile Transaction  24 Apr 2, SYSTEM (\$4,001.25) Payment Estimate Item Adjustment generated Stockpile Transaction  3 SYSTEM (\$4,001.25) Payment Estimate Item Adjustment generated Stockpile Transaction  4 SYSTEM (\$4,001.25) Payment Estimate Item Adjustment generated Stockpile Transaction  5 SYSTEM (\$4,001.25) Payment Estimate Item Adjustment generated Stockpile Transaction  6 SYSTEM (\$4,001.25) Payment Estimate Item Adjustment generated Stockpile Transaction  7 SYSTEM (\$4,001.25) Payment Estimate Item Adjustment generated Stockpile Transaction  8 SYSTEM (\$4,001.25) Payment Estimate Item Adjustment generated Stockpile Transaction	on
2020  12 Oct 1, 2VSTEM (\$15,204.75) Payment Estimate Item Adjustment generated Stockpile Transaction  14 Nov 2, 2020  23 Mar 16, 2021  24 Apr 2, 2021  - Total  Construction Stockpile - Total  (\$85,893.50)  SYSTEM (\$15,204.75) Payment Estimate Item Adjustment generated Stockpile Transaction  (\$15,204.75) Pay	
2020  14 Nov 2, 2020  23 Mar 16, 2021  24 Apr 2, 2021  - Total  Construction Stockpile - Total  (\$13,070.75) Payment Estimate Item Adjustment generated Stockpile Transaction (\$35,477.75) Payment Estimate Item Adjustment generated Stockpile Transaction (\$4,001.25) Payment Estimate Item Adjustment generated Stockpile Transaction (\$85,893.50)	
2020 23 Mar 16, 2021 (\$35,477.75) Payment Estimate Item Adjustment generated Stockpile Transaction 24 Apr 2, 2021 (\$4,001.25) Payment Estimate Item Adjustment generated Stockpile Transaction  - Total (\$85,893.50)  Construction Stockpile - Total (\$85,893.50)	n
2021  24 Apr 2, 2021  - Total (\$85,893.50)  Construction Stockpile - Total (\$85,893.50)	n
2021   (\$85,893.50)	on
Construction Stockpile - Total (\$85,893.50)	on
Construction 4 As-40 CVCTFM 605 900 FG 500 FG 100 A March 100 A Ma	
Construction 1 Apr 16, SYSTEM \$85,893.50 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile 2020	n
- Total \$85,893.50	
Construction Stockpile STMI - Total \$85,893.50	
Overrun Overrun 24 Apr 2, 2021 \$1,000.00 This adjustment offsets the original system-generated Overrun Pay Estimate Item Adjustment (0002) due to user woodsk1 overridding Estimate Exception 38 on the current Payment Estimate.	
24 Apr 2, SYSTEM (\$1,000.00)	
Overrun - Total \$0.00	
Overrun - Total \$0.00	
0350 - Total \$0.00	
0360 MGS BRIDGE APP. Construction 4 Jun 3, SYSTEM (\$2,998.00) Payment Estimate Item Adjustment generated Stockpile Transaction 1 System 1 System 1 System 2020	n
(REG/NO CURB)  6 Jul 2, 2020  SYSTEM (\$2,998.00) Payment Estimate Item Adjustment generated Stockpile Transaction	n
10 Sep 3, 2020 SYSTEM (\$2,998.00) Payment Estimate Item Adjustment generated Stockpile Transaction	n
11 Sep 16, 2020 (\$2,998.00) Payment Estimate Item Adjustment generated Stockpile Transaction	n
Nov 2, 2020 SYSTEM (\$2,998.00) Payment Estimate Item Adjustment generated Stockpile Transaction	n
23 Mar 16, 2021 (\$14,990.00) Payment Estimate Item Adjustment generated Stockpile Transaction	n
24 Apr 2, 2021 SYSTEM (\$2,998.00) Payment Estimate Item Adjustment generated Stockpile Transaction	on
2021  29 Jun 16, SYSTEM (\$2,998.00) Payment Estimate Item Adjustment generated Stockpile Transaction	
2021  29 Jun 16, SYSTEM (\$2,998.00) Payment Estimate Item Adjustment generated Stockpile Transaction 2021	
29 Jun 16, 2021  - Total (\$35,976.00)  Construction Stockpile - Total (\$35,976.00)	on
29 Jun 16, 2021 (\$2,998.00) Payment Estimate Item Adjustment generated Stockpile Transaction  - Total (\$35,976.00)  Construction Stockpile - Total (\$35,976.00)  Construction 1 Apr 16, SYSTEM \$35,976.00 Payment Estimate Item Adjustment generated Stockpile Transaction	on



				<b></b>								
Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
J9I3553	0360	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	Other Item Adjustment	STMA	29	Jun 17, 2021	woodsk1	\$2,998.00	Reapplies stockpile adjustment that was generated initially with no overall pay being given.			
		(1.25/110 001.2)							The line item was paid then reduced due to overrun and change order anticipated to address payment.			
									This adjustment corrects the stockpile deduction since no pay is being made in general.			
				STMA - Tota	al			\$2,998.00				
			Other Item Adj	djustment - Total				\$2,998.00				
	0360 -	) - Total						\$2,998.00				
	0370	MGS END ANCHOR	Construction Stockpile		12	Oct 1, 2020	SYSTEM	(\$3,210.00)	Payment Estimate Item Adjustment generated Stockpile Transaction			
				- Total				(\$3,210.00)				
			Construction S	Stockpile - To	tal			(\$3,210.00)				
			Construction Stockpile		1	Apr 16, 2020	SYSTEM	\$3,210.00	Payment Estimate Item Adjustment generated Stockpile Transaction			
			STMI	- Total				\$3,210.00				
			Construction S	Stockpile STMI - Total				\$3,210.00				
	0370 -	Total						\$0.00				
	0380	TYPE A CRASHWORTHY	Construction Stockpile		4	Jun 3, 2020	SYSTEM	(\$3,020.00)	Payment Estimate Item Adjustment generated Stockpile Transaction			
		END TERMINAL (MASH)			6	Jul 2, 2020	SYSTEM	(\$3,020.00)	Payment Estimate Item Adjustment generated Stockpile Transaction			
					10	Sep 3, 2020	SYSTEM	(\$3,020.00)	Payment Estimate Item Adjustment generated Stockpile Transaction			
					11	Sep 16, 2020	SYSTEM	(\$3,020.00)	Payment Estimate Item Adjustment generated Stockpile Transaction			
					12	Oct 1, 2020	SYSTEM	(\$9,060.00)	Payment Estimate Item Adjustment generated Stockpile Transaction			
					14	Nov 2, 2020	SYSTEM	(\$3,020.00)	Payment Estimate Item Adjustment generated Stockpile Transaction			
					23	Mar 16, 2021	SYSTEM	(\$16,610.00)	Payment Estimate Item Adjustment generated Stockpile Transaction			
					29	Apr 2, 2021 Jun 16,	SYSTEM	(\$3,020.00)	Payment Estimate Item Adjustment generated Stockpile Transaction  Payment Estimate Item Adjustment generated Stockpile Transaction			
				Total	20	2021	OTOTEM	, , ,	Tayrion Estimate term registrion generated electrone transaction			
				- Total				(\$45,300.00)				
			Construction Construction Stockpile	Stockpile - To				(\$45,300.00)				
					1	Apr 16, 2020	SYSTEM	\$45,300.00	Payment Estimate Item Adjustment generated Stockpile Transaction			
			STMI	- Total				\$45,300.00				
			Construction S	Stockpile STI	/II - Total			\$45,300.00				
			Other Item Adjustment	STMA	29	Jun 17, 2021	woodsk1	\$1,510.00	Reapplies stockpile adjustment that was generated initially with no overall pay being given.			
									The line item was paid then reduced due to overrun and change order anticipated to address payment.			
									This adjustment corrects the stockpile deduction since no pay is being made in general.			
				STMA - Tota	al			\$1,510.00				
			Other Item Adj	justment - To	tal			\$1,510.00				
	0380 - Total							\$1,510.00				
	0400	EMULSIFIED ASPHALT, SEAL COAT	Material		9	Aug 18, 2020	SYSTEM	\$265.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.			
					9	Aug 18, 2020	SYSTEM	(\$265.00)	Connect Exception to on the outent rayment Estimate.			
				- Total				\$0.00				
			Material - Tota					\$0.00				
			Other Item Adjustment	ACAD	19	Jan 20, 2021	woodsk1	(\$19.32)	AC Seal Coat Adjustment. August 17th, 2020 placement date.			
			,	ACAD - Tota	al			(\$19.32)				
				ACAD - Total				(7.0.02)				



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
J9I3553	0400	EMULSIFIED ASPHALT, SEAL COAT	Other Item Ad	justment - To	tal			(\$19.32)			
	0400 -	Total						(\$19.32)			
	0410	SEAL COAT AGGREGATE, GRADE B1	Material		9	Aug 18, 2020	SYSTEM	\$662.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 26 on the current Payment Estimate.		
					9	Aug 18, 2020	SYSTEM	(\$662.50)			
					10	Sep 3, 2020	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.		
					10	Sep 3, 2020	SYSTEM	(\$1,325.00)			
					11	Sep 16, 2020	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.		
					11	Sep 16, 2020	SYSTEM	(\$1,325.00)			
					12	Oct 1, 2020	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.		
					12	Oct 1, 2020	SYSTEM	(\$1,325.00)			
					13	Oct 16, 2020	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.		
					13	Oct 16, 2020	SYSTEM	(\$1,325.00)			
				14 14 15 15 16 16 17	14	Nov 2, 2020	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.		
					14	Nov 2, 2020	SYSTEM	(\$1,325.00)			
					15	Nov 17, 2020	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.		
					15	15	Nov 17, 2020	SYSTEM	(\$1,325.00)		
					16	Dec 2, 2020	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.		
					16	Dec 2, 2020	SYSTEM	(\$1,325.00)			
					Dec 16, 2020	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.			
					17	Dec 16, 2020	SYSTEM	(\$1,325.00)			
					18	Jan 4, 2021	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.		
				18 19 19 20	18	Jan 4, 2021	SYSTEM	(\$1,325.00)			
						19		19	Jan 20, 2021	SYSTEM	\$1,325.00
					19	Jan 20, 2021	SYSTEM	(\$1,325.00)			
					20	Feb 1, 2021	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.		
					20	Feb 1, 2021	SYSTEM	(\$1,325.00)			
					21	Feb 16, 2021	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.		
					21	Feb 16, 2021	SYSTEM	(\$1,325.00)			



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J9I3553	0410	SEAL COAT AGGREGATE, GRADE B1	Material		22	Mar 2, 2021	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
					22	Mar 2, 2021	SYSTEM	(\$1,325.00)		
					23	Mar 16, 2021	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
					23	Mar 16, 2021	SYSTEM	(\$1,325.00)		
					24	Apr 2, 2021	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
					24	Apr 2, 2021	SYSTEM	(\$1,325.00)		
					25	Apr 16, 2021	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
					25	Apr 16, 2021	SYSTEM	(\$1,325.00)		
					26	May 3, 2021	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	
					26	May 3, 2021	SYSTEM	(\$1,325.00)		
					27	May 17, 2021	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
					27	May 17, 2021	SYSTEM	(\$1,325.00)		
					28	Jun 2, 2021	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
					28	Jun 2, 2021	SYSTEM	(\$1,325.00)		
					29	Jun 16, 2021	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	
			Material - Total		29	Jun 16, 2021	SYSTEM	(\$1,325.00)		
				- Total				\$0.00		
	0440	T-4-1		al				\$0.00 \$0.00		
	0410 -	CURB BLOCKOUT	Material		2	May 4, 2020	SYSTEM	\$11,278.05	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	
					2	May 4, 2020	SYSTEM	(\$11,278.05)		
					3	May 19, 2020	SYSTEM	\$16,671.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.	
					3	May 19, 2020	SYSTEM	(\$16,671.90)		
					4	Jun 3, 2020	SYSTEM	\$16,671.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 26 on the current Payment Estimate.	
					4	Jun 3, 2020	SYSTEM	(\$16,671.90)		
					5	Jun 16, 2020	SYSTEM	\$16,671.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 26 on the current Payment Estimate.	
						5	Jun 16, 2020	SYSTEM	(\$16,671.90)	
					6	Jul 2, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.	
					6	Jul 2, 2020	SYSTEM	(\$33,343.80)		
					7	Jul 16,	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment	





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																			
J9I3553	0420	20 CURB BLOCKOUT	Material			2020			Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 34 on the current Payment Estimate.																			
					7	Jul 16, 2020	SYSTEM	(\$33,343.80)																				
					8	Aug 3, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 40 on the current Payment Estimate.																			
					8	Aug 3, 2020	SYSTEM	(\$33,343.80)																				
					9	Aug 18, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 76 on the current Payment Estimate.																			
					9	Aug 18, 2020	SYSTEM	(\$33,343.80)																				
					10	Sep 3, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 62 on the current Payment Estimate.																			
					10	Sep 3, 2020	SYSTEM	(\$33,343.80)																				
					11	Sep 16, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 50 on the current Payment Estimate.																			
					11	Sep 16, 2020	SYSTEM	(\$33,343.80)																				
					12	Oct 1, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 26 on the current Payment Estimate.																			
						12	Oct 1, 2020	SYSTEM	(\$33,343.80)																			
					13	Oct 16, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 27 on the current Payment Estimate.																			
					13	Oct 16, 2020	SYSTEM	(\$33,343.80)																				
					14	Nov 2, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 28 on the current Payment Estimate.																			
						14	Nov 2, 2020	SYSTEM	(\$33,343.80)																			
					15	Nov 17, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 29 on the current Payment Estimate.																			
					15	Nov 17, 2020	SYSTEM	(\$33,343.80)																				
					16	Dec 2, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 29 on the current Payment Estimate.																			
						16	Dec 2, 2020	SYSTEM	(\$33,343.80)																			
						17	Dec 16, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 33 on the current Payment Estimate.																		
					17	Dec 16, 2020	SYSTEM	(\$33,343.80)																				
																								18	Jan 4, 2021	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
							18	Jan 4, 2021	SYSTEM	(\$33,343.80)																		
						19	Jan 20, 2021	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 10 on the current Payment Estimate.																		
														19	Jan 20, 2021	SYSTEM	(\$33,343.80)											
					20	Feb 1, 2021	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 10 on the current Payment Estimate.																			
					20	Feb 1, 2021	SYSTEM	(\$33,343.80)																				



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3553	0420	CURB BLOCKOUT	Material		21	Feb 16, 2021	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					21	Feb 16, 2021	SYSTEM	(\$33,343.80)	
					22	Mar 2, 2021	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					22	Mar 2, 2021	SYSTEM	(\$33,343.80)	
					23	Mar 16, 2021	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					23	Mar 16, 2021	SYSTEM	(\$33,343.80)	
					24	Apr 2, 2021	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					24	Apr 2, 2021	SYSTEM	(\$33,343.80)	
					25	Apr 16, 2021	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					25	Apr 16, 2021	SYSTEM	(\$33,343.80)	
					26	May 3, 2021	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					26	May 3, 2021	SYSTEM	(\$33,343.80)	
					27	May 17, 2021	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					27	May 17, 2021	SYSTEM	(\$33,343.80)	
					28	Jun 2, 2021	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					28	Jun 2, 2021	SYSTEM	(\$33,343.80)	
					29	Jun 16, 2021	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					29	Jun 16, 2021	SYSTEM	(\$33,343.80)	
				- Total				\$0.00	
	0420 -	Total	Material - Tota					\$0.00 \$0.00	
		HALF-SOLE REPAIR	Material		3	May 19, 2020	SYSTEM	\$12,412.98	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					3	May 19, 2020	SYSTEM	(\$12,412.98)	
					4	Jun 3, 2020	SYSTEM	\$23,457.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
					4	Jun 3, 2020	SYSTEM	(\$23,457.60)	
					5	Jun 16, 2020	SYSTEM	\$37,727.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
					5	Jun 16, 2020	SYSTEM	(\$37,727.64)	
					6	Jul 2, 2020	SYSTEM	\$67,440.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 49 on the current Payment Estimate.
					6	Jul 2, 2020	SYSTEM	(\$67,440.60)	
					7	Jul 16,	SYSTEM	\$67,440.60	This adjustment offsets the original system-generated Overrun Payment





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks														
J9I3553	0430	HALF-SOLE REPAIR	Material			2020			Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 52 on the current Payment Estimate.														
					7	Jul 16, 2020	SYSTEM	(\$67,440.60)															
					8	Aug 3, 2020	SYSTEM	\$67,440.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 52 on the current Payment Estimate.														
					8	Aug 3, 2020	SYSTEM	(\$67,440.60)															
					9	Aug 18, 2020	SYSTEM	\$67,440.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 87 on the current Payment Estimate.														
					9	Aug 18, 2020	SYSTEM	(\$67,440.60)															
					10	Sep 3, 2020	SYSTEM	\$67,440.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 73 on the current Payment Estimate.														
					10	Sep 3, 2020	SYSTEM	(\$67,440.60)															
					11	Sep 16, 2020	SYSTEM	\$67,440.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 62 on the current Payment Estimate.														
					11	Sep 16, 2020	SYSTEM	(\$67,440.60)															
					12	Oct 1, 2020	SYSTEM	\$73,793.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 45 on the current Payment Estimate.														
					12	Oct 1, 2020	SYSTEM	(\$73,793.70)															
					13	Oct 16, 2020	SYSTEM	\$73,793.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 46 on the current Payment Estimate.														
					13	Oct 16, 2020	SYSTEM	(\$73,793.70)															
					14	Nov 2, 2020	SYSTEM	\$73,793.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 47 on the current Payment Estimate.														
					14	Nov 2, 2020	SYSTEM	(\$73,793.70)															
					15	Nov 17, 2020	SYSTEM	\$73,793.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 48 on the current Payment Estimate.														
					15	Nov 17, 2020	SYSTEM	(\$73,793.70)															
					16	Dec 2, 2020	SYSTEM	\$73,793.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 48 on the current Payment Estimate.														
					16	Dec 2, 2020	SYSTEM	(\$73,793.70)															
																			17	Dec 16, 2020	SYSTEM	\$73,793.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 52 on the current Payment Estimate.
						17	Dec 16, 2020	SYSTEM	(\$73,793.70)														
					18	Jan 4, 2021	SYSTEM	\$73,793.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 45 on the current Payment Estimate.														
					18	Jan 4, 2021	SYSTEM	(\$73,793.70)															
					19	Jan 20, 2021	SYSTEM	\$73,793.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 33 on the current Payment Estimate.														
					19	Jan 20, 2021	SYSTEM	(\$73,793.70)															
					20	Feb 1, 2021	SYSTEM	\$73,793.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 33 on the current Payment Estimate.														
					20	Feb 1, 2021	SYSTEM	(\$73,793.70)															



ject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
3553	0430	HALF-SOLE REPAIR	Material	, ypc	21	Feb 16, 2021	SYSTEM	\$73,793.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Paymen Estimate Exception 33 on the current Payment Estimate.
					21	Feb 16, 2021	SYSTEM	(\$73,793.70)	
					22	Mar 2, 2021	SYSTEM	\$73,793.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Paymen Estimate Exception 33 on the current Payment Estimate.
					22	Mar 2, 2021	SYSTEM	(\$73,793.70)	·
					23	Mar 16, 2021	SYSTEM	\$73,793.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Paymer Estimate Exception 33 on the current Payment Estimate.
					23	Mar 16, 2021	SYSTEM	(\$73,793.70)	
					24	Apr 2, 2021	SYSTEM	\$73,793.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Paymer Estimate Exception 29 on the current Payment Estimate.
					24	Apr 2, 2021	SYSTEM	(\$73,793.70)	
					25	Apr 16, 2021	SYSTEM	\$73,793.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payme Estimate Exception 29 on the current Payment Estimate.
					25	Apr 16, 2021	SYSTEM	(\$73,793.70)	
					26	May 3, 2021	SYSTEM	\$73,793.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payme Estimate Exception 38 on the current Payment Estimate.
					26	May 3, 2021	SYSTEM	(\$73,793.70)	
					27	May 17, 2021	SYSTEM	\$73,793.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payme Estimate Exception 45 on the current Payment Estimate.
					27	May 17, 2021	SYSTEM	(\$73,793.70)	
					28	Jun 2, 2021	SYSTEM	\$73,793.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payme Estimate Exception 51 on the current Payment Estimate.
					28	Jun 2, 2021	SYSTEM	(\$73,793.70)	
					29	Jun 16, 2021	SYSTEM	\$73,793.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payme Estimate Exception 52 on the current Payment Estimate.
					29	Jun 16, 2021	SYSTEM	(\$73,793.70)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0430 -							\$0.00	
	0450	EMULSIFIED ASPHALT, SEAL COAT	Material		9	Aug 18, 2020	SYSTEM	\$287.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payme Estimate Exception 5 on the current Payment Estimate.
					9	Aug 18, 2020	SYSTEM	(\$287.50)	
			Material	- Total				\$0.00	
			Material - Tota		10	lam 00	was dele	\$0.00	AC Coal Coat Adjustment - August 47th - 0000 all account date
			Other Item Adjustment	ACAD		Jan 20, 2021	woodsk1	(\$20.96)	AC Seal Coat Adjustment. August 17th, 2020 placement date.
			ou	ACAD - Tot				(\$20.96)	
	0.450	Total	Other Item Ad	justment - To	ital			(\$20.96)	
	0450 -		Mada di 1			A 10	OVOTE:	(\$20.96)	This call out was to first a the extension of the contract of
	0460	SEAL COAT AGGREGATE, GRADE B1	Material		9	Aug 18, 2020	SYSTEM	\$720.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payme Estimate Exception 27 on the current Payment Estimate.
					9	Aug 18, 2020	SYSTEM	(\$720.00)	
					10	Sep 3, 2020	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payme



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3553	0460	SEAL COAT	Material	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,					Estimate Exception 13 on the current Payment Estimate.
		AGGREGATE, GRADE B1			10	Sep 3, 2020	SYSTEM	(\$1,440.00)	
					11	Sep 16, 2020	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					11	Sep 16, 2020	SYSTEM	(\$1,440.00)	
					12	Oct 1, 2020	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					12	Oct 1, 2020	SYSTEM	(\$1,440.00)	
					13	Oct 16, 2020	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					13	Oct 16, 2020	SYSTEM	(\$1,440.00)	Estimate Exception 3 on the current rayment Estimate.
					14	Nov 2, 2020	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment
					14	Nov 2,	SYSTEM	(\$1,440.00)	Estimate Exception 5 on the current Payment Estimate.
					15	2020 Nov 17, 2020	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					15	Nov 17, 2020	SYSTEM	(\$1,440.00)	
					16	Dec 2, 2020	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					16	Dec 2, 2020	SYSTEM	(\$1,440.00)	
					17	Dec 16, 2020	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					17	Dec 16, 2020	SYSTEM	(\$1,440.00)	
					18	Jan 4, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					18	Jan 4, 2021	SYSTEM	(\$1,440.00)	
					19	Jan 20, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					19	Jan 20, 2021	SYSTEM	(\$1,440.00)	
					20	Feb 1, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					20	Feb 1, 2021	SYSTEM	(\$1,440.00)	
					21	Feb 16, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					21	Feb 16, 2021	SYSTEM	(\$1,440.00)	
					22	Mar 2, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					22	Mar 2, 2021	SYSTEM	(\$1,440.00)	
					23	Mar 16, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					23	Mar 16, 2021	SYSTEM	(\$1,440.00)	
					24	Apr 2,	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3553	0460	SEAL COAT AGGREGATE, GRADE B1	Material			2021			Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		GRADE BT			24	Apr 2, 2021	SYSTEM	(\$1,440.00)	
					25	Apr 16, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					25	Apr 16, 2021	SYSTEM	(\$1,440.00)	
					26	May 3, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					26	May 3, 2021	SYSTEM	(\$1,440.00)	
					27	May 17, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					27	May 17, 2021	SYSTEM	(\$1,440.00)	
					28	Jun 2, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					28	Jun 2, 2021	SYSTEM	(\$1,440.00)	
					29	Jun 16, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					29	Jun 16, 2021	SYSTEM	(\$1,440.00)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0460 -	- Total						\$0.00	
						8440			
	0470	CURB BLOCKOUT	Material		3	May 19, 2020	SYSTEM	\$12,100.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
	0470	CURB BLOCKOUT	Material		3		SYSTEM	\$12,100.62 (\$12,100.62)	Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment
	0470	CURB BLOCKOUT	Material			2020 May 19,			Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 25 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment
	0470	CURB BLOCKOUT	Material		3	2020 May 19, 2020 Jun 3,	SYSTEM	(\$12,100.62)	Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 25 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment
	0470	CURB BLOCKOUT	Material		3	2020 May 19, 2020 Jun 3, 2020	SYSTEM SYSTEM	(\$12,100.62) \$17,908.92	Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 25 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment
	0470	CURB BLOCKOUT	Material		3 4	2020 May 19, 2020 Jun 3, 2020 Jun 3, 2020 Jun 16,	SYSTEM SYSTEM SYSTEM	(\$12,100.62) \$17,908.92 (\$17,908.92)	Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 25 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment
	0470	CURB BLOCKOUT	Material		3 4 4 5	2020 May 19, 2020 Jun 3, 2020 Jun 3, 2020 Jun 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM	(\$12,100.62) \$17,908.92 (\$17,908.92) \$17,908.92	Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 25 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment
	0470	CURB BLOCKOUT	Material		3 4 4 5	2020 May 19, 2020 Jun 3, 2020 Jun 16, 2020 Jun 16, 2020 Jun 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM	(\$12,100.62) \$17,908.92 (\$17,908.92) \$17,908.92 (\$17,908.92)	Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 25 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment
	0470	CURB BLOCKOUT	Material		3 4 4 5 5 5 6	2020 May 19, 2020 Jun 3, 2020 Jun 16, 2020 Jun 16, 2020 Jul 2, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$12,100.62) \$17,908.92 (\$17,908.92) \$17,908.92 (\$17,908.92) \$35,817.85	Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 25 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Exception 38 on the current Payment Estimate.
	0470	CURB BLOCKOUT	Material		3 4 4 5 5 6 6 6	2020  May 19, 2020  Jun 3, 2020  Jun 36, 2020  Jun 16, 2020  Jul 2, 2020  Jul 16, 2020  Jul 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$12,100.62) \$17,908.92 (\$17,908.92) \$17,908.92 (\$17,908.92) \$35,817.85	Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 25 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Exception 38 on the current Payment Estimate.
	0470	CURB BLOCKOUT	Material		3 4 4 5 5 6 6 7 7	2020 May 19, 2020 Jun 3, 2020 Jun 16, 2020 Jul 2, 2020 Jul 2, 2020 Jul 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$12,100.62) \$17,908.92 (\$17,908.92) \$17,908.92 (\$17,908.92) \$35,817.85 (\$35,817.85) \$35,817.85	Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 25 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
	0470	CURB BLOCKOUT	Material		3 4 5 5 6 7 7	2020 May 19, 2020 Jun 3, 2020 Jun 16, 2020 Jul 2, 2020 Jul 2, 2020 Jul 16, 2020 Jul 16, 2020 Aug 3,	SYSTEM	(\$12,100.62) \$17,908.92 (\$17,908.92) \$17,908.92 (\$17,908.92) \$35,817.85 (\$35,817.85) \$35,817.85	Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 25 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 40 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Exception 40 on the current Payment Estimate.
	0470	CURB BLOCKOUT	Material		3 4 4 5 5 6 7 7 8	2020  May 19, 2020  Jun 3, 2020  Jun 16, 2020  Jul 2, 2020  Jul 16, 2020  Jul 16, 2020  Aug 3, 2020  Aug 3,	SYSTEM	(\$12,100.62) \$17,908.92 (\$17,908.92) \$17,908.92 (\$17,908.92) \$35,817.85 (\$35,817.85) \$35,817.85 (\$35,817.85)	Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 25 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 40 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Exception 40 on the current Payment Estimate.
	0470	CURB BLOCKOUT	Material		3 4 5 5 6 7 7 8 8	2020  May 19, 2020  Jun 3, 2020  Jun 16, 2020  Jul 2, 2020  Jul 2, 2020  Jul 16, 2020  Aug 3, 2020  Aug 3, 2020  Aug 18, 4	SYSTEM	(\$12,100.62) \$17,908.92 (\$17,908.92) \$17,908.92 (\$17,908.92) \$35,817.85 (\$35,817.85) \$35,817.85 (\$35,817.85)	Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 25 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 40 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 34 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3553	0470	CURB BLOCKOUT	Material	.,					Estimate Exception 50 on the current Payment Estimate.
					10	Sep 3, 2020	SYSTEM	(\$35,817.85)	
					11	Sep 16, 2020	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
					11	Sep 16, 2020	SYSTEM	(\$35,817.85)	
					12	Oct 1, 2020	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
					12	Oct 1, 2020	SYSTEM	(\$35,817.85)	
					13	Oct 16, 2020	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
					13	Oct 16, 2020	SYSTEM	(\$35,817.85)	Estimate Escapacion de different agriculta agr
					14	Nov 2, 2020	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
					14	Nov 2, 2020	SYSTEM	(\$35,817.85)	
					15	Nov 17, 2020	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
					15	Nov 17, 2020	SYSTEM	(\$35,817.85)	
					16	Dec 2, 2020	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
					16	Dec 2, 2020	SYSTEM	(\$35,817.85)	
					17	Dec 16, 2020	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
					17	Dec 16, 2020	SYSTEM	(\$35,817.85)	
					18	Jan 4, 2021	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					18	Jan 4, 2021	SYSTEM	(\$35,817.85)	
					19	Jan 20, 2021	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					19	Jan 20, 2021	SYSTEM	(\$35,817.85)	
					20	Feb 1, 2021	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					20	Feb 1, 2021	SYSTEM	(\$35,817.85)	
					21	Feb 16, 2021	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					21	Feb 16, 2021	SYSTEM	(\$35,817.85)	
					22	Mar 2, 2021	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					22	Mar 2, 2021	SYSTEM	(\$35,817.85)	
					23	Mar 16, 2021	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					23	Mar 16, 2021	SYSTEM	(\$35,817.85)	
					24	Apr 2,	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Material Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J9I3553	0470	CURB BLOCKOUT	Material			2021			Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	
					24	Apr 2, 2021	SYSTEM	(\$35,817.85)		
					25	Apr 16, 2021	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	
					25	Apr 16, 2021	SYSTEM	(\$35,817.85)		
					26	May 3, 2021	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.	
					26	May 3, 2021	SYSTEM	(\$35,817.85)		
					27	May 17, 2021	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 25 on the current Payment Estimate.	
					27	May 17, 2021	SYSTEM	(\$35,817.85)		
					28	Jun 2, 2021	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 25 on the current Payment Estimate.	
						28	Jun 2, 2021	SYSTEM	(\$35,817.85)	
					29	Jun 16, 2021	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 26 on the current Payment Estimate.	
					29	Jun 16, 2021	SYSTEM	(\$35,817.85)		
				- Total				\$0.00		
			Material - Tota	ıl				\$0.00		
	0470 -	- Total						\$0.00		
	0480	HALF-SOLE REPAIR	Material		3	May 19,	SYSTEM	\$4,160.68	This adjustment offsets the original system-generated Overrun Payment	
	0400		Waterial			2020			Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 31 on the current Payment Estimate.	
	0460		Waterial		3	2020 May 19, 2020	SYSTEM	(\$4,160.68)	Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment	
	0460		Waterial			May 19,	SYSTEM SYSTEM	(\$4,160.68) \$25,157.60	Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 31 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment	
	0460		Waterial		3	May 19, 2020 Jun 3,			Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 31 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment	
	0460		Waterland		3	May 19, 2020 Jun 3, 2020 Jun 3,	SYSTEM	\$25,157.60	Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 31 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment	
	0480		Waterial		3 4	May 19, 2020 Jun 3, 2020 Jun 3, 2020 Jun 16,	SYSTEM SYSTEM	\$25,157.60 (\$25,157.60)	Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 31 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment	
	0480		Waterial		3 4 4 5	May 19, 2020 Jun 3, 2020 Jun 3, 2020 Jun 16, 2020 Jun 16,	SYSTEM SYSTEM SYSTEM	\$25,157.60 (\$25,157.60) \$41,510.04	Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 31 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment	
	0480				3 4 4 5	May 19, 2020 Jun 3, 2020 Jun 3, 2020 Jun 16, 2020 Jun 16, 2020 Jun 16, 2020 Jun 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM	\$25,157.60 (\$25,157.60) \$41,510.04 (\$41,510.04)	Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 31 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment	
	0400				3 4 4 5 5 6 6	May 19, 2020 Jun 3, 2020 Jun 16, 2020 Jun 16, 2020 Jun 16, 2020 Jul 2, 2020 Jul 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$25,157.60 (\$25,157.60) \$41,510.04 (\$41,510.04) \$69,183.40	Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 31 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 45 on the current Payment Estimate.	
	0400				3 4 4 5 5 6 6 6	May 19, 2020 Jun 3, 2020 Jun 16, 2020 Jun 16, 2020 Jul 2, 2020 Jul 2, 2020 Jul 16, 2020 Jul 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$25,157.60 (\$25,157.60) \$41,510.04 (\$41,510.04) \$69,183.40	Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 31 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 45 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Exception 45 on the current Payment Estimate.	
	0400				3 4 4 5 5 6 6 7 7	May 19, 2020 Jun 3, 2020 Jun 3, 2020 Jun 16, 2020 Jun 16, 2020 Jul 2, 2020 Jul 16, 2020 Jul 16, 2020 Jul 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$25,157.60 (\$25,157.60) \$41,510.04 (\$41,510.04) \$69,183.40 (\$69,183.40) \$69,183.40	Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 31 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 45 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 48 on the current Payment Estimate.	
	0400				3 4 5 5 6 7 7	May 19, 2020 Jun 3, 2020 Jun 16, 2020 Jun 16, 2020 Jul 2, 2020 Jul 16, 2020 Jul 16, 2020 Jul 2, 2020 Jul 16, 2020 Jul 16, 2020 Aug 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$25,157.60 (\$25,157.60) \$41,510.04 (\$41,510.04) \$69,183.40 (\$69,183.40) \$69,183.40	Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 31 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 45 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 48 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Exception 48 on the current Payment Estimate.	
	0400				3 4 4 5 5 6 7 7 8	May 19, 2020 Jun 3, 2020 Jun 16, 2020 Jul 2, 2020 Jul 16, 2020 Jul 2, 2020 Jul 16, 2020 Aug 3, 2020 Aug 3,	SYSTEM	\$25,157.60 (\$25,157.60) \$41,510.04 (\$41,510.04) \$69,183.40 (\$69,183.40) \$69,183.40 (\$69,183.40)	Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 31 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 45 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 48 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Exception 48 on the current Payment Estimate.	
	0400				3 4 5 5 6 7 7 8 8	May 19, 2020 Jun 3, 2020 Jun 16, 2020 Jul 2, 2020 Jul 16, 2020 Jul 16, 2020 Aug 3, 2020 Aug 18, 4 May 18, 18, 2020	SYSTEM	\$25,157.60 (\$25,157.60) \$41,510.04 (\$41,510.04) \$69,183.40 (\$69,183.40) \$69,183.40 (\$69,183.40) \$69,183.40	Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 31 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 45 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 48 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Exception 48 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 48 on the current Payment Estimate.	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3553	0480	HALF-SOLE REPAIR	Material						Estimate Exception 69 on the current Payment Estimate.
					10	Sep 3, 2020	SYSTEM	(\$69,183.40)	
					11	Sep 16, 2020	SYSTEM	\$69,183.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 58 on the current Payment Estimate.
					11	Sep 16, 2020	SYSTEM	(\$69,183.40)	
					12	Oct 1, 2020	SYSTEM	\$69,957.48	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 50 on the current Payment Estimate.
					12	Oct 1, 2020	SYSTEM	(\$69,957.48)	
					13	Oct 16, 2020	SYSTEM	\$69,957.48	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 51 on the current Payment Estimate.
					13	Oct 16, 2020	SYSTEM	(\$69,957.48)	Estimate Exception of the current ayment Estimate.
					14	Nov 2, 2020	SYSTEM	\$69,957.48	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 52 on the current Payment Estimate.
					14	Nov 2,	SYSTEM	(\$69,957.48)	Estimate Exception 32 on the current Payment Estimate.
					15	2020 Nov 17, 2020	SYSTEM	\$69,957.48	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 53 on the current Payment Estimate.
					15	Nov 17, 2020	SYSTEM	(\$69,957.48)	
					16	Dec 2, 2020	SYSTEM	\$69,957.48	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 53 on the current Payment Estimate.
					16	Dec 2, 2020	SYSTEM	(\$69,957.48)	
					17	Dec 16, 2020	SYSTEM	\$69,957.48	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 47 on the current Payment Estimate.
					17	Dec 16, 2020	SYSTEM	(\$69,957.48)	
					18	Jan 4, 2021	SYSTEM	\$69,957.48	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 50 on the current Payment Estimate.
					18	Jan 4, 2021	SYSTEM	(\$69,957.48)	
					19	Jan 20, 2021	SYSTEM	\$69,957.48	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					19	Jan 20, 2021	SYSTEM	(\$69,957.48)	
					20	Feb 1, 2021	SYSTEM	\$69,957.48	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					20	Feb 1, 2021	SYSTEM	(\$69,957.48)	
					21	Feb 16, 2021	SYSTEM	\$69,957.48	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					21	Feb 16, 2021	SYSTEM	(\$69,957.48)	
					22	Mar 2, 2021	SYSTEM	\$69,957.48	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					22	Mar 2, 2021	SYSTEM	(\$69,957.48)	
					23	Mar 16, 2021	SYSTEM	\$69,957.48	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					23	Mar 16, 2021	SYSTEM	(\$69,957.48)	
					24	Apr 2,	SYSTEM	\$69,957.48	This adjustment offsets the original system-generated Material Payment



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
913553	0480	HALF-SOLE REPAIR	Material			2021			Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					24	Apr 2, 2021	SYSTEM	(\$69,957.48)	
					25	Apr 16, 2021	SYSTEM	\$69,957.48	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					25	Apr 16, 2021	SYSTEM	(\$69,957.48)	
					26	May 3, 2021	SYSTEM	\$69,957.48	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 41 on the current Payment Estimate.
					26	May 3, 2021	SYSTEM	(\$69,957.48)	
					27	May 17, 2021	SYSTEM	\$69,957.48	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 48 on the current Payment Estimate.
					27	May 17, 2021	SYSTEM	(\$69,957.48)	
					28	Jun 2, 2021	SYSTEM	\$69,957.48	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 54 on the current Payment Estimate.
					28	Jun 2, 2021	SYSTEM	(\$69,957.48)	
					29	Jun 16, 2021	SYSTEM	\$69,957.48	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 55 on the current Payment Estimate.
					29	Jun 16, 2021	SYSTEM	(\$69,957.48)	
				- Total				\$0.00	
			Material - Tota	otal			\$0.00		
	0480 -	- Total						\$0.00	
	0500	EMULSIFIED	Other Item	ACAD	10	Jan 20,		(040.00)	AC Cool Cook Adjustment Contembre 25th 2020 placement date
	0000	ASPHALT, SEAL COAT	Other Item Adjustment	ACAD		2021	woodsk1	(\$19.33)	AC Seal Coat Adjustment. September 25th 2020 placement date.
	0000	ASPHALT, SEAL	Adjustment	ACAD - Tot	al		WOODSKT	(\$19.33)	AC Sear Coat Adjustment. September 25th 2020 placement date.
		ASPHALT, SEAL COAT		ACAD - Tot	al		Woodskil	(\$19.33) (\$19.33)	AC Sear Coat Adjustment. September 25th 2020 placement date.
	<b>0500</b> -	ASPHALT, SEAL COAT  Total  SEAL COAT AGGREGATE,	Adjustment Other Item Ad	ACAD - Tot	al		SYSTEM	(\$19.33)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Paymen
	0500 -	ASPHALT, SEAL COAT  Total  SEAL COAT	Adjustment Other Item Ad	ACAD - Tot	al tal	Jan 20, 2021 Jan 20,		(\$19.33) (\$19.33) (\$19.33)	This adjustment offsets the original system-generated Material Payment
	0500 -	ASPHALT, SEAL COAT  Total  SEAL COAT AGGREGATE,	Adjustment Other Item Ad	ACAD - Tot	al tal	Jan 20, 2021	SYSTEM	(\$19.33) (\$19.33) (\$19.33) \$1,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment
	0500 -	ASPHALT, SEAL COAT  Total  SEAL COAT AGGREGATE,	Adjustment Other Item Ad	ACAD - Tot	19	Jan 20, 2021  Jan 20, 2021  Feb 1,	SYSTEM SYSTEM	(\$19.33) (\$19.33) (\$19.33) \$1,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
	0500 -	ASPHALT, SEAL COAT  Total  SEAL COAT AGGREGATE,	Adjustment Other Item Ad	ACAD - Tot	19 19 20	Jan 20, 2021  Jan 20, 2021  Jan 20, 2021  Feb 1, 2021	SYSTEM SYSTEM SYSTEM	(\$19.33) (\$19.33) (\$19.33) \$1,325.00 (\$1,325.00) \$1,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment
	0500 -	ASPHALT, SEAL COAT  Total  SEAL COAT AGGREGATE,	Adjustment Other Item Ad	ACAD - Tot	19 19 20 20	Jan 20, 2021  Jan 20, 2021  Jan 20, 2021  Feb 1, 2021  Feb 1, 2021  Feb 16,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$19.33) (\$19.33) (\$19.33) \$1,325.00 (\$1,325.00) (\$1,325.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment
	0500 -	ASPHALT, SEAL COAT  Total  SEAL COAT AGGREGATE,	Adjustment Other Item Ad	ACAD - Tot	19 19 20 21	Jan 20, 2021  Jan 20, 2021  Jan 20, 2021  Feb 1, 2021  Feb 16, 2021  Feb 16, 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$19.33) (\$19.33) (\$19.33) \$1,325.00 (\$1,325.00) \$1,325.00 (\$1,325.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
	0500 -	ASPHALT, SEAL COAT  Total  SEAL COAT AGGREGATE,	Adjustment Other Item Ad	ACAD - Tot	19 19 20 21 21	Jan 20, 2021  Jan 20, 2021  Jan 20, 2021  Feb 1, 2021  Feb 16, 2021  Feb 16, 2021  Mar 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$19.33) (\$19.33) (\$19.33) (\$19.33) \$1,325.00 (\$1,325.00) (\$1,325.00) (\$1,325.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate.
	0500 -	ASPHALT, SEAL COAT  Total  SEAL COAT AGGREGATE,	Adjustment Other Item Ad	ACAD - Tot	19 19 20 20 21 21	Jan 20, 2021  Jan 20, 2021  Jan 20, 2021  Feb 1, 2021  Feb 16, 2021  Mar 2, 2021  Mar 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$19.33) (\$19.33) (\$19.33) \$1,325.00 (\$1,325.00) (\$1,325.00) (\$1,325.00) (\$1,325.00) (\$1,325.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
	0500 -	ASPHALT, SEAL COAT  Total  SEAL COAT AGGREGATE,	Adjustment Other Item Ad	ACAD - Tot	19 19 20 20 21 21 22	Jan 20, 2021  Jan 20, 2021  Jan 20, 2021  Feb 1, 2021  Feb 16, 2021  Mar 2, 2021  Mar 16, 2021  Mar 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$19.33) (\$19.33) (\$19.33) \$1,325.00 (\$1,325.00) (\$1,325.00) (\$1,325.00) (\$1,325.00) (\$1,325.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate.
	0500 -	ASPHALT, SEAL COAT  Total  SEAL COAT AGGREGATE,	Adjustment Other Item Ad	ACAD - Tot	19 19 20 20 21 21 22 22	Jan 20, 2021  Jan 20, 2021  Jan 20, 2021  Feb 1, 2021  Feb 16, 2021  Mar 2, 2021  Mar 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$19.33) (\$19.33) (\$19.33) \$1,325.00 (\$1,325.00) (\$1,325.00) (\$1,325.00) (\$1,325.00) (\$1,325.00) (\$1,325.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9l3553	0510	SEAL COAT AGGREGATE, GRADE B1	Material		25	Apr 16, 2021	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					25	Apr 16, 2021	SYSTEM	(\$1,325.00)	
					26	May 3, 2021	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					26	May 3, 2021	SYSTEM	(\$1,325.00)	
					27	May 17, 2021	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					27	May 17, 2021	SYSTEM	(\$1,325.00)	
					28	Jun 2, 2021	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					28	Jun 2, 2021	SYSTEM	(\$1,325.00)	
					29	Jun 16, 2021	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					29	Jun 16, 2021	SYSTEM	(\$1,325.00)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0510 -	Total						\$0.00	
	0520	CURB BLOCKOUT	Material		9	Aug 18, 2020	SYSTEM	\$16,671.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 70 on the current Payment Estimate.
					9	Aug 18, 2020	SYSTEM	(\$16,671.90)	
					10	Sep 3, 2020	SYSTEM	\$16,671.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 56 on the current Payment Estimate.
					10	Sep 3, 2020	SYSTEM	(\$16,671.90)	
					11	Sep 16, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 44 on the current Payment Estimate.
					11	Sep 16, 2020	SYSTEM	(\$33,343.80)	
					12	Oct 1, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					12	Oct 1, 2020	SYSTEM	(\$33,343.80)	
					13	Oct 16, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					13	Oct 16, 2020	SYSTEM	(\$33,343.80)	
					14	Nov 2, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					14	Nov 2, 2020	SYSTEM	(\$33,343.80)	
					15	Nov 17, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
					15	Nov 17, 2020	SYSTEM	(\$33,343.80)	
					16	Dec 2, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
					16	Dec 2, 2020	SYSTEM	(\$33,343.80)	
					17	Dec 16,	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment



oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																		
3553	0520	CURB BLOCKOUT	Material			2020			Estimate Item Adjustment (0010) due to user woodsk1 overridding Paymen Estimate Exception 27 on the current Payment Estimate.																		
					17	Dec 16, 2020	SYSTEM	(\$33,343.80)																			
					18	Jan 4, 2021	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Paymen Estimate Exception 32 on the current Payment Estimate.																		
					18	Jan 4, 2021	SYSTEM	(\$33,343.80)																			
					19	Jan 20, 2021	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Paymen Estimate Exception 21 on the current Payment Estimate.																		
					19	Jan 20, 2021	SYSTEM	(\$33,343.80)																			
					20	Feb 1, 2021	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Paymer Estimate Exception 21 on the current Payment Estimate.																		
					20	Feb 1, 2021	SYSTEM	(\$33,343.80)																			
					21	Feb 16, 2021	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Paymer Estimate Exception 21 on the current Payment Estimate.																		
					21	Feb 16, 2021	SYSTEM	(\$33,343.80)																			
					22	Mar 2, 2021	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payme Estimate Exception 21 on the current Payment Estimate.																		
					22	Mar 2, 2021	SYSTEM	(\$33,343.80)																			
													23	Mar 16, 2021	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payme Estimate Exception 21 on the current Payment Estimate.										
							23	Mar 16, 2021	SYSTEM	(\$33,343.80)																	
					24	Apr 2, 2021	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payme Estimate Exception 19 on the current Payment Estimate.																		
						24	Apr 2, 2021	SYSTEM	(\$33,343.80)																		
						25	Apr 16, 2021	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payme Estimate Exception 19 on the current Payment Estimate.																	
					25	Apr 16, 2021	SYSTEM	(\$33,343.80)																			
					26	May 3, 2021	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payme Estimate Exception 23 on the current Payment Estimate.																		
					26	May 3, 2021	SYSTEM	(\$33,343.80)																			
					27	May 17, 2021	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payme Estimate Exception 30 on the current Payment Estimate.																		
																				27	May 17, 2021	SYSTEM	(\$33,343.80)				
																							28	Jun 2, 2021	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payme Estimate Exception 30 on the current Payment Estimate.
																					28	Jun 2, 2021	SYSTEM	(\$33,343.80)			
			29	29	Jun 16, 2021	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payme Estimate Exception 31 on the current Payment Estimate.																			
					29	Jun 16, 2021	SYSTEM	(\$33,343.80)																			
				- Total				\$0.00																			
	0.00		Material - Total					\$0.00																			
	0520 -		Madagia		7	lul 40	0,407514	\$0.00	This collection at affects the collection in the collection of the																		
(	0530	HALF-SOLE REPAIR	Material		7	Jul 16, 2020	SYSTEM	\$8,503.38	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payme																		



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3553	0530	HALF-SOLE REPAIR	Material						Estimate Exception 47 on the current Payment Estimate.
					7	Jul 16, 2020	SYSTEM	(\$8,503.38)	
					8	Aug 3, 2020	SYSTEM	\$8,503.38	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 47 on the current Payment Estimate.
					8	Aug 3, 2020	SYSTEM	(\$8,503.38)	
					9	Aug 18, 2020	SYSTEM	\$23,457.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 82 on the current Payment Estimate.
					9	Aug 18, 2020	SYSTEM	(\$23,457.60)	
					10	Sep 3, 2020	SYSTEM	\$23,457.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment
					10	Sep 3,	SYSTEM	(\$23,457.60)	Estimate Exception 68 on the current Payment Estimate.
						2020			
					11	Sep 16, 2020	SYSTEM	\$23,457.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 57 on the current Payment Estimate.
					11	Sep 16, 2020	SYSTEM	(\$23,457.60)	
					12	Oct 1, 2020	SYSTEM	\$83,372.22	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 49 on the current Payment Estimate.
					12	Oct 1, 2020	SYSTEM	(\$83,372.22)	
					13	Oct 16, 2020	SYSTEM	\$83,372.22	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 50 on the current Payment Estimate.
					13	Oct 16, 2020	SYSTEM	(\$83,372.22)	
					14	Nov 2, 2020	SYSTEM	\$83,372.22	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 51 on the current Payment Estimate.
					14	Nov 2, 2020	SYSTEM	(\$83,372.22)	
					15	Nov 17, 2020	SYSTEM	\$83,372.22	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 52 on the current Payment Estimate.
					15	Nov 17, 2020	SYSTEM	(\$83,372.22)	
					16	Dec 2, 2020	SYSTEM	\$83,372.22	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 52 on the current Payment Estimate.
					16	Dec 2, 2020	SYSTEM	(\$83,372.22)	
					17	Dec 16, 2020	SYSTEM	\$83,372.22	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 51 on the current Payment Estimate.
					17	Dec 16, 2020	SYSTEM	(\$83,372.22)	
					18	Jan 4, 2021	SYSTEM	\$83,372.22	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 54 on the current Payment Estimate.
					18	Jan 4, 2021	SYSTEM	(\$83,372.22)	
					19	Jan 20, 2021	SYSTEM	\$83,372.22	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
					19	Jan 20, 2021	SYSTEM	(\$83,372.22)	
					20	Feb 1, 2021	SYSTEM	\$83,372.22	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
					20	Feb 1, 2021	SYSTEM	(\$83,372.22)	
					21	Feb 16,	SYSTEM	\$83,372.22	This adjustment offsets the original system-generated Material Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3553	0530	HALF-SOLE REPAIR	Material			2021			Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
					21	Feb 16, 2021	SYSTEM	(\$83,372.22)	
					22	Mar 2, 2021	SYSTEM	\$83,372.22	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
					22	Mar 2, 2021	SYSTEM	(\$83,372.22)	
					23	Mar 16, 2021	SYSTEM	\$83,372.22	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
					23	Mar 16, 2021	SYSTEM	(\$83,372.22)	
					24	Apr 2, 2021	SYSTEM	\$83,372.22	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					24	Apr 2, 2021	SYSTEM	(\$83,372.22)	
					25	Apr 16, 2021	SYSTEM	\$83,372.22	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					25	Apr 16, 2021	SYSTEM	(\$83,372.22)	
					26	May 3, 2021	SYSTEM	\$83,372.22	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 45 on the current Payment Estimate.
					26	May 3, 2021	SYSTEM	(\$83,372.22)	
					27	May 17, 2021	SYSTEM	\$83,372.22	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 52 on the current Payment Estimate.
					27	May 17, 2021	SYSTEM	(\$83,372.22)	
					28	Jun 2, 2021	SYSTEM	\$83,372.22	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 58 on the current Payment Estimate.
					28	Jun 2, 2021	SYSTEM	(\$83,372.22)	
					29	Jun 16, 2021	SYSTEM	\$83,372.22	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 59 on the current Payment Estimate.
					29	Jun 16, 2021	SYSTEM	(\$83,372.22)	
				- Total				\$0.00	
	0530 -	Total	Material - Tota	1				\$0.00 \$0.00	
	0550	EMULSIFIED ASPHALT, SEAL	Other Item Adjustment	ACAD	19	Jan 20, 2021	woodsk1	(\$17.50)	AC Seal Coat Adjustment. September 25th, 2020 placement date.
		COAT		ACAD - Tot	al			(\$17.50)	
			Other Item Ad	justment - To	tal			(\$17.50)	
	0550 -				40		0)/2==	(\$17.50)	
	0560	SEAL COAT AGGREGATE, GRADE B1	Material		19	Jan 20, 2021	SYSTEM	\$1,205.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Paymen Estimate Exception 5 on the current Payment Estimate.
					19	Jan 20, 2021	SYSTEM	(\$1,205.00)	
					20	Feb 1, 2021	SYSTEM	\$1,205.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					20	Feb 1, 2021	SYSTEM	(\$1,205.00)	
					21	Feb 16, 2021	SYSTEM	\$1,205.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					21	Feb 16, 2021	SYSTEM	(\$1,205.00)	. ,
						2021			



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																	
J9I3553	0560	SEAL COAT AGGREGATE, GRADE B1	Material		22	Mar 2, 2021	SYSTEM	\$1,205.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.																	
					22	Mar 2, 2021	SYSTEM	(\$1,205.00)																		
					23	Mar 16, 2021	SYSTEM	\$1,205.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.																	
					23	Mar 16, 2021	SYSTEM	(\$1,205.00)																		
					24	Apr 2, 2021	SYSTEM	\$1,205.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.																	
					24	Apr 2, 2021	SYSTEM	(\$1,205.00)																		
					25	Apr 16, 2021	SYSTEM	\$1,205.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.																	
					25	Apr 16, 2021	SYSTEM	(\$1,205.00)																		
					26	May 3, 2021	SYSTEM	\$1,205.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 6 on the current Payment Estimate.																	
						26	May 3, 2021	SYSTEM	(\$1,205.00)																	
												27	May 17, 2021	SYSTEM	\$1,205.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 10 on the current Payment Estimate.										
							27	May 17, 2021	SYSTEM	(\$1,205.00)																
							28	Jun 2, 2021	SYSTEM	\$1,205.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 10 on the current Payment Estimate.															
									28	Jun 2, 2021	SYSTEM	(\$1,205.00)														
						29	Jun 16, 2021	SYSTEM	\$1,205.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.																
					29	Jun 16, 2021	SYSTEM	(\$1,205.00)																		
				- Total				\$0.00																		
	0560 -	Total	Material - Tota	1				\$0.00 \$0.00																		
	0570	CURB BLOCKOUT	Material		9	Aug 18, 2020	SYSTEM	\$15,434.12	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 58 on the current Payment Estimate.																	
													9	Aug 18, 2020	SYSTEM	(\$15,434.12)										
																										10
							10	Sep 3, 2020	SYSTEM	(\$15,434.12)																
																11	Sep 16, 2020	SYSTEM	\$30,868.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.						
																		11	Sep 16, 2020	SYSTEM	(\$30,868.25)					
											1	1:	1													12
					12	Oct 1, 2020	SYSTEM	(\$30,868.25)																		
						1								13	13	Oct 16, 2020	SYSTEM	\$30,868.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate.							
											13	Oct 16, 2020	SYSTEM	(\$30,868.25)												
						14	Nov 2,	SYSTEM	\$30,868.25	This adjustment offsets the original system-generated Overrun Payment																





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																	
J9I3553	0570	CURB BLOCKOUT	Material			2020			Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 22 on the current Payment Estimate.																	
					14	Nov 2, 2020	SYSTEM	(\$30,868.25)																		
					15	Nov 17, 2020	SYSTEM	\$30,868.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 23 on the current Payment Estimate.																	
					15	Nov 17, 2020	SYSTEM	(\$30,868.25)																		
					16	Dec 2, 2020	SYSTEM	\$30,868.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 23 on the current Payment Estimate.																	
					16	Dec 2, 2020	SYSTEM	(\$30,868.25)																		
					17	Dec 16, 2020	SYSTEM	\$30,868.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate.																	
						17	Dec 16, 2020	SYSTEM	(\$30,868.25)																	
					18	Jan 4, 2021	SYSTEM	\$30,868.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.																	
					18	Jan 4, 2021	SYSTEM	(\$30,868.25)																		
						19	Jan 20, 2021	SYSTEM	\$30,868.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 27 on the current Payment Estimate.																
						19	Jan 20, 2021	SYSTEM	(\$30,868.25)																	
					20	Feb 1, 2021	SYSTEM	\$30,868.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 27 on the current Payment Estimate.																	
						20	Feb 1, 2021	SYSTEM	(\$30,868.25)																	
					21	Feb 16, 2021	SYSTEM	\$30,868.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 27 on the current Payment Estimate.																	
						21	Feb 16, 2021	SYSTEM	(\$30,868.25)																	
					22	Mar 2, 2021	SYSTEM	\$30,868.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 27 on the current Payment Estimate.																	
											22	Mar 2, 2021	SYSTEM	(\$30,868.25)												
							23	Mar 16, 2021	SYSTEM	\$30,868.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 27 on the current Payment Estimate.															
																						23	Mar 16, 2021	SYSTEM	(\$30,868.25)	
																	24	Apr 2, 2021	SYSTEM	\$30,868.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 24 on the current Payment Estimate.					
					24	Apr 2, 2021	SYSTEM	(\$30,868.25)																		
												25	Apr 16, 2021	SYSTEM	\$30,868.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 24 on the current Payment Estimate.										
					25	Apr 16, 2021	SYSTEM	(\$30,868.25)																		
				7	:	26	May 3, 2021	SYSTEM	\$30,868.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 28 on the current Payment Estimate.																
					26	May 3, 2021	SYSTEM	(\$30,868.25)																		
						;			27	May 17, 2021	SYSTEM	\$30,868.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 35 on the current Payment Estimate.													
					27	May 17, 2021	SYSTEM	(\$30,868.25)																		



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks													
J9I3553	0570	CURB BLOCKOUT	Material		28	Jun 2, 2021	SYSTEM	\$30,868.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 35 on the current Payment Estimate.													
					28	Jun 2, 2021	SYSTEM	(\$30,868.25)														
					29	Jun 16, 2021	SYSTEM	\$30,868.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 36 on the current Payment Estimate.													
					29	Jun 16, 2021	SYSTEM	(\$30,868.25)														
				- Total				\$0.00														
			Material - Tota	1				\$0.00														
	0570 -	Total						\$0.00														
	0580	HALF-SOLE REPAIR	Material		7	Jul 16, 2020	SYSTEM	\$21,758.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 55 on the current Payment Estimate.													
					7	Jul 16, 2020	SYSTEM	(\$21,758.00)														
					8	Aug 3, 2020	SYSTEM	\$21,758.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 55 on the current Payment Estimate.													
					8	Aug 3, 2020	SYSTEM	(\$21,758.00)														
					9	Aug 18, 2020	SYSTEM	\$21,758.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 90 on the current Payment Estimate.													
														9	Aug 18, 2020	SYSTEM	(\$21,758.00)					
					10	Sep 3, 2020	SYSTEM	\$21,758.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 76 on the current Payment Estimate.													
					10	Sep 3, 2020	SYSTEM	(\$21,758.00)														
					11	Sep 16, 2020	SYSTEM	\$21,758.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 65 on the current Payment Estimate.													
					11	Sep 16, 2020	SYSTEM	(\$21,758.00)														
				- Total				\$0.00														
			Material - Tota					\$0.00														
	0580 -	Total						\$0.00														
	0640	CLASS B-2 CONCRETE	Material		27	May 17, 2021	SYSTEM	\$7,097.08	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.													
					27	May 17, 2021	SYSTEM	(\$7,097.08)														
																		28	Jun 2, 2021	SYSTEM	\$17,012.11	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					28	Jun 2, 2021	SYSTEM	(\$17,012.11)														
					29	Jun 16, 2021	SYSTEM	\$17,012.11	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.													
					29	Jun 16, 2021	SYSTEM	(\$17,012.11)														
				- Total				\$0.00														
			Material - Tota					\$0.00														
	0640 - 0650	Total  CURB BLOCKOUT	Material		28	Jun 2,	SYSTEM	\$0.00 \$8,717.44	This adjustment offsets the original system-generated Material Payment													
					28	2021 Jun 2,	SYSTEM	(\$8,717.44)	Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 40 on the current Payment Estimate.													
					20	Jun 2, 2021	SISIEM	(φ0,/1/.44)														
					29	Jun 16, 2021	SYSTEM	\$50,682.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 41 on the current Payment Estimate.													



roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks								
913553	0650	CURB BLOCKOUT	Material		29	Jun 16, 2021	SYSTEM	(\$50,682.80)									
				- Total				\$0.00									
			Material - Tota					\$0.00									
	0650 -	Total						\$0.00									
	0680	REINFORCING STEEL (EPOXY COATED)	Material		27	May 17, 2021	SYSTEM	\$2,272.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 55 on the current Payment Estimate.								
					27	May 17, 2021	SYSTEM	(\$2,272.50)									
					28	Jun 2, 2021	SYSTEM	\$4,545.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 61 on the current Payment Estimate.								
					28	Jun 2, 2021	SYSTEM	(\$4,545.00)									
					29	Jun 16, 2021	SYSTEM	\$4,545.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 62 on the current Payment Estimate.								
					29	Jun 16, 2021	SYSTEM	(\$4,545.00)									
				- Total	al			\$0.00									
			Material - Tota					\$0.00									
	0680 -	Total						\$0.00									
	0730	CURB BLOCKOUT	Material	Material	Material	Material		26	May 3, 2021	SYSTEM	\$24,791.08	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 33 on the current Payment Estimate.					
				2	26	May 3, 2021	SYSTEM	(\$24,791.08)									
					27	May 17, 2021	SYSTEM	\$24,791.08	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 40 on the current Payment Estimate.								
														27	May 17, 2021	SYSTEM	(\$24,791.08)
					28	Jun 2, 2021	SYSTEM	\$49,582.17	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 46 on the current Payment Estimate.								
					28	Jun 2, 2021	SYSTEM	(\$49,582.17)									
					29	Jun 16, 2021	SYSTEM	\$49,582.17	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 47 on the current Payment Estimate.								
					29	Jun 16, 2021	SYSTEM	(\$49,582.17)									
				- Total				\$0.00									
			Material - Tota					\$0.00									
	0730 -							\$0.00									
	0740	HALF-SOLE REPAIR	Material		24	Apr 2, 2021	SYSTEM	\$36,341.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 37 on the current Payment Estimate.								
					24	Apr 2, 2021	SYSTEM	(\$36,341.40)									
					29	25	Apr 16, 2021	SYSTEM	\$36,341.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 37 on the current Payment Estimate.							
					25	Apr 16, 2021	SYSTEM	(\$36,341.40)									
					26	May 3, 2021	SYSTEM	\$36,341.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 46 on the current Payment Estimate.								
					26	May 3, 2021	SYSTEM	(\$36,341.40)									
				- Total				\$0.00									
			Material - Tota					\$0.00									
	0740 -							\$0.00									
	0760	EMULSIFIED ASPHALT, SEAL	Other Item Adjustment	SEAL	27	May 17, 2021	woodsk1	(\$1.35)	Applies to this payment period.								



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																	
J9I3553	0760	COAT	Other Item Adjustment	SEAL - Tota	ıl			(\$1.35)																		
			Other Item Adj	ustment - To	tal			(\$1.35)																		
	0760 -	Total						(\$1.35)																		
	0770	SEAL COAT AGGREGATE, GRADE B1	Material		27	May 17, 2021	SYSTEM	\$2,315.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 6 on the current Payment Estimate.																	
					27	May 17, 2021	SYSTEM	(\$2,315.00)																		
					28	Jun 2, 2021	SYSTEM	\$2,315.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 6 on the current Payment Estimate.																	
					28	Jun 2, 2021	SYSTEM	(\$2,315.00)																		
					29	Jun 16, 2021	SYSTEM	\$2,315.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate.																	
					29	Jun 16, 2021	SYSTEM	(\$2,315.00)																		
				- Total				\$0.00																		
			Material - Tota					\$0.00																		
	0770 -	Total						\$0.00																		
	0780	HALF-SOLE REPAIR	Material	Material	Material	Material	aterial	// Material	11	Sep 16, 2020	SYSTEM	\$2,577.84	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 56 on the current Payment Estimate.													
											11	Sep 16, 2020	SYSTEM	(\$2,577.84)												
					12	Oct 1, 2020	SYSTEM	\$14,607.76	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 44 on the current Payment Estimate.																	
																						12	Oct 1, 2020	SYSTEM	(\$14,607.76)	
							13	Oct 16, 2020	SYSTEM	\$42,964.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 45 on the current Payment Estimate.															
						13	Oct 16, 2020	SYSTEM	(\$42,964.00)																	
					14	Nov 2, 2020	SYSTEM	\$42,964.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 46 on the current Payment Estimate.																	
					14	Nov 2, 2020	SYSTEM	(\$42,964.00)																		
																		15	Nov 17, 2020	SYSTEM	\$42,964.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 47 on the current Payment Estimate.				
					15	Nov 17, 2020	SYSTEM	(\$42,964.00)																		
											16	Dec 2, 2020	SYSTEM	\$42,964.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 47 on the current Payment Estimate.											
					16	Dec 2, 2020	SYSTEM	(\$42,964.00)																		
					17	Dec 16, 2020	SYSTEM	\$244,035.52	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 46 on the current Payment Estimate.																	
					17	Dec 16, 2020	SYSTEM	(\$244,035.52)																		
					18	Jan 4, 2021	SYSTEM	\$244,035.52	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 48 on the current Payment Estimate.																	
					18	Jan 4, 2021	SYSTEM	(\$244,035.52)																		
				- Total				\$0.00																		
			Material - Tota					\$0.00																		
	0780 -	Total						\$0.00																		
	0800	EMULSIFIED ASPHALT, SEAL	Other Item Adjustment	SEAL	27	May 17, 2021	woodsk1	(\$1.35)	Applies to this payment period.																	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																					
J9I3553	0800	COAT	Other Item Adjustment	SEAL - Tota	ıl			(\$1.35)																						
			Other Item Adj	ustment - To	tal			(\$1.35)																						
	0800 -	- Total						(\$1.35)																						
	0810	SEAL COAT AGGREGATE, GRADE B1	Material		27	May 17, 2021	SYSTEM	\$2,315.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate.																					
					27	May 17, 2021	SYSTEM	(\$2,315.00)																						
					28	Jun 2, 2021	SYSTEM	\$2,315.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate.																					
					28	Jun 2, 2021	SYSTEM	(\$2,315.00)																						
					29	Jun 16, 2021	SYSTEM	\$2,315.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.																					
					29	Jun 16, 2021	SYSTEM	(\$2,315.00)																						
				- Total				\$0.00																						
			Material - Tota					\$0.00																						
	0810 -	- Total						\$0.00																						
	0820	HALF-SOLE REPAIR	Material	Material		11	Sep 16, 2020	SYSTEM	\$3,007.48	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 66 on the current Payment Estimate.																				
															11	Sep 16, 2020	SYSTEM	(\$3,007.48)												
					12	Oct 1, 2020	SYSTEM	\$42,964.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 48 on the current Payment Estimate.																					
																										12	Oct 1, 2020	SYSTEM	(\$42,964.00)	
							13	Oct 16, 2020	SYSTEM	\$42,964.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 49 on the current Payment Estimate.																			
								13	Oct 16, 2020	SYSTEM	(\$42,964.00)																			
					14	Nov 2, 2020	SYSTEM	\$42,964.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 50 on the current Payment Estimate.																					
					14	Nov 2, 2020	SYSTEM	(\$42,964.00)																						
					15	Nov 17, 2020	SYSTEM	\$42,964.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 51 on the current Payment Estimate.																					
					15	Nov 17, 2020	SYSTEM	(\$42,964.00)																						
									16	Dec 2, 2020	SYSTEM	\$42,964.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Paymen Estimate Exception 51 on the current Payment Estimate.																	
					16	Dec 2, 2020	SYSTEM	(\$42,964.00)																						
				17	17	Dec 16, 2020	SYSTEM	\$318,363.24	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Paymen Estimate Exception 45 on the current Payment Estimate.																					
					17	Dec 16, 2020	SYSTEM	(\$318,363.24)																						
					18	Jan 4, 2021	SYSTEM	\$318,363.24	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Paymen Estimate Exception 49 on the current Payment Estimate.																					
					18	Jan 4, 2021	SYSTEM	(\$318,363.24)																						
				- Total				\$0.00																						
			Material - Tota	1				\$0.00																						
	0820 -	- Total						\$0.00																						
	5004	SLAB EDGE REPAIR (BRIDGES)	Material		17	Dec 16, 2020	SYSTEM	\$5,398.58	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment																					



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks																
	20	2 coonpact	Туре	Adjustment Type	Number	Date	Ву	7 1110 1111	. temane																
J9I3553	5004	SLAB EDGE	Material	31					Estimate Exception 55 on the current Payment Estimate.																
		REPAIR (BRIDGES)			17	Dec 16,	SYSTEM	(\$5,398.58)																	
					18	2020 Jan 4, 2021	SYSTEM	\$5,398.58	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment																
					18		CVCTEM	(AE 300 E0)	Estimate Exception 56 on the current Payment Estimate.																
					10	Jan 4, 2021	SYSTEM	(\$5,398.58)																	
			Material - Tota	- Total				\$0.00 \$0.00																	
	5004 -	Total	Waterial - Tota					\$0.00																	
	5005	SLAB EDGE	Material		17	Dec 16,	SYSTEM	\$7,607.09	This adjustment offsets the original system-generated Overrun Payment																
		REPAIR (BRIDGES)				2020			Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 56 on the current Payment Estimate.																
					17	Dec 16, 2020	SYSTEM	(\$7,607.09)																	
					18	Jan 4, 2021	SYSTEM	\$7,607.09	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 55 on the current Payment Estimate.																
					18	Jan 4, 2021	SYSTEM	(\$7,607.09)																	
				- Total				\$0.00																	
			Material - Tota					\$0.00																	
	5005 -	Total						\$0.00																	
	5007	TEMPORARY LONG-TERM RUMBLE STRIPS	Material		26	May 3, 2021	SYSTEM	\$21,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.																
					26	May 3, 2021	SYSTEM	(\$21,600.00)																	
					27	May 17, 2021	SYSTEM	\$21,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.																
					27	May 17, 2021	SYSTEM	(\$21,600.00)																	
					28	Jun 2, 2021	SYSTEM	\$21,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.																
					28	Jun 2, 2021	SYSTEM	(\$21,600.00)	Estimate Exception 17 of the suitoff Estimate.																
					29	Jun 16, 2021	SYSTEM	\$21,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.																
					29	Jun 16, 2021	SYSTEM	(\$21,600.00)																	
				- Total		2021		\$0.00																	
			Material - Tota					\$0.00																	
	5007 -	Total						\$0.00																	
	5008	MISC. SHAPING SLOPES	Material		26	May 3, 2021	SYSTEM	\$2,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																
					26	May 3, 2021	SYSTEM	(\$2,520.00)	, ,																
																					27	May 17, 2021	SYSTEM	\$2,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment
								27	May 17, 2021	SYSTEM	(\$2,520.00)	Estimate Exception 1 on the current Payment Estimate.													
					28	Jun 2, 2021	SYSTEM	\$2,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																
					28	Jun 2, 2021	SYSTEM	(\$2,520.00)																	
							29	29	29	29			29	Jun 16, 2021	SYSTEM	\$2,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.								
					29	Jun 16,	SYSTEM	(\$2,520.00)																	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																			
J9I3553	5008	MISC. SHAPING SLOPES	Material			2021																						
		020120		- Total				\$0.00																				
		_	Material - Tota					\$0.00																				
	5008 -							\$0.00																				
	5009	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN	Material		26	May 3, 2021	SYSTEM	\$9,555.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.																			
					26	May 3, 2021	SYSTEM	(\$9,555.00)																				
					27	May 17, 2021	SYSTEM	\$9,555.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.																			
					27	May 17, 2021	SYSTEM	(\$9,555.00)																				
					28	Jun 2, 2021	SYSTEM	\$9,555.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.																			
					28	Jun 2, 2021	SYSTEM	(\$9,555.00)																				
					29	Jun 16, 2021	SYSTEM	\$9,555.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.																			
					29	Jun 16, 2021	SYSTEM	(\$9,555.00)																				
				- Total				\$0.00																				
			Material - Tota					\$0.00																				
	5009 -	Total						\$0.00																				
	5010	FULL DEPTH REPAIR	Material		26	May 3, 2021	SYSTEM	\$6,678.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 47 on the current Payment Estimate.																			
					26	May 3, 2021	SYSTEM	(\$6,678.00)																				
				- Total				\$0.00																				
			Material - Tota					\$0.00																				
	5010 -	Total						\$0.00																				
J9I3553 -	Total							\$54,918.20																				
J9S3571	0850	MISC. AGGREGATE FOR BASE	Material		2	May 4, 2020	SYSTEM	\$17,901.77	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																			
					2	May 4, 2020	SYSTEM	(\$17,901.77)																				
					3	May 19, 2020	SYSTEM	\$42,591.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																			
					3	May 19, 2020	SYSTEM	(\$42,591.62)																				
																								4	Jun 3, 2020	SYSTEM	\$42,591.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Jun 3, 2020	SYSTEM	(\$42,591.62)																				
														5	Jun 16, 2020	SYSTEM	\$42,591.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.										
					5	Jun 16, 2020	SYSTEM	(\$42,591.62)																				
						6	Jul 2, 2020	SYSTEM	\$42,591.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																		
				6	Jul 2, 2020	SYSTEM	(\$42,591.62)																					
					7	Jul 16, 2020	SYSTEM	\$42,591.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woods/1 overridding Payment Estimate Expension 1 on the current Payment Estimate.																			
					7	Jul 16,	SYSTEM	(\$42,591.62)	Estimate Exception 1 on the current Payment Estimate.																			
						2020																						



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9S3571	0850	MISC. AGGREGATE FOR BASE	Material	Type	8	Aug 3, 2020	SYSTEM	\$42,591.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					8	Aug 3, 2020	SYSTEM	(\$42,591.62)	
					9	Aug 18, 2020	SYSTEM	\$42,591.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					9	Aug 18, 2020	SYSTEM	(\$42,591.62)	
					10	Sep 3, 2020	SYSTEM	\$48,392.79	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					10	Sep 3,	SYSTEM	(\$48,392.79)	Estimate Exception 1 of the Current Fayment Estimate.
					11	2020 Sep 16, 2020	SYSTEM	\$48,392.79	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment
					11	Sep 16,	SYSTEM	(\$48,392.79)	Estimate Exception 1 on the current Payment Estimate.
					12	2020 Oct 1,	SYSTEM	\$64,697.64	This adjustment offsets the original system-generated Overrun Payment
						2020		. ,	Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					12	Oct 1, 2020	SYSTEM	(\$64,697.64)	
					13	Oct 16, 2020	SYSTEM	\$64,697.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					13	Oct 16, 2020	SYSTEM	(\$64,697.64)	
					14	Nov 2, 2020	SYSTEM	\$64,697.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					14	Nov 2, 2020	SYSTEM	(\$64,697.64)	
					15	Nov 17, 2020	SYSTEM	\$64,697.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					15	Nov 17, 2020	SYSTEM	(\$64,697.64)	
					16	Dec 2, 2020	SYSTEM	\$64,697.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					16	Dec 2, 2020	SYSTEM	(\$64,697.64)	
					17	Dec 16, 2020	SYSTEM	\$64,697.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					17	Dec 16, 2020	SYSTEM	(\$64,697.64)	
					18	Jan 4, 2021	SYSTEM	\$64,697.64	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					18	Jan 4, 2021	SYSTEM	(\$64,697.64)	
				- Total				\$0.00	
	0850	·Total	Material - Tota					\$0.00	
	0850 -	BIT. PAVEMENT	Other Item	ACAD	2	May 4,	woodsk1	\$0.00 \$460.98	
		MIXTURE PG64-22 (BP-1)	Adjustment		17	2020 Dec 16,	woodsk1	\$8.06	*See Attached AC Price Index Adjustment Sheet.
				ACAD - Tota	al	2020		\$469.04	
			Other Item Ad					\$469.04	
	0870	Total						\$469.04	
	0880	ASPHALTIC	Material		2	May 4,	SYSTEM	\$456,638.72	This adjustment offsets the original system-generated Overrun Payment
	2000	CONCRETE MIXTURE PG 70-22			_	2020	O . Livi	÷ .30,000.72	Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
J9S3571	0880	(SP125C MIX)	Material		2	May 4, 2020	SYSTEM	(\$456,638.72)					
					3	May 19, 2020	SYSTEM	\$456,638.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.				
					3	May 19, 2020	SYSTEM	(\$456,638.72)					
					4	Jun 3, 2020	SYSTEM	\$456,638.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.				
					4	Jun 3, 2020	SYSTEM	(\$456,638.72)					
					5	Jun 16, 2020	SYSTEM	\$456,638.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.				
					5	Jun 16, 2020	SYSTEM	(\$456,638.72)	,				
									6	Jul 2, 2020	SYSTEM	\$456,638.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
									6	Jul 2, 2020	SYSTEM	(\$456,638.72)	
											7	Jul 16, 2020	SYSTEM
					7	Jul 16, 2020	SYSTEM	(\$940,718.72)					
						8	Aug 3, 2020	SYSTEM	\$940,718.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.			
							8	Aug 3, 2020	SYSTEM	(\$940,718.72)			
							9	Aug 18, 2020	SYSTEM	\$940,718.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.		
							9	Aug 18, 2020	SYSTEM	(\$940,718.72)			
							10	Sep 3, 2020	SYSTEM	\$1,038,932.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.		
							10	Sep 3, 2020	SYSTEM	(\$1,038,932.50)			
					11	Sep 16, 2020	SYSTEM	\$1,038,932.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.				
					11	Sep 16, 2020	SYSTEM	(\$1,038,932.50)					
				- Total				\$0.00					
			Material - Tota					\$0.00					
			Other Item Adjustment	ACAD		Apr 16, 2020	woodsk1	\$1,227.35					
					2	May 4, 2020	woodsk1	\$1,493.29					
					17	Dec 16, 2020	woodsk1	\$7.00	*See Attached AC Price Index Adjustment Sheet.				
				ACAD - Tota				\$2,727.64					
				BITM	8	Aug 3, 2020	woodsk1	\$66,845.91	TSR #001 Payment Adjustment. Lot #001 \$18,153.00				
									TSR #002 Payment Adjustment. Lot #004 \$10,068.56				
									Lot 1 Bonus Payment Adjustment \$12,102.00				
									Lot 2 Bonus Payment Adjustment \$6,051.00				
									Lot 3 Bonus Payment Adjustment \$12,102.00				
									Lot 4 Bonus Payment Adjustment \$8,369.35				
									Total Bituminous Pay Factor Adjustment For Line Item Posting #0880 \$66,845.91				



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks						
J9S3571	0880		Other Item Adjustment	BITM - Tota				\$66,845.91							
			Other Item Adj	ustment - To	tal			\$69,573.55							
	0880 -	Total						\$69,573.55							
	0890	TACK COAT	Material		1	Apr 16,	SYSTEM	(\$10,486.00)							
					2	2020 May 4, 2020	SYSTEM	\$24,460.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment						
					2	May 4, 2020	SYSTEM	(\$24,460.20)	Estimate Exception 3 on the current Payment Estimate.						
					3	May 19, 2020	SYSTEM	\$24,460.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.						
					3	May 19, 2020	SYSTEM	(\$24,460.20)							
					4	Jun 3, 2020	SYSTEM	\$24,460.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.						
					4	Jun 3, 2020	SYSTEM	(\$24,460.20)							
							5	Jun 16, 2020	SYSTEM	\$24,460.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.				
								5	Jun 16, 2020	SYSTEM	(\$24,460.20)				
				6	Jul 2, 2020	SYSTEM	\$24,460.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.							
					6	Jul 2, 2020	SYSTEM	(\$24,460.20)							
					7	Jul 16, 2020	SYSTEM	\$24,460.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.						
									7	Jul 16, 2020	SYSTEM	(\$24,460.20)			
								8	Aug 3, 2020	SYSTEM	\$24,460.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.			
											8	Aug 3, 2020	SYSTEM	(\$24,460.20)	
													9	Aug 18, 2020	SYSTEM
									9	Aug 18, 2020	SYSTEM	(\$24,460.20)			
					10	Sep 3, 2020	SYSTEM	\$27,242.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.						
					10	Sep 3, 2020	SYSTEM	(\$27,242.20)							
					11	Sep 16, 2020	SYSTEM	\$27,242.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.						
					11	Sep 16, 2020	SYSTEM	(\$27,242.20)							
				- Total				(\$10,486.00)							
			Material - Tota					(\$10,486.00)							
	_		MaterialCredit		2	May 4, 2020	SYSTEM	\$10,486.00							
			- Total				\$10,486.00								
			MaterialCredit	- Total				\$10,486.00							
			Other Item Adjustment	MDPA	1	Apr 16, 2020	woodsk1	\$10,486.00							
					2	May 4, 2020	woodsk1	(\$10,486.00)	This adjustment is being added to balance line item 0890 discrepancy amount.						
				MDPA - Tota	al			\$0.00							



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																				
J9S3571	0890	TACK COAT	Other Item Adj	ustment - To	tal			\$0.00																					
	0890 -	Total						\$0.00																					
	0900	BITUMINOUS FOG SEAL	Material		2	May 4, 2020	SYSTEM	\$4,565.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.																				
					2	May 4, 2020	SYSTEM	(\$4,565.00)																					
					3	May 19, 2020	SYSTEM	\$8,436.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.																				
					3	May 19, 2020	SYSTEM	(\$8,436.95)																					
					4	Jun 3, 2020	SYSTEM	\$8,436.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.																				
					4	Jun 3, 2020	SYSTEM	(\$8,436.95)																					
					5	Jun 16, 2020	SYSTEM	\$8,436.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.																				
					5	Jun 16, 2020	SYSTEM	(\$8,436.95)																					
								6	Jul 2, 2020	SYSTEM	\$8,436.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.																	
							6	Jul 2, 2020	SYSTEM	(\$8,436.95)																			
					7	Jul 16, 2020	SYSTEM	\$8,436.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.																				
					7	Jul 16, 2020	SYSTEM	(\$8,436.95)																					
					8	Aug 3, 2020	SYSTEM	\$8,436.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.																				
					8	Aug 3, 2020	SYSTEM	(\$8,436.95)																					
					9	Aug 18, 2020	SYSTEM	\$8,436.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 29 on the current Payment Estimate.																				
					9	Aug 18, 2020	SYSTEM	(\$8,436.95)																					
							10	Sep 3, 2020	SYSTEM	\$10,511.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.																		
					10	Sep 3, 2020	SYSTEM	(\$10,511.95)																					
																	11	Sep 16, 2020	SYSTEM	\$10,511.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.								
					11	Sep 16, 2020	SYSTEM	(\$10,511.95)																					
					12	Oct 1, 2020	SYSTEM	\$19,920.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.																				
					12	Oct 1, 2020	SYSTEM	(\$19,920.00)																					
																									13	Oct 16, 2020	SYSTEM	\$19,920.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					13	Oct 16, 2020	SYSTEM	(\$19,920.00)																					
																14	Nov 2, 2020	SYSTEM	\$19,920.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 6 on the current Payment Estimate.									
				14	Nov 2, 2020	SYSTEM	(\$19,920.00)																						
				15	Nov 17, 2020	SYSTEM	\$19,920.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment																					



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9S3571	0900	BITUMINOUS FOG	Material						Estimate Exception 7 on the current Payment Estimate.
		SEAL			15	Nov 17, 2020	SYSTEM	(\$19,920.00)	
					16	Dec 2, 2020	SYSTEM	\$19,920.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					16	Dec 2, 2020	SYSTEM	(\$19,920.00)	
					17	Dec 16, 2020	SYSTEM	\$19,920.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					17	Dec 16, 2020	SYSTEM	(\$19,920.00)	
					18	Jan 4, 2021	SYSTEM	\$19,920.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					18	Jan 4, 2021	SYSTEM	(\$19,920.00)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0900 -	Total						\$0.00	
	0910	TRUCK OR TRAILER MOUNTED ATTEN (TMA)	Material		4	Jun 3, 2020	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					4	Jun 3, 2020	SYSTEM	(\$1,000.00)	
					5	Jun 16, 2020	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					5	Jun 16, 2020	SYSTEM	(\$1,000.00)	
					6	Jul 2, 2020	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					6	Jul 2, 2020	SYSTEM	(\$1,000.00)	
					7	Jul 16, 2020	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					7	Jul 16, 2020	SYSTEM	(\$1,000.00)	
					8	Aug 3, 2020	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					8	Aug 3, 2020	SYSTEM	(\$1,000.00)	
					9	Aug 18, 2020	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					9	Aug 18, 2020	SYSTEM	(\$1,000.00)	
					10	Sep 3, 2020	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					10	Sep 3, 2020	SYSTEM	(\$1,000.00)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0910 -	Total						\$0.00	
	0920	CONSTRUCTION SIGNS	Material		1	Apr 16, 2020	SYSTEM	(\$15,366.00)	
					2	May 4, 2020	SYSTEM	\$15,366.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					2	May 4, 2020	SYSTEM	(\$15,366.00)	
					3	May 19,	SYSTEM	\$15,366.00	This adjustment offsets the original system-generated Overrun Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9S3571	0920	CONSTRUCTION SIGNS	Material	. , , p =		2020			Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					3	May 19, 2020	SYSTEM	(\$15,366.00)	
					4	Jun 3, 2020	SYSTEM	\$15,366.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					4	Jun 3, 2020	SYSTEM	(\$15,366.00)	
					5	Jun 16, 2020	SYSTEM	\$15,366.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					5	Jun 16, 2020	SYSTEM	(\$15,366.00)	
					6	Jul 2, 2020	SYSTEM	\$15,366.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					6	Jul 2, 2020	SYSTEM	(\$15,366.00)	
					7	Jul 16, 2020	SYSTEM	\$15,366.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					7	Jul 16, 2020	SYSTEM	(\$15,366.00)	
					8	Aug 3, 2020	SYSTEM	\$15,366.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					8	Aug 3, 2020	SYSTEM	(\$15,366.00)	
					9	Aug 18, 2020	SYSTEM	\$15,366.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overridding Payment Estimate Exception 41 on the current Payment Estimate.
					9	Aug 18, 2020	SYSTEM	(\$15,366.00)	
					10	Sep 3, 2020	SYSTEM	\$15,366.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user woodsk1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					10	Sep 3, 2020	SYSTEM	(\$15,366.00)	
				- Total				(\$15,366.00)	
			Material - Tota	I				(\$15,366.00)	
			MaterialCredit		2	May 4, 2020	SYSTEM	\$15,366.00	
				- Total				\$15,366.00	
			MaterialCredit	- Total				\$15,366.00	
			Other Item Adjustment	MDPA	1	Apr 16, 2020	woodsk1	\$15,366.00	
					2	May 4, 2020	woodsk1	(\$15,366.00)	This adjustment is being added to balance line item 0920 discrepancy amount
				MDPA - Tot	al			\$0.00	
			Other Item Ad	justment - To	tal			\$0.00	
	0920 -	Total						\$0.00	
	0930	FLAG ASSEMBLY	Material		1	Apr 16, 2020	SYSTEM	(\$140.00)	
					2	May 4, 2020	SYSTEM	\$140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					2	May 4, 2020	SYSTEM	(\$140.00)	
					3	May 19, 2020	SYSTEM	\$140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					3	May 19, 2020	SYSTEM	(\$140.00)	
					4	Jun 3, 2020	SYSTEM	\$140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 10 on the current Payment Estimate.



MDPA - Total   S0.00	J9S3571 0930 FL	Description								
1000   1000	0930 - Total		Line		Adjustment				Amount	Remarks
2000   Eliminate form Aplicational Corp. Opin Opin Quick or worder (a) Payment Estimate.		FLAG ASSEMBLY	0930	Material		4		SYSTEM	(\$140.00)	
1						5		SYSTEM	\$140.00	Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment
2020   Editionale Blank Adjustment (0026) due to user woodskit oversiding Peyment						5		SYSTEM	(\$140.00)	
2020   14-00   15-00						6		SYSTEM	\$140.00	Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment
2000						6		SYSTEM	(\$140.00)	
7						7		SYSTEM	\$140.00	Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment
R						7		SYSTEM	(\$140.00)	
						8	Aug 3,	SYSTEM	\$140.00	Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment
2020   Estimate Item Adjustment (0029) due to user woodskt 1 overridding Payment Estimate   Estimate Exception 42 on the current Payment Estimate   Estimate Exception 42 on the current Payment Estimate   Estimate   Exception 42 on the current Payment Estimate   Estimate   Exception 12 on the current Payment   Estimate   Estima						8		SYSTEM	(\$140.00)	
10   Sep 3,   SYSTEM   S140.00   This adjustment offsets the original system-generated Overrun Payment Estimate Exception 28 on the current Payment Estimate Exception 28 on the current Payment Estimate Exception 28 on the current Payment Estimate.						9		SYSTEM	\$140.00	Estimate Item Adjustment (0029) due to user woodsk1 overridding Payment
2020						9		SYSTEM	(\$140.00)	
1-Total   (\$140.00)						10		SYSTEM	\$140.00	Estimate Item Adjustment (0031) due to user woodsk1 overridding Payment
Material - Total  Material Credit  2 May 4, SYSTEM \$140.00  - Total  S140.00  Material Credit \$140.00  Cither Item Adjustment  MDPA - Total  S140.00  MDPA - Total  S140.00  CHANNELIZER (TRIM LINE)  CHANNELIZER (TRIM LINE)  Material  A Jun 3, SYSTEM \$600.00  Dayson - Total  S200  SYSTEM \$600.00  SYSTEM \$600.00  This adjustment offsets the original system-generated Overrun Payment Estimate Exception 11 on the current Payment Estimate.  A Jun 3, SYSTEM \$600.00  This adjustment offsets the original system-generated Overrun Payment Estimate Exception 11 on the current Payment Estimate Exception 11 on the current Payment Estimate Exception 12 on the current Payment Estimate Exception 12 on the current Payment Estimate Exception 12 on the current Payment Estimate.  A Jun 3, SYSTEM \$600.00  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Item Adjustment (017) due to user woodsk1 overridding Payment Estimate Item Adjustment (017) due to user woodsk1 overridding Payment Estimate Item Adjustment (017) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  A Jul 2, SYSTEM \$600.00  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (017) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.  A Jul 2, SYSTEM \$600.00  This adjustment offsets the original system-generated Overrun Payment Estimate Exception 18 on the current Payment Estimate.  B Jul 2, SYSTEM \$600.00  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (017) due to user woodsk1 overridding Payment Estimate Item Adjustment (017) due to user woodsk1 overridding Payment Estimate Item Adjustment (017) due to user woodsk1 overridding Payment Estimate Item Adjustment (017) due to user woodsk1 overridding Payment Estimate Item Adjustment (017) due to user woodsk1 overridding Payment Estimate Item Adju						10		SYSTEM	(\$140.00)	
MaterialCredit					- Total				(\$140.00)	
Total				Material - Tota	d				(\$140.00)	
Material Credit - Total  Other Item Adjustment  MDPA 1 Apr 16, woodsk1 \$140.00  2 May 4, woodsk1 \$140.00  This adjustment is being added to balance line item 0180 discrepancy amount \$0.00  Other Item Adjustment - Total  S0.00  Other Item Adjustment - Total  S0.00  CHANNELIZER (TRIM LINE)  Material  4 Jun 3, SYSTEM \$600.00  This adjustment offsets the original system-generated Overrun Payment Estimate Exception 11 on the current Payment Estimate.  4 Jun 3, SYSTEM \$600.00  This adjustment offsets the original system-generated Overrun Payment Estimate Exception 11 on the current Payment Estimate.  5 Jun 16, SYSTEM \$600.00  This adjustment offsets the original system-generated Overrun Payment Estimate Exception 12 on the current Payment Estimate.  5 Jun 16, SYSTEM \$600.00  This adjustment offsets the original system-generated Overrun Payment Estimate Exception 12 on the current Payment Estimate.  5 Jun 16, SYSTEM \$600.00  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.  6 Jul 2, SYSTEM \$600.00  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Item Adjustment (002				MaterialCredit		2		SYSTEM	\$140.00	
Other Item Adjustment    MDPA   1					- Total				\$140.00	
Adjustment 2020  2 May 4, woodsk1 (\$140.00) This adjustment is being added to balance line item 0180 discrepancy amount    MDPA - Total				MaterialCredit	- Total				\$140.00	
MDPA - Total   \$0.00				Other Item						
Other Item Adjustment - Total  9940 CHANNELIZER (TRIM LINE)  Material  4 Jun 3, 2020 SYSTEM \$600.00  5 Jun 16, 2020 SYSTEM \$600.00  5 Jun 16, 2020 SYSTEM \$600.00  5 Jun 16, 2020 This adjustment offsets the original system-generated Overrun Payment Estimate Exception 11 on the current Payment Estimate.  5 Jun 16, 2020 This adjustment offsets the original system-generated Overrun Payment Estimate Exception 12 on the current Payment Estimate Exception 15 on the current Payment Estimate Exception 16 on the current Payment Estimate Exception 18 on the current Payment Estimate Exception 18 on the current Payment Estimate.  6 Jul 2, 2020 SYSTEM \$600.00  7 Jul 16, SYSTEM \$600.00  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.  6 Jul 2, 2020 This adjustment offsets the original system-generated Overrun Payment Estimate Exception 18 on the current Payment Estimate.  7 Jul 16, SYSTEM \$600.00  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment					MDPA			woodsk1	\$140.00	
Solid   Soli						2	2020 May 4,		(\$140.00)	This adjustment is being added to balance line item 0180 discrepancy amount.
CHANNELIZER (TRIM LINE)   Material				Adjustment	MDPA - Tot	2 al	2020 May 4,		(\$140.00) \$0.00	This adjustment is being added to balance line item 0180 discrepancy amount.
4 Jun 3, 2020 (\$600.00)  5 Jun 16, 2020 (\$600.00)  5 Jun 16, 2020 (\$600.00)  5 Jun 16, 2020 (\$600.00)  6 Jul 2, 2020 (\$600.00)  6 Jul 2, 2020 (\$600.00)  6 Jul 2, 2020 (\$600.00)  7 Jul 16, SYSTEM (\$600.00)  7 Jul 16, 2020 (\$600.00)  SYSTEM (\$600.00)  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.				Adjustment	MDPA - Tot	2 al	2020 May 4,		(\$140.00) \$0.00 \$0.00	This adjustment is being added to balance line item 0180 discrepancy amount.
5 Jun 16, 2020 \$YSTEM \$600.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  5 Jun 16, 2020 \$YSTEM \$600.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.  6 Jul 2, 2020 \$YSTEM \$600.00 This adjustment offsets the original system-generated Overrun Payment Estimate Exception 18 on the current Payment Estimate.		CHANNELIZER		Adjustment Other Item Ad	MDPA - Tot	2 al tal	2020 May 4, 2020 Jun 3,	woodsk1	(\$140.00) \$0.00 \$0.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment
5 Jun 16, 2020 (\$600.00) 6 Jul 2, 2020 SYSTEM \$600.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate. 6 Jul 2, 2020 (\$600.00) 7 Jul 16, SYSTEM \$600.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment		CHANNELIZER		Adjustment Other Item Ad	MDPA - Tot	2 al tal	Jun 3, 2020  Jun 3, 2020	woodsk1	(\$140.00) \$0.00 \$0.00 \$0.00 \$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment
2020 Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.  6 Jul 2, 2020  7 Jul 16, SYSTEM \$600.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment		CHANNELIZER		Adjustment Other Item Ad	MDPA - Tot	2 al tal 4	Jun 3, 2020 Jun 3, 2020 Jun 16,	woodsk1  SYSTEM  SYSTEM	(\$140.00) \$0.00 \$0.00 \$0.00 \$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment
2020  7 Jul 16, SYSTEM \$600.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment		CHANNELIZER		Adjustment Other Item Ad	MDPA - Tot	2 al tal 4 5	Jun 3, 2020 Jun 3, 2020 Jun 16, 2020 Jun 16, 2020	woodsk1  SYSTEM  SYSTEM  SYSTEM	(\$140.00) \$0.00 \$0.00 \$0.00 \$600.00 (\$600.00)	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment
2020 Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment		CHANNELIZER		Adjustment Other Item Ad	MDPA - Tot	2 aal tal 4 4 5 5 5	Jun 3, 2020  Jun 3, 2020  Jun 16, 2020  Jun 16, 2020  Jun 16, 2020  Jun 16, 2020	woodsk1  SYSTEM  SYSTEM  SYSTEM  SYSTEM	(\$140.00) \$0.00 \$0.00 \$0.00 \$600.00 (\$600.00)	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment
Estimate Exception 19 on the current Payment Estimate.		CHANNELIZER		Adjustment Other Item Ad	MDPA - Tot	2 al 4 4 5 5 6 6	Jun 3, 2020  Jun 3, 2020  Jun 16, 2020  Jun 16, 2020  Jul 2, 2020  Jul 2, 2020	woodsk1  SYSTEM  SYSTEM  SYSTEM  SYSTEM  SYSTEM	(\$140.00) \$0.00 \$0.00 \$600.00 (\$600.00) \$600.00 (\$600.00)	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment
7 Jul 16, 2020 (\$600.00)		CHANNELIZER		Adjustment Other Item Ad	MDPA - Tot	2 al tal 4 4 5 5 6 6 6	Jun 3, 2020  Jun 3, 2020  Jun 16, 2020  Jul 12, 2020  Jul 16, 2020  Jul 17, 2020  Jul 18, 2020  Jul 19, 2020  Jul 19, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$140.00) \$0.00 \$0.00 \$0.00 \$600.00 (\$600.00) \$600.00 (\$600.00)	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Exception 18 on the current Payment Estimate.
8 Aug 3, SYSTEM \$600.00 This adjustment offsets the original system-generated Overrun Payment		CHANNELIZER		Adjustment Other Item Ad	MDPA - Tot	2 al 4 4 5 5 6 6 7	Jun 3, 2020  Jun 3, 2020  Jun 16, 2020  Jul 12, 2020  Jul 16, 2020	woodsk1  SYSTEM  SYSTEM  SYSTEM  SYSTEM  SYSTEM  SYSTEM  SYSTEM	(\$140.00) \$0.00 \$0.00 \$0.00 \$600.00) \$600.00  (\$600.00) \$600.00  (\$600.00)	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Exception 18 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
J9S3571	0940	CHANNELIZER	Material	Type					Estimate Exception 19 on the current Payment Estimate.
		(TRIM LINE)			8	Aug 3, 2020	SYSTEM	(\$600.00)	
					9	Aug 18, 2020	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user woodsk1 overridding Payment Estimate Exception 43 on the current Payment Estimate.
					9	Aug 18, 2020	SYSTEM	(\$600.00)	
					10	Sep 3, 2020	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user woodsk1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					10	Sep 3, 2020	SYSTEM	(\$600.00)	
				- Total				\$0.00	
			Material - Tota	l e				\$0.00	
	0940 -	Total						\$0.00	
	0950	CMS W/O COMMUNICATION INTERFACE, CONT	Material		1	Apr 16, 2020	SYSTEM	(\$7,000.00)	
		F/			2	May 4, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					2	May 4, 2020	SYSTEM	(\$7,000.00)	
					3	May 19, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					3	May 19, 2020	SYSTEM	(\$7,000.00)	
					4	Jun 3, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					4	Jun 3, 2020	SYSTEM	(\$7,000.00)	
					5	Jun 16, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					5	Jun 16, 2020	SYSTEM	(\$7,000.00)	
					6	Jul 2, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					6	Jul 2, 2020	SYSTEM	(\$7,000.00)	
					7	Jul 16, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					7	Jul 16, 2020	SYSTEM	(\$7,000.00)	
					8	Aug 3, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					8	Aug 3, 2020	SYSTEM	(\$7,000.00)	
					9	Aug 18, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user woodsk1 overridding Payment Estimate Exception 47 on the current Payment Estimate.
					9	Aug 18, 2020	SYSTEM	(\$7,000.00)	
					10	Sep 3, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					10	Sep 3, 2020	SYSTEM	(\$7,000.00)	
				- Total				(\$7,000.00)	
			Material - Tota					(\$7,000.00)	
			MaterialCredit		2	May 4, 2020	SYSTEM	\$7,000.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9S3571	0950	CMS W/O	MaterialCredit	- Total				\$7,000.00	
		COMMUNICATION INTERFACE, CONT	MaterialCredit	- Total				\$7,000.00	
		F/	Other Item Adjustment	MDPA	1	Apr 16, 2020	woodsk1	\$7,000.00	
					2	May 4, 2020	woodsk1	(\$7,000.00)	This adjustment is being added to balance line item 0950 discrepancy amount.
				MDPA - Tota	al			\$0.00	
			Other Item Adj	justment - To	tal			\$0.00	
	0950 -	Total						\$0.00	
	0960	WORK ZONE TRAFFIC SIGNAL SYSTEM	Material		4	Jun 3, 2020	SYSTEM	\$8,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					4	Jun 3, 2020	SYSTEM	(\$8,400.00)	
					5	Jun 16, 2020	SYSTEM	\$8,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					5	Jun 16, 2020	SYSTEM	(\$8,400.00)	
					6	Jul 2, 2020	SYSTEM	\$8,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					6	Jul 2, 2020	SYSTEM	(\$8,400.00)	
					7	Jul 16, 2020	SYSTEM	\$8,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					7	Jul 16, 2020	SYSTEM	(\$8,400.00)	
					8	Aug 3, 2020	SYSTEM	\$8,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					8	Aug 3, 2020	SYSTEM	(\$8,400.00)	
					9	Aug 18, 2020	SYSTEM	\$8,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user woodsk1 overridding Payment Estimate Exception 49 on the current Payment Estimate.
					9	Aug 18, 2020	SYSTEM	(\$8,400.00)	
					10	Sep 3, 2020	SYSTEM	\$8,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0034) due to user woodsk1 overridding Payment Estimate Exception 35 on the current Payment Estimate.
					10	Sep 3, 2020	SYSTEM	(\$8,400.00)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0960 -	Total						\$0.00	
	0970	TEMPORARY LONG-TERM RUMBLE STRIPS	Material		4	Jun 3, 2020	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					4	Jun 3, 2020	SYSTEM	(\$3,600.00)	
					5	Jun 16, 2020	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					5	Jun 16, 2020	SYSTEM	(\$3,600.00)	
					6	Jul 2, 2020	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					6	Jul 2, 2020	SYSTEM	(\$3,600.00)	
					7	Jul 16, 2020	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					7	Jul 16, 2020	SYSTEM	(\$3,600.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9S3571	0970	TEMPORARY LONG-TERM RUMBLE STRIPS	Material		8	Aug 3, 2020	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user woodsk1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					8	Aug 3, 2020	SYSTEM	(\$3,600.00)	
					9	Aug 18, 2020	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 50 on the current Payment Estimate.
					9	Aug 18, 2020	SYSTEM	(\$3,600.00)	
					10	Sep 3, 2020	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0035) due to user woodsk1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					10	Sep 3, 2020	SYSTEM	(\$3,600.00)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0970 -	Total						\$0.00	
	0990	TEMPORARY REMOVABLE MARKING TAPE 4 IN.,	Material		4	Jun 3, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
		IIV.,			4	Jun 3, 2020	SYSTEM	(\$2,424.00)	
					5	Jun 16, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					5	Jun 16, 2020	SYSTEM	(\$2,424.00)	
					6	Jul 2, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user woodsk1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					6	Jul 2, 2020	SYSTEM	(\$2,424.00)	
					7	Jul 16, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					7	Jul 16, 2020	SYSTEM	(\$2,424.00)	
					8	Aug 3, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user woodsk1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					8	Aug 3, 2020	SYSTEM	(\$2,424.00)	
					9	Aug 18, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0034) due to user woodsk1 overridding Payment Estimate Exception 51 on the current Payment Estimate.
					9	Aug 18, 2020	SYSTEM	(\$2,424.00)	
					10	Sep 3, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0036) due to user woodsk1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
					10	Sep 3, 2020	SYSTEM	(\$2,424.00)	
					11	Sep 16, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					11	Sep 16, 2020	SYSTEM	(\$2,424.00)	
					12	Oct 1, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					12	Oct 1, 2020	SYSTEM	(\$2,424.00)	
					13	Oct 16, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					13	Oct 16, 2020	SYSTEM	(\$2,424.00)	
					14	Nov 2,	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9S3571	0990	TEMPORARY REMOVABLE	Material			2020			Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
		MARKING TAPE 4 IN.,			14	Nov 2, 2020	SYSTEM	(\$2,424.00)	
					15	Nov 17, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					15	Nov 17, 2020	SYSTEM	(\$2,424.00)	
					16	Dec 2, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					16	Dec 2, 2020	SYSTEM	(\$2,424.00)	
					17	Dec 16, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					17	Dec 16, 2020	SYSTEM	(\$2,424.00)	
					18	Jan 4, 2021	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					18	Jan 4, 2021	SYSTEM	(\$2,424.00)	
				- Total				\$0.00	
			Material - Tota	ı				\$0.00	
	0990 -	Total						\$0.00	
	1000	TEMPORARY REMOVABLE MARKING TAPE	Material		4	Jun 3, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					4	Jun 3, 2020	SYSTEM	(\$4,000.00)	
					5	Jun 16, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					5	Jun 16, 2020	SYSTEM	(\$4,000.00)	
					6	Jul 2, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user woodsk1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					6	Jul 2, 2020	SYSTEM	(\$4,000.00)	
					7	Jul 16, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user woodsk1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					7	Jul 16, 2020	SYSTEM	(\$4,000.00)	
					8	Aug 3, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user woodsk1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					8	Aug 3, 2020	SYSTEM	(\$4,000.00)	
					9	Aug 18, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0035) due to user woodsk1 overridding Payment Estimate Exception 52 on the current Payment Estimate.
					9	Aug 18, 2020	SYSTEM	(\$4,000.00)	
					10	Sep 3, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0037) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
					10	Sep 3, 2020	SYSTEM	(\$4,000.00)	
					11	Sep 16, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					11	Sep 16, 2020	SYSTEM	(\$4,000.00)	
					12	Oct 1, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9S3571	1000	TEMPORARY	Material						Estimate Exception 14 on the current Payment Estimate.
		REMOVABLE MARKING TAPE			12	Oct 1, 2020	SYSTEM	(\$4,000.00)	
					13	Oct 16, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					13	Oct 16, 2020	SYSTEM	(\$4,000.00)	
					14	Nov 2, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					14	Nov 2, 2020	SYSTEM	(\$4,000.00)	
					15	Nov 17, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					15	Nov 17, 2020	SYSTEM	(\$4,000.00)	
					16	Dec 2, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					16	Dec 2, 2020	SYSTEM	(\$4,000.00)	
					17	Dec 16, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					17	Dec 16, 2020	SYSTEM	(\$4,000.00)	
					18	Jan 4, 2021	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					18	Jan 4, 2021	SYSTEM	(\$4,000.00)	
				- Total				\$0.00	
	1000		Material - Tota	ıl				\$0.00	
	1010	TEMPORARY REMOVABLE MARKING TAPE, 24	Material		4	Jun 3, 2020	SYSTEM	\$0.00 \$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
		IN.			4	Jun 3, 2020	SYSTEM	(\$240.00)	
					5	Jun 16, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					5	Jun 16, 2020	SYSTEM	(\$240.00)	
					6	Jul 2, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					6	Jul 2, 2020	SYSTEM	(\$240.00)	
					7	Jul 16, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user woodsk1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					7	Jul 16, 2020	SYSTEM	(\$240.00)	
					8	Aug 3, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					8	Aug 3, 2020	SYSTEM	(\$240.00)	
					9	Aug 18, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0036) due to user woodsk1 overridding Payment Estimate Exception 53 on the current Payment Estimate.
					9		SYSTEM	\$240.00 (\$240.00)	Estimate Item Adjustment (0036) due to user woodsk1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9S3571	1010	TEMPORARY REMOVABLE	Material		10	Sep 3, 2020	SYSTEM	(\$240.00)	
		MARKING TAPE, 24 IN.			11	Sep 16, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					11	Sep 16, 2020	SYSTEM	(\$240.00)	
					12	Oct 1, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					12	Oct 1, 2020	SYSTEM	(\$240.00)	
					13	Oct 16, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					13	Oct 16, 2020	SYSTEM	(\$240.00)	
					14	Nov 2, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					14	Nov 2, 2020	SYSTEM	(\$240.00)	
					15	Nov 17, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					15	Nov 17, 2020	SYSTEM	(\$240.00)	
					16	Dec 2, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					16	Dec 2, 2020	SYSTEM	(\$240.00)	
					17	Dec 16, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					17	Dec 16, 2020	SYSTEM	(\$240.00)	
					18	Jan 4, 2021	SYSTEM	\$240.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					18	Jan 4, 2021	SYSTEM	(\$240.00)	
				- Total				\$0.00	
			Material - Tota	ı				\$0.00	
		Total						\$0.00	
	1020	4 IN. WHITE WATERBORNE PAVEMENT MARKING	Material		3	May 19, 2020	SYSTEM	\$6,270.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					3	May 19, 2020	SYSTEM	(\$6,270.00)	
					4	Jun 3, 2020	SYSTEM	\$6,270.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					4	Jun 3, 2020	SYSTEM	(\$6,270.00)	
					5	Jun 16, 2020	SYSTEM	\$6,270.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					5	Jun 16, 2020	SYSTEM	(\$6,270.00)	
					6	Jul 2, 2020	SYSTEM	\$6,270.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user woodsk1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					6	Jul 2, 2020	SYSTEM	(\$6,270.00)	
					7	Jul 16, 2020	SYSTEM	\$6,270.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user woodsk1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					7	Jul 16,	SYSTEM	(\$6,270.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9S3571	1020	4 IN. WHITE	Material			2020			
		WATERBORNE PAVEMENT MARKING			8	Aug 3, 2020	SYSTEM	\$6,270.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user woodsk1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					8	Aug 3, 2020	SYSTEM	(\$6,270.00)	
					9	Aug 18, 2020	SYSTEM	\$6,270.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0037) due to user woodsk1 overridding Payment Estimate Exception 54 on the current Payment Estimate.
					9	Aug 18, 2020	SYSTEM	(\$6,270.00)	
					10	Sep 3, 2020	SYSTEM	\$12,574.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0038) due to user woodsk1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
					10	Sep 3, 2020	SYSTEM	(\$12,574.32)	
					11	Sep 16, 2020	SYSTEM	\$12,574.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					11	Sep 16, 2020	SYSTEM	(\$12,574.32)	
					12	Oct 1, 2020	SYSTEM	\$12,574.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					12	Oct 1, 2020	SYSTEM	(\$12,574.32)	
					13	Oct 16, 2020	SYSTEM	\$12,574.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					13	Oct 16, 2020	SYSTEM	(\$12,574.32)	
					14	Nov 2, 2020	SYSTEM	\$12,574.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					14	Nov 2, 2020	SYSTEM	(\$12,574.32)	
					15	Nov 17, 2020	SYSTEM	\$12,574.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					15	Nov 17, 2020	SYSTEM	(\$12,574.32)	
					16	Dec 2, 2020	SYSTEM	\$12,574.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					16	Dec 2, 2020	SYSTEM	(\$12,574.32)	
					17	Dec 16, 2020	SYSTEM	\$12,574.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					17	Dec 16, 2020	SYSTEM	(\$12,574.32)	
					18	Jan 4, 2021	SYSTEM	\$12,574.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					18	Jan 4, 2021	SYSTEM	(\$12,574.32)	·
				- Total				\$0.00	
			Material - Tota	ı				\$0.00	
			Other Item Adjustment	REFL	10	Sep 3, 2020	woodsk1	\$153.21	Yellow: 63.78% @ 105 = (102,369 x .6378) = (65,290.9' @ 105% Pay Adjustment) = (65,290.9 x .0055) = \$359.10
									32.14% @ 100 = (102,369 x .3214) = (32,901.4* @ 100% Pay) *(Also Includes 2nd Mobilization & Application)
									4.08% @ 80 = (102,369 x .0408) = (4,176.7' @ 80% Pay Adjustment) = (4,176.7 x .088) = -\$91.89
									Total Adjustment = \$267.21



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
			Туре	Adjustment Type	Number	Date	Ву		
J9S3571	1020	4 IN. WHITE WATERBORNE PAVEMENT MARKING	Other Item Adjustment						
									White:
									92.28%@ 105 = (30,488 x .9228) = (28,134.3' @ 105% Pay Adjustment) = (28,134.3 x .0055) = \$154.74
									7.2%@ 100 = (30,488 x .0720) = (2,195.1' @ 100% Pay) *(Also Includes 2nd Mobilization & Application)
									0.52%@80 = (30,488 x .0052) = (158.5' @ 80% Pay Adjustment) = (158.5 x .088) = -\$1.53
									Total Adjustment = \$153.21
									,
									* Remaining Quantity From 2nd Mobilization & Application Paid @ 100%
				REFL - Tota				\$153.21	
			Other Item Ad	justment - To	tal			\$153.21	
		Total					OVOTEN	\$153.21	Ti. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.
	1030	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	Material		3	May 19, 2020	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
		WARRING			3	May 19, 2020	SYSTEM	(\$1,760.00)	
					4	Jun 3, 2020	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					4	Jun 3, 2020	SYSTEM	(\$1,760.00)	
					5	Jun 16, 2020	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					5	Jun 16, 2020	SYSTEM	(\$1,760.00)	
					6	Jul 2, 2020	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user woodsk1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					6	Jul 2, 2020	SYSTEM	(\$1,760.00)	
					7	Jul 16, 2020	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					7	Jul 16, 2020	SYSTEM	(\$1,760.00)	
					8	Aug 3, 2020	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					8	Aug 3, 2020	SYSTEM	(\$1,760.00)	
					9	Aug 18, 2020	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0038) due to user woodsk1 overridding Payment Estimate Exception 56 on the current Payment Estimate.
					9	Aug 18, 2020	SYSTEM	(\$1,760.00)	
					10	Sep 3, 2020	SYSTEM	\$3,519.89	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0039) due to user woodsk1 overridding Payment Estimate Exception 42 on the current Payment Estimate.
					10	Sep 3, 2020	SYSTEM	(\$3,519.89)	
					11	Sep 16, 2020	SYSTEM	\$3,519.89	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user woodsk1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					11	Sep 16, 2020	SYSTEM	(\$3,519.89)	
					12	Oct 1, 2020	SYSTEM	\$3,519.89	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
J9S3571	1030	4 IN. YELLOW	, ,	Туре	114111201	Date	2,		Estimate Exception 18 on the current Payment Estimate.
3933371	1030	WATERBORNE PAVEMENT	iviaterial		12	Oct 1,	SYSTEM	(\$3,519.89)	Estimate Exception to of the current Payment Estimate.
		MARKING			13	2020 Oct 16, 2020	SYSTEM	\$3,519.89	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment
					13	Oct 16, 2020	SYSTEM	(\$3,519.89)	Estimate Exception 19 on the current Payment Estimate.
					14	Nov 2, 2020	SYSTEM	\$3,519.89	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					14	Nov 2, 2020	SYSTEM	(\$3,519.89)	Example: Example: 25 of the carrott symbol Educate.
					15	Nov 17, 2020	SYSTEM	\$3,519.89	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment
					15	Nov 17, 2020	SYSTEM	(\$3,519.89)	Estimate Exception 21 on the current Payment Estimate.
					16	Dec 2, 2020	SYSTEM	\$3,519.89	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					16	Dec 2, 2020	SYSTEM	(\$3,519.89)	
					17	Dec 16, 2020	SYSTEM	\$3,519.89	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					17	Dec 16, 2020	SYSTEM	(\$3,519.89)	
					18	Jan 4, 2021	SYSTEM	\$3,519.89	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					18	Jan 4, 2021	SYSTEM	(\$3,519.89)	
				- Total				\$0.00	
			Material - Tota	al .	10			\$0.00	
			Material - Total Other Item Adjustment		10	Sep 3, 2020	woodsk1		Yellow: 63.78% @ 105 = (102,369 x .6378) = (65,290.9' @ 105% Pay Adjustment) = (65,290.9 x .0055) = \$359.10
			Other Item	al .	10		woodsk1	\$0.00	63.78% @ 105 = (102,369 x .6378) = (65,290.9' @ 105% Pay Adjustment)
			Other Item	al .	10		woodsk1	\$0.00	63.78% @ 105 = (102,369 x .6378) = (65,290.9' @ 105% Pay Adjustment) = (65,290.9 x .0055) = \$359.10 32.14% @ 100 = (102,369 x .3214) = (32,901.4' @ 100% Pay) *(Also
			Other Item	al .	10		woodsk1	\$0.00	63.78% @ 105 = (102,369 x .6378) = (65,290.9' @ 105% Pay Adjustment) = (65,290.9 x .0055) = \$359.10 32.14% @ 100 = (102,369 x .3214) = (32,901.4' @ 100% Pay) *(Also Includes 2nd Mobilization & Application) 4.08% @ 80 = (102,369 x .0408) = (4,176.7' @ 80% Pay Adjustment) =
			Other Item	al .	10		woodsk1	\$0.00	63.78% @ 105 = (102,369 x .6378) = (65,290.9' @ 105% Pay Adjustment) = (65,290.9 x .0055) = \$359.10  32.14% @ 100 = (102,369 x .3214) = (32,901.4' @ 100% Pay) *(Also Includes 2nd Mobilization & Application)  4.08% @ 80 = (102,369 x .0408) = (4,176.7' @ 80% Pay Adjustment) = (4,176.7 x .088) = -\$91.89
			Other Item	al .	10		woodsk1	\$0.00	63.78% @ 105 = (102,369 x .6378) = (65,290.9' @ 105% Pay Adjustment) = (65,290.9 x .0055) = \$359.10  32.14% @ 100 = (102,369 x .3214) = (32,901.4' @ 100% Pay) *(Also Includes 2nd Mobilization & Application)  4.08% @ 80 = (102,369 x .0408) = (4,176.7' @ 80% Pay Adjustment) = (4,176.7 x .088) = -\$91.89  Total Adjustment = \$267.21
			Other Item	al .	10		woodsk1	\$0.00	63.78% @ 105 = (102,369 x .6378) = (65,290.9' @ 105% Pay Adjustment) = (65,290.9 x .0055) = \$359.10  32.14% @ 100 = (102,369 x .3214) = (32,901.4' @ 100% Pay) *(Also Includes 2nd Mobilization & Application)  4.08% @ 80 = (102,369 x .0408) = (4,176.7' @ 80% Pay Adjustment) = (4,176.7 x .088) = -\$91.89  Total Adjustment = \$267.21  White:  92.28%@ 105 = (30,488 x .9228) = (28,134.3' @ 105% Pay Adjustment) =
			Other Item	al .	10		woodsk1	\$0.00	63.78% @ 105 = (102,369 x .6378) = (65,290.9' @ 105% Pay Adjustment) = (65,290.9 x .0055) = \$359.10  32.14% @ 100 = (102,369 x .3214) = (32,901.4' @ 100% Pay) *(Also Includes 2nd Mobilization & Application)  4.08% @ 80 = (102,369 x .0408) = (4,176.7' @ 80% Pay Adjustment) = (4,176.7 x .088) = -\$91.89  Total Adjustment = \$267.21  White:  92.28%@ 105 = (30,488 x .9228) = (28,134.3' @ 105% Pay Adjustment) = (28,134.3 x .0055) = \$154.74  7.2%@ 100 = (30,488 x .0720) = (2,195.1' @ 100% Pay) *(Also Includes
			Other Item	al .	10		woodsk1	\$0.00	63.78% @ 105 = (102,369 x .6378) = (65,290.9' @ 105% Pay Adjustment) = (65,290.9 x .0055) = \$359.10  32.14% @ 100 = (102,369 x .3214) = (32,901.4' @ 100% Pay) *(Also Includes 2nd Mobilization & Application)  4.08% @ 80 = (102,369 x .0408) = (4,176.7' @ 80% Pay Adjustment) = (4,176.7 x .088) = -\$91.89  Total Adjustment = \$267.21  White:  92.28%@ 105 = (30,488 x .9228) = (28,134.3' @ 105% Pay Adjustment) = (28,134.3 x .0055) = \$154.74  7.2%@ 100 = (30,488 x .0720) = (2,195.1' @ 100% Pay) *(Also Includes 2nd Mobilization & Application)  0.52%@80 = (30,488 x .0052) = (158.5' @ 80% Pay Adjustment) =
			Other Item	al .	10		woodsk1	\$0.00	63.78% @ 105 = (102,369 x .6378) = (65,290.9' @ 105% Pay Adjustment) = (65,290.9 x .0055) = \$359.10  32.14% @ 100 = (102,369 x .3214) = (32,901.4' @ 100% Pay) *(Also Includes 2nd Mobilization & Application)  4.08% @ 80 = (102,369 x .0408) = (4,176.7' @ 80% Pay Adjustment) = (4,176.7 x .088) = -\$91.89  Total Adjustment = \$267.21  White:  92.28%@ 105 = (30,488 x .9228) = (28,134.3' @ 105% Pay Adjustment) = (28,134.3 x .0055) = \$154.74  7.2%@ 100 = (30,488 x .0720) = (2,195.1' @ 100% Pay) *(Also Includes 2nd Mobilization & Application)  0.52%@80 = (30,488 x .0052) = (158.5' @ 80% Pay Adjustment) = (158.5 x .088) = -\$1.53
			Other Item	al .			woodsk1	\$0.00	63.78% @ 105 = (102,369 x .6378) = (65,290.9' @ 105% Pay Adjustment) = (65,290.9 x .0055) = \$359.10  32.14% @ 100 = (102,369 x .3214) = (32,901.4' @ 100% Pay) *(Also Includes 2nd Mobilization & Application)  4.08% @ 80 = (102,369 x .0408) = (4,176.7' @ 80% Pay Adjustment) = (4,176.7 x .088) = -\$91.89  Total Adjustment = \$267.21  White:  92.28%@ 105 = (30,488 x .9228) = (28,134.3' @ 105% Pay Adjustment) = (28,134.3 x .0055) = \$154.74  7.2%@ 100 = (30,488 x .0720) = (2,195.1' @ 100% Pay) *(Also Includes 2nd Mobilization & Application)  0.52%@80 = (30,488 x .0052) = (158.5' @ 80% Pay Adjustment) = (158.5 x .088) = -\$1.53  Total Adjustment = \$153.21
			Other Item	REFL - Tota			woodsk1	\$0.00 \$267.21	63.78% @ 105 = (102,369 x .6378) = (65,290.9' @ 105% Pay Adjustment) = (65,290.9 x .0055) = \$359.10  32.14% @ 100 = (102,369 x .3214) = (32,901.4' @ 100% Pay) *(Also Includes 2nd Mobilization & Application)  4.08% @ 80 = (102,369 x .0408) = (4,176.7' @ 80% Pay Adjustment) = (4,176.7 x .088) = -\$91.89  Total Adjustment = \$267.21  White:  92.28%@ 105 = (30,488 x .9228) = (28,134.3' @ 105% Pay Adjustment) = (28,134.3 x .0055) = \$154.74  7.2%@ 100 = (30,488 x .0720) = (2,195.1' @ 100% Pay) *(Also Includes 2nd Mobilization & Application)  0.52%@80 = (30,488 x .0052) = (158.5' @ 80% Pay Adjustment) = (158.5 x .088) = -\$1.53



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9S3571	1080	MGS GUARDRAIL	Construction Stockpile	, , , , , , , , , , , , , , , , , , ,	8	Aug 3, 2020	SYSTEM	(\$1,493.80)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$1,493.80)	
			Construction S	l Stockpile - To	otal			(\$1,493.80)	
			Construction Stockpile		1	Apr 16, 2020	SYSTEM	\$1,493.80	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$1,493.80	
			Construction S	Stockpile STI	/II - Total			\$1,493.80	
	1080 -	Total						\$0.00	
	1090	MGS BRIDGE APP. TRANS SEC	Construction Stockpile		8	Aug 3, 2020	SYSTEM	(\$5,996.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		(REG/NO CURB)		- Total				(\$5,996.00)	
			Construction S	Stockpile - To	tal			(\$5,996.00)	
			Construction Stockpile		1	Apr 16, 2020	SYSTEM	\$5,996.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$5,996.00	
			Construction S	Stockpile STI	/II - Total			\$5,996.00	
	1090 -	Total						\$0.00	
	1100	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		8	Aug 3, 2020	SYSTEM	(\$6,040.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$6,040.00)	
			Construction	uction Stockpile - Total				(\$6,040.00)	
			Construction Stockpile		1	Apr 16, 2020	SYSTEM	\$6,040.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$6,040.00	
		Construction Stockpile STMI - Total						\$6,040.00	
	1100 -	Total						\$0.00	
	1130	EMULSIFIED ASPHALT, SEAL COAT			9	Aug 18, 2020	SYSTEM	\$575.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0039) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					9	Aug 18, 2020	SYSTEM	(\$575.00)	
					10	Sep 3, 2020	SYSTEM	\$575.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0040) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					10	Sep 3, 2020	SYSTEM	(\$575.00)	
						11	Sep 16, 2020	SYSTEM	\$575.00
					11	Sep 16,	SYSTEM	(\$575.00)	Estimate Exception 5 on the current Payment Estimate.
				- Total				\$0.00	
			Motorial Tet						
			Material - Tota Other Item Adjustment	ACAD	19	Jan 20, 2021	woodsk1	\$0.00 (\$20.97)	AC Seal Coat Adjustment. August 10th, 2020 placement date.
				ACAD - Tota	al			(\$20.97)	
			Other Item Adjustment - Total					(\$20.97)	
	1130 -	Total						(\$20.97)	
	1130 -	SEAL COAT AGGREGATE, GRADE B1	Material		9	Aug 18, 2020	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0040) due to user woodsk1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					9	Aug 18, 2020	SYSTEM	(\$1,435.00)	•
					10	Sep 3, 2020	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0041) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					10	Sep 3, 2020	SYSTEM	(\$1,435.00)	
					11	Sep 16, 2020	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks																				
J9S3571	1140	SEAL COAT AGGREGATE,	Material	Туре	11	Sep 16, 2020	SYSTEM	(\$1,435.00)																					
		GRADE B1			12	Oct 1, 2020	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.																				
					12	Oct 1, 2020	SYSTEM	(\$1,435.00)																					
					13	Oct 16, 2020	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.																				
					13	Oct 16, 2020	SYSTEM	(\$1,435.00)	·																				
					14	Nov 2, 2020	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.																				
					14	Nov 2, 2020	SYSTEM	(\$1,435.00)	·																				
					15	Nov 17, 2020	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.																				
					15	Nov 17, 2020	SYSTEM	(\$1,435.00)																					
					16	Dec 2, 2020	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.																				
					16	Dec 2, 2020	SYSTEM	(\$1,435.00)																					
					17	Dec 16, 2020	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.																				
				17	Dec 16, 2020	SYSTEM	(\$1,435.00)																						
						18	Jan 4, 2021	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user woodsk1 overridding Payment Estimate Exception 6 on the current Payment Estimate.																			
					18	Jan 4, 2021	SYSTEM	(\$1,435.00)																					
					19	Jan 20, 2021	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 6 on the current Payment Estimate.																				
					19	Jan 20, 2021	SYSTEM	(\$1,435.00)																					
					20	Feb 1, 2021	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 6 on the current Payment Estimate.																				
					20	Feb 1, 2021	SYSTEM	(\$1,435.00)																					
						21	Feb 16, 2021	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 6 on the current Payment Estimate.																			
						21	Feb 16, 2021	SYSTEM	(\$1,435.00)																				
					22	Mar 2, 2021	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 6 on the current Payment Estimate.																				
																									22	Mar 2, 2021	SYSTEM	(\$1,435.00)	
								23	Mar 16, 2021	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 6 on the current Payment Estimate.																	
					23	Mar 16, 2021	SYSTEM	(\$1,435.00)																					
						24	Apr 2, 2021	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 6 on the current Payment Estimate.																			
					24	Apr 2, 2021	SYSTEM	(\$1,435.00)																					
					25	Apr 16, 2021	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 6 on the current Payment Estimate.																				



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks												
J9S3571	1140	SEAL COAT AGGREGATE, GRADE B1	Material		25	Apr 16, 2021	SYSTEM	(\$1,435.00)													
					26	May 3, 2021	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate.												
					26	May 3, 2021	SYSTEM	(\$1,435.00)													
						27	May 17, 2021	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.											
					27	May 17, 2021	SYSTEM	(\$1,435.00)													
					28	Jun 2, 2021	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.												
					28	Jun 2, 2021	SYSTEM	(\$1,435.00)	Estimate Exception 11 on the earlost Laymont Estimate.												
							29	Jun 16, 2021	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.										
					29	Jun 16, 2021	SYSTEM	(\$1,435.00)													
				- Total		2021		\$0.00													
			Material - Tota					\$0.00													
	1140 -	·Total						\$0.00													
		SUPERSTRUCTURE REPAIR (UNFORMED)	Material	Material	6	Jul 2, 2020	SYSTEM	\$3,111.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 44 on the current Payment Estimate.												
					6	Jul 2, 2020	SYSTEM	(\$3,111.60)													
					7	Jul 16, 2020	SYSTEM	\$6,223.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 46 on the current Payment Estimate.												
					7	Jul 16, 2020	SYSTEM	(\$6,223.20)													
					8	Aug 3, 2020	SYSTEM	\$6,223.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0036) due to user woodsk1 overridding Payment Estimate Exception 46 on the current Payment Estimate.												
					8	Aug 3, 2020	SYSTEM	(\$6,223.20)													
					9	Aug 18, 2020	SYSTEM	\$6,223.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0041) due to user woodsk1 overridding Payment Estimate Exception 81 on the current Payment Estimate.												
					9	Aug 18, 2020	SYSTEM	(\$6,223.20)													
					10	Sep 3, 2020	SYSTEM	\$6,223.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0042) due to user woodsk1 overridding Payment Estimate Exception 67 on the current Payment Estimate.												
					10	Sep 3, 2020	SYSTEM	(\$6,223.20)													
																		11	Sep 16, 2020	SYSTEM	\$6,223.20
					11	Sep 16, 2020	SYSTEM	(\$6,223.20)													
					12	Oct 1, 2020	SYSTEM	\$9,645.96	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overridding Payment Estimate Exception 43 on the current Payment Estimate.												
					12	Oct 1, 2020	SYSTEM	(\$9,645.96)	. ,												
					13	Oct 16, 2020	SYSTEM	\$9,645.96	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 44 on the current Payment Estimate.												
					13	Oct 16, 2020	SYSTEM	(\$9,645.96)													
					14	Nov 2, 2020	SYSTEM	\$9,645.96	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user woodsk1 overridding Payment Estimate Exception 45 on the current Payment Estimate.												
					14	Nov 2,	SYSTEM	(\$9,645.96)	,												



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
J9S3571	1150	SUPERSTRUCTURE	Material			2020					
		REPAIR (UNFORMED)			15	Nov 17, 2020	SYSTEM	\$9,645.96	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overridding Payment Estimate Exception 46 on the current Payment Estimate.		
					15	Nov 17, 2020	SYSTEM	(\$9,645.96)			
					16	Dec 2, 2020	SYSTEM	\$9,645.96	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overridding Payment Estimate Exception 46 on the current Payment Estimate.		
					16	Dec 2, 2020	SYSTEM	(\$9,645.96)			
					17	Dec 16, 2020	SYSTEM	\$9,645.96	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overridding Payment Estimate Exception 44 on the current Payment Estimate.		
					17	Dec 16, 2020	SYSTEM	(\$9,645.96)	,		
					18	Jan 4, 2021	SYSTEM	\$9,645.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user woodsk1 overridding Payment Estimate Exception 44 on the current Payment Estimate.		
					18	Jan 4, 2021	SYSTEM	(\$9,645.96)	Examinate Exception 1. 57 the surface Symbol Committee		
				- Total		2021		\$0.00			
			Material - Tota					\$0.00			
	1150 -	· Total						\$0.00			
	1160	SLAB EDGE REPAIR (BRIDGES)	Material	Material	5	Jun 16, 2020	SYSTEM	\$7,361.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 40 on the current Payment Estimate.		
					5	Jun 16, 2020	SYSTEM	(\$7,361.70)			
					6	Jul 2, 2020	SYSTEM	\$7,361.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0034) due to user woodsk1 overridding Payment Estimate Exception 52 on the current Payment Estimate.		
					6	Jul 2, 2020	SYSTEM	(\$7,361.70)			
					7	Jul 16, 2020	SYSTEM	\$14,723.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0034) due to user woodsk1 overridding Payment Estimate Exception 56 on the current Payment Estimate.		
					7	Jul 16, 2020	SYSTEM	(\$14,723.40)			
					8	Aug 3, 2020	SYSTEM	\$14,723.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0037) due to user woodsk1 overridding Payment Estimate Exception 56 on the current Payment Estimate.		
					8	Aug 3, 2020	SYSTEM	(\$14,723.40)			
					9		SYSTEM	\$14,723.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0042) due to user woodsk1 overridding Payment Estimate Exception 91 on the current Payment Estimate.		
					9	Aug 18, 2020	SYSTEM	(\$14,723.40)			
							10	Sep 3, 2020	SYSTEM	\$14,723.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0043) due to user woodsk1 overridding Payment Estimate Exception 77 on the current Payment Estimate.
					10	Sep 3, 2020	SYSTEM	(\$14,723.40)			
							11	Sep 16, 2020	SYSTEM	\$14,723.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 67 on the current Payment Estimate.
					11	Sep 16, 2020	SYSTEM	(\$14,723.40)			
					12	Oct 1, 2020	SYSTEM	\$14,723.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user woodsk1 overridding Payment Estimate Exception 54 on the current Payment Estimate.		
					12	Oct 1, 2020	SYSTEM	(\$14,723.40)			
					12	Oct 1, 2020 Oct 16, 2020	SYSTEM	(\$14,723.40) \$14,723.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overridding Payment Estimate Exception 55 on the current Payment Estimate.		

Jun 21, 2021



## Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
1983571	1160	SLAB EDGE REPAIR (BRIDGES)	Material		14	Nov 2, 2020	SYSTEM	\$14,723.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user woodsk1 overridding Payment Estimate Exception 56 on the current Payment Estimate.	
					14	Nov 2, 2020	SYSTEM	(\$14,723.40)		
						15	Nov 17, 2020	SYSTEM	\$14,723.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overridding Payment Estimate Exception 57 on the current Payment Estimate.
					15	Nov 17, 2020	SYSTEM	(\$14,723.40)		
					16	Dec 2, 2020	SYSTEM	\$14,723.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overridding Payment Estimate Exception 57 on the current Payment Estimate.	
					16	Dec 2, 2020	SYSTEM	(\$14,723.40)		
					17	Dec 16, 2020	SYSTEM	\$14,723.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user woodsk1 overridding Payment Estimate Exception 57 on the current Payment Estimate.	
					17	Dec 16, 2020	SYSTEM	(\$14,723.40)		
					18	Jan 4, 2021	SYSTEM	\$14,723.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user woodsk1 overridding Payment Estimate Exception 57 on the current Payment Estimate.	
					18	Jan 4, 2021	SYSTEM	(\$14,723.40)		
				- Total	- Total			\$0.00		
			Material - Tota	al				\$0.00		
	1160 -	Total						\$0.00		
	1180	BRIDGE GUARDRAIL (THRIE BEAM)	Construction Stockpile			6	Jul 2, 2020	SYSTEM	(\$14,685.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
					8	Aug 3, 2020	SYSTEM	(\$14,685.00)	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				(\$29,370.00)		
			Construction	struction Stockpile - Total				(\$29,370.00)		
			Construction Stockpile STMI		2	May 4, 2020	SYSTEM	\$29,370.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total	- Total			\$29,370.00		
		Construction Stockpile STMI - Total						\$29,370.00		
	1180 -	Total						\$0.00		
	Total							\$70,442.04		
J9S3571 -	- I Ulai									