

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: July 1, 2020

Progress Estimate Number	Contract ID	200221-C04	Pay Period Start June 16, 2020 Original Contract Amount \$249,330.02
6	Prime Contracto	or Capital Paving 8	Construction, LLC Pay Period End June 30, 2020 Net Change Order Amount \$4,319.37
· ·			Current Contract Amount \$253,649.39

Approval Date		By User						
July 2, 2020	Generated and Approved (and should be considered Draft) at the Project Office Level by	vohsr1						
July 2, 2020	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	penner1						
July 2, 2020	Reviewed and Approved at the Central Office Controllers Office Level by							

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
November 1, 2020	November 1, 2020		100.00%

No Milestones Exist for Contract

Contract Total Pay For Estimate No. 6									
	This Estimate	Previous	To Date						
200221-C04									
Total Posted Items Pay	\$0.00	\$253,649.39	\$253,649.39						
Gross Item Adjustments	\$0.00	(\$6,371.98)	(\$6,371.98)						
Incentive	\$0.00	\$0.00	\$0.00						
Disincentive	\$0.00	\$0.00	\$0.00						
Liquidated Damage	\$0.00	\$0.00	\$0.00						
Other Contract Adjustments	\$0.00	\$0.00	\$0.00						
		\$247,277.41	\$247,277.41						
Contract Total Payable This Estimate:	\$0.00								

Items Paid This Estimate Period

No Data Available

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
4S3356	0050	CONCRETE CURB RAMP	Material			-17.2	\$437.50	(\$7,525.00)
	0050	CONCRETE CURB RAMP	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0001) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	17.2	\$437.50	\$7,525.00
	0140	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	Material			-285	\$14.00	(\$3,990.00)
	0140	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	285	\$14.00	\$3,990.00
	0150	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material			-6	\$200.00	(\$1,200.00)
	0150	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	6	\$200.00	\$1,200.00
	0160	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	Material			-7	\$100.00	(\$700.00)
	0160	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 5 on	7	\$100.00	\$700.00

Revision 4/1/2020 Page 1 of 11



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: July 1, 2020

Progress Estimate Number 6	Contract ID Prime Contrac	200221-C ctor Capital Pa		Pay Period StartJune 16, 2020 Ori truction, LLC Pay Period End June 30, 2020 Ne Cu	Change Ord	der Amount	
D : ():		A 11 1 1	011 11	0 1	A 11 ()	1	A 11 ()

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4S3356					the current Payment Estimate.			
Total								\$0.00

Revision 4/1/2020 Page 2 of 11



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Information	on					
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work							
J4S3356	FAS S302(86)	Resurface	RA	JACKSON	from S Outer Road to State Maintenance Ends							
Γotals by J	Job Numbe	ers										
J4S3356		ed Item Pay s Item Adjustm		s Item Pay	This Estimate \$0.00 \$0.00 \$0.00	Previous \$253,649.39 (\$6,371.98) \$247,277.41	To Date \$253,649.39 (\$6,371.98) \$247,277.41					
	Liqui	tive centive dated Damages Contract Adju		1	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00							

Revision 4/1/2020 Page 3 of 11



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4S3356, Item 6081010, Project Item Line Number 0050, Material Set 608101096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Working with materials to resolve exception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3356, Item 6081010, Project Item Line Number 0050, Material Set 608101096, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Working with materials to resolve exception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3356, Item 6200018, Project Item Line Number 0140, Material Set 620001896, Material 1048PMPFYL - Performed Thermoplastic Marking Tape YL, Acceptance Action Generic 1048PMPFYL is insufficient.	Working with materials to resolve exception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3356, Item 6200021, Project Item Line Number 0150, Material Set 620002196, Material 1048PMPFWHXX - Pref Mrk Tape Direct Indcat or Shape WH, Acceptance Action Generic 1048PMPFWHXX is insufficient.	Working with materials to resolve exception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3356, Item 6200036, Project Item Line Number 0160, Material Set 620003696, Material 1048PMPFWHXX - Pref Mrk Tape Direct Indcat or Shape WH, Acceptance Action Generic 1048PMPFWHXX is insufficient.	Working with materials to resolve exception.	vohsr1	Overridden

Revision 4/1/2020 Page 4 of 11



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
00221-C04	J4S3356	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$6,400.00	\$6,400.00
		0001	0020	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	519.00	-258.00	261.00	TONS	261.00	\$38.13	\$9,951.93
		0001	0030	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	1,927.70	0.00	1,927.70	TONS	1,927.70	\$88.01	\$169,656.88
		0001 0040 4071005 TAG			TACK COAT	1,605.00	193.00	1,798.00	GAL	1,798.00	\$2.52	\$4,530.96
		0001	0050	6081010	CONCRETE CURB RAMP	17.20	0.00	17.20	SQYD	17.20	\$437.50	\$7,525.00
		0001	0060	6081012	TRUNCATED DOMES	22.00	0.00	22.00	SQFT	22.00	\$40.00	\$880.00
		0001 0070 6123000A 0001 0080 6161005		6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$577.33	\$1,154.66
				6161005	CONSTRUCTION SIGNS	811.00	-291.00	520.00	SQFT	520.00	\$5.00	\$2,600.00
	0001 0090 6161009			6161009	FLAG ASSEMBLY	12.00	-4.00	8.00	EA	8.00	\$25.00	\$200.00
		0001	0100	6161025	CHANNELIZER (TRIM LINE)	200.00	-170.00	30.00	EA	30.00	\$1.00	\$30.00
		0001	0110	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$950.00	\$1,900.00
		0001	0120	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$16,189.53	\$16,189.53
		0001	0130	6200003	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 4 IN., WHITE	445.00	-445.00	0.00	LF	0.00	\$3.00	\$0.00
		0001	0140	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	21.00	264.00	285.00	LF	285.00	\$14.00	\$3,990.00
		0001	0150	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	4.00	2.00	6.00	EA	6.00	\$200.00	\$1,200.00
		0001	0160	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	7.00	0.00	7.00	EA	7.00	\$100.00	\$700.00
		0001	0170	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	13,480.00	1,144.00	14,624.00	LF	14,624.00	\$0.06	\$877.44
		0001 0180 6206001C 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS				13,950.00	2,533.00	16,483.00	LF	16,483.00	\$0.06	\$988.98
		0001	0190	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	1,158.00	16.00	1,174.00	SQYD	1,174.00	\$10.76	\$12,632.24
		0001	5001	6139901	MISC.Full Depth Pavement Repair	0.00	1.00	1.00	LS	1.00	\$12,241.77	\$12,241.77
	Project J	4S3356 - To	tal Value	Posted to D	ate as of Report Generated Date							\$253,649.39
221-C04 Ove	rall - Total	Value Post	ted to Da	to as of Rone	ort Generated Date							\$253,649.

Revision 4/1/2020 Page 5 of 11



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line are details from Line Item agency views.

No Agency View Details Exist

Revision 4/1/2020 Page 6 of 11



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
Line	Description	Type	Adjustment Type	Number	Date	By	Amount	IXCIIIAINS
0020	MISC. PERMANENT AGGREGATE EDGE TREATMENT	Material		1	Apr 16, 2020	SYSTEM	(\$9,917.99)	
				1	Apr 16, 2020	SYSTEM	\$9,917.99	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0020 -	Total						\$0.00	
0030	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Other Item Adjustment	FUEL		Apr 16, 2020	vohsr1	(\$2,815.98)	This adjustment is being made for asphalt fuel adjustment.
			FUEL - Tota	ı			(\$2,815.98)	
	Other Item Adjustment - Total						(\$2,815.98)	
0030 -	Total						(\$2,815.98)	
0040	TACK COAT	Material		1	Apr 16, 2020	SYSTEM	(\$4,530.96)	
				1	Apr 16, 2020	SYSTEM	\$4,530.96	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				2	May 5, 2020	SYSTEM	(\$4,530.96)	
				2	May 5, 2020	SYSTEM	\$4,530.96	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	TACK COAT	Overrun	Overrun	1	Apr 16, 2020	SYSTEM	(\$486.36)	
				1	Apr 16, 2020	SYSTEM	\$486.36	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 17 on the current Payment Estimate.
				2	May 5, 2020	SYSTEM	(\$486.36)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				2	May 5, 2020	SYSTEM	\$486.36	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 11 on the current Payment Estimate.
				3	May 18, 2020	SYSTEM	(\$486.36)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				4	Jun 2, 2020	SYSTEM	\$486.36	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',2.52000 - 2.52000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0040 -	Total						\$0.00	
0050	CONCRETE CURB RAMP	Material		1	Apr 16, 2020	SYSTEM	(\$7,525.00)	
				1	Apr 16, 2020	SYSTEM	\$7,525.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				2	May 5, 2020	SYSTEM	(\$7,525.00)	
				2	May 5, 2020	SYSTEM	\$7,525.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				3	May 18, 2020	SYSTEM	(\$7,525.00)	
				3	May 18, 2020	SYSTEM	\$7,525.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				4	Jun 2, 2020	SYSTEM	(\$7,525.00)	

Revision 4/1/2020 Page 7 of 11



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
Line	Besonption	Туре	Adjustment Type	Number	Date	Ву	7 tillount	Kondile
0050	CONCRETE CURB RAMP	Material		4	Jun 2, 2020	SYSTEM	\$7,525.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				5	Jun 16, 2020	SYSTEM	(\$7,525.00)	
				5	Jun 16, 2020	SYSTEM	\$7,525.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				6	Jul 1, 2020	SYSTEM	(\$7,525.00)	
				6	Jul 1, 2020	SYSTEM	\$7,525.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0050 -	Total						\$0.00	
0060	TRUNCATED DOMES	Material		1	Apr 16, 2020	SYSTEM	(\$880.00)	
				1	Apr 16, 2020	SYSTEM	\$880.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user vohsr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0060 -	Total						\$0.00	
0800	CONSTRUCTION SIGNS	Material		1	Apr 16, 2020	SYSTEM	(\$2,595.05)	
				1	Apr 16, 2020	SYSTEM	\$2,595.05	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user vohsr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0080 -	Total						\$0.00	
0090	FLAG ASSEMBLY	Material		1	Apr 16, 2020	SYSTEM	(\$200.00)	
				1	Apr 16, 2020	SYSTEM	\$200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user vohsr1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0090 -	Total						\$0.00	
0100	CHANNELIZER (TRIM LINE)	Material		1	Apr 16, 2020	SYSTEM	(\$30.00)	
				1	Apr 16, 2020	SYSTEM	\$30.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user vohsr1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0100 -	Total						\$0.00	
0110	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE,	Material		1	Apr 16, 2020	SYSTEM	(\$1,900.00)	
	CONTRACTOR FURNISHED, CONTRACTOR RETAINED			1	Apr 16, 2020	SYSTEM	\$1,900.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user vohsr1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	Total						\$0.00	

Revision 4/1/2020 Page 8 of 11



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0140	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	Material		2	May 5, 2020	SYSTEM	(\$3,850.00)	
				2	May 5, 2020	SYSTEM	\$3,850.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				3	May 18, 2020	SYSTEM	(\$3,990.00)	
				3	May 18, 2020	SYSTEM	\$3,990.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				4	Jun 2, 2020	SYSTEM	(\$3,990.00)	
				4	Jun 2, 2020	SYSTEM	\$3,990.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				5	Jun 16, 2020	SYSTEM	(\$3,990.00)	
				5	Jun 16, 2020	SYSTEM	\$3,990.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				6	Jul 1, 2020	SYSTEM	(\$3,990.00)	
				6	Jul 1, 2020	SYSTEM	\$3,990.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
	- Total						\$0.00	
	Material - Total						\$0.00	
	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	Overrun	Overrun	2	May 5, 2020	SYSTEM	\$3,556.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 12 on the current Payment Estimate.
				2	May 5, 2020	SYSTEM	(\$3,556.00)	
				2	May 5, 2020	vohsr1	(\$3,556.00)	Correction for overrun item adjustment due to material exception override.
			Overrun - T	otal			(\$3,556.00)	
	Overrun - Total						(\$3,556.00)	
0140	PREFORMED THERMOPLASTIC	Material		1	Apr 16,	SYSTEM	(\$3,556.00) (\$1,200.00)	
	PAVEMENT MARKING, LEFT/RIGHT ARROW			1	2020 Apr 16, 2020	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				2	May 5, 2020	SYSTEM	(\$1,200.00)	
				2	May 5, 2020	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user vohsr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				3	May 18, 2020	SYSTEM	(\$1,200.00)	
				3	May 18, 2020	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				4	Jun 2, 2020	SYSTEM	(\$1,200.00)	
				4	Jun 2, 2020	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				5	Jun 16, 2020	SYSTEM	(\$1,200.00)	
					Jun 16,	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Overrun

Revision 4/1/2020 Page 9 of 11



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0150	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material			2020			Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				6	Jul 1, 2020	SYSTEM	(\$1,200.00)	
				6	Jul 1, 2020	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Overrun	Overrun	1	Apr 16, 2020 Apr 16,	SYSTEM	(\$400.00)	This adjustment offsets the original system-generated Overrun
					2020	STSTEW	φ400.00	Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 18 on the current Payment Estimate.
				2	May 5, 2020	SYSTEM	(\$400.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				2	May 5, 2020	SYSTEM	\$400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 13 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0150 -	- Total						\$0.00	
0160	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	Material		1	Apr 16, 2020	SYSTEM	(\$700.00)	
				1	Apr 16, 2020	SYSTEM	\$700.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user vohsr1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				2	May 5, 2020	SYSTEM	(\$700.00)	
				2	May 5, 2020	SYSTEM	\$700.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user vohsr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				3	May 18, 2020	SYSTEM	(\$700.00)	
				3	May 18, 2020	SYSTEM	\$700.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user vohsr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				4	Jun 2, 2020	SYSTEM	(\$700.00)	
				4	Jun 2, 2020	SYSTEM	\$700.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user vohsr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				5	Jun 16, 2020	SYSTEM	(\$700.00)	
				5	Jun 16, 2020	SYSTEM	\$700.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				6	Jul 1, 2020	SYSTEM	(\$700.00)	
				6	Jul 1, 2020	SYSTEM	\$700.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0160 -	- Total						\$0.00	
0170	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		1	Apr 16, 2020	SYSTEM	(\$877.44)	
	SEADO			1	Apr 16, 2020	SYSTEM	\$877.44	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user vohsr1 overridding Payment Estimate Exception 13 on the current Payment

Revision 4/1/2020 Page 10 of 11



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
		Туре	Adjustment Type		Date	Ву		
0170	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material						Estimate.
				2	May 5, 2020	SYSTEM	(\$877.44)	
				2	May 5, 2020	SYSTEM	\$877.44	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user vohsr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				3	May 18, 2020	SYSTEM	(\$877.44)	
				3	May 18, 2020	SYSTEM	\$877.44	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user vohsr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				4	Jun 2, 2020	SYSTEM	(\$877.44)	
				4	Jun 2, 2020	SYSTEM	\$877.44	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user vohsr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Overrun	Overrun	1	Apr 16, 2020	SYSTEM	(\$68.64)	
				1	Apr 16, 2020	SYSTEM	\$68.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 19 on the current Payment Estimate.
				2	May 5, 2020	SYSTEM	(\$68.64)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				2	May 5, 2020	SYSTEM	\$68.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) overridding Payment Estimate Exception 14 on the current Payment Estimate.
			Overrun - T	otol		\$0.00		
			Overruii - 1	Otal			Ψ0.00	
	Overrun - Total		Overruit - 1	Otai			\$0.00	
0170 -	Total		Overruit - 1				\$0.00 \$0.00	
0170 -	Total 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P	Material	Overrun - 1	1	Apr 16, 2020	SYSTEM	\$0.00 \$0.00 (\$988.98)	
	Total 4 IN. YELLOW STANDARD WATERBORNE	Material	Overruit - 1			SYSTEM SYSTEM	\$0.00 \$0.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user vohsr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
	Total 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P	Material	Overruii - 1	1	2020 Apr 16,		\$0.00 \$0.00 (\$988.98)	Payment Estimate Item Adjustment (0008) due to user vohsr1 overridding Payment Estimate Exception 15 on the current Payment
	Total 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P	Material		1	2020 Apr 16, 2020 May 5,	SYSTEM	\$0.00 \$0.00 (\$988.98) \$988.98 (\$988.98)	Payment Estimate Item Adjustment (0008) due to user vohsr1 overridding Payment Estimate Exception 15 on the current Payment
	Total 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material	- Total	1 1 2	2020 Apr 16, 2020 May 5, 2020 May 5,	SYSTEM	\$0.00 \$0.00 (\$988.98) \$988.98 (\$988.98) \$988.98	Payment Estimate Item Adjustment (0008) due to user vohsr1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user vohsr1 overridding Payment Estimate Exception 10 on the current Payment
	Total 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS Material - Total		- Total	1 2 2	2020 Apr 16, 2020 May 5, 2020 May 5, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$988.98) \$988.98 (\$988.98) \$988.98	Payment Estimate Item Adjustment (0008) due to user vohsr1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user vohsr1 overridding Payment Estimate Exception 10 on the current Payment
	Total 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS			1 2 2 1	2020 Apr 16, 2020 May 5, 2020 May 5, 2020	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$988.98) \$988.98 (\$988.98) \$988.98 \$0.00 \$0.00 (\$151.98)	Payment Estimate Item Adjustment (0008) due to user vohsr1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user vohsr1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
	Total 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS Material - Total 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P		- Total	1 2 2	2020 Apr 16, 2020 May 5, 2020 May 5, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$988.98) \$988.98 (\$988.98) \$988.98	Payment Estimate Item Adjustment (0008) due to user vohsr1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user vohsr1 overridding Payment Estimate Exception 10 on the current Payment
	Total 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS Material - Total 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P		- Total	1 2 2 1	2020 Apr 16, 2020 May 5, 2020 May 5, 2020 Apr 16, 2020 Apr 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$988.98) \$988.98 (\$988.98) \$988.98 \$0.00 \$0.00 (\$151.98)	Payment Estimate Item Adjustment (0008) due to user vohsr1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user vohsr1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment
	Total 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS Material - Total 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P		- Total Overrun	1 1 2 2 2	2020 Apr 16, 2020 May 5, 2020 May 5, 2020 Apr 16, 2020 Apr 16, 2020 May 5, 4020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$988.98) \$988.98 (\$988.98) \$988.98 \$0.00 \$0.00 (\$151.98) \$151.98	Payment Estimate Item Adjustment (0008) due to user vohsr1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user vohsr1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 20 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment
	Total 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS Material - Total 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS		- Total	1 1 2 2 2	2020 Apr 16, 2020 May 5, 2020 Apr 16, 2020 May 5, 2020 Apr 16, 2020 Apr 16, 2020 May 5, 2020 May 5, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$988.98) \$988.98 (\$988.98) \$988.98 \$0.00 \$151.98 (\$151.98) \$151.98	Payment Estimate Item Adjustment (0008) due to user vohsr1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user vohsr1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 20 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) overridding Payment
0180	Total 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS Material - Total 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS Overrun - Total		- Total Overrun	1 1 2 2 2	2020 Apr 16, 2020 May 5, 2020 Apr 16, 2020 May 5, 2020 Apr 16, 2020 Apr 16, 2020 May 5, 2020 May 5, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$988.98) \$988.98 (\$988.98) \$988.98 \$0.00 (\$151.98) \$151.98 (\$151.98) \$151.98	Payment Estimate Item Adjustment (0008) due to user vohsr1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user vohsr1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 20 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) overridding Payment
0180	Total 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS Material - Total 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS Overrun - Total		- Total Overrun	1 1 2 2 2	2020 Apr 16, 2020 May 5, 2020 Apr 16, 2020 May 5, 2020 Apr 16, 2020 Apr 16, 2020 May 5, 2020 May 5, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$988.98) \$988.98 (\$988.98) \$988.98 \$0.00 \$151.98 (\$151.98) \$151.98	Payment Estimate Item Adjustment (0008) due to user vohsr1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user vohsr1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 20 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) overridding Payment

Revision 4/1/2020 Page 11 of 11