

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 3, 2020

Progress Estimate Number	Contract ID	200221-C04	Pay Period Start July 16, 2020	Original Contract Amount \$249,330.02
8	Prime Contracto	rCapital Paving & Construction	on, LLCPay Period End August 1, 202	0Net Change Order Amount\$4,319.37
· ·				Current Contract Amount \$253,649.39

Approval Date		By User
August 3, 2020	Generated and Approved (and should be considered Draft) at the Project Office Level by	vohsr1
August 3, 2020	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	wilsoj9
August 4, 2020	Reviewed and Approved at the Central Office Controllers Office Level by	greggd1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
November 1, 2020	November 1, 2020		100.00%

No Milestones Exist for Contract

Contract Total Pay	For Estimate No. 8			
		This Estimate	Previous	To Date
200221-C04				
	Total Posted Items Pay	\$0.00	\$253,649.39	\$253,649.39
	Gross Item Adjustments	\$0.00	(\$6,371.98)	(\$6,371.98)
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	•		\$247,277.41	\$247,277.41
Contract Total Pay	able This Estimate:	\$0.00		

Items Paid This Estimate Period

No Data Available

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item	<u>Adjustı</u>	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4S3356	0050	CONCRETE CURB RAMP	Material			-17.2	\$437.50	(\$7,525.00)
	0050	CONCRETE CURB RAMP	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0001) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	17.2	\$437.50	\$7,525.00
Total								\$0.00

Revision 4/1/2020 Page 1 of 11



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Information	n
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J4S3356	FAS S302(86)	Resurface	RA	JACKSON	from S Outer Road to Sta	ate Maintenance Ends	
Totals by	Job Numbe	ers					
J4S3356					This Estimate	Previous	To Date
		d Item Pay Item Adjustm		s Item Pay	\$0.00 \$0.00 \$0.00	\$253,649.39 (\$6,371.98) \$247,277.41	\$253,649.39 (\$6,371.98) \$247,277.41
			Gioss	s itelli Fay	• • • • • • • • • • • • • • • • • • • •	•	• •
	Incen				\$0.00	\$0.00	\$0.00
		centive dated Damages			\$0.00 \$0.00	\$0.00 \$0.00	\$0.00 \$0.00
	Liquit	Contract Adju			\$0.00	\$0.00	\$0.00

Revision 4/1/2020 Page 2 of 11



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4S3356, Item 6081010, Project Item Line Number 0050, Material Set 608101096, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Working with materials to resolve exception.	vohsr1	Overridden

Revision 4/1/2020 Page 3 of 11



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
00221-C04	J4S3356	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$6,400.00	\$6,400.00
		0001	0020	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	519.00	-258.00	261.00	TONS	261.00	\$38.13	\$9,951.93
		0001	0030	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	1,927.70	0.00	1,927.70	TONS	1,927.70	\$88.01	\$169,656.88
		0001	0040	4071005	TACK COAT	1,605.00	193.00	1,798.00	GAL	1,798.00	\$2.52	\$4,530.96
		0001	0050	6081010	CONCRETE CURB RAMP	17.20	0.00	17.20	SQYD	17.20	\$437.50	\$7,525.00
		0001	0060	6081012	TRUNCATED DOMES	22.00	0.00	22.00	SQFT	22.00	\$40.00	\$880.00
		0001	0070	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$577.33	\$1,154.66
		0001	0080	6161005	CONSTRUCTION SIGNS	811.00	-291.00	520.00	SQFT	520.00	\$5.00	\$2,600.00
		0001	0090	6161009	FLAG ASSEMBLY	12.00	-4.00	8.00	EA	8.00	\$25.00	\$200.0
		0001	0100	6161025	CHANNELIZER (TRIM LINE)	200.00	-170.00	30.00	EA	30.00	\$1.00	\$30.0
		0001	0110	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$950.00	\$1,900.0
		0001	0120	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$16,189.53	\$16,189.5
		0001	0130	6200003	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 4 IN., WHITE	445.00	-445.00	0.00	LF	0.00	\$3.00	\$0.0
		0001	0140	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	21.00	264.00	285.00	LF	285.00	\$14.00	\$3,990.0
		0001	0150	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	4.00	2.00	6.00	EA	6.00	\$200.00	\$1,200.0
		0001	0160	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	7.00	0.00	7.00	EA	7.00	\$100.00	\$700.0
		0001	0170	6206000C	$4\ \mbox{IN}.$ WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	13,480.00	1,144.00	14,624.00	LF	14,624.00	\$0.06	\$877.4
		0001	0180	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	13,950.00	2,533.00	16,483.00	LF	16,483.00	\$0.06	\$988.9
		0001	0190	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	1,158.00	16.00	1,174.00	SQYD	1,174.00	\$10.76	\$12,632.2
		0001	5001	6139901	MISC.Full Depth Pavement Repair	0.00	1.00	1.00	LS	1.00	\$12,241.77	\$12,241.7
	Project J	4S3356 - To	otal Value	Posted to D	ate as of Report Generated Date							\$253,649.3
221-C04 Ove	erall - Total	Value Pos	ted to Da	te as of Repo	ort Generated Date							\$253,649.3

Revision 4/1/2020 Page 4 of 11



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line are details from Line Item agency views.

No Agency View Details Exist

Revision 4/1/2020 Page 5 of 11



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
Line	Description	Type	Adjustment Type	Number	Date	By	Amount	IXCIIIAINS
0020	MISC. PERMANENT AGGREGATE EDGE TREATMENT	Material		1	Apr 16, 2020	SYSTEM	(\$9,917.99)	
				1	Apr 16, 2020	SYSTEM	\$9,917.99	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0020 -	Total						\$0.00	
0030	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Other Item Adjustment	FUEL		Apr 16, 2020	vohsr1	(\$2,815.98)	This adjustment is being made for asphalt fuel adjustment.
			FUEL - Tota	ı			(\$2,815.98)	
	Other Item Adjustment - Total						(\$2,815.98)	
0030 -	Total						(\$2,815.98)	
0040	TACK COAT	Material		1	Apr 16, 2020	SYSTEM	(\$4,530.96)	
				1	Apr 16, 2020	SYSTEM	\$4,530.96	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				2	May 5, 2020	SYSTEM	(\$4,530.96)	
				2	May 5, 2020	SYSTEM	\$4,530.96	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	TACK COAT	Overrun	Overrun	1	Apr 16, 2020	SYSTEM	(\$486.36)	
				1	Apr 16, 2020	SYSTEM	\$486.36	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 17 on the current Payment Estimate.
				2	May 5, 2020	SYSTEM	(\$486.36)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				2	May 5, 2020	SYSTEM	\$486.36	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 11 on the current Payment Estimate.
				3	May 18, 2020	SYSTEM	(\$486.36)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				4	Jun 2, 2020	SYSTEM	\$486.36	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',2.52000 - 2.52000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0040 -	Total						\$0.00	
0050	CONCRETE CURB RAMP	Material		1	Apr 16, 2020	SYSTEM	(\$7,525.00)	
				1	Apr 16, 2020	SYSTEM	\$7,525.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				2	May 5, 2020	SYSTEM	(\$7,525.00)	
				2	May 5, 2020	SYSTEM	\$7,525.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				3	May 18, 2020	SYSTEM	(\$7,525.00)	
				3	May 18, 2020	SYSTEM	\$7,525.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				4	Jun 2, 2020	SYSTEM	(\$7,525.00)	

Revision 4/1/2020 Page 6 of 11



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0050	CONCRETE CURB RAMP	Material	31	4	Jun 2, 2020	SYSTEM	\$7,525.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				5	Jun 16, 2020	SYSTEM	(\$7,525.00)	
				5	Jun 16, 2020	SYSTEM	\$7,525.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				6	Jul 1, 2020	SYSTEM	(\$7,525.00)	
				6	Jul 1, 2020	SYSTEM	\$7,525.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$7,525.00)	
				7	Jul 16, 2020	SYSTEM	\$7,525.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$7,525.00)	
				8	Aug 3, 2020	SYSTEM	\$7,525.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0050 -	Total						\$0.00	
0060	TRUNCATED DOMES	Material		1	Apr 16, 2020	SYSTEM	(\$880.00)	
				1	Apr 16, 2020	SYSTEM	\$880.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user vohsr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0060 -	· Total						\$0.00	
0080	CONSTRUCTION SIGNS	Material		1	Apr 16, 2020	SYSTEM	(\$2,595.05)	
				1	Apr 16, 2020	SYSTEM	\$2,595.05	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user vohsr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0080 -	·Total						\$0.00	
0090	FLAG ASSEMBLY	Material		1	Apr 16, 2020	SYSTEM	(\$200.00)	
				1	Apr 16, 2020	SYSTEM	\$200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user vohsr1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0090 -	Total						\$0.00	
0100	CHANNELIZER (TRIM LINE)	Material		1	Apr 16, 2020	SYSTEM	(\$30.00)	
				1	Apr 16, 2020	SYSTEM	\$30.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user vohsr1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	

Revision 4/1/2020 Page 7 of 11



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0100 -	Total						\$0.00	
0110	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED,	Material		1	Apr 16, 2020	SYSTEM	(\$1,900.00)	
	CONTRACTOR RETAINED			1	Apr 16, 2020	SYSTEM	\$1,900.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user vohsr1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0110 -	Total						\$0.00	
0140	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	Material		2	May 5, 2020	SYSTEM	(\$3,850.00)	
				2	May 5, 2020	SYSTEM	\$3,850.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				3	May 18, 2020	SYSTEM	(\$3,990.00)	
				3	May 18, 2020	SYSTEM	\$3,990.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				4	Jun 2, 2020	SYSTEM	(\$3,990.00)	
				4	Jun 2, 2020	SYSTEM	\$3,990.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				5	Jun 16, 2020	SYSTEM	(\$3,990.00)	
				5	Jun 16, 2020	SYSTEM	\$3,990.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				6	Jul 1, 2020	SYSTEM	(\$3,990.00)	
				6	Jul 1, 2020	SYSTEM	\$3,990.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$3,990.00)	
				7	Jul 16, 2020	SYSTEM	\$3,990.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	Overrun	Overrun	2	May 5, 2020	SYSTEM	\$3,556.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 12 on the current Payment Estimate.
				2	May 5, 2020	SYSTEM	(\$3,556.00)	
				2	May 5, 2020	vohsr1	(\$3,556.00)	Correction for overrun item adjustment due to material exception override.
			Overrun - T	otal			(\$3,556.00)	
	Overrun - Total						(\$3,556.00)	
0140 -	Total						(\$3,556.00)	
0150	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT	Material		1	Apr 16, 2020	SYSTEM	(\$1,200.00)	
	ARROW			1	Apr 16, 2020	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				2	May 5, 2020	SYSTEM	(\$1,200.00)	
				2	May 5,	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Overrun

Revision 4/1/2020 Page 8 of 11



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0150	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material			2020			Payment Estimate Item Adjustment (0009) due to user vohsr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				3	May 18, 2020	SYSTEM	(\$1,200.00)	
				3	May 18, 2020	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				4	Jun 2, 2020	SYSTEM	(\$1,200.00)	
				4	Jun 2, 2020	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				5	Jun 16, 2020	SYSTEM	(\$1,200.00)	
				5	Jun 16, 2020	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				6	Jul 1, 2020	SYSTEM	(\$1,200.00)	
				6	Jul 1, 2020	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$1,200.00)	
				7	Jul 16, 2020	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Overrun	Overrun	1	Apr 16, 2020	SYSTEM	(\$400.00)	
		Overrun	Overrun	1		SYSTEM SYSTEM		This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 18 on the current Payment Estimate.
	PAVEMENT MARKING, LEFT/RIGHT	Overrun	Overrun		2020 Apr 16,		(\$400.00)	Payment Estimate Item Adjustment (0003) overridding Payment
	PAVEMENT MARKING, LEFT/RIGHT	Overrun	Overrun	1	2020 Apr 16, 2020 May 5,	SYSTEM	(\$400.00) \$400.00	Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 18 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment
	PAVEMENT MARKING, LEFT/RIGHT	Overrun	Overrun - T	2	2020 Apr 16, 2020 May 5, 2020 May 5,	SYSTEM SYSTEM	(\$400.00) \$400.00 (\$400.00)	Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 18 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment
2450	PAVEMENT MARKING, LEFT/RIGHT ARROW Overrun - Total	Overrun		2	2020 Apr 16, 2020 May 5, 2020 May 5,	SYSTEM SYSTEM	(\$400.00) \$400.00 (\$400.00) \$400.00 \$0.00	Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 18 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment
	PAVEMENT MARKING, LEFT/RIGHT ARROW Overrun - Total Total			1 2 2 2 otal	2020 Apr 16, 2020 May 5, 2020 May 5, 2020	SYSTEM SYSTEM	(\$400.00) \$400.00 (\$400.00) \$400.00 \$0.00 \$0.00	Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 18 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment
0150 • 0160	PAVEMENT MARKING, LEFT/RIGHT ARROW Overrun - Total	Overrun		1 2 2 2 ootal	2020 Apr 16, 2020 May 5, 2020 May 5, 2020	SYSTEM SYSTEM SYSTEM SYSTEM	(\$400.00) \$400.00 (\$400.00) \$400.00 \$0.00 \$0.00 (\$700.00)	Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 18 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 13 on the current Payment Estimate.
	Overrun - Total PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW			1 2 2 2 otal	2020 Apr 16, 2020 May 5, 2020 May 5, 2020	SYSTEM SYSTEM	(\$400.00) \$400.00 (\$400.00) \$400.00 \$0.00 \$0.00	Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 18 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment
	Overrun - Total PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW			1 2 2 2 ootal	2020 Apr 16, 2020 May 5, 2020 May 5, 2020 Apr 16, 2020 Apr 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM	(\$400.00) \$400.00 (\$400.00) \$400.00 \$0.00 \$0.00 (\$700.00)	Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 18 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user vohsr1 overridding Payment Estimate Exception 12 on the current Payment
	Overrun - Total PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW			1 2 2 2 ootal 1 1 1	2020 Apr 16, 2020 May 5, 2020 May 5, 2020 Apr 16, 2020 Apr 16, 2020 May 5,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$400.00) \$400.00 (\$400.00) \$400.00 \$0.00 \$0.00 (\$700.00)	Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 18 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user vohsr1 overridding Payment Estimate Exception 12 on the current Payment
	Overrun - Total PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW			1 2 2 2 ootal 1 1 1 2 2	2020 Apr 16, 2020 May 5, 2020 May 5, 2020 Apr 16, 2020 Apr 16, 2020 May 5, 2020 May 5, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$400.00) \$400.00 (\$400.00) \$400.00 \$0.00 \$0.00 (\$700.00) \$700.00	Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 18 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user vohsr1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user vohsr1 overridding Payment Estimate Item Adjustment (0017) due to user vohsr1 overridding Payment Estimate Exception 6 on the current Payment
	Overrun - Total PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW			1 2 2 1 1 1 1 2 2 2	2020 Apr 16, 2020 May 5, 2020 May 5, 2020 Apr 16, 2020 Apr 16, 2020 May 5, 2020 May 5, 2020 May 5, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$400.00) \$400.00 (\$400.00) \$400.00 \$0.00 \$0.00 (\$700.00) \$700.00	Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 18 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user vohsr1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user vohsr1 overridding Payment Estimate Item Adjustment (0017) due to user vohsr1 overridding Payment Estimate Exception 6 on the current Payment
	Overrun - Total PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW			1 2 2 1 1 1 1 2 2 3 3	2020 Apr 16, 2020 May 5, 2020 May 5, 2020 Apr 16, 2020 Apr 16, 2020 Apr 2020 May 5, 2020 May 5, 2020 May 18, 2020 May 18, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$400.00) \$400.00 (\$400.00) \$400.00 \$0.00 \$0.00 \$700.00 \$700.00 \$700.00 \$700.00	Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 18 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '0.0000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user vohsr1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user vohsr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.

Revision 4/1/2020 Page 9 of 11



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0160	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	Material			2020			Payment Estimate Item Adjustment (0005) due to user vohsr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				5	Jun 16, 2020	SYSTEM	(\$700.00)	
				5	Jun 16, 2020	SYSTEM	\$700.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				6	Jul 1, 2020	SYSTEM	(\$700.00)	
				6	Jul 1, 2020	SYSTEM	\$700.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$700.00)	
				7	Jul 16, 2020	SYSTEM	\$700.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	· Total						\$0.00	
0170	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		1	Apr 16, 2020	SYSTEM	(\$877.44)	
				1	Apr 16, 2020	SYSTEM	\$877.44	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user vohsr1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				2	May 5, 2020	SYSTEM	(\$877.44)	
				2	May 5, 2020	SYSTEM	\$877.44	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user vohsr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				3	May 18, 2020	SYSTEM	(\$877.44)	
				3	May 18, 2020	SYSTEM	\$877.44	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user vohsr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				4	Jun 2, 2020	SYSTEM	(\$877.44)	
				4	Jun 2, 2020	SYSTEM	\$877.44	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user vohsr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Overrun	Overrun	1	Apr 16, 2020	SYSTEM	(\$68.64)	
				1	Apr 16, 2020	SYSTEM	\$68.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 19 on the current Payment Estimate.
				2	May 5, 2020	SYSTEM	(\$68.64)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				2	May 5, 2020	SYSTEM	\$68.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) overridding Payment Estimate Exception 14 on the current Payment Estimate.
	Overrun - Total						\$0.00	
0.4	Overrun - Total						\$0.00	
0170 - 0180	- Total 4 IN. YELLOW STANDARD WATERBORNE	Material		1	Apr 16,	SYSTEM	\$0.00 (\$988.98)	
	PAVEMENT MARKING PAINT, TYPE P BEADS			1	2020 Apr 16, 2020	SYSTEM	\$988.98	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user vohsr1 overridding Payment Estimate Exception 15 on the current Payment

Revision 4/1/2020 Page 10 of 11



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0180	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material						Estimate.
				2	May 5, 2020	SYSTEM	(\$988.98)	
				2	May 5, 2020	SYSTEM	\$988.98	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user vohsr1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
		- Total				\$0.00		
	Material - Total					\$0.00		
	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Overrun	Overrun	1	Apr 16, 2020	SYSTEM	(\$151.98)	
				1	Apr 16, 2020	SYSTEM	\$151.98	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 20 on the current Payment Estimate.
				2	May 5, 2020	SYSTEM	(\$151.98)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				2	May 5, 2020	SYSTEM	\$151.98	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) overridding Payment Estimate Exception 15 on the current Payment Estimate.
		Overrun - Total				\$0.00		
	Overrun - Total						\$0.00	
0180 -	Total				\$0.00			
Overall - Total							(\$6,371.98)	

Revision 4/1/2020 Page 11 of 11