

Pay Estimate Created Date: November 2, 2020

Progress Estima 8	ate Number	Contract ID Prime Contractor	200320-B01 Emery Sapp & Sons,	Pay Period Start October Inc. Pay Period End Novemb	16, 2020 Original Contract Amount er 1, 2020 Net Change Order Amount Current Contract Amount	t \$37,249.37			
Approval Date						By User			
November 2, 2020			Generated and Approved (and should be considered Draft) at the Project Office Level by						
November 2, 2020		R	eviewed and Approve	d (and should be considered Dra	ft) at the Resident Engineer Level by	lincom			
November 3, 2020			Rev	viewed and Approved at the Cen	tral Office Controllers Office Level by	greggd1			
Original Comp	letion Date	Current Con	npletion Date	Actual Completion Date	% of Current Contract Amour	nt Complete			
November 1	1, 2020	Novembe	er 1, 2020	er 1, 2020 November 1, 2020 99.44%					

No Milestones Exist for Contract

This Estimate		
This Estimate	Previous	To Date
\$0.00	\$1,766,636.31	\$1,766,636.31
\$0.00	\$144.39	\$144.39
\$0.00	\$0.00	\$0.00
\$0.00	\$0.00	\$0.00
\$0.00	\$0.00	\$0.00
\$0.00	\$0.00	\$0.00
	\$1,766,780.70	\$1,766,780.70
\$0.00		
	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$1,766,636.31 \$0.00 \$144.39 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$1,766,780.70

Items Paid This Estimate Period

No Data Available

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Project	Line	Item Description	Adjustment	Other Item	Comments	Adjustment	Line Item	Adjustment
Number	No.		Туре	Adjustment Type		Quantity	Adjustment Unit Price	amount
J2P3171	0070	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material			-9,798.41	\$9.45	(\$92,594.97)
	0070	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0001) due to user gardb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	9,798.41	\$9.45	\$92,594.97
	0080	MISC.	Material			-14,037.06	\$34.70	(\$487,085.98)
	0080	MISC.	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0002) due to user gardb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	14,037.06	\$34.70	\$487,085.98
	0090	3 IN. CONCRETE MEDIAN STRIP	Material			-29.9	\$170.00	(\$5,083.00)
	0090	3 IN. CONCRETE MEDIAN STRIP	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0003) due to user gardb1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	29.9	\$170.00	\$5,083.00
	0360	PRECAST CONCRETE DROP INLET 5 FT X 3 FT	Material			-9	\$710.00	(\$6,390.00)
	0360	PRECAST CONCRETE DROP INLET 5 FT X 3 FT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0004) due to user gardb1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	9	\$710.00	\$6,390.00
J2S3295	0700	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Material			-1,993	\$66.50	(\$132,534.50)
	0700	BITUMINOUS PAVEMENT MIXTURE PG64-22	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item	1,993	\$66.50	\$132,534.50



Pay Estimate Created Date: November 2, 2020

Progre	ess Estir 8	mate Number Contract ID Prime Cont	200320 ractor Emery		Pay Period Start October 16, 2020 Orig , Inc. Pay Period End November 1, 2020 Net Curr	Change Orde	er Amount \$	
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustmen amount
12S3295		(SURFACE LEVELING)			Adjustment (0005) due to user gardb1 overridding Payment Estimate Exception 4 on the current Payment Estimate.			
	0720	CONCRETE CURB RAMP	Material			-29.4	\$158.00	(\$4,645.2
	0720	CONCRETE CURB RAMP	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0006) due to user gardb1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	29.4	\$158.00	\$4,645.2
	0750	CONCRETE SIDEWALK, 4 IN				-156.5	\$89.00	(\$13,928.5
	0750	CONCRETE SIDEWALK, 4 IN.			This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0007) due to user gardb1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	156.5	\$89.00	\$13,928.5
	0760	CONCRETE SIDEWALK, 7 IN.				-36.2	\$81.00	(\$2,932.2
	0760	CONCRETE SIDEWALK, 7 IN.			This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0008) due to user gardb1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	36.2	\$81.00	\$2,932.2
	0770	MISC.	Material			-56.4	\$160.00	(\$9,024.0
	0770	MISC.	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0009) due to user gardb1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	56.4	\$160.00	\$9,024.0
	0780	MISC.	Material			-69	\$54.00	(\$3,726.0
	0780	MISC.	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0010) due to user gardb1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	69	\$54.00	\$3,726.0
	0790	MISC	Material			-128	\$52.00	(\$6,656.0
	0790	MISC.	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0011) due to user gardb1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	128	\$52.00	\$6,656.0
otal	· · · · ·		1					\$0.0



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Contract Project Information		
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work		
J2P3171	FAF-61-4(182)	Intersection improvements	61	RALLS	at Rte. A and 5th St. intersections in New London		
J2S3295	FAF-61-4(181)	Resurface and ADA improvements	61	RALLS	om Rte. 61 to 0.2 mile north of Rte. 19 at New London		

Totals by Job Numbers

71	This Estimate	Previous	To Date
Posted Item Pay	\$0.00	\$1,457,009.00	\$1,457,009.00
Gross Item Adjustments	\$0.00	\$77.38	\$77.38
Gross Item Pay	\$0.00	\$1,457,086.38	\$1,457,086.38
Incentive	\$0.00	\$0.00	\$0.00
Disincentive	\$0.00	\$0.00	\$0.00
	1		
Liquidated Damages	\$0.00	\$0.00	\$0.00
Other Contract Adjustments	\$0.00	\$0.00	\$0.00
95	This Estimate	Previous	To Date
Posted Item Pay	\$0.00	\$309,627.31	\$309.627.31
Gross Item Adjustments	\$0.00	\$67.01	\$67.01
Gross Item Pay	\$0.00 \$0.00	\$309.694.32	\$309.694.32
Gross tiell Fay	\$0.00	\$305,054.52	\$303,034.32
Incentive	\$0.00	\$0.00	\$0.00
Incentive Disincentive	\$0.00 \$0.00	\$0.00 \$0.00	\$0.00 \$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Exceeded Completion Time Exception: Contract 200320-B01, Time ID 00 DT, Time Type Completion Date, Current Completion Date 11/1/2020 12:00:00 AM.	No Remark was entered by Engineer	gardb1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J2P3171, Item 3040506, Project Item Line Number 0070, Material Set 304050696, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient.	No Remark was entered by Engineer	gardb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J2P3171, Item 4019905, Project Item Line Number 0080, Material Set 401990596, Material 0401BPPMBP1 - Plant Mix for Bit Pavement BP-1, Acceptance Action Generic AspLow is insufficient.	No Remark was entered by Engineer	gardb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3295, Item 4020520, Project Item Line Number 0700, Material Set 402052096, Material 0402SLPMSL - Plant Mix for Surface Leveling, Acceptance Action Generic AspSL is insufficient.	No Remark was entered by Engineer	gardb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3295, Item 6081010, Project Item Line Number 0720, Material Set 608101096, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	No Remark was entered by Engineer	gardb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J2P3171, Item 6083003, Project Item Line Number 0090, Material Set 608300396, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	No Remark was entered by Engineer	gardb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3295, Item 6086004, Project Item Line Number 0750, Material Set 608600496, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	No Remark was entered by Engineer	gardb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3295, Item 6086004, Project Item Line Number 0750, Material Set 608600496, Material 1036RSWFPLW014 - W01.4 Plain Welded Wire Fabric @, Acceptance Action Generic ReSteelFabric is insufficient.	No Remark was entered by Engineer	gardb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3295, Item 6086007, Project Item Line Number 0760, Material Set 608600796, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	No Remark was entered by Engineer	gardb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3295, Item 6086007, Project Item Line Number 0760, Material Set 608600796, Material 1036RSWFPLW014 - W01.4 Plain Welded Wire Fabric @, Acceptance Action Generic ReSteelFabric is insufficient.	No Remark was entered by Engineer	gardb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3295, Item 6089905, Project Item Line Number 0770, Material Set 6089905, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	No Remark was entered by Engineer	gardb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3295, Item 6089905, Project Item Line Number 0770, Material Set 6089905, Material 1036RSWFPLW014 - W01.4 Plain Welded Wire Fabric @, Acceptance Action Generic ReSteelFabric is insufficient.	No Remark was entered by Engineer	gardb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3295, Item 6099903, Project Item Line Number 0790, Material Set 6099903, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	No Remark was entered by Engineer	gardb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3295, Item 6099903, Project Item Line Number 0780, Material Set 6099903, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	No Remark was entered by Engineer	gardb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J2P3171, Item 7311053, Project Item Line Number 0360, Material Set 731105396, Material 1033DIRCPK - Precast Conc Drop Inlet, Acceptance Action Generic 1033DIRCPK is insufficient.	No Remark was entered by Engineer	gardb1	Overridden

Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Vote: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200320-B01	J2P3171	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$33,200.00	\$33,200.00
		0001	0020	2031000	CLASS A EXCAVATION	8,213.00	0.00	8,213.00	CUYD	8,213.00	\$15.70	\$128,944.10
		0001	0030	2036000	COMPACTING EMBANKMENT	1,756.00	0.00	1,756.00	CUYD	1,756.00	\$4.40	\$7,726.40
		0001	0040	2063000	CLASS 3 EXCAVATION	397.00	0.00	397.00	CUYD	397.00	\$5.70	\$2,262.90
		0001	0050	2071000	LINEAR GRADING CLASS 1	21.20	0.00	21.20	STA	21.20	\$1,120.00	\$23,744.00
		0001	0060	2101006A	SUBGRADE COMPACTION (6-INCH DEPTH)	69.00	0.00	69.00	100F	69.00	\$610.00	\$42,090.00
		0001	0070	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	13,514.00	284.41	13,798.41	SQYD	13,798.41	\$9.45	\$130,394.97
		0001	0080	4019905	MISC.Optional Pavement	13,514.00	523.06	14,037.06	SQYD	14,037.06	\$34.70	\$487,085.98
		0001	0090	6083003	3 IN. CONCRETE MEDIAN STRIP	29.90	0.00	29.90	SQYD	29.90	\$170.00	\$5,083.00
		0001	0100	6097000	ROCK LINING	4.00	0.00	4.00	CUYD	4.00	\$150.00	\$600.00
		0001	0110	6122012	IMPACT ATTENUATOR 55 MPH (SAND BARREL ARRAY)	2.00	0.00	2.00	EA	2.00	\$2,850.00	\$5,700.00
		0001	0120	6122020	REPLACEMENT SAND BARREL	1.00	-1.00	0.00	EA	0.00	\$510.00	\$0.00
		0001	0130	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$5,700.00	\$11,400.00
		0001	0140	6141024	GRATE AND BEARING PLATE (5 FT. X 3 FT. OR 1524 MM X 914 MM)	3.00	0.00	3.00	EA	3.00	\$1,600.00	\$4,800.00
		0001	0150	6161005	CONSTRUCTION SIGNS	1,170.00	0.00	1,170.00	SQFT	1,170.00	\$6.25	\$7,312.50
		0001	0160	6161008	ADVANCED WARNING RAIL SYSTEM	14.00	0.00	14.00	EA	14.00	\$54.70	\$765.80
		0001	0170	6161009	FLAG ASSEMBLY	11.00	0.00	11.00	EA	11.00	\$20.00	\$220.00
		0001	0180	6161025	CHANNELIZER (TRIM LINE)	300.00	0.00	300.00	EA	300.00	\$20.00	\$6,000.00
		0001	0190	6161030	TYPE III MOVEABLE BARRICADE	28.00	0.00	28.00	EA	28.00	\$120.00	\$3,360.00
		0001	0200	6161033	DIRECTIONAL INDICATOR BARRICADE	36.00	0.00	36.00	EA	36.00	\$22.00	\$792.00
		0001	0210	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	2.00	\$625.00	\$1,250.00
		0001	0220	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	-1.00	3.00	EA	3.00	\$3,400.00	\$10,200.00
		0001	0230	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	4.00	0.00	4.00	EA	4.00	\$850.00	\$3,400.00
		0001	0240	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	550.00	50.00	600.00	LF	600.00	\$20.00	\$12,000.00
		0001	0250	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$130,000.70	\$130,000.70
		0001	0260	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	4.00	-4.00	0.00	EA	0.00	\$600.00	\$0.00
		0001	0270	6191000	PAVEMENT EDGE TREATMENT	5,921.00	0.00	5,921.00	LF	5,921.00	\$10.00	\$59,210.00
		0001	0280	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN.	425.00	0.00	425.00	LF	425.00	\$20.00	\$8,500.00
		0001	0290	6200021	WHITE PREFORMED THERMOPLASTIC PAVEMENT MARKING,	17.00	0.00	17.00	EA	17.00	\$300.00	\$5,100.00
		0001	0300	6200042	LEFT/RIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	24.00	0.00	24.00	EA	24.00	\$51.00	\$1,224.00
		0001	0310	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	6,787.00	0.00	6,787.00	LF	6,787.00	\$0.16	\$1,085.92
		0001	0320	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	4,915.00	0.00	4,915.00	LF	4,915.00	\$0.16	\$786.40
		0001	0330	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT	2,074.00	0.00	2,074.00	LF	2,074.00	\$2.30	\$4,770.20
		0001	0340	6274000	MARKING PAINT, TYPE L BEADS CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$8,900.00	\$8,900.00
		0001	0350	7261018	18 IN. PIPE GROUP A	213.00	0.00	213.00	LF	213.00	\$138.00	\$29,394.00
		0001	0360	7311053	PRECAST CONCRETE DROP INLET 5 FT X 3 FT	9.00	0.00	9.00	FT	9.00	\$710.00	\$6,390.00
		0001	0370	7320618A	18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END	2.00	0.00	2.00	EA	1.00	\$580.00	\$580.00
		0001	0380	8051000A	SECTION SEEDING - COOL SEASON MIXTURES	2.40	0.00	2.40	ACRE	1.92	\$3,100.00	\$5,952.00
		0001	0390	8061004	SEDIMENT TRAP ROCK	7.90	0.00	7.90	CUYD	7.90	\$170.00	\$1,343.00
		0001	0390	8061004	ROCK DITCH CHECK	869.00	-355.00	514.00	LF	514.00	\$170.00	\$6,990.40
			0400	8061005	SEDIMENT REMOVAL	91.00	0.00	91.00	CUYD	0.00	\$13.00	\$0,990.40
		0001	0410	8061018	TEMPORARY SEEDING AND MULCHING	1.20	-1.20	0.00	ACRE	0.00	\$47.00	\$0.00
		0001	0420	8061017	SILT FENCE	935.00	-1.20	935.00	LF	935.00	\$850.00	\$0.00

Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTEL To Date (See report generated date)
200320-B01	J2P3171	0020	0440	7032002	CLASS B CONCRETE (MISC)	2.80	0.00	2.80	CUYD	2.80	\$1,938.00	\$5,426.40
		0020	0450	9013003	CONDUIT, 3 IN. RIGID, IN TRENCH	20.00	0.00	20.00	LF	20.00	\$13.65	\$273.00
		0020	0460	9014004	CONDUIT, 4 IN. RIGID, PUSHED	310.00	0.00	310.00	LF	310.00	\$23.00	\$7,130.00
		0020	0470	9015010	TRENCHING TYPE I	3,322.00	0.00	3,322.00	LF	3,322.00	\$5.10	\$16,942.20
		0020	0480	9016110	PULL BOX, PREFORMED CLASS 1	8.00	0.00	8.00	EA	8.00	\$1,255.00	\$10,040.00
		0020	0490	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	540.00	0.00	540.00	LF	540.00	\$1.15	\$621.00
		0020	0500	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	4,200.00	0.00	4,200.00	LF	4,200.00	\$4.00	\$16,800.00
		0020	0510	9018245	POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	6.00	0.00	6.00	EA	6.00	\$1,368.00	\$8,208.0
		0020	0520	9019902	MISC.Combination Pad Mounted Power Supply/ Lighting Control Station	1.00	0.00	1.00	EA	1.00	\$8,230.00	\$8,230.0
		0020	0530	9019902	MISC.TENON MOUNT LIGHT POLE, 45 FT.	6.00	0.00	6.00	EA	6.00	\$2,800.00	\$16,800.0
		0020	0540	9019902	MISC.TENON MOUNTED LED-C LUMINAIRE	6.00	0.00	6.00	EA	6.00	\$800.00	\$4,800.0
		0040	0550	9031010	CONCRETE FOOTINGS, EMBEDDED	14.20	0.00	14.20	CUYD	14.20	\$2,050.00	\$29,110.0
		0040	0560	9031210	STRUCTURAL STEEL POSTS	3,440.00	0.00	3,440.00	LB	3,440.00	\$5.50	\$18,920.0
		0040	0570	9031220	PIPE POSTS	1,700.00	0.00	1,700.00	LB	1,700.00	\$5.50	\$9,350.0
		0040	0580	9031241	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE)	20.00	0.00	20.00	EA	20.00	\$250.00	\$5,000.0
		0040	0590	9031242	36 IN. SURFACE-MOUNT DELINEATOR POST	6.00	0.00	6.00	EA	6.00	\$114.00	\$684.0
		0040	0600	9031270A	2 IN. PSST POST - 12 GA.	480.00	0.00	480.00	LF	480.00	\$18.00	\$8,640.0
		0040	0610	9031272	2.25 IN. PSST POST - 12 GA.	128.00	0.00	128.00	LF	128.00	\$19.00	\$2,432.0
		0040	0620	9031273	POST ANCHOR FOR 2 IN. PSST - 7 GA.	90.00	0.00	90.00	LF	90.00	\$34.00	\$3,060.0
		0040	0630	9031280	2.5 IN. PSST POST - 12 GA.	384.00	0.00	384.00	LF	384.00	\$20.50	\$7,872.0
		0040	0640	9031281	POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	72.00	0.00	72.00	LF	72.00	\$36.50	\$2,628.0
		0040	0650	9035004A	SH-FLAT SHEET	688.00	0.00	688.00	SQFT	688.00	\$27.00	\$18,576.0
		0040	0660	9035011A	ST-STRUCTURAL	254.00	0.00	254.00	SQFT	254.00	\$29.50	\$7,493.0
		0040	0670	9035069A	SHF-FLAT SHEET FLUORESCENT	9.00	0.00	9.00	SQFT	9.00	\$31.75	\$285.7
		0001	5001	4019905	MISC.Repair work on Route 61 due to damage from tractor trailer accident 7-16-20	0.00	1.00	1.00	SQYD	1.00	\$47,025.61	\$47,025.6
		2P3171 - To			ate as of Report Generated Date							\$1,457,008.9
	J2S3295	0001	0680	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$6,750.00	\$6,750.0
		0001	0690	3049910	MISC.TYPE 1 AGGREGATE FOR SHOULDERS	309.60	-296.10	13.50	TONS	13.50	\$41.00	\$553.5
		0001	0700	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	1,993.00	0.00	1,993.00	TONS	1,993.00	\$66.50	\$132,534.5
		0001	0710	4071005	TACK COAT	2,768.00	-353.00	2,415.00	GAL	2,415.00	\$2.50	\$6,037.5
		0001	0720	6081010	CONCRETE CURB RAMP	29.40	0.00	29.40	SQYD	29.40	\$158.00	\$4,645.2
		0001	0730	6081012	TRUNCATED DOMES	98.00	0.00	98.00	SQFT	98.00	\$19.50	\$1,911.0
		0001	0740	6084023	SIDEWALK HAND-RAILING WITHOUT BALUSTERS	97.00	0.00	97.00	LF	97.00	\$170.00	\$16,490.0
		0001	0750	6086004	CONCRETE SIDEWALK, 4 IN.	156.50	0.00	156.50	SQYD	156.50	\$89.00	\$13,928.5
		0001	0760	6086007	CONCRETE SIDEWALK, 7 IN.	36.20	0.00	36.20	SQYD	36.20	\$81.00	\$2,932.2
		0001	0770	6089905	MISC.CONCRETE SIDEWALK, 4 IN., SPECIAL	56.40	0.00	56.40	SQYD	56.40	\$160.00	\$9,024.0
		0001	0780	6099903	MISC.CONCRETE CURB TYPE S, SPECIAL	69.00	0.00	69.00	LF	69.00	\$54.00	\$3,726.0
		0001	0790	6099903	MISC.CURB AND GUTTER, TYPE B, SPECIAL	128.00	0.00	128.00	LF	128.00	\$52.00	\$6,656.0
		0001	0800	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	-1.00	1.00	EA	1.00	\$2,850.00	\$2,850.0
		0001	0810	6161005	CONSTRUCTION SIGNS	1,250.00	-510.00	740.00	SQFT	740.00	\$6.25	\$4,625.0
		0001	0820	6161009	FLAG ASSEMBLY	6.00	0.00	6.00	EA	6.00	\$20.00	\$120.0
		0001	0830	6161025	CHANNELIZER (TRIM LINE)	178.00	0.00	178.00	EA	178.00	\$20.00	\$3,560.0
				0404000	DIRECTIONAL INDICATOR BARRICADE	18.00	-18.00	0.00	EA	0.00	\$22.00	\$0.0
		0001	0840	6161033							+	
		0001	0840 0850	6161033	FLASHING ARROW PANEL	3.00	0.00	3.00	EA	1.00	\$625.00	\$625.0



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200320-B01	J2S3295				RETAINED							
		0001	0870	6169902	MISC.DETECTABLE PEDESTRIAN BARRICADE	4.00	0.00	4.00	EA	4.00	\$225.00	\$900.00
		0001	0880	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$44,288.86	\$44,288.86
		0001	0890	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	337.00	0.00	337.00	LF	337.00	\$0.16	\$53.92
		0001	0900	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	7,287.00	0.00	7,287.00	LF	7,287.00	\$0.09	\$655.83
		0001	0910	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	7,604.00	0.00	7,604.00	LF	7,604.00	\$0.09	\$684.36
		0001	0920	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	27,660.00	0.00	27,660.00	SQYD	27,660.00	\$0.90	\$24,894.00
		0001	0930	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$8,909.61	\$8,909.61
		0001	0940	8059901	MISC.SEEDING AND MULCHING	1.00	0.00	1.00	LS	0.50	\$4,560.26	\$2,280.13
		0020	0950	9019901	MISC.LIGHT POLE AND PULL BOX ADJUSTMENT	1.00	0.00	1.00	LS	1.00	\$3,192.19	\$3,192.19
	Project J	2S3295 - To	otal Value	Posted to D	ate as of Report Generated Date							\$309,627.30
200320-B01 Ove	rall - Total	Value Pos	ted to Da	te as of Repo	ort Generated Date							\$1,766,636.29



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work. The information below this line are details from Line Item agency views. No Agency View Details Exist



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0030	COMPACTING EMBANKMENT	Material		1	Jul 16, 2020	SYSTEM	(\$1,320.00)	
				1	Jul 16, 2020	SYSTEM	\$1,320.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user gardb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				2	Aug 3, 2020	SYSTEM	(\$1,588.40)	
				2	Aug 3, 2020	SYSTEM	\$1,588.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user gardb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				3	Aug 14, 2020	SYSTEM	(\$6,956.40)	
				3	Aug 14, 2020	SYSTEM	\$6,956.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user gardb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				4	Sep 3, 2020	SYSTEM	(\$7,726.40)	
				4	Sep 3, 2020	SYSTEM	\$7,726.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user gardb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				5	Sep 16, 2020	SYSTEM	(\$7,726.40)	
				5	Sep 16, 2020	SYSTEM	\$7,726.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user gardb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0030 -	Total						\$0.00	
0060	SUBGRADE COMPACTION (6- INCH DEPTH)	Material		1	Jul 16, 2020	SYSTEM	(\$19,947.00)	
				1	Jul 16, 2020	SYSTEM	\$19,947.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user gardb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				2	Aug 3, 2020	SYSTEM	(\$19,947.00)	
				2	Aug 3, 2020	SYSTEM	\$19,947.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user gardb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				3	Aug 14, 2020	SYSTEM	(\$37,881.00)	
				3	Aug 14, 2020	SYSTEM	\$37,881.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user gardb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				4	Sep 3, 2020	SYSTEM	(\$42,090.00)	
				4	Sep 3, 2020	SYSTEM	\$42,090.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user gardb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				5	Sep 16, 2020	SYSTEM	(\$42,090.00)	
				5	Sep 16, 2020	SYSTEM	\$42,090.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user gardb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0060 -							\$0.00	
0070	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		1	Jul 16, 2020	SYSTEM	(\$30,807.00)	
				1	Jul 16, 2020	SYSTEM	\$30,807.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user gardb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				2	Aug 3, 2020	SYSTEM	(\$48,024.90)	
				2	Aug 3, 2020	SYSTEM	\$48,024.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user gardb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0070	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		3	Aug 14, 2020	SYSTEM	(\$114,940.35)	
				3	Aug 14, 2020	SYSTEM	\$114,940.35	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user gardb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				4	Sep 3, 2020	SYSTEM	(\$114,940.35)	
				4	Sep 3, 2020	SYSTEM	\$114,940.35	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user gardb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				5	Sep 16, 2020	SYSTEM	(\$127,707.30)	
				5	Sep 16, 2020	SYSTEM	\$127,707.30	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user gardb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				6	Oct 1, 2020	SYSTEM	(\$92,594.97)	
				6	Oct 1, 2020	SYSTEM	\$92,594.97	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user gardb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				7	Oct 19, 2020	SYSTEM	(\$92,594.97)	
				7	Oct 19, 2020	SYSTEM	\$92,594.97	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user gardb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				8	Nov 2, 2020	SYSTEM	(\$92,594.97)	
				8	Nov 2, 2020	SYSTEM	\$92,594.97	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user gardb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0070	- Total MISC. Optional Pavement	Material		3	Aug 14,	SYSTEM	\$0.00 (\$375,140.66)	
5000	inico. optional i avoinont	Material			2020			
				3	Aug 14, 2020	SYSTEM	\$375,140.66	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user gardb1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				4	Sep 3, 2020	SYSTEM	(\$375,140.66)	
				4	Sep 3, 2020	SYSTEM	\$375,140.66	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user gardb1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				5	Sep 16, 2020	SYSTEM	(\$375,140.66)	
				5	Sep 16, 2020	SYSTEM	\$375,140.66	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user gardb1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				6	Oct 1, 2020	SYSTEM	(\$487,085.98)	
				6	Oct 1, 2020	SYSTEM	\$487,085.98	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user gardb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				7	Oct 19, 2020	SYSTEM	(\$487,085.98)	
				7	Oct 19, 2020	SYSTEM	\$487,085.98	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user gardb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				8	Nov 2, 2020	SYSTEM	(\$487,085.98)	
				8	Nov 2, 2020	SYSTEM	\$487,085.98	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user gardb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total Total		- Total				\$0.00 \$0.00 \$0.00	



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks	
Line	2 cool pilon	Туре	Adjustment Type	Number	Date	Ву	7 1110 1111		
0090	3 IN. CONCRETE MEDIAN STRIP	Material		4	Sep 3, 2020	SYSTEM	(\$4,573.00)		
				4	Sep 3, 2020	SYSTEM	\$4,573.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user gardb1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	
				5	Sep 16, 2020	SYSTEM	(\$5,083.00)		
				5	Sep 16, 2020	SYSTEM	\$5,083.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user gardb1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	
					6	Oct 1, 2020	SYSTEM	(\$5,083.00)	
				6	Oct 1, 2020	SYSTEM	\$5,083.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user gardb1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
				7	Oct 19, 2020	SYSTEM	(\$5,083.00)		
				7	Oct 19, 2020	SYSTEM	\$5,083.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user gardb1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
				8	Nov 2, 2020	SYSTEM	(\$5,083.00)		
				8	Nov 2, 2020	SYSTEM	\$5,083.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user gardb1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	
			- Total				\$0.00		
	Material - Total						\$0.00		
0090 -	- Total						\$0.00		
0100	ROCK LINING	Material		4	Sep 3, 2020	SYSTEM	(\$600.00)		
				4	Sep 3, 2020	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user gardb1 overridding Payment Estimate Exception 35 on the current Payment Estimate.	
			- Total				\$0.00		
	Material - Total						\$0.00		
0100 -	Total						\$0.00		
0240	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	Material		1	Jul 16, 2020	SYSTEM	(\$11,000.00)		
				1	Jul 16, 2020	SYSTEM	\$11,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user gardb1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
				2	Aug 3, 2020	SYSTEM	(\$11,000.00)		
				3	Aug 14, 2020	SYSTEM	(\$12,000.00)		
				3	Aug 14, 2020	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user gardb1 overridding Payment Estimate Exception 39 on the current Payment Estimate.	
			- Total				(\$11,000.00)		
	Material - Total						(\$11,000.00)		
	TEMPORARY TRAFFIC BARRIER, CONTRACTOR	MaterialCredit		3	Aug 14, 2020	SYSTEM	\$11,000.00		
	FURNISHED / RETAINED		- Total				\$11,000.00		
	FURNISHED / RETAINED						\$11,000.00		
	FURNISHED / RETAINED								
	MaterialCredit - Total TEMPORARY TRAFFIC BARRIER, CONTRACTOR	Other Item Adjustment	MDPA	2	Aug 3, 2020	gardb1	\$11,000.00	Material payment adjustment correction.	
	MaterialCredit - Total TEMPORARY TRAFFIC		MDPA	2 3		gardb1 gardb1	\$11,000.00 (\$11,000.00)	Material payment adjustment correction. Material payment adjustment for overpaument	
	MaterialCredit - Total TEMPORARY TRAFFIC BARRIER, CONTRACTOR		MDPA MDPA - Tot	3	2020 Aug 14,				
	MaterialCredit - Total TEMPORARY TRAFFIC BARRIER, CONTRACTOR			3	2020 Aug 14,		(\$11,000.00)		
0240 -	MaterialCredit - Total TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED			3	2020 Aug 14,		(\$11,000.00) \$0.00		



				1				
Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0280	WHITE	Material		2	Aug 3, 2020	SYSTEM	\$1,160.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user gardb1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				3	Aug 14, 2020	SYSTEM	(\$1,160.00)	
				3	Aug 14, 2020	SYSTEM	\$1,160.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user gardb1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0280 -	Total						\$0.00	
0290	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material		2	Aug 3, 2020	SYSTEM	(\$1,200.00)	
				2	Aug 3, 2020	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user gardb1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				3	Aug 14, 2020	SYSTEM	(\$1,200.00)	
				3	Aug 14, 2020	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user gardb1 overridding Payment Estimate Exception 41 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0290 -	Total						\$0.00	
0310	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT	Material		2	Aug 3, 2020	SYSTEM	(\$155.68)	
	MARKING PAINT, TYPE L BEADS			2	Aug 3, 2020	SYSTEM	\$155.68	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user gardb1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				3	Aug 14, 2020	SYSTEM	(\$155.68)	
				3	Aug 14, 2020	SYSTEM	\$155.68	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user gardb1 overridding Payment Estimate Exception 42 on the current Payment Estimate.
				4	Sep 3, 2020	SYSTEM	(\$155.68)	
				5	Sep 16, 2020	SYSTEM	(\$155.68)	
				5	Sep 16, 2020	SYSTEM	\$155.68	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user gardb1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
			- Total				(\$155.68)	
	Material - Total						(\$155.68)	
	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	MaterialCredit		5	Sep 16, 2020	SYSTEM	\$155.68	
			- Total				\$155.68	
	MaterialCredit - Total						\$155.68	
	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS		REFL	6	Oct 1, 2020	gardb1	\$39.09	Edge line of Rte. 61
			REFL - Tota	ıl			\$39.09	
	Other Item Adjustment - Total						\$39.09	
0310 -							\$39.09	
0320	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Other Item Adjustment	REFL	6	Oct 1, 2020	gardb1	\$38.29	Centerline Rte. 61
			REFL - Tota	ıl			\$38.29	
	Other Item Adjustment - Total						\$38.29	
0320 -							\$38.29	
0360	PRECAST CONCRETE DROP	Material		3	Aug 14,	SYSTEM	(\$5,751.00)	
0000	I REGAULOUNGRETE DROP	Matchai		5	Aug 14,	STOTEN	(40,701.00)	



				1				
Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
0260		Material	Туре		2020			
0360	INLET 5 FT X 3 FT	Material		3	2020 Aug 14, 2020	SYSTEM	\$5,751.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user gardb1 overridding Payment
				4	Sep 3,	SYSTEM	(\$5,751.00)	Estimate Exception 47 on the current Payment Estimate.
				5	2020 Sep 16,	SYSTEM	(\$5,751.00)	
					2020			
				5	Sep 16, 2020	SYSTEM	\$5,751.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user gardb1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
				8	Nov 2, 2020	SYSTEM	(\$6,390.00)	
				8	Nov 2, 2020	SYSTEM	\$6,390.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user gardb1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
			- Total				(\$5,751.00)	
	Material - Total						(\$5,751.00)	
	PRECAST CONCRETE DROP INLET 5 FT X 3 FT	MaterialCredit		5	Sep 16, 2020	SYSTEM	\$5,751.00	
			- Total				\$5,751.00	
	MaterialCredit - Total						\$5,751.00	
0360 -	Total						\$0.00	
0370	18 IN. OR ALLOWED SUBSTITUTE GROUP A	Material		2	Aug 3, 2020	SYSTEM	(\$580.00)	
	FLARED END SECTION			2	Aug 3, 2020	SYSTEM	\$580.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user gardb1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				3	Aug 14, 2020	SYSTEM	(\$580.00)	
				3	Aug 14, 2020	SYSTEM	\$580.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user gardb1 overridding Payment Estimate Exception 48 on the current Payment Estimate.
				4	Sep 3, 2020	SYSTEM	(\$580.00)	
				5	Sep 16, 2020	SYSTEM	(\$580.00)	
				5	Sep 16, 2020	SYSTEM	\$580.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user gardb1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
			- Total				(\$580.00)	
	Material - Total						(\$580.00)	
	18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	MaterialCredit		5	Sep 16, 2020	SYSTEM	\$580.00	
			- Total				\$580.00	
	MaterialCredit - Total						\$580.00	
0370 -							\$0.00	
0380	SEEDING - COOL SEASON MIXTURES	Material		2	Aug 3, 2020	SYSTEM	(\$1,550.00)	
				2	Aug 3, 2020	SYSTEM	\$1,550.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user gardb1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				3	Aug 14, 2020	SYSTEM	(\$1,550.00)	
				3	Aug 14, 2020	SYSTEM	\$1,550.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user gardb1 overridding Payment Estimate Exception 49 on the current Payment Estimate.
				4	Sep 3, 2020	SYSTEM	(\$5,952.00)	
			- Total				(\$5,952.00)	
	Material - Total						(\$5,952.00)	
	SEEDING - COOL SEASON	MaterialCredit		5	Sep 16,	SYSTEM	\$5,952.00	
	MIXTURES				2020			



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0380		MaterialCredit	- Total				\$5,952.00	
0300	MaterialCredit - Total	MaterialCredit	- 10(a)				\$5,952.00	
1200	- Total						\$0.00	
		Material		2	Aug 14	OVOTEM		
0440	CLASS B CONCRETE (MISC)	Material		3	Aug 14, 2020	SYSTEM	(\$4,883.76)	
				3	Aug 14, 2020	SYSTEM	\$4,883.76	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user gardb1 overridding Paymen Estimate Exception 44 on the current Payment Estimate.
				4	Sep 3, 2020	SYSTEM	(\$4,883.76)	
			- Total				(\$4,883.76)	
	Material - Total						(\$4,883.76)	
	CLASS B CONCRETE (MISC)	MaterialCredit		5	Sep 16, 2020	SYSTEM	\$4,883.76	
			- Total				\$4,883.76	
	MaterialCredit - Total						\$4,883.76	
0440	- Total						\$0.00	
0520	MISC. Combination Pad Mounted Power Supply/ Lighting Control	Material		3	Aug 14, 2020	SYSTEM	(\$4,115.00)	
	Station			3	Aug 14, 2020	SYSTEM	\$4,115.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user gardb1 overridding Paymen Estimate Exception 56 on the current Payment Estimate.
				4	Sep 3, 2020	SYSTEM	(\$4,115.00)	
			5	Sep 16, 2020	SYSTEM	(\$4,115.00)		
				5	Sep 16, 2020	SYSTEM	\$4,115.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user gardb1 overridding Paymen Estimate Exception 33 on the current Payment Estimate.
			- Total				(\$4,115.00)	
	Material - Total						(\$4,115.00)	
	MISC. Combination Pad Mounted Power Supply/ Lighting Control Station	MaterialCredit		5	Sep 16, 2020	SYSTEM	\$4,115.00	
			- Total				\$4,115.00	
	MaterialCredit - Total						\$4,115.00	
0520	- Total						\$0.00	
0540	MISC. TENON MOUNTED LED-C LUMINAIRE	Material		5	Sep 16, 2020	SYSTEM	(\$4,800.00)	
				5	Sep 16, 2020	SYSTEM	\$4,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user gardb1 overridding Paymer Estimate Exception 32 on the current Payment Estimate.
								Esumate Exception 32 on the current Payment Esumate.
			- Total				\$0.00	Estimate Exception 32 on the current Payment Estimate.
	Material - Total		- Total				\$0.00 \$0.00	
0540	Material - Total - Total		- Total					Estimate Exception 32 on the current Payment Estimate.
		Construction Stockpile	- Total	3	Aug 14, 2020	SYSTEM	\$0.00	Payment Estimate Item Adjustment generated Stockpile Transaction
	- Total		- Total	3	Aug 14, 2020 Sep 3, 2020	SYSTEM SYSTEM	\$0.00 \$0.00	
	- Total		- Total		2020 Sep 3,		\$0.00 \$0.00 \$8,655.40	Payment Estimate Item Adjustment generated Stockpile Transaction
	- Total				2020 Sep 3,		\$0.00 \$0.00 \$8,655.40 (\$8,655.40)	Payment Estimate Item Adjustment generated Stockpile Transaction
	Total STRUCTURAL STEEL POSTS	Stockpile			2020 Sep 3,		\$0.00 \$0.00 \$8,655.40 (\$8,655.40) \$0.00	Payment Estimate Item Adjustment generated Stockpile Transaction
	Total STRUCTURAL STEEL POSTS Construction Stockpile - Total	Stockpile		4	2020 Sep 3, 2020 Sep 3,	SYSTEM	\$0.00 \$0.00 \$8,655.40 (\$8,655.40) \$0.00 \$0.00	Payment Estimate Item Adjustment generated Stockpile Transaction
0540 0560	Total STRUCTURAL STEEL POSTS Construction Stockpile - Total STRUCTURAL STEEL POSTS	Stockpile	- Total	4	2020 Sep 3, 2020 Sep 3,	SYSTEM	\$0.00 \$0.00 \$8,655.40 (\$8,655.40) \$0.00 \$0.00 (\$18,920.00) (\$18,920.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
	Total STRUCTURAL STEEL POSTS Construction Stockpile - Total	Stockpile	- Total	4	2020 Sep 3, 2020 Sep 3,	SYSTEM	\$0.00 \$0.00 \$8,655.40 (\$8,655.40) \$0.00 \$0.00 (\$18,920.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
	Total STRUCTURAL STEEL POSTS Construction Stockpile - Total STRUCTURAL STEEL POSTS Material - Total	Stockpile	- Total	4	2020 Sep 3, 2020 Sep 3, 2020	SYSTEM SYSTEM	\$0.00 \$0.00 \$8,655.40 (\$8,655.40) \$0.00 \$0.00 (\$18,920.00) (\$18,920.00) (\$18,920.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
	Total STRUCTURAL STEEL POSTS Construction Stockpile - Total STRUCTURAL STEEL POSTS Material - Total	Stockpile	- Total - Total	4	2020 Sep 3, 2020 Sep 3, 2020	SYSTEM SYSTEM	\$0.00 \$0.00 \$8,655.40 (\$8,655.40) \$0.00 (\$18,920.00) (\$18,920.00) (\$18,920.00) \$18,920.00	Payment Estimate Item Adjustment generated Stockpile Transaction



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0570	PIPE POSTS	Construction Stockpile		3	Aug 14, 2020	SYSTEM	\$3,536.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				4	Sep 3, 2020	SYSTEM	(\$3,536.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
	PIPE POSTS	Material		4	Sep 3, 2020	SYSTEM	(\$9,350.00)	
	Material Tatal		- Total				(\$9,350.00)	
	Material - Total						(\$9,350.00)	
	PIPE POSTS	MaterialCredit		5	Sep 16, 2020	SYSTEM	\$9,350.00	
			- Total				\$9,350.00	
	MaterialCredit - Total						\$9,350.00	
0570 -	Total						\$0.00	
0580	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL	Construction Stockpile		2	Aug 3, 2020	SYSTEM	\$3,240.00	Payment Estimate Item Adjustment generated Stockpile Transaction
	TUBE)			4	Sep 3, 2020	SYSTEM	(\$3,240.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
0580 -	Total						\$0.00	
0590	36 IN. SURFACE-MOUNT DELINEATOR POST	Construction Stockpile		2	Aug 3, 2020	SYSTEM	\$195.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				5	Sep 16, 2020	SYSTEM	(\$195.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total		Total				\$0.00	
0590 -							\$0.00	
0600	2 IN. PSST POST - 12 GA.	Construction Stockpile		2	Aug 3, 2020	SYSTEM	\$1,824.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				4	Sep 3, 2020	SYSTEM	(\$1,824.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
0600 -	Total						\$0.00	
0610	2.25 IN. PSST POST - 12 GA.	Construction Stockpile		2	Aug 3, 2020	SYSTEM	\$544.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				4	Sep 3, 2020	SYSTEM	(\$544.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
0610 -	Total						\$0.00	
0620	POST ANCHOR FOR 2 IN. PSST - 7 GA.	Construction Stockpile		2	Aug 3, 2020	SYSTEM	\$1,359.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				4	Sep 3, 2020	SYSTEM	(\$1,359.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stocknile Total							
	Construction Stockpile - Total						\$0.00	
0620 - 0630	Total 2.5 IN. PSST POST - 12 GA.	Construction		2	Aug 3,	SYSTEM	\$0.00 \$1,958.40	Payment Estimate Item Adjustment generated Stockpile Transaction
		Stockpile		4	2020 Sep 3, 2020	SYSTEM	(\$1,958.40)	Payment Estimate Item Adjustment generated Stockpile Transaction
			Tetel		2020			
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
0630 -	Total						\$0.00	
0640	POST ANCHOR FOR 2.5 IN.	Construction		2	Aug 3,	SYSTEM	\$1,581.84	Payment Estimate Item Adjustment generated Stockpile Transaction



				_	-	-		
Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0640	PSST - 7 GA.	Stockpile			2020			
				4	Sep 3, 2020	SYSTEM	(\$1,581.84)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
0640 -	Total						\$0.00	
0650	SH-FLAT SHEET	Construction Stockpile		2	Aug 3, 2020	SYSTEM	\$5,435.20	Payment Estimate Item Adjustment generated Stockpile Transaction
				4	Sep 3, 2020	SYSTEM	(\$5,435.20)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
0650 -	Total						\$0.00	
0660	ST-STRUCTURAL	Construction Stockpile		2	Aug 3, 2020	SYSTEM	\$3,276.60	Payment Estimate Item Adjustment generated Stockpile Transaction
				4	Sep 3, 2020	SYSTEM	(\$3,276.60)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
0660 -	Total						\$0.00	
0670	SHF-FLAT SHEET FLUORESCENT	Construction Stockpile		2	Aug 3, 2020	SYSTEM	\$98.10	Payment Estimate Item Adjustment generated Stockpile Transaction
				4	Sep 3, 2020	SYSTEM	(\$98.10)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
0670 -	Total						\$0.00	
0690	MISC. TYPE 1 AGGREGATE FOR SHOULDERS	Material		3	Aug 14, 2020	SYSTEM	(\$553.50)	
				4	Sep 3, 2020	SYSTEM	(\$553.50)	
				4	Sep 3, 2020	SYSTEM	\$553.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0042) due to user gardb1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				5	Sep 16, 2020	SYSTEM	(\$553.50)	
				5	Sep 16, 2020	SYSTEM	\$553.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user gardb1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				(\$553.50)	
	Material - Total						(\$553.50)	
	MISC. TYPE 1 AGGREGATE FOR SHOULDERS	MaterialCredit		4	Sep 3, 2020	SYSTEM	\$553.50	
			- Total				\$553.50	
	MaterialCredit - Total						\$553.50	
0690 -	Total						\$0.00	
0700	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE	Material		4	Sep 3, 2020	SYSTEM	(\$132,534.50)	
	LEVELING)			4	Sep 3, 2020	SYSTEM	\$132,534.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0043) due to user gardb1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				5	Sep 16, 2020	SYSTEM	(\$132,534.50)	
				5	Sep 16, 2020	SYSTEM	\$132,534.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user gardb1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				6	Oct 1, 2020	SYSTEM	(\$132,534.50)	
				6	Oct 1, 2020	SYSTEM	\$132,534.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user gardb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0700	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE	Material		7	Oct 19, 2020	SYSTEM	(\$132,534.50)	
	LEVELING)			7	Oct 19, 2020	SYSTEM	\$132,534.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user gardb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				8	Nov 2, 2020	SYSTEM	(\$132,534.50)	
				8	Nov 2, 2020	SYSTEM	\$132,534.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user gardb1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total	1			\$0.00	
	Material - Total						\$0.00	
)700 -	- Total						\$0.00	
0720	CONCRETE CURB RAMP	Material		3	Aug 14, 2020	SYSTEM	(\$4,645.20)	
				3	Aug 14, 2020	SYSTEM	\$4,645.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user gardb1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				4	Sep 3, 2020	SYSTEM	(\$4,645.20)	
				4	Sep 3, 2020	SYSTEM	\$4,645.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0044) due to user gardb1 overridding Paymen Estimate Exception 8 on the current Payment Estimate.
				5	Sep 16, 2020	SYSTEM	(\$4,645.20)	
				5	Sep 16, 2020	SYSTEM	\$4,645.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user gardb1 overridding Paymen Estimate Exception 8 on the current Payment Estimate.
				6	Oct 1, 2020	SYSTEM	(\$4,645.20)	
				6	Oct 1, 2020	SYSTEM	\$4,645.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user gardb1 overridding Paymer Estimate Exception 4 on the current Payment Estimate.
				7	Oct 19, 2020	SYSTEM	(\$4,645.20)	
				7	Oct 19, 2020	SYSTEM	\$4,645.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user gardb1 overridding Paymen Estimate Exception 4 on the current Payment Estimate.
				8	Nov 2, 2020	SYSTEM	(\$4,645.20)	
				8	Nov 2, 2020	SYSTEM	\$4,645.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user gardb1 overridding Paymen Estimate Exception 5 on the current Payment Estimate.
			- Total		1		\$0.00	
	Material - Total						\$0.00	
)720 -	- Total						\$0.00	
0730	TRUNCATED DOMES	Material		3	Aug 14, 2020	SYSTEM	(\$1,911.00)	
				3	Aug 14, 2020	SYSTEM	\$1,911.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user gardb1 overridding Paymer Estimate Exception 12 on the current Payment Estimate.
				4	Sep 3, 2020	SYSTEM	(\$1,911.00)	
				4	Sep 3, 2020	SYSTEM	\$1,911.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0045) due to user gardb1 overridding Paymer Estimate Exception 13 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
)73 <u>0</u> -	- Total						\$0.00	
0740	SIDEWALK HAND-RAILING WITHOUT BALUSTERS	Material		6	Oct 1, 2020	SYSTEM	(\$16,490.00)	
				6	Oct 1, 2020	SYSTEM	\$16,490.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user gardb1 overridding Paymen Estimate Exception 6 on the current Payment Estimate.
			- Total		1		\$0.00	



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks								
0740	Material - Total						\$0.00									
0740 -	- Total						\$0.00									
0750	CONCRETE SIDEWALK, 4 IN.	Material		3	Aug 14, 2020	SYSTEM	(\$13,928.50)									
				3	Aug 14, 2020	SYSTEM	\$13,928.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user gardb1 overridding Payment Estimate Exception 13 on the current Payment Estimate.								
				4	Sep 3, 2020	SYSTEM	(\$13,928.50)									
				4	Sep 3, 2020	SYSTEM	\$13,928.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0046) due to user gardb1 overridding Payment Estimate Exception 17 on the current Payment Estimate.								
				5	Sep 16, 2020	SYSTEM	(\$13,928.50)									
				5	Sep 16, 2020	SYSTEM	\$13,928.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user gardb1 overridding Payment Estimate Exception 11 on the current Payment Estimate.								
				6	Oct 1, 2020	SYSTEM	(\$13,928.50)									
				6	Oct 1, 2020	SYSTEM	\$13,928.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user gardb1 overridding Payment Estimate Exception 7 on the current Payment Estimate.								
												7	Oct 19, 2020	SYSTEM	(\$13,928.50)	
				7	Oct 19, 2020	SYSTEM	\$13,928.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user gardb1 overridding Payment Estimate Exception 6 on the current Payment Estimate.								
						8	Nov 2, 2020	SYSTEM	(\$13,928.50)							
				8	Nov 2, 2020	SYSTEM	\$13,928.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user gardb1 overridding Payment Estimate Exception 7 on the current Payment Estimate.								
			- Total				\$0.00									
	Material - Total						\$0.00									
0750 ·	- Total						\$0.00									
0760	CONCRETE SIDEWALK, 7 IN.	Material		3	Aug 14, 2020	SYSTEM	(\$2,932.20)									
				3	Aug 14, 2020	SYSTEM	\$2,932.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user gardb1 overridding Payment Estimate Exception 20 on the current Payment Estimate.								
				4	Sep 3, 2020	SYSTEM	(\$2,932.20)									
					4	Sep 3,	SYSTEM	\$2,932.20	This adjustment offsets the original system-generated Overrun Payment							
					2020			Estimate Item Adjustment (0047) due to user gardb1 overridding Payment Estimate Exception 23 on the current Payment Estimate.								
				5	2020 Sep 16, 2020	SYSTEM	(\$2,932.20)	Estimate Item Adjustment (0047) due to user gardb1 overridding Payment								
				5	Sep 16,	SYSTEM SYSTEM	(\$2,932.20) \$2,932.20	Estimate Item Adjustment (0047) due to user gardb1 overridding Payment								
					Sep 16, 2020 Sep 16,		,	Estimate Item Adjustment (0047) due to user gardb1 overridding Payment Estimate Exception 23 on the current Payment Estimate.								
				5	Sep 16, 2020 Sep 16, 2020 Oct 1,	SYSTEM	\$2,932.20	Estimate Item Adjustment (0047) due to user gardb1 overridding Payment Estimate Exception 23 on the current Payment Estimate.								
				5	Sep 16, 2020 Sep 16, 2020 Oct 1, 2020 Oct 1,	SYSTEM SYSTEM	\$2,932.20 (\$2,932.20)	Estimate Item Adjustment (0047) due to user gardb1 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user gardb1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user gardb1 overridding Payment								
				5 6 6	Sep 16, 2020 Sep 16, 2020 Oct 1, 2020 Oct 1, 2020 Oct 19,	SYSTEM SYSTEM SYSTEM	\$2,932.20 (\$2,932.20) \$2,932.20	Estimate Item Adjustment (0047) due to user gardb1 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user gardb1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user gardb1 overridding Payment								
				5 6 6 7	Sep 16, 2020 Sep 16, 2020 Oct 1, 2020 Oct 1, 2020 Oct 19, 2020 Oct 19,	SYSTEM SYSTEM SYSTEM SYSTEM	\$2,932.20 (\$2,932.20) \$2,932.20 (\$2,932.20)	Estimate Item Adjustment (0047) due to user gardb1 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user gardb1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user gardb1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Exception 9 on the current Payment Estimate.								
				5 6 6 7 7 7	Sep 16, 2020 Sep 16, 2020 Oct 1, 2020 Oct 1, 2020 Oct 19, 2020 Oct 19, 2020	SYSTEM SYSTEM SYSTEM SYSTEM	\$2,932.20 (\$2,932.20) \$2,932.20 (\$2,932.20) \$2,932.20	Estimate Item Adjustment (0047) due to user gardb1 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user gardb1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user gardb1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Exception 9 on the current Payment Estimate.								



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
0760	Material - Total						\$0.00		
0760 -	Total						\$0.00		
0770	MISC. CONCRETE SIDEWALK, 4 IN., SPECIAL	Material		3	Aug 14, 2020	SYSTEM	(\$9,024.00)		
				3	Aug 14, 2020	SYSTEM	\$9,024.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user gardb1 overridding Payment Estimate Exception 25 on the current Payment Estimate.	
				4	Sep 3, 2020	SYSTEM	(\$9,024.00)		
				4	Sep 3, 2020	SYSTEM	\$9,024.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0048) due to user gardb1 overridding Payment Estimate Exception 29 on the current Payment Estimate.	
				5	Sep 16, 2020	SYSTEM	(\$9,024.00)		
				5	Sep 16, 2020	SYSTEM	\$9,024.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user gardb1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	
				6	Oct 1, 2020	SYSTEM	(\$9,024.00)		
				6	Oct 1, 2020	SYSTEM	\$9,024.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user gardb1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	
				7	Oct 19, 2020	SYSTEM	(\$9,024.00)		
				7	Oct 19, 2020	SYSTEM	\$9,024.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user gardb1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	
					8	Nov 2, 2020	SYSTEM	(\$9,024.00)	
					8	Nov 2, 2020	SYSTEM	\$9,024.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user gardb1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
			- Total				\$0.00		
	Material - Total						\$0.00		
0770 -	Total						\$0.00		
0780	MISC. CONCRETE CURB TYPE S, SPECIAL	Material		3	Aug 14, 2020	SYSTEM	(\$3,726.00)		
				3	Aug 14, 2020	SYSTEM	\$3,726.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user gardb1 overridding Payment Estimate Exception 35 on the current Payment Estimate.	
				4	Sep 3, 2020	SYSTEM	(\$3,726.00)		
				4	Sep 3, 2020	SYSTEM	\$3,726.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0049) due to user gardb1 overridding Payment Estimate Exception 36 on the current Payment Estimate.	
				5	Sep 16, 2020	SYSTEM	(\$3,726.00)		
				5	Sep 16, 2020	SYSTEM	\$3,726.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user gardb1 overridding Payment Estimate Exception 20 on the current Payment Estimate.	
				6	Oct 1, 2020	SYSTEM	(\$3,726.00)		
				6	Oct 1, 2020	SYSTEM	\$3,726.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user gardb1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	
				7	Oct 19, 2020	SYSTEM	(\$3,726.00)		
				7	Oct 19, 2020	SYSTEM	\$3,726.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user gardb1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	
				8	Nov 2, 2020	SYSTEM	(\$3,726.00)		
						OVOTEN	¢0.700.00	This address of a first the address of a sector of Oceaning Decision to	
				8	Nov 2, 2020	SYSTEM	\$3,726.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user gardb1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0780	Material - Total		Type				\$0.00	
0780 -							\$0.00	
0790	MISC. CURB AND GUTTER, TYPE B, SPECIAL	Material		3	Aug 14, 2020	SYSTEM	(\$6,656.00)	
				3	Aug 14, 2020	SYSTEM	\$6,656.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user gardb1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
				4	Sep 3, 2020	SYSTEM	(\$6,656.00)	
				4	Sep 3, 2020	SYSTEM	\$6,656.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0050) due to user gardb1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
				5	Sep 16, 2020	SYSTEM	(\$6,656.00)	
				5	Sep 16, 2020	SYSTEM	\$6,656.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user gardb1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
				6	Oct 1, 2020	SYSTEM	(\$6,656.00)	
				6	Oct 1, 2020	SYSTEM	\$6,656.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user gardb1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				7	Oct 19, 2020	SYSTEM	(\$6,656.00)	
				7	Oct 19, 2020	SYSTEM	\$6,656.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user gardb1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
			8	Nov 2, 2020	SYSTEM	(\$6,656.00)		
				8	Nov 2, 2020	SYSTEM	\$6,656.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user gardb1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0790 -							\$0.00	
0890	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L	Material		5	Sep 16, 2020	SYSTEM	(\$25.76)	
	BEADS			5	Sep 16, 2020	SYSTEM	\$25.76	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user gardb1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0890 -							\$0.00	
0900	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P	Material		5	Sep 16, 2020	SYSTEM	(\$327.96)	
	BEADS			5	Sep 16, 2020	SYSTEM	\$327.96	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user gardb1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Other Item Adjustment	REFL	6	Oct 1, 2020	gardb1	\$32.79	Edge line of Bus. Rte. 61
			REFL - Tota	ıl			\$32.79	
	Other Item Adjustment - Total						\$32.79	
0900 -							\$32.79	
0910	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P	Material		5	Sep 16, 2020	SYSTEM	(\$342.18)	
	BEADS			5	Sep 16, 2020	SYSTEM	\$342.18	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user gardb1 overridding Payment
								Estimate Exception 28 on the current Payment Estimate.
			- Total				\$0.00	Estimate Exception 28 on the current Payment Estimate.



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0910	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Other Item Adjustment	REFL	6	Oct 1, 2020	gardb1	\$34.22	Centerline of Bus. Rte. 61
			REFL - Tota	I			\$34.22	
	Other Item Adjustment - Total						\$34.22	
0910 -	Total						\$34.22	
0940	MISC. SEEDING AND MULCHING	Material		3	Aug 14, 2020	SYSTEM	(\$912.05)	
				3	Aug 14, 2020	SYSTEM	\$912.05	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user gardb1 overridding Payment Estimate Exception 53 on the current Payment Estimate.
				4	Sep 3, 2020	SYSTEM	(\$2,280.13)	
			- Total				(\$2,280.13)	
	Material - Total						(\$2,280.13)	
	MISC. SEEDING AND MULCHING	MaterialCredit		5	Sep 16, 2020	SYSTEM	\$2,280.13	
			- Total				\$2,280.13	
	MaterialCredit - Total						\$2,280.13	
0940 -	Total						\$0.00	
Overa	III - Total						\$144.39	