

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 11, 2021

Final Estimate Number 14	Contract ID Prime Contractor	200320-C02 Cale Seymour Construction	•	August 1, 2021	Original Contract Amount Net Change Order Amount Current Contract Amount	it (\$125.71)	
						· · ·	

Approval Date		By User
November 12, 2021	Generated and Approved (and should be considered Draft) at the Project Office Level by	rileyr1
December 7, 2021	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	holdtc
December 7, 2021	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
December 1, 2020	March 16, 2021	February 5, 2021	100.00%

	Contract Informational Dat	es	Milestones
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract
Acceptance Date	November 15, 2021	November 15, 2021	
Awarded Date	April 1, 2020	April 1, 2020	
Letting Date	March 20, 2020	March 20, 2020	
Notice to Proceed Date	May 4, 2020	May 4, 2020	
Open to Traffic Date	February 5, 2021	February 5, 2021	
Work Began Date	October 30, 2020	October 30, 2020	

Contract Total Pay For Estima	te No. 14				
		This Estimate	Previous	To Date	
200320-C02					
Total Po	sted Items Pay	\$0.00	\$140,598.38	\$140,598.38	
Gross It	em Adjustments	\$0.00	(\$12.16)	(\$12.16)	
Incentive	e	\$0.00	\$0.00	\$0.00	
Disincer	ntive	\$0.00	\$0.00	\$0.00	
Liquidat	ed Damage	\$0.00	\$0.00	\$0.00	
Other C	ontract Adjustments	\$0.00	\$0.00	\$0.00	
			\$140,586.22	\$140,586.22	
Contract Total Payable This Es	stimate:	\$0.00			

Items Paid This Estimate Period

No Data Available

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

No Data Available

Revision 4/1/2020 Page 1 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Information					
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work				
J3S3106	FAS S301(75)	-									
J7S3403	FAS S603(14)	ADA improvements	В	BENTON	from Jefferson Street to 0.03 miles north of Valley Street in Cole Camp						
Γotals by .	Job Numbe	rs									
J3S3106		d Item Pay Item Adjustme		Item Pay	This Estimate \$0.00 \$0.00 \$0.00	Previous \$102,104.73 \$0.36 \$102,105.09	To Date \$102,104.73 \$0.36 \$102,105.09				
	Liquid	tive centive lated Damages Contract Adjus	tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00				
J7S3403		d Item Pay Item Adjustme		Item Pay	This Estimate \$0.00 \$0.00 \$0.00	Previous \$38,493.65 (\$12.52) \$38,481.13	To Date \$38,493,65 (\$12.52) \$38,481.13				
	Liquid	tive centive lated Damages Contract Adjus	tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00				

Revision 4/1/2020 Page 2 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period No Exceptions Exist on Contract

Revision 4/1/2020 Page 3 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated

Contract lm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repo generated date)
00320-C02	J3S3106	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS		\$1,500.00	\$1,500.0
		0001	0020	2071000	LINEAR GRADING CLASS 1	23.00	0.30	23.30	STA	23.30	\$296.00	\$6,896.8
		0001	0030	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	19.00	-3.00	16.00	SQYD	16.00	\$9.52	\$152.3
		0001	0040	6081010	CONCRETE CURB RAMP	163.00	2.00	165.00	SQYD	165.00	\$132.23	\$21,817.9
		0001	0050	6081012	TRUNCATED DOMES	240.00	0.00	240.00	SQFT	240.00	\$22.00	\$5,280.0
		0001	0060	6085008	PAVED APPROACH, 8 IN.	19.10	-3.10	16.00	SQYD	16.00	\$93.32	\$1,493.1
		0001	0070	6086004	CONCRETE SIDEWALK, 4 IN.	1,073.00	3.00	1,076.00	SQYD	1,076.00	\$45.00	\$48,420.0
		0001	0080	6086007	CONCRETE SIDEWALK, 7 IN.	17.00	0.00	17.00	SQYD	17.00	\$65.98	\$1,121.6
		0001	0090	6086008	CONCRETE SIDEWALK, 8 IN.	34.00	0.00	34.00	SQYD	34.00	\$65.98	\$2,243.
		0001	0100	6091011	CONCRETE CURB (OVER 6 IN. HEIGHT) TYPE S	18.00	0.00	18.00	LF	18.00	\$36.00	\$648.
		0001	0110	6161005	CONSTRUCTION SIGNS	188.00	0.00	188.00	SQFT	188.00	\$8.00	\$1,504.
		0001	0120	6161009	FLAG ASSEMBLY	3.00	0.00	3.00	EA	3.00	\$30.00	\$90.
		0001	0130	6161025	CHANNELIZER (TRIM LINE)	40.00	0.00	40.00	EA	40.00	\$45.00	\$1,800.
		0001	0140	6169902	MISC.ADA COMPLIANT MOVEABLE BARRICADE	4.00	0.00	4.00	EA	4.00	\$175.00	\$700
		0001	0150	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$5,700.00	\$5,700
		0001	0160	8051000A	SEEDING - COOL SEASON MIXTURES	0.40	0.00	0.40	ACRE	0.40	\$3,500.00	\$1,400
		0001	0170	8061007A	CURB INLET CHECK	7.00	0.00	7.00	EA	7.00	\$135.00	\$945
		0001	0180	8061016	SEDIMENT REMOVAL	7.00	-7.00	0.00	CUYD	0.00	\$29.24	\$0
		0040	0190	9031270A	2 IN. PSST POST - 12 GA.	21.00	0.00	21.00	LF	21.00	\$10.08	\$211
		0040	0200	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	3.00	0.00	3.00	LF	3.00	\$42.38	\$127
		0040	0210	9031273	POST ANCHOR FOR 2 IN. PSST - 7 GA.	3.00	0.00	3.00	LF	3.00	\$17.91	\$53
					ate as of Report Generated Date	4.00	0.00	4.00	1.0	4.00	04 500 00	\$102,104
	J7S3403	0001	0220	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00		\$1,500
		0001	0230	2071000	LINEAR GRADING CLASS 1	0.30	0.00	0.30	STA	0.30	\$296.00	\$88
				2079903		000 00				000.00	&F F0	04.40
		0001	0240		MISC.LINEAR GRADING FOR ADA FACILITIES	269.00	0.00	269.00	LF	269.00	\$5.56	
		0001	0250	3040143	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	151.00	0.00	151.00	SQYD	151.00	\$6.61	\$998
		0001	0250	3040143 5021108	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) CONCRETE PAVEMENT (8 IN. NON-REINF)	151.00 29.30	0.00	151.00 29.30	SQYD	151.00 29.30	\$6.61 \$126.00	\$1,49£ \$99£ \$3,691
		0001 0001 0001	0250 0260 0270	3040143 5021108 6049904	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) CONCRETE PAVEMENT (8 IN. NON-REINF) MISC.STEEL PLATE	151.00 29.30 13.00	0.00	151.00 29.30 13.00	SQYD SQYD SQFT	151.00 29.30 13.00	\$6.61 \$126.00 \$410.00	\$998 \$3,691 \$5,330
		0001 0001 0001 0001	0250 0260 0270 0280	3040143 5021108 6049904 6081012	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) CONCRETE PAVEMENT (8 IN. NON-REINF) MISC.STEEL PLATE TRUNCATED DOMES	151.00 29.30 13.00 30.00	0.00 0.00 0.00	151.00 29.30 13.00 30.00	SQYD SQYD SQFT SQFT	151.00 29.30 13.00 30.00	\$6.61 \$126.00 \$410.00 \$22.00	\$998 \$3,69 \$5,330 \$660
		0001 0001 0001	0250 0260 0270 0280 0290	3040143 5021108 6049904 6081012 6086004	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) CONCRETE PAVEMENT (8 IN. NON-REINF) MISC.STEEL PLATE TRUNCATED DOMES CONCRETE SIDEWALK, 4 IN.	151.00 29.30 13.00 30.00 106.50	0.00 0.00 0.00 0.00	151.00 29.30 13.00 30.00 106.50	SQYD SQYD SQFT SQFT SQYD	151.00 29.30 13.00 30.00 106.50	\$6.61 \$126.00 \$410.00 \$22.00 \$45.00	\$998 \$3,69 \$5,330 \$660 \$4,792
		0001 0001 0001 0001	0250 0260 0270 0280	3040143 5021108 6049904 6081012	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) CONCRETE PAVEMENT (8 IN. NON-REINF) MISC.STEEL PLATE TRUNCATED DOMES CONCRETE SIDEWALK, 4 IN. CONCRETE SIDEWALK, 8 IN.	151.00 29.30 13.00 30.00	0.00 0.00 0.00	151.00 29.30 13.00 30.00	SQYD SQYD SQFT SQFT	151.00 29.30 13.00 30.00	\$6.61 \$126.00 \$410.00 \$22.00	\$998 \$3,69 \$5,330 \$660 \$4,792
		0001 0001 0001 0001 0001	0250 0260 0270 0280 0290	3040143 5021108 6049904 6081012 6086004	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) CONCRETE PAVEMENT (8 IN. NON-REINF) MISC.STEEL PLATE TRUNCATED DOMES CONCRETE SIDEWALK, 4 IN.	151.00 29.30 13.00 30.00 106.50	0.00 0.00 0.00 0.00	151.00 29.30 13.00 30.00 106.50	SQYD SQYD SQFT SQFT SQYD	151.00 29.30 13.00 30.00 106.50	\$6.61 \$126.00 \$410.00 \$22.00 \$45.00	\$998 \$3,69° \$5,330° \$660° \$4,792° \$911° \$500°
		0001 0001 0001 0001 0001 0001	0250 0260 0270 0280 0290 0300	3040143 5021108 6049904 6081012 6086004 6086008 6099903	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) CONCRETE PAVEMENT (8 IN. NON-REINF) MISC.STEEL PLATE TRUNCATED DOMES CONCRETE SIDEWALK, 4 IN. CONCRETE SIDEWALK, 8 IN.	151.00 29.30 13.00 30.00 106.50	0.00 0.00 0.00 0.00 0.00	151.00 29.30 13.00 30.00 106.50	SQYD SQYD SQFT SQFT SQYD SQYD	151.00 29.30 13.00 30.00 106.50 13.90	\$6.61 \$126.00 \$410.00 \$22.00 \$45.00 \$65.99	\$998 \$3,69° \$5,330° \$660° \$4,792° \$911° \$500°
		0001 0001 0001 0001 0001 0001	0250 0260 0270 0280 0290 0300	3040143 5021108 6049904 6081012 6086004 6086008 6099903	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) CONCRETE PAVEMENT (8 IN. NON-REINF) MISC.STEEL PLATE TRUNCATED DOMES CONCRETE SIDEWALK, 4 IN. CONCRETE SIDEWALK, 8 IN. MISC.MODIFIED TYPE A GUTTER	151.00 29.30 13.00 30.00 106.50 13.90 5.00	0.00 0.00 0.00 0.00 0.00 0.00	151.00 29.30 13.00 30.00 106.50 13.90 5.00	SQYD SQYD SQFT SQFT SQYD SQYD	151.00 29.30 13.00 30.00 106.50 13.90	\$6.61 \$126.00 \$410.00 \$22.00 \$45.00 \$65.99	\$991 \$3,69 \$5,33(\$660 \$4,79; \$91' \$500
		0001 0001 0001 0001 0001 0001 0001	0250 0260 0270 0280 0290 0300 0310	3040143 5021108 6049904 6081012 6086004 6086008 6099903 6123000A	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) CONCRETE PAVEMENT (8 IN. NON-REINF) MISC.STEEL PLATE TRUNCATED DOMES CONCRETE SIDEWALK, 4 IN. CONCRETE SIDEWALK, 8 IN. MISC.MODIFIED TYPE A GUTTER TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	151.00 29.30 13.00 30.00 106.50 13.90 5.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00	151.00 29.30 13.00 30.00 106.50 13.90 5.00	SQYD SQYD SQFT SQFT SQYD SQYD LF EA	151.00 29.30 13.00 30.00 106.50 13.90 5.00	\$6.61 \$126.00 \$410.00 \$22.00 \$45.00 \$65.99 \$100.00	\$998 \$3,69 \$5,336 \$666 \$4,793 \$917 \$500 \$5,000 \$1,966
		0001 0001 0001 0001 0001 0001 0001 000	0250 0260 0270 0280 0290 0300 0310 0320	3040143 5021108 6049904 6081012 6086004 6086008 6099903 6123000A 6161005	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) CONCRETE PAVEMENT (8 IN. NON-REINF) MISC.STEEL PLATE TRUNCATED DOMES CONCRETE SIDEWALK, 4 IN. CONCRETE SIDEWALK, 8 IN. MISC.MODIFIED TYPE A GUTTER TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) CONSTRUCTION SIGNS	151.00 29.30 13.00 30.00 106.50 13.90 5.00 1.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	151.00 29.30 13.00 30.00 106.50 13.90 5.00 1.00	SQYD SQYD SQFT SQFT SQYD LF EA SQFT	151.00 29.30 13.00 30.00 106.50 13.90 5.00 1.00	\$6.61 \$126.00 \$410.00 \$22.00 \$45.00 \$65.99 \$100.00 \$5,000.00	\$990 \$3,69 \$5,330 \$660 \$4,79: \$91' \$500 \$5,000 \$1,960
		0001 0001 0001 0001 0001 0001 0001 000	0250 0260 0270 0280 0290 0300 0310 0320 0330	3040143 5021108 6049904 6081012 6086004 6086008 6099903 6123000A 6161005 6161008	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) CONCRETE PAVEMENT (8 IN. NON-REINF) MISC.STEEL PLATE TRUNCATED DOMES CONCRETE SIDEWALK, 4 IN. CONCRETE SIDEWALK, 8 IN. MISC.MODIFIED TYPE A GUTTER TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) CONSTRUCTION SIGNS ADVANCED WARNING RAIL SYSTEM	151.00 29.30 13.00 30.00 106.50 13.90 5.00 1.00 246.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	151.00 29.30 13.00 30.00 106.50 13.90 5.00 1.00 246.00	SQYD SQYT SQFT SQYD SQYD LF EA SQFT	151.00 29.30 13.00 30.00 106.50 13.90 5.00 1.00 246.00	\$6.61 \$126.00 \$410.00 \$22.00 \$45.00 \$65.99 \$100.00 \$5,000.00	\$991 \$3,69 \$5,33(\$66(\$4,79; \$91; \$500 \$5,00(\$1,96(\$4,79;
		0001 0001 0001 0001 0001 0001 0001 000	0250 0260 0270 0280 0290 0300 0310 0320 0330 0340 0350	3040143 5021108 6049904 6081012 6086004 6086008 6099903 6123000A 6161005 6161008	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) CONCRETE PAVEMENT (8 IN. NON-REINF) MISC.STEEL PLATE TRUNCATED DOMES CONCRETE SIDEWALK, 4 IN. CONCRETE SIDEWALK, 8 IN. MISC.MODIFIED TYPE A GUTTER TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) CONSTRUCTION SIGNS ADVANCED WARNING RAIL SYSTEM FLAG ASSEMBLY	151.00 29.30 13.00 30.00 106.50 13.90 5.00 1.00 246.00 2.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	151.00 29.30 13.00 30.00 106.50 13.90 5.00 1.00 246.00 2.00	SQYD SQYD SQFT SQFT SQYD SQYD LF EA SQFT EA	151.00 29.30 13.00 30.00 106.50 13.90 5.00 1.00 246.00 2.00	\$6.61 \$126.00 \$410.00 \$22.00 \$45.00 \$65.99 \$100.00 \$5,000.00 \$60.00 \$30.00	\$990 \$3,69 \$5,330 \$660 \$4,790 \$910 \$500 \$1,960 \$120 \$60 \$1,800
		0001 0001 0001 0001 0001 0001 0001 000	0250 0260 0270 0280 0290 0300 0310 0320 0330 0340 0350	3040143 5021108 6049904 6081012 6086004 6086008 6099903 6123000A 6161005 6161008 6161009	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) CONCRETE PAVEMENT (8 IN. NON-REINF) MISC.STEEL PLATE TRUNCATED DOMES CONCRETE SIDEWALK, 4 IN. CONCRETE SIDEWALK, 8 IN. MISC.MODIFIED TYPE A GUTTER TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) CONSTRUCTION SIGNS ADVANCED WARNING RAIL SYSTEM FLAG ASSEMBLY CHANNELIZER (TRIM LINE)	151.00 29.30 13.00 30.00 106.50 13.90 5.00 1.00 246.00 2.00 40.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	151.00 29.30 13.00 30.00 106.50 13.90 5.00 1.00 246.00 2.00 40.00	SQYD SQYD SQFT SQFT SQYD SQYD LF EA SQFT EA EA	151.00 29.30 13.00 30.00 106.50 13.90 5.00 1.00 246.00 2.00 40.00	\$6.61 \$126.00 \$410.00 \$22.00 \$45.00 \$65.99 \$100.00 \$5,000.00 \$8.00 \$60.00 \$30.00	\$998 \$3,69* \$5,33(\$660 \$4,792 \$917 \$500 \$1,966 \$1,226
		0001 0001 0001 0001 0001 0001 0001 0001 0001 0001 0001	0250 0260 0270 0280 0290 0300 0310 0320 0330 0340 0350 0360	3040143 5021108 6049904 6081012 6086004 6086008 6099903 6123000A 6161005 6161008 6161009 6161025 6169902	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) CONCRETE PAVEMENT (8 IN. NON-REINF) MISC.STEEL PLATE TRUNCATED DOMES CONCRETE SIDEWALK, 4 IN. CONCRETE SIDEWALK, 8 IN. MISC.MODIFIED TYPE A GUTTER TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) CONSTRUCTION SIGNS ADVANCED WARNING RAIL SYSTEM FLAG ASSEMBLY CHANNELIZER (TRIM LINE) MISC.ADA COMPLIANT MOVEABLE BARRICADE	151.00 29.30 13.00 30.00 106.50 13.90 5.00 1.00 246.00 2.00 40.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00	151.00 29.30 13.00 30.00 106.50 13.90 5.00 1.00 246.00 2.00 40.00	SQYD SQYD SQFT SQFT SQYD SQYD LF EA SQFT EA EA EA	151.00 29.30 13.00 30.00 106.50 13.90 5.00 1.00 246.00 2.00 40.00	\$6.61 \$126.00 \$410.00 \$22.00 \$45.00 \$65.99 \$100.00 \$5,000.00 \$60.00 \$30.00 \$45.00	\$998 \$3,69* \$5,33(\$660 \$4,792 \$917 \$500 \$1,968 \$1,800 \$1,225 \$1,938
		0001 0001 0001 0001 0001 0001 0001 0001 0001 0001 0001 0001	0250 0260 0270 0280 0290 0300 0310 0320 0330 0340 0350 0360	3040143 5021108 6049904 6081012 6086004 6086008 6099903 6123000A 6161005 6161009 6161025 6169902 6181000 6274000	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) CONCRETE PAVEMENT (8 IN. NON-REINF) MISC.STEEL PLATE TRUNCATED DOMES CONCRETE SIDEWALK, 4 IN. CONCRETE SIDEWALK, 8 IN. MISC.MODIFIED TYPE A GUTTER TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) CONSTRUCTION SIGNS ADVANCED WARNING RAIL SYSTEM FLAG ASSEMBLY CHANNELIZER (TRIM LINE) MISC.ADA COMPLIANT MOVEABLE BARRICADE MOBILIZATION	151.00 29.30 13.00 30.00 106.50 13.90 5.00 1.00 246.00 2.00 40.00 7.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00	151.00 29.30 13.00 30.00 106.50 13.90 5.00 1.00 246.00 2.00 40.00 7.00	SQYD SQYD SQFT SQFT SQYD SQYD LF EA SQFT EA EA EA LS	151.00 29.30 13.00 30.00 106.50 13.90 5.00 1.00 246.00 2.00 40.00 7.00	\$6.61 \$126.00 \$410.00 \$22.00 \$45.00 \$65.99 \$100.00 \$5,000.00 \$80.00 \$30.00 \$45.00 \$175.00	\$990 \$3,69 \$5,330 \$660 \$4,790 \$500 \$1,960 \$120 \$60 \$1,800 \$1,220 \$1,930 \$940
		0001 0001 0001 0001 0001 0001 0001 000	0250 0260 0270 0280 0290 0300 0310 0320 0330 0340 0350 0360 0370 0380	3040143 5021108 6049904 6081012 6086004 6086008 6099903 6123000A 6161005 6161009 6161025 6169902 6181000 6274000	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) CONCRETE PAVEMENT (8 IN. NON-REINF) MISC.STEEL PLATE TRUNCATED DOMES CONCRETE SIDEWALK, 4 IN. CONCRETE SIDEWALK, 8 IN. MISC.MODIFIED TYPE A GUTTER TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) CONSTRUCTION SIGNS ADVANCED WARNING RAIL SYSTEM FLAG ASSEMBLY CHANNELIZER (TRIM LINE) MISC.ADA COMPLIANT MOVEABLE BARRICADE MOBILIZATION CONTRACTOR FURNISHED SURVEYING AND STAKING	151.00 29.30 13.00 30.00 106.50 13.90 5.00 1.00 246.00 2.00 40.00 7.00 1.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00	151.00 29.30 13.00 30.00 106.50 13.90 5.00 1.00 246.00 2.00 40.00 7.00 1.00	SQYD SQYD SQFT SQFT SQYD LF EA SQFT EA LS LS	151.00 29.30 13.00 30.00 106.50 13.90 5.00 246.00 2.00 40.00 7.00 1.00	\$6.61 \$126.00 \$410.00 \$22.00 \$45.00 \$65.99 \$100.00 \$5,000.00 \$8.00 \$60.00 \$175.00 \$1,935.00	\$998 \$3,69* \$5,33(\$660 \$4,792 \$917 \$500 \$1,966 \$1,800 \$1,229 \$1,932 \$1,229 \$1,729
		0001 0001 0001 0001 0001 0001 0001 000	0250 0260 0270 0280 0290 0300 0310 0320 0330 0340 0350 0360 0370 0380 0390	3040143 5021108 6049904 6081012 6086004 6086008 6099903 6123000A 6161005 6161009 6161025 6169902 6181000 6274000 8031000A	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) CONCRETE PAVEMENT (8 IN. NON-REINF) MISC.STEEL PLATE TRUNCATED DOMES CONCRETE SIDEWALK, 4 IN. CONCRETE SIDEWALK, 8 IN. MISC.MODIFIED TYPE A GUTTER TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) CONSTRUCTION SIGNS ADVANCED WARNING RAIL SYSTEM FLAG ASSEMBLY CHANNELIZER (TRIM LINE) MISC.ADA COMPLIANT MOVEABLE BARRICADE MOBILIZATION CONTRACTOR FURNISHED SURVEYING AND STAKING TURF TYPE TALL FESCUE SODDING	151.00 29.30 13.00 30.00 106.50 13.90 5.00 1.00 246.00 2.00 40.00 7.00 1.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00	151.00 29.30 13.00 30.00 106.50 13.90 5.00 1.00 246.00 2.00 40.00 7.00 1.00	SQYD SQYD SQFT SQFT SQYD LF EA SQFT EA LS LS SQYD	151.00 29.30 13.00 30.00 106.50 13.90 5.00 246.00 2.00 40.00 7.00 1.00	\$6.61 \$126.00 \$410.00 \$22.00 \$45.00 \$65.99 \$100.00 \$5,000.00 \$8.00 \$45.00 \$175.00 \$1,935.00	\$998
		0001 0001 0001 0001 0001 0001 0001 000	0250 0260 0270 0280 0290 0300 0310 0320 0330 0340 0350 0360 0370 0380 0390 0400	3040143 5021108 6049904 6081012 6086004 6086008 6099903 6123000A 6161005 6161009 6161025 6169902 6181000 6274000 8031000A 8061005	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) CONCRETE PAVEMENT (8 IN. NON-REINF) MISC.STEEL PLATE TRUNCATED DOMES CONCRETE SIDEWALK, 4 IN. CONCRETE SIDEWALK, 8 IN. MISC.MODIFIED TYPE A GUTTER TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) CONSTRUCTION SIGNS ADVANCED WARNING RAIL SYSTEM FLAG ASSEMBLY CHANNELIZER (TRIM LINE) MISC.ADA COMPLIANT MOVEABLE BARRICADE MOBILIZATION CONTRACTOR FURNISHED SURVEYING AND STAKING TURF TYPE TALL FESCUE SODDING ROCK DITCH CHECK	151.00 29.30 13.00 30.00 106.50 13.90 5.00 1.00 246.00 2.00 40.00 7.00 1.00 1.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	151.00 29.30 13.00 30.00 106.50 13.90 5.00 2.00 2.00 40.00 7.00 1.00 2.04.00	SQYD SQYD SQFT SQFT SQYD SQYD LF EA SQFT EA LS LS SQYD	151.00 29.30 13.00 30.00 106.50 13.90 5.00 246.00 2.00 40.00 7.00 1.00 204.00	\$6.61 \$126.00 \$410.00 \$22.00 \$45.00 \$65.99 \$100.00 \$5,000.00 \$8.00 \$60.00 \$175.00 \$1,935.00 \$940.00 \$8.48	\$998 \$3,691 \$5,330 \$660 \$4,792 \$917 \$500 \$1,968 \$1,205 \$1,225 \$1,938 \$940 \$1,725

Revision 4/1/2020 Page 4 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200320-C02	J7S3403	0040	0450	9031241	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE)	2.00	0.00	2.00	EA	2.00	\$250.00	\$500.00
		0040	0460	9031270A	2 IN. PSST POST - 12 GA.	32.00	0.00	32.00	LF	32.00	\$42.38	\$1,356.16
		0040	0470	9031273	POST ANCHOR FOR 2 IN. PSST - 7 GA.	6.00	0.00	6.00	LF	6.00	\$17.91	\$107.46
		0040	0480	9035004A	SH-FLAT SHEET	9.00	0.00	9.00	SQFT	9.00	\$30.00	\$270.00
		0040	0490	9039902	MISC.RELOCATE AND REMOUNT EXISTING SIGN ON NEW PSST	1.00	0.00	1.00	EA	1.00	\$555.00	\$555.00
	Project J	7S3403 - To	otal Value	Posted to E	Date as of Report Generated Date							\$38,493.65
200320-C02 Ove	rall - Total	Value Pos	ted to Da	te as of Rep	ort Generated Date							\$140,598.37

Revision 4/1/2020 Page 5 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 4/1/2020 Page 6 of 13

Dec 14, 2021



Line Item Adjustments by Estimate

ect	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
	210	2 000.194011	Туре	Adjustment Type	Number	Date	Ву	, and diff	. S. Harro
106	0030	TYPE 5 AGGREGATE FOR BASE	Price FUEL		6	Jan 15, 2021	SYSTEM	\$0.07	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
		TONBAGE		- Total				\$0.07	
			Price FUEL - 1	Γotal				\$0.07	
	0030 -	Total						\$0.07	
	0040	CONCRETE CURB RAMP	Material		3	Dec 1, 2020	SYSTEM	\$5,289.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user mothee overridding Payment Estimate Exception 8 on the current Payment Estimate.
					3	Dec 1, 2020	SYSTEM	(\$5,289.20)	
					4	Dec 15, 2020	SYSTEM	\$13,487.46	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user mothee overridding Payment Estimate Exception 6 on the current Payment Estimate.
					4	Dec 15, 2020	SYSTEM	(\$13,487.46)	
				- Total				\$0.00	
			Material - Tota	al				\$0.00	
	0040 -	Total						\$0.00	
	0060	PAVED APPROACH, 8 IN.	Material		6	Jan 15, 2021	SYSTEM	\$1,493.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user mothee overridding Payment Estimate Exception 8 on the current Payment Estimate.
		IN.			6	Jan 15, 2021	SYSTEM	(\$1,493.12)	
					7	Feb 1, 2021	SYSTEM	\$1,493.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user mothee overridding Payment Estimate Exception 8 on the current Payment Estimate.
					7	Feb 1, 2021	SYSTEM	(\$1,493.12)	
				- Total				\$0.00	
			Material - Tota	al				\$0.00	
			Price FUEL		6	Jan 15, 2021	SYSTEM	\$0.29	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$0.29	
			Price FUEL - 1	Γotal				\$0.29	
J	0060 -	Total						\$0.29	
	0070	CONCRETE SIDEWALK, 4 IN.	Material		2	Nov 16, 2020	SYSTEM	(\$3,915.00)	
					3	Dec 1, 2020	SYSTEM	\$21,285.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user mothee overridding Payment Estimate Exception 11 on the current Payment Estimate.
					3	Dec 1, 2020	SYSTEM	(\$21,285.00)	
				- Total				(\$3,915.00)	
			Material - Tota	ıl				(\$3,915.00)	
			MaterialCredit		3	Dec 1, 2020	SYSTEM	\$3,915.00	
				- Total				\$3,915.00	
			MaterialCredit	t - Total				\$3,915.00	
	0070 -							\$0.00	
	0800	CONCRETE SIDEWALK, 7 IN.	Material		2	Nov 16, 2020	SYSTEM	(\$442.07)	
					3	Dec 1, 2020	SYSTEM	\$442.07	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user mothee overridding Payment Estimate Exception 14 on the current Payment Estimate.
					3	Dec 1, 2020	SYSTEM	(\$442.07)	
				- Total				(\$442.07)	
			Material - Tota	al				(\$442.07)	
			MaterialCredit		3	Dec 1,	SYSTEM	\$442.07	
						2020			



MoDOT

Line Item Adjustments by Estimate

	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J3S3106	0080	CONCRETE SIDEWALK, 7 IN.	MaterialCredit	- Total				\$442.07		
		SIDEWALK, 7 IIV.	MaterialCredit	- Total				\$442.07		
	0080 -	· Total						\$0.00		
	0090	CONCRETE SIDEWALK, 8 IN.	Material		3	Dec 1, 2020	SYSTEM	\$1,860.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user mothee overridding Payment Estimate Exception 16 on the current Payment Estimate.	
					3	Dec 1, 2020	SYSTEM	(\$1,860.64)		
					4	Dec 15, 2020	SYSTEM	\$1,860.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user mothee overridding Payment Estimate Exception 7 on the current Payment Estimate.	
						4	Dec 15, 2020	SYSTEM	(\$1,860.64)	
					5	Jan 4, 2021	SYSTEM	\$2,243.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mothee overridding Payment Estimate Exception 8 on the current Payment Estimate.	
					5	Jan 4, 2021	SYSTEM	(\$2,243.32)		
					6	Jan 15, 2021	SYSTEM	\$2,243.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mothee overridding Payment Estimate Exception 9 on the current Payment Estimate.	
					6	Jan 15, 2021	SYSTEM	(\$2,243.32)		
					7	Feb 1, 2021	SYSTEM	\$2,243.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user mothee overridding Payment Estimate Exception 9 on the current Payment Estimate.	
					7	Feb 1, 2021	SYSTEM	(\$2,243.32)		
				2021			\$0.00			
			Material - Tota	ıl				\$0.00		
	0090 -	· Total						\$0.00		
	0100	CONCRETE CURB (OVER 6 IN. HEIGHT)	Material	Material						
	0100	CURB (OVER 6 IN. HEIGHT)	Material		6	Jan 15, 2021	SYSTEM	\$648.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user mothee overridding Payment Estimate Exception 10 on the current Payment Estimate.	
	0100	CURB (OVER 6	Material		6		SYSTEM	\$648.00 (\$648.00)	Estimate Item Adjustment (0005) due to user mothee overridding Payment	
	0100	CURB (OVER 6 IN. HEIGHT)	Material			2021 Jan 15,			Estimate Item Adjustment (0005) due to user mothee overridding Payment	
	0100	CURB (OVER 6 IN. HEIGHT)	Material		6	2021 Jan 15, 2021 Feb 1,	SYSTEM	(\$648.00)	Estimate Item Adjustment (0005) due to user mothee overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mothee overridding Payment	
	0100	CURB (OVER 6 IN. HEIGHT)	Material	- Total	6	2021 Jan 15, 2021 Feb 1, 2021	SYSTEM	(\$648.00) \$648.00	Estimate Item Adjustment (0005) due to user mothee overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mothee overridding Payment	
	0100	CURB (OVER 6 IN. HEIGHT)	Material Material - Tota		6	2021 Jan 15, 2021 Feb 1, 2021	SYSTEM	(\$648.00) \$648.00 (\$648.00)	Estimate Item Adjustment (0005) due to user mothee overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mothee overridding Payment	
		CURB (OVER 6 IN. HEIGHT)			6	2021 Jan 15, 2021 Feb 1, 2021	SYSTEM	(\$648.00) \$648.00 (\$648.00) \$0.00	Estimate Item Adjustment (0005) due to user mothee overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mothee overridding Payment	
		CURB (OVER 6 IN. HEIGHT) TYPE S			6	2021 Jan 15, 2021 Feb 1, 2021	SYSTEM	(\$648.00) \$648.00 (\$648.00) \$0.00	Estimate Item Adjustment (0005) due to user mothee overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mothee overridding Payment	
	0100 -	CURB (OVER 6 IN. HEIGHT) TYPE S Total SEEDING - COOL SEASON	Material - Tota		6 7 7	2021 Jan 15, 2021 Feb 1, 2021 Feb 1, 2021	SYSTEM SYSTEM SYSTEM	(\$648.00) \$648.00 (\$648.00) \$0.00 \$0.00	Estimate Item Adjustment (0005) due to user mothee overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mothee overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user mothee overridding Payment	
	0100 -	CURB (OVER 6 IN. HEIGHT) TYPE S Total SEEDING - COOL SEASON	Material - Tota		6 7 7	2021 Jan 15, 2021 Feb 1, 2021 Feb 1, 2021 Jan 15, 2021 Jan 15, 2021	SYSTEM SYSTEM SYSTEM	(\$648.00) \$648.00 (\$648.00) \$0.00 \$0.00 \$1,400.00	Estimate Item Adjustment (0005) due to user mothee overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mothee overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user mothee overridding Payment	
	0100 -	CURB (OVER 6 IN. HEIGHT) TYPE S Total SEEDING - COOL SEASON	Material - Tota		6 7 7	2021 Jan 15, 2021 Feb 1, 2021 Feb 1, 2021 Jan 15, 2021 Jan 15, 2021 Jan 15, 2021 Feb 1, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	(\$648.00) \$648.00 (\$648.00) \$0.00 \$0.00 \$1,400.00	Estimate Item Adjustment (0005) due to user mothee overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mothee overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user mothee overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mothee overridding Payment Estimate Item Adjustment (0004) due to user mothee overridding Payment	
	0100 -	CURB (OVER 6 IN. HEIGHT) TYPE S Total SEEDING - COOL SEASON	Material - Tota		6 7 7 8 6 6 7	Jan 15, 2021 Feb 1, 2021 Jan 15, 2021 Jan 15, 2021 Jan 15, 2021 Feb 1, 2021 Feb 1, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$648.00) \$648.00 (\$648.00) \$0.00 \$0.00 \$1,400.00 (\$1,400.00)	Estimate Item Adjustment (0005) due to user mothee overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mothee overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user mothee overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mothee overridding Payment Estimate Item Adjustment (0004) due to user mothee overridding Payment	
	0100 -	CURB (OVER 6 IN. HEIGHT) TYPE S Total SEEDING - COOL SEASON	Material - Tota		6 7 7 7 6 6 7	Jan 15, 2021 Feb 1, 2021 Jan 15, 2021 Feb 1, 2021 Jan 15, 2021 Jan 15, 2021 Feb 1, 2021 Feb 1, 2021 Feb 1, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$648.00) \$648.00 (\$648.00) \$0.00 \$0.00 \$1,400.00 (\$1,400.00) (\$1,400.00)	Estimate Item Adjustment (0005) due to user mothee overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mothee overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user mothee overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mothee overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 12 on the current Payment Estimate.	
	0100 -	CURB (OVER 6 IN. HEIGHT) TYPE S Total SEEDING - COOL SEASON	Material - Tota		6 7 7 6 6 7 7 8	Jan 15, 2021 Feb 1, 2021 Jan 15, 2021 Feb 1, 2021 Jan 15, 2021 Jan 15, 2021 Feb 1, 2021 Feb 1, 2021 Feb 1, 2021 Feb 1, 2021 Feb 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$648.00) \$648.00 (\$648.00) \$0.00 \$0.00 \$1,400.00 (\$1,400.00) \$1,400.00 (\$1,400.00)	Estimate Item Adjustment (0005) due to user mothee overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mothee overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user mothee overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mothee overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 12 on the current Payment Estimate.	





Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks									
J3S3106	0160	SEEDING - COOL SEASON MIXTURES	Material		10	Mar 15, 2021	SYSTEM	\$1,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mothee overridding Payment Estimate Exception 8 on the current Payment Estimate.									
					10	Mar 15, 2021	SYSTEM	(\$1,400.00)										
					11	Apr 2, 2021	SYSTEM	\$1,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mothee overridding Payment Estimate Exception 4 on the current Payment Estimate.									
					11	Apr 2, 2021	SYSTEM	(\$1,400.00)										
					12	Apr 16, 2021	SYSTEM	\$1,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mothee overridding Payment Estimate Exception 4 on the current Payment Estimate.									
					12	Apr 16, 2021	SYSTEM	(\$1,400.00)										
					13	May 3, 2021	SYSTEM	\$1,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mothee overridding Payment Estimate Exception 3 on the current Payment Estimate.									
					13	May 3, 2021	SYSTEM	(\$1,400.00)										
				- Total		2021		\$0.00										
			Material - Tota	ı				\$0.00										
	0160 -	Total						\$0.00										
J3S3106 -	Total							\$0.36										
J7S3403	0250	TYPE 1 AGGREGATE FOR BASE (4 IN.	Material		2	Nov 16, 2020	SYSTEM	\$998.11	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user mothee overridding Payment Estimate Exception 1 on the current Payment Estimate.									
		тніск)			2	Nov 16, 2020	SYSTEM	(\$998.11)										
				- Total				\$0.00										
			Material - Tota	ıl				\$0.00										
			Price FUEL		2	Nov 16, 2020	SYSTEM	(\$7.25)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL									
				- Total				(\$7.25)										
			Price FUEL - 1	otal				(\$7.25)										
	0250 -	Total						(\$7.25)										
	0260	CONCRETE PAVEMENT (8 IN. NON-REINF)	Material		3	Dec 1, 2020	SYSTEM	\$3,691.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user mothee overridding Payment Estimate Exception 2 on the current Payment Estimate.									
					3	Dec 1, 2020	SYSTEM	(\$3,691.80)										
					4	Dec 15, 2020	SYSTEM	\$3,691.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user mothee overridding Payment Estimate Exception 1 on the current Payment Estimate.									
					4	Dec 15, 2020	SYSTEM	(\$3,691.80)										
									5	Jan 4, 2021	SYSTEM	\$3,691.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mothee overridding Payment Estimate Exception 3 on the current Payment Estimate.					
					5	Jan 4, 2021	SYSTEM	(\$3,691.80)										
														6 Jan 15, SYSTEM \$3,691.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user mothee overridding Payment Estimate Exception 3 on the current Payment Estimate.			
					6	Jan 15, 2021	SYSTEM	(\$3,691.80)										
			7											7	Feb 1, 2021	SYSTEM	\$3,691.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user mothee overridding Payment Estimate Exception 3 on the current Payment Estimate.
				-	7	Feb 1, 2021	SYSTEM	(\$3,691.80)										
					8	Feb 16, 2021	SYSTEM	\$3,691.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mothee overridding Payment Estimate Exception 3 on the current Payment Estimate.									



MoDOT

Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J7S3403	0260	CONCRETE PAVEMENT (8	Material	,	8	Feb 16, 2021	SYSTEM	(\$3,691.80)	
		IN. NON-REINF)			9	Mar 1, 2021	SYSTEM	\$3,691.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mothee overridding Payment Estimate Exception 3 on the current Payment Estimate.
					9	Mar 1, 2021	SYSTEM	(\$3,691.80)	
					10	Mar 15, 2021	SYSTEM	\$3,691.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mothee overridding Payment Estimate Exception 3 on the current Payment Estimate.
					10	Mar 15, 2021	SYSTEM	(\$3,691.80)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
			Price FUEL		3	Dec 1, 2020	SYSTEM	(\$5.27)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				(\$5.27)	
			Price FUEL - T	otal				(\$5.27)	
	0260 -	Total	7110010EE 10tal						
	0280	TRUNCATED DOMES	Material		2	Nov 16, 2020	SYSTEM	(\$5.27) (\$660.00)	
				- Total				(\$660.00)	
			Material - Tota					(\$660.00)	
			MaterialCredit		3	Dec 1,	SYSTEM	\$660.00	
						2020			
				- Total				\$660.00	
			MaterialCredit	- Total				\$660.00	
	0280 -	Total						\$0.00	
	0290	CONCRETE SIDEWALK, 4 IN.			3	Dec 1, 2020	SYSTEM	\$4,792.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user mothee overridding Payment Estimate Exception 13 on the current Payment Estimate.
					3	Dec 1, 2020	SYSTEM	(\$4,792.50)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0290 -	Total							
	0300	CONCRETE SIDEWALK, 8 IN.	Material		3	Dec 1, 2020	SYSTEM	\$917.26	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user mothee overridding Payment Estimate Exception 15 on the current Payment Estimate.
					3	Dec 1, 2020	SYSTEM	(\$917.26)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0300 -	Total						\$0.00	
	0320	TRUCK OR TRAILER MOUNTED	Material		7	Feb 1, 2021	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user mothee overridding Payment Estimate Exception 11 on the current Payment Estimate.
		ATTEN (TMA)			7	Feb 1, 2021	SYSTEM	(\$5,000.00)	
					8	Feb 16, 2021	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user mothee overridding Payment Estimate Exception 7 on the current Payment Estimate.
					8	Feb 16, 2021	SYSTEM	(\$5,000.00)	
					9	Mar 1, 2021	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user mothee overridding Payment Estimate Exception 7 on the current Payment Estimate.
					9	Mar 1, 2021	SYSTEM	(\$5,000.00)	
					10	Mar 15, 2021	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user mothee overridding Payment Estimate Exception 7 on the current Payment Estimate.

Dec 14, 2021



Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J7S3403	0320	TRUCK OR TRAILER MOUNTED ATTEN (TMA)	Material		10	Mar 15, 2021	SYSTEM	(\$5,000.00)	
					11	Apr 2, 2021	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user mothee overridding Payment Estimate Exception 3 on the current Payment Estimate.
					11	Apr 2, 2021	SYSTEM	(\$5,000.00)	
					12	Apr 16, 2021	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user mothee overridding Payment Estimate Exception 3 on the current Payment Estimate.
					12	Apr 16, 2021	SYSTEM	(\$5,000.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0320 -	Total						\$0.00	
	0330	CONSTRUCTION SIGNS	Material		1	Nov 2, 2020	SYSTEM	(\$1,008.00)	
				- Total				(\$1,008.00)	
			Material - Tota	ı				(\$1,008.00)	
			MaterialCredit		2	Nov 16, 2020	SYSTEM	\$1,008.00	
				- Total				\$1,008.00	
			MaterialCredit	- Total				\$1,008.00	
	0330 -	Total						\$0.00	
	0340	ADVANCED WARNING RAIL SYSTEM	Material		1	Nov 2, 2020	SYSTEM	(\$120.00)	
				- Total				(\$120.00)	
			Material - Tota	ı				(\$120.00)	
			MaterialCredit		2	Nov 16, 2020	SYSTEM	\$120.00	
				- Total				\$120.00	
	0040	MaterialCredit - Total						\$120.00	
	0340 -	FLAG ASSEMBLY	Material		1	Nov 2, 2020	SYSTEM	\$0.00 (\$60.00)	
				- Total				(\$60.00)	
			Material - Tota					(\$60.00)	
			MaterialCredit		2	Nov 16, 2020	SYSTEM	\$60.00	
				- Total				\$60.00	
			MaterialCredit	- Total				\$60.00	
	0350 -	- Total						\$0.00	
	0360	CHANNELIZER (TRIM LINE)	Material		1	Nov 2, 2020	SYSTEM	(\$675.00)	
				- Total				(\$675.00)	
			Material - Tota	rial - Total				(\$675.00)	
			MaterialCredit		2	Nov 16, 2020	SYSTEM	\$675.00	
				- Total				\$675.00	
			MaterialCredit - Total					\$675.00	
	0360 -	Total						\$0.00	
	0430	SILT FENCE	Material		2	Nov 16, 2020	SYSTEM	(\$540.00)	
				- Total				(\$540.00)	
			Material - Tota	ı				(\$540.00)	
			MaterialCredit		3	Dec 1, 2020	SYSTEM	\$540.00	



MoDOT

Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J7S3403	0430	SILT FENCE	MaterialCredit	erialCredit - Total					
			MaterialCredit - Total					\$540.00	
	0430 -	· Total						\$0.00	
	0440	CONCRETE FOOTINGS, EMBEDDED	Material		5	Jan 4, 2021	SYSTEM	\$290.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user mothee overridding Payment Estimate Exception 9 on the current Payment Estimate.
					5	Jan 4, 2021	SYSTEM	(\$290.00)	
					6	Jan 15, 2021	SYSTEM	\$290.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user mothee overridding Payment Estimate Exception 15 on the current Payment Estimate.
					6	Jan 15, 2021	SYSTEM	(\$290.00)	
					7	Feb 1, 2021	SYSTEM	\$290.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user mothee overridding Payment Estimate Exception 13 on the current Payment Estimate.
					7	Feb 1, 2021	SYSTEM	(\$290.00)	
					8	Feb 16, 2021	SYSTEM	\$290.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user mothee overridding Payment Estimate Exception 9 on the current Payment Estimate.
					8	Feb 16, 2021	SYSTEM	(\$290.00)	
					9	Mar 1, 2021	SYSTEM	\$290.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user mothee overridding Payment Estimate Exception 9 on the current Payment Estimate.
					9	Mar 1, 2021	SYSTEM	(\$290.00)	
					10	Mar 15, 2021	SYSTEM	\$290.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user mothee overridding Payment Estimate Exception 9 on the current Payment Estimate.
					10	Mar 15, 2021	SYSTEM	(\$290.00)	
				- Total				\$0.00	
			Material - Tota	ı				\$0.00	
	0440 -	· Total						\$0.00	
	0480	SH-FLAT SHEET	Material		5	Jan 4, 2021	SYSTEM	\$270.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user mothee overridding Payment Estimate Exception 10 on the current Payment Estimate.
					5	Jan 4, 2021	SYSTEM	(\$270.00)	
					6	Jan 15, 2021	SYSTEM	\$270.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user mothee overridding Payment Estimate Exception 16 on the current Payment Estimate.
					6	Jan 15, 2021	SYSTEM	(\$270.00)	
					7	Feb 1, 2021	SYSTEM	\$270.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user mothee overridding Payment Estimate Exception 14 on the current Payment Estimate.
					7	Feb 1, 2021	SYSTEM	(\$270.00)	
					8	Feb 16, 2021	SYSTEM	\$270.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user mothee overridding Payment Estimate Exception 10 on the current Payment Estimate.
					8	Feb 16, 2021	SYSTEM	(\$270.00)	
					9	Mar 1, 2021	SYSTEM	\$270.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user mothee overridding Payment Estimate Exception 10 on the current Payment Estimate.
					9	Mar 1, 2021	SYSTEM	(\$270.00)	
					10	Mar 15, 2021	SYSTEM	\$270.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user mothee overridding Payment Estimate Exception 10 on the current Payment Estimate.
					10	Mar 15,	SYSTEM	(\$270.00)	

Dec 14, 2021



Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J7S3403	0480	SH-FLAT SHEET	Material			2021			
					11	Apr 2, 2021	SYSTEM	\$270.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user mothee overridding Payment Estimate Exception 6 on the current Payment Estimate.
					11	Apr 2, 2021	SYSTEM	(\$270.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
0480 - Total									
J7S3403 -	Total							(\$12.52)	
Overall - Total								(\$12.16)	