

### Pay Estimate Created Date: January 15, 2021

Progress Estima 6	ate Number	Contract ID 200320-C02 Prime Contractor Cale Seymou	Pay Period Start Janu r Construction Pay Period End Janu		unt \$0.00						
Approval Date					By User						
January 15, 2021	Generated and Approved (and should be considered Draft) at the Project Office Level by										
January 15, 2021		Reviewed and Ap	proved (and should be considered Dra	ft) at the Resident Engineer Level by	rileyr1						
January 20, 2021			Reviewed and Approved at the Cent	tral Office Controllers Office Level by	greggd1						
Original Comp	letion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete							
December	December 1, 2020 94.78%										

No Milestones Exist for Contract

Contract Total	Pay For Estir	nate No. 6					
			This Estimate	Previou	IS	To Date	
200320-C02	Gross Incen Disino Liquic	Posted Items s Item Adjustr tive centive dated Damage Contract Adj	ments <b>\$0.36</b> \$0.00 \$0.00 e \$0.00	\$122,0 (\$12.52 \$0.00 \$0.00 \$0.00 \$0.00 \$122,00	2)	\$133,380.: (\$12.16) \$0.00 \$0.00 \$0.00 \$0.00 \$133,368.0	
Contract Total	Payable This	Estimate:	\$11,305.52	<b>,</b> , .		<b>,</b> ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
ems Paid This	Estimate Per	iod					
Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J3S3106	0010	2022010	REMOVAL OF IMPROVEMENTS	LS	\$1,500.000	0.1	\$150.00
	0020	2071000	LINEAR GRADING CLASS 1	STA	\$296.000	0.3	\$88.80
	0030	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	SQYD	\$9.520	16	\$152.32
	0040	6081010	CONCRETE CURB RAMP	SQYD	\$132.230	19	\$2,512.37
	0050	6081012	TRUNCATED DOMES	SQFT	\$22.000	30	\$660.00
	0060	6085008	PAVED APPROACH, 8 IN.	SQYD	\$93.320	16	\$1,493.12
	0070	6086004	CONCRETE SIDEWALK, 4 IN.	SQYD	\$45.000	20	\$900.00
	0100	6091011	CONCRETE CURB (OVER 6 IN. HEIGHT) TYPE S	LF	\$36.000	18	\$648.00
	0160	8051000A	SEEDING - COOL SEASON MIXTURES	ACRE	\$3,500.000	0.4	\$1,400.00
	0190	9031270A	2 IN. PSST POST - 12 GA.	LF	\$10.080	21	\$211.68
	0200	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	LF	\$42.380	3	\$127.14
	0210	9031273	POST ANCHOR FOR 2 IN. PSST - 7 GA.	LF	\$17.910	3	\$53.73
Project J3S31	06 - Total						\$8,397.16
J7S3403	0330	6161005	CONSTRUCTION SIGNS	SQFT	\$8.000	120	\$960.00
	0360	6161025	CHANNELIZER (TRIM LINE)	EA	\$45.000	25	\$1,125.00
	0370	6169902	MISC.ADA COMPLIANT MOVEABLE BARRICADE	EA	\$175.000	4	\$700.00
	0430	8061019	SILT FENCE	LF	\$3.000	41	\$123.00
Project J7S34	03 - Total						\$2,908.00
Overall - Tota							\$11,305.16

Line Item Adjustments This Estimate



### Pay Estimate Created Date: January 15, 2021

Progre	ess Esti (	mate Number S	Contract ID Prime Contra	200320 actor Cale Se		Pay Period Start January 2, 2021 Orig ruction Pay Period End January 15, 2021 Net Cur		er Amount \$	0.00
Project Number	Line No.	Item Des	scription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustmen amount
J3S3106	0030		REGATE FOR (4 IN. THICK)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	16	\$0.00	\$0.07
	0060	PAVED APP	PROACH, 8 IN.	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	16	\$0.02	\$0.29
	0060	PAVED APP	ROACH, 8 IN.	Material			-16	\$93.32	(\$1,493.12)
	0060	PAVED APF	PROACH, 8 IN.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user mothee overridding Payment Estimate Exception 8 on the current Payment Estimate.	16	\$93.32	\$1,493.12
	0090	CONCRETE	SIDEWALK, 8 IN.	Material			-34	\$65.98	(\$2,243.32)
	0090	CONCRETE	SIDEWALK, 8 IN.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user mothee overridding Payment Estimate Exception 9 on the current Payment Estimate.	34	\$65.98	\$2,243.32
	0100	CONCRETE C IN. HE	URB (OVER 6 IGHT) TYPE S	Material			-18	\$36.00	(\$648.00)
	0100	CONCRETE C IN. HE	URB (OVER 6 IGHT) TYPE S	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user mothee overridding Payment Estimate Exception 10 on the current Payment Estimate.	18	\$36.00	\$648.00
	0160	SEEDING - C	OOL SEASON MIXTURES	Material			-0.4	\$3,500.00	(\$1,400.00)
	0160	SEEDING - C	OOL SEASON MIXTURES	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user mothee overridding Payment Estimate Exception 11 on the current Payment Estimate.	0.4	\$3,500.00	\$1,400.00
J7S3403	0260		AVEMENT(8 . NON-REINF)	Material			-29.3	\$126.00	(\$3,691.80)
	0260			Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user mothee overridding Payment Estimate Exception 3 on the current Payment Estimate.	29.3	\$126.00	\$3,691.80
	0440	CONCRET	E FOOTINGS, EMBEDDED	Material			-0.2	\$1,450.00	(\$290.00)
	0440	CONCRET	E FOOTINGS, EMBEDDED	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user mothee overridding Payment Estimate Exception 15 on the current Payment Estimate.	0.2	\$1,450.00	\$290.00
	0480	SH	-FLAT SHEET	Material			-9	\$30.00	(\$270.00)
	0480	SH	SH-FLAT SHEET       Material       This adjustment offsets the original syste         generated Material Payment Estimate Ite       Adjustment (0009) due to user moth         overridding Payment Estimate Exception       on the current Payment Estimate				9	\$30.00	\$270.00
Total									\$0.36



## Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

	Contract Project Information												
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work								
J3S3106		ADA improvements	765	PETTIS	om Morgan Street to Pacific Street								
J7S3403		ADA improvements	В	BENTON	from Jefferson Street to 0.03 miles north of Valley Street in Cole Camp								

### Totals by Job Numbers

06	This Estimate	Previous	To Date
Posted Item Pay	\$8,397.16	\$93,219.31	\$101,616.47
Gross Item Adjustments	\$0.36	\$0.00	\$0.36
Gross Item Pay	\$8,397.52	\$93,219.31	\$101,616.83
Incentive	\$0.00	\$0.00	\$0.00
Disincentive	\$0.00	\$0.00	\$0.00
Liquidated Damages	\$0.00	\$0.00	\$0.00
Other Contract Adjustments	\$0.00	\$0.00	\$0.00
13	This Estimate	Previous	To Date
Posted Item Pay	\$2,908.00	\$28,855.73	\$31,763.73
Gross Item Adjustments	\$0.00	(\$12.52)	(\$12.52)
Gross Item Pay	\$2,908.00	\$28,843.21	\$31,751.21
		\$0.00	\$0.00
Incentive	\$0.00		
Disincentive	\$0.00	\$0.00	\$0.00



## Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

### Exceptions (Discrepancies) This Estimate Period

	1		
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J7S3403, Item 3040143, Project Item Line Number 0250, Material Set 304014396, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Working with KC District Materials to resolve	mothee	Overridden
Estimate Exception Type: Insufficient Materials: Project J7S3403, Item 3040143, Project Item Line Number 0250, Material Set 304014396, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient.	Working with KC District Materials to resolve	mothee	Overridden
Estimate Exception Type: Insufficient Materials: Project J7S3403, Item 5021108, Project Item Line Number 0260, Material Set 502110896, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Working with KC District Materials to resolve	mothee	Overridden
Estimate Exception Type: Insufficient Materials: Project J7S3403, Item 5021108, Project Item Line Number 0260, Material Set 502110896, Material 1057JMDAEC4.11 - Dowel Assemblies Epoxy Ctd Gr40 1 1/4" @, Acceptance Action Generic ReinforcingMisc is insufficient.	Working with KC District Materials to resolve	mothee	Overridden
Estimate Exception Type: Insufficient Materials: Project J7S3403, Item 5021108, Project Item Line Number 0260, Material Set 502110896, Material 1057JMDAEC6.11 - Dowel Assemblies Epoxy Ctd Gr60 1 1/4" @, Acceptance Action Generic ReinforcingMisc is insufficient.	Working with KC District Materials to resolve	mothee	Overridden
Estimate Exception Type: Insufficient Materials: Project J7S3403, Item 5021108, Project Item Line Number 0260, Material Set 502110896, Material 1057JMTBE28016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 40/M280@, Acceptance Action Generic ReinforcingMisc is insufficient.	Working with KC District Materials to resolve	mothee	Overridden
Estimate Exception Type: Insufficient Materials: Project J3S3106, Item 6081010, Project Item Line Number 0040, Material Set 608101096, Material 1055CMMLT1D - Clear Pavement Cure (non-dissipating) @, Acceptance Action Generic 1055CMMLT1D is insufficient.	All required tests have been performed. Waiting on cylinder break information to be entered into AASHTOWARE	mothee	Overridden
Estimate Exception Type: Insufficient Materials: Project J3S3106, Item 6085008, Project Item Line Number 0060, Material Set 608500896, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	All required tests have been performed. Waiting on cylinder break information to be entered into AASHTOWARE	mothee	Overridden
Estimate Exception Type: Insufficient Materials: Project J3S3106, Item 6086008, Project Item Line Number 0090, Material Set 608600896, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	All required tests have been performed. Waiting on cylinder break information to be entered into AASHTOWARE	mothee	Overridden
Estimate Exception Type: Insufficient Materials: Project J3S3106, Item 6091011, Project Item Line Number 0100, Material Set 609101196, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	All required tests have been performed. Waiting on cylinder break information to be entered into AASHTOWARE	mothee	Overridden
Estimate Exception Type: Insufficient Materials: Project J3S3106, Item 8051000A, Project Item Line Number 0160, Material Set 8051000A96, Material 0805SD - Grass Seed -Seed, Acceptance Action Generic 0805SD is insufficient.	Certifications have been sent to KC District Materials	mothee	Overridden
Estimate Exception Type: Insufficient Materials: Project J3S3106, Item 8051000A, Project Item Line Number 0160, Material Set 8051000A96, Material 0802MLST - Mulch Straw (Vegetative Mulch), Acceptance Action Generic 0802MLST is insufficient.	Certifications have been sent to KC District Materials	mothee	Overridden
Estimate Exception Type: Insufficient Materials: Project J3S3106, Item 8051000A, Project Item Line Number 0160, Material Set 8051000A96, Material 0801FZ - Fertilizer, Acceptance Action Generic 0801FZ is insufficient.	Certifications have been sent to KC District Materials	mothee	Overridden
Estimate Exception Type: Insufficient Materials: Project J3S3106, Item 8051000A, Project Item Line Number 0160, Material Set 8051000A96, Material 0801AG - Agricultural Lime -Effective Nuetralizer, Acceptance Action Generic 0801AG is insufficient.	Certifications have been sent to KC District Materials	mothee	Overridden
Estimate Exception Type: Insufficient Materials: Project J7S3403, Item 9031010, Project Item Line Number 0440, Material Set 903101096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Working with KC District Materials to resolve	mothee	Overridden
Estimate Exception Type: Insufficient Materials: Project J7S3403, Item 9035004A, Project Item Line Number 0480, Material Set 9035004A96, Material 1042SM - Sign Material, Acceptance Action Generic 1042SM is insufficient.	Need certifications entered into AASHTOWARE	mothee	Overridden

### Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

### Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Q	uantities	and Valu	es are b	ased on R	eport Generated date and can differ from the posted am	ount at th	e time the	e Estimate v	vas Gen	erated.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200320-C02	J3S3106	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$1,500.00	\$1,500.00
		0001	0020	2071000	LINEAR GRADING CLASS 1	23.00	0.00	23.00	STA	23.00	\$296.00	\$6,808.00
		0001	0030	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	19.00	0.00	19.00	SQYD	16.00	\$9.52	\$152.32
		0001	0040	6081010	CONCRETE CURB RAMP	163.00	0.00	163.00	SQYD	163.00	\$132.23	\$21,553.49
		0001	0050	6081012	TRUNCATED DOMES	240.00	0.00	240.00	SQFT	240.00	\$22.00	\$5,280.00
		0001	0060	6085008	PAVED APPROACH, 8 IN.	19.10	0.00	19.10	SQYD	16.00	\$93.32	\$1,493.12
		0001	0070	6086004	CONCRETE SIDEWALK, 4 IN.	1,073.00	0.00	1,073.00	SQYD	1,073.00	\$45.00	\$48,285.00
		0001	0080	6086007 6086008	CONCRETE SIDEWALK, 7 IN. CONCRETE SIDEWALK, 8 IN.	17.00 34.00	0.00	34.00	SQYD SQYD	17.00 34.00	\$65.98	\$1,121.66
		0001	0100	6091011	CONCRETE SIDEWALK, 6 IN. CONCRETE CURB (OVER 6 IN. HEIGHT) TYPE S	18.00	0.00	18.00	LF	18.00	\$05.96	\$2,243.32
		0001	0110	6161005	CONSTRUCTION SIGNS	188.00	0.00	188.00	SQFT	188.00	\$30.00	\$048.00
		0001	0120	6161009	FLAG ASSEMBLY	3.00	0.00	3.00	EA	3.00	\$30.00	\$90.00
		0001	0130	6161025	CHANNELIZER (TRIM LINE)	40.00	0.00	40.00	EA	40.00	\$45.00	\$1,800.00
		0001	0140	6169902	MISC.ADA COMPLIANT MOVEABLE BARRICADE	4.00	0.00	4.00	EA	4.00	\$175.00	\$700.00
		0001	0150	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$5,700.00	\$5,700.00
		0001	0160	8051000A	SEEDING - COOL SEASON MIXTURES	0.40	0.00	0.40	ACRE	0.40	\$3,500.00	\$1,400.00
		0001	0170	8061007A	CURB INLET CHECK	7.00	0.00	7.00	EA	7.00	\$135.00	\$945.00
		0001	0180	8061016	SEDIMENT REMOVAL	7.00	0.00		CUYD	0.00	\$29.24	\$0.00
		0040	0190	9031270A	2 IN. PSST POST - 12 GA.	21.00	0.00	21.00	LF	21.00	\$10.08	\$211.68
		0040	0200	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	3.00	0.00	3.00	LF	3.00	\$42.38	\$127.14
		0040	0210	9031273	POST ANCHOR FOR 2 IN. PSST - 7 GA.	3.00	0.00	3.00	LF	3.00	\$17.91	\$53.73
	Project J	3S3106 - To	otal Value	Posted to D	Date as of Report Generated Date							\$101,616.46
	J7S3403	0001	0220	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$1,500.00	\$1,500.00
		0001	0230	2071000	LINEAR GRADING CLASS 1	0.30	0.00	0.30	STA	0.30	\$296.00	\$88.80
		0001	0240	2079903	MISC.LINEAR GRADING FOR ADA FACILITIES	269.00	0.00	269.00	LF	269.00	\$5.56	\$1,495.64
		0001	0250	3040143	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	151.00	0.00	151.00	SQYD	151.00	\$6.61	\$998.11
		0001	0260	5021108	CONCRETE PAVEMENT ( 8 IN. NON-REINF)	29.30	0.00	29.30	SQYD	29.30	\$126.00	\$3,691.80
		0001	0270	6049904	MISC.STEEL PLATE	13.00	0.00	13.00	SQFT	13.00	\$410.00	\$5,330.00
		0001	0280	6081012	TRUNCATED DOMES	30.00	0.00	30.00	SQFT	30.00	\$22.00	\$660.00
		0001	0290	6086004	CONCRETE SIDEWALK, 4 IN.	106.50	0.00	106.50	SQYD	106.50	\$45.00	\$4,792.50
		0001	0300	6086008	CONCRETE SIDEWALK, 8 IN.	13.90	0.00	13.90	SQYD	13.90	\$65.99	\$917.26
		0001	0310	6099903	MISC.MODIFIED TYPE A GUTTER	5.00	0.00	5.00	LF	5.00	\$100.00	\$500.00
		0001	0320	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	1.00	0.00	1.00	EA	0.00	\$5,000.00	\$0.00
		0001	0330	6161005 6161008		246.00	0.00	246.00	SQFT	246.00	\$8.00	\$1,968.00
		0001			ADVANCED WARNING RAIL SYSTEM	2.00	0.00	2.00	EA	2.00	\$60.00	\$120.00
		0001				2.00	0.00	2.00	E۸	2.00	\$30.00	00.032
		0001	0350	6161009	FLAG ASSEMBLY	2.00	0.00	2.00	EA	2.00	\$30.00	\$60.00
		0001	0350 0360	6161009 6161025	CHANNELIZER (TRIM LINE)	40.00	0.00	40.00	EA	40.00	\$45.00	\$1,800.00
		0001 0001	0350	6161009								
		0001	0350 0360 0370	6161009 6161025 6169902	CHANNELIZER (TRIM LINE) MISC.ADA COMPLIANT MOVEABLE BARRICADE	40.00	0.00	40.00	EA EA	40.00	\$45.00 \$175.00	\$1,800.00 \$1,225.00
		0001 0001 0001	0350 0360 0370 0380	6161009 6161025 6169902 6181000	CHANNELIZER (TRIM LINE) MISC.ADA COMPLIANT MOVEABLE BARRICADE MOBILIZATION	40.00 7.00 1.00	0.00 0.00 0.00	40.00 7.00 1.00	EA EA LS	40.00 7.00 1.00	\$45.00 \$175.00 \$1,935.00	\$1,800.00 \$1,225.00 \$1,935.00
		0001 0001 0001 0001	0350 0360 0370 0380 0390	6161009 6161025 6169902 6181000 6274000	CHANNELIZER (TRIM LINE) MISC.ADA COMPLIANT MOVEABLE BARRICADE MOBILIZATION CONTRACTOR FURNISHED SURVEYING AND STAKING	40.00 7.00 1.00 1.00	0.00 0.00 0.00 0.00	40.00 7.00 1.00 1.00	EA EA LS LS	40.00 7.00 1.00 1.00	\$45.00 \$175.00 \$1,935.00 \$940.00	\$1,800.00 \$1,225.00 \$1,935.00 \$940.00
		0001 0001 0001 0001 0001	0350 0360 0370 0380 0390 0400	6161009 6161025 6169902 6181000 6274000 8031000A	CHANNELIZER (TRIM LINE) MISC.ADA COMPLIANT MOVEABLE BARRICADE MOBILIZATION CONTRACTOR FURNISHED SURVEYING AND STAKING TURF TYPE TALL FESCUE SODDING	40.00 7.00 1.00 1.00 142.00	0.00 0.00 0.00 0.00 0.00	40.00 7.00 1.00 1.00 142.00	EA EA LS LS SQYD	40.00 7.00 1.00 1.00 0.00	\$45.00 \$175.00 \$1,935.00 \$940.00 \$8.48	\$1,800.00 \$1,225.00 \$1,935.00 \$940.00 \$0.00
		0001 0001 0001 0001 0001 0001	0350 0360 0370 0380 0390 0400 0410	6161009 6161025 6169902 6181000 6274000 8031000A 8061005	CHANNELIZER (TRIM LINE) MISC.ADA COMPLIANT MOVEABLE BARRICADE MOBILIZATION CONTRACTOR FURNISHED SURVEYING AND STAKING TURF TYPE TALL FESCUE SODDING ROCK DITCH CHECK	40.00 7.00 1.00 1.00 142.00 20.00	0.00 0.00 0.00 0.00 0.00 0.00	40.00 7.00 1.00 1.00 142.00 20.00	EA EA LS SQYD LF	40.00 7.00 1.00 1.00 0.00 0.00	\$45.00 \$175.00 \$1,935.00 \$940.00 \$8.48 \$13.50	\$1,800.00 \$1,225.00 \$1,935.00 \$940.00 \$0.00 \$0.00
		0001 0001 0001 0001 0001 0001	0350 0360 0370 0380 0390 0400 0410 0420	6161009 6161025 6169902 6181000 6274000 8031000A 8061005 8061016	CHANNELIZER (TRIM LINE) MISC.ADA COMPLIANT MOVEABLE BARRICADE MOBILIZATION CONTRACTOR FURNISHED SURVEYING AND STAKING TURF TYPE TALL FESCUE SODDING ROCK DITCH CHECK SEDIMENT REMOVAL	40.00 7.00 1.00 1.00 142.00 20.00 5.00	0.00 0.00 0.00 0.00 0.00 0.00	40.00 7.00 1.00 142.00 20.00 5.00	EA EA LS SQYD LF CUYD	40.00 7.00 1.00 0.00 0.00 0.00 221.00	\$45.00 \$175.00 \$1,935.00 \$940.00 \$8.48 \$13.50 \$29.24	\$1,800.00 \$1,225.00 \$1,935.00 \$940.00 \$0.00 \$0.00 \$0.00

### Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

### Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based	on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200320-C02	J7S3403	0040	0450	9031241	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE)	2.00	0.00	2.00	EA	2.00	\$250.00	\$500.00
		0040	0460	9031270A	2 IN. PSST POST - 12 GA.	32.00	0.00	32.00	LF	32.00	\$42.38	\$1,356.16
		0040	0470	9031273	POST ANCHOR FOR 2 IN. PSST - 7 GA.	6.00	0.00	6.00	LF	6.00	\$17.91	\$107.46
		0040	0480	9035004A	SH-FLAT SHEET	9.00	0.00	9.00	SQFT	9.00	\$30.00	\$270.00
		0040	0490	9039902	MISC.RELOCATE AND REMOUNT EXISTING SIGN ON NEW PSST	1.00	0.00	1.00	EA	1.00	\$555.00	\$555.00
	Project J	7S3403 - To	tal Value	Posted to D	Date as of Report Generated Date							\$31,763.73
200320-C02 Ove	rall - Total	Value Post	ed to Dat	te as of Repo	ort Generated Date							\$133,380.19



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J3S3106

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0010	2022010	REMOVAL OF IMPROVEMENTS	1/7/21	1/8/21	0.10	LS	100% of Contract					
0020	2071000	LINEAR GRADING CLASS 1	1/7/21	1/8/21	-0.30	STA		848+88 Rt				Will pay +0.3 overrun after change Order is approved.
				1/8/21	0.20	STA	Commercial Entrance	848+88 Rt				
				1/8/21	0.40	STA	836+33 to 836+49 Rt - 0.2 847+71 to 847+84 Rt - 0.1 847+84 to 847+91 Rt - 0.1					
0030	3040504	TYPE 5 AGGREGATE FOR BASE	1/7/21	1/8/21	16.00	SQYD	Commercial Entrance	848+88 Rt				
0040	6081010	CONCRETE CURB RAMP	1/7/21	1/8/21	-2.00	SQYD	Will pay +2 overrun after change order is approved.					
				1/8/21	21.00	SQYD	836+33 to 836+49 Rt - 9 847+71 to 847+84 Rt - 12					
0050	6081012	TRUNCATED DOMES	1/7/21	1/8/21	30.00	SQFT	836+33 to 836+49 Rt - 20 847+71 to 847+84 Rt - 10					
0060	6085008	PAVED APPROACH, 8 IN.	1/8/21	1/8/21	16.00	SQYD	Commercial Entrance	848+74 Rt		849+03 Rt		
0070	6086004	CONCRETE SIDEWALK, 4 IN.	1/7/21	1/8/21	11.00	SQYD	836+34 to 836+39 Rt - 3 847+84 to 847+91 Rt - 8					
			1/8/21	1/8/21	9.00	SQYD	848+71 to 848+81 Rt - 5 848+95 to 849+03 Rt - 5 Will pay overrun after change order is approved					
0100	6091011	CONCRETE CURB (OVER 6 IN. HEIGHT) TYPE S	1/7/21	1/8/21	18.00	LF	847+71 to 847+91 Rt SW Quad at Jefferson					
0160	8051000A	SEEDING - COOL SEASON MIXTURES	1/15/21	1/15/21	0.40	ACRE	Throughout project					
0190	9031270A	2 IN. PSST POST - 12 GA.	1/7/21	1/8/21	21.00	LF	836+47 Lt - 10.5 847+74 Rt - 10.5					
0200	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	1/7/21	1/8/21	3.00	LF		836+47 Lt				
0210	9031273	POST ANCHOR FOR 2 IN. PSST - 7 GA.	1/7/21	1/8/21	3.00	LF		847+74 Rt				

#### Project: J7S3403

Line Number	ltem Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0330	6161005	CONSTRUCTION SIGNS	1/14/21	1/14/21	120.00	SQFT	Throughout Project	4+77	12' Rt.	7+23	12' Lt.	
0360	6161025	CHANNELIZER (TRIM LINE)	1/14/21	1/14/21	25.00	EA	Throughout Project	4+77	10' Rt.	7+23	10' Rt.	
0370	6169902	MISC. TRAFFIC CONTROL DEVICES	1/14/21	1/14/21	4.00	EA	Around Existing and New Sidewalk	4+23	15' Rt.	6+84	15' Rt.	
0430	8061019	SILT FENCE	1/14/21	1/14/21	41.00	LF	Removal of Sidewalk on East Side	6+98	18' Lt.	7+23	18' Lt.	

The information below this line are details for Construction Signs (if applicable). No Data Available



				_	-	-		
Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0030	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Price		6	Jan 15, 2021	SYSTEM	\$0.07	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
		- Total				\$0.07		
	Price - Total						\$0.07	
0030 -	Total						\$0.07	
0040	CONCRETE CURB RAMP	Material		3	Dec 1,	SYSTEM	(\$5,289.20)	
				3	2020 Dec 1, 2020	SYSTEM	\$5,289.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user mothee overridding Payment Estimate Exception 8 on
				4	Dec 15,	SYSTEM	(\$13,487.46)	the current Payment Estimate.
				4	2020 Dec 15,	SYSTEM	\$13,487.46	This adjustment offsets the original system-generated Overrun Payment Estimate Item
			Total		2020		\$0.00	Adjustment (0001) due to user mothee overridding Payment Estimate Exception 6 on the current Payment Estimate.
	- Total							
0040	Material - Total						\$0.00	
0040 -		Material		C	les 45	OVOTEN	\$0.00	
0060	PAVED APPROACH, 8 IN.	Material		6	Jan 15, 2021	SYSTEM	(\$1,493.12)	
				6	Jan 15, 2021	SYSTEM	\$1,493.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user mothee overridding Payment Estimate Exception 8 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	PAVED APPROACH, 8 IN.	Price		6	Jan 15, 2021	SYSTEM	\$0.29	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
	- Total						\$0.29	
	Price - Total						\$0.29	
0060 -	Total						\$0.29	
0070	CONCRETE SIDEWALK, 4 IN.	Material		2	Nov 16, 2020	SYSTEM	(\$3,915.00)	
				3	Dec 1, 2020	SYSTEM		
				3	Dec 1, 2020	SYSTEM	\$21,285.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user mothee overridding Payment Estimate Exception 11 on the current Payment Estimate.
			- Total				(\$3,915.00)	
	Material - Total						(\$3,915.00)	
	CONCRETE SIDEWALK, 4 IN.	MaterialCredit		3	Dec 1, 2020	SYSTEM	\$3,915.00	
			- Total				\$3,915.00	
	MaterialCredit - Total						\$3,915.00	
0070 -							\$0.00	
0080	CONCRETE SIDEWALK, 7 IN.	Material		2	Nov 16, 2020	SYSTEM	(\$442.07)	
				3	Dec 1, 2020	SYSTEM	(\$442.07)	
				3	Dec 1, 2020	SYSTEM	\$442.07	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user mothee overridding Payment Estimate Exception 14 on the current Payment Estimate.
	- Total						(\$442.07)	
	Material - Total						(\$442.07)	
	CONCRETE SIDEWALK, 7 IN.	MaterialCredit		3	Dec 1, 2020	SYSTEM	\$442.07	
			- Total				\$442.07	
	MaterialCredit - Total						\$442.07	
0080 -	Total						\$0.00	
0090	CONCRETE SIDEWALK, 8 IN.	Material		3	Dec 1, 2020	SYSTEM	(\$1,860.64)	



Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
0090	CONCRETE		Туре	3	Dec 1,	SYSTEM	\$1,860.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item
0090	CONCRETE SIDEWALK, 8 IN.	Material		5	2020	STOTEM	φ1,000.04	Adjustment (0008) due to user mothee overridding Payment Estimate Exception 16 on the current Payment Estimate.
				4	Dec 15, 2020	SYSTEM	(\$1,860.64)	
				4	Dec 15, 2020	SYSTEM	\$1,860.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user mothee overridding Payment Estimate Exception 7 on the current Payment Estimate.
				5	Jan 4, 2021	SYSTEM	(\$2,243.32)	
				5	Jan 4, 2021	SYSTEM	\$2,243.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mothee overridding Payment Estimate Exception 8 on the current Payment Estimate.
				6	Jan 15, 2021	SYSTEM	(\$2,243.32)	
				6	Jan 15, 2021	SYSTEM	\$2,243.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mothee overridding Payment Estimate Exception 9 on the current Payment Estimate.
		- Total				\$0.00		
	Material - Total						\$0.00	
0090 -	Total						\$0.00	
0100	CONCRETE CURB (OVER 6 IN. HEIGHT) TYPE S	Material		6	Jan 15, 2021	SYSTEM	(\$648.00)	
				6	Jan 15, 2021	SYSTEM	\$648.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user mothee overridding Payment Estimate Exception 10 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0100 -							\$0.00	
0160	SEEDING - COOL SEASON MIXTURES	Material		6	Jan 15, 2021	SYSTEM	(\$1,400.00)	
				6	Jan 15, 2021	SYSTEM	\$1,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user mothee overridding Payment Estimate Exception 11 on the current Payment Estimate.
	- Total						\$0.00	
0400	Material - Total						\$0.00	
<b>0160</b> - 0250	TYPE 1	Material		2	Nov 16, 2020	SYSTEM	\$0.00 (\$998.11)	
	AGGREGATE FOR BASE (4 IN. THICK)			2	Nov 16, 2020	SYSTEM	\$998.11	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user mothee overridding Payment Estimate Exception 1 on the current Payment Estimate.
				- Total			\$0.00	
	Material - Total						\$0.00	
	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	Price		2	Nov 16, 2020	SYSTEM	(\$7.25)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			- Total	- Total			(\$7.25)	
	Price - Total						(\$7.25)	
0250 -							(\$7.25)	
0260	CONCRETE PAVEMENT ( 8 IN. NON-REINF)	Material		3	Dec 1, 2020	SYSTEM	(\$3,691.80)	
				3	Dec 1, 2020	SYSTEM	\$3,691.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user mothee overridding Payment Estimate Exception 2 on the current Payment Estimate.
				4	Dec 15, 2020	SYSTEM	(\$3,691.80)	
				4	Dec 15, 2020	SYSTEM	\$3,691.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user mothee overridding Payment Estimate Exception 1 on the current Payment Estimate.
				5	Jan 4, 2021	SYSTEM	(\$3,691.80)	
				5	Jan 4, 2021	SYSTEM	\$3,691.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mothee overridding Payment Estimate Exception 3 on



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
		Туре	Adjustment Type	Number	Date	Ву		
0260	CONCRETE PAVEMENT ( 8 IN.	Material						the current Payment Estimate.
	NON-REINF)			6	Jan 15, 2021	SYSTEM	(\$3,691.80)	
				6	Jan 15, 2021	SYSTEM	\$3,691.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user mothee overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	CONCRETE PAVEMENT ( 8 IN. NON-REINF)	Price		3	Dec 1, 2020	SYSTEM	(\$5.27)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			- Total				(\$5.27)	
	Price - Total						(\$5.27)	
0260 -	- Total						(\$5.27)	
0280	TRUNCATED DOMES	Material		2	Nov 16, 2020	SYSTEM	(\$660.00)	
			- Total				(\$660.00)	
	Material - Total						(\$660.00)	
	TRUNCATED DOMES	MaterialCredit		3	Dec 1, 2020	SYSTEM	\$660.00	
			- Total				\$660.00	
	MaterialCredit - Total						\$660.00	
0280 -	- Total						\$0.00	
0290	CONCRETE SIDEWALK, 4 IN.	Material		3	Dec 1, 2020	SYSTEM	(\$4,792.50)	
				3	Dec 1, 2020	SYSTEM	\$4,792.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user mothee overridding Payment Estimate Exception 13 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0290 -	- Total						\$0.00	
0300	CONCRETE M SIDEWALK, 8 IN.	Material		3	Dec 1, 2020	SYSTEM	(\$917.26)	
				3	Dec 1, 2020	SYSTEM	\$917.26	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user mothee overridding Payment Estimate Exception 15 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total		- Total				\$0.00 \$0.00	
0300 -			- Total					
0300 - 0330		Material		1	Nov 2, 2020	SYSTEM	\$0.00	
	- Total CONSTRUCTION	Material		1		SYSTEM	\$0.00 \$0.00	
	- Total CONSTRUCTION	Material		1		SYSTEM	\$0.00 \$0.00 (\$1,008.00)	
	Total CONSTRUCTION SIGNS		- Total	1		SYSTEM	\$0.00 \$0.00 (\$1,008.00) (\$1,008.00)	
	Total CONSTRUCTION SIGNS Material - Total CONSTRUCTION				2020 Nov 16,		\$0.00 \$0.00 (\$1,008.00) (\$1,008.00) (\$1,008.00)	
0330	Total CONSTRUCTION SIGNS Material - Total CONSTRUCTION SIGNS MaterialCredit - Total		- Total		2020 Nov 16,		\$0.00 \$0.00 (\$1,008.00) (\$1,008.00) (\$1,008.00) \$1,008.00	
0330	Total CONSTRUCTION SIGNS Material - Total CONSTRUCTION SIGNS		- Total		2020 Nov 16,		\$0.00 \$0.00 (\$1,008.00) (\$1,008.00) (\$1,008.00) \$1,008.00 \$1,008.00	
0330	Total CONSTRUCTION SIGNS Material - Total CONSTRUCTION SIGNS MaterialCredit - Total		- Total		2020 Nov 16,		\$0.00 \$0.00 (\$1,008.00) (\$1,008.00) \$1,008.00 \$1,008.00 \$1,008.00	
0330 0330 -	Total CONSTRUCTION SIGNS Material - Total CONSTRUCTION SIGNS MaterialCredit - Total Total ADVANCED WARNING RAIL	MaterialCredit	- Total	2	2020 Nov 16, 2020 Nov 2,	SYSTEM	\$0.00 \$0.00 (\$1,008.00) (\$1,008.00) (\$1,008.00 \$1,008.00 \$1,008.00 \$1,008.00	
0330 0330 -	Total CONSTRUCTION SIGNS Material - Total CONSTRUCTION SIGNS MaterialCredit - Total Total ADVANCED WARNING RAIL	MaterialCredit	- Total - Total	2	2020 Nov 16, 2020 Nov 2,	SYSTEM	\$0.00 \$0.00 (\$1,008.00) (\$1,008.00) \$1,008.00 \$1,008.00 \$1,008.00 \$1,008.00 (\$120.00)	
0330 0330 -	Total CONSTRUCTION SIGNS Material - Total CONSTRUCTION SIGNS MaterialCredit - Total Total ADVANCED WARNING RAIL SYSTEM Material - Total	MaterialCredit	- Total - Total	2	2020 Nov 16, 2020 Nov 2,	SYSTEM	\$0.00 \$0.00 (\$1,008.00) (\$1,008.00) \$1,008.00 \$1,008.00 \$1,008.00 \$1,008.00 (\$120.00) (\$120.00)	
0330 0330 -	Total CONSTRUCTION SIGNS Material - Total CONSTRUCTION SIGNS MaterialCredit - Total Total ADVANCED WARNING RAIL SYSTEM Material - Total ADVANCED	MaterialCredit	- Total - Total	2	2020 Nov 16, 2020 Nov 2, 2020	SYSTEM	\$0.00 \$0.00 (\$1,008.00) (\$1,008.00) \$1,008.00 \$1,008.00 \$1,008.00 (\$120.00) (\$120.00) (\$120.00) \$120.00	
0330 0330 -	Total CONSTRUCTION SIGNS Material - Total CONSTRUCTION SIGNS MaterialCredit - Total Total ADVANCED WARNING RAIL SYSTEM Material - Total	MaterialCredit	- Total - Total	2	2020 Nov 16, 2020 Nov 2, 2020	SYSTEM	\$0.00 \$0.00 (\$1,008.00) (\$1,008.00) \$1,008.00 \$1,008.00 \$1,008.00 \$1,008.00 (\$120.00) (\$120.00) (\$120.00)	



Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
0350	FLAG ASSEMBLY	Material	Туре	1	Nov 2,	SYSTEM	(\$60.00)	
0000	I EAG AGGEMIDET	Material			2020	OTOTEM	(\$00.00)	
			- Total				(\$60.00)	
	Material - Total						(\$60.00)	
	FLAG ASSEMBLY	MaterialCredit		2	Nov 16, 2020	SYSTEM	\$60.00	
			- Total				\$60.00	
	MaterialCredit - Total						\$60.00	
0350 -							\$0.00	
0360	CHANNELIZER (TRIM LINE)	Material		1	Nov 2, 2020	SYSTEM	(\$675.00)	
			- Total				(\$675.00)	
	Material - Total						(\$675.00)	
	CHANNELIZER (TRIM LINE)	MaterialCredit		2	Nov 16, 2020	SYSTEM	\$675.00	
			- Total				\$675.00	
	MaterialCredit - Total						\$675.00	
0360 - 0430	Total SILT FENCE	Material		2	Nov 16,	SYSTEM	\$0.00 (\$540.00)	
					2020			
			- Total				(\$540.00)	
	Material - Total						(\$540.00)	
	SILT FENCE	MaterialCredit		3	Dec 1, 2020	SYSTEM	\$540.00	
			- Total				\$540.00	
	MaterialCredit - Total						\$540.00	
0430 -							\$0.00	
0440	CONCRETE FOOTINGS, EMBEDDED	Material		5	Jan 4, 2021	SYSTEM	(\$290.00)	
				5	Jan 4, 2021	SYSTEM	\$290.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user mothee overridding Payment Estimate Exception 9 on the current Payment Estimate.
				6	Jan 15, 2021	SYSTEM	(\$290.00)	
				6	Jan 15, 2021	SYSTEM	\$290.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user mothee overridding Payment Estimate Exception 15 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0440 -							\$0.00	
0480	SH-FLAT SHEET	Material		5	Jan 4, 2021	SYSTEM	(\$270.00)	
				5	Jan 4, 2021	SYSTEM	\$270.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user mothee overridding Payment Estimate Exception 10 on the current Payment Estimate.
				6	Jan 15, 2021	SYSTEM	(\$270.00)	
				6	Jan 15, 2021	SYSTEM	\$270.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user mothee overridding Payment Estimate Exception 16 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0480 -	Total						\$0.00	
Overa	II - Total						(\$12.16)	