

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: June 16, 2020

Progress Estimate Number	Contract ID 200320-F06	Pay Period Start June 2, 2020 Original Contract Amount \$2,232,310.42
1	Prime Contractor N.B. West Contr	acting Company Pay Period End June 15, 2020 Net Change Order Amount \$37,400.26
-		Current Contract Amount \$2,269,710.68

Approval Date		By User
June 16, 2020	Generated and Approved (and should be considered Draft) at the Project Office Level by	BOWMAM2
June 16, 2020	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	vancef1
June 17, 2020	Reviewed and Approved at the Central Office Controllers Office Level by	greggd1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
November 2, 2020	November 2, 2020		87.13%

No Milestones Exist for Contract

Contract Total Pa	ay For Estimate No. 4			
		This Estimate	Previous	To Date
200320-F06				
	Total Posted Items Pay	\$172,876.60	\$1,804,804.67	\$1,977,681.27
	Gross Item Adjustments	\$0.00	(\$89,802.41)	(\$89,802.41)
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
			\$1,715,002.26	\$1,887,878.86
Contract Total Pa	ayable This Estimate:	\$172,876.60		

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6M0276	0010	2022010	REMOVAL OF IMPROVEMENTS	LS	\$2,500.000	1	\$2,500.00
	0020	2159903	MISC.MODIFIED SHAPING SLOPES, CLASS III	LF	\$12.000	718	\$8,616.00
	0800	6169901	MISC.TEMPORARY TRAFFIC CONTROL	LS	\$19,200.000	0.25	\$4,800.00
	0100	6181000	MOBILIZATION	LS	\$145,000.000	0.25	\$36,250.00
	0150	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	LS	\$5,000.000	1	\$5,000.00
	0160	6061060	MGS GUARDRAIL	LF	\$24.000	225	\$5,400.00
	0170	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)		\$3,050.000	4	\$12,200.00
	0180	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	EA	\$2,800.000	4	\$11,200.00
	0210	6239905	MISC.HYBRID POLYMER CONCRETE (HPC) OVERLAY	SQYD	\$150.000	168.5	\$25,275.00
	0230	7040113	CLEAN AND EPOXY SEAL	SQFT	\$7.400	719	\$5,320.60
Project J6M	0276 - Tota	ı					\$116,561.60
J6S3420	0240	2022010	REMOVAL OF IMPROVEMENTS	LS	\$1,875.000	1	\$1,875.00
	0260	2151000A	SHAPING SLOPES, CLASS I	100F	\$1,120.000	2	\$2,240.00
	0270	2159903	MISC.MODIFIED, SHAPING SLOPES, CLASS III	LF	\$12.000	600	\$7,200.00
	0380	6181000	MOBILIZATION	LS	\$90,000.000	0.5	\$45,000.00
Project J6S	3420 - Total						\$56,315.00
Overall - To	tal						\$172,876.60

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item /	Adjustr	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6M0276	0030	CRUSHED STONE (B)	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-40	\$260.00	(\$10,400.00)
	0030	CRUSHED STONE (B)	Material			-80	\$260.00	(\$20,800.00)
	0030	CRUSHED STONE (B)	Overrun		This adjustment offsets the original system-	40	\$260.00	\$10,400.00

Revision 4/1/2020 Page 1 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: June 16, 2020

Progress Estimate Number
4

Contract ID 200320-F06 Pay Period Start June 2, 2020 Original Contract Amount \$2,232,310.42
Prime Contractor N.B. West Contracting Company Pay Period End June 15, 2020 Net Change Order Amount \$37,400.26
Current Contract Amount \$2,269,710.68

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6M0276					generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 17 on the current Payment Estimate.			
	0030	CRUSHED STONE (B)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0002) due to user bowmam2 overridding Payment Estimate Exception 2 on the current Payment Estimate.	80	\$260.00	\$20,800.00
	0170	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	Material			-4	\$3,050.00	(\$12,200.00)
	0170	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0003) due to user bowmam2 overridding Payment Estimate Exception 5 on the current Payment Estimate.	4	\$3,050.00	\$12,200.00
	0180	TYPE A CRASHWORTHY END TERMINAL (MASH)	Material			-4	\$2,800.00	(\$11,200.00)
	0180	TYPE A CRASHWORTHY END TERMINAL (MASH)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0004) due to user bowmam2 overridding Payment Estimate Exception 7 on the current Payment Estimate.	4	\$2,800.00	\$11,200.00
	0230	CLEAN AND EPOXY SEAL	Material			-1,419	\$7.40	(\$10,500.60)
	0230	CLEAN AND EPOXY SEAL	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0005) due to user bowmam2 overridding Payment Estimate Exception 16 on the current Payment Estimate.	1,419	\$7.40	\$10,500.60
J6S3420	0280	CRUSHED STONE (B)	Material			-21	\$255.00	(\$5,355.00)
	0280	CRUSHED STONE (B)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0006) due to user bowmam2 overridding Payment Estimate Exception 1 on the current Payment Estimate.	21	\$255.00	\$5,355.00
	0300	TACK COAT	Material			-3,600	\$2.35	(\$8,460.00)
	0300	TACK COAT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0007) due to user bowmam2 overridding Payment Estimate Exception 3 on the current Payment Estimate.	3,600	\$2.35	\$8,460.00
	0390	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-41,712	\$0.12	(\$5,005.44)
	0390	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0008) due to user bowmam2 overridding Payment Estimate Exception 9 on the current Payment Estimate.	41,712	\$0.12	\$5,005.44
	0400	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-41,712	\$0.13	(\$5,422.56)
	0400	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0009) due to user bowmam2 overridding Payment Estimate Exception 11	41,712	\$0.13	\$5,422.56

Revision 4/1/2020 Page 2 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: June 16, 2020

Progress Estimate Number
4

Contract ID 200320-F06 Pay Period Start June 2, 2020 Original Contract Amount \$2,232,310.42
Prime Contractor N.B. West Contracting Company Pay Period End June 15, 2020 Net Change Order Amount \$37,400.26
Current Contract Amount \$2,269,710.68

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6S3420					on the current Payment Estimate.			
	0410	24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-24	\$5.00	(\$120.00
	0410	24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0010) due to user bowmam2 overridding Payment Estimate Exception 13 on the current Payment Estimate.	24	\$5.00	\$120.00
	0430	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	Material			-362.5	\$28.00	(\$10,150.00)
	0430	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0011) due to user bowmam2 overridding Payment Estimate Exception 4 on the current Payment Estimate.	362.5	\$28.00	\$10,150.00
	0440	ASYMMETRICAL TRANSITION SECTION, 6.5 FT. POSTS	Material			-4	\$600.00	(\$2,400.00
	0440	ASYMMETRICAL TRANSITION SECTION, 6.5 FT. POSTS	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0012) due to user bowmam2 overridding Payment Estimate Exception 6 on the current Payment Estimate.	4	\$600.00	\$2,400.00
	0450	TYPE A CRASHWORTHY END TERMINAL (MASH)	Material			-4	\$2,900.00	(\$11,600.00
	0450	TYPE A CRASHWORTHY END TERMINAL (MASH)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0013) due to user bowmam2 overridding Payment Estimate Exception 8 on the current Payment Estimate.	4	\$2,900.00	\$11,600.00
otal								\$0.00

Revision 4/1/2020 Page 3 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Information				
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work					
J6M0276	State	Resurface	Υ	FRANKLIN	from Route YY to Route E					
J6S3420		Resurface	ZZ, Y	FRANKLIN	from Route C to Route Y	Route C to Route Y on Route ZZ and from Route YY to Route 50 on Route Y				
Γotals by J	lob Numbe	ers								
J6M0276	Incen Dising	d Item Pay s Item Adjustm tive centive dated Damage Contract Adju	Gros:	s Item Pay	This Estimate \$116,561.60 \$0.00 \$116,561.60 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	Previous \$907,449.65 (\$82,700.81) \$824,748.84 \$0.00 \$0.00 \$0.00 \$0.00	To Date \$1,024,011.25 (\$82,700.81) \$941,310.44 \$0.00 \$0.00 \$0.00 \$0.00			
J6S3420		d Item Pay Item Adjustm		s Item Pay	This Estimate \$56,315.00 \$0.00 \$56,315.00	Previous \$897,355.02 (\$7,101.60) \$890,253.42	To Date \$953,670.02 (\$7,101.60) \$946,568.42			
	Liquid	tive centive dated Damage Contract Adju		3	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00			

Revision 4/1/2020 Page 4 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6S3420, Item 3102002, Project Item Line Number 0280, Material Set 310200296, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Working with St. Louis Materials to resolve.	BOWMAM2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6M0276, Item 3102002, Project Item Line Number 0030, Material Set 310200296, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Working with St. Louis Materials to resolve.	BOWMAM2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3420, Item 4071005, Project Item Line Number 0300, Material Set 407100596, Material 1015EASS1H - Emulsified Asphalt SS-1H, Acceptance Action Generic AspEmulsion is insufficient.	Working with St. Louis Materials to resolve.	BOWMAM2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3420, Item 6061061, Project Item Line Number 0430, Material Set 606106196, Material 1065DE - Delineators, Acceptance Action Generic 1065DE is insufficient.	Working with St. Louis Materials to resolve.	BOWMAM2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6M0276, Item 6061069, Project Item Line Number 0170, Material Set 606106996, Material 1040GRAB - Bridge Anchor Section, Acceptance Action Generic 1040GRAB is insufficient.	Working with St. Louis Materials to resolve.	BOWMAM2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3420, Item 6062303, Project Item Line Number 0440, Material Set 606230396, Material 1040GRTS - Transition Section, Acceptance Action Generic 1040GRTS is insufficient.	Working with St. Louis Materials to resolve.	BOWMAM2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6M0276, Item 6063014, Project Item Line Number 0180, Material Set 606301496, Material 1040GRCWA - Crashworthy End Terminal Type A, Acceptance Action Generic 1040GRCWA is insufficient.	Working with St. Louis Materials to resolve.	BOWMAM2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3420, Item 6063014, Project Item Line Number 0450, Material Set 606301496, Material 1040GRCWA - Crashworthy End Terminal Type A, Acceptance Action Generic 1040GRCWA is insufficient.	Working with St. Louis Materials to resolve.	BOWMAM2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3420, Item 6206000C, Project Item Line Number 0390, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	Waiting on Retro- reflectivity results.	BOWMAM2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3420, Item 6206000C, Project Item Line Number 0390, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Waiting on Retro- reflectivity results.	BOWMAM2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3420, Item 6206001C, Project Item Line Number 0400, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	Waiting on Retro- reflectivity results.	BOWMAM2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3420, Item 6206001C, Project Item Line Number 0400, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Waiting on Retro- reflectivity results.	BOWMAM2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3420, Item 6206124A, Project Item Line Number 0410, Material Set 6206124A96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	Waiting on Retro- reflectivity results.	BOWMAM2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3420, Item 6206124A, Project Item Line Number 0410, Material Set 6206124A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient.	Waiting on Retro- reflectivity results.	BOWMAM2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3420, Item 6206124A, Project Item Line Number 0410, Material Set 6206124A96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Waiting on Retro- reflectivity results.	BOWMAM2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6M0276, Item 7040113, Project Item Line Number 0230, Material Set 704011396, Material 1039ERBCT3 - Type III Epoxy Resin for Conc Patch Cmp, Acceptance Action Generic 1039ERBCT3 is insufficient.	Working with St. Iouis Materials to resolve.	BOWMAM2	Overridden
Estimate Exception Type: Item Overrun: Contract 200320-F06, Contract Project J6M0276, Project Item Line Number 0030, Contract Line Item Number 0030, Item 3102002, Minor Item.	Waiting on Change order approval.	BOWMAM2	Overridden
Estimate Exception Type: Item Overrun: Contract 200320-F06, Contract Project J6M0276, Project Item Line Number 0060, Contract Line Item Number 0060, Item 6133020, Minor Item.	Waiting on Change order approval.	BOWMAM2	Overridden
Estimate Exception Type: Item Overrun: Contract 200320-F06, Contract Project J6M0276, Project Item Line Number 0070, Contract Line Item Number 0070, Item 6133021, Minor Item.	Waiting on Change order approval.	BOWMAM2	Overridden

Revision 4/1/2020 Page 5 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repo generated date)
0320-F06	J6M0276	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$2,500.00	\$2,500.0
		0001	0020	2159903	MISC.MODIFIED SHAPING SLOPES, CLASS III	718.00	0.00	718.00	LF	718.00	\$12.00	\$8,616.0
		0001	0030	3102002	CRUSHED STONE (B)	40.00	40.00	80.00	TONS	80.00	\$260.00	\$20,800.0
		0001	0040	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	6,228.00	-93.90	6,134.10	TONS	6,134.10	\$80.00	\$490,728.0
		0001	0050	4139912	MISC.OPTIONAL SURFACE TREATMENT	18,613.00	-3,492.00	15,121.00	GAL	15,121.00	\$2.45	\$37,046.4
		0001	0060	6133020	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	469.30	487.20	956.50	TONS	956.50	\$112.30	\$107,414.
		0001	0070	6133021	REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	2,807.20	2,345.10	5,152.30	SQYD	5,152.30	\$7.50	\$38,642.
		0001	0800	6169901	MISC.TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.75	\$19,200.00	\$14,400
		0001	0090	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN	4.00	0.00	4.00	EA	2.00	\$1,000.00	\$2,000
		0001	0100	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$145,000.00	\$145,000
		0001	0110	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	56,021.00	0.00	56,021.00	LF	0.00	\$0.12	\$0
		0001	0120	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	56,021.00	0.00	56,021.00	LF	0.00	\$0.13	\$0
		0001	0130	6206124A	24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	12.00	0.00	12.00	LF	0.00	\$5.00	\$0
		0001	0140	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	2,119.00	0.00	2,119.00	SQYD	2,119.00	\$4.00	\$8,476
		0001	0150	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$5,000.00	\$5,000
		0010	0160	6061060	MGS GUARDRAIL	225.00	0.00	225.00	LF	225.00	\$24.00	\$5,400
		0010	0170	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	4.00	0.00	4.00	EA	4.00	\$3,050.00	\$12,200
		0010	0180	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	4.00	0.00	4.00	EA	4.00	\$2,800.00	\$11,200
		0070	0190	2161501	REMOVAL OF ASPHALT WEARING SURFACE	8,080.00	0.00	8,080.00	SQFT	8,080.00	\$1.40	\$11,312
		0070	0200	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	150.00	0.00	150.00	SQYD	0.00	\$400.00	\$1
		0070	0210	6239905	MISC.HYBRID POLYMER CONCRETE (HPC) OVERLAY	898.00	0.00	898.00	SQYD	618.50	\$150.00	\$92,77
	0070 0220 7040104	7040104	HALF-SOLE REPAIR	200.00	-200.00	0.00	SQFT	0.00	\$66.00	\$1		
		0070	0230	7040113	CLEAN AND EPOXY SEAL	1,419.00	0.00	1,419.00	SQFT	1,419.00	\$7.40	\$10,500
	Project Je	6M0276 - To	tal Value	Posted to D	ate as of Report Generated Date							\$1,024,01°
	J6S3420	0001	0240	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$1,875.00	\$1,875
		0001	0250	2129909	MISC.SHOULDERING	416.90	0.00	416.90	STA	416.90	\$140.00	\$58,36
		0001	0260	2151000A	SHAPING SLOPES, CLASS I	2.00	0.00	2.00	100F	2.00	\$1,120.00	\$2,24
		0001						000.00	LF	000.00		\$7,20
			0270	2159903	MISC.MODIFIED, SHAPING SLOPES, CLASS III	600.00	0.00	600.00	Li	600.00	\$12.00	Ψ1,20
		0001	0270	2159903 3102002	MISC.MODIFIED, SHAPING SLOPES, CLASS III CRUSHED STONE (B)	600.00	0.00	21.00	TONS	21.00	\$12.00 \$255.00	
		0001										\$5,35
			0280	3102002	CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE	21.00	0.00 -73.10	21.00	TONS	21.00	\$255.00	\$5,35 \$349,59
		0001	0280	3102002 4020520	CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	21.00	0.00 -73.10	21.00 4,825.30	TONS	21.00 4,825.30	\$255.00 \$72.45	\$5,358 \$349,598 \$8,466
		0001	0280 0290 0300	3102002 4020520 4071005	CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT	21.00 4,898.40 5,357.00	-73.10 -1,757.00	21.00 4,825.30 3,600.00	TONS TONS GAL	21.00 4,825.30 3,600.00	\$255.00 \$72.45 \$2.35	\$5,356 \$349,593 \$8,466 \$1
		0001 0001 0001	0280 0290 0300 0310	3102002 4020520 4071005 4091048	CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT EMULSIFIED ASPHALT, SEAL COAT	21.00 4,898.40 5,357.00 11,679.00	0.00 -73.10 -1,757.00 0.00	21.00 4,825.30 3,600.00 11,679.00	TONS TONS GAL GAL	21.00 4,825.30 3,600.00 0.00	\$255.00 \$72.45 \$2.35 \$2.60	\$5,35i \$349,59i \$8,46i \$i
		0001 0001 0001 0001	0280 0290 0300 0310 0320	3102002 4020520 4071005 4091048 4094001	CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT EMULSIFIED ASPHALT, SEAL COAT SEAL COAT AGGREGATE, GRADE A1 FURNISHING AND PLACING BITUMINOUS MATERIAL FOR	21.00 4,898.40 5,357.00 11,679.00 116,794.00 2,707.80	0.00 -73.10 -1,757.00 0.00	21.00 4,825.30 3,600.00 11,679.00 116,794.00	TONS TONS GAL GAL SQYD	21.00 4,825.30 3,600.00 0.00	\$255.00 \$72.45 \$2.35 \$2.60 \$0.85	\$5,35: \$349,59: \$8,46: \$! \$!
		0001 0001 0001 0001 0001	0280 0290 0300 0310 0320	3102002 4020520 4071005 4091048 4094001 6133020	CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT EMULSIFIED ASPHALT, SEAL COAT SEAL COAT AGGREGATE, GRADE A1 FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	21.00 4,898.40 5,357.00 11,679.00 116,794.00 2,707.80	0.00 -73.10 -1,757.00 0.00 0.00 -40.40	21.00 4,825.30 3,600.00 11,679.00 116,794.00 2,667.40	TONS TONS GAL GAL SQYD TONS	21.00 4,825.30 3,600.00 0.00 0.00 2,679.90	\$255.00 \$72.45 \$2.35 \$2.60 \$0.85 \$95.50	\$5,35 \$349,59 \$8,46 \$ \$ \$255,93
		0001 0001 0001 0001 0001	0280 0290 0300 0310 0320 0330	3102002 4020520 4071005 4091048 4094001 6133020 6133021	CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT EMULSIFIED ASPHALT, SEAL COAT SEAL COAT AGGREGATE, GRADE A1 FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	21.00 4,898.40 5,357.00 11,679.00 116,794.00 2,707.80 16,198.00	0.00 -73.10 -1,757.00 0.00 0.00 -40.40 -1,319.80	21.00 4,825.30 3,600.00 11,679.00 116,794.00 2,667.40 14,878.20	TONS TONS GAL GAL SQYD TONS	21.00 4,825.30 3,600.00 0.00 0.00 2,679.90 14,878.20	\$255.00 \$72.45 \$2.35 \$2.60 \$0.85 \$95.50	\$5,35 \$349,59 \$8,46 \$ \$ \$255,93 \$110,84
		0001 0001 0001 0001 0001 0001	0280 0290 0300 0310 0320 0330 0340	3102002 4020520 4071005 4091048 4094001 6133020 6133021 6161047	CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT EMULSIFIED ASPHALT, SEAL COAT SEAL COAT AGGREGATE, GRADE A1 FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR TYPE III OBJECT MARKER	21.00 4,898.40 5,357.00 11,679.00 116,794.00 2,707.80 16,198.00	0.00 -73.10 -1,757.00 0.00 0.00 -40.40 -1,319.80	21.00 4,825.30 3,600.00 11,679.00 116,794.00 2,667.40 14,878.20	TONS TONS GAL GAL SQYD TONS SQYD EA	21.00 4,825.30 3,600.00 0.00 0.00 2,679.90 14,878.20 0.00	\$255.00 \$72.45 \$2.35 \$2.60 \$0.85 \$95.50 \$7.45 \$200.00	\$5,35 \$349,59 \$8,46 \$1 \$255,93 \$110,84 \$15,00
		0001 0001 0001 0001 0001 0001 0001	0280 0290 0300 0310 0320 0330 0340 0350	3102002 4020520 4071005 4091048 4094001 6133020 6133021 6161047 6169901	CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT EMULSIFIED ASPHALT, SEAL COAT SEAL COAT AGGREGATE, GRADE A1 FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR TYPE III OBJECT MARKER MISC.TEMPORARY TRAFFIC CONTROL MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN,	21.00 4,898.40 5,357.00 11,679.00 116,794.00 2,707.80 16,198.00 16.00	0.00 -73.10 -1,757.00 0.00 -0.00 -40.40 -1,319.80 0.00	21.00 4,825.30 3,600.00 11,679.00 116,794.00 2,667.40 14,878.20 16.00	TONS TONS GAL GAL SQYD TONS SQYD EA LS	21.00 4,825.30 3,600.00 0.00 2,679.90 14,878.20 0.00 0.75	\$255.00 \$72.45 \$2.35 \$2.60 \$0.85 \$95.50 \$7.45 \$200.00	\$5,351 \$349,592 \$8,466 \$(\$255,930 \$110,842 \$(\$15,000 \$4,000
		0001 0001 0001 0001 0001 0001 0001 000	0280 0290 0300 0310 0320 0330 0340 0350 0360	3102002 4020520 4071005 4091048 4094001 6133020 6133021 6161047 6169901 6169902	CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT EMULSIFIED ASPHALT, SEAL COAT SEAL COAT AGGREGATE, GRADE A1 FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR TYPE III OBJECT MARKER MISC.TEMPORARY TRAFFIC CONTROL MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN, CONTRACTOR FURNISHED AND RETAINED	21.00 4,898.40 5,357.00 11,679.00 116,794.00 2,707.80 16,198.00 16.00 4.00	0.00 -73.10 -1,757.00 0.00 -40.40 -1,319.80 0.00 0.00	21.00 4,825.30 3,600.00 11,679.00 116,794.00 2,667.40 14,878.20 16.00 1.00	TONS GAL GAL SQYD TONS SQYD EA LS EA	21.00 4,825.30 3,600.00 0.00 2,679.90 14,878.20 0.00 0.76 4.00	\$255.00 \$72.45 \$2.35 \$2.60 \$0.85 \$95.50 \$7.45 \$200.00 \$1,000.00	\$5,35 \$349,59 \$8,46 \$1 \$255,99 \$110,84 \$1 \$15,000 \$4,000
		0001 0001 0001 0001 0001 0001 0001 000	0280 0290 0300 0310 0320 0330 0340 0350 0360 0370	3102002 4020520 4071005 4091048 4094001 6133020 6133021 6161047 6169902 6181000 6206000C	CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT EMULSIFIED ASPHALT, SEAL COAT SEAL COAT AGGREGATE, GRADE A1 FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR TYPE III OBJECT MARKER MISC.TEMPORARY TRAFFIC CONTROL MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN, CONTRACTOR FURNISHED AND RETAINED MOBILIZATION 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING	21.00 4,898.40 5,357.00 11,679.00 116,794.00 2,707.80 16,198.00 16.00 4.00 1.00	0.00 -73.10 -1,757.00 0.00 0.00 -40.40 -1,319.80 0.00 0.00 0.00 0.00	21.00 4,825.30 3,600.00 11,679.00 116,794.00 2,667.40 14,878.20 16.00 4.00 1.00	TONS TONS GAL GAL SQYD TONS SQYD EA LS EA	21.00 4,825.30 3,600.00 0.00 2,679.90 14,878.20 0.00 0.75 4.00	\$255.00 \$72.45 \$2.35 \$2.60 \$0.85 \$95.50 \$7.45 \$200.00 \$1,000.00 \$90,000.00	\$5,35i \$349,59i \$8,46i \$i \$255,93i \$110,84i \$i \$4,00i \$90,00i
		0001 0001 0001 0001 0001 0001 0001 0001 0001	0280 0290 0300 0310 0320 0330 0340 0350 0360 0370 0380	3102002 4020520 4071005 4091048 4094001 6133020 6133021 6161047 6169902 6181000 6206000C	CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT EMULSIFIED ASPHALT, SEAL COAT SEAL COAT AGGREGATE, GRADE A1 FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR TYPE III OBJECT MARKER MISC.TEMPORARY TRAFFIC CONTROL MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN, CONTRACTOR FURNISHED AND RETAINED MOBILIZATION 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT	21.00 4,898.40 5,357.00 11,679.00 116,794.00 2,707.80 16,198.00 1.00 4.00 1.00	0.00 -73.10 -1,757.00 0.00 0.00 -40.40 -1,319.80 0.00 0.00 0.00 0.00	21.00 4,825.30 3,600.00 11,679.00 116,794.00 2,667.40 14,878.20 16.00 4.00 4.00	TONS TONS GAL SQYD TONS SQYD EA LS EA LS	21.00 4,825.30 3,600.00 0.00 2,679.90 14,878.20 0.00 0.75 4.00 41,712.00	\$255.00 \$72.45 \$2.35 \$2.60 \$0.85 \$95.50 \$7.45 \$200.00 \$1,000.00 \$90,000.00	\$1,200 \$5,351 \$349,592 \$8,460 \$10,842 \$110,842 \$15,000 \$4,000 \$5,000 \$5,000 \$5,422
		0001 0001 0001 0001 0001 0001 0001 000	0280 0290 0300 0310 0320 0330 0340 0350 0360 0370 0380 0390	3102002 4020520 4071005 4091048 4094001 6133020 6133021 6161047 6169901 6181000 6206000C 6206001C	CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT EMULSIFIED ASPHALT, SEAL COAT SEAL COAT AGGREGATE, GRADE A1 FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR TYPE III OBJECT MARKER MISC.TEMPORARY TRAFFIC CONTROL MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN, CONTRACTOR FURNISHED AND RETAINED MOBILIZATION 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS 24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	21.00 4,898.40 5,357.00 11,679.00 116,794.00 2,707.80 16,198.00 1.00 4.00 1.00 1.00 142,032.00	0.00 -73.10 -1,757.00 0.00 0.00 -40.40 -1,319.80 0.00 0.00 0.00 0.00 0.00 0.00	21.00 4,825.30 3,600.00 11,679.00 116,794.00 2,667.40 14,878.20 16.00 1.00 4.00 1.00 1.00 142,032.00	TONS TONS GAL SQYD TONS SQYD EA LS EA LS LF	21.00 4,825.30 3,600.00 0.00 0.00 2,679.90 14,878.20 0.00 0.75 4.00 1.00 41,712.00	\$255.00 \$72.45 \$2.35 \$2.60 \$0.85 \$95.50 \$7.45 \$200.00 \$1,000.00 \$90,000.00 \$0.12 \$0.13	\$5,351 \$349,592 \$8,460 \$1 \$255,930 \$110,842 \$15,000 \$90,000 \$5,422

Revision 4/1/2020 Page 6 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200320-F06	J6S3420	0010	0440	6062303	ASYMMETRICAL TRANSITION SECTION, 6.5 FT. POSTS	4.00	0.00	4.00	EA	4.00	\$600.00	\$2,400.00
		0010	0450	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	4.00	0.00	4.00	EA	4.00	\$2,900.00	\$11,600.00
		0001	5001	6139905		0.00	28.00	28.00	SQYD	0.00	\$252.95	\$0.00
	Project J6S3420 - Total Value Posted to Date as of Report Generated Date										\$953,670.02	
200320-F06 Ove	00320-F06 Overall - Total Value Posted to Date as of Report Generated Date											\$1,977,681.28

Revision 4/1/2020 Page 7 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J6M0276

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0010	2022010	REMOVAL OF IMPROVEMENTS	6/15/20	6/16/20	1.00	LS		0.00		5.305		At Bridge #A4229
0020	2159903	MISC. SHAPING SLOPES	6/15/20	6/16/20	718.00	LF		0.00		5.305		At Bridge # A4229
0080	6169901	MISC.	6/15/20	6/16/20	0.25	LS		0.00		5.035		
0100	6181000	MOBILIZATION	6/15/20	6/16/20	0.25	LS		0.00		5.035		
0150	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKI	6/15/20	6/16/20	1.00	LS		0.00		5.035		
0160	6061060	MGS GUARDRAIL	6/4/20	6/8/20	225.00	LF	Bridge #A4229 on route Y	0.00		5.2		
0170	6061069	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	6/4/20	6/8/20	4.00	EA	Bridge #A4229 on route Y	0.00		5.2		
0180	6063014	TYPE A CRSHWTHY END TERMINAL (MASH)	6/4/20	6/8/20	4.00	EA	Bridge # A4226 on route Y	0.00		5.2		
0210	6239905	MISC.	6/15/20	6/15/20	168.50	SQYD	Bridge #A4229	2.17		2.22		
0230	7040113	CLEAN AND EPOXY SEAL	6/15/20	6/16/20	719.00	SQFT		0.00		5.035		At bridge # A4229

Project: J6S3420

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted		S		Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0240	2022010	REMOVAL OF IMPROVEMENTS	6/15/20	6/16/20	1.00	LS		0.00		3.948		Bridge # R0290
0260	2151000A	SHAPING SLOPES, CLASS I	6/15/20	6/16/20	2.00	100F		0.00		3.948		Bridge # R0290
0270	2159903	MISC. SHAPING SLOPES	6/15/20	6/16/20	600.00	LF		0.00		3.948		Bridge # R0290
0380	6181000	MOBILIZATION	6/15/20	6/16/20	0.50	LS		0.00		3.948		

The information below this line are details from Line Item agency views.

No Agency View Details Exist

Revision 4/1/2020 Page 8 of 13



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0030	CRUSHED STONE (B)	Material		3	Jun 2, 2020	SYSTEM	(\$20,800.00)	
				3	Jun 2, 2020	SYSTEM	\$20,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user bowmam2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				4	Jun 16, 2020	SYSTEM	(\$20,800.00)	
				4	Jun 16, 2020	SYSTEM	\$20,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user bowmam2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	CRUSHED STONE (B)	Overrun	Overrun	3	Jun 2, 2020	SYSTEM	(\$10,400.00)	
				3	Jun 2, 2020	SYSTEM	\$10,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 19 on the current Payment Estimate.
				3	Jun 2, 2020	BOWMAM2	(\$10,400.00)	Over-run adjustment.
				4	Jun 16, 2020	SYSTEM	(\$10,400.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				4	Jun 16, 2020	SYSTEM	\$10,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 17 on the current Payment Estimate.
			Overrun - T	otal			(\$10,400.00)	
	Overrun - Total						(\$10,400.00)	
0030 -	Total						(\$10,400.00)	
0040	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Material		3	Jun 2, 2020	SYSTEM	(\$490,728.00)	
				3	Jun 2, 2020	SYSTEM	\$490,728.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user bowmam2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0040 -	Total						\$0.00	
0060	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	Overrun	Overrun	3	Jun 2, 2020	SYSTEM	(\$54,712.56)	
		Overrun - T	otal			(\$54,712.56)		
	Overrun - Total						(\$54,712.56)	
0060 -	Total						(\$54,712.56)	
0070	REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	Overrun	Overrun	3	Jun 2, 2020	SYSTEM	(\$17,588.25)	
			Overrun - T	otal			(\$17,588.25)	
	Overrun - Total						(\$17,588.25)	
0070 -	Total						(\$17,588.25)	
0170	MGS BRIDGE APPROACH TRANSITION SECTION	Material		4	Jun 16, 2020	SYSTEM	(\$12,200.00)	
	(REGULAR/NO CURB)			4	Jun 16, 2020	SYSTEM	\$12,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user bowmam2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
		- Total				\$0.00		
	Material - Total						\$0.00	
0170 -	Total						\$0.00	
0180	TYPE A CRASHWORTHY END TERMINAL (MASH)	Material		4	Jun 16, 2020	SYSTEM	(\$11,200.00)	
				4	Jun 16, 2020	SYSTEM	\$11,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user bowmam2 overridding Payment Estimate Exception 7 on the current Payment

Revision 4/1/2020 Page 9 of 13



Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
0180	TYPE A CRASHWORTHY END TERMINAL (MASH)	Material	Туре					Estimate.
	TERMINAL (MASH)		- Total				\$0.00	
	Material - Total						\$0.00	
0180 -	Total						\$0.00	
0230	CLEAN AND EPOXY SEAL	Material		2	May 18, 2020	SYSTEM	(\$5,180.00)	
				2	May 18, 2020	SYSTEM	\$5,180.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user bowmam2 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				3	Jun 2, 2020	SYSTEM	(\$5,180.00)	
				3	Jun 2, 2020	SYSTEM	\$5,180.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user bowmam2 overridding Payment Estimate Exception 18 on the current Payment Estimate.
				4	Jun 16, 2020	SYSTEM	(\$10,500.60)	
				4	Jun 16, 2020	SYSTEM	\$10,500.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user bowmam2 overridding Payment Estimate Exception 16 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0230 -				0		0.12	\$0.00	
0280	CRUSHED STONE (B)	Material		2	May 18, 2020	SYSTEM	(\$5,355.00)	
				2	May 18, 2020	SYSTEM	\$5,355.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user bowmam2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				3	Jun 2, 2020	SYSTEM	(\$5,355.00)	
				3	Jun 2, 2020	SYSTEM	\$5,355.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user bowmam2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				4	Jun 16, 2020	SYSTEM	(\$5,355.00)	
				4	Jun 16, 2020	SYSTEM	\$5,355.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user bowmam2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
0280 -	Material - Total						\$0.00 \$0.00	
0290	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Material		1	May 4, 2020	SYSTEM	(\$177,792.30)	
	(-2			1	May 4, 2020	SYSTEM	\$177,792.30	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user bowmam2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				2	May 18, 2020	SYSTEM	(\$354,889.08)	
				2	May 18, 2020	SYSTEM	\$354,889.08	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user bowmam2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				3	Jun 2, 2020	SYSTEM	(\$349,592.98)	
				3	Jun 2, 2020	SYSTEM	\$349,592.98	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user bowmam2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	

Revision 4/1/2020 Page 10 of 13



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0290 -	Total		.,,,,,				\$0.00	
0300	TACK COAT	Material		1	May 4, 2020	SYSTEM	(\$8,692.65)	
				1	May 4, 2020	SYSTEM	\$8,692.65	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user bowmam2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				2	May 18, 2020	SYSTEM	(\$11,280.00)	
				2	May 18, 2020	SYSTEM	\$11,280.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user bowmam2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				3	Jun 2, 2020	SYSTEM	(\$8,460.00)	
				3	Jun 2, 2020	SYSTEM	\$8,460.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user bowmam2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				4	Jun 16, 2020	SYSTEM	(\$8,460.00)	
				4	Jun 16, 2020	SYSTEM	\$8,460.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user bowmam2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0300 -	Total						\$0.00	
0390	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		2	May 18, 2020	SYSTEM	(\$5,005.44)	
	WARRING FAIRT, FILE BELLIGO			2	May 18, 2020	SYSTEM	\$5,005.44	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user bowmam2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				3	Jun 2, 2020	SYSTEM	(\$5,005.44)	
				3	Jun 2, 2020	SYSTEM	\$5,005.44	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user bowmam2 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				4	Jun 16, 2020	SYSTEM	(\$5,005.44)	
				4	Jun 16, 2020	SYSTEM	\$5,005.44	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user bowmam2 overridding Payment Estimate Exception 9 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Other Item Adjustment	REFL	2	May 18, 2020	BOWMAM2	(\$3,408.77)	
			REFL - Tota	ıl			(\$3,408.77)	
	Other Item Adjustment - Total						(\$3,408.77)	
0390 -	Total						(\$3,408.77)	
0400	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT	Material		2	May 18, 2020	SYSTEM	(\$5,422.56)	
	MARKING PAINT, TYPE P BEADS			2	May 18, 2020	SYSTEM	\$5,422.56	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user bowmam2 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				3	Jun 2, 2020	SYSTEM	(\$5,422.56)	
				3	Jun 2, 2020	SYSTEM	\$5,422.56	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user bowmam2 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				4	Jun 16,	SYSTEM	(\$5,422.56)	

Revision 4/1/2020 Page 11 of 13



1.50.0	Diti	A -1:	Ott	F-4	0	O	A t	Demonto
Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
			Туре					
0400	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		4	Jun 16, 2020	SYSTEM	\$5,422.56	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user bowmam2 overridding Payment Estimate Exception 11 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Other Item Adjustment	REFL	2	May 18, 2020	BOWMAM2	(\$3,692.83)	
			REFL - Tota	ı			(\$3,692.83)	
	Other Item Adjustment - Total						(\$3,692.83)	
0400 -	Total						(\$3,692.83)	
0410	24 IN. WHITE STANDARD WATERBORNE PAVEMENT	Material		2	May 18, 2020	SYSTEM	(\$120.00)	
	MARKING PAINT, TYPE P BEADS			2	May 18, 2020	SYSTEM	\$120.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user bowmam2 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				3	Jun 2, 2020	SYSTEM	(\$120.00)	
				3	Jun 2, 2020	SYSTEM	\$120.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user bowmam2 overridding Payment Estimate Exception 15 on the current Payment Estimate.
				4	Jun 16, 2020	SYSTEM	(\$120.00)	
				4	Jun 16, 2020	SYSTEM	\$120.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user bowmam2 overridding Payment Estimate Exception 13 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0410 -	Total						\$0.00	
0430	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	Material		3	Jun 2, 2020	SYSTEM	(\$10,150.00)	
0430		Material		3		SYSTEM		This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user bowmam2 overridding Payment Estimate Exception 7 on the current Payment Estimate.
0430		Material			2020 Jun 2,		(\$10,150.00)	Payment Estimate Item Adjustment (0013) due to user bowmam2 overridding Payment Estimate Exception 7 on the current Payment
0430		Material		3	2020 Jun 2, 2020 Jun 16,	SYSTEM	(\$10,150.00) \$10,150.00	Payment Estimate Item Adjustment (0013) due to user bowmam2 overridding Payment Estimate Exception 7 on the current Payment
0430	FT 3 IN. SPACING	Material	- Total	3	2020 Jun 2, 2020 Jun 16, 2020 Jun 16,	SYSTEM	(\$10,150.00) \$10,150.00 (\$10,150.00) \$10,150.00	Payment Estimate Item Adjustment (0013) due to user bowmam2 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user bowmam2 overridding Payment Estimate Exception 4 on the current Payment
	FT 3 IN. SPACING Material - Total	Material	- Total	3	2020 Jun 2, 2020 Jun 16, 2020 Jun 16,	SYSTEM	(\$10,150.00) \$10,150.00 (\$10,150.00) \$10,150.00 \$0.00	Payment Estimate Item Adjustment (0013) due to user bowmam2 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user bowmam2 overridding Payment Estimate Exception 4 on the current Payment
0430 -	FT 3 IN. SPACING Material - Total Total	Material	- Total	4 4	2020 Jun 2, 2020 Jun 16, 2020 Jun 16,	SYSTEM	(\$10,150.00) \$10,150.00 (\$10,150.00) \$10,150.00	Payment Estimate Item Adjustment (0013) due to user bowmam2 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user bowmam2 overridding Payment Estimate Exception 4 on the current Payment
	FT 3 IN. SPACING Material - Total	Material	- Total	3	2020 Jun 2, 2020 Jun 16, 2020 Jun 16,	SYSTEM	(\$10,150.00) \$10,150.00 (\$10,150.00) \$10,150.00 \$0.00	Payment Estimate Item Adjustment (0013) due to user bowmam2 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user bowmam2 overridding Payment Estimate Exception 4 on the current Payment
0430 -	Material - Total Total ASYMMETRICAL TRANSITION		- Total	4 4	2020 Jun 2, 2020 Jun 16, 2020 Jun 16, 2020	SYSTEM SYSTEM SYSTEM	(\$10,150.00) \$10,150.00 (\$10,150.00) \$10,150.00 \$0.00 \$0.00	Payment Estimate Item Adjustment (0013) due to user bowmam2 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user bowmam2 overridding Payment Estimate Exception 4 on the current Payment
0430 -	Material - Total Total ASYMMETRICAL TRANSITION		- Total	3 4 4 4	Jun 16, 2020 Jun 2, 2020 Jun 16, 2020 Jun 16, 2020 Jun 2, 2020 Jun 2, 2020	SYSTEM SYSTEM SYSTEM SYSTEM	(\$10,150.00) \$10,150.00 (\$10,150.00) \$10,150.00 \$0.00 \$0.00 \$0.00 (\$2,400.00)	Payment Estimate Item Adjustment (0013) due to user bowmam2 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user bowmam2 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user bowmam2 overridding Payment Estimate Exception 9 on the current Payment
0430 -	Material - Total Total ASYMMETRICAL TRANSITION			3 3 3 3	Jun 2, 2020 Jun 16, 2020 Jun 16, 2020 Jun 2, 2020 Jun 2, 2020	SYSTEM SYSTEM SYSTEM SYSTEM	(\$10,150.00) \$10,150.00 (\$10,150.00) \$10,150.00 \$0.00 \$0.00 (\$2,400.00)	Payment Estimate Item Adjustment (0013) due to user bowmam2 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user bowmam2 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user bowmam2 overridding Payment Estimate Exception 9 on the current Payment
0430 -	Material - Total Total ASYMMETRICAL TRANSITION SECTION, 6.5 FT. POSTS		- Total	3 3 3 4	Jun 2, 2020 Jun 16, 2020 Jun 16, 2020 Jun 2, 2020 Jun 2, 2020 Jun 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$10,150.00) \$10,150.00 (\$10,150.00) \$10,150.00 \$0.00 \$0.00 (\$2,400.00) \$2,400.00	Payment Estimate Item Adjustment (0013) due to user bowmam2 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user bowmam2 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user bowmam2 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user bowmam2 overridding Payment Estimate Exception 6 on the current Payment
0430 - 0440	Material - Total Total ASYMMETRICAL TRANSITION SECTION, 6.5 FT. POSTS			3 3 3 4	Jun 2, 2020 Jun 16, 2020 Jun 16, 2020 Jun 2, 2020 Jun 2, 2020 Jun 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$10,150.00) \$10,150.00 (\$10,150.00) \$10,150.00 \$0.00 \$0.00 \$0.00 (\$2,400.00) \$2,400.00 \$2,400.00 \$0.00 \$0.00	Payment Estimate Item Adjustment (0013) due to user bowmam2 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user bowmam2 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user bowmam2 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user bowmam2 overridding Payment Estimate Exception 6 on the current Payment
0430 - 0440	Material - Total Total ASYMMETRICAL TRANSITION SECTION, 6.5 FT. POSTS Material - Total Total	Material		3 3 3 4 4	Jun 2, 2020 Jun 16, 2020 Jun 16, 2020 Jun 2, 2020 Jun 2, 2020 Jun 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$10,150.00) \$10,150.00 (\$10,150.00) \$10,150.00 \$0.00 \$0.00 \$0.00 (\$2,400.00) \$2,400.00 \$2,400.00 \$0.00 \$0.00 \$0.00	Payment Estimate Item Adjustment (0013) due to user bowmam2 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user bowmam2 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user bowmam2 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user bowmam2 overridding Payment Estimate Exception 6 on the current Payment
0430 - 0440	Material - Total Total ASYMMETRICAL TRANSITION SECTION, 6.5 FT. POSTS			3 3 3 4	Jun 2, 2020 Jun 16, 2020 Jun 16, 2020 Jun 2, 2020 Jun 2, 2020 Jun 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$10,150.00) \$10,150.00 (\$10,150.00) \$10,150.00 \$0.00 \$0.00 \$0.00 (\$2,400.00) \$2,400.00 \$2,400.00 \$0.00 \$0.00	Payment Estimate Item Adjustment (0013) due to user bowmam2 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user bowmam2 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user bowmam2 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user bowmam2 overridding Payment Estimate Exception 6 on the current Payment

Revision 4/1/2020 Page 12 of 13



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0450	TYPE A CRASHWORTHY END TERMINAL (MASH)	Material			2020			Payment Estimate Item Adjustment (0015) due to user bowmam2 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				4	Jun 16, 2020	SYSTEM	(\$11,600.00)	
				4	Jun 16, 2020	SYSTEM	\$11,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user bowmam2 overridding Payment Estimate Exception 8 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0450 -	- Total						\$0.00	
Overall - Total							(\$89,802.41)	

Revision 4/1/2020 Page 13 of 13