Pay Estimate Created Date: July 16, 2020

| Progress Estima 6 | te Number | Contract ID Prime Contractor | 200320-F06 N.B. West Contract | ting Company | | | Original Contract Amount Net Change Order Amount Current Contract Amount | \$2,232,310.42 \$140,647.30 \$2,372,957.72 | | | | |
|----------------------|---|--|----------------------------------|----------------|-----------------------|----------------|--|--|--|--|--|--|
| Approval Date | | | | | | | | By User | | | | |
| July 16, 2020 | | Generated and Approved (and should be considered Draft) at the Project Office Level by | | | | | | | | | | |
| July 16, 2020 | | | Reviewed and App | proved (and sh | ould be considered D | raft) at the F | Resident Engineer Level by | vancef1 | | | | |
| July 17, 2020 | | | | Reviewed an | nd Approved at the Ce | entral Office | Controllers Office Level by | greggd1 | | | | |
| Original Compl | inal Completion Date Current Completion Date Actual Completion Date % of Current Contract Amo | | | | | | | | | | | |
| November 2 | 2, 2020 | Novemb | oer 2, 2020 | 20 96.71% | | | | | | | | |

No Milestones Exist for Contract

| Contract Total Pa | ay For Estimate No. 6 | | | | |
|-------------------|----------------------------|---------------|----------------|----------------|--|
| | | This Estimate | Previous | To Date | |
| 200320-F06 | | | | | |
| | Total Posted Items Pay | \$42,425.25 | \$2,252,493.61 | \$2,294,918.86 | |
| | Gross Item Adjustments | (\$7,817.05) | (\$47,501.60) | (\$55,318.65) | |
| | Incentive | \$0.00 | \$0.00 | \$0.00 | |
| | Disincentive | \$0.00 | \$0.00 | \$0.00 | |
| | Liquidated Damage | \$0.00 | \$0.00 | \$0.00 | |
| | Other Contract Adjustments | \$0.00 | \$0.00 | \$0.00 | |
| | | | \$2,204,992.01 | \$2,239,600.21 | |
| Contract Total Pa | ayable This Estimate: | \$34,608.20 | | | |

Contract Total Payable This Estimate: Items Paid This Estimate Period

| Project Number | Line Number | Item Code | Item Description | Unit | Unit Price | Current Installed Qty | Current Installed Amount |
|-------------------|----------------|--------------|---|------|------------|--------------------------|-----------------------------|
| J6M0276 | 0110 | 6206000C | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | LF | \$0.120 | 56,021 | \$6,722.52 |
| | 0120 | 6206001C | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | LF | \$0.130 | 56,021 | \$7,282.73 |
| | 0130 | 6206124A | 24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | LF | \$5.000 | 12 | \$60.00 |
| Project J6M | 0276 - Tota | d. | | | | | \$14,065.25 |
| J6S3420 | 0350 | 6161047 | TYPE III OBJECT MARKER | EA | \$200.000 | 16 | \$3,200.00 |
| | 0390 | 6206000C | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | LF | \$0.120 | 100,320 | \$12,038.40 |
| | 0400 | 6206001C | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | LF | \$0.130 | 100,320 | \$13,041.60 |
| | 0410 | 6206124A | 24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | LF | \$5.000 | 16 | \$80.00 |
| Project J6S | 3420 - Tota | I | | | | | \$28,360.00 |
| Overall - To | tal | | | | | | \$42,425.25 |

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

| Project Number | Line No. | Item Description | Adjustment Type | Other Item Adjustment Type | Comments | Adjustment Quantity | Line Item Adjustment Unit Price | Adjustment amount |
|-------------------|-------------|--|--------------------------|----------------------------------|--|------------------------|---------------------------------------|----------------------|
| J6M0276 | 0030 | CRUSHED STONE (B) | Material | | | -80 | \$260.00 | (\$20,800.00) |
| | 0030 | CRUSHED STONE (B) | Material | | This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0002) due to user bowmam2 overridding Payment Estimate Exception 2 on the current Payment Estimate. | 80 | \$260.00 | \$20,800.00 |
| | 0110 | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | Other Item Adjustment | Retroreflectivity Adjustment | Holding 20% of contract price , waiting on retro reflectivity results. | | | (\$1,344.50) |
| | 0120 | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | Other Item Adjustment | Retroreflectivity Adjustment | Holding 20% of contract price , waiting on retro reflectivity results. | | | (\$1,456.55) |



Pay Estimate Created Date: July 16, 2020

| Progre | | imate Number 6 | Contract ID Prime Contra | 200320 actor N.B. W |)-F06 /est Contracting C | | | r Amount 🖇 | 2,232,310.42 140,647.30 2,372,957.72 |
|-------------------|-------------|-------------------|---|--------------------------|----------------------------------|---|------------------------|---------------------------------------|--|
| Project Number | Line No. | Item Des | cription | Adjustment Type | Other Item Adjustment Type | Comments | Adjustment Quantity | Line Item Adjustment Unit Price | Adjustment amount |
| J6M0276 | 0130 | WATERBORN | E STANDARD E PAVEMENT AINT, TYPE P BEADS | Material | | | -12 | \$5.00 | (\$60.00 |
| | 0130 | WATERBORN | E STANDARD E PAVEMENT AINT, TYPE P BEADS | Material | | This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0003) due to user bowmam2 overridding Payment Estimate Exception 17 on the current Payment Estimate. | 12 | \$5.00 | \$60.00 |
| | 0170 | TRANSITI | E APPROACH ON SECTION AR/NO CURB) | Material | | | -4 | \$3,050.00 | (\$12,200.00 |
| | 0170 | TRANSITI | E APPROACH ON SECTION AR/NO CURB) | Material | | This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0004) due to user bowmam2 overridding Payment Estimate Exception 13 on the current Payment Estimate. | 4 | \$3,050.00 | \$12,200.00 |
| | 0180 | | ASHWORTHY IINAL (MASH) | Material | | | -4 | \$2,800.00 | (\$11,200.00) |
| | 0180 | | ASHWORTHY IINAL (MASH) | Material | | This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0005) due to user bowmam2 overridding Payment Estimate Exception 15 on the current Payment Estimate. | 4 | \$2,800.00 | \$11,200.00 |
| J6S3420 | 0280 | CRUSHE | D STONE (B) | Material | | | -21 | \$255.00 | (\$5,355.00) |
| | 0280 | CRUSHE | D STONE (B) | Material | | This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0006) due to user bowmam2 overridding Payment Estimate Exception 1 on the current Payment Estimate. | 21 | \$255.00 | \$5,355.00 |
| | 0300 | | TACK COAT | Material | | | -3,600 | \$2.35 | (\$8,460.00) |
| | 0300 | | TACK COAT | Material | | This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0007) due to user bowmam2 overridding Payment Estimate Exception 3 on the current Payment Estimate. | 3,600 | \$2.35 | \$8,460.00 |
| | 0310 | EMULSIFIE | ED ASPHALT, SEAL COAT | Material | | | -51,389.4 | \$2.60 | (\$133,612.44) |
| | 0310 | EMULSIFIE | ED ASPHALT, SEAL COAT | Material | | This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0008) due to user bowmam2 overridding Payment Estimate Exception 4 on the current Payment Estimate. | 51,389.4 | \$2.60 | \$133,612.44 |
| | 0320 | SEAL COAT A | AGGREGATE, GRADE A1 | Material | | | -116,794 | \$0.85 | (\$99,274.90) |
| | 0320 | SEAL COAT A | AGGREGATE, GRADE A1 | Material | | This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0009) due to user bowmam2 overridding Payment Estimate Exception 11 on the current Payment Estimate. | 116,794 | \$0.85 | \$99,274.90 |
| | 0330 | | JS MATERIAL S C PARTIAL | Overrun | | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). | -12.5 | \$95.50 | (\$1,193.75) |
| | 0330 | | JS MATERIAL S C PARTIAL | Overrun | | This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0001) due to user bowmam2 overridding Payment Estimate Exception 19 on the current Payment Estimate. | 12.5 | \$95.50 | \$1,193.75 |
| | 0390 | WATERBORN | E STANDARD E PAVEMENT AINT, TYPE P | Other Item Adjustment | Retroreflectivity Adjustment | Holding 20% of contract price , waiting on retro reflectivity results. | | | (\$2,407.68) |



Pay Estimate Created Date: July 16, 2020

| Progre | ess Esti (| mate Number | Contract ID Prime Contra | 200320 actor N.B. W | 0-F06 /est Contracting C | | | r Amount \$ | 2,232,310.42 140,647.30 2,372,957.72 |
|-------------------|---------------|--|---|--------------------------|----------------------------------|---|------------------------|---------------------------------------|--|
| Project Number | Line No. | Item Desc | cription | Adjustment Type | Other Item Adjustment Type | Comments | Adjustment Quantity | Line Item Adjustment Unit Price | Adjustment amount |
| J6S3420 | | | BEADS | | | | | | |
| | 0400 | 4 IN. YELLOW WATERBORNE MARKING PA | E PAVEMENT | Other Item Adjustment | Retroreflectivity Adjustment | Holding 20% of contract price , waiting on retro reflectivity results. | | | (\$2,608.32) |
| | 0410 | 24 IN. WHITE WATERBORNE MARKING PA | | Material | | | -40 | \$5.00 | (\$200.00) |
| | 0410 | 24 IN. WHITE WATERBORNE MARKING PA | | Material | | This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0010) due to user bowmam2 overridding Payment Estimate Exception 18 on the current Payment Estimate. | 40 | \$5.00 | \$200.00 |
| | 0430 | | RDRAIL, 8 FT. 5, 6 FT 3 IN. SPACING | Material | | | -362.5 | \$28.00 | (\$10,150.00) |
| | 0430 | | RDRAIL, 8 FT. 5, 6 FT 3 IN. SPACING | Material | | This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0011) due to user bowmam2 overridding Payment Estimate Exception 12 on the current Payment Estimate. | 362.5 | \$28.00 | \$10,150.00 |
| | 0440 | ASY TRANSITION S | MMETRICAL SECTION, 6.5 FT. POSTS | Material | | | -4 | \$600.00 | (\$2,400.00) |
| | 0440 | ASY TRANSITION S | MMETRICAL SECTION, 6.5 FT. POSTS | Material | | This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0012) due to user bowmam2 overridding Payment Estimate Exception 14 on the current Payment Estimate. | 4 | \$600.00 | \$2,400.00 |
| | 0450 | | ASHWORTHY INAL (MASH) | Material | | | -4 | \$2,900.00 | (\$11,600.00) |
| | 0450 | | ASHWORTHY INAL (MASH) | Material | | This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0013) due to user bowmam2 overridding Payment Estimate Exception 16 on the current Payment Estimate. | 4 | \$2,900.00 | \$11,600.00 |
| otal | | | | | | | | | (\$7,817.05) |



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

| | Contract Project Information | | | | | | | | | | |
|--|------------------------------|-----------|-------|----------|--|--|--|--|--|--|--|
| Project Number Federal Proj. Number Project Description Route County | | | | | | | | | | | |
| J6M0276 | State | Resurface | Υ | FRANKLIN | rom Route YY to Route E | | | | | | |
| J6S3420 | | Resurface | ZZ, Y | FRANKLIN | from Route C to Route Y on Route ZZ and from Route YY to Route 50 on Route Y | | | | | | |

Totals by Job Numbers

| 10276 | This Estimate | Previous | To Date |
|--|--|---|--|
| Posted Item Pay | \$14,065.25 | \$1,065,936.25 | \$1,080,001.50 |
| Gross Item Adjustments | (\$2,801.05) | (\$40,400.00) | (\$43,201.05) |
| Gross Item Pay | \$11,264.20 | \$1,025,536.25 | \$1,036,800.45 |
| | | | |
| Incentive | \$0.00 | \$0.00 | \$0.00 |
| Disincentive | \$0.00 | \$0.00 | \$0.00 |
| Liquidated Damages | \$0.00 | \$0.00 | \$0.00 |
| | | | |
| Other Contract Adjustments | \$0.00 | \$0.00 | \$0.00 |
| Other Contract Adjustments | • • • • • | | • • • • |
| | \$0.00 This Estimate | \$0.00 Previous | \$0.00 To Date |
| Other Contract Adjustments | • • • • • | | • • • • |
| Other Contract Adjustments | This Estimate | Previous | To Date |
| Other Contract Adjustments 3420 Posted Item Pay | This Estimate \$28,360.00 | Previous \$1,186,557.36 | To Date \$1,214,917.36 |
| Other Contract Adjustments 3420 Posted Item Pay Gross Item Adjustments Gross Item Pay | This Estimate \$28,360.00 (\$5,016.00) \$23,344.00 | Previous \$1,186,557.36 (\$7,101.60) \$1,179,455.76 | To Date \$1,214,917.36 (\$12,117.60) \$1,202,799.76 |
| Other Contract Adjustments 3420 Posted Item Pay Gross Item Adjustments Gross Item Pay Incentive | This Estimate \$28,360.00 (\$5,016.00) \$23,344.00 \$0.00 | Previous \$1,186,557.36 (\$7,101.60) \$1,179,455.76 \$0.00 | To Date \$1,214,917.36 (\$12,117.60) \$1,202,799.76 \$0.00 |
| Other Contract Adjustments 3420 Posted Item Pay Gross Item Adjustments Gross Item Pay Incentive Disincentive | This Estimate \$28,360.00 (\$5,016.00) \$23,344.00 \$0.00 \$0.00 | Previous \$1,186,557.36 (\$7,101.60) \$1,179,455.76 \$0.00 \$0.00 | To Date \$1,214,917.36 (\$12,117.60) \$1,202,799.76 \$0.00 \$0.00 |
| Other Contract Adjustments 3420 Posted Item Pay Gross Item Adjustments Gross Item Pay Incentive | This Estimate \$28,360.00 (\$5,016.00) \$23,344.00 \$0.00 | Previous \$1,186,557.36 (\$7,101.60) \$1,179,455.76 \$0.00 | To Date \$1,214,917.36 (\$12,117.60) \$1,202,799.76 \$0.00 |



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

| Exceptions (Discrepancies) This Estimate Feriou | | | |
|--|---|------------|------------|
| Exceptions / Discrepencies | Explanation | Entered By | Status |
| Estimate Exception Type: Insufficient Materials: Project J6S3420, Item 3102002, Project Item Line Number 0280, Material Set 310200296, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient. | Working with SL Materials to resolve this issue. | BOWMAM2 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6M0276, Item 3102002, Project Item Line Number 0030, Material Set 310200296, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient. | Working with SL Materials to resolve this issue. | BOWMAM2 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3420, Item 4071005, Project Item Line Number 0300, Material Set 407100596, Material 1015EASS1H - Emulsified Asphalt SS-1H, Acceptance Action Generic AspEmulsion is insufficient. | Working with STL materials to resolve, STL material needs to remove items that were not needed. | BOWMAM2 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3420, Item 4091048, Project Item Line Number 0310, Material Set 409104896, Material 1015EACRS1 - Emulsified Asphalt CRS-1, Acceptance Action Generic AspEmulsion is insufficient. | Working with STL materials to resolve, STL material needs to remove items that were not needed. | BOWMAM2 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3420, Item 4091048, Project Item Line Number 0310, Material Set 409104896, Material 1015EACRS2 - Emulsified Asphalt CRS-2, Acceptance Action Generic AspEmulsion is insufficient. | Working with STL materials to resolve, STL material needs to remove items that were not needed. | BOWMAM2 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3420, Item 4091048, Project Item Line Number 0310, Material Set 409104896, Material 1015EACRS2P - Emulsified Asphalt CRS-2P, Acceptance Action Generic AspEmulsion is insufficient. | Working with STL materials to resolve, STL material needs to remove items that were not needed. | BOWMAM2 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3420, Item 4091048, Project Item Line Number 0310, Material Set 409104896, Material 1015EAEA150 - Emulsified Asphalt EA-150, Acceptance Action Generic AspEmulsion is insufficient. | Working with STL materials to resolve, STL material needs to remove items that were not needed. | BOWMAM2 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3420, Item 4091048, Project Item Line Number 0310, Material Set 409104896, Material 1015EAEA300 - Emulsified Asphalt EA-300, Acceptance Action Generic AspEmulsion is insufficient. | Working with STL materials to resolve, STL material needs to remove items that were not needed. | BOWMAM2 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3420, Item 4091048, Project Item Line Number 0310, Material Set 409104896, Material 1015EAEA90P - Emulsified Asphalt EA-90P, Acceptance Action Generic AspEmulsion is insufficient. | Working with STL materials to resolve, STL material needs to remove items that were not needed. | BOWMAM2 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3420, Item 4091048, Project Item Line Number 0310, Material Set 409104896, Material 1015EARS1 - Emulsified Asphalt RS-1, Acceptance Action Generic AspEmulsion is insufficient. | Working with STL materials to resolve, STL material needs to remove items that were not needed. | BOWMAM2 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3420, Item 4094001, Project Item Line Number 0320, Material Set 409400196, Material 1003GA - Aggregate for Seal Coat Grade A1, Acceptance Action Generic 1003GA is insufficient. | Working with STL material to resolve this issue. | BOWMAM2 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3420, Item 6061061, Project Item Line Number 0430, Material Set 606106196, Material 1065DE - Delineators, Acceptance Action Generic 1065DE is insufficient. | Working with STL material to resolve this issue. | BOWMAM2 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6M0276, Item 6061069, Project Item Line Number 0170, Material Set 606106996, Material 1040GRAB - Bridge Anchor Section, Acceptance Action Generic 1040GRAB is insufficient. | Working with STL material to resolve this issue. | BOWMAM2 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3420, Item 6062303, Project Item Line Number 0440, Material Set 606230396, Material 1040GRTS - Transition Section, Acceptance Action Generic 1040GRTS is insufficient. | Working with STL material to resolve this issue. | BOWMAM2 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6M0276, Item 6063014, Project Item Line Number 0180, Material Set 606301496, Material 1040GRCWA - Crashworthy End Terminal Type A, Acceptance Action Generic 1040GRCWA is insufficient. | Working with STL material to resolve this issue. | BOWMAM2 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3420, Item 6063014, Project Item Line Number 0450, Material Set 606301496, Material 1040GRCWA - Crashworthy End Terminal Type A, Acceptance Action Generic 1040GRCWA is insufficient. | Working with STL material to resolve this issue. | BOWMAM2 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6M0276, Item 6206124A, Project Item Line Number 0130, Material Set 6206124A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient. | Waiting on retro reflectivity numbers for entire project Route ZZ numbers are completed, waiting route Y results. | BOWMAM2 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3420, Item 6206124A, Project Item Line Number 0410, Material Set 6206124A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient. | Waiting on retro reflectivity results for route Y. | BOWMAM2 | Overridden |
| Estimate Exception Type: Item Overrun: Contract 200320-F06, Contract Project J6S3420, Project Item Line Number 0330, Contract Line Item Number 0330, Item 6133020, Minor Item. | Working with STL Materials to resolve this issue. | BOWMAM2 | Overridden |
| | | | |

Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Note: Posted Q | uantities a | and Value | es are b | ased on R | eport Generated date and can differ from the posted amo | unt at the ti | ime the Es | timate was | Generat | ed. | | |
|-------------------------|----------------|------------|-------------|--------------|--|-----------------|------------------------|------------------------------|---------|------------------------------------|--------------|--|
| Contract Nm.CONTRACT | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTED To Date (See report generated date) |
| 200320-F06 | J6M0276 | 0001 | 0010 | 2022010 | REMOVAL OF IMPROVEMENTS | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$2,500.00 | \$2,500.00 |
| | | 0001 | 0020 | 2159903 | MISC.MODIFIED SHAPING SLOPES, CLASS III | 718.00 | 0.00 | 718.00 | LF | 718.00 | \$12.00 | \$8,616.00 |
| | | 0001 | 0030 | 3102002 | CRUSHED STONE (B) | 40.00 | 40.00 | 80.00 | TONS | 80.00 | \$260.00 | \$20,800.00 |
| | | 0001 | 0040 | 4020520 | BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) | 6,228.00 | -93.90 | 6,134.10 | TONS | 6,134.10 | \$80.00 | \$490,728.00 |
| | | 0001 | 0050 | 4139912 | MISC.OPTIONAL SURFACE TREATMENT | 18,613.00 | -3,492.00 | 15,121.00 | GAL | 15,121.00 | \$2.45 | \$37,046.45 |
| | | 0001 | 0060 | 6133020 | FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR | 469.30 | 487.20 | 956.50 | TONS | 956.50 | \$112.30 | \$107,414.95 |
| | | 0001 | 0070 | 6133021 | REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR | 2,807.20 | 2,345.10 | 5,152.30 | SQYD | 5,152.30 | \$7.50 | \$38,642.25 |
| | | 0001 | 0080 | 6169901 | MISC.TEMPORARY TRAFFIC CONTROL | 1.00 | 0.00 | 1.00 | LS | 0.75 | \$19,200.00 | \$14,400.00 |
| | | 0001 | 0090 | 6169902 | MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN | 4.00 | 0.00 | 4.00 | EA | 2.00 | \$1,000.00 | \$2,000.00 |
| | | 0001 | 0100 | 6181000 | MOBILIZATION | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$145,000.00 | \$145,000.00 |
| | | 0001 | 0110 | 6206000C | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | 56,021.00 | 0.00 | 56,021.00 | LF | 56,021.00 | \$0.12 | \$6,722.52 |
| | | 0001 | 0120 | | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | 56,021.00 | 0.00 | 56,021.00 | LF | 56,021.00 | \$0.13 | \$7,282.73 |
| | | 0001 | 0130 | 6206124A | 24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | 12.00 | 0.00 | 12.00 | LF | 12.00 | \$5.00 | \$60.00 |
| | | 0001 | 0140 | 6224010 | MODIFIED COLDMILLING (DEPTH TRANSITIONS) | 2,119.00 | 0.00 | 2,119.00 | SQYD | 2,119.00 | \$4.00 | \$8,476.00 |
| | | 0001 | 0150 | 6274000 | CONTRACTOR FURNISHED SURVEYING AND STAKING | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$5,000.00 | \$5,000.00 |
| | | 0010 | 0160 | 6061060 | MGS GUARDRAIL | 225.00 | 0.00 | 225.00 | LF | 225.00 | \$24.00 | \$5,400.00 |
| | | 0010 | 0170 | 6061069 | MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB) | 4.00 | 0.00 | 4.00 | EA | 4.00 | \$3,050.00 | \$12,200.00 |
| | | 0010 | 0180 | 6063014 | TYPE A CRASHWORTHY END TERMINAL (MASH) | 4.00 | 0.00 | 4.00 | EA | 4.00 | \$2,800.00 | \$11,200.00 |
| | | 0070 | 0190 | 2161501 | REMOVAL OF ASPHALT WEARING SURFACE | 8,080.00 | 0.00 | 8,080.00 | SQFT | 8,080.00 | \$1.40 | \$11,312.00 |
| | | 0070 | 0200 | 5031011A | BRIDGE APPROACH SLAB (MINOR ROAD) | 150.00 | 0.00 | 150.00 | SQYD | 0.00 | \$400.00 | \$0.00 |
| | | 0070 | 0210 | 6239905 | MISC.HYBRID POLYMER CONCRETE (HPC) OVERLAY | 898.00 | 0.00 | 898.00 | SQYD | 898.00 | \$150.00 | \$134,700.00 |
| | | 0070 | 0220 | 7040104 | HALF-SOLE REPAIR | 200.00 | -200.00 | 0.00 | SQFT | 0.00 | \$66.00 | \$0.00 |
| | | 0070 | 0230 | 7040113 | CLEAN AND EPOXY SEAL | 1,419.00 | 0.00 | 1,419.00 | SQFT | 1,419.00 | \$7.40 | \$10,500.60 |
| | Project J6 | M0276 - To | otal Value | Posted to D | Pate as of Report Generated Date | | | | | | | \$1,080,001.50 |
| | J6S3420 | 0001 | 0240 | 2022010 | REMOVAL OF IMPROVEMENTS | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$1,875.00 | \$1,875.00 |
| | | 0001 | 0250 | 2129909 | MISC.SHOULDERING | 416.90 | 0.00 | 416.90 | STA | 416.90 | \$140.00 | \$58,366.00 |
| | | 0001 | 0260 | 2151000A | SHAPING SLOPES, CLASS I | 2.00 | 0.00 | 2.00 | 100F | 2.00 | \$1,120.00 | \$2,240.00 |
| | | 0001 | 0270 | 2159903 | MISC.MODIFIED, SHAPING SLOPES, CLASS III | 600.00 | 0.00 | 600.00 | LF | 600.00 | \$12.00 | \$7,200.00 |
| | | 0001 | 0280 | 3102002 | CRUSHED STONE (B) | 21.00 | 0.00 | 21.00 | TONS | 21.00 | \$255.00 | \$5,355.00 |
| | | 0001 | 0290 | 4020520 | BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) | 4,898.40 | -73.10 | 4,825.30 | TONS | 4,825.30 | \$72.45 | \$349,592.98 |
| | | 0001 | 0300 | 4071005 | TACK COAT | 5,357.00 | -1,757.00 | 3,600.00 | GAL | 3,600.00 | \$2.35 | \$8,460.00 |
| | | 0001 | 0310 | 4091048 | EMULSIFIED ASPHALT, SEAL COAT | 11,679.00 | 39,710.40 | 51,389.40 | GAL | 51,389.40 | \$2.60 | \$133,612.44 |
| | | 0001 | 0320 | 4094001 | SEAL COAT AGGREGATE, GRADE A1 | 116,794.00 | 0.00 | 116,794.00 | SQYD | 116,794.00 | \$0.85 | \$99,274.90 |
| | | 0001 | 0330 | 6133020 | FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR | 2,707.80 | -40.40 | 2,667.40 | TONS | 2,679.90 | \$95.50 | \$255,930.45 |
| | | 0001 | 0340 | 6133021 | REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR | 16,198.00 | -1,319.80 | 14,878.20 | SQYD | 14,878.20 | \$7.45 | \$110,842.59 |
| | | 0001 | 0350 | 6161047 | TYPE III OBJECT MARKER | 16.00 | 0.00 | 16.00 | EA | 16.00 | \$200.00 | \$3,200.00 |
| | | 0001 | 0360 | 6169901 | MISC.TEMPORARY TRAFFIC CONTROL | 1.00 | 0.00 | 1.00 | LS | 0.75 | \$20,000.00 | \$15,000.00 |
| | | 0001 | 0370 | 6169902 | MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN, CONTRACTOR FURNISHED AND RETAINED | 4.00 | 0.00 | 4.00 | EA | 4.00 | \$1,000.00 | \$4,000.00 |
| | | 0001 | 0380 | 6181000 | MOBILIZATION | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$90,000.00 | \$90,000.00 |
| | | 0001 | 0390 | 6206000C | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | 142,032.00 | 0.00 | 142,032.00 | LF | 142,032.00 | \$0.12 | \$17,043.84 |
| | | 0001 | 0400 | 6206001C | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | 142,032.00 | 0.00 | 142,032.00 | LF | 142,032.00 | \$0.13 | \$18,464.16 |
| | | 0001 | 0410 | 6206124A | 24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | 40.00 | 0.00 | 40.00 | LF | 40.00 | \$5.00 | \$200.00 |
| | | 0001 | 0420 | 6224010 | MODIFIED COLDMILLING (DEPTH TRANSITIONS) | 2,022.00 | 0.00 | 2,022.00 | SQYD | 2,022.00 | \$5.00 | \$10,110.00 |
| | | 0010 | 0430 | 6061061 | MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING | 375.00 | 0.00 | 375.00 | LF | 362.50 | \$28.00 | \$10,150.00 |



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate) Note: Posted Quantities and Values are based on Report Generat

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract Nm.CONTRACT | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTED To Date (See report generated date) |
|---|----------------|----------|-------------|--------------|--|-----------------|------------------------|------------------------------|------|------------------------------------|----------------|--|
| 200320-F06 | J6S3420 | 0010 | 0440 | 6062303 | ASYMMETRICAL TRANSITION SECTION, 6.5 FT. POSTS | 4.00 | 0.00 | 4.00 | EA | 4.00 | \$600.00 | \$2,400.00 |
| | | 0010 | 0450 | 6063014 | TYPE A CRASHWORTHY END TERMINAL (MASH) | 4.00 | 0.00 | 4.00 | EA | 4.00 | \$2,900.00 | \$11,600.00 |
| | | 0001 | 5001 | 6139905 | | 0.00 | 28.00 | 28.00 | SQYD | 0.00 | \$252.95 | \$0.00 |
| Project J6S3420 - Total Value Posted to Date as of Report Generated Date | | | | | | | | | | \$1,214,917.36 | | |
| 200320-F06 Overall - Total Value Posted to Date as of Report Generated Date | | | | | | | | | | | \$2,294,918.86 | |



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J6M0276

| Line Number | ltem Code | Description | DWR Date | DWR Approval Date | Quantity Posted | Units | Location | From Station/ Log Mile | Offset/ Distance | To Station/ Log Mile | Offset/ Distance | Comments |
|----------------|--------------|--|-------------|-------------------------|--------------------|-------|--|---------------------------------|---------------------|-------------------------------|---------------------|----------|
| 0110 | 6206000C | 4 IN. WHITE WATERBORNE PAVEMENT MARKING | 7/6/20 | 7/15/20 | 56,021.00 | LF | Route Y from Route E to Route YY both directions | 0.00 | | 5.305 | | |
| 0120 | 6206001C | 4 IN. YELLOW WATERBORNE PAVEMENT MARKING | 7/6/20 | 7/15/20 | 56,021.00 | LF | Route Y from Route E to Route YY both directions | 0.00 | | 5.305 | | |
| 0130 | 6206124A | 24 IN. WHITE WATERBORNE PAVEMENT MARKING | 7/6/20 | 7/15/20 | 12.00 | LF | On route Y at route E | 0.00 | | 5.305 | | |

Project: J6S3420

| Line Number | ltem Code | Description | DWR Date | DWR Approval Date | Quantity Posted | Units | Location | From Station/ Log Mile | Offset/ Distance | To Station/ Log Mile | Offset/ Distance | Comments |
|----------------|--------------|--|-------------|-------------------------|--------------------|-------|---|---------------------------------|---------------------|-------------------------------|---------------------|----------|
| 0350 | 6161047 | TYPE III OBJECT MARKER | 7/9/20 | 7/13/20 | 16.00 | EA | 12 installed at bridge 0489 over Cedar Fork Creek. 4 installed at the Box Culvert at Brook Ridge Lane. | 5.305 | | 14.785 | | |
| 0390 | 6206000C | 4 IN. WHITE WATERBORNE PAVEMENT MARKING | 7/6/20 | 7/15/20 | 100,320.00 | LF | Route Y from Route YY to Route 50 both directions | 5.305 | | 14.785 | | |
| 0400 | 6206001C | 4 IN. YELLOW WATERBORNE PAVEMENT MARKING | 7/6/20 | 7/15/20 | 100,320.00 | LF | Route Y from Route YY to Route 50 both directions. | 5.305 | | 14.785 | | |
| 0410 | 6206124A | 24 IN. WHITE WATERBORNE PAVEMENT MARKING | 7/6/20 | 7/15/20 | 16.00 | LF | Route Y at route 50 | 0.00 | | 14.785 | | |

The information below this line are details from Line Item agency views. No Agency View Details Exist

Revision 4/1/2020



| Line | Description | Adjustment Type | Other Adjustment | Est. Number | Created Date | Created By | Amount | Remarks |
|------|--|--------------------|------------------------|---------------------|--|------------------|---|---|
| 0030 | CRUSHED STONE (B) | Material | Туре | 3 | Jun 2, 2020 | SYSTEM | (\$20,800.00) | |
| | | | | 3 | Jun 2, 2020 | SYSTEM | \$20,800.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user bowmam2 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | 4 | Jun 16, 2020 | SYSTEM | (\$20,800.00) | |
| | | | | 4 | Jun 16, 2020 | SYSTEM | \$20,800.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user bowmam2 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | 5 | Jul 1, 2020 | SYSTEM | (\$20,800.00) | |
| | | | | 5 | Jul 1, 2020 | SYSTEM | \$20,800.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user bowmam2 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | 6 | Jul 16, 2020 | SYSTEM | (\$20,800.00) | |
| | | | | 6 | Jul 16, 2020 | SYSTEM | \$20,800.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user bowmam2 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| | CRUSHED STONE (B) | Overrun | Overrun | 3 | Jun 2, 2020 | SYSTEM | (\$10,400.00) | |
| | | | | 3 | Jun 2, 2020 | SYSTEM | \$10,400.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 19 on the current Payment Estimate. |
| | | | | 3 | Jun 2, 2020 | BOWMAM2 | (\$10,400.00) | Over-run adjustment. |
| | | | | 4 | Jun 16, 2020 | SYSTEM | (\$10,400.00) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). |
| | | | | 4 | Jun 16, 2020 | SYSTEM | \$10,400.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 17 on the current Payment Estimate. |
| | | Overrun - Total | | | | (\$10,400.00) | | |
| | Overrun - Total | | | | | | (\$10,400.00) | |
| 030 | - Total | | | | | | (\$10,400.00) | |
| 040 | BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) | Material | | 3 | Jun 2, 2020 | SYSTEM | (\$490,728.00) | |
| | | | | 3 | Jun 2, 2020 | SYSTEM | \$490,728.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user bowmam2 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| | | | | | | | | |
| | - Total | | | | | | \$0.00 | |
| | Total FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH | Overrun | Overrun | | Jun 2, 2020 | SYSTEM | (\$54,712.56) | |
| | FURNISHING AND PLACING BITUMINOUS MATERIAL FOR | Overrun | | 5 | | SYSTEM SYSTEM | (\$54,712.56) \$54,712.56 | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',112.30000 - 112.30000, 'is applied (if non-zero). |
| | FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR | Overrun | Overrun Overrun - T | 5 | 2020 Jul 1, | | (\$54,712.56) \$54,712.56 \$0.00 | quantity on all previous payment estimates. Price Adjustments of |
| 060 | FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR | Overrun | | 5 | 2020 Jul 1, | | (\$54,712.56) \$54,712.56 \$0.00 \$0.00 | quantity on all previous payment estimates. Price Adjustments of |
| 060 | FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR Overrun - Total Total REMOVAL FOR CLASS C PARTIAL | Overrun | | 5 otal | 2020 Jul 1, 2020 Jun 2, | | (\$54,712.56) \$54,712.56 \$0.00 | quantity on all previous payment estimates. Price Adjustments of |
| 060 | FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR Overrun - Total | | Overrun - T | 5 otal | 2020 Jul 1, 2020 | SYSTEM | (\$54,712.56) \$54,712.56 \$0.00 \$0.00 \$0.00 | quantity on all previous payment estimatés. Price Adjustments of ',112.30000 - 112.30000, 'is applied (if non-zero). Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of |
| 060 | FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR Overrun - Total Total REMOVAL FOR CLASS C PARTIAL | | Overrun - T | 5 otal 3 5 | 2020 Jul 1, 2020 Jun 2, 2020 Jul 1, | SYSTEM | (\$54,712.56) \$54,712.56 \$0.00 \$0.00 \$0.00 (\$17,588.25) | quantity on all previous payment estimatés. Price Adjustments of ',112.30000 - 112.30000, 'is applied (if non-zero). Unit price based on averaged overrun adjustments for installed |



| Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | | |
|--------|---|--------------------------|-----------------------------|----------------|-----------------|--------------|------------------|---|--------|-------------|
| 0070 - | Total | | | | | | \$0.00 | | | |
| 0110 | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | Other Item Adjustment | REFL | 6 | Jul 16, 2020 | BOWMAM2 | (\$1,344.50) | Holding 20% of contract price , waiting on retro reflectivity results. | | |
| | | | REFL - Tota | ıl | | | (\$1,344.50) | | | |
| | Other Item Adjustment - Total | | | | | (\$1,344.50) | | | | |
| 0110 - | Total | | | | | | (\$1,344.50) | | | |
| 0120 | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | Other Item Adjustment | REFL | 6 | Jul 16, 2020 | BOWMAM2 | (\$1,456.55) | Holding 20% of contract price , waiting on retro reflectivity results. | | |
| | | | REFL - Total | | | | (\$1,456.55) | | | |
| | Other Item Adjustment - Total | | | | | | (\$1,456.55) | | | |
| 0120 - | Total | | | | | | (\$1,456.55) | | | |
| 0130 | 24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT TYPE P BEADS | Material | | 6 | Jul 16, 2020 | SYSTEM | (\$60.00) | | | |
| | MARKING PAINT, TYPE P BEADS | | | 6 | Jul 16, 2020 | SYSTEM | \$60.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user bowmam2 overridding Payment Estimate Exception 17 on the current Payment Estimate. | | |
| | | | - Total | | | | \$0.00 | | | |
| | Material - Total | | | | | | \$0.00 | | | |
| 0130 - | Total | | | | | | \$0.00 | | | |
| 0170 | MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB) | | | 4 | Jun 16, 2020 | SYSTEM | (\$12,200.00) | | | |
| | | | | 4 | Jun 16, 2020 | SYSTEM | \$12,200.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user bowmam2 overridding Payment Estimate Exception 5 on the current Payment Estimate. | | |
| | | | | 5 | Jul 1, 2020 | SYSTEM | (\$12,200.00) | | | |
| | | | | | | | 5 | Jul 1, 2020 | SYSTEM | \$12,200.00 |
| | | | | 6 | Jul 16, 2020 | SYSTEM | (\$12,200.00) | | | |
| | | | | 6 | Jul 16, 2020 | SYSTEM | \$12,200.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user bowmam2 overridding Payment Estimate Exception 13 on the current Payment Estimate. | | |
| | | | - Total | | | | \$0.00 | | | |
| | Material - Total | | | | | | \$0.00 | | | |
| 0170 - | Total | | | | _ | | \$0.00 | | | |
| 0180 | TYPE A CRASHWORTHY END TERMINAL (MASH) | Material | | 4 | Jun 16, 2020 | SYSTEM | (\$11,200.00) | | | |
| | | | | 4 | Jun 16, 2020 | SYSTEM | \$11,200.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user bowmam2 overridding Payment Estimate Exception 7 on the current Payment Estimate. | | |
| | | | | 5 | Jul 1, 2020 | SYSTEM | (\$11,200.00) | | | |
| | | | | 5 | Jul 1, 2020 | SYSTEM | \$11,200.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user bowmam2 overridding Payment Estimate Exception 15 on the current Payment Estimate. | | |
| | | | | 6 | Jul 16, 2020 | SYSTEM | (\$11,200.00) | | | |
| | | | | 6 | Jul 16, 2020 | SYSTEM | \$11,200.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user bowmam2 overridding Payment Estimate Exception 15 on the current Payment Estimate. | | |
| | | | | | | | | | | |
| | | | - Total | | | | \$0.00 | | | |
| | Material - Total | | - Total | | | | \$0.00 \$0.00 | | | |
| 0180 - | | | - Total | | | | | | | |



| Line | Description | Adjustment | Other | Est. | Created | Created By | Amount | Remarks |
|-----------------------|-------------------------------|------------|--------------------|--------|-----------------|------------|---------------|---|
| | | Туре | Adjustment Type | Number | Date | | | |
| 0210 | CONCRETE (HPC) OVERLAY | Adjustment | | | 2020 | | | |
| | | | SUBI - Tota | l | | | (\$30,000.00) | |
| 0040 | Other Item Adjustment - Total | | | | | | (\$30,000.00) | |
| 0210 - 0230 | CLEAN AND EPOXY SEAL | Material | | 2 | May 18, | SYSTEM | (\$30,000.00) | |
| 0230 | CLEAN AND EFOXT SEAL | Material | | 2 | 2020 | STOTEIN | (\$5,160.00) | |
| | | | | 2 | May 18, 2020 | SYSTEM | \$5,180.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user bowmam2 overridding Payment Estimate Exception 12 on the current Payment Estimate. |
| | | | | 3 | Jun 2, 2020 | SYSTEM | (\$5,180.00) | |
| | | | | 3 | Jun 2, 2020 | SYSTEM | \$5,180.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user bowmam2 overridding Payment Estimate Exception 18 on the current Payment Estimate. |
| | | | | 4 | Jun 16, 2020 | SYSTEM | (\$10,500.60) | |
| | | | | 4 | Jun 16, 2020 | SYSTEM | \$10,500.60 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user bowmam2 overridding Payment Estimate Exception 16 on the current Payment Estimate. |
| | | | | 5 | Jul 1, 2020 | SYSTEM | (\$10,500.60) | |
| | | | | 5 | Jul 1, 2020 | SYSTEM | \$10,500.60 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user bowmam2 overridding Payment Estimate Exception 24 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0230 - | - Total | | | | | | \$0.00 | |
| 0280 | CRUSHED STONE (B) | Material | | 2 | May 18, 2020 | SYSTEM | (\$5,355.00) | |
| | | | | 2 | May 18, 2020 | SYSTEM | \$5,355.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user bowmam2 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | 3 | Jun 2, 2020 | SYSTEM | (\$5,355.00) | |
| | | | | 3 | Jun 2, 2020 | SYSTEM | \$5,355.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user bowmam2 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | 4 | Jun 16, 2020 | SYSTEM | (\$5,355.00) | |
| | | | | 4 | Jun 16, 2020 | SYSTEM | \$5,355.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user bowmam2 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | 5 | Jul 1, 2020 | SYSTEM | (\$5,355.00) | |
| | | | | 5 | Jul 1, 2020 | SYSTEM | \$5,355.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user bowmam2 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | 6 | Jul 16, 2020 | SYSTEM | (\$5,355.00) | |
| | | | | 6 | Jul 16, 2020 | SYSTEM | \$5,355.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user bowmam2 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | | | Total | | | | | |
| | Material - Total | | rotur | | | | \$0.00 | |
| | - Total | | Total | | | | \$0.00 | |
| 0280 - 0290 | | Material | - Cui | 1 | May 4, 2020 | SYSTEM | | |



| Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|--------|---|--------------------|-----------------------------|----------------|-----------------|------------|----------------|--|
| 0290 | BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) | Material | | | 2020 | | | Payment Estimate Item Adjustment (0001) due to user bowmam2 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | 2 | May 18, 2020 | SYSTEM | (\$354,889.08) | |
| | | | | 2 | May 18, 2020 | SYSTEM | \$354,889.08 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user bowmam2 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | 3 | Jun 2, 2020 | SYSTEM | (\$349,592.98) | |
| | | | | 3 | Jun 2, 2020 | SYSTEM | \$349,592.98 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user bowmam2 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0290 - | | Meterial | | 4 | Maria | OVOTEN | \$0.00 | |
| 0300 | TACK COAT | Material | | 1 | May 4, 2020 | SYSTEM | (\$8,692.65) | |
| | | | | 1 | May 4, 2020 | SYSTEM | \$8,692.65 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user bowmam2 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | 2 | May 18, 2020 | SYSTEM | (\$11,280.00) | |
| | | | | 2 | May 18, 2020 | SYSTEM | \$11,280.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user bowmam2 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | 3 | Jun 2, 2020 | SYSTEM | (\$8,460.00) | |
| | | | | 3 | Jun 2, 2020 | SYSTEM | \$8,460.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user bowmam2 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | 4 | Jun 16, 2020 | SYSTEM | (\$8,460.00) | |
| | | | | 4 | Jun 16, 2020 | SYSTEM | \$8,460.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user bowmam2 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | 5 | Jul 1, 2020 | SYSTEM | (\$8,460.00) | |
| | | | | 5 | Jul 1, 2020 | SYSTEM | \$8,460.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user bowmam2 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | 6 | Jul 16, 2020 | SYSTEM | (\$8,460.00) | |
| | | | | 6 | Jul 16, 2020 | SYSTEM | \$8,460.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user bowmam2 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0300 - | | Motorial | | 5 | Jul 4 | OVOTEM | \$0.00 | |
| 0310 | EMULSIFIED ASPHALT, SEAL COAT | Material | | 5 | Jul 1, 2020 | SYSTEM | (\$133,612.44) | |
| | | | | 5 | Jul 1, 2020 | SYSTEM | \$133,612.44 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user bowmam2 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | 6 | Jul 16, 2020 | SYSTEM | (\$133,612.44) | |
| | | | | 6 | Jul 16, 2020 | SYSTEM | \$133,612.44 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user bowmam2 overridding Payment Estimate Exception 4 on the current Payment Estimate. |



| Line | Description | Adjustment | Other | Est. | Created | Created By | Amount | Remarks |
|------|--|--------------------------|--------------------|--------------------------------------|--|--|--|---|
| | | Туре | Adjustment Type | Number | Date | | | |
| 0310 | | Material | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0310 | - Total | | | | | | \$0.00 | |
| 0320 | SEAL COAT AGGREGATE, GRADE A1 | Material | | 5 | Jul 1, 2020 | SYSTEM | (\$99,274.90) | |
| | | | | 5 | Jul 1, 2020 | SYSTEM | \$99,274.90 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user bowmam2 overridding Payment Estimate Exception 11 on the current Payment Estimate. |
| | | | | 6 | Jul 16, 2020 | SYSTEM | (\$99,274.90) | |
| | | | | 6 | Jul 16, 2020 | SYSTEM | \$99,274.90 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user bowmam2 overridding Payment Estimate Exception 11 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 320 | - Total | | | | | | \$0.00 | |
| 330 | FURNISHING AND PLACING BITUMINOUS MATERIAL FOR | Overrun | Overrun | 5 | Jul 1, 2020 | SYSTEM | (\$1,193.75) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). |
| | CLASS C PARTIAL DEPTH PAVEMENT REPAIR | | | 5 | Jul 1, 2020 | SYSTEM | \$1,193.75 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user bowmam2 overridding Payment Estimate Exception 25 on the current Payment Estimate. |
| | | | | 6 | Jul 16, 2020 | SYSTEM | (\$1,193.75) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). |
| | | | | 6 | Jul 16, 2020 | SYSTEM | \$1,193.75 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user bowmam2 overridding Payment Estimate Exception 19 on the current Payment Estimate. |
| | Overrun - Total | | | | | | \$0.00 | |
| | Overrun - Total | | | | | | \$0.00 | |
| 330 | - Total | | | | | | \$0.00 | |
| 390 | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | Material | | 2 | May 18, 2020 | SYSTEM | (\$5,005.44) | |
| | | | | 2 | May 18, | | | |
| | | | | | 2020 | SYSTEM | \$5,005.44 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user bowmam2 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | 3 | | SYSTEM | \$5,005.44 (\$5,005.44) | Payment Estimate Item Adjustment (0005) due to user bowmam2 overridding Payment Estimate Exception 5 on the current Payment |
| | | | | 3 | 2020 Jun 2, | | | Payment Estimate Item Adjustment (0005) due to user bowmam2 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user bowmam2 |
| | | | | | 2020 Jun 2, 2020 Jun 2, | SYSTEM | (\$5,005.44) | Payment Estimate Item Adjustment (0005) due to user bowmam2 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user bowmam2 overridding Payment Estimate Exception 11 on the current Payment |
| | | | | 3 | 2020 Jun 2, 2020 Jun 2, 2020 Jun 16, | SYSTEM SYSTEM | (\$5,005.44) \$5,005.44 | Payment Estimate Item Adjustment (0005) due to user bowmam2 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user bowmam2 overridding Payment Estimate Exception 11 on the current Payment |
| | | | | 3 | 2020 Jun 2, 2020 Jun 2, 2020 Jun 16, 2020 Jun 16, | SYSTEM SYSTEM SYSTEM | (\$5,005.44) \$5,005.44 (\$5,005.44) | Payment Estimate Item Adjustment (0005) due to user bowmam2 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user bowmam2 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user bowmam2 overridding Payment Estimate Exception 9 on the current Payment |
| | | | | 3 4 4 | 2020 Jun 2, 2020 Jun 2, 2020 Jun 16, 2020 Jun 16, 2020 Jun 1, | SYSTEM SYSTEM SYSTEM SYSTEM | (\$5,005.44) \$5,005.44 (\$5,005.44) \$5,005.44 | Payment Estimate Item Adjustment (0005) due to user bowmam2 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user bowmam2 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user bowmam2 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user bowmam2 overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | | | - Total | 3 4 4 5 | 2020 Jun 2, 2020 Jun 2, 2020 Jun 16, 2020 Jun 16, 2020 Jul 1, 2020 Jul 1, | SYSTEM SYSTEM SYSTEM SYSTEM | (\$5,005.44) \$5,005.44 (\$5,005.44) \$5,005.44 (\$5,005.44) | Payment Estimate Item Adjustment (0005) due to user bowmam2 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user bowmam2 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user bowmam2 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user bowmam2 overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | Material - Total | | - Total | 3 4 4 5 | 2020 Jun 2, 2020 Jun 2, 2020 Jun 16, 2020 Jun 16, 2020 Jul 1, 2020 Jul 1, | SYSTEM SYSTEM SYSTEM SYSTEM | (\$5,005.44) \$5,005.44 (\$5,005.44) \$5,005.44 (\$5,005.44) \$5,005.44 | Payment Estimate Item Adjustment (0005) due to user bowmam2 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user bowmam2 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user bowmam2 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user bowmam2 overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT | Other Item Adjustment | - Total REFL | 3 4 4 5 | 2020 Jun 2, 2020 Jun 2, 2020 Jun 16, 2020 Jun 16, 2020 Jul 1, 2020 Jul 1, | SYSTEM SYSTEM SYSTEM SYSTEM | (\$5,005.44) \$5,005.44 (\$5,005.44) \$5,005.44 (\$5,005.44) \$5,005.44 \$5,005.44 | Payment Estimate Item Adjustment (0005) due to user bowmam2 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user bowmam2 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user bowmam2 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user bowmam2 overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | 4 IN. WHITE STANDARD | | | 3 4 4 5 5 5 | 2020 Jun 2, 2020 Jun 2, 2020 Jun 16, 2020 Jun 16, 2020 Jul 1, 2020 Jul 1, 2020 Jul 1, 2020 | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | (\$5,005.44) \$5,005.44 (\$5,005.44) \$5,005.44 (\$5,005.44) \$5,005.44 \$5,005.44 | Payment Estimate Item Adjustment (0005) due to user bowmam2 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user bowmam2 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user bowmam2 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user bowmam2 overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT | | | 3 4 4 5 5 5 2 6 | 2020 Jun 2, 2020 Jun 2, 2020 Jun 16, 2020 Jun 16, 2020 Jul 1, 2020 Jul 1, 2020 Jul 1, 2020 Jul 1, 2020 Jul 1, 2020 | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | (\$5,005.44) \$5,005.44 (\$5,005.44) \$5,005.44 (\$5,005.44) \$5,005.44 \$5,005.44 \$0.00 \$0.00 | Payment Estimate Item Adjustment (0005) due to user bowmam2 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user bowmam2 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user bowmam2 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user bowmam2 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user bowmam2 overridding Payment Estimate Exception 17 on the current Payment Estimate. |
| | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT | | REFL | 3 4 4 5 5 5 2 6 | 2020 Jun 2, 2020 Jun 2, 2020 Jun 16, 2020 Jun 16, 2020 Jul 1, 2020 Jul 1, 2020 Jul 1, 2020 Jul 1, 2020 Jul 1, 2020 | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | (\$5,005.44) \$5,005.44 (\$5,005.44) \$5,005.44 (\$5,005.44) \$5,005.44 \$5,005.44 \$5,005.44 (\$3,408.77) (\$3,408.77) | Payment Estimate Item Adjustment (0005) due to user bowmam2 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user bowmam2 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user bowmam2 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user bowmam2 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user bowmam2 overridding Payment Estimate Exception 17 on the current Payment Estimate. |



| Line | Description | Adjustment | Other | Est. | Created | Created By | Amount | Remarks |
|-------|---|--------------------------|--------------------|--------|-----------------|------------|--------------------|---|
| LINE | Description | Туре | Adjustment Type | Number | Date | Created by | Amount | I Cellidi KS |
| 0400 | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | Material | | 2 | May 18, 2020 | SYSTEM | (\$5,422.56) | |
| | | | | 2 | May 18, 2020 | SYSTEM | \$5,422.56 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user bowmam2 overridding Payment Estimate Exception 7 on the current Payment Estimate. |
| | | | | 3 | Jun 2, 2020 | SYSTEM | (\$5,422.56) | |
| | | | | 3 | Jun 2, 2020 | SYSTEM | \$5,422.56 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user bowmam2 overridding Payment Estimate Exception 13 on the current Payment Estimate. |
| | | | | 4 | Jun 16, 2020 | SYSTEM | (\$5,422.56) | |
| | | | | 4 | Jun 16, 2020 | SYSTEM | \$5,422.56 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user bowmam2 overridding Payment Estimate Exception 11 on the current Payment Estimate. |
| | | | | 5 | Jul 1, 2020 | SYSTEM | (\$5,422.56) | |
| | | | | 5 | Jul 1, 2020 | SYSTEM | \$5,422.56 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user bowmam2 overridding Payment Estimate Exception 19 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT | Other Item Adjustment | REFL | 2 | May 18, 2020 | BOWMAM2 | (\$3,692.83) | |
| | MARKING PAINT, TYPE P BEADS | | | 6 | Jul 16, 2020 | BOWMAM2 | (\$2,608.32) | Holding 20% of contract price , waiting on retro reflectivity results. |
| | | | REFL - Tota | d . | | | (\$6,301.15) | |
| | Other Item Adjustment - Total | | | | | | (\$6,301.15) | |
| 400 - | Total | | | | | | (\$6,301.15) | |
| 410 | 24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | Material | | 2 | May 18, 2020 | SYSTEM | (\$120.00) | |
| | | | | 2 | May 18, 2020 | SYSTEM | \$120.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user bowmam2 overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | | | | 3 | Jun 2, 2020 | SYSTEM | (\$120.00) | |
| | | | | 3 | Jun 2, 2020 | SYSTEM | \$120.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user bowmam2 overridding Payment Estimate Exception 15 on the current Payment Estimate. |
| | | | | 4 | Jun 16, 2020 | SYSTEM | (\$120.00) | |
| | | | | 4 | Jun 16, 2020 | SYSTEM | \$120.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user bowmam2 overridding Payment Estimate Exception 13 on the current Payment Estimate. |
| | | | | 5 | Jul 1, 2020 | SYSTEM | (\$120.00) | |
| | | | | 5 | Jul 1, 2020 | SYSTEM | \$120.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user bowmam2 overridding Payment Estimate Exception 23 on the current Payment Estimate. |
| | | | | 6 | Jul 16, 2020 | SYSTEM | (\$200.00) | |
| | | | | | | | | |
| | | | | 6 | Jul 16, 2020 | SYSTEM | \$200.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user bowmam2 overridding Payment Estimate Exception 18 on the current Payment Estimate. |
| | | | - Total | 6 | | SYSTEM | \$200.00 \$0.00 | Payment Estimate Item Adjustment (0010) due to user bowmam2 overridding Payment Estimate Exception 18 on the current Payment |
| | Material - Total | | - Total | 6 | | SYSTEM | | Payment Estimate Item Adjustment (0010) due to user bowmam2 overridding Payment Estimate Exception 18 on the current Payment |
| 410 - | Material - Total Total | | - Total | 6 | | SYSTEM | \$0.00 | Payment Estimate Item Adjustment (0010) due to user bowmam2 overridding Payment Estimate Exception 18 on the current Payment |



| Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | |
|--------|--|--------------------|---|----------------|-----------------|----------------|---------------|---|--|
| 0430 | MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING | Material | .,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, | 3 | Jun 2, 2020 | SYSTEM | \$10,150.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user bowmam2 overridding Payment Estimate Exception 7 on the current Payment Estimate. | |
| | | | | 4 | Jun 16, 2020 | SYSTEM | (\$10,150.00) | | |
| | | | | 4 | Jun 16, 2020 | SYSTEM | \$10,150.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user bowmam2 overridding Payment Estimate Exception 4 on the current Payment Estimate. | |
| | | | | 5 | Jul 1, 2020 | SYSTEM | (\$10,150.00) | | |
| | | | | 5 | Jul 1, 2020 | SYSTEM | \$10,150.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user bowmam2 overridding Payment Estimate Exception 12 on the current Payment Estimate. | |
| | | | | 6 | Jul 16, 2020 | SYSTEM | (\$10,150.00) | | |
| | | | | 6 | Jul 16, 2020 | SYSTEM | \$10,150.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user bowmam2 overridding Payment Estimate Exception 12 on the current Payment Estimate. | |
| | | | - Total | | | | \$0.00 | | |
| | Material - Total | | | | | | \$0.00 | | |
| 0430 - | | | | 0 | | 0)(0777 | \$0.00 | | |
| 0440 | 40 ASYMMETRICAL TRANSITION SECTION, 6.5 FT. POSTS | Material | Material | | 3 | Jun 2, 2020 | SYSTEM | (\$2,400.00) | |
| | | | | 3 | Jun 2, 2020 | SYSTEM | \$2,400.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user bowmam2 overridding Payment Estimate Exception 9 on the current Payment Estimate. | |
| | | | | 4 | Jun 16, 2020 | SYSTEM | (\$2,400.00) | | |
| | | | | 4 | Jun 16, 2020 | SYSTEM | \$2,400.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user bowmam2 overridding Payment Estimate Exception 6 on the current Payment Estimate. | |
| | | | | 5 | Jul 1, 2020 | SYSTEM | (\$2,400.00) | | |
| | | | | 5 | Jul 1, 2020 | SYSTEM | \$2,400.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user bowmam2 overridding Payment Estimate Exception 14 on the current Payment Estimate. | |
| | | | | 6 | Jul 16, 2020 | SYSTEM | (\$2,400.00) | | |
| | | | | 6 | Jul 16, 2020 | SYSTEM | \$2,400.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user bowmam2 overridding Payment Estimate Exception 14 on the current Payment Estimate. | |
| | | | - Total | | | | \$0.00 | | |
| | Material - Total | | | | | | \$0.00 | | |
| 0440 - | | | | | | | \$0.00 | | |
| 0450 | TYPE A CRASHWORTHY END TERMINAL (MASH) | Material | | 3 | Jun 2, 2020 | SYSTEM | (\$11,600.00) | | |
| | | | | 3 | Jun 2, 2020 | SYSTEM | \$11,600.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user bowmam2 overridding Payment Estimate Exception 10 on the current Payment Estimate. | |
| | | | | 4 | Jun 16, 2020 | SYSTEM | (\$11,600.00) | | |
| | | | | 4 | Jun 16, 2020 | SYSTEM | \$11,600.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user bowmam2 overridding Payment Estimate Exception 8 on the current Payment Estimate. | |
| | | | | 5 | Jul 1, 2020 | SYSTEM | (\$11,600.00) | | |
| | | | | 5 | Jul 1, 2020 | SYSTEM | \$11,600.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user bowmam2 overridding Payment Estimate Exception 16 on the current Payment | |



| Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|--------|------------------------|--------------------|-----------------------------|----------------|-----------------|---------------|---------------|---|
| 0450 | TYPE A CRASHWORTHY END | Material | | | | | | Estimate. |
| | TERMINAL (MASH) | | | 6 | Jul 16, 2020 | SYSTEM | (\$11,600.00) | |
| | | | | 6 | Jul 16, 2020 | SYSTEM | \$11,600.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user bowmam2 overridding Payment Estimate Exception 16 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0450 · | - Total | | | | | | \$0.00 | |
| Overa | all - Total | | | | | (\$55,318.65) | | |