73.42%



Missouri Department of Transportation Contractor's Pay Estimate Summary

August 6, 2021

Pay Estimate Created Date: September 16, 2020

Progress Estimate Number	Contract ID	200320-F09	Pay Period Start	September 2, 2020	Original Contract Amount	\$3,384,741.53
9	Prime Contractor	N.B. West Contracting Company	Pay Period End	September 15, 2020	Net Change Order Amount Current Contract Amount	(\$11,962.39) \$3,372,779.14

Original Comp	letion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amou	nt Complete
September 18, 2020		F	Reviewed and Approved at the Cen	tral Office Controllers Office Level by	greggd1
September 16, 2020		Reviewed and Appro	ved (and should be considered Dra	ft) at the Resident Engineer Level by	vancef1
September 16, 2020		Generated and A	approved (and should be considered	d Draft) at the Project Office Level by	fullek2
Approval Date					By User

No Milestones Exist for Contract

August 6, 2021

Contract Total Pa	y For Estimate No. 9			
		This Estimate	Previous	To Date
200320-F09				
	Total Posted Items Pay	\$0.00	\$2,476,416.59	\$2,476,416.59
	Gross Item Adjustments	\$0.00	\$17,785.28	\$17,785.28
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	•		\$2,494,201.87	\$2,494,201.87
Contract Total Pa	yable This Estimate:	\$0.00		

Items Paid This Estimate Period

No Data Available

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6S3240	0100	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material			-307	\$5.00	(\$1,535.00)
	0100	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0011) due to user fullerk2 overridding Payment Estimate Exception 1 on the current Payment Estimate.	307	\$5.00	\$1,535.00
	0110	GRAVEL (A) OR CRUSHED STONE (B)	Material			-93.89	\$33.00	(\$3,098.37)
	0110	GRAVEL (A) OR CRUSHED STONE (B)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0012) due to user fullerk2 overridding Payment Estimate Exception 3 on the current Payment Estimate.	93.89	\$33.00	\$3,098.37
	0150	CONCRETE GUTTER TYPE A	Material			-8	\$200.00	(\$1,600.00)
	0150	CONCRETE GUTTER TYPE A	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0013) due to user fullerk2 overridding Payment Estimate Exception 7 on the current Payment Estimate.	8	\$200.00	\$1,600.00
	0160	CURB AND GUTTER TYPE B	Material			-105	\$40.00	(\$4,200.00)
	0160	CURB AND GUTTER TYPE B	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0014) due to user fullerk2 overridding Payment Estimate Exception 10 on the current Payment Estimate.	105	\$40.00	\$4,200.00

Revision 4/1/2020 Page 1 of 32



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: September 16, 2020

Pay Period **Progress Estimate** September 2, 2020 Original Contract Amount \$3,384,741.53 **Contract ID** 200320-F09 Number Start Pay Period End September 15, 2020 Prime N.B. West Contracting **Net Change Order** 9 (\$11,962.39) Contractor Company Amount **Current Contract Amount** \$3,372,779.14

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6S3240	0210	FURNISHING TYPE 1 ROCK BLANKET	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-25	\$38.00	(\$950.00)
	0210	FURNISHING TYPE 1 ROCK BLANKET	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0003) due to user fullerk2 overridding Payment Estimate Exception 23 on the current Payment Estimate.	25	\$38.00	\$950.00
	0220	PLACING TYPE 1 ROCK BLANKET	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-25	\$18.00	(\$450.00)
	0220	PLACING TYPE 1 ROCK BLANKET	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0004) due to user fullerk2 overridding Payment Estimate Exception 24 on the current Payment Estimate.	25	\$18.00	\$450.00
	0340	FLOWABLE BACKFILL	Material			-21	\$300.00	(\$6,300.00)
	0340	FLOWABLE BACKFILL	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0015) due to user fullerk2 overridding Payment Estimate Exception 14 on the current Payment Estimate.	21	\$300.00	\$6,300.00
	0370	SUBSURFACE DRAINAGE GEOTEXTILE	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-45	\$5.00	(\$225.00)
	0370	SUBSURFACE DRAINAGE GEOTEXTILE	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0001) due to user fullerk2 overridding Payment Estimate Exception 21 on the current Payment Estimate.	45	\$5.00	\$225.00
	0430	30 IN. PIPE GROUP A	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-5	\$240.00	(\$1,200.00)
	0430	30 IN. PIPE GROUP A	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0002) due to user fullerk2 overridding Payment Estimate Exception 22 on the current Payment Estimate.	5	\$240.00	\$1,200.00
J6S3421	0710	GRAVEL (A) OR CRUSHED STONE (B)	Material			-470.4	\$40.00	(\$18,816.00)
	0710	GRAVEL (A) OR CRUSHED STONE (B)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0016) due to user fullerk2 overridding Payment Estimate Exception 2 on the current Payment Estimate.	470.4	\$40.00	\$18,816.00
	0750	6 IN. CONCRETE MEDIAN STRIP	Material			-113	\$64.00	(\$7,232.00)
	0750	6 IN. CONCRETE MEDIAN STRIP	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0017) due to user fullerk2 overridding Payment Estimate Exception 4 on the current Payment Estimate.	113	\$64.00	\$7,232.00
	0870	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-8	\$25.00	(\$200.00)

Revision 4/1/2020 Page 2 of 32



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: September 16, 2020

Pay Period **Progress Estimate** September 2, 2020 Original Contract Amount \$3,384,741.53 **Contract ID** 200320-F09 Number Start Pay Period End September 15, 2020 Prime N.B. West Contracting **Net Change Order** 9 (\$11,962.39) Contractor Company Amount Current Contract Amount \$3,372,779.14

et Lir		Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
21 087	PREFORMEI THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINI TRIANGLES) 		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0005) due to user fullerk2 overridding Payment Estimate Exception 25 on the current Payment Estimate.	8	\$25.00	\$200.00
088	6 IN. WHITE HIGH BUILT WATERBORNE PAVEMEN MARKING PAINT, TYPE BEADS	Г -		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-516	\$0.25	(\$129.00
088	6 IN. WHITE HIGH BUILT WATERBORNE PAVEMEN MARKING PAINT, TYPE BEADS	Г -		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0006) due to user fullerk2 overridding Payment Estimate Exception 26 on the current Payment Estimate.	516	\$0.25	\$129.0
089	00 6 IN. YELLOW HIGH BUILI WATERBORNE PAVEMEN' MARKING PAINT, TYPE BEADS	Г -		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-46	\$0.25	(\$11.5
089	00 6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMEN MARKING PAINT, TYPE BEADS	Г -		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0007) due to user fullerk2 overridding Payment Estimate Exception 27 on the current Payment Estimate.	46	\$0.25	\$11.5
092	PAVEMENT MARKING REMOVAL (SYMBOLS			Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-4	\$20.00	(\$80.0
092	PAVEMENT MARKING REMOVAL (SYMBOLS			This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0008) due to user fullerk2 overridding Payment Estimate Exception 28 on the current Payment Estimate.	4	\$20.00	\$80.0
107	CONDUIT, 3 IN. RIGID PUSHEI			Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-7	\$17.25	(\$120.7
107	CONDUIT, 3 IN. RIGID PUSHEI			This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0009) due to user fullerk2 overridding Payment Estimate Exception 29 on the current Payment Estimate.	7	\$17.25	\$120.7
111	0 SH-FLAT SHEET - SIGNA SIGN				-15	\$96.62	(\$1,449.3
11	0 SH-FLAT SHEET - SIGNA SIGN			This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0018) due to user fullerk2 overridding Payment Estimate Exception 15 on the current Payment Estimate.	15	\$96.62	\$1,449.3
113	POST, SIGNAL 8 FT. OR 2.				-1	\$807.00	(\$807.0
113	POST, SIGNAL 8 FT. OR 2.			This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0019) due to user fullerk2 overridding Payment Estimate Exception 16 on the current Payment Estimate.	1	\$807.00	\$807.0
117	70 CABLE, LOOP DETECTOR IN DUC			Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-486	\$5.46	(\$2,653.5
117	O CABLE, LOOP DETECTOR			This adjustment offsets the original system- generated Overrun Payment Estimate Item	486	\$5.46	\$2,653.5

Revision 4/1/2020 Page 3 of 32



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: September 16, 2020

	Progre	ess Estimate Number	Contract ID Prime Contractor	200320-F0 N.B. West Company	09 Contracting	Pay Period End 2020 An	et Change Ore	dor	\$11,962.39)
Project Number	Line No.	Item Description		Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6S3421						Adjustment (0010) due to user fullerk2 overridding Payment Estimate Exception 30 on the current Payment Estimate.			
	1180	BAS	SE, CONCRETE	Material			-1.3	\$4,530.00	(\$5,889.00
	1180	BAS	SE, CONCRETE	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0020) due to user fullerk2 overridding Payment Estimate Exception 18 on the current Payment Estimate.	1.3	\$4,530.00	\$5,889.00
Total									\$0.00

Revision 4/1/2020 Page 4 of 32



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

						Contract Project Information	
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J6S3240	FAS- S501(096)	Coldmill, resurface, & drainage	I-55	JEFFERSON	from Route M to R	oute Z	
J6S3421	FAS S502(34)	Resurface and ADA improvements	I-55	JEFFERSON	from Vogel Road to	o end of maintenance and Imp	perial Main Street from OR 55 to Old
Totals by .	Job Number	s					
J6S3240					This Estimate	Previous	To Date
		Item Pay Item Adjustmen	ts Gross Ito	em Pav	\$0.00 \$0.00 \$0.00	\$1,465,490.61 (\$2,825.00) \$1,462,665.61	\$1,465,490.61 (\$2,825.00) \$1,462,665.61
	Incenti	ve	0.000	J u.y	\$0.00	\$0.00	\$0.00
	Disince	entive ated Damages			\$0.00 \$0.00	\$0.00 \$0.00	\$0.00 \$0.00
		Contract Adjusti	ments		\$0.00	\$0.00	\$0.00
J6S3421					This Estimate	Previous	To Date
		Item Pay Item Adjustmen	ite		\$0.00 \$0.00	\$1,010,925.98 \$20.610.28	\$1,010,925.98 \$20.610.28
	51033		Gross It	em Pay	\$0.00	\$1,031,536.26	\$1,031,536.26
	Incenti				\$0.00	\$0.00	\$0.00
	Disince	entive ated Damages			\$0.00 \$0.00	\$0.00 \$0.00	\$0.00 \$0.00
		contract Adjusti	ments		\$0.00	\$0.00	\$0.00

Revision 4/1/2020 Page 5 of 32



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6S3240, Item 3040504, Project Item Line Number 0100, Material Set 304050496, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Waiting on material approval.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3421, Item 3105002, Project Item Line Number 0710, Material Set 310500296, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Waiting on material approval.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3240, Item 3105002, Project Item Line Number 0110, Material Set 310500296, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Waiting on material approval.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3421, Item 6083006, Project Item Line Number 0750, Material Set 608300696, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on material approval.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3421, Item 6083006, Project Item Line Number 0750, Material Set 608300696, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Waiting on material approval.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3421, Item 6083006, Project Item Line Number 0750, Material Set 608300696, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Waiting on material approval.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3240, Item 6091041, Project Item Line Number 0150, Material Set 609104196, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on material approval.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3240, Item 6091041, Project Item Line Number 0150, Material Set 609104196, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Waiting on material approval.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3240, Item 6091041, Project Item Line Number 0150, Material Set 609104196, Material 1036RSDFPL42M13 - Reinforcing Steel No. 4/M13 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Waiting on material approval.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3240, Item 6091052, Project Item Line Number 0160, Material Set 609105296, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on material approval.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3240, Item 6091052, Project Item Line Number 0160, Material Set 609105296, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Waiting on material approval.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3240, Item 6091052, Project Item Line Number 0160, Material Set 609105296, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Waiting on material approval.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3240, Item 6091052, Project Item Line Number 0160, Material Set 609105296, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Waiting on material approval.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3240, Item 6214600A, Project Item Line Number 0340, Material Set 6214600A96, Material 0621FB - Flowable Backfill, Acceptance Action Generic 0621FB is insufficient.	Waiting on material approval.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3421, Item 9020833, Project Item Line Number 1110, Material Set 902083396, Material 1042SM - Sign Material, Acceptance Action Generic 1042SM is insufficient.	Waiting on material approval.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3421, Item 9022708, Project Item Line Number 1130, Material Set 902270896, Material 0902TSBTZCAB - Bolts Galv Anchor for Traffic Signals, Acceptance Action Generic 0902TSBTZCAB is insufficient.	Waiting on material approval.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3421, Item 9022708, Project Item Line Number 1130, Material Set 902270896, Material 1092TSPS - Traffic Signal Post(s) - All Types, Acceptance Action Generic 1092TSPS is insufficient.	Waiting on material approval.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3421, Item 9029100, Project Item Line Number 1180, Material Set 902910096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Waiting on material approval.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3421, Item 9029100, Project Item Line Number 1180, Material Set 902910096, Material 1036RSDFPL42M13 - Reinforcing Steel No. 4/M13 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Waiting on material approval.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3421, Item 9029100, Project Item Line Number 1180, Material Set 902910096, Material 1036RSDFPL42M19 - Reinforcing Steel No. 6/M19 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Waiting on material approval.	fullek2	Overridden
Estimate Exception Type: Item Overrun: Contract 200320-F09, Contract Project J6S3240, Project Item Line Number 0370, Contract Line Item Number 0370, Item 6240101A, Minor Item.	Pending change order.	fullek2	Overridden
Estimate Exception Type: Item Overrun: Contract 200320-F09, Contract Project J6S3240, Project Item Line Number 0430, Contract Line Item Number 0430, Item 7261030, Minor Item.	Pending change order.	fullek2	Overridden
Estimate Exception Type: Item Overrun: Contract 200320-F09, Contract Project J6S3240, Project Item Line Number 0210, Contract Line Item Number 0210, Item 6113010, Minor Item.	Pending change order.	fullek2	Overridden
Estimate Exception Type: Item Overrun: Contract 200320-F09, Contract Project J6S3240, Project Item Line Number 0220, Contract Line Item Number 0220, Item 6113030, Minor Item.	Pending change order.	fullek2	Overridden
Estimate Exception Type: Item Overrun: Contract 200320-F09, Contract Project J6S3421, Project Item Line Number 0870, Contract Line Item Number 0870, Item 6200042, Minor Item.	Pending change order.	fullek2	Overridden

Revision 4/1/2020 Page 6 of 32



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Item Overrun: Contract 200320-F09, Contract Project J6S3421, Project Item Line Number 0880, Contract Line Item Number 0880, Item 6205902A, Minor Item.	Pending change order.	fullek2	Overridden
Estimate Exception Type: Item Overrun: Contract 200320-F09, Contract Project J6S3421, Project Item Line Number 0890, Contract Line Item Number 0890, Item 6205903A, Minor Item.	Pending change order.	fullek2	Overridden
Estimate Exception Type: Item Overrun: Contract 200320-F09, Contract Project J6S3421, Project Item Line Number 0920, Contract Line Item Number 0920, Item 6207002, Minor Item.	Pending change order.	fullek2	Overridden
Estimate Exception Type: Item Overrun: Contract 200320-F09, Contract Project J6S3421, Project Item Line Number 1070, Contract Line Item Number 1070, Item 9014003, Minor Item.	Pending change order.	fullek2	Overridden
Estimate Exception Type: Item Overrun: Contract 200320-F09, Contract Project J6S3421, Project Item Line Number 1170, Contract Line Item Number 1170, Item 9028500, Minor Item.	Pending change order.	fullek2	Overridden

Revision 4/1/2020 Page 7 of 32



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200320-F09	J6S3240	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$158,200.00	\$158,200.00
		0001	0020	2031000	CLASS A EXCAVATION	309.00	0.00	309.00	CUYD	309.00	\$24.00	\$7,416.00
		0001	0030	2035500	EMBANKMENT IN PLACE	257.00	0.00	257.00	CUYD	257.00	\$36.00	\$9,252.00
		0001	0040	2036000	COMPACTING EMBANKMENT	263.00	0.00	263.00	CUYD	263.00	\$5.00	\$1,315.00
		0001	0050	2063000	CLASS 3 EXCAVATION	1,524.00	0.00	1,524.00	CUYD	1,524.00	\$0.01	\$15.24
		0001	0060	2063500	CULVERT CLEANOUT	7.00	-5.00	2.00	EA	2.00	\$800.00	\$1,600.00
		0001	0070	2072000	LINEAR GRADING CLASS 2	2.30	0.00	2.30	STA	2.30	\$1,440.00	\$3,312.00
		0001	0080	2129900	MISC.Shouldering	377.00	0.00	377.00	100F	0.00	\$100.00	\$0.00
		0001	0090	2159903	MISC.MODIFIED SHAPING SLOPES, CLASS III	4,400.00	0.00	4,400.00	LF	4,360.00	\$8.00	\$34,880.00
		0001	0100	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	355.00	0.00	355.00	SQYD	307.00	\$5.00	\$1,535.00
		0001	0110	3105002	GRAVEL (A) OR CRUSHED STONE (B)	293.00	0.00	293.00	TONS	93.89	\$33.00	\$3,098.37
		0001	0120	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	7,051.10	0.00	7,051.10	TONS	0.00	\$73.50	\$0.00
		0001	0130	4013000	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	144.70	0.00	144.70	TONS	133.43	\$200.00	\$26,686.00
		0001	0140	4071005	TACK COAT	7,446.00	0.00	7,446.00	GAL	0.00	\$1.96	\$0.00
		0001	0150	6091041	CONCRETE GUTTER TYPE A	8.00	0.00	8.00	LF	8.00	\$200.00	\$1,600.00
		0001	0160	6091052	CURB AND GUTTER TYPE B	105.00	0.00	105.00	LF	105.00	\$40.00	\$4,200.00
		0001	0170	6091060	PAVED DITCH	5.00	0.00	5.00	SQYD	0.00	\$200.00	\$0.00
		0001	0180	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	89.00	0.00	89.00	CUYD	89.00	\$45.00	\$4,005.00
		0001	0190	6096041	PLACING TYPE 1 ROCK DITCH LINER	89.00	0.00	89.00	CUYD	89.00	\$26.00	\$2,314.00
		0001	0200	6097000	ROCK LINING	109.00	0.00	109.00	CUYD	74.00	\$145.00	\$10,730.00
		0001	0210	6113010	FURNISHING TYPE 1 ROCK BLANKET	532.00	229.00	761.00	CUYD	786.00	\$38.00	\$29,868.00
		0001	0220	6113030	PLACING TYPE 1 ROCK BLANKET	532.00	229.00	761.00	CUYD	786.00	\$18.00	\$14,148.00
		0001	0230	6169901	MISC.TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.75	\$62,000.00	\$46,500.00
		0001	0240	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN, CONTRACTOR FURNISHED/RETAINED	6.00	0.00	6.00	EA	6.00	\$1,000.00	\$6,000.00
		0001	0250	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$128,000.00	\$128,000.00
		0001	0260	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	128.00	0.00	128.00	LF	0.00	\$20.00	\$0.00
		0001	0270	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	88.00	0.00	88.00	LF	0.00	\$20.00	\$0.00
		0001	0280	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	12.00	0.00	12.00	EA	0.00	\$280.00	\$0.00
		0001	0290	6200027	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT	2.00	0.00	2.00	EA	0.00	\$500.00	\$0.00
		0001	0300	6200042	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	49.00	0.00	49.00	EA	0.00	\$25.00	\$0.00
		0001	0310	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	45,414.00	0.00	45,414.00	LF	0.00	\$0.20	\$0.00
		0001	0320	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	36,714.00	0.00	36,714.00	LF	0.00	\$0.20	\$0.00
		0001	0330	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	34.00	0.00	34.00	EA	0.00	\$20.00	\$0.00
		0001	0340	6214600A	FLOWABLE BACKFILL	21.00	0.00	21.00	CUYD	21.00	\$300.00	\$6,300.00
		0001	0350	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	64,741.00	0.00	64,741.00	SQYD	0.00	\$1.05	\$0.00
		0001	0360	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	9,381.00	0.00	9,381.00	SQYD	0.00	\$3.35	\$0.00
		0001	0370	6240101A	SUBSURFACE DRAINAGE GEOTEXTILE	1,311.00	0.00	1,311.00	SQYD	1,356.00	\$5.00	\$6,780.00
		0001	0380	6249905	MISC.Installing High Performance Geotextile	1,852.00	0.00	1,852.00	SQYD	1,852.00	\$1.00	\$1,852.00
		0001	0390	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.75	\$5,000.00	\$3,750.00
		0001	0400	7252019	CORRUGATED METALLIC-COATED STEEL PIPE-ARCH TYPE B-19/B-19A	119.00	0.00	119.00	LF	119.00	\$680.00	\$80,920.00
		0001	0410	7261018	18 IN. PIPE GROUP A	59.00	0.00	59.00	LF	59.00	\$220.00	\$12,980.00
		0001	0420	7261024	24 IN. PIPE GROUP A	158.00	0.00	158.00	LF	158.00	\$230.00	\$36,340.00
		0001	0430	7261030	30 IN. PIPE GROUP A	148.00	0.00	148.00	LF	153.00	\$240.00	\$36,720.00
		0001	0440	7261036	36 IN. PIPE GROUP A	169.00	0.00	169.00	LF	169.00	\$250.00	\$42,250.00

Page 8 of 32 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT					eport Generated date and can differ from the posted am							
WII.GONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200320-F09	J6S3240	0001	0450	7265430	JACKED 30 IN. CLASS V REINFORCED CONCRETE PIPE CULVERT (GASKET TYPE)	173.00	0.00	173.00	LF	173.00	\$1,120.00	\$193,760.00
		0001	0460	7320618A	18 IN, OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	1.00	0.00	1.00	EA	1.00	\$1,100.00	\$1,100.00
		0001	0470	7320624A	24 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	4.00	0.00	4.00	EA	4.00	\$1,200.00	\$4,800.00
		0001	0480	7320630A	30 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	5.00	0.00	5.00	EA	5.00	\$1,400.00	\$7,000.00
		0001	0490	7320636A	36 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	3.00	0.00	3.00	EA	3.00	\$1,750.00	\$5,250.00
		0001	0500	7321014A	18 IN. OR ALLOWED SUBSTITUTE SAFETY SLOPE END SECTION	1.00	0.00	1.00	EA	1.00	\$1,500.00	\$1,500.00
		0001	0510	7321017A	30 IN, OR ALLOWED SUBSTITUTE SAFETY SLOPE END SECTION	1.00	0.00	1.00	EA	1.00	\$2,500.00	\$2,500.00
		0001	0520	7321018A	36 IN. OR ALLOWED SUBSTITUTE SAFETY SLOPE END SECTION	1.00	0.00	1.00	EA	1.00	\$3,200.00	\$3,200.00
		0001	0530	7359903	MISC.PIPE LINER FOR EXISTING 18 IN. CULVERT	98.00	-98.00	0.00	LF	0.00	\$90.00	\$0.00
		0001	0540	7359903	MISC.PIPE LINER FOR EXISTING 36 IN. CULVERT	261.00	-261.00	0.00	LF	0.00	\$120.00	\$0.00
		0001	0550	7359903	MISC.PIPE LINER FOR EXISTING 42 IN. CULVERT	125.00	-125.00	0.00	LF	0.00	\$160.00	\$0.00
		0001	0560	7359903	MISC.PIPE LINER FOR EXISTING 48 IN. CULVERT	91.00	-91.00	0.00	LF	0.00	\$200.00	\$0.00
		0001	0570	8051000A	SEEDING - COOL SEASON MIXTURES	1.70	0.00	1.70	ACRE	0.80	\$5,500.00	\$4,400.00
		0001	0580	8061005	ROCK DITCH CHECK	510.00	0.00	510.00	LF	225.00	\$25.00	\$5,625.00
		0001	0590	8061006	ALTERNATE DITCH CHECK	426.00	0.00	426.00	LF	0.00	\$12.00	\$0.00
		0001	0600	8061016	SEDIMENT REMOVAL	472.00	0.00	472.00	CUYD	0.00	\$0.01	\$0.00
		0001	0610	8061017	TEMPORARY SEEDING AND MULCHING	0.80	0.00	0.80	ACRE	0.00	\$0.01	\$0.00
		0001	0620	8061019	SILT FENCE	1,799.00	0.00	1,799.00	LF	685.00	\$4.00	\$2,740.00
		0010	0630	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	15,563.00	0.00	15,563.00	LF	15,563.00	\$23.00	\$357,949.00
		0010	0640	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	2.00	0.00	2.00	EA	2.00	\$3,000.00	\$6,000.00
		0010	0650	6061080	MGS END ANCHOR	3.00	1.00	4.00	EA	4.00	\$1,000.00	\$4,000.00
		0010	0660	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	55.00	-1.00	54.00	EA	54.00	\$2,650.00	\$143,100.00
		0030	0670	9028500	CABLE, LOOP DETECTOR, IN DUCT	350.00	0.00	350.00	LF	0.00	\$7.19	\$0.00
		0050	0680	9109903	MISC.MoDOT ITS Assets Relocation	200.00	0.00	200.00	LF	0.00	\$11.50	\$0.00
	Project J	6S3240 - To	otal Value	Posted to D	ate as of Report Generated Date		0.00	1.00	LS			\$1,465,490.61
	1653421	0001	0690	2022010		1 00					\$27.561.00	
	J6S3421	0001	0690	2022010		1.00	0.00			0.30	\$27,561.00	
	J6S3421	0001	0700	2159903	MISC.MODIFIED, SHAPING SLOPES, CLASS III	1,749.00	0.00	1,749.00	LF	0.00	\$8.00	\$0.00
	J6S3421	0001	0700 0710	2159903 3105002	MISC.MODIFIED, SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B)	1,749.00 501.00	0.00	1,749.00 501.00	LF	0.00	\$8.00 \$40.00	\$0.00 \$18,816.00
	J6S3421	0001	0700 0710 0720	2159903 3105002 4020520	MISC.MODIFIED, SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	1,749.00 501.00 4,886.90	0.00 936.85	1,749.00 501.00 5,823.75	LF TONS TONS	0.00 470.40 5,823.75	\$8.00 \$40.00 \$83.50	\$0.00 \$18,816.00 \$486,283.12
	J6S3421	0001	0700 0710 0720 0730	2159903 3105002 4020520 4071005	MISC.MODIFIED, SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT	1,749.00 501.00 4,886.90 7,348.00	0.00 936.85 237.00	1,749.00 501.00 5,823.75 7,585.00	LF TONS TONS GAL	0.00 470.40 5,823.75 7,585.00	\$8.00 \$40.00 \$83.50 \$1.96	\$0.00 \$18,816.00 \$486,283.12 \$14,866.60
	J6S3421	0001 0001 0001	0700 0710 0720	2159903 3105002 4020520	MISC.MODIFIED, SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	1,749.00 501.00 4,886.90	0.00 936.85	1,749.00 501.00 5,823.75	LF TONS TONS	0.00 470.40 5,823.75	\$8.00 \$40.00 \$83.50	\$0.00 \$18,816.00 \$486,283.12 \$14,866.60 \$4,650.00
	J6S3421	0001 0001 0001 0001	0700 0710 0720 0730	2159903 3105002 4020520 4071005	MISC.MODIFIED, SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT	1,749.00 501.00 4,886.90 7,348.00	0.00 936.85 237.00	1,749.00 501.00 5,823.75 7,585.00	LF TONS TONS GAL	0.00 470.40 5,823.75 7,585.00	\$8.00 \$40.00 \$83.50 \$1.96	\$0.00 \$18,816.00 \$486,283.12 \$14,866.60 \$4,650.00
	J6S3421	0001 0001 0001 0001 0001	0700 0710 0720 0730 0740	2159903 3105002 4020520 4071005 6081012	MISC.MODIFIED, SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT TRUNCATED DOMES	1,749.00 501.00 4,886.90 7,348.00	0.00 936.85 237.00 13.00	1,749.00 501.00 5,823.75 7,585.00	TONS TONS GAL SQFT	0.00 470.40 5,823.75 7,585.00	\$8.00 \$40.00 \$83.50 \$1.96 \$30.00	\$0.00 \$18,816.00 \$486,283.12 \$14,866.60 \$4,650.00
	J6S3421	0001 0001 0001 0001 0001	0700 0710 0720 0730 0740 0750	2159903 3105002 4020520 4071005 6081012 6083006	MISC.MODIFIED, SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT TRUNCATED DOMES 6 IN. CONCRETE MEDIAN STRIP	1,749.00 501.00 4,886.90 7,348.00 142.00 300.00	0.00 936.85 237.00 13.00 -187.00	1,749.00 501.00 5,823.75 7,585.00 155.00	LF TONS TONS GAL SQFT SQYD	0.00 470.40 5,823.75 7,585.00 155.00	\$8.00 \$40.00 \$83.50 \$1.96 \$30.00 \$64.00	\$0.00 \$18,816.00 \$486,283.12 \$14,866.60 \$4,650.00 \$7,232.00 \$3,000.00
	J6S3421	0001 0001 0001 0001 0001 0001	0700 0710 0720 0730 0740 0750	2159903 3105002 4020520 4071005 6081012 6083006 6089902	MISC.MODIFIED, SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT TRUNCATED DOMES 6 IN. CONCRETE MEDIAN STRIP MISC.ADA CURB RAMP FURNISHING AND PLACING BITUMINOUS MATERIAL FOR	1,749.00 501.00 4,886.90 7,348.00 142.00 300.00	0.00 936.85 237.00 13.00 -187.00	1,749.00 501.00 5,823.75 7,585.00 155.00 113.00	LF TONS TONS GAL SQFT SQYD EA	0.00 470.40 5,823.75 7,585.00 155.00 113.00	\$8.00 \$40.00 \$83.50 \$1.96 \$30.00 \$64.00	\$0.00 \$18,816.00 \$486,283.12 \$14,866.60 \$4,650.00 \$7,232.00 \$3,000.00
	J6S3421	0001 0001 0001 0001 0001 0001 0001	0700 0710 0720 0730 0740 0750 0760	2159903 3105002 4020520 4071005 6081012 6083006 6089902 6133020	MISC.MODIFIED, SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT TRUNCATED DOMES 6 IN. CONCRETE MEDIAN STRIP MISC.ADA CURB RAMP FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	1,749.00 501.00 4,886.90 7,348.00 142.00 300.00 1.00 1,070.30	0.00 936.85 237.00 13.00 -187.00 0.00	1,749.00 501.00 5,823.75 7,585.00 155.00 113.00 1.00	LF TONS TONS GAL SQFT SQYD EA TONS	0.00 470.40 5,823.75 7,585.00 155.00 113.00 1.00	\$8.00 \$40.00 \$83.50 \$1.96 \$30.00 \$64.00 \$3,000.00	\$0.00 \$18,816.00 \$486,283.12 \$14,866.60 \$4,650.00 \$7,232.00 \$3,000.00 \$65,956.94
	J6S3421	0001 0001 0001 0001 0001 0001 0001 000	0700 0710 0720 0730 0740 0750 0760 0770	2159903 3105002 4020520 4071005 6081012 6083006 6089902 6133020	MISC.MODIFIED, SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT TRUNCATED DOMES 6 IN. CONCRETE MEDIAN STRIP MISC.ADA CURB RAMP FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	1,749.00 501.00 4,886.90 7,348.00 142.00 300.00 1.00 1,070.30 6,526.00	0.00 936.85 237.00 13.00 -187.00 0.00 -178.99	1,749.00 501.00 5,823.75 7,585.00 155.00 1.00 891.31 5,731.00	LF TONS TONS GAL SQFT SQYD EA TONS	0.00 470.40 5,823.75 7,585.00 155.00 113.00 1.00 891.31 5,731.00	\$8.00 \$40.00 \$83.50 \$1.96 \$30.00 \$64.00 \$74.00	\$0.00 \$18,816.00 \$486,283.12 \$14,866.60 \$4,650.00 \$7,232.00 \$3,000.00 \$65,956.94 \$74,503.00
	J6S3421	0001 0001 0001 0001 0001 0001 0001 000	0700 0710 0720 0730 0740 0750 0760 0770 0780	2159903 3105002 4020520 4071005 6081012 6083006 6089902 6133020 6133021 6161070	MISC.MODIFIED, SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT TRUNCATED DOMES 6 IN. CONCRETE MEDIAN STRIP MISC.ADA CURB RAMP FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR TUBULAR MARKER	1,749.00 501.00 4,886.90 7,348.00 142.00 300.00 1.070.30 6,526.00	0.00 936.85 237.00 13.00 -187.00 0.00 -178.99 -795.00	1,749.00 501.00 5,823.75 7,585.00 155.00 113.00 891.31 5,731.00	LF TONS TONS GAL SQFT SQYD EA TONS SQYD EA	0.00 470.40 5,823.75 7,585.00 155.00 113.00 1.00 891.31 5,731.00	\$8.00 \$40.00 \$83.50 \$1.96 \$30.00 \$64.00 \$74.00 \$13.00 \$80.00	\$0.00 \$18,816.00 \$486,283.12 \$14,866.60 \$4,650.00 \$7,232.00 \$3,000.00 \$65,956.94 \$74,503.00 \$19,000.00
	J6S3421	0001 0001 0001 0001 0001 0001 0001 000	0700 0710 0720 0730 0740 0750 0760 0770 0780 0790	2159903 3105002 4020520 4071005 6081012 6083006 6089902 6133020 6133021 6161070 6169901	MISC.MODIFIED, SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT TRUNCATED DOMES 6 IN. CONCRETE MEDIAN STRIP MISC.ADA CURB RAMP FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR TUBULAR MARKER MISC.Temporary Traffic Control MISC.NTCIP COMPLIANT CHANGEABLE SIGN, CONTRACTOR	1,749.00 501.00 4,886.90 7,348.00 142.00 300.00 1,070.30 6,526.00 12.00	0.00 936.85 237.00 13.00 -187.00 0.00 -178.99 -795.00 0.00	1,749.00 501.00 5,823.75 7,585.00 155.00 113.00 891.31 5,731.00 12.00	LF TONS TONS GAL SQFT SQYD EA TONS SQYD EA LS	0.00 470.40 5.823.75 7,585.00 155.00 113.00 1.00 891.31 5,731.00 0.00 0.95	\$8.00 \$40.00 \$83.50 \$1.96 \$30.00 \$64.00 \$3,000.00 \$74.00 \$13.00 \$80.00	\$0.00 \$18,816.00 \$486,283.12 \$14,866.60 \$4,650.00 \$7,232.00 \$3,000.00 \$65,956.94 \$74,503.00 \$19,000.00
	J6S3421	0001 0001 0001 0001 0001 0001 0001 000	0700 0710 0720 0730 0740 0750 0760 0770 0780 0790 0800	2159903 3105002 4020520 4071005 6081012 6083006 6089902 6133020 6133021 6161070 6169901 6169902	MISC.MODIFIED, SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT TRUNCATED DOMES 6 IN. CONCRETE MEDIAN STRIP MISC.ADA CURB RAMP FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR TUBULAR MARKER MISC.Temporary Traffic Control MISC.NTCIP COMPLIANT CHANGEABLE SIGN, CONTRACTOR FURNISH/RETAINED	1,749.00 501.00 4,886.90 7,348.00 142.00 300.00 1.00 1,070.30 6,526.00 12.00 4.00	0.00 936.85 237.00 13.00 -187.00 0.00 -178.99 -795.00 0.00 0.00	1,749.00 501.00 5,823.75 7,585.00 155.00 113.00 1.00 891.31 5,731.00 12.00 1.00 4.00	LF TONS TONS GAL SQFT SQYD EA TONS SQYD EA LS	0.00 470.40 5.823.75 7,585.00 155.00 113.00 1.00 891.31 5,731.00 0.00 0.95	\$8.00 \$40.00 \$83.50 \$1.96 \$30.00 \$64.00 \$3,000.00 \$74.00 \$80.00 \$20,000.00	\$0.00 \$18,816.00 \$486,283.12 \$14,866.60 \$4,650.00 \$7,232.00 \$3,000.00 \$65,956.94 \$74,503.00 \$118,000.00
	J6S3421	0001 0001 0001 0001 0001 0001 0001 000	0700 0710 0720 0730 0740 0750 0760 0770 0780 0790 0800 0810	2159903 3105002 4020520 4071005 6081012 6083006 6089902 6133020 6133021 6161070 6169901 6169902 6181000	MISC.MODIFIED, SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT TRUNCATED DOMES 6 IN. CONCRETE MEDIAN STRIP MISC.ADA CURB RAMP FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR TUBULAR MARKER MISC.Temporary Traffic Control MISC.NTCIP COMPLIANT CHANGEABLE SIGN, CONTRACTOR FURNISH/RETAINED MOBILIZATION PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN.	1,749.00 501.00 4,886.90 7,348.00 142.00 300.00 1.00 1,070.30 6,526.00 12.00 4.00 1.00	0.00 936.85 237.00 13.00 -187.00 0.00 -178.99 -795.00 0.00 0.00	1,749.00 501.00 5,823.75 7,585.00 155.00 113.00 1.00 891.31 5,731.00 12.00 1.00 4.00	LF TONS TONS GAL SQFT SQYD EA TONS SQYD EA LS LS	0.00 470.40 5,823.75 7,585.00 155.00 113.00 1.00 891.31 5,731.00 0.00 0.95 4.00	\$8.00 \$40.00 \$83.50 \$1.96 \$30.00 \$64.00 \$3,000.00 \$74.00 \$80.00 \$20,000.00 \$118,000.00	\$8,268.30 \$0.00 \$18,816.00 \$486,283.12 \$14,866.60 \$4,650.00 \$7,232.00 \$3,000.00 \$65,956.94 \$74,503.00 \$0.00 \$118,000.00 \$9,100.00
	J6S3421	0001 0001 0001 0001 0001 0001 0001 000	0700 0710 0720 0730 0740 0750 0760 0770 0780 0800 0810	2159903 3105002 4020520 4071005 6081012 6083006 6089902 6133020 6133021 6161070 6169901 6169902 6181000 6200015	MISC.MODIFIED, SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT TRUNCATED DOMES 6 IN. CONCRETE MEDIAN STRIP MISC.ADA CURB RAMP FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR TUBULAR MARKER MISC.Temporary Traffic Control MISC.NTCIP COMPLIANT CHANGEABLE SIGN, CONTRACTOR FURNISHIRETAINED MOBILIZATION PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN.	1,749.00 501.00 4,886.90 7,348.00 142.00 300.00 1,070.30 6,526.00 12.00 4.00 4.00 4.00	0.00 936.85 237.00 13.00 -187.00 0.00 -178.99 -795.00 0.00 0.00 0.00	1,749.00 501.00 5,823.75 7,585.00 113.00 1.00 891.31 5,731.00 12.00 4.00 4.00 464.00	LF TONS TONS GAL SQFT SQYD EA TONS SQYD EA LS LS	0.00 470.40 5,823.75 7,585.00 155.00 113.00 1.00 891.31 5,731.00 0.00 0.95 4.00	\$8.00 \$40.00 \$83.50 \$1.96 \$30.00 \$64.00 \$3,000.00 \$74.00 \$80.00 \$20,000.00 \$118,000.00	\$0.00 \$18,816.00 \$486,283.12 \$14,866.60 \$4,650.00 \$7,232.00 \$3,000.00 \$65,956.94 \$74,503.00 \$0.00 \$19,000.00 \$41,000.00 \$118,000.00

Page 9 of 32 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200320-F09	J6S3421	0001	0870	6200042	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	49.00	0.00	49.00	EA	57.00	\$25.00	\$1,425.00
		0001	0880	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	1,417.00	0.00	1,417.00	LF	1,933.00	\$0.25	\$483.25
		0001	0890	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	271.00	0.00	271.00	LF	317.00	\$0.25	\$79.25
		0001	0900	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	48,807.00	-1,126.00	47,681.00	LF	47,681.00	\$0.20	\$9,536.20
		0001	0910	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	45,826.00	725.00	46,551.00	LF	46,551.00	\$0.20	\$9,310.20
		0001	0920	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	22.00	0.00	22.00	EA	26.00	\$20.00	\$520.00
		0001	0930	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	10,812.00	0.00	10,812.00	SQYD	10,812.00	\$1.90	\$20,542.80
		0001	0940	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	9,577.00	0.00	9,577.00	SQYD	9,577.00	\$2.76	\$26,432.52
		0001	0950	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	117.00	0.00	117.00	STA	117.00	\$17.00	\$1,989.00
		0001	0960	6261001	BITUMINOUS CENTERLINE RUMBLE STRIP	165.00	0.00	165.00	STA	165.00	\$27.00	\$4,455.00
		0001	0970	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$1,500.00	\$1,500.00
		0010	0980	6061060	MGS GUARDRAIL	800.00	0.00	800.00	LF	0.00	\$23.00	\$0.00
		0010	0990	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	150.00	0.00	150.00	LF	0.00	\$26.00	\$0.00
		0010	1000	6061063	MGS GUARDRAIL, 6 FT. POSTS, 3 FT 1.5 IN. SPACING	50.00	0.00	50.00	LF	0.00	\$34.00	\$0.00
		0010	1010	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	4.00	0.00	4.00	EA	0.00	\$2,900.00	\$0.00
		0010	1020	6061080	MGS END ANCHOR	5.00	0.00	5.00	EA	0.00	\$1,000.00	\$0.00
		0010	1030	6062301A	TRANSITION SECTION, 7.5 FT. POSTS	4.00	0.00	4.00	EA	0.00	\$600.00	\$0.00
		0010	1040	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	10.00	0.00	10.00	EA	0.00	\$2,800.00	\$0.00
		0020	1050	9011312	LUMINAIRE, LED-B	3.00	0.00	3.00	EA	3.00	\$404.00	\$1,212.00
		0020	1060	9011313	LUMINAIRE, LED-C	18.00	0.00	18.00	EA	18.00	\$484.00	\$8,712.00
		0020	1070	9014003	CONDUIT, 3 IN. RIGID, PUSHED	56.00	90.00	146.00	LF	153.00	\$17.25	\$2,639.25
		0020	1080	9015010	TRENCHING TYPE I	9.00	0.00	9.00	LF	0.00	\$10.30	\$0.00
		0020	1090	9015020	TRENCHING TYPE II	1.00	0.00	1.00	LF	0.00	\$11.10	\$0.00
		0030	1100	9020113	SIGNAL HEAD, TYPE 3T	1.00	0.00	1.00	EA	0.00	\$780.00	\$0.00
		0030	1110	9020833	SH-FLAT SHEET - SIGNAL SIGN	15.00	0.00	15.00	SQFT	15.00	\$96.62	\$1,449.30
		0030	1120	9020834	SIGNAL SIGN, MOUNTING HARDWARE	16.00	0.00	16.00	EA	16.00	\$17.30	\$276.80
		0030	1130	9022708	POST, SIGNAL 8 FT. OR 2.4 M	1.00	0.00	1.00	EA	1.00	\$807.00	\$807.00
		0030	1140	9028206	CABLE, 6 AWG 1 CONDUCTOR, POWER	30.00	0.00	30.00	LF	0.00	\$1.75	\$0.00
		0030	1150	9028308	CABLE, 16 AWG 2 CONDUCTOR	490.00	680.00	1,170.00	LF	1,170.00	\$1.49	\$1,743.30
		0030	1160	9028310	CABLE, 16 AWG 5 CONDUCTOR	40.00	510.00	550.00	LF	550.00	\$1.75	\$962.50
		0030	1170	9028500	CABLE, LOOP DETECTOR, IN DUCT	4,520.00	0.00	4,520.00	LF	5,006.00	\$5.46	\$27,332.76
		0030	1180	9029100	BASE, CONCRETE	1.00	0.30	1.30	CUYD	1.30	\$4,530.00	\$5,889.00
		0030	1190	9029902	MISC.APS - AUDIBLE PEDESTRIAN SIGNAL - PUSHBUTTON	16.00	0.00	16.00	EA	16.00	\$748.00	\$11,968.00
		0030	1200	9029902	MISC.COUNTDOWN PEDESTRIAN HEAD, TYPE 1S	16.00	0.00	16.00	EA	16.00	\$518.00	\$8,288.00
		0030	1210	9029902	MISC.PAD MOUNTED UPS - UNINTERRUPTIBLE POWER SUPPLY	1.00	0.00	1.00	EA	0.50	\$8,447.00	\$4,223.50
		0030	1220	9029902	MISC.PEDESTRIAN PUSH BUTTON STANCHION	5.00	7.00	12.00	EA	12.00	\$653.00	\$7,836.00
		0050	1230	9109903	MISC.MoDOT ITS Assets Relocation	1,500.00	0.00	1,500.00	LF	0.00	\$11.50	\$0.00
		0070	1240	7134000	BRIDGE GUARDRAIL (THRIE BEAM)	75.00	0.00	75.00	LF	0.00	\$200.00	\$0.00
		0001	5101	2022010	REMOVAL OF IMPROVEMENTS	0.00	1.00	1.00	LS	1.00	\$4,702.56	\$4,702.56
		0030	5102	9029901	MISC.Adjust to Grade Pullbox	0.00	1.00	1.00	LS	1.00	\$1,659.82	\$1,659.82
	Project J	6S3421 - To	otal Value	Posted to D	late as of Report Generated Date							\$1,010,925.98
200320-F09 Ove	rall - Total	Value Post	ed to Dat	e as of Repo	ort Generated Date							\$2,476,416.58

Revision 4/1/2020 Page 10 of 32



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line are details from Line Item agency views.

No Agency View Details Exist

Revision 4/1/2020 Page 11 of 32



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0030	EMBANKMENT IN PLACE	Material		7	Aug 17, 2020	SYSTEM	(\$9,252.00)	
				7	Aug 17, 2020	SYSTEM	\$9,252.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user fullerk2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0030 -	Total						\$0.00	
0040	COMPACTING EMBANKMENT	Material		7	Aug 17, 2020	SYSTEM	(\$1,315.00)	
				7	Aug 17, 2020	SYSTEM	\$1,315.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user fullerk2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0040 -	Total						\$0.00	
0100	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material		5	Jul 16, 2020	SYSTEM	(\$571.45)	
				5	Jul 16, 2020	SYSTEM	\$571.45	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user fullerk2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				6	Aug 3, 2020	SYSTEM	(\$850.95)	
				6	Aug 3, 2020	SYSTEM	\$850.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user fullerk2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				7	Aug 17, 2020	SYSTEM	(\$1,535.00)	
				7	Aug 17, 2020	SYSTEM	\$1,535.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user fullerk2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				8	Sep 1, 2020	SYSTEM	(\$1,535.00)	
				8	Sep 1, 2020	SYSTEM	\$1,535.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user fullerk2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				9	Sep 16, 2020	SYSTEM	(\$1,535.00)	
				9	Sep 16, 2020	SYSTEM	\$1,535.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user fullerk2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0100 -							\$0.00	
0110	GRAVEL (A) OR CRUSHED STONE (B)	Material		5	Jul 16, 2020	SYSTEM	(\$1,379.07)	
				5	Jul 16, 2020	SYSTEM	\$1,379.07	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user fullerk2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				6	Aug 3, 2020	SYSTEM	(\$1,913.67)	
				6	Aug 3, 2020	SYSTEM	\$1,913.67	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user fullerk2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				7	Aug 17, 2020	SYSTEM	(\$3,098.37)	
				7	Aug 17, 2020	SYSTEM	\$3,098.37	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user fullerk2 overridding Payment Estimate Exception 5 on the current Payment

Revision 4/1/2020 Page 12 of 32



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0110	GRAVEL (A) OR CRUSHED STONE	Material						Estimate.
	(B)			8	Sep 1, 2020	SYSTEM	(\$3,098.37)	
				8	Sep 1, 2020	SYSTEM	\$3,098.37	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user fullerk2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				9	Sep 16, 2020	SYSTEM	(\$3,098.37)	
				9	Sep 16, 2020	SYSTEM	\$3,098.37	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user fullerk2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0110 -	Total						\$0.00	
0150	CONCRETE GUTTER TYPE A	Material		8	Sep 1, 2020	SYSTEM	(\$1,600.00)	
				8	Sep 1, 2020	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user fullerk2 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				9	Sep 16, 2020	SYSTEM	(\$1,600.00)	
				9	Sep 16, 2020	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user fullerk2 overridding Payment Estimate Exception 7 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0150 -	Total						\$0.00	
0160	CURB AND GUTTER TYPE B	Material		8	Sep 1, 2020	SYSTEM	(\$4,200.00)	
				8	Sep 1, 2020	SYSTEM	\$4,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user fullerk2 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				9	Sep 16, 2020	SYSTEM	(\$4,200.00)	
				9	Sep 16, 2020	SYSTEM	\$4,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user fullerk2 overridding Payment Estimate Exception 10 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0160 -	Total						\$0.00	
0180	FURNISHING TYPE 1 ROCK DITCH LINER	Material		5	Jul 16, 2020	SYSTEM	(\$4,005.00)	
				5	Jul 16, 2020	SYSTEM	\$4,005.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user fullerk2 overridding Payment Estimate Exception 11 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0180 -	Total						\$0.00	
0200	ROCK LINING	Material		3	Jun 16, 2020	SYSTEM	(\$1,160.00)	
				3	Jun 16, 2020	SYSTEM	\$1,160.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user fullerk2 overridding Payment Estimate Exception 10 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0200 -	Total						\$0.00	
0210	FURNISHING TYPE 1 ROCK	Other Item	OVRN	7	Aug 17,	fullek2	(\$950.00)	Change order in progress.

Revision 4/1/2020 Page 13 of 32



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0210	BLANKET	Adjustment	.,,,,,		2020			
			OVRN - Tot	al			(\$950.00)	
	Other Item Adjustment - Total						(\$950.00)	
	FURNISHING TYPE 1 ROCK BLANKET	Overrun	Overrun	7	Aug 17, 2020	SYSTEM	(\$950.00)	
				7	Aug 17, 2020	SYSTEM	\$950.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user fullerk2 overridding Payment Estimate Exception 21 on the current Payment Estimate.
				8	Sep 1, 2020	SYSTEM	(\$950.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				8	Sep 1, 2020	SYSTEM	\$950.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user fullerk2 overridding Payment Estimate Exception 26 on the current Payment Estimate.
				9	Sep 16, 2020	SYSTEM	(\$950.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				9	Sep 16, 2020	SYSTEM	\$950.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user fullerk2 overridding Payment Estimate Exception 23 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0210 -	Total						(\$950.00)	
0220	PLACING TYPE 1 ROCK BLANKET	Other Item Adjustment	OVRN	7	Aug 17, 2020	fullek2	(\$450.00)	Change order in progress.
			OVRN - Tot	al			(\$450.00)	
	Other Item Adjustment - Total						(\$450.00)	
	PLACING TYPE 1 ROCK BLANKET	Overrun	Overrun	7	Aug 17, 2020	SYSTEM	(\$450.00)	
				7	Aug 17, 2020	SYSTEM	\$450.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user fullerk2 overridding Payment Estimate Exception 22 on the current Payment Estimate.
				8	Sep 1, 2020	SYSTEM	(\$450.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				8	Sep 1, 2020	SYSTEM	\$450.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user fullerk2 overridding Payment Estimate Exception 27 on the current Payment Estimate.
				9	Sep 16, 2020	SYSTEM	(\$450.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				9	Sep 16, 2020	SYSTEM	\$450.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user fullerk2 overridding Payment Estimate Exception 24 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0220 - 0230	Total MISC. TEMPORARY TRAFFIC	Material		1	May 18,	SYSTEM	(\$450.00)	
0230	CONTROL	ivialerial			2020		(\$15,500.00)	
				1	May 18, 2020	SYSTEM	\$15,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user burlbe overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0230 -						0)/	\$0.00	
0240	MISC. NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN, CONTRACTOR	Material		1	May 18, 2020	SYSTEM	(\$2,000.00)	
	FURNISHED/RETAINED			1	May 18, 2020	SYSTEM	\$2,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user burlbe overridding Payment Estimate Exception 7 on the current Payment Estimate.
			- Total				\$0.00	

Revision 4/1/2020 Page 14 of 32



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0240	Material - Total	,	,				\$0.00	
0240 -	- Total						\$0.00	
0340	FLOWABLE BACKFILL	Material		5	Jul 16, 2020	SYSTEM	(\$6,300.00)	
				5	Jul 16, 2020	SYSTEM	\$6,300.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user fullerk2 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				6	Aug 3, 2020	SYSTEM	(\$6,300.00)	
				6	Aug 3, 2020	SYSTEM	\$6,300.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user fullerk2 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				7	Aug 17, 2020	SYSTEM	(\$6,300.00)	
				7	Aug 17, 2020	SYSTEM	\$6,300.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user fullerk2 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				8	Sep 1, 2020	SYSTEM	(\$6,300.00)	
				8	Sep 1, 2020	SYSTEM	\$6,300.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user fullerk2 overridding Payment Estimate Exception 16 on the current Payment Estimate.
				9	Sep 16, 2020	SYSTEM	(\$6,300.00)	
				9	Sep 16, 2020	SYSTEM	\$6,300.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user fullerk2 overridding Payment Estimate Exception 14 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	- Total						\$0.00	
0370	SUBSURFACE DRAINAGE GEOTEXTILE		OVRN		Aug 17, 2020	fullek2	(\$225.00)	Change order in progress.
			OVRN - Tota	al			(\$225.00)	
	Other Item Adjustment - Total	-	_				(\$225.00)	
	SUBSURFACE DRAINAGE GEOTEXTILE	Overrun	Overrun		Aug 17, 2020	SYSTEM	(\$225.00)	
				7	Aug 17, 2020	SYSTEM	\$225.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user fullerk2 overridding Payment Estimate Exception 19 on the current Payment Estimate.
				8	Sep 1, 2020	SYSTEM	(\$225.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				8	Sep 1, 2020	SYSTEM	\$225.00	This adjustment offsets the original system-generated Overrun
					2020			Payment Estimate Item Adjustment (0001) due to user fullerk2 overridding Payment Estimate Exception 24 on the current Payment Estimate.
				9	Sep 16, 2020	SYSTEM	(\$225.00)	Payment Estimate Item Adjustment (0001) due to user fullerk2 overridding Payment Estimate Exception 24 on the current Payment
				9	Sep 16,	SYSTEM SYSTEM	(\$225.00) \$225.00	Payment Estimate Item Adjustment (0001) due to user fullerk2 overridding Payment Estimate Exception 24 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment
			Overrun - To	9	Sep 16, 2020		\$225.00 \$0.00	Payment Estimate Item Adjustment (0001) due to user fullerk2 overridding Payment Estimate Exception 24 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user fullerk2 overridding Payment Estimate Exception 21 on the current Payment
	Overrun - Total		Overrun - T	9	Sep 16, 2020		\$225.00 \$0.00 \$0.00	Payment Estimate Item Adjustment (0001) due to user fullerk2 overridding Payment Estimate Exception 24 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user fullerk2 overridding Payment Estimate Exception 21 on the current Payment
0370 - 0380	Overrun - Total - Total MISC. Installing High Performance	Material	Overrun - To	9	Sep 16, 2020		\$225.00 \$0.00	Payment Estimate Item Adjustment (0001) due to user fullerk2 overridding Payment Estimate Exception 24 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user fullerk2 overridding Payment Estimate Exception 21 on the current Payment
	- Total	Material	Overrun - To	9 otal	Sep 16, 2020 Sep 16, 2020 Jul 16, 2020	SYSTEM	\$225.00 \$0.00 \$0.00 (\$225.00) (\$1,324.00)	Payment Estimate Item Adjustment (0001) due to user fullerk2 overridding Payment Estimate Exception 24 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user fullerk2 overridding Payment Estimate Exception 21 on the current Payment Estimate.
	Total MISC. Installing High Performance	Material	Overrun - To	9 otal	Sep 16, 2020 Sep 16, 2020	SYSTEM	\$225.00 \$0.00 \$0.00 (\$225.00)	Payment Estimate Item Adjustment (0001) due to user fullerk2 overridding Payment Estimate Exception 24 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user fullerk2 overridding Payment Estimate Exception 21 on the current Payment

Revision 4/1/2020 Page 15 of 32



Main	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
Content Cont	LIIIE	Description		Adjustment				Amount	Nemans
Page	0380	MISC. Installing High Performance	Material			2020			
Material - Total So IN , PIPE GROUP A Agustinose CVRN Total CVRN To		Geotextile			6		SYSTEM	\$1,852.00	Payment Estimate Item Adjustment (0022) due to user fullerk2 overridding Payment Estimate Exception 12 on the current Payment
Output				- Total				\$0.00	
Section Sect		Material - Total						\$0.00	
Adjustment Adjustment OVERN - Total	0380 -	Total						\$0.00	
Other Item Adjustment - Total	0430	30 IN. PIPE GROUP A		OVRN	7		fullek2	(\$1,200.00)	Change order in progress.
				OVRN - Tota	al			(\$1,200.00)	
Part		Other Item Adjustment - Total						(\$1,200.00)	
Payment Estimate Item Adjustment (2002) due to user fullent		30 IN. PIPE GROUP A	Overrun	Overrun	7		SYSTEM	(\$1,200.00)	
					7		SYSTEM	\$1,200.00	Payment Estimate Item Adjustment (0002) due to user fullerk2 overridding Payment Estimate Exception 20 on the current Payment
Payment Estimate Islam Askspriant (0002) due to user fullerk2 overridding Payment Estimate Islamate Exception 2 on the current Payment Islamate Exception 2 on the Current Payment Estimate Islamate Exception 2 on the Current Payment Islamate Exception 1 on the Current Payment Payment Payment Islamate Exception 1 on the Current Payment Payment					8		SYSTEM	(\$1,200.00)	
Part					8		SYSTEM	\$1,200.00	Payment Estimate Item Adjustment (0002) due to user fullerk2 overridding Payment Estimate Exception 25 on the current Payment
Payment Estimate Item Adjustment (0002) due to user fullence coveridating Payment Estimate Exception 22 on the current Payment Estimate Exception 23 on the current Payment Estimate Exception 24 on the current Payment Estimate Exception 14 on the current Payment Estimate Item Adjustment (0003) due to user fullence current Payment Estimate Item Adjustment (0003) due to user fullence current Payment Indicated Payment Estimate Exception 14 on the current Payment Indicated Payment Estimate Exception 14 on the current Payment Indicated Payment Estimate Exception 14 on the current Payment Indicated Payment Estimate Exception 15 on the current Payment Indicated Payment Estimate Exception 15 on the current Payment Indicated Payment Estimate Exception 17 on the current Payment Indicated Payment Estimate Exception 17 on the current Payment Indicated Payment Estimate Exception 17 on the current Payment Indicated Payment Estimate Exception 17 on the current Payment Indicated Payment Estimate Exception 17 on the current Payment Indicated Payment Estimate Exception 17 on the current Payment Indicated Payment Estimate Exception 17 on the current Payment Indicated Ind					9		SYSTEM	(\$1,200.00)	
					9		SYSTEM	\$1,200.00	Payment Estimate Item Adjustment (0002) due to user fullerk2 overridding Payment Estimate Exception 22 on the current Payment
				Overrun - T	otal			\$0.00	
		Overrun - Total						\$0.00	
SAFETY SLOPE END SECTION 2020 5	0430 -	Total						(\$1,200.00)	
Payment Estimate Item Adjustment (0003) due to user fuller\(\frac{2}{2}\) overridding Payment Estimate Exception 14 on the current Payment Estimate. S0.00	0520		Material		5		SYSTEM	(\$3,200.00)	
Source S					5		SYSTEM	\$3,200.00	Payment Estimate Item Adjustment (0003) due to user fullerk2 overridding Payment Estimate Exception 14 on the current Payment
SEEDING - COOL SEASON MIXTURES 8 Sep 1, 2020 SYSTEM \$4,400.00				- Total				\$0.00	
SEEDING - COOL SEASON MIXTURES		Material - Total						\$0.00	
2020	0520 -	Total						\$0.00	
Payment Estimate Item Adjustment (0016) due to user fullerk2 overridding Payment Estimate Exception 17 on the current Payment Estimate. Solid	0570	MINTUREO	Material		8	0000	SYSTEM	(\$4,400.00)	
Material - Total \$0.00					8		SYSTEM	\$4,400.00	Payment Estimate Item Adjustment (0016) due to user fullerk2 overridding Payment Estimate Exception 17 on the current Payment
ROCK DITCH CHECK Material 3 Jun 16, 2020				- Total				\$0.00	
ROCK DITCH CHECK Material 3 Jun 16, 2020 4 Jul 1, 2020 4 Jul 1, 2020 SYSTEM (\$2,375.00) This adjustment offsets the original system-generated Overrun Payment Estimate Exception 18 on the current Payment Estimate. 4 Jul 1, 2020 This adjustment offsets the original system-generated Overrun Payment Estimate. 5 Jul 16, SYSTEM (\$2,375.00) This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user fullerk2 overridding Payment Estimate Exception 10 on the current Payment Estimate.		Material - Total						\$0.00	
3 Jun 16, 2020 \$\frac{1}{2020}\$ \$1	0570 -	Total						\$0.00	
2020 Payment Estimate Item Adjustment (0002) due to user fullerk2 overridding Payment Estimate Exception 18 on the current Payment Estimate. 4 Jul 1, 2020 4 Jul 1, 2020 SYSTEM \$2,375.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user fullerk2 overridding Payment Estimate Exception 10 on the current Payment Estimate. 5 Jul 16, SYSTEM (\$2,875.00)	0580	ROCK DITCH CHECK	Material		3		SYSTEM	(\$2,375.00)	
4 Jul 1, 2020 \$YSTEM \$2,375.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user fullerk2 overridding Payment Estimate Exception 10 on the current Payment Estimate. 5 Jul 16, SYSTEM (\$2,875.00)					3		SYSTEM	\$2,375.00	Payment Estimate Item Adjustment (0002) due to user fullerk2 overridding Payment Estimate Exception 18 on the current Payment
2020 Payment Estimate Item Adjustment (0002) due to user fullerk2 overridding Payment Estimate Exception 10 on the current Payment Estimate. 5 Jul 16, SYSTEM (\$2,875.00)					4		SYSTEM	(\$2,375.00)	
					4		SYSTEM	\$2,375.00	Payment Estimate Item Adjustment (0002) due to user fullerk2 overridding Payment Estimate Exception 10 on the current Payment
					5		SYSTEM	(\$2,875.00)	

Revision 4/1/2020 Page 16 of 32



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
	·	Туре	Adjustment Type	Number	Date	Ву		
0580	ROCK DITCH CHECK	Material		5	Jul 16, 2020	SYSTEM	\$2,875.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user fullerk2 overridding Payment Estimate Exception 15 on the current Payment Estimate.
				6	Aug 3, 2020	SYSTEM	(\$4,375.00)	
				6	Aug 3, 2020	SYSTEM	\$4,375.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user fullerk2 overridding Payment Estimate Exception 13 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0580 -				_			\$0.00	
0620	SILT FENCE	Material		2	Jun 2, 2020	SYSTEM	(\$200.00)	
				2	Jun 2, 2020	SYSTEM	\$200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user fullerk2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				3	Jun 16, 2020	SYSTEM	(\$960.00)	
				3	Jun 16, 2020	SYSTEM	\$960.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user fullerk2 overridding Payment Estimate Exception 19 on the current Payment Estimate.
				4	Jul 1, 2020	SYSTEM	(\$960.00)	
				4	Jul 1, 2020	SYSTEM	\$960.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user fullerk2 overridding Payment Estimate Exception 11 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0620 -	Total						\$0.00	
0630	MGS GUARDRAIL, 8 FT. POSTS, 6	Construction		1	8440			
0030	FT 3 IN. SPACING			1	May 18, 2020	SYSTEM	\$157,085.95	Payment Estimate Item Adjustment generated Stockpile Transaction
0030	F1 3 IN. SPACING			2		SYSTEM	\$157,085.95 (\$27,504.93)	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
0030	F1 3 IN. SPACING				2020 Jun 2,			Payment Estimate Item Adjustment generated Stockpile Transaction
0030	F1 3 IN. SPACING			2	2020 Jun 2, 2020 Jun 16,	SYSTEM	(\$27,504.93)	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
0030	F1 3 IN. SPACING			2	2020 Jun 2, 2020 Jun 16, 2020 Jul 1,	SYSTEM SYSTEM	(\$27,504.93) (\$45,516.87)	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
0030	F1 3 IN. SPACING			2 3 4	2020 Jun 2, 2020 Jun 16, 2020 Jul 1, 2020 Jul 16,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$27,504.93) (\$45,516.87) (\$21,574.97) (\$19,934.76)	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
0030	F1 3 IN. SPACING		- Total	2 3 4 5	2020 Jun 2, 2020 Jun 16, 2020 Jul 1, 2020 Jul 16, 2020 Aug 3,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$27,504.93) (\$45,516.87) (\$21,574.97) (\$19,934.76)	Payment Estimate Item Adjustment generated Stockpile Transaction
0030	F1 3 IN. SPACING Construction Stockpile - Total		- Total	2 3 4 5	2020 Jun 2, 2020 Jun 16, 2020 Jul 1, 2020 Jul 16, 2020 Aug 3,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$27,504.93) (\$45,516.87) (\$21,574.97) (\$19,934.76) (\$42,554.42)	Payment Estimate Item Adjustment generated Stockpile Transaction
0630 -	Construction Stockpile - Total		- Total	2 3 4 5	2020 Jun 2, 2020 Jun 16, 2020 Jul 1, 2020 Jul 16, 2020 Aug 3,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$27,504.93) (\$45,516.87) (\$21,574.97) (\$19,934.76) (\$42,554.42) \$0.00	Payment Estimate Item Adjustment generated Stockpile Transaction
	Construction Stockpile - Total Total MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED		- Total	2 3 4 5	2020 Jun 2, 2020 Jun 16, 2020 Jul 1, 2020 Jul 16, 2020 Aug 3,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$27,504.93) (\$45,516.87) (\$21,574.97) (\$19,934.76) (\$42,554.42) \$0.00 \$0.00	Payment Estimate Item Adjustment generated Stockpile Transaction
0630 -	Construction Stockpile - Total Total MGS BRIDGE APPROACH	Stockpile	- Total	2 3 4 5 6	2020 Jun 2, 2020 Jun 16, 2020 Jul 1, 2020 Jul 16, 2020 Aug 3, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$27,504.93) (\$45,516.87) (\$21,574.97) (\$19,934.76) (\$42,554.42) \$0.00 \$0.00	Payment Estimate Item Adjustment generated Stockpile Transaction
0630 -	Construction Stockpile - Total Total MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED	Stockpile	- Total	2 3 4 5 6	2020 Jun 2, 2020 Jun 16, 2020 Jul 1, 2020 Jul 16, 2020 Aug 3, 2020 May 18, 2020 Aug 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$27,504.93) (\$45,516.87) (\$21,574.97) (\$19,934.76) (\$42,554.42) \$0.00 \$0.00 \$3,012.00	Payment Estimate Item Adjustment generated Stockpile Transaction
0630 -	Construction Stockpile - Total Total MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED	Stockpile		2 3 4 5 6	2020 Jun 2, 2020 Jun 16, 2020 Jul 1, 2020 Jul 16, 2020 Aug 3, 2020 May 18, 2020 Aug 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$27,504.93) (\$45,516.87) (\$21,574.97) (\$19,934.76) (\$42,554.42) \$0.00 \$0.00 \$3,012.00 (\$3,012.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
0630 -	Construction Stockpile - Total Total MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB) Construction Stockpile - Total	Stockpile		2 3 4 5 6	2020 Jun 2, 2020 Jun 16, 2020 Jul 1, 2020 Jul 16, 2020 Aug 3, 2020 May 18, 2020 Aug 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$27,504.93) (\$45,516.87) (\$21,574.97) (\$19,934.76) (\$42,554.42) \$0.00 \$0.00 \$3,012.00 (\$3,012.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
0630 - 0640	Construction Stockpile - Total Total MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB) Construction Stockpile - Total	Stockpile		2 3 4 5 6	2020 Jun 2, 2020 Jun 16, 2020 Jul 1, 2020 Jul 16, 2020 Aug 3, 2020 May 18, 2020 Aug 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$27,504.93) (\$45,516.87) (\$21,574.97) (\$19,934.76) (\$42,554.42) \$0.00 \$0.00 \$3,012.00 (\$3,012.00) \$0.00 \$0.00	Payment Estimate Item Adjustment generated Stockpile Transaction
0630 - 0640 -	Construction Stockpile - Total Total MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB) Construction Stockpile - Total Total	Construction Stockpile Construction		2 3 4 5 6	2020 Jun 2, 2020 Jun 16, 2020 Jul 11, 2020 Jul 16, 2020 Aug 3, 2020 May 18, 2020 May 18,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$27,504.93) (\$45,516.87) (\$21,574.97) (\$19,934.76) (\$42,554.42) \$0.00 \$0.00 \$3,012.00) (\$3,012.00) \$0.00 \$0.00 \$0.00	Payment Estimate Item Adjustment generated Stockpile Transaction
0630 - 0640 -	Construction Stockpile - Total Total MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB) Construction Stockpile - Total Total	Construction Stockpile Construction		2 3 4 5 6	2020 Jun 2, 2020 Jun 16, 2020 Jul 11, 2020 Jul 16, 2020 Aug 3, 2020 May 18, 2020 May 18, 2020 May 18, 2020 Jun 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$27,504.93) (\$45,516.87) (\$21,574.97) (\$19,934.76) (\$42,554.42) \$0.00 \$0.00 \$3,012.00 (\$3,012.00) \$0.00 \$0.00 \$0.00 \$0.00	Payment Estimate Item Adjustment generated Stockpile Transaction
0630 - 0640 -	Construction Stockpile - Total Total MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB) Construction Stockpile - Total Total	Construction Stockpile Construction		2 3 4 5 6	2020 Jun 2, 2020 Jun 16, 2020 Jul 1, 2020 Jul 16, 2020 Aug 3, 2020 May 18, 2020 May 18, 2020 Jun 2, 2020 Jun 2, 2020 Jun 1,	SYSTEM	(\$27,504.93) (\$45,516.87) (\$21,574.97) (\$19,934.76) (\$42,554.42) \$0.00 \$0.00 \$3,012.00) \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction

Revision 4/1/2020 Page 17 of 32



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0650 -	Total						\$0.00	
0660	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		1	May 18, 2020	SYSTEM	\$65,824.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				2	Jun 2, 2020	SYSTEM	(\$10,771.20)	Payment Estimate Item Adjustment generated Stockpile Transaction
				3	Jun 16, 2020	SYSTEM	(\$10,771.20)	Payment Estimate Item Adjustment generated Stockpile Transaction
				4	Jul 1, 2020	SYSTEM	(\$8,377.60)	Payment Estimate Item Adjustment generated Stockpile Transaction
				5	Jul 16, 2020	SYSTEM	(\$10,771.20)	Payment Estimate Item Adjustment generated Stockpile Transaction
				6	Aug 3, 2020	SYSTEM	(\$25,132.80)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
0660 -	Total						\$0.00	
0710	GRAVEL (A) OR CRUSHED STONE (B)	Material		3	Jun 16, 2020	SYSTEM	(\$18,816.00)	
				3	Jun 16, 2020	SYSTEM	\$18,816.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user fullerk2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				4	Jul 1, 2020	SYSTEM	(\$18,816.00)	
				4	Jul 1, 2020	SYSTEM	\$18,816.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user fullerk2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				5	Jul 16, 2020	SYSTEM	(\$18,816.00)	
				5	Jul 16, 2020	SYSTEM	\$18,816.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user fullerk2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				6	Aug 3, 2020	SYSTEM	(\$18,816.00)	
				6	Aug 3, 2020	SYSTEM	\$18,816.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user fullerk2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				7	Aug 17, 2020	SYSTEM	(\$18,816.00)	
				7	Aug 17, 2020	SYSTEM	\$18,816.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user fullerk2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				8	Sep 1, 2020	SYSTEM	(\$18,816.00)	
				8	Sep 1, 2020	SYSTEM	\$18,816.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user fullerk2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				9	Sep 16, 2020	SYSTEM	(\$18,816.00)	
				9	Sep 16, 2020	SYSTEM	\$18,816.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user fullerk2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0710 -	Total						\$0.00	
0720	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Material		1	May 18, 2020	SYSTEM	(\$171,923.16)	
				1	May 18, 2020	SYSTEM	\$171,923.16	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user burlbe overridding Payment Estimate Exception 1 on the current Payment Estimate.

Revision 4/1/2020 Page 18 of 32



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0720	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Material	Туре	2	Jun 2, 2020	SYSTEM	(\$486,283.12)	
	7 004 22 (0014) 702 227221140)			2	Jun 2, 2020	SYSTEM	\$486,283.12	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user fullerk2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				3	Jun 16, 2020	SYSTEM	(\$486,283.12)	
				3	Jun 16, 2020	SYSTEM	\$486,283.12	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user fullerk2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				4	Jul 1, 2020	SYSTEM	(\$486,283.12)	
				4	Jul 1, 2020	SYSTEM	\$486,283.12	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user fullerk2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				5	Jul 16, 2020	SYSTEM	(\$486,283.12)	
				5	Jul 16, 2020	SYSTEM	\$486,283.12	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user fullerk2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				6	Aug 3, 2020	SYSTEM	(\$486,283.12)	
				6	Aug 3, 2020	SYSTEM	\$486,283.12	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user fullerk2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				7	Aug 17, 2020	SYSTEM	(\$486,283.12)	
				7	Aug 17, 2020	SYSTEM	\$486,283.12	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user fullerk2 overridding Payment Estimate Exception 6 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total		- Total				\$0.00 \$0.00	
	Material - Total BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Other Item Adjustment	- Total	1	May 18, 2020	burlbe		SL 18-29 Mix ID 4.2% Virgin 2058.96 Tons Placed 05012020 to 05152020 Base = \$462.50 Current = \$420.00 Difference = -\$42.50 Total = -\$3675.24
	BITUMINOUS PAVEMENT MIXTURE		ACAD	2		buribe fullek2	\$0.00	4.2% Virgin 2058.96 Tons Placed 05012020 to 05152020 Base = \$462.50 Current = \$420.00 Difference = -\$42.50
	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)			2	2020 Jun 2,		\$0.00 (\$3,675.24) (\$6,721.44)	4.2% Virgin 2058.96 Tons Placed 05012020 to 05152020 Base = \$462.50 Current = \$420.00 Difference = -\$42.50 Total = -\$3675.24 SL 18-29 Mix ID 4.2% Virgin 3765.51 Tons Placed 05162020 to 06012020 Base = \$462.50 Current = \$420.00 Difference = -\$42.50
	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) Other Item Adjustment - Total	Adjustment	ACAD - Tot	2 al	Jun 2, 2020	fullek2	\$0.00 (\$3,675.24) (\$6,721.44) (\$10,396.68)	4.2% Virgin 2058.96 Tons Placed 05012020 to 05152020 Base = \$462.50 Current = \$420.00 Difference = -\$42.50 Total = -\$3675.24 SL 18-29 Mix ID 4.2% Virgin 3765.51 Tons Placed 05162020 to 06012020 Base = \$462.50 Current = \$420.00 Difference = -\$42.50
	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)		ACAD	2 al	Jun 2, 2020	fullek2	\$0.00 (\$3,675.24) (\$6,721.44) (\$10,396.68) (\$10,396.68) (\$78,226.98)	4.2% Virgin 2058.96 Tons Placed 05012020 to 05152020 Base = \$462.50 Current = \$420.00 Difference = -\$42.50 Total = -\$3675.24 SL 18-29 Mix ID 4.2% Virgin 3765.51 Tons Placed 05162020 to 06012020 Base = \$462.50 Current = \$420.00 Difference = -\$42.50 Total = -\$6721.44
	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) Other Item Adjustment - Total BITUMINOUS PAVEMENT MIXTURE	Adjustment	ACAD - Tot	2 al	Jun 2, 2020 Jun 2, 2020	fullek2	\$0.00 (\$3,675.24) (\$6,721.44) (\$10,396.68)	4.2% Virgin 2058.96 Tons Placed 05012020 to 05152020 Base = \$462.50 Current = \$420.00 Difference = -\$42.50 Total = -\$3675.24 SL 18-29 Mix ID 4.2% Virgin 3765.51 Tons Placed 05162020 to 06012020 Base = \$462.50 Current = \$420.00 Difference = -\$42.50
	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) Other Item Adjustment - Total BITUMINOUS PAVEMENT MIXTURE	Adjustment	ACAD - Tot	2 al	Jun 2, 2020 Jun 2, 2020 Jun 2,	fullek2	\$0.00 (\$3,675.24) (\$6,721.44) (\$10,396.68) (\$10,396.68) (\$78,226.98)	4.2% Virgin 2058.96 Tons Placed 05012020 to 05152020 Base = \$462.50 Current = \$420.00 Difference = \$42.50 Total = -\$3675.24 SL 18-29 Mix ID 4.2% Virgin 3765.51 Tons Placed 05162020 to 06012020 Base = \$462.50 Current = \$420.00 Difference = \$42.00 Difference = \$42.50 Total = -\$6721.44
	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) Other Item Adjustment - Total BITUMINOUS PAVEMENT MIXTURE	Adjustment	ACAD - Tot	2 2 2	Jun 2, 2020 Jun 2, 2020 Jun 2, 2020 Jun 2,	fullek2 SYSTEM SYSTEM	\$0.00 (\$3,675.24) (\$6,721.44) (\$10,396.68) (\$10,396.68) (\$78,226.98) \$78,226.98	4.2% Virgin 2058.96 Tons Placed 05012020 to 05152020 Base = \$462.50 Current = \$420.00 Difference = -\$42.50 Total = -\$3675.24 SL 18-29 Mix ID 4.2% Virgin 3765.51 Tons Placed 05162020 to 06012020 Base = \$462.50 Current = \$420.00 Difference = -\$42.50 Total = -\$6721.44 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 5 on the current Payment Estimate.
	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) Other Item Adjustment - Total BITUMINOUS PAVEMENT MIXTURE	Adjustment	ACAD - Tot	2 2 2 2	Jun 2, 2020 Jun 2, 2020 Jun 2, 2020 Jun 2, 2020 Jun 16,	fullek2 SYSTEM SYSTEM fullek2	\$0.00 (\$3,675.24) (\$6,721.44) (\$10,396.68) (\$10,396.68) (\$78,226.98) \$78,226.98	4.2% Virgin 2058.96 Tons Placed 05012020 to 05152020 Base = \$462.50 Current = \$420.00 Difference = -\$42.50 Total = -\$3675.24 SL 18-29 Mix ID 4.2% Virgin 3765.51 Tons Placed 05162020 to 06012020 Base = \$462.50 Current = \$420.00 Difference = -\$42.50 Total = -\$6721.44 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 5 on the current Payment Estimate. Overrun deduction. Averaged Price Adjustment from this item on all previous payment
	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) Other Item Adjustment - Total BITUMINOUS PAVEMENT MIXTURE	Adjustment	ACAD - Tot	2 2 2 2 3	Jun 2, 2020 Jun 2, 2020 Jun 2, 2020 Jun 2, 2020 Jun 16, 2020	fullek2 SYSTEM SYSTEM fullek2 SYSTEM	\$0.00 (\$3,675.24) (\$6,721.44) (\$6,721.44) (\$10,396.68) (\$78,226.98) \$78,226.98 (\$78,226.98)	4.2% Virgin 2058.96 Tons Placed 05012020 to 05152020 Base = \$462.50 Current = \$420.00 Difference = \$42.50 Total = -\$3675.24 SL 18-29 Mix ID 4.2% Virgin 3765.51 Tons Placed 05162020 to 06012020 Base = \$462.50 Current = \$420.00 Difference = -\$42.50 Total = -\$6721.44 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 5 on the current Payment Estimate. Overrun deduction. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment

Revision 4/1/2020 Page 19 of 32



	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0720	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Overrun	Overrun		2020			Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 22 on the current Payment Estimate.
				5	Jul 16, 2020	SYSTEM	(\$78,226.98)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				5	Jul 16, 2020	SYSTEM	\$78,226.98	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) overridding Payment Estimate Exception 26 on the current Payment Estimate.
				6	Aug 3, 2020	fullek2	\$78,226.98	Change Order Approved
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
	Total						(\$10,396.68)	
0730	TACK COAT	Material		1	May 18, 2020	SYSTEM	(\$5,458.60)	
				1	May 18, 2020	SYSTEM	\$5,458.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user burlbe overridding Payment Estimate Exception 2 on the current Payment Estimate.
				2	Jun 2, 2020	SYSTEM	(\$14,866.60)	
				2	Jun 2, 2020	SYSTEM	\$14,866.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user fullerk2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				3	Jun 16, 2020	SYSTEM	(\$14,866.60)	
				3	Jun 16, 2020	SYSTEM	\$14,866.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user fullerk2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				4	Jul 1, 2020	SYSTEM	(\$14,866.60)	
				4	Jul 1, 2020	SYSTEM	\$14,866.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user fullerk2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				5	Jul 16, 2020	SYSTEM	(\$14,866.60)	
				5	Jul 16, 2020	SYSTEM	\$14,866.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user fullerk2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				6	Aug 3, 2020	SYSTEM	(\$14,866.60)	
				6	Aug 3, 2020	SYSTEM	\$14,866.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user fullerk2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	TACK COAT	Overrun	Overrun	2	Jun 2,	SYSTEM	(\$464.52)	
					2020			
				2	Jun 2, 2020	SYSTEM	\$464.52	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 6 on the current Payment Estimate.
				2	Jun 2,	SYSTEM fullek2	\$464.52 (\$464.52)	Payment Estimate Item Adjustment (0007) overridding Payment
					Jun 2, 2020 Jun 2,			Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 6 on the current Payment Estimate.
				2	Jun 2, 2020 Jun 2, 2020 Jun 16,	fullek2	(\$464.52)	Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 6 on the current Payment Estimate. Overrun deduction. Averaged Price Adjustment from this item on all previous payment
				2	Jun 2, 2020 Jun 2, 2020 Jun 16, 2020 Jun 16,	fullek2 SYSTEM	(\$464.52) (\$464.52)	Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 6 on the current Payment Estimate. Overrun deduction. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment
				3	Jun 2, 2020 Jun 2, 2020 Jun 16, 2020 Jun 16, 2020 Jul 1,	fullek2 SYSTEM SYSTEM	(\$464.52) (\$464.52) \$464.52	Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 6 on the current Payment Estimate. Overrun deduction. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 28 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment

Revision 4/1/2020 Page 20 of 32



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0730	TACK COAT	Overrun	Overrun		2020			estimates of '0.00000' is applied (if non-zero).
				5	Jul 16, 2020	SYSTEM	\$464.52	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) overridding Payment Estimate Exception 27 on the current Payment Estimate.
				6	Aug 3, 2020	fullek2	\$464.52	Change Order Approved
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0730 -	Total						\$0.00	
0740	TRUNCATED DOMES	Material		3	Jun 16, 2020	SYSTEM	(\$4,665.00)	
				3	Jun 16, 2020	SYSTEM	\$4,665.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user fullerk2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				4	Jul 1, 2020	SYSTEM	(\$4,665.00)	
				4	Jul 1, 2020	SYSTEM	\$4,665.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user fullerk2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	TRUNCATED DOMES	Overrun	Overrun	3	Jun 16, 2020	SYSTEM	(\$405.00)	
				3	Jun 16, 2020	SYSTEM	\$405.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) overridding Payment Estimate Exception 29 on the current Payment Estimate.
				3	Jun 16, 2020	fullek2	(\$405.00)	
				4	Jul 1, 2020	SYSTEM	(\$405.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				4	Jul 1, 2020	SYSTEM	\$405.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) overridding Payment Estimate Exception 24 on the current Payment Estimate.
				5	Jul 16, 2020	SYSTEM	(\$405.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				5	Jul 16, 2020	SYSTEM	\$405.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user fullerk2 overridding Payment Estimate Exception 28 on the current Payment Estimate.
				6	Aug 3, 2020	fullek2	\$390.00	Change order approved.
				8	Sep 1, 2020	fullek2	\$15.00	Change Order approved.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0740 -	Total						\$0.00	
0750	6 IN. CONCRETE MEDIAN STRIP	Material		3	Jun 16, 2020	SYSTEM	(\$7,232.00)	
				3	Jun 16, 2020	SYSTEM	\$7,232.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user fullerk2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				4	Jul 1, 2020	SYSTEM	(\$7,232.00)	
				4	Jul 1, 2020	SYSTEM	\$7,232.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user fullerk2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				5	Jul 16, 2020	SYSTEM	(\$7,232.00)	
				5	Jul 16, 2020	SYSTEM	\$7,232.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user fullerk2 overridding Payment Estimate Exception 6 on the current Payment Estimate.

Revision 4/1/2020 Page 21 of 32



Line	Description	Adjustraant	Other	Est.	Created	Created	Amount	Remarks
Line	Description	Adjustment Type	Adjustment Type	Number	Date	By	Amount	remars
0750	6 IN. CONCRETE MEDIAN STRIP	Material		6	Aug 3, 2020	SYSTEM	(\$7,232.00)	
				6	Aug 3, 2020	SYSTEM	\$7,232.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user fullerk2 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				7	Aug 17, 2020	SYSTEM	(\$7,232.00)	
				7	Aug 17, 2020	SYSTEM	\$7,232.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user fullerk2 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				8	Sep 1, 2020	SYSTEM	(\$7,232.00)	
				8	Sep 1, 2020	SYSTEM	\$7,232.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user fullerk2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				9	Sep 16, 2020	SYSTEM	(\$7,232.00)	
				9	Sep 16, 2020	SYSTEM	\$7,232.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user fullerk2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0750 - 1	Total						\$0.00	
0770	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH	Other Item Adjustment	ACAD	1	May 18, 2020	burlbe	(\$1,439.47)	BP1 19-19 Mix ID 3.8% Virgin 891.31 Tons Placed 05012020 to 05152020
	PAVEMENT REPAIR							Base = \$462.50 Current = \$420.00 Difference = -\$42.50 Total = -\$1439.47
	PAVEMENT REPAIR		ACAD - Tota	al			(\$1,439.47)	Current = \$420.00 Difference = -\$42.50
	PAVEMENT REPAIR Other Item Adjustment - Total		ACAD - Tota	al			(\$1,439.47) (\$1,439.47)	Current = \$420.00 Difference = -\$42.50
0770 -	Other Item Adjustment - Total		ACAD - Tota	al				Current = \$420.00 Difference = -\$42.50
	Other Item Adjustment - Total	Material	ACAD - Tota	al 1	May 18, 2020	SYSTEM	(\$1,439.47)	Current = \$420.00 Difference = -\$42.50
0770 - 1	Other Item Adjustment - Total Total	Material	ACAD - Tota			SYSTEM SYSTEM	(\$1,439.47) (\$1,439.47)	Current = \$420.00 Difference = -\$42.50
0770 - 1	Other Item Adjustment - Total Total	Material	ACAD - Total	1	2020 May 18,		(\$1,439.47) (\$1,439.47) (\$5,000.00)	Current = \$420.00 Difference = -\$42.50 Total = -\$1439.47 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user burlbe overridding Payment Estimate Exception 5 on the current Payment
0770 - 1	Other Item Adjustment - Total Total	Material		1	2020 May 18,		(\$1,439.47) (\$1,439.47) (\$5,000.00) \$5,000.00	Current = \$420.00 Difference = -\$42.50 Total = -\$1439.47 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user burlbe overridding Payment Estimate Exception 5 on the current Payment
0770 - 1	Other Item Adjustment - Total Total MISC. Temporary Traffic Control	Material		1	2020 May 18,		(\$1,439.47) (\$1,439.47) (\$5,000.00) \$5,000.00	Current = \$420.00 Difference = -\$42.50 Total = -\$1439.47 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user burlbe overridding Payment Estimate Exception 5 on the current Payment
0770 - 0800	Other Item Adjustment - Total Total MISC. Temporary Traffic Control Material - Total Total MISC. NTCIP COMPLIANT CHANGEABLE SIGN, CONTRACTOR	Material Material		1	2020 May 18,		(\$1,439.47) (\$1,439.47) (\$5,000.00) \$5,000.00 \$0.00	Current = \$420.00 Difference = -\$42.50 Total = -\$1439.47 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user burlbe overridding Payment Estimate Exception 5 on the current Payment
0770 - 1 0800 0800 - 1	Other Item Adjustment - Total Total MISC. Temporary Traffic Control Material - Total Total MISC. NTCIP COMPLIANT			1	2020 May 18, 2020 May 18,	SYSTEM	(\$1,439.47) (\$1,439.47) (\$5,000.00) \$5,000.00 \$0.00	Current = \$420.00 Difference = -\$42.50 Total = -\$1439.47 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user burlbe overridding Payment Estimate Exception 5 on the current Payment
0770 - 1 0800 0800 - 1	Other Item Adjustment - Total Total MISC. Temporary Traffic Control Material - Total Total MISC. NTCIP COMPLIANT CHANGEABLE SIGN, CONTRACTOR			1 1	2020 May 18, 2020 May 18, 2020 May 18,	SYSTEM	(\$1,439.47) (\$1,439.47) (\$5,000.00) \$5,000.00 \$0.00 \$0.00 (\$2,000.00)	Current = \$420.00 Difference = -\$42.50 Total = -\$1439.47 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user burlbe overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user burlbe overridding Payment Estimate Exception 6 on the current Payment
0800 - 0810	Other Item Adjustment - Total Total MISC. Temporary Traffic Control Material - Total Total MISC. NTCIP COMPLIANT CHANGEABLE SIGN, CONTRACTOR		- Total	1 1	2020 May 18, 2020 May 18, 2020 May 18,	SYSTEM	(\$1,439.47) (\$1,439.47) (\$5,000.00) \$5,000.00 \$0.00 \$0.00 (\$2,000.00)	Current = \$420.00 Difference = -\$42.50 Total = -\$1439.47 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user burlbe overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user burlbe overridding Payment Estimate Exception 6 on the current Payment
0800 - 0810	Other Item Adjustment - Total Total MISC. Temporary Traffic Control Material - Total Total MISC. NTCIP COMPLIANT CHANGEABLE SIGN, CONTRACTOR FURNISH/RETAINED Material - Total		- Total	1 1	2020 May 18, 2020 May 18, 2020 May 18,	SYSTEM	\$1,439.47) (\$1,439.47) (\$5,000.00) \$5,000.00 \$0.00 \$0.00 (\$2,000.00) \$2,000.00	Current = \$420.00 Difference = -\$42.50 Total = -\$1439.47 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user burlbe overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user burlbe overridding Payment Estimate Exception 6 on the current Payment
0800 - 1 0800 - 1 0810 - 1 0810 - 1	Other Item Adjustment - Total Total MISC. Temporary Traffic Control Material - Total Total MISC. NTCIP COMPLIANT CHANGEABLE SIGN, CONTRACTOR FURNISH/RETAINED Material - Total		- Total	1 1 1 1 3	2020 May 18, 2020 May 18, 2020 May 18, 2020 Jun 16, 2020	SYSTEM SYSTEM SYSTEM	\$1,439.47) (\$1,439.47) (\$5,000.00) \$5,000.00 \$0.00 \$0.00 \$2,000.00) \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	Current = \$420.00 Difference = -\$42.50 Total = -\$1439.47 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user burlbe overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user burlbe overridding Payment Estimate Exception 6 on the current Payment Estimate.
0800 - 1 0800 - 1 0810 - 1 0810 - 1	Other Item Adjustment - Total Total MISC. Temporary Traffic Control Material - Total Total MISC. NTCIP COMPLIANT CHANGEABLE SIGN, CONTRACTOR FURNISH/RETAINED Material - Total Total PREFORMED THERMOPLASTIC	Material	- Total	1 1 1 1	2020 May 18, 2020 May 18, 2020 May 18, 2020	SYSTEM SYSTEM SYSTEM	\$1,439.47) (\$1,439.47) (\$5,000.00) \$5,000.00 \$0.00 \$0.00 \$2,000.00) \$2,000.00 \$0.00 \$4,320.00)	Current = \$420.00 Difference = -\$42.50 Total = -\$1439.47 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user burlbe overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user burlbe overridding Payment Estimate Exception 6 on the current Payment
0800 - 1 0800 - 2 0810 - 2 0810 - 3	Other Item Adjustment - Total Total MISC. Temporary Traffic Control Material - Total Total MISC. NTCIP COMPLIANT CHANGEABLE SIGN, CONTRACTOR FURNISH/RETAINED Material - Total Total PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material	- Total	1 1 1 1 3	2020 May 18, 2020 May 18, 2020 May 18, 2020 Jun 16, 2020	SYSTEM SYSTEM SYSTEM	\$1,439.47) (\$1,439.47) (\$5,000.00) \$5,000.00 \$0.00 \$0.00 \$2,000.00) \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	Current = \$420.00 Difference = -\$42.50 Total = -\$1439.47 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user burlbe overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user burlbe overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user fullerk2 overridding Payment Estimate Exception 11 on the current Payment
0800 - 1 0800 - 2 0810 - 2 0830	Other Item Adjustment - Total Total MISC. Temporary Traffic Control Material - Total Total MISC. NTCIP COMPLIANT CHANGEABLE SIGN, CONTRACTOR FURNISH/RETAINED Material - Total Total PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material	- Total	1 1 1 1 3	2020 May 18, 2020 May 18, 2020 May 18, 2020 Jun 16, 2020	SYSTEM SYSTEM SYSTEM	\$1,439.47) (\$1,439.47) (\$5,000.00) \$5,000.00 \$0.00 \$0.00 \$2,000.00) \$2,000.00 \$0.00 \$4,320.00)	Current = \$420.00 Difference = -\$42.50 Total = -\$1439.47 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user burlbe overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user burlbe overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user fullerk2 overridding Payment Estimate Exception 11 on the current Payment
0800 - 1 0800 - 2 0810 - 2 0810 - 3	Other Item Adjustment - Total Total MISC. Temporary Traffic Control Material - Total Total MISC. NTCIP COMPLIANT CHANGEABLE SIGN, CONTRACTOR FURNISH/RETAINED Material - Total Total PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material	- Total	1 1 1 1 3	2020 May 18, 2020 May 18, 2020 May 18, 2020 Jun 16, 2020	SYSTEM SYSTEM SYSTEM	\$1,439.47) (\$1,439.47) (\$5,000.00) \$5,000.00 \$0.00 \$0.00 \$2,000.00) \$2,000.00 \$0.00 \$0.00 \$4,320.00 \$4,320.00	Current = \$420.00 Difference = -\$42.50 Total = -\$1439.47 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user burlbe overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user burlbe overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user fullerk2 overridding Payment Estimate Exception 11 on the current Payment

Revision 4/1/2020 Page 22 of 32



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0850	ARROW	Material		3	Jun 16, 2020	SYSTEM	\$5,320.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user fullerk2 overridding Payment Estimate Exception 12 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0850 -	Total						\$0.00	
0870	70 PREFORMED THERMOPLASTIC Mai PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	Material		3	Jun 16, 2020	SYSTEM	(\$175.00)	
	TIED EINE THATOLES			3	Jun 16, 2020	SYSTEM	\$175.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user fullerk2 overridding Payment Estimate Exception 13 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES		Overrun	4	Jul 1, 2020	SYSTEM	(\$200.00)	
	TIELD EINE THANKOLES			4	Jul 1, 2020	SYSTEM	\$200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user fullerk2 overridding Payment Estimate Exception 25 on the current Payment Estimate.
				4	Jul 1, 2020	fullek2	(\$200.00)	Change order in progress.
				5	Jul 16, 2020	SYSTEM	(\$200.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				5	Jul 16, 2020	SYSTEM	\$200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user fullerk2 overridding Payment Estimate Exception 29 on the current Payment Estimate.
				6	Aug 3, 2020	SYSTEM	(\$200.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				6	Aug 3, 2020	SYSTEM	\$200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user fullerk2 overridding Payment Estimate Exception 21 on the current Payment Estimate.
				7	Aug 17, 2020	SYSTEM	(\$200.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				7	Aug 17, 2020	SYSTEM	\$200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user fullerk2 overridding Payment Estimate Exception 23 on the current Payment Estimate.
				8	Sep 1, 2020	SYSTEM	(\$200.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				8	Sep 1, 2020	SYSTEM	\$200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user fullerk2 overridding Payment Estimate Exception 28 on the current Payment Estimate.
				9	Sep 16, 2020	SYSTEM	(\$200.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				9	Sep 16, 2020	SYSTEM	\$200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user fullerk2 overridding Payment Estimate Exception 25 on the current Payment Estimate.
			Overrun - T	otal			(\$200.00)	
	Overrun - Total						(\$200.00)	
0870 -	Total						(\$200.00)	
0880	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT TYPE I BEADS	Overrun	Overrun	4	Jul 1, 2020	SYSTEM	(\$129.00)	
	MARKING PAINT, TYPE L BEADS			4	Jul 1, 2020	SYSTEM	\$97.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user fullerk2 overridding Payment Estimate Exception 26 on the current Payment Estimate.
				4	Jul 1, 2020	SYSTEM	\$31.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user fullerk2 overridding Payment Estimate Exception 26 on the current Payment Estimate.
				4	Jul 1, 2020	fullek2	(\$129.00)	Change order in progress.

Revision 4/1/2020 Page 23 of 32



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0880	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT	Overrun	Overrun	5	Jul 16, 2020	SYSTEM	(\$129.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
	MARKING PAINT, TYPE L BEADS			5	Jul 16, 2020	SYSTEM	\$129.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user fullerk2 overridding Payment Estimate Exception 30 on the current Payment Estimate.
				6	Aug 3, 2020	SYSTEM	(\$129.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				6	Aug 3, 2020	SYSTEM	\$129.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user fullerk2 overridding Payment Estimate Exception 22 on the current Payment Estimate.
				7	Aug 17, 2020	SYSTEM	(\$129.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				7	Aug 17, 2020	SYSTEM	\$129.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user fullerk2 overridding Payment Estimate Exception 24 on the current Payment Estimate.
				8	Sep 1, 2020	SYSTEM	(\$129.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				8	Sep 1, 2020	SYSTEM	\$129.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user fullerk2 overridding Payment Estimate Exception 29 on the current Payment Estimate.
				9	Sep 16, 2020	SYSTEM	(\$129.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				9	Sep 16, 2020	SYSTEM	\$129.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user fullerk2 overridding Payment Estimate Exception 26 on the current Payment Estimate.
			Overrun - T	otal			(\$129.00)	
	Overrun - Total						(\$129.00)	
0880 -	·Total						(\$129.00)	
0890	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Overrun	Overrun	4	Jul 1, 2020	SYSTEM	(\$11.50)	
				4	Jul 1, 2020	SYSTEM	\$11.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user fullerk2 overridding Payment Estimate Exception 27 on the current Payment Estimate.
				4	Jul 1, 2020	fullek2	(\$11.50)	Change order in progress.
				5	Jul 16, 2020	SYSTEM	(\$11.50)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				5	Jul 16, 2020	SYSTEM	\$11.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user fullerk2 overridding Payment Estimate Exception 31 on the current Payment Estimate.
				6	Aug 3, 2020	SYSTEM	(\$11.50)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				6	Aug 3, 2020	SYSTEM	\$11.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user fullerk2 overridding Payment Estimate Exception 23 on the current Payment Estimate.
				7	Aug 17, 2020	SYSTEM	(\$11.50)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				7	Aug 17, 2020	SYSTEM	\$11.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user fullerk2 overridding Payment Estimate Exception 25 on the current Payment Estimate.
				8	Sep 1, 2020	SYSTEM	(\$11.50)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				8	Sep 1, 2020	SYSTEM	\$11.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user fullerk2 overridding Payment Estimate Exception 30 on the current Payment Estimate.
				9	Sep 16, 2020	SYSTEM	(\$11.50)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				9	Sep 16, 2020	SYSTEM	\$11.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user fullerk2 overridding Payment Estimate Exception 27 on the current Payment

Revision 4/1/2020 Page 24 of 32



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0890	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Overrun	Overrun					Estimate.
			Overrun - T	otal			(\$11.50)	
	Overrun - Total						(\$11.50)	
0890 -	·Total						(\$11.50)	
0900	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		3	Jun 16, 2020	SYSTEM	(\$9,213.40)	
				3	Jun 16, 2020	SYSTEM	\$9,213.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user fullerk2 overridding Payment Estimate Exception 14 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Other Item Adjustment	REFL	7	Aug 17, 2020	fullek2	\$455.83	Results in e-projects under project file.
			REFL - Tota	ıl			\$455.83	
	Other Item Adjustment - Total						\$455.83	
0900 -	· Total						\$455.83	
0910	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		3	Jun 16, 2020	SYSTEM	(\$9,031.60)	
	WARRINGT AIRT, THE ET BEADS			3	Jun 16, 2020	SYSTEM	\$9,031.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user fullerk2 overridding Payment Estimate Exception 16 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Other Item Adjustment	REFL	7	Aug 17, 2020	fullek2	\$426.41	Results in e-projects under project file.
			REFL - Tota	ı			\$426.41	
	Other Item Adjustment - Total						\$426.41	
	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Overrun	Overrun	4	Jul 1, 2020	SYSTEM	(\$145.00)	
				4	Jul 1, 2020	SYSTEM	\$145.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user fullerk2 overridding Payment Estimate Exception 28 on the current Payment Estimate.
				4	Jul 1, 2020	fullek2	(\$145.00)	Change order in progress.
				5	Jul 16, 2020	SYSTEM	(\$145.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				5	Jul 16, 2020	SYSTEM	\$145.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user fullerk2 overridding Payment Estimate Exception 32 on the current Payment Estimate.
				6	Aug 3, 2020	fullek2	\$145.00	Change order approved.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0910 -	Total						\$426.41	
0920	PAVEMENT MARKING REMOVAL (SYMBOLS)	Overrun	Overrun	4	Jul 1, 2020	SYSTEM	(\$80.00)	
				4	Jul 1, 2020	SYSTEM	\$80.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user fullerk2 overridding Payment Estimate Exception 29 on the current Payment Estimate.
				4	Jul 1, 2020	fullek2	(\$80.00)	Change order in progress.
				5	Jul 16, 2020	SYSTEM	(\$80.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				5	Jul 16, 2020	SYSTEM	\$80.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user fullerk2 overridding Payment Estimate Exception 33 on the current Payment

Revision 4/1/2020 Page 25 of 32



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0920	PAVEMENT MARKING REMOVAL	Overrun	Overrun					Estimate.
	(SYMBOLS)			6	Aug 3, 2020	SYSTEM	(\$80.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				6	Aug 3, 2020	SYSTEM	\$80.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user fullerk2 overridding Payment Estimate Exception 24 on the current Payment Estimate.
				7	Aug 17, 2020	SYSTEM	(\$80.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				7	Aug 17, 2020	SYSTEM	\$80.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user fullerk2 overridding Payment Estimate Exception 26 on the current Payment Estimate.
				8	Sep 1, 2020	SYSTEM	(\$80.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				8	Sep 1, 2020	SYSTEM	\$80.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user fullerk2 overridding Payment Estimate Exception 31 on the current Payment Estimate.
				9	Sep 16, 2020	SYSTEM	(\$80.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				9	Sep 16, 2020	SYSTEM	\$80.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user fullerk2 overridding Payment Estimate Exception 28 on the current Payment Estimate.
			Overrun - T	otal			(\$80.00)	
	Overrun - Total						(\$80.00)	
0920 -	Total						(\$80.00)	
0980	MGS GUARDRAIL	Construction Stockpile		1	May 18, 2020	SYSTEM	\$8,104.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$8,104.00	
	Construction Stockpile - Total						\$8,104.00	
0980 -	Total						\$8,104.00	
0990	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING			1	May 18, 2020	SYSTEM	\$1,785.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$1,785.00	
	Construction Stockpile - Total						\$1,785.00	
0990 -	Total						\$1,785.00	
1000	MGS GUARDRAIL, 6 FT. POSTS, 3 FT 1.5 IN. SPACING	Construction Stockpile		1	May 18, 2020	SYSTEM	\$823.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$823.00	
	Construction Stockpile - Total						\$823.00	
1000 -	Total						\$823.00	
1010	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	Construction Stockpile		1	May 18, 2020	SYSTEM	\$6,024.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$6,024.00	
	Construction Stockpile - Total						\$6,024.00	
1010 -	Total						\$6,024.00	
1020	MGS END ANCHOR	Construction Stockpile		1	May 18, 2020	SYSTEM	\$2,455.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$2,455.00	
	Construction Stockpile - Total						\$2,455.00	
1020 -	Total						\$2,455.00	
1030	TRANSITION SECTION, 7.5 FT. POSTS	Construction Stockpile		1	May 18, 2020	SYSTEM	\$608.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$608.00	
	Construction Stockpile - Total						\$608.00	
1030 -	Total						\$608.00	
1040	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		1	May 18, 2020	SYSTEM	\$14,960.00	Payment Estimate Item Adjustment generated Stockpile Transaction

Revision 4/1/2020 Page 26 of 32



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1040		Construction Stockpile	- Total				\$14,960.00	
	Construction Stockpile - Total						\$14,960.00	
1040 -	Total						\$14,960.00	
1070	CONDUIT, 3 IN. RIGID, PUSHED	Material		3	Jun 16, 2020	SYSTEM	(\$2,518.50)	
				3	Jun 16, 2020	SYSTEM	\$2,518.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user fullerk2 overridding Payment Estimate Exception 20 on the current Payment Estimate.
				4	Jul 1, 2020	SYSTEM	(\$2,518.50)	
				4	Jul 1, 2020	SYSTEM	\$2,518.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user fullerk2 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				5	Jul 16, 2020	SYSTEM	(\$2,518.50)	
				5	Jul 16, 2020	SYSTEM	\$2,518.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user fullerk2 overridding Payment Estimate Exception 16 on the current Payment Estimate.
				6	Aug 3, 2020	SYSTEM	(\$2,639.25)	
				6	Aug 3, 2020	SYSTEM	\$2,639.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user fullerk2 overridding Payment Estimate Exception 14 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	CONDUIT, 3 IN. RIGID, PUSHED	Overrun	Overrun	3	Jun 16, 2020	SYSTEM	(\$1,552.50)	
				3	Jun 16, 2020	SYSTEM	\$1,552.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) overridding Payment Estimate Exception 30 on the current Payment Estimate.
				3	Jun 16, 2020	fullek2	(\$1,552.50)	
				4	Jul 1, 2020	SYSTEM	(\$1,552.50)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				4	Jul 1, 2020	SYSTEM	\$1,552.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) overridding Payment Estimate Exception 30 on the current Payment Estimate.
				5	Jul 16, 2020	SYSTEM	(\$1,552.50)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				5	Jul 16, 2020	SYSTEM	\$1,552.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) overridding Payment Estimate Exception 34 on the current Payment Estimate.
				6	Aug 3, 2020	SYSTEM	\$120.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) overridding Payment Estimate Exception 25 on the current Payment Estimate.
				6	Aug 3, 2020	SYSTEM	(\$120.75)	
				6	Aug 3, 2020	fullek2	\$1,552.50	Change Order has been approved.
				6	Aug 3, 2020	fullek2	(\$120.75)	Overrun of 7 feet.
				7	Aug 17, 2020	SYSTEM	(\$120.75)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				7	Aug 17, 2020	SYSTEM	\$120.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user fullerk2 overridding Payment Estimate Exception 27 on the current Payment Estimate.
				8	Sep 1, 2020	SYSTEM	(\$120.75)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				8	Sep 1, 2020	SYSTEM	\$120.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user fullerk2 overridding Payment Estimate Exception 32 on the current Payment Estimate.

Revision 4/1/2020 Page 27 of 32



Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
1070	CONDUIT, 3 IN. RIGID, PUSHED	Overrun	Type Overrun	9	Sep 16,	SYSTEM	(\$120.75)	Averaged Price Adjustment from this item on all previous payment
				9	2020 Sep 16, 2020	SYSTEM	\$120.75	estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user fullerk2 overridding Payment Estimate Exception 29 on the current Payment
							(4.100.00)	Estimate.
	Overrun - Total		Overrun - T	otal			(\$120.75)	
1070	· Total						(\$120.75)	
1110	SH-FLAT SHEET - SIGNAL SIGN	Material		6	Aug 3,	SYSTEM	(\$1,449.30)	
				6	2020 Aug 3, 2020	SYSTEM	\$1,449.30	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user fullerk2
				7	Aug 17,	SYSTEM	(\$1,449.30)	overridding Payment Estimate Exception 15 on the current Payment Estimate.
				,	2020	STSTEIN	(\$1,449.30)	
				7	Aug 17, 2020	SYSTEM	\$1,449.30	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user fullerk2 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				8	Sep 1, 2020	SYSTEM	(\$1,449.30)	
				8	Sep 1, 2020	SYSTEM	\$1,449.30	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user fullerk2 overridding Payment Estimate Exception 18 on the current Payment Estimate.
				9	Sep 16, 2020	SYSTEM	(\$1,449.30)	
				9	Sep 16, 2020	SYSTEM	\$1,449.30	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user fullerk2 overridding Payment Estimate Exception 15 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total		- Total				\$0.00	
	- Total	Versiel	- Total		lul 4	OVOTEM	\$0.00 \$0.00	
1110 - 1130		Material	- Total	4	Jul 1, 2020	SYSTEM	\$0.00 \$0.00 (\$807.00)	
	- Total	Material	- Total	4		SYSTEM SYSTEM	\$0.00 \$0.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user fullerk2 overridding Payment Estimate Exception 13 on the current Payment Estimate.
	- Total	Material	- Total		2020 Jul 1,		\$0.00 \$0.00 (\$807.00)	Payment Estimate Item Adjustment (0023) due to user fullerk2 overridding Payment Estimate Exception 13 on the current Payment
	- Total	Material	- Total	4	Jul 1, 2020 Jul 16,	SYSTEM	\$0.00 \$0.00 (\$807.00) \$807.00	Payment Estimate Item Adjustment (0023) due to user fullerk2 overridding Payment Estimate Exception 13 on the current Payment
	- Total	Material	- Total	5	Jul 16, 2020 Jul 16, 2020 Jul 16,	SYSTEM	\$0.00 \$0.00 (\$807.00) \$807.00	Payment Estimate Item Adjustment (0023) due to user fullerk2 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user fullerk2 overridding Payment Estimate Exception 17 on the current Payment
	- Total	Material	- Total	5 5	Jul 16, 2020 Jul 16, 2020 Jul 16, 2020 Aug 3,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$807.00) \$807.00 (\$807.00)	Payment Estimate Item Adjustment (0023) due to user fullerk2 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user fullerk2 overridding Payment Estimate Exception 17 on the current Payment
	- Total	Material	- Total	5 5 6	2020 Jul 1, 2020 Jul 16, 2020 Jul 16, 2020 Aug 3, 2020 Aug 3,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$807.00) \$807.00 (\$807.00) (\$807.00)	Payment Estimate Item Adjustment (0023) due to user fullerk2 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user fullerk2 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user fullerk2 overridding Payment Estimate Exception 16 on the current Payment
	- Total	Material	- Total	5 5 6 6	2020 Jul 1, 2020 Jul 16, 2020 Jul 16, 2020 Aug 3, 2020 Aug 3, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$807.00) \$807.00 (\$807.00) \$807.00	Payment Estimate Item Adjustment (0023) due to user fullerk2 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user fullerk2 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user fullerk2 overridding Payment Estimate Exception 16 on the current Payment
	- Total	Material	- Total	5 5 6 6	2020 Jul 1, 2020 Jul 16, 2020 Jul 16, 2020 Aug 3, 2020 Aug 17, 2020 Aug 17,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$807.00) \$807.00 (\$807.00) \$807.00 (\$807.00)	Payment Estimate Item Adjustment (0023) due to user fullerk2 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user fullerk2 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user fullerk2 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user fullerk2 overridding Payment Estimate Exception 14 on the current Payment
	- Total	Material	- Total	4 5 5 6 6 7 7	2020 Jul 1, 2020 Jul 16, 2020 Jul 16, 2020 Aug 3, 2020 Aug 17, 2020 Aug 17, 2020 Sep 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$807.00) \$807.00 (\$807.00) \$807.00 (\$807.00) \$807.00	Payment Estimate Item Adjustment (0023) due to user fullerk2 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user fullerk2 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user fullerk2 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user fullerk2 overridding Payment Estimate Exception 14 on the current Payment
	- Total	Material	- Total	4 5 5 6 6 7 7	2020 Jul 1, 2020 Jul 16, 2020 Jul 16, 2020 Aug 3, 2020 Aug 17, 2020 Aug 17, 2020 Sep 1, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$807.00) \$807.00 (\$807.00) \$807.00 (\$807.00) \$807.00 (\$807.00)	Payment Estimate Item Adjustment (0023) due to user fullerk2 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user fullerk2 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user fullerk2 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user fullerk2 overridding Payment Estimate Exception 14 on the current Payment Estimate.

Revision 4/1/2020 Page 28 of 32



130 POST, SIGNAL RFT, CR2 AM Material Post	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
Material - Total	1130	POST, SIGNAL 8 FT. OR 2.4 M	Material			2020			overridding Payment Estimate Exception 16 on the current Payment
1350 CABLE, 16 ANG 2 CONDUCTOR Malerial				- Total				\$0.00	
1100 CABLE 16 ANG 2 CONDUCTOR Material		Material - Total						\$0.00	
3	1130 -	Total						\$0.00	
Payment Estimate Iban Adjustment (0022) due to user hishest covering Payment Estimate Exception 2 in the current Payment Estimate Exception 2 in the current Payment Estimate Exception 2 in the current Payment Estimate Exception 1 in the current Payment Estimate Exception 2 in the current Payment Estimate Exception 3 in the cur	1150	150 CABLE, 16 AWG 2 CONDUCTOR M	Material		3		SYSTEM	(\$1,743.30)	
A					3		SYSTEM	\$1,743.30	Payment Estimate Item Adjustment (0022) due to user fullerk2 overridding Payment Estimate Exception 21 on the current Payment
2020 Payment Estimate Item Adjustment (2025) due to user fullency consisting Payment Estimate Exception 16 on the current Payment Estimate Exception 20 on the current Payment Estimate Exception 20 on the current Payment Estimate Exception 20 on the current Payment Estimate Payment Estimate Exception 20 on the current Payment Estimate Payment Payment Estimate Payment					4		SYSTEM	(\$1,743.30)	
2020 5					4		SYSTEM	\$1,743.30	Payment Estimate Item Adjustment (0025) due to user fullerk2 overridding Payment Estimate Exception 16 on the current Payment
Payment Estimate Item Adjustment (0029) due to user fuller/2 overriding pyment Estimate Item Adjustment (0029) due to user fuller/2 overriding pyment Estimate Payment Estimate Exception 21 on the current Payment Estimate Exception 22 on the current Payment Estimate Exception 23 on the current Payment Estimate Exception 24 on the current Payment Estimate Exception 25 on the current Payment Estim					5		SYSTEM	(\$1,743.30)	
Material - Total CABLE. 16 AWG 2 CONDUCTOR Overrun 3					5		SYSTEM	\$1,743.30	Payment Estimate Item Adjustment (0026) due to user fullerk2 overridding Payment Estimate Exception 20 on the current Payment
CABLE, 16 AWG 2 CONDUCTOR Overrun 3				- Total				\$0.00	
2020 3 Jun 16, fullek2 (\$1,013.20) 2020 4 Jul 1, SYSTEM (\$1,013.20) 2020 4 Jul 1, SYSTEM (\$1,013.20) 2020 20		Material - Total						\$0.00	
2020		CABLE, 16 AWG 2 CONDUCTOR	Overrun	Overrun	3		SYSTEM	(\$1,013.20)	
2020 4 Jul 1, 2020 2020 5 Jul 16, 2020					3		SYSTEM	\$1,013.20	Payment Estimate Item Adjustment (0021) overridding Payment
2020 SYSTEM S1,013.20 This adjustment offsets the original system-generated Overrun Payment Estimate Estimate Item Adjustment (0024) overridding Payment Estimate Estimate Estimate Item Adjustment (0024) overridding Payment Estimate Estimate Estimate Estimate Estimate Item Adjustment (0024) overridding Payment Estimate Estimate Estimate Estimate Estimate Estimate Estimate Estimate Sof '0.00000' is applied (if non-zero). SySTEM S1,013.20					3		fullek2	(\$1,013.20)	
2020 Payment Estimate (from Adjustment (6024) overridding Payment Estimate. (5 Jul 16, 2020 Payment Estimate. Exception 31 on the current Payment Estimate. (5 Jul 16, 2020 Payment Estimate (50,40) overridding Payment (50					4		SYSTEM	(\$1,013.20)	
System Studies System					4		SYSTEM	\$1,013.20	Payment Estimate Item Adjustment (0024) overridding Payment
2020 Payment Estimate Item Adjustment (0025) overridding Payment Estimate Estimate Item Adjustment (0025) overridding Payment Estimate.					5		SYSTEM	(\$1,013.20)	
1150 - Total Su.00					5		SYSTEM	\$1,013.20	Payment Estimate Item Adjustment (0025) overridding Payment
1150 - Total S0.00					6		fullek2	\$1,013.20	Change order approved.
Sum of the content				Overrun - T	otal			\$0.00	
1160 CABLE, 16 AWG 5 CONDUCTOR Material 3 Jun 16, 2020 SYSTEM \$953.75 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user fullerk2 overridding Payment Estimate Exception 22 on the current Payment Estimate. 4 Jul 1, 2020 SYSTEM \$953.75 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user fullerk2 overridding Payment Estimate Exception 17 on the current Payment Estimate. 5 Jul 16, 2020 SYSTEM \$953.75 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user fullerk2 overridding Payment Estimate Item Adjustment (0028) due to user fullerk2 overridding Payment Estimate Item Adjustment (0028) due to user fullerk2 overridding Payment Estimate Exception 21 on the current Payment Estimate.		Overrun - Total						\$0.00	
2020 3 Jun 16, 2020 \$953.75 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user fullerk2 overridding Payment Estimate Exception 22 on the current Payment Estimate. 4 Jul 1, 2020 \$953.75 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user fullerk2 overridding Payment Estimate Item Adjustment (0027) due to user fullerk2 overridding Payment Estimate Exception 17 on the current Payment Estimate. 5 Jul 16, 2020 \$953.75 This adjustment offsets the original system-generated Overrun Payment Estimate. 5 Jul 16, 2020 \$953.75 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user fullerk2 overridding Payment Estimate Item Adjustment (0028) due to user fullerk2 overridding Payment Estimate Exception 21 on the current Payment Estimate.	1150 -	Total						\$0.00	
2020 Payment Estimate Item Adjustment (0024) due to user fullerk2 overridding Payment Estimate Exception 22 on the current Payment Estimate. 4 Jul 1, 2020 SYSTEM (\$953.75) 4 Jul 1, 2020 \$953.75 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user fullerk2 overridding Payment Estimate Exception 17 on the current Payment Estimate. 5 Jul 16, 2020 \$953.75 This adjustment offsets the original system-generated Overrun Payment Estimate. 5 Jul 16, 2020 \$953.75 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user fullerk2 overridding Payment Estimate Exception 21 on the current Payment Estimate.	1160	CABLE, 16 AWG 5 CONDUCTOR	Material		3		SYSTEM	(\$953.75)	
4 Jul 1, 2020 \$953.75 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user fullerk2 overridding Payment Estimate Exception 17 on the current Payment Estimate. 5 Jul 16, 2020 \$953.75 This adjustment offsets the original system-generated Overrun Payment Estimate. 5 Jul 16, 2020 \$953.75 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user fullerk2 overridding Payment Estimate Exception 21 on the current Payment Estimate.					3		SYSTEM	\$953.75	Payment Estimate Item Adjustment (0024) due to user fullerk2 overridding Payment Estimate Exception 22 on the current Payment
2020 Payment Estimate Item Adjustment (0027) due to user fullerk2 overridding Payment Estimate Exception 17 on the current Payment Estimate. 5 Jul 16, 2020 5 Jul 16, 2020 SYSTEM \$953.75 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user fullerk2 overridding Payment Estimate Exception 21 on the current Payment Estimate.					4		SYSTEM	(\$953.75)	
5 Jul 16, 2020 5 SYSTEM \$953.75 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user fullerk2 overridding Payment Estimate Exception 21 on the current Payment Estimate.					4		SYSTEM	\$953.75	Payment Estimate Item Adjustment (0027) due to user fullerk2 overridding Payment Estimate Exception 17 on the current Payment
2020 Payment Estimate Item Adjustment (0028) due to user fullerk2 overridding Payment Estimate Exception 21 on the current Payment Estimate.					5		SYSTEM	(\$953.75)	
- Total \$0.00					5		SYSTEM	\$953.75	Payment Estimate Item Adjustment (0028) due to user fullerk2 overridding Payment Estimate Exception 21 on the current Payment
				- Total				\$0.00	

Revision 4/1/2020 Page 29 of 32



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1160	Material - Total						\$0.00	
	CABLE, 16 AWG 5 CONDUCTOR	Overrun	Overrun	3	Jun 16, 2020	SYSTEM	(\$883.75)	
				3	Jun 16, 2020	SYSTEM	\$883.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) overridding Payment Estimate Exception 32 on the current Payment Estimate.
				3	Jun 16, 2020	fullek2	(\$883.75)	
				4	Jul 1, 2020	SYSTEM	(\$883.75)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				4	Jul 1, 2020	SYSTEM	\$883.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) overridding Payment Estimate Exception 32 on the current Payment Estimate.
				5	Jul 16, 2020	SYSTEM	(\$883.75)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				5	Jul 16, 2020	SYSTEM	\$883.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) overridding Payment Estimate Exception 36 on the current Payment Estimate.
				6	Aug 3, 2020	fullek2	\$883.75	Change order approved.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
1160 -	· Total						\$0.00	
1170	CABLE, LOOP DETECTOR, IN DUCT	Material		3	Jun 16, 2020	SYSTEM	(\$21,086.52)	
				3	Jun 16, 2020	SYSTEM	\$21,086.52	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user fullerk2 overridding Payment Estimate Exception 23 on the current Payment Estimate.
				4	Jul 1, 2020	SYSTEM	(\$27,332.76)	
				4	Jul 1, 2020	SYSTEM	\$27,332.76	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user fullerk2 overridding Payment Estimate Exception 18 on the current Payment Estimate.
				5	Jul 16, 2020	SYSTEM	(\$27,332.76)	
				5	Jul 16, 2020	SYSTEM	\$27,332.76	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user fullerk2 overridding Payment Estimate Exception 22 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	CABLE, LOOP DETECTOR, IN DUCT	Overrun	Overrun	4	Jul 1, 2020	SYSTEM	(\$2,653.56)	
				4	Jul 1, 2020	SYSTEM	\$2,653.56	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) overridding Payment Estimate Exception 33 on the current Payment Estimate.
				4	Jul 1, 2020	fullek2	(\$2,653.56)	Change order in progress.
				5	Jul 16, 2020	SYSTEM	(\$2,653.56)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				5	Jul 16, 2020	SYSTEM	\$2,653.56	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) overridding Payment Estimate Exception 37 on the current Payment Estimate.
				6	Aug 3, 2020	SYSTEM	(\$2,653.56)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				6	Aug 3, 2020	SYSTEM	\$2,653.56	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user fullerk2 overridding Payment Estimate Exception 26 on the current Payment Estimate.
				7	Aug 17, 2020	SYSTEM	(\$2,653.56)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				7	Aug 17, 2020	SYSTEM	\$2,653.56	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user fullerk2 overridding Payment Estimate Exception 28 on the current Payment Estimate.

Revision 4/1/2020 Page 30 of 32



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks															
1170	CABLE, LOOP DETECTOR, IN DUCT	Overrun	Overrun	8	Sep 1, 2020	SYSTEM	(\$2,653.56)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).															
			8	Sep 1, 2020	SYSTEM	\$2,653.56	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user fullerk2 overridding Payment Estimate Exception 33 on the current Payment Estimate.																
			9	Sep 16, 2020	SYSTEM	(\$2,653.56)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).																
				9	Sep 16, 2020	SYSTEM	\$2,653.56	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user fullerk2 overridding Payment Estimate Exception 30 on the current Payment Estimate.															
			Overrun - T	otal			(\$2,653.56)																
	Overrun - Total						(\$2,653.56)																
1170 -	- Total						(\$2,653.56)																
1180	BASE, CONCRETE	Material		3	Jun 16, 2020	SYSTEM	(\$5,889.00)																
				3	Jun 16, 2020	SYSTEM	\$5,889.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user fullerk2 overridding Payment Estimate Exception 24 on the current Payment Estimate.															
				4	Jul 1, 2020	SYSTEM	(\$5,889.00)																
				4	Jul 1, 2020	SYSTEM	\$5,889.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user fullerk2 overridding Payment Estimate Exception 19 on the current Payment Estimate.															
				5	Jul 16, 2020	SYSTEM	(\$5,889.00)																
				5	Jul 16, 2020	SYSTEM	\$5,889.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user fullerk2 overridding Payment Estimate Exception 23 on the current Payment Estimate.															
				6	Aug 3, 2020	SYSTEM	(\$5,889.00)																
				6	Aug 3, 2020	SYSTEM	\$5,889.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user fullerk2 overridding Payment Estimate Exception 18 on the current Payment Estimate.															
				7	Aug 17, 2020	SYSTEM	(\$5,889.00)																
				7	Aug 17, 2020	SYSTEM	\$5,889.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user fullerk2 overridding Payment Estimate Exception 16 on the current Payment Estimate.															
				8	Sep 1, 2020	SYSTEM	(\$5,889.00)																
				9	8	Sep 1, 2020	SYSTEM	\$5,889.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user fullerk2 overridding Payment Estimate Exception 21 on the current Payment Estimate.														
																					9	Sep 16, 2020	SYSTEM
				9	Sep 16, 2020	SYSTEM	\$5,889.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user fullerk2 overridding Payment Estimate Exception 18 on the current Payment Estimate.															
			- Total				\$0.00																
	Material - Total	0	6	0	lun 40	OVCTT::	\$0.00																
	BASE, CONCRETE	Overrun	Overrun		Jun 16, 2020	SYSTEM	(\$1,359.00)																
				3	Jun 16, 2020	SYSTEM	\$1,359.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) overridding Payment Estimate Exception 33 on the current Payment Estimate.															
				3	Jun 16, 2020	fullek2	(\$1,359.00)																
				4	Jul 1, 2020	SYSTEM	(\$1,359.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).															
				4	Jul 1,	SYSTEM	\$1,359.00	This adjustment offsets the original system-generated Overrun															

Revision 4/1/2020 Page 31 of 32



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1180	BASE, CONCRETE	Overrun	Overrun		2020			Payment Estimate Item Adjustment (0030) overridding Payment Estimate Exception 34 on the current Payment Estimate.
				5	Jul 16, 2020	SYSTEM	(\$1,359.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				5	Jul 16, 2020	SYSTEM	\$1,359.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) overridding Payment Estimate Exception 38 on the current Payment Estimate.
				6	Aug 3, 2020	fullek2	\$1,359.00	Change order approved.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
1180 -	Total						\$0.00	
1220	MISC. PEDESTRIAN PUSH BUTTON STANCHION	Overrun	Overrun	4	Jul 1, 2020	SYSTEM	(\$2,612.00)	
				4	Jul 1, 2020	SYSTEM	\$2,612.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user fullerk2 overridding Payment Estimate Exception 35 on the current Payment Estimate.
				4	Jul 1, 2020	fullek2	(\$2,612.00)	Change order in progress.
				5	Jul 16, 2020	SYSTEM	(\$2,612.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				5	Jul 16, 2020	SYSTEM	\$2,612.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user fullerk2 overridding Payment Estimate Exception 39 on the current Payment Estimate.
				6	Aug 3, 2020	fullek2	\$2,612.00	Change order approved.
	Overrun - Total						\$0.00	
	Overrun - Total						\$0.00	
1220 -	Total						\$0.00	
Overa	II - Total						\$17,785.28	

Revision 4/1/2020 Page 32 of 32