

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 3, 2020

Progress Estimate Number 6		Contract ID Prime Contractor	200320-F10 R. V. Wagner, Inc.	Pay Period Start Pay Period End	July 16, 2020 August 1, 2020	Original Contract Amount Net Change Order Amount Current Contract Amount	\$819,381.50 \$0.00 \$819,381.50
Approval Date							By User
August 3, 2020		Ge	nerated and Approv	red (and should be co	onsidered Draft) a	at the Project Office Level by	steppr1
August 4, 2020		Review	ed and Approved (a	and should be consid	ered Draft) at the	Resident Engineer Level by	morgac1
August 5, 2020			Review	ved and Approved at	the Central Offic	e Controllers Office Level by	greggd1
Original Comp	letion Date	Current Comple	tion Date	Actual Completion	6 of Current Contract Amoun	t Complete	
November	ovember 2, 2020 November 2, 2020 72.52%						

No Milestones Exist for Contract

Contract Total Pay	For Estimate No. 6				
		This Estimate	Previous	To Date	
200320-F10					
	Total Posted Items Pay	\$0.00	\$594,249.95	\$594,249.95	
	Gross Item Adjustments	\$0.00	\$0.00	\$0.00	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
	·		\$594,249.95	\$594,249.95	
Contract Total Paya	able This Estimate:	\$0.00			

Items Paid This Estimate Period

No Data Available

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

e Item .	Adjusti	ments This Estimate						
roject umber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustmer amount
S3287	0050	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	Material			-25	\$36.00	(\$900.00
	0050	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0001) due to user steppr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	25	\$36.00	\$900.00
	0130	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material			-1,297	\$1.05	(\$1,361.85
	0130	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0002) due to user steppr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	1,297	\$1.05	\$1,361.85
	0140	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material			-1,523	\$1.05	(\$1,599.15
	0140	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0003) due to user steppr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	1,523	\$1.05	\$1,599.15
(0150	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-592	\$1.05	(\$621.60
	0150	4 IN. WHITE STANDARD WATERBORNE PAVEMENT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item	592	\$1.05	\$621.60

Revision 4/1/2020 Page 1 of 15



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 3, 2020

Progress Estimate Number
6
Contract ID 200320-F10 Pay Period Start Pay Period End August 1, 2020 Original Contract Amount August 1, 2020 Original Contract Amount Current Contract Amount Sel 19,381.50

ect ber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
287		MARKING PAINT, TYPE P BEADS			Adjustment (0004) due to user steppr1 overridding Payment Estimate Exception 8 on the current Payment Estimate.			
	0160	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-592	\$1.05	(\$621.60
	0160	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0005) due to user steppr1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	592	\$1.05	\$621.60
	0170	FLOWABLE BACKFILL	Material			-5	\$450.00	(\$2,250.00
	0170	FLOWABLE BACKFILL	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0006) due to user steppr1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	5	\$450.00	\$2,250.00
	0350	SILICONE EXPANSION JOINT SEALANT	Material			-116	\$33.80	(\$3,920.80
	0350	SILICONE EXPANSION JOINT SEALANT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0007) due to user steppr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	116	\$33.80	\$3,920.80
	0430	SILICONE EXPANSION JOINT SEALANT	Material			-189	\$32.50	(\$6,142.50)
	0430	SILICONE EXPANSION JOINT SEALANT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0008) due to user steppr1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	189	\$32.50	\$6,142.50
	0450	CLEANING AND EPOXY COATING	Material			-30	\$74.00	(\$2,220.00
	0450	CLEANING AND EPOXY COATING	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0009) due to user steppr1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	30	\$74.00	\$2,220.00
	0470	SILICONE EXPANSION JOINT SEALANT	Material			-138	\$37.00	(\$5,106.00
	0470	SILICONE EXPANSION JOINT SEALANT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0010) due to user steppr1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	138	\$37.00	\$5,106.00
	0520	GRAY EPOXY-MASTIC PRIMER	Material			-1	\$5,300.00	(\$5,300.00)
(0520	GRAY EPOXY-MASTIC PRIMER	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0011) due to user steppr1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	1	\$5,300.00	\$5,300.00
	0530	SILICONE EXPANSION JOINT SEALANT	Material			-134	\$37.00	(\$4,958.00)
	0530	SILICONE EXPANSION JOINT SEALANT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0012) due to user steppr1	134	\$37.00	\$4,958.00

Revision 4/1/2020 Page 2 of 15



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 3, 2020

Progr	ress Es	timate Number 6	Contract IE Prime Con		0320-F10 V. Wagner, Inc.	Pay Period Start Pay Period End		Net Cha	I Contract Ai ange Order A t Contract Ar	mount \$0	319,381.50 0.00 319,381.50
Project Number	Line No.	Item Descrip	otion	Adjustment Type	Other Item Adjustment Type	Comments			Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6S3287						overridding Payme on the c					
Total											\$0.00

Revision 4/1/2020 Page 3 of 15



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Informati	on					
Project Number	Federal Proj. Number	Description	Route	County	Location of Work							
J6S3287	FAF 30-1(47)	6 Bridge rehabilitations		JEFFERSON	on Routes 30, B, NN and MM							
Totals by J	Job Numb	ers										
J6S3287		ed Item Pay ss Item Adjustm		tem Pay	This Estimate \$0.00 \$0.00 \$0.00	Previous \$594,249.95 \$0.00 \$594,249.95	To Date \$594,249.95 \$0.00 \$594,249.95					
	Disir Liqu	ntive ncentive idated Damages er Contract Adju			\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00					

Revision 4/1/2020 Page 4 of 15



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6S3287, Item 6092011, Project Item Line Number 0050, Material Set 609201196, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	steppr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3287, Item 6092011, Project Item Line Number 0050, Material Set 609201196, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	steppr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3287, Item 6092011, Project Item Line Number 0050, Material Set 609201196, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	No Remark was entered by Engineer	steppr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3287, Item 6205902A, Project Item Line Number 0130, Material Set 6205902A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.	No Remark was entered by Engineer	steppr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3287, Item 6205902A, Project Item Line Number 0130, Material Set 6205902A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient.	No Remark was entered by Engineer	steppr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3287, Item 6205903A, Project Item Line Number 0140, Material Set 6205903A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.	No Remark was entered by Engineer	steppr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3287, Item 6205903A, Project Item Line Number 0140, Material Set 6205903A96, Material 1048PMTRHBWBYL - Marking Paint Acrylic Watr HiBld Yellow, Acceptance Action Generic 1048PMTRHBWBYL is insufficient.	No Remark was entered by Engineer	steppr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3287, Item 6206000C, Project Item Line Number 0150, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	No Remark was entered by Engineer	steppr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3287, Item 6206000C, Project Item Line Number 0150, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	No Remark was entered by Engineer	steppr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3287, Item 6206001C, Project Item Line Number 0160, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	No Remark was entered by Engineer	steppr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3287, Item 6206001C, Project Item Line Number 0160, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	No Remark was entered by Engineer	steppr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3287, Item 6214600A, Project Item Line Number 0170, Material Set 6214600A96, Material 0621FB - Flowable Backfill, Acceptance Action Generic 0621FB is insufficient.	No Remark was entered by Engineer	steppr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3287, Item 7040113, Project Item Line Number 0450, Material Set 704011396, Material 1039ERBCT3 - Type III Epoxy Resin for Conc Patch Cmp, Acceptance Action Generic 1039ERBCT3 is insufficient.	No Remark was entered by Engineer	steppr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3287, Item 7125961, Project Item Line Number 0520, Material Set 712596196, Material 1045PTGREPMA - Gray Epoxy-Mastic Primer, Acceptance Action Generic 1045PTGREPMA is insufficient.	No Remark was entered by Engineer	steppr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3287, Item 7173002, Project Item Line Number 0350, Material Set 717300296, Material 1057JMJCSS - Silicon Sealant for Sawed/Formed Jnts @, Acceptance Action Generic 1057JMJCSS is insufficient.	No Remark was entered by Engineer	steppr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3287, Item 7173002, Project Item Line Number 0470, Material Set 717300296, Material 1057JMJCSS - Silicon Sealant for Sawed/Formed Jnts @, Acceptance Action Generic 1057JMJCSS is insufficient.	No Remark was entered by Engineer	steppr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3287, Item 7173002, Project Item Line Number 0430, Material Set 717300296, Material 1057JMJCSS - Silicon Sealant for Sawed/Formed Jnts @, Acceptance Action Generic 1057JMJCSS is insufficient.	No Remark was entered by Engineer	steppr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3287, Item 7173002, Project Item Line Number 0530, Material Set 717300296, Material 1057JMJCSS - Silicon Sealant for Sawed/Formed Jnts @, Acceptance Action Generic 1057JMJCSS is insufficient.	No Remark was entered by Engineer	steppr1	Overridden

Revision 4/1/2020 Page 5 of 15



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTEI To Date (See repor- generated date)
00320-F10	J6S3287	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$12,000.00	\$12,000.0
		0001	0020	2159903	MISC.Modified Shaping Slopes, Class III	2,945.00	0.00	2,945.00	LF	2,707.50	\$9.50	\$25,721.2
		0001	0030	2164000	CURB REMOVAL	25.00	0.00	25.00	LF	25.00	\$6.00	\$150.0
		0001	0040	4135000	BITUMINOUS PAVEMENT CRACK SEALING	48.00	0.00	48.00	LF	0.00	\$24.00	\$0.0
		0001	0050	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	25.00	0.00	25.00	LF	25.00	\$36.00	\$900.0
		0001	0060	6113020	FURNISHING TYPE 2 ROCK BLANKET	430.00	0.00	430.00	CUYD	430.00	\$34.00	\$14,620.0
		0001	0070	6113040	PLACING TYPE 2 ROCK BLANKET	430.00	0.00	430.00	CUYD	430.00	\$20.00	\$8,600.0
		0001	0800	6133018	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS B PARTIAL DEPTH PAVEMENT REPAIR	0.10	0.00	0.10	TONS	0.00	\$11,000.00	\$0.0
		0001	0090	6133019	REMOVAL FOR CLASS B PARTIAL DEPTH PAVEMENT REPAIR	4.40	0.00	4.40	SQYD	0.00	\$215.00	\$0.0
		0001	0100	6169901	MISC.TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.80	\$37,000.00	\$29,600.0
		0001	0110	6169902	MISC.NTCIP CHANGEABLE MESSAGE SIGN WITH COMM.	4.00	0.00	4.00	EA	3.00	\$3,350.00	\$10,050.0
		0001	0120	6181000	INTERFACE, CONTRACTOR FURNISHED/RETAINED MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$62,000.00	\$62,000.0
		0001	0130	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING	1,297.00	0.00	1,297.00	LF	1,297.00	\$1.05	\$1,361.8
					PAINT, TYPE L BEADS							
		0001	0140	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	1,523.00	0.00	1,523.00	LF	1,523.00	\$1.05	\$1,599.1
		0001	0150	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	592.00	0.00	592.00	LF	592.00	\$1.05	\$621.6
		0001	0160	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	592.00	0.00	592.00	LF	592.00	\$1.05	\$621.6
		0001	0170	6214600A	FLOWABLE BACKFILL	5.00	0.00	5.00	CUYD	5.00	\$450.00	\$2,250.0
		0001	0180	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF	211.00	0.00	211.00	SQYD	0.00	\$27.00	\$0.0
		0001	0190	6240103A	SURFACING (3 IN. THICK OR LESS) PERMANENT EROSION CONTROL GEOTEXTILE	643.00	0.00	643.00	SQYD	0.00	\$2.40	\$0.0
		0001	0200	8061019	SILT FENCE	740.00	0.00	740.00	LF	0.00	\$4.00	\$0.0
		0010	0210	6061060	MGS GUARDRAIL	1,783.00	0.00	1,783.00	LF	1,720.00	\$20.20	\$34,744.0
		0010	0220	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED	8.00	0.00	8.00	EA	6.00	\$3,200.00	\$19,200.0
			0220	6061060	CURB)	2.00	0.00	3.00	ΕΛ.	2.00		
		0010	0230	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	3.00	0.00	3.00	EA	3.00	\$3,100.00	\$9,300.0
		0010	0240	6061074	MGS HEIGHT AND BLOCK TRANSITION	2.00	0.00	2.00	EA	2.00	\$640.00	\$1,280.0
		0010	0250	6061080	MGS END ANCHOR	2.00	0.00	2.00	EA	1.00	\$1,000.00	\$1,000.0
		0010	0260	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	12.00	0.00	12.00	EA	11.00	\$2,800.00	\$30,800.0
		0030	0270	9029902	MISC.MISC. PULLBOX ADJUSTMENT	1.00	0.00	1.00	EA	1.00	\$1,200.00	\$1,200.0
		0070	0280	2062000	CLASS 2 EXCAVATION	16.00	0.00	16.00	CUYD	0.00	\$770.00	\$0.0
		0070	0290	6233000	EPOXY POLYMER WEARING SURFACE	893.00	0.00	893.00	SQYD	893.00	\$35.00	\$31,255.0
		0070	0300	7040113	CLEANING AND EPOXY COATING	18.00	0.00	18.00	SQFT	0.00	\$74.00	\$0.0
		0070	0310	7049902	MISC.FRP PILE JACKETING SYSTEM	14.00	0.00	14.00	EA	0.00	\$3,300.00	\$0.0
		0070	0320	7049904	MISC.REPAIRING BRIDGE APPROACH SLAB (HALF-SOLING)	50.00	0.00	50.00	SQFT	34.00	\$112.00	\$3,808.0
		0070	0330	7125102	SURFACE PREPARATION FOR APPLYING EPOXY-MASTIC PRIMER	1.00	0.00	1.00	LS	0.00	\$11,500.00	\$0.0
		0070	0340	7125961	GRAY EPOXY-MASTIC PRIMER	1.00	0.00	1.00	LS	0.00	\$5,300.00	\$0.0
		0070	0350	7173002	SILICONE EXPANSION JOINT SEALANT	116.00	0.00	116.00	LF	116.00	\$33.80	\$3,920.8
		0071	0360	2062000	CLASS 2 EXCAVATION	18.00	0.00	18.00	CUYD	9.00	\$850.00	\$7,650.0
		0071	0370	6233000	EPOXY POLYMER WEARING SURFACE	1,116.00	0.00	1,116.00	SQYD	1,116.00	\$32.50	\$36,270.0
		0071	0380	7040113	CLEANING AND EPOXY COATING	7.00	0.00	7.00	SQFT	0.00	\$74.00	\$0.0
		0071	0390	7049902	MISC.FRP PILE JACKETING SYSTEM	16.00	0.00	16.00	EA	8.00	\$3,550.00	\$28,400.0
		0071	0400	7049904	MISC.REPAIRING BRIDGE APPROACH SLAB (HALF-SOLING)	180.00	0.00	180.00	SQFT	91.00	\$86.50	\$7,871.
		0071	0410	7125102	SURFACE PREPARATION FOR APPLYING EPOXY-MASTIC PRIMER	1.00	0.00	1.00	LS	0.50	\$11,900.00	\$5,950.0
		0071	0420	7125961	GRAY EPOXY-MASTIC PRIMER	1.00	0.00	1.00	LS	0.00	\$5,300.00	\$0.0
		0071	0430	7173002	SILICONE EXPANSION JOINT SEALANT	189.00	0.00	189.00	LF	189.00	\$32.50	\$6,142.5

Revision 4/1/2020 Page 6 of 15



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200320-F10	J6S3287	0072	0440	6233000	EPOXY POLYMER WEARING SURFACE	946.00	0.00	946.00	SQYD	946.00	\$34.00	\$32,164.00
		0072	0450	7040113	CLEANING AND EPOXY COATING	60.00	0.00	60.00	SQFT	30.00	\$74.00	\$2,220.00
		0072	0460	7129902	MISC.CORED SLAB DRAINS	18.00	0.00	18.00	EA	18.00	\$1,000.00	\$18,000.00
		0072	0470	7173002	SILICONE EXPANSION JOINT SEALANT	138.00	0.00	138.00	LF	138.00	\$37.00	\$5,106.00
		0073	0480	2062000	CLASS 2 EXCAVATION	16.00	0.00	16.00	CUYD	16.00	\$840.00	\$13,440.00
		0073	0490	6233000	EPOXY POLYMER WEARING SURFACE	1,415.00	0.00	1,415.00	SQYD	1,415.00	\$35.50	\$50,232.50
		0073	0500	7049902	MISC.FRP PILE JACKETING SYSTEM	14.00	0.00	14.00	EA	14.00	\$3,150.00	\$44,100.00
		0073	0510	7125102	SURFACE PREPARATION FOR APPLYING EPOXY-MASTIC PRIMER	1.00	0.00	1.00	LS	1.00	\$11,800.00	\$11,800.00
		0073	0520	7125961	GRAY EPOXY-MASTIC PRIMER	1.00	0.00	1.00	LS	1.00	\$5,300.00	\$5,300.00
		0073	0530	7173002	SILICONE EXPANSION JOINT SEALANT	134.00	0.00	134.00	LF	134.00	\$37.00	\$4,958.00
		0074	0540	6233000	EPOXY POLYMER WEARING SURFACE	969.00	0.00	969.00	SQYD	969.00	\$33.80	\$32,752.20
		0074	0550	7173002	SILICONE EXPANSION JOINT SEALANT	123.00	0.00	123.00	LF	0.00	\$38.00	\$0.00
		0075	0560	6233000	EPOXY POLYMER WEARING SURFACE	266.00	0.00	266.00	SQYD	266.00	\$65.00	\$17,290.00
		0075	0570	7173002	SILICONE EXPANSION JOINT SEALANT	110.00	0.00	110.00	LF	0.00	\$40.00	\$0.00
	Project J	6S3287 - To	tal Value	Posted to I	Date as of Report Generated Date							\$636,249.95
200320-F10 Ove	rall - Total	Value Post	ed to Dat	te as of Rep	ort Generated Date							\$636,249.95

Revision 4/1/2020 Page 7 of 15



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line are details from Line Item agency views.

No Agency View Details Exist

Revision 4/1/2020 Page 8 of 15



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0050	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	Material		1	May 18, 2020	SYSTEM	(\$900.00)	
				1	May 18, 2020	SYSTEM	\$900.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user steppr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				2	Jun 3, 2020	SYSTEM	(\$900.00)	
				2	Jun 3, 2020	SYSTEM	\$900.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user steppr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				3	Jun 16, 2020	SYSTEM	(\$900.00)	
				3	Jun 16, 2020	SYSTEM	\$900.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user steppr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				4	Jul 1, 2020	SYSTEM	(\$900.00)	
				4	Jul 1, 2020	SYSTEM	\$900.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user steppr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				5	Jul 17, 2020	SYSTEM	(\$900.00)	
				5	Jul 17, 2020	SYSTEM	\$900.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user steppr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				6	Aug 3, 2020	SYSTEM	(\$900.00)	
				6	Aug 3, 2020	SYSTEM	\$900.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user steppr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0050 -	· Total						\$0.00	
0060	FURNISHING TYPE 2 ROCK BLANKET	Material		3	Jun 16, 2020	SYSTEM	(\$14,620.00)	
				3	Jun 16, 2020	SYSTEM	\$14,620.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user steppr1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0060 -	· Total						\$0.00	
0130	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT	Material		5	Jul 17, 2020	SYSTEM	(\$1,361.85)	
	MARKING PAINT, TYPE L BEADS			5	Jul 17, 2020	SYSTEM	\$1,361.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user steppr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				6	Aug 3, 2020	SYSTEM	(\$1,361.85)	
				6	Aug 3, 2020	SYSTEM	\$1,361.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user steppr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0130 -	Total						\$0.00	
0140	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		5	Jul 17, 2020	SYSTEM	(\$1,599.15)	
	MANAMING FAINT, TIPE L DEAUS			5	Jul 17, 2020	SYSTEM	\$1,599.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user steppr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				6	Aug 3, 2020	SYSTEM	(\$1,599.15)	
				6	Aug 3, 2020	SYSTEM	\$1,599.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user steppr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
			- Total				\$0.00	

Revision 4/1/2020 Page 9 of 15



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks							
0140	Material - Total		. 71-				\$0.00								
0140 -	· Total						\$0.00								
0150	4 IN. WHITE STANDARD WATERBORNE PAVEMENT	Material		5	Jul 17, 2020	SYSTEM	(\$621.60)								
	MARKING PAINT, TYPE P BEADS			5	Jul 17, 2020	SYSTEM	\$621.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user steppr1 overridding Payment Estimate Exception 8 on the current Payment Estimate.							
				6	Aug 3, 2020	SYSTEM	(\$621.60)								
				6	Aug 3, 2020	SYSTEM	\$621.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user steppr1 overridding Payment Estimate Exception 8 on the current Payment Estimate.							
			- Total				\$0.00								
	Material - Total						\$0.00								
0150 -	· Total						\$0.00								
0160	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		5	Jul 17, 2020	SYSTEM	(\$621.60)								
	WARNING FAINT, TIPE F BEADS			5	Jul 17, 2020	SYSTEM	\$621.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user steppr1 overridding Payment Estimate Exception 10 on the current Payment Estimate.							
				6	Aug 3, 2020	SYSTEM	(\$621.60)								
				6	Aug 3, 2020	SYSTEM	\$621.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user steppr1 overridding Payment Estimate Exception 10 on the current Payment Estimate.							
			- Total				\$0.00								
	Material - Total						\$0.00								
0160 -	·Total						\$0.00								
0170	FLOWABLE BACKFILL	Material		1	May 18, 2020	SYSTEM	(\$2,250.00)								
											1	May 18, 2020	SYSTEM	\$2,250.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user steppr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				2	Jun 3, 2020	SYSTEM	(\$2,250.00)								
				2	Jun 3, 2020	SYSTEM	\$2,250.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user steppr1 overridding Payment Estimate Exception 12 on the current Payment Estimate.							
				3	Jun 16, 2020	SYSTEM	(\$2,250.00)								
				3	Jun 16, 2020	SYSTEM	\$2,250.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user steppr1 overridding Payment Estimate Exception 14 on the current Payment Estimate.							
				4	Jul 1, 2020	SYSTEM	(\$2,250.00)								
				4	Jul 1, 2020	SYSTEM	\$2,250.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user steppr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.							
				5	Jul 17, 2020	SYSTEM	(\$2,250.00)								
				5	Jul 17, 2020	SYSTEM	\$2,250.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user steppr1 overridding Payment Estimate Exception 12 on the current Payment Estimate.							
				6	Aug 3, 2020	SYSTEM	(\$2,250.00)								
				6	Aug 3, 2020	SYSTEM	\$2,250.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user steppr1 overridding Payment Estimate Exception 12 on the current Payment Estimate.							
			- Total				\$0.00								
	Material - Total						\$0.00								
0170 -	Total						\$0.00								
0210	MGS GUARDRAIL	Material		1	May 18, 2020	SYSTEM	(\$11,615.00)								
				1	May 18, 2020	SYSTEM	\$11,615.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user steppr1 overridding Payment							

Revision 4/1/2020 Page 10 of 15



1.5	Deseriation	Adimeter	O#	F-4	0	0	Λ	DewI
Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0210	MGS GUARDRAIL	Material						Estimate Exception 1 on the current Payment Estimate.
				2	Jun 3, 2020	SYSTEM	(\$26,765.00)	
				2	Jun 3, 2020	SYSTEM	\$26,765.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user steppr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				3	Jun 16, 2020	SYSTEM	(\$34,744.00)	
				3	Jun 16, 2020	SYSTEM	\$34,744.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user steppr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0210 -	Total						\$0.00	
0220	MGS BRIDGE APPROACH TRANSITION SECTION	Material		2	Jun 3, 2020	SYSTEM	(\$6,400.00)	
	(EXTENDED CURB)			2	Jun 3, 2020	SYSTEM	\$6,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user steppr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				3	Jun 16, 2020	SYSTEM	(\$19,200.00)	
				3	Jun 16, 2020	SYSTEM	\$19,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user steppr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0220 -	Total						\$0.00	
0230	MGS BRIDGE APPROACH TRANSITION SECTION	Material		1	May 18, 2020	SYSTEM	(\$6,200.00)	
	(REGULAR/NO CURB)			1	May 18, 2020	SYSTEM	\$6,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user steppr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				2	Jun 3, 2020	SYSTEM	(\$9,300.00)	
				2	Jun 3, 2020	SYSTEM	\$9,300.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user steppr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				3	Jun 16, 2020	SYSTEM	(\$9,300.00)	
				3	Jun 16, 2020	SYSTEM	\$9,300.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user steppr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0230 - 0250	Total MGS END ANCHOR	Material		3	Jun 16,	SYSTEM	\$0.00 (\$1,000.00)	
				3	2020 Jun 16, 2020	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user steppr1 overridding Payment
			- Total				\$0.00	Estimate Exception 4 on the current Payment Estimate.
	Material - Total		Total				\$0.00	
0250 -							\$0.00	
0260	TYPE A CRASHWORTHY END TERMINAL (MASH)	Material		1	May 18, 2020	SYSTEM	(\$5,600.00)	
	()			1	May 18, 2020	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user steppr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				2	Jun 3, 2020	SYSTEM	(\$16,800.00)	•
				2	Jun 3, 2020	SYSTEM	\$16,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user steppr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				3	Jun 16,	SYSTEM	(\$30,800.00)	

Revision 4/1/2020 Page 11 of 15



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0260	TYPE A CRASHWORTHY END	Material			2020			
	TERMINAL (MASH)			3	Jun 16, 2020	SYSTEM	\$30,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user steppr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0260 -	Total						\$0.00	
0290	EPOXY POLYMER WEARING SURFACE	Material		4	Jul 1, 2020	SYSTEM	(\$31,255.00)	
				4	Jul 1, 2020	SYSTEM	\$31,255.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user steppr1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total					\$0.00		
0290 -							\$0.00	
0350	SILICONE EXPANSION JOINT SEALANT	Material		1	May 18, 2020	SYSTEM	(\$3,920.80)	
				1	May 18, 2020	SYSTEM	\$3,920.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user steppr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
				2	Jun 3, 2020	SYSTEM	(\$3,920.80)	
				2	Jun 3, 2020	SYSTEM	\$3,920.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user steppr1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
				3	Jun 16, 2020	SYSTEM	(\$3,920.80)	
				3	Jun 16, 2020	SYSTEM	\$3,920.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user steppr1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
				4	Jul 1, 2020	SYSTEM	(\$3,920.80)	
				4	Jul 1, 2020	SYSTEM	\$3,920.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user steppr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
				5	Jul 17, 2020	SYSTEM	(\$3,920.80)	
				5	Jul 17, 2020	SYSTEM	\$3,920.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user steppr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
				6	Aug 3, 2020	SYSTEM	(\$3,920.80)	
				6	Aug 3, 2020	SYSTEM	\$3,920.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user steppr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
		- Total	- Total			\$0.00		
	Material - Total						\$0.00	
0350 -	Total						\$0.00	
0370	EPOXY POLYMER WEARING SURFACE	Material		4	Jul 1, 2020	SYSTEM	(\$36,270.00)	
				4	Jul 1, 2020	SYSTEM	\$36,270.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user steppr1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
	- Total						\$0.00	
	Material - Total						\$0.00	
0370 -	Total						\$0.00	
0430	SILICONE EXPANSION JOINT SEALANT	Material		1	May 18, 2020	SYSTEM	(\$6,142.50)	
				1	May 18, 2020	SYSTEM	\$6,142.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user steppr1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				2	Jun 3, 2020	SYSTEM	(\$6,142.50)	
				2	Jun 3,	SYSTEM	\$6,142.50	This adjustment offsets the original system-generated Overrun Payment

Revision 4/1/2020 Page 12 of 15



Decomption									
SEALANT	Line	Description		Adjustment				Amount	Remarks
2000 3 2000 3	0430		Material			2020			
Aug. SYSTEM (55.142.50)					3		SYSTEM	(\$6,142.50)	
4					3		SYSTEM	\$6,142.50	Estimate Item Adjustment (0010) due to user steppr1 overridding Payment
2000 1					4		SYSTEM	(\$6,142.50)	
2000					4		SYSTEM	\$6,142.50	Estimate Item Adjustment (0006) due to user steppr1 overridding Payment
2000					5		SYSTEM	(\$6,142.50)	
Aug. System Sp. 142.50 Sp					5		SYSTEM	\$6,142.50	Estimate Item Adjustment (0008) due to user steppr1 overridding Payment
Part					6		SYSTEM	(\$6,142.50)	
Material - Total So.00					6		SYSTEM	\$6,142.50	Estimate Item Adjustment (0008) due to user steppr1 overridding Payment
Material - Total So.00			- Total				\$0.00		
Section		Material - Total							
EPOXY POLYMER WEARING Material	0.400								
2020 4 Jul 1, 2020 4 Jul 1, 2020 5 5 5 5 5 5 5 5 5									
Aug Carried Carried	0440		Material			2020		,	
Material - Total So.00					4		SYSTEM	\$32,164.00	Estimate Item Adjustment (0007) due to user steppr1 overridding Payment
				- Total				\$0.00	
CLEANING AND EPOXY COATING		Material - Total						\$0.00	
CLEANING AND EPOXY COATING	0440 -	· Total						\$0.00	
2020 Setimate (mn Adjustment (0011) due to user stepptr overridding Payment Estimate Exception 15 on the current Payment Estimate Exception 15 on the current Payment Estimate.		CLEANING AND EPOXY	Material		3		SYSTEM		
2020					3		SYSTEM	\$2,220.00	Estimate Item Adjustment (0011) due to user steppr1 overridding Payment
2020 Estimate Item Adjustment (0008) due to user steppr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.					4		SYSTEM	(\$2,220.00)	
2020					4		SYSTEM	\$2,220.00	Estimate Item Adjustment (0008) due to user steppr1 overridding Payment
2020 Estimate Item Adjustment (0009) due to user steppr1 overridding Payment Estimate Exception 13 on the current Payment Estimate.					5		SYSTEM	(\$2,220.00)	
2020 SYSTEM \$2,220.00 This adjustment offsets the original system-generated Overrun Payment Estimate Estimate Exception 13 on the current Payment Estimate. - Total					5		SYSTEM	\$2,220.00	Estimate Item Adjustment (0009) due to user steppr1 overridding Payment
Summer S					6		SYSTEM	(\$2,220.00)	
Material - Total Solution Silicone Expansion Joint SEALANT Silicone Expansion Joint SEALANT Material Jun 16, 2020 Jun 16, 2020 System System (\$5,106.00) This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user steppr1 overridding Payment Estimate Exception 19 on the current Payment Estimate. Jul 1, 2020 Jul 1, 2020 System (\$5,106.00) Jul 1, 2020 This adjustment offsets the original system-generated Overrun Payment Estimate Exception 19 on the current Payment Estimate. Jul 1, 2020 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user steppr1 overridding Payment Estimate Item Adjustment (0009) due to user steppr1 overridding Payment					6		SYSTEM	\$2,220.00	Estimate Item Adjustment (0009) due to user steppr1 overridding Payment
Material - Total S0.00 0450 - Total SILICONE EXPANSION JOINT SEALANT Material 3 Jun 16, 2020 SYSTEM (\$5,106.00) 3 Jun 16, 2020 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user steppr1 overridding Payment Estimate Exception 19 on the current Payment Estimate Exception 19 on the current Payment Estimate. 4 Jul 1, 2020 4 Jul 1, 2020 SYSTEM \$5,106.00 This adjustment offsets the original system-generated Overrun Payment Estimate Exception 19 on the current Payment Estimate.				- Total				\$0.00	
0470 SILICONE EXPANSION JOINT SEALANT Material 3 Jun 16, 2020 4 Jul 1, 2020 4 Jul 1, 2020 4 Jul 1, 2020 SYSTEM \$5,106.00 This adjustment offsets the original system-generated Overrun Payment Estimate Exception 19 on the current Payment Estimate. 4 Jul 1, 2020 4 Jul 1, 2020 This adjustment offsets the original system-generated Overrun Payment Estimate Exception 19 on the current Payment Estimate.		Material - Total							
SILICONE EXPANSION JOINT SEALANT Material 3 Jun 16, 2020 4 Jul 1, 2020 5 SYSTEM (\$5,106.00) This adjustment offsets the original system-generated Overrun Payment Estimate Exception 19 on the current Payment Estimate. 4 Jul 1, 2020 5 SYSTEM (\$5,106.00) This adjustment offsets the original system-generated Overrun Payment Estimate Exception 19 on the current Payment Estimate.	0.450								
3 Jun 16, 2020 \$5,106.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user steppr1 overridding Payment Estimate Exception 19 on the current Payment Estimate. 4 Jul 1, 2020 \$YSTEM (\$5,106.00) 4 Jul 1, 2020 \$This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user steppr1 overridding Payment		SILICONE EXPANSION JOINT	Material		3		SYSTEM		
4 Jul 1, 2020 (\$5,106.00) 4 Jul 1, SYSTEM (\$5,106.00) 5 Jul 1, SYSTEM 2020 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user steppr1 overridding Payment					3	Jun 16,	SYSTEM	\$5,106.00	Estimate Item Adjustment (0012) due to user steppr1 overridding Payment
4 Jul 1, SYSTEM \$5,106.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user steppr1 overridding Payment					4		SYSTEM	(\$5,106.00)	2.3
						2020			

Revision 4/1/2020 Page 13 of 15



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0470	SILICONE EXPANSION JOINT SEALANT	Material		5	Jul 17, 2020	SYSTEM	(\$5,106.00)	
				5	Jul 17, 2020	SYSTEM	\$5,106.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user steppr1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
				6	Aug 3, 2020	SYSTEM	(\$5,106.00)	
				6	Aug 3, 2020	SYSTEM	\$5,106.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user steppr1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0470 -	· Total						\$0.00	
0490	EPOXY POLYMER WEARING SURFACE	Material		4	Jul 1, 2020	SYSTEM	(\$50,232.50)	
				4	Jul 1, 2020	SYSTEM	\$50,232.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user steppr1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
		Total				60.00	Estimate Exception 6 on the current Payment Estimate.	
	Material - Total		- Total				\$0.00	
0.400							\$0.00	
0490 -						2) (2===	\$0.00	
0520	GRAY EPOXY-MASTIC PRIMER	Material		1	May 18, 2020	SYSTEM	(\$5,300.00)	
				1	May 18, 2020	SYSTEM	\$5,300.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user steppr1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				2	Jun 3, 2020	SYSTEM	(\$5,300.00)	
				2	Jun 3, 2020	SYSTEM	\$5,300.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user steppr1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				3	Jun 16, 2020	SYSTEM	(\$5,300.00)	
				3	Jun 16, 2020	SYSTEM	\$5,300.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user steppr1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
				4	Jul 1, 2020	SYSTEM	(\$5,300.00)	
				4	Jul 1, 2020	SYSTEM	\$5,300.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user steppr1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				5	Jul 17, 2020	SYSTEM	(\$5,300.00)	
				5	Jul 17, 2020	SYSTEM	\$5,300.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user steppr1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				6	Aug 3, 2020	SYSTEM	(\$5,300.00)	
				6	Aug 3, 2020	SYSTEM	\$5,300.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user steppr1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0520 -	Total						\$0.00	
0530	SILICONE EXPANSION JOINT SEALANT	Material		1	May 18, 2020	SYSTEM	(\$4,958.00)	
				1	May 18, 2020	SYSTEM	\$4,958.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user steppr1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				2	Jun 3, 2020	SYSTEM	(\$4,958.00)	
				2	Jun 3, 2020	SYSTEM	\$4,958.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user steppr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
				3	Jun 16, 2020	SYSTEM	(\$4,958.00)	

Revision 4/1/2020 Page 14 of 15



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0530	SILICONE EXPANSION JOINT SEALANT	Material		3	Jun 16, 2020	SYSTEM	\$4,958.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user steppr1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
				4	Jul 1, 2020	SYSTEM	(\$4,958.00)	
				4	Jul 1, 2020	SYSTEM	\$4,958.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user steppr1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				5	Jul 17, 2020	SYSTEM	(\$4,958.00)	
				5	Jul 17, 2020	SYSTEM	\$4,958.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user steppr1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
				6	Aug 3, 2020	SYSTEM	(\$4,958.00)	
				6	Aug 3, 2020	SYSTEM	\$4,958.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user steppr1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0530 -	- Total						\$0.00	
0540	EPOXY POLYMER WEARING SURFACE	Material		4	Jul 1, 2020	SYSTEM	(\$32,752.20)	
				4	Jul 1, 2020	SYSTEM	\$32,752.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user steppr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
	- Total						\$0.00	
	Material - Total						\$0.00	
0540	- Total						\$0.00	
0560	EPOXY POLYMER WEARING SURFACE	Material		4	Jul 1, 2020	SYSTEM	(\$17,290.00)	
				4	Jul 1, 2020	SYSTEM	\$17,290.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user steppr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
	- Total						\$0.00	
	Material - Total						\$0.00	
0560	- Total						\$0.00	
Overa	all - Total						\$0.00	

Revision 4/1/2020 Page 15 of 15