

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: July 16, 2020

Progress Estimate Number	Contract ID	200320-F11	Pay Period Start	July 1, 2020	Original Contract Am	nount \$723,851.90
2	Prime Contractor	L.F. Krupp Construction, Inc. dba Krupp	Pay Period End	July 15, 2020	Net Change Order Amount Current Contract Am	\$0.00 ount \$723,851.90

By User		Approval Date
mckinm1	Generated and Approved (and should be considered Draft) at the Project Office Level by	July 16, 2020
vancef1	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	July 17, 2020
greggd1	Reviewed and Approved at the Central Office Controllers Office Level by	July 17, 2020

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
November 2, 2020	November 2, 2020		21.60%

No Milestones Exist for Contract

Contract Total Pa	ay For Estimate No. 2				
		This Estimate	Previous	To Date	
200320-F11					
	Total Posted Items Pay	\$105,745.70	\$50,627.30	\$156,373.00	
	Gross Item Adjustments	\$0.00	\$0.00	\$0.00	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
	•		\$50,627.30	\$156,373.00	
Contract Total Pa	ayable This Estimate:	\$105,745.70			

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6S3390	0090	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	SQYD	\$7.000	1,417	\$9,919.00
	0110	4010150	TYPE A2 SHOULDER	SQYD	\$29.300	224	\$6,563.20
	0120	4029905	MISC.OPTIONAL PAVEMENT	SQYD	\$48.500	627	\$30,409.50
	0171	6181000	MOBILIZATION	LS	\$90,530.000	0.5	\$45,265.00
	0390	8061006	ALTERNATE DITCH CHECK	LF	\$8.000	32	\$256.00
	0470	9015010	TRENCHING TYPE I	LF	\$4.750	740	\$3,515.00
	0530	9028824	PULL BOX, CONCRETE, DOUBLE TYPE B	EA	\$2,800.000	1	\$2,800.00
	5001	6189901	MISC.Adjust Mobilization for Contract Bond	LS	\$7,018.000	1	\$7,018.00
Project J6S339	00 - Total						\$105,745.70
Overall - Total							\$105,745.70

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

	,	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6S3390	0040	COMPACTING EMBANKMENT	Material			-309	\$14.25	(\$4,403.25)
	0040	COMPACTING EMBANKMENT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0001) due to user mckinm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	309	\$14.25	\$4,403.25
	0050	COMPACTING IN CUT	Material			-15.5	\$160.00	(\$2,480.00)
	0050	COMPACTING IN CUT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0002) due to user mckinm1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	15.5	\$160.00	\$2,480.00

Revision 4/1/2020 Page 1 of 9



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: July 16, 2020

Pay Period **Progress Estimate** Contract ID 200320-F11 July 1, 2020 Original Contract Amount \$723,851.90 Number Start Pay Period End July 15, 2020 Prime L.F. Krupp Construction, Inc. dba **Net Change Order** 2 \$0.00 Amount \$0.00 Current Contract Amount \$723,851.90 Contractor Krupp

Project lumber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustmen amount
6S3390	0090	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material	71		-1,417	\$7.00	(\$9,919.00
	0090	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0003) due to user mckinm1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	1,417	\$7.00	\$9,919.00
	0110	TYPE A2 SHOULDER	Material			-224	\$29.30	(\$6,563.20
	0110	TYPE A2 SHOULDER	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0004) due to user mckinm1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	224	\$29.30	\$6,563.20
	0380	ROCK DITCH CHECK	Material			-50	\$18.00	(\$900.00)
	0380	ROCK DITCH CHECK	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0005) due to user mckinm1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	50	\$18.00	\$900.00
	0390	ALTERNATE DITCH CHECK	Material			-112	\$8.00	(\$896.00)
	0390	ALTERNATE DITCH CHECK	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0006) due to user mckinm1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	112	\$8.00	\$896.00
	0420	SILT FENCE	Material			-1,370	\$2.15	(\$2,945.50
	0420	SILT FENCE	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0007) due to user mckinm1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	1,370	\$2.15	\$2,945.50
	0530	PULL BOX, CONCRETE, DOUBLE TYPE B	Material			-1	\$2,800.00	(\$2,800.00)
	0530	PULL BOX, CONCRETE, DOUBLE TYPE B	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0008) due to user mckinm1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	1	\$2,800.00	\$2,800.00
otal								\$0.00

Revision 4/1/2020 Page 2 of 9



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Information	
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J6S3390	FAF-30-1(46)	Grading and pavement	30	JEFFERSON	from Rivermont T	rail to 0.5 miles west and the	en from Local Hillsboro Road to 500 f
Totalo by	Job Numbers						
•	Job Nullibers						
J6S3390	Posted Ite	m Pay			This Estimate \$105,745.70	Previous \$50,627.30	To Date \$156,373.00
•	Posted Ite	n Adjustments	s Gross Iter	m Pay			
•	Posted Ite	n Adjustments		т Рау	\$105,745.70 \$0.00	\$50,627.30 \$0.00	\$156,373.00 \$0.00
•	Posted Ite	n Adjustments G		т Рау	\$105,745.70 \$0.00 \$105,745.70	\$50,627.30 \$0.00 \$50,627.30	\$156,373.00 \$0.00 \$156,373.00
•	Posted Ite Gross Iter Incentive Disincenti	n Adjustments G		m Pay	\$105,745.70 \$0.00 \$105,745.70 \$0.00	\$50,627.30 \$0.00 \$50,627.30 \$0.00	\$156,373.00 \$0.00 \$156,373.00 \$0.00

Revision 4/1/2020 Page 3 of 9



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6S3390, Item 2036000, Project Item Line Number 0040, Material Set 203600096, Material 0200XXCS - Compacted Soil for Subgrade or Embankment, Acceptance Action Generic 0200XXCS is insufficient.	No Remark was entered by Engineer	mckinm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3390, Item 2037075, Project Item Line Number 0050, Material Set 203707596, Material 0200XXCS - Compacted Soil for Subgrade orEmbankment, Acceptance Action Generic 0200XXCS is insufficient.	No Remark was entered by Engineer	mckinm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3390, Item 3040506, Project Item Line Number 0090, Material Set 304050696, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	No Remark was entered by Engineer	mckinm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3390, Item 4010150, Project Item Line Number 0110, Material Set 401015096, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	No Remark was entered by Engineer	mckinm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3390, Item 4010150, Project Item Line Number 0110, Material Set 401015096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	mckinm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3390, Item 4010150, Project Item Line Number 0110, Material Set 401015096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	mckinm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3390, Item 4010150, Project Item Line Number 0110, Material Set 401015096, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	No Remark was entered by Engineer	mckinm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3390, Item 8061005, Project Item Line Number 0380, Material Set 806100596, Material 0806TEC - Temporary Erosion Control, Acceptance Action Generic 0806TEC is insufficient.	No Remark was entered by Engineer	mckinm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3390, Item 8061006, Project Item Line Number 0390, Material Set 806100696, Material 0806TEC - Temporary Erosion Control, Acceptance Action Generic 0806TEC is insufficient.	No Remark was entered by Engineer	mckinm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3390, Item 8061019, Project Item Line Number 0420, Material Set 806101996, Material 1011GXT2 - Geotextile Fabric for TempSiltFence (T2), Acceptance Action Generic 1011GXT2 is insufficient.	No Remark was entered by Engineer	mckinm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3390, Item 9028824, Project Item Line Number 0530, Material Set 902882496, Material 1062PBPC - Pull Box Precast Concrete, Acceptance Action Generic 1062PBPC is insufficient.	No Remark was entered by Engineer	mckinm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3390, Item 9028824, Project Item Line Number 0530, Material Set 902882496, Material 1062PBFC - Frame and Cover for Concrete Pull Box, Acceptance Action Generic 1062PBFC is insufficient.	No Remark was entered by Engineer	mckinm1	Overridder

Revision 4/1/2020 Page 4 of 9



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200320-F11	J6S3390	0001	0010	2013000	CLEARING AND GRUBBING	1.00	0.00	1.00	ACRE	1.00	\$1.00	\$1.00
		0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.10	\$16,935.00	\$1,693.50
		0001	0030	2031000	CLASS A EXCAVATION	2,932.00	0.00	2,932.00	CUYD	1,307.00	\$19.45	\$25,421.15
		0001	0040	2036000	COMPACTING EMBANKMENT	548.00	0.00	548.00	CUYD	309.00	\$14.25	\$4,403.2
		0001	0050	2037075	COMPACTING IN CUT	31.50	0.00	31.50	STA	15.50	\$160.00	\$2,480.0
		0001	0060	2063000	CLASS 3 EXCAVATION	82.00	0.00	82.00	CUYD	0.00	\$24.55	\$0.0
		0001	0070	2063500	CULVERT CLEANOUT	3.00	0.00	3.00	EA	0.00	\$1,000.00	\$0.0
		0001	0080	2072000	LINEAR GRADING CLASS 2	0.20	0.00	0.20	STA	0.00	\$1,725.00	\$0.0
		0001	0090	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	6,029.00	0.00	6,029.00	SQYD	1,417.00	\$7.00	\$9,919.0
		0001	0100	3105003	GRAVEL (A) OR CRUSHED STONE (B)	61.00	0.00	61.00	SQYD	0.00	\$9.30	\$0.0
		0001	0110	4010150	TYPE A2 SHOULDER	885.00	0.00	885.00	SQYD	224.00	\$29.30	\$6,563.2
		0001	0120	4029905	MISC.OPTIONAL PAVEMENT	5,144.00	0.00	5,144.00	SQYD	627.00	\$48.50	\$30,409.5
		0001	0130	6083006	6 IN. CONCRETE MEDIAN STRIP	356.00	0.00	356.00	SQYD	0.00	\$16.50	\$0.0
		0001	0140	6097000	ROCK LINING	7.00	0.00	7.00	CUYD	0.00	\$150.00	\$0.0
		0001	0150	6169901	MISC.TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.25	\$21,280.00	\$5,320.0
		0001	0160	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN, CONTRACTOR FURNISHED/RETAINED	2.00	0.00	2.00	EA	1.00	\$2,800.00	\$2,800.0
		0001	0170	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$97,548.00	\$0.0
		0001	0171	6181000	MOBILIZATION	0.00	1.00	1.00	LS	0.50	\$90,530.00	\$45,265.0
		0001	0180	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	2.00	0.00	2.00	EA	0.00	\$600.00	\$0.0
		0001	0190	6191000	PAVEMENT EDGE TREATMENT	3,173.00	0.00	3,173.00	LF	1,591.00	\$1.90	\$3,022.9
		0001	0200	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	28.00	0.00	28.00	LF	0.00	\$22.00	\$0.0
		0001	0210	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	18.00	0.00	18.00	EA	0.00	\$300.00	\$0.0
		0001	0220	6200042	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	27.00	0.00	27.00	EA	0.00	\$35.00	\$0.0
		0001	0230	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	382.00	0.00	382.00	LF	0.00	\$0.25	\$0.0
		0001	0240	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	8,074.00	0.00	8,074.00	LF	0.00	\$0.35	\$0.0
		0001	0250	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	2,869.00	0.00	2,869.00	LF	0.00	\$0.35	\$0.0
		0001	0260	6206000C	$4\ \mbox{IN}.$ WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	129.00	0.00	129.00	LF	0.00	\$0.25	\$0.0
		0001	0270	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	3.00	0.00	3.00	EA	0.00	\$100.00	\$0.0
		0001	0280	6209902	MISC.LANE REDUCTION ARROW	6.00	0.00	6.00	EA	0.00	\$750.00	\$0.0
		0001	0290	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.25	\$4,000.00	\$1,000.0
		0001	0300	7250318A	18 IN. PIPE GROUP B	49.00	0.00	49.00	LF	0.00	\$53.55	\$0.0
		0001	0310	7261018	18 IN. PIPE GROUP A	98.00	0.00	98.00	LF	0.00	\$62.80	\$0.0
		0001	0320	7261021	21 IN. PIPE GROUP A	92.00	0.00	92.00	LF	0.00	\$67.00	\$0.0
		0001	0330	7320018A	18 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION	2.00	0.00	2.00	EA	0.00	\$450.00	\$0.0
		0001	0340	7320618A	18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	2.00	0.00	2.00	EA	0.00	\$450.00	\$0.0
		0001	0350	7320621A	21 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	2.00	0.00	2.00	EA	0.00	\$500.00	\$0.0
		0001	0360	8051000A	SEEDING - COOL SEASON MIXTURES	1.20	0.00	1.20	ACRE	0.00	\$5,100.00	\$0.0
		0001	0370	8061002	SEDIMENT BASIN ROCK	11.70	0.00	11.70	CUYD	0.00	\$75.00	\$0.0
		0001	0380	8061005	ROCK DITCH CHECK	CK 168.00 0.00 168.00 LF 5		50.00	\$18.00	\$900.0		
		0001	0390	8061006	ALTERNATE DITCH CHECK	430.00	0.00	430.00	LF	112.00	\$8.00	\$896.0
		0001	0400	8061016	SEDIMENT REMOVAL	129.00	0.00	129.00	CUYD	0.00	\$1.00	\$0.0
		0001	0410	8061017	TEMPORARY SEEDING AND MULCHING	1.20	0.00	1.20	ACRE	0.00	\$1,800.00	\$0.0
		0001	0420	8061019	SILT FENCE	3,675.00	0.00	3,675.00	LF	1,370.00	\$2.15	\$2,945.5

Revision 4/1/2020 Page 5 of 9



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200320-F11	J6S3390	0020	0430	9011062	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 2	3.00	0.00	3.00	EA	0.00	\$2,828.00	\$0.00
		0020	0440	9011108	BRACKET ARM, 8 FT. OR 2.4 M	3.00	0.00	3.00	EA	0.00	\$619.00	\$0.00
		0020	0450	9011312	LUMINAIRE, LED-B	6.00	0.00	6.00	EA	0.00	\$758.00	\$0.00
		0020	0460	9014003	CONDUIT, 3 IN. RIGID, PUSHED	64.00	0.00	64.00	LF	0.00	\$32.00	\$0.00
		0020	0470	9015010	TRENCHING TYPE I	2,656.00	0.00	2,656.00	LF	740.00	\$4.75	\$3,515.00
		0020	0480	9016110	PULL BOX, PREFORMED CLASS 1	4.00	0.00	4.00	EA	0.00	\$1,210.00	\$0.00
		0020	0490	9017008	CABLE, 8 AWG 1 CONDUCTOR	160.00	0.00	160.00	LF	0.00	\$2.00	\$0.00
		0020	0500	9017208	WIRE, 8 AWG, BARE NEUTRAL	80.00	0.00	80.00	LF	0.00	\$1.00	\$0.00
		0020	0510	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	3,170.00	0.00	3,170.00	LF	0.00	\$2.50	\$0.00
		0020	0520	9018245	POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	3.00	0.00	3.00	EA	0.00	\$1,377.00	\$0.00
		0030	0530	9028824	PULL BOX, CONCRETE, DOUBLE TYPE B	1.00	0.00	1.00	EA	1.00	\$2,800.00	\$2,800.00
		0040	0540	9031010	CONCRETE FOOTINGS, EMBEDDED	10.40	0.00	10.40	CUYD	0.00	\$1,750.00	\$0.00
		0040	0550	9031210	STRUCTURAL STEEL POSTS	1,500.00	0.00	1,500.00	LB	0.00	\$4.50	\$0.00
		0040	0560	9031220	PIPE POSTS	6,150.00	0.00	6,150.00	LB	0.00	\$4.50	\$0.00
		0040	0570	9035004A	SH-FLAT SHEET	375.00	0.00	375.00	SQFT	0.00	\$23.00	\$0.00
		0040	0580	9035011A	ST-STRUCTURAL	87.00	0.00	87.00	SQFT	0.00	\$28.00	\$0.00
		0040	0590	9035069A	SHF-FLAT SHEET FLUORESCENT	18.00	0.00	18.00	SQFT	0.00	\$26.00	\$0.00
		0001	5001	6189901	MISC.Adjust Mobilization for Contract Bond	0.00	1.00	1.00	LS	1.00	\$7,018.00	\$7,018.00
	Project J	6S3390 - To	otal Value	Posted to D	Date as of Report Generated Date							\$156,373.00
200320-F11 Ove	rall - Total	Value Post	ed to Dat	e as of Repo	ort Generated Date							\$156,373.00

Revision 4/1/2020 Page 6 of 9



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J6S3390

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0090	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	7/6/20	7/15/20	1,417.00	SQYD	EB Rte 30 Acceleration Lane/Shoulder base course	1247+50	53	1239+00	53	
0110	4010150	TYPE A2 SHOULDER	7/8/20	7/15/20	224.00	SQYD	EB Rte 30 acceleration lane shoulder 67'Lt	1247+50	67	1243+48	67	
0120	4029905	MISC. BITUMINOUS PAVEMENT (SURF. LEVEL)	7/8/20	7/15/20	627.00	SQYD	EB Rte 30 Acceleration Lane 53' Lt	1247+50	53	1243+48	53	
0171	6181000	MOBILIZATION	7/15/20	7/16/20	0.50	LS	EB Rte 30 at Local Hillsboro Rd	1248+26	159	1233+00	53	
0390	8061006	ALTERNATE DITCH CHECK	7/15/20	7/16/20	32.00	LF	Rte 30 Median	1078+15	10	1066+00	10	
0470	9015010	TRENCHING TYPE I	7/15/20	7/16/20	740.00	LF	Rte 30 Median right of centerline	1078+15	10	1068+35	10	
0530	9028824	PULL BOX, CONCRETE, DOUBLE TYPE B	7/15/20	7/16/20	1.00	EA	EB Rte 30 at Local Hillsboro Rd	1247+90	90			
5001	6189901	MISC.	7/15/20	7/16/20	1.00	LS		1248+26	159	1233+00	53	

The information below this line are details from Line Item agency views. No Agency View Details Exist

Revision 4/1/2020 Page 7 of 9



Missouri Department of Transportation Contractor's Pay Estimate Summary Line Item Adjustments - All Estimates

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0040	COMPACTING EMBANKMENT	Material		1	Jul 1, 2020	SYSTEM	(\$4,403.25)	
				1	Jul 1, 2020	SYSTEM	\$4,403.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user mckinm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				2	Jul 16, 2020	SYSTEM	(\$4,403.25)	
				2	Jul 16, 2020	SYSTEM	\$4,403.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user mckinm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0040 -	- Total						\$0.00	
0050	COMPACTING IN CUT	Material		1	Jul 1, 2020	SYSTEM	(\$2,480.00)	
				1	Jul 1, 2020	SYSTEM	\$2,480.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user mckinm1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				2	Jul 16, 2020	SYSTEM	(\$2,480.00)	
				2	Jul 16, 2020	SYSTEM	\$2,480.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user mckinm1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0050 -	- Total						\$0.00	
0090	TYPE 5 AGGREGATE FOR	Material		2	Jul 16, 2020	SYSTEM	(\$9,919.00)	
	BASE (6 IN. THICK)			2	Jul 16, 2020	SYSTEM	\$9,919.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user mckinm1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	- Total			_			\$0.00	
0110	- Total TYPE A2 SHOULDER	Material		2	Jul 16, 2020	SYSTEM	(\$6,563.20)	
	TYPE A2	Material		2		SYSTEM	(\$6,563.20) \$6,563.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user mckinm1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
	TYPE A2 SHOULDER	Material	- Total		2020 Jul 16,		(\$6,563.20) \$6,563.20 \$0.00	Adjustment (0004) due to user mckinm1 overridding Payment Estimate Exception 4 on the
0110	TYPE A2 SHOULDER	Material	- Total		2020 Jul 16,		(\$6,563.20) \$6,563.20 \$0.00 \$0.00	Adjustment (0004) due to user mckinm1 overridding Payment Estimate Exception 4 on the
0110	TYPE A2 SHOULDER		- Total	2	Jul 16, 2020	SYSTEM	\$6,563.20 \$6,563.20 \$0.00 \$0.00	Adjustment (0004) due to user mckinm1 overridding Payment Estimate Exception 4 on the
0110	TYPE A2 SHOULDER	Material Material	- Total	2	Jul 1, 2020	SYSTEM	\$6,563.20 \$6,563.20 \$0.00 \$0.00 \$0.00 (\$3,022.90)	Adjustment (0004) due to user mckinm1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
0110	TYPE A2 SHOULDER Material - Total - Total PAVEMENT EDGE		- Total	2	Jul 16, 2020	SYSTEM	\$6,563.20 \$6,563.20 \$0.00 \$0.00	Adjustment (0004) due to user mckinm1 overridding Payment Estimate Exception 4 on the
0110	TYPE A2 SHOULDER Material - Total - Total PAVEMENT EDGE		- Total	2	Jul 16, 2020 Jul 16, 2020 Jul 1, 2020 Jul 1,	SYSTEM	\$6,563.20 \$6,563.20 \$0.00 \$0.00 \$0.00 (\$3,022.90)	Adjustment (0004) due to user mckinm1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user mckinm1 overridding Payment Estimate Exception 3 on the
0110	TYPE A2 SHOULDER Material - Total - Total PAVEMENT EDGE			2	Jul 16, 2020 Jul 16, 2020 Jul 1, 2020 Jul 1,	SYSTEM	\$6,563.20 \$6,563.20 \$0.00 \$0.00 \$0.00 \$3,022.90 \$3,022.90	Adjustment (0004) due to user mckinm1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user mckinm1 overridding Payment Estimate Exception 3 on the
0110 - 0110 - 0190	TYPE A2 SHOULDER Material - Total Total PAVEMENT EDGE TREATMENT			2	Jul 16, 2020 Jul 16, 2020 Jul 1, 2020 Jul 1,	SYSTEM	\$6,563.20 \$6,563.20 \$0.00 \$0.00 \$0.00 (\$3,022.90) \$3,022.90	Adjustment (0004) due to user mckinm1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user mckinm1 overridding Payment Estimate Exception 3 on the
0110 - 0110 - 0190	Material - Total PAVEMENT EDGE TREATMENT Material - Total			2	Jul 16, 2020 Jul 16, 2020 Jul 1, 2020 Jul 1,	SYSTEM	\$6,563.20 \$6,563.20 \$0.00 \$0.00 \$0.00 \$3,022.90 \$3,022.90 \$0.00 \$0.00	Adjustment (0004) due to user mckinm1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user mckinm1 overridding Payment Estimate Exception 3 on the
0110 - 0110 - 0190	TYPE A2 SHOULDER Material - Total - Total PAVEMENT EDGE TREATMENT Material - Total - Total ROCK DITCH	Material		1 1	Jul 1, 2020 Jul 11, 2020 Jul 1, 2020 Jul 1,	SYSTEM SYSTEM SYSTEM	\$6,563.20) \$6,563.20 \$0.00 \$0.00 \$0.00 \$3,022.90) \$3,022.90 \$0.00 \$0.00	Adjustment (0004) due to user mckinm1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user mckinm1 overridding Payment Estimate Exception 3 on the
0110 - 0110 - 0190	TYPE A2 SHOULDER Material - Total - Total PAVEMENT EDGE TREATMENT Material - Total - Total ROCK DITCH	Material		1 1 1	Jul 1, 2020 Jul 11, 2020 Jul 1, 2020	SYSTEM SYSTEM SYSTEM SYSTEM	\$6,563.20) \$6,563.20 \$0.00 \$0.00 \$0.00 (\$3,022.90) \$3,022.90 \$0.00 \$0.00 \$0.00	Adjustment (0004) due to user mckinm1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user mckinm1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user mckinm1 overridding Payment Estimate Exception 4 on the
0110 - 0110 - 0190	TYPE A2 SHOULDER Material - Total - Total PAVEMENT EDGE TREATMENT Material - Total - Total ROCK DITCH	Material		1 1 1 1	Jul 1, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$6,563.20 \$6,563.20 \$0.00 \$0.00 \$0.00 \$3,022.90 \$0.00 \$0.00 \$0.00 \$900.00	Adjustment (0004) due to user mckinm1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user mckinm1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user mckinm1 overridding Payment Estimate Exception 4 on the
0110 - 0110 - 0190	TYPE A2 SHOULDER Material - Total - Total PAVEMENT EDGE TREATMENT Material - Total - Total ROCK DITCH	Material		1 1 1 2	Jul 1, 2020 Jul 16, 2020 Jul 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$6,563.20 \$6,563.20 \$0.00 \$0.00 \$0.00 \$3,022.90 \$0.00 \$0.00 \$0.00 \$900.00 \$900.00	Adjustment (0004) due to user mckinm1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user mckinm1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user mckinm1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user mckinm1 overridding Payment Estimate Exception 8 on the
0110 - 0110 - 0190	TYPE A2 SHOULDER Material - Total - Total PAVEMENT EDGE TREATMENT Material - Total - Total ROCK DITCH	Material	- Total	1 1 1 2	Jul 1, 2020 Jul 16, 2020 Jul 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$6,563.20 \$6,563.20 \$0.00 \$0.00 \$0.00 \$3,022.90 \$0.00 \$0.00 \$0.00 \$900.00 \$900.00	Adjustment (0004) due to user mckinm1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user mckinm1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user mckinm1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user mckinm1 overridding Payment Estimate Exception 8 on the

Revision 4/1/2020 Page 8 of 9



Missouri Department of Transportation Contractor's Pay Estimate Summary Line Item Adjustments - All Estimates

Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
			Type			01/0==1/		
0390	ALTERNATE DITCH CHECK	Material		1	Jul 1, 2020	SYSTEM	(\$640.00)	
				1	Jul 1, 2020	SYSTEM	\$640.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user mckinm1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				2	Jul 16, 2020	SYSTEM	(\$896.00)	
				2	Jul 16, 2020	SYSTEM	\$896.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user mckinm1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
	- Total						\$0.00	
	Material - Total						\$0.00	
0390 -	Total						\$0.00	
0420	SILT FENCE	Material		1	Jul 1, 2020	SYSTEM	(\$2,945.50)	
				1	Jul 1, 2020	SYSTEM	\$2,945.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user mckinm1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				2	Jul 16, 2020	SYSTEM	(\$2,945.50)	
				2	Jul 16, 2020	SYSTEM	\$2,945.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user mckinm1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
	- Total						\$0.00	
	Material - Total						\$0.00	
0420 -	Total						\$0.00	
0530	PULL BOX, CONCRETE, DOUBLE TYPE B	Material		2	Jul 16, 2020	SYSTEM	(\$2,800.00)	
			2	2	Jul 16, 2020	SYSTEM	\$2,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user mckinm1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
	- Total						\$0.00	
	Material - Total						\$0.00	
0530 - Total							\$0.00	
Overall - Total							\$0.00	

Revision 4/1/2020 Page 9 of 9