

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: January 19, 2021

ount\$30,171.88	nuary 2, 2021 Original Contract Amo nuary 15, 2021Net Change Order Amo Current Contract Amo		Contract ID 200320-H04 Prime Contractor Capital Paving & Cor	ate Number	Progress Estima 10			
By User					Approval Date			
turnep3	ed Draft) at the Project Office Level by	Approved (and should be considere	Generated and		January 20, 2021			
wilkem1	aft) at the Resident Engineer Level by	oved (and should be considered Dra	Reviewed and Appr		January 20, 2021			
greggd1	ntral Office Controllers Office Level by	Reviewed and Approved at the Cer			January 20, 2021			
ınt Complete	Original Completion Date Current Completion Date Actual Completion Date % of Current Contract Amount							
	05 33%		November 25, 2020	1 2020	November			

No Milestones Exist for Contract

Contract Total Pa	y For Estimate No. 10			
		This Estimate	Previous	To Date
200320-H04				
	Total Posted Items Pay	\$520.00	\$4,697,718.52	\$4,698,238.52
	Gross Item Adjustments	\$1,000.00	(\$204,306.67)	(\$203,306.67)
	Incentive	\$0.00	\$89,983.32	\$89,983.32
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	·		\$4,583,395.17	\$4,584,915.17
Contract Total Pa	yable This Estimate:	\$1,520.00		

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount			
J9P3520	0120	6161005	CONSTRUCTION SIGNS	SQFT	\$5.000	96	\$480.00			
	0130	6161009	FLAG ASSEMBLY	EA	\$20.000	2	\$40.00			
Project J9P3520 -	Project J9P3520 - Total									
Overall - Total	\$520.00									

Contract Adjustments This Estimate

		stments Exist on Contract ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9P3520	0050	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Material			-26,478.8	\$56.48	(\$1,495,522.62)
	0050	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user turnep3 overridding Payment Estimate Exception 1 on the current Payment Estimate.	26,478.8	\$56.48	\$1,495,522.62
	0060	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Material			-36,605.1	\$64.69	(\$2,367,983.92)
	0060	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.	36,605.1	\$64.69	\$2,367,983.92
	0090	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	Other Item Adjustment	Other	This adjustment ensures full payment for Line 0090: TMAs, and zeroes any previous adjustments.			\$1,000.00
Total								\$1,000.00

Page 1 of 15 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Information							
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work								
J9P3520	FAF 412-1(17)	Resurface	412	DUNKLIN	from end of divided highv	vay to Route VV							
Totals by	Job Numbe	rs											
		-											
					This Estimate	Previous	To Date						
J9P3520	Posted	d Item Pay Item Adjustme	ents		This Estimate \$520.00 \$1,000.00	Previous \$4,697,718.52 (\$204,306.67)	To Date \$4,698,238.52 (\$203,306.67)						
	Posted	d Item Pay		Item Pay	\$520.00	\$4,697,718.52	\$4,698,238.52						
•	Posted	d Item Pay Item Adjustmo		Item Pay	\$520.00 \$1,000.00	\$4,697,718.52 (\$204,306.67)	\$4,698,238.52 (\$203,306.67)						
	Posted Gross	d Item Pay Item Adjustme		Item Pay	\$520.00 \$1,000.00 \$1,520.00	\$4,697,718.52 (\$204,306.67) \$4,493,411.85	\$4,698,238.52 (\$203,306.67) \$4,494,931.85						
•	Posted Gross Incent Disinc Liquid	d Item Pay Item Adjustme	Gross	Item Pay	\$520.00 \$1,000.00 \$1,520.00 \$0.00	\$4,697,718.52 (\$204,306.67) \$4,493,411.85 \$89,983.32	\$4,698,238.52 (\$203,306.67) \$4,494,931.85 \$89,983.32						

Revision 4/1/2020 Page 2 of 15



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J9P3520, Item 4011209, Project Item Line Number 0050, Material Set 401120996, Material 0401BPPMBP1 - Plant Mix for Bit Pavement BP-1, Acceptance Action Generic AspLow is insufficient.	Awaiting QA Results to be entered.	turnep3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3520, Item 4030103, Project Item Line Number 0060, Material Set 403010396, Material 0403SP125CLG - Superpave 12.5 mm, Des C 80 Gyros, Acceptance Action Generic AspHigh is insufficient.	Awaiting QA Results to be entered.	turnep3	Overridden

Revision 4/1/2020 Page 3 of 15



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
00320-H04	J9P3520	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$16,064.79	\$16,064.79
		0001	0020	2159903	MISC.MODIFIED SHAPING SLOPES, CLASS III	4,918.00	0.00	4,918.00	LF	3,942.50	\$14.00	\$55,195.00
		0001	0030	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	4,090.90	0.00	4,090.90	TONS	3,091.60	\$38.68	\$119,583.09
		0001	0040	3105002	GRAVEL (A) OR CRUSHED STONE (B)	134.00	0.00	134.00	TONS	134.00	\$27.53	\$3,689.02
		0001	0050	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	26,084.80	394.00	26,478.80	TONS	26,478.80	\$56.48	\$1,495,522.62
		0001	0060	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	37,345.50	0.00	37,345.50	TONS	36,605.10	\$64.69	\$2,367,983.92
		0001	0070	4071005	TACK COAT	50,915.00	191.00	51,106.00	GAL	51,106.00	\$2.00	\$102,212.00
		0001	0080	4134000	BITUMINOUS FOG SEAL	18,233.00	0.00	18,233.00	GAL	6,642.00	\$2.34	\$15,542.28
		0001	0090	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	2.00	4.00	EA	4.00	\$500.00	\$2,000.00
		0001	0100	6133020	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	307.20	26.10	333.30	TONS	333.30	\$172.35	\$57,444.26
		0001	0110	6133021	REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	1,806.10	105.50	1,911.60	SQYD	1,911.60	\$13.35	\$25,519.86
		0001	0120	6161005	CONSTRUCTION SIGNS	3,547.00	0.00	3,547.00	SQFT	2,279.00	\$5.00	\$11,395.00
		0001	0130	6161009	FLAG ASSEMBLY	6.00	0.00	6.00	EA	6.00	\$20.00	\$120.00
		0001	0140	6161025	CHANNELIZER (TRIM LINE)	110.00	0.00	110.00	EA	110.00	\$20.00	\$2,200.00
		0001	0150	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$2,800.00	\$5,600.00
		0001	0160	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$118,630.47	\$118,630.47
		0001	0170	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	429.00	0.00	429.00	LF	414.00	\$20.00	\$8,280.00
		0001	0180	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	425.00	0.00	425.00	LF	390.00	\$20.00	\$7,800.00
		0001	0190	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	11.00	2.00	13.00	EA	13.00	\$280.00	\$3,640.00
		0001	0200	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	63,365.00	0.00	63,365.00	LF	0.00	\$0.15	\$0.00
		0001	0210	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	229,952.00	0.00	229,952.00	LF	0.00	\$0.20	\$0.00
		0001	0220	6209901	MISC.TEMPORARY PAVEMENT MARKING PAINT	1.00	0.00	1.00	LS	0.00	\$0.00	\$0.00
		0001	0230	6209902	MISC.PREFORMED THERMOPLASTIC PAVEMENT MARKING, LANE REDUCTION ARROW	2.00	0.00	2.00	EA	2.00	\$2,000.00	\$4,000.00
		0001	0240	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	27,934.00	0.00	27,934.00	SQYD	26,692.00	\$1.23	\$32,831.16
		0001	0250	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	9,730.00	0.00	9,730.00	SQYD	8,146.00	\$5.36	\$43,662.56
		0001	0260	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	1,914.00	0.00	1,914.00	STA	1,914.00	\$15.50	\$29,667.00
		0001	0270	6261001	BITUMINOUS CENTERLINE RUMBLE STRIP	941.00	0.00	941.00	STA	941.00	\$15.50	\$14,585.50
		0010	0280	6061060	MGS GUARDRAIL	2,088.00	0.00	2,088.00	LF	1,550.00	\$24.00	\$37,200.00
		0010	0290	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	RIDGE APPROACH TRANSITION SECTION 20.00 0.00 20.00 EA 19.00 \$3,050.0 AR/NO CURB)					\$3,050.00	\$57,950.00
		0010	0300	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	26.00	0.00	26.00	EA	21.00	\$2,850.00	\$59,850.00
		0001	5001	6161008	ADVANCED WARNING RAIL SYSTEM	0.00	2.00	2.00	EA	2.00	\$35.00	\$70.00
	Project J	9P3520 - To	otal Value	Posted to D	Date as of Report Generated Date							\$4,698,238.53
320-H04 Ove	rall - Total	Value Pos	ted to Da	te as of Repo	ort Generated Date							\$4,698,238.53

Revision 4/1/2020 Page 4 of 15



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J9P3520

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0120	6161005	CONSTRUCTION SIGNS	1/15/21	1/19/21	96.00		2 Sign Packages: 2 Road Work Ahead = 2 x 16 sqft 2 Flagger = 2 x 16 sqft 2 One Lane Road Ahead = 2 x 16 sqft	0.835	RLC	22.055	RLC	
0130	6161009	FLAG ASSEMBLY	1/15/21	1/19/21	2.00	EA	Various Locations	0.835	RLC	22.055	RLC	

The information below this line are details for Construction Signs (if applicable).

Project Line Number DWR Date Total Quantity Posted For DWR Date Sign Information Station Log Mile Location Number of Items SF Each Sign Special Sign SF Each Special Sign Total SF to Post GO20-2 48x24 8.00 END ROAD WORK 28' L of C/L J9P3520 0120 October 23, 2020 816 .833 CONST-7-72 72x36 18.00 RATE OUR WORK ZONE .856 28' R of C/L 18 10 GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES 28' R of C/L CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE 28' R of C/L 12 1.033 WO8-12 48x48 16.00 NO CENTER LINE 16 1.118 28' R of C/L WO8-11 48x48 16.00 UNEVEN LANES 1.284 28' R of C/L 16 WO8-11 48x48 16.00 UNEVEN LANES 1.82 28' L of C/L 16 WO8-11 48x48 16.00 UNEVEN LANES 28' L of C/L 16 10.581 WO8-12 48x48 16.00 NO CENTER LINE 10.731 28' R of C/L 16 WO8-11 48x48 16.00 UNEVEN LANES 10.774 28' R of C/L 16 48x48 16.00 UNEVEN 16 WO8-11 LANES 11.513 28' L of C/L WO8-12 48x48 16.00 NO CENTER LINE 11.614 28' L of C/L 16 WO8-12 48x48 16.00 NO CENTER LINE 16 11.731 28' R of C/L WO8-11 48x48 16.00 UNEVEN LANES 11.791 28' R of C/L 16 16 WO8-11 LANES 48x48 16.00 UNEVEN 12.649 28' L of C/L WO8-11 48x48 16.00 UNEVEN LANES 28' R of C/L 16 12.798 28' L of C/L 16 WO8-11 LANES 48x48 16.00 UNEVEN 13.654 WO8-12 48x48 16.00 NO CENTER LINE 13.694 28' L of C/L 16 16 WO8-11 LANES 48x48 16.00 UNEVEN 19.431 28' R of C/L 16 WO8-11 LANES 48x48 16.00 UNEVEN 2.252 28' R of C/L WO8-11 LANES 48x48 16.00 UNEVEN 2.753 28' L of C/L 16 16 WO8-12 48x48 16.00 NO CENTER LINE 2.816 28' L of C/L WO8-11 LANES 48x48 16.00 UNEVEN 20.217 28' L of C/L 16 WO8-12 48x48 16.00 NO CENTER LINE 28' L of C/I 16 20.262 WO8-12 48x48 16.00 NO CENTER LINE 20.453 28' R of C/I 16 WO8-11 48x48 16.00 UNEVEN LANES 20.677 28' L of C/L 16 WO8-12 48x48 16.00 NO CENTER LINE 20 751 28' L of C/L 16 WO8-12 48x48 16.00 NO CENTER LINE 16 21.846 28' L of C/L CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE 21.929 28' L of C'L 12 GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES 10 21.971 28' L of C/L CONST-7-72 72x36 18.00 RATE OUR WORK ZONE 22.052 28' L of C/L 18 GO20-2 48x24 8.00 END ROAD WORK 22 052 28' R of C/L WO8-12 48x48 16.00 NO CENTER LINE 3.00 28' R of C/L 16 WO8-11 48x48 16.00 UNEVEN LANES 3.047 28' R of C/L 16 16 WO8-11 48x48 16.00 UNEVEN LANES 3.317 28' L of C/L WO8-12 48x48 16.00 NO CENTER LINE 4.355 28' L of C/L 16 WO8-12 48x48 16.00 NO CENTER LINE 4 477 28' R of C/L 16 WO8-11 48x48 16.00 UNEVEN LANES 4 522 28' R of C/L 16 WO8-11 48x48 16.00 UNEVEN LANES 5.138 28' L of C/L 16 WO8-12 48x48 16.00 NO CENTER LINE 5.178 28' L of C/L 16 WO8-11 48x48 16.00 UNEVEN LANES 5.474 28' R of C/L 16 WO8-11 48x48 16.00 UNEVEN LANES 5 938 28' L of C/L 16

Revision 4/1/2020 Page 5 of 15

6.421

6 465

28' R of C/L

28' R of C/L

16

16

WO8-12 48x48 16.00 NO CENTER LINE

WO8-11 48x48 16.00 UNEVEN



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

roject	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Po				
P3520	0120	October 23, 2020	816	LANES												
				WO8-11 48x48 16.00 UNEVEN LANES		6.868	28' L of C/L		16							
				WO8-12 48x48 16.00 NO CENTE LINE	R	6.986	28' L of C/L		16							
				WO8-12 48x48 16.00 NO CENTE LINE	R	7.591	28' L of C/L		16							
				WO8-11 48x48 16.00 UNEVEN LANES		8.124	28' R of C/L		16							
				WO8-11 48x48 16.00 UNEVEN LANES		8.535	28' L of C/L		16							
						WO8-12 48x48 16.00 NO CENTE LINE	R	8.792	28' R of C/L		16					
				WO8-11 48x48 16.00 UNEVEN LANES		8.838	28' R of C/L		16							
				WO8-12 48x48 16.00 NO CENTE LINE	R	9.598	28' L of C/L		16							
				WO8-11 48x48 16.00 UNEVEN LANES		9.783	28' R of C/L		16							
		November 11, 2020	20 128	WO8-11 48x48 16.00 UNEVEN LANES		16.041	25' L of C/L		16							
				WO8-12 48x48 16.00 NO CENTE LINE	R	16.152	25' L of C/L		16							
					WO8-11 48x48 16.00 UNEVEN LANES		16.335	25' R of C/L		16						
				WO8-11 48x48 16.00 UNEVEN LANES		18.173	25' L of C/L		16							
				WO8-12 48x48 16.00 NO CENTE LINE	R	18.263	25' L of C/L		16							
				WO8-12 48x48 16.00 NO CENTE LINE	R	18.399	25' R of C/L		16							
				WO8-11 48x48 16.00 UNEVEN LANES		18.442	25' R of C/L		16							
					WO8-11 48x48 16.00 UNEVEN LANES		19.286	25' L of C/L		16						
		November 12, 2020	U W U	WO8-12 48x48 16.00 NO CENTE LINE		14.037	28' R of C/L		16							
				L V L V				WO8-12 48x48 16.00 NO CENTE LINE		15.064	28' L of C/L		16			
										WO8-12 48x48 16.00 NO CENTE LINE		16.292	28' R of C/L		16	
					WO8-12 48x48 16.00 NO CENTE LINE		20.829	28' R of C/L		16						
				WO8-12 48x48 16.00 NO CENTE LINE	R	7.117	28' R of C/L		16							

Revision 4/1/2020 Page 6 of 15



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0020	MISC. MODIFIED SHAPING SLOPES, CLASS III	Material	,	6	Nov 16, 2020	SYSTEM	(\$10,080.00)	
				6	Nov 16, 2020	SYSTEM	\$10,080.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				7	Dec 3, 2020	SYSTEM	(\$54,635.00)	
				7	Dec 3, 2020	SYSTEM	\$54,635.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0020 -	Total						\$0.00	
0030	MISC. PERMANENT AGGREGATE EDGE TREATMENT	Material		7	Dec 3, 2020	SYSTEM	(\$119,582.31)	
				7	Dec 3, 2020	SYSTEM	\$119,582.31	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				8	Dec 16, 2020	SYSTEM	(\$119,583.09)	
				8	Dec 16, 2020	SYSTEM	\$119,583.09	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user turnep3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				9	Jan 4, 2021	SYSTEM	(\$119,583.09)	
				9	Jan 4, 2021	SYSTEM	\$119,583.09	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user turnep3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total							
							\$0.00	
0030 -	· Total						\$0.00 \$0.00	
0030 - 0040	Total GRAVEL (A) OR CRUSHED STONE (B)	Material		7	Dec 3, 2020	SYSTEM		
		Material		7		SYSTEM SYSTEM	\$0.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate.
		Material			2020 Dec 3,		\$0.00 (\$3,689.02)	Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 5 on the current
		Material		7	2020 Dec 3, 2020	SYSTEM	\$0.00 (\$3,689.02) \$3,689.02	Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 5 on the current
		Material		7	Dec 3, 2020 Dec 16, 2020 Dec 16, 2020	SYSTEM	\$0.00 (\$3,689.02) \$3,689.02 (\$3,689.02)	Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 2 on the current
		Material		7 8 8	Dec 3, 2020 Dec 16, 2020 Dec 16, 2020 Jan 4,	SYSTEM SYSTEM SYSTEM	\$0.00 (\$3,689.02) \$3,689.02 (\$3,689.02)	Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 2 on the current
		Material	- Total	7 8 8 9	2020 Dec 3, 2020 Dec 16, 2020 Dec 16, 2020 Jan 4, 2021 Jan 4,	SYSTEM SYSTEM SYSTEM	\$0.00 (\$3,689.02) \$3,689.02 (\$3,689.02) (\$3,689.02)	Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 2 on the current
0040	GRAVEL (A) OR CRUSHED STONE (B) Material - Total	Material	- Total	7 8 8 9	2020 Dec 3, 2020 Dec 16, 2020 Dec 16, 2020 Jan 4, 2021 Jan 4,	SYSTEM SYSTEM SYSTEM	\$0.00 (\$3,689.02) \$3,689.02 (\$3,689.02) \$3,689.02 (\$3,689.02)	Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 2 on the current
	GRAVEL (A) OR CRUSHED STONE (B) Material - Total	Material	- Total	7 8 8 9	2020 Dec 3, 2020 Dec 16, 2020 Dec 16, 2020 Jan 4, 2021 Jan 4,	SYSTEM SYSTEM SYSTEM	\$0.00 (\$3,689.02) \$3,689.02 (\$3,689.02) \$3,689.02 (\$3,689.02)	Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 2 on the current
0040	GRAVEL (A) OR CRUSHED STONE (B) Material - Total	Material	- Total	7 8 8 9	2020 Dec 3, 2020 Dec 16, 2020 Dec 16, 2020 Jan 4, 2021 Jan 4,	SYSTEM SYSTEM SYSTEM	\$0.00 (\$3,689.02) \$3,689.02 (\$3,689.02) \$3,689.02 (\$3,689.02) \$0.00	Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 2 on the current
0040	Material - Total BITUMINOUS PAVEMENT MIXTURE		- Total	7 8 8 9 9	2020 Dec 3, 2020 Dec 16, 2020 Dec 16, 2020 Jan 4, 2021 Jan 4, 2021 Oct 1,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$3,689.02) \$3,689.02 (\$3,689.02) \$3,689.02 (\$3,689.02) \$0.00 \$0.00	Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 2 on the current
0040	Material - Total BITUMINOUS PAVEMENT MIXTURE		- Total	7 8 8 9 9	2020 Dec 3, 2020 Dec 16, 2020 Dec 16, 2020 Jan 4, 2021 Jan 4, 2021 Oct 1, 2020 Oct 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$3,689.02) \$3,689.02 (\$3,689.02) \$3,689.02 (\$3,689.02) \$0.00 \$0.00 (\$734,432.03)	Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.

Revision 4/1/2020 Page 7 of 15



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0050	BITUMINOUS PAVEMENT MIXTURE	Material						Payment Estimate.
	PG64-22, (BP-1)			5	Nov 2, 2020	SYSTEM	(\$734,432.03)	
				5	Nov 2, 2020	SYSTEM	\$734,432.03	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				6	Nov 16, 2020	SYSTEM	(\$1,495,517.54)	
				6	Nov 16, 2020	SYSTEM	\$1,495,517.54	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				7	Dec 3, 2020	SYSTEM	(\$1,495,517.54)	
				7	Dec 3, 2020	SYSTEM	\$1,495,517.54	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				8	Dec 16, 2020	SYSTEM	(\$1,495,522.62)	
				8	Dec 16, 2020	SYSTEM	\$1,495,522.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				9	Jan 4, 2021	SYSTEM	(\$1,495,522.62)	
				9	Jan 4, 2021	SYSTEM	\$1,495,522.62	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				10	Jan 19, 2021	SYSTEM	(\$1,495,522.62)	
				10	Jan 19, 2021	SYSTEM	\$1,495,522.62	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user turnep3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Other Item Adjustment	ACAD	2	Sep 16, 2020	turnep3	(\$9,731.85)	AC Index Price Adjustment: -\$9,731.85
				3	Oct 1, 2020	turnep3	(\$20,988.69)	AC Index Price Adjustment: -\$20,988.69
				6	Nov 16, 2020	turnep3	(\$34,193.60)	Asphalt Index Price Adjustment: -\$34,193.60
			ACAD - Tota	al			(\$64,914.14)	
	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)		FUEL	8	Dec 16, 2020	turnep3	\$0.02	Correction of Fuel Price adjustment due to rounding BP-1 totals.
			FUEL - Tota	ıl			\$0.02	
	Other Item Adjustment - Total						(\$64,914.12)	
	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Overrun	Overrun	6	Nov 16, 2020	SYSTEM	(\$21,855.70)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				6	Nov 16, 2020	SYSTEM	\$21,855.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) overridding Payment Estimate Exception 6 on the current Payment Estimate.
				7	Dec 3, 2020	SYSTEM	(\$21,881.39)	Averaged Price Adjustment from this item on all previous payment estimates of '-0.93078' is applied (if non-zero).
				7	Dec 3, 2020	SYSTEM	\$21,881.39	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 11 on the current Payment Estimate.
				8	Dec 16, 2020	SYSTEM	(\$21,881.39)	Averaged Price Adjustment from this item on all previous payment estimates of '-0.93078' is applied (if non-zero).
				8	Dec 16, 2020	SYSTEM	(\$5.07)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				8	Dec 16, 2020	SYSTEM	\$5.07	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 10 on the current Payment Estimate.

Revision 4/1/2020 Page 8 of 15



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
		Туре	Adjustment Type		Date	Ву		
0050	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Overrun	Overrun	8	Dec 16, 2020	SYSTEM	\$21,881.39	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 10 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Price		2	Sep 16, 2020	SYSTEM	(\$3,555.78)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				3	Oct 1, 2020	SYSTEM	(\$7,668.76)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				6	Nov 16, 2020	SYSTEM	(\$13,421.40)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				8	Dec 16, 2020	SYSTEM	(\$0.02)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			- Total				(\$24,645.96)	
	Price - Total						(\$24,645.96)	
0050 -	- Total						(\$89,560.08)	
0060	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Material		4	Oct 16, 2020	SYSTEM	(\$831,265.85)	
				4	Oct 16, 2020	SYSTEM	\$831,265.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				5	Nov 2, 2020	SYSTEM	(\$2,367,981.98)	
				5	Nov 2, 2020	SYSTEM	\$2,367,981.98	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				6	Nov 16, 2020	SYSTEM	(\$2,367,981.98)	
				6	Nov 16, 2020	SYSTEM	\$2,367,981.98	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user turnep3 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				7	Dec 3, 2020	SYSTEM	(\$2,367,981.98)	
				7	Dec 3, 2020	SYSTEM	\$2,367,981.98	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user turnep3 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				8	Dec 16, 2020	SYSTEM	(\$2,367,983.92)	
				8	Dec 16, 2020	SYSTEM	\$2,367,983.92	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user turnep3 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				9	Jan 4, 2021	SYSTEM	(\$2,367,983.92)	
				9	Jan 4, 2021	SYSTEM	\$2,367,983.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				10	Jan 19, 2021	SYSTEM	(\$2,367,983.92)	
				10	Jan 19, 2021	SYSTEM	\$2,367,983.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Other Item Adjustment	ACAD	4	Oct 16, 2020	turnep3	(\$28,623.35)	AC Index Price Adjustment: -\$28623.35 Calculated by hand using appropriate indexes. AC Index
				_	N	, -	(055.51)	spreadsheet did not include index for October 2020, but value was given in index list on MoDOT website.
				5	Nov 2, 2020	turnep3	(\$52,914.44)	AC Index Price Adjustment: -\$52914.44
			ACAD - Tot	al			(\$81,537.79)	

Revision 4/1/2020 Page 9 of 15



			2.1					
Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0060	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Other Item Adjustment	FUEL	5	Nov 2, 2020	turnep3	(\$25,237.40)	Fuel Price Adjustment: -\$25237.40
				6	Nov 16, 2020	turnep3	\$25,237.40	Correction for double adjustment of Fuel Price Adjustment on Estimate 0005: \$25,237.40
				8	Dec 16, 2020	turnep3	\$0.01	Correction of Fuel Price adjustment due to rounding SP125 totals.
			FUEL - Tota	ıl			\$0.01	
	Other Item Adjustment - Total						(\$81,537.78)	
	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Price		4	Oct 16, 2020	SYSTEM	(\$13,651.84)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				5	Nov 2, 2020	SYSTEM	(\$25,237.40)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				8	Dec 16, 2020	SYSTEM	(\$0.01)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			- Total				(\$38,889.25)	
	Price - Total						(\$38,889.25)	
0060 -	· Total						(\$120,427.03)	
0070	TACK COAT	Material		1	Sep 2, 2020	SYSTEM	(\$78.00)	
				1	Sep 2, 2020	SYSTEM	\$78.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user turnep3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				2	Sep 16, 2020	SYSTEM	(\$9,036.00)	
				2	Sep 16, 2020	SYSTEM	\$9,036.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				3	Oct 1, 2020	SYSTEM	(\$22,768.00)	
				3	Oct 1, 2020	SYSTEM	\$22,768.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	TACK COAT	Overrun	Overrun	6	Nov 16, 2020	SYSTEM	(\$382.00)	
				6	Nov 16, 2020	SYSTEM	\$382.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user turnep3 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				7	Dec 3, 2020	SYSTEM	(\$382.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				7	Dec 3, 2020	SYSTEM	\$382.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user turnep3 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				8	Dec 16, 2020	SYSTEM	(\$382.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				8	Dec 16, 2020	SYSTEM	\$382.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Exception 11 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0070 -	· Total						\$0.00	
0080	BITUMINOUS FOG SEAL	Material		7	Dec 3, 2020	SYSTEM	(\$15,542.28)	
				7	Dec 3, 2020	SYSTEM	\$15,542.28	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Exception 8 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	

Revision 4/1/2020 Page 10 of 15



	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
0080 - T	Гotal						\$0.00			
0090	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	Other Item Adjustment	OADJ	8	Dec 16, 2020	turnep3	(\$1,000.00)	Removal of previous line item adjustment for overrun of 2 TMAs. Change Order has been submitted and is awaiting approval.		
				9	Jan 4, 2021	turnep3	(\$1,000.00)	Removing the \$1000 automatic overrun adjustment. Change Order 0003 has been submitted and approved which included overrun adjustment for 2 additional TMAs.		
			OADJ - Tota	al			(\$2,000.00)			
	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)		OTHR	10	Jan 19, 2021	turnep3	\$1,000.00	This adjustment ensures full payment for Line 0090: TMAs, and zeroes any previous adjustments.		
			OTHR - Tota	al			\$1,000.00			
C	Other Item Adjustment - Total						(\$1,000.00)			
	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	Overrun	Overrun	7	Dec 3, 2020	SYSTEM	(\$1,000.00)			
				7	Dec 3, 2020	turnep3	\$1,000.00	Due to additional TMAs required for Striping and Rumble Strips operations, \$1000 was adjusted for the 2 additional TMAs (\$500 per EA) until a Change Order correcting the quantity is submitted.		
				9	Jan 4, 2021	SYSTEM	\$1,000.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',500.00000 - 500.00000, 'is applied (if non-zero).		
			Overrun - T	otal			\$1,000.00			
C	Overrun - Total						\$1,000.00			
0090 - T	Гotal						\$0.00			
0100	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR			1	Sep 2, 2020	SYSTEM	(\$6,206.32)			
				1	Sep 2, 2020	SYSTEM	\$6,206.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.		
				2	Sep 16, 2020	SYSTEM	(\$6,206.32)			
				2	Sep 16, 2020	SYSTEM	\$6,206.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.		
				3	Oct 1, 2020	SYSTEM	(\$6,206.32)			
				3	Oct 1, 2020	SYSTEM	\$6,206.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.		
				4	Oct 16, 2020	SYSTEM	(\$57,433.91)			
				4	Oct 16, 2020	SYSTEM	\$57,433.91	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.		
				5	Nov 2, 2020	SYSTEM	(\$57,433.91)			
							5	Nov 2, 2020	SYSTEM	\$57,433.91
				6	Nov 16, 2020	SYSTEM	(\$57,433.91)			
				6	Nov 16, 2020	SYSTEM	\$57,433.91	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate.		
				7	Dec 3, 2020	SYSTEM	(\$57,433.91)			
				7	Dec 3, 2020	SYSTEM	\$57,433.91	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user turnep3 overridding Payment Estimate Exception 9 on the current Payment Estimate.		
			- Total				\$0.00			

Revision 4/1/2020 Page 11 of 15



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
Line	Description	Туре	Adjustment Type		Date	By	Amount	INCHIGINS
0100	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C	Other Item Adjustment	ACAD	1	Sep 2, 2020	turnep3	(\$80.21)	AC Price Index Adjustment: -\$80.21
	PARTIAL DEPTH PAVEMENT REPAIR			4	Oct 16,	turnep3	(\$662.28)	AC Index Price Adjustment: -\$662.28
					2020			Calculated according to index appropriate for when the work was performed (9/9/2020).
			ACAD - Total	al			(\$742.49)	
	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C		FUEL	1	Sep 2, 2020	turnep3	(\$34.67)	Asphalt Paving Production and Hauling Fuel Adjustment: - \$34.67
	PARTIAL DEPTH PAVEMENT REPAIR			4	Oct 16,	turnep3	(\$256.65)	Fuel Price Adjustment: -\$256.65
					2020			Calculated according to index appropriate for when the work was performed (9/9/2020).
			FUEL - Tota	ıl			(\$291.32)	
	Other Item Adjustment - Total						(\$1,033.81)	
	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C	Overrun	Overrun	4	Oct 16, 2020	SYSTEM	(\$4,487.99)	
	PARTIAL DEPTH PAVEMENT REPAIR			4	Oct 16, 2020	SYSTEM	\$4,487.99	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) overridding Payment Estimate Exception 4 on the current Payment Estimate.
				5	Nov 2, 2020	SYSTEM	(\$4,487.99)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				5	Nov 2, 2020	SYSTEM	\$4,487.99	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) overridding Payment Estimate Exception 5 on the current Payment Estimate.
				6	Nov 16, 2020	SYSTEM	(\$4,487.99)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				6	Nov 16, 2020	SYSTEM	\$4,487.99	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) overridding Payment Estimate Exception 8 on the current Payment Estimate.
				7	Dec 3, 2020	SYSTEM	(\$4,487.99)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				7	Dec 3, 2020	SYSTEM	\$4,487.99	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) overridding Payment Estimate Exception 14 on the current Payment Estimate.
				8	Dec 16, 2020	SYSTEM	(\$4,487.99)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				8	Dec 16, 2020	SYSTEM	(\$10.34)	
				8	Dec 16, 2020	SYSTEM	\$10.34	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user turnep3 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				8	Dec 16, 2020	SYSTEM	\$4,487.99	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user turnep3 overridding Payment Estimate Exception 13 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0100 -	Total						(\$1,033.81)	
0110	REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	Overrun	Overrun	2	Sep 16, 2020	SYSTEM	(\$1,408.43)	
				2	Sep 16, 2020	SYSTEM	\$1,408.43	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				3	Oct 1, 2020	SYSTEM	(\$1,408.43)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				3	Oct 1, 2020	SYSTEM	\$1,408.43	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user turnep3 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				4	Oct 16, 2020	SYSTEM	(\$1,408.43)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				4	Oct 16, 2020	SYSTEM	\$1,408.43	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate.

Revision 4/1/2020 Page 12 of 15



					_			_
Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0110	REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	Overrun	Overrun	5	Nov 2, 2020	SYSTEM	(\$1,408.43)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				5	Nov 2, 2020	SYSTEM	\$1,408.43	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user turnep3 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				6	Nov 16, 2020	SYSTEM	(\$1,408.43)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				6	Nov 16, 2020	SYSTEM	\$1,408.43	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user turnep3 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				7	Dec 3, 2020	SYSTEM	(\$1,408.43)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				7	Dec 3, 2020	SYSTEM	\$1,408.43	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user turnep3 overridding Payment Estimate Exception 15 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0110 -	Total						\$0.00	
0120	CONSTRUCTION SIGNS	Material		1	Sep 2, 2020	SYSTEM	(\$480.00)	
				1	Sep 2, 2020	SYSTEM	\$480.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0120 -	Total						\$0.00	
0150	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION	Material		1	Sep 2, 2020	SYSTEM	(\$5,600.00)	
	INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED			1	Sep 2, 2020	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0150 -	Total						\$0.00	
0170	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material		7	Dec 3, 2020	SYSTEM	(\$7,120.00)	
				7	Dec 3, 2020	SYSTEM	\$7,120.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user turnep3 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				8	Dec 16, 2020	SYSTEM	(\$8,280.00)	
				8	Dec 16, 2020	SYSTEM	\$8,280.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user turnep3 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				9	Jan 4, 2021	SYSTEM	(\$8,280.00)	
				9	Jan 4, 2021	SYSTEM	\$8,280.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user turnep3 overridding Payment Estimate Exception 7 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0170 -	Total						\$0.00	
0180	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	Material		8	Dec 16, 2020	SYSTEM	(\$7,800.00)	
				8	Dec 16, 2020	SYSTEM	\$7,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user turnep3 overridding Payment Estimate Exception 7 on the current Payment Estimate.

Revision 4/1/2020 Page 13 of 15



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0180	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	Material		9	Jan 4, 2021	SYSTEM	(\$7,800.00)	
				9	Jan 4, 2021	SYSTEM	\$7,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 8 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0180 -	Total						\$0.00	
0190	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material		8	Dec 16, 2020	SYSTEM	(\$3,640.00)	
				8	Dec 16, 2020	SYSTEM	\$3,640.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user turnep3 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				9	Jan 4, 2021	SYSTEM	(\$3,640.00)	
				9	Jan 4, 2021	SYSTEM	\$3,640.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user turnep3 overridding Payment Estimate Exception 9 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Overrun	Overrun	8	Dec 16, 2020	SYSTEM	(\$560.00)	
				8	Dec 16, 2020	SYSTEM	\$560.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) overridding Payment Estimate Exception 14 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0190 -	· Total						\$0.00	
0230	MISC. PREFORMED THERMOPLASTIC PAVEMENT MARKING, LANE REDUCTION ARROW	Material		8	Dec 16, 2020	SYSTEM	(\$4,000.00)	
				8	Dec 16, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user turnep3 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				9	Jan 4, 2021	SYSTEM	(\$4,000.00)	
				9	Jan 4, 2021	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user turnep3 overridding Payment Estimate Exception 10 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0230 -	Total						\$0.00	
0280	MGS GUARDRAIL	Construction Stockpile		2	Sep 16, 2020	SYSTEM	\$21,339.36	Payment Estimate Item Adjustment generated Stockpile Transaction
				6	Nov 16, 2020	SYSTEM	(\$3,690.56)	Payment Estimate Item Adjustment generated Stockpile Transaction
				7	Dec 3, 2020	SYSTEM	(\$13,910.55)	Payment Estimate Item Adjustment generated Stockpile Transaction
	- Total						\$3,738.25	
	Construction Stockpile - Total						\$3,738.25	
	·Total						\$3,738.25	
0290	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	Construction Stockpile		2	Sep 16, 2020	SYSTEM	\$29,200.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				6	Nov 16, 2020	SYSTEM	(\$3,244.44)	Payment Estimate Item Adjustment generated Stockpile Transaction
			T-4-1	7	Dec 3, 2020	SYSTEM	(\$25,955.56)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
0290 -	· Total						\$0.00	

Revision 4/1/2020 Page 14 of 15



	5		0.11		0	0 1 1		D
Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0300	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		2	Sep 16, 2020	SYSTEM	\$38,766.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				6	Nov 16, 2020	SYSTEM	(\$6,626.67)	Payment Estimate Item Adjustment generated Stockpile Transaction
				7	Dec 3, 2020	SYSTEM	(\$28,163.33)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$3,976.00	
	Construction Stockpile - Total						\$3,976.00	
0300 -	Total						\$3,976.00	
5001	ADVANCED WARNING RAIL SYSTEM	Material		8	Dec 16, 2020	SYSTEM	(\$70.00)	
				8	Dec 16, 2020	SYSTEM	\$70.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				9	Jan 4, 2021	SYSTEM	(\$70.00)	
				9	Jan 4, 2021	SYSTEM	\$70.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Exception 6 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total				\$0.00			
5001 -	Total				\$0.00			
Overa	II - Total				(\$203,306.67)			

Revision 4/1/2020 Page 15 of 15