

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: February 16, 2021

Progress Estimate Number	Contract ID 200320-H04	Pay Period StartFebruary 2, 2021 Original Contract Amount \$4,898,461.04
12	Prime ContractorCapital Paving & Constr	ruction, LLCPay Period End February 15, 2021Net Change Order Amount (\$56,376.25)
		Current Contract Amount \$4,842,084.79

Approval Date		By User
February 16, 2021	Generated and Approved (and should be considered Draft) at the Project Office Level by	turnep3
February 16, 2021	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	wilkem1
February 17, 2021	Reviewed and Approved at the Central Office Controllers Office Level by	greggd1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
November 1, 2020	November 25, 2020		97.82%

	Milestones		
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract
Acceptance Date			
Awarded Date	April 1, 2020	April 1, 2020	
Letting Date	March 20, 2020	March 20, 2020	
Notice to Proceed Date	June 1, 2020	June 1, 2020	
Open to Traffic Date			
Work Began Date			

Contract Total Pa	y For Estimate No. 12				
		This Estimate	Previous	To Date	
200320-H04					
	Total Posted Items Pay	\$0.00	\$4,736,380.64	\$4,736,380.64	
	Gross Item Adjustments	\$0.00	(\$203,306.67)	(\$203,306.67)	
	Incentive	\$19,407.00	\$161,352.28	\$180,759.28	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
			\$4,694,426.25	\$4,713,833.25	
Contract Total Pa	yable This Estimate:	\$19,407.00			

Items Paid This Estimate Period

No Data Available

Contract Adjustments This	<u>Estimate</u>				
Adj Type	Entered By	Comments	Time Units	Rate	Amount
SPADIncentive	turnep3	Performance Testing Bonus (0 - 10k Tons): 3% = \$19,407			\$19,407.00

Overall - Total \$19,407.00 These amounts are listed in the Incentive, Disincentive, Liquidated Damages or Other Contract Adjustments

<u>ine Item Adjustments This Estimate</u> Project Item Description Adjustment Other Item Comments Adjustment Line Item Adjustment Line Number Adjustment No. Туре Adjustment Quantity amount Unit Price Type J9P3520 0050 **BITUMINOUS PAVEMENT** Material -26,478.8 \$56.48 (\$1,495,522.62) MIXTURE PG64-22, (BP-1) BITUMINOUS PAVEMENT This adjustment offsets the original system-0050 Material 26,478.8 \$56.48 \$1,495,522.62 generated Material Payment Estimate Item MIXTURE PG64-22, (BP-1) Adjustment (0001) due to user turnep3 overridding Payment Estimate Exception 1 on the current Payment Estimate. 0060 ASPHALTIC CONCRETE -36,605.1 \$64.69 (\$2,367,983.92) Material **MIXTURE PG 70-22 (SP125C** MIX) ASPHALTIC CONCRETE This adjustment offsets the original system-36,605.1 0060 \$64.69 \$2,367,983.92 Material MIXTURE PG 70-22 (SP125C generated Material Payment Estimate Item MIX) Adjustment (0002) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate. **Total** \$0.00

Revision 4/1/2020 Page 1 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Information				
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work			
J9P3520 FAF Resurface 412 DUNKLIN					from end of divided highw	from end of divided highway to Route VV				
Γotals by .	Job Numbe	rs								
J9P3520					This Estimate	Previous	To Date			
J9P3520	Posted	d Item Pay			This Estimate \$0.00	Previous \$4,736,380.64	To Date \$4,736,380.64			
J9P3520		d Item Pay Item Adjustme	ents							
J9P3520				Item Pay	\$0.00	\$4,736,380.64	\$4,736,380.64			
J9P3520		Item Adjustme		Item Pay	\$0.00 \$0.00 \$0.00	\$4,736,380.64 (\$203,306.67) \$4,533,073.97	\$4,736,380.64 (\$203,306.67) \$4,533,073.97			
J9P3520	Gross	Item Adjustme		Item Pay	\$0.00 \$0.00	\$4,736,380.64 (\$203,306.67)	\$4,736,380.64 (\$203,306.67)			
J9P3520	Incent Disinc	Item Adjustme	Gross	Item Pay	\$0.00 \$0.00 \$0.00 \$19,407.00	\$4,736,380.64 (\$203,306.67) \$4,533,073.97 \$161,352.28	\$4,736,380.64 (\$203,306.67) \$4,533,073.97 \$180,759.28			

Revision 4/1/2020 Page 2 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J9P3520, Item 4011209, Project Item Line Number 0050, Material Set 401120996, Material 0401BPPMBP1 - Plant Mix for Bit Pavement BP-1, Acceptance Action Generic AspLow is insufficient.	Awaiting QA results to be entered.	turnep3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3520, Item 4030103, Project Item Line Number 0060, Material Set 403010396, Material 0403SP125CLG - Superpave 12.5 mm, Des C 80 Gyros, Acceptance Action Generic AspHigh is insufficient.	Awaiting QA results to be entered.	turnep3	Overridden

Revision 4/1/2020 Page 3 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
0320-H04	J9P3520	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$16,064.79	\$16,064.79
		0001	0020	2159903	MISC.MODIFIED SHAPING SLOPES, CLASS III	4,918.00	0.00	4,918.00	LF	3,942.50	\$14.00	\$55,195.00
		0001	0030	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	4,090.90	-395.60	3,695.30	TONS	3,695.30	\$38.68	\$142,934.20
		0001	0040	3105002	GRAVEL (A) OR CRUSHED STONE (B)	134.00	0.00	134.00	TONS	134.00	\$27.53	\$3,689.02
		0001	0050	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	26,084.80	394.00	26,478.80	TONS	26,478.80	\$56.48	\$1,495,522.62
		0001	0060	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	37,345.50	-740.40	36,605.10	TONS	36,605.10	\$64.69	\$2,367,983.92
		0001	0070	4071005	TACK COAT	50,915.00	191.00	51,106.00	GAL	51,106.00	\$2.00	\$102,212.00
		0001	0080	4134000	BITUMINOUS FOG SEAL	18,233.00	-10,937.00	7,296.00	GAL	7,296.00	\$2.34	\$17,072.64
		0001	0090	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	2.00	4.00	EA	4.00	\$500.00	\$2,000.00
		0001	0100	6133020	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	307.20	26.10	333.30	TONS	333.30	\$172.35	\$57,444.26
		0001	0110	6133021	REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	1,806.10	105.50	1,911.60	SQYD	1,911.60	\$13.35	\$25,519.86
		0001	0120	6161005	CONSTRUCTION SIGNS	3,547.00	0.00	3,547.00	SQFT	2,279.00	\$5.00	\$11,395.00
		0001	0130	6161009	FLAG ASSEMBLY	6.00	0.00	6.00	EA	6.00	\$20.00	\$120.00
		0001	0140	6161025	CHANNELIZER (TRIM LINE)	110.00	0.00	110.00	EA	110.00	\$20.00	\$2,200.00
		0001	0150	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$2,800.00	\$5,600.00
		0001	0160	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$118,630.47	\$118,630.47
		0001	0170	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	429.00	-15.00	414.00	LF	414.00	\$20.00	\$8,280.00
		0001	0180	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	425.00	-35.00	390.00	LF	390.00	\$20.00	\$7,800.00
		0001	0190	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	11.00	2.00	13.00	EA	13.00	\$280.00	\$3,640.00
		0001	0200	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	63,365.00	0.00	63,365.00	LF	0.00	\$0.15	\$0.00
		0001	0210	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	229,952.00	0.00	229,952.00	LF	0.00	\$0.20	\$0.00
		0001	0220	6209901	MISC.TEMPORARY PAVEMENT MARKING PAINT	1.00	0.00	1.00	LS	0.00	\$0.00	\$0.00
		0001	0230	6209902	MISC.PREFORMED THERMOPLASTIC PAVEMENT MARKING, LANE REDUCTION ARROW	2.00	0.00	2.00	EA	2.00	\$2,000.00	\$4,000.00
		0001	0240	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	27,934.00	-1,242.00	26,692.00	SQYD	26,692.00	\$1.23	\$32,831.16
		0001	0250	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	9,730.00	890.00	10,620.00	SQYD	10,620.00	\$5.36	\$56,923.20
		0001	0260	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	1,914.00	0.00	1,914.00	STA	1,914.00	\$15.50	\$29,667.00
		0001	0270	6261001	BITUMINOUS CENTERLINE RUMBLE STRIP	941.00	0.00	941.00	STA	941.00	\$15.50	\$14,585.50
		0010	0280	6061060	MGS GUARDRAIL	2,088.00	0.00	2,088.00	LF	1,550.00	\$24.00	\$37,200.00
		0010	0290	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	20.00	0.00	20.00	EA	19.00	\$3,050.00	\$57,950.00
		0010	0300	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	26.00	0.00	26.00	EA	21.00	\$2,850.00	\$59,850.00
		0001	5001	6161008	ADVANCED WARNING RAIL SYSTEM	0.00	2.00	2.00	EA	2.00	\$35.00	\$70.00
	Project J	P3520 - To	otal Value	Posted to D	Date as of Report Generated Date							\$4,736,380.64
0320-H04 Ove	rall - Total	Value Post	ted to Da	te as of Rep	ort Generated Date							\$4,736,380.64

Page 4 of 16 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

1	The information	below this	<u>line are</u>	details fo	r Construction	Signs	(if applicable).	

Project	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
9P3520	0120	October 23, 2020	816	GO20-2 48x24 8.00 END ROAD WORK		.833	28' L of C/L		8			
				CONST-7-72 72x36 18.00 RATE OUR WORK ZONE		.856	28' R of C/L		18			
				GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES		.97	28' R of C/L		10			
				CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE		1.033	28' R of C/L		12			
				WO8-12 48x48 16.00 NO CENTER LINE		1.118	28' R of C/L		16			
				WO8-11 48x48 16.00 UNEVEN LANES		1.284	28' R of C/L		16			
				WO8-11 48x48 16.00 UNEVEN LANES		1.82	28' L of C/L		16			
				WO8-11 48x48 16.00 UNEVEN LANES		10.581	28' L of C/L		16			
				WO8-12 48x48 16.00 NO CENTER LINE		10.731	28' R of C/L		16			
				WO8-11 48x48 16.00 UNEVEN LANES		10.774	28' R of C/L		16			
				WO8-11 48x48 16.00 UNEVEN LANES			28' L of C/L		16			
				WO8-12 48x48 16.00 NO CENTER LINE			28' L of C/L		16			
				WO8-12 48x48 16.00 NO CENTER LINE		11.731	C/L		16			
				WO8-11 48x48 16.00 UNEVEN LANES		11.791	28' R of C/L 28' L of		16			
				WO8-11 48x48 16.00 UNEVEN LANES WO8-11 48x48 16.00 UNEVEN		12.649	28' L of C/L 28' R of		16			
				WO8-11 48x48 16.00 UNEVEN WO8-11 48x48 16.00 UNEVEN		13.654	28' L of		16			
				LANES WO8-12		13.694	28' L of		16			
				WO8-12 48X48 16.00 NO CENTER WO8-11 48X48 16.00 UNEVEN		19.431	28' R of		16			
				LANES WO8-11		2.252	C/L 28' R of		16			
				LANES WO8-11		2.753	C/L 28' L of		16			
				WO8-12 48x48 16.00 NO CENTER		2.816	C/L 28' L of		16			
				WO8-11 48x48 16.00 UNEVEN		20.217	C/L 28' L of		16			
				WO8-12 48x48 16.00 NO CENTER		20.262	28' L of		16			
				UO8-12 48x48 16.00 NO CENTER LINE		20.453	C/L 28' R of C/L		16			
				WO8-11 48x48 16.00 UNEVEN LANES		20.677	28' L of C/L		16			
				WO8-12 48x48 16.00 NO CENTER LINE		20.751	28' L of C/L		16			
				WO8-12 48x48 16.00 NO CENTER LINE		21.846	28' L of C/L		16			
				CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE		21.929	28' L of C'L		12			
				GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES		21.971	28' L of C/L		10			
				CONST-7-72 72x36 18.00 RATE OUR WORK ZONE		22.052	28' L of C/L		18			
				GO20-2 48x24 8.00 END ROAD WORK		22.052	28' R of C/L		8			

Revision 4/1/2020 Page 5 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work. The information below this line are details for Construction Signs (if applicable). Project DWR Date Total Quantity Posted Sign Information Station Log Location Number of SF Each Number For DWR Date Mile Sign Special Sign J9P3520 0120 October 23. 816 WO8-12 48x48 16.00 NO CENTER 3.00 28' R of 16 LINE C/L 28' R of WO8-11 48x48 16.00 UNEVEN 3.047 16 LANES C/L WO8-11 48x48 16.00 UNEVEN 3.317 28' L of 16 LANES C/L WO8-12 48x48 16.00 NO CENTER 4.355 28' L of 16 LINE C/L WO8-12 48x48 16.00 NO CENTER 4.477 28' R of 16 LINE WO8-11 28' R of 48x48 16.00 UNEVEN 4.522 16 LANES WO8-11 48x48 16.00 UNEVEN 5.138 28' L of 16 C/L **LANES** WO8-12 48x48 16.00 NO CENTER 5.178 28' L of 16 LINE C/L WO8-11 48x48 16.00 UNEVEN 5.474 28' R of 16 LANES C/L WO8-11 28' L of 48x48 16.00 UNEVEN 5.938 16 LANES WO8-12 28' R of 48x48 16 00 NO CENTER 6.421 16 WO8-11 48x48 16.00 UNEVEN 6.465 28' R of 16 **LANES** C/L WO8-11 48x48 16.00 UNEVEN 6.868 28' L of 16 LANES C/L WO8-12 48x48 16.00 NO CENTER 6.986 28' L of 16 LINE C/L WO8-12 48x48 16.00 NO CENTER 7.591 28' L of 16 WO8-11 28' R of 48x48 16.00 UNEVEN 8.124 16 LANES C/L WO8-11 48x48 16.00 UNEVEN 8.535 28' L of 16 LANES C/L 28' R of WO8-12 48x48 16.00 NO CENTER 8.792 16 LINE C/L WO8-11 48x48 16.00 UNEVEN 8.838 28' R of 16 LANES WO8-12 48x48 16.00 NO CENTER 9.598 28' L of 16 C/L 28' R of WO8-11 48x48 16.00 UNEVEN 9.783 16 LANES C/L November 128 WO8-11 48x48 16.00 UNEVEN 16.041 25' L of 16 11, 2020 **LANES** C/L WO8-12 25' L of 48x48 16.00 NO CENTER 16.152 16 LINE C/L WO8-11 48x48 16.00 UNEVEN 16.335 25' R of 16 LANES C/L WO8-11 25' L of 48x48 16.00 UNEVEN 18.173 16 LANES C/L WO8-12 48x48 16.00 NO CENTER 18.263 25' L of 16 LINE WO8-12 48x48 16.00 NO CENTER 18.399 25' R of 16 LINE C/L WO8-11 48x48 16.00 UNEVEN 18.442 25' R of 16 LANES C/L WO8-11 19.286 25' L of 48x48 16.00 UNEVEN 16 **LANES** C/L WO8-12 November 80 48x48 16.00 NO CENTER 14.037 28' R of 16 12, 2020 LINE C/L WO8-12 48x48 16.00 NO CENTER 15.064 28' L of 16 LINE C/L WO8-12 48x48 16.00 NO CENTER 28' R of 16.292 16

Revision 4/1/2020 Page 6 of 16

C/L



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The strate was attended as	41-1- 11		O! /!f !! l- ! - \
i ne information be	iow this line are	details for Construct	ion Signs (if applicable).

Project	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
J9P3520	0120	November 12, 2020	80	WO8-12 48x48 16.00 NO CENTER LINE		20.829	28' R of C/L		16			
				WO8-12 48x48 16.00 NO CENTER LINE		7.117	28' R of C/L		16			
	0120 - To	otal										

Revision 4/1/2020 Page 7 of 16



Lie	Description:	A alice to a second	O#	E-4	C==-1-1	Cuncted	A ma c	Denvisides
Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0020	MISC. MODIFIED SHAPING SLOPES, CLASS III	Material		6	Nov 16, 2020	SYSTEM	(\$10,080.00)	
				6	Nov 16, 2020	SYSTEM	\$10,080.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				7	Dec 3, 2020	SYSTEM	(\$54,635.00)	
				7	Dec 3, 2020	SYSTEM	\$54,635.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0020 -	- Total						\$0.00	
0030	MISC. PERMANENT AGGREGATE EDGE TREATMENT	Material		7	Dec 3, 2020	SYSTEM	(\$119,582.31)	
				7	Dec 3, 2020	SYSTEM	\$119,582.31	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				8	Dec 16, 2020	SYSTEM	(\$119,583.09)	
				8	Dec 16, 2020	SYSTEM	\$119,583.09	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user turnep3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				9	Jan 4, 2021	SYSTEM	(\$119,583.09)	
				9	Jan 4, 2021	SYSTEM	\$119,583.09	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user turnep3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total		- Total				\$0.00 \$0.00	
0030 -			- Total					
0030 -		Material	- Total	7	Dec 3, 2020	SYSTEM	\$0.00	
	- Total	Material	- Total	7		SYSTEM SYSTEM	\$0.00 \$0.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate.
	- Total	Material	- Total		2020 Dec 3,		\$0.00 \$0.00 (\$3,689.02)	Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 5 on the current
	- Total	Material	- Total	7	2020 Dec 3, 2020 Dec 16,	SYSTEM	\$0.00 \$0.00 (\$3,689.02) \$3,689.02	Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 5 on the current
	- Total	Material	- Total	7	Dec 3, 2020 Dec 16, 2020 Dec 16,	SYSTEM	\$0.00 \$0.00 (\$3,689.02) \$3,689.02	Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 2 on the current
	- Total	Material	- Total	7 8 8	Dec 3, 2020 Dec 16, 2020 Dec 16, 2020 Jan 4,	SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,689.02) \$3,689.02 (\$3,689.02)	Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 2 on the current
	- Total	Material	- Total	7 8 8 9	2020 Dec 3, 2020 Dec 16, 2020 Dec 16, 2020 Jan 4, 2021 Jan 4,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,689.02) \$3,689.02 (\$3,689.02) (\$3,689.02)	Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 2 on the current
	- Total	Material		7 8 8 9	2020 Dec 3, 2020 Dec 16, 2020 Dec 16, 2020 Jan 4, 2021 Jan 4,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,689.02) \$3,689.02 (\$3,689.02) \$3,689.02	Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 2 on the current
	GRAVEL (A) OR CRUSHED STONE (B)	Material		7 8 8 9	2020 Dec 3, 2020 Dec 16, 2020 Dec 16, 2020 Jan 4, 2021 Jan 4,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,689.02) \$3,689.02 (\$3,689.02) \$3,689.02 \$3,689.02	Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 2 on the current
0040	Total GRAVEL (A) OR CRUSHED STONE (B) Material - Total Total	Material		7 8 8 9	2020 Dec 3, 2020 Dec 16, 2020 Dec 16, 2020 Jan 4, 2021 Jan 4,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,689.02) \$3,689.02 (\$3,689.02) \$3,689.02 (\$3,689.02) \$3,689.02	Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 2 on the current
0040	GRAVEL (A) OR CRUSHED STONE (B) Material - Total BITUMINOUS PAVEMENT MIXTURE			7 8 8 9 9	2020 Dec 3, 2020 Dec 16, 2020 Dec 16, 2020 Jan 4, 2021 Jan 4, 2021 Oct 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,689.02) \$3,689.02 (\$3,689.02) \$3,689.02 \$3,689.02 \$0.00 \$0.00	Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 2 on the current
0040	GRAVEL (A) OR CRUSHED STONE (B) Material - Total BITUMINOUS PAVEMENT MIXTURE			7 8 8 9 9	2020 Dec 3, 2020 Dec 16, 2020 Dec 16, 2020 Jan 4, 2021 Jan 4, 2021 Oct 1, 2020 Oct 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,689.02) \$3,689.02 (\$3,689.02) \$3,689.02 (\$3,689.02) \$0.00 \$0.00 \$0.00 (\$734,432.03)	Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.

Revision 4/1/2020 Page 8 of 16



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
LITIC	Безоприон	Type	Adjustment Type		Date	By	Amount	romans
0050	BITUMINOUS PAVEMENT MIXTURE	Material	Type					Payment Estimate.
	PG64-22, (BP-1)			5	Nov 2,	SYSTEM	(\$734,432.03)	
					2020		(+, .02.00)	
				5	Nov 2, 2020	SYSTEM	\$734,432.03	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				6	Nov 16, 2020	SYSTEM	(\$1,495,517.54)	
				6	Nov 16, 2020	SYSTEM	\$1,495,517.54	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				7	Dec 3, 2020	SYSTEM	(\$1,495,517.54)	
				7	Dec 3, 2020	SYSTEM	\$1,495,517.54	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				8	Dec 16, 2020	SYSTEM	(\$1,495,522.62)	
				8	Dec 16, 2020	SYSTEM	\$1,495,522.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				9	Jan 4, 2021	SYSTEM	(\$1,495,522.62)	
				9	Jan 4, 2021	SYSTEM	\$1,495,522.62	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				10	Jan 19, 2021	SYSTEM	(\$1,495,522.62)	
				10	Jan 19, 2021	SYSTEM	\$1,495,522.62	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user turnep3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				11	Feb 2, 2021	SYSTEM	(\$1,495,522.62)	
				11	Feb 2, 2021	SYSTEM	\$1,495,522.62	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user turnep3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				12	Feb 16, 2021	SYSTEM	(\$1,495,522.62)	
				12	Feb 16, 2021	SYSTEM	\$1,495,522.62	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user turnep3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Other Item Adjustment	ACAD	2	Sep 16, 2020	turnep3	(\$9,731.85)	AC Index Price Adjustment: -\$9,731.85
				3	Oct 1, 2020	turnep3	(\$20,988.69)	AC Index Price Adjustment: -\$20,988.69
				6	Nov 16, 2020	turnep3	(\$34,193.60)	Asphalt Index Price Adjustment: -\$34,193.60
			ACAD - Tot				(\$64,914.14)	
	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)		FUEL		Dec 16, 2020	turnep3	\$0.02	Correction of Fuel Price adjustment due to rounding BP-1 totals.
			FUEL - Tota	ıl			\$0.02	
	Other Item Adjustment - Total						(\$64,914.12)	
	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Overrun	Overrun	6	Nov 16, 2020	SYSTEM	(\$21,855.70)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				6	Nov 16, 2020	SYSTEM	\$21,855.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) overridding Payment Estimate Exception 6 on the current Payment Estimate.
				7	Dec 3,	SYSTEM	(\$21,881.39)	Averaged Price Adjustment from this item on all previous

Revision 4/1/2020 Page 9 of 16



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0050	BITUMINOUS PAVEMENT MIXTURE	Overrun	Overrun		2020			payment estimates of '-0.93078' is applied (if non-zero).
	PG64-22, (BP-1)			7	Dec 3, 2020	SYSTEM	\$21,881.39	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 11 on the current Payment Estimate.
				8	Dec 16, 2020	SYSTEM	(\$21,881.39)	Averaged Price Adjustment from this item on all previous payment estimates of '-0.93078' is applied (if non-zero).
				8	Dec 16, 2020	SYSTEM	(\$5.07)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				8	Dec 16, 2020	SYSTEM	\$5.07	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 10 on the current Payment Estimate.
				8	Dec 16, 2020	SYSTEM	\$21,881.39	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 10 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Price		2	Sep 16, 2020	SYSTEM	(\$3,555.78)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				3	Oct 1, 2020	SYSTEM	(\$7,668.76)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				6	Nov 16, 2020	SYSTEM	(\$13,421.40)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				8	Dec 16, 2020	SYSTEM	(\$0.02)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			- Total				(\$24,645.96)	
	Price - Total						(\$24,645.96)	
0050 -	·Total						(\$89,560.08)	
0060	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Material		4	Oct 16, 2020	SYSTEM	(\$831,265.85)	
				4	Oct 16, 2020	SYSTEM	\$831,265.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				5	Nov 2, 2020	SYSTEM	(\$2,367,981.98)	
				5	Nov 2, 2020	SYSTEM	\$2,367,981.98	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				6	Nov 16, 2020	SYSTEM	(\$2,367,981.98)	
				6	Nov 16, 2020	SYSTEM	\$2,367,981.98	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user turnep3 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				7	Dec 3, 2020	SYSTEM	(\$2,367,981.98)	
				7	Dec 3, 2020	SYSTEM	\$2,367,981.98	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user turnep3 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				8	Dec 16, 2020	SYSTEM	(\$2,367,983.92)	
				8	Dec 16, 2020	SYSTEM	\$2,367,983.92	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user turnep3 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				9	Jan 4, 2021	SYSTEM	(\$2,367,983.92)	
				9	Jan 4, 2021	SYSTEM	\$2,367,983.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				10	Jan 19, 2021	SYSTEM	(\$2,367,983.92)	
				10	Jan 19, 2021	SYSTEM	\$2,367,983.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user turnep3 overridding Payment Estimate Exception 2 on the current

Revision 4/1/2020 Page 10 of 16



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0060	ASPHALTIC CONCRETE MIXTURE PG	Material						Payment Estimate.
	70-22 (SP125C MIX)			11	Feb 2, 2021	SYSTEM	(\$2,367,983.92)	
				11	Feb 2, 2021	SYSTEM	\$2,367,983.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				12	Feb 16, 2021	SYSTEM	(\$2,367,983.92)	
				12	Feb 16, 2021	SYSTEM	\$2,367,983.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Other Item Adjustment	ACAD	4	Oct 16, 2020	turnep3	(\$28,623.35)	AC Index Price Adjustment: -\$28623.35
	70-22 (SP1230 WIX)	Adjustinent			2020			Calculated by hand using appropriate indexes. AC Index spreadsheet did not include index for October 2020, but value was given in index list on MoDOT website.
				5	Nov 2, 2020	turnep3	(\$52,914.44)	AC Index Price Adjustment: -\$52914.44
			ACAD - Tota	ıl			(\$81,537.79)	
	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)		FUEL	5	Nov 2, 2020	turnep3	(\$25,237.40)	Fuel Price Adjustment: -\$25237.40
				6	Nov 16, 2020	turnep3	\$25,237.40	Correction for double adjustment of Fuel Price Adjustment on Estimate 0005: \$25,237.40
				8	Dec 16, 2020	turnep3	\$0.01	Correction of Fuel Price adjustment due to rounding SP125 totals.
			FUEL - Tota				\$0.01	
	Other Item Adjustment - Total						(\$81,537.78)	
	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Price		4	Oct 16, 2020	SYSTEM	(\$13,651.84)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				5	Nov 2, 2020	SYSTEM	(\$25,237.40)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				8	Dec 16, 2020	SYSTEM	(\$0.01)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			- Total				(\$38,889.25)	
	Price - Total						(\$38,889.25)	
0060 -	Total						(\$120,427.03)	
0070	TACK COAT	Material		1	Sep 2, 2020	SYSTEM	(\$78.00)	
				1	Sep 2, 2020	SYSTEM	\$78.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user turnep3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				2	Sep 16, 2020	SYSTEM	(\$9,036.00)	
				2	Sep 16, 2020	SYSTEM	\$9,036.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				3	Oct 1, 2020	SYSTEM	(\$22,768.00)	
				3	Oct 1, 2020	SYSTEM	\$22,768.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	TACK COAT	Overrun	Overrun	6	Nov 16, 2020	SYSTEM	(\$382.00)	
				6	Nov 16, 2020	SYSTEM	\$382.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user turnep3 overridding Payment Estimate Exception 7 on the current Payment Estimate.

Revision 4/1/2020 Page 11 of 16



Track CoAT Oversian	TACK COAT Coverum Co	Line	Description	Adiustosant	Other	Est.	Created	Created	Amount	Remarks
2000	1000 10000 10000 10000 10000 10000 10000 10000 10000	Line	Description	Adjustment Type	Adjustment				Amount	Remarks
2000	2000	0070	TACK COAT	Overrun	Overrun	7		SYSTEM	(\$382.00)	
BITUMNOUS FOG SEAL Malerial	2000 SYSTEM \$30,000 Prepared Estimate for 0.00007 in applied (from zero).					7		SYSTEM	\$382.00	Payment Estimate Item Adjustment (0008) due to user turnep3 overridding Payment Estimate Exception 12 on the current
2020 Payment Estimate Ben Adjustment (500) also to set true true (7 Payment Estimate Ben Adjustment (500) also to set true true (7 Payment Estimate Exception 11 on the current (7 Payment Estimate Exception 12 on the current (7 Payment Estimate Exception 13 on the current (7 Payment Estimate Exception 14 on the current (7 Payment Estimate Exception 15 on the current (7 Payment	Overrun - Total Overru					8		SYSTEM	(\$382.00)	
OPTO-Total 19.00	Overrun - Total					8		SYSTEM	\$382.00	Payment Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Exception 11 on the current
Solid					Overrun - T	otal			\$0.00	
BITUMINOUS FOG SEAL Material Four Fo	Second S		Overrun - Total						\$0.00	
		0070 -	Total						\$0.00	
		0800	BITUMINOUS FOG SEAL	Material		7		SYSTEM	(\$15,542.28)	
Material - Total S0.00	Material - Total S0.00					7		SYSTEM	\$15,542.28	Payment Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Exception 8 on the current
TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) Adjustment Other Item Adjustme	Communication Communicatio				- Total				\$0.00	
TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) Adjustment	TRUCK OR TRAILER MOUNTED ADJUSTMENT Adjustment Dec 16,		Material - Total						\$0.00	
ATTENUATOR (TMA) Adjustment 2020 0	ATTENUATOR (TMA) Adjustment 2020 3	0080 -	Total						\$0.00	
Comparison of the comparison	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) Other Itom Adjustment - Total Overrun 7 Dec 3, 2020 TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) Other Itom Adjustment - Total Overrun 7 Dec 3, 2020 TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) Overrun 7 Dec 3, 2020 TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) Overrun 7 Dec 3, 2020 TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) Overrun 7 Dec 3, 2020 TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) Overrun 7 Dec 3, 2020 TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) Overrun 7 Dec 3, 2020 TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) Overrun 7 Dec 3, 2020 TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) Overrun 7 Dec 3, 2020 TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) Overrun 7 Dec 3, 2020 TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) Overrun 7 Dec 3, 2020 Overrun 7 Dec 3,	0090			OADJ	8		turnep3	(\$1,000.00)	Removal of previous line item adjustment for overrun of 2 TMAs. Change Order has been submitted and is awaiting approval.
TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) OTHR - Total Other Item Adjustment - Total Overrun - Total Ove	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)					9		turnep3	(\$1,000.00)	Order 0003 has been submitted and approved which included
ATTENUATOR (TMA) OTHR - Total TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) Provided the second of th	ATTENUATOR (TMA)				OADJ - Tota	al			(\$2,000.00)	
Overrun - Total Overru	Overrun - Total TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) Page 3, 2020				OTHR	10		turnep3	\$1,000.00	This adjustment ensures full payment for Line 0090: TMAs, and zeroes any previous adjustments.
TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) Provided Trailing And PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR Truck OR TRAILER MOUNTED ACTION BY STEM Sep 2. SySTEM \$6,206.32 This adjustment offsets the original system-generated Over Payment Estimate Exception 3 on the current Payment Estimate Exception 2 on the current Payment Estimate Exception 2 on the current Payment Estimate Exception 2 on the current Payment Estimate Exception 3 on the current Payment Estimate Exception 2 on the current Payment Estimate Exception 2 on the current Payment Estimate Exception 2 on the current Payment Estimate Exception 3 on the current Payment Estimate Exception 3 on the current Payment Estimate Exception 2 on the current Payment Estimate Exception 3 on the current Payment Estimate Exception 2 on the current Payment Estimate Exception 3 on the current Payment Estimate Exception 2 on the current Payment Estimate Exception 3 on the current Payment Estimate Exception 2 on the current Payment Estimate Exception 3 on the current Payment Estimate Exception 3 on the current Payment Estimate Exception 2 on the current Payment Estimate Exception 3 on the current Payment Estimate Exception	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) Overrun				OTHR - Tot	al			\$1,000.00	
ATTENUATOR (TMA) 2020 Turnep3 \$1,000.00 Due to additional TMAs required for Striping and Rumble St operations, \$1000 was adjusted for the 2 additional TMAs (per EA) until a Change Order correcting the quantity is submitted. 9	ATTENUATOR (TMA) 2020 Total		Other Item Adjustment - Total						(\$1,000.00)	
2020 Poperations, \$1000 was adjusted for the 2 additional TMAs (per EA) until a change Order correcting the quantity is submitted. 9	2020 2020			Overrun	Overrun	7		SYSTEM	(\$1,000.00)	
Overrun - Total So. 00 FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR Overrun - Total I Sep 2, 2020 SySTEM \$6,206.32 This adjustment offsets the original system-generated Over Payment Estimate litem Adjustment (0002) due to user turn overridding Payment Estimate litem Adjustment (0004) due to user turn overridding Payment Estimate litem Adjustment (0004) due to user turn overridding Payment Estimate litem Adjustment (0004) due to user turn overridding Payment Estimate litem Adjustment (0004) due to user turn overridding Payment Estimate litem Adjustment (0004) due to user turn overridding Payment Estimate Exception 2 on the current Payment Estimate litem Adjustment (0004) due to user turn overridding Payment Estimate Exception 2 on the current Payment Estimate Litem Adjustment (0006) due to user turn overridding Payment Estimate Exception 3 on the current Payment Estimate Litem Adjustment (0006) due to user turn overridding Payment Estimate Litem Adjustment (0006) due to user turn overridding Payment Estimate Litem Adjustment (0006) due to user turn overridding Payment Estimate Litem Adjustment (0006) due to user turn overridding Payment Estimate Litem Adjustment (0006) due to user turn overridding Payment Estimate Litem Adjustment (0006) due to user turn overridding Payment Estimate Litem Adjustment (0006) due to user turn overridding Payment Estimate Litem Adjustment (0006) due to user turn overridding Payment Estimate Litem Adjustment (0006) due to user turn overridding Payment Estimate Litem Adjustment (0006) due to user turn overridding Payment Estimate Litem Adjustment (0006) due to user turn overridding Payment Estimate Litem Adjustment (0006) due to user turn overridding Payment Estimate Litem Adjustment (0006) due to user turn overridding Payment Estimate Litem Adjustment overridding Payment	Overrun - Total St,000.00 St,000.000 - 500.00000, 'is applied (if non-zero). St,000.00 St,000.00 St,000.00 St,000.000					7		turnep3	\$1,000.00	
Overrun - Total S1,000.00 PURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR Sep 2, 2020 SYSTEM (\$6,206.32) SYSTEM \$6,206.32 This adjustment offsets the original system-generated Over Payment Estimate ltem Adjustment (0002) due to user turn overridding Payment Estimate ltem Adjustment (0004) due to user turn overridding Payment Estimate ltem Adjustment (0004) due to user turn overridding Payment Estimate ltem Adjustment (0004) due to user turn overridding Payment Estimate ltem Adjustment (0004) due to user turn overridding Payment Estimate ltem Adjustment offsets the original system-generated Over Payment Estimate ltem Adjustment (0004) due to user turn overridding Payment Estimate Exception 2 on the current Payment Estimate ltem Adjustment offsets the original system-generated Over Payment Estimate ltem Adjustment (0006) due to user turn overridding Payment Estimate Exception 3 on the current Payment Estimate ltem Adjustment (0006) due to user turn overridding Payment Estimate Exception 3 on the current Payment Estimate E	Overrun - Total S1,000.00					9		SYSTEM		quantity on all previous payment estimates. Price Adjustments of
Sumarian	Sum				Overrun - T	otal				
PARTIAL DEPTH PAVEMENT REPAIR Material 1 Sep 2, 2020 SYSTEM (\$6,206.32) 1 Sep 2, 2020 SYSTEM \$6,206.32 This adjustment offsets the original system-generated Over Payment Estimate Item Adjustment (0002) due to user turns overridding Payment Estimate Item Adjustment (0004) due to user turns overridding Payment Estimate Item Adjustment (0004) due to user turns overridding Payment Estimate Item Adjustment (0004) due to user turns overridding Payment Estimate Item Adjustment (0004) due to user turns overridding Payment Estimate Exception 2 on the current Payment Estimate Item Adjustment (0004) due to user turns overridding Payment Estimate Exception 2 on the current Payment Estimate Item Adjustment (0006) due to user turns overridding Payment Estimate Item Adjustment (0006) due to user turns overridding Payment Estimate Item Adjustment (0006) due to user turns overridding Payment Estimate Item Adjustment (0006) due to user turns overridding Payment Estimate Item Adjustment (0006) due to user turns overridding Payment Estimate Exception 3 on the current Payment Estimate Item Adjustment (0006) due to user turns overridding Payment Estimate Exception 3 on the current Payment Estimate Exception 3 o	1 Sep 2, 2020 SYSTEM \$6,206.32		Overrun - Total						\$1,000.00	
BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR 1 Sep 2, 2020 1 Sep 2, 2020 2 Sep 16, 2020 2 Sep 16, 2020 2 Sep 16, 2020 3 Oct 1, 2020 3 SYSTEM \$6,206.32 46,206.32 57 This adjustment offsets the original system-generated Over Payment Estimate Exception 3 on the current Payment Estimate Item Adjustment (0004) due to user turn overridding Payment Estimate Exception 2 on the current Payment Estimate. 3 Oct 1, 2020 3 Oct 1, 2020 3 Oct 1, 2020 3 SYSTEM \$6,206.32 This adjustment offsets the original system-generated Over Payment Estimate Exception 2 on the current Payment Estimate.	BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR 1 Sep 2, 2020 1 Sep 2, 2020 2 Sep 16, 2020 2 Sep 16, 2020 2 Sep 16, 2020 3 Oct 1, 2020 4 Oct 16, SYSTEM 4 Oct 16, SYSTEM (\$57,433.91) 5 SYSTEM (\$57,433.91)	0090 -	Total						\$0.00	
1 Sep 2, 2020 SYSTEM \$6,206.32 This adjustment offsets the original system-generated Over Payment Estimate Estimate Exception 3 on the current Payment Estimate Exception 3 on the current Payment Estimate Exception 3 on the current Payment Estimate Item Adjustment (0004) due to user turns overridding Payment Estimate Item Adjustment (0004) due to user turns overridding Payment Estimate Exception 2 on the current Payment Estimate. 3 Oct 1, 2020 SYSTEM (\$6,206.32) 3 Oct 1, 2020 This adjustment offsets the original system-generated Over Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Over Payment Estimate Item Adjustment (0004) due to user turns overridding Payment Estimate Item Adjustment (0006) due to user turns overridding Payment Estimate Exception 3 on the current Payment Estimate Exception 3 on the current Payment Estimate.	1 Sep 2, 2020 SYSTEM \$6,206.32 This adjustment offsets the original system-generated Overrun Payment Estimate Exception 3 on the current Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate Exception 2 on the current Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Estimate Exception 3 on the current Payment Estimate Estimate Exception 3 on the current Payment	0100	BITUMINOUS MATERIAL FOR CLASS C	Material		1		SYSTEM	(\$6,206.32)	
2 Sep 16, 2020 \$SYSTEM \$6,206.32 This adjustment offsets the original system-generated Over Payment Estimate Item Adjustment (0004) due to user turns overridding Payment Estimate Exception 2 on the current Payment Estimate. 3 Oct 1, 2020 \$SYSTEM \$6,206.32 This adjustment offsets the original system-generated Over Payment Estimate Item Adjustment (0006) due to user turns overridding Payment Estimate Exception 3 on the current Payment Estimate Exception 3 on the current Payment Estimate.	2 Sep 16, 2020 \$\frac{1}{2020}\$ \$1		PARTIAL DEFTIT PAVEMENT REPAIR			1		SYSTEM	\$6,206.32	Payment Estimate Item Adjustment (0002) due to user turnep3 overridding Payment Estimate Exception 3 on the current
2020 Payment Estimate Item Adjustment (0004) due to user turno overridding Payment Estimate Exception 2 on the current Payment Estimate. 3 Oct 1, 2020 3 Oct 1, 2020 SYSTEM \$6,206.32 This adjustment offsets the original system-generated Over Payment Estimate Item Adjustment (0006) due to user turno overridding Payment Estimate Exception 3 on the current Payment Estimate.	2020 Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate. 3 Oct 1, 2020 3 Oct 1, SYSTEM \$6,206.32 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate. 4 Oct 16, SYSTEM \$57,433.91					2		SYSTEM	(\$6,206.32)	
2020 3 Oct 1, 2020 \$ SYSTEM \$6,206.32 This adjustment offsets the original system-generated Over Payment Estimate Item Adjustment (0006) due to user turns overridding Payment Estimate Exception 3 on the current Payment Estimate.	2020 3 Oct 1, 2020 \$ \$6,206.32 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate. 4 Oct 16, SYSTEM (\$57,433.91)					2		SYSTEM	\$6,206.32	Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 2 on the current
2020 Payment Estimate Item Adjustment (0006) due to user turne overridding Payment Estimate Exception 3 on the current Payment Estimate.	2020 Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate. 4 Oct 16, SYSTEM (\$57,433.91)					3		SYSTEM	(\$6,206.32)	
						3		SYSTEM	\$6,206.32	Payment Estimate Item Adjustment (0006) due to user turnep3

Revision 4/1/2020 Page 12 of 16



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0100	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	Material		4	Oct 16, 2020	SYSTEM	\$57,433.91	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				5	Nov 2, 2020	SYSTEM	(\$57,433.91)	
				5	Nov 2, 2020	SYSTEM	\$57,433.91	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user turnep3 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				6	Nov 16, 2020	SYSTEM	(\$57,433.91)	
				6	Nov 16, 2020	SYSTEM	\$57,433.91	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				7	Dec 3, 2020	SYSTEM	(\$57,433.91)	
				7	Dec 3, 2020	SYSTEM	\$57,433.91	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user turnep3 overridding Payment Estimate Exception 9 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C	Other Item Adjustment	ACAD	1	Sep 2, 2020	turnep3	(\$80.21)	AC Price Index Adjustment: -\$80.21
	PARTIAL DEPTH PAVEMENT REPAIR			4	Oct 16, 2020	turnep3	(\$662.28)	AC Index Price Adjustment: -\$662.28
								Calculated according to index appropriate for when the work was performed (9/9/2020).
			ACAD - Tota	al			(\$742.49)	
	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C		FUEL	1	Sep 2, 2020	turnep3	(\$34.67)	Asphalt Paving Production and Hauling Fuel Adjustment: - \$34.67
	PARTIAL DEPTH PAVEMENT REPAIR			4	Oct 16, 2020	turnep3	(\$256.65)	Fuel Price Adjustment: -\$256.65
								Calculated according to index appropriate for when the work was performed (9/9/2020).
			FUEL - Tota				(\$291.32)	
	Other Item Adjustment - Total						(\$1,033.81)	
	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C	Overrun	Overrun	4	Oct 16, 2020	SYSTEM	(\$4,487.99)	
	PARTIAL DEPTH PAVEMENT REPAIR			4	Oct 16, 2020	SYSTEM	\$4,487.99	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) overridding Payment Estimate Exception 4 on the current Payment Estimate.
				5	Nov 2, 2020	SYSTEM	(\$4,487.99)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				5	Nov 2, 2020	SYSTEM	\$4,487.99	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) overridding Payment Estimate Exception 5 on the current Payment Estimate.
				6	Nov 16, 2020	SYSTEM	(\$4,487.99)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				6	Nov 16, 2020	SYSTEM	\$4,487.99	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) overridding Payment Estimate Exception 8 on the current Payment Estimate.
				7	Dec 3, 2020	SYSTEM	(\$4,487.99)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				7	Dec 3, 2020	SYSTEM	\$4,487.99	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) overridding Payment Estimate Exception 14 on the current Payment Estimate.
				8	Dec 16, 2020	SYSTEM	(\$4,487.99)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				8	Dec 16, 2020	SYSTEM	(\$10.34)	
				8	Dec 16, 2020	SYSTEM	\$10.34	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user turnep3 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				8	Dec 16, 2020	SYSTEM	\$4,487.99	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user turnep3

Revision 4/1/2020 Page 13 of 16



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0100	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	Overrun	Overrun					overridding Payment Estimate Exception 13 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0100 -	·Total						(\$1,033.81)	
0110	REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	Overrun	Overrun	2	Sep 16, 2020	SYSTEM	(\$1,408.43)	
				2	Sep 16, 2020	SYSTEM	\$1,408.43	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				3	Oct 1, 2020	SYSTEM	(\$1,408.43)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				3	Oct 1, 2020	SYSTEM	\$1,408.43	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user turnep3 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				4	Oct 16, 2020	SYSTEM	(\$1,408.43)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				4	Oct 16, 2020	SYSTEM	\$1,408.43	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				5	Nov 2, 2020	SYSTEM	(\$1,408.43)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				5	Nov 2, 2020	SYSTEM	\$1,408.43	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user turnep3 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				6	Nov 16, 2020	SYSTEM	(\$1,408.43)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				6	Nov 16, 2020	SYSTEM	\$1,408.43	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user turnep3 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				7	Dec 3, 2020	SYSTEM	(\$1,408.43)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				7	Dec 3, 2020	SYSTEM	\$1,408.43	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user turnep3 overridding Payment Estimate Exception 15 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0110 -	· Total						\$0.00	
0120	CONSTRUCTION SIGNS	Material		1	Sep 2, 2020	SYSTEM	(\$480.00)	
				1	Sep 2, 2020	SYSTEM	\$480.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0120 -	· Total						\$0.00	
0150	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR	Material		1	Sep 2, 2020	SYSTEM	(\$5,600.00)	
	FURNISHED, CONTRACTOR RETAINED			1	Sep 2, 2020	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0150 -	Total						\$0.00	
0170	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material		7	Dec 3, 2020	SYSTEM	(\$7,120.00)	
				7	Dec 3,	SYSTEM	\$7,120.00	This adjustment offsets the original system-generated Overrun

Revision 4/1/2020 Page 14 of 16



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
		Туре	Adjustment Type	Number	Date	Ву		
0170	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material			2020			Payment Estimate Item Adjustment (0015) due to user turnep3 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				8	Dec 16, 2020	SYSTEM	(\$8,280.00)	
				8	Dec 16, 2020	SYSTEM	\$8,280.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user turnep3 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				9	Jan 4, 2021	SYSTEM	(\$8,280.00)	
				9	Jan 4, 2021	SYSTEM	\$8,280.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user turnep3 overridding Payment Estimate Exception 7 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0170 -	·Total						\$0.00	
0180	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	Material		8	Dec 16, 2020	SYSTEM	(\$7,800.00)	
				8	Dec 16, 2020	SYSTEM	\$7,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user turnep3 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				9	Jan 4, 2021	SYSTEM	(\$7,800.00)	
				9	Jan 4, 2021	SYSTEM	\$7,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 8 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0180 -	· Total						\$0.00	
0190	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT	Material		8	Dec 16, 2020	SYSTEM	(\$3,640.00)	
	ARROW			8	Dec 16, 2020	SYSTEM	\$3,640.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user turnep3 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				9	Jan 4, 2021	SYSTEM	(\$3,640.00)	
				9	Jan 4, 2021	SYSTEM	\$3,640.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user turnep3 overridding Payment Estimate Exception 9 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT	Overrun	Overrun	8	Dec 16, 2020	SYSTEM	(\$560.00)	
	ARROW			8	Dec 16, 2020	SYSTEM	\$560.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) overridding Payment Estimate Exception 14 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0190 -	· Total						\$0.00	
0230	MISC. PREFORMED THERMOPLASTIC PAVEMENT MARKING, LANE	Material		8	Dec 16, 2020	SYSTEM	(\$4,000.00)	
	REDUCTION ARROW			8	Dec 16, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user turnep3 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				9	Jan 4, 2021	SYSTEM	(\$4,000.00)	
					Jan 4,	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Material

Revision 4/1/2020 Page 15 of 16



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0230		Material	- Total				\$0.00	
	Material - Total						\$0.00	
0230 -	- Total						\$0.00	
0250	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	Overrun	Overrun	11	Feb 2, 2021	SYSTEM	(\$4,770.40)	
				11	Feb 2, 2021	SYSTEM	\$4,770.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			Overrun - To	otal			\$0.00	
	Overrun - Total						\$0.00	
0250 -	- Total						\$0.00	
0280	MGS GUARDRAIL	Construction Stockpile		2	Sep 16, 2020	SYSTEM	\$21,339.36	Payment Estimate Item Adjustment generated Stockpile Transaction
				6	Nov 16, 2020	SYSTEM	(\$3,690.56)	Payment Estimate Item Adjustment generated Stockpile Transaction
				7	Dec 3, 2020	SYSTEM	(\$13,910.55)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$3,738.25	
	Construction Stockpile - Total						\$3,738.25	
0280 -	- Total						\$3,738.25	
0290	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	Construction Stockpile		2	Sep 16, 2020	SYSTEM	\$29,200.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				6	Nov 16, 2020	SYSTEM	(\$3,244.44)	Payment Estimate Item Adjustment generated Stockpile Transaction
				7	Dec 3, 2020	SYSTEM	(\$25,955.56)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
0290 -	- Total						\$0.00	
0300	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		2	Sep 16, 2020	SYSTEM	\$38,766.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				6	Nov 16, 2020	SYSTEM	(\$6,626.67)	Payment Estimate Item Adjustment generated Stockpile Transaction
				7	Dec 3, 2020	SYSTEM	(\$28,163.33)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$3,976.00	
	Construction Stockpile - Total						\$3,976.00	
0300 -	- Total						\$3,976.00	
5001	ADVANCED WARNING RAIL SYSTEM	Material		8	Dec 16, 2020	SYSTEM	(\$70.00)	
				8	Dec 16, 2020	SYSTEM	\$70.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				9	Jan 4, 2021	SYSTEM	(\$70.00)	
				9	Jan 4, 2021	SYSTEM	\$70.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Exception 6 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
5001 -	- Total						\$0.00	
Overa	all - Total						(\$203,306.67)	

Revision 4/1/2020 Page 16 of 16