

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: March 16, 2021

Progress Estimate Number	Contract ID	200320-H04				Original Contract Amount	
14	Prime Contracto	or Capital Paving & Construction	, LLC P	Pay Period End	March 15, 2021	•	· · · /
1-7						Current Contract Amount	\$4,890,956.65

Approval Date		By User
March 17, 2021	Generated and Approved (and should be considered Draft) at the Project Office Level by	turnep3
March 17, 2021	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	wilkem1
March 17, 2021	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
November 1, 2020	November 25, 2020		98.59%

	Milestones		
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract
Acceptance Date			
Awarded Date	April 1, 2020	April 1, 2020	
Letting Date	March 20, 2020	March 20, 2020	
Notice to Proceed Date	June 1, 2020	June 1, 2020	
Open to Traffic Date			
Work Began Date	August 31, 2020	August 31, 2020	

Contract Total Pay For Estimate No. 14								
	This Estimate	Previous	To Date					
200320-H04								
Total Posted Items Pay	\$85,521.86	\$4,736,380.64	\$4,821,902.50					
Gross Item Adjustments	(\$7,714.25)	(\$203,306.67)	(\$211,020.92)					
Incentive	\$22,444.65	\$232,391.79	\$254,836.44					
Disincentive	(\$2,627.82)	\$0.00	(\$2,627.82)					
Liquidated Damage	\$0.00	\$0.00	\$0.00					
Other Contract Adjustments	\$0.00	(\$2,231.66)	(\$2,231.66)					
		\$4,763,234.10	\$4,860,858.54					
Contract Total Payable This Estimate:	\$97,624.44							

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount		
J9P3520	0020	2159903	MISC.MODIFIED SHAPING SLOPES, CLASS III	LF	\$14.000	900	\$12,600.00		
	0280	6061060	MGS GUARDRAIL	LF	\$24.000	400	\$9,600.00		
	0290	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	EA	\$3,050.000	4	\$12,200.00		
	0300	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	EA	\$2,850.000	4	\$11,400.00		
	5002	6069901	MISC.Misc. Guardrail Item: Box Culvert Thrie Beam	LS	\$39,721.860	1	\$39,721.86		
Project J9P3	520 - Total						\$85,521.86		
Overall - Total									

Contract Adjustments This Estimate

Adj Type	Entered By	Comments	Time Units	Rate	Amount
ABIRIncentive	turnep3	IRI Smoothness Incentive for 55 mph+: 3% Bonus for 24414 total LF of Segments = \$6,265.64			\$6,265.64
SPADIncentive	turnep3	Elevated Density Adjustment: 1% Bonus for Sublots between 94% and 97% = \$14,231.80			\$14,231.80
OTHRDisincentive	turnep3	Marred Surface Deduction from Diamond Grinding: (\$1,384.65) Calculated from Field Measurements			(\$1,384.65)
ADIRDisincentive	turnep3	IRI Smoothness Deduction for 55 mph+: 3% Deduction for 4844 total LF of Segments = (\$1,243.17)			(\$1,243.17)

Revision 4/1/2020 Page 1 of 17



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: March 16, 2021

Progress Estimate Number 14		00320-H04 I apital Paving & Construction, LLC I		15, 2021 Net Change O	ract Amount \$4,898,461.04 Prder Amount (\$7,504.39) ract Amount \$4,890,956.65
Adi Type	Entered By	Comments	Time Units	Rate	Amount

Adj Type	Entered By	Comments	Time Units	Rate	Amount
ABIRIncentive	turnep3	IRI Smoothness Incentive for 45 mph: 3% Bonus for 7578 total LF of Segments = \$1,947.21			\$1,947.21

Overall - Total \$19,816.83

Overall -	These amounts are listed in the Incentive, Disincentive, Liquidated Damages or Other Contract Adjustment										
ine Item	<u>Adjust</u>	ments This Estimate									
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount			
	0050	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Material			-11,478.8	\$56.48	(\$648,322.62			
	0050	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user turnep3 overridding Payment Estimate Exception 1 on the current Payment Estimate.	11,478.8	\$56.48	\$648,322.62			
	0060	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Material			-36,605.1	\$64.69	(\$2,367,983.92			
	0060	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.	36,605.1	\$64.69	\$2,367,983.92			
	0280	MGS GUARDRAIL	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$3,738.25			
	0300	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$3,976.00			
Total								(\$7,714,25			

Revision 4/1/2020 Page 2 of 17



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Information						
Project Number	Federal Proj. Number	Project Description	Route	County		Location of Work						
J9P3520	FAF 412-1(17)	Resurface	412	DUNKLIN	from end of divided highw	from end of divided highway to Route VV						
Totals by	Job Numbe	rs .										
J9P3520												
J9F3320					This Estimate	Previous	To Date					
J9F3520	Poste	l Item Pay			This Estimate \$85,521.86	Previous \$4,736,380.64	To Date \$4,821,902.50					
J9F3520		l Item Pay Item Adjustme	ents									
J9F3520				Item Pay	\$85,521.86	\$4,736,380.64	\$4,821,902.50					
J9F3520		Item Adjustme		Item Pay	\$85,521.86 (\$7,714.25)	\$4,736,380.64 (\$203,306.67)	\$4,821,902.50 (\$211,020.92)					
J9F3520	Gross	Item Adjustme		Item Pay	\$85,521.86 (\$7,714.25) \$77,807.61	\$4,736,380.64 (\$203,306.67) \$4,533,073.97	\$4,821,902.50 (\$211,020.92) \$4,610,881.58					
J9F3520	Gross Incent Disinc	Item Adjustme	Gross	Item Pay	\$85,521.86 (\$7,714.25) \$77,807.61 \$22,444.65	\$4,736,380.64 (\$203,306.67) \$4,533,073.97 \$232,391.79	\$4,821,902.50 (\$211,020.92) \$4,610,881.58 \$254,836.44					

Revision 4/1/2020 Page 3 of 17



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J9P3520, Item 4011209, Project Item Line Number 0050, Material Set 401120996, Material 0401BPPMBP1 - Plant Mix for Bit Pavement BP-1, Acceptance Action Generic AspLow is insufficient.	Resolving issues with QC testing results not showing up.	turnep3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3520, Item 4030103, Project Item Line Number 0060, Material Set 403010396, Material 0403SP125CLG - Superpave 12.5 mm, Des C 80 Gyros, Acceptance Action Generic AspHigh is insufficient.	Resolving issues with QC testing results not showing up.	turnep3	Overridden

Revision 4/1/2020 Page 4 of 17



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract lm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
00320-H04	J9P3520	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$16,064.79	\$16,064.79
		0001	0020	2159903	MISC.MODIFIED SHAPING SLOPES, CLASS III	4,918.00	0.00	4,918.00	LF	4,842.50	\$14.00	\$67,795.00
		0001	0030	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	4,090.90	-395.60	3,695.30	TONS	3,695.30	\$38.68	\$142,934.20
		0001	0040	3105002	GRAVEL (A) OR CRUSHED STONE (B)	134.00	0.00	134.00	TONS	134.00	\$27.53	\$3,689.02
		0001	0050	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	26,084.80	394.00	26,478.80	TONS	26,478.80	\$56.48	\$1,495,522.62
		0001	0060	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	37,345.50	-740.40	36,605.10	TONS	36,605.10	\$64.69	\$2,367,983.92
		0001	0070	4071005	TACK COAT	50,915.00	191.00	51,106.00	GAL	51,106.00	\$2.00	\$102,212.00
		0001	0080	4134000	BITUMINOUS FOG SEAL	18,233.00	-10,937.00	7,296.00	GAL	7,296.00	\$2.34	\$17,072.64
		0001	0090	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	2.00	4.00	EA	4.00	\$500.00	\$2,000.00
		0001	0100	6133020	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	307.20	26.10	333.30	TONS	333.30	\$172.35	\$57,444.26
		0001	0110	6133021	REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	1,806.10	105.50	1,911.60	SQYD	1,911.60	\$13.35	\$25,519.86
		0001	0120	6161005	CONSTRUCTION SIGNS	3,547.00	0.00	3,547.00	SQFT	2,279.00	\$5.00	\$11,395.00
		0001	0130	6161009	FLAG ASSEMBLY	6.00	0.00	6.00	EA	6.00	\$20.00	\$120.00
		0001	0140	6161025	CHANNELIZER (TRIM LINE)	110.00	0.00	110.00	EA	110.00	\$20.00	\$2,200.00
		0001	0150	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$2,800.00	\$5,600.00
		0001	0160	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$118,630.47	\$118,630.47
		0001	0170	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	429.00	-15.00	414.00	LF	414.00	\$20.00	\$8,280.00
		0001	0180	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	425.00	-35.00	390.00	LF	390.00	\$20.00	\$7,800.00
		0001	0190	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	11.00	2.00	13.00	EA	13.00	\$280.00	\$3,640.00
		0001	0200	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	63,365.00	0.00	63,365.00	LF	0.00	\$0.15	\$0.00
		0001	0210	6205902A	$\bf 6$ IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	229,952.00	0.00	229,952.00	LF	0.00	\$0.20	\$0.00
		0001	0220	6209901	MISC.TEMPORARY PAVEMENT MARKING PAINT	1.00	0.00	1.00	LS	0.00	\$0.00	\$0.00
		0001	0230	6209902	MISC.PREFORMED THERMOPLASTIC PAVEMENT MARKING, LANE REDUCTION ARROW	2.00	0.00	2.00	EA	2.00	\$2,000.00	\$4,000.00
		0001	0240	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	27,934.00	-1,242.00	26,692.00	SQYD	26,692.00	\$1.23	\$32,831.16
		0001	0250	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	9,730.00	890.00	10,620.00	SQYD	10,620.00	\$5.36	\$56,923.20
		0001	0260	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	1,914.00	0.00	1,914.00	STA	1,914.00	\$15.50	\$29,667.00
		0001	0270	6261001	BITUMINOUS CENTERLINE RUMBLE STRIP	941.00	0.00	941.00	STA	941.00	\$15.50	\$14,585.50
		0010	0280	6061060	MGS GUARDRAIL	2,088.00	0.00	2,088.00	LF	1,950.00	\$24.00	\$46,800.00
		0010	0290	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	20.00	3.00	23.00	EA	23.00	\$3,050.00	\$70,150.00
		0010	0300	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	26.00	0.00	26.00	EA	25.00	\$2,850.00	\$71,250.00
		0001	5001	6161008	ADVANCED WARNING RAIL SYSTEM	0.00	2.00	2.00	EA	2.00	\$35.00	\$70.00
		0010	5002	6069901	MISC.Misc. Guardrail Item: Box Culvert Thrie Beam	0.00	1.00	1.00	LS	1.00	\$39,721.86	\$39,721.86
					late as of Report Generated Date							\$4,821,902.50
00320-H04 Ove	erall - Total	Value Post	ted to Da	te as of Repo	ort Generated Date							\$4,821,902.50

Revision 4/1/2020 Page 5 of 17



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J9P3520

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0020	2159903	MISC. SHAPING SLOPES	3/4/21	3/16/21	450.00	LF	EB Lane of Box Culvert A1205	20.012	ROC	20.079	ROC	Field Measured
				3/16/21	450.00	LF	WB Lane of Box Culvert A1205	20.033	LOC	20.100	LOC	Field Measured
0280	6061060	MGS GUARDRAIL	3/4/21	3/16/21	200.00	LF	EB Lane of Box Culvert A1205	20.012	ROC	20.079	ROC	
				3/16/21	200.00	LF	WB Lane of Box Culvert A1205	20.033	LOC	20.100	LOC	
0290	6061069	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	3/4/21	3/16/21	2.00	EA	SE and NE Corners of Box Culvert A1205	20.012	ROC	20.079	ROC	
				3/16/21	2.00	EA	SW and NW Corners of Box Culvert A1205	20.033	LOC	20.100	LOC	
0300	6063014	TYPE A CRSHWTHY END TERMINAL (MASH)	3/4/21	3/16/21	1.00	EA	NE Corner of Box Culvert A1205	20.079	ROC			
				3/16/21	1.00	EA	NW Corner of Box Culvert A1205	20.100	LOC			
				3/16/21	1.00	EA	SE Corner of Box Culvert A1205	20.012	ROC			
				3/16/21	1.00	EA	SW Corner of Box Culvert A1205	20.033	LOC			
5002	6069901	MISC. GUARDRAIL ITEM	3/4/21	3/16/21	1.00	LS	Box Culvert A1205	20.012	RLC	20.100	RLC	

5002	6069901 MISC	C. GUARDRAIL ITEM	3/4/21 3/16/	21 1.00 LS Box Culvert A120	5			20.012 RLC	20.100 RLC			
			s for Construction Signs (if appli		01.17	1 10		N. 1. 611	055 10:	0 :10:	055 10 :10:	T. 1051 D
Project P3520		DWR Date October 23, 2020	Total Quantity Posted For DWR Date 816	Sign Information GO20-2 48x24 8.00 END ROAD	Station	Log Mile	Location 28' L of C/L	Number of Items	SF Each Sign 8	Special Sign	SF Each Special Sign	Total SF to Pos
				WORK								
				CONST-7-72 72x36 18.00 RATE OUR WORK ZONE		.856	28' R of C/L		18			
				GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES		.97	28' R of C/L		10			
				CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE		1.033	28' R of C/L		12			
				WO8-12 48x48 16.00 NO CENTER LINE		1.118	28' R of C/L		16			
				WO8-11 48x48 16.00 UNEVEN LANES		1.284	28' R of C/L		16			
				WO8-11 48x48 16.00 UNEVEN LANES		1.82	28' L of C/L		16			
				WO8-11 48x48 16.00 UNEVEN LANES		10.581	28' L of C/L		16			
				WO8-12 48x48 16.00 NO CENTER LINE		10.731	28' R of C/L		16			
				WO8-11 48x48 16.00 UNEVEN LANES		10.774	28' R of C/L		16			
				WO8-11 48x48 16.00 UNEVEN LANES		11.513	28' L of C/L		16			
				WO8-12 48x48 16.00 NO CENTER LINE		11.614	28' L of C/L		16			
				WO8-12 48x48 16.00 NO CENTER LINE		11.731	28' R of C/L		16			
				WO8-11 48x48 16.00 UNEVEN LANES		11.791	28' R of C/L		16			
				WO8-11 48x48 16.00 UNEVEN LANES		12.649	28' L of C/L		16			
				WO8-11 48x48 16.00 UNEVEN		12.798	28' R of C/L		16			
				UO8-11 48x48 16.00 UNEVEN LANES		13.654	28' L of C/L		16			
				WO8-12 48x48 16.00 NO CENTER LINE		13.694	28' L of C/L		16			
				WO8-11 48x48 16.00 UNEVEN LANES		19.431	28' R of C/L		16			
				WO8-11 48x48 16.00 UNEVEN LANES		2.252	28' R of C/L		16			
				WO8-11 48x48 16.00 UNEVEN LANES		2.753	28' L of C/L		16			
				WO8-12 48x48 16.00 NO CENTER LINE		2.816	28' L of C/L		16			
				WO8-11 48x48 16.00 UNEVEN LANES		20.217	28' L of C/L		16			
				WO8-12 48x48 16.00 NO CENTER LINE		20.262	28' L of C/L		16			
				WO8-12 48x48 16.00 NO CENTER		20.453	28' R of C/L		16			
				WO8-11 48x48 16.00 UNEVEN		20.677	28' L of C/L		16			
				WO8-12 48x48 16.00 NO CENTER		20.751	28' L of C/L		16			
				UNS-12 48x48 16.00 NO CENTER		21.846	28' L of C/L		16			
				LINE CONST-8 48x36 12.00 WORK		21.929	28' L of C'L		12			
				ZONE NO PHONE ZONE GO20-1 60x24 10.00 ROAD WORK		21.971	28' L of C/L		10			
				NEXT XX MILES CONST-7-72 72x36 18.00 RATE OUR		22.052	28' L of C/L		18			
				WORK ZONE GO20-2 48x24 8.00 END ROAD		22.052	28' R of C/L		8			
				WORK WO8-12 48x48 16.00 NO CENTER		3.00	28' R of C/L		16			
				WO8-11 48x48 16.00 UNEVEN		3.047	28' R of C/L		16			
				UNES WO8-11 48x48 16.00 UNEVEN		3.317	28' L of C/L		16			
				UNS-12 48x48 16.00 NO CENTER		4.355	28' L of C/L		16			
				LINE								
				WO8-12 48x48 16.00 NO CENTER LINE		4.477	28' R of C/L		16			
				WO8-11 48x48 16.00 UNEVEN LANES		4.522	28' R of C/L		16			
				WO8-11 48x48 16.00 UNEVEN		5.138	28' L of C/L		16			

Revision 4/1/2020 Page 6 of 17



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work. The information below this line are details for Construction Signs (if applicable).

ject	Line Number	DWR Date	Total Quantity Posted For DWR Date		Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Po
520	0120	October 23, 2020	816	LANES									
				WO8-12 LINE	48x48 16.00 NO CENTER		5.178	28' L of C/L		16			
				WO8-11 LANES	48x48 16.00 UNEVEN		5.474	28' R of C/L		16			
				WO8-11 LANES	48x48 16.00 UNEVEN		5.938	28' L of C/L		16			
				WO8-12 LINE	48x48 16.00 NO CENTER		6.421	28' R of C/L		16			
				WO8-11 LANES	48x48 16.00 UNEVEN		6.465	28' R of C/L		16			
				WO8-11 LANES	48x48 16.00 UNEVEN		6.868	28' L of C/L		16			
				WO8-12 LINE	48x48 16.00 NO CENTER		6.986	28' L of C/L		16			
				WO8-12 LINE	48x48 16.00 NO CENTER		7.591	28' L of C/L		16			
				WO8-11 LANES	48x48 16.00 UNEVEN		8.124	28' R of C/L		16			
				WO8-11 LANES	48x48 16.00 UNEVEN		8.535	28' L of C/L		16			
				WO8-12 LINE	48x48 16.00 NO CENTER		8.792	28' R of C/L		16			
				WO8-11 LANES	48x48 16.00 UNEVEN		8.838	28' R of C/L		16			
				WO8-12 LINE	48x48 16.00 NO CENTER		9.598	28' L of C/L		16			
		November 11, 2020		WO8-11 LANES	48x48 16.00 UNEVEN		9.783	28' R of C/L		16			
		November 11, 2020	128	LANES	48x48 16.00 UNEVEN		16.041	25' L of C/L		16			
				LINE	48x48 16.00 NO CENTER		16.152	25' L of C/L		16			
				LANES	48x48 16.00 UNEVEN		16.335	25' R of C/L		16			
				LANES	48x48 16.00 UNEVEN		18.173	25' L of C/L		16			
				WO8-12 LINE	48x48 16.00 NO CENTER		18.263	25' L of C/L		16			
				LINE	48x48 16.00 NO CENTER		18.399	25' R of C/L		16			
				LANES	48x48 16.00 UNEVEN		18.442	25' R of C/L		16			
				LANES	48x48 16.00 UNEVEN		19.286	25' L of C/L		16			
		November 12, 2020	80	LINE	48x48 16.00 NO CENTER		14.037	28' R of C/L		16			
				LINE	48x48 16.00 NO CENTER		15.064	28' L of C/L		16			
				LINE	48x48 16.00 NO CENTER		16.292	28' R of C/L		16			
				LINE	48x48 16.00 NO CENTER		20.829	28' R of C/L		16			
				WO8-12 LINE	48x48 16.00 NO CENTER		7.117	28' R of C/L		16			

Revision 4/1/2020 Page 7 of 17



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0020	MISC. MODIFIED SHAPING SLOPES, CLASS III	Material		6	Nov 16, 2020	SYSTEM	(\$10,080.00)	
				6	Nov 16, 2020	SYSTEM	\$10,080.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				7	Dec 3, 2020	SYSTEM	(\$54,635.00)	
				7	Dec 3, 2020	SYSTEM	\$54,635.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0020 -							\$0.00	
0030	MISC. PERMANENT AGGREGATE EDGE TREATMENT	Material		7	Dec 3, 2020	SYSTEM	(\$119,582.31)	
				7	Dec 3, 2020	SYSTEM	\$119,582.31	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				8	Dec 16, 2020	SYSTEM	(\$119,583.09)	
				8	Dec 16, 2020	SYSTEM	\$119,583.09	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user turnep3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				9	Jan 4, 2021	SYSTEM	(\$119,583.09)	
				9	Jan 4, 2021	SYSTEM	\$119,583.09	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user turnep3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0030 -								
0030 -		Material		7	Dec 3, 2020	SYSTEM	\$0.00	
	Total	Material		7		SYSTEM SYSTEM	\$0.00 \$0.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate.
	Total	Material			2020 Dec 3,		\$0.00 \$0.00 (\$3,689.02)	Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 5 on the current
	Total	Material		7	2020 Dec 3, 2020 Dec 16,	SYSTEM	\$0.00 \$0.00 (\$3,689.02) \$3,689.02	Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 5 on the current
	Total	Material		7	Dec 3, 2020 Dec 16, 2020 Dec 16,	SYSTEM	\$0.00 \$0.00 (\$3,689.02) \$3,689.02	Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 2 on the current
	Total	Material		7 8 8	Dec 3, 2020 Dec 16, 2020 Dec 16, 2020 Jan 4,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,689.02) \$3,689.02 (\$3,689.02)	Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 2 on the current
	Total GRAVEL (A) OR CRUSHED STONE (B)	Material	- Total	7 8 8 9	2020 Dec 3, 2020 Dec 16, 2020 Jan 4, 2021 Jan 4,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,689.02) \$3,689.02 (\$3,689.02) (\$3,689.02)	Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 2 on the current
0040	GRAVEL (A) OR CRUSHED STONE (B)	Material	- Total	7 8 8 9	2020 Dec 3, 2020 Dec 16, 2020 Dec 16, 2020 Jan 4, 2021 Jan 4,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,689.02) \$3,689.02 (\$3,689.02) \$3,689.02 (\$3,689.02) \$3,689.02	Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 2 on the current
0040	Total GRAVEL (A) OR CRUSHED STONE (B) Material - Total Total		- Total	7 8 8 9 9	2020 Dec 3, 2020 Dec 16, 2020 Dec 16, 2020 Jan 4, 2021 Jan 4, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,689.02) \$3,689.02 (\$3,689.02) \$3,689.02 \$3,689.02 \$0.00 \$0.00	Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 2 on the current
0040	GRAVEL (A) OR CRUSHED STONE (B)	Material Material	- Total	7 8 8 9	2020 Dec 3, 2020 Dec 16, 2020 Dec 16, 2020 Jan 4, 2021 Jan 4,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,689.02) \$3,689.02 (\$3,689.02) \$3,689.02 (\$3,689.02) \$3,689.02	Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 2 on the current
0040	GRAVEL (A) OR CRUSHED STONE (B) Material - Total Total BITUMINOUS PAVEMENT MIXTURE		- Total	7 8 8 9 9	2020 Dec 3, 2020 Dec 16, 2020 Dec 16, 2020 Jan 4, 2021 Jan 4, 2021 Oct 1,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,689.02) \$3,689.02 (\$3,689.02) \$3,689.02 \$3,689.02 \$0.00 \$0.00	Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 2 on the current
0040	GRAVEL (A) OR CRUSHED STONE (B) Material - Total Total BITUMINOUS PAVEMENT MIXTURE		- Total	7 8 8 9 9	2020 Dec 3, 2020 Dec 16, 2020 Dec 16, 2020 Jan 4, 2021 Jan 4, 2021 Oct 1, 2020 Oct 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,689.02) \$3,689.02 (\$3,689.02) \$3,689.02 (\$3,689.02) \$0.00 \$0.00 \$0.00 (\$734,432.03)	Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.

Revision 4/1/2020 Page 8 of 17



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
0050	BITUMINOUS PAVEMENT MIXTURE	Material	Турс					Payment Estimate.		
	PG64-22, (BP-1)			5	Nov 2, 2020	SYSTEM	(\$734,432.03)			
				5	Nov 2, 2020	SYSTEM	\$734,432.03	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.		
				6	Nov 16, 2020	SYSTEM	(\$1,495,517.54)			
				6	Nov 16, 2020	SYSTEM	\$1,495,517.54	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.		
				7	Dec 3, 2020	SYSTEM	(\$1,495,517.54)			
				7	Dec 3, 2020	SYSTEM	\$1,495,517.54	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 6 on the current Payment Estimate.		
				8	Dec 16, 2020	SYSTEM	(\$1,495,522.62)			
				8	Dec 16, 2020	SYSTEM	\$1,495,522.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.		
				9	Jan 4, 2021	SYSTEM	(\$1,495,522.62)			
				9	Jan 4, 2021	SYSTEM	\$1,495,522.62	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.		
					10	Jan 19, 2021	SYSTEM	(\$1,495,522.62)		
				10	Jan 19, 2021	SYSTEM	\$1,495,522.62	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user turnep3 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
				11	Feb 2, 2021	SYSTEM	(\$1,495,522.62)			
						11	Feb 2, 2021	SYSTEM	\$1,495,522.62	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user turnep3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				12	Feb 16, 2021	SYSTEM	(\$1,495,522.62)			
				12	Feb 16, 2021	SYSTEM	\$1,495,522.62	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user turnep3 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
				13	Mar 2, 2021	SYSTEM	(\$1,495,522.62)			
				13	Mar 2, 2021	SYSTEM	\$1,495,522.62	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user turnep3 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
				14	Mar 16, 2021	SYSTEM	(\$648,322.62)			
				14	Mar 16, 2021	SYSTEM	\$648,322.62	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user turnep3 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
			- Total				\$0.00			
	Material - Total						\$0.00			
	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Other Item Adjustment	ACAD		Sep 16, 2020	turnep3	(\$9,731.85)	AC Index Price Adjustment: -\$9,731.85		
				3	Oct 1, 2020	turnep3	(\$20,988.69)	AC Index Price Adjustment: -\$20,988.69		
				6	Nov 16, 2020	turnep3	(\$34,193.60)	Asphalt Index Price Adjustment: -\$34,193.60		

Revision 4/1/2020 Page 9 of 17



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0050		Other Item	ACAD - Tot	al			(\$64,914.14)	
	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Adjustment	FUEL		Dec 16, 2020	turnep3	\$0.02	Correction of Fuel Price adjustment due to rounding BP-1 totals.
			FUEL - Tota	ıl			\$0.02	
	Other Item Adjustment - Total						(\$64,914.12)	
	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Overrun	Overrun	6	Nov 16, 2020	SYSTEM	(\$21,855.70)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				6	Nov 16, 2020	SYSTEM	\$21,855.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) overridding Payment Estimate Exception 6 on the current Payment Estimate.
				7	Dec 3, 2020	SYSTEM	(\$21,881.39)	Averaged Price Adjustment from this item on all previous payment estimates of '-0.93078' is applied (if non-zero).
				7	Dec 3, 2020	SYSTEM	\$21,881.39	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 11 on the current Payment Estimate.
				8	Dec 16, 2020	SYSTEM	(\$21,881.39)	Averaged Price Adjustment from this item on all previous payment estimates of '-0.93078' is applied (if non-zero).
				8	Dec 16, 2020	SYSTEM	(\$5.07)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				8	Dec 16, 2020	SYSTEM	\$5.07	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 10 on the current Payment Estimate.
				8	Dec 16, 2020	SYSTEM	\$21,881.39	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 10 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Price		2	Sep 16, 2020	SYSTEM	(\$3,555.78)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				3	Oct 1, 2020	SYSTEM	(\$7,668.76)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				6	Nov 16, 2020	SYSTEM	(\$13,421.40)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				8	Dec 16, 2020	SYSTEM	(\$0.02)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			- Total				(\$24,645.96)	
	Price - Total						(\$24,645.96)	
0050	- Total						(\$89,560.08)	
0060	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Material		4	Oct 16, 2020	SYSTEM	(\$831,265.85)	
				4	Oct 16, 2020	SYSTEM	\$831,265.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				5	Nov 2, 2020	SYSTEM	(\$2,367,981.98)	
				5	Nov 2, 2020	SYSTEM	\$2,367,981.98	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				6	Nov 16, 2020	SYSTEM	(\$2,367,981.98)	
				6	Nov 16, 2020	SYSTEM	\$2,367,981.98	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user turnep3 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				7	Dec 3, 2020	SYSTEM	(\$2,367,981.98)	
				7	Dec 3, 2020	SYSTEM	\$2,367,981.98	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user turnep3 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				8	Dec 16, 2020	SYSTEM	(\$2,367,983.92)	
				8	Dec 16, 2020	SYSTEM	\$2,367,983.92	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user turnep3

Revision 4/1/2020 Page 10 of 17



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
		Туре	Adjustment Type	Number	Date	Ву		
0060	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Material						overridding Payment Estimate Exception 4 on the current Payment Estimate.
				9	Jan 4, 2021	SYSTEM	(\$2,367,983.92)	
				9	Jan 4, 2021	SYSTEM	\$2,367,983.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				10	Jan 19, 2021	SYSTEM	(\$2,367,983.92)	
				10	Jan 19, 2021	SYSTEM	\$2,367,983.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				11	Feb 2, 2021	SYSTEM	(\$2,367,983.92)	
				11	Feb 2, 2021	SYSTEM	\$2,367,983.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				12	Feb 16, 2021	SYSTEM	(\$2,367,983.92)	
				12	Feb 16, 2021	SYSTEM	\$2,367,983.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				13	Mar 2, 2021	SYSTEM	(\$2,367,983.92)	
				13	Mar 2, 2021	SYSTEM	\$2,367,983.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				14	Mar 16, 2021	SYSTEM	(\$2,367,983.92)	
				14	Mar 16, 2021	SYSTEM	\$2,367,983.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total	Other Item	ACAD	4	Oat 16	tummam?	\$0.00	AC Index Drice Adjustments #20003.25
	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Other Item Adjustment	ACAD	4	Oct 16, 2020	turnep3	(\$28,623.35)	AC Index Price Adjustment: -\$28623.35 Calculated by hand using appropriate indexes. AC Index spreadsheet did not include index for October 2020, but value was given in index list on MoDOT website.
				5	Nov 2, 2020	turnep3	(\$52,914.44)	AC Index Price Adjustment: -\$52914.44
			ACAD - Tota	al			(\$81,537.79)	
	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)		FUEL	5	Nov 2, 2020	turnep3	(\$25,237.40)	Fuel Price Adjustment: -\$25237.40
				6	Nov 16, 2020	turnep3	\$25,237.40	Correction for double adjustment of Fuel Price Adjustment on Estimate 0005: \$25,237.40
				8	Dec 16, 2020	turnep3	\$0.01	Correction of Fuel Price adjustment due to rounding SP125 totals.
			FUEL - Tota	ıl			\$0.01	
	Other Item Adjustment - Total						(\$81,537.78)	
	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Price		4	Oct 16, 2020	SYSTEM	(\$13,651.84)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				5	Nov 2, 2020	SYSTEM	(\$25,237.40)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				8	Dec 16, 2020	SYSTEM	(\$0.01)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			- Total				(\$38,889.25)	
	Price - Total						(\$38,889.25)	
0060 -	Total						(\$120,427.03)	
0070	TACK COAT	Material		1	Sep 2, 2020	SYSTEM	(\$78.00)	

Revision 4/1/2020 Page 11 of 17



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
		Туре	Adjustment Type	Number	Date	Ву		
0070	TACK COAT	Material		1	Sep 2, 2020	SYSTEM	\$78.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user turnep3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				2	Sep 16, 2020	SYSTEM	(\$9,036.00)	
				2	Sep 16, 2020	SYSTEM	\$9,036.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				3	Oct 1, 2020	SYSTEM	(\$22,768.00)	
				3	Oct 1, 2020	SYSTEM	\$22,768.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	TACK COAT	Overrun	Overrun	6	Nov 16, 2020	SYSTEM	(\$382.00)	
				6	Nov 16, 2020	SYSTEM	\$382.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user turnep3 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				7	Dec 3, 2020	SYSTEM	(\$382.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				7	Dec 3, 2020	SYSTEM	\$382.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user turnep3 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				8	Dec 16, 2020	SYSTEM	(\$382.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				8	Dec 16, 2020	SYSTEM	\$382.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Exception 11 on the current Payment Estimate.
			Overrun - To	otal			\$0.00	
	Overrun - Total						\$0.00	
0070 -	Total						\$0.00	
0800	BITUMINOUS FOG SEAL	Material		7	Dec 3, 2020	SYSTEM	(\$15,542.28)	
				7	Dec 3, 2020	SYSTEM	\$15,542.28	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Exception 8 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0080 -							\$0.00	
0090	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	Other Item Adjustment	OADJ		Dec 16, 2020	turnep3	(\$1,000.00)	Removal of previous line item adjustment for overrun of 2 TMAs. Change Order has been submitted and is awaiting approval.
				9	Jan 4, 2021	turnep3	(\$1,000.00)	Removing the \$1000 automatic overrun adjustment. Change Order 0003 has been submitted and approved which included overrun adjustment for 2 additional TMAs.
			OADJ - Tota				(\$2,000.00)	
	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)		OTHR		Jan 19, 2021	turnep3	\$1,000.00	This adjustment ensures full payment for Line 0090: TMAs, and zeroes any previous adjustments.
			OTHR - Tota	al			\$1,000.00	
	Other Item Adjustment - Total						(\$1,000.00)	
	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	Overrun	Overrun	7	Dec 3, 2020	SYSTEM	(\$1,000.00)	
				7	Dec 3, 2020	turnep3	\$1,000.00	Due to additional TMAs required for Striping and Rumble Strips operations, \$1000 was adjusted for the 2 additional TMAs (\$500 per EA) until a Change Order correcting the quantity is submitted.
				9	Jan 4, 2021	SYSTEM	\$1,000.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',500.00000 - 500.00000, 'is applied (if non-zero).

Revision 4/1/2020 Page 12 of 17



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
0090		Overrun	Overrun - T	otal			\$1,000.00					
	Overrun - Total						\$1,000.00					
0090 -	Total						\$0.00					
0100	FURNISHING AND PLACING	Material		1	Sep 2,	SYSTEM	(\$6,206.32)					
	BITUMINOUS MATERIAL FOR CLASS C				2020		, ,					
	PARTIAL DEPTH PAVEMENT REPAIR			1	Sep 2, 2020	SYSTEM	\$6,206.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.				
				2	Sep 16, 2020	SYSTEM	(\$6,206.32)					
				2	Sep 16, 2020	SYSTEM	\$6,206.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.				
								3	Oct 1, 2020	SYSTEM	(\$6,206.32)	
				3	Oct 1, 2020	SYSTEM	\$6,206.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.				
				4	Oct 16, 2020	SYSTEM	(\$57,433.91)					
				4	Oct 16, 2020	SYSTEM	\$57,433.91	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.				
				5	Nov 2, 2020	SYSTEM	(\$57,433.91)					
								5	Nov 2, 2020	SYSTEM	\$57,433.91	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user turnep3 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					6	Nov 16, 2020	SYSTEM	(\$57,433.91)				
					6	Nov 16, 2020	SYSTEM	\$57,433.91	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate.			
									7	Dec 3, 2020	SYSTEM	(\$57,433.91)
				7	Dec 3, 2020	SYSTEM	\$57,433.91	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user turnep3 overridding Payment Estimate Exception 9 on the current Payment Estimate.				
			- Total				\$0.00					
	Material - Total						\$0.00					
	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	Other Item Adjustment	ACAD	1	Sep 2, 2020	turnep3	(\$80.21)	AC Price Index Adjustment: -\$80.21				
	PARTIAL DEPTH PAVEMENT REPAIR			4	Oct 16, 2020	turnep3	(\$662.28)	AC Index Price Adjustment: -\$662.28 Calculated according to index appropriate for when the work was performed (9/9/2020).				
			ACAD - Total	al			(\$742.49)					
	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C		FUEL		Sep 2, 2020	turnep3	(\$34.67)	Asphalt Paving Production and Hauling Fuel Adjustment: - \$34.67				
	PARTIAL DEPTH PAVEMENT REPAIR			4	Oct 16,	turnep3	(\$256.65)	Fuel Price Adjustment: -\$256.65				
					2020			Calculated according to index appropriate for when the work was performed (9/9/2020).				
			FUEL - Tota	ıl			(\$291.32)					
	Other Item Adjustment - Total						(\$1,033.81)					
	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C	Overrun	Overrun	4	Oct 16, 2020	SYSTEM	(\$4,487.99)					
	PARTIAL DEPTH PAVEMENT REPAIR			4	Oct 16, 2020	SYSTEM	\$4,487.99	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) overridding Payment Estimate Exception 4 on the current Payment Estimate.				
				5	Nov 2,	SYSTEM	(\$4,487.99)	Averaged Price Adjustment from this item on all previous				

Revision 4/1/2020 Page 13 of 17



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																
0100	FURNISHING AND PLACING	Overrun	Overrun		2020			payment estimates of '0.00000' is applied (if non-zero).																
	BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR			5	Nov 2, 2020	SYSTEM	\$4,487.99	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) overridding Payment Estimate Exception 5 on the current Payment Estimate.																
				6	Nov 16, 2020	SYSTEM	(\$4,487.99)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).																
				6	Nov 16, 2020	SYSTEM	\$4,487.99	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) overridding Payment Estimate Exception 8 on the current Payment Estimate.																
				7	Dec 3, 2020	SYSTEM	(\$4,487.99)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).																
				7	Dec 3, 2020	SYSTEM	\$4,487.99	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) overridding Payment Estimate Exception 14 on the current Payment Estimate.																
				8	Dec 16, 2020	SYSTEM	(\$4,487.99)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).																
				8	Dec 16, 2020	SYSTEM	(\$10.34)																	
				8	Dec 16, 2020	SYSTEM	\$10.34	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user turnep3 overridding Payment Estimate Exception 13 on the current Payment Estimate.																
				8	Dec 16, 2020	SYSTEM	\$4,487.99	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user turnep3 overridding Payment Estimate Exception 13 on the current Payment Estimate.																
			Overrun - T	otal			\$0.00																	
	Overrun - Total						\$0.00																	
0100 -	Total						(\$1,033.81)																	
0110	REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	Overrun	Overrun	2	Sep 16, 2020	SYSTEM	(\$1,408.43)																	
				2	Sep 16, 2020	SYSTEM	\$1,408.43	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.																
				3	Oct 1, 2020	SYSTEM	(\$1,408.43)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).																
				3	Oct 1, 2020	SYSTEM	\$1,408.43	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user turnep3 overridding Payment Estimate Exception 4 on the current Payment Estimate.																
				4	Oct 16, 2020	SYSTEM	(\$1,408.43)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).																
				4	Oct 16, 2020	SYSTEM	\$1,408.43	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate.																
				5	Nov 2, 2020	SYSTEM	(\$1,408.43)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).																
				5	Nov 2, 2020	SYSTEM	\$1,408.43	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user turnep3 overridding Payment Estimate Exception 6 on the current Payment Estimate.																
				6	Nov 16, 2020	SYSTEM	(\$1,408.43)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).																
																				6	Nov 16, 2020	SYSTEM	\$1,408.43	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user turnep3 overridding Payment Estimate Exception 9 on the current Payment Estimate.
								7	Dec 3, 2020	SYSTEM	(\$1,408.43)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).												
				7	Dec 3, 2020	SYSTEM	\$1,408.43	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user turnep3 overridding Payment Estimate Exception 15 on the current Payment Estimate.																
			Overrun - T	otal			\$0.00																	
	Overrun - Total						\$0.00																	
0110 -	Total						\$0.00																	

Revision 4/1/2020 Page 14 of 17



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0120	CONSTRUCTION SIGNS	Material		1	Sep 2, 2020	SYSTEM	(\$480.00)	
				1	Sep 2, 2020	SYSTEM	\$480.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0120 -	Total						\$0.00	
0150	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR	Material		1	Sep 2, 2020	SYSTEM	(\$5,600.00)	
	FURNISHED, CONTRACTOR RETAINED			1	Sep 2, 2020	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0150 -	Total						\$0.00	
0170	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material		7	Dec 3, 2020	SYSTEM	(\$7,120.00)	
				7	Dec 3, 2020	SYSTEM	\$7,120.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user turnep3 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				8	Dec 16, 2020	SYSTEM	(\$8,280.00)	
				8	Dec 16, 2020	SYSTEM	\$8,280.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user turnep3 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				9	Jan 4, 2021	SYSTEM	(\$8,280.00)	
				9	Jan 4, 2021	SYSTEM	\$8,280.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user turnep3 overridding Payment Estimate Exception 7 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0170 -	Total						\$0.00	
0180	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	Material		8	Dec 16, 2020	SYSTEM	(\$7,800.00)	
				8	Dec 16, 2020	SYSTEM	\$7,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user turnep3 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				9	Jan 4, 2021	SYSTEM	(\$7,800.00)	
				9	Jan 4, 2021	SYSTEM	\$7,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 8 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0180 -	Total						\$0.00	
0190	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT	Material		8	Dec 16, 2020	SYSTEM	(\$3,640.00)	
	ARROW			8	Dec 16, 2020	SYSTEM	\$3,640.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user turnep3 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				9	Jan 4, 2021	SYSTEM	(\$3,640.00)	
				9	Jan 4, 2021	SYSTEM	\$3,640.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user turnep3 overridding Payment Estimate Exception 9 on the current Payment Estimate.
	on 4/1/2020		- Total				\$0.00	Page 15 of 1

Revision 4/1/2020 Page 15 of 17



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0190	Material - Total		, , , , , , , , , , , , , , , , , , ,				\$0.00	
	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Overrun	Overrun	8	Dec 16, 2020	SYSTEM	(\$560.00)	
				8	Dec 16, 2020	SYSTEM	\$560.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) overridding Payment Estimate Exception 14 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0190 -	·Total						\$0.00	
0230	MISC. PREFORMED THERMOPLASTIC PAVEMENT MARKING, LANE REDUCTION ARROW	Material		8	Dec 16, 2020	SYSTEM	(\$4,000.00)	
				8	Dec 16, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user turnep3 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				9	Jan 4, 2021	SYSTEM	(\$4,000.00)	
				9	Jan 4, 2021	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user turnep3 overridding Payment Estimate Exception 10 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0230 -	· Total						\$0.00	
0250	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	Overrun	Overrun	11	Feb 2, 2021	SYSTEM	(\$4,770.40)	
				11	Feb 2, 2021	SYSTEM	\$4,770.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0250 -	·Total						\$0.00	
0280	MGS GUARDRAIL	Construction Stockpile		2	Sep 16, 2020	SYSTEM	\$21,339.36	Payment Estimate Item Adjustment generated Stockpile Transaction
				6	Nov 16, 2020	SYSTEM	(\$3,690.56)	Payment Estimate Item Adjustment generated Stockpile Transaction
				7	Dec 3, 2020	SYSTEM	(\$13,910.55)	Payment Estimate Item Adjustment generated Stockpile Transaction
				14	Mar 16, 2021	SYSTEM	(\$3,738.25)	Payment Estimate Item Adjustment generated Stockpile Transaction
	- Total						\$0.00	
0000	Construction Stockpile - Total						\$0.00	
0280 -	MGS BRIDGE APPROACH TRANSITION	Construction Stockpile		2	Sep 16, 2020	SYSTEM	\$0.00 \$29,200.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				6	Nov 16, 2020	SYSTEM	(\$3,244.44)	Payment Estimate Item Adjustment generated Stockpile Transaction
				7	Dec 3, 2020	SYSTEM	(\$25,955.56)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
0290 -	· Total						\$0.00	
0300	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		2	Sep 16, 2020	SYSTEM	\$38,766.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				6	Nov 16, 2020	SYSTEM	(\$6,626.67)	Payment Estimate Item Adjustment generated Stockpile Transaction
				7	Dec 3, 2020	SYSTEM	(\$28,163.33)	Payment Estimate Item Adjustment generated Stockpile Transaction
				14	Mar 16, 2021	SYSTEM	(\$3,976.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	

Revision 4/1/2020 Page 16 of 17



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0300	Construction Stockpile - Total					\$0.00		
0300 -	- Total					\$0.00		
5001	ADVANCED WARNING RAIL SYSTEM	Material		8	Dec 16, 2020	SYSTEM	(\$70.00)	
				8	Dec 16, 2020	SYSTEM	\$70.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				9	Jan 4, 2021	SYSTEM	(\$70.00)	
				9	Jan 4, 2021	SYSTEM	\$70.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Exception 6 on the current Payment Estimate.
	- Total						\$0.00	
	Material - Total				\$0.00			
5001 -	- Total				\$0.00			
Overa	all - Total				(\$211,020.92)			

Revision 4/1/2020 Page 17 of 17