

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: April 16, 2021

Progress Estimate Number	Contract ID	200320-H04	Pay Period Start April 2, 2021	Original Contract Amount	\$4,898,461.04
16	Prime Contracto	or Capital Paving & Construction, LLC	Pay Period End April 15, 202	1 Net Change Order Amount Current Contract Amount	(' '
				Current Contract Amount	\$4,004,049.39

Approval Date		By User
April 16, 2021	Generated and Approved (and should be considered Draft) at the Project Office Level by	turnep3
April 16, 2021	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	wilkem1
April 19, 2021	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
November 1, 2020	November 25, 2020	March 4, 2021	98.77%

	Contract Informational Dat	es	Milestones
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract
Acceptance Date			
Awarded Date	April 1, 2020	April 1, 2020	
Letting Date	March 20, 2020	March 20, 2020	
Notice to Proceed Date	June 1, 2020	June 1, 2020	
Open to Traffic Date			
Work Began Date	August 31, 2020	August 31, 2020	

Contract Total Page	y For Estimate No. 16				
		This Estimate	Previous	To Date	
200320-H04					
	Total Posted Items Pay	\$2,551.74	\$4,821,902.50	\$4,824,454.24	
	Gross Item Adjustments	\$0.00	(\$211,020.92)	(\$211,020.92)	
	Incentive	\$0.00	\$265,776.09	\$265,776.09	
	Disincentive	\$0.00	(\$4,794.39)	(\$4,794.39)	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	(\$2,231.68)	(\$2,231.68)	
	•		\$4,869,631.60	\$4,872,183.34	
Contract Total Pag	yable This Estimate:	\$2,551.74			

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit Unit Price		Current Installed Qty	Current Installed Amount
J9P3520	0120	6161005	CONSTRUCTION SIGNS	SQFT	\$5.000	348	\$1,740.00
	5003	5003 6207001 PAVEMENT MARKING REMOVAL		LF	\$0.830	978	\$811.74
Project J9P3520 -	Total						\$2,551.74
Overall - Total							\$2,551.74

Contract Adjustments This Estimate

		ments Exist on Contract ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9P3520	0050	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Material			-11,478.8	\$56.48	(\$648,322.62)
	0050	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user turnep3 overridding Payment Estimate Exception 1 on the current Payment Estimate.	11,478.8	\$56.48	\$648,322.62
	0060	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Material			-36,605.1	\$64.69	(\$2,367,983.92)
	0060	ASPHALTIC CONCRETE Material MIXTURE PG 70-22 (SP125C MIX)			This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.	36,605.1	\$64.69	\$2,367,983.92
Total								\$0.00

Revision 4/1/2020 Page 1 of 15



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Information	
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J9P3520	FAF 412-1(17)	Resurface	412	DUNKLIN	from end of divided highv	vay to Route VV	
Γotals by J	Job Numbe	rs					
J9P3520	Poste	d Item Pay			This Estimate \$2,551.74	Previous \$4,821,902.50	To Date \$4,824,454.24
		Item Adjustme		Item Pay	\$0.00 \$2,551.74	(\$211,020.92) \$4,610,881.58	(\$211,020.92) \$4,613,433.32
	Incent				\$0.00	\$265,776.09	\$265,776.09
	Dising Liquid	entive lated Damages	i		\$0.00 \$0.00	(\$4,794.39) \$0.00	(\$4,794.39) \$0.00
	Other	Contract Adjus	etmonte		\$0.00	(\$2,231.68)	(\$2,231.68)

Revision 4/1/2020 Page 2 of 15



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J9P3520, Item 4011209, Project Item Line Number 0050, Material Set 401120996, Material 0401BPPMBP1 - Plant Mix for Bit Pavement BP-1, Acceptance Action Generic AspLow is insufficient.	Awaiting resolution of issues with QC testing.	turnep3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3520, Item 4030103, Project Item Line Number 0060, Material Set 403010396, Material 0403SP125CLG - Superpave 12.5 mm, Des C 80 Gyros, Acceptance Action Generic AspHigh is insufficient.	Awaiting resolution of issues with QC testing.	turnep3	Overridden

Revision 4/1/2020 Page 3 of 15



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

ntract NTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
-H04	J9P3520	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$16,064.79	\$16,064.79
		0001	0020	2159903	MISC.MODIFIED SHAPING SLOPES, CLASS III	4,918.00	-75.50	4,842.50	LF	4,842.50	\$14.00	\$67,795.00
		0001	0030	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	4,090.90	-395.60	3,695.30	TONS	3,695.30	\$38.68	\$142,934.2
		0001	0040	3105002	GRAVEL (A) OR CRUSHED STONE (B)	134.00	0.00	134.00	TONS	134.00	\$27.53	\$3,689.0
		0001	0050	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	26,084.80	394.00	26,478.80	TONS	26,478.80	\$56.48	\$1,495,522.6
		0001	0060	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	37,345.50	-740.40	36,605.10	TONS	36,605.10	\$64.69	\$2,367,983.9
		0001	0070	4071005	TACK COAT	50,915.00	191.00	51,106.00	GAL	51,106.00	\$2.00	\$102,212.0
		0001	0080	4134000	BITUMINOUS FOG SEAL	18,233.00	-10,937.00	7,296.00	GAL	7,296.00	\$2.34	\$17,072.6
		0001	0090	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	2.00	4.00	EA	4.00	\$500.00	\$2,000.0
		0001	0100	6133020	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	307.20	26.10	333.30	TONS	333.30	\$172.35	\$57,444.2
		0001	0110	6133021	REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	1,806.10	105.50	1,911.60	SQYD	1,911.60	\$13.35	\$25,519.8
		0001	0120	6161005	CONSTRUCTION SIGNS	3,547.00	0.00	3,547.00	SQFT	2,627.00	\$5.00	\$13,135.0
		0001	0130	6161009	FLAG ASSEMBLY	6.00	0.00	6.00	EA	6.00	\$20.00	\$120.0
		0001	0140	6161025	CHANNELIZER (TRIM LINE)	110.00	0.00	110.00	EA	110.00	\$20.00	\$2,200.0
		0001	0150	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$2,800.00	\$5,600.0
		0001	0160	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$118,630.47	\$118,630.4
		0001	0170	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	429.00	-15.00	414.00	LF	414.00	\$20.00	\$8,280.0
		0001	0180	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	425.00	-35.00	390.00	LF	390.00	\$20.00	\$7,800.0
		0001	0190	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	11.00	2.00	13.00	EA	13.00	\$280.00	\$3,640.0
		0001	0200	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	63,365.00	0.00	63,365.00	LF	0.00	\$0.15	\$0.0
		0001	0210	6205902A	$\boldsymbol{6}$ IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	229,952.00	0.00	229,952.00	LF	0.00	\$0.20	\$0.0
		0001	0220	6209901	MISC.TEMPORARY PAVEMENT MARKING PAINT	1.00	0.00	1.00	LS	0.00	\$0.00	\$0.0
		0001	0230	6209902	MISC.PREFORMED THERMOPLASTIC PAVEMENT MARKING, LANE REDUCTION ARROW	2.00	0.00	2.00	EA	2.00	\$2,000.00	\$4,000.0
		0001	0240	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	27,934.00	-1,242.00	26,692.00	SQYD	26,692.00	\$1.23	\$32,831.1
		0001	0250	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	9,730.00	890.00	10,620.00	SQYD	10,620.00	\$5.36	\$56,923.2
		0001	0260	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	1,914.00	0.00	1,914.00	STA	1,914.00	\$15.50	\$29,667.0
		0001	0270	6261001	BITUMINOUS CENTERLINE RUMBLE STRIP	941.00	0.00	941.00	STA	941.00	\$15.50	\$14,585.5
		0010	0280	6061060	MGS GUARDRAIL	2,088.00	-138.00	1,950.00	LF	1,950.00	\$24.00	\$46,800.0
		0010	0290	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	20.00	3.00	23.00	EA	23.00	\$3,050.00	\$70,150.0
		0010	0300	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	26.00	-1.00	25.00	EA	25.00	\$2,850.00	\$71,250.0
		0001	5001	6161008	ADVANCED WARNING RAIL SYSTEM	0.00	2.00	2.00	EA	2.00	\$35.00	\$70.0
		0010	5002	6069901	MISC.Misc. Guardrail Item: Box Culvert Thrie Beam	0.00	1.00	1.00	LS	1.00	\$39,721.86	\$39,721.8
		0001	5003	6207001	PAVEMENT MARKING REMOVAL	0.00	978.00	978.00	LF	978.00	\$0.83	\$811.7
	Project J	9P3520 - To	otal Value	Posted to D	ate as of Report Generated Date							\$4,824,454.2
-H04 Ove	erall - Total	Value Post	ted to Da	te as of Repo	ort Generated Date							\$4,824,454

Page 4 of 15 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J9P3520

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0120	6161005	CONSTRUCTION SIGNS	4/15/21	4/16/21	163.00	SQFT	2 Shoulder Work Ahead Signs: 2 * 16 sqft = 32 sqft 4 Pilot Carin Use Walt & Follow Signs: 4 * 8.75 sqft = 35 sqft 6 Be Prepared to Stop Signs: 6 * 16 sqft = 96 sqft Total: 163 sqft	0.835	RLC	22.055	RLC	
				4/16/21	185.00	SQFT	Correction for sign quantities paid at Bridges: F0956: 37 sqft paid corrected to 74 sqft A1399: 37 sqft paid corrected to 74 sqft A1400: 37 sqft paid corrected to 74 sqft A1207: 37 sqft paid corrected to 74 sqft A1206: 37 sqft paid corrected to 74 sqft	0.835	RLC	22.055	RLC	
5003	6207001	PAVEMENT MARKING REMOVAL	4/15/21	4/16/21	978.00	LF	Pavement Marking Removal of 24" Thermoplastic Pavement Markings between Routes A and O/Y	20.398	LOC	20.780	LOC	

The information below this line are details for Construction Signs (if applicable). Station Log Mile Location Project Line Number DWR Date Total Quantity Posted For DWR Date Sign Information Number of Items SF Each Sign Special Sign SF Each Special Sign Total SF to Post J9P3520 0120 October 23, 2020 GO20-2 48x24 8.00 END ROAD WORK .833 28' L of C/L CONST-7-72 72x36 18.00 RATE OUR WORK ZONE GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES .97 28' R of C/L 10 CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE 1.033 28' R of C/L 12 WO8-12 48x48 16.00 NO CENTER LINE 28' R of C/L WO8-11 48x48 16.00 UNEVEN LANES 28' R of C/L 16 WO8-11 48x48 16.00 UNEVEN LANES 1.82 28' L of C/L 16 WO8-11 48x48 16.00 UNEVEN LANES 28' L of C/L 16 WO8-12 48x48 16.00 NO CENTER 10.731 28' R of C/L 48x48 16.00 UNEVEN 16 28' L of C/L 16 48x48 16.00 UNEVEN WO8-12 48x48 16.00 NO CENTER LINE 11.614 28' L of C/L 16 WO8-12 48x48 16.00 NO CENTER LINE 11.731 28' R of C/L 28' R of C/L 16 WO8-11 48x48 16.00 UNEVEN LANES 11.791 48x48 16.00 UNEVEN 28' L of C/L 16 WO8-11 48x48 16.00 UNEVEN LANES 12.798 28' R of C/L 16 WO8-11 48x48 16.00 UNEVEN LANES 13.654 28' L of C/L 16 WO8-12 48x48 16.00 NO CENTER LINE 16 WO8-11 48x48 16.00 UNEVEN LANES 16 19.431 28' R of C/L WO8-11 48x48 16.00 UNEVEN LANES 28' R of C/L 16 2.252 WO8-11 48x48 16.00 UNEVEN LANES 2.753 28' L of C/L 16 WO8-12 48x48 16.00 NO CENTER LINE 2.816 28' L of C/L 16 WO8-11 48x48 16.00 UNEVEN LANES 28' L of C/L 16 20.217 16 WO8-12 48x48 16.00 NO CENTER LINE 20.262 28' L of C/L WO8-12 48x48 16.00 NO CENTER LINE 20.453 28' R of C/L 16 WO8-11 48x48 16.00 UNEVEN LANES 20.677 28' L of C/L 16 WO8-12 48x48 16.00 NO CENTER LINE 28' L of C/L 16 20.751 WO8-12 48x48 16.00 NO CENTER LINE 16 21.846 28' L of C/L CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE 12 28' L of C'L 21.929 GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES 21.971 28' L of C/L 10 CONST-7-72 72x36 18.00 RATE OUR WORK ZONE 28' L of C/L 18 22.052 GO20-2 48x24 8.00 END ROAD WORK 22.052 28' R of C/L WO8-12 48x48 16.00 NO CENTER LINE 16 3.00 28' R of C/L WO8-11 48x48 16.00 UNEVEN LANES 16 3.047 28' R of C/L WO8-11 48x48 16.00 UNEVEN LANES 3.317 28' L of C/L 16 16 WO8-12 48x48 16.00 NO CENTER LINE 4.355 28' L of C/L WO8-12 48x48 16.00 NO CENTER LINE 4.477 28' R of C/L 16 WO8-11 48x48 16.00 UNEVEN LANES 28' R of C/L 16 4.522 WO8-11 48x48 16.00 UNEVEN LANES 5.138 28' L of C/L 16 WO8-12 48x48 16.00 NO CENTER 28' L of C/I 16 5 178

Revision 4/1/2020 Page 5 of 15



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line are details for Construction Stone (if applicable).

Line Number	DWR Date	Total Quantity Posted For DWR Date		Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Po
0120	October 23, 2020	816	WO8-11 LANES	48x48 16.00 UNEVEN		5.474	28' R of C/L		16			
			WO8-11 LANES	48x48 16.00 UNEVEN		5.938	28' L of C/L		16			
			WO8-12 LINE	48x48 16.00 NO CENTER		6.421	28' R of C/L		16			
			WO8-11 LANES	48x48 16.00 UNEVEN		6.465	28' R of C/L		16			
			WO8-11 LANES	48x48 16.00 UNEVEN		6.868	28' L of C/L		16			
			WO8-12 LINE	48x48 16.00 NO CENTER		6.986	28' L of C/L		16			
			WO8-12 LINE	48x48 16.00 NO CENTER		7.591	28' L of C/L		16			
			WO8-11 LANES	48x48 16.00 UNEVEN		8.124	28' R of C/L		16			
			WO8-11 LANES	48x48 16.00 UNEVEN		8.535	28' L of C/L		16			
			WO8-12 LINE	48x48 16.00 NO CENTER		8.792	28' R of C/L		16			
			WO8-11 LANES	48x48 16.00 UNEVEN		8.838	28' R of C/L		16			
			WO8-12 LINE	48x48 16.00 NO CENTER		9.598	28' L of C/L		16			
			WO8-11 LANES	48x48 16.00 UNEVEN		9.783	28' R of C/L		16			
	November 11, 2020	128	WO8-11 LANES	48x48 16.00 UNEVEN		16.041	25' L of C/L		16			
			WO8-12 LINE	48x48 16.00 NO CENTER		16.152	25' L of C/L		16			
			WO8-11 LANES	48x48 16.00 UNEVEN		16.335	25' R of C/L		16			
			WO8-11 LANES	48x48 16.00 UNEVEN		18.173	25' L of C/L		16			
			WO8-12 LINE	48x48 16.00 NO CENTER		18.263	25' L of C/L		16			
			WO8-12 LINE	48x48 16.00 NO CENTER		18.399	25' R of C/L		16			
			WO8-11 LANES	48x48 16.00 UNEVEN		18.442	25' R of C/L		16			
			WO8-11 LANES	48x48 16.00 UNEVEN		19.286	25' L of C/L		16			
	November 12, 2020	80	WO8-12 LINE	48x48 16.00 NO CENTER		14.037	28' R of C/L		16			
			WO8-12 LINE	48x48 16.00 NO CENTER		15.064	28' L of C/L		16			
			WO8-12 LINE	48x48 16.00 NO CENTER		16.292	28' R of C/L		16			
			WO8-12 LINE	48x48 16.00 NO CENTER		20.829	28' R of C/L		16			
			WO8-12 LINE	48x48 16.00 NO CENTER		7.117	28' R of C/L		16			
		October 23, 2020 November 11, 2020	October 23, 2020 816 November 11, 2020 128	October 23, 2020 816 W08-11 LANES W08-11 LANES W08-12 LINE W08-11 LANES W08-11 LANES W08-11 LANES W08-12 LINE W08-11 LANES W08-11 LANES W08-11 LANES W08-11 LANES W08-11 LANES W08-11 LANES W08-12 LINE W	October 23, 2020 816 WO8-11	October 23, 2020 816 WO8-11 48x48 16.00 UNEVEN MO8-11 48x48 16.00 UNEVEN MO8-11 48x48 16.00 UNEVEN MO8-12 48x48 16.00 UNEVEN MO8	October 23, 2020 816 WOB-11 48x48 16.00 UNEVEN 5.474	October 23, 2020 816 W08-11 48x48 16.00 UNEVEN 5.474 28° R of CIL LANES W08-12 48x48 16.00 UNEVEN 5.938 28° L of CIL LINE W08-11 48x48 16.00 UNEVEN 6.421 28° R of CIL LINE W08-11 48x48 16.00 UNEVEN 6.425 28° R of CIL LINE W08-11 48x48 16.00 UNEVEN 6.485 28° L of CIL LINE W08-11 48x48 16.00 UNEVEN 6.888 28° L of CIL LINE W08-12 48x48 18.00 NO CENTER 8.124 28° R of CIL LINE W08-11 48x48 16.00 UNEVEN 8.124 28° R of CIL LINE W08-11 48x48 16.00 UNEVEN 8.535 28° L of CIL LINE W08-11 48x48 16.00 UNEVEN 8.838 28° R of CIL LINE W08-11 48x48 16.00 UNEVEN 8.838 28° R of CIL LINE W08-11 48x48 16.00 UNEVEN 9.598 28° L of CIL LINE W08-11 48x48 16.00 UNEVEN 9.783 28° R of CIL LINE W08-11 48x48 16.00 UNEVEN 9.783 28° R of CIL LINE W08-11 48x48 16.00 UNEVEN 16.041 28° L of CIL LINE W08-11 48x48 16.00 UNEVEN 16.041 28° L of CIL LINE W08-11 48x48 16.00 UNEVEN 16.335 28° R of CIL LINE W08-12 48x48 16.00 UNEVEN 16.335 28° R of CIL LINE W08-12 48x48 16.00 UNEVEN 16.335 28° R of CIL LINE W08-12 48x48 16.00 UNEVEN 18.432 28° R of CIL LINE W08-12 48x48 16.00 UNEVEN 18.432 28° R of CIL LINE W08-12 48x48 16.00 UNEVEN 18.432 28° R of CIL LINE W08-12 48x48 16.00 UNEVEN 18.432 28° R of CIL LINE W08-12 48x48 16.00 UNEVEN 18.432 28° R of CIL LINE W08-12 48x48 16.00 UNEVEN 18.432 28° R of CIL LINE W08-12 48x48 16.00 UNEVEN 18.432 28° R of CIL LINE W08-12 48x48 16.00 UNEVEN 18.432 28° R of CIL LINE W08-12 48x48 16.00 UNEVEN 18.432 28° R of CIL LINE W08-12 48x48 16.00 UNEVEN 18.432 28° R of CIL LINE W08-12 48x48 16.00 UNEVEN 18.432 28° R of CIL LINE W08-12 48x48 16.00 UNEVEN 18.432 28° R of CIL LINE W08-12 48x48 16.00 UNEVEN 18.432 28° R of CIL LINE W08-12 48x48 16.00 UNEVEN 18.432 28° R of CIL LINE W08-12 48x48	October 23, 2020	October 23, 2020 Side	October 23, 2020 B16	October 23, 2020 RESERVE PARA

Revision 4/1/2020 Page 6 of 15



MSC. SHAPNO Maleral	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1	J9P3520	0020		Material		6		SYSTEM	\$10,080.00	Estimate Item Adjustment (0014) due to user turnep3 overridding Payment
2020 17 10 10 10 10 10 10 1						6		SYSTEM	(\$10,080.00)	
Total						7		SYSTEM	\$54,635.00	Estimate Item Adjustment (0002) due to user turnep3 overridding Payment
National Total Social						7		SYSTEM	(\$54,635.00)	
					- Total				\$0.00	
Material FOR BASE Material				Material - To	tal				\$0.00	
### AGGREGATE FOR BASE POR BASE		0020 -	Total						\$0.00	
8 Bost 5, VSTEM \$119,583.00 This adjustment offsets the original system-generated Overrun Payment Estimate Recognition 1 on the current Payment Restinate Recognition 2 on the current Payment Restinate Recognition 1 on the current Payment Restinate Recognition 2 on th		0030	AGGREGATE	Material		7		SYSTEM	\$119,582.31	Estimate Item Adjustment (0003) due to user turnep3 overridding Payment
2020 Estimate Elem Adjustment (Q005) due to user turnep3 overridding Payment Estimate Exception 1 on the current Payment Estimate Exception 1 on the current Payment Estimate Exception 2 on the current Payment Estimate Estimate Exception 1 on the current Payment Estimate International Payment International Paym						7		SYSTEM	(\$119,582.31)	
2020 9 Jan 4 SYSTEM \$119,583.09 This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate Estimate Exception 1 on the current Payment Estimate Exception 2 on the current Payment Estimate Exception 3 on the current Payment Estimate Exception 5 on the current Payment Estimate Exception 5 on the current Payment Estimate Exception 6 on the current Payment Estimate Estimate Exception 6 on the current Payment Estimate Estimate Exception 6 on the current Payment Estimate Estimate Exception 6 on the						8		SYSTEM	\$119,583.09	Estimate Item Adjustment (0005) due to user turnep3 overridding Payment
2021 Settinate Item Adjustment (0010) due to user turnegs overridding Payment Estimate Exception 1 on the current Payment Estimate Exception 2 on the current Payment Estimate Exception 1 on the current Payment Estimate Item Adjustment (0004) due to user turnegal overridding Payment Estimate Item Adjustment (0004) due to user turnegal overridding Payment Estimate Item Adjustment (0004) due to user turnegal overridding Payment Estimate Item Adjustment (0004) due to user turnegal overridding Payment						8		SYSTEM	(\$119,583.09)	
Total S0.00						9		SYSTEM	\$119,583.09	Estimate Item Adjustment (0010) due to user turnep3 overridding Payment
						9		SYSTEM	(\$119,583.09)	
1					- Total				\$0.00	
				Material - To	tal				\$0.00	
CRUSHED STONE		0030 -	Total						\$0.00	
2020 8 Dec 16, SYSTEM 2020		0040	CRUSHED STONE	Material		7		SYSTEM	\$3,689.02	Estimate Item Adjustment (0004) due to user turnep3 overridding Payment
2020 Estimate tem Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.						7		SYSTEM	(\$3,689.02)	
2020 9 Jan 4, 2021 202						8		SYSTEM	\$3,689.02	Estimate Item Adjustment (0006) due to user turnep3 overridding Payment
Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate. 9 Jan 4, 2021 System (\$3,689.02) Total						8		SYSTEM	(\$3,689.02)	
Cot 1 System Sy						9		SYSTEM	\$3,689.02	Estimate Item Adjustment (0003) due to user turnep3 overridding Payment
Material - Total \$0.00						9		SYSTEM	(\$3,689.02)	
Solution					- Total				\$0.00	
BIT. PAVEMENT MIXTURE PG64-22 (BP-1) Material 3 Oct 1, 2020 SYSTEM \$734,432.03 This adjustment offsets the original system-generated Overrun Payment Estimate Exception 1 on the current Payment Estimate. 3 Oct 1, 2020 SYSTEM (\$734,432.03) 4 Oct 16, 2020 SYSTEM \$734,432.03 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user turnep3 overridding Payment Estimate Exception 1 on the current Payment Estimate Exception 1 on the current Payment Estimate Exception 1 on the current Payment Estimate. 4 Oct 16, 2020 SYSTEM (\$734,432.03) 5 Nov 2, 2020 SYSTEM \$734,432.03 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user turnep3 overridding Payment Estimate Item Adjustment (0012) due to user turnep3 overridding Payment Estimate Item Adjustment (0012) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.				Material - To	tal				\$0.00	
MIXTURE PG64-22 (BP-1) 2020 Cot 1, 2020 Quantification of the current Payment Estimate (0004) due to user turnep3 overridding Payment Estimate Exception 1 on the current Payment Estimate. 3		0040 -	Total						\$0.00	
2020 4 Oct 16, 2020 SYSTEM \$734,432.03 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user turnep3 overridding Payment Estimate Exception 1 on the current Payment Estimate. 4 Oct 16, 2020 5 Nov 2, 2020 SYSTEM \$734,432.03 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate. 5 Nov 2, 2020 SYSTEM (\$734,432.03)		0050	MIXTURE	Material		3		SYSTEM	\$734,432.03	Estimate Item Adjustment (0004) due to user turnep3 overridding Payment
Estimate Item Adjustment (0010) due to user turnep3 overridding Payment Estimate Exception 1 on the current Payment Estimate. 4 Oct 16, 2020 SYSTEM (\$734,432.03) 5 Nov 2, 2020 SYSTEM \$734,432.03 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate. 5 Nov 2, 2020 SYSTEM (\$734,432.03)						3		SYSTEM	(\$734,432.03)	
5 Nov 2, 2020 SYSTEM \$734,432.03 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate. 5 Nov 2, 2020 SYSTEM (\$734,432.03)						4		SYSTEM	\$734,432.03	Estimate Item Adjustment (0010) due to user turnep3 overridding Payment
2020 Estimate Item Adjustment (0012) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate. 5 Nov 2, 2020 (\$734,432.03)						4		SYSTEM	(\$734,432.03)	
2020						5		SYSTEM	\$734,432.03	Estimate Item Adjustment (0012) due to user turnep3 overridding Payment
6 Nov 16, SYSTEM \$1,495,517.54 This adjustment offsets the original system-generated Overrun Payment						5		SYSTEM	(\$734,432.03)	
						6		SYSTEM	\$1,495,517.54	This adjustment offsets the original system-generated Overrun Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9P3520	0050	BIT. PAVEMENT MIXTURE	Material			2020			Estimate Item Adjustment (0013) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		PG64-22 (BP-1)			6	Nov 16, 2020	SYSTEM	(\$1,495,517.54)	
					7	Dec 3, 2020	SYSTEM	\$1,495,517.54	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					7	Dec 3, 2020	SYSTEM	(\$1,495,517.54)	
					8	Dec 16, 2020	SYSTEM	\$1,495,522.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					8	Dec 16, 2020	SYSTEM	(\$1,495,522.62)	
					9	Jan 4, 2021	SYSTEM	\$1,495,522.62	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					9	Jan 4, 2021	SYSTEM	(\$1,495,522.62)	
					10	Jan 19, 2021	SYSTEM	\$1,495,522.62	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user turnep3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					10	Jan 19, 2021	SYSTEM	(\$1,495,522.62)	
					11	Feb 2, 2021	SYSTEM	\$1,495,522.62	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user turnep3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					11	Feb 2, 2021	SYSTEM	(\$1,495,522.62)	
					12	Feb 16, 2021	SYSTEM	\$1,495,522.62	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user turnep3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					12	Feb 16, 2021	SYSTEM	(\$1,495,522.62)	
					13	Mar 2, 2021	SYSTEM	\$1,495,522.62	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user turnep3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					13	Mar 2, 2021	SYSTEM	(\$1,495,522.62)	
					14	Mar 16, 2021	SYSTEM	\$648,322.62	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user turnep3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					14	Mar 16, 2021	SYSTEM	(\$648,322.62)	
					15	Apr 1, 2021	SYSTEM	\$648,322.62	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user turnep3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					15	Apr 1, 2021	SYSTEM	(\$648,322.62)	
					16	Apr 16, 2021	SYSTEM	\$648,322.62	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user turnep3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					16	Apr 16, 2021	SYSTEM	(\$648,322.62)	
			Motovici. T	- Total				\$0.00	
			Material - To	ACAD	2	Sep 16,	turnep3	\$0.00 (\$9,731.85)	AC Index Price Adjustment: -\$9,731.85
			Adjustment		3	2020 Oct 1,	turnep3	(\$20,988.69)	AC Index Price Adjustment: -\$20,988.69
					6	2020 Nov 16,	turnep3	(\$34,193.60)	Asphalt Index Price Adjustment: -\$34,193.60
				ACAB T		2020		, , ,	
				ACAD - Tota		Dec 16,	turnep3	(\$64,914.14) \$0.02	Correction of Fuel Price adjustment due to rounding BP-1 totals.
				FUEL - Tota		2020		\$0.02	
				TUEL - Tota				\$0.02	



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9P3520	0050	BIT. PAVEMENT	Other Item A	djustment - T	otal			(\$64,914.12)	
		MIXTURE PG64-22 (BP-1)	Overrun	Overrun	6	Nov 16, 2020	SYSTEM	(\$21,855.70)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					6	Nov 16, 2020	SYSTEM	\$21,855.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) overridding Payment Estimate Exception 6 on the current Payment Estimate.
					7	Dec 3, 2020	SYSTEM	(\$21,881.39)	Averaged Price Adjustment from this item on all previous payment estimates of '-0.93078' is applied (if non-zero).
					7	Dec 3, 2020	SYSTEM	\$21,881.39	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 11 on the current Payment Estimate.
					8	Dec 16, 2020	SYSTEM	(\$21,881.39)	Averaged Price Adjustment from this item on all previous payment estimates of '-0.93078' is applied (if non-zero).
					8	Dec 16, 2020	SYSTEM	(\$5.07)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					8	Dec 16, 2020	SYSTEM	\$5.07	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 10 on the current Payment Estimate.
					8	Dec 16, 2020	SYSTEM	\$21,881.39	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 10 on the current Payment Estimate.
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
			Price FUEL		2	Sep 16, 2020	SYSTEM	(\$3,555.78)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					3	Oct 1, 2020	SYSTEM	(\$7,668.76)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					6	Nov 16, 2020	SYSTEM	(\$13,421.40)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					8	Dec 16, 2020	SYSTEM	(\$0.02)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				(\$24,645.96)	
			Price FUEL -	Total				(\$24,645.96)	
	0050 -	- Total						(\$89,560.08)	
	0050 -	ASPHALTIC CONCRETE MIXTURE PG	Material		4	Oct 16, 2020	SYSTEM	(\$89,560.08) \$831,265.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
		ASPHALTIC CONCRETE	Material		4		SYSTEM SYSTEM		Estimate Item Adjustment (0009) due to user turnep3 overridding Payment
		ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C	Material			2020 Oct 16,		\$831,265.85	Estimate Item Adjustment (0009) due to user turnep3 overridding Payment
		ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C	Material		4	2020 Oct 16, 2020 Nov 2,	SYSTEM	\$831,265.85 (\$831,265.85)	Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user turnep3 overridding Payment
		ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C	Material		5	2020 Oct 16, 2020 Nov 2, 2020	SYSTEM	\$831,265.85 (\$831,265.85) \$2,367,981.98	Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user turnep3 overridding Payment
		ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C	Material		5	2020 Oct 16, 2020 Nov 2, 2020 Nov 2, 2020 Nov 16,	SYSTEM SYSTEM	\$831,265.85 (\$831,265.85) \$2,367,981.98 (\$2,367,981.98)	Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user turnep3 overridding Payment
		ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C	Material		4 5 5	2020 Oct 16, 2020 Nov 2, 2020 Nov 2, 2020 Nov 16, 2020 Nov 16,	SYSTEM SYSTEM SYSTEM	\$831,265.85 (\$831,265.85) \$2,367,981.98 (\$2,367,981.98) \$2,367,981.98	Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user turnep3 overridding Payment
		ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C	Material		45566	2020 Oct 16, 2020 Nov 2, 2020 Nov 16, 2020 Nov 16, 2020 Dec 3,	SYSTEM SYSTEM SYSTEM SYSTEM	\$831,265.85 (\$831,265.85) \$2,367,981.98 (\$2,367,981.98) \$2,367,981.98	Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user turnep3 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user turnep3 overridding Payment Estimate Item Adjustment (0007) due to user turnep3 overridding Payment
		ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C	Material		4 5 5 6 6 7 7	2020 Oct 16, 2020 Nov 2, 2020 Nov 16, 2020 Nov 16, 2020 Dec 3, 2020 Dec 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$831,265.85 (\$831,265.85) \$2,367,981.98 (\$2,367,981.98) \$2,367,981.98 (\$2,367,981.98)	Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user turnep3 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user turnep3 overridding Payment Estimate Item Adjustment (0007) due to user turnep3 overridding Payment
		ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C	Material		4 5 5 6 6 7 7	2020 Oct 16, 2020 Nov 2, 2020 Nov 16, 2020 Nov 16, 2020 Dec 3, 2020 Dec 16, 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$831,265.85 (\$831,265.85) \$2,367,981.98 (\$2,367,981.98) \$2,367,981.98 (\$2,367,981.98) \$2,367,981.98	Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user turnep3 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user turnep3 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Exception 7 on the current Payment Estimate.
		ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C	Material		4 5 5 6 6 7 7 8 8	2020 Oct 16, 2020 Nov 2, 2020 Nov 16, 2020 Nov 16, 2020 Dec 3, 2020 Dec 16, 2020 Dec 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$831,265.85 (\$831,265.85) \$2,367,981.98 (\$2,367,981.98) \$2,367,981.98 (\$2,367,981.98) \$2,367,981.98 (\$2,367,981.98) \$2,367,981.98)	Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user turnep3 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user turnep3 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Exception 7 on the current Payment Estimate.
		ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C	Material		4 5 5 6 6 7 7 8 8 8	2020 Oct 16, 2020 Nov 2, 2020 Nov 16, 2020 Nov 16, 2020 Dec 3, 2020 Dec 16, 2020 Dec 16, 2020 Jan 4,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$831,265.85 (\$831,265.85) \$2,367,981.98 (\$2,367,981.98) \$2,367,981.98 (\$2,367,981.98) \$2,367,981.98 (\$2,367,983.92)	Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user turnep3 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user turnep3 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user turnep3 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment



ject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
3520	0060	ASPHALTIC CONCRETE	Material						Estimate Exception 2 on the current Payment Estimate.
		MIXTURE PG 70-22 (SP125C			10	Jan 19, 2021	SYSTEM	(\$2,367,983.92)	
		MIX)			11	Feb 2, 2021	SYSTEM	\$2,367,983.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					11	Feb 2, 2021	SYSTEM	(\$2,367,983.92)	
					12	Feb 16, 2021	SYSTEM	\$2,367,983.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					12	Feb 16, 2021	SYSTEM	(\$2,367,983.92)	
					13	Mar 2, 2021	SYSTEM	\$2,367,983.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					13	Mar 2, 2021	SYSTEM	(\$2,367,983.92)	
					14	Mar 16, 2021	SYSTEM	\$2,367,983.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					14	Mar 16, 2021	SYSTEM	(\$2,367,983.92)	
					15	Apr 1, 2021	SYSTEM	\$2,367,983.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					15	Apr 1, 2021	SYSTEM	(\$2,367,983.92)	
					16	Apr 16, 2021	SYSTEM	\$2,367,983.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					16	Apr 16, 2021	SYSTEM	(\$2,367,983.92)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Other Item Adjustment	ACAD	4	Oct 16, 2020	turnep3	(\$28,623.35)	AC Index Price Adjustment: -\$28623.35
			,						Calculated by hand using appropriate indexes. AC Index spreadsheet did not include index for October 2020, but value was given in index list on MoDOT website.
					5	Nov 2, 2020	turnep3	(\$52,914.44)	AC Index Price Adjustment: -\$52914.44
				ACAD - Tota	al			(\$81,537.79)	
				FUEL	5	Nov 2, 2020	turnep3	(\$25,237.40)	Fuel Price Adjustment: -\$25237.40
					6	Nov 16, 2020	turnep3	\$25,237.40	Correction for double adjustment of Fuel Price Adjustment on Estimate 0005: \$25,237.40
					8	Dec 16, 2020	turnep3	\$0.01	Correction of Fuel Price adjustment due to rounding SP125 totals.
								CO 04	
				FUEL - Tota				\$0.01	
			Other Item A	FUEL - Tota djustment - T				(\$81,537.78)	
			Other Item A Price FUEL			Oct 16, 2020	SYSTEM		Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					otal		SYSTEM SYSTEM	(\$81,537.78)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					otal 4	2020 Nov 2,		(\$81,537.78) (\$13,651.84)	, , , , , , , , , , , , , , , , , , , ,
					otal 4 5	2020 Nov 2, 2020 Dec 16,	SYSTEM	(\$81,537.78) (\$13,651.84) (\$25,237.40)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				djustment - T	otal 4 5	2020 Nov 2, 2020 Dec 16,	SYSTEM	(\$81,537.78) (\$13,651.84) (\$25,237.40) (\$0.01)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
	0060 -	· Total	Price FUEL	djustment - T	otal 4 5	2020 Nov 2, 2020 Dec 16,	SYSTEM	(\$81,537.78) (\$13,651.84) (\$25,237.40) (\$0.01) (\$38,889.25)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
	0060 - 0070	Total TACK COAT	Price FUEL	djustment - T	otal 4 5	2020 Nov 2, 2020 Dec 16,	SYSTEM	(\$81,537.78) (\$13,651.84) (\$25,237.40) (\$0.01) (\$38,889.25) (\$38,889.25)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9P3520	0070	TACK COAT	Material		2	Sep 16, 2020	SYSTEM	\$9,036.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					2	Sep 16, 2020	SYSTEM	(\$9,036.00)	
					3	Oct 1, 2020	SYSTEM	\$22,768.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					3	Oct 1, 2020	SYSTEM	(\$22,768.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Overrun	Overrun	6	Nov 16, 2020	SYSTEM	\$382.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user turnep3 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					6	Nov 16, 2020	SYSTEM	(\$382.00)	
					7	Dec 3, 2020	SYSTEM	(\$382.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					7	Dec 3, 2020	SYSTEM	\$382.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user turnep3 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					8	Dec 16, 2020	SYSTEM	(\$382.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					8	Dec 16, 2020	SYSTEM	\$382.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	0070 -	Total						\$0.00	
	0800	BITUMINOUS FOG SEAL	Material		7	Dec 3, 2020	SYSTEM	\$15,542.28	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					7	Dec 3, 2020	SYSTEM	(\$15,542.28)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0080 -	Total						\$0.00	
	0090	TRUCK OR TRAILER MOUNTED ATTEN	Other Item Adjustment	OADJ	8	Dec 16, 2020	turnep3	(\$1,000.00)	Removal of previous line item adjustment for overrun of 2 TMAs. Change Order has been submitted and is awaiting approval.
		(TMA)			9	Jan 4, 2021	turnep3	(\$1,000.00)	Removing the \$1000 automatic overrun adjustment. Change Order 0003 has been submitted and approved which included overrun adjustment for 2 additional TMAs.
				OADJ - Tota	al			(\$2,000.00)	
				OTHR	10	Jan 19, 2021	turnep3	\$1,000.00	This adjustment ensures full payment for Line 0090: TMAs, and zeroes any previous adjustments.
				OTHR - Tota	al			\$1,000.00	
			Other Item A	djustment - T	otal			(\$1,000.00)	
			Overrun	Overrun	7	Dec 3, 2020	turnep3	\$1,000.00	Due to additional TMAs required for Striping and Rumble Strips operations, \$1000 was adjusted for the 2 additional TMAs (\$500 per EA) until a Change Order correcting the quantity is submitted.
					7	Dec 3, 2020	SYSTEM	(\$1,000.00)	
					9	Jan 4, 2021	SYSTEM	\$1,000.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',500.00000 - 500.00000, 'is applied (if non-zero).
				Overrun - T	otal			\$1,000.00	
			Overrun - To	tal				\$1,000.00	
	0090 -	Total						\$0.00	
	0100	FURN & PLACE BIT. MATL FOR	Material		1	Sep 2, 2020	SYSTEM	\$6,206.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		CL C PARTIAL							Estimate Exception of the surroller dymone Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9P3520	0100	FURN & PLACE BIT. MATL FOR CL C PARTIAL	Material		2	Sep 16, 2020	SYSTEM	\$6,206.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					2	Sep 16, 2020	SYSTEM	(\$6,206.32)	
					3	Oct 1, 2020	SYSTEM	\$6,206.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					3	Oct 1, 2020	SYSTEM	(\$6,206.32)	
					4	Oct 16, 2020	SYSTEM	\$57,433.91	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					4	Oct 16, 2020	SYSTEM	(\$57,433.91)	
					5	Nov 2, 2020	SYSTEM	\$57,433.91	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user turnep3 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					5	Nov 2, 2020	SYSTEM	(\$57,433.91)	
					6	Nov 16, 2020	SYSTEM	\$57,433.91	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					6	Nov 16, 2020	SYSTEM	(\$57,433.91)	
					7	Dec 3, 2020	SYSTEM	\$57,433.91	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user turnep3 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					7	Dec 3, 2020	SYSTEM	(\$57,433.91)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
			Other Item Adjustment	ACAD	1	Sep 2, 2020	turnep3	(\$80.21)	AC Price Index Adjustment: -\$80.21
					4	Oct 16, 2020	turnep3	(\$662.28)	AC Index Price Adjustment: -\$662.28
									Calculated according to index appropriate for when the work was performed (9/9/2020).
				ACAD - Tota	al			(\$742.49)	
				FUEL	1	Sep 2, 2020	turnep3	(\$34.67)	Asphalt Paving Production and Hauling Fuel Adjustment: -\$34.67
					4	Oct 16, 2020	turnep3	(\$256.65)	Fuel Price Adjustment: -\$256.65
									Calculated according to index appropriate for when the work was performed (9/9/2020).
				FUEL - Tota				(\$291.32)	
			Other Item A	djustment - T	otal			(\$1,033.81)	
			Overrun	Overrun	4	Oct 16, 2020	SYSTEM	\$4,487.99	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) overridding Payment Estimate Exception 4 on the current Payment Estimate.
					4	Oct 16, 2020	SYSTEM	(\$4,487.99)	
					5	Nov 2, 2020	SYSTEM	(\$4,487.99)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					5	Nov 2, 2020	SYSTEM	\$4,487.99	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) overridding Payment Estimate Exception 5 on the current Payment Estimate.
					6	Nov 16, 2020	SYSTEM	(\$4,487.99)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					6	Nov 16, 2020	SYSTEM	\$4,487.99	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) overridding Payment Estimate Exception 8 on the current Payment Estimate.
					7	Dec 3, 2020	SYSTEM	(\$4,487.99)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					7	Dec 3, 2020	SYSTEM	\$4,487.99	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) overridding Payment Estimate Exception 14 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9P3520	0100	FURN & PLACE BIT. MATL FOR	Overrun	Overrun	8	Dec 16, 2020	SYSTEM	(\$4,487.99)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
		CL C PARTIAL			8	Dec 16, 2020	SYSTEM	\$10.34	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user turnep3 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					8	Dec 16, 2020	SYSTEM	\$4,487.99	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user turnep3 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					8	Dec 16, 2020	SYSTEM	(\$10.34)	
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	0100 -	Total						(\$1,033.81)	
	0110	REMOVAL FOR CLASS C PARTIAL DEPTH PAVT REPAIR	Overrun	Overrun	2	Sep 16, 2020	SYSTEM	\$1,408.43	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		PAVI REPAIR			2	Sep 16, 2020	SYSTEM	(\$1,408.43)	
					3	Oct 1, 2020	SYSTEM	(\$1,408.43)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					3	Oct 1, 2020	SYSTEM	\$1,408.43	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user turnep3 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					4	Oct 16, 2020	SYSTEM	(\$1,408.43)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					4	Oct 16, 2020	SYSTEM	\$1,408.43	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					5	Nov 2, 2020	SYSTEM	(\$1,408.43)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					5	Nov 2, 2020	SYSTEM	\$1,408.43	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user turnep3 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					6	Nov 16, 2020	SYSTEM	(\$1,408.43)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					6	Nov 16, 2020	SYSTEM	\$1,408.43	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user turnep3 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					7	Dec 3, 2020	SYSTEM	(\$1,408.43)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					7	Dec 3, 2020	SYSTEM	\$1,408.43	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user turnep3 overridding Payment Estimate Exception 15 on the current Payment Estimate.
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	0110 - 0120	CONSTRUCTION SIGNS	Material		1	Sep 2, 2020	SYSTEM	\$0.00 \$480.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment
						Sep 2, 2020	SYSTEM	(\$480.00)	Estimate Exception 4 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0120 -	· Total						\$0.00	
	0150	CMS W/O COMMUNICATION INTERFACE,	Material		1	Sep 2, 2020	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate.
		CONT F/			1	Sep 2, 2020	SYSTEM	(\$5,600.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0150 -	Total						\$0.00	
	0170	PREF THERMO PVMT MARK, 24 IN WHIT	Material		7	Dec 3, 2020	SYSTEM	\$7,120.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user turnep3 overridding Payment Estimate Exception 10 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9P3520	0170	PREF THERMO PVMT MARK, 24	Material		7	Dec 3, 2020	SYSTEM	(\$7,120.00)	
		IN WHIT			8	Dec 16, 2020	SYSTEM	\$8,280.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user turnep3 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					8	Dec 16, 2020	SYSTEM	(\$8,280.00)	
					9	Jan 4, 2021	SYSTEM	\$8,280.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user turnep3 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					9	Jan 4, 2021	SYSTEM	(\$8,280.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0170 -	· Total						\$0.00	
	0180	PREF THERMO PVMT MARK, 24 IN YELLOW	Material		8	Dec 16, 2020	SYSTEM	\$7,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user turnep3 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					8	Dec 16, 2020	SYSTEM	(\$7,800.00)	
					9	Jan 4, 2021	SYSTEM	\$7,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					9	Jan 4, 2021	SYSTEM	(\$7,800.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0180 -	· Total						\$0.00	
	0190	PREF THERMO PVMT MARK, LT/RT ARROW	Material		8	Dec 16, 2020	SYSTEM	\$3,640.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user turnep3 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					8	Dec 16, 2020	SYSTEM	(\$3,640.00)	
					9	Jan 4, 2021	SYSTEM	\$3,640.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user turnep3 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					9	Jan 4, 2021	SYSTEM	(\$3,640.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Overrun	Overrun	8	Dec 16, 2020	SYSTEM	\$560.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) overridding Payment Estimate Exception 14 on the current Payment Estimate.
					8	Dec 16, 2020	SYSTEM	(\$560.00)	
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	0190 - 0230	Total MISC. PAVEMENT	Material		8	Dec 16,	SYSTEM	\$0.00 \$4,000.00	This adjustment offsets the original system-generated Overrun Payment
		MARKINGS				2020			Estimate Item Adjustment (0016) due to user turnep3 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					8	Dec 16, 2020	SYSTEM	(\$4,000.00)	
					9	Jan 4, 2021	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user turnep3 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					9	Jan 4, 2021	SYSTEM	(\$4,000.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0230 -			-			271==	\$0.00	
	0250	MODIFIED COLDMILLING (DEPTH	Overrun	Overrun	11	Feb 2, 2021	SYSTEM	\$4,770.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.



JRPAS20 December 1
Overrun - Total
MGS GUARDRAIL Construction Con
Stockpile
14
Construction Stockpile - Total (\$21,339,36)
Construction Stockpile - Total Sep 16, 2020 SySTEM S21,339.36 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile STMI - Total S21,339.36 SySTEM S22,200.00 SySTEM S21,200.00 SySTEM S21,200.00 SySTEM S22,200.00 SySTEM S33,766.00 SySTEM S33,
Construction Stockpile STMI -Total S21,339.36 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile STMI -Total S21,339.36
Stockpile STM -Total S21,339.36 S21,33
Construction Stockpile STMI - Total \$21,339.36
MGS BRIDGE
MGS BRIDGE APP. TRAINS SEC (REG/NO CURB)
APP_TRANS_SEC (REG/NO CURB)
Total (\$29,200.00) Construction Stockpile - Total (\$29,200.00) Construction Stockpile - Total (\$29,200.00) Construction Stockpile - Total (\$29,200.00) Construction Stockpile STMI - Total \$29,200.00 Construction Stockpile STMI - Total \$38,766.00 Construction Stockpile - Total \$38,766.00 Construction Stockpile STMI - Total \$38,766.00
Construction Stockpile - Total Construction Stockpile STMI - Total Construction Stockpile STMI - Total CONSTRUCTION Stockpile STMI - Total CONSTRUCTION Stockpile STMI - Total CONSTRUCTION Stockpile STMI - Total CONSTRUCTION Stockpile STMI - Total CONSTRUCTION Stockpile STMI - Total CONSTRUCTION Stockpile STMI - Total CONSTRUCTION Stockpile STMI - Total CONSTRUCTION Stockpile - Total CONSTRUCTION Stockpile STMI - Total S38,766.00
Construction Stockpile STMI 2 Sep 16, 2020 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile STMI 529,200.00 Construction Stockpile STMI - Total \$29,200.00 Construction Stockpile STMI - Total \$29,200.00 TYPE A CRSHWTHY END TERMINAL (MASH) (MASH) Construction Stockpile - Total (\$38,766.00) Construction Stockpile - Total (\$38,766.00) Construction Stockpile - Total (\$38,766.00) Construction Stockpile STMI - Total \$38,766.00
Stockpile STMI - Total \$29,200.00
Construction Stockpile STMI - Total \$29,200.00
Construction Stockpile Construction Stockpile Construction
TYPE A CRSHWTHY END TERMINAL (MASH) Output O
CRSHWTHY END TERMINAL (MASH) CRSHWTHY END TERMINAL (MASH)
(MASH) Total Construction Stockpile - Total SYSTEM System
2021
Construction Stockpile - Total (\$38,766.00) Construction Stockpile STMI 2 Sep 16, 2020 SYSTEM \$38,766.00 Payment Estimate Item Adjustment generated Stockpile Transaction \$38,766.00 Construction Stockpile STMI - Total \$38,766.00 0300 - Total \$0.00
Construction Stockpile STMI - Total Construction Stockpile STMI - Total Construction Stockpile STMI - Total S38,766.00 \$38,766.00 \$38,766.00 \$38,766.00 \$38,766.00
Stockpile STMI
- Total
0300 - Total \$0.00
5001 ADVANCED Material 8 Dec 16, SYSTEM \$70.00 This adjustment offsets the original system-generated Overrun Payment 8 Dec 16, SYSTEM \$70.00 This adjustment (0017) due to user turnep3 overridding Payme 8 SYSTEM Estimate Item Adjustment (0017) due to user turnep3 overridding Payme 8 Estimate Exception 5 on the current Payment Estimate.
8 Dec 16, 2020 (\$70.00)
9 Jan 4, 2021 \$YSTEM \$70.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user turnep3 overridding Payme Estimate Exception 6 on the current Payment Estimate.
9 Jan 4, 2021 (\$70.00)
- Total \$0.00
- Total \$0.00 Material - Total \$0.00
Material - Total \$0.00