

## Missouri Department of Transportation Contractor's Pay Estimate Summary

July 6, 2020

Pay Estimate Created Date: May 3, 2021

Progress Estim	ate Number	Contract ID Prime Contractor	200417-C03 Comanche Const	ruction, Inc			Original Contract Amount Net Change Order Amount Current Contract Amount	. , ,					
Approval Date								By User					
May 3, 2021			Generated and A	Approved (	and should be considered	d Draft) at	the Project Office Level by	watsom1					
May 3, 2021		Reviewed and Approved (and should be considered Draft) at the Resident Engineer Lev											
May 4, 2021	4, 2021 Reviewed and Approved at the Central Office Controllers Office Leve												
Original Comp	letion Date	Current Cor	npletion Date	Actua	al Completion Date	%	6 of Current Contract Amount Complete						
November	5, 2021	Decemb	er 3, 2021			25.00%							
	Contra	ct Informational Da	tes		Milestones								
Date Description	on Origina	al Completion Date	Current Complet	tion Date	No Milestones Exist for	Contract							
Acceptance Date													
Awarded Date	May 6,	2020	May 6, 2020										
Letting Date	April 17												

Contract Total Pa	ay For Estimate No. 10				
		This Estimate	Previous	To Date	
200417-C03					
	Total Posted Items Pay	\$293,465.16	\$827,617.07	\$1,121,082.23	
	Gross Item Adjustments	(\$36,622.23)	\$201,120.10	\$164,497.87	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
	•		\$1,028,737.17	\$1,285,580.10	
<b>Contract Total Pa</b>	yable This Estimate:	\$256,842.93			

## Items Paid This Estimate Period

Notice to Proceed Date July 6, 2020

Open to Traffic Date Work Began Date

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J4P3266	0040	6161005	CONSTRUCTION SIGNS	SQFT	\$19.600	36	\$705.60
	0550	7040101	SUBSTRUCTURE REPAIR (FORMED)	SQFT	\$162.150	75	\$12,161.25
	0560	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	SQFT	\$162.150	-29	(\$4,702.35)
	0570	7040104	HALF-SOLE REPAIR	SQFT	\$43.900	1,656	\$72,698.40
	0580	7040106	FULL DEPTH REPAIR	SQFT	\$63.800	400	\$25,520.00
	0840	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	LS	\$7,120.500	1	\$7,120.50
	0880	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	LS	\$7,812.950	1	\$7,812.95
	1110	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	LF	\$448.950	162	\$72,729.90
	1130	7034214	CLASS B-2 CONCRETE	CUYD	\$2,888.200	15.3	\$44,189.46
	1140	7101000	REINFORCING STEEL (EPOXY COATED)	LB	\$3.050	2,080	\$6,344.00
	1160	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	LF	\$380.050	81	\$30,784.05
	1250	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	LS	\$6,380.600	1	\$6,380.60
	5006	7049904	MISC.Clean and Epoxy Seal	SQFT	\$12.880	910	\$11,720.80
Project J4P3	266 - Total						\$293,465.16
Overall - Tota	ıl						\$293,465.16

## Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Revision 4/1/2020 Page 1 of 14



## Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: May 3, 2021

Progress Estimate Number
10 Contract ID 200417-C03 Pay Period Start April 16, 2021 Original Contract Amount \$4,099,005.37 Pay Period End May 1, 2021 Original Contract Amount \$4,099,005.37 Pay Period End May 1, 2021 Original Contract Amount \$4,099,005.37 Original Contract Amount \$4,099,005.37 Original Contract Amount \$4,499,005.37 Original Contract Amount \$4,499,005.3

Line Item	<u>Adjustr</u>	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4P3266	0550	SUBSTRUCTURE REPAIR (FORMED)	Material			-75	\$162.15	(\$12,161.25)
	0570	HALF-SOLE REPAIR	Overrun			-323	\$43.90	(\$14,179.70)
	0580	FULL DEPTH REPAIR	Overrun		Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',63.80000 - 63.80000, 'is applied (if non-zero).	131.5	\$63.80	\$8,389.70
	1140	REINFORCING STEEL (EPOXY COATED)	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$1,390.36)
	1160	STRIP SEAL EXPANSION JOINT SYSTEM	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$17,280.62)
Total								(\$36,622.23)

Revision 4/1/2020 Page 2 of 14



## Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(	Contract Project Information	n
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J4P3266	FAS S302(002)	Bridge Rehabilitation	Various	VARIOUS	at various locations th	roughout the urban Kansa	s City district
Totals by J	Job Number	s					
J4P3266		Item Pay Item Adjustmer	its Gross Ite	em Pay	This Estimate \$293,465.16 (\$36,622.23) \$256,842.93	Previous \$827,617.07 \$201,120.10 \$1,028,737.17	To Date \$1,121,082.23 \$164,497.87 <b>\$1,2</b> 85,580.10
			ments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00

Revision 4/1/2020 Page 3 of 14



## Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

## **Exceptions (Discrepancies) This Estimate Period**

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4P3266, Item 7040101, Project Item Line Number 0550, Material Set 704010196, Material 4066SPSM - Special Provision Special Mortar, Acceptance Action Generic 4066SPSM is insufficient.	Waiting on material certification from contractor.	watsom1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J4P3266, Item 7040103, Project Item Line Number 0560, Material Set 704010396, Material 4066SPSM - Special Provision Special Mortar, Acceptance Action Generic 4066SPSM is insufficient.	This item will be removed on a future change order.	watsom1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 200417-C03, Contract Project J4P3266, Project Item Line Number 0570, Contract Line Item Number 0570, Item 7040104, Minor Item.	A future change order will be created to adjust for final quantities.	watsom1	Acknowledged

Revision 4/1/2020 Page 4 of 14



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

					eport Generated date and can differ from the posted am							
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200417-C03	J4P3266	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS		\$113,120.00	\$0.00
		0001	0020	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	153.00	0.00	153.00	SQFT	0.00	\$67.35	\$0.00
		0001	0030	4030007	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP095BSM MIX)	231.20	0.00	231.20	TONS	0.00	\$432.80	\$0.00
		0001	0040	6161005	CONSTRUCTION SIGNS	1,078.00	0.00	1,078.00	SQFT	1,044.00	\$19.60	\$20,462.40
		0001	0050	6161008	ADVANCED WARNING RAIL SYSTEM	8.00	-4.00	4.00	EA	0.00	\$309.15	\$0.00
		0001	0060	6161009	FLAG ASSEMBLY	8.00	-8.00	0.00	EA	0.00	\$103.05	\$0.00
		0001	0070	6161025	CHANNELIZER (TRIM LINE)	210.00	120.00	330.00	EA	330.00	\$51.50	\$16,995.00
		0001	0080	6161030	TYPE III MOVEABLE BARRICADE	16.00	0.00	16.00	EA	16.00	\$412.20	\$6,595.20
		0001	0090	6161040	FLASHING ARROW PANEL	4.00	0.00	4.00	EA	4.00	\$5,152.30	\$20,609.20
		0001	0100	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	4.00	\$17,002.60	\$68,010.40
		0001	0105	6162000A	WORK ZONE TRAFFIC SIGNAL SYSTEM	1.00	0.00	1.00	EA	0.00	\$7,728.45	\$0.00
		0001	0110	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED /	1,230.00	0.00	1,230.00	LF	0.00	\$19.75	\$0.00
		0001	0120	6173700B	RETAINED TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED	1,289.00	0.00	1,289.00	LF	536.00	\$29.75	\$15,946.00
		0001	0130	6174000A	TEMPORARY TRAFFIC BARRIER HEIGHT TRANSITION	6.00	0.00	6.00	EA	4.00	\$497.85	\$1,991.40
		0001	0140	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	6,444.00	0.00	6,444.00	LF	0.00	\$9.95	\$0.00
		0001	0150	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$406,875.00	\$0.00
		0001	0151	6181000	MOBILIZATION	0.00	1.00	1.00	LS	0.50	\$388,169.00	\$194,084.50
		0001	0160	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	16.00	0.00	16.00	EA	0.00	\$257.60	\$0.00
		0001	0170	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	4,271.00	0.00	4,271.00	LF	0.00	\$0.30	\$0.00
		0001	0180	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	1,458.00	0.00	1,458.00	LF	0.00	\$0.30	\$0.00
		0001	0190	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,640.00	0.00	1,640.00	LF	0.00	\$0.15	\$0.00
		0001	0200	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	5,071.00	0.00	5,071.00	LF	0.00	\$0.15	\$0.00
		0001	0210	6207001	PAVEMENT MARKING REMOVAL	20,939.00	23,714.00	44,653.00	LF	0.00	\$2.25	\$0.00
		0001	0220	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	18,663.00	13,750.00	32,413.00	LF	950.00	\$2.25	\$2,137.50
		0001	0230	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	2,534.00	0.00	2,534.00	SQYD	0.00	\$26.50	\$0.00
		0010	0240	6061060	MGS GUARDRAIL	5,588.00	0.00	5,588.00	LF	0.00	\$19.05	\$0.00
		0010	0250	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	12.00	0.00	12.00	EA	0.00	\$2,833.75	\$0.00
		0010	0260	6061080	MGS END ANCHOR	2.00	0.00	2.00	EA	0.00	\$875.90	\$0.00
		0010	0270	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	6.00	0.00	6.00	EA	0.00	\$2,627.65	\$0.00
		0070	0280	2161502	REMOVAL OF CONCRETE WEARING SURFACE	8,665.00	0.00	8,665.00	SQFT	0.00	\$2.80	\$0.00
		0070	0290	2165500	REMOVAL OF CATHODIC PROTECTION SYSTEM	1.00	0.00	1.00	LS	0.00	\$1,818.40	\$0.00
		0070	0300	5050001	OPTIONAL CONCRETE WEARING SURFACE	963.00	0.00	963.00	SQYD	0.00	\$91.80	\$0.00
		0070	0310	7040104	HALF-SOLE REPAIR	450.00	0.00	450.00	SQFT	0.00	\$43.90	\$0.00
		0071	0320	2161502	REMOVAL OF CONCRETE WEARING SURFACE	8,665.00	0.00	8,665.00	SQFT	0.00	\$2.80	\$0.00
		0071	0330	2165500	REMOVAL OF CATHODIC PROTECTION SYSTEM	1.00	0.00	1.00	LS	0.00	\$1,818.40	\$0.00
		0071	0340	5050001	OPTIONAL CONCRETE WEARING SURFACE	963.00	0.00	963.00	SQYD	0.00	\$91.80	\$0.00
		0071	0350	7040104	HALF-SOLE REPAIR	450.00	0.00	450.00	SQFT	0.00	\$43.90	\$0.00
		0072	0360	2161502	REMOVAL OF CONCRETE WEARING SURFACE	8,230.00	0.00	8,230.00	SQFT	0.00	\$2.80	\$0.00
		0072	0370	2165500	REMOVAL OF CATHODIC PROTECTION SYSTEM	1.00	0.00	1.00	LS	0.00	\$1,818.40	\$0.00
		0072	0380	5050001	OPTIONAL CONCRETE WEARING SURFACE	914.00	0.00	914.00	SQYD	0.00	\$91.80	\$0.00
		0072	0390	7040104	HALF-SOLE REPAIR	400.00	0.00	400.00	SQFT	0.00	\$43.90	\$0.00
		0072	0400	7040106	FULL DEPTH REPAIR	100.00	0.00	100.00	SQFT	0.00	\$63.80	\$0.00
		0073	0410	2161502	REMOVAL OF CONCRETE WEARING SURFACE	9,330.00	0.00	9,330.00	SQFT	0.00	\$2.60	\$0.00
		0073	0420	2163502	PARTIAL REMOVAL OF SUBSTRUCTURE CONCRETE	1.00	0.00	1.00	LS	0.00	\$11,742.65	\$0.00

Page 5 of 14 Revision 4/1/2020



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200417-C03	J4P3266	0073	0430	2164000	CURB REMOVAL	10.00	0.00	10.00	LF	0.00	\$275.85	\$0.00
		0073	0440	2165500	REMOVAL OF CATHODIC PROTECTION SYSTEM	1.00	0.00	1.00	LS	0.00	\$1,818.40	\$0.00
		0073	0450	5050001	OPTIONAL CONCRETE WEARING SURFACE	1,037.00	0.00	1,037.00	SQYD	0.00	\$91.80	\$0.00
		0073	0460	7034001	CLASS B-1 CONCRETE	4.20	0.00	4.20	CUYD	0.00	\$3,283.90	\$0.00
		0073	0470	7034600	CURB BLOCKOUT	21.00	0.00	21.00	LF	0.00	\$314.05	\$0.00
		0073	0480	7040104	HALF-SOLE REPAIR	450.00	0.00	450.00	SQFT	0.00	\$43.90	\$0.00
		0073	0490	7040106	FULL DEPTH REPAIR	100.00	0.00	100.00	SQFT	0.00	\$63.80	\$0.00
		0073	0500	7101000	REINFORCING STEEL (EPOXY COATED)	790.00	0.00	790.00	LB	0.00	\$2.45	\$0.00
		0074	0510	2161502	REMOVAL OF CONCRETE WEARING SURFACE	12,442.00	0.00	12,442.00	SQFT	12,442.00	\$2.05	\$25,506.10
		0074	0520	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	243.00	0.00	243.00	LF	243.00	\$321.05	\$78,015.15
		0074	0530	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,376.00	0.00	1,376.00	SQYD	0.00	\$137.30	\$0.00
		0074	0540	7034001	CLASS B-1 CONCRETE	16.30	0.00	16.30	CUYD	16.30	\$3,465.40	\$56,486.02
		0074	0550	7040101	SUBSTRUCTURE REPAIR (FORMED)	200.00	0.00	200.00	SQFT	75.00	\$162.15	\$12,161.25
		0074	0560	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	500.00	0.00	500.00	SQFT	0.00	\$162.15	\$0.00
		0074	0570	7040104	HALF-SOLE REPAIR	1,850.00	4,650.00	6,500.00	SQFT	6,823.00	\$43.90	\$299,529.70
		0074	0580	7040106	FULL DEPTH REPAIR	600.00	800.00	1,400.00	SQFT	1,331.50	\$63.80	\$84,949.70
		0074	0590	7101000	REINFORCING STEEL (EPOXY COATED)	4,280.00	0.00	4,280.00	LB	4,280.00	\$2.15	\$9,202.00
		0075	0600	2161502	REMOVAL OF CONCRETE WEARING SURFACE	9,139.00	0.00	9,139.00	SQFT	0.00	\$2.70	\$0.00
		0075	0610	5050001	OPTIONAL CONCRETE WEARING SURFACE	1,015.00	0.00	1,015.00	SQYD	0.00	\$91.80	\$0.00
		0075	0620	7034600	CURB BLOCKOUT	509.00	0.00	509.00	LF	0.00	\$97.20	\$0.00
		0075	0630	7040104	HALF-SOLE REPAIR	900.00	0.00	900.00	SQFT	0.00	\$43.90	\$0.00
		0075	0640	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	450.00	0.00	450.00	SQFT	0.00	\$75.50	\$0.00
		0076	0650	2161502	REMOVAL OF CONCRETE WEARING SURFACE	9,139.00	0.00	9,139.00	SQFT	0.00	\$2.70	\$0.00
		0076	0660	5050001	OPTIONAL CONCRETE WEARING SURFACE	1,015.00	0.00	1,015.00	SQYD	0.00	\$91.80	\$0.00
		0076	0670	7034600	CURB BLOCKOUT	509.00	0.00	509.00	LF	0.00	\$98.00	\$0.00
		0076	0680	7040104	HALF-SOLE REPAIR	900.00	0.00	900.00	SQFT	0.00	\$43.90	\$0.00
		0076	0690	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	450.00	0.00	450.00	SQFT	0.00	\$75.50	\$0.00
		0077	0700	2161502	REMOVAL OF CONCRETE WEARING SURFACE	5,187.00	0.00	5,187.00	SQFT	0.00	\$4.35	\$0.00
		0077	0710	5050001	OPTIONAL CONCRETE WEARING SURFACE	576.00	0.00	576.00	SQYD	0.00	\$91.80	\$0.00
		0077	0720	7034600	CURB BLOCKOUT	301.00	0.00	301.00	LF	0.00	\$124.00	\$0.00
		0077	0730	7040104	HALF-SOLE REPAIR	500.00	0.00	500.00	SQFT	0.00	\$43.90	\$0.00
		0077	0740	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	250.00	0.00	250.00	SQFT	0.00	\$75.50	\$0.00
		0077	0750	7040113	CLEANING AND EPOXY COATING	990.00	0.00	990.00	SQFT	0.00	\$5.50	\$0.00
		0078	0760	2161502	REMOVAL OF CONCRETE WEARING SURFACE	5,187.00	0.00	5,187.00	SQFT	0.00	\$4.35	\$0.00
		0078	0770	5050001	OPTIONAL CONCRETE WEARING SURFACE	576.00	0.00	576.00	SQYD	0.00	\$91.80	\$0.00
		0078	0780	7034600	CURB BLOCKOUT	301.00	0.00	301.00	LF	0.00	\$124.00	\$0.00
		0078	0790	7040104	HALF-SOLE REPAIR	500.00	0.00	500.00	SQFT	0.00	\$43.90	\$0.00
		0078	0800	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	250.00	0.00	250.00	SQFT	0.00	\$75.50	\$0.00
		0078	0810	7040113	CLEANING AND EPOXY COATING	990.00	0.00	990.00	SQFT	0.00	\$5.50	\$0.00
		0079	0820	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	144.00	0.00	144.00	LF	0.00	\$45.75	\$0.00
		0079	0830	2169903	MISC.REMOVAL AND REINSTALLATION OF SIDEWALK SKID	30.00	0.00	30.00	LF	0.00	\$261.45	\$0.00
		0079	0840	7110200	PLATE PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	1.00	\$7,120.50	\$7,120.50
		0079	0850	7171002	PREFORMED COMPRESSION SEAL	110.00	0.00	110.00	LF	0.00	\$95.15	\$0.00
		0800	0860	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	196.00	0.00	196.00	LF	0.00	\$45.75	\$0.00
		0080	0870	2169903	MISC.REMOVAL AND REINSTALLATION OF SIDEWALK SKID	26.00	0.00	26.00	LF	0.00	\$301.65	\$0.00
					PLATE							

Page 6 of 14 Revision 4/1/2020



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

	No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200417-C03	J4P3266	0080	0880	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	1.00	\$7,812.95	\$7,812.95
		0080	0890	7171002	PREFORMED COMPRESSION SEAL	165.00	0.00	165.00	LF	0.00	\$95.15	\$0.00
		0081	0900	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	63.00	0.00	63.00	LF	0.00	\$704.60	\$0.00
		0081	0910	2169903	MISC.REMOVE AND REPLACE BARRIER CURB	12.00	0.00	12.00	LF	0.00	\$709.90	\$0.00
		0081	0920	7034214	CLASS B-2 CONCRETE	5.90	0.00	5.90	CUYD	0.00	\$2,888.20	\$0.00
		0081	0930	7101000	REINFORCING STEEL (EPOXY COATED)	730.00	0.00	730.00	LB	0.00	\$3.55	\$0.00
		0081	0940	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$3,634.45	\$0.00
		0081	0950	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	63.00	0.00	63.00	LF	0.00	\$380.05	\$0.00
		0082	0960	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	92.00	0.00	92.00	LF	0.00	\$45.75	\$0.00
		0082	0970	7171002	PREFORMED COMPRESSION SEAL	92.00	0.00	92.00	LF	0.00	\$95.15	\$0.00
		0083	0980	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	92.00	0.00	92.00	LF	0.00	\$45.75	\$0.00
		0083	0990	7171002	PREFORMED COMPRESSION SEAL	92.00	0.00	92.00	LF	0.00	\$95.15	\$0.00
		0084	1000	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	192.00	0.00	192.00	LF	0.00	\$45.75	\$0.00
		0084	1010	7049903	MISC.RAISED MEDIAN REPAIR	40.00	0.00	40.00	LF	0.00	\$122.70	\$0.00
		0084	1020	7171002	PREFORMED COMPRESSION SEAL	192.00	0.00	192.00	LF	0.00	\$95.15	\$0.00
		0085	1030	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	193.00	0.00	193.00	LF	0.00	\$448.95	\$0.00
		0085	1040	2169903	MISC.REMOVE AND REPLACE BARRIER CURB	12.00	0.00	12.00	LF	0.00	\$709.90	\$0.00
		0085	1050	2169904	MISC.REMOVE AND REPLACE RAISED MEDIAN CURB	24.00	0.00	24.00	SQFT	0.00	\$166.85	\$0.00
		0085	1060	7034214	CLASS B-2 CONCRETE	16.90	0.00	16.90	CUYD	0.00	\$2,888.20	\$0.00
		0085	1070	7049903	MISC.RAISED MEDIAN REPAIR	20.00	0.00	20.00	LF	0.00	\$122.75	\$0.00
		0085	1080	7101000	REINFORCING STEEL (EPOXY COATED)	2,570.00	0.00	2,570.00	LB	0.00	\$2.70	\$0.00
		0085	1090	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$4,907.05	\$0.00
		0085	1100	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	163.00	0.00	163.00	LF	0.00	\$380.05	\$0.00
		0086	1110	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	162.00	0.00	162.00	LF	162.00	\$448.95	\$72,729.90
		0086	1120	2169904	MISC.REMOVE AND REPLACE RAISED MEDIAN CURB	24.00	0.00	24.00	SQFT	0.00	\$122.75	\$0.00
		0086	1130	7034214	CLASS B-2 CONCRETE	15.30	0.00	15.30	CUYD	15.30	\$2,888.20	\$44,189.46
		0086	1140	7101000	REINFORCING STEEL (EPOXY COATED)	2,080.00	0.00	2,080.00	LB	2,080.00	\$3.05	\$6,344.00
		0086	1150	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$6,167.30	\$0.00
		0086	1160	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	162.00	0.00	162.00	LF	81.00	\$380.05	\$30,784.05
		0087	1170	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	192.00	0.00	192.00	LF	0.00	\$448.95	\$0.00
		0087	1180	2169903	MISC.REMOVE AND REPLACE BARRIER CURB	12.00	0.00	12.00	LF	0.00	\$709.90	\$0.00
		0087	1190	2169904	MISC.REMOVE AND REPLACE RAISED MEDIAN CURB	24.00	0.00	24.00	SQFT	0.00	\$122.75	\$0.00
		0087	1200	7034214	CLASS B-2 CONCRETE	17.20	0.00	17.20	CUYD	0.00	\$2,888.20	\$0.00
		0087	1210	7101000	REINFORCING STEEL (EPOXY COATED)	2,900.00	0.00	2,900.00	LB	0.00	\$3.10	\$0.00
		0087	1220	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$4,118.75	\$0.00
		0087	1230	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	162.00	0.00	162.00	LF	0.00	\$380.05	\$0.00
		0088	1240	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	185.00	0.00	185.00	LF	0.00	\$45.75	\$0.00
		0088	1250	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	1.00	\$6,380.60	\$6,380.60
		0088	1260	7171002	PREFORMED COMPRESSION SEAL	185.00	0.00	185.00	LF	0.00	\$95.15	\$0.00
		0001	5001	6122017	IMPACT ATTENUATOR 65 MPH (SAND BARREL ARRAY)	0.00	2.00	2.00	EA	0.00	\$3,417.28	\$0.00
		0001	5002	6122030	IMPACT ATTENUATOR (RELOCATION)	0.00	14.00	14.00	EA	0.00	\$1,257.22	\$0.00
		0001	5003	6122020	REPLACEMENT SAND BARREL	0.00	1.00	1.00	EA	0.00	\$526.52	\$0.00
		0001	5004	6189901	MISC.Contract Bond Payment	0.00	1.00	1.00	LS	1.00	\$18,706.00	\$18,706.00
		0001	5005	9029901	MISC.SIGNAL MODIFICATION	0.00	1.00	1.00	LS	0.50	\$5,224.89	\$2,612.44

Revision 4/1/2020 Page 7 of 14



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200417-C03	J4P3266	0074	5006	7049904	MISC.Clean and Epoxy Seal	0.00	910.00	910.00	SQFT	910.00	\$12.88	\$11,720.80
	Project J4P3266 - Total Value Posted to Date as of Report Generated Date							\$1,121,082.22				
200417-C03 Ove	3 Overall - Total Value Posted to Date as of Report Generated Date									\$1,121,082.22		

Revision 4/1/2020 Page 8 of 14



## Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

## The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J4P3266

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0040	6161005	CONSTRUCTION SIGNS	4/19/21	4/21/21	36.00	SQFT	Euclid Ave., Michigan Ave., and The Paseo	1				
0550	7040101	SUBSTRUCTURE REPAIR (FORMED)	4/27/21	5/3/21	29.00	SQFT	Bents 1 & 5 that were completed on March 26th.	238+15				
			4/30/21	5/3/21	4.00	SQFT	Bent 4 on Bannister Road	238+15				
				5/3/21	42.00	SQFT	Bent 2 on Bannister Road	238+15				
0560	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	4/27/21	5/3/21	-29.00	SQFT	Paid wrong line item.	238+15				
0570	7040104	HALF-SOLE REPAIR	4/22/21	5/3/21	703.00	SQFT	WB Bannister Zone C Bent 2 and 3. 334 SQFT on Bent 2, and 369 on Bent 3.	238+15				
			4/26/21	5/3/21	245.00	SQFT	Special repair zone C, intermediate bent 4. WB Bannister Rd.	1				
			4/27/21	5/3/21	317.50	SQFT	EB Bannister Rd. intermediate bents 2, 3, and 4. Special repair zones "A"	1				
			4/30/21	5/3/21	390.50	SQFT	B Zones's EB Bannister Road	238+15				
0580	7040106	FULL DEPTH REPAIR	4/22/21	5/3/21	199.00	SQFT	WB Bannister Zone C Bent 2 and 3. 79 SQFT on Bent 2 and 120 SQFT on Bent 3.	238+15				
			4/26/21	5/3/21	135.00	SQFT	Special repair zone C, intermediate bent 4. WB Bannister Rd.	1				
			4/27/21	5/3/21	9.00	SQFT	EB Bannister Rd. intermediate bent 4. Special repair zone "A"	1				
			4/30/21	5/3/21	57.00	SQFT	B Zone's EB Bannister Road	238+15				
0840	7110200	PROTECTIVE COATING - CONCRETE BENTS AND	4/22/21	5/3/21	1.00	LS	Soccer Dr. Bents 1 and 3	18+45				
0880	7110200	PROTECTIVE COATING - CONCRETE BENTS AND	4/22/21	5/3/21	1.00	LS	North Oak Bents 1 and 3.	38+50				
1110	2164500	REMOVAL OF EXISTING EXPANSION JOINT &	4/19/21	4/21/21	81.00	LF	West end of bridge.	1.6				
		ADJACENT CONCRETE	4/21/21	4/21/21	81.00	LF	East Side of Linwood.	5+99				
1130	7034214	CLASS B-2 CONCRETE	4/26/21	5/3/21	7.65	CUYD	Joint on west side of bridge, at end bent 1.	1				
			4/29/21	5/3/21	7.65	CUYD	west end expansion joint					
1140	7101000	REINFORCING STEEL (EPOXY COATED)	4/30/21	5/3/21	2,080.00	LB	EB Joint for Linwood	5+99				
1160	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	4/30/21	5/3/21	81.00	LF	WB Joint on Linwood	5+99				
1250	7110200	PROTECTIVE COATING - CONCRETE BENTS AND	4/26/21	5/3/21	1.00	LS	End bents 1 and 3.	1				
5006	7049904	MISC.	4/24/21	5/3/21	910.00	SQFT	South face of box girders from end bent 1 to end bent 5.	1				

Project	Line	DWR Date	Total Quantity Posted For DWR		Sign Information	Station	Log Mile	Location	Number of	SF Each	Special Sign	SF Each Special	Total SF to
4P3266	Number 0040	March 8, 2021	Date 453	special ZONE	??x?? ??.00 NO PASSING		0.005	Drury Ave	1.00	Sign	36x36 Road Work Ahead	9.00	Post
		2021		special	??x?? ??.00 NO PASSING		0.005	Marian Park	1.00		36x36 Road Work Ahead	9.00	
					??x?? ??.00 NO PASSING		0.068	Freemont	1.00		36x36 Road Work Ahead	9.00	
					??x?? ??.00 NO PASSING		0.104	Drury Ave.	1.00		36x36 Road Work Ahead	9.00	
					??x?? ??.00 NO PASSING		0.287	95th Terr.	1.00		36x36 Road Work Ahead	9.00	
				ZONE special ZONE	??x?? ??.00 NO PASSING		0.697	Belmont	1.00		36x36 Road Work Ahead	9.00	
					??x?? ??.00 NO PASSING		0.94	EB 87th	1.00		24x12 Detour	2.00	
					??x?? ??.00 NO PASSING		0.94	EB 87th	1.00		21x15 Arrow	2.19	2.
					??x?? ??.00 NO PASSING		0.94	EB 87th	1.00		24x24 State Marker	4.00	
					??x?? ??.00 NO PASSING		1.028	Marian Dr.	1.00		36x36 Road Work Ahead	9.00	
					??x?? ??.00 NO PASSING		1.0335	Hillcrest Rd.	1.00		36x36 Road Work Ahead	9.00	
					??x?? ??.00 NO PASSING		1.536	EB 87th	1.00		24x12 Detour	2.00	
					??x?? ??.00 NO PASSING		1.536	EB 87th	1.00		21x15 Arrow	2.19	2
					??x?? ??.00 NO PASSING		1.536	EB 87th	1.00		24x24 State Marker	4.00	
					??x?? ??.00 NO PASSING		1.585	EB 87th	1.00		24x12 Detour	2.00	
					??x?? ??.00 NO PASSING		1.585	EB 87th	1.00		21x15 Arrow	2.19	2
				special ZONE	??x?? ??.00 NO PASSING		1.585	EB 87th	1.00		24x24 State Marker	4.00	
				special ZONE	??x?? ??.00 NO PASSING		1.633	EB 87th	1.00		24x12 Detour	2.00	
				special ZONE	??x?? ??.00 NO PASSING		1.633	EB 87th	1.00		21x15 Arrow	2.19	2.
				special ZONE	??x?? ??.00 NO PASSING		1.633	EB 87th	1.00		24x24 State Marker	4.00	
				special ZONE	??x?? ??.00 NO PASSING		124.355	SB US 71	1.00		24x12 Detour	2.00	
				special ZONE	??x?? ??.00 NO PASSING		124.355	SB US 71	1.00		24x12 South	2.00	
				special ZONE	??x?? ??.00 NO PASSING		124.355	SB US 71	1.00		21x15 Arrow	2.19	2.
				special ZONE	??x?? ??.00 NO PASSING		124.355	SB US 71	1.00		30x24 Interstate Marker	5.00	
				special ZONE	??x?? ??.00 NO PASSING		129.559	SB US 71	1.00		24x12 Detour	2.00	
				special ZONE	??x?? ??.00 NO PASSING		129.559	SB US 71	1.00		24x12 South	2.00	
				special ZONE	??x?? ??.00 NO PASSING		129.559	SB US 71	1.00		21x15 Arrow	2.19	2.
				special ZONE	??x?? ??.00 NO PASSING		129.559	SB US 71	1.00		30x24 Interstate Marker	5.00	
				special ZONE	??x?? ??.00 NO PASSING		2.045	Hillcrest	1.00		36x36 Road Work Ahead	9.00	

Revision 4/1/2020 Page 9 of 14



## Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

ect Line Number	DWR Date	are details for Construction  Total Quantity Posted For DWR Date		Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF Post
266 0040	March 8, 2021	453	special ZONE	??x?? ??.00 NO PASSING		3.955	EB Banister Rd.	2.00	9	36x36 Road Work Ahead	9.00	
				??x?? ??.00 NO PASSING		4.048	EB Banister Rd.	2.00		24x36 WZ Speed Limit	6.00	
			R3-7L	30x30 6.25 LEFT LANE URN LEFT		4.099	EB Banister Rd.	1.00	6.25			6
			R3-7L	30x30 6.25 LEFT LANE URN LEFT		4.196	EB Banister Rd.	1.00	6.25			6
			R3-7L	30x30 6.25 LEFT LANE URN LEFT		4.229	EB Banister Rd.	1.00	6.25			6
			R3-7L	30x30 6.25 LEFT LANE URN LEFT		4.23	EB Banister Rd.	1.00	6.25			
			special ZONE	??x?? ??.00 NO PASSING		4.286	EB Banister Rd.	1.00		24x12 Detour	2.00	
			special ZONE	??x?? ??.00 NO PASSING		4.286	EB Banister	1.00		21x15 Arrow	2.19	
				??x?? ??.00 NO PASSING		4.286	EB Banister Rd.	1.00		24x24 State Marker	4.00	
			special	??x?? ??.00 NO PASSING		4.286	EB Banister Rd.	1.00		48x24 Semi Trucks	8.00	
				48x48 16.00 NO LEFT TURN		4.286	EB Banister Rd.	1.00	16			
			WO20-2			4.325	NB 435	1.00	16			
			AHEAD	??x?? ??.00 NO PASSING		4.509	NB 435	1.00		24x12 Detour	2.00	
			ZONE	??x?? ??.00 NO PASSING		4.509	NB 435	1.00		21x15 Arrow	2.19	
			ZONE	??x?? ??.00 NO PASSING		4.509	NB 435	1.00		24x24 State Marker	4.00	
			ZONE WO20-1	48x48 16.00		4.695	NB 435	1.00	16			
			ROAD/B special	RIDGE/RAMP WORK AHEAD  ??x?? ??.00 NO PASSING		4.972	NB 435	1.00		24x12 Detour	2.00	
			ZONE	??x?? ??.00 NO PASSING		4.972	NB 435	1.00		21x15 Arrow	2.19	
			ZONE	??x?? ??.00 NO PASSING		4.972	NB 435	1.00		24x24 State Marker	4.00	
			ZONE			49.992	SB 435	1.00		24x12 Detour	2.00	
			ZONE	??x?? ??.00 NO PASSING ??x?? ??.00 NO PASSING		49.992	SB 435	1.00		21x15 Arrow	2.19	
			ZONE									
			zone	??x?? ??.00 NO PASSING		49.992	SB 435	1.00		24x24 State Marker	4.00	
			zone zone	??x?? ??.00 NO PASSING		5.701	WB Banister Rd.	1.00		36x36 Road Work Ahead	9.00	
			zone zone	??x?? ??.00 NO PASSING		5.734	NB 435	1.00		24x12 Detour	2.00	
			special ZONE	??x?? ??.00 NO PASSING		5.734	NB 435	1.00		21x15 Arrow	2.19	
			special ZONE	??x?? ??.00 NO PASSING		5.734	NB 435	1.00		24x24 State Marker	4.00	
			special ZONE	??x?? ??.00 NO PASSING		5.773	WB Banister Rd.	1.00		36x36 Left Lane Closed Ahead	9.00	
			special ZONE	??x?? ??.00 NO PASSING		5.778	WB Banister Rd.	1.00		36x36 Left Lane Closed	9.00	
			special ZONE	??x?? ??.00 NO PASSING		5.925	NB 435	1.00		24x12 Detour	2.00	
			special ZONE	??x?? ??.00 NO PASSING		5.925	NB 435	1.00		21x15 Arrow	2.19	
			special ZONE	??x?? ??.00 NO PASSING		5.925	NB 435	1.00		24x24 State Marker	4.00	
			special ZONE	??x?? ??.00 NO PASSING		5.944	WB Banister Rd.	1.00		24x36 WZ Speed Limit	6.00	
			WO20-1 ROAD/B	48x48 16.00 RIDGE/RAMP WORK AHEAD		50.21	SB 435	1.00	16			
				24x18 3.00 END DETOUR		50.215	SB 435	1.00	3			
			special	24x18 3.00 END DETOUR ??x?? ??.00 NO PASSING		51.833 6.056	SB 435 WB Banister Rd.	1.00	3	30x30 Double Down	6.25	
			ZONE	??x?? ??.00 NO PASSING		6.256	WB Banister Rd.	2.00		36x36 Left Lane Closed Ahead	9.00	
			ZONE	??x?? ??.00 NO PASSING		6.288	WB Banister Rd.	1.00		36x36 Detour Ahead	9.00	
			ZONE	??x?? ??.00 NO PASSING		6.355	WB Banister Rd.	1.00		30x30 Double Down	6.25	
			ZONE	??x?? ??.00 NO PASSING		6.405	WB Banister Rd.	1.00		30x30 Double Down	6.25	
			ZONE	??x?? ??.00 NO PASSING		6.405	WB Banister Rd.	1.00		36x36 Left Lane Closed	9.00	
			ZONE	??x?? ??.00 NO PASSING		6.405	WB Banister Rd.	1.00		36x36 Merge	9.00	
			ZONE	??x?? ??.00 NO PASSING		6.453	WB Banister Rd.	1.00		30x30 Double Down	6.25	
			ZONE	??x?? ??.00 NO PASSING		6.601	WB Banister Rd.	1.00		24x12 Detour	2.00	
			ZONE	??x?? ??.00 NO PASSING		6.601	WB Banister Rd.	1.00		24x12 Detour 24x12 South	2.00	
			ZONE									
			special ZONE	??x?? ??.00 NO PASSING		6.601	WB Banister Rd.	1.00		21x15 Arrow	2.19	
				00 00 00 00 1:= = : = : :								
			special ZONE	??x?? ??.00 NO PASSING		6.601	WB Banister Rd.	1.00		30x24 Interstate Marker	5.00	
			ZONE special ZONE	??x?? ??.00 NO PASSING  ??x?? ??.00 NO PASSING  ??x?? ??.00 NO PASSING		6.601 6.624 7.192	WB Banister Rd.  WB Banister Rd.  WB Banister Rd.	1.00		30x24 Interstate Marker 36x36 No Left Turn 24x12 Detour	9.00 2.00	



### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line are details for Construction Signs (if published).

March N.   423   2006   2007	ct Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF Post
2021   2021		March 8		ZONE				Ittellia	Oigii		Oign	1 031
### 2016   187   1	30 0040	2021	100			7 192	WB Banister Rd	1.00		21x15 Arrow	2 19	
April 12, 2021   388   Second Spr Debte   10.0   10   10   10   10   10   10												
SYMBOL PECKEN ROLF)						7.192	WB Banister Rd.	1.00		30x24 Interstate Marker	5.00	
NO.		March 16, 2021	187	WO4-1aR 48x48 16.00 MERGE (SYMBOL FROM RIGHT)		49.319	SB 435	1.00	16			
### NGFITCH TEMPELET LANE CLOSED Wh-1469, 48-88 1000 MRFREDE ### 1500 4 48-88 1000 MRFREDE ### 1500 MRFREDE						49.079	SB 435	2.00	12			
### ### ### ### ### ### ### ### ### ##						48.911	SB 435	1.00	16			
### WOOD-1 #Bole 15:00   NOADSPROCEREAD WORK AREAD   48.255   58.455   1.00   16				W4-1(48) 48x48 16.00 MERGE		48.911	SB 435	1.00	16			
NOLDERFORDERAMP WORK AMED   0.202   EB STH RAMP TO 435 S   100   16				EO5-2 48x36 12.00 EXIT OPEN		50.109	SB 435	1.00	12			
APEAD				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		48.255	SB 435	2.00	16			
ROADGREGERAMP WORK AFAEAD R1-2 48TH 639 YELD A9478 12, 2021  388 S9 Special Sign Details See Spe				W3-2A(48) 48x48 16.00 YIELD AHEAD		0.202	EB 87TH RAMP TO 435 S	1.00	16			
### NODE # 46-66 16:00   RIGHTCENTET (JAME CLOSED AHEAD   APERIOT CAPET (JAME CLOSED A				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		0.145	EB 87TH RAMP TO 435 S	1.00	16			
### RIGHTICHYRELEFT LANE CLOSED AFFERD ### A				R1-2 48 TRI 6.93 YIELD		49.476	SB 435	1.00	6.93			
See Special Sign Details				RIGHT/CENTER/LEFT LANE CLOSED		48.591	SB 435	2.00	16			
See Special Sign Details		April 12, 2021	368	See Special Sign Details		1.1 to 1.82	EB and WB Linwood	2.00		Road Closed Ahead 36"x36"	9.00	
See Special Sign Details   0.957   EB Linwood Bivd   1.00   Road Work Ahead 36°x36°   9.00				See Special Sign Details		1.034	EB Linwood Blvd	1.00		Right Lane Closed Ahead 36"x36"	9.00	
See Special Sign Details				See Special Sign Details		1	Flora, Woodland, and Highland	4.00		Road Work Ahead 36"x36"	9.00	
See Special Sign Details   0.362   SB Michigan Ave   2.00   No Left Turn 24"x24"   4.00				See Special Sign Details		0.957	EB Linwood Blvd	1.00		Road Work Ahead 36"x36"	9.00	
See Special Sign Details				See Special Sign Details		0.833	NB Euclid Ave	2.00		No Left Turn 24"x24"	4.00	
See Special Sign Details				See Special Sign Details		0.362	SB Michigan Ave	2.00		No Left Turn 24"x24"	4.00	
See Special Sign Details				See Special Sign Details		0.352	SB Garfield Ave.	1.00		Road Work Ahead 36"x36"	9.00	
See Special Sign Details				See Special Sign Details		0.349	SB Wayne Ave	1.00		Road Work Ahead 36"x36"	9.00	
See Special Sign Details				See Special Sign Details		1.109	EB Linwood Blvd	1.00		Right Lane Closed 36"x36"	9.00	
R114 60x30 12:50 ROAD   1.287 to 2.099   Linwood Blvd on barricades   4.00   12.5				See Special Sign Details		1.275	EB 31st St.	1.00		Detour Up Arrow 30"x24"	5.00	
CLOSED TO THRU TRAFFIC   See Special Sign Details   1.479   EB 31st St   1.00   Detour Right Arrow 30"x24"   5.00   See Special Sign Details   1.516 to 2.892   NB and SB Brooklyn Ave.   2.00   Road Work Ahead 36"x36"   9.00				See Special Sign Details			Linwood Blvd on barricades	2.00		Detour 48"x18"	6.00	
See Special Sign Details						1.287 to 2.099	Linwood Blvd on barricades	4.00	12.5			
R11.2 48x30 10.00 ROAD   1.591 to 2.17   Linwood Blvd on barricades   2.00   10     10				See Special Sign Details		1.479	EB 31st St	1.00		Detour Right Arrow 30"x24"	5.00	
CLOSED				See Special Sign Details		1.516 to 2.892	NB and SB Brooklyn Ave.	2.00		Road Work Ahead 36"x36"	9.00	
See Special Sign Details   1.82   WB Linwood Blvd   1.00   Road Work Ahead 36"x36"   9.00						1.591 to 2.17	Linwood Blvd on barricades	2.00	10			
See Special Sign Details				See Special Sign Details		1.646	NB Brooklyn Ave.	1.00		Detour Left Arrow 30"x24"	5.00	
See Special Sign Details				See Special Sign Details		1.82	WB Linwood Blvd	1.00		Road Work Ahead 36"x36"	9.00	
WO20-1 48x48 16.00   ROADBRIDGE/RAMP WORK AHEAD   120.4   SB 71 Hwy   2.00   16   ROADBRIDGE/RAMP WORK AHEAD   120.45   SB 71 Hwy   2.00   Right Shoulder Closed Ahead   16.00   46°x46°   46°x46°   6.00   62°x46°				See Special Sign Details		1.847	WB Linwood Blvd	1.00		Right Lane Closed Ahead 36"x36"	9.00	
ROAD/BRIDGE/RAMP WORK AHEAD										Right Lane Closed 36"x36"	9.00	
See Special Sign Details   120.5 SB 71 Hwy   2.00 Right Shoulder Closed 46"x48"   16.00				ROAD/BRIDGE/RAMP WORK AHEAD			·		16			
See Special Sign Details   2.45   WB 31st St.   0.00   Detour Up Arrow 30"x24"   0.00										48"x48"		
See Special Sign Details   2.455   WB 31st St   1.00   Detour Up Arrow 30"x24"   5.00												
See Special Sign Details         2.834         WB 31st St         1.00         Detour Left Arrow 30"x24"         5.00           See Special Sign Details         4.014         NE The Paseo         1.00         Detour Right Arrow 30"x24"         5.00           April 19, 2021         36         See Special Sign Details         1.657 to 2.546         Euclid, Michigan, and 2x The         4.00         Road Work Ahead 36"x36"         9.00												
See Special Sign Details         4.014         NE The Paseo         1.00         Detour Right Arrow 30"x24"         5.00           April 19, 2021         36         See Special Sign Details         1.657 to 2.546         Euclid, Michigan, and 2x The         4.00         Road Work Ahead 36"x36"         9.00												
April 19, 2021 36 See Special Sign Details 1.657 to 2.546 Euclid, Michigan, and 2x The 4.00 Road Work Ahead 36"x36" 9.00												
April 19, 2021 36 See Special Sign Details 1.657 to 2.546 Euclid, Michigan, and 2x The Pase 4.00 Road Work Ahead 36"x36" 9.00												
		April 19, 2021	36	See Special Sign Details		1.657 to 2.546	Euclid, Michigan, and 2x The Paseo	4.00		Road Work Ahead 36"x36"	9.00	

Revision 4/1/2020 Page 11 of 14



## Line Item Adjustments by Estimate

Contract ID:190315-C01

n		5		011		0 1 1	0 1 1		0 1
Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
4P3266	0070	CHANNELIZER (TRIM LINE)	Overrun	Overrun	7	Mar 16, 2021	SYSTEM	(\$515.00)	
					8	Apr 2, 2021	SYSTEM	(\$5,665.00)	
					9	Apr 16, 2021	SYSTEM	\$6,180.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',51.50000 - 51.50000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - Tota	al				\$0.00	
	0070 -	Total						\$0.00	
	0240	MGS GUARDRAIL	Construction Stockpile		2	Sep 16, 2020	SYSTEM	\$4,775.50	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMA	- Total				\$4,775.50	
			Construction	Stockpile STI	MA - Total			\$4,775.50	
			Construction Stockpile		2	Sep 16, 2020	SYSTEM	\$46,935.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$46,935.00	
			Construction	Stockpile STI	VII - Total			\$46,935.00	
	0240 -	Total						\$51,710.50	
	0250	MGS BRIDGE APP. TRANS	Construction Stockpile		2	Sep 16, 2020	SYSTEM	\$14,940.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		SEC (REG/NO CURB)	STMI	- Total				\$14,940.00	
			Construction Stockpile STMI - Total					\$14,940.00	
	0250 -	Total						\$14,940.00	
	0270	TYPE A CRSHWTHY END TERMINAL (MASH)	Construction Stockpile STMI		2	Sep 16, 2020	SYSTEM	\$1,507.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$1,507.00	
			Construction	Stockpile STI	VII - Total			\$1,507.00	
	0270 -	Total						\$1,507.00	
	0470	CURB BLOCKOUT	Construction Stockpile STMI		5	Nov 2, 2020	SYSTEM	\$324.55	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$324.55	
			Construction Stockpile STMI - Total					\$324.55	
	0470 -	Total						\$324.55	
	0500	REINFORCING STEEL (EPOXY COATED)	Construction Stockpile STMI		5	Nov 2, 2020	SYSTEM	\$526.23	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$526.23	
			Construction Stockpile STMI - Total					\$526.23	
		CLASS B-1 CONCRETE						\$526.23	
	0540		Material	2		Apr 2, 2021	SYSTEM	(\$56,486.02)	
				- Total				(\$56,486.02)	
			Material - Tota MaterialCredit	ıl	9	Apr 16,	SYSTEM	(\$56,486.02) \$56,486.02	
						2021		ATA 100 00	
			Makari 10 atte	- Total				\$56,486.02	
	0540	Takal	MaterialCredit	- Iotal				\$56,486.02	
		Total	Material		0	A C	0)/07=:	\$0.00	
	0550	SUBSTRUCTURE REPAIR (FORMED)	Material		10	Apr 2, 2021	SYSTEM	(\$4,702.35)	
				- Total	10	May 3, 2021	SISIEM	(\$12,161.25)	
			Material - Tota					(\$16,863.60)	
			Material - Tota		9	Apr 16, 2021	SYSTEM	\$4,702.35	
				- Total				\$4,702.35	



## Line Item Adjustments by Estimate

## Contract ID:190315-C01

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1P3266	0550	SUBSTRUCTURE REPAIR (FORMED)	MaterialCredit	- Total				\$4,702.35	
	0550 -	Total						(\$12,161.25)	
	0570	HALF-SOLE REPAIR	Overrun	Overrun	8	Apr 2, 2021	SYSTEM	(\$7,748.35)	
					9	Apr 16, 2021	SYSTEM	\$7,748.35	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is applied (if non-zero).
					10	May 3, 2021	SYSTEM	(\$14,179.70)	
				Overrun - T	otal			(\$14,179.70)	
			Overrun - Tota	d				(\$14,179.70)	
	0570 -	Total						(\$14,179.70)	
	0580	FULL DEPTH REPAIR	Overrun	Overrun	9	Apr 16, 2021	SYSTEM	(\$8,389.70)	
					10	May 3, 2021	SYSTEM	\$8,389.70	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',63.80000 - 63.80000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - Tota	d				\$0.00	
	0580 -	Total						\$0.00	
	0590	REINFORCING STEEL (EPOXY COATED)	Construction Stockpile		8	Apr 2, 2021	SYSTEM	(\$2,855.51)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$2,855.51)	
			Construction	Stockpile - To	tal			(\$2,855.51)	
			Construction Stockpile STMI		5	Nov 2, 2020	SYSTEM	\$2,855.51	Payment Estimate Item Adjustment generated Stockpile Transaction
			011111	- Total				\$2,855.51	
			Construction	Stockpile STI	MI - Total			\$2,855.51	
			Material		8	Apr 2, 2021	SYSTEM	(\$9,202.00)	
				- Total				(\$9,202.00)	
			Material - Tota	l				(\$9,202.00)	
			MaterialCredit		9	Apr 16, 2021	SYSTEM	\$9,202.00	
				- Total				\$9,202.00	
			MaterialCredit - Total					\$9,202.00	
	0590 - 0620		Construction		5	Nov 2,	SYSTEM	\$0.00 \$2,816.11	Payment Estimate Item Adjustment generated Stockpile Transaction
		BLOCKOUT	Stockpile STMI	- Total		2020		\$2,816.11	
			Construction S	Construction Stockpile STMI - Total				\$2,816.11	
	0620 -	Total						\$2,816.11	
	0670	CURB BLOCKOUT	Construction Stockpile		5	Nov 2, 2020	SYSTEM	\$2,816.11	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$2,816.11	
			Construction	Stockpile STI	VII - Total			\$2,816.11	
	0670 -	Total						\$2,816.11	
	0720	CURB BLOCKOUT	Construction Stockpile STMI		5	Nov 2, 2020	SYSTEM	\$1,875.85	Payment Estimate Item Adjustment generated Stockpile Transaction
			O I IVII	- Total				\$1,875.85	
			Construction	Stockpile STI	VII - Total			\$1,875.85	
	0720 -	Total						\$1,875.85	
	0780	CURB BLOCKOUT	Construction Stockpile STMI		5	Nov 2, 2020	SYSTEM	\$1,875.85	Payment Estimate Item Adjustment generated Stockpile Transaction
			STIVII	- Total				\$1,875.85	
			Construction	Stockpile STI	MI - Total			\$1,875.85	



## Line Item Adjustments by Estimate

Contract ID:190315-C01

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3266	0780 -	Total						\$1,875.85	
	0930	REINFORCING STEEL (EPOXY	Construction Stockpile		5	Nov 2, 2020	SYSTEM	\$484.82	Payment Estimate Item Adjustment generated Stockpile Transaction
		COATED)	STMI	- Total				\$484.82	
			Construction	Stockpile STI	MI - Total			\$484.82	
	0930 -	Total						\$484.82	
	0950	STRIP SEAL EXPANSION JOINT SYSTEM	Construction Stockpile STMI		3	Oct 1, 2020	SYSTEM	\$13,856.25	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$13,856.25	
			Construction	Stockpile STI	VII - Total			\$13,856.25	
	0950 -							\$13,856.25	
	1080	REINFORCING STEEL (EPOXY COATED)	Construction Stockpile STMI		5	Nov 2, 2020	SYSTEM	\$1,712.91	Payment Estimate Item Adjustment generated Stockpile Transaction
			0 ( 1)	- Total				\$1,712.91	
	4000	Total	Construction	Stockpile STI	VII - I otal			\$1,712.91	
	1080 -		0 1 "			0.11	0)/0==-	\$1,712.91	2 15 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	1100	STRIP SEAL EXPANSION JOINT SYSTEM	Construction Stockpile STMI		3	Oct 1, 2020	SYSTEM	\$38,590.03	Payment Estimate Item Adjustment generated Stockpile Transaction
			0 ( 1)	- Total				\$38,590.03	
			Construction	Stockpile STI	VII - Total			\$38,590.03	
	1100 -							\$38,590.03	
	1140	REINFORCING STEEL (EPOXY COATED)	Construction Stockpile		10	May 3, 2021	SYSTEM	(\$1,390.36)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total					(\$1,390.36)	
			Construction	Stockpile - To				(\$1,390.36)	
			Construction Stockpile STMI	Total	5	Nov 2, 2020	SYSTEM	\$1,390.36	Payment Estimate Item Adjustment generated Stockpile Transaction
			O a mademus di a m	- Total Stockpile STMI - Total				\$1,390.36	
	1140 -	Total	Construction	Stockpile STI	vii - Totai			\$1,390.36 \$0.00	
			Construction		10	May 2	CVCTEM		Downant Catimate Ham Adjustment generated Stackails Transaction
	1160	STRIP SEAL EXPANSION JOINT SYSTEM	Construction Stockpile	- Total	10	May 3, 2021	SYSTEM	(\$17,280.62) (\$17,280.62)	Payment Estimate Item Adjustment generated Stockpile Transaction
			Construction		ntal			(\$17,280.62)	
			Construction Stockpile - To Construction Stockpile		3	Oct 1, 2020	SYSTEM	\$34,561.25	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$34,561.25	
			Construction Stockpile STMI - Total					\$34,561.25	
	1160 -	Total						\$17,280.63	
	1210	REINFORCING STEEL (EPOXY	Construction Stockpile		5	Nov 2, 2020	SYSTEM	\$1,931.95	Payment Estimate Item Adjustment generated Stockpile Transaction
		COATED)	STMI	- Total				\$1,931.95	
			Construction	Stockpile STI	MI - Total			\$1,931.95	
	1210 -	Total						\$1,931.95	
	1230	STRIP SEAL EXPANSION JOINT SYSTEM	Construction Stockpile		3	Oct 1, 2020	SYSTEM	\$38,590.03	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total	- Total			\$38,590.03	
			Construction	Stockpile STI	VII - Total			\$38,590.03	
	1230 -	Total						\$38,590.03	
J4P3266 -	Total							\$164,497.87	
Overall -	Total							\$164,497.87	