

#### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: May 2, 2022

Progress Estimate Number	Contract ID	200417-C03	Pay Period Start	April 16, 2022	Original Contract Amount	\$4,099,005.37
29	<b>Prime Contractor</b>	Comanche Construction, Inc.	Pay Period End	May 1, 2022	<b>Net Change Order Amount</b>	\$1,510,827.92
25					Current Contract Amount	\$5,609,833.29

Approval Date		By User
May 2, 2022	Generated and Approved (and should be considered Draft) at the Project Office Level by	baldwc2
May 2, 2022	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	penner1
May 3, 2022	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
November 5, 2021	August 26, 2022		86.93%

	Contract Informational Dates									
Date Description	Original Completion Date	<b>Current Completion Date</b>	No Milestones Exist for Contract							
Acceptance Date										
Awarded Date	May 6, 2020	May 6, 2020								
Letting Date	May 4, 2020	May 4, 2020								
Notice to Proceed Date	July 6, 2020	July 6, 2020								
Open to Traffic Date										
Work Began Date	March 8, 2021	March 8, 2021								

Contract Total Pay For Estimate No. 29			
	This Estimate	Previous	To Date
200417-C03			
Total Posted Items Pay	\$89,813.03	\$4,787,075.93	\$4,876,888.96
Gross Item Adjustments	(\$7,735.40)	\$45,239.40	\$37,504.00
Incentive	\$0.00	\$0.00	\$0.00
Disincentive	\$0.00	\$0.00	\$0.00
Liquidated Damage	\$0.00	\$0.00	\$0.00
Other Contract Adjustments	\$0.00	\$0.00	\$0.00
		\$4,832,315.33	\$4,914,392.96
Contract Total Payable This Estimate:	\$82,077.63		

#### **Items Paid This Estimate Period**

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount			
J4P3266	0030	4030007	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP095BSM MIX)	TONS	\$432.800	56.98	\$24,660.94			
	0240	6061060	MGS GUARDRAIL	LF	\$19.050	525	\$10,001.25			
	0250	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	EA	\$2,833.750	2	\$5,667.50			
	0270	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	EA	\$2,627.650	2	\$5,255.30			
	0660	5050001	OPTIONAL CONCRETE WEARING SURFACE	SQYD	\$91.800	433	\$39,749.40			
	5009	4071005	TACK COAT	GAL	\$2.630	78	\$205.14			
	5025	6069902	MISC.DUARDRAIL POSTS DRILLED IN CONCRETE FLUMES	EA	\$194.250	22	\$4,273.50			
Project J4P3	3266 - Total						\$89,813.03			
Overall - Tot	Overall - Total									

### Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

	ine Item Adjustments This Estimate													
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount						
J4P3266	3266 0240 MGS GUARDRAIL Constructi Stockp		Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$4,746.98)						
	0250	MGS BRIDGE APPROACH TRANSITION SECTION	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$2,988.12)						

Revision 4/1/2020 Page 1 of 22



### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: May 2, 2022

Progress Estimate Number	Contract ID	200417-C03	Pay Period Start	April 16, 2022	Original Contract Amount	\$4,099,005.37
29	Prime Contractor	Comanche Construction, Inc.	Pay Period End			
					Current Contract Amount	\$5,609,833.29

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4P3266		(REGULAR/NO CURB)						
	0270	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$0.30)
Total								(\$7,735.40)


Revision 4/1/2020 Page 2 of 22



### Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(	Contract Project Information	
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J4P3266	FAS S302(002)	Bridge Rehabilitation	Various	VARIOUS	at various locations th	roughout the urban Kansas C	City district
Totals by	Job Number	s					
J4P3266					This Estimate	Previous	To Date
J4P3266	Posted	Item Pay			This Estimate \$89,813.03	Previous \$4,787,075.93	<b>To Date</b> \$4,876,888.96
J4P3266		Item Pay tem Adjustmen	nts				
J4P3266		tem Adjustmen	nts Gross Ite	m Pay	\$89,813.03	\$4,787,075.93	\$4,876,888.96
J4P3266		tem Adjustmen		m Pay	\$89,813.03 (\$7,735.40)	\$4,787,075.93 \$45,239.40	\$4,876,888.96 \$37,504.00
J4P3266	Gross I	tem Adjustmen		m Pay	\$89,813.03 (\$7,735.40) <b>\$82,077.63</b>	\$4,787,075.93 \$45,239.40 <b>\$4,832,315.33</b>	\$4,876,888.96 \$37,504.00 <b>\$4,914,392.96</b>
J4P3266	Gross I	tem Adjustmen		em Pay	\$89,813.03 (\$7,735.40) <b>\$82,077.63</b> \$0.00	\$4,787,075.93 \$45,239.40 <b>\$4,832,315.33</b> \$0.00	\$4,876,888.96 \$37,504.00 <b>\$4,914,392.96</b> \$0.00

Revision 4/1/2020 Page 3 of 22





# Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

## Exceptions (Discrepancies) This Estimate Period No Exceptions Exist on Contract

Revision 4/1/2020 Page 4 of 22



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note: Posted Q	luantities	and valu	es are b	ased on R	eport Generated date and can differ from the posted am	ount at the	time the E	stimate was	Genera	ated.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200417-C03	J4P3266	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS		\$113,120.00	\$56,560.00
		0001	0020	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	153.00	-153.00	0.00	SQFT	0.00	\$67.35	\$0.00
		0001	0030	4030007	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP095BSM MIX)	231.20	0.00	231.20	TONS	152.08	\$432.80	\$65,820.22
		0001	0040	6161005	CONSTRUCTION SIGNS	1,078.00	250.00	1,328.00	SQFT	1,328.00	\$19.60	\$26,028.80
		0001	0050	6161008	ADVANCED WARNING RAIL SYSTEM	8.00	-4.00	4.00	EA	4.00	\$309.15	\$1,236.60
		0001	0060	6161009	FLAG ASSEMBLY	8.00	-8.00	0.00	EA	0.00	\$103.05	\$0.00
		0001	0070	6161025	CHANNELIZER (TRIM LINE)	210.00	120.00	330.00	EA	330.00	\$51.50	\$16,995.00
		0001 0080	0080	6161030	TYPE III MOVEABLE BARRICADE	16.00	0.00	16.00	EA	16.00	\$412.20	\$6,595.20
		0001	0090	6161040	FLASHING ARROW PANEL	4.00	0.00	4.00	EA	4.00	\$5,152.30	\$20,609.20
		0001	0100	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	4.00	\$17,002.60	\$68,010.40
		0001	0105	6162000A	WORK ZONE TRAFFIC SIGNAL SYSTEM	1.00	0.00	1.00	EA	1.00	\$7,728.45	\$7,728.45
		0001	0110	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	1,230.00	3,286.00	4,516.00	LF	3,812.50	\$19.75	\$75,296.88
		0001	0120	6173700B	TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED	1,289.00	1,058.00	2,347.00	LF	1,630.00	\$29.75	\$48,492.50
		0001	0130	6174000A	TEMPORARY TRAFFIC BARRIER HEIGHT TRANSITION	6.00	0.00	6.00	EA	6.00	\$497.85	\$2,987.10
		0001	0140	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	6,444.00	-2,679.00	3,765.00	LF	1,907.50	\$9.95	\$18,979.62
		0001	0150	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$406,875.00	\$0.00
		0001	0151	6181000	MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$388,169.00	\$388,169.00
		0001	0160	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	16.00	-4.00	12.00	EA	12.00	\$257.60	\$3,091.20
		0001	0170	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	4,271.00	7,759.00	12,030.00	LF	10,378.00	\$0.30	\$3,113.40
		0001	0180	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	1,458.00	4,197.00	5,655.00	LF	4,559.00	\$0.30	\$1,367.70
		0001	0190	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,640.00	-300.00	1,340.00	LF	1,340.00	\$0.15	\$201.00
		0001	0200	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	5,071.00	-1,881.00	3,190.00	LF	3,190.00	\$0.15	\$478.50
		0001	0210	6207001	PAVEMENT MARKING REMOVAL	20,939.00	51,308.00	72,247.00	LF	67,785.00	\$2.25	\$152,516.25
		0001	0220	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	18,663.00	50,786.00	69,449.00	LF	57,901.00	\$2.25	\$130,277.25
		0001	0230	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	2,534.00	153.20	2,687.20	SQYD	1,420.70	\$26.50	\$37,648.55
		0010	0240	6061060	MGS GUARDRAIL	5,588.00	25.00	5,613.00	LF	2,700.00	\$19.05	\$51,435.00
		0010	0250	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	12.00	0.00	12.00	EA	6.00	\$2,833.75	\$17,002.50
		0010	0260	6061080	MGS END ANCHOR	2.00	0.00	2.00	EA	1.00	\$875.90	\$875.90
		0010	0270	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	6.00	0.00	6.00	EA	3.00	\$2,627.65	\$7,882.95
		0070	0280	2161502	REMOVAL OF CONCRETE WEARING SURFACE	8,665.00	0.00	8,665.00	SQFT	8,665.00	\$2.80	\$24,262.00
		0070	0290	2165500	REMOVAL OF CATHODIC PROTECTION SYSTEM	1.00	0.00	1.00	LS	1.00	\$1,818.40	\$1,818.40
		0070	0300	5050001	OPTIONAL CONCRETE WEARING SURFACE	963.00	0.00	963.00	SQYD	963.00	\$91.80	\$88,403.40
		0070	0310	7040104	HALF-SOLE REPAIR	450.00	2,125.00	2,575.00	SQFT	2,575.00	\$43.90	\$113,042.50
		0071	0320	2161502	REMOVAL OF CONCRETE WEARING SURFACE	8,665.00	0.00	8,665.00	SQFT	8,665.00	\$2.80	\$24,262.00
		0071	0330	2165500	REMOVAL OF CATHODIC PROTECTION SYSTEM	1.00	0.00	1.00	LS	1.00	\$1,818.40	\$1,818.40
		0071	0340	5050001	OPTIONAL CONCRETE WEARING SURFACE	963.00	0.00	963.00	SQYD	963.00	\$91.80	\$88,403.40
		0071	0350	7040104	HALF-SOLE REPAIR	450.00	7,322.00	7,772.00	SQFT	7,772.00	\$43.90	\$341,190.80
		0072	0360	2161502	REMOVAL OF CATHODIC PROTECTION SYSTEM	8,230.00	0.00	8,230.00	SQFT	8,230.00	\$2.80	\$23,044.00
		0072	0370	2165500	REMOVAL OF CATHODIC PROTECTION SYSTEM	1.00	0.00	1.00	LS	1.00	\$1,818.40	\$1,818.40
		0072	0380	5050001	OPTIONAL CONCRETE WEARING SURFACE	914.00	0.00	914.00	SQYD	914.00	\$91.80	\$83,905.20
		0072	0390	7040104	HALF-SOLE REPAIR	400.00	1,212.00	1,612.00	SQFT	1,612.00	\$43.90	\$70,766.80
		0072	0400	7040106	FULL DEPTH REPAIR	100.00	-28.00	72.00	SQFT	72.00	\$63.80	\$4,593.60
		0073	0410	2161502	REMOVAL OF CONCRETE WEARING SURFACE	9,330.00	0.00	9,330.00	SQFT	9,330.00	\$2.60	\$24,258.00
		0073	0420	2163502	PARTIAL REMOVAL OF SUBSTRUCTURE CONCRETE	1.00	0.00	1.00	LS	1.00	\$11,742.65	\$11,742.65

Page 5 of 22 Revision 4/1/2020



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
J4P3266	0073	0430	2164000	CURB REMOVAL	10.00	0.00	10.00	LF	10.00	\$275.85	\$2,758.50
	0073	0440	2165500	REMOVAL OF CATHODIC PROTECTION SYSTEM	1.00	0.00	1.00	LS	1.00	\$1,818.40	\$1,818.40
	0073	0450	5050001	OPTIONAL CONCRETE WEARING SURFACE	1,037.00	0.00	1,037.00	SQYD	1,037.00	\$91.80	\$95,196.60
	0073	0460	7034001	CLASS B-1 CONCRETE	4.20	0.00	4.20	CUYD	4.20	\$3,283.90	\$13,792.38
	0073	0470	7034600	CURB BLOCKOUT	21.00	0.00	21.00	LF	21.00	\$314.05	\$6,595.05
	0073	0480	7040104	HALF-SOLE REPAIR	450.00	2,340.50	2,790.50	SQFT	2,790.50	\$43.90	\$122,502.95
	0073	0490	7040106	FULL DEPTH REPAIR	100.00	56.00	156.00	SQFT	156.00	\$63.80	\$9,952.80
	0073	0500	7101000	REINFORCING STEEL (EPOXY COATED)	790.00	0.00	790.00	LB	790.00	\$2.45	\$1,935.50
	0074	0510	2161502	REMOVAL OF CONCRETE WEARING SURFACE	12,442.00	0.00	12,442.00	SQFT	12,442.00	\$2.05	\$25,506.10
	0074	0520	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	243.00	0.00	243.00	LF	243.00	\$321.05	\$78,015.15
	0074	0530	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,376.00	0.00	1,376.00	SQYD	1,376.00	\$137.30	\$188,924.80
	0074	0540	7034001	CLASS B-1 CONCRETE	16.30	0.00	16.30	CUYD	16.30	\$3,465.40	\$56,486.02
	0074	0550	7040101	SUBSTRUCTURE REPAIR (FORMED)	200.00	-125.00	75.00	SQFT	75.00	\$162.15	\$12,161.25
	0074	0560	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	500.00	-500.00	0.00	SQFT	0.00	\$162.15	\$0.00
	0074	0570	7040104	HALF-SOLE REPAIR	1,850.00	5,393.00	7,243.00	SQFT	7,243.00	\$43.90	\$317,967.70
	0074	0580	7040106	FULL DEPTH REPAIR	600.00	887.00	1,487.00	SQFT	1,487.00	\$63.80	\$94,870.60
	0074	0590	7101000	REINFORCING STEEL (EPOXY COATED)	4,280.00	0.00	4,280.00	LB	4,280.00	\$2.15	\$9,202.00
	0075	0600	2161502	REMOVAL OF CONCRETE WEARING SURFACE	9,139.00	0.00	9,139.00	SQFT	0.00	\$2.70	\$0.00
	0075	0610	5050001	OPTIONAL CONCRETE WEARING SURFACE	1,015.00	0.00	1,015.00	SQYD	0.00	\$91.80	\$0.00
	0075	0620	7034600	CURB BLOCKOUT	509.00	0.00	509.00	LF	0.00	\$97.20	\$0.00
	0075	0630	7040104	HALF-SOLE REPAIR	900.00	0.00	900.00	SQFT	0.00	\$43.90	\$0.00
	0075	0640	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	450.00	0.00	450.00	SQFT	0.00	\$75.50	\$0.00
	0076	0650	2161502	REMOVAL OF CONCRETE WEARING SURFACE	9,139.00	0.00	9,139.00	SQFT	9,139.00	\$2.70	\$24,675.30
	0076	0660	5050001	OPTIONAL CONCRETE WEARING SURFACE	1,015.00	0.00	1,015.00	SQYD	1,015.00	\$91.80	\$93,177.00
	0076	0670	7034600	CURB BLOCKOUT	509.00	0.00	509.00	LF	509.00	\$98.00	\$49,882.00
	0076	0680	7040104	HALF-SOLE REPAIR	900.00	2,005.00	2,905.00	SQFT	2,905.00	\$43.90	\$127,529.50
	0076	0690	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	450.00	610.00	1,060.00	SQFT	1,060.00	\$75.50	\$80,030.00
	0077	0700	2161502	REMOVAL OF CONCRETE WEARING SURFACE	5,187.00	0.00	5,187.00	SQFT	0.00	\$4.35	\$0.00
	0077	0710	5050001	OPTIONAL CONCRETE WEARING SURFACE	576.00	0.00	576.00	SQYD	0.00	\$91.80	\$0.00
	0077	0720	7034600	CURB BLOCKOUT	301.00	0.00	301.00	LF	0.00	\$124.00	\$0.00
	0077	0730	7040104	HALF-SOLE REPAIR	500.00	0.00	500.00	SQFT	0.00	\$43.90	\$0.00
	0077	0740	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	250.00	0.00	250.00	SQFT	0.00	\$75.50	\$0.00
	0077	0750	7040113	CLEANING AND EPOXY COATING	990.00	0.00	990.00	SQFT	990.00	\$5.50	\$5,445.00
	0078	0760	2161502	REMOVAL OF CONCRETE WEARING SURFACE	5,187.00	0.00	5,187.00	SQFT	5,187.00	\$4.35	\$22,563.45
	0078	0770	5050001	OPTIONAL CONCRETE WEARING SURFACE	576.00	0.00	576.00	SQYD	576.00	\$91.80	\$52,876.80
	0078	0780	7034600	CURB BLOCKOUT	301.00	0.00	301.00	LF	301.00	\$124.00	\$37,324.00
	0078	0790	7040104	HALF-SOLE REPAIR	500.00	-179.00	321.00	SQFT	321.00	\$43.90	\$14,091.90
	0078	0800	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	250.00	-162.00	88.00	SQFT	88.00	\$75.50	\$6,644.00
	0078	0810	7040113	CLEANING AND EPOXY COATING	990.00	0.00	990.00	SQFT	990.00	\$5.50	\$5,445.00
	0079	0820	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	144.00	0.00	144.00	LF	144.00	\$45.75	\$6,588.00
	0079	0830	2169903	MISC.REMOVAL AND REINSTALLATION OF SIDEWALK SKID PLATE	30.00	0.00	30.00	LF	30.00	\$261.45	\$7,843.50
	0079	0840	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS	1.00	0.00	1.00	LS	1.00	\$7,120.50	\$7,120.50
	0079	0850	7171002	PREFORMED COMPRESSION SEAL	110.00	0.00	110.00	LF	110.00	\$95.15	\$10,466.50
	0080	0860	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	196.00	0.00	196.00	LF	196.00	\$45.75	\$8,967.00
						0.00	26.00	LF			
		J4P3266 0073 0073 0073 0073 0073 0073 0073 0073	JAP3266 0073 0430 0430 0073 0440 0073 0450 0073 0470 0073 0480 0073 0500 0074 0510 0074 0550 0074 0570 0074 0570 0075 0610 0075 0610 0075 0610 0075 0620 0075 0630 0076 0650 0076 0650 0076 0650 0076 0660 0076 0670 0076 0680 0076 0680 0077 0710 0077 0720 0077 0720 0077 0730 0077 0740 0077 0750 0078 0760 0079 0830 0079 0830 0079 0830 0079 0830 0079 0850	J4P3266         0073         0430         2164000           0073         0440         2165500           0073         0450         5050001           0073         0460         7034001           0073         0460         7034600           0073         0470         7034600           0073         0490         7040104           0073         0500         7101000           0074         0510         2161502           0074         0530         5052000           0074         0530         5052000           0074         0550         7040101           0074         0550         7040104           0074         0560         7040104           0074         0560         7040104           0074         0560         7040104           0074         0560         7040104           0074         0590         7101000           0075         0600         2161502           0076         0660         7034600           0075         0620         7034600           0076         0660         5050001           0076         0660         5050001     <	JAP3286   0073	JAP3206   0.073   0.430   2164000   CURB REMOVAL   10.00   0.00   0.440   2165500   REMOVAL OF CATHODIC PROTECTION SYSTEM   1.00   0.	Name	APPEAD   19		NET   100	APPINES   1978

Revision 4/1/2020 Page 6 of 22



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200417-C03	J4P3266	0080	0880	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	1.00	\$7,812.95	\$7,812.95
		0800	0890	7171002	PREFORMED COMPRESSION SEAL	165.00	0.00	165.00	LF	165.00	\$95.15	\$15,699.75
		0081	0900	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	63.00	0.00	63.00	LF	63.00	\$704.60	\$44,389.80
		0081	0910	2169903	MISC.REMOVE AND REPLACE BARRIER CURB	12.00	0.00	12.00	LF	12.00	\$709.90	\$8,518.80
		0081	0920	7034214	CLASS B-2 CONCRETE	5.90	0.00	5.90	CUYD	5.90	\$2,888.20	\$17,040.38
		0081	0930	7101000	REINFORCING STEEL (EPOXY COATED)	730.00	0.00	730.00	LB	730.00	\$3.55	\$2,591.50
		0081	0940	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	1.00	\$3,634.45	\$3,634.45
		0081	0950	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	63.00	0.00	63.00	LF	63.00	\$380.05	\$23,943.15
		0082	0960	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	92.00	0.00	92.00	LF	92.00	\$45.75	\$4,209.00
		0082	0970	7171002	PREFORMED COMPRESSION SEAL	92.00	0.00	92.00	LF	92.00	\$95.15	\$8,753.80
		0083	0980	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	92.00	0.00	92.00	LF	92.00	\$45.75	\$4,209.00
		0083	0990	7171002	PREFORMED COMPRESSION SEAL	92.00	0.00	92.00	LF	92.00	\$95.15	\$8,753.80
		0084	1000	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	192.00	0.00	192.00	LF	192.00	\$45.75	\$8,784.00
		0084	1010	7049903	MISC.RAISED MEDIAN REPAIR	40.00	-40.00	0.00	LF	0.00	\$122.70	\$0.00
		0084	1020	7171002	PREFORMED COMPRESSION SEAL	192.00	0.00	192.00	LF	192.00	\$95.15	\$18,268.80
		0085	1030	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	193.00	0.00	193.00	LF	193.00	\$448.95	\$86,647.35
		0085	1040	2169903	MISC.REMOVE AND REPLACE BARRIER CURB	12.00	0.00	12.00	LF	12.00	\$709.90	\$8,518.80
		0085	1050	2169904	MISC.REMOVE AND REPLACE RAISED MEDIAN CURB	24.00	0.00	24.00	SQFT	24.00	\$166.85	\$4,004.40
		0085	1060	7034214	CLASS B-2 CONCRETE	16.90	0.00	16.90	CUYD	16.90	\$2,888.20	\$48,810.58
		0085	1070	7049903	MISC.RAISED MEDIAN REPAIR	20.00	0.00	20.00	LF	20.00	\$122.75	\$2,455.00
		0085	1080	7101000	REINFORCING STEEL (EPOXY COATED)	2,570.00	0.00	2,570.00	LB	2,570.00	\$2.70	\$6,939.00
		0085	1090	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	1.00	\$4,907.05	\$4,907.05
		0085	1100	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	163.00	0.00	163.00	LF	163.00	\$380.05	\$61,948.15
		0086	1110	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	162.00	0.00	162.00	LF	162.00	\$448.95	\$72,729.90
		0086	1120	2169904	MISC.REMOVE AND REPLACE RAISED MEDIAN CURB	24.00	0.00	24.00	SQFT	24.00	\$122.75	\$2,946.00
		0086	1130	7034214	CLASS B-2 CONCRETE	15.30	0.00	15.30	CUYD	15.30	\$2,888.20	\$44,189.46
		0086	1140	7101000	REINFORCING STEEL (EPOXY COATED)	2,080.00	0.00	2,080.00	LB	2,080.00	\$3.05	\$6,344.00
		0086	1150	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	1.00	\$6,167.30	\$6,167.30
		0086	1160	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	162.00	0.00	162.00	LF	162.00	\$380.05	\$61,568.10
		0087	1170	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	192.00	0.00	192.00	LF	192.00	\$448.95	\$86,198.40
		0087	1180	2169903	MISC.REMOVE AND REPLACE BARRIER CURB	12.00	0.00	12.00	LF	12.00	\$709.90	\$8,518.80
		0087	1190	2169904	MISC.REMOVE AND REPLACE RAISED MEDIAN CURB	24.00	0.00	24.00	SQFT	24.00	\$122.75	\$2,946.00
		0087	1200	7034214	CLASS B-2 CONCRETE	17.20	0.00	17.20	CUYD	17.20	\$2,888.20	\$49,677.04
		0087	1210	7101000	REINFORCING STEEL (EPOXY COATED)	2,900.00	0.00	2,900.00	LB	2,900.00	\$3.10	\$8,990.00
		0087	1220	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	1.00	\$4,118.75	\$4,118.75
		0087	1230	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	162.00	0.00	162.00	LF	162.00	\$380.05	\$61,568.10
		0088	1240	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	185.00	15.00	200.00	LF	200.00	\$45.75	\$9,150.00
		0088	1250	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	1.00	\$6,380.60	\$6,380.60
		0088	1260	7171002	PREFORMED COMPRESSION SEAL	185.00	15.00	200.00	LF	200.00	\$95.15	\$19,030.00
		0001	5001	6122017	IMPACT ATTENUATOR 65 MPH (SAND BARREL ARRAY)	0.00	4.00	4.00	EA	2.00	\$3,417.28	\$6,834.56
		0001	5002	6122030	IMPACT ATTENUATOR (RELOCATION)	0.00	14.00	14.00	EA	10.00	\$1,257.22	\$12,572.20
		0001	5003	6122020	REPLACEMENT SAND BARREL	0.00	1.00	1.00	EA	0.00	\$526.52	\$0.00
		0001	5004	6189901	MISC.Contract Bond Payment	0.00	1.00	1.00	LS	1.00	\$18,706.00	\$18,706.00
		0001	5005	9029901	MISC.SIGNAL MODIFICATION	0.00	1.00	1.00	LS	1.00	\$5,224.89	\$5,224.89

Revision 4/1/2020 Page 7 of 22



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract n.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
0417-C03	J4P3266	0074	5006	7049904	MISC.Clean and Epoxy Seal	0.00	910.00	910.00	SQFT	910.00	\$12.88	\$11,720.80
		0001	5007	4039910	MISC.ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP125B MIX)	0.00	19.20	19.20	TONS	19.20	\$559.65	\$10,745.28
		0001	5008	6189901	MISC.MOBILIZATION FOR ASPHALT TIE-IN PAVEMENT	0.00	1.00	1.00	LS	1.00	\$3,150.00	\$3,150.00
		0001	5009	4071005	TACK COAT	0.00	274.00	274.00	GAL	195.00	\$2.63	\$512.85
		0001	5010	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	0.00	44.00	44.00	LF	44.00	\$22.05	\$970.20
		0001	5011	4039910	MISC.SP125C (70-22) (100.1-500 TONS) (OVER 9 FEET WIDE)	0.00	417.70	417.70	TONS	417.70	\$94.37	\$39,418.35
		0072	5012	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	0.00	3,372.40	3,372.40	SQYD	3,372.40	\$9.95	\$33,555.38
		0001	5013	4071005	TACK COAT	0.00	412.00	412.00	GAL	412.00	\$4.16	\$1,713.92
		0001	5014	6189902	MISC.MOBILIZATION COLDMILLING & RESURFACING (15-1000 tons)	0.00	4.00	4.00	EA	4.00	\$5,617.50	\$22,470.00
		0001	5015	6252003	SLAB JACKING MATERIAL HIGH DENSITY POLYURETHANE	0.00	0.00	0.00	LB	0.00	\$6.83	\$0.00
		0001	5016	6189901	MISC.MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$2,205.00	\$2,205.00
		0087	5017	6169902	MISC.ADA BARRICADE	0.00	4.00	4.00	EA	4.00	\$110.25	\$441.00
		0070	5018	6175011B	RELOCATING TEMPORARY TRAFFIC BARRIER ANCHORED	0.00	1,944.00	1,944.00	LF	691.00	\$20.35	\$14,061.85
		0081	5019	7040101	SUBSTRUCTURE REPAIR (FORMED)	0.00	20.00	20.00	SQFT	20.00	\$162.15	\$3,243.00
		0073 5020 1046002 VALUE ENGINEERING			VALUE ENGINEERING	0.00	35,298.30	35,298.30	EA	35,298.30	\$1.00	\$35,298.30
		0073	5021	2169901	MISC.REMOVAL BY JACK HAMMERING	0.00	1.00	1.00	LS	1.00	\$9,714.11	\$9,714.11
		0001	5022	6169901	MISC.MOBILIZATION FOR CMS BOARDS	0.00	1.00	1.00	LS	1.00	\$1,575.00	\$1,575.00
		0073	5023	6069901	MISC.GUARDRAIL REMOVAL AND INSTALL	0.00	1.00	1.00	LS	1.00	\$12,384.66	\$12,384.66
		0001	5024	2071000	LINEAR GRADING CLASS 1	0.00	5.00	5.00	STA	5.00	\$313.53	\$1,567.65
		0010	5025	6069902	MISC.DUARDRAIL POSTS DRILLED IN CONCRETE FLUMES	0.00	55.00	55.00	EA	33.00	\$194.25	\$6,410.25
		0001	5026	4030003	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP095C MIX)	0.00	96.00	96.00	TONS	96.00	\$155.40	\$14,918.40
		0001	5027	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	0.00	22.00	22.00	SQYD	22.00	\$65.63	\$1,443.86
		0071	5028	7040113	CLEANING AND EPOXY COATING	0.00	16.00	16.00	SQFT	16.00	\$5.50	\$88.00
		0079	5029	6189901	MISC.MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$988.37	\$988.37
		0001	5030	4019910	MISC.SHOULDER MIX (100.1-500 TONS)(4.1-9 FEET WIDE)	0.00	138.00	138.00	TONS	138.00	\$82.95	\$11,447.10
		0001	5031	4019910	MISC.SHOULDER MIX (15-100 TONS) (2-4 FEET WIDE)	0.00	110.70	110.70	TONS	110.70	\$128.10	\$14,180.67
		0001	5032	6229905	MISC.MILLING per SY (>6")	0.00	418.00	418.00	SQYD	418.00	\$7.56	\$3,160.08
		0001	5033	6229905	MISC.MILLING per SY (2"-4")	0.00	220.00	220.00	SQYD	220.00	\$2.52	\$554.40
		0001	5034	6189902	MISC.MOBILIZATION COLDMILL & RESURFACING (15-1000 TONS)	0.00	1.00	1.00	EA	1.00	\$5,250.00	\$5,250.00
		0001	5035	4071005	TACK COAT	0.00	19.00	19.00	GAL	19.00	\$3.89	\$73.91
	Project Je	4P3266 - To	otal Value	Posted to D	ate as of Report Generated Date							\$4,876,888.87
17-C03 Ove	erall - Total	Value Pos	ted to Dat	e as of Repo	ort Generated Date							\$4,876,888.87

Page 8 of 22 Revision 4/1/2020



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J4P3266

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0030	4030007	ASPH. CONC. MIXTURE PG 70-22 (SP095BSM)	4/29/22	4/29/22	56.98	TONS	Stage 2 Searcy and Brighton bridge transitions	129+70				
0240	6061060	MGS GUARDRAIL	4/26/22	4/27/22	262.50	LF	Stage 2 Searcy	129+70				
			4/27/22	4/27/22	262.50	LF	WB Brighton stage 2 LT	114+90				
0250	6061069	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	4/26/22	4/27/22	1.00	EA	Stage 2 Searcy	129+70				
			4/27/22	4/27/22	1.00	EA	WB Brighton stage 2 LT	114+90				
0270	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	4/26/22	4/27/22	1.00	EA	Stage 2 Searcy	129+70				
			4/27/22	4/27/22	1.00	EA	WB Brighton stage 2 LT	114+90				
0660	5050001	OPTIONAL CONCRETE WEARING SURFACE	4/22/22	4/26/22	433.00	SQYD	Stage 2 at Brighton	114+90				
5009	4071005	TACK COAT	4/29/22	4/29/22	78.00	GAL	Stage 2 Searcy and Brighton bridge transitions	129+70				
5025	6069902	MISC. GUARDRAIL ITEM	4/26/22	4/27/22	11.00	EA	WB Brighton stage 2 LT	114+90				
				4/27/22	11.00	EA	WB Searcy stage 2 LT	129+70				

Project	Line Number	DWR Date	Total Quantity Posted For DWR Date	on oign	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
I4P3266	0040	March 8, 2021	453	special ZONE	??x?? ??.00 NO PASSING		0.005	Drury Ave	1.00		36x36 Road Work Ahead	9.00	
					??x?? ??.00 NO PASSING		0.005	Marian Park	1.00		36x36 Road Work Ahead	9.00	
				special ZONE	??x?? ??.00 NO PASSING		0.068	Freemont	1.00		36x36 Road Work Ahead	9.00	
				special ZONE	??x?? ??.00 NO PASSING		0.104	Drury Ave.	1.00		36x36 Road Work Ahead	9.00	
				special ZONE	??x?? ??.00 NO PASSING		0.287	95th Terr.	1.00		36x36 Road Work Ahead	9.00	
				special ZONE	??x?? ??.00 NO PASSING		0.697	Belmont	1.00		36x36 Road Work Ahead	9.00	
				special ZONE	??x?? ??.00 NO PASSING		0.94	EB 87th	1.00		24x12 Detour	2.00	
				special ZONE	??x?? ??.00 NO PASSING		0.94	EB 87th	1.00		21x15 Arrow	2.19	2.
				special ZONE	??x?? ??.00 NO PASSING		0.94	EB 87th	1.00		24x24 State Marker	4.00	
				special ZONE	??x?? ??.00 NO PASSING		1.028	Marian Dr.	1.00		36x36 Road Work Ahead	9.00	
				special ZONE	??x?? ??.00 NO PASSING		1.0335	Hillcrest Rd.	1.00		36x36 Road Work Ahead	9.00	
				special ZONE	??x?? ??.00 NO PASSING		1.536	EB 87th	1.00		24x12 Detour	2.00	
				special ZONE	??x?? ??.00 NO PASSING		1.536	EB 87th	1.00		21x15 Arrow	2.19	2.
				special ZONE	??x?? ??.00 NO PASSING		1.536	EB 87th	1.00		24x24 State Marker	4.00	
				special ZONE	??x?? ??.00 NO PASSING		1.585	EB 87th	1.00		24x12 Detour	2.00	
				special ZONE	??x?? ??.00 NO PASSING		1.585	EB 87th	1.00		21x15 Arrow	2.19	2
				special ZONE	??x?? ??.00 NO PASSING		1.585	EB 87th	1.00		24x24 State Marker	4.00	
				special ZONE	??x?? ??.00 NO PASSING		1.633	EB 87th	1.00		24x12 Detour	2.00	
				special ZONE	??x?? ??.00 NO PASSING		1.633	EB 87th	1.00		21x15 Arrow	2.19	2
				special ZONE	??x?? ??.00 NO PASSING		1.633	EB 87th	1.00		24x24 State Marker	4.00	
				special ZONE	??x?? ??.00 NO PASSING		124.355	SB US 71	1.00		24x12 Detour	2.00	
				special ZONE	??x?? ??.00 NO PASSING		124.355	SB US 71	1.00		24x12 South	2.00	
				special ZONE	??x?? ??.00 NO PASSING		124.355	SB US 71	1.00		21x15 Arrow	2.19	2
				special ZONE	??x?? ??.00 NO PASSING		124.355	SB US 71	1.00		30x24 Interstate Marker	5.00	
				ZONE	??x?? ??.00 NO PASSING		129.559	SB US 71	1.00		24x12 Detour	2.00	
				ZONE	??x?? ??.00 NO PASSING		129.559	SB US 71	1.00		24x12 South	2.00	
				special ZONE	??x?? ??.00 NO PASSING		129.559	SB US 71	1.00		21x15 Arrow	2.19	2
				special ZONE	??x?? ??.00 NO PASSING		129.559	SB US 71	1.00		30x24 Interstate Marker	5.00	
				ZONE	??x?? ??.00 NO PASSING		2.045	Hillcrest	1.00		36x36 Road Work Ahead	9.00	
				special ZONE	??x?? ??.00 NO PASSING		3.955	EB Banister Rd.	2.00		36x36 Road Work Ahead	9.00	
				special ZONE	??x?? ??.00 NO PASSING		4.048	EB Banister Rd.	2.00		24x36 WZ Speed Limit	6.00	
				MUST T	30x30 6.25 LEFT LANE URN LEFT		4.099	EB Banister Rd.	1.00	6.25			6.
				MUSTT	30x30 6.25 LEFT LANE URN LEFT		4.196	EB Banister Rd.	1.00	6.25			6.
				MUST T	30x30 6.25 LEFT LANE URN LEFT		4.229	EB Banister Rd.	1.00	6.25			6.
				MUST T	30x30 6.25 LEFT LANE URN LEFT		4.23	EB Banister Rd.	1.00	6.25			6
				ZONE	??x?? ??.00 NO PASSING		4.286	EB Banister Rd.	1.00		24x12 Detour	2.00	
				ZONE	??x?? ??.00 NO PASSING		4.286	EB Banister	1.00		21x15 Arrow	2.19	2.
				ZONE	??x?? ??.00 NO PASSING		4.286	EB Banister Rd.	1.00		24x24 State Marker	4.00	
				special	??x?? ??.00 NO PASSING		4.286	EB Banister Rd.	1.00		48x24 Semi Trucks	8.00	

Revision 4/1/2020 Page 9 of 22



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line are details for Construction Signs (if applicable)

roject	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
3266 00	040	March 8, 2021	453	ZONE R3-2 48x48 16.00 NO LEFT TURN		4.286	EB Banister Rd.	1.00	16			1
				(SYMBOL) W020-2 48x48 16.00 DETOUR		4.325	NB 435	1.00	16			1
				AHEAD special ??x?? ??.00 NO PASSING		4.509	NB 435	1.00		24x12 Detour	2.00	
				ZONE special ??x?? ??.00 NO PASSING		4.509	NB 435	1.00		21x15 Arrow	2.19	2.
				ZONE special ??x?? ??.00 NO PASSING		4.509	NB 435	1.00		24x24 State Marker	4.00	
				ZONE						24X24 State Walker	4:00	
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		4.695	NB 435	1.00	16			
				special ??x?? ??.00 NO PASSING ZONE		4.972	NB 435	1.00		24x12 Detour	2.00	
				special ??x?? ??.00 NO PASSING ZONE		4.972	NB 435	1.00		21x15 Arrow	2.19	2
				special ??x?? ??.00 NO PASSING ZONE		4.972	NB 435	1.00		24x24 State Marker	4.00	
				special ??x?? ??.00 NO PASSING ZONE		49.992	SB 435	1.00		24x12 Detour	2.00	
				special ??x?? ??.00 NO PASSING ZONE		49.992	SB 435	1.00		21x15 Arrow	2.19	2
				special ??x?? ??.00 NO PASSING ZONE		49.992	SB 435	1.00		24x24 State Marker	4.00	
				special ??x?? ??.00 NO PASSING ZONE		5.701	WB Banister Rd.	1.00		36x36 Road Work Ahead	9.00	
				special ??x?? ??.00 NO PASSING ZONE		5.734	NB 435	1.00		24x12 Detour	2.00	
				special ??x?? ??.00 NO PASSING ZONE		5.734	NB 435	1.00		21x15 Arrow	2.19	2
				special ??x?? ??.00 NO PASSING ZONE		5.734	NB 435	1.00		24x24 State Marker	4.00	
				special ??x?? ??.00 NO PASSING ZONE		5.773	WB Banister Rd.	1.00		36x36 Left Lane Closed Ahead	9.00	
				special ??x?? ??.00 NO PASSING ZONE		5.778	WB Banister Rd.	1.00		36x36 Left Lane Closed	9.00	
				special ??x?? ??.00 NO PASSING ZONE		5.925	NB 435	1.00		24x12 Detour	2.00	
				special ??x?? ??.00 NO PASSING ZONE		5.925	NB 435	1.00		21x15 Arrow	2.19	
				special ??x?? ??.00 NO PASSING ZONE		5.925	NB 435	1.00		24x24 State Marker	4.00	
				special ??x?? ??.00 NO PASSING		5.944	WB Banister Rd.	1.00		24x36 WZ Speed Limit	6.00	
				ZONE WO20-1 48x48 16.00		50.21	SB 435	1.00	16			
				ROAD/BRIDGE/RAMP WORK AHEAD  MO4-8a 24x18 3.00 END DETOUR		50.215	SB 435	1.00	3			
				MO4-8a 24x18 3.00 END DETOUR		51.833	SB 435	1.00	3	20.000	0.05	
				special ??x?? ??.00 NO PASSING ZONE		6.056	WB Banister Rd.	1.00		30x30 Double Down	6.25	
				special ??x?? ??.00 NO PASSING ZONE		6.256	WB Banister Rd.	2.00		36x36 Left Lane Closed Ahead	9.00	
				special ??x?? ??.00 NO PASSING ZONE		6.288	WB Banister Rd.	1.00		36x36 Detour Ahead	9.00	
				special ??x?? ??.00 NO PASSING ZONE		6.355	WB Banister Rd.	1.00		30x30 Double Down	6.25	
				special ??x?? ??.00 NO PASSING ZONE		6.405	WB Banister Rd.	1.00		30x30 Double Down	6.25	
				special ??x?? ??.00 NO PASSING ZONE		6.405	WB Banister Rd.	1.00		36x36 Left Lane Closed	9.00	
				special ??x?? ??.00 NO PASSING ZONE		6.405	WB Banister Rd.	1.00		36x36 Merge	9.00	
				special ??x?? ??.00 NO PASSING ZONE		6.453	WB Banister Rd.	1.00		30x30 Double Down	6.25	
				special ??x?? ??.00 NO PASSING ZONE		6.601	WB Banister Rd.	1.00		24x12 Detour	2.00	
				special ??x?? ??.00 NO PASSING ZONE		6.601	WB Banister Rd.	1.00		24x12 South	2.00	
				special ??x?? ??.00 NO PASSING ZONE		6.601	WB Banister Rd.	1.00		21x15 Arrow	2.19	
				special ??x?? ??.00 NO PASSING ZONE		6.601	WB Banister Rd.	1.00		30x24 Interstate Marker	5.00	
				special ??x?? ??.00 NO PASSING ZONE		6.624	WB Banister Rd.	1.00		36x36 No Left Turn	9.00	
				special ??x?? ??.00 NO PASSING ZONE		7.192	WB Banister Rd.	1.00		24x12 Detour	2.00	
				special ??x?? ??.00 NO PASSING		7.192	WB Banister Rd.	1.00		24x12 South	2.00	
				ZONE special ??x?? ??.00 NO PASSING		7.192	WB Banister Rd.	1.00		21x15 Arrow	2.19	
				ZONE special ??x?? ??.00 NO PASSING		7.192	WB Banister Rd.	1.00		30x24 Interstate Marker	5.00	
		March 16,	187	ZONE WO3-2A(48) 48x48 16.00 YIELD		0.202	EB 87TH RAMP TO 435 S	1.00	16			
		2021		AHEAD W020-1 48x48 16.00		0.145	EB 87TH RAMP TO 435 S	1.00	16			
				ROAD/BRIDGE/RAMP WORK AHEAD  EO5-2 48x36 12:00 EXIT OPEN		50.109	SB 435	1.00	12			
				R1-2 48 TRI 6.93 YIELD		49.476	SB 435	1.00	6.93			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		48.255	SB 435	2.00	16			
				R2-1 36x48 12.00 SPEED LIMIT XX		49.079	SB 435	2.00	12			
				WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		48.911	SB 435	1.00	16			
				WO4-1(48) 48x48 16.00 MERGE		48.911	SB 435	1.00	16			

Revision 4/1/2020 Page 10 of 22



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work. The information below this line are details for Construction Signs (if applicable).

ject Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
3266 0040	March 16, 2021	187	WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD		48.591	SB 435	2.00	16			3
			WO4-1aR 48x48 16.00 MERGE (SYMBOL FROM RIGHT)		49.319	SB 435	1.00	16			1
	April 12, 2021	368	See Special Sign Details		1.287 and 2.058	Linwood Blvd on barricades	2.00		Detour 48"x18"	6.00	1
			R11-4 60x30 12.50 ROAD CLOSED TO THRU TRAFFIC		1.287 to 2.099	Linwood Blvd on barricades	4.00	12.5			5
			See Special Sign Details		1.275	EB 31st St.	1.00		Detour Up Arrow 30"x24"	5.00	
			See Special Sign Details		1.109	EB Linwood Blvd	1.00		Right Lane Closed 36"x36"	9.00	
			See Special Sign Details		1.1 to 1.82	EB and WB Linwood	2.00		Road Closed Ahead 36"x36"	9.00	1
			See Special Sign Details		1.034	EB Linwood Blvd	1.00		Right Lane Closed Ahead 36"x36"	9.00	
			See Special Sign Details		1	Flora, Woodland, and Highland	4.00		Road Work Ahead 36"x36"	9.00	3
			See Special Sign Details		0.957	EB Linwood Blvd	1.00		Road Work Ahead 36"x36"	9.00	
			See Special Sign Details		0.833	NB Euclid Ave	2.00		No Left Turn 24"x24"	4.00	
			See Special Sign Details		0.362	SB Michigan Ave	2.00		No Left Turn 24"x24"	4.00	
			See Special Sign Details		0.352	SB Garfield Ave.	1.00		Road Work Ahead 36"x36"	9.00	
			See Special Sign Details		0.349	SB Wayne Ave	1.00		Road Work Ahead 36"x36"	9.00	
			See Special Sign Details		1.479	EB 31st St	1.00		Detour Right Arrow 30"x24"	5.00	
			See Special Sign Details		4.014	NE The Paseo	1.00		Detour Right Arrow 30"x24"	5.00	
			See Special Sign Details		2.834	WB 31st St	1.00		Detour Left Arrow 30"x24"	5.00	
			See Special Sign Details		2.455	WB 31st St	1.00		Detour Up Arrow 30"x24"	5.00	
			See Special Sign Details		2.45	WB 31st St.	0.00		Detour Up Arrow 30"x24"	0.00	
			See Special Sign Details		120.5	SB 71 Hwy	2.00		Right Shoulder Closed 48"x48"	16.00	3
			See Special Sign Details		120.45	SB 71 Hwy	2.00		Right Shoulder Closed Ahead 48"x48"	16.00	3
			WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		120.4	SB 71 Hwy	2.00	16			3
			See Special Sign Details		1.937	WB Linwood Blvd	1.00		Right Lane Closed 36"x36"	9.00	
			See Special Sign Details		1.847	WB Linwood Blvd	1.00		Right Lane Closed Ahead 36"x36"	9.00	
			See Special Sign Details		1.516 to 2.892	NB and SB Brooklyn Ave.	2.00		Road Work Ahead 36"x36"	9.00	1
			R11-2 48x30 10.00 ROAD CLOSED		1.591 to 2.17	Linwood Blvd on barricades	2.00	10			2
			See Special Sign Details		1.646	NB Brooklyn Ave.	1.00		Detour Left Arrow 30"x24"	5.00	
			See Special Sign Details		1.82	WB Linwood Blvd	1.00		Road Work Ahead 36"x36"	9.00	
	April 19, 2021	36	See Special Sign Details		1.657 to 2.546	Euclid, Michigan, and 2x The Paseo	4.00		Road Work Ahead 36"x36"	9.00	3
	June 1, 2021	64	WO1-4bR 48x48 16.00 DOUBLE ARROW REVERSE CURVE (SYMBOL RIGHT ARROWS)		7.161	NB I-435 at Oldham Rd and Gregory Blvd	4.00	16			6
	July 16, 2021	124	WO20-4 48x48 16.00 ONE LANE ROAD AHEAD		1	77th	2.00	16			3
			WO3-3 48x48 16.00 SIGNAL AHEAD (SYMBOL)		1	77th	2.00	16			3
			R10-6 24x36 6.00 STOP HERE ON RED (45 DEGREE ARROW		1	77th	2.00	6			1
			WO1-3L 48x48 16.00 REVERSE TURN (SYMBOL LEFT ARROW)		1	435	2.00	16			3
			WO1-2L 48x48 16.00 CURVE (SYMBOL LEFT ARROW)		1	77th	1.00	16			1
	October 8, 2021	96	WO5-1 48x48 16.00 ROAD/BRIDGE/RAMP NARROWS		41.817	SB 435	2.00	16			3
			WO5-1 48x48 16.00 ROAD/BRIDGE/RAMP NARROWS		43.766	SB 435	2.00	16			3
			WO5-1 48x48 16.00 ROAD/BRIDGE/RAMP NARROWS		42.293	SB 435	2.00	16			3
0040 - Total						· ·					1327.5

Revision 4/1/2020 Page 11 of 22



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J4P3266	0040	CONSTRUCTION SIGNS	Overrun	Overrun	12	Jun 2, 2021	SYSTEM	(\$588.00)		
					16	Aug 2, 2021	SYSTEM	(\$2,430.40)		
					17	Aug 16, 2021	SYSTEM	\$1,215.20	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',19.60000 - 19.60000, 'is applied (if non-zero).	
					18	Sep 1, 2021	SYSTEM	\$1,803.20	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',19.60000 - 19.60000, 'is applied (if non-zero).	
					21	Oct 18, 2021	SYSTEM	(\$1,881.60)		
					22	Nov 3, 2021	SYSTEM	\$1,881.60	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',19.60000 - 19.60000, 'is applied (if non-zero).	
				Overrun - To	otal			\$0.00		
			Overrun - Tota					\$0.00		
	0040 -	· Total						\$0.00		
	0070	CHANNELIZER (TRIM LINE)	Overrun	Overrun	7	Mar 16, 2021	SYSTEM	(\$515.00)		
		,			8	Apr 2, 2021	SYSTEM	(\$5,665.00)		
					9	Apr 16, 2021	SYSTEM	\$6,180.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',51.50000 - 51.50000, 'is applied (if non-zero).	
				Overrun - To	otal			\$0.00	applied (ii non-zero).	
			Overrup Teta		otai			\$0.00		
	0070	Гotal	Overrun - Total							
			0	0	47	A 40	OVOTEM	\$0.00		
	0110	TEMPORARY TRAFFIC BARRIER, CONT.	Overrun	Overrun	17	Aug 16, 2021	SYSTEM	(\$12,886.88) \$12,886.88	Unit wise board on covered accommodification of installed quantity on all	
		FURN/RE			10	Sep 1, 2021	STSTEW	φ12,000.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',19.75000 - 19.75000, 'is applied (if non-zero).	
				Overrun - T	otal			\$0.00		
			Overrun - Tota	il				\$0.00		
	0110 -	· Total						\$0.00		
	0160	PREF THERMO PVMT MARK, LT/RT ARROW			12	Jun 2, 2021	SYSTEM	\$3,091.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user watsom1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
					12	Jun 2, 2021	SYSTEM	(\$3,091.20)		
				- Total				\$0.00		
			Material - Tota					\$0.00		
	0160 -	· Total						\$0.00		
	0190	4 IN. WHITE WATERBORNE PAVEMENT	Material		12	Jun 2, 2021	SYSTEM	\$201.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user watsom1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	
		MARKING				12	Jun 2, 2021	SYSTEM	(\$201.00)	
					13	Jun 16, 2021	SYSTEM	\$201.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user watsom1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	
			13	13	Jun 16, 2021	SYSTEM	(\$201.00)			
				- Total				\$0.00		
			Material - Tota	ıl				\$0.00		
	0190 -	· Total						\$0.00		
	0200	4 IN. YELLOW WATERBORNE PAVEMENT	Material		12	Jun 2, 2021	SYSTEM	\$83.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user watsom1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	
		MARKING			12	Jun 2, 2021	SYSTEM	(\$83.25)		



ct	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
JI.	LINE	Description	Туре	Adjustment Type	Number	Date	By	Amount	Reilians
66 (	0200	4 IN. YELLOW WATERBORNE PAVEMENT	Material		13	Jun 16, 2021	SYSTEM	\$83.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user watsom1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
		MARKING			13	Jun 16, 2021	SYSTEM	(\$83.25)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0200 -	Total						\$0.00	
(	0220	4 IN TEMPORARY PAVEMENT	Overrun	Overrun	20	Oct 4, 2021	SYSTEM	(\$9,191.25)	
		MARKING PAINT			21	Oct 18, 2021	SYSTEM	(\$21,384.00)	
					22	Nov 3, 2021	SYSTEM	\$30,575.25	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',2.25000 - 2.25000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - Tota	al				\$0.00	
	0220 -	Total						\$0.00	
(	0240	MGS GUARDRAIL	Construction Stockpile		22	Nov 3, 2021	SYSTEM	(\$7,518.75)	Payment Estimate Item Adjustment generated Stockpile Transaction
					23	Nov 16, 2021	SYSTEM	(\$12,608.37)	Payment Estimate Item Adjustment generated Stockpile Transaction
					29	May 2, 2022	SYSTEM	(\$4,746.98)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$24,874.10)	
			Construction	Stockpile - To				(\$24,874.10)	
			Construction Stockpile STMA		2	Sep 16, 2020	SYSTEM	\$4,775.50	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$4,775.50	
			Construction	Stockpile STI	MA - Total			\$4,775.50	
			Construction Stockpile STMI		2	Sep 16, 2020	SYSTEM	\$46,935.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			Construction	- Total Stockpile STI	MI - Total			\$46,935.00 \$46,935.00	
	0240 -	Total						\$26,836.40	
(	0250	MGS BRIDGE APP. TRANS	Construction Stockpile		22	Nov 3, 2021	SYSTEM	(\$2,988.12)	Payment Estimate Item Adjustment generated Stockpile Transaction
		SEC (REG/NO CURB)			23	Nov 16, 2021	SYSTEM	(\$2,988.12)	Payment Estimate Item Adjustment generated Stockpile Transaction
					29	May 2, 2022	SYSTEM	(\$2,988.12)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$8,964.36)	
			Construction	Stockpile - To				(\$8,964.36)	
			Construction Stockpile STMI	T. 1	2	Sep 16, 2020	SYSTEM	\$14,940.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			0	- Total				\$14,940.00	
	0000		Construction	Stockpile STI	WII - Total			\$14,940.00	
	0250 -		0 1 "		00		0)/0==-	\$5,975.64	
(	0270	TYPE A CRASHWORTHY END TERMINAL	Construction Stockpile		22	Nov 3, 2021	SYSTEM	(\$1,506.70)	Payment Estimate Item Adjustment generated Stockpile Transaction
		(MASH)		- Total	29	May 2, 2022	SISIEW	(\$0.30)	Payment Estimate Item Adjustment generated Stockpile Transaction
			Construction		otal			(\$1,507.00)	
		Construction Stockpile - Total  Construction 2				Sep 16,	SYSTEM	\$1,507.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			Stockpile STMI	- Total		2020	SISIEW	\$1,507.00	r aymonic Estimate trem Aujustinent generateu Stockpile Transaction
			Construction		MI - Total			\$1,507.00	
	0270 -	Total	Sonsa detion	экоскрпе 511	Potal			\$1,507.00	
	0270 -	Total						\$0.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
4P3266	0310	HALF-SOLE REPAIR	Material		16	Aug 2, 2021	SYSTEM	\$113,042.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user baldwc2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					16	Aug 2, 2021	SYSTEM	(\$113,042.50)	
					17	Aug 16, 2021	SYSTEM	\$113,042.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user baldwc2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					17	Aug 16, 2021	SYSTEM	(\$113,042.50)	
					18	Sep 1, 2021	SYSTEM	\$113,042.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user baldwc2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					18	Sep 1, 2021	SYSTEM	(\$113,042.50)	
					19	Sep 16, 2021	SYSTEM	\$113,042.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user baldwc2 overridding Payment
					19	Sep 16, 2021	SYSTEM	(\$113,042.50)	Estimate Exception 1 on the current Payment Estimate.
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
			Overrun	Overrun	13	Jun 16, 2021	SYSTEM	\$23,925.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user watsom1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					13	Jun 16, 2021	SYSTEM	\$15,013.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user watsom1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					13	Jun 16, 2021	SYSTEM	(\$38,939.30)	
					14	Jul 1, 2021	SYSTEM	(\$38,939.30)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					14	Jul 1, 2021	SYSTEM	\$6,321.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user baldwc2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					14	Jul 1, 2021	SYSTEM	\$10,975.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user baldwc2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					14	Jul 1, 2021	SYSTEM	\$8,560.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user baldwc2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					14	Jul 1, 2021	SYSTEM	\$38,939.30	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user baldwc2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					14	Jul 1, 2021	SYSTEM	(\$25,857.10)	
				Overrun - T	otal			\$0.00	
			Overrun - Tota	al				\$0.00	
	0310 - 0350	HALF-SOLE REPAIR	Overrun	Overrun	24	Dec 2, 2021	SYSTEM	\$0.00 \$19,316.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user baldwc2 overridding Payment
					24	Dec 2,	SYSTEM	(\$19,316.00)	Estimate Exception 12 on the current Payment Estimate.
				Overrun - To	otal	2021		\$0.00	
			Overrun - Tota					\$0.00	
	0350 -	· Total						\$0.00	
	0390	HALF-SOLE REPAIR	Overrun	Overrun	13	Jun 16, 2021	SYSTEM	\$25,593.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user watsom1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					13	Jun 16, 2021	SYSTEM	(\$25,593.70)	
					14	Jul 1,	SYSTEM	(\$25,593.70)	Averaged Price Adjustment from this item on all previous payment estimates
						2021			of '0.00000' is applied (if non-zero).



	roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
October	P3266	0390		Overrun	Overrun		2021			Estimate Item Adjustment (0007) due to user baldwc2 overridding Payment Estimate Exception 4 on the current Payment Estimate.			
Construction   Stockylin   S					Overrun - T	otal			\$0.00				
Contraction				Overrun - Tota	al				\$0.00				
BLOCKOUT   Stocypic   Total		0390 -	Total						\$0.00				
Construction Stockpile - Total		0470				22		SYSTEM	, ,	Payment Estimate Item Adjustment generated Stockpile Transaction			
Construction   Societies   Societies   Societies   Societies   Societies   Societies   Statifies   Societies   S													
Stockpile   STM					Stockpile - To								
Material				Stockpile		5		SYSTEM		Payment Estimate Item Adjustment generated Stockpile Transaction			
Material													
2021   Estimate Item Adjustment (0007) due to user baldwc2 overridding Payr Estimate Exception 1 on the current Payment Estimate.   22 Nov 3, SYSTEM   (\$6,595.05)					Stockpile STI								
2021   23				Material		22		SYSTEM	\$6,595.05	Estimate Item Adjustment (0007) due to user baldwc2 overridding Payment			
2021   Estimate tem Adjustment (0003) due to user baldwo2 overridding Payr Estimate Exception 2 on the current Payment Estimate.    1						22		SYSTEM	(\$6,595.05)				
2021   24   Dec 2, 2   SYSTEM   \$6,595.05   This adjustment offsets the original system-generated Material Payment Estimate   Exception 2 on the current Payment Estimate.						23		SYSTEM	\$6,595.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user baldwc2 overridding Payment Estimate Exception 2 on the current Payment Estimate.			
2021   Estimate Item Adjustment (0006) due to user baldwe2 overridding Payr Estimate Exception 2 on the current Payment Estimate.						23		SYSTEM	(\$6,595.05)				
Total   S0.00						24		SYSTEM	\$6,595.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user baldwc2 overridding Payment Estimate Exception 2 on the current Payment Estimate.			
Material - Total   Summary   Summa						24		SYSTEM	(\$6,595.05)				
STEEL   FORM   STEEL   ST					- Total				\$0.00				
Construction Stockpile   22   Nov 3, 2021   SYSTEM   (\$526.23)   Payment Estimate Item Adjustment generated Stockpile Transaction   Stockpile   Total   (\$526.23)				Material - Tota	ıl				\$0.00				
STEEL (EPOXY COATED    Total   (\$526.23)		0470 -	Total						\$0.00				
Construction Stockpile   Total   (\$526.23)		0500	STEEL (EPOXY			22		SYSTEM	(\$526.23)	Payment Estimate Item Adjustment generated Stockpile Transaction			
Construction Stockpile STMI - Total \$526.23 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile STMI - Total \$526.23 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile STMI - Total \$526.23 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile STMI - Total \$526.23 Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user watsom1 overridding Payres (\$188,924.80) Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate Exception 1 on the current Payment Estimate Item Adjustment (0006) due to user watsom1 overridding Payres (\$188,924.80) Payment Estimate Item Adjustment (0006) due to user watsom1 overridding Payres (\$188,924.80) Payment Estimate Exception 2 on the current Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user watsom1 overridding Payres (\$188,924.80) Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user watsom1 overridding Payres (\$188,924.80) Payment Estimate Exception 1 on the current Payment Estimate Item Adjustment (0004) due to user watsom1 overridding Payres (\$188,924.80) Payment Estimate Exception 1 on the current			,		- Total				(\$526.23)				
Stockpile   STMI    2020   S526.23				Construction	Stockpile - To				(\$526.23)				
Construction Stockpile STMI - Total   S526.23				Stockpile		5		SYSTEM		Payment Estimate Item Adjustment generated Stockpile Transaction			
S0.00													
Description   Concrete   Material   May 17, 2021   System   \$188,924.80   This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user watsom1 overridding Payment Estimate Exception 1 on the current Payment Estimate.   11		0500	Total	Construction	Stockpile STI	vii - Total							
11			LATEX MODIFIED	Material		11		SYSTEM		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user watsom1 overridding Payment			
12			WEARING			11		SYSTEM	(\$188,924.80)	Estimate Exception 1 on the current Payment Estimate.			
2021						12		SYSTEM	\$188,924.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user watsom1 overridding Payment Estimate Exception 2 on the current Payment Estimate.			
2021   Estimate Item Adjustment (0004) due to user watsom1 overridding Payl Estimate Exception 1 on the current Payment Estimate.    13						12		SYSTEM	(\$188,924.80)				
2021									13		SYSTEM	\$188,924.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user watsom1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
Material - Total   \$0.00						13		SYSTEM	(\$188,924.80)				
0530 - Total         \$0.00           0540         CLASS B-1 CONCRETE         8         Apr 2, 2021         SYSTEM (\$56,486.02)					- Total				\$0.00				
0540 CLASS B-1 CONCRETE 8 Apr 2, 2021 (\$56,486.02)				Material - Tota	ıl				\$0.00				
CONCRETE 2021		0530 -	Total						\$0.00				
- Total (\$56,486.02)		0540		Material		8		SYSTEM	(\$56,486.02)				
					- Total				(\$56,486.02)				



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3266	0540	CLASS B-1	Material - Tota	ıl				(\$56,486.02)	
		CONCRETE	MaterialCredit		9	Apr 16, 2021	SYSTEM	\$56,486.02	
				- Total		2021		\$56,486.02	
			MaterialCredit					\$56,486.02	
	0540 -	- Total	materiarorean	Total				\$0.00	
	0550	SUBSTRUCTURE	Material		8	Apr 2,	SYSTEM	(\$4,702.35)	
		REPAIR (FORMED)			10	2021 May 3,	SYSTEM	(\$12,161.25)	
						2021			
					13	Jun 16, 2021	SYSTEM	\$12,161.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user watsom1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					13	Jun 16, 2021	SYSTEM	(\$12,161.25)	
				- Total		2021		(\$16,863.60)	
			Material - Tota					(\$16,863.60)	
			MaterialCredit		9	Apr 16,	SYSTEM	\$4,702.35	
			Waterlaioredit		3	2021	OTOTEW	ψ+,702.00	
					11	May 17, 2021	SYSTEM	\$12,161.25	
				- Total				\$16,863.60	
			MaterialCredit	- Total				\$16,863.60	
	0550 -							\$0.00	
	0570	HALF-SOLE	Other Item Adjustment	OADJ	11	May 17, 2021	watsom1	\$18,438.00	Adjustment is being made so the contractor can receive payment for the work that has been completed. A change order should be approved before the next estimate.
					12	Jun 2, 2021	watsom1	(\$18,438.00)	Contractor was paid for this work on estimate 11. This adjustment makes the total of all adjustments 0.
				OADJ - Tota	al l			\$0.00	
			Other Item Ad						
			Other Item Ad	justment - To	tal			\$0.00	
			Other Item Ad		stal 8	Apr 2, 2021	SYSTEM	<b>\$0.00</b> (\$7,748.35)	
				justment - To	tal		SYSTEM SYSTEM	\$0.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is applied (if non-zero).
				justment - To	stal 8	2021 Apr 16, 2021 May 3,		<b>\$0.00</b> (\$7,748.35)	previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is
				justment - To	8 9	2021 Apr 16, 2021	SYSTEM	\$0.00 (\$7,748.35) \$7,748.35	previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is
				justment - To	9 10	2021 Apr 16, 2021 May 3, 2021 May 17,	SYSTEM	\$0.00 (\$7,748.35) \$7,748.35 (\$14,179.70)	previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is
				justment - To	9 10 11 12	2021 Apr 16, 2021 May 3, 2021 May 17, 2021 Jun 2,	SYSTEM SYSTEM	\$0.00 (\$7,748.35) \$7,748.35 (\$14,179.70) (\$18,438.00)	previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is applied (if non-zero).  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is
				justment - To Overrun Overrun - To	9 10 11 12	2021 Apr 16, 2021 May 3, 2021 May 17, 2021 Jun 2,	SYSTEM SYSTEM	\$0.00 (\$7,748.35) \$7,748.35 (\$14,179.70) (\$18,438.00) \$32,617.70	previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is applied (if non-zero).  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is
	0570 -	- Total	Overrun	justment - To Overrun Overrun - To	9 10 11 12	2021 Apr 16, 2021 May 3, 2021 May 17, 2021 Jun 2,	SYSTEM SYSTEM	\$0.00 (\$7,748.35) \$7,748.35 (\$14,179.70) (\$18,438.00) \$32,617.70	previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is applied (if non-zero).  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is
	<b>0570</b> - 0580	- Total FULL DEPTH REPAIR	Overrun	justment - To Overrun Overrun - To	9 10 11 12 otal	2021 Apr 16, 2021 May 3, 2021 May 17, 2021 Jun 2,	SYSTEM SYSTEM	\$0.00 (\$7,748.35) \$7,748.35 (\$14,179.70) (\$18,438.00) \$32,617.70 \$0.00	previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is applied (if non-zero).  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is
		FULL DEPTH	Overrun - Tota Other Item	justment - To Overrun Overrun - To	9 10 11 12 otal	2021 Apr 16, 2021 May 3, 2021 May 17, 2021 Jun 2, 2021 May 17, 7, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$7,748.35) \$7,748.35 (\$14,179.70) (\$18,438.00) \$32,617.70 \$0.00 \$0.00	previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is applied (if non-zero).  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is applied (if non-zero).  Adjustment is being made so the contractor can receive payment for the work that has been completed. A change order should be approved before the next
		FULL DEPTH	Overrun - Tota Other Item	justment - To Overrun Overrun - To	10 11 12 11 12 12	2021 Apr 16, 2021 May 3, 2021 May 17, 2021 Jun 2, 2021  May 17, 2021  Jun 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM watsom1	\$0.00 (\$7,748.35) \$7,748.35 (\$14,179.70) (\$18,438.00) \$32,617.70 \$0.00 \$0.00 \$5,550.60	previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is applied (if non-zero).  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is applied (if non-zero).  Adjustment is being made so the contractor can receive payment for the work that has been completed. A change order should be approved before the next estimate.  Contractor was paid for this work on estimate 11. This adjustment makes the
		FULL DEPTH	Overrun - Tota Other Item	Overrun - Total  OADJ - Total	10 11 12 12 12 14 14 15 15 16 16 16 16 16 16 16 16 16 16 16 16 16	2021 Apr 16, 2021 May 3, 2021 May 17, 2021 Jun 2, 2021  May 17, 2021  Jun 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM watsom1	\$0.00 (\$7,748.35) \$7,748.35 (\$14,179.70) (\$18,438.00) \$32,617.70 \$0.00 \$0.00 \$5,550.60	previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is applied (if non-zero).  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is applied (if non-zero).  Adjustment is being made so the contractor can receive payment for the work that has been completed. A change order should be approved before the next estimate.  Contractor was paid for this work on estimate 11. This adjustment makes the
		FULL DEPTH	Overrun - Tota Other Item Adjustment	Overrun - Total  OADJ - Total	10	2021 Apr 16, 2021 May 3, 2021 May 17, 2021 Jun 2, 2021  May 17, 2021  Jun 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM watsom1 watsom1	\$0.00 (\$7,748.35) \$7,748.35 (\$14,179.70) (\$18,438.00) \$32,617.70 \$0.00 \$0.00 \$5,550.60 (\$5,550.60)	previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is applied (if non-zero).  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is applied (if non-zero).  Adjustment is being made so the contractor can receive payment for the work that has been completed. A change order should be approved before the next estimate.  Contractor was paid for this work on estimate 11. This adjustment makes the
		FULL DEPTH	Overrun - Tota Other Item Adjustment Other Item Ad	Overrun - Total  OADJ - Tota	110	2021 Apr 16, 2021 May 3, 2021 May 17, 2021 Jun 2, 2021 Jun 2, 2021  Apr 16, 4	SYSTEM SYSTEM SYSTEM SYSTEM watsom1	\$0.00 (\$7,748.35) \$7,748.35 (\$14,179.70) (\$18,438.00) \$32,617.70 \$0.00 \$0.00 \$5,550.60 (\$5,550.60)	previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is applied (if non-zero).  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is applied (if non-zero).  Adjustment is being made so the contractor can receive payment for the work that has been completed. A change order should be approved before the next estimate.  Contractor was paid for this work on estimate 11. This adjustment makes the
		FULL DEPTH	Overrun - Tota Other Item Adjustment Other Item Ad	Overrun - Total  OADJ - Tota	10	2021 Apr 16, 2021 May 3, 2021 Jun 2, 2021  May 17, 2021  Jun 2, 2021  Apr 16, 2021  May 3,	SYSTEM SYSTEM SYSTEM SYSTEM watsom1 watsom1	\$0.00 (\$7,748.35) \$7,748.35 (\$14,179.70) (\$18,438.00) \$32,617.70 \$0.00 \$0.00 \$5,550.60 (\$5,550.60) \$0.00 (\$6,000 \$0.00 \$0.00 \$0.00 \$0.00	previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is applied (if non-zero).  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is applied (if non-zero).  Adjustment is being made so the contractor can receive payment for the work that has been completed. A change order should be approved before the next estimate.  Contractor was paid for this work on estimate 11. This adjustment makes the total of all adjustments 0.  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',63.80000 - 63.80000, 'is



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3266	0580	FULL DEPTH REPAIR	Overrun	Overrun					applied (if non-zero).
		KLIAIK		Overrun - T	otal			\$0.00	
			Overrun - Tota	ıl				\$0.00	
	0580 -	Total						\$0.00	
	0590	REINFORCING STEEL (EPOXY COATED)	Construction Stockpile		8	Apr 2, 2021	SYSTEM	(\$2,855.51)	Payment Estimate Item Adjustment generated Stockpile Transaction
		J 21 11 = 2 ,		- Total				(\$2,855.51)	
			Construction S	Stockpile - To	otal			(\$2,855.51)	
			Construction Stockpile STMI		5	Nov 2, 2020	SYSTEM	\$2,855.51	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$2,855.51	
			Construction S	Stockpile STI				\$2,855.51	
			Material		8	Apr 2, 2021	SYSTEM	(\$9,202.00)	
				- Total				(\$9,202.00)	
			Material - Tota					(\$9,202.00)	
			MaterialCredit		9	Apr 16, 2021	SYSTEM	\$9,202.00	
				- Total				\$9,202.00	
			MaterialCredit	- Total				\$9,202.00	
	0590 -							\$0.00	
	0620	CURB BLOCKOUT	Construction Stockpile STMI		5	Nov 2, 2020	SYSTEM	\$2,816.11	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$2,816.11	
			Construction S	Stockpile STI	MI - Total			\$2,816.11	
	0620 -							\$2,816.11	
	0660	OPTIONAL Mai CONCRETE WEARING	Material		23	Nov 16, 2021	SYSTEM	\$53,427.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user baldwc2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		SURFACE			23	Nov 16, 2021	SYSTEM	(\$53,427.60)	
					24	Dec 2, 2021	SYSTEM	\$53,427.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user baldwc2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					24	Dec 2, 2021	SYSTEM	(\$53,427.60)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0660 -	Total						\$0.00	
	0670	CURB BLOCKOUT	Construction Stockpile		20	Oct 4, 2021	SYSTEM	(\$2,816.11)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$2,816.11)	
			Construction S	Stockpile - To	otal			(\$2,816.11)	
			Construction Stockpile STMI		5	Nov 2, 2020	SYSTEM	\$2,816.11	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$2,816.11	
			Construction S	Stockpile STI				\$2,816.11	
			Material		20	Oct 4, 2021	SYSTEM	\$24,941.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user baldwc2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					20	Oct 4, 2021	SYSTEM	(\$24,941.00)	
				- Total				\$0.00	
			Material - Tota	ı				\$0.00	
	0670 -	Total						\$0.00	
	0690	DECK REPAIR WITH VOID TUBE REPLACEMENT	Material		21	Oct 18, 2021	SYSTEM	\$30,275.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user baldwc2 overridding Payment Estimate Exception 1 on the current Payment Estimate.



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
266	0690	DECK REPAIR WITH VOID TUBE REPLACEMENT	Material		21	Oct 18, 2021	SYSTEM	(\$30,275.50)		
					22	Nov 3, 2021	SYSTEM	\$41,676.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user baldwc2 overridding Payment Estimate Exception 3 on the current Payment Estimate.	
					22	Nov 3, 2021	SYSTEM	(\$41,676.00)		
					23	Nov 16, 2021	SYSTEM	\$50,358.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user baldwc2 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
					23	Nov 16, 2021	SYSTEM	(\$50,358.50)		
					24	Dec 2, 2021	SYSTEM	\$20,158.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user baldwc2 overridding Payment Estimate Expension 2 on the ourset Payment Estimate	
					24	Dec 2, 2021	SYSTEM	(\$20,158.50)	Estimate Exception 3 on the current Payment Estimate.	
				- Total		2021		\$0.00		
			Material - Tota	1				\$0.00		
			Overrun	Overrun	21	Oct 18, 2021	SYSTEM	\$3,850.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception on the current Payment Estimate. Material Insufficiency Quantity 401.000; Overrun Quantity Balance 51.00.	
					21	Oct 18, 2021	SYSTEM	(\$3,850.50)		
				Overrun - T	otal			\$0.00		
			Overrun - Tota	al				\$0.00		
	0690 -	· Total						\$0.00		
	0720	CURB BLOCKOUT	Construction Stockpile STMI		5	Nov 2, 2020	SYSTEM	\$1,875.85	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				\$1,875.85		
			Construction Stockpile STMI - Total					\$1,875.85		
	0720 -	· Total						\$1,875.85		
	0780	CURB BLOCKOUT	Construction Stockpile		20	Oct 4, 2021	SYSTEM	(\$1,875.85)	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				(\$1,875.85)		
			Construction Construction Stockpile STMI	Stockpile - To	otal			(\$1,875.85)		
					5	Nov 2, 2020	SYSTEM	\$1,875.85	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				\$1,875.85		
				Construction Material	Stockpile STI	MI - Total 20	Oct 4, 2021	SYSTEM	\$1,875.85 \$18,662.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user baldwc2 overridding Paymen
					20	Oct 4,	SYSTEM	(\$18,662.00)	Estimate Exception 4 on the current Payment Estimate.	
				- Total		2021		\$0.00		
			Material - Tota	ıl				\$0.00		
	0780 - Total							\$0.00		
	0790	HALF-SOLE REPAIR	Material		20	Oct 4, 2021	SYSTEM	\$9,438.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user baldwc2 overridding Paymen Estimate Exception 6 on the current Payment Estimate.	
					20	Oct 4, 2021	SYSTEM	(\$9,438.50)		
				- Total				\$0.00		
			Material - Tota	ıl				\$0.00		
	0790 -	Total						\$0.00		
	0800	DECK REPAIR WITH VOID TUBE REPLACEMENT	ID TUBE		20	Oct 4, 2021	SYSTEM	\$3,850.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user baldwc2 overridding Paymer Estimate Exception 7 on the current Payment Estimate.	
					20	Oct 4, 2021	SYSTEM	(\$3,850.50)	,	



et	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
66	0800	DECK REPAIR WITH VOID TUBE	Material	- Total				\$0.00	
		REPLACEMENT	Material - Tota	ıl				\$0.00	
	0800 -	Total						\$0.00	
-	0850	PREFORMED COMPRESSION SEAL	Material		24	Dec 2, 2021	SYSTEM	\$10,466.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user baldwc2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					24	Dec 2, 2021	SYSTEM	(\$10,466.50)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0850 -	Total						\$0.00	
•	0920	CLASS B-2 CONCRETE	Material		16	Aug 2, 2021	SYSTEM	\$8,520.19	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user baldwc2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					16	Aug 2, 2021	SYSTEM	(\$8,520.19)	
					17	Aug 16, 2021	SYSTEM	\$12,780.28	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user baldwc2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					17	Aug 16, 2021	SYSTEM	(\$12,780.28)	
				- Total		2021		\$0.00	
			Material - Tota					\$0.00	
	0920 -	Total	material rote	<u>''</u>				\$0.00	
	0930	REINFORCING STEEL (EPOXY COATED)	Construction Stockpile		16	Aug 2, 2021	SYSTEM	(\$243.75)	Payment Estimate Item Adjustment generated Stockpile Transaction
					17	Aug 16, 2021	SYSTEM	(\$121.88)	Payment Estimate Item Adjustment generated Stockpile Transaction
					18	Sep 1, 2021	SYSTEM	(\$119.19)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$484.82)	
			Construction Stockpile - Total					(\$484.82)	
			Construction Stockpile STMI		5	Nov 2, 2020	SYSTEM	\$484.82	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$484.82	
	Construction Stockpile STMI - Total								
	0930 -	Total						\$0.00	
1	0950	STRIP SEAL EXPANSION JOINT SYSTEM	Construction Stockpile		18	Sep 1, 2021	SYSTEM	(\$13,856.25)	Payment Estimate Item Adjustment generated Stockpile Transaction
		JOHN GIGIEM		- Total				(\$13,856.25)	
			Construction	Stockpile - To	otal			(\$13,856.25)	
			Construction Stockpile STMI		3	Oct 1, 2020	SYSTEM	\$13,856.25	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$13,856.25	
			Construction	Stockpile STI	/II - Total			\$13,856.25	
	0950 -							\$0.00	
09	0970	PREFORMED COMPRESSION SEAL	Material		24	Dec 2, 2021	SYSTEM	\$8,753.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user baldwc2 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					24	Dec 2, 2021	SYSTEM	(\$8,753.80)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0970 -							\$0.00	
1	0990	PREFORMED COMPRESSION SEAL	Material		23	Nov 16, 2021	SYSTEM	\$8,753.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user baldwc2 overridding Payment Estimate Exception 5 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
J4P3266	0990	PREFORMED COMPRESSION SEAL	Material		24	Dec 2, 2021	SYSTEM	\$8,753.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user baldwc2 overridding Payment Estimate Exception 9 on the current Payment Estimate.			
					24	Dec 2, 2021	SYSTEM	(\$8,753.80)				
				- Total				\$0.00				
			Material - Total					\$0.00				
	0990 -	Total						\$0.00				
	1020	PREFORMED COMPRESSION SEAL	Material		24	Dec 2, 2021	SYSTEM	\$9,134.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user baldwc2 overridding Payment Estimate Exception 10 on the current Payment Estimate.			
					24	Dec 2, 2021	SYSTEM	(\$9,134.40)				
				- Total				\$0.00				
			Material - Tota	ıl				\$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user baldwc2 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user baldwc2 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user watsom1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  Payment Estimate Item Adjustment generated Stockpile Transaction  Payment Estimate Item Adjustment generated Stockpile Transaction			
	1020 -	Total						\$0.00				
	1060	CLASS B-2 CONCRETE	Material		12	Jun 2, 2021	SYSTEM	\$48,810.58	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user watsom1 overridding Payment Estimate Exception 12 on the current Payment Estimate.			
					12	Jun 2, 2021	SYSTEM	(\$48,810.58)				
				- Total				\$0.00				
			Material - Tota	ıl				\$0.00				
	1060 -	Total						\$0.00				
	1080	REINFORCING STEEL (EPOXY COATED)	Construction Stockpile	12	Jun 2, 2021	SYSTEM	(\$1,712.91)	Payment Estimate Item Adjustment generated Stockpile Transaction				
			- Total  Construction Stockpile - Total					(\$1,712.91)				
				Stockpile - To				(\$1,712.91)				
			Construction Stockpile STMI		5	Nov 2, 2020	SYSTEM	\$1,712.91	Payment Estimate Item Adjustment generated Stockpile Transaction			
			- Total					\$1,712.91				
			Construction	Stockpile STI	MI - Total			\$1,712.91				
	1080 -	Total						\$0.00				
	1100	STRIP SEAL EXPANSION JOINT SYSTEM	Stockpile		12	Jun 2, 2021	SYSTEM	(\$38,590.03)	Payment Estimate Item Adjustment generated Stockpile Transaction			
				- Total				(\$38,590.03)				
			Construction	Stockpile - To	otal			(\$38,590.03)				
			Construction Stockpile STMI		3	Oct 1, 2020	SYSTEM	\$38,590.03	Payment Estimate Item Adjustment generated Stockpile Transaction			
				- Total				\$38,590.03				
			Construction Stockpile STMI - Total					\$38,590.03				
	1100 -							\$0.00				
	1140	REINFORCING STEEL (EPOXY COATED)	Construction Stockpile		10	May 3, 2021	SYSTEM	(\$1,390.36)	Payment Estimate Item Adjustment generated Stockpile Transaction			
		COATED)		- Total				(\$1,390.36)				
			Construction	Stockpile - To	otal			(\$1,390.36)				
			Construction Stockpile		5	Nov 2, 2020	SYSTEM	\$1,390.36	Payment Estimate Item Adjustment generated Stockpile Transaction			
			2	- Total				\$1,390.36				
			Construction	Stockpile STI	VII - Total			\$1,390.36				
	1140 -	Total						\$0.00				
	1160	STRIP SEAL EXPANSION JOINT SYSTEM	ON Stockpile		10	May 3, 2021	SYSTEM	(\$17,280.62)	Payment Estimate Item Adjustment generated Stockpile Transaction			
					11	May 17, 2021	SYSTEM	(\$17,280.63)	Payment Estimate Item Adjustment generated Stockpile Transaction			
				- Total				(\$34,561.25)				
			Construction	Stockpile - To	otal			(\$34,561.25)				
			Construction		3	Oct 1,	SYSTEM	\$34,561.25	Payment Estimate Item Adjustment generated Stockpile Transaction			



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3266	1160	STRIP SEAL EXPANSION	Stockpile STMI			2020			
		JOINT SYSTEM	STIVII	- Total				\$34,561.25	
			Construction	Stockpile STI	VII - Total			\$34,561.25	
	1160 -	Total						\$0.00	
	1200	CLASS B-2 CONCRETE	Material		14	Jul 1, 2021	SYSTEM	\$24,838.52	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user baldwc2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					14	Jul 1, 2021	SYSTEM	(\$24,838.52)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	1200 -	Total						\$0.00	
	1210	REINFORCING STEEL (EPOXY COATED)	Construction Stockpile		14	Jul 1, 2021	SYSTEM	(\$968.30)	Payment Estimate Item Adjustment generated Stockpile Transaction
		COATED)			15	Jul 16, 2021	SYSTEM	(\$963.65)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$1,931.95)	
			Construction	Stockpile - To	otal			(\$1,931.95)	
			Construction Stockpile		5	Nov 2, 2020	SYSTEM	\$1,931.95	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$1,931.95	
			Construction	Stockpile STI	VII - Tota <u>l</u>			\$1,931.95	
			Material		14	Jul 1, 2021	SYSTEM	\$4,495.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user baldwc2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					14	Jul 1, 2021	SYSTEM	(\$4,495.00)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	1210 -	Total						\$0.00	
	1230	STRIP SEAL EXPANSION JOINT SYSTEM	Construction Stockpile		14	Jul 1, 2021	SYSTEM	(\$19,295.01)	Payment Estimate Item Adjustment generated Stockpile Transaction
					15	Jul 16, 2021	SYSTEM	(\$19,295.02)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$38,590.03)	
			Construction	Stockpile - To	otal			(\$38,590.03)	
			Construction Stockpile STMI		3	Oct 1, 2020	SYSTEM	\$38,590.03	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$38,590.03	
			Construction Stockpile STMI		II - Total			\$38,590.03	
	1230 -	Total						\$0.00	
	5001	IMPACT ATTENUATOR 65 MPH (SAND	Material		12	Jun 2, 2021	SYSTEM	\$6,834.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user watsom1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		BARREL ARRAY)			12	Jun 2, 2021	SYSTEM	(\$6,834.56)	
				- Total				\$0.00	
			Material - Tota	Material - Total					
	5001 -	Total						\$0.00	
	5007	MISC.	C. Material		12	Jun 2, 2021	SYSTEM	\$10,745.28	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user watsom1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					12	Jun 2, 2021	SYSTEM	(\$10,745.28)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	5007 -	Total						\$0.00	
	5010	PREF THERMO PVMT MARK, 24	Material		12	Jun 2, 2021	SYSTEM	\$970.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user watsom1 overridding Payment





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3266	5010	IN WHIT	Material						Estimate Exception 4 on the current Payment Estimate.
					12	Jun 2, 2021	SYSTEM	(\$970.20)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	5010 -	Total						\$0.00	
	5012	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	Overrun	Overrun	21	Oct 18, 2021	SYSTEM	(\$392.03)	
					22	Nov 3, 2021	SYSTEM	\$392.03	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',9.95000 - 9.95000, 'is applied (if non-zero).
				Overrun - Total				\$0.00	
			Overrun - Total					\$0.00	
	5012 -	Total						\$0.00	
	5013	TACK COAT	Overrun	Overrun	20	Oct 4, 2021	SYSTEM	(\$2.91)	
					22	Nov 3, 2021	SYSTEM	\$2.91	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',4.16000 - 4.16000, 'is applied (if non-zero).
				Overrun - Total				\$0.00	
			Overrun - Tota	al				\$0.00	
	5013 -	Total						\$0.00	
J4P3266 -	P3266 - Total							\$37,504.00	
Overall -	Total							\$37,504.00	