

Pay Estimate Created Date: April 2, 2021

Progress Estimate Number	Contract ID	200417-C05		1 Original Contract Amount \$965,424.35
6	Prime Contractor	r Capital Electric Line Builders, Inc	. Pay Period End April 1, 2021	Net Change Order Amount \$94,730.23
•				Current Contract Amount \$1,060,154.58

Approval Date		By User
April 5, 2021	Generated and Approved (and should be considered Draft) at the Project Office Level by	karlic1
April 5, 2021	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	warrem1
April 6, 2021	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
December 1, 2020	April 30, 2021		49.53%

	Contract Informational Dat	tes	Milestones
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract
Acceptance Date			
Awarded Date	May 6, 2020	May 6, 2020	
Letting Date	April 17, 2020	April 17, 2020	
Notice to Proceed Date	June 8, 2020	June 8, 2020	
Open to Traffic Date			
Work Began Date			

Contract Total Pa	ay For Estimate No. 6			
		This Estimate	Previous	To Date
200417-C05	Total Doots d Marco Dov	\$60.454.05	Ф455 007 25	Ø505 050 40
	Total Posted Items Pay Gross Item Adjustments	\$69,151.05 (\$37,442.60)	\$455,907.35 (\$12,301.75)	\$525,058.40 (\$49,744.35)
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage Other Contract Adjustments	\$0.00 \$0.00	\$0.00 \$0.00	\$0.00 \$0.00
	Other Contract Adjustments	φ0.00	\$443,605.60	\$475,314.05
Contract Total Pa	ayable This Estimate:	\$31,708.45		

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J4S3294	0020	6169902	MISC.TEMPORARY TRAFFIC CONTROL TYPE 1	EA	\$105.000	1	\$105.00
	0030	6169902	MISC.TEMPORARY TRAFFIC CONTROL TYPE 2	EA	\$430.000	5	\$2,150.00
	0040	6169902	MISC.TEMPORARY TRAFFIC CONTROL TYPE 3	EA	\$455.000	1	\$455.00
	0050	6169902	MISC.TEMPORARY TRAFFIC CONTROL TYPE 4	EA	\$455.000	3	\$1,365.00
	0100	9020514	SIGNAL HEAD, TYPE 4B	EA	\$1,435.000	2	\$2,870.00
	0110	9020833	SH-FLAT SHEET - SIGNAL SIGN	SQFT	\$57.000	15	\$855.00
	0120	9020834	SIGNAL SIGN, MOUNTING HARDWARE	EA	\$170.000	1	\$170.00
	0130	9024283	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	EA	\$15,240.000	2	\$30,480.00
	0160	9028208	CABLE, 8 AWG 1 CONDUCTOR, POWER	LF	\$2.750	78	\$214.50
	0250	9029902	MISC.LENS REPLACEMENT, ARROWS TO CIRCULAR	EA	\$270.000	4	\$1,080.00
	0340	9108353	FIBER OPTIC CABLE, 12-STRAND, SINGLE MODE	LF	\$3.350	4,577	\$15,332.95
	0410	9109902	MISC.CCTV CAMERA ASSEMBLY, DOME TYPE WITH CABLE	EA	\$4,670.000	1	\$4,670.00
	0450	9109902	MISC.FIBER OPTIC SPLICE ENCLOSURE	EA	\$615.000	1	\$615.00
	0460	9109902	MISC.FIBER OPTIC SPLICE, UNDERGROUND	EA	\$210.000	2	\$420.00
	0530	9109902	MISC.PRE-TERMINATED FIBER PANEL	EA	\$530.000	5	\$2,650.00
	0570	9109903	MISC.TRACER WIRE NO. 14 FOR EXISTING CONDUIT	LF	\$1.100	3,696	\$4,065.60
	0590	6169902	MISC.TEMPORARY TRAFFIC CONTROL TYPE 4	EA	\$785.000	1	\$785.00
	0670	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	LF	\$31.000	28	\$868.00

Revision 4/1/2020 Page 1 of 32



Pay Estimate Created Date: April 2, 2021

Progress Estimate Number
6 Contract ID 200417-C05 Pay Period Start March 16, 2021 Original Contract Amount \$965,424.35 Prime Contractor Capital Electric Line Builders, Inc. Pay Period End April 1, 2021 Net Change Order Amount \$94,730.23 Current Contract Amount \$1,060,154.58

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount			
Project J4S32	294 - Total						\$69,151.05			
Overall - Tota	rall - Total									

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Project	Line	Item Description	Adjustment	Other Item	Comments	Adjustment	Line Item	Adjustment
Number	No.	item Description	Type	Adjustment Type	Confinents	Quantity	Adjustment Unit Price	amount
4S3294	0070	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	Material			-120	\$11.25	(\$1,350.00)
	0070	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0032) due to user johnsse overridding Payment Estimate Exception 1 on the current Payment Estimate.	120	\$11.25	\$1,350.00
	0800	CABLE, 12 AWG 2 CONDUCTOR	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-74	\$3.75	(\$277.50
	0800	CABLE, 12 AWG 2 CONDUCTOR	Material			-724	\$3.75	(\$2,715.00
	0800	CABLE, 12 AWG 2 CONDUCTOR	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0017) overridding Payment Estimate Exception 42 on the current Payment Estimate. Material Insufficiency Quantity 724.000; Overrun Quantity Balance 74.00.	74	\$3.75	\$277.50
	0800	CABLE, 12 AWG 2 CONDUCTOR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0018) due to user johnsse overridding Payment Estimate Exception 16 on the current Payment Estimate.	724	\$3.75	\$2,715.00
	0090	SIGNAL HEAD, TYPE 4C	Material			-6	\$1,170.00	(\$7,020.00
	0090	SIGNAL HEAD, TYPE 4C	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0026) due to user johnsse overridding Payment Estimate Exception 2 on the current Payment Estimate.	6	\$1,170.00	\$7,020.00
	0100	SIGNAL HEAD, TYPE 4B	Material			-7	\$1,435.00	(\$10,045.00
	0100	SIGNAL HEAD, TYPE 4B	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0024) due to user johnsse overridding Payment Estimate Exception 3 on the current Payment Estimate.	7	\$1,435.00	\$10,045.00
	0110	SH-FLAT SHEET - SIGNAL SIGN	Material			-99	\$57.00	(\$5,643.00
	0110	SH-FLAT SHEET - SIGNAL SIGN	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0025) due to user johnsse overridding Payment Estimate Exception 4 on the current Payment Estimate.	99	\$57.00	\$5,643.00
	0130	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	Overrun			-1	\$15,240.00	(\$15,240.00)
	0130	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	Overrun			-1	\$15,240.00	(\$15,240.00)
	0130	CONTROLLER ASSEMBLY	Material			-11	\$15,240.00	(\$167,640.00

Revision 4/1/2020 Page 2 of 32



Pay Estimate Created Date: April 2, 2021

Progress Estimate Number
6 Contract ID 200417-C05 Pay Period Start March 16, 2021 Original Contract Amount \$965,424.35 Prime Contractor Capital Electric Line Builders, Inc. Pay Period End April 1, 2021 Net Change Order Amount \$94,730.23 Current Contract Amount \$1,060,154.58

	ici Amount						
Adjustment amount	Line Item Adjustment Unit Price	Adjustment Quantity	Comments	Other Item Adjustment Type	Adjustment Type	Item Description	Line No.
						HOUSING, NEMA TS2 CONTROLLER	
\$15,240.00	\$15,240.00	1	This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 34 on the current Payment Estimate. Material Insufficiency Quantity 11.000; Overrun Quantity Balance 2.00.		Overrun	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	0130
\$15,240.00	\$15,240.00	1	This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 34 on the current Payment Estimate. Material Insufficiency Quantity 11.000; Overrun Quantity Balance 2.00.		Overrun	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	0130
\$167,640.00	\$15,240.00	11	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user johnsse overridding Payment Estimate Exception 5 on the current Payment Estimate.		Material	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	0130
(\$30,480.00			Entered to hold overrun amount until a change order is approved.	Overrun	Other Item Adjustment	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	0130
(\$3,268.00	\$38.00	-86	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).		Overrun	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	0140
(\$26,790.0	\$38.00	-705			Material	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	0140
\$3,268.00	\$38.00	86	This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 35 on the current Payment Estimate. Material Insufficiency Quantity 705.000; Overrun Quantity Balance 86.00.		Overrun	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	0140
\$26,790.00	\$38.00	705	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user johnsse overridding Payment Estimate Exception 8 on the current Payment Estimate.		Material	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	0140
(\$1,320.00	\$88.00	-15			Material	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	0150
\$1,320.00	\$88.00	15	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0027) due to user johnsse overridding Payment Estimate Exception 13 on the current Payment Estimate.		Material	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	0150
(\$2,392.50	\$2.75	-870			Material	CABLE, 8 AWG 1 CONDUCTOR, POWER	0160
\$2,392.50	\$2.75	870	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0028) due to user johnsse overridding Payment Estimate Exception 15 on the current Payment Estimate.		Material	CABLE, 8 AWG 1 CONDUCTOR, POWER	0160
(\$263.50	\$3.10	-85	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).		Overrun	CABLE, 16 AWG 2 CONDUCTOR	0170
(\$1,782.50	\$3.10	-575			Material	CABLE, 16 AWG 2 CONDUCTOR	0170
\$263.50	\$3.10	85	This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0006) overridding Payment		Overrun	CABLE, 16 AWG 2 CONDUCTOR	0170

Revision 4/1/2020 Page 3 of 32



Pay Estimate Created Date: April 2, 2021

Progress Estimate Number
6 Contract ID 200417-C05 Pay Period Start March 16, 2021 Original Contract Amount \$965,424.35 Prime Contractor Capital Electric Line Builders, Inc. Pay Period End April 1, 2021 Net Change Order Amount \$94,730.23 Current Contract Amount \$1,060,154.58

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
4S3294					Estimate Exception 36 on the current Payment Estimate. Material Insufficiency Quantity 575.000; Overrun Quantity Balance 85.00.			
	0170	CABLE, 16 AWG 2 CONDUCTOR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user johnsse overridding Payment Estimate Exception 17 on the current Payment Estimate.	575	\$3.10	\$1,782.50
	0180	CABLE, 16 AWG 5 CONDUCTOR	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-90	\$4.25	(\$382.50
	0180	CABLE, 16 AWG 5 CONDUCTOR	Material			-580	\$4.25	(\$2,465.00
	0180	CABLE, 16 AWG 5 CONDUCTOR	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 37 on the current Payment Estimate. Material Insufficiency Quantity 580.000; Overrun Quantity Balance 90.00.	90	\$4.25	\$382.50
	0180	CABLE, 16 AWG 5 CONDUCTOR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user johnsse overridding Payment Estimate Exception 18 on the current Payment Estimate.	580	\$4.25	\$2,465.00
	0190	CABLE, 16 AWG 7 CONDUCTOR	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-455	\$4.85	(\$2,206.75
	0190	CABLE, 16 AWG 7 CONDUCTOR	Material			-3,375	\$4.85	(\$16,368.75
	0190	CABLE, 16 AWG 7 CONDUCTOR	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0010) overridding Payment Estimate Exception 38 on the current Payment Estimate. Material Insufficiency Quantity 3375.000; Overrun Quantity Balance 455.00.	455	\$4.85	\$2,206.75
	0190	CABLE, 16 AWG 7 CONDUCTOR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user johnsse overridding Payment Estimate Exception 19 on the current Payment Estimate.	3,375	\$4.85	\$16,368.75
	0200	CABLE, LOOP DETECTOR, LEAD-IN	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-335	\$4.10	(\$1,373.50
	0200	CABLE, LOOP DETECTOR, LEAD-IN	Material			-1,885	\$4.10	(\$7,728.50
	0200	CABLE, LOOP DETECTOR, LEAD-IN	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0012) overridding Payment Estimate Exception 39 on the current Payment Estimate. Material Insufficiency Quantity 1885.000; Overrun Quantity Balance 335.00.	335	\$4.10	\$1,373.50
	0200	CABLE, LOOP DETECTOR, LEAD-IN	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user johnsse overridding Payment Estimate Exception 20 on the current Payment Estimate.	1,885	\$4.10	\$7,728.50
	0210	POWER SUPPLY ASSEMBLY, TYPE-2 WITH 120V LIGHTING CONTROL CABINET	Material			-4	\$5,300.00	(\$21,200.00

Revision 4/1/2020 Page 4 of 32



Pay Estimate Created Date: April 2, 2021

Progress Estimate Number
6 Contract ID 200417-C05 Pay Period Start March 16, 2021 Original Contract Amount \$965,424.35 Prime Contractor Capital Electric Line Builders, Inc. Pay Period End April 1, 2021 Net Change Order Amount \$94,730.23 Current Contract Amount \$1,060,154.58

		irrent Contra						
Adjustment amount	Line Item Adjustment Unit Price	Adjustment Quantity	Comments	Other Item Adjustment Type	Adjustment Type	Item Description	Line No.	Project Number
\$21,200.00	\$5,300.00	4	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0029) due to user johnsse overridding Payment Estimate Exception 21 on the current Payment Estimate.		Material	POWER SUPPLY ASSEMBLY, TYPE-2 WITH 120V LIGHTING CONTROL CABINET	0210	1S3294
(\$4,530.00	\$2,265.00	-2	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).		Overrun	PULL BOX, PREFORMED CLASS 3	0220	
(\$13,590.00	\$2,265.00	-6			Material	PULL BOX, PREFORMED CLASS 3	0220	
\$4,530.00	\$2,265.00	2	This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0014) overridding Payment Estimate Exception 40 on the current Payment Estimate. Material Insufficiency Quantity 6.000; Overrun Quantity Balance 2.00.		Overrun	PULL BOX, PREFORMED CLASS 3	0220	
\$13,590.00	\$2,265.00	6	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user johnsse overridding Payment Estimate Exception 23 on the current Payment Estimate.		Material	PULL BOX, PREFORMED CLASS 3	0220	
(\$18,000.00	\$1,800.00	-10			Material	BASE, CONCRETE	0230	
\$18,000.00	\$1,800.00	10	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0030) due to user johnsse overridding Payment Estimate Exception 26 on the current Payment Estimate.		Material	BASE, CONCRETE	0230	
(\$540.00	\$270.00	-2			Overrun	MISC.	0250	
\$540.00	\$270.00	2	This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0016) due to user johnsse overridding Payment Estimate Exception 41 on the current Payment Estimate.		Overrun	MISC.	0250	
(\$540.00			Entered to hold overrun amount until a change order is approved.	Overrun	Other Item Adjustment	MISC.	0250	
(\$4,668.00	\$6.00	-778			Material	MISC.	0270	
\$4,668.00	\$6.00	778	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0031) due to user johnsse overridding Payment Estimate Exception 30 on the current Payment Estimate.		Material	MISC.	0270	
(\$2,775.60	\$10.80	-257			Material	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE	0280	
\$2,775.60	\$10.80	257	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0033) due to user johnsse overridding Payment Estimate Exception 7 on the current Payment Estimate.		Material	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE	0280	
(\$1,500.00	\$100.00	-15			Material	CONDUIT, 4 IN., TRENCH WITH TRACER WIRE	0300	
\$1,500.00	\$100.00	15	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0034) due to user johnsse overridding Payment Estimate Exception 10 on the current Payment Estimate.		Material	CONDUIT, 4 IN., TRENCH WITH TRACER WIRE	0300	
(\$1,035.00	\$17.25	-60			Material	CONDUIT, 2 IN., PUSHED WITH TRACER WIRE	0310	
\$1,035.00	\$17.25	60	This adjustment offsets the original system- generated Material Payment Estimate Item		Material	CONDUIT, 2 IN., PUSHED WITH TRACER WIRE	0310	

Revision 4/1/2020 Page 5 of 32



Pay Estimate Created Date: April 2, 2021

Progress Estimate Number
6 Contract ID 200417-C05 Pay Period Start March 16, 2021 Original Contract Amount \$965,424.35 Prime Contractor Capital Electric Line Builders, Inc. Pay Period End April 1, 2021 Net Change Order Amount \$94,730.23 Current Contract Amount \$1,060,154.58

		in ent contra						
Adjustment amount	Line Item Adjustment Unit Price	Adjustment Quantity	Comments	Other Item Adjustment Type	Adjustment Type	Item Description	Line No.	Project Number
			Adjustment (0035) due to user johnsse overridding Payment Estimate Exception 11 on the current Payment Estimate.					4S3294
(\$15,332.95	\$3.35	-4,577			Material	FIBER OPTIC CABLE, 12- STRAND, SINGLE MODE	0340	
\$15,332.95	\$3.35	4,577	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0036) due to user johnsse overridding Payment Estimate Exception 31 on the current Payment Estimate.		Material	FIBER OPTIC CABLE, 12- STRAND, SINGLE MODE	0340	
(\$10,325.00	\$2,065.00	-5			Material	PULL BOX, PREFORMED CLASS 3	0350	
\$10,325.00	\$2,065.00	5	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0037) due to user johnsse overridding Payment Estimate Exception 32 on the current Payment Estimate.		Material	PULL BOX, PREFORMED CLASS 3	0350	
(\$5,160.00	\$1,720.00	-3			Material	PULL BOX, PREFORMED CLASS 5	0360	
\$5,160.00	\$1,720.00	3	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0038) due to user johnsse overridding Payment Estimate Exception 33 on the current Payment Estimate.		Material	PULL BOX, PREFORMED CLASS 5	0360	
(\$105.60	\$1.10	-96			Overrun	MISC.	0570	
\$105.60	\$1.10	96	This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0019) due to user johnsse overridding Payment Estimate Exception 43 on the current Payment Estimate.		Overrun	MISC.	0570	
(\$150.60			Entered to hold overrun amount until a change order is approved.	Overrun	Other Item Adjustment	MISC.	0570	
(\$14,580.00	\$14,580.00	-1			Material	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	0650	
\$14,580.00	\$14,580.00	1	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0039) due to user johnsse overridding Payment Estimate Exception 6 on the current Payment Estimate.		Material	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	0650	
(\$868.00	\$31.00	-28			Overrun	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	0670	
(\$4,154.00	\$31.00	-134			Material	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	0670	
\$868.00	\$31.00	28	This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0020) overridding Payment Estimate Exception 44 on the current Payment Estimate. Material Insufficiency Quantity 134.000; Overrun Quantity Balance 28.00.		Overrun	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	0670	
\$4,154.00	\$31.00	134	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0021) due to user johnsse overridding Payment Estimate Exception 9 on the current Payment Estimate.		Material	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	0670	
(\$868.00			Entered to hold overrun amount until a change order is approved.	Overrun	Other Item Adjustment	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	0670	
(\$3,220.00	\$23.00	-140			Material	CONDUIT, 2 IN., PUSHED WITH TRACER WIRE	0680	

Revision 4/1/2020 Page 6 of 32



Pay Estimate Created Date: April 2, 2021

Progress Estimate Number
6 Contract ID 200417-C05 Pay Period Start March 16, 2021 Original Contract Amount \$965,424.35 Prime Contractor Capital Electric Line Builders, Inc. Pay Period End April 1, 2021 Net Change Order Amount \$94,730.23 Current Contract Amount \$1,060,154.58

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4S3294	0680	CONDUIT, 2 IN., PUSHED WITH TRACER WIRE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0022) due to user johnsse overridding Payment Estimate Exception 12 on the current Payment Estimate.	140	\$23.00	\$3,220.00
	0680	CONDUIT, 2 IN., PUSHED WITH TRACER WIRE	Other Item Adjustment	Overrun	Entered to hold overrun amount until a change order is approved.			(\$3,220.00)
	0690	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	Material			-84	\$26.00	(\$2,184.00)
	0690	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0040) due to user johnsse overridding Payment Estimate Exception 14 on the current Payment Estimate.	84	\$26.00	\$2,184.00
	0690	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	Other Item Adjustment	Overrun	Entered to hold overrun amount until a change order is approved.			(\$2,184.00)
	0740	POWER SUPPLY ASSEMBLY, TYPE-2 WITH 120V LIGHTING CONTROL CABINET	Material			-1	\$4,650.00	(\$4,650.00)
	0740	POWER SUPPLY ASSEMBLY, TYPE-2 WITH 120V LIGHTING CONTROL CABINET	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0041) due to user johnsse overridding Payment Estimate Exception 22 on the current Payment Estimate.	1	\$4,650.00	\$4,650.00
	0750	PULL BOX, PREFORMED CLASS 3	Material			-2	\$2,130.00	(\$4,260.00)
	0750	PULL BOX, PREFORMED CLASS 3	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0042) due to user johnsse overridding Payment Estimate Exception 24 on the current Payment Estimate.	2	\$2,130.00	\$4,260.00
	0760	PULL BOX, PREFORMED CLASS 3	Material			-1	\$2,130.00	(\$2,130.00)
	0760	PULL BOX, PREFORMED CLASS 3	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0023) due to user johnsse overridding Payment Estimate Exception 25 on the current Payment Estimate.	1	\$2,130.00	\$2,130.00
	0770	BASE, CONCRETE	Material			-2	\$1,620.00	(\$3,240.00)
	0770	BASE, CONCRETE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0043) due to user johnsse overridding Payment Estimate Exception 28 on the current Payment Estimate.	2	\$1,620.00	\$3,240.00
Γotal								(\$37,442.60)

Revision 4/1/2020 Page 7 of 32



					(Contract Project Information	1	
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work	
J4S3294	FAS S302(23)	Signal improvements	Various	VARIOUS	in various locations in	the Kansas City District		
Totals by .	Job Numbe	rs						
J4S3294					This Estimate	Previous	To Date	
		d Item Pay			\$69,151.05	\$455,907.35	\$525,058.40	
	Gross	Item Adjustme		_	(\$37,442.60) (\$12,301.75) (\$49,744.35)			
			Gross It	em Pay	\$31,708.45	\$443,605.60	\$475,314.05	
	Incent	tive			\$0.00	\$0.00	\$0.00	
	Disino	entive			\$0.00	\$0.00	\$0.00	
		lated Damages			\$0.00	\$0.00	\$0.00	
		Contract Adjus			\$0.00	\$0.00	\$0.00	

Revision 4/1/2020 Page 8 of 32



Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4S3294, Item 9017110, Project Item Line Number 0070, Material Set 901711096, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	WORKING WITH MATERIALS AND CONTRACTOR FOR RESOLVE DISCREPANCY.	johnsse	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3294, Item 9020414, Project Item Line Number 0090, Material Set 902041496, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	WORKING WITH MATERIALS AND CONTRACTOR FOR RESOLVE DISCREPANCY.	johnsse	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3294, Item 9020514, Project Item Line Number 0100, Material Set 902051496, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	WORKING WITH MATERIALS AND CONTRACTOR FOR RESOLVE DISCREPANCY.	johnsse	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3294, Item 9020833, Project Item Line Number 0110, Material Set 902083396, Material 1042SM - Sign Material, Acceptance Action Generic 1042SM is insufficient.	WORKING WITH MATERIALS AND CONTRACTOR FOR RESOLVE DISCREPANCY.	johnsse	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3294, Item 9024283, Project Item Line Number 0130, Material Set 902428396, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	WORKING WITH MATERIALS AND CONTRACTOR FOR RESOLVE DISCREPANCY.	johnsse	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3294, Item 9024283, Project Item Line Number 0650, Material Set 902428396, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	WORKING WITH MATERIALS AND CONTRACTOR FOR RESOLVE DISCREPANCY.	johnsse	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3294, Item 9025200, Project Item Line Number 0280, Material Set 902520096, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient.	WORKING WITH MATERIALS AND CONTRACTOR FOR RESOLVE DISCREPANCY.	johnsse	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3294, Item 9025300, Project Item Line Number 0140, Material Set 902530096, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient.	WORKING WITH MATERIALS AND CONTRACTOR FOR RESOLVE DISCREPANCY.	johnsse	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3294, Item 9025300, Project Item Line Number 0670, Material Set 902530096, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient.	WORKING WITH MATERIALS AND CONTRACTOR FOR RESOLVE DISCREPANCY.	johnsse	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3294, Item 9025400, Project Item Line Number 0300, Material Set 902540096, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient.	WORKING WITH MATERIALS AND CONTRACTOR FOR RESOLVE DISCREPANCY.	johnsse	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3294, Item 9027200, Project Item Line Number 0310, Material Set 902720096, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient.	WORKING WITH MATERIALS AND CONTRACTOR FOR RESOLVE DISCREPANCY.	johnsse	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3294, Item 9027200, Project Item Line Number 0680, Material Set 902720096, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient.	WORKING WITH MATERIALS AND CONTRACTOR FOR RESOLVE DISCREPANCY.	johnsse	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3294, Item 9027300, Project Item Line Number 0150, Material Set 902730096, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient.	WORKING WITH MATERIALS AND CONTRACTOR FOR RESOLVE DISCREPANCY.	johnsse	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3294, Item 9027300, Project Item Line Number 0690, Material Set 902730096, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient.	WORKING WITH MATERIALS AND CONTRACTOR FOR RESOLVE DISCREPANCY.	johnsse	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3294, Item 9028208, Project Item Line Number 0160, Material Set 902820896, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	WORKING WITH MATERIALS AND CONTRACTOR FOR RESOLVE DISCREPANCY.	johnsse	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3294, Item 9028302, Project Item Line Number 0080, Material Set 902830296, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	WORKING WITH MATERIALS AND CONTRACTOR FOR RESOLVE DISCREPANCY.	johnsse	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3294, Item 9028308, Project Item Line Number 0170, Material Set 902830896, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	WORKING WITH MATERIALS AND CONTRACTOR FOR RESOLVE DISCREPANCY.	johnsse	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3294, Item 9028310, Project Item Line Number 0180, Material Set 902831096, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	WORKING WITH MATERIALS AND CONTRACTOR FOR RESOLVE DISCREPANCY.	johnsse	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3294, Item 9028311, Project Item Line Number 0190, Material Set 902831196, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	WORKING WITH MATERIALS AND CONTRACTOR FOR RESOLVE DISCREPANCY.	johnsse	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3294, Item 9028510, Project Item Line Number 0200, Material Set 902851096, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	WORKING WITH MATERIALS AND CONTRACTOR FOR RESOLVE DISCREPANCY.	johnsse	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3294, Item 9028621, Project Item Line Number 0210, Material Set 902862196, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	WORKING WITH MATERIALS AND CONTRACTOR FOR RESOLVE DISCREPANCY.	johnsse	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3294, Item 9028621, Project Item Line Number 0740, Material Set 902862196, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	WORKING WITH MATERIALS AND CONTRACTOR FOR RESOLVE DISCREPANCY.	johnsse	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3294, Item 9028812, Project Item Line Number 0220, Material Set 902881296, Material 1062PBPF - Pull Box Preformed Poly Resin Fiber, Acceptance Action Generic 1062PBPF is insufficient.	WORKING WITH MATERIALS AND CONTRACTOR FOR RESOLVE DISCREPANCY.	johnsse	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3294, Item 9028812, Project Item Line Number 0750, Material Set 902881296, Material 1062PBPF - Pull Box Preformed Poly Resin Fiber, Acceptance	WORKING WITH MATERIALS AND CONTRACTOR FOR RESOLVE DISCREPANCY.	johnsse	Overridden

Revision 4/1/2020 Page 9 of 32



Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Action Generic 1062PBPF is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J4S3294, Item 9028812, Project Item Line Number 0760, Material Set 902881296, Material 1062PBPF - Pull Box Preformed Poly Resin Fiber, Acceptance Action Generic 1062PBPF is insufficient.	WORKING WITH MATERIALS AND CONTRACTOR FOR RESOLVE DISCREPANCY.	johnsse	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3294, Item 9029100, Project Item Line Number 0230, Material Set 902910096, Material 1036RSDFPL42M19 - Reinforcing Steel No. 6/M19 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	WORKING WITH MATERIALS AND CONTRACTOR FOR RESOLVE DISCREPANCY.	johnsse	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3294, Item 9029100, Project Item Line Number 0230, Material Set 902910096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	WORKING WITH MATERIALS AND CONTRACTOR FOR RESOLVE DISCREPANCY.	johnsse	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3294, Item 9029100, Project Item Line Number 0770, Material Set 902910096, Material 1036RSDFPL42M19 - Reinforcing Steel No. 6/M19 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	WORKING WITH MATERIALS AND CONTRACTOR FOR RESOLVE DISCREPANCY.	johnsse	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3294, Item 9029100, Project Item Line Number 0770, Material Set 902910096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	WORKING WITH MATERIALS AND CONTRACTOR FOR RESOLVE DISCREPANCY.	johnsse	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3294, Item 9029903, Project Item Line Number 0270, Material Set 902990396, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	WORKING WITH MATERIALS AND CONTRACTOR FOR RESOLVE DISCREPANCY.	johnsse	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3294, Item 9108353, Project Item Line Number 0340, Material Set 910835396, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	WORKING WITH MATERIALS AND CONTRACTOR FOR RESOLVE DISCREPANCY.	johnsse	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3294, Item 9108812, Project Item Line Number 0350, Material Set 910881296, Material 1062PBPF - Pull Box Preformed Poly Resin Fiber, Acceptance Action Generic 1062PBPF is insufficient.	WORKING WITH MATERIALS AND CONTRACTOR FOR RESOLVE DISCREPANCY.	johnsse	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3294, Item 9108816, Project Item Line Number 0360, Material Set 910881696, Material 1062PBPF - Pull Box Preformed Poly Resin Fiber, Acceptance Action Generic 1062PBPF is insufficient.	WORKING WITH MATERIALS AND CONTRACTOR FOR RESOLVE DISCREPANCY.	johnsse	Overridden
Estimate Exception Type: Item Overrun: Contract 200417-C05, Contract Project J4S3294, Project Item Line Number 0130, Contract Line Item Number 0130, Item 9024283, Minor Item.	No Remark was entered by Engineer	johnsse	Overridden
Estimate Exception Type: Item Overrun: Contract 200417-C05, Contract Project J4S3294, Project Item Line Number 0140, Contract Line Item Number 0140, Item 9025300, Minor Item.	No Remark was entered by Engineer	johnsse	Overridden
Estimate Exception Type: Item Overrun: Contract 200417-C05, Contract Project J4S3294, Project Item Line Number 0170, Contract Line Item Number 0170, Item 9028308, Minor Item.	No Remark was entered by Engineer	johnsse	Overridden
Estimate Exception Type: Item Overrun: Contract 200417-C05, Contract Project J4S3294, Project Item Line Number 0180, Contract Line Item Number 0180, Item 9028310, Minor Item.	No Remark was entered by Engineer	johnsse	Overridden
Estimate Exception Type: Item Overrun: Contract 200417-C05, Contract Project J4S3294, Project Item Line Number 0190, Contract Line Item Number 0190, Item 9028311, Minor Item.	No Remark was entered by Engineer	johnsse	Overridden
Estimate Exception Type: Item Overrun: Contract 200417-C05, Contract Project J4S3294, Project Item Line Number 0200, Contract Line Item Number 0200, Item 9028510, Minor Item.	No Remark was entered by Engineer	johnsse	Overridden
Estimate Exception Type: Item Overrun: Contract 200417-C05, Contract Project J4S3294, Project Item Line Number 0220, Contract Line Item Number 0220, Item 9028812, Minor Item.	No Remark was entered by Engineer	johnsse	Overridden
Estimate Exception Type: Item Overrun: Contract 200417-C05, Contract Project J4S3294, Project Item Line Number 0250, Contract Line Item Number 0250, Item 9029902, Minor Item.	WORKING WITH MATERIALS AND CONTRACTOR FOR RESOLVE DISCREPANCY.	johnsse	Overridden
Estimate Exception Type: Item Overrun: Contract 200417-C05, Contract Project J4S3294, Project Item Line Number 0080, Contract Line Item Number 0080, Item 9028302, Minor Item.	No Remark was entered by Engineer	johnsse	Overridden
Estimate Exception Type: Item Overrun: Contract 200417-C05, Contract Project J4S3294, Project Item Line Number 0570, Contract Line Item Number 0570, Item 9109903, Minor Item.	WORKING WITH AND CONTRACTOR FOR RESOLVE DISCREPANCY.	johnsse	Overridden
Estimate Exception Type: Item Overrun: Contract 200417-C05, Contract Project J4S3294, Project Item Line Number 0670, Contract Line Item Number 0670, Item 9025300, Minor Item.	No Remark was entered by Engineer	johnsse	Overridden

Revision 4/1/2020 Page 10 of 32



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repor generated date)
200417-C05	J4S3294	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.00	\$9,635.00	\$0.0
		0001	0020	6169902	MISC.TEMPORARY TRAFFIC CONTROL TYPE 1	1.00	0.00	1.00	EA	1.00	\$105.00	\$105.0
		0001	0030	6169902	MISC.TEMPORARY TRAFFIC CONTROL TYPE 2	23.00	0.00	23.00	EA	25.00	\$430.00	\$10,750.0
		0001	0040	6169902	MISC.TEMPORARY TRAFFIC CONTROL TYPE 3	8.00	0.00	8.00	EA	11.00	\$455.00	\$5,005.0
		0001	0050	6169902	MISC.TEMPORARY TRAFFIC CONTROL TYPE 4	11.00	0.00	11.00	EA	7.00	\$455.00	\$3,185.0
		0001	0060	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.00	\$116,000.00	\$0.0
		0020	0070	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	120.00	0.00	120.00	LF	120.00	\$11.25	\$1,350.0
		0020	0800	9028302	CABLE, 12 AWG 2 CONDUCTOR	650.00	0.00	650.00	LF	724.00	\$3.75	\$2,715.0
		0030	0090	9020414	SIGNAL HEAD, TYPE 4C	6.00	0.00	6.00	EA	6.00	\$1,170.00	\$7,020.0
		0030	0100	9020514	SIGNAL HEAD, TYPE 4B	9.00	0.00	9.00	EA	7.00	\$1,435.00	\$10,045.0
		0030	0110	9020833	SH-FLAT SHEET - SIGNAL SIGN	120.00	0.00	120.00	SQFT	99.00	\$57.00	\$5,643.0
		0030	0120	9020834	SIGNAL SIGN, MOUNTING HARDWARE	16.00	0.00	16.00	EA	12.00	\$170.00	\$2,040.0
		0030	0130	9024283	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	9.00	0.00	9.00	EA	11.00	\$15,240.00	\$167,640.0
		0030	0140	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	619.00	0.00	619.00	LF	705.00	\$38.00	\$26,790.0
		0030	0150	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	15.00	0.00	15.00	LF	15.00	\$88.00	\$1,320.0
		0030	0160	9028208	CABLE, 8 AWG 1 CONDUCTOR, POWER	950.00	0.00	950.00	LF	870.00	\$2.75	\$2,392.5
		0030	0170	9028308	CABLE, 16 AWG 2 CONDUCTOR	490.00	0.00	490.00	LF	575.00	\$3.10	\$1,782.5
		0030	0180	9028310	CABLE, 16 AWG 5 CONDUCTOR	490.00	0.00	490.00	LF	580.00	\$4.25	\$2,465.0
		0030	0190	9028311	CABLE, 16 AWG 7 CONDUCTOR	2,920.00	20.00	2,940.00	LF	3,375.00	\$4.85	\$16,368.
		0030	0200	9028510	CABLE, LOOP DETECTOR, LEAD-IN	1,550.00	0.00	1,550.00	LF	1,885.00	\$4.10	\$7,728
		0030	0210	9028621	POWER SUPPLY ASSEMBLY, TYPE-2 WITH 120V LIGHTING CONTROL CABINET	4.00	0.00	4.00	EA	4.00	\$5,300.00	\$21,200
		0030	0220	9028812	PULL BOX, PREFORMED CLASS 3	4.00	0.00	4.00	EA	6.00	\$2,265.00	\$13,590
		0030	0230	9029100	BASE, CONCRETE	11.60	3.20	14.80	CUYD	10.00	\$1,800.00	\$18,000
		0030	0240	9029902	MISC.CONTROLLER MODOT KC DISTRICT SPECIFIED INTO EXISTING CABINET	1.00	0.00	1.00	EA	1.00	\$3,840.00	\$3,840
		0030	0250	9029902	MISC.LENS REPLACEMENT, ARROWS TO CIRCULAR	2.00	0.00	2.00	EA	4.00	\$270.00	\$1,080
		0030	0260	9029902	MISC.MMU2 MODOT KC DISTRICT SPECIFIED INTO EXISTING CABINET	1.00	0.00	1.00	EA	1.00	\$2,380.00	\$2,380
		0030	0270	9029903	MISC.VIDEO CABLE	778.00	0.00	778.00	LF	778.00	\$6.00	\$4,668
		0050	0280	9025200	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE	2,452.00	117.00	2,569.00	LF	3,015.00	\$10.80	\$32,562
		0050	0290	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	30.00	-30.00	0.00	LF	0.00	\$49.70	\$0.
		0050	0300	9025400	CONDUIT, 4 IN., TRENCH WITH TRACER WIRE	15.00	0.00	15.00	LF	15.00	\$100.00	\$1,500
		0050	0310	9027200	CONDUIT, 2 IN., PUSHED WITH TRACER WIRE	548.00	59.00	607.00	LF	402.00	\$17.25	\$6,934
		0050	0320	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	14.00	-14.00	0.00	LF	0.00	\$120.00	\$0.
		0050	0330	9029902	MISC.CONTROLLER, MODOT KC DISTRICT SPECIFIED	1.00	1.00	2.00	EA	1.00	\$3,840.00	\$3,840
		0050	0340	9108353	FIBER OPTIC CABLE, 12-STRAND, SINGLE MODE	7,190.00	1,010.00	8,200.00	LF	4,577.00	\$3.35	\$15,332
		0050	0350	9108812	PULL BOX, PREFORMED CLASS 3	9.00	0.00	9.00	EA	8.00	\$2,065.00	\$16,520
		0050	0360	9108816	PULL BOX, PREFORMED CLASS 5	6.00	0.00	6.00	EA	3.00	\$1,720.00	\$5,160
		0050	0370	9109901	MISC.FIBER OPTIC TESTING AND DOCUMENTATION	1.00	0.00	1.00	LS	0.00	\$2,450.00	\$0
		0050	0380	9109901	MISC.INSTALLATION OF COMMISSION FURNISHED TELE	1.00	0.00	1.00	LS	0.00	\$10,430.00	\$0
		0050	0390	9109902	COMMUNICATION EQUIPMENT MISC.BASE, CONCRETE FOR CABINET SHIFT	1.00	0.00	1.00	EA	1.00	\$2,390.00	\$2.390
			MISC.CAMERA AND RADIO POLE RISER, 20 FT	23.00	0.00	23.00	EA	22.00	\$2,740.00	\$60,280		
		0050	0410	9109902		4.00	0.00	4.00	EA	3.00	\$4,670.00	\$14,010
		0050	0420	9109902	MISC.CCTV CAMERA ASSEMBLY, TOP MOUNTED TYPE WITH	11.00	0.00	11.00	EA	10.00	\$6,315.00	\$63,150
					CABLE							
		0050	0430	9109902		1.00	0.00	1.00	EA	1.00	\$2,325.00	\$2,325.0
		0050	0440	9109902	MISC.EXTERNAL RIGID CONDUIT ENTRY	2.00	0.00	2.00	EA	2.00	\$1,460.00	\$2,920.

Revision 4/1/2020 Page 11 of 32



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repor generated date)
200417-C05	J4S3294	0050	0450	9109902	MISC.FIBER OPTIC SPLICE ENCLOSURE	11.00	0.00	11.00	EA	1.00	\$615.00	\$615.0
		0050	0460	9109902	MISC.FIBER OPTIC SPLICE, UNDERGROUND	9.00	15.00	24.00	EA	2.00	\$210.00	\$420.0
		0050	0470	9109902	MISC.MEDIA CONVERTER, FURNISH AND INSTALL	14.00	0.00	14.00	EA	0.00	\$340.00	\$0.0
		0050	0480	9109902	MISC.OGL SUBSCRIBER WIRELESS RADIO, WITH CABLE	24.00	0.00	24.00	EA	0.00	\$2,165.00	\$0.0
		0050	0490	9109902	MISC.OGL BASE WIRELESS RADIO, WITH CABLE	12.00	0.00	12.00	EA	0.00	\$4,265.00	\$0.0
		0050	0500	9109902	MISC.OGL POINT TO POINT WIRELESS RADIO, WITH CABLE	2.00	0.00	2.00	EA	0.00	\$10,115.00	\$0.00
		0050	0510	9109902	MISC.OGL SFP MODULE, FURNISH AND INSTALL	1.00	0.00	1.00	EA	0.00	\$282.00	\$0.0
		0050	0520	9109902	MISC.OGL SWITCH, FURNISH AND INSTALL	4.00	0.00	4.00	EA	0.00	\$1,170.00	\$0.0
		0050	0530	9109902	MISC.PRE-TERMINATED FIBER PANEL	8.00	0.00	8.00	EA	5.00	\$530.00	\$2,650.
		0050	0540	9109902	MISC.PULL BOX, INTERCEPT, CLASS 5	1.00	0.00	1.00	EA	0.00	\$590.00	\$0.
		0050	0550	9109902	MISC.PULL BOX, INTERCEPT, STANDARD CONCRETE	3.00	-3.00	0.00	EA	0.00	\$725.00	\$0.0
		0050	0560	9109903	MISC.PRE-TERMINATED FIBER PANEL CABLE	995.00	230.00	1,225.00	LF	0.00	\$4.25	\$0.0
		0050	0570	9109903	MISC.TRACER WIRE NO. 14 FOR EXISTING CONDUIT	3,600.00	96.00	3,696.00	LF	3,696.00	\$1.10	\$4,065.6
		0051	0580	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.00	\$4,930.00	\$0.0
		0051	0590	6169902	MISC.TEMPORARY TRAFFIC CONTROL TYPE 4	1.00	0.00	1.00	EA	2.00	\$785.00	\$1,570.
		0051	0600	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.00	\$8,785.00	\$0.
		0051	0610	9020413	SIGNAL HEAD, TYPE 3C	8.00	0.00	8.00	EA	0.00	\$820.00	\$0.
		0051	0620	9020414	SIGNAL HEAD, TYPE 4C	2.00	0.00	2.00	EA	0.00	\$1,070.00	\$0
		0051	0630	9022708	POST, SIGNAL 8 FT. OR 2.4 M	2.00	0.00	2.00	EA	0.00	\$970.00	\$0
		0051	0640	9023602	SPAN WIRE ASSEMBLY, MESSENGER WITH TETHER	365.00	0.00	365.00	LF	0.00	\$7.40	\$0
		0051	0650	9024283	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	1.00	0.00	1.00	EA	1.00	\$14,580.00	\$14,580
		0051	0660	9025200	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE	105.00	0.00	105.00	LF	0.00	\$23.00	\$0
		0051	0670	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	106.00	0.00	106.00	LF	134.00	\$31.00	\$4,154
		0051	0680	9027200	CONDUIT, 2 IN., PUSHED WITH TRACER WIRE	140.00	0.00	140.00	LF	140.00	\$23.00	\$3,220
		0051	0690	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	84.00	0.00	84.00	LF	84.00	\$26.00	\$2,184
		0051	0700	9028208	CABLE, 8 AWG 1 CONDUCTOR, POWER	100.00	0.00	100.00	LF	0.00	\$4.00	\$0
		0051	0710	9028308	CABLE, 16 AWG 2 CONDUCTOR	540.00	0.00	540.00	LF	0.00	\$1.35	\$0
		0051	0720	9028310	CABLE, 16 AWG 5 CONDUCTOR	550.00	0.00	550.00	LF	0.00	\$1.70	\$0
		0051	0730	9028311	CABLE, 16 AWG 7 CONDUCTOR	1,860.00	0.00	1,860.00	LF	0.00	\$2.00	\$0
		0051	0740	9028621	POWER SUPPLY ASSEMBLY, TYPE-2 WITH 120V LIGHTING	1.00	0.00	1.00	EA	1.00	\$4,650.00	\$4,650
		0051	0750	9028812	CONTROL CABINET PULL BOX, PREFORMED CLASS 3	2.00	1.00	3.00	EA	2.00	\$2,130.00	\$4,260
		0051	0760		PULL BOX, PREFORMED CLASS 3	1.00	0.00	1.00	EA	1.00	\$2,130.00	\$2,130
		0051	0770		BASE, CONCRETE	15.40	0.80	16.20	CUYD	3.00	\$1,620.00	\$4,860
		0051	0780	9029902		2.00	0.00	2.00	EA	0.00	\$1,300.00	\$0
		0051	0790		MISC.POST, STEEL SPAN WIRE - INSTALLATION	4.00	0.00	4.00	EA	4.00	\$1,280.00	\$5,120
		0051	0800	9029902		1.00	0.00	1.00	EA	0.00	\$3,390.00	\$0,120
			0810		MISC.VIDEO CABLE	1,200.00	0.00	1,200.00	LF	0.00	\$2.55	\$0
		0051							LF			
		0051	0820	9108353		40.00	0.00	40.00		0.00	\$26.00	\$0
		0020	5001	9109902		0.00	46.00	46.00	EA	0.00	\$248.18	\$6 143
		0020	5002		CCTV CAMERA ASSEMBLY, INSTALLED	0.00	6.00	6.00	EA	1.00	\$6,143.00	\$6,143
		0051	5003		SH-FLAT SHEET - SIGNAL SIGN	0.00	15.00	15.00	SQFT	0.00	\$57.00	\$0
		0051	5004	9020834		0.00	2.00	2.00	EA	0.00	\$170.00	\$0
		0051	5005		SIGNAL HEAD, TYPE 1S	0.00	2.00	2.00	EA	0.00	\$782.00	\$0
		0050	5006	9028812	PULL BOX, PREFORMED CLASS 3	0.00	2.00	2.00	EA	0.00	\$2,467.00	\$0.
		0020	5007	9109902	MISC.ADDITIONAL 20 FT POLE RISER	0.00	1.00	1.00	EA	0.00	\$3,643.00	\$0

Revision 4/1/2020 Page 12 of 32



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200417-C05	J4S3294	0030	5008	9109902	MISC.TRAFFIC SIGNAL ANCHOR BOLTS 1.75 X 90 -GAV	0.00	4.00	4.00	EA	0.00	\$936.50	\$0.00
		0050	5009	9109901	MISC.ADDITIONAL WIRELESS RADIO	0.00	1.00	1.00	LS	0.00	\$5,460.00	\$0.00
		0050	5010	9109901	MISC.FIBER OPTIC TESTING AND DOCUMENTATION	0.00	1.00	1.00	LS	0.00	\$4,067.00	\$0.00
		0050	5011	9109901	MISC.INSTALLATION OF COMMISSION FURNISHED TELE COMMUNICATION EQUIPMENT	0.00	1.00	1.00	LS	0.00	\$4,172.00	\$0.00
Project J4S3294 - Total Value Posted to Date as of Report Generated Date												\$626,649.30
200417-C05 Overall - Total Value Posted to Date as of Report Generated Date												\$626,649.30

Revision 4/1/2020 Page 13 of 32



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J4S3294

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0020	6169902	MISC. TRAFFIC CONTROL DEVICES	3/24/21	4/2/21	1.00	EA	MO92/KEARNEY MAINTENANCE BUILDING					
0030	6169902	MISC. TRAFFIC CONTROL DEVICES	3/16/21	4/2/21	2.00	EA	MO92/KENTUCKY, MO92/PRAIRIE VIEW RD/RUNNING HORSE					
			3/24/21	4/2/21	1.00	EA	MO D/PRAIRIE VIEW RD					
			3/30/21	4/2/21	1.00	EA	MO D/AMBASSADOR					
			4/1/21	4/2/21	1.00	EA	MO D/I-29 EAST SIDE					
0040	6169902	MISC. TRAFFIC CONTROL DEVICES	3/24/21	4/2/21	1.00	EA	MO92/MO33					
0050	6169902	MISC. TRAFFIC CONTROL DEVICES	3/24/21	4/2/21	1.00	EA	MO D/PRAIRIE VEW RD					
			3/30/21	4/2/21	1.00	EA	MO D/AMBASSADOR					
			4/1/21	4/2/21	1.00	EA	MO D/I-29 EAST SIDE					
0100	9020514	SIGNAL HEAD, TYPE 4B	4/1/21	4/2/21	2.00	EA	MO D/I-29 EAST SIDE					
0110	9020833	SH-FLAT SHEET - SIGNAL SIGN	4/1/21	4/2/21	15.00	SQFT	MO D/I-29 EAST SIDE					
0120	9020834	SIGNAL SIGN, MOUNTING HARDWARE	4/1/21	4/2/21	1.00	EA	MO D/I-29 EAST SIDE					
0130	9024283	CONTROLLER ASSEMBLY HOUSING,	3/24/21	4/2/21	1.00	EA	MO D/PRAIRIE VIEW RD					
			4/1/21	4/2/21	1.00	EA	MO D/I-29 EAST SIDE					
0160	9028208	CABLE, 8 AWG 1 CONDUCTOR, POWER	3/24/21	4/2/21	78.00	LF	MO D/PRAIRIE VIEW RD					
0250	9029902	MISC.	3/24/21	4/2/21	4.00	EA	MO D/PRAIRIE VIEW RD					
0340	9108353	FIBER OPTIC CABLE, 12-STRAND, SINGLE MOD	3/16/21	4/2/21	1,850.00	LF	MO92/RUNNING HORSE TO PRAIRIE VIEW RD.					
			3/17/21	4/2/21	2,727.00	LF	MO D/I-29 PRAIRIE VIEW RD TO AMBASSADOR DR					
0410	9109902	MISC. ITS	3/30/21	4/2/21	1.00	EA	MO D/AMBASSADOR					
0450	9109902	MISC. ITS	3/24/21	4/2/21	1.00	EA	MO92/KEARNEY MAINTENANCE BUILDING					
0460	9109902	MISC. ITS	3/24/21	4/2/21	2.00	EA	MO92/KEARNEY MAINTENANCE BUILDING, MO92/MO33					
0530	9109902	MISC. ITS	3/16/21	4/2/21	2.00	EA	MO92/KENTUCKY, MO92/PRAIRIE VIEW RD/RUNNING HORSE					
			3/18/21	4/2/21	3.00	EA	MO D/PRAIRIE VIEW RD,MO D/I-29, MOD/AMBASSADOR DR.					
0570	9109903	MISC. ITS	3/16/21	4/2/21	1,299.00	LF	MO92/RUNNING HORSE TO PRAIRIE VIEW RD.					
			3/17/21	4/2/21	2,397.00	LF	MO D/I-29 PRAIRE VIEW RD TO AMBASSADOR DR.					
0590	6169902	MISC. TRAFFIC CONTROL DEVICES	3/30/21	4/2/21	1.00	EA	MO 92/PRAIRIE VIEW DR (ALT A)					
0670	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	3/30/21	4/2/21	28.00	LF	MO 92/PRAIRIE VIEW RD (ALT A)					PB17-SIG1

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 4/1/2020 Page 14 of 32



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3294	0030	MISC. TRAFFIC	Overrun	Overrun	7	Apr 19, 2021	SYSTEM	(\$860.00)	
		CONTROL DEVICES		Overrun - T	otal			(\$860.00)	
			Overrun - To	otal				(\$860.00)	
	0030 -	Total						(\$860.00)	
	0040	MISC. TRAFFIC	Overrun	Overrun	7	Apr 19, 2021	SYSTEM	(\$1,365.00)	
		CONTROL DEVICES		Overrun - T	otal			(\$1,365.00)	
		BEVIOLO	Overrun - To					(\$1,365.00)	
	0040 -	· Total						(\$1,365.00)	
	0070	CABLE, 10	Material		4	Mar 3,	SYSTEM	\$1,350.00	This adjustment offsets the original system-generated Material Payment
	0070	AWG 1 CONDUCTOR, POLE &	iviateriai		4	2021	STSTEW	ψ1,550.00	Estimate Item Adjustment (0022) due to user johnsse overridding Payment Estimate Exception 1 on the current Payment Estimate.
		BRACKE			4	Mar 3, 2021	SYSTEM	(\$1,350.00)	
					5	Mar 16, 2021	SYSTEM	\$1,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user johnsse overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	Mar 16, 2021	SYSTEM	(\$1,350.00)	
					6	Apr 2, 2021	SYSTEM	\$1,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user johnsse overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Apr 2, 2021	SYSTEM	(\$1,350.00)	
					7	Apr 19, 2021	SYSTEM	\$1,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user johnsse overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Apr 19, 2021	SYSTEM	(\$1,350.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0070 -	Total						\$0.00	
	0800	CABLE, 12 AWG 2 CONDUCTOR	Material		3	Feb 16, 2021	SYSTEM	\$1,368.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user johnsse overridding Payment Estimate Exception 6 on the current Payment Estimate.
					3	Feb 16, 2021	SYSTEM	(\$1,368.75)	
					4	Mar 3, 2021	SYSTEM	\$2,715.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user johnsse overridding Payment Estimate Exception 12 on the current Payment Estimate.
					4	Mar 3, 2021	SYSTEM	(\$2,715.00)	
					5	Mar 16, 2021	SYSTEM	\$2,715.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user johnsse overridding Payment Estimate Exception 16 on the current Payment Estimate.
					5	Mar 16, 2021	SYSTEM	(\$2,715.00)	
					6	Apr 2, 2021	SYSTEM	\$2,715.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user johnsse overridding Payment Estimate Exception 16 on the current Payment Estimate.
					6	Apr 2, 2021	SYSTEM	(\$2,715.00)	
					7	Apr 19, 2021	SYSTEM	\$2,715.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user johnsse overridding Payment Estimate Exception 16 on the current Payment Estimate.
					7	Apr 19, 2021	SYSTEM	(\$2,715.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Other Item Adjustment	OVRN	4	Mar 3, 2021	karlic1	(\$277.50)	holding overrun amount due to materials exception also on this line.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks					
J4S3294	0800	CABLE, 12 AWG 2	Other Item Adjustment	OVRN - Tota	al			(\$277.50)						
		CONDUCTOR	Other Item	Adjustment -	Total			(\$277.50)						
			Overrun	Overrun	4	Mar 3, 2021	SYSTEM	\$277.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) overridding Payment Estimate Exception 27 on the current Payment Estimate. Material Insufficiency Quantity 724.000; Overrun Quantity Balance 74.00.					
					4	Mar 3, 2021	SYSTEM	(\$277.50)						
					5	Mar 16, 2021	SYSTEM	(\$277.50)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).					
					5	Mar 16, 2021	SYSTEM	\$277.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) overridding Payment Estimate Exception 39 on the current Payment Estimate. Material Insufficiency Quantity 724.000; Overrun Quantity Balance 74.00.					
					6	Apr 2, 2021	SYSTEM	(\$277.50)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).					
					6	Apr 2, 2021	SYSTEM	\$277.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) overridding Payment Estimate Exception 42 on the current Payment Estimate. Material Insufficiency Quantity 724.000; Overrun Quantity Balance 74.00.					
					7	Apr 19, 2021	SYSTEM	(\$277.50)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).					
					7	Apr 19, 2021	SYSTEM	\$277.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) overridding Payment Estimate Exception 44 on the current Payment Estimate. Material Insufficiency Quantity 724.000; Overrun Quantity Balance 74.00.					
				Overrun - T	otal			\$0.00						
			Overrun - To	Overrun - Total					\$0.00					
	0080 -	Total						(\$277.50)						
), TYPE		4	Mar 3, 2021	SYSTEM	\$2,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user johnsse overridding Payment Estimate Exception 2 on the current Payment Estimate.						
					4	Mar 3, 2021	SYSTEM	(\$2,340.00)						
					5	Mar 16, 2021	SYSTEM	\$7,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user johnsse overridding Payment Estimate Exception 2 on the current Payment Estimate.					
					5	Mar 16, 2021	SYSTEM	(\$7,020.00)						
					6	Apr 2, 2021	SYSTEM	\$7,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user johnsse overridding Payment Estimate Exception 2 on the current Payment Estimate.					
					6	Apr 2, 2021	SYSTEM	(\$7,020.00)						
					7	Apr 19, 2021	SYSTEM	\$7,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user johnsse overridding Payment Estimate Exception 2 on the current Payment Estimate.					
					7	Apr 19, 2021	SYSTEM	(\$7,020.00)						
				- Total				\$0.00						
			Material - T	otal				\$0.00						
	0090 -	Total						\$0.00						
	0100	SIGNAL HEAD, TYPE 4B	Material		4	Mar 3, 2021	SYSTEM	\$2,870.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user johnsse overridding Payment Estimate Exception 3 on the current Payment Estimate.					
					4	Mar 3, 2021	SYSTEM	(\$2,870.00)						
					5	Mar 16,	SYSTEM	\$7,175.00	This adjustment offsets the original system-generated Material Payment					
						2021			Estimate Item Adjustment (0018) due to user johnsse overridding Payment Estimate Exception 3 on the current Payment Estimate.					
					5	2021 Mar 16, 2021	SYSTEM	(\$7,175.00)	Estimate Item Adjustment (0018) due to user johnsse overridding Payment Estimate Exception 3 on the current Payment Estimate.					



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks						
J4S3294	0100	SIGNAL HEAD, TYPE	Material			2021			Estimate Item Adjustment (0024) due to user johnsse overridding Payment Estimate Exception 3 on the current Payment Estimate.						
		4B			6	Apr 2, 2021	SYSTEM	(\$10,045.00)							
					7	Apr 19, 2021	SYSTEM	\$10,045.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user johnsse overridding Payment Estimate Exception 3 on the current Payment Estimate.						
					7	Apr 19, 2021	SYSTEM	(\$10,045.00)							
				- Total				\$0.00							
			Material - To	otal				\$0.00							
	0100 -	Total						\$0.00							
	0110	SH-FLAT SHEET - SIGNAL SIGN	Material		4	Mar 3, 2021	SYSTEM	\$1,710.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user johnsse overridding Payment Estimate Exception 4 on the current Payment Estimate.						
					4	Mar 3, 2021	SYSTEM	(\$1,710.00)							
					5	Mar 16, 2021	SYSTEM	\$4,788.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user johnsse overridding Payment Estimate Exception 4 on the current Payment Estimate.						
					5	Mar 16, 2021	SYSTEM	(\$4,788.00)							
					6	Apr 2, 2021	SYSTEM	\$5,643.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user johnsse overridding Payment Estimate Exception 4 on the current Payment Estimate.						
								6	Apr 2, 2021	SYSTEM	(\$5,643.00)				
															7
					7	Apr 19, 2021	SYSTEM	(\$5,643.00)							
				- Total				\$0.00							
			Material - To	otal				\$0.00							
	0110 -	Total						\$0.00							
	0130	CONTROLLER ASSEMBLY HOUSING,	Material		2	Feb 2, 2021	SYSTEM	\$30,480.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user johnsse overridding Payment Estimate Exception 1 on the current Payment Estimate.						
					2	Feb 2, 2021	SYSTEM	(\$30,480.00)							
					3	Feb 16, 2021	SYSTEM	\$30,480.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user johnsse overridding Payment Estimate Exception 1 on the current Payment Estimate.						
					3	Feb 16, 2021	SYSTEM	(\$30,480.00)							
					4	Mar 3, 2021	SYSTEM	\$60,960.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user johnsse overridding Payment Estimate Exception 5 on the current Payment Estimate.						
					4	Mar 3, 2021	SYSTEM	(\$60,960.00)							
							5	Mar 16, 2021	SYSTEM	\$137,160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user johnsse overridding Payment Estimate Exception 5 on the current Payment Estimate.				
					5	Mar 16, 2021	SYSTEM	(\$137,160.00)							
					6	Apr 2, 2021	SYSTEM	\$167,640.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user johnsse overridding Payment Estimate Exception 5 on the current Payment Estimate.						
					6	Apr 2, 2021	SYSTEM	(\$167,640.00)							
					7	Apr 19, 2021	SYSTEM	\$167,640.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user johnsse overridding Payment Estimate Exception 5 on the current Payment Estimate.						



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
J4S3294	0130	CONTROLLER	Material		7	Apr 19, 2021	SYSTEM	(\$167,640.00)			
		HOUSING,		- Total				\$0.00			
			Material - To	otal				\$0.00			
			Other Item Adjustment	OVRN	6	Apr 5, 2021	karlic1	(\$30,480.00)	Entered to hold overrun amount until a change order is approved.		
				OVRN - Tota	al			(\$30,480.00)			
			Other Item	Adjustment -	Total			(\$30,480.00)			
			Overrun	Overrun	6	Apr 2, 2021	SYSTEM	\$15,240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 34 on the current Payment Estimate. Material Insufficiency Quantity 11.000; Overrun Quantity Balance 2.00.		
					6	Apr 2, 2021	SYSTEM	\$15,240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 34 on the current Payment Estimate. Material Insufficiency Quantity 11.000; Overrun Quantity Balance 2.00.		
					6	Apr 2, 2021	SYSTEM	(\$30,480.00)			
					7	Apr 19, 2021	SYSTEM	(\$30,480.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).		
					7	Apr 19, 2021	SYSTEM	\$30,480.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 34 on the current Payment Estimate. Material Insufficiency Quantity 11.000; Overrun Quantity Balance 2.00.		
				Overrun - To	otal			\$0.00			
			Overrun - T	otal				\$0.00			
	0130 -	Total						(\$30,480.00)			
	0140	CONDUIT, 3 IN., TRENCH WITH TRACER	Material		1	Jan 19, 2021	SYSTEM	\$9,044.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user johnsse overridding Payment Estimate Exception 1 on the current Payment Estimate.		
		WIRE			1	Jan 19, 2021	SYSTEM	(\$9,044.00)			
					2	Feb 2, 2021	SYSTEM	\$9,044.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user johnsse overridding Payment Estimate Exception 2 on the current Payment Estimate.		
					2	Feb 2, 2021	SYSTEM	(\$9,044.00)			
							3	Feb 16, 2021	SYSTEM	\$11,324.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user johnsse overridding Payment Estimate Exception 2 on the current Payment Estimate.
					3	Feb 16, 2021	SYSTEM	(\$11,324.00)			
					4	Mar 3, 2021	SYSTEM	\$25,194.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user johnsse overridding Payment Estimate Exception 7 on the current Payment Estimate.		
					4	Mar 3, 2021	SYSTEM	(\$25,194.00)			
					5	Mar 16, 2021	SYSTEM	\$26,790.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user johnsse overridding Payment Estimate Exception 8 on the current Payment Estimate.		
					5	Mar 16, 2021	SYSTEM	(\$26,790.00)			
					6	Apr 2, 2021	SYSTEM	\$26,790.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user johnsse overridding Payment Estimate Exception 8 on the current Payment Estimate.		
					6	Apr 2, 2021	SYSTEM	(\$26,790.00)			
							7	Apr 19, 2021	SYSTEM	\$26,790.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user johnsse overridding Payment Estimate Exception 8 on the current Payment Estimate.
					7	Apr 19, 2021	SYSTEM	(\$26,790.00)			
				- Total				\$0.00			



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks															
J4S3294	0140	CONDUIT, 3	Material - To	otal				\$0.00																
		IN., TRENCH WITH TRACER	Other Item Adjustment	OVRN	4	Mar 3, 2021	johnsse	(\$1,672.00)	holding overrun amount due to materials exception also on this line.															
		WIRE		OVRN - Tota	al			(\$1,672.00)																
			Other Item	Adjustment -	Total			(\$1,672.00)																
			Overrun	Overrun	4	Mar 3, 2021	SYSTEM	\$1,672.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 22 on the current Payment Estimate. Material Insufficiency Quantity 663.000; Overrun Quantity Balance 44.00.															
					4	Mar 3, 2021	SYSTEM	(\$1,672.00)																
					5	Mar 16, 2021	SYSTEM	(\$1,672.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).															
					5	Mar 16, 2021	SYSTEM	\$1,596.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 33 on the current Payment Estimate. Material Insufficiency Quantity 705.000; Overrun Quantity Balance 86.00.															
						5	Mar 16, 2021	SYSTEM	\$1,672.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 33 on the current Payment Estimate. Material Insufficiency Quantity 705.000; Overrun Quantity Balance 86.00.														
					5	Mar 17, 2021	johnsse	(\$1,596.00)	WORKING WITH CONTRACTOR CHANGE ORDER IN PROGRESS.															
								5 Mar 16, 2021 (\$1,596.00)																
								6	Apr 2, 2021	SYSTEM	(\$3,268.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).												
								6	Apr 2, 2021	SYSTEM	\$3,268.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 35 on the current Payment Estimate. Material Insufficiency Quantity 705.000; Overrun Quantity Balance 86.00.												
					7	Apr 19, 2021	SYSTEM	(\$3,268.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).															
					7	Apr 19, 2021	SYSTEM	\$3,268.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 35 on the current Payment Estimate. Material Insufficiency Quantity 705.000; Overrun Quantity Balance 86.00.															
				Overrun - T	otal			(\$1,596.00)																
			Overrun - T	otal				(\$1,596.00)																
	0140 -	Total						(\$3,268.00)																
	0150	CONDUIT, 3 IN., PUSHED WITH TRACER	Material		1	Jan 19, 2021	SYSTEM	\$1,320.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user johnsse overridding Payment Estimate Exception 2 on the current Payment Estimate.															
		WIRE													:	2				1	Jan 19, 2021	SYSTEM	(\$1,320.00)	
																				2	Feb 2, 2021	SYSTEM	\$1,320.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user johnsse overridding Payment Estimate Exception 3 on the current Payment Estimate.
									2								2	Feb 2, 2021	SYSTEM	(\$1,320.00)				
																				3	Feb 16, 2021	SYSTEM	\$1,320.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user johnsse overridding Payment Estimate Exception 5 on the current Payment Estimate.
					3	Feb 16, 2021	SYSTEM	(\$1,320.00)																
						4	Mar 3, 2021	SYSTEM	\$1,320.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user johnsse overridding Payment Estimate Exception 10 on the current Payment Estimate.														
					4	Mar 3, 2021	SYSTEM	(\$1,320.00)																
					5	Mar 16, 2021	SYSTEM	\$1,320.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user johnsse overridding Payment Estimate Exception 13 on the current Payment Estimate.															
					5	Mar 16, 2021	SYSTEM	(\$1,320.00)																



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3294	0150	CONDUIT, 3 IN., PUSHED WITH	Material		6	Apr 2, 2021	SYSTEM	\$1,320.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user johnsse overridding Payment Estimate Exception 13 on the current Payment Estimate.
		TRACER WIRE			6	Apr 2, 2021	SYSTEM	(\$1,320.00)	
					7	Apr 19, 2021	SYSTEM	\$1,320.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user johnsse overridding Payment Estimate Exception 13 on the current Payment Estimate.
					7	Apr 19, 2021	SYSTEM	(\$1,320.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0150 -	Total						\$0.00	
	0160	CABLE, 8 AWG 1 CONDUCTOR, POWER	Material		4	Mar 3, 2021	SYSTEM	\$511.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user johnsse overridding Payment Estimate Exception 11 on the current Payment Estimate.
					4	Mar 3, 2021	SYSTEM	(\$511.50)	
					5	Mar 16, 2021	SYSTEM	\$2,178.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user johnsse overridding Payment Estimate Exception 15 on the current Payment Estimate.
					5	Mar 16, 2021	SYSTEM	(\$2,178.00)	
					6	Apr 2, 2021	SYSTEM	\$2,392.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user johnsse overridding Payment Estimate Exception 15 on the current Payment Estimate.
					6	Apr 2, 2021	SYSTEM	(\$2,392.50)	
					7	Apr 19, 2021	SYSTEM	\$2,392.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user johnsse overridding Payment Estimate Exception 15 on the current Payment Estimate.
					7	Apr 19, 2021	SYSTEM	(\$2,392.50)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0160 -	Total						\$0.00	
	0170	CABLE, 16 AWG 2 CONDUCTOR	Material		3	Feb 16, 2021	SYSTEM	\$899.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user johnsse overridding Payment Estimate Exception 7 on the current Payment Estimate.
					3	Feb 16, 2021	SYSTEM	(\$899.00)	
					4	Mar 3, 2021	SYSTEM	\$1,782.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user johnsse overridding Payment Estimate Exception 13 on the current Payment Estimate.
					4	Mar 3, 2021	SYSTEM	(\$1,782.50)	
					5	Mar 16, 2021	SYSTEM	\$1,782.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user johnsse overridding Payment Estimate Exception 17 on the current Payment Estimate.
					5	Mar 16, 2021	SYSTEM	(\$1,782.50)	
					6	Apr 2, 2021	SYSTEM	\$1,782.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user johnsse overridding Payment Estimate Exception 17 on the current Payment Estimate.
					6	Apr 2, 2021	SYSTEM	(\$1,782.50)	
					7	Apr 19, 2021	SYSTEM	\$1,782.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user johnsse overridding Payment Estimate Exception 17 on the current Payment Estimate.
								(04 700 50)	
					7	Apr 19, 2021	SYSTEM	(\$1,782.50)	
				- Total	7		SYSTEM	\$0.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																							
J4S3294	0170	CABLE, 16 AWG 2	Other Item Adjustment	OVRN	4	Mar 3, 2021	johnsse	(\$263.50)	holding overrun amount due to materials exception also on this line.																							
		CONDUCTOR		OVRN - Tota	al			(\$263.50)																								
			Other Item	Adjustment -	Total			(\$263.50)																								
			Overrun	Overrun	4	Mar 3, 2021	SYSTEM	\$263.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 23 on the current Payment Estimate. Material Insufficiency Quantity 575.000; Overrun Quantity Balance 85.00.																							
					4	Mar 3, 2021	SYSTEM	(\$263.50)																								
					5	Mar 16, 2021	SYSTEM	(\$263.50)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).																							
				5	Mar 16, 2021	SYSTEM	\$263.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 34 on the current Payment Estimate. Material Insufficiency Quantity 575.000; Overrun Quantity Balance 85.00.																								
					6	Apr 2, 2021	SYSTEM	(\$263.50)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).																							
						6	Apr 2, 2021	SYSTEM	\$263.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) overridding Payment Estimate Exception 36 on the current Payment Estimate. Material Insufficiency Quantity 575.000; Overrun Quantity Balance 85.00.																						
							7	Apr 19, 2021	SYSTEM	(\$263.50)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).																					
											7	Apr 19, 2021	SYSTEM	\$263.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 36 on the current Payment Estimate. Material Insufficiency Quantity 575.000; Overrun Quantity Balance 85.00.																	
				Overrun - T	otal			\$0.00																								
			Overrun - T	otal				\$0.00																								
	0170 -	· Total						(\$263.50)																								
	0180	CABLE, 16 AWG 5 CONDUCTOR	AWG 5	Material		3	Feb 16, 2021	SYSTEM	\$1,232.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user johnsse overridding Payment Estimate Exception 8 on the current Payment Estimate.																						
						3	Feb 16, 2021	SYSTEM	(\$1,232.50)																							
					4	Mar 3, 2021	SYSTEM	\$2,465.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user johnsse overridding Payment Estimate Exception 14 on the current Payment Estimate.																							
					4	Mar 3, 2021	SYSTEM	(\$2,465.00)																								
					5	Mar 16, 2021	SYSTEM	\$2,465.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user johnsse overridding Payment Estimate Exception 18 on the current Payment Estimate.																							
																												5	Mar 16,	SYSTEM	(\$2,465.00)	
						2021		(ψ2, του.ου)																								
					6		SYSTEM	\$2,465.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user johnsse overridding Payment Estimate Exception 18 on the current Payment Estimate.																							
						2021 Apr 2,	SYSTEM	, , ,	Estimate Item Adjustment (0009) due to user johnsse overridding Payment																							
					6	2021 Apr 2, 2021 Apr 2,		\$2,465.00	Estimate Item Adjustment (0009) due to user johnsse overridding Payment																							
					6	2021 Apr 2, 2021 Apr 2, 2021 Apr 19,	SYSTEM	\$2,465.00 (\$2,465.00)	Estimate Item Adjustment (0009) due to user johnsse overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user johnsse overridding Payment																							
				- Total	6 6 7	2021 Apr 2, 2021 Apr 2, 2021 Apr 19, 2021 Apr 19,	SYSTEM SYSTEM	\$2,465.00 (\$2,465.00) \$2,465.00	Estimate Item Adjustment (0009) due to user johnsse overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user johnsse overridding Payment																							
			Material - To		6 6 7	2021 Apr 2, 2021 Apr 2, 2021 Apr 19, 2021 Apr 19,	SYSTEM SYSTEM	\$2,465.00 (\$2,465.00) \$2,465.00 (\$2,465.00)	Estimate Item Adjustment (0009) due to user johnsse overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user johnsse overridding Payment																							
			Material - To Other Item Adjustment		6 6 7	2021 Apr 2, 2021 Apr 2, 2021 Apr 19, 2021 Apr 19,	SYSTEM SYSTEM	\$2,465.00 (\$2,465.00) \$2,465.00 (\$2,465.00)	Estimate Item Adjustment (0009) due to user johnsse overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user johnsse overridding Payment																							
			Other Item	otal	6 6 7 7 4	2021 Apr 2, 2021 Apr 2, 2021 Apr 19, 2021 Apr 19, 2021 Mar 3,	SYSTEM SYSTEM SYSTEM	\$2,465.00 (\$2,465.00) \$2,465.00 (\$2,465.00) \$0.00	Estimate Item Adjustment (0009) due to user johnsse overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user johnsse overridding Payment Estimate Exception 18 on the current Payment Estimate.																							
			Other Item Adjustment	otal OVRN	6 6 7 7 7 4 4 al	2021 Apr 2, 2021 Apr 2, 2021 Apr 19, 2021 Apr 19, 2021 Mar 3,	SYSTEM SYSTEM SYSTEM	\$2,465.00 (\$2,465.00) \$2,465.00 (\$2,465.00) \$0.00 (\$382.50)	Estimate Item Adjustment (0009) due to user johnsse overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user johnsse overridding Payment Estimate Exception 18 on the current Payment Estimate.																							



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3294	0180	CABLE, 16 AWG 5 CONDUCTOR	Overrun	Overrun		2021			Estimate Item Adjustment (0005) overridding Payment Estimate Exception 24 on the current Payment Estimate. Material Insufficiency Quantity 580.000; Overrun Quantity Balance 90.00.
					4	Mar 3, 2021	SYSTEM	(\$382.50)	
					5	Mar 16, 2021	SYSTEM	(\$382.50)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					5	Mar 16, 2021	SYSTEM	\$382.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) overridding Payment Estimate Exception 35 on the current Payment Estimate. Material Insufficiency Quantity 580.000; Overrun Quantity Balance 90.00.
					6	Apr 2, 2021	SYSTEM	(\$382.50)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					6	Apr 2, 2021	SYSTEM	\$382.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 37 on the current Payment Estimate. Material Insufficiency Quantity 580.000; Overrun Quantity Balance 90.00.
					7	Apr 19, 2021	SYSTEM	(\$382.50)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					7	Apr 19, 2021	SYSTEM	\$382.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 37 on the current Payment Estimate. Material Insufficiency Quantity 580.000; Overrun Quantity Balance 90.00.
				Overrun - T	otal			\$0.00	
			Overrun - T	otal				\$0.00	
	0180 -	Total						(\$382.50)	
	0190	CABLE, 16 AWG 7 CONDUCTOR	Material		3	Feb 16, 2021	SYSTEM	\$5,262.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user johnsse overridding Payment Estimate Exception 9 on the current Payment Estimate.
					3	Feb 16, 2021	SYSTEM	(\$5,262.25)	
					4	Mar 3, 2021	SYSTEM	\$10,573.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user johnsse overridding Payment Estimate Exception 15 on the current Payment Estimate.
					4	Mar 3, 2021	SYSTEM	(\$10,573.00)	
					5	Mar 16, 2021	SYSTEM	\$16,368.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user johnsse overridding Payment Estimate Exception 19 on the current Payment Estimate.
					5	Mar 16, 2021	SYSTEM	(\$16,368.75)	
					6	Apr 2, 2021	SYSTEM	\$16,368.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user johnsse overridding Payment Estimate Exception 19 on the current Payment Estimate.
					6	Apr 2, 2021	SYSTEM	(\$16,368.75)	
					7	Apr 19, 2021	SYSTEM	\$16,368.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user johnsse overridding Payment Estimate Exception 19 on the current Payment Estimate.
					7	Apr 19, 2021	SYSTEM	(\$16,368.75)	
				- Total				\$0.00	
			Material - To					\$0.00	
			Overrun	Overrun	5	Mar 16, 2021	SYSTEM	\$2,206.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 36 on the current Payment Estimate. Material Insufficiency Quantity 3375.000; Overrun Quantity Balance 455.00.
					5	Mar 17, 2021	johnsse	(\$2,206.75)	WORKING WITH CONTRACTOR CHANGE ORDER IN PROGRESS
					5	Mar 16, 2021	SYSTEM	(\$2,206.75)	
					6	Apr 2, 2021	SYSTEM	(\$2,206.75)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					6	Apr 2, 2021	SYSTEM	\$2,206.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) overridding Payment Estimate Exception 38



D!4	1.5	December	A -1:4	O41	F-4	0	0	A	Demode												
Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks												
J4S3294	0190	CABLE, 16 AWG 7 CONDUCTOR	Overrun	Overrun					on the current Payment Estimate. Material Insufficiency Quantity 3375.000; Overrun Quantity Balance 455.00.												
		CONDUCTOR			7	Apr 19, 2021	SYSTEM	(\$2,109.75)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).												
					7	Apr 19, 2021	SYSTEM	\$2,109.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 38 on the current Payment Estimate. Material Insufficiency Quantity 3375.000; Overrun Quantity Balance 435.00.												
					7	Apr 19, 2021	johnsse	(\$2,109.75)													
					7	Apr 19, 2021	johnsse	\$2,206.75													
				Overrun - T	otal			(\$2,109.75)													
			Overrun - T	otal				(\$2,109.75)													
	0190 -	Total						(\$2,109.75)													
	0200	CABLE, LOOP DETECTOR, LEAD-IN	Material		3	Feb 16, 2021	SYSTEM	\$3,628.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user johnsse overridding Payment Estimate Exception 10 on the current Payment Estimate.												
					3	Feb 16, 2021	SYSTEM	(\$3,628.50)													
					4	Mar 3, 2021	SYSTEM	\$7,728.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user johnsse overridding Payment Estimate Exception 16 on the current Payment Estimate.												
					4	Mar 3, 2021	SYSTEM	(\$7,728.50)													
					5	Mar 16, 2021	SYSTEM	\$7,728.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user johnsse overridding Payment Estimate Exception 20 on the current Payment Estimate.												
												5	Mar 16, 2021	SYSTEM	(\$7,728.50)						
											6	Apr 2, 2021	SYSTEM	\$7,728.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user johnsse overridding Payment Estimate Exception 20 on the current Payment Estimate.						
					6	Apr 2, 2021	SYSTEM	(\$7,728.50)													
					7	Apr 19, 2021	SYSTEM	\$7,728.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user johnsse overridding Payment Estimate Exception 20 on the current Payment Estimate.												
					7	Apr 19, 2021	SYSTEM	(\$7,728.50)													
				- Total				\$0.00													
			Material - To	otal				\$0.00													
			Other Item Adjustment	OVRN	4	Mar 3, 2021	johnsse	(\$1,373.50)	holding overrun amount due to materials exception also on this line.												
				OVRN - Tota	al			(\$1,373.50)													
			Other Item /	Adjustment -	Total			(\$1,373.50)													
			Overrun	Overrun	4	Mar 3, 2021	SYSTEM	\$1,373.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 25 on the current Payment Estimate. Material Insufficiency Quantity 1885.000; Overrun Quantity Balance 335.00.												
					4	Mar 3, 2021	SYSTEM	(\$1,373.50)													
											Ę	5	Ę	!	!		5	Mar 16, 2021	SYSTEM	(\$1,373.50)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					5	Mar 16, 2021	SYSTEM	\$1,373.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) overridding Payment Estimate Exception 37 on the current Payment Estimate. Material Insufficiency Quantity 1885.000; Overrun Quantity Balance 335.00.												
					6	Apr 2, 2021	SYSTEM	(\$1,373.50)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).												
					6	Apr 2, 2021	SYSTEM	\$1,373.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) overridding Payment Estimate Exception 39 on the current Payment Estimate. Material Insufficiency Quantity 1885.000; Overrun Quantity Balance 335.00.												



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks												
J4S3294	0200	CABLE, LOOP DETECTOR,	Overrun	Overrun	7	Apr 19, 2021	SYSTEM	(\$1,373.50)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).												
		LEAD-IN			7	Apr 19, 2021	SYSTEM	\$1,373.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) overridding Payment Estimate Exception 39 on the current Payment Estimate. Material Insufficiency Quantity 1885.000; Overrun Quantity Balance 335.00.												
				Overrun - T	otal			\$0.00													
			Overrun - T	otal				\$0.00													
	0200 -	Total						(\$1,373.50)													
	0210	POWER SUPPLY ASSEMBLY, TYPE-2 WITH	Material		2	Feb 2, 2021	SYSTEM	\$10,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user johnsse overridding Payment Estimate Exception 4 on the current Payment Estimate.												
		120V			2	Feb 2, 2021	SYSTEM	(\$10,600.00)													
						3	Feb 16, 2021	SYSTEM	\$10,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user johnsse overridding Payment Estimate Exception 11 on the current Payment Estimate.											
					3	Feb 16, 2021	SYSTEM	(\$10,600.00)													
					4	Mar 3, 2021	SYSTEM	\$21,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user johnsse overridding Payment Estimate Exception 17 on the current Payment Estimate.												
					4	Mar 3, 2021	SYSTEM	(\$21,200.00)													
					5	Mar 16, 2021	SYSTEM	\$21,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user johnsse overridding Payment Estimate Exception 21 on the current Payment Estimate.												
							5	Mar 16, 2021	SYSTEM	(\$21,200.00)											
					6	Apr 2, 2021	SYSTEM	\$21,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user johnsse overridding Payment Estimate Exception 21 on the current Payment Estimate.												
								6	Apr 2, 2021	SYSTEM	(\$21,200.00)										
					7	Apr 19, 2021	SYSTEM	\$21,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user johnsse overridding Payment Estimate Exception 21 on the current Payment Estimate.												
					7	Apr 19, 2021	SYSTEM	(\$21,200.00)													
				- Total				\$0.00													
			Material - To	otal				\$0.00													
	0210 -	Total						\$0.00													
	0220	PULL BOX, PREFORMED CLASS 3	Material		1	Jan 19, 2021	SYSTEM	\$4,530.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user johnsse overridding Payment Estimate Exception 3 on the current Payment Estimate.												
					1	Jan 19, 2021	SYSTEM	(\$4,530.00)													
					2	Feb 2, 2021	SYSTEM	\$4,530.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user johnsse overridding Payment Estimate Exception 5 on the current Payment Estimate.												
																	2	Feb 2, 2021	SYSTEM	(\$4,530.00)	
					3	Feb 16, 2021	SYSTEM	\$6,795.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user johnsse overridding Payment Estimate Exception 12 on the current Payment Estimate.												
					3	Feb 16, 2021	SYSTEM	(\$6,795.00)													
							4	4	Mar 3, 2021	SYSTEM	\$13,590.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user johnsse overridding Payment Estimate Exception 18 on the current Payment Estimate.									
					4	Mar 3, 2021	SYSTEM	(\$13,590.00)													
					5	Mar 16, 2021	SYSTEM	\$13,590.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user johnsse overridding Payment												



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3294	0220	PULL BOX,	Material						Estimate Exception 23 on the current Payment Estimate.
		PREFORMED CLASS 3			5	Mar 16, 2021	SYSTEM	(\$13,590.00)	
					6	Apr 2, 2021	SYSTEM	\$13,590.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user johnsse overridding Payment Estimate Exception 23 on the current Payment Estimate.
					6	Apr 2, 2021	SYSTEM	(\$13,590.00)	
					7	Apr 19, 2021	SYSTEM	\$13,590.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user johnsse overridding Payment Estimate Exception 23 on the current Payment Estimate.
					7	Apr 19, 2021	SYSTEM	(\$13,590.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Other Item Adjustment	OVRN	4	Mar 3, 2021	johnsse	(\$4,530.00)	holding overrun amount due to materials exception also on this line.
				OVRN - Tota	al			(\$4,530.00)	
			Other Item /	Adjustment -	Total			(\$4,530.00)	
			Overrun	Overrun	4	Mar 3, 2021	SYSTEM	\$4,530.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 26 on the current Payment Estimate. Material Insufficiency Quantity 6.000; Overrun Quantity Balance 2.00.
					4	Mar 3, 2021	SYSTEM	(\$4,530.00)	
					5	Mar 16, 2021	SYSTEM	(\$4,530.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					5	Mar 16, 2021	SYSTEM	\$4,530.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) overridding Payment Estimate Exception 38 on the current Payment Estimate. Material Insufficiency Quantity 6.000; Overrun Quantity Balance 2.00.
					6	Apr 2, 2021	SYSTEM	(\$4,530.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					6	Apr 2, 2021	SYSTEM	\$4,530.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) overridding Payment Estimate Exception 40 on the current Payment Estimate. Material Insufficiency Quantity 6.000; Overrun Quantity Balance 2.00.
					7	Apr 19, 2021	SYSTEM	(\$4,530.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					7	Apr 19, 2021	SYSTEM	\$4,530.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) overridding Payment Estimate Exception 40 on the current Payment Estimate. Material Insufficiency Quantity 6.000; Overrun Quantity Balance 2.00.
				Overrun - T	otal			\$0.00	
			Overrun - T	otal				\$0.00	
	0220 -	Total						(\$4,530.00)	
	0230	BASE, CONCRETE	Material		1	Jan 19, 2021	SYSTEM	\$7,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user johnsse overridding Payment Estimate Exception 4 on the current Payment Estimate.
					1	Jan 19, 2021	SYSTEM	(\$7,200.00)	
					2	Feb 2, 2021	SYSTEM	\$7,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user johnsse overridding Payment Estimate Exception 6 on the current Payment Estimate.
					2	Feb 2, 2021	SYSTEM	(\$7,200.00)	
					3	Feb 16, 2021	SYSTEM	\$7,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user johnsse overridding Payment Estimate Exception 13 on the current Payment Estimate.
					3	Feb 16, 2021	SYSTEM	(\$7,200.00)	
					4	Mar 3, 2021	SYSTEM	\$14,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user johnsse overridding Payment Estimate Exception 19 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3294	0230	BASE, CONCRETE	Material		4	Mar 3, 2021	SYSTEM	(\$14,400.00)	
					5	Mar 16, 2021	SYSTEM	\$18,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user johnsse overridding Payment Estimate Exception 26 on the current Payment Estimate.
					5	Mar 16, 2021	SYSTEM	(\$18,000.00)	
					6	Apr 2, 2021	SYSTEM	\$18,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user johnsse overridding Payment Estimate Exception 26 on the current Payment Estimate.
					6	Apr 2, 2021	SYSTEM	(\$18,000.00)	
					7	Apr 19, 2021	SYSTEM	\$18,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user johnsse overridding Payment Estimate Exception 26 on the current Payment Estimate.
					7	Apr 19, 2021	SYSTEM	(\$18,000.00)	
				- Total				\$0.00	
			Material - To					\$0.00	
	0220	Total	material - It						
		Total						\$0.00	
	0250	MISC.	Other Item Adjustment	OVRN		Apr 5, 2021	karlic1	(\$540.00)	Entered to hold overrun amount until a change order is approved.
				OVRN - Tota	al			(\$540.00)	
			Other Item /	Adjustment -	Total			(\$540.00)	
			Overrun	Overrun	6	Apr 2, 2021	SYSTEM	\$540.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user johnsse overridding Payment Estimate Exception 41 on the current Payment Estimate.
					6	Apr 2, 2021	SYSTEM	(\$540.00)	
					7	Apr 19, 2021	SYSTEM	(\$540.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					7	Apr 19, 2021	johnsse	\$540.00	
				Overrun - T	otal			\$0.00	
			Overrun - T	otal				\$0.00	
	0250	· Total						(\$540.00)	
	0270	MISC.	Material		5	Mar 16, 2021	SYSTEM	\$4,668.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user johnsse overridding Payment Estimate Exception 30 on the current Payment Estimate.
					5	Mar 16, 2021	SYSTEM	(\$4,668.00)	
					6	Apr 2, 2021	SYSTEM	\$4,668.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user johnsse overridding Payment Estimate Exception 30 on the current Payment Estimate.
					6	Apr 2, 2021	SYSTEM	(\$4,668.00)	
					7	Apr 19, 2021	SYSTEM	\$4,668.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user taylot3 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					7	Apr 19, 2021	SYSTEM	(\$4,668.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0270 -	Total						\$0.00	
	0280	CONDUIT, 2 IN., TRENCH WITH	Material		4	Mar 3, 2021	SYSTEM	\$648.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user johnsse overridding Payment Estimate Exception 6 on the current Payment Estimate.
		TRACER WIRE			4	Mar 3, 2021	SYSTEM	(\$648.00)	
					5	Mar 16, 2021	SYSTEM	\$2,775.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user johnsse overridding Payment Estimate Exception 7 on the current Payment Estimate.



March 1	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
TRACKER 6	J4S3294	0280	IN., TRENCH	Material		5		SYSTEM	(\$2,775.60)		
2011 SVSTEM S12,062.00 This adjustment offsets the original system-generated Material Payment Estimate Isen Adjustment (0021) size to user jornses overridding Payment Estimate Isen Adjustment (0022) size to user jornses overridding Payment Estimate Isen Adjustment (0022) size to user jornses overridding Payment Estimate Isen Adjustment (0021) size to user jornses overridding Payment Estimate Isen Adjustment (0021) overridding Payment Isen Adjustment (0021) over Isen Adjustment (0021) over Isen Isen Adjustment Isen Adjustment (0021) over Isen Isen Isen Isen Isen Isen Isen Isen			TRACER			6		SYSTEM	\$2,775.60	Estimate Item Adjustment (0033) due to user johnsse overridding Payment	
2021 February Fe						6		SYSTEM	(\$2,775.60)		
Total Span						7		SYSTEM	\$32,562.00	Estimate Item Adjustment (0022) due to user johnsse overridding Payment	
Material - Total						7		SYSTEM	(\$32,562.00)		
Overrun					- Total				\$0.00		
2021 Settings in the Adjustment (0021) overrinding Payment Estinate Exception 45 on the current Payment Estinate Exception 15 on the current Payment Estinate Estinate Exception 10 on the current Payment Estinate Estinate Exception 10 on the current Payment Estinate Exception 10 on the current Payment Estinate Estinate Estinate Estinate Exception 10 on the current Payment Estinate Estinate Estinate Exception 10 on the current Payment Estinate Estinate Estinate Estinate Exception 10 on the current Payment Estinate Est				Material - To	otal				\$0.00		
2021 Compute				Overrun	Overrun	7		SYSTEM	\$4,816.80	Estimate Item Adjustment (0021) overridding Payment Estimate Exception 45 on the current Payment Estimate. Material Insufficiency Quantity 3015.000;	
Overrun - Total						7		SYSTEM	(\$4,816.80)		
						7		johnsse	(\$4,816.80)		
					Overrun - To	otal			(\$4,816.80)		
				Overrun - T	otal				(\$4,816.80)		
N. TRENCH WITH TRACER 2021 SYSTEM (\$1,500.00)		0280 -	Total						(\$4,816.80)		
Wire		0300	IN., TRENCH WITH TRACER			3		SYSTEM	\$1,500.00	Estimate Item Adjustment (0012) due to user johnsse overridding Payment	
2021 Estimate Item Adjustment (0024) due to user johnsse overridding Payment Estimate Exception 8 on the current Payment Estimate.								3		SYSTEM	(\$1,500.00)
2021						4		SYSTEM	\$1,500.00	Estimate Item Adjustment (0024) due to user johnsse overridding Payment	
2021 SySTEM Estimate Item Adjustment (0029) due to user johnsse overridding Payment Estimate Exception 10 on the current Payment Estimate.						4		SYSTEM	(\$1,500.00)		
2021						5		SYSTEM	\$1,500.00	Estimate Item Adjustment (0029) due to user johnsse overridding Payment	
2021 Estimate Item Adjustment (0034) due to user johnsse overridding Payment Estimate Exception 10 on the current Payment Estimate.						5		SYSTEM	(\$1,500.00)		
2021						6		SYSTEM	\$1,500.00	Estimate Item Adjustment (0034) due to user johnsse overridding Payment	
2021 Estimate Item Adjustment (0037) due to user johnsse overridding Payment Estimate. 7 Apr 19, 2021 \$0.00 - Total \$0.00 0300 - Total \$0.00 0310 CONDUIT, 2 IN., PUSHED WITH TRACER WIRE 4 Mar 3, 2021 4 Mar 3, SYSTEM \$1,035.00 Estimate Item Adjustment (0037) due to user johnsse overridding Payment Estimate. 8 Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate. 8 This adjustment (0013) due to user johnsse overridding Payment Estimate Exception 4 on the current Payment Estimate. 9 This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate. 9 This adjustment offsets the original system-generated Material Payment Estimate Exception 9 on the current Payment Estimate Estimate Item Adjustment (0025) due to user johnsse overridding Payment Estimate Exception 9 on the current Payment Estimate.						6		SYSTEM	(\$1,500.00)		
-Total \$0.00 Material - Total \$0.00						7		SYSTEM	\$1,500.00	Estimate Item Adjustment (0037) due to user johnsse overridding Payment	
Material - Total \$0.00						7		SYSTEM	(\$1,500.00)		
Solution Solution									\$0.00		
O310 CONDUIT, 2 IN., PUSHED WITH TRACER WIRE 3 Feb 16, 2021 4 Mar 3, SYSTEM \$1,035.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate. 4 Mar 3, SYSTEM \$1,035.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user johnsse overridding Payment Estimate Item Adjustment (0025) due to user johnsse overridding Payment Estimate Exception 9 on the current Payment Estimate.				Material - To	otal						
IN., PUSHED WITH TRACER WIRE 3 Feb 16, 2021 4 Mar 3, 2021 5 SYSTEM (\$258.75) 4 Mar 3, 2021 4 Mar 3, SYSTEM \$1,035.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 9 on the current Payment Estimate.		0300 -							\$0.00		
WIRE 3 Feb 16, 2021 (\$258.75) 4 Mar 3, 2021 \$1,035.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user johnsse overridding Payment Estimate Exception 9 on the current Payment Estimate. 4 Mar 3, SYSTEM (\$1,035.00)		0310	IN., PUSHED WITH	Material		3		SYSTEM	\$258.75	Estimate Item Adjustment (0013) due to user johnsse overridding Payment	
Estimate Item Adjustment (0025) due to user johnsse overridding Payment Estimate Exception 9 on the current Payment Estimate. 4 Mar 3, SYSTEM (\$1,035.00)						3		SYSTEM	(\$258.75)		
						4		SYSTEM	\$1,035.00	Estimate Item Adjustment (0025) due to user johnsse overridding Payment	
						4		SYSTEM	(\$1,035.00)		



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
S3294	0310	CONDUIT, 2 IN., PUSHED WITH TRACER	Material		5	Mar 16, 2021	SYSTEM	\$1,035.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user johnsse overridding Payment Estimate Exception 11 on the current Payment Estimate.
		WIRE			5	Mar 16, 2021	SYSTEM	(\$1,035.00)	
					6	Apr 2, 2021	SYSTEM	\$1,035.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user johnsse overridding Payment Estimate Exception 11 on the current Payment Estimate.
					6	Apr 2, 2021	SYSTEM	(\$1,035.00)	
					7	Apr 19, 2021	SYSTEM	\$6,934.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user johnsse overridding Payment Estimate Exception 11 on the current Payment Estimate.
					7	Apr 19, 2021	SYSTEM	(\$6,934.50)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0310 -	Total						\$0.00	
	0340	FIBER OPTIC CABLE, 12- STRAND, SINGLE MOD	Material		6	Apr 2, 2021	SYSTEM	\$15,332.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user johnsse overridding Payment Estimate Exception 31 on the current Payment Estimate.
		SINGLE WOD			6	Apr 2, 2021	SYSTEM	(\$15,332.95)	
					7	Apr 19, 2021	SYSTEM	\$15,332.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user taylot3 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					7	Apr 19, 2021	SYSTEM	(\$15,332.95)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0340 -	Total						\$0.00	
	0350	PULL BOX, PREFORMED CLASS 3	Material		4	Mar 3, 2021	SYSTEM	\$4,130.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user johnsse overridding Payment Estimate Exception 21 on the current Payment Estimate.
					4	Mar 3, 2021	SYSTEM	(\$4,130.00)	
					5	Mar 16, 2021	SYSTEM	\$10,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user johnsse overridding Payment Estimate Exception 31 on the current Payment Estimate.
					5	Mar 16, 2021	SYSTEM	(\$10,325.00)	
					6	Apr 2, 2021	SYSTEM	\$10,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user johnsse overridding Payment Estimate Exception 32 on the current Payment Estimate.
					6	Apr 2, 2021	SYSTEM	(\$10,325.00)	
					7	Apr 19, 2021	SYSTEM	\$16,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user taylot3 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					7	Apr 19, 2021	SYSTEM	(\$16,520.00)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0350 -	Total						\$0.00	
	0360	PULL BOX, PREFORMED CLASS 5	Material		5	Mar 16, 2021	SYSTEM	\$5,160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user johnsse overridding Payment Estimate Exception 32 on the current Payment Estimate.
					5	Mar 16, 2021	SYSTEM	(\$5,160.00)	
					6	Apr 2,	SYSTEM	\$5,160.00	This adjustment offsets the original system-generated Material Payment



Project Line Description Adjustment Type Adjustment Type Adjustment Type Est. Number Date By Amount Remark	em-generated Material Payment user taylot3 overridding Payment yment Estimate.
PREFORMED 2021 7 Apr 19, 2021 SYSTEM \$5,160.00 This adjustment offsets the original system Estimate Item Adjustment (0041) due to Estimate Exception 33 on the current Parameter Total \$0.00 - Total \$0.00 - Total \$0.00 - Total \$0.00	user taylot3 overridding Payment yment Estimate.
7	user taylot3 overridding Payment yment Estimate.
2021	
Material - Total \$0.00 0360 - Total \$0.00	
0360 - Total \$0.00	
0360 - Total \$0.00	
0570 MISC. ITS Other Item Adjustment OVRN 6 Apr 5, karlic1 (\$150.60) Entered to hold overrun amount until a cl	nange order is approved.
7 Apr 20, 2021 \$150.60 Change order has been approved.	
OVRN - Total \$0.00	
Other Item Adjustment - Total \$0.00	
Overrun Overrun 6 Apr 2, 2021 \$105.60 This adjustment offsets the original syste Estimate Item Adjustment (0019) due to Estimate Exception 43 on the current Pa	user johnsse overridding Payment
6 Apr 2, 2021 (\$105.60)	
Overrun - Total \$0.00	
Overrun - Total \$0.00	
0570 - Total \$0.00	
0590 MISC. Overrun 7 Apr 19, SYSTEM (\$785.00) TRAFFIC CONTROL	
DEVICES Overrun - Total (\$785.00)	
Overrun - Total (\$785.00)	
0590 - Total (\$785.00)	
0650 CONTROLLER ASSEMBLY HOUSING, Material 5 Mar 16, 2021 \$14,580.00 This adjustment offsets the original system Estimate Item Adjustment (0033) due to Estimate Exception 6 on the current Pay	user johnsse overridding Payment
5 Mar 16, 2021 (\$14,580.00)	
6 Apr 2, 2021 \$14,580.00 This adjustment offsets the original syste Estimate Item Adjustment (0039) due to Estimate Exception 6 on the current Pay	user johnsse overridding Payment
6 Apr 2, 2021 (\$14,580.00)	
7 Apr 19, SYSTEM \$14,580.00 This adjustment offsets the original syste Estimate Item Adjustment (0042) due to Estimate Exception 6 on the current Pay.	user johnsse overridding Payment
7 Apr 19, SYSTEM (\$14,580.00)	
- Total \$0.00	
Material - Total \$0.00	
0650 - Total \$0.00	
0670 CONDUIT, 3 Material 5 Mar 16, SYSTEM \$3,286.00 This adjustment offsets the original syste Estimate Item Adjustment (0034) due to Estimate Exception 9 on the current Pay	user johnsse overridding Payment
TRACER WIRE 5 Mar 16, SYSTEM (\$3,286.00)	
6 Apr 2, 2021 SYSTEM \$4,154.00 This adjustment offsets the original syste Estimate Item Adjustment (0021) due to Estimate Exception 9 on the current Pay	user johnsse overridding Payment
6 Apr 2, SYSTEM (\$4,154.00)	
7 Apr 19, 2021 \$4,154.00 This adjustment offsets the original syste Estimate Item Adjustment (0024) due to Estimate Exception 9 on the current Pay	user johnsse overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks									
J4S3294	0670	CONDUIT, 3 IN., TRENCH	Material		7	Apr 19, 2021	SYSTEM	(\$4,154.00)										
		WITH TRACER		- Total				\$0.00										
		WIRE	Material - To	otal				\$0.00										
			Other Item Adjustment	OVRN	6	Apr 5, 2021	karlic1	(\$868.00)	Entered to hold overrun amount until a change order is approved.									
				OVRN - Tota	al			(\$868.00)										
			Other Here					· · · · · · · · · · · · · · · · · · ·										
				Adjustment -				(\$868.00)										
			Overrun	Overrun	6	Apr 2, 2021	SYSTEM	\$868.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) overridding Payment Estimate Exception 44 on the current Payment Estimate. Material Insufficiency Quantity 134.000; Overrun Quantity Balance 28.00.									
					6	Apr 2, 2021	SYSTEM	(\$868.00)										
					7	Apr 19, 2021	SYSTEM	(\$868.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).									
					7	Apr 19, 2021	SYSTEM	\$868.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) overridding Payment Estimate Exception 46 on the current Payment Estimate. Material Insufficiency Quantity 134.000; Overrun Quantity Balance 28.00.									
				Overrun - To	otal			\$0.00										
			Overrun - To	otal				\$0.00										
	0670	· Total						(\$868.00)										
	0680		Material	Material	Material	Material		5	Mar 16, 2021	SYSTEM	\$3,220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user johnsse overridding Payment Estimate Exception 12 on the current Payment Estimate.						
												5	Mar 16, 2021	SYSTEM	(\$3,220.00)			
					6	Apr 2, 2021	SYSTEM	\$3,220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user johnsse overridding Payment Estimate Exception 12 on the current Payment Estimate.									
														6	Apr 2, 2021	SYSTEM	(\$3,220.00)	
												7	Apr 19, 2021	SYSTEM	\$3,220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user johnsse overridding Payment Estimate Exception 12 on the current Payment Estimate.		
					7	Apr 19, 2021	SYSTEM	(\$3,220.00)										
				- Total				\$0.00										
			Material - To	otal				\$0.00										
			Other Item Adjustment	OVRN	6	Apr 5, 2021	karlic1	(\$3,220.00)	Entered to hold overrun amount until a change order is approved.									
					7	Apr 20, 2021	warrem1	\$3,220.00	Change order has been approved.									
				OVRN - Tota	al			\$0.00										
			Other Item A	Adjustment -	Total			\$0.00										
	06 <u>80</u> -	· Total						\$0.00										
	0690	CONDUIT, 3 IN., PUSHED WITH	Material		5	Mar 16, 2021	SYSTEM	\$2,184.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user johnsse overridding Payment Estimate Exception 14 on the current Payment Estimate.									
		TRACER WIRE			5	Mar 16, 2021	SYSTEM	(\$2,184.00)										
					6	Apr 2, 2021	SYSTEM	\$2,184.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user johnsse overridding Payment Estimate Exception 14 on the current Payment Estimate.									
					6	Apr 2, 2021	SYSTEM	(\$2,184.00)										
										7	Apr 19, 2021	SYSTEM	\$2,184.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user johnsse overridding Payment Estimate Exception 14 on the current Payment Estimate.				



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3294	0690	CONDUIT, 3	Material	- Total				\$0.00	
		IN., PUSHED WITH	Material - To	otal				\$0.00	
		TRACER WIRE	Other Item Adjustment	OVRN	6	Apr 5, 2021	karlic1	(\$2,184.00)	Entered to hold overrun amount until a change order is approved.
					7	Apr 20, 2021	warrem1	\$2,184.00	Change order has been approved.
				OVRN - Tota	al			\$0.00	
			Other Item /	Adjustment -	Total			\$0.00	
	0690 - Total							\$0.00	
	0740	POWER SUPPLY ASSEMBLY, TYPE-2 WITH 120V	Material		5	Mar 16, 2021	SYSTEM	\$4,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user johnsse overridding Payment Estimate Exception 22 on the current Payment Estimate.
					5	Mar 16, 2021	SYSTEM	(\$4,650.00)	
					6	Apr 2, 2021	SYSTEM	\$4,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user johnsse overridding Payment Estimate Exception 22 on the current Payment Estimate.
					6	Apr 2, 2021	SYSTEM	(\$4,650.00)	
					7	Apr 19, 2021	SYSTEM	\$4,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user johnsse overridding Payment Estimate Exception 22 on the current Payment Estimate.
					7	Apr 19, 2021	SYSTEM	(\$4,650.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0740 -	Total						\$0.00	
	0750	PULL BOX, PREFORMED CLASS 3	Material		5	Mar 16, 2021	SYSTEM	\$4,260.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user johnsse overridding Payment Estimate Exception 24 on the current Payment Estimate.
					5	Mar 16, 2021	SYSTEM	(\$4,260.00)	
					6	Apr 2, 2021	SYSTEM	\$4,260.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user johnsse overridding Payment Estimate Exception 24 on the current Payment Estimate.
					6	Apr 2, 2021	SYSTEM	(\$4,260.00)	
					7	Apr 19, 2021	SYSTEM	\$4,260.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user johnsse overridding Payment Estimate Exception 24 on the current Payment Estimate.
					7	Apr 19, 2021	SYSTEM	(\$4,260.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0750 - Total							\$0.00	
	0760	PULL BOX, PREFORMED CLASS 3	Material		5	Mar 16, 2021	SYSTEM	\$2,130.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user johnsse overridding Payment Estimate Exception 25 on the current Payment Estimate.
					5	Mar 16, 2021	SYSTEM	(\$2,130.00)	
				6	6	Apr 2, 2021	SYSTEM	\$2,130.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user johnsse overridding Payment Estimate Exception 25 on the current Payment Estimate.
					6	Apr 2, 2021	SYSTEM	(\$2,130.00)	
					7	Apr 19, 2021	SYSTEM	\$2,130.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user johnsse overridding Payment Estimate Exception 25 on the current Payment Estimate.
					7	Apr 19, 2021	SYSTEM	(\$2,130.00)	
				- Total				\$0.00	





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3294	0760	PULL BOX, PREFORMED CLASS 3	Material - To	otal				\$0.00	
	0760 -	Total						\$0.00	
	0770	BASE, CONCRETE			5	Mar 16, 2021	SYSTEM	\$3,240.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user johnsse overridding Payment Estimate Exception 28 on the current Payment Estimate.
					5	Mar 16, 2021	SYSTEM	(\$3,240.00)	
					6	Apr 2, 2021	SYSTEM	\$3,240.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user johnsse overridding Payment Estimate Exception 28 on the current Payment Estimate.
					6	Apr 2, 2021	SYSTEM	(\$3,240.00)	
					7	Apr 19, 2021	SYSTEM	\$4,860.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user taylot3 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					7	Apr 19, 2021	SYSTEM	(\$4,860.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0770 -	Total						\$0.00	
J4S3294 - Total								(\$51,919.55)	
Overall - Total								(\$51,919.55)	