

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: June 1, 2021

Progress Estimate Number	Contract ID	200515-C05	Pay Period Start	: May 16, 2021	Original Contract Amount	\$1,995,000.00
15	Prime Contractor	Comanche Construction, Inc.	Pay Period End	June 1, 2021	Net Change Order Amount	\$37,268.25
10					Current Contract Amount	\$2,032,268.25

Approval Date		By User
June 2, 2021	Generated and Approved (and should be considered Draft) at the Project Office Level by	mcclon1
June 4, 2021	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	sandis1
June 4, 2021	Reviewed and Approved at the Central Office Controllers Office Level by	greggd1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
June 30, 2021	June 30, 2022		14.00%

	Contract Informational Dates												
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract										
Acceptance Date													
Awarded Date	June 3, 2020	June 3, 2020											
Letting Date	May 15, 2020	May 15, 2020											
Notice to Proceed Date	July 1, 2020	July 1, 2020											
Open to Traffic Date													
Work Began Date													

Contract Total Pa	y For Estimate No. 15				
		This Estimate	Previous	To Date	
200515-C05					
	Total Posted Items Pay	\$0.00	\$284,449.26	\$284,449.26	
	Gross Item Adjustments	\$0.00	\$0.00	\$0.00	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$119,959.78	\$119,959.78	
			\$404,409.04	\$404,409.04	
Contract Total Pag	yable This Estimate:	\$0.00			

Items Paid This Estimate Period

No Data Available Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

		ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4I3175	5001	REINFORCING STEEL	Material			-681	\$4.71	(\$3,207.51)
	5001	REINFORCING STEEL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user mcclon1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	681	\$4.71	\$3,207.51
Total								\$0.00

Revision 4/1/2020 Page 1 of 7



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Information	on						
Project Number	Federal Proj. Number	Project Description	Route	County		Location of Work							
J4I3175 FAS S302(5) Job Order Contracting for bridge repair Various Area Various locations in the urban Kansas City District													
Totals by .	Job Numb	ers											
J4I3175					This Estimate	Previous	To Date						
	Post	ed Item Pay			\$0.00	\$284,449.26	\$284,449.26						
	Gros	s Item Adjustr	nents		\$0.00	\$0.00	\$0.00						
			Gross	Item Pay	\$0.00	\$284,449.26	\$284,449.26						
	Incer	ntive			\$0.00	\$0.00	\$0.00						
		centive			\$0.00	\$0.00	\$0.00						
		dated Damage	s		\$0.00	\$0.00	\$0.00						
		r Contract Adj			\$0.00	\$119,959.78	\$119,959.78						

Revision 4/1/2020 Page 2 of 7



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4l3175, Item 7061000, Project Item Line Number 5001, Material Set 706100096, Material 1036RSDFPL42M16 - Reinforcing Steel No. 5/M16 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	No Remark was entered by Engineer	mcclon1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3175, Item 7061000, Project Item Line Number 5001, Material Set 706100096, Material 1036RSDFPL42M13 - Reinforcing Steel No. 4/M13 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	No Remark was entered by Engineer	mcclon1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3175, Item 7061000, Project Item Line Number 5001, Material Set 706100096, Material 1036RSDFPL42M19 - Reinforcing Steel No. 6/M19 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	No Remark was entered by Engineer	mcclon1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3175, Item 7061000, Project Item Line Number 5001, Material Set 706100096, Material 1036RSDFPL42M22 - Reinforcing Steel No. 7/M22 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	No Remark was entered by Engineer	mcclon1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3175, Item 7061000, Project Item Line Number 5001, Material Set 706100096, Material 1036RSDFPL42M25 - Reinforcing Steel No. 8/M25 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	No Remark was entered by Engineer	mcclon1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3175, Item 7061000, Project Item Line Number 5001, Material Set 706100096, Material 1036RSDFPL42M29 - Reinforcing Steel No. 9/M29 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	No Remark was entered by Engineer	mcclon1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3175, Item 7061000, Project Item Line Number 5001, Material Set 706100096, Material 1036RSDFPL42M32 - Reinforcing Steel No. 10/M32 Gr 60/M420@, Acceptance Action Generic ReSteelBars is insufficient.	No Remark was entered by Engineer	mcclon1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3175, Item 7061000, Project Item Line Number 5001, Material Set 706100096, Material 1036RSDFPL42M36 - Reinforcing Steel No. 11/M36 Gr 60/M420@, Acceptance Action Generic ReSteelBars is insufficient.	No Remark was entered by Engineer	mcclon1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3175, Item 7061000, Project Item Line Number 5001, Material Set 706100096, Material 1036RSSRPLAB - Plain Spiral Stl Rein for Anchor Bolts @, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	mcclon1	Overridden

Revision 4/1/2020 Page 3 of 7



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200515-C05	J4I3175	0001	0010	6189916	MISC.NIGHTTIME WORK ADJUSTMENT FACTOR	1,125,000.00	0.00	1,125,000.00	DLR	0.00	\$1.25	\$0.00
		0001	0020	6189916	MISC.NORMAL WORK ADJUSTMENT FACTOR	225,000.00	0.00	225,000.00	DLR	173,130.00	\$1.45	\$251,038.50
		0001	0030	6189916	MISC.WEEKEND WORK ADJUSTMENT FACTOR	150,000.00	0.00	150,000.00	DLR	0.00	\$1.75	\$0.00
		0001	5001	7061000	REINFORCING STEEL	0.00	1,500.00	1,500.00	LB	681.00	\$4.71	\$3,207.51
		0001	5002	6079901	MISC. FENCE REPAIR	0.00	1.00	1.00	LS	1.00	\$30,203.25	\$30,203.25
		0001	9000	6189916	MISC.Liquidated Damages	0.00			DLR	0.00	(\$1.00)	\$0.00
		0001	9100	6189916	MISC.Additional Items	0.00			DLR	0.00	\$1.00	\$0.00
		0001	9200	6189902	MISC.High Priority Repair	0.00			EA	0.00	\$2,400.00	\$0.00
	Project .	J4I3175 - To	otal Value	Posted to	Date as of Report Generated Date							\$284,449.26
200515-C05 Ove	200515-C05 Overall - Total Value Posted to Date as of Report Generated Date										\$284,449.26	

Revision 4/1/2020 Page 4 of 7



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 4/1/2020 Page 5 of 7



Line Item Adjustments by Estimate

Contract ID:190621-F01

		Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks						
J4I3175	5001	REINFORCING STEEL	Material		4	Dec 16, 2020	SYSTEM	\$3,207.51	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user mcclon1 overridding Payment Estimate Exception 3 on the current Payment Estimate.						
					4	Dec 16, 2020	SYSTEM	(\$3,207.51)							
						5	Jan 5, 2021	SYSTEM	\$3,207.51	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mcclon1 overridding Payment Estimate Exception 3 on the current Payment Estimate.					
					5	Jan 5, 2021	SYSTEM	(\$3,207.51)							
					6	Jan 20, 2021	SYSTEM	\$3,207.51	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mcclon1 overridding Payment Estimate Exception 2 on the current Payment Estimate.						
					6	Jan 20, 2021	SYSTEM	(\$3,207.51)							
					7	Feb 3, 2021	SYSTEM	\$3,207.51	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user sandis1 overridding Payment Estimate Exception 1 on the current Payment Estimate.						
					7	Feb 3, 2021	SYSTEM	(\$3,207.51)							
					8	Feb 17, 2021	SYSTEM	\$3,207.51	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mcclon1 overridding Payment Estimate Exception 2 on the current Payment Estimate.						
					8	Feb 17, 2021	SYSTEM	(\$3,207.51)							
					9	Mar 2, 2021	SYSTEM	\$3,207.51	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mcclon1 overridding Payment Estimate Exception 2 on the current Payment Estimate.						
						9	Mar 2, 2021	SYSTEM	(\$3,207.51)						
						10	Mar 16, 2021	SYSTEM	\$3,207.51	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mcclon1 overridding Payment Estimate Exception 2 on the current Payment Estimate.					
											10	Mar 16, 2021	SYSTEM	(\$3,207.51)	
						11	Apr 6, 2021	SYSTEM	\$3,207.51	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mcclon1 overridding Payment Estimate Exception 2 on the current Payment Estimate.					
					11	Apr 6, 2021	SYSTEM	(\$3,207.51)							
					12	Apr 16, 2021	SYSTEM	\$3,207.51	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mcclon1 overridding Payment Estimate Exception 2 on the current Payment Estimate.						
					12	Apr 16, 2021	SYSTEM	(\$3,207.51)							
					13	May 4, 2021	SYSTEM	\$3,207.51	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user sandis1 overridding Payment Estimate Exception 1 on the current Payment Estimate.						
					13	May 4, 2021	SYSTEM	(\$3,207.51)							
					14	May 17, 2021	SYSTEM	\$3,207.51	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mcclon1 overridding Payment Estimate Exception 2 on the current Payment Estimate.						
					14	May 17, 2021	SYSTEM	(\$3,207.51)							
					15	Jun 1, 2021	SYSTEM	\$3,207.51	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mcclon1 overridding Payment Estimate Exception 2 on the current Payment Estimate.						
					15	Jun 1, 2021	SYSTEM	(\$3,207.51)							
				- Total				\$0.00							
			Material - To	otal				\$0.00							
	5001 -	· Total						\$0.00							

Jun 4, 2021



Line Item Adjustments by Estimate

Contract ID:190621-F01

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4I3175 - Total									
Overall - Total								\$0.00	