

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: December 16, 2020

Progres 4	s Estimate Number	Contract ID Prime Contractor	200515-C05 Comanche Construc Inc.	Pay Period Start Start Pay Period End	December 15	Original Contract Amou Net Change Order Amount Current Contract Amou	\$7,065.00		
Approval Date							By User		
December 16, 2020			Generated and App	proved (and should be co	nsidered Draft) at th	ne Project Office Level by	sandis1		
December 16, 2020			Reviewed and Approve	d (and should be conside	red Draft) at the Re	esident Engineer Level by	sandis1		
December 17, 2020	Reviewed and Approved at the Central Office Controllers Office Level by								
Original Comp	letion Date	Current	Completion Date	Actual Completion D	ate % o	f Current Contract Amou	nt Complete		
June 30,	0, 2021 June 30, 2022 12.70%								

No Milestones Exist for Contract

Contract Total P	ay For Estimate No. 4			
		This Estimate	Previous	To Date
200515-C05				
	Total Posted Items Pay	\$3,207.51	\$251,038.50	\$254,246.01
	Gross Item Adjustments	\$0.00	\$0.00	\$0.00
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	•		\$251,038.50	\$254,246.01
Contract Total P	avable This Estimate:	\$3,207.51		

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J4I3175	5001	7061000	REINFORCING STEEL	LB	\$4.710	681	\$3,207.51
Project J4I3175 - T	roject J4l3175 - Total						\$3,207.51
Overall - Total							\$3,207.51

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item	Adjust	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4I3175	5001	REINFORCING STEEL	Material			-681	\$4.71	(\$3,207.51)
	5001	REINFORCING STEEL	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0001) due to user mcclon1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	681	\$4.71	\$3,207.51
Total								\$0.00

Revision 4/1/2020 Page 1 of 6



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Information	n					
Project Number	Federal Proj. Number	Project Description	Route	County		Location of Work						
J4I3175	FAS S302(5)	Job Order Contracting for bridge repair	Various	VARIOUS	at various locations in the urban Kansas City District							
Γotals by .	Job Numb	ers										
J4I3175					This Estimate	Previous	To Date					
		ed Item Pay			\$3,207.51	\$251,038.50	\$254,246.01					
	Gros	s Item Adjustr			\$0.00	\$0.00	\$0.00					
			Gross	Item Pay	\$3,207.51	\$251,038.50	\$254,246.01					
	Incer	ntive			\$0.00	\$0.00	\$0.00					
		centive			\$0.00	\$0.00	\$0.00					
	Liqui	dated Damage	es		\$0.00	\$0.00	\$0.00					
	Othe	r Contract Adj	ustments	i	\$0.00	\$0.00	\$0.00					

Revision 4/1/2020 Page 2 of 6



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4l3175, Item 7061000, Project Item Line Number 5001, Material Set 706100096, Material 1036RSDFPL42M16 - Reinforcing Steel No. 5/M16 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	No Remark was entered by Engineer	mcclon1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3175, Item 7061000, Project Item Line Number 5001, Material Set 706100096, Material 1036RSDFPL42M13 - Reinforcing Steel No. 4/M13 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	No Remark was entered by Engineer	mcclon1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3175, Item 7061000, Project Item Line Number 5001, Material Set 706100096, Material 1036RSDFPL42M19 - Reinforcing Steel No. 6/M19 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	No Remark was entered by Engineer	mcclon1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3175, Item 7061000, Project Item Line Number 5001, Material Set 706100096, Material 1036RSDFPL42M22 - Reinforcing Steel No. 7/M22 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	No Remark was entered by Engineer	mcclon1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3175, Item 7061000, Project Item Line Number 5001, Material Set 706100096, Material 1036RSDFPL42M25 - Reinforcing Steel No. 8/M25 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	No Remark was entered by Engineer	mcclon1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3175, Item 7061000, Project Item Line Number 5001, Material Set 706100096, Material 1036RSDFPL42M29 - Reinforcing Steel No. 9/M29 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	No Remark was entered by Engineer	mcclon1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3175, Item 7061000, Project Item Line Number 5001, Material Set 706100096, Material 1036RSDFPL42M32 - Reinforcing Steel No. 10/M32 Gr 60/M420@, Acceptance Action Generic ReSteelBars is insufficient.	No Remark was entered by Engineer	mcclon1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3175, Item 7061000, Project Item Line Number 5001, Material Set 706100096, Material 1036RSDFPL42M36 - Reinforcing Steel No. 11/M36 Gr 60/M420@, Acceptance Action Generic ReSteelBars is insufficient.	No Remark was entered by Engineer	mcclon1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3175, Item 7061000, Project Item Line Number 5001, Material Set 706100096, Material 1036RSSRPLAB - Plain Spiral Stl Rein for Anchor Bolts @, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	mcclon1	Overridden

Revision 4/1/2020 Page 3 of 6



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200515-C05	J4I3175	0001	0010	6189916	MISC.NIGHTTIME WORK ADJUSTMENT FACTOR	1,125,000.00	0.00	1,125,000.00	DLR	0.00	\$1.25	\$0.00
		0001	0020	6189916	MISC.NORMAL WORK ADJUSTMENT FACTOR	225,000.00	0.00	225,000.00	DLR	173,130.00	\$1.45	\$251,038.50
		0001	0030	6189916	MISC.WEEKEND WORK ADJUSTMENT FACTOR	150,000.00	0.00	150,000.00	DLR	0.00	\$1.75	\$0.00
		0001	5001	7061000	REINFORCING STEEL	0.00	1,500.00	1,500.00	LB	681.00	\$4.71	\$3,207.51
		0001	9000	6189916	MISC.Liquidated Damages	0.00			DLR	0.00	(\$1.00)	\$0.00
		0001	9100	6189916	MISC.Additional Items	0.00			DLR	0.00	\$1.00	\$0.00
		0001	9200	6189902	MISC.High Priority Repair	0.00			EA	0.00	\$2,400.00	\$0.00
	Project J4l3175 - Total Value Posted to Date as of Report Generated Date										\$254,246.01	
200515-C05 Ove	200515-C05 Overall - Total Value Posted to Date as of Report Generated Date									\$254,246.01		

Revision 4/1/2020 Page 4 of 6



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

$\underline{\textbf{The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.}$

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
5001	7061000	REINFORCING STEEL	12/15/20	12/16/20	139.00	LB	I-670 ramp toward US 71 NB					This provides payment for WO#2 for the following Fixed Unit Price: Reinforcing Steel 139 LB
				12/16/20	542.00	LB	Holmes Rd Bridge over I-670					This provides payment for WO#3 for the following Fixed Unit Price: Reinforcing Steel 542 LB

The information below this line are details from Line Item agency views. No Agency View Details Exist

Revision 4/1/2020 Page 5 of 6



Missouri Department of Transportation Contractor's Pay Estimate Summary Line Item Adjustments - All Estimates

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
5001	REINFORCING STEEL	Material		4	Dec 16, 2020	SYSTEM	(\$3,207.51)	
				4	Dec 16, 2020	SYSTEM	\$3,207.51	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user mcclon1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
5001 -	5001 - Total						\$0.00	
Overa	Overall - Total						\$0.00	

Revision 4/1/2020 Page 6 of 6