



**Missouri Department of Transportation  
Contractor's Pay Estimate Summary**

Report Generated on June 18, 2022

Pay Estimate Created Date: June 17, 2022

Progress Estimate Number  32	Contract ID	200515-C06	Pay Period Start	June 2, 2022	Original Contract Amount	\$1,664,400.00
	Prime Contractor	Custom Lighting Services, LLC dba Black	Pay Period End	June 15, 2022	Net Change Order Amount	\$60,104.61
					Current Contract Amount	\$1,724,504.61

Approval Date		By User
June 17, 2022	Generated and Approved (and should be considered Draft) at the Project Office Level by	weathc1
June 17, 2022	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	sandis1
June 17, 2022	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

<b>Original Completion Date</b>	<b>Current Completion Date</b>	<b>Actual Completion Date</b>	<b>% of Current Contract Amount Complete</b>
May 31, 2021	May 31, 2022		73.24%

Contract Informational Dates			Milestones
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract
Acceptance Date			
Awarded Date	June 3, 2020	June 3, 2020	
Letting Date	May 15, 2020	May 15, 2020	
Notice to Proceed Date	June 4, 2020	June 4, 2020	
Open to Traffic Date			
Work Began Date	August 17, 2020	August 17, 2020	

Contract Total Pay For Estimate No. 32			
	This Estimate	Previous	To Date
200515-C06			
Total Posted Items Pay	\$60,273.84	\$1,202,710.22	\$1,262,984.06
Gross Item Adjustments	\$0.00	\$0.00	\$0.00
Incentive	\$0.00	\$0.00	\$0.00
Disincentive	\$0.00	\$0.00	\$0.00
Liquidated Damage	\$0.00	\$0.00	\$0.00
Other Contract Adjustments	\$0.00	\$0.00	\$0.00
		\$1,202,710.22	\$1,262,984.06
<b>Contract Total Payable This Estimate:</b>	<b>\$60,273.84</b>		

**Items Paid This Estimate Period**

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J4I3239	0010	9019902	MISC.LABOR/EQUIPMENT FOR TROUBLE SHOOTING/INVESTIGATION/REPAIR WORK ADJUSTMENT FACTOR	EA	\$1.045	39,391	\$41,163.60
	0020	9019902	MISC.MATERIAL FOR REPAIR WORK ADJUSTMENT FACTOR	EA	\$1.750	9,527.28	\$16,672.74
	0030	9019902	MISC.TRAFFIC CONTROL ADJUSTMENT FACTOR	EA	\$3.250	750	\$2,437.50
<b>Project J4I3239 - Total</b>							<b>\$60,273.84</b>
<b>Overall - Total</b>							<b>\$60,273.84</b>

**Contract Adjustments This Estimate**

No Contract Adjustments Exist on Contract

**Line Item Adjustments This Estimate**

No Data Available



**Missouri Department of Transportation  
Contractor's Pay Estimate Summary  
Project Details**

Report Generated on June 18, 2022

Contract Project Information

Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work
J413239		Job Order Contract for lighting repair	Various	VARIOUS	at various locations in the urban Kansas City District

Totals by Job Numbers

Job Number	Totals by Job Numbers			
	This Estimate	Previous	To Date	
J413239	<b>Posted Item Pay</b>	\$60,273.84	\$1,202,710.22	\$1,262,984.06
	<b>Gross Item Adjustments</b>	\$0.00	\$0.00	\$0.00
	<b>Gross Item Pay</b>	<b>\$60,273.84</b>	<b>\$1,202,710.22</b>	<b>\$1,262,984.06</b>
	<b>Incentive</b>	\$0.00	\$0.00	\$0.00
	<b>Disincentive</b>	\$0.00	\$0.00	\$0.00
	<b>Liquidated Damages</b>	\$0.00	\$0.00	\$0.00
	<b>Other Contract Adjustments</b>	\$0.00	\$0.00	\$0.00



**Missouri Department of Transportation  
Contractor's Pay Estimate Summary  
Exceptions**

Report Generated on June 18, 2022

**Exceptions (Discrepancies) This Estimate Period**

No Exceptions Exist on Contract



**Missouri Department of Transportation  
Contractor's Pay Estimate Summary  
Contract Line Items and Total Paid for All Estimates**

Report Generated on June 18, 2022

**Total Paid / All Items / All Estimates (Including this Estimate)**

**Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.**

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200515-C06	J413239	0020	0010	9019902	MISC.LABOR/EQUIPMENT FOR TROUBLE SHOOTING/INVESTIGATION/REPAIR WORK ADJUSTMENT FACTOR	720,000.00	0.00	720,000.00	EA	648,510.25	\$1.04	\$677,693.21
			0020	9019902	MISC.MATERIAL FOR REPAIR WORK ADJUSTMENT FACTOR	432,000.00	0.00	432,000.00	EA	212,959.97	\$1.75	\$372,679.95
			0030	9019902	MISC.TRAFFIC CONTROL ADJUSTMENT FACTOR	48,000.00	0.00	48,000.00	EA	46,925.00	\$3.25	\$152,506.25
			5001	9019901	MISC.MISC. WORK ORDER NUMBER 2987438	0.00	1.00	1.00	LS	1.00	\$686.21	\$686.21
			5002	9019901	MISC.MISC. WORK ORDER NUMBER 2992895	0.00	1.00	1.00	LS	1.00	\$832.54	\$832.54
			5003	9019901	MISC.MISC. WORK ORDER NUMBER 2987439	0.00	1.00	1.00	LS	1.00	\$52.32	\$52.32
			5004	9019901	MISC.MISC. WORK ORDER NUMBER 2992889	0.00	1.00	1.00	LS	1.00	\$1,374.44	\$1,374.44
			5005	9019901	MISC.MISC. WORK ORDER NUMBER 2992988	0.00	1.00	1.00	LS	1.00	\$17.88	\$17.88
			5006	9019901	MISC.MISC. WORK ORDER NUMBER 2993000	0.00	1.00	1.00	LS	1.00	\$190.62	\$190.62
			5007	9019901	MISC.MISC. WORK ORDER NUMBER 3044858	0.00	1.00	1.00	LS	1.00	\$462.00	\$462.00
			5008	9019901	MISC.MISC. WORK ORDER NUMBER 3050651	0.00	1.00	1.00	LS	1.00	\$431.40	\$431.40
			5009	9019901	MISC.MISC. WORK ORDER NUMBER 2992985	0.00	1.00	1.00	LS	1.00	\$1,072.87	\$1,072.87
			5010	9019901	MISC.MISC. WORK ORDER NUMBER 3020566	0.00	1.00	1.00	LS	1.00	\$13.20	\$13.20
			5011	9019901	MISC.MISC. WORK ORDER NUMBER 2993015	0.00	1.00	1.00	LS	1.00	\$1,043.92	\$1,043.92
			5012	9019901	MISC.MISC. WORK ORDER NUMBER 3052659	0.00	1.00	1.00	LS	1.00	\$924.00	\$924.00
			5013	9019901	MISC.MISC. WORK ORDER NUMBER 3107298	0.00	1.00	1.00	LS	1.00	\$1,587.19	\$1,587.19
			5014	9019901	MISC.MISC. WORK ORDER NUMBER 3085642	0.00	1.00	1.00	LS	1.00	\$432.61	\$432.61
			5015	9019901	MISC.MISC. WORK ORDER NUMBER 3107288	0.00	1.00	1.00	LS	1.00	\$260.50	\$260.50
			5016	9019901	MISC.MISC. WORK ORDER NUMBER 3107323	0.00	1.00	1.00	LS	1.00	\$685.66	\$685.66
			5017	9019901	MISC.MISC. WORK ORDER NUMBER 3107326	0.00	1.00	1.00	LS	1.00	\$190.87	\$190.87
			5018	9019901	MISC.MISC. WORK ORDER NUMBER 3130075	0.00	1.00	1.00	LS	1.00	\$462.00	\$462.00
			5019	9019901	MISC.MISC. WORK ORDER NUMBER 3130077	0.00	1.00	1.00	LS	1.00	\$1,064.71	\$1,064.71
			5020	9019901	MISC.MISC. WORK ORDER NUMBER 2993014	0.00	1.00	1.00	LS	1.00	\$303.96	\$303.96
			5021	9019901	MISC.MISC. WORK ORDER NUMBER 2993017	0.00	1.00	1.00	LS	1.00	\$1,336.20	\$1,336.20
			5022	9019901	MISC.MISC. WORK ORDER NUMBER 3050652	0.00	1.00	1.00	LS	1.00	\$3,252.31	\$3,252.31
			5023	9019901	MISC.MISC. WORK ORDER NUMBER 3081298	0.00	1.00	1.00	LS	1.00	\$205.62	\$205.62
			5024	9019901	MISC.MISC. WORK ORDER NUMBER 3085436	0.00	1.00	1.00	LS	1.00	\$442.87	\$442.87
			5025	9019901	MISC.MISC. WORK ORDER NUMBER 3085458	0.00	1.00	1.00	LS	1.00	\$1,406.86	\$1,406.86
			5026	9019901	MISC.MISC. WORK ORDER NUMBER 3107284	0.00	1.00	1.00	LS	1.00	\$900.88	\$900.88
			5027	9019901	MISC.MISC. WORK ORDER NUMBER 3107295	0.00	1.00	1.00	LS	1.00	\$618.00	\$618.00
			5028	9019901	MISC.MISC. WORK ORDER NUMBER 3023831	0.00	1.00	1.00	LS	1.00	\$2,089.56	\$2,089.56
			5029	9019901	MISC.MISC. WORK ORDER NUMBER 3130070	0.00	1.00	1.00	LS	1.00	\$2,523.84	\$2,523.84
			5030	9019901	MISC.MISC. WORK ORDER NUMBER 3135995	0.00	1.00	1.00	LS	1.00	\$730.20	\$730.20
			5031	9019901	MISC.MISC. WORK ORDER NUMBER 3136655	0.00	1.00	1.00	LS	1.00	\$924.00	\$924.00
			5032	9019901	MISC.MISC. WORK ORDER NUMBER 3158107	0.00	1.00	1.00	LS	1.00	\$1,120.75	\$1,120.75
			5033	9019901	MISC.MISC. WORK ORDER NUMBER 3158110	0.00	1.00	1.00	LS	1.00	\$560.38	\$560.38
			5034	9019901	MISC.MISC. WORK ORDER NUMBER 3186561	0.00	1.00	1.00	LS	1.00	\$1,285.02	\$1,285.02
			5035	9019901	MISC.MISC. WORK ORDER NUMBER 3193508	0.00	1.00	1.00	LS	1.00	\$924.00	\$924.00
			5036	9019901	MISC.MISC. WORK ORDER NUMBER 3193513	0.00	1.00	1.00	LS	1.00	\$361.02	\$361.02
			5037	9019901	MISC.MISC. WORK ORDER NUMBER 3158121	0.00	1.00	1.00	LS	1.00	\$1,120.75	\$1,120.75
			5038	9019901	MISC.MISC. WORK ORDER NUMBER 3193505	0.00	1.00	1.00	LS	1.00	\$462.00	\$462.00
5039	9019901	MISC.MISC. WORK ORDER NUMBER 3193506	0.00	1.00	1.00	LS	1.00	\$1,215.84	\$1,215.84			
5040	9019901	MISC.MISC. WORK ORDER NUMBER 3227823	0.00	1.00	1.00	LS	1.00	\$2,508.74	\$2,508.74			
5041	9019901	MISC.MISC. WORK ORDER NUMBER 3252353	0.00	1.00	1.00	LS	1.00	\$143.88	\$143.88			



**Missouri Department of Transportation  
Contractor's Pay Estimate Summary  
Contract Line Items and Total Paid for All Estimates**

Report Generated on June 18, 2022

**Total Paid / All Items / All Estimates (Including this Estimate)**

**Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.**

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200515-C06	J413239	0020	5042	9019901	MISC.MISC. WORK ORDER NUMBER 3252358	0.00	1.00	1.00	LS	1.00	\$379.32	\$379.32
		0020	5043	9019901	MISC.MISC. WORK ORDER NUMBER 3182841	0.00	1.00	1.00	LS	1.00	\$578.88	\$578.88
		0020	5044	9019901	MISC.MISC. WORK ORDER NUMBER 3218501	0.00	1.00	1.00	LS	1.00	\$2,517.60	\$2,517.60
		0020	5045	9019901	MISC.MISC. WORK ORDER NUMBER 3252366	0.00	1.00	1.00	LS	1.00	\$924.00	\$924.00
		0020	5046	9019901	MISC.MISC. WORK ORDER NUMBER 3273946	0.00	1.00	1.00	LS	1.00	\$823.02	\$823.02
		0020	5047	9019901	MISC.MISC. WORK ORDER NUMBER 3273948	0.00	1.00	1.00	LS	1.00	\$924.00	\$924.00
		0020	5048	9019901	MISC.MISC. WORK ORDER NUMBER 3280047	0.00	1.00	1.00	LS	1.00	\$652.94	\$652.94
		0020	5049	9019901	MISC.MISC. WORK ORDER NUMBER 3300194	0.00	1.00	1.00	LS	1.00	\$462.00	\$462.00
		0020	5050	9019901	MISC.MISC. WORK ORDER NUMBER 3300194	0.00	1.00	1.00	LS	1.00	\$924.00	\$924.00
		0020	5051	9019901	MISC.MISC. WORK ORDER NUMBER 3218502	0.00	1.00	1.00	LS	1.00	\$2,590.18	\$2,590.18
		0020	5052	9019901	MISC.MISC. WORK ORDER NUMBER 3307381	0.00	1.00	1.00	LS	1.00	\$1,264.92	\$1,264.92
		0020	5053	9019901	MISC.MISC. WORK ORDER NUMBER 3334227	0.00	1.00	1.00	LS	1.00	\$462.00	\$462.00
		0020	5054	9019901	MISC.MISC. WORK ORDER NUMBER 3357349	0.00	1.00	1.00	LS	1.00	\$462.00	\$462.00
		0020	5055	9019901	MISC.MISC. WORK ORDER NUMBER 3357350	0.00	1.00	1.00	LS	1.00	\$924.00	\$924.00
		0020	5056	9019901	MISC.MISC. WORK ORDER NUMBER 3365085	0.00	1.00	1.00	LS	1.00	\$456.00	\$456.00
		0020	5057	9019901	MISC.MISC. WORK ORDER NUMBER 3273944	0.00	1.00	1.00	LS	1.00	\$474.00	\$474.00
		0020	5058	9019901	MISC.MISC. WORK ORDER NUMBER 3365087	0.00	1.00	1.00	LS	1.00	\$571.68	\$571.68
		0020	5059	9019901	MISC.MISC. WORK ORDER NUMBER 3365092	0.00	1.00	1.00	LS	1.00	\$1,126.32	\$1,126.32
		0020	5060	9019901	MISC.MISC. WORK ORDER NUMBER 3372013	0.00	1.00	1.00	LS	1.00	\$1,452.46	\$1,452.46
		0020	5061	9019901	MISC.MISC. WORK ORDER NUMBER 3372016	0.00	1.00	1.00	LS	1.00	\$750.91	\$750.91
		0020	5062	9019901	MISC.MISC. WORK ORDER NUMBER 3373553	0.00	1.00	1.00	LS	1.00	\$685.66	\$685.66
		0020	5063	9019901	MISC.MISC. WORK ORDER NUMBER 3392019	0.00	1.00	1.00	LS	1.00	\$462.00	\$462.00
		0020	5064	9019901	MISC.MISC. WORK ORDER NUMBER 3402437	0.00	1.00	1.00	LS	1.00	\$462.00	\$462.00
		0020	5065	9019901	MISC.MISC. WORK ORDER NUMBER 3402441	0.00	1.00	1.00	LS	1.00	\$462.00	\$462.00
		0020	5066	9019901	MISC.MISC. WORK ORDER NUMBER 3402443	0.00	1.00	1.00	LS	1.00	\$924.00	\$924.00
		0020	5067	9019901	MISC.MISC. WORK ORDER NUMBER 3402447	0.00	1.00	1.00	LS	1.00	\$462.00	\$462.00
		0020	5068	9019901	MISC.MISC. WORK ORDER NUMBER 3402451	0.00	1.00	1.00	LS	1.00	\$319.10	\$319.10
		0020	5069	9019901	MISC.MISC. WORK ORDER NUMBER 3420396	0.00	1.00	1.00	LS	1.00	\$462.00	\$462.00
		0020	5070	9019901	MISC.MISC. WORK ORDER NUMBER 3428785	0.00	1.00	1.00	LS	1.00	\$462.00	\$462.00
		0020	5071	9019901	MISC.MISC. WORK ORDER NUMBER 3431481	0.00	1.00	1.00	LS	1.00	\$462.00	\$462.00
0020	9000	6189916			MISC.Liquidated Damages	0.00			DLR	0.00	(\$1.00)	\$0.00
0020	9100	6189916			MISC.Additional Items	0.00			DLR	0.00	\$1.00	\$0.00
0020	9200	6189902			MISC.High Priority Repair	0.00			EA	0.00	\$2,400.00	\$0.00
<b>Project J413239 - Total Value Posted to Date as of Report Generated Date</b>											<b>\$1,262,984.02</b>	
<b>200515-C06 Overall - Total Value Posted to Date as of Report Generated Date</b>											<b>\$1,262,984.02</b>	



**Missouri Department of Transportation  
Contractor's Pay Estimate Summary  
Installed Locations of Paid Line Items (This Estimate Only)**

Report Generated on June 18, 2022

**The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.**

Project: J413239

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0010	9019902	MISC. HIGHWAY LIGHTING	6/15/22	6/15/22	450.00	EA	291 Hwy 23rd St. (78 Hwy)					76-1310487, WO3590406
				6/15/22	1,125.00	EA	I-70 Manchester Bridge					76-1310484, WO3566089
				6/15/22	7,317.00	EA	I-70 EB from Admiral					76-1310486, WO3566091
				6/15/22	8,553.00	EA	I-470 & Raytown Road					76-1310482, WO3460380
				6/15/22	8,895.00	EA	I-70 WB from I-435 to Admiral					76-1310485, WO3566090
				6/15/22	13,051.00	EA	I-29 / I-35 Mast Arm					76-1310483, WO3460381
0020	9019902	MISC. HIGHWAY LIGHTING	6/15/22	6/15/22	800.00	EA	I-70 Manchester Bridge					76-1310484, WO3566089
				6/15/22	1,127.28	EA	291 Hwy 23rd St. (78 Hwy)					76-1310487, WO3590406
				6/15/22	3,600.00	EA	I-70 EB from Admiral					76-1310486, WO3566091
				6/15/22	4,000.00	EA	I-70 WB from I-435 to Admiral					76-1310485, WO3566090
0030	9019902	MISC. HIGHWAY LIGHTING	6/15/22	6/15/22	250.00	EA	I-70 EB from Admiral					76-1310486, WO3566091
				6/15/22	250.00	EA	I-70 Manchester Bridge					76-1310484, WO3566089
				6/15/22	250.00	EA	I-70 WB from I-435 to Admiral					76-1310485, WO3566090

**The information below this line are details for Construction Signs (if applicable).**  
No Data Available



## Line Item Adjustments by Estimate

Contract ID:190215-D05

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks					
J413239	5001	MISC. HIGHWAY LIGHTING	Material		29	Apr 15, 2022	SYSTEM	\$686.21	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user weathc1 overriding Payment Estimate Exception 1 on the current Payment Estimate.					
					29	Apr 15, 2022	SYSTEM	(\$686.21)						
					30	May 2, 2022	SYSTEM	\$686.21	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user weathc1 overriding Payment Estimate Exception 1 on the current Payment Estimate.					
					30	May 2, 2022	SYSTEM	(\$686.21)						
					31	Jun 1, 2022	SYSTEM	\$686.21	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user weathc1 overriding Payment Estimate Exception 1 on the current Payment Estimate.					
					31	Jun 1, 2022	SYSTEM	(\$686.21)						
					<b>- Total</b>							<b>\$0.00</b>		
					<b>Material - Total</b>							<b>\$0.00</b>		
					<b>5001 - Total</b>							<b>\$0.00</b>		
						5002	MISC. HIGHWAY LIGHTING	Material		29	Apr 15, 2022	SYSTEM	\$832.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user weathc1 overriding Payment Estimate Exception 2 on the current Payment Estimate.
										29	Apr 15, 2022	SYSTEM	(\$832.54)	
										30	May 2, 2022	SYSTEM	\$832.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user weathc1 overriding Payment Estimate Exception 2 on the current Payment Estimate.
30	May 2, 2022	SYSTEM	(\$832.54)											
31	Jun 1, 2022	SYSTEM	\$832.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user weathc1 overriding Payment Estimate Exception 2 on the current Payment Estimate.										
31	Jun 1, 2022	SYSTEM	(\$832.54)											
<b>- Total</b>										<b>\$0.00</b>				
<b>Material - Total</b>										<b>\$0.00</b>				
<b>5002 - Total</b>										<b>\$0.00</b>				
	5003	MISC. HIGHWAY LIGHTING	Material							29	Apr 15, 2022	SYSTEM	\$52.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weathc1 overriding Payment Estimate Exception 9 on the current Payment Estimate.
										29	Apr 15, 2022	SYSTEM	(\$52.32)	
										30	May 2, 2022	SYSTEM	\$52.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weathc1 overriding Payment Estimate Exception 9 on the current Payment Estimate.
					30	May 2, 2022	SYSTEM	(\$52.32)						
					31	Jun 1, 2022	SYSTEM	\$52.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weathc1 overriding Payment Estimate Exception 9 on the current Payment Estimate.					
					31	Jun 1, 2022	SYSTEM	(\$52.32)						
					<b>- Total</b>							<b>\$0.00</b>		
					<b>Material - Total</b>							<b>\$0.00</b>		
					<b>5003 - Total</b>							<b>\$0.00</b>		
						5004	MISC. HIGHWAY LIGHTING	Material		29	Apr 15, 2022	SYSTEM	\$1,374.44	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user weathc1 overriding Payment Estimate Exception 6 on the current Payment Estimate.
										29	Apr 15, 2022	SYSTEM	(\$1,374.44)	
										30	May 2, 2022	SYSTEM	\$1,374.44	This adjustment offsets the original system-generated Material Payment



## Line Item Adjustments by Estimate

Contract ID:190215-D05

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J413239	5004	MISC. HIGHWAY LIGHTING	Material			2022			Estimate Item Adjustment (0006) due to user weathc1 overriding Payment Estimate Exception 6 on the current Payment Estimate.
					30	May 2, 2022	SYSTEM	(\$1,374.44)	
					31	Jun 1, 2022	SYSTEM	\$1,374.44	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user weathc1 overriding Payment Estimate Exception 6 on the current Payment Estimate.
					31	Jun 1, 2022	SYSTEM	(\$1,374.44)	
					<b>- Total</b>			<b>\$0.00</b>	
					<b>Material - Total</b>			<b>\$0.00</b>	
<b>5004 - Total</b>			<b>\$0.00</b>						
5005	MISC. HIGHWAY LIGHTING	Material		29	Apr 15, 2022	SYSTEM	\$17.88	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user weathc1 overriding Payment Estimate Exception 3 on the current Payment Estimate.	
				29	Apr 15, 2022	SYSTEM	(\$17.88)		
				30	May 2, 2022	SYSTEM	\$17.88	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user weathc1 overriding Payment Estimate Exception 3 on the current Payment Estimate.	
				30	May 2, 2022	SYSTEM	(\$17.88)		
				31	Jun 1, 2022	SYSTEM	\$17.88	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user weathc1 overriding Payment Estimate Exception 3 on the current Payment Estimate.	
				31	Jun 1, 2022	SYSTEM	(\$17.88)		
				<b>- Total</b>			<b>\$0.00</b>		
<b>Material - Total</b>			<b>\$0.00</b>						
<b>5005 - Total</b>			<b>\$0.00</b>						
5006	MISC. HIGHWAY LIGHTING	Material		29	Apr 15, 2022	SYSTEM	\$190.62	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user weathc1 overriding Payment Estimate Exception 10 on the current Payment Estimate.	
				29	Apr 15, 2022	SYSTEM	(\$190.62)		
				30	May 2, 2022	SYSTEM	\$190.62	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user weathc1 overriding Payment Estimate Exception 10 on the current Payment Estimate.	
				30	May 2, 2022	SYSTEM	(\$190.62)		
				31	Jun 1, 2022	SYSTEM	\$190.62	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user weathc1 overriding Payment Estimate Exception 10 on the current Payment Estimate.	
				31	Jun 1, 2022	SYSTEM	(\$190.62)		
				<b>- Total</b>			<b>\$0.00</b>		
<b>Material - Total</b>			<b>\$0.00</b>						
<b>5006 - Total</b>			<b>\$0.00</b>						
5007	MISC. HIGHWAY LIGHTING	Material		29	Apr 15, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user weathc1 overriding Payment Estimate Exception 7 on the current Payment Estimate.	
				29	Apr 15, 2022	SYSTEM	(\$462.00)		
				30	May 2, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user weathc1 overriding Payment Estimate Exception 7 on the current Payment Estimate.	
				30	May 2, 2022	SYSTEM	(\$462.00)		
				31	Jun 1, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user weathc1 overriding Payment	





## Line Item Adjustments by Estimate

Contract ID:190215-D05

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
J413239	5007	MISC. HIGHWAY LIGHTING	Material						Estimate Exception 7 on the current Payment Estimate.		
					31	Jun 1, 2022	SYSTEM	(\$462.00)			
				<b>- Total</b>						\$0.00	
				<b>Material - Total</b>						\$0.00	
				<b>5007 - Total</b>						\$0.00	
J413239	5008	MISC. HIGHWAY LIGHTING	Material		29	Apr 15, 2022	SYSTEM	\$431.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user weathc1 overriding Payment Estimate Exception 4 on the current Payment Estimate.		
					29	Apr 15, 2022	SYSTEM	(\$431.40)			
					30	May 2, 2022	SYSTEM	\$431.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user weathc1 overriding Payment Estimate Exception 4 on the current Payment Estimate.		
					30	May 2, 2022	SYSTEM	(\$431.40)			
					31	Jun 1, 2022	SYSTEM	\$431.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user weathc1 overriding Payment Estimate Exception 4 on the current Payment Estimate.		
					31	Jun 1, 2022	SYSTEM	(\$431.40)			
				<b>- Total</b>						\$0.00	
<b>Material - Total</b>						\$0.00					
<b>5008 - Total</b>						\$0.00					
J413239	5009	MISC. HIGHWAY LIGHTING	Material		29	Apr 15, 2022	SYSTEM	\$1,072.87	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user weathc1 overriding Payment Estimate Exception 8 on the current Payment Estimate.		
					29	Apr 15, 2022	SYSTEM	(\$1,072.87)			
					30	May 2, 2022	SYSTEM	\$1,072.87	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user weathc1 overriding Payment Estimate Exception 8 on the current Payment Estimate.		
					30	May 2, 2022	SYSTEM	(\$1,072.87)			
					31	Jun 1, 2022	SYSTEM	\$1,072.87	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user weathc1 overriding Payment Estimate Exception 8 on the current Payment Estimate.		
					31	Jun 1, 2022	SYSTEM	(\$1,072.87)			
				<b>- Total</b>						\$0.00	
<b>Material - Total</b>						\$0.00					
<b>5009 - Total</b>						\$0.00					
J413239	5010	MISC. HIGHWAY LIGHTING	Material		29	Apr 15, 2022	SYSTEM	\$13.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user weathc1 overriding Payment Estimate Exception 5 on the current Payment Estimate.		
					29	Apr 15, 2022	SYSTEM	(\$13.20)			
					30	May 2, 2022	SYSTEM	\$13.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user weathc1 overriding Payment Estimate Exception 5 on the current Payment Estimate.		
					30	May 2, 2022	SYSTEM	(\$13.20)			
					31	Jun 1, 2022	SYSTEM	\$13.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user weathc1 overriding Payment Estimate Exception 5 on the current Payment Estimate.		
					31	Jun 1, 2022	SYSTEM	(\$13.20)			
				<b>- Total</b>						\$0.00	
<b>Material - Total</b>						\$0.00					



## Line Item Adjustments by Estimate

Jun 18, 2022

Contract ID:190215-D05

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J413239	<b>5010 - Total</b>								<b>\$0.00</b>	
	5011	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$1,043.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user weathc1 overriding Payment Estimate Exception 37 on the current Payment Estimate.	
					28	Apr 1, 2022	SYSTEM	(\$1,043.92)		
	- Total								\$0.00	
	Material - Total								\$0.00	
	<b>5011 - Total</b>								<b>\$0.00</b>	
	5012	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$924.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user weathc1 overriding Payment Estimate Exception 23 on the current Payment Estimate.	
					28	Apr 1, 2022	SYSTEM	(\$924.00)		
	- Total								\$0.00	
	Material - Total								\$0.00	
	<b>5012 - Total</b>								<b>\$0.00</b>	
	5013	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$1,587.19	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user weathc1 overriding Payment Estimate Exception 31 on the current Payment Estimate.	
					28	Apr 1, 2022	SYSTEM	(\$1,587.19)		
	- Total								\$0.00	
	Material - Total								\$0.00	
	<b>5013 - Total</b>								<b>\$0.00</b>	
	5014	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$432.61	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user weathc1 overriding Payment Estimate Exception 38 on the current Payment Estimate.	
					28	Apr 1, 2022	SYSTEM	(\$432.61)		
	- Total								\$0.00	
	Material - Total								\$0.00	
	<b>5014 - Total</b>								<b>\$0.00</b>	
	5015	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$260.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user weathc1 overriding Payment Estimate Exception 7 on the current Payment Estimate.	
					28	Apr 1, 2022	SYSTEM	(\$260.50)		
	- Total								\$0.00	
	Material - Total								\$0.00	
	<b>5015 - Total</b>								<b>\$0.00</b>	
	5016	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$685.66	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user weathc1 overriding Payment Estimate Exception 8 on the current Payment Estimate.	
					28	Apr 1, 2022	SYSTEM	(\$685.66)		
- Total								\$0.00		
Material - Total								\$0.00		
<b>5016 - Total</b>								<b>\$0.00</b>		
5017	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$190.87	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user weathc1 overriding Payment Estimate Exception 39 on the current Payment Estimate.		
				28	Apr 1, 2022	SYSTEM	(\$190.87)			
- Total								\$0.00		
Material - Total								\$0.00		



## Line Item Adjustments by Estimate

Jun 18, 2022

Contract ID:190215-D05

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J413239	<b>5017 - Total</b>								<b>\$0.00</b>	
	5018	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user weathc1 overriding Payment Estimate Exception 13 on the current Payment Estimate.	
					28	Apr 1, 2022	SYSTEM	(\$462.00)		
	- Total								\$0.00	
	Material - Total								\$0.00	
	<b>5018 - Total</b>								<b>\$0.00</b>	
	5019	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$1,064.71	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user weathc1 overriding Payment Estimate Exception 14 on the current Payment Estimate.	
					28	Apr 1, 2022	SYSTEM	(\$1,064.71)		
	- Total								\$0.00	
	Material - Total								\$0.00	
	<b>5019 - Total</b>								<b>\$0.00</b>	
	5020	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$303.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user weathc1 overriding Payment Estimate Exception 40 on the current Payment Estimate.	
					28	Apr 1, 2022	SYSTEM	(\$303.96)		
	- Total								\$0.00	
	Material - Total								\$0.00	
	<b>5020 - Total</b>								<b>\$0.00</b>	
	5021	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$1,336.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user weathc1 overriding Payment Estimate Exception 24 on the current Payment Estimate.	
					28	Apr 1, 2022	SYSTEM	(\$1,336.20)		
	- Total								\$0.00	
	Material - Total								\$0.00	
	<b>5021 - Total</b>								<b>\$0.00</b>	
	5022	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$3,252.31	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user weathc1 overriding Payment Estimate Exception 25 on the current Payment Estimate.	
					28	Apr 1, 2022	SYSTEM	(\$3,252.31)		
	- Total								\$0.00	
	Material - Total								\$0.00	
	<b>5022 - Total</b>								<b>\$0.00</b>	
	5023	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$205.62	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user weathc1 overriding Payment Estimate Exception 15 on the current Payment Estimate.	
					28	Apr 1, 2022	SYSTEM	(\$205.62)		
- Total								\$0.00		
Material - Total								\$0.00		
<b>5023 - Total</b>								<b>\$0.00</b>		
5024	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$442.87	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user weathc1 overriding Payment Estimate Exception 26 on the current Payment Estimate.		
				28	Apr 1, 2022	SYSTEM	(\$442.87)			
- Total								\$0.00		
Material - Total								\$0.00		



## Line Item Adjustments by Estimate

Jun 18, 2022

Contract ID:190215-D05

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J413239	<b>5024 - Total</b>								<b>\$0.00</b>	
	5025	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$1,406.86	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weathc1 overriding Payment Estimate Exception 9 on the current Payment Estimate.	
					28	Apr 1, 2022	SYSTEM	(\$1,406.86)		
	- Total								\$0.00	
	Material - Total								\$0.00	
	<b>5025 - Total</b>								<b>\$0.00</b>	
	5026	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$900.88	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user weathc1 overriding Payment Estimate Exception 27 on the current Payment Estimate.	
					28	Apr 1, 2022	SYSTEM	(\$900.88)		
	- Total								\$0.00	
	Material - Total								\$0.00	
	<b>5026 - Total</b>								<b>\$0.00</b>	
	5027	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$618.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user weathc1 overriding Payment Estimate Exception 32 on the current Payment Estimate.	
					28	Apr 1, 2022	SYSTEM	(\$618.00)		
	- Total								\$0.00	
	Material - Total								\$0.00	
	<b>5027 - Total</b>								<b>\$0.00</b>	
	5028	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$2,089.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user weathc1 overriding Payment Estimate Exception 33 on the current Payment Estimate.	
					28	Apr 1, 2022	SYSTEM	(\$2,089.56)		
	- Total								\$0.00	
	Material - Total								\$0.00	
	<b>5028 - Total</b>								<b>\$0.00</b>	
	5029	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$2,523.84	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user weathc1 overriding Payment Estimate Exception 1 on the current Payment Estimate.	
					28	Apr 1, 2022	SYSTEM	(\$2,523.84)		
	- Total								\$0.00	
Material - Total								\$0.00		
<b>5029 - Total</b>								<b>\$0.00</b>		
5030	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$730.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user weathc1 overriding Payment Estimate Exception 2 on the current Payment Estimate.		
				28	Apr 1, 2022	SYSTEM	(\$730.20)			
- Total								\$0.00		
Material - Total								\$0.00		
<b>5030 - Total</b>								<b>\$0.00</b>		
5031	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$924.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user weathc1 overriding Payment Estimate Exception 16 on the current Payment Estimate.		
				28	Apr 1, 2022	SYSTEM	(\$924.00)			
- Total								\$0.00		
Material - Total								\$0.00		



## Line Item Adjustments by Estimate

Jun 18, 2022

Contract ID:190215-D05

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J413239	<b>5031 - Total</b>								<b>\$0.00</b>	
	5032	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$1,120.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user weathc1 overriding Payment Estimate Exception 3 on the current Payment Estimate.	
					28	Apr 1, 2022	SYSTEM	(\$1,120.75)		
	- Total								\$0.00	
	Material - Total								\$0.00	
	<b>5032 - Total</b>								<b>\$0.00</b>	
	5033	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$560.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user weathc1 overriding Payment Estimate Exception 4 on the current Payment Estimate.	
					28	Apr 1, 2022	SYSTEM	(\$560.38)		
	- Total								\$0.00	
	Material - Total								\$0.00	
	<b>5033 - Total</b>								<b>\$0.00</b>	
	5034	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$1,285.02	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user weathc1 overriding Payment Estimate Exception 5 on the current Payment Estimate.	
					28	Apr 1, 2022	SYSTEM	(\$1,285.02)		
	- Total								\$0.00	
	Material - Total								\$0.00	
	<b>5034 - Total</b>								<b>\$0.00</b>	
	5035	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$924.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user weathc1 overriding Payment Estimate Exception 17 on the current Payment Estimate.	
					28	Apr 1, 2022	SYSTEM	(\$924.00)		
	- Total								\$0.00	
	Material - Total								\$0.00	
	<b>5035 - Total</b>								<b>\$0.00</b>	
	5036	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$361.02	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user weathc1 overriding Payment Estimate Exception 34 on the current Payment Estimate.	
					28	Apr 1, 2022	SYSTEM	(\$361.02)		
	- Total								\$0.00	
	Material - Total								\$0.00	
	<b>5036 - Total</b>								<b>\$0.00</b>	
	5037	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$1,120.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user weathc1 overriding Payment Estimate Exception 35 on the current Payment Estimate.	
					28	Apr 1, 2022	SYSTEM	(\$1,120.75)		
- Total								\$0.00		
Material - Total								\$0.00		
<b>5037 - Total</b>								<b>\$0.00</b>		
5038	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user weathc1 overriding Payment Estimate Exception 18 on the current Payment Estimate.		
				28	Apr 1, 2022	SYSTEM	(\$462.00)			
- Total								\$0.00		
Material - Total								\$0.00		



## Line Item Adjustments by Estimate

Jun 18, 2022

Contract ID:190215-D05

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J413239	<b>5038 - Total</b>								<b>\$0.00</b>	
	5039	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$1,215.84	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user weathc1 overriding Payment Estimate Exception 19 on the current Payment Estimate.	
					28	Apr 1, 2022	SYSTEM	(\$1,215.84)		
	- Total								\$0.00	
	Material - Total								\$0.00	
	<b>5039 - Total</b>								<b>\$0.00</b>	
	5040	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$2,508.74	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user weathc1 overriding Payment Estimate Exception 20 on the current Payment Estimate.	
					28	Apr 1, 2022	SYSTEM	(\$2,508.74)		
	- Total								\$0.00	
	Material - Total								\$0.00	
	<b>5040 - Total</b>								<b>\$0.00</b>	
	5041	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$143.88	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user weathc1 overriding Payment Estimate Exception 28 on the current Payment Estimate.	
					28	Apr 1, 2022	SYSTEM	(\$143.88)		
	- Total								\$0.00	
	Material - Total								\$0.00	
	<b>5041 - Total</b>								<b>\$0.00</b>	
	5042	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$379.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user weathc1 overriding Payment Estimate Exception 36 on the current Payment Estimate.	
					28	Apr 1, 2022	SYSTEM	(\$379.32)		
	- Total								\$0.00	
	Material - Total								\$0.00	
	<b>5042 - Total</b>								<b>\$0.00</b>	
	5043	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$578.88	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user weathc1 overriding Payment Estimate Exception 6 on the current Payment Estimate.	
					28	Apr 1, 2022	SYSTEM	(\$578.88)		
	- Total								\$0.00	
Material - Total								\$0.00		
<b>5043 - Total</b>								<b>\$0.00</b>		
5044	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$2,517.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user weathc1 overriding Payment Estimate Exception 10 on the current Payment Estimate.		
				28	Apr 1, 2022	SYSTEM	(\$2,517.60)			
- Total								\$0.00		
Material - Total								\$0.00		
<b>5044 - Total</b>								<b>\$0.00</b>		
5045	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$924.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user weathc1 overriding Payment Estimate Exception 11 on the current Payment Estimate.		
				28	Apr 1, 2022	SYSTEM	(\$924.00)			
- Total								\$0.00		
Material - Total								\$0.00		



## Line Item Adjustments by Estimate

Jun 18, 2022

Contract ID:190215-D05

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J413239	<b>5045 - Total</b>								<b>\$0.00</b>	
	5046	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$823.02	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user weathc1 overriding Payment Estimate Exception 29 on the current Payment Estimate.	
					28	Apr 1, 2022	SYSTEM	(\$823.02)		
	<b>- Total</b>								<b>\$0.00</b>	
	<b>Material - Total</b>								<b>\$0.00</b>	
	<b>5046 - Total</b>								<b>\$0.00</b>	
	5047	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$924.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user weathc1 overriding Payment Estimate Exception 12 on the current Payment Estimate.	
					28	Apr 1, 2022	SYSTEM	(\$924.00)		
	<b>- Total</b>								<b>\$0.00</b>	
	<b>Material - Total</b>								<b>\$0.00</b>	
	<b>5047 - Total</b>								<b>\$0.00</b>	
	5048	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$652.94	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user weathc1 overriding Payment Estimate Exception 30 on the current Payment Estimate.	
					28	Apr 1, 2022	SYSTEM	(\$652.94)		
	<b>- Total</b>								<b>\$0.00</b>	
	<b>Material - Total</b>								<b>\$0.00</b>	
	<b>5048 - Total</b>								<b>\$0.00</b>	
	5049	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user weathc1 overriding Payment Estimate Exception 21 on the current Payment Estimate.	
					28	Apr 1, 2022	SYSTEM	(\$462.00)		
	<b>- Total</b>								<b>\$0.00</b>	
	<b>Material - Total</b>								<b>\$0.00</b>	
	<b>5049 - Total</b>								<b>\$0.00</b>	
	5050	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$924.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user weathc1 overriding Payment Estimate Exception 22 on the current Payment Estimate.	
					28	Apr 1, 2022	SYSTEM	(\$924.00)		
	<b>- Total</b>								<b>\$0.00</b>	
	<b>Material - Total</b>								<b>\$0.00</b>	
	<b>5050 - Total</b>								<b>\$0.00</b>	
	5051	MISC. HIGHWAY LIGHTING	Material		29	Apr 15, 2022	SYSTEM	\$2,590.18	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user weathc1 overriding Payment Estimate Exception 18 on the current Payment Estimate.	
					29	Apr 15, 2022	SYSTEM	(\$2,590.18)		
30					May 2, 2022	SYSTEM	\$2,590.18	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user weathc1 overriding Payment Estimate Exception 18 on the current Payment Estimate.		
30					May 2, 2022	SYSTEM	(\$2,590.18)			
31					Jun 1, 2022	SYSTEM	\$2,590.18	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user weathc1 overriding Payment Estimate Exception 18 on the current Payment Estimate.		
31					Jun 1, 2022	SYSTEM	(\$2,590.18)			
<b>- Total</b>								<b>\$0.00</b>		



## Line Item Adjustments by Estimate

Jun 18, 2022

Contract ID:190215-D05

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J413239	5051	MISC. HIGHWAY LIGHTING	Material - Total						\$0.00	
	5051 - Total								\$0.00	
	5052	MISC. HIGHWAY LIGHTING	Material		29	Apr 15, 2022	SYSTEM	\$1,264.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user weathc1 overriding Payment Estimate Exception 23 on the current Payment Estimate.	
					29	Apr 15, 2022	SYSTEM	(\$1,264.92)		
					30	May 2, 2022	SYSTEM	\$1,264.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user weathc1 overriding Payment Estimate Exception 23 on the current Payment Estimate.	
					30	May 2, 2022	SYSTEM	(\$1,264.92)		
					31	Jun 1, 2022	SYSTEM	\$1,264.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user weathc1 overriding Payment Estimate Exception 23 on the current Payment Estimate.	
					31	Jun 1, 2022	SYSTEM	(\$1,264.92)		
					- Total					
	Material - Total								\$0.00	
	5052 - Total								\$0.00	
	5053	MISC. HIGHWAY LIGHTING	Material		29	Apr 15, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user weathc1 overriding Payment Estimate Exception 11 on the current Payment Estimate.	
					29	Apr 15, 2022	SYSTEM	(\$462.00)		
					30	May 2, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user weathc1 overriding Payment Estimate Exception 11 on the current Payment Estimate.	
					30	May 2, 2022	SYSTEM	(\$462.00)		
					31	Jun 1, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user weathc1 overriding Payment Estimate Exception 11 on the current Payment Estimate.	
					31	Jun 1, 2022	SYSTEM	(\$462.00)		
					- Total					
	Material - Total								\$0.00	
	5053 - Total								\$0.00	
	5054	MISC. HIGHWAY LIGHTING	Material		29	Apr 15, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user weathc1 overriding Payment Estimate Exception 19 on the current Payment Estimate.	
					29	Apr 15, 2022	SYSTEM	(\$462.00)		
					30	May 2, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user weathc1 overriding Payment Estimate Exception 19 on the current Payment Estimate.	
					30	May 2, 2022	SYSTEM	(\$462.00)		
					31	Jun 1, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user weathc1 overriding Payment Estimate Exception 19 on the current Payment Estimate.	
					31	Jun 1, 2022	SYSTEM	(\$462.00)		
- Total						\$0.00				
Material - Total								\$0.00		
5054 - Total								\$0.00		
5055	MISC. HIGHWAY	Material		29	Apr 15, 2022	SYSTEM	\$924.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user weathc1 overriding Payment		





## Line Item Adjustments by Estimate

Jun 18, 2022

Contract ID:190215-D05

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks					
J413239	5055	LIGHTING	Material						Estimate Exception 31 on the current Payment Estimate.					
					29	Apr 15, 2022	SYSTEM	(\$924.00)						
					30	May 2, 2022	SYSTEM	\$924.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user weathc1 overriding Payment Estimate Exception 31 on the current Payment Estimate.					
					30	May 2, 2022	SYSTEM	(\$924.00)						
					31	Jun 1, 2022	SYSTEM	\$924.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user weathc1 overriding Payment Estimate Exception 31 on the current Payment Estimate.					
					31	Jun 1, 2022	SYSTEM	(\$924.00)						
					<b>- Total</b>								<b>\$0.00</b>	
					<b>Material - Total</b>								<b>\$0.00</b>	
					<b>5055 - Total</b>								<b>\$0.00</b>	
					5056	MISC. HIGHWAY LIGHTING	Material		29	Apr 15, 2022	SYSTEM	\$456.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user weathc1 overriding Payment Estimate Exception 24 on the current Payment Estimate.	
29	Apr 15, 2022	SYSTEM	(\$456.00)											
30	May 2, 2022	SYSTEM	\$456.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user weathc1 overriding Payment Estimate Exception 24 on the current Payment Estimate.										
30	May 2, 2022	SYSTEM	(\$456.00)											
31	Jun 1, 2022	SYSTEM	\$456.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user weathc1 overriding Payment Estimate Exception 24 on the current Payment Estimate.										
31	Jun 1, 2022	SYSTEM	(\$456.00)											
<b>- Total</b>									<b>\$0.00</b>					
<b>Material - Total</b>								<b>\$0.00</b>						
<b>5056 - Total</b>								<b>\$0.00</b>						
5057	MISC. HIGHWAY LIGHTING	Material		29	Apr 15, 2022	SYSTEM	\$474.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user weathc1 overriding Payment Estimate Exception 20 on the current Payment Estimate.						
				29	Apr 15, 2022	SYSTEM	(\$474.00)							
				30	May 2, 2022	SYSTEM	\$474.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user weathc1 overriding Payment Estimate Exception 20 on the current Payment Estimate.						
				30	May 2, 2022	SYSTEM	(\$474.00)							
				31	Jun 1, 2022	SYSTEM	\$474.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user weathc1 overriding Payment Estimate Exception 20 on the current Payment Estimate.						
				31	Jun 1, 2022	SYSTEM	(\$474.00)							
<b>- Total</b>								<b>\$0.00</b>						
<b>Material - Total</b>								<b>\$0.00</b>						
<b>5057 - Total</b>								<b>\$0.00</b>						
5058	MISC. HIGHWAY LIGHTING	Material		29	Apr 15, 2022	SYSTEM	\$571.68	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user weathc1 overriding Payment Estimate Exception 25 on the current Payment Estimate.						
				29	Apr 15, 2022	SYSTEM	(\$571.68)							
				30	May 2, 2022	SYSTEM	\$571.68	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user weathc1 overriding Payment Estimate Exception 25 on the current Payment Estimate.						



## Line Item Adjustments by Estimate

Contract ID:190215-D05

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J413239	5058	MISC. HIGHWAY LIGHTING	Material		30	May 2, 2022	SYSTEM	(\$571.68)	
					31	Jun 1, 2022	SYSTEM	\$571.68	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user weathc1 overriding Payment Estimate Exception 25 on the current Payment Estimate.
					31	Jun 1, 2022	SYSTEM	(\$571.68)	
					<b>- Total</b>			<b>\$0.00</b>	
					<b>Material - Total</b>			<b>\$0.00</b>	
					<b>5058 - Total</b>			<b>\$0.00</b>	
J413239	5059	MISC. HIGHWAY LIGHTING	Material		29	Apr 15, 2022	SYSTEM	\$1,126.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user weathc1 overriding Payment Estimate Exception 12 on the current Payment Estimate.
					29	Apr 15, 2022	SYSTEM	(\$1,126.32)	
					30	May 2, 2022	SYSTEM	\$1,126.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user weathc1 overriding Payment Estimate Exception 12 on the current Payment Estimate.
					30	May 2, 2022	SYSTEM	(\$1,126.32)	
					31	Jun 1, 2022	SYSTEM	\$1,126.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user weathc1 overriding Payment Estimate Exception 12 on the current Payment Estimate.
					31	Jun 1, 2022	SYSTEM	(\$1,126.32)	
					<b>- Total</b>			<b>\$0.00</b>	
<b>Material - Total</b>			<b>\$0.00</b>						
<b>5059 - Total</b>			<b>\$0.00</b>						
J413239	5060	MISC. HIGHWAY LIGHTING	Material		29	Apr 15, 2022	SYSTEM	\$1,452.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user weathc1 overriding Payment Estimate Exception 26 on the current Payment Estimate.
					29	Apr 15, 2022	SYSTEM	(\$1,452.46)	
					30	May 2, 2022	SYSTEM	\$1,452.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user weathc1 overriding Payment Estimate Exception 26 on the current Payment Estimate.
					30	May 2, 2022	SYSTEM	(\$1,452.46)	
					31	Jun 1, 2022	SYSTEM	\$1,452.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user weathc1 overriding Payment Estimate Exception 26 on the current Payment Estimate.
					31	Jun 1, 2022	SYSTEM	(\$1,452.46)	
					<b>- Total</b>			<b>\$0.00</b>	
<b>Material - Total</b>			<b>\$0.00</b>						
<b>5060 - Total</b>			<b>\$0.00</b>						
J413239	5061	MISC. HIGHWAY LIGHTING	Material		29	Apr 15, 2022	SYSTEM	\$750.91	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user weathc1 overriding Payment Estimate Exception 13 on the current Payment Estimate.
					29	Apr 15, 2022	SYSTEM	(\$750.91)	
					30	May 2, 2022	SYSTEM	\$750.91	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user weathc1 overriding Payment Estimate Exception 13 on the current Payment Estimate.
					30	May 2, 2022	SYSTEM	(\$750.91)	
					31	Jun 1, 2022	SYSTEM	\$750.91	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user weathc1 overriding Payment Estimate Exception 13 on the current Payment Estimate.
					31	Jun 1, 2022	SYSTEM	(\$750.91)	



## Line Item Adjustments by Estimate

Jun 18, 2022

Contract ID:190215-D05

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
J413239	5061	MISC. HIGHWAY LIGHTING	Material			2022						
				<b>- Total</b>							<b>\$0.00</b>	
				<b>Material - Total</b>							<b>\$0.00</b>	
	<b>5061 - Total</b>								<b>\$0.00</b>			
	5062	MISC. HIGHWAY LIGHTING	Material		29	Apr 15, 2022	SYSTEM	\$685.66	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user weathc1 overriding Payment Estimate Exception 14 on the current Payment Estimate.			
					29	Apr 15, 2022	SYSTEM	(\$685.66)				
					30	May 2, 2022	SYSTEM	\$685.66	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user weathc1 overriding Payment Estimate Exception 14 on the current Payment Estimate.			
					30	May 2, 2022	SYSTEM	(\$685.66)				
					31	Jun 1, 2022	SYSTEM	\$685.66	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user weathc1 overriding Payment Estimate Exception 14 on the current Payment Estimate.			
					31	Jun 1, 2022	SYSTEM	(\$685.66)				
				<b>- Total</b>							<b>\$0.00</b>	
	<b>Material - Total</b>							<b>\$0.00</b>				
	<b>5062 - Total</b>								<b>\$0.00</b>			
	5063	MISC. HIGHWAY LIGHTING	Material		29	Apr 15, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user weathc1 overriding Payment Estimate Exception 21 on the current Payment Estimate.			
					29	Apr 15, 2022	SYSTEM	(\$462.00)				
					30	May 2, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user weathc1 overriding Payment Estimate Exception 21 on the current Payment Estimate.			
					30	May 2, 2022	SYSTEM	(\$462.00)				
					31	Jun 1, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user weathc1 overriding Payment Estimate Exception 21 on the current Payment Estimate.			
					31	Jun 1, 2022	SYSTEM	(\$462.00)				
				<b>- Total</b>							<b>\$0.00</b>	
<b>Material - Total</b>							<b>\$0.00</b>					
<b>5063 - Total</b>								<b>\$0.00</b>				
5064	MISC. HIGHWAY LIGHTING	Material		29	Apr 15, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user weathc1 overriding Payment Estimate Exception 15 on the current Payment Estimate.				
				29	Apr 15, 2022	SYSTEM	(\$462.00)					
				30	May 2, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user weathc1 overriding Payment Estimate Exception 15 on the current Payment Estimate.				
				30	May 2, 2022	SYSTEM	(\$462.00)					
				31	Jun 1, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user weathc1 overriding Payment Estimate Exception 15 on the current Payment Estimate.				
				31	Jun 1, 2022	SYSTEM	(\$462.00)					
			<b>- Total</b>							<b>\$0.00</b>		
<b>Material - Total</b>							<b>\$0.00</b>					
<b>5064 - Total</b>								<b>\$0.00</b>				



## Line Item Adjustments by Estimate

Jun 18, 2022

Contract ID:190215-D05

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks					
J413239	5065	MISC. HIGHWAY LIGHTING	Material		29	Apr 15, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user weathc1 overriding Payment Estimate Exception 22 on the current Payment Estimate.					
					29	Apr 15, 2022	SYSTEM	(\$462.00)						
					30	May 2, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user weathc1 overriding Payment Estimate Exception 22 on the current Payment Estimate.					
					30	May 2, 2022	SYSTEM	(\$462.00)						
					31	Jun 1, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user weathc1 overriding Payment Estimate Exception 22 on the current Payment Estimate.					
					31	Jun 1, 2022	SYSTEM	(\$462.00)						
					<b>- Total</b>								<b>\$0.00</b>	
					<b>Material - Total</b>								<b>\$0.00</b>	
					<b>5065 - Total</b>								<b>\$0.00</b>	
						5066	MISC. HIGHWAY LIGHTING	Material		29	Apr 15, 2022	SYSTEM	\$924.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user weathc1 overriding Payment Estimate Exception 16 on the current Payment Estimate.
										29	Apr 15, 2022	SYSTEM	(\$924.00)	
										30	May 2, 2022	SYSTEM	\$924.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user weathc1 overriding Payment Estimate Exception 16 on the current Payment Estimate.
30	May 2, 2022	SYSTEM	(\$924.00)											
31	Jun 1, 2022	SYSTEM	\$924.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user weathc1 overriding Payment Estimate Exception 16 on the current Payment Estimate.										
31	Jun 1, 2022	SYSTEM	(\$924.00)											
<b>- Total</b>										<b>\$0.00</b>				
<b>Material - Total</b>										<b>\$0.00</b>				
<b>5066 - Total</b>										<b>\$0.00</b>				
	5067	MISC. HIGHWAY LIGHTING	Material							29	Apr 15, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user weathc1 overriding Payment Estimate Exception 27 on the current Payment Estimate.
										29	Apr 15, 2022	SYSTEM	(\$462.00)	
										30	May 2, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user weathc1 overriding Payment Estimate Exception 27 on the current Payment Estimate.
					30	May 2, 2022	SYSTEM	(\$462.00)						
					31	Jun 1, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user weathc1 overriding Payment Estimate Exception 27 on the current Payment Estimate.					
					31	Jun 1, 2022	SYSTEM	(\$462.00)						
					<b>- Total</b>								<b>\$0.00</b>	
					<b>Material - Total</b>								<b>\$0.00</b>	
					<b>5067 - Total</b>								<b>\$0.00</b>	
						5068	MISC. HIGHWAY LIGHTING	Material		29	Apr 15, 2022	SYSTEM	\$319.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user weathc1 overriding Payment Estimate Exception 28 on the current Payment Estimate.
										29	Apr 15, 2022	SYSTEM	(\$319.10)	
										30	May 2, 2022	SYSTEM	\$319.10	This adjustment offsets the original system-generated Material Payment



## Line Item Adjustments by Estimate

Contract ID:190215-D05

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J413239	5068	MISC. HIGHWAY LIGHTING	Material			2022			Estimate Item Adjustment (0028) due to user weathc1 overriding Payment Estimate Exception 28 on the current Payment Estimate.
					30	May 2, 2022	SYSTEM	(\$319.10)	
					31	Jun 1, 2022	SYSTEM	\$319.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user weathc1 overriding Payment Estimate Exception 28 on the current Payment Estimate.
					31	Jun 1, 2022	SYSTEM	(\$319.10)	
					<b>- Total</b>			<b>\$0.00</b>	
					<b>Material - Total</b>			<b>\$0.00</b>	
<b>5068 - Total</b>			<b>\$0.00</b>						
5069	MISC. HIGHWAY LIGHTING	Material		29	Apr 15, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user weathc1 overriding Payment Estimate Exception 29 on the current Payment Estimate.	
				29	Apr 15, 2022	SYSTEM	(\$462.00)		
				30	May 2, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user weathc1 overriding Payment Estimate Exception 29 on the current Payment Estimate.	
				30	May 2, 2022	SYSTEM	(\$462.00)		
				31	Jun 1, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user weathc1 overriding Payment Estimate Exception 29 on the current Payment Estimate.	
				31	Jun 1, 2022	SYSTEM	(\$462.00)		
				<b>- Total</b>			<b>\$0.00</b>		
<b>Material - Total</b>			<b>\$0.00</b>						
<b>5069 - Total</b>			<b>\$0.00</b>						
5070	MISC. HIGHWAY LIGHTING	Material		29	Apr 15, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user weathc1 overriding Payment Estimate Exception 17 on the current Payment Estimate.	
				29	Apr 15, 2022	SYSTEM	(\$462.00)		
				30	May 2, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user weathc1 overriding Payment Estimate Exception 17 on the current Payment Estimate.	
				30	May 2, 2022	SYSTEM	(\$462.00)		
				31	Jun 1, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user weathc1 overriding Payment Estimate Exception 17 on the current Payment Estimate.	
				31	Jun 1, 2022	SYSTEM	(\$462.00)		
				<b>- Total</b>			<b>\$0.00</b>		
<b>Material - Total</b>			<b>\$0.00</b>						
<b>5070 - Total</b>			<b>\$0.00</b>						
5071	MISC. HIGHWAY LIGHTING	Material		29	Apr 15, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user weathc1 overriding Payment Estimate Exception 30 on the current Payment Estimate.	
				29	Apr 15, 2022	SYSTEM	(\$462.00)		
				30	May 2, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user weathc1 overriding Payment Estimate Exception 30 on the current Payment Estimate.	
				30	May 2, 2022	SYSTEM	(\$462.00)		
				31	Jun 1, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user weathc1 overriding Payment	



## Line Item Adjustments by Estimate

Contract ID:190215-D05

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J413239	5071	MISC. HIGHWAY LIGHTING	Material						Estimate Exception 30 on the current Payment Estimate.
					31	Jun 1, 2022	SYSTEM	(\$462.00)	
				<b>- Total</b>				<b>\$0.00</b>	
			<b>Material - Total</b>					<b>\$0.00</b>	
	<b>5071 - Total</b>							<b>\$0.00</b>	
<b>J413239 - Total</b>								<b>\$0.00</b>	
<b>Overall - Total</b>								<b>\$0.00</b>	