

Pay Estimate Created Date: March 16, 2021

Progress Estimate Number	Contract ID	200515-C11	Pay Period Start	March 2, 2021	<b>Original Contract Amount</b>	\$754,572.64
15	<b>Prime Contractor</b>	<b>Gunter Construction Company</b>	Pay Period End	March 15, 2021	<b>Net Change Order Amount</b>	\$153,436.62
13					Current Contract Amount	\$908,009.26

Approval Date		By User
March 16, 2021	Generated and Approved (and should be considered Draft) at the Project Office Level by	weathc1
March 17, 2021	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	sandis1
March 17, 2021	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
December 4, 2020	January 5, 2021		98.84%

	Contract Informational Date	tes	Milestones
Date Description	Original Completion Date	<b>Current Completion Date</b>	No Milestones Exist for Contract
Acceptance Date			
Awarded Date	June 3, 2020	June 3, 2020	
Letting Date	May 15, 2020	May 15, 2020	
Notice to Proceed Date	July 6, 2020	July 6, 2020	
Open to Traffic Date			
Work Began Date			

Contract Total Pay	For Estimate No. 15			
		This Estimate	Previous	To Date
200515-C11				
	Total Posted Items Pay	\$0.00	\$897,478.37	\$897,478.37
	Gross Item Adjustments	\$0.00	(\$301.76)	(\$301.76)
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$477.73	\$477.73
			\$897,654.34	\$897,654.34
<b>Contract Total Pay</b>	/able This Estimate:	\$0.00		

#### Items Paid This Estimate Period

No Data Available

#### Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

		tments Exist on Contract						
Line Item	<u>Adjustr</u>	nents This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4S3167	0030	COMPACTING EMBANKMENT	Material			-74.4	\$65.00	(\$4,836.00)
	0030	COMPACTING EMBANKMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0030) due to user weathc1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	74.4	\$65.00	\$4,836.00
	0060	MISC.	Material			-636.67	\$5.00	(\$3,183.35)
	0060	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0024) due to user weathc1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	636.67	\$5.00	\$3,183.35
	0070	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material			-628.3	\$23.00	(\$14,450.90)
	0070	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0031) due to user weathc1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	628.3	\$23.00	\$14,450.90
	0090	MISC.	Material			-289.8	\$90.00	(\$26,082.00)

Revision 4/1/2020 Page 1 of 65



Pay Estimate Created Date: March 16, 2021

Progress Estimate Number
15

Contract ID 200515-C11 Pay Period Start March 2, 2021 Original Contract Amount \$754,572.64
Pay Period End March 15, 2021 Net Change Order Amount \$153,436.62
Current Contract Amount \$908,009.26

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4S3167	0090	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0025) due to user weathc1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	289.8	\$90.00	\$26,082.00
	0110	PIPE COLLAR, TYPE A	Material			-3	\$1,695.00	(\$5,085.00)
	0110	PIPE COLLAR, TYPE A	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0032) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	3	\$1,695.00	\$5,085.00
	0120	CONCRETE CURB RAMP	Material			-96.6	\$185.00	(\$17,871.00)
	0120	CONCRETE CURB RAMP	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0034) due to user weathc1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	96.6	\$185.00	\$17,871.00
	0130	TRUNCATED DOMES	Material			-40	\$20.00	(\$800.00)
	0130	TRUNCATED DOMES	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0035) due to user weathc1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	40	\$20.00	\$800.00
	0140	6 IN. CONCRETE MEDIAN STRIP	Material			-70.7	\$140.00	(\$9,898.00)
	0140	6 IN. CONCRETE MEDIAN STRIP	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0033) due to user weathc1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	70.7	\$140.00	\$9,898.00
	0150	PAVED APPROACH, 8 IN.	Material			-100.5	\$115.00	(\$11,557.50)
	0150	PAVED APPROACH, 8 IN.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0036) due to user weathc1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	100.5	\$115.00	\$11,557.50
	0160	CONCRETE SIDEWALK, 4 IN.	Material			-566.9	\$75.00	(\$42,517.50)
	0160	CONCRETE SIDEWALK, 4 IN.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0037) due to user weathc1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	566.9	\$75.00	\$42,517.50
	0170	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	Material			-227.5	\$60.00	(\$13,650.00)
	0170	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0038) due to user weathc1 overridding Payment Estimate Exception 18 on the current Payment Estimate.	227.5	\$60.00	\$13,650.00
	0190	CONCRETE GUTTER TYPE B	Material			-21.5	\$120.00	(\$2,580.00)
	0190	CONCRETE GUTTER TYPE B	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0026) due to user weathc1 overridding Payment Estimate Exception 20 on the current Payment Estimate.	21.5	\$120.00	\$2,580.00

Revision 4/1/2020 Page 2 of 65



Pay Estimate Created Date: March 16, 2021

Progress Estimate Number
15

Contract ID 200515-C11 Pay Period Start March 2, 2021 Original Contract Amount \$754,572.64
Prime Contractor Gunter Construction Company Pay Period End March 15, 2021 Net Change Order Amount \$153,436.62
Current Contract Amount \$908,009.26

ect ber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
167	0200	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	Material			-100	\$40.00	(\$4,000.00)
	0200	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0027) due to user weathc1 overridding Payment Estimate Exception 22 on the current Payment Estimate.	100	\$40.00	\$4,000.00
	0210	MISC.	Material			-425	\$48.00	(\$20,400.00)
	0210	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0039) due to user weathc1 overridding Payment Estimate Exception 28 on the current Payment Estimate.	425	\$48.00	\$20,400.00
	0220	MISC.	Material			-182	\$130.00	(\$23,660.00)
	0220	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0023) due to user weathc1 overridding Payment Estimate Exception 25 on the current Payment Estimate.	182	\$130.00	\$23,660.00
	0390	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-27.5	\$14.00	(\$385.00)
	0390	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0001) due to user weathc1 overridding Payment Estimate Exception 49 on the current Payment Estimate.	27.5	\$14.00	\$385.00
	0420	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-2	\$430.00	(\$860.00)
	0420	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0002) due to user weathc1 overridding Payment Estimate Exception 50 on the current Payment Estimate.	2	\$430.00	\$860.00
	0430	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-8	\$140.00	(\$1,120.00)
	0430	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0003) due to user weathc1 overridding Payment Estimate Exception 51 on the current Payment Estimate.	8	\$140.00	\$1,120.00
	0440	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-308	\$0.18	(\$55.44)
	0440	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Exception 52 on the current Payment Estimate.	308	\$0.18	\$55.44
	0450	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-118	\$0.18	(\$21.24)

Revision 4/1/2020 Page 3 of 65



Pay Estimate Created Date: March 16, 2021

**Progress Estimate Number** 15

Contract ID200515-C11Pay Period StartMarch 2, 2021Original Contract Amount\$754,572.64Prime ContractorGunter Construction CompanyPay Period EndMarch 15, 2021Net Change Order Amount\$153,436.62Current Contract Amount\$908,009.26

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
4S3167	0450	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0005) due to user weathc1 overridding Payment Estimate Exception 53 on the current Payment Estimate.	118	\$0.18	\$21.24
	0470	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-193	\$0.12	(\$23.16
	0470	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0006) due to user weathc1 overridding Payment Estimate Exception 54 on the current Payment Estimate.	193	\$0.12	\$23.16
	0610	TURF TYPE TALL FESCUE SODDING	Material			-1,281	\$7.00	(\$8,967.00
	0610	TURF TYPE TALL FESCUE SODDING	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0029) due to user weathc1 overridding Payment Estimate Exception 30 on the current Payment Estimate.	1,281	\$7.00	\$8,967.00
	0660	SILT FENCE	Material			-15	\$1.65	(\$24.75
	0660	SILT FENCE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0022) due to user weathc1 overridding Payment Estimate Exception 35 on the current Payment Estimate.	15	\$1.65	\$24.75
	0740	POST, SIGNAL 8 FT. OR 2.4 M	Material			-4	\$1,050.00	(\$4,200.00
	0740	POST, SIGNAL 8 FT. OR 2.4 M	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0028) due to user weathc1 overridding Payment Estimate Exception 36 on the current Payment Estimate.	4	\$1,050.00	\$4,200.00
	0750	POST, TYPE BL, LONGEST ARM 55 FT.	Material			-2	\$23,650.00	(\$47,300.00
	0750	POST, TYPE BL, LONGEST ARM 55 FT.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0042) due to user weathc1 overridding Payment Estimate Exception 39 on the current Payment Estimate.	2	\$23,650.00	\$47,300.00
	0770	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-30	\$20.00	(\$600.00
	0770	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	Material			-190	\$20.00	(\$3,800.00
	0770	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 55 on the current Payment Estimate. Material Insufficiency Quantity 190.000; Overrun Quantity Balance 30.00.	30	\$20.00	\$600.00
	0770	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user weathc1 overridding Payment Estimate Exception 40 on the current Payment Estimate.	190	\$20.00	\$3,800.00
	0780	CONDUIT, 4 IN., TRENCH WITH TRACER WIRE	Material			-22	\$58.00	(\$1,276.00

Revision 4/1/2020 Page 4 of 65



Pay Estimate Created Date: March 16, 2021

Progress Estimate Number
15

Contract ID 200515-C11 Pay Period Start March 2, 2021 Original Contract Amount \$754,572.64
Prime Contractor Gunter Construction Company Pay Period End March 15, 2021 Net Change Order Amount \$153,436.62
Current Contract Amount \$908,009.26

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4S3167	0780	CONDUIT, 4 IN., TRENCH WITH TRACER WIRE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0021) due to user weathc1 overridding Payment Estimate Exception 41 on the current Payment Estimate.	22	\$58.00	\$1,276.00
	0790	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-135	\$36.00	(\$4,860.00)
	0790	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	Material			-320	\$36.00	(\$11,520.00)
	0790	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 56 on the current Payment Estimate. Material Insufficiency Quantity 320.000; Overrun Quantity Balance 135.00.	135	\$36.00	\$4,860.00
	0790	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user weathc1 overridding Payment Estimate Exception 42 on the current Payment Estimate.	320	\$36.00	\$11,520.00
	0810	CABLE, 8 AWG 1 CONDUCTOR, POWER	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-570	\$1.45	(\$826.50)
	0810	CABLE, 8 AWG 1 CONDUCTOR, POWER	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0011) due to user weathc1 overridding Payment Estimate Exception 57 on the current Payment Estimate.	570	\$1.45	\$826.50
	0830	CABLE, 16 AWG 2 CONDUCTOR	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-150	\$1.60	(\$240.00)
	0830	CABLE, 16 AWG 2 CONDUCTOR	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0012) due to user weathc1 overridding Payment Estimate Exception 58 on the current Payment Estimate.	150	\$1.60	\$240.00
	0840	CABLE, 16 AWG 5 CONDUCTOR	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-240	\$2.50	(\$600.00)
	0840	CABLE, 16 AWG 5 CONDUCTOR	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0013) due to user weathc1 overridding Payment Estimate Exception 59 on the current Payment Estimate.	240	\$2.50	\$600.00
	0850	CABLE, 16 AWG 7 CONDUCTOR	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-490	\$2.90	(\$1,421.00)
	0850	CABLE, 16 AWG 7 CONDUCTOR	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0014) due to user weathc1 overridding Payment Estimate Exception 60 on the current Payment Estimate.	490	\$2.90	\$1,421.00
	0880	PULL BOX, PREFORMED CLASS 2	Material			-1	\$750.00	(\$750.00)
	0880	PULL BOX, PREFORMED CLASS 2	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0018) due to user weathc1 overridding Payment Estimate Exception 43 on the current Payment Estimate.	1	\$750.00	\$750.00

Revision 4/1/2020 Page 5 of 65



Pay Estimate Created Date: March 16, 2021

Progress Estimate Number
15

Contract ID 200515-C11 Pay Period Start March 2, 2021 Original Contract Amount \$754,572.64
Pay Period End March 15, 2021 Net Change Order Amount \$153,436.62
Current Contract Amount \$908,009.26

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4S3167	0890	PULL BOX, PREFORMED CLASS 3	Material			-2	\$1,100.00	(\$2,200.00)
	0890	PULL BOX, PREFORMED CLASS 3	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0019) due to user weathc1 overridding Payment Estimate Exception 44 on the current Payment Estimate.	2	\$1,100.00	\$2,200.00
	0930	CONDUIT, 3 IN., RIGID, IN TRENCH	Material			-745	\$16.26	(\$12,113.70)
	0930	CONDUIT, 3 IN., RIGID, IN TRENCH	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0040) due to user weathc1 overridding Payment Estimate Exception 45 on the current Payment Estimate.	745	\$16.26	\$12,113.70
	0940	CONDUIT, 3 IN., RIGID, PUSHED	Material			-1,285	\$34.96	(\$44,923.60)
	0940	CONDUIT, 3 IN., RIGID, PUSHED	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0041) due to user weathc1 overridding Payment Estimate Exception 46 on the current Payment Estimate.	1,285	\$34.96	\$44,923.60
	0960	PULL BOX, PREFORMED CLASS 1	Material			-4	\$625.00	(\$2,500.00)
	0960	PULL BOX, PREFORMED CLASS 1	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0020) due to user weathc1 overridding Payment Estimate Exception 47 on the current Payment Estimate.	4	\$625.00	\$2,500.00
	0970	PULL BOX, PREFORMED CLASS 5	Material			-2	\$1,400.00	(\$2,800.00)
	0970	PULL BOX, PREFORMED CLASS 5	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0017) due to user weathc1 overridding Payment Estimate Exception 48 on the current Payment Estimate.	2	\$1,400.00	\$2,800.00
	0990	MISC.	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-2	\$1,200.00	(\$2,400.00)
	0990	MISC.	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0015) due to user weathc1 overridding Payment Estimate Exception 61 on the current Payment Estimate.	2	\$1,200.00	\$2,400.00
	5002	SEEDING - COOL SEASON MIXTURES	Material			-0.085	\$23,667.60	(\$2,011.75)
	5002	SEEDING - COOL SEASON MIXTURES	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0016) due to user weathc1 overridding Payment Estimate Exception 31 on the current Payment Estimate.	0.085	\$23,667.60	\$2,011.75
Total								\$0.00

Revision 4/1/2020 Page 6 of 65



						Contract Project Informatio	n			
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work			
J4S3167	FAF 7-3(24)	Signal improvements and add intersection turn lanes	7	JACKSON	on 8th Street in Blue Springs					
otals by	Job Numbe	ers								
J4S3167					This Estimate	Previous	To Date			
		Posted Item Pay Gross Item Adjustments			\$0.00 \$0.00	\$897,478.37 (\$301.76)	\$897,478.37 (\$301.76)			
			Gross	Item Pay	\$0.00	\$897,176.61	\$897,176.61			
	Incen	ntive			\$0.00	\$0.00	\$0.00			
		centive			\$0.00	\$0.00	\$0.00			
	I iaui	dated Damages			\$0.00	\$0.00	\$0.00			
		r Contract Adjus			\$0.00	\$477.73	\$477.73			

Revision 4/1/2020 Page 7 of 65



#### **Exceptions (Discrepancies) This Estimate Period**

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4S3167, Item 2036000, Project Item Line Number 0030, Material Set 203600096, Material 0200XXCS - Compacted Soil for Subgrade or Embankment, Acceptance Action Generic 0200XXCS is insufficient.	Materials need to enter compaction sample record	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3167, Item 2099905, Project Item Line Number 0060, Material Set 2099905, Material 0200XXCS - Compacted Soil for Subgrade orEmbankment, Acceptance Action Generic 0200XXCS is insufficient.	Materials need to enter compaction sample record	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3167, Item 3040506, Project Item Line Number 0070, Material Set 304050696, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Materials need to enter compaction sample record	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3167, Item 4019905, Project Item Line Number 0090, Material Set 401990596, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Materials need to enter a sample record for concrete breaks.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3167, Item 6044011, Project Item Line Number 0110, Material Set 604401196, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Materials need to enter a sample record for concrete breaks.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3167, Item 6044011, Project Item Line Number 0110, Material Set 604401196, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Materials need to enter a sample record for concrete breaks.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3167, Item 6081010, Project Item Line Number 0120, Material Set 608101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Materials need to enter a sample record for concrete breaks.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3167, Item 6081010, Project Item Line Number 0120, Material Set 608101096, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Materials need to enter a sample record for concrete breaks.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3167, Item 6081010, Project Item Line Number 0120, Material Set 608101096, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Materials need to enter a sample record for concrete breaks.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3167, Item 6081012, Project Item Line Number 0130, Material Set 608101296, Material 1067TRDO - Truncated Domes for ADA, Acceptance Action Generic 1067TRDO is insufficient.	Materials need to enter a sample record for concrete breaks.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3167, Item 6083006, Project Item Line Number 0140, Material Set 608300696, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Materials need to enter a sample record for concrete breaks.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3167, Item 6083006, Project Item Line Number 0140, Material Set 608300696, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Materials need to enter a sample record for concrete breaks.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3167, Item 6085008, Project Item Line Number 0150, Material Set 608500896, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Materials need to enter a sample record for concrete breaks.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3167, Item 6085008, Project Item Line Number 0150, Material Set 608500896, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Materials need to enter a sample record for concrete breaks.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3167, Item 6085008, Project Item Line Number 0150, Material Set 608500896, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Materials need to enter a sample record for concrete breaks.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3167, Item 6086004, Project Item Line Number 0160, Material Set 608600496, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Materials need to enter a sample record for concrete breaks.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3167, Item 6086004, Project Item Line Number 0160, Material Set 608600496, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Materials need to enter a sample record for concrete breaks.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3167, Item 6091010, Project Item Line Number 0170, Material Set 609101096, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Materials need to enter a sample record for concrete breaks.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3167, Item 6091010, Project Item Line Number 0170, Material Set 609101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Materials need to enter a sample record for concrete breaks.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3167, Item 6091042, Project Item Line Number 0190, Material Set 609104296, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Materials need to enter a sample record for concrete breaks.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3167, Item 6091042, Project Item Line Number 0190, Material Set 609104296, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Materials need to enter a sample record for concrete breaks.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3167, Item 6092011, Project Item Line Number 0200, Material Set 609201196, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Materials need to enter a sample record for concrete breaks.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3167, Item 6092011, Project Item Line Number 0200, Material Set 609201196, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Materials need to enter a sample record for concrete breaks.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3167, Item 6092011, Project Item Line Number 0200, Material Set 609201196, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action	Materials need to enter a sample record for concrete breaks.	weathc1	Overridden

Revision 4/1/2020 Page 8 of 65



**Exceptions (Discrepancies) This Estimate Period** 

Exceptions (Discrepancies) This Estimate Period			1
Exceptions / Discrepencies	Explanation	Entered By	Status
Generic 1005GDCMLD is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J4S3167, Item 6099903, Project Item Line Number 0220, Material Set 609903, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Materials need to enter a sample record for concrete breaks.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3167, Item 6099903, Project Item Line Number 0220, Material Set 609903, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Materials need to enter a sample record for concrete breaks.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3167, Item 6099903, Project Item Line Number 0220, Material Set 609903, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Materials need to enter a sample record for concrete breaks.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3167, Item 6099903, Project Item Line Number 0210, Material Set 6099903, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Materials need to enter a sample record for concrete breaks.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3167, Item 6099903, Project Item Line Number 0210, Material Set 6099903, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Materials need to enter a sample record for concrete breaks.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3167, Item 8031000A, Project Item Line Number 0610, Material Set 8031000A96, Material 0803SO - Sod, Acceptance Action Generic 0803SO is insufficient.	The sod was placed and is waiting for proper rooting	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3167, Item 8051000A, Project Item Line Number 5002, Material Set 8051000A96, Material 0805SD - Grass Seed -Seed, Acceptance Action Generic 0805SD is insufficient.	The sod was placed and is waiting for proper rooting	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3167, Item 8051000A, Project Item Line Number 5002, Material Set 8051000A96, Material 0802MLST - Mulch Straw (Vegetative Mulch), Acceptance Action Generic 0802MLST is insufficient.	The sod was placed and is waiting for proper rooting	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3167, Item 8051000A, Project Item Line Number 5002, Material Set 8051000A96, Material 0801FZ - Fertilizer, Acceptance Action Generic 0801FZ is insufficient.	The sod was placed and is waiting for proper rooting	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3167, Item 8051000A, Project Item Line Number 5002, Material Set 8051000A96, Material 0801AG - Agricultural Lime -Effective Nuetralizer, Acceptance Action Generic 0801AG is insufficient.	The sod was placed and is waiting for proper rooting	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3167, Item 8061019, Project Item Line Number 0660, Material Set 806101996, Material 1011GXT2 - Geotextile Fabric for TempSiltFence (T2), Acceptance Action Generic 1011GXT2 is insufficient.	Didn't use full quantity	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3167, Item 9022708, Project Item Line Number 0740, Material Set 902270896, Material 1092TSPS - Traffic Signal Post(s) - All Types, Acceptance Action Generic 1092TSPS is insufficient.	Signal posts are installed and waiting on certifications from WIT.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3167, Item 9022708, Project Item Line Number 0740, Material Set 902270896, Material 0902TSBTZCAB - Bolts Galv Anchor for Traffic Signals, Acceptance Action Generic 0902TSBTZCAB is insufficient.	Signal posts are installed and waiting on certifications from WIT.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3167, Item 9023455, Project Item Line Number 0750, Material Set 902345596, Material 0902TSBTZCAB - Bolts Galv Anchor for Traffic Signals, Acceptance Action Generic 0902TSBTZCAB is insufficient.	Signal heads are installed and waiting on certifications from WIT.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3167, Item 9023455, Project Item Line Number 0750, Material Set 902345596, Material 1092TSPS - Traffic Signal Post(s) - All Types, Acceptance Action Generic 1092TSPS is insufficient.	Signal heads are installed and waiting on certifications from WIT.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3167, Item 9025300, Project Item Line Number 0770, Material Set 902530096, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient.	Waiting for WIT to send in certifications of tracer wire.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3167, Item 9025400, Project Item Line Number 0780, Material Set 902540096, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient.	Waiting for WIT to send in certifications of tracer wire.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3167, Item 9027300, Project Item Line Number 0790, Material Set 902730096, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient.	Waiting for WIT to send in certifications of tracer wire.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3167, Item 9028811, Project Item Line Number 0880, Material Set 902881196, Material 1062PBPF - Pull Box Preformed Poly Resin Fiber, Acceptance Action Generic 1062PBPF is insufficient.	Materials has inspected the pull boxes and waiting for WIT to send in certifications.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3167, Item 9028812, Project Item Line Number 0890, Material Set 902881296, Material 1062PBPF - Pull Box Preformed Poly Resin Fiber, Acceptance Action Generic 1062PBPF is insufficient.	Materials has inspected the pull boxes and waiting for WIT to send in certifications.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3167, Item 9105201, Project Item Line Number 0930, Material Set 910520196, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient.	Waiting for WIT to send in certifications of In-Trenched conduit.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3167, Item 9107201, Project Item Line Number 0940, Material Set 910720196, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient.	Waiting for WIT to send in certifications of Pushed conduit.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3167, Item 9108810, Project Item Line Number 0960, Material Set 910881096, Material 1062PBPF - Pull Box Preformed Poly Resin Fiber, Acceptance Action Generic 1062PBPF is insufficient.	Materials has inspected the pull boxes waiting for WIT to send in certifications.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3167, Item 9108816, Project Item Line Number	Materials has inspected the pull boxes waiting for WIT to send	weathc1	Overridden
ovision 4/1/2020			Dago 0 of

Revision 4/1/2020 Page 9 of 65



#### **Exceptions (Discrepancies) This Estimate Period**

Exceptions / Discrepencies	Explanation	Entered By	Status
0970, Material Set 910881696, Material 1062PBPF - Pull Box Preformed Poly Resin Fiber, Acceptance Action Generic 1062PBPF is insufficient.	in certifications.		
Estimate Exception Type: Item Overrun: Contract 200515-C11, Contract Project J4S3167, Project Item Line Number 0390, Contract Line Item Number 0390, Item 6200015, Minor Item.	Will be on Change Order #0007	weathc1	Overridden
Estimate Exception Type: Item Overrun: Contract 200515-C11, Contract Project J4S3167, Project Item Line Number 0420, Contract Line Item Number 0420, Item 6200027, Minor Item.	Will be on Change Order #0007	weathc1	Overridden
Estimate Exception Type: Item Overrun: Contract 200515-C11, Contract Project J4S3167, Project Item Line Number 0430, Contract Line Item Number 0430, Item 6200036, Minor Item.	Will be on Change Order #0007	weathc1	Overridden
Estimate Exception Type: Item Overrun: Contract 200515-C11, Contract Project J4S3167, Project Item Line Number 0440, Contract Line Item Number 0440, Item 6205902A, Minor Item.	Will be on Change Order #0007	weathc1	Overridden
Estimate Exception Type: Item Overrun: Contract 200515-C11, Contract Project J4S3167, Project Item Line Number 0450, Contract Line Item Number 0450, Item 6205903A, Minor Item.	Will be on Change Order #0007	weathc1	Overridden
Estimate Exception Type: Item Overrun: Contract 200515-C11, Contract Project J4S3167, Project Item Line Number 0470, Contract Line Item Number 0470, Item 6206001C, Minor Item.	Will be on Change Order #0007	weathc1	Overridden
Estimate Exception Type: Item Overrun: Contract 200515-C11, Contract Project J4S3167, Project Item Line Number 0770, Contract Line Item Number 0770, Item 9025300, Minor Item.	Will be on Change Order #0007	weathc1	Overridden
Estimate Exception Type: Item Overrun: Contract 200515-C11, Contract Project J4S3167, Project Item Line Number 0790, Contract Line Item Number 0790, Item 9027300, Minor Item.	Will be on Change Order #0007	weathc1	Overridden
Estimate Exception Type: Item Overrun: Contract 200515-C11, Contract Project J4S3167, Project Item Line Number 0810, Contract Line Item Number 0810, Item 9028208, Minor Item.	Will be on Change Order #0007	weathc1	Overridden
Estimate Exception Type: Item Overrun: Contract 200515-C11, Contract Project J4S3167, Project Item Line Number 0830, Contract Line Item Number 0830, Item 9028308, Minor Item.	Will be on Change Order #0007	weathc1	Overridden
Estimate Exception Type: Item Overrun: Contract 200515-C11, Contract Project J4S3167, Project Item Line Number 0840, Contract Line Item Number 0840, Item 9028310, Minor Item.	Will be on Change Order #0007	weathc1	Overridden
Estimate Exception Type: Item Overrun: Contract 200515-C11, Contract Project J4S3167, Project Item Line Number 0850, Contract Line Item Number 0850, Item 9028311, Minor Item.	Will be on Change Order #0007	weathc1	Overridden
Estimate Exception Type: Item Overrun: Contract 200515-C11, Contract Project J4S3167, Project Item Line Number 0990, Contract Line Item Number 0990, Item 9109902, Minor Item.	Will be on Change Order #0007	weathc1	Overridden

Revision 4/1/2020 Page 10 of 65



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

#### Total Paid / All Items / All Estimates (Including this Estimate)

Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repo generated date)
00515-C11	J4S3167	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	1.00	2.00	LS	2.00	\$60,000.00	\$120,000.0
		0001	0020	2031000	CLASS A EXCAVATION	364.40	0.00	364.40	CUYD	364.40	\$80.00	\$29,152.0
		0001	0030	2036000	COMPACTING EMBANKMENT	74.40	0.00	74.40	CUYD	74.40	\$65.00	\$4,836.0
		0001	0040	2063000	CLASS 3 EXCAVATION	544.00	0.00	544.00	CUYD	544.00	\$70.00	\$38,080.0
		0001	0050	2079909	MISC.MODIFIED CLASS 2 LINEAR GRADING	10.20	1.60	11.80	STA	11.80	\$2,000.00	\$23,600.0
		0001	0060	2099905	MISC.MODIFIED 6 IN. SUBGRADE COMPACTION	239.60	397.07	636.67	SQYD	636.67	\$5.00	\$3,183.
		0001	0070	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	454.70	173.60	628.30	SQYD	628.30	\$23.00	\$14,450.
		0001	0800	4013000	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	232.00	-120.00	112.00	TONS	112.00	\$124.00	\$13,888
		0001	0090	4019905	MISC.Optional Pavement	234.20	55.60	289.80	SQYD	289.80	\$90.00	\$26,082
		0001	0100	4071005	TACK COAT	33.00	0.10	33.10	GAL	33.10	\$4.00	\$132
		0001	0110	6044011	PIPE COLLAR, TYPE A	10.00	-7.00	3.00	EA	3.00	\$1,695.00	\$5,085
		0001	0120	6081010	CONCRETE CURB RAMP	71.60	25.00	96.60	SQYD	96.60	\$185.00	\$17,871
		0001	0130	6081012	TRUNCATED DOMES	66.80	-26.80	40.00	SQFT	40.00	\$20.00	\$800
		0001	0140	6083006	6 IN. CONCRETE MEDIAN STRIP	70.00	0.70	70.70	SQYD	70.70	\$140.00	\$9,898
		0001	0150	6085008	PAVED APPROACH, 8 IN.	258.60	-158.10	100.50	SQYD	100.50	\$115.00	\$11,557
		0001	0160	6086004	CONCRETE SIDEWALK, 4 IN.	500.00	66.90	566.90	SQYD	566.90	\$75.00	\$42,517
		0001	0170	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	40.80	186.70	227.50	LF	227.50	\$60.00	\$13,650
		0001	0180	6091011	CONCRETE CURB (OVER 6 IN. HEIGHT) TYPE S	106.50	-106.50	0.00	LF	0.00	\$60.00	\$0
		0001	0190	6091042	CONCRETE GUTTER TYPE B	22.00	-0.50	21.50	LF	21.50	\$120.00	\$2,580
		0001	0200	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	176.30	-76.30	100.00	LF	100.00	\$40.00	\$4,000
		0001	0210	6099903	MISC.2 FT TYPE A CURB & GUTTER	349.00	76.00	425.00	LF	425.00	\$48.00	\$20,400
		0001	0220	6099903	MISC.Modified Integral Curb	31.10	150.90	182.00	LF	182.00	\$130.00	\$23,660
		0001	0230	6141120	CURVED VANE GRATE AND FRAME (2 FT. X 2 FT. OR 600MM X 600MM)	5.00	-2.00	3.00	EA	3.00	\$340.00	\$1,020
		0001	0240	6141121	CURVED VANE GRATE AND FRAME (4 FT. X 2 FT. OR 1200MM X 600MM)	1.00	0.00	1.00	EA	1.00	\$650.00	\$650
		0001	0250	6143013	MANHOLE FRAME AND COVER, TYPE 3	2.00	0.00	2.00	EA	2.00	\$180.00	\$360
		0001	0260	6149902	MISC.BICYCLE FRIENDLY APWA FRAME AND GRATE	3.00	0.00	3.00	EA	3.00	\$210.00	\$630
		0001	0270	6161005	CONSTRUCTION SIGNS	482.00	0.00	482.00	SQFT	482.00	\$4.00	\$1,928
		0001	0280	6161008	ADVANCED WARNING RAIL SYSTEM	2.00	0.00	2.00	EA	2.00	\$35.00	\$70
		0001	0290	6161009	FLAG ASSEMBLY	4.00	0.00	4.00	EA	4.00	\$15.00	\$60
		0001	0300	6161025	CHANNELIZER (TRIM LINE)	150.00	0.00	150.00	EA	150.00	\$18.00	\$2,700
		0001	0310	6161030	TYPE III MOVEABLE BARRICADE	2.00	0.00	2.00	EA	2.00	\$140.00	\$280
		0001	0320	6161033	DIRECTIONAL INDICATOR BARRICADE	30.00	0.00	30.00	EA	30.00	\$55.00	\$1,650
		0001	0330	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	2.00	\$1,800.00	\$3,600
		0001	0340	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$4,000.00	\$8,000
		0001	0350	6169902	MISC.ADA Compliant Moveble Barricade	4.00	0.00	4.00	EA	4.00	\$50.00	\$200
		0001	0360	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$56,655.00	\$56,655
		0001	0370	6200003	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 4 IN., WHITE	150.00	-150.00	0.00	LF	0.00	\$2.65	\$1
		0001	0380	6200009	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE	265.00	0.00	265.00	LF	0.00	\$4.00	\$
		0001	0390	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	114.00	0.00	114.00	LF	141.50	\$14.00	\$1,98
		0001	0400	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	26.00	0.00	26.00	LF	22.00	\$14.00	\$30
			PREFORMED THERMOPLASTIC PAVEMENT MARKING,	12.00	0.00	12.00	EA	9.00	\$220.00	\$1,980		
		0001	0420	6200027	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT	1.00	0.00	1.00	EA	3.00	\$430.00	\$1,290
		0001	0430	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	14.00	0.00	14.00	EA	22.00	\$140.00	\$3,080

Revision 4/1/2020 Page 11 of 65



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTEI To Date (See repor generated date)
00515-C11	J4S3167	0001	0440	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	2,325.00	0.00	2,325.00	LF	2,633.00	\$0.18	\$473.9
		0001	0450	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	1,899.00	0.00	1,899.00	LF	2,017.00	\$0.18	\$363.0
		0001	0460	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	175.00	0.00	175.00	LF	175.00	\$0.12	\$21.0
		0001	0470	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,050.00	0.00	1,050.00	LF	1,243.00	\$0.12	\$149.1
		0001	0480	6207001	PAVEMENT MARKING REMOVAL	5,217.00	0.00	5,217.00	LF	5,217.00	\$0.55	\$2,869.3
		0001	0490	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	16.00	0.00	16.00	EA	10.00	\$50.00	\$500.0
		0001	0500	6209902	MISC.PREFORMED THERMOPLASTIC BICYCLE SYMBOLS	8.00	0.00	8.00	EA	8.00	\$350.00	\$2,800.0
		0001	0510	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$8,000.00	\$8,000.0
		0001	0520	7139903A	MISC.APWA SINGLE GRATE INLET	13.00	0.00	13.00	LF	13.00	\$650.00	\$8,450.0
		0001	0530	7261012	12 IN. PIPE GROUP A	36.00	-7.00	29.00	LF	29.00	\$70.00	\$2,030.0
		0001	0540	7261015	15 IN. PIPE GROUP A	42.00	-5.00	37.00	LF	37.00	\$70.00	\$2,590.0
		0001	0550	7261018	18 IN. PIPE GROUP A	12.00	-10.80	1.20	LF	1.20	\$55.00	\$66.0
		0001	0560	7261036	36 IN. PIPE GROUP A	65.00	-36.00	29.00	LF	29.00	\$125.00	\$3,625.0
		0001	0570	7310060	PRECAST CONCRETE MANHOLE - 60 IN.	24.00	0.00	24.00	FT	24.00	\$550.00	\$13,200.0
		0001	0580	7311022	PRECAST CONCRETE DROP INLET 2 FT X 2 FT	11.00	0.00	11.00	FT	11.00	\$620.00	\$6,820.
		0001	0590	7311042	PRECAST CONCRETE DROP INLET 4 FT X 2 FT	13.00	0.00	13.00	FT	13.00	\$540.00	\$7,020.
		0001	0600	7320618A	18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	1.00	-1.00	0.00	EA	0.00	\$2,400.00	\$0.
		0001	0610	8031000A	TURF TYPE TALL FESCUE SODDING	1,108.00	173.00	1,281.00	SQYD	1,281.00	\$7.00	\$8,967
		0001	0620	8061006	ALTERNATE DITCH CHECK	50.00	0.00	50.00	LF	0.00	\$9.25	\$0.
		0001	0630	8061007A	CURB INLET CHECK	15.00	2.00	17.00	EA	17.00	\$69.00	\$1,173.
		0001	0640	8061016	SEDIMENT REMOVAL	20.00	0.00	20.00	CUYD	20.00	\$50.00	\$1,000.
		0001	0660	8061019	SILT FENCE	120.00	0.00	120.00	LF	15.00	\$1.65	\$24.
		0030	0680	9020513	SIGNAL HEAD, TYPE 3B	7.00	0.00	7.00	EA	7.00	\$1,220.00	\$8,540
		0030	0690	9020514	SIGNAL HEAD, TYPE 4B	3.00	0.00	3.00	EA	3.00	\$1,530.00	\$4,590
		0030	0700	9020515	SIGNAL HEAD, TYPE 5B	1.00	0.00	1.00	EA	1.00	\$1,660.00	\$1,660.
		0030	0710	9020811	SIGNAL HEAD, TYPE 1S, PEDESTRIAN	4.00	0.00	4.00	EA	4.00	\$1,500.00	\$6,000
		0030	0720	9020833	SH-FLAT SHEET - SIGNAL SIGN	62.00	0.00	62.00	SQFT	62.00	\$14.00	\$868.
		0030	0730	9020834	SIGNAL SIGN, MOUNTING HARDWARE	8.00	0.00	8.00	EA	8.00	\$150.00	\$1,200.
		0030	0735	9022651	LUMINAIRE LED-A, 120 VOLT COMPATIBLE	2.00	0.00	2.00	EA	2.00	\$550.00	\$1,100.
		0030	0740	9022708	POST, SIGNAL 8 FT. OR 2.4 M	4.00	0.00	4.00	EA	4.00	\$1,050.00	\$4,200
		0030	0750	9023455	POST, TYPE BL, LONGEST ARM 55 FT.	2.00	0.00	2.00	EA	2.00	\$23,650.00	\$47,300.
		0030	0760	9024283	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	1.00	0.00	1.00	EA	1.00	\$19,450.00	\$19,450.
		0030	0770	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	160.00	0.00	160.00	LF	190.00	\$20.00	\$3,800.
		0030	0780	9025400	CONDUIT, 4 IN., TRENCH WITH TRACER WIRE	22.00	0.00	22.00	LF	22.00	\$58.00	\$1,276.
		0030	0790	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	185.00	0.00	185.00	LF	320.00	\$36.00	\$11,520.
		0030	0800	9028100	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	180.00	0.00	180.00	LF	120.00	\$1.66	\$199.
		0030	0810	9028208	CABLE, 8 AWG 1 CONDUCTOR, POWER	150.00	0.00	150.00	LF	720.00	\$1.45	\$1,044
		0030	0820	9028302	CABLE, 12 AWG 2 CONDUCTOR	720.00	0.00	720.00	LF	550.00	\$1.80	\$990.
		0030	0830	9028308	CABLE, 16 AWG 2 CONDUCTOR	750.00	0.00	750.00	LF	900.00	\$1.60	\$1,440
		0030	0840	9028310	CABLE, 16 AWG 5 CONDUCTOR	760.00	0.00	760.00	LF	1,000.00	\$2.50	\$2,500
		0030	0850	9028311	CABLE, 16 AWG 7 CONDUCTOR	2,010.00	0.00	2,010.00	LF	2,500.00	\$2.90	\$7,250
		0030	0860	9028621	POWER SUPPLY ASSEMBLY, TYPE-2 WITH 120V LIGHTING CONTROL CABINET	1.00	0.00	1.00	EA	1.00	\$7,250.00	\$7,250
		0030	0870	9028810	PULL BOX, PREFORMED CLASS 1	1.00	0.00	1.00	EA	0.00	\$625.00	\$0.
		0030	0880	9028811	PULL BOX, PREFORMED CLASS 2	3.00	0.00	3.00	EA	1.00	\$750.00	\$750.

Page 12 of 65 Revision 4/1/2020



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTEI To Date (See repor- generated date)
515-C11	J4S3167	0030	0890	9028812	PULL BOX, PREFORMED CLASS 3	2.00	0.00	2.00	EA	2.00	\$1,100.00	\$2,200.0
		0030	0900	9029100	BASE, CONCRETE	11.00	6.00	17.00	CUYD	17.00	\$1,366.71	\$23,234.0
		0030	0910	9029902	MISC.Accessible Pedestrian Signals (Pushbuttons)	4.00	0.00	4.00	EA	4.00	\$1,565.00	\$6,260.0
		0030	0920	9029902	MISC.Optional Traffic Signal Detectors	4.00	0.00	4.00	EA	4.00	\$325.00	\$1,300.0
		0050	0930	9105201	CONDUIT, 3 IN., RIGID, IN TRENCH	745.00	660.00	1,405.00	LF	745.00	\$16.26	\$12,113.7
		0050	0940	9107201	CONDUIT, 3 IN., RIGID, PUSHED	536.00	749.00	1,285.00	LF	1,285.00	\$34.96	\$44,923.6
		0050	0950	9108353	FIBER OPTIC CABLE, 12-STRAND, SINGLE MODE	1,666.00	0.00	1,666.00	LF	1,666.00	\$3.25	\$5,414.5
		0050	0960	9108810	PULL BOX, PREFORMED CLASS 1	8.00	0.00	8.00	EA	4.00	\$625.00	\$2,500.0
		0050	0970	9108816	PULL BOX, PREFORMED CLASS 5	2.00	1.00	3.00	EA	2.00	\$1,400.00	\$2,800.0
		0050	0980	9109901	MISC.FIBER OPTIC TESTING AND DOCUMENTATION	1.00	0.00	1.00	LS	1.00	\$2,000.00	\$2,000.0
		0050	0985	9109901	MISC.INSTALLATION OF COMMISSION FURNISHED TELECOMMUNICATIONS EQUIPMENT	1.00	0.00	1.00	LS	1.00	\$3,500.00	\$3,500.0
		0050	0990	9109902	MISC.FIBER OPTIC SPLICE CABINET	2.00	0.00	2.00	EA	4.00	\$1,200.00	\$4,800.0
		0050	1000	9109902	MISC.FIBER OPTIC SPLICE UNDERGROUND	2.00	0.00	2.00	EA	2.00	\$1,050.00	\$2,100.0
		0050	1010	9109902	MISC.MEDIA CONVERTER FURNISH AND INSTALL	2.00	0.00	2.00	EA	2.00	\$1,350.00	\$2,700.0
		0050	1020	9109902	MISC.OGL SWITCH - FURNISH INSTALL	2.00	0.00	2.00	EA	2.00	\$8,500.00	\$17,000.
		0050	1030	9109902	MISC.PRE-TERMINATED FIBER PANEL, FURNISH - INSTALL	2.00	0.00	2.00	EA	2.00	\$550.00	\$1,100.
		0050	1040	9109902	MISC.SPLICE ENCLOSURE	1.00	1.00	2.00	EA	2.00	\$450.00	\$900.
		0050	1050	9109903	MISC.PRE-TERMINATED FIBER PANEL CABLE FURNISH - INSTALL	120.00	0.00	120.00	LF	120.00	\$5.50	\$660.0
		0001	5001	7320615A	15 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	0.00	1.00	1.00	EA	1.00	\$2,400.00	\$2,400.
		0001	5002	8051000A	SEEDING - COOL SEASON MIXTURES	0.00	0.08	0.08	ACRE	0.08	\$23,667.60	\$2,011.
		0001	5003	6089901		0.00	1.00	1.00	LS	1.00	\$6,840.18	\$6,840.
		0001	5004	7339901	MISC.PIPING ROOF DRAIN INTO DI 6	0.00	1.00	1.00	LS	1.00	\$1,555.61	\$1,555.
		0001	5005	6169901	MISC.TRAFFIC CONTROL – DI-9 STORM SEWER PIPE EXTENSION	0.00	1.00	1.00	LS	1.00	\$1,652.77	\$1,652.
		0001	5006	7339901	MISC.STORM SEWER ELEVATION CHANGES	0.00	1.00	1.00	LS	1.00	\$15,263.48	\$15,263.
		0001	5007	7339901	MISC.STORM SEWER ELEVATION CHANGES	0.00	1.00	1.00	LS	1.00	\$3,691.76	\$3,691.
		0001	5008	6099901	MISC.CURB ELEVATION ADJUSTMENTS	0.00	1.00	1.00	LS	1.00	\$874.21	\$874.
		0001	5009	2029901	01 MISC.REMOVAL OF IMPROVEMENTS 0.00 1.00 1.00 LS 1.00 \$1,671.90							
		0001	5010	9109901	MISC.MISC. DELAY COSTS	0.00	1.00	1.00	LS	1.00	\$8,281.57	\$8,281.
		0001	5011	9039901	MISC.SIGN INSTALLATION	0.00	1.00	1.00	LS	1.00	\$2,794.16	\$2,794.
		0030	5012	9029901	MISC.SIGNAL HEAD REPLACEMENT	0.00	1.00	1.00	LS	0.00	\$4,069.28	\$0.
	Project L	182167 To	tal Value	Postod to D	late as of Report Generated Date							\$897,478.

Page 13 of 65 Revision 4/1/2020



# Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 4/1/2020 Page 14 of 65



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0030	COMPACTING EMBANKMENT	Material		6	Oct 2, 2020	SYSTEM	(\$4,836.00)	
				6	Oct 2, 2020	SYSTEM	\$4,836.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user weathc1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				7	Nov 3, 2020	SYSTEM	(\$4,836.00)	
				7	Nov 3, 2020	SYSTEM	\$4,836.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user weathc1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				8	Nov 16, 2020	SYSTEM	(\$4,836.00)	
				8	Nov 16, 2020	SYSTEM	\$4,836.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user weathc1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				9	Dec 3, 2020	SYSTEM	(\$4,836.00)	
				9	Dec 3, 2020	SYSTEM	\$4,836.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user weathc1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				10	Dec 16, 2020	SYSTEM	(\$4,836.00)	
				10	Dec 16, 2020	SYSTEM	\$4,836.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				11	Jan 4, 2021	SYSTEM	(\$4,836.00)	
				11	Jan 4, 2021	SYSTEM	\$4,836.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user weathc1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				12	Jan 19, 2021	SYSTEM	(\$4,836.00)	
				12	Jan 19, 2021	SYSTEM	\$4,836.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user weathc1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				13	Feb 17, 2021	SYSTEM	(\$4,836.00)	
				13	Feb 17, 2021	SYSTEM	\$4,836.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0049) due to user weathc1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				14	Mar 2, 2021	SYSTEM	(\$4,836.00)	
				14	Mar 2, 2021	SYSTEM	\$4,836.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user weathc1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				15	Mar 16, 2021	SYSTEM	(\$4,836.00)	
				15	Mar 16, 2021	SYSTEM	\$4,836.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user weathc1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
	Metadal Total		- Total				\$0.00	
0030 -	Material - Total						\$0.00 \$0.00	
0030 -	MISC. MODIFIED 6 IN, SUBGRADE COMPACTION	Material		4	Sep 1, 2020	SYSTEM	(\$1,317.50)	
	3376.161	ON	N	4	Sep 1, 2020	SYSTEM	\$1,317.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				5	Sep 21, 2020	SYSTEM	(\$3,183.35)	
			Ę	5	Sep 21, 2020	SYSTEM	\$3,183.35	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user weathc1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				6	Oct 2, 2020	SYSTEM	(\$3,183.35)	
				6	Oct 2, 2020	SYSTEM	\$3,183.35	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user weathc1 overridding Payment Estimate Exception 2 on the current Payment Estimate.

Revision 4/1/2020 Page 15 of 65



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks										
Line	Bescription	Туре	Adjustment Type	Number	Date	By	Amount	Remains										
0060	MISC. MODIFIED 6 IN. SUBGRADE COMPACTION	Material		7	Nov 3, 2020	SYSTEM	(\$3,183.35)											
				7	Nov 3, 2020	SYSTEM	\$3,183.35	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user weathc1 overridding Payment Estimate Exception 2 on the current Payment Estimate.										
				8	Nov 16, 2020	SYSTEM	(\$3,183.35)											
				8	Nov 16, 2020	SYSTEM	\$3,183.35	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user weathc1 overridding Payment Estimate Exception 2 on the current Payment Estimate.										
				9	Dec 3, 2020	SYSTEM	(\$3,183.35)											
				9	Dec 3, 2020	SYSTEM	\$3,183.35	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user weathc1 overridding Payment Estimate Exception 2 on the current Payment Estimate.										
				10	Dec 16, 2020	SYSTEM	(\$3,183.35)											
				10	Dec 16, 2020	SYSTEM	\$3,183.35	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user weathc1 overridding Payment Estimate Exception 2 on the current Payment Estimate.										
				11	Jan 4, 2021	SYSTEM	(\$3,183.35)											
				11	Jan 4, 2021	SYSTEM	\$3,183.35	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user weathc1 overridding Payment Estimate Exception 2 on the current Payment Estimate.										
				12	Jan 19, 2021	SYSTEM	(\$3,183.35)											
				12	Jan 19, 2021	SYSTEM	\$3,183.35	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user weathc1 overridding Payment Estimate Exception 2 on the current Payment Estimate.										
				13	Feb 17, 2021	SYSTEM	(\$3,183.35)											
				13	Feb 17, 2021	SYSTEM	\$3,183.35	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user weathc1 overridding Payment Estimate Exception 2 on the current Payment Estimate.										
				14	Mar 2, 2021	SYSTEM	(\$3,183.35)											
				14	Mar 2, 2021	SYSTEM	\$3,183.35	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user weathc1 overridding Payment Estimate Exception 2 on the current Payment Estimate.										
				15	Mar 16, 2021	SYSTEM	(\$3,183.35)											
				15	Mar 16, 2021	SYSTEM	\$3,183.35	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user weathc1 overridding Payment Estimate Exception 2 on the current Payment Estimate.										
			- Total				\$0.00											
	Material - Total						\$0.00											
	MISC. MODIFIED 6 IN. SUBGRADE COMPACTION	Overrun	Overrun		Sep 1, 2020	SYSTEM	(\$119.50)											
				4	Sep 1, 2020	SYSTEM	\$119.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 42 on the current Payment Estimate.										
				5	Sep 21, 2020	SYSTEM	(\$119.50)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).										
														5	Sep 21, 2020	SYSTEM	(\$1,865.85)	
										5	Sep 21, 2020	SYSTEM	\$1,865.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 52 on the current Payment Estimate.				
				5	Sep 21, 2020	SYSTEM	\$119.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 52 on the current Payment Estimate.										
					6	Oct 2, 2020	SYSTEM	(\$1,865.85)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).									
					6	Oct 2, 2020	SYSTEM	\$1,865.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 51 on the current Payment Estimate.									
				7	Nov 3,	SYSTEM	(\$1,865.85)	Averaged Price Adjustment from this item on all previous payment										

Revision 4/1/2020 Page 16 of 65



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks										
0060	MISC. MODIFIED 6 IN. SUBGRADE	Overrun	Overrun		2020			estimates of '0.00000' is applied (if non-zero).										
	COMPACTION			7	Nov 3, 2020	SYSTEM	\$1,865.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 53 on the current Payment Estimate.										
				8	Nov 16, 2020	SYSTEM	(\$1,865.85)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).										
				8	Nov 16, 2020	SYSTEM	\$1,865.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 58 on the current Payment Estimate.										
				9	Dec 3, 2020	SYSTEM	(\$1,865.85)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).										
				9	Dec 3, 2020	SYSTEM	\$1,865.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 67 on the current Payment Estimate.										
			Overrun - T	otal			\$0.00											
	Overrun - Total						\$0.00											
0060 -	Total						\$0.00											
0070	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		4	Sep 1, 2020	SYSTEM	(\$14,450.90)											
				4	Sep 1, 2020	SYSTEM	\$14,450.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user weathc1 overridding Payment Estimate Exception 2 on the current Payment Estimate.										
				5	Sep 21, 2020	SYSTEM	(\$14,450.90)											
				5	Sep 21, 2020	SYSTEM	\$14,450.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user weathc1 overridding Payment Estimate Exception 2 on the current Payment Estimate.										
				6	Oct 2, 2020	SYSTEM	(\$14,450.90)											
				6	Oct 2, 2020	SYSTEM	\$14,450.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user weathc1 overridding Payment Estimate Exception 3 on the current Payment Estimate.										
				7	Nov 3, 2020	SYSTEM	(\$14,450.90)											
				7	Nov 3, 2020	SYSTEM	\$14,450.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user weathc1 overridding Payment Estimate Exception 3 on the current Payment Estimate.										
				8	Nov 16, 2020	SYSTEM	(\$14,450.90)											
				8	Nov 16, 2020	SYSTEM	\$14,450.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user weathc1 overridding Payment Estimate Exception 3 on the current Payment Estimate.										
				9	Dec 3, 2020	SYSTEM	(\$14,450.90)											
				9	Dec 3, 2020	SYSTEM	\$14,450.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user weathc1 overridding Payment Estimate Exception 3 on the current Payment Estimate.										
				10	Dec 16, 2020	SYSTEM	(\$14,450.90)											
				10	Dec 16, 2020	SYSTEM	\$14,450.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user weathc1 overridding Payment Estimate Exception 3 on the current Payment Estimate.										
														11	Jan 4, 2021	SYSTEM	(\$14,450.90)	
																	11	Jan 4, 2021
									12	Jan 19, 2021	SYSTEM	(\$14,450.90)						
				1					12	Jan 19, 2021	SYSTEM	\$14,450.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user weathc1 overridding Payment Estimate Exception 3 on the current Payment Estimate.					
				13	Feb 17, 2021	SYSTEM	(\$14,450.90)											
				13	Feb 17, 2021	SYSTEM	\$14,450.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user weathc1 overridding Payment Estimate Exception 3 on the current Payment Estimate.										

Revision 4/1/2020 Page 17 of 65



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks										
0070	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		14	Mar 2, 2021	SYSTEM	(\$14,450.90)											
				14	Mar 2, 2021	SYSTEM	\$14,450.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user weathc1 overridding Payment Estimate Exception 3 on the current Payment Estimate.										
				15	Mar 16, 2021	SYSTEM	(\$14,450.90)											
				15	Mar 16, 2021	SYSTEM	\$14,450.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user weathc1 overridding Payment Estimate Exception 3 on the current Payment Estimate.										
			- Total				\$0.00											
	Material - Total						\$0.00											
	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Overrun	Overrun	4	Sep 1, 2020	SYSTEM	(\$3,992.80)											
						4	Sep 1, 2020	SYSTEM	\$3,992.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 43 on the current Payment Estimate.								
				5	Sep 21, 2020	SYSTEM	(\$3,992.80)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).										
				5	Sep 21, 2020	SYSTEM	\$3,992.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) overridding Payment Estimate Exception 53 on the current Payment Estimate.										
			Overrun - T	otal			\$0.00											
	Overrun - Total						\$0.00											
0070 -	· Total						\$0.00											
0090	MISC. Optional Pavement	Material		3	Aug 18, 2020	SYSTEM	(\$1,593.00)											
				3	Aug 18, 2020	SYSTEM	\$1,593.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user weathc1 overridding Payment Estimate Exception 1 on the current Payment Estimate.										
				4	Sep 1, 2020	SYSTEM	(\$18,567.00)											
				4	Sep 1, 2020	SYSTEM	\$18,567.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user weathc1 overridding Payment Estimate Exception 3 on the current Payment Estimate.										
				5	Sep 21, 2020	SYSTEM	(\$20,601.00)											
				5	Sep 21, 2020	SYSTEM	\$20,601.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user weathc1 overridding Payment Estimate Exception 3 on the current Payment Estimate.										
				6	Oct 2, 2020	SYSTEM	(\$20,601.00)											
				6	Oct 2, 2020	SYSTEM	\$20,601.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user weathc1 overridding Payment Estimate Exception 4 on the current Payment Estimate.										
				7	Nov 3, 2020	SYSTEM	(\$20,601.00)											
				7	Nov 3, 2020	SYSTEM	\$20,601.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user weathc1 overridding Payment Estimate Exception 4 on the current Payment Estimate.										
				8	Nov 16, 2020	SYSTEM	(\$20,601.00)											
														8	Nov 16, 2020	SYSTEM	\$20,601.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user weathc1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				9	Dec 3, 2020	SYSTEM	(\$20,601.00)											
				9	Dec 3, 2020	SYSTEM	\$20,601.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user weathc1 overridding Payment Estimate Exception 4 on the current Payment Estimate.										
				10	Dec 16, 2020	SYSTEM	(\$26,082.00)											
					10	Dec 16, 2020	SYSTEM	\$26,082.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user weathc1 overridding Payment Estimate Exception 4 on the current Payment Estimate.									
				11	Jan 4, 2021	SYSTEM	(\$26,082.00)											

Revision 4/1/2020 Page 18 of 65



1.5	5	A dia t	6"	-	0	0	Δ	
Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0090	MISC. Optional Pavement	Material		11	Jan 4, 2021	SYSTEM	\$26,082.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user weathc1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				12	Jan 19, 2021	SYSTEM	(\$26,082.00)	
				12	Jan 19, 2021	SYSTEM	\$26,082.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user weathc1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				13	Feb 17, 2021	SYSTEM	(\$26,082.00)	
				13	Feb 17, 2021	SYSTEM	\$26,082.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user weathc1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				14	Mar 2, 2021	SYSTEM	(\$26,082.00)	
				14	Mar 2, 2021	SYSTEM	\$26,082.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user weathc1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				15	Mar 16, 2021	SYSTEM	(\$26,082.00)	
				15	Mar 16, 2021	SYSTEM	\$26,082.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user weathc1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0090 -	Total						\$0.00	
0100	TACK COAT	Material		4	Sep 1, 2020	SYSTEM	(\$132.40)	
				4	Sep 1, 2020	SYSTEM	\$132.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user weathc1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				5	Sep 21, 2020	SYSTEM	(\$132.40)	
				5	Sep 21, 2020	SYSTEM	\$132.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	TACK COAT	Overrun	Overrun	4	Sep 1, 2020	SYSTEM	(\$0.40)	
				4	Sep 1, 2020	SYSTEM	\$0.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 44 on the current Payment Estimate.
				5	Sep 21, 2020	SYSTEM	(\$0.40)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				5	Sep 21, 2020	SYSTEM	\$0.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 54 on the current Payment Estimate.
				6	Oct 2, 2020	SYSTEM	(\$0.40)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				6	Oct 2, 2020	SYSTEM	\$0.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user weathc1 overridding Payment Estimate Exception 52 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0100 -	Total						\$0.00	
0110	PIPE COLLAR, TYPE A	Material		2	Aug 4, 2020	SYSTEM	(\$1,695.00)	
				2	Aug 4, 2020	SYSTEM	\$1,695.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user weathc1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				3	Aug 18, 2020	SYSTEM	(\$1,695.00)	
				3	Aug 18, 2020	SYSTEM	\$1,695.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Exception 2 on the current Payment Estimate.

Revision 4/1/2020 Page 19 of 65



Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
0110	PIPE COLLAR, TYPE A	Material	Туре	4	Sep 1,	SYSTEM	(\$1,695.00)	
					2020	OVOTELL		
				4	Sep 1, 2020	SYSTEM	\$1,695.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user weathc1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				5	Sep 21, 2020	SYSTEM	(\$5,085.00)	
				5	Sep 21, 2020	SYSTEM	\$5,085.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user weathc1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				6	Oct 2, 2020	SYSTEM	(\$5,085.00)	
				6	Oct 2, 2020	SYSTEM	\$5,085.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				7	Nov 3, 2020	SYSTEM	(\$5,085.00)	
				7	Nov 3, 2020	SYSTEM	\$5,085.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				8	Nov 16, 2020	SYSTEM	(\$5,085.00)	
				8	Nov 16, 2020	SYSTEM	\$5,085.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				9	Dec 3, 2020	SYSTEM	(\$5,085.00)	
				9	Dec 3, 2020	SYSTEM	\$5,085.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				10	Dec 16, 2020	SYSTEM	(\$5,085.00)	
				10	Dec 16, 2020	SYSTEM	\$5,085.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				11	Jan 4, 2021	SYSTEM	(\$5,085.00)	
				11	Jan 4, 2021	SYSTEM	\$5,085.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0048) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				12	Jan 19, 2021	SYSTEM	(\$5,085.00)	
				12	Jan 19, 2021	SYSTEM	\$5,085.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0048) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				13	Feb 17, 2021	SYSTEM	(\$5,085.00)	
				13	Feb 17, 2021	SYSTEM	\$5,085.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0051) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				14	Mar 2, 2021	SYSTEM	(\$5,085.00)	
				14	Mar 2, 2021	SYSTEM	\$5,085.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				15	Mar 16, 2021	SYSTEM	(\$5,085.00)	
				15	Mar 16, 2021	SYSTEM	\$5,085.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0110 -	CONCRETE CURB RAMP	Material		4	Sep 1,	SYSTEM	\$0.00	
0120	CONCRETE CURD RAMP	iviateiläl		4	Sep 1, 2020	SISIEW	(\$2,090.50)	
				4	Sep 1, 2020	SYSTEM	\$2,090.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user weathc1 overridding Payment Estimate Exception 10 on the current Payment Estimate.

Revision 4/1/2020 Page 20 of 65



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																
0120	CONCRETE CURB RAMP	Material	1 3 P G	5	Sep 21, 2020	SYSTEM	(\$10,748.50)																	
				5	Sep 21, 2020	SYSTEM	\$10,748.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user weathc1 overridding Payment Estimate Exception 9 on the current Payment Estimate.																
				6	Oct 2, 2020	SYSTEM	(\$13,930.50)																	
								6	Oct 2, 2020	SYSTEM	\$13,930.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user weathc1 overridding Payment Estimate Exception 7 on the current Payment Estimate.												
						7	Nov 3, 2020	SYSTEM	(\$13,930.50)															
				7	Nov 3, 2020	SYSTEM	\$13,930.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 7 on the current Payment Estimate.																
						8	Nov 16, 2020	SYSTEM	(\$13,930.50)															
						8	Nov 16, 2020	SYSTEM	\$13,930.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user weathc1 overridding Payment Estimate Exception 7 on the current Payment Estimate.														
							9	Dec 3, 2020	SYSTEM	(\$13,930.50)														
						9	Dec 3, 2020	SYSTEM	\$13,930.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user weathc1 overridding Payment Estimate Exception 7 on the current Payment Estimate.														
								10	Dec 16, 2020	SYSTEM	(\$17,871.00)													
				10	Dec 16, 2020	SYSTEM	\$17,871.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user weathc1 overridding Payment Estimate Exception 7 on the current Payment Estimate.																
					11	Jan 4, 2021	SYSTEM	(\$17,871.00)																
				11	Jan 4, 2021	SYSTEM	\$17,871.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0052) due to user weathc1 overridding Payment Estimate Exception 7 on the current Payment Estimate.																
					12	Jan 19, 2021	SYSTEM	(\$17,871.00)																
				12	Jan 19, 2021	SYSTEM	\$17,871.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0052) due to user weathc1 overridding Payment Estimate Exception 7 on the current Payment Estimate.																
															13	Feb 17, 2021	SYSTEM	(\$17,871.00)						
																				13	Feb 17, 2021	SYSTEM	\$17,871.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0055) due to user weathc1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
																			14	Mar 2, 2021	SYSTEM	(\$17,871.00)		
				15	Mar 16, 2021	SYSTEM	(\$17,871.00)																	
				15	Mar 16, 2021	SYSTEM	\$17,871.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user weathc1 overridding Payment Estimate Exception 7 on the current Payment Estimate.																
	Material - Total		- Total				\$0.00 \$0.00																	
0120	· Total						\$0.00																	
0130	TRUNCATED DOMES	Material		5	Sep 21, 2020	SYSTEM	(\$200.00)																	
				5	Sep 21, 2020	SYSTEM	\$200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user weathc1 overridding Payment Estimate Exception 12 on the current Payment Estimate.																
				6	Oct 2, 2020	SYSTEM	(\$400.00)	, , , , , , , , , , , , , , , , , , , ,																
				6	Oct 2, 2020	SYSTEM	\$400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user weathc1 overridding Payment Estimate Exception 10 on the current Payment Estimate.																

Revision 4/1/2020 Page 21 of 65



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks																							
		Type	Adjustment Type	Number	Date	Ву																									
0130	TRUNCATED DOMES	Material		7	Nov 3, 2020	SYSTEM	(\$400.00)																								
				7	Nov 3, 2020	SYSTEM	\$400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user weathc1 overridding Payment Estimate Exception 10 on the current Payment Estimate.																							
				8	Nov 16, 2020	SYSTEM	(\$400.00)																								
					8	Nov 16, 2020	SYSTEM	\$400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user weathc1 overridding Payment Estimate Exception 10 on the current Payment Estimate.																						
									9	Dec 3, 2020	SYSTEM	(\$400.00)																			
				9	Dec 3, 2020	SYSTEM	\$400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user weathc1 overridding Payment Estimate Exception 10 on the current Payment Estimate.																							
					10	Dec 16, 2020	SYSTEM	(\$800.00)																							
				10	Dec 16, 2020	SYSTEM	\$800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user weathc1 overridding Payment Estimate Exception 10 on the current Payment Estimate.																							
							11	Jan 4, 2021	SYSTEM	(\$800.00)																					
					11	Jan 4, 2021	SYSTEM	\$800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0053) due to user weathc1 overridding Payment Estimate Exception 10 on the current Payment Estimate.																						
							12	Jan 19, 2021	SYSTEM	(\$800.00)																					
				12	Jan 19, 2021	SYSTEM	\$800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0053) due to user weathc1 overridding Payment Estimate Exception 10 on the current Payment Estimate.																							
				13	Feb 17, 2021	SYSTEM	(\$800.00)																								
				13	Feb 17, 2021	SYSTEM	\$800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0056) due to user weathc1 overridding Payment Estimate Exception 10 on the current Payment Estimate.																							
				14	Mar 2, 2021	SYSTEM	(\$800.00)																								
				14	Mar 2, 2021	SYSTEM	\$800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user weathc1 overridding Payment Estimate Exception 10 on the current Payment Estimate.																							
								15	Mar 16, 2021	SYSTEM	(\$800.00)																				
									15	Mar 16, 2021	SYSTEM	\$800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user weathc1 overridding Payment Estimate Exception 10 on the current Payment Estimate.																		
			- Total				\$0.00																								
	Material - Total						\$0.00																								
	Total					0)/	\$0.00																								
0140	6 IN. CONCRETE MEDIAN STRIP	Material		6	Oct 2, 2020	SYSTEM	(\$9,898.00)																								
				6	Oct 2, 2020	SYSTEM	\$9,898.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user weathc1 overridding Payment Estimate Exception 11 on the current Payment Estimate.																							
																									7	Nov 3, 2020	SYSTEM	(\$9,898.00)			
																													7	Nov 3, 2020	SYSTEM
				8	Nov 16, 2020	SYSTEM	(\$9,898.00)																								
																											8	Nov 16, 2020	SYSTEM	\$9,898.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user weathc1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				9	Dec 3, 2020	SYSTEM	\$9,898.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user weathc1 overridding Payment Estimate Exception 11 on the current Payment Estimate.																							

Revision 4/1/2020 Page 22 of 65



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks									
0140	6 IN. CONCRETE MEDIAN STRIP	Material		10	Dec 16, 2020	SYSTEM	(\$9,898.00)										
				10	Dec 16, 2020	SYSTEM	\$9,898.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user weathc1 overridding Payment Estimate Exception 11 on the current Payment Estimate.									
				11	Jan 4, 2021	SYSTEM	(\$9,898.00)										
				11	Jan 4, 2021	SYSTEM	\$9,898.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0051) due to user weathc1 overridding Payment Estimate Exception 11 on the current Payment Estimate.									
					12	Jan 19, 2021	SYSTEM	(\$9,898.00)									
				12	Jan 19, 2021	SYSTEM	\$9,898.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0051) due to user weathc1 overridding Payment Estimate Exception 11 on the current Payment Estimate.									
					13	Feb 17, 2021	SYSTEM	(\$9,898.00)									
										13	Feb 17, 2021	SYSTEM	\$9,898.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0054) due to user weathc1 overridding Payment Estimate Exception 11 on the current Payment Estimate.			
													14	Mar 2, 2021	SYSTEM	(\$9,898.00)	
															14	Mar 2, 2021	SYSTEM
										15	Mar 16, 2021	SYSTEM	(\$9,898.00)				
				15	Mar 16, 2021	SYSTEM	\$9,898.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user weathc1 overridding Payment Estimate Exception 11 on the current Payment Estimate.									
			- Total				\$0.00										
	Material - Total																
	6 IN. CONCRETE MEDIAN STRIP						\$0.00										
		Overrun	Overrun	6	Oct 2, 2020	SYSTEM	\$0.00 (\$98.00)										
		Overrun	Overrun	6		SYSTEM SYSTEM		This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) overridding Payment Estimate Exception 57 on the current Payment Estimate.									
		Overrun	Overrun		2020 Oct 2,		(\$98.00)	Estimate Item Adjustment (0013) overridding Payment Estimate									
		Overrun	Overrun	6	2020 Oct 2, 2020 Nov 3,	SYSTEM	(\$98.00) \$98.00	Estimate Item Adjustment (0013) overridding Payment Estimate Exception 57 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment									
		Overrun	Overrun	6	2020 Oct 2, 2020 Nov 3, 2020 Nov 3,	SYSTEM	(\$98.00) \$98.00 (\$98.00)	Estimate Item Adjustment (0013) overridding Payment Estimate Exception 57 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate									
		Overrun	Overrun	6 7 7	2020 Oct 2, 2020 Nov 3, 2020 Nov 3, 2020	SYSTEM SYSTEM	(\$98.00) \$98.00 (\$98.00) \$98.00	Estimate Item Adjustment (0013) overridding Payment Estimate Exception 57 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 56 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment									
		Overrun	Overrun	6 7 7 8	2020 Oct 2, 2020 Nov 3, 2020 Nov 16, 2020 Nov 16,	SYSTEM SYSTEM SYSTEM	(\$98.00) \$98.00 (\$98.00) \$98.00	Estimate Item Adjustment (0013) overridding Payment Estimate Exception 57 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 56 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate									
		Overrun	Overrun	6 7 7 8 8	2020 Oct 2, 2020 Nov 3, 2020 Nov 3, 2020 Nov 16, 2020 Dec 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$98.00) \$98.00 (\$98.00) \$98.00 (\$98.00)	Estimate Item Adjustment (0013) overridding Payment Estimate Exception 57 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 56 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 62 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment									
	6 IN. CONCRETE MEDIAN STRIP	Overrun	Overrun - To	6 7 7 8 8 8 9 9 9	2020 Oct 2, 2020 Nov 3, 2020 Nov 3, 2020 Nov 16, 2020 Dec 3, 2020 Dec 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$98.00) \$98.00 (\$98.00) \$98.00 (\$98.00) \$98.00 \$98.00	Estimate Item Adjustment (0013) overridding Payment Estimate Exception 57 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 56 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 62 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).									
	6 IN. CONCRETE MEDIAN STRIP  Overrun - Total	Overrun		6 7 7 8 8 8 9 9 9	2020 Oct 2, 2020 Nov 3, 2020 Nov 3, 2020 Nov 16, 2020 Dec 3, 2020 Dec 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$98.00) \$98.00 (\$98.00) \$98.00 (\$98.00) \$98.00 \$98.00	Estimate Item Adjustment (0013) overridding Payment Estimate Exception 57 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 56 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 62 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate									
	6 IN. CONCRETE MEDIAN STRIP  Overrun - Total  Total			6 7 7 8 8 8 9 9 9	2020 Oct 2, 2020 Nov 3, 2020 Nov 16, 2020 Dec 3, 2020 Dec 3, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$98.00) \$98.00 (\$98.00) \$98.00 (\$98.00) \$98.00 \$98.00 \$0.00	Estimate Item Adjustment (0013) overridding Payment Estimate Exception 57 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 56 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 62 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate									
<b>0140</b> 0150	6 IN. CONCRETE MEDIAN STRIP  Overrun - Total	Overrun		6 7 7 7 8 8 8 9 9 9 Dtal	2020 Oct 2, 2020 Nov 3, 2020 Nov 16, 2020 Dec 3, 2020  Aug 18, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$98.00) \$98.00 (\$98.00) \$98.00 (\$98.00) \$98.00 \$98.00 \$0.00 \$0.00 (\$5,359.00)	Estimate Item Adjustment (0013) overridding Payment Estimate Exception 57 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 56 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 62 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 71 on the current Payment Estimate.									
	6 IN. CONCRETE MEDIAN STRIP  Overrun - Total  Total			6 7 7 7 8 8 8 9 9 9 9 1 3 3 3 3 3	2020 Oct 2, 2020 Nov 3, 2020 Nov 3, 2020 Nov 16, 2020 Dec 3, 2020  Aug 18, 2020 Aug 18, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$98.00) \$98.00 (\$98.00) \$98.00 (\$98.00) \$98.00 \$98.00 \$0.00 \$0.00 \$5,359.00	Estimate Item Adjustment (0013) overridding Payment Estimate Exception 57 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 56 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 62 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate									
	6 IN. CONCRETE MEDIAN STRIP  Overrun - Total  Total			6 7 7 7 8 8 8 9 9 9 Dtal	2020 Oct 2, 2020 Nov 3, 2020 Nov 3, 2020 Nov 16, 2020 Dec 3, 2020 Aug 18, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$98.00) \$98.00 (\$98.00) \$98.00 (\$98.00) \$98.00 \$98.00 \$0.00 \$0.00 (\$5,359.00)	Estimate Item Adjustment (0013) overridding Payment Estimate Exception 57 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 56 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 62 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 71 on the current Payment Estimate.									
	6 IN. CONCRETE MEDIAN STRIP  Overrun - Total  Total			6 7 7 7 8 8 8 9 9 9 9 1 3 3 3 3	2020 Oct 2, 2020 Nov 3, 2020 Nov 16, 2020 Nov 16, 2020 Dec 3, 2020 Dec 3, 2020 Aug 18, 2020 Sep 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$98.00) \$98.00 (\$98.00) \$98.00 (\$98.00) \$98.00 \$98.00 \$0.00 \$0.00 \$5,359.00	Estimate Item Adjustment (0013) overridding Payment Estimate Exception 57 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 56 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 62 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 71 on the current Payment Estimate.									

Revision 4/1/2020 Page 23 of 65



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																					
0150	PAVED APPROACH, 8 IN.	Material	71	5	Sep 21, 2020	SYSTEM	\$11,557.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user weathc1 overridding Payment Estimate Exception 13 on the current Payment Estimate.																					
				6	Oct 2, 2020	SYSTEM	(\$11,557.50)																						
				6	Oct 2, 2020	SYSTEM	\$11,557.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user weathc1 overridding Payment Estimate Exception 14 on the current Payment Estimate.																					
							7	Nov 3, 2020	SYSTEM	(\$11,557.50)																			
					7	Nov 3, 2020	SYSTEM	\$11,557.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Exception 14 on the current Payment Estimate.																				
									8	Nov 16, 2020	SYSTEM	(\$11,557.50)																	
				8	Nov 16, 2020	SYSTEM	\$11,557.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Exception 14 on the current Payment Estimate.																					
					9	Dec 3, 2020	SYSTEM	(\$11,557.50)																					
						9	Dec 3, 2020	SYSTEM	\$11,557.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Exception 14 on the current Payment Estimate.																			
								10	Dec 16, 2020	SYSTEM	(\$11,557.50)																		
					10	Dec 16, 2020	SYSTEM	\$11,557.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user weathc1 overridding Payment Estimate Exception 14 on the current Payment Estimate.																				
				11	Jan 4, 2021	SYSTEM	(\$11,557.50)																						
				11	Jan 4, 2021	SYSTEM	\$11,557.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0054) due to user weathc1 overridding Payment Estimate Exception 14 on the current Payment Estimate.																					
									12	Jan 19, 2021	SYSTEM	(\$11,557.50)																	
								12	Jan 19, 2021	SYSTEM	\$11,557.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0054) due to user weathc1 overridding Payment Estimate Exception 14 on the current Payment Estimate.																	
																		13	Feb 17, 2021	SYSTEM	(\$11,557.50)								
					13	Feb 17, 2021	SYSTEM	\$11,557.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0057) due to user weathc1 overridding Payment Estimate Exception 14 on the current Payment Estimate.																				
											14	Mar 2, 2021	SYSTEM	(\$11,557.50)															
																													14
				15	Mar 16, 2021	SYSTEM	(\$11,557.50)																						
							15	Mar 16, 2021	SYSTEM	\$11,557.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user weathc1 overridding Payment Estimate Exception 13 on the current Payment Estimate.																		
			- Total				\$0.00																						
	Material - Total						\$0.00																						
	PAVED APPROACH, 8 IN.	Overrun	Overrun		Oct 2, 2020	SYSTEM	(\$1,357.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).																					
																									6	Oct 2, 2020	SYSTEM	\$1,357.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 53 on the current Payment Estimate.
				7	Nov 3, 2020	SYSTEM	(\$1,357.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).																					
						7	Nov 3, 2020	SYSTEM	\$1,357.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 54 on the current Payment Estimate.																			
									8	Nov 16, 2020	SYSTEM	(\$1,357.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).																
												8	Nov 16,	SYSTEM	\$1,357.00	This adjustment offsets the original system-generated Overrun Payment													

Revision 4/1/2020 Page 24 of 65



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																				
0150	PAVED APPROACH, 8 IN.	Overrun	Overrun		2020			Estimate Item Adjustment (0003) overridding Payment Estimate Exception 59 on the current Payment Estimate.																				
				9	Dec 3, 2020	SYSTEM	(\$1,357.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).																				
				9	Dec 3, 2020	SYSTEM	\$1,357.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 68 on the current Payment Estimate.																				
			Overrun - To	otal			\$0.00																					
	Overrun - Total						\$0.00																					
0150 -				_		0)10==11	\$0.00																					
0160	CONCRETE SIDEWALK, 4 IN.	Material		5	Sep 21, 2020	SYSTEM	(\$23,363.25)																					
					5	Sep 21, 2020	SYSTEM	\$23,363.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user weathc1 overridding Payment Estimate Exception 18 on the current Payment Estimate.																			
					6	Oct 2, 2020	SYSTEM	(\$38,233.50)																				
							6	Oct 2, 2020	SYSTEM	\$38,233.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user weathc1 overridding Payment Estimate Exception 18 on the current Payment Estimate.																	
										7	Nov 3, 2020	SYSTEM	(\$38,233.50)															
							7	Nov 3, 2020	SYSTEM	\$38,233.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user weathc1 overridding Payment Estimate Exception 18 on the current Payment Estimate.																	
					8	Nov 16, 2020	SYSTEM	(\$38,233.50)																				
				8	Nov 16, 2020	SYSTEM	\$38,233.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user weathc1 overridding Payment Estimate Exception 18 on the current Payment Estimate.																				
						9	Dec 3, 2020	SYSTEM	(\$38,233.50)																			
										9	Dec 3, 2020	SYSTEM	\$38,233.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user weathc1 overridding Payment Estimate Exception 20 on the current Payment Estimate.														
					10	Dec 16, 2020	SYSTEM	(\$42,517.50)																				
					10	Dec 16, 2020	SYSTEM	\$42,517.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user weathc1 overridding Payment Estimate Exception 17 on the current Payment Estimate.																			
				11	Jan 4, 2021	SYSTEM	(\$42,517.50)																					
																				11	Jan 4, 2021	SYSTEM	\$42,517.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0055) due to user weathc1 overridding Payment Estimate Exception 17 on the current Payment Estimate.				
																			12	Jan 19, 2021	SYSTEM	(\$42,517.50)						
																		12	Jan 19, 2021	SYSTEM	\$42,517.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0055) due to user weathc1 overridding Payment Estimate Exception 17 on the current Payment Estimate.						
									13	Feb 17, 2021	SYSTEM	(\$42,517.50)																
																									13	Feb 17, 2021	SYSTEM	\$42,517.50
																	14	Mar 2, 2021	SYSTEM	\$42,517.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user weathc1 overridding Payment Estimate Exception 16 on the current Payment Estimate.							
						15	Mar 16, 2021	SYSTEM	(\$42,517.50)																			
																								15	Mar 16, 2021	SYSTEM	\$42,517.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user weathc1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
			- Total				\$0.00																					
	Material - Total						\$0.00																					

Revision 4/1/2020 Page 25 of 65



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																							
)160 -	Total						\$0.00																								
)170	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	Material		4	Sep 1, 2020	SYSTEM	(\$7,986.00)																								
				4	Sep 1, 2020	SYSTEM	\$7,986.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user weathc1 overridding Payment Estimate Exception 19 on the current Payment Estimate.																							
				5	Sep 21, 2020	SYSTEM	(\$13,650.00)																								
					5	Sep 21, 2020	SYSTEM	\$13,650.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user weathc1 overridding Payment Estimate Exception 21 on the current Payment Estimate.																						
						6	Oct 2, 2020	SYSTEM	(\$13,650.00)																						
					6	Oct 2, 2020	SYSTEM	\$13,650.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user weathof overridding Payment Estimate Exception 21 on the current Payment Estimate.																						
							7	Nov 3, 2020	SYSTEM	(\$13,650.00)																					
						7	Nov 3, 2020	SYSTEM	\$13,650.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user weathof overridding Payment Estimate Exception 21 on the current Payment Estimate.																					
									8	Nov 16, 2020	SYSTEM	(\$13,650.00)																			
									8	Nov 16, 2020	SYSTEM	\$13,650.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user weathc1 overridding Payment Estimate Exception 21 on the current Payment Estimate.																		
				9	Dec 3, 2020	SYSTEM	(\$13,650.00)																								
					9	Dec 3, 2020	SYSTEM	\$13,650.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user weathc1 overridding Payment Estimate Exception 21 on the current Payment Estimate.																						
															10	Dec 16, 2020	SYSTEM	(\$13,650.00)													
				10	Dec 16, 2020	SYSTEM	\$13,650.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user weathc1 overridding Payment Estimate Exception 20 on the current Payment Estimate.																							
														11	Jan 4, 2021	SYSTEM	(\$13,650.00)														
				11	Jan 4, 2021	SYSTEM	\$13,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0056) due to user weathc1 overridding Payment Estimate Exception 20 on the current Payment Estimate.																							
																					12	Jan 19, 2021	SYSTEM	(\$13,650.00)							
																											12	Jan 19, 2021	SYSTEM	\$13,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0056) due to user weathc1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
				13	Feb 17, 2021	SYSTEM	(\$13,650.00)																								
				13	Feb 17, 2021	SYSTEM	\$13,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0059) due to user weathc1 overridding Payment Estimate Exception 20 on the current Payment Estimate.																							
												14	Mar 2, 2021	SYSTEM	(\$13,650.00)																
																											14	Mar 2, 2021	SYSTEM	\$13,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user weathc1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
				15	Mar 16, 2021	SYSTEM	\$13,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user weathc1 overridding Payment Estimate Exception 18 on the current Payment Estimate.																							
			- Total				\$0.00																								
	Material - Total						\$0.00																								
	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	Overrun	Overrun	4	Sep 1, 2020	SYSTEM	(\$5,538.00)																								
				4	Sep 1, 2020	SYSTEM	\$5,538.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 45 on the current Payment Estimate.																							

Revision 4/1/2020 Page 26 of 65



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
0170	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	Overrun	Overrun	5	Sep 21, 2020	SYSTEM	(\$5,538.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	
				5	Sep 21, 2020	SYSTEM	(\$5,664.00)		
				5	Sep 21, 2020	SYSTEM	\$5,664.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) overridding Payment Estimate Exception 55 on the current Payment Estimate.	
				5	Sep 21, 2020	SYSTEM	\$5,538.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) overridding Payment Estimate Exception 55 on the current Payment Estimate.	
				6	Oct 2, 2020	SYSTEM	(\$5,664.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	
					6	Oct 2, 2020	SYSTEM	\$5,664.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) overridding Payment Estimate Exception 54 on the current Payment Estimate.
							7	Nov 3, 2020	SYSTEM
				7	Nov 3, 2020	SYSTEM	\$5,664.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 55 on the current Payment Estimate.	
				8	Nov 16, 2020	SYSTEM	(\$5,664.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	
				8	Nov 16, 2020	SYSTEM	\$5,664.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 60 on the current Payment Estimate.	
				9	Dec 3, 2020	SYSTEM	(\$5,664.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	
				9	Dec 3, 2020	SYSTEM	\$5,664.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 69 on the current Payment Estimate.	
			Overrun - T	otal			\$0.00		
	Overrun - Total						\$0.00		
0170 -	- Total						\$0.00		
0180	CONCRETE CURB (OVER 6 IN. HEIGHT) TYPE S	Material		5	Sep 21, 2020	SYSTEM	(\$9,060.00)		
				5	Sep 21, 2020	SYSTEM	\$9,060.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user weathc1 overridding Payment Estimate Exception 24 on the current Payment Estimate.	
				7	Nov 3, 2020	SYSTEM	(\$10,920.00)		
				7	Nov 3, 2020	SYSTEM	\$10,920.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user weathc1 overridding Payment Estimate Exception 24 on the current Payment Estimate.	
			- Total				\$0.00		
	Material - Total						\$0.00		
	CONCRETE CURB (OVER 6 IN. HEIGHT) TYPE S	Overrun	Overrun	5	Sep 21, 2020	SYSTEM	(\$2,670.00)		
				5	Sep 21, 2020	SYSTEM	\$2,670.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) overridding Payment Estimate Exception 56 on the current Payment Estimate.	
			Overrun - T	otal			\$0.00		
	Overrun - Total						\$0.00		
0180	- Total						\$0.00		
0190	CONCRETE GUTTER TYPE B	Material		4	Sep 1, 2020	SYSTEM	(\$2,580.00)		
				4	Sep 1, 2020	SYSTEM	\$2,580.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user weathc1 overridding Payment Estimate Exception 23 on the current Payment Estimate.	
				5	Sep 21, 2020	SYSTEM	(\$2,580.00)		
					5	Sep 21, 2020	SYSTEM	\$2,580.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user weathc1 overridding
								Payment Estimate Exception 27 on the current Payment Estimate.	
				6	Oct 2, 2020	SYSTEM	(\$2,580.00)	Payment Estimate Exception 27 on the current Payment Estimate.	

Revision 4/1/2020 Page 27 of 65



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																						
0190	CONCRETE GUTTER TYPE B	Material			2020			Estimate Item Adjustment (0017) due to user weathc1 overridding Payment Estimate Exception 24 on the current Payment Estimate.																						
				7	Nov 3, 2020	SYSTEM	(\$2,580.00)																							
				7	Nov 3, 2020	SYSTEM	\$2,580.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user weathc1 overridding Payment Estimate Exception 27 on the current Payment Estimate.																						
				8	Nov 16, 2020	SYSTEM	(\$2,580.00)																							
								8	Nov 16, 2020	SYSTEM	\$2,580.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user weathc1 overridding Payment Estimate Exception 24 on the current Payment Estimate.																		
							9	Dec 3, 2020	SYSTEM	(\$2,580.00)																				
				9	Dec 3, 2020	SYSTEM	\$2,580.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user weathc1 overridding Payment Estimate Exception 24 on the current Payment Estimate.																						
						10	Dec 16, 2020	SYSTEM	(\$2,580.00)																					
													10	Dec 16, 2020	SYSTEM	\$2,580.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user weathc1 overridding Payment Estimate Exception 23 on the current Payment Estimate.													
							11	Jan 4, 2021	SYSTEM	(\$2,580.00)																				
				11	Jan 4, 2021	SYSTEM	\$2,580.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user weathc1 overridding Payment Estimate Exception 23 on the current Payment Estimate.																						
				12	Jan 19, 2021	SYSTEM	(\$2,580.00)																							
					12	Jan 19, 2021	SYSTEM	\$2,580.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user weathc1 overridding Payment Estimate Exception 23 on the current Payment Estimate.																					
						13	Feb 17, 2021	SYSTEM	(\$2,580.00)																					
				13	Feb 17, 2021	SYSTEM	\$2,580.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user weathc1 overridding Payment Estimate Exception 23 on the current Payment Estimate.																						
											14					14	Mar 2, 2021	SYSTEM	(\$2,580.00)											
														14	Mar 2, 2021	SYSTEM	\$2,580.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user weathc1 overridding Payment Estimate Exception 20 on the current Payment Estimate.												
																				15	Mar 16, 2021	SYSTEM	(\$2,580.00)							
												15	Mar 16, 2021	SYSTEM	\$2,580.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user weathc1 overridding Payment Estimate Exception 20 on the current Payment Estimate.														
			- Total				\$0.00																							
0.400	Material - Total						\$0.00																							
0190 - 0200	INTEGRAL CURB (6 IN. HEIGHT AND	Material		4	Sep 1,	SYSTEM	\$0.00 (\$2,420.00)																							
	UNDER) TYPE A	A.		A .																						4	2020 Sep 1, 2020	SYSTEM	\$2,420.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user weathc1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
											5	Sep 21, 2020	SYSTEM	(\$3,000.00)	Estimate Energian 20 on the sarrort Laymont Estimate.															
														Ę										5	Sep 21, 2020	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user weatho1 overridding Payment Estimate Exception 30 on the current Payment Estimate.		
																	6	Oct 2, 2020	SYSTEM	(\$4,000.00)										
				6	Oct 2, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user weathc1 overridding Payment Estimate Exception 27 on the current Payment Estimate.																						
						7	Nov 3, 2020	SYSTEM	(\$4,000.00)																					

Revision 4/1/2020 Page 28 of 65



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks													
0200	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	Material		7	Nov 3, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user weathc1 overridding Payment Estimate Exception 30 on the current Payment Estimate.													
				8	Nov 16, 2020	SYSTEM	(\$4,000.00)														
				8	Nov 16, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user weathc1 overridding Payment Estimate Exception 27 on the current Payment Estimate.													
						9	Dec 3, 2020	SYSTEM	(\$4,000.00)												
						9	Dec 3, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user weathc1 overridding Payment Estimate Exception 27 on the current Payment Estimate.											
									10	Dec 16, 2020	SYSTEM	(\$4,000.00)									
										10	Dec 16, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user weathc1 overridding Payment Estimate Exception 26 on the current Payment Estimate.							
					11	Jan 4, 2021	SYSTEM	(\$4,000.00)													
											11	Jan 4, 2021	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user weathc1 overridding Payment Estimate Exception 26 on the current Payment Estimate.						
								12	Jan 19, 2021	SYSTEM	(\$4,000.00)										
				12	Jan 19, 2021	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user weathc1 overridding Payment Estimate Exception 26 on the current Payment Estimate.													
				13	Feb 17, 2021	SYSTEM	(\$4,000.00)														
						13	Feb 17, 2021	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user weathc1 overridding Payment Estimate Exception 26 on the current Payment Estimate.											
						14	Mar 2, 2021	SYSTEM	(\$4,000.00)												
							14	Mar 2, 2021	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user weathc1 overridding Payment Estimate Exception 22 on the current Payment Estimate.										
						15	Mar 16, 2021	SYSTEM	(\$4,000.00)												
				15	Mar 16, 2021	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user weathc1 overridding Payment Estimate Exception 22 on the current Payment Estimate.													
	Material - Total		- Total				\$0.00 \$0.00														
		Overrun	Overrun	6	Oct 2, 2020	SYSTEM	(\$580.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).													
	ONDERN TIPE A			6	Oct 2, 2020	SYSTEM	(\$1,000.00)	commerce of viceous is applied (if notification).													
				6	Oct 2, 2020	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 55 on the current Payment Estimate.													
				6	Oct 2, 2020	SYSTEM	\$580.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 55 on the current Payment Estimate.													
			Overrun - To	otal			\$0.00														
	Overrun - Total						\$0.00														
0200 - 0210	Total  MISC. 2 FT TYPE A CURB & GUTTER	Material		4	Sep 1,	SYSTEM	\$0.00 (\$13,425.60)														
UZ 1U	WINGO. 2111 TITE A GUITE & GUITER	wateridi		4	Sep 1, 2020	SYSTEM	\$13,425.60	This adjustment offsets the original system-generated Overrun Payment													
				т	2020	STOTEM	ψ10,720.00	This adjustine to rest in the original system-generated overriding Estimate Item Adjustment (0019) due to user weathor overridding Payment Estimate Exception 29 on the current Payment Estimate.													
														!	5	5	5	Sep 21, 2020	SYSTEM	(\$13,425.60)	
				5	Sep 21, 2020	SYSTEM	\$13,425.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user weathc1 overridding													

Revision 4/1/2020 Page 29 of 65



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																																	
0210	MISC. 2 FT TYPE A CURB & GUTTER	Material	, ,,					Payment Estimate Exception 35 on the current Payment Estimate.																																	
				6	Oct 2, 2020	SYSTEM	(\$17,073.60)																																		
				6	Oct 2, 2020	SYSTEM	\$17,073.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user weathc1 overridding Payment Estimate Exception 33 on the current Payment Estimate.																																	
									7	Nov 3, 2020	SYSTEM	(\$17,073.60)																													
								7	Nov 3, 2020	SYSTEM	\$17,073.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user weathc1 overridding Payment Estimate Exception 33 on the current Payment Estimate.																													
										8	Nov 16, 2020	SYSTEM	(\$17,073.60)																												
							8	Nov 16, 2020	SYSTEM	\$17,073.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user weathc1 overridding Payment Estimate Exception 33 on the current Payment Estimate.																														
							9	Dec 3, 2020	SYSTEM	(\$17,073.60)																															
					9	Dec 3, 2020	SYSTEM	\$17,073.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user weathc1 overridding Payment Estimate Exception 33 on the current Payment Estimate.																																
											10	Dec 16, 2020	SYSTEM	(\$20,400.00)																											
				10	Dec 16, 2020	SYSTEM	\$20,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user weathc1 overridding Payment Estimate Exception 32 on the current Payment Estimate.																																	
				11	Jan 4, 2021	SYSTEM	(\$20,400.00)																																		
				11	Jan 4, 2021	SYSTEM	\$20,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0057) due to user weathc1 overridding Payment Estimate Exception 32 on the current Payment Estimate.																																	
				12	Jan 19, 2021	SYSTEM	(\$20,400.00)																																		
							12	Jan 19, 2021	SYSTEM	\$20,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0057) due to user weathc1 overridding Payment Estimate Exception 32 on the current Payment Estimate.																														
														13	Feb 17, 2021	SYSTEM	(\$20,400.00)																								
				13	Feb 17, 2021	SYSTEM	\$20,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user weathc1 overridding Payment Estimate Exception 32 on the current Payment Estimate.																																	
																									14	Mar 2, 2021	SYSTEM	(\$20,400.00)													
																																							14	Mar 2, 2021	SYSTEM
																							15	Mar 16, 2021	SYSTEM	(\$20,400.00)															
											15	Mar 16, 2021	SYSTEM	\$20,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user weathc1 overridding Payment Estimate Exception 28 on the current Payment Estimate.																										
			- Total				\$0.00																																		
	Material - Total						\$0.00																																		
0210 -		Mad 11		-	0- 61	OVOTE	\$0.00																																		
0220	MISC. Modified Integral Curb	Material		5	Sep 21, 2020	SYSTEM	(\$4,030.00)	This all the second first the second																																	
																													5	Sep 21, 2020	SYSTEM	\$4,030.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user weathc1 overridding Payment Estimate Exception 33 on the current Payment Estimate.								
																					6	Oct 2, 2020	SYSTEM	(\$23,660.00)																	
																																		6	Oct 2, 2020	SYSTEM	\$23,660.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user weathc1 overridding Payment Estimate Exception 30 on the current Payment Estimate.			
			8																																					8	Nov 16, 2020
																					8	Nov 16,	SYSTEM	\$23,660.00	This adjustment offsets the original system-generated Overrun Payment																

Revision 4/1/2020 Page 30 of 65



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
0220	MISC. Modified Integral Curb	Material			2020			Estimate Item Adjustment (0008) due to user weathc1 overridding Payment Estimate Exception 30 on the current Payment Estimate.				
				9	Dec 3, 2020	SYSTEM	(\$23,660.00)					
				9	Dec 3, 2020	SYSTEM	\$23,660.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user weathc1 overridding Payment Estimate Exception 30 on the current Payment Estimate.				
					10	Dec 16, 2020	SYSTEM	(\$23,660.00)				
					10	Dec 16, 2020	SYSTEM	\$23,660.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user weathc1 overridding Payment Estimate Exception 29 on the current Payment Estimate.			
				11	Jan 4, 2021	SYSTEM	(\$23,660.00)					
						11	Jan 4, 2021	SYSTEM	\$23,660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user weathc1 overridding Payment Estimate Exception 29 on the current Payment Estimate.		
						12	Jan 19, 2021	SYSTEM	(\$23,660.00)			
								12	Jan 19, 2021	SYSTEM	\$23,660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user weathc1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
										13	Feb 17, 2021	SYSTEM
					13	Feb 17, 2021	SYSTEM	\$23,660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user weathc1 overridding Payment Estimate Exception 29 on the current Payment Estimate.			
				14	Mar 2, 2021	SYSTEM	(\$23,660.00)					
				14	Mar 2, 2021	SYSTEM	\$23,660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user weathc1 overridding Payment Estimate Exception 25 on the current Payment Estimate.				
						15	Mar 16, 2021	SYSTEM	(\$23,660.00)			
				15	Mar 16, 2021	SYSTEM	\$23,660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user weathc1 overridding Payment Estimate Exception 25 on the current Payment Estimate.				
			- Total				\$0.00					
	Material - Total  MISC. Modified Integral Curb	Overrun	Overrun	6	Oct 2,	SYSTEM	\$0.00 (\$13,247.00)					
				6	2020 Oct 2, 2020	SYSTEM	\$13,247.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) overridding Payment Estimate Exception 56 on the current Payment Estimate.				
				8	Nov 16, 2020	SYSTEM	(\$13,247.00)	Exception 30 on the current ayment Estimate.				
				8	Nov 16, 2020	SYSTEM	\$13,247.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 61 on the current Payment Estimate.				
				9	Dec 3, 2020	SYSTEM	(\$13,247.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).				
				9	Dec 3, 2020	SYSTEM	\$13,247.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 70 on the current Payment Estimate.				
			Overrun - T	otal			\$0.00					
	Overrun - Total						\$0.00					
<b>0220</b> - 0230	CURVED VANE GRATE AND FRAME	Material		3	Aug 18,	SYSTEM	\$0.00 (\$680.00)					
	(2 FT. X 2 FT. OR 600MM X 600MM)			3	2020 Aug 18,	SYSTEM	\$680.00	This adjustment offsets the original system-generated Overrun Payment				
					2020	21/		Estimate Item Adjustment (0006) due to user weathc1 overridding Payment Estimate Exception 11 on the current Payment Estimate.				
				4	Sep 1, 2020	SYSTEM	(\$680.00)					
				4	Sep 1, 2020	SYSTEM	\$680.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user weathc1 overridding Payment Estimate Exception 32 on the current Payment Estimate.				

Revision 4/1/2020 Page 31 of 65



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks														
0230	CURVED VANE GRATE AND FRAME (2 FT. X 2 FT. OR 600MM X 600MM)	Material		5	Sep 21, 2020	SYSTEM	(\$1,020.00)															
				5	Sep 21, 2020	SYSTEM	\$1,020.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user weathc1 overridding Payment Estimate Exception 38 on the current Payment Estimate.														
				6	Oct 2, 2020	SYSTEM	(\$1,020.00)															
								6	Oct 2, 2020	SYSTEM	\$1,020.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user weathc1 overridding Payment Estimate Exception 36 on the current Payment Estimate.										
													7	Nov 3, 2020	SYSTEM	(\$1,020.00)						
					7	Nov 3, 2020	SYSTEM	\$1,020.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user weathc1 overridding Payment Estimate Exception 36 on the current Payment Estimate.													
												8	Nov 16, 2020	SYSTEM	(\$1,020.00)							
											8	Nov 16, 2020	SYSTEM	\$1,020.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user weathc1 overridding Payment Estimate Exception 36 on the current Payment Estimate.							
											9	Dec 3, 2020	SYSTEM	(\$1,020.00)								
				9	Dec 3, 2020	SYSTEM	\$1,020.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user weathc1 overridding Payment Estimate Exception 36 on the current Payment Estimate.														
			- Total				\$0.00															
	Material - Total						\$0.00															
0230 -	Total	Matarial					\$0.00															
0240	CURVED VANE GRATE AND FRAME (4 FT. X 2 FT. OR 1200MM X 600MM)	Material		3	Aug 18, 2020	SYSTEM	(\$650.00)															
				3	Aug 18, 2020	SYSTEM	\$650.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user weathc1 overridding Payment Estimate Exception 12 on the current Payment Estimate.														
				4	Sep 1, 2020	SYSTEM	(\$650.00)															
				4	Sep 1, 2020	SYSTEM	\$650.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user weathc1 overridding Payment Estimate Exception 33 on the current Payment Estimate.														
														5	Sep 21, 2020	SYSTEM	(\$650.00)					
				5	Sep 21, 2020	SYSTEM	\$650.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user weathc1 overridding Payment Estimate Exception 39 on the current Payment Estimate.														
				6	Oct 2, 2020	SYSTEM	(\$650.00)															
				6	Oct 2, 2020	SYSTEM	\$650.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user weathc1 overridding Payment Estimate Exception 37 on the current Payment Estimate.														
																		7	Nov 3, 2020	SYSTEM	(\$650.00)	
									7	Nov 3, 2020	SYSTEM	\$650.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user weathc1 overridding Payment Estimate Exception 37 on the current Payment Estimate.									
																		8	Nov 16, 2020	SYSTEM	(\$650.00)	
				8	Nov 16, 2020	SYSTEM	\$650.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user weathc1 overridding Payment Estimate Exception 37 on the current Payment Estimate.														
						9	Dec 3, 2020	SYSTEM	(\$650.00)													
				9	Dec 3, 2020	SYSTEM	\$650.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user weathc1 overridding Payment Estimate Exception 37 on the current Payment Estimate.														
			- Total				\$0.00															
	Material - Total						\$0.00															
							\$0.00															

Revision 4/1/2020 Page 32 of 65



Lina	Description	Adiustosont	Other	Fat	Cuantad	Cuantad	Amazumt	Denseyles
Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0260	MISC. BICYCLE FRIENDLY APWA FRAME AND GRATE	Material		3	Aug 18, 2020	SYSTEM	(\$420.00)	
				3	Aug 18, 2020	SYSTEM	\$420.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user weathc1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0260 -	- Total						\$0.00	
0270	CONSTRUCTION SIGNS	Material		1	Jul 20, 2020	SYSTEM	(\$944.00)	
				1	Jul 20, 2020	SYSTEM	\$944.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user weathc1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				2	Aug 4, 2020	SYSTEM	(\$944.00)	
				2	Aug 4, 2020	SYSTEM	\$944.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				3	Aug 18, 2020	SYSTEM	(\$944.00)	
				3	Aug 18, 2020	SYSTEM	\$944.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0270 -	· Total						\$0.00	
0280	ADVANCED WARNING RAIL SYSTEM	Material		1	Jul 20, 2020	SYSTEM	(\$70.00)	
				1	Jul 20, 2020	SYSTEM	\$70.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				2	Aug 4, 2020	SYSTEM	(\$70.00)	
				2	Aug 4, 2020	SYSTEM	\$70.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				3	Aug 18, 2020	SYSTEM	(\$70.00)	
				3	Aug 18, 2020	SYSTEM	\$70.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user weathc1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0280 -	· Total						\$0.00	
0290	FLAG ASSEMBLY	Material		1	Jul 20, 2020	SYSTEM	(\$60.00)	
				1	Jul 20, 2020	SYSTEM	\$60.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user weathc1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				2	Aug 4, 2020	SYSTEM	(\$60.00)	
				2	Aug 4, 2020	SYSTEM	\$60.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user weathc1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				3	Aug 18, 2020	SYSTEM	(\$60.00)	
				3	Aug 18, 2020	SYSTEM	\$60.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user weathc1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
		- Total				\$0.00		
	Material - Total						\$0.00	
0290 -	· Total						\$0.00	
0300	CHANNELIZER (TRIM LINE)	Material		1	Jul 20, 2020	SYSTEM	(\$1,260.00)	

Revision 4/1/2020 Page 33 of 65



	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0300	CHANNELIZER (TRIM LINE)	Material		1	Jul 20, 2020	SYSTEM	\$1,260.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user weathc1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				2	Aug 4, 2020	SYSTEM	(\$2,700.00)	
				2	Aug 4, 2020	SYSTEM	\$2,700.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user weathc1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				3	Aug 18, 2020	SYSTEM	(\$2,700.00)	
				3	Aug 18, 2020	SYSTEM	\$2,700.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user weathc1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0300 -	Total						\$0.00	
0330	FLASHING ARROW PANEL	Material		1	Jul 20, 2020	SYSTEM	(\$1,800.00)	
				1	Jul 20, 2020	SYSTEM	\$1,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				2	Aug 4, 2020	SYSTEM	(\$1,800.00)	
				2	Aug 4, 2020	SYSTEM	\$1,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user weathc1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				3	Aug 18, 2020	SYSTEM	(\$1,800.00)	
				3	Aug 18, 2020	SYSTEM	\$1,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user weathc1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
			- Total				\$0.00	
	Metadal Tatal							
	Material - Total						\$0.00	
0330 -							\$0.00 \$0.00	
<b>0330</b> -	Total  CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION	Material		1	Jul 20, 2020	SYSTEM		
	Total  CHANGEABLE MESSAGE SIGN	Material		1		SYSTEM SYSTEM	\$0.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user weathc1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
	Total  CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR	Material			2020 Jul 20,		<b>\$0.00</b> (\$8,000.00)	Estimate Item Adjustment (0008) due to user weathc1 overridding
	Total  CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR	Material		1	2020 Jul 20, 2020 Aug 4,	SYSTEM	\$0.00 (\$8,000.00) \$8,000.00	Estimate Item Adjustment (0008) due to user weathc1 overridding
	Total  CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR	Material		1	2020 Jul 20, 2020 Aug 4, 2020 Aug 4,	SYSTEM SYSTEM	\$0.00 (\$8,000.00) \$8,000.00 (\$8,000.00)	Estimate Item Adjustment (0008) due to user weathc1 overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user weathc1 overridding
	Total  CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR	Material		2	2020 Jul 20, 2020 Aug 4, 2020 Aug 4, 2020	SYSTEM SYSTEM	\$0.00 (\$8,000.00) \$8,000.00 (\$8,000.00) \$8,000.00	Estimate Item Adjustment (0008) due to user weathc1 overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user weathc1 overridding
	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	Material	- Total	1 2 2 3	2020 Jul 20, 2020 Aug 4, 2020 Aug 4, 2020 Aug 18, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 (\$8,000.00) \$8,000.00 (\$8,000.00) \$8,000.00	Estimate Item Adjustment (0008) due to user weathc1 overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user weathc1 overridding
0340	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	Material	- Total	1 2 2 3	2020 Jul 20, 2020 Aug 4, 2020 Aug 4, 2020 Aug 18, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 (\$8,000.00) \$8,000.00 (\$8,000.00) \$8,000.00 (\$8,000.00)	Estimate Item Adjustment (0008) due to user weathc1 overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user weathc1 overridding
0340 -	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED  Material - Total	Material	- Total	2 2 3 3 3	2020 Jul 20, 2020 Aug 4, 2020 Aug 4, 2020 Aug 18, 2020 Aug 18, 2020	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$8,000.00) \$8,000.00 (\$8,000.00) \$8,000.00 (\$8,000.00) \$0.00	Estimate Item Adjustment (0008) due to user weathc1 overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user weathc1 overridding
0340	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	Material Material	- Total	1 2 2 2 3 3 3 10 10 Miles	2020 Jul 20, 2020 Aug 4, 2020 Aug 4, 2020 Aug 18, 2020 Dec 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$8,000.00) \$8,000.00 (\$8,000.00) \$8,000.00 (\$8,000.00) \$0.00 \$0.00 (\$1,981.00)	Estimate Item Adjustment (0008) due to user weathc1 overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user weathc1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
0340 -	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED  Material - Total Total PREFORMED THERMOPLASTIC		- Total	2 2 3 3 3	2020 Jul 20, 2020 Aug 4, 2020 Aug 4, 2020 Aug 18, 2020 Aug 18, 2020 Dec 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$8,000.00) \$8,000.00 (\$8,000.00) \$8,000.00 (\$8,000.00) \$0.00 \$0.00	Estimate Item Adjustment (0008) due to user weathc1 overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user weathc1 overridding
0340 -	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED  Material - Total Total PREFORMED THERMOPLASTIC		- Total	1 2 2 2 3 3 3 10 10 Miles	2020 Jul 20, 2020 Aug 4, 2020 Aug 4, 2020 Aug 18, 2020  Dec 16, 2020  Dec 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$8,000.00) \$8,000.00 (\$8,000.00) \$8,000.00 (\$8,000.00) \$0.00 \$0.00 (\$1,981.00)	Estimate Item Adjustment (0008) due to user weathc1 overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user weathc1 overridding Payment Estimate Exception 19 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user weathc1 overridding
0340 -	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED  Material - Total Total PREFORMED THERMOPLASTIC		- Total	1 2 2 2 3 3 3 10 10 10 10	2020 Jul 20, 2020 Aug 4, 2020 Aug 4, 2020 Aug 18, 2020  Dec 16, 2020  Jan 4,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$8,000.00) \$8,000.00 (\$8,000.00) \$8,000.00 (\$8,000.00) \$0.00 \$0.00 (\$1,981.00)	Estimate Item Adjustment (0008) due to user weathc1 overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user weathc1 overridding Payment Estimate Exception 19 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user weathc1 overridding
0340 -	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED  Material - Total Total PREFORMED THERMOPLASTIC		- Total	1 2 2 3 3 3 10 10 10 11 11	2020 Jul 20, 2020 Aug 4, 2020 Aug 4, 2020 Aug 18, 2020  Dec 16, 2020  Dec 16, 2020  Jan 4, 2021  Jan 4,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$8,000.00) \$8,000.00 (\$8,000.00) \$8,000.00 (\$8,000.00) \$0.00 \$0.00 (\$1,981.00) (\$1,981.00)	Estimate Item Adjustment (0008) due to user weathc1 overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user weathc1 overridding Payment Estimate Exception 19 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user weathc1 overridding Payment Estimate Exception 35 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user weathc1 overridding

Revision 4/1/2020 Page 34 of 65



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0390	PREFORMED THERMOPLASTIC	Material						Payment Estimate Exception 35 on the current Payment Estimate.
	PAVEMENT MARKING, 24 IN. WHITE			13	Feb 17, 2021	SYSTEM	(\$1,981.00)	
				13	Feb 17, 2021	SYSTEM	\$1,981.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user weathc1 overridding Payment Estimate Exception 35 on the current Payment Estimate.
		- Total				\$0.00		
	Material - Total					\$0.00		
	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Overrun	Overrun	10	Dec 16, 2020	SYSTEM	(\$385.00)	
				10	Dec 16, 2020	SYSTEM	\$385.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 67 on the current Payment Estimate.
				11	Jan 4, 2021	SYSTEM	(\$385.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				11	Jan 4, 2021	SYSTEM	\$385.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 83 on the current Payment Estimate. Material Insufficiency Quantity 141.500; Overrun Quantity Balance 27.50.
				12	Jan 19, 2021	SYSTEM	(\$385.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				12	Jan 19, 2021	SYSTEM	\$385.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 83 on the current Payment Estimate. Material Insufficiency Quantity 141.500; Overrun Quantity Balance 27.50.
				13	Feb 17, 2021	SYSTEM	(\$385.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				13	Feb 17, 2021	SYSTEM	\$385.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 90 on the current Payment Estimate. Material Insufficiency Quantity 141.500; Overrun Quantity Balance 27.50.
				14	Mar 2, 2021	SYSTEM	(\$385.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				14	Mar 2, 2021	SYSTEM	\$385.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user weathc1 overridding Payment Estimate Exception 53 on the current Payment Estimate.
				15	Mar 16, 2021	SYSTEM	(\$385.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				15	Mar 16, 2021	SYSTEM	\$385.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user weathc1 overridding Payment Estimate Exception 49 on the current Payment Estimate.
	Overrun - Total						\$0.00	
	Overrun - Total						\$0.00	
0390 -	Total						\$0.00	
0400	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	Material		11	Jan 4, 2021	SYSTEM	(\$308.00)	
				11	Jan 4, 2021	SYSTEM	\$308.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user weathc1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
				12	Jan 19, 2021	SYSTEM	(\$308.00)	
				12	Jan 19, 2021	SYSTEM	\$308.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user weathc1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
				13	Feb 17, 2021	SYSTEM	(\$308.00)	
				13	Feb 17, 2021	SYSTEM	\$308.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0061) due to user weathc1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
	- Total						\$0.00	
	Material - Total					\$0.00		
0400 -	Total						\$0.00	
0410	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material		10	Dec 16, 2020	SYSTEM	(\$1,980.00)	
	AINOW			10	Dec 16, 2020	SYSTEM	\$1,980.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user weathc1 overridding

Revision 4/1/2020 Page 35 of 65



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0410	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material						Payment Estimate Exception 36 on the current Payment Estimate.
				11	Jan 4, 2021	SYSTEM	(\$1,980.00)	
				11	Jan 4, 2021	SYSTEM	\$1,980.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user weathc1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
				12	Jan 19, 2021	SYSTEM	(\$1,980.00)	
				12	Jan 19, 2021	SYSTEM	\$1,980.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user weathc1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
				13	Feb 17, 2021	SYSTEM	(\$1,980.00)	
				13	Feb 17, 2021	SYSTEM	\$1,980.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user weathc1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0410 -	Total						\$0.00	
0420	PREFORMED THERMOPLASTIC PAVEMENT MARKING,	Material		10	Dec 16, 2020	SYSTEM	(\$430.00)	
	COMBINATION STR/LT/RT			10	Dec 16, 2020	SYSTEM	\$430.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user weathc1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
				11	Jan 4, 2021	SYSTEM	(\$1,290.00)	
				11	Jan 4, 2021	SYSTEM	\$1,290.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
				12	Jan 19, 2021	SYSTEM	(\$1,290.00)	
				12	Jan 19, 2021	SYSTEM	\$1,290.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
				13	Feb 17, 2021	SYSTEM	(\$1,290.00)	
				13	Feb 17, 2021	SYSTEM	\$1,290.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
			- Total			\$0.00		
	Material - Total						\$0.00	
	PREFORMED THERMOPLASTIC PAVEMENT MARKING,	Overrun	Overrun	11	Jan 4, 2021	SYSTEM	(\$860.00)	
	COMBINATION STR/LT/RT			11	Jan 4, 2021	SYSTEM	\$860.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 84 on the current Payment Estimate. Material Insufficiency Quantity 3.000; Overrun Quantity Balance 2.00.
				12	Jan 19, 2021	SYSTEM	(\$860.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				12	Jan 19, 2021	SYSTEM	\$860.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 84 on the current Payment Estimate. Material Insufficiency Quantity 3.000; Overrun Quantity Balance 2.00.
				13	Feb 17, 2021	SYSTEM	(\$860.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				13	Feb 17, 2021	SYSTEM	\$860.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 91 on the current Payment Estimate. Material Insufficiency Quantity 3.000; Overrun Quantity Balance 2.00.
				14	Mar 2, 2021	SYSTEM	(\$860.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				14	Mar 2, 2021	SYSTEM	\$860.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user weathc1 overridding Payment Estimate Exception 54 on the current Payment Estimate.
				15	Mar 16, 2021	SYSTEM	(\$860.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				15	Mar 16,	SYSTEM	\$860.00	This adjustment offsets the original system-generated Overrun Payment

Revision 4/1/2020 Page 36 of 65



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks					
0420	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT	Overrun	Overrun		2021			Estimate Item Adjustment (0002) due to user weathc1 overridding Payment Estimate Exception 50 on the current Payment Estimate.					
			Overrun - To	otal			\$0.00						
	Overrun - Total						\$0.00						
0420 -	Total						\$0.00						
0430	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	Material		10	Dec 16, 2020	SYSTEM	(\$3,080.00)						
	IIIIBBEGGK			10	Dec 16, 2020	SYSTEM	\$3,080.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Exception 38 on the current Payment Estimate.					
				11	Jan 4, 2021	SYSTEM	(\$3,080.00)						
				11	Jan 4, 2021	SYSTEM	\$3,080.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user weathc1 overridding Payment Estimate Exception 39 on the current Payment Estimate.					
				12	Jan 19, 2021	SYSTEM	(\$3,080.00)						
						12	Jan 19, 2021	SYSTEM	\$3,080.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user weathc1 overridding Payment Estimate Exception 39 on the current Payment Estimate.			
				13	Feb 17, 2021	SYSTEM	(\$3,080.00)						
				13	Feb 17, 2021	SYSTEM	\$3,080.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user weathc1 overridding Payment Estimate Exception 39 on the current Payment Estimate.					
			- Total				\$0.00						
	Material - Total						\$0.00						
	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	Overrun	Overrun	10	Dec 16, 2020	SYSTEM	(\$1,120.00)						
	WIDDLOCK			10	Dec 16, 2020	SYSTEM	\$1,120.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 68 on the current Payment Estimate.					
				11	Jan 4, 2021	SYSTEM	(\$1,120.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).					
				11	Jan 4, 2021	SYSTEM	\$1,120.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 85 on the current Payment Estimate. Material Insufficiency Quantity 22.000; Overrun Quantity Balance 8.00.					
				12	Jan 19, 2021	SYSTEM	(\$1,120.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).					
				12	Jan 19, 2021	SYSTEM	\$1,120.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 85 on the current Payment Estimate. Material Insufficiency Quantity 22.000; Overrun Quantity Balance 8.00.					
				13	Feb 17, 2021	SYSTEM	(\$1,120.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).					
									13	Feb 17, 2021	SYSTEM	\$1,120.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 92 on the current Payment Estimate. Material Insufficiency Quantity 22.000; Overrun Quantity Balance 8.00.
				14	Mar 2, 2021	SYSTEM	(\$1,120.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).					
				14	Mar 2, 2021	SYSTEM	\$1,120.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user weathc1 overridding Payment Estimate Exception 55 on the current Payment Estimate.					
				15	Mar 16, 2021	SYSTEM	(\$1,120.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).					
				15	Mar 16, 2021	SYSTEM	\$1,120.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user weathc1 overridding Payment Estimate Exception 51 on the current Payment Estimate.					
			Overrun - To	otal			\$0.00						
	Overrun - Total						\$0.00						
0430 -	Total						\$0.00						
0440	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Overrun	Overrun	11	Jan 4, 2021	SYSTEM	(\$55.44)						

Revision 4/1/2020 Page 37 of 65



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks					
0440	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Overrun	Overrun	11	Jan 4, 2021	SYSTEM	\$55.44	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user weathc1 overridding Payment Estimate Exception 86 on the current Payment Estimate.					
				12	Jan 19, 2021	SYSTEM	(\$55.44)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).					
				12	Jan 19, 2021	SYSTEM	\$55.44	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user weathc1 overridding Payment Estimate Exception 86 on the current Payment Estimate.					
				13	Feb 17, 2021	SYSTEM	(\$55.44)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).					
				13	Feb 17, 2021	SYSTEM	\$55.44	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user weathc1 overridding Payment Estimate Exception 93 on the current Payment Estimate.					
				14	Mar 2, 2021	SYSTEM	(\$55.44)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).					
									14	Mar 2, 2021	SYSTEM	\$55.44	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Exception 56 on the current Payment Estimate.
				15	Mar 16, 2021	SYSTEM	(\$55.44)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).					
				15	Mar 16, 2021	SYSTEM	\$55.44	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Exception 52 on the current Payment Estimate.					
			Overrun - To	otal			\$0.00						
	Overrun - Total						\$0.00						
0440 -	Total						\$0.00						
0450	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT	Overrun	Overrun	11	Jan 4, 2021	SYSTEM	(\$21.24)						
	MARKING PAINT, TYPE L BEADS			11	Jan 4, 2021	SYSTEM	\$21.24	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user weathc1 overridding Payment Estimate Exception 87 on the current Payment Estimate.					
				12	Jan 19, 2021	SYSTEM	(\$21.24)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).					
				12	Jan 19, 2021	SYSTEM	\$21.24	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user weathc1 overridding Payment Estimate Exception 87 on the current Payment Estimate.					
				13	Feb 17, 2021	SYSTEM	(\$21.24)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).					
				13	Feb 17, 2021	SYSTEM	\$21.24	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user weathc1 overridding Payment Estimate Exception 94 on the current Payment Estimate.					
				14	Mar 2, 2021	SYSTEM	(\$21.24)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).					
				14	Mar 2, 2021	SYSTEM	\$21.24	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user weathc1 overridding Payment Estimate Exception 57 on the current Payment Estimate.					
				15	Mar 16, 2021	SYSTEM	(\$21.24)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).					
				15	Mar 16, 2021	SYSTEM	\$21.24	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user weathc1 overridding Payment Estimate Exception 53 on the current Payment Estimate.					
			Overrun - To	otal			\$0.00						
	Overrun - Total						\$0.00						
0450 -							\$0.00						
0470	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Overrun	Overrun		Jan 4, 2021	SYSTEM	(\$23.16)						
	.,			11	Jan 4, 2021	SYSTEM	\$23.16	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 88 on the current Payment Estimate.					
				12	Jan 19, 2021	SYSTEM	(\$23.16)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).					
				12	Jan 19, 2021	SYSTEM	\$23.16	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 88 on the current Payment Estimate.					
				13	Feb 17, 2021	SYSTEM	(\$23.16)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).					

Revision 4/1/2020 Page 38 of 65



Lie	Deserie tiere	A alice to a contract	045	F-4	Cuartest	Cuarted	A ma c	DamI
Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0470	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Overrun	Overrun	13	Feb 17, 2021	SYSTEM	\$23.16	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 95 on the current Payment Estimate.
				14	Mar 2, 2021	SYSTEM	(\$23.16)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				14	Mar 2, 2021	SYSTEM	\$23.16	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user weathc1 overridding Payment Estimate Exception 58 on the current Payment Estimate.
				15	Mar 16, 2021	SYSTEM	(\$23.16)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				15	Mar 16, 2021	SYSTEM	\$23.16	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user weathc1 overridding Payment Estimate Exception 54 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0470 -	Total						\$0.00	
0500	MISC. PREFORMED THERMOPLASTIC BICYCLE	Material		11	Jan 4, 2021	SYSTEM	(\$2,800.00)	
	SYMBOLS			11	Jan 4, 2021	SYSTEM	\$2,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user weathc1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
				12	Jan 19, 2021	SYSTEM	(\$2,800.00)	
				12	Jan 19, 2021	SYSTEM	\$2,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user weathc1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
				13	Feb 17, 2021	SYSTEM	(\$2,800.00)	
				13	Feb 17, 2021	SYSTEM	\$2,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user weathc1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0500 -	Total						\$0.00	
0520	MISC. APWA SINGLE GRATE INLET	Material		3	Aug 18, 2020	SYSTEM	(\$5,200.00)	
				3	Aug 18, 2020	SYSTEM	\$5,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user weathc1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
				4	Sep 1, 2020	SYSTEM	(\$8,450.00)	
				4	Sep 1, 2020	SYSTEM	\$8,450.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user weathc1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
				5	Sep 21, 2020	SYSTEM	(\$8,450.00)	
				5	Sep 21, 2020	SYSTEM	\$8,450.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user weathc1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
			- Total	5		SYSTEM	\$8,450.00 \$0.00	Estimate Item Adjustment (0029) due to user weathc1 overridding
	Material - Total		- Total	5		SYSTEM	\$0.00 \$0.00	Estimate Item Adjustment (0029) due to user weathc1 overridding
0520 -	Total		- Total		2020		\$0.00 \$0.00 \$0.00	Estimate Item Adjustment (0029) due to user weathc1 overridding
<b>0520</b> - 0580		Material	- Total	3	2020 Aug 18, 2020	SYSTEM	\$0.00 \$0.00 \$0.00 (\$1,860.00)	Estimate Item Adjustment (0029) due to user weathc1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
	Total PRECAST CONCRETE DROP INLET	Material	- Total		2020 Aug 18,	SYSTEM	\$0.00 \$0.00 \$0.00 (\$1,860.00) \$1,860.00	Estimate Item Adjustment (0029) due to user weathc1 overridding
	Total PRECAST CONCRETE DROP INLET	Material	- Total	3	Aug 18, 2020 Aug 18,	SYSTEM	\$0.00 \$0.00 \$0.00 (\$1,860.00)	Estimate Item Adjustment (0029) due to user weathc1 overridding Payment Estimate Exception 40 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user weathc1 overridding
	Total PRECAST CONCRETE DROP INLET	Material	- Total	3	Aug 18, 2020 Aug 18, 2020 Sep 1,	SYSTEM	\$0.00 \$0.00 \$0.00 (\$1,860.00) \$1,860.00	Estimate Item Adjustment (0029) due to user weathc1 overridding Payment Estimate Exception 40 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user weathc1 overridding
	Total PRECAST CONCRETE DROP INLET	Material	- Total	3 3 4	Aug 18, 2020 Aug 18, 2020 Sep 1, 2020 Sep 1,	SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 (\$1,860.00) \$1,860.00	Estimate Item Adjustment (0029) due to user weathc1 overridding Payment Estimate Exception 40 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user weathc1 overridding Payment Estimate Exception 21 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user weathc1 overridding

Revision 4/1/2020 Page 39 of 65



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks											
		Туре	Adjustment Type	Number	Date	Ву													
0580	PRECAST CONCRETE DROP INLET 2 FT X 2 FT	Material						Payment Estimate Exception 41 on the current Payment Estimate.											
			- Total				\$0.00												
	Material - Total						\$0.00												
	Total					2)(2==1	\$0.00												
0590	PRECAST CONCRETE DROP INLET 4 FT X 2 FT	Material		3	Aug 18, 2020	SYSTEM	(\$7,020.00)												
				3	Aug 18, 2020	SYSTEM	\$7,020.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user weathc1 overridding Payment Estimate Exception 22 on the current Payment Estimate.											
				4	Sep 1, 2020	SYSTEM	(\$7,020.00)												
				4	Sep 1, 2020	SYSTEM	\$7,020.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user weathc1 overridding Payment Estimate Exception 36 on the current Payment Estimate.											
				5	Sep 21, 2020	SYSTEM	(\$7,020.00)												
				5	Sep 21, 2020	SYSTEM	\$7,020.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user weathc1 overridding Payment Estimate Exception 42 on the current Payment Estimate.											
			- Total				\$0.00	,											
	Material - Total						\$0.00												
0590 -	· Total						\$0.00												
0600	18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	Material		2	Aug 4, 2020	SYSTEM	(\$2,400.00)												
	GROOF AT EARLES END GEGNON	SECTION		2	Aug 4, 2020	SYSTEM	\$2,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user weathc1 overridding Payment Estimate Exception 10 on the current Payment Estimate.											
					3	Aug 18, 2020	SYSTEM	(\$2,400.00)											
				3	Aug 18, 2020	SYSTEM	\$2,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user weathc1 overridding Payment Estimate Exception 23 on the current Payment Estimate.											
			- Total				\$0.00												
	Material - Total						\$0.00												
	·Total						\$0.00												
0610	TURF TYPE TALL FESCUE SODDING	Material		6	Oct 2, 2020	SYSTEM	(\$5,390.00)												
				6	Oct 2, 2020	SYSTEM	\$5,390.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0034) due to user weathc1 overridding Payment Estimate Exception 39 on the current Payment Estimate.											
				7	Nov 3, 2020	SYSTEM	(\$6,601.00)												
				7	Nov 3, 2020	SYSTEM	\$6,601.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user weathc1 overridding Payment Estimate Exception 39 on the current Payment Estimate.											
					8	Nov 16, 2020	SYSTEM	(\$6,601.00)											
																	8	Nov 16, 2020	SYSTEM
			9	Dec 3, 2020	SYSTEM	(\$6,601.00)													
				9	Dec 3, 2020	SYSTEM	\$6,601.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user weathc1 overridding Payment Estimate Exception 39 on the current Payment Estimate.											
				10	Dec 16, 2020	SYSTEM	(\$7,756.00)												
				10	Dec 16, 2020	SYSTEM	\$7,756.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user weathc1 overridding Payment Estimate Exception 39 on the current Payment Estimate.											
				11	Jan 4, 2021	SYSTEM	(\$8,967.00)												
						11	Jan 4, 2021	SYSTEM	\$8,967.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user weathc1 overridding Payment Estimate Exception 41 on the current Payment Estimate.									

Revision 4/1/2020 Page 40 of 65



Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
0610	TURF TYPE TALL FESCUE SODDING	Material	Type	12	Jan 19, 2021	SYSTEM	(\$8,967.00)	
				12	Jan 19, 2021	SYSTEM	\$8,967.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user weathc1 overridding Payment Estimate Exception 41 on the current Payment Estimate.
				13	Feb 17, 2021	SYSTEM	(\$8,967.00)	
				13	Feb 17, 2021	SYSTEM	\$8,967.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0048) due to user weathc1 overridding Payment Estimate Exception 41 on the current Payment Estimate.
				14	Mar 2, 2021	SYSTEM	(\$8,967.00)	
				14	Mar 2, 2021	SYSTEM	\$8,967.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user weatho1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
				15	Mar 16, 2021	SYSTEM	(\$8,967.00)	
				15	Mar 16, 2021	SYSTEM	\$8,967.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user weathc1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0610	Total						\$0.00	
0630	CURB INLET CHECK	Material		1	Jul 20, 2020	SYSTEM	(\$1,173.00)	
				1	Jul 20, 2020	SYSTEM	\$1,173.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user weathc1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				2	Aug 4, 2020	SYSTEM	(\$1,173.00)	
				2	Aug 4, 2020	SYSTEM	\$1,173.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user weathc1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				3	Aug 18, 2020	SYSTEM	(\$1,173.00)	
				3	Aug 18, 2020	SYSTEM	\$1,173.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user weathc1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
				4	Sep 1, 2020	SYSTEM	(\$1,173.00)	
				4	Sep 1, 2020	SYSTEM	\$1,173.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user weathor overridding Payment Estimate Exception 37 on the current Payment Estimate.
				5	Sep 21, 2020	SYSTEM	(\$1,173.00)	
				5	Sep 21, 2020	SYSTEM	\$1,173.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user weathc1 overridding Payment Estimate Exception 43 on the current Payment Estimate.
				6	Oct 2, 2020	SYSTEM	(\$1,173.00)	
				6	Oct 2, 2020	SYSTEM	\$1,173.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0035) due to user weathc1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
				7	Nov 3, 2020	SYSTEM	(\$1,173.00)	
				7	Nov 3, 2020	SYSTEM	\$1,173.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user weathc1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
				8	Nov 16, 2020	SYSTEM	(\$1,173.00)	
				8	Nov 16, 2020	SYSTEM	\$1,173.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user weathc1 overridding Payment Estimate Exception 44 on the current Payment Estimate.
				9	Dec 3, 2020	SYSTEM	(\$1,173.00)	
				9	Dec 3, 2020	SYSTEM	\$1,173.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user weathc1 overridding Payment Estimate Exception 44 on the current Payment Estimate.

Revision 4/1/2020 Page 41 of 65



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0630	CURB INLET CHECK	Material		10	Dec 16, 2020	SYSTEM	(\$1,173.00)	
				10	Dec 16, 2020	SYSTEM	\$1,173.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user weathc1 overridding Payment Estimate Exception 44 on the current Payment Estimate.
				11	Jan 4, 2021	SYSTEM	(\$1,173.00)	
				11	Jan 4, 2021	SYSTEM	\$1,173.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user weathc1 overridding Payment Estimate Exception 46 on the current Payment Estimate.
				12	Jan 19, 2021	SYSTEM	(\$1,173.00)	
				12	Jan 19, 2021	SYSTEM	\$1,173.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user weathc1 overridding Payment Estimate Exception 46 on the current Payment Estimate.
				13	Feb 17, 2021	SYSTEM	(\$1,173.00)	
				13	Feb 17, 2021	SYSTEM	\$1,173.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user weathc1 overridding Payment Estimate Exception 46 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	CURB INLET CHECK	Overrun	Overrun	1	Jul 20, 2020	SYSTEM	(\$138.00)	
				1	Jul 20, 2020	SYSTEM	\$138.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 8 on the current Payment Estimate.
				2	Aug 4, 2020	SYSTEM	(\$138.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				2	Aug 4, 2020	SYSTEM	\$138.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 12 on the current Payment Estimate.
				3	Aug 18, 2020	SYSTEM	(\$138.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				3	Aug 18, 2020	SYSTEM	\$138.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 25 on the current Payment Estimate.
				4	Sep 1, 2020	SYSTEM	(\$138.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				4	Sep 1, 2020	SYSTEM	\$138.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 41 on the current Payment Estimate.
				5	Sep 21, 2020	SYSTEM	(\$138.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				5	Sep 21, 2020	SYSTEM	\$138.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 51 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
	- Total						\$0.00	
0660	SILT FENCE	Material		11	Jan 4, 2021	SYSTEM	(\$24.75)	
				11	Jan 4, 2021	SYSTEM	\$24.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user weathc1 overridding Payment Estimate Exception 47 on the current Payment Estimate.
				12	Jan 19, 2021	SYSTEM	(\$24.75)	
				12	Jan 19, 2021	SYSTEM	\$24.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user weathc1 overridding Payment Estimate Exception 47 on the current Payment Estimate.
				13	Feb 17, 2021	SYSTEM	(\$24.75)	
				13	Feb 17, 2021	SYSTEM	\$24.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user weathc1 overridding Payment Estimate Exception 47 on the current Payment Estimate.
				14	Mar 2, 2021	SYSTEM	(\$24.75)	

Revision 4/1/2020 Page 42 of 65



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0660	SILT FENCE	Material		14	Mar 2, 2021	SYSTEM	\$24.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user weathc1 overridding Payment Estimate Exception 35 on the current Payment Estimate.
				15	Mar 16, 2021	SYSTEM	(\$24.75)	
				15	Mar 16, 2021	SYSTEM	\$24.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user weathc1 overridding Payment Estimate Exception 35 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0660 -	- Total						\$0.00	
0680	SIGNAL HEAD, TYPE 3B	Material		9	Dec 3, 2020	SYSTEM	(\$4,880.00)	
				9	Dec 3, 2020	SYSTEM	\$4,880.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user weathc1 overridding Payment Estimate Exception 45 on the current Payment Estimate.
				10	Dec 16, 2020	SYSTEM	(\$4,880.00)	
				10	Dec 16, 2020	SYSTEM	\$4,880.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user weathc1 overridding Payment Estimate Exception 45 on the current Payment Estimate.
				11	Jan 4, 2021	SYSTEM	(\$8,540.00)	
				11	Jan 4, 2021	SYSTEM	\$8,540.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0064) due to user weathc1 overridding Payment Estimate Exception 48 on the current Payment Estimate.
				12	Jan 19, 2021	SYSTEM	(\$8,540.00)	
				12	Jan 19, 2021	SYSTEM	\$8,540.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0064) due to user weathc1 overridding Payment Estimate Exception 48 on the current Payment Estimate.
				13	Feb 17, 2021	SYSTEM	(\$8,540.00)	
				13	Feb 17, 2021	SYSTEM	\$8,540.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0073) due to user weathc1 overridding Payment Estimate Exception 48 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0680 -	- Total						\$0.00	
0690	SIGNAL HEAD, TYPE 4B	Material		9	Dec 3, 2020	SYSTEM	(\$1,530.00)	
				9	Dec 3, 2020	SYSTEM	\$1,530.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0034) due to user weathc1 overridding Payment Estimate Exception 46 on the current Payment Estimate.
				10	Dec 16, 2020	SYSTEM	(\$1,530.00)	
				10	Dec 16, 2020	SYSTEM	\$1,530.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user weathc1 overridding Payment Estimate Exception 46 on the current Payment Estimate.
				11	Jan 4, 2021	SYSTEM	(\$4,590.00)	
				11	Jan 4, 2021	SYSTEM	\$4,590.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0065) due to user weathc1 overridding Payment Estimate Exception 49 on the current Payment Estimate.
				12	Jan 19, 2021	SYSTEM	(\$4,590.00)	
				12	Jan 19, 2021	SYSTEM	\$4,590.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0065) due to user weathc1 overridding Payment Estimate Exception 49 on the current Payment Estimate.
				13	Feb 17, 2021	SYSTEM	(\$4,590.00)	
				13	Feb 17, 2021	SYSTEM	\$4,590.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0074) due to user weathc1 overridding Payment Estimate Exception 49 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	

Revision 4/1/2020 Page 43 of 65



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
0690 -	Total						\$0.00		
0700	SIGNAL HEAD, TYPE 5B	Material		11	Jan 4, 2021	SYSTEM	(\$1,660.00)		
				11	Jan 4, 2021	SYSTEM	\$1,660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user weathc1 overridding Payment Estimate Exception 50 on the current Payment Estimate.	
				12	Jan 19, 2021	SYSTEM	(\$1,660.00)		
				12	Jan 19, 2021	SYSTEM	\$1,660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user weathc1 overridding Payment Estimate Exception 50 on the current Payment Estimate.	
				13	Feb 17, 2021	SYSTEM	(\$1,660.00)		
				13	Feb 17, 2021	SYSTEM	\$1,660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user weathc1 overridding Payment Estimate Exception 50 on the current Payment Estimate.	
			- Total				\$0.00		
	Material - Total						\$0.00		
0700 -	Total						\$0.00		
0710	SIGNAL HEAD, TYPE 1S, PEDESTRIAN	Material		11	Jan 4, 2021	SYSTEM	(\$6,000.00)		
	LECTRAN				11	Jan 4, 2021	SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user weathc1 overridding Payment Estimate Exception 51 on the current Payment Estimate.
				12	Jan 19, 2021	SYSTEM	(\$6,000.00)		
				12	Jan 19, 2021	SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user weathc1 overridding Payment Estimate Exception 51 on the current Payment Estimate.	
				13	Feb 17, 2021	SYSTEM	(\$6,000.00)		
				13	Feb 17, 2021	SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user weathc1 overridding Payment Estimate Exception 51 on the current Payment Estimate.	
			- Total				\$0.00		
	Material - Total						\$0.00		
0710 -	Total						\$0.00		
0720	SH-FLAT SHEET - SIGNAL SIGN	Material		13	Feb 17, 2021	SYSTEM	(\$868.00)		
				13	Feb 17, 2021	SYSTEM	\$868.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user weathc1 overridding Payment Estimate Exception 52 on the current Payment Estimate.	
				14	Mar 2, 2021	SYSTEM	(\$868.00)		
				14	Mar 2, 2021	SYSTEM	\$868.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user weathc1 overridding Payment Estimate Exception 36 on the current Payment Estimate.	
			- Total				\$0.00		
	Material - Total						\$0.00		
0720 -	Total						\$0.00		
0730	SIGNAL SIGN, MOUNTING HARDWARE	Material		9	Dec 3, 2020	SYSTEM	(\$600.00)		
				9	Dec 3, 2020	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0035) due to user weathc1 overridding Payment Estimate Exception 47 on the current Payment Estimate.	
				10	Dec 16, 2020	SYSTEM	(\$600.00)		
				10	Dec 16, 2020	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user weathc1 overridding Payment Estimate Exception 47 on the current Payment Estimate.	
			11	Jan 4, 2021	SYSTEM	(\$1,200.00)			
				11	Jan 4, 2021	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0066) due to user weathc1 overridding Payment Estimate Exception 52 on the current Payment Estimate.	

Revision 4/1/2020 Page 44 of 65



Line				_					
	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
0730	SIGNAL SIGN, MOUNTING HARDWARE	Material		12	Jan 19, 2021	SYSTEM	(\$1,200.00)		
				12	Jan 19, 2021	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0066) due to user weathc1 overridding Payment Estimate Exception 52 on the current Payment Estimate.	
				13	Feb 17, 2021	SYSTEM	(\$1,200.00)		
				13	Feb 17, 2021	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0075) due to user weathc1 overridding Payment Estimate Exception 53 on the current Payment Estimate.	
			- Total				\$0.00		
	Material - Total						\$0.00		
0730 -	- Total						\$0.00		
0735	LUMINAIRE LED-A, 120 VOLT COMPATIBLE	Material		11	Jan 4, 2021	SYSTEM	(\$1,100.00)		
				11	Jan 4, 2021	SYSTEM	\$1,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user weathc1 overridding Payment Estimate Exception 53 on the current Payment Estimate.	
				12	Jan 19, 2021	SYSTEM	(\$1,100.00)		
				12	Jan 19, 2021	SYSTEM	\$1,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user weathc1 overridding Payment Estimate Exception 53 on the current Payment Estimate.	
					13	Feb 17, 2021	SYSTEM	(\$1,100.00)	
				13	Feb 17, 2021	SYSTEM	\$1,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user weathc1 overridding Payment Estimate Exception 54 on the current Payment Estimate.	
			- Total				\$0.00		
	Material - Total						\$0.00		
0735 -	Total						\$0.00		
0740	POST, SIGNAL 8 FT. OR 2.4 M	Material		11	Jan 4, 2021	SYSTEM	(\$4,200.00)		
				11	Jan 4, 2021	SYSTEM	\$4,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user weathc1 overridding Payment Estimate Exception 54 on the current Payment Estimate.	
				40					
				12	Jan 19, 2021	SYSTEM	(\$4,200.00)		
				12		SYSTEM	(\$4,200.00) \$4,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user weathc1 overridding Payment Estimate Exception 54 on the current Payment Estimate.	
					2021 Jan 19,		, , ,	Estimate Item Adjustment (0044) due to user weathc1 overridding	
				12	2021 Jan 19, 2021 Feb 17,	SYSTEM	\$4,200.00	Estimate Item Adjustment (0044) due to user weathc1 overridding	
				12	2021 Jan 19, 2021 Feb 17, 2021 Feb 17,	SYSTEM	\$4,200.00 (\$4,200.00)	Estimate Item Adjustment (0044) due to user weathc1 overridding Payment Estimate Exception 54 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user weathc1 overridding	
				12 13	2021 Jan 19, 2021 Feb 17, 2021 Feb 17, 2021 Mar 2,	SYSTEM SYSTEM	\$4,200.00 (\$4,200.00) \$4,200.00	Estimate Item Adjustment (0044) due to user weathc1 overridding Payment Estimate Exception 54 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user weathc1 overridding	
				12 13 13	2021  Jan 19, 2021  Feb 17, 2021  Feb 17, 2021  Mar 2, 2021  Mar 2,	SYSTEM SYSTEM SYSTEM	\$4,200.00 (\$4,200.00) \$4,200.00 (\$4,200.00)	Estimate Item Adjustment (0044) due to user weathc1 overridding Payment Estimate Exception 54 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user weathc1 overridding Payment Estimate Exception 55 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user weathc1 overridding	
				12 13 13 14	2021 Jan 19, 2021 Feb 17, 2021 Feb 17, 2021 Mar 2, 2021 Mar 16, 4021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$4,200.00 (\$4,200.00) \$4,200.00 (\$4,200.00) \$4,200.00	Estimate Item Adjustment (0044) due to user weathc1 overridding Payment Estimate Exception 54 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user weathc1 overridding Payment Estimate Exception 55 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user weathc1 overridding	
			- Total	12 13 13 14 14 15	2021 Jan 19, 2021 Feb 17, 2021 Feb 17, 2021 Mar 2, 2021 Mar 16, 2021 Mar 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$4,200.00 (\$4,200.00) \$4,200.00 (\$4,200.00) (\$4,200.00)	Estimate Item Adjustment (0044) due to user weathc1 overridding Payment Estimate Exception 54 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user weathc1 overridding Payment Estimate Exception 55 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user weathc1 overridding Payment Estimate Exception 37 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user weathc1 overridding	
	Material - Total		- Total	12 13 13 14 14 15	2021 Jan 19, 2021 Feb 17, 2021 Feb 17, 2021 Mar 2, 2021 Mar 16, 2021 Mar 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$4,200.00 (\$4,200.00) \$4,200.00 (\$4,200.00) \$4,200.00 (\$4,200.00)	Estimate Item Adjustment (0044) due to user weathc1 overridding Payment Estimate Exception 54 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user weathc1 overridding Payment Estimate Exception 55 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user weathc1 overridding Payment Estimate Exception 37 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user weathc1 overridding	
0740 -	Material - Total		- Total	12 13 13 14 14 15	2021 Jan 19, 2021 Feb 17, 2021 Feb 17, 2021 Mar 2, 2021 Mar 16, 2021 Mar 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$4,200.00 (\$4,200.00) \$4,200.00 (\$4,200.00) \$4,200.00 \$4,200.00	Estimate Item Adjustment (0044) due to user weathc1 overridding Payment Estimate Exception 54 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user weathc1 overridding Payment Estimate Exception 55 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user weathc1 overridding Payment Estimate Exception 37 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user weathc1 overridding	
0740 - 0750		Material	- Total	12 13 13 14 14 15	2021 Jan 19, 2021 Feb 17, 2021 Feb 17, 2021 Mar 2, 2021 Mar 16, 2021 Mar 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$4,200.00 (\$4,200.00) \$4,200.00 (\$4,200.00) \$4,200.00 \$4,200.00 \$0.00	Estimate Item Adjustment (0044) due to user weathc1 overridding Payment Estimate Exception 54 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user weathc1 overridding Payment Estimate Exception 55 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user weathc1 overridding Payment Estimate Exception 37 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user weathc1 overridding	
	Total POST, TYPE BL, LONGEST ARM 55	Material	- Total	12 13 13 14 14 15 15	2021 Jan 19, 2021 Feb 17, 2021 Feb 17, 2021 Mar 2, 2021 Mar 16, 2021 Mar 16, 2021 Dec 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$4,200.00 (\$4,200.00) \$4,200.00 (\$4,200.00) \$4,200.00 (\$4,200.00) \$0.00 \$0.00	Estimate Item Adjustment (0044) due to user weathc1 overridding Payment Estimate Exception 54 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user weathc1 overridding Payment Estimate Exception 55 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user weathc1 overridding Payment Estimate Exception 37 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user weathc1 overridding	

Revision 4/1/2020 Page 45 of 65



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0750	POST, TYPE BL, LONGEST ARM 55 FT.	Material		10	Dec 16, 2020	SYSTEM	\$47,300.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user weathc1 overridding Payment Estimate Exception 48 on the current Payment Estimate.
				11	Jan 4, 2021	SYSTEM	(\$47,300.00)	
				11	Jan 4, 2021	SYSTEM	\$47,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0063) due to user weathc1 overridding Payment Estimate Exception 57 on the current Payment Estimate.
				12	Jan 19, 2021	SYSTEM	(\$47,300.00)	
				12	Jan 19, 2021	SYSTEM	\$47,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0063) due to user weathc1 overridding Payment Estimate Exception 57 on the current Payment Estimate.
				13	Feb 17, 2021	SYSTEM	(\$47,300.00)	
				13	Feb 17, 2021	SYSTEM	\$47,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0072) due to user weathc1 overridding Payment Estimate Exception 58 on the current Payment Estimate.
				14	Mar 2, 2021	SYSTEM	(\$47,300.00)	
				14	Mar 2, 2021	SYSTEM	\$47,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user weathc1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
				15	Mar 16, 2021	SYSTEM	(\$47,300.00)	
				15	Mar 16, 2021	SYSTEM	\$47,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user weathc1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0750 -	- Total						\$0.00	
0760	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	Material		7	Nov 3, 2020	SYSTEM	(\$19,450.00)	
				7	Nov 3, 2020	SYSTEM	\$19,450.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user weathc1 overridding Payment Estimate Exception 41 on the current Payment Estimate.
				8	Nov 16, 2020	SYSTEM	(\$19,450.00)	
				8	Nov 16, 2020	SYSTEM	\$19,450.00	This adjustment effects the evisinal evistors generated Oversus Devisions
					2020		ψ10,100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user weathc1 overridding Payment Estimate Exception 45 on the current Payment Estimate.
				9	Dec 3, 2020	SYSTEM	(\$38,900.00)	Estimate Item Adjustment (0029) due to user weathc1 overridding
				9	Dec 3,	SYSTEM		Estimate Item Adjustment (0029) due to user weathc1 overridding
					Dec 3, 2020		(\$38,900.00)	Estimate Item Adjustment (0029) due to user weathc1 overridding Payment Estimate Exception 45 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user weathc1 overridding
				9	Dec 3, 2020  Dec 3, 2020  Dec 16,	SYSTEM	(\$38,900.00)	Estimate Item Adjustment (0029) due to user weathc1 overridding Payment Estimate Exception 45 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user weathc1 overridding
				9	Dec 3, 2020  Dec 3, 2020  Dec 16, 2020  Dec 16,	SYSTEM SYSTEM	(\$38,900.00) \$38,900.00 (\$19,450.00)	Estimate Item Adjustment (0029) due to user weathc1 overridding Payment Estimate Exception 45 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user weathc1 overridding Payment Estimate Exception 51 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user weathc1 overridding
				9 10 10	Dec 3, 2020 Dec 3, 2020 Dec 16, 2020 Dec 16, 2020 Jan 4,	SYSTEM SYSTEM	(\$38,900.00) \$38,900.00 (\$19,450.00) \$19,450.00	Estimate Item Adjustment (0029) due to user weathc1 overridding Payment Estimate Exception 45 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user weathc1 overridding Payment Estimate Exception 51 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user weathc1 overridding
				9 10 10 11	Dec 3, 2020  Dec 3, 2020  Dec 16, 2020  Jan 4, 2021  Jan 4,	SYSTEM SYSTEM SYSTEM	(\$38,900.00) \$38,900.00 (\$19,450.00) \$19,450.00	Estimate Item Adjustment (0029) due to user weathc1 overridding Payment Estimate Exception 45 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user weathc1 overridding Payment Estimate Exception 51 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user weathc1 overridding Payment Estimate Exception 51 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user weathc1 overridding
				9 10 10 11 11 11	Dec 3, 2020  Dec 3, 2020  Dec 16, 2020  Dec 16, 2020  Jan 4, 2021  Jan 4, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$38,900.00) \$38,900.00 (\$19,450.00) \$19,450.00 (\$19,450.00)	Estimate Item Adjustment (0029) due to user weathc1 overridding Payment Estimate Exception 45 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user weathc1 overridding Payment Estimate Exception 51 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user weathc1 overridding Payment Estimate Exception 51 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user weathc1 overridding
				9 10 10 11 11 11 12	Dec 3, 2020  Dec 3, 2020  Dec 16, 2020  Jan 4, 2021  Jan 19, 2021  Jan 19, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$38,900.00) \$38,900.00 (\$19,450.00) \$19,450.00 (\$19,450.00) (\$19,450.00)	Estimate Item Adjustment (0029) due to user weathc1 overridding Payment Estimate Exception 45 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user weathc1 overridding Payment Estimate Exception 51 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user weathc1 overridding Payment Estimate Exception 51 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user weathc1 overridding Payment Estimate Exception 60 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user weathc1 overridding
				9 10 10 11 11 11 12 12 12	Dec 3, 2020  Dec 16, 2020  Dec 16, 2020  Jan 4, 2021  Jan 19, 2021  Jan 19, 2021  Feb 17,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$38,900.00) \$38,900.00 (\$19,450.00) \$19,450.00 (\$19,450.00) \$19,450.00 (\$19,450.00)	Estimate Item Adjustment (0029) due to user weathc1 overridding Payment Estimate Exception 45 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user weathc1 overridding Payment Estimate Exception 51 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user weathc1 overridding Payment Estimate Exception 51 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user weathc1 overridding Payment Estimate Exception 60 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user weathc1 overridding

Revision 4/1/2020 Page 46 of 65



ine	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks															
760	Material - Total						\$0.00																
	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	Overrun	Overrun	9	Dec 3, 2020	SYSTEM	(\$19,450.00)																
				9	Dec 3, 2020	SYSTEM	\$19,450.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) overridding Payment Estimate Exception 72 on the current Payment Estimate.															
			Overrun - T	otal			\$0.00																
	Overrun - Total						\$0.00																
760 -	Total						\$0.00																
770	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	Material		5	Sep 21, 2020	SYSTEM	(\$1,700.00)																
				5	Sep 21, 2020	SYSTEM	\$1,700.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user weathc1 overridding Payment Estimate Exception 44 on the current Payment Estimate.															
				6	Oct 2, 2020	SYSTEM	(\$3,800.00)																
				6	Oct 2, 2020	SYSTEM	\$3,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user weathc1 overridding Payment Estimate Exception 41 on the current Payment Estimate.															
					7	Nov 3, 2020	SYSTEM	(\$3,800.00)															
						7	Nov 3, 2020	SYSTEM	\$3,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user weathc1 overridding Payment Estimate Exception 42 on the current Payment Estimate.													
						8	Nov 16, 2020	SYSTEM	(\$3,800.00)														
				8	Nov 16, 2020	SYSTEM	\$3,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user weathc1 overridding Payment Estimate Exception 46 on the current Payment Estimate.															
									9	Dec 3, 2020	SYSTEM	(\$3,800.00)											
					9	Dec 3, 2020	SYSTEM	\$3,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user weathc1 overridding Payment Estimate Exception 52 on the current Payment Estimate.														
				10	Dec 16, 2020	SYSTEM	(\$3,800.00)																
						10	Dec 16, 2020	SYSTEM	\$3,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user weathc1 overridding Payment Estimate Exception 52 on the current Payment Estimate.													
									11	Jan 4, 2021	SYSTEM	(\$3,800.00)											
									11	Jan 4, 2021	SYSTEM	\$3,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user weathc1 overridding Payment Estimate Exception 61 on the current Payment Estimate.										
				12	Jan 19, 2021	SYSTEM	(\$3,800.00)																
																12	Jan 19, 2021	SYSTEM	\$3,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user weathc1 overridding Payment Estimate Exception 61 on the current Payment Estimate.			
																	13	Feb 17, 2021	SYSTEM	(\$3,800.00)			
																			13	Feb 17, 2021	SYSTEM	\$3,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user weathc1 overridding Payment Estimate Exception 62 on the current Payment Estimate.
																					14	Mar 2, 2021	SYSTEM
				1	1	1	1:	14	Mar 2, 2021	SYSTEM	\$3,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user weatho1 overridding Payment Estimate Exception 41 on the current Payment Estimate.											
																			15	Mar 16, 2021	SYSTEM	(\$3,800.00)	
												15	Mar 16, 2021	SYSTEM	\$3,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user weathc1 overridding Payment Estimate Exception 40 on the current Payment Estimate.							
			- Total				\$0.00																
	Material - Total						\$0.00																

Revision 4/1/2020 Page 47 of 65



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
0770	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	Overrun	Overrun	6	Oct 2, 2020	SYSTEM	(\$600.00)					
				6	Oct 2, 2020	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) overridding Payment Estimate Exception 58 on the current Payment Estimate.				
				7	Nov 3, 2020	SYSTEM	(\$600.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).				
				7	Nov 3, 2020	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) overridding Payment Estimate Exception 57 on the current Payment Estimate.				
				8	Nov 16, 2020	SYSTEM	(\$600.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).				
				8	Nov 16, 2020	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) overridding Payment Estimate Exception 63 on the current Payment Estimate.				
					9	Dec 3, 2020	SYSTEM	(\$600.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).			
				9	Dec 3, 2020	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) overridding Payment Estimate Exception 73 on the current Payment Estimate.				
				10	Dec 16, 2020	SYSTEM	(\$600.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).				
				10	Dec 16, 2020	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 69 on the current Payment Estimate.				
				11	Jan 4, 2021	SYSTEM	(\$600.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).				
				11	Jan 4, 2021	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) overridding Payment Estimate Exception 89 on the current Payment Estimate. Material Insufficiency Quantity 190.000; Overrun Quantity Balance 30.00.				
								12	Jan 19, 2021	SYSTEM	(\$600.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					12	Jan 19, 2021	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) overridding Payment Estimate Exception 89 on the current Payment Estimate. Material Insufficiency Quantity 190.000; Overrun Quantity Balance 30.00.			
									13	Feb 17, 2021	SYSTEM	(\$600.00)
				13	Feb 17, 2021	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) overridding Payment Estimate Exception 96 on the current Payment Estimate. Material Insufficiency Quantity 190.000; Overrun Quantity Balance 30.00.				
									14	Mar 2, 2021	SYSTEM	(\$600.00)
				14	Mar 2, 2021	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 59 on the current Payment Estimate. Material Insufficiency Quantity 190.000; Overrun Quantity Balance 30.00.				
				15	Mar 16, 2021	SYSTEM	(\$600.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).				
				15	Mar 16, 2021	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 55 on the current Payment Estimate. Material Insufficiency Quantity 190.000; Overrun Quantity Balance 30.00.				
			Overrun - T	otal			\$0.00					
	Overrun - Total						\$0.00					
0770 -						0)/==	\$0.00					
0780	CONDUIT, 4 IN., TRENCH WITH TRACER WIRE	Material		6	Oct 2, 2020	SYSTEM	(\$1,276.00)	-				
				6	Oct 2, 2020	SYSTEM	\$1,276.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0036) due to user weathc1 overridding Payment Estimate Exception 42 on the current Payment Estimate.				
				7	Nov 3, 2020	SYSTEM	(\$1,276.00)					
				7	Nov 3, 2020	SYSTEM	\$1,276.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user weathc1 overridding Payment Estimate Exception 43 on the current Payment Estimate.				
				8	Nov 16,	SYSTEM	(\$1,276.00)					

Revision 4/1/2020 Page 48 of 65



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																												
0780	CONDUIT, 4 IN., TRENCH WITH	Material			2020																															
	TRACER WIRE			8	Nov 16, 2020	SYSTEM	\$1,276.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user weathc1 overridding Payment Estimate Exception 47 on the current Payment Estimate.																												
				9	Dec 3, 2020	SYSTEM	(\$1,276.00)																													
							9	Dec 3, 2020	SYSTEM	\$1,276.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0037) due to user weathc1 overridding Payment Estimate Exception 53 on the current Payment Estimate.																									
				10	Dec 16, 2020	SYSTEM	(\$1,276.00)																													
				10	Dec 16, 2020	SYSTEM	\$1,276.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user weathc1 overridding Payment Estimate Exception 53 on the current Payment Estimate.																												
				11	Jan 4, 2021	SYSTEM	(\$1,276.00)																													
				11	Jan 4, 2021	SYSTEM	\$1,276.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user weathc1 overridding Payment Estimate Exception 62 on the current Payment Estimate.																												
				12	Jan 19, 2021	SYSTEM	(\$1,276.00)																													
				12	Jan 19, 2021	SYSTEM	\$1,276.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user weathc1 overridding Payment Estimate Exception 62 on the current Payment Estimate.																												
				13	Feb 17, 2021	SYSTEM	(\$1,276.00)																													
				13	Feb 17, 2021	SYSTEM	\$1,276.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user weathc1 overridding Payment Estimate Exception 63 on the current Payment Estimate.																												
						14	Mar 2, 2021	SYSTEM	(\$1,276.00)																											
				14	Mar 2, 2021	SYSTEM	\$1,276.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user weathc1 overridding Payment Estimate Exception 42 on the current Payment Estimate.																												
				15	Mar 16, 2021	SYSTEM	(\$1,276.00)																													
				15	Mar 16, 2021	SYSTEM	\$1,276.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user weathc1 overridding Payment Estimate Exception 41 on the current Payment Estimate.																												
			- Total				\$0.00																													
	Material - Total						\$0.00																													
<b>0780</b> - 0790	CONDUIT, 3 IN., PUSHED WITH	Material		5	Sep 21,	SYSTEM	\$0.00 (\$46,260.00)																													
	TRACER WIRE			5	2020 Sep 21, 2020	SYSTEM	\$46,260.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user weathc1 overridding Payment Estimate Exception 45 on the current Payment Estimate.																												
				6	Oct 2, 2020	SYSTEM	(\$11,520.00)																													
																	6	Oct 2, 2020	SYSTEM	\$11,520.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user weathor overridding Payment Estimate Exception 43 on the current Payment Estimate.															
																																	7	Nov 3, 2020	SYSTEM	(\$11,520.00)
																																	7	Nov 3, 2020	SYSTEM	\$11,520.00
				8	Nov 16, 2020	SYSTEM	(\$11,520.00)																													
			9								8	Nov 16, 2020	SYSTEM	\$11,520.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user weathc1 overridding Payment Estimate Exception 48 on the current Payment Estimate.																					
															!			5	9					9	Dec 3, 2020	SYSTEM	(\$11,520.00)									
				9	Dec 3, 2020	SYSTEM	\$11,520.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user weathc1 overridding Payment Estimate Exception 54 on the current Payment Estimate.																												

Revision 4/1/2020 Page 49 of 65



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																		
0790	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	Material	.,,,,,	10	Dec 16, 2020	SYSTEM	(\$11,520.00)																			
				10	Dec 16, 2020	SYSTEM	\$11,520.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user weathc1 overridding Payment Estimate Exception 54 on the current Payment Estimate.																		
				11	Jan 4, 2021	SYSTEM	(\$11,520.00)																			
				11	Jan 4, 2021	SYSTEM	\$11,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user weathc1 overridding Payment Estimate Exception 63 on the current Payment Estimate.																		
				12	Jan 19, 2021	SYSTEM	(\$11,520.00)																			
				12	Jan 19, 2021	SYSTEM	\$11,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user weathc1 overridding Payment Estimate Exception 63 on the current Payment Estimate.																		
				13	Feb 17, 2021	SYSTEM	(\$11,520.00)																			
				13	Feb 17, 2021	SYSTEM	\$11,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user weathc1 overridding Payment Estimate Exception 64 on the current Payment Estimate.																		
				14	Mar 2, 2021	SYSTEM	(\$11,520.00)																			
										14	Mar 2, 2021	SYSTEM	\$11,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user weathc1 overridding Payment Estimate Exception 43 on the current Payment Estimate.												
						15	Mar 16, 2021	SYSTEM	(\$11,520.00)																	
				15	Mar 16, 2021	SYSTEM	\$11,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user weathc1 overridding Payment Estimate Exception 42 on the current Payment Estimate.																		
			- Total				\$0.00																			
	Material - Total						\$0.00																			
	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	Overrun	Overrun	5	Sep 21, 2020	SYSTEM	(\$39,600.00)																			
				5	Sep 21, 2020	SYSTEM	\$39,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) overridding Payment Estimate Exception 57 on the current Payment Estimate.																		
				6	Oct 2, 2020	SYSTEM	(\$4,860.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).																		
				6	Oct 2, 2020	SYSTEM	\$4,860.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) overridding Payment Estimate Exception 59 on the current Payment Estimate.																		
				7	Nov 3, 2020	SYSTEM	(\$4,860.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).																		
														7	Nov 3, 2020	SYSTEM	\$4,860.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) overridding Payment Estimate Exception 58 on the current Payment Estimate.								
																						8	Nov 16, 2020	SYSTEM	(\$4,860.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
																		8	Nov 16, 2020	SYSTEM	\$4,860.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) overridding Payment Estimate Exception 64 on the current Payment Estimate.				
															9	Dec 3, 2020	SYSTEM	(\$4,860.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).							
																								9	Dec 3, 2020	SYSTEM
				10	Dec 16, 2020	SYSTEM	(\$4,860.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).																		
																	10	Dec 16, 2020	SYSTEM	\$4,860.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 70 on the current Payment Estimate.					
										11	Jan 4, 2021	SYSTEM	(\$4,860.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).												
					11	Jan 4, 2021	SYSTEM	\$4,860.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) overridding Payment Estimate Exception 90 on the current Payment Estimate. Material Insufficiency																	

Revision 4/1/2020 Page 50 of 65



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0790	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	Overrun	Overrun	12	Jan 19, 2021	SYSTEM	(\$4,860.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				12	Jan 19, 2021	SYSTEM	\$4,860.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) overridding Payment Estimate Exception 90 on the current Payment Estimate. Material Insufficiency Quantity 320.000; Overrun Quantity Balance 135.00.
				13	Feb 17, 2021	SYSTEM	(\$4,860.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				13	Feb 17, 2021	SYSTEM	\$4,860.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) overridding Payment Estimate Exception 97 on the current Payment Estimate. Material Insufficiency Quantity 320.000; Overrun Quantity Balance 135.00.
				14	Mar 2, 2021	SYSTEM	(\$4,860.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				14	Mar 2, 2021	SYSTEM	\$4,860.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 60 on the current Payment Estimate. Material Insufficiency Quantity 320.000; Overrun Quantity Balance 135.00.
				15	Mar 16, 2021	SYSTEM	(\$4,860.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				15	Mar 16, 2021	SYSTEM	\$4,860.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 56 on the current Payment Estimate. Material Insufficiency Quantity 320.000; Overrun Quantity Balance 135.00.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0790 -	- Total						\$0.00	
0800	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	Material		11	Jan 4, 2021	SYSTEM	(\$199.20)	
				11	Jan 4, 2021	SYSTEM	\$199.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0049) due to user weathc1 overridding Payment Estimate Exception 64 on the current Payment Estimate.
				12	Jan 19, 2021	SYSTEM	(\$199.20)	
				12	Jan 19, 2021	SYSTEM	\$199.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0049) due to user weathc1 overridding Payment Estimate Exception 64 on the current Payment Estimate.
				13	Feb 17, 2021	SYSTEM	(\$199.20)	
				13	Feb 17, 2021	SYSTEM	\$199.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0052) due to user weathc1 overridding Payment Estimate Exception 65 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0800 -	- Total						\$0.00	
0810	CABLE, 8 AWG 1 CONDUCTOR, POWER	Material		11	Jan 4, 2021	SYSTEM	(\$1,044.00)	
				11	Jan 4, 2021	SYSTEM	\$1,044.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user weathc1 overridding Payment Estimate Exception 65 on the current Payment Estimate.
				12	Jan 19, 2021	SYSTEM	(\$1,044.00)	
				12	Jan 19, 2021	SYSTEM	\$1,044.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user weathc1 overridding Payment Estimate Exception 65 on the current Payment Estimate.
				13	Feb 17, 2021	SYSTEM	(\$1,044.00)	
				13	Feb 17, 2021	SYSTEM	\$1,044.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user weathc1 overridding Payment Estimate Exception 66 on the current Payment Estimate.
		- Total				\$0.00		
	Material - Total					\$0.00		
	CABLE, 8 AWG 1 CONDUCTOR, POWER	Overrun	Overrun	11	Jan 4, 2021	SYSTEM	(\$826.50)	
				11	Jan 4, 2021	SYSTEM	\$826.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) overridding Payment Estimate Exception 91 on the current Payment Estimate. Material Insufficiency

Revision 4/1/2020 Page 51 of 65



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
LITIC	Dosonphon	Type	Adjustment Type	Number	Date	By	Amount	Nordal No
0810	CABLE, 8 AWG 1 CONDUCTOR,	Overrun	Overrun					Quantity 720.000; Overrun Quantity Balance 570.00.
	POWER			12	Jan 19, 2021	SYSTEM	(\$826.50)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				12	Jan 19, 2021	SYSTEM	\$826.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) overridding Payment Estimate Exception 91 on the current Payment Estimate. Material Insufficiency Quantity 720.000; Overrun Quantity Balance 570.00.
				13	Feb 17, 2021	SYSTEM	(\$826.50)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				13	Feb 17, 2021	SYSTEM	\$826.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) overridding Payment Estimate Exception 98 on the current Payment Estimate. Material Insufficiency Quantity 720.000; Overrun Quantity Balance 570.00.
				14	Mar 2, 2021	SYSTEM	(\$826.50)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				14	Mar 2, 2021	SYSTEM	\$826.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user weathc1 overridding Payment Estimate Exception 61 on the current Payment Estimate.
				15	Mar 16, 2021	SYSTEM	(\$826.50)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				15	Mar 16, 2021	SYSTEM	\$826.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user weathc1 overridding Payment Estimate Exception 57 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0810 -	- Total						\$0.00	
0820	CABLE, 12 AWG 2 CONDUCTOR	Material		11	Jan 4, 2021	SYSTEM	(\$990.00)	
				11	Jan 4, 2021	SYSTEM	\$990.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user weathc1 overridding Payment Estimate Exception 66 on the current Payment Estimate.
				12	Jan 19, 2021	SYSTEM	(\$990.00)	
				12	Jan 19, 2021	SYSTEM	\$990.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user weathc1 overridding Payment Estimate Exception 66 on the current Payment Estimate.
				13	Feb 17, 2021	SYSTEM	(\$990.00)	
				13	Feb 17, 2021	SYSTEM	\$990.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user weathc1 overridding Payment Estimate Exception 67 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0820 -	- Total						\$0.00	
0830	CABLE, 16 AWG 2 CONDUCTOR	Material		11	Jan 4, 2021	SYSTEM	(\$1,440.00)	
				11	Jan 4, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user weathc1 overridding Payment Estimate Exception 67 on the current Payment Estimate.
				12	Jan 19, 2021	SYSTEM	(\$1,440.00)	
				12	Jan 19, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user weathc1 overridding Payment Estimate Exception 67 on the current Payment Estimate.
				13	Feb 17, 2021	SYSTEM	(\$1,440.00)	
				13	Feb 17, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user weathc1 overridding Payment Estimate Exception 68 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	CABLE, 16 AWG 2 CONDUCTOR	Overrun	Overrun	11	Jan 4, 2021	SYSTEM	(\$240.00)	
				11	Jan 4, 2021	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) overridding Payment Estimate Exception 92 on the current Payment Estimate. Material Insufficiency

Revision 4/1/2020 Page 52 of 65



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks						
0830	CABLE, 16 AWG 2 CONDUCTOR	Overrun	Overrun					Quantity 900.000; Overrun Quantity Balance 150.00.						
				12	Jan 19, 2021	SYSTEM	(\$240.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).						
				12	Jan 19, 2021	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) overridding Payment Estimate Exception 92 on the current Payment Estimate. Material Insufficiency Quantity 900.000; Overrun Quantity Balance 150.00.						
				13	Feb 17, 2021	SYSTEM	(\$240.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).						
				13	Feb 17, 2021	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) overridding Payment Estimate Exception 99 on the current Payment Estimate. Material Insufficiency Quantity 900.000; Overrun Quantity Balance 150.00.						
				14	Mar 2, 2021	SYSTEM	(\$240.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).						
				14	Mar 2, 2021	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user weathc1 overridding Payment Estimate Exception 62 on the current Payment Estimate.						
				15	Mar 16, 2021	SYSTEM	(\$240.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).						
				15	Mar 16, 2021	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user weathc1 overridding Payment Estimate Exception 58 on the current Payment Estimate.						
			Overrun - T	otal			\$0.00							
	Overrun - Total						\$0.00							
0830	- Total						\$0.00							
0840	CABLE, 16 AWG 5 CONDUCTOR	Material		11	Jan 4, 2021	SYSTEM	(\$2,500.00)							
				11	Jan 4, 2021	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user weathc1 overridding Payment Estimate Exception 68 on the current Payment Estimate.						
				12	Jan 19, 2021	SYSTEM	(\$2,500.00)							
				12	Jan 19, 2021	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user weathc1 overridding Payment Estimate Exception 68 on the current Payment Estimate.						
				13	Feb 17, 2021	SYSTEM	(\$2,500.00)							
				13	Feb 17, 2021	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user weathc1 overridding Payment Estimate Exception 69 on the current Payment Estimate.						
			- Total				\$0.00							
	Material - Total						\$0.00							
	CABLE, 16 AWG 5 CONDUCTOR	Overrun	Overrun	11	Jan 4, 2021	SYSTEM	(\$600.00)							
										11	Jan 4, 2021	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) overridding Payment Estimate Exception 93 on the current Payment Estimate. Material Insufficiency Quantity 1000.000; Overrun Quantity Balance 240.00.
				12	Jan 19, 2021	SYSTEM	(\$600.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).						
				12	Jan 19, 2021	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) overridding Payment Estimate Exception 93 on the current Payment Estimate. Material Insufficiency Quantity 1000.000; Overrun Quantity Balance 240.00.						
				13	Feb 17, 2021	SYSTEM	(\$600.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).						
				13	Feb 17, 2021	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) overridding Payment Estimate Exception 100 on the current Payment Estimate. Material Insufficiency Quantity 1000.000; Overrun Quantity Balance 240.00.						
				14	Mar 2, 2021	SYSTEM	(\$600.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).						
				1	14	14	Mar 2, 2021	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user weathc1 overridding Payment Estimate Exception 50 on the current Payment Estimate.				
				15	Mar 16, 2021	SYSTEM	(\$600.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).						

Revision 4/1/2020 Page 53 of 65



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0840	CABLE, 16 AWG 5 CONDUCTOR	Overrun	Overrun	15	Mar 16, 2021	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user weathc1 overridding Payment Estimate Exception 59 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0840 -	- Total						\$0.00	
0850	CABLE, 16 AWG 7 CONDUCTOR	Material		9	Dec 3, 2020	SYSTEM	(\$986.00)	
				9	Dec 3, 2020	SYSTEM	\$986.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0038) due to user weathc1 overridding Payment Estimate Exception 55 on the current Payment Estimate.
				10	Dec 16, 2020	SYSTEM	(\$986.00)	
				10	Dec 16, 2020	SYSTEM	\$986.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0034) due to user weathc1 overridding Payment Estimate Exception 55 on the current Payment Estimate.
				11	Jan 4, 2021	SYSTEM	(\$7,250.00)	
				11	Jan 4, 2021	SYSTEM	\$7,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user weathc1 overridding Payment Estimate Exception 69 on the current Payment Estimate.
				12	Jan 19, 2021	SYSTEM	(\$7,250.00)	
				12	Jan 19, 2021	SYSTEM	\$7,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user weathc1 overridding Payment Estimate Exception 69 on the current Payment Estimate.
				13	Feb 17, 2021	SYSTEM	(\$7,250.00)	
				13	Feb 17, 2021	SYSTEM	\$7,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user weathc1 overridding Payment Estimate Exception 70 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	CABLE, 16 AWG 7 CONDUCTOR	Overrun	Overrun	11	Jan 4, 2021	SYSTEM	(\$1,421.00)	
				11	Jan 4, 2021	SYSTEM	\$1,421.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) overridding Payment Estimate Exception 94 on the current Payment Estimate. Material Insufficiency Quantity 2500.000; Overrun Quantity Balance 490.00.
				12	Jan 19, 2021	SYSTEM	(\$1,421.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				12	Jan 19, 2021	SYSTEM	\$1,421.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) overridding Payment Estimate Exception 94 on the current Payment Estimate. Material Insufficiency Quantity 2500.000; Overrun Quantity Balance 490.00.
				13	Feb 17, 2021	SYSTEM	(\$1,421.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				13	Feb 17, 2021	SYSTEM	\$1,421.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) overridding Payment Estimate Exception 101 on the current Payment Estimate. Material Insufficiency Quantity 2500.000; Overrun Quantity Balance 490.00.
				14	Mar 2, 2021	SYSTEM	(\$1,421.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				14		SYSTEM SYSTEM	(\$1,421.00) \$1,421.00	
					2021 Mar 2,		, , ,	estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user weathc1 overridding
				14	2021 Mar 2, 2021 Mar 16,	SYSTEM	\$1,421.00	estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user weathc1 overridding Payment Estimate Exception 51 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment
			Overrun - To	14 15 15	2021 Mar 2, 2021 Mar 16, 2021 Mar 16,	SYSTEM SYSTEM	\$1,421.00 (\$1,421.00)	estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user weatho1 overridding Payment Estimate Exception 51 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user weatho1 overridding
	Overrun - Total		Overrun - To	14 15 15	2021 Mar 2, 2021 Mar 16, 2021 Mar 16,	SYSTEM SYSTEM	\$1,421.00 (\$1,421.00) \$1,421.00 \$0.00	estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user weatho1 overridding Payment Estimate Exception 51 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user weatho1 overridding
0850 -	Overrun - Total  Total  POWER SUPPLY ASSEMBLY.		Overrun - T	14 15 15	2021 Mar 2, 2021 Mar 16, 2021 Mar 16,	SYSTEM SYSTEM	\$1,421.00 (\$1,421.00) \$1,421.00	estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user weatho1 overridding Payment Estimate Exception 51 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user weatho1 overridding

Revision 4/1/2020 Page 54 of 65



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0860	POWER SUPPLY ASSEMBLY, TYPE-2 WITH 120V LIGHTING CONTROL CABINET	Material		7	Nov 3, 2020	SYSTEM	\$7,250.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user weathc1 overridding Payment Estimate Exception 45 on the current Payment Estimate.
				8	Nov 16, 2020	SYSTEM	(\$7,250.00)	
				8	Nov 16, 2020	SYSTEM	\$7,250.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user weathc1 overridding Payment Estimate Exception 49 on the current Payment Estimate.
				9	Dec 3, 2020	SYSTEM	(\$14,500.00)	
				9	Dec 3, 2020	SYSTEM	\$14,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user weathc1 overridding Payment Estimate Exception 56 on the current Payment Estimate.
				10	Dec 16, 2020	SYSTEM	(\$7,250.00)	
				10	Dec 16, 2020	SYSTEM	\$7,250.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0035) due to user weathc1 overridding Payment Estimate Exception 56 on the current Payment Estimate.
				11	Jan 4, 2021	SYSTEM	(\$7,250.00)	
				11	Jan 4, 2021	SYSTEM	\$7,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user weathc1 overridding Payment Estimate Exception 70 on the current Payment Estimate.
				12	Jan 19, 2021	SYSTEM	(\$7,250.00)	
				12	Jan 19, 2021	SYSTEM	\$7,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user weathc1 overridding Payment Estimate Exception 70 on the current Payment Estimate.
				13	Feb 17, 2021	SYSTEM	(\$7,250.00)	
				13	Feb 17, 2021	SYSTEM	\$7,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user weathc1 overridding Payment Estimate Exception 71 on the current Payment Estimate.
	- Total							
			- Total				\$0.00	
	Material - Total		- Total				\$0.00 \$0.00	
	POWER SUPPLY ASSEMBLY, TYPE-2 WITH 120V LIGHTING	Overrun	- Total Overrun	9	Dec 3, 2020	SYSTEM		
	POWER SUPPLY ASSEMBLY,	Overrun		9		SYSTEM SYSTEM	\$0.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) overridding Payment Estimate Exception 75 on the current Payment Estimate.
	POWER SUPPLY ASSEMBLY, TYPE-2 WITH 120V LIGHTING	Overrun		9	2020 Dec 3,		<b>\$0.00</b> (\$7,250.00)	Estimate Item Adjustment (0021) overridding Payment Estimate
	POWER SUPPLY ASSEMBLY, TYPE-2 WITH 120V LIGHTING	Overrun	Overrun	9	2020 Dec 3,		\$0.00 (\$7,250.00) \$7,250.00	Estimate Item Adjustment (0021) overridding Payment Estimate
0860 -	POWER SUPPLY ASSEMBLY, TYPE-2 WITH 120V LIGHTING CONTROL CABINET	Overrun	Overrun	9	2020 Dec 3,		\$0.00 (\$7,250.00) \$7,250.00 \$0.00	Estimate Item Adjustment (0021) overridding Payment Estimate
<b>0860</b> -	POWER SUPPLY ASSEMBLY, TYPE-2 WITH 120V LIGHTING CONTROL CABINET  Overrun - Total		Overrun	9	2020 Dec 3,		\$0.00 (\$7,250.00) \$7,250.00 \$0.00 \$0.00	Estimate Item Adjustment (0021) overridding Payment Estimate
	POWER SUPPLY ASSEMBLY, TYPE-2 WITH 120V LIGHTING CONTROL CABINET  Overrun - Total  Total		Overrun	9 otal	2020 Dec 3, 2020	SYSTEM	\$0.00 (\$7,250.00) \$7,250.00 \$0.00 \$0.00	Estimate Item Adjustment (0021) overridding Payment Estimate
	POWER SUPPLY ASSEMBLY, TYPE-2 WITH 120V LIGHTING CONTROL CABINET  Overrun - Total  Total		Overrun	9 otal	2020 Dec 3, 2020 Oct 2, 2020 Oct 2,	SYSTEM	\$0.00 (\$7,250.00) \$7,250.00 \$0.00 \$0.00 (\$750.00)	Estimate Item Adjustment (0021) overridding Payment Estimate Exception 75 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0037) due to user weathc1 overridding
	POWER SUPPLY ASSEMBLY, TYPE-2 WITH 120V LIGHTING CONTROL CABINET  Overrun - Total  Total		Overrun	9 otal 6 6 6	2020 Dec 3, 2020 Oct 2, 2020 Oct 2, 2020 Nov 3,	SYSTEM SYSTEM SYSTEM	\$0.00 (\$7,250.00) \$7,250.00 \$0.00 \$0.00 (\$750.00)	Estimate Item Adjustment (0021) overridding Payment Estimate Exception 75 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0037) due to user weathc1 overridding
	POWER SUPPLY ASSEMBLY, TYPE-2 WITH 120V LIGHTING CONTROL CABINET  Overrun - Total  Total		Overrun	9 6 6 7	2020 Dec 3, 2020 Oct 2, 2020 Oct 2, 2020 Nov 3, 2020 Nov 3,	SYSTEM  SYSTEM  SYSTEM  SYSTEM	\$0.00 (\$7,250.00) \$7,250.00 \$0.00 \$0.00 (\$750.00)	Estimate Item Adjustment (0021) overridding Payment Estimate Exception 75 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0037) due to user weathc1 overridding Payment Estimate Exception 44 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user weathc1 overridding
	POWER SUPPLY ASSEMBLY, TYPE-2 WITH 120V LIGHTING CONTROL CABINET  Overrun - Total  Total		Overrun	9 ootal 6 6 7 7 7	2020 Dec 3, 2020 Oct 2, 2020 Oct 2, 2020 Nov 3, 2020 Nov 3, 2020	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$7,250.00) \$7,250.00 \$0.00 \$0.00 (\$750.00) \$750.00	Estimate Item Adjustment (0021) overridding Payment Estimate Exception 75 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0037) due to user weathc1 overridding Payment Estimate Exception 44 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user weathc1 overridding
	POWER SUPPLY ASSEMBLY, TYPE-2 WITH 120V LIGHTING CONTROL CABINET  Overrun - Total  Total		Overrun	9 6 6 7 7 8 8	2020 Dec 3, 2020 Oct 2, 2020 Oct 2, 2020 Nov 3, 2020 Nov 3, 2020 Nov 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$7,250.00) \$7,250.00 \$0.00 \$0.00 (\$750.00) \$750.00 (\$750.00)	Estimate Item Adjustment (0021) overridding Payment Estimate Exception 75 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0037) due to user weathc1 overridding Payment Estimate Exception 44 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user weathc1 overridding Payment Estimate Exception 46 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user weathc1 overridding
	POWER SUPPLY ASSEMBLY, TYPE-2 WITH 120V LIGHTING CONTROL CABINET  Overrun - Total  Total		Overrun	9 6 6 7 7 8 8 8	2020 Dec 3, 2020 Oct 2, 2020 Oct 2, 2020 Nov 3, 2020 Nov 16, 2020 Dec 3,	SYSTEM  SYSTEM  SYSTEM  SYSTEM  SYSTEM  SYSTEM  SYSTEM  SYSTEM	\$0.00 (\$7,250.00) \$7,250.00 \$0.00 \$0.00 (\$750.00) \$750.00 (\$750.00) \$750.00	Estimate Item Adjustment (0021) overridding Payment Estimate Exception 75 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0037) due to user weathc1 overridding Payment Estimate Exception 44 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user weathc1 overridding Payment Estimate Exception 46 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user weathc1 overridding
	POWER SUPPLY ASSEMBLY, TYPE-2 WITH 120V LIGHTING CONTROL CABINET  Overrun - Total  Total		Overrun	9 obtail 6 6 7 7 8 8 8 9	2020 Dec 3, 2020 Oct 2, 2020 Oct 2, 2020 Nov 3, 2020 Nov 16, 2020 Dec 3, 2020 Dec 3, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$7,250.00) \$7,250.00 \$0.00 \$0.00 (\$750.00) \$750.00 (\$750.00) \$750.00 (\$750.00)	Estimate Item Adjustment (0021) overridding Payment Estimate Exception 75 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0037) due to user weathc1 overridding Payment Estimate Exception 44 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user weathc1 overridding Payment Estimate Exception 46 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user weathc1 overridding Payment Estimate Exception 50 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0039) due to user weathc1 overridding

Revision 4/1/2020 Page 55 of 65



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																										
0880	PULL BOX, PREFORMED CLASS 2	Material						Payment Estimate Exception 57 on the current Payment Estimate.																										
				11	Jan 4, 2021	SYSTEM	(\$750.00)																											
				11	Jan 4, 2021	SYSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user weathc1 overridding Payment Estimate Exception 71 on the current Payment Estimate.																										
				12	Jan 19, 2021	SYSTEM	(\$750.00)																											
				12	Jan 19, 2021	SYSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user weathc1 overridding Payment Estimate Exception 71 on the current Payment Estimate.																										
				13	Feb 17, 2021	SYSTEM	(\$750.00)																											
				13	Feb 17, 2021	SYSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user weathc1 overridding Payment Estimate Exception 72 on the current Payment Estimate.																										
				14	Mar 2, 2021	SYSTEM	(\$750.00)																											
				14	Mar 2, 2021	SYSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user weathc1 overridding Payment Estimate Exception 44 on the current Payment Estimate.																										
				15	Mar 16, 2021	SYSTEM	(\$750.00)																											
				15	Mar 16, 2021	SYSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user weathc1 overridding Payment Estimate Exception 43 on the current Payment Estimate.																										
			- Total				\$0.00																											
	Material - Total						\$0.00																											
0880 -	Total						\$0.00																											
0890	PULL BOX, PREFORMED CLASS 3	Material		5	Sep 21, 2020	SYSTEM	(\$2,200.00)																											
				5	Sep 21, 2020	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user weathc1 overridding Payment Estimate Exception 46 on the current Payment Estimate.																										
				6	Oct 2, 2020	SYSTEM	(\$2,200.00)																											
				6	Oct 2, 2020	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0038) due to user weathc1 overridding Payment Estimate Exception 45 on the current Payment Estimate.																										
				7	Nov 3, 2020	SYSTEM	(\$2,200.00)																											
																		7	Nov 3, 2020	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user weathc1 overridding Payment Estimate Exception 47 on the current Payment Estimate.												
																								8	Nov 16, 2020	SYSTEM	(\$2,200.00)							
																								8	Nov 16, 2020	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user weathc1 overridding Payment Estimate Exception 51 on the current Payment Estimate.						
																9	Dec 3, 2020	SYSTEM	(\$2,200.00)															
																														9	Dec 3, 2020	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0040) due to user weathc1 overridding Payment Estimate Exception 58 on the current Payment Estimate.
																					10	Dec 16, 2020	SYSTEM	(\$2,200.00)										
																						10	Dec 16, 2020	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0037) due to user weathc1 overridding Payment Estimate Exception 58 on the current Payment Estimate.								
																1							11	Jan 4, 2021	SYSTEM	(\$2,200.00)								
																									1			1					11	11
																		12	Jan 19, 2021	SYSTEM	(\$2,200.00)													
						12	Jan 19,	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment																								

Revision 4/1/2020 Page 56 of 65



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks													
0890	PULL BOX, PREFORMED CLASS 3	Material			2021			Estimate Item Adjustment (0030) due to user weathc1 overridding Payment Estimate Exception 72 on the current Payment Estimate.													
				13	Feb 17, 2021	SYSTEM	(\$2,200.00)														
				13	Feb 17, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user weathc1 overridding Payment Estimate Exception 73 on the current Payment Estimate.													
				14	Mar 2, 2021	SYSTEM	(\$2,200.00)														
				14	Mar 2, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user weathc1 overridding Payment Estimate Exception 45 on the current Payment Estimate.													
				15	Mar 16, 2021	SYSTEM	(\$2,200.00)														
				15	Mar 16, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user weathc1 overridding Payment Estimate Exception 44 on the current Payment Estimate.													
			- Total				\$0.00														
	Material - Total						\$0.00														
0890	·Total						\$0.00														
0900	BASE, CONCRETE	Material		5	Sep 21, 2020	SYSTEM	(\$13,667.10)														
				5	Sep 21, 2020	SYSTEM	\$13,667.10	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0034) due to user weathc1 overridding Payment Estimate Exception 47 on the current Payment Estimate.													
									6	Oct 2, 2020	SYSTEM	(\$23,234.07)									
				6	Oct 2, 2020	SYSTEM	\$23,234.07	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user weathc1 overridding Payment Estimate Exception 46 on the current Payment Estimate.													
				7	Nov 3, 2020	SYSTEM	(\$23,234.07)														
				7	Nov 3, 2020	SYSTEM	\$23,234.07	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user weathc1 overridding Payment Estimate Exception 48 on the current Payment Estimate.													
								8	Nov 16, 2020	SYSTEM	(\$23,234.07)										
				8	Nov 16, 2020	SYSTEM	\$23,234.07	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0034) due to user weathc1 overridding Payment Estimate Exception 52 on the current Payment Estimate.													
				9	Dec 3, 2020	SYSTEM	(\$23,234.07)														
				9	Dec 3, 2020	SYSTEM	\$23,234.07	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0041) due to user weathc1 overridding Payment Estimate Exception 59 on the current Payment Estimate.													
				10	Dec 16, 2020	SYSTEM	(\$23,234.07)														
				10	Dec 16, 2020	SYSTEM	\$23,234.07	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0038) due to user weathc1 overridding Payment Estimate Exception 59 on the current Payment Estimate.													
														11	Jan 4, 2021	SYSTEM	(\$23,234.07)				
												12	Jan 19, 2021	SYSTEM	(\$23,234.07)						
				12	Jan 19, 2021	SYSTEM	\$23,234.07	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user weathc1 overridding Payment Estimate Exception 73 on the current Payment Estimate.													
				13	Feb 17, 2021	SYSTEM	(\$23,234.07)														
				13	Feb 17, 2021	SYSTEM	\$23,234.07	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0069) due to user weathc1 overridding Payment Estimate Exception 74 on the current Payment Estimate.													
			- Total				\$0.00														
	Material - Total						\$0.00														

Revision 4/1/2020 Page 57 of 65



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0900	BASE, CONCRETE	Overrun	Overrun	6	Oct 2, 2020	SYSTEM	(\$8,200.26)	
				6	Oct 2, 2020	SYSTEM	\$8,200.26	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) overridding Payment Estimate Exception 60 on the current Payment Estimate.
			Overrun - To	otal			\$0.00	
	Overrun - Total						\$0.00	
0900 -	Total						\$0.00	
0910	MISC. Accessible Pedestrian Signals (Pushbuttons)	Material		11	Jan 4, 2021	SYSTEM	(\$6,260.00)	
				11	Jan 4, 2021	SYSTEM	\$6,260.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user weathc1 overridding Payment Estimate Exception 74 on the current Payment Estimate.
				12	Jan 19, 2021	SYSTEM	(\$6,260.00)	
				12	Jan 19, 2021	SYSTEM	\$6,260.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user weathc1 overridding Payment Estimate Exception 74 on the current Payment Estimate.
				13	Feb 17, 2021	SYSTEM	(\$6,260.00)	
				13	Feb 17, 2021	SYSTEM	\$6,260.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0053) due to user weathc1 overridding Payment Estimate Exception 75 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0910 -	Total						\$0.00	
0920	MISC. Optional Traffic Signal Detectors	Material		9	Dec 3, 2020	SYSTEM	(\$650.00)	
				9	Dec 3, 2020	SYSTEM	\$650.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0042) due to user weathc1 overridding Payment Estimate Exception 60 on the current Payment Estimate.
				10	Dec 16, 2020	SYSTEM	(\$650.00)	
				10	Dec 16, 2020	SYSTEM	\$650.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0039) due to user weathc1 overridding Payment Estimate Exception 60 on the current Payment Estimate.
				11	Jan 4, 2021	SYSTEM	(\$1,300.00)	
				11	Jan 4, 2021	SYSTEM	\$1,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0067) due to user weathc1 overridding Payment Estimate Exception 75 on the current Payment Estimate.
				12	Jan 19, 2021	SYSTEM	(\$1,300.00)	
				12	Jan 19, 2021	SYSTEM	\$1,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0067) due to user weathc1 overridding Payment Estimate Exception 75 on the current Payment Estimate.
				13	Feb 17, 2021	SYSTEM	(\$1,300.00)	
				13	Feb 17, 2021	SYSTEM	\$1,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0076) due to user weathc1 overridding Payment Estimate Exception 76 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0920 -	Total						\$0.00	
0930	CONDUIT, 3 IN., RIGID, IN TRENCH	Material		4	Sep 1, 2020	SYSTEM	(\$1,382.10)	
				4	Sep 1, 2020	SYSTEM	\$1,382.10	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user weathc1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
				6	Oct 2, 2020	SYSTEM	(\$1,382.10)	
				6	Oct 2, 2020	SYSTEM	\$1,382.10	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0039) due to user weathc1 overridding Payment Estimate Exception 47 on the current Payment Estimate.
				7	Nov 3, 2020	SYSTEM	(\$12,113.70)	

Revision 4/1/2020 Page 58 of 65



Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks																										
0000	COMPUIT A IN PIOID IN TREMOU		Туре				#40.440.70	Triangle of the state of the st																										
0930	CONDUIT, 3 IN., RIGID, IN TRENCH	Material		7	Nov 3, 2020	SYSTEM	\$12,113.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0034) due to user weathc1 overridding Payment Estimate Exception 49 on the current Payment Estimate.																										
				8	Nov 16, 2020	SYSTEM	(\$12,113.70)																											
				8	Nov 16, 2020	SYSTEM	\$12,113.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0035) due to user weathc1 overridding Payment Estimate Exception 53 on the current Payment Estimate.																										
				9	Dec 3, 2020	SYSTEM	(\$12,113.70)																											
				9	Dec 3, 2020	SYSTEM	\$12,113.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0043) due to user weathc1 overridding Payment Estimate Exception 61 on the current Payment Estimate.																										
				10	Dec 16, 2020	SYSTEM	(\$12,113.70)																											
				10	Dec 16, 2020	SYSTEM	\$12,113.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0040) due to user weathc1 overridding Payment Estimate Exception 61 on the current Payment Estimate.																										
				11	Jan 4, 2021	SYSTEM	(\$12,113.70)																											
							11	Jan 4, 2021	SYSTEM	\$12,113.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0061) due to user weathc1 overridding Payment Estimate Exception 76 on the current Payment Estimate.																							
				12	Jan 19, 2021	SYSTEM	(\$12,113.70)																											
					12	Jan 19, 2021	SYSTEM	\$12,113.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0061) due to user weathc1 overridding Payment Estimate Exception 76 on the current Payment Estimate.																									
				13	Feb 17, 2021	SYSTEM	(\$12,113.70)																											
						13	Feb 17, 2021	SYSTEM	\$12,113.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0070) due to user weathc1 overridding Payment Estimate Exception 77 on the current Payment Estimate.																								
				14	Mar 2, 2021	SYSTEM	(\$12,113.70)																											
				14	Mar 2, 2021	SYSTEM	\$12,113.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user weathc1 overridding Payment Estimate Exception 46 on the current Payment Estimate.																										
																15	Mar 16, 2021	SYSTEM	(\$12,113.70)															
				15	Mar 16, 2021	SYSTEM	\$12,113.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user weathc1 overridding Payment Estimate Exception 45 on the current Payment Estimate.																										
	Metadel Tetal		- Total				\$0.00																											
0020	Material - Total						\$0.00																											
0930 -	Total  CONDUIT 3 IN RIGID PUSHED	Material		4	San 1	SYSTEM	\$0.00 (\$56.110.80)																											
0940	CONDUIT, 3 IN., RIGID, PUSHED	iviaterial			Sep 1, 2020		(\$56,110.80)	This adjustment offsets the existing a second of the secon																										
																			4	Sep 1, 2020	SYSTEM	\$56,110.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user weathc1 overridding Payment Estimate Exception 39 on the current Payment Estimate.											
				5	Sep 21, 2020	SYSTEM	(\$11,187.20)																											
																														5	Sep 21, 2020	SYSTEM	\$11,187.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0035) due to user weathc1 overridding Payment Estimate Exception 48 on the current Payment Estimate.
				6	Oct 2, 2020	SYSTEM	(\$44,923.60)																											
				6	Oct 2, 2020	SYSTEM	\$44,923.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user weathc1 overridding Payment Estimate Exception 48 on the current Payment Estimate.																										
				7	Nov 3, 2020	SYSTEM	(\$44,923.60)																											
				7	Nov 3, 2020	SYSTEM	\$44,923.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0035) due to user weathc1 overridding Payment Estimate Exception 50 on the current Payment Estimate.																										
				8	Nov 16, 2020	SYSTEM	(\$44,923.60)																											

Revision 4/1/2020 Page 59 of 65



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0940	CONDUIT, 3 IN., RIGID, PUSHED	Material	.,,,,,	8	Nov 16, 2020	SYSTEM	\$44,923.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0036) due to user weathc1 overridding Payment Estimate Exception 54 on the current Payment Estimate.
				9	Dec 3, 2020	SYSTEM	(\$44,923.60)	
				9	Dec 3, 2020	SYSTEM	\$44,923.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0044) due to user weathc1 overridding Payment Estimate Exception 62 on the current Payment Estimate.
				10	Dec 16, 2020	SYSTEM	(\$44,923.60)	
				10	Dec 16, 2020	SYSTEM	\$44,923.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0041) due to user weathc1 overridding Payment Estimate Exception 62 on the current Payment Estimate.
				11	Jan 4, 2021	SYSTEM	(\$44,923.60)	
				11	Jan 4, 2021	SYSTEM	\$44,923.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0062) due to user weathc1 overridding Payment Estimate Exception 77 on the current Payment Estimate.
				12	Jan 19, 2021	SYSTEM	(\$44,923.60)	
				12	Jan 19, 2021	SYSTEM	\$44,923.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0062) due to user weathc1 overridding Payment Estimate Exception 77 on the current Payment Estimate.
				13	Feb 17, 2021	SYSTEM	(\$44,923.60)	
				13	Feb 17, 2021	SYSTEM	\$44,923.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0071) due to user weathc1 overridding Payment Estimate Exception 78 on the current Payment Estimate.
				14	Mar 2, 2021	SYSTEM	(\$44,923.60)	
				14	Mar 2, 2021	SYSTEM	\$44,923.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user weathc1 overridding Payment Estimate Exception 47 on the current Payment Estimate.
				15	Mar 16, 2021	SYSTEM	(\$44,923.60)	
				15	Mar 16, 2021	SYSTEM	\$44,923.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user weathc1 overridding Payment Estimate Exception 46 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	CONDUIT, 3 IN., RIGID, PUSHED	Overrun	Overrun	4	Sep 1, 2020	SYSTEM	(\$37,372.24)	
				4	Sep 1, 2020	SYSTEM	\$37,372.24	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) overridding Payment Estimate Exception 46 on the current Payment Estimate.
				6	Oct 2, 2020	SYSTEM	(\$26,185.04)	
				6	Oct 2, 2020	SYSTEM	\$26,185.04	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) overridding Payment Estimate Exception 61 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0940 -	Total						\$0.00	
0950	FIBER OPTIC CABLE, 12-STRAND, SINGLE MODE	Material		8	Nov 16, 2020	SYSTEM	(\$5,414.50)	
				8	Nov 16, 2020	SYSTEM	\$5,414.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0037) due to user weathc1 overridding Payment Estimate Exception 55 on the current Payment Estimate.
				9	Dec 3, 2020	SYSTEM	(\$5,414.50)	
				9	Dec 3, 2020	SYSTEM	\$5,414.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0045) due to user weathc1 overridding Payment Estimate Exception 63 on the current Payment Estimate.
				10	Dec 16, 2020	SYSTEM	(\$5,414.50)	
				10	Dec 16, 2020	SYSTEM	\$5,414.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0042) due to user weathc1 overridding

Revision 4/1/2020 Page 60 of 65



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks												
0950	FIBER OPTIC CABLE, 12-STRAND,		Material	Material	Material	Material	Material	Material	Material	Material	.,,,,,					Payment Estimate Exception 63 on the current Payment Estimate.				
0000	SINGLE MODE			11	Jan 4, 2021	SYSTEM	(\$5,414.50)	A Symon Estimate Exception of Shand State of Symon Estimate.												
					11	Jan 4, 2021	SYSTEM	\$5,414.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user weathor overridding Payment Estimate Exception 78 on the current Payment Estimate.											
				12	Jan 19, 2021	SYSTEM	(\$5,414.50)													
				12	Jan 19, 2021	SYSTEM	\$5,414.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user weathc1 overridding Payment Estimate Exception 78 on the current Payment Estimate.												
				13	Feb 17, 2021	SYSTEM	(\$5,414.50)													
				13	Feb 17, 2021	SYSTEM	\$5,414.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user weathc1 overridding Payment Estimate Exception 79 on the current Payment Estimate.												
			- Total				\$0.00													
	Material - Total						\$0.00													
0950 -	- Total						\$0.00													
0960	PULL BOX, PREFORMED CLASS 1	Material		4	Sep 1, 2020	SYSTEM	(\$2,500.00)													
				4	Sep 1, 2020	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user weathc1 overridding Payment Estimate Exception 40 on the current Payment Estimate.												
					5	Sep 21, 2020	SYSTEM	(\$2,500.00)												
					5	Sep 21, 2020	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0036) due to user weathc1 overridding Payment Estimate Exception 49 on the current Payment Estimate.											
				6	Oct 2, 2020	SYSTEM	(\$2,500.00)													
				6	Oct 2, 2020	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0040) due to user weathc1 overridding Payment Estimate Exception 49 on the current Payment Estimate.												
				7	Nov 3, 2020	SYSTEM	(\$2,500.00)													
				7	Nov 3, 2020	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0036) due to user weathc1 overridding Payment Estimate Exception 51 on the current Payment Estimate.												
				8	Nov 16, 2020	SYSTEM	(\$2,500.00)													
				8	Nov 16, 2020	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0038) due to user weathc1 overridding Payment Estimate Exception 56 on the current Payment Estimate.												
										9	Dec 3, 2020	SYSTEM	(\$2,500.00)							
					9	Dec 3, 2020	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0046) due to user weathc1 overridding Payment Estimate Exception 64 on the current Payment Estimate.											
																10	Dec 16, 2020	SYSTEM	(\$2,500.00)	
															10	Dec 16, 2020	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0043) due to user weathc1 overridding Payment Estimate Exception 64 on the current Payment Estimate.	
					11	Jan 4, 2021	SYSTEM	(\$2,500.00)												
					11	Jan 4, 2021	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user weathc1 overridding Payment Estimate Exception 79 on the current Payment Estimate.											
					12	Jan 19, 2021	SYSTEM	(\$2,500.00)												
					12	Jan 19, 2021	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user weathc1 overridding Payment Estimate Exception 79 on the current Payment Estimate.											
					13	Feb 17, 2021	SYSTEM	(\$2,500.00)												
				13	Feb 17,	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Material Payment												

Revision 4/1/2020 Page 61 of 65



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0960	PULL BOX, PREFORMED CLASS 1	Material			2021			Estimate Item Adjustment (0034) due to user weathc1 overridding Payment Estimate Exception 80 on the current Payment Estimate.
				14	Mar 2, 2021	SYSTEM	(\$2,500.00)	
				14	Mar 2, 2021	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user weathc1 overridding Payment Estimate Exception 48 on the current Payment Estimate.
				15	Mar 16, 2021	SYSTEM	(\$2,500.00)	
				15	Mar 16, 2021	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user weathc1 overridding Payment Estimate Exception 47 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	· Total						\$0.00	
0970	PULL BOX, PREFORMED CLASS 5	Material		5	Sep 21, 2020	SYSTEM	(\$1,400.00)	
				5	Sep 21, 2020	SYSTEM	\$1,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0037) due to user weathc1 overridding Payment Estimate Exception 50 on the current Payment Estimate.
				6	Oct 2, 2020	SYSTEM	(\$1,400.00)	
				6	Oct 2, 2020	SYSTEM	\$1,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0041) due to user weathc1 overridding Payment Estimate Exception 50 on the current Payment Estimate.
				7	Nov 3, 2020	SYSTEM	(\$2,800.00)	
				7	Nov 3, 2020	SYSTEM	\$2,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0037) due to user weathc1 overridding Payment Estimate Exception 52 on the current Payment Estimate.
				8	Nov 16, 2020	SYSTEM	(\$2,800.00)	
				8	Nov 16, 2020	SYSTEM	\$2,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0039) due to user weathc1 overridding Payment Estimate Exception 57 on the current Payment Estimate.
				9	Dec 3, 2020	SYSTEM	(\$2,800.00)	
				9	Dec 3, 2020	SYSTEM	\$2,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0047) due to user weathc1 overridding Payment Estimate Exception 65 on the current Payment Estimate.
				10	Dec 16, 2020	SYSTEM	(\$2,800.00)	
				10	Dec 16, 2020	SYSTEM	\$2,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0044) due to user weathc1 overridding Payment Estimate Exception 65 on the current Payment Estimate.
				11	Jan 4, 2021	SYSTEM	(\$2,800.00)	
				11	Jan 4, 2021	SYSTEM	\$2,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user weathc1 overridding Payment Estimate Exception 80 on the current Payment Estimate.
				12	Jan 19, 2021	SYSTEM	(\$2,800.00)	
				12	Jan 19, 2021	SYSTEM	\$2,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user weathc1 overridding Payment Estimate Exception 80 on the current Payment Estimate.
				13	Feb 17, 2021	SYSTEM	(\$2,800.00)	
				13	Feb 17, 2021	SYSTEM	\$2,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user weathc1 overridding Payment Estimate Exception 81 on the current Payment Estimate.
				14	Mar 2, 2021	SYSTEM	(\$2,800.00)	
				14	Mar 2, 2021	SYSTEM	\$2,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user weathc1 overridding Payment Estimate Exception 49 on the current Payment Estimate.
				15	Mar 16, 2021	SYSTEM	(\$2,800.00)	

Revision 4/1/2020 Page 62 of 65



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
0970	PULL BOX, PREFORMED CLASS 5	Material		15	Mar 16, 2021	SYSTEM	\$2,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user weathc1 overridding Payment Estimate Exception 48 on the current Payment Estimate.			
			- Total				\$0.00				
	Material - Total						\$0.00				
0970 -	Total						\$0.00				
0985	MISC. INSTALLATION OF COMMISSION FURNISHED TELECOMMUNICATIONS EQUIPMENT	Material		11	Jan 4, 2021	SYSTEM	(\$3,500.00)				
				11	Jan 4, 2021	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0059) due to user weathc1 overridding Payment Estimate Exception 81 on the current Payment Estimate.			
				12	Jan 19, 2021	SYSTEM	(\$3,500.00)				
				12	Jan 19, 2021	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0059) due to user weathc1 overridding Payment Estimate Exception 81 on the current Payment Estimate.			
				13	Feb 17, 2021	SYSTEM	(\$3,500.00)				
				13	Feb 17, 2021	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0068) due to user weathc1 overridding Payment Estimate Exception 82 on the current Payment Estimate.			
			- Total				\$0.00				
	Material - Total						\$0.00				
0985 -	Total						\$0.00				
0990	MISC. FIBER OPTIC SPLICE CABINET	Material		9	Dec 3, 2020	SYSTEM	(\$2,400.00)				
				9	Dec 3, 2020	SYSTEM	\$2,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0048) due to user weathc1 overridding Payment Estimate Exception 66 on the current Payment Estimate.			
				10	Dec 16, 2020	SYSTEM	(\$2,400.00)				
				10	Dec 16, 2020	SYSTEM	\$2,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0045) due to user weathc1 overridding Payment Estimate Exception 66 on the current Payment Estimate.			
				11	Jan 4, 2021	SYSTEM	(\$2,400.00)				
				11	Jan 4, 2021	SYSTEM	\$2,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0068) due to user weathc1 overridding Payment Estimate Exception 82 on the current Payment Estimate.			
				12	Jan 19, 2021	SYSTEM	(\$2,400.00)				
				12	Jan 19, 2021	SYSTEM	\$2,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0068) due to user weathc1 overridding Payment Estimate Exception 82 on the current Payment Estimate.			
				13	Feb 17, 2021	SYSTEM	(\$4,800.00)				
									13	Feb 17, 2021	SYSTEM
			- Total				\$0.00				
	Material - Total						\$0.00				
	MISC. FIBER OPTIC SPLICE CABINET	Overrun	Overrun	13	Feb 17, 2021	SYSTEM	(\$2,400.00)				
				13	Feb 17, 2021	SYSTEM	\$2,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) overridding Payment Estimate Exception 102 on the current Payment Estimate. Material Insufficiency Quantity 4.000; Overrun Quantity Balance 2.00.			
				14	Mar 2, 2021	SYSTEM	(\$2,400.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).			
				14	Mar 2, 2021	SYSTEM	\$2,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user weathc1 overridding Payment Estimate Exception 52 on the current Payment Estimate.			
				15	Mar 16, 2021	SYSTEM	(\$2,400.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).			
				15	Mar 16, 2021	SYSTEM	\$2,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user weathc1 overridding			

Revision 4/1/2020 Page 63 of 65



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0990	MISC. FIBER OPTIC SPLICE CABINET	Overrun	Overrun					Payment Estimate Exception 61 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0990 -	Total						\$0.00	
1000	MISC. FIBER OPTIC SPLICE UNDERGROUND	Material		13	Feb 17, 2021	SYSTEM	(\$2,100.00)	
				13	Feb 17, 2021	SYSTEM	\$2,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0063) due to user weathc1 overridding Payment Estimate Exception 84 on the current Payment Estimate.
			- Total			\$0.00		
	Material - Total						\$0.00	
1000 -	Total						\$0.00	
1010	MISC. MEDIA CONVERTER FURNISH AND INSTALL	Material		13	Feb 17, 2021	SYSTEM	(\$2,700.00)	
				13	Feb 17, 2021	SYSTEM	\$2,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0067) due to user weathc1 overridding Payment Estimate Exception 88 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1010 -	Total						\$0.00	
1020	MISC. OGL SWITCH - FURNISH INSTALL	Material		13	Feb 17, 2021	SYSTEM	(\$17,000.00)	
				13	Feb 17, 2021	SYSTEM	\$17,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0065) due to user weathc1 overridding Payment Estimate Exception 87 on the current Payment Estimate.
	- Total						\$0.00	
	Material - Total						\$0.00	
1020 -	Total						\$0.00	
1030	MISC. PRE-TERMINATED FIBER PANEL, FURNISH - INSTALL	Material		13	Feb 17, 2021	SYSTEM	(\$1,100.00)	
				13	Feb 17, 2021	SYSTEM	\$1,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0062) due to user weathc1 overridding Payment Estimate Exception 83 on the current Payment Estimate.
	- Total						\$0.00	
	Material - Total						\$0.00	
1030 -	Total						\$0.00	
1040	MISC. SPLICE ENCLOSURE	Material		13	Feb 17, 2021	SYSTEM	(\$900.00)	
				13	Feb 17, 2021	SYSTEM	\$900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0064) due to user weathc1 overridding Payment Estimate Exception 86 on the current Payment Estimate.
	- Total						\$0.00	
	Material - Total						\$0.00	
1040 -	Total						\$0.00	
1050	MISC. PRE-TERMINATED FIBER PANEL CABLE FURNISH - INSTALL	Material		13	Feb 17, 2021	SYSTEM	(\$660.00)	
				13	Feb 17, 2021	SYSTEM	\$660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0066) due to user weathc1 overridding Payment Estimate Exception 89 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1050 -	Total						\$0.00	
5001		Material		6	Oct 2, 2020	SYSTEM	(\$2,400.00)	
				6	Oct 2, 2020	SYSTEM	\$2,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0042) due to user weathc1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
				7	Nov 3, 2020	SYSTEM	(\$2,400.00)	
				7	Nov 3,	SYSTEM	\$2,400.00	This adjustment offsets the original system-generated Overrun Payment

Revision 4/1/2020 Page 64 of 65



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
5001	15 IN. OR ALLOWED SUBSTITUTE I GROUP A FLARED END SECTION	Material			2020			Estimate Item Adjustment (0038) due to user weathc1 overridding Payment Estimate Exception 38 on the current Payment Estimate.		
				8	Nov 16, 2020	SYSTEM	(\$2,400.00)			
				8	Nov 16, 2020	SYSTEM	\$2,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0040) due to user weathc1 overridding Payment Estimate Exception 38 on the current Payment Estimate.		
				9	Dec 3, 2020	SYSTEM	(\$2,400.00)			
				9	Dec 3, 2020	SYSTEM	\$2,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0049) due to user weathc1 overridding Payment Estimate Exception 38 on the current Payment Estimate.		
			- Total			\$0.00				
	Material - Total						\$0.00			
5001 -	Total						\$0.00			
5002	SEEDING - COOL SEASON MIXTURES	Material		8	Nov 16, 2020	SYSTEM	(\$1,704.07)			
				8	Nov 16, 2020	SYSTEM	\$1,704.07	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0041) due to user weathc1 overridding Payment Estimate Exception 40 on the current Payment Estimate.		
				9	Dec 3, 2020	SYSTEM	(\$1,704.07)			
				9	Dec 3, 2020	SYSTEM	\$1,704.07	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0050) due to user weathc1 overridding Payment Estimate Exception 40 on the current Payment Estimate.		
				10	Dec 16, 2020	SYSTEM	(\$1,704.07)			
				10	Dec 16, 2020	SYSTEM	\$1,704.07	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0046) due to user weathc1 overridding Payment Estimate Exception 40 on the current Payment Estimate.		
				11	Jan 4, 2021	SYSTEM	(\$1,704.07)			
				11	Jan 4, 2021	SYSTEM	\$1,704.07	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user weathc1 overridding Payment Estimate Exception 42 on the current Payment Estimate.		
				12	Jan 19, 2021	SYSTEM	(\$1,704.07)			
				12	Jan 19, 2021	SYSTEM	\$1,704.07	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user weathc1 overridding Payment Estimate Exception 42 on the current Payment Estimate.		
				13	Feb 17, 2021	SYSTEM	(\$2,011.75)			
				13	Feb 17, 2021	SYSTEM	\$2,011.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user weathc1 overridding Payment Estimate Exception 42 on the current Payment Estimate.		
						14	14	Mar 2, 2021	SYSTEM	(\$2,011.75)
				14	Mar 2, 2021	SYSTEM	\$2,011.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user weathc1 overridding Payment Estimate Exception 32 on the current Payment Estimate.		
				15	Mar 16, 2021	SYSTEM	(\$2,011.75)			
				15	Mar 16, 2021	SYSTEM	\$2,011.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user weathc1 overridding Payment Estimate Exception 31 on the current Payment Estimate.		
		- Total				\$0.00				
	Material - Total					\$0.00				
	SEEDING - COOL SEASON MIXTURES	Other Item Adjustment	OTHR	13	Feb 17, 2021	weathc1	(\$301.76)	Holding 15% to ensure Sod growth.		
			OTHR - Tota	al			(\$301.76)			
	Other Item Adjustment - Total						(\$301.76)			
002 -	Total						(\$301.76)			
vera	II - Total						(\$301.76)			

Revision 4/1/2020 Page 65 of 65