

#### **Missouri Department of Transportation Contractor's Pay Estimate Summary**

Pay Estimate Created Date: March 16, 2021

| Progress Estimate<br>Number | Contract ID         | 200515-C12                             | Pay Period<br>Start | March 2, 2021 | Original Contract Amoun                               | <b>t</b> \$1,687,091.92        |
|-----------------------------|---------------------|--|---------------------|---------------|---|--------------------------------|
| 18                          | Prime<br>Contractor | Radmacher Brothers Excavating Co.,Inc. | Pay Period End      |               | Net Change Order<br>Amount<br>Current Contract Amount | \$16,592.23<br>£\$1,703,684.15 |

| By User |  | Approval Date  |
|---------|--|----------------|
| schnod1 | Generated and Approved (and should be considered Draft) at the Project Office Level by   | March 16, 2021 |
| warrem1 | Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by | March 16, 2021 |
| ramses1 | Reviewed and Approved at the Central Office Controllers Office Level by                  | March 17, 2021 |

| Original Completion Date | Current Completion Date | Actual Completion Date | % of Current Contract Amount Complete |
|--------------------------|-------------------------|------------------------|---------------------------------------|
| November 13, 2020        | November 13, 2020       | November 13, 2020      | 99.52%                                |

| Con                       | tract Information                                | al Dates            |  | Mile                           | stones                        |                             |                         |  |
|---------------------------|--|---------------------|--|--------------------------------|-------------------------------|-----------------------------|-------------------------|--|
| Date<br>Description       | Original Current Completion Completion Date Date |                     | Date Description                                   | Original<br>Completion<br>Date | Current<br>Completion<br>Date | Days Remaining on Milestone | Diary<br>Charge<br>Days |  |
| Acceptance<br>Date        |  |                     | Milestone - Calendar Time JSP<br>B - Calendar Days | November 14,<br>2020           | November 14,<br>2020          | Milestone<br>Complete       |                         |  |
| Awarded Date              | June 3, 2020                                     | June 3, 2020        |  |                                |                               |                             |                         |  |
| Letting Date              | May 15, 2020                                     | May 15, 2020        |  |                                |                               |                             |                         |  |
| Notice to<br>Proceed Date | June 18, 2020                                    | June 18, 2020       |  |                                |                               |                             |                         |  |
| Open to Traffic<br>Date   | December 3,<br>2020                              | December 3,<br>2020 |  |                                |                               |                             |                         |  |
| Work Began<br>Date        |  |                     |  |                                |                               |                             |                         |  |

| Contract Total Pay For Estimate No. 18 |                            |               |                |                |  |  |  |  |  |  |  |
|--|----------------------------|---------------|----------------|----------------|--|--|--|--|--|--|--|
|  |                            | This Estimate | Previous       | To Date        |  |  |  |  |  |  |  |
| 200515-C12                             |                            |               |                |                |  |  |  |  |  |  |  |
|  | Total Posted Items Pay     | \$19,511.83   | \$1,676,003.26 | \$1,695,515.09 |  |  |  |  |  |  |  |
|  | Gross Item Adjustments     | \$33.30       | \$1,381.99     | \$1,415.29     |  |  |  |  |  |  |  |
|  | Incentive                  | \$0.00        | \$0.00         | \$0.00         |  |  |  |  |  |  |  |
|  | Disincentive               | \$0.00        | \$0.00         | \$0.00         |  |  |  |  |  |  |  |
|  | Liquidated Damage          | \$0.00        | \$0.00         | \$0.00         |  |  |  |  |  |  |  |
|  | Other Contract Adjustments | \$0.00        | \$0.00         | \$0.00         |  |  |  |  |  |  |  |
|  | ,                          |               | \$1,677,385.25 | \$1,696,930.38 |  |  |  |  |  |  |  |
| Contract Total Pa                      | avable This Estimate:      | \$19 545 13   |                |                |  |  |  |  |  |  |  |

#### Items Paid This Estimate Period

| Project<br>Number | Line<br>Number | Item<br>Code | Item Description                        | Unit | Unit Price | Current Installed<br>Qty | Current Installed<br>Amount |
|-------------------|----------------|--------------|---|------|------------|--------------------------|-----------------------------|
| J4S3205           | 0040           | 2035500      | EMBANKMENT IN PLACE                     | CUYD | \$15.700   | 230                      | \$3,611.00                  |
|                   | 0090           | 3040506      | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) | SQYD | \$10.100   | 42                       | \$424.20                    |
|                   | 0120           | 5029905      | MISC.TINTED CONCRETE PAVEMENT (8")      | SQYD | \$94.600   | 0.1                      | \$9.46                      |
|                   | 0210           | 6085007      | PAVED APPROACH, 7 IN.                   | SQYD | \$58.600   | 25.3                     | \$1,482.58                  |
|                   | 0220           | 6086004      | CONCRETE SIDEWALK, 4 IN.                | SQYD | \$31.300   | -13.3                    | (\$416.29)                  |
|                   | 0270           | 6099903      | MISC.APWA CURB AND GUTTER TYPE CG-1     | LF   | \$19.950   | 232.5                    | \$4,638.38                  |
|                   | 5003           | 6053020A     | FRENCH UNDERDRAIN                       | LF   | \$135.650  | 70                       | \$9,495.50                  |
|                   | 5004           | 6049902      | MISC.MANHOLE LID                        | EA   | \$267.000  | 1                        | \$267.00                    |
| Project J4S320    | 5 - Total      |              |   |      |            |                          | \$19,511.83                 |
| Overall - Total   |                |              |   |      |            |                          | \$19,511.83                 |

#### **Contract Adjustments This Estimate**

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Revision 4/1/2020 Page 1 of 30



## Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: March 16, 2021

Pay Period Start **Progress Estimate** March 2, 2021 Original Contract Amount\$1,687,091.92 **Contract ID** 200515-C12 Number Pay Period End March 15, 2021 Prime Radmacher Brothers Excavating Net Change Order 18 \$16,592.23 Contractor Amount Co.,Inc. Current Contract Amount \$1,703,684.15

| Adjustment<br>amount | Line Item<br>Adjustment<br>Unit Price | Adjustment<br>Quantity | Comments  | Other Item<br>Adjustment<br>Type | Adjustment<br>Type       | Item Description                           | Line<br>No. |
|----------------------|---------------------------------------|------------------------|---|----------------------------------|--------------------------|--|-------------|
| \$94.18              | \$0.41                                | 230                    | Reference Item Price Adjustment Index<br>Adjustment Type applied is FUEL  |                                  | Price                    | EMBANKMENT IN PLACE                        | 0040        |
| (\$94.18             |                                       |                        | Removing system generated fuel adjustment, and entering manual adjustment.  | Fuel Price                       | Other Item<br>Adjustment | EMBANKMENT IN PLACE                        | 0040        |
| \$25.76              |                                       |                        | Manual fuel adjustment for work done during the estimate 0008 period.   | Fuel Price                       | Other Item<br>Adjustment | EMBANKMENT IN PLACE                        | 0040        |
| \$11.30              | \$0.27                                | 42                     | Reference Item Price Adjustment Index<br>Adjustment Type applied is FUEL  |                                  | Price                    | TYPE 5 AGGREGATE FOR<br>BASE (6 IN. THICK) | 0090        |
| (\$60,448.50         | \$10.10                               | -5,985                 |   |                                  | Material                 | TYPE 5 AGGREGATE FOR<br>BASE (6 IN. THICK) | 0090        |
| \$60,448.50          | \$10.10                               | 5,985                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0011) due to user schnod1<br>overridding Payment Estimate Exception 1 on<br>the current Payment Estimate. |                                  | Material                 | TYPE 5 AGGREGATE FOR<br>BASE (6 IN. THICK) | 0090        |
| (\$11.30             |                                       |                        | Removing auto fuel adjustment, and entering manual fuel adjustment.   | Fuel Price                       | Other Item<br>Adjustment | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)    | 0090        |
| \$3.09               |                                       |                        | Manual fuel adjustment calculation for work done during estimate period 0008.   | Fuel Price                       | Other Item<br>Adjustment | TYPE 5 AGGREGATE FOR<br>BASE (6 IN. THICK) | 0090        |
| (\$3,819.20          | \$17.60                               | -217                   |   |                                  | Material                 | PIPE AGGREGATE<br>PAVEMENT EDGE DRAIN      | 0150        |
| \$3,819.20           | \$17.60                               | 217                    | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0012) due to user schnod1<br>overridding Payment Estimate Exception 5 on<br>the current Payment Estimate. |                                  | Material                 | PIPE AGGREGATE<br>PAVEMENT EDGE DRAIN      | 0150        |
| (\$1,775.40          | \$1,775.40                            | -1                     |   |                                  | Material                 | OUTLET PIPES AND<br>SPLASH PADS            | 0160        |
| \$1,775.40           | \$1,775.40                            | 1                      | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0018) due to user schnod1<br>overridding Payment Estimate Exception 6 on<br>the current Payment Estimate. |                                  | Material                 | OUTLET PIPES AND<br>SPLASH PADS            | 0160        |
| (\$7,894.80          | \$25.80                               | -306                   |   |                                  | Material                 | MODIFIED CONCRETE<br>GUTTER TYPE B         | 0180        |
| \$7,894.80           | \$25.80                               | 306                    | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0019) due to user schnod1<br>overridding Payment Estimate Exception 8 on<br>the current Payment Estimate. |                                  | Material                 | MODIFIED CONCRETE<br>GUTTER TYPE B         | 0180        |
| (\$1,484.60          | \$47.25                               | -31.42                 | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).   |                                  | Overrun                  | CONCRETE CURB RAMP                         | 0190        |
| \$1,484.60           | \$47.25                               | 31.42                  | This adjustment offsets the original system-<br>generated Overrun Payment Estimate Item<br>Adjustment (0010) due to user schnod1<br>overridding Payment Estimate Exception 18<br>on the current Payment Estimate. |                                  | Overrun                  | CONCRETE CURB RAMP                         | 0190        |
| \$16.28              | \$0.64                                | 25.3                   | Reference Item Price Adjustment Index<br>Adjustment Type applied is FUEL  |                                  | Price                    | PAVED APPROACH, 7 IN.                      | 0210        |
| (\$4,529.78          | \$58.60                               | -77.3                  |   |                                  | Material                 | PAVED APPROACH, 7 IN.                      | 0210        |
| \$4,529.78           | \$58.60                               | 77.3                   | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0013) due to user schnod1<br>overridding Payment Estimate Exception 9 on<br>the current Payment Estimate. |                                  | Material                 | PAVED APPROACH, 7 IN.                      | 0210        |

Revision 4/1/2020 Page 2 of 30



## Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: March 16, 2021

Pay Period Start **Progress Estimate** March 2, 2021 Original Contract Amount\$1,687,091.92 **Contract ID** 200515-C12 Number Pay Period End March 15, 2021 Prime Radmacher Brothers Excavating Net Change Order 18 \$16,592.23 Contractor Amount Co.,Inc. Current Contract Amount \$1,703,684.15

| Project<br>Number | Line<br>No. | Item Description                                 | Adjustment<br>Type       | Other Item<br>Adjustment<br>Type | Comments   | Adjustment<br>Quantity | Line Item<br>Adjustment<br>Unit Price | Adjustment<br>amount |
|-------------------|-------------|--|--------------------------|----------------------------------|--|------------------------|---------------------------------------|----------------------|
| J4S3205           | 0210        | PAVED APPROACH, 7 IN.                            | Other Item<br>Adjustment | Fuel Price                       | Removing auto fuel adjustment, to enter manual fuel adjustment.  |                        |                                       | (\$16.28)            |
|                   | 0210        | PAVED APPROACH, 7 IN.                            | Other Item<br>Adjustment | Fuel Price                       | Manual fuel adjustment for work that was done during the 0008 estimate period.   |                        |                                       | \$4.45               |
|                   | 0450        | FLOWABLE BACKFILL                                | Material                 |                                  |  | -38                    | \$172.75                              | (\$6,564.50)         |
|                   | 0450        | FLOWABLE BACKFILL                                | Material                 |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0014) due to user schnod1<br>overridding Payment Estimate Exception 10<br>on the current Payment Estimate. | 38                     | \$172.75                              | \$6,564.50           |
|                   | 0480        | MECHANICALLY<br>STABILIZED EARTH WALL<br>SYSTEMS | Material                 |                                  |  | -3,595                 | \$78.75                               | (\$283,106.25)       |
|                   | 0480        | MECHANICALLY<br>STABILIZED EARTH WALL<br>SYSTEMS | Material                 |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0015) due to user schnod1<br>overridding Payment Estimate Exception 11<br>on the current Payment Estimate. | 3,595                  | \$78.75                               | \$283,106.25         |
|                   | 0490        | FORM LINERS FOR MSE<br>WALL SYSTEMS              | Material                 |                                  |  | -399                   | \$1.15                                | (\$458.85)           |
|                   | 0490        | FORM LINERS FOR MSE<br>WALL SYSTEMS              | Material                 |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0016) due to user schnod1<br>overridding Payment Estimate Exception 16<br>on the current Payment Estimate. | 399                    | \$1.15                                | \$458.85             |
|                   | 1040        | CONCRETE FOOTINGS,<br>EMBEDDED                   | Material                 |                                  |  | -0.4                   | \$2,100.00                            | (\$840.00)           |
|                   | 1040        | CONCRETE FOOTINGS,<br>EMBEDDED                   | Material                 |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0017) due to user schnod1<br>overridding Payment Estimate Exception 17<br>on the current Payment Estimate. | 0.4                    | \$2,100.00                            | \$840.00             |
|                   | 5003        | FRENCH UNDERDRAIN                                | Material                 |                                  |  | -70                    | \$135.65                              | (\$9,495.50)         |
|                   | 5003        | FRENCH UNDERDRAIN                                | Material                 |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0020) due to user schnod1<br>overridding Payment Estimate Exception 3 on<br>the current Payment Estimate.  | 70                     | \$135.65                              | \$9,495.50           |
| otal              |             |  |                          |                                  |  |                        |                                       | \$33.30              |

Revision 4/1/2020 Page 3 of 30



### Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

|                   |                            |                            |       |            | Co   | ontract Project Information                                     |   |
|-------------------|----------------------------|----------------------------|-------|------------|--|---|---|
| Project<br>Number | Federal<br>Proj.<br>Number | Project<br>Description     | Route | County     |  |   | Location of Work  |
| J4S3205           | FAS<br>S301(73)            | Build new roundabout       | 1     | CLAY       | on Route 1 at Parvin Road                              |   |   |
| Totals by         | Job Numbe                  | rs                         |       |            |  |   |   |
|                   |                            |                            |       |            |  |   |   |
| J4S3205           |                            |                            |       |            | This Estimate  | Previous  | To Date   |
| J4S3205           | Poste                      | d Item Pay                 |       |            | This Estimate<br>\$19,511.83                           | Previous<br>\$1,676,003.26                                      | <b>To Date</b><br>\$1,695,515.09                                |
| J4S3205           |                            | d Item Pay<br>Item Adjustm | ents  |            |  |   |   |
| J4S3205           |                            |                            |       | Item Pay   | \$19,511.83<br>\$33.30                                 | \$1,676,003.26  | \$1,695,515.09  |
| J4S3205           |                            | Item Adjustm               |       | s Item Pay | \$19,511.83<br>\$33.30                                 | \$1,676,003.26<br>\$1,381.99                                    | \$1,695,515.09<br>\$1,415.29                                    |
| J4S3205           | Gross                      | Item Adjustm               |       | s Item Pay | \$19,511.83<br>\$33.30<br>\$19,545.13                  | \$1,676,003.26<br>\$1,381.99<br><b>\$1,677,385.25</b>           | \$1,695,515.09<br>\$1,415.29<br><b>\$1,696,930.38</b>           |
| J4S3205           | Gross<br>Incent<br>Disino  | Item Adjustm               | Gross | tem Pay    | \$19,511.83<br>\$33.30<br><b>\$19,545.13</b><br>\$0.00 | \$1,676,003.26<br>\$1,381.99<br><b>\$1,677,385.25</b><br>\$0.00 | \$1,695,515.09<br>\$1,415.29<br><b>\$1,696,930.38</b><br>\$0.00 |

Revision 4/1/2020 Page 4 of 30



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

#### **Exceptions (Discrepancies) This Estimate Period**

| Exceptions (Discrepancies) This Estimate Feriou  |                                   |               |            |
|--|-----------------------------------|---------------|------------|
| Exceptions / Discrepencies   | Explanation                       | Entered<br>By | Status     |
| Estimate Exception Type: Insufficient Materials: Project J4S3205, Item 3040506, Project Item Line Number 0090, Material Set 304050696, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.     | No Remark was entered by Engineer | schnod1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3205, Item 4019905, Project Item Line Number 0100, Material Set 401990596, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.   | No Remark was entered by Engineer | schnod1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3205, Item 6053020A, Project Item Line Number 5003, Material Set 6053020A96, Material 1011GXT1 - Geotextile Fabric for SubsrfDrainage(T1), Acceptance Action Generic 1011GXT1 is insufficient.         | No Remark was entered by Engineer | schnod1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3205, Item 6053020A, Project Item Line Number 5003, Material Set 6053020A96, Material 1009G3DRLD - Agg for Drainage Gr3 Limestone/Dolomite, Acceptance Action Generic 1009G3DRLD is insufficient.      | No Remark was entered by Engineer | schnod1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3205, Item 6053030A, Project Item Line Number 0150, Material Set 6053030A96, Material 1009G5DRLS - Agg for Drainage Gr5 Limestone, Acceptance Action Generic 1009G5DRLS is insufficient.               | No Remark was entered by Engineer | schnod1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3205, Item 6054020, Project Item Line Number 0160, Material Set 605402096, Material 1013DMPVSC4.04 - Underdrain Sch40 PVC 4" (102mm), Acceptance Action Generic 1013DMPVSC4.04 is insufficient.        | No Remark was entered by Engineer | schnod1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3205, Item 6054020, Project Item Line Number 0160, Material Set 605402096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.                            | No Remark was entered by Engineer | schnod1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3205, Item 6071102, Project Item Line Number 0180, Material Set 607110296, Material 1036RSDFPL42M13 - Reinforcing Steel No. 4/M13 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient. | No Remark was entered by Engineer | schnod1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3205, Item 6085007, Project Item Line Number 0210, Material Set 608500796, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.   | No Remark was entered by Engineer | schnod1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3205, Item 6214600A, Project Item Line Number 0450, Material Set 6214600A96, Material 0621FB - Flowable Backfill, Acceptance Action Generic 0621FB is insufficient.                                    | No Remark was entered by Engineer | schnod1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3205, Item 7201000, Project Item Line Number 0480, Material Set 720100096, Material 1052MSEWMETS - Metalic Reinforcement Strips for MSE, Acceptance Action Generic 1052MSEWMETS is insufficient.       | No Remark was entered by Engineer | schnod1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3205, Item 7201000, Project Item Line Number 0480, Material Set 720100096, Material 0720MSEW - MSE Wall System -Bridge Approved Design, Acceptance Action Generic 0720MSEW is insufficient.            | No Remark was entered by Engineer | schnod1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3205, Item 7201000, Project Item Line Number 0480, Material Set 720100096, Material 1010SGBF - Select Gran Backfill for Structural Sys, Acceptance Action Generic 1010SGBF is insufficient.            | No Remark was entered by Engineer | schnod1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3205, Item 7201000, Project Item Line Number 0480, Material Set 720100096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.                      | No Remark was entered by Engineer | schnod1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3205, Item 7201000, Project Item Line Number 0480, Material Set 720100096, Material 1013DMCRPE06 - Underdrain Corrugated PE 6" (150mm), Acceptance Action Generic 1013DMCRPE06 is insufficient.        | No Remark was entered by Engineer | schnod1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3205, Item 7201100, Project Item Line Number 0490, Material Set 720110096, Material 3099XXAS - Aesthetic Items on Project, Acceptance Action Generic 3099XXAS is insufficient.                         | No Remark was entered by Engineer | schnod1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3205, Item 9031010, Project Item Line Number 1040, Material Set 903101096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.                            | No Remark was entered by Engineer | schnod1       | Overridden |
| Estimate Exception Type: Item Overrun: Contract 200515-C12, Contract Project J4S3205, Project Item Line Number 0190, Contract Line Item Number 0190, Item 6081010, Minor Item.   | No Remark was entered by Engineer | schnod1       | Overridden |

Revision 4/1/2020 Page 5 of 30



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract<br>Nm.CONTRACT | Project<br>No. | Category | Line<br>No. | Item<br>Code | eport Generated date and can differ from the posted ame<br>Description                             | Bid<br>Quantity | Net<br>Change<br>Order | Total<br>Current<br>Quantity | Unit     | Total<br>Posted<br>Approved | Unit Price   | Total Value POSTED<br>To Date (See report<br>generated date) |
|-------------------------|----------------|----------|-------------|--------------|--|-----------------|------------------------|------------------------------|----------|-----------------------------|--------------|--|
| 200515-C12              | J4S3205        | 0001     | 0010        | 2013000      | CLEARING AND GRUBBING  | 2.00            | 0.00                   | 2.00                         | ACRE     | Qty 2.00                    | \$5.664.30   | \$11,328.60  |
|                         |                | 0001     | 0020        | 2022010      | REMOVAL OF IMPROVEMENTS  | 1.00            | 0.00                   | 1.00                         | LS       | 1.00                        | \$53,932.15  | \$53,932.15  |
|                         |                | 0001     | 0030        | 2031000      | CLASS A EXCAVATION   | 4,621.00        | 0.00                   | 4,621.00                     | CUYD     | 4,621.00                    | \$6.15       | \$28,419.15  |
|                         |                | 0001     | 0040        | 2035500      | EMBANKMENT IN PLACE  | 4,919.00        | 230.00                 | 5,149.00                     | CUYD     | 5,149.00                    | \$15.70      | \$80,839.30  |
|                         |                | 0001     | 0050        | 2036000      | COMPACTING EMBANKMENT  | 4,710.00        | 0.00                   | 4,710.00                     | CUYD     | 4,710.00                    | \$1.15       | \$5,416.50   |
|                         |                | 0001     | 0060        | 2037075      | COMPACTING IN CUT  | 14.00           | 0.00                   | 14.00                        | STA      | 14.00                       | \$1,221.55   | \$17,101.70  |
|                         |                | 0001     | 0070        | 2063000      | CLASS 3 EXCAVATION   | 994.00          | 0.00                   | 994.00                       | CUYD     | 994.00                      | \$10.15      | \$10,089.10  |
|                         |                | 0001     | 0080        | 2063300      | CLASS 4 EXCAVATION   | 1,266.00        | 0.00                   | 1,266.00                     | CUYD     | 1,266.00                    | \$5.65       | \$7,152.90   |
|                         |                | 0001     | 0090        | 3040506      | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)  | 5,943.00        | 42.00                  | 5,985.00                     | SQYD     | 5,985.00                    | \$10.10      | \$60,448.50  |
|                         |                | 0001     | 0100        | 4019905      | MISC.OPTIONAL PAVEMENT   | 4,477.50        | 0.00                   | 4,477.50                     | SQYD     | 4,477.50                    | \$54.75      | \$245,143.12   |
|                         |                | 0001     | 0110        | 5021106      | CONCRETE PAVEMENT ( 6 IN. NON-REINF)   | 270.30          | 0.00                   | 270.30                       | SQYD     | 270.30                      | \$46.30      | \$12,514.89  |
|                         |                | 0001     | 0120        | 5029905      | MISC.TINTED CONCRETE PAVEMENT (8")   | 552.20          | 0.00                   | 552.20                       | SQYD     | 552.20                      | \$94.60      | \$52,238.12  |
|                         |                |          | 0130        | 6042010      | ADJUSTING MANHOLE  | 5.00            | 0.00                   | 5.00                         | EA       | 4.00                        | \$1,450.05   | \$5,800.20   |
|                         |                | 0001     |             |              | PIPE COLLAR. TYPE C  |                 |                        |                              |          |                             |              |  |
|                         |                | 0001     | 0140        | 6044013      | PIPE AGGREGATE PAVEMENT EDGE DRAIN   | 1.00            | 0.00                   | 1.00                         | EA<br>LF | 1.00                        | \$1,788.05   | \$1,788.05   |
|                         |                | 0001     | 0150        | 6053030A     |  | 217.00          | 0.00                   | 217.00                       |          | 217.00                      | \$17.60      | \$3,819.20   |
|                         |                | 0001     | 0160        | 6054020      | OUTLET PIPES AND SPLASH PADS   | 1.00            | 0.00                   | 1.00                         | EA       | 1.00                        | \$1,775.40   | \$1,775.40   |
|                         |                | 0001     | 0170        | 6071050      | CHAIN-LINK FENCE (RETAINING WALLS)   | 469.00          | -469.00                | 0.00                         | LF       | 0.00                        | \$55.15      | \$0.00   |
|                         |                | 0001     | 0180        | 6071102      | MODIFIED CONCRETE GUTTER TYPE B  | 306.00          | 0.00                   | 306.00                       | LF       | 306.00                      | \$25.80      | \$7,894.80   |
|                         |                | 0001     | 0190        | 6081010      | CONCRETE CURB RAMP   | 241.20          | 0.00                   | 241.20                       | SQYD     | 272.62                      | \$47.25      | \$12,881.30  |
|                         |                | 0001     | 0200        | 6081012      | TRUNCATED DOMES  | 346.00          | 0.00                   | 346.00                       | SQFT     | 346.00                      | \$19.60      | \$6,781.60   |
|                         |                | 0001     | 0210        | 6085007      | PAVED APPROACH, 7 IN.  | 52.00           | 25.30                  | 77.30                        | SQYD     | 77.30                       | \$58.60      | \$4,529.78   |
|                         |                | 0001     | 0220        | 6086004      | CONCRETE SIDEWALK, 4 IN.   | 857.10          | -4.30                  | 852.80                       | SQYD     | 852.80                      | \$31.30      | \$26,692.64  |
|                         |                | 0001     | 0230        | 6091052      | CURB AND GUTTER TYPE B   | 1,816.00        | -232.00                | 1,584.00                     | LF       | 1,584.00                    | \$28.00      | \$44,352.00  |
|                         |                | 0001     | 0240        | 6092011      | INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A  | 217.00          | 0.00                   | 217.00                       | LF       | 217.00                      | \$17.80      | \$3,862.60   |
|                         |                | 0001     | 0250        | 6092031      | CONCRETE CURB LOW PROFILE TYPE E   | 614.00          | 0.00                   | 614.00                       | LF       | 613.90                      | \$17.50      | \$10,743.25  |
|                         |                | 0001     | 0260        | 6097000      | ROCK LINING  | 21.00           | 0.00                   | 21.00                        | CUYD     | 21.00                       | \$93.85      | \$1,970.85   |
|                         |                | 0001     | 0270        | 6099903      | MISC.APWA CURB AND GUTTER TYPE CG-1  | 1,286.00        | 232.00                 | 1,518.00                     | LF       | 1,518.00                    | \$19.95      | \$30,284.10  |
|                         |                | 0001     | 0280        | 6141024      | GRATE AND BEARING PLATE (5 FT. X 3 FT. OR 1524 MM X 914 MM)  | 1.00            | 0.00                   | 1.00                         | EA       | 1.00                        | \$3,340.20   | \$3,340.20   |
|                         |                | 0001     | 0290        | 6141120      | CURVED VANE GRATE AND FRAME (2 FT. X 2 FT. OR 600MM X 600MM)                                       | 1.00            | 0.00                   | 1.00                         | EA       | 1.00                        | \$2,558.90   | \$2,558.90   |
|                         |                | 0001     | 0300        | 6143014      | MANHOLE FRAME AND COVER, TYPE 4  | 4.00            | 0.00                   | 4.00                         | EA       | 4.00                        | \$1,510.05   | \$6,040.20   |
|                         |                | 0001     | 0310        | 6161005      | CONSTRUCTION SIGNS   | 1,604.00        | 0.00                   | 1,604.00                     | SQFT     | 1,604.00                    | \$8.40       | \$13,473.60  |
|                         |                | 0001     | 0320        | 6161008      | ADVANCED WARNING RAIL SYSTEM   | 8.00            | 0.00                   | 8.00                         | EA       | 8.00                        | \$89.25      | \$714.00   |
|                         |                | 0001     | 0330        | 6161009      | FLAG ASSEMBLY  | 4.00            | 0.00                   | 4.00                         | EA       | 4.00                        | \$26.25      | \$105.00   |
|                         |                | 0001     | 0340        | 6161025      | CHANNELIZER (TRIM LINE)  | 20.00           | 0.00                   | 20.00                        | EA       | 20.00                       | \$21.00      | \$420.00   |
|                         |                | 0001     | 0350        | 6161030      | TYPE III MOVEABLE BARRICADE  | 20.00           | 0.00                   | 20.00                        | EA       | 20.00                       | \$225.75     | \$4,515.00   |
|                         |                | 0001     | 0360        | 6161098A     | CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED | 4.00            | 0.00                   | 4.00                         | EA       | 4.00                        | \$5,250.00   | \$21,000.00  |
|                         |                | 0001     | 0370        | 6181000      | MOBILIZATION   | 1.00            | 0.00                   | 1.00                         | LS       | 1.00                        | \$142,362.50 | \$142,362.50   |
|                         |                | 0001     | 0380        | 6181020      | ADDITIONAL MOBILIZATION FOR SEEDING  | 4.00            | 0.00                   | 4.00                         | EA       | 0.00                        | \$600.00     | \$0.00   |
|                         |                | 0001     | 0390        | 6200009      | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE  | 54.00           | 0.00                   | 54.00                        | LF       | 54.00                       | \$9.45       | \$510.30   |
|                         |                | 0001     | 0400        | 6200036      | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK                                     | 24.00           | 0.00                   | 24.00                        | EA       | 24.00                       | \$189.00     | \$4,536.00   |
|                         |                | 0001     | 0410        | 6200042      | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES                        | 36.00           | 0.00                   | 36.00                        | EA       | 36.00                       | \$36.75      | \$1,323.00   |
|                         |                | 0001     | 0420        | 6205901A     | 4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT<br>MARKING PAINT, TYPE L BEADS                         | 2,549.00        | 0.00                   | 2,549.00                     | LF       | 2,549.00                    | \$0.45       | \$1,147.05   |
|                         |                | 0001     | 0430        | 6205902A     | 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS                             | 2,279.00        | 0.00                   | 2,279.00                     | LF       | 2,279.00                    | \$0.65       | \$1,481.35   |
|                         |                | 0001     | 0440        | 6205903A     | 6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT<br>MARKING PAINT, TYPE L BEADS                         | 320.00          | 0.00                   | 320.00                       | LF       | 320.00                      | \$0.65       | \$208.00   |

Page 6 of 30 Revision 4/1/2020



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| ote: Posted Q           | uantities      | and Valu | es are b    | ased on R    | eport Generated date and can differ from the posted am     | ount at the     | e time the             | Estimate wa                  | is Gene | rated.                             |             |  |
|-------------------------|----------------|----------|-------------|--------------|--|-----------------|------------------------|------------------------------|---------|------------------------------------|-------------|--|
| Contract<br>Nm.CONTRACT | Project<br>No. | Category | Line<br>No. | Item<br>Code | Description  | Bid<br>Quantity | Net<br>Change<br>Order | Total<br>Current<br>Quantity | Unit    | Total<br>Posted<br>Approved<br>Qty | Unit Price  | Total Value POSTED<br>To Date (See report<br>generated date) |
| 200515-C12              | J4S3205        | 0001     | 0450        | 6214600A     | FLOWABLE BACKFILL  | 38.00           | 0.00                   | 38.00                        | CUYD    | 38.00                              | \$172.75    | \$6,564.50   |
|                         |                | 0001     | 0460        | 6274000      | CONTRACTOR FURNISHED SURVEYING AND STAKING                 | 1.00            | 0.00                   | 1.00                         | LS      | 1.00                               | \$10,741.50 | \$10,741.50  |
|                         |                | 0001     | 0470        | 7110400      | SACRIFICIAL GRAFFITI PROTECTION SYSTEM                     | 1.00            | 0.00                   | 1.00                         | LS      | 1.00                               | \$5,268.95  | \$5,268.95   |
|                         |                | 0001     | 0480        | 7201000      | MECHANICALLY STABILIZED EARTH WALL SYSTEMS                 | 4,290.00        | -695.00                | 3,595.00                     | SQFT    | 3,595.00                           | \$78.75     | \$283,106.25   |
|                         |                | 0001     | 0490        | 7201100      | FORM LINERS FOR MSE WALL SYSTEMS                           | 476.00          | -77.00                 | 399.00                       | SQYD    | 399.00                             | \$1.15      | \$458.85   |
|                         |                | 0001     | 0500        | 7250315A     | 15 IN. PIPE GROUP B  | 296.00          | 0.00                   | 296.00                       | LF      | 296.00                             | \$70.25     | \$20,794.00  |
|                         |                | 0001     | 0510        | 7250318A     | 18 IN. PIPE GROUP B  | 64.00           | 0.00                   | 64.00                        | LF      | 64.00                              | \$82.20     | \$5,260.80   |
|                         |                | 0001     | 0520        | 7250324A     | 24 IN. PIPE GROUP B  | 390.00          | 0.00                   | 390.00                       | LF      | 390.00                             | \$83.45     | \$32,545.50  |
|                         |                | 0001     | 0530        | 7250336A     | 36 IN. PIPE GROUP B  | 20.00           | 0.00                   | 20.00                        | LF      | 20.00                              | \$130.15    | \$2,603.00   |
|                         |                | 0001     | 0540        | 7250348A     | 48 IN. PIPE GROUP B  | 284.00          | 0.00                   | 284.00                       | LF      | 284.00                             | \$122.55    | \$34,804.20  |
|                         |                | 0001     | 0550        | 7261015      | 15 IN. PIPE GROUP A  | 147.00          | 0.00                   | 147.00                       | LF      | 147.00                             | \$72.85     | \$10,708.95  |
|                         |                | 0001     | 0560        | 7261024      | 24 IN. PIPE GROUP A  | 50.00           | 0.00                   | 50.00                        | LF      | 50.00                              | \$91.95     | \$4,597.50   |
|                         |                | 0001     | 0570        | 7310048      | PRECAST CONCRETE MANHOLE - 48 IN.                          | 6.00            | 0.00                   | 6.00                         | FT      | 6.00                               | \$545.75    | \$3,274.50   |
|                         |                | 0001     | 0580        | 7310072      | PRECAST CONCRETE MANHOLE - 72 IN.                          | 45.00           | 0.00                   | 45.00                        | FT      | 45.00                              | \$650.40    | \$29,268.00  |
|                         |                | 0001     | 0590        | 7311022      | PRECAST CONCRETE DROP INLET 2 FT X 2 FT                    | 4.00            | 0.00                   | 4.00                         | FT      | 4.00                               | \$1,219.65  | \$4,878.60   |
|                         |                | 0001     | 0600        | 7311053      | PRECAST CONCRETE DROP INLET 5 FT X 3 FT                    | 5.00            | 0.00                   | 5.00                         | FT      | 5.00                               | \$1,435.85  | \$7,179.25   |
|                         |                | 0001     | 0610        | 7319902      | MISC.APWA 5' x 5' Junction Box                             | 1.00            | 0.00                   | 1.00                         | EA      | 1.00                               | \$4,369.35  | \$4,369.35   |
|                         |                | 0001     | 0620        | 7319902      | MISC.APWA TYPE 2 5' X 3' CURB INLET                        | 8.00            | 0.00                   | 8.00                         | EA      | 8.00                               | \$4,337.35  | \$34,698.80  |
|                         |                | 0001     | 0630        | 7319902      | MISC.APWA TYPE 2 5' X 4' CURB INLET                        | 1.00            | 0.00                   | 1.00                         | EA      | 1.00                               | \$5,063.50  | \$5,063.50   |
|                         |                | 0001     | 0640        | 7320015A     | 15 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END<br>SECTION | 3.00            | 0.00                   | 3.00                         | EA      | 3.00                               | \$1,037.50  | \$3,112.50   |
|                         |                | 0001     | 0650        | 7320018A     | 18 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION    | 1.00            | 0.00                   | 1.00                         | EA      | 1.00                               | \$1,072.35  | \$1,072.35   |
|                         |                |          | 0660        | 7320036A     | 36 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION    | 1.00            | 0.00                   | 1.00                         | EA      | 1.00                               | \$1,590.35  | \$1,590.35   |
|                         |                |          | 0670        | 7320048A     | 48 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION    | 1.00            | 0.00                   | 1.00                         | EA      | 1.00                               | \$2,391.90  | \$2,391.90   |
|                         |                | 0001     | 0680        | 8032000A     | KENTUCKY BLUEGRASS SODDING                                 | 860.00          | 0.00                   | 860.00                       | SQYD    | 860.00                             | \$7.30      | \$6,278.00   |
|                         |                | 0001     | 0690        | 8034000      | BUFFALOGRASS SODDING                                       | 404.00          | 0.00                   | 404.00                       | SQYD    | 404.00                             | \$18.55     | \$7,494.20   |
|                         |                | 0001     | 0700        | 8051000A     | SEEDING - COOL SEASON MIXTURES                             | 1.10            | 0.00                   | 1.10                         | ACRE    | 1.10                               | \$3,286.50  | \$3,615.15   |
|                         |                | 0001     | 0710        | 8061005      | ROCK DITCH CHECK   | 19.00           | 0.00                   | 19.00                        | LF      | 0.00                               | \$45.40     | \$0.00   |
|                         |                | 0001     | 0720        | 8061007A     | CURB INLET CHECK   | 10.00           | 0.00                   | 10.00                        | EA      | 6.00                               | \$68.25     | \$409.50   |
|                         |                | 0001     | 0730        | 8061016      | SEDIMENT REMOVAL   | 22.00           | 0.00                   | 22.00                        | CUYD    | 0.00                               | \$63.45     | \$0.00   |
|                         |                | 0001     | 0740        | 8061017      | TEMPORARY SEEDING AND MULCHING                             | 1.10            | 0.00                   | 1.10                         | ACRE    | 0.00                               | \$2,205.00  | \$0.00   |
|                         |                | 0001     | 0750        | 8061019      | SILT FENCE   | 692.00          | 0.00                   | 692.00                       | LF      | 340.00                             | \$1.60      | \$544.00   |
|                         |                | 0001     | 0760        | 8089902      | MISC.CARPINUS BETULUS, 'COLUMNARIS'                        | 3.00            | 0.00                   | 3.00                         | EA      | 3.00                               | \$635.25    | \$1,905.75   |
|                         |                | 0001     | 0770        | 8089902      | MISC.RHUS AROMATICA, 'GRO-LOW'                             | 18.00           | 0.00                   | 18.00                        | EA      | 18.00                              | \$70.35     | \$1,266.30   |
|                         |                | 0001     | 0780        | 8089902      | MISC.VIBURNUM, 'BLUE MUFFIN'                               | 18.00           | 0.00                   | 18.00                        | EA      | 18.00                              | \$83.50     | \$1,503.00   |
|                         |                | 0020     | 0790        | 9019902      | MISC.150W LED KCMO TYPE B LUMINAIRE                        | 1.00            | 0.00                   | 1.00                         | EA      | 1.00                               | \$430.10    | \$430.10   |
|                         |                | 0020     | 0800        | 9019902      | MISC.250W LED KCMO TYPE C LUMINAIRE                        | 1.00            | 0.00                   | 1.00                         | EA      | 1.00                               | \$557.65    | \$557.65   |
|                         |                | 0020     | 0810        | 9019902      | MISC.400W LED KCMO PARKS LUMINAIRE                         | 8.00            | 0.00                   | 8.00                         | EA      | 8.00                               | \$2,303.05  | \$18,424.40  |
|                         |                | 0020     | 0820        | 9019902      | MISC.400W LED KCMO TYPE D LUMINAIRE                        | 1.00            | 0.00                   | 1.00                         | EA      | 1.00                               | \$750.00    | \$750.00   |
|                         |                | 0020     | 0830        | 9019902      | MISC.KCMO 6" ANTI-THEFT CABLE RETAINER ASSEMBLY            | 2.00            | 0.00                   | 2.00                         | EA      | 2.00                               | \$63.40     | \$126.80   |
|                         |                | 0020     | 0840        | 9019902      | MISC.KCMO 8" ANTI-THEFT CABLE RETAINER ASSEMBLY            | 9.00            | 0.00                   | 9.00                         | EA      | 9.00                               | \$74.85     | \$673.65   |
|                         |                | 0020     | 0850        | 9019902      | MISC.KCMO APWA 6" SCREW-IN POLE FOUNDATION                 | 2.00            | 0.00                   | 2.00                         | EA      | 2.00                               | \$928.20    | \$1,856.40   |
|                         |                | 0020     | 0860        | 9019902      | MISC.KCMO APWA 8" SCREW-IN POLE FOUNDATION                 | 8.00            | 0.00                   | 8.00                         | EA      | 8.00                               | \$1,104.90  | \$8,839.20   |
|                         |                | 0020     | 0870        | 9019902      | MISC.KCMO APWA LIGHTING POLE, 35 FT                        | 8.00            | 0.00                   | 8.00                         | EA      | 8.00                               | \$1,703.95  | \$13,631.60  |
|                         |                | 0020     | 0880        | 9019902      | MISC.KCMO CONDUIT MARKERS                                  | 6.00            | 0.00                   | 6.00                         | EA      | 6.00                               | \$138.90    | \$833.40   |
|                         |                |          |             |              |  |                 |                        |                              |         | 22.00                              |             |  |

Page 7 of 30 Revision 4/1/2020



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract<br>Im.CONTRACT | Project<br>No. | Category    | Line<br>No. | Item<br>Code  | Description  | Bid<br>Quantity | Net<br>Change<br>Order | Total<br>Current<br>Quantity | Unit | Total<br>Posted<br>Approved<br>Qty | Unit Price | Total Value POSTED<br>To Date (See report<br>generated date) |
|-------------------------|----------------|-------------|-------------|---------------|--|-----------------|------------------------|------------------------------|------|------------------------------------|------------|--|
| 00515-C12               | J4S3205        | 0020        | 0900        | 9019902       | MISC.KCMO CONNECTOR KITS - UNFUSED                       | 11.00           | 0.00                   | 11.00                        | EA   | 11.00                              | \$73.10    | \$804.10   |
|                         |                | 0020        | 0910        | 9019902       | MISC.KCMO GROUND ROD                                     | 1.00            | 0.00                   | 1.00                         | EA   | 1.00                               | \$180.50   | \$180.50   |
|                         |                | 0020        | 0920        | 9019902       | MISC.KCMO LIGHT POLE AND CONTROLLER ID MARKERS           | 11.00           | 0.00                   | 11.00                        | EA   | 11.00                              | \$29.80    | \$327.80   |
|                         |                | 0020        | 0930        | 9019902       | MISC.KCMO LIGHTING POLE, 30 FT                           | 2.00            | 0.00                   | 2.00                         | EA   | 2.00                               | \$1,346.50 | \$2,693.00   |
|                         |                | 0020        | 0940        | 9019902       | MISC.LIGHTING CONTROLLER, 240V 2-CIRCUIT WITH FOUNDATION | 1.00            | 0.00                   | 1.00                         | EA   | 1.00                               | \$6,226.30 | \$6,226.30   |
|                         |                | 0020        | 0950        | 9019902       | MISC.PULL BOX, KCMO TYPE 2                               | 2.00            | 0.00                   | 2.00                         | EA   | 2.00                               | \$471.65   | \$943.3  |
|                         |                | 0020        | 0960        | 9019903       | MISC.KCMO CABLE, 10 AWG 1 CONDUCTOR (RHH/RHW/USE)        | 920.00          | 0.00                   | 920.00                       | LF   | 920.00                             | \$1.35     | \$1,242.00   |
|                         |                | 0020        | 0970        | 9019903       | MISC.KCMO CABLE, 4 AWG 1 CONDUCTOR (RHH/RHW/USE)         | 300.00          | 0.00                   | 300.00                       | LF   | 300.00                             | \$2.20     | \$660.00   |
|                         |                | 0020        | 0980        | 9019903       | MISC.KCMO CABLE, 6 AWG 1 CONDUCTOR (RHH/RHW/USE)         | 3,104.00        | 0.00                   | 3,104.00                     | LF   | 3,104.00                           | \$1.80     | \$5,587.20   |
|                         |                | 0020        | 0990        | 9019903       | MISC.KCMO CABLE, 6 AWG 1 CONDUCTOR BARE (RHH/RHW/USE)    | 1,552.00        | 0.00                   | 1,552.00                     | LF   | 1,552.00                           | \$1.45     | \$2,250.40   |
|                         |                | 0020        | 1000        | 9019903       | MISC.KCMO CONDUIT, 2 IN. PVC, SCHEDULE 40, IN TRENCH     | 1,170.00        | 0.00                   | 1,170.00                     | LF   | 1,170.00                           | \$1.90     | \$2,223.0  |
|                         |                | 0020        | 1010        | 9019903       | MISC.KCMO CONDUIT, 3 IN. PVC, SCHEDULE 40, IN TRENCH     | 100.00          | 0.00                   | 100.00                       | LF   | 100.00                             | \$2.20     | \$220.0  |
|                         |                | 0020        | 1020        | 9019903       | MISC.KCMO CONDUIT, 4 IN. RIGID, PUSHED                   | 251.00          | 0.00                   | 251.00                       | LF   | 251.00                             | \$4.75     | \$1,192.2  |
|                         |                | 0020        | 1030        | 9019903       | MISC.KCMO TRENCHING                                      | 1,429.00        | 0.00                   | 1,429.00                     | LF   | 1,429.00                           | \$14.40    | \$20,577.6   |
|                         |                | 0040        | 1040        | 9031010       | CONCRETE FOOTINGS, EMBEDDED                              | 0.40            | 0.00                   | 0.40                         | CUYD | 0.40                               | \$2,100.00 | \$840.0  |
|                         |                | 0040        | 1050        | 9031241       | BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE)        | 4.00            | 0.00                   | 4.00                         | EA   | 4.00                               | \$262.50   | \$1,050.0  |
|                         |                | 0040        | 1060        | 9031270A      | 2 IN. PSST POST - 12 GA.                                 | 329.00          | 0.00                   | 329.00                       | LF   | 329.00                             | \$12.10    | \$3,980.9  |
|                         |                | 0040        | 1070        | 9031271       | POST ANCHOR FOR 2 IN. PSST - 12 GA.                      | 78.00           | 0.00                   | 78.00                        | LF   | 78.00                              | \$24.15    | \$1,883.7  |
|                         |                | 0040        | 1080        | 9031272       | 2.25 IN. PSST POST - 12 GA.                              | 28.00           | 0.00                   | 28.00                        | LF   | 28.00                              | \$12.60    | \$352.8  |
|                         |                | 0040        | 1090        | 9031280       | 2.5 IN. PSST POST - 12 GA.                               | 168.00          | 0.00                   | 168.00                       | LF   | 168.00                             | \$15.75    | \$2,646.0  |
|                         |                | 0040        | 1100        | 9031281       | POST ANCHOR FOR 2.5 IN. PSST - 7 GA.                     | 36.00           | 0.00                   | 36.00                        | LF   | 36.00                              | \$47.25    | \$1,701.0  |
|                         |                | 0040        | 1110        | 9035004A      | SH-FLAT SHEET  | 129.00          | 0.00                   | 129.00                       | SQFT | 129.00                             | \$25.20    | \$3,250.8  |
|                         |                | 0040        | 1120        | 9035069A      | SHF-FLAT SHEET FLUORESCENT                               | 166.00          | 0.00                   | 166.00                       | SQFT | 166.00                             | \$27.85    | \$4,623.1  |
|                         |                | 0001        | 5001        | 6079903       | MISC.FENCING   | 0.00            | 469.00                 | 469.00                       | LF   | 469.00                             | \$120.96   | \$56,730.2   |
|                         |                | 0001        | 5002        | 1046002       | VALUE ENGINEERING  | 0.00            | 27,269.05              | 27,269.05                    | EA   | 27,269.05                          | \$1.00     | \$27,269.0   |
|                         |                | 0001        | 5003        | 6053020A      | FRENCH UNDERDRAIN  | 0.00            | 70.00                  | 70.00                        | LF   | 70.00                              | \$135.65   | \$9,495.5  |
|                         |                | 0001        | 5004        | 6049902       | MISC.MANHOLE LID   | 0.00            | 1.00                   | 1.00                         | EA   | 1.00                               | \$267.00   | \$267.0  |
|                         | Project J      | 4S3205 - To | otal Value  | Posted to D   | Date as of Report Generated Date                         |                 |                        |                              |      |                                    |            | \$1,695,796.7  |
| 0515-C12 Ove            | erall - Total  | Value Pos   | ted to Da   | te as of Repo | ort Generated Date                                       |                 |                        |                              |      |                                    |            | \$1,695,796.   |

Page 8 of 30 Revision 4/1/2020



## Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J4S3205

| Line<br>Number | Item<br>Code | Description                             | DWR<br>Date | DWR<br>Approval<br>Date | Quantity<br>Posted | Units | Location  | From<br>Station/<br>Log<br>Mile | Offset/<br>Distance | To<br>Station/<br>Log<br>Mile | Offset/<br>Distance | Comments |
|----------------|--------------|---|-------------|-------------------------|--------------------|-------|---|---------------------------------|---------------------|-------------------------------|---------------------|----------|
| 0040           | 2035500      | EMBANKMENT IN PLACE                     | 3/12/21     | 3/16/21                 | 230.00             | CUYD  | CO 3  | 0                               |                     | 0                             |                     |          |
| 0090           | 3040506      | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) | 3/12/21     | 3/16/21                 | 42.00              | SQYD  | CO 3  | 0                               |                     | 0                             |                     |          |
| 0120           | 5029905      | MISC.                                   | 3/12/21     | 3/16/21                 | 0.10               | SQYD  | Rounding.   | 0                               |                     | 0                             |                     |          |
| 0210           | 6085007      | PAVED APPROACH, 7 IN.                   | 3/12/21     | 3/16/21                 | 25.30              | SQYD  | CO 3  | 0                               |                     | 0                             |                     |          |
| 0220           | 6086004      | CONCRETE SIDEWALK, 4 IN.                | 3/12/21     | 3/16/21                 | -13.30             | SQYD  | Correction from payment of sidewalk that was changed into paved approach on CO 3. | 0                               |                     | 0                             |                     |          |
| 0270           | 6099903      | MISC. PAVED DRAINAGE                    | 3/12/21     | 3/16/21                 | 232.50             | LF    | CO 3  | 0                               |                     | 0                             |                     |          |
| 5003           | 6053020A     | FRENCH UNDERDRAIN                       | 3/12/21     | 3/16/21                 | 70.00              | LF    |   | 0                               |                     | 0                             |                     |          |
| 5004           | 6049902      | MISC. DRAINAGE ITEM                     | 3/12/21     | 3/16/21                 | 1.00               | EA    |   | 0                               |                     | 0                             |                     |          |

| 0270               | 6099903   | MISC. PAVED DRAIN      | AGE 3/12/21                               | 1 3/16/                  | 21 23                            | 32.50                 | LF                 | CO 3     |         |                    |  | 0    |            |       | )       |                        |                      |                 |
|--------------------|-----------|------------------------|---|--------------------------|----------------------------------|-----------------------|--------------------|----------|---------|--------------------|--|------|------------|-------|---------|------------------------|----------------------|-----------------|
|                    |           | FRENCH UNDERDRA        |   |                          |                                  | 70.00                 | LF                 |          |         |                    |  | 0    |            |       |         |                        |                      |                 |
| 5004               |           | MISC. DRAINAGE ITE     |   |                          |                                  | 1.00                  | EA                 |          |         |                    |  | 0    |            |       | )       |                        |                      |                 |
|                    |           |                        | letails for Construction Signs (if ap     | pplica                   |                                  |                       |                    |          |         |                    |  |      |            |       |         |                        |                      |                 |
| Project<br>I4S3205 | Line Numb | DWR Date June 18, 2020 | Total Quantity Posted For DWR Date<br>268 | WOOD                     | Sign<br>-3 48x4                  |                       | mation             |          | Station | Log Mile           | Location<br>Prather Road                 | 1.00 | r of Items | SF Ea | ch Sign | Special Sign           | SF Each Special Sign | Total SF to Pos |
| 1433203            | 0310      | Julie 16, 2020         | 200                                       | CLOSI                    | ED AHEAI                         | AD 10                 | .00 ROAL           | <b>'</b> |         | .004               | Flatilet Road                            | 1.00 |            | 10    |         |                        |                      |                 |
|                    |           |                        |   |                          | -3 48x4<br>ED AHEAI              |                       | .00 ROAI           | )        |         | 1.33               | Prather Road                             | 1.00 |            | 16    |         |                        |                      |                 |
|                    |           |                        |   |                          | 60x30                            |                       | 0 ROAD             |          |         | .971               | Parvin Road                              | 2.00 |            | 12.5  |         |                        |                      |                 |
|                    |           |                        |   |                          | ED TO TH                         |                       |                    |          |         |                    |  |      |            |       |         |                        |                      |                 |
|                    |           |                        |   | WO20<br>CLOSI            | -3 48x4<br>ED AHEAI              | 48 16<br>AD           | .00 ROAI           | )        |         | 0.928              | Parvin Road                              | 1.00 |            | 16    |         |                        |                      |                 |
|                    |           |                        |   | R11-4                    | 60x30                            | 0 12.5                | 0 ROAD             |          |         | 0.947              | Prather Road                             | 2.00 |            | 12.5  |         |                        |                      |                 |
|                    |           |                        |   |                          | ED TO TH                         |                       |                    |          |         | 0.004              | Parvin Road                              | 4.00 |            | 40    |         |                        |                      |                 |
|                    |           |                        |   | CLOSI                    | -3a 4x4<br>ED 500 F1             | T 10.                 | OU NOAD            |          |         | 0.991              | Fai viii Roau                            | 1.00 |            | 16    |         |                        |                      |                 |
|                    |           |                        |   | R11-2<br>CLOSI           | 48x30                            | 0 10.0                | 00 ROAD            |          |         | 1.025              | Prather Road                             | 1.00 |            | 10    |         |                        |                      |                 |
|                    |           |                        |   |                          | 48x30                            | 0 10.0                | 0 ROAD             |          |         | 1.046              | Parvin Road                              | 1.00 |            | 10    |         |                        |                      |                 |
|                    |           |                        |   | CLOS                     |                                  |                       |                    |          |         |                    |  |      |            |       |         |                        |                      |                 |
|                    |           |                        |   | WO20<br>CLOSI            | -3 48x4<br>ED AHEAI              | 48 16<br>AD           | .00 ROAI           | )        |         | 1.138              | Parvin Road                              | 1.00 |            | 16    |         |                        |                      |                 |
|                    |           |                        |   | R11-2                    | 48x30                            | 0 10.0                | 00 ROAD            |          |         | 1.141              | Prather Road                             | 1.00 |            | 10    |         |                        |                      |                 |
|                    |           |                        |   | CLOSI                    |                                  | 1 16                  | 00 BOAD            |          |         | 1 107              | Brother Reed                             | 1.00 |            | 16    |         |                        |                      |                 |
|                    |           |                        |   | CLOS                     | -3a 4x4<br>ED 500 F1             | T 10.                 | JU RUAL            |          |         | 1.187              | Prather Road                             | 1.00 |            | 16    |         |                        |                      |                 |
|                    |           |                        |   | R11-4<br>CLOS            | 60x30<br>ED TO TH                | 0 12.5<br>HRUT        | 0 ROAD             |          |         | 1.187              | Prather Road                             | 2.00 |            | 12.5  |         |                        |                      |                 |
|                    |           |                        |   | WO20                     | -3a 4x4                          | 4 16.                 |                    | ,        |         | 1.215              | Parvin Road                              | 1.00 |            | 16    |         |                        |                      |                 |
|                    |           |                        |   | CLOSI                    | ED 500 FT                        | т                     |                    |          |         |                    |  |      |            |       |         |                        |                      |                 |
|                    |           |                        |   |                          | 60x30<br>ED TO TH                |                       |                    |          |         | 1.215              | Parvin Road                              | 2.00 |            | 12.5  |         |                        |                      |                 |
|                    |           |                        |   |                          | 48x30                            | 0 10.0                | 00 ROAD            |          |         | 1.216              | Parvin Road                              | 1.00 |            | 10    |         |                        |                      |                 |
|                    |           |                        |   | CLOSI                    | ED<br>⊩3a 4x4                    | 1 16                  | OU BOAD            | ,        |         | .947               | Prather Road                             | 1.00 |            | 16    |         |                        |                      |                 |
|                    |           |                        |   |                          | ED 500 F1                        |                       | OU NOAD            |          |         | .541               | Transfittoau                             | 1.00 |            | 10    |         |                        |                      |                 |
|                    |           |                        | 1336                                      |                          | Ba 24x1                          |                       |                    |          |         | .056               | Prather Road                             | 1.00 |            | 3     |         |                        |                      |                 |
|                    |           |                        |   | CLOSI                    | a 60x30<br>ED XX MII<br>FIC ONLY | IILES A               | 50 ROAD<br>MEAD LO | DCAL     |         | .1                 | Prather Road                             | 1.00 |            | 12.5  |         |                        |                      | •               |
|                    |           |                        |   | See S                    | pecial Sigr                      | gn Deta               | ails               |          |         | .239               | 210                                      | 1.00 |            |       |         | MO4-11-36              | 19.50                |                 |
|                    |           |                        |   | WO20                     | l-2 48x4<br>D                    | 48 16                 | .00 DETC           | DUR      |         | .629               | Parvin Road                              | 1.00 |            | 16    |         |                        |                      |                 |
|                    |           |                        |   |                          | pecial Sigr                      | n Deta                | ails               |          |         | .758               | Parvin Road                              | 1.00 |            |       |         | M04-11-42              | 21.00                |                 |
|                    |           |                        |   | R11-3                    | a 60x30<br>ED XX MII<br>FIC ONLY | 0 12.                 | 50 ROAD            |          |         | .77                | Parvin Road                              | 1.00 |            | 12.5  |         |                        |                      | 1               |
|                    |           |                        |   |                          | pecial Sigr                      |                       | ails               |          |         | .77                | Parvin Road                              | 2.00 |            |       |         | M04-11-42              | 21.00                |                 |
|                    |           |                        |   |                          | pecial Sigr                      |                       |                    |          |         | .865               | 210                                      | 1.00 |            |       |         | MO4-11-36              | 19.50                | 1               |
|                    |           |                        |   | CLOSI                    | a 60x30<br>ED XX MII<br>FIC ONLY | IILES A               | 50 ROAD<br>MEAD LO | DCAL     |         | 0.632              | Parvin Road                              | 1.00 |            | 12.5  |         |                        |                      |                 |
|                    |           |                        |   | WO20                     | -2 48x4                          |                       | .00 DETC           | DUR      |         | 0.83               | 210                                      | 1.00 |            | 16    |         |                        |                      |                 |
|                    |           |                        |   | AHEA                     | D                                |                       |                    |          |         |                    |  |      |            |       |         |                        |                      |                 |
|                    |           |                        |   |                          | pecial Sigr                      |                       |                    |          |         | 1.113              | 210                                      | 1.00 |            |       |         | MO4-11-36              | 19.50                | 1               |
|                    |           |                        |   |                          | pecial Sigr<br>pecial Sigr       |                       |                    |          |         | 1.258              | 210                                      | 2.00 |            |       |         | MO4-11-36              | 19.50<br>19.50       |                 |
|                    |           |                        |   |                          | peciai Sigi<br>I-2 48x4          |                       |                    | DUR      |         | 1.552              | 135                                      | 1.00 |            | 16    |         | MO4-11-36              | 19.50                |                 |
|                    |           |                        |   | AHEA                     | D                                |                       |                    |          |         |                    | 117                                      |      |            |       |         |                        |                      |                 |
|                    |           |                        |   |                          | pecial Sigr                      |                       |                    |          |         | 104.217            | 135                                      | 1.00 |            |       |         | MO4-11-36              | 19.50                | 1               |
|                    |           |                        |   |                          | pecial Sigr                      |                       |                    |          |         | 104.969            | 135                                      | 2.00 |            |       |         | MO4-11-36              | 19.50                |                 |
|                    |           |                        |   |                          | pecial Sigr                      |                       |                    |          |         | 105.168            | 135                                      | 1.00 |            |       |         | MO4-11-36              | 19.50                | 1               |
|                    |           |                        |   |                          | pecial Sigr<br>pecial Sigr       |                       |                    |          |         | 105.447<br>106.593 | 135                                      | 1.00 |            |       |         | MO4-11-36<br>MO4-11-36 | 19.50                | 1               |
|                    |           |                        |   |                          | pecial Sigr                      |                       |                    |          |         | 107.169            | 135                                      | 1.00 |            |       |         | MO4-11-36              | 19.50                | 1               |
|                    |           |                        |   |                          | pecial Sigr                      |                       |                    |          |         | 2.065              | Chouteau Trafficway                      | 1.00 |            |       |         | MO4-11-36              | 19.50                | 1               |
|                    |           |                        |   |                          | pecial Sigr                      |                       |                    |          |         | 2.065              | Chouteau Trafficway                      | 1.00 |            |       |         | M04-11-42              | 21.00                |                 |
|                    |           |                        |   |                          | pecial Sigr                      |                       |                    |          |         | 2.32               | Chouteau Trafficway                      | 1.00 |            |       |         | M04-11-42              | 21.00                |                 |
|                    |           |                        |   | R11-3:<br>CLOSI<br>TRAFF | a 60x30<br>ED XX MII<br>FIC ONLY | 0 12.<br>IILES A<br>Y | 50 ROAD<br>HEAD LO | DCAL     |         | 2.32               | Parvin Road                              | 1.00 |            | 12.5  |         |                        |                      | •               |
|                    |           |                        |   |                          | pecial Sigr                      |                       | ails               |          |         | 2.385              | Chouteau Trafficway                      | 1.00 |            |       |         | M04-11-42              | 21.00                |                 |
|                    |           |                        |   | MO4-8                    | Ba 24x1                          | 18 3.                 | 00 END D           | ETOUR    |         | 2.485              | Parvin Road                              | 1.00 |            | 3     |         |                        |                      |                 |
|                    |           |                        |   | See S                    | pecial Sigr                      | gn Deta               | ails               |          |         | 2.781              | Chouteau Trafficway                      | 1.00 |            |       |         | MO4-11-36              | 19.50                |                 |
|                    |           |                        |   |                          | pecial Sigr                      |                       |                    |          |         | 2.781              | Chouteau Trafficway                      | 1.00 |            |       |         | M04-11-42              | 21.00                |                 |
|                    |           |                        |   |                          | pecial Sigr                      |                       |                    |          |         | 3.22               | Chouteau Trafficway                      | 1.00 |            |       |         | MO4-11-36              | 19.50                |                 |
|                    |           |                        |   |                          | pecial Sigr                      |                       |                    |          |         | 3.22               | Chouteau Trafficway  Chouteau Trafficway | 1.00 |            |       |         | M04-11-42              | 21.00<br>19.50       |                 |
|                    |           |                        |   |                          |                                  |                       |                    |          |         |                    |  | 1.00 |            |       |         | MO4-11-36              | IM BIT               | 1               |
|                    |           |                        |   |                          | pecial Sigr<br>pecial Sigr       |                       |                    |          |         | 3.668              | 210                                      | 1.00 |            |       |         | MO4-11-36              | 19.50                | 1               |

1.00 Revision 4/1/2020 Page 9 of 30



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line are details for Construction Signs (if applicable).

| ject | Line Number | DWR Date      | Total Quantity Posted For DWR Date | Sign Information   | Station | Log Mile | Location            | Number of Items | SF Each Sign | Special Sign | SF Each Special Sign | Total SF to Post |
|------|-------------|---------------|------------------------------------|--|---------|----------|---------------------|-----------------|--------------|--------------|----------------------|------------------|
| 205  | 0310        | June 18, 2020 | 1336                               | AHEAD  |         |          |                     |                 |              |              |                      |                  |
|      |             |               |                                    | See Special Sign Details   |         | 32.385   | 210                 | 1.00            |              | MO4-11-36    | 19.50                | 19.5             |
|      |             |               |                                    | See Special Sign Details   |         | 32.627   | 210                 | 1.00            |              | MO4-11-36    | 19.50                | 19.5             |
|      |             |               |                                    | See Special Sign Details   |         | 32.627   | 210                 | 1.00            |              | M04-11-42    | 21.00                | 21               |
|      |             |               |                                    | See Special Sign Details   |         | 33.094   | 210                 | 1.00            |              | MO4-11-36    | 19.50                | 19.5             |
|      |             |               |                                    | See Special Sign Details   |         | 33.293   | 210                 | 1.00            |              | M04-11-42    | 21.00                | 21               |
|      |             |               |                                    | R11-3a 60x30 12.50 ROAD<br>CLOSED XX MILES AHEAD LOCAL<br>TRAFFIC ONLY |         | 4.19     | Parvin Road         | 1.00            | 12.5         |              |                      | 12.5             |
|      |             |               |                                    | WO20-2 48x48 16.00 DETOUR<br>AHEAD                                     |         | 4.19     | Parvin Road         | 1.00            | 16           |              |                      | 16               |
|      |             |               |                                    | See Special Sign Details   |         | 4.314    | Parvin Road         | 1.00            |              | M04-11-42    | 21.00                | 21               |
|      |             |               |                                    | See Special Sign Details   |         | 4.317    | Parvin Road         | 1.00            |              | M04-11-42    | 21.00                | 21               |
|      |             |               |                                    | See Special Sign Details   |         | 4.728    | Chouteau Trafficway | 1.00            |              | MO4-11-36    | 19.50                | 19.5             |
|      |             |               |                                    | See Special Sign Details   |         | 4.767    | Chouteau Trafficway | 1.00            |              | MO4-11-36    | 19.50                | 19.5             |
|      |             |               |                                    | WO20-2 48x48 16.00 DETOUR<br>AHEAD                                     |         | 5.203    | Prather Road        | 1.00            | 16           |              |                      | 16               |
|      |             |               |                                    | R11-3a 60x30 12.50 ROAD<br>CLOSED XX MILES AHEAD LOCAL<br>TRAFFIC ONLY |         | 5.389    | Prather Road        | 1.00            | 12.5         |              |                      | 12.5             |
|      |             |               |                                    | MO4-8a 24x18 3.00 END DETOUR   |         | 5.389    | Prather Road        | 1.00            | 3            |              |                      | 3                |
|      |             |               |                                    | See Special Sign Details   |         | 5.445    | Prather Road        | 1.00            |              | MO4-11-36    | 19.50                | 19.5             |
|      |             |               |                                    | R11-3a 60x30 12.50 ROAD<br>CLOSED XX MILES AHEAD LOCAL<br>TRAFFIC ONLY |         | 5.611    | Prather Road        | 1.00            | 12.5         |              |                      | 12.5             |
|      |             |               |                                    | See Special Sign Details   |         | 6.134    | 135                 | 1.00            |              | MO4-11-36    | 19.50                | 19.5             |
|      |             |               |                                    | MO4-8a 24x18 3.00 END DETOUR   |         | 6.134    | Parvin Road         | 1.00            | 3            |              |                      | 3                |
|      |             |               |                                    | See Special Sign Details   |         | 7.524    | 135                 | 1.00            |              | MO4-11-36    | 19.50                | 19.5             |
|      |             |               |                                    | See Special Sign Details   |         | 7.524    | 135                 | 1.00            |              | M04-11-42    | 21.00                | 21               |
|      |             |               |                                    | See Special Sign Details   |         | 8.033    | 135                 | 1.00            |              | MO4-11-36    | 19.50                | 19.5             |
|      |             |               |                                    | See Special Sign Details   |         | 8.033    | 135                 | 1.00            |              | M04-11-42    | 21.00                | 21               |
|      |             |               |                                    | See Special Sign Details   |         | 8.976    | 135                 | 1.00            |              | M04-11-42    | 21.00                | 21               |
|      |             |               |                                    | See Special Sign Details   |         | 8.976    | 135                 | 4.00            |              | MO4-11-36    | 19.50                | 78               |
|      |             |               |                                    | See Special Sign Details   |         | 9.379    | 135                 | 1.00            |              | MO4-11-36    | 19.50                | 19.5             |
|      |             |               |                                    | See Special Sign Details   |         | 9.379    | 135                 | 1.00            |              | M04-11-42    | 21.00                | 21               |
|      |             |               |                                    | See Special Sign Details   |         | 9.495    | 135                 | 1.00            |              | M04-11-42    | 21.00                | 21               |
|      |             |               |                                    | See Special Sign Details   |         | 9.495    | 135                 | 2.00            |              | MO4-11-36    | 19.50                | 39               |
|      |             |               |                                    | See Special Sign Details   |         | 9.766    | 135                 | 1.00            |              | M04-11-42    | 21.00                | 21               |

Revision 4/1/2020 Page 10 of 30



| Line   | Description                             | Adjustment<br>Type       | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By | Amount        | Remarks  |
|--------|---|--------------------------|-----------------------------|----------------|-----------------|---------------|---------------|--|
| 0030   | CLASS A EXCAVATION                      | Price                    |                             | 8              | Oct 16,<br>2020 | SYSTEM        | \$295.74      | Reference Item Price Adjustment Index Adjustment Type applied is FUEL  |
|        |   |                          | - Total                     |                |                 |               | \$295.74      |  |
|        | Price - Total                           |                          |                             |                |                 |               | \$295.74      |  |
| 0030 - | Total                                   |                          |                             |                |                 |               | \$295.74      |  |
| 0040   | EMBANKMENT IN PLACE                     | Material                 |                             | 8              | Oct 16,<br>2020 | SYSTEM        | (\$77,228.30) |  |
|        |   |                          |                             | 8              | Oct 16,<br>2020 | SYSTEM        | \$77,228.30   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 1 on the current Payment Estimate.          |
|        |   |                          | - Total                     |                |                 |               | \$0.00        |  |
|        | Material - Total                        |                          |                             |                |                 |               | \$0.00        |  |
|        | EMBANKMENT IN PLACE                     | Other Item<br>Adjustment | FUEL                        | 18             | Mar 16,<br>2021 | schnod1       | (\$94.18)     | Removing system generated fuel adjustment, and entering manual adjustment.   |
|        |   |                          |                             | 18             | Mar 16,<br>2021 | schnod1       | \$25.76       | Manual fuel adjustment for work done during the estimate 0008 period.  |
|        |   |                          | FUEL - Tota                 | ıl             |                 |               | (\$68.42)     |  |
|        | Other Item Adjustment - Total           |                          |                             |                |                 |               | (\$68.42)     |  |
|        | EMBANKMENT IN PLACE                     | Price                    |                             | 8              | Oct 16,<br>2020 | SYSTEM        | \$550.93      | Reference Item Price Adjustment Index Adjustment Type applied is FUEL  |
|        |   |                          |                             | 18             | Mar 16,<br>2021 | SYSTEM        | \$94.18       | Reference Item Price Adjustment Index Adjustment Type applied is FUEL  |
|        |   |                          | - Total                     |                |                 |               | \$645.11      |  |
|        | Price - Total                           |                          |                             |                |                 |               | \$645.11      |  |
| 0040 - | Total                                   |                          |                             |                |                 |               | \$576.69      |  |
| 0090   | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) | Material                 |                             | 6              | Sep 16,<br>2020 | SYSTEM        | (\$21,477.65) |  |
|        |   |                          |                             | 6              | Sep 16,<br>2020 | SYSTEM        | \$21,477.65   | This adjustment offsets the original system-generated Overrun<br>Payment Estimate Item Adjustment (0002) due to user schnod1<br>overridding Payment Estimate Exception 1 on the current Payment<br>Estimate. |
|        |   |                          |                             | 7              | Oct 2,<br>2020  | SYSTEM        | (\$28,762.78) |  |
|        |   |                          |                             | 7              | Oct 2,<br>2020  | SYSTEM        | \$28,762.78   | This adjustment offsets the original system-generated Overrun<br>Payment Estimate Item Adjustment (0007) due to user schnod1<br>overridding Payment Estimate Exception 1 on the current Payment<br>Estimate. |
|        |   |                          |                             | 8              | Oct 16,<br>2020 | SYSTEM        | (\$35,937.82) |  |
|        |   |                          |                             | 8              | Oct 16,<br>2020 | SYSTEM        | \$35,937.82   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate.          |
|        |   |                          |                             | 9              | Nov 2,<br>2020  | SYSTEM        | (\$56,743.82) |  |
|        |   |                          |                             | 9              | Nov 2,<br>2020  | SYSTEM        | \$56,743.82   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user schnod1 overridding Payment Estimate Exception 1 on the current Payment Estimate.          |
|        |   |                          |                             | 10             | Nov 16,<br>2020 | SYSTEM        | (\$56,743.82) |  |
|        |   |                          |                             | 10             | Nov 16,<br>2020 | SYSTEM        | \$56,743.82   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate.          |
|        |   |                          |                             | 11             | Dec 2,<br>2020  | SYSTEM        | (\$60,024.30) |  |
|        |   |                          |                             | 11             | Dec 2,<br>2020  | SYSTEM        | \$60,024.30   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate.          |
|        |   |                          |                             | 12             | Dec 16,<br>2020 | SYSTEM        | (\$60,024.30) |  |
|        |   |                          |                             | 12             | Dec 16,<br>2020 | SYSTEM        | \$60,024.30   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user schnod1  |

Revision 4/1/2020 Page 11 of 30



| Line | Description                             | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date         | Created<br>By | Amount              | Remarks  |
|------|---|--------------------|-----------------------------|----------------|-------------------------|---------------|---------------------|--|
| 0090 | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) | Material           |                             |                |                         |               |                     | overridding Payment Estimate Exception 1 on the current Payment Estimate.  |
|      |   |                    |                             | 13             | Jan 4,<br>2021          | SYSTEM        | (\$60,024.30)       |  |
|      |   |                    |                             | 13             | Jan 4,<br>2021          | SYSTEM        | \$60,024.30         | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schnod1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
|      |   |                    |                             | 14             | Jan 19,<br>2021         | SYSTEM        | (\$60,024.30)       |  |
|      |   |                    |                             | 14             | Jan 19,<br>2021         | SYSTEM        | \$60,024.30         | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
|      |   |                    |                             | 15             | Feb 2,<br>2021          | SYSTEM        | (\$60,024.30)       |  |
|      |   |                    |                             | 15             | Feb 2,<br>2021          | SYSTEM        | \$60,024.30         | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
|      |   |                    |                             | 16             | Feb 16,<br>2021         | SYSTEM        | (\$60,024.30)       |  |
|      |   |                    |                             | 16             | Feb 16,<br>2021         | SYSTEM        | \$60,024.30         | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user yostj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.  |
|      |   |                    |                             | 17             | Mar 2,<br>2021          | SYSTEM        | (\$60,024.30)       |  |
|      |   |                    |                             | 17             | Mar 2,<br>2021          | SYSTEM        | \$60,024.30         | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
|      |   |                    |                             | 18             | Mar 16,<br>2021         | SYSTEM        | (\$60,448.50)       |  |
|      |   |                    |                             | 18             | Mar 16,<br>2021         | SYSTEM        | \$60,448.50         | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schnod1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
|      | Material - Total                        |                    | - Total                     |                |                         |               | \$0.00              |  |
|      | TYPE 5 AGGREGATE FOR BASE (6 IN.        | Other Item         | FUEL                        | 18             | Mar 16,                 | schnod1       | \$0.00<br>(\$11.30) | Removing auto fuel adjustment, and entering manual fuel  |
|      | THICK)                                  | Adjustment         |                             | 18             | 2021<br>Mar 16,<br>2021 | schnod1       | \$3.09              | adjustment.  Manual fuel adjustment calculation for work done during estimate period 0008.   |
|      |   |                    | FUEL - Tota                 | I              |                         |               | (\$8.21)            |  |
|      | Other Item Adjustment - Total           |                    |                             |                |                         |               | (\$8.21)            |  |
|      | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) | Price              |                             | 6              | Sep 16,<br>2020         | SYSTEM        | \$185.86            | Reference Item Price Adjustment Index Adjustment Type applied is FUEL  |
|      |   |                    |                             | 7              | Oct 2,<br>2020          | SYSTEM        | \$63.04             | Reference Item Price Adjustment Index Adjustment Type applied is FUEL  |
|      |   |                    |                             | 8              | Oct 16,<br>2020         | SYSTEM        | \$52.29             | Reference Item Price Adjustment Index Adjustment Type applied is FUEL  |
|      |   |                    |                             | 9              | Nov 2,<br>2020          | SYSTEM        | \$151.61            | Reference Item Price Adjustment Index Adjustment Type applied is FUEL  |
|      |   |                    |                             | 11             | Dec 2,<br>2020          | SYSTEM        | \$25.40             | Reference Item Price Adjustment Index Adjustment Type applied is FUEL  |
|      |   |                    |                             | 18             | Mar 16,<br>2021         | SYSTEM        | \$11.30             | Reference Item Price Adjustment Index Adjustment Type applied is FUEL  |
|      |   |                    | - Total                     |                |                         |               | \$489.50            |  |
|      | Price - Total                           |                    |                             |                |                         |               | \$489.50            |  |
|      | - Total                                 |                    |                             |                |                         |               | \$481.29            |  |
| 0100 | MISC. OPTIONAL PAVEMENT                 | Material           |                             | 8              | Oct 16,<br>2020         | SYSTEM        | (\$162,585.60)      |  |
|      |   |                    |                             | 8              | Oct 16,<br>2020         | SYSTEM        | \$162,585.60        | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  |

Revision 4/1/2020 Page 12 of 30



| Line | Description                              | Adjustment<br>Type | Other<br>Adjustment | Est.<br>Number | Created<br>Date | Created<br>By | Amount                 | Remarks  |
|------|--|--------------------|---------------------|----------------|-----------------|---------------|------------------------|--|
| 0100 | MISC. OPTIONAL PAVEMENT                  | Material           | Туре                | 9              | Nov 2,<br>2020  | SYSTEM        | (\$245,143.12)         |  |
|      |  |                    |                     | 9              | Nov 2,<br>2020  | SYSTEM        | \$245,143.12           | This adjustment offsets the original system-generated Overrun<br>Payment Estimate Item Adjustment (0005) due to user schnod1<br>overridding Payment Estimate Exception 2 on the current Payment<br>Estimate. |
|      |  |                    |                     | 10             | Nov 16,<br>2020 | SYSTEM        | (\$129,201.40)         |  |
|      |  |                    |                     | 10             | Nov 16,<br>2020 | SYSTEM        | \$129,201.40           | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Exception 4 on the current Payment Estimate.          |
|      |  |                    |                     | 11             | Dec 2,<br>2020  | SYSTEM        | (\$129,201.40)         |  |
|      |  |                    |                     | 11             | Dec 2,<br>2020  | SYSTEM        | \$129,201.40           | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user schnod1 overridding Payment Estimate Exception 4 on the current Payment Estimate.          |
|      |  |                    |                     | 12             | Dec 16,<br>2020 | SYSTEM        | (\$129,201.40)         |  |
|      |  |                    |                     | 12             | Dec 16,<br>2020 | SYSTEM        | \$129,201.40           | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate.          |
|      |  |                    |                     | 13             | Jan 4,<br>2021  | SYSTEM        | (\$129,201.40)         |  |
|      |  |                    |                     | 13             | Jan 4,<br>2021  | SYSTEM        | \$129,201.40           | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate.         |
|      |  |                    |                     | 14             | Jan 19,<br>2021 | SYSTEM        | (\$129,201.40)         |  |
|      |  |                    |                     | 14             | Jan 19,<br>2021 | SYSTEM        | \$129,201.40           | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate.         |
|      |  |                    | - Total             |                |                 |               | \$0.00                 |  |
| 0400 | Material - Total<br>- Total              |                    |                     |                |                 |               | \$0.00                 |  |
| 0110 | CONCRETE PAVEMENT ( 6 IN. NON-           | Material           |                     | 7              | Oct 2,          | SYSTEM        | \$0.00<br>(\$2,361.30) |  |
| 0110 | REINF)                                   | Waterial           |                     |                | 2020            |               |                        |  |
|      |  |                    |                     | 7              | Oct 2,<br>2020  | SYSTEM        | \$2,361.30             | This adjustment offsets the original system-generated Overrun<br>Payment Estimate Item Adjustment (0008) due to user schnod1<br>overridding Payment Estimate Exception 2 on the current Payment<br>Estimate. |
|      |  |                    |                     | 8              | Oct 16,<br>2020 | SYSTEM        | (\$6,153.27)           |  |
|      |  |                    |                     | 8              | Oct 16,<br>2020 | SYSTEM        | \$6,153.27             | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Exception 4 on the current Payment Estimate.          |
|      |  |                    |                     | 9              | Nov 2,<br>2020  | SYSTEM        | (\$12,514.89)          |  |
|      |  |                    |                     | 9              | Nov 2,<br>2020  | SYSTEM        | \$12,514.89            | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate.          |
|      |  |                    | - Total             |                |                 |               | \$0.00                 |  |
|      | Material - Total                         |                    |                     |                |                 |               | \$0.00                 |  |
|      | CONCRETE PAVEMENT ( 6 IN. NON-<br>REINF) | Price              |                     | 7              | Oct 2,<br>2020  | SYSTEM        | \$9.50                 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL  |
|      |  |                    |                     | 8              | Oct 16,<br>2020 | SYSTEM        | \$12.84                | Reference Item Price Adjustment Index Adjustment Type applied is FUEL  |
|      |  |                    |                     | 9              | Nov 2,<br>2020  | SYSTEM        | \$21.55                | Reference Item Price Adjustment Index Adjustment Type applied is FUEL  |
|      |  |                    | - Total             |                |                 |               | \$43.89                |  |
|      |  |                    |                     |                |                 |               | \$43.89                |  |
|      | Price - Total<br>- Total                 |                    |                     |                |                 |               | \$43.89                |  |

Revision 4/1/2020 Page 13 of 30



| Line | Description                           | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By | Amount        | Remarks  |
|------|---------------------------------------|--------------------|-----------------------------|----------------|-----------------|---------------|---------------|--|
| 0120 | MISC. TINTED CONCRETE PAVEMENT (8")   | Material           |                             | 10             | Nov 16,<br>2020 | SYSTEM        | (\$12,162.63) |  |
|      |                                       |                    |                             | 10             | Nov 16,<br>2020 | SYSTEM        | \$12,162.63   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user schnod1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  |
|      |                                       |                    | - Total                     |                |                 |               | \$0.00        |  |
|      | Material - Total                      |                    |                             |                |                 |               | \$0.00        |  |
|      | - Total                               |                    |                             |                |                 |               | \$0.00        |  |
| 0140 | PIPE COLLAR, TYPE C                   | Material           |                             | 2              | Jul 16,<br>2020 | SYSTEM        | (\$1,788.05)  |  |
|      |                                       |                    |                             | 2              | Jul 16,<br>2020 | SYSTEM        | \$1,788.05    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user schnod1 overridding Payment Estimate Exception 1 on the current Payment Estimate.  |
|      |                                       |                    | - Total                     |                |                 |               | \$0.00        |  |
|      | Material - Total                      |                    |                             |                |                 |               | \$0.00        |  |
| 0140 | - Total                               |                    |                             |                |                 |               | \$0.00        |  |
| 0150 | PIPE AGGREGATE PAVEMENT EDGE<br>DRAIN | Material           |                             | 9              | Nov 2,<br>2020  | SYSTEM        | (\$3,819.20)  |  |
|      |                                       |                    |                             | 9              | Nov 2,<br>2020  | SYSTEM        | \$3,819.20    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user schnod1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  |
|      |                                       |                    |                             | 10             | Nov 16,<br>2020 | SYSTEM        | (\$3,819.20)  |  |
|      |                                       |                    |                             | 10             | Nov 16,<br>2020 | SYSTEM        | \$3,819.20    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user schnod1 overridding Payment Estimate Exception 6 on the current Payment Estimate.  |
|      |                                       |                    |                             | 11             | Dec 2,<br>2020  | SYSTEM        | (\$3,819.20)  |  |
|      |                                       |                    |                             | 11             | Dec 2,<br>2020  | SYSTEM        | \$3,819.20    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  |
|      |                                       |                    |                             | 12             | Dec 16,<br>2020 | SYSTEM        | (\$3,819.20)  |  |
|      |                                       |                    |                             | 12             | Dec 16,<br>2020 | SYSTEM        | \$3,819.20    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  |
|      |                                       |                    |                             | 13             | Jan 4,<br>2021  | SYSTEM        | (\$3,819.20)  |  |
|      |                                       |                    |                             | 13             | Jan 4,<br>2021  | SYSTEM        | \$3,819.20    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schnod1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
|      |                                       |                    |                             | 14             | Jan 19,<br>2021 | SYSTEM        | (\$3,819.20)  |  |
|      |                                       |                    |                             | 14             | Jan 19,<br>2021 | SYSTEM        | \$3,819.20    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schnod1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
|      |                                       |                    |                             | 15             | Feb 2,<br>2021  | SYSTEM        | (\$3,819.20)  |  |
|      |                                       |                    |                             | 15             | Feb 2,<br>2021  | SYSTEM        | \$3,819.20    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
|      |                                       |                    |                             | 16             | Feb 16,<br>2021 | SYSTEM        | (\$3,819.20)  |  |
|      |                                       |                    |                             | 16             | Feb 16,<br>2021 | SYSTEM        | \$3,819.20    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user yostj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  |
|      |                                       |                    |                             | 17             | Mar 2,<br>2021  | SYSTEM        | (\$3,819.20)  |  |
|      |                                       |                    |                             | 17             | Mar 2,          | SYSTEM        | \$3,819.20    | This adjustment offsets the original system-generated Material   |

Revision 4/1/2020 Page 14 of 30



| Line | Description                           | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By | Amount           | Remarks   |
|------|---------------------------------------|--------------------|-----------------------------|----------------|-----------------|---------------|------------------|---|
| 0150 | PIPE AGGREGATE PAVEMENT EDGE<br>DRAIN | Material           |                             |                | 2021            |               |                  | Payment Estimate Item Adjustment (0003) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate.   |
|      |                                       |                    |                             | 18             | Mar 16,<br>2021 | SYSTEM        | (\$3,819.20)     |   |
|      |                                       |                    |                             | 18             | Mar 16,<br>2021 | SYSTEM        | \$3,819.20       | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 5 on the current Payment Estimate.          |
|      | Metavial Total                        |                    | - Total                     |                |                 |               | \$0.00           |   |
| 0150 | Material - Total<br>- Total           |                    |                             |                |                 |               | \$0.00<br>\$0.00 |   |
| 0160 | OUTLET PIPES AND SPLASH PADS          | Material           |                             | 12             | Dec 16,         | SYSTEM        | (\$1,775.40)     |   |
| 0100 | COTLETT II EO AND OF EACHT ADO        | Waterial           |                             |                | 2020            | OTOTEW        | (ψ1,773.40)      |   |
|      |                                       |                    |                             | 12             | Dec 16,<br>2020 | SYSTEM        | \$1,775.40       | This adjustment offsets the original system-generated Overrun<br>Payment Estimate Item Adjustment (0017) due to user schnod1<br>overridding Payment Estimate Exception 4 on the current Payment<br>Estimate.  |
|      |                                       |                    |                             | 13             | Jan 4,<br>2021  | SYSTEM        | (\$1,775.40)     |   |
|      |                                       |                    |                             | 13             | Jan 4,<br>2021  | SYSTEM        | \$1,775.40       | This adjustment offsets the original system-generated Material<br>Payment Estimate Item Adjustment (0019) due to user schnod1<br>overridding Payment Estimate Exception 7 on the current Payment<br>Estimate. |
|      |                                       |                    |                             | 14             | Jan 19,<br>2021 | SYSTEM        | (\$1,775.40)     |   |
|      |                                       |                    |                             | 14             | Jan 19,<br>2021 | SYSTEM        | \$1,775.40       | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schnod1 overridding Payment Estimate Exception 7 on the current Payment Estimate.          |
|      |                                       |                    |                             | 15             | Feb 2,<br>2021  | SYSTEM        | (\$1,775.40)     |   |
|      |                                       |                    |                             | 15             | Feb 2,<br>2021  | SYSTEM        | \$1,775.40       | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schnod1 overridding Payment Estimate Exception 4 on the current Payment Estimate.          |
|      |                                       |                    |                             | 16             | Feb 16,<br>2021 | SYSTEM        | (\$1,775.40)     |   |
|      |                                       |                    |                             | 16             | Feb 16,<br>2021 | SYSTEM        | \$1,775.40       | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user yostj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.           |
|      |                                       |                    |                             | 17             | Mar 2,<br>2021  | SYSTEM        | (\$1,775.40)     |   |
|      |                                       |                    |                             | 17             | Mar 2,<br>2021  | SYSTEM        | \$1,775.40       | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schnod1 overridding Payment Estimate Exception 4 on the current Payment Estimate.          |
|      |                                       |                    |                             | 18             | Mar 16,<br>2021 | SYSTEM        | (\$1,775.40)     |   |
|      |                                       |                    |                             | 18             | Mar 16,<br>2021 | SYSTEM        | \$1,775.40       | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schnod1 overridding Payment Estimate Exception 6 on the current Payment Estimate.          |
|      |                                       |                    | - Total                     |                |                 |               | \$0.00           |   |
|      | Material - Total                      |                    |                             |                |                 |               | \$0.00           |   |
|      | - Total                               | Mark 11            |                             | 40             | No. 12          | 0)/07=::      | \$0.00           |   |
| 0180 | MODIFIED CONCRETE GUTTER TYPE B       | Material           |                             | 10             | Nov 16,<br>2020 | SYSTEM        | (\$7,894.80)     |   |
|      |                                       |                    |                             | 10             | Nov 16,<br>2020 | SYSTEM        | \$7,894.80       | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user schnod1 overridding Payment Estimate Exception 9 on the current Payment Estimate.           |
|      |                                       |                    |                             | 11             | Dec 2,<br>2020  | SYSTEM        | (\$7,894.80)     |   |
|      |                                       |                    |                             | 11             | Dec 2,<br>2020  | SYSTEM        | \$7,894.80       | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user schnod1 overridding Payment Estimate Exception 8 on the current Payment Estimate.           |

Revision 4/1/2020 Page 15 of 30



| Line   | Description                     | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By | Amount       | Remarks  |
|--------|---------------------------------|--------------------|-----------------------------|----------------|-----------------|---------------|--------------|--|
| 0180   | MODIFIED CONCRETE GUTTER TYPE B | Material           |                             | 12             | Dec 16,<br>2020 | SYSTEM        | (\$7,894.80) |  |
|        |                                 |                    |                             | 12             | Dec 16,<br>2020 | SYSTEM        | \$7,894.80   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user schnod1 overridding Payment Estimate Exception 6 on the current Payment Estimate.  |
|        |                                 |                    |                             | 13             | Jan 4,<br>2021  | SYSTEM        | (\$7,894.80) |  |
|        |                                 |                    |                             | 13             | Jan 4,<br>2021  | SYSTEM        | \$7,894.80   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schnod1 overridding Payment Estimate Exception 9 on the current Payment Estimate. |
|        |                                 |                    |                             | 14             | Jan 19,<br>2021 | SYSTEM        | (\$7,894.80) |  |
|        |                                 |                    |                             | 14             | Jan 19,<br>2021 | SYSTEM        | \$7,894.80   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schnod1 overridding Payment Estimate Exception 9 on the current Payment Estimate. |
|        |                                 |                    |                             | 15             | Feb 2,<br>2021  | SYSTEM        | (\$7,894.80) |  |
|        |                                 |                    |                             | 15             | Feb 2,<br>2021  | SYSTEM        | \$7,894.80   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schnod1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
|        |                                 |                    |                             | 16             | Feb 16,<br>2021 | SYSTEM        | (\$7,894.80) |  |
|        |                                 |                    |                             | 16             | Feb 16,<br>2021 | SYSTEM        | \$7,894.80   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user yostj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.  |
|        |                                 |                    |                             | 17             | Mar 2,<br>2021  | SYSTEM        | (\$7,894.80) |  |
|        |                                 |                    |                             | 17             | Mar 2,<br>2021  | SYSTEM        | \$7,894.80   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schnod1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
|        |                                 |                    |                             | 18             | Mar 16,<br>2021 | SYSTEM        | (\$7,894.80) |  |
|        |                                 |                    |                             | 18             | Mar 16,<br>2021 | SYSTEM        | \$7,894.80   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schnod1 overridding Payment Estimate Exception 8 on the current Payment Estimate. |
|        |                                 |                    | - Total                     |                |                 |               | \$0.00       |  |
|        | Material - Total                |                    |                             |                |                 |               | \$0.00       |  |
| 0180 - | - Total                         |                    |                             |                |                 |               | \$0.00       |  |
| 0190   | CONCRETE CURB RAMP              | Material           |                             | 9              | Nov 2,<br>2020  | SYSTEM        | (\$6,897.08) |  |
|        |                                 |                    |                             | 9              | Nov 2,<br>2020  | SYSTEM        | \$6,897.08   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user schnod1 overridding Payment Estimate Exception 10 on the current Payment Estimate. |
|        |                                 |                    | - Total                     |                |                 |               | \$0.00       |  |
|        | Material - Total                |                    |                             |                |                 |               | \$0.00       |  |
|        | CONCRETE CURB RAMP              | Overrun            | Overrun                     | 11             | Dec 2,<br>2020  | SYSTEM        | (\$1,484.60) |  |
|        |                                 |                    |                             | 11             | Dec 2,<br>2020  | SYSTEM        | \$1,484.60   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Exception 20 on the current Payment Estimate. |
|        |                                 |                    |                             | 12             | Dec 16,<br>2020 | SYSTEM        | (\$1,484.60) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  |
|        |                                 |                    |                             | 12             | Dec 16,<br>2020 | SYSTEM        | \$1,484.60   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user schnod1 overridding Payment Estimate Exception 35 on the current Payment Estimate. |
|        |                                 |                    |                             | 13             | Jan 4,<br>2021  | SYSTEM        | (\$1,484.60) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  |
|        |                                 |                    |                             | 13             | Jan 4,<br>2021  | SYSTEM        | \$1,484.60   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user schnod1  |

Revision 4/1/2020 Page 16 of 30



| Line   | Description                              | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number        | Created<br>Date   | Created<br>By                                    | Amount   | Remarks  |
|--------|--|--------------------|-----------------------------|-----------------------|---|--|--|--|
| 0190   | CONCRETE CURB RAMP                       | Overrun            | Overrun                     |                       |   |  |  | overridding Payment Estimate Exception 43 on the current Payment Estimate.   |
|        |  |                    |                             | 14                    | Jan 19,<br>2021   | SYSTEM   | (\$1,484.60)   | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  |
|        |  |                    |                             | 14                    | Jan 19,<br>2021   | SYSTEM   | \$1,484.60   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user schnod1 overridding Payment Estimate Exception 36 on the current Payment Estimate.   |
|        |  |                    |                             | 15                    | Feb 2,<br>2021  | SYSTEM   | (\$1,484.60)   | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  |
|        |  |                    |                             | 15                    | Feb 2,<br>2021  | SYSTEM   | \$1,484.60   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user schnod1 overridding Payment Estimate Exception 16 on the current Payment Estimate.   |
|        |  |                    |                             | 16                    | Feb 16,<br>2021   | SYSTEM   | (\$1,484.60)   | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  |
|        |  |                    |                             | 16                    | Feb 16,<br>2021   | SYSTEM   | \$1,484.60   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user yostj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.  |
|        |  |                    |                             | 17                    | Mar 2,<br>2021  | SYSTEM   | (\$1,484.60)   | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  |
|        |  |                    |                             | 17                    | Mar 2,<br>2021  | SYSTEM   | \$1,484.60   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user schnod1 overridding Payment Estimate Exception 16 on the current Payment Estimate.   |
|        |  |                    |                             | 18                    | Mar 16,<br>2021   | SYSTEM   | (\$1,484.60)   | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  |
|        |  |                    |                             | 18                    | Mar 16,<br>2021   | SYSTEM   | \$1,484.60   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user schnod1 overridding Payment Estimate Exception 18 on the current Payment Estimate.   |
|        |  |                    | Overrun - T                 | otal                  |   |  | \$0.00   |  |
|        | Overrun - Total                          |                    |                             |                       |   |  | \$0.00   |  |
| 0400   |  |                    |                             |                       |   |  |  |  |
| 0190 - | Total                                    |                    |                             |                       |   |  | \$0.00   |  |
| 0200   | Total TRUNCATED DOMES                    | Material           |                             | 9                     | Nov 2,<br>2020  | SYSTEM   | <b>\$0.00</b> (\$3,920.00)   |  |
|        |  | Material           |                             | 9                     |   | SYSTEM<br>SYSTEM                                 |  | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user schnod1 overridding Payment Estimate Exception 15 on the current Payment Estimate.   |
|        |  | Material           | - Total                     |                       | 2020<br>Nov 2,  |  | (\$3,920.00)   | Payment Estimate Item Adjustment (0014) due to user schnod1 overridding Payment Estimate Exception 15 on the current   |
|        |  | Material           | - Total                     |                       | 2020<br>Nov 2,  |  | (\$3,920.00)<br>\$3,920.00   | Payment Estimate Item Adjustment (0014) due to user schnod1 overridding Payment Estimate Exception 15 on the current   |
|        | TRUNCATED DOMES  Material - Total        | Material           | - Total                     |                       | 2020<br>Nov 2,  |  | (\$3,920.00)<br>\$3,920.00<br>\$0.00   | Payment Estimate Item Adjustment (0014) due to user schnod1 overridding Payment Estimate Exception 15 on the current   |
| 0200   | TRUNCATED DOMES  Material - Total        |                    | - Total                     |                       | 2020<br>Nov 2,  |  | (\$3,920.00)<br>\$3,920.00<br>\$0.00   | Payment Estimate Item Adjustment (0014) due to user schnod1 overridding Payment Estimate Exception 15 on the current   |
| 0200   | TRUNCATED DOMES  Material - Total  Total |                    | - Total                     | 9                     | 2020<br>Nov 2,<br>2020  | SYSTEM   | \$3,920.00)<br>\$3,920.00<br>\$0.00<br>\$0.00  | Payment Estimate Item Adjustment (0014) due to user schnod1 overridding Payment Estimate Exception 15 on the current   |
| 0200   | TRUNCATED DOMES  Material - Total  Total |                    | - Total                     | 7                     | 2020<br>Nov 2,<br>2020<br>Oct 2,<br>2020<br>Oct 2,  | SYSTEM   | \$3,920.00)<br>\$3,920.00<br>\$0.00<br>\$0.00<br>\$1,793.16)   | Payment Estimate Item Adjustment (0014) due to user schnod1 overridding Payment Estimate Exception 15 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user schnod1 overridding Payment Estimate Exception 8 on the current Payment  |
| 0200   | TRUNCATED DOMES  Material - Total  Total |                    | - Total                     | 7 7                   | 2020<br>Nov 2,<br>2020<br>Oct 2,<br>2020<br>Oct 2,<br>2020  | SYSTEM SYSTEM SYSTEM                             | \$3,920.00)<br>\$3,920.00<br>\$0.00<br>\$0.00<br>(\$1,793.16)  | Payment Estimate Item Adjustment (0014) due to user schnod1 overridding Payment Estimate Exception 15 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user schnod1 overridding Payment Estimate Exception 8 on the current Payment  |
| 0200   | TRUNCATED DOMES  Material - Total  Total |                    | - Total                     | 7 7 8                 | 2020<br>Nov 2,<br>2020<br>Oct 2,<br>2020<br>Oct 2,<br>2020<br>Oct 16,<br>2020<br>Oct 16,                  | SYSTEM SYSTEM SYSTEM SYSTEM                      | (\$3,920.00)<br>\$3,920.00<br>\$0.00<br>\$0.00<br>(\$1,793.16)<br>\$1,793.16                               | Payment Estimate Item Adjustment (0014) due to user schnod1 overridding Payment Estimate Exception 15 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user schnod1 overridding Payment Estimate Exception 8 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user schnod1 overridding Payment Estimate Exception 7 on the current Payment   |
| 0200   | TRUNCATED DOMES  Material - Total  Total |                    | - Total                     | 7 7 8 8 8             | 2020<br>Nov 2,<br>2020<br>Oct 2,<br>2020<br>Oct 2,<br>2020<br>Oct 16,<br>2020<br>Nov 2,                   | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM               | \$3,920.00<br>\$3,920.00<br>\$0.00<br>\$0.00<br>(\$1,793.16)<br>\$1,793.16                                 | Payment Estimate Item Adjustment (0014) due to user schnod1 overridding Payment Estimate Exception 15 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user schnod1 overridding Payment Estimate Exception 8 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user schnod1 overridding Payment Estimate Exception 7 on the current Payment   |
| 0200   | TRUNCATED DOMES  Material - Total  Total |                    | - Total                     | 9 7 7 7 8 8 8 9 9     | 2020<br>Nov 2,<br>2020<br>Oct 2,<br>2020<br>Oct 2,<br>2020<br>Oct 16,<br>2020<br>Nov 2,<br>2020<br>Nov 2, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM        | (\$3,920.00)<br>\$3,920.00<br>\$0.00<br>\$0.00<br>(\$1,793.16)<br>\$1,793.16<br>(\$1,793.16)               | Payment Estimate Item Adjustment (0014) due to user schnod1 overridding Payment Estimate Exception 15 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user schnod1 overridding Payment Estimate Exception 8 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user schnod1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user schnod1 overridding Payment Estimate Item Adjustment (0009) due to user schnod1 overridding Payment Estimate Exception 16 on the current |
| 0200   | TRUNCATED DOMES  Material - Total  Total |                    | - Total                     | 7<br>7<br>8<br>8<br>9 | 2020 Nov 2, 2020 Oct 2, 2020 Oct 2, 2020 Oct 16, 2020 Nov 2, 2020 Nov 2, 2020 Nov 2, 2020                 | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | (\$3,920.00)<br>\$3,920.00<br>\$0.00<br>\$0.00<br>(\$1,793.16)<br>\$1,793.16<br>(\$1,793.16)<br>\$1,793.16 | Payment Estimate Item Adjustment (0014) due to user schnod1 overridding Payment Estimate Exception 15 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user schnod1 overridding Payment Estimate Exception 8 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user schnod1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user schnod1 overridding Payment Estimate Item Adjustment (0009) due to user schnod1 overridding Payment Estimate Exception 16 on the current |

Revision 4/1/2020 Page 17 of 30



| Line | Description                   | Adjustment<br>Type       | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By | Amount        | Remarks   |
|------|-------------------------------|--------------------------|-----------------------------|----------------|-----------------|---------------|---------------|---|
| 0210 | PAVED APPROACH, 7 IN.         | Material                 | - 77                        |                | 2020            |               |               |   |
|      |                               |                          |                             | 11             | Dec 2,<br>2020  | SYSTEM        | \$1,793.16    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 9 on the current Payment Estimate.   |
|      |                               |                          |                             | 12             | Dec 16,<br>2020 | SYSTEM        | (\$3,047.20)  |   |
|      |                               |                          |                             | 12             | Dec 16,<br>2020 | SYSTEM        | \$3,047.20    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Exception 7 on the current Payment Estimate.   |
|      |                               |                          |                             | 13             | Jan 4,<br>2021  | SYSTEM        | (\$3,047.20)  |   |
|      |                               |                          |                             | 13             | Jan 4,<br>2021  | SYSTEM        | \$3,047.20    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schnod1 overridding Payment Estimate Exception 13 on the current Payment Estimate. |
|      |                               |                          |                             | 14             | Jan 19,<br>2021 | SYSTEM        | (\$3,047.20)  |   |
|      |                               |                          |                             | 14             | Jan 19,<br>2021 | SYSTEM        | \$3,047.20    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schnod1 overridding Payment Estimate Exception 13 on the current Payment Estimate. |
|      |                               |                          |                             | 15             | Feb 2,<br>2021  | SYSTEM        | (\$3,047.20)  |   |
|      |                               |                          |                             | 15             | Feb 2,<br>2021  | SYSTEM        | \$3,047.20    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schnod1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  |
|      |                               |                          |                             | 16             | Feb 16,<br>2021 | SYSTEM        | (\$3,047.20)  |   |
|      |                               |                          |                             | 16             | Feb 16,<br>2021 | SYSTEM        | \$3,047.20    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user yostj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.   |
|      |                               |                          |                             | 17             | Mar 2,<br>2021  | SYSTEM        | (\$3,047.20)  |   |
|      |                               |                          |                             | 17             | Mar 2,<br>2021  | SYSTEM        | \$3,047.20    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schnod1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  |
|      |                               |                          |                             | 18             | Mar 16,<br>2021 | SYSTEM        | (\$4,529.78)  |   |
|      |                               |                          |                             | 18             | Mar 16,<br>2021 | SYSTEM        | \$4,529.78    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schnod1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  |
|      |                               |                          | - Total                     |                |                 |               | \$0.00        |   |
|      | Material - Total              |                          |                             |                |                 |               | \$0.00        |   |
|      | PAVED APPROACH, 7 IN.         | Other Item<br>Adjustment | FUEL                        | 18             | Mar 16,<br>2021 | schnod1       | (\$16.28)     | Removing auto fuel adjustment, to enter manual fuel adjustment.   |
|      |                               |                          |                             | 18             | Mar 16,<br>2021 | schnod1       | \$4.45        | Manual fuel adjustment for work that was done during the 0008 estimate period.  |
|      |                               |                          | FUEL - Tota                 | ıl             |                 |               | (\$11.83)     |   |
|      | Other Item Adjustment - Total | D:                       |                             | -              | 0 : -           | 0)/075        | (\$11.83)     |   |
|      | PAVED APPROACH, 7 IN.         | Price                    |                             | 7              | Oct 2,<br>2020  | SYSTEM        | \$6.40        | Reference Item Price Adjustment Index Adjustment Type applied is FUEL   |
|      |                               |                          |                             | 12             | Dec 16,<br>2020 | SYSTEM        | \$6.83        | Reference Item Price Adjustment Index Adjustment Type applied is FUEL   |
|      |                               |                          |                             | 18             | Mar 16,<br>2021 | SYSTEM        | \$16.28       | Reference Item Price Adjustment Index Adjustment Type applied is FUEL   |
|      |                               |                          | - Total                     |                |                 |               | \$29.51       |   |
|      | Price - Total                 |                          |                             |                |                 |               | \$29.51       |   |
|      | - Total                       |                          |                             |                |                 |               | \$17.68       |   |
| 0220 | CONCRETE SIDEWALK, 4 IN.      | Material                 |                             | 9              | Nov 2,<br>2020  | SYSTEM        | (\$10,926.52) |   |
|      |                               |                          |                             | 9              | Nov 2,          | SYSTEM        | \$10,926.52   | This adjustment offsets the original system-generated Overrun   |

Revision 4/1/2020 Page 18 of 30



| 1.     | Descri ii   | A discort          | Or.                         | ·              | 0               | 0 1           | A 1           | Day 1  |
|--------|---|--------------------|-----------------------------|----------------|-----------------|---------------|---------------|--|
| Line   | Description   | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By | Amount        | Remarks  |
| 0220   | CONCRETE SIDEWALK, 4 IN.  | Material           |                             |                | 2020            |               |               | Payment Estimate Item Adjustment (0011) due to user schnod1 overridding Payment Estimate Exception 23 on the current Payment Estimate.   |
|        |   |                    | - Total                     |                |                 |               | \$0.00        |  |
|        | Material - Total  |                    |                             |                |                 |               | \$0.00        |  |
| 0220 - | · Total   |                    |                             |                |                 |               | \$0.00        |  |
| 0230   | CURB AND GUTTER TYPE B  | Material           |                             | 7              | Oct 2,<br>2020  | SYSTEM        | (\$28,462.00) |  |
|        |   |                    |                             | 7              | Oct 2,<br>2020  | SYSTEM        | \$28,462.00   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user schnod1 overridding Payment Estimate Exception 14 on the current Payment Estimate. |
|        |   |                    |                             | 8              | Oct 16,<br>2020 | SYSTEM        | (\$34,062.00) |  |
|        |   |                    |                             | 8              | Oct 16,<br>2020 | SYSTEM        | \$34,062.00   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user schnod1 overridding Payment Estimate Exception 12 on the current Payment Estimate. |
|        |   |                    |                             | 9              | Nov 2,<br>2020  | SYSTEM        | (\$34,062.00) |  |
|        |   |                    |                             | 9              | Nov 2,<br>2020  | SYSTEM        | \$34,062.00   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 25 on the current Payment Estimate. |
|        |   |                    |                             | 10             | Nov 16,<br>2020 | SYSTEM        | (\$47,289.20) |  |
|        |   |                    |                             | 10             | Nov 16,<br>2020 | SYSTEM        | \$47,289.20   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user schnod1 overridding Payment Estimate Exception 12 on the current Payment Estimate. |
|        |   |                    |                             | 11             | Dec 2,<br>2020  | SYSTEM        | (\$44,352.00) |  |
|        |   |                    |                             | 11             | Dec 2,<br>2020  | SYSTEM        | \$44,352.00   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user schnod1 overridding Payment Estimate Exception 10 on the current Payment Estimate. |
|        |   |                    | - Total                     |                |                 |               | \$0.00        |  |
|        | Material - Total  |                    |                             |                |                 |               | \$0.00        |  |
| 0230 - | Total   |                    |                             |                |                 |               | \$0.00        |  |
| 0260   | ROCK LINING   | Material           |                             | 11             | Dec 2,<br>2020  | SYSTEM        | (\$1,970.85)  |  |
|        |   |                    |                             | 11             | Dec 2,<br>2020  | SYSTEM        | \$1,970.85    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user schnod1 overridding Payment Estimate Exception 11 on the current Payment Estimate. |
|        |   |                    | - Total                     |                |                 |               | \$0.00        |  |
|        | Material - Total  |                    |                             |                |                 |               | \$0.00        |  |
| 0260   | · Total   |                    |                             |                |                 |               | \$0.00        |  |
| 0270   | MISC. APWA CURB AND GUTTER TYPE<br>CG-1                         | Material           |                             | 10             | Nov 16,<br>2020 | SYSTEM        | (\$6,224.40)  |  |
|        |   |                    |                             | 10             | Nov 16,<br>2020 | SYSTEM        | \$6,224.40    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 13 on the current Payment Estimate. |
|        |   |                    |                             | 11             | Dec 2,<br>2020  | SYSTEM        | (\$6,224.40)  |  |
|        |   |                    |                             | 11             | Dec 2,<br>2020  | SYSTEM        | \$6,224.40    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user schnod1 overridding Payment Estimate Exception 12 on the current Payment Estimate. |
|        |   |                    | - Total                     |                |                 |               | \$0.00        |  |
|        | Material - Total  |                    |                             |                |                 |               | \$0.00        |  |
| 0270   | · Total   |                    |                             |                |                 |               | \$0.00        |  |
| 0290   | CURVED VANE GRATE AND FRAME (2<br>FT. X 2 FT. OR 600MM X 600MM) | Material           |                             | 5              | Sep 2,<br>2020  | SYSTEM        | (\$2,558.90)  |  |
|        |   |                    |                             | 5              | Sep 2,          | SYSTEM        | \$2,558.90    | This adjustment offsets the original system-generated Overrun  |

Revision 4/1/2020 Page 19 of 30



| Line   | Description  | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By | Amount        | Remarks  |
|--------|--|--------------------|-----------------------------|----------------|-----------------|---------------|---------------|--|
| 0290   | CURVED VANE GRATE AND FRAME (2 FT. X 2 FT. OR 600MM X 600MM) | Material           |                             |                | 2020            |               |               | Payment Estimate Item Adjustment (0001) due to user schnod1 overridding Payment Estimate Exception 1 on the current Payment Estimate.  |
|        |  |                    |                             | 6              | Sep 16,<br>2020 | SYSTEM        | (\$2,558.90)  |  |
|        |  |                    |                             | 6              | Sep 16,<br>2020 | SYSTEM        | \$2,558.90    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate.          |
|        |  |                    |                             | 7              | Oct 2,<br>2020  | SYSTEM        | (\$2,558.90)  |  |
|        |  |                    |                             | 7              | Oct 2,<br>2020  | SYSTEM        | \$2,558.90    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user schnod1 overridding Payment Estimate Exception 20 on the current Payment Estimate.         |
|        |  |                    | - Total                     |                |                 |               | \$0.00        |  |
|        | Material - Total   |                    |                             |                |                 |               | \$0.00        |  |
| 0290 - | Total  |                    |                             |                |                 |               | \$0.00        |  |
| 0300   | MANHOLE FRAME AND COVER, TYPE 4                              | Material           |                             | 3              | Aug 3,<br>2020  | SYSTEM        | (\$3,020.10)  |  |
|        |  |                    |                             | 3              | Aug 3,<br>2020  | SYSTEM        | \$3,020.10    | This adjustment offsets the original system-generated Overrun<br>Payment Estimate Item Adjustment (0001) due to user schnod1<br>overridding Payment Estimate Exception 1 on the current Payment<br>Estimate. |
|        |  |                    |                             | 4              | Aug 17,<br>2020 | SYSTEM        | (\$3,020.10)  |  |
|        |  |                    |                             | 4              | Aug 17,<br>2020 | SYSTEM        | \$3,020.10    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user schnod1 overridding Payment Estimate Exception 1 on the current Payment Estimate.          |
|        |  |                    |                             | 5              | Sep 2,<br>2020  | SYSTEM        | (\$6,040.20)  |  |
|        |  |                    |                             | 5              | Sep 2,<br>2020  | SYSTEM        | \$6,040.20    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate.          |
|        |  |                    |                             | 6              | Sep 16,<br>2020 | SYSTEM        | (\$6,040.20)  |  |
|        |  |                    |                             | 6              | Sep 16,<br>2020 | SYSTEM        | \$6,040.20    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate.          |
|        |  |                    |                             | 7              | Oct 2,<br>2020  | SYSTEM        | (\$6,040.20)  |  |
|        |  |                    |                             | 7              | Oct 2,<br>2020  | SYSTEM        | \$6,040.20    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 21 on the current Payment Estimate.         |
|        |  |                    | - Total                     |                |                 |               | \$0.00        |  |
|        | Material - Total   |                    |                             |                |                 |               | \$0.00        |  |
| 0300 - |  | Madagid            |                             | 4              | lul d           | 0)(0751:      | \$0.00        |  |
| 0310   | CONSTRUCTION SIGNS   | Material           |                             | 1              | Jul 1,<br>2020  | SYSTEM        | (\$13,473.60) |  |
|        |  |                    |                             | 1              | Jul 1,<br>2020  | SYSTEM        | \$13,473.60   | This adjustment offsets the original system-generated Overrun<br>Payment Estimate Item Adjustment (0001) due to user schnod1<br>overridding Payment Estimate Exception 1 on the current Payment<br>Estimate. |
|        |  |                    | - Total                     |                |                 |               | \$0.00        |  |
|        | Material - Total   |                    |                             |                |                 |               | \$0.00        |  |
| 0310 - |  |                    |                             |                |                 |               | \$0.00        |  |
| 0320   | ADVANCED WARNING RAIL SYSTEM                                 | Material           |                             | 1              | Jul 1,<br>2020  | SYSTEM        | (\$714.00)    |  |
|        |  |                    |                             | 1              | Jul 1,<br>2020  | SYSTEM        | \$714.00      | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate.          |
|        |  |                    | - Total                     |                |                 |               | \$0.00        |  |

Revision 4/1/2020 Page 20 of 30



| Line   | Description  | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By | Amount        | Remarks  |
|--------|--|--------------------|-----------------------------|----------------|-----------------|---------------|---------------|--|
| 0320   | Material - Total   |                    |                             |                |                 |               | \$0.00        |  |
| 0320 - | · Total  |                    |                             |                |                 |               | \$0.00        |  |
| 0330   | FLAG ASSEMBLY  | Material           |                             | 1              | Jul 1,<br>2020  | SYSTEM        | (\$105.00)    |  |
|        |  |                    |                             | 1              | Jul 1,<br>2020  | SYSTEM        | \$105.00      | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate.            |
|        |  |                    | - Total                     |                |                 |               | \$0.00        |  |
|        | Material - Total   |                    |                             |                |                 |               | \$0.00        |  |
| 0330 - | Total  |                    |                             |                |                 |               | \$0.00        |  |
| 0340   | CHANNELIZER (TRIM LINE)                                  | Material           |                             | 1              | Jul 1,<br>2020  | SYSTEM        | (\$420.00)    |  |
|        |  |                    |                             | 1              | Jul 1,<br>2020  | SYSTEM        | \$420.00      | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user schnod1 overridding Payment Estimate Exception 4 on the current Payment Estimate.            |
|        |  |                    | - Total                     |                |                 |               | \$0.00        |  |
|        | Material - Total   |                    |                             |                |                 |               | \$0.00        |  |
| 0340 - | · Total  |                    |                             |                |                 |               | \$0.00        |  |
| 0350   | TYPE III MOVEABLE BARRICADE                              | Material           |                             | 1              | Jul 1,<br>2020  | SYSTEM        | (\$4,515.00)  |  |
|        |  |                    |                             | 1              | Jul 1,<br>2020  | SYSTEM        | \$4,515.00    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user schnod1 overridding Payment Estimate Exception 5 on the current Payment Estimate.            |
|        |  |                    | - Total                     |                |                 |               | \$0.00        |  |
|        | Material - Total   |                    |                             |                |                 |               | \$0.00        |  |
| 0350 - | · Total  |                    |                             |                |                 |               | \$0.00        |  |
| 0360   | CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, | Material           |                             | 1              | Jul 1,<br>2020  | SYSTEM        | (\$21,000.00) |  |
|        | CONTRACTOR FURNISHED,<br>CONTRACTOR RETAINED             |                    |                             | 1              | Jul 1,<br>2020  | SYSTEM        | \$21,000.00   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user schnod1 overridding Payment Estimate Exception 6 on the current Payment Estimate.            |
|        |  |                    | - Total                     |                |                 |               | \$0.00        |  |
|        | Material - Total   |                    |                             |                |                 |               | \$0.00        |  |
| 0360 - | · Total  |                    |                             |                |                 |               | \$0.00        |  |
| 0390   | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE    | Material           |                             | 12             | Dec 16,<br>2020 | SYSTEM        | (\$510.30)    |  |
|        |  |                    |                             | 12             | Dec 16,<br>2020 | SYSTEM        | \$510.30      | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user schnod1 overridding Payment Estimate Exception 8 on the current Payment Estimate.            |
|        |  |                    |                             | 13             | Jan 4,<br>2021  | SYSTEM        | (\$510.30)    |  |
|        |  |                    |                             | 13             | Jan 4,<br>2021  | SYSTEM        | \$510.30      | This adjustment offsets the original system-generated Material<br>Payment Estimate Item Adjustment (0007) due to user schnod1<br>overridding Payment Estimate Exception 22 on the current<br>Payment Estimate. |
|        |  |                    |                             | 14             | Jan 19,<br>2021 | SYSTEM        | (\$510.30)    |  |
|        |  |                    |                             | 14             | Jan 19,<br>2021 | SYSTEM        | \$510.30      | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schnod1 overridding Payment Estimate Exception 22 on the current Payment Estimate.          |
|        |  |                    | - Total                     |                |                 |               | \$0.00        |  |
|        | Material - Total   |                    |                             |                |                 |               | \$0.00        |  |
| 0390 - | · Total  |                    |                             |                |                 |               | \$0.00        |  |
| 0400   | PREFORMED THERMOPLASTIC<br>PAVEMENT MARKING, 30 IN WHITE | Material           |                             | 12             | Dec 16,<br>2020 | SYSTEM        | (\$4,536.00)  |  |
|        | MIDBLOCK   |                    |                             | 12             | Dec 16,<br>2020 | SYSTEM        | \$4,536.00    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user schnod1 overridding Payment Estimate Exception 9 on the current Payment Estimate.            |

Revision 4/1/2020 Page 21 of 30



| Line   | Description   | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By | Amount       | Remarks   |
|--------|---|--------------------|-----------------------------|----------------|-----------------|---------------|--------------|---|
| 0400   | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE                         | Material           |                             | 13             | Jan 4,<br>2021  | SYSTEM        | (\$4,536.00) |   |
|        | MIDBLOCK  |                    |                             | 13             | Jan 4,<br>2021  | SYSTEM        | \$4,536.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 23 on the current Payment Estimate.         |
|        |   |                    |                             | 14             | Jan 19,<br>2021 | SYSTEM        | (\$4,536.00) |   |
|        |   |                    |                             | 14             | Jan 19,<br>2021 | SYSTEM        | \$4,536.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 23 on the current Payment Estimate.         |
|        |   |                    | - Total                     |                |                 |               | \$0.00       |   |
|        | Material - Total  |                    |                             |                |                 |               | \$0.00       |   |
| 0400 - | Total   |                    |                             |                |                 |               | \$0.00       |   |
| 0410   | PAVEMENT MARKING, 12 IN WHITE,  | Material           |                             | 14             | Jan 19,<br>2021 | SYSTEM        | (\$1,323.00) |   |
|        | YIELD LINE TRIANGLES  |                    |                             | 14             | Jan 19,<br>2021 | SYSTEM        | \$1,323.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 24 on the current Payment Estimate.         |
|        |   |                    | - Total                     |                |                 |               | \$0.00       |   |
|        | Material - Total  |                    |                             |                |                 |               | \$0.00       |   |
| 0410 - | Total   |                    |                             |                |                 |               | \$0.00       |   |
| 0420   | 4 IN. YELLOW HIGH BUILD<br>WATERBORNE PAVEMENT MARKING<br>PAINT, TYPE L BEADS | Material           |                             | 12             | Dec 16,<br>2020 | SYSTEM        | (\$1,147.05) |   |
|        | FAINT, TIFE E BEADS   |                    |                             | 12             | Dec 16,<br>2020 | SYSTEM        | \$1,147.05   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user schnod1 overridding Payment Estimate Exception 10 on the current Payment Estimate.          |
|        |   |                    | - Total                     |                |                 |               | \$0.00       |   |
|        | Material - Total  |                    |                             |                |                 |               | \$0.00       |   |
| 0420 - | Total   |                    |                             |                |                 |               | \$0.00       |   |
| 0430   | 6 IN. WHITE HIGH BUILD WATERBORNE<br>PAVEMENT MARKING PAINT, TYPE L<br>BEADS  | Material           |                             | 12             | Dec 16,<br>2020 | SYSTEM        | (\$1,481.35) |   |
|        |   |                    |                             | 12             | Dec 16,<br>2020 | SYSTEM        | \$1,481.35   | This adjustment offsets the original system-generated Overrun<br>Payment Estimate Item Adjustment (0021) due to user schnod1<br>overridding Payment Estimate Exception 12 on the current<br>Payment Estimate. |
|        |   |                    | - Total                     |                |                 |               | \$0.00       |   |
|        | Material - Total  |                    |                             |                |                 |               | \$0.00       |   |
| 0430 - | Total   |                    |                             |                |                 |               | \$0.00       |   |
| 0440   | 6 IN. YELLOW HIGH BUILD<br>WATERBORNE PAVEMENT MARKING<br>PAINT, TYPE L BEADS | Material           |                             | 12             | Dec 16,<br>2020 | SYSTEM        | (\$208.00)   |   |
|        | FAINT, TIFE E BLADS   |                    |                             | 12             | Dec 16,<br>2020 | SYSTEM        | \$208.00     | This adjustment offsets the original system-generated Overrun<br>Payment Estimate Item Adjustment (0022) due to user schnod1<br>overridding Payment Estimate Exception 14 on the current<br>Payment Estimate. |
|        |   |                    | - Total                     |                |                 |               | \$0.00       |   |
|        | Material - Total  |                    |                             |                |                 |               | \$0.00       |   |
| 0440 - | Total   |                    |                             |                |                 |               | \$0.00       |   |
| 0450   | FLOWABLE BACKFILL   | Material           |                             | 5              | Sep 2,<br>2020  | SYSTEM        | (\$6,564.50) |   |
|        |   |                    |                             | 5              | Sep 2,<br>2020  | SYSTEM        | \$6,564.50   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate.           |
|        |   |                    |                             | 6              | Sep 16,<br>2020 | SYSTEM        | (\$6,564.50) |   |
|        |   |                    |                             | 6              | Sep 16,<br>2020 | SYSTEM        | \$6,564.50   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user schnod1 overridding Payment Estimate Exception 4 on the current Payment Estimate.           |
|        |   |                    |                             | 7              | Oct 2,<br>2020  | SYSTEM        | (\$6,564.50) |   |

Revision 4/1/2020 Page 22 of 30



| Line | Description       | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By | Amount         | Remarks   |              |                 |        |            |  |
|------|-------------------|--------------------|-----------------------------|----------------|-----------------|---------------|----------------|---|--------------|-----------------|--------|------------|--|
| 0450 | FLOWABLE BACKFILL | Material           |                             | 7              | Oct 2,<br>2020  | SYSTEM        | \$6,564.50     | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user schnod1 overridding Payment Estimate Exception 22 on the current Payment Estimate.          |              |                 |        |            |  |
|      |                   |                    |                             | 8              | Oct 16,<br>2020 | SYSTEM        | (\$6,564.50)   |   |              |                 |        |            |  |
|      |                   |                    |                             | 8              | Oct 16,<br>2020 | SYSTEM        | \$6,564.50     | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user schnod1 overridding Payment Estimate Exception 15 on the current Payment Estimate.          |              |                 |        |            |  |
|      |                   |                    |                             | 9              | Nov 2,<br>2020  | SYSTEM        | (\$6,564.50)   |   |              |                 |        |            |  |
|      |                   |                    |                             | 9              | Nov 2,<br>2020  | SYSTEM        | \$6,564.50     | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user schnod1 overridding Payment Estimate Exception 28 on the current Payment Estimate.          |              |                 |        |            |  |
|      |                   |                    |                             | 10             | Nov 16,<br>2020 | SYSTEM        | (\$6,564.50)   |   |              |                 |        |            |  |
|      |                   |                    |                             | 10             | Nov 16,<br>2020 | SYSTEM        | \$6,564.50     | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user schnod1 overridding Payment Estimate Exception 14 on the current Payment Estimate.          |              |                 |        |            |  |
|      |                   |                    |                             | 11             | Dec 2,<br>2020  | SYSTEM        | (\$6,564.50)   |   |              |                 |        |            |  |
|      |                   |                    |                             | 11             | Dec 2,<br>2020  | SYSTEM        | \$6,564.50     | This adjustment offsets the original system-generated Overrun<br>Payment Estimate Item Adjustment (0011) due to user schnod1<br>overridding Payment Estimate Exception 13 on the current<br>Payment Estimate. |              |                 |        |            |  |
|      |                   |                    |                             | 12             | Dec 16,<br>2020 | SYSTEM        | (\$6,564.50)   |   |              |                 |        |            |  |
|      |                   |                    |                             |                |                 |               |                |   | 12           | Dec 16,<br>2020 | SYSTEM | \$6,564.50 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user schnod1 overridding Payment Estimate Exception 16 on the current Payment Estimate. |
|      |                   |                    |                             |                |                 | 13            | Jan 4,<br>2021 | SYSTEM  | (\$6,564.50) |                 |        |            |  |
|      |                   |                    |                             | 13             | Jan 4,<br>2021  | SYSTEM        | \$6,564.50     | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schnod1 overridding Payment Estimate Exception 24 on the current Payment Estimate.         |              |                 |        |            |  |
|      |                   |                    |                             | 14             | Jan 19,<br>2021 | SYSTEM        | (\$6,564.50)   |   |              |                 |        |            |  |
|      |                   |                    |                             | 14             | Jan 19,<br>2021 | SYSTEM        | \$6,564.50     | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schnod1 overridding Payment Estimate Exception 25 on the current Payment Estimate.         |              |                 |        |            |  |
|      |                   |                    |                             | 15             | Feb 2,<br>2021  | SYSTEM        | (\$6,564.50)   |   |              |                 |        |            |  |
|      |                   |                    |                             | 15             | Feb 2,<br>2021  | SYSTEM        | \$6,564.50     | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schnod1 overridding Payment Estimate Exception 8 on the current Payment Estimate.          |              |                 |        |            |  |
|      |                   |                    |                             | 16             | Feb 16,<br>2021 | SYSTEM        | (\$6,564.50)   |   |              |                 |        |            |  |
|      |                   |                    |                             | 16             | Feb 16,<br>2021 | SYSTEM        | \$6,564.50     | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user yostj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.           |              |                 |        |            |  |
|      |                   |                    |                             | 17             | Mar 2,<br>2021  | SYSTEM        | (\$6,564.50)   |   |              |                 |        |            |  |
|      |                   |                    |                             | 17             | Mar 2,<br>2021  | SYSTEM        | \$6,564.50     | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schnod1 overridding Payment Estimate Exception 8 on the current Payment Estimate.          |              |                 |        |            |  |
|      |                   |                    |                             | 18             | Mar 16,<br>2021 | SYSTEM        | (\$6,564.50)   |   |              |                 |        |            |  |
|      |                   |                    |                             | 18             | Mar 16,<br>2021 | SYSTEM        | \$6,564.50     | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schnod1 overridding Payment Estimate Exception 10 on the current Payment Estimate.         |              |                 |        |            |  |
|      |                   |                    | - Total                     |                |                 |               | \$0.00         |   |              |                 |        |            |  |

Revision 4/1/2020 Page 23 of 30



| Line   | Description                                | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By | Amount         | Remarks   |                |                |              |  |  |
|--------|--|--------------------|-----------------------------|----------------|-----------------|---------------|----------------|---|----------------|----------------|--------------|--|--|
| 0450   | Material - Total                           |                    |                             |                |                 |               | \$0.00         |   |                |                |              |  |  |
| 0450 - | · Total                                    |                    |                             |                |                 |               | \$0.00         |   |                |                |              |  |  |
| 0480   | MECHANICALLY STABILIZED EARTH WALL SYSTEMS | Material           |                             | 7              | Oct 2,<br>2020  | SYSTEM        | (\$254,795.62) |   |                |                |              |  |  |
|        |  |                    |                             | 7              | Oct 2,<br>2020  | SYSTEM        | \$254,795.62   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user schnod1 overridding Payment Estimate Exception 23 on the current Payment Estimate.  |                |                |              |  |  |
|        |  |                    |                             | 8              | Oct 16,<br>2020 | SYSTEM        | (\$254,795.62) |   |                |                |              |  |  |
|        |  |                    |                             | 8              | Oct 16,<br>2020 | SYSTEM        | \$254,795.62   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 16 on the current Payment Estimate.  |                |                |              |  |  |
|        |  |                    |                             |                |                 |               |                |   | 9              | Nov 2,<br>2020 | SYSTEM       | (\$254,795.62)   |  |
|        |  |                    |                             |                |                 |               |                | 9   | Nov 2,<br>2020 | SYSTEM         | \$254,795.62 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user schnod1 overridding Payment Estimate Exception 29 on the current Payment Estimate. |  |
|        |  |                    |                             | 10             | Nov 16,<br>2020 | SYSTEM        | (\$254,795.62) |   |                |                |              |  |  |
|        |  |                    |                             | 10             | Nov 16,<br>2020 | SYSTEM        | \$254,795.62   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user schnod1 overridding Payment Estimate Exception 15 on the current Payment Estimate.  |                |                |              |  |  |
|        |  |                    |                             | 11             | Dec 2,<br>2020  | SYSTEM        | (\$254,795.62) |   |                |                |              |  |  |
|        |  |                    |                             | 11             | Dec 2,<br>2020  | SYSTEM        | \$254,795.62   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 14 on the current Payment Estimate.  |                |                |              |  |  |
|        |  |                    |                             | 12             | Dec 16,<br>2020 | SYSTEM        | (\$283,106.25) |   |                |                |              |  |  |
|        |  |                    |                             | 12             | Dec 16,<br>2020 | SYSTEM        | \$283,106.25   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user schnod1 overridding Payment Estimate Exception 17 on the current Payment Estimate.  |                |                |              |  |  |
|        |  |                    |                             | 13             | Jan 4,<br>2021  | SYSTEM        | (\$283,106.25) |   |                |                |              |  |  |
|        |  |                    |                             | 13             | Jan 4,<br>2021  | SYSTEM        | \$283,106.25   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schnod1 overridding Payment Estimate Exception 25 on the current Payment Estimate. |                |                |              |  |  |
|        |  |                    |                             | 14             | Jan 19,<br>2021 | SYSTEM        | (\$283,106.25) |   |                |                |              |  |  |
|        |  |                    |                             | 14             | Jan 19,<br>2021 | SYSTEM        | \$283,106.25   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schnod1 overridding Payment Estimate Exception 26 on the current Payment Estimate. |                |                |              |  |  |
|        |  |                    |                             | 15             | Feb 2,<br>2021  | SYSTEM        | (\$283,106.25) |   |                |                |              |  |  |
|        |  |                    |                             | 15             | Feb 2,<br>2021  | SYSTEM        | \$283,106.25   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schnod1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  |                |                |              |  |  |
|        |  |                    |                             | 16             | Feb 16,<br>2021 | SYSTEM        | (\$283,106.25) |   |                |                |              |  |  |
|        |  |                    |                             | 16             | Feb 16,<br>2021 | SYSTEM        | \$283,106.25   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user yostj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.   |                |                |              |  |  |
|        |  |                    |                             | 17             | Mar 2,<br>2021  | SYSTEM        | (\$283,106.25) |   |                |                |              |  |  |
|        |  |                    |                             | 17             | Mar 2,<br>2021  | SYSTEM        | \$283,106.25   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schnod1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  |                |                |              |  |  |
|        |  |                    |                             | 18             | Mar 16,<br>2021 | SYSTEM        | (\$283,106.25) |   |                |                |              |  |  |

Revision 4/1/2020 Page 24 of 30



| Line   | Description                                   | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By | Amount       | Remarks  |
|--------|---|--------------------|-----------------------------|----------------|-----------------|---------------|--------------|--|
| 0480   | MECHANICALLY STABILIZED EARTH<br>WALL SYSTEMS | Material           |                             | 18             | Mar 16,<br>2021 | SYSTEM        | \$283,106.25 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schnod1 overridding Payment Estimate Exception 11 on the current Payment Estimate.          |
|        |   |                    | - Total                     |                |                 |               | \$0.00       |  |
|        | Material - Total                              |                    |                             |                |                 |               | \$0.00       |  |
| 0480 - | - Total                                       |                    |                             |                |                 |               | \$0.00       |  |
| 0490   | FORM LINERS FOR MSE WALL SYSTEMS              | Material           |                             | 7              | Oct 2,<br>2020  | SYSTEM        | (\$458.85)   |  |
|        |   |                    |                             | 7              | Oct 2,<br>2020  | SYSTEM        | \$458.85     | This adjustment offsets the original system-generated Overrun<br>Payment Estimate Item Adjustment (0015) due to user schnod1<br>overridding Payment Estimate Exception 27 on the current<br>Payment Estimate.  |
|        |   |                    |                             | 8              | Oct 16,<br>2020 | SYSTEM        | (\$458.85)   |  |
|        |   |                    |                             | 8              | Oct 16,<br>2020 | SYSTEM        | \$458.85     | This adjustment offsets the original system-generated Overrun<br>Payment Estimate Item Adjustment (0013) due to user schnod1<br>overridding Payment Estimate Exception 20 on the current<br>Payment Estimate.  |
|        |   |                    |                             | 9              | Nov 2,<br>2020  | SYSTEM        | (\$458.85)   |  |
|        |   |                    |                             | 9              | Nov 2,<br>2020  | SYSTEM        | \$458.85     | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user schnod1 overridding Payment Estimate Exception 32 on the current Payment Estimate.           |
|        |   |                    |                             | 10             | Nov 16,<br>2020 | SYSTEM        | (\$458.85)   |  |
|        |   |                    |                             | 10             | Nov 16,<br>2020 | SYSTEM        | \$458.85     | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user schnod1 overridding Payment Estimate Exception 18 on the current Payment Estimate.           |
|        |   |                    |                             | 11             | Dec 2,<br>2020  | SYSTEM        | (\$458.85)   |  |
|        |   |                    |                             | 11             | Dec 2,<br>2020  | SYSTEM        | \$458.85     | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user schnod1 overridding Payment Estimate Exception 17 on the current Payment Estimate.           |
|        |   |                    |                             | 12             | Dec 16,<br>2020 | SYSTEM        | (\$458.85)   |  |
|        |   |                    |                             | 12             | Dec 16,<br>2020 | SYSTEM        | \$458.85     | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user schnod1 overridding Payment Estimate Exception 22 on the current Payment Estimate.           |
|        |   |                    |                             | 13             | Jan 4,<br>2021  | SYSTEM        | (\$458.85)   |  |
|        |   |                    |                             | 13             | Jan 4,<br>2021  | SYSTEM        | \$458.85     | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schnod1 overridding Payment Estimate Exception 30 on the current Payment Estimate.          |
|        |   |                    |                             | 14             | Jan 19,<br>2021 | SYSTEM        | (\$458.85)   |  |
|        |   |                    |                             | 14             | Jan 19,<br>2021 | SYSTEM        | \$458.85     | This adjustment offsets the original system-generated Material<br>Payment Estimate Item Adjustment (0011) due to user schnod1<br>overridding Payment Estimate Exception 31 on the current<br>Payment Estimate. |
|        |   |                    |                             | 15             | Feb 2,<br>2021  | SYSTEM        | (\$458.85)   |  |
|        |   |                    |                             | 15             | Feb 2,<br>2021  | SYSTEM        | \$458.85     | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 14 on the current Payment Estimate.          |
|        |   |                    |                             | 16             | Feb 16,<br>2021 | SYSTEM        | (\$458.85)   |  |
|        |   |                    |                             | 16             | Feb 16,<br>2021 | SYSTEM        | \$458.85     | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user yostj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.           |
|        |   |                    |                             | 17             | Mar 2,<br>2021  | SYSTEM        | (\$458.85)   |  |
|        |   |                    |                             | 17             | Mar 2,          | SYSTEM        | \$458.85     | This adjustment offsets the original system-generated Material   |

Revision 4/1/2020 Page 25 of 30



| Line   | Description                             | Adjustment | Other              | Est.   | Created         | Created  | Amount        | Remarks  |
|--------|---|------------|--------------------|--------|-----------------|----------|---------------|--|
|        |   | Type       | Adjustment<br>Type | Number | Date            | Ву       |               |  |
| 0490   | FORM LINERS FOR MSE WALL SYSTEMS        | Material   |                    |        | 2021            |          |               | Payment Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 14 on the current Payment Estimate.   |
|        |   |            |                    | 18     | Mar 16,<br>2021 | SYSTEM   | (\$458.85)    |  |
|        |   |            |                    | 18     | Mar 16,<br>2021 | SYSTEM   | \$458.85      | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schnod1 overridding Payment Estimate Exception 16 on the current Payment Estimate.        |
|        |   |            | - Total            |        |                 |          | \$0.00        |  |
|        | Material - Total                        |            |                    |        |                 |          | \$0.00        |  |
| 0490 - |   |            |                    | -      |                 | 2)/2==1/ | \$0.00        |  |
| 0570   | PRECAST CONCRETE MANHOLE - 48 IN.       | Material   |                    | 5      | Sep 2,<br>2020  | SYSTEM   | (\$3,274.50)  |  |
|        |   |            |                    | 5      | Sep 2,<br>2020  | SYSTEM   | \$3,274.50    | This adjustment offsets the original system-generated Overrun<br>Payment Estimate Item Adjustment (0004) due to user schnod1<br>overridding Payment Estimate Exception 4 on the current Payment<br>Estimate. |
|        |   |            |                    | 6      | Sep 16,<br>2020 | SYSTEM   | (\$3,274.50)  |  |
|        |   |            |                    | 6      | Sep 16,<br>2020 | SYSTEM   | \$3,274.50    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user schnod1 overridding Payment Estimate Exception 5 on the current Payment Estimate.          |
|        |   |            | - Total            |        |                 |          | \$0.00        |  |
|        | Material - Total                        |            |                    |        |                 |          | \$0.00        |  |
| 0570 - | · Total                                 |            |                    |        |                 |          | \$0.00        |  |
| 0580   | PRECAST CONCRETE MANHOLE - 72 IN.       | Material   |                    | 2      | Jul 16,<br>2020 | SYSTEM   | (\$29,268.00) |  |
|        |   |            |                    | 2      | Jul 16,<br>2020 | SYSTEM   | \$29,268.00   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate.          |
|        |   |            |                    | 3      | Aug 3,<br>2020  | SYSTEM   | (\$29,268.00) |  |
|        |   |            |                    | 3      | Aug 3,<br>2020  | SYSTEM   | \$29,268.00   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate.          |
|        |   |            |                    | 4      | Aug 17,<br>2020 | SYSTEM   | (\$29,268.00) |  |
|        |   |            |                    | 4      | Aug 17,<br>2020 | SYSTEM   | \$29,268.00   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate.          |
|        |   |            |                    | 5      | Sep 2,<br>2020  | SYSTEM   | (\$29,268.00) |  |
|        |   |            |                    | 5      | Sep 2,<br>2020  | SYSTEM   | \$29,268.00   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user schnod1 overridding Payment Estimate Exception 5 on the current Payment Estimate.          |
|        |   |            |                    | 6      | Sep 16,<br>2020 | SYSTEM   | (\$29,268.00) |  |
|        |   |            |                    | 6      | Sep 16,<br>2020 | SYSTEM   | \$29,268.00   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 6 on the current Payment Estimate.          |
|        |   |            | - Total            |        |                 |          | \$0.00        |  |
|        | Material - Total                        |            |                    |        |                 |          | \$0.00        |  |
| 0580 - |   | Material   |                    | 4      | Λυσ 17          | QVQTEMA  | \$0.00        |  |
| 0590   | PRECAST CONCRETE DROP INLET 2 FT X 2 FT | iviaterial |                    |        | Aug 17,<br>2020 | SYSTEM   | (\$4,878.60)  |  |
|        |   |            |                    | 4      | Aug 17,<br>2020 | SYSTEM   | \$4,878.60    | This adjustment offsets the original system-generated Overrun<br>Payment Estimate Item Adjustment (0003) due to user schnod1<br>overridding Payment Estimate Exception 3 on the current Payment<br>Estimate. |
|        |   |            |                    | 5      | Sep 2,<br>2020  | SYSTEM   | (\$4,878.60)  |  |

Revision 4/1/2020 Page 26 of 30



| Line   | Description                             | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By | Amount       | Remarks   |
|--------|---|--------------------|-----------------------------|----------------|-----------------|---------------|--------------|---|
| 0590   | PRECAST CONCRETE DROP INLET 2 FT X 2 FT | Material           |                             | 5              | Sep 2,<br>2020  | SYSTEM        | \$4,878.60   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user schnod1 overridding Payment Estimate Exception 6 on the current Payment Estimate.           |
|        |   |                    |                             | 6              | Sep 16,<br>2020 | SYSTEM        | (\$4,878.60) |   |
|        |   |                    |                             | 6              | Sep 16,<br>2020 | SYSTEM        | \$4,878.60   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 7 on the current Payment Estimate.           |
|        |   |                    |                             | 7              | Oct 2,<br>2020  | SYSTEM        | (\$4,878.60) |   |
|        |   |                    |                             | 7              | Oct 2,<br>2020  | SYSTEM        | \$4,878.60   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user schnod1 overridding Payment Estimate Exception 28 on the current Payment Estimate.          |
|        |   |                    | - Total                     |                |                 |               | \$0.00       |   |
|        | Material - Total                        |                    |                             |                |                 |               | \$0.00       |   |
| 0590 - | Total                                   |                    |                             |                |                 |               | \$0.00       |   |
| 0680   | KENTUCKY BLUEGRASS SODDING              | Material           |                             | 11             | Dec 2,<br>2020  | SYSTEM        | (\$6,278.00) |   |
|        |   |                    |                             | 11             | Dec 2,<br>2020  | SYSTEM        | \$6,278.00   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user schnod1 overridding Payment Estimate Exception 18 on the current Payment Estimate.          |
|        |   |                    | - Total                     |                |                 |               | \$0.00       |   |
|        | Material - Total                        |                    |                             |                |                 |               | \$0.00       |   |
| 0680 - | Total                                   |                    |                             |                |                 |               | \$0.00       |   |
| 0690   | BUFFALOGRASS SODDING                    | Material           |                             | 11             | Dec 2,<br>2020  | SYSTEM        | (\$7,494.20) |   |
|        |   |                    |                             | 11             | Dec 2,<br>2020  | SYSTEM        | \$7,494.20   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user schnod1 overridding Payment Estimate Exception 19 on the current Payment Estimate.          |
|        |   |                    | - Total                     |                |                 |               | \$0.00       |   |
|        | Material - Total                        |                    |                             |                |                 |               | \$0.00       |   |
| 0690 - | Total                                   |                    |                             |                |                 |               | \$0.00       |   |
| 0700   | SEEDING - COOL SEASON MIXTURES          | Material           |                             | 12             | Dec 16,<br>2020 | SYSTEM        | (\$3,615.15) |   |
|        |   |                    |                             | 12             | Dec 16,<br>2020 | SYSTEM        | \$3,615.15   | This adjustment offsets the original system-generated Overrun<br>Payment Estimate Item Adjustment (0026) due to user schnod1<br>overridding Payment Estimate Exception 23 on the current<br>Payment Estimate. |
|        |   |                    |                             | 13             | Jan 4,<br>2021  | SYSTEM        | (\$3,615.15) |   |
|        |   |                    |                             | 13             | Jan 4,<br>2021  | SYSTEM        | \$3,615.15   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 31 on the current Payment Estimate.         |
|        |   |                    |                             | 14             | Jan 19,<br>2021 | SYSTEM        | (\$3,615.15) |   |
|        |   |                    |                             | 14             | Jan 19,<br>2021 | SYSTEM        | \$3,615.15   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 32 on the current Payment Estimate.         |
|        |   |                    | - Total                     |                |                 |               | \$0.00       |   |
|        | Material - Total                        |                    |                             |                |                 |               | \$0.00       |   |
| 0700 - | Total                                   |                    |                             |                |                 |               | \$0.00       |   |
| 0720   | CURB INLET CHECK                        | Material           |                             | 8              | Oct 16,<br>2020 | SYSTEM        | (\$409.50)   |   |
|        |   |                    |                             | 8              | Oct 16,<br>2020 | SYSTEM        | \$409.50     | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user schnod1 overridding Payment Estimate Exception 21 on the current Payment Estimate.          |
|        |   |                    | - Total                     |                |                 |               | \$0.00       |   |
|        | Material - Total                        |                    |                             |                |                 |               | \$0.00       |   |

Revision 4/1/2020 Page 27 of 30



|        | Description                                       | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By | Amount       | Remarks  |
|--------|---|--------------------|-----------------------------|----------------|-----------------|---------------|--------------|--|
| 0720 - | · Total   |                    |                             |                |                 |               | \$0.00       |  |
| 0750   | SILT FENCE  | Material           |                             | 1              | Jul 1,<br>2020  | SYSTEM        | (\$544.00)   |  |
|        |   |                    |                             | 1              | Jul 1,<br>2020  | SYSTEM        | \$544.00     | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 7 on the current Payment Estimate.            |
|        |   |                    | - Total                     |                |                 |               | \$0.00       |  |
|        | Material - Total                                  |                    |                             |                |                 |               | \$0.00       |  |
| 0750 - | Total   |                    |                             |                |                 |               | \$0.00       |  |
| 1040   | CONCRETE FOOTINGS, EMBEDDED                       | Material           |                             | 12             | Dec 16,<br>2020 | SYSTEM        | (\$840.00)   |  |
|        |   |                    |                             | 12             | Dec 16,<br>2020 | SYSTEM        | \$840.00     | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 26 on the current Payment Estimate.           |
|        |   |                    |                             | 13             | Jan 4,<br>2021  | SYSTEM        | (\$840.00)   |  |
|        |   |                    |                             | 13             | Jan 4,<br>2021  | SYSTEM        | \$840.00     | This adjustment offsets the original system-generated Material<br>Payment Estimate Item Adjustment (0015) due to user schnod1<br>overridding Payment Estimate Exception 34 on the current<br>Payment Estimate. |
|        |   |                    |                             | 14             | Jan 19,<br>2021 | SYSTEM        | (\$840.00)   |  |
|        |   |                    |                             | 14             | Jan 19,<br>2021 | SYSTEM        | \$840.00     | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schnod1 overridding Payment Estimate Exception 35 on the current Payment Estimate.          |
|        |   |                    |                             | 15             | Feb 2,<br>2021  | SYSTEM        | (\$840.00)   |  |
|        |   |                    |                             | 15             | Feb 2,<br>2021  | SYSTEM        | \$840.00     | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 15 on the current Payment Estimate.          |
|        |   |                    |                             | 16             | Feb 16,<br>2021 | SYSTEM        | (\$840.00)   |  |
|        |   |                    |                             | 16             | Feb 16,<br>2021 | SYSTEM        | \$840.00     | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user yostj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.           |
|        |   |                    |                             | 17             | Mar 2,<br>2021  | SYSTEM        | (\$840.00)   |  |
|        |   |                    |                             | 17             | Mar 2,<br>2021  | SYSTEM        | \$840.00     | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 15 on the current Payment Estimate.          |
|        |   |                    |                             | 18             | Mar 16,<br>2021 | SYSTEM        | (\$840.00)   |  |
|        |   |                    |                             | 18             | Mar 16,<br>2021 | SYSTEM        | \$840.00     | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schnod1 overridding Payment Estimate Exception 17 on the current Payment Estimate.          |
|        |   |                    | - Total                     |                |                 |               | \$0.00       |  |
|        | Material - Total                                  |                    |                             |                |                 |               | \$0.00       |  |
| 1040 - | Total   |                    |                             |                |                 |               | \$0.00       |  |
| 1050   | BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE) | Material           |                             | 12             | Dec 16,<br>2020 | SYSTEM        | (\$1,050.00) |  |
|        |   |                    |                             | 12             | Dec 16,<br>2020 | SYSTEM        | \$1,050.00   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user schnod1 overridding Payment Estimate Exception 27 on the current Payment Estimate.           |
|        |   |                    |                             | 13             | Jan 4,<br>2021  | SYSTEM        | (\$1,050.00) |  |
|        |   |                    |                             | 13             | Jan 4,<br>2021  | SYSTEM        | \$1,050.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schnod1 overridding Payment Estimate Exception 35 on the current Payment Estimate.          |
|        |   |                    | - Total                     |                |                 |               | \$0.00       |  |

Revision 4/1/2020 Page 28 of 30



| Line   | Description   | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number                   | Created<br>Date   | Created<br>By                             | Amount   | Remarks  |
|--------|---|--------------------|-----------------------------|----------------------------------|---|---|--|--|
| 1050   | Material - Total                                    |                    |                             |                                  |   |   | \$0.00   |  |
| 1050 - | Total   |                    |                             |                                  |   |   | \$0.00   |  |
| 1060   | 2 IN. PSST POST - 12 GA.                            | Material           |                             | 12                               | Dec 16,<br>2020   | SYSTEM                                    | (\$3,980.90)   |  |
|        |   |                    |                             | 12                               | Dec 16,<br>2020   | SYSTEM                                    | \$3,980.90   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user schnod1 overridding Payment Estimate Exception 28 on the current Payment Estimate.   |
|        |   |                    |                             | 13                               | Jan 4,<br>2021  | SYSTEM                                    | (\$3,980.90)   |  |
|        |   |                    |                             | 13                               | Jan 4,<br>2021  | SYSTEM                                    | \$3,980.90   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schnod1 overridding Payment Estimate Exception 36 on the current Payment Estimate.  |
|        |   |                    | - Total                     |                                  |   |   | \$0.00   |  |
|        | Material - Total                                    |                    |                             |                                  |   |   | \$0.00   |  |
| 060 -  | Total   |                    |                             |                                  |   |   | \$0.00   |  |
| 070    | POST ANCHOR FOR 2 IN. PSST - 12 GA.                 | Material           |                             | 12                               | Dec 16,<br>2020   | SYSTEM                                    | (\$1,883.70)   |  |
|        |   |                    |                             | 12                               | Dec 16,<br>2020   | SYSTEM                                    | \$1,883.70   | This adjustment offsets the original system-generated Overrun<br>Payment Estimate Item Adjustment (0011) due to user schnod1<br>overridding Payment Estimate Exception 29 on the current<br>Payment Estimate.  |
|        |   |                    |                             | 13                               | Jan 4,<br>2021  | SYSTEM                                    | (\$1,883.70)   |  |
|        |   |                    |                             | 13                               | Jan 4,<br>2021  | SYSTEM                                    | \$1,883.70   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Exception 37 on the current Payment Estimate.  |
|        |   |                    | - Total                     |                                  |   |   | \$0.00   |  |
|        | Material - Total                                    |                    |                             |                                  |   |   | \$0.00   |  |
| 070 -  | Total   |                    |                             |                                  |   |   | \$0.00   |  |
| 080    | 2.25 IN. PSST POST - 12 GA.                         | Material           |                             | 12                               | Dec 16,   | SYSTEM                                    | (\$352.80)   |  |
|        |   |                    |                             |                                  | 2020  |   | ` ′  |  |
|        |   |                    |                             | 12                               |   | SYSTEM                                    | \$352.80   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 30 on the current Payment Estimate.   |
|        |   |                    |                             |                                  | 2020<br>Dec 16,   |   | ` ′  | Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 30 on the current   |
|        |   |                    |                             | 12                               | 2020<br>Dec 16,<br>2020   | SYSTEM                                    | \$352.80   | Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 30 on the current   |
|        |   |                    | - Total                     | 12                               | 2020 Dec 16, 2020  Jan 4, 2021 Jan 4,   | SYSTEM                                    | \$352.80<br>(\$352.80)<br>\$352.80   | Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 30 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schnod1 overridding Payment Estimate Exception 38 on the current  |
|        | Material - Total                                    |                    | - Total                     | 12                               | 2020  Dec 16, 2020  Jan 4, 2021  Jan 4,   | SYSTEM                                    | \$352.80<br>(\$352.80)<br>\$352.80<br>\$0.00   | Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 30 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schnod1 overridding Payment Estimate Exception 38 on the current  |
| 080 -  | Total   |                    | - Total                     | 12                               | 2020  Dec 16, 2020  Jan 4, 2021  Jan 4,   | SYSTEM                                    | \$352.80<br>(\$352.80)<br>\$352.80<br>\$0.00<br>\$0.00   | Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 30 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schnod1 overridding Payment Estimate Exception 38 on the current  |
|        |   | Material           | - Total                     | 12 13 13 12                      | 2020 Dec 16, 2020 Jan 4, 2021 Jan 4, 2021 Dec 16, 2020  | SYSTEM SYSTEM SYSTEM SYSTEM               | \$352.80<br>(\$352.80)<br>\$352.80<br>\$0.00<br>\$0.00<br>(\$2,646.00)   | Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 30 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schnod1 overridding Payment Estimate Exception 38 on the current Payment Estimate.  |
|        | Total   | Material           | - Total                     | 13 13                            | 2020 Dec 16, 2020 Jan 4, 2021 Jan 4, 2021 Dec 16, 2021  | SYSTEM SYSTEM SYSTEM                      | \$352.80<br>(\$352.80)<br>\$352.80<br>\$0.00<br>\$0.00   | Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 30 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schnod1 overridding Payment Estimate Exception 38 on the current  |
|        | Total   | Material           | - Total                     | 12 13 13 12                      | 2020 Dec 16, 2020 Jan 4, 2021 Jan 4, 2021 Dec 16, 2020 Dec 16, 16, 2020                                   | SYSTEM SYSTEM SYSTEM SYSTEM               | \$352.80<br>(\$352.80)<br>\$352.80<br>\$0.00<br>\$0.00<br>(\$2,646.00)   | Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 30 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schnod1 overridding Payment Estimate Exception 38 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user schnod1 overridding Payment Estimate Item Adjustment (0013) due to user schnod1 overridding Payment Estimate Exception 31 on the current  |
|        | Total   | Material           | - Total                     | 12<br>13<br>13<br>12<br>12       | Dec 16, 2021  Jan 4, 2021  Jan 4, 2021  Dec 16, 2020  Dec 16, 2020  Jan 4, 2021                           | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM        | \$352.80<br>(\$352.80)<br>\$352.80<br>\$0.00<br>\$0.00<br>(\$2,646.00)   | Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 30 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schnod1 overridding Payment Estimate Exception 38 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user schnod1 overridding Payment Estimate Item Adjustment (0013) due to user schnod1 overridding Payment Estimate Exception 31 on the current  |
|        | Total   | Material           | - Total                     | 12<br>13<br>13<br>12<br>12<br>12 | Dec 16, 2021  Jan 4, 2021  Jan 4, 2021  Jan 4, 2021  Dec 16, 2020  Dec 16, 2020  Jan 4, 2021  Jan 4, 2021 | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$352.80<br>(\$352.80)<br>\$352.80<br>\$0.00<br>\$0.00<br>(\$2,646.00)<br>\$2,646.00                                       | Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 30 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schnod1 overridding Payment Estimate Exception 38 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user schnod1 overridding Payment Estimate Exception 31 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schnod1 overridding Payment Estimate Item Adjustment (0018) due to user schnod1 overridding Payment Estimate Item Adjustment (0018) due to user schnod1 overridding Payment Estimate Exception 39 on the current |
|        | Total   | Material           |                             | 12<br>13<br>13<br>12<br>12<br>12 | Dec 16, 2021  Jan 4, 2021  Jan 4, 2021  Jan 4, 2021  Dec 16, 2020  Dec 16, 2020  Jan 4, 2021  Jan 4, 2021 | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$352.80<br>(\$352.80)<br>\$352.80<br>\$0.00<br>\$0.00<br>(\$2,646.00)<br>\$2,646.00<br>(\$2,646.00)                       | Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 30 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schnod1 overridding Payment Estimate Exception 38 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user schnod1 overridding Payment Estimate Exception 31 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schnod1 overridding Payment Estimate Item Adjustment (0018) due to user schnod1 overridding Payment Estimate Item Adjustment (0018) due to user schnod1 overridding Payment Estimate Exception 39 on the current |
| 1090   | Total  2.5 IN. PSST POST - 12 GA.                   | Material           |                             | 12<br>13<br>13<br>12<br>12<br>12 | Dec 16, 2021  Jan 4, 2021  Jan 4, 2021  Jan 4, 2021  Dec 16, 2020  Dec 16, 2020  Jan 4, 2021  Jan 4, 2021 | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$352.80<br>(\$352.80)<br>\$352.80<br>\$0.00<br>\$0.00<br>(\$2,646.00)<br>\$2,646.00<br>(\$2,646.00)<br>\$2,646.00         | Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 30 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schnod1 overridding Payment Estimate Exception 38 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user schnod1 overridding Payment Estimate Exception 31 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schnod1 overridding Payment Estimate Item Adjustment (0018) due to user schnod1 overridding Payment Estimate Exception 39 on the current   |
| 1090   | Total  2.5 IN. PSST POST - 12 GA.  Material - Total |                    |                             | 12<br>13<br>13<br>12<br>12<br>12 | Dec 16, 2021  Jan 4, 2021  Jan 4, 2021  Jan 4, 2021  Dec 16, 2020  Dec 16, 2020  Jan 4, 2021  Jan 4, 2021 | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$352.80<br>(\$352.80)<br>\$352.80<br>\$0.00<br>\$0.00<br>\$0.00<br>(\$2,646.00)<br>\$2,646.00<br>\$2,646.00<br>\$2,646.00 | Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 30 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schnod1 overridding Payment Estimate Exception 38 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user schnod1 overridding Payment Estimate Exception 31 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schnod1 overridding Payment Estimate Item Adjustment (0018) due to user schnod1 overridding Payment Estimate Exception 39 on the current   |

Revision 4/1/2020 Page 29 of 30



|                    | Description                          | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date                                      | Created<br>By | Amount   | Remarks   |
|--------------------|--------------------------------------|--------------------|-----------------------------|----------------|--|---------------|--|---|
| 1100               | POST ANCHOR FOR 2.5 IN. PSST - 7 GA. | Material           |                             |                |  |               |  | overridding Payment Estimate Exception 32 on the current Payment Estimate.  |
|                    |                                      |                    |                             | 13             | Jan 4,<br>2021                                       | SYSTEM        | (\$1,701.00)   |   |
|                    |                                      |                    |                             | 13             | Jan 4,<br>2021                                       | SYSTEM        | \$1,701.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schnod1 overridding Payment Estimate Exception 40 on the current Payment Estimate.   |
|                    |                                      |                    | - Total                     |                |  |               | \$0.00   |   |
|                    | Material - Total                     |                    |                             |                |  |               | \$0.00   |   |
| 1100 -             | - Total                              |                    |                             |                |  |               | \$0.00   |   |
| 1110               | SH-FLAT SHEET                        | Material           |                             | 12             | Dec 16,<br>2020                                      | SYSTEM        | (\$3,250.80)   |   |
|                    |                                      |                    |                             | 12             | Dec 16,<br>2020                                      | SYSTEM        | \$3,250.80   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user schnod1 overridding Payment Estimate Exception 33 on the current Payment Estimate.  |
|                    |                                      |                    |                             | 13             | Jan 4,<br>2021                                       | SYSTEM        | (\$3,250.80)   |   |
|                    |                                      |                    |                             | 13             | Jan 4,<br>2021                                       | SYSTEM        | \$3,250.80   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schnod1 overridding Payment Estimate Exception 41 on the current Payment Estimate.   |
|                    |                                      |                    | - Total                     |                |  |               | \$0.00   |   |
|                    | Material - Total                     |                    |                             |                |  |               | \$0.00   |   |
| 1110 -             | - Total                              |                    |                             |                |  |               | \$0.00   |   |
| 1120               | SHF-FLAT SHEET FLUORESCENT           | Material           |                             | 12             | Dec 16,<br>2020                                      | SYSTEM        | (\$4,623.10)   |   |
|                    |                                      |                    |                             | 12             | Dec 16,<br>2020                                      | SYSTEM        | \$4,623.10   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user schnod1   |
|                    |                                      |                    |                             |                |  |               |  | overridding Payment Estimate Exception 34 on the current Payment Estimate.  |
|                    |                                      |                    |                             | 13             | Jan 4,<br>2021                                       | SYSTEM        | (\$4,623.10)   | overridding Payment Estimate Exception 34 on the current  |
|                    |                                      |                    |                             | 13             |  | SYSTEM        | (\$4,623.10)<br>\$4,623.10   | overridding Payment Estimate Exception 34 on the current  |
|                    |                                      |                    | - Total                     |                | 2021<br>Jan 4,                                       |               |  | overridding Payment Estimate Exception 34 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schnod1 overridding Payment Estimate Exception 42 on the current   |
|                    | Material - Total                     |                    | - Total                     |                | 2021<br>Jan 4,                                       |               | \$4,623.10   | overridding Payment Estimate Exception 34 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schnod1 overridding Payment Estimate Exception 42 on the current   |
| 1120 -             | Material - Total<br>- Total          |                    | - Total                     |                | 2021<br>Jan 4,                                       |               | \$4,623.10<br>\$0.00   | overridding Payment Estimate Exception 34 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schnod1 overridding Payment Estimate Exception 42 on the current   |
| <b>1120</b> - 5003 |                                      | Material           | - Total                     |                | 2021<br>Jan 4,                                       |               | \$4,623.10<br>\$0.00<br>\$0.00   | overridding Payment Estimate Exception 34 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schnod1 overridding Payment Estimate Exception 42 on the current   |
|                    | - Total                              | Material           | - Total                     | 13             | 2021<br>Jan 4,<br>2021<br>Mar 16,                    | SYSTEM        | \$4,623.10<br>\$0.00<br>\$0.00<br>\$0.00                               | overridding Payment Estimate Exception 34 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schnod1 overridding Payment Estimate Exception 42 on the current   |
|                    | - Total FRENCH UNDERDRAIN            | Material           | - Total                     | 13             | 2021<br>Jan 4,<br>2021<br>Mar 16,<br>2021<br>Mar 16, | SYSTEM        | \$4,623.10<br>\$0.00<br>\$0.00<br>\$0.00<br>(\$9,495.50)               | overridding Payment Estimate Exception 34 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schnod1 overridding Payment Estimate Exception 42 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment |
|                    | - Total                              | Material           |                             | 13             | 2021<br>Jan 4,<br>2021<br>Mar 16,<br>2021<br>Mar 16, | SYSTEM        | \$4,623.10<br>\$0.00<br>\$0.00<br>\$0.00<br>(\$9,495.50)<br>\$9,495.50 | overridding Payment Estimate Exception 34 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schnod1 overridding Payment Estimate Exception 42 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment |
| 5003               | - Total FRENCH UNDERDRAIN            | Material           |                             | 13             | 2021<br>Jan 4,<br>2021<br>Mar 16,<br>2021<br>Mar 16, | SYSTEM        | \$4,623.10<br>\$0.00<br>\$0.00<br>\$0.00<br>(\$9,495.50)<br>\$9,495.50 | overridding Payment Estimate Exception 34 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schnod1 overridding Payment Estimate Exception 42 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment |

Revision 4/1/2020 Page 30 of 30