

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: February 16, 2022

Progress Estimate Number	Contract ID 200515-D01	Pay Period Start February 2, 2022 Original Contract Amount \$507,803.50
20	Prime Contractor Meyer Electric Company, In	c. Pay Period End February 15, 2022 Net Change Order Amount (\$512.73) Current Contract Amount \$507,290.77

Approval Date		By User
February 17, 2022	Generated and Approved (and should be considered Draft) at the Project Office Level by	stokez1
February 17, 2022	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	browns1
February 18, 2022	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete				
November 10, 2020	August 20, 2021	December 13, 2021	99.21%				

	Contract Informational Dates											
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract									
Acceptance Date												
Awarded Date	June 3, 2020	June 3, 2020										
Letting Date	May 15, 2020	May 15, 2020										
Notice to Proceed Date	July 6, 2020	July 6, 2020										
Open to Traffic Date												
Work Began Date	April 5, 2021	April 5, 2021										

Contract Total Pay For Estimate No. 20										
		This Estimate	Previous	To Date						
200515-D01										
	Total Posted Items Pay	\$0.00	\$503,307.77	\$503,307.77						
	Gross Item Adjustments	\$2,810.00	(\$2,810.00)	\$0.00						
	Incentive	\$0.00	\$0.00	\$0.00						
	Disincentive	\$0.00	\$0.00	\$0.00						
	Liquidated Damage	\$0.00	\$0.00	\$0.00						
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00						
			\$500,497.77	\$503,307.77						
Contract Total Payab	le This Estimate:	\$2,810.00								

Items Paid This Estimate Period

No Data Available

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

		stments Exist on Contract						
Line Item	Adjusti	ments This Estimate						
Project Number	Line No.			Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5P3426	0770	STRUCTURAL STEEL POSTS	MaterialCredit			50	\$25.00	\$1,250.00
	0770	STRUCTURAL STEEL POSTS	Material			-50	\$25.00	(\$1,250.00)
	0770	STRUCTURAL STEEL POSTS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user stokez1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	50	\$25.00	\$1,250.00
	0780	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE)	MaterialCredit			4	\$205.00	\$820.00
	0780	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE)	Material			-4	\$205.00	(\$820.00)
	0780	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	4	\$205.00	\$820.00
	0790	2.5 IN. PSST POST - 12 GA.	Material			-64	\$11.00	(\$704.00)

Revision 4/1/2020 Page 1 of 22



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: February 16, 2022

Progress Estimate Number 20 Contract ID 200515-D01 Pay Period Start February 2, 2022 Original Contract Amount \$507,803.50 Prime Contractor Meyer Electric Company, Inc. Pay Period End February 15, 2022 Net Change Order Amount (\$512.73) Current Contract Amount \$507,290.77

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5P3426	0790	2.5 IN. PSST POST - 12 GA.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	64	\$11.00	\$704.00
	0800	POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	Material			-12	\$40.00	(\$480.00)
	0800	POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	12	\$40.00	\$480.00
	0810	SH-FLAT SHEET	MaterialCredit			37	\$20.00	\$740.00
	0810	SH-FLAT SHEET	Material			-37	\$20.00	(\$740.00)
	0810	SH-FLAT SHEET	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user stokez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	37	\$20.00	\$740.00
	5002	MISC.	Material			-6	\$866.67	(\$5,200.02)
	5002	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	6	\$866.67	\$5,200.02
Total								\$2,810.00

Revision 4/1/2020 Page 2 of 22



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Information	n				
Project Number	Federal Proj. Number	Project Description	Route	County		Location of Work					
J5P3426	5P3426 FAF Signal improvements Warious MILLER at MO 52 and RT CC in Eldon; at RT OO and Summit Dr. in Holts Summit; at RT C and RT CC in Eldon; at RT OO and Summit Dr. in Holts Summit; at RT C and RT CC in Eldon; at RT OO and Summit Dr. in Holts Summit; at RT C and RT CC in Eldon; at RT OO and Summit Dr. in Holts Summit; at RT C and RT CC in Eldon; at RT OO and Summit Dr. in Holts Summit; at RT C and RT CC in Eldon; at RT OO and Summit Dr. in Holts Summit; at RT C and RT CC in Eldon; at RT OO and Summit Dr. in Holts Summit; at RT C and RT CC in Eldon; at RT OO and Summit Dr. in Holts Summit; at RT C and RT CC in Eldon; at RT OO and Summit Dr. in Holts Summit; at RT C and RT CC in Eldon; at RT OO and Summit Dr. in Holts Summit; at RT C and RT CC in Eldon; at RT CC										
Totals by J	Job Numb	ers									
J5P3426		ed Item Pay s Item Adjustme		tem Pay	This Estimate \$0.00 \$2,810.00 \$2,810.00	Previous \$503,307.77 (\$2,810.00) \$500,497.77	To Date \$503,307.77 \$0.00 \$503,307.77				
	Liqui	ntive Icentive Idated Damages Ir Contract Adjus			\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00				

Revision 4/1/2020 Page 3 of 22



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J5P3426, Item 9029902, Project Item Line Number 5002, Material Set 9029902, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	stokez1 Certification has been received and needs to be entered by MoDOT	stokez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3426, Item 9031210, Project Item Line Number 0770, Material Set 903121096, Material 0903HSPSSS - Structural Steel Post for Highway Signin, Acceptance Action Generic 0903HSPSSS is insufficient.	stokez1 Certification has been received and needs to be entered by MoDOT	stokez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3426, Item 9031241, Project Item Line Number 0780, Material Set 903124196, Material 0903HSBA - Breakaway Assembly for Highway Signing, Acceptance Action Generic 0903HSBA is insufficient.	stokez1 Certification has been received and needs to be entered by MoDOT	stokez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3426, Item 9031280, Project Item Line Number 0790, Material Set 903128096, Material 0903HSTS - Tubular Steel Sign Support, Acceptance Action Generic 0903HSTS is insufficient.	stokez1 Certification has been received and needs to be entered by MoDOT	stokez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3426, Item 9031281, Project Item Line Number 0800, Material Set 903128196, Material 0903HSTS - Tubular Steel Sign Support, Acceptance Action Generic 0903HSTS is insufficient.	stokez1 Certification has been received and needs to be entered by MoDOT	stokez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3426, Item 9035004A, Project Item Line Number 0810, Material Set 9035004A96, Material 1042SM - Sign Material, Acceptance Action Generic 1042SM is insufficient.	stokez1 Certification has been received and needs to be entered by MoDOT	stokez1	Overridden

Revision 4/1/2020 Page 4 of 22



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Im.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repor generated date)
00515-D01	J5P3426	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	-	\$13,600.00	\$13,600.0
		0001	0020	6083006	6 IN. CONCRETE MEDIAN STRIP	2.40	0.00	2.40	SQYD	2.40	\$600.00	\$1,440.0
		0001	0030	6161005	CONSTRUCTION SIGNS	903.00	-475.00	428.00	SQFT	428.00	\$7.50	\$3,210.0
		0001	0040	6161009	FLAG ASSEMBLY	8.00	-8.00	0.00	EA	0.00	\$25.00	\$0.0
		0001	0050	6161010	RELOCATED SIGNS	965.00	-269.00	696.00	SQFT	696.00	\$7.00	\$4,872.0
		0001	0060	6161025	CHANNELIZER (TRIM LINE)	260.00	0.00	260.00	EA	260.00	\$25.00	\$6,500.0
		0001	0070	6161040	FLASHING ARROW PANEL	2.00	-2.00	0.00	EA	0.00	\$925.00	\$0.0
		0001	0080	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	4.00	\$4,000.00	\$16,000.0
		0001	0090	6169902	MISC.DETECTABLE PEDESTRIAN CHANNELIZING BARRICADE - TYPE II	4.00	0.00	4.00	EA	4.00	\$160.00	\$640.0
		0001	0100	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$15,800.00	\$15,800.0
		0001	0110	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	6.00	0.00	0 6.00	EA	6.00	\$600.00	\$3,600.0
		0001	0120	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	48.00	66.00	114.00	LF	114.00	\$25.00	\$2,850.
		0001	0130	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	62.00	0.00	62.00	LF	62.00	\$2.00	\$124.
		0001	0140	6206001C	4 IN, YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	16.00	0.00	16.00	LF	16.00	\$2.00	\$32.
		0001	0150	6206108A	8 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	117.00	0.00	117.00	LF	117.00	\$3.00	\$351.
		0001	0160	6207001	PAVEMENT MARKING REMOVAL	137.00	0.00	137.00	LF	137.00	\$3.00	\$411.
		0001	0170	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	3.00	0.00	3.00	EA	3.00	\$125.00	\$375
		0001	0180	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$2,800.00	\$2,800
		0001	0190	8061006	ALTERNATE DITCH CHECK	370.00	-31.00	339.00	LF	339.00	\$13.00	\$4,407
		0001	0200	8061007A	CURB INLET CHECK	2.00	2.00	4.00	EA	4.00	\$250.00	\$1,000
		0001	0210	8061016	SEDIMENT REMOVAL LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 1 LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 2		-35.00	2.00	CUYD	2.00	\$30.00	\$60
		0020	0220	9011060			-3.00	0.00	EA	0.00	\$2,742.00	\$0
		0020	0230	9011062			-1.00	0.00	EA	0.00	\$2,313.00	\$0
		0020	0240	9011115	BRACKET ARM, 15 FT. OR 4.6 M	4.00	0.00	4.00	EA	4.00	\$760.00	\$3,040
		0020 0250 9011311 LUMINAIRE, LED-A	LUMINAIRE, LED-A	7.00	0.00	7.00	EA	0.00	\$569.00	\$0		
		0020	0260	9011312	LUMINAIRE, LED-B	4.00	0.00	4.00	EA	4.00	\$610.00	\$2,440
		0020	0270	9012230	BASE MOUNTED CONTROL STATION 240 VOLT - 4 CIRCUIT	1.00	0.00	1.00	EA	1.00	\$5,300.00	\$5,300
		0020	0280	9013002	CONDUIT, 2 IN. RIGID, IN TRENCH	63.00	52.00	115.00	LF	115.00	\$10.00	\$1,150
		0020	0290	9013003	CONDUIT, 3 IN. RIGID, IN TRENCH	116.00	-42.00	74.00	LF	74.00	\$11.00	\$814
		0020	0300	9013004	CONDUIT, 4 IN. RIGID, IN TRENCH	56.00	0.00	56.00	LF	56.00	\$12.00	\$672
		0020	0310	9014004	CONDUIT, 4 IN. RIGID, PUSHED	266.00	0.00	266.00	LF	266.00	\$18.00	\$4,788
		0020	0320	9016110	PULL BOX, PREFORMED CLASS 1	4.00	0.00	4.00	EA	4.00	\$1,000.00	\$4,000
		0020	0330	9017002	CABLE, 2 AWG 1 CONDUCTOR	240.00	0.00	240.00	LF	240.00	\$2.10	\$504
		0020	0340	9017008	CABLE, 8 AWG 1 CONDUCTOR	1,260.00	0.00	1,260.00	LF	1,260.00	\$1.20	\$1,512
		0020	0350	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	480.00	0.00	480.00	LF	480.00	\$0.85	\$408
		0020	0360	9018245	POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	4.00	0.00	4.00	EA	4.00	\$1,200.00	\$4,800
		0020	0370	9018613	POWER SUPPLY ASSEMBLY, TYPE 2, 240/120 VOLT SERVICE,	3.00	0.00	3.00	EA	3.00	\$3,395.00	\$10,185
		0030	0380	9020113	LIGHTING AND SIGNALS SIGNAL HEAD, TYPE 3T	1.00	0.00	1.00	EA	1.00	\$739.00	\$739
		0030	0390	9020213	SIGNAL HEAD, TYPE 3S	8.00	0.00	8.00	EA	8.00	\$707.00	\$5,656
		0030	0400	9020513	SIGNAL HEAD, TYPE 3B	22.00	-1.00	21.00	EA	21.00	\$857.00	\$17,997
		0030	0410	9020514	SIGNAL HEAD, TYPE 4B	3.00	1.00	4.00	EA	4.00	\$987.00	\$3,948
		0030	0410	9020811	SIGNAL HEAD, TYPE 1S, PEDESTRIAN	6.00	0.00	6.00	EA	6.00	\$407.00	\$2,442
		0030	0430	9020833	SH-FLAT SHEET - SIGNAL SIGN	257.00	-1.00	256.00	SQFT	256.00	\$40.00	\$10,240

Revision 4/1/2020 Page 5 of 22



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract n.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See report generated date)
0515-D01	J5P3426	0030	0440	9020834	SIGNAL SIGN, MOUNTING HARDWARE	40.00	0.00	40.00	EA	40.00	\$195.00	\$7,800.0
		0030	0450	9022708	POST, SIGNAL 8 FT. OR 2.4 M	5.00	0.00	5.00	EA	5.00	\$607.00	\$3,035.0
		0030	0460	9022715	POST, SIGNAL 15 FT. OR 4.6 M	1.00	0.00	1.00	EA	1.00	\$790.00	\$790.0
		0030	0470	9023115	POST, TYPE CL, 15 FT. ARM OR 4.6 M ARM	1.00	0.00	1.00	EA	1.00	\$6,639.00	\$6,639.0
		0030	0480	9023120	POST, TYPE CL, 20 FT. ARM OR 6.1 M ARM	1.00	0.00	1.00	EA	1.00	\$6,717.00	\$6,717.0
		0030	0490	9023125	POST, TYPE CL, 25 FT. ARM OR 7.6 M ARM	2.00	0.00	2.00	EA	2.00	\$6,742.00	\$13,484.0
		0030	0500	9023130	POST, TYPE CL, 30 FT. ARM OR 9.1 M ARM	1.00	0.00	1.00	EA	1.00	\$8,289.00	\$8,289.0
		0030	0510	9023135	POST, TYPE CL, 35 FT. ARM OR 10.7 M ARM	3.00	0.00	3.00	EA	3.00	\$7,600.00	\$22,800.0
		0030	0520	9023140	POST, TYPE CL, 40 FT. ARM OR 12.2 M ARM	2.00	0.00	2.00	EA	2.00	\$9,711.00	\$19,422.
		0030	0530	9023445	POST, TYPE BL, LONGEST ARM 45 FT. OR 13.7 M	1.00	0.00	1.00	EA	1.00	\$14,515.00	\$14,515.0
		0030	0540	9024281	CONTROLLER ASSEMBLY HOUSING, KEYBOARD ENTRY, 8 PHASE NEMA CONTROLLER	3.00	0.00	3.00	EA	3.00	\$15,554.00	\$46,662.0
		0030	0550	9024920	DETECTOR, PUSHBUTTON	6.00	-6.00	0.00	EA	0.00	\$206.00	\$0.0
		0030	0560	9025200	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE	230.00	-33.00	197.00	LF	197.00	\$9.50	\$1,871.
		0030	0570	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	547.00	-26.00	521.00	LF	521.00	\$10.00	\$5,210.
		0030	0580	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	798.00	0.00	798.00	LF	798.00	\$24.00	\$19,152.
		0030	0590	9028100	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	640.00	0.00	640.00	LF	640.00	\$0.85	\$544.
		0030	0600	9028202	CABLE, 2 AWG 1 CONDUCTOR, POWER	530.00	0.00	530.00	LF	530.00	\$1.80	\$954.
		0030	0610	9028208	CABLE, 8 AWG 1 CONDUCTOR, POWER	230.00	-70.00	160.00	LF	160.00	\$1.10	\$176.
		0030 0620 9			CABLE, 12 AWG 2 CONDUCTOR	1,170.00	-50.00	1,120.00	LF	1,120.00	\$1.10	\$1,232
		0030	0630	9028308	CABLE, 16 AWG 2 CONDUCTOR	1,500.00	0.00	1,500.00	LF	1,500.00	\$1.05	\$1,575
		0030 0640 9028310			CABLE, 16 AWG 5 CONDUCTOR	1,500.00	0.00	1,500.00	LF	1,500.00	\$1.12	\$1,680
		0030	0650	9028311	CABLE, 16 AWG 7 CONDUCTOR	5,200.00	-70.00	5,130.00	LF	5,130.00	\$1.20	\$6,156
		0030	0660	9028350	FIBER OPTIC CABLE, 6 - FIBER, SINGLE MODE	620.00	10.00	630.00	LF	630.00	\$3.25	\$2,047
		0030	0670	9028510	CABLE, LOOP DETECTOR, LEAD-IN	1,080.00	10.00	1,090.00	LF	1,090.00	\$1.20	\$1,308
		0030	0680	9028810	PULL BOX, PREFORMED CLASS 1		0.00	2.00	EA	2.00	\$985.00	\$1,970
		0030	0690	9028811	PULL BOX, PREFORMED CLASS 2	9.00	0.00	9.00	EA	9.00	\$1,350.00	\$12,150
		0030	0700	9028812	PULL BOX, PREFORMED CLASS 3	2.00	0.00	2.00	EA	2.00	\$1,600.00	\$3,200
		0030	0710	9028816	PULL BOX, PREFORMED CLASS 5	1.00	0.00	1.00	EA	1.00	\$1,600.00	\$1,600
		0030	0720	9028824	PULL BOX, CONCRETE, DOUBLE TYPE B	2.00	0.00	2.00	EA	2.00	\$2,900.00	\$5,800
		0030	0730	9029100	BASE, CONCRETE	42.20	0.40	42.60	CUYD	42.60	\$1,350.00	\$57,510
		0030	0740	9029902	MISC.GRIDSMART V.D.S. Salvage	1.00	0.00	1.00	EA	1.00	\$1,600.00	\$1,600
		0030	0750	9029902	MISC.GRIDSMART Video Detection System	2.00	0.00	2.00	EA	2.00	\$23,000.00	\$46,000
		0040	0760	9031010	CONCRETE FOOTINGS, EMBEDDED	0.40	0.00	0.40	CUYD	0.40	\$1,500.00	\$600
		0040	0770	9031210	STRUCTURAL STEEL POSTS	50.00	0.00	50.00	LB	50.00	\$25.00	\$1,250
		0040	0780	9031241	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE)	4.00	0.00	4.00	EA	4.00	\$205.00	\$820
		0040	0790	9031280	2.5 IN. PSST POST - 12 GA.	64.00	0.00	64.00	LF	64.00	\$11.00	\$704
		0040	0800	9031281	POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	12.00	0.00	12.00	LF	12.00	\$40.00	\$480
		0040	0810	9035004A	SH-FLAT SHEET	37.00	0.00	37.00	SQFT	37.00	\$20.00	\$740
		0020	5001	9011064	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 3	0.00	4.00	4.00	EA	4.00	\$2,634.75	\$10,539
		0030	5002	9029902		0.00	6.00	6.00	EA	6.00	\$866.67	\$5,200
		0001	5003	6181000	MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$966.25	\$966
		0001	5004	6200009	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE	0.00	226.00	226.00	LF	226.00	\$6.25	\$1,412
	Project J	5P3426 - To	otal Value	Posted to D	late as of Report Generated Date							\$503,307

Revision 4/1/2020 Page 6 of 22



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 4/1/2020 Page 7 of 22



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks								
J5P3426	0020	6 IN. CONCRETE MEDIAN STRIP	Material		3	Apr 19, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.								
					3	Apr 19, 2021	SYSTEM	(\$1,440.00)									
						4	May 3, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.							
					4	May 3, 2021	SYSTEM	(\$1,440.00)									
					5	May 17, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.								
					5	May 17, 2021	SYSTEM	(\$1,440.00)									
					6	Jun 1, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.								
					6	Jun 1, 2021	SYSTEM	(\$1,440.00)									
					7	Jun 16, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.								
					7	Jun 16, 2021	SYSTEM	(\$1,440.00)									
					8	Jun 30, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.								
					8	Jun 30, 2021	SYSTEM	(\$1,440.00)									
					9	Jul 16, 2021	SYSTEM	(\$1,440.00)									
					10	Aug 2, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.								
					10	Aug 2, 2021	SYSTEM	(\$1,440.00)									
					11	Aug 16, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.								
					11	Aug 16, 2021	SYSTEM	(\$1,440.00)									
					12	Sep 2, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.								
					12	Sep 2, 2021	SYSTEM	(\$1,440.00)									
													13	Sep 16, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					13	Sep 16, 2021	SYSTEM	(\$1,440.00)									
				- Total				(\$1,440.00)									
			Material - Tota		4.0		2772	(\$1,440.00)									
			MaterialCredit		10	Aug 2, 2021	SYSTEM	\$1,440.00									
				- Total				\$1,440.00									
			MaterialCredit	- Total				\$1,440.00									
	0020 -	Total						\$0.00									
	0120	PREF THERMO	Material		5	May 17, 2021	SYSTEM	(\$300.00)									
		PVMT MARK, 24 IN WHIT			6	Jun 1, 2021	SYSTEM	(\$300.00)									
				- Total				(\$600.00)									



Manual Creat Manual Total Manual Creat Manu	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks						
PAYAT MARKS Machinal Credit 1001 100	J5P3426	0120		Material - Tota	ı				(\$600.00)							
170				MaterialCredit		6		SYSTEM	\$300.00							
Total			24 IN WHIT			7	Jun 16,	SYSTEM	\$300.00							
Material Credit September September							2021		4000.00							
Overrun 14 Sep 20 SYSTEM (\$1,650.00)				M (1 10 12												
18																
2022 Private Extractises - Price Adjustments of 1,25 0,0000 - 25 0,0000, 1s applied (if non-zero). 10.00				Overrun	Overrun		2021		(\$1,650.00)							
10130 Total						18		SYSTEM	\$1,650.00	previous payment estimates. Price Adjustments of ',25.00000 - 25.00000, 'is						
120 - Total					Overrun - T	otal			\$0.00							
0130 A. H. WHTE WATERBORNE PAVEMENT MARKING 0				Overrun - Tota	ıl				\$0.00							
2021 9		0120 -	Total						\$0.00							
MARKING			WATERBORNE PAVEMENT	Material		8		SYSTEM								
2021 Estimate Item Adjustment (0004) due to user stokez 1 overridding Payment						9		SYSTEM	(\$124.00)							
11													10		SYSTEM	\$124.00
1						10		SYSTEM	(\$124.00)							
12 Sep 2, SYSTEM S124.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user stokez1 overridding Payment Estimate Exception 2 on the current Payment Estimate Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Exception 2 on the current Payment Estimate Exception 3 on the										11		SYSTEM	\$124.00	Estimate Item Adjustment (0003) due to user stokez1 overridding Payment		
2021 Estimate Item Adjustment (0001) due to user stokez1 overridding Payment Estimate Exception 2 on the current Payment Estimate.															11	Aug 16, 2021
2021 13							12	Sep 2, 2021	SYSTEM	\$124.00	Estimate Item Adjustment (0001) due to user stokez1 overridding Payment					
2021 Estimate Item Adjustment (0004) due to user stokez 1 overridding Payment Estimate Exception 2 on the current Payment Estimate.							12		SYSTEM	(\$124.00)						
Aug 2, SYSTEM S248.00						13		SYSTEM	\$124.00	Estimate Item Adjustment (0004) due to user stokez1 overridding Payment						
Material - Total System \$124.00						13		SYSTEM	(\$124.00)							
MaterialCredit 9					- Total				(\$248.00)							
2021 10 Aug 2, 2021 20				Material - Tota	l e				(\$248.00)							
Total \$248.00				MaterialCredit		9		SYSTEM	\$124.00							
MaterialCredit - Total \$248.00						10		SYSTEM	\$124.00							
MaterialCredit - Total \$248.00					- Total				\$248.00							
Sumarrian Suma				Materi <u>alCredit</u>	- Total				\$248.00							
Material Material Material		01 <u>30</u> -	Total													
PAVEMENT MARKING 9 Jul 16, 2021 10 Aug 2, 2021 10 Aug 2, 2021 11 Aug 16, 2021 12 Aug 16, 2021 13 Aug 16, 2021 14 Aug 16, 2021 15 SYSTEM (\$32.00) 16 SYSTEM (\$32.00) 17 Inis adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate. 18 Aug 16, 2021 19 Jul 16, 2021 10 Aug 2, 2021 10 Aug 2, 2021 11 Aug 16, SYSTEM (\$32.00) 11 Aug 16, SYSTEM (\$32.00) 12 SYSTEM (\$32.00) 13 Aug 16, SYSTEM (\$32.00)			4 IN. YELLOW	Material		8		SYSTEM								
10 Aug 2, 2021 \$YSTEM \$32.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user stokez1 overridding Payment Estimate Exception 3 on the current Payment Estimate. 10 Aug 2, 2021 \$YSTEM (\$32.00) 11 Aug 16, 2021 \$This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Exception 3 on the current Payment Estimate. 11 Aug 16, SYSTEM (\$32.00)			PAVEMENT			9	Jul 16,	SYSTEM	(\$32.00)							
10 Aug 2, 2021 (\$32.00) 11 Aug 16, 2021 \$SYSTEM (\$32.00) This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Exception 3 on the current Payment Estimate. 11 Aug 16, SYSTEM (\$32.00)					10	10	Aug 2,	SYSTEM	\$32.00	Estimate Item Adjustment (0012) due to user stokez1 overridding Payment						
11 Aug 16, 2021 \$32.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Exception 3 on the current Payment Estimate. 11 Aug 16, SYSTEM (\$32.00)					10		SYSTEM	(\$32.00)								
11 Aug 16, SYSTEM (\$32.00)						11	Aug 16,	SYSTEM	\$32.00	Estimate Item Adjustment (0004) due to user stokez1 overridding Payment						
						11	Aug 16, 2021	SYSTEM	(\$32.00)	·						



ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks						
26	0140	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	Material		12	Sep 2, 2021	SYSTEM	\$32.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.						
		MARKING			12	Sep 2, 2021	SYSTEM	(\$32.00)							
					13	Sep 16, 2021	SYSTEM	\$32.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user stokez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.						
					13	Sep 16, 2021	SYSTEM	(\$32.00)							
				- Total				(\$64.00)							
			Material - Tota	ıl				(\$64.00)							
			MaterialCredit		9	Jul 16, 2021	SYSTEM	\$32.00							
					10	Aug 2, 2021	SYSTEM	\$32.00							
				- Total				\$64.00							
			MaterialCredit	- Total				\$64.00							
	0140 -	Total						\$0.00							
	0150	8 IN. WHITE WATERBORNE	Material		8	Jun 30, 2021	SYSTEM	(\$351.00)							
		PAVEMENT MARKING			9	Jul 16, 2021	SYSTEM	(\$351.00)							
					10	Aug 2, 2021	SYSTEM	\$351.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.						
					10	Aug 2, 2021	SYSTEM	(\$351.00)							
											11	Aug 16, 2021	SYSTEM	\$351.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
								11	Aug 16, 2021	SYSTEM	(\$351.00)				
						12	Sep 2, 2021	SYSTEM	\$351.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user stokez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.					
						12	Sep 2, 2021	SYSTEM	(\$351.00)						
					13	Sep 16, 2021	SYSTEM	\$351.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.						
					13	Sep 16, 2021	SYSTEM	(\$351.00)							
				- Total				(\$702.00)							
			Material - Tota	ıl				(\$702.00)							
			MaterialCredit		9	Jul 16, 2021	SYSTEM	\$351.00							
					10	Aug 2, 2021	SYSTEM	\$351.00							
				- Total				\$702.00							
			MaterialCredit	- Total				\$702.00							
	0150 -	Total						\$0.00							
	0190	ALTERNATE DITCH CHECK	Material		3	Apr 19, 2021	SYSTEM	(\$1,287.00)							
				- Total				(\$1,287.00)							
			Material - Tota	ıl				(\$1,287.00)							
			MaterialCredit		4	May 3, 2021	SYSTEM	\$1,287.00							
				- Total				\$1,287.00							
			MaterialCredit	- Total				\$1,287.00							
	0190 -	Total						\$0.00							



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks					
J5P3426	0200	CURB INLET CHECK	Material		3	Apr 19, 2021	SYSTEM	(\$1,000.00)						
				- Total				(\$1,000.00)						
			Material - Tota					(\$1,000.00)						
			MaterialCredit		4	May 3, 2021	SYSTEM	\$1,000.00						
				- Total				\$1,000.00						
			MaterialCredit	- Total				\$1,000.00						
			Overrun	Overrun	3	Apr 19, 2021	SYSTEM	\$500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 12 on the current Payment Estimate. Material Insufficiency Quantity 4.000; Overrun Quantity Balance 2.00.					
					3	Apr 19, 2021	SYSTEM	(\$500.00)						
					4	May 3, 2021	SYSTEM	(\$500.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).					
	0200 -				5	May 17, 2021	SYSTEM	\$500.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',250.00000 - 250.00000, 'is applied (if non-zero).					
				Overrun - Total				\$0.00						
			Overrun - Tota	ıl				\$0.00						
	0200 -	Total						\$0.00						
	0270	BASE MOUNTED CONTROL	Material		4	May 3, 2021	SYSTEM	\$5,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.					
		STATION	TION			4	May 3, 2021	SYSTEM	(\$5,300.00)					
										5	May 17, 2021	SYSTEM	\$5,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user stokez1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
							5	May 17, 2021	SYSTEM	(\$5,300.00)				
					6	Jun 1, 2021	SYSTEM	\$5,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user stokez1 overridding Payment Estimate Exception 8 on the current Payment Estimate.					
					6 Jun 1, SYSTE 2021		SYSTEM	(\$5,300.00)						
				- Total				\$0.00						
			Material - Tota	l				\$0.00						
	0270 -	Total						\$0.00						
	0280	CONDUIT, 2 IN. RIGID, IN TRENCH	Overrun	Overrun	4	May 3, 2021	SYSTEM	(\$420.00)						
					13	Sep 16, 2021	SYSTEM	(\$100.00)						
					18	Jan 18, 2022	SYSTEM	\$520.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',10.00000 - 10.00000, 'is applied (if non-zero).					
				Overrun - T	otal			\$0.00						
			Overrun - Tota	ıl				\$0.00						
	0280 -	Total						\$0.00						
	0330	CABLE, 2 AWG 1 CONDUCTOR	Material		4	May 3, 2021	SYSTEM	\$497.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user stokez1 overridding Payment Estimate Exception 8 on the current Payment Estimate.					
					4	May 3, 2021	SYSTEM	(\$497.70)						
					5	May 17, 2021	SYSTEM	\$497.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user stokez1 overridding Payment Estimate Exception 9 on the current Payment Estimate.					
					5	May 17, 2021	SYSTEM	(\$497.70)						
							6	Jun 1, 2021	SYSTEM	\$497.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user stokez1 overridding Payment			



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																		
J5P3426	0330	CABLE, 2 AWG	Material						Estimate Exception 9 on the current Payment Estimate.																		
		CONDUCTOR			6	Jun 1, 2021	SYSTEM	(\$497.70)																			
				- Total				\$0.00																			
	0000	Total	Material - Tota					\$0.00																			
	0330 -						0) (07514	\$0.00																			
	0340	CABLE, 8 AWG 1 CONDUCTOR	Material		4	May 3, 2021	SYSTEM	\$1,506.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user stokez1 overridding Payment Estimate Exception 9 on the current Payment Estimate.																		
					4	May 3, 2021	SYSTEM	(\$1,506.00)																			
					5	May 17, 2021	SYSTEM	\$1,506.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Exception 10 on the current Payment Estimate.																		
					5	May 17, 2021	SYSTEM	(\$1,506.00)																			
					6	Jun 1, 2021	SYSTEM	\$1,506.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Exception 10 on the current Payment Estimate.																		
			Material - Tota		6	Jun 1, 2021	SYSTEM	(\$1,506.00)																			
				- Total				\$0.00																			
								\$0.00																			
	0340 -	Total						\$0.00																			
	0350	CABLE, 10 AWG 1 CONDUCTOR,	Material		4	May 3, 2021	SYSTEM	\$408.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user stokez1 overridding Payment Estimate Exception 10 on the current Payment Estimate.																		
		POLE & BRACKE												4	May 3, 2021	SYSTEM	(\$408.00)										
					5	May 17, 2021	SYSTEM	\$408.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user stokez1 overridding Payment Estimate Exception 11 on the current Payment Estimate.																		
													5	May 17, 2021	SYSTEM	(\$408.00)											
										6	Jun 1, 2021	SYSTEM	\$408.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user stokez1 overridding Payment Estimate Exception 11 on the current Payment Estimate.													
					6	Jun 1, 2021	SYSTEM	(\$408.00)																			
				- Total	2021		\$0.00																				
			Material - Tota					\$0.00																			
	0350 -	Total						\$0.00																			
	0370	POWER SUPPLY ASSEMBLY,	Material		4	May 3, 2021	SYSTEM	\$3,395.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment Estimate Exception 11 on the current Payment Estimate.																		
		TYPE 2, 240/120		E 2, 1120 4	TYPE 2,	TYPE 2, 240/120										5	4	May 3, 2021	SYSTEM	(\$3,395.00)							
																							5	May 17, 2021	SYSTEM	\$3,395.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
																		5	May 17, 2021	SYSTEM	(\$3,395.00)						
							6	Jun 1, 2021	SYSTEM	\$3,395.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 12 on the current Payment Estimate.																
			7 J			6	Jun 1, 2021	SYSTEM	(\$3,395.00)																		
				7	Jun 16, 2021	SYSTEM	\$3,395.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user stokez1 overridding Payment Estimate Exception 9 on the current Payment Estimate.																			
				7	Jun 16, 2021	SYSTEM	(\$3,395.00)																				
					8	Jun 30,	SYSTEM	\$3,395.00	This adjustment offsets the original system-generated Material Payment																		



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																					
J5P3426	0370	POWER SUPPLY ASSEMBLY,	Material			2021			Estimate Item Adjustment (0007) due to user stokez1 overridding Payment Estimate Exception 11 on the current Payment Estimate.																					
		TYPE 2, 240/120			8	Jun 30, 2021	SYSTEM	(\$3,395.00)																						
					9	Jul 16, 2021	SYSTEM	(\$3,395.00)																						
					10	Aug 2, 2021	SYSTEM	(\$3,395.00)																						
					11	Aug 16, 2021	SYSTEM	\$3,395.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user stokez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.																					
					11	Aug 16, 2021	SYSTEM	(\$3,395.00)																						
					12	Sep 2, 2021	SYSTEM	\$3,395.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user stokez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.																					
					12	Sep 2, 2021	SYSTEM	(\$3,395.00)																						
					13	Sep 16, 2021	SYSTEM	\$3,395.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.																					
					13	Sep 16, 2021	SYSTEM	(\$3,395.00)																						
					14	Sep 30, 2021	SYSTEM	\$10,185.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user stokez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.																					
					14	Sep 30, 2021	SYSTEM	(\$10,185.00)																						
								15	Oct 18, 2021	SYSTEM	\$10,185.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user stokez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.																		
					15	Oct 18, 2021	SYSTEM	(\$10,185.00)																						
					16	Nov 2, 2021	SYSTEM	\$10,185.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user stokez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.																					
									16	Nov 2, 2021	SYSTEM	(\$10,185.00)																		
						17	Nov 16, 2021	SYSTEM	\$10,185.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																				
					17	Nov 16, 2021	SYSTEM	(\$10,185.00)																						
				- Total				(\$6,790.00)																						
			Material - Tota	l				(\$6,790.00)																						
			MaterialCredit		10	Aug 2, 2021	SYSTEM	\$3,395.00																						
											-		11	11			\$3,395.00													
				- Total				\$6,790.00																						
			MaterialCredit	- Total				\$6,790.00																						
	0370 -						0)/0==-	\$0.00																						
	0390		Material		4	May 3, 2021	SYSTEM	\$2,828.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user stokez1 overridding Payment Estimate Exception 12 on the current Payment Estimate.																					
											5															4	May 3, 2021	SYSTEM	(\$2,828.00)	
																5	May 17, 2021	SYSTEM	\$2,828.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment Estimate Exception 13 on the current Payment Estimate.										
			1	5	May 17, 2021	SYSTEM	(\$2,828.00)																							
							6	Jun 1, 2021	SYSTEM	\$2,828.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment																			



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3426	0390	SIGNAL HEAD, TYPE 3S	Material						Estimate Exception 13 on the current Payment Estimate.
		200			6	Jun 1, 2021	SYSTEM	(\$2,828.00)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0390 -	- Total						\$0.00	
	0400	SIGNAL HEAD, TYPE 3B	Material		4	May 3, 2021	SYSTEM	\$6,856.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user stokez1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					4	May 3, 2021	SYSTEM	(\$6,856.00)	
					5	May 17, 2021	SYSTEM	\$6,856.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user stokez1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					5	May 17, 2021	SYSTEM	(\$6,856.00)	
					6	Jun 1, 2021	SYSTEM	\$6,856.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user stokez1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					6	Jun 1, 2021	SYSTEM	(\$6,856.00)	
				- Total				\$0.00	
	0.400	T	Material - Tota	11				\$0.00	
	0400 -	SIGNAL HEAD, TYPE 4B	Overrun	Overrun	11	Aug 16, 2021	SYSTEM	\$0.00 (\$987.00)	
		TYPE 4B	E 4B		18	Jan 18, 2022	SYSTEM	\$987.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',987.00000 - 987.00000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - Tota					\$0.00	
	0410 -	· Total	Overrun - Tota					\$0.00 \$0.00	
	0410 -	SH-FLAT SHEET - SIGNAL SIGN	Overrun - Tota		4	May 3, 2021	SYSTEM		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user stokez1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
		SH-FLAT SHEET -			4		SYSTEM SYSTEM	\$0.00	Estimate Item Adjustment (0014) due to user stokez1 overridding Payment
		SH-FLAT SHEET -				2021 May 3,		\$0.00 \$3,600.00	Estimate Item Adjustment (0014) due to user stokez1 overridding Payment
		SH-FLAT SHEET -			4	2021 May 3, 2021 May 17,	SYSTEM SYSTEM	\$0.00 \$3,600.00 (\$3,600.00)	Estimate Item Adjustment (0014) due to user stokez1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment
		SH-FLAT SHEET -			5	2021 May 3, 2021 May 17, 2021	SYSTEM SYSTEM	\$0.00 \$3,600.00 (\$3,600.00) \$3,600.00	Estimate Item Adjustment (0014) due to user stokez1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment
		SH-FLAT SHEET -			5	2021 May 3, 2021 May 17, 2021 May 17, 2021 Jun 1,	SYSTEM SYSTEM	\$0.00 \$3,600.00 (\$3,600.00) \$3,600.00 (\$3,600.00)	Estimate Item Adjustment (0014) due to user stokez1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment
		SH-FLAT SHEET -			4 5 5	2021 May 3, 2021 May 17, 2021 May 17, 2021 Jun 1, 2021 Jun 1, 201	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$3,600.00 (\$3,600.00) \$3,600.00 (\$3,600.00)	Estimate Item Adjustment (0014) due to user stokez1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment
		SH-FLAT SHEET -			45566	2021 May 3, 2021 May 17, 2021 May 17, 2021 Jun 1, 2021 Jun 1, 2021 Jun 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$3,600.00 (\$3,600.00) \$3,600.00 (\$3,600.00) (\$3,600.00)	Estimate Item Adjustment (0014) due to user stokez1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Payment
		SH-FLAT SHEET -			4 5 5 6 6 7 7	2021 May 3, 2021 May 17, 2021 May 17, 2021 Jun 1, 2021 Jun 1, 2021 Jun 16, 2021 Jun 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$3,600.00 (\$3,600.00) \$3,600.00 (\$3,600.00) (\$3,600.00) \$3,600.00	Estimate Item Adjustment (0014) due to user stokez1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Payment
		SH-FLAT SHEET -			4 5 5 6 6 7 7	2021 May 3, 2021 May 17, 2021 May 17, 2021 Jun 1, 2021 Jun 1, 2021 Jun 16, 2021 Jun 16, 2021 Jun 30,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$3,600.00 (\$3,600.00) \$3,600.00 (\$3,600.00) (\$3,600.00) (\$3,600.00)	Estimate Item Adjustment (0014) due to user stokez1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Payment
		SH-FLAT SHEET -			4 5 5 6 6 7 7 8 8	2021 May 3, 2021 May 17, 2021 May 17, 2021 Jun 1, 2021 Jun 1, 2021 Jun 16, 2021 Jun 30, 2021 Jul 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$3,600.00 (\$3,600.00) \$3,600.00 (\$3,600.00) (\$3,600.00) (\$3,600.00) (\$3,600.00) (\$6,460.00)	Estimate Item Adjustment (0014) due to user stokez1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Payment
		SH-FLAT SHEET -			4 5 5 6 6 7 7 8 8 9	2021 May 3, 2021 May 17, 2021 May 17, 2021 Jun 1, 2021 Jun 1, 2021 Jun 16, 2021 Jun 30, 2021 Jul 16, 2021 Aug 2,	SYSTEM	\$0.00 \$3,600.00 (\$3,600.00) \$3,600.00 (\$3,600.00) (\$3,600.00) (\$3,600.00) (\$3,600.00) (\$6,460.00)	Estimate Item Adjustment (0014) due to user stokez1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Exception 10 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks								
J5P3426	0430	SH-FLAT SHEET -	Material		12	Sep 2, 2021	SYSTEM	(\$10,225.00)									
		SIGNAL SIGN			13	Sep 16, 2021	SYSTEM	(\$10,224.00)									
				- Total				(\$43,594.00)									
			Material - Tota	ıl				(\$43,594.00)									
			MaterialCredit		9	Jul 16, 2021	SYSTEM	\$6,460.00									
					10	Aug 2, 2021	SYSTEM	\$6,460.00									
					12	Sep 2, 2021	SYSTEM	\$10,225.00									
					13	Sep 16, 2021	SYSTEM	\$10,225.00									
					14	Sep 30, 2021	SYSTEM	\$10,224.00									
				- Total				\$43,594.00									
			MaterialCredit	- Total				\$43,594.00									
	0430 -	Total						\$0.00									
	0600	CABLE, 2 AWG 1 CONDUCTOR,	Material		4	May 3, 2021	SYSTEM	\$313.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user stokez1 overridding Payment Estimate Exception 15 on the current Payment Estimate.								
		POWER			4	May 3, 2021	SYSTEM	(\$313.20)									
					5	May 17, 2021	SYSTEM	\$313.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user stokez1 overridding Payment Estimate Exception 16 on the current Payment Estimate.								
													5	May 17, 2021	SYSTEM	(\$313.20)	
					6	Jun 1, 2021	SYSTEM	\$313.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user stokez1 overridding Payment Estimate Exception 16 on the current Payment Estimate.								
					6	6 Jun 1, SYSTEM 2021		(\$313.20)									
				- Total				\$0.00									
			Material - Tota	ıl				\$0.00									
	0600 -	Total						\$0.00									
	0610	CABLE, 8 AWG 1 CONDUCTOR, POWER	Material		4	May 3, 2021	SYSTEM	\$31.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user stokez1 overridding Payment Estimate Exception 16 on the current Payment Estimate.								
		TOWER			4	May 3, 2021	SYSTEM	(\$31.90)									
					5	May 17, 2021	SYSTEM	\$31.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user stokez1 overridding Payment Estimate Exception 17 on the current Payment Estimate.								
					5	May 17, 2021	SYSTEM	(\$31.90)									
					6	Jun 1, 2021	SYSTEM	\$31.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user stokez1 overridding Payment Estimate Exception 17 on the current Payment Estimate.								
					6	Jun 1, 2021	SYSTEM	(\$31.90)									
				- Total				\$0.00									
			Material - Tota	ıl				\$0.00									
	0610 -	Total						\$0.00									
	0630	CABLE, 16 AWG 2 CONDUCTOR	Material		4	May 3, 2021	SYSTEM	\$849.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user stokez1 overridding Payment Estimate Exception 17 on the current Payment Estimate.								
					4	May 3, 2021	SYSTEM	(\$849.45)									
					5	May 17, 2021	SYSTEM	\$849.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user stokez1 overridding Payment								



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3426	0630	CABLE, 16 AWG 2	Material						Estimate Exception 18 on the current Payment Estimate.
		CONDUCTOR			5	May 17, 2021	SYSTEM	(\$849.45)	
					6	Jun 1, 2021	SYSTEM	\$849.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user stokez1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					6	Jun 1, 2021	SYSTEM	(\$849.45)	
				- Total				\$0.00	
			Material - Tota	ı				\$0.00	
	0630 -	- Total						\$0.00	
	0640	CABLE, 16 AWG 5 CONDUCTOR	Material		4	May 3, 2021	SYSTEM	\$910.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user stokez1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					4	May 3, 2021	SYSTEM	(\$910.56)	
					5	May 17, 2021	SYSTEM	\$910.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user stokez1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					5	May 17, 2021	SYSTEM	(\$910.56)	
					6	Jun 1, 2021	SYSTEM	\$910.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user stokez1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					6	Jun 1, 2021	SYSTEM	(\$910.56)	
				- Total				\$0.00	
			Material - Tota	ı				\$0.00	
	0640 -	· Total						\$0.00	
	0650	CABLE, 16 AWG 7 CONDUCTOR	Material		4	May 3, 2021	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user stokez1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					4	May 3, 2021	SYSTEM	(\$2,424.00)	
					5	May 17, 2021	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user stokez1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					5	May 17, 2021	SYSTEM	(\$2,424.00)	
					6	Jun 1, 2021	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user stokez1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					6	Jun 1, 2021	SYSTEM	(\$2,424.00)	
				- Total				\$0.00	
			Material - Tota	ı				\$0.00	
	0650	- Total						\$0.00	
	0660	FIBER OPTIC CABLE, 6 - FIBER, SINGLE MOD	Material		8	Jun 30, 2021	SYSTEM	\$2,034.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user stokez1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
		IVIOD			8	Jun 30, 2021	SYSTEM	(\$2,034.50)	
					9	Jul 16, 2021	SYSTEM	(\$2,034.50)	
				- Total				(\$2,034.50)	
			Material - Tota	I				(\$2,034.50)	
			MaterialCredit		10	Aug 2, 2021	SYSTEM	\$2,034.50	
				- Total				\$2,034.50	
			MaterialCredit					\$2,034.50	
			Overrun	Overrun	8	Jun 30,	SYSTEM	\$19.50	This adjustment offsets the original system-generated Overrun Payment



SP-9426 ORF FIRER OPTITIC Overtun	Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks						
CABLE_LOP Overrun - Total	1 Toject	LITIC	Description		Adjustment				Amount	Kellaks						
8	J5P3426	0660	CABLE, 6 - FIBER, SINGLE	Overrun	Overrun		2021			on the current Payment Estimate. Material Insufficiency Quantity 626.000;						
9 201 9 201 10 201 10 201 10 201 10 201 10 201 10 201 10 201 10 201 10 201 10 201 10 201 10 201 10 201 10 201			MOD			8		SYSTEM	(\$19.50)							
2021						9		SYSTEM	(\$19.50)							
13 Sep 16 SYSTEM (\$13.00)						9		SYSTEM	\$19.50	Estimate Item Adjustment (0002) overridding Payment Estimate Exception 14 on the current Payment Estimate. Material Insufficiency Quantity 626.000;						
18						10		SYSTEM	(\$19.50)							
2022 Seption						13		SYSTEM	(\$13.00)							
		2000 Tabl				18		SYSTEM	\$32.50	previous payment estimates. Price Adjustments of ',3.25000 - 3.25000, 'is						
					Overrun - T	otal			\$0.00							
Overrun Figure Concept Conce			Overrun - Tota	al				\$0.00								
DETECTOR 13 Sep 16 SYSTEM (\$6.00)		0660 -	Total						\$0.00							
13		0670	DETECTOR,	Overrun	Overrun	8		SYSTEM	(\$6.00)							
2022 September			LEAD-IN			13		SYSTEM	(\$6.00)							
						18		SYSTEM	\$12.00	previous payment estimates. Price Adjustments of ',1.20000 - 1.20000, 'is						
1070 PULL BOX					Overrun - Total				\$0.00							
				Overrun - Tota	al				\$0.00							
CONCRETE, DOUBLE TYPE B 2021 Apr 19, SYSTEM (\$5.800.00) 2021 4 May 3, SYSTEM (\$5.800.00) 2021 5 May 17, SYSTEM (\$5.800.00) 2021 6 May 17, SYSTEM (\$5.800.00) 2021 6 Material - Total 2020 1 This adjustment offsets the original system-generated Material Payment Estimate Exception 20 on the current Payment Estimate. 2020 1 This adjustment (0012) due to user stokez1 overridding Payment Estimate Exception 21 on the current Payment Estimate. 2020 1 This adjustment offsets the original system-generated Material Payment Estimate Exception 21 on the current Payment Estimate. 2020 - Total 2021 3 Apr 19, SYSTEM (\$5.800.00) 2020 1 This adjustment offsets the original system-generated Material Payment Estimate Exception 21 on the current Payment Estimate Exception 21 on the current Payment Estimate Exception 21 on the current Payment Estimate Exception 11 on the current Payment Estimate Estimate Exception 11 on the current Payment Estimate Estimate Exception 11 on the current Payment Estimate Exception 11 on the current Payment Estimate Estimate Exception 11 on the current Payment Estimate Exception 12 on the current Payment Estimate Exception 22 on the current Payment Estimate Exception 22 on the current Payment Estimate Exception 22 on the current Payment Estimate Estimate Exception 23 on the current Payment Estimate Exception 23 on the current Payment Estimate Extended Exception 23 on the current Payment Estimate Exception 23 on the current Payment Estimate Extended		0670 -	Total						\$0.00							
Apr 19, 2021 SYSTEM S5,800.00		0720	CONCRETE, DOUBLE TYPE	Material		3		SYSTEM	\$5,800.00	Estimate Item Adjustment (0005) due to user stokez1 overridding Payment						
2021 Estimate Item Adjustment (0020) due to user stokez1 overridding Payment Estimate Exception 20 on the current Payment Estimate.			Б			3		SYSTEM	(\$5,800.00)							
2021						4		SYSTEM	\$5,800.00	Estimate Item Adjustment (0020) due to user stokez1 overridding Payment						
System S						4		SYSTEM	(\$5,800.00)							
Total \$0.00						5		SYSTEM	\$5,800.00	Estimate Item Adjustment (0012) due to user stokez1 overridding Payment						
Solution						5		SYSTEM	(\$5,800.00)							
Solution					- Total				\$0.00							
BASE, CONCRETE Material 3				Material - Tota	ıl				\$0.00							
CONCRETE 2021 Estimate Item Adjustment (0006) due to user stokez1 overridding Payment Estimate Exception 11 on the current Payment Estimate. 3 Apr 19, 2021 4 May 3, 2021 SYSTEM \$18,508.50 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user stokez1 overridding Payment Estimate Exception 22 on the current Payment Estimate. 4 May 3, 2021 SYSTEM \$22,923.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 23 on the current Payment Estimate Exception 23 on the current Payment Estimate.		0720 -	Total						\$0.00							
2021 4 May 3, 2021 \$18,508.50 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user stokez1 overridding Payment Estimate Exception 22 on the current Payment Estimate. 4 May 3, 2021 \$2921 \$2923.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user stokez1 overridding Payment Estimate Exception 23 on the current Payment Estimate.		0730		Material		3		SYSTEM	\$18,508.50	Estimate Item Adjustment (0006) due to user stokez1 overridding Payment						
Estimate Item Adjustment (0021) due to user stokez1 overridding Payment Estimate Exception 22 on the current Payment Estimate. 4 May 3, 2021 5 May 17, 2021 \$22,923.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user stokez1 overridding Payment Estimate Exception 23 on the current Payment Estimate.						3		SYSTEM	(\$18,508.50)							
5 May 17, 2021 \$22,923.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user stokez1 overridding Payment Estimate Exception 23 on the current Payment Estimate.						4	4		SYSTEM	\$18,508.50	Estimate Item Adjustment (0021) due to user stokez1 overridding Payment					
2021 Estimate Item Adjustment (0013) due to user stokez1 overridding Payment Estimate Exception 23 on the current Payment Estimate.						4		SYSTEM	(\$18,508.50)							
5 May 17, SYSTEM (\$22,923.00)						5		SYSTEM	\$22,923.00	Estimate Item Adjustment (0013) due to user stokez1 overridding Payment						
												5	May 17,	SYSTEM	(\$22,923.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3426	0730	BASE,	Material			2021			
		CONCRETE			6	Jun 1, 2021	SYSTEM	\$29,416.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user stokez1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					6	Jun 1, 2021	SYSTEM	(\$29,416.50)	
					7	Jun 16, 2021	SYSTEM	\$37,719.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					7	Jun 16, 2021	SYSTEM	(\$37,719.00)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
			Overrun	Overrun	14	Sep 30, 2021	SYSTEM	(\$540.00)	
					18	Jan 18, 2022	SYSTEM	\$540.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',1350.00000 - 1350.00000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - Tota	al				\$0.00	
	0730 -	- Total						\$0.00	
	0750	MISC.	Construction Stockpile		4	May 3, 2021	SYSTEM	(\$22,999.15)	Payment Estimate Item Adjustment generated Stockpile Transaction
					11	Aug 16, 2021	SYSTEM	(\$14,990.85)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total		2021		(\$37,990.00)	
			Construction		otal			(\$37,990.00)	
			Construction	otoonpiio it	1	Aug 3,	SYSTEM	\$37,990.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			Construction Stockpile STMI		·	2020	0.0.2	ψοι,σσσ.σσ	- aymon zoumato tom rajacimon gonorated etectipile manedetten
			STIVII	- Total					
				- Total				\$37,990.00	
			Construction		VII - Total			\$37,990.00 \$37,990.00	
	0750 -	- Total	Construction		/II - Total				
	0750 - 0770	- Total STRUCTURAL STEEL POSTS	Construction Material		MI - Total	Sep 2, 2021	SYSTEM	\$37,990.00	
		STRUCTURAL					SYSTEM SYSTEM	\$37,990.00 \$0.00	
		STRUCTURAL			12	2021 Sep 16,		\$37,990.00 \$0.00 (\$1,250.00)	
		STRUCTURAL			12	2021 Sep 16, 2021 Sep 30,	SYSTEM	\$37,990.00 \$0.00 (\$1,250.00) (\$1,250.00)	
		STRUCTURAL			12 13 14	2021 Sep 16, 2021 Sep 30, 2021 Oct 18,	SYSTEM SYSTEM	\$37,990.00 \$0.00 (\$1,250.00) (\$1,250.00) (\$1,250.00) (\$1,250.00)	
		STRUCTURAL			12 13 14 15	2021 Sep 16, 2021 Sep 30, 2021 Oct 18, 2021 Nov 2,	SYSTEM SYSTEM	\$37,990.00 \$0.00 (\$1,250.00) (\$1,250.00) (\$1,250.00) (\$1,250.00)	
		STRUCTURAL			12 13 14 15	2021 Sep 16, 2021 Sep 30, 2021 Oct 18, 2021 Nov 2, 2021 Nov 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$37,990.00 \$0.00 (\$1,250.00) (\$1,250.00) (\$1,250.00) (\$1,250.00) (\$1,250.00)	
		STRUCTURAL			12 13 14 15 16 17	2021 Sep 16, 2021 Sep 30, 2021 Oct 18, 2021 Nov 2, 2021 Nov 16, 2021 Jan 18,	SYSTEM SYSTEM SYSTEM SYSTEM	\$37,990.00 \$0.00 (\$1,250.00) (\$1,250.00) (\$1,250.00) (\$1,250.00) (\$1,250.00)	
		STRUCTURAL			12 13 14 15 16 17	2021 Sep 16, 2021 Sep 30, 2021 Oct 18, 2021 Nov 2, 2021 Nov 16, 2021 Jan 18, 2022 Feb 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$37,990.00 \$0.00 (\$1,250.00) (\$1,250.00) (\$1,250.00) (\$1,250.00) (\$1,250.00) (\$1,250.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user stokez1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
		STRUCTURAL			12 13 14 15 16 17 18	2021 Sep 16, 2021 Sep 30, 2021 Oct 18, 2021 Nov 2, 2021 Jan 18, 2022 Feb 1, 2022 Feb 17,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$37,990.00 \$0.00 (\$1,250.00) (\$1,250.00) (\$1,250.00) (\$1,250.00) (\$1,250.00) (\$1,250.00) (\$1,250.00)	Estimate Item Adjustment (0002) due to user stokez1 overridding Payment
		STRUCTURAL			12 13 14 15 16 17 18 19	2021 Sep 16, 2021 Sep 30, 2021 Oct 18, 2021 Nov 2, 2021 Nov 16, 2021 Jan 18, 2022 Feb 1, 2022 Feb 17, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$37,990.00 \$0.00 (\$1,250.00) (\$1,250.00) (\$1,250.00) (\$1,250.00) (\$1,250.00) (\$1,250.00) (\$1,250.00) (\$1,250.00)	Estimate Item Adjustment (0002) due to user stokez1 overridding Payment
		STRUCTURAL		Stockpile STI	12 13 14 15 16 17 18 19	2021 Sep 16, 2021 Sep 30, 2021 Oct 18, 2021 Nov 2, 2021 Nov 16, 2021 Jan 18, 2022 Feb 1, 2022 Feb 17, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$37,990.00 \$0.00 (\$1,250.00) (\$1,250.00) (\$1,250.00) (\$1,250.00) (\$1,250.00) (\$1,250.00) (\$1,250.00) (\$1,250.00)	Estimate Item Adjustment (0002) due to user stokez1 overridding Payment
		STRUCTURAL	Material	Stockpile STI	12 13 14 15 16 17 18 19	2021 Sep 16, 2021 Sep 30, 2021 Oct 18, 2021 Nov 2, 2021 Nov 16, 2021 Jan 18, 2022 Feb 1, 2022 Feb 17, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$37,990.00 \$0.00 (\$1,250.00) (\$1,250.00) (\$1,250.00) (\$1,250.00) (\$1,250.00) (\$1,250.00) (\$1,250.00) (\$1,250.00) (\$1,250.00)	Estimate Item Adjustment (0002) due to user stokez1 overridding Payment
		STRUCTURAL	Material Material - Tota	Stockpile STI	12 13 14 15 16 17 18 19 20 20	2021 Sep 16, 2021 Sep 30, 2021 Oct 18, 2021 Nov 2, 2021 Jan 18, 2022 Feb 1, 2022 Feb 17, 2022 Feb 17, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$37,990.00 \$0.00 (\$1,250.00) (\$1,250.00) (\$1,250.00) (\$1,250.00) (\$1,250.00) (\$1,250.00) (\$1,250.00) (\$1,250.00) (\$1,250.00) (\$1,250.00) (\$1,250.00) (\$1,000.00)	Estimate Item Adjustment (0002) due to user stokez1 overridding Payment



roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
P3426	0770	STRUCTURAL STEEL POSTS	MaterialCredit			2021							
		3122270313			16	Nov 2, 2021	SYSTEM	\$1,250.00					
					17	Nov 16, 2021	SYSTEM	\$1,250.00					
					18	Jan 18, 2022	SYSTEM	\$1,250.00					
					19	Feb 1, 2022	SYSTEM	\$1,250.00					
					20	Feb 17, 2022	SYSTEM	\$1,250.00					
				- Total				\$10,000.00					
			MaterialCredit	- Total				\$10,000.00					
	0770 -				40	0 0	0)/0==:	\$0.00					
	0780	BREAKAWAY ASSEMBLY (PERFORATED	Material		12	Sep 2, 2021	SYSTEM	(\$820.00)					
		SQUARE STEEL TUBE)			13	Sep 16, 2021	SYSTEM	(\$820.00)					
					14	Sep 30, 2021	SYSTEM	(\$820.00)					
					15	Oct 18, 2021	SYSTEM	(\$820.00)					
					16	Nov 2, 2021	SYSTEM	(\$820.00)					
								17	Nov 16, 2021	SYSTEM	(\$820.00)		
													18
					19	Feb 1, 2022	SYSTEM	(\$820.00)					
									20	Feb 17, 2022	SYSTEM	\$820.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
									20	Feb 17, 2022	SYSTEM	(\$820.00)	
				- Total				(\$6,560.00)					
			Material - Tota	ıl				(\$6,560.00)					
			MaterialCredit		13	Sep 16, 2021	SYSTEM	\$820.00					
					14	Sep 30, 2021	SYSTEM	\$820.00					
					15	2021	SYSTEM	\$820.00					
					16	Nov 2, 2021	SYSTEM	\$820.00					
					17	Nov 16, 2021	SYSTEM	\$820.00					
					18	Jan 18, 2022	SYSTEM	\$820.00					
					19	Feb 1, 2022	SYSTEM	\$820.00					
					20	Feb 17, 2022	SYSTEM	\$820.00					
				- Total				\$6,560.00					
	0=00		MaterialCredit	- Total				\$6,560.00					
	0780 - 0790	2.5 IN. PSST	Material		12	Sep 2,	SYSTEM	\$0.00 (\$704.00)					
		POST - 12 GA.			13	2021 Sep 16,	SYSTEM	(\$704.00)					
						2021							



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks										
J5P3426	0790	2.5 IN. PSST POST - 12 GA.	Material		14	Sep 30, 2021	SYSTEM	(\$704.00)											
					15	Oct 18, 2021	SYSTEM	(\$704.00)											
					16	Nov 2, 2021	SYSTEM	\$704.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user stokez1 overridding Payment Estimate Exception 8 on the current Payment Estimate.										
					16	Nov 2, 2021	SYSTEM	(\$704.00)											
					17	Nov 16, 2021	SYSTEM	\$704.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.										
					17	Nov 16, 2021	SYSTEM	(\$704.00)											
					18	Jan 18, 2022	SYSTEM	\$704.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.										
					18	Jan 18, 2022	SYSTEM	(\$704.00)											
					19	Feb 1, 2022	SYSTEM	\$704.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.										
					19	Feb 1, 2022	SYSTEM	(\$704.00)											
					20	Feb 17, 2022	SYSTEM	\$704.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.										
					20	Feb 17, 2022	SYSTEM	(\$704.00)											
				- Total				(\$2,816.00)											
			Material - Tota					(\$2,816.00)											
			Material - Total		13	Sep 16, 2021	SYSTEM	\$704.00											
					14	Sep 30, 2021	SYSTEM	\$704.00											
					15	Oct 18, 2021	SYSTEM	\$704.00											
					16	Nov 2, 2021	SYSTEM	\$704.00											
				- Total				\$2,816.00											
			MaterialCredit	- Total				\$2,816.00											
	0790 -	Total						\$0.00											
	0800	ANCHOR FOR	Material		12	Sep 2, 2021	SYSTEM	(\$480.00)											
		2.5 IN. PSST - 7 GA.			13	Sep 16, 2021	SYSTEM	(\$480.00)											
															14	Sep 30, 2021	SYSTEM	(\$480.00)	
					15	Oct 18, 2021	SYSTEM	(\$480.00)											
					16	Nov 2, 2021	SYSTEM	\$480.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user stokez1 overridding Payment Estimate Exception 9 on the current Payment Estimate.										
					16	Nov 2, 2021	SYSTEM	(\$480.00)											
					17	Nov 16, 2021	SYSTEM	\$480.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user stokez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.										
					17	Nov 16, 2021	SYSTEM	(\$480.00)											
					18	Jan 18, 2022	SYSTEM	\$480.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user stokez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.										



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
			Type	Adjustment Type	Number	Date	Ву		
J5P3426	0800	POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	Material		18	Jan 18, 2022	SYSTEM	(\$480.00)	
					19	Feb 1, 2022	SYSTEM	\$480.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					19	Feb 1, 2022	SYSTEM	(\$480.00)	
					20	Feb 17, 2022	SYSTEM	\$480.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					20	Feb 17, 2022	SYSTEM	(\$480.00)	
				- Total				(\$1,920.00)	
			Material - Tota					(\$1,920.00)	
			MaterialCredit		13	Sep 16, 2021	SYSTEM	\$480.00	
					14	Sep 30, 2021	SYSTEM	\$480.00	
					15	Oct 18, 2021	SYSTEM	\$480.00	
					16	Nov 2, 2021	SYSTEM	\$480.00	
				- Total				\$1,920.00	
			MaterialCredit	- Total				\$1,920.00	
	0800 -	· Total						\$0.00	
	0810	SH-FLAT SHEET	Material		12	Sep 2, 2021	SYSTEM	(\$740.00)	
					13	Sep 16, 2021	SYSTEM	(\$740.00)	
					14	Sep 30, 2021	SYSTEM	(\$740.00)	
					15	Oct 18, 2021	SYSTEM	(\$740.00)	
					16	Nov 2, 2021	SYSTEM	(\$740.00)	
					17	Nov 16, 2021	SYSTEM	(\$740.00)	
					18	Jan 18, 2022	SYSTEM	(\$740.00)	
					19	Feb 1, 2022	SYSTEM	(\$740.00)	
					20	Feb 17, 2022	SYSTEM	\$740.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user stokez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					20	Feb 17, 2022	SYSTEM	(\$740.00)	
				- Total				(\$5,920.00)	
			Material - Tota					(\$5,920.00)	
			MaterialCredit		13	Sep 16, 2021	SYSTEM	\$740.00	
					14	Sep 30, 2021	SYSTEM	\$740.00	
					15	Oct 18, 2021	SYSTEM	\$740.00	
					16	Nov 2, 2021	SYSTEM	\$740.00	
					17	Nov 16, 2021	SYSTEM	\$740.00	
					18	Jan 18, 2022	SYSTEM	\$740.00	
					19	Feb 1, 2022	SYSTEM	\$740.00	





Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
			Туре	Adjustment Type	Number	Date	Ву		
J5P3426	0810	SH-FLAT SHEET	MaterialCredit		20	Feb 17, 2022	SYSTEM	\$740.00	
				- Total				\$5,920.00	
			MaterialCredit	redit - Total				\$5,920.00	
	0810 -	0810 - Total							
	5001	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT	Material		7	Jun 16, 2021	SYSTEM	\$10,539.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					7	Jun 16, 2021	SYSTEM	(\$10,539.00)	
				- Total				\$0.00	
			Material - Tota	Material - Total				\$0.00	
	5001 -	Total						\$0.00	
	5002	MISC.	Material		19	Feb 1, 2022	SYSTEM	\$5,200.02	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user stokez1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					19	Feb 1, 2022	SYSTEM	(\$5,200.02)	
					20	Feb 17, 2022	SYSTEM	\$5,200.02	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					20	Feb 17, 2022	SYSTEM	(\$5,200.02)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	5002 -	Total						\$0.00	
	5004	PREF THERMO PAVMT MARKING, 6 IN WHITE	Material		19	Feb 1, 2022	SYSTEM	\$1,412.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					19	Feb 1, 2022	SYSTEM	(\$1,412.50)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	5004 -	Total						\$0.00	
J5P3426 -	Total							\$0.00	
Overall - 1	Total							\$0.00	