

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: September 20, 2022

Final Estimate Number	Contract ID	200515-D01	Pay Period Start May 2,	, 2022	Original Contract Amount	\$507,803.50
23	Prime Contracto	or Meyer Electric Company, Inc	. Pay Period End Septem	mber 15, 2022 i	Net Change Order Amount	(\$244.73)
20				(Current Contract Amount	\$507,558.77

Approval Date		By User
November 21, 2022	Generated and Approved (and should be considered Draft) at the Project Office Level by	browns1
January 24, 2023	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	holdtc
February 3, 2023	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
November 10, 2020	October 1, 2021	September 28, 2021	100.00%

	Contract Informational Date	tes	Milestones
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract
Acceptance Date	January 6, 2023	January 6, 2023	
Awarded Date	June 3, 2020	June 3, 2020	
Letting Date	May 15, 2020	May 15, 2020	
Notice to Proceed Date	July 6, 2020	July 6, 2020	
Open to Traffic Date			
Work Began Date	April 5, 2021	April 5, 2021	

Contract Total Pa	ay For Estimate No. 23				
		This Estimate	Previous	To Date	
200515-D01					
	Total Posted Items Pay	(\$90.00)	\$507,648.77	\$507,558.77	
	Gross Item Adjustments	\$0.00	\$0.00	\$0.00	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
			\$507,648.77	\$507,558.77	
Contract Total Pa	ayable This Estimate:	(\$90.00)			

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J5P3426	0030	6161005	CONSTRUCTION SIGNS	SQFT	\$7.500	-12	(\$90.00)
Project J5P3426 -	Total						(\$90.00)
Overall - Total							(\$90.00)

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

No Data Available

Page 1 of 21 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Information	
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J5P3426	FAF 52-3(25)	Signal improvements	Various	MILLER	at MO 52 and RT CC in E	Eldon; at RT OO and Summ	it Dr. in Holts Summit; at RT C and R
Totals by J	Job Numbe	ers					
J5P3426					This Estimate	Previous	To Date
	Poste	d Item Pay			(\$90.00)	\$507,648.77	\$507,558.77
	Gross	s Item Adjustme	ents		\$0.00	\$0.00	\$0.00
			Gross I	tem Pay	(\$90.00)	\$507,648.77	\$507,558.77
	Incen	tive			\$0.00	\$0.00	\$0.00
	Disin	centive			\$0.00	\$0.00	\$0.00
	Liqui	dated Damages			\$0.00	\$0.00	\$0.00
		Contract Adjus			\$0.00	\$0.00	\$0.00

Revision 4/1/2020 Page 2 of 21



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period No Exceptions Exist on Contract

Revision 4/1/2020 Page 3 of 21



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	eport Generated date and can differ from the posted amo Description	Bid Quantity	Net Change	Total Current	Vas Ger Unit	Total Posted	Unit Price	Total Value POSTED To Date (See report
NIII.CONTICACT	NO.		NO.	Code		Quantity	Order	Quantity		Approved Qty		generated date)
200515-D01	J5P3426	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$13,600.00	\$13,600.00
		0001	0020	6083006	6 IN. CONCRETE MEDIAN STRIP	2.40	0.00	2.40	SQYD	2.40	\$600.00	\$1,440.00
		0001	0030	6161005	CONSTRUCTION SIGNS	903.00	-487.00	416.00	SQFT	416.00	\$7.50	\$3,120.00
		0001	0040	6161009	FLAG ASSEMBLY	8.00	-8.00	0.00	EA	0.00	\$25.00	\$0.00
		0001	0050	6161010	RELOCATED SIGNS	965.00	-269.00	696.00	SQFT	696.00	\$7.00	\$4,872.00
		0001	0060	6161025	CHANNELIZER (TRIM LINE)	260.00	0.00	260.00	EA	260.00	\$25.00	\$6,500.00
		0001	0070	6161040	FLASHING ARROW PANEL	2.00	-2.00	0.00	EA	0.00	\$925.00	\$0.00
		0001	0080	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	4.00	\$4,000.00	\$16,000.00
		0001	0090	6169902	MISC.DETECTABLE PEDESTRIAN CHANNELIZING BARRICADE - TYPE II	4.00	0.00	4.00	EA	4.00	\$160.00	\$640.00
		0001	0100	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$15,800.00	\$15,800.00
		0001	0110	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	6.00	0.00	6.00	EA	6.00	\$600.00	\$3,600.00
		0001	0120	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	48.00	66.00	114.00	LF	114.00	\$25.00	\$2,850.00
		0001	0130	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	62.00	0.00	62.00	LF	62.00	\$2.00	\$124.00
		0001	0140	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT. TYPE P BEADS	16.00	0.00	16.00	LF	16.00	\$2.00	\$32.00
		0001	0150	6206108A	8 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	117.00	0.00	117.00	LF	117.00	\$3.00	\$351.00
		0001	0160	6207001	PAVEMENT MARKING REMOVAL	137.00	0.00	137.00	LF	137.00	\$3.00	\$411.00
		0001	0170	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	3.00	0.00	3.00	EA	3.00	\$125.00	\$375.00
		0001	0180	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$2,800.00	\$2,800.00
		0001	0190	8061006	ALTERNATE DITCH CHECK	370.00	-31.00	339.00	LF	339.00	\$13.00	\$4,407.00
		0001	0200	8061007A	CURB INLET CHECK	2.00	2.00	4.00	EA	4.00	\$250.00	\$1,000.00
		0001	0210	8061016	SEDIMENT REMOVAL	37.00	-35.00	2.00	CUYD	2.00	\$30.00	\$60.00
		0020	0220	9011060	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 1	3.00	-3.00	0.00	EA	0.00	\$2,742.00	\$0.00
		0020	0230	9011062	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 2	1.00	-1.00	0.00	EA	0.00	\$2,313.00	\$0.00
		0020	0240	9011115	BRACKET ARM, 15 FT. OR 4.6 M	4.00	0.00	4.00	EA	4.00	\$760.00	\$3,040.00
		0020	0250	9011311	LUMINAIRE, LED-A	7.00	0.00	7.00	EA	7.00	\$569.00	\$3,983.00
		0020	0260	9011312	LUMINAIRE, LED-B	4.00	0.00	4.00	EA	4.00	\$610.00	\$2,440.00
		0020	0270	9012230	BASE MOUNTED CONTROL STATION 240 VOLT - 4 CIRCUIT	1.00	0.00	1.00	EA	1.00	\$5,300.00	\$5,300.00
		0020	0280	9013002	CONDUIT, 2 IN. RIGID, IN TRENCH	63.00	52.00	115.00	LF	115.00	\$10.00	\$1,150.00
		0020	0290	9013003	CONDUIT, 3 IN. RIGID, IN TRENCH	116.00	-42.00	74.00	LF	74.00	\$11.00	\$814.00
		0020	0300	9013004	CONDUIT, 4 IN. RIGID, IN TRENCH	56.00	0.00	56.00	LF	56.00	\$12.00	\$672.00
		0020	0310	9014004	CONDUIT, 4 IN. RIGID, PUSHED	266.00	0.00	266.00	LF	266.00	\$18.00	\$4,788.00
		0020	0320	9016110	PULL BOX, PREFORMED CLASS 1	4.00	0.00	4.00	EA	4.00	\$1,000.00	\$4,000.00
		0020	0330	9017002	CABLE, 2 AWG 1 CONDUCTOR	240.00	0.00	240.00	LF	240.00	\$2.10	\$504.00
		0020	0340	9017008	CABLE, 8 AWG 1 CONDUCTOR	1,260.00	0.00	1,260.00	LF	1,260.00	\$1.20	\$1,512.00
		0020	0350	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	480.00	0.00	480.00	LF	480.00	\$0.85	\$408.00
		0020	0360	9018245	POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	4.00	0.00	4.00	EA	4.00	\$1,200.00	\$4,800.00
		0020	0370	9018613	POWER SUPPLY ASSEMBLY, TYPE 2, 240/120 VOLT SERVICE, LIGHTING AND SIGNALS	3.00	0.00	3.00	EA	3.00	\$3,395.00	\$10,185.00
		0030	0380	9020113	SIGNAL HEAD, TYPE 3T	1.00	0.00	1.00	EA	1.00	\$739.00	\$739.00
		0030	0390	9020213	SIGNAL HEAD, TYPE 3S	8.00	0.00	8.00	EA	8.00	\$707.00	\$5,656.00
		0030	0400	9020513	SIGNAL HEAD, TYPE 3B	22.00	-1.00	21.00	EA	21.00	\$857.00	\$17,997.00
		0030	0410	9020514	SIGNAL HEAD, TYPE 4B	3.00	1.00	4.00	EA	4.00	\$987.00	\$3,948.00
		0030	0420	9020811	SIGNAL HEAD, TYPE 1S, PEDESTRIAN	6.00	0.00	6.00	EA	6.00	\$407.00	\$2,442.00
		0030	0430	9020833	SH-FLAT SHEET - SIGNAL SIGN	257.00	-1.00	256.00	SQFT	256.00	\$40.00	\$10,240.00

Revision 4/1/2020 Page 4 of 21



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200515-D01	J5P3426	0030	0440	9020834	SIGNAL SIGN, MOUNTING HARDWARE	40.00	0.00	40.00	EA	40.00	\$195.00	\$7,800.00
		0030	0450	9022708	POST, SIGNAL 8 FT. OR 2.4 M	5.00	0.00	5.00	EA	5.00	\$607.00	\$3,035.00
		0030	0460	9022715	POST, SIGNAL 15 FT. OR 4.6 M	1.00	0.00	1.00	EA	1.00	\$790.00	\$790.00
		0030	0470	9023115	POST, TYPE CL, 15 FT. ARM OR 4.6 M ARM	1.00	0.00	1.00	EA	1.00	\$6,639.00	\$6,639.00
		0030	0480	9023120	POST, TYPE CL, 20 FT. ARM OR 6.1 M ARM	1.00	0.00	1.00	EA	1.00	\$6,717.00	\$6,717.00
		0030	0490	9023125	POST, TYPE CL, 25 FT. ARM OR 7.6 M ARM	2.00	0.00	2.00	EA	2.00	\$6,742.00	\$13,484.00
		0030	0500	9023130	POST, TYPE CL, 30 FT. ARM OR 9.1 M ARM	1.00	0.00	1.00	EA	1.00	\$8,289.00	\$8,289.00
		0030	0510	9023135	POST, TYPE CL, 35 FT. ARM OR 10.7 M ARM	3.00	0.00	3.00	EA	3.00	\$7,600.00	\$22,800.00
		0030	0520	9023140	POST, TYPE CL, 40 FT. ARM OR 12.2 M ARM	2.00	0.00	2.00	EA	2.00	\$9,711.00	\$19,422.00
		0030	0530	9023445	POST, TYPE BL, LONGEST ARM 45 FT. OR 13.7 M	1.00	0.00	1.00	EA	1.00	\$14,515.00	\$14,515.00
		0030	0540	9024281	CONTROLLER ASSEMBLY HOUSING, KEYBOARD ENTRY, 8 PHASE NEMA CONTROLLER	3.00	0.00	3.00	EA	3.00	\$15,554.00	\$46,662.00
		0030	0550	9024920	DETECTOR, PUSHBUTTON	6.00	-6.00	0.00	EA	0.00	\$206.00	\$0.00
		0030	0560	9025200	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE	230.00	-33.00	197.00	LF	197.00	\$9.50	\$1,871.50
		0030	0570	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	547.00	-26.00	521.00	LF	521.00	\$10.00	\$5,210.00
		0030	0580	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	798.00	0.00	798.00	LF	798.00	\$24.00	\$19,152.00
		0030	0590	9028100	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	640.00	0.00	640.00	LF	640.00	\$0.85	\$544.00
		0030	0600	9028202	CABLE, 2 AWG 1 CONDUCTOR, POWER	530.00	0.00	530.00	LF	530.00	\$1.80	\$954.00
		0030	0610	9028208	CABLE, 8 AWG 1 CONDUCTOR, POWER	230.00	-70.00	160.00	LF	160.00	\$1.10	\$176.00
		0030	0620	9028302	CABLE, 12 AWG 2 CONDUCTOR	1,170.00	-50.00	1,120.00	LF	1,120.00	\$1.10	\$1,232.00
		0030	0630	9028308	CABLE, 16 AWG 2 CONDUCTOR	1,500.00	0.00	1,500.00	LF	1,500.00	\$1.05	\$1,575.00
		0030	0640	9028310	CABLE, 16 AWG 5 CONDUCTOR	1,500.00	0.00	1,500.00	LF	1,500.00	\$1.12	\$1,680.00
		0030	0650	9028311	CABLE, 16 AWG 7 CONDUCTOR	5,200.00	-70.00	5,130.00	LF	5,130.00	\$1.20	\$6,156.00
		0030	0660	9028350	FIBER OPTIC CABLE, 6 - FIBER, SINGLE MODE	620.00	10.00	630.00	LF	630.00	\$3.25	\$2,047.50
		0030	0670	9028510	CABLE, LOOP DETECTOR, LEAD-IN	1,080.00	10.00	1,090.00	LF	1,090.00	\$1.20	\$1,308.00
		0030	0680	9028810	PULL BOX, PREFORMED CLASS 1	2.00	0.00	2.00	EA	2.00	\$985.00	\$1,970.00
		0030	0690	9028811	PULL BOX, PREFORMED CLASS 2	9.00	0.00	9.00	EA	9.00	\$1,350.00	\$12,150.00
		0030	0700	9028812	PULL BOX, PREFORMED CLASS 3	2.00	0.00	2.00	EA	2.00	\$1,600.00	\$3,200.00
		0030	0710	9028816	PULL BOX, PREFORMED CLASS 5	1.00	0.00	1.00	EA	1.00	\$1,600.00	\$1,600.00
		0030	0720	9028824	PULL BOX, CONCRETE, DOUBLE TYPE B	2.00	0.00	2.00	EA	2.00	\$2,900.00	\$5,800.00
		0030	0730	9029100	BASE, CONCRETE	42.20	0.40	42.60	CUYD	42.60	\$1,350.00	\$57,510.00
		0030	0740	9029902	MISC.GRIDSMART V.D.S. Salvage	1.00	0.00	1.00	EA	1.00	\$1,600.00	\$1,600.00
		0030	0750	9029902	MISC.GRIDSMART Video Detection System	2.00	0.00	2.00	EA	2.00	\$23,000.00	\$46,000.00
		0040	0760	9031010	CONCRETE FOOTINGS, EMBEDDED	0.40	0.00	0.40	CUYD	0.40	\$1,500.00	\$600.00
		0040	0770	9031210	STRUCTURAL STEEL POSTS	50.00	0.00	50.00	LB	50.00	\$25.00	\$1,250.00
		0040	0780	9031241	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE)	4.00	0.00	4.00	EA	4.00	\$205.00	\$820.00
		0040	0790	9031280	2.5 IN. PSST POST - 12 GA.	64.00	0.00	64.00	LF	64.00	\$11.00	\$704.00
		0040	0800	9031281	POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	12.00	0.00	12.00	LF	12.00	\$40.00	\$480.00
		0040	0810	9035004A	SH-FLAT SHEET	37.00	17.90	54.90	SQFT	54.90	\$20.00	\$1,098.00
		0020	5001	9011064	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 3	0.00	4.00	4.00	EA	4.00	\$2,634.75	\$10,539.00
		0030	5002	9029902		0.00	6.00	6.00	EA	6.00	\$866.67	\$5,200.02
		0001	5003	6181000	MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$966.25	\$966.25
		0001	5004	6200009	PREFORMED THERMOPLASTIC PAVEMENT MARKING, $ 6 \text{IN}. $ WHITE	0.00	226.00	226.00	LF	226.00	\$6.25	\$1,412.50
	Project J	5P3426 - To	otal Value	Posted to D	late as of Report Generated Date							\$507,558.77
200515-D01 Ove	rall - Total	Value Post	ted to Da	te as of Repo	ort Generated Date							\$507,558.77

Revision 4/1/2020 Page 5 of 21



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J5P3426

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	Offset/ Distance	Comments
0030	6161005	CONSTRUCTION SIGNS	6/23/22	9/6/22	-12.00	SQFT	12 SQFT is being removed to match field measured quantity				

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 4/1/2020 Page 6 of 21



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3426	0020	6 IN. CONCRETE MEDIAN STRIP	Material		3	Apr 19, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Apr 19, 2021	SYSTEM	(\$1,440.00)	
					4	May 3, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	May 3, 2021	SYSTEM	(\$1,440.00)	
					5	May 17, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	May 17, 2021	SYSTEM	(\$1,440.00)	
					6	Jun 1, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Jun 1, 2021	SYSTEM	(\$1,440.00)	
					7	Jun 16, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Jun 16, 2021	SYSTEM	(\$1,440.00)	
					8	Jun 30, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					8	Jun 30, 2021	SYSTEM	(\$1,440.00)	
					9	Jul 16, 2021	SYSTEM	(\$1,440.00)	
					10	Aug 2, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					10	Aug 2, 2021	SYSTEM	(\$1,440.00)	
					11	Aug 16, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					11	Aug 16, 2021	SYSTEM	(\$1,440.00)	
					12	Sep 2, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					12	Sep 2, 2021	SYSTEM	(\$1,440.00)	
					13	Sep 16, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					13	Sep 16, 2021	SYSTEM	(\$1,440.00)	
				- Total				(\$1,440.00)	
			Material - Tota				ava==:	(\$1,440.00)	
			MaterialCredit		10	Aug 2, 2021	SYSTEM	\$1,440.00	
				- Total				\$1,440.00	
			MaterialCredit	- Total				\$1,440.00	
		· Total						\$0.00	
	0120	PREF THERMO PVMT MARK,	Material		5	May 17, 2021	SYSTEM	(\$300.00)	
		24 IN WHIT			6	Jun 1, 2021	SYSTEM	(\$300.00)	
				- Total				(\$600.00)	



roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks							
P3426	0120	PREF	Material - Tota					(\$600.00)								
		THERMO PVMT MARK, 24 IN WHIT	MaterialCredit		6	Jun 1, 2021	SYSTEM	\$300.00								
					7	Jun 16, 2021	SYSTEM	\$300.00								
				- Total				\$600.00								
			MaterialCredit	- Total				\$600.00								
			Overrun	Overrun	14	Sep 30, 2021	SYSTEM	(\$1,650.00)								
					18	Jan 18, 2022	SYSTEM	\$1,650.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',25.00000 - 25.00000, 'is applied (if non-zero).							
				Overrun - To	otal			\$0.00								
			Overrun - Tota					\$0.00								
1	0120 -	Total						\$0.00								
	0130	4 IN. WHITE WATERBORNE	Material		8	Jun 30, 2021	SYSTEM	(\$124.00)								
		PAVEMENT MARKING			9	Jul 16, 2021	SYSTEM	(\$124.00)								
					10	Aug 2, 2021	SYSTEM	\$124.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Exception 2 on the current Payment Estimate.							
					10	Aug 2, 2021	SYSTEM	(\$124.00)								
					11	Aug 16, 2021	SYSTEM	\$124.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user stokez1 overridding Payment Estimate Exception 2 on the current Payment Estimate.							
												11	Aug 16, 2021	SYSTEM	(\$124.00)	
													12	Sep 2, 2021	SYSTEM	\$124.00
					12	Sep 2, 2021	SYSTEM	(\$124.00)								
					13	Sep 16, 2021	SYSTEM	\$124.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Exception 2 on the current Payment Estimate.							
					13	Sep 16, 2021	SYSTEM	(\$124.00)								
				- Total				(\$248.00)								
			Material - Tota	I				(\$248.00)								
			MaterialCredit		9	Jul 16, 2021	SYSTEM	\$124.00								
					10	Aug 2, 2021	SYSTEM	\$124.00								
				- Total				\$248.00								
			MaterialCredit	- Total				\$248.00								
	0130 -	Total						\$0.00								
	0140	4 IN. YELLOW WATERBORNE PAVEMENT	Material		8	Jun 30, 2021	SYSTEM	(\$32.00)								
		MARKING			9	Jul 16, 2021	SYSTEM	(\$32.00)								
					10	Aug 2, 2021	SYSTEM	\$32.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user stokez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.							
					10	Aug 2, 2021	SYSTEM	(\$32.00)								
					11	Aug 16, 2021	SYSTEM	\$32.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.							
					11	Aug 16, 2021	SYSTEM	(\$32.00)								



ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks											
26	0140	4 IN. YELLOW WATERBORNE PAVEMENT	Material		12	Sep 2, 2021	SYSTEM	\$32.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.											
		MARKING			12	Sep 2, 2021	SYSTEM	(\$32.00)												
					13	Sep 16, 2021	SYSTEM	\$32.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user stokez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.											
					13	Sep 16, 2021	SYSTEM	(\$32.00)												
				- Total				(\$64.00)												
			Material - Tota					(\$64.00)												
			MaterialCredit		9	Jul 16, 2021	SYSTEM	\$32.00												
					10	Aug 2, 2021	SYSTEM	\$32.00												
				- Total				\$64.00												
			MaterialCredit	- Total				\$64.00												
	0140 -	Total						\$0.00												
ľ	0150	8 IN. WHITE WATERBORNE	Material		8	Jun 30, 2021	SYSTEM	(\$351.00)												
		PAVEMENT MARKING			9	Jul 16, 2021	SYSTEM	(\$351.00)												
					10	Aug 2, 2021	SYSTEM	\$351.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.											
					10	Aug 2, 2021	SYSTEM	(\$351.00)												
																11	Aug 16, 2021	SYSTEM	\$351.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
												11	Aug 16, 2021	SYSTEM	(\$351.00)					
					12	Sep 2, 2021	SYSTEM	\$351.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user stokez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.											
					12	Sep 2, 2021	SYSTEM	(\$351.00)												
					13	Sep 16, 2021	SYSTEM	\$351.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.											
					13	Sep 16, 2021	SYSTEM	(\$351.00)												
				- Total				(\$702.00)												
			Material - Tota	ı				(\$702.00)												
			MaterialCredit		9	Jul 16, 2021	SYSTEM	\$351.00												
					10	Aug 2, 2021	SYSTEM	\$351.00												
				- Total				\$702.00												
			MaterialCredit	- Total				\$702.00												
	0150 -	Total						\$0.00												
	0190	ALTERNATE DITCH CHECK	Material		3	Apr 19, 2021	SYSTEM	(\$1,287.00)												
				- Total				(\$1,287.00)												
			Material - Tota					(\$1,287.00)												
			MaterialCredit		4	May 3, 2021	SYSTEM	\$1,287.00												
				- Total				\$1,287.00												
			MaterialCredit	- Total				\$1,287.00												
	0190 -	Total						\$0.00												



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks						
J5P3426	0200	CURB INLET CHECK	Material		3	Apr 19, 2021	SYSTEM	(\$1,000.00)							
				- Total				(\$1,000.00)							
			Material - Tota					(\$1,000.00)							
			MaterialCredit		4	May 3, 2021	SYSTEM	\$1,000.00							
				- Total				\$1,000.00							
			MaterialCredit	- Total				\$1,000.00							
			Overrun	Overrun	3	Apr 19, 2021	SYSTEM	\$500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 12 on the current Payment Estimate. Material Insufficiency Quantity 4.000; Overrun Quantity Balance 2.00.						
					3	Apr 19, 2021	SYSTEM	(\$500.00)							
					4	May 3, 2021	SYSTEM	(\$500.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).						
					5	May 17, 2021	SYSTEM	\$500.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',250.00000 - 250.00000, 'is applied (if non-zero).						
				Overrun - T	otal			\$0.00							
			Overrun - Tota	ıl				\$0.00							
	0200 -							\$0.00							
	0270	BASE MOUNTED CONTROL STATION	Material		4	May 3, 2021	SYSTEM	\$5,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.						
		STATION			4	May 3, 2021	SYSTEM	(\$5,300.00)							
											5	May 17, 2021	SYSTEM	\$5,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user stokez1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
										5	May 17, 2021	SYSTEM	(\$5,300.00)		
									6	Jun 1, 2021	SYSTEM	\$5,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user stokez1 overridding Payment Estimate Exception 8 on the current Payment Estimate.		
						6 Jun 1, SYSTEM 2021		(\$5,300.00)							
				- Total				\$0.00							
			Material - Tota					\$0.00							
	0270 -	Total						\$0.00							
	0280	CONDUIT, 2 IN. RIGID, IN TRENCH	Overrun	Overrun		May 3, 2021	SYSTEM	(\$420.00)							
					13	Sep 16, 2021	SYSTEM	(\$100.00)							
					18	Jan 18, 2022	SYSTEM	\$520.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',10.00000 - 10.00000, 'is applied (if non-zero).						
				Overrun - T	otal			\$0.00							
			Overrun - Tota					\$0.00							
	0280 -	Total						\$0.00							
	0330	CABLE, 2 AWG 1 CONDUCTOR	Material		4	May 3, 2021	SYSTEM	\$497.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user stokez1 overridding Payment Estimate Exception 8 on the current Payment Estimate.						
					4	May 3, 2021	SYSTEM	(\$497.70)							
					5	May 17, 2021	SYSTEM	\$497.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user stokez1 overridding Payment Estimate Exception 9 on the current Payment Estimate.						
					5	May 17, 2021	SYSTEM	(\$497.70)							
					6	Jun 1, 2021	SYSTEM	\$497.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user stokez1 overridding Payment						



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks												
J5P3426	0330	CABLE, 2 AWG	Material						Estimate Exception 9 on the current Payment Estimate.												
		CONDUCTOR			6	Jun 1, 2021	SYSTEM	(\$497.70)													
				- Total				\$0.00													
			Material - Tota					\$0.00													
	0330 -							\$0.00													
	0340	CABLE, 8 AWG 1 CONDUCTOR	Material		4	May 3, 2021	SYSTEM	\$1,506.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user stokez1 overridding Payment Estimate Exception 9 on the current Payment Estimate.												
					4	May 3, 2021	SYSTEM	(\$1,506.00)													
					5	May 17, 2021	SYSTEM	\$1,506.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Exception 10 on the current Payment Estimate.												
					5	May 17, 2021	SYSTEM	(\$1,506.00)													
					6	Jun 1, 2021	SYSTEM	\$1,506.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Exception 10 on the current Payment Estimate.												
		340 - Total			6	Jun 1, 2021	SYSTEM	(\$1,506.00)													
				- Total				\$0.00													
			Material - Tota					\$0.00													
	0340 -	Total						\$0.00													
	0350	CABLE, 10 AWG 1 CONDUCTOR, POLE &	Material		4	May 3, 2021	SYSTEM	\$408.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user stokez1 overridding Payment Estimate Exception 10 on the current Payment Estimate.												
		BRACKE										4	May 3, 2021	SYSTEM	(\$408.00)						
										5	May 17, 2021	SYSTEM	\$408.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user stokez1 overridding Payment Estimate Exception 11 on the current Payment Estimate.							
								5	May 17, 2021	SYSTEM	(\$408.00)										
													6	Jun 1, 2021	SYSTEM	\$408.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user stokez1 overridding Payment Estimate Exception 11 on the current Payment Estimate.				
					6	Jun 1, 2021	SYSTEM	(\$408.00)													
				- Total				\$0.00													
			Material - Tota					\$0.00													
	0350 -	Total						\$0.00													
	0370	POWER SUPPLY ASSEMBLY,	Material		4	May 3, 2021	SYSTEM	\$3,395.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment Estimate Exception 11 on the current Payment Estimate.												
		TYPE 2, 240/120										5		4	May 3, 2021	SYSTEM	(\$3,395.00)				
																	5	May 17, 2021	SYSTEM	\$3,395.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
													5	May 17, 2021	SYSTEM	(\$3,395.00)					
					6	Jun 1, 2021	SYSTEM	\$3,395.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 12 on the current Payment Estimate.												
					6	Jun 1, 2021	SYSTEM	(\$3,395.00)													
				7	Jun 16, 2021	SYSTEM	\$3,395.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user stokez1 overridding Payment Estimate Exception 9 on the current Payment Estimate.													
					7	Jun 16, 2021	SYSTEM	(\$3,395.00)													
					8	Jun 30,	SYSTEM	\$3,395.00	This adjustment offsets the original system-generated Material Payment												



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3426	0370	POWER SUPPLY	Material			2021			Estimate Item Adjustment (0007) due to user stokez1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
		ASSEMBLY, TYPE 2, 240/120			8	Jun 30, 2021	SYSTEM	(\$3,395.00)	
					9	Jul 16, 2021	SYSTEM	(\$3,395.00)	
					10	Aug 2, 2021	SYSTEM	(\$3,395.00)	
					11	Aug 16, 2021	SYSTEM	\$3,395.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user stokez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					11	Aug 16, 2021	SYSTEM	(\$3,395.00)	
					12	Sep 2, 2021	SYSTEM	\$3,395.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user stokez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					12	Sep 2, 2021	SYSTEM	(\$3,395.00)	
					13	Sep 16, 2021	SYSTEM	\$3,395.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					13	Sep 16, 2021	SYSTEM	(\$3,395.00)	
					14	Sep 30, 2021	SYSTEM	\$10,185.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user stokez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					14	Sep 30, 2021	SYSTEM	(\$10,185.00)	
					15	Oct 18, 2021	SYSTEM	\$10,185.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user stokez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					15	Oct 18, 2021	SYSTEM	(\$10,185.00)	
					16	Nov 2, 2021	SYSTEM	\$10,185.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user stokez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					16	Nov 2, 2021	SYSTEM	(\$10,185.00)	
					17	Nov 16, 2021	SYSTEM	\$10,185.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					17	Nov 16, 2021	SYSTEM	(\$10,185.00)	
				- Total				(\$6,790.00)	
			Material - Tota	I				(\$6,790.00)	
			MaterialCredit		10	Aug 2, 2021	SYSTEM	\$3,395.00	
					11	Aug 16, 2021	SYSTEM	\$3,395.00	
				- Total				\$6,790.00	
			MaterialCredit	- Total				\$6,790.00	
		Total						\$0.00	
	0390	SIGNAL HEAD, TYPE 3S	Material		4	May 3, 2021	SYSTEM	\$2,828.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user stokez1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					4	May 3, 2021	SYSTEM	(\$2,828.00)	
					5	May 17, 2021	SYSTEM	\$2,828.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					5	May 17, 2021	SYSTEM	(\$2,828.00)	
					6	Jun 1, 2021	SYSTEM	\$2,828.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment Estimate Exception 13 on the current Payment Estimate.



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3426	0390	SIGNAL HEAD, TYPE 3S	Material		6	Jun 1, 2021	SYSTEM	(\$2,828.00)	
				- Total				\$0.00	
			Material - Tota	al				\$0.00	
	0390 -	- Total						\$0.00	
	0400	SIGNAL HEAD, TYPE 3B	Material		4	May 3, 2021	SYSTEM	\$6,856.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user stokez1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					4	May 3, 2021	SYSTEM	(\$6,856.00)	
					5	May 17, 2021	SYSTEM	\$6,856.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user stokez1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					5	May 17, 2021	SYSTEM	(\$6,856.00)	
					6	Jun 1, 2021	SYSTEM	\$6,856.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user stokez1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					6	Jun 1, 2021	SYSTEM	(\$6,856.00)	
				- Total				\$0.00	
			Material - Tota	al				\$0.00	
	0400 -	- Total						\$0.00	
	0410	SIGNAL HEAD, TYPE 4B	Overrun	Overrun	11	Aug 16, 2021	SYSTEM	(\$987.00)	
					18	Jan 18, 2022	SYSTEM	\$987.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',987.00000 - 987.00000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - Tota	al				\$0.00	
	0410 -	- Total						00.00	
	0410							\$0.00	
	0430	SH-FLAT SHEET - SIGNAL SIGN	Material		4	May 3, 2021	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user stokez1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
		SH-FLAT SHEET -	Material		4		SYSTEM SYSTEM		Estimate Item Adjustment (0014) due to user stokez1 overridding Payment
		SH-FLAT SHEET -	Material			2021 May 3,		\$3,600.00	Estimate Item Adjustment (0014) due to user stokez1 overridding Payment
		SH-FLAT SHEET -	Material		4	2021 May 3, 2021 May 17,	SYSTEM	\$3,600.00 (\$3,600.00)	Estimate Item Adjustment (0014) due to user stokez1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment
		SH-FLAT SHEET -	Material		5	May 3, 2021 May 17, 2021 May 17,	SYSTEM SYSTEM	\$3,600.00 (\$3,600.00) \$3,600.00	Estimate Item Adjustment (0014) due to user stokez1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment
		SH-FLAT SHEET -	Material		5	2021 May 3, 2021 May 17, 2021 May 17, 2021 Jun 1,	SYSTEM SYSTEM	\$3,600.00 (\$3,600.00) \$3,600.00 (\$3,600.00)	Estimate Item Adjustment (0014) due to user stokez1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment
		SH-FLAT SHEET -	Material		4 5 5	2021 May 3, 2021 May 17, 2021 May 17, 2021 Jun 1, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$3,600.00 (\$3,600.00) \$3,600.00 (\$3,600.00) \$3,600.00	Estimate Item Adjustment (0014) due to user stokez1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment
		SH-FLAT SHEET -	Material		45566	2021 May 3, 2021 May 17, 2021 May 17, 2021 Jun 1, 2021 Jun 1, 2021 Jun 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$3,600.00 (\$3,600.00) \$3,600.00 (\$3,600.00) \$3,600.00	Estimate Item Adjustment (0014) due to user stokez1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Payment
		SH-FLAT SHEET -	Material		45667	2021 May 3, 2021 May 17, 2021 May 17, 2021 Jun 1, 2021 Jun 1, 2021 Jun 16, 2021 Jun 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$3,600.00 (\$3,600.00) \$3,600.00 (\$3,600.00) (\$3,600.00) \$3,600.00	Estimate Item Adjustment (0014) due to user stokez1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Payment
		SH-FLAT SHEET -	Material		4 5 5 6 6 7 7	2021 May 3, 2021 May 17, 2021 May 17, 2021 Jun 1, 2021 Jun 1, 2021 Jun 16, 2021 Jun 16, 2021 Jun 30,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$3,600.00 (\$3,600.00) \$3,600.00 (\$3,600.00) (\$3,600.00) \$3,600.00	Estimate Item Adjustment (0014) due to user stokez1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Payment
		SH-FLAT SHEET -	Material		4 5 5 6 6 7 7 8 8	2021 May 3, 2021 May 17, 2021 Jun 1, 2021 Jun 1, 2021 Jun 16, 2021 Jun 30, 2021 Jul 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$3,600.00 (\$3,600.00) \$3,600.00 (\$3,600.00) (\$3,600.00) (\$3,600.00) (\$3,600.00) (\$6,460.00)	Estimate Item Adjustment (0014) due to user stokez1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Payment
		SH-FLAT SHEET -	Material		4 5 5 6 6 7 7 8 8 9	2021 May 3, 2021 May 17, 2021 Jun 1, 2021 Jun 16, 2021 Jun 30, 2021 Jun 16, 2021 Jun 16, 2021 Aug 2,	SYSTEM	\$3,600.00 (\$3,600.00) \$3,600.00 (\$3,600.00) \$3,600.00 (\$3,600.00) (\$3,600.00) (\$6,460.00)	Estimate Item Adjustment (0014) due to user stokez1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
		SH-FLAT SHEET -	Material		4 5 5 6 6 7 7 8 8 9 10	2021 May 3, 2021 May 17, 2021 May 17, 2021 Jun 1, 2021 Jun 16, 2021 Jun 30, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2,	SYSTEM	\$3,600.00 (\$3,600.00) \$3,600.00 (\$3,600.00) \$3,600.00 (\$3,600.00) (\$3,600.00) (\$6,460.00) (\$6,460.00)	Estimate Item Adjustment (0014) due to user stokez1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Exception 10 on the current Payment Estimate.



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks					
126	0430	SH-FLAT SHEET -	Material			2021								
		SIGNAL SIGN			13	Sep 16, 2021	SYSTEM	(\$10,224.00)						
				- Total				(\$43,594.00)						
			Material - Tota					(\$43,594.00)						
			MaterialCredit		9	Jul 16, 2021	SYSTEM	\$6,460.00						
					10	Aug 2, 2021	SYSTEM	\$6,460.00						
					12	Sep 2, 2021	SYSTEM	\$10,225.00						
					13	Sep 16, 2021	SYSTEM	\$10,225.00						
				Total	14	Sep 30, 2021	SYSTEM	\$10,224.00						
			Material 2	- Total				\$43,594.00						
	0430 -	Total	MaterialCredit	- Total				\$43,594.00						
	0600	CABLE, 2 AWG 1 CONDUCTOR,	Material		4	May 3, 2021	SYSTEM	\$0.00 \$313.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user stokez1 overridding Payment Estimate Exception 15 on the current Payment Estimate.					
		POWER			4	May 3, 2021	SYSTEM	(\$313.20)						
					5	May 17, 2021	SYSTEM	\$313.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user stokez1 overridding Payment Estimate Exception 16 on the current Payment Estimate.					
										5	May 17, 2021	SYSTEM	(\$313.20)	
								6	Jun 1, 2021	SYSTEM	\$313.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user stokez1 overridding Payment Estimate Exception 16 on the current Payment Estimate.		
					6	Jun 1, 2021	SYSTEM	(\$313.20)						
				- Total				\$0.00						
			Material - Tota	l				\$0.00						
	0600 -	Total						\$0.00						
	0610	CABLE, 8 AWG 1 CONDUCTOR,	Material		4	May 3, 2021	SYSTEM	\$31.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user stokez1 overridding Payment Estimate Exception 16 on the current Payment Estimate.					
		POWER			4	May 3, 2021	SYSTEM	(\$31.90)						
					5	May 17, 2021	SYSTEM	\$31.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user stokez1 overridding Payment Estimate Exception 17 on the current Payment Estimate.					
					5	May 17, 2021	SYSTEM	(\$31.90)						
					6	Jun 1, 2021	SYSTEM	\$31.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user stokez1 overridding Payment Estimate Exception 17 on the current Payment Estimate.					
					6	Jun 1, 2021	SYSTEM	(\$31.90)						
				- Total				\$0.00						
			Material - Tota	l				\$0.00						
	0610 -	Total						\$0.00						
	0630	CABLE, 16 AWG 2 CONDUCTOR	Material		4	May 3, 2021	SYSTEM	\$849.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user stokez1 overridding Payment Estimate Exception 17 on the current Payment Estimate.					
					4	May 3, 2021	SYSTEM	(\$849.45)						
					5	May 17, 2021	SYSTEM	\$849.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user stokez1 overridding Payment Estimate Exception 18 on the current Payment Estimate.					



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
J5P3426	0630	CABLE, 16 AWG 2	Material		5	May 17, 2021	SYSTEM	(\$849.45)			
		CONDUCTOR			6	Jun 1, 2021	SYSTEM	\$849.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user stokez1 overridding Payment Estimate Exception 18 on the current Payment Estimate.		
					6	Jun 1, 2021	SYSTEM	(\$849.45)			
				- Total				\$0.00			
			Material - Tota					\$0.00			
	0630 -	Total						\$0.00			
	0640	CABLE, 16 AWG 5 CONDUCTOR	Material		4	May 3, 2021	SYSTEM	\$910.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user stokez1 overridding Payment Estimate Exception 18 on the current Payment Estimate.		
					4	May 3, 2021	SYSTEM	(\$910.56)			
					5	May 17, 2021	SYSTEM	\$910.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user stokez1 overridding Payment Estimate Exception 19 on the current Payment Estimate.		
						May 17, 2021	SYSTEM	(\$910.56)			
					6	Jun 1, 2021	SYSTEM	\$910.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user stokez1 overridding Payment Estimate Exception 19 on the current Payment Estimate.		
					6	Jun 1, 2021	SYSTEM	(\$910.56)			
			- Total				\$0.00				
			Material - Tota					\$0.00			
	0640 - Total	Total						\$0.00			
	0640 - 0650	CABLE, 16 AWG 7 CONDUCTOR	Material		4	May 3, 2021	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user stokez1 overridding Payment Estimate Exception 19 on the current Payment Estimate.		
					4	May 3, 2021	SYSTEM	(\$2,424.00)			
							5	May 17, 2021	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user stokez1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					5	May 17, 2021	SYSTEM	(\$2,424.00)			
						6	Jun 1, 2021	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user stokez1 overridding Payment Estimate Exception 20 on the current Payment Estimate.	
					6	Jun 1, 2021	SYSTEM	(\$2,424.00)			
				- Total				\$0.00			
			Material - Tota	ı				\$0.00			
	0650 -	Total						\$0.00			
	0660	FIBER OPTIC CABLE, 6 - FIBER, SINGLE	Material		8	Jun 30, 2021	SYSTEM	\$2,034.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user stokez1 overridding Payment Estimate Exception 13 on the current Payment Estimate.		
		MOD			8	Jun 30, 2021	SYSTEM	(\$2,034.50)			
					9	Jul 16, 2021	SYSTEM	(\$2,034.50)			
				- Total				(\$2,034.50)			
			Material - Tota	ı				(\$2,034.50)			
			MaterialCredit		10	Aug 2, 2021	SYSTEM	\$2,034.50			
				- Total				\$2,034.50			
			MaterialCredit	- Total				\$2,034.50			
			Overrun	Overrun	8	Jun 30, 2021	SYSTEM	\$19.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 14 on the current Payment Estimate. Material Insufficiency Quantity 626.000;		



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3426	0660	FIBER OPTIC	Overrun	Overrun					Overrun Quantity Balance 6.00.
		CABLE, 6 - FIBER, SINGLE MOD			8	Jun 30, 2021	SYSTEM	(\$19.50)	
					9	Jul 16, 2021	SYSTEM	(\$19.50)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					9	Jul 16, 2021	SYSTEM	\$19.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 14 on the current Payment Estimate. Material Insufficiency Quantity 626.000; Overrun Quantity Balance 6.00.
					10	Aug 2, 2021	SYSTEM	(\$19.50)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					13	Sep 16, 2021	SYSTEM	(\$13.00)	
					18	Jan 18, 2022	SYSTEM	\$32.50	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',3.25000 - 3.25000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - Tota	al				\$0.00	
	0660 -	· Total						\$0.00	
	0670	CABLE, LOOP DETECTOR,	Overrun	Overrun	8	Jun 30, 2021	SYSTEM	(\$6.00)	
		LEAD-IN			13	Sep 16, 2021	SYSTEM	(\$6.00)	
					18	Jan 18, 2022	SYSTEM	\$12.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',1.20000 - 1.20000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - Tota	al				\$0.00	
	0670 -	- Total						\$0.00	
	0720	CONCRETE, DOUBLE TYPE	Material		3	Apr 19, 2021	SYSTEM	\$5,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
	CONCRETE,								Estimate Exception to on the current Payment Estimate.
				3	Apr 19, 2021	SYSTEM	(\$5,800.00)	Esumate Exception 10 on the current rayment Esumate.	
		В			3		SYSTEM	(\$5,800.00) \$5,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user stokez1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
		В				2021 May 3,			This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user stokez1 overridding Payment
		В			4	2021 May 3, 2021 May 3,	SYSTEM	\$5,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user stokez1 overridding Payment
		В			4	2021 May 3, 2021 May 3, 2021 May 17, 2021	SYSTEM	\$5,800.00 (\$5,800.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user stokez1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user stokez1 overridding Payment
		В		- Total	4 4 5	2021 May 3, 2021 May 3, 2021 May 17, 2021	SYSTEM SYSTEM	\$5,800.00 (\$5,800.00) \$5,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user stokez1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user stokez1 overridding Payment
		В	Material - Tota		4 4 5	2021 May 3, 2021 May 3, 2021 May 17, 2021	SYSTEM SYSTEM	\$5,800.00 (\$5,800.00) \$5,800.00 (\$5,800.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user stokez1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user stokez1 overridding Payment
	0720 -		Material - Tota		4 4 5	2021 May 3, 2021 May 3, 2021 May 17, 2021	SYSTEM SYSTEM	\$5,800.00 (\$5,800.00) \$5,800.00 (\$5,800.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user stokez1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user stokez1 overridding Payment
	0720 - 0730		Material - Tota		4 4 5	2021 May 3, 2021 May 3, 2021 May 17, 2021	SYSTEM SYSTEM	\$5,800.00 (\$5,800.00) \$5,800.00 (\$5,800.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user stokez1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user stokez1 overridding Payment
		· Total BASE,			4 4 5 5 5	2021 May 3, 2021 May 3, 2021 May 17, 2021 May 17, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$5,800.00 (\$5,800.00) \$5,800.00 (\$5,800.00) \$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user stokez1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user stokez1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment
		· Total BASE,			4 4 5 5 5 3	2021 May 3, 2021 May 3, 2021 May 17, 2021 May 17, 2021 Apr 19, 2021 Apr 19,	SYSTEM SYSTEM SYSTEM SYSTEM	\$5,800.00 (\$5,800.00) \$5,800.00 (\$5,800.00) \$0.00 \$0.00 \$18,508.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user stokez1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user stokez1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment
		· Total BASE,			4 5 5 3 3 3	2021 May 3, 2021 May 3, 2021 May 17, 2021 May 17, 2021 Apr 19, 2021 Apr 19, 2021 May 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$5,800.00 (\$5,800.00) \$5,800.00 (\$5,800.00) \$0.00 \$0.00 \$18,508.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user stokez1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user stokez1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user stokez1 overridding Payment Estimate Item Adjustment (0021) due to user stokez1 overridding Payment
		· Total BASE,			4 4 5 5 3 3 4 4	2021 May 3, 2021 May 3, 2021 May 17, 2021 May 17, 2021 Apr 19, 2021 Apr 2021 May 3, 2021 May 3, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$5,800.00 (\$5,800.00) \$5,800.00 (\$5,800.00) \$0.00 \$0.00 \$18,508.50 (\$18,508.50)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user stokez1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user stokez1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user stokez1 overridding Payment Estimate Item Adjustment (0021) due to user stokez1 overridding Payment
		· Total BASE,			4 4 5 5 3 3 4	2021 May 3, 2021 May 17, 2021 May 17, 2021 Apr 19, 2021 Apr 19, 2021 May 3, 2021 May 3, 2021 May 3, 2021 May 17, 19, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$5,800.00 (\$5,800.00) \$5,800.00 (\$5,800.00) \$0.00 \$0.00 \$18,508.50 (\$18,508.50) (\$18,508.50)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user stokez1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user stokez1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user stokez1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 22 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks						
J5P3426	0730	BASE, CONCRETE	Material			2021			Estimate Item Adjustment (0012) due to user stokez1 overridding Payment Estimate Exception 21 on the current Payment Estimate.						
					6	Jun 1, 2021	SYSTEM	(\$29,416.50)							
					7	Jun 16, 2021	SYSTEM	\$37,719.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 11 on the current Payment Estimate.						
					7	Jun 16, 2021	SYSTEM	(\$37,719.00)							
				- Total				\$0.00							
			Material - Tota	ıl				\$0.00							
			Overrun	Overrun	14	Sep 30, 2021	SYSTEM	(\$540.00)							
					18	Jan 18, 2022	SYSTEM	\$540.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',1350.00000 - 1350.00000, 'is applied (if non-zero).						
				Overrun - T	otal			\$0.00							
			Overrun - Tota	al				\$0.00							
	0730 -	- Total						\$0.00							
	0750	MISC.	Construction Stockpile		4	May 3, 2021	SYSTEM	(\$22,999.15)	Payment Estimate Item Adjustment generated Stockpile Transaction						
					11	Aug 16, 2021	SYSTEM	(\$14,990.85)	Payment Estimate Item Adjustment generated Stockpile Transaction						
				- Total				(\$37,990.00)							
			Construction	Stockpile - To	otal			(\$37,990.00)							
			Construction Stockpile STMI		1	Aug 3, 2020	SYSTEM	\$37,990.00	Payment Estimate Item Adjustment generated Stockpile Transaction						
			0111111	- Total				\$37,990.00							
			Construction	Stockpile STI	MI - Total			\$37,990.00							
	0750 -	· Total						\$0.00							
	0770	STRUCTURAL STEEL POSTS	Material		12	Sep 2, 2021	SYSTEM	(\$1,250.00)							
					13	Sep 16, 2021	SYSTEM	(\$1,250.00)							
					14	Sep 30, 2021	SYSTEM	(\$1,250.00)							
					15	Oct 18, 2021	SYSTEM	(\$1,250.00)							
					16	Nov 2, 2021	SYSTEM	(\$1,250.00)							
					17	Nov 16, 2021	SYSTEM	(\$1,250.00)							
					18	Jan 18, 2022	SYSTEM	(\$1,250.00)							
											19	Feb 1, 2022	SYSTEM	(\$1,250.00)	
					20	Feb 17, 2022	SYSTEM	\$1,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user stokez1 overridding Payment Estimate Exception 2 on the current Payment Estimate.						
					20	Feb 17, 2022	SYSTEM	(\$1,250.00)							
				- Total				(\$10,000.00)							
			Material - Tota					(\$10,000.00)							
			MaterialCredit		13	Sep 16, 2021	SYSTEM	\$1,250.00							
					14	2021 Sep 30, 2021	SYSTEM	\$1,250.00							
						2021 Sep 30,									



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks								
J5P3426	0770	STRUCTURAL STEEL POSTS	MaterialCredit		17	Nov 16, 2021	SYSTEM	\$1,250.00									
					18	Jan 18, 2022	SYSTEM	\$1,250.00									
					19	Feb 1, 2022	SYSTEM	\$1,250.00									
					20	Feb 17, 2022	SYSTEM	\$1,250.00									
				- Total				\$10,000.00									
			MaterialCredit	- Total				\$10,000.00									
	0770 -							\$0.00									
	0780	BREAKAWAY ASSEMBLY (PERFORATED	Material		12	Sep 2, 2021	SYSTEM	(\$820.00)									
		SQUARE STEEL TUBE)			13	Sep 16, 2021	SYSTEM	(\$820.00)									
					14	Sep 30, 2021	SYSTEM	(\$820.00)									
					15	Oct 18, 2021	SYSTEM	(\$820.00)									
					16	Nov 2, 2021	SYSTEM	(\$820.00)									
					17	Nov 16, 2021	SYSTEM	(\$820.00)									
					18	Jan 18, 2022	SYSTEM	(\$820.00)									
					19	Feb 1, 2022	SYSTEM	(\$820.00)									
													20	Feb 17, 2022	SYSTEM	\$820.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					20	Feb 17, 2022	SYSTEM	(\$820.00)									
				- Total				(\$6,560.00)									
			Material - Tota	I				(\$6,560.00)									
			MaterialCredit		13	Sep 16, 2021	SYSTEM	\$820.00									
					14	Sep 30, 2021	SYSTEM	\$820.00									
				15	15	Oct 18, 2021	SYSTEM	\$820.00									
					16	Nov 2, 2021	SYSTEM	\$820.00									
				17	17	Nov 16, 2021	SYSTEM	\$820.00									
									18	Jan 18, 2022	SYSTEM	\$820.00					
									19	Feb 1, 2022	SYSTEM	\$820.00					
					20	Feb 17, 2022	SYSTEM	\$820.00									
				- Total				\$6,560.00									
			MaterialCredit	- Total				\$6,560.00									
	0780 -							\$0.00									
	0790	2.5 IN. PSST POST - 12 GA.	Material		12	Sep 2, 2021	SYSTEM	(\$704.00)									
					13	Sep 16, 2021	SYSTEM	(\$704.00)									
					14	Sep 30, 2021	SYSTEM	(\$704.00)									
					15	Oct 18, 2021	SYSTEM	(\$704.00)									



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
			Туре	Adjustment Type	Number	Date	Ву		
J5P3426	0790	2.5 IN. PSST POST - 12 GA.	Material		16	Nov 2, 2021	SYSTEM	\$704.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user stokez1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					16	Nov 2, 2021	SYSTEM	(\$704.00)	
					17	Nov 16, 2021	SYSTEM	\$704.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					17	Nov 16, 2021	SYSTEM	(\$704.00)	
					18	Jan 18, 2022	SYSTEM	\$704.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					18	Jan 18, 2022	SYSTEM	(\$704.00)	
					19	Feb 1, 2022	SYSTEM	\$704.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					19	Feb 1, 2022	SYSTEM	(\$704.00)	
					20	Feb 17, 2022	SYSTEM	\$704.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					20	Feb 17, 2022	SYSTEM	(\$704.00)	
				- Total				(\$2,816.00)	
			Material - Tota					(\$2,816.00)	
			MaterialCredit		13	Sep 16, 2021	SYSTEM	\$704.00	
					14	Sep 30, 2021	SYSTEM	\$704.00	
					15	Oct 18, 2021	SYSTEM	\$704.00	
					16	Nov 2, 2021	SYSTEM	\$704.00	
				- Total				\$2,816.00	
			MaterialCredit	- Total				\$2,816.00	
	0790 -							\$0.00	
	0800	POST ANCHOR FOR 2.5 IN. PSST -	Material		12	Sep 2, 2021	SYSTEM	(\$480.00)	
		7 GA.			13	Sep 16, 2021	SYSTEM	(\$480.00)	
					14	Sep 30, 2021	SYSTEM	(\$480.00)	
					15	Oct 18, 2021	SYSTEM	(\$480.00)	
					16	Nov 2, 2021	SYSTEM	\$480.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user stokez1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					16	Nov 2, 2021	SYSTEM	(\$480.00)	
					17	Nov 16, 2021	SYSTEM	\$480.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user stokez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					17	Nov 16, 2021	SYSTEM	(\$480.00)	
					18	Jan 18, 2022	SYSTEM	\$480.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user stokez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					18	Jan 18, 2022	SYSTEM	(\$480.00)	
					19	Feb 1, 2022	SYSTEM	\$480.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks															
J5P3426	0800	POST ANCHOR FOR	Material	Type	19	Feb 1, 2022	SYSTEM	(\$480.00)																
		2.5 IN. PSST - 7 GA.			20	Feb 17, 2022	SYSTEM	\$480.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.															
					20	Feb 17, 2022	SYSTEM	(\$480.00)	Estimate Exception 3 on the current rayment Estimate.															
				- Total				(\$1,920.00)																
			Material - Tota					(\$1,920.00)																
			MaterialCredit		13	Sep 16,	SYSTEM	\$480.00																
					14	2021 Sep 30,	SYSTEM	\$480.00																
					15	2021 Oct 18,	SYSTEM	\$480.00																
					16	2021 Nov 2,	SYSTEM	\$480.00																
						2021																		
				- Total				\$1,920.00																
			MaterialCredit	- Total				\$1,920.00																
		· Total						\$0.00																
	0810	SH-FLAT SHEET	Material		12	Sep 2, 2021	SYSTEM	(\$740.00)																
					13	Sep 16, 2021	SYSTEM	(\$740.00)																
					14	Sep 30, 2021	SYSTEM	(\$740.00)																
					15	Oct 18, 2021	SYSTEM	(\$740.00)																
					16	Nov 2, 2021	SYSTEM	(\$740.00)																
					17	Nov 16, 2021	SYSTEM	(\$740.00)																
					18	Jan 18, 2022	SYSTEM	(\$740.00)																
					19	Feb 1, 2022	SYSTEM	(\$740.00)																
					20	Feb 17, 2022	SYSTEM	\$740.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user stokez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.															
					20	Feb 17, 2022	SYSTEM	(\$740.00)																
				- Total				(\$5,920.00)																
			Material - Tota					(\$5,920.00)																
			MaterialCredit		13	Sep 16, 2021	SYSTEM	\$740.00																
											1	14	Sep 30, 2021	SYSTEM	\$740.00									
													15	1	15	15	15	1	1	15	Oct 18, 2021	SYSTEM	\$740.00	
													16	Nov 2, 2021	SYSTEM	\$740.00								
					17	Nov 16, 2021	SYSTEM	\$740.00																
					18	Jan 18, 2022	SYSTEM	\$740.00																
					19	Feb 1, 2022	SYSTEM	\$740.00																
					20	Feb 17, 2022	SYSTEM	\$740.00																
				- Total				\$5,920.00																
			MaterialCredit	- Total				\$5,920.00																





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3426	0810 - Total							\$0.00	
	5001	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT	Material		7	Jun 16, 2021	SYSTEM	\$10,539.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					7	Jun 16, 2021	SYSTEM	(\$10,539.00)	
				- Total	- Total				
			Material - Total					\$0.00	
	5001 - Total							\$0.00	
	5002	MISC.	Material		19	Feb 1, 2022	SYSTEM	\$5,200.02	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user stokez1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					19	Feb 1, 2022	SYSTEM	(\$5,200.02)	
					20	Feb 17, 2022	SYSTEM	\$5,200.02	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					20	Feb 17, 2022	SYSTEM	(\$5,200.02)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	5002 -	002 - Total						\$0.00	
	5004	PREF THERMO PAVMT MARKING, 6 IN WHITE	Material		19	Feb 1, 2022	SYSTEM	\$1,412.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					19	Feb 1, 2022	SYSTEM	(\$1,412.50)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	5004 - Total							\$0.00	
J5P3426 - Total							\$0.00		
Overall - Total							\$0.00		