

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: April 19, 2021

Progress Estimate Number	Contract ID 200515-F10	Pay Period Start April 2, 2021 Original Contract Amount \$3,406,354.96
17	Prime Contractor Lamke Trenchin	g & Excavating, Inc. Pay Period End April 15, 2021 Net Change Order Amount \$0.00
17		Current Contract Amount \$3,406,354.96

Approval Date		By User
April 19, 2021	Generated and Approved (and should be considered Draft) at the Project Office Level by	washid1
April 19, 2021	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	washas
April 20, 2021	Reviewed and Approved at the Central Office Controllers Office Level by	greggd1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
October 1, 2021	October 1, 2021		82.66%

	Contract Informational Dat	tes	Milestones
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract
Acceptance Date			
Awarded Date	June 3, 2020	June 3, 2020	
Letting Date	May 15, 2020	May 15, 2020	
Notice to Proceed Date	August 3, 2020	August 3, 2020	
Open to Traffic Date			
Work Began Date			

Contract Total Pa	ay For Estimate No. 17			
		This Estimate	Previous	To Date
200515-F10				
	Total Posted Items Pay	\$183,836.10	\$2,631,688.11	\$2,815,524.21
	Gross Item Adjustments	\$0.00	\$317.73	\$317.73
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
			\$2,632,005.84	\$2,815,841.94
Contract Total Pa	ayable This Estimate:	\$183,836,10		

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6S3258	0120	6083006	6 IN. CONCRETE MEDIAN STRIP	SQYD	\$49.500	1,059.6	\$52,450.20
	0135	6086004	CONCRETE SIDEWALK, 4 IN.	SQYD	\$54.000	202.7	\$10,945.80
	0140	6089902	MISC.ADA CURB RAMP	EA	\$2,250.000	4	\$9,000.00
	0650	9029902	MISC.FLASHING LED STOP SIGN	EA	\$2,711.000	2	\$5,422.00
	0660	9029902	MISC.RECTANGUALR RAPID FLASHING BEACON	EA	\$11,742.000	7	\$82,194.00
	0670	9031010	CONCRETE FOOTINGS, EMBEDDED	CUYD	\$2,300.000	2.9	\$6,670.00
	0690	9031270A	2 IN. PSST POST - 12 GA.	LF	\$12.000	231	\$2,772.00
	0700	9031272	2.25 IN. PSST POST - 12 GA.	LF	\$13.000	56	\$728.00
	0710	9031273	POST ANCHOR FOR 2 IN. PSST - 7 GA.	LF	\$30.000	63	\$1,890.00
	0720	9031280	2.5 IN. PSST POST - 12 GA.	LF	\$14.000	104	\$1,456.00
	0730	9031281	POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	LF	\$40.000	24	\$960.00
	0740	9035004A	SH-FLAT SHEET	SQFT	\$23.000	110.2	\$2,534.60
	0750	9035069A	SHF-FLAT SHEET FLUORESCENT	SQFT	\$26.000	145	\$3,770.00
	0760	9109901	MISC.ITS ASSET MANAGEMENT TOOL	LS	\$600.000	1	\$600.00
	0810	9109902	MISC.INSTALL CCTV CAMERA ASSEMBLY	EA	\$800.000	1	\$800.00
	0820	9109902	MISC.INSTALL COMMUNICATION EQUIPMENT	EA	\$455.000	1	\$455.00
	0850	9109902	MISC.WALL-MOUNTED INTERCONNECT CENTER	EA	\$466.000	2	\$932.00
	0860	9109903	MISC.CCTV CAMERA CABLE	LF	\$2.250	70	\$157.50
	0870	9109903	MISC.FIBER OPTIC CABLE, 24 STRAND, SINGLE MODE	LF	\$1.100	90	\$99.00

Revision 4/1/2020 Page 1 of 33



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: April 19, 2021

Progress Estimate Number
17

Contract ID 200515-F10 Pay Period Start April 2, 2021 Original Contract Amount \$3,406,354.96
Prime Contractor Lamke Trenching & Excavating, Inc. Pay Period End April 15, 2021 Net Change Order Amount \$0.00
Current Contract Amount \$3,406,354.96

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
Project J6S32	58 - Total						\$183,836.10
Overall - Tota							\$183,836.10

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
I6S3258	0020	EMBANKMENT IN PLACE	Material			-1,987	\$28.56	(\$56,748.72)
	0020	EMBANKMENT IN PLACE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0018) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	1,987	\$28.56	\$56,748.72
	0060	MISC.	Material			-878.4	\$90.60	(\$79,583.04)
	0060	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0019) due to user washid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	878.4	\$90.60	\$79,583.04
	0120	6 IN. CONCRETE MEDIAN STRIP	Material			-13,452	\$49.50	(\$665,874.00)
	0120	6 IN. CONCRETE MEDIAN STRIP	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user washid1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	13,452	\$49.50	\$665,874.00
	0130	8 IN. CONCRETE MEDIAN STRIP	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-311.33	\$55.00	(\$17,123.15)
	0130	8 IN. CONCRETE MEDIAN STRIP	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0001) due to user washid1 overridding Payment Estimate Exception 39 on the current Payment Estimate.	311.33	\$55.00	\$17,123.15
	0135	CONCRETE SIDEWALK, 4 IN.	Material			-524.4	\$54.00	(\$28,317.60)
	0135	CONCRETE SIDEWALK, 4 IN.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user washid1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	524.4	\$54.00	\$28,317.60
	0140	MISC.	Material			-36	\$2,250.00	(\$81,000.00)
	0140	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0020) due to user washid1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	36	\$2,250.00	\$81,000.00
	0240	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material			-476	\$20.00	(\$9,520.00)
	0240	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user washid1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	476	\$20.00	\$9,520.00
	0250	PREFORMED	Material			-113	\$20.00	(\$2,260.00)

Revision 4/1/2020 Page 2 of 33



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: April 19, 2021

Progress Estimate Number
17

Contract ID 200515-F10 Pay Period Start April 2, 2021 Original Contract Amount \$3,406,354.96
Prime Contractor Lamke Trenching & Excavating, Inc. Pay Period End April 15, 2021 Net Change Order Amount \$0.00
Current Contract Amount \$3,406,354.96

						irrent Contra		, , , , , , , , , , , , , , , , , , , ,
roject umber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
3258		THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW						
	0250	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user washid1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	113	\$20.00	\$2,260.00
	0290	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-8,077	\$0.11	(\$888.47
	0290	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user washid1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	8,077	\$0.11	\$888.47
	0300	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-8,039	\$0.11	(\$884.29
	0300	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user washid1 overridding Payment Estimate Exception 19 on the current Payment Estimate.	8,039	\$0.11	\$884.29
	0370	TOPSOIL	Material			-1,609	\$35.00	(\$56,315.00
	0370	TOPSOIL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user washid1 overridding Payment Estimate Exception 21 on the current Payment Estimate.	1,609	\$35.00	\$56,315.00
	0380	SEEDING - COOL SEASON MIXTURES	Material			-2.3	\$5,800.00	(\$13,340.00
	0380	SEEDING - COOL SEASON MIXTURES	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user washid1 overridding Payment Estimate Exception 22 on the current Payment Estimate.	2.3	\$5,800.00	\$13,340.00
	0390	TEMPORARY SEEDING AND MULCHING	Material			-0.8	\$2,200.00	(\$1,760.00
	0390	TEMPORARY SEEDING AND MULCHING	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user washid1 overridding Payment Estimate Exception 26 on the current Payment Estimate.	0.8	\$2,200.00	\$1,760.00
	0610	BASE, CONCRETE	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-1.97	\$1,555.00	(\$3,063.35
	0610	BASE, CONCRETE	Material			-14.07	\$1,555.00	(\$21,878.85
	0610	BASE, CONCRETE	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 40 on the current Payment Estimate. Material Insufficiency Quantity 14.070; Overrun Quantity Balance 1.97.	1.97	\$1,555.00	\$3,063.35
	0610	BASE, CONCRETE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user washid1 overridding Payment Estimate Exception 29	14.07	\$1,555.00	\$21,878.85

Revision 4/1/2020 Page 3 of 33



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: April 19, 2021

Progress Estimate Number
17

Contract ID 200515-F10 Pay Period Start April 2, 2021 Original Contract Amount \$3,406,354.96
Prime Contractor Lamke Trenching & Excavating, Inc. Pay Period End April 15, 2021 Net Change Order Amount \$0.00
Current Contract Amount \$3,406,354.96

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6S3258					on the current Payment Estimate.			
	0670	CONCRETE FOOTINGS, EMBEDDED	Material			-12	\$2,300.00	(\$27,600.00
	0670	CONCRETE FOOTINGS, EMBEDDED	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user washid1 overridding Payment Estimate Exception 32 on the current Payment Estimate.	12	\$2,300.00	\$27,600.00
	0760	MISC.	Material			-1	\$600.00	(\$600.00)
	0760	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user washid1 overridding Payment Estimate Exception 35 on the current Payment Estimate.	1	\$600.00	\$600.00
	0810	MISC.	Material			-1	\$800.00	(\$800.00)
	0810	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user washid1 overridding Payment Estimate Exception 36 on the current Payment Estimate.	1	\$800.00	\$800.00
	0820	MISC.	Material			-1	\$455.00	(\$455.00
	0820	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0016) due to user washid1 overridding Payment Estimate Exception 37 on the current Payment Estimate.	1	\$455.00	\$455.00
	0860	MISC.	Material			-70	\$2.25	(\$157.50)
	0860	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0017) due to user washid1 overridding Payment Estimate Exception 38 on the current Payment Estimate.	70	\$2.25	\$157.50
otal								\$0.00

Revision 4/1/2020 Page 4 of 33



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Contract Project Information
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work
J6S3258	FAF 115-1(46)	Microsurface and ADA improvements	115	ST LOUIS CITY	from St. Louis city limits to Natural Bridge
otals by J	Job Numbe	rs			
J6S3258					This Estimate Previous To Date

This Estimate Previous To Date
Gross Item Adjustments \$0.00 \$317.73 \$317.73
Gross Item Pay \$183,836.10 \$2,632,005.84 \$2,815,841.94
Incentive \$0.00 \$0.00 \$0.00
Disincentive \$0.00 \$0.00 \$0.00
Liquidated Damages \$0.00 \$0.00 \$0.00
Other Contract Adjustments \$0.00 \$0.00 \$0.00

Revision 4/1/2020 Page 5 of 33



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			1
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 2035500, Project Item Line Number 0020, Material Set 203550096, Material 0200XXCS - Compacted Soil for Subgrade orEmbankment, Acceptance Action Generic 0200XXCS is insufficient.	Need to create sample record.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 5029905, Project Item Line Number 0060, Material Set 502990596, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Need QA & QC material reports.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 5029905, Project Item Line Number 0060, Material Set 502990596, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Need QA & QC material reports.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 5029905, Project Item Line Number 0060, Material Set 502990596, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Need QA & QC material reports.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6083006, Project Item Line Number 0120, Material Set 608300696, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Need QA & QC material reports.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6083006, Project Item Line Number 0120, Material Set 608300696, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Need QA & QC material reports.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6083006, Project Item Line Number 0120, Material Set 608300696, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Need QA & QC material reports.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6086004, Project Item Line Number 0135, Material Set 608600496, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Need QA & QC material reports.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6086004, Project Item Line Number 0135, Material Set 608600496, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Need QA & QC material reports.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6086004, Project Item Line Number 0135, Material Set 608600496, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Need QA & QC material reports.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6089902, Project Item Line Number 0140, Material Set 6089902, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Need QA & QC material reports.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6089902, Project Item Line Number 0140, Material Set 6089902, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Need QA & QC material reports.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6089902, Project Item Line Number 0140, Material Set 6089902, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Need QA & QC material reports.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6089902, Project Item Line Number 0140, Material Set 6089902, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Need QA & QC material reports.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6200015, Project Item Line Number 0240, Material Set 620001596, Material 1048PMPFWH - Performed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Material not installed.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6200018, Project Item Line Number 0250, Material Set 620001896, Material 1048PMPFYL - Performed Thermoplastic Marking Tape YL, Acceptance Action Generic 1048PMPFYL is insufficient.	Material not installed.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6206000C, Project Item Line Number 0290, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	Material not installed.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6206000C, Project Item Line Number 0290, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Material not installed.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6206001C, Project Item Line Number 0300, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Material not installed.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6206001C, Project Item Line Number 0300, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	Material not installed.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 8041000, Project Item Line Number 0370, Material Set 804100096, Material 0804TP - Topsoil, Acceptance Action Generic 0804TP is insufficient.	Need to create sample record.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 8051000A, Project Item Line Number 0380, Material Set 8051000A96, Material 0801FZ - Fertilizer, Acceptance Action Generic 0801FZ is insufficient.	Need to create sample record.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 8051000A, Project Item Line Number 0380, Material Set 8051000A96, Material 0801AG - Agricultural Lime -Effective Nuetralizer, Acceptance Action Generic 0801AG is insufficient.	Need to create sample record.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 8051000A, Project Item Line Number 0380, Material Set 8051000A96, Material 0802MLST - Mulch Straw (Vegetative Mulch),	Need to create sample record.	washid1	Overridden

Revision 4/1/2020 Page 6 of 33



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Acceptance Action Generic 0802MLST is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 8051000A, Project Item Line Number 0380, Material Set 8051000A96, Material 0805SD - Grass Seed -Seed, Acceptance Action Generic 0805SD is insufficient.	Need to create sample record.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 8061017, Project Item Line Number 0390, Material Set 806101796, Material 0805SD - Grass Seed -Seed, Acceptance Action Generic 0805SD is insufficient.	Need to create sample record.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 8061017, Project Item Line Number 0390, Material Set 806101796, Material 0802MLST - Mulch Straw (Vegetative Mulch), Acceptance Action Generic 0802MLST is insufficient.	Need to create sample record.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 8061017, Project Item Line Number 0390, Material Set 806101796, Material 0801FZ - Fertilizer, Acceptance Action Generic 0801FZ is insufficient.	Need to create sample record.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 9029100, Project Item Line Number 0610, Material Set 902910096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Need QA & QC material reports.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 9029100, Project Item Line Number 0610, Material Set 902910096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Need QA & QC material reports.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 9029100, Project Item Line Number 0610, Material Set 902910096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Need QA & QC material reports.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 9031010, Project Item Line Number 0670, Material Set 903101096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Need QA & QC material reports.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 9031010, Project Item Line Number 0670, Material Set 903101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Need QA & QC material reports.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 9031010, Project Item Line Number 0670, Material Set 903101096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Need QA & QC material reports.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 9109901, Project Item Line Number 0760, Material Set 9109901, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Need to create sample record.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 9109902, Project Item Line Number 0810, Material Set 9109902, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Need to create sample record.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 9109902, Project Item Line Number 0820, Material Set 9109902, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Need to create sample record.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 9109903, Project Item Line Number 0860, Material Set 9109903, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Need to create sample record.	washid1	Overridden
Estimate Exception Type: Item Overrun: Contract 200515-F10, Contract Project J6S3258, Project Item Line Number 0130, Contract Line Item Number 0130, Item 6083008, Minor Item.	Design change.	washid1	Overridden
Estimate Exception Type: Item Overrun: Contract 200515-F10, Contract Project J6S3258, Project Item Line Number 0610, Contract Line Item Number 0610, Item 9029100, Minor Item.	Design error.	washid1	Overridden

Revision 4/1/2020 Page 7 of 33



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note: Posted Q	uantities	and Valu	es are b	ased on R	eport Generated date and can differ from the posted am	ount at the	time the	Estimate wa	s Gener	ated.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200515-F10	J6S3258	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS		\$142,000.00	\$142,000.00
		0001	0020	2035500	EMBANKMENT IN PLACE	1,987.00	0.00	1,987.00	CUYD	1,987.00	\$28.56	\$56,748.72
		0001	0030	3049905	MISC.TYPE 5 AGGREGATE FOR BASE (11.5 IN. THICK)	835.00	0.00	835.00	SQYD	0.00	\$10.00	\$0.00
		0001	0040	4010102	9 INCHES, BITUMINOUS PAVEMENT	418.80	0.00	418.80	SQYD	181.00	\$85.00	\$15,385.00
		0001	0050	4139905	MISC.MODIFIED MICROSURFACING, TYPE II	207,095.00	0.00	207,095.00	SQYD	191,318.30	\$2.90	\$554,823.07
		0001	0060	5029905	MISC.CONTRAST CONCRETE PAVEMENT, 7.5 IN.	878.40	0.00	878.40	SQYD	878.40	\$90.60	\$79,583.04
		0001	0070	6039902	WATER	35.00	0.00	35.00	EA	17.00	\$225.00	\$3,825.00
		0001	0080	6042010	ADJUSTING MANHOLE	5.00	0.00	5.00	EA	3.00	\$500.00	\$1,500.00
		0001	0090	6049902	MISC.ADJUST PULL BOXES	12.00	0.00	12.00	EA	1.00	\$710.00	\$710.00
		0001	0100	6081000	CONCRETE MEDIAN	834.70	0.00	834.70	SQYD	0.00	\$47.50	\$0.00
		0001	0110	6081012	TRUNCATED DOMES	1,350.00	0.00	1,350.00	SQFT	280.00	\$24.00	\$6,720.00
		0001	0120	6083006	6 IN. CONCRETE MEDIAN STRIP	16,524.20	0.00	16,524.20	SQYD	14,511.60	\$49.50	\$718,324.20
		0001	0130	6083008	8 IN. CONCRETE MEDIAN STRIP	1,898.60	0.00	1,898.60	SQYD	2,209.93	\$55.00	\$121,546.15
		0001	0135	6086004	CONCRETE SIDEWALK, 4 IN.	524.40	0.00	524.40	SQYD	524.40	\$54.00	\$28,317.60
		0001	0140	6089902	MISC.ADA CURB RAMP	36.00	0.00	36.00	EA	36.00	\$2,250.00	\$81,000.00
		0001	0150	6089902	MISC.ISLAND TUBULAR MARKER	870.00	0.00	870.00	EA	698.00	\$45.00	\$31,410.00
		0001	0160	6092021	INTEGRAL CURB (OVER 6 IN. HEIGHT) TYPE A	577.00	0.00	577.00	LF	577.00	\$15.00	\$8,655.00
		0001	0170	6133020	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	125.30	0.00	125.30	TONS	108.50	\$250.00	\$27,125.00
		0001	0180	6133021	REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	747.40	0.00	747.40	SQYD	672.10	\$5.55	\$3,730.16
		0001	0190	6169901	MISC.TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.50	\$32,582.50	\$16,291.25
		0001	0200	6169902	MISC NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN (CONTRACTOR FURNISHED AND RETAINED)	2.00	0.00	2.00	EA	0.00	\$5,000.00	\$0.00
		0001	0210	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$365,000.00	\$365,000.00
		0001	0220	6200003	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 4 IN., WHITE	2,340.00	0.00	2,340.00	LF	253.00	\$5.00	\$1,265.00
		0001	0230	6200006	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 4 IN YELLOW	699.00	0.00	699.00	LF	0.00	\$5.00	\$0.00
		0001	0240	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	1,906.00	0.00	1,906.00	LF	476.00	\$20.00	\$9,520.00
		0001	0250	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	437.00	0.00	437.00	LF	113.00	\$20.00	\$2,260.00
		0001	0260	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	108.00	0.00	108.00	EA	29.00	\$300.00	\$8,700.00
		0001	0270	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	897.00	0.00	897.00	EA	509.00	\$180.00	\$91,620.00
		0001	0280	6200042	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	309.00	0.00	309.00	EA	251.00	\$50.00	\$12,550.00
		0001	0290	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	60,094.00	0.00	60,094.00	LF	8,077.00	\$0.11	\$888.47
		0001	0300	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	51,999.00	0.00	51,999.00	LF	8,039.00	\$0.11	\$884.29
		0001	0310	6207001	PAVEMENT MARKING REMOVAL	8,509.00	0.00	8,509.00	LF	3,453.20	\$1.00	\$3,453.20
		0001	0320	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	322.00	0.00	322.00	EA	196.00	\$50.00	\$9,800.00
		0001	0330	6209902	MISC.CURB REFLECTORS	1,302.00	0.00	1,302.00	EA	843.00	\$4.00	\$3,372.00
		0001	0340	6209902	MISC.LANE REDUCTION ARROW	12.00	0.00	12.00	EA	0.00	\$1,700.00	\$0.00
		0001	0350	6221003	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (GREATER THAN 3 IN. THICK)	1,669.00	0.00	1,669.00	SQYD	1,669.00	\$7.85	\$13,101.65
		0001	0360	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.25	\$22,000.00	\$5,500.00
		0001	0370	8041000	TOPSOIL	1,609.00	0.00	1,609.00	CUYD	1,609.00	\$35.00	\$56,315.00
		0001	0380	8051000A	SEEDING - COOL SEASON MIXTURES	2.30	0.00	2.30	ACRE	2.30	\$5,800.00	\$13,340.00
		0001	0390	8061017	TEMPORARY SEEDING AND MULCHING	0.80	0.00	0.80	ACRE	0.80	\$2,200.00	\$1,760.00
		0020	0400	9019902	MISC.REMOVE AND RESET ST LOUIS CITY LIGHT	5.00	0.00	5.00	EA	4.00	\$2,134.00	\$8,536.00
		0030	0410	9020513	SIGNAL HEAD, TYPE 3B	8.00	0.00	8.00	EA	8.00	\$830.00	\$6,640.00
		0030	0420	9020514	SIGNAL HEAD, TYPE 4B	2.00	0.00	2.00	EA	2.00	\$905.00	\$1,810.00
		0030	0430	9020811	SIGNAL HEAD, TYPE 1S, PEDESTRIAN	8.00	0.00	8.00	EA	8.00	\$410.00	\$3,280.00
Revision 4/1/202	20											Page 8 of 33

Page 8 of 33 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200515-F10	J6S3258	0030	0440	9020833	SH-FLAT SHEET - SIGNAL SIGN	10.00	0.00	10.00	SQFT	0.00	\$40.00	\$0.00
		0030	0450	9020834	SIGNAL SIGN, MOUNTING HARDWARE	2.00	0.00	2.00	EA	0.00	\$28.00	\$0.00
		0030	0460	9022708	POST, SIGNAL 8 FT. OR 2.4 M	2.00	0.00	2.00	EA	2.00	\$571.00	\$1,142.00
		0030	0480	9023135	POST, TYPE CL, 35 FT. ARM OR 10.7 M ARM	1.00	0.00	1.00	EA	1.00	\$7,817.00	\$7,817.00
		0030	0485	9023230	POST, TYPE C, 30 FT. ARM OR 9.1 M ARM	1.00	0.00	1.00	EA	1.00	\$7,095.00	\$7,095.00
		0030	0495	9023250	POST, TYPE C, 50 FT. ARM OR 15.2 M ARM	2.00	0.00	2.00	EA	2.00	\$10,610.00	\$21,220.00
		0030	0500	9024283	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	1.00	0.00	1.00	EA	1.00	\$14,960.00	\$14,960.00
		0030	0510	9024975	VIDEO DETECTION SYSTEM	1.00	0.00	1.00	EA	1.00	\$16,027.00	\$16,027.00
		0030	0520	9025200	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE	14.00	0.00	14.00	LF	14.00	\$9.20	\$128.80
		0030	0530	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	123.00	0.00	123.00	LF	123.00	\$11.40	\$1,402.20
		0030	0540	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	250.00	0.00	250.00	LF	250.00	\$32.80	\$8,200.00
		0030	0550	9028208	CABLE, 8 AWG 1 CONDUCTOR, POWER	70.00	0.00	70.00	LF	63.00	\$0.95	\$59.85
		0030	0560	9028308	CABLE, 16 AWG 2 CONDUCTOR	1,270.00	0.00	1,270.00	LF	1,207.00	\$0.50	\$603.50
		0030	0570	9028310	CABLE, 16 AWG 5 CONDUCTOR	1,280.00	0.00	1,280.00	LF	1,215.00	\$1.10	\$1,336.50
		0030	0580	9028311	CABLE, 16 AWG 7 CONDUCTOR	2,150.00	0.00	2,150.00	LF	2,051.00	\$1.60	\$3,281.60
		0030	0590	9028811	PULL BOX, PREFORMED CLASS 2	3.00	0.00	3.00	EA	3.00	\$1,221.00	\$3,663.00
		0030	0600	9028812	PULL BOX, PREFORMED CLASS 3	1.00	0.00	1.00	EA	1.00	\$1,643.00	\$1,643.00
		0030	0610	9029100	BASE, CONCRETE	12.10	0.00	12.10	CUYD	14.07	\$1,555.00	\$21,878.85
		0030	0620	9029902	MISC.ATC TRAFFIC SIGNAL CONTROLLER	1.00	0.00	1.00	EA	0.00	\$3,270.00	\$0.00
		0030	0630	9029902	MISC.AUDIBLE PEDESTRIAN PUSHBUTTON AND SIGNING	8.00	0.00	8.00	EA	0.00	\$652.00	\$0.00
		0030	0640	9029902	MISC.COMBINATION PAD MOUNTED 120V/240V POWER SUPPLY AND LIGHTING CONTROLLER WITH UPS	1.00	0.00	1.00	EA	1.00	\$12,615.00	\$12,615.00
		0030	0650	9029902	MISC.FLASHING LED STOP SIGN	4.00	0.00	4.00	EA	2.00	\$2,711.00	\$5,422.00
		0030	0660	9029902	MISC.RECTANGUALR RAPID FLASHING BEACON	11.00	0.00	11.00	EA	7.00	\$11,742.00	\$82,194.00
		0040	0670	9031010	CONCRETE FOOTINGS, EMBEDDED	19.00	0.00	19.00	CUYD	12.00	\$2,300.00	\$27,600.00
		0040	0680	9031241	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE)	12.00	0.00	12.00	EA	0.00	\$250.00	\$0.00
		0040	0690	9031270A	2 IN. PSST POST - 12 GA.	1,608.00	0.00	1,608.00	LF	1,142.00	\$12.00	\$13,704.00
		0040	0700	9031272	2.25 IN. PSST POST - 12 GA.	164.00	0.00	164.00	LF	140.00	\$13.00	\$1,820.00
		0040	0710	9031273	POST ANCHOR FOR 2 IN. PSST - 7 GA.	450.00	0.00	450.00	LF	321.00	\$30.00	\$9,630.00
		0040	0720	9031280	2.5 IN. PSST POST - 12 GA.	503.00	0.00	503.00	LF	188.00	\$14.00	\$2,632.00
		0040	0730	9031281	POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	120.00	0.00	120.00	LF	42.00	\$40.00	\$1,680.00
		0040	0740	9035004A	SH-FLAT SHEET	663.00	0.00	663.00	SQFT	543.20	\$23.00	\$12,493.60
		0040	0750	9035069A	SHF-FLAT SHEET FLUORESCENT	768.00	0.00	768.00	SQFT	358.00	\$26.00	\$9,308.00
		0050	0760	9109901	MISC.ITS ASSET MANAGEMENT TOOL	1.00	0.00	1.00	LS	1.00	\$600.00	\$600.00
		0050	0770	9109902	MISC.CCTV CAMERA ASSEMBLY	1.00	0.00	1.00	EA	1.00	\$2,599.00	\$2,599.00
		0050	0780	9109902	MISC.FIBER OPTIC FUSION SPLICE	8.00	0.00	8.00	EA	4.00	\$111.00	\$444.00
		0050	0790	9109902	MISC.FIBER OPTIC JUMPER	8.00	0.00	8.00	EA	2.00	\$18.00	\$36.00
		0050	0800	9109902	MISC.FIBER OPTIC PIGTAIL	8.00	0.00	8.00	EA	4.00	\$9.00	\$36.00
		0050	0810	9109902	MISC.INSTALL CCTV CAMERA ASSEMBLY	1.00	0.00	1.00	EA	1.00	\$800.00	\$800.00
		0050	0820	9109902	MISC.INSTALL COMMUNICATION EQUIPMENT	1.00	0.00	1.00	EA	1.00	\$455.00	\$455.00
		0050	0830	9109902	MISC.ITS PULL BOX, CLASS 5	1.00	0.00	1.00	EA	1.00	\$1,498.00	\$1,498.00
		0050	0840	9109902	MISC.NETWORK CONNECTED SIGNAL MONITOR	1.00	0.00	1.00	EA	1.00	\$1,021.00	\$1,021.00
		0050	0850	9109902	MISC.WALL-MOUNTED INTERCONNECT CENTER	2.00	0.00	2.00	EA	2.00	\$466.00	\$932.00
		0050	0860	9109903	MISC.CCTV CAMERA CABLE	70.00	0.00	70.00	LF	70.00	\$2.25	\$157.50
		0050	0870	9109903	MISC.FIBER OPTIC CABLE, 24 STRAND, SINGLE MODE	90.00	0.00	90.00	LF	90.00	\$1.10	\$99.00
	Project Je	6S3258 - To	tal Value	Posted to D	late as of Report Generated Date							\$2,815,524.20
200515-F10 Over	rall - Total	Value Post	ed to Dat	e as of Repo	ort Generated Date							\$2,815,524.20

Page 9 of 33 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number			DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0120	6083006	6 IN. CONCRETE MEDIAN STRIP	4/2/21	4/13/21	6.00	SQYD	Rte. 115 @ Darby	2+99		3+09		Median
				4/13/21	6.60	SQYD	Rte 115 @ Darby	2+99		3+19		Bump Out
				4/13/21	10.70	SQYD	Rte. 115 @ Darby	3+33		3+46		Median
				4/13/21	28.30	SQYD	Rte. 115 @ Darby	2+68		2+89		
				4/13/21	34.30	SQYD	Rte. 115 @ Darby	3+56		3+80		Median
				4/13/21	260.90	SQYD	Goodfellow at Rte. 115.	0+48		2+00		
			4/5/21	4/13/21	192.00	SQYD	Goodfellow Left	0+65		1+72		
			4/6/21	4/13/21	72.60	SQYD	Rte. 115 West of Goodfellow.	16+94		18+24		
				4/13/21	79.80	SQYD	Goodfellow North	0+77		1+67		
				4/13/21	231.60	SQYD	Rte. 115 East of Goodfellow	13+78		15+63		
			4/15/21	4/16/21	33.20	SQYD	Rte. 115 Left	19+15		20+14		
				4/16/21	103.60	SQYD	Rte. 115 Left WB Rte. 115 to NB Goodfellow	16+22		17+44		
0135	6086004	CONCRETE SIDEWALK, 4 IN.	4/12/21	4/13/21	40.30	SQYD	SE Quadrant at Rte. 115 and Goodfellow.	0+10	0+35			
				4/13/21	84.00	SQYD	NE Quadrant at Rte. 115 and Goodfellow	0+00	1+00			
			4/15/21	4/16/21	78.40	SQYD	SW corner of Rte. 115 at Goodfellow	15+20		16+30		
0140	6089902	MISC. CONCRETE	4/12/21	4/13/21	1.00	EA	NjE Quadrant at Rte. 115 and Goodfellow.	0+00		0+15		
				4/13/21	2.00	EA	SE Quadrant of Rte. 115 and Goodfellow.	0+00		0+35		
			4/15/21	4/16/21	1.00	EA	NE corner of Rte. 115 and Goodfellow, on Goodfellow.	0+70		0+70		
0650	9029902	MISC.	4/9/21	4/14/21	2.00	EA	Darby St.	2+84	RT	3+59	LT	Rte.115 & Darby St.
0660	9029902	MISC.	4/9/21	4/14/21	1.00	EA	Clay Ave.					Rte.115 & Clay Ave.
				4/14/21	2.00	EA	Lambdin Ave.					Rte.115 & Lambdin Ave.
				4/14/21	2.00	EA	Spring Ave.					Rte.115 & Spring Ave.
				4/14/21	2.00	EA	Warne Ave.					Rte.116 & Warne Ave.
0670	9031010	CONCRETE FOOTINGS, EMBEDDED	4/14/21	4/19/21	2.90	CUYD	Rte.115 & Goodfellow Blvd.					Rte.115
0690	9031270A	2 IN. PSST POST - 12 GA.	4/14/21	4/19/21	231.00	LF	Rte.115 & Goodfellow Blvd.					Rte.115
0700	9031272	2.25 IN. PSST POST - 12 GA.	4/14/21	4/19/21	56.00	LF	Rte.115 & Goodfellow Blvd.					Rte.115
0710		POST ANCHOR FOR 2 IN. PSST - 7 GA.	4/14/21		63.00		Rte.115 & Goodfellow Blvd.					Rte.115
0720	9031280	2.5 IN. PSST POST - 12 GA.	4/14/21	4/19/21	104.00	LF	Rte.115 & Goodfellow Blvd.					Rte.115
0730	9031281	POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	4/14/21	4/19/21	24.00	LF	Rte.115 & Goodfellow Blvd.					Rte.115
0740		SH-FLAT SHEET	4/14/21	4/19/21	110.20		Rte.115 & Goodfellow Blvd.					Rte.115
0750		SHF-FLAT SHEET FLUORESCENT	4/14/21	4/19/21	145.00	SQFT	Rte.115 & Goodfellow Blvd.					Rte.115
0760		MISC. ITS	4/12/21		1.00		Fair Ave.					Rte.115 & Fair Ave.
0810	9109902	MISC. ITS	4/12/21	4/14/21	1.00	EA	Fair Ave.					Rte.115 & Fair Ave.
0820	9109902	MISC. ITS	4/12/21	4/14/21	1.00	EA	Fair Ave.					Rte.115 & Fair Ave.
0850		MISC. ITS		4/14/21	2.00		Fair Ave.					Rte.115 & Fair Ave.
0860		MISC. ITS	4/12/21	4/14/21	70.00	LF	Fair Ave.					Rte.115 & Fair Ave.
0870	9109903	MISC. ITS	4/12/21	4/14/21	90.00	LF	Fair Ave.					Rte.115 & Fair Ave.

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 4/1/2020 Page 10 of 33



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3258	0020	EMBANKMENT IN PLACE	Material		6	Nov 3, 2020	SYSTEM	\$56,748.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Nov 3, 2020	SYSTEM	(\$56,748.72)	
					7	Nov 16, 2020	SYSTEM	\$56,748.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Nov 16, 2020	SYSTEM	(\$56,748.72)	
					8	Dec 2, 2020	SYSTEM	\$56,748.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					8	Dec 2, 2020	SYSTEM	(\$56,748.72)	
					9	Dec 16, 2020	SYSTEM	\$56,748.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					9	Dec 16, 2020	SYSTEM	(\$56,748.72)	
					10	Jan 4, 2021	SYSTEM	\$56,748.72	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					10	Jan 4, 2021	SYSTEM	(\$56,748.72)	
					11	Jan 19, 2021	SYSTEM	\$56,748.72	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					11	Jan 19, 2021	SYSTEM	(\$56,748.72)	
					12	Feb 1, 2021	SYSTEM	\$56,748.72	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					12	Feb 1, 2021	SYSTEM	(\$56,748.72)	
					13	Feb 16, 2021	SYSTEM	\$56,748.72	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					13	Feb 16, 2021	SYSTEM	(\$56,748.72)	
					14	Mar 1, 2021	SYSTEM	\$56,748.72	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					14	Mar 1, 2021	SYSTEM	(\$56,748.72)	
					15	Mar 15, 2021	SYSTEM	\$56,748.72	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					15	Mar 15, 2021	SYSTEM	(\$56,748.72)	
					16	Apr 1, 2021	SYSTEM	\$56,748.72	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					16	Apr 1, 2021	SYSTEM	(\$56,748.72)	
					17	Apr 19, 2021	SYSTEM	\$56,748.72	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					17	Apr 19, 2021	SYSTEM	(\$56,748.72)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Price FUEL		6	Nov 3, 2020	SYSTEM	\$222.54	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$222.54	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J6S3258	0020	EMBANKMENT IN PLACE	Price FUEL	- Total				\$222.54		
	0020 -	· Total						\$222.54		
	0040	9 INCHES, BITUMINOUS	Price FUEL		6	Nov 3, 2020	SYSTEM	\$95.19	Reference Item Price Adjustment Index Adjustment Type applied is FUEL	
		PAVEMENT		- Total				\$95.19		
			Price FUEL	- Total				\$95.19		
	0040 -	· Total						\$95.19		
	0060	MISC.	Material		16	Apr 1, 2021	SYSTEM	\$79,583.04	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user washid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
					16	Apr 1, 2021	SYSTEM	(\$79,583.04)		
					17	Apr 19, 2021	SYSTEM	\$79,583.04	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user washid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
					17	Apr 19, 2021	SYSTEM	(\$79,583.04)		
				- Total				\$0.00		
			Material - To	otal				\$0.00		
	0060 -	· Total						\$0.00		
	0070	WATER - UTILITY ITEM	Material		3	Sep 17, 2020	SYSTEM	\$1,575.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					3	Sep 17, 2020	SYSTEM	(\$1,575.00)		
					4	Oct 1, 2020	SYSTEM	\$1,575.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					4	Oct 1, 2020	SYSTEM	(\$1,575.00)		
					5	Oct 15, 2020	SYSTEM	\$1,575.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					5	Oct 15, 2020	SYSTEM	(\$1,575.00)		
					6	Nov 3, 2020	SYSTEM	\$1,575.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user washid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
					6	Nov 3, 2020	SYSTEM	(\$1,575.00)		
						7	Nov 16, 2020	SYSTEM	\$1,575.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user washid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					7	Nov 16, 2020	SYSTEM	(\$1,575.00)		
					8	Dec 2, 2020	SYSTEM	\$1,575.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user washid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
					8	Dec 2, 2020	SYSTEM	(\$1,575.00)		
					9	Dec 16, 2020	SYSTEM	\$1,575.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user washid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
					9	Dec 16, 2020	SYSTEM	(\$1,575.00)		
					10	Jan 4, 2021	SYSTEM	\$1,575.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user washid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
					10	Jan 4, 2021	SYSTEM	(\$1,575.00)		
					11	Jan 19, 2021	SYSTEM	\$1,575.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user washid1 overridding Payment	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
J6S3258	0070	WATER - UTILITY ITEM	Material		11	Jan 19,	SYSTEM	(\$1,575.00)	Estimate Exception 2 on the current Payment Estimate.			
				- Total		2021		\$0.00				
			Material - To					\$0.00				
	0070 -	Total	material 1	J. C.				\$0.00				
	0110	TRUNCATED DOMES	Material		9	Dec 16, 2020	SYSTEM	\$6,720.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user washid1 overridding Payment Estimate Exception 3 on the current Payment Estimate.			
					9	Dec 16, 2020	SYSTEM	(\$6,720.00)				
					10	Jan 4, 2021	SYSTEM	\$6,720.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user washid1 overridding Payment Estimate Exception 3 on the current Payment Estimate.			
					10	Jan 4, 2021	SYSTEM	(\$6,720.00)				
				- Total				\$0.00				
			Material - To	otal				\$0.00				
	0110 -	Total						\$0.00				
	0120	6 IN. CONCRETE MEDIAN STRIP	Material		1	Aug 17, 2020	SYSTEM	\$69,304.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.			
					1	Aug 17, 2020	SYSTEM	(\$69,304.95)				
							2	Sep 1, 2020	SYSTEM	\$259,483.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
							2	Sep 1, 2020	SYSTEM	(\$259,483.95)		
					3	Sep 17, 2020	SYSTEM	\$341,807.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user washid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.			
					3	Sep 17, 2020	SYSTEM	(\$341,807.40)				
					4	Oct 1, 2020	SYSTEM	\$403,959.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user washid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.			
					4	Oct 1, 2020	SYSTEM	(\$403,959.60)				
					5	Oct 15, 2020	SYSTEM	\$608,394.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user washid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.			
					5	Oct 15, 2020	SYSTEM	(\$608,394.60)				
					6	Nov 3, 2020	SYSTEM	\$610,300.35	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user washid1 overridding Payment Estimate Exception 3 on the current Payment Estimate.			
					6	Nov 3, 2020	SYSTEM	(\$610,300.35)				
					7	Nov 16, 2020	SYSTEM	\$650,202.30	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user washid1 overridding Payment Estimate Exception 3 on the current Payment Estimate.			
								7	Nov 16, 2020	SYSTEM	(\$650,202.30)	
					8	Dec 2, 2020	SYSTEM	\$665,874.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user washid1 overridding Payment Estimate Exception 3 on the current Payment Estimate.			
					8	Dec 2, 2020	SYSTEM	(\$665,874.00)				
					9	Dec 16, 2020	SYSTEM	\$665,874.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user washid1 overridding Payment Estimate Exception 4 on the current Payment Estimate.			
					9	Dec 16,	SYSTEM	(\$665,874.00)				



March 100 10	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
MEDIAN STRIP	J6S3258	0120		Material			2020							
1						10		SYSTEM	\$665,874.00	Estimate Item Adjustment (0007) due to user washid1 overridding Payment				
2021 2021						10		SYSTEM	(\$665,874.00)					
12 Peb 11						11		SYSTEM	\$665,874.00	Estimate Item Adjustment (0006) due to user washid1 overridding Payment				
2021 Feb 1,						11		SYSTEM	(\$665,874.00)					
13						12		SYSTEM	\$665,874.00	Estimate Item Adjustment (0007) due to user washid1 overridding Payment				
2021 Estimate Item Adjustment (0007) due to user washind overridding Payment Estimate Exception 2 on the current Payment Estimate Scaption 2 on the current Payment Estimate Scaption 2 on the current Payment Estimate Payment Estimate Scaption 2 on the current Payment Estimate Payment Estimate Scaption 2 on the current Payment Estimate Scaption 3 on the current Payment Scattinate Scaption 4 on the current Payment Scattinate Scaption 4 on the current Payment Scattinate Scaption 5 on the current Payment Scattinate S						12		SYSTEM	(\$665,874.00)					
14						13		SYSTEM	\$665,874.00	Estimate Item Adjustment (0007) due to user washid1 overridding Payment				
2021 Estimate Item Adjustment (0009) due to user washift overridding Payment Estimate Exception 2 on the current Payment Estimate.						13		SYSTEM	(\$665,874.00)					
15						14		SYSTEM	\$665,874.00	Estimate Item Adjustment (0009) due to user washid1 overridding Payment				
2021						14		SYSTEM	(\$665,874.00)					
2021 16						15		SYSTEM	\$665,874.00	Estimate Item Adjustment (0007) due to user washid1 overridding Payment				
Estimate Item Adjustment (0006) due to user washid1 overridding Payment Estimate Exception 5 on the current Payment Estimate. 16										15		SYSTEM	(\$665,874.00)	
2021						16		SYSTEM	\$517,403.70	Estimate Item Adjustment (0006) due to user washid1 overridding Payment				
2021 Sept System Solon						16		SYSTEM	(\$517,403.70)					
10120 - Total S0.00						17		SYSTEM	\$665,874.00	Estimate Item Adjustment (0006) due to user washid1 overridding Payment				
130 Total So.00 So.00						17		SYSTEM	(\$665,874.00)					
Sum Sum					- Total				\$0.00					
Discription Sind Concrete Material 2 Sep 1, 2020 SySTEM \$53,339.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 4 on the current Payment Estimate.				Material - To	otal				\$0.00					
CONCRETE MEDIAN STRIP 2 Sep 1, 2020 SYSTEM (\$53,339.00) 3 Sep 17, 2020 SYSTEM (\$109,906.50) This adjustment offsets the original system-generated Overrun Payment Estimate Exception 5 on the current Payment Estimate. 3 Sep 17, 2020 SYSTEM (\$109,906.50) 4 Oct 1, 2020 SYSTEM (\$109,906.50) 4 Oct 1, 2020 SYSTEM (\$121,546.15) 5 Oct 15, 2020 SYSTEM (\$121,546.15) 5 Oct 15, SYSTEM (\$121,546.15) 5 Oct 15, SYSTEM (\$121,546.15) 6 Oct 15, SYSTEM (\$121,546.15) 7 This adjustment offsets the original system-generated Overrun Payment Estimate Exception 5 on the current Payment Estimate.		0120 -	Total						\$0.00					
3 Sep 17, 2020 SYSTEM \$109,906.50 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 5 on the current Payment Estimate. 3 Sep 17, 2020 SYSTEM (\$109,906.50) 4 Oct 1, 2020 SYSTEM \$121,546.15 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user washid1 overridding Payment Estimate Exception 5 on the current Payment Estimate. 4 Oct 1, 2020 SYSTEM (\$121,546.15) 5 Oct 15, 2020 SYSTEM \$121,546.15 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 5 on the current Payment Estimate.		0130	CONCRETE	Material		2		SYSTEM	\$53,339.00	Estimate Item Adjustment (0002) due to user washid1 overridding Payment				
Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 5 on the current Payment Estimate. Sep 17, 2020 Verificial SySTEM (\$109,906.50) Verificial SySTEM (\$121,546.15) SySTEM (\$121,546.15) This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user washid1 overridding Payment Estimate Exception 5 on the current Payment Estimate. Verificial SySTEM (\$121,546.15) SySTEM (\$121,546.15) This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 5 on the current Payment Estimate.						2		SYSTEM	(\$53,339.00)					
2020 4 Oct 1, 2020 \$YSTEM \$121,546.15 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user washid1 overridding Payment Estimate Exception 5 on the current Payment Estimate. 4 Oct 1, 2020 \$YSTEM (\$121,546.15) 5 Oct 15, 2020 \$YSTEM \$121,546.15 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 5 on the current Payment Estimate. 5 Oct 15, \$YSTEM (\$121,546.15)						3		SYSTEM	\$109,906.50	Estimate Item Adjustment (0002) due to user washid1 overridding Payment				
2020 Estimate Item Adjustment (0003) due to user washid1 overridding Payment Estimate Exception 5 on the current Payment Estimate. 4 Oct 1, 2020 SYSTEM (\$121,546.15) 5 Oct 15, 2020 \$YSTEM \$121,546.15 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 5 on the current Payment Estimate. 5 Oct 15, SYSTEM (\$121,546.15)						3		SYSTEM	(\$109,906.50)					
2020 5 Oct 15, 2020 \$YSTEM \$121,546.15 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 5 on the current Payment Estimate. 5 Oct 15, \$YSTEM (\$121,546.15)										4		SYSTEM	\$121,546.15	Estimate Item Adjustment (0003) due to user washid1 overridding Payment
2020 Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 5 on the current Payment Estimate. 5 Oct 15, SYSTEM (\$121,546.15)					4		SYSTEM	(\$121,546.15)						
										5		SYSTEM	\$121,546.15	Estimate Item Adjustment (0002) due to user washid1 overridding Payment
						5		SYSTEM	(\$121,546.15)					



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																											
J6S3258	0130	8 IN. CONCRETE MEDIAN STRIP	Material	1 ype	6	Nov 3, 2020	SYSTEM	\$121,546.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user washid1 overridding Payment Estimate Exception 6 on the current Payment Estimate.																											
					6	Nov 3, 2020	SYSTEM	(\$121,546.15)																												
					7	Nov 16, 2020	SYSTEM	\$121,546.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 6 on the current Payment Estimate.																											
					7	Nov 16, 2020	SYSTEM	(\$121,546.15)																												
					8	Dec 2, 2020	SYSTEM	\$121,546.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 6 on the current Payment Estimate.																											
					8	Dec 2, 2020	SYSTEM	(\$121,546.15)																												
					9	Dec 16, 2020	SYSTEM	\$121,546.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 7 on the current Payment Estimate.																											
					9	Dec 16, 2020	SYSTEM	(\$121,546.15)																												
					10	Jan 4, 2021	SYSTEM	\$121,546.15	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 7 on the current Payment Estimate.																											
					10	Jan 4, 2021	SYSTEM	(\$121,546.15)																												
					11	Jan 19, 2021	SYSTEM	\$121,546.15	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 6 on the current Payment Estimate.																											
					11	Jan 19, 2021	SYSTEM	(\$121,546.15)																												
					12	Feb 1, 2021	SYSTEM	\$121,546.15	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 5 on the current Payment Estimate.																											
					12	Feb 1, 2021	SYSTEM	(\$121,546.15)																												
					13	Feb 16, 2021	SYSTEM	\$121,546.15	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 5 on the current Payment Estimate.																											
					13	Feb 16, 2021	SYSTEM	(\$121,546.15)																												
					14	Mar 1, 2021	SYSTEM	\$121,546.15	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 5 on the current Payment Estimate.																											
					14	Mar 1, 2021	SYSTEM	(\$121,546.15)																												
					15	Mar 15, 2021	SYSTEM	\$121,546.15	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 5 on the current Payment Estimate.																											
					15	Mar 15, 2021	SYSTEM	(\$121,546.15)																												
				- Total				\$0.00																												
			Material - To					\$0.00																												
			Overrun	Overrun	3	Sep 17, 2020	SYSTEM	\$5,483.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 9 on the current Payment Estimate.																											
					3	Sep 17, 2020	SYSTEM	(\$5,483.50)																												
					4	Oct 1, 2020	SYSTEM	(\$5,483.50)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).																											
				4																					,						,	4	Oct 1, 2020	SYSTEM	\$11,639.65	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 9
						2020			on the current Payment Estimate.																											



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks												
J6S3258	0130	8 IN. CONCRETE	Overrun	Overrun	4	Oct 1, 2020	SYSTEM	(\$11,639.65)													
		MEDIAN STRIP			5	Oct 15, 2020	SYSTEM	(\$17,123.15)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).												
					5	Oct 15, 2020	SYSTEM	\$17,123.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 9 on the current Payment Estimate.												
					6	Nov 3, 2020	SYSTEM	(\$17,123.15)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).												
					6	Nov 3, 2020	SYSTEM	\$17,123.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) overridding Payment Estimate Exception 20 on the current Payment Estimate.												
					7	Nov 16, 2020	SYSTEM	(\$17,123.15)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).												
					7	Nov 16, 2020	SYSTEM	\$17,123.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 31 on the current Payment Estimate.												
					8	Dec 2, 2020	SYSTEM	(\$17,123.15)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).												
						8	Dec 2, 2020	SYSTEM	\$17,123.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 35 on the current Payment Estimate.											
					9	Dec 16, 2020	SYSTEM	(\$17,123.15)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).												
					9	Dec 16, 2020	SYSTEM	\$17,123.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 43 on the current Payment Estimate.												
					10	Jan 4, 2021	SYSTEM	(\$17,123.15)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).												
					10	Jan 4, 2021	SYSTEM	\$17,123.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 41 on the current Payment Estimate. Material Insufficiency Quantity 2209.930; Overrun Quantity Balance 311.33.												
					11	Jan 19, 2021	SYSTEM	(\$17,123.15)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).												
					11	Jan 19, 2021	SYSTEM	\$17,123.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 37 on the current Payment Estimate. Material Insufficiency Quantity 2209.930; Overrun Quantity Balance 311.33.												
					12	Feb 1, 2021	SYSTEM	(\$17,123.15)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).												
					12	Feb 1, 2021	SYSTEM	\$17,123.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 33 on the current Payment Estimate. Material Insufficiency Quantity 2209.930; Overrun Quantity Balance 311.33.												
					13	Feb 16, 2021	SYSTEM	(\$17,123.15)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).												
					13	Feb 16, 2021	SYSTEM	\$17,123.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 34 on the current Payment Estimate. Material Insufficiency Quantity 2209.930; Overrun Quantity Balance 311.33.												
					14	Mar 1, 2021	SYSTEM	(\$17,123.15)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).												
																	14	Mar 1, 2021	SYSTEM	\$17,123.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 39 on the current Payment Estimate. Material Insufficiency Quantity 2209.930; Overrun Quantity Balance 311.33.
					15	Mar 15, 2021	SYSTEM	(\$17,123.15)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).												
											15	Mar 15, 2021	SYSTEM	\$17,123.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 33 on the current Payment Estimate. Material Insufficiency Quantity 2209.930; Overrun Quantity Balance 311.33.						
					16	Apr 1, 2021	SYSTEM	(\$17,123.15)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).												
					16	Apr 1, 2021	SYSTEM	\$17,123.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user washid1 overridding Payment												



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
J6S3258	0130	8 IN.	Overrun	Overrun					Estimate Exception 33 on the current Payment Estimate.				
		CONCRETE MEDIAN STRIP			17	Apr 19, 2021	SYSTEM	(\$17,123.15)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).				
					17	Apr 19, 2021	SYSTEM	\$17,123.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user washid1 overridding Payment Estimate Exception 39 on the current Payment Estimate.				
				Overrun - T	otal			\$0.00					
			Overrun - T	otal				\$0.00					
	0130 -	Total						\$0.00					
	0135	CONCRETE SIDEWALK, 4 IN.	Material		9	Dec 16, 2020	SYSTEM	\$6,102.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user washid1 overridding Payment Estimate Exception 10 on the current Payment Estimate.				
					9	Dec 16, 2020	SYSTEM	(\$6,102.00)					
					10	Jan 4, 2021	SYSTEM	\$6,102.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user washid1 overridding Payment Estimate Exception 8 on the current Payment Estimate.				
					10	Jan 4, 2021	SYSTEM	(\$6,102.00)					
					11	Jan 19, 2021	SYSTEM	\$17,371.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user washid1 overridding Payment Estimate Exception 7 on the current Payment Estimate.				
					11	Jan 19, 2021	SYSTEM	(\$17,371.80)					
					12	Feb 1, 2021	SYSTEM	\$17,371.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user washid1 overridding Payment Estimate Exception 6 on the current Payment Estimate.				
					12	Feb 1, 2021	SYSTEM	(\$17,371.80)					
					13	Feb 16, 2021	SYSTEM	\$17,371.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user washid1 overridding Payment Estimate Exception 6 on the current Payment Estimate.				
					13	Feb 16, 2021	SYSTEM	(\$17,371.80)					
					14	Mar 1, 2021	SYSTEM	\$17,371.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user washid1 overridding Payment Estimate Exception 6 on the current Payment Estimate.				
							14	Mar 1, 2021	SYSTEM	(\$17,371.80)			
					15	Mar 15, 2021	SYSTEM	\$17,371.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user washid1 overridding Payment Estimate Exception 6 on the current Payment Estimate.				
					15	Mar 15, 2021	SYSTEM	(\$17,371.80)					
									16	Apr 1, 2021	SYSTEM	\$17,371.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user washid1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					16	Apr 1, 2021	SYSTEM	(\$17,371.80)					
					17	Apr 19, 2021	SYSTEM	\$28,317.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user washid1 overridding Payment Estimate Exception 8 on the current Payment Estimate.				
					17	Apr 19, 2021	SYSTEM	(\$28,317.60)					
				- Total				\$0.00					
			Material - To	otal				\$0.00					
	0135 -	Total						\$0.00					
	0140	MISC. CONCRETE	Material		9	Dec 16, 2020	SYSTEM	\$15,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user washid1 overridding Payment Estimate Exception 13 on the current Payment Estimate.				
					9	Dec 16, 2020	SYSTEM	(\$15,750.00)					
					10	Jan 4,	SYSTEM	\$15,750.00	This adjustment offsets the original system-generated Material Payment				



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks									
J6S3258	0140	MISC. CONCRETE	Material			2021			Estimate Item Adjustment (0026) due to user washid1 overridding Payment Estimate Exception 11 on the current Payment Estimate.									
					10	Jan 4, 2021	SYSTEM	(\$15,750.00)										
					11	Jan 19, 2021	SYSTEM	\$54,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user washid1 overridding Payment Estimate Exception 10 on the current Payment Estimate.									
					11	Jan 19, 2021	SYSTEM	(\$54,000.00)										
					12	Feb 1, 2021	SYSTEM	\$63,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user washid1 overridding Payment Estimate Exception 9 on the current Payment Estimate.									
					12	Feb 1, 2021	SYSTEM	(\$63,000.00)										
					13	Feb 16, 2021	SYSTEM	\$63,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user washid1 overridding Payment Estimate Exception 9 on the current Payment Estimate.									
					13	Feb 16, 2021	SYSTEM	(\$63,000.00)										
					14	Mar 1, 2021	SYSTEM	\$63,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user washid1 overridding Payment Estimate Exception 9 on the current Payment Estimate.									
					14	Mar 1, 2021	SYSTEM	(\$63,000.00)										
					15	Mar 15, 2021	SYSTEM	\$63,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user washid1 overridding Payment Estimate Exception 9 on the current Payment Estimate.									
					15	Mar 15, 2021	SYSTEM	(\$63,000.00)										
					16	Apr 1, 2021	SYSTEM	\$72,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user washid1 overridding Payment Estimate Exception 11 on the current Payment Estimate.									
					16	Apr 1, 2021	SYSTEM	(\$72,000.00)										
					17	Apr 19, 2021	SYSTEM	\$81,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user washid1 overridding Payment Estimate Exception 11 on the current Payment Estimate.									
					17	Apr 19, 2021	SYSTEM	(\$81,000.00)										
				- Total				\$0.00										
			Material - To	otal				\$0.00										
	0140 -		Meterial		7	Nev 16	CVCTEM	\$0.00	This adjustment affects the existed system generated Overwin Develop									
	0160	INTEGRAL CURB (OVER 6 IN. HEIGHT) TYPE A	Material		7	Nov 16, 2020	SYSTEM	\$4,935.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user washid1 overridding Payment Estimate Exception 9 on the current Payment Estimate.									
					7	Nov 16, 2020	SYSTEM	(\$4,935.00)										
														8	Dec 2, 2020	SYSTEM	\$4,935.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user washid1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					8	Dec 2, 2020	SYSTEM	(\$4,935.00)										
					9	Dec 16, 2020	SYSTEM	\$4,935.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user washid1 overridding Payment Estimate Exception 17 on the current Payment Estimate.									
					9	Dec 16, 2020	SYSTEM	(\$4,935.00)										
					10	Jan 4, 2021	SYSTEM	\$4,935.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user washid1 overridding Payment Estimate Exception 15 on the current Payment Estimate.									
					10	Jan 4, 2021	SYSTEM	(\$4,935.00)										
					11	Jan 19, 2021	SYSTEM	\$4,935.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user washid1 overridding Payment Estimate Exception 14 on the current Payment Estimate.									



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3258	0160	INTEGRAL CURB (OVER 6	Material		11	Jan 19, 2021	SYSTEM	(\$4,935.00)	
		IN. HEIGHT) TYPE A			12	Feb 1, 2021	SYSTEM	\$4,935.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user washid1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					12	Feb 1, 2021	SYSTEM	(\$4,935.00)	
					13	Feb 16, 2021	SYSTEM	\$4,935.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user washid1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					13	Feb 16, 2021	SYSTEM	(\$4,935.00)	
					14	Mar 1, 2021	SYSTEM	\$4,935.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user washid1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					14	Mar 1, 2021	SYSTEM	(\$4,935.00)	
					15	Mar 15, 2021	SYSTEM	\$4,935.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user washid1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					15	Mar 15, 2021	SYSTEM	(\$4,935.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0160 -						0)/0751/	\$0.00	
	0190	MISC.	Material		1	Aug 17, 2020	SYSTEM	\$4,887.38	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					1	Aug 17, 2020	SYSTEM	(\$4,887.38)	
					2	Sep 1, 2020	SYSTEM	\$4,887.38	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user washid1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					2	Sep 1, 2020	SYSTEM	(\$4,887.38)	
					3	Sep 17, 2020	SYSTEM	\$16,291.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user washid1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					3	Sep 17, 2020	SYSTEM	(\$16,291.25)	
					4	Oct 1, 2020	SYSTEM	\$16,291.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user washid1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					4	Oct 1, 2020	SYSTEM	(\$16,291.25)	
					5	Oct 15, 2020	SYSTEM	\$16,291.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user washid1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					5	Oct 15, 2020	SYSTEM	(\$16,291.25)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0190 -						2) (2)	\$0.00	
	0220	PREF THERMO PAVEMENT MARKING, 4 IN	Material		9	Dec 16, 2020	SYSTEM	\$1,265.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user washid1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
		WHITE			9	Dec 16, 2020	SYSTEM	(\$1,265.00)	
					10	Jan 4, 2021	SYSTEM	\$1,265.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user washid1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					10	Jan 4, 2021	SYSTEM	(\$1,265.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																
J6S3258	0220	PREF THERMO PAVEMENT	Material		11	Jan 19, 2021	SYSTEM	\$1,265.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user washid1 overridding Payment Estimate Exception 16 on the current Payment Estimate.																
		MARKING, 4 IN WHITE			11	Jan 19, 2021	SYSTEM	(\$1,265.00)																	
				- Total				\$0.00																	
			Material - To	otal				\$0.00																	
	0220 -	- Total						\$0.00																	
	0240	PREF THERMO PVMT MARK, 24 IN WHIT	Material		7	Nov 16, 2020	SYSTEM	\$7,900.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user washid1 overridding Payment Estimate Exception 12 on the current Payment Estimate.																
		24 IIV VVI II I			7	Nov 16, 2020	SYSTEM	(\$7,900.00)																	
					8	Dec 2, 2020	SYSTEM	\$9,520.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user washid1 overridding Payment Estimate Exception 12 on the current Payment Estimate.																
					8	Dec 2, 2020	SYSTEM	(\$9,520.00)																	
					9	Dec 16, 2020	SYSTEM	\$9,520.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user washid1 overridding Payment Estimate Exception 20 on the current Payment Estimate.																
								9	Dec 16, 2020	SYSTEM	(\$9,520.00)														
					10	Jan 4, 2021	SYSTEM	\$9,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user washid1 overridding Payment Estimate Exception 18 on the current Payment Estimate.																
					10	Jan 4, 2021	SYSTEM	(\$9,520.00)																	
					11	Jan 19, 2021	SYSTEM	\$9,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user washid1 overridding Payment Estimate Exception 17 on the current Payment Estimate.																
					11	Jan 19, 2021	SYSTEM	(\$9,520.00)																	
					12	Feb 1, 2021	SYSTEM	\$9,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user washid1 overridding Payment Estimate Exception 15 on the current Payment Estimate.																
						12	Feb 1, 2021	SYSTEM	(\$9,520.00)																
					13	Feb 16, 2021	SYSTEM	\$9,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user washid1 overridding Payment Estimate Exception 15 on the current Payment Estimate.																
					13	Feb 16, 2021	SYSTEM	(\$9,520.00)																	
																14	Mar 1, 2021	SYSTEM	\$9,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user washid1 overridding Payment Estimate Exception 15 on the current Payment Estimate.					
							14	Mar 1, 2021	SYSTEM	(\$9,520.00)															
										15	Mar 15, 2021	SYSTEM	\$9,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user washid1 overridding Payment Estimate Exception 15 on the current Payment Estimate.											
													15	Mar 15, 2021	SYSTEM	(\$9,520.00)									
												1									16	Apr 1, 2021	SYSTEM	\$9,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user washid1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
																					16				
																	17	Apr 19, 2021	SYSTEM	\$9,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user washid1 overridding Payment Estimate Exception 15 on the current Payment Estimate.				
					17	Apr 19, 2021	SYSTEM	(\$9,520.00)																	
				- Total				\$0.00																	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3258	0240	PREF THERMO PVMT MARK, 24 IN WHIT	Material - To	otal				\$0.00	
	0240 -	Total						\$0.00	
	0250	PREF THERMO PVMT MARK,	Material		8	Dec 2, 2020	SYSTEM	\$2,260.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user washid1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
		24 IN YELLOW			8	Dec 2, 2020	SYSTEM	(\$2,260.00)	
					9	Dec 16, 2020	SYSTEM	\$2,260.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user washid1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					9	Dec 16, 2020	SYSTEM	(\$2,260.00)	
					10	Jan 4, 2021	SYSTEM	\$2,260.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user washid1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					10	Jan 4, 2021	SYSTEM	(\$2,260.00)	
					11	Jan 19, 2021	SYSTEM	\$2,260.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user washid1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					11	Jan 19, 2021	SYSTEM	(\$2,260.00)	
					12	Feb 1, 2021	SYSTEM	\$2,260.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user washid1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					12	Feb 1, 2021	SYSTEM	(\$2,260.00)	
					13	Feb 16, 2021	SYSTEM	\$2,260.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user washid1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					13	Feb 16, 2021	SYSTEM	(\$2,260.00)	
					14	Mar 1, 2021	SYSTEM	\$2,260.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user washid1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					14	Mar 1, 2021	SYSTEM	(\$2,260.00)	
					15	Mar 15, 2021	SYSTEM	\$2,260.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user washid1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					15	Mar 15, 2021	SYSTEM	(\$2,260.00)	
					16	Apr 1, 2021	SYSTEM	\$2,260.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user washid1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					16	Apr 1, 2021	SYSTEM	(\$2,260.00)	
					17	Apr 19, 2021	SYSTEM	\$2,260.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user washid1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					17	Apr 19, 2021	SYSTEM	(\$2,260.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0250 - 0260	Total PREF THERMO	Material		7	Nov 16, 2020	SYSTEM	\$0.00 \$3,900.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user washid1 overridding Payment
		PVMT MARK, LT/RT ARROW			7	Nov 16,	SYSTEM	(\$3,900.00)	Estimate Exception 13 on the current Payment Estimate.
					8	2020 Dec 2,	SYSTEM	\$8,700.00	This adjustment offsets the original system-generated Overrun Payment
						2020			Estimate Item Adjustment (0009) due to user washid1 overridding Payment



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
3258	0260	PREF	Material						Estimate Exception 14 on the current Payment Estimate.
		THERMO PVMT MARK, LT/RT ARROW			8	Dec 2, 2020	SYSTEM	(\$8,700.00)	
					9	Dec 16, 2020	SYSTEM	\$8,700.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user washid1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					9	Dec 16, 2020	SYSTEM	(\$8,700.00)	
					10	Jan 4, 2021	SYSTEM	\$8,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user washid1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					10	Jan 4, 2021	SYSTEM	(\$8,700.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0260 -	Total						\$0.00	
	0270	PREF THERMO PVMT MARK,	Material		7	Nov 16, 2020	SYSTEM	\$63,180.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user washid1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
		30" WHT MIDBL			7	Nov 16, 2020	SYSTEM	(\$63,180.00)	
					8	Dec 2, 2020	SYSTEM	\$77,220.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user washid1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					8	Dec 2, 2020	SYSTEM	(\$77,220.00)	
					9	Dec 16, 2020	SYSTEM	\$91,620.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user washid1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					9	Dec 16, 2020	SYSTEM	(\$91,620.00)	
					10	Jan 4, 2021	SYSTEM	\$91,620.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user washid1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					10	Jan 4, 2021	SYSTEM	(\$91,620.00)	
				- Total				\$0.00	
			Material - To	otal					
			Materiai - 1	otai				\$0.00	
	0270 -	Total	Material - 10	otai				\$0.00 \$0.00	
	0270 - 0280	PREF THERMO PVMT MARK,	Material Material	Otal	7	Nov 16, 2020	SYSTEM		This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user washid1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
		PREF THERMO		O.C.I	7		SYSTEM SYSTEM	\$0.00	Estimate Item Adjustment (0010) due to user washid1 overridding Payment
		PREF THERMO PVMT MARK,		ocai		2020 Nov 16,		\$0.00 \$4,600.00	Estimate Item Adjustment (0010) due to user washid1 overridding Payment
		PREF THERMO PVMT MARK,		ocai	7	2020 Nov 16, 2020 Dec 2,	SYSTEM	\$0.00 \$4,600.00 (\$4,600.00)	Estimate Item Adjustment (0010) due to user washid1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user washid1 overridding Payment
		PREF THERMO PVMT MARK,			7	2020 Nov 16, 2020 Dec 2, 2020	SYSTEM SYSTEM	\$0.00 \$4,600.00 (\$4,600.00) \$4,600.00	Estimate Item Adjustment (0010) due to user washid1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user washid1 overridding Payment
		PREF THERMO PVMT MARK,			7 8	2020 Nov 16, 2020 Dec 2, 2020 Dec 2, 2020 Dec 16,	SYSTEM SYSTEM SYSTEM	\$0.00 \$4,600.00 (\$4,600.00) \$4,600.00	Estimate Item Adjustment (0010) due to user washid1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user washid1 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user washid1 overridding Payment
		PREF THERMO PVMT MARK,			7 8 8 9	2020 Nov 16, 2020 Dec 2, 2020 Dec 2, 2020 Dec 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$4,600.00 (\$4,600.00) \$4,600.00 (\$4,600.00) \$12,550.00	Estimate Item Adjustment (0010) due to user washid1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user washid1 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user washid1 overridding Payment
		PREF THERMO PVMT MARK,		ocal Control of the C	7 8 8 9 9	2020 Nov 16, 2020 Dec 2, 2020 Dec 2, 2020 Dec 16, 2020 Dec 16, 2020 Jan 4,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$4,600.00 (\$4,600.00) \$4,600.00 (\$4,600.00) \$12,550.00	Estimate Item Adjustment (0010) due to user washid1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user washid1 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user washid1 overridding Payment Estimate Exception 24 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user washid1 overridding Payment Estimate Item Adjustment (0003) due to user washid1 overridding Payment
		PREF THERMO PVMT MARK,		- Total	7 8 8 9 9	2020 Nov 16, 2020 Dec 2, 2020 Dec 16, 2020 Dec 16, 2020 Jan 4, 2021 Jan 4,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$4,600.00 (\$4,600.00) \$4,600.00 (\$4,600.00) \$12,550.00 (\$12,550.00)	Estimate Item Adjustment (0010) due to user washid1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user washid1 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user washid1 overridding Payment Estimate Exception 24 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user washid1 overridding Payment Estimate Item Adjustment (0003) due to user washid1 overridding Payment
		PREF THERMO PVMT MARK,		- Total	7 8 8 9 9	2020 Nov 16, 2020 Dec 2, 2020 Dec 16, 2020 Dec 16, 2020 Jan 4, 2021 Jan 4,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$4,600.00 (\$4,600.00) \$4,600.00 (\$4,600.00) \$12,550.00 (\$12,550.00) (\$12,550.00)	Estimate Item Adjustment (0010) due to user washid1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user washid1 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user washid1 overridding Payment Estimate Exception 24 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user washid1 overridding Payment Estimate Item Adjustment (0003) due to user washid1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3258	0290	4 IN. WHITE WATERBORNE PAVEMENT	Material		7	Nov 16, 2020	SYSTEM	\$812.46	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user washid1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
		MARKING			7	Nov 16, 2020	SYSTEM	(\$812.46)	
					8	Dec 2, 2020	SYSTEM	\$812.46	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user washid1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					8	Dec 2, 2020	SYSTEM	(\$812.46)	
					9	Dec 16, 2020	SYSTEM	\$888.47	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user washid1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					9	Dec 16, 2020	SYSTEM	(\$888.47)	
					10	Jan 4, 2021	SYSTEM	\$888.47	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user washid1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					10	Jan 4, 2021	SYSTEM	(\$888.47)	
					11	Jan 19, 2021	SYSTEM	\$888.47	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user washid1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					11	Jan 19, 2021	SYSTEM	(\$888.47)	
					12	Feb 1, 2021	SYSTEM	\$888.47	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user washid1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					12	Feb 1, 2021	SYSTEM	(\$888.47)	
					13	Feb 16, 2021	SYSTEM	\$888.47	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user washid1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					13	Feb 16, 2021	SYSTEM	(\$888.47)	
					14	Mar 1, 2021	SYSTEM	\$888.47	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user washid1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					14	Mar 1, 2021	SYSTEM	(\$888.47)	
					15	Mar 15, 2021	SYSTEM	\$888.47	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user washid1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					15	Mar 15, 2021	SYSTEM	(\$888.47)	
					16	Apr 1, 2021	SYSTEM	\$888.47	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user washid1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					16	Apr 1, 2021	SYSTEM	(\$888.47)	
					17	Apr 19, 2021	SYSTEM	\$888.47	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user washid1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					17	Apr 19, 2021	SYSTEM	(\$888.47)	
				- Total				\$0.00	
	0000	T-4-L	Material - To	otal				\$0.00	
	0290 -	4 IN. YELLOW WATERBORNE PAVEMENT	Material		7	Nov 16, 2020	SYSTEM	\$0.00 \$747.67	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user washid1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
		MARKING			7	Nov 16, 2020	SYSTEM	(\$747.67)	
					8	Dec 2, 2020	SYSTEM	\$747.67	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user washid1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3258	0300	4 IN. YELLOW	Material						Estimate Exception 19 on the current Payment Estimate.
		WATERBORNE PAVEMENT MARKING			8	Dec 2, 2020	SYSTEM	(\$747.67)	
					9	Dec 16, 2020	SYSTEM	\$884.29	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user washid1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					9	Dec 16, 2020	SYSTEM	(\$884.29)	
					10	Jan 4, 2021	SYSTEM	\$884.29	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user washid1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					10	Jan 4, 2021	SYSTEM	(\$884.29)	
					11	Jan 19, 2021	SYSTEM	\$884.29	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user washid1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					11	Jan 19, 2021	SYSTEM	(\$884.29)	
					12	Feb 1, 2021	SYSTEM	\$884.29	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user washid1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					12	Feb 1, 2021	SYSTEM	(\$884.29)	
					13	Feb 16, 2021	SYSTEM	\$884.29	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user washid1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					13	Feb 16, 2021	SYSTEM	(\$884.29)	
					14	Mar 1, 2021	SYSTEM	\$884.29	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user washid1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					14	Mar 1, 2021	SYSTEM	(\$884.29)	
					15	Mar 15, 2021	SYSTEM	\$884.29	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user washid1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					15	Mar 15, 2021	SYSTEM	(\$884.29)	
					16	Apr 1, 2021	SYSTEM	\$884.29	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user washid1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					16	Apr 1, 2021	SYSTEM	(\$884.29)	
					17	Apr 19, 2021	SYSTEM	\$884.29	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user washid1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					17	Apr 19, 2021	SYSTEM	(\$884.29)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
		Total						\$0.00	
	0370	TOPSOIL	Material		6	Nov 3, 2020	SYSTEM	\$56,315.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user washid1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					6	Nov 3, 2020	SYSTEM	(\$56,315.00)	
					7	Nov 16, 2020	SYSTEM	\$56,315.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user washid1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					7	Nov 16, 2020	SYSTEM	(\$56,315.00)	
					8	Dec 2, 2020	SYSTEM	\$56,315.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user washid1 overridding Payment Estimate Exception 21 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks										
J6S3258	0370	TOPSOIL	Material		8	Dec 2, 2020	SYSTEM	(\$56,315.00)											
					9	Dec 16, 2020	SYSTEM	\$56,315.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user washid1 overridding Payment Estimate Exception 29 on the current Payment Estimate.										
					9	Dec 16, 2020	SYSTEM	(\$56,315.00)											
					10	Jan 4, 2021	SYSTEM	\$56,315.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user washid1 overridding Payment Estimate Exception 27 on the current Payment Estimate.										
					10	Jan 4, 2021	SYSTEM	(\$56,315.00)											
					11	Jan 19, 2021	SYSTEM	\$56,315.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user washid1 overridding Payment Estimate Exception 23 on the current Payment Estimate.										
					11	Jan 19, 2021	SYSTEM	(\$56,315.00)											
					12	Feb 1, 2021	SYSTEM	\$56,315.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user washid1 overridding Payment Estimate Exception 21 on the current Payment Estimate.										
					12	Feb 1, 2021	SYSTEM	(\$56,315.00)											
					13	Feb 16, 2021	SYSTEM	\$56,315.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user washid1 overridding Payment Estimate Exception 21 on the current Payment Estimate.										
					13	Feb 16, 2021	SYSTEM	(\$56,315.00)											
					14	Mar 1, 2021	SYSTEM	\$56,315.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user washid1 overridding Payment Estimate Exception 21 on the current Payment Estimate.										
					14	Mar 1, 2021	SYSTEM	(\$56,315.00)											
					15	Mar 15, 2021	SYSTEM	\$56,315.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user washid1 overridding Payment Estimate Exception 21 on the current Payment Estimate.										
						15	Mar 15, 2021	SYSTEM	(\$56,315.00)										
							16	Apr 1, 2021	SYSTEM	\$56,315.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user washid1 overridding Payment Estimate Exception 21 on the current Payment Estimate.								
										16	Apr 1, 2021	SYSTEM	(\$56,315.00)						
																		17	Apr 19, 2021
					17	Apr 19, 2021	SYSTEM	(\$56,315.00)											
			Material - To	- Total otal				\$0.00 \$0.00											
	0370 -	Total						\$0.00											
	0380	SEEDING - COOL SEASON	Material												6	Nov 3, 2020	SYSTEM	\$13,340.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user washid1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
		MIXTURES				6	Nov 3, 2020	SYSTEM	(\$13,340.00)										
					7	Nov 16, 2020	SYSTEM	\$13,340.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user washid1 overridding Payment Estimate Exception 21 on the current Payment Estimate.										
					7	Nov 16, 2020	SYSTEM	(\$13,340.00)											
					8	Dec 2, 2020	SYSTEM	\$13,340.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user washid1 overridding Payment Estimate Exception 22 on the current Payment Estimate.										
					8	Dec 2, 2020	SYSTEM	(\$13,340.00)											



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3258	0380	SEEDING - COOL SEASON	Material		9	Dec 16, 2020	SYSTEM	\$13,340.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user washid1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
		MIXTURES			9	Dec 16, 2020	SYSTEM	(\$13,340.00)	
					10	Jan 4, 2021	SYSTEM	\$13,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user washid1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					10	Jan 4, 2021	SYSTEM	(\$13,340.00)	
					11	Jan 19, 2021	SYSTEM	\$13,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user washid1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					11	Jan 19, 2021	SYSTEM	(\$13,340.00)	
					12	Feb 1, 2021	SYSTEM	\$13,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user washid1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					12	Feb 1, 2021	SYSTEM	(\$13,340.00)	
					13	Feb 16, 2021	SYSTEM	\$13,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user washid1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					13	Feb 16, 2021	SYSTEM	(\$13,340.00)	
					14	Mar 1, 2021	SYSTEM	\$13,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user washid1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					14	Mar 1, 2021	SYSTEM	(\$13,340.00)	
					15	Mar 15, 2021	SYSTEM	\$13,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user washid1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					15	Mar 15, 2021	SYSTEM	(\$13,340.00)	
					16	Apr 1, 2021	SYSTEM	\$13,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user washid1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					16	Apr 1, 2021	SYSTEM	(\$13,340.00)	
					17	Apr 19, 2021	SYSTEM	\$13,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user washid1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					17	Apr 19, 2021	SYSTEM	(\$13,340.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0380 -	Total						\$0.00	
	0390	TEMPORARY SEEDING AND MULCHING	Material		6	Nov 3, 2020	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user washid1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					6	Nov 3, 2020	SYSTEM	(\$1,760.00)	
					7	Nov 16, 2020	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user washid1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					7	Nov 16, 2020	SYSTEM	(\$1,760.00)	
					8	Dec 2, 2020	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user washid1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					8	Dec 2, 2020	SYSTEM	(\$1,760.00)	
					9	Dec 16,	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Overrun Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
6S3258	0390	TEMPORARY	Material	71					Estimate Exception 34 on the current Payment Estimate.
		SEEDING AND MULCHING			9	Dec 16, 2020	SYSTEM	(\$1,760.00)	
					10	Jan 4, 2021	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user washid1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					10	Jan 4, 2021	SYSTEM	(\$1,760.00)	
					11	Jan 19, 2021	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user washid1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					11	Jan 19, 2021	SYSTEM	(\$1,760.00)	
					12	Feb 1, 2021	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user washid1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					12	Feb 1, 2021	SYSTEM	(\$1,760.00)	
					13	Feb 16, 2021	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user washid1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					13	Feb 16, 2021	SYSTEM	(\$1,760.00)	
					14	Mar 1, 2021	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user washid1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					14	Mar 1, 2021	SYSTEM	(\$1,760.00)	
					15	Mar 15, 2021	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user washid1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					15	Mar 15, 2021	SYSTEM	(\$1,760.00)	
					16	Apr 1, 2021	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user washid1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					16	Apr 1, 2021	SYSTEM	(\$1,760.00)	
					17	Apr 19, 2021	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user washid1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					17	Apr 19, 2021	SYSTEM	(\$1,760.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0390 -							\$0.00	
	0460	POST, SIGNAL 8 FT. OR 2.4 M	Material		14	Mar 1, 2021	SYSTEM	\$1,142.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user washid1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					14	Mar 1, 2021	SYSTEM	(\$1,142.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0460 -	Total						\$0.00	
	0610	BASE, CONCRETE	Material		11	Jan 19, 2021	SYSTEM	\$11,755.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user washid1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					11	Jan 19, 2021	SYSTEM	(\$11,755.80)	
					12	Feb 1, 2021	SYSTEM	\$21,878.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user washid1 overridding Payment Estimate Exception 31 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks											
J6S3258	0610	BASE,	Material	. 7/2-		2021														
		CONCRETE			13	Feb 16, 2021	SYSTEM	\$21,878.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user washid1 overridding Payment Estimate Exception 29 on the current Payment Estimate.											
					13	Feb 16, 2021	SYSTEM	(\$21,878.85)												
					14	Mar 1, 2021	SYSTEM	\$21,878.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user washid1 overridding Payment Estimate Exception 34 on the current Payment Estimate.											
					14	Mar 1, 2021	SYSTEM	(\$21,878.85)												
					15	Mar 15, 2021	SYSTEM	\$21,878.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user washid1 overridding Payment Estimate Exception 29 on the current Payment Estimate.											
					15	Mar 15, 2021	SYSTEM	(\$21,878.85)												
					16	Apr 1, 2021	SYSTEM	\$21,878.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user washid1 overridding Payment Estimate Exception 29 on the current Payment Estimate.											
					16	Apr 1, 2021	SYSTEM	(\$21,878.85)												
					17	Apr 19, 2021	SYSTEM	\$21,878.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user washid1 overridding Payment Estimate Exception 29 on the current Payment Estimate.											
					17	Apr 19, 2021	SYSTEM	(\$21,878.85)												
				- Total				\$0.00												
			Material - To Overrun			otal				\$0.00										
				Overrun	12	Feb 1, 2021	SYSTEM	\$3,063.35	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 34 on the current Payment Estimate. Material Insufficiency Quantity 14.070; Overrun Quantity Balance 1.97.											
						12	Feb 1, 2021	SYSTEM	(\$3,063.35)											
							13	Feb 16, 2021	SYSTEM	(\$3,063.35)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).									
					13	Feb 16, 2021	SYSTEM	\$3,063.35	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 33 on the current Payment Estimate. Material Insufficiency Quantity 14.070; Overrun Quantity Balance 1.97.											
					14	Mar 1, 2021	SYSTEM	(\$3,063.35)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).											
					14	Mar 1, 2021	SYSTEM	\$3,063.35	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 40 on the current Payment Estimate. Material Insufficiency Quantity 14.070; Overrun Quantity Balance 1.97.											
					15	Mar 15, 2021	SYSTEM	(\$3,063.35)	Averaged Price Adjustment from this item on all previous payment estimates of '0.0000' is applied (if non-zero).											
																15	Mar 15, 2021	SYSTEM	\$3,063.35	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 34 on the current Payment Estimate. Material Insufficiency Quantity 14.070; Overrun Quantity Balance 1.97.
					16	Apr 1, 2021	SYSTEM	(\$3,063.35)	Averaged Price Adjustment from this item on all previous payment estimates of '0.0000' is applied (if non-zero).											
													16	Apr 1, 2021	SYSTEM	\$3,063.35	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 34 on the current Payment Estimate. Material Insufficiency Quantity 14.070; Overrun Quantity Balance 1.97.			
											17	Apr 19, 2021	SYSTEM	(\$3,063.35)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).					
					17	Apr 19, 2021	SYSTEM	\$3,063.35	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 40 on the current Payment Estimate. Material Insufficiency Quantity 14.070; Overrun Quantity Balance 1.97.											
				Overrun - T	otal			\$0.00												



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks													
J6S3258	0610 -	Total						\$0.00														
	0640	MISC.	Material		14	Mar 1, 2021	SYSTEM	\$12,615.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user washid1 overridding Payment Estimate Exception 35 on the current Payment Estimate.													
					14	Mar 1, 2021	SYSTEM	(\$12,615.00)														
				- Total				\$0.00														
			Material - To	otal				\$0.00														
	0640 -	Total						\$0.00														
	0670	CONCRETE FOOTINGS, EMBEDDED	Material		8	Dec 2, 2020	SYSTEM	\$20,930.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user washid1 overridding Payment Estimate Exception 29 on the current Payment Estimate.													
					8	Dec 2, 2020	SYSTEM	(\$20,930.00)														
					9	Dec 16, 2020	SYSTEM	\$20,930.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user washid1 overridding Payment Estimate Exception 37 on the current Payment Estimate.													
						9	Dec 16, 2020	SYSTEM	(\$20,930.00)													
						10	Jan 4, 2021	SYSTEM	\$20,930.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user washid1 overridding Payment Estimate Exception 35 on the current Payment Estimate.												
					10	Jan 4, 2021	SYSTEM	(\$20,930.00)														
					11	Jan 19, 2021	SYSTEM	\$20,930.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user washid1 overridding Payment Estimate Exception 35 on the current Payment Estimate.													
					11	Jan 19, 2021	SYSTEM	(\$20,930.00)														
					12	Feb 1, 2021	SYSTEM	\$20,930.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user washid1 overridding Payment Estimate Exception 32 on the current Payment Estimate.													
							12	Feb 1, 2021	SYSTEM	(\$20,930.00)												
					13	Feb 16, 2021	SYSTEM	\$20,930.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user washid1 overridding Payment Estimate Exception 32 on the current Payment Estimate.													
					13	Feb 16, 2021	SYSTEM	(\$20,930.00)														
					14	Mar 1, 2021	SYSTEM	\$20,930.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user washid1 overridding Payment Estimate Exception 36 on the current Payment Estimate.													
										14	Mar 1, 2021	SYSTEM	(\$20,930.00)									
											1	15	15	15	15	1	15	Mar 15, 2021	SYSTEM	\$20,930.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user washid1 overridding Payment Estimate Exception 32 on the current Payment Estimate.	
					15	Mar 15, 2021	SYSTEM	(\$20,930.00)														
														16				16	Apr 1, 2021	SYSTEM	\$20,930.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user washid1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
																		1	16	Apr 1, 2021	SYSTEM	(\$20,930.00)
					17	17	Apr 19, 2021	SYSTEM	\$27,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user washid1 overridding Payment Estimate Exception 32 on the current Payment Estimate.												
					17	Apr 19, 2021	SYSTEM	(\$27,600.00)														
				- Total				\$0.00														
			Material - To	otal				\$0.00														
	0670 -	Total						\$0.00														
	0690	2 IN. PSST	Material		8	Dec 2,	SYSTEM	\$10,932.00	This adjustment offsets the original system-generated Overrun Payment													



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3258	0690	POST - 12 GA.	Material			2020			Estimate Item Adjustment (0018) due to user washid1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					8	Dec 2, 2020	SYSTEM	(\$10,932.00)	
					9	Dec 16, 2020	SYSTEM	\$10,932.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user washid1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
					9	Dec 16, 2020	SYSTEM	(\$10,932.00)	
					10	Jan 4, 2021	SYSTEM	\$10,932.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user washid1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					10	Jan 4, 2021	SYSTEM	(\$10,932.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0690 -	Total						\$0.00	
	0700	2.25 IN. PSST POST - 12 GA.	Material		8	Dec 2, 2020	SYSTEM	\$1,092.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user washid1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					8	Dec 2, 2020	SYSTEM	(\$1,092.00)	
					9	Dec 16, 2020	SYSTEM	\$1,092.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user washid1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
					9	Dec 16, 2020	SYSTEM	(\$1,092.00)	
					10	Jan 4, 2021	SYSTEM	\$1,092.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user washid1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
					10	Jan 4, 2021	SYSTEM	(\$1,092.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0700 -	Total		aterial				\$0.00	
	0710	POST ANCHOR FOR 2 IN. PSST - 7 GA.	Material		8	Dec 2, 2020	SYSTEM	\$7,740.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user washid1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					8	Dec 2, 2020	SYSTEM	(\$7,740.00)	
					9	Dec 16, 2020	SYSTEM	\$7,740.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user washid1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
					9	Dec 16, 2020	SYSTEM	(\$7,740.00)	
					10	Jan 4, 2021	SYSTEM	\$7,740.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user washid1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
					10	Jan 4, 2021	SYSTEM	(\$7,740.00)	
				- Total					
			Material - Total					\$0.00	
	0710 -	- Total						\$0.00	
	0720	2.5 IN. PSST POST - 12 GA.	Material		8	Dec 2, 2020	SYSTEM	\$1,176.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user washid1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					8	Dec 2, 2020	SYSTEM	(\$1,176.00)	
					9	Dec 16, 2020	SYSTEM	\$1,176.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user washid1 overridding Payment Estimate Exception 41 on the current Payment Estimate.
					9	Dec 16, 2020	SYSTEM	(\$1,176.00)	



Drainat	Line	Description	A director cont	Other	Est.	Created	Created	Amount	Remarks
Project	Line	Description	Adjustment Type	Adjustment	Number	Date	By	Amount	Remains
I6S3258	0720	2.5 IN. PSST POST - 12 GA.	Material	Туре	10	Jan 4, 2021	SYSTEM	\$1,176.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user washid1 overridding Payment
					10	Jan 4,	SYSTEM	(\$1,176.00)	Estimate Exception 39 on the current Payment Estimate.
						2021			
				- Total				\$0.00	
	0700		Material - To	otal				\$0.00	
	0720 -							\$0.00	
	0730	POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	Material		8	Dec 2, 2020	SYSTEM	\$720.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user washid1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
		7 07 11			8	Dec 2, 2020	SYSTEM	(\$720.00)	
					9	Dec 16, 2020	SYSTEM	\$720.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user washid1 overridding Payment Estimate Exception 42 on the current Payment Estimate.
					9	Dec 16, 2020	SYSTEM	(\$720.00)	
					10	Jan 4, 2021	SYSTEM	\$720.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user washid1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
					10	Jan 4, 2021	SYSTEM	(\$720.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0730 -	Total						\$0.00	
	0760	MISC. ITS	Material		17	Apr 19, 2021	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user washid1 overridding Payment Estimate Exception 35 on the current Payment Estimate.
					17	Apr 19, 2021	SYSTEM	(\$600.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0760 -	Total						\$0.00	
	0770	MISC. ITS	Material		14	Mar 1, 2021	SYSTEM	\$2,599.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user washid1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
				14		Mar 1, 2021	SYSTEM	(\$2,599.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0770 -	Total						\$0.00	
	0780	MISC. ITS	Material		6	Nov 3, 2020	SYSTEM	\$444.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user washid1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					6	Nov 3, 2020	SYSTEM	(\$444.00)	
					7	Nov 16, 2020	SYSTEM	\$444.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user washid1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					7	Nov 16, 2020	SYSTEM	(\$444.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0780 -	Total						\$0.00	
	0790	MISC. ITS	Material		6	Nov 3, 2020	SYSTEM	\$36.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user washid1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					6	Nov 3, 2020	SYSTEM	(\$36.00)	
					7	Nov 16,	SYSTEM	\$36.00	This adjustment offsets the original system-generated Overrun Payment



ject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
3258	0790	MISC. ITS	Material			2020			Estimate Item Adjustment (0017) due to user washid1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					7	Nov 16, 2020	SYSTEM	(\$36.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0790 -	Total						\$0.00	
	0800	MISC. ITS	Material		6	Nov 3, 2020	SYSTEM	\$36.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user washid1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					6	Nov 3, 2020	SYSTEM	(\$36.00)	
					7	Nov 16, 2020	SYSTEM	\$36.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user washid1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					7	Nov 16, 2020	SYSTEM	(\$36.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0800 -	Total						\$0.00	
	0810	MISC. ITS	Material		17	Apr 19, 2021	SYSTEM	\$800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user washid1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					17	Apr 19, 2021	SYSTEM	(\$800.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0810 -	Total						\$0.00	
	0820	MISC. ITS	Material		17	Apr 19, 2021	SYSTEM	\$455.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user washid1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
					17	Apr 19, 2021	SYSTEM	(\$455.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0820 -	Total						\$0.00	
	0830	MISC. ITS	Material		11	Jan 19, 2021	SYSTEM	\$1,498.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user washid1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					11	Jan 19, 2021	SYSTEM	(\$1,498.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0830 -	Total						\$0.00	
	0840	MISC. ITS	Material		14	Mar 1, 2021	SYSTEM	\$1,021.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user washid1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
					14	Mar 1, 2021	SYSTEM	(\$1,021.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0840 -	Total						\$0.00	
	0860		Material		17	Apr 19, 2021	SYSTEM	\$157.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user washid1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
					17	Apr 19, 2021	SYSTEM	(\$157.50)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	



Apr 21, 2021

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3258	0860 -	Total						\$0.00	
J6S3258 -	- Total						\$317.73		
Overall - Total									