

Pay Estimate Created Date: February 2, 2021

Progress Estimate Number 14		Contract ID 200515 Prime Contractor KCI Co			ry 16, 2021 Original Contract Amount ary 1, 2021 Net Change Order Amount Current Contract Amount				
Approval Date						By User			
February 2, 2021		Generated and Approved (and should be considered Draft) at the Project Office Level by							
February 2, 2021		Reviewe	ed and Approved (and	should be considered Dr	raft) at the Resident Engineer Level by	washas			
February 3, 2021			Reviewe	d and Approved at the Ce	ntral Office Controllers Office Level by	greggd1			
Original Completion Date		Current Completio	n Date Act	ual Completion Date	% of Current Contract Amount Complete				
June 1, 2022 June 1, 2022			!		31.17%				
No Milestones Exist	for Contract								

No Milestones Exist for Contract

Contract Total Pa	ay For Estimate No. 14				
		This Estimate	Previous	To Date	
200515-F15					
	Total Posted Items Pay	\$669,749.17	\$6,642,713.86	\$7,312,463.03	
	Gross Item Adjustments	\$44,117.82	\$197,138.11	\$241,255.93	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	(\$172,776.21)	\$414,986.36	\$242,210.15	
			\$7,254,838.33	\$7,795,929.11	
Contract Total Pa	ayable This Estimate:	\$541,090.78			

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6I2222	0050	2031000	CLASS A EXCAVATION	CUYD	\$15.000	23,036	\$345,540.00
	0060	2036000	COMPACTING EMBANKMENT	CUYD	\$3.000	500	\$1,500.00
	0800	2039901	MISC.STOCK PILE REMOVAL AT OLD 21ST STREET FOR MSD	LS	\$85,000.000	0.25	\$21,250.00
	0300	6049903	MISC.MODOT MANHOLE - ADJUST TO GRADE	LF	\$1,000.000	2.3	\$2,300.00
	1330	8061019	SILT FENCE	LF	\$2.250	255	\$573.75
	2670	7034212	SLAB ON STEEL	SQYD	\$470.000	37	\$17,390.00
	5013	7011105	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	LF	\$567.750	202.8	\$115,139.70
	5014	7011204	ROCK SOCKETS (3 FT 0 IN. DIA.)	LF	\$917.100	76.7	\$70,341.57
	5015	7101000	REINFORCING STEEL (EPOXY COATED)	LB	\$1.490	24,760	\$36,892.40
	5016	7011300	VIDEO CAMERA INSPECTION	EA	\$577.500	6	\$3,465.00
	5017	7011400	FOUNDATION INSPECTION HOLES	LF	\$136.500	185.1	\$25,266.15
	5018	7011600	SONIC LOGGING TESTING	EA	\$4,593.000	6	\$27,558.00
	5019	7061070	MECHANICAL BAR SPLICE	EA	\$140.700	18	\$2,532.60
Project J6I22	22 - Total						\$669,749.17
Overall - Tota	ıl						\$669,749.17

Contract Adjustments This Estimate

Adj Type	Entered By	Comments	Time Units	Rate	Amount
OTHROther Contract Adjustment		22nd Street bridge VE consultant engineering services			\$12,705.06
OTHROther Contract Adjustment		22nd Street VE Drilled Shaft & Rock Socket replenishment			(\$185,481.27)

Overall - Total These amounts are listed in the Incentive, Disincentive, Liquidated Damages or Other Contract Adjustments (\$172,776.21)

ı	1 1 to 1 to 1	14	A -11-	- 4	-4-	T1-1-	F - 45	-4-
							Estim	

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6I2222	0050	CLASS A EXCAVATION	Price		Reference Item Price Adjustment Index	23,036	\$0.13	\$3,086.82

Page 1 of 37 Revision 4/1/2020



Pay Estimate Created Date: February 2, 2021

Progress Estimate Number
14 Contract ID 200515-F15 Pay Period Start January 16, 2021 Original Contract Amount \$24,269,745.00 Prime Contractor KCI Construction Company Pay Period End February 1, 2021 Net Change Order Amount (\$809,800.53) Current Contract Amount \$23,459,944.47

ect per	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
22					Adjustment Type applied is FUEL			
	0060	COMPACTING EMBANKMENT	Material			-65,830	\$3.00	(\$197,490.00
	0060	COMPACTING EMBANKMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate.	65,830	\$3.00	\$197,490.00
	0210	TYPE A2 SHOULDER	Material			-413.36	\$36.00	(\$14,880.96
	0210	TYPE A2 SHOULDER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user hillt5 overridding Payment Estimate Exception 6 on the current Payment Estimate.	413.36	\$36.00	\$14,880.96
	0675	CONCRETE TRAFFIC BARRIER, TYPE C	Material			-461	\$145.00	(\$66,845.00
	0675	CONCRETE TRAFFIC BARRIER, TYPE C	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user hillt5 overridding Payment Estimate Exception 13 on the current Payment Estimate.	461	\$145.00	\$66,845.00
	0690	CONCRETE TRAFFIC BARRIER, TYPE D (RETAINING WALL)	Material			-1,745	\$85.00	(\$148,325.00
	0690	CONCRETE TRAFFIC BARRIER, TYPE D (RETAINING WALL)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user hillt5 overridding Payment Estimate Exception 16 on the current Payment Estimate.	1,745	\$85.00	\$148,325.00
	0990	MISC.	Material			-2,401	\$15.50	(\$37,215.50
	0990	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 18 on the current Payment Estimate.	2,401	\$15.50	\$37,215.50
	1050	MISC.	Material			-952	\$25.00	(\$23,800.00
	1050	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user hillt5 overridding Payment Estimate Exception 31 on the current Payment Estimate.	952	\$25.00	\$23,800.00
	1090	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material			-3,394	\$60.00	(\$203,640.00
	1090	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user hillt5 overridding Payment Estimate Exception 49 on the current Payment Estimate.	3,394	\$60.00	\$203,640.00
	1100	SELECT GRANULAR BACKFILL FOR STRUCTURAL SYSTEMS	Material			-8,552	\$30.00	(\$256,560.00
	1100	SELECT GRANULAR BACKFILL FOR STRUCTURAL SYSTEMS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user hillt5 overridding Payment Estimate Exception 52 on the current Payment Estimate.	8,552	\$30.00	\$256,560.00
	1210	MISC.	Material			-5	\$350.00	(\$1,750.00
	1210	MISC.	Material		This adjustment offsets the original system-	5	\$350.00	\$1,750.00

Revision 4/1/2020 Page 2 of 37



Pay Estimate Created Date: February 2, 2021

Progress Estimate Number
14 Contract ID 200515-F15 Pay Period Start January 16, 2021 Original Contract Amount \$24,269,745.00
Prime Contractor KCI Construction Company Pay Period End February 1, 2021 Net Change Order Amount (\$809,800.53)
Current Contract Amount \$23,459,944.47

ect ber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
222					generated Material Payment Estimate Item Adjustment (0004) due to user hillt5 overridding Payment Estimate Exception 53 on the current Payment Estimate.			
	1290	ROCK DITCH CHECK	Material			-24	\$10.50	(\$252.00
	1290	ROCK DITCH CHECK	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 55 on the current Payment Estimate.	24	\$10.50	\$252.00
	1490	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material			-2,629.87	\$6.50	(\$17,094.16
	1490	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user hillt5 overridding Payment Estimate Exception 2 on the current Payment Estimate.	2,629.87	\$6.50	\$17,094.16
	1510	CONCRETE PAVEMENT (9 IN. NON-REINFORCED 15 FT. JOINTS)	Material			-1,259.3	\$54.00	(\$68,002.20
	1510	CONCRETE PAVEMENT (9 IN. NON-REINFORCED 15 FT. JOINTS)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate.	1,259.3	\$54.00	\$68,002.20
	1550	TYPE A2 SHOULDER	Material			-865.37	\$35.00	(\$30,287.95
	1550	TYPE A2 SHOULDER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0016) due to user hillt5 overridding Payment Estimate Exception 8 on the current Payment Estimate.	865.37	\$35.00	\$30,287.95
	1560	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	Material			-225	\$15.00	(\$3,375.00
	1560	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0017) due to user hillt5 overridding Payment Estimate Exception 10 on the current Payment Estimate.	225	\$15.00	\$3,375.00
	1780	MISC.	Material			-1	\$16,605.00	(\$16,605.00
	1780	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user hillt5 overridding Payment Estimate Exception 56 on the current Payment Estimate.	1	\$16,605.00	\$16,605.00
	2210	CONCRETE FOOTINGS, BOLT DOWN	Material			-12.5	\$1,200.00	(\$15,000.00
	2210	CONCRETE FOOTINGS, BOLT DOWN	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user hillt5 overridding Payment Estimate Exception 57 on the current Payment Estimate.	12.5	\$1,200.00	\$15,000.00
	2670	SLAB ON STEEL	Material			-37	\$470.00	(\$17,390.00
	2670	SLAB ON STEEL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0018) due to user hillt5 overridding Payment Estimate Exception 32 on the current Payment Estimate.	37	\$470.00	\$17,390.00
	2790	STRIP SEAL EXPANSION	Construction		Payment Estimate Item Adjustment generated			\$9,471.00

Revision 4/1/2020 Page 3 of 37



Pay Estimate Created Date: February 2, 2021

Progress Estimate Number
14 Contract ID 200515-F15 Pay Period Start January 16, 2021 Original Contract Amount \$24,269,745.00 Pay Period End February 1, 2021 Net Change Order Amount \$24,269,745.00 Current Contract Amount \$23,459,944.47

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6I2222		JOINT SYSTEM	Stockpile		Stockpile Transaction			
	2940	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material			-8,672	\$62.50	(\$542,000.00)
	2940	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0020) due to user hillt5 overridding Payment Estimate Exception 50 on the current Payment Estimate.	8,672	\$62.50	\$542,000.00
	3760	MISC.	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			\$26,016.00
	3830	STRIP SEAL EXPANSION JOINT SYSTEM	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			\$5,544.00
	5013	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	Material			-202.8	\$567.75	(\$115,139.70
	5013	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0023) due to user hillt5 overridding Payment Estimate Exception 19 on the current Payment Estimate.	202.8	\$567.75	\$115,139.70
	5014	ROCK SOCKETS (3 FT 0 IN. DIA.)	Material			-76.7	\$917.10	(\$70,341.57
	5014	ROCK SOCKETS (3 FT 0 IN. DIA.)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0025) due to user hillt5 overridding Payment Estimate Exception 26 on the current Payment Estimate.	76.7	\$917.10	\$70,341.57
	5015	REINFORCING STEEL (EPOXY COATED)	Material			-24,760	\$1.49	(\$36,892.40
	5015	REINFORCING STEEL (EPOXY COATED)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0026) due to user hillt5 overridding Payment Estimate Exception 42 on the current Payment Estimate.	24,760	\$1.49	\$36,892.40
	5019	MECHANICAL BAR SPLICE	Material			-18	\$140.70	(\$2,532.60
	5019	MECHANICAL BAR SPLICE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0024) due to user hillt5 overridding Payment Estimate Exception 41 on the current Payment Estimate.	18	\$140.70	\$2,532.60
otal								\$44,117.82

Revision 4/1/2020 Page 4 of 37



	Contract Project Information									
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work					
J6I2222	I-64-1 (61)	Interchange improvements	I-64	ST LOUIS CITY	from west of Ewing Ave to east of 21st Street					

Totals by Jo	ob Numbers			
J6I2222		This Estimate	Previous	To Date
	Posted Item Pay Gross Item Adjustments	\$669,749.17 \$44,117.82	\$6,642,713.86 \$197,138.11	\$7,312,463.03 \$241,255.93
	Gross Item Pay	\$713,866.99	\$6,839,851.97	\$7,553,718.96
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damages	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	(\$172,776.21)	\$414,986.36	\$242,210.15

Revision 4/1/2020 Page 5 of 37



Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			1
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 2036000, Project Item Line Number 0060, Material Set 203600096, Material 0200XXCS - Compacted Soil for Subgrade or Embankment, Acceptance Action Generic 0200XXCS is insufficient.	Plan quantity has not been reached/installed at this time	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 3040506, Project Item Line Number 1490, Material Set 304050696, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Aggregate material testing needs to be reported	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 5021309, Project Item Line Number 1510, Material Set 502130996, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Aggregate material testing needs to be reported	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 5021309, Project Item Line Number 1510, Material Set 502130996, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Aggregate material testing needs to be reported	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 5021309, Project Item Line Number 1510, Material Set 502130996, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Waiting on PAL	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 5021340, Project Item Line Number 0210, Material Set 502134096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Aggregate material testing needs to be reported	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 5021340, Project Item Line Number 0210, Material Set 502134096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Aggregate material testing needs to be reported	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 5021340, Project Item Line Number 1550, Material Set 502134096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Aggregate material testing needs to be reported	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 5021340, Project Item Line Number 1550, Material Set 502134096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Aggregate material testing needs to be reported	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 6092011, Project Item Line Number 1560, Material Set 609201196, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Aggregate material testing needs to be reported	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 6092011, Project Item Line Number 1560, Material Set 609201196, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Aggregate material testing needs to be reported	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 6092011, Project Item Line Number 1560, Material Set 609201196, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Waiting on PAL	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 6173000, Project Item Line Number 0675, Material Set 617300096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Plan quantity has not been reached/installed at this time	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 6173000, Project Item Line Number 0675, Material Set 617300096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Aggregate material testing needs to be reported	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 6173000, Project Item Line Number 0675, Material Set 617300096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Aggregate material testing needs to be reported	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 6173102, Project Item Line Number 0690, Material Set 617310296, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Aggregate material testing needs to be reported	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 6173102, Project Item Line Number 0690, Material Set 617310296, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Aggregate material testing needs to be reported	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 6249905, Project Item Line Number 0990, Material Set 624990596, Material 3099XX - See Remarks for Description of Material, Acceptance Action Generic 3099XX is insufficient.	Aggregate material testing needs to be reported	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011105, Project Item Line Number 5013, Material Set 701110596, Material 0701PLCA - Casing for Drilled Shafts, Acceptance Action Generic 0701PLCA is insufficient.	material certification need to be reviewed/approved	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7011105, Project Item Line Number 5013, Material Set 701110596, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Aggregate material testing needs to be reported	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7011105, Project Item Line Number 5013, Material Set 701110596, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Aggregate material testing needs to be reported	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011105, Project Item Line Number 5013, Material Set 701110596, Material 0701PLCSLT - Drilled Shaft CSL steel pipe, Acceptance Action Generic 0701PLCSLT is insufficient.	material certification need to be reviewed/approved	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011105, Project Item Line Number 5013, Material Set 701110596, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Aggregate material testing needs to be reported	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011105, Project Item Line Number 5013, Material Set 701110596, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action	Waiting on 28 day break	hillt5	Overridden

Revision 4/1/2020 Page 6 of 37



Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Generic 0501CCB2.A is insufficient.		2,	
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7011105, Project Item Line Number 5013, Material Set 701110596, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	Aggregate material testing needs to be reported	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011204, Project Item Line Number 5014, Material Set 701120496, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Aggregate material testing needs to be reported	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011204, Project Item Line Number 5014, Material Set 701120496, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	Aggregate material testing needs to be reported	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011204, Project Item Line Number 5014, Material Set 701120496, Material 100510OPTLD1 - PCCP 1" Max LS/DO, Acceptance Action Generic 100510OPTLD1 is insufficient.	Aggregate material testing needs to be reported	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 7011204, Project Item Line Number 5014, Material Set 701120496, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Aggregate material testing needs to be reported	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011204, Project Item Line Number 5014, Material Set 701120496, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Aggregate material testing needs to be reported	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7019903, Project Item Line Number 1050, Material Set 7019903, Material 1010SGBF - Select Gran Backfill for Structural Sys, Acceptance Action Generic 1010SGBF is insufficient.	Aggregate material testing needs to be reported	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7034212, Project Item Line Number 2670, Material Set 703421296, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Aggregate material testing needs to be reported	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7034212, Project Item Line Number 2670, Material Set 703421296, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Aggregate material testing needs to be reported	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7034212, Project Item Line Number 2670, Material Set 703421296, Material 0705DPRCPS30 - Prestress Conc Deck Panel 3" (75 mm), Acceptance Action Generic 0705DPRCPS30 is insufficient.	material certification need to be reviewed/approved	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7034212, Project Item Line Number 2670, Material Set 703421296, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Waiting on 28 day break	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7034212, Project Item Line Number 2670, Material Set 703421296, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Waiting on PAL	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7034212, Project Item Line Number 2670, Material Set 703421296, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Waiting on PAL	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7034212, Project Item Line Number 2670, Material Set 703421296, Material 1036RSDFEC42M22 - Rein Steel EC No. 7/M22 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Waiting on PAL	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7034212, Project Item Line Number 2670, Material Set 703421296, Material 1036RSDFPL42M19 - Reinforcing Steel No. 6/M19 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Waiting on PAL	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7034212, Project Item Line Number 2670, Material Set 703421296, Material 1036RSDFPL42M25 - Reinforcing Steel No. 8/M25 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Waiting on PAL	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7061070, Project Item Line Number 5019, Material Set 706107096, Material 1036RSMBS - Mechanical Bar Splice for Reinf Steel @, Acceptance Action Generic ReinforcingMisc is insufficient.	Waiting on PAL	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7101000, Project Item Line Number 5015, Material Set 710100096, Material 1036RSDFEC42M16 - Rein Steel EC No. 5/M16 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Waiting on PAL	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7101000, Project Item Line Number 5015, Material Set 710100096, Material 1036RSDFEC42M25 - Rein Steel EC No. 8/M25 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Waiting on PAL	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7101000, Project Item Line Number 5015, Material Set 710100096, Material 1036RSDFEC42M22 - Rein Steel EC No. 7/M22 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Waiting on PAL	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7101000, Project Item Line Number 5015, Material Set 710100096, Material 1036RSDFEC42M19 - Rein Steel EC No. 6/M19 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Waiting on PAL	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7101000, Project Item Line Number 5015, Material Set 710100096, Material 1036RSDFEC42M29 - Rein Steel EC No. 9/M29 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Waiting on PAL	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7101000, Project Item Line Number 5015, Material Set 710100096, Material 1036RSDFEC42M13 - Rein Steel EC No. 4/M13 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Waiting on PAL	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7101000, Project Item Line Number	1036RSSRECAB	hillt5	Overridden

Revision 4/1/2020 Page 7 of 37



Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
5015, Material Set 710100096, Material 1036RSSRECAB - Epoxy Ctd Sprl Stl Rein for Anch Bolts @, Acceptance Action Generic ReinforcingMisc is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7201000, Project Item Line Number 1090, Material Set 720100096, Material 1010SGBF - Select Gran Backfill for Structural Sys, Acceptance Action Generic 1010SGBF is insufficient.	Aggregate material testing needs to be reported	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7201000, Project Item Line Number 2940, Material Set 720100096, Material 1010SGBF - Select Gran Backfill for Structural Sys, Acceptance Action Generic 1010SGBF is insufficient.	Aggregate material testing needs to be reported	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7201000, Project Item Line Number 2940, Material Set 720100096, Material 0720MSEW - MSE Wall System -Bridge Approved Design, Acceptance Action Generic 0720MSEW is insufficient.	MSE wall material certification need to be reviewed/approved	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7201200, Project Item Line Number 1100, Material Set 720120096, Material 1010SGBF - Select Gran Backfill for Structural Sys, Acceptance Action Generic 1010SGBF is insufficient.	Aggregate material testing needs to be reported	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 7319913, Project Item Line Number 1210, Material Set 731991396, Material 1033DIRCPK - Precast Conc Drop Inlet, Acceptance Action Generic 1033DIRCPK is insufficient.	Waiting on shipping report	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7319913, Project Item Line Number 1200, Material Set 731991396, Material 1033DIRCPK - Precast Conc Drop Inlet, Acceptance Action Generic 1033DIRCPK is insufficient.	Waiting on shipping report	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 8061005, Project Item Line Number 1290, Material Set 806100596, Material 0806TEC - Temporary Erosion Control, Acceptance Action Generic 0806TEC is insufficient.	Waiting on shipping report	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 9019901, Project Item Line Number 1780, Material Set 9019901, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient.	Plan quantity has not been reached/installed at this time	hillt5	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 9031020, Project Item Line Number 2210, Material Set 903102096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Plan quantity has not been reached/installed at this time	hillt5	Overridden

Revision 4/1/2020 Page 8 of 37



Total Paid / All Items / All Estimates (Including this Estimate)

Contract CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTEI To Date (See report generated date)
515-F15	J6I2222	0001	0010	2013000	CLEARING AND GRUBBING	2.00	0.00	2.00	ACRE	2.00	\$25,000.00	\$50,000.00
		0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.42	\$600,000.00	\$252,000.0
		0001	0025	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	155.00	0.00	155.00	SQFT	135.00	\$140.50	\$18,967.5
		0001	0040	2029901	MISC.REMOVAL OF ACM CONDUIT SYSTEM - TELEPHONE	1.00	0.00	1.00	LS	0.00	\$13,500.00	\$0.0
		0001	0045	2029903	MISC.MISCELLANEOUS ACM REMOVAL	80.00	0.00	80.00	LF	0.00	\$48.00	\$0.0
		0001	0050	2031000	CLASS A EXCAVATION	153,414.00	0.00	153,414.00	CUYD	69,942.00	\$15.00	\$1,049,130.0
		0001	0060	2036000	COMPACTING EMBANKMENT	106,637.00	0.00	106,637.00	CUYD	65,830.00	\$3.00	\$197,490.0
		0001	0070	2037075	COMPACTING IN CUT	45.00	0.00	45.00	STA	0.00	\$1.00	\$0.0
		0001	0080	2039901	MISC.STOCK PILE REMOVAL AT OLD 21ST STREET FOR MSD	1.00	0.00	1.00	LS	0.25	\$85,000.00	\$21,250.0
		0001	0090	2039907	MISC.Lightweight Fill	16,413.00	0.00	16,413.00	CUYD	0.00	\$61.50	\$0.0
		0001	0100	2042010	SETTLEMENT GAUGE	10.00	0.00	10.00	EA	10.00	\$1,500.00	\$15,000.0
		0001	0110	2043010	PORE PRESSURE MEASURING DEVICE	3.00	0.00	3.00	EA	3.00	\$4,000.00	\$12,000.0
		0001	0120	2063000	CLASS 3 EXCAVATION	2,716.00	0.00	2,716.00	CUYD	2,299.00	\$15.00	\$34,485.0
		0001	0130	2071000	LINEAR GRADING CLASS 1	11.00	0.00	11.00	STA	0.00	\$800.00	\$0.0
		0001	0140	3040143	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	1,152.00	0.00	1,152.00	SQYD	0.00	\$11.00	\$0.0
		0001	0150	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	72.00	0.00	72.00	SQYD	0.00	\$23.00	\$0.0
		0001	0160	3105003	GRAVEL (A) OR CRUSHED STONE (B)	540.00	0.00	540.00	SQYD	0.00	\$12.00	\$0.0
		0001	0170	4011207	BITUMINOUS PAVEMENT MIXTURE PG70-22, (BP-1)	1,950.80	0.00	1,950.80	TONS	0.00	\$77.75	\$0.0
		0001	0180	4030109	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125CLP MIX)	376.20	0.00	376.20	TONS	0.00	\$125.00	\$0.0
		0001	0190	4071005	TACK COAT	1,660.00	0.00	1,660.00	GAL	0.00	\$3.50	\$0.0
		0001	0200	5021108	CONCRETE PAVEMENT (8 IN. NON-REINF)	366.30	0.00	366.30	SQYD	0.00	\$49.00	\$0.0
		0001	0210	5021340	TYPE A2 SHOULDER	1,563.20	0.00	1,563.20	SQYD	413.36	\$36.00	\$14,880.9
		0001	0220	5041000	CONCRETE APPROACH PAVEMENT	105.20	0.00	105.20	SQYD	0.00	\$150.00	\$0.0
		0001	0230	6039901	WATER	1.00	0.00	1.00	LS	1.00	\$30,000.00	\$30,000.0
		0001	0240	6039901	WATER	1.00	0.00	1.00	LS	0.00	\$12,000.00	\$0.0
		0001	0250	6039903	WATER	20.00	0.00	20.00	LF	20.00	\$2,000.00	\$40,000.0
		0001	0260	6039903	WATER	150.00	0.00	150.00	LF	150.00	\$2,000.00	\$300,000.0
		0001	0270	6039903	WATER	570.00	0.00	570.00	LF	390.20	\$400.00	\$156,080.0
		0001	0280	6039903	WATER	100.00	0.00	100.00	LF	100.00	\$400.00	\$40,000.0
		0001	0290	6049901	MISC.INSPECTION OF 9X7 CONCRETE ARCH SEWER	1.00	0.00	1.00	LS	0.00	\$6,000.00	\$0.0
		0001	0300	6049903	MISC.MODOT MANHOLE - ADJUST TO GRADE	24.00	0.00	24.00	LF	24.00	\$1,000.00	\$24,000.0
		0001	0310	6049903	MISC.MSD MANHOLE - ADJUST TO GRADE, 5' TO 10' RANGE	25.00	0.00	25.00	LF	15.40	\$1,000.00	\$15,400.0
		0001	0320	6049903	MISC.MSD MANHOLE - ADJUST TO GRADE, 10' TO 15' RANGE	23.00	0.00	23.00	LF	0.00	\$1,000.00	\$0.0
		0001	0330	6049903	MISC MSD MANHOLE - ADJUST TO GRADE. 15' TO 20' RANGE	37.00	0.00	37.00	LF	18.20	\$1.000.00	\$18,200.0
		0001	0340	6049903	MISC.MSD MANHOLE - ADJUST TO GRADE, 25' TO 30' RANGE	28.00	0.00	28.00	LF	0.00	\$1,000.00	\$0.0
		0001	0350	6071012A		586.00	0.00	586.00	LF	0.00	\$28.00	\$0.0
		0001	0360	6071040	DRIVE GATE (CHAIN-LINK)	2.00	0.00	2.00	EA	0.00	\$1,200.00	\$0.0
		0001	0370	6071050	CHAIN-LINK FENCE (RETAINING WALLS)	1,800.00	0.00	1,800.00	LF	0.00	\$24.00	\$0.0
		0001	0380	6071102	MODIFIED CONCRETE GUTTER TYPE B	2,038.00	0.00	2.038.00	LF	0.00	\$34.00	\$0.0
			0390	6081012	TRUNCATED DOMES	60.00	0.00	60.00	SQFT	0.00	\$35.00	\$0.0
		0001										
		0001	0400	6083006	6 IN. CONCRETE MEDIAN STRIP PAVED APPROACH, 8 IN.	529.80	0.00	529.80	SQYD	0.00	\$100.00 \$125.00	\$0.0
		0001		6085008		72.30		72.30		0.00		\$0.0
		0001	0420	6086004	CONCRETE SIDEWALK, 4 IN.	1,152.10	0.00	1,152.10	SQYD	0.00	\$51.00	\$0.0
		0001	0430	6086007	CONCRETE SIDEWALK, 7 IN.	15.30	0.00	15.30	SQYD	0.00	\$65.00	\$0.0
		0001	0440	6089902	MISC.ADA CURB RAMP	16.00	0.00	16.00	EA	0.00	\$3,550.00	\$0.0
		0001	0450	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	301.00	0.00	301.00	LF	0.00	\$45.00	\$0.0
		0001	0460	6091042	CONCRETE GUTTER TYPE B	2,007.00	0.00	2,007.00	LF	0.00	\$30.00	\$0.0

Revision 4/1/2020 Page 9 of 37



Total Paid / All Items / All Estimates (Including this Estimate)

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200515-F15	J6I2222	0001	0470	6091060	PAVED DITCH	210.30	0.00	210.30	SQYD	0.00	\$81.00	\$0.00
		0001	0480	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	203.00	0.00	203.00	LF	0.00	\$15.00	\$0.00
		0001	0490	6096020	FURNISHING TYPE 2 ROCK DITCH LINER	24.00	0.00	24.00	CUYD	0.00	\$100.00	\$0.00
		0001	0500	6096042	PLACING TYPE 2 ROCK DITCH LINER	24.00	0.00	24.00	CUYD	0.00	\$100.00	\$0.00
		0001	0510	6097000	ROCK LINING	2.00	0.00	2.00	CUYD	0.00	\$1,000.00	\$0.00
		0001	0515	6099903	MISC.MODIFIED INTEGRAL CURB (2 IN. HEIGHT) TYPE A	320.00	0.00	320.00	LF	0.00	\$50.00	\$0.00
		0001	0520	6113020	FURNISHING TYPE 2 ROCK BLANKET	567.00	0.00	567.00	CUYD	0.00	\$48.00	\$0.00
		0001	0530	6113040	PLACING TYPE 2 ROCK BLANKET	567.00	0.00	567.00	CUYD	0.00	\$21.00	\$0.00
		0001	0540	6116010A	SLOPE PROTECTION	1.00	0.00	1.00	SQYD	0.00	\$300.00	\$0.00
		0001	0550	6119907	MISC.Furnishing Modified Rock Blanket	1,151.00	0.00	1,151.00	CUYD	0.00	\$50.00	\$0.00
		0001	0560	6119907	MISC.Placing Modified Rock Blanket	1,151.00	0.00	1,151.00	CUYD	0.00	\$21.00	\$0.00
		0001	0570	6122012	IMPACT ATTENUATOR 55 MPH (SAND BARREL ARRAY)	5.00	0.00	5.00	EA	2.00	\$2,823.00	\$5,646.00
		0001	0580	6122020	REPLACEMENT SAND BARREL	12.00	0.00	12.00	EA	0.00	\$431.00	\$0.00
		0001	0590	6122030	IMPACT ATTENUATOR (RELOCATION)	9.00	0.00	9.00	EA	0.00	\$877.00	\$0.00
		0001	0600	6133020	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	148.50	0.00	148.50	TONS	0.00	\$62.00	\$0.00
		0001	0610	6133021	REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	528.50	0.00	528.50	SQYD	0.00	\$58.75	\$0.00
		0001	0620	6141024	GRATE AND BEARING PLATE (5 FT. X 3 FT. OR 1524 MM X 914 MM)	10.00	0.00	10.00	EA	4.00	\$1,400.00	\$5,600.00
		0001	0630	6141120	CURVED VANE GRATE AND FRAME (2 FT. X 2 FT. OR 600MM X	72.00	-72.00	0.00	EA	0.00	\$700.00	\$0.00
		0001	0640	6149902	600MM) MISC.Parallel Grate and Bearing Plate (2 FT.x2FT.)	67.00	-57.00	10.00	EA	1.00	\$700.00	\$700.00
		0001	0650	6169901	MISC.TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.50	\$465,000.00	\$232,500.00
		0001	0660	6169902	MISC.MSD Manhole Frame and Cover	17.00	-17.00	0.00	EA	0.00	\$400.00	\$0.00
		0001	0670	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN	8.00	0.00	8.00	EA	5.00	\$3,500.00	\$17,500.00
		0001	0675	6173000	(CONTRACTOR FURNISHED AND RETAINED) CONCRETE TRAFFIC BARRIER, TYPE C	254.00	357.00	611.00	LF	461.00	\$145.00	\$66,845.00
		0001	0680	6173100	CONCRETE TRAFFIC BARRIER, TYPE D	1,787.00	0.00	1,787.00	LF	0.00	\$90.00	\$0.00
		0001	0690	6173102	CONCRETE TRAFFIC BARRIER, TYPE D (RETAINING WALL)	2,413.00	0.00	2,413.00	LF	1,745.00	\$85.00	\$148,325.00
		0001	0700	6173103	CONCRETE TRAFFIC BARRIER, TYPE D (MOMENT SLAB)	440.00	0.00	440.00	LF	0.00	\$110.00	\$0.00
		0001	0710	6173600D		2,488.00	0.00	2,488.00	LF	2,000.50	\$25.90	\$51,812.95
					RETAINED							
		0001	0720	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	4,013.00	0.00	4,013.00	LF	212.50	\$11.50	\$2,443.75
		0001	0730	6179903	MISC.MODIFIED BARRIER WALL	315.00	0.00	315.00	LF	0.00	\$300.00	\$0.00
		0001	0740	6181000	MOBILIZATION	1.00	-1.00	0.00	LS		\$2,269,999.84	\$0.00
		0001	0741	6181000	MOBILIZATION	0.00	1.00	1.00	LS		\$2,162,092.84	\$1,621,569.63
		0001	0750	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	2.00	0.00	2.00	EA	0.00	\$600.00	\$0.00
		0001	0760	6189901	MISC.TEMPORARY RAILROAD CROSSING	1.00	0.00	1.00	LS	0.00	\$30,000.00	\$0.00
		0001	0765	6189916	MISC.ACCELERATING THE COMPLETION OF WORK REQUIRING RAILROAD FLAGGERS (INCENTIVE/DISINCENTIVE CLAUSE)	1,000.00	0.00	1,000.00	DLR	0.00	\$0.00	\$0.00
		0001	0770	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	505.00	0.00	505.00	LF	0.00	\$25.00	\$0.00
		0001	0780	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	19.00	0.00	19.00	EA	0.00	\$320.00	\$0.00
		0001	0790	6200027	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT	7.00	0.00	7.00	EA	0.00	\$450.00	\$0.00
		0001	0800	6200030	PREFORMED THERMOPLASTIC PAVEMENT MARKING, WORD (ONLY)	9.00	0.00	9.00	EA	0.00	\$450.00	\$0.00
		0001	0810	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	114.00	0.00	114.00	EA	0.00	\$200.00	\$0.00
		0001	0820	6200042	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	14.00	0.00	14.00	EA	0.00	\$50.00	\$0.00
		0001	0830	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	21,905.00	0.00	21,905.00	LF	0.00	\$0.50	\$0.00
		0001	0840	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	12,373.00	0.00	12,373.00	LF	0.00	\$0.50	\$0.00
		0001	0850	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	4,999.00	0.00	4,999.00	LF	0.00	\$1.00	\$0.00

Revision 4/1/2020 Page 10 of 37



Total Paid / All Items / All Estimates (Including this Estimate)

Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved	Unit Price	Total Value POSTE To Date (See repo generated date)
00515-F15	J6I2222	0001	0860	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING	9,364.00	0.00	9,364.00	LF	Qty 0.00	\$0.50	\$0.0
		0001	0870	6206001C	PAINT, TYPE P BEADS 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT. TYPE P BEADS	3,485.00	0.00	3,485.00	LF	0.00	\$0.50	\$0.0
		0001	0880	6206124A		91.00	0.00	91.00	LF	0.00	\$10.00	\$0.0
		0001	0890	6206125A	24 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	84.00	0.00	84.00	LF	0.00	\$10.00	\$0.0
		0001	0900	6207001	PAVEMENT MARKING REMOVAL	7,291.00	0.00	7,291.00	LF	0.00	\$1.00	\$0.
		0001	0910	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	56.00	0.00	56.00	EA	0.00	\$50.00	\$0.
		0001	0920	6209902	MISC.ISLAND TUBULAR MARKER	8.00	0.00	8.00	EA	0.00	\$110.00	\$0.
		0001	0930	6209902	MISC.PREFORMED THERMOPLASTIC PAVEMENT MARKING, LANE REDUCTION ARROW	8.00	0.00	8.00	EA	0.00	\$2,000.00	\$0.
		0001	0940	6209902	MISC.TIER TWO INLAID PAVEMENT MARKER SYSTEM	8.00	0.00	8.00	EA	0.00	\$4,475.00	\$0.
		0001	0950	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	2,356.00	0.00	2,356.00	SQYD	0.00	\$6.75	\$0.
		0001	0960	6221003	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (GREATER THAN 3 IN. THICK)	10,196.00	0.00	10,196.00	SQYD	0.00	\$3.85	\$0.
		0001	0970	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	150.00	0.00	150.00	SQYD	0.00	\$13.50	\$0
		0001	0980	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	3,917.00	0.00	3,917.00	SQYD	0.00	\$3.00	\$0
		0001	0990	6249905	MISC.Miscellaneous Granular Drainage Blanket	2,115.00	286.00	2,401.00	SQYD	2,401.00	\$15.50	\$37,215
		0001	1000	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.40	\$125,000.00	\$50,000
		0001	1010	7011105	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	30.00	0.00	30.00	LF	0.00	\$415.00	\$0
		0001	1020	7011107	DRILLED SHAFTS (4 FT. 6 IN. DIA.)	39.00	0.00	39.00	LF	0.00	\$415.00	\$0
		0001	1030	7011207	ROCK SOCKETS (4 FT 6 IN. DIA.)	6.00	0.00	6.00	LF	0.00	\$415.00	\$0
		0001	1040	7011600	SONIC LOGGING TESTING	1.00	0.00	1.00	EA	0.00	\$1,000.00	\$0
		0001	1050	7019903	MISC.Miscellaneous Stone Columns	6,535.00	-5,583.00	952.00	LF	952.00	\$25.00	\$23,800
		0001	1060	7033009	AESTHETIC CONCRETE STAIN	1.00	0.00	1.00	LS	0.00	\$6,110.88	\$0
		0001	1080	7061000	REINFORCING STEEL	5,740.00	0.00	5,740.00	LB	0.00	\$1.60	\$0
		0001	1090	7201000	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	3,394.00	0.00	3,394.00	SQFT	3,394.00	\$60.00	\$203,640
		0001	1100	7201200	SELECT GRANULAR BACKFILL FOR STRUCTURAL SYSTEMS	12,416.00	0.00	12,416.00	CUYD	8,552.00	\$30.00	\$256,560
		0001	1110	7261015	15 IN. PIPE GROUP A	3,631.00	0.00	3,631.00	LF	1,266.00	\$70.00	\$88,620
		0001	1120	7261018	18 IN. PIPE GROUP A	1,252.00	0.00	1,252.00	LF	375.00	\$80.00	\$30,000
		0001	1130	7261024	24 IN. PIPE GROUP A	118.00	0.00	118.00	LF	0.00	\$135.00	\$0
		0001	1140	7261030	30 IN. PIPE GROUP A	298.00	0.00	298.00	LF	298.00	\$250.00	\$74,500
		0001	1150	7261036	36 IN. PIPE GROUP A	54.00	0.00	54.00	LF	54.00	\$400.00	\$21,600
		0001	1160	7279901	MISC.MSD SPECIAL DRAINAGE STRUCTURE #"301"	1.00	0.00	1.00	LS	1.00	\$55,000.00	\$55,000
		0001	1170	7311022	PRECAST CONCRETE DROP INLET 2 FT X 2 FT	57.00	0.00	57.00	FT	21.91	\$350.00	\$7,668
		0001	1180	7311042	PRECAST CONCRETE DROP INLET 4 FT X 2 FT	178.00	0.00	178.00	FT	77.00	\$450.00	\$34,650
		0001	1190	7311053	PRECAST CONCRETE DROP INLET 5 FT X 3 FT	56.00	0.00	56.00	FT	36.00	\$650.00	\$23,400
		0001	1200	7319913	MISC.MSD Standard 60" Manhole	56.00	0.00	56.00	FT	56.00	\$510.00	\$28,560
		0001	1210	7319913	MISC.MSD Standard Line 48" Manhole	76.00	0.00	76.00	FT	45.00	\$350.00	\$15,750
		0001	1220	7320615A	15 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	1.00	1.00	2.00	EA	2.00	\$800.00	\$1,600
		0001	1230	7320624A	24 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	2.00	0.00	2.00	EA	0.00	\$1,000.00	\$0
		0001	1240	7320630A	30 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	1.00	0.00	1.00	EA	0.00	\$1,500.00	\$0
		0001	1245	8031000A	TURF TYPE TALL FESCUE SODDING	1,242.00	0.00	1,242.00	SQYD	0.00	\$8.50	\$0
		0001	1260	8059919	MISC.WARM OR COOL SEASON MIXTURES	9.00	0.00	9.00	ACRE	0.00	\$1,975.00	\$0
		0001	1270	8061003	SEDIMENT TRAP EXCAVATION	57.00	0.00	57.00	CUYD	0.00	\$25.00	\$0
		0001	1280	8061004	SEDIMENT TRAP ROCK	7.00	0.00	7.00	CUYD	0.00	\$100.00	\$(
		0001	1290	8061005	ROCK DITCH CHECK	2,613.00	0.00	2,613.00	LF	24.00	\$10.50	\$252
		0001	1300	8061007A	CURB INLET CHECK	111.00	0.00	111.00	EA	0.00	\$115.00	\$0
							0.00		CUYD	0.00		

Revision 4/1/2020 Page 11 of 37



Total Paid / All Items / All Estimates (Including this Estimate)

Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
00515-F15	J6I2222	0001	1320	8061017	TEMPORARY SEEDING AND MULCHING	14.00	0.00	14.00	ACRE	0.00	\$1,500.00	\$0.00
		0001	1330	8061019	SILT FENCE	8,207.00	0.00	8,207.00	LF	2,258.00	\$2.25	\$5,080.50
		0001	1340	8064128	TYPE 1 TURF REINFORCEMENT MAT	913.00	0.00	913.00	SQYD	0.00	\$5.15	\$0.00
		0002	1350	3030600	FURNISHING ROCK BASE MATERIAL	3,355.00	0.00	3,355.00	SQYD	0.00	\$0.00	\$0.00
		0002	1360	3030610A	PLACING ROCK BASE	3,355.00	0.00	3,355.00	SQYD	0.00	\$0.00	\$0.00
		0002	1370	4030419	9 INCHES, ASPHALTIC CONCRETE PAVEMENT SP125CLP	2,073.00	0.00	2,073.00	SQYD	0.00	\$0.00	\$0.00
		0003	1380	3030600	FURNISHING ROCK BASE MATERIAL	3,363.00	0.00	3,363.00	SQYD	0.00	\$10.50	\$0.00
		0003	1390	3030610A	PLACING ROCK BASE	3,363.00	0.00	3,363.00	SQYD	0.00	\$5.50	\$0.00
		0003	1400	5021332	CONCRETE PAVEMENT (8 1/2 IN. NON-REINFORCED, 15 FT.	2,073.00	0.00	2,073.00	SQYD	0.00	\$51.00	\$0.00
		0004	1410	4010150	JOINTS) TYPE A2 SHOULDER	206.10	0.00	206.10	SQYD	0.00	\$0.00	\$0.00
		0004	1420	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	304.00	0.00	304.00	LF	0.00	\$0.00	\$0.00
		0005	1430	5021340	TYPE A2 SHOULDER	206.10	0.00	206.10	SQYD	0.00	\$35.50	\$0.00
		0005	1440	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	304.00	0.00	304.00	LF	0.00	\$20.00	\$0.00
		0006	1450	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	20,740.00	0.00	20,740.00	SQYD	0.00	\$0.00	\$0.00
		0006	1460	4039905	MISC.11.5 INCHES, ASPHALTIC CONCRETE PAVEMENT	10,939.00	0.00	10,939.00	SQYD	0.00	\$0.00	\$0.00
		0000	1470	4039905	SP125CLP MISC.9.5 INCHES, ASPHALTIC CONCRETE PAVEMENT	6,859.00	0.00	6,859.00	SQYD	0.00	\$0.00	\$0.00
		0006			SP125CLP							
		0006	1480	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	2,017.00	0.00	2,017.00	LF	0.00	\$0.00	\$0.00
		0007	1490	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	20,910.00	0.00	20,910.00	SQYD	2,629.87	\$6.50	\$17,094.16
		0007	1500	5021308	CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. JOINTS)	6,859.00	0.00	6,859.00	SQYD	0.00	\$51.00	\$0.00
		0007	1510	5021309	CONCRETE PAVEMENT (9 IN. NON-REINFORCED 15 FT. JOINTS)	10,939.00	0.00	10,939.00	SQYD	1,259.30	\$54.00	\$68,002.20
		0007	1520	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	2,017.00	0.00	2,017.00	LF	0.00	\$15.00	\$0.00
		0008	1530	4010150	TYPE A2 SHOULDER	3,806.80	0.00	3,806.80	SQYD	0.00	\$0.00	\$0.00
		0008	1540	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	3,319.00	0.00	3,319.00	LF	0.00	\$0.00	\$0.00
		0009	1550	5021340	TYPE A2 SHOULDER	3,806.80	0.00	3,806.80	SQYD	865.37	\$35.00	\$30,287.95
		0009	1560	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	3,319.00	0.00	3,319.00	LF	225.00	\$15.00	\$3,375.00
		0010	1570	6061060	MGS GUARDRAIL	3,813.00	0.00	3,813.00	LF	0.00	\$19.00	\$0.00
		0010	1580	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED	2.00	0.00	2.00	EA	0.00	\$2,850.00	\$0.00
		0010	1590	6061069	CURB) MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	2.00	0.00	2.00	EA	0.00	\$2,800.00	\$0.00
		0010	1600	6061070	MGS VERTICAL CONCRETE BARRIER TRANSITION	11.00	0.00	11.00	EA	0.00	\$2,750.00	\$0.00
		0010	1610	6061080	MGS END ANCHOR	8.00	0.00	8.00	EA	0.00	\$1,000.00	\$0.00
		0010	1620	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	12.00	0.00	12.00	EA	0.00	\$2,600.00	\$0.00
		0010	1630	6063019	TYPE E CRASHWORTHY END TERMINAL	1.00	0.00	1.00	EA	0.00	\$27,500.00	\$0.00
		0020	1640	9011330	LUMINAIRE, 1000 WATT HIGH PRESSURE SODIUM HIGH MAST	16.00	0.00	16.00	EA	0.00	\$1,018.00	\$0.00
		0020	1650	9013002	CONDUIT, 2 IN. RIGID, IN TRENCH	26.00	0.00	26.00	LF	0.00	\$10.45	\$0.00
		0020	1660	9013003	CONDUIT, 3 IN. RIGID, IN TRENCH	282.00	0.00	282.00	LF	0.00	\$11.00	\$0.00
		0020	1670	9013004	CONDUIT, 4 IN. RIGID, IN TRENCH	23.00	0.00	23.00	LF	0.00	\$12.35	\$0.00
		0020	1680	9014004	CONDUIT, 4 IN. RIGID, PUSHED	339.00	0.00	339.00	LF	0.00	\$26.60	\$0.00
		0020	1690	9015010	TRENCHING TYPE I	2,136.00	0.00	2,136.00	LF	0.00	\$3.80	\$0.00
		0020	1700	9015020	TRENCHING TYPE II	237.00	0.00	237.00	LF	0.00	\$3.80	\$0.00
		0020	1710	9016110	PULL BOX, PREFORMED CLASS 1	15.00	0.00	15.00	EA	0.00	\$765.00	\$0.00
		0020	1720	9016112	PULL BOX, PREFORMED CLASS 3	2.00	0.00	2.00	EA	0.00	\$1,343.00	\$0.00
		0020	1730	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	360.00	0.00	360.00	LF	0.00	\$0.55	\$0.00
		0020	1740	9017401	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 2 AWG	800.00	0.00	800.00	LF	0.00	\$6.00	\$0.00
		0020	1750	9017404	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 6 AWG	2,190.00	0.00	2,190.00	LF	0.00	\$3.60	\$0.00
		0020	1760	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	1,010.00	0.00	1,010.00	LF	0.00	\$2.90	\$0.00

Revision 4/1/2020 Page 12 of 37



Total Paid / All Items / All Estimates (Including this Estimate)

Contract		Category	Line	ltem	Report Generated date and can differ from the posted am Description	Bid		Total	Unit	ed. Total	Unit Price	Total Value POSTED
Nm.CONTRACT	Project No.	Category	No.	Code	резации	Quantity	Net Change Order	Current Quantity	Offic	Posted Approved Qty	Offit Price	To Date (See report generated date)
200515-F15	J6I2222	0020	1770	9018245	POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	4.00	0.00	4.00	EA	0.00	\$1,068.00	\$0.00
		0020	1780	9019901	MISC.EXTERNAL CONDUIT SYSTEM ON STRUCTURE	1.00	0.00	1.00	LS	1.00	\$16,605.00	\$16,605.00
		0020	1790	9019902	MISC.150 FT HIGH MAST POLE	2.00	0.00	2.00	EA	0.00	\$34,530.00	\$0.00
		0020	1800	9019902	MISC.45 FT TOP MOUNT POLES, TYPE AT	4.00	0.00	4.00	EA	0.00	\$2,250.00	\$0.00
		0020	1810	9019902	MISC.ADJUST PULL BOX TO GRADE	1.00	0.00	1.00	EA	0.00	\$483.00	\$0.00
		0020	1820	9019902	MISC.BASE MOUNTED 240/480V COMBINATION POWER SUPPLY AND CONTROLLER	2.00	0.00	2.00	EA	0.00	\$7,258.00	\$0.00
		0020	1830	9019902	MISC.LED-C TOP-MOUNT LUMINAIRE	4.00	0.00	4.00	EA	0.00	\$572.00	\$0.00
		0020	1840	9019903	MISC.1 IN RIGID GALVANIZED STEEL CONDUIT	549.00	0.00	549.00	LF	0.00	\$15.85	\$0.00
		0020	1850	9019903	MISC.THHN CABLE 2C #6 AWG	1,830.00	0.00	1,830.00	LF	0.00	\$1.65	\$0.00
		0030	1860	9020213	SIGNAL HEAD, TYPE 3S	3.00	0.00	3.00	EA	0.00	\$761.00	\$0.00
		0030	1870	9020513	SIGNAL HEAD, TYPE 3B	37.00	0.00	37.00	EA	0.00	\$927.00	\$0.00
		0030	1880	9020514	SIGNAL HEAD, TYPE 4B	3.00	0.00	3.00	EA	0.00	\$1,038.00	\$0.00
		0030	1890	9020833	SH-FLAT SHEET - SIGNAL SIGN	133.00	0.00	133.00	SQFT	0.00	\$12.50	\$0.00
		0030	1900	9020834	SIGNAL SIGN, MOUNTING HARDWARE	41.00	0.00	41.00	EA	0.00	\$33.00	\$0.00
		0030	1910	9022708	POST, SIGNAL 8 FT. OR 2.4 M	18.00	0.00	18.00	EA	0.00	\$645.00	\$0.00
		0030	1920	9022715	POST, SIGNAL 15 FT. OR 4.6 M	1.00	0.00	1.00	EA	0.00	\$972.00	\$0.00
		0030	1930	9023230	POST, TYPE C, 30 FT. ARM OR 9.1 M ARM	1.00	0.00	1.00	EA	0.00	\$7,324.00	\$0.00
		0030	1940	9023235	POST, TYPE C, 35 FT. ARM OR 10.7 M ARM	1.00	0.00	1.00	EA	0.00	\$7,532.00	\$0.00
		0030	1950	9023250	POST, TYPE C, 50 FT. ARM OR 15.2 M ARM	1.00	0.00	1.00	EA	0.00	\$10,292.00	\$0.00
		0030	1960	9023255	POST, TYPE C, 55 FT. ARM	4.00	0.00	4.00	EA	0.00	\$11,930.00	\$0.00
		0030	1970	9023335	POST, TYPE B, LONGEST ARM 35 FT. OR 10.7 M	1.00	0.00	1.00	EA	0.00	\$12,945.00	\$0.00
		0030	1980	9023345	POST, TYPE B, LONGEST ARM 45 FT. OR 13.7 M	1.00	0.00	1.00	EA	0.00	\$12,439.00	\$0.00
		0030	1990	9024283	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	3.00	0.00	3.00	EA	0.00	\$13,359.00	\$0.00
		0030	2000	9024975	VIDEO DETECTION SYSTEM	4.00	0.00	4.00	EA	0.00	\$12,698.00	\$0.00
		0030	2010	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	1,320.00	0.00	1,320.00	LF	0.00	\$10.20	\$0.00
		0030	2020	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	844.00	0.00	844.00	LF	0.00	\$23.00	\$0.00
		0030	2030	9028208	CABLE, 8 AWG 1 CONDUCTOR, POWER	3,350.00	0.00	3,350.00	LF	0.00	\$0.95	\$0.00
		0030	2040	9028308	CABLE, 16 AWG 2 CONDUCTOR	3,730.00	0.00	3,730.00	LF	0.00	\$0.50	\$0.00
		0030	2050	9028310	CABLE, 16 AWG 5 CONDUCTOR	3,750.00	0.00	3,750.00	LF	0.00	\$1.10	\$0.00
		0030	2060	9028311	CABLE, 16 AWG 7 CONDUCTOR	6,790.00	0.00	6,790.00	LF	0.00	\$1.60	\$0.00
		0030	2070	9028810	PULL BOX, PREFORMED CLASS 1	10.00	0.00	10.00	EA	0.00	\$602.00	\$0.00
		0030	2080	9028811	PULL BOX, PREFORMED CLASS 2	8.00	0.00	8.00	EA	0.00	\$1,221.00	\$0.00
		0030	2090	9028812	PULL BOX, PREFORMED CLASS 3	3.00	0.00	3.00	EA	0.00	\$1,642.00	\$0.00
		0030	2100	9029100	BASE, CONCRETE	44.00	0.00	44.00	CUYD	0.00	\$1,160.00	\$0.00
		0030	2110	9029901	MISC.TRAFFIC SIGNAL MAINTENANCE AND PROGRAMMING	1.00	0.00	1.00	LS	0.00	\$65,520.00	\$0.00
		0030	2120	9029902	MISC.ATC TRAFFIC SIGNAL CONTROLLER	3.00	0.00	3.00	EA	0.00	\$3,214.00	\$0.00
		0030	2130	9029902	MISC.AUDIBLE PEDESTRIAN PUSH BUTTON AND SIGNING	24.00	0.00	24.00	EA	0.00	\$715.00	\$0.00
		0030	2140	9029902	MISC.COMBINATION PAD MOUNTED 120V/240V POWER	1.00	0.00	1.00	EA	0.00	\$14,267.00	\$0.00
		0030	2150	9029902	SUPPLY AND LIGHTING CONTROLLER WITH UPS MISC.CONCRETE TRANSFORMER PAD	1.00	0.00	1.00	EA	0.00	\$3.863.00	\$0.00
		0030	2160	9029902	MISC.Countdown Pedestrian Signal Head, Type 1S	22.00	0.00	22.00	EA	0.00	\$450.00	\$0.00
		0030	2170	9029902	MISC.Install 55' Arm on Existing Signal Post	1.00	0.00	1.00	EA	0.00	\$4,795.00	\$0.00
		0030	2180	9029902	MISC.NETWORK CONNECTED SIGNAL MONITOR	3.00	0.00	3.00	EA	0.00	\$1,010.00	\$0.00
		0030	2190	9029902	MISC.3" PVC CONDUIT WITH PULL TAPE	255.00	0.00	255.00	LF	0.00	\$1,010.00	\$0.00
		0030	2200	9029903	CONCRETE FOOTINGS, EMBEDDED	10.60	0.00	10.60	CUYD	0.00	\$1,400.00	\$0.00
		0040	2210	9031020	CONCRETE FOOTINGS, BOLT DOWN	82.30	6.50	88.80	CUYD	12.50	\$1,400.00	\$15,000.00
				9031020	STRUCTURAL STEEL POSTS				LB	0.00		
		0040	2220	9031210	STRUCTURAL STEEL PUSTS	3,150.00	0.00	3,150.00	LD	0.00	\$4.50	\$0.00

Revision 4/1/2020 Page 13 of 37



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report General

ote: Posted Q	uantities	and Valu	ies are	based on F	Report Generated date and can differ from the posted a	mount at the	time the Es	timate was	Generat	ed.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
00515-F15	J6I2222	0040	2230	9031220	PIPE POSTS	5,390.00	0.00	5,390.00	LB	0.00	\$3.75	\$0.00
		0040	2240	9031270A	2 IN. PSST POST - 12 GA.	60.00	0.00	60.00	LF	0.00	\$12.00	\$0.00
		0040	2250	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	21.00	0.00	21.00	LF	0.00	\$40.00	\$0.00
		0040	2260	9035004A	SH-FLAT SHEET	598.00	0.00	598.00	SQFT	0.00	\$21.00	\$0.00
		0040	2270	9035011A	ST-STRUCTURAL	2,364.00	0.00	2,364.00	SQFT	0.00	\$24.00	\$0.00
		0040	2280	9035069A	SHF-FLAT SHEET FLUORESCENT	93.00	0.00	93.00	SQFT	0.00	\$24.00	\$0.00
		0040	2290	9035071A	STF-STRUCTURAL FLUORESCENT	390.00	0.00	390.00	SQFT	0.00	\$26.00	\$0.00
		0040	2300	9036036	TUBULAR SUPPORT, TYPE C-2315-20	2.00	0.00	2.00	EA	0.00	\$12,950.00	\$0.00
		0040	2310	9036042	TUBULAR SUPPORT, TYPE C-2018-28	2.00	0.00	2.00	EA	0.00	\$20,000.00	\$0.00
		0040	2320	9039901	MISC.SIGN 12 CANTILEVER BOX TRUSS, 30 FT ARM	1.00	0.00	1.00	LS	0.00	\$29,000.00	\$0.00
		0040	2330	9039901	MISC.SIGN 4 SPAN BOX TRUSS (98 FT)	1.00	0.00	1.00	LS	0.00	\$66,000.00	\$0.00
		0040	2340	9039901	MISC.SIGN 8 SPAN BOX TRUSS (83 FT-5 IN)	1.00	0.00	1.00	LS	0.00	\$52,500.00	\$0.00
		0040	2350	9039901	MISC.SPECIAL STREET NAME BRIDGE MOUNTED SIGNS	1.00	0.00	1.00	LS	0.00	\$20,000.00	\$0.00
		0050	2360	9108208	CABLE, 8 AWG, 1 CONDUCTOR, POWER	2,510.00	0.00	2,510.00	LF	0.00	\$1.00	\$0.00
		0050	2370	9108408	WIRE, 8 AWG, BARE NEUTRAL	1,010.00	0.00	1,010.00	LF	0.00	\$1.00	\$0.00
		0050	2380	9109100	BASE, CONCRETE	2.00	0.00	2.00	CUYD	0.00	\$1,726.00	\$0.00
		0050	2390	9109230	DYNAMIC MESSAGE SIGN ASSEMBLY, INSTALLED	1.00	-1.00	0.00	EA	0.00	\$9,413.00	\$0.00
		0050	2400	9109901	MISC.ITS ASSET MANAGEMENT TOOL	1.00	0.00	1.00	LS	0.00	\$2,797.00	\$0.00
		0050	2410	9109902	MISC.ADJUST EXISTING P.B. TO GRADE	1.00	0.00	1.00	EA	0.00	\$1,335.00	\$0.00
		0050	2420	9109902	MISC.BURIED CABLE DELINEATOR POST	12.00	0.00	12.00	EA	1.00	\$100.00	\$100.00
		0050	2430	9109902	MISC.BUTTERFLY DMS STRUCTURE	1.00	0.00	1.00	EA	0.00	\$55,944.00	\$0.00
		0050	2440	9109902	MISC.CCTV EXTENSION POLE, 20' METALLICFINISH	1.00	0.00	1.00	EA	0.00	\$1,554.00	\$0.00
		0050	2450	9109902	MISC.FIBER OPTIC FUSION SPLICE	310.00	48.00	358.00	EA	272.00	\$39.00	\$10,608.00
		0050	2460	9109902	MISC.FIBER OPTIC JUMPER,SM, FURNISH AND INSTALL	34.00	0.00	34.00	EA	7.00	\$22.00	\$154.00
		0050	2470	9109902	MISC.FIBER OPTIC PIGTAIL, SM, FURNISH AND INSTALL	42.00	0.00	42.00	EA	26.00	\$10.00	\$260.00
		0050	2480	9109902	MISC FIELD TERMINAL CABINET, TYPE 7, FURNISH AND INSTALL	1.00	0.00	1.00	EA	0.00	\$3,314.00	\$0.00
		0050	2490	9109902	MISC.INSTALL CCTV CAMERA ASSEMBLY	1.00	0.00	1.00	EA	0.00	\$883.00	\$0.00
		0050	2500	9109902	MISC.INSTALL CONDUIT INTO EXISTING BOX	5.00	0.00	5.00	EA	0.00	\$210.00	\$0.00
		0050	2510	9109902	MISC.ITS PULL BOX, CLASS 5	5.00	0.00	5.00	EA	0.00	\$1,842.00	\$0.00
		0050	2520	9109902	MISC.ITS PULL BOX, CLASS 2	1.00	0.00	1.00	EA	0.00	\$1,554.00	\$0.00
		0050	2530	9109902	MISC.SIGN STRUCTURE BASE MESH	1.00	0.00	1.00	EA	0.00	\$310.00	\$0.00
		0050	2540	9109902	MISC.UNDERGROUND FIBER CABLE SPLICE ENCLOSURE	2.00	2.00	4.00	EA	2.00	\$621.00	\$1,242.00
		0050	2550	9109902	MISC.WALL-MOUNTED FIBER INTERCONNECT CENTER, FURNISH AND INSTALL	7.00	0.00	7.00	EA	0.00	\$350.00	\$0.00
		0050	2560	9109903	MISC.24 STRAND, SINGLE MODE FIBER OPTIC CABLE	7,760.00	0.00	7,760.00	LF	7,760.00	\$1.85	\$14,356.00
		0050	2570	9109903	MISC.72 STRAND, SINGLE MODE FIBER OPTIC CABLE	4,200.00	0.00	4,200.00	LF	4,200.00	\$2.05	\$8,610.00
		0050	2580	9109903	MISC.CAT-5 ETHERNET CABLE	200.00	0.00	200.00	LF	0.00	\$1.70	\$0.00
		0050	2590	9109903	MISC.Conduit, PVC, PUSHED, 2"	399.00	0.00	399.00	LF	256.00	\$16.45	\$4,211.20
		0050	2600	9109903	MISC.CONDUIT, PVC, TRENCH, 2"	1,083.00	0.00	1,083.00	LF	0.00	\$5.90	\$0.00
		0070	2610	2163000	PARTIAL REMOVAL OF EXISTING BRIDGE DECK	2,033.00	0.00	2,033.00	SQFT	2,033.00	\$10.00	\$20,330.00
		0070	2620	2163502	PARTIAL REMOVAL OF SUBSTRUCTURE CONCRETE	1.00	0.00	1.00	LS	1.00	\$9,200.00	\$9,200.00
		0070	2630	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	41.00	0.00	41.00	LF	0.00	\$425.00	\$0.00
		0070	2640	5031010A		59.00	0.00	59.00	SQYD	0.00	\$355.00	\$0.00
		0070	2650	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	1.00	0.00	1.00	CUYD	0.00	\$5,050.00	\$0.00
		0070	2660	7034001	CLASS B-1 CONCRETE	0.70	0.00	0.70	CUYD	0.00	\$12,650.00	\$0.00
		0070	2670	7034212	SLAB ON STEEL	212.00	0.00	212.00	SQYD	37.00	\$470.00	\$17,390.00
		0070	2680	7034214	CLASS B-2 CONCRETE	3.50	0.00	3.50	CUYD	0.00	\$6,530.00	\$0.00

Revision 4/1/2020 Page 14 of 37



Total Paid / All Items / All Estimates (Including this Estimate)

Contract Nm.CONTRACT	Project No.	Category		Item Code	Report Generated date and can differ from the posted an Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved	Unit Price	Total Value POSTED To Date (See report generated date)
200515-F15	J6I2222	0070	2690	7034610	CORRAL CURB	182.00	0.00	182.00	LF	Qty 0.00	\$117.00	\$0.00
200010110	OOILLLL	0070	2700	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	1,275.00	0.00	1,275.00	SQFT	0.00	\$158.00	\$0.00
		0070	2710	7040113	CLEANING AND EPOXY COATING	6,834.00	0.00	6,834.00	SQFT	0.00	\$3.36	\$0.00
		0070	2720	7049904	MISC.BARRIER CURB REPAIR (UNFORMED	195.00	0.00	195.00	SQFT	0.00	\$175.00	\$0.00
		0070	2730	7101000	REINFORCING STEEL (EPOXY COATED)	850.00	0.00	850.00	LB	0.00	\$3.00	\$0.00
		0070	2740	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS	1.00	0.00	1.00	LS	0.00	\$1,584.52	\$0.00
		0070			(EPOXY)							
		0070	2750	7123130	REHABILITATE BEARING	8.00	0.00	8.00	EA	0.00	\$3,712.50	\$0.00
		0070	2760	7123620	DRAINAGE SYSTEM (ON STRUCTURE)	1.00	0.00	1.00	LS	0.00	\$10,500.00	\$0.00
		0070	2770	7129901	MISC.FLUSH DRAINAGE SYSTEM AND EXPANSION JOINTS	1.00	0.00	1.00	LS	0.00	\$20,000.00	\$0.00
		0070	2780	7129902	MISC.FATIGUE CRACK REPAIR	1.00	0.00	1.00	EA	0.00	\$6,516.00	\$0.00
		0070	2790	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	41.00	0.00	41.00	LF	0.00	\$490.00	\$0.00
		0071	2800	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	25.00	0.00	25.00	SQFT	0.00	\$158.00	\$0.00
		0071	2810	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	1,483.00	0.00	1,483.00	SQFT	0.00	\$158.00	\$0.00
		0071	2820	7040113	CLEANING AND EPOXY COATING	5,621.00	0.00	5,621.00	SQFT	0.00	\$3.04	\$0.00
		0071	2830	7049904	MISC.BARRIER CURB REPAIR (UNFORMED)	142.00	0.00	142.00	SQFT	0.00	\$175.00	\$0.00
		0071	2840	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$3,678.35	\$0.00
		0071	2850	7121000	FABRICATED STRUCTURAL CARBON STEEL (MISC)	290.00	0.00	290.00	LB	0.00	\$23.00	\$0.00
		0071	2860	7123130	REHABILITATE BEARING	5.00	0.00	5.00	EA	0.00	\$2,570.00	\$0.00
		0071	2875	7125111	INTERMEDIATE FIELD COAT (SYSTEM G)	1.00	0.00	1.00	LS	0.00	\$1,330.80	\$0.00
		0071	2885	7125112	FINISH FIELD COAT (SYSTEM G)	1.00	0.00	1.00	LS	0.00	\$475.20	\$0.00
		0071	2890	7129901	MISC.FLUSH DRAINAGE SYSTEM AND EXPANSION JOINTS	1.00	0.00	1.00	LS	0.00	\$20,000.00	\$0.00
		0071	2900	7129902	MISC.FATIGUE CRACK REPAIR	3.00	0.00	3.00	EA	0.00	\$2,040.00	\$0.00
		0072	2910	7121060	FABRICATED SIGN SUPPORT BRACKETS	1.00	0.00	1.00	LS	0.00	\$3,600.00	\$0.00
		0073	2920	2065500	TEMPORARY SHORING	1.00	0.00	1.00	LS	1.00	\$150,000.00	\$150,000.00
		0073	2930	7033009	AESTHETIC CONCRETE STAIN	1.00	0.00	1.00	LS	0.00	\$14,877.00	\$0.00
		0073	2940	7201000	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	8,672.00	0.00	8,672.00	SQFT	8,672.00	\$62.50	\$542,000.00
		0074	2955	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	258.00	0.00	258.00	SQYD	0.00	\$145.00	\$0.00
		0074	2960	6079903	MISC.(60 IN.) DECORATIVE PEDESTRIAN FENCE	280.00	0.00	280.00	LF	0.00	\$130.00	\$0.00
		0074	2970	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	820.00	0.00	820.00	LF	0.00	\$68.00	\$0.00
		0074	2980	7025001	DYNAMIC PILE TESTING	2.00	0.00	2.00	EA	0.00	\$2,325.00	\$0.00
		0074	2990	7027000	PILE POINT REINFORCEMENT	14.00	0.00	14.00	EA	0.00	\$80.00	\$0.00
		0074	3000	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	56.40	0.00	56.40	CUYD	0.00	\$565.00	\$0.00
		0074	3010		TYPE D BARRIER	288.00	0.00	288.00	LF	0.00	\$115.00	\$0.00
		0074	3020	7034221	SLAB ON CONCRETE NU-GIRDER	760.00	0.00	760.00	SQYD	0.00	\$335.00	\$0.00
		0074	3030	7034630	CONCRETE CURB (BRIDGE RAIL)	306.00	0.00	306.00	LF	0.00	\$75.00	\$0.00
		0074	3040	7056022	NU 43. PRESTRESSED CONCRETE NU-GIRDER	894.00	0.00	894.00	LF	0.00	\$215.00	\$0.00
		0074	3050	7071000	CONDUIT SYSTEM ON STRUCTURE	1.00	0.00	1.00	LS	0.00	\$5,927.00	\$0.00
		0074	3060	7121060	FABRICATED SIGN SUPPORT BRACKETS	1.00	0.00	1.00	LS	0.00	\$7,100.00	\$0.00
		0074	3070	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	0.00	\$2,500.00	\$0.00
		0074	3080	7161000	PLAIN NEOPRENE BEARING PAD	16.00	0.00	16.00	EA	0.00	\$200.00	\$0.00
		0074	3090	7201300	PIPE PILE SPACERS	14.00	0.00	14.00	EA	0.00	\$1,000.00	\$0.00
									EA			
		0074	3100	9019902	MISC.ORNAMENTAL LUMINAIRE	10.00	0.00	10.00		0.00	\$1,658.00	\$0.00
		0075	3110	7033009	AESTHETIC CONCRETE STAIN	1.00	-1.00	0.00	LS	0.00	\$17,530.50	\$0.00
		0075	3120	7201000	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	7,637.00	-7,637.00	0.00	SQFT	0.00	\$110.00	\$0.00
		0076	3130	7033009	AESTHETIC CONCRETE STAIN	1.00	-1.00	0.00	LS	0.00	\$6,525.00	\$0.00
		0076	3140	7201000	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	3,410.00	-3,410.00	0.00	SQFT	0.00	\$110.00	\$0.00

Revision 4/1/2020 Page 15 of 37



Total Paid / All Items / All Estimates (Including this Estimate)

Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repo generated date)
0515-F15	J6I2222	0077	3150	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	0.00	\$146,000.00	\$0.0
		0077	3160	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	250.00	0.00	250.00	SQYD	0.00	\$155.00	\$0.0
		0077	3170	6079903	MISC.(60 IN.) DECORATIVE PEDESTRIAN FENCE	404.00	0.00	404.00	LF	0.00	\$130.00	\$0.0
		0077	3180	7011105	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	30.00	0.00	30.00	LF	0.00	\$490.00	\$0.0
		0077	3190	7011204	ROCK SOCKETS (3 FT 0 IN. DIA.)	30.00	0.00	30.00	LF	0.00	\$815.00	\$0.0
		0077	3200	7011300	VIDEO CAMERA INSPECTION	3.00	0.00	3.00	EA	0.00	\$450.00	\$0.0
		0077	3210	7011400	FOUNDATION INSPECTION HOLES	60.00	0.00	60.00	LF	0.00	\$140.00	\$0.0
		0077	3220	7011600	SONIC LOGGING TESTING	3.00	0.00	3.00	EA	0.00	\$2,100.00	\$0.
		0077	3230	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	462.00	0.00	462.00	LF	0.00	\$75.00	\$0.
		0077	3240	7025001	DYNAMIC PILE TESTING	2.00	0.00	2.00	EA	0.00	\$2,350.00	\$0.
		0077	3250	7026000	PRE-BORE FOR PILING	252.00	0.00	252.00	LF	0.00	\$180.00	\$0.
		0077	3260	7027000	PILE POINT REINFORCEMENT	14.00	0.00	14.00	EA	0.00	\$80.00	\$0.
		0077	3270	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	49.60	0.00	49.60	CUYD	0.00	\$800.00	\$0.
		0077	3280	7034003	CLASS B-1 CONCRETE (SUBSTRUCTURE)	60.30	0.00	60.30	CUYD	0.00	\$1,055.00	\$0.
		0077	3290	7034219A	TYPE D BARRIER	404.00	0.00	404.00	LF	0.00	\$130.00	\$0.
		0077	3300	7034221	SLAB ON CONCRETE NU-GIRDER	1,175.00	0.00	1,175.00	SQYD	0.00	\$290.00	\$0.
		0077	3310	7034630	CONCRETE CURB (BRIDGE RAIL)	447.00	0.00	447.00	LF	0.00	\$62.00	\$0.
		0077	3320	7056021	NU 35, PRESTRESSED CONCRETE NU-GIRDER	1,268.00	0.00	1,268.00	LF	0.00	\$210.00	\$0.
		0077	3330	7061060	REINFORCING STEEL (BRIDGES)	18,420.00	-18,420.00	0.00	LB	0.00	\$1.00	\$0.
		0077	3340	7071000	CONDUIT SYSTEM ON STRUCTURE	1.00	0.00	1.00	LS	0.00	\$26,383.00	\$0
		0077	3350	7079901	MISC.CONDUIT SYSTEM ON STRUCTURE - ATT TELPHONE	1.00	0.00	1.00	LS	0.00	\$3,730.00	\$0
		0077	3355	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$8,330.05	\$0
		0077	3370	7121060	FABRICATED SIGN SUPPORT BRACKETS	1.00	0.00	1.00	LS	0.00	\$27,500.00	\$0
		0077	3380	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	0.00	\$2,500.00	\$0
		0077	3390	7161003	LAMINATED NEOPRENE BEARING PAD (TAPERED)	28.00	0.00	28.00	EA	0.00	\$425.00	\$0
		0077	3400	7201300	PIPE PILE SPACERS	14.00	0.00	14.00	EA	0.00	\$855.00	\$0
		0077	3410	9019903	MISC.ORNAMENTAL LUMINAIRE	12.00	0.00	12.00	LF	0.00	\$1,658.00	\$0
		0078	3420	7033009	AESTHETIC CONCRETE STAIN	1.00	0.00	1.00	LS	0.00	\$7,856.10	\$0
		0078	3430	7201000	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	4,182.00	0.00	4,182.00	SQFT	0.00	\$80.00	\$0
		0079	3440	7033009	AESTHETIC CONCRETE STAIN	1.00	0.00	1.00	LS	0.00	\$3,654.00	\$0
		0079	3450	7201000	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	2,521.00	0.00	2,521.00	SQFT	0.00	\$80.00	\$0
		0080	3460	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	0.70	\$655,000.00	\$458,500
		0080	3470	5031010A	BRIDGE APPROACH SLAB (MAJOR ROAD)	81.00	0.00	81.00	SQYD	0.00	\$200.00	\$0
		0080	3480	7011110	DRILLED SHAFTS (6 FT. 0 IN. DIA.)	380.40	0.00	380.40	LF	0.00	\$485.00	\$0
		0080	3490	7011209	ROCK SOCKETS (5 FT 6 IN. DIA.)	108.00	0.00	108.00	LF	0.00	\$2,555.00	\$0
		0080	3500	7011300	VIDEO CAMERA INSPECTION	6.00	0.00	6.00	EA	0.00	\$550.00	\$0
		0080	3510	7011400	FOUNDATION INSPECTION HOLES	174.00	0.00	174.00	LF	125.80	\$155.00	\$19,499
		0080	3520	7011600	SONIC LOGGING TESTING	6.00	0.00	6.00	EA	0.00	\$4.250.00	\$0
		0080	3530	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	430.00	0.00	430.00	LF	0.00	\$85.00	\$0
		0080	3540	7025001	DYNAMIC PILE TESTING	1.00	0.00	1.00	EA	0.00	\$2,700.00	\$0
		0080	3550	7027000	PILE POINT REINFORCEMENT	5.00	0.00	5.00	EA	0.00	\$80.00	\$0
		0080	3560	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	21.70	0.00	21.70	CUYD	0.00	\$745.00	\$0
		0080	3570	7032003	CLASS B-1 CONCRETE (SUBSTRUCTURE)	379.50	0.00	379.50	CUYD	0.00	\$743.00	\$0
		0080	3580	7034003	SLAB ON STEEL	304.00	0.00	304.00	SQYD	0.00	\$335.00	\$0
		0080	3590	7034212 7034219A	TYPE D BARRIER	1,779.00	0.00	1,779.00	LF	0.00	\$58.00	\$(
			3600	7034219A 7034221	SLAB ON CONCRETE NU-GIRDER	2,430.00	0.00	2,430.00	SQYD	0.00	\$340.00	
		0800	5000	1004221	OLAB ON CONCIL IL NU-CIRDER	2,430.00	0.00	2,430.00	JUID	0.00	φ340.00	\$0

Revision 4/1/2020 Page 16 of 37



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note: Posted Q	uantities	and Valu	ies are l	pased on I	Report Generated date and can differ from the posted am	ount at the	time the Es	stimate was	General	ted.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200515-F15	J6I2222	0800	3620	7056025	NU 70, PRESTRESSED CONCRETE NU-GIRDER	1,151.00	0.00	1,151.00	LF	0.00	\$270.00	\$0.00
		0800	3630	7061060	REINFORCING STEEL (BRIDGES)	170,450.00	0.00	170,450.00	LB	0.00	\$0.85	\$0.00
		0800	3640	7061070	MECHANICAL BAR SPLICE	480.00	0.00	480.00	EA	0.00	\$95.00	\$0.00
		0800	3650	7101000	REINFORCING STEEL (EPOXY COATED)	12,940.00	0.00	12,940.00	LB	0.00	\$1.15	\$0.00
		0800	3660	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$9,744.80	\$0.00
		0800	3670	7120900	EXPANSION DEVICE (FINGER PLATE)	23.00	0.00	23.00	LF	0.00	\$2,400.00	\$0.00
		0800	3680	7121121	FABRICATED STRUCTURAL LOW ALLOY STEEL (PLATE GIRDER) A709, GRADE 50	79,550.00	0.00	79,550.00	LB	0.00	\$3.19	\$0.00
		0800	3690	7123210	EARTH QUAKE RESTRAINER ASSEMBLIES	3.00	0.00	3.00	EA	0.00	\$13,125.00	\$0.00
		0800	3700	7123301	STEEL INTERMEDIATE DIAPHRAGM FOR P/S CONCRETE GIRDERS	30.00	0.00	30.00	EA	0.00	\$680.00	\$0.00
		0800	3710	7123620	DRAINAGE SYSTEM (ON STRUCTURE)	1.00	0.00	1.00	LS	0.00	\$80,000.00	\$0.00
		0080	3720	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	500.00	0.00	500.00	SQFT	0.00	\$81.40	\$0.00
		0080	3730	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	500.00	0.00	500.00	SQFT	0.00	\$2.00	\$0.00
		0800	3740	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	5,000.00	0.00	5,000.00	SQFT	0.00	\$6.65	\$0.00
		0080	3750	7125370A	FINISH FIELD COAT (SYSTEM G)	2,700.00	0.00	2,700.00	SQFT	0.00	\$2.38	\$0.00
		0800	3760	7129903	MISC.MODULAR EXPANSION JOINT SYSTEM	24.00	0.00	24.00	LF	0.00	\$2,400.00	\$0.00
		0800	3770	7151001	VERTICAL DRAIN AT END BENTS	1.00	0.00	1.00	EA	0.00	\$2,500.00	\$0.00
		0800	3780	7161000	PLAIN NEOPRENE BEARING PAD	8.00	0.00	8.00	EA	0.00	\$225.00	\$0.00
		0800	3790	7161002	LAMINATED NEOPRENE BEARING PAD	3.00	0.00	3.00	EA	0.00	\$250.00	\$0.00
		0800	3800	7161003	LAMINATED NEOPRENE BEARING PAD (TAPERED)	21.00	0.00	21.00	EA	0.00	\$320.00	\$0.00
		0800	3810	7162000	LAMINATED NEOPRENE BEARING PAD ASSEMBLY	16.00	0.00	16.00	EA	0.00	\$1,520.00	\$0.00
		0800	3820	7163000	TYPE N PTFE BEARING	3.00	0.00	3.00	EA	0.00	\$2,500.00	\$0.00
		0800	3830	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	24.00	0.00	24.00	LF	0.00	\$510.00	\$0.00
		0001	5001	6189901	MISC.Adjust Mobilization for Contract Bond	0.00	1.00	1.00	LS	1.00	\$107,907.00	\$107,907.00
		0001	5002	6141121	CURVED VANE GRATE AND FRAME (4 FT. X 2 FT. OR 1200MM X 600MM)	0.00	36.00	36.00	EA	0.00	\$1,400.00	\$0.00
		0001	5003	6149902	MISC.Parallel Grate and Bearing Plate (4 FT.x2FT.)	0.00	30.00	30.00	EA	6.00	\$1,400.00	\$8,400.00
		0050	5004	9109901	MISC.DMS Board Removal	0.00	1.00	1.00	LS	1.00	\$12,673.51	\$12,673.51
		0001	5005	6173700B	TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED	0.00	638.00	638.00	LF	638.00	\$40.79	\$26,024.02
		0001	5006	2063100	CLASS 3 EXCAVATION IN ROCK	0.00	18.50	18.50	CUYD	0.00	\$85.00	\$0.00
		0050	5007	9109901	MISC.Colored Dynamic Message Sign	0.00	1.00	1.00	LS	0.00	\$110,608.04	\$0.00
		0001	5008	6149902	MISC.MISC. MSD Manhole Frame and Cover	0.00	17.00	17.00	EA	5.00	\$400.00	\$2,000.00
		0001	5009	2032000	CLASS C EXCAVATION	0.00	728.90	728.90	CUYD	728.90	\$75.00	\$54,667.50
		0001	5010	7209901	MISC.Rock Fill Alternative Ground Improvement	0.00	1.00	1.00	LS	1.00	\$7,822.60	\$7,822.60
		0077	5011	7101000	REINFORCING STEEL (EPOXY COATED)	0.00	18,420.00	18,420.00	LB	0.00	\$1.33	\$0.00
		0001	5012	2029901	MISC.Barrier Wall Removal	0.00	1.00	1.00	LS	1.00	\$5,226.18	\$5,226.18
		0074	5013	7011105	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	0.00	202.80	202.80	LF	202.80	\$567.75	\$115,139.70
		0074	5014	7011204	ROCK SOCKETS (3 FT 0 IN. DIA.)	0.00	76.70	76.70	LF	76.70	\$917.10	\$70,341.57
		0074	5015	7101000	REINFORCING STEEL (EPOXY COATED)	0.00	24,760.00	24,760.00	LB	24,760.00	\$1.49	\$36,892.40
		0074	5016	7011300	VIDEO CAMERA INSPECTION	0.00	6.00	6.00	EA	6.00	\$577.50	\$3,465.00
		0074	5017	7011400	FOUNDATION INSPECTION HOLES	0.00	185.10	185.10	LF	185.10	\$136.50	\$25,266.15
		0074	5018	7011600	SONIC LOGGING TESTING	0.00	6.00	6.00	EA	6.00	\$4,593.00	\$27,558.00
		0074	5019	7061070	MECHANICAL BAR SPLICE	0.00	36.00	36.00	EA	18.00	\$140.70	\$2,532.60
200545 545 3					Date as of Report Generated Date							\$7,312,463.02
200515-F15 Ove	rall - Tota	Value Pos	ted to Da	te as of Rep	ort Generated Date							\$7,312,463.02

Revision 4/1/2020 Page 17 of 37



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J6I2222

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0050	2031000	CLASS A EXCAVATION	1/28/21	2/1/21	23,036.00	CUYD	Excavation from Construction Stockpile on North Side of I-64	0		0		20,000 CY catch up payment as well as excavations from 1/18 - 1/20
0060	2036000	COMPACTING EMBANKMENT	1/28/21	2/1/21	500.00	CUYD	Between Ramp D and South Outer Road	16+87		22+22.17		
0800	2039901	MISC.	1/28/21	2/1/21	0.25	LS	Old 21st St Stockpile	0		0		
0300	6049903	MISC. DRAINAGE ITEM	1/28/21	2/1/21	2.30	LF	Various locations	0		0		Under 22nd street Bridge, MH-394, MH-395
1330	8061019	SILT FENCE	1/22/21	1/25/21	255.00	LF	NW Corner of Ewing Bridge along Exit 38B for Market St	0		0		
2670	7034212	SLAB ON STEEL	2/1/21	2/2/21	37.00	SQYD	Bridge A150114 stay in place forms	0		0		50% of the Stay in Place forms installed
5013	7011105	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	1/21/21	1/25/21	202.80	LF	Bridge A8831 Bents 2 & 3 Drilled Shafts	6+50.33		7+56.58		Change Order No. 9 Processed - Work performed at an earlier date
5014	7011204	ROCK SOCKETS (3 FT 0 IN. DIA.)	1/21/21	1/25/21	76.70	LF	Bridge A8831 Bents 2 & 3 Drilled Shafts	6+50.33		7+56.58		Change Order No. 9 Processed - Work performed at an earlier date
5015	7101000	REINFORCING STEEL (EPOXY COATED)	1/21/21	1/25/21	24,760.00	LB	Bridge A8831 Bents 2 & 3 Drilled Shafts	6+50.33		7+56.58		Change Order No. 9 Processed - Work performed at an earlier date
5016	7011300	VIDEO CAMERA INSPECTION	1/21/21	1/25/21	6.00	EA	Bridge A8831 Bents 2 & 3 Drilled Shafts	6+50.33		7+56.58		Change Order No. 9 Processed - Work performed at an earlier date
5017	7011400	FOUNDATION INSPECTION HOLES	1/21/21	1/25/21	185.10	LF	Bridge A8831 Bents 2 & 3 Drilled Shafts	6+50.33		7+56.58		Change Order No. 9 Processed - Work performed at an earlier date
5018	7011600	SONIC LOGGING TESTING	1/21/21	1/25/21	6.00	EA	Bridge A8831 Bents 2 & 3 Drilled Shafts	6+50.33		7+56.58		Change Order No. 9 Processed - Work performed at an earlier date
5019	7061070	MECHANICAL BAR SPLICE	1/21/21	1/25/21	18.00	EA	Bridge A8831 Bents 2 & 3 Drilled Shafts	6+50.33		7+56.58		Change Order No. 9 Processed - Work performed at an earlier date

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 4/1/2020 Page 18 of 37



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks													
0050	CLASS A EXCAVATION	Price		4	Sep 2, 2020	SYSTEM	\$24.92	Reference Item Price Adjustment Index Adjustment Type applied is FUEL													
				4	Sep 2, 2020	SYSTEM	\$7.00	Reference Item Price Adjustment Index Adjustment Type applied is FUEL													
				5	Sep 16, 2020	SYSTEM	\$349.60	Reference Item Price Adjustment Index Adjustment Type applied is FUEL													
				7	Oct 16, 2020	SYSTEM	\$800.00	Reference Item Price Adjustment Index Adjustment Type applied is FUEL													
				9	Nov 16, 2020	SYSTEM	\$1,020.00	Reference Item Price Adjustment Index Adjustment Type applied is FUEL													
				10	Dec 2, 2020	SYSTEM	\$204.00	Reference Item Price Adjustment Index Adjustment Type applied is FUEL													
				11	Dec 16, 2020	SYSTEM	\$1,142.60	Reference Item Price Adjustment Index Adjustment Type applied is FUEL													
				13	Jan 19, 2021	SYSTEM	\$201.00	Reference Item Price Adjustment Index Adjustment Type applied is FUEL													
				14	Feb 2, 2021	SYSTEM	\$3,086.82	Reference Item Price Adjustment Index Adjustment Type applied is FUEL													
			- Total				\$6,835.94														
	Price - Total						\$6,835.94														
0050 -	Total						\$6,835.94														
0060	COMPACTING EMBANKMENT	Material		5	Sep 16, 2020	SYSTEM	(\$74,940.00)														
				5	Sep 16, 2020	SYSTEM	\$74,940.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.													
				6	Oct 1, 2020	SYSTEM	(\$74,940.00)														
				6	Oct 1, 2020	SYSTEM	\$74,940.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.													
				7	Oct 16, 2020	SYSTEM	(\$112,440.00)														
				7	Oct 16, 2020	SYSTEM	\$112,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.													
				8	Nov 2, 2020	SYSTEM	(\$112,440.00)														
				8	Nov 2, 2020	SYSTEM	\$112,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate.													
				9	Nov 16, 2020	SYSTEM	(\$157,440.00)														
				9	Nov 16, 2020	SYSTEM	\$157,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate.													
				10	Dec 2, 2020	SYSTEM	(\$166,440.00)														
				10	Dec 2, 2020	SYSTEM	\$166,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.													
				11	Dec 16, 2020	SYSTEM	(\$195,990.00)														
				11	Dec 16, 2020	SYSTEM	\$195,990.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user schlag1 overridding Payment Estimate Exception 1 on the current Payment Estimate.													
				12	Jan 4, 2021	SYSTEM	(\$195,990.00)														
				12	Jan 4, 2021	SYSTEM	\$195,990.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.													
						1									1	13	13	Jan 19, 2021	SYSTEM	(\$195,990.00)	
						13	Jan 19, 2021	SYSTEM	\$195,990.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schlag1 overridding Payment Estimate Exception 1 on the current Payment Estimate.											

Revision 4/1/2020 Page 19 of 37



								_ ,					
Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks					
0060	COMPACTING EMBANKMENT	Material		14	Feb 2, 2021	SYSTEM	(\$197,490.00)						
				14	Feb 2, 2021	SYSTEM	\$197,490.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate.					
			- Total				\$0.00						
	Material - Total						\$0.00						
0060 -	- Total						\$0.00						
0210	TYPE A2 SHOULDER	Material		6	Oct 1, 2020	SYSTEM	(\$14,241.60)						
				6	Oct 1, 2020	SYSTEM	\$14,241.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user kloepj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.					
				7	Oct 16, 2020	SYSTEM	(\$14,241.60)						
				7	Oct 16, 2020	SYSTEM	\$14,241.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user kloepj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.					
				8	Nov 2, 2020	SYSTEM	(\$14,241.60)						
				8	Nov 2, 2020	SYSTEM	\$14,241.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user hillt5 overridding Payment Estimate Exception 6 on the current Payment Estimate.					
				9	Nov 16, 2020	SYSTEM	(\$14,241.60)						
				9	Nov 16, 2020	SYSTEM	\$14,241.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user hillt5 overridding Payment Estimate Exception 6 on the current Payment Estimate.					
					10	Dec 2, 2020	SYSTEM	(\$14,880.96)					
				10	Dec 2, 2020	SYSTEM	\$14,880.96	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user kloepj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.					
				11	Dec 16, 2020	SYSTEM	(\$14,880.96)						
				11	Dec 16, 2020	SYSTEM	\$14,880.96	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user schlag1 overridding Payment Estimate Exception 6 on the current Payment Estimate.					
				12	Jan 4, 2021	SYSTEM	(\$14,880.96)						
									12	Jan 4, 2021	SYSTEM	\$14,880.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				13	Jan 19, 2021	SYSTEM	(\$14,880.96)						
				13	Jan 19, 2021	SYSTEM	\$14,880.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schlag1 overridding Payment Estimate Exception 6 on the current Payment Estimate.					
				14	Feb 2, 2021	SYSTEM	(\$14,880.96)						
				14	Feb 2, 2021	SYSTEM	\$14,880.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hillt5 overridding Payment Estimate Exception 6 on the current Payment Estimate.					
			- Total				\$0.00						
	Material - Total						\$0.00						
0210 -	- Total						\$0.00						
0270	WATER	Construction Stockpile		6	Oct 1, 2020	SYSTEM	\$75,319.80	Payment Estimate Item Adjustment generated Stockpile Transaction					
				11	Dec 16, 2020	SYSTEM	(\$43,011.57)	Payment Estimate Item Adjustment generated Stockpile Transaction					
				13	Jan 19, 2021	SYSTEM	(\$8,549.46)	Payment Estimate Item Adjustment generated Stockpile Transaction					
			- Total				\$23,758.77						
	Construction Stockpile - Tota						\$23,758.77						
0270 -	- Total						\$23,758.77						

Revision 4/1/2020 Page 20 of 37



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																					
0280	WATER	Construction Stockpile	. 71-	6	Oct 1, 2020	SYSTEM	\$13,214.00	Payment Estimate Item Adjustment generated Stockpile Transaction																					
		·		11	Dec 16, 2020	SYSTEM	(\$13,214.00)	Payment Estimate Item Adjustment generated Stockpile Transaction																					
			- Total				\$0.00																						
	Construction Stockpile - Tota						\$0.00																						
0280 -	· Total						\$0.00																						
0675	CONCRETE TRAFFIC BARRIER, TYPE C	Material		3	Aug 17, 2020	SYSTEM	(\$36,830.00)																						
				3	Aug 17, 2020	SYSTEM	\$36,830.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																					
				4	Sep 2, 2020	SYSTEM	(\$36,830.00)																						
				4	Sep 2, 2020	SYSTEM	\$36,830.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																					
				5	Sep 16, 2020	SYSTEM	(\$36,830.00)																						
					5	Sep 16, 2020	SYSTEM	\$36,830.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.																				
				6	Oct 1, 2020	SYSTEM	(\$66,845.00)																						
				6	Oct 1, 2020	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.																					
				7	Oct 16, 2020	SYSTEM	(\$66,845.00)																						
				7	Oct 16, 2020	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.																					
					8	Nov 2, 2020	SYSTEM	(\$66,845.00)																					
				8	Nov 2, 2020	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user hillt5 overridding Payment Estimate Exception 14 on the current Payment Estimate.																					
									9	Nov 16, 2020	SYSTEM	(\$66,845.00)																	
							9	Nov 16, 2020	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user hillt5 overridding Payment Estimate Exception 14 on the current Payment Estimate.																		
																	10	Dec 2, 2020	SYSTEM	(\$66,845.00)									
				10	Dec 2, 2020	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.																					
						11	Dec 16, 2020	SYSTEM	(\$66,845.00)																				
																		11	Dec 16, 2020	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user schlag1 overridding Payment Estimate Exception 14 on the current Payment Estimate.							
																		12	Jan 4, 2021	SYSTEM	(\$66,845.00)								
																									12	Jan 4, 2021	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kloepj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
				13	Jan 19, 2021	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schlag1 overridding Payment Estimate Exception 14 on the current Payment Estimate.																					
				14	Feb 2, 2021	SYSTEM	(\$66,845.00)																						
				14	Feb 2, 2021	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hillt5 overridding Payment Estimate Exception 13 on the current Payment Estimate.																					

Revision 4/1/2020 Page 21 of 37



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																									
0675		Material	- Total				\$0.00																										
	Material - Total						\$0.00																										
0675 -	Total						\$0.00																										
0690	CONCRETE TRAFFIC BARRIER, TYPE D	Material		6	Oct 1, 2020	SYSTEM	(\$15,385.00)																										
	(RETAINING WALL)			6	Oct 1, 2020	SYSTEM	\$15,385.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.																									
				7	Oct 16, 2020	SYSTEM	(\$51,935.00)																										
				7	Oct 16, 2020	SYSTEM	\$51,935.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.																									
				8	Nov 2, 2020	SYSTEM	(\$78,625.00)																										
							8	Nov 2, 2020	SYSTEM	\$78,625.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user hillt5 overridding Payment Estimate Exception 17 on the current Payment Estimate.																						
				9	Nov 16, 2020	SYSTEM	(\$79,900.00)																										
				9	Nov 16, 2020	SYSTEM	\$79,900.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user hillt5 overridding Payment Estimate Exception 17 on the current Payment Estimate.																									
				10	Dec 2, 2020	SYSTEM	(\$148,325.00)																										
				10	Dec 2, 2020	SYSTEM	\$148,325.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.																									
				11	Dec 16, 2020	SYSTEM	(\$148,325.00)																										
				11	Dec 16, 2020	SYSTEM	\$148,325.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user schlag1 overridding Payment Estimate Exception 17 on the current Payment Estimate.																									
							12	Jan 4, 2021	SYSTEM	(\$148,325.00)																							
					12	Jan 4, 2021	SYSTEM	\$148,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.																								
											13	Jan 19, 2021	SYSTEM	(\$148,325.00)																			
									13	Jan 19, 2021	SYSTEM	\$148,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schlag1 overridding Payment Estimate Exception 17 on the current Payment Estimate.																				
				14	Feb 2, 2021	SYSTEM	(\$148,325.00)																										
				14	Feb 2, 2021	SYSTEM	\$148,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hillt5 overridding Payment Estimate Exception 16 on the current Payment Estimate.																									
			- Total				\$0.00																										
	Material - Total						\$0.00																										
0690 -	Total						\$0.00																										
0990	MISC. Miscellaneous Granular Drainage Blanket	Material		6	Oct 1, 2020	SYSTEM	(\$11,470.00)																										
																													6	Oct 1, 2020	SYSTEM	\$11,470.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
				7	Oct 16, 2020	SYSTEM	(\$32,782.50)																										
				1											7			7	7	7			7		7	7	7	7	Oct 16, 2020	SYSTEM	\$32,782.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 25 on the current Payment Estimate.	
																	8	Nov 2, 2020	SYSTEM	(\$32,782.50)													
					8	Nov 2, 2020	SYSTEM	\$32,782.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user hillt5 overridding Payment Estimate Exception 20 on the current Payment Estimate.																								

Revision 4/1/2020 Page 22 of 37



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																							
0990	MISC. Miscellaneous Granular Drainage Blanket	Material	3.	9	Nov 16, 2020	SYSTEM	(\$32,782.50)																								
				9	Nov 16, 2020	SYSTEM	\$32,782.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user hillts overridding Payment Estimate Exception 20 on the current Payment Estimate.																							
				10	Dec 2, 2020	SYSTEM	(\$37,215.50)																								
				10	Dec 2, 2020	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.																							
				11	Dec 16, 2020	SYSTEM	(\$37,215.50)																								
				11	Dec 16, 2020	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user schlag1 overridding Payment Estimate Exception 19 on the current Payment Estimate.																							
				12	Jan 4, 2021	SYSTEM	(\$37,215.50)																								
					12	Jan 4, 2021	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.																						
				13	Jan 19, 2021	SYSTEM	(\$37,215.50)																								
				13	Jan 19, 2021	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schlag1 overridding Payment Estimate Exception 19 on the current Payment Estimate.																							
								14	14 Feb 2, 2021 (\$37,215.50)																						
				14	Feb 2, 2021	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 18 on the current Payment Estimate.																							
			- Total			\$0.00																									
	Material - Total						\$0.00																								
0990 -	· Total						\$0.00																								
1050	MISC. Miscellaneous Stone Columns	Material	Material	Material	Material		8	Nov 2, 2020	SYSTEM	(\$23,800.00)																					
				8	Nov 2, 2020	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user hillt5 overridding Payment Estimate Exception 21 on the current Payment Estimate.																							
										9	Nov 16, 2020	SYSTEM	(\$23,800.00)																		
					9	Nov 16, 2020	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user hillt5 overridding Payment Estimate Exception 21 on the current Payment Estimate.																						
												10	Dec 2, 2020	SYSTEM	(\$23,800.00)																
																											10	Dec 2, 2020	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
																							11	Dec 16, 2020	SYSTEM	(\$23,800.00)					
																				11	Dec 16, 2020	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user schlag1 overridding Payment Estimate Exception 20 on the current Payment Estimate.							
																												12	Jan 4, 2021	SYSTEM	(\$23,800.00)
		13		12	Jan 4, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kloepj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.																							
			13	13															13	Jan 19, 2021	SYSTEM	(\$23,800.00)									
																	1	1			1:	13	13	Jan 19, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schlag1 overridding Payment Estimate Exception 20 on the current Payment Estimate.				
						14	Feb 2, 2021	SYSTEM	(\$23,800.00)																						
						14	Feb 2, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hillt5 overridding Payment Estimate Exception 31 on the current Payment Estimate.																					

Revision 4/1/2020 Page 23 of 37



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																																				
1050		Material	- Total				\$0.00																																					
	Material - Total						\$0.00																																					
1050 -	Total						\$0.00																																					
1090	MECHANICALLY	Material		7	Oct 16,	SYSTEM	(\$203,640.00)																																					
	STABILIZED EARTH WALL SYSTEMS			7	2020 Oct 16, 2020	SYSTEM	\$203,640.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment																																				
				8	Nov 2, 2020	SYSTEM	(\$203,640.00)	Estimate Exception 26 on the current Payment Estimate.																																				
				8	Nov 2, 2020	SYSTEM	\$203,640.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user hillt5 overridding Payment Estimate Exception 26 on the current Payment Estimate.																																				
				9	Nov 16, 2020	SYSTEM	(\$203,640.00)																																					
							9	Nov 16, 2020	SYSTEM	\$203,640.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user hillt5 overridding Payment Estimate Exception 26 on the current Payment Estimate.																																	
						10	Dec 2, 2020	SYSTEM	(\$203,640.00)																																			
				10	Dec 2, 2020	SYSTEM	\$203,640.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.																																				
					11	Dec 16, 2020	SYSTEM	(\$203,640.00)																																				
				11	Dec 16, 2020	SYSTEM	\$203,640.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user schlag1 overridding Payment Estimate Exception 24 on the current Payment Estimate.																																				
				12	Jan 4, 2021	SYSTEM	(\$203,640.00)																																					
				12	Jan 4, 2021	SYSTEM	\$203,640.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.																																				
									13	Jan 19, 2021	SYSTEM	(\$203,640.00)																																
				13	Jan 19, 2021	SYSTEM	\$203,640.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schlag1 overridding Payment Estimate Exception 21 on the current Payment Estimate.																																				
											14	Feb 2, 2021	SYSTEM	(\$203,640.00)																														
				14	Feb 2, 2021	SYSTEM	\$203,640.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hillt5 overridding Payment Estimate Exception 49 on the current Payment Estimate.																																				
			- Total				\$0.00																																					
	Material - Total						\$0.00																																					
1090 -	Total						\$0.00																																					
1100	SELECT GRANULAR BACKFILL FOR STRUCTURAL SYSTEMS	Material		7	Oct 16, 2020	SYSTEM	(\$41,310.00)																																					
	STRUCTURAL STSTEMS															1	1 1 1	12				7	Oct 16, 2020	SYSTEM	\$41,310.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.																		
																			11	Dec 16, 2020	SYSTEM	(\$256,560.00)																						
																						1										11	Dec 16, 2020	SYSTEM	\$256,560.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user schlag1 overridding Payment Estimate Exception 26 on the current Payment Estimate.								
																							12	Jan 4, 2021	SYSTEM	(\$256,560.00)																		
																															12									12	Jan 4, 2021	SYSTEM	\$256,560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
																																13	Jan 19, 2021	SYSTEM	(\$256,560.00)									
				13	Jan 19, 2021	SYSTEM	\$256,560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schlag1 overridding Payment Estimate Exception 24 on the current Payment Estimate.																																				

Revision 4/1/2020 Page 24 of 37



	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1100	SELECT GRANULAR BACKFILL FOR	Material		14	Feb 2, 2021	SYSTEM	(\$256,560.00)	
	STRUCTURAL SYSTEMS			14	Feb 2, 2021	SYSTEM	\$256,560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hillt5 overridding Payment Estimate Exception 52 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1100 -	- Total						\$0.00	
1160	MISC. MSD SPECIAL DRAINAGE STRUCTURE #"301"	Material		9	Nov 16, 2020	SYSTEM	(\$49,500.00)	
	,, 00.			9	Nov 16, 2020	SYSTEM	\$49,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user hillt5 overridding Payment Estimate Exception 29 on the current Payment Estimate.
				10	Dec 2, 2020	SYSTEM	(\$55,000.00)	
				10	Dec 2, 2020	SYSTEM	\$55,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
				11	Dec 16, 2020	SYSTEM	(\$55,000.00)	
				11	Dec 16, 2020	SYSTEM	\$55,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user schlag1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
				12	Jan 4, 2021	SYSTEM	(\$55,000.00)	
				12	Jan 4, 2021	SYSTEM	\$55,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
				13	Jan 19, 2021	SYSTEM	(\$55,000.00)	
				13	Jan 19, 2021	SYSTEM	\$55,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schlag1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total		- Total				\$0.00 \$0.00	
1160 -	Material - Total - Total		- Total					
1160 - 1170		Material	- Total	3	Aug 17, 2020	SYSTEM	\$0.00	
	- Total PRECAST CONCRETE	Material	- Total	3		SYSTEM	\$0.00 \$0.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user kloep/1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
	- Total PRECAST CONCRETE	Material	- Total		2020 Aug 17,		\$0.00 \$0.00 (\$2,450.00)	Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment
	- Total PRECAST CONCRETE	Material	- Total	3	2020 Aug 17, 2020 Sep 2,	SYSTEM	\$0.00 \$0.00 (\$2,450.00) \$2,450.00	Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment
	- Total PRECAST CONCRETE	Material	- Total	3	2020 Aug 17, 2020 Sep 2, 2020 Sep 2,	SYSTEM SYSTEM	\$0.00 \$0.00 (\$2,450.00) \$2,450.00 (\$4,200.00)	Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment
	- Total PRECAST CONCRETE	Material	- Total	3 4 4	2020 Aug 17, 2020 Sep 2, 2020 Sep 2, 2020 Sep 16,	SYSTEM SYSTEM	\$0.00 \$0.00 (\$2,450.00) \$2,450.00 (\$4,200.00) \$4,200.00	Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment
	- Total PRECAST CONCRETE	Material	- Total	3 4 4 5	2020 Aug 17, 2020 Sep 2, 2020 Sep 2, 2020 Sep 16, 2020 Sep 16,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$2,450.00) \$2,450.00 (\$4,200.00) \$4,200.00	Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment
	- Total PRECAST CONCRETE	Material	- Total	3 4 4 5 5	2020 Aug 17, 2020 Sep 2, 2020 Sep 2, 2020 Sep 16, 2020 Sep 16, 2020 Oct 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$2,450.00) \$2,450.00 (\$4,200.00) \$4,200.00 (\$4,200.00)	Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment
	- Total PRECAST CONCRETE	Material	- Total	3 4 4 5 5 5 6	2020 Aug 17, 2020 Sep 2, 2020 Sep 2, 2020 Sep 16, 2020 Oct 1, 2020 Oct 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$2,450.00) \$2,450.00 (\$4,200.00) \$4,200.00 (\$4,200.00) (\$4,200.00)	Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment
	- Total PRECAST CONCRETE	Material	- Total	3 4 4 5 5 6 6 6	2020 Aug 17, 2020 Sep 2, 2020 Sep 2, 2020 Sep 16, 2020 Oct 1, 2020 Oct 1, 2020 Oct 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$2,450.00) \$2,450.00 (\$4,200.00) \$4,200.00 (\$4,200.00) \$4,200.00 \$4,200.00	Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment
	- Total PRECAST CONCRETE	Material	- Total	3 4 4 5 5 6 6 7 7	2020 Aug 17, 2020 Sep 2, 2020 Sep 16, 2020 Sep 16, 2020 Oct 1, 2020 Oct 16, 2020 Oct 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$2,450.00) \$2,450.00 (\$4,200.00) \$4,200.00 (\$4,200.00) \$4,200.00 (\$4,200.00)	Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment
	- Total PRECAST CONCRETE	Material		3 4 4 5 5 6 6 7 7	2020 Aug 17, 2020 Sep 2, 2020 Sep 16, 2020 Sep 16, 2020 Oct 1, 2020 Oct 16, 2020 Oct 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$2,450.00) \$2,450.00 (\$4,200.00) \$4,200.00 (\$4,200.00) \$4,200.00 (\$4,200.00) \$4,200.00	Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment
1170	PRECAST CONCRETE DROP INLET 2 FT X 2 FT	Material		3 4 4 5 5 6 6 7 7	2020 Aug 17, 2020 Sep 2, 2020 Sep 16, 2020 Sep 16, 2020 Oct 1, 2020 Oct 16, 2020 Oct 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$2,450.00) \$2,450.00 (\$4,200.00) \$4,200.00 (\$4,200.00) \$4,200.00 (\$4,200.00) \$4,200.00 \$4,200.00 \$4,200.00	Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment

Revision 4/1/2020 Page 25 of 37



	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
1180	PRECAST CONCRETE DROP INLET 4 FT X 2 FT	Material	Туре	3	Aug 17, 2020	SYSTEM	\$8,100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				4	Sep 2, 2020	SYSTEM	(\$8,550.00)	Estimate Exception 6 on the current rayment Estimate.
				4	Sep 2, 2020	SYSTEM	\$8,550.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				5	Sep 16, 2020	SYSTEM	(\$8,550.00)	
				5	Sep 16, 2020	SYSTEM	\$8,550.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					6	Oct 1, 2020	SYSTEM	(\$8,550.00)
				6	Oct 1, 2020	SYSTEM	\$8,550.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1180	·Total						\$0.00	
1190	PRECAST CONCRETE DROP INLET 5 FT X 3 FT	Material		6	Oct 1, 2020	SYSTEM	(\$1,950.00)	
				6	Oct 1, 2020	SYSTEM	\$1,950.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
				7	Oct 16, 2020	SYSTEM	(\$15,600.00)	
				7	Oct 16, 2020	SYSTEM	\$15,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1190 -	Material - Total · Total						\$0.00 \$0.00	
1190 - 1200		Material		3	Aug 17, 2020	SYSTEM		
	Total MISC. MSD Standard 60"	Material		3		SYSTEM SYSTEM	\$0.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
	Total MISC. MSD Standard 60"	Material			2020 Aug 17,		\$0.00 (\$5,610.00)	Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment
	Total MISC. MSD Standard 60"	Material		3	2020 Aug 17, 2020 Sep 2,	SYSTEM	\$0.00 (\$5,610.00) \$5,610.00	Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment
	Total MISC. MSD Standard 60"	Material		3	2020 Aug 17, 2020 Sep 2, 2020 Sep 2,	SYSTEM SYSTEM	\$0.00 (\$5,610.00) \$5,610.00 (\$5,610.00)	Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment
	Total MISC. MSD Standard 60"	Material		3 4 4	2020 Aug 17, 2020 Sep 2, 2020 Sep 2, 2020 Sep 16,	SYSTEM SYSTEM	\$0.00 (\$5,610.00) \$5,610.00 (\$5,610.00) \$5,610.00	Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment
	Total MISC. MSD Standard 60"	Material		3 4 4 5	2020 Aug 17, 2020 Sep 2, 2020 Sep 2, 2020 Sep 16, 2020 Sep 16,	SYSTEM SYSTEM SYSTEM	\$0.00 (\$5,610.00) \$5,610.00 (\$5,610.00) \$5,610.00	Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment
	Total MISC. MSD Standard 60"	Material		3 4 4 5 5	2020 Aug 17, 2020 Sep 2, 2020 Sep 2, 2020 Sep 16, 2020 Sep 16, 2020 Oct 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$5,610.00) \$5,610.00 (\$5,610.00) \$5,610.00 (\$5,610.00)	Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment
	Total MISC. MSD Standard 60"	Material		3 4 4 5 5 6	2020 Aug 17, 2020 Sep 2, 2020 Sep 2, 2020 Sep 16, 2020 Oct 1, 2020 Oct 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$5,610.00) \$5,610.00 (\$5,610.00) \$5,610.00 (\$5,610.00) \$5,610.00	Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment
	Total MISC. MSD Standard 60"	Material		3 4 4 5 5 6 6	2020 Aug 17, 2020 Sep 2, 2020 Sep 16, 2020 Sep 16, 2020 Oct 1, 2020 Oct 1, 2020 Oct 16, 4	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$5,610.00) \$5,610.00 (\$5,610.00) \$5,610.00 (\$5,610.00) \$5,610.00 (\$10,710.00)	Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment
	Total MISC. MSD Standard 60"	Material	- Total	3 4 4 5 5 6 6 7 7	2020 Aug 17, 2020 Sep 2, 2020 Sep 16, 2020 Oct 1, 2020 Oct 16, 2020 Oct 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$5,610.00) \$5,610.00 (\$5,610.00) \$5,610.00 (\$5,610.00) (\$10,710.00) (\$10,710.00)	Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 30 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Exception 30 on the current Payment Estimate.
	Total MISC. MSD Standard 60"	Material	- Total	3 4 4 5 5 6 6 7 7	2020 Aug 17, 2020 Sep 2, 2020 Sep 16, 2020 Oct 1, 2020 Oct 16, 2020 Oct 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$5,610.00) \$5,610.00 (\$5,610.00) \$5,610.00 (\$5,610.00) \$5,610.00 (\$10,710.00) \$10,710.00	Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 30 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Exception 30 on the current Payment Estimate.
1200	MISC. MSD Standard 60" Manhole	Material	- Total	3 4 4 5 5 6 6 7 7	2020 Aug 17, 2020 Sep 2, 2020 Sep 16, 2020 Oct 1, 2020 Oct 16, 2020 Oct 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$5,610.00) \$5,610.00 (\$5,610.00) \$5,610.00 (\$5,610.00) \$5,610.00 (\$10,710.00) \$10,710.00 \$10,710.00	Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 30 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Exception 30 on the current Payment Estimate.
1200	MISC. MSD Standard 60" Manhole	Material	- Total	3 4 4 5 5 6 6 7 7	2020 Aug 17, 2020 Sep 2, 2020 Sep 16, 2020 Oct 1, 2020 Oct 16, 2020 Oct 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$5,610.00) \$5,610.00 (\$5,610.00) \$5,610.00 (\$5,610.00) \$5,610.00 (\$10,710.00) \$10,710.00 \$10,710.00 \$0.00	Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 30 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Exception 30 on the current Payment Estimate.

Revision 4/1/2020 Page 26 of 37



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																																				
1210	MISC. MSD Standard Line	Material						Estimate Exception 29 on the current Payment Estimate.																																				
	48" Manhole			7	Oct 16, 2020	SYSTEM	(\$12,950.00)																																					
				7	Oct 16, 2020	SYSTEM	\$12,950.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.																																				
				12	Jan 4, 2021	SYSTEM	(\$1,750.00)																																					
				12	Jan 4, 2021	SYSTEM	\$1,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.																																				
				13	Jan 19, 2021	SYSTEM	(\$1,750.00)																																					
				13	Jan 19, 2021	SYSTEM	\$1,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schlag1 overridding Payment Estimate Exception 26 on the current Payment Estimate.																																				
				14	Feb 2, 2021	SYSTEM	(\$1,750.00)																																					
				14	Feb 2, 2021	SYSTEM	\$1,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hillto overridding Payment Estimate Exception 53 on the current Payment Estimate.																																				
			- Total				\$0.00																																					
	Material - Total						\$0.00																																					
1210 -	Total						\$0.00																																					
1220	15 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	Material		6	Oct 1, 2020	SYSTEM	(\$800.00)																																					
	FLARED END SECTION				6	Oct 1, 2020	SYSTEM	\$800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.																																			
									7	Oct 16, 2020	SYSTEM	(\$1,600.00)																																
				7	Oct 16, 2020	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 34 on the current Payment Estimate.																																				
							8	Nov 2, 2020	SYSTEM	(\$1,600.00)																																		
				8	Nov 2, 2020	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user hillt5 overridding Payment Estimate Exception 29 on the current Payment Estimate.																																				
																		9	Nov 16, 2020	SYSTEM	(\$1,600.00)																							
					9 10 10 11															9	Nov 16, 2020	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user hillt5 overridding Payment Estimate Exception 30 on the current Payment Estimate.																				
						10	Dec 2, 2020	SYSTEM	(\$1,600.00)																																			
																																				10	Dec 2, 2020	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user kloepj1 overridding Payment Estimate Exception 30 on the current Payment Estimate.				
																		11	Dec 16, 2020	SYSTEM	(\$1,600.00)																							
																							11	11	Dec 16, 2020	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user schlag1 overridding Payment Estimate Exception 28 on the current Payment Estimate.																
				12	Jan 4, 2021	SYSTEM	(\$1,600.00)																																					
													12																											12	Jan 4, 2021	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kloepj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
																					13	Jan 19, 2021	SYSTEM	(\$1,600.00)																				
				13	Jan 19, 2021	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schlag1 overridding Payment Estimate Exception 28 on the current Payment Estimate.																																				
		- Total				\$0.00																																						
	Material - Total						\$0.00																																					

Revision 4/1/2020 Page 27 of 37



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																				
1220 -	· Total		31				\$0.00																					
1290	ROCK DITCH CHECK	Material		4	Sep 2, 2020	SYSTEM	(\$252.00)																					
				4	Sep 2, 2020	SYSTEM	\$252.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.																				
				5	Sep 16, 2020	SYSTEM	(\$252.00)																					
								5	Sep 16, 2020	SYSTEM	\$252.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.																
				6	Oct 1, 2020	SYSTEM	(\$252.00)																					
					6	Oct 1, 2020	SYSTEM	\$252.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.																			
							7	Oct 16, 2020	SYSTEM	(\$252.00)																		
					7	Oct 16, 2020	SYSTEM	\$252.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Exception 35 on the current Payment Estimate.																			
					8	Nov 2, 2020	SYSTEM	(\$252.00)																				
							8	Nov 2, 2020	SYSTEM	\$252.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 30 on the current Payment Estimate.																	
								9	Nov 16, 2020	SYSTEM	(\$252.00)																	
				9	Nov 16, 2020	SYSTEM	\$252.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 31 on the current Payment Estimate.																				
			10	Dec 2, 2020	SYSTEM	(\$252.00)																						
				10	Dec 2, 2020	SYSTEM	\$252.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user kloepj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.																				
						11	Dec 16, 2020	SYSTEM	(\$252.00)																			
				11	Dec 16, 2020	SYSTEM	\$252.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user schlag1 overridding Payment Estimate Exception 29 on the current Payment Estimate.																				
										12	Jan 4, 2021	SYSTEM	(\$252.00)															
														1	1					13	12	Jan 4, 2021	SYSTEM	\$252.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user kloepj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.			
																					13	Jan 19, 2021	SYSTEM	(\$252.00)				
																											13	Jan 19, 2021
																		14	Feb 2, 2021	SYSTEM	(\$252.00)							
				14	Feb 2, 2021	SYSTEM	\$252.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 55 on the current Payment Estimate.																				
			- Total				\$0.00																					
	Material - Total						\$0.00																					
1290 -	·Total						\$0.00																					
1330	SILT FENCE	Material		4	Sep 2, 2020	SYSTEM	(\$4,506.75)																					
				5	4	4	4	Sep 2, 2020	SYSTEM	\$4,506.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.																	
					5	Sep 16, 2020	SYSTEM	(\$4,506.75)																				
				5	Sep 16,	SYSTEM	\$4,506.75	This adjustment offsets the original system-generated Overrun Payment																				

Revision 4/1/2020 Page 28 of 37



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks															
1330	SILT FENCE	Material			2020			Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.															
				6	Oct 1, 2020	SYSTEM	(\$4,506.75)																
				6	Oct 1, 2020	SYSTEM	\$4,506.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.															
				7	Oct 16, 2020	SYSTEM	(\$4,506.75)																
				7	Oct 16, 2020	SYSTEM	\$4,506.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user kloepj1 overridding Payment Estimate Exception 36 on the current Payment Estimate.															
			- Total				\$0.00																
	Material - Total						\$0.00																
330 -	Total						\$0.00																
1490	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		5	Sep 16, 2020	SYSTEM	(\$12,444.25)																
				5	Sep 16, 2020	SYSTEM	\$12,444.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.															
				6	Oct 1, 2020	SYSTEM	(\$14,110.85)																
				6	Oct 1, 2020	SYSTEM	\$14,110.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.															
									7	Oct 16, 2020	SYSTEM	(\$17,094.16)											
					7	Oct 16, 2020	SYSTEM	\$17,094.16	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.														
				8	Nov 2, 2020	SYSTEM	(\$17,094.16)																
				8	Nov 2, 2020	SYSTEM	\$17,094.16	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user hillt5 overridding Payment Estimate Exception 2 on the current Payment Estimate.															
												9	Nov 16, 2020	SYSTEM	(\$17,094.16)								
						9	Nov 16, 2020	SYSTEM	\$17,094.16	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user hillt5 overridding Payment Estimate Exception 2 on the current Payment Estimate.													
				10	Dec 2, 2020	SYSTEM	(\$17,094.16)																
				10	Dec 2, 2020	SYSTEM	\$17,094.16	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.															
				11	Dec 16, 2020	SYSTEM	(\$17,094.16)																
				11	Dec 16, 2020	SYSTEM	\$17,094.16	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user schlag1 overridding Payment Estimate Exception 2 on the current Payment Estimate.															
				12	Jan 4, 2021	SYSTEM	(\$17,094.16)																
																			12	Jan 4, 2021	SYSTEM	\$17,094.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user kloepj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
																			13	Jan 19, 2021	SYSTEM	(\$17,094.16)	
				13	Jan 19, 2021	SYSTEM	\$17,094.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schlag1 overridding Payment Estimate Exception 2 on the current Payment Estimate.															
				14	Feb 2, 2021	SYSTEM	(\$17,094.16)																
				14	Feb 2, 2021	SYSTEM	\$17,094.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hillts overridding Payment Estimate Exception 2 on the current Payment Estimate.															
			- Total				\$0.00																
	Material - Total						\$0.00																

Revision 4/1/2020 Page 29 of 37



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks											
1490	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Price		5	Sep 16, 2020	SYSTEM	\$167.33	Reference Item Price Adjustment Index Adjustment Type applied is FUEL											
				6	Oct 1, 2020	SYSTEM	\$22.41	Reference Item Price Adjustment Index Adjustment Type applied is FUEL											
				7	Oct 16, 2020	SYSTEM	\$33.78	Reference Item Price Adjustment Index Adjustment Type applied is FUEL											
			- Total				\$223.52												
	Price - Total						\$223.52												
1490 -	Total						\$223.52												
1510	CONCRETE PAVEMENT (9 IN. NON-REINFORCED 15	Material		5	Sep 16, 2020	SYSTEM	(\$49,717.80)												
	FT. JOINTS)			5	Sep 16, 2020	SYSTEM	\$49,717.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user kloepj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.											
				6	Oct 1, 2020	SYSTEM	(\$63,768.60)												
					6	Oct 1, 2020	SYSTEM	\$63,768.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user kloepj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.										
					7	Oct 16, 2020	SYSTEM	(\$68,002.20)											
							7	Oct 16, 2020	SYSTEM	\$68,002.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user kloepj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.								
											8	Nov 2, 2020	SYSTEM	(\$68,002.20)					
					8	Nov 2, 2020	SYSTEM	\$68,002.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate.										
						9	Nov 16, 2020	SYSTEM	(\$68,002.20)										
							9	Nov 16, 2020	SYSTEM	\$68,002.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate.								
						10	Dec 2, 2020	SYSTEM	(\$68,002.20)										
						10	Dec 2, 2020	SYSTEM	\$68,002.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.									
					11	Dec 16, 2020	SYSTEM	(\$68,002.20)											
				11	Dec 16, 2020	SYSTEM	\$68,002.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user schlag1 overridding Payment Estimate Exception 3 on the current Payment Estimate.											
							12 12 13	12	Jan 4, 2021	SYSTEM	(\$68,002.20)								
										12	Jan 4, 2021	SYSTEM	\$68,002.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.					
															13	Jan 19, 2021	SYSTEM	\$68,002.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schlag1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
												14	Feb 2, 2021	SYSTEM	(\$68,002.20)				
				14	Feb 2, 2021	SYSTEM	\$68,002.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate.											
			- Total				\$0.00												
	Material - Total						\$0.00												
	CONCRETE PAVEMENT (9 IN. NON-REINFORCED 15	Price		5	Sep 16, 2020	SYSTEM	\$230.91	Reference Item Price Adjustment Index Adjustment Type applied is FUEL											
	FT. JOINTS)				6	6	Oct 1, 2020	SYSTEM	\$65.26	Reference Item Price Adjustment Index Adjustment Type applied is FUEL									
																7	Oct 16,	SYSTEM	\$16.56

Revision 4/1/2020 Page 30 of 37



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
1510	CONCRETE PAVEMENT (9 IN. NON-REINFORCED 15 FT. JOINTS)	Price			2020						
			- Total				\$312.73				
	Price - Total						\$312.73				
1510 -	Total						\$312.73				
1550	550 TYPE A2 SHOULDER	Material		6	Oct 1, 2020	SYSTEM	(\$14,224.00)				
					6	Oct 1, 2020	SYSTEM	\$14,224.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.		
				7	Oct 16, 2020	SYSTEM	(\$30,287.95)				
				7	Oct 16, 2020	SYSTEM	\$30,287.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.			
				8	Nov 2, 2020	SYSTEM	(\$30,287.95)				
					8	Nov 2, 2020	SYSTEM	\$30,287.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user hillt5 overridding Payment Estimate Exception 8 on the current Payment Estimate.		
				9	Nov 16, 2020	SYSTEM	(\$30,287.95)				
					9	Nov 16, 2020	SYSTEM	\$30,287.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user hillt5 overridding Payment Estimate Exception 8 on the current Payment Estimate.		
					10	Dec 2, 2020	SYSTEM	(\$30,287.95)			
				10	Dec 2, 2020	SYSTEM	\$30,287.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user kloepj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.			
				11	Dec 16, 2020	SYSTEM	(\$30,287.95)				
						11	Dec 16, 2020	SYSTEM	\$30,287.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user schlag1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	
				12	Jan 4, 2021	SYSTEM	(\$30,287.95)				
				12	Jan 4, 2021	SYSTEM	\$30,287.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.			
				13	Jan 19, 2021	SYSTEM	(\$30,287.95)				
							13	Jan 19, 2021	SYSTEM	\$30,287.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schlag1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
								14	Feb 2, 2021	SYSTEM	(\$30,287.95)
				14	Feb 2, 2021	SYSTEM	\$30,287.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user hillt5 overridding Payment Estimate Exception 8 on the current Payment Estimate.			
			- Total				\$0.00				
	Material - Total						\$0.00				
1550 -	Total						\$0.00				
1560	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	Material		6	Oct 1, 2020	SYSTEM	(\$3,375.00)				
	A					6	Oct 1, 2020	SYSTEM	\$3,375.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user kloepj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	
						7	Oct 16, 2020	SYSTEM	(\$3,375.00)		
						7	Oct 16, 2020	SYSTEM	\$3,375.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user kloepj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	
				8	Nov 2, 2020	SYSTEM	(\$3,375.00)				

Revision 4/1/2020 Page 31 of 37



NTCGRAL CUIDS & IN.	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
9	1560	HEIGHT AND UNDER) TYPE	Material	Турс	8		SYSTEM	\$3,375.00	Estimate Item Adjustment (0008) due to user hillt5 overridding Payment
2000					9		SYSTEM	(\$3,375.00)	
10					9		SYSTEM	\$3,375.00	Estimate Item Adjustment (0008) due to user hillt5 overridding Payment
1					10		SYSTEM	(\$3,375.00)	
11					10		SYSTEM	\$3,375.00	Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment
2020 SysTem Statistical Exception 10 on the current Payment Estimate Exception 11 on the current Payment Estimate Exception 10 on the current Payment					11		SYSTEM	(\$3,375.00)	
12					11		SYSTEM	\$3,375.00	Estimate Item Adjustment (0012) due to user schlag1 overridding Payment
2021 Section Estimate Exception 10 on the current Payment Estimate Estimate Exception 11 on the current Payment Estimate Estimate Exception 11 on the current Payment Estimate Estimate Exception 11 on the current Payment Estimate Estimate Exception 11 on the current Payment Estimate Estimate Exception 11 on the current Payment Estimate Estimate Exception 11 on the current Payment Estimate Estimate Exception 11 on the current Payment Estimate Estimate Exception 10 on the current Payment Estimate Estimate Exception 10 on the current Payment Estimate Exception 10 on the current Paym					12		SYSTEM	(\$3,375.00)	
2021					12		SYSTEM	\$3,375.00	Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment
2021					13		SYSTEM	(\$3,375.00)	
2021 14					13		SYSTEM	\$3,375.00	Estimate Item Adjustment (0020) due to user schlag1 overridding Payment
2021 Estimate Item Adjustment (0017) due to user hillst overridding Payment Estimate Exception 10 on the current Payment Estimate.					14		SYSTEM	(\$3,375.00)	
Material - Total					14		SYSTEM	\$3,375.00	Estimate Item Adjustment (0017) due to user hillt5 overridding Payment
Source S				- Total				\$0.00	
1570 MGS GUARDRAIL Construction Stockpile - Total	1560 -								
Total \$38,968.86					3		SYSTEM		Payment Estimate Item Adjustment generated Stockpile Transaction
1570 - Total 1580 MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB) - Total Construction Stockpile - Total 1580 - Total 1580 - Total MGS BRIDGE APPROACH (EXTENDED CURB) - Total Construction Stockpile - Total 1590 MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB) - Total - Total S3,016.00 Payment Estimate Item Adjustment generated Stockpile Transaction \$3,016.00 Payment Estimate Item Adjustment generated Stockpile Transaction \$2,920.00 Payment Estimate Item Adjustment generated Stockpile Transaction \$2,920.00 MGS VERTICAL CONCRETE BARRIER TRANSITION Stockpile - Total Construction Stockpile - Total 1600 - Total S13,915.00 Payment Estimate Item Adjustment generated Stockpile Transaction \$13,915.00 Payment Estimate Item Adjustment generated Stockpile Transaction				- Total				\$38,968.86	
MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB) Stockpile - Total S3,016.00 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile - Total S3,016.00		Construction Stockpile - Tota	ı					\$38,968.86	
TRANSITION SECTION (EXTENDED CURB) - Total - Total S3,016.00 Construction Stockpile - Total S3,016.00 Stockpile - Total S3,016.00 MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB) - Total - Total S2,920.00 Construction Stockpile - Total S2,920.00 S2,920.00 Construction Stockpile - Total S2,920.00 S3 Aug 17, SYSTEM S13,915.00 Construction Stockpile - Total S13,915.00 Payment Estimate Item Adjustment generated Stockpile Transaction S13,915.00 Payment Estimate Item Adjustment generated Stockpile Transaction S13,915.00 Payment Estimate Item Adjustment generated Stockpile Transaction	1570 -	Total						\$38,968.86	
Construction Stockpile - Total \$3,016.00 1580 - Total \$3,016.00 MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB) - Total \$2,920.00 Construction Stockpile - Total \$2,920.00 - Total \$2,920.00 System \$2,920.00 System \$2,920.00 Construction Stockpile - Total \$2,920.00 Construction Stockpile - Total \$13,915.00 Payment Estimate Item Adjustment generated Stockpile Transaction \$13,915.00	1580	TRANSITION SECTION			3		SYSTEM	\$3,016.00	Payment Estimate Item Adjustment generated Stockpile Transaction
1580 - Total S3,016.00 MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB) - Total Construction Stockpile - Total S2,920.00 Construction Stockpile - Total S2,920.00 Construction Stockpile - Total S2,920.00 S2,920.00 S2,920.00 S2,920.00 S2,920.00 Fayment Estimate Item Adjustment generated Stockpile Transaction				- Total					
MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB) - Total - Total S2,920.00 Construction Stockpile - Total S2,920.00 Construction Stockpile - Total S2,920.00 Construction Stockpile - Total S2,920.00 SYSTEM \$2,920.00 Construction Stockpile - Total S2,920.00 SYSTEM \$2,920.00 Payment Estimate Item Adjustment generated Stockpile Transaction \$2,920.00 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile - Total S13,915.00 Construction Stockpile - Total \$13,915.00 Construction Stockpile - Total \$13,915.00 MGS END ANCHOR Construction 3 Aug 17, SYSTEM \$13,915.00 Payment Estimate Item Adjustment generated Stockpile Transaction									
TRANSITION SECTION (REGULAR/NO CURB) - Total - Total S2,920.00 Construction Stockpile - Total S2,920.00 1590 - Total S2,920.00 1600 MGS VERTICAL CONCRETE BARRIER TRANSITION Stockpile - Total - Total SYSTEM S13,915.00 Construction Stockpile - Total S13,915.00 Construction Stockpile - Total S13,915.00 S13,915.00 Construction Stockpile - Total S13,915.00 Construction Stockpile - Total S13,915.00 Construction Stockpile - Total S13,915.00 Payment Estimate Item Adjustment generated Stockpile Transaction S13,915.00 Payment Estimate Item Adjustment generated Stockpile Transaction S13,915.00 Payment Estimate Item Adjustment generated Stockpile Transaction							a.v.===		
Construction Stockpile - Total \$2,920.00 1590 - Total \$2,920.00 MGS VERTICAL CONCRETE BARRIER TRANSITION Total - Total Construction Stockpile - Total \$13,915.00 Construction Stockpile - Total \$13,915.00 Construction Stockpile - Total \$13,915.00 Payment Estimate Item Adjustment generated Stockpile Transaction	1590	TRANSITION SECTION			3		SYSTEM		Payment Estimate Item Adjustment generated Stockpile Transaction
1590 - Total \$2,920.00 MGS VERTICAL CONCRETE BARRIER TRANSITION Stockpile - Total \$13,915.00 Construction Stockpile - Total \$13,915.00 Construction Stockpile - Total \$13,915.00 MGS END ANCHOR Construction 3 Aug 17, SYSTEM \$4,256.00 Payment Estimate Item Adjustment generated Stockpile Transaction \$13,915.00				- Total					
1600 MGS VERTICAL CONCRETE BARRIER TRANSITION Stockpile 3 Aug 17, 2020 SYSTEM \$13,915.00 Payment Estimate Item Adjustment generated Stockpile Transaction \$13,915.00 Construction Stockpile - Total \$13,915.00 Stockpile - Total Stockpile - T			ı						
BARRIER TRANSITION Stockpile 2020	1590 -	Total						\$2,920.00	
Construction Stockpile - Total \$13,915.00 1600 - Total \$13,915.00 1610 MGS END ANCHOR Construction 3 Aug 17, SYSTEM \$4,256.00 Payment Estimate Item Adjustment generated Stockpile Transaction	1600			-	3		SYSTEM		Payment Estimate Item Adjustment generated Stockpile Transaction
1600 - Total \$13,915.00 1610 MGS END ANCHOR Construction 3 Aug 17, SYSTEM \$4,256.00 Payment Estimate Item Adjustment generated Stockpile Transaction				- I otal					
1610 MGS END ANCHOR Construction 3 Aug 17, SYSTEM \$4,256.00 Payment Estimate Item Adjustment generated Stockpile Transaction									
	1600 -	Total						\$13,915.00	
Stockpite 2020	1610	MGS END ANCHOR	Construction Stockpile		3	Aug 17, 2020	SYSTEM	\$4,256.00	Payment Estimate Item Adjustment generated Stockpile Transaction
- Total \$4,256.00				- Total				\$4,256.00	
Construction Stockpile - Total \$4,256.00		Construction Stockpile - Tota	ı					\$4,256.00	
1610 - Total \$4,256.00								04.050.00	

Revision 4/1/2020 Page 32 of 37



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks							
1620	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		3	Aug 17, 2020	SYSTEM	\$17,892.00	Payment Estimate Item Adjustment generated Stockpile Transaction							
			- Total				\$17,892.00								
	Construction Stockpile - Tota	l .					\$17,892.00								
1620 -	Total						\$17,892.00								
1630	TYPE E CRASHWORTHY END TERMINAL	Construction Stockpile		2	Aug 3, 2020	SYSTEM	\$18,995.00	Payment Estimate Item Adjustment generated Stockpile Transaction							
			- Total				\$18,995.00								
	Construction Stockpile - Tota	<u> </u>					\$18,995.00								
1630 -	Total						\$18,995.00								
1780	MISC. EXTERNAL CONDUIT SYSTEM ON STRUCTURE	Material		3	Aug 17, 2020	SYSTEM	(\$16,605.00)								
				3	Aug 17, 2020	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.							
				4	Sep 2, 2020	SYSTEM	(\$16,605.00)								
				4	Sep 2, 2020	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.							
				5	Sep 16, 2020	SYSTEM	(\$16,605.00)								
				5	Sep 16, 2020	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.							
				6	Oct 1, 2020	SYSTEM	(\$16,605.00)								
				6	Oct 1, 2020	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 34 on the current Payment Estimate.							
				7	Oct 16, 2020	SYSTEM	(\$16,605.00)								
				7	Oct 16, 2020	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 37 on the current Payment Estimate.							
											8	Nov 2, 2020	SYSTEM	(\$16,605.00)	
				8	Nov 2, 2020	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user hillt5 overridding Payment Estimate Exception 31 on the current Payment Estimate.							
				9	Nov 16, 2020	SYSTEM	(\$16,605.00)								
					9	Nov 16, 2020	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user hillto overridding Payment Estimate Exception 32 on the current Payment Estimate.						
						10	Dec 2, 2020	SYSTEM	(\$16,605.00)						
										10	Dec 2, 2020	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.	
				11	Dec 16, 2020	SYSTEM	(\$16,605.00)								
				11	Dec 16, 2020	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user schlag1 overridding Payment Estimate Exception 30 on the current Payment Estimate.							
				12	Jan 4, 2021	SYSTEM	(\$16,605.00)								
						12	Jan 4, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.					
				13	Jan 19, 2021	SYSTEM	(\$16,605.00)								
				13	Jan 19, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schlag1 overridding Payment Estimate Exception 30 on the current Payment Estimate.							
				14	Feb 2,	SYSTEM	(\$16,605.00)								

Revision 4/1/2020 Page 33 of 37



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks					
1780	MISC. EXTERNAL CONDUIT	Material	, ,,		2021								
	SYSTEM ON STRUCTURE			14	Feb 2, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hillt5 overridding Payment Estimate Exception 56 on the current Payment Estimate.					
			- Total				\$0.00						
	Material - Total						\$0.00						
1780 -	Total						\$0.00						
2210	2210 CONCRETE FOOTINGS, BOLT DOWN	Material		3	Aug 17, 2020	SYSTEM	(\$15,000.00)						
				3	Aug 17, 2020	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.					
				4	Sep 2, 2020	SYSTEM	(\$15,000.00)						
				4	Sep 2, 2020	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 13 on the current Payment Estimate.					
				5	Sep 16, 2020	SYSTEM	(\$15,000.00)						
				5	Sep 16, 2020	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user kloepj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.					
				6	Oct 1, 2020	SYSTEM	(\$15,000.00)						
				6	Oct 1, 2020	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment Estimate Exception 35 on the current Payment Estimate.					
					7	Oct 16, 2020	SYSTEM	(\$15,000.00)					
				7	Oct 16, 2020	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment Estimate Exception 38 on the current Payment Estimate.					
				8	Nov 2, 2020	SYSTEM	(\$15,000.00)						
									8	Nov 2, 2020	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user hillt5 overridding Payment Estimate Exception 32 on the current Payment Estimate.
				9	Nov 16, 2020	SYSTEM	(\$15,000.00)						
				9	Nov 16, 2020	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user hillt5 overridding Payment Estimate Exception 33 on the current Payment Estimate.					
				10	Dec 2, 2020	SYSTEM	(\$15,000.00)						
					10	Dec 2, 2020	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.				
				11	Dec 16, 2020	SYSTEM	(\$15,000.00)						
					11	Dec 16, 2020	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user schlag1 overridding Payment Estimate Exception 31 on the current Payment Estimate.				
				12	Jan 4, 2021	SYSTEM	(\$15,000.00)						
				12	Jan 4, 2021	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 34 on the current Payment Estimate.					
					13	Jan 19, 2021	SYSTEM	(\$15,000.00)					
					13	Jan 19, 2021	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schlag1 overridding Payment Estimate Exception 31 on the current Payment Estimate.				
							14	Feb 2, 2021	SYSTEM	(\$15,000.00)			
				14	Feb 2, 2021	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hillt5 overridding Payment Estimate Exception 57 on the current Payment Estimate.					

Revision 4/1/2020 Page 34 of 37



2210	cription	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
		Material	- Total				\$0.00	
Material - Tot	al						\$0.00	
2210 - Total							\$0.00	
	CTURAL STEEL	Construction		5	Sep 16,	SYSTEM	\$7,567.11	Payment Estimate Item Adjustment generated Stockpile Transaction
	POSTS	Stockpile			2020			, , , , , , , , , , , , , , , , , , ,
			- Total				\$7,567.11	
Construction	Stockpile - Tota						\$7,567.11	
2220 - Total							\$7,567.11	
2230	PIPE POSTS	Construction Stockpile		5	Sep 16, 2020	SYSTEM	\$10,734.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$10,734.00	
Construction	Stockpile - Tota						\$10,734.00	
2230 - Total							\$10,734.00	
2300 TUBULAR SI	UPPORT, TYPE C-2315-20			8	Nov 2, 2020	SYSTEM	\$1,400.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$1,400.00	
Construction	Stockpile - Tota	l					\$1,400.00	
2300 - Total							\$1,400.00	
2310 TUBULAR SI	UPPORT, TYPE C-2018-28			8	Nov 2, 2020	SYSTEM	\$1,400.00	Payment Estimate Item Adjustment generated Stockpile Transaction
	0 2010 20	Otoonpilo	- Total		2020		\$1,400.00	
Construction	Stockpile - Tota						\$1,400.00	
2310 - Total	Ottoonpilo . otta	•					\$1,400.00	
	2 CANTILEVER	Construction		8	Nov 2,	SYSTEM	\$2,300.00	Payment Estimate Item Adjustment generated Stockpile Transaction
	JSS, 30 FT ARM	Stockpile			2020	0.0.2	ΨΣ,000.00	Taylindia Edilinate Roll Anapatanon gorio atou otoorpilo Manaadion
			- Total				\$2,300.00	
Construction	Stockpile - Tota						\$2,300.00	
2320 - Total							\$2,300.00	
	SN 4 SPAN BOX TRUSS (98 FT)			8	Nov 2, 2020	SYSTEM	\$2,600.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$2,600.00	
Construction	Stockpile - Tota						\$2,600.00	
2330 - Total							\$2,600.00	
	SN 8 SPAN BOX ISS (83 FT-5 IN)			8	Nov 2, 2020	SYSTEM	\$2,600.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$2,600.00	
Construction	Stockpile - Tota	l					\$2,600.00	
							\$2,600.00	
2340 - Total	LAB ON STEEL	Material		14	Feb 2,	SYSTEM	(047,000,00)	
					2021		(\$17,390.00)	
				14	2021 Feb 2, 2021	SYSTEM	\$17,390.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user hillts overridding Payment
			- Total	14	Feb 2,		\$17,390.00	
2670 S	al		- Total	14	Feb 2,		\$17,390.00 \$0.00	Estimate Item Adjustment (0018) due to user hillt5 overridding Payment
2670 S	al		- Total	14	Feb 2,		\$17,390.00 \$0.00 \$0.00	Estimate Item Adjustment (0018) due to user hillt5 overridding Payment
Material - Tot		Construction	- Total		Feb 2, 2021	SYSTEM	\$17,390.00 \$0.00 \$0.00	Estimate Item Adjustment (0018) due to user hillt5 overridding Payment Estimate Exception 32 on the current Payment Estimate.
2670 S Material - Tot 2670 - Total 2790 STRIP SEA	al AL EXPANSION JOINT SYSTEM			14	Feb 2,		\$17,390.00 \$0.00 \$0.00 \$0.00 \$9,471.00	Estimate Item Adjustment (0018) due to user hillt5 overridding Payment
2670 S Material - Tot 2670 - Total 2790 STRIP SE	AL EXPANSION JOINT SYSTEM	Stockpile	- Total		Feb 2, 2021	SYSTEM	\$17,390.00 \$0.00 \$0.00 \$0.00 \$9,471.00	Estimate Item Adjustment (0018) due to user hillt5 overridding Payment Estimate Exception 32 on the current Payment Estimate.
Material - Total 2790 STRIP SE	AL EXPANSION	Stockpile			Feb 2, 2021	SYSTEM	\$17,390.00 \$0.00 \$0.00 \$0.00 \$9,471.00 \$9,471.00	Estimate Item Adjustment (0018) due to user hillt5 overridding Payment Estimate Exception 32 on the current Payment Estimate.
Material - Tot 2670 - Total 2790 STRIP SEA Construction 2790 - Total	AL EXPANSION JOINT SYSTEM Stockpile - Tota	Stockpile		14	Feb 2, 2021	SYSTEM	\$17,390.00 \$0.00 \$0.00 \$0.00 \$9,471.00 \$9,471.00 \$9,471.00	Estimate Item Adjustment (0018) due to user hillt5 overridding Payment Estimate Exception 32 on the current Payment Estimate.
Material - Tot 2670 - Total 2790 STRIP SE Construction 2790 - Total 2940 M	AL EXPANSION JOINT SYSTEM Stockpile - Tota MECHANICALLY D EARTH WALL	Stockpile			Feb 2, 2021	SYSTEM	\$17,390.00 \$0.00 \$0.00 \$0.00 \$9,471.00 \$9,471.00	Estimate Item Adjustment (0018) due to user hillt5 overridding Payment Estimate Exception 32 on the current Payment Estimate.
2670 S Material - Tot 2670 - Total 2790 STRIP SE Construction 2790 - Total 2940 M	AL EXPANSION JOINT SYSTEM Stockpile - Tota	Stockpile		14	Feb 2, 2021 Feb 2, 2021	SYSTEM	\$17,390.00 \$0.00 \$0.00 \$0.00 \$9,471.00 \$9,471.00 \$9,471.00	Estimate Item Adjustment (0018) due to user hillt5 overridding Payment Estimate Exception 32 on the current Payment Estimate.

Revision 4/1/2020 Page 35 of 37



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
		Туре	Adjustment Type	Number	Date	Ву		
2940	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material		9	Nov 16, 2020	SYSTEM	\$352,312.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user hillt5 overridding Payment Estimate Exception 22 on the current Payment Estimate.
				10	Dec 2, 2020	SYSTEM	(\$514,875.00)	
				10	Dec 2, 2020	SYSTEM	\$514,875.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
				11	Dec 16, 2020	SYSTEM	(\$514,875.00)	
				11	Dec 16, 2020	SYSTEM	\$514,875.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user schlag1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
				12	Jan 4, 2021	SYSTEM	(\$542,000.00)	
				12	Jan 4, 2021	SYSTEM	\$542,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
				13	Jan 19, 2021	SYSTEM	(\$542,000.00)	
				13	Jan 19, 2021	SYSTEM	\$542,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schlag1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
				14	Feb 2, 2021	SYSTEM	(\$542,000.00)	
				14	Feb 2, 2021	SYSTEM	\$542,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user hillt5 overridding Payment Estimate Exception 50 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
2940 -	· Total						\$0.00	
2960	MISC. (60 IN.) DECORATIVE PEDESTRIAN FENCE			4	Sep 2, 2020	SYSTEM	\$16,591.23	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$16,591.23	
	Construction Stockpile - Tota	ıl					\$16,591.23	
2960 -	· Total						\$16,591.23	
3170	MISC. (60 IN.) DECORATIVE PEDESTRIAN FENCE			4	Sep 2, 2020	SYSTEM	\$23,938.77	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$23,938.77	
	Construction Stockpile - Tota	ı						
3170 -							\$23,938.77	
	· I otal						\$23,938.77 \$23,938.77	
3760	MISC. MODULAR EXPANSION JOINT SYSTEM			14	Feb 2, 2021	SYSTEM		Payment Estimate Item Adjustment generated Stockpile Transaction
3760	MISC. MODULAR		- Total	14		SYSTEM	\$23,938.77	Payment Estimate Item Adjustment generated Stockpile Transaction
	MISC. MODULAR EXPANSION JOINT SYSTEM Construction Stockpile - Tota	Stockpile	- Total	14		SYSTEM	\$23,938.77 \$26,016.00	Payment Estimate Item Adjustment generated Stockpile Transaction
3760 -	MISC. MODULAR EXPANSION JOINT SYSTEM Construction Stockpile - Tota	Stockpile	- Total	14		SYSTEM	\$23,938.77 \$26,016.00 \$26,016.00	Payment Estimate Item Adjustment generated Stockpile Transaction
	MISC. MODULAR EXPANSION JOINT SYSTEM Construction Stockpile - Tota	Stockpile	- Total	14		SYSTEM	\$23,938.77 \$26,016.00 \$26,016.00 \$26,016.00	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
3760 -	MISC. MODULAR EXPANSION JOINT SYSTEM Construction Stockpile - Total STRIP SEAL EXPANSION	Stockpile	- Total		2021 Feb 2,		\$23,938.77 \$26,016.00 \$26,016.00 \$26,016.00 \$26,016.00	
3760 -	MISC. MODULAR EXPANSION JOINT SYSTEM Construction Stockpile - Total STRIP SEAL EXPANSION	Stockpile Construction Stockpile			2021 Feb 2,		\$23,938.77 \$26,016.00 \$26,016.00 \$26,016.00 \$26,016.00 \$5,544.00	
3760 -	MISC. MODULAR EXPANSION JOINT SYSTEM Construction Stockpile - Total STRIP SEAL EXPANSION JOINT SYSTEM Construction Stockpile - Tota	Stockpile Construction Stockpile			2021 Feb 2,		\$23,938.77 \$26,016.00 \$26,016.00 \$26,016.00 \$26,016.00 \$5,544.00	
3760 - 3830	MISC. MODULAR EXPANSION JOINT SYSTEM Construction Stockpile - Total STRIP SEAL EXPANSION JOINT SYSTEM Construction Stockpile - Tota	Stockpile Construction Stockpile			2021 Feb 2,		\$23,938.77 \$26,016.00 \$26,016.00 \$26,016.00 \$26,016.00 \$5,544.00 \$5,544.00	
3760 - 3830 -	MISC. MODULAR EXPANSION JOINT SYSTEM Construction Stockpile - Total STRIP SEAL EXPANSION JOINT SYSTEM Construction Stockpile - Total Total DRILLED SHAFTS (3 FT. 6	Stockpile Construction Stockpile		14	Feb 2, 2021	SYSTEM	\$23,938.77 \$26,016.00 \$26,016.00 \$26,016.00 \$26,016.00 \$5,544.00 \$5,544.00 \$5,544.00	
3760 - 3830 -	MISC. MODULAR EXPANSION JOINT SYSTEM Construction Stockpile - Total STRIP SEAL EXPANSION JOINT SYSTEM Construction Stockpile - Total Total DRILLED SHAFTS (3 FT. 6	Stockpile Construction Stockpile		14	Feb 2, 2021 Feb 2, 2021 Feb 2, 2021	SYSTEM	\$23,938.77 \$26,016.00 \$26,016.00 \$26,016.00 \$26,016.00 \$5,544.00 \$5,544.00 \$5,544.00 \$115,139.70)	Payment Estimate Item Adjustment generated Stockpile Transaction This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user hillt5 overridding Payment
3760 - 3830 -	MISC. MODULAR EXPANSION JOINT SYSTEM Construction Stockpile - Total STRIP SEAL EXPANSION JOINT SYSTEM Construction Stockpile - Total Total DRILLED SHAFTS (3 FT. 6	Stockpile Construction Stockpile	- Total	14	Feb 2, 2021 Feb 2, 2021 Feb 2, 2021	SYSTEM	\$23,938.77 \$26,016.00 \$26,016.00 \$26,016.00 \$26,016.00 \$5,544.00 \$5,544.00 \$5,544.00 \$5,544.00 \$115,139.70	Payment Estimate Item Adjustment generated Stockpile Transaction This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user hillt5 overridding Payment
3760 - 3830 3830 - 5013	MISC. MODULAR EXPANSION JOINT SYSTEM Construction Stockpile - Total STRIP SEAL EXPANSION JOINT SYSTEM Construction Stockpile - Total DRILLED SHAFTS (3 FT. 6 IN. DIA.)	Stockpile Construction Stockpile	- Total	14	Feb 2, 2021 Feb 2, 2021 Feb 2, 2021	SYSTEM	\$23,938.77 \$26,016.00 \$26,016.00 \$26,016.00 \$26,016.00 \$5,544.00 \$5,544.00 \$5,544.00 \$115,139.70 \$115,139.70	Payment Estimate Item Adjustment generated Stockpile Transaction This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user hillt5 overridding Payment
3760 - 3830 3830 - 5013	MISC. MODULAR EXPANSION JOINT SYSTEM Construction Stockpile - Total STRIP SEAL EXPANSION JOINT SYSTEM Construction Stockpile - Total DRILLED SHAFTS (3 FT. 6 IN. DIA.)	Stockpile Construction Stockpile	- Total	14	Feb 2, 2021 Feb 2, 2021 Feb 2, 2021	SYSTEM	\$23,938.77 \$26,016.00 \$26,016.00 \$26,016.00 \$26,016.00 \$5,544.00 \$5,544.00 \$5,544.00 \$115,139.70 \$115,139.70	Payment Estimate Item Adjustment generated Stockpile Transaction This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user hillt5 overridding Payment

Revision 4/1/2020 Page 36 of 37



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
5014	ROCK SOCKETS (3 FT 0 IN. DIA.)	Material			2021			Estimate Item Adjustment (0025) due to user hillt5 overridding Payment Estimate Exception 26 on the current Payment Estimate.	
			- Total				\$0.00		
	Material - Total						\$0.00		
5014 -	4 - Total						\$0.00		
5015	REINFORCING STEEL (EPOXY COATED)	Material		14	Feb 2, 2021	SYSTEM	(\$36,892.40)		
				14	Feb 2, 2021	SYSTEM	\$36,892.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user hillt5 overridding Payment Estimate Exception 42 on the current Payment Estimate.	
			- Total				\$0.00		
	Material - Total						\$0.00		
5015 -	Total						\$0.00		
5019	MECHANICAL BAR SPLICE	Material	Material		14	Feb 2, 2021	SYSTEM	(\$2,532.60)	
				14	Feb 2, 2021	SYSTEM	\$2,532.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user hillt5 overridding Payment Estimate Exception 41 on the current Payment Estimate.	
	- Total						\$0.00		
	Material - Total						\$0.00		
5019 -	Total						\$0.00		
Overa	II - Total						\$241,255.93		

Revision 4/1/2020 Page 37 of 37