

Letting Date

Open to Traffic Date
Work Began Date

Notice to Proceed Date July 6, 2020

## Missouri Department of Transportation Contractor's Pay Estimate Summary

May 15, 2020 July 6, 2020

Pay Estimate Created Date: March 2, 2021

May 15, 2020

| Progress Estimate | Number  |                         | 200515-F15<br>KCI Construction C |           | Pay Period Start February<br>Pay Period End March 1 |              | Original Contract Amount<br>Net Change Order Amount<br>Current Contract Amount | (\$324,312.19) |  |
|-------------------|---|-------------------------|----------------------------------|-----------|---|--------------|--|----------------|--|
| Approval Date     |   |                         |                                  |           |   |              |  | By User        |  |
| March 2, 2021     |   |                         | Generated and                    | Approved  | (and should be considered                           | d Draft) at  | the Project Office Level by  | kloepj1        |  |
| March 2, 2021     |   | F                       | Reviewed and Appro               | oved (and | should be considered Dra                            | ft) at the F | Resident Engineer Level by   | washas         |  |
| March 3, 2021     | Reviewed and Approved at the Central Office Controllers Office Level by |                         |                                  |           |   |              |  |                |  |
| Original Complet  | ion Date  | Current Completion Date |                                  |           | al Completion Date                                  | %            | % of Current Contract Amount Complete  |                |  |
| June 1, 202       | 22  | June 1, 2022            |                                  |           |   |              | 31.80%   |                |  |
|                   | Contra  | ct Informational Dat    | tes                              |           | Milestones  |              |  |                |  |
| Date Description  | Origina   | I Completion Date       | Date Current Completion Date     |           | No Milestones Exist for Contract                    |              |  |                |  |
| Acceptance Date   |   |                         |                                  |           |   |              |  |                |  |
| Awarded Date      | June 3, 2020  |                         | June 3, 2020                     |           |   |              |  |                |  |

| Contract Total Pay For Estimate No. 16 |  |   |  |  |  |  |  |  |  |  |  |
|--|--|---|--|--|--|--|--|--|--|--|--|
|  |  | This Estimate   | Previous   | To Date  |  |  |  |  |  |  |  |
| 200515-F15                             | Total Posted Items Pay<br>Gross Item Adjustments<br>Incentive<br>Disincentive<br>Liquidated Damage<br>Other Contract Adjustments | \$253,102.20<br>(\$13,020.86)<br>\$0.00<br>\$0.00<br>\$0.00<br>\$0.00 | \$7,361,816.03<br>\$217,497.16<br>\$0.00<br>\$0.00<br>\$0.00<br>\$242,210.15<br>\$7,821,523.34 | \$7,614,918.23<br>\$204,476.30<br>\$0.00<br>\$0.00<br>\$0.00<br>\$242,210.15<br>\$8,061,604.68 |  |  |  |  |  |  |  |
| Contract Total Pa                      | ayable This Estimate:  | \$240,081.34  |  |  |  |  |  |  |  |  |  |

### Items Paid This Estimate Period

| Project<br>Number | Line<br>Number             | Item<br>Code | Item Description   | Unit | Unit Price    | Current<br>Installed Qty | Current<br>Installed<br>Amount |
|-------------------|----------------------------|--------------|--|------|---------------|--------------------------|--------------------------------|
| J6I2222           | 0025                       | 2024043      | REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)                                       | SQFT | \$140.500     | 20                       | \$2,810.00                     |
|                   | 0040                       | 2029901      | MISC.REMOVAL OF ACM CONDUIT SYSTEM - TELEPHONE                                   | LS   | \$13,500.000  | 0.9                      | \$12,150.00                    |
|                   | 0310                       | 6049903      | MISC.MSD MANHOLE - ADJUST TO GRADE, 5' TO 10' RANGE                              | LF   | \$1,000.000   | 3                        | \$3,000.00                     |
|                   | 0480                       | 6092011      | INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A                                    | LF   | \$15.000      | 181                      | \$2,715.00                     |
|                   | 0515                       | 6099903      | MISC.MODIFIED INTEGRAL CURB (2 IN. HEIGHT) TYPE A                                | LF   | \$50.000      | 122                      | \$6,100.00                     |
|                   | 0570                       | 6122012      | IMPACT ATTENUATOR 55 MPH (SAND BARREL ARRAY)                                     | EA   | \$2,823.000   | 2                        | \$5,646.00                     |
|                   | 0670                       | 6169902      | MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN (CONTRACTOR FURNISHED AND RETAINED) | EA   | \$3,500.000   | 2                        | \$7,000.00                     |
|                   | 0710                       | 6173600D     | TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED                       | LF   | \$25.900      | 188                      | \$4,869.20                     |
|                   | 0720                       | 6175010A     | RELOCATING TEMPORARY TRAFFIC BARRIER   | LF   | \$11.500      | 900                      | \$10,350.00                    |
|                   | 1310                       | 8061016      | SEDIMENT REMOVAL   | CUYD | \$25.000      | 205                      | \$5,125.00                     |
|                   | 1570                       | 6061060      | MGS GUARDRAIL  | LF   | \$19.000      | 413                      | \$7,847.00                     |
|                   | 1600                       | 6061070      | MGS VERTICAL CONCRETE BARRIER TRANSITION   | EA   | \$2,750.000   | 3                        | \$8,250.00                     |
|                   | 1610                       | 6061080      | MGS END ANCHOR   | EA   | \$1,000.000   | 1                        | \$1,000.00                     |
|                   | 1620                       | 6063014      | TYPE A CRASHWORTHY END TERMINAL (MASH)   | EA   | \$2,600.000   | 3                        | \$7,800.00                     |
|                   | 2650                       | 7032003      | CLASS B CONCRETE (SUBSTRUCTURE)  | CUYD | \$5,050.000   | 1                        | \$5,050.00                     |
|                   | 2670                       | 7034212      | SLAB ON STEEL  | SQYD | \$470.000     | 37                       | \$17,390.00                    |
|                   | 3150                       | 2160500      | REMOVAL OF BRIDGES   | LS   | \$146,000.000 | 1                        | \$146,000.00                   |
| Project J6        | 6 <mark>12222 - T</mark> o | tal          |  |      |               |                          | \$253,102.20                   |

Revision 4/1/2020 Page 1 of 45



Pay Estimate Created Date: March 2, 2021

| Prime Contractor KCI Construction Company Pay Period End March 1, 2021 Net Change Order Amount (\$324,312.19) Current Contract Amount \$23,945,432.81 |  | Contract ID Prime Contractor |  | • | March 1, 2021 |  | (\$324,312.19) |
|---|--|------------------------------|--|---|---------------|--|----------------|
|---|--|------------------------------|--|---|---------------|--|----------------|

Project Number Current Installed Qty Current Installed Line Item Description Unit Unit Price Item Number Code Amount Overall - Total \$253,102.20

### Contract Adjustments This Estimate

| Project<br>lumber | Line<br>No. | Item Description  | Adjustment<br>Type | Other Item<br>Adjustment<br>Type | Comments   | Adjustment<br>Quantity | Line Item<br>Adjustment<br>Unit Price | Adjustment amount |
|-------------------|-------------|---|--------------------|----------------------------------|--|------------------------|---------------------------------------|-------------------|
| 612222            | 0060        | COMPACTING EMBANKMENT                                   | Material           |                                  |  | -65,830                | \$3.00                                | (\$197,490.00)    |
|                   | 0060        | COMPACTING<br>EMBANKMENT                                | Material           |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0003) due to user kloepj1<br>overridding Payment Estimate Exception 1 on<br>the current Payment Estimate.  | 65,830                 | \$3.00                                | \$197,490.00      |
|                   | 0210        | TYPE A2 SHOULDER  | Material           |                                  |  | -413.36                | \$36.00                               | (\$14,880.96)     |
|                   | 0210        | TYPE A2 SHOULDER  | Material           |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0004) due to user kloepj1<br>overridding Payment Estimate Exception 6 on<br>the current Payment Estimate.  | 413.36                 | \$36.00                               | \$14,880.96       |
|                   | 0480        | INTEGRAL CURB (6 IN.<br>HEIGHT AND UNDER) TYPE<br>A     | Material           |                                  |  | -181                   | \$15.00                               | (\$2,715.00)      |
|                   | 0480        | INTEGRAL CURB (6 IN.<br>HEIGHT AND UNDER) TYPE<br>A     | Material           |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0009) due to user kloepj1<br>overridding Payment Estimate Exception 10<br>on the current Payment Estimate. | 181                    | \$15.00                               | \$2,715.00        |
|                   | 0675        | CONCRETE TRAFFIC<br>BARRIER, TYPE C                     | Material           |                                  |  | -461                   | \$145.00                              | (\$66,845.00)     |
|                   | 0675        | CONCRETE TRAFFIC<br>BARRIER, TYPE C                     | Material           |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0002) due to user kloepj1<br>overridding Payment Estimate Exception 22<br>on the current Payment Estimate. | 461                    | \$145.00                              | \$66,845.00       |
|                   | 0690        | CONCRETE TRAFFIC<br>BARRIER, TYPE D<br>(RETAINING WALL) | Material           |                                  |  | -1,745                 | \$85.00                               | (\$148,325.00)    |
|                   | 0690        | CONCRETE TRAFFIC<br>BARRIER, TYPE D<br>(RETAINING WALL) | Material           |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0005) due to user kloepj1<br>overridding Payment Estimate Exception 25<br>on the current Payment Estimate. | 1,745                  | \$85.00                               | \$148,325.00      |
|                   | 0990        | MISC.   | Material           |                                  |  | -2,401                 | \$15.50                               | (\$37,215.50)     |
|                   | 0990        | MISC.   | Material           |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0006) due to user kloepj1<br>overridding Payment Estimate Exception 27<br>on the current Payment Estimate. | 2,401                  | \$15.50                               | \$37,215.50       |
|                   | 1050        | MISC.   | Material           |                                  |  | -952                   | \$25.00                               | (\$23,800.00)     |
|                   | 1050        | MISC.   | Material           |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0007) due to user kloepj1<br>overridding Payment Estimate Exception 35<br>on the current Payment Estimate. | 952                    | \$25.00                               | \$23,800.00       |
|                   | 1100        | SELECT GRANULAR<br>BACKFILL FOR<br>STRUCTURAL SYSTEMS   | Material           |                                  |  | -8,552                 | \$30.00                               | (\$256,560.00)    |

Page 2 of 45 Revision 4/1/2020



Pay Estimate Created Date: March 2, 2021

Progress Estimate Number
16 Contract ID 200515-F15 Pay Period Start February 16, 2021 Original Contract Amount \$24,269,745.00
Prime Contractor KCI Construction Company Pay Period End March 1, 2021 Net Change Order Amount (\$324,312.19)
Current Contract Amount \$23,945,432.81

| et<br>er | Line<br>No. | Item Description   | Adjustment<br>Type        | Other Item<br>Adjustment<br>Type | Comments   | Adjustment<br>Quantity | Line Item<br>Adjustment<br>Unit Price | Adjustment<br>amount |
|----------|-------------|--|---------------------------|----------------------------------|--|------------------------|---------------------------------------|----------------------|
| 2        | 1100        | SELECT GRANULAR<br>BACKFILL FOR<br>STRUCTURAL SYSTEMS        | Material                  |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0008) due to user kloepj1<br>overridding Payment Estimate Exception 50<br>on the current Payment Estimate. | 8,552                  | \$30.00                               | \$256,560.00         |
|          | 1490        | TYPE 5 AGGREGATE FOR<br>BASE (6 IN. THICK)                   | Material                  |                                  |  | -2,629.87              | \$6.50                                | (\$17,094.16         |
|          | 1490        | TYPE 5 AGGREGATE FOR<br>BASE (6 IN. THICK)                   | Material                  |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0015) due to user kloepj1<br>overridding Payment Estimate Exception 2 on<br>the current Payment Estimate.  | 2,629.87               | \$6.50                                | \$17,094.16          |
|          | 1510        | CONCRETE PAVEMENT (9<br>IN. NON-REINFORCED 15<br>FT. JOINTS) | Material                  |                                  |  | -1,259.3               | \$54.00                               | (\$68,002.20         |
|          | 1510        | CONCRETE PAVEMENT (9<br>IN. NON-REINFORCED 15<br>FT. JOINTS) | Material                  |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0016) due to user kloepj1<br>overridding Payment Estimate Exception 3 on<br>the current Payment Estimate.  | 1,259.3                | \$54.00                               | \$68,002.20          |
|          | 1550        | TYPE A2 SHOULDER   | Material                  |                                  |  | -865.37                | \$35.00                               | (\$30,287.95)        |
|          | 1550        | TYPE A2 SHOULDER   | Material                  |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0017) due to user kloepj1<br>overridding Payment Estimate Exception 8 on<br>the current Payment Estimate.  | 865.37                 | \$35.00                               | \$30,287.95          |
|          | 1560        | INTEGRAL CURB (6 IN.<br>HEIGHT AND UNDER) TYPE<br>A          | Material                  |                                  |  | -225                   | \$15.00                               | (\$3,375.00)         |
|          | 1560        | INTEGRAL CURB (6 IN.<br>HEIGHT AND UNDER) TYPE<br>A          | Material                  |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0018) due to user kloepj1<br>overridding Payment Estimate Exception 13<br>on the current Payment Estimate. | 225                    | \$15.00                               | \$3,375.00           |
|          | 1570        | MGS GUARDRAIL  | Construction<br>Stockpile |                                  | Payment Estimate Item Adjustment generated<br>Stockpile Transaction  |                        |                                       | (\$4,220.86)         |
|          | 1600        | MGS VERTICAL CONCRETE BARRIER TRANSITION                     | Construction<br>Stockpile |                                  | Payment Estimate Item Adjustment generated Stockpile Transaction   |                        |                                       | (\$3,795.00)         |
|          | 1610        | MGS END ANCHOR   | Construction<br>Stockpile |                                  | Payment Estimate Item Adjustment generated Stockpile Transaction   |                        |                                       | (\$532.00)           |
|          | 1620        | TYPE A CRASHWORTHY<br>END TERMINAL (MASH)                    | Construction<br>Stockpile |                                  | Payment Estimate Item Adjustment generated Stockpile Transaction   |                        |                                       | (\$4,473.00)         |
|          | 1780        | MISC.  | Material                  |                                  |  | -1                     | \$16,605.00                           | (\$16,605.00         |
|          | 1780        | MISC.  | Material                  |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0013) due to user kloepj1<br>overridding Payment Estimate Exception 51<br>on the current Payment Estimate. | 1                      | \$16,605.00                           | \$16,605.00          |
|          | 2210        | CONCRETE FOOTINGS,<br>BOLT DOWN                              | Material                  |                                  |  | -12.5                  | \$1,200.00                            | (\$15,000.00)        |
| 2        | 2210        | CONCRETE FOOTINGS,<br>BOLT DOWN                              | Material                  |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0014) due to user kloepj1<br>overridding Payment Estimate Exception 52<br>on the current Payment Estimate. | 12.5                   | \$1,200.00                            | \$15,000.00          |
|          | 2650        | CLASS B CONCRETE<br>(SUBSTRUCTURE)                           | Material                  |                                  |  | -1                     | \$5,050.00                            | (\$5,050.00)         |
|          | 2650        | CLASS B CONCRETE (SUBSTRUCTURE)                              | Material                  |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item   | 1                      | \$5,050.00                            | \$5,050.00           |

Revision 4/1/2020 Page 3 of 45



Pay Estimate Created Date: March 2, 2021

Progress Estimate Number
16 Contract ID 200515-F15 Pay Period Start February 16, 2021 Original Contract Amount \$24,269,745.00
Prime Contractor KCI Construction Company Pay Period End March 1, 2021 Net Change Order Amount (\$324,312.19)
Current Contract Amount \$23,945,432.81

| ect<br>ber | Line<br>No. | Item Description   | Adjustment<br>Type | Other Item<br>Adjustment<br>Type | Comments   | Adjustment<br>Quantity | Line Item<br>Adjustment<br>Unit Price | Adjustment<br>amount |
|------------|-------------|--|--------------------|----------------------------------|--|------------------------|---------------------------------------|----------------------|
| 222        |             |  |                    |                                  | Adjustment (0019) due to user kloepj1<br>overridding Payment Estimate Exception 36<br>on the current Payment Estimate.   |                        |                                       |                      |
|            | 2670        | SLAB ON STEEL  | Material           |                                  |  | -74                    | \$470.00                              | (\$34,780.00         |
|            | 2670        | SLAB ON STEEL  | Material           |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0020) due to user kloepj1<br>overridding Payment Estimate Exception 39<br>on the current Payment Estimate. | 74                     | \$470.00                              | \$34,780.00          |
|            | 2940        | MECHANICALLY<br>STABILIZED EARTH WALL<br>SYSTEMS   | Material           |                                  |  | -8,672                 | \$62.50                               | (\$542,000.00        |
|            | 2940        | MECHANICALLY<br>STABILIZED EARTH WALL<br>SYSTEMS   | Material           |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0021) due to user kloepj1<br>overridding Payment Estimate Exception 49<br>on the current Payment Estimate. | 8,672                  | \$62.50                               | \$542,000.00         |
|            | 5013        | DRILLED SHAFTS (3 FT. 6<br>IN. DIA.)   | Material           |                                  |  | -202.8                 | \$567.75                              | (\$115,139.70        |
|            | 5013        | DRILLED SHAFTS (3 FT. 6<br>IN. DIA.)   | Material           |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0022) due to user kloepj1<br>overridding Payment Estimate Exception 28<br>on the current Payment Estimate. | 202.8                  | \$567.75                              | \$115,139.70         |
|            | 5014        | ROCK SOCKETS (3 FT 0 IN. DIA.)   | Material           |                                  |  | -76.7                  | \$917.10                              | (\$70,341.57         |
|            | 5014        | ROCK SOCKETS (3 FT 0 IN. DIA.)   | Material           |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0023) due to user kloepj1<br>overridding Payment Estimate Exception 33<br>on the current Payment Estimate. | 76.7                   | \$917.10                              | \$70,341.57          |
|            | 5015        | REINFORCING STEEL (EPOXY COATED)   | Material           |                                  |  | -24,760                | \$1.49                                | (\$36,892.40         |
|            | 5015        | REINFORCING STEEL<br>(EPOXY COATED)  | Material           |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0024) due to user kloepj1<br>overridding Payment Estimate Exception 46<br>on the current Payment Estimate. | 24,760                 | \$1.49                                | \$36,892.40          |
|            | 5020        | FURNISHING AND PLACING<br>CONCRETE MATERIAL FOR<br>FULL DEPTH PAVEMENT<br>REPAIR                           | Material           |                                  |  | -165.7                 | \$110.00                              | (\$18,227.00         |
|            | 5020        | FURNISHING AND PLACING<br>CONCRETE MATERIAL FOR<br>FULL DEPTH PAVEMENT<br>REPAIR                           | Material           |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0025) due to user kloepj1<br>overridding Payment Estimate Exception 16<br>on the current Payment Estimate. | 165.7                  | \$110.00                              | \$18,227.00          |
| 5          | 5021        | TIE BAR (DRILLING,<br>FURNISHING AND<br>INSTALLATION) FOR FULL<br>DEPTH PAVEMENT REPAIR<br>(TYPE L JOINTS) | Material           |                                  |  | -58                    | \$12.00                               | (\$696.00            |
|            | 5021        | TIE BAR (DRILLING,<br>FURNISHING AND<br>INSTALLATION) FOR FULL<br>DEPTH PAVEMENT REPAIR<br>(TYPE L JOINTS) | Material           |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0026) due to user kloepj1<br>overridding Payment Estimate Exception 19<br>on the current Payment Estimate. | 58                     | \$12.00                               | \$696.00             |
|            | 5022        | DOWEL BAR (DRILLING,<br>FURNISHING AND<br>INSTALLATION) FOR FULL   | Material           |                                  |  | -130                   | \$15.00                               | (\$1,950.00          |

Revision 4/1/2020 Page 4 of 45



Pay Estimate Created Date: March 2, 2021

| Progr             |             | timate Number<br>16   | Contract ID<br>Prime Contr | 200515-<br>actor KCI Con |  |          | Change Orde            | t Amount \$2<br>er Amount (\$<br>t Amount \$2 | 324,312.19)       |
|-------------------|-------------|-----------------------|----------------------------|--------------------------|--|----------|------------------------|---|-------------------|
| Project<br>Number | Line<br>No. | Item Desc             | cription                   | Adjustment<br>Type       | Other Item<br>Adjustment<br>Type   | Comments | Adjustment<br>Quantity | Line Item<br>Adjustment<br>Unit Price         | Adjustment amount |
| J6I2222           |             | DEPTH PAVEMENT REPAIR |                            |                          |  |          |                        |   |                   |
|                   |             |                       | Material                   |                          | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0027) due to user kloepj1<br>overridding Payment Estimate Exception 18<br>on the current Payment Estimate. |          | \$15.00                | \$1,950.00                                    |                   |
| Total             |             |                       |                            |                          |  |          |                        |   | (\$13,020.86)     |

Revision 4/1/2020 Page 5 of 45



|                   | Contract Project Information |                          |       |                     |   |  |  |  |
|-------------------|------------------------------|--------------------------|-------|---------------------|---|--|--|--|
| Project<br>Number | Federal<br>Proj.<br>Number   | Project<br>Description   | Route | County              | Location of Work                              |  |  |  |
| J6I2222           | I-64-1<br>(61)               | Interchange improvements | I-64  | ST<br>LOUIS<br>CITY | from west of Ewing Ave to east of 21st Street |  |  |  |

| Totals by Job Numbers |   |                                      |                                       |                                       |  |  |  |  |  |  |
|-----------------------|---|--------------------------------------|---------------------------------------|---------------------------------------|--|--|--|--|--|--|
| J6I2222               |   | This Estimate                        | Previous                              | To Date                               |  |  |  |  |  |  |
|                       | Posted Item Pay<br>Gross Item Adjustments | \$253,102.20                         | \$7,361,816.03                        | \$7,614,918.23                        |  |  |  |  |  |  |
|                       | Gross Item Pay                            | (\$13,020.86)<br><b>\$240,081.34</b> | \$217,497.16<br><b>\$7,579,313.19</b> | \$204,476.30<br><b>\$7,819,394.53</b> |  |  |  |  |  |  |
|                       | Incentive                                 | \$0.00                               | \$0.00                                | \$0.00                                |  |  |  |  |  |  |
|                       | Disincentive                              | \$0.00                               | \$0.00                                | \$0.00                                |  |  |  |  |  |  |
|                       | Liquidated Damages                        | \$0.00                               | \$0.00                                | \$0.00                                |  |  |  |  |  |  |
|                       | Other Contract Adjustments                | \$0.00                               | \$242,210.15                          | \$242,210.15                          |  |  |  |  |  |  |

Revision 4/1/2020 Page 6 of 45



**Exceptions (Discrepancies) This Estimate Period** 

| Exceptions (Discrepancies) This Estimate Period   |   |               |            |
|---|---|---------------|------------|
| Exceptions / Discrepencies  | Explanation   | Entered<br>By | Status     |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 2036000, Project Item Line Number 0060, Material Set 203600096, Material 0200XXCS - Compacted Soil for Subgrade or Embankment, Acceptance Action Generic 0200XXCS is insufficient.             | Plan quantity has not been reached/installed at this time | kloepj1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 3040506, Project Item Line Number 1490, Material Set 304050696, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.        | Aggregate material testing needs to be reported           | kloepj1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 5021309, Project Item Line Number 1510, Material Set 502130996, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.                 | Aggregate material testing needs to be reported           | kloepj1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 5021309, Project Item Line Number 1510, Material Set 502130996, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.                  | Aggregate material testing needs to be reported           | kloepj1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 5021309, Project Item Line Number 1510, Material Set 502130996, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient. | Waiting on PAL  | kloepj1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 5021340, Project Item Line Number 0210, Material Set 502134096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.                  | Aggregate material testing needs to be reported           | kloepj1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 5021340, Project Item Line Number 0210, Material Set 502134096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.                 | Aggregate material testing needs to be reported           | kloepj1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 5021340, Project Item Line Number 1550, Material Set 502134096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.                 | Aggregate material testing needs to be reported           | kloepj1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 5021340, Project Item Line Number 1550, Material Set 502134096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.                  | Aggregate material testing needs to be reported           | kloepj1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 6092011, Project Item Line Number 0480, Material Set 609201196, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.                  | Aggregate material testing needs to be reported           | kloepj1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 6092011, Project Item Line Number 0480, Material Set 609201196, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.                 | Aggregate material testing needs to be reported           | kloepj1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 6092011, Project Item Line Number 0480, Material Set 609201196, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.    | Waiting on PAL  | kloepj1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 6092011, Project Item Line Number 1560, Material Set 609201196, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.    | Waiting on PAL  | kloepj1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 6092011, Project Item Line Number 1560, Material Set 609201196, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.                 | Aggregate material testing needs to be reported           | kloepj1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 6092011, Project Item Line Number 1560, Material Set 609201196, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.                  | Aggregate material testing needs to be reported           | kloepj1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 6131010, Project Item Line Number 5020, Material Set 613101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.                 | Aggregate material testing needs to be reported           | kloepj1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 6131010, Project Item Line Number 5020, Material Set 613101096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.                  | Aggregate material testing needs to be reported           | kloepj1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 6131015, Project Item Line Number 5022, Material Set 613101596, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient.                    | Waiting on PAL  | kloepj1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 6131018, Project Item Line Number 5021, Material Set 613101896, Material 1057JMTBE42019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient. | Waiting on PAL  | kloepj1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 6131018, Project Item Line Number 5021, Material Set 613101896, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient. | Waiting on PAL  | kloepj1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 6131018, Project Item Line Number 5021, Material Set 613101896, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient.                    | Waiting on PAL  | kloepj1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 6173000, Project Item Line Number 0675, Material Set 617300096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.                         | Waiting on 28 day break                                   | kloepj1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 6173000, Project Item Line Number 0675, Material Set 617300096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.                  | Aggregate material testing needs to be reported           | kloepj1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 6173000, Project Item Line Number 0675, Material Set 617300096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance  | Aggregate material testing needs to be reported           | kloepj1       | Overridden |
|   |   |               |            |

Revision 4/1/2020 Page 7 of 45



**Exceptions (Discrepancies) This Estimate Period** 

| Exceptions (Discrepancies) This Estimate Period  |  |               |            |
|--|--|---------------|------------|
| Exceptions / Discrepencies   | Explanation  | Entered<br>By | Status     |
| Action Generic 1005FACCNSCA is insufficient.   |  |               |            |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 6173102, Project Item Line Number 0690, Material Set 617310296, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.              | Aggregate material testing needs to be reported      | kloepj1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 6173102, Project Item Line Number 0690, Material Set 617310296, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.               | Aggregate material testing needs to be reported      | kloepj1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 6249905, Project Item Line Number 0990, Material Set 624990596, Material 3099XX - See Remarks for Description of Material, Acceptance Action Generic 3099XX is insufficient.                | Aggregate material testing needs to be reported      | kloepj1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011105, Project Item Line Number 5013, Material Set 701110596, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.              | Aggregate material testing needs to be reported      | kloepj1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011105, Project Item Line Number 5013, Material Set 701110596, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.                          | Aggregate material testing needs to be reported      | kloepj1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011105, Project Item Line Number 5013, Material Set 701110596, Material 0701PLCA - Casing for Drilled Shafts, Acceptance Action Generic 0701PLCA is insufficient.                          | Material certification needs to be reviewed/approved | kloepj1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011105, Project Item Line Number 5013, Material Set 701110596, Material 0701PLCSLT - Drilled Shaft CSL steel pipe, Acceptance Action Generic 0701PLCSLT is insufficient.                   | Material certification needs to be reviewed/approved | kloepj1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011105, Project Item Line Number 5013, Material Set 701110596, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.                      | Waiting on 28 day break                              | kloepj1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011204, Project Item Line Number 5014, Material Set 701120496, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.                          | Aggregate material testing needs to be reported      | kloepj1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011204, Project Item Line Number 5014, Material Set 701120496, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.              | Aggregate material testing needs to be reported      | kloepj1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7019903, Project Item Line Number 1050, Material Set 7019903, Material 1010SGBF - Select Gran Backfill for Structural Sys, Acceptance Action Generic 1010SGBF is insufficient.              | Aggregate material testing needs to be reported      | kloepj1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7032003, Project Item Line Number 2650, Material Set 703200396, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.              | Aggregate material testing needs to be reported      | kloepj1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7032003, Project Item Line Number 2650, Material Set 703200396, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.               | Aggregate material testing needs to be reported      | kloepj1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7032003, Project Item Line Number 2650, Material Set 703200396, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.                            | Waiting on 28 day break                              | kloepj1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7034212, Project Item Line Number 2670, Material Set 703421296, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient. | Waiting on PAL                                       | kloepj1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7034212, Project Item Line Number 2670, Material Set 703421296, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.                  | Waiting on PAL                                       | kloepj1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7034212, Project Item Line Number 2670, Material Set 703421296, Material 1036RSDFPL42M19 - Reinforcing Steel No. 6/M19 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient. | Waiting on PAL                                       | kloepj1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7034212, Project Item Line Number 2670, Material Set 703421296, Material 1036RSDFPL42M25 - Reinforcing Steel No. 8/M25 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient. | Waiting on PAL                                       | kloepj1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7034212, Project Item Line Number 2670, Material Set 703421296, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.              | Aggregate material testing needs to be reported      | kloepj1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7034212, Project Item Line Number 2670, Material Set 703421296, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.               | Aggregate material testing needs to be reported      | kloepj1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7034212, Project Item Line Number 2670, Material Set 703421296, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.                      | Waiting on 28 day break                              | kloepj1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7101000, Project Item Line Number 5015, Material Set 710100096, Material 1036RSDFEC42M25 - Rein Steel EC No. 8/M25 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.     | Waiting on PAL                                       | kloepj1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7101000, Project Item Line Number 5015, Material Set 710100096, Material 1036RSDFEC42M29 - Rein Steel EC No. 9/M29 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.     | Waiting on PAL                                       | kloepj1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7101000, Project Item Line Number   | Waiting on PAL                                       | kloepj1       | Overridden |
|  |  |               |            |

Revision 4/1/2020 Page 8 of 45



### **Exceptions (Discrepancies) This Estimate Period**

| Exceptions / Discrepencies  | Explanation  | Entered<br>By | Status     |
|---|--|---------------|------------|
| 5015, Material Set 710100096, Material 1036RSSRECAB - Epoxy Ctd Sprl Stl Rein for Anch Bolts @, Acceptance Action Generic ReinforcingMisc is insufficient.  |  |               |            |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7201000, Project Item Line Number 2940, Material Set 720100096, Material 0720MSEW - MSE Wall System -Bridge Approved Design, Acceptance Action Generic 0720MSEW is insufficient. | Waiting on Bridge to report the accepted MSE Wall system submittal | kloepj1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7201200, Project Item Line Number 1100, Material Set 720120096, Material 1010SGBF - Select Gran Backfill for Structural Sys, Acceptance Action Generic 1010SGBF is insufficient. | Aggregate material testing needs to be reported                    | kloepj1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 9019901, Project Item Line Number 1780, Material Set 9019901, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient.                   | Plan quantity has not been reached/installed at this time          | kloepj1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 9031020, Project Item Line Number 2210, Material Set 903102096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.                 | Plan quantity has not been reached/installed at this time          | kloepj1       | Overridden |

Revision 4/1/2020 Page 9 of 45



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

|                         | uantities      |          |             | based on F   | Report Generated date and can differ from the posted am |                 | time the Es            |                              |      |                                    |              |  |
|-------------------------|----------------|----------|-------------|--------------|---|-----------------|------------------------|------------------------------|------|------------------------------------|--------------|--|
| Contract<br>Nm.CONTRACT | Project<br>No. | Category | Line<br>No. | Item<br>Code | Description   | Bid<br>Quantity | Net<br>Change<br>Order | Total<br>Current<br>Quantity | Unit | Total<br>Posted<br>Approved<br>Qty | Unit Price   | Total Value POSTED<br>To Date (See report<br>generated date) |
| 200515-F15              | J6I2222        | 0001     | 0010        | 2013000      | CLEARING AND GRUBBING                                   | 2.00            | 0.00                   | 2.00                         | ACRE | 2.00                               | \$25,000.00  | \$50,000.00  |
|                         |                | 0001     | 0020        | 2022010      | REMOVAL OF IMPROVEMENTS                                 | 1.00            | 0.00                   | 1.00                         | LS   | 0.42                               | \$600,000.00 | \$252,000.00   |
|                         |                | 0001     | 0025        | 2024043      | REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)              | 155.00          | 0.00                   | 155.00                       | SQFT | 155.00                             | \$140.50     | \$21,777.50  |
|                         |                | 0001     | 0040        | 2029901      | MISC.REMOVAL OF ACM CONDUIT SYSTEM - TELEPHONE          | 1.00            | 0.00                   | 1.00                         | LS   | 0.90                               | \$13,500.00  | \$12,150.00  |
|                         |                | 0001     | 0045        | 2029903      | MISC.MISCELLANEOUS ACM REMOVAL                          | 80.00           | 0.00                   | 80.00                        | LF   | 0.00                               | \$48.00      | \$0.00   |
|                         |                | 0001     | 0050        | 2031000      | CLASS A EXCAVATION                                      | 153,414.00      | 0.00                   | 153,414.00                   | CUYD | 69,942.00                          | \$15.00      | \$1,049,130.00   |
|                         |                | 0001     | 0060        | 2036000      | COMPACTING EMBANKMENT                                   | 106,637.00      | 0.00                   | 106,637.00                   | CUYD | 65,830.00                          | \$3.00       | \$197,490.00   |
|                         |                | 0001     | 0070        | 2037075      | COMPACTING IN CUT                                       | 45.00           | 0.00                   | 45.00                        | STA  | 0.00                               | \$1.00       | \$0.00   |
|                         |                | 0001     | 0080        | 2039901      | MISC.STOCK PILE REMOVAL AT OLD 21ST STREET FOR MSD      | 1.00            | 0.00                   | 1.00                         | LS   | 0.25                               | \$85,000.00  | \$21,250.00  |
|                         |                | 0001     | 0090        | 2039907      | MISC.Lightweight Fill                                   | 16,413.00       | 0.00                   | 16,413.00                    | CUYD | 0.00                               | \$61.50      | \$0.00   |
|                         |                | 0001     | 0100        | 2042010      | SETTLEMENT GAUGE  | 10.00           | 0.00                   | 10.00                        | EA   | 10.00                              | \$1,500.00   | \$15,000.00  |
|                         |                | 0001     | 0110        | 2043010      | PORE PRESSURE MEASURING DEVICE                          | 3.00            | 0.00                   | 3.00                         | EA   | 3.00                               | \$4,000.00   | \$12,000.00  |
|                         |                | 0001     | 0120        | 2063000      | CLASS 3 EXCAVATION                                      | 2,716.00        | 0.00                   | 2,716.00                     | CUYD | 2,299.00                           | \$15.00      | \$34,485.00  |
|                         |                | 0001     | 0130        | 2071000      | LINEAR GRADING CLASS 1                                  | 11.00           | 0.00                   | 11.00                        | STA  | 0.00                               | \$800.00     | \$0.00   |
|                         |                | 0001     | 0140        | 3040143      | TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)                 | 1,152.00        | 0.00                   | 1,152.00                     | SQYD | 0.00                               | \$11.00      | \$0.00   |
|                         |                | 0001     | 0150        | 3040504      | TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)                 | 72.00           | 0.00                   | 72.00                        | SQYD | 0.00                               | \$23.00      | \$0.00   |
|                         |                | 0001     | 0160        | 3105003      | GRAVEL (A) OR CRUSHED STONE (B)                         | 540.00          | 2,888.00               | 3,428.00                     | SQYD | 0.00                               | \$12.00      | \$0.00   |
|                         |                | 0001     | 0170        | 4011207      | BITUMINOUS PAVEMENT MIXTURE PG70-22, (BP-1)             | 1,950.80        | 0.00                   | 1,950.80                     | TONS | 0.00                               | \$77.75      | \$0.00   |
|                         |                | 0001     | 0180        | 4030109      | ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125CLP MIX)      | 376.20          | 0.00                   | 376.20                       | TONS | 0.00                               | \$125.00     | \$0.00   |
|                         |                | 0001     | 0190        | 4071005      | TACK COAT   | 1,660.00        | 0.00                   | 1,660.00                     | GAL  | 0.00                               | \$3.50       | \$0.00   |
|                         |                | 0001     | 0200        | 5021108      | CONCRETE PAVEMENT ( 8 IN. NON-REINF)                    | 366.30          | 0.00                   | 366.30                       | SQYD | 0.00                               | \$49.00      | \$0.00   |
|                         |                | 0001     | 0210        | 5021340      | TYPE A2 SHOULDER  | 1,563.20        | 0.00                   | 1,563.20                     | SQYD | 413.36                             | \$36.00      | \$14,880.96  |
|                         |                | 0001     | 0220        | 5041000      | CONCRETE APPROACH PAVEMENT                              | 105.20          | 0.00                   | 105.20                       | SQYD | 0.00                               | \$150.00     | \$0.00   |
|                         |                | 0001     | 0230        | 6039901      | WATER   | 1.00            | 0.00                   | 1.00                         | LS   | 1.00                               | \$30,000.00  | \$30,000.00  |
|                         |                | 0001     | 0240        | 6039901      | WATER   | 1.00            | 0.00                   | 1.00                         | LS   | 0.00                               | \$12,000.00  | \$0.00   |
|                         |                | 0001     | 0250        | 6039903      | WATER   | 20.00           | 0.00                   | 20.00                        | LF   | 20.00                              | \$2,000.00   | \$40,000.00  |
|                         |                | 0001     | 0260        | 6039903      | WATER   | 150.00          | 7.00                   | 157.00                       | LF   | 157.00                             | \$2,000.00   | \$314,000.00   |
|                         |                | 0001     | 0270        | 6039903      | WATER   | 570.00          | -179.80                | 390.20                       | LF   | 390.20                             | \$400.00     | \$156,080.00   |
|                         |                | 0001     | 0280        | 6039903      | WATER   | 100.00          | 0.00                   | 100.00                       | LF   | 100.00                             | \$400.00     | \$40,000.00  |
|                         |                | 0001     | 0290        | 6049901      | MISC.INSPECTION OF 9X7 CONCRETE ARCH SEWER              | 1.00            | 0.00                   | 1.00                         | LS   | 0.00                               | \$6,000.00   | \$0.00   |
|                         |                | 0001     | 0300        | 6049903      | MISC.MODOT MANHOLE - ADJUST TO GRADE                    | 24.00           | 0.00                   | 24.00                        | LF   | 24.00                              | \$1,000.00   | \$24,000.00  |
|                         |                | 0001     | 0310        | 6049903      | MISC.MSD MANHOLE - ADJUST TO GRADE, 5' TO 10' RANGE     | 25.00           | 0.00                   | 25.00                        | LF   | 18.40                              | \$1,000.00   | \$18,400.00  |
|                         |                | 0001     | 0320        | 6049903      | MISC.MSD MANHOLE - ADJUST TO GRADE, 10' TO 15' RANGE    | 23.00           | 0.00                   | 23.00                        | LF   | 0.00                               | \$1,000.00   | \$0.00   |
|                         |                | 0001     | 0330        | 6049903      | MISC.MSD MANHOLE - ADJUST TO GRADE, 15' TO 20' RANGE    | 37.00           | 0.00                   | 37.00                        | LF   | 18.20                              | \$1,000.00   | \$18,200.00  |
|                         |                | 0001     | 0340        | 6049903      | MISC.MSD MANHOLE - ADJUST TO GRADE, 25' TO 30' RANGE    | 28.00           | 0.00                   | 28.00                        | LF   | 0.00                               | \$1,000.00   | \$0.00   |
|                         |                | 0001     | 0350        | 6071012A     | CHAIN-LINK FENCE (60 IN.)                               | 586.00          | 0.00                   | 586.00                       | LF   | 0.00                               | \$28.00      | \$0.00   |
|                         |                | 0001     | 0360        | 6071040      | DRIVE GATE (CHAIN-LINK)                                 | 2.00            | 0.00                   | 2.00                         | EA   | 0.00                               | \$1,200.00   | \$0.00   |
|                         |                | 0001     | 0370        | 6071050      | CHAIN-LINK FENCE (RETAINING WALLS)                      | 1,800.00        | 0.00                   | 1,800.00                     | LF   | 0.00                               | \$24.00      | \$0.00   |
|                         |                | 0001     | 0380        | 6071102      | MODIFIED CONCRETE GUTTER TYPE B                         | 2,038.00        | 0.00                   | 2,038.00                     | LF   | 0.00                               | \$34.00      | \$0.00   |
|                         |                | 0001     | 0390        | 6081012      | TRUNCATED DOMES   | 60.00           | 0.00                   | 60.00                        | SQFT | 0.00                               | \$35.00      | \$0.00   |
|                         |                | 0001     | 0400        | 6083006      | 6 IN. CONCRETE MEDIAN STRIP                             | 529.80          | 0.00                   | 529.80                       | SQYD | 0.00                               | \$100.00     | \$0.00   |
|                         |                | 0001     | 0410        | 6085008      | PAVED APPROACH, 8 IN.                                   | 72.30           | 0.00                   | 72.30                        | SQYD | 0.00                               | \$125.00     | \$0.00   |
|                         |                | 0001     | 0420        | 6086004      | CONCRETE SIDEWALK, 4 IN.                                | 1,152.10        | 0.00                   | 1,152.10                     | SQYD | 0.00                               | \$51.00      | \$0.00   |
|                         |                | 0001     | 0430        | 6086007      | CONCRETE SIDEWALK, 7 IN.                                | 15.30           | 0.00                   | 15.30                        | SQYD | 0.00                               | \$65.00      | \$0.00   |
|                         |                | 0001     | 0440        | 6089902      | MISC.ADA CURB RAMP                                      | 16.00           | 0.00                   | 16.00                        | EA   | 0.00                               | \$3,550.00   | \$0.00   |
|                         |                | 0001     | 0450        | 6091010      | CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S           | 301.00          | 0.00                   | 301.00                       | LF   | 0.00                               | \$45.00      | \$0.00   |
|                         |                | 0001     | 0460        | 6091042      | CONCRETE GUTTER TYPE B                                  | 2,007.00        | 0.00                   | 2,007.00                     | LF   | 0.00                               | \$30.00      | \$0.00   |

Revision 4/1/2020 Page 10 of 45



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract<br>Nm.CONTRACT | Project<br>No. | Category | Line<br>No. | Item<br>Code | Report Generated date and can differ from the posted am  Description                                 | Bid<br>Quantity | Net Change Order | Total Current Quantity | Unit | Total<br>Posted<br>Approved | Unit Price     | Total Value POSTED To Date (See report generated date) |
|-------------------------|----------------|----------|-------------|--------------|--|-----------------|------------------|------------------------|------|-----------------------------|----------------|--|
| 200515-F15              | J6I2222        | 0001     | 0470        | 6091060      | PAVED DITCH  | 210.30          | 0.00             | 210.30                 | SQYD | Qty 0.00                    | \$81.00        | \$0.00   |
|                         |                | 0001     | 0480        | 6092011      | INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A  | 203.00          | 0.00             | 203.00                 | LF   | 181.00                      | \$15.00        | \$2,715.00   |
|                         |                | 0001     | 0490        | 6096020      | FURNISHING TYPE 2 ROCK DITCH LINER   | 24.00           | 0.00             | 24.00                  | CUYD | 0.00                        | \$100.00       | \$0.00   |
|                         |                | 0001     | 0500        | 6096042      | PLACING TYPE 2 ROCK DITCH LINER  | 24.00           | 0.00             | 24.00                  | CUYD | 0.00                        | \$100.00       | \$0.0  |
|                         |                | 0001     | 0510        | 6097000      | ROCK LINING  | 2.00            | 0.00             | 2.00                   | CUYD | 0.00                        | \$1,000.00     | \$0.0  |
|                         |                | 0001     | 0515        | 6099903      | MISC.MODIFIED INTEGRAL CURB (2 IN. HEIGHT) TYPE A  | 320.00          | 0.00             | 320.00                 | LF   | 122.00                      | \$50.00        | \$6,100.0  |
|                         |                | 0001     | 0520        | 6113020      | FURNISHING TYPE 2 ROCK BLANKET   | 567.00          | 0.00             | 567.00                 | CUYD | 0.00                        | \$48.00        | \$0.0  |
|                         |                | 0001     | 0530        | 6113040      | PLACING TYPE 2 ROCK BLANKET  | 567.00          | 0.00             | 567.00                 | CUYD | 0.00                        | \$21.00        | \$0.0  |
|                         |                | 0001     | 0540        | 6116010A     | SLOPE PROTECTION   | 1.00            | 0.00             | 1.00                   | SQYD | 0.00                        | \$300.00       | \$0.0  |
|                         |                | 0001     | 0550        | 6119907      | MISC.Furnishing Modified Rock Blanket  | 1,151.00        | 0.00             | 1,151.00               | CUYD | 0.00                        | \$50.00        | \$0.0  |
|                         |                | 0001     | 0560        | 6119907      | MISC.Placing Modified Rock Blanket   | 1,151.00        | 0.00             | 1,151.00               | CUYD | 0.00                        | \$21.00        | \$0.0  |
|                         |                | 0001     | 0570        | 6122012      | IMPACT ATTENUATOR 55 MPH (SAND BARREL ARRAY)   | 5.00            | 0.00             | 5.00                   | EA   | 4.00                        | \$2,823.00     | \$11,292.0   |
|                         |                | 0001     | 0580        | 6122020      | REPLACEMENT SAND BARREL  | 12.00           | 0.00             | 12.00                  | EA   | 0.00                        | \$431.00       | \$0.0  |
|                         |                | 0001     | 0590        | 6122030      | IMPACT ATTENUATOR (RELOCATION)   | 9.00            | 0.00             | 9.00                   | EA   | 0.00                        | \$877.00       | \$0.0  |
|                         |                | 0001     | 0600        | 6133020      | FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR                 | 148.50          | 0.00             | 148.50                 | TONS | 0.00                        | \$62.00        | \$0.0  |
|                         |                | 0001     | 0610        | 6133021      | REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR  | 528.50          | 0.00             | 528.50                 | SQYD | 0.00                        | \$58.75        | \$0.0  |
|                         |                | 0001     | 0620        | 6141024      | GRATE AND BEARING PLATE (5 FT. X 3 FT. OR 1524 MM X 914 MM)  | 10.00           | 0.00             | 10.00                  | EA   | 4.00                        | \$1,400.00     | \$5,600.0  |
|                         |                | 0001     | 0630        | 6141120      | CURVED VANE GRATE AND FRAME (2 FT. X 2 FT. OR 600MM X 600MM)   | 72.00           | -72.00           | 0.00                   | EA   | 0.00                        | \$700.00       | \$0.0  |
|                         |                | 0001     | 0640        | 6149902      | MISC.Parallel Grate and Bearing Plate (2 FT.x2FT.)   | 67.00           | -57.00           | 10.00                  | EA   | 1.00                        | \$700.00       | \$700.0  |
|                         |                | 0001     | 0650        | 6169901      | MISC.TEMPORARY TRAFFIC CONTROL   | 1.00            | 0.00             | 1.00                   | LS   | 0.50                        | \$465,000.00   | \$232,500.0  |
|                         |                | 0001     | 0660        | 6169902      | MISC.MSD Manhole Frame and Cover   | 17.00           | -17.00           | 0.00                   | EA   | 0.00                        | \$400.00       | \$0.0  |
|                         |                | 0001     | 0670        | 6169902      | MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN (CONTRACTOR FURNISHED AND RETAINED)                     | 8.00            | 0.00             | 8.00                   | EA   | 7.00                        | \$3,500.00     | \$24,500.0   |
|                         |                | 0001     | 0675        | 6173000      | CONCRETE TRAFFIC BARRIER, TYPE C   | 254.00          | 357.00           | 611.00                 | LF   | 461.00                      | \$145.00       | \$66,845.0   |
|                         |                | 0001     | 0680        | 6173100      | CONCRETE TRAFFIC BARRIER, TYPE D   | 1,787.00        | 0.00             | 1,787.00               | LF   | 0.00                        | \$90.00        | \$0.0  |
|                         |                | 0001     | 0690        | 6173102      | CONCRETE TRAFFIC BARRIER, TYPE D (RETAINING WALL)  | 2,413.00        | 0.00             | 2,413.00               | LF   | 1,745.00                    | \$85.00        | \$148,325.0  |
|                         |                | 0001     | 0700        | 6173103      | CONCRETE TRAFFIC BARRIER, TYPE D (MOMENT SLAB)   | 440.00          | 0.00             | 440.00                 | LF   | 0.00                        | \$110.00       | \$0.   |
|                         |                | 0001     | 0710        | 6173600D     | TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED   | 2,488.00        | 0.00             | 2,488.00               | LF   | 2,188.50                    | \$25.90        | \$56,682.  |
|                         |                | 0001     | 0720        | 6175010A     | RELOCATING TEMPORARY TRAFFIC BARRIER   | 4,013.00        | 0.00             | 4,013.00               | LF   | 1,112.50                    | \$11.50        | \$12,793.  |
|                         |                | 0001     | 0730        | 6179903      | MISC.MODIFIED BARRIER WALL   | 315.00          | 0.00             | 315.00                 | LF   | 0.00                        | \$300.00       | \$0.   |
|                         |                | 0001     | 0740        | 6181000      | MOBILIZATION   | 1.00            | -1.00            | 0.00                   | LS   | 0.00                        | \$2,269,999.84 | \$0.   |
|                         |                | 0001     | 0741        | 6181000      | MOBILIZATION   | 0.00            | 1.00             | 1.00                   | LS   | 0.75                        | \$2,162,092.84 | \$1,621,569.   |
|                         |                | 0001     | 0750        | 6181020      | ADDITIONAL MOBILIZATION FOR SEEDING  | 2.00            | 0.00             | 2.00                   | EA   | 0.00                        | \$600.00       | \$0.0  |
|                         |                | 0001     | 0760        | 6189901      | MISC.TEMPORARY RAILROAD CROSSING   | 1.00            | 0.00             | 1.00                   | LS   | 0.00                        | \$30,000.00    | \$0.   |
|                         |                | 0001     | 0765        | 6189916      | MISC.ACCELERATING THE COMPLETION OF WORK REQUIRING RAILROAD FLAGGERS (INCENTIVE/DISINCENTIVE CLAUSE) | 1,000.00        | 0.00             | 1,000.00               | DLR  | 0.00                        | \$0.00         | \$0.0  |
|                         |                | 0001     | 0770        | 6200015      | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE   | 505.00          | 0.00             | 505.00                 | LF   | 0.00                        | \$25.00        | \$0.   |
|                         |                | 0001     | 0780        | 6200021      | PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW   | 19.00           | 0.00             | 19.00                  | EA   | 0.00                        | \$320.00       | \$0.   |
|                         |                | 0001     | 0790        | 6200027      | PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT                                      | 7.00            | 0.00             | 7.00                   | EA   | 0.00                        | \$450.00       | \$0.   |
|                         |                | 0001     | 0800        | 6200030      | PREFORMED THERMOPLASTIC PAVEMENT MARKING, WORD (ONLY)  | 9.00            | 0.00             | 9.00                   | EA   | 0.00                        | \$450.00       | \$0.   |
|                         |                | 0001     | 0810        | 6200036      | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK                                       | 114.00          | 0.00             | 114.00                 | EA   | 0.00                        | \$200.00       | \$0.   |
|                         |                | 0001     | 0820        | 6200042      | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES                          | 14.00           | 0.00             | 14.00                  | EA   | 0.00                        | \$50.00        | \$0.   |
|                         |                | 0001     | 0830        | 6205902A     | 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS                               | 21,905.00       | 0.00             | 21,905.00              | LF   | 0.00                        | \$0.50         | \$0.   |
|                         |                | 0001     | 0840        |              | 6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS                              | 12,373.00       | 0.00             | 12,373.00              | LF   | 0.00                        | \$0.50         | \$0.   |
|                         |                | 0001     | 0850        | 6205906A     | 12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS                              | 4,999.00        | 0.00             | 4,999.00               | LF   | 0.00                        | \$1.00         | \$0.   |
|                         |                | 0001     | 0860        | 6206000C     | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING   | 9,364.00        | 0.00             | 9,364.00               | LF   | 0.00                        | \$0.50         | \$0.0  |

Revision 4/1/2020 Page 11 of 45



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Note: Posted Qu         | uantities      | and Valu | ies are     | based on F   | Report Generated date and can differ from the posted am                         | ount at the     | time the Es            | timate was                   | Generat | ed.                                |              |  |
|-------------------------|----------------|----------|-------------|--------------|---|-----------------|------------------------|------------------------------|---------|------------------------------------|--------------|--|
| Contract<br>Nm.CONTRACT | Project<br>No. | Category | Line<br>No. | Item<br>Code | Description   | Bid<br>Quantity | Net<br>Change<br>Order | Total<br>Current<br>Quantity | Unit    | Total<br>Posted<br>Approved<br>Qty | Unit Price   | Total Value POSTED<br>To Date (See report<br>generated date) |
| 200515-F15              | J6I2222        |          |             |              | PAINT, TYPE P BEADS   |                 |                        |                              |         | ,                                  |              |  |
|                         |                | 0001     | 0870        | 6206001C     | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT<br>MARKING PAINT. TYPE P BEADS        | 3,485.00        | 0.00                   | 3,485.00                     | LF      | 0.00                               | \$0.50       | \$0.00   |
|                         |                | 0001     | 0880        | 6206124A     | 24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING                               | 91.00           | 0.00                   | 91.00                        | LF      | 0.00                               | \$10.00      | \$0.00   |
|                         |                | 0001     | 0890        | 6206125A     | PAINT, TYPE P BEADS  24 IN. YELLOW STANDARD WATERBORNE PAVEMENT                 | 84.00           | 0.00                   | 84.00                        | LF      | 0.00                               | \$10.00      | \$0.00   |
|                         |                | 0001     | 0900        | 6207001      | MARKING PAINT, TYPE P BEADS PAVEMENT MARKING REMOVAL                            | 7,291.00        | 0.00                   | 7,291.00                     | LF      | 0.00                               | \$1.00       | \$0.00   |
|                         |                | 0001     | 0910        | 6207002      | PAVEMENT MARKING REMOVAL (SYMBOLS)  | 56.00           | 0.00                   | 56.00                        | EA      | 0.00                               | \$50.00      | \$0.00   |
|                         |                | 0001     | 0920        | 6209902      | MISC.ISLAND TUBULAR MARKER  | 8.00            | 0.00                   | 8.00                         | EA      | 0.00                               | \$110.00     | \$0.00   |
|                         |                | 0001     | 0930        | 6209902      | MISC.PREFORMED THERMOPLASTIC PAVEMENT MARKING,                                  | 8.00            | 0.00                   | 8.00                         | EA      | 0.00                               | \$2,000.00   | \$0.00   |
|                         |                | 0001     | 0940        | 6209902      | LANE REDUCTION ARROW  MISC.TIER TWO INLAID PAVEMENT MARKER SYSTEM               | 8.00            | 0.00                   | 8.00                         | EA      | 0.00                               | \$4,475.00   | \$0.00   |
|                         |                | 0001     | 0950        | 6221001      | COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF                                  | 2,356.00        | 0.00                   | 2,356.00                     | SQYD    | 0.00                               | \$6.75       | \$0.00   |
|                         |                | 0001     | 0960        | 6221003      | SURFACING (3 IN. THICK OR LESS)  COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF | 10,196.00       | 0.00                   | 10,196.00                    | SQYD    | 0.00                               | \$3.85       | \$0.00   |
|                         |                | 0001     | 0970        | 6224010      | SURFACING (GREATER THAN 3 IN. THICK)  MODIFIED COLDMILLING (DEPTH TRANSITIONS)  | 150.00          | 0.00                   | 150.00                       | SQYD    | 0.00                               | \$13.50      | \$0.00   |
|                         |                | 0001     | 0980        | 6240103A     | PERMANENT EROSION CONTROL GEOTEXTILE  | 3,917.00        | 0.00                   | 3,917.00                     | SQYD    | 0.00                               | \$3.00       | \$0.00   |
|                         |                | 0001     | 0990        | 6249905      | MISC.Miscellaneous Granular Drainage Blanket                                    | 2,115.00        | 286.00                 | 2,401.00                     | SQYD    | 2,401.00                           | \$15.50      | \$37,215.50  |
|                         |                | 0001     | 1000        | 6274000      | CONTRACTOR FURNISHED SURVEYING AND STAKING                                      | 1.00            | 0.00                   | 1.00                         | LS      | 0.40                               | \$125,000.00 | \$50,000.00  |
|                         |                | 0001     | 1010        | 7011105      | DRILLED SHAFTS (3 FT. 6 IN. DIA.)   | 30.00           | 0.00                   | 30.00                        | LF      | 0.00                               | \$415.00     | \$0.00   |
|                         |                | 0001     | 1020        | 7011107      | DRILLED SHAFTS (4 FT. 6 IN. DIA.)   | 39.00           | 0.00                   | 39.00                        | LF      | 0.00                               | \$415.00     | \$0.00   |
|                         |                | 0001     | 1030        | 7011207      | ROCK SOCKETS (4 FT 6 IN. DIA.)  | 6.00            | 0.00                   | 6.00                         | LF      | 0.00                               | \$415.00     | \$0.00   |
|                         |                | 0001     | 1040        | 7011600      | SONIC LOGGING TESTING   | 1.00            | 0.00                   | 1.00                         | EA      | 0.00                               | \$1,000.00   | \$0.00   |
|                         |                | 0001     | 1050        | 7019903      | MISC.Miscellaneous Stone Columns  | 6,535.00        | -5,583.00              | 952.00                       | LF      | 952.00                             | \$25.00      | \$23,800.00  |
|                         |                | 0001     | 1060        | 7033009      | AESTHETIC CONCRETE STAIN  | 1.00            | 0.00                   | 1.00                         | LS      | 0.00                               | \$6,110.88   | \$0.00   |
|                         |                | 0001     | 1080        | 7061000      | REINFORCING STEEL   | 5,740.00        | 0.00                   | 5,740.00                     | LB      | 0.00                               | \$1.60       | \$0.00   |
|                         |                | 0001     | 1090        | 7201000      | MECHANICALLY STABILIZED EARTH WALL SYSTEMS                                      | 3,394.00        | 0.00                   | 3,394.00                     | SQFT    | 3,394.00                           | \$60.00      | \$203,640.00   |
|                         |                | 0001     | 1100        | 7201200      | SELECT GRANULAR BACKFILL FOR STRUCTURAL SYSTEMS                                 | 12,416.00       | 0.00                   | 12,416.00                    | CUYD    | 8,552.00                           | \$30.00      | \$256,560.00   |
|                         |                | 0001     | 1110        | 7261015      | 15 IN. PIPE GROUP A   | 3,631.00        | 0.00                   | 3,631.00                     | LF      | 1,266.00                           | \$70.00      | \$88,620.00  |
|                         |                | 0001     | 1120        | 7261018      | 18 IN. PIPE GROUP A   | 1,252.00        | 0.00                   | 1,252.00                     | LF      | 375.00                             | \$80.00      | \$30,000.00  |
|                         |                | 0001     | 1130        | 7261024      | 24 IN. PIPE GROUP A   | 118.00          | 0.00                   | 118.00                       | LF      | 0.00                               | \$135.00     | \$0.00   |
|                         |                | 0001     | 1140        | 7261030      | 30 IN. PIPE GROUP A   | 298.00          | 0.00                   | 298.00                       | LF      | 298.00                             | \$250.00     | \$74,500.00  |
|                         |                | 0001     | 1150        | 7261036      | 36 IN. PIPE GROUP A   | 54.00           | 0.00                   | 54.00                        | LF      | 54.00                              | \$400.00     | \$21,600.00  |
|                         |                | 0001     | 1160        | 7279901      | MISC.MSD SPECIAL DRAINAGE STRUCTURE #"301"                                      | 1.00            | 0.00                   | 1.00                         | LS      | 1.00                               | \$55,000.00  | \$55,000.00  |
|                         |                | 0001     | 1170        | 7311022      | PRECAST CONCRETE DROP INLET 2 FT X 2 FT   | 57.00           | 0.00                   | 57.00                        | FT      | 21.91                              | \$350.00     | \$7,668.50   |
|                         |                | 0001     | 1180        | 7311042      | PRECAST CONCRETE DROP INLET 4 FT X 2 FT   | 178.00          | 0.00                   | 178.00                       | FT      | 77.00                              | \$450.00     | \$34,650.00  |
|                         |                | 0001     | 1190        | 7311053      | PRECAST CONCRETE DROP INLET 5 FT X 3 FT   | 56.00           | 0.00                   | 56.00                        | FT      | 36.00                              | \$650.00     | \$23,400.00  |
|                         |                | 0001     | 1200        | 7319913      | MISC.MSD Standard 60" Manhole   | 56.00           | 0.00                   | 56.00                        | FT      | 56.00                              | \$510.00     | \$28,560.00  |
|                         |                | 0001     | 1210        | 7319913      | MISC.MSD Standard Line 48" Manhole  | 76.00           | 0.00                   | 76.00                        | FT      | 45.00                              | \$350.00     | \$15,750.00  |
|                         |                | 0001     | 1220        | 7320615A     | 15 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION                         | 1.00            | 1.00                   | 2.00                         | EA      | 2.00                               | \$800.00     | \$1,600.00   |
|                         |                | 0001     | 1230        | 7320624A     | 24 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END<br>SECTION                      | 2.00            | 0.00                   | 2.00                         | EA      | 0.00                               | \$1,000.00   | \$0.00   |
|                         |                | 0001     | 1240        | 7320630A     |   | 1.00            | 0.00                   | 1.00                         | EA      | 0.00                               | \$1,500.00   | \$0.00   |
|                         |                | 0001     | 1245        | 8031000A     | TURF TYPE TALL FESCUE SODDING   | 1,242.00        | 0.00                   | 1,242.00                     | SQYD    | 0.00                               | \$8.50       | \$0.00   |
|                         |                | 0001     | 1260        | 8059919      | MISC.WARM OR COOL SEASON MIXTURES   | 9.00            | 0.00                   | 9.00                         | ACRE    | 0.00                               | \$1,975.00   | \$0.00   |
|                         |                | 0001     | 1270        | 8061003      | SEDIMENT TRAP EXCAVATION  | 57.00           | 0.00                   | 57.00                        | CUYD    | 0.00                               | \$25.00      | \$0.00   |
|                         |                | 0001     | 1280        | 8061004      | SEDIMENT TRAP ROCK  | 7.00            | 0.00                   | 7.00                         | CUYD    | 0.00                               | \$100.00     | \$0.00   |
|                         |                | 0001     | 1290        | 8061005      | ROCK DITCH CHECK  | 2,613.00        | 0.00                   | 2,613.00                     | LF      | 24.00                              | \$10.50      | \$252.00   |
|                         |                | 0001     | 1300        | 8061007A     | CURB INLET CHECK  | 111.00          | 0.00                   | 111.00                       | EA      | 0.00                               | \$115.00     | \$0.00   |
|                         |                | 0001     | 1310        | 8061016      | SEDIMENT REMOVAL  | 267.00          | 0.00                   | 267.00                       | CUYD    | 205.00                             | \$25.00      | \$5,125.00   |

Page 12 of 45 Revision 4/1/2020



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract<br>Nm.CONTRACT | Project<br>No. | Category | Line<br>No. | Item<br>Code | Report Generated date and can differ from the posted am  Description | Bid<br>Quantity | Net<br>Change | Total<br>Current | Unit | Total<br>Posted | Unit Price  | Total Value POSTED<br>To Date (See report |
|-------------------------|----------------|----------|-------------|--------------|--|-----------------|---------------|------------------|------|-----------------|-------------|---|
|                         |                |          |             |              |  |                 | Order         | Quantity         |      | Approved<br>Qty |             | generated date)                           |
| 200515-F15              | J6I2222        | 0001     | 1320        | 8061017      | TEMPORARY SEEDING AND MULCHING                                       | 14.00           | 0.00          | 14.00            | ACRE | 0.00            | \$1,500.00  | \$0.00                                    |
|                         |                | 0001     | 1330        | 8061019      | SILT FENCE   | 8,207.00        | 0.00          | 8,207.00         | LF   | 2,258.00        | \$2.25      | \$5,080.50                                |
|                         |                | 0001     | 1340        | 8064128      | TYPE 1 TURF REINFORCEMENT MAT  | 913.00          | 0.00          | 913.00           | SQYD | 0.00            | \$5.15      | \$0.00                                    |
|                         |                | 0002     | 1350        | 3030600      | FURNISHING ROCK BASE MATERIAL  | 3,355.00        | 0.00          | 3,355.00         | SQYD | 0.00            | \$0.00      | \$0.00                                    |
|                         |                | 0002     | 1360        | 3030610A     | PLACING ROCK BASE  | 3,355.00        | 0.00          | 3,355.00         | SQYD | 0.00            | \$0.00      | \$0.00                                    |
|                         |                | 0002     | 1370        | 4030419      | 9 INCHES, ASPHALTIC CONCRETE PAVEMENT SP125CLP                       | 2,073.00        | 0.00          | 2,073.00         | SQYD | 0.00            | \$0.00      | \$0.00                                    |
|                         |                | 0003     | 1380        | 3030600      | FURNISHING ROCK BASE MATERIAL  | 3,363.00        | 0.00          | 3,363.00         | SQYD | 0.00            | \$10.50     | \$0.00                                    |
|                         |                | 0003     | 1390        | 3030610A     | PLACING ROCK BASE  | 3,363.00        | 0.00          | 3,363.00         | SQYD | 0.00            | \$5.50      | \$0.00                                    |
|                         |                | 0003     | 1400        | 5021332      | CONCRETE PAVEMENT (8 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)          | 2,073.00        | 0.00          | 2,073.00         | SQYD | 0.00            | \$51.00     | \$0.00                                    |
|                         |                | 0004     | 1410        | 4010150      | TYPE A2 SHOULDER   | 206.10          | 0.00          | 206.10           | SQYD | 0.00            | \$0.00      | \$0.00                                    |
|                         |                | 0004     | 1420        | 6091010      | CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S                        | 304.00          | 0.00          | 304.00           | LF   | 0.00            | \$0.00      | \$0.00                                    |
|                         |                | 0005     | 1430        | 5021340      | TYPE A2 SHOULDER   | 206.10          | 0.00          | 206.10           | SQYD | 0.00            | \$35.50     | \$0.00                                    |
|                         |                | 0005     | 1440        | 6092011      | INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A                        | 304.00          | 0.00          | 304.00           | LF   | 0.00            | \$20.00     | \$0.00                                    |
|                         |                | 0006     | 1450        | 3040506      | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)                              | 20,740.00       | 0.00          | 20,740.00        | SQYD | 0.00            | \$0.00      | \$0.00                                    |
|                         |                | 0006     | 1460        | 4039905      | MISC.11.5 INCHES, ASPHALTIC CONCRETE PAVEMENT<br>SP125CLP            | 10,939.00       | 0.00          | 10,939.00        | SQYD | 0.00            | \$0.00      | \$0.00                                    |
|                         |                | 0006     | 1470        | 4039905      | MISC.9.5 INCHES, ASPHALTIC CONCRETE PAVEMENT                         | 6,859.00        | 0.00          | 6,859.00         | SQYD | 0.00            | \$0.00      | \$0.00                                    |
|                         |                | 0006     | 1480        | 6091010      | SP125CLP  CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S              | 2,017.00        | 0.00          | 2,017.00         | LF   | 0.00            | \$0.00      | \$0.00                                    |
|                         |                | 0007     | 1490        | 3040506      | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)                              | 20.910.00       | 0.00          | 20,910.00        | SQYD | 2,629.87        | \$6.50      | \$17,094.16                               |
|                         |                | 0007     | 1500        | 5021308      | CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT.                      | 6,859.00        | 0.00          | 6,859.00         | SQYD | 0.00            | \$51.00     | \$0.00                                    |
|                         |                |          |             |              | JOINTS)  |                 |               |                  |      |                 |             |   |
|                         |                | 0007     | 1510        | 5021309      | CONCRETE PAVEMENT (9 IN. NON-REINFORCED 15 FT. JOINTS)               | 10,939.00       | 0.00          | 10,939.00        | SQYD | 1,259.30        | \$54.00     | \$68,002.20                               |
|                         |                | 0007     | 1520        | 6092011      | INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A                        | 2,017.00        | 0.00          | 2,017.00         | LF   | 0.00            | \$15.00     | \$0.00                                    |
|                         |                | 8000     | 1530        | 4010150      | TYPE A2 SHOULDER   | 3,806.80        | 0.00          | 3,806.80         | SQYD | 0.00            | \$0.00      | \$0.00                                    |
|                         |                | 8000     | 1540        | 6091010      | CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S                        | 3,319.00        | 0.00          | 3,319.00         | LF   | 0.00            | \$0.00      | \$0.00                                    |
|                         |                | 0009     | 1550        | 5021340      | TYPE A2 SHOULDER   | 3,806.80        | 0.00          | 3,806.80         | SQYD | 865.37          | \$35.00     | \$30,287.95                               |
|                         |                | 0009     | 1560        | 6092011      | INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A                        | 3,319.00        | 0.00          | 3,319.00         | LF   | 225.00          | \$15.00     | \$3,375.00                                |
|                         |                | 0010     | 1570        | 6061060      | MGS GUARDRAIL  | 3,813.00        | 0.00          | 3,813.00         | LF   | 413.00          | \$19.00     | \$7,847.00                                |
|                         |                | 0010     | 1580        | 6061068      | MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)               | 2.00            | 0.00          | 2.00             | EA   | 0.00            | \$2,850.00  | \$0.00                                    |
|                         |                | 0010     | 1590        | 6061069      | MGS BRIDGE APPROACH TRANSITION SECTION (REGULARINO CURB)             | 2.00            | 0.00          | 2.00             | EA   | 0.00            | \$2,800.00  | \$0.00                                    |
|                         |                | 0010     | 1600        | 6061070      | MGS VERTICAL CONCRETE BARRIER TRANSITION                             | 11.00           | 0.00          | 11.00            | EA   | 3.00            | \$2,750.00  | \$8,250.00                                |
|                         |                | 0010     | 1610        | 6061080      | MGS END ANCHOR   | 8.00            | 0.00          | 8.00             | EA   | 1.00            | \$1,000.00  | \$1,000.00                                |
|                         |                | 0010     | 1620        | 6063014      | TYPE A CRASHWORTHY END TERMINAL (MASH)                               | 12.00           | 0.00          | 12.00            | EA   | 3.00            | \$2,600.00  | \$7,800.00                                |
|                         |                | 0010     | 1630        | 6063019      | TYPE E CRASHWORTHY END TERMINAL                                      | 1.00            | 0.00          | 1.00             | EA   | 0.00            | \$27,500.00 | \$0.00                                    |
|                         |                | 0020     | 1640        | 9011330      | LUMINAIRE, 1000 WATT HIGH PRESSURE SODIUM HIGH MAST                  | 16.00           | 0.00          | 16.00            | EA   | 0.00            | \$1,018.00  | \$0.00                                    |
|                         |                | 0020     | 1650        | 9013002      | CONDUIT, 2 IN. RIGID, IN TRENCH                                      | 26.00           | 0.00          | 26.00            | LF   | 0.00            | \$10.45     | \$0.00                                    |
|                         |                | 0020     | 1660        | 9013003      | CONDUIT, 3 IN. RIGID, IN TRENCH                                      | 282.00          | 0.00          | 282.00           | LF   | 0.00            | \$11.00     | \$0.00                                    |
|                         |                | 0020     | 1670        | 9013004      | CONDUIT, 4 IN. RIGID, IN TRENCH                                      | 23.00           | 0.00          | 23.00            | LF   | 0.00            | \$12.35     | \$0.00                                    |
|                         |                | 0020     | 1680        | 9014004      | CONDUIT, 4 IN. RIGID, PUSHED   | 339.00          | 0.00          | 339.00           | LF   | 0.00            | \$26.60     | \$0.00                                    |
|                         |                | 0020     | 1690        | 9015010      | TRENCHING TYPE I   | 2,136.00        | 0.00          | 2,136.00         | LF   | 0.00            | \$3.80      | \$0.00                                    |
|                         |                | 0020     | 1700        | 9015020      | TRENCHING TYPE II  | 237.00          | 0.00          | 237.00           | LF   | 0.00            | \$3.80      | \$0.00                                    |
|                         |                | 0020     | 1710        | 9016110      | PULL BOX, PREFORMED CLASS 1  | 15.00           | 0.00          | 15.00            | EA   | 0.00            | \$765.00    | \$0.00                                    |
|                         |                | 0020     | 1720        | 9016112      | PULL BOX, PREFORMED CLASS 3  | 2.00            | 0.00          | 2.00             | EA   | 0.00            | \$1,343.00  | \$0.00                                    |
|                         |                | 0020     | 1730        | 9017110      | CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET                          | 360.00          | 0.00          | 360.00           | LF   | 0.00            | \$0.55      | \$0.00                                    |
|                         |                | 0020     | 1740        | 9017401      | CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 2 AWG         | 800.00          | 0.00          | 800.00           | LF   | 0.00            | \$6.00      | \$0.00                                    |
|                         |                | 0020     | 1750        | 9017404      | CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 6 AWG         | 2,190.00        | 0.00          | 2,190.00         | LF   | 0.00            | \$3.60      | \$0.00                                    |
|                         |                | 0020     | 1760        | 9017407      | CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG         | 1,010.00        | 0.00          | 1,010.00         | LF   | 0.00            | \$2.90      | \$0.00                                    |

Revision 4/1/2020 Page 13 of 45



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| otal Value POSTED<br>o Date (See report<br>generated date) | Unit Price  | Total<br>Posted<br>Approved | Unit | Total Current Quantity | Net<br>Change<br>Order | Bid<br>Quantity | Report Generated date and can differ from the posted amo<br>Description              | Item<br>Code | Line<br>No. | Category | Project<br>No. | Contract<br>Nm.CONTRACT |
|--|-------------|-----------------------------|------|------------------------|------------------------|-----------------|--|--------------|-------------|----------|----------------|-------------------------|
| \$0.00   | \$1,068.00  | Qty<br>0.00                 | EA   | 4.00                   | 0.00                   | 4.00            | POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)                                   | 9018245      | 1770        | 0020     | J6I2222        | 200515-F15              |
| \$16,605.00  | \$16,605.00 | 1.00                        | LS   | 1.00                   | 0.00                   | 1.00            | MISC.EXTERNAL CONDUIT SYSTEM ON STRUCTURE  | 9019901      | 1780        | 0020     |                |                         |
| \$0.00   | \$34,530.00 | 0.00                        | EA   | 2.00                   | 0.00                   | 2.00            | MISC.150 FT HIGH MAST POLE   | 9019902      | 1790        | 0020     |                |                         |
| \$0.00   | \$2,250.00  | 0.00                        | EA   | 4.00                   | 0.00                   | 4.00            | MISC.45 FT TOP MOUNT POLES, TYPE AT  | 9019902      | 1800        | 0020     |                |                         |
| \$0.00   | \$483.00    | 0.00                        | EA   | 1.00                   | 0.00                   | 1.00            | MISC.ADJUST PULL BOX TO GRADE  | 9019902      | 1810        | 0020     |                |                         |
| \$0.00   | \$7,258.00  | 0.00                        | EA   | 2.00                   | 0.00                   | 2.00            | MISC.BASE MOUNTED 240/480V COMBINATION POWER   | 9019902      | 1820        | 0020     |                |                         |
|  |             |                             |      |                        |                        |                 | SUPPLY AND CONTROLLER  |              |             |          |                |                         |
| \$0.00   | \$572.00    | 0.00                        | EA   | 4.00                   | 0.00                   | 4.00            | MISC.LED-C TOP-MOUNT LUMINAIRE   | 9019902      | 1830        | 0020     |                |                         |
| \$0.00   | \$15.85     | 0.00                        | LF   | 549.00                 | 0.00                   | 549.00          | MISC.1 IN RIGID GALVANIZED STEEL CONDUIT   | 9019903      | 1840        | 0020     |                |                         |
| \$0.0  | \$1.65      | 0.00                        | LF   | 1,830.00               | 0.00                   | 1,830.00        | MISC.THHN CABLE 2C #6 AWG  | 9019903      | 1850        | 0020     |                |                         |
| \$0.00   | \$761.00    | 0.00                        | EA   | 3.00                   | 0.00                   | 3.00            | SIGNAL HEAD, TYPE 3S   | 9020213      | 1860        | 0030     |                |                         |
| \$0.00   | \$927.00    | 0.00                        | EA   | 37.00                  | 0.00                   | 37.00           | SIGNAL HEAD, TYPE 3B   | 9020513      | 1870        | 0030     |                |                         |
| \$0.00   | \$1,038.00  | 0.00                        | EA   | 3.00                   | 0.00                   | 3.00            | SIGNAL HEAD, TYPE 4B   | 9020514      | 1880        | 0030     |                |                         |
| \$0.00   | \$12.50     | 0.00                        | SQFT | 133.00                 | 0.00                   | 133.00          | SH-FLAT SHEET - SIGNAL SIGN  | 9020833      | 1890        | 0030     |                |                         |
| \$0.00   | \$33.00     | 0.00                        | EA   | 41.00                  | 0.00                   | 41.00           | SIGNAL SIGN, MOUNTING HARDWARE   | 9020834      | 1900        | 0030     |                |                         |
| \$0.00   | \$645.00    | 0.00                        | EA   | 18.00                  | 0.00                   | 18.00           | POST, SIGNAL 8 FT. OR 2.4 M  | 9022708      | 1910        | 0030     |                |                         |
| \$0.00   | \$972.00    | 0.00                        | EA   | 1.00                   | 0.00                   | 1.00            | POST, SIGNAL 15 FT. OR 4.6 M   | 9022715      | 1920        | 0030     |                |                         |
| \$0.00   | \$7,324.00  | 0.00                        | EA   | 1.00                   | 0.00                   | 1.00            | POST, TYPE C, 30 FT. ARM OR 9.1 M ARM  | 9023230      | 1930        | 0030     |                |                         |
| \$0.00   | \$7,532.00  | 0.00                        | EA   | 1.00                   | 0.00                   | 1.00            | POST, TYPE C, 35 FT. ARM OR 10.7 M ARM   | 9023235      | 1940        | 0030     |                |                         |
| \$0.00   | \$10,292.00 | 0.00                        | EA   | 1.00                   | 0.00                   | 1.00            | POST, TYPE C, 50 FT. ARM OR 15.2 M ARM   | 9023250      | 1950        | 0030     |                |                         |
| \$0.0  | \$11,930.00 | 0.00                        | EA   | 4.00                   | 0.00                   | 4.00            | POST, TYPE C, 55 FT. ARM   | 9023255      | 1960        | 0030     |                |                         |
| \$0.0  | \$12,945.00 | 0.00                        | EA   | 1.00                   | 0.00                   | 1.00            | POST, TYPE B, LONGEST ARM 35 FT. OR 10.7 M   | 9023335      | 1970        | 0030     |                |                         |
| \$0.0  | \$12,439.00 | 0.00                        | EA   | 1.00                   | 0.00                   | 1.00            | POST, TYPE B, LONGEST ARM 45 FT. OR 13.7 M   | 9023345      | 1980        | 0030     |                |                         |
| \$0.0  | \$13,359.00 | 0.00                        | EA   | 3.00                   | 0.00                   | 3.00            | CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER                                     | 9024283      | 1990        | 0030     |                |                         |
| \$0.0  | \$12,698.00 | 0.00                        | EA   | 4.00                   | 0.00                   | 4.00            | VIDEO DETECTION SYSTEM   | 9024975      | 2000        | 0030     |                |                         |
| \$0.0  | \$10.20     | 0.00                        | LF   | 1,320.00               | 0.00                   | 1,320.00        | CONDUIT, 3 IN., TRENCH WITH TRACER WIRE  | 9025300      | 2010        | 0030     |                |                         |
| \$0.0  | \$23.00     | 0.00                        | LF   | 844.00                 | 0.00                   | 844.00          | CONDUIT, 3 IN., PUSHED WITH TRACER WIRE  | 9027300      | 2020        | 0030     |                |                         |
| \$0.0  | \$0.95      | 0.00                        | LF   | 3,350.00               | 0.00                   | 3,350.00        | CABLE, 8 AWG 1 CONDUCTOR, POWER  | 9028208      | 2030        | 0030     |                |                         |
| \$0.0  | \$0.50      | 0.00                        | LF   | 3,730.00               | 0.00                   | 3,730.00        | CABLE, 16 AWG 2 CONDUCTOR  | 9028308      | 2040        | 0030     |                |                         |
| \$0.0  | \$1.10      | 0.00                        | LF   | 3,750.00               | 0.00                   | 3,750.00        | CABLE, 16 AWG 5 CONDUCTOR  | 9028310      | 2050        | 0030     |                |                         |
| \$0.0  | \$1.60      | 0.00                        | LF   | 6,790.00               | 0.00                   | 6,790.00        | CABLE, 16 AWG 7 CONDUCTOR  | 9028311      | 2060        |          |                |                         |
| \$0.0  | \$602.00    | 0.00                        | EA   |                        | 0.00                   |                 | PULL BOX. PREFORMED CLASS 1  | 9028810      | 2070        | 0030     |                |                         |
|  |             |                             |      | 10.00                  |                        | 10.00           |  |              |             | 0030     |                |                         |
| \$0.0  | \$1,221.00  | 0.00                        | EA   | 8.00                   | 0.00                   | 8.00            | PULL BOX, PREFORMED CLASS 2  | 9028811      | 2080        | 0030     |                |                         |
| \$0.0  | \$1,642.00  | 0.00                        | EA   | 3.00                   | 0.00                   | 3.00            | PULL BOX, PREFORMED CLASS 3  | 9028812      | 2090        | 0030     |                |                         |
| \$0.0  | \$1,160.00  | 0.00                        | CUYD | 44.00                  | 0.00                   | 44.00           | BASE, CONCRETE   | 9029100      | 2100        | 0030     |                |                         |
| \$0.0  | \$65,520.00 | 0.00                        | LS   | 1.00                   | 0.00                   | 1.00            | MISC.TRAFFIC SIGNAL MAINTENANCE AND PROGRAMMING                                      | 9029901      | 2110        | 0030     |                |                         |
| \$0.0  | \$3,214.00  | 0.00                        | EA   | 3.00                   | 0.00                   | 3.00            | MISC.ATC TRAFFIC SIGNAL CONTROLLER   | 9029902      | 2120        | 0030     |                |                         |
| \$0.0  | \$715.00    | 0.00                        | EA   | 24.00                  | 0.00                   | 24.00           | MISC.AUDIBLE PEDESTRIAN PUSH BUTTON AND SIGNING                                      | 9029902      | 2130        | 0030     |                |                         |
| \$0.0  | \$14,267.00 | 0.00                        | EA   | 1.00                   | 0.00                   | 1.00            | MISC.COMBINATION PAD MOUNTED 120V/240V POWER SUPPLY AND LIGHTING CONTROLLER WITH UPS | 9029902      | 2140        | 0030     |                |                         |
| \$0.0  | \$3,863.00  | 0.00                        | EA   | 1.00                   | 0.00                   | 1.00            | MISC.CONCRETE TRANSFORMER PAD  | 9029902      | 2150        | 0030     |                |                         |
| \$0.0  | \$450.00    | 0.00                        | EA   | 22.00                  | 0.00                   | 22.00           | MISC.Countdown Pedestrian Signal Head, Type 1S                                       | 9029902      | 2160        | 0030     |                |                         |
| \$0.0  | \$4,795.00  | 0.00                        | EA   | 1.00                   | 0.00                   | 1.00            | MISC.Install 55' Arm on Existing Signal Post   | 9029902      | 2170        | 0030     |                |                         |
| \$0.0  | \$1,010.00  | 0.00                        | EA   | 3.00                   | 0.00                   | 3.00            | MISC.NETWORK CONNECTED SIGNAL MONITOR  | 9029902      | 2180        | 0030     |                |                         |
| \$0.0  | \$10.20     | 0.00                        | LF   | 255.00                 | 0.00                   | 255.00          | MISC.3" PVC CONDUIT WITH PULL TAPE   | 9029903      | 2190        | 0030     |                |                         |
| \$0.0  | \$1,400.00  | 0.00                        | CUYD | 10.60                  | 0.00                   | 10.60           | CONCRETE FOOTINGS, EMBEDDED  | 9031010      | 2200        | 0040     |                |                         |
| \$15,000.0   | \$1,200.00  | 12.50                       | CUYD | 88.80                  | 6.50                   | 82.30           | CONCRETE FOOTINGS, BOLT DOWN   | 9031020      | 2210        | 0040     |                |                         |
| \$0.0  | \$4.50      | 0.00                        | LB   | 3,150.00               | 0.00                   | 3,150.00        | STRUCTURAL STEEL POSTS   | 9031210      | 2220        | 0040     |                |                         |
| \$0.0  | \$3.75      | 0.00                        | LB   | 5,390.00               | 0.00                   | 5,390.00        | PIPE POSTS   | 9031220      | 2230        | 0040     |                |                         |

Page 14 of 45 Revision 4/1/2020



### Total Paid / All Items / All Estimates (Including this Estimate)

|                         | uantities      |          |             | based on I   | Report Generated date and can differ from the posted a           |                 | time the Es            | timate was                   |      | ed.                                |             |  |
|-------------------------|----------------|----------|-------------|--------------|--|-----------------|------------------------|------------------------------|------|------------------------------------|-------------|--|
| Contract<br>Nm.CONTRACT | Project<br>No. | Category | Line<br>No. | Item<br>Code | Description  | Bid<br>Quantity | Net<br>Change<br>Order | Total<br>Current<br>Quantity | Unit | Total<br>Posted<br>Approved<br>Qty | Unit Price  | Total Value POSTED<br>To Date (See report<br>generated date) |
| 200515-F15              | J6I2222        | 0040     | 2240        | 9031270A     | 2 IN. PSST POST - 12 GA.   | 60.00           | 0.00                   | 60.00                        | LF   | 0.00                               | \$12.00     | \$0.00   |
|                         |                | 0040     | 2250        | 9031271      | POST ANCHOR FOR 2 IN. PSST - 12 GA.                              | 21.00           | 0.00                   | 21.00                        | LF   | 0.00                               | \$40.00     | \$0.00   |
|                         |                | 0040     | 2260        | 9035004A     | SH-FLAT SHEET  | 598.00          | 0.00                   | 598.00                       | SQFT | 0.00                               | \$21.00     | \$0.00   |
|                         |                | 0040     | 2270        | 9035011A     | ST-STRUCTURAL  | 2,364.00        | 0.00                   | 2,364.00                     | SQFT | 0.00                               | \$24.00     | \$0.00   |
|                         |                | 0040     | 2280        | 9035069A     | SHF-FLAT SHEET FLUORESCENT                                       | 93.00           | 0.00                   | 93.00                        | SQFT | 0.00                               | \$24.00     | \$0.00   |
|                         |                | 0040     | 2290        | 9035071A     | STF-STRUCTURAL FLUORESCENT                                       | 390.00          | 0.00                   | 390.00                       | SQFT | 0.00                               | \$26.00     | \$0.00   |
|                         |                | 0040     | 2300        | 9036036      | TUBULAR SUPPORT, TYPE C-2315-20                                  | 2.00            | 0.00                   | 2.00                         | EA   | 0.00                               | \$12,950.00 | \$0.00   |
|                         |                | 0040     | 2310        | 9036042      | TUBULAR SUPPORT, TYPE C-2018-28                                  | 2.00            | 0.00                   | 2.00                         | EA   | 0.00                               | \$20,000.00 | \$0.00   |
|                         |                | 0040     | 2320        | 9039901      | MISC.SIGN 12 CANTILEVER BOX TRUSS, 30 FT ARM                     | 1.00            | 0.00                   | 1.00                         | LS   | 0.00                               | \$29,000.00 | \$0.00   |
|                         |                | 0040     | 2330        | 9039901      | MISC.SIGN 4 SPAN BOX TRUSS (98 FT)                               | 1.00            | 0.00                   | 1.00                         | LS   | 0.00                               | \$66,000.00 | \$0.00   |
|                         |                | 0040     | 2340        | 9039901      | MISC.SIGN 8 SPAN BOX TRUSS (83 FT-5 IN)                          | 1.00            | 0.00                   | 1.00                         | LS   | 0.00                               | \$52,500.00 | \$0.00   |
|                         |                | 0040     | 2350        | 9039901      | MISC.SPECIAL STREET NAME BRIDGE MOUNTED SIGNS                    | 1.00            | 0.00                   | 1.00                         | LS   | 0.00                               | \$20,000.00 | \$0.00   |
|                         |                | 0050     | 2360        | 9108208      | CABLE, 8 AWG, 1 CONDUCTOR, POWER                                 | 2,510.00        | 0.00                   | 2,510.00                     | LF   | 0.00                               | \$1.00      | \$0.00   |
|                         |                | 0050     | 2370        | 9108408      | WIRE, 8 AWG, BARE NEUTRAL  | 1,010.00        | 0.00                   | 1,010.00                     | LF   | 0.00                               | \$1.00      | \$0.00   |
|                         |                | 0050     | 2380        | 9109100      | BASE, CONCRETE   | 2.00            | 0.00                   | 2.00                         | CUYD | 0.00                               | \$1,726.00  | \$0.00   |
|                         |                | 0050     | 2390        | 9109230      | DYNAMIC MESSAGE SIGN ASSEMBLY, INSTALLED                         | 1.00            | -1.00                  | 0.00                         | EA   | 0.00                               | \$9,413.00  | \$0.00   |
|                         |                | 0050     | 2400        | 9109901      | MISC.ITS ASSET MANAGEMENT TOOL                                   | 1.00            | 0.00                   | 1.00                         | LS   | 0.00                               | \$2,797.00  | \$0.00   |
|                         |                | 0050     | 2410        | 9109902      | MISC.ADJUST EXISTING P.B. TO GRADE                               | 1.00            | 0.00                   | 1.00                         | EA   | 0.00                               | \$1.335.00  | \$0.00   |
|                         |                | 0050     | 2420        | 9109902      | MISC.BURIED CABLE DELINEATOR POST                                | 12.00           | 0.00                   | 12.00                        | EA   | 1.00                               | \$100.00    | \$100.00   |
|                         |                | 0050     | 2430        | 9109902      | MISC.BUTTERFLY DMS STRUCTURE                                     | 1.00            | 0.00                   | 1.00                         | EA   | 0.00                               | \$55,944.00 | \$0.00   |
|                         |                |          | 2440        | 9109902      | MISC.CCTV EXTENSION POLE, 20' METALLICFINISH                     | 1.00            | 0.00                   | 1.00                         | EA   | 0.00                               | \$1,554.00  | \$0.00   |
|                         |                | 0050     | 2450        | 9109902      | MISC.FIBER OPTIC FUSION SPLICE                                   | 310.00          | 48.00                  | 358.00                       | EA   | 272.00                             | \$39.00     | \$10,608.00  |
|                         |                | 0050     | 2460        | 9109902      | MISC.FIBER OPTIC JUMPER,SM, FURNISH AND INSTALL                  | 34.00           | 0.00                   | 34.00                        | EA   | 7.00                               | \$22.00     | \$154.00   |
|                         |                | 0050     | 2470        | 9109902      | MISC.FIBER OPTIC PIGTAIL, SM, FURNISH AND INSTALL                | 42.00           | 0.00                   | 42.00                        | EA   | 26.00                              | \$10.00     | \$260.00   |
|                         |                | 0050     |             |              |  |                 |                        |                              |      |                                    |             |  |
|                         |                | 0050     | 2480        | 9109902      | MISC.FIELD TERMINAL CABINET, TYPE 7, FURNISH AND INSTALL         | 1.00            | 0.00                   | 1.00                         | EA   | 0.00                               | \$3,314.00  | \$0.00   |
|                         |                | 0050     | 2490        | 9109902      | MISC.INSTALL CCTV CAMERA ASSEMBLY                                | 1.00            | 0.00                   | 1.00                         | EA   | 0.00                               | \$883.00    | \$0.00   |
|                         |                | 0050     | 2500        | 9109902      | MISC.INSTALL CONDUIT INTO EXISTING BOX                           | 5.00            | 0.00                   | 5.00                         | EA   | 0.00                               | \$210.00    | \$0.00   |
|                         |                | 0050     | 2510        | 9109902      | MISC.ITS PULL BOX, CLASS 5                                       | 5.00            | 0.00                   | 5.00                         | EA   | 0.00                               | \$1,842.00  | \$0.00   |
|                         |                | 0050     | 2520        | 9109902      | MISC.ITS PULL BOX, CLASS 2                                       | 1.00            | 0.00                   | 1.00                         | EA   | 0.00                               | \$1,554.00  | \$0.00   |
|                         |                | 0050     | 2530        | 9109902      | MISC.SIGN STRUCTURE BASE MESH                                    | 1.00            | 0.00                   | 1.00                         | EA   | 0.00                               | \$310.00    | \$0.00   |
|                         |                | 0050     | 2540        | 9109902      | MISC.UNDERGROUND FIBER CABLE SPLICE ENCLOSURE                    | 2.00            | 2.00                   | 4.00                         | EA   | 2.00                               | \$621.00    | \$1,242.00   |
|                         |                | 0050     | 2550        | 9109902      | MISC.WALL-MOUNTED FIBER INTERCONNECT CENTER, FURNISH AND INSTALL | 7.00            | 0.00                   | 7.00                         | EA   | 0.00                               | \$350.00    | \$0.00   |
|                         |                | 0050     | 2560        | 9109903      | MISC.24 STRAND, SINGLE MODE FIBER OPTIC CABLE                    | 7,760.00        | 0.00                   | 7,760.00                     | LF   | 7,760.00                           | \$1.85      | \$14,356.00  |
|                         |                | 0050     | 2570        | 9109903      | MISC.72 STRAND, SINGLE MODE FIBER OPTIC CABLE                    | 4,200.00        | 0.00                   | 4,200.00                     | LF   | 4,200.00                           | \$2.05      | \$8,610.00   |
|                         |                | 0050     | 2580        | 9109903      | MISC.CAT-5 ETHERNET CABLE  | 200.00          | 0.00                   | 200.00                       | LF   | 0.00                               | \$1.70      | \$0.00   |
|                         |                | 0050     | 2590        | 9109903      | MISC.Conduit, PVC, PUSHED, 2"                                    | 399.00          | 0.00                   | 399.00                       | LF   | 256.00                             | \$16.45     | \$4,211.20   |
|                         |                | 0050     | 2600        | 9109903      | MISC.CONDUIT, PVC, TRENCH, 2"                                    | 1,083.00        | 0.00                   | 1,083.00                     | LF   | 0.00                               | \$5.90      | \$0.00   |
|                         |                | 0070     | 2610        | 2163000      | PARTIAL REMOVAL OF EXISTING BRIDGE DECK                          | 2,033.00        | 0.00                   | 2,033.00                     | SQFT | 2,033.00                           | \$10.00     | \$20,330.00  |
|                         |                | 0070     | 2620        | 2163502      | PARTIAL REMOVAL OF SUBSTRUCTURE CONCRETE                         | 1.00            | 0.00                   | 1.00                         | LS   | 1.00                               | \$9,200.00  | \$9,200.00   |
|                         |                | 0070     | 2630        | 2164500      | REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT                   | 41.00           | 0.00                   | 41.00                        | LF   | 0.00                               | \$425.00    | \$0.00   |
|                         |                | 0070     | 2640        | 5031010△     | CONCRETE BRIDGE APPROACH SLAB (MAJOR ROAD)                       | 59.00           | 0.00                   | 59.00                        | SQYD | 0.00                               | \$355.00    | \$0.00   |
|                         |                | 0070     | 2650        | 7032003      | CLASS B CONCRETE (SUBSTRUCTURE)                                  | 1.00            | 0.00                   | 1.00                         | CUYD | 1.00                               | \$5,050.00  | \$5,050.00   |
|                         |                |          | 2660        | 7032003      | CLASS B-1 CONCRETE   | 0.70            | 0.00                   | 0.70                         | CUYD | 0.00                               | \$12,650.00 | \$5,050.00   |
|                         |                | 0070     |             |              |  |                 |                        |                              | SQYD |                                    |             |  |
|                         |                | 0070     | 2670        | 7034212      | SLAB ON STEEL  | 212.00          | 0.00                   | 212.00                       |      | 74.00                              | \$470.00    | \$34,780.00  |
|                         |                | 0070     | 2680        | 7034214      | CLASS B-2 CONCRETE   | 3.50            | 0.00                   | 3.50                         | CUYD | 0.00                               | \$6,530.00  | \$0.00   |
|                         |                | 0070     | 2690        | 7034610      | CORRAL CURB  | 182.00          | 0.00                   | 182.00                       | LF   | 0.00                               | \$117.00    | \$0.00   |

Revision 4/1/2020 Page 15 of 45



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract    | uantities<br>Project | and Valu | Line | based on F | Report Generated date and can differ from the posted ar  Description | nount at the | time the Es     | timate was          | General<br>Unit | ted.<br>Total             | Unit Price   | Total Value POSTE                      |
|-------------|----------------------|----------|------|------------|--|--------------|-----------------|---------------------|-----------------|---------------------------|--------------|--|
| Nm.CONTRACT | No.                  | - Logory | No.  | Code       | 2000.  | Quantity     | Change<br>Order | Current<br>Quantity | 5               | Posted<br>Approved<br>Qty | 2.110        | To Date (See report<br>generated date) |
| 200515-F15  | J6I2222              | 0070     | 2700 | 7040103    | SUPERSTRUCTURE REPAIR (UNFORMED)                                     | 1,275.00     | 0.00            | 1,275.00            | SQFT            | 0.00                      | \$158.00     | \$0.00                                 |
|             |                      | 0070     | 2710 | 7040113    | CLEANING AND EPOXY COATING   | 6,834.00     | 0.00            | 6,834.00            | SQFT            | 0.00                      | \$3.36       | \$0.00                                 |
|             |                      | 0070     | 2720 | 7049904    | MISC.BARRIER CURB REPAIR (UNFORMED                                   | 195.00       | 0.00            | 195.00              | SQFT            | 0.00                      | \$175.00     | \$0.00                                 |
|             |                      | 0070     | 2730 | 7101000    | REINFORCING STEEL (EPOXY COATED)                                     | 850.00       | 0.00            | 850.00              | LB              | 0.00                      | \$3.00       | \$0.00                                 |
|             |                      | 0070     | 2740 | 7110200    | PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)                | 1.00         | 0.00            | 1.00                | LS              | 0.00                      | \$1,584.52   | \$0.00                                 |
|             |                      | 0070     | 2750 | 7123130    | REHABILITATE BEARING   | 8.00         | 0.00            | 8.00                | EA              | 0.00                      | \$3,712.50   | \$0.00                                 |
|             |                      | 0070     | 2760 | 7123620    | DRAINAGE SYSTEM (ON STRUCTURE)                                       | 1.00         | 0.00            | 1.00                | LS              | 0.00                      | \$10,500.00  | \$0.00                                 |
|             |                      | 0070     | 2770 | 7129901    | MISC.FLUSH DRAINAGE SYSTEM AND EXPANSION JOINTS                      | 1.00         | 0.00            | 1.00                | LS              | 0.00                      | \$20,000.00  | \$0.0                                  |
|             |                      | 0070     | 2780 | 7129902    | MISC.FATIGUE CRACK REPAIR  | 1.00         | 0.00            | 1.00                | EA              | 0.00                      | \$6,516.00   | \$0.0                                  |
|             |                      | 0070     | 2790 | 7172001    | STRIP SEAL EXPANSION JOINT SYSTEM                                    | 41.00        | 0.00            | 41.00               | LF              | 0.00                      | \$490.00     | \$0.0                                  |
|             |                      | 0071     | 2800 | 7040102    | SUBSTRUCTURE REPAIR (UNFORMED)                                       | 25.00        | 0.00            | 25.00               | SQFT            | 0.00                      | \$158.00     | \$0.0                                  |
|             |                      | 0071     | 2810 | 7040103    | SUPERSTRUCTURE REPAIR (UNFORMED)                                     | 1,483.00     | 0.00            | 1,483.00            | SQFT            | 0.00                      | \$158.00     | \$0.0                                  |
|             |                      | 0071     | 2820 | 7040113    | CLEANING AND EPOXY COATING   | 5,621.00     | 0.00            | 5,621.00            | SQFT            | 0.00                      | \$3.04       | \$0.0                                  |
|             |                      | 0071     | 2830 | 7049904    | MISC.BARRIER CURB REPAIR (UNFORMED)                                  | 142.00       | 0.00            | 142.00              | SQFT            | 0.00                      | \$175.00     | \$0.0                                  |
|             |                      | 0071     | 2840 | 7110200    | PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)                | 1.00         | 0.00            | 1.00                | LS              | 0.00                      | \$3,678.35   | \$0.0                                  |
|             |                      | 0071     | 2850 | 7121000    | FABRICATED STRUCTURAL CARBON STEEL (MISC)                            | 290.00       | 0.00            | 290.00              | LB              | 0.00                      | \$23.00      | \$0.0                                  |
|             |                      | 0071     | 2860 | 7123130    | REHABILITATE BEARING   | 5.00         | 0.00            | 5.00                | EA              | 0.00                      | \$2,570.00   | \$0.0                                  |
|             |                      | 0071     | 2875 | 7125111    | INTERMEDIATE FIELD COAT (SYSTEM G)                                   | 1.00         | 0.00            | 1.00                | LS              | 0.00                      | \$1,330.80   | \$0.0                                  |
|             |                      | 0071     | 2885 | 7125112    | FINISH FIELD COAT (SYSTEM G)   | 1.00         | 0.00            | 1.00                | LS              | 0.00                      | \$475.20     | \$0.0                                  |
|             |                      | 0071     | 2890 | 7129901    | MISC.FLUSH DRAINAGE SYSTEM AND EXPANSION JOINTS                      | 1.00         | 0.00            | 1.00                | LS              | 0.00                      | \$20,000.00  | \$0.0                                  |
|             |                      | 0071     | 2900 | 7129902    | MISC.FATIGUE CRACK REPAIR  | 3.00         | 0.00            | 3.00                | EA              | 0.00                      | \$2,040.00   | \$0.0                                  |
|             |                      | 0072     | 2910 | 7121060    | FABRICATED SIGN SUPPORT BRACKETS                                     | 1.00         | 0.00            | 1.00                | LS              | 0.00                      | \$3,600.00   | \$0.0                                  |
|             |                      | 0073     | 2920 | 2065500    | TEMPORARY SHORING  | 1.00         | 0.00            | 1.00                | LS              | 1.00                      | \$150,000.00 | \$150,000.0                            |
|             |                      | 0073     | 2930 | 7033009    | AESTHETIC CONCRETE STAIN   | 1.00         | 0.00            | 1.00                | LS              | 0.00                      | \$14,877.00  | \$0.0                                  |
|             |                      | 0073     | 2940 | 7201000    | MECHANICALLY STABILIZED EARTH WALL SYSTEMS                           | 8,672.00     | 0.00            | 8,672.00            | SQFT            | 8,672.00                  | \$62.50      | \$542,000.0                            |
|             |                      | 0074     | 2955 | 5031011A   | BRIDGE APPROACH SLAB (MINOR ROAD)                                    | 258.00       | 0.00            | 258.00              | SQYD            | 0.00                      | \$145.00     | \$0.0                                  |
|             |                      | 0074     | 2960 | 6079903    | MISC.(60 IN.) DECORATIVE PEDESTRIAN FENCE                            | 280.00       | 0.00            | 280.00              | LF              | 0.00                      | \$130.00     | \$0.                                   |
|             |                      | 0074     | 2970 | 7021212    | GALVANIZED STRUCTURAL STEEL PILES (12 IN)                            | 820.00       | 0.00            | 820.00              | LF              | 0.00                      | \$68.00      | \$0.                                   |
|             |                      | 0074     | 2980 | 7025001    | DYNAMIC PILE TESTING   | 2.00         | 0.00            | 2.00                | EA              | 0.00                      | \$2,325.00   | \$0.                                   |
|             |                      | 0074     | 2990 | 7027000    | PILE POINT REINFORCEMENT   | 14.00        | 0.00            | 14.00               | EA              | 0.00                      | \$80.00      | \$0.                                   |
|             |                      | 0074     | 3000 | 7032003    | CLASS B CONCRETE (SUBSTRUCTURE)                                      | 56.40        | 0.00            | 56.40               | CUYD            | 0.00                      | \$565.00     | \$0.0                                  |
|             |                      | 0074     | 3010 | 7034219A   | TYPE D BARRIER   | 288.00       | 0.00            | 288.00              | LF              | 0.00                      | \$115.00     | \$0.0                                  |
|             |                      | 0074     | 3020 | 7034221    | SLAB ON CONCRETE NU-GIRDER   | 760.00       | 0.00            | 760.00              | SQYD            | 0.00                      | \$335.00     | \$0.0                                  |
|             |                      | 0074     | 3030 | 7034630    | CONCRETE CURB (BRIDGE RAIL)  | 306.00       | 0.00            | 306.00              | LF              | 0.00                      | \$75.00      | \$0.0                                  |
|             |                      | 0074     | 3040 | 7056022    | NU 43, PRESTRESSED CONCRETE NU-GIRDER                                | 894.00       | 0.00            | 894.00              | LF              | 0.00                      | \$215.00     | \$0.0                                  |
|             |                      | 0074     | 3050 | 7071000    | CONDUIT SYSTEM ON STRUCTURE  | 1.00         | 0.00            | 1.00                | LS              | 0.00                      | \$5,927.00   | \$0.0                                  |
|             |                      | 0074     | 3060 | 7121060    | FABRICATED SIGN SUPPORT BRACKETS                                     | 1.00         | 0.00            | 1.00                | LS              | 0.00                      | \$7,100.00   | \$0.0                                  |
|             |                      | 0074     | 3070 | 7151001    | VERTICAL DRAIN AT END BENTS  | 2.00         | 0.00            | 2.00                | EA              | 0.00                      | \$2,500.00   | \$0.0                                  |
|             |                      | 0074     | 3080 | 7161000    | PLAIN NEOPRENE BEARING PAD   | 16.00        | 0.00            | 16.00               | EA              | 0.00                      | \$200.00     | \$0.0                                  |
|             |                      | 0074     | 3090 | 7201300    | PIPE PILE SPACERS  | 14.00        | 0.00            | 14.00               | EA              | 0.00                      | \$1,000.00   | \$0.                                   |
|             |                      | 0074     | 3100 | 9019902    | MISC.ORNAMENTAL LUMINAIRE  | 10.00        | 0.00            | 10.00               | EA              | 0.00                      | \$1,658.00   | \$0.                                   |
|             |                      | 0075     | 3110 | 7033009    | AESTHETIC CONCRETE STAIN   | 1.00         | -1.00           | 0.00                | LS              | 0.00                      | \$17,530.50  | \$0.0                                  |
|             |                      | 0075     | 3120 | 7201000    | MECHANICALLY STABILIZED EARTH WALL SYSTEMS                           | 7,637.00     | -7,637.00       | 0.00                | SQFT            | 0.00                      | \$110.00     | \$0.0                                  |
|             |                      | 0075     | 3130 | 7033009    | AESTHETIC CONCRETE STAIN   | 1.00         | -1.00           | 0.00                | LS              | 0.00                      | \$6,525.00   | \$0.                                   |
|             |                      | 0076     | 3140 | 7201000    | MECHANICALLY STABILIZED EARTH WALL SYSTEMS                           | 3,410.00     | -3,410.00       | 0.00                | SQFT            | 0.00                      | \$110.00     | \$0.0                                  |
|             |                      | 55.0     |      |            |  |              |                 |                     |                 |                           |              |  |
|             |                      | 0077     | 3150 | 2160500    | REMOVAL OF BRIDGES   | 1.00         | 0.00            | 1.00                | LS              | 1.00                      | \$146,000.00 | \$146,000.0                            |

Page 16 of 45 Revision 4/1/2020



### Total Paid / All Items / All Estimates (Including this Estimate)

| Note: Posted Q          | uantities      | and Valu | ies are     | based on F   | Report Generated date and can differ from the posted a | mount at the    | time the Es            | timate was                   | Generat | ed.                                |              |  |
|-------------------------|----------------|----------|-------------|--------------|--|-----------------|------------------------|------------------------------|---------|------------------------------------|--------------|--|
| Contract<br>Nm.CONTRACT | Project<br>No. | Category | Line<br>No. | Item<br>Code | Description  | Bid<br>Quantity | Net<br>Change<br>Order | Total<br>Current<br>Quantity | Unit    | Total<br>Posted<br>Approved<br>Qty | Unit Price   | Total Value POSTED<br>To Date (See report<br>generated date) |
| 200515-F15              | J6I2222        | 0077     | 3170        | 6079903      | MISC.(60 IN.) DECORATIVE PEDESTRIAN FENCE              | 404.00          | 0.00                   | 404.00                       | LF      | 0.00                               | \$130.00     | \$0.00   |
|                         |                | 0077     | 3180        | 7011105      | DRILLED SHAFTS (3 FT. 6 IN. DIA.)                      | 30.00           | 0.00                   | 30.00                        | LF      | 0.00                               | \$490.00     | \$0.00   |
|                         |                | 0077     | 3190        | 7011204      | ROCK SOCKETS (3 FT 0 IN. DIA.)                         | 30.00           | 0.00                   | 30.00                        | LF      | 0.00                               | \$815.00     | \$0.00   |
|                         |                | 0077     | 3200        | 7011300      | VIDEO CAMERA INSPECTION                                | 3.00            | 0.00                   | 3.00                         | EA      | 0.00                               | \$450.00     | \$0.00   |
|                         |                | 0077     | 3210        | 7011400      | FOUNDATION INSPECTION HOLES                            | 60.00           | 0.00                   | 60.00                        | LF      | 0.00                               | \$140.00     | \$0.00   |
|                         |                | 0077     | 3220        | 7011600      | SONIC LOGGING TESTING                                  | 3.00            | 0.00                   | 3.00                         | EA      | 0.00                               | \$2,100.00   | \$0.00   |
|                         |                | 0077     | 3230        | 7021212      | GALVANIZED STRUCTURAL STEEL PILES (12 IN)              | 462.00          | 0.00                   | 462.00                       | LF      | 0.00                               | \$75.00      | \$0.00   |
|                         |                | 0077     | 3240        | 7025001      | DYNAMIC PILE TESTING                                   | 2.00            | 0.00                   | 2.00                         | EA      | 0.00                               | \$2,350.00   | \$0.00   |
|                         |                | 0077     | 3250        | 7026000      | PRE-BORE FOR PILING                                    | 252.00          | 0.00                   | 252.00                       | LF      | 0.00                               | \$180.00     | \$0.00   |
|                         |                | 0077     | 3260        | 7027000      | PILE POINT REINFORCEMENT                               | 14.00           | 0.00                   | 14.00                        | EA      | 0.00                               | \$80.00      | \$0.00   |
|                         |                | 0077     | 3270        | 7032003      | CLASS B CONCRETE (SUBSTRUCTURE)                        | 49.60           | 0.00                   | 49.60                        | CUYD    | 0.00                               | \$800.00     | \$0.00   |
|                         |                | 0077     | 3280        | 7034003      | CLASS B-1 CONCRETE (SUBSTRUCTURE)                      | 60.30           | 0.00                   | 60.30                        | CUYD    | 0.00                               | \$1,055.00   | \$0.00   |
|                         |                | 0077     | 3290        | 7034219A     | TYPE D BARRIER   | 404.00          | 0.00                   | 404.00                       | LF      | 0.00                               | \$130.00     | \$0.00   |
|                         |                | 0077     | 3300        | 7034221      | SLAB ON CONCRETE NU-GIRDER                             | 1,175.00        | 0.00                   | 1,175.00                     | SQYD    | 0.00                               | \$290.00     | \$0.00   |
|                         |                | 0077     | 3310        | 7034630      | CONCRETE CURB (BRIDGE RAIL)                            | 447.00          | 0.00                   | 447.00                       | LF      | 0.00                               | \$62.00      | \$0.00   |
|                         |                | 0077     | 3320        | 7056021      | NU 35, PRESTRESSED CONCRETE NU-GIRDER                  | 1,268.00        | 0.00                   | 1,268.00                     | LF      | 0.00                               | \$210.00     | \$0.00   |
|                         |                | 0077     | 3330        | 7061060      | REINFORCING STEEL (BRIDGES)                            | 18,420.00       | -18,420.00             | 0.00                         | LB      | 0.00                               | \$1.00       | \$0.00   |
|                         |                | 0077     | 3340        | 7071000      | CONDUIT SYSTEM ON STRUCTURE                            | 1.00            | 0.00                   | 1.00                         | LS      | 0.00                               | \$26.383.00  | \$0.00   |
|                         |                | 0077     | 3350        | 7079901      | MISC.CONDUIT SYSTEM ON STRUCTURE - ATT TELPHONE        | 1.00            | 0.00                   | 1.00                         | LS      | 0.00                               | \$3,730.00   | \$0.00   |
|                         |                | 0077     | 3355        | 7110200      | PROTECTIVE COATING - CONCRETE BENTS AND PIERS          | 1.00            | 0.00                   | 1.00                         | LS      | 0.00                               | \$8,330.05   | \$0.00   |
|                         |                |          |             |              | (EPOXY)  |                 |                        |                              |         |                                    |              |  |
|                         |                | 0077     | 3370        | 7121060      | FABRICATED SIGN SUPPORT BRACKETS                       | 1.00            | 0.00                   | 1.00                         | LS      | 0.00                               | \$27,500.00  | \$0.00   |
|                         |                | 0077     | 3380        | 7151001      | VERTICAL DRAIN AT END BENTS                            | 2.00            | 0.00                   | 2.00                         | EA      | 0.00                               | \$2,500.00   | \$0.00   |
|                         |                | 0077     | 3390        | 7161003      | LAMINATED NEOPRENE BEARING PAD (TAPERED)               | 28.00           | 0.00                   | 28.00                        | EA      | 0.00                               | \$425.00     | \$0.00   |
|                         |                | 0077     | 3400        | 7201300      | PIPE PILE SPACERS                                      | 14.00           | 0.00                   | 14.00                        | EA      | 0.00                               | \$855.00     | \$0.00   |
|                         |                | 0077     | 3410        | 9019903      | MISC.ORNAMENTAL LUMINAIRE                              | 12.00           | 0.00                   | 12.00                        | LF      | 0.00                               | \$1,658.00   | \$0.00   |
|                         |                | 0078     | 3420        | 7033009      | AESTHETIC CONCRETE STAIN                               | 1.00            | 0.00                   | 1.00                         | LS      | 0.00                               | \$7,856.10   | \$0.00   |
|                         |                | 0078     | 3430        | 7201000      | MECHANICALLY STABILIZED EARTH WALL SYSTEMS             | 4,182.00        | 0.00                   | 4,182.00                     | SQFT    | 0.00                               | \$80.00      | \$0.00   |
|                         |                | 0079     | 3440        | 7033009      | AESTHETIC CONCRETE STAIN                               | 1.00            | 0.00                   | 1.00                         | LS      | 0.00                               | \$3,654.00   | \$0.00   |
|                         |                | 0079     | 3450        | 7201000      | MECHANICALLY STABILIZED EARTH WALL SYSTEMS             | 2,521.00        | 0.00                   | 2,521.00                     | SQFT    | 0.00                               | \$80.00      | \$0.00   |
|                         |                | 0800     | 3460        | 2160500      | REMOVAL OF BRIDGES                                     | 1.00            | 0.00                   | 1.00                         | LS      | 0.70                               | \$655,000.00 | \$458,500.00   |
|                         |                | 0800     | 3470        | 5031010A     | BRIDGE APPROACH SLAB (MAJOR ROAD)                      | 81.00           | 0.00                   | 81.00                        | SQYD    | 0.00                               | \$200.00     | \$0.00   |
|                         |                | 0800     | 3480        | 7011110      | DRILLED SHAFTS (6 FT. 0 IN. DIA.)                      | 380.40          | 0.00                   | 380.40                       | LF      | 0.00                               | \$485.00     | \$0.00   |
|                         |                | 0800     | 3490        | 7011209      | ROCK SOCKETS (5 FT 6 IN. DIA.)                         | 108.00          | 0.00                   | 108.00                       | LF      | 0.00                               | \$2,555.00   | \$0.00   |
|                         |                | 0800     | 3500        | 7011300      | VIDEO CAMERA INSPECTION                                | 6.00            | 0.00                   | 6.00                         | EA      | 0.00                               | \$550.00     | \$0.00   |
|                         |                | 0800     | 3510        | 7011400      | FOUNDATION INSPECTION HOLES                            | 174.00          | 0.00                   | 174.00                       | LF      | 125.80                             | \$155.00     | \$19,499.00  |
|                         |                | 0800     | 3520        | 7011600      | SONIC LOGGING TESTING                                  | 6.00            | 0.00                   | 6.00                         | EA      | 0.00                               | \$4,250.00   | \$0.00   |
|                         |                | 0800     | 3530        | 7021212      | GALVANIZED STRUCTURAL STEEL PILES (12 IN)              | 430.00          | 0.00                   | 430.00                       | LF      | 0.00                               | \$85.00      | \$0.00   |
|                         |                | 0800     | 3540        | 7025001      | DYNAMIC PILE TESTING                                   | 1.00            | 0.00                   | 1.00                         | EA      | 0.00                               | \$2,700.00   | \$0.00   |
|                         |                | 0800     | 3550        | 7027000      | PILE POINT REINFORCEMENT                               | 5.00            | 0.00                   | 5.00                         | EA      | 0.00                               | \$80.00      | \$0.00   |
|                         |                | 0800     | 3560        | 7032003      | CLASS B CONCRETE (SUBSTRUCTURE)                        | 21.70           | 0.00                   | 21.70                        | CUYD    | 0.00                               | \$745.00     | \$0.00   |
|                         |                | 0800     | 3570        | 7034003      | CLASS B-1 CONCRETE (SUBSTRUCTURE)                      | 379.50          | 0.00                   | 379.50                       | CUYD    | 0.00                               | \$710.00     | \$0.00   |
|                         |                | 0800     | 3580        | 7034212      | SLAB ON STEEL  | 304.00          | 0.00                   | 304.00                       | SQYD    | 0.00                               | \$335.00     | \$0.00   |
|                         |                | 0800     | 3590        | 7034219A     | TYPE D BARRIER   | 1,779.00        | 0.00                   | 1,779.00                     | LF      | 0.00                               | \$58.00      | \$0.00   |
|                         |                | 0800     | 3600        | 7034221      | SLAB ON CONCRETE NU-GIRDER                             | 2,430.00        | 0.00                   | 2,430.00                     | SQYD    | 0.00                               | \$340.00     | \$0.00   |
|                         |                | 0800     | 3610        | 7056023      | NU 53, PRESTRESSED CONCRETE NU-GIRDER                  | 1,504.00        | 0.00                   | 1,504.00                     | LF      | 0.00                               | \$270.00     | \$0.00   |
|                         |                | 0800     | 3620        | 7056025      | NU 70, PRESTRESSED CONCRETE NU-GIRDER                  | 1,151.00        | 0.00                   | 1,151.00                     | LF      | 0.00                               | \$270.00     | \$0.00   |
|                         |                | 0800     | 3630        | 7061060      | REINFORCING STEEL (BRIDGES)                            | 170,450.00      | 0.00                   | 170,450.00                   | LB      | 0.00                               | \$0.85       | \$0.00   |

Revision 4/1/2020 Page 17 of 45



### Total Paid / All Items / All Estimates (Including this Estimate)

| vote: Posted Q          | uantities      |          | ies are     | based on I   | Report Generated date and can differ from the posted am  |                 | time the Es            | timate was                   | Generat | ed.                                |              |  |
|-------------------------|----------------|----------|-------------|--------------|--|-----------------|------------------------|------------------------------|---------|------------------------------------|--------------|--|
| Contract<br>Nm.CONTRACT | Project<br>No. | Category | Line<br>No. | Item<br>Code | Description  | Bid<br>Quantity | Net<br>Change<br>Order | Total<br>Current<br>Quantity | Unit    | Total<br>Posted<br>Approved<br>Qty | Unit Price   | Total Value POSTED<br>To Date (See report<br>generated date) |
| 200515-F15              | J6I2222        | 0080     | 3640        | 7061070      | MECHANICAL BAR SPLICE  | 480.00          | 0.00                   | 480.00                       | EA      | 0.00                               | \$95.00      | \$0.00   |
|                         |                | 0080     | 3650        | 7101000      | REINFORCING STEEL (EPOXY COATED)   | 12,940.00       | 0.00                   | 12,940.00                    | LB      | 0.00                               | \$1.15       | \$0.00   |
|                         |                | 0080     | 3660        | 7110200      | PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)  | 1.00            | 0.00                   | 1.00                         | LS      | 0.00                               | \$9,744.80   | \$0.00   |
|                         |                | 0800     | 3670        | 7120900      | EXPANSION DEVICE (FINGER PLATE)  | 23.00           | 0.00                   | 23.00                        | LF      | 0.00                               | \$2,400.00   | \$0.00   |
|                         |                | 0080     | 3680        | 7121121      | FABRICATED STRUCTURAL LOW ALLOY STEEL (PLATE GIRDER) A709, GRADE 50                            | 79,550.00       | 0.00                   | 79,550.00                    | LB      | 0.00                               | \$3.19       | \$0.00   |
|                         |                | 0800     | 3690        | 7123210      | EARTH QUAKE RESTRAINER ASSEMBLIES  | 3.00            | 0.00                   | 3.00                         | EA      | 0.00                               | \$13,125.00  | \$0.00   |
|                         |                | 0080     | 3700        | 7123301      | STEEL INTERMEDIATE DIAPHRAGM FOR P/S CONCRETE GIRDERS  | 30.00           | 0.00                   | 30.00                        | EA      | 0.00                               | \$680.00     | \$0.00   |
|                         |                | 0800     | 3710        | 7123620      | DRAINAGE SYSTEM (ON STRUCTURE)   | 1.00            | 0.00                   | 1.00                         | LS      | 0.00                               | \$80,000.00  | \$0.00   |
|                         |                | 0080     | 3720        | 7125200      | SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL   | 500.00          | 0.00                   | 500.00                       | SQFT    | 0.00                               | \$81.40      | \$0.00   |
|                         |                | 0080     | 3730        | 7125210      | FIELD APPLICATION OF INORGANIC ZINC PRIMER   | 500.00          | 0.00                   | 500.00                       | SQFT    | 0.00                               | \$2.00       | \$0.00   |
|                         |                | 0080     | 3740        | 7125365A     | INTERMEDIATE FIELD COAT (SYSTEM G)   | 5,000.00        | 0.00                   | 5,000.00                     | SQFT    | 0.00                               | \$6.65       | \$0.00   |
|                         |                | 0080     | 3750        | 7125370A     | FINISH FIELD COAT (SYSTEM G)   | 2,700.00        | 0.00                   | 2,700.00                     | SQFT    | 0.00                               | \$2.38       | \$0.00   |
|                         |                | 0080     | 3760        | 7129903      | MISC.MODULAR EXPANSION JOINT SYSTEM  | 24.00           | 0.00                   | 24.00                        | LF      | 0.00                               | \$2,400.00   | \$0.00   |
|                         |                | 0080     | 3770        | 7151001      | VERTICAL DRAIN AT END BENTS  | 1.00            | 0.00                   | 1.00                         | EA      | 0.00                               | \$2,500.00   | \$0.00   |
|                         |                | 0080     | 3780        | 7161000      | PLAIN NEOPRENE BEARING PAD   | 8.00            | 0.00                   | 8.00                         | EA      | 0.00                               | \$225.00     | \$0.00   |
|                         |                | 0080     | 3790        | 7161002      | LAMINATED NEOPRENE BEARING PAD   | 3.00            | 0.00                   | 3.00                         | EA      | 0.00                               | \$250.00     | \$0.00   |
|                         |                | 0080     | 3800        | 7161003      | LAMINATED NEOPRENE BEARING PAD (TAPERED)   | 21.00           | 0.00                   | 21.00                        | EA      | 0.00                               | \$320.00     | \$0.00   |
|                         |                | 0080     | 3810        | 7162000      | LAMINATED NEOPRENE BEARING PAD ASSEMBLY  | 16.00           | 0.00                   | 16.00                        | EA      | 0.00                               | \$1,520.00   | \$0.00   |
|                         |                | 0080     | 3820        | 7163000      | TYPE N PTFE BEARING  | 3.00            | 0.00                   | 3.00                         | EA      | 0.00                               | \$2,500.00   | \$0.00   |
|                         |                | 0080     | 3830        | 7172001      | STRIP SEAL EXPANSION JOINT SYSTEM  | 24.00           | 0.00                   | 24.00                        | LF      | 0.00                               | \$510.00     | \$0.00   |
|                         |                | 0001     | 5001        | 6189901      | MISC.Adjust Mobilization for Contract Bond   | 0.00            | 1.00                   | 1.00                         | LS      | 1.00                               | \$107,907.00 | \$107,907.00   |
|                         |                | 0001     | 5002        | 6141121      | CURVED VANE GRATE AND FRAME (4 FT. X 2 FT. OR 1200MM X 600MM)                                  | 0.00            | 36.00                  | 36.00                        | EA      | 0.00                               | \$1,400.00   | \$0.00   |
|                         |                | 0001     | 5003        | 6149902      | MISC.Parallel Grate and Bearing Plate (4 FT.x2FT.)   | 0.00            | 30.00                  | 30.00                        | EA      | 6.00                               | \$1,400.00   | \$8,400.00   |
|                         |                | 0050     | 5004        | 9109901      | MISC.DMS Board Removal   | 0.00            | 1.00                   | 1.00                         | LS      | 1.00                               | \$12,673.51  | \$12,673.51  |
|                         |                | 0001     | 5005        | 6173700B     | TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED                            | 0.00            | 638.00                 | 638.00                       | LF      | 638.00                             | \$40.79      | \$26,024.02  |
|                         |                | 0001     | 5006        | 2063100      | CLASS 3 EXCAVATION IN ROCK   | 0.00            | 18.50                  | 18.50                        | CUYD    | 0.00                               | \$85.00      | \$0.00   |
|                         |                | 0050     | 5007        | 9109901      | MISC.Colored Dynamic Message Sign  | 0.00            | 1.00                   | 1.00                         | LS      | 0.00                               | \$110,608.04 | \$0.00   |
|                         |                | 0001     | 5008        | 6149902      | MISC.MISC. MSD Manhole Frame and Cover   | 0.00            | 17.00                  | 17.00                        | EA      | 5.00                               | \$400.00     | \$2,000.00   |
|                         |                | 0001     | 5009        | 2032000      | CLASS C EXCAVATION   | 0.00            | 728.90                 | 728.90                       | CUYD    | 728.90                             | \$75.00      | \$54,667.50  |
|                         |                | 0001     | 5010        | 7209901      | MISC.Rock Fill Alternative Ground Improvement  | 0.00            | 1.00                   | 1.00                         | LS      | 1.00                               | \$7,822.60   | \$7,822.60   |
|                         |                | 0077     | 5011        | 7101000      | REINFORCING STEEL (EPOXY COATED)   | 0.00            | 18,420.00              | 18,420.00                    | LB      | 0.00                               | \$1.33       | \$0.00   |
|                         |                | 0001     | 5012        | 2029901      | MISC.Barrier Wall Removal  | 0.00            | 1.00                   | 1.00                         | LS      | 1.00                               | \$5,226.18   | \$5,226.18   |
|                         |                | 0074     | 5013        | 7011105      | DRILLED SHAFTS (3 FT. 6 IN. DIA.)  | 0.00            | 202.80                 | 202.80                       | LF      | 202.80                             | \$567.75     | \$115,139.70   |
|                         |                | 0074     | 5014        | 7011204      | ROCK SOCKETS (3 FT 0 IN. DIA.)   | 0.00            | 76.70                  | 76.70                        | LF      | 76.70                              | \$917.10     | \$70,341.57  |
|                         |                | 0074     | 5015        | 7101000      | REINFORCING STEEL (EPOXY COATED)   | 0.00            | 24,760.00              | 24,760.00                    | LB      | 24,760.00                          | \$1.49       | \$36,892.40  |
|                         |                | 0074     | 5016        | 7011300      | VIDEO CAMERA INSPECTION  | 0.00            | 6.00                   | 6.00                         | EA      | 6.00                               | \$577.50     | \$3,465.00   |
|                         |                | 0074     | 5017        | 7011400      | FOUNDATION INSPECTION HOLES  | 0.00            | 185.10                 | 185.10                       | LF      | 185.10                             | \$136.50     | \$25,266.15  |
|                         |                | 0074     | 5018        | 7011600      | SONIC LOGGING TESTING  | 0.00            | 6.00                   | 6.00                         | EA      | 6.00                               | \$4,593.00   | \$27,558.00  |
|                         |                | 0074     | 5019        | 7061070      | MECHANICAL BAR SPLICE  | 0.00            | 36.00                  | 36.00                        | EA      | 18.00                              | \$140.70     | \$2,532.60   |
|                         |                | 0001     | 5020        | 6131010      | FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR                        | 0.00            | 165.70                 | 165.70                       | SQYD    | 165.70                             | \$110.00     | \$18,227.00  |
|                         |                | 0001     | 5021        | 6131018      | TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS) | 0.00            | 58.00                  | 58.00                        | EA      | 58.00                              | \$12.00      | \$696.00   |
|                         |                | 0001     | 5022        | 6131015      | DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR               | 0.00            | 130.00                 | 130.00                       | EA      | 130.00                             | \$15.00      | \$1,950.00   |
|                         |                | 0001     | 5023        | 1046002      | VALUE ENGINEERING  | 0.00            | 14,480.00              | 14,480.00                    | EA      | 14,480.00                          | \$1.00       | \$14,480.00  |
|                         |                | 0001     | 5024        | 7269923      | SEWER  | 0.00            | 701.00                 | 701.00                       | LF      | 0.00                               | \$461.34     | \$0.00   |
|                         |                | 0001     | 5025        | 7269922      | SEWER  | 0.00            | 150,000.00             | 150,000.00                   | EA      | 0.00                               | \$1.00       | \$0.00   |

Revision 4/1/2020 Page 18 of 45



### Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Note. I osted Q   | uarititics     | and valu | ics are i   | ascu on i    | report ocherated date and can dilier from the posted am | ount at the     | unio uno Ec            | Junate was                   | Conorat        | ou.                                |            | ,  |
|---|----------------|----------|-------------|--------------|---|-----------------|------------------------|------------------------------|----------------|------------------------------------|------------|--|
| Contract<br>Nm.CONTRACT   | Project<br>No. | Category | Line<br>No. | Item<br>Code | Description   | Bid<br>Quantity | Net<br>Change<br>Order | Total<br>Current<br>Quantity | Unit           | Total<br>Posted<br>Approved<br>Qty | Unit Price | Total Value POSTED<br>To Date (See report<br>generated date) |
| 200515-F15 Project J6I2222 - Total Value Posted to Date as of Report Generated Date |                |          |             |              |   |                 |                        |                              |                | \$7,614,918.22                     |            |  |
| 200515-F15 Overall - Total Value Posted to Date as of Report Generated Date         |                |          |             |              |   |                 |                        |                              | \$7,614,918.22 |                                    |            |  |

Revision 4/1/2020 Page 19 of 45



# Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J6I2222

| Line<br>Number | Item<br>Code | Description                                  | DWR<br>Date | DWR<br>Approval<br>Date | Quantity<br>Posted | Units | Location  | From<br>Station/<br>Log Mile | Offset/<br>Distance | To<br>Station/<br>Log Mile | Offset/<br>Distance | Comments                          |
|----------------|--------------|--|-------------|-------------------------|--------------------|-------|---|------------------------------|---------------------|----------------------------|---------------------|-----------------------------------|
| 0025           | 2024043      | REMOVAL OF MISCELLANEOUS ACM NON-FRIABLE     | 2/28/21     | 3/2/21                  | 20.00              | SQFT  | Ewing Brdige  |                              |                     |                            |                     |                                   |
| 0040           | 2029901      | MISC. REMOVALS                               | 2/28/21     | 3/2/21                  | 0.90               | LS    | Ewing Bridge  |                              |                     |                            |                     |                                   |
| 0310           | 6049903      | MISC. DRAINAGE ITEM                          | 3/1/21      | 3/2/21                  | 3.00               | LF    | MSD Manhole 283 initial work  | 3+90.54                      |                     |                            |                     |                                   |
| 0480           | 6092011      | INTEGRAL CURB (6 IN. HEIGHT AND UNDER)       | 2/25/21     | 3/1/21                  | 181.00             | LF    | EB I-64 from 63+90 to 64+45<br>WB I-64 from 63+90 to 65+15  |                              |                     |                            |                     |                                   |
| 0515           | 6099903      | MISC. PAVED DRAINAGE                         | 2/25/21     | 3/1/21                  | 122.00             | LF    | EB I-64 from 64+45 to 64+87<br>WB I-64 from 65+15 to 65+95  |                              |                     |                            |                     |                                   |
| 0570           | 6122012      | IMPACT ATTENUATOR 55 MPH (SAND BARREL ARRAY) | 2/28/21     | 3/2/21                  | 2.00               | EA    | I-64 WB & EB at Ewing before the temporary traffic barriers on the right shoulders  | 0                            |                     | 0                          |                     |                                   |
| 0670           | 6169902      | MISC. TRAFFIC CONTROL DEVICES                | 2/25/21     | 3/2/21                  | 2.00               | EA    | NB/SB Ewing Ave bridge  | 0                            |                     | 0                          |                     |                                   |
| 0710           | 6173600D     | TEMPORARY TRAFFIC BARRIER, CONT. FURN/RE     | 2/28/21     | 3/2/21                  | 188.00             | LF    | Installed 15 temporary traffic barriers on the I-64 right shoulder at Ewing   | 0                            |                     | 0                          |                     |                                   |
| 0720           | 6175010A     | RELOCATING TEMPORARY TRAFFIC BARRIER         | 2/28/21     | 3/2/21                  | 900.00             | LF    | Relocated and installed on I-64 WB & EB 72 temporary traffic barriers on the right shoulders at Ewing and in the center median trench section | 0                            |                     | 0                          |                     |                                   |
| 1310           | 8061016      | SEDIMENT REMOVAL                             | 3/1/21      | 3/2/21                  | 205.00             | CUYD  | Work performed at an earlier date   | 0                            |                     | 0                          |                     |                                   |
| 1570           | 6061060      | MGS GUARDRAIL                                | 2/25/21     | 3/1/21                  | 325.00             | LF    | EB I-64 Right Shoulder  | 55+49.73                     |                     | 59+60.00                   |                     |                                   |
|                |              |  | 2/26/21     | 3/1/21                  | 88.00              | LF    | I-64 WB Left Shoulder   | 63+90.00                     |                     | 65+65.74                   |                     |                                   |
| 1600           | 6061070      | MGS VERTICAL CONCRETE BARRIER TRANSITION     | 2/25/21     | 3/1/21                  | 2.00               | EA    | EB I-64 Right Shoulder- Two Locations   | 55+49.73                     |                     | 64+41.75                   |                     |                                   |
|                |              |  | 2/26/21     | 3/1/21                  | 1.00               | EA    | I-64 WB Left Shoulder   | 63+90.00                     |                     | 65+65.74                   |                     |                                   |
| 1610           | 6061080      | MGS END ANCHOR                               | 2/25/21     | 3/1/21                  | 1.00               | EA    | EB I-64 Right Shoulder  | 63+90.00                     |                     | 64+41.75                   |                     |                                   |
| 1620           | 6063014      | TYPE A CRSHWTHY END TERMINAL (MASH)          | 2/25/21     | 3/1/21                  | 1.00               | EA    | EB I-64 Right Shoulder  | 55+49.73                     |                     | 59+60.00                   |                     |                                   |
|                |              |  |             | 3/2/21                  | 1.00               | EA    | EB 64 past 22nd St bridge location  | 64+66.74                     |                     | 65+17.88                   |                     | Work installed at an earlier date |
|                |              |  | 2/26/21     | 3/1/21                  | 1.00               | EA    | I-64 WB Left Shoulder   | 63+90.00                     |                     | 65+65.74                   |                     |                                   |
| 2650           | 7032003      | CLASS B CONCRETE (SUBSTRUCTURE)              | 2/25/21     | 3/1/21                  | 1.00               | CUYD  | Bent 1 Ramp E on WB I-64  |                              |                     |                            |                     |                                   |
| 2670           | 7034212      | SLAB ON STEEL                                | 3/1/21      | 3/2/21                  | 37.00              | SQYD  | Bridge A150114 deck forming   | 0                            |                     | 0                          |                     |                                   |
| 3150           | 2160500      | REMOVAL OF BRIDGES                           | 2/28/21     | 3/2/21                  | 1.00               | LS    | Ewing bridge demo   |                              |                     |                            |                     |                                   |
|                |              |  |             |                         |                    |       |   |                              |                     |                            |                     |                                   |

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 4/1/2020 Page 20 of 45



| Line   | Description           | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By | Amount         | Remarks  |          |   |    |                |        |                |    |                 |                 |                |                |  |  |  |  |  |  |  |  |  |  |    |
|--------|-----------------------|--------------------|-----------------------------|----------------|-----------------|---------------|----------------|--|----------|---|----|----------------|--------|----------------|----|-----------------|-----------------|----------------|----------------|--|--|--|--|--|--|--|--|--|--|----|
| 0050   | CLASS A EXCAVATION    | Price              |                             | 4              | Sep 2,<br>2020  | SYSTEM        | \$24.92        | Reference Item Price Adjustment Index Adjustment Type applied is FUEL  |          |   |    |                |        |                |    |                 |                 |                |                |  |  |  |  |  |  |  |  |  |  |    |
|        |                       |                    |                             | 4              | Sep 2,<br>2020  | SYSTEM        | \$7.00         | Reference Item Price Adjustment Index Adjustment Type applied is FUEL  |          |   |    |                |        |                |    |                 |                 |                |                |  |  |  |  |  |  |  |  |  |  |    |
|        |                       |                    |                             | 5              | Sep 16,<br>2020 | SYSTEM        | \$349.60       | Reference Item Price Adjustment Index Adjustment Type applied is FUEL  |          |   |    |                |        |                |    |                 |                 |                |                |  |  |  |  |  |  |  |  |  |  |    |
|        |                       |                    |                             | 7              | Oct 16,<br>2020 | SYSTEM        | \$800.00       | Reference Item Price Adjustment Index Adjustment Type applied is FUEL  |          |   |    |                |        |                |    |                 |                 |                |                |  |  |  |  |  |  |  |  |  |  |    |
|        |                       |                    |                             | 9              | Nov 16,<br>2020 | SYSTEM        | \$1,020.00     | Reference Item Price Adjustment Index Adjustment Type applied is FUEL  |          |   |    |                |        |                |    |                 |                 |                |                |  |  |  |  |  |  |  |  |  |  |    |
|        |                       |                    |                             |                |                 | 10            | Dec 2,<br>2020 | SYSTEM   | \$204.00 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |    |                |        |                |    |                 |                 |                |                |  |  |  |  |  |  |  |  |  |  |    |
|        |                       |                    |                             | 11             | Dec 16,<br>2020 | SYSTEM        | \$1,142.60     | Reference Item Price Adjustment Index Adjustment Type applied is FUEL  |          |   |    |                |        |                |    |                 |                 |                |                |  |  |  |  |  |  |  |  |  |  |    |
|        |                       |                    |                             | 13             | Jan 19,<br>2021 | SYSTEM        | \$201.00       | Reference Item Price Adjustment Index Adjustment Type applied is FUEL  |          |   |    |                |        |                |    |                 |                 |                |                |  |  |  |  |  |  |  |  |  |  |    |
|        |                       |                    | - Total                     | 14             | Feb 2,<br>2021  | SYSTEM        | \$3,086.82     | Reference Item Price Adjustment Index Adjustment Type applied is FUEL  |          |   |    |                |        |                |    |                 |                 |                |                |  |  |  |  |  |  |  |  |  |  |    |
|        |                       |                    | - Total                     |                |                 |               | \$6,835.94     |  |          |   |    |                |        |                |    |                 |                 |                |                |  |  |  |  |  |  |  |  |  |  |    |
|        | Price - Total         |                    |                             |                |                 |               | \$6,835.94     |  |          |   |    |                |        |                |    |                 |                 |                |                |  |  |  |  |  |  |  |  |  |  |    |
| 0050 - | - Total               |                    |                             |                |                 |               | \$6,835.94     |  |          |   |    |                |        |                |    |                 |                 |                |                |  |  |  |  |  |  |  |  |  |  |    |
| 0060   | COMPACTING EMBANKMENT | Material           |                             | 5              | Sep 16,<br>2020 | SYSTEM        | (\$74,940.00)  |  |          |   |    |                |        |                |    |                 |                 |                |                |  |  |  |  |  |  |  |  |  |  |    |
|        |                       |                    |                             | 5              | Sep 16,<br>2020 | SYSTEM        | \$74,940.00    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.          |          |   |    |                |        |                |    |                 |                 |                |                |  |  |  |  |  |  |  |  |  |  |    |
|        |                       |                    |                             | 6              | Oct 1,<br>2020  | SYSTEM        | (\$74,940.00)  |  |          |   |    |                |        |                |    |                 |                 |                |                |  |  |  |  |  |  |  |  |  |  |    |
|        |                       |                    |                             | 6              | Oct 1,<br>2020  | SYSTEM        | \$74,940.00    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.          |          |   |    |                |        |                |    |                 |                 |                |                |  |  |  |  |  |  |  |  |  |  |    |
|        |                       |                    |                             | 7              | Oct 16,<br>2020 | SYSTEM        | (\$112,440.00) |  |          |   |    |                |        |                |    |                 |                 |                |                |  |  |  |  |  |  |  |  |  |  |    |
|        |                       |                    |                             | 7              | Oct 16,<br>2020 | SYSTEM        | \$112,440.00   | This adjustment offsets the original system-generated Overrun<br>Payment Estimate Item Adjustment (0016) due to user kloepj1<br>overridding Payment Estimate Exception 1 on the current Payment<br>Estimate. |          |   |    |                |        |                |    |                 |                 |                |                |  |  |  |  |  |  |  |  |  |  |    |
|        |                       |                    |                             |                |                 |               |                |  |          |   |    |                |        |                |    | 8               | Nov 2,<br>2020  | SYSTEM         | (\$112,440.00) |  |  |  |  |  |  |  |  |  |  |    |
|        |                       |                    |                             | 8              | Nov 2,<br>2020  | SYSTEM        | \$112,440.00   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate.           |          |   |    |                |        |                |    |                 |                 |                |                |  |  |  |  |  |  |  |  |  |  |    |
|        |                       |                    |                             | 9              | Nov 16,<br>2020 | SYSTEM        | (\$157,440.00) |  |          |   |    |                |        |                |    |                 |                 |                |                |  |  |  |  |  |  |  |  |  |  |    |
|        |                       |                    |                             |                |                 |               |                |  |          |   |    |                |        |                |    | 9               | Nov 16,<br>2020 | SYSTEM         | \$157,440.00   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. |  |  |  |  |  |  |  |  |  |    |
|        |                       |                    |                             | 10             | Dec 2,<br>2020  | SYSTEM        | (\$166,440.00) |  |          |   |    |                |        |                |    |                 |                 |                |                |  |  |  |  |  |  |  |  |  |  |    |
|        |                       |                    |                             | 10             | Dec 2,<br>2020  | SYSTEM        | \$166,440.00   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.          |          |   |    |                |        |                |    |                 |                 |                |                |  |  |  |  |  |  |  |  |  |  |    |
|        |                       |                    |                             |                |                 |               |                |  |          |   |    |                |        |                | 11 | Dec 16,<br>2020 | SYSTEM          | (\$195,990.00) |                |  |  |  |  |  |  |  |  |  |  |    |
|        |                       |                    |                             |                |                 |               |                |  |          |   |    |                |        |                |    |                 |                 |                |                |  |  |  |  |  |  |  |  |  |  | 11 |
|        |                       |                    |                             |                |                 |               |                |  |          |   | 12 | Jan 4,<br>2021 | SYSTEM | (\$195,990.00) |    |                 |                 |                |                |  |  |  |  |  |  |  |  |  |  |    |
|        |                       |                    |                             | 12             | Jan 4,<br>2021  | SYSTEM        | \$195,990.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.         |          |   |    |                |        |                |    |                 |                 |                |                |  |  |  |  |  |  |  |  |  |  |    |

Revision 4/1/2020 Page 21 of 45



| Line | Description           | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By | Amount         | Remarks  |
|------|-----------------------|--------------------|-----------------------------|----------------|-----------------|---------------|----------------|--|
| 0060 | COMPACTING EMBANKMENT | Material           |                             | 13             | Jan 19,<br>2021 | SYSTEM        | (\$195,990.00) |  |
|      |                       |                    |                             | 13             | Jan 19,<br>2021 | SYSTEM        | \$195,990.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schlag1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
|      |                       |                    |                             | 14             | Feb 2,<br>2021  | SYSTEM        | (\$197,490.00) |  |
|      |                       |                    |                             | 14             | Feb 2,<br>2021  | SYSTEM        | \$197,490.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hillit5 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
|      |                       |                    |                             | 15             | Feb 16,<br>2021 | SYSTEM        | (\$197,490.00) |  |
|      |                       |                    |                             | 15             | Feb 16,<br>2021 | SYSTEM        | \$197,490.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schlag1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
|      |                       |                    |                             | 16             | Mar 2,<br>2021  | SYSTEM        | (\$197,490.00) |  |
|      |                       |                    |                             | 16             | Mar 2,<br>2021  | SYSTEM        | \$197,490.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
|      |                       |                    | - Total                     |                |                 |               | \$0.00         |  |
|      | Material - Total      |                    |                             |                |                 |               | \$0.00         |  |
| 0060 | - Total               |                    |                             |                |                 |               | \$0.00         |  |
| 0210 | TYPE A2 SHOULDER      | Material           |                             | 6              | Oct 1,<br>2020  | SYSTEM        | (\$14,241.60)  |  |
|      |                       |                    |                             | 6              | Oct 1,<br>2020  | SYSTEM        | \$14,241.60    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user kloepj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.  |
|      |                       |                    |                             | 7              | Oct 16,<br>2020 | SYSTEM        | (\$14,241.60)  |  |
|      |                       |                    |                             | 7              | Oct 16,<br>2020 | SYSTEM        | \$14,241.60    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user kloepj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.  |
|      |                       |                    |                             | 8              | Nov 2,<br>2020  | SYSTEM        | (\$14,241.60)  |  |
|      |                       |                    |                             | 8              | Nov 2,<br>2020  | SYSTEM        | \$14,241.60    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user hillt5 overridding Payment Estimate Exception 6 on the current Payment Estimate.   |
|      |                       |                    |                             | 9              | Nov 16,<br>2020 | SYSTEM        | (\$14,241.60)  |  |
|      |                       |                    |                             | 9              | Nov 16,<br>2020 | SYSTEM        | \$14,241.60    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user hillt5 overridding Payment Estimate Exception 6 on the current Payment Estimate.   |
|      |                       |                    |                             | 10             | Dec 2,<br>2020  | SYSTEM        | (\$14,880.96)  |  |
|      |                       |                    |                             | 10             | Dec 2,<br>2020  | SYSTEM        | \$14,880.96    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user kloepj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.  |
|      |                       |                    |                             | 11             | Dec 16,<br>2020 | SYSTEM        | (\$14,880.96)  |  |
|      |                       |                    |                             | 11             | Dec 16,<br>2020 | SYSTEM        | \$14,880.96    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user schlag1 overridding Payment Estimate Exception 6 on the current Payment Estimate.  |
|      |                       |                    |                             | 12             | Jan 4,<br>2021  | SYSTEM        | (\$14,880.96)  |  |
|      |                       |                    |                             | 12             | Jan 4,<br>2021  | SYSTEM        | \$14,880.96    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 7 on the current Payment Estimate. |
|      |                       |                    |                             | 13             | Jan 19,         | SYSTEM        | (\$14,880.96)  |  |

Revision 4/1/2020 Page 22 of 45



| Line   | Description                                   | Adjustment<br>Type        | Other<br>Adjustment | Est.<br>Number | Created Date    | Created<br>By | Amount        | Remarks   |
|--------|---|---------------------------|---------------------|----------------|-----------------|---------------|---------------|---|
|        |   |                           | Туре                |                |                 |               |               |   |
| 0210   | TYPE A2 SHOULDER                              | Material                  |                     |                | 2021            |               |               |   |
|        |   |                           |                     | 13             | Jan 19,<br>2021 | SYSTEM        | \$14,880.96   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schlag1 overridding Payment Estimate Exception 6 on the current Payment Estimate.  |
|        |   |                           |                     | 14             | Feb 2,<br>2021  | SYSTEM        | (\$14,880.96) |   |
|        |   |                           |                     | 14             | Feb 2,<br>2021  | SYSTEM        | \$14,880.96   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hillt5 overridding Payment Estimate Exception 6 on the current Payment Estimate.   |
|        |   |                           |                     | 15             | Feb 16,<br>2021 | SYSTEM        | (\$14,880.96) |   |
|        |   |                           |                     | 15             | Feb 16,<br>2021 | SYSTEM        | \$14,880.96   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schlag1 overridding Payment Estimate Exception 6 on the current Payment Estimate.  |
|        |   |                           |                     | 16             | Mar 2,<br>2021  | SYSTEM        | (\$14,880.96) |   |
|        |   |                           |                     | 16             | Mar 2,<br>2021  | SYSTEM        | \$14,880.96   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kloepj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.  |
|        |   |                           | - Total             |                |                 |               | \$0.00        |   |
|        | Material - Total                              |                           |                     |                |                 |               | \$0.00        |   |
| 0210 - | · Total                                       |                           |                     |                |                 |               | \$0.00        |   |
| 0270   | WATER   | Construction<br>Stockpile |                     | 6              | Oct 1,<br>2020  | SYSTEM        | \$75,319.80   | Payment Estimate Item Adjustment generated Stockpile Transaction  |
|        |   |                           |                     | 11             | Dec 16,<br>2020 | SYSTEM        | (\$43,011.57) | Payment Estimate Item Adjustment generated Stockpile Transaction  |
|        |   |                           |                     | 13             | Jan 19,<br>2021 | SYSTEM        | (\$8,549.46)  | Payment Estimate Item Adjustment generated Stockpile Transaction  |
|        |   |                           |                     | 15             | Feb 16,<br>2021 | SYSTEM        | (\$23,758.77) | Payment Estimate Item Adjustment generated Stockpile Transaction  |
|        |   |                           | - Total             |                |                 |               | \$0.00        |   |
|        | Construction Stockpile - Total                |                           |                     |                |                 |               | \$0.00        |   |
| 0270 - | Total   |                           |                     |                |                 |               | \$0.00        |   |
| 0280   | WATER   | Construction<br>Stockpile |                     | 6              | Oct 1,<br>2020  | SYSTEM        | \$13,214.00   | Payment Estimate Item Adjustment generated Stockpile Transaction  |
|        |   |                           |                     | 11             | Dec 16,<br>2020 | SYSTEM        | (\$13,214.00) | Payment Estimate Item Adjustment generated Stockpile Transaction  |
|        |   |                           | - Total             |                |                 |               | \$0.00        |   |
|        | Construction Stockpile - Total                |                           |                     |                |                 |               | \$0.00        |   |
| 0280 - | Total   |                           |                     |                |                 |               | \$0.00        |   |
| 0480   | INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A | Material                  |                     | 16             | Mar 2,<br>2021  | SYSTEM        | (\$2,715.00)  |   |
|        |   |                           |                     | 16             | Mar 2,<br>2021  | SYSTEM        | \$2,715.00    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate. |
|        |   |                           | - Total             |                |                 |               | \$0.00        |   |
|        | Material - Total                              |                           |                     |                |                 |               | \$0.00        |   |
| 0480 - | Total   |                           |                     |                |                 |               | \$0.00        |   |
| 0675   | CONCRETE TRAFFIC BARRIER, TYPE C              | Material                  |                     | 3              | Aug 17,<br>2020 | SYSTEM        | (\$36,830.00) |   |
|        |   |                           |                     | 3              | Aug 17,<br>2020 | SYSTEM        | \$36,830.00   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.   |
|        |   |                           |                     | 4              | Sep 2,<br>2020  | SYSTEM        | (\$36,830.00) |   |
|        |   |                           |                     | 4              | Sep 2,<br>2020  | SYSTEM        | \$36,830.00   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.   |

Revision 4/1/2020 Page 23 of 45



| Line | Description                      | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By | Amount          | Remarks  |               |   |                 |                 |               |   |        |               |  |    |                |                 |               |                |   |                |                 |             |  |
|------|----------------------------------|--------------------|-----------------------------|----------------|-----------------|---------------|-----------------|--|---------------|---|-----------------|-----------------|---------------|---|--------|---------------|--|----|----------------|-----------------|---------------|----------------|---|----------------|-----------------|-------------|--|
| 0675 | CONCRETE TRAFFIC BARRIER, TYPE C | Material           |                             | 5              | Sep 16,<br>2020 | SYSTEM        | (\$36,830.00)   |  |               |   |                 |                 |               |   |        |               |  |    |                |                 |               |                |   |                |                 |             |  |
|      |                                  |                    |                             | 5              | Sep 16,<br>2020 | SYSTEM        | \$36,830.00     | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  |               |   |                 |                 |               |   |        |               |  |    |                |                 |               |                |   |                |                 |             |  |
|      |                                  |                    |                             | 6              | Oct 1,<br>2020  | SYSTEM        | (\$66,845.00)   |  |               |   |                 |                 |               |   |        |               |  |    |                |                 |               |                |   |                |                 |             |  |
|      |                                  |                    |                             | 6              | Oct 1,<br>2020  | SYSTEM        | \$66,845.00     | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 16 on the current Payment Estimate. |               |   |                 |                 |               |   |        |               |  |    |                |                 |               |                |   |                |                 |             |  |
|      |                                  |                    |                             |                |                 | 7             | Oct 16,<br>2020 | SYSTEM   | (\$66,845.00) |   |                 |                 |               |   |        |               |  |    |                |                 |               |                |   |                |                 |             |  |
|      |                                  |                    |                             | 7              | Oct 16,<br>2020 | SYSTEM        | \$66,845.00     | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 16 on the current Payment Estimate. |               |   |                 |                 |               |   |        |               |  |    |                |                 |               |                |   |                |                 |             |  |
|      |                                  |                    |                             |                |                 | 8             | Nov 2,<br>2020  | SYSTEM   | (\$66,845.00) |   |                 |                 |               |   |        |               |  |    |                |                 |               |                |   |                |                 |             |  |
|      |                                  |                    |                             |                |                 | 8             | Nov 2,<br>2020  | SYSTEM   | \$66,845.00   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user hillt5 overridding Payment Estimate Exception 14 on the current Payment Estimate. |                 |                 |               |   |        |               |  |    |                |                 |               |                |   |                |                 |             |  |
|      |                                  |                    |                             |                |                 |               |                 |  |               |   | 9               | Nov 16,<br>2020 | SYSTEM        | (\$66,845.00)   |        |               |  |    |                |                 |               |                |   |                |                 |             |  |
|      |                                  |                    |                             | 9              | Nov 16,<br>2020 | SYSTEM        | \$66,845.00     | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user hillt5 overridding Payment Estimate Exception 14 on the current Payment Estimate.  |               |   |                 |                 |               |   |        |               |  |    |                |                 |               |                |   |                |                 |             |  |
|      |                                  |                    |                             | 10             | Dec 2,<br>2020  | SYSTEM        | (\$66,845.00)   |  |               |   |                 |                 |               |   |        |               |  |    |                |                 |               |                |   |                |                 |             |  |
|      |                                  |                    |                             | 10             | Dec 2,<br>2020  | SYSTEM        | \$66,845.00     | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 14 on the current Payment Estimate. |               |   |                 |                 |               |   |        |               |  |    |                |                 |               |                |   |                |                 |             |  |
|      |                                  |                    |                             | 11             | Dec 16,<br>2020 | SYSTEM        | (\$66,845.00)   |  |               |   |                 |                 |               |   |        |               |  |    |                |                 |               |                |   |                |                 |             |  |
|      |                                  |                    |                             | 11             | Dec 16,<br>2020 | SYSTEM        | \$66,845.00     | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user schlag1 overridding Payment Estimate Exception 14 on the current Payment Estimate. |               |   |                 |                 |               |   |        |               |  |    |                |                 |               |                |   |                |                 |             |  |
|      |                                  |                    |                             |                |                 |               |                 |  |               |   |                 |                 |               |   |        |               |  | 12 | Jan 4,<br>2021 | SYSTEM          | (\$66,845.00) |                |   |                |                 |             |  |
|      |                                  |                    |                             |                |                 |               |                 |  |               | 12  | Jan 4,<br>2021  | SYSTEM          | \$66,845.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kloepj1 overridding Payment Estimate Exception 15 on the current Payment Estimate. |        |               |  |    |                |                 |               |                |   |                |                 |             |  |
|      |                                  |                    |                             |                |                 |               |                 |  |               | 13  | Jan 19,<br>2021 | SYSTEM          | (\$66,845.00) |   |        |               |  |    |                |                 |               |                |   |                |                 |             |  |
|      |                                  |                    |                             |                |                 |               |                 |  |               |   |                 |                 |               |   |        |               |  |    |                |                 |               |                |   | 13             | Jan 19,<br>2021 | SYSTEM      | \$66,845.00  |
|      |                                  |                    |                             | 14             | Feb 2,<br>2021  | SYSTEM        | (\$66,845.00)   |  |               |   |                 |                 |               |   |        |               |  |    |                |                 |               |                |   |                |                 |             |  |
|      |                                  |                    |                             |                |                 |               |                 |  |               |   |                 |                 |               |   |        |               |  |    |                |                 |               |                | 14  | Feb 2,<br>2021 | SYSTEM          | \$66,845.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hillt5 overridding Payment Estimate Exception 13 on the current Payment Estimate. |
|      |                                  |                    |                             |                |                 |               |                 |  |               |   |                 |                 | 15            | Feb 16,<br>2021   | SYSTEM | (\$66,845.00) |  |    |                |                 |               |                |   |                |                 |             |  |
|      |                                  |                    |                             |                |                 |               |                 |  |               |   |                 |                 |               |   |        |               |  |    | 15             | Feb 16,<br>2021 | SYSTEM        | \$66,845.00    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schlag1 overridding Payment Estimate Exception 21 on the current Payment Estimate. |                |                 |             |  |
|      |                                  |                    |                             |                |                 |               |                 |  |               |   |                 |                 |               |   |        |               |  |    |                |                 | 16            | Mar 2,<br>2021 | SYSTEM  | (\$66,845.00)  |                 |             |  |
|      |                                  |                    |                             |                |                 |               |                 |  |               |   |                 |                 |               |   |        |               |  |    |                |                 |               |                |   |                |                 |             |  |

Revision 4/1/2020 Page 24 of 45



| Line   | Description                                       | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By   | Amount         | Remarks   |        |               |   |  |    |                 |        |
|--------|---|--------------------|-----------------------------|----------------|-----------------|-----------------|----------------|---|--------|---------------|---|--|----|-----------------|--------|
| 0675   |   | Material           | - Total                     |                |                 |                 | \$0.00         |   |        |               |   |  |    |                 |        |
|        | Material - Total                                  |                    |                             |                |                 |                 | \$0.00         |   |        |               |   |  |    |                 |        |
| 0675 - | Total   |                    |                             |                |                 |                 | \$0.00         |   |        |               |   |  |    |                 |        |
| 0690   | CONCRETE TRAFFIC BARRIER, TYPE D (RETAINING WALL) | Material           |                             | 6              | Oct 1,<br>2020  | SYSTEM          | (\$15,385.00)  |   |        |               |   |  |    |                 |        |
|        |   |                    |                             | 6              | Oct 1,<br>2020  | SYSTEM          | \$15,385.00    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.  |        |               |   |  |    |                 |        |
|        |   |                    |                             | 7              | Oct 16,<br>2020 | SYSTEM          | (\$51,935.00)  |   |        |               |   |  |    |                 |        |
|        |   |                    |                             | 7              | Oct 16,<br>2020 | SYSTEM          | \$51,935.00    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.  |        |               |   |  |    |                 |        |
|        |   |                    |                             |                |                 |                 | 8              | Nov 2,<br>2020  | SYSTEM | (\$78,625.00) |   |  |    |                 |        |
|        |   |                    |                             |                |                 |                 | 8              | Nov 2,<br>2020  | SYSTEM | \$78,625.00   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user hillt5 overridding Payment Estimate Exception 17 on the current Payment Estimate. |  |    |                 |        |
|        |   |                    |                             |                |                 |                 | 9              | Nov 16,<br>2020   | SYSTEM | (\$79,900.00) |   |  |    |                 |        |
|        |   |                    |                             | 9              | Nov 16,<br>2020 | SYSTEM          | \$79,900.00    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user hillt5 overridding Payment Estimate Exception 17 on the current Payment Estimate.   |        |               |   |  |    |                 |        |
|        |   |                    |                             | 10             | Dec 2,<br>2020  | SYSTEM          | (\$148,325.00) |   |        |               |   |  |    |                 |        |
|        |   |                    |                             | 10             | Dec 2,<br>2020  | SYSTEM          | \$148,325.00   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.  |        |               |   |  |    |                 |        |
|        |   |                    |                             |                | 11              | Dec 16,<br>2020 | SYSTEM         | (\$148,325.00)  |        |               |   |  |    |                 |        |
|        |   |                    |                             |                |                 |                 |                |   |        |               |   |  | 11 | Dec 16,<br>2020 | SYSTEM |
|        |   |                    |                             | 12             | Jan 4,<br>2021  | SYSTEM          | (\$148,325.00) |   |        |               |   |  |    |                 |        |
|        |   |                    |                             | 12             | Jan 4,<br>2021  | SYSTEM          | \$148,325.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 18 on the current Payment Estimate. |        |               |   |  |    |                 |        |
|        |   |                    |                             | 13             | Jan 19,<br>2021 | SYSTEM          | (\$148,325.00) |   |        |               |   |  |    |                 |        |
|        |   |                    |                             | 13             | Jan 19,<br>2021 | SYSTEM          | \$148,325.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schlag1 overridding Payment Estimate Exception 17 on the current Payment Estimate. |        |               |   |  |    |                 |        |
|        |   |                    |                             | 14             | Feb 2,<br>2021  | SYSTEM          | (\$148,325.00) |   |        |               |   |  |    |                 |        |
|        |   |                    |                             | 14             | Feb 2,<br>2021  | SYSTEM          | \$148,325.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hillt5 overridding Payment Estimate Exception 16 on the current Payment Estimate.  |        |               |   |  |    |                 |        |
|        |   |                    |                             | 15             | Feb 16,<br>2021 | SYSTEM          | (\$148,325.00) |   |        |               |   |  |    |                 |        |
|        |   |                    |                             | 15             | Feb 16,<br>2021 | SYSTEM          | \$148,325.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schlag1 overridding Payment Estimate Exception 24 on the current Payment Estimate. |        |               |   |  |    |                 |        |
|        |   |                    |                             | 16             | Mar 2,<br>2021  | SYSTEM          | (\$148,325.00) |   |        |               |   |  |    |                 |        |
|        |   |                    |                             | 16             | Mar 2,<br>2021  | SYSTEM          | \$148,325.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 25 on the current Payment Estimate. |        |               |   |  |    |                 |        |
|        |   |                    | - Total                     |                |                 |                 | \$0.00         |   |        |               |   |  |    |                 |        |

Revision 4/1/2020 Page 25 of 45



| 0690 - T |                                       |          |         |    |                 |                |                |   |   |                |        |               |                 |        |             |   |        |             |   |                 |        |               |  |
|----------|---------------------------------------|----------|---------|----|-----------------|----------------|----------------|---|---|----------------|--------|---------------|-----------------|--------|-------------|---|--------|-------------|---|-----------------|--------|---------------|--|
|          | MISC. Miscellaneous Granular Drainage |          |         |    |                 |                | \$0.00         |   |   |                |        |               |                 |        |             |   |        |             |   |                 |        |               |  |
| 0990     |                                       |          |         |    |                 |                | \$0.00         |   |   |                |        |               |                 |        |             |   |        |             |   |                 |        |               |  |
|          | Diariket                              | Material |         | 6  | Oct 1,<br>2020  | SYSTEM         | (\$11,470.00)  |   |   |                |        |               |                 |        |             |   |        |             |   |                 |        |               |  |
|          |                                       |          |         | 6  | Oct 1,<br>2020  | SYSTEM         | \$11,470.00    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 25 on the current Payment Estimate.  |   |                |        |               |                 |        |             |   |        |             |   |                 |        |               |  |
|          |                                       |          |         | 7  | Oct 16,<br>2020 | SYSTEM         | (\$32,782.50)  |   |   |                |        |               |                 |        |             |   |        |             |   |                 |        |               |  |
|          |                                       |          |         | 7  | Oct 16,<br>2020 | SYSTEM         | \$32,782.50    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 25 on the current Payment Estimate.  |   |                |        |               |                 |        |             |   |        |             |   |                 |        |               |  |
|          |                                       |          |         | 8  | Nov 2,<br>2020  | SYSTEM         | (\$32,782.50)  |   |   |                |        |               |                 |        |             |   |        |             |   |                 |        |               |  |
|          |                                       |          |         | 8  | Nov 2,<br>2020  | SYSTEM         | \$32,782.50    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user hillt5 overridding Payment Estimate Exception 20 on the current Payment Estimate.   |   |                |        |               |                 |        |             |   |        |             |   |                 |        |               |  |
|          |                                       |          |         | 9  | Nov 16,<br>2020 | SYSTEM         | (\$32,782.50)  |   |   |                |        |               |                 |        |             |   |        |             |   |                 |        |               |  |
|          |                                       |          |         | 9  | Nov 16,<br>2020 | SYSTEM         | \$32,782.50    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user hillt5 overridding Payment Estimate Exception 20 on the current Payment Estimate.   |   |                |        |               |                 |        |             |   |        |             |   |                 |        |               |  |
|          |                                       |          |         |    |                 | 10             | Dec 2,<br>2020 | SYSTEM  | (\$37,215.50)   |                |        |               |                 |        |             |   |        |             |   |                 |        |               |  |
|          |                                       |          |         | 10 | Dec 2,<br>2020  | SYSTEM         | \$37,215.50    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.  |   |                |        |               |                 |        |             |   |        |             |   |                 |        |               |  |
|          |                                       |          |         | 11 | Dec 16,<br>2020 | SYSTEM         | (\$37,215.50)  |   |   |                |        |               |                 |        |             |   |        |             |   |                 |        |               |  |
|          |                                       |          |         | 11 | Dec 16,<br>2020 | SYSTEM         | \$37,215.50    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user schlag1 overridding Payment Estimate Exception 19 on the current Payment Estimate.  |   |                |        |               |                 |        |             |   |        |             |   |                 |        |               |  |
|          |                                       |          |         |    |                 |                |                |   | 12  | Jan 4,<br>2021 | SYSTEM | (\$37,215.50) |                 |        |             |   |        |             |   |                 |        |               |  |
|          |                                       |          |         |    | 12              | Jan 4,<br>2021 | SYSTEM         | \$37,215.50   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate. |                |        |               |                 |        |             |   |        |             |   |                 |        |               |  |
|          |                                       |          |         |    |                 |                |                |   |   |                |        |               |                 |        |             |   |        |             | 13  | Jan 19,<br>2021 | SYSTEM | (\$37,215.50) |  |
|          |                                       |          |         |    |                 |                |                |   |   |                |        |               |                 |        | 13          | Jan 19,<br>2021   | SYSTEM | \$37,215.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schlag1 overridding Payment Estimate Exception 19 on the current Payment Estimate. |                 |        |               |  |
|          |                                       |          |         |    |                 | 14             | Feb 2,<br>2021 | SYSTEM  | (\$37,215.50)   |                |        |               |                 |        |             |   |        |             |   |                 |        |               |  |
|          |                                       |          |         | 14 | Feb 2,<br>2021  | SYSTEM         | \$37,215.50    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 18 on the current Payment Estimate.  |   |                |        |               |                 |        |             |   |        |             |   |                 |        |               |  |
|          |                                       |          |         | 15 | Feb 16,<br>2021 | SYSTEM         | (\$37,215.50)  |   |   |                |        |               |                 |        |             |   |        |             |   |                 |        |               |  |
|          |                                       |          |         |    |                 |                |                |   |   |                |        | 15            | Feb 16,<br>2021 | SYSTEM | \$37,215.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schlag1 overridding Payment Estimate Exception 26 on the current Payment Estimate. |        |             |   |                 |        |               |  |
|          |                                       |          |         | 16 | Mar 2,<br>2021  | SYSTEM         | (\$37,215.50)  |   |   |                |        |               |                 |        |             |   |        |             |   |                 |        |               |  |
|          |                                       |          |         | 16 | Mar 2,<br>2021  | SYSTEM         | \$37,215.50    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment Estimate Exception 27 on the current Payment Estimate. |   |                |        |               |                 |        |             |   |        |             |   |                 |        |               |  |
|          |                                       |          | - Total |    |                 |                | \$0.00         |   |   |                |        |               |                 |        |             |   |        |             |   |                 |        |               |  |
| N        | Material - Total                      |          |         |    |                 |                | \$0.00         |   |   |                |        |               |                 |        |             |   |        |             |   |                 |        |               |  |

Revision 4/1/2020 Page 26 of 45



| Line   | Description                                | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By  | Amount          | Remarks   |             |  |    |                |        |               |  |  |  |  |  |  |  |  |    |                 |        |             |   |
|--------|--|--------------------|-----------------------------|----------------|-----------------|----------------|-----------------|---|-------------|--|----|----------------|--------|---------------|--|--|--|--|--|--|--|--|----|-----------------|--------|-------------|---|
| 0990 - | · Total                                    |                    |                             |                |                 |                | \$0.00          |   |             |  |    |                |        |               |  |  |  |  |  |  |  |  |    |                 |        |             |   |
| 1050   | MISC. Miscellaneous Stone Columns          | Material           |                             | 8              | Nov 2,<br>2020  | SYSTEM         | (\$23,800.00)   |   |             |  |    |                |        |               |  |  |  |  |  |  |  |  |    |                 |        |             |   |
|        |  |                    |                             | 8              | Nov 2,<br>2020  | SYSTEM         | \$23,800.00     | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user hillt5 overridding Payment Estimate Exception 21 on the current Payment Estimate.           |             |  |    |                |        |               |  |  |  |  |  |  |  |  |    |                 |        |             |   |
|        |  |                    |                             | 9              | Nov 16,<br>2020 | SYSTEM         | (\$23,800.00)   |   |             |  |    |                |        |               |  |  |  |  |  |  |  |  |    |                 |        |             |   |
|        |  |                    |                             | 9              | Nov 16,<br>2020 | SYSTEM         | \$23,800.00     | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user hillt5 overridding Payment Estimate Exception 21 on the current Payment Estimate.           |             |  |    |                |        |               |  |  |  |  |  |  |  |  |    |                 |        |             |   |
|        |  |                    |                             | 10             | Dec 2,<br>2020  | SYSTEM         | (\$23,800.00)   |   |             |  |    |                |        |               |  |  |  |  |  |  |  |  |    |                 |        |             |   |
|        |  |                    |                             |                |                 | 10             | Dec 2,<br>2020  | SYSTEM  | \$23,800.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 21 on the current Payment Estimate. |    |                |        |               |  |  |  |  |  |  |  |  |    |                 |        |             |   |
|        |  |                    |                             |                |                 |                | 11              | Dec 16,<br>2020   | SYSTEM      | (\$23,800.00)  |    |                |        |               |  |  |  |  |  |  |  |  |    |                 |        |             |   |
|        |  |                    |                             |                |                 | 11             | Dec 16,<br>2020 | SYSTEM  | \$23,800.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user schlag1 overridding Payment Estimate Exception 20 on the current Payment Estimate. |    |                |        |               |  |  |  |  |  |  |  |  |    |                 |        |             |   |
|        |  |                    |                             |                | 12              | Jan 4,<br>2021 | SYSTEM          | (\$23,800.00)   |             |  |    |                |        |               |  |  |  |  |  |  |  |  |    |                 |        |             |   |
|        |  |                    |                             | 12             | Jan 4,<br>2021  | SYSTEM         | \$23,800.00     | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kloepj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.         |             |  |    |                |        |               |  |  |  |  |  |  |  |  |    |                 |        |             |   |
|        |  |                    |                             |                |                 |                | 13              | Jan 19,<br>2021   | SYSTEM      | (\$23,800.00)  |    |                |        |               |  |  |  |  |  |  |  |  |    |                 |        |             |   |
|        |  |                    |                             | 13             | Jan 19,<br>2021 | SYSTEM         | \$23,800.00     | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schlag1 overridding Payment Estimate Exception 20 on the current Payment Estimate.         |             |  |    |                |        |               |  |  |  |  |  |  |  |  |    |                 |        |             |   |
|        |  |                    |                             |                |                 |                |                 |   |             |  | 14 | Feb 2,<br>2021 | SYSTEM | (\$23,800.00) |  |  |  |  |  |  |  |  |    |                 |        |             |   |
|        |  |                    |                             | 14             | Feb 2,<br>2021  | SYSTEM         | \$23,800.00     | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hillt5 overridding Payment Estimate Exception 31 on the current Payment Estimate.          |             |  |    |                |        |               |  |  |  |  |  |  |  |  |    |                 |        |             |   |
|        |  |                    |                             | 15             | Feb 16,<br>2021 | SYSTEM         | (\$23,800.00)   |   |             |  |    |                |        |               |  |  |  |  |  |  |  |  |    |                 |        |             |   |
|        |  |                    |                             |                |                 |                |                 |   |             |  |    |                |        |               |  |  |  |  |  |  |  |  | 15 | Feb 16,<br>2021 | SYSTEM | \$23,800.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schlag1 overridding Payment Estimate Exception 39 on the current Payment Estimate. |
|        |  |                    |                             |                |                 |                | 16              | Mar 2,<br>2021  | SYSTEM      | (\$23,800.00)  |    |                |        |               |  |  |  |  |  |  |  |  |    |                 |        |             |   |
|        |  |                    |                             | 16             | Mar 2,<br>2021  | SYSTEM         | \$23,800.00     | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kloepj1 overridding Payment Estimate Exception 35 on the current Payment Estimate.         |             |  |    |                |        |               |  |  |  |  |  |  |  |  |    |                 |        |             |   |
|        |  |                    | - Total                     |                |                 |                | \$0.00          |   |             |  |    |                |        |               |  |  |  |  |  |  |  |  |    |                 |        |             |   |
|        | Material - Total                           |                    |                             |                |                 |                | \$0.00          |   |             |  |    |                |        |               |  |  |  |  |  |  |  |  |    |                 |        |             |   |
|        | Total                                      |                    |                             | _              |                 | 0)/0==         | \$0.00          |   |             |  |    |                |        |               |  |  |  |  |  |  |  |  |    |                 |        |             |   |
| 1090   | MECHANICALLY STABILIZED EARTH WALL SYSTEMS | Material           |                             | 7              | Oct 16,<br>2020 | SYSTEM         | (\$203,640.00)  |   |             |  |    |                |        |               |  |  |  |  |  |  |  |  |    |                 |        |             |   |
|        |  |                    |                             | 7              | Oct 16,<br>2020 | SYSTEM         | \$203,640.00    | This adjustment offsets the original system-generated Overrun<br>Payment Estimate Item Adjustment (0018) due to user kloepj1<br>overridding Payment Estimate Exception 26 on the current Payment<br>Estimate. |             |  |    |                |        |               |  |  |  |  |  |  |  |  |    |                 |        |             |   |
|        |  |                    |                             | 8              | Nov 2,<br>2020  | SYSTEM         | (\$203,640.00)  |   |             |  |    |                |        |               |  |  |  |  |  |  |  |  |    |                 |        |             |   |
|        |  |                    |                             | 8              | Nov 2,<br>2020  | SYSTEM         | \$203,640.00    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user hillt5 overridding Payment Estimate Exception 26 on the current Payment Estimate.           |             |  |    |                |        |               |  |  |  |  |  |  |  |  |    |                 |        |             |   |

Revision 4/1/2020 Page 27 of 45



| Line | Description  | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By   | Amount         | Remarks   |   |
|------|--|--------------------|-----------------------------|----------------|-----------------|-----------------|----------------|---|---|
| 1090 | MECHANICALLY STABILIZED EARTH WALL SYSTEMS         | Material           |                             | 9              | Nov 16,<br>2020 | SYSTEM          | (\$203,640.00) |   |   |
|      |  |                    |                             | 9              | Nov 16,<br>2020 | SYSTEM          | \$203,640.00   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user hillt5 overridding Payment Estimate Exception 26 on the current Payment Estimate.           |   |
|      |  |                    |                             | 10             | Dec 2,<br>2020  | SYSTEM          | (\$203,640.00) |   |   |
|      |  |                    |                             | 10             | Dec 2,<br>2020  | SYSTEM          | \$203,640.00   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.          |   |
|      |  |                    |                             | 11             | Dec 16,<br>2020 | SYSTEM          | (\$203,640.00) |   |   |
|      |  |                    |                             | 11             | Dec 16,<br>2020 | SYSTEM          | \$203,640.00   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user schlag1 overridding Payment Estimate Exception 24 on the current Payment Estimate.          |   |
|      |  |                    |                             | 12             | Jan 4,<br>2021  | SYSTEM          | (\$203,640.00) |   |   |
|      |  |                    |                             | 12             | Jan 4,<br>2021  | SYSTEM          | \$203,640.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.         |   |
|      |  |                    |                             | 13             | Jan 19,<br>2021 | SYSTEM          | (\$203,640.00) |   |   |
|      |  |                    |                             |                | 13              | Jan 19,<br>2021 | SYSTEM         | \$203,640.00  | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schlag1 overridding Payment Estimate Exception 21 on the current Payment Estimate. |
|      |  |                    |                             | 14             | Feb 2,<br>2021  | SYSTEM          | (\$203,640.00) |   |   |
|      |  |                    |                             | 14             | Feb 2,<br>2021  | SYSTEM          | \$203,640.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hillt5 overridding Payment Estimate Exception 49 on the current Payment Estimate.          |   |
|      |  |                    | - Total                     |                |                 |                 | \$0.00         |   |   |
|      | Material - Total                                   |                    |                             |                |                 |                 | \$0.00         |   |   |
|      | Total  |                    |                             |                |                 |                 | \$0.00         |   |   |
| 1100 | SELECT GRANULAR BACKFILL FOR<br>STRUCTURAL SYSTEMS | Material           |                             | 7              | Oct 16,<br>2020 | SYSTEM          | (\$41,310.00)  |   |   |
|      |  |                    |                             | 7              | Oct 16,<br>2020 | SYSTEM          | \$41,310.00    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.          |   |
|      |  |                    |                             | 11             | Dec 16,<br>2020 | SYSTEM          | (\$256,560.00) |   |   |
|      |  |                    |                             | 11             | Dec 16,<br>2020 | SYSTEM          | \$256,560.00   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user schlag1 overridding Payment Estimate Exception 26 on the current Payment Estimate.          |   |
|      |  |                    |                             | 12             | Jan 4,<br>2021  | SYSTEM          | (\$256,560.00) |   |   |
|      |  |                    |                             | 12             | Jan 4,<br>2021  | SYSTEM          | \$256,560.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 27 on the current Payment Estimate.         |   |
|      |  |                    |                             | 13             | Jan 19,<br>2021 | SYSTEM          | (\$256,560.00) |   |   |
|      |  |                    |                             | 13             | Jan 19,<br>2021 | SYSTEM          | \$256,560.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schlag1 overridding Payment Estimate Exception 24 on the current Payment Estimate.         |   |
|      |  |                    |                             | 14             | Feb 2,<br>2021  | SYSTEM          | (\$256,560.00) |   |   |
|      |  |                    |                             |                |                 | 01/0==1/        | 0050 500 00    |   |   |
|      |  |                    |                             | 14             | Feb 2,<br>2021  | SYSTEM          | \$256,560.00   | This adjustment offsets the original system-generated Material<br>Payment Estimate Item Adjustment (0011) due to user hillt5<br>overridding Payment Estimate Exception 52 on the current Payment<br>Estimate. |   |

Revision 4/1/2020 Page 28 of 45



|        |  |                    |                             | _              |                 |               |                |   |
|--------|--|--------------------|-----------------------------|----------------|-----------------|---------------|----------------|---|
| Line   | Description                                    | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By | Amount         | Remarks   |
| 1100   | SELECT GRANULAR BACKFILL FOR                   | Material           |                             |                | 2021            |               |                |   |
|        | STRUCTURAL SYSTEMS                             |                    |                             | 15             | Feb 16,<br>2021 | SYSTEM        | \$256,560.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schlag1 overridding Payment Estimate Exception 51 on the current Payment Estimate. |
|        |  |                    |                             | 16             | Mar 2,<br>2021  | SYSTEM        | (\$256,560.00) |   |
|        |  |                    |                             | 16             | Mar 2,<br>2021  | SYSTEM        | \$256,560.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Exception 50 on the current Payment Estimate. |
|        |  |                    | - Total                     |                |                 |               | \$0.00         |   |
|        | Material - Total                               |                    |                             |                |                 |               | \$0.00         |   |
| 1100 - | · Total  |                    |                             |                |                 |               | \$0.00         |   |
| 1160   | MISC. MSD SPECIAL DRAINAGE<br>STRUCTURE #"301" | Material           |                             | 9              | Nov 16,<br>2020 | SYSTEM        | (\$49,500.00)  |   |
|        |  |                    |                             | 9              | Nov 16,<br>2020 | SYSTEM        | \$49,500.00    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user hillt5 overridding Payment Estimate Exception 29 on the current Payment Estimate.   |
|        |  |                    |                             | 10             | Dec 2,<br>2020  | SYSTEM        | (\$55,000.00)  |   |
|        |  |                    |                             | 10             | Dec 2,<br>2020  | SYSTEM        | \$55,000.00    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.  |
|        |  |                    |                             | 11             | Dec 16,<br>2020 | SYSTEM        | (\$55,000.00)  |   |
|        |  |                    |                             | 11             | Dec 16,<br>2020 | SYSTEM        | \$55,000.00    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user schlag1 overridding Payment Estimate Exception 27 on the current Payment Estimate.  |
|        |  |                    |                             | 12             | Jan 4,<br>2021  | SYSTEM        | (\$55,000.00)  |   |
|        |  |                    |                             | 12             | Jan 4,<br>2021  | SYSTEM        | \$55,000.00    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 28 on the current Payment Estimate. |
|        |  |                    |                             | 13             | Jan 19,<br>2021 | SYSTEM        | (\$55,000.00)  |   |
|        |  |                    |                             | 13             | Jan 19,<br>2021 | SYSTEM        | \$55,000.00    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schlag1 overridding Payment Estimate Exception 25 on the current Payment Estimate. |
|        |  |                    | - Total                     |                |                 |               | \$0.00         |   |
|        | Material - Total                               |                    |                             |                |                 |               | \$0.00         |   |
| 1160 - | · Total  |                    |                             |                |                 |               | \$0.00         |   |
| 1170   | PRECAST CONCRETE DROP INLET 2<br>FT X 2 FT     | Material           |                             | 3              | Aug 17,<br>2020 | SYSTEM        | (\$2,450.00)   |   |
|        |  |                    |                             | 3              | Aug 17,<br>2020 | SYSTEM        | \$2,450.00     | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.   |
|        |  |                    |                             | 4              | Sep 2,<br>2020  | SYSTEM        | (\$4,200.00)   |   |
|        |  |                    |                             | 4              | Sep 2,<br>2020  | SYSTEM        | \$4,200.00     | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.   |
|        |  |                    |                             | 5              | Sep 16,<br>2020 | SYSTEM        | (\$4,200.00)   |   |
|        |  |                    |                             | 5              | Sep 16,<br>2020 | SYSTEM        | \$4,200.00     | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.  |
|        |  |                    |                             | 6              | Oct 1,<br>2020  | SYSTEM        | (\$4,200.00)   |   |
|        |  |                    |                             | 6              | Oct 1,<br>2020  | SYSTEM        | \$4,200.00     | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user kloepj1   |

Revision 4/1/2020 Page 29 of 45



| Line   | Description                                | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By | Amount        | Remarks  |
|--------|--|--------------------|-----------------------------|----------------|-----------------|---------------|---------------|--|
| 1170   | PRECAST CONCRETE DROP INLET 2<br>FT X 2 FT | Material           |                             |                |                 |               |               | overridding Payment Estimate Exception 26 on the current Payment Estimate.   |
|        |  |                    |                             | 7              | Oct 16,<br>2020 | SYSTEM        | (\$4,200.00)  |  |
|        |  |                    |                             | 7              | Oct 16,<br>2020 | SYSTEM        | \$4,200.00    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment Estimate Exception 30 on the current Payment Estimate.         |
|        |  |                    | - Total                     |                |                 |               | \$0.00        |  |
|        | Material - Total                           |                    |                             |                |                 |               | \$0.00        |  |
| 1170 - |  |                    |                             |                |                 | OVOTEM        | \$0.00        |  |
| 1180   | PRECAST CONCRETE DROP INLET 4<br>FT X 2 FT | Material           |                             | 3              | Aug 17,<br>2020 | SYSTEM        | (\$8,100.00)  |  |
|        |  |                    |                             | 3              | Aug 17,<br>2020 | SYSTEM        | \$8,100.00    | This adjustment offsets the original system-generated Overrun<br>Payment Estimate Item Adjustment (0013) due to user kloepj1<br>overridding Payment Estimate Exception 8 on the current Payment<br>Estimate. |
|        |  |                    |                             | 4              | Sep 2,<br>2020  | SYSTEM        | (\$8,550.00)  |  |
|        |  |                    |                             | 4              | Sep 2,<br>2020  | SYSTEM        | \$8,550.00    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.          |
|        |  |                    |                             | 5              | Sep 16,<br>2020 | SYSTEM        | (\$8,550.00)  |  |
|        |  |                    |                             | 5              | Sep 16,<br>2020 | SYSTEM        | \$8,550.00    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.         |
|        |  |                    |                             | 6              | Oct 1,<br>2020  | SYSTEM        | (\$8,550.00)  |  |
|        |  |                    |                             | 6              | Oct 1,<br>2020  | SYSTEM        | \$8,550.00    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 27 on the current Payment Estimate.         |
|        |  |                    | - Total                     |                |                 |               | \$0.00        |  |
|        | Material - Total                           |                    |                             |                |                 |               | \$0.00        |  |
| 1180 - |  |                    |                             |                |                 |               | \$0.00        |  |
| 1190   | PRECAST CONCRETE DROP INLET 5<br>FT X 3 FT | Material           |                             | 6              | Oct 1,<br>2020  | SYSTEM        | (\$1,950.00)  |  |
|        |  |                    |                             | 6              | Oct 1,<br>2020  | SYSTEM        | \$1,950.00    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.         |
|        |  |                    |                             | 7              | Oct 16,<br>2020 | SYSTEM        | (\$15,600.00) |  |
|        |  |                    |                             | 7              | Oct 16,<br>2020 | SYSTEM        | \$15,600.00   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.         |
|        |  |                    | - Total                     |                |                 |               | \$0.00        |  |
|        | Material - Total                           |                    |                             |                |                 |               | \$0.00        |  |
| 1190 - |  |                    |                             |                |                 |               | \$0.00        |  |
| 1200   | MISC. MSD Standard 60" Manhole             | Material           |                             | 3              | Aug 17,<br>2020 | SYSTEM        | (\$5,610.00)  |  |
|        |  |                    |                             | 3              | Aug 17,<br>2020 | SYSTEM        | \$5,610.00    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.          |
|        |  |                    |                             | 4              | Sep 2,<br>2020  | SYSTEM        | (\$5,610.00)  |  |
|        |  |                    |                             | 4              | Sep 2,<br>2020  | SYSTEM        | \$5,610.00    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.          |
|        |  |                    |                             | 5              | Sep 16,         | SYSTEM        | (\$5,610.00)  |  |

Revision 4/1/2020 Page 30 of 45



| Line   | Description  | Adjustment | Other              | Est.   | Created         | Created         | Amount        | Remarks   |  |
|--------|--|------------|--------------------|--------|-----------------|-----------------|---------------|---|--|
| 20     | Soosii,piidii  | Туре       | Adjustment<br>Type | Number | Date            | Ву              | , anount      | · Gualité   |  |
| 1200   | MISC. MSD Standard 60" Manhole                             | Material   |                    | 5      | Sep 16,<br>2020 | SYSTEM          | \$5,610.00    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.          |  |
|        |  |            |                    | 6      | Oct 1,<br>2020  | SYSTEM          | (\$10,710.00) |   |  |
|        |  |            |                    | 6      | Oct 1,<br>2020  | SYSTEM          | \$10,710.00   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 30 on the current Payment Estimate.          |  |
|        |  |            | - Total            | 7      | Oct 16,<br>2020 | SYSTEM          | (\$10,710.00) |   |  |
|        |  |            |                    | 7      | Oct 16,<br>2020 | SYSTEM          | \$10,710.00   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.          |  |
|        |  |            |                    |        |                 |                 | \$0.00        |   |  |
|        | Material - Total   |            |                    |        |                 |                 | \$0.00        |   |  |
| 1200 - | - Total  |            |                    |        |                 |                 | \$0.00        |   |  |
| 1210   | MISC. MSD Standard Line 48" Manhole                        | Material   |                    | 6      | Oct 1,<br>2020  | SYSTEM          | (\$3,850.00)  |   |  |
|        |  |            |                    |        | 6               | Oct 1,<br>2020  | SYSTEM        | \$3,850.00  | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate. |
|        |  |            |                    |        | 7               | Oct 16,<br>2020 | SYSTEM        | (\$12,950.00)   |  |
|        |  |            |                    | 7      | Oct 16,<br>2020 | SYSTEM          | \$12,950.00   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.          |  |
|        |  |            |                    | 12     | Jan 4,<br>2021  | SYSTEM          | (\$1,750.00)  |   |  |
|        |  |            |                    | 12     | Jan 4,<br>2021  | SYSTEM          | \$1,750.00    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.         |  |
|        |  |            |                    | 13     | Jan 19,<br>2021 | SYSTEM          | (\$1,750.00)  |   |  |
|        |  |            |                    | 13     | Jan 19,<br>2021 | SYSTEM          | \$1,750.00    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schlag1 overridding Payment Estimate Exception 26 on the current Payment Estimate.         |  |
|        |  |            |                    | 14     | Feb 2,<br>2021  | SYSTEM          | (\$1,750.00)  |   |  |
|        |  |            |                    | 14     | Feb 2,<br>2021  | SYSTEM          | \$1,750.00    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hillt5 overridding Payment Estimate Exception 53 on the current Payment Estimate.          |  |
|        |  |            |                    | 15     | Feb 16,<br>2021 | SYSTEM          | (\$1,750.00)  |   |  |
|        |  |            |                    | 15     | Feb 16,<br>2021 | SYSTEM          | \$1,750.00    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schlag1 overridding Payment Estimate Exception 52 on the current Payment Estimate.         |  |
|        |  |            | - Total            |        |                 |                 | \$0.00        |   |  |
|        | Material - Total   |            |                    |        |                 |                 | \$0.00        |   |  |
|        | - Total  |            |                    |        | 0.1.            | 0)/0==:         | \$0.00        |   |  |
| 1220   | 15 IN. OR ALLOWED SUBSTITUTE<br>GROUP A FLARED END SECTION | Material   |                    | 6      | Oct 1,<br>2020  | SYSTEM          | (\$800.00)    |   |  |
|        |  |            |                    | 6      | Oct 1,<br>2020  | SYSTEM          | \$800.00      | This adjustment offsets the original system-generated Overrun<br>Payment Estimate Item Adjustment (0017) due to user kloepj1<br>overridding Payment Estimate Exception 31 on the current Payment<br>Estimate. |  |
|        |  |            |                    | 7      | Oct 16,<br>2020 | SYSTEM          | (\$1,600.00)  |   |  |
|        |  |            |                    | 7      | Oct 16,<br>2020 | SYSTEM          | \$1,600.00    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 34 on the current Payment                    |  |

Revision 4/1/2020 Page 31 of 45



| Line | Description                  | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By | Amount          | Remarks   |              |  |
|------|------------------------------|--------------------|-----------------------------|----------------|-----------------|---------------|-----------------|---|--------------|--|
| 1220 | 15 IN. OR ALLOWED SUBSTITUTE | Material           | Type                        |                |                 |               |                 | Estimate.   |              |  |
| 1220 | GROUP A FLARED END SECTION   | .Jatonai           |                             | 8              | Nov 2,          | SYSTEM        | (\$1,600.00)    |   |              |  |
|      |                              |                    |                             |                | 2020            | J. J. LIVI    | (\$ 1,000.00)   |   |              |  |
|      |                              |                    |                             | 8              | Nov 2,<br>2020  | SYSTEM        | \$1,600.00      | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user hillt5 overridding Payment Estimate Exception 29 on the current Payment Estimate.           |              |  |
|      |                              |                    |                             | 9              | Nov 16,<br>2020 | SYSTEM        | (\$1,600.00)    |   |              |  |
|      |                              |                    |                             | 9              | Nov 16,<br>2020 | SYSTEM        | \$1,600.00      | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user hillt5 overridding Payment Estimate Exception 30 on the current Payment Estimate.           |              |  |
|      |                              |                    |                             | 10             | Dec 2,<br>2020  | SYSTEM        | (\$1,600.00)    |   |              |  |
|      |                              |                    |                             | 10             | Dec 2,<br>2020  | SYSTEM        | \$1,600.00      | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user kloepj1 overridding Payment Estimate Exception 30 on the current Payment Estimate.          |              |  |
|      |                              |                    |                             | 11             | Dec 16,<br>2020 | SYSTEM        | (\$1,600.00)    |   |              |  |
|      |                              |                    |                             | 11             | Dec 16,<br>2020 | SYSTEM        | \$1,600.00      | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user schlag1 overridding Payment Estimate Exception 28 on the current Payment Estimate.          |              |  |
|      |                              |                    |                             | 12             | Jan 4,<br>2021  | SYSTEM        | (\$1,600.00)    |   |              |  |
|      |                              |                    |                             | 12             | Jan 4,<br>2021  | SYSTEM        | \$1,600.00      | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kloepj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.         |              |  |
|      |                              |                    |                             |                |                 | 13            | Jan 19,<br>2021 | SYSTEM  | (\$1,600.00) |  |
|      |                              |                    |                             | 13             | Jan 19,<br>2021 | SYSTEM        | \$1,600.00      | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schlag1 overridding Payment Estimate Exception 28 on the current Payment Estimate.         |              |  |
|      |                              |                    | - Total                     |                |                 |               | \$0.00          |   |              |  |
|      | Material - Total             |                    |                             |                |                 |               | \$0.00          |   |              |  |
|      | - Total                      |                    |                             |                |                 |               | \$0.00          |   |              |  |
| 1290 | ROCK DITCH CHECK             | Material           |                             | 4              | Sep 2,<br>2020  | SYSTEM        | (\$252.00)      |   |              |  |
|      |                              |                    |                             | 4              | Sep 2,<br>2020  | SYSTEM        | \$252.00        | This adjustment offsets the original system-generated Overrun<br>Payment Estimate Item Adjustment (0017) due to user kloepj1<br>overridding Payment Estimate Exception 10 on the current Payment<br>Estimate. |              |  |
|      |                              |                    |                             | 5              | Sep 16,<br>2020 | SYSTEM        | (\$252.00)      |   |              |  |
|      |                              |                    |                             | 5              | Sep 16,<br>2020 | SYSTEM        | \$252.00        | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.          |              |  |
|      |                              |                    |                             | 6              | Oct 1,<br>2020  | SYSTEM        | (\$252.00)      |   |              |  |
|      |                              |                    |                             | 6              | Oct 1,<br>2020  | SYSTEM        | \$252.00        | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.          |              |  |
|      |                              |                    |                             | 7              | Oct 16,<br>2020 | SYSTEM        | (\$252.00)      |   |              |  |
|      |                              |                    |                             | 7              | Oct 16,<br>2020 | SYSTEM        | \$252.00        | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Exception 35 on the current Payment Estimate.          |              |  |
|      |                              |                    |                             | 8              | Nov 2,<br>2020  | SYSTEM        | (\$252.00)      |   |              |  |
|      |                              |                    |                             | 8              | Nov 2,<br>2020  | SYSTEM        | \$252.00        | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 30 on the current Payment Estimate.           |              |  |

Revision 4/1/2020 Page 32 of 45



| Line | Description      | Adjustment<br>Type | Other<br>Adjustment<br>Type           | Est.<br>Number | Created<br>Date | Created<br>By | Amount                 | Remarks   |            |  |  |  |  |  |  |  |  |  |   |                 |        |              |  |
|------|------------------|--------------------|---------------------------------------|----------------|-----------------|---------------|------------------------|---|------------|--|--|--|--|--|--|--|--|--|---|-----------------|--------|--------------|--|
| 1290 | ROCK DITCH CHECK | Material           | , , , , , , , , , , , , , , , , , , , | 9              | Nov 16,<br>2020 | SYSTEM        | (\$252.00)             |   |            |  |  |  |  |  |  |  |  |  |   |                 |        |              |  |
|      |                  |                    |                                       | 9              | Nov 16,<br>2020 | SYSTEM        | \$252.00               | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 31 on the current Payment Estimate.           |            |  |  |  |  |  |  |  |  |  |   |                 |        |              |  |
|      |                  |                    |                                       | 10             | Dec 2,<br>2020  | SYSTEM        | (\$252.00)             |   |            |  |  |  |  |  |  |  |  |  |   |                 |        |              |  |
|      |                  |                    |                                       | 10             | Dec 2,<br>2020  | SYSTEM        | \$252.00               | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user kloepj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.          |            |  |  |  |  |  |  |  |  |  |   |                 |        |              |  |
|      |                  |                    |                                       | 11             | Dec 16,<br>2020 | SYSTEM        | (\$252.00)             |   |            |  |  |  |  |  |  |  |  |  |   |                 |        |              |  |
|      |                  |                    |                                       | 11             | Dec 16,<br>2020 | SYSTEM        | \$252.00               | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user schlag1 overridding Payment Estimate Exception 29 on the current Payment Estimate.          |            |  |  |  |  |  |  |  |  |  |   |                 |        |              |  |
|      |                  |                    |                                       | 12             | Jan 4,<br>2021  | SYSTEM        | (\$252.00)             |   |            |  |  |  |  |  |  |  |  |  |   |                 |        |              |  |
|      |                  |                    |                                       | 12             | Jan 4,<br>2021  | SYSTEM        | \$252.00               | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user kloepj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.         |            |  |  |  |  |  |  |  |  |  |   |                 |        |              |  |
|      |                  |                    |                                       | 13             | Jan 19,<br>2021 | SYSTEM        | (\$252.00)             |   |            |  |  |  |  |  |  |  |  |  |   |                 |        |              |  |
|      |                  |                    |                                       | 13             | Jan 19,<br>2021 | SYSTEM        | \$252.00               | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schlag1 overridding Payment Estimate Exception 29 on the current Payment Estimate.         |            |  |  |  |  |  |  |  |  |  |   |                 |        |              |  |
|      |                  |                    |                                       | 14             | Feb 2,<br>2021  | SYSTEM        | (\$252.00)             |   |            |  |  |  |  |  |  |  |  |  |   |                 |        |              |  |
|      |                  |                    |                                       | 14             | Feb 2,<br>2021  | SYSTEM        | \$252.00               | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 55 on the current Payment Estimate.          |            |  |  |  |  |  |  |  |  |  |   |                 |        |              |  |
|      |                  |                    |                                       |                |                 | 15            | Feb 16,<br>2021        | SYSTEM  | (\$252.00) |  |  |  |  |  |  |  |  |  |   |                 |        |              |  |
|      |                  |                    |                                       | 15             | Feb 16,<br>2021 | SYSTEM        | \$252.00               | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schlag1 overridding Payment Estimate Exception 54 on the current Payment Estimate.         |            |  |  |  |  |  |  |  |  |  |   |                 |        |              |  |
|      |                  |                    | - Total                               |                |                 |               | \$0.00                 |   |            |  |  |  |  |  |  |  |  |  |   |                 |        |              |  |
|      | Material - Total |                    |                                       |                |                 |               | \$0.00                 |   |            |  |  |  |  |  |  |  |  |  |   |                 |        |              |  |
| 1330 | Total SILT FENCE | Material           |                                       | 4              | Sep 2, 2020     | SYSTEM        | \$0.00<br>(\$4,506.75) |   |            |  |  |  |  |  |  |  |  |  |   |                 |        |              |  |
|      |                  |                    |                                       | 4              | Sep 2,<br>2020  | SYSTEM        | \$4,506.75             | This adjustment offsets the original system-generated Overrun<br>Payment Estimate Item Adjustment (0018) due to user kloepj1<br>overridding Payment Estimate Exception 11 on the current Payment<br>Estimate. |            |  |  |  |  |  |  |  |  |  |   |                 |        |              |  |
|      |                  |                    |                                       |                |                 |               |                        |   |            |  |  |  |  |  |  |  |  |  | 5 | Sep 16,<br>2020 | SYSTEM | (\$4,506.75) |  |
|      |                  |                    |                                       |                |                 |               |                        |   |            |  |  |  |  |  |  |  |  |  |   |                 |        |              |  |
|      |                  |                    |                                       | 6              | Oct 1,<br>2020  | SYSTEM        | (\$4,506.75)           |   |            |  |  |  |  |  |  |  |  |  |   |                 |        |              |  |
|      |                  |                    |                                       | 6              | Oct 1,<br>2020  | SYSTEM        | \$4,506.75             | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.          |            |  |  |  |  |  |  |  |  |  |   |                 |        |              |  |
|      |                  |                    |                                       | 7              | Oct 16,<br>2020 | SYSTEM        | (\$4,506.75)           |   |            |  |  |  |  |  |  |  |  |  |   |                 |        |              |  |
|      |                  |                    |                                       |                |                 | 7             | Oct 16,<br>2020        | SYSTEM  | \$4,506.75 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user kloepj1 overridding Payment Estimate Exception 36 on the current Payment Estimate. |  |  |  |  |  |  |  |  |   |                 |        |              |  |
|      |                  |                    | - Total                               |                |                 |               | \$0.00                 |   |            |  |  |  |  |  |  |  |  |  |   |                 |        |              |  |

Revision 4/1/2020 Page 33 of 45



| Line   | Description                                | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By | Amount         | Remarks  |             |   |        |             |  |  |  |  |  |  |  |    |                 |        |               |  |
|--------|--|--------------------|-----------------------------|----------------|-----------------|---------------|----------------|--|-------------|---|--------|-------------|--|--|--|--|--|--|--|----|-----------------|--------|---------------|--|
| 1330   | Material - Total                           |                    |                             |                |                 |               | \$0.00         |  |             |   |        |             |  |  |  |  |  |  |  |    |                 |        |               |  |
| 1330 - | Total                                      |                    |                             |                |                 |               | \$0.00         |  |             |   |        |             |  |  |  |  |  |  |  |    |                 |        |               |  |
| 1490   | TYPE 5 AGGREGATE FOR BASE (6<br>IN. THICK) | Material           |                             | 5              | Sep 16,<br>2020 | SYSTEM        | (\$12,444.25)  |  |             |   |        |             |  |  |  |  |  |  |  |    |                 |        |               |  |
|        |  |                    |                             | 5              | Sep 16,<br>2020 | SYSTEM        | \$12,444.25    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  |             |   |        |             |  |  |  |  |  |  |  |    |                 |        |               |  |
|        |  |                    |                             | 6              | Oct 1,<br>2020  | SYSTEM        | (\$14,110.85)  |  |             |   |        |             |  |  |  |  |  |  |  |    |                 |        |               |  |
|        |  |                    |                             | 6              | Oct 1,<br>2020  | SYSTEM        | \$14,110.85    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  |             |   |        |             |  |  |  |  |  |  |  |    |                 |        |               |  |
|        |  |                    |                             | 7              | Oct 16,<br>2020 | SYSTEM        | (\$17,094.16)  |  |             |   |        |             |  |  |  |  |  |  |  |    |                 |        |               |  |
|        |  |                    |                             | 7              | Oct 16,<br>2020 | SYSTEM        | \$17,094.16    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  |             |   |        |             |  |  |  |  |  |  |  |    |                 |        |               |  |
|        |  |                    |                             | 8              | Nov 2,<br>2020  | SYSTEM        | (\$17,094.16)  |  |             |   |        |             |  |  |  |  |  |  |  |    |                 |        |               |  |
|        |  |                    |                             | 8              | Nov 2,<br>2020  | SYSTEM        | \$17,094.16    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user hillt5 overridding Payment Estimate Exception 2 on the current Payment Estimate.   |             |   |        |             |  |  |  |  |  |  |  |    |                 |        |               |  |
|        |  |                    |                             | 9              | Nov 16,<br>2020 | SYSTEM        | (\$17,094.16)  |  |             |   |        |             |  |  |  |  |  |  |  |    |                 |        |               |  |
|        |  |                    |                             | 9              | Nov 16,<br>2020 | SYSTEM        | \$17,094.16    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user hillt5 overridding Payment Estimate Exception 2 on the current Payment Estimate.   |             |   |        |             |  |  |  |  |  |  |  |    |                 |        |               |  |
|        |  |                    |                             | 10             | Dec 2,<br>2020  | SYSTEM        | (\$17,094.16)  |  |             |   |        |             |  |  |  |  |  |  |  |    |                 |        |               |  |
|        |  |                    |                             | 10             | Dec 2,<br>2020  | SYSTEM        | \$17,094.16    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  |             |   |        |             |  |  |  |  |  |  |  |    |                 |        |               |  |
|        |  |                    |                             | 11             | Dec 16,<br>2020 | SYSTEM        | (\$17,094.16)  |  |             |   |        |             |  |  |  |  |  |  |  |    |                 |        |               |  |
|        |  |                    |                             | 11             | Dec 16,<br>2020 | SYSTEM        | \$17,094.16    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user schlag1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  |             |   |        |             |  |  |  |  |  |  |  |    |                 |        |               |  |
|        |  |                    |                             | 12             | Jan 4,<br>2021  | SYSTEM        | (\$17,094.16)  |  |             |   |        |             |  |  |  |  |  |  |  |    |                 |        |               |  |
|        |  |                    |                             | 12             | Jan 4,<br>2021  | SYSTEM        | \$17,094.16    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user kloepj1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |             |   |        |             |  |  |  |  |  |  |  |    |                 |        |               |  |
|        |  |                    |                             |                |                 |               |                |  |             |   |        |             |  |  |  |  |  |  |  | 13 | Jan 19,<br>2021 | SYSTEM | (\$17,094.16) |  |
|        |  |                    |                             |                |                 |               |                |  | 13          | Jan 19,<br>2021   | SYSTEM | \$17,094.16 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schlag1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |  |  |  |  |  |  |    |                 |        |               |  |
|        |  |                    |                             | 14             | Feb 2,<br>2021  | SYSTEM        | (\$17,094.16)  |  |             |   |        |             |  |  |  |  |  |  |  |    |                 |        |               |  |
|        |  |                    |                             |                |                 | 14            | Feb 2,<br>2021 | SYSTEM   | \$17,094.16 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hillt5 overridding Payment Estimate Exception 2 on the current Payment Estimate. |        |             |  |  |  |  |  |  |  |    |                 |        |               |  |
|        |  |                    |                             | 15             | Feb 16,<br>2021 | SYSTEM        | (\$17,094.16)  |  |             |   |        |             |  |  |  |  |  |  |  |    |                 |        |               |  |
|        |  |                    |                             | 15             | Feb 16,<br>2021 | SYSTEM        | \$17,094.16    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schlag1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |             |   |        |             |  |  |  |  |  |  |  |    |                 |        |               |  |
|        |  |                    |                             | 16             | Mar 2,<br>2021  | SYSTEM        | (\$17,094.16)  |  |             |   |        |             |  |  |  |  |  |  |  |    |                 |        |               |  |

Revision 4/1/2020 Page 34 of 45



| Line   | Description  | Adjustment<br>Type | Other<br>Adjustment | Est.<br>Number | Created<br>Date | Created<br>By | Amount         | Remarks   |             |   |   |  |    |                |        |                 |        |             |  |
|--------|--|--------------------|---------------------|----------------|-----------------|---------------|----------------|---|-------------|---|---|--|----|----------------|--------|-----------------|--------|-------------|--|
|        |  |                    | Type                |                |                 |               |                |   |             |   |   |  |    |                |        |                 |        |             |  |
| 1490   | TYPE 5 AGGREGATE FOR BASE (6<br>IN. THICK)                 | Material           |                     | 16             | Mar 2,<br>2021  | SYSTEM        | \$17,094.16    | This adjustment offsets the original system-generated Material<br>Payment Estimate Item Adjustment (0015) due to user kloepj1<br>overridding Payment Estimate Exception 2 on the current Payment<br>Estimate. |             |   |   |  |    |                |        |                 |        |             |  |
|        |  |                    | - Total             |                |                 |               | \$0.00         |   |             |   |   |  |    |                |        |                 |        |             |  |
|        | Material - Total   |                    |                     |                |                 |               | \$0.00         |   |             |   |   |  |    |                |        |                 |        |             |  |
|        | TYPE 5 AGGREGATE FOR BASE (6<br>IN. THICK)                 | Price              |                     | 5              | Sep 16,<br>2020 | SYSTEM        | \$167.33       | Reference Item Price Adjustment Index Adjustment Type applied is FUEL   |             |   |   |  |    |                |        |                 |        |             |  |
|        |  |                    |                     | 6              | Oct 1,<br>2020  | SYSTEM        | \$22.41        | Reference Item Price Adjustment Index Adjustment Type applied is FUEL   |             |   |   |  |    |                |        |                 |        |             |  |
|        |  |                    |                     | 7              | Oct 16,<br>2020 | SYSTEM        | \$33.78        | Reference Item Price Adjustment Index Adjustment Type applied is FUEL   |             |   |   |  |    |                |        |                 |        |             |  |
|        |  |                    | - Total             |                |                 |               | \$223.52       |   |             |   |   |  |    |                |        |                 |        |             |  |
|        | Price - Total  |                    |                     |                |                 |               | \$223.52       |   |             |   |   |  |    |                |        |                 |        |             |  |
| 1490 - | Total  |                    |                     |                |                 |               | \$223.52       |   |             |   |   |  |    |                |        |                 |        |             |  |
| 1510   | CONCRETE PAVEMENT (9 IN. NON-<br>REINFORCED 15 FT. JOINTS) | Material           |                     | 5              | Sep 16,<br>2020 | SYSTEM        | (\$49,717.80)  |   |             |   |   |  |    |                |        |                 |        |             |  |
|        |  |                    |                     | 5              | Sep 16,<br>2020 | SYSTEM        | \$49,717.80    | This adjustment offsets the original system-generated Overrun<br>Payment Estimate Item Adjustment (0024) due to user kloepj1<br>overridding Payment Estimate Exception 3 on the current Payment<br>Estimate.  |             |   |   |  |    |                |        |                 |        |             |  |
|        |  |                    |                     | 6              | Oct 1,<br>2020  | SYSTEM        | (\$63,768.60)  |   |             |   |   |  |    |                |        |                 |        |             |  |
|        |  |                    |                     |                |                 | 6             | Oct 1,<br>2020 | SYSTEM  | \$63,768.60 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user kloepj1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |   |  |    |                |        |                 |        |             |  |
|        |  |                    |                     |                |                 |               | 7              | Oct 16,<br>2020   | SYSTEM      | (\$68,002.20)   |   |  |    |                |        |                 |        |             |  |
|        |  |                    |                     |                |                 |               | 7              | Oct 16,<br>2020   | SYSTEM      | \$68,002.20   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user kloepj1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |  |    |                |        |                 |        |             |  |
|        |  |                    |                     | 8              | Nov 2,<br>2020  | SYSTEM        | (\$68,002.20)  |   |             |   |   |  |    |                |        |                 |        |             |  |
|        |  |                    |                     |                |                 |               | 8              | Nov 2,<br>2020  | SYSTEM      | \$68,002.20   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate.  |  |    |                |        |                 |        |             |  |
|        |  |                    |                     | 9              | Nov 16,<br>2020 | SYSTEM        | (\$68,002.20)  |   |             |   |   |  |    |                |        |                 |        |             |  |
|        |  |                    |                     | 9              | Nov 16,<br>2020 | SYSTEM        | \$68,002.20    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate.            |             |   |   |  |    |                |        |                 |        |             |  |
|        |  |                    |                     |                |                 |               |                |   |             |   |   |  | 10 | Dec 2,<br>2020 | SYSTEM | (\$68,002.20)   |        |             |  |
|        |  |                    |                     | 10             | Dec 2,<br>2020  | SYSTEM        | \$68,002.20    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.           |             |   |   |  |    |                |        |                 |        |             |  |
|        |  |                    |                     | 11             | Dec 16,<br>2020 | SYSTEM        | (\$68,002.20)  |   |             |   |   |  |    |                |        |                 |        |             |  |
|        |  |                    |                     | 11             | Dec 16,<br>2020 | SYSTEM        | \$68,002.20    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user schlag1 overridding Payment Estimate Exception 3 on the current Payment Estimate.           |             |   |   |  |    |                |        |                 |        |             |  |
|        |  |                    |                     | 12             | Jan 4,<br>2021  | SYSTEM        | (\$68,002.20)  |   |             |   |   |  |    |                |        |                 |        |             |  |
|        |  |                    |                     | 12             | Jan 4,<br>2021  | SYSTEM        | \$68,002.20    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.          |             |   |   |  |    |                |        |                 |        |             |  |
|        |  |                    |                     | 13             | Jan 19,<br>2021 | SYSTEM        | (\$68,002.20)  |   |             |   |   |  |    |                |        |                 |        |             |  |
|        |  |                    |                     |                |                 |               |                |   |             |   |   |  |    |                | 13     | Jan 19,<br>2021 | SYSTEM | \$68,002.20 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schlag1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |

Revision 4/1/2020 Page 35 of 45



| Line |  |                    |                             |  |  |  |   |  |  |  |  |  |  |  |  |  |
|------|--|--------------------|-----------------------------|--|--|--|---|--|--|--|--|--|--|--|--|--|
|      | Description  | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number                         | Created<br>Date  | Created<br>By                                    | Amount  | Remarks  |  |  |  |  |  |  |  |  |
| 1510 | CONCRETE PAVEMENT (9 IN. NON-<br>REINFORCED 15 FT. JOINTS) | Material           |                             | 14                                     | Feb 2,<br>2021   | SYSTEM   | (\$68,002.20)   |  |  |  |  |  |  |  |  |  |
|      |  |                    |                             | 14                                     | Feb 2,<br>2021   | SYSTEM   | \$68,002.20   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate.  |  |  |  |  |  |  |  |  |
|      |  |                    |                             | 15                                     | Feb 16,<br>2021  | SYSTEM   | (\$68,002.20)   |  |  |  |  |  |  |  |  |  |
|      |  |                    |                             | 15                                     | Feb 16,<br>2021  | SYSTEM   | \$68,002.20   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schlag1 overridding Payment Estimate Exception 3 on the current Payment Estimate.   |  |  |  |  |  |  |  |  |
|      |  |                    |                             | 16                                     | Mar 2,<br>2021   | SYSTEM   | (\$68,002.20)   |  |  |  |  |  |  |  |  |  |
|      |  |                    |                             | 16                                     | Mar 2,<br>2021   | SYSTEM   | \$68,002.20   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.   |  |  |  |  |  |  |  |  |
|      |  |                    | - Total                     |  |  |  | \$0.00  |  |  |  |  |  |  |  |  |  |
|      | Material - Total   |                    |                             |  |  |  | \$0.00  |  |  |  |  |  |  |  |  |  |
|      | CONCRETE PAVEMENT (9 IN. NON-<br>REINFORCED 15 FT. JOINTS) | Price              |                             | 5                                      | Sep 16,<br>2020  | SYSTEM   | \$230.91  | Reference Item Price Adjustment Index Adjustment Type applied is FUEL  |  |  |  |  |  |  |  |  |
|      |  |                    |                             | 6                                      | Oct 1,<br>2020   | SYSTEM   | \$65.26   | Reference Item Price Adjustment Index Adjustment Type applied is FUEL  |  |  |  |  |  |  |  |  |
|      |  |                    |                             | 7                                      | Oct 16,<br>2020  | SYSTEM   | \$16.56   | Reference Item Price Adjustment Index Adjustment Type applied is FUEL  |  |  |  |  |  |  |  |  |
|      |  |                    | - Total                     |  |  |  | \$312.73  |  |  |  |  |  |  |  |  |  |
|      | Price - Total  |                    |                             |  |  |  | \$312.73  |  |  |  |  |  |  |  |  |  |
| 1510 | - Total  |                    |                             |  |  |  | \$312.73  |  |  |  |  |  |  |  |  |  |
| 1550 | TYPE A2 SHOULDER   | Material           |                             | 6                                      | Oct 1,<br>2020   | SYSTEM   | (\$14,224.00)   |  |  |  |  |  |  |  |  |  |
|      |  |                    |                             | 6                                      | Oct 1,<br>2020   | SYSTEM   | \$14,224.00   | This adjustment offsets the original system-generated Overrun<br>Payment Estimate Item Adjustment (0006) due to user kloepj1<br>overridding Payment Estimate Exception 10 on the current Payment<br>Estimate.  |  |  |  |  |  |  |  |  |
|      |  |                    |                             |  |  |  |   |  |  |  |  |  |  |  |  |  |
|      |  |                    |                             | 7                                      | Oct 16,<br>2020  | SYSTEM   | (\$30,287.95)   |  |  |  |  |  |  |  |  |  |
|      |  |                    |                             | 7                                      |  | SYSTEM   | (\$30,287.95)<br>\$30,287.95  | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.   |  |  |  |  |  |  |  |  |
|      |  |                    |                             |  | 2020<br>Oct 16,  |  |   | Payment Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment   |  |  |  |  |  |  |  |  |
|      |  |                    |                             | 7                                      | 2020<br>Oct 16,<br>2020<br>Nov 2,  | SYSTEM   | \$30,287.95   | Payment Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment   |  |  |  |  |  |  |  |  |
|      |  |                    |                             | 7                                      | 2020<br>Oct 16,<br>2020<br>Nov 2,<br>2020<br>Nov 2,  | SYSTEM   | \$30,287.95<br>(\$30,287.95)  | Payment Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user hillt5 overridding Payment Estimate Exception 8 on the current Payment   |  |  |  |  |  |  |  |  |
|      |  |                    |                             | 7 8 8                                  | 2020<br>Oct 16,<br>2020<br>Nov 2,<br>2020<br>Nov 2,<br>2020  | SYSTEM SYSTEM SYSTEM                             | \$30,287.95<br>(\$30,287.95)<br>\$30,287.95   | Payment Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user hillt5 overridding Payment Estimate Exception 8 on the current Payment   |  |  |  |  |  |  |  |  |
|      |  |                    |                             | 7 8 8 8 9                              | 2020<br>Oct 16,<br>2020<br>Nov 2,<br>2020<br>Nov 2,<br>2020<br>Nov 16,<br>2020                       | SYSTEM SYSTEM SYSTEM                             | \$30,287.95<br>(\$30,287.95)<br>\$30,287.95<br>(\$30,287.95)  | Payment Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user hillt5 overridding Payment Estimate Exception 8 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user hillt5 overridding Payment Estimate Exception 8 on the current Payment   |  |  |  |  |  |  |  |  |
|      |  |                    |                             | 7<br>8<br>8<br>8<br>9<br>9             | 2020 Oct 16, 2020 Nov 2, 2020 Nov 2, 2020 Nov 16, 2020 Document 16, 2020 Dec 2,                      | SYSTEM SYSTEM SYSTEM SYSTEM                      | \$30,287.95<br>(\$30,287.95)<br>\$30,287.95<br>(\$30,287.95)<br>\$30,287.95                                 | Payment Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user hillt5 overridding Payment Estimate Exception 8 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user hillt5 overridding Payment Estimate Exception 8 on the current Payment   |  |  |  |  |  |  |  |  |
|      |  |                    |                             | 7<br>8<br>8<br>8<br>9<br>9             | 2020 Oct 16, 2020 Nov 2, 2020 Nov 16, 2020  Nov 16, 2020 Dec 2, 2020 Dec 2, 2020                     | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM               | \$30,287.95<br>(\$30,287.95)<br>\$30,287.95<br>(\$30,287.95)<br>\$30,287.95                                 | Payment Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user hillt5 overridding Payment Estimate Exception 8 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user hillt5 overridding Payment Estimate Exception 8 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user kloepj1 overridding Payment Estimate Exception 8 on the current Payment  |  |  |  |  |  |  |  |  |
|      |  |                    |                             | 7<br>8<br>8<br>8<br>9<br>9<br>10       | 2020 Oct 16, 2020 Nov 2, 2020 Nov 16, 2020  Nov 16, 2020  Dec 2, 2020  Dec 2, 2020  Dec 16, 16, 2020 | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM        | \$30,287.95<br>(\$30,287.95)<br>\$30,287.95<br>(\$30,287.95)<br>\$30,287.95<br>(\$30,287.95)                | Payment Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user hillt5 overridding Payment Estimate Exception 8 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user hillt5 overridding Payment Estimate Exception 8 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user kloepj1 overridding Payment Estimate Exception 8 on the current Payment  |  |  |  |  |  |  |  |  |
|      |  |                    |                             | 7<br>8<br>8<br>8<br>9<br>9<br>10<br>10 | 2020 Oct 16, 2020 Nov 2, 2020 Nov 16, 2020 Nov 16, 2020 Dec 2, 2020 Dec 16, 2020 Dec 16, 2020        | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$30,287.95<br>(\$30,287.95)<br>\$30,287.95<br>(\$30,287.95)<br>\$30,287.95<br>(\$30,287.95)<br>\$30,287.95 | Payment Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user hillt5 overridding Payment Estimate Exception 8 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user hillt5 overridding Payment Estimate Exception 8 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user kloepj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user schlag1 overridding Payment Estimate Item Adjustment (0011) due to user schlag1 overridding Payment Estimate Exception 8 on the current Payment |  |  |  |  |  |  |  |  |

Revision 4/1/2020 Page 36 of 45



| Line           | Description                                   | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By  | Amount  | Remarks   |   |                |        |               |  |   |                |                 |            |   |  |        |                 |        |            |  |
|----------------|---|--------------------|-----------------------------|----------------|-----------------|----------------|---|---|---|----------------|--------|---------------|--|---|----------------|-----------------|------------|---|--|--------|-----------------|--------|------------|--|
| 1550           | TYPE A2 SHOULDER                              | Material           |                             |                |                 |                |   | overridding Payment Estimate Exception 9 on the current Payment Estimate.   |   |                |        |               |  |   |                |                 |            |   |  |        |                 |        |            |  |
|                |   |                    |                             | 13             | Jan 19,<br>2021 | SYSTEM         | (\$30,287.95)   | Eduniate.   |   |                |        |               |  |   |                |                 |            |   |  |        |                 |        |            |  |
|                |   |                    |                             | 13             | Jan 19,<br>2021 | SYSTEM         | \$30,287.95   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schlag1 overridding Payment Estimate Exception 8 on the current Payment Estimate.          |   |                |        |               |  |   |                |                 |            |   |  |        |                 |        |            |  |
|                |   |                    |                             | 14             | Feb 2,<br>2021  | SYSTEM         | (\$30,287.95)   |   |   |                |        |               |  |   |                |                 |            |   |  |        |                 |        |            |  |
|                |   |                    |                             |                | 14              | Feb 2,<br>2021 | SYSTEM  | \$30,287.95   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user hillt5 overridding Payment Estimate Exception 8 on the current Payment Estimate. |                |        |               |  |   |                |                 |            |   |  |        |                 |        |            |  |
|                |   |                    |                             | 15             | Feb 16,<br>2021 | SYSTEM         | (\$30,287.95)   |   |   |                |        |               |  |   |                |                 |            |   |  |        |                 |        |            |  |
|                |   |                    |                             | 15             | Feb 16,<br>2021 | SYSTEM         | \$30,287.95   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schlag1 overridding Payment Estimate Exception 8 on the current Payment Estimate.          |   |                |        |               |  |   |                |                 |            |   |  |        |                 |        |            |  |
|                |   |                    |                             |                |                 |                |   |   | 16  | Mar 2,<br>2021 | SYSTEM | (\$30,287.95) |  |   |                |                 |            |   |  |        |                 |        |            |  |
|                |   |                    |                             | 16             | Mar 2,<br>2021  | SYSTEM         | \$30,287.95   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.          |   |                |        |               |  |   |                |                 |            |   |  |        |                 |        |            |  |
|                |   |                    | - Total                     |                |                 |                | \$0.00  |   |   |                |        |               |  |   |                |                 |            |   |  |        |                 |        |            |  |
|                | Material - Total                              |                    |                             |                |                 |                | \$0.00  |   |   |                |        |               |  |   |                |                 |            |   |  |        |                 |        |            |  |
| 1550 -<br>1560 |   | Material           |                             | 6              | Oct 1,          | SYSTEM         | \$0.00<br>(\$3,375.00)  |   |   |                |        |               |  |   |                |                 |            |   |  |        |                 |        |            |  |
| 1560           | INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A | Material           |                             |                | 2020            |                |   |   |   |                |        |               |  |   |                |                 |            |   |  |        |                 |        |            |  |
|                |   |                    |                             | 6              | Oct 1,<br>2020  | SYSTEM         | \$3,375.00  | This adjustment offsets the original system-generated Overrun<br>Payment Estimate Item Adjustment (0007) due to user kloepj1<br>overridding Payment Estimate Exception 12 on the current Payment<br>Estimate. |   |                |        |               |  |   |                |                 |            |   |  |        |                 |        |            |  |
|                |   |                    |                             | 7              | Oct 16,<br>2020 | SYSTEM         | (\$3,375.00)  |   |   |                |        |               |  |   |                |                 |            |   |  |        |                 |        |            |  |
|                |   |                    |                             | 7              | Oct 16,<br>2020 | SYSTEM         | \$3,375.00  | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user kloepj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.          |   |                |        |               |  |   |                |                 |            |   |  |        |                 |        |            |  |
|                |   |                    |                             |                |                 |                |   |   |   |                |        |               |  |   |                |                 |            | 8   | Nov 2,<br>2020   | SYSTEM | (\$3,375.00)    |        |            |  |
|                |   |                    |                             |                |                 |                |   |   |   |                |        |               |  | 8 | Nov 2,<br>2020 | SYSTEM          | \$3,375.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 10 on the current Payment Estimate. |  |        |                 |        |            |  |
|                |   |                    |                             | 9              | Nov 16,<br>2020 | SYSTEM         | (\$3,375.00)  |   |   |                |        |               |  |   |                |                 |            |   |  |        |                 |        |            |  |
|                |   |                    |                             |                |                 |                |   |   |   |                |        |               |  |   |                |                 |            |   |  | 9      | Nov 16,<br>2020 | SYSTEM | \$3,375.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 10 on the current Payment Estimate.  |
|                |   |                    |                             | 10             | Dec 2,<br>2020  | SYSTEM         | (\$3,375.00)  |   |   |                |        |               |  |   |                |                 |            |   |  |        |                 |        |            |  |
|                |   |                    |                             |                |                 |                |   |   |   |                |        |               |  |   |                |                 |            |   |  | 10     | Dec 2,<br>2020  | SYSTEM | \$3,375.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate. |
|                |   |                    |                             | 11             | Dec 16,<br>2020 | SYSTEM         | (\$3,375.00)  |   |   |                |        |               |  |   |                |                 |            |   |  |        |                 |        |            |  |
|                |   |                    |                             |                |                 |                |   |   |   |                |        |               |  |   | 11             | Dec 16,<br>2020 | SYSTEM     | \$3,375.00  | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user schlag1 overridding Payment Estimate Exception 10 on the current Payment Estimate. |        |                 |        |            |  |
|                |   |                    |                             |                |                 |                |   |   |   |                |        |               |  |   |                |                 |            |   |  |        |                 |        | -          | 12   |
|                |   |                    | 12                          | Jan 4,<br>2021 | SYSTEM          | \$3,375.00     | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 11 on the current Payment |   |   |                |        |               |  |   |                |                 |            |   |  |        |                 |        |            |  |

Revision 4/1/2020 Page 37 of 45



| Line   | Description  | Adjustment                | Other              | Est.   | Created         | Created | Amount       | Remarks   |
|--------|--|---------------------------|--------------------|--------|-----------------|---------|--------------|---|
|        | ·  | Туре                      | Adjustment<br>Type | Number | Date            | Ву      |              |   |
| 1560   | INTEGRAL CURB (6 IN. HEIGHT AND                                | Material                  |                    |        |                 |         |              | Estimate.   |
|        | UNDER) TYPE A  |                           |                    | 13     | Jan 19,<br>2021 | SYSTEM  | (\$3,375.00) |   |
|        |  |                           |                    | 13     | Jan 19,<br>2021 | SYSTEM  | \$3,375.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schlag1 overridding Payment Estimate Exception 10 on the current Payment Estimate. |
|        |  |                           |                    | 14     | Feb 2,<br>2021  | SYSTEM  | (\$3,375.00) |   |
|        |  |                           |                    | 14     | Feb 2,<br>2021  | SYSTEM  | \$3,375.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user hillt5 overridding Payment Estimate Exception 10 on the current Payment Estimate.  |
|        |  |                           |                    | 15     | Feb 16,<br>2021 | SYSTEM  | (\$3,375.00) |   |
|        |  |                           |                    | 15     | Feb 16,<br>2021 | SYSTEM  | \$3,375.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schlag1 overridding Payment Estimate Exception 10 on the current Payment Estimate. |
|        |  |                           |                    | 16     | Mar 2,<br>2021  | SYSTEM  | (\$3,375.00) |   |
|        |  |                           |                    | 16     | Mar 2,<br>2021  | SYSTEM  | \$3,375.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 13 on the current Payment Estimate. |
|        |  |                           | - Total            |        |                 |         | \$0.00       |   |
|        | Material - Total   |                           |                    |        |                 |         | \$0.00       |   |
| 1560 - | · Total  |                           |                    |        |                 |         | \$0.00       |   |
| 1570   | MGS GUARDRAIL  | Construction<br>Stockpile |                    | 3      | Aug 17,<br>2020 | SYSTEM  | \$38,968.86  | Payment Estimate Item Adjustment generated Stockpile Transaction  |
|        |  |                           |                    | 16     | Mar 2,<br>2021  | SYSTEM  | (\$4,220.86) | Payment Estimate Item Adjustment generated Stockpile Transaction  |
|        |  |                           | - Total            |        |                 |         | \$34,748.00  |   |
|        | Construction Stockpile - Total                                 |                           |                    |        |                 |         | \$34,748.00  |   |
| 1570 - | · Total  |                           |                    |        |                 |         | \$34,748.00  |   |
| 1580   | MGS BRIDGE APPROACH<br>TRANSITION SECTION (EXTENDED<br>CURB)   | Construction<br>Stockpile |                    | 3      | Aug 17,<br>2020 | SYSTEM  | \$3,016.00   | Payment Estimate Item Adjustment generated Stockpile Transaction  |
|        |  |                           | - Total            |        |                 |         | \$3,016.00   |   |
|        | Construction Stockpile - Total                                 |                           |                    |        |                 |         | \$3,016.00   |   |
| 1580 - | · Total  |                           |                    |        |                 |         | \$3,016.00   |   |
| 1590   | MGS BRIDGE APPROACH<br>TRANSITION SECTION (REGULAR/NO<br>CURB) |                           |                    | 3      | Aug 17,<br>2020 | SYSTEM  | \$2,920.00   | Payment Estimate Item Adjustment generated Stockpile Transaction  |
|        |  |                           | - Total            |        |                 |         | \$2,920.00   |   |
|        | Construction Stockpile - Total                                 |                           |                    |        |                 |         | \$2,920.00   |   |
| 1590 - | Total  |                           |                    |        |                 |         | \$2,920.00   |   |
| 1600   | MGS VERTICAL CONCRETE BARRIER TRANSITION                       | Construction<br>Stockpile |                    | 3      | Aug 17,<br>2020 | SYSTEM  | \$13,915.00  | Payment Estimate Item Adjustment generated Stockpile Transaction  |
|        |  |                           |                    | 16     | Mar 2,<br>2021  | SYSTEM  | (\$3,795.00) | Payment Estimate Item Adjustment generated Stockpile Transaction  |
|        |  |                           | - Total            |        |                 |         | \$10,120.00  |   |
|        | Construction Stockpile - Total                                 |                           |                    |        |                 |         | \$10,120.00  |   |
| 1600 - | · Total  |                           |                    |        |                 |         | \$10,120.00  |   |
| 1610   | MGS END ANCHOR   | Construction<br>Stockpile |                    | 3      | Aug 17,<br>2020 | SYSTEM  | \$4,256.00   | Payment Estimate Item Adjustment generated Stockpile Transaction  |
|        |  |                           |                    | 16     | Mar 2,<br>2021  | SYSTEM  | (\$532.00)   | Payment Estimate Item Adjustment generated Stockpile Transaction  |
|        |  |                           | - Total            |        |                 |         | \$3,724.00   |   |
|        | Construction Stockpile - Total                                 |                           |                    |        |                 |         | \$3,724.00   |   |
| 1610 - | Total  |                           |                    |        |                 |         | \$3,724.00   |   |
| _      |  |                           |                    |        |                 |         |              |   |

Revision 4/1/2020 Page 38 of 45



| Line   | Description                                   | Adjustment<br>Type        | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By   | Amount         | Remarks   |  |  |        |                 |                 |                |   |  |                |        |             |  |  |  |  |  |  |  |  |   |                 |        |             |  |
|--------|---|---------------------------|-----------------------------|----------------|-----------------|-----------------|----------------|---|--|--|--------|-----------------|-----------------|----------------|---|--|----------------|--------|-------------|--|--|--|--|--|--|--|--|---|-----------------|--------|-------------|--|
| 1620   | TYPE A CRASHWORTHY END<br>TERMINAL (MASH)     | Construction<br>Stockpile |                             | 16             | Mar 2,<br>2021  | SYSTEM          | (\$4,473.00)   | Payment Estimate Item Adjustment generated Stockpile Transaction  |  |  |        |                 |                 |                |   |  |                |        |             |  |  |  |  |  |  |  |  |   |                 |        |             |  |
|        |   |                           | - Total                     |                |                 |                 | \$13,419.00    |   |  |  |        |                 |                 |                |   |  |                |        |             |  |  |  |  |  |  |  |  |   |                 |        |             |  |
|        | Construction Stockpile - Total                |                           |                             |                |                 |                 | \$13,419.00    |   |  |  |        |                 |                 |                |   |  |                |        |             |  |  |  |  |  |  |  |  |   |                 |        |             |  |
| 1620 - | Total   |                           |                             |                |                 |                 | \$13,419.00    |   |  |  |        |                 |                 |                |   |  |                |        |             |  |  |  |  |  |  |  |  |   |                 |        |             |  |
| 1630   | TYPE E CRASHWORTHY END<br>TERMINAL            | Construction<br>Stockpile |                             | 2              | Aug 3,<br>2020  | SYSTEM          | \$18,995.00    | Payment Estimate Item Adjustment generated Stockpile Transaction  |  |  |        |                 |                 |                |   |  |                |        |             |  |  |  |  |  |  |  |  |   |                 |        |             |  |
|        |   |                           | - Total                     |                |                 |                 | \$18,995.00    |   |  |  |        |                 |                 |                |   |  |                |        |             |  |  |  |  |  |  |  |  |   |                 |        |             |  |
|        | Construction Stockpile - Total                |                           |                             |                |                 |                 | \$18,995.00    |   |  |  |        |                 |                 |                |   |  |                |        |             |  |  |  |  |  |  |  |  |   |                 |        |             |  |
| 1630 - | Total   |                           |                             |                |                 |                 | \$18,995.00    |   |  |  |        |                 |                 |                |   |  |                |        |             |  |  |  |  |  |  |  |  |   |                 |        |             |  |
| 1780   | 80 MISC. EXTERNAL CONDUIT SYSTEM ON STRUCTURE |                           |                             | 3              | Aug 17,<br>2020 | SYSTEM          | (\$16,605.00)  |   |  |  |        |                 |                 |                |   |  |                |        |             |  |  |  |  |  |  |  |  |   |                 |        |             |  |
|        |   |                           |                             | 3              | Aug 17,<br>2020 | SYSTEM          | \$16,605.00    | This adjustment offsets the original system-generated Overrun<br>Payment Estimate Item Adjustment (0015) due to user kloepj1<br>overridding Payment Estimate Exception 10 on the current Payment<br>Estimate. |  |  |        |                 |                 |                |   |  |                |        |             |  |  |  |  |  |  |  |  |   |                 |        |             |  |
|        |   |                           |                             | 4              | Sep 2,<br>2020  | SYSTEM          | (\$16,605.00)  |   |  |  |        |                 |                 |                |   |  |                |        |             |  |  |  |  |  |  |  |  |   |                 |        |             |  |
|        |   |                           |                             |                |                 |                 |                |   |  |  | 4      | Sep 2,<br>2020  | SYSTEM          | \$16,605.00    | This adjustment offsets the original system-generated Overrun<br>Payment Estimate Item Adjustment (0019) due to user kloepj1<br>overridding Payment Estimate Exception 12 on the current Payment<br>Estimate. |  |                |        |             |  |  |  |  |  |  |  |  |   |                 |        |             |  |
|        |   |                           |                             | 5              | Sep 16,<br>2020 | SYSTEM          | (\$16,605.00)  |   |  |  |        |                 |                 |                |   |  |                |        |             |  |  |  |  |  |  |  |  |   |                 |        |             |  |
|        |   |                           |                             |                | 5               | Sep 16,<br>2020 | SYSTEM         | \$16,605.00   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate. |  |        |                 |                 |                |   |  |                |        |             |  |  |  |  |  |  |  |  |   |                 |        |             |  |
|        |   |                           |                             |                |                 |                 |                |   | 6  | Oct 1,<br>2020   | SYSTEM | (\$16,605.00)   |                 |                |   |  |                |        |             |  |  |  |  |  |  |  |  |   |                 |        |             |  |
|        |   |                           |                             |                |                 | 6               | Oct 1,<br>2020 | SYSTEM  | \$16,605.00  | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 34 on the current Payment Estimate. |        |                 |                 |                |   |  |                |        |             |  |  |  |  |  |  |  |  |   |                 |        |             |  |
|        |   |                           |                             |                |                 |                 |                |   |  |  |        | 7               | Oct 16,<br>2020 | SYSTEM         | (\$16,605.00)   |  |                |        |             |  |  |  |  |  |  |  |  |   |                 |        |             |  |
|        |   |                           |                             |                |                 |                 |                |   |  |  | 7      | Oct 16,<br>2020 | SYSTEM          | \$16,605.00    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 37 on the current Payment Estimate.          |  |                |        |             |  |  |  |  |  |  |  |  |   |                 |        |             |  |
|        |   |                           |                             | 8              | Nov 2,<br>2020  | SYSTEM          | (\$16,605.00)  |   |  |  |        |                 |                 |                |   |  |                |        |             |  |  |  |  |  |  |  |  |   |                 |        |             |  |
|        |   |                           |                             |                |                 | 8               | Nov 2,<br>2020 | SYSTEM  | \$16,605.00  | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user hillt5 overridding Payment Estimate Exception 31 on the current Payment Estimate.  |        |                 |                 |                |   |  |                |        |             |  |  |  |  |  |  |  |  |   |                 |        |             |  |
|        |   |                           |                             | 9              | Nov 16,<br>2020 | SYSTEM          | (\$16,605.00)  |   |  |  |        |                 |                 |                |   |  |                |        |             |  |  |  |  |  |  |  |  |   |                 |        |             |  |
|        |   |                           |                             |                |                 |                 |                |   |  |  |        |                 |                 |                |   |  |                |        |             |  |  |  |  |  |  |  |  | 9 | Nov 16,<br>2020 | SYSTEM | \$16,605.00 | This adjustment offsets the original system-generated Overrun<br>Payment Estimate Item Adjustment (0015) due to user hillt5<br>overridding Payment Estimate Exception 32 on the current Payment<br>Estimate. |
|        |   |                           |                             | 10             | Dec 2,<br>2020  | SYSTEM          | (\$16,605.00)  |   |  |  |        |                 |                 |                |   |  |                |        |             |  |  |  |  |  |  |  |  |   |                 |        |             |  |
|        |   |                           |                             |                |                 |                 |                |   |  |  |        |                 |                 |                |   | 10   | Dec 2,<br>2020 | SYSTEM | \$16,605.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 32 on the current Payment Estimate. |  |  |  |  |  |  |  |   |                 |        |             |  |
|        |   |                           |                             | 11             | Dec 16,<br>2020 | SYSTEM          | (\$16,605.00)  |   |  |  |        |                 |                 |                |   |  |                |        |             |  |  |  |  |  |  |  |  |   |                 |        |             |  |
|        |   |                           |                             |                |                 |                 |                |   | 1  | 1  | -      | 11              | Dec 16,<br>2020 | SYSTEM         | \$16,605.00   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user schlag1 overridding Payment Estimate Exception 30 on the current Payment Estimate. |                |        |             |  |  |  |  |  |  |  |  |   |                 |        |             |  |
|        |   |                           |                             |                |                 |                 |                |   |  |  |        |                 | 12              | Jan 4,<br>2021 | SYSTEM  | (\$16,605.00)  |                |        |             |  |  |  |  |  |  |  |  |   |                 |        |             |  |
|        |   |                           |                             | 12             | Jan 4,<br>2021  | SYSTEM          | \$16,605.00    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Exception 33 on the current Payment                   |  |  |        |                 |                 |                |   |  |                |        |             |  |  |  |  |  |  |  |  |   |                 |        |             |  |

Revision 4/1/2020 Page 39 of 45



| Line   | Description                   | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By   | Amount          | Remarks   |             |   |  |   |                 |        |               |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |   |                |        |             |  |
|--------|-------------------------------|--------------------|-----------------------------|----------------|-----------------|-----------------|-----------------|---|-------------|---|--|---|-----------------|--------|---------------|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|---|----------------|--------|-------------|--|
| 1780   | MISC. EXTERNAL CONDUIT SYSTEM | Material           |                             |                |                 |                 |                 | Estimate.   |             |   |  |   |                 |        |               |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |   |                |        |             |  |
|        | ON STRUCTURE                  |                    |                             | 13             | Jan 19,<br>2021 | SYSTEM          | (\$16,605.00)   |   |             |   |  |   |                 |        |               |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |   |                |        |             |  |
|        |                               |                    |                             | 13             | Jan 19,<br>2021 | SYSTEM          | \$16,605.00     | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schlag1 overridding Payment Estimate Exception 30 on the current Payment Estimate. |             |   |  |   |                 |        |               |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |   |                |        |             |  |
|        |                               |                    |                             | 14             | Feb 2,<br>2021  | SYSTEM          | (\$16,605.00)   |   |             |   |  |   |                 |        |               |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |   |                |        |             |  |
|        |                               |                    |                             | 14             | Feb 2,<br>2021  | SYSTEM          | \$16,605.00     | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hillt5 overridding Payment Estimate Exception 56 on the current Payment Estimate.  |             |   |  |   |                 |        |               |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |   |                |        |             |  |
|        |                               |                    |                             | 15             | Feb 16,<br>2021 | SYSTEM          | (\$16,605.00)   |   |             |   |  |   |                 |        |               |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |   |                |        |             |  |
|        |                               |                    |                             |                |                 | 15              | Feb 16,<br>2021 | SYSTEM  | \$16,605.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schlag1 overridding Payment Estimate Exception 55 on the current Payment Estimate. |  |   |                 |        |               |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |   |                |        |             |  |
|        |                               |                    |                             | 16             | Mar 2,<br>2021  | SYSTEM          | (\$16,605.00)   |   |             |   |  |   |                 |        |               |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |   |                |        |             |  |
|        |                               |                    |                             | 16             | Mar 2,<br>2021  | SYSTEM          | \$16,605.00     | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 51 on the current Payment Estimate. |             |   |  |   |                 |        |               |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |   |                |        |             |  |
|        |                               |                    | - Total                     |                |                 |                 | \$0.00          |   |             |   |  |   |                 |        |               |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |   |                |        |             |  |
|        | Material - Total              |                    |                             |                |                 |                 | \$0.00          |   |             |   |  |   |                 |        |               |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |   |                |        |             |  |
| 1780 - | Total                         |                    |                             |                |                 |                 | \$0.00          |   |             |   |  |   |                 |        |               |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |   |                |        |             |  |
| 2210   | CONCRETE FOOTINGS, BOLT DOWN  | Material           |                             | 3              | Aug 17,<br>2020 | SYSTEM          | (\$15,000.00)   |   |             |   |  |   |                 |        |               |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |   |                |        |             |  |
|        |                               |                    |                             | 3              | Aug 17,<br>2020 | SYSTEM          | \$15,000.00     | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  |             |   |  |   |                 |        |               |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |   |                |        |             |  |
|        |                               |                    |                             |                | 4               | Sep 2,<br>2020  | SYSTEM          | (\$15,000.00)   |             |   |  |   |                 |        |               |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |   |                |        |             |  |
|        |                               |                    |                             | 4              | Sep 2,<br>2020  | SYSTEM          | \$15,000.00     | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 13 on the current Payment Estimate.  |             |   |  |   |                 |        |               |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |   |                |        |             |  |
|        |                               |                    |                             | 5              | Sep 16,<br>2020 | SYSTEM          | (\$15,000.00)   |   |             |   |  |   |                 |        |               |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |   |                |        |             |  |
|        |                               |                    |                             | 5              | Sep 16,<br>2020 | SYSTEM          | \$15,000.00     | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user kloepj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.  |             |   |  |   |                 |        |               |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |   |                |        |             |  |
|        |                               |                    |                             | 6              | Oct 1,<br>2020  | SYSTEM          | (\$15,000.00)   |   |             |   |  |   |                 |        |               |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |   |                |        |             |  |
|        |                               |                    |                             |                |                 |                 |                 |   |             |   |  |   |                 |        |               |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  | 6 | Oct 1,<br>2020 | SYSTEM | \$15,000.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment Estimate Exception 35 on the current Payment Estimate. |
|        |                               |                    |                             |                | 7               | Oct 16,<br>2020 | SYSTEM          | (\$15,000.00)   |             |   |  |   |                 |        |               |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |   |                |        |             |  |
|        |                               |                    |                             | 7              | Oct 16,<br>2020 | SYSTEM          | \$15,000.00     | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment Estimate Exception 38 on the current Payment Estimate.  |             |   |  |   |                 |        |               |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |   |                |        |             |  |
|        |                               |                    |                             | 8              | Nov 2,<br>2020  | SYSTEM          | (\$15,000.00)   |   |             |   |  |   |                 |        |               |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |   |                |        |             |  |
|        |                               |                    |                             | 8              | Nov 2,<br>2020  | SYSTEM          | \$15,000.00     | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user hillt5 overridding Payment Estimate Exception 32 on the current Payment Estimate.   |             |   |  |   |                 |        |               |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |   |                |        |             |  |
|        |                               |                    |                             |                |                 |                 |                 |   |             |   |  | 9 | Nov 16,<br>2020 | SYSTEM | (\$15,000.00) |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |   |                |        |             |  |
|        |                               |                    |                             | 9              | Nov 16,<br>2020 | SYSTEM          | \$15,000.00     | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user hillt5 overridding Payment Estimate Exception 33 on the current Payment Estimate.   |             |   |  |   |                 |        |               |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |   |                |        |             |  |

Revision 4/1/2020 Page 40 of 45



| Line   | Description                     | Adjustment<br>Type        | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By   | Amount                    | Remarks   |   |
|--------|---------------------------------|---------------------------|-----------------------------|----------------|-----------------|-----------------|---------------------------|---|---|
| 2210   | CONCRETE FOOTINGS, BOLT DOWN    | Material                  |                             | 10             | Dec 2,<br>2020  | SYSTEM          | (\$15,000.00)             |   |   |
|        |                                 |                           |                             | 10             | Dec 2,<br>2020  | SYSTEM          | \$15,000.00               | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.  |   |
|        |                                 |                           |                             | 11             | Dec 16,<br>2020 | SYSTEM          | (\$15,000.00)             |   |   |
|        |                                 |                           |                             | 11             | Dec 16,<br>2020 | SYSTEM          | \$15,000.00               | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user schlag1 overridding Payment Estimate Exception 31 on the current Payment Estimate.  |   |
|        |                                 |                           |                             |                | 12              | Jan 4,<br>2021  | SYSTEM                    | (\$15,000.00)   |   |
|        |                                 |                           |                             | 12             | Jan 4,<br>2021  | SYSTEM          | \$15,000.00               | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 34 on the current Payment Estimate. |   |
|        |                                 |                           |                             | 13             | Jan 19,<br>2021 | SYSTEM          | (\$15,000.00)             |   |   |
|        |                                 |                           |                             | 13             | Jan 19,<br>2021 | SYSTEM          | \$15,000.00               | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schlag1 overridding Payment Estimate Exception 31 on the current Payment Estimate. |   |
|        |                                 |                           |                             | 14             | Feb 2,<br>2021  | SYSTEM          | (\$15,000.00)             |   |   |
|        |                                 |                           |                             |                | 14              | Feb 2,<br>2021  | SYSTEM                    | \$15,000.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hillt5 overridding Payment Estimate Exception 57 on the current Payment Estimate.  |
|        |                                 |                           |                             | 15             | Feb 16,<br>2021 | SYSTEM          | (\$15,000.00)             |   |   |
|        |                                 |                           |                             |                | 15              | Feb 16,<br>2021 | SYSTEM                    | \$15,000.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schlag1 overridding Payment Estimate Exception 56 on the current Payment Estimate. |
|        |                                 |                           |                             | 16             | Mar 2,<br>2021  | SYSTEM          | (\$15,000.00)             |   |   |
|        |                                 |                           |                             | 16             | Mar 2,<br>2021  | SYSTEM          | \$15,000.00               | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 52 on the current Payment Estimate. |   |
|        |                                 |                           | - Total                     |                |                 |                 | \$0.00                    |   |   |
|        | Material - Total                |                           |                             |                |                 |                 | \$0.00                    |   |   |
| 2210 - |                                 |                           |                             | _              |                 | 2)/2==1/        | \$0.00                    |   |   |
| 2220   | STRUCTURAL STEEL POSTS          | Stockpile Stockpile       |                             | 5              | Sep 16,<br>2020 | SYSTEM          | \$7,567.11                | Payment Estimate Item Adjustment generated Stockpile Transaction  |   |
|        |                                 |                           | - Total                     |                |                 |                 | \$7,567.11                |   |   |
| 2220 - | Construction Stockpile - Total  |                           |                             |                |                 |                 | \$7,567.11                |   |   |
| 2230   | PIPE POSTS                      | Construction<br>Stockpile |                             | 5              | Sep 16, 2020    | SYSTEM          | \$7,567.11<br>\$10,734.00 | Payment Estimate Item Adjustment generated Stockpile Transaction  |   |
|        |                                 | Stockpile                 | - Total                     |                | 2020            |                 | \$10,734.00               |   |   |
|        | Construction Stockpile - Total  |                           |                             |                |                 |                 | \$10,734.00               |   |   |
| 2230 - | Total                           |                           |                             |                |                 |                 | \$10,734.00               |   |   |
| 2300   | TUBULAR SUPPORT, TYPE C-2315-20 | Construction<br>Stockpile |                             | 8              | Nov 2,<br>2020  | SYSTEM          | \$1,400.00                | Payment Estimate Item Adjustment generated Stockpile Transaction  |   |
|        |                                 |                           | - Total                     |                |                 |                 | \$1,400.00                |   |   |
|        | Construction Stockpile - Total  |                           |                             |                |                 |                 | \$1,400.00                |   |   |
| 2300 - |                                 |                           |                             |                |                 |                 | \$1,400.00                |   |   |
| 2310   | TUBULAR SUPPORT, TYPE C-2018-28 | Construction<br>Stockpile |                             | 8              | Nov 2,<br>2020  | SYSTEM          | \$1,400.00                | Payment Estimate Item Adjustment generated Stockpile Transaction  |   |
|        |                                 |                           | - Total                     |                |                 |                 | \$1,400.00                |   |   |
|        | Construction Stockpile - Total  |                           |                             |                |                 |                 | \$1,400.00                |   |   |
| 2310 - | Total                           |                           |                             |                |                 |                 | \$1,400.00                |   |   |

Revision 4/1/2020 Page 41 of 45



| Line   | Description                                      | Adjustment<br>Type        | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By | Amount         | Remarks  |
|--------|--|---------------------------|-----------------------------|----------------|-----------------|---------------|----------------|--|
| 2320   | MISC. SIGN 12 CANTILEVER BOX<br>TRUSS, 30 FT ARM | Construction<br>Stockpile |                             | 8              | Nov 2,<br>2020  | SYSTEM        | \$2,300.00     | Payment Estimate Item Adjustment generated Stockpile Transaction   |
|        |  |                           | - Total                     |                |                 |               | \$2,300.00     |  |
|        | Construction Stockpile - Total                   |                           |                             |                |                 |               | \$2,300.00     |  |
| 2320 - | · Total  |                           |                             |                |                 |               | \$2,300.00     |  |
| 2330   | MISC. SIGN 4 SPAN BOX TRUSS (98 FT)              | Construction<br>Stockpile |                             | 8              | Nov 2,<br>2020  | SYSTEM        | \$2,600.00     | Payment Estimate Item Adjustment generated Stockpile Transaction   |
|        |  |                           | - Total                     |                |                 |               | \$2,600.00     |  |
|        | Construction Stockpile - Total                   |                           |                             |                |                 |               | \$2,600.00     |  |
| 2330 - | · Total  |                           |                             |                |                 |               | \$2,600.00     |  |
| 2340   | MISC. SIGN 8 SPAN BOX TRUSS (83<br>FT-5 IN)      | Construction<br>Stockpile |                             | 8              | Nov 2,<br>2020  | SYSTEM        | \$2,600.00     | Payment Estimate Item Adjustment generated Stockpile Transaction   |
|        |  |                           | - Total                     |                |                 |               | \$2,600.00     |  |
|        | Construction Stockpile - Total                   |                           |                             |                |                 |               | \$2,600.00     |  |
| 2340 - | - Total  |                           |                             |                |                 |               | \$2,600.00     |  |
| 2650   | CLASS B CONCRETE<br>(SUBSTRUCTURE)               | Material                  |                             | 16             | Mar 2,<br>2021  | SYSTEM        | (\$5,050.00)   |  |
|        |  |                           |                             | 16             | Mar 2,<br>2021  | SYSTEM        | \$5,050.00     | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 36 on the current Payment Estimate.          |
|        |  |                           | - Total                     |                |                 |               | \$0.00         |  |
|        | Material - Total                                 |                           |                             |                |                 |               | \$0.00         |  |
| 2650 - | · Total  |                           |                             |                |                 |               | \$0.00         |  |
| 2670   | SLAB ON STEEL                                    | Material                  |                             | 14             | Feb 2,<br>2021  | SYSTEM        | (\$17,390.00)  |  |
|        |  |                           |                             | 14             | Feb 2,<br>2021  | SYSTEM        | \$17,390.00    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user hillt5 overridding Payment Estimate Exception 32 on the current Payment Estimate.           |
|        |  |                           |                             | 15             | Feb 16,<br>2021 | SYSTEM        | (\$17,390.00)  |  |
|        |  |                           |                             | 15             | Feb 16,<br>2021 | SYSTEM        | \$17,390.00    | This adjustment offsets the original system-generated Material<br>Payment Estimate Item Adjustment (0017) due to user schlag1<br>overridding Payment Estimate Exception 40 on the current Payment<br>Estimate. |
|        |  |                           |                             | 16             | Mar 2,<br>2021  | SYSTEM        | (\$34,780.00)  |  |
|        |  |                           |                             | 16             | Mar 2,<br>2021  | SYSTEM        | \$34,780.00    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 39 on the current Payment Estimate.          |
|        |  |                           | - Total                     |                |                 |               | \$0.00         |  |
|        | Material - Total                                 |                           |                             |                |                 |               | \$0.00         |  |
| 2670 - | Total  |                           |                             |                |                 |               | \$0.00         |  |
| 2790   | STRIP SEAL EXPANSION JOINT<br>SYSTEM             | Construction<br>Stockpile |                             | 14             | Feb 2,<br>2021  | SYSTEM        | \$9,471.00     | Payment Estimate Item Adjustment generated Stockpile Transaction   |
|        |  |                           | - Total                     |                |                 |               | \$9,471.00     |  |
|        | Construction Stockpile - Total                   |                           |                             |                |                 |               | \$9,471.00     |  |
| 2790 - | · Total  |                           |                             |                |                 |               | \$9,471.00     |  |
| 2940   | MECHANICALLY STABILIZED EARTH<br>WALL SYSTEMS    | Material                  |                             | 8              | Nov 2,<br>2020  | SYSTEM        | (\$81,250.00)  |  |
|        |  |                           |                             | 8              | Nov 2,<br>2020  | SYSTEM        | \$81,250.00    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user hillt5 overridding Payment Estimate Exception 22 on the current Payment Estimate.            |
|        |  |                           |                             | 9              | Nov 16,<br>2020 | SYSTEM        | (\$352,312.50) |  |
|        |  |                           |                             | 9              | Nov 16,<br>2020 | SYSTEM        | \$352,312.50   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user hillt5 overridding Payment Estimate Exception 22 on the current Payment Estimate.            |
|        |  |                           |                             | 10             | Dec 2,<br>2020  | SYSTEM        | (\$514,875.00) |  |
|        | on 4/1/2020                                      |                           |                             |                | 2020            |               |                | Page 42 of 41  |

Revision 4/1/2020 Page 42 of 45



| 13     | Description                                   | Adinator                  | 04                          | F-4            | Cun-t           | 0             | A                          | Daw with  |
|--------|---|---------------------------|-----------------------------|----------------|-----------------|---------------|----------------------------|---|
| Line   | Description                                   | Adjustment<br>Type        | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By | Amount                     | Remarks   |
| 2940   | MECHANICALLY STABILIZED EARTH<br>WALL SYSTEMS | Material                  |                             | 10             | Dec 2,<br>2020  | SYSTEM        | \$514,875.00               | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.  |
|        |   |                           |                             | 11             | Dec 16,<br>2020 | SYSTEM        | (\$514,875.00)             |   |
|        |   |                           |                             | 11             | Dec 16,<br>2020 | SYSTEM        | \$514,875.00               | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user schlag1 overridding Payment Estimate Exception 21 on the current Payment Estimate.  |
|        |   |                           |                             | 12             | Jan 4,<br>2021  | SYSTEM        | (\$542,000.00)             |   |
|        |   |                           |                             | 12             | Jan 4,<br>2021  | SYSTEM        | \$542,000.00               | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 24 on the current Payment Estimate. |
|        |   |                           |                             | 13             | Jan 19,<br>2021 | SYSTEM        | (\$542,000.00)             |   |
|        |   |                           |                             | 13             | Jan 19,<br>2021 | SYSTEM        | \$542,000.00               | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schlag1 overridding Payment Estimate Exception 22 on the current Payment Estimate. |
|        |   |                           |                             | 14             | Feb 2,<br>2021  | SYSTEM        | (\$542,000.00)             |   |
|        |   |                           |                             | 14             | Feb 2,<br>2021  | SYSTEM        | \$542,000.00               | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user hillt5 overridding Payment Estimate Exception 50 on the current Payment Estimate.  |
|        |   |                           |                             | 15             | Feb 16,<br>2021 | SYSTEM        | (\$542,000.00)             |   |
|        |   |                           |                             | 15             | Feb 16,<br>2021 | SYSTEM        | \$542,000.00               | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schlag1 overridding Payment Estimate Exception 50 on the current Payment Estimate. |
|        |   |                           |                             | 16             | Mar 2,<br>2021  | SYSTEM        | (\$542,000.00)             |   |
|        |   |                           |                             | 16             | Mar 2,<br>2021  | SYSTEM        | \$542,000.00               | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment Estimate Exception 49 on the current Payment Estimate. |
|        |   |                           | - Total                     |                |                 |               | \$0.00                     |   |
|        | Material - Total                              |                           |                             |                |                 |               | \$0.00                     |   |
|        | - Total                                       |                           |                             |                |                 |               | \$0.00                     |   |
| 2960   | MISC. (60 IN.) DECORATIVE<br>PEDESTRIAN FENCE | Construction<br>Stockpile |                             | 4              | Sep 2,<br>2020  | SYSTEM        | \$16,591.23                | Payment Estimate Item Adjustment generated Stockpile Transaction  |
|        | Construction Steelmile Total                  |                           | - Total                     |                |                 |               | \$16,591.23                |   |
| 2960 - | Construction Stockpile - Total  - Total       |                           |                             |                |                 |               | \$16,591.23<br>\$16,591.23 |   |
| 3170   | MISC. (60 IN.) DECORATIVE<br>PEDESTRIAN FENCE | Construction<br>Stockpile |                             | 4              | Sep 2,<br>2020  | SYSTEM        | \$23,938.77                | Payment Estimate Item Adjustment generated Stockpile Transaction  |
|        |   |                           | - Total                     |                |                 |               | \$23,938.77                |   |
|        | Construction Stockpile - Total                |                           |                             |                |                 |               | \$23,938.77                |   |
|        | - Total                                       |                           |                             |                |                 |               | \$23,938.77                |   |
| 3760   | MISC. MODULAR EXPANSION JOINT SYSTEM          | Construction<br>Stockpile |                             | 14             | Feb 2,<br>2021  | SYSTEM        | \$26,016.00                | Payment Estimate Item Adjustment generated Stockpile Transaction  |
|        | Canatavation Stanlands Tatal                  |                           | - Total                     |                |                 |               | \$26,016.00                |   |
| 3760 - | Construction Stockpile - Total                |                           |                             |                |                 |               | \$26,016.00<br>\$26,016.00 |   |
| 3830   | STRIP SEAL EXPANSION JOINT SYSTEM             | Construction<br>Stockpile |                             | 14             | Feb 2,<br>2021  | SYSTEM        | \$5,544.00                 | Payment Estimate Item Adjustment generated Stockpile Transaction  |
|        |   |                           | - Total                     |                |                 |               | \$5,544.00                 |   |
|        | Construction Stockpile - Total                |                           |                             |                |                 |               | \$5,544.00                 |   |
|        | - Total                                       |                           |                             |                |                 |               | \$5,544.00                 |   |
| 5013   | DRILLED SHAFTS (3 FT. 6 IN. DIA.)             | Material                  |                             | 14             | Feb 2,<br>2021  | SYSTEM        | (\$115,139.70)             |   |

Revision 4/1/2020 Page 43 of 45



| Line   | Description                       | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By | Amount         | Remarks   |
|--------|-----------------------------------|--------------------|-----------------------------|----------------|-----------------|---------------|----------------|---|
| 5013   | DRILLED SHAFTS (3 FT. 6 IN. DIA.) | Material           |                             | 14             | Feb 2,<br>2021  | SYSTEM        | \$115,139.70   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user hillt5 overridding Payment Estimate Exception 19 on the current Payment Estimate.  |
|        |                                   |                    |                             | 15             | Feb 16,<br>2021 | SYSTEM        | (\$115,139.70) |   |
|        |                                   |                    |                             | 15             | Feb 16,<br>2021 | SYSTEM        | \$115,139.70   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schlag1 overridding Payment Estimate Exception 27 on the current Payment Estimate. |
|        |                                   |                    |                             | 16             | Mar 2,<br>2021  | SYSTEM        | (\$115,139.70) |   |
|        |                                   |                    |                             | 16             | Mar 2,<br>2021  | SYSTEM        | \$115,139.70   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment Estimate Exception 28 on the current Payment Estimate. |
|        |                                   |                    | - Total                     |                |                 |               | \$0.00         |   |
|        | Material - Total                  |                    |                             |                |                 |               | \$0.00         |   |
| 5013 - | · Total                           |                    |                             |                |                 |               | \$0.00         |   |
| 5014   | ROCK SOCKETS (3 FT 0 IN. DIA.)    | Material           |                             | 14             | Feb 2,<br>2021  | SYSTEM        | (\$70,341.57)  |   |
|        |                                   |                    |                             | 14             | Feb 2,<br>2021  | SYSTEM        | \$70,341.57    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user hillt5 overridding Payment Estimate Exception 26 on the current Payment Estimate.  |
|        |                                   |                    |                             | 15             | Feb 16,<br>2021 | SYSTEM        | (\$70,341.57)  |   |
|        |                                   |                    |                             | 15             | Feb 16,<br>2021 | SYSTEM        | \$70,341.57    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schlag1 overridding Payment Estimate Exception 34 on the current Payment Estimate. |
|        |                                   |                    |                             | 16             | Mar 2,<br>2021  | SYSTEM        | (\$70,341.57)  |   |
|        |                                   |                    |                             | 16             | Mar 2,<br>2021  | SYSTEM        | \$70,341.57    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment Estimate Exception 33 on the current Payment Estimate. |
|        |                                   |                    | - Total                     |                |                 |               | \$0.00         |   |
|        | Material - Total                  |                    |                             |                |                 |               | \$0.00         |   |
| 5014 - | ·Total                            |                    |                             |                |                 |               | \$0.00         |   |
| 5015   | REINFORCING STEEL (EPOXY COATED)  | Material           |                             | 14             | Feb 2,<br>2021  | SYSTEM        | (\$36,892.40)  |   |
|        |                                   |                    |                             | 14             | Feb 2,<br>2021  | SYSTEM        | \$36,892.40    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user hillt5 overridding Payment Estimate Exception 42 on the current Payment Estimate.  |
|        |                                   |                    |                             | 15             | Feb 16,<br>2021 | SYSTEM        | (\$36,892.40)  |   |
|        |                                   |                    |                             | 15             | Feb 16,<br>2021 | SYSTEM        | \$36,892.40    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schlag1 overridding Payment Estimate Exception 47 on the current Payment Estimate. |
|        |                                   |                    |                             | 16             | Mar 2,<br>2021  | SYSTEM        | (\$36,892.40)  |   |
|        |                                   |                    |                             | 16             | Mar 2,<br>2021  | SYSTEM        | \$36,892.40    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user kloepj1 overridding Payment Estimate Exception 46 on the current Payment Estimate. |
|        |                                   |                    | - Total                     |                |                 |               | \$0.00         |   |
|        | Material - Total                  |                    |                             |                |                 |               | \$0.00         |   |
| 5015 - | Total                             |                    |                             |                |                 |               | \$0.00         |   |
| 5019   | MECHANICAL BAR SPLICE             | Material           |                             | 14             | Feb 2,<br>2021  | SYSTEM        | (\$2,532.60)   |   |
|        |                                   |                    |                             | 14             | Feb 2,<br>2021  | SYSTEM        | \$2,532.60     | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user hillt5 overridding Payment Estimate Exception 41 on the current Payment Estimate.  |
|        |                                   |                    | - Total                     |                |                 |               | \$0.00         |   |

Revision 4/1/2020 Page 44 of 45



| Line            | Description   | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By | Amount        | Remarks   |
|-----------------|---|--------------------|-----------------------------|----------------|-----------------|---------------|---------------|---|
| 5019            | Material - Total  |                    |                             |                |                 |               | \$0.00        |   |
| 5019 -          | · Total   |                    |                             |                |                 |               | \$0.00        |   |
| 5020            | FURNISHING AND PLACING<br>CONCRETE MATERIAL FOR FULL<br>DEPTH PAVEMENT REPAIR                           | Material           |                             | 15             | Feb 16,<br>2021 | SYSTEM        | (\$18,227.00) |   |
|                 |   |                    |                             | 15             | Feb 16,<br>2021 | SYSTEM        | \$18,227.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schlag1 overridding Payment Estimate Exception 13 on the current Payment Estimate. |
|                 |   |                    |                             | 16             | Mar 2,<br>2021  | SYSTEM        | (\$18,227.00) |   |
|                 |   |                    |                             | 16             | Mar 2,<br>2021  | SYSTEM        | \$18,227.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user kloepj1 overridding Payment Estimate Exception 16 on the current Payment Estimate. |
|                 | - Total   |                    |                             |                |                 |               | \$0.00        |   |
|                 | Material - Total  |                    |                             |                |                 |               | \$0.00        |   |
| 5020 -          | 020 - Total   |                    |                             |                |                 |               | \$0.00        |   |
| 5021            | TIE BAR (DRILLING, FURNISHING<br>AND INSTALLATION) FOR FULL<br>DEPTH PAVEMENT REPAIR (TYPE L<br>JOINTS) | Material           |                             | 15             | Feb 16,<br>2021 | SYSTEM        | (\$696.00)    |   |
|                 |   |                    |                             | 15             | Feb 16,<br>2021 | SYSTEM        | \$696.00      | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user schlag1 overridding Payment Estimate Exception 18 on the current Payment Estimate. |
|                 |   |                    |                             | 16             | Mar 2,<br>2021  | SYSTEM        | (\$696.00)    |   |
|                 |   |                    |                             | 16             | Mar 2,<br>2021  | SYSTEM        | \$696.00      | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user kloepj1 overridding Payment Estimate Exception 19 on the current Payment Estimate. |
|                 | - Total   |                    |                             |                |                 |               | \$0.00        |   |
|                 | Material - Total  |                    |                             |                |                 |               | \$0.00        |   |
| 5021 -          | · Total   |                    |                             |                |                 |               | \$0.00        |   |
| 5022            | DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR                        | Material           |                             | 15             | Feb 16,<br>2021 | SYSTEM        | (\$1,950.00)  |   |
|                 |   |                    |                             | 15             | Feb 16,<br>2021 | SYSTEM        | \$1,950.00    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schlag1 overridding Payment Estimate Exception 16 on the current Payment Estimate. |
|                 |   |                    |                             | 16             | Mar 2,<br>2021  | SYSTEM        | (\$1,950.00)  |   |
|                 |   |                    |                             | 16             | Mar 2,<br>2021  | SYSTEM        | \$1,950.00    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user kloepj1 overridding Payment Estimate Exception 18 on the current Payment Estimate. |
|                 | - Total   |                    |                             |                |                 |               | \$0.00        |   |
|                 | Material - Total  |                    |                             |                |                 |               | \$0.00        |   |
| 5022 - Total    |   |                    |                             |                |                 |               | \$0.00        |   |
| Overall - Total |   |                    |                             |                |                 |               | \$204,476.30  |   |

Revision 4/1/2020 Page 45 of 45