

Pay Estimate Created Date: July 16, 2021

Progress Estimate Number 25		Contract ID Prime Contractor	200515-F15 KCI Construction Con	Pay Period Start mpany Pay Period End		Original Contract Amount Net Change Order Amount Current Contract Amount	\$24,269,745.00 \$507,432.48 \$24,777,177.48
Approval Date							By User
July 16, 2021			Generated and App	roved (and should be con	sidered Draft)	at the Project Office Level by	kloepj1
July 16, 2021		R	eviewed and Approved	d (and should be considere	ed Draft) at the	Resident Engineer Level by	washas
July 19, 2021			Rev	viewed and Approved at th	e Central Offic	e Controllers Office Level by	ramses1
Original Completion Date Current Com		pletion Date	Actual Completion Dat	e c	% of Current Contract Amou	nt Complete	
June 1, 2022 June 1		, 2022			56.65%		

	Contract Informational Dates									
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract							
Acceptance Date										
Awarded Date	June 3, 2020	June 3, 2020								
Letting Date	May 15, 2020	May 15, 2020								
Notice to Proceed Date	July 6, 2020	July 6, 2020								
Open to Traffic Date										
Work Began Date										

Contract Total Pa	y For Estimate No. 25				
		This Estimate	Previous	To Date	
200515-F15					
	Total Posted Items Pay	\$1,676,209.08	\$12,360,766.97	\$14,036,976.05	
	Gross Item Adjustments	(\$53,294.35)	\$411,974.65	\$358,680.30	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$265,444.89	\$265,444.89	
			\$13,038,186.51	\$14,661,101.24	
Contract Total Page	yable This Estimate:	\$1,622,914.73			

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6I2222	0120	2063000	CLASS 3 EXCAVATION	CUYD	\$15.000	389	\$5,835.00
	0440	6089902	MISC.ADA CURB RAMP	EA	\$3,550.000	1	\$3,550.00
	0450	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	LF	\$45.000	113	\$5,085.00
	0460	6091042	CONCRETE GUTTER TYPE B	LF	\$30.000	268	\$8,040.00
	0650	6169901	MISC.TEMPORARY TRAFFIC CONTROL	LS	\$465,000.000	0.25	\$116,250.00
	0741	6181000	MOBILIZATION	LS	\$2,162,092.840	0.25	\$540,523.21
	1110	7261015	15 IN. PIPE GROUP A	LF	\$70.000	168	\$11,760.00
	1140	7261030	30 IN. PIPE GROUP A	LF	\$250.000	67	\$16,750.00
	1170	7311022	PRECAST CONCRETE DROP INLET 2 FT X 2 FT	FT	\$350.000	-1.91	(\$668.50)
	1180	7311042	PRECAST CONCRETE DROP INLET 4 FT X 2 FT	FT	\$450.000	19	\$8,550.00
	1190	7311053	PRECAST CONCRETE DROP INLET 5 FT X 3 FT	FT	\$650.000	16	\$10,400.00
	1200	7319913	MISC.MSD Standard 60" Manhole	FT	\$510.000	1	\$510.00
	1210	7319913	MISC.MSD Standard Line 48" Manhole	FT	\$350.000	2	\$700.00
	1220	7320615A	15 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	EA	\$800.000	6	\$4,800.00
	1240	7320630A	30 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	EA	\$1,500.000	1	\$1,500.00
	1320	8061017	TEMPORARY SEEDING AND MULCHING	ACRE	\$1,500.000	1.6	\$2,400.00
	1490	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	SQYD	\$6.500	1,039.2	\$6,754.80
	1500	5021308	CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. JOINTS)	SQYD	\$51.000	553.8	\$28,243.80

Revision 4/1/2020 Page 1 of 81



Pay Estimate Created Date: July 16, 2021

Progress Estimate Number 25 Contract ID 200515-F15 Pay Period Start July 1, 2021 Original Contract Amount \$24,269,745.00 Pay Period End July 15, 2021 Net Change Order Amount 507,432.48 Current Contract Amount \$24,777,177.48

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6I2222	1510	5021309	CONCRETE PAVEMENT (9 IN. NON-REINFORCED 15 FT. JOINTS)	SQYD	\$54.000	449.3	\$24,262.20
	1550	5021340	TYPE A2 SHOULDER	SQYD	\$35.000	36.1	\$1,263.50
	2270	9035011A	ST-STRUCTURAL	SQFT	\$24.000	170	\$4,080.00
	2290	9035071A	STF-STRUCTURAL FLUORESCENT	SQFT	\$26.000	90	\$2,340.00
	2330	9039901	MISC.SIGN 4 SPAN BOX TRUSS (98 FT)	LS	\$66,000.000	1	\$66,000.00
	2720	7049904	MISC.BARRIER CURB REPAIR (UNFORMED	SQFT	\$175.000	2	\$350.00
	3000	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	CUYD	\$565.000	36.1	\$20,396.50
	3390	7161003	LAMINATED NEOPRENE BEARING PAD (TAPERED)	EA	\$425.000	14	\$5,950.00
	3480	7011110	DRILLED SHAFTS (6 FT. 0 IN. DIA.)	LF	\$485.000	62.33	\$30,230.05
	3490	7011209	ROCK SOCKETS (5 FT 6 IN. DIA.)	LF	\$2,555.000	24.24	\$61,933.20
	3500	7011300	VIDEO CAMERA INSPECTION	EA	\$550.000	1	\$550.00
	3520	7011600	SONIC LOGGING TESTING	EA	\$4,250.000	1	\$4,250.00
	3630	7061060	REINFORCING STEEL (BRIDGES)	LB	\$0.850	35,330	\$30,030.50
	3640	7061070	MECHANICAL BAR SPLICE	EA	\$95.000	24	\$2,280.00
	5045	1099902	MISC.Value Engineering Design Costs - VECP #20-29	EA	\$1.000	214,535	\$214,535.00
	5046	1046002	VALUE ENGINEERING	EA	\$1.000	279,927.42	\$279,927.42
	5047	7250415	15 IN. PIPE GROUP C	LF	\$70.000	88	\$6,160.00
	5049	7320618A	18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	EA	\$900.000	2	\$1,800.00
	5053	1099902	MISC.Value Engineering Design Costs VECP #20-49	EA	\$1.000	46,410	\$46,410.00
	5054	1046002	VALUE ENGINEERING	EA	\$1.000	102,477.4	\$102,477.40
Project J6I22	222 - Total						\$1,676,209.08
Overall - Tot	tal						\$1,676,209.08

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

		stments Exist on Contract ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6I2222	0140	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	Material			-143	\$11.00	(\$1,573.00)
	0140	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	143	\$11.00	\$1,573.00
	0150	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material			-72	\$23.00	(\$1,656.00)
	0150	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user kloepj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	72	\$23.00	\$1,656.00
	0160	GRAVEL (A) OR CRUSHED STONE (B)	Material			-2,888	\$12.00	(\$34,656.00)
	0160	GRAVEL (A) OR CRUSHED STONE (B)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	2,888	\$12.00	\$34,656.00

Revision 4/1/2020 Page 2 of 81



Pay Estimate Created Date: July 16, 2021

Progress Estimate Number 25

Contract ID 200515-F15 Pay Period Start July 1, 2021 Original Contract Amount

\$24,269,745.00 Prime Contractor KCI Construction Company Pay Period End July 15, 2021 Net Change Order Amount \$507,432.48 Current Contract Amount \$24,777,177.48

ect ber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
222	0200	CONCRETE PAVEMENT (8 IN. NON-REINF)	Material			-293.2	\$49.00	(\$14,366.80
	0200	CONCRETE PAVEMENT (8 IN. NON-REINF)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	293.2	\$49.00	\$14,366.80
	0380	MODIFIED CONCRETE GUTTER TYPE B	Material			-458	\$34.00	(\$15,572.00
	0380	MODIFIED CONCRETE GUTTER TYPE B	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	458	\$34.00	\$15,572.00
	0410	PAVED APPROACH, 8 IN.	Material			-72.3	\$125.00	(\$9,037.50
	0410	PAVED APPROACH, 8 IN.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	72.3	\$125.00	\$9,037.50
	0420	CONCRETE SIDEWALK, 4 IN.	Material			-142.4	\$51.00	(\$7,262.40
	0420	CONCRETE SIDEWALK, 4 IN.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	142.4	\$51.00	\$7,262.40
	0440	MISC.	Material			-4	\$3,550.00	(\$14,200.00
	0440	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	4	\$3,550.00	\$14,200.00
	0450	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	Material			-113	\$45.00	(\$5,085.00
	0450	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	113	\$45.00	\$5,085.00
	0460	CONCRETE GUTTER TYPE B	Material			-268	\$30.00	(\$8,040.00
	0460	CONCRETE GUTTER TYPE B	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.	268	\$30.00	\$8,040.00
	0490	FURNISHING TYPE 2 ROCK DITCH LINER	Material			-210.5	\$100.00	(\$21,050.00
	0490	FURNISHING TYPE 2 ROCK DITCH LINER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.	210.5	\$100.00	\$21,050.00
	0675	CONCRETE TRAFFIC BARRIER, TYPE C	Material			-485	\$145.00	(\$70,325.00
	0675	CONCRETE TRAFFIC BARRIER, TYPE C	Material		This adjustment offsets the original system- generated Material Payment Estimate Item	485	\$145.00	\$70,325.00

Revision 4/1/2020 Page 3 of 81




Pay Estimate Created Date: July 16, 2021

Progress Estimate Number 25 Contract ID 200515-F15 Pay Period Start July 1, 2021 Original Contract Amount \$24,269,745.00 Pay Period End July 15, 2021 Net Change Order Amount \$507,432.48 Current Contract Amount \$24,777,177.48

ct er	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
22					Adjustment (0006) due to user kloepj1 overridding Payment Estimate Exception 23 on the current Payment Estimate.			
	0690	CONCRETE TRAFFIC BARRIER, TYPE D (RETAINING WALL)	Material			-2,289	\$85.00	(\$194,565.00
	0690	CONCRETE TRAFFIC BARRIER, TYPE D (RETAINING WALL)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 24 on the current Payment Estimate.	2,289	\$85.00	\$194,565.00
	0990	MISC.	Material			-2,401	\$15.50	(\$37,215.50
	0990	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 25 on the current Payment Estimate.	2,401	\$15.50	\$37,215.50
	1050	MISC.	Material			-952	\$25.00	(\$23,800.00
	1050	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.	952	\$25.00	\$23,800.00
	1190	PRECAST CONCRETE DROP INLET 5 FT X 3 FT	Material			-55	\$650.00	(\$35,750.00)
	1190	PRECAST CONCRETE DROP INLET 5 FT X 3 FT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user kloepj1 overridding Payment Estimate Exception 71 on the current Payment Estimate.	55	\$650.00	\$35,750.00
	1320	TEMPORARY SEEDING AND MULCHING	Material			-1.6	\$1,500.00	(\$2,400.00)
	1320	TEMPORARY SEEDING AND MULCHING	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 73 on the current Payment Estimate.	1.6	\$1,500.00	\$2,400.00
	1490	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	182.8	\$0.30	\$55.08
	1490	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	192.3	\$0.30	\$57.94
	1490	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	110.3	\$0.30	\$33.23
	1490	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	553.8	\$0.30	\$166.86
	1490	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material			-9,214.47	\$6.50	(\$59,894.06)
	1490	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0044) due to user kloepj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	9,214.47	\$6.50	\$59,894.06
	1500	CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. JOINTS)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	553.8	\$0.79	\$435.29
	1500	CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. JOINTS)	Material			-3,055.6	\$51.00	(\$155,835.60)

Revision 4/1/2020 Page 4 of 81



Pay Estimate Created Date: July 16, 2021

Progress Estimate Number
25

Contract ID 200515-F15 Pay Period Start July 1, 2021 Original Contract Amount \$24,269,745.00
Prime Contractor KCI Construction Company Pay Period End July 15, 2021 Net Change Order Amount Current Contract Amount \$24,777,177.48

ject nber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
2222	1500	CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. JOINTS)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0046) due to user kloepj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	3,055.6	\$51.00	\$155,835.60
	1510	CONCRETE PAVEMENT (9 IN. NON-REINFORCED 15 FT. JOINTS)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	146.7	\$0.86	\$126.84
	1510	CONCRETE PAVEMENT (9 IN. NON-REINFORCED 15 FT. JOINTS)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	192.3	\$0.86	\$166.26
	1510	CONCRETE PAVEMENT (9 IN. NON-REINFORCED 15 FT. JOINTS)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	110.3	\$0.86	\$95.37
	1510	CONCRETE PAVEMENT (9 IN. NON-REINFORCED 15 FT. JOINTS)	Material			-2,978.2	\$54.00	(\$160,822.80
	1510	CONCRETE PAVEMENT (9 IN. NON-REINFORCED 15 FT. JOINTS)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user kloepj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	2,978.2	\$54.00	\$160,822.80
	1520	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	Material			-210	\$15.00	(\$3,150.00
	1520	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0047) due to user kloepj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.	210	\$15.00	\$3,150.00
	1560	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	Material			-512	\$15.00	(\$7,680.00
	1560	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0048) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.	512	\$15.00	\$7,680.00
	1570	MGS GUARDRAIL	Material			-463	\$19.00	(\$8,797.00
	1570	MGS GUARDRAIL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	463	\$19.00	\$8,797.00
	1780	MISC.	Material			-1	\$16,605.00	(\$16,605.00
	1780	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment Estimate Exception 76 on the current Payment Estimate.	1	\$16,605.00	\$16,605.00
	1870	SIGNAL HEAD, TYPE 3B	Material			-5	\$927.00	(\$4,635.00
	1870	SIGNAL HEAD, TYPE 3B	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0024) due to user kloepj1 overridding Payment Estimate Exception 77 on the current Payment Estimate.	5	\$927.00	\$4,635.00
	1910	POST, SIGNAL 8 FT. OR 2.4 M	Material			-3	\$645.00	(\$1,935.00
	1910	POST, SIGNAL 8 FT. OR 2.4	Material		This adjustment offsets the original system-	3	\$645.00	\$1,935.00

Revision 4/1/2020 Page 5 of 81



Pay Estimate Created Date: July 16, 2021

Progress Estimate Number 25

Contract ID 200515-F15 Pay Period Start July 1, 2021 Original Contract Amount

Prime Contractor KCI Construction Company Pay Period End July 15, 2021 Net Change Order Amount \$507,432.48 Current Contract Amount \$24,777,177.48

\$24,269,745.00

ject nber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
2222		М			generated Material Payment Estimate Item Adjustment (0025) due to user kloepj1 overridding Payment Estimate Exception 78 on the current Payment Estimate.			
	1960	POST, TYPE C, 55 FT. ARM	Material			-1	\$11,930.00	(\$11,930.00
	1960	POST, TYPE C, 55 FT. ARM	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0026) due to user kloepj1 overridding Payment Estimate Exception 81 on the current Payment Estimate.	1	\$11,930.00	\$11,930.00
	1990	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	Material			-1	\$13,359.00	(\$13,359.00
	1990	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0027) due to user kloepj1 overridding Payment Estimate Exception 82 on the current Payment Estimate.	1	\$13,359.00	\$13,359.00
	2060	CABLE, 16 AWG 7 CONDUCTOR	Material			-1,176	\$1.60	(\$1,881.60
	2060	CABLE, 16 AWG 7 CONDUCTOR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0028) due to user kloepj1 overridding Payment Estimate Exception 83 on the current Payment Estimate.	1,176	\$1.60	\$1,881.60
	2100	BASE, CONCRETE	Material			-6.59	\$1,160.00	(\$7,644.40
	2100	BASE, CONCRETE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0029) due to user kloepj1 overridding Payment Estimate Exception 84 on the current Payment Estimate.	6.59	\$1,160.00	\$7,644.40
	2210	CONCRETE FOOTINGS, BOLT DOWN	Material			-56.32	\$1,200.00	(\$67,584.00
	2210	CONCRETE FOOTINGS, BOLT DOWN	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0034) due to user kloepj1 overridding Payment Estimate Exception 85 on the current Payment Estimate.	56.32	\$1,200.00	\$67,584.00
	2270	ST-STRUCTURAL	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$2,190.22
	2290	STF-STRUCTURAL FLUORESCENT	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$1,341.00
	2330	MISC.	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$2,600.00
	2330	MISC.	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$48,300.00
	2330	MISC.	Material			-1	\$66,000.00	(\$66,000.00
	2330	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0039) due to user kloepj1 overridding Payment Estimate Exception 87 on the current Payment Estimate.	1	\$66,000.00	\$66,000.00
	2670	SLAB ON STEEL	Material			-214	\$470.00	(\$100,580.00
	2670	SLAB ON STEEL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0049) due to user kloepj1 overridding Payment Estimate Exception 38 on the current Payment Estimate.	214	\$470.00	\$100,580.00

Page 6 of 81 Revision 4/1/2020

Pay Estimate Created Date: July 16, 2021

Progress Estimate Number 25

Contract ID 200515-F15 Pay Period Start July 1, 2021 Original Contract Amount

Prime Contractor KCI Construction Company Pay Period End July 15, 2021 Net Change Order Amount \$507,432.48 Current Contract Amount \$24,777,177.48

\$24,269,745.00

ect ber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
222	2690	CORRAL CURB	Material			-142	\$117.00	(\$16,614.00
	2690	CORRAL CURB	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0050) due to user kloepj1 overridding Payment Estimate Exception 41 on the current Payment Estimate.	142	\$117.00	\$16,614.00
	2700	SUPERSTRUCTURE REPAIR (UNFORMED)	Material			-1,269	\$158.00	(\$200,502.00
	2700	SUPERSTRUCTURE REPAIR (UNFORMED)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0051) due to user kloepj1 overridding Payment Estimate Exception 43 on the current Payment Estimate.	1,269	\$158.00	\$200,502.00
	2720	MISC.	Material			-148	\$175.00	(\$25,900.00)
	2720	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0052) due to user kloepj1 overridding Payment Estimate Exception 51 on the current Payment Estimate.	148	\$175.00	\$25,900.00
	2730	REINFORCING STEEL (EPOXY COATED)	Material			-850	\$3.00	(\$2,550.00)
	2730	REINFORCING STEEL (EPOXY COATED)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0053) due to user kloepj1 overridding Payment Estimate Exception 53 on the current Payment Estimate.	850	\$3.00	\$2,550.00
	2810	SUPERSTRUCTURE REPAIR (UNFORMED)	Material			-1,483	\$158.00	(\$234,314.00
	2810	SUPERSTRUCTURE REPAIR (UNFORMED)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0054) due to user kloepj1 overridding Payment Estimate Exception 48 on the current Payment Estimate.	1,483	\$158.00	\$234,314.00
	2940	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material			-8,672	\$62.50	(\$542,000.00)
	2940	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0055) due to user kloepj1 overridding Payment Estimate Exception 57 on the current Payment Estimate.	8,672	\$62.50	\$542,000.00
	3000	CLASS B CONCRETE (SUBSTRUCTURE)	Material			-36.1	\$565.00	(\$20,396.50)
	3000	CLASS B CONCRETE (SUBSTRUCTURE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0056) due to user kloepj1 overridding Payment Estimate Exception 34 on the current Payment Estimate.	36.1	\$565.00	\$20,396.50
	3180	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	Material			-25.5	\$490.00	(\$12,495.00
	3180	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0030) due to user kloepj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.	25.5	\$490.00	\$12,495.00
	3190	ROCK SOCKETS (3 FT 0 IN. DIA.)	Material			-30	\$815.00	(\$24,450.00)
	3190	ROCK SOCKETS (3 FT 0 IN. DIA.)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item	30	\$815.00	\$24,450.00

Page 7 of 81 Revision 4/1/2020



Pay Estimate Created Date: July 16, 2021

Progress Estimate Number 25 Contract ID 200515-F15 Pay Period Start July 1, 2021 Original Contract Amount \$24,269,745.00 Prime Contractor KCI Construction Company Pay Period End July 15, 2021 Net Change Order Amount Current Contract Amount \$24,777,177.48

Line r No.	Item Description	Adjustment Type	Other Item Adjustment	Comments	Adjustment Quantity	Line Item Adjustment	Adjustment amount
2			Туре	Adjustment (0031) due to user kloepj1		Unit Price	
				overridding Payment Estimate Exception 30 on the current Payment Estimate.			
3280	CLASS B-1 CONCRETE (SUBSTRUCTURE)	Material			-60.3	\$1,055.00	(\$63,616.50
3280	CLASS B-1 CONCRETE (SUBSTRUCTURE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0032) due to user kloepj1 overridding Payment Estimate Exception 35 on the current Payment Estimate.	60.3	\$1,055.00	\$63,616.50
3400	PIPE PILE SPACERS	Material			-14	\$855.00	(\$11,970.00
3400	PIPE PILE SPACERS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0033) due to user kloepj1 overridding Payment Estimate Exception 65 on the current Payment Estimate.	14	\$855.00	\$11,970.00
3430	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material			-836	\$80.00	(\$66,880.00
3430	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0057) due to user kloepj1 overridding Payment Estimate Exception 59 on the current Payment Estimate.	836	\$80.00	\$66,880.00
3450	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material			-2,269	\$80.00	(\$181,520.00
3450	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0058) due to user kloepj1 overridding Payment Estimate Exception 62 on the current Payment Estimate.	2,269	\$80.00	\$181,520.00
3480	DRILLED SHAFTS (6 FT. 0 IN. DIA.)	Material			-246.16	\$485.00	(\$119,387.60
3480	DRILLED SHAFTS (6 FT. 0 IN. DIA.)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0059) due to user kloepj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.	246.16	\$485.00	\$119,387.60
3490	ROCK SOCKETS (5 FT 6 IN. DIA.)	Material			-108	\$2,555.00	(\$275,940.00
3490	ROCK SOCKETS (5 FT 6 IN. DIA.)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0060) due to user kloepj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.	108	\$2,555.00	\$275,940.00
5008	MISC.	Material			-1	\$400.00	(\$400.00
5008	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0061) due to user kloepj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.	1	\$400.00	\$400.00
5011	REINFORCING STEEL (EPOXY COATED)	Material			-18,950	\$1.33	(\$25,203.50
5011	REINFORCING STEEL (EPOXY COATED)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0062) due to user kloepj1 overridding Payment Estimate Exception 54 on the current Payment Estimate.	18,950	\$1.33	\$25,203.50

Revision 4/1/2020 Page 8 of 81



Pay Estimate Created Date: July 16, 2021

Progress Estimate Number 25

Contract ID 200515-F15 Pay Period Start July 1, 2021 Original Contract Amount

Prime Contractor KCI Construction Company Pay Period End July 15, 2021 Net Change Order Amount \$507,432.48 Current Contract Amount \$24,777,177.48

\$24,269,745.00

oject nber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
2222	5013	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	Material			-202.8	\$567.75	(\$115,139.70
	5013	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0063) due to user kloepj1 overridding Payment Estimate Exception 27 on the current Payment Estimate.	202.8	\$567.75	\$115,139.70
	5014	ROCK SOCKETS (3 FT 0 IN. DIA.)	Material			-76.7	\$917.10	(\$70,341.57
	5014	ROCK SOCKETS (3 FT 0 IN. DIA.)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0064) due to user kloepj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.	76.7	\$917.10	\$70,341.57
	5015	REINFORCING STEEL (EPOXY COATED)	Material			-24,760	\$1.49	(\$36,892.40
	5015	REINFORCING STEEL (EPOXY COATED)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0065) due to user kloepj1 overridding Payment Estimate Exception 55 on the current Payment Estimate.	24,760	\$1.49	\$36,892.40
	5025	SEWER	Material			-147,772	\$1.00	(\$147,772.00
	5025	SEWER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0066) due to user kloepj1 overridding Payment Estimate Exception 68 on the current Payment Estimate.	147,772	\$1.00	\$147,772.00
	5026	CLASS B-1 CONCRETE (SUBSTRUCTURE)	Material			-99.8	\$1,404.00	(\$140,119.20
	5026	CLASS B-1 CONCRETE (SUBSTRUCTURE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0067) due to user kloepj1 overridding Payment Estimate Exception 36 on the current Payment Estimate.	99.8	\$1,404.00	\$140,119.20
	5037	REINFORCING STEEL (EPOXY COATED)	Material			-31,150	\$1.19	(\$37,068.50
	5037	REINFORCING STEEL (EPOXY COATED)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0068) due to user kloepj1 overridding Payment Estimate Exception 56 on the current Payment Estimate.	31,150	\$1.19	\$37,068.50
	5047	15 IN. PIPE GROUP C	Material			-88	\$70.00	(\$6,160.00
	5047	15 IN. PIPE GROUP C	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0069) due to user kloepj1 overridding Payment Estimate Exception 67 on the current Payment Estimate.	88	\$70.00	\$6,160.00
	5049	18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	Material			-2	\$900.00	(\$1,800.00
	5049	18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0070) due to user kloepj1 overridding Payment Estimate Exception 72 on the current Payment Estimate.	2	\$900.00	\$1,800.00

Page 9 of 81 Revision 4/1/2020



					Contract Project Information
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work
J6I2222	I-64-1 (61)	Interchange improvements	I-64	ST LOUIS CITY	from west of Ewing Ave to east of 21st Street

Totals by Job Numbers	y Job Numbers									
J6I2222	This Estimate	Previous	To Date							
Posted Item Pay Gross Item Adjustments	\$1,676,209.08 (\$53,294.35)	\$12,360,766.97 \$411,974.65	\$14,036,976.05 \$358,680.30							
Gross Item	n Pay \$1,622,914.73	\$12,772,741.62	\$14,395,656.35							
Incentive	\$0.00	\$0.00	\$0.00							
Disincentive	\$0.00	\$0.00	\$0.00							
Liquidated Damages	\$0.00	\$0.00	\$0.00							
Other Contract Adjustments	\$0.00	\$265,444.89	\$265,444.89							

Revision 4/1/2020 Page 10 of 81



Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 3040143, Project Item Line Number 0140, Material Set 304014396, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 3040504, Project Item Line Number 0150, Material Set 304050496, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 3040506, Project Item Line Number 1490, Material Set 304050696, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 3105003, Project Item Line Number 0160, Material Set 310500396, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 5021108, Project Item Line Number 0200, Material Set 502110896, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Waiting on PAL	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 5021108, Project Item Line Number 0200, Material Set 502110896, Material 1057JMDAEC4.11 - Dowel Assemblies Epoxy Ctd Gr40 1 1/4" @, Acceptance Action Generic ReinforcingMisc is insufficient.	Waiting on PAL	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 5021308, Project Item Line Number 1500, Material Set 502130896, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Waiting on PAL	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 5021308, Project Item Line Number 1500, Material Set 502130896, Material 1057JMDAEC4.11 - Dowel Assemblies Epoxy Ctd Gr40 1 1/4* @, Acceptance Action Generic ReinforcingMisc is insufficient.	Waiting on PAL	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 5021308, Project Item Line Number 1500, Material Set 502130896, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 5021308, Project Item Line Number 1500, Material Set 502130896, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 5021309, Project Item Line Number 1510, Material Set 502130996, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Waiting on PAL	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 6061060, Project Item Line Number 1570, Material Set 606106096, Material 1065DE - Delineators, Acceptance Action Generic 1065DE is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 6071102, Project Item Line Number 0380, Material Set 607110296, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Waiting on 28 day break	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 6085008, Project Item Line Number 0410, Material Set 608500896, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Waiting on PAL	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 6086004, Project Item Line Number 0420, Material Set 608600496, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Waiting on 28 day break	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 6089902, Project Item Line Number 0440, Material Set 6089902, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Waiting on 28 day break	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 6091010, Project Item Line Number 0450, Material Set 609101096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Waiting on 28 day break	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 6091042, Project Item Line Number 0460, Material Set 609104296, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Waiting on 28 day break	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 6092011, Project Item Line Number 1520, Material Set 609201196, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Waiting on 28 day break	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 6092011, Project Item Line Number 1560, Material Set 609201196, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Waiting on 28 day break	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 6096020, Project Item Line Number 0490, Material Set 609602096, Material 0609PDDL - Paved Drainage Material for Ditch Liner, Acceptance Action Generic 0609PDDL is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 6149902, Project Item Line Number 5008, Material Set 6149902, Material 0614DFMNFCMSD - Manhole Frame and cover (M.S.D.), Acceptance Action Generic 0614DFMNFCMSD is insufficient.	Plan quantity has not been reached/installed at this time	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 6173000, Project Item Line Number 0675, Material Set 617300096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Waiting on 28 day break	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 6173102, Project Item Line Number 0690, Material Set 617310296, Material 1009G4DRLDAA - Agg for Drainage Gr4 Alt A	Aggregate material testing needs to be reported	kloepj1	Overridden

Revision 4/1/2020 Page 11 of 81



Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Limestone/DO, Acceptance Action Generic 1009G4DRLDAA is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 6249905, Project Item Line Number 0990, Material Set 624990596, Material 3099XX - See Remarks for Description of Material, Acceptance Action Generic 3099XX is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7011105, Project Item Line Number 3180, Material Set 701110596, Material 0701PLCSLT - Drilled Shaft CSL steel pipe, Acceptance Action Generic 0701PLCSLT is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7011105, Project Item Line Number 5013, Material Set 701110596, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7011110, Project Item Line Number 3480, Material Set 701111096, Material 0701PLCSLT - Drilled Shaft CSL steel pipe, Acceptance Action Generic 0701PLCSLT is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011110, Project Item Line Number 3480, Material Set 701111096, Material 0701PLCA - Casing for Drilled Shafts, Acceptance Action Generic 0701PLCA is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7011204, Project Item Line Number 3190, Material Set 701120496, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7011204, Project Item Line Number 5014, Material Set 701120496, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7011209, Project Item Line Number 3490, Material Set 701120996, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7019903, Project Item Line Number 1050, Material Set 7019903, Material 1010SGBF - Select Gran Backfill for Structural Sys, Acceptance Action Generic 1010SGBF is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7032003, Project Item Line Number 3000, Material Set 703200396, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Waiting on 28 day break	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7034003, Project Item Line Number 3280, Material Set 703400396, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Waiting on 28 day break	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7034003, Project Item Line Number 5026, Material Set 703400396, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7034003, Project Item Line Number 5026, Material Set 703400396, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7034212, Project Item Line Number 2670, Material Set 703421296, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Waiting on 28 day break	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7034212, Project Item Line Number 2670, Material Set 703421296, Material 0501CCB2MDA - Concrete, Modified B-2 w/Air, Acceptance Action Generic 0501CCB2MDA is insufficient.	Waiting on 28 day break	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7034212, Project Item Line Number 2670, Material Set 703421296, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Waiting on PAL	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7034610, Project Item Line Number 2690, Material Set 703461096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Waiting on 28 day break	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7034610, Project Item Line Number 2690, Material Set 703461096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Waiting on PAL	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7040103, Project Item Line Number 2700, Material Set 704010396, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7040103, Project Item Line Number 2700, Material Set 704010396, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Waiting on 28 day break	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7040103, Project Item Line Number 2700, Material Set 704010396, Material 4066SPSM - Special Provision Special Mortar, Acceptance Action Generic 4066SPSM is insufficient.	Waiting on 28 day break	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7040103, Project Item Line Number 2700, Material Set 704010396, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7040103, Project Item Line Number 2810, Material Set 704010396, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7040103, Project Item Line	Aggregate material testing needs to be reported	kloepj1	Overridden

Revision 4/1/2020 Page 12 of 81



Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Number 2810, Material Set 704010396, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7040103, Project Item Line Number 2810, Material Set 704010396, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Waiting on 28 day break	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7040103, Project Item Line Number 2810, Material Set 704010396, Material 4066SPSM - Special Provision Special Mortar, Acceptance Action Generic 4066SPSM is insufficient.	Waiting on 28 day break	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7049904, Project Item Line Number 2720, Material Set 7049904, Material 4066SPSM - Special Provision Special Mortar, Acceptance Action Generic 4066SPSM is insufficient.	Waiting on 28 day break	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7049904, Project Item Line Number 2720, Material Set 7049904, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7101000, Project Item Line Number 2730, Material Set 710100096, Material 1036RSSRECAB - Epoxy Ctd Sprl Stl Rein for Anch Bolts @, Acceptance Action Generic ReinforcingMisc is insufficient.	Waiting on PAL	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7101000, Project Item Line Number 5011, Material Set 710100096, Material 1036RSSRECAB - Epoxy Ctd Sprl Stl Rein for Anch Bolts @, Acceptance Action Generic ReinforcingMisc is insufficient.	Waiting on PAL	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7101000, Project Item Line Number 5015, Material Set 710100096, Material 1036RSSRECAB - Epoxy Ctd Sprl Stl Rein for Anch Bolts @, Acceptance Action Generic ReinforcingMisc is insufficient.	Waiting on PAL	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7101000, Project Item Line Number 5037, Material Set 710100096, Material 1036RSSRECAB - Epoxy Ctd Sprl Stl Rein for Anch Bolts @, Acceptance Action Generic ReinforcingMisc is insufficient.	Waiting on PAL	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7201000, Project Item Line Number 2940, Material Set 720100096, Material 1010SGBF - Select Gran Backfill for Structural Sys, Acceptance Action Generic 1010SGBF is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7201000, Project Item Line Number 2940, Material Set 720100096, Material 0720MSEW - MSE Wall System -Bridge Approved Design, Acceptance Action Generic 0720MSEW is insufficient.	Waiting on Bridge to report the accepted MSE wall system submittal	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7201000, Project Item Line Number 3430, Material Set 720100096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Waiting on 28 day break	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7201000, Project Item Line Number 3430, Material Set 720100096, Material 1052MSEWMETS - Metalic Reinforcement Strips for MSE, Acceptance Action Generic 1052MSEWMETS is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7201000, Project Item Line Number 3430, Material Set 720100096, Material 0720MSEW - MSE Wall System -Bridge Approved Design, Acceptance Action Generic 0720MSEW is insufficient.	Waiting on Bridge to report the accepted MSE wall system submittal	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7201000, Project Item Line Number 3450, Material Set 720100096, Material 0720MSEW - MSE Wall System -Bridge Approved Design, Acceptance Action Generic 0720MSEW is insufficient.	Waiting on Bridge to report the accepted MSE wall system submittal	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7201000, Project Item Line Number 3450, Material Set 720100096, Material 1052MSEWMETS - Metalic Reinforcement Strips for MSE, Acceptance Action Generic 1052MSEWMETS is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7201000, Project Item Line Number 3450, Material Set 720100096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Waiting on 28 day break	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7201300, Project Item Line Number 3400, Material Set 7201300, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Waiting on 28 day break	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7201300, Project Item Line Number 3400, Material Set 7201300, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7250415, Project Item Line Number 5047, Material Set 725041596, Material 1020CPCSZC.015 - CulvPipe Zn Ctd Corrug Stl 15" 375mm, Acceptance Action Generic 1020CPCSZC.015 is insufficient.	Waiting on shipping report	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7269922, Project Item Line Number 5025, Material Set 7269922, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Waiting on 28 day break	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7269922, Project Item Line Number 5025, Material Set 7269922, Material 0200XXCS - Compacted Soil for Subgrade or Embankment, Acceptance Action Generic 0200XXCS is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7269923, Project Item Line Number 5024, Material Set 726992396, Material 4028SPPV08 - 8" PVC Sewer Pipe, Acceptance Action Generic 4028SPPV08 is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7311053, Project Item Line Number 1190, Material Set 731105396, Material 1009G3DRLD - Agg for Drainage Gr3 Limestone/Dolomite, Acceptance Action Generic 1009G3DRLD is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden

Revision 4/1/2020 Page 13 of 81



Exceptions (Discrepancies) This Estimate Period

xceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7320618A, Project Item Line Number 5049, Material Set 7320618A96, Material 1032ESRCF - Conc End Section for Round Pipe, Acceptance Action Generic 1032ESRCF is insufficient.	Waiting on shipping report	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 8061017, Project Item Line Number 1320, Material Set 806101796, Material 0801FZ - Fertilizer, Acceptance Action Generic 0801FZ s insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 8061017, Project Item Line Number 1320, Material Set 806101796, Material 0805SD - Grass Seed -Seed, Acceptance Action Generic 0805SD is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 8061017, Project Item Line Number 1320, Material Set 806101796, Material 0802MLST - Mulch Straw (Vegetative Mulch), Acceptance Action Generic 0802MLST is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 9019901, Project Item Line Number 1780, Material Set 9019901, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient.	Planned quantity has not been reached/installed at this time	kloepj1	Overridden
estimate Exception Type: Insufficient Materials: Project J6l2222, Item 9020513, Project Item Line Aumber 1870, Material Set 902051396, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
stimate Exception Type: Insufficient Materials: Project J6I2222, Item 9022708, Project Item Line lumber 1910, Material Set 902270896, Material 0902TSXX - Traffic Signals Material, Acceptance Action seneric 0902TSXX is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
stimate Exception Type: Insufficient Materials: Project J6I2222, Item 9022708, Project Item Line umber 1910, Material Set 902270896, Material 0902TSBTZCAB - Bolts Galv Anchor for Traffic Signals, cceptance Action Generic 0902TSBTZCAB is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
stimate Exception Type: Insufficient Materials: Project J6l2222, Item 9022708, Project Item Line umber 1910, Material Set 902270896, Material 1092TSPS - Traffic Signal Post(s) - All Types, cceptance Action Generic 1092TSPS is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
stimate Exception Type: Insufficient Materials: Project J6I2222, Item 9023255, Project Item Line umber 1960, Material Set 902325596, Material 0902TSXX - Traffic Signals Material, Acceptance Action ieneric 0902TSXX is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
stimate Exception Type: Insufficient Materials: Project J6l2222, Item 9024283, Project Item Line lumber 1990, Material Set 902428396, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
stimate Exception Type: Insufficient Materials: Project J6I2222, Item 9028311, Project Item Line lumber 2060, Material Set 902831196, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
estimate Exception Type: Insufficient Materials: Project J6I2222, Item 9029100, Project Item Line Ilumber 2100, Material Set 902910096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance action Generic 0501CCBA is insufficient.	Waiting on 28 day break	kloepj1	Overridden
stimate Exception Type: Insufficient Materials: Project J6l2222, Item 9031020, Project Item Line lumber 2210, Material Set 903102096, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance action Generic 0501CCB2.A is insufficient.	Waiting on 28 day break	kloepj1	Overridden
stimate Exception Type: Insufficient Materials: Project J6l2222, Item 9031020, Project Item Line lumber 2210, Material Set 903102096, Material 1005FACCNSCA - Natural Sand for Conc Class A, cceptance Action Generic 1005FACCNSCA is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
estimate Exception Type: Insufficient Materials: Project J6l2222, Item 9039901, Project Item Line Aumber 2330, Material Set 9039901, Material 0903HSSBPSST - Slip Base PSST Posts, Acceptance Action Generic 0903HSSBPSST is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 9039901, Project Item Line lumber 2330, Material Set 9039901, Material 1080BRM - Bridge Material, Acceptance Action Generic 080BRM is insufficient.	Waiting on Bridge to report material	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 9039901, Project Item Line lumber 2330, Material Set 9039901, Material 0903HSOHTR - Overhead Truss Sign, Acceptance Action Generic 0903HSOHTR is insufficient.	Waiting on Bridge to report material	kloepj1	Overridden
stimate Exception Type: Item Overrun: Contract 200515-F15, Contract Project J6l2222, Project Item ine Number 0710, Contract Line Item Number 0710, Item 6173600D, Minor Item.	Waiting on a change order to pay this item	kloepj1	Acknowledged
stimate Exception Type: Item Overrun: Contract 200515-F15, Contract Project J6l2222, Project Item ine Number 2020, Contract Line Item Number 2020, Item 9027300, Minor Item.	Waiting on a change order to pay this item	kloepj1	Acknowledged
stimate Exception Type: Item Overrun: Contract 200515-F15, Contract Project J6l2222, Project Item ine Number 2080, Contract Line Item Number 2080, Item 9028811, Minor Item.	Waiting on a change order to pay this item	kloepj1	Acknowledged

Revision 4/1/2020 Page 14 of 81



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note: Posted Q	uantities	and valu	ies are	based on I	Report Generated date and can differ from the posted am	ount at the	time the Es	stimate was	Genera	ted.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200515-F15	J6I2222	0001	0010	2013000	CLEARING AND GRUBBING	2.00	0.00	2.00	ACRE	2.00	\$25,000.00	\$50,000.00
		0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.52	\$600,000.00	\$312,000.00
		0001	0025	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	155.00	0.00	155.00	SQFT	155.00	\$140.50	\$21,777.50
		0001	0040	2029901	MISC.REMOVAL OF ACM CONDUIT SYSTEM - TELEPHONE	1.00	0.00	1.00	LS	1.00	\$13,500.00	\$13,500.00
		0001	0045	2029903	MISC.MISCELLANEOUS ACM REMOVAL	80.00	0.00	80.00	LF	0.00	\$48.00	\$0.00
		0001	0050	2031000	CLASS A EXCAVATION	153,414.00	0.00	153,414.00	CUYD	142,072.00	\$15.00	\$2,131,080.00
		0001	0060	2036000	COMPACTING EMBANKMENT	106,637.00	11,081.00	117,718.00	CUYD	117,718.00	\$3.00	\$353,154.00
		0001	0070	2037075	COMPACTING IN CUT	45.00	0.00	45.00	STA	0.00	\$1.00	\$0.00
		0001	0080	2039901	MISC.STOCK PILE REMOVAL AT OLD 21ST STREET FOR MSD	1.00	0.00	1.00	LS	0.75	\$85,000.00	\$63,750.00
		0001	0090	2039907	MISC.Lightweight Fill	16,413.00	-16,413.00	0.00	CUYD	0.00	\$61.50	\$0.00
		0001	0100	2042010	SETTLEMENT GAUGE	10.00	0.00	10.00	EA	10.00	\$1,500.00	\$15,000.00
		0001	0110	2043010	PORE PRESSURE MEASURING DEVICE	3.00	0.00	3.00	EA	3.00	\$4,000.00	\$12,000.00
		0001	0120	2063000	CLASS 3 EXCAVATION	2,716.00	1,201.00	3,917.00	CUYD	2,882.00	\$15.00	\$43,230.00
		0001	0130	2071000	LINEAR GRADING CLASS 1	11.00	0.00	11.00	STA	3.00	\$800.00	\$2,400.00
		0001	0140	3040143	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	1,152.00	-64.00	1,088.00	SQYD	143.00	\$11.00	\$1,573.00
		0001	0150	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	72.00	0.00	72.00	SQYD	72.00	\$23.00	\$1,656.00
		0001	0160	3105003	GRAVEL (A) OR CRUSHED STONE (B)	540.00	2,888.00	3,428.00	SQYD	2,888.00	\$12.00	\$34,656.00
		0001	0170	4011207	BITUMINOUS PAVEMENT MIXTURE PG70-22, (BP-1)	1,950.80	0.00	1,950.80	TONS	0.00	\$77.75	\$0.00
		0001	0180	4030109	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125CLP MIX)	376.20	0.00	376.20	TONS	0.00	\$125.00	\$0.00
		0001	0190	4071005	TACK COAT	1,660.00	0.00	1,660.00	GAL	0.00	\$3.50	\$0.00
		0001	0200	5021108	CONCRETE PAVEMENT (8 IN. NON-REINF)	366.30	0.00	366.30	SQYD	293.20	\$49.00	\$14,366.80
		0001	0210	5021340	TYPE A2 SHOULDER	1,563.20	0.00	1,563.20	SQYD	519.96	\$36.00	\$18,718.56
		0001	0220	5041000	CONCRETE APPROACH PAVEMENT	105.20	0.00	105.20	SQYD	0.00	\$150.00	\$0.00
		0001	0230	6039901	WATER	1.00	0.00	1.00	LS	1.00	\$30,000.00	\$30,000.00
		0001	0240	6039901	WATER	1.00	0.00	1.00	LS	0.00	\$12,000.00	\$0.00
		0001	0250	6039903	WATER	20.00	0.00	20.00	LF	20.00	\$2,000.00	\$40,000.00
		0001	0260	6039903	WATER	150.00	7.00	157.00	LF	157.00	\$2,000.00	\$314,000.00
		0001	0270	6039903	WATER	570.00	-179.80	390.20	LF	390.20	\$400.00	\$156,080.00
		0001	0280	6039903	WATER	100.00	0.00	100.00	LF	100.00	\$400.00	\$40,000.00
		0001	0290	6049901	MISC.INSPECTION OF 9X7 CONCRETE ARCH SEWER	1.00	0.00	1.00	LS	0.00	\$6,000.00	\$0.00
		0001	0300	6049903	MISC.MODOT MANHOLE - ADJUST TO GRADE	24.00	0.00	24.00	LF	24.00	\$1,000.00	\$24,000.00
		0001	0310	6049903	MISC.MSD MANHOLE - ADJUST TO GRADE, 5' TO 10' RANGE	25.00	0.00	25.00	LF	18.40	\$1,000.00	\$18,400.00
		0001	0320	6049903	MISC.MSD MANHOLE - ADJUST TO GRADE, 10' TO 15' RANGE	23.00	0.00	23.00	LF	0.00	\$1,000.00	\$0.00
		0001	0330	6049903	MISC.MSD MANHOLE - ADJUST TO GRADE, 15' TO 20' RANGE	37.00	0.00	37.00	LF	18.20	\$1,000.00	\$18,200.00
		0001	0340	6049903	MISC.MSD MANHOLE - ADJUST TO GRADE, 25' TO 30' RANGE	28.00	0.00	28.00	LF	0.00	\$1,000.00	\$0.00
		0001	0350	6071012A	CHAIN-LINK FENCE (60 IN.)	586.00	0.00	586.00	LF	0.00	\$28.00	\$0.00
		0001	0360	6071040	DRIVE GATE (CHAIN-LINK)	2.00	0.00	2.00	EA	0.00	\$1,200.00	\$0.00
		0001	0370	6071050	CHAIN-LINK FENCE (RETAINING WALLS)	1,800.00	-963.00	837.00	LF	480.00	\$24.00	\$11,520.00
		0001	0380	6071102	MODIFIED CONCRETE GUTTER TYPE B	2,038.00	-1,085.00	953.00	LF	458.00	\$34.00	\$15,572.00
		0001	0390	6081012	TRUNCATED DOMES	60.00	0.00	60.00	SQFT	0.00	\$35.00	\$0.00
		0001	0400	6083006	6 IN. CONCRETE MEDIAN STRIP	529.80	0.00	529.80	SQYD	0.00	\$100.00	\$0.00
		0001	0410	6085008	PAVED APPROACH, 8 IN.	72.30	0.00	72.30	SQYD	72.30	\$125.00	\$9,037.50
		0001	0420	6086004	CONCRETE SIDEWALK, 4 IN.	1,152.10	-63.80	1,088.30	SQYD	142.40	\$51.00	\$7,262.40
		0001	0430	6086007	CONCRETE SIDEWALK, 7 IN.	15.30	-15.30	0.00	SQYD	0.00	\$65.00	\$0.00
		0001	0440	6089902	MISC.ADA CURB RAMP	16.00	0.00	16.00	EA	4.00	\$3,550.00	\$14,200.00
		0001	0450	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	301.00	0.00	301.00	LF	113.00	\$45.00	\$5,085.00
		0001	0460	6091042	CONCRETE GUTTER TYPE B	2,007.00	1,085.00	3,092.00	LF	268.00	\$30.00	\$8,040.00

Revision 4/1/2020 Page 15 of 81



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Report Generated date and can differ from the posted am Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200515-F15	J6I2222	0001	0470	6091060	PAVED DITCH	210.30	0.00	210.30	SQYD	0.00	\$81.00	\$0.00
		0001	0480	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	203.00	1,718.00	1,921.00	LF	181.00	\$15.00	\$2,715.00
		0001	0490	6096020	FURNISHING TYPE 2 ROCK DITCH LINER	24.00	233.40	257.40	CUYD	210.50	\$100.00	\$21,050.00
		0001	0500	6096042	PLACING TYPE 2 ROCK DITCH LINER	24.00	233.40	257.40	CUYD	210.50	\$100.00	\$21,050.00
		0001	0510	6097000	ROCK LINING	2.00	10.00	12.00	CUYD	0.00	\$1,000.00	\$0.00
		0001	0515	6099903	MISC.MODIFIED INTEGRAL CURB (2 IN. HEIGHT) TYPE A	320.00	0.00	320.00	LF	122.00	\$50.00	\$6,100.00
		0001	0520	6113020	FURNISHING TYPE 2 ROCK BLANKET	567.00	0.00	567.00	CUYD	0.00	\$48.00	\$0.00
		0001	0530	6113040	PLACING TYPE 2 ROCK BLANKET	567.00	0.00	567.00	CUYD	0.00	\$21.00	\$0.00
		0001	0540	6116010A	SLOPE PROTECTION	1.00	-1.00	0.00	SQYD	0.00	\$300.00	\$0.00
		0001	0550	6119907	MISC.Furnishing Modified Rock Blanket	1,151.00	0.00	1,151.00	CUYD	0.00	\$50.00	\$0.00
		0001	0560	6119907	MISC.Placing Modified Rock Blanket	1,151.00	0.00	1,151.00	CUYD	0.00	\$21.00	\$0.00
		0001	0570	6122012	IMPACT ATTENUATOR 55 MPH (SAND BARREL ARRAY)	5.00	0.00	5.00	EA	4.00	\$2,823.00	\$11,292.00
		0001	0580	6122020	REPLACEMENT SAND BARREL	12.00	0.00	12.00	EA	5.00	\$431.00	\$2,155.00
		0001	0590	6122030	IMPACT ATTENUATOR (RELOCATION)	9.00	0.00	9.00	EA	2.00	\$877.00	\$1,754.00
		0001	0600	6133020	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	148.50	0.00	148.50	TONS	0.00	\$62.00	\$0.00
		0001	0610	6133021	REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	528.50	0.00	528.50	SQYD	0.00	\$58.75	\$0.00
		0001	0620	6141024	GRATE AND BEARING PLATE (5 FT. X 3 FT. OR 1524 MM X 914 MM)	10.00	2.00	12.00	EA	4.00	\$1,400.00	\$5,600.00
		0001	0630	6141120	CURVED VANE GRATE AND FRAME (2 FT. X 2 FT. OR 600MM X 600MM)	72.00	-72.00	0.00	EA	0.00	\$700.00	\$0.00
		0001	0640	6149902	MISC.Parallel Grate and Bearing Plate (2 FT.x2FT.)	67.00	-57.00	10.00	EA	1.00	\$700.00	\$700.00
		0001	0650	6169901	MISC.TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.75	\$465,000.00	\$348,750.00
		0001	0660	6169902	MISC.MSD Manhole Frame and Cover	17.00	-17.00	0.00	EA	0.00	\$400.00	\$0.00
		0001	0670	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN (CONTRACTOR FURNISHED AND RETAINED)	8.00	0.00	8.00	EA	7.00	\$3,500.00	\$24,500.00
		0001	0675	6173000	CONCRETE TRAFFIC BARRIER, TYPE C	254.00	357.00	611.00	LF	485.00	\$145.00	\$70,325.00
		0001	0680	6173100	CONCRETE TRAFFIC BARRIER, TYPE D	1,787.00	-1,185.00	602.00	LF	0.00	\$90.00	\$0.00
		0001	0690	6173102	CONCRETE TRAFFIC BARRIER, TYPE D (RETAINING WALL)	2,413.00	1,085.00	3,498.00	LF	2,289.00	\$85.00	\$194,565.00
		0001	0700	6173103	CONCRETE TRAFFIC BARRIER, TYPE D (MOMENT SLAB)	440.00	0.00	440.00	LF	0.00	\$110.00	\$0.00
		0001	0710	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	2,488.00	0.00	2,488.00	LF	2,713.50	\$25.90	\$70,279.65
		0001	0720	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	4,013.00	0.00	4,013.00	LF	1,112.50	\$11.50	\$12,793.75
		0001	0730	6179903	MISC.MODIFIED BARRIER WALL	315.00	0.00	315.00	LF	0.00	\$300.00	\$0.00
		0001	0740	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$2,269,999.84	\$0.00
		0001	0741	6181000	MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$2,162,092.84	\$2,162,092.84
		0001	0750	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	2.00	0.00	2.00	EA	0.00	\$600.00	\$0.00
		0001	0760	6189901	MISC.TEMPORARY RAILROAD CROSSING	1.00	0.00	1.00	LS	0.00	\$30,000.00	\$0.00
		0001	0765	6189916	MISC.ACCELERATING THE COMPLETION OF WORK REQUIRING RAILROAD FLAGGERS (INCENTIVE/DISINCENTIVE CLAUSE)	1,000.00	0.00	1,000.00	DLR	0.00	\$0.00	\$0.00
		0001	0770	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	505.00	0.00	505.00	LF	0.00	\$25.00	\$0.00
		0001	0780	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	19.00	0.00	19.00	EA	0.00	\$320.00	\$0.00
		0001	0790	6200027	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT	7.00	0.00	7.00	EA	0.00	\$450.00	\$0.00
		0001	0800	6200030	PREFORMED THERMOPLASTIC PAVEMENT MARKING, WORD (ONLY)	9.00	0.00	9.00	EA	0.00	\$450.00	\$0.00
		0001	0810	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	114.00	0.00	114.00	EA	0.00	\$200.00	\$0.00
		0001	0820	6200042	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	14.00	0.00	14.00	EA	0.00	\$50.00	\$0.00
		0001	0830	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	21,905.00	0.00	21,905.00	LF	0.00	\$0.50	\$0.00
		0001	0840	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	12,373.00	0.00	12,373.00	LF	0.00	\$0.50	\$0.00
		0001	0850	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	4,999.00	0.00	4,999.00	LF	0.00	\$1.00	\$0.00
		0001	0860	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING	9,364.00	0.00	9,364.00	LF	0.00	\$0.50	\$0.00

Page 16 of 81 Revision 4/1/2020



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note: Posted Qi	uantities	and Valu	ies are	based on F	Report Generated date and can differ from the posted am	ount at the	time the Es	timate was	Generat	ed.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200515-F15	J6I2222				PAINT, TYPE P BEADS					,		
		0001	0870	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT. TYPE P BEADS	3,485.00	0.00	3,485.00	LF	0.00	\$0.50	\$0.00
		0001	0880	6206124A	24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING	91.00	0.00	91.00	LF	0.00	\$10.00	\$0.00
		0001	0890	6206125A	PAINT, TYPE P BEADS 24 IN. YELLOW STANDARD WATERBORNE PAVEMENT	84.00	0.00	84.00	LF	0.00	\$10.00	\$0.00
		0001	0900	6207001	MARKING PAINT, TYPE P BEADS PAVEMENT MARKING REMOVAL	7,291.00	0.00	7,291.00	LF	0.00	\$1.00	\$0.00
		0001	0910	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	56.00	0.00	56.00	EA	0.00	\$50.00	\$0.00
		0001	0920	6209902	2 MISC.ISLAND TUBULAR MARKER	8.00	0.00	8.00	EA	0.00	\$110.00	\$0.00
		0001	0930	6209902	MISC.PREFORMED THERMOPLASTIC PAVEMENT MARKING,	8.00	0.00	8.00	EA	0.00	\$2,000.00	\$0.00
		0001	0940	6209902	LANE REDUCTION ARROW MISC.TIER TWO INLAID PAVEMENT MARKER SYSTEM	8.00	0.00	8.00	EA	0.00	\$4,475.00	\$0.00
		0001	0950	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF	2,356.00	0.00	2,356.00	SQYD	0.00	\$6.75	\$0.00
		0001	0960	6221003	SURFACING (3 IN. THICK OR LESS) COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF	10,196.00	0.00	10,196.00	SQYD	0.00	\$3.85	\$0.00
		0001	0970	6224010	SURFACING (GREATER THAN 3 IN. THICK) MODIFIED COLDMILLING (DEPTH TRANSITIONS)	150.00	0.00	150.00	SQYD	0.00	\$13.50	\$0.00
		0001	0980	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	3,917.00	172.10	4,089.10	SQYD	906.40	\$3.00	\$2,719.20
		0001	0990	6249905	MISC.Miscellaneous Granular Drainage Blanket	2,115.00	286.00	2,401.00	SQYD	2,401.00	\$15.50	\$37,215.50
		0001	1000	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.60	\$125,000.00	\$75,000.00
		0001	1010	7011105	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	30.00	0.00	30.00	LF	0.00	\$415.00	\$0.00
		0001	1020	7011107	DRILLED SHAFTS (4 FT. 6 IN. DIA.)	39.00	0.00	39.00	LF	0.00	\$415.00	\$0.00
		0001	1030	7011207	ROCK SOCKETS (4 FT 6 IN. DIA.)	6.00	0.00	6.00	LF	0.00	\$415.00	\$0.00
		0001	1040	7011600	SONIC LOGGING TESTING	1.00	0.00	1.00	EA	0.00	\$1,000.00	\$0.00
		0001	1050	7019903	MISC.Miscellaneous Stone Columns	6,535.00	-5,583.00	952.00	LF	952.00	\$25.00	\$23,800.00
		0001	1060	7033009	AESTHETIC CONCRETE STAIN	1.00	0.00	1.00	LS	0.00	\$6,110.88	\$0.00
		0001	1080	7061000	REINFORCING STEEL	5,740.00	0.00	5,740.00	LB	0.00	\$1.60	\$0.00
		0001	1090	7201000	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	3,394.00	0.00	3,394.00	SQFT	3,394.00	\$60.00	\$203,640.00
		0001	1100	7201200	SELECT GRANULAR BACKFILL FOR STRUCTURAL SYSTEMS	12,416.00	-478.00	11,938.00	CUYD	11,052.00	\$30.00	\$331,560.00
		0001	1110	7261015	15 IN. PIPE GROUP A	3,631.00	-921.00	2,710.00	LF	1,535.00	\$70.00	\$107,450.00
		0001	1120	7261018	18 IN. PIPE GROUP A	1,252.00	-169.00	1,083.00	LF	410.00	\$80.00	\$32,800.00
		0001	1130	7261024	24 IN. PIPE GROUP A	118.00	-118.00	0.00	LF	0.00	\$135.00	\$0.00
		0001	1140	7261030	30 IN. PIPE GROUP A	298.00	67.00	365.00	LF	365.00	\$250.00	\$91,250.00
		0001	1150	7261036	36 IN. PIPE GROUP A	54.00	0.00	54.00	LF	54.00	\$400.00	\$21,600.00
		0001	1160	7279901	MISC.MSD SPECIAL DRAINAGE STRUCTURE #"301"	1.00	0.00	1.00	LS	1.00	\$55,000.00	\$55,000.00
		0001	1170	7311022	PRECAST CONCRETE DROP INLET 2 FT X 2 FT	57.00	0.00	57.00	FT	20.00	\$350.00	\$7,000.00
		0001	1180	7311042	PRECAST CONCRETE DROP INLET 4 FT X 2 FT	178.00	-11.00	167.00	FT	108.00	\$450.00	\$48,600.00
		0001	1190	7311053	PRECAST CONCRETE DROP INLET 5 FT X 3 FT	56.00	18.00	74.00	FT	55.00	\$650.00	\$35,750.00
		0001	1200	7319913	MISC.MSD Standard 60" Manhole	56.00	1.00	57.00	FT	57.00	\$510.00	\$29,070.00
		0001	1210	7319913	MISC.MSD Standard Line 48" Manhole	76.00	7.00	83.00	FT	58.00	\$350.00	\$20,300.00
		0001	1220	7320615A	15 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	1.00	8.00	9.00	EA	8.00	\$800.00	\$6,400.00
		0001	1230	7320624A	24 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	2.00	-2.00	0.00	EA	0.00	\$1,000.00	\$0.00
		0001	1240	7320630A	30 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	1.00	0.00	1.00	EA	1.00	\$1,500.00	\$1,500.00
		0001	1245	8031000A	TURF TYPE TALL FESCUE SODDING	1,242.00	0.00	1,242.00	SQYD	0.00	\$8.50	\$0.00
		0001	1260	8059919	MISC.WARM OR COOL SEASON MIXTURES	9.00	0.00	9.00	ACRE	0.00	\$1,975.00	\$0.00
		0001	1270	8061003	SEDIMENT TRAP EXCAVATION	57.00	0.00	57.00	CUYD	0.00	\$25.00	\$0.00
		0001	1280	8061004	SEDIMENT TRAP ROCK	7.00	0.00	7.00	CUYD	0.00	\$100.00	\$0.00
		0001	1290	8061005	ROCK DITCH CHECK	2,613.00	0.00	2,613.00	LF	24.00	\$10.50	\$252.00
		0001	1300	8061007A	CURB INLET CHECK	111.00	0.00	111.00	EA	0.00	\$115.00	\$0.00
		0001	1310	8061016	SEDIMENT REMOVAL	267.00	0.00	267.00	CUYD	217.00	\$25.00	\$5,425.00

Revision 4/1/2020 Page 17 of 81



Total Paid / All Items / All Estimates (Including this Estimate)

0001 0001 0001 0002 0002 0002 0003 0003	1330 1340 1350 1360 1370 1380 1390 1400 1410 1420 1430 1440	8061017 8061019 8064128 3030600 3030610A 4030419 3030600 3030610A 5021332 4010150 6091010 5021340 6092011	TEMPORARY SEEDING AND MULCHING SILT FENCE TYPE 1 TURF REINFORCEMENT MAT FURNISHING ROCK BASE MATERIAL PLACING ROCK BASE 9 INCHES, ASPHALTIC CONCRETE PAVEMENT SP125CLP FURNISHING ROCK BASE MATERIAL PLACING ROCK BASE CONCRETE PAVEMENT (8 1/2 IN. NON-REINFORCED, 15 FT. JOINTS) TYPE A2 SHOULDER CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S TYPE A2 SHOULDER	14.00 8,207.00 913.00 3,355.00 2,073.00 3,363.00 2,073.00 2,073.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	14.00 8,207.00 913.00 3,355.00 2,073.00 3,363.00 2,073.00	ACRE LF SQYD SQYD SQYD SQYD SQYD SQYD SQYD SQYD	0ty 1.60 2,308.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	\$1,500.00 \$2,25 \$5,15 \$0.00 \$0.00 \$10.50 \$5,50	\$2,400.00 \$5,193.00 \$0.00 \$0.00 \$0.00
0001 0002 0002 0002 0003 0003 0003 0004 0004 0005 0005 0006	1340 1350 1360 1370 1380 1390 1400 1410 1420 1430 1440	8064128 3030600 3030610A 4030419 3030600 3030610A 5021332 4010150 6091010 5021340	TYPE 1 TURF REINFORCEMENT MAT FURNISHING ROCK BASE MATERIAL PLACING ROCK BASE 9 INCHES, ASPHALTIC CONCRETE PAVEMENT SP125CLP FURNISHING ROCK BASE MATERIAL PLACING ROCK BASE CONCRETE PAVEMENT (8 1/2 IN. NON-REINFORCED, 15 FT. JOINTS) TYPE A2 SHOULDER CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	913.00 3,355.00 3,355.00 2,073.00 3,363.00 2,073.00	0.00 0.00 0.00 0.00 0.00 0.00	913.00 3,355.00 3,355.00 2,073.00 3,363.00 3,363.00	SQYD SQYD SQYD SQYD SQYD SQYD	0.00 0.00 0.00 0.00 0.00	\$5.15 \$0.00 \$0.00 \$0.00 \$10.50	\$0.00 \$0.00 \$0.00
0002 0002 0002 0003 0003 0003 0004 0004 0005 0005 0006	1350 1360 1370 1380 1390 1400 1410 1420 1430 1440	3030600 3030610A 4030419 3030600 3030610A 5021332 4010150 6091010 5021340	FURNISHING ROCK BASE MATERIAL PLACING ROCK BASE 9 INCHES, ASPHALTIC CONCRETE PAVEMENT SP125CLP FURNISHING ROCK BASE MATERIAL PLACING ROCK BASE CONCRETE PAVEMENT (8 1/2 IN. NON-REINFORCED, 15 FT. JOINTS) TYPE A2 SHOULDER CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	3,355.00 3,355.00 2,073.00 3,363.00 3,363.00 2,073.00	0.00 0.00 0.00 0.00 0.00	3,355.00 3,355.00 2,073.00 3,363.00 3,363.00	SQYD SQYD SQYD SQYD SQYD	0.00 0.00 0.00 0.00	\$0.00 \$0.00 \$0.00 \$10.50	\$0.0 \$0.0
0002 0002 0003 0003 0003 0004 0004 0005 0005	1360 1370 1380 1390 1400 1410 1420 1430 1440	3030610A 4030419 3030600 3030610A 5021332 4010150 6091010 5021340	PLACING ROCK BASE 9 INCHES, ASPHALTIC CONCRETE PAVEMENT SP125CLP FURNISHING ROCK BASE MATERIAL PLACING ROCK BASE CONCRETE PAVEMENT (8 1/2 IN. NON-REINFORCED, 15 FT. JOINTS) TYPE A2 SHOULDER CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	3,355.00 2,073.00 3,363.00 3,363.00 2,073.00	0.00 0.00 0.00 0.00	3,355.00 2,073.00 3,363.00 3,363.00	SQYD SQYD SQYD SQYD	0.00 0.00 0.00	\$0.00 \$0.00 \$10.50	\$0.0 \$0.0
0002 0003 0003 0003 0004 0004 0005 0005 0006	1370 1380 1390 1400 1410 1420 1430 1440 1450	4030419 3030600 3030610A 5021332 4010150 6091010 5021340	9 INCHES, ASPHALTIC CONCRETE PAVEMENT SP125CLP FURNISHING ROCK BASE MATERIAL PLACING ROCK BASE CONCRETE PAVEMENT (8 1/2 IN. NON-REINFORCED, 15 FT. JOINTS) TYPE A2 SHOULDER CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	2,073.00 3,363.00 3,363.00 2,073.00	0.00 0.00 0.00 0.00	2,073.00 3,363.00 3,363.00	SQYD SQYD SQYD	0.00 0.00 0.00	\$0.00 \$10.50	\$0.0
0003 0003 0003 0004 0004 0005 0005 0006	1380 1390 1400 1410 1420 1430 1440	3030600 3030610A 5021332 4010150 6091010 5021340	FURNISHING ROCK BASE MATERIAL PLACING ROCK BASE CONCRETE PAVEMENT (8 1/2 IN. NON-REINFORCED, 15 FT. JOINTS) TYPE A2 SHOULDER CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	3,363.00 3,363.00 2,073.00	0.00 0.00 0.00	3,363.00 3,363.00	SQYD	0.00	\$10.50	
0003 0003 0004 0004 0005 0005 0006	1390 1400 1410 1420 1430 1440	3030610A 5021332 4010150 6091010 5021340	PLACING ROCK BASE CONCRETE PAVEMENT (8 1/2 IN. NON-REINFORCED, 15 FT. JOINTS) TYPE A2 SHOULDER CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	3,363.00	0.00	3,363.00	SQYD	0.00		\$0.0
0003 0004 0004 0005 0005 0006	1400 1410 1420 1430 1440 1450	5021332 4010150 6091010 5021340	CONCRETE PAVEMENT (8 1/2 IN. NON-REINFORCED, 15 FT. JOINTS) TYPE A2 SHOULDER CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	2,073.00	0.00				\$5.50	
0004 0004 0005 0005 0006	1410 1420 1430 1440 1450	4010150 6091010 5021340	JOINTS) TYPE A2 SHOULDER CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S			2,073.00	SQYD			\$0.0
0004 0005 0005 0006	1420 1430 1440 1450	6091010 5021340	TYPE A2 SHOULDER CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	206.10				0.00	\$51.00	\$0.0
0005 0005 0006	1430 1440 1450	5021340			0.00	206.10	SQYD	0.00	\$0.00	\$0.0
0005 0006 0006	1440 1450		TYPE A2 SHOULDER	304.00	0.00	304.00	LF	0.00	\$0.00	\$0.0
0006	1450	6092011		206.10	0.00	206.10	SQYD	0.00	\$35.50	\$0.0
0006			INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	304.00	0.00	304.00	LF	0.00	\$20.00	\$0.0
		3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	20,740.00	0.00	20,740.00	SQYD	0.00	\$0.00	\$0.0
0006	1460	4039905	MISC.11.5 INCHES, ASPHALTIC CONCRETE PAVEMENT	10,939.00	0.00	10,939.00	SQYD	0.00	\$0.00	\$0.0
0000	1470	4039905	SP125CLP MISC.9.5 INCHES, ASPHALTIC CONCRETE PAVEMENT	6,859.00	0.00	6.859.00	SQYD	0.00	\$0.00	\$0.00
			SP125CLP			.,				
0006		6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	2,017.00	0.00	2,017.00	LF	0.00	\$0.00	\$0.0
0007		3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	20,910.00	-323.00	20,587.00	SQYD	9,214.47	\$6.50	\$59,894.0
0007	1500	5021308	JOINTS)	6,859.00	0.00	6,859.00	SQYD	3,055.60	\$51.00	\$155,835.6
0007	1510	5021309	CONCRETE PAVEMENT (9 IN. NON-REINFORCED 15 FT. JOINTS)	10,939.00	-323.00	10,616.00	SQYD	2,978.20	\$54.00	\$160,822.8
0007	1520	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	2,017.00	-1,225.00	792.00	LF	210.00	\$15.00	\$3,150.0
0008	1530	4010150	TYPE A2 SHOULDER	3,806.80	0.00	3,806.80	SQYD	0.00	\$0.00	\$0.0
0008	1540	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	3,319.00	0.00	3,319.00	LF	0.00	\$0.00	\$0.0
0009	1550	5021340	TYPE A2 SHOULDER	3,806.80	0.00	3,806.80	SQYD	2,159.77	\$35.00	\$75,591.9
0009	1560	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	3,319.00	-2,667.00	652.00	LF	512.00	\$15.00	\$7,680.0
0010	1570	6061060	MGS GUARDRAIL	3,813.00	-62.00	3,751.00	LF	463.00	\$19.00	\$8,797.0
0010	1580	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	2.00	0.00	2.00	EA	0.00	\$2,850.00	\$0.0
0010	1590	6061069	MGS BRIDGE APPROACH TRANSITION SECTION	2.00	0.00	2.00	EA	0.00	\$2,800.00	\$0.0
0010	1600	6061070	MGS VERTICAL CONCRETE BARRIER TRANSITION	11.00	0.00	11.00	EA	4.00	\$2,750.00	\$11,000.0
0010	1610	6061080	MGS END ANCHOR	8.00	0.00	8.00	EA	1.00	\$1,000.00	\$1,000.0
0010	1620	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	12.00	0.00	12.00	EA	4.00	\$2,600.00	\$10,400.0
0010	1630	6063019	TYPE E CRASHWORTHY END TERMINAL	1.00	0.00	1.00	EA	0.00	\$27,500.00	\$0.0
0020	1640	9011330	LUMINAIRE, 1000 WATT HIGH PRESSURE SODIUM HIGH MAST	16.00	0.00	16.00	EA	0.00	\$1,018.00	\$0.0
0020	1650	9013002	CONDUIT, 2 IN. RIGID, IN TRENCH	26.00	0.00	26.00	LF	0.00	\$10.45	\$0.0
0020	1660	9013003	CONDUIT, 3 IN. RIGID, IN TRENCH	282.00	0.00	282.00	LF	120.00	\$11.00	\$1,320.0
0020	1670	9013004	CONDUIT, 4 IN. RIGID, IN TRENCH	23.00	0.00	23.00	LF	0.00	\$12.35	\$0.0
0020	1680	9014004	CONDUIT, 4 IN. RIGID, PUSHED	339.00	0.00	339.00	LF	0.00	\$26.60	\$0.0
0020	1690	9015010	TRENCHING TYPE I	2,136.00	0.00	2,136.00	LF	0.00	\$3.80	\$0.0
0020	1700	9015020	TRENCHING TYPE II	237.00	0.00	237.00	LF	0.00	\$3.80	\$0.0
0020	1710	9016110	PULL BOX, PREFORMED CLASS 1	15.00	0.00	15.00	EA	4.00	\$765.00	\$3,060.0
0020	1720	9016112	PULL BOX, PREFORMED CLASS 3	2.00	0.00	2.00	EA	1.00	\$1,343.00	\$1,343.0
0020	1730	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	360.00	0.00	360.00	LF	0.00	\$0.55	\$0.0
0020	1740	9017401	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE	800.00	0.00	800.00	LF	0.00	\$6.00	\$0.0
0020	1750	9017404	NEUTRAL, 2 AWG CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE	2,190.00	0.00	2,190.00	LF	0.00	\$3.60	\$0.0
	1760	9017407	NEUTRAL, 6 AWG CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE	1,010.00	0.00		LF			\$0.0
	0007 0008 0008 0009 0009 0010 0010 0010 0010	0007 1510 0007 1520 0008 1530 0008 1540 0009 1550 0009 1560 0010 1570 0010 1580 0010 1690 0010 1610 0010 1620 0010 1630 0020 1650 0020 1660 0020 1670 0020 1690 0020 1700 0020 1720 0020 1730 0020 1740 0020 1750	0007 1510 5021309 0007 1520 6092011 0008 1530 4010150 0008 1540 6091010 0009 1550 5021340 0009 1560 6092011 0010 1570 6061060 0010 1580 6061068 0010 1590 6061069 0010 1600 6061070 0010 1610 6063014 0010 1620 6063014 0010 1630 6063019 0020 1640 9013002 0020 1650 9013002 0020 1660 9013003 0020 1660 9013004 0020 1680 9014004 0020 1690 9015010 0020 1700 9015020 0020 1770 9016110 0020 1720 9016112 0020 1730 9017110 <td< td=""><td> JOINTS 1510 5021309 CONCRETE PAVEMENT (9 IN. NON-REINFORCED 15 FT. JOINTS) 1520 6092011 INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A 1530 4010150 TYPE A2 SHOULDER 1540 6091010 CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S 1550 5021340 TYPE A2 SHOULDER 1550 5021340 TYPE A2 SHOULDER 1550 6092011 INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A 1550 6061060 MGS GUARDRAIL 1570 6061060 MGS GUARDRAIL 1570 6061060 MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB) 1590 6061069 MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB) 1600 6061070 MGS VERTICAL CONCRETE BARRIER TRANSITION 1610 6061080 MGS END ANCHOR 1620 6063014 TYPE A CRASHWORTHY END TERMINAL (MASH) 1630 6063014 TYPE A CRASHWORTHY END TERMINAL (MASH) 1630 6063019 TYPE E CRASHWORTHY END TERMINAL (MASH) 1630 6063019 TYPE E CRASHWORTHY END TERMINAL 1630 1660 9013002 1670 9013002 CONDUIT, 2 IN. RIGID, IN TRENCH 1670 9013004 CONDUIT, 3 IN. RIGID, IN TRENCH 1670 9013004 CONDUIT, 4 IN. RIGID, IN TRENCH 1670 9015020 TRENCHING TYPE II 1670 9015020 TRENCHING TYPE II 1670 9016110 PULL BOX, PREFORMED CLASS 1 1670 9016112 PULL BOX, PREFORMED CLASS 3 1670 9017404 CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE 1670 9017404 CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE 1670 1670 9017404 CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE 1670 1670 9017404 CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE 1670 1670 9017404 CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE 1670 1670 9017404 CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE 1670 1670 1670 9017404 CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE 1670 16</td><td> JOINTS 0007 1510 5021309 CONCRETE PAVEMENT (9 IN. NON-REINFORCED 15 FT. 10,939.00 JOINTS 1520 6092011 INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A 2,017.00 2,0008 1530 4010150 TYPE A2 SHOULDER 3,806.80 0008 1540 6091010 CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S 3,319.00 0009 1550 5021340 TYPE A2 SHOULDER 3,806.80 0009 1560 6092011 INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A 3,319.00 0010 1570 6061060 MGS GUARDRAIL 3,813.00 0010 1580 6061068 MGS GUARDRAIL 3,813.00 0010 1580 6061068 MGS GUARDRAIL 2,00 CURB 0010 1690 6061070 MGS SRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB) 0010 1600 6061070 MGS VERTICAL CONCRETE BARRIER TRANSITION 11.00 0010 1610 6061080 MGS END ANCHOR 8.00 0010 1620 6063014 TYPE A CRASHWORTHY END TERMINAL (MASH) 12.00 0010 1630 6063019 TYPE E CRASHWORTHY END TERMINAL (MASH) 12.00 0020 1640 9011330 LUMINAIRE, 1000 WATT HIGH PRESSURE SODIUM HIGH MAST 16.00 0020 1660 9013003 CONDUIT, 2 IN. RIGID, IN TRENCH 26.00 0020 1680 9014004 CONDUIT, 3 IN. RIGID, IN TRENCH 282.00 0020 1680 9014004 CONDUIT, 4 IN. RIGID, IN TRENCH 23.00 0020 1680 9015010 TRENCHING TYPE II 237.00 0020 1700 9015020 TRENCHING TYPE II 237.00 0020 1700 9015020 TRENCHING TYPE II 237.00 0020 1710 9016110 PULL BOX, PREFORMED CLASS 1 15.00 0020 1730 9017101 CABLE, CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE 800.00 NEUTRAL, 2 AWG 0020 1750 9017404 CABLE, CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE 800.00 0020 1750 9017404 CABLE, CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE 2,190.00 0020 1750 9017404 CABLE, CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE 2,190.00 0020 1750 9017404 CABLE, CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE 2,190.00 0020 1750 9017404 CABLE, CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE 2,190.00 0020 1750 9017404 CABLE, CONDUIT, 1 IN., 2 CONDUCTOR</td><td> Joints J</td><td> Joints Joints </td><td> DOINTS DOINTS DOINTS DOINTS DOINTS DO</td><td> </td><td> SOUTH 1510 5021309 CONCRETTE PAVEMENT (9 IN. NON-REINFORCED 15 FT. 10,939.00 -323.00 10,816.00 SOVD 2,978.20 \$\$4.00 \$\$5.00 \$\$15.00 </td></td<>	JOINTS 1510 5021309 CONCRETE PAVEMENT (9 IN. NON-REINFORCED 15 FT. JOINTS) 1520 6092011 INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A 1530 4010150 TYPE A2 SHOULDER 1540 6091010 CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S 1550 5021340 TYPE A2 SHOULDER 1550 5021340 TYPE A2 SHOULDER 1550 6092011 INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A 1550 6061060 MGS GUARDRAIL 1570 6061060 MGS GUARDRAIL 1570 6061060 MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB) 1590 6061069 MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB) 1600 6061070 MGS VERTICAL CONCRETE BARRIER TRANSITION 1610 6061080 MGS END ANCHOR 1620 6063014 TYPE A CRASHWORTHY END TERMINAL (MASH) 1630 6063014 TYPE A CRASHWORTHY END TERMINAL (MASH) 1630 6063019 TYPE E CRASHWORTHY END TERMINAL (MASH) 1630 6063019 TYPE E CRASHWORTHY END TERMINAL 1630 1660 9013002 1670 9013002 CONDUIT, 2 IN. RIGID, IN TRENCH 1670 9013004 CONDUIT, 3 IN. RIGID, IN TRENCH 1670 9013004 CONDUIT, 4 IN. RIGID, IN TRENCH 1670 9015020 TRENCHING TYPE II 1670 9015020 TRENCHING TYPE II 1670 9016110 PULL BOX, PREFORMED CLASS 1 1670 9016112 PULL BOX, PREFORMED CLASS 3 1670 9017404 CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE 1670 9017404 CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE 1670 1670 9017404 CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE 1670 1670 9017404 CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE 1670 1670 9017404 CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE 1670 1670 9017404 CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE 1670 1670 1670 9017404 CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE 1670 16	JOINTS 0007 1510 5021309 CONCRETE PAVEMENT (9 IN. NON-REINFORCED 15 FT. 10,939.00 JOINTS 1520 6092011 INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A 2,017.00 2,0008 1530 4010150 TYPE A2 SHOULDER 3,806.80 0008 1540 6091010 CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S 3,319.00 0009 1550 5021340 TYPE A2 SHOULDER 3,806.80 0009 1560 6092011 INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A 3,319.00 0010 1570 6061060 MGS GUARDRAIL 3,813.00 0010 1580 6061068 MGS GUARDRAIL 3,813.00 0010 1580 6061068 MGS GUARDRAIL 2,00 CURB 0010 1690 6061070 MGS SRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB) 0010 1600 6061070 MGS VERTICAL CONCRETE BARRIER TRANSITION 11.00 0010 1610 6061080 MGS END ANCHOR 8.00 0010 1620 6063014 TYPE A CRASHWORTHY END TERMINAL (MASH) 12.00 0010 1630 6063019 TYPE E CRASHWORTHY END TERMINAL (MASH) 12.00 0020 1640 9011330 LUMINAIRE, 1000 WATT HIGH PRESSURE SODIUM HIGH MAST 16.00 0020 1660 9013003 CONDUIT, 2 IN. RIGID, IN TRENCH 26.00 0020 1680 9014004 CONDUIT, 3 IN. RIGID, IN TRENCH 282.00 0020 1680 9014004 CONDUIT, 4 IN. RIGID, IN TRENCH 23.00 0020 1680 9015010 TRENCHING TYPE II 237.00 0020 1700 9015020 TRENCHING TYPE II 237.00 0020 1700 9015020 TRENCHING TYPE II 237.00 0020 1710 9016110 PULL BOX, PREFORMED CLASS 1 15.00 0020 1730 9017101 CABLE, CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE 800.00 NEUTRAL, 2 AWG 0020 1750 9017404 CABLE, CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE 800.00 0020 1750 9017404 CABLE, CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE 2,190.00 0020 1750 9017404 CABLE, CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE 2,190.00 0020 1750 9017404 CABLE, CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE 2,190.00 0020 1750 9017404 CABLE, CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE 2,190.00 0020 1750 9017404 CABLE, CONDUIT, 1 IN., 2 CONDUCTOR	Joints J	Joints Joints	DOINTS DOINTS DOINTS DOINTS DOINTS DO		SOUTH 1510 5021309 CONCRETTE PAVEMENT (9 IN. NON-REINFORCED 15 FT. 10,939.00 -323.00 10,816.00 SOVD 2,978.20 \$\$4.00 \$\$5.00 \$\$15.00

Revision 4/1/2020 Page 18 of 81



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

No.		No.	Code	Description	Bid Quantity	Net Change	Total Current	Unit	Total Posted	Unit Price	Total Value POSTED To Date (See report
			2340			Order	Quantity		Approved Qty		generated date)
1612222	0020	1770	9018245	POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	4.00	0.00	4.00	EA	0.00	\$1,068.00	\$0.00
	0020	1780	9019901	MISC.EXTERNAL CONDUIT SYSTEM ON STRUCTURE	1.00	0.00	1.00	LS	1.00	\$16,605.00	\$16,605.00
	0020	1790	9019902	MISC.150 FT HIGH MAST POLE	2.00	0.00	2.00	EA	0.00	\$34,530.00	\$0.00
	0020	1800	9019902	MISC.45 FT TOP MOUNT POLES, TYPE AT	4.00	0.00	4.00	EA	0.00	\$2,250.00	\$0.00
	0020	1810	9019902	MISC.ADJUST PULL BOX TO GRADE	1.00	0.00	1.00	EA	0.00	\$483.00	\$0.00
	0020	1820	9019902	MISC.BASE MOUNTED 240/480V COMBINATION POWER SUPPLY AND CONTROLLER	2.00	0.00	2.00	EA	0.00	\$7,258.00	\$0.00
	0020	1830	9019902	MISC.LED-C TOP-MOUNT LUMINAIRE	4.00	0.00	4.00	EA	0.00	\$572.00	\$0.00
	0020	1840	9019903	MISC.1 IN RIGID GALVANIZED STEEL CONDUIT	549.00	0.00	549.00	LF	0.00	\$15.85	\$0.00
	0020	1850	9019903	MISC.THHN CABLE 2C #6 AWG	1,830.00	0.00	1,830.00	LF	0.00	\$1.65	\$0.00
	0030	1860	9020213	SIGNAL HEAD, TYPE 3S	3.00	0.00	3.00	EA	0.00	\$761.00	\$0.00
	0030	1870	9020513	SIGNAL HEAD, TYPE 3B	37.00	0.00	37.00	EA	5.00	\$927.00	\$4,635.00
	0030	1880	9020514	SIGNAL HEAD, TYPE 4B	3.00	0.00	3.00	EA	0.00	\$1,038.00	\$0.00
	0030	1890	9020833	SH-FLAT SHEET - SIGNAL SIGN	133.00	15.00	148.00	SQFT	0.00	\$12.50	\$0.00
0030	0030	1900	9020834	SIGNAL SIGN, MOUNTING HARDWARE	41.00	2.00	43.00	EA	0.00	\$33.00	\$0.00
	0030	1910	9022708	POST, SIGNAL 8 FT. OR 2.4 M	18.00	0.00	18.00	EA	3.00	\$645.00	\$1,935.00
	0030	1920	9022715	POST, SIGNAL 15 FT. OR 4.6 M	1.00	0.00	1.00	EA	0.00	\$972.00	\$0.00
	0030	1930	9023230	POST, TYPE C, 30 FT. ARM OR 9.1 M ARM	1.00	0.00	1.00	EA	0.00	\$7,324.00	\$0.00
	0030	1940	9023235	POST, TYPE C, 35 FT. ARM OR 10.7 M ARM	1.00	0.00	1.00	EA	0.00	\$7,532.00	\$0.00
	0030	1950	9023250	POST, TYPE C, 50 FT. ARM OR 15.2 M ARM	1.00	0.00	1.00	EA	0.00	\$10,292.00	\$0.00
	0030	1960	9023255	POST, TYPE C, 55 FT. ARM	4.00	0.00	4.00	EA	1.00	\$11,930.00	\$11,930.00
	0030	1970	9023335	POST, TYPE B, LONGEST ARM 35 FT. OR 10.7 M	1.00	-1.00	0.00	EA	0.00	\$12,945.00	\$0.00
	0030	1980	9023345	POST, TYPE B, LONGEST ARM 45 FT. OR 13.7 M	1.00	-1.00	0.00	EA	0.00	\$12,439.00	\$0.00
	0030	1990	9024283	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	3.00	0.00	3.00	EA	1.00	\$13,359.00	\$13,359.00
	0030	2000	9024975	VIDEO DETECTION SYSTEM	4.00	0.00	4.00	EA	0.00	\$12,698.00	\$0.00
	0030	2010	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	1,320.00	14.00	1,334.00	LF	376.00	\$10.20	\$3,835.20
	0030	2020	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	844.00	0.00	844.00	LF	871.00	\$23.00	\$20,033.00
	0030	2030	9028208	CABLE, 8 AWG 1 CONDUCTOR, POWER	3,350.00	41.00	3,391.00	LF	0.00	\$0.95	\$0.00
	0030	2040	9028308	CABLE, 16 AWG 2 CONDUCTOR	3,730.00	-285.00	3,445.00	LF	0.00	\$0.50	\$0.0
	0030	2050	9028310	CABLE, 16 AWG 5 CONDUCTOR	3,750.00	-287.00	3,463.00	LF	0.00	\$1.10	\$0.00
	0030	2060	9028311	CABLE, 16 AWG 7 CONDUCTOR	6,790.00	-343.00	6,447.00	LF	1,176.00	\$1.60	\$1,881.60
	0030	2070	9028810	PULL BOX, PREFORMED CLASS 1	10.00	0.00	10.00	EA	2.00	\$602.00	\$1,204.00
	0030	2080	9028811	PULL BOX, PREFORMED CLASS 2	8.00	0.00	8.00	EA	9.00	\$1,221.00	\$10,989.00
	0030	2090	9028812	PULL BOX, PREFORMED CLASS 3	3.00	0.00	3.00	EA	1.00	\$1,642.00	\$1,642.00
	0030	2100	9029100	BASE, CONCRETE	44.00	-1.00	43.00	CUYD	6.59	\$1,160.00	\$7,644.40
	0030	2110	9029901	MISC.TRAFFIC SIGNAL MAINTENANCE AND PROGRAMMING	1.00	0.00	1.00	LS	0.35	\$65,520.00	\$22,932.00
	0030	2120	9029902	MISC.ATC TRAFFIC SIGNAL CONTROLLER	3.00	0.00	3.00	EA	0.00	\$3,214.00	\$0.00
	0030	2130	9029902	MISC.AUDIBLE PEDESTRIAN PUSH BUTTON AND SIGNING	24.00	0.00	24.00	EA	0.00	\$715.00	\$0.00
	0030	2140	9029902	MISC.COMBINATION PAD MOUNTED 120V/240V POWER	1.00	0.00	1.00	EA	0.00	\$14,267.00	\$0.00
	0030	2150	9029902		1.00	0.00	1.00	FA	0.00	\$3,863,00	\$0.00
											\$0.00
											\$0.00
											\$0.00
											\$0.00
											\$0.0
											\$67,584.00
											\$0.00
	0040	2230	9031210	PIPE POSTS	5,390.00	-300.00	5,090.00	LB	0.00	\$3.75	\$0.00
	3/2222	0020 0020 0020 0020 0020 0020 0020 002	0020 1780 0020 1790 0020 1800 0020 1810 0020 1820 0020 1830 0020 1840 0020 1850 0030 1860 0030 1880 0030 1890 0030 1990 0030 1990 0030 1990 0030 1950 0030 1950 0030 1960 0030 1990 0030 1990 0030 1990 0030 1990 0030 1990 0030 2010 0030 2020 0030 2030 0030 2040 0030 2050 0030 2060 0030 2070 0030 2090 0030 2100 0030 2120 0030 <td>0020 1780 9019901 0020 1790 9019902 0020 1800 9019902 0020 1810 9019902 0020 1820 9019902 0020 1830 9019903 0020 1840 9019903 0020 1850 9019903 0030 1860 9020213 0030 1870 9020513 0030 1880 9020514 0030 1890 9020833 0030 1990 9022715 0030 1990 9022715 0030 1990 9023255 0030 1950 9023255 0030 1960 9023255 0030 1990 9024283 0030 1990 9024283 0030 1990 9024375 0030 1990 9024375 0030 2010 9025300 0030 2020 9027300 <td< td=""><td>0020 1780 9919901 MISC.EXTERNAL CONDUIT SYSTEM ON STRUCTURE 0020 1790 9919902 MISC.150 FT HIGH MAST POLE 0020 1800 9019902 MISC.AS FT TOP MOUNT POLES, TYPE AT 0020 1810 9019902 MISC.AS FT TOP MOUNT POLES, TYPE AT 0020 1820 9019902 MISC.AS ADJUST PULL BOX TO GRADE 0020 1830 9019902 MISC.LED.C TOP MOUNT LUMINAIRE 0020 1840 9019903 MISC.TIN RIGIG GALVANIZED STEEL CONDUIT 0030 1860 9019903 MISC.TIN RIGIG GALVANIZED STEEL CONDUIT 0030 1860 9020213 SIGNAL HEAD. TYPE 88 0030 1860 9020213 SIGNAL HEAD. TYPE 4B 0030 1860 9020634 SIGNAL SIGN, MOUNTING HARDWARE 0030 1900 9020834 SIGNAL SIGN, MOUNTING HARDWARE 0030 1910 90222708 POST, SIGNAL 8 FT.OR 2.4 M 0030 1920 9022330 POST, TYPE C, 30 FT. ARM OR 1.1 MARM 0030 1930 9023333 POST, TYPE C, 30 FT. ARM OR 1.</td><td>0020 1780 9019901 MISC EXTERNAL CONDUIT SYSTEM ON STRUCTURE 1.00 0020 1800 9019902 MISC 150 FT HIGH MAST POLE 2.00 0020 1800 9019902 MISC AS FT TOP MOUNT POLES, TYPE AT 4.00 0020 1810 9019902 MISC ADUST PULL BOX TO GRADE 1.00 0020 1820 9019902 MISC LID CONTROLLER 2.00 0020 1830 9019903 MISC LID CONTROLLER 4.00 0020 1840 9019903 MISC LID CONTROLLER 4.00 0020 1850 9019903 MISC LID CONTROLLER 4.00 0030 1860 9020213 SIGNAL HEAD, TYPE 3B 3.00 0030 1860 9020213 SIGNAL HEAD, TYPE 4B 3.00 0030 1860 90202833 SIGNAL HEAD, TYPE 4B 3.00 0030 1860 9020833 SIGNAL HEAD, TYPE 4B 3.00 0030 1860 9020833 SIGNAL HEAD, TYPE 4B 3.00 0030 1860 9020834<</td><td>0020 1780 9019901 MISC_EXTERNAL CONDUIT SYSTEM ON STRUCTURE 1.00 0.00 0020 1790 9019902 MISC_169 FT HIGH MAST POLE 2.00 0.00 0020 1810 9019902 MISC_165 FT TOP MOUNT POLES, TYPE AT 4.00 0.00 0020 1820 9019902 MISC_BASE MOUNTED 249/48/Y COMENATION POWER 2.00 0.00 0020 1830 9019902 MISC_BASE MOUNTED 249/48/Y COMENATION POWER 2.00 0.00 0020 1830 9019903 MISC_THIND CONTROLLER 4.00 0.00 0020 1830 9019903 MISC_THIND CONTROLLER 4.00 0.00 0030 1860 9020213 MISC_THIND TYPE 38 3.00 0.00 0030 1860 9020513 SIGMAL HEAD, TYPE 3B 3.70 0.00 0030 1860 9020533 SIGHAL HEAD, TYPE 4B 3.00 0.00 0030 1800 9020735 SIGMAL HEAD, TYPE 4B 3.00 0.00 0030 1800 9020735</td><td>0020 1780 8019801 MISC_EXTERNAL CONDUIT SYSTEM ON STRUCTURE 1.00 0.00 1.20 0020 1790 8019802 MISC_199 FT RIGH MAST POLE 2.00 0.00 2.20 0020 1810 8019802 MISC_ADUST PULL BOX TO GRADE 1.00 0.00 1.00 0020 1820 9019802 MISC_ADUST PULL BOX TO GRADE 1.00 0.00 2.00 0020 1820 9019802 MISC_BASE MOUNTED 240440V COMBINATION POWER 2.00 0.00 4.00 0020 1820 9019903 MISC_IN RIGID GALVANZED STEEL CONDUIT 5.90 0.00 5.90 0020 1850 9029213 SIGNAL HEAD, TYPE 3S 3.00 0.00 3.70 0030 1860 9020213 SIGNAL HEAD, TYPE 3B 3.00 0.00 3.00 0033 1890 9020513 SIGNAL HEAD, TYPE 3B 3.00 0.00 3.00 0033 1800 9020514 SIGNAL HEAD, TYPE 3B 3.00 0.00 3.00 0033 <t< td=""><td> 0000 1780 0019901 MISC.EXTERNAL CONDUIT SYSTEM ON STRUCTURE 1.00 0.00 1.</td><td> 1.000 1770</td><td> </td></t<></td></td<></td>	0020 1780 9019901 0020 1790 9019902 0020 1800 9019902 0020 1810 9019902 0020 1820 9019902 0020 1830 9019903 0020 1840 9019903 0020 1850 9019903 0030 1860 9020213 0030 1870 9020513 0030 1880 9020514 0030 1890 9020833 0030 1990 9022715 0030 1990 9022715 0030 1990 9023255 0030 1950 9023255 0030 1960 9023255 0030 1990 9024283 0030 1990 9024283 0030 1990 9024375 0030 1990 9024375 0030 2010 9025300 0030 2020 9027300 <td< td=""><td>0020 1780 9919901 MISC.EXTERNAL CONDUIT SYSTEM ON STRUCTURE 0020 1790 9919902 MISC.150 FT HIGH MAST POLE 0020 1800 9019902 MISC.AS FT TOP MOUNT POLES, TYPE AT 0020 1810 9019902 MISC.AS FT TOP MOUNT POLES, TYPE AT 0020 1820 9019902 MISC.AS ADJUST PULL BOX TO GRADE 0020 1830 9019902 MISC.LED.C TOP MOUNT LUMINAIRE 0020 1840 9019903 MISC.TIN RIGIG GALVANIZED STEEL CONDUIT 0030 1860 9019903 MISC.TIN RIGIG GALVANIZED STEEL CONDUIT 0030 1860 9020213 SIGNAL HEAD. TYPE 88 0030 1860 9020213 SIGNAL HEAD. TYPE 4B 0030 1860 9020634 SIGNAL SIGN, MOUNTING HARDWARE 0030 1900 9020834 SIGNAL SIGN, MOUNTING HARDWARE 0030 1910 90222708 POST, SIGNAL 8 FT.OR 2.4 M 0030 1920 9022330 POST, TYPE C, 30 FT. ARM OR 1.1 MARM 0030 1930 9023333 POST, TYPE C, 30 FT. ARM OR 1.</td><td>0020 1780 9019901 MISC EXTERNAL CONDUIT SYSTEM ON STRUCTURE 1.00 0020 1800 9019902 MISC 150 FT HIGH MAST POLE 2.00 0020 1800 9019902 MISC AS FT TOP MOUNT POLES, TYPE AT 4.00 0020 1810 9019902 MISC ADUST PULL BOX TO GRADE 1.00 0020 1820 9019902 MISC LID CONTROLLER 2.00 0020 1830 9019903 MISC LID CONTROLLER 4.00 0020 1840 9019903 MISC LID CONTROLLER 4.00 0020 1850 9019903 MISC LID CONTROLLER 4.00 0030 1860 9020213 SIGNAL HEAD, TYPE 3B 3.00 0030 1860 9020213 SIGNAL HEAD, TYPE 4B 3.00 0030 1860 90202833 SIGNAL HEAD, TYPE 4B 3.00 0030 1860 9020833 SIGNAL HEAD, TYPE 4B 3.00 0030 1860 9020833 SIGNAL HEAD, TYPE 4B 3.00 0030 1860 9020834<</td><td>0020 1780 9019901 MISC_EXTERNAL CONDUIT SYSTEM ON STRUCTURE 1.00 0.00 0020 1790 9019902 MISC_169 FT HIGH MAST POLE 2.00 0.00 0020 1810 9019902 MISC_165 FT TOP MOUNT POLES, TYPE AT 4.00 0.00 0020 1820 9019902 MISC_BASE MOUNTED 249/48/Y COMENATION POWER 2.00 0.00 0020 1830 9019902 MISC_BASE MOUNTED 249/48/Y COMENATION POWER 2.00 0.00 0020 1830 9019903 MISC_THIND CONTROLLER 4.00 0.00 0020 1830 9019903 MISC_THIND CONTROLLER 4.00 0.00 0030 1860 9020213 MISC_THIND TYPE 38 3.00 0.00 0030 1860 9020513 SIGMAL HEAD, TYPE 3B 3.70 0.00 0030 1860 9020533 SIGHAL HEAD, TYPE 4B 3.00 0.00 0030 1800 9020735 SIGMAL HEAD, TYPE 4B 3.00 0.00 0030 1800 9020735</td><td>0020 1780 8019801 MISC_EXTERNAL CONDUIT SYSTEM ON STRUCTURE 1.00 0.00 1.20 0020 1790 8019802 MISC_199 FT RIGH MAST POLE 2.00 0.00 2.20 0020 1810 8019802 MISC_ADUST PULL BOX TO GRADE 1.00 0.00 1.00 0020 1820 9019802 MISC_ADUST PULL BOX TO GRADE 1.00 0.00 2.00 0020 1820 9019802 MISC_BASE MOUNTED 240440V COMBINATION POWER 2.00 0.00 4.00 0020 1820 9019903 MISC_IN RIGID GALVANZED STEEL CONDUIT 5.90 0.00 5.90 0020 1850 9029213 SIGNAL HEAD, TYPE 3S 3.00 0.00 3.70 0030 1860 9020213 SIGNAL HEAD, TYPE 3B 3.00 0.00 3.00 0033 1890 9020513 SIGNAL HEAD, TYPE 3B 3.00 0.00 3.00 0033 1800 9020514 SIGNAL HEAD, TYPE 3B 3.00 0.00 3.00 0033 <t< td=""><td> 0000 1780 0019901 MISC.EXTERNAL CONDUIT SYSTEM ON STRUCTURE 1.00 0.00 1.</td><td> 1.000 1770</td><td> </td></t<></td></td<>	0020 1780 9919901 MISC.EXTERNAL CONDUIT SYSTEM ON STRUCTURE 0020 1790 9919902 MISC.150 FT HIGH MAST POLE 0020 1800 9019902 MISC.AS FT TOP MOUNT POLES, TYPE AT 0020 1810 9019902 MISC.AS FT TOP MOUNT POLES, TYPE AT 0020 1820 9019902 MISC.AS ADJUST PULL BOX TO GRADE 0020 1830 9019902 MISC.LED.C TOP MOUNT LUMINAIRE 0020 1840 9019903 MISC.TIN RIGIG GALVANIZED STEEL CONDUIT 0030 1860 9019903 MISC.TIN RIGIG GALVANIZED STEEL CONDUIT 0030 1860 9020213 SIGNAL HEAD. TYPE 88 0030 1860 9020213 SIGNAL HEAD. TYPE 4B 0030 1860 9020634 SIGNAL SIGN, MOUNTING HARDWARE 0030 1900 9020834 SIGNAL SIGN, MOUNTING HARDWARE 0030 1910 90222708 POST, SIGNAL 8 FT.OR 2.4 M 0030 1920 9022330 POST, TYPE C, 30 FT. ARM OR 1.1 MARM 0030 1930 9023333 POST, TYPE C, 30 FT. ARM OR 1.	0020 1780 9019901 MISC EXTERNAL CONDUIT SYSTEM ON STRUCTURE 1.00 0020 1800 9019902 MISC 150 FT HIGH MAST POLE 2.00 0020 1800 9019902 MISC AS FT TOP MOUNT POLES, TYPE AT 4.00 0020 1810 9019902 MISC ADUST PULL BOX TO GRADE 1.00 0020 1820 9019902 MISC LID CONTROLLER 2.00 0020 1830 9019903 MISC LID CONTROLLER 4.00 0020 1840 9019903 MISC LID CONTROLLER 4.00 0020 1850 9019903 MISC LID CONTROLLER 4.00 0030 1860 9020213 SIGNAL HEAD, TYPE 3B 3.00 0030 1860 9020213 SIGNAL HEAD, TYPE 4B 3.00 0030 1860 90202833 SIGNAL HEAD, TYPE 4B 3.00 0030 1860 9020833 SIGNAL HEAD, TYPE 4B 3.00 0030 1860 9020833 SIGNAL HEAD, TYPE 4B 3.00 0030 1860 9020834<	0020 1780 9019901 MISC_EXTERNAL CONDUIT SYSTEM ON STRUCTURE 1.00 0.00 0020 1790 9019902 MISC_169 FT HIGH MAST POLE 2.00 0.00 0020 1810 9019902 MISC_165 FT TOP MOUNT POLES, TYPE AT 4.00 0.00 0020 1820 9019902 MISC_BASE MOUNTED 249/48/Y COMENATION POWER 2.00 0.00 0020 1830 9019902 MISC_BASE MOUNTED 249/48/Y COMENATION POWER 2.00 0.00 0020 1830 9019903 MISC_THIND CONTROLLER 4.00 0.00 0020 1830 9019903 MISC_THIND CONTROLLER 4.00 0.00 0030 1860 9020213 MISC_THIND TYPE 38 3.00 0.00 0030 1860 9020513 SIGMAL HEAD, TYPE 3B 3.70 0.00 0030 1860 9020533 SIGHAL HEAD, TYPE 4B 3.00 0.00 0030 1800 9020735 SIGMAL HEAD, TYPE 4B 3.00 0.00 0030 1800 9020735	0020 1780 8019801 MISC_EXTERNAL CONDUIT SYSTEM ON STRUCTURE 1.00 0.00 1.20 0020 1790 8019802 MISC_199 FT RIGH MAST POLE 2.00 0.00 2.20 0020 1810 8019802 MISC_ADUST PULL BOX TO GRADE 1.00 0.00 1.00 0020 1820 9019802 MISC_ADUST PULL BOX TO GRADE 1.00 0.00 2.00 0020 1820 9019802 MISC_BASE MOUNTED 240440V COMBINATION POWER 2.00 0.00 4.00 0020 1820 9019903 MISC_IN RIGID GALVANZED STEEL CONDUIT 5.90 0.00 5.90 0020 1850 9029213 SIGNAL HEAD, TYPE 3S 3.00 0.00 3.70 0030 1860 9020213 SIGNAL HEAD, TYPE 3B 3.00 0.00 3.00 0033 1890 9020513 SIGNAL HEAD, TYPE 3B 3.00 0.00 3.00 0033 1800 9020514 SIGNAL HEAD, TYPE 3B 3.00 0.00 3.00 0033 <t< td=""><td> 0000 1780 0019901 MISC.EXTERNAL CONDUIT SYSTEM ON STRUCTURE 1.00 0.00 1.</td><td> 1.000 1770</td><td> </td></t<>	0000 1780 0019901 MISC.EXTERNAL CONDUIT SYSTEM ON STRUCTURE 1.00 0.00 1.	1.000 1770	

Page 19 of 81 Revision 4/1/2020



Total Paid / All Items / All Estimates (Including this Estimate)

lote: Posted Q	uantities	and Valu	ies are	based on I	Report Generated date and can differ from the posted a	mount at the	time the Es	timate was	Generat	ed.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200515-F15	J6I2222	0040	2240	9031270A	2 IN. PSST POST - 12 GA.	60.00	0.00	60.00	LF	0.00	\$12.00	\$0.00
		0040	2250	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	21.00	0.00	21.00	LF	0.00	\$40.00	\$0.00
		0040	2260	9035004A	SH-FLAT SHEET	598.00	0.00	598.00	SQFT	0.00	\$21.00	\$0.00
		0040	2270	9035011A	ST-STRUCTURAL	2,364.00	3.00	2,367.00	SQFT	170.00	\$24.00	\$4,080.00
		0040	2280	9035069A	SHF-FLAT SHEET FLUORESCENT	93.00	0.00	93.00	SQFT	0.00	\$24.00	\$0.00
		0040	2290	9035071A	STF-STRUCTURAL FLUORESCENT	390.00	0.00	390.00	SQFT	90.00	\$26.00	\$2,340.00
		0040	2300	9036036	TUBULAR SUPPORT, TYPE C-2315-20	2.00	0.00	2.00	EA	0.00	\$12,950.00	\$0.00
		0040	2310	9036042	TUBULAR SUPPORT, TYPE C-2018-28	2.00	-2.00	0.00	EA	0.00	\$20,000.00	\$0.00
		0040	2320	9039901	MISC.SIGN 12 CANTILEVER BOX TRUSS, 30 FT ARM	1.00	0.00	1.00	LS	0.00	\$29,000.00	\$0.00
		0040	2330	9039901	MISC.SIGN 4 SPAN BOX TRUSS (98 FT)	1.00	0.00	1.00	LS	1.00	\$66,000.00	\$66,000.00
		0040	2340	9039901	MISC.SIGN 8 SPAN BOX TRUSS (83 FT-5 IN)	1.00	0.00	1.00	LS	0.00	\$52,500.00	\$0.00
		0040	2350	9039901	MISC.SPECIAL STREET NAME BRIDGE MOUNTED SIGNS	1.00	0.00	1.00	LS	0.00	\$20,000.00	\$0.00
		0050	2360	9108208	CABLE, 8 AWG, 1 CONDUCTOR, POWER	2,510.00	0.00	2,510.00	LF	0.00	\$1.00	\$0.00
		0050	2370	9108408	WIRE, 8 AWG, BARE NEUTRAL	1,010.00	0.00	1,010.00	LF	0.00	\$1.00	\$0.00
		0050	2380	9109100	BASE, CONCRETE	2.00	0.00	2.00	CUYD	0.00	\$1,726.00	\$0.00
		0050	2390	9109230	DYNAMIC MESSAGE SIGN ASSEMBLY, INSTALLED	1.00	-1.00	0.00	EA	0.00	\$9,413.00	\$0.00
		0050	2400	9109901	MISC.ITS ASSET MANAGEMENT TOOL	1.00	0.00	1.00	LS	0.00	\$2,797.00	\$0.00
		0050	2410	9109902	MISC.ADJUST EXISTING P.B. TO GRADE	1.00	0.00	1.00	EA	0.00	\$1,335.00	\$0.00
		0050	2420	9109902	MISC.BURIED CABLE DELINEATOR POST	12.00	0.00	12.00	EA	1.00	\$100.00	\$100.00
		0050	2430	9109902	MISC.BUTTERFLY DMS STRUCTURE	1.00	0.00	1.00	EA	0.00	\$55,944.00	\$0.00
		0050	2440	9109902	MISC.CCTV EXTENSION POLE, 20' METALLICFINISH	1.00	0.00	1.00	EA	0.00	\$1,554.00	\$0.00
		0050	2450	9109902	MISC.FIBER OPTIC FUSION SPLICE	310.00	48.00	358.00	EA	272.00	\$39.00	\$10,608.00
		0050	2460	9109902	MISC.FIBER OPTIC JUMPER,SM, FURNISH AND INSTALL	34.00	0.00	34.00	EA	7.00	\$22.00	\$154.00
		0050	2470	9109902	MISC.FIBER OPTIC PIGTAIL, SM, FURNISH AND INSTALL	42.00	0.00	42.00	EA	26.00	\$10.00	\$260.00
		0050	2480	9109902	MISC.FIELD TERMINAL CABINET, TYPE 7, FURNISH AND	1.00	0.00	1.00	EA	0.00	\$3,314.00	\$0.00
		0050	2490	9109902	INSTALL MISC.INSTALL CCTV CAMERA ASSEMBLY	1.00	0.00	1.00	EA	0.00	\$883.00	\$0.00
		0050	2500	9109902	MISC.INSTALL CONDUIT INTO EXISTING BOX	5.00	0.00	5.00	EA	0.00	\$210.00	\$0.00
		0050		9109902				5.00	EA			
		0050	2510		MISC.ITS PULL BOX, CLASS 5	5.00	0.00		EA	0.00	\$1,842.00	\$0.00
		0050	2520	9109902	MISC.ITS PULL BOX, CLASS 2 MISC.SIGN STRUCTURE BASE MESH	1.00	0.00	1.00		0.00	\$1,554.00	\$0.00
		0050	2530	9109902	MISC.UNDERGROUND FIBER CABLE SPLICE ENCLOSURE	1.00	0.00	1.00	EA	0.00	\$310.00	\$0.00
		0050	2540	9109902		2.00	2.00	4.00	EA	2.00	\$621.00	\$1,242.00
		0050	2550	9109902	MISC.WALL-MOUNTED FIBER INTERCONNECT CENTER, FURNISH AND INSTALL	7.00	0.00	7.00	EA	0.00	\$350.00	\$0.00
		0050	2560	9109903	MISC.24 STRAND, SINGLE MODE FIBER OPTIC CABLE	7,760.00	0.00	7,760.00	LF	7,760.00	\$1.85	\$14,356.00
		0050	2570	9109903	MISC.72 STRAND, SINGLE MODE FIBER OPTIC CABLE	4,200.00	0.00	4,200.00	LF	4,200.00	\$2.05	\$8,610.00
		0050	2580	9109903	MISC.CAT-5 ETHERNET CABLE	200.00	0.00	200.00	LF	0.00	\$1.70	\$0.00
		0050	2590	9109903	MISC.Conduit, PVC, PUSHED, 2"	399.00	0.00	399.00	LF	399.00	\$16.45	\$6,563.55
		0050	2600	9109903	MISC.CONDUIT, PVC, TRENCH, 2"	1,083.00	0.00	1,083.00	LF	0.00	\$5.90	\$0.00
		0070	2610	2163000	PARTIAL REMOVAL OF EXISTING BRIDGE DECK	2,033.00	0.00	2,033.00	SQFT	2,033.00	\$10.00	\$20,330.00
		0070	2620	2163502	PARTIAL REMOVAL OF SUBSTRUCTURE CONCRETE	1.00	0.00	1.00	LS	1.00	\$9,200.00	\$9,200.00
		0070	2630	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	41.00	0.00	41.00	LF	0.00	\$425.00	\$0.00
		0070	2640	5031010A	BRIDGE APPROACH SLAB (MAJOR ROAD)	59.00	0.00	59.00	SQYD	0.00	\$355.00	\$0.00
		0070	2650	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	1.00	0.00	1.00	CUYD	1.00	\$5,050.00	\$5,050.00
		0070	2660	7034001	CLASS B-1 CONCRETE	0.70	0.00	0.70	CUYD	0.00	\$12,650.00	\$0.00
		0070	2670	7034212	SLAB ON STEEL	212.00	2.00	214.00	SQYD	214.00	\$470.00	\$100,580.00
		0070	2680	7034214	CLASS B-2 CONCRETE	3.50	0.00	3.50	CUYD	0.00	\$6,530.00	\$0.00
		0070	2690	7034610	CORRAL CURB	182.00	0.00	182.00	LF	142.00	\$117.00	\$16,614.00

Revision 4/1/2020 Page 20 of 81



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

ontract Pr		Category	Line No.	Item Code	Report Generated date and can differ from the posted ar Description	Bid Quantity	Net Change	Total Current	Unit	Total Posted	Unit Price	Total Value POSTED To Date (See report
							Order	Quantity		Approved Qty		generated date)
5-F15 J6I	12222	0070	2700	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	1,275.00	0.00	1,275.00	SQFT	1,269.00	\$158.00	\$200,502.00
		0070	2710	7040113	CLEANING AND EPOXY COATING	6,834.00	0.00	6,834.00	SQFT	0.00	\$3.36	\$0.00
		0070	2720	7049904	MISC.BARRIER CURB REPAIR (UNFORMED	195.00	0.00	195.00	SQFT	148.00	\$175.00	\$25,900.00
		0070	2730	7101000	REINFORCING STEEL (EPOXY COATED)	850.00	0.00	850.00	LB	850.00	\$3.00	\$2,550.00
		0070	2740	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$1,584.52	\$0.00
		0070	2750	7123130	REHABILITATE BEARING	8.00	0.00	8.00	EA	0.00	\$3,712.50	\$0.00
		0070	2760	7123620	DRAINAGE SYSTEM (ON STRUCTURE)	1.00	0.00	1.00	LS	0.00	\$10,500.00	\$0.00
		0070	2770	7129901	MISC.FLUSH DRAINAGE SYSTEM AND EXPANSION JOINTS	1.00	0.00	1.00	LS	0.00	\$20,000.00	\$0.00
		0070	2780	7129902	MISC.FATIGUE CRACK REPAIR	1.00	0.00	1.00	EA	0.00	\$6,516.00	\$0.00
		0070	2790	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	41.00	0.00	41.00	LF	0.00	\$490.00	\$0.00
		0071	2800	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	25.00	0.00	25.00	SQFT	0.00	\$158.00	\$0.00
		0071	2810	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	1,483.00	0.00	1,483.00	SQFT	1,483.00	\$158.00	\$234,314.00
		0071	2820	7040113	CLEANING AND EPOXY COATING	5,621.00	0.00	5,621.00	SQFT	0.00	\$3.04	\$0.00
		0071	2830	7049904	MISC.BARRIER CURB REPAIR (UNFORMED)	142.00	0.00	142.00	SQFT	142.00	\$175.00	\$24,850.00
		0071	2840	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$3,678.35	\$0.00
		0071	2850	7121000	FABRICATED STRUCTURAL CARBON STEEL (MISC)	290.00	0.00	290.00	LB	0.00	\$23.00	\$0.00
		0071	2860	7123130	REHABILITATE BEARING	5.00	0.00	5.00	EA	0.00	\$2,570.00	\$0.00
		0071	2875	7125111	INTERMEDIATE FIELD COAT (SYSTEM G)	1.00	0.00	1.00	LS	0.00	\$1,330.80	\$0.00
		0071	2885	7125112	FINISH FIELD COAT (SYSTEM G)	1.00	0.00	1.00	LS	0.00	\$475.20	\$0.00
		0071	2890	7129901	MISC.FLUSH DRAINAGE SYSTEM AND EXPANSION JOINTS	1.00	0.00	1.00	LS	0.00	\$20,000.00	\$0.00
		0071	2900	7129902	MISC.FATIGUE CRACK REPAIR	3.00	0.00	3.00	EA	0.00	\$2,040.00	\$0.00
		0072	2910	7121060	FABRICATED SIGN SUPPORT BRACKETS	1.00	0.00	1.00	LS	0.00	\$3,600.00	\$0.00
		0073	2920	2065500	TEMPORARY SHORING	1.00	0.00	1.00	LS	1.00	\$150,000.00	\$150,000.00
		0073	2930	7033009	AESTHETIC CONCRETE STAIN	1.00	0.00	1.00	LS	0.00	\$14,877.00	\$0.0
		0073	2940	7201000	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	8,672.00	0.00	8,672.00	SQFT	8,672.00	\$62.50	\$542,000.0
		0074	2955	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	258.00	-258.00	0.00	SQYD	0.00	\$145.00	\$0.0
		0074	2960	6079903	MISC.(60 IN.) DECORATIVE PEDESTRIAN FENCE	280.00	-280.00	0.00	LF	0.00	\$130.00	\$0.0
		0074	2970	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	820.00	7.00	827.00	LF	741.00	\$68.00	\$50,388.00
		0074	2980	7025001	DYNAMIC PILE TESTING	2.00	0.00	2.00	EA	2.00	\$2,325.00	\$4,650.00
		0074	2990	7027000	PILE POINT REINFORCEMENT	14.00	0.00	14.00	EA	14.00	\$80.00	\$1,120.00
		0074	3000	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	56.40	13.90	70.30	CUYD	36.10	\$565.00	\$20,396.50
		0074	3010	7034219A	TYPE D BARRIER	288.00	-288.00	0.00	LF	0.00	\$115.00	\$0.00
		0074	3020	7034221	SLAB ON CONCRETE NU-GIRDER	760.00	-760.00	0.00	SQYD	0.00	\$335.00	\$0.00
		0074	3030	7034630	CONCRETE CURB (BRIDGE RAIL)	306.00	-306.00	0.00	LF	0.00	\$75.00	\$0.00
		0074	3040	7056022	NU 43, PRESTRESSED CONCRETE NU-GIRDER	894.00	-894.00	0.00	LF	0.00	\$215.00	\$0.00
		0074	3050	7071000	CONDUIT SYSTEM ON STRUCTURE	1.00	-1.00	0.00	LS	0.00	\$5,927.00	\$0.00
		0074	3060	7121060	FABRICATED SIGN SUPPORT BRACKETS	1.00	0.00	1.00	LS	0.00	\$7,100.00	\$0.00
		0074	3070	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	0.00	\$2,500.00	\$0.00
		0074	3080	7161000	PLAIN NEOPRENE BEARING PAD	16.00	0.00	16.00	EA	0.00	\$200.00	\$0.00
		0074	3090	7201300	PIPE PILE SPACERS	14.00	-14.00	0.00	EA	0.00	\$1,000.00	\$0.00
		0074	3100	9019902	MISC.ORNAMENTAL LUMINAIRE	10.00	4.00	14.00	EA	0.00	\$1,658.00	\$0.00
		0075	3110	7033009	AESTHETIC CONCRETE STAIN	1.00	-1.00	0.00	LS	0.00	\$17,530.50	\$0.00
		0075	3120	7201000	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	7,637.00	-7,637.00	0.00	SQFT	0.00	\$110.00	\$0.00
		0076	3130	7033009	AESTHETIC CONCRETE STAIN	1.00	-1.00	0.00	LS	0.00	\$6,525.00	\$0.0
		0076	3140	7201000	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	3,410.00	-3,410.00	0.00	SQFT	0.00	\$110.00	\$0.00
		0077	3150	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$146,000.00	\$146,000.00
		5511	3160		BRIDGE APPROACH SLAB (MINOR ROAD)	250.00	0.00	250.00	SQYD	0.00	\$140,000.00	\$0.00

Revision 4/1/2020 Page 21 of 81



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Q	uantities	and Valu	ies are	based on F	Report Generated date and can differ from the posted a	mount at the	time the Es	stimate was	Generat	ted.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200515-F15	J6I2222	0077	3170	6079903	MISC.(60 IN.) DECORATIVE PEDESTRIAN FENCE	404.00	0.00	404.00	LF	0.00	\$130.00	\$0.00
		0077	3180	7011105	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	30.00	0.00	30.00	LF	25.50	\$490.00	\$12,495.00
		0077	3190	7011204	ROCK SOCKETS (3 FT 0 IN. DIA.)	30.00	0.00	30.00	LF	30.00	\$815.00	\$24,450.00
		0077	3200	7011300	VIDEO CAMERA INSPECTION	3.00	0.00	3.00	EA	3.00	\$450.00	\$1,350.00
		0077	3210	7011400	FOUNDATION INSPECTION HOLES	60.00	0.00	60.00	LF	60.00	\$140.00	\$8,400.00
		0077	3220	7011600	SONIC LOGGING TESTING	3.00	0.00	3.00	EA	3.00	\$2,100.00	\$6,300.00
		0077	3230	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	462.00	0.00	462.00	LF	462.00	\$75.00	\$34,650.00
		0077	3240	7025001	DYNAMIC PILE TESTING	2.00	0.00	2.00	EA	2.00	\$2,350.00	\$4,700.00
		0077	3250	7026000	PRE-BORE FOR PILING	252.00	0.00	252.00	LF	252.00	\$180.00	\$45,360.00
		0077	3260	7027000	PILE POINT REINFORCEMENT	14.00	0.00	14.00	EA	14.00	\$80.00	\$1,120.00
		0077	3270	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	49.60	0.00	49.60	CUYD	49.60	\$800.00	\$39,680.00
		0077	3280	7034003	CLASS B-1 CONCRETE (SUBSTRUCTURE)	60.30	0.00	60.30	CUYD	60.30	\$1,055.00	\$63,616.50
		0077	3290	7034219A	TYPE D BARRIER	404.00	0.00	404.00	LF	0.00	\$130.00	\$0.00
		0077	3300	7034221	SLAB ON CONCRETE NU-GIRDER	1,175.00	0.00	1,175.00	SQYD	0.00	\$290.00	\$0.00
		0077	3310	7034630	CONCRETE CURB (BRIDGE RAIL)	447.00	0.00	447.00	LF	0.00	\$62.00	\$0.00
		0077	3320	7056021	NU 35, PRESTRESSED CONCRETE NU-GIRDER	1,268.00	0.00	1,268.00	LF	0.00	\$210.00	\$0.00
		0077	3330	7061060	REINFORCING STEEL (BRIDGES)	18,420.00	-18,420.00	0.00	LB	0.00	\$1.00	\$0.00
		0077	3340	7071000	CONDUIT SYSTEM ON STRUCTURE	1.00	0.00	1.00	LS	0.00	\$26.383.00	\$0.00
		0077	3350	7079901	MISC.CONDUIT SYSTEM ON STRUCTURE - ATT TELPHONE	1.00	0.00	1.00	LS	0.00	\$3,730.00	\$0.00
		0077	3355	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS	1.00	0.00	1.00	LS	0.00	\$8,330.05	\$0.00
					(EPOXY)							
		0077	3370	7121060	FABRICATED SIGN SUPPORT BRACKETS	1.00	0.00	1.00	LS	0.00	\$27,500.00	\$0.00
		0077	3380	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	0.00	\$2,500.00	\$0.00
		0077	3390	7161003	LAMINATED NEOPRENE BEARING PAD (TAPERED)	28.00	0.00	28.00	EA	28.00	\$425.00	\$11,900.00
		0077	3400	7201300	PIPE PILE SPACERS	14.00	0.00	14.00	EA	14.00	\$855.00	\$11,970.00
		0077	3410	9019903	MISC.ORNAMENTAL LUMINAIRE	12.00	0.00	12.00	LF	0.00	\$1,658.00	\$0.00
		0078	3420	7033009	AESTHETIC CONCRETE STAIN	1.00	0.00	1.00	LS	0.00	\$7,856.10	\$0.00
		0078	3430	7201000	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	4,182.00	0.00	4,182.00	SQFT	836.00	\$80.00	\$66,880.00
		0079	3440	7033009	AESTHETIC CONCRETE STAIN	1.00	0.00	1.00	LS	0.00	\$3,654.00	\$0.00
		0079	3450	7201000	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	2,521.00	0.00	2,521.00	SQFT	2,269.00	\$80.00	\$181,520.00
		0800	3460	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	0.70	\$655,000.00	\$458,500.00
		0800	3470	5031010A	BRIDGE APPROACH SLAB (MAJOR ROAD)	81.00	0.00	81.00	SQYD	0.00	\$200.00	\$0.00
		0800	3480	7011110	DRILLED SHAFTS (6 FT. 0 IN. DIA.)	380.40	0.00	380.40	LF	246.16	\$485.00	\$119,387.60
		0800	3490	7011209	ROCK SOCKETS (5 FT 6 IN. DIA.)	108.00	0.00	108.00	LF	108.00	\$2,555.00	\$275,940.00
		0800	3500	7011300	VIDEO CAMERA INSPECTION	6.00	0.00	6.00	EA	4.00	\$550.00	\$2,200.00
		0800	3510	7011400	FOUNDATION INSPECTION HOLES	174.00	0.00	174.00	LF	174.00	\$155.00	\$26,970.00
		0800	3520	7011600	SONIC LOGGING TESTING	6.00	0.00	6.00	EA	3.00	\$4,250.00	\$12,750.00
		0800	3530	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	430.00	0.00	430.00	LF	0.00	\$85.00	\$0.00
		0800	3540	7025001	DYNAMIC PILE TESTING	1.00	0.00	1.00	EA	0.00	\$2,700.00	\$0.00
		0800	3550	7027000	PILE POINT REINFORCEMENT	5.00	0.00	5.00	EA	0.00	\$80.00	\$0.00
		0800	3560	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	21.70	0.00	21.70	CUYD	0.00	\$745.00	\$0.00
		0800	3570	7034003	CLASS B-1 CONCRETE (SUBSTRUCTURE)	379.50	0.00	379.50	CUYD	0.00	\$710.00	\$0.00
		0800	3580	7034212	SLAB ON STEEL	304.00	0.00	304.00	SQYD	0.00	\$335.00	\$0.00
		0800	3590	7034219A	TYPE D BARRIER	1,779.00	0.00	1,779.00	LF	0.00	\$58.00	\$0.00
		0800	3600	7034221	SLAB ON CONCRETE NU-GIRDER	2,430.00	0.00	2,430.00	SQYD	0.00	\$340.00	\$0.00
		0800	3610	7056023	NU 53, PRESTRESSED CONCRETE NU-GIRDER	1,504.00	0.00	1,504.00	LF	0.00	\$270.00	\$0.00
		0800	3620	7056025	NU 70, PRESTRESSED CONCRETE NU-GIRDER	1,151.00	0.00	1,151.00	LF	0.00	\$270.00	\$0.00
		0800	3630	7061060	REINFORCING STEEL (BRIDGES)	170,450.00	0.00	170,450.00	LB	134,380.00	\$0.85	\$114,223.00

Revision 4/1/2020 Page 22 of 81



Total Paid / All Items / All Estimates (Including this Estimate)

vote: Posted Q	uantities	and Valu	ies are	based on I	Report Generated date and can differ from the posted am	ount at the	time the Es	timate was	Generat	ed.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200515-F15	J6I2222	0080	3640	7061070	MECHANICAL BAR SPLICE	480.00	0.00	480.00	EA	152.00	\$95.00	\$14,440.00
		0800	3650	7101000	REINFORCING STEEL (EPOXY COATED)	12,940.00	0.00	12,940.00	LB	0.00	\$1.15	\$0.00
		0080	3660	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$9,744.80	\$0.00
		0800	3670	7120900	EXPANSION DEVICE (FINGER PLATE)	23.00	0.00	23.00	LF	0.00	\$2,400.00	\$0.00
		0080	3680	7121121	FABRICATED STRUCTURAL LOW ALLOY STEEL (PLATE GIRDER) A709, GRADE 50	79,550.00	0.00	79,550.00	LB	0.00	\$3.19	\$0.00
		0800	3690	7123210	EARTH QUAKE RESTRAINER ASSEMBLIES	3.00	0.00	3.00	EA	0.00	\$13,125.00	\$0.00
		0080	3700	7123301	STEEL INTERMEDIATE DIAPHRAGM FOR P/S CONCRETE GIRDERS	30.00	0.00	30.00	EA	0.00	\$680.00	\$0.00
		0800	3710	7123620	DRAINAGE SYSTEM (ON STRUCTURE)	1.00	0.00	1.00	LS	0.00	\$80,000.00	\$0.00
		0800	3720	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	500.00	0.00	500.00	SQFT	0.00	\$81.40	\$0.00
		0800	3730	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	500.00	0.00	500.00	SQFT	0.00	\$2.00	\$0.00
		0800	3740	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	5,000.00	0.00	5,000.00	SQFT	0.00	\$6.65	\$0.00
		0080	3750	7125370A	FINISH FIELD COAT (SYSTEM G)	2,700.00	0.00	2,700.00	SQFT	0.00	\$2.38	\$0.00
		0080	3760	7129903	MISC.MODULAR EXPANSION JOINT SYSTEM	24.00	0.00	24.00	LF	0.00	\$2,400.00	\$0.00
		0800	3770	7151001	VERTICAL DRAIN AT END BENTS	1.00	0.00	1.00	EA	0.00	\$2,500.00	\$0.00
		0080	3780	7161000	PLAIN NEOPRENE BEARING PAD	8.00	0.00	8.00	EA	0.00	\$225.00	\$0.00
		0080	3790	7161002	LAMINATED NEOPRENE BEARING PAD	3.00	0.00	3.00	EA	0.00	\$250.00	\$0.00
		0080	3800	7161003	LAMINATED NEOPRENE BEARING PAD (TAPERED)	21.00	0.00	21.00	EA	0.00	\$320.00	\$0.00
		0080	3810	7162000	LAMINATED NEOPRENE BEARING PAD ASSEMBLY	16.00	0.00	16.00	EA	0.00	\$1,520.00	\$0.00
		0800	3820	7163000	TYPE N PTFE BEARING	3.00	0.00	3.00	EA	0.00	\$2,500.00	\$0.00
		0800	3830	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	24.00	0.00	24.00	LF	0.00	\$510.00	\$0.00
		0001	5001	6189901	MISC.Adjust Mobilization for Contract Bond	0.00	1.00	1.00	LS	1.00	\$107,907.00	\$107,907.00
		0001	5002	6141121	CURVED VANE GRATE AND FRAME (4 FT. X 2 FT. OR 1200MM X 600MM)	0.00	18.00	18.00	EA	0.00	\$1,400.00	\$0.00
		0001	5003	6149902	MISC.Parallel Grate and Bearing Plate (4 FT.x2FT.)	0.00	27.00	27.00	EA	6.00	\$1,400.00	\$8,400.00
		0050	5004	9109901	MISC.DMS Board Removal	0.00	1.00	1.00	LS	1.00	\$12,673.51	\$12,673.51
		0001	5005	6173700B	TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED	0.00	638.00	638.00	LF	638.00	\$40.79	\$26,024.02
		0001	5006	2063100	CLASS 3 EXCAVATION IN ROCK	0.00	18.50	18.50	CUYD	18.50	\$85.00	\$1,572.50
		0050	5007	9109901	MISC.Colored Dynamic Message Sign	0.00	1.00	1.00	LS	0.00	\$110,608.04	\$0.00
		0001	5008	6149902	MISC.MISC. MSD Manhole Frame and Cover	0.00	19.00	19.00	EA	6.00	\$400.00	\$2,400.00
		0001	5009	2032000	CLASS C EXCAVATION	0.00	1,139.90	1,139.90	CUYD	1,139.90	\$75.00	\$85,492.50
		0001	5010	7209901	MISC.Rock Fill Alternative Ground Improvement	0.00	1.00	1.00	LS	1.00	\$7,822.60	\$7,822.60
		0077	5011	7101000	REINFORCING STEEL (EPOXY COATED)	0.00	18,950.00	18,950.00	LB	18,950.00	\$1.33	\$25,203.50
		0001	5012	2029901	MISC.Barrier Wall Removal	0.00	1.00	1.00	LS	1.00	\$5,226.18	\$5,226.18
		0074	5013	7011105	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	0.00	202.80	202.80	LF	202.80	\$567.75	\$115,139.70
		0074	5014	7011204	ROCK SOCKETS (3 FT 0 IN. DIA.)	0.00	76.70	76.70	LF	76.70	\$917.10	\$70,341.57
		0074	5015	7101000	REINFORCING STEEL (EPOXY COATED)	0.00	24,760.00	24,760.00	LB	24,760.00	\$1.49	\$36,892.40
		0074	5016	7011300	VIDEO CAMERA INSPECTION	0.00	6.00	6.00	EA	6.00	\$577.50	\$3,465.00
		0074	5017	7011400	FOUNDATION INSPECTION HOLES	0.00	185.10	185.10	LF	185.10	\$136.50	\$25,266.15
		0074	5018	7011600	SONIC LOGGING TESTING	0.00	6.00	6.00	EA	6.00	\$4,593.00	\$27,558.00
		0074	5019	7061070	MECHANICAL BAR SPLICE	0.00	108.00	108.00	EA	108.00	\$140.70	\$15,195.60
		0001	5020	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	0.00	165.70	165.70	SQYD	165.70	\$110.00	\$18,227.00
		0001	5021	6131018	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	0.00	58.00	58.00	EA	58.00	\$12.00	\$696.00
		0001	5022	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	0.00	130.00	130.00	EA	130.00	\$15.00	\$1,950.00
		0001	5023	1046002	VALUE ENGINEERING	0.00	14,480.00	14,480.00	EA	14,480.00	\$1.00	\$14,480.00
		0001	5024	7269923	SEWER	0.00	701.00	701.00	LF	701.00	\$461.34	\$323,399.34
		0001	5025	7269922	SEWER	0.00	150,000.00	150,000.00	EA	147,772.00	\$1.00	\$147,772.00

Revision 4/1/2020 Page 23 of 81



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract n.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
0515-F15	J6I2222	0074	5026	7034003	CLASS B-1 CONCRETE (SUBSTRUCTURE)	0.00	99.80	99.80	CUYD	99.80	\$1,404.00	\$140,119.20
		0001	5027	2039907	MISC.MISC. Lightweight Fill	0.00	6,779.00	6,779.00	CUYD	4,693.00	\$64.50	\$302,698.50
		0074	5028	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	0.00	223.00	223.00	SQYD	0.00	\$149.00	\$0.00
		0074	5029	7034221	SLAB ON CONCRETE NU-GIRDER	0.00	1,269.00	1,269.00	SQYD	0.00	\$406.00	\$0.00
		0074	5030	7034630	CONCRETE CURB (BRIDGE RAIL)	0.00	377.00	377.00	LF	0.00	\$77.00	\$0.00
		0074	5031	7056022	NU 43, PRESTRESSED CONCRETE NU-GIRDER	0.00	1,485.00	1,485.00	LF	0.00	\$221.00	\$0.00
		0074	5032	7071000	CONDUIT SYSTEM ON STRUCTURE	0.00	1.00	1.00	LS	0.00	\$9,965.00	\$0.00
		0010	5033	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	0.00	50.00	50.00	LF	0.00	\$29.40	\$0.00
		0077	5034	6079903	MISC.(70in.) Decorative Pedestrian Fence	0.00	440.00	440.00	LF	0.00	\$152.25	\$0.00
		0074	5035	7026000	PRE-BORE FOR PILING	0.00	189.00	189.00	LF	189.00	\$154.00	\$29,106.00
		0074	5036	7034216	TYPE H BARRIER	0.00	446.00	446.00	LF	0.00	\$129.00	\$0.00
		0074	5037	7101000	REINFORCING STEEL (EPOXY COATED)	0.00	31,150.00	31,150.00	LB	31,150.00	\$1.19	\$37,068.50
		0074	5038	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	0.00	1.00	1.00	LS	0.00	\$13,118.70	\$0.00
		0074	5039	7123620	DRAINAGE SYSTEM (ON STRUCTURE)	0.00	1.00	1.00	LS	0.00	\$58,912.00	\$0.00
		0074	5040	7161002	LAMINATED NEOPRENE BEARING PAD	0.00	24.00	24.00	EA	0.00	\$300.00	\$0.00
		0074	5041	7161003	LAMINATED NEOPRENE BEARING PAD (TAPERED)	0.00	8.00	8.00	EA	0.00	\$360.00	\$0.00
		0030	5042	9023340	POST, TYPE B, LONGEST ARM 40 FT. OR 12.2 M	0.00	1.00	1.00	EA	0.00	\$15,863.40	\$0.00
		0030	5043	9023340	POST, TYPE B, LONGEST ARM 40 FT. OR 12.2 M	0.00	1.00	1.00	EA	0.00	\$15,319.50	\$0.00
		0074	5044	6116010A	SLOPE PROTECTION	0.00	544.00	544.00	SQYD	0.00	\$150.00	\$0.00
		0074	5045	1099902	MISC.Value Engineering Design Costs - VECP #20-29	0.00	214,535.00	214,535.00	EA	214,535.00	\$1.00	\$214,535.00
		0074	5046	1046002	VALUE ENGINEERING	0.00	279,927.42	279,927.42	EA	279,927.42	\$1.00	\$279,927.42
		0001	5047	7250415	15 IN. PIPE GROUP C	0.00	88.00	88.00	LF	88.00	\$70.00	\$6,160.00
		0001	5048	7250418	18 IN. PIPE GROUP C	0.00	99.00	99.00	LF	0.00	\$80.00	\$0.00
		0001	5049	7320618A	18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	0.00	2.00	2.00	EA	2.00	\$900.00	\$1,800.00
		0001	5050	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	0.00	5.30	5.30	CUYD	0.00	\$100.00	\$0.00
		0001	5051	6096041	PLACING TYPE 1 ROCK DITCH LINER	0.00	5.30	5.30	CUYD	0.00	\$100.00	\$0.00
		0001	5052	6044011	PIPE COLLAR, TYPE A	0.00	2.00	2.00	EA	0.00	\$2,468.00	\$0.00
		0001	5053	1099902	MISC.Value Engineering Design Costs VECP #20-49	0.00	46,410.00	46,410.00	EA	46,410.00	\$1.00	\$46,410.00
		0001	5054	1046002	VALUE ENGINEERING	0.00	102,477.40	102,477.40	EA	102,477.40	\$1.00	\$102,477.40
	Project J	 6 2222 - To	otal Value	Posted to D	ate as of Report Generated Date							\$14,036,976.04
15-F15 Over	all - Total	Value Pos	ted to Da	ate as of Rep	ort Generated Date							\$14,036,976.04

Revision 4/1/2020 Page 24 of 81



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line	Item	Description	DWR	DWR	Quantity	Units	Location	From	Offset/	То	Offset/	Comments
Number	Code		Date	Approval Date	Posted			Station/ Log Mile	Distance	Station/ Log Mile	Distance	
0120	2063000	CLASS 3 EXCAVATION	7/15/21	7/16/21	389.00	CUYD	Adjusted payment following Change Orders 14 & 15 for class 3 excavation of precast drainage	0		0		Adjusted pay from previous entries of 8/12/20, 8/14/20, 8/18/20, 9/29/20, 10/8/20, 11/6/20, 11/9/20, and 11/18/20, Also included class 3 excavation for Pipe runs (910, 807, 707, 328, 313, 312, 302) and Drop Inlets (312, 313, 705, 716, 806, and 910)
0440	6089902	MISC. CONCRETE	7/8/21	7/13/21	1.00	EA	ADA ramp at NE corner of Jefferson Ave. and SOR					Paying for work performed on 7/2/21
0450	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER)	7/13/21	7/16/21	113.00	LF	I-64 NOR Right Turn Widening to Jefferson	0		0		
0460	6091042	CONCRETE GUTTER TYPE B	7/9/21	7/16/21	268.00	LF	Behind barrier wall on EB and WB I-64 at 22nd street bridge.	61	91	63	25	
0650	6169901	MISC.	7/15/21	7/16/21	0.25	LS	2nd Partial Payment - 50% Contract Complete	0		0		
0741	6181000	MOBILIZATION	7/15/21	7/16/21	0.25	LS	Final Payment for Mobilization - 50% Contract Complete	0		0		
1110	7261015	15 IN. PIPE GROUP A	7/14/21	7/16/21	168.00	LF	P312, P313, P807, & P910	0		0		This also accounts for Pipe that was previously overpaid
1140	7261030	30 IN. PIPE GROUP A	7/14/21	7/16/21	67.00	LE	P307 & P321	0		0		, , , , , , , , , , , , , , , , , , ,
1170	7311022		7/14/21		-1.91	FT	1007 01 021	0		0		Structure 374 was paid in correctly; this correction brings
1180	7311042	PRECAST CONCRETE DROP INLET 4 FT X 2 FT	7/15/21	7/16/21	19.00	FT	Paying for Structures: 313, 374, 393, 705, and 910					this line item to the current total Paying for structure 313-2 LF
												Paying for studente 374 - 4 LF Paying for studente 393 - 5 LF Paying for studente 393 - 5 LF Paying for studente 910 - 8 LF Paying for studente 910 - 4 LF Correcting for pay: Overpay for adjustments on ramp D: (3 LF) Underpay for structures 382, 363, 383 · 4 LF Underpay for structures 379 - 2 LF Overpay for structure 772 - 27: (5 LF) Overpay for structure 772 - 27: (5 LF) Overpay for structure 772 - 27: (5 LF) Underpay - 6 LF Underpay - 6 LF Overpay - 10 LF Total - 19LF
1190	7311053	PRECAST CONCRETE DROP INLET 5 FT X 3 FT	7/15/21	7/16/21	16.00	FT	Structures 806, 727, 328					Paying for structure 806 - 3 LF Paying for structure 328 - 3 LF Paying for structure 727 - 10 LF
1200	7319913	MISC. MANHOLES AND DROP INLETS	7/15/21	7/16/21	1.00	FT	22nd street manholes					Correcting for underpay on MH 307 and MH 309 on 11/18/2020
1210	7319913	MISC. MANHOLES AND DROP INLETS	7/15/21	7/16/21	2.00	FT	SOR 24+50					Structure 729 (60" manhole) was paid as 48" manhole fi 11 LF. Structure 724 (48" manhole) was paid as 60" manhole for 11 LF. The quantity for structure 724 was 1 LF. To correct this, the remaining 3 LF of structure 724 will be paid as line 1210.
												1 LF was subtracted due to overpay on structure 707
1220	7320615A	15 IN. GROUP A FLARED END SECT	7/15/21	7/16/21	6.00	EA	Structures 327, 330, 732, 733, 734, 811					Paying for structures 327, 330, 732, 733, 734, 811
1240	7320630A	30 IN. GROUP A FLARED END SECT	7/15/21	7/16/21	1.00	EA	Structure 321					Paying for structure 321
1320	8061017	TEMPORARY SEEDING AND MULCHING	7/14/21	7/16/21	1.60	ACRE	South Side of SOR including detention pond area and South Side of Ramp F embankment	18+50		31+50		80% Partial Payment
1490	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	7/8/21	7/13/21	182.80	SQYD	9" approach pavement at Jefferson and NOR (7/7/21) and A2 shoulder on Ramp D (7/2/21)					Paying for work performed on 7/2/21 and 7/7/21
			7/12/21	7/13/21	192.30	SQYD	9" approach at NOR and Jefferson Lanes 1 and 3					Paying for work completed on 7/9/21 Underpaid for concrete poured 7/7/21, adjusting to pay correct quantity
			7/13/21	7/16/21	110.30	SQYD	I-64 NOR Right Turn Widening to Jefferson	0		0		
			7/15/21	7/16/21	553.80	SQYD	I-64 WB NOR Lane 3 at MSE Wall section	0		0		
1500	5021308	CONCRETE PAVEMENT (8 IN. NON-REINFORCED,	7/15/21	7/16/21	553.80	SQYD	I-64 WB NOR Lane 3 at MSE Wall section	0		0		
1510	5021309	CONCRETE PAVEMENT (9 IN. NON-REINFORCED,	7/8/21	7/13/21	146.70	SQYD	Lane 2 and Lane 4 approach (9") at Jefferson and NOR intersection					Paying for work performed on 7/7/21
			7/12/21	7/13/21	192.30	SQYD	9" approach at NOR and Jefferson Lanes 1 and 3					Paying for work completed on 7/9/21 Underpaid for concrete poured 7/7/21, adjusting to pay correct quantity
			7/13/21	7/16/21	110.30	SQYD	I-64 NOR Right Turn Widening to Jefferson	0		0		
				7/13/21	36.10	SQYD	A2 shoulder on Ramp D near gore point with SOR Lane 1					Paying for work performed on 7/2/21
1550	5021340	TYPE A2 SHOULDER	7/8/21									
		TYPE A2 SHOULDER ST-STRUCTURAL	7/8/21	7/16/21	170.00	SQFT	Signs 4a, 4b, 4c, 4d on Span Box Truss No. 4	43+42				
2270	9035011A				170.00 90.00		Signs 4a, 4b, 4c, 4d on Span Box Truss No. 4 Signs 4b & 4d on Span Box Truss No. 4	43+42 43+42				
2270	9035011A 9035071A	ST-STRUCTURAL	7/14/21	7/16/21		SQFT						
2270 2290	9035011A 9035071A 9039901	ST-STRUCTURAL STF-STRUCTURAL FLUORESCENT MISC. HIGHWAY SIGNING	7/14/21 7/14/21 7/14/21	7/16/21	90.00	SQFT LS	Signs 4b & 4d on Span Box Truss No. 4	43+42		0		South side
2270 2290 2330	9035011A 9035071A 9039901 7049904 7032003	ST-STRUCTURAL STF-STRUCTURAL FLUORESCENT MISC. HIGHWAY SIGNING MISC. CLASS B CONCRETE (SUBSTRUCTURE)	7/14/21 7/14/21 7/14/21	7/16/21 7/16/21 7/16/21	90.00 1.00 2.00	SQFT LS SQFT	Signs 4b & 4d on Span Box Truss No. 4 EB 64 Sign Number 4 Span Box Truss	43+42 43+42		0		South side
2270 2290 2330 2720	9035011A 9035071A 9039901 7049904 7032003	ST-STRUCTURAL STF-STRUCTURAL FLUORESCENT MISC. HIGHWAY SIGNING MISC.	7/14/21 7/14/21 7/14/21 7/8/21 7/13/21	7/16/21 7/16/21 7/16/21	90.00 1.00 2.00	SQFT LS SQFT	Signs 4b & 4d on Span Box Truss No. 4 EB 64 Sign Number 4 Span Box Truss WB 64 Hole 40	43+42 43+42		0 4+94		South side Bearings installed on 7/2.
2270 2290 2330 2720 3000 3390	9035011A 9035071A 9035901 7049904 7032003 7161003	ST-STRUCTURAL STF-STRUCTURAL FLUORESCENT MISC. HIGHWAY SIGNING MISC. CLASS B CONCRETE (SUBSTRUCTURE) LAMINATED NEOPRENE BEARING PAD (TAPERED) DRILLED SHAFTS (6 FT. 0 IN. DIA.)	7/14/21 7/14/21 7/14/21 7/8/21 7/13/21 7/8/21 7/14/21	7/16/21 7/16/21 7/16/21 7/16/21 7/16/21 7/15/21	90.00 1.00 2.00 36.10 14.00	SQFT LS SQFT CUYD EA	Signs 4b & 4d on Span Box Truss No. 4 EB 64 Sign Number 4 Span Box Truss WB 64 Hole 40 Bridge A8831 End Bent 4 Cap Bent 2 (Back) and Bent 1 tapered bearing pads at Ewing. Bearings installed on 6/30 were Bent 2 (Ahead) and Bent 3 pads Bridge A8854 Drilled shaft 2B	43+42 43+42 0 4+3.57		4+94		
2270 2290 2330 2720 3000 3390 3480 3490	9035011A 9035071A 9039901 7049904 7032003 7161003 7011110 7011209	ST-STRUCTURAL STF-STRUCTURAL FLUORESCENT MISC. HIGHWAY SIGNING MISC. CLASS B CONCRETE (SUBSTRUCTURE) LAMINATED NEOPRENE BEARING PAD (TAPERED) DRILLED SHAFTS (6 FT. 0 IN. DIA.) ROCK SOCKETS (5 FT 6 IN. DIA.)	7/14/21 7/14/21 7/14/21 7/8/21 7/13/21 7/8/21 7/14/21 7/14/21	7/16/21 7/16/21 7/16/21 7/16/21 7/16/21 7/15/21 7/15/21	90.00 1.00 2.00 36.10 14.00 62.33	SQFT LS SQFT CUYD EA LF	Signs 4b & 4d on Span Box Truss No. 4 EB 64 Sign Number 4 Span Box Truss WB 64 Hole 40 Bridge A8831 End Bent 4 Cap Bent 2 (Back) and Bent 1 tapered bearing pads at Ewing. Bearings installed on 6/30 were Bent 2 (Ahead) and Bent 3 pads Bridge A8854 Drilled shaft 2B Bridge A8854 Drilled shaft 2B paid 24.24 this is the plan quantity 14.16 remaining on change order.	43+42 43+42 0 4+3.57		4+94		
2270 2290 2330 2720 3000 3390 3480 3490	9035011A 9035071A 9039901 7049904 7032003 7161003 7011110 7011209	ST-STRUCTURAL STF-STRUCTURAL FLUORESCENT MISC. HIGHWAY SIGNING MISC. CLASS B CONCRETE (SUBSTRUCTURE) LAMINATED NEOPRENE BEARING PAD (TAPERED) DRILLED SHAFTS (6 FT. 0 IN. DIA.) ROCK SOCKETS (5 FT 6 IN. DIA.) VIDEO CAMERA INSPECTION	7/14/21 7/14/21 7/14/21 7/8/21 7/13/21 7/8/21 7/14/21 7/14/21 7/14/21	7/16/21 7/16/21 7/16/21 7/16/21 7/16/21 7/16/21 7/15/21 7/15/21 7/16/21	90.00 1.00 2.00 36.10 14.00 62.33 24.24	SQFT LS SQFT CUYD EA LF LF LF EA	Signs 4b & 4d on Span Box Truss No. 4 EB 64 Sign Number 4 Span Box Truss WB 64 Hole 40 Bentige A8831 End Bent 4 Cap Bent 2 (Back) and Bent 1 tapered bearing pads at Ewing. Bearings installed on 6/30 were Bent 2 (Ahead) and Bent 3 pads Bridge A8854 Drilled shaft 2B Bridge A8854 Drilled shaft 2B Bridge A8854 Frilled shaft 2B Bridge A8854 Frilled shaft 2B Ramp F Bent 2B	43+42 43+42 0 4+3.57 0 0 33+61.42		4+94		
2270 2290 2330 2720 3000 3390 3480 3490 3500 3520	9035011A 9035071A 9039901 7049904 7032003 7161003 7011110 7011209 7011300 7011600	ST-STRUCTURAL STF-STRUCTURAL FLUORESCENT MISC. HIGHWAY SIGNING MISC. CLASS B CONCRETE (SUBSTRUCTURE) LAMINATED NEOPRENE BEARING PAD (TAPERED) DRILLED SHAFTS (6 FT. 0 IN. DIA.) ROCK SOCKETS (5 FT 6 IN. DIA.) VIDEO CAMERA INSPECTION SONIC LOGGING TESTING	7/14/21 7/14/21 7/14/21 7/8/21 7/13/21 7/8/21 7/14/21 7/14/21 7/14/21 7/15/21	7/16/21 7/16/21 7/16/21 7/16/21 7/16/21 7/15/21 7/15/21 7/16/21 7/16/21	90.00 1.00 2.00 36.10 14.00 62.33 24.24 1.00	SQFT LS SQFT CUYD EA LF LF LF EA	Signs 4b & 4d on Span Box Truss No. 4 EB 64 Sign Number 4 Span Box Truss WB 64 Hole 40 Bridge A8831 End Bent 4 Cap Bent 2 (Back) and Bent 1 tapered bearing pads at Ewing. Bearings installed on 6/30 were Bent 2 (Ahead) and Bent 3 pads Bridge A8854 Drilled shaft 2B Bridge A8854 Drilled shaft 2B Bridge A8854 Drilled shaft 2B Ramp F Bent 3 CSL	43+42 43+42 0 4+3.57		4+94		
2270 2290 2330 2720 3000 3390 3480 3490 3500 3520 3630	9035011A 9035071A 9039901 7049904 7032003 7161003 7011110 7011209 7011300 7061060	ST-STRUCTURAL STF-STRUCTURAL FLUORESCENT MISC. HIGHWAY SIGNING MISC. CLASS B CONCRETE (SUBSTRUCTURE) LAMINATED NEOPRENE BEARING PAD (TAPERED) DRILLED SHAFTS (6 FT. 0 IN. DIA.) ROCK SOCKETS (5 FT 6 IN. DIA.) VIDEO CAMERA INSPECTION SONIC LOGGING TESTING REINFORCING STEEL (BRIDGES)	7/14/21 7/14/21 7/14/21 7/8/21 7/13/21 7/8/21 7/14/21 7/14/21 7/15/21 7/15/21	7/16/21 7/16/21 7/16/21 7/16/21 7/16/21 7/15/21 7/15/21 7/16/21 7/16/21 7/16/21	90.00 1.00 2.00 36.10 14.00 62.33 24.24 1.00 1.00 35,330.00	SQFT LS SQFT CUYD EA LF LF EA EA	Signs 4b & 4d on Span Box Truss No. 4 EB 64 Sign Number 4 Span Box Truss WB 64 Hole 40 Bridge A8831 End Bent 4 Cap Bent1 2 (Back) and Bent 1 tapered bearing pads at Ewing, Bearings installed on 6/30 were Bent 2 (Ahead) and Bent 3 pads Bridge A8854 Drilled shaft 2B Bridge A8854 Drilled shaft 2B paid 24.24 this is the plan quantity 14.16 remaining on change order. Ramp F Bent 3 CSL Bridge A8854 Bent 2B Drilled Shaft and Rock Socket	43+42 43+42 0 4+3.57 0 0 33+61.42		4+94		
2270 2290 2330 2720 3000 3390 3480 3490 3500 3520 3630 3640	9035011A 9035071A 9039901 7049904 7032003 7161003 7011110 7011209 7011300 7061060 7061070	ST-STRUCTURAL STF-STRUCTURAL FLUORESCENT MISC. HIGHWAY SIGNING MISC. CLASS B CONCRETE (SUBSTRUCTURE) LAMINATED NEOPRENE BEARING PAD (TAPERED) DRILLED SHAFTS (6 FT. 0 IN. DIA.) ROCK SOCKETS (5 FT 6 IN. DIA.) VIDEO CAMERA INSPECTION SONIC LOGGING TESTING REINFORCING STEEL (BRIDGES) MECHANICAL BAR SPLICE	7/14/21 7/14/21 7/14/21 7/8/21 7/8/21 7/13/21 7/14/21 7/14/21 7/14/21 7/15/21 7/15/21	7/16/21 7/16/21 7/16/21 7/16/21 7/16/21 7/15/21 7/15/21 7/16/21 7/16/21 7/16/21 7/16/21	90.00 1.00 2.00 36.10 14.00 62.33 24.24 1.00 1.00 35.330.00 24.00	SQFT LS SQFT CUYD EA LF LF EA EA LB EA	Signs 4b & 4d on Span Box Truss No. 4 EB 64 Sign Number 4 Span Box Truss WB 64 Hole 40 Bridge A8831 End Bent 4 Cap Bent 2 (Back) and Bent 1 tapered bearing pads at Ewing. Bearings installed on 6/30 were Bent 2 (Ahead) and Bent 3 pads Bridge A8654 Drilled shaft 2B Bridge A8654 Drilled shaft 2B paid 24.24 this is the plan quantity 14.16 remaining on change order. Ramp F Bent 2B Ramp F Bent 3 CSL Bridge A8654 Bent 2B Drilled Shaft and Rock Socket Bridge A8654 Bent 2B Drilled Shaft and Rock Socket	43+42 0 43+45 0 4+3.57 0 0 33+61.42 34+62.59		4+94 0 0		Bearings installed on 7/2.
2270 2290 2330 2720 3000 3390 3480 3490 3500 3520 3630 3640 5045	9035011A 9035071A 9039901 7049904 7032003 7161003 7011110 7011209 7011300 7061060 7061070 1099902	ST-STRUCTURAL STF-STRUCTURAL FLUORESCENT MISC. HIGHWAY SIGNING MISC. CLASS B CONCRETE (SUBSTRUCTURE) LAMINATED NEOPRENE BEARING PAD (TAPERED) DRILLED SHAFTS (6 FT. 0 IN. DIA.) ROCK SOCKETS (5 FT 6 IN. DIA.) VIDEO CAMERA INSPECTION SONIC LOGGING TESTING REINFORCING STEEL (BRIDGES) MECHANICAL BAR SPLICE MISC.	7/14/21 7/14/21 7/14/21 7/8/21 7/8/21 7/13/21 7/14/21 7/14/21 7/15/21 7/15/21 7/15/21	7/16/21 7/16/21 7/16/21 7/16/21 7/16/21 7/15/21 7/15/21 7/16/21 7/16/21 7/16/21 7/16/21	90.00 1.00 2.00 36.10 14.00 62.33 24.24 1.00 1.00 35,330.00 24.00 214,535.00	SQFT LS SQFT CUYD EA LF LF EA EA EA EA	Signs 4b & 4d on Span Box Truss No. 4 EB 64 Sign Number 4 Span Box Truss WB 64 Hole 40 Bridge A8831 End Bent 4 Cap Bent 2 (Back) and Bent 1 tapered bearing pads at Ewing. Bearings installed on 6/30 were Bent 2 (Ahead) and Bent 3 pads Bridge A8854 Drilled shaft 2B Bridge A8854 Drilled shaft 2B paid 24.24 this is the plan quantity 14.16 remaining on change order. Ramp F Bent 2B Ramp F Bent 3 CSL Bridge A8854 Bent 2B Drilled Shaft and Rock Socket Bridge A8854 Bent 2B Drilled Shaft and Rock Socket Bridge A8854 Bent 2B Drilled Shaft and Rock Socket	43+42 43+42 0 4+3.57 0 33+61.42 34+62.59		4+94 0 0		Bearings installed on 7/2. VE Change Order 12
2270 2290 2330 2720 3000 3390 3480 3500 3520 3630 3640 5045 5046	9035011A 9035071A 9039901 7049904 7032003 7161003 7011110 7011209 7011300 7061060 7061070 1099902 1046002	ST-STRUCTURAL STF-STRUCTURAL FLUORESCENT MISC. HIGHWAY SIGNING MISC. CLASS B CONCRETE (SUBSTRUCTURE) LAMINATED NEOPRENE BEARING PAD (TAPERED) DRILLED SHAFTS (6 FT. 0 IN. DIA.) ROCK SOCKETS (5 FT 6 IN. DIA.) VIDEO CAMERA INSPECTION SONIC LOGGING TESTING REINFORCING STEEL (BRIDGES) MECHANICAL BAR SPLICE MISC. VALUE ENGINEERING	7/14/21 7/14/21 7/14/21 7/8/21 7/8/21 7/8/21 7/14/21 7/14/21 7/14/21 7/15/21 7/15/21 7/15/21	7/16/21 7/16/21 7/16/21 7/16/21 7/16/21 7/15/21 7/15/21 7/16/21 7/16/21 7/16/21 7/16/21 7/16/21 7/16/21 7/16/21	90.00 1.00 2.00 36.10 14.00 62.33 24.24 1.00 1.00 35.330.00 24.00 279,927.42	SQFT LS SQFT CUYD EA LF LF EA EA LB EA EA	Signs 4b & 4d on Span Box Truss No. 4 EB 64 Sign Number 4 Span Box Truss WB 64 Hole 40 Bertidge A8831 End Bent 4 Cap Bent 2 (Back) and Bent 1 tapered bearing pads at Ewing. Bearings installed on 6/30 were Bent 2 (Ahead) and Bent 3 pads Bridge A8854 Drilled shaft 2B Ramp F Bent 3 CSL Bridge A8854 Bent 2B Drilled Shaft and Rock Socket Bridge A8854 Bent 2B Drilled Shaft and Rock Socket 22nd St VE Design Costs to HNTB	43+42 0 4+3.57 0 0 33+61.42 34+62.59		0 0 0		Bearings installed on 7/2.
2270 2290 2330 2720 3000 3390 3480 3500 3520 3630 3640 5045 5046 5047	9035011A 9035071A 9039901 7049904 7032003 7161003 7011110 7011209 7011300 7051000 7061000 7061070 1099902 1046002 7250415	ST-STRUCTURAL STF-STRUCTURAL FLUORESCENT MISC. HIGHWAY SIGNING MISC. CLASS B CONCRETE (SUBSTRUCTURE) LAMINATED NEOPRENE BEARING PAD (TAPERED) DRILLED SHAFTS (6 FT. 0 IN. DIA.) ROCK SOCKETS (5 FT 6 IN. DIA.) VIDEO CAMERA INSPECTION SONIC LOGGING TESTING REINFORCING STEEL (BRIDGES) MECHANICAL BAR SPLICE MISC. VALUE ENGINEERING 15 IN. PIPE CULVERT GROUP C	7/14/21 7/14/21 7/14/21 7/8/21 7/8/21 7/8/21 7/14/21 7/14/21 7/14/21 7/15/21 7/15/21 7/15/21 7/15/21 7/15/21	7/16/21 7/16/21 7/16/21 7/16/21 7/16/21 7/15/21 7/15/21 7/16/21 7/16/21 7/16/21 7/16/21 7/16/21 7/16/21 7/16/21 7/16/21	90.00 1.00 2.00 36.10 14.00 62.33 24.24 1.00 1.00 35.330.00 24.00 214,535.00 279,927.42 88.00	SQFT LS SQFT CUYD EA LF LF EA EA EA EA EA EA	Signs 4b & 4d on Span Box Truss No. 4 EB 64 Sign Number 4 Span Box Truss WB 64 Hole 40 Bridge A8831 End Bent 4 Cap Bent 2 (Back) and Bent 1 tapered bearing pads at Ewing. Bearings installed on 6/30 were Bent 2 (Ahead) and Bent 3 pads Bridge A8854 Drilled shaft 2B Bridge A8854 Bent 2B Bridge A8854 Bent 2B Drilled Shaft and Rock Socket Bridge A8854 Bent 2B Drilled Shaft and Rock Socket 22nd St VE Design Costs to HNTB 22nd St VE 50% Savings to KCI	43+42 43+42 0 4+3.57 0 33+61.42 34+62.59		4+94 0 0		Bearings installed on 7/2. VE Change Order 12 VE Change Order 12
2270 2290 2330 2720 3000 3390 3480 3500 3520 3630 3640 5045 5046	9035011A 9035071A 9039901 7049904 7032003 7161003 7011110 7011209 7011300 7051000 7061000 7061070 1099902 1046002 7250415	ST-STRUCTURAL STF-STRUCTURAL FLUORESCENT MISC. HIGHWAY SIGNING MISC. CLASS B CONCRETE (SUBSTRUCTURE) LAMINATED NEOPRENE BEARING PAD (TAPERED) DRILLED SHAFTS (6 FT. 0 IN. DIA.) ROCK SOCKETS (5 FT 6 IN. DIA.) VIDEO CAMERA INSPECTION SONIC LOGGING TESTING REINFORCING STEEL (BRIDGES) MECHANICAL BAR SPLICE MISC. VALUE ENGINEERING 15 IN. PIPE CULVERT GROUP C 18 IN. GROUP A FLARED END SECT	7/14/21 7/14/21 7/14/21 7/8/21 7/8/21 7/8/21 7/14/21 7/14/21 7/14/21 7/15/21 7/15/21 7/15/21	7/16/21 7/16/21 7/16/21 7/16/21 7/16/21 7/15/21 7/15/21 7/16/21 7/16/21 7/16/21 7/16/21 7/16/21 7/16/21 7/16/21 7/16/21	90.00 1.00 2.00 36.10 14.00 62.33 24.24 1.00 1.00 35.330.00 24.00 279,927.42	SQFT LS SQFT CUYD EA LF LF EA EA LB EA EA LC EA EA EA EA	Signs 4b & 4d on Span Box Truss No. 4 EB 64 Sign Number 4 Span Box Truss WB 64 Hole 40 Bertidge A8831 End Bent 4 Cap Bent 2 (Back) and Bent 1 tapered bearing pads at Ewing. Bearings installed on 6/30 were Bent 2 (Ahead) and Bent 3 pads Bridge A8854 Drilled shaft 2B Ramp F Bent 3 CSL Bridge A8854 Bent 2B Drilled Shaft and Rock Socket Bridge A8854 Bent 2B Drilled Shaft and Rock Socket 22nd St VE Design Costs to HNTB	43+42 0 4+3.57 0 0 33+61.42 34+62.59		0 0 0		Bearings installed on 7/2. VE Change Order 12

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 4/1/2020 Page 25 of 81



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	0050	CLASS A EXCAVATION	Price FUEL		4	Sep 2, 2020	SYSTEM	\$24.92	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					4	Sep 2, 2020	SYSTEM	\$7.00	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					5	Sep 16, 2020	SYSTEM	\$349.60	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					7	Oct 16, 2020	SYSTEM	\$800.00	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					9	Nov 16, 2020	SYSTEM	\$1,020.00	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					10	Dec 2, 2020	SYSTEM	\$204.00	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					11	Dec 16, 2020	SYSTEM	\$1,142.60	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					13	Jan 19, 2021	SYSTEM	\$201.00	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					14	Feb 2, 2021	SYSTEM	\$3,086.82	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					17	Mar 16, 2021	SYSTEM	\$5,917.63	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					18	Apr 2, 2021	SYSTEM	\$397.80	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					19	Apr 16, 2021	SYSTEM	\$3,640.00	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					20	May 3, 2021	SYSTEM	\$2,497.82	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					21	May 17, 2021	SYSTEM	\$2,962.18	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					22	Jun 2, 2021	SYSTEM	\$1,579.26	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$23,830.63	
			Price FUEL -	Total				\$23,830.63	
	0050 -	Total						\$23,830.63	
	0060	COMPACTING EMBANKMENT	Material		5	Sep 16, 2020	SYSTEM	\$74,940.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	Sep 16, 2020	SYSTEM	(\$74,940.00)	
					6	Oct 1, 2020	SYSTEM	\$74,940.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Oct 1, 2020	SYSTEM	(\$74,940.00)	
					7	Oct 16, 2020	SYSTEM	\$112,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Oct 16, 2020	SYSTEM	(\$112,440.00)	
					8	Nov 2, 2020	SYSTEM	\$112,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					8	Nov 2, 2020	SYSTEM	(\$112,440.00)	
					9	Nov 16, 2020	SYSTEM	\$157,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user hillto overridding Payment Estimate Exception 1 on the current Payment Estimate.
					9	Nov 16, 2020	SYSTEM	(\$157,440.00)	
					10	Dec 2, 2020	SYSTEM	\$166,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					10	Dec 2, 2020	SYSTEM	(\$166,440.00)	
					11	Dec 16, 2020	SYSTEM	\$195,990.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user schlag1 overridding Payment Estimate Exception 1 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	0060	COMPACTING EMBANKMENT	Material		11	Dec 16, 2020	SYSTEM	(\$195,990.00)	
					12	Jan 4, 2021	SYSTEM	\$195,990.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					12	Jan 4, 2021	SYSTEM	(\$195,990.00)	
					13	Jan 19, 2021	SYSTEM	\$195,990.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schlag1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					13	Jan 19, 2021	SYSTEM	(\$195,990.00)	
					14	Feb 2, 2021	SYSTEM	\$197,490.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					14	Feb 2, 2021	SYSTEM	(\$197,490.00)	
					15	Feb 16, 2021	SYSTEM	\$197,490.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schlag1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					15	Feb 16, 2021	SYSTEM	(\$197,490.00)	
					16	Mar 2, 2021	SYSTEM	\$197,490.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					16	Mar 2, 2021	SYSTEM	(\$197,490.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0060 -							\$0.00	
	0140	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	Material		22	Jun 2, 2021	SYSTEM	\$1,320.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$1,320.00)	
					23	Jun 16, 2021	SYSTEM	\$1,518.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$1,518.00)	
					24	Jul 1, 2021	SYSTEM	\$1,573.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$1,573.00)	
					25	Jul 16, 2021	SYSTEM	\$1,573.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$1,573.00)	
				- Total				\$0.00	
			Material - To	tal			01/0===	\$0.00	
			Price FUEL		22	Jun 2, 2021	SYSTEM	\$23.04	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					23	Jun 16, 2021	SYSTEM	\$3.49	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					24	Jul 1, 2021	SYSTEM	\$0.97	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$27.50	
			Price FUEL -	Total				\$27.50	
	0140 -							\$27.50	
	0150	TYPE 5 AGGREGATE FOR BASE	Material		21	May 17, 2021	SYSTEM	\$1,656.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					21	May 17,	SYSTEM	(\$1,656.00)	



Majerial Total	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
22	J6I2222	0150		Material			2021			
2021 23 34 16 SYSTEM \$1,680.00 24 24 34 15 SYSTEM \$1,680.00 25 34 16 SYSTEM \$1,680.00 24 34 17 SYSTEM \$1,680.00 25 34 16 SYSTEM \$1,680.00 26 34 35 SYSTEM \$1,680.00 27 SYSTEM \$1,680.00 SysTEM \$1,680.						22		SYSTEM	\$1,656.00	Estimate Item Adjustment (0009) due to user hillt5 overridding Payment
2021 2021						22		SYSTEM	(\$1,656.00)	
201						23		SYSTEM	\$1,656.00	Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment
24						23		SYSTEM	(\$1,656.00)	
24						24		SYSTEM	\$1,656.00	Estimate Item Adjustment (0004) due to user hillt5 overridding Payment
25						24		SYSTEM	(\$1,656.00)	,
Material - Total S0.00						25	Jul 16,	SYSTEM	\$1,656.00	Estimate Item Adjustment (0009) due to user kloepj1 overridding Payment
National Total Support Suppo						25		SYSTEM	(\$1,656.00)	Estimate Exception 2 on the current Payment Estimate.
Material - Total					- Total		2021		\$0.00	
Price FUEL 21 May 17, 2VSTEM 513.82 Reference item Price Adjustment Index Adjustment Type applied is FUEL 1019 Total 513.82 S13.82 S13.				Material - Tot						
150						21		SYSTEM		Reference Item Price Adjustment Index Adjustment Type applied is FUEL
STANUEL (A) OR CRUSHED STONE (B) 18					- Total				\$13.82	
18				Price FUEL -	Total				\$13.82	
Estimate Item Adjustment (10003) due to user klosep1 overridding Payment Estimate Exception 2 on the current Payment Estimate.		0150 -	Total						\$13.82	
2021 19		0160	CRUSHED STONE	Material		18		SYSTEM	\$34,656.00	Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment
Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment Estimate Exception 2 on the current Payment Estimate. 19						18		SYSTEM	(\$34,656.00)	
2021 20 May 3, 2VSTEM 234,656.00 2021 21 May 17, 2VSTEM 234,656.00 21 May 17, SYSTEM 234,656.00 22 May 17, SYSTEM 234,656.00 23 Jun 2, 2021 24 Jun 2, 2021 25 Jun 16, SYSTEM 234,656.00 26 Jun 16, SYSTEM 234,656.00 27 Jun 16, SYSTEM 234,656.00 28 Jun 16, 2021 29 Jun 17, SYSTEM 234,656.00 2021 2021 2021 2021 2021 2021 2021 2						19		SYSTEM	\$34,656.00	Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment
Estimate Item Adjustment (0007) due to user hillts overridding Payment Estimate Exception 2 on the current Payment Estimate. 20 May 3, 2021 21 May 17, 2021 22 May 17, 2021 23 Jun 2, 2021 24 Jun 2, 2021 25 Jun 16, 2021 27 SYSTEM \$34,656.00 28 SYSTEM \$34,656.00 29 Jun 16, 2021 20 Jun 16, 2021 20 Jun 16, 2021 20 Jun 16, 2021 20 SYSTEM \$34,656.00 21 SYSTEM \$34,656.00 22 Jun 17, 2021 23 Jun 18, 2021 24 Jul 1, 2021 25 SYSTEM \$34,656.00 26 SYSTEM \$34,656.00 27 SYSTEM \$34,656.00 28 SYSTEM \$34,656.00 29 Jun 16, 2021 20 Jun 16, 2021 20 SYSTEM \$34,656.00 21 SYSTEM \$34,656.00 22 SYSTEM \$34,656.00 23 Jun 16, 2021 24 Jul 1, 2021 25 SYSTEM \$34,656.00 26 SYSTEM \$34,656.00 27 SYSTEM SYSTE						19		SYSTEM	(\$34,656.00)	
21 May 17, 2021 \$34,656.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate. 21 May 17, 2021 \$YSTEM \$34,656.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate. 22 Jun 2, 2021 \$YSTEM \$34,656.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate. 23 Jun 16, 2021 \$YSTEM \$34,656.00 This adjustment offsets the original system-generated Material Payment Estimate tem Adjustment (0006) due to user hillts overridding Payment Estimate Exception 4 on the current Payment Estimate Estimate tem Adjustment (0006) due to user kloepj1 overridding Payment Estimate Exception 4 on the current Payment Estimate. 23 Jun 16, 2021 \$YSTEM \$34,656.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate. 24 Jul 1, 2021 \$YSTEM \$34,656.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate. 24 Jul 1, 2021 \$YSTEM \$34,656.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate.						20		SYSTEM	\$34,656.00	Estimate Item Adjustment (0007) due to user hillt5 overridding Payment
Estimate Item Adjustment (0006) due to user hill15 overridding Payment Estimate Exception 3 on the current Payment Estimate. 21 May 17, 2021 22 Jun 2, 2021 SYSTEM \$34,656.00 23 Jun 12, 2021 23 Jun 16, 2021 24 Jul 1, 2021 25 Jul 1, 2021 26 SYSTEM \$34,656.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kloep]1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hermit overridding Payment Estimate Item Adjustment (0005) due to user hermit overridding Payment Estimate Exception 4 on the current Payment Estimate. 24 Jul 1, 2021 SYSTEM (\$34,656.00) This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate.						20		SYSTEM	(\$34,656.00)	
21 May 17, 2021 SYSTEM (\$34,656.00) 22 Jun 2, 2021 SYSTEM \$34,656.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hillt5 overridding Payment Estimate Exception 4 on the current Payment Estimate. 22 Jun 2, 2021 SYSTEM (\$34,656.00) 23 Jun 16, 2021 SYSTEM \$34,656.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kloep/1 overridding Payment Estimate Exception 4 on the current Payment Estimate. 23 Jun 16, 2021 SYSTEM (\$34,656.00) 24 Jul 1, 2021 SYSTEM \$34,656.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user herrmt1 overridding Payment Estimate Item Adjustment (0005) due to user herrmt1 overridding Payment Estimate Exception 4 on the current Pa						21		SYSTEM	\$34,656.00	Estimate Item Adjustment (0006) due to user hillt5 overridding Payment
22 Jun 2, 2021 SYSTEM \$34,656.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hillt5 overridding Payment Estimate Exception 4 on the current Payment Estimate. 23 Jun 16, 2021 SYSTEM \$34,656.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment Estimate Exception 4 on the current Payment Estimate. 23 Jun 16, 2021 SYSTEM (\$34,656.00) 24 Jul 1, 2021 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hermt1 overridding Payment Estimate Item Adjustment (0005) due to user hermt1 overridding Payment Estimate Item Adjustment (0005) due to user hermt1 overridding Payment Estimate Item Adjustment (0005) due to user hermt1 overridding Payment Estimate Exception 4 on the current Payment Estimate. 24 Jul 1, 2021 SYSTEM (\$34,656.00) 25 Jul 16, SYSTEM \$34,656.00 This adjustment offsets the original system-generated Material Payment						21		SYSTEM	(\$34,656.00)	
22 Jun 2, 2021 SYSTEM (\$34,656.00) 23 Jun 16, 2021 SYSTEM \$34,656.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment Estimate Exception 4 on the current Payment Estimate. 23 Jun 16, 2021 SYSTEM (\$34,656.00) 24 Jul 1, 2021 SYSTEM \$34,656.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user herrmt1 overridding Payment Estimate Exception 4 on the current Payment Estimate. 24 Jul 1, 2021 SYSTEM (\$34,656.00) 25 Jul 16, SYSTEM \$34,656.00 This adjustment offsets the original system-generated Material Payment						22	Jun 2,	SYSTEM	\$34,656.00	Estimate Item Adjustment (0010) due to user hillt5 overridding Payment
23 Jun 16, 2021 \$\frac{1}{2021}\$ \$						22		SYSTEM	(\$34,656.00)	
23 Jun 16, 2021 (\$34,656.00) 24 Jul 1, 2021 (\$34,656.00) 25 Jul 16, SYSTEM (\$34,656.00) SYSTEM (\$34,656.00) This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user herrmt1 overridding Payment Estimate Exception 4 on the current Payment Estimate. 24 Jul 1, 2021 (\$34,656.00) 25 Jul 16, SYSTEM \$34,656.00 This adjustment offsets the original system-generated Material Payment						23	Jun 16,	SYSTEM	\$34,656.00	Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment
24 Jul 1, 2021 \$34,656.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user herrmt1 overridding Payment Estimate Exception 4 on the current Payment Estimate. 24 Jul 1, 2021 \$SYSTEM (\$34,656.00) 25 Jul 16, \$SYSTEM \$34,656.00 This adjustment offsets the original system-generated Material Payment						23		SYSTEM	(\$34,656.00)	
24 Jul 1, 2021 (\$34,656.00) 25 Jul 16, SYSTEM \$34,656.00 This adjustment offsets the original system-generated Material Payment						24	Jul 1,	SYSTEM	\$34,656.00	Estimate Item Adjustment (0005) due to user herrmt1 overridding Payment
25 Jul 16, SYSTEM \$34,656.00 This adjustment offsets the original system-generated Material Payment						24		SYSTEM	(\$34,656.00)	Estimate Endopolis 4 on the current agricult agricult.
Estimate Exception 4 on the current Payment Estimate.						25		SYSTEM	\$34,656.00	Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	0160	GRAVEL (A) OR CRUSHED STONE	Material		25	Jul 16, 2021	SYSTEM	(\$34,656.00)	
		(B)		- Total				\$0.00	
			Material - To	tal				\$0.00	
	0160 -	Total						\$0.00	
	0200	CONCRETE PAVEMENT (8 IN. NON-REINF)	Material		21	May 17, 2021	SYSTEM	\$1,798.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$1,798.30)	
					22	Jun 2, 2021	SYSTEM	\$1,161.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0061) due to user hillt5 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$1,161.30)	
					23	Jun 16, 2021	SYSTEM	\$14,366.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$14,366.80)	
					24	Jul 1, 2021	SYSTEM	\$14,366.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user herrmt1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$14,366.80)	
					25	Jul 16, 2021	SYSTEM	\$14,366.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$14,366.80)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Price FUEL		21	May 17, 2021	SYSTEM	\$28.19	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					22	Jun 2, 2021	SYSTEM	(\$9.98)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					23	Jun 16, 2021	SYSTEM	\$208.59	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$226.80	
			Price FUEL -	Total				\$226.80	
	0200 -	Total						\$226.80	
	0210	TYPE A2 SHOULDER	Material		6	Oct 1, 2020	SYSTEM	\$14,241.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user kloepj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					6	Oct 1, 2020	SYSTEM	(\$14,241.60)	
					7	Oct 16, 2020	SYSTEM	\$14,241.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user kloepj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					7	Oct 16, 2020	SYSTEM	(\$14,241.60)	
					8	Nov 2, 2020	SYSTEM	\$14,241.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user hillt5 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					8	Nov 2, 2020	SYSTEM	(\$14,241.60)	
					9	Nov 16, 2020	SYSTEM	\$14,241.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user hillt5 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					9	Nov 16, 2020	SYSTEM	(\$14,241.60)	
					10	Dec 2, 2020	SYSTEM	\$14,880.96	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user kloepj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					10	Dec 2,	SYSTEM	(\$14,880.96)	



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
222	0210	TYPE A2 SHOULDER	Material			2020			
		SHOULDER			11	Dec 16, 2020	SYSTEM	\$14,880.96	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user schlag1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					11	Dec 16, 2020	SYSTEM	(\$14,880.96)	
					12	Jan 4, 2021	SYSTEM	\$14,880.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					12	Jan 4, 2021	SYSTEM	(\$14,880.96)	
					13	Jan 19, 2021	SYSTEM	\$14,880.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schlag1 overridding Paymen Estimate Exception 6 on the current Payment Estimate.
					13	Jan 19, 2021	SYSTEM	(\$14,880.96)	
					14	Feb 2, 2021	SYSTEM	\$14,880.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hillt5 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					14	Feb 2, 2021	SYSTEM	(\$14,880.96)	
					15	Feb 16, 2021	SYSTEM	\$14,880.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schlag1 overridding Paymer Estimate Exception 6 on the current Payment Estimate.
					15	Feb 16, 2021	SYSTEM	(\$14,880.96)	
					16	Mar 2, 2021	SYSTEM	\$14,880.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kloepj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					16	Mar 2, 2021	SYSTEM	(\$14,880.96)	
					17	Mar 16, 2021	SYSTEM	\$14,880.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					17	Mar 16, 2021	SYSTEM	(\$14,880.96)	
					18	Apr 2, 2021	SYSTEM	\$14,880.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kloepj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					18	Apr 2, 2021	SYSTEM	(\$14,880.96)	
					19	Apr 16, 2021	SYSTEM	\$14,880.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kloepj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					19	Apr 16, 2021	SYSTEM	(\$14,880.96)	
					20	May 3, 2021	SYSTEM	\$14,880.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					20	May 3, 2021	SYSTEM	(\$14,880.96)	
					21	May 17, 2021	SYSTEM	\$14,880.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hillt5 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$14,880.96)	
					22	Jun 2, 2021	SYSTEM	\$14,880.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hillts overridding Payment Estimate Exception 12 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$14,880.96)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	0210 -	Total						\$0.00	
	0270	WATER - UTILITY	Construction Stockpile		11	Dec 16, 2020	SYSTEM	(\$43,011.57)	Payment Estimate Item Adjustment generated Stockpile Transaction



Type Adjustment Type Date By J612222 0270 WATER - UTILITY Construction 13 Jan 19, SYSTEM (\$8,549.46) Payment Estimate Item Adjustment of	
	concepted Ctackwile Transaction
ITEM Stockpile 2021	
15 Feb 16, 2021 (\$23,758.77) Payment Estimate Item Adjustment gr	lenerated Stockpile Transaction
- Total (\$75,319.80)	
Construction Stockpile - Total (\$75,319.80)	
Construction 6 Oct 1, SYSTEM \$75,319.80 Payment Estimate Item Adjustment grant Stockpile 2020 STMI	enerated Stockpile Transaction
- Total \$75,319.80	
Construction Stockpile STMI - Total \$75,319.80	
0270 - Total \$0.00	
0280 WATER - UTILITY Construction ITEM Stockpile 11 Dec 16, SYSTEM (\$13,214.00) Payment Estimate Item Adjustment gr	enerated Stockpile Transaction
- Total (\$13,214.00)	
Construction Stockpile - Total (\$13,214.00)	
Construction 6 Oct 1, SYSTEM \$13,214.00 Payment Estimate Item Adjustment gr	reperated Stockpile Transaction
Stockpile 2020 STMI	onorated eteotopic Handdollon
Construction Stockpile STMI - Total \$13,214.00	
0280 - Total \$0.00	
0380 MODIFIED Material 22 Jun 2, SYSTEM \$15,062.00 This adjustment offsets the original sy Estimate Item Adjustment (0012) due Estimate Exception 16 on the current	to user hillt5 overridding Payment
22 Jun 2, 2021 SYSTEM (\$15,062.00)	
23 Jun 16, 2021 SYSTEM \$15,572.00 This adjustment offsets the original sy Estimate Item Adjustment (0009) due Estimate Exception 19 on the current	to user kloepj1 overridding Payment
23 Jun 16, 2021 (\$15,572.00)	
24 Jul 1, 2021 SYSTEM \$15,572.00 This adjustment offsets the original sy Estimate Item Adjustment (0007) due Estimate Exception 13 on the current	to user herrmt1 overridding Payment
24 Jul 1, SYSTEM (\$15,572.00)	
25 Jul 16, 2021 SYSTEM \$15,572.00 This adjustment offsets the original sy Estimate Item Adjustment (0012) due Estimate Exception 13 on the current	to user kloepj1 overridding Payment
25 Jul 16, 2021 (\$15,572.00)	
-Total \$0.00	
Material - Total \$0.00	
0380 - Total \$0.00	
0410 PAVED APPROACH, 8 IN. 21 May 17, 2021 \$9,037.50 This adjustment offsets the original sy Estimate Item Adjustment (0012) due Estimate Exception 19 on the current	to user hillt5 overridding Payment
21 May 17, SYSTEM (\$9,037.50)	,
22 Jun 2, 2021 SYSTEM \$9,037.50 This adjustment offsets the original sy Estimate Item Adjustment (0013) due Estimate Exception 19 on the current	to user hillt5 overridding Payment
22 Jun 2, 2021 SYSTEM (\$9,037.50)	
23 Jun 16, 2021 \$9,037.50 This adjustment offsets the original sy Estimate Item Adjustment (0010) due Estimate Exception 22 on the current	to user kloepj1 overridding Payment
23 Jun 16, 2021 (\$9,037.50)	
24 Jul 1, 2021 SYSTEM \$9,037.50 This adjustment offsets the original sy Estimate Item Adjustment (0008) due Estimate Exception 14 on the current	to user herrmt1 overridding Payment
24 Jul 1, SYSTEM (\$9,037.50)	



ject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
222	0410	PAVED APPROACH, 8 IN.	Material		25	Jul 16, 2021	SYSTEM	\$9,037.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.				
					25	Jul 16, 2021	SYSTEM	(\$9,037.50)					
				- Total				\$0.00					
			Material - To	rial - Total				\$0.00					
			Price FUEL		21	May 17, 2021	SYSTEM	\$55.53	Reference Item Price Adjustment Index Adjustment Type applied is FUEL				
				- Total				\$55.53					
			Price FUEL -	Total				\$55.53					
	0410 -	Total						\$55.53					
	0420	CONCRETE SIDEWALK, 4 IN.	Material		22	Jun 2, 2021	SYSTEM	\$6,120.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hillt5 overridding Payment Estimate Exception 22 on the current Payment Estimate.				
					22	Jun 2, 2021	SYSTEM	(\$6,120.00)					
					23	Jun 16, 2021	SYSTEM	\$7,007.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 23 on the current Payment Estimate.				
					23	Jun 16, 2021	SYSTEM	(\$7,007.40)					
					24	Jul 1, 2021	SYSTEM	\$7,262.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user herrmt1 overridding Payment Estimate Exception 15 on the current Payment Estimate.				
					24	Jul 1, 2021	SYSTEM	(\$7,262.40)					
					25	Jul 16, 2021	SYSTEM	\$7,262.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.				
					25	Jul 16, 2021	SYSTEM	(\$7,262.40)					
				- Total				\$0.00					
			Material - Total					\$0.00					
	0420 -							\$0.00					
	0440	MISC. CONCRETE	Material		23	Jun 16, 2021	SYSTEM	\$7,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.				
					23	Jun 16, 2021	SYSTEM	(\$7,100.00)					
						24	Jul 1, 2021	SYSTEM	\$10,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user herrmt1 overridding Payment Estimate Exception 16 on the current Payment Estimate.			
						24	Jul 1, 2021	SYSTEM	(\$10,650.00)				
					25	Jul 16, 2021	SYSTEM	\$14,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.				
					25	Jul 16,	SYSTEM	\$14,200.00 (\$14,200.00)	Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment				
				- Total		Jul 16, 2021 Jul 16,			Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment				
			Material - To			Jul 16, 2021 Jul 16,		(\$14,200.00)	Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment				
	0440 -	Total	Material - To			Jul 16, 2021 Jul 16,		(\$14,200.00)	Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment				
	0440 - 0450	Total CONCRETE CURB (6 IN. HEIGHT AND UNDER)	Material - To			Jul 16, 2021 Jul 16,		(\$14,200.00) \$0.00 \$0.00	Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment				
		CONCRETE CURB (6 IN. HEIGHT AND			25	Jul 16, 2021 Jul 16, 2021 Jul 16,	SYSTEM	(\$14,200.00) \$0.00 \$0.00	Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment				
		CONCRETE CURB (6 IN. HEIGHT AND			25	Jul 16, 2021 Jul 16, 2021 Jul 16, 2021 Jul 16, 2021	SYSTEM	(\$14,200.00) \$0.00 \$0.00 \$0.00 \$5,085.00	Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment				
		CONCRETE CURB (6 IN. HEIGHT AND		tal - Total	25	Jul 16, 2021 Jul 16, 2021 Jul 16, 2021 Jul 16, 2021	SYSTEM	(\$14,200.00) \$0.00 \$0.00 \$0.00 \$5,085.00 (\$5,085.00)	Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment				
		CONCRETE CURB (6 IN. HEIGHT AND UNDER)	Material	tal - Total	25	Jul 16, 2021 Jul 16, 2021 Jul 16, 2021 Jul 16, 2021	SYSTEM	(\$14,200.00) \$0.00 \$0.00 \$5,085.00 (\$5,085.00)	Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment				



roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
2222	0460	CONCRETE GUTTER TYPE B	Material		25	Jul 16, 2021	SYSTEM	(\$8,040.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0460 -	Total						\$0.00	
	0480	INTEGRAL CURB (6 IN. HEIGHT AND UNDER)	Material		16	Mar 2, 2021	SYSTEM	\$2,715.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					16	Mar 2, 2021	SYSTEM	(\$2,715.00)	
					17	Mar 16, 2021	SYSTEM	\$2,715.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					17	Mar 16, 2021	SYSTEM	(\$2,715.00)	
					18	Apr 2, 2021	SYSTEM	\$2,715.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					18	Apr 2, 2021	SYSTEM	(\$2,715.00)	
					19	Apr 16, 2021	SYSTEM	\$2,715.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					19	Apr 16, 2021	SYSTEM	(\$2,715.00)	
					20	May 3, 2021	SYSTEM	\$2,715.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hillt5 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					20	May 3, 2021	SYSTEM	(\$2,715.00)	
					21	May 17, 2021	SYSTEM	\$2,715.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user hillt5 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$2,715.00)	
					22	Jun 2, 2021	SYSTEM	\$2,715.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user hillt5 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$2,715.00)	
					23	Jun 16, 2021	SYSTEM	\$2,715.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$2,715.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0480 -	Total						\$0.00	
	0490	FURN. TYPE 2 ROCK DITCH LINER	Material		24	Jul 1, 2021	SYSTEM	\$21,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user herrmt1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$21,050.00)	
					25	Jul 16, 2021	SYSTEM	\$21,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$21,050.00)	
			Motorial To	- Total				\$0.00	
	0.400	T-4-1	Material - To	tai				\$0.00	
	0490 -						0)40==-	\$0.00	
	0675	CONCRETE TRAFFIC BARRIER, TYPE C	Material		3	Aug 17, 2020	SYSTEM	\$36,830.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Aug 17,	SYSTEM	(\$36,830.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																					
J6I2222		CONCRETE TRAFFIC BARRIER,	Material			2020																								
		TYPE C			4	Sep 2, 2020	SYSTEM	\$36,830.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																					
					4	Sep 2, 2020	SYSTEM	(\$36,830.00)																						
					5	Sep 16, 2020	SYSTEM	\$36,830.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.																					
					5	Sep 16, 2020	SYSTEM	(\$36,830.00)																						
					6	Oct 1, 2020	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.																					
					6	Oct 1, 2020	SYSTEM	(\$66,845.00)																						
					7	Oct 16, 2020	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.																					
					7	Oct 16, 2020	SYSTEM	(\$66,845.00)																						
					8	Nov 2, 2020	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user hillt5 overridding Payment Estimate Exception 14 on the current Payment Estimate.																					
					8	Nov 2, 2020	SYSTEM	(\$66,845.00)																						
								9	Nov 16, 2020	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user hillts overridding Payment Estimate Exception 14 on the current Payment Estimate.																		
					9	Nov 16, 2020	SYSTEM	(\$66,845.00)																						
					10	Dec 2, 2020	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.																					
					10	Dec 2, 2020	SYSTEM	(\$66,845.00)																						
					11	Dec 16, 2020	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user schlag1 overridding Payment Estimate Exception 14 on the current Payment Estimate.																					
					11	Dec 16, 2020	SYSTEM	(\$66,845.00)																						
					12	Jan 4, 2021	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kloepj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.																					
					12	Jan 4, 2021	SYSTEM	(\$66,845.00)																						
								13	Jan 19, 2021	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schlag1 overridding Payment Estimate Exception 14 on the current Payment Estimate.																		
																							13	Jan 19, 2021	SYSTEM	(\$66,845.00)				
														14	Feb 2, 2021	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hillt5 overridding Payment Estimate Exception 13 on the current Payment Estimate.												
																														14
							15	Feb 16, 2021	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schlag1 overridding Payment Estimate Exception 21 on the current Payment Estimate.																			
										15	Feb 16, 2021	SYSTEM	(\$66,845.00)																	
																												16	Mar 2, 2021	SYSTEM
					16	Mar 2, 2021	SYSTEM	(\$66,845.00)																						
					17	Mar 16, 2021	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kloepj1 overridding Payment																					



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks														
J6I2222	0675	CONCRETE TRAFFIC BARRIER,	Material						Estimate Exception 17 on the current Payment Estimate.														
		TYPE C			17	Mar 16, 2021	SYSTEM	(\$66,845.00)															
					18	Apr 2, 2021	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kloepj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.														
					18	Apr 2, 2021	SYSTEM	(\$66,845.00)															
							19	Apr 16, 2021	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.												
					19	Apr 16, 2021	SYSTEM	(\$66,845.00)															
					20	May 3, 2021	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hillt5 overridding Payment Estimate Exception 19 on the current Payment Estimate.														
					20	May 3, 2021	SYSTEM	(\$66,845.00)															
					21	May 17, 2021	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hillt5 overridding Payment Estimate Exception 33 on the current Payment Estimate.														
					21	May 17, 2021	SYSTEM	(\$66,845.00)															
																			22	Jun 2, 2021	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hillt5 overridding Payment Estimate Exception 36 on the current Payment Estimate.
							22	22	Jun 2, 2021	SYSTEM	(\$66,845.00)												
					23	Jun 16, 2021	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kloepj1 overridding Payment Estimate Exception 39 on the current Payment Estimate.														
						23	Jun 16, 2021	SYSTEM	(\$66,845.00)														
					24	Jul 1, 2021	SYSTEM	\$70,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user herrmt1 overridding Payment Estimate Exception 22 on the current Payment Estimate.														
					24	Jul 1, 2021	SYSTEM	(\$70,325.00)															
					25	Jul 16, 2021	SYSTEM	\$70,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment Estimate Exception 23 on the current Payment Estimate.														
					25	Jul 16, 2021	SYSTEM	(\$70,325.00)															
				- Total				\$0.00															
	0075	Total	Material - To	tal				\$0.00															
	0690	CONCRETE TRAFFIC BARRIER, TYPE D (RETAINING WALL)	ARRIER, TYPE D		6	Oct 1, 2020	SYSTEM	\$0.00 \$15,385.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.														
					6	Oct 1, 2020	SYSTEM	(\$15,385.00)															
					7	Oct 16, 2020	SYSTEM	\$51,935.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.														
					7	Oct 16, 2020	SYSTEM	(\$51,935.00)															
					8	Nov 2, 2020	SYSTEM	\$78,625.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user hillt5 overridding Payment Estimate Exception 17 on the current Payment Estimate.														
						8	Nov 2, 2020	SYSTEM	(\$78,625.00)														
							9	Nov 16, 2020	SYSTEM	\$79,900.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user hillt5 overridding Payment Estimate Exception 17 on the current Payment Estimate.												
					9	Nov 16, 2020	SYSTEM	(\$79,900.00)															



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks													
J6I2222	0690	CONCRETE TRAFFIC BARRIER, TYPE D (RETAINING WALL)	Material		10	Dec 2, 2020	SYSTEM	\$148,325.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.													
					10	Dec 2, 2020	SYSTEM	(\$148,325.00)														
					11	Dec 16, 2020	SYSTEM	\$148,325.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user schlag1 overridding Payment Estimate Exception 17 on the current Payment Estimate.													
							11	Dec 16, 2020	SYSTEM	(\$148,325.00)												
							12	Jan 4, 2021	SYSTEM	\$148,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.											
						12	Jan 4, 2021	SYSTEM	(\$148,325.00)													
					13	Jan 19, 2021	SYSTEM	\$148,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schlag1 overridding Payment Estimate Exception 17 on the current Payment Estimate.													
					13	Jan 19, 2021	SYSTEM	(\$148,325.00)														
					14	Feb 2, 2021	SYSTEM	\$148,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hillt5 overridding Payment Estimate Exception 16 on the current Payment Estimate.													
					14	Feb 2, 2021	SYSTEM	(\$148,325.00)														
													15	Feb 16, 2021	SYSTEM	\$148,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schlag1 overridding Payment Estimate Exception 24 on the current Payment Estimate.					
						15	Feb 16, 2021	SYSTEM	(\$148,325.00)													
						16	Mar 2, 2021	SYSTEM	\$148,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 25 on the current Payment Estimate.												
					16	Mar 2, 2021	SYSTEM	(\$148,325.00)														
						17	Mar 16, 2021	SYSTEM	\$148,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.												
					17	Mar 16, 2021	SYSTEM	(\$148,325.00)														
					18	Apr 2, 2021	SYSTEM	\$148,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.													
					18	Apr 2, 2021	SYSTEM	(\$148,325.00)														
						19	Apr 16, 2021	SYSTEM	\$148,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.												
					19	Apr 16, 2021	SYSTEM	(\$148,325.00)														
															20	May 3, 2021	SYSTEM	\$194,565.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hillt5 overridding Payment Estimate Exception 22 on the current Payment Estimate.			
																						20
								21	May 17, 2021	SYSTEM	\$194,565.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hillt5 overridding Payment Estimate Exception 35 on the current Payment Estimate.										
					21	May 17, 2021	SYSTEM	(\$194,565.00)														
								22	Jun 2, 2021	SYSTEM	\$194,565.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user hillt5 overridding Payment Estimate Exception 38 on the current Payment Estimate.										
								22	Jun 2, 2021	SYSTEM	(\$194,565.00)											
					23	Jun 16, 2021	SYSTEM	\$194,565.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 41 on the current Payment Estimate.													



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks									
J6I2222	0690	CONCRETE TRAFFIC BARRIER,	Material		23	Jun 16, 2021	SYSTEM	(\$194,565.00)										
		TYPE D (RETAINING WALL)			24	Jul 1, 2021	SYSTEM	\$194,565.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user herrmt1 overridding Payment Estimate Exception 23 on the current Payment Estimate.									
					24	Jul 1, 2021	SYSTEM	(\$194,565.00)										
					25	Jul 16, 2021	SYSTEM	\$194,565.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 24 on the current Payment Estimate.									
					25	Jul 16, 2021	SYSTEM	(\$194,565.00)										
				- Total				\$0.00										
			Material - To	tal				\$0.00										
	0690 -	Total						\$0.00										
	0710	TEMPORARY TRAFFIC BARRIER, CONT. FURN/RE	Overrun	Overrun	20	May 3, 2021	SYSTEM	\$5,840.45	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user hillt5 overridding Payment Estimate Exception 94 on the current Payment Estimate.									
					20	May 3, 2021	SYSTEM	(\$5,840.45)										
					21	May 17, 2021	SYSTEM	(\$5,840.45)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).									
				Overrun - T	otal			(\$5,840.45)										
			Overrun - To	tal				(\$5,840.45)										
	0710 -	Total						(\$5,840.45)										
	0990	MISC. GEOTEXTILE	Material		6	Oct 1, 2020	SYSTEM	\$11,470.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 25 on the current Payment Estimate.									
					6	Oct 1, 2020	SYSTEM	(\$11,470.00)										
					7	Oct 16, 2020	SYSTEM	\$32,782.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 25 on the current Payment Estimate.									
					7	Oct 16, 2020	SYSTEM	(\$32,782.50)										
					8	Nov 2, 2020	SYSTEM	\$32,782.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user hillt5 overridding Payment Estimate Exception 20 on the current Payment Estimate.									
												8	Nov 2, 2020	SYSTEM	(\$32,782.50)			
					9	Nov 16, 2020	SYSTEM	\$32,782.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user hillt5 overridding Payment Estimate Exception 20 on the current Payment Estimate.									
					9	Nov 16, 2020	SYSTEM	(\$32,782.50)										
					10	Dec 2, 2020	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.									
					10	Dec 2, 2020	SYSTEM	(\$37,215.50)										
					11	Dec 16, 2020	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user schlag1 overridding Payment Estimate Exception 19 on the current Payment Estimate.									
			1			11	Dec 16, 2020	SYSTEM	(\$37,215.50)									
											12	Jan 4, 2021	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.			
				12	Jan 4, 2021	SYSTEM	(\$37,215.50)											
				1	1	1	-					1:	13	1	13	Jan 19, 2021	SYSTEM	\$37,215.50
					13	Jan 19, 2021	SYSTEM	(\$37,215.50)										
					14	Feb 2,	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Material Payment									



ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
22	0990	MISC. GEOTEXTILE	Material			2021			Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 18 on the current Payment Estimate.	
					14	Feb 2, 2021	SYSTEM	(\$37,215.50)		
					15	Feb 16, 2021	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schlag1 overridding Payment Estimate Exception 26 on the current Payment Estimate.	
					15	Feb 16, 2021	SYSTEM	(\$37,215.50)		
					16	Mar 2, 2021	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment Estimate Exception 27 on the current Payment Estimate.	
					16	Mar 2, 2021	SYSTEM	(\$37,215.50)		
					17	Mar 16, 2021	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Paymen Estimate Exception 22 on the current Payment Estimate.	
					17	Mar 16, 2021	SYSTEM	(\$37,215.50)		
					18	Apr 2, 2021	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kloepj1 overridding Paymen Estimate Exception 23 on the current Payment Estimate.	
					18	Apr 2, 2021	SYSTEM	(\$37,215.50)		
					19	Apr 16, 2021	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user kloepj1 overridding Paymen Estimate Exception 22 on the current Payment Estimate.	
					19	Apr 16, 2021	SYSTEM	(\$37,215.50)		
						20	May 3, 2021	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hillt5 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					20	May 3, 2021	SYSTEM	(\$37,215.50)		
					21	May 17, 2021	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user hillt5 overridding Payment Estimate Exception 38 on the current Payment Estimate.	
					21	May 17, 2021	SYSTEM	(\$37,215.50)		
					22	Jun 2, 2021	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user hillt5 overridding Payment Estimate Exception 41 on the current Payment Estimate.	
					22	Jun 2, 2021	SYSTEM	(\$37,215.50)		
					23	Jun 16, 2021	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Paymen Estimate Exception 44 on the current Payment Estimate.	
					23	Jun 16, 2021	SYSTEM	(\$37,215.50)		
					24	Jul 1, 2021	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user herrmt1 overridding Paymer Estimate Exception 24 on the current Payment Estimate.	
					24	Jul 1, 2021	SYSTEM	(\$37,215.50)		
					25	Jul 16, 2021	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Paymen Estimate Exception 25 on the current Payment Estimate.	
					25	Jul 16, 2021	SYSTEM	(\$37,215.50)		
				- Total				\$0.00		
	0000	Total	Material - To	tal				\$0.00		
	0990 - 1050	MISC.	Material		8	Nov 2, 2020	SYSTEM	\$0.00 \$23,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user hill5 overridding Payment Estimate Execution 24 on the current Payment Estimate.	
									Estimate Exception 21 on the current Payment Estimate.	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	1050	MISC.	Material		9	Nov 16, 2020	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user hillt5 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					9	Nov 16, 2020	SYSTEM	(\$23,800.00)	
					10	Dec 2, 2020	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					10	Dec 2, 2020	SYSTEM	(\$23,800.00)	
					11	Dec 16, 2020	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user schlag1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					11	Dec 16, 2020	SYSTEM	(\$23,800.00)	
					12	Jan 4, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kloepj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					12	Jan 4, 2021	SYSTEM	(\$23,800.00)	
					13	Jan 19, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schlag1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					13	Jan 19, 2021	SYSTEM	(\$23,800.00)	
					14	Feb 2, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hillt5 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					14	Feb 2, 2021	SYSTEM	(\$23,800.00)	
					15	Feb 16, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schlag1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
					15	Feb 16, 2021	SYSTEM	(\$23,800.00)	
					16	Mar 2, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kloepj1 overridding Payment Estimate Exception 35 on the current Payment Estimate.
					16	Mar 2, 2021	SYSTEM	(\$23,800.00)	
					17	Mar 16, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					17	Mar 16, 2021	SYSTEM	(\$23,800.00)	
					18	Apr 2, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					18	Apr 2, 2021	SYSTEM	(\$23,800.00)	
					19	Apr 16, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					19	Apr 16, 2021	SYSTEM	(\$23,800.00)	
					20	May 3, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hillt5 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					20	May 3, 2021	SYSTEM	(\$23,800.00)	
					21	May 17, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user hillt5 overridding Payment Estimate Exception 51 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$23,800.00)	
					22	Jun 2, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user hillt5 overridding Payment Estimate Exception 63 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	1050	MISC.	Material		22	Jun 2, 2021	SYSTEM	(\$23,800.00)	
					23	Jun 16, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 66 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$23,800.00)	
					24	Jul 1, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user herrmt1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$23,800.00)	
					25	Jul 16, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$23,800.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	1050 -	Total						\$0.00	
	1090	MECHANICALLY STABILIZED EARTH WALL SYS	Material		7	Oct 16, 2020	SYSTEM	\$203,640.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					7	Oct 16, 2020	SYSTEM	(\$203,640.00)	
					8	Nov 2, 2020	SYSTEM	\$203,640.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user hillt5 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					8	Nov 2, 2020	SYSTEM	(\$203,640.00)	
					9	Nov 16, 2020	SYSTEM	\$203,640.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user hillt5 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					9	Nov 16, 2020	SYSTEM	(\$203,640.00)	
					10	Dec 2, 2020	SYSTEM	\$203,640.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					10	Dec 2, 2020	SYSTEM	(\$203,640.00)	
					11	Dec 16, 2020	SYSTEM	\$203,640.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user schlag1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					11	Dec 16, 2020	SYSTEM	(\$203,640.00)	
					12	Jan 4, 2021	SYSTEM	\$203,640.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					12	Jan 4, 2021	SYSTEM	(\$203,640.00)	
					13	Jan 19, 2021	SYSTEM	\$203,640.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schlag1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					13	Jan 19, 2021	SYSTEM	(\$203,640.00)	
					14	Feb 2, 2021	SYSTEM	\$203,640.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hillt5 overridding Payment Estimate Exception 49 on the current Payment Estimate.
					14	Feb 2, 2021	SYSTEM	(\$203,640.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	1090 -	Total						\$0.00	
	1100	SELECT GRANULAR BACKFILL FOR	Material		7	Oct 16, 2020	SYSTEM	\$41,310.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks											
J6I2222	1100	STRUCTURAL	Material		7	Oct 16, 2020	SYSTEM	(\$41,310.00)												
					11	Dec 16, 2020	SYSTEM	\$256,560.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user schlag1 overridding Payment Estimate Exception 26 on the current Payment Estimate.											
					11	Dec 16, 2020	SYSTEM	(\$256,560.00)												
					12	Jan 4, 2021	SYSTEM	\$256,560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 27 on the current Payment Estimate.											
					12	Jan 4, 2021	SYSTEM	(\$256,560.00)												
					13	Jan 19, 2021	SYSTEM	\$256,560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schlag1 overridding Payment Estimate Exception 24 on the current Payment Estimate.											
					13	Jan 19, 2021	SYSTEM	(\$256,560.00)												
					14	Feb 2, 2021	SYSTEM	\$256,560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hillt5 overridding Payment Estimate Exception 52 on the current Payment Estimate.											
					14	Feb 2, 2021	SYSTEM	(\$256,560.00)												
					15	Feb 16, 2021	SYSTEM	\$256,560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schlag1 overridding Payment Estimate Exception 51 on the current Payment Estimate.											
					15	Feb 16, 2021	SYSTEM	(\$256,560.00)												
					16	Mar 2, 2021	SYSTEM	\$256,560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Exception 50 on the current Payment Estimate.											
																16	Mar 2, 2021	SYSTEM	(\$256,560.00)	
								17	Mar 16, 2021	SYSTEM	\$256,560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kloepj1 overridding Payment Estimate Exception 43 on the current Payment Estimate.								
					17	Mar 16, 2021	SYSTEM	(\$256,560.00)												
					18	Apr 2, 2021	SYSTEM	\$286,560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Exception 48 on the current Payment Estimate.											
					18	Apr 2, 2021	SYSTEM	(\$286,560.00)												
				- Total				\$0.00												
	1100 -	Total	Material - To	tal				\$0.00 \$0.00												
	1160		Material		9	Nov 16, 2020	SYSTEM	\$49,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user hillt5 overridding Payment Estimate Exception 29 on the current Payment Estimate.											
					9	Nov 16, 2020	SYSTEM	(\$49,500.00)												
					10	Dec 2, 2020	SYSTEM	\$55,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.											
										10	Dec 2, 2020	SYSTEM	(\$55,000.00)							
					11	Dec 16, 2020	SYSTEM	\$55,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user schlag1 overridding Payment Estimate Exception 27 on the current Payment Estimate.											
					11	Dec 16, 2020	SYSTEM	(\$55,000.00)												
					12	Jan 4, 2021	SYSTEM	\$55,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.											
					12	Jan 4, 2021	SYSTEM	(\$55,000.00)												
					13	Jan 19, 2021	SYSTEM	\$55,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schlag1 overridding Payment											



roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
612222	1160	MISC.	Material						Estimate Exception 25 on the current Payment Estimate.
					13	Jan 19, 2021	SYSTEM	(\$55,000.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
J	1160 -	Total						\$0.00	
	1170	PRECAST CONCRETE DROP INLET 2 FT X 2 FT	Material		3	Aug 17, 2020	SYSTEM	\$2,450.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					3	Aug 17, 2020	SYSTEM	(\$2,450.00)	
					4	Sep 2, 2020	SYSTEM	\$4,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					4	Sep 2, 2020	SYSTEM	(\$4,200.00)	Estimate Estapator 7 of the surface
					5	Sep 16, 2020	SYSTEM	\$4,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					5	Sep 16, 2020	SYSTEM	(\$4,200.00)	
					6	Oct 1, 2020	SYSTEM	\$4,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					6	Oct 1, 2020	SYSTEM	(\$4,200.00)	
					7	Oct 16, 2020	SYSTEM	\$4,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
				7	Oct 16, 2020	SYSTEM	(\$4,200.00)		
			- Total				\$0.00		
			Material - To	tal				\$0.00	
	1170 -							\$0.00	
	1180	PRECAST CONCRETE DROP INLET 4 FT X 2 FT	Material		3	Aug 17, 2020	SYSTEM	\$8,100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					3	Aug 17, 2020	SYSTEM	(\$8,100.00)	
					4	Sep 2, 2020	SYSTEM	\$8,550.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					4	Sep 2, 2020	SYSTEM	(\$8,550.00)	
					5	Sep 16, 2020	SYSTEM	\$8,550.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					5	Sep 16, 2020	SYSTEM	(\$8,550.00)	
					6	Oct 1, 2020	SYSTEM	\$8,550.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					6	Oct 1, 2020	SYSTEM	(\$8,550.00)	•
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1180 -					0	0)/2==:	\$0.00	
	1190	PRECAST CONCRETE DROP INLET 5 FT X 3 FT	Material		6	Oct 1, 2020	SYSTEM	\$1,950.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					6	Oct 1, 2020	SYSTEM	(\$1,950.00)	
					7	Oct 16, 2020	SYSTEM	\$15,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks												
J6I2222	1190	PRECAST CONCRETE DROP	Material		7	Oct 16, 2020	SYSTEM	(\$15,600.00)													
		INLET 5 FT X 3 FT			25	Jul 16, 2021	SYSTEM	\$35,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kloepj1 overridding Payment Estimate Exception 71 on the current Payment Estimate.												
					25	Jul 16, 2021	SYSTEM	(\$35,750.00)													
				- Total				\$0.00													
			Material - To	tal				\$0.00													
	1190 -	Total						\$0.00													
	1200	MISC. MANHOLES AND DROP INLETS	Material		3	Aug 17, 2020	SYSTEM	\$5,610.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.												
					3	Aug 17, 2020	SYSTEM	(\$5,610.00)													
					4	Sep 2, 2020	SYSTEM	\$5,610.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.												
					4	Sep 2, 2020	SYSTEM	(\$5,610.00)													
						5	Sep 16, 2020	SYSTEM	\$5,610.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.											
							5	Sep 16, 2020	SYSTEM	(\$5,610.00)											
						6	Oct 1, 2020	SYSTEM	\$10,710.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 30 on the current Payment Estimate.											
					6	Oct 1, 2020	SYSTEM	(\$10,710.00)													
					7	Oct 16, 2020	SYSTEM	\$10,710.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.												
					7	Oct 16, 2020	SYSTEM	(\$10,710.00)													
				- Total				\$0.00													
			Material - To	tal				\$0.00													
	1200 -	Total						\$0.00													
	1210	MISC. MANHOLES AND DROP INLETS	Material		6	Oct 1, 2020	SYSTEM	\$3,850.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.												
											6	Oct 1, 2020	SYSTEM	(\$3,850.00)							
												7	Oct 16, 2020	SYSTEM	\$12,950.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.					
												-					7	Oct 16, 2020	SYSTEM	(\$12,950.00)	
									12	Jan 4, 2021	SYSTEM	\$1,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.								
										12	Jan 4, 2021	SYSTEM	(\$1,750.00)								
													1				13	Jan 19, 2021	SYSTEM	\$1,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schlag1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
										13	Jan 19, 2021	SYSTEM	(\$1,750.00)								
					14							1	1			14	14	14	Feb 2, 2021	SYSTEM	\$1,750.00
				14		14	Feb 2, 2021	SYSTEM	(\$1,750.00)												
					15	Feb 16, 2021	SYSTEM	\$1,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schlag1 overridding Payment Estimate Exception 52 on the current Payment Estimate.												



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks												
J6I2222	1210	MISC. MANHOLES AND DROP INLETS	Material		15	Feb 16, 2021	SYSTEM	(\$1,750.00)													
				- Total				\$0.00													
			Material - To	tal				\$0.00													
	1210 -	Total						\$0.00													
	1220	15 IN. GROUP A FLARED END SECT	Material		6	Oct 1, 2020	SYSTEM	\$800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.												
					6	Oct 1, 2020	SYSTEM	(\$800.00)													
					7	Oct 16, 2020	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 34 on the current Payment Estimate.												
					7	Oct 16, 2020	SYSTEM	(\$1,600.00)													
					8	Nov 2, 2020	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user hillt5 overridding Payment Estimate Exception 29 on the current Payment Estimate.												
								8	Nov 2, 2020	SYSTEM	(\$1,600.00)										
					9	Nov 16, 2020	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user hillt5 overridding Payment Estimate Exception 30 on the current Payment Estimate.												
					9	Nov 16, 2020	SYSTEM	(\$1,600.00)													
					10	Dec 2, 2020	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user kloepj1 overridding Payment Estimate Exception 30 on the current Payment Estimate.												
											10	Dec 2, 2020	SYSTEM	(\$1,600.00)							
					11	Dec 16, 2020	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user schlag1 overridding Payment Estimate Exception 28 on the current Payment Estimate.												
					11	Dec 16, 2020	SYSTEM	(\$1,600.00)													
									12	Jan 4, 2021	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kloepj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.								
					12	Jan 4, 2021	SYSTEM	(\$1,600.00)													
					13	Jan 19, 2021	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schlag1 overridding Payment Estimate Exception 28 on the current Payment Estimate.												
					13	Jan 19, 2021	SYSTEM	(\$1,600.00)													
				- Total				\$0.00													
			Material - To	tal				\$0.00													
	1220 -	Total						\$0.00													
	1290	ROCK DITCH CHECK	Material	Material		4	Sep 2, 2020	SYSTEM	\$252.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.											
						4	Sep 2, 2020	SYSTEM	(\$252.00)												
																5		Sep 16, 2020	SYSTEM	\$252.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					5	Sep 16, 2020	SYSTEM	(\$252.00)													
					6	Oct 1, 2020	SYSTEM	\$252.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.												
					6	Oct 1, 2020	SYSTEM	(\$252.00)													
					7	Oct 16, 2020	SYSTEM	\$252.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Exception 35 on the current Payment Estimate.												



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
1612222	1290	ROCK DITCH CHECK	Material		7	Oct 16, 2020	SYSTEM	(\$252.00)				
					8	Nov 2, 2020	SYSTEM	\$252.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 30 on the current Payment Estimate.			
					8	Nov 2, 2020	SYSTEM	(\$252.00)				
					9	Nov 16, 2020	SYSTEM	\$252.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 31 on the current Payment Estimate.			
					9	Nov 16, 2020	SYSTEM	(\$252.00)				
					10	Dec 2, 2020	SYSTEM	\$252.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user kloepj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.			
					10	Dec 2, 2020	SYSTEM	(\$252.00)				
					11	Dec 16, 2020	SYSTEM	\$252.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user schlag1 overridding Payment Estimate Exception 29 on the current Payment Estimate.			
					11	Dec 16, 2020	SYSTEM	(\$252.00)				
					12	Jan 4, 2021	SYSTEM	\$252.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user kloepj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.			
					12	Jan 4, 2021	SYSTEM	(\$252.00)				
					13	Jan 19, 2021	SYSTEM	\$252.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schlag1 overridding Payment Estimate Exception 29 on the current Payment Estimate.			
					13	Jan 19, 2021	SYSTEM	(\$252.00)				
					14	Feb 2, 2021	SYSTEM	\$252.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 55 on the current Payment Estimate.			
					14	Feb 2, 2021	SYSTEM	(\$252.00)				
					15	Feb 16, 2021	SYSTEM	\$252.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schlag1 overridding Payment Estimate Exception 54 on the current Payment Estimate.			
					15	Feb 16, 2021	SYSTEM	(\$252.00)				
				- Total				\$0.00				
	1290 -	Total	Material - To	(al				\$0.00 \$0.00				
	1320	TEMPORARY SEEDING AND MULCHING	Material		25	Jul 16, 2021	SYSTEM	\$2,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 73 on the current Payment Estimate.			
					25	Jul 16, 2021	SYSTEM	(\$2,400.00)				
				- Total				\$0.00				
			Material - To	tal				\$0.00				
	1320 -							\$0.00				
	1330	SILT FENCE	Material		4	Sep 2, 2020	SYSTEM	\$4,506.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.			
					4	Sep 2, 2020	SYSTEM	(\$4,506.75)				
					5	Sep 16, 2020	SYSTEM	\$4,506.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.			
					5	Sep 16, 2020	SYSTEM	(\$4,506.75)				
					6	6		6	Oct 1, 2020	SYSTEM	\$4,506.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks															
J6I2222	1330	SILT FENCE	Material	, , , , , , , , , , , , , , , , , , ,	6	Oct 1, 2020	SYSTEM	(\$4,506.75)																
					7	Oct 16, 2020	SYSTEM	\$4,506.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user kloepj1 overridding Payment Estimate Exception 36 on the current Payment Estimate.															
					7	Oct 16, 2020	SYSTEM	(\$4,506.75)																
				- Total				\$0.00																
			Material - To	tal				\$0.00																
	1330 -	Total						\$0.00																
	1490	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		5	Sep 16, 2020	SYSTEM	\$12,444.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.															
					5	Sep 16, 2020	SYSTEM	(\$12,444.25)																
					6	Oct 1, 2020	SYSTEM	\$14,110.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.															
							6	Oct 1, 2020	SYSTEM	(\$14,110.85)														
									7	Oct 16, 2020	SYSTEM	\$17,094.16	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.											
								7	Oct 16, 2020	SYSTEM	(\$17,094.16)													
					8	Nov 2, 2020	SYSTEM	\$17,094.16	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user hillt5 overridding Payment Estimate Exception 2 on the current Payment Estimate.															
						8	Nov 2, 2020	SYSTEM	(\$17,094.16)															
					9	Nov 16, 2020	SYSTEM	\$17,094.16	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user hillt5 overridding Payment Estimate Exception 2 on the current Payment Estimate.															
					9	Nov 16, 2020	SYSTEM	(\$17,094.16)																
					10	Dec 2, 2020	SYSTEM	\$17,094.16	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.															
						10	Dec 2, 2020	SYSTEM	(\$17,094.16)															
					11	Dec 16, 2020	SYSTEM	\$17,094.16	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user schlag1 overridding Payment Estimate Exception 2 on the current Payment Estimate.															
																			11	Dec 16, 2020	SYSTEM	(\$17,094.16)		
																	12	Jan 4, 2021	SYSTEM	\$17,094.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user kloepj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.			
										12	Jan 4, 2021	SYSTEM	(\$17,094.16)											
					13	Jan 19, 2021	SYSTEM	\$17,094.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schlag1 overridding Payment Estimate Exception 2 on the current Payment Estimate.															
							1	1			13	Jan 19, 2021	SYSTEM	(\$17,094.16)										
																		14	Feb 2, 2021	SYSTEM	\$17,094.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hillt5 overridding Payment Estimate Exception 2 on the current Payment Estimate.		
											1	14	Feb 2, 2021	SYSTEM	(\$17,094.16)									
																				15	Feb 16, 2021	SYSTEM	\$17,094.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schlag1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
														1:	15	Feb 16, 2021	SYSTEM	(\$17,094.16)						
					16	Mar 2, 2021	SYSTEM	\$17,094.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment															



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																		
J6I2222	1490	TYPE 5 AGGREGATE FOR	Material						Estimate Exception 2 on the current Payment Estimate.																		
		BASE (6 IN. THICK)			16	Mar 2, 2021	SYSTEM	(\$17,094.16)																			
					17	Mar 16, 2021	SYSTEM	\$17,094.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																		
					17	Mar 16, 2021	SYSTEM	(\$17,094.16)																			
					18	Apr 2, 2021	SYSTEM	\$17,094.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																		
					18	Apr 2, 2021	SYSTEM	(\$17,094.16)																			
					19	Apr 16, 2021	SYSTEM	\$23,568.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																		
								19	Apr 16, 2021	SYSTEM	(\$23,568.16)																
							20	May 3, 2021	SYSTEM	\$24,747.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate.																
							20	May 3, 2021	SYSTEM	(\$24,747.26)																	
											21	May 17, 2021	SYSTEM	\$25,904.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user hillto overridding Payment Estimate Exception 2 on the current Payment Estimate.												
							21	May 17, 2021	SYSTEM	(\$25,904.26)																	
							22	Jun 2, 2021	SYSTEM	\$27,859.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate.																
									22	Jun 2, 2021	SYSTEM	(\$27,859.46)															
					23	Jun 16, 2021	SYSTEM	\$39,318.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user kloepj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.																		
							23	Jun 16, 2021	SYSTEM	(\$39,318.96)																	
						24	Jul 1, 2021	SYSTEM	\$53,139.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate.																	
										24	Jul 1, 2021	SYSTEM	(\$53,139.26)														
																										25	Jul 16, 2021
					25	Jul 16, 2021	SYSTEM	(\$59,894.06)																			
				- Total				\$0.00																			
			Material - Tot Price FUEL	tal	5	Sep 16,	SYSTEM	\$0.00 \$167.33	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																		
			Price FUEL	Price FUEL		2020 Oct 1,	SYSTEM	\$22.41	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																		
				7 11 20	7 11 20	1 2	1 2	1 2	1 2	7 18 20	7	7	7		7	7				Oct 16,	SYSTEM	\$33.78	Reference Item Price Adjustment Index Adjustment Type applied is FUEL				
																		2020			· · · · · · · · · · · · · · · · · · ·						
													Apr 16, 2021	SYSTEM	\$256.57	Reference Item Price Adjustment Index Adjustment Type applied is FUEL											
													20				May 3, 2021	SYSTEM	\$46.73	Reference Item Price Adjustment Index Adjustment Type applied is FUEL							
				21	May 17, 2021	SYSTEM	\$52.40	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																			
				22	Jun 2, 2021	SYSTEM	\$88.56	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																			
					23	Jun 16, 2021	SYSTEM	\$523.08	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																		



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																
J6I2222	1490	TYPE 5 AGGREGATE FOR	Price FUEL	. , , , ,	24	Jul 1, 2021	SYSTEM	\$630.84	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																
		BASE (6 IN. THICK)			25	Jul 16, 2021	SYSTEM	\$313.11	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																
				- Total				\$2,134.81																	
			Price FUEL -	Total				\$2,134.81																	
	1490 -	Total						\$2,134.81																	
	1500	CONCRETE PAVEMENT (8 IN. NON-REINFORCED,	Material		21	May 17, 2021	SYSTEM	\$4,080.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user hillt5 overridding Payment Estimate Exception 8 on the current Payment Estimate.																
					21	May 17, 2021	SYSTEM	(\$4,080.00)																	
					23	Jun 16, 2021	SYSTEM	\$76,168.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user kloepj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.																
					23	Jun 16, 2021	SYSTEM	(\$76,168.50)	·																
						24	Jul 1, 2021	SYSTEM	\$127,591.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user herrmt1 overridding Payment Estimate Exception 7 on the current Payment Estimate.															
								24	Jul 1, 2021	SYSTEM	(\$127,591.80)	·													
						25	Jul 16, 2021	SYSTEM	\$155,835.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user kloepj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.															
					25	Jul 16, 2021	SYSTEM	(\$155,835.60)																	
				- Total				\$0.00																	
			Material - To	tal				\$0.00																	
			Price FUEL		Price FUEL	Price FUEL		21	May 17, 2021	SYSTEM	\$61.44	Reference Item Price Adjustment Index Adjustment Type applied is FUEL													
									22	Jun 2, 2021	SYSTEM	(\$61.44)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL												
					23	Jun 16, 2021	SYSTEM	\$1,155.97	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																
							24	Jul 1, 2021	SYSTEM	\$780.42	Reference Item Price Adjustment Index Adjustment Type applied is FUEL														
					25	Jul 16, 2021	SYSTEM	\$435.29	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																
				- Total				\$2,371.68																	
			Price FUEL -	Total				\$2,371.68																	
	1500 -	Total						\$2,371.68																	
	1510	CONCRETE PAVEMENT (9 IN. NON-REINFORCED,	Material		5	Sep 16, 2020	SYSTEM	\$49,717.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user kloepj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.																
									5	Sep 16, 2020	SYSTEM	(\$49,717.80)													
					6	Oct 1, 2020	SYSTEM	\$63,768.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user kloepj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.																
													6	Oct 1, 2020	SYSTEM	(\$63,768.60)									
															7	Oct 16, 2020	SYSTEM	\$68,002.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user kloepj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.						
				8	8	8	8	8	8	8													7	Oct 16, 2020	SYSTEM
											8	Nov 2, 2020	SYSTEM	\$68,002.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate.										
											8	Nov 2, 2020	SYSTEM	(\$68,002.20)											
						9	Nov 16, 2020	SYSTEM	\$68,002.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate.															



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	1510	CONCRETE PAVEMENT (9 IN.	Material		9	Nov 16, 2020	SYSTEM	(\$68,002.20)	
		NON-REINFORCED,			10	Dec 2, 2020	SYSTEM	\$68,002.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					10	Dec 2, 2020	SYSTEM	(\$68,002.20)	
					11	Dec 16, 2020	SYSTEM	\$68,002.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user schlag1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					11	Dec 16, 2020	SYSTEM	(\$68,002.20)	
					12	Jan 4, 2021	SYSTEM	\$68,002.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					12	Jan 4, 2021	SYSTEM	(\$68,002.20)	
					13	Jan 19, 2021	SYSTEM	\$68,002.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schlag1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					13	Jan 19, 2021	SYSTEM	(\$68,002.20)	
					14	Feb 2, 2021	SYSTEM	\$68,002.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					14	Feb 2, 2021	SYSTEM	(\$68,002.20)	
					15	Feb 16, 2021	SYSTEM	\$68,002.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schlag1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					15	Feb 16, 2021	SYSTEM	(\$68,002.20)	
					16	Mar 2, 2021	SYSTEM	\$68,002.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					16	Mar 2, 2021	SYSTEM	(\$68,002.20)	
					17	Mar 16, 2021	SYSTEM	\$68,002.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					17	Mar 16, 2021	SYSTEM	(\$68,002.20)	
					18	Apr 2, 2021	SYSTEM	\$68,002.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					18	Apr 2, 2021	SYSTEM	(\$68,002.20)	
					19	Apr 16, 2021	SYSTEM	\$96,098.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kloepj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					19	Apr 16, 2021	SYSTEM	(\$96,098.40)	
					20	May 3, 2021	SYSTEM	\$96,098.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					20	May 3, 2021	SYSTEM	(\$96,098.40)	
					21	May 17, 2021	SYSTEM	\$105,710.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user hillt5 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$105,710.40)	
					22	Jun 2, 2021	SYSTEM	\$114,415.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hillt5 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$114,415.20)	
					23	Jun 16,	SYSTEM	\$114,415.20	This adjustment offsets the original system-generated Material Payment



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	1510	CONCRETE		Туре		2021	_,		Estimate Item Adjustment (0042) due to user kloopid eversidding Poursent
JUIZZZZ	1010	PAVEMENT (9 IN. NON-REINFORCED,	iviatellal			2021			Estimate Item Adjustment (0043) due to user kloepj1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
		INDIN-REINFURGED,			23	Jun 16, 2021	SYSTEM	(\$114,415.20)	
					24	Jul 1, 2021	SYSTEM	\$136,560.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user herrmt1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$136,560.60)	
					25	Jul 16, 2021	SYSTEM	\$160,822.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kloepj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$160,822.80)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
			Price FUEL		5	Sep 16, 2020	SYSTEM	\$230.91	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					6	Oct 1, 2020	SYSTEM	\$65.26	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					7	Oct 16, 2020	SYSTEM	\$16.56	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					19	Apr 16, 2021	SYSTEM	\$384.61	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					21	May 17, 2021	SYSTEM	\$150.37	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					22	Jun 2, 2021	SYSTEM	\$136.18	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					24	Jul 1, 2021	SYSTEM	\$349.16	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					25	Jul 16, 2021	SYSTEM	\$388.47	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$1,721.52	
			Price FUEL -	Total				\$1,721.52	
	1510 -							\$1,721.52	
	1520	INTEGRAL CURB (6 IN. HEIGHT AND UNDER)	Material		21	May 17, 2021	SYSTEM	\$3,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user hillt5 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$3,150.00)	
					22	Jun 2, 2021	SYSTEM	\$3,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user hillt5 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$3,150.00)	
					23	Jun 16, 2021	SYSTEM	\$3,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user kloepj1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$3,150.00)	
					24	Jul 1, 2021	SYSTEM	\$3,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user herrmt1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$3,150.00)	
					25	Jul 16, 2021	SYSTEM	\$3,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user kloepj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$3,150.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	1520 -	Total						\$0.00	
	1550	TYPE A2	Material		6	Oct 1,	SYSTEM	\$14,224.00	This adjustment offsets the original system-generated Overrun Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks															
J6I2222	1550	SHOULDER	Material			2020			Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.															
					6	Oct 1, 2020	SYSTEM	(\$14,224.00)																
					7	Oct 16, 2020	SYSTEM	\$30,287.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.															
					7	Oct 16, 2020	SYSTEM	(\$30,287.95)																
					8	Nov 2, 2020	SYSTEM	\$30,287.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user hillto overridding Payment Estimate Exception 8 on the current Payment Estimate.															
					8	Nov 2, 2020	SYSTEM	(\$30,287.95)																
					9	Nov 16, 2020	SYSTEM	\$30,287.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user hillto overridding Payment Estimate Exception 8 on the current Payment Estimate.															
					9	Nov 16, 2020	SYSTEM	(\$30,287.95)																
					10	Dec 2, 2020	SYSTEM	\$30,287.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user kloepj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.															
					10	Dec 2, 2020	SYSTEM	(\$30,287.95)																
					11	Dec 16, 2020	SYSTEM	\$30,287.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user schlag1 overridding Payment Estimate Exception 8 on the current Payment Estimate.															
					11	Dec 16, 2020	SYSTEM	(\$30,287.95)																
					12	Jan 4, 2021	SYSTEM	\$30,287.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.															
					12	Jan 4, 2021	SYSTEM	(\$30,287.95)																
					13	Jan 19, 2021	SYSTEM	\$30,287.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schlag1 overridding Payment Estimate Exception 8 on the current Payment Estimate.															
					13	Jan 19, 2021	SYSTEM	(\$30,287.95)																
					14	Feb 2, 2021	SYSTEM	\$30,287.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user hillt5 overridding Payment Estimate Exception 8 on the current Payment Estimate.															
					14	Feb 2, 2021	SYSTEM	(\$30,287.95)																
					15	Feb 16, 2021	SYSTEM	\$30,287.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schlag1 overridding Payment Estimate Exception 8 on the current Payment Estimate.															
					15	Feb 16, 2021	SYSTEM	(\$30,287.95)																
					16	Mar 2, 2021	SYSTEM	\$30,287.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.															
					16	Mar 2, 2021	SYSTEM	(\$30,287.95)																
																				17	Mar 16, 2021	SYSTEM	\$30,287.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					17	Mar 16, 2021	SYSTEM	(\$30,287.95)																
					18	Apr 2, 2021	SYSTEM	\$30,287.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.															
					18	Apr 2, 2021	SYSTEM	(\$30,287.95)																
					19	Apr 16, 2021	SYSTEM	\$46,937.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.															
					19	Apr 16,	SYSTEM	(\$46,937.45)																



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks														
J6I2222	1550		Material			2021																	
					20	May 3, 2021	SYSTEM	\$53,286.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user hillt5 overridding Payment Estimate Exception 8 on the current Payment Estimate.														
					20	May 3, 2021	SYSTEM	(\$53,286.45)															
					21	May 17, 2021	SYSTEM	\$53,286.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user hillt5 overridding Payment Estimate Exception 16 on the current Payment Estimate.														
					21	May 17, 2021	SYSTEM	(\$53,286.45)															
					22	Jun 2, 2021	SYSTEM	\$53,286.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user hillt5 overridding Payment Estimate Exception 13 on the current Payment Estimate.														
					22	Jun 2, 2021	SYSTEM	(\$53,286.45)															
					23	Jun 16, 2021	SYSTEM	\$53,286.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user kloepj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.														
					23	Jun 16,	SYSTEM	(\$53,286.45)	Estimate Exception to off the sensitiff ayrion Estimate.														
				- Total		2021		\$0.00															
			Material - Tot					\$0.00															
	1550 -	Total						\$0.00															
	1560	INTEGRAL CURB (6 IN. HEIGHT AND UNDER)	Material		6	Oct 1, 2020	SYSTEM	\$3,375.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user kloepj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.														
										6	Oct 1, 2020	SYSTEM	(\$3,375.00)										
											7	Oct 16, 2020	SYSTEM	\$3,375.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user kloepj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.								
							7	Oct 16, 2020	SYSTEM	(\$3,375.00)													
					8	Nov 2, 2020	SYSTEM	\$3,375.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 10 on the current Payment Estimate.														
					8	Nov 2, 2020	SYSTEM	(\$3,375.00)															
					9	Nov 16, 2020	SYSTEM	\$3,375.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 10 on the current Payment Estimate.														
						9	Nov 16, 2020	SYSTEM	(\$3,375.00)														
												10	Dec 2, 2020	SYSTEM	\$3,375.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.							
											10	Dec 2, 2020	SYSTEM	(\$3,375.00)									
													11	Dec 16, 2020	SYSTEM	\$3,375.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user schlag1 overridding Payment Estimate Exception 10 on the current Payment Estimate.						
					11	Dec 16, 2020	SYSTEM	(\$3,375.00)															
									1						1:		1:		12	Jan 4, 2021	SYSTEM	\$3,375.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
																			12	Jan 4, 2021	SYSTEM	(\$3,375.00)	
																		13	Jan 19, 2021	SYSTEM	\$3,375.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schlag1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	
					13	Jan 19, 2021	SYSTEM	(\$3,375.00)															
					14	Feb 2, 2021	SYSTEM	\$3,375.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user hillt5 overridding Payment Estimate Exception 10 on the current Payment Estimate.														



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	1560	INTEGRAL CURB (6 IN. HEIGHT AND	Material		14	Feb 2, 2021	SYSTEM	(\$3,375.00)	
		UNDER)			15	Feb 16, 2021	SYSTEM	\$3,375.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schlag1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					15	Feb 16, 2021	SYSTEM	(\$3,375.00)	
					16	Mar 2, 2021	SYSTEM	\$3,375.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					16	Mar 2, 2021	SYSTEM	(\$3,375.00)	
					17	Mar 16, 2021	SYSTEM	\$3,375.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					17	Mar 16, 2021	SYSTEM	(\$3,375.00)	
					18	Apr 2, 2021	SYSTEM	\$3,375.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					18	Apr 2, 2021	SYSTEM	(\$3,375.00)	
					19	Apr 16, 2021	SYSTEM	\$4,575.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					19	Apr 16, 2021	SYSTEM	(\$4,575.00)	
					20	May 3, 2021	SYSTEM	\$7,380.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user hillt5 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					20	May 3, 2021	SYSTEM	(\$7,380.00)	
					21	May 17, 2021	SYSTEM	\$7,380.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user hillt5 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$7,380.00)	
					22	Jun 2, 2021	SYSTEM	\$7,380.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user hillt5 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$7,380.00)	
					23	Jun 16, 2021	SYSTEM	\$7,380.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user kloepj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$7,380.00)	
					24	Jul 1, 2021	SYSTEM	\$7,680.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user herrmt1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$7,680.00)	
					25	Jul 16, 2021	SYSTEM	\$7,680.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0048) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$7,680.00)	
				- Total				\$0.00	
	4500	Total	Material - To	tal				\$0.00	
	1560 - 1570	MGS GUARDRAIL	Construction		16	Mar 2,	SYSTEM	\$0.00 (\$4,220.86)	Payment Estimate Item Adjustment generated Stockpile Transaction
			Stockpile		20	2021 May 3, 2021	SYSTEM	(\$589.21)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$4,810.07)	
			Construction	Stockpile - 1	Total Total			(\$4,810.07)	



Type Adjustment Type 3 Aug 17, SYSTEM \$38,968.86 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile Total \$38,968.86 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile Transaction Stockpile STMI - Total \$38,968.86 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile STMI - Total \$38,968.86 Payment Estimate Item Adjustment (0015) due to user nillis overridding Payment Estimate Exception 10 on the current Payment Estimate. Payment Estimate Exception 10 on the current Payment Estimate Exce			5		011			0		B 1		
1570 MGS GLARGRAM Construction Study Construction Construction Study Construction	ct	Line	Description		Adjustment				Amount	Remarks		
STATE Stat	22	1570	MGS GUARDRAIL		Туре	3		SYSTEM	\$38,968.86	Payment Estimate Item Adjustment generated Stockpile Transaction		
Construction Stockpile STML Total					- Total		2020		\$38 968 86			
Material				Construction		TMI - Tota						
2021							May 3,	SYSTEM		Estimate Item Adjustment (0015) due to user hillt5 overridding Payment		
2021 2021						20		SYSTEM	(\$8,797.00)			
22						21		SYSTEM	\$8,797.00	Estimate Item Adjustment (0018) due to user hillt5 overridding Payment		
2021 SySTEM (38.797.00) This adjustment offset be original system-generated Material Payment Estimate Exception 13 on the current Payment Estimate Item Adjustment generated Slockpile Transaction Slockpile Transaction Slockpile Transaction Slockpile Transaction Slockpile Estimate Item Adjustment generated Slockpile Transaction Slockpile Estimate Item Adjustment generated Slockpile Transaction Slockpile Estimate Estimate Item Adjustment generated Slockpile Transaction Slockpile						21		SYSTEM	(\$8,797.00)			
2021 23 Jun 16 SYSTEM 38,797.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user kloegif overridding Payment Estimate Item Adjustment (0017) due to user kloegif overridding Payment Estimate Item Adjustment (0017) due to user kloegif overridding Payment Estimate Exception 18 on the current Payment Estimate Exception 19 on the current Payment Estimate Exception 12 on the current Payment Estimate Item Adjustment generated Stockpile Transaction Exception 12 on the current Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile Transaction Stockpile Transaction Stockpile Transaction Stockpile Transaction Stockpile Transaction Exception Total Stockpile STMI Total Stockpile STMI Total Stockpile STMI Total Stockp						22		SYSTEM	\$8,797.00	Estimate Item Adjustment (0019) due to user hillt5 overridding Payment		
201						22		SYSTEM	(\$8,797.00)			
2021 24						23		SYSTEM	\$8,797.00	Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment		
2021 Estimate Item Adjustment (0015) due to user hermit overridding Payment Estimate Item Adjustment (0015) due to user hermit overridding Payment Estimate Item Adjustment (0015) due to user hermit overridding Payment Estimate Item Adjustment (0015) due to user klosej lo verridding Payment Estimate Item Adjustment (0015) due to user klosej lo verridding Payment Estimate Item Adjustment (0015) due to user klosej lo verridding Payment Estimate Item Adjustment (0015) due to user klosej lo verridding Payment Estimate Item Adjustment (0015) due to user klosej lo verridding Payment Item Adjustment (0015) due to user klosej lo verrid						23		SYSTEM	(\$8,797.00)			
2021 25						24		SYSTEM	\$8,797.00	Estimate Item Adjustment (0015) due to user herrmt1 overridding Payment		
2021 System Estimate Item Adjustment (0022) due to user kloep ft overridding Payment Estimate Item Adjustment (0022) due to user kloep ft overridding Payment Estimate Exception 12 on the current Payment Estimate. 1570 - Total								24		SYSTEM	(\$8,797.00)	
Total S0.00						25		SYSTEM	\$8,797.00	Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment		
Material - Total						25		SYSTEM	(\$8,797.00)			
1570 - Total 1580 MGS BRIDGE APP TRANS SEC (EXT CURB) Stockpile Transaction Stockpile STMI - Total Stackpile					- Total				\$0.00			
Second Part				Material - To	tal							
CURB STM			MGS BRIDGE APP.			3		SYSTEM		Payment Estimate Item Adjustment generated Stockpile Transaction		
1580 - Total 1590 MGS BRIDGE APP. TOTAL 1590 TRANS SEC (REG/NO CURB) 1590 - Total 1590 - Total 1590 - Total 1600 - Total					Total		2020		£2.04C.00			
1580 - Total 1590 MGS BRIDGE APP. TRANS SEC (REG/NO CURB) STMI - Total Construction Stockpile STMI - Total 1590 - Total 1600 MGS VERTICAL CONCRETE BARRIER TRANSITION - Total - Total - Total Construction Stockpile STMI - Total - Total - Total - Total S2,920.00 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile Transaction (\$3,795.00) Payment Estimate Item Adjustment generated Stockpile Transaction (\$1,265.00) Payment Estimate Item Adjustment generated Stockpile Transaction (\$5,060.00) - Total Construction Stockpile - Total Construction Stockpile STMI - Total Construction Stockpile STMI - Total S13,915.00 Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile STMI - Total S13,915.00 Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile STMI - Total S13,915.00 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile STMI - Total S13,915.00 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile STMI - Total S13,915.00 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile STMI - Total S13,915.00 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile STMI - Total S13,915.00 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile STMI - Total S13,915.00 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile STMI - Total S13,915.00 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile STMI - Total S13,915.00 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile STMI - Total				Construction		TMI Tota						
1590 MGS BRIDGE APP. TRANS SEC (REG/NO CURB) STMI Total \$2,920.00		1580 -	Total	Construction	otockpile o	rimi - rota	<u>'</u>					
Construction Stockpile STMI - Total \$2,920.00			MGS BRIDGE APP.			3		SYSTEM		Payment Estimate Item Adjustment generated Stockpile Transaction		
Construction Stockpile STMI - Total \$2,920.00					- Total				\$2,920.00			
MGS VERTICAL CONCRETE BARRIER TRANSITION				Construction	Stockpile S	TMI - Tota						
CONCRETE BARRIER TRANSITION - Total Construction Stockpile - Total Construction Stockpile STMI - Total Construction Stockpile STMI - Total Construction Stockpile STMI - Total Construction Stockpile STMI - Total Construction Stockpile STMI - Total Construction Stockpile STMI - Total Construction Stockpile STMI - Total Construction Stockpile STMI - Total S13,915.00 1600 - Total S8,855.00 1610 MGS END ANCHOR Construction Stockpile Transaction S1021 SYSTEM S13,915.00 S13,915.00 Payment Estimate Item Adjustment generated Stockpile Transaction		1590 -	Total						\$2,920.00			
TRANSITION 20 May 3, 2021 SYSTEM (\$1,265.00) Payment Estimate Item Adjustment generated Stockpile Transaction - Total (\$5,060.00) Construction Stockpile - Total (\$5,060.00) Construction Stockpile STMI 3 Aug 17, 2020 SYSTEM \$13,915.00 Payment Estimate Item Adjustment generated Stockpile Transaction - Total \$13,915.00 Construction Stockpile STMI - Total \$13,915.00 Construction Stockpile STMI - Total \$13,915.00 MGS END ANCHOR Construction Stockpile STMI - Total \$9,855.00 1610 MGS END ANCHOR Construction Stockpile Transaction Stockpile Tra		1600	CONCRETE			16		SYSTEM	(\$3,795.00)	Payment Estimate Item Adjustment generated Stockpile Transaction		
Construction Stockpile - Total Construction Stockpile STMI - Total Construction Stockpile STMI - Total Construction Stockpile STMI - Total Construction Stockpile STMI - Total S13,915.00 S13,915.00 S13,915.00 S13,915.00 S13,915.00 Payment Estimate Item Adjustment generated Stockpile Transaction \$13,915.00 S13,915.00 Payment Estimate Item Adjustment generated Stockpile Transaction S13,915.00 S13,915.00 Payment Estimate Item Adjustment generated Stockpile Transaction S13,915.00 S13,915.00 S13,915.00 S13,915.00 Payment Estimate Item Adjustment generated Stockpile Transaction						20		SYSTEM	(\$1,265.00)	Payment Estimate Item Adjustment generated Stockpile Transaction		
Construction Stockpile STMI - Total Construction Stockpile STMI - Total Construction Stockpile STMI - Total S13,915.00 Construction Stockpile STMI - Total S13,915.00 S13,915.00 S13,915.00 S13,915.00 S13,915.00 Payment Estimate Item Adjustment generated Stockpile Transaction \$8,855.00 S13,915.00 Payment Estimate Item Adjustment generated Stockpile Transaction S13,915.00 S13,915.00 Payment Estimate Item Adjustment generated Stockpile Transaction S13,915.00					- Total				(\$5,060.00)			
Stockpile 2020				Construction	Stockpile - 1	Total			(\$5,060.00)			
Construction Stockpile STMI - Total \$13,915.00 1600 - Total \$8,855.00 1610 MGS END ANCHOR Construction Stockpile				Stockpile		3		SYSTEM	\$13,915.00	Payment Estimate Item Adjustment generated Stockpile Transaction		
1600 - Total\$8,855.001610MGS END ANCHOR StockpileConstruction Stockpile16Mar 2, 2021SYSTEM (\$532.00)Payment Estimate Item Adjustment generated Stockpile Transaction				O I IVII	- Total				\$13,915.00			
1610 MGS END ANCHOR Construction Stockpile 16 Mar 2, 2021 SYSTEM (\$532.00) Payment Estimate Item Adjustment generated Stockpile Transaction				Construction	Stockpile S	TMI - Tota	!		\$13,915.00			
Stockpile 2021		1600 -	Total						\$8,855.00			
- Total (\$532.00)		1610	MGS END ANCHOR			16		SYSTEM	, ,			
					- Total				(\$532.00)			



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks												
J6I2222	1610	MGS END ANCHOR	Construction	Stockpile - 1	Γotal			(\$532.00)													
			Construction Stockpile STMI		3	Aug 17, 2020	SYSTEM	\$4,256.00	Payment Estimate Item Adjustment generated Stockpile Transaction												
				- Total				\$4,256.00													
		_	Construction	Stockpile S	ΓΜΙ - Total			\$4,256.00													
	1610 -		0 1 11		40		OVOTEM	\$3,724.00													
	1620	TYPE A CRASHWORTHY	Construction Stockpile		16	Mar 2, 2021	SYSTEM	(\$4,473.00)	Payment Estimate Item Adjustment generated Stockpile Transaction												
		END TERMINAL (MASH)			20	May 3, 2021	SYSTEM	(\$1,491.00)	Payment Estimate Item Adjustment generated Stockpile Transaction												
				- Total				(\$5,964.00)													
			Construction	Stockpile - 1	Γotal			(\$5,964.00)													
			Construction Stockpile STMI		3	Aug 17, 2020	SYSTEM	\$17,892.00	Payment Estimate Item Adjustment generated Stockpile Transaction												
			STIVII	- Total				\$17,892.00													
			Construction	Stockpile S	ΓΜΙ - Total			\$17,892.00													
	1620 -	Total						\$11,928.00													
	1630	1630 TYPE E CRASHWORTHY END TERMINAL	Construction Stockpile STMI		2	Aug 3, 2020	SYSTEM	\$18,995.00	Payment Estimate Item Adjustment generated Stockpile Transaction												
				- Total				\$18,995.00													
			Construction	Stockpile S	ΓMI - Total			\$18,995.00													
	1630 -							\$18,995.00													
	1780	MISC. HIGHWAY LIGHTING	Material		3	Aug 17, 2020	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.												
					3	Aug 17, 2020	SYSTEM	(\$16,605.00)													
					4	Sep 2, 2020	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.												
					4	Sep 2, 2020	SYSTEM	(\$16,605.00)													
					5	Sep 16, 2020	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.												
					5	Sep 16, 2020	SYSTEM	(\$16,605.00)													
								6	Oct 1, 2020	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 34 on the current Payment Estimate.									
					6	Oct 1, 2020	SYSTEM	(\$16,605.00)													
										7	Oct 16, 2020	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 37 on the current Payment Estimate.							
							7	Oct 16, 2020	SYSTEM	(\$16,605.00)											
					8	Nov 2, 2020	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user hillt5 overridding Payment Estimate Exception 31 on the current Payment Estimate.												
							8	Nov 2, 2020	SYSTEM	(\$16,605.00)											
											9	Nov 16, 2020	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user hillt5 overridding Payment Estimate Exception 32 on the current Payment Estimate.						
														9	Nov 16, 2020	SYSTEM	(\$16,605.00)				
																			10	Dec 2, 2020	SYSTEM
													10	Dec 2, 2020	SYSTEM	(\$16,605.00)					
					11	Dec 16, 2020	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user schlag1 overridding Payment												



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																		
J6I2222	1780	MISC. HIGHWAY LIGHTING	Material						Estimate Exception 30 on the current Payment Estimate.																		
		2.6			11	Dec 16, 2020	SYSTEM	(\$16,605.00)																			
					12	Jan 4, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.																		
					12	Jan 4, 2021	SYSTEM	(\$16,605.00)																			
					13	Jan 19, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schlag1 overridding Payment Estimate Exception 30 on the current Payment Estimate.																		
					13	Jan 19, 2021	SYSTEM	(\$16,605.00)																			
					14	Feb 2, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hillt5 overridding Payment Estimate Exception 56 on the current Payment Estimate.																		
					14	Feb 2, 2021	SYSTEM	(\$16,605.00)																			
					15	Feb 16, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schlag1 overridding Payment Estimate Exception 55 on the current Payment Estimate.																		
					15	Feb 16, 2021	SYSTEM	(\$16,605.00)																			
					16	Mar 2, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 51 on the current Payment Estimate.																		
					16	Mar 2, 2021	SYSTEM	(\$16,605.00)																			
					17	Mar 16, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user kloepj1 overridding Payment Estimate Exception 44 on the current Payment Estimate.																		
					17	Mar 16, 2021	SYSTEM	(\$16,605.00)																			
							18	Apr 2, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment Estimate Exception 58 on the current Payment Estimate.																
					18	Apr 2, 2021	SYSTEM	(\$16,605.00)																			
						19	Apr 16, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 66 on the current Payment Estimate.																	
							19	Apr 16, 2021	SYSTEM	(\$16,605.00)																	
					20	May 3, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user hillt5 overridding Payment Estimate Exception 91 on the current Payment Estimate.																		
					20	May 3, 2021	SYSTEM	(\$16,605.00)																			
																			21	May 17, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user hillto overridding Payment Estimate Exception 111 on the current Payment Estimate.				
								21	May 17, 2021	SYSTEM	(\$16,605.00)																
																	22	Jun 2, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user hillt5 overridding Payment Estimate Exception 122 on the current Payment Estimate.						
																		22	Jun 2, 2021	SYSTEM	(\$16,605.00)						
					23	Jun 16, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 121 on the current Payment Estimate.																		
												2				2	23	23	23		23		23	Jun 16, 2021	SYSTEM	(\$16,605.00)	
					24	Jul 1, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user herrmt1 overridding Payment Estimate Exception 80 on the current Payment Estimate.																		
					24	Jul 1, 2021	SYSTEM	(\$16,605.00)																			



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks											
612222	1780	MISC. HIGHWAY LIGHTING	Material	i ype	25	Jul 16, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment Estimate Exception 76 on the current Payment Estimate.											
					25	Jul 16, 2021	SYSTEM	(\$16,605.00)	Estimate Exception 70 of the Current Payment Estimate.											
				- Total		2021		\$0.00												
			Material - To					\$0.00												
	1780 -	Total						\$0.00												
	1870	SIGNAL HEAD, TYPE 3B	Material		21	May 17, 2021	SYSTEM	\$4,635.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user hillt5 overridding Payment Estimate Exception 112 on the current Payment Estimate.											
					21	May 17, 2021	SYSTEM	(\$4,635.00)												
					22	Jun 2, 2021	SYSTEM	\$4,635.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hillt5 overridding Payment Estimate Exception 123 on the current Payment Estimate.											
					22	Jun 2, 2021	SYSTEM	(\$4,635.00)												
					23	Jun 16, 2021	SYSTEM	\$4,635.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 122 on the current Payment Estimate.											
					23	Jun 16, 2021	SYSTEM	(\$4,635.00)												
					24	Jul 1, 2021	SYSTEM	\$4,635.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user herrmt1 overridding Payment Estimate Exception 81 on the current Payment Estimate.											
																24	Jul 1, 2021	SYSTEM	(\$4,635.00)	
								25	Jul 16, 2021	SYSTEM	\$4,635.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user kloepj1 overridding Payment Estimate Exception 77 on the current Payment Estimate.								
							25	Jul 16, 2021	SYSTEM	(\$4,635.00)										
				- Total				\$0.00												
			Material - To	Total				\$0.00												
	1870 -	Total						\$0.00												
	1910	POST, SIGNAL 8 FT. OR 2.4 M	Material		21	May 17, 2021	SYSTEM	\$1,935.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hillt5 overridding Payment Estimate Exception 113 on the current Payment Estimate.											
					21	May 17, 2021	SYSTEM	(\$1,935.00)												
					22	Jun 2, 2021	SYSTEM	\$1,935.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user hillt5 overridding Payment Estimate Exception 124 on the current Payment Estimate.											
					22	Jun 2, 2021	SYSTEM	(\$1,935.00)												
					23	Jun 16, 2021	SYSTEM	\$1,935.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 123 on the current Payment Estimate.											
					23	Jun 16, 2021	SYSTEM	(\$1,935.00)												
				2	24	24	Jul 1, 2021	SYSTEM	\$1,935.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user herrmt1 overridding Payment Estimate Exception 82 on the current Payment Estimate.										
				24	Jul 1, 2021	SYSTEM	(\$1,935.00)													
					25	Jul 16, 2021	SYSTEM	\$1,935.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user kloepj1 overridding Payment Estimate Exception 78 on the current Payment Estimate.											
					25	Jul 16, 2021	SYSTEM	(\$1,935.00)												
				- Total				\$0.00												
			Material - To	tal				\$0.00												
	1910 -	Total						\$0.00												
	1960	POST, TYPE C, 55	Material		21	May 17,	SYSTEM	\$11,930.00	This adjustment offsets the original system-generated Material Payment											



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
22	1960	FT. ARM	Material		04	2021	OVOTE::	(044,000,000	Estimate Item Adjustment (0022) due to user hillt5 overridding Payment Estimate Exception 116 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$11,930.00)	
					22	Jun 2, 2021	SYSTEM	\$11,930.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user hillt5 overridding Payment Estimate Exception 127 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$11,930.00)	
					23	Jun 16, 2021	SYSTEM	\$11,930.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment Estimate Exception 126 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$11,930.00)	
					24	Jul 1, 2021	SYSTEM	\$11,930.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user herrmt1 overridding Payment Estimate Exception 85 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$11,930.00)	
					25	Jul 16, 2021	SYSTEM	\$11,930.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user kloepj1 overridding Payment Estimate Exception 81 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$11,930.00)	
				- Total				\$0.00	
	1960	Total	Material - To	tai				\$0.00 \$0.00	
	1990	990 CONTROLLER ASSEMBLY HOUSING,	Material		21	May 17, 2021	SYSTEM	\$13,359.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user hillt5 overridding Payment Estimate Exception 117 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$13,359.00)	
					22	Jun 2, 2021	SYSTEM	\$13,359.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user hillt5 overridding Payment Estimate Exception 129 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$13,359.00)	
					23	Jun 16, 2021	SYSTEM	\$13,359.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment Estimate Exception 128 on the current Payment Estimate.
					23		SYSTEM	\$13,359.00 (\$13,359.00)	Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment
						2021 Jun 16,			Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment
					23	Jun 16, 2021 Jul 1,	SYSTEM	(\$13,359.00)	Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment Estimate Exception 128 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user herrmt1 overridding Payment
					23	Jun 16, 2021 Jul 1, 2021 Jul 1,	SYSTEM	(\$13,359.00) \$13,359.00	Estimate Item Adjustment (0022) due to user kloep/1 overridding Payment Estimate Exception 128 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user herrmt1 overridding Payment
					23 24 24	Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16,	SYSTEM SYSTEM	(\$13,359.00) \$13,359.00 (\$13,359.00) \$13,359.00 (\$13,359.00)	Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment Estimate Exception 128 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user herrmt1 overridding Payment Estimate Exception 87 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user kloepj1 overridding Payment
				- Total	23 24 24 25	2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16,	SYSTEM SYSTEM SYSTEM	(\$13,359.00) \$13,359.00 (\$13,359.00) \$13,359.00 (\$13,359.00)	Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment Estimate Exception 128 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user herrmt1 overridding Payment Estimate Exception 87 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user kloepj1 overridding Payment
	1000	Total	Material - Tol		23 24 24 25	2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16,	SYSTEM SYSTEM SYSTEM	(\$13,359.00) \$13,359.00 (\$13,359.00) \$13,359.00 (\$13,359.00) \$0.00	Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment Estimate Exception 128 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user herrmt1 overridding Payment Estimate Exception 87 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user kloepj1 overridding Payment
	1990 -	CONDUIT, 3 IN., PUSHED WITH	Material - Tol		23 24 24 25 25	2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16,	SYSTEM SYSTEM SYSTEM	(\$13,359.00) \$13,359.00 (\$13,359.00) \$13,359.00 (\$13,359.00)	Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment Estimate Exception 128 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user herrmt1 overridding Payment Estimate Exception 87 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user kloepj1 overridding Payment
		CONDUIT, 3 IN.,		tal	23 24 24 25 25 25	2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 May 17,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$13,359.00) \$13,359.00 (\$13,359.00) \$13,359.00 (\$13,359.00) \$0.00 \$0.00	Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment Estimate Exception 128 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user herrmt1 overridding Payment Estimate Exception 87 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user kloepj1 overridding Payment
		CONDUIT, 3 IN., PUSHED WITH		Overrun Overrun - To	23 24 24 25 25 25	2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 May 17,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$13,359.00) \$13,359.00 (\$13,359.00) \$13,359.00 (\$13,359.00) \$0.00 \$0.00 (\$621.00)	Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment Estimate Exception 128 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user herrmt1 overridding Payment Estimate Exception 87 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user kloepj1 overridding Payment
		CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	Overrun	Overrun Overrun - To	23 24 24 25 25 25	2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 May 17,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$13,359.00) \$13,359.00 (\$13,359.00) \$13,359.00 (\$13,359.00) \$0.00 \$0.00 (\$621.00)	Estimate Item Adjustment (0022) due to user kloep/1 overridding Payment Estimate Exception 128 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user herrmt1 overridding Payment Estimate Exception 87 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user kloep/1 overridding Payment
	2020	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	Overrun	Overrun Overrun - To	23 24 24 25 25 25	2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 May 17,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$13,359.00) \$13,359.00 (\$13,359.00) \$13,359.00 (\$13,359.00) \$0.00 \$0.00 (\$621.00) (\$621.00)	Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment Estimate Exception 128 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user herrmt1 overridding Payment Estimate Exception 87 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user kloepj1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
				Туре					
J6I2222	2060	CABLE, 16 AWG 7 CONDUCTOR	Material		22	Jun 2, 2021	SYSTEM	\$1,881.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user hillt5 overridding Payment Estimate Exception 130 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$1,881.60)	
					23	Jun 16, 2021	SYSTEM	\$1,881.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment Estimate Exception 129 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$1,881.60)	
					24	Jul 1, 2021	SYSTEM	\$1,881.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hermit overridding Payment
					24	Jul 1,	SYSTEM	(\$1,881.60)	Estimate Exception 88 on the current Payment Estimate.
						2021	OTOTEM	(ψ1,001.00)	
					25	Jul 16, 2021	SYSTEM	\$1,881.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user kloepj1 overridding Payment Estimate Exception 83 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$1,881.60)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	2060 -	Total						\$0.00	
	2080	PULL BOX, PREFORMED	Overrun	Overrun	21	May 17, 2021	SYSTEM	(\$1,221.00)	
		CLASS 2		Overrun - T	otal			(\$1,221.00)	
			Overrun - To	tal				(\$1,221.00)	
	2080 -	Total						(\$1,221.00)	
	2100	BASE, CONCRETE	Material		18	Apr 2, 2021	SYSTEM	\$2,320.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 59 on the current Payment Estimate.
					18	Apr 2, 2021	SYSTEM	(\$2,320.00)	
					19	Apr 16, 2021	SYSTEM	\$7,644.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 67 on the current Payment Estimate.
					19	Apr 16, 2021	SYSTEM	(\$7,644.40)	
					20	May 3, 2021	SYSTEM	\$7,644.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user hillt5 overridding Payment Estimate Exception 92 on the current Payment Estimate.
					20	May 3, 2021	SYSTEM	(\$7,644.40)	
					21	May 17, 2021	SYSTEM	\$7,644.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user hillt5 overridding Payment Estimate Exception 119 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$7,644.40)	
					22	Jun 2, 2021	SYSTEM	\$7,644.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user hillt5 overridding Payment Estimate Exception 131 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$7,644.40)	
					23	Jun 16, 2021	SYSTEM	\$7,644.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user kloepj1 overridding Payment Estimate Exception 130 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$7,644.40)	
					24	Jul 1, 2021	SYSTEM	\$7,644.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user herrmt1 overridding Payment Estimate Exception 89 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$7,644.40)	
					25	Jul 16, 2021	SYSTEM	\$7,644.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user kloepj1 overridding Payment Estimate Exception 84 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks																						
J6I2222	2100	BASE, CONCRETE	Material	Туре	25	Jul 16, 2021	SYSTEM	(\$7,644.40)																							
				- Total		2021		\$0.00																							
			Material - Tot					\$0.00																							
	2100 -	Total						\$0.00																							
	2210	CONCRETE FOOTINGS, BOLT DOWN	Material		3	Aug 17, 2020	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.																						
					3	Aug 17, 2020	SYSTEM	(\$15,000.00)																							
					4	Sep 2, 2020	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 13 on the current Payment Estimate.																						
						4	Sep 2, 2020	SYSTEM	(\$15,000.00)																						
							5	Sep 16, 2020	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user kloepj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.																				
														5	Sep 16, 2020	SYSTEM	(\$15,000.00)														
									6	Oct 1, 2020	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment Estimate Exception 35 on the current Payment Estimate.																		
					6	Oct 1, 2020	SYSTEM	(\$15,000.00)																							
					7	Oct 16, 2020	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment Estimate Exception 38 on the current Payment Estimate.																						
						7	Oct 16, 2020	SYSTEM	(\$15,000.00)																						
					8	Nov 2, 2020	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user hillt5 overridding Payment Estimate Exception 32 on the current Payment Estimate.																						
					8	Nov 2, 2020	SYSTEM	(\$15,000.00)																							
					9	Nov 16, 2020	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user hillt5 overridding Payment Estimate Exception 33 on the current Payment Estimate.																						
						9	Nov 16, 2020	SYSTEM	(\$15,000.00)																						
									10	Dec 2, 2020	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.																		
											10	Dec 2, 2020	SYSTEM	(\$15,000.00)																	
																	11	Dec 16, 2020	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user schlag1 overridding Payment Estimate Exception 31 on the current Payment Estimate.										
																11	Dec 16, 2020	SYSTEM	(\$15,000.00)												
								12	Jan 4, 2021	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 34 on the current Payment Estimate.																			
															12	Jan 4, 2021	SYSTEM	(\$15,000.00)													
																		13	Jan 19, 2021	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schlag1 overridding Payment Estimate Exception 31 on the current Payment Estimate.									
							13	Jan 19, 2021	SYSTEM	(\$15,000.00)																					
																							-		1		14	Feb 2, 2021	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hillt5 overridding Payment Estimate Exception 57 on the current Payment Estimate.
												14	Feb 2, 2021	SYSTEM	(\$15,000.00)																
					15	Feb 16, 2021	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schlag1 overridding Payment																						



t	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
2	2210	CONCRETE FOOTINGS, BOLT	Material						Estimate Exception 56 on the current Payment Estimate.
		DOWN			15	Feb 16, 2021	SYSTEM	(\$15,000.00)	
					16	Mar 2, 2021	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 52 on the current Payment Estimate.
					16	Mar 2, 2021	SYSTEM	(\$15,000.00)	
					17	Mar 16, 2021	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment Estimate Exception 45 on the current Payment Estimate.
					17	Mar 16, 2021	SYSTEM	(\$15,000.00)	
					18	Apr 2, 2021	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 60 on the current Payment Estimate.
					18	Apr 2, 2021	SYSTEM	(\$15,000.00)	
					19	Apr 16, 2021	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 68 on the current Payment Estimate.
					19	Apr 16, 2021	SYSTEM	(\$15,000.00)	
					20	May 3, 2021	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user hillt5 overridding Payment Estimate Exception 93 on the current Payment Estimate.
					20	May 3, 2021	SYSTEM	(\$15,000.00)	
					21	May 17, 2021	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user hillt5 overridding Payment Estimate Exception 120 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$15,000.00)	
					22	Jun 2, 2021	SYSTEM	\$50,784.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user hillt5 overridding Payment Estimate Exception 132 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$50,784.00)	
					23	Jun 16, 2021	SYSTEM	\$50,784.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user kloepj1 overridding Payment Estimate Exception 131 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$50,784.00)	
					24	Jul 1, 2021	SYSTEM	\$67,584.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user herrmt1 overridding Payment Estimate Exception 90 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$67,584.00)	
					25	Jul 16, 2021	SYSTEM	\$67,584.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user kloepj1 overridding Payment Estimate Exception 85 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$67,584.00)	
			Material - Tot	- Total				\$0.00	
	2210 -	Total	waterial - To	lai				\$0.00 \$0.00	
	2220	STRUCTURAL STEEL POSTS	Construction Stockpile STMI		5	Sep 16, 2020	SYSTEM	\$7,567.11	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$7,567.11	
			Construction	Stockpile S	ΓΜΙ - Total			\$7,567.11	
	2220 - 2230	Total PIPE POSTS	Construction Stockpile		5	Sep 16, 2020	SYSTEM	\$7,567.11 \$10,734.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total		.=-		\$10,734.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
612222	2230 -	· Total						\$10,734.00	
	2240	2 IN. PSST POST - 12 GA.	Construction Stockpile		23	Jun 16, 2021	SYSTEM	\$259.20	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$259.20	
			Construction	Stockpile S	TMI - Total			\$259.20	
	2240 -	· Total						\$259.20	
	2250	POST ANCHOR FOR 2 IN. PSST - 12 GA.	Construction Stockpile STMI		23	Jun 16, 2021	SYSTEM	\$100.17	Payment Estimate Item Adjustment generated Stockpile Transaction
		GA.	STIVII	- Total				\$100.17	
			Construction	Stockpile S	TMI - Total			\$100.17	
	2250 -	· Total						\$100.17	
	2260	SH-FLAT SHEET	Construction Stockpile STMI		23	Jun 16, 2021	SYSTEM	\$4,724.20	Payment Estimate Item Adjustment generated Stockpile Transaction
			OTIVII	- Total				\$4,724.20	
			Construction	Stockpile S	TMI - Total			\$4,724.20	
	2260 -	· Total						\$4,724.20	
	2270	ST-STRUCTURAL	Construction Stockpile		25	Jul 16, 2021	SYSTEM	(\$2,190.22)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$2,190.22)	
			Construction	Stockpile - 1	Total			(\$2,190.22)	
			Construction Stockpile STMI		23	Jun 16, 2021	SYSTEM	\$30,495.60	Payment Estimate Item Adjustment generated Stockpile Transaction
			STIVII	- Total				\$30,495.60	
			Construction	Stockpile S	TMI - Total			\$30,495.60	
	2270 -	· Total						\$28,305.38	
	2280 SHF-FLAT SHEET FLUORESCENT	Construction Stockpile STMI		23	Jun 16, 2021	SYSTEM	\$1,013.70	Payment Estimate Item Adjustment generated Stockpile Transaction	
			STIVII	- Total				\$1,013.70	
			Construction	Stockpile S	TMI - Total			\$1,013.70	
	2280 -	Total						\$1,013.70	
	2290	STF-STRUCTURAL FLUORESCENT	Construction Stockpile		25	Jul 16, 2021	SYSTEM	(\$1,341.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$1,341.00)	
			Construction	Stockpile - 1	Total			(\$1,341.00)	
			Construction Stockpile STMI		23	Jun 16, 2021	SYSTEM	\$5,811.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$5,811.00	
			Construction	Stockpile S	TMI - Total			\$5,811.00	
	2290 -	· Total						\$4,470.00	
	2300	TUBULAR SUPPORT, TYPE C-2315-20	Construction Stockpile STMI		8	Nov 2, 2020	SYSTEM	\$1,400.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$1,400.00	
			Construction	Stockpile S	TMI - Total			\$1,400.00	
	2300 -	· Total						\$1,400.00	
	2310	TUBULAR SUPPORT, TYPE C-2018-28	Construction Stockpile STMI		8	Nov 2, 2020	SYSTEM	\$1,400.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		5 25 .5 26		- Total				\$1,400.00	
			Construction	Stockpile S	TMI - Total			\$1,400.00	
	2310	· Total						\$1,400.00	
	2320	MISC. HIGHWAY SIGNING	Construction Stockpile STMI		8	Nov 2, 2020	SYSTEM	\$2,300.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			511411	- Total				\$2,300.00	
			Construction	Stockpile S	TMI - Total			\$2,300.00	
	2320 -	· Total						\$2,300.00	
	2330	MISC. HIGHWAY SIGNING	Construction Stockpile		25	Jul 16, 2021	SYSTEM	(\$50,900.00)	Payment Estimate Item Adjustment generated Stockpile Transaction



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks											
J6I2222	2330	MISC. HIGHWAY SIGNING	Construction Stockpile	- Total				(\$50,900.00)												
			Construction	Stockpile - 1	Γotal			(\$50,900.00)												
			Construction Stockpile		8	Nov 2, 2020	SYSTEM	\$2,600.00	Payment Estimate Item Adjustment generated Stockpile Transaction											
			STMI		23	Jun 16, 2021	SYSTEM	\$48,300.00	Payment Estimate Item Adjustment generated Stockpile Transaction											
				- Total				\$50,900.00												
			Construction	Stockpile S1	ΓMI - Total			\$50,900.00												
			Material		25	Jul 16, 2021	SYSTEM	\$66,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user kloepj1 overridding Payment Estimate Exception 87 on the current Payment Estimate.											
					25	Jul 16, 2021	SYSTEM	(\$66,000.00)												
				- Total				\$0.00												
			Material - Tot	tal				\$0.00												
	2330 -	Total						\$0.00												
	2340	MISC. HIGHWAY SIGNING	Construction Stockpile STMI		8	Nov 2, 2020	SYSTEM	\$2,600.00	Payment Estimate Item Adjustment generated Stockpile Transaction											
				- Total				\$2,600.00												
			Construction	Stockpile S1	ΓΜΙ - Total			\$2,600.00												
	2340 -				40		OVOTEM	\$2,600.00												
	2650	CLASS B CONCRETE (SUBSTRUCTURE)	Material		16	Mar 2, 2021	SYSTEM	\$5,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 36 on the current Payment Estimate.											
							16	Mar 2, 2021	SYSTEM	(\$5,050.00)										
										17	Mar 16, 2021	SYSTEM	\$5,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.						
								17	Mar 16, 2021	SYSTEM	(\$5,050.00)	Established Established Established Established								
							18	Apr 2, 2021	SYSTEM	\$5,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 30 on the current Payment Estimate.									
						18	Apr 2, 2021	SYSTEM	(\$5,050.00)											
					19	Apr 16, 2021	SYSTEM	\$5,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.											
					19	Apr 16, 2021	SYSTEM	(\$5,050.00)												
																20	May 3, 2021	SYSTEM	\$5,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user hillt5 overridding Payment Estimate Exception 35 on the current Payment Estimate.
						20	May 3, 2021	SYSTEM	(\$5,050.00)											
										21						21	May 17, 2021	SYSTEM	\$5,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user hillt5 overridding Payment Estimate Exception 55 on the current Payment Estimate.
											21	May 17, 2021	SYSTEM	(\$5,050.00)						
														22	Jun 2, 2021	SYSTEM	\$5,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user hillt5 overridding Payment Estimate Exception 67 on the current Payment Estimate.		
					22	Jun 2, 2021	SYSTEM	(\$5,050.00)												
														23	Jun 16, 2021	SYSTEM	\$5,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user kloepj1 overridding Payment Estimate Exception 69 on the current Payment Estimate.		
					23	Jun 16, 2021	SYSTEM	(\$5,050.00)	Esception of our are outloned aymone Estimate.											
					- Total				\$0.00											
			Material - Tot	tal				\$0.00												



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	2650 -	· Total						\$0.00	
	2670	SLAB ON STEEL	Material		14	Feb 2, 2021	SYSTEM	\$17,390.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user hillt5 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					14	Feb 2, 2021	SYSTEM	(\$17,390.00)	
					15	Feb 16, 2021	SYSTEM	\$17,390.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schlag1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
					15	Feb 16, 2021	SYSTEM	(\$17,390.00)	
					16	Mar 2, 2021	SYSTEM	\$34,780.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
					16	Mar 2, 2021	SYSTEM	(\$34,780.00)	
					17	Mar 16, 2021	SYSTEM	\$34,780.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					17	Mar 16, 2021	SYSTEM	(\$34,780.00)	
					18	Apr 2, 2021	SYSTEM	\$99,640.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					18	Apr 2, 2021	SYSTEM	(\$99,640.00)	
					19	Apr 16, 2021	SYSTEM	\$99,640.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					19	Apr 16, 2021	SYSTEM	(\$99,640.00)	
					20	May 3, 2021	SYSTEM	\$99,640.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user hillt5 overridding Payment Estimate Exception 43 on the current Payment Estimate.
					20	May 3, 2021	SYSTEM	(\$99,640.00)	
					21	May 17, 2021	SYSTEM	\$100,580.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user hillt5 overridding Payment Estimate Exception 62 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$100,580.00)	
					22	Jun 2, 2021	SYSTEM	\$100,580.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user hillt5 overridding Payment Estimate Exception 74 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$100,580.00)	
					23	Jun 16, 2021	SYSTEM	\$100,580.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0048) due to user kloepj1 overridding Payment Estimate Exception 76 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$100,580.00)	
					24	Jul 1, 2021	SYSTEM	\$100,580.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user herrmt1 overridding Payment Estimate Exception 41 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$100,580.00)	
					25	Jul 16, 2021	SYSTEM	\$100,580.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0049) due to user kloepj1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$100,580.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	2670 -	· Total						\$0.00	
	2690	CORRAL CURB	Material		19	Apr 16, 2021	SYSTEM	\$16,614.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user kloepj1 overridding Payment Estimate Exception 37 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	2690	CORRAL CURB	Material		19	Apr 16, 2021	SYSTEM	(\$16,614.00)	
					20	May 3, 2021	SYSTEM	\$16,614.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user hillt5 overridding Payment Estimate Exception 48 on the current Payment Estimate.
					20	May 3, 2021	SYSTEM	(\$16,614.00)	
					21	May 17, 2021	SYSTEM	\$16,614.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user hillt5 overridding Payment Estimate Exception 68 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$16,614.00)	
					22	Jun 2, 2021	SYSTEM	\$16,614.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user hillto overridding Payment Estimate Exception 80 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$16,614.00)	
					23	Jun 16, 2021	SYSTEM	\$16,614.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0049) due to user kloepj1 overridding Payment Estimate Exception 81 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$16,614.00)	
					24	Jul 1, 2021	SYSTEM	\$16,614.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user herrmt1 overridding Payment Estimate Exception 44 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$16,614.00)	
					25	Jul 16, 2021	SYSTEM	\$16,614.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user kloepj1 overridding Payment Estimate Exception 41 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$16,614.00)	
								00.00	
				- Total				\$0.00	
	2690 -	. Total	Material - To					\$0.00	
	2690 - 2700	Total SUPERSTRUCTURE REPAIR (UNFORMED)	Material - To		17	Mar 16, 2021	SYSTEM		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
		SUPERSTRUCTURE REPAIR			17		SYSTEM	\$0.00 \$0.00	Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment
		SUPERSTRUCTURE REPAIR				2021 Mar 16,		\$0.00 \$0.00 \$13,114.00	Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment
		SUPERSTRUCTURE REPAIR			17	2021 Mar 16, 2021 Apr 2,	SYSTEM	\$0.00 \$0.00 \$13,114.00 (\$13,114.00)	Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment
		SUPERSTRUCTURE REPAIR			17	2021 Mar 16, 2021 Apr 2, 2021	SYSTEM SYSTEM	\$0.00 \$0.00 \$13,114.00 (\$13,114.00) \$33,022.00	Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment
		SUPERSTRUCTURE REPAIR			17 18	2021 Mar 16, 2021 Apr 2, 2021 Apr 2, 2021 Apr 16,	SYSTEM SYSTEM	\$0.00 \$0.00 \$13,114.00 (\$13,114.00) \$33,022.00 (\$33,022.00)	Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user kloepj1 overridding Payment
		SUPERSTRUCTURE REPAIR			17 18 18 19	2021 Mar 16, 2021 Apr 2, 2021 Apr 2, 2021 Apr 16, 2021 Apr 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$13,114.00 (\$13,114.00) \$33,022.00 (\$33,022.00) \$33,022.00	Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user kloepj1 overridding Payment
		SUPERSTRUCTURE REPAIR			17 18 18 19	2021 Mar 16, 2021 Apr 2, 2021 Apr 16, 2021 Apr 16, 2021 May 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$13,114.00 (\$13,114.00) \$33,022.00 (\$33,022.00) (\$33,022.00)	Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user kloepj1 overridding Payment Estimate Exception 39 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user hillts overridding Payment Estimate Item Adjustment (0029) due to user hillts overridding Payment
		SUPERSTRUCTURE REPAIR			17 18 18 19 19	2021 Mar 16, 2021 Apr 2, 2021 Apr 2, 2021 Apr 16, 2021 Apr 16, 2021 May 3, 2021 May 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$13,114.00 (\$13,114.00) \$33,022.00 (\$33,022.00) \$33,022.00 (\$33,022.00)	Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user kloepj1 overridding Payment Estimate Exception 39 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user hillts overridding Payment Estimate Item Adjustment (0029) due to user hillts overridding Payment
		SUPERSTRUCTURE REPAIR			17 18 18 19 19 20 20	2021 Mar 16, 2021 Apr 2, 2021 Apr 2, 2021 Apr 16, 2021 Apr 16, 2021 May 3, 2021 May 3, 2021 May 17, May 17,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$13,114.00 (\$13,114.00) \$33,022.00 (\$33,022.00) \$33,022.00 (\$33,022.00) (\$74,892.00)	Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user kloepj1 overridding Payment Estimate Exception 39 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user hillt5 overridding Payment Estimate Exception 50 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 50 on the current Payment Estimate.
		SUPERSTRUCTURE REPAIR			17 18 18 19 19 20 20 21	2021 Mar 16, 2021 Apr 2, 2021 Apr 2, 2021 Apr 16, 2021 Apr 16, 2021 May 3, 2021 May 3, 2021 May 17, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$13,114.00 (\$13,114.00) \$33,022.00 (\$33,022.00) (\$33,022.00) \$74,892.00 (\$74,892.00) \$133,826.00	Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user kloepj1 overridding Payment Estimate Exception 39 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user hillt5 overridding Payment Estimate Exception 50 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 50 on the current Payment Estimate.
		SUPERSTRUCTURE REPAIR			17 18 18 19 19 20 20 21	2021 Mar 16, 2021 Apr 2, 2021 Apr 2, 2021 Apr 16, 2021 Apr 16, 2021 May 3, 2021 May 17, 2021 May 17, 2021 Jun 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$13,114.00 (\$13,114.00) \$33,022.00 (\$33,022.00) (\$33,022.00) (\$74,892.00) (\$74,892.00) \$133,826.00	Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user kloepj1 overridding Payment Estimate Exception 39 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user hillt5 overridding Payment Estimate Exception 50 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user hillt5 overridding Payment Estimate Exception 70 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 70 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks													
J6I2222	2700	SUPERSTRUCTURE REPAIR	Material						Estimate Exception 83 on the current Payment Estimate.													
		(UNFORMED)			23	Jun 16, 2021	SYSTEM	(\$195,604.00)														
					24	Jul 1, 2021	SYSTEM	\$200,502.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user herrmt1 overridding Payment Estimate Exception 46 on the current Payment Estimate.													
					24	Jul 1, 2021	SYSTEM	(\$200,502.00)														
					25	Jul 16, 2021	SYSTEM	\$200,502.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0051) due to user kloepj1 overridding Payment Estimate Exception 43 on the current Payment Estimate.													
					25	Jul 16, 2021	SYSTEM	(\$200,502.00)														
				- Total				\$0.00														
			Material - Tot	tal				\$0.00														
	2700 -	· Total						\$0.00														
	2720	MISC.	Material		20	May 3, 2021	SYSTEM	\$17,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user hillt5 overridding Payment Estimate Exception 58 on the current Payment Estimate.													
					20	May 3, 2021	SYSTEM	(\$17,150.00)														
					21	May 17, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user hillt5 overridding Payment Estimate Exception 78 on the current Payment Estimate.													
					21	May 17, 2021	SYSTEM	(\$23,800.00)														
					22	Jun 2, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user hillt5 overridding Payment Estimate Exception 90 on the current Payment Estimate.													
					22	Jun 2, 2021	SYSTEM	(\$23,800.00)														
					23	Jun 16, 2021	SYSTEM	\$25,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0051) due to user kloepj1 overridding Payment Estimate Exception 91 on the current Payment Estimate.													
					23	Jun 16, 2021	SYSTEM	(\$25,550.00)														
					24	Jul 1, 2021	SYSTEM	\$25,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user herrmt1 overridding Payment Estimate Exception 54 on the current Payment Estimate.													
					24	Jul 1, 2021	SYSTEM	(\$25,550.00)														
					25	Jul 16, 2021	SYSTEM	\$25,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0052) due to user kloepj1 overridding Payment Estimate Exception 51 on the current Payment Estimate.													
					25	Jul 16, 2021	SYSTEM	(\$25,900.00)														
				- Total				\$0.00														
			Material - Tot	tal				\$0.00														
	2720 - 2730	REINFORCING STEEL (EPOXY	Material		18	Apr 2, 2021	SYSTEM	\$0.00 \$2,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment													
		COATED)																18	Apr 2, 2021	SYSTEM	(\$2,550.00)	Estimate Exception 40 on the current Payment Estimate.
					19	Apr 16, 2021	SYSTEM	\$2,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user kloepj1 overridding Payment Estimate Exception 44 on the current Payment Estimate.													
					19	Apr 16, 2021	SYSTEM	(\$2,550.00)	,													
					20	May 3, 2021	SYSTEM	\$2,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user hillt5 overridding Payment Estimate Exception 62 on the current Payment Estimate.													
					20	May 3, 2021	SYSTEM	(\$2,550.00)														
					21	May 17, 2021	SYSTEM	\$2,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user hillt5 overridding Payment													



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	2730	REINFORCING STEEL (EPOXY	Material						Estimate Exception 82 on the current Payment Estimate.
		COATED)			21	May 17, 2021	SYSTEM	(\$2,550.00)	
					22	Jun 2, 2021	SYSTEM	\$2,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user hillt5 overridding Payment Estimate Exception 96 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$2,550.00)	
					23	Jun 16, 2021	SYSTEM	\$2,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0052) due to user kloepj1 overridding Payment Estimate Exception 96 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$2,550.00)	
					24	Jul 1, 2021	SYSTEM	\$2,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user herrmt1 overridding Payment Estimate Exception 58 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$2,550.00)	
					25	Jul 16, 2021	SYSTEM	\$2,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0053) due to user kloepj1 overridding Payment Estimate Exception 53 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$2,550.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	2730 -	Total						\$0.00	
	2790	STRIP SEAL EXPANSION JOINT SYSTEM	Construction Stockpile STMI		14	Feb 2, 2021	SYSTEM	\$9,471.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			O a madema attack	- Total	T-4-1			\$9,471.00	
	2790 -	Total	Construction	1 Stockpile S1	IVII - TOTA			\$9,471.00 \$9,471.00	
		- Total SUPERSTRUCTURE	REPAIR		18	Apr 2,	SYSTEM	\$33,654.00	This adjustment effects the original system generated Material Dayment
		REPAIR	Waterial		10	2021	0.0.2	ψ50,054.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment Estimate Expension 30 on the current Payment Estimate Expension 30 on the current Payment Estimate
			Waterial		18		SYSTEM	(\$33,654.00)	
		REPAIR	Watchal			2021 Apr 2,			Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment
		REPAIR	wacha		18	2021 Apr 2, 2021 Apr 16,	SYSTEM	(\$33,654.00)	Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment Estimate Exception 39 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user kloepj1 overridding Payment
		REPAIR			18	2021 Apr 2, 2021 Apr 16, 2021 Apr 16,	SYSTEM	(\$33,654.00) \$73,628.00	Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment Estimate Exception 39 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user kloepj1 overridding Payment
		REPAIR			18 19	2021 Apr 2, 2021 Apr 16, 2021 Apr 16, 2021 May 3,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$33,654.00) \$73,628.00 (\$73,628.00)	Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment Estimate Exception 39 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user kloepj1 overridding Payment Estimate Exception 40 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user hillt5 overridding Payment
		REPAIR			18 19 19 20	2021 Apr 2, 2021 Apr 16, 2021 Apr 16, 2021 May 3, 2021 May 3,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$33,654.00) \$73,628.00 (\$73,628.00) \$131,140.00	Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment Estimate Exception 39 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user kloepj1 overridding Payment Estimate Exception 40 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user hillt5 overridding Payment
		REPAIR			18 19 19 20 20	2021 Apr 2, 2021 Apr 16, 2021 Apr 16, 2021 May 3, 2021 May 3, 2021 May 17, 17, 18, 18, 18, 18, 18, 18, 18, 18, 18, 18	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$33,654.00) \$73,628.00 (\$73,628.00) \$131,140.00	Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment Estimate Exception 39 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user kloepj1 overridding Payment Estimate Exception 40 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user hillt5 overridding Payment Estimate Exception 54 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0048) due to user hillt5 overridding Payment Estimate Item Adjustment (0048) due to user hillt5 overridding Payment
		REPAIR			18 19 19 20 20 21	2021 Apr 2, 2021 Apr 16, 2021 Apr 16, 2021 May 3, 2021 May 3, 2021 May 17, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$33,654.00) \$73,628.00 (\$73,628.00) \$131,140.00 (\$131,140.00) \$165,742.00	Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment Estimate Exception 39 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user kloepj1 overridding Payment Estimate Exception 40 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user hillt5 overridding Payment Estimate Exception 54 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0048) due to user hillt5 overridding Payment Estimate Item Adjustment (0048) due to user hillt5 overridding Payment
		REPAIR			18 19 19 20 20 21 21	2021 Apr 2, 2021 Apr 16, 2021 Apr 16, 2021 May 3, 2021 May 3, 2021 May 17, 2021 Jun 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$33,654.00) \$73,628.00 (\$73,628.00) \$131,140.00 (\$131,140.00) \$165,742.00	Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment Estimate Exception 39 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user kloepj1 overridding Payment Estimate Exception 40 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user hillt5 overridding Payment Estimate Exception 54 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0048) due to user hillt5 overridding Payment Estimate Exception 74 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 74 on the current Payment Estimate.
		REPAIR			18 19 19 20 20 21 21 22	2021 Apr 2, 2021 Apr 16, 2021 Apr 16, 2021 Apr 16, 2021 May 3, 2021 May 17, 2021 Jun 2, 2021 Jun 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$33,654.00) \$73,628.00 (\$73,628.00) \$131,140.00 (\$131,140.00) \$165,742.00 (\$165,742.00) \$234,314.00	Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment Estimate Exception 39 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user kloepj1 overridding Payment Estimate Exception 40 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user hillt5 overridding Payment Estimate Exception 54 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0048) due to user hillt5 overridding Payment Estimate Exception 74 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 74 on the current Payment Estimate.
		REPAIR			18 19 19 20 20 21 21 22 22	2021 Apr 2, 2021 Apr 16, 2021 Apr 16, 2021 Apr 16, 2021 May 3, 2021 May 17, 2021 Jun 2, 2021 Jun 2, 2021 Jun 16,	SYSTEM	(\$33,654.00) \$73,628.00 (\$73,628.00) \$131,140.00 (\$131,140.00) \$165,742.00 (\$165,742.00) \$234,314.00	Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment Estimate Exception 39 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user kloepj1 overridding Payment Estimate Exception 40 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user hillt5 overridding Payment Estimate Exception 54 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0048) due to user hillt5 overridding Payment Estimate Exception 74 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user hillt5 overridding Payment Estimate Exception 86 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 86 on the current Payment Estimate.
		REPAIR			18 19 19 20 20 21 21 22 22 23	2021 Apr 2, 2021 Apr 16, 2021 Apr 16, 2021 Apr 16, 2021 May 3, 2021 May 17, 2021 Jun 2, 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021	SYSTEM	(\$33,654.00) \$73,628.00 (\$73,628.00) \$131,140.00 (\$131,140.00) \$165,742.00 (\$165,742.00) \$234,314.00 (\$234,314.00) \$234,314.00	Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment Estimate Exception 39 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user kloepj1 overridding Payment Estimate Exception 40 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user hillt5 overridding Payment Estimate Exception 54 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0048) due to user hillt5 overridding Payment Estimate Exception 74 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user hillt5 overridding Payment Estimate Exception 86 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 86 on the current Payment Estimate.



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks														
			Туре	Adjustment Type	Number	Date	Ву																
J6I2222	2810	SUPERSTRUCTURE REPAIR (UNFORMED)	Material		25	Jul 16, 2021	SYSTEM	\$234,314.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0054) due to user kloepj1 overridding Payment Estimate Exception 48 on the current Payment Estimate.														
					25	Jul 16, 2021	SYSTEM	(\$234,314.00)															
				- Total				\$0.00															
			Material - Tot	al				\$0.00															
	2810 -	Total						\$0.00															
	2940	MECHANICALLY STABILIZED EARTH WALL SYS	Material		8	Nov 2, 2020	SYSTEM	\$81,250.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user hillt5 overridding Payment Estimate Exception 22 on the current Payment Estimate.														
					8	Nov 2, 2020	SYSTEM	(\$81,250.00)															
					9	Nov 16, 2020	SYSTEM	\$352,312.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user hillt5 overridding Payment Estimate Exception 22 on the current Payment Estimate.														
					9	Nov 16, 2020	SYSTEM	(\$352,312.50)															
					10	Dec 2, 2020	SYSTEM	\$514,875.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.														
														10	Dec 2, 2020	SYSTEM	(\$514,875.00)						
																			11	Dec 16, 2020	SYSTEM	\$514,875.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user schlag1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
						11	Dec 16, 2020	SYSTEM	(\$514,875.00)														
							12	Jan 4, 2021	SYSTEM	\$542,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 24 on the current Payment Estimate.												
										12	Jan 4, 2021	SYSTEM	(\$542,000.00)										
						13	Jan 19, 2021	SYSTEM	\$542,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schlag1 overridding Payment Estimate Exception 22 on the current Payment Estimate.													
									13	Jan 19, 2021	SYSTEM	(\$542,000.00)											
					14	Feb 2, 2021	SYSTEM	\$542,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user hillt5 overridding Payment Estimate Exception 50 on the current Payment Estimate.														
					14	Feb 2, 2021	SYSTEM	(\$542,000.00)															
					15	Feb 16, 2021	SYSTEM	\$542,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schlag1 overridding Payment Estimate Exception 50 on the current Payment Estimate.														
																			15	Feb 16, 2021	SYSTEM	(\$542,000.00)	
																		16	Mar 2, 2021	SYSTEM	\$542,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment Estimate Exception 49 on the current Payment Estimate.	
																16	Mar 2, 2021	SYSTEM	(\$542,000.00)				
					17	Mar 16, 2021	SYSTEM	(\$542,000.00)															
					18	Apr 2, 2021	SYSTEM	\$542,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment Estimate Exception 44 on the current Payment Estimate.														
					18	Apr 2, 2021	SYSTEM	(\$542,000.00)															
					19	Apr 16, 2021	SYSTEM	\$542,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user kloepj1 overridding Payment Estimate Exception 48 on the current Payment Estimate.														
					19	Apr 16,	SYSTEM	(\$542,000.00)	, · · · · · · · · · · · · · · · · · · ·														



Type Adjustment Number Date By Type	Remarks
J6I2222 2940 MECHANICALLY Material 2021	
STABILIZED EARTH WALL SYS 20 May 3, 2021 SYSTEM \$542,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user hillt5 overridding Payment Estimate Exception 73 on the current Payment Estimate.
20 May 3, SYSTEM (\$542,000.00) 2021	
21 May 17, SYSTEM \$542,000.00 2021	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0049) due to user hillt5 overridding Payment Estimate Exception 93 on the current Payment Estimate.
21 May 17, SYSTEM (\$542,000.00)	
22 Jun 2, 2021 SYSTEM \$542,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user hillt5 overridding Payment Estimate Exception 103 on the current Payment Estimate.
22 Jun 2, SYSTEM (\$542,000.00) 2021	
23 Jun 16, 2021 SYSTEM \$542,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0054) due to user kloepj1 overridding Payment Estimate Exception 103 on the current Payment Estimate.
23 Jun 16, SYSTEM (\$542,000.00) 2021	
24 Jul 1, SYSTEM \$542,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user herrmt1 overridding Payment Estimate Exception 65 on the current Payment Estimate.
24 Jul 1, SYSTEM (\$542,000.00)	
25 Jul 16, SYSTEM \$542,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0055) due to user kloepj1 overridding Payment Estimate Exception 57 on the current Payment Estimate.
25 Jul 16, SYSTEM (\$542,000.00) 2021	
- Total \$0.00	
Material - Total \$0.00	
2940 - Total \$0.00	
2940 - Total \$0.00 2960 MISC. FENCING Construction 21 May 17, 2021 SYSTEM (\$16,591.23)	Payment Estimate Item Adjustment generated Stockpile Transaction
2960 MISC. FENCING Construction 21 May 17, SYSTEM (\$16,591.23)	Payment Estimate Item Adjustment generated Stockpile Transaction
2960 MISC. FENCING Stockpile Construction Stockpile 21 May 17, 2021 SYSTEM (\$16,591.23)	Payment Estimate Item Adjustment generated Stockpile Transaction
2960 MISC. FENCING Construction Stockpile 21 May 17, 2021 SYSTEM (\$16,591.23) - Total (\$16,591.23)	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
2960 MISC. FENCING Construction Stockpile 21 May 17, 2021 SYSTEM (\$16,591.23) - Total (\$16,591.23)	
2960 MISC. FENCING Construction Stockpile 21 May 17, 2021 (\$16,591.23) - Total (\$16,591.23) Construction Stockpile - Total (\$16,591.23) Construction Stockpile 4 Sep 2, 2020 SYSTEM \$16,591.23 STMI STMI SYSTEM (\$16,591.23) SYSTEM \$16,591.23 STMI STMI SYSTEM (\$16,591.23) SYSTEM STMI STMI STMI SYSTEM STMI STMI SYSTEM STMI STMI STMI SYSTEM STMI STMI STMI STMI SYSTEM STMI STMI STMI SYSTEM STMI STMI STMI SYSTEM STMI STMI SYSTEM STMI STMI SYSTEM STMI STMI STMI SYSTEM STMI STMI SYSTEM STMI ST	
2960 MISC. FENCING Construction 21 May 17, SYSTEM (\$16,591.23)	
MISC. FENCING Construction Stockpile 21 May 17, 2021 SYSTEM (\$16,591.23) - Total (\$16,591.23)	
2960 MISC. FENCING Construction Stockpile 21 May 17, 2021 (\$16,591.23)	Payment Estimate Item Adjustment generated Stockpile Transaction This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0056) due to user kloepj1 overridding Payment
2960 MISC. FENCING Construction Stockpile - Total - Total (\$16,591.23)	Payment Estimate Item Adjustment generated Stockpile Transaction This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0056) due to user kloepj1 overridding Payment
MISC. FENCING Construction Stockpile 21 May 17, 2021 (\$16,591.23)	Payment Estimate Item Adjustment generated Stockpile Transaction This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0056) due to user kloepj1 overridding Payment
MISC. FENCING Construction Stockpile - Total - Total (\$16,591.23) (\$16,591.23) - Total (\$16,591.23) (\$16,591.23) (\$16,591.23) - Total (\$16,591.23) (\$16,591.23) - Total - Tota	Payment Estimate Item Adjustment generated Stockpile Transaction This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0056) due to user kloepj1 overridding Payment
MISC. FENCING Construction Stockpile -Total (\$16,591.23)	Payment Estimate Item Adjustment generated Stockpile Transaction This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0056) due to user kloepj1 overridding Payment
2960 MISC. FENCING Construction Stockpile 21 May 17, 2021 SYSTEM (\$16,591.23)	Payment Estimate Item Adjustment generated Stockpile Transaction This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0056) due to user kloepj1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
MISC. FENCING Construction Stockpile STM S	Payment Estimate Item Adjustment generated Stockpile Transaction This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0056) due to user kloepj1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
MISC. FENCING Construction Stockpile -Total (\$16,591.23)	Payment Estimate Item Adjustment generated Stockpile Transaction This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0056) due to user kloepj1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
MISC. FENCING Construction Stockpile STMI Construction Stockpile STMI State Sta	Payment Estimate Item Adjustment generated Stockpile Transaction This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0056) due to user kloepj1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
2960 MISC. FENCING Construction Stockpile Construction Stockpile -Total (\$16,591.23)	Payment Estimate Item Adjustment generated Stockpile Transaction This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0056) due to user kloepj1 overridding Payment Estimate Exception 34 on the current Payment Estimate. Payment Estimate Item Adjustment generated Stockpile Transaction This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user hillto overridding Payment



Material	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																						
22	J6I2222	3180		Material						Estimate Exception 42 on the current Payment Estimate.																						
2021 Estimate Rem Adjustment (COZS) due to user keps) overwiding Payment			F1. 6 IN. DIA.)			22		SYSTEM	(\$12,495.00)																							
2						23		SYSTEM	\$12,495.00	Estimate Item Adjustment (0025) due to user kloepj1 overridding Payment																						
201						23		SYSTEM	(\$12,495.00)	ZOSINIAO ZIJOOPION TO ON ATO GANDAN T GYNIAM ZOSINIAO.																						
2021 27 27 27 27 27 27 27						24		SYSTEM	\$12,495.00	Estimate Item Adjustment (0023) due to user herrmt1 overridding Payment																						
2021 System State Stat						24		SYSTEM	(\$12,495.00)																							
Total SySTEM S12,495.00 SySTEM S12,495.00 SySTEM S24,450.00 SySTEM SySTEM S24,450.00 SySTEM SySTE						25		SYSTEM	\$12,495.00	Estimate Item Adjustment (0030) due to user kloepj1 overridding Payment																						
Total						25		SYSTEM	(\$12,495.00)																							
Store Stor					- Total		2021		\$0.00																							
1900 ROCK SOCKETS (3 FT 0 IN DIA) Material 21 May 17, SYSTEM \$24,450.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 40 on the current Payment Estimate Exception 50 on the current Payme				Material - Tot																												
PT 0 IN DIA		3180 -	Total						\$0.00																							
22		3190		Material		21		SYSTEM	\$24,450.00	Estimate Item Adjustment (0029) due to user hillt5 overridding Payment																						
2021 Estimate Item Adjustment (0028) due to user hills overridding Payment						21		SYSTEM	(\$24,450.00)																							
2021 23						22		SYSTEM	\$24,450.00	Estimate Item Adjustment (0028) due to user hillt5 overridding Payment																						
2021 Estimate tem Adjustment (0026) due to user kloepij overridding Payment Estimate Exception 57 on the current Payment Estimate.							22		SYSTEM	(\$24,450.00)																						
2021 24 Jul 1, 27 27 27 27 27 27 27 2						23		SYSTEM	\$24,450.00	Estimate Item Adjustment (0026) due to user kloepj1 overridding Payment																						
2021 Estimate Item Adjustment (0024) due to user hermr1 overridding Payment Estimate Exception 31 on the current Payment Estimate.						23		SYSTEM	(\$24,450.00)																							
2021 25						24		SYSTEM	\$24,450.00	Estimate Item Adjustment (0024) due to user herrmt1 overridding Payment																						
25 Jul 16, 2021 \$YSTEM \$24,450.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user kloepj1 overridding Payment Estimate Exception 30 on the current Payment Estimate. 25 Jul 16, 2021 \$0.00 Naterial - Total						24		SYSTEM	(\$24,450.00)																							
25						25	Jul 16,	SYSTEM	\$24,450.00	Estimate Item Adjustment (0031) due to user kloepj1 overridding Payment																						
Total \$0.00						25		SYSTEM	(\$24,450.00)	Estimate Exception so on the current rayment Estimate.																						
\$0.00 CLASS B CONCRETE (SUBSTRUCTURE) Description: CLASS B CONCRETE (SUBSTRUCTURE) Description: CONCRETE (SUBSTRUCTURE) Description: De					- Total		2021		\$0.00																							
CLASS B CONCRETE (SUBSTRUCTURE) Material 20				Material - Tot	tal				\$0.00																							
CONCRETE (SUBSTRUCTURE) 2021 2021 Estimate Item Adjustment (0020) due to user hillt5 overridding Payment Estimate Exception 32 on the current Payment Estimate. 20 May 3, 2021 21 May 17, 2021 21 May 17, 2021 22 May 17, SYSTEM (\$19,840.00) 23 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user hillt5 overridding Payment Estimate Exception 52 on the current Payment Estimate. 21 May 17, 2021 22 Jun 2, SYSTEM (\$19,840.00) This adjustment offsets the original system-generated Material Payment		3190 -	Total						\$0.00																							
2021 May 17, 2021 SYSTEM (\$19,840.00) 21		3270	CONCRETE	Material		20		SYSTEM	\$19,840.00	Estimate Item Adjustment (0020) due to user hillt5 overridding Payment																						
2021 Estimate Item Adjustment (0030) dué to user hillt5 overridding Payment Estimate Exception 52 on the current Payment Estimate. 21 May 17, 2021 (\$19,840.00) 22 Jun 2, SYSTEM \$19,840.00 This adjustment offsets the original system-generated Material Payment																									2	2	2	20		SYSTEM	(\$19,840.00)	
2021 22 Jun 2, SYSTEM \$19,840.00 This adjustment offsets the original system-generated Material Payment						21		SYSTEM	\$19,840.00	Estimate Item Adjustment (0030) due to user hillt5 overridding Payment																						
						21		SYSTEM	(\$19,840.00)																							
2021 Estimate Item Adjustment (0029) due to user hillt5 overridding Payment Estimate Exception 64 on the current Payment Estimate.						2					2	2		2			:	2	22	Jun 2, 2021	SYSTEM	\$19,840.00	Estimate Item Adjustment (0029) due to user hillt5 overridding Payment									
22 Jun 2, 2021 (\$19,840.00)						22	22		SYSTEM	(\$19,840.00)																						
23 Jun 16, SYSTEM \$19,840.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user kloepj1 overridding Payment						23		SYSTEM	\$19,840.00																							



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks															
			Туре	Adjustment Type	Number	Date	Ву																	
J6I2222	3270	CLASS B CONCRETE	Material						Estimate Exception 67 on the current Payment Estimate.															
		(SUBSTRUCTURE)			23	Jun 16, 2021	SYSTEM	(\$19,840.00)																
				- Total				\$0.00																
			Material - Tot	tal				\$0.00																
	3270 -	Total						\$0.00																
	3280	CLASS B-1 CONCRETE (SUBSTR)	Material		24	Jul 1, 2021	SYSTEM	\$63,616.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user herrmt1 overridding Payment Estimate Exception 37 on the current Payment Estimate.															
					24	Jul 1, 2021	SYSTEM	(\$63,616.50)																
					25	Jul 16, 2021	SYSTEM	\$63,616.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user kloepj1 overridding Payment Estimate Exception 35 on the current Payment Estimate.															
					25	Jul 16, 2021	SYSTEM	(\$63,616.50)																
				- Total				\$0.00																
			Material - Tot	tal				\$0.00																
	3280 -	Total						\$0.00																
	3370	FAB. SIGN SUPPORT	Construction Stockpile		19	Apr 16, 2021	SYSTEM	\$14,500.00	Payment Estimate Item Adjustment generated Stockpile Transaction															
		BRACKETS	STMI	- Total				\$14,500.00																
				Construction Stockpile STMI - Total				\$14,500.00																
	3370 -	Total	CONSTRUCTION						\$14,500.00															
	3400	PIPE PILE SPACERS	Material		18	Apr 2, 2021	SYSTEM	\$11,970.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 49 on the current Payment Estimate.															
								18	Apr 2, 2021	SYSTEM	(\$11,970.00)													
					19	Apr 16, 2021	SYSTEM	\$11,970.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 57 on the current Payment Estimate.															
					19	Apr 16, 2021	SYSTEM	(\$11,970.00)																
					20	May 3, 2021	SYSTEM	\$11,970.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hillto overridding Payment Estimate Exception 82 on the current Payment Estimate.															
					20	May 3, 2021	SYSTEM	(\$11,970.00)																
					21	May 17, 2021	SYSTEM	\$11,970.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user hillt5 overridding Payment Estimate Exception 102 on the current Payment Estimate.															
					:	:								:	21	May 17, 2021	SYSTEM	(\$11,970.00)						
					22	Jun 2, 2021	SYSTEM	\$11,970.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user hillt5 overridding Payment Estimate Exception 112 on the current Payment Estimate.															
													22	Jun 2, 2021	SYSTEM	(\$11,970.00)								
			2	23		23								2	2	2		2	2		23	23	23	23
					23	Jun 16, 2021	SYSTEM	(\$11,970.00)																
					24	Jul 1, 2021	SYSTEM	\$11,970.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user herrmt1 overridding Payment Estimate Exception 73 on the current Payment Estimate.															
					24	Jul 1, 2021	SYSTEM	(\$11,970.00)																
					25	Jul 16, 2021	SYSTEM	\$11,970.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user kloepj1 overridding Payment Estimate Exception 65 on the current Payment Estimate.															
					25	Jul 16, 2021	SYSTEM	(\$11,970.00)																



Material Folia September September Material Folia September	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks										
Material Total	J6I2222	3400																		
19				Material - To	tal															
STABLIZED LARTH								a) (==												
201		3430	STABILIZED EARTH	Material		19		SYSTEM	\$66,880.00	Estimate Item Adjustment (0029) due to user kloepj1 overridding Payment										
2021 2021 349 34						19		SYSTEM	(\$66,880.00)											
201						20		SYSTEM	\$66,880.00	Estimate Item Adjustment (0034) due to user hillt5 overridding Payment										
2011						20		SYSTEM	(\$66,880.00)											
22						21		SYSTEM	\$66,880.00	Estimate Item Adjustment (0051) due to user hillt5 overridding Payment										
2021 SYSTEM G86,880.00 2021 22 Jun 2, 2021 23 Jun 16, 2021 23 Jun 16, 2021 24 Jun 17, 2021 25 Jun 18, 2021 25 Jun						21		SYSTEM	(\$66,880.00)											
23						22		SYSTEM	\$66,880.00	Estimate Item Adjustment (0046) due to user hillt5 overridding Payment										
2021 Estimate Item Agustment (0565) due to user kneep! overridding Payment Estimate Estimate Exception 150 on the current Payment Estimate						22		SYSTEM	(\$66,880.00)											
2021						23		SYSTEM	\$66,880.00	Estimate Item Adjustment (0055) due to user kloepj1 overridding Payment										
2021 SYSTEM S66,880.00 25 Jul 16, 2021 SYSTEM S66,880.00 26 Jul 16, 2021 SYSTEM S66,880.00 27 28 Jul 16, 2021 SYSTEM S66,880.00 27 28 Jul 16, 2021 SYSTEM S66,880.00 Stimute Exception 59 on the current Payment Estimate Exception 59 on the current Payment Estimate Exception 59 on the current Payment Estimate Extended Material Payment Stimute Exception 59 on the current Payment Estimate Extended Estimate Exception 59 on the current Payment Estimate Extended Estimate Exception 59 on the current Payment Estimate Estimate Extended Estimate Exception 59 on the current Payment Estimate Estimate Estimate Extended Extended Extended Extended Extended Extended Extended Estimate Extended Ex						23		SYSTEM	(\$66,880.00)											
2021 25						24		SYSTEM	\$66,880.00	Estimate Item Adjustment (0045) due to user herrmt1 overridding Payment										
2021 Estimate Item Adjustment (0057) due to user kloep]1 overridding Payment Estimate Estimate Exception 59 on the current Payment Estimate.						24		SYSTEM	(\$66,880.00)											
3430 - Total 30.00 3430 - Total 30.00 3430 - Total 3450 MECHANICALLY STABILIZED EARTH WALL SYS 18						25		SYSTEM	\$66,880.00	Estimate Item Adjustment (0057) due to user kloepj1 overridding Payment										
Substitute						25		SYSTEM	(\$66,880.00)											
Succession Suc					- Total				\$0.00											
MECHANICALLY STABILIZED EARTH WALL SYS Material STABILIZED EARTH WALL SYS MECHANICALLY STABILIZED EARTH WALL SYS Material Payment Estimate Exception 53 on the current Payment Estimate Exception 78 on the current Payment Estimate Estimate Item Adjustment (0036) due to user hillfs overridding Payment Estimate Exception 78 on the current Payment Estimate Estimate Exception 78 on the current Payment Estimate Estimate Exception 78 on the current Payment Estimate Estimate Exception 98 on the current Payment Estimate Estimate Exception 98 on the current Payment Estimate Estimate Exception 98 on the current Payment Estimate Estimate Exception 109 on the current Payment Estimate Estimate Estimate Exception 109 on the current Payment Estimate. 20				Material - Total					\$0.00											
STABILIZED EARTH WALL SYS 18		3430 -	Total						\$0.00											
2021 SYSTEM \$181,520.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 53 on the current Payment Estimate Exception 53 on the current Payment Estimate. 19 Apr 16, 2021 \$YSTEM (\$181,520.00) 20 May 3, 2021 SYSTEM \$181,520.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user hillfs overridding Payment Estimate Exception 78 on the current Payment Estimate. 20 May 3, 2021 SYSTEM (\$181,520.00) 21 May 17, 2021 SYSTEM \$181,520.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0052) due to user hillfs overridding Payment Estimate Exception 98 on the current Payment Estimate. 21 May 17, 2021 SYSTEM (\$181,520.00) 22 Jun 2, SYSTEM \$181,520.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 98 on the current Payment Estimate. 22 Jun 2, SYSTEM \$181,520.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user hillfs overridding Payment Estimate Item Adjustment (0047) due to user hillfs overridding Payment Estimate Exception 109 on the current Payment Estimate.		3450	STABILIZED EARTH	Material		18		SYSTEM	\$50,400.00	Estimate Item Adjustment (0024) due to user kloepj1 overridding Payment										
Estimate Item Adjustment (0030) due to user kloepj1 overridding Payment Estimate Exception 53 on the current Payment Estimate. 19					18	18		SYSTEM	(\$50,400.00)											
20 May 3, 2021 SYSTEM \$181,520.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user hillt5 overridding Payment Estimate Exception 78 on the current Payment Estimate. 20 May 3, 2021 SYSTEM (\$181,520.00) 21 May 17, 2021 SYSTEM \$181,520.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0052) due to user hillt5 overridding Payment Estimate Exception 98 on the current Payment Estimate. 21 May 17, 2021 SYSTEM (\$181,520.00) 22 Jun 2, 2021 This adjustment offsets the original system-generated Material Payment Estimate Exception 98 on the current Payment Estimate. 23 Jun 2, 2021 SYSTEM (\$181,520.00) This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user hillt5 overridding Payment Estimate Exception 109 on the current Payment Estimate.							1	19	19							19		SYSTEM	\$181,520.00	Estimate Item Adjustment (0030) due to user kloepj1 overridding Payment
Estimate Item Adjustment (0035) due to user hillt5 overridding Payment Estimate Exception 78 on the current Payment Estimate. 20 May 3, 2021 21 May 17, 2021 22 Jun 2, 2021 SYSTEM \$181,520.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0052) due to user hillt5 overridding Payment Estimate Exception 98 on the current Payment Estimate. 21 May 17, 2021 SYSTEM \$181,520.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user hillt5 overridding Payment Estimate Exception 109 on the current Payment Estimate. 22 Jun 2, SYSTEM (\$181,520.00)										19		SYSTEM	(\$181,520.00)							
2021 May 17, 2021 SYSTEM \$181,520.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0052) due to user hillt5 overridding Payment Estimate Exception 98 on the current Payment Estimate. May 17, 2021 SYSTEM (\$181,520.00) 22 Jun 2, 2021 SYSTEM \$181,520.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user hillt5 overridding Payment Estimate Exception 109 on the current Payment Estimate. 23 Jun 2, SYSTEM (\$181,520.00)																				20
2021 Estimate Item Adjustment (0052) due to user hillt5 overridding Payment Estimate Exception 98 on the current Payment Estimate. 21 May 17, 2021 (\$181,520.00) 22 Jun 2, 2021 \$YSTEM \$181,520.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user hillt5 overridding Payment Estimate Exception 109 on the current Payment Estimate. 22 Jun 2, \$YSTEM (\$181,520.00)						20		SYSTEM	(\$181,520.00)											
2021 22 Jun 2, 2021 \$181,520.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user hillt5 overridding Payment Estimate Exception 109 on the current Payment Estimate. 22 Jun 2, SYSTEM (\$181,520.00)						21		SYSTEM	\$181,520.00	Estimate Item Adjustment (0052) due to user hillt5 overridding Payment										
2021 Estimate Item Adjustment (0047) due to user hillt5 overridding Payment Estimate Exception 109 on the current Payment Estimate. 22 Jun 2, SYSTEM (\$181,520.00)						21		SYSTEM	(\$181,520.00)											
					22	22		SYSTEM	\$181,520.00	Estimate Item Adjustment (0047) due to user hillt5 overridding Payment										
2021						22	Jun 2, 2021	SYSTEM	(\$181,520.00)											



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																																				
J6I2222	3450	MECHANICALLY STABILIZED EARTH WALL SYS	Material		23	Jun 16, 2021	SYSTEM	\$181,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0056) due to user kloepj1 overridding Payment Estimate Exception 108 on the current Payment Estimate.																																				
					23	Jun 16, 2021	SYSTEM	(\$181,520.00)																																					
					24	Jul 1, 2021	SYSTEM	\$181,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user herrmt1 overridding Payment Estimate Exception 70 on the current Payment Estimate.																																				
					24	Jul 1, 2021	SYSTEM	(\$181,520.00)																																					
					25	Jul 16, 2021	SYSTEM	\$181,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user kloepj1 overridding Payment Estimate Exception 62 on the current Payment Estimate.																																				
					25	Jul 16, 2021	SYSTEM	(\$181,520.00)																																					
				- Total				\$0.00																																					
			Material - To	tal				\$0.00																																					
	3450 -							\$0.00																																					
	3480	DRILLED SHAFTS (6 FT. 0 IN. DIA.)	Material		22	Jun 2, 2021	SYSTEM	\$25,409.15	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0048) due to user hillt5 overridding Payment Estimate Exception 49 on the current Payment Estimate.																																				
					22	Jun 2, 2021	SYSTEM	(\$25,409.15)																																					
					23	Jun 16, 2021	SYSTEM	\$89,157.55	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0057) due to user kloepj1 overridding Payment Estimate Exception 52 on the current Payment Estimate.																																				
					23	Jun 16, 2021	SYSTEM	(\$89,157.55)																																					
					24	Jul 1, 2021	SYSTEM	\$89,157.55	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user herrmt1 overridding Payment Estimate Exception 28 on the current Payment Estimate.																																				
					24	Jul 1, 2021	SYSTEM	(\$89,157.55)																																					
						25	Jul 16, 2021	SYSTEM	\$119,387.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0059) due to user kloepj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.																																			
					25	Jul 16, 2021	SYSTEM	(\$119,387.60)																																					
				- Total				\$0.00																																					
			Material - To	tal				\$0.00																																					
	3480 -	Total						\$0.00																																					
	3490	ROCK SOCKETS (5 FT 6 IN. DIA.)	Material		22	Jun 2, 2021	SYSTEM	\$95,378.15	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0049) due to user hillt5 overridding Payment Estimate Exception 59 on the current Payment Estimate.																																				
					22	Jun 2, 2021	SYSTEM	(\$95,378.15)																																					
																														23	23	Jun 16, 2021	SYSTEM	\$214,006.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user kloepj1 overridding Payment Estimate Exception 62 on the current Payment Estimate.										
					23	Jun 16, 2021	SYSTEM	(\$214,006.80)																																					
																										2															24	Jul 1, 2021	SYSTEM	\$214,006.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0048) due to user herrmt1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$214,006.80)																																					
					25	Jul 16, 2021	SYSTEM	\$275,940.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user kloepj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.																																				
					25	Jul 16, 2021	SYSTEM	(\$275,940.00)																																					
				- Total				\$0.00																																					
			Material - To	tal				\$0.00																																					
	3490 -	Total						\$0.00																																					
	3630	REINFORCING	Material		22	Jun 2,	SYSTEM	\$26,851.50	This adjustment offsets the original system-generated Material Payment																																				



Project 1940						1																			
Settonate Exception 34 on the current Programs Extranate.	Project	Line	Description		Adjustment				Amount	Remarks															
201	J6I2222	3630	STEEL (BRIDGES)	Material			2021																		
201 201						22		SYSTEM	(\$26,851.50)																
20						23		SYSTEM	\$84,192.50	Estimate Item Adjustment (0059) due to user kloepj1 overridding Payment															
24 Jul 1 SYSTEM 884,192.07 This adjustment offsee the original system-generated Material Payment Estimate Examples in Control of the Control of Statistical Payment Estimate Examples in Control of Statistical Payment Estimate Intern Adjustment generated Stadistical Transaction Statistical Payment International Payment Internat						23	Jun 16,	SYSTEM	(\$84,192.50)	Estimate Exception 95 on the current Payment Estimate.															
2021 24 24 24 25 25 25 25 25							2021																		
STRUCTURAL Social Social STRUCTURAL Social Social STRUCTURAL Social Social STRUCTURAL Social						24		SYSTEM	\$84,192.50	Estimate Item Adjustment (0049) due to user herrmt1 overridding Payment															
Sabo						24		SYSTEM	(\$84,192.50)																
Strict Strict Strict Stockpile Total					- Total				\$0.00																
STRUCINEAL SIGNAL Construction Stockpile STM - Total				Material - Tot	tal				\$0.00																
April September Septembe		3630 -	Total						\$0.00																
CONSTRUCTION Total			MISC. STRUCTURAL	Stockpile		14		SYSTEM		Payment Estimate Item Adjustment generated Stockpile Transaction															
STRIP SEAL				STIVII	- Total				\$26,016.00																
Sample				Construction	Stockpile S	TMI - Tota			\$26,016.00																
Sample		3760 -	Total						\$26,016.00																
Total S5,844.00 S5,844.00 S5		3830	EXPANSION JOINT	Stockpile		14		SYSTEM		Payment Estimate Item Adjustment generated Stockpile Transaction															
State			SYSTEM	STMI	- Total				\$5,54 <u>4.00</u>																
Signature Sign				Construction	Stockpile S	TMI - Tota	ı		\$5,544.00																
Misc. ITS Construction Slockpile Total S75,000.00 Payment Estimate Item Adjustment generated Stockpile Transaction S100,000 S75,000.00 S75,000.		3830 -	Total		Polistruction Stockpile STWI - Total																				
				Stockpile		20		SYSTEM		Payment Estimate Item Adjustment generated Stockpile Transaction															
SOOR MISC. DRAINAGE FITTINGS Material 19				SIMI	- Total				\$75,000.00																
MISC. DRAINAGE FITTINGS Material FITTINGS May 3, 2021 SYSTEM (\$400.00)				Construction	n Stockpile STMI - Total				\$75,000.00																
PITTINGS 2021 Estimate Item Adjustment (0031) due to user kloep]1 overridding Payment Estimate Exception 16 on the current Payment Estimate.		5007 -	Total						\$75,000.00																
201 May 3, 2021 20 May 3, 2021 20 May 3, 2021 21 May 17, 2021 21 May 17, 278TEM (\$400.00) 21 May 17, 2021 22 Jun 2, 2021 23 Jun 16, 2021 24 Jun 16, SYSTEM (\$400.00) 25 Juh 16, SYSTEM (\$400.00) 26 Juh 16, SYSTEM (\$400.00) 27 This adjustment offsets the original system-generated Material Payment Estimate Exception 32 on the current Payment Estimate. 29 Jun 16, SYSTEM (\$400.00) 2021 2021 2021 2021 2021 2021 2021 2		5008	MISC. DRAINAGE	Material		19		SYSTEM	\$400.00	Estimate Item Adjustment (0031) due to user kloepj1 overridding Payment															
Estimate Exception 18 on the current Payment Estimate. 20 May 3, 2021 21 May 17, 2021 22 May 17, 2021 23 Jun 2, 2021 24 Jun 16, 2021 25 Jun 16, SYSTEM 2021 26 SYSTEM 27 SYSTEM 28 SYSTEM 28 SYSTEM 29 SYSTEM 29 SYSTEM 20 SYSTEM 30 SYSTEM 3						19		SYSTEM	(\$400.00)																
2021 SYSTEM \$400.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0053) due to user hillt5 overridding Payment Estimate Exception 32 on the current Payment Estimate. 21 May 17, 2021 SYSTEM (\$400.00) 22 Jun 2, 2021 SYSTEM \$400.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0051) due to user hillt5 overridding Payment Estimate Exception 35 on the current Payment Estimate. 22 Jun 2, 2021 SYSTEM (\$400.00) 23 Jun 16, 2021 SYSTEM \$400.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user kloep! overridding Payment Estimate Item Adjustment (0060) due to user kloep! overridding Payment Estimate Exception 38 on the current Payment Estimate. 23 Jun 16, SYSTEM (\$400.00) 24 Jul 1, SYSTEM \$400.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user hermit overridding Payment Estimate Item Adjustment (0050) due to user hermit overridding Payment Estimate Item Adjustment (0050) due to user hermit overridding Payment Estimate Item Adjustment (0050) due to user hermit overridding Payment Estimate Exception 21 on the current Payment Estimate. 24 Jul 1, SYSTEM (\$400.00) 25 Jul 16, SYSTEM \$400.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 21 on the current Payment Estimate.								20		SYSTEM	\$400.00	Estimate Item Adjustment (0037) due to user hillt5 overridding Payment													
Estimate Item Adjustment (0053) due to user hillt5 overridding Payment Estimate Exception 32 on the current Payment Estimate. 21 May 17, 2021 (\$400.00) 22 Jun 2, 2021 \$YSTEM \$400.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0051) due to user hillt5 overridding Payment Estimate Exception 35 on the current Payment Estimate. 22 Jun 2, 2021 \$YSTEM \$400.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user kloep)1 overridding Payment Estimate Item Adjustment (0060) due to user kloep)1 overridding Payment Estimate Exception 38 on the current Payment Estimate. 23 Jun 16, 2021 \$YSTEM \$400.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user herrm11 overridding Payment Estimate Item Adjustment (0050) due to user herrm11 overridding Payment Estimate Exception 21 on the current Payment Estimate. 24 Jul 1, 2021 \$YSTEM \$400.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 21 on the current Payment Estimate. 25 Jul 16, \$YSTEM \$400.00 This adjustment offsets the original system-generated Material Payment						20		SYSTEM	(\$400.00)																
22 Jun 2, 2021 SYSTEM \$400.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0051) due to user hillt5 overridding Payment Estimate Exception 35 on the current Payment Estimate. 22 Jun 2, 2021 SYSTEM (\$400.00) 23 Jun 16, 2021 SYSTEM \$400.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user kloep)1 overridding Payment Estimate Exception 38 on the current Payment Estimate. 23 Jun 16, SYSTEM (\$400.00) 24 Jul 1, SYSTEM \$400.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user herrint1 overridding Payment Estimate Item Adjustment (0050) due to user herrint1 overridding Payment Estimate Exception 21 on the current Payment Estimate. 24 Jul 1, SYSTEM (\$400.00) 25 Jul 16, SYSTEM \$400.00 This adjustment offsets the original system-generated Material Payment								21		SYSTEM	\$400.00	Estimate Item Adjustment (0053) due to user hillt5 overridding Payment													
Estimate Item Adjustment (0051) due to user hillt5 overridding Payment Estimate Exception 35 on the current Payment Estimate. 22																								21	
22 Jun 2, 2021 SYSTEM (\$400.00) 23 Jun 16, 2021 \$400.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user kloepj1 overridding Payment Estimate Exception 38 on the current Payment Estimate. 23 Jun 16, 2021 \$400.00 (\$400.00) 24 Jul 1, 2021 \$400.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user herrmt1 overridding Payment Estimate Exception 21 on the current Payment Estimate. 24 Jul 1, 2021 \$400.00 (\$400.00) 25 Jul 16, SYSTEM \$400.00 This adjustment offsets the original system-generated Material Payment						22		SYSTEM	\$400.00	Estimate Item Adjustment (0051) due to user hillt5 overridding Payment															
2021 Estimate Item Adjustment (0060) due to user kloepj1 overridding Payment Estimate Exception 38 on the current Payment Estimate. 23 Jun 16, 2021 (\$400.00) 24 Jul 1, 2021 \$400.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 21 on the current Payment Estimate. 24 Jul 1, 2021 \$400.00 (\$400.00) 25 Jul 16, SYSTEM \$400.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 21 on the current Payment Estimate.						22		SYSTEM	(\$400.00)																
2021 24 Jul 1, 2021 \$400.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user herrmt1 overridding Payment Estimate Exception 21 on the current Payment Estimate. 24 Jul 1, 2021 25 Jul 16, SYSTEM \$400.00 This adjustment offsets the original system-generated Material Payment						23		SYSTEM	\$400.00	Estimate Item Adjustment (0060) due to user kloepj1 overridding Payment															
2021 Estimate Item Adjustment (0050) due to user herrmt1 overridding Payment Estimate Exception 21 on the current Payment Estimate. 24 Jul 1, 2021 (\$400.00) 25 Jul 16, SYSTEM \$400.00 This adjustment offsets the original system-generated Material Payment						23		SYSTEM	(\$400.00)																
2021 25 Jul 16, SYSTEM \$400.00 This adjustment offsets the original system-generated Material Payment						24		SYSTEM	\$400.00	Estimate Item Adjustment (0050) due to user herrmt1 overridding Payment															
						24		SYSTEM	(\$400.00)																
						25		SYSTEM	\$400.00																



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks									
J6I2222	5008	MISC. DRAINAGE FITTINGS	Material						Estimate Exception 22 on the current Payment Estimate.									
		11111100			25	Jul 16, 2021	SYSTEM	(\$400.00)										
				- Total				\$0.00										
			Material - To	tal				\$0.00										
	5008 -	Total						\$0.00										
	5009	CLASS C EXCAVATION	Price FUEL		21	May 17, 2021	SYSTEM	\$154.54	Reference Item Price Adjustment Index Adjustment Type applied is FUEL									
				- Total				\$154.54										
			Price FUEL -	Total				\$154.54										
	5009 -							\$154.54										
	5011	REINFORCING STEEL (EPOXY COATED)	Material		22	Jun 2, 2021	SYSTEM	\$25,203.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0052) due to user hillt5 overridding Payment Estimate Exception 98 on the current Payment Estimate.									
					22	Jun 2, 2021	SYSTEM	(\$25,203.50)										
					23	Jun 16, 2021	SYSTEM	\$25,203.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0061) due to user kloepj1 overridding Payment Estimate Exception 98 on the current Payment Estimate.									
					23	Jun 16, 2021	SYSTEM	(\$25,203.50)										
					24	Jul 1, 2021	SYSTEM	\$25,203.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0051) due to user herrmt1 overridding Payment Estimate Exception 60 on the current Payment Estimate.									
					24	Jul 1, 2021	SYSTEM	(\$25,203.50)										
					25	Jul 16, 2021	SYSTEM	\$25,203.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0062) due to user kloepj1 overridding Payment Estimate Exception 54 on the current Payment Estimate.									
					25	Jul 16, 2021	SYSTEM	(\$25,203.50)										
				- Total				\$0.00										
			Material - To	tal				\$0.00										
	5011 -							\$0.00										
	5013	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	Material		14	Feb 2, 2021	SYSTEM	\$115,139.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user hillt5 overridding Payment Estimate Exception 19 on the current Payment Estimate.									
					14	Feb 2, 2021	SYSTEM	(\$115,139.70)										
					15	Feb 16, 2021	SYSTEM	\$115,139.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schlag1 overridding Payment Estimate Exception 27 on the current Payment Estimate.									
					15	Feb 16, 2021	SYSTEM	(\$115,139.70)										
													16	Mar 2, 2021	SYSTEM	\$115,139.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.	
						2021												
					17	2021 Mar 16, 2021	SYSTEM	\$115,139.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 23 on the current Payment Estimate.									
						Mar 16,		\$115,139.70 (\$115,139.70)	Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment									
					17	Mar 16, 2021 Mar 16,			Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment									
					17	Mar 16, 2021 Mar 16, 2021 Apr 2,	SYSTEM SYSTEM	(\$115,139.70)	Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user kloepj1 overridding Payment									
					17 17 18	Mar 16, 2021 Mar 16, 2021 Apr 2, 2021	SYSTEM SYSTEM	(\$115,139.70) \$115,139.70	Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user kloepj1 overridding Payment									



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	5013	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	Material	Туре	20	May 3, 2021	SYSTEM	\$115,139.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user hillt5 overridding Payment
		,			20	May 3,	SYSTEM	(\$115,139.70)	Estimate Exception 26 on the current Payment Estimate.
					21	2021 May 17,	SYSTEM	\$115,139.70	This adjustment offsets the original system-generated Material Payment
					04	2021	OVOTEM	(0445 400 70)	Estimate Item Adjustment (0055) due to user hillt5 overridding Payment Estimate Exception 43 on the current Payment Estimate.
					21	May 17, 2021		(\$115,139.70)	This allows the first hand and the state of
					22	Jun 2, 2021	SYSTEM	\$115,139.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0053) due to user hillt5 overridding Payment Estimate Exception 46 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$115,139.70)	
					23	Jun 16, 2021	SYSTEM	\$115,139.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0062) due to user kloepj1 overridding Payment Estimate Exception 49 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$115,139.70)	
					24	Jul 1, 2021	SYSTEM	\$115,139.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0052) due to user herrmt1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$115,139.70)	
					25	Jul 16, 2021	SYSTEM	\$115,139.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0063) due to user kloepj1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$115,139.70)	
				- Total				\$0.00	
	5042	- Total	Material - To	tal				\$0.00 \$0.00	
	5013 -	- 10tal							
	E014		Meterial		1.1	Fab 0	CVCTEM		This adjustment effects the asisinal system generated Material Daymont
	5014	ROCK SOCKETS (3 FT 0 IN. DIA.)	Material		14	Feb 2, 2021	SYSTEM	\$70,341.57	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user hillt5 overridding Payment Estimate Exception 26 on the current Payment Estimate.
	5014	ROCK SOCKETS (3	Material		14		SYSTEM		Estimate Item Adjustment (0025) due to user hillt5 overridding Payment
	5014	ROCK SOCKETS (3	Material			2021 Feb 2,		\$70,341.57	Estimate Item Adjustment (0025) due to user hillt5 overridding Payment
	5014	ROCK SOCKETS (3	Material		14	2021 Feb 2, 2021 Feb 16,	SYSTEM	\$70,341.57 (\$70,341.57)	Estimate Item Adjustment (0025) due to user hillt5 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schlag1 overridding Payment
	5014	ROCK SOCKETS (3	Material		14	2021 Feb 2, 2021 Feb 16, 2021	SYSTEM SYSTEM	\$70,341.57 (\$70,341.57) \$70,341.57	Estimate Item Adjustment (0025) due to user hillt5 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schlag1 overridding Payment
	5014	ROCK SOCKETS (3	Material		14 15	2021 Feb 2, 2021 Feb 16, 2021 Feb 16, 2021 Mar 2,	SYSTEM SYSTEM	\$70,341.57 (\$70,341.57) \$70,341.57 (\$70,341.57)	Estimate Item Adjustment (0025) due to user hillt5 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schlag1 overridding Payment Estimate Exception 34 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment
	5014	ROCK SOCKETS (3	Material		14 15 15	2021 Feb 2, 2021 Feb 16, 2021 Feb 16, 2021 Mar 2, 2021 Mar 2,	SYSTEM SYSTEM SYSTEM SYSTEM	\$70,341.57 (\$70,341.57) \$70,341.57 (\$70,341.57) \$70,341.57	Estimate Item Adjustment (0025) due to user hillt5 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schlag1 overridding Payment Estimate Exception 34 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment
	5014	ROCK SOCKETS (3	Material		14 15 15 16	2021 Feb 2, 2021 Feb 16, 2021 Feb 16, 2021 Mar 2, 2021 Mar 2, 2021 Mar 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$70,341.57 (\$70,341.57) \$70,341.57 (\$70,341.57) \$70,341.57	Estimate Item Adjustment (0025) due to user hillt5 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schlag1 overridding Payment Estimate Exception 34 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment Estimate Exception 33 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment
	5014	ROCK SOCKETS (3	Material		14 15 15 16 16 17	2021 Feb 2, 2021 Feb 16, 2021 Feb 16, 2021 Mar 2, 2021 Mar 16, 2021 Mar 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$70,341.57 (\$70,341.57) \$70,341.57 (\$70,341.57) \$70,341.57 (\$70,341.57) \$70,341.57	Estimate Item Adjustment (0025) due to user hillt5 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schlag1 overridding Payment Estimate Exception 34 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment Estimate Exception 33 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment
	5014	ROCK SOCKETS (3	Material		14 15 15 16 16 17 17	2021 Feb 2, 2021 Feb 16, 2021 Feb 16, 2021 Mar 2, 2021 Mar 16, 2021 Mar 16, 2021 Apr 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$70,341.57 (\$70,341.57) \$70,341.57 (\$70,341.57) \$70,341.57 (\$70,341.57) \$70,341.57	Estimate Item Adjustment (0025) due to user hillt5 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schlag1 overridding Payment Estimate Exception 34 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment Estimate Exception 33 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user kloepj1 overridding Payment Estimate Item Adjustment (0026) due to user kloepj1 overridding Payment
	5014	ROCK SOCKETS (3	Material		14 15 15 16 16 17 17 18	2021 Feb 2, 2021 Feb 16, 2021 Feb 16, 2021 Mar 2, 2021 Mar 16, 2021 Mar 16, 2021 Apr 2, 2021 Apr 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$70,341.57 (\$70,341.57) \$70,341.57 (\$70,341.57) \$70,341.57 (\$70,341.57) \$70,341.57 (\$70,341.57)	Estimate Item Adjustment (0025) due to user hillt5 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schlag1 overridding Payment Estimate Exception 34 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment Estimate Exception 33 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user kloepj1 overridding Payment Estimate Item Adjustment (0026) due to user kloepj1 overridding Payment
	5014	ROCK SOCKETS (3	Material		14	2021 Feb 2, 2021 Feb 16, 2021 Feb 16, 2021 Mar 2, 2021 Mar 16, 2021 Apr 2, 2021 Apr 16, 2021 Apr 16, 2021	SYSTEM	\$70,341.57 (\$70,341.57) \$70,341.57 (\$70,341.57) \$70,341.57 (\$70,341.57) \$70,341.57 (\$70,341.57) (\$70,341.57)	Estimate Item Adjustment (0025) due to user hillt5 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schlag1 overridding Payment Estimate Exception 34 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment Estimate Exception 33 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user kloepj1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user kloepj1 overridding Payment Estimate Item Adjustment (0033) due to user kloepj1 overridding Payment Estimate Item Adjustment (0033) due to user kloepj1 overridding Payment
	5014	ROCK SOCKETS (3	Material		14 15 15 16 16 17 17 18 18 19	2021 Feb 2, 2021 Feb 16, 2021 Feb 16, 2021 Mar 2, 2021 Mar 16, 2021 Mar 16, 2021 Apr 2, 2021 Apr 16, 2021 Apr 16, 2021	SYSTEM	\$70,341.57 (\$70,341.57) \$70,341.57 (\$70,341.57) \$70,341.57 (\$70,341.57) \$70,341.57 (\$70,341.57) \$70,341.57 (\$70,341.57)	Estimate Item Adjustment (0025) due to user hillt5 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schlag1 overridding Payment Estimate Exception 34 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment Estimate Exception 33 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user kloepj1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 27 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																													
J6I2222	5014	ROCK SOCKETS (3	Material			2021																																
		FT 0 IN. DIA.)			21	May 17, 2021	SYSTEM	\$70,341.57	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0056) due to user hillt5 overridding Payment Estimate Exception 49 on the current Payment Estimate.																													
					21	May 17, 2021	SYSTEM	(\$70,341.57)																														
					22	Jun 2, 2021	SYSTEM	\$70,341.57	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0054) due to user hillt5 overridding Payment Estimate Exception 57 on the current Payment Estimate.																													
					22	Jun 2, 2021	SYSTEM	(\$70,341.57)																														
					23	Jun 16, 2021	SYSTEM	\$70,341.57	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0063) due to user kloepj1 overridding Payment Estimate Exception 60 on the current Payment Estimate.																													
					23	Jun 16, 2021	SYSTEM	(\$70,341.57)																														
					24	Jul 1, 2021	SYSTEM	\$70,341.57	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0053) due to user herrmt1 overridding Payment Estimate Exception 32 on the current Payment Estimate.																													
					24	Jul 1, 2021	SYSTEM	(\$70,341.57)	Estimate Exception of the sunsiti ayribin Estimate.																													
					25	Jul 16, 2021	SYSTEM	\$70,341.57	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0064) due to user kloepj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.																													
					25	Jul 16, 2021	SYSTEM	(\$70,341.57)	Esumate exception 31 on the current Payment Esumate.																													
				- Total		2021		\$0.00																														
			Material - Tot					\$0.00																														
	5014 -	Total						\$0.00																														
	5015	REINFORCING STEEL (EPOXY COATED)	Material		14	Feb 2, 2021	SYSTEM	\$36,892.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user hillt5 overridding Payment Estimate Exception 42 on the current Payment Estimate.																													
					14	Feb 2, 2021	SYSTEM	(\$36,892.40)																														
					15	Feb 16, 2021	SYSTEM	\$36,892.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schlag1 overridding Payment Estimate Exception 47 on the current Payment Estimate.																													
					15	Feb 16, 2021	SYSTEM	(\$36,892.40)																														
					16	Mar 2, 2021	SYSTEM	\$36,892.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user kloepj1 overridding Payment Estimate Exception 46 on the current Payment Estimate.																													
					16	Mar 2, 2021	SYSTEM	(\$36,892.40)																														
							17	Mar 16, 2021	SYSTEM	\$36,892.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment Estimate Exception 39 on the current Payment Estimate.																											
								17	Mar 16, 2021	SYSTEM	(\$36,892.40)																											
																																		18	Apr 2, 2021	SYSTEM	\$36,892.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user kloepj1 overridding Payment Estimate Exception 42 on the current Payment Estimate.
																												1	1			18	Apr 2, 2021	SYSTEM	(\$36,892.40)			
																										19	Apr 16, 2021	SYSTEM	\$36,892.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user kloepj1 overridding Payment Estimate Exception 46 on the current Payment Estimate.								
															19	Apr 16, 2021	SYSTEM	(\$36,892.40)																				
												20	May 3, 2021	SYSTEM	\$36,892.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user hillt5 overridding Payment Estimate Exception 64 on the current Payment Estimate.																						
						20	May 3, 2021	SYSTEM	(\$36,892.40)																													
					21	May 17, 2021	SYSTEM	\$36,892.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0057) due to user hillt5 overridding Payment Estimate Exception 84 on the current Payment Estimate.																													



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																			
J6I2222	5015	REINFORCING STEEL (EPOXY	Material	,,,	21	May 17, 2021	SYSTEM	(\$36,892.40)																				
		COATED)			22	Jun 2, 2021	SYSTEM	\$36,892.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0055) due to user hillt5 overridding Payment Estimate Exception 99 on the current Payment Estimate.																			
					22	Jun 2, 2021	SYSTEM	(\$36,892.40)																				
						23	Jun 16, 2021	SYSTEM	\$36,892.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0064) due to user kloepj1 overridding Payment Estimate Exception 99 on the current Payment Estimate.																		
					23	Jun 16, 2021	SYSTEM	(\$36,892.40)																				
					24	Jul 1, 2021	SYSTEM	\$36,892.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0054) due to user herrmt1 overridding Payment Estimate Exception 61 on the current Payment Estimate.																			
					24	Jul 1, 2021	SYSTEM	(\$36,892.40)																				
					25	Jul 16, 2021	SYSTEM	\$36,892.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0065) due to user kloepj1 overridding Payment Estimate Exception 55 on the current Payment Estimate.																			
					25	Jul 16, 2021	SYSTEM	(\$36,892.40)																				
				- Total				\$0.00																				
	-04-		Material - Tot	tal				\$0.00																				
	5015 -		Metavial		4.4	Fab 2	CVCTEM	\$0.00	This adjustment offsets the original system generated Material Dayment																			
	5019	MECHANICAL BAR SPLICE	Material		14	Feb 2, 2021	SYSTEM	\$2,532.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user hillt5 overridding Payment Estimate Exception 41 on the current Payment Estimate.																			
					14	Feb 2, 2021	SYSTEM	(\$2,532.60)																				
			Material To	- Total				\$0.00																				
	5019 -	Total	Material - To	tai				\$0.00 \$0.00																				
	5020	FURN & PLACE CONC MATL FOR FULL DEPTH	Material		15	Feb 16, 2021	SYSTEM	\$18,227.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schlag1 overridding Payment Estimate Exception 13 on the current Payment Estimate.																			
		. 022 32			15	Feb 16, 2021	SYSTEM	(\$18,227.00)	ZOSINIAO ZINOPIONI TO SILATO SALISANI SYNONI ZOSINIAO.																			
					16	Mar 2, 2021	SYSTEM	\$18,227.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user kloepj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.																			
					16	Mar 2, 2021	SYSTEM	(\$18,227.00)																				
											17	Mar 16, 2021	SYSTEM	\$18,227.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment Estimate Exception 13 on the current Payment Estimate.													
																				17	Mar 16, 2021	SYSTEM	(\$18,227.00)					
												18	Apr 2, 2021	SYSTEM	\$18,227.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user kloepj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.												
					19	Apr 16, 2021	SYSTEM	\$18,227.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user kloepj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.																			
					19	Apr 16, 2021	SYSTEM	(\$18,227.00)																				
					20	May 3, 2021	SYSTEM	\$18,227.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user hillto overridding Payment Estimate Exception 16 on the current Payment Estimate.																			
					20	May 3, 2021	SYSTEM	(\$18,227.00)																				
					21	May 17, 2021	SYSTEM	\$18,227.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user hillt5 overridding Payment Estimate Exception 30 on the current Payment Estimate.																			



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	5020	FURN & PLACE CONC MATL FOR	Material		21	May 17, 2021	SYSTEM	(\$18,227.00)	
	FOLL DE	FULL DEPTH			22	Jun 2, 2021	SYSTEM	\$18,227.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0056) due to user hillt5 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$18,227.00)	
					23	Jun 16, 2021	SYSTEM	\$18,227.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0065) due to user kloepj1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$18,227.00)	
					24	Jul 1, 2021	SYSTEM	\$18,227.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0055) due to user herrmt1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$18,227.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	5020 -	Total						\$0.00	
	5021	TIE BAR (DRILL, FURN & INSTAL) (TYPE L	Material		15	Feb 16, 2021	SYSTEM	\$696.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user schlag1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					15	Feb 16, 2021	SYSTEM	(\$696.00)	
					16	Mar 2, 2021	SYSTEM	\$696.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user kloepj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					16	Mar 2, 2021	SYSTEM	(\$696.00)	
					17	Mar 16, 2021	SYSTEM	\$696.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					17	Mar 16, 2021	SYSTEM	(\$696.00)	
					18	Apr 2, 2021	SYSTEM	\$696.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user kloepj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					18	Apr 2, 2021	SYSTEM	(\$696.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	5021 -	Total						\$0.00	
	5022	DOWEL BAR (DRILLING, FURNISHING AND	Material		15	Feb 16, 2021	SYSTEM	\$1,950.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schlag1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
		INST			15	Feb 16, 2021	SYSTEM	(\$1,950.00)	
					16	Mar 2, 2021	SYSTEM	\$1,950.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user kloepj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					16	Mar 2, 2021	SYSTEM	(\$1,950.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	5022 -	Total						\$0.00	
	5025	SEWER - RIGID PIPE	Material		18	Apr 2, 2021	SYSTEM	\$99,643.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user kloepj1 overridding Payment Estimate Exception 53 on the current Payment Estimate.
					18	Apr 2, 2021	SYSTEM	(\$99,643.00)	
					19	Apr 16, 2021	SYSTEM	\$147,772.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user kloepj1 overridding Payment Estimate Exception 61 on the current Payment Estimate.
					19	Apr 16,	SYSTEM	(\$147,772.00)	



Application	D : .		Б	A 11	011					5 -
20	Project	Line	Description	Adjustment Type		Est. Number	Created Date	Created By	Amount	Remarks
20	J6I2222	5025		Material			2021			
2						20		SYSTEM	\$147,772.00	Estimate Item Adjustment (0042) due to user hillt5 overridding Payment
2021 2021						20		SYSTEM	(\$147,772.00)	
22						21		SYSTEM	\$147,772.00	Estimate Item Adjustment (0059) due to user hillt5 overridding Payment
2011 Estimate Rem Adjustment (0.057) use to use hills ovendiding Payment Estimate Exception 110 on the current Payment Estimate Exception 110 on the current Payment Estimate Exception 110 on the current Payment Estimate (2014) 2014						21		SYSTEM	(\$147,772.00)	
2021 23 24 m 16, 279 270						22		SYSTEM	\$147,772.00	Estimate Item Adjustment (0057) due to user hillt5 overridding Payment
2021						22		SYSTEM	(\$147,772.00)	
24						23		SYSTEM	\$147,772.00	Estimate Item Adjustment (0066) due to user kloepj1 overridding Payment
2021 SYSTEM SYSTEM STATUTE						23		SYSTEM	(\$147,772.00)	
2021 25						24		SYSTEM	\$147,772.00	Estimate Item Adjustment (0056) due to user herrmt1 overridding Payment
25						24		SYSTEM	(\$147,772.00)	
Total S0.00 Material - Total S0.00 Material - Total S0.00						25	Jul 16,	SYSTEM	\$147,772.00	Estimate Item Adjustment (0066) due to user kloepj1 overridding Payment
South Sout						25		SYSTEM	(\$147,772.00)	
Soze					- Total				\$0.00	
CLASS B-1 CONCRETE (SUBSTR)										
2021 Estimate Item Adjustment (0043) due to user hillifs overridding Payment Estimate Exception 38 on the current Payment Estimate.				Material - To	tal				\$0.00	
2021 21 May 17, SYSTEM \$140,119.20 22 Jun 2, SYSTEM \$140,119.20 22 Jun 2, SYSTEM \$140,119.20 23 Jun 16, 2021 24 Jun 16, 2021 25 SySTEM \$140,119.20 26 Jun 16, 2021 27 Jun 17, SYSTEM \$140,119.20 28 Jun 16, 2021 29 Jun 18, SYSTEM \$140,119.20 201 This adjustment offsets the original system-generated Material Payment Estimate Exception 70 on the current Payment Estimate. 29 Jun 18, SYSTEM \$140,119.20 201 This adjustment offsets the original system-generated Material Payment Estimate Exception 70 on the current Payment Estimate. 202 Jun 16, SYSTEM \$140,119.20 21 This adjustment offsets the original system-generated Material Payment Estimate Exception 72 on the current Payment Estimate. 203 Jun 16, SYSTEM \$140,119.20 205 Jun 16, SYSTEM \$140,119.20 206 This adjustment offsets the original system-generated Material Payment Estimate Exception 72 on the current Payment Estimate. 21 Jun 18, SYSTEM \$140,119.20 22 This adjustment offsets the original system-generated Material Payment Estimate Exception 72 on the current Payment Estimate. 22 Jun 18, SYSTEM \$140,119.20 23 Jun 16, SYSTEM \$140,119.20 24 Jun 17, SYSTEM \$140,119.20 25 Jun 16, SYSTEM \$140,119.20 26 Jun 16, SYSTEM \$140,119.20 27 This adjustment offsets the original system-generated Material Payment Estimate Exception 38 on the current Payment Estimate. 23 Jun 16, SYSTEM \$140,119.20 25 Jun 16, SYSTEM \$140,119.20 26 Jun 16, SYSTEM \$140,119.20 27 This adjustment offsets the original system-generated Material Payment Estimate Exception 36 on the current Payment Estimate Estimate Exception 36 on the current Payment Estimate.		5025 -	Total	Material - To	tal					
Estimate ltem Adjustment (0060) due to user hill5 overridding Payment Estimate Exception 58 on the current Payment Estimate.			CLASS B-1 CONCRETE		tal	20		SYSTEM	\$0.00	Estimate Item Adjustment (0043) due to user hillt5 overridding Payment
22 Jun 2, 2021 SYSTEM \$140,119.20 This adjustment offsets the original system-generated Material Payment Estimate Exception 70 on the current Payment Estimate. 22 Jun 2, 2021 SYSTEM (\$140,119.20) 20 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0067) due to user kidoepj1 overridding Payment Estimate Item Adjustment (0067) due to user kidoepj1 overridding Payment Estimate Exception 72 on the current Payment Estimate. 23 Jun 16, SYSTEM (\$140,119.20) SYSTEM 2021 SYSTEM \$140,119.20 This adjustment offsets the original system-generated Material Payment Estimate Exception 72 on the current Payment Estimate. 24 Jul 1, 2021 SYSTEM \$140,119.20 This adjustment offsets the original system-generated Material Payment Estimate Exception 38 on the current Payment Estimate. 24 Jul 1, SYSTEM \$140,119.20 This adjustment offsets the original system-generated Material Payment Estimate Exception 38 on the current Payment Estimate. 25 Jul 16, SYSTEM \$140,119.20 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0067) due to user kloepj1 overridding Payment Estimate Exception 36 on the current Payment Estimate.			CLASS B-1 CONCRETE		tal		2021 May 3,		\$0.00 \$140,119.20	Estimate Item Adjustment (0043) due to user hillt5 overridding Payment
Estimate (tem Adjustment (0058) due to user hillt5 overridding Payment Estimate Exception 70 on the current Payment Estimate. 22 Jun 2, 2021 23 Jun 16, 2021 24 Jul 1, 2021 25 Jul 16, 2021 26 Jul 1, 2021 27 Jul 16, 2021 28 SYSTEM (\$140,119.20) 29 This adjustment offsets the original system-generated Material Payment Estimate Exception 72 on the current Payment Estimate. 20 Jun 16, 2021 21 Jul 1, 2021 22 Jul 1, 2021 23 Jul 16, 2021 24 Jul 1, 2021 25 Jul 16, 2021 26 Jul 16, 2021 27 Jul 16, 2021 28 SYSTEM (\$140,119.20) 29 This adjustment offsets the original system-generated Material Payment Estimate Exception 38 on the current Payment Estimate. 29 Jul 16, 2021 20 Jul 16, 2021 20 Jul 16, 2021 20 Jul 16, 2021 20 SYSTEM (\$140,119.20) 20 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0067) due to user kloepj1 overridding Payment Estimate Item Adjustment (0067) due to user kloepj1 overridding Payment Estimate Item Adjustment (0067) due to user kloepj1 overridding Payment Estimate Item Adjustment (0067) due to user kloepj1 overridding Payment Estimate Item Adjustment (0067) due to user kloepj1 overridding Payment Estimate Item Adjustment (0067) due to user kloepj1 overridding Payment Estimate Item Adjustment (0067) due to user kloepj1 overridding Payment Estimate Item Adjustment (0067) due to user kloepj1 overridding Payment Estimate Item Adjustment (0067) due to user kloepj1 overridding Payment Estimate Item Adjustment (0067) due to user kloepj1 overridding Payment Estimate Item Adjustment (0067) due to user kloepj1 overridding Payment Estimate Item Adjustment (0067) due to user kloepj1 overridding Payment Estimate Item Adjustment (0067) due to user kloepj1 overridding Payment Estimate Item Adjustment (0067) due to user kloepj1 overridding Payment Estimate Item Adjustment (0067) due to user kloepj1 overridding Payment Estimate Item Adjustment (0067) due to user kloepj1 overridding Payment (0067) due to user kloepj1 overridding Payment (0067) due			CLASS B-1 CONCRETE		tal	20	2021 May 3, 2021 May 17,	SYSTEM	\$0.00 \$140,119.20 (\$140,119.20)	Estimate Item Adjustment (0043) due to user hillt5 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user hillt5 overridding Payment
2021 23 Jun 16, 2021 24 Jul 1, 2021 25 Jul 16, 2021 26 Jul 1, 2021 27 SYSTEM \$140,119.20 28 Jul 1, 2021 29 Jul 1, 2021 20 Jul 1, 2021 25 Jul 16, 2021 26 SYSTEM \$140,119.20 27 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0057) due to user herrmt1 overridding Payment Estimate Exception 38 on the current Payment Estimate. 27 Jul 16, 2021 28 SYSTEM \$140,119.20 29 Jul 16, 2021 20 Jul 16, 2021 20 Jul 16, 2021 20 Jul 16, 2021 20 Jul 16, 2021 30 Jul 16, 2021 40 SYSTEM \$140,119.20 50 Jul 16, 2021 50 Jul 16, 2021 50 Jul 16, 2021 50 Jul 16, 2021			CLASS B-1 CONCRETE		tal	20	2021 May 3, 2021 May 17, 2021	SYSTEM	\$0.00 \$140,119.20 (\$140,119.20) \$140,119.20	Estimate Item Adjustment (0043) due to user hillt5 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user hillt5 overridding Payment
Estimate Item Adjustment (0067) due to user kloepj1 overridding Payment Estimate Exception 72 on the current Payment Estimate. 23			CLASS B-1 CONCRETE		tal	20 21 21	2021 May 3, 2021 May 17, 2021 May 17, 2021 Jun 2,	SYSTEM SYSTEM	\$0.00 \$140,119.20 (\$140,119.20) \$140,119.20 (\$140,119.20)	Estimate Item Adjustment (0043) due to user hillt5 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user hillt5 overridding Payment Estimate Exception 58 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user hillt5 overridding Payment
24 Jul 1, 2021 SYSTEM \$140,119.20 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0057) due to user herrmt1 overridding Payment Estimate Exception 38 on the current Payment Estimate. 24 Jul 1, 2021 SYSTEM (\$140,119.20) 25 Jul 16, 2021 SYSTEM \$140,119.20 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0067) due to user kloepj1 overridding Payment Estimate Exception 36 on the current Payment Estimate. 25 Jul 16, 2021 SYSTEM (\$140,119.20) - Total \$0.00			CLASS B-1 CONCRETE		tal	20 21 21 22	2021 May 3, 2021 May 17, 2021 May 17, 2021 Jun 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$140,119.20 (\$140,119.20) \$140,119.20 (\$140,119.20) \$140,119.20	Estimate Item Adjustment (0043) due to user hillt5 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user hillt5 overridding Payment Estimate Exception 58 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user hillt5 overridding Payment
Estimate Item Adjustment (0057) due to user herrmt1 overridding Payment Estimate Exception 38 on the current Payment Estimate. 24 Jul 1, 2021 25 Jul 16, 2021 27 SYSTEM (\$140,119.20) This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0067) due to user kloepj1 overridding Payment Estimate Exception 36 on the current Payment Estimate. 25 Jul 16, 2021 SYSTEM (\$140,119.20) - Total \$0.00			CLASS B-1 CONCRETE		tal	20 21 21 22 22	2021 May 3, 2021 May 17, 2021 May 17, 2021 Jun 2, 2021 Jun 2, 2021 Jun 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$140,119.20 (\$140,119.20) \$140,119.20 (\$140,119.20) \$140,119.20	Estimate Item Adjustment (0043) due to user hillt5 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user hillt5 overridding Payment Estimate Exception 58 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user hillt5 overridding Payment Estimate Exception 70 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0067) due to user kloepj1 overridding Payment Estimate Item Adjustment (0067) due to user kloepj1 overridding Payment
2021 25 Jul 16, 2021 25 Jul 16, 2021 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0067) due to user kloepj1 overridding Payment Estimate Exception 36 on the current Payment Estimate. 25 Jul 16, 2021 System (\$140,119.20) - Total			CLASS B-1 CONCRETE		tal	20 21 21 22 22 22 23	2021 May 3, 2021 May 17, 2021 May 17, 2021 Jun 2, 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$140,119.20 (\$140,119.20) \$140,119.20 (\$140,119.20) \$140,119.20 (\$140,119.20)	Estimate Item Adjustment (0043) due to user hillt5 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user hillt5 overridding Payment Estimate Exception 58 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user hillt5 overridding Payment Estimate Exception 70 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0067) due to user kloepj1 overridding Payment
2021 Estimate Item Adjustment (0067) due to user kloepj1 overridding Payment Estimate Exception 36 on the current Payment Estimate. 25 Jul 16, 2021 (\$140,119.20) - Total \$0.00			CLASS B-1 CONCRETE		tal	20 21 21 22 22 23 23	2021 May 3, 2021 May 17, 2021 May 17, 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$140,119.20 (\$140,119.20) \$140,119.20 (\$140,119.20) \$140,119.20 (\$140,119.20)	Estimate Item Adjustment (0043) due to user hillt5 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user hillt5 overridding Payment Estimate Exception 58 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user hillt5 overridding Payment Estimate Exception 70 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0067) due to user kloepj1 overridding Payment Estimate Exception 72 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0057) due to user herrmt1 overridding Payment Estimate Item Adjustment (0057) due to user herrmt1 overridding Payment
25 Jul 16, 2021 (\$140,119.20) - Total \$0.00			CLASS B-1 CONCRETE		tal	20 21 21 22 22 23 23 24	2021 May 3, 2021 May 17, 2021 May 17, 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$140,119.20 (\$140,119.20) \$140,119.20 (\$140,119.20) \$140,119.20 (\$140,119.20) \$140,119.20 (\$140,119.20)	Estimate Item Adjustment (0043) due to user hillt5 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user hillt5 overridding Payment Estimate Exception 58 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user hillt5 overridding Payment Estimate Exception 70 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0067) due to user kloepj1 overridding Payment Estimate Exception 72 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0057) due to user herrmt1 overridding Payment Estimate Item Adjustment (0057) due to user herrmt1 overridding Payment
			CLASS B-1 CONCRETE		tal	20 21 21 22 22 23 23 24 24	2021 May 3, 2021 May 17, 2021 May 17, 2021 Jun 2, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$140,119.20 (\$140,119.20) \$140,119.20 (\$140,119.20) \$140,119.20 (\$140,119.20) \$140,119.20 (\$140,119.20)	Estimate Item Adjustment (0043) due to user hillt5 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user hillt5 overridding Payment Estimate Exception 58 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user hillt5 overridding Payment Estimate Exception 70 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0067) due to user kloepj1 overridding Payment Estimate Exception 72 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0057) due to user herrmt1 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 38 on the current Payment Estimate.
Material - Total \$0.00			CLASS B-1 CONCRETE		tal	20 21 21 22 22 23 23 24 24 25	2021 May 3, 2021 May 17, 2021 May 17, 2021 Jun 2, 2021 Jun 16, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Jul 16, 2021 Jul 16, 2021	SYSTEM	\$0.00 \$140,119.20 (\$140,119.20) \$140,119.20 (\$140,119.20) \$140,119.20 (\$140,119.20) \$140,119.20 (\$140,119.20) \$140,119.20 (\$140,119.20)	Estimate Item Adjustment (0043) due to user hillt5 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user hillt5 overridding Payment Estimate Exception 58 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user hillt5 overridding Payment Estimate Exception 70 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0067) due to user kloepj1 overridding Payment Estimate Exception 72 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0057) due to user herrmt1 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 38 on the current Payment Estimate.
			CLASS B-1 CONCRETE			20 21 21 22 22 23 23 24 24 25	2021 May 3, 2021 May 17, 2021 May 17, 2021 Jun 2, 2021 Jun 16, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Jul 16, 2021 Jul 16, 2021	SYSTEM	\$0.00 \$140,119.20 (\$140,119.20) \$140,119.20 (\$140,119.20) \$140,119.20 (\$140,119.20) \$140,119.20 (\$140,119.20) \$140,119.20 (\$140,119.20) \$140,119.20	Estimate Item Adjustment (0043) due to user hillt5 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user hillt5 overridding Payment Estimate Exception 58 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user hillt5 overridding Payment Estimate Exception 70 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0067) due to user kloepj1 overridding Payment Estimate Exception 72 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0057) due to user herrmt1 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 38 on the current Payment Estimate.

Jul 19, 2021



Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
J6I2222	5026 -	Total						\$0.00					
	5034	MISC. FENCING	Construction Stockpile STMI		20	May 3, 2021	SYSTEM	\$32,885.60	Payment Estimate Item Adjustment generated Stockpile Transaction				
			STIVII	- Total				\$32,885.60					
			Construction	Stockpile S	ГМI - Total			\$32,885.60					
	5034 -	Total						\$32,885.60					
	5037	REINFORCING STEEL (EPOXY COATED)	Material	Material		20	May 3, 2021	SYSTEM	\$37.06	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user hillt5 overridding Payment Estimate Exception 66 on the current Payment Estimate.			
					20	May 3, 2021	SYSTEM	(\$37.06)					
					21	May 17, 2021	SYSTEM	\$37,068.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0061) due to user hillt5 overridding Payment Estimate Exception 86 on the current Payment Estimate.				
					21	May 17, 2021	SYSTEM	(\$37,068.50)					
					22	Jun 2, 2021	SYSTEM	\$37,068.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0059) due to user hillt5 overridding Payment Estimate Exception 101 on the current Payment Estimate.				
					22	Jun 2, 2021	SYSTEM	(\$37,068.50)					
					23	Jun 16, 2021	SYSTEM	\$37,068.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0068) due to user kloepj1 overridding Payment Estimate Exception 101 on the current Payment Estimate.				
					23	Jun 16, 2021	SYSTEM	(\$37,068.50)					
					24	Jul 1, 2021	SYSTEM	\$37,068.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user herrmt1 overridding Payment Estimate Exception 63 on the current Payment Estimate.				
									24	Jul 1, 2021	SYSTEM	(\$37,068.50)	
					25	Jul 16, 2021	SYSTEM	\$37,068.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0068) due to user kloepj1 overridding Payment Estimate Exception 56 on the current Payment Estimate.				
					25	Jul 16, 2021	SYSTEM	(\$37,068.50)					
				- Total				\$0.00					
			Material - Tot	al				\$0.00					
	5037 -	Total						\$0.00					
	5047	15 IN. PIPE CULVERT GROUP C	Material		25	Jul 16, 2021	SYSTEM	\$6,160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0069) due to user kloepj1 overridding Payment Estimate Exception 67 on the current Payment Estimate.				
					25	Jul 16, 2021	SYSTEM	(\$6,160.00)					
				- Total				\$0.00					
			Material - To	tal				\$0.00					
	5047 -	Total						\$0.00					
	5049	18 IN. GROUP A FLARED END SECT	Material		25	Jul 16, 2021	SYSTEM	\$1,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0070) due to user kloepj1 overridding Payment Estimate Exception 72 on the current Payment Estimate.				
					25	Jul 16, 2021	SYSTEM	(\$1,800.00)					
				- Total				\$0.00					
			Material - Tot	tal				\$0.00					
	5049 -	Total						\$0.00					
J6I2222 -	Total							\$358,680.30					
Overall -	Total							\$358,680.30					