

Pay Estimate Created Date: September 2, 2021

Progress Estimate Number	Contract ID	200515-F15	3	Original Contract Amount \$24,269,745.00
28	Prime Contracto	or KCI Construction Company	Pay Period End September 1, 2021	Net Change Order Amount \$839,574.30
20				Current Contract Amount \$25,109,319.30

Approval Date		By User
September 3, 2021	Generated and Approved (and should be considered Draft) at the Project Office Level by	kloepj1
September 3, 2021	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	washas
September 3, 2021	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
June 1, 2022	June 1, 2022		66.70%

	Contract Informational Date	tes	Milestones
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract
Acceptance Date			
Awarded Date	June 3, 2020	June 3, 2020	
Letting Date	May 15, 2020	May 15, 2020	
Notice to Proceed Date	July 6, 2020	July 6, 2020	
Open to Traffic Date			
Work Began Date			

Contract Total Pa	ay For Estimate No. 28			
		This Estimate	Previous	To Date
200515-F15				
	Total Posted Items Pay	\$868,711.47	\$15,878,602.75	\$16,747,314.22
	Gross Item Adjustments	\$1,384.72	\$347,324.26	\$348,708.98
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$5,765.00	\$4,054.50	\$9,819.50
	,		\$16,229,981.51	\$17,105,842.70
Contract Total Pa	avable This Estimate:	\$875.861.19		

Items Paid This Estimate Period

Project Line Item Number Number Code	Item Description	Unit			
Number Number Code	item Bescription	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6I2222 0020 2022010 REMOVA	AL OF IMPROVEMENTS	LS	\$600,000.000	0.13	\$78,000.00
0050 2031000 CLASS A	AEXCAVATION	CUYD	\$15.000	1,000	\$15,000.00
0120 2063000 CLASS 3	EXCAVATION	CUYD	\$15.000	534	\$8,010.00
0200 5021108 CONCRE	ETE PAVEMENT (8 IN. NON-REINF)	SQYD	\$49.000	64.4	\$3,155.60
0380 6071102 MODIFIE	D CONCRETE GUTTER TYPE B	LF	\$34.000	82	\$2,788.00
0640 6149902 MISC.Par	rallel Grate and Bearing Plate (2 FT.x2FT.)	EA	\$700.000	1	\$700.00
1060 7033009 AESTHET	TIC CONCRETE STAIN	LS	\$6,110.880	1	\$6,110.88
1110 7261015 15 IN. PIF	PE GROUP A	LF	\$70.000	351	\$24,570.00
1120 7261018 18 IN. PIF	PE GROUP A	LF	\$80.000	352	\$28,160.00
1170 7311022 PRECAS	T CONCRETE DROP INLET 2 FT X 2 FT	FT	\$350.000	20	\$7,000.00
1180 7311042 PRECAS	T CONCRETE DROP INLET 4 FT X 2 FT	FT	\$450.000	25	\$11,250.00
1210 7319913 MISC.MS	SD Standard Line 48" Manhole	FT	\$350.000	25	\$8,750.00
1220 7320615A 15 IN. OR SECTION	R ALLOWED SUBSTITUTE GROUP A FLARED END N	EA	\$800.000	1	\$800.00
1490 3040506 TYPE 5 A	AGGREGATE FOR BASE (6 IN. THICK)	SQYD	\$6.500	2,223.4	\$14,452.10
1500 5021308 CONCRE JOINTS)	ETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT.	SQYD	\$51.000	406.7	\$20,741.70
1510 5021309 CONCRE	ETE PAVEMENT (9 IN. NON-REINFORCED 15 FT.	SQYD	\$54.000	1,334.2	\$72,046.80

Revision 4/1/2020 Page 1 of 100

\$5,765.00



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: September 2, 2021

Contract ID 200515-F15 Pay Period Start August 16, 2021 Original Contract Amount \$24,269,745.00
Prime Contractor KCI Construction Company Pay Period End September 1, 2021 Net Change Order Amount \$839,574.30
Current Contract Amount \$25,109,319.30 **Progress Estimate Number** 28

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6I2222			JOINTS)				
	1550	5021340	TYPE A2 SHOULDER	SQYD	\$35.000	417.8	\$14,623.00
	1690	9015010	TRENCHING TYPE I	LF	\$3.800	949	\$3,606.20
	1700	9015020	TRENCHING TYPE II	LF	\$3.800	106	\$402.80
	1710	9016110	PULL BOX, PREFORMED CLASS 1	EA	\$765.000	1	\$765.00
	1730	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	LF	\$0.550	360	\$198.00
	1740	9017401	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 2 AWG	LF	\$6.000	800	\$4,800.00
	1750	9017404	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 6 AWG	LF	\$3.600	336	\$1,209.60
	1760	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	LF	\$2.900	310	\$899.00
	1770	9018245	POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)		\$1,068.000	4	\$4,272.0
	1800	9019902	MISC.45 FT TOP MOUNT POLES, TYPE AT	EA	\$2,250.000	4	\$9,000.00
	1820	9019902	MISC.BASE MOUNTED 240/480V COMBINATION POWER SUPPLY AND CONTROLLER	EA	\$7,258.000	0.33	\$2,395.1
	1830	9019902	MISC.LED-C TOP-MOUNT LUMINAIRE	EA	\$572.000	4	\$2,288.0
	2010	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	LF	\$10.200	261	\$2,662.2
	2080	9028811	PULL BOX, PREFORMED CLASS 2	EA	\$1,221.000	1	\$1,221.0
	2100	9029100	BASE, CONCRETE	CUYD	\$1,160.000	3.71	\$4,303.6
	2700	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	SQFT	\$158.000	51	\$8,058.0
	2810	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	SQFT	\$158.000	886	\$139,988.0
	2830	7049904	MISC.BARRIER CURB REPAIR (UNFORMED)	SQFT	\$175.000	189	\$33,075.0
	3300	7034221	SLAB ON CONCRETE NU-GIRDER	SQYD	\$290.000	587.5	\$170,375.0
	3350	7079901	MISC.CONDUIT SYSTEM ON STRUCTURE - ATT TELPHONE	LS	\$3,730.000	1	\$3,730.0
	3355	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	LS	\$8,330.050	1	\$8,330.0
	3420	7033009	AESTHETIC CONCRETE STAIN	LS	\$7,856.100	1	\$7,856.1
	3440	7033009	AESTHETIC CONCRETE STAIN	LS	\$3,654.000	1	\$3,654.0
	5002	6141121	CURVED VANE GRATE AND FRAME (4 FT. X 2 FT. OR 1200MM X 600MM)	EA	\$1,400.000	2	\$2,800.0
	5003	6149902	MISC.Parallel Grate and Bearing Plate (4 FT.x2FT.)	EA	\$1,400.000	4	\$5,600.0
	5029	7034221	SLAB ON CONCRETE NU-GIRDER	SQYD	\$406.000	271	\$110,026.0
	5038	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	LS	\$13,118.700	1	\$13,118.7
	5048	7250418	18 IN. PIPE GROUP C	LF	\$80.000	99	\$7,920.0
roject J6I	2222 - Tota	al					\$868,711.4
verall - T	otal						\$868,711.4

Contract Adjustments This Estimate

Adj Type	Entered By	Comments	Time Units	Rate	Amount
RFADOther Contract Adjustment	kloepj1	RailPros Invoice Number KC3330620210731			\$5,765.00

Overall - Total These amounts are listed in the Incentive, Disincentive, Liquidated Damages or Other Contract Adjustments

ine Item Adjustments This Estimate

Revision 4/1/2020 Page 2 of 100



Pay Estimate Created Date: September 2, 2021

Progress Estimate Number 28 Contract ID 200515-F15 Pay Period Start August 16, 2021 Prime Contractor KCI Construction Company Pay Period End September 1, 2021 Net Change Order Amount \$839,574.30 Current Contract Amount \$25,109,319.30

ject nber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
2222	0050	CLASS A EXCAVATION	Price	.) [-	Reference Item Price Adjustment Index Adjustment Type applied is FUEL	1,000	\$0.28	\$278.00
	0160	GRAVEL (A) OR CRUSHED STONE (B)	Material			-888	\$12.00	(\$10,656.00
	0160	GRAVEL (A) OR CRUSHED STONE (B)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	888	\$12.00	\$10,656.00
	0200	CONCRETE PAVEMENT (8 IN. NON-REINF)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	64.4	\$0.83	\$53.71
	0410	PAVED APPROACH, 8 IN.	Material			-72.3	\$125.00	(\$9,037.50
	0410	PAVED APPROACH, 8 IN.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	72.3	\$125.00	\$9,037.50
	0460	CONCRETE GUTTER TYPE B	Material			-268	\$30.00	(\$8,040.00
	0460	CONCRETE GUTTER TYPE B	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	268	\$30.00	\$8,040.00
	0490	FURNISHING TYPE 2 ROCK DITCH LINER	Material			-210.5	\$100.00	(\$21,050.00
	0490	FURNISHING TYPE 2 ROCK DITCH LINER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	210.5	\$100.00	\$21,050.00
	0675	CONCRETE TRAFFIC BARRIER, TYPE C	Material			-485	\$145.00	(\$70,325.00
	0675	CONCRETE TRAFFIC BARRIER, TYPE C	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user kloepj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	485	\$145.00	\$70,325.00
	0690	CONCRETE TRAFFIC BARRIER, TYPE D (RETAINING WALL)	Material			-2,335.5	\$85.00	(\$198,517.50
	0690	CONCRETE TRAFFIC BARRIER, TYPE D (RETAINING WALL)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	2,335.5	\$85.00	\$198,517.50
	0990	MISC.	Material			-2,401	\$15.50	(\$37,215.50
	0990	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	2,401	\$15.50	\$37,215.50
	1050	MISC.	Material			-952	\$25.00	(\$23,800.00
	1050	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 25 on the current Payment Estimate.	952	\$25.00	\$23,800.00

Revision 4/1/2020 Page 3 of 100



Pay Estimate Created Date: September 2, 2021

Progress Estimate Number 28 Contract ID 200515-F15 Pay Period Start August 16, 2021 Prime Contractor KCI Construction Company Pay Period End September 1, 2021 Net Change Order Amount \$839,574.30 Current Contract Amount \$25,109,319.30

ject	Line	Item Description	Adjustment	Other Item	Comments	Adjustment	Line Item	Adjustment
nber	No.	·	Туре	Adjustment Type		Quantity	Adjustment Unit Price	amount
222	1060	AESTHETIC CONCRETE STAIN	Material			-1	\$6,110.88	(\$6,110.88
	1060	AESTHETIC CONCRETE STAIN	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.	1	\$6,110.88	\$6,110.88
	1190	PRECAST CONCRETE DROP INLET 5 FT X 3 FT	Material			-55	\$650.00	(\$35,750.00
	1190	PRECAST CONCRETE DROP INLET 5 FT X 3 FT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment Estimate Exception 75 on the current Payment Estimate.	55	\$650.00	\$35,750.00
	1490	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	470.9	\$0.32	\$150.55
	1490	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	691.7	\$0.32	\$221.14
	1490	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	176.9	\$0.32	\$56.55
	1490	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	222.9	\$0.32	\$71.26
	1490	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	275.2	\$0.32	\$87.98
	1490	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	271.6	\$0.32	\$86.83
	1490	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	114.2	\$0.32	\$36.51
	1490	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material			-8,144.722	\$6.50	(\$52,940.69
	1490	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	8,144.722	\$6.50	\$52,940.69
	1500	CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. JOINTS)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	258.6	\$0.83	\$215.67
	1500	CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. JOINTS)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	114.4	\$0.83	\$95.41
	1500	CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. JOINTS)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	33.7	\$0.83	\$28.11
	1500	CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. JOINTS)	Material			-5,208.6	\$51.00	(\$265,638.60
	1500	CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. JOINTS)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0049) due to user kloepj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	5,208.6	\$51.00	\$265,638.60
	1510	CONCRETE PAVEMENT (9 IN. NON-REINFORCED 15 FT. JOINTS)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	212	\$0.92	\$194.49
	1510	CONCRETE PAVEMENT (9 IN. NON-REINFORCED 15	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	691.7	\$0.92	\$634.57

Revision 4/1/2020 Page 4 of 100



Pay Estimate Created Date: September 2, 2021

Progress Estimate Number 28 Contract ID 200515-F15 Pay Period Start August 16, 2021 Prime Contractor KCI Construction Company Pay Period End September 1, 2021 Net Change Order Amount \$839,574.30 Current Contract Amount \$25,109,319.30

ect per	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
22		FT. JOINTS)						
	1510	CONCRETE PAVEMENT (9 IN. NON-REINFORCED 15 FT. JOINTS)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	62.5	\$0.92	\$57.34
	1510	CONCRETE PAVEMENT (9 IN. NON-REINFORCED 15 FT. JOINTS)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	222.9	\$0.92	\$204.49
	1510	CONCRETE PAVEMENT (9 IN. NON-REINFORCED 15 FT. JOINTS)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	129	\$0.92	\$118.34
	1510	CONCRETE PAVEMENT (9 IN. NON-REINFORCED 15 FT. JOINTS)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	16.1	\$0.92	\$14.77
	1520	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	Material			-210	\$15.00	(\$3,150.00)
	1520	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0056) due to user kloepj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	210	\$15.00	\$3,150.00
	1550	TYPE A2 SHOULDER	Material			-39.6	\$35.00	(\$1,386.00
	1550	TYPE A2 SHOULDER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0057) due to user kloepj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	39.6	\$35.00	\$1,386.00
	1570	MGS GUARDRAIL	Material			-463	\$19.00	(\$8,797.00
	1570	MGS GUARDRAIL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	463	\$19.00	\$8,797.00
	1730	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	Material			-360	\$0.55	(\$198.00
	1730	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment Estimate Exception 76 on the current Payment Estimate.	360	\$0.55	\$198.00
	1740	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 2 AWG	Material			-800	\$6.00	(\$4,800.00)
	1740	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 2 AWG	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment Estimate Exception 77 on the current Payment Estimate.	800	\$6.00	\$4,800.00
	1750	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 6 AWG	Material			-336	\$3.60	(\$1,209.60
	1750	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 6 AWG	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0024) due to user kloepj1 overridding Payment Estimate Exception 78 on the current Payment Estimate.	336	\$3.60	\$1,209.60
	1760	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE	Material			-310	\$2.90	(\$899.00)

Revision 4/1/2020 Page 5 of 100

Pay Estimate Created Date: September 2, 2021

Progress Estimate Number 28 Contract ID 200515-F15 Pay Period Start August 16, 2021 Prime Contractor KCI Construction Company Pay Period End September 1, 2021 Net Change Order Amount \$839,574.30 Current Contract Amount \$25,109,319.30

						rent Contrac		
ject nber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
222		NEUTRAL, 8 AWG						
	1760	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0025) due to user kloepj1 overridding Payment Estimate Exception 79 on the current Payment Estimate.	310	\$2.90	\$899.00
	1770	POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	Material			-4	\$1,068.00	(\$4,272.00
	1770	POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0026) due to user kloepj1 overridding Payment Estimate Exception 80 on the current Payment Estimate.	4	\$1,068.00	\$4,272.00
	1780	MISC.	Material			-1	\$16,605.00	(\$16,605.00
	1780	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0027) due to user kloepj1 overridding Payment Estimate Exception 82 on the current Payment Estimate.	1	\$16,605.00	\$16,605.00
	1800	MISC.	Material			-4	\$2,250.00	(\$9,000.00
	1800	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0029) due to user kloepj1 overridding Payment Estimate Exception 84 on the current Payment Estimate.	4	\$2,250.00	\$9,000.00
	1820	MISC.	Material			-0.33	\$7,258.00	(\$2,395.14
	1820	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0030) due to user kloepj1 overridding Payment Estimate Exception 85 on the current Payment Estimate.	0.33	\$7,258.00	\$2,395.14
	1830	MISC.	Material			-4	\$572.00	(\$2,288.00
	1830	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0028) due to user kloepj1 overridding Payment Estimate Exception 83 on the current Payment Estimate.	4	\$572.00	\$2,288.00
	1870	SIGNAL HEAD, TYPE 3B	Material			-5	\$927.00	(\$4,635.00
	1870	SIGNAL HEAD, TYPE 3B	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0031) due to user kloepj1 overridding Payment Estimate Exception 88 on the current Payment Estimate.	5	\$927.00	\$4,635.00
	1910	POST, SIGNAL 8 FT. OR 2.4 M	Material			-3	\$645.00	(\$1,935.00
	1910	POST, SIGNAL 8 FT. OR 2.4 M	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0032) due to user kloepj1 overridding Payment Estimate Exception 89 on the current Payment Estimate.	3	\$645.00	\$1,935.00
	1960	POST, TYPE C, 55 FT. ARM	Material			-1	\$11,930.00	(\$11,930.00
	1960	POST, TYPE C, 55 FT. ARM	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0033) due to user kloepj1 overridding Payment Estimate Exception 92 on the current Payment Estimate.	1	\$11,930.00	\$11,930.00
	1990	CONTROLLER ASSEMBLY	Material			-1	\$13,359.00	(\$13,359.00

Revision 4/1/2020 Page 6 of 100



Pay Estimate Created Date: September 2, 2021

Progress Estimate Number 28 Contract ID 200515-F15 Pay Period Start August 16, 2021 Prime Contractor KCI Construction Company Pay Period End September 1, 2021 Net Change Order Amount \$839,574.30 Current Contract Amount \$25,109,319.30

ect	Line No.	Item Description	Adjustment Type	Other Item Adjustment	Comments	Adjustment Quantity	Line Item Adjustment	Adjustment amount
			,,,	Туре			Unit Price	
22		HOUSING, NEMA TS2 CONTROLLER						
	1990	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0034) due to user kloepj1 overridding Payment Estimate Exception 93 on the current Payment Estimate.	1	\$13,359.00	\$13,359.00
	2060	CABLE, 16 AWG 7 CONDUCTOR	Material			-1,176	\$1.60	(\$1,881.60
	2060	CABLE, 16 AWG 7 CONDUCTOR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0035) due to user kloepj1 overridding Payment Estimate Exception 94 on the current Payment Estimate.	1,176	\$1.60	\$1,881.60
	2080	PULL BOX, PREFORMED CLASS 2	Overrun			-1	\$1,221.00	(\$1,221.00
	2100	BASE, CONCRETE	Material			-10.3	\$1,160.00	(\$11,948.00
	2100	BASE, CONCRETE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0037) due to user kloepj1 overridding Payment Estimate Exception 95 on the current Payment Estimate.	10.3	\$1,160.00	\$11,948.00
	2210	CONCRETE FOOTINGS, BOLT DOWN	Material			-56.32	\$1,200.00	(\$67,584.00
	2210	CONCRETE FOOTINGS, BOLT DOWN	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0044) due to user kloepj1 overridding Payment Estimate Exception 96 on the current Payment Estimate.	56.32	\$1,200.00	\$67,584.00
	2330	MISC.	Material			-1	\$66,000.00	(\$66,000.00
	2330	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0045) due to user kloepj1 overridding Payment Estimate Exception 97 on the current Payment Estimate.	1	\$66,000.00	\$66,000.00
	2670	SLAB ON STEEL	Material			-214	\$470.00	(\$100,580.00
	2670	SLAB ON STEEL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0058) due to user kloepj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.	214	\$470.00	\$100,580.00
	2690	CORRAL CURB	Material			-142	\$117.00	(\$16,614.00
	2690	CORRAL CURB	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0059) due to user kloepj1 overridding Payment Estimate Exception 39 on the current Payment Estimate.	142	\$117.00	\$16,614.00
	2700	SUPERSTRUCTURE REPAIR (UNFORMED)	Material			-1,320	\$158.00	(\$208,560.00
	2700	SUPERSTRUCTURE REPAIR (UNFORMED)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0060) due to user kloepj1 overridding Payment Estimate Exception 41 on the current Payment Estimate.	1,320	\$158.00	\$208,560.00
	2720	MISC.	Material			-148	\$175.00	(\$25,900.00
	2720	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0061) due to user kloepj1	148	\$175.00	\$25,900.00

Revision 4/1/2020 Page 7 of 100



Pay Estimate Created Date: September 2, 2021

Progress Estimate Number 28 Contract ID 200515-F15 Pay Period Start August 16, 2021 Original Contract Amount \$24,269,745.00 Prime Contractor KCI Construction Company Pay Period End September 1, 2021 Net Change Order Amount \$839,574.30 Current Contract Amount \$25,109,319.30

ct er	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
22					overridding Payment Estimate Exception 49 on the current Payment Estimate.			
	2730	REINFORCING STEEL (EPOXY COATED)	Material			-850	\$3.00	(\$2,550.00
	2730	REINFORCING STEEL (EPOXY COATED)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0062) due to user kloepj1 overridding Payment Estimate Exception 54 on the current Payment Estimate.	850	\$3.00	\$2,550.00
	2810	SUPERSTRUCTURE REPAIR (UNFORMED)	Material			-2,369	\$158.00	(\$374,302.00
	2810	SUPERSTRUCTURE REPAIR (UNFORMED)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0063) due to user kloepj1 overridding Payment Estimate Exception 45 on the current Payment Estimate.	2,369	\$158.00	\$374,302.00
	2830	MISC.	Material			-331	\$175.00	(\$57,925.00
	2830	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0064) due to user kloepj1 overridding Payment Estimate Exception 51 on the current Payment Estimate.	331	\$175.00	\$57,925.00
	2940	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material			-8,672	\$62.50	(\$542,000.00
	2940	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0065) due to user kloepj1 overridding Payment Estimate Exception 62 on the current Payment Estimate.	8,672	\$62.50	\$542,000.00
	3180	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	Material			-25.5	\$490.00	(\$12,495.00
	3180	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0039) due to user kloepj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.	25.5	\$490.00	\$12,495.00
	3190	ROCK SOCKETS (3 FT 0 IN. DIA.)	Material			-30	\$815.00	(\$24,450.00
	3190	ROCK SOCKETS (3 FT 0 IN. DIA.)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0040) due to user kloepj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.	30	\$815.00	\$24,450.00
	3300	SLAB ON CONCRETE NU- GIRDER	Material			-1,116.25	\$290.00	(\$323,712.50
	3300	SLAB ON CONCRETE NU- GIRDER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0041) due to user kloepj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.	1,116.25	\$290.00	\$323,712.50
	3350	MISC.	Material			-1	\$3,730.00	(\$3,730.00
	3350	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0042) due to user kloepj1 overridding Payment Estimate Exception 53 on the current Payment Estimate.	1	\$3,730.00	\$3,730.00
	3355	PROTECTIVE COATING - CONCRETE BENTS AND	Material			-1	\$8,330.05	(\$8,330.05



Pay Estimate Created Date: September 2, 2021

Progress Estimate Number 28 Contract ID 200515-F15 Pay Period Start August 16, 2021 Original Contract Amount \$24,269,745.00 Prime Contractor KCI Construction Company Pay Period End September 1, 2021 Net Change Order Amount \$839,574.30 Current Contract Amount \$25,109,319.30

ect per	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
22		PIERS (EPOXY)						
	3355	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0038) due to user kloepj1 overridding Payment Estimate Exception 60 on the current Payment Estimate.	1	\$8,330.05	\$8,330.05
	3400	PIPE PILE SPACERS	Material			-14	\$855.00	(\$11,970.00
	3400	PIPE PILE SPACERS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0043) due to user kloepj1 overridding Payment Estimate Exception 69 on the current Payment Estimate.	14	\$855.00	\$11,970.00
	3420	AESTHETIC CONCRETE STAIN	Material			-1	\$7,856.10	(\$7,856.10
	3420	AESTHETIC CONCRETE STAIN	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0066) due to user kloepj1 overridding Payment Estimate Exception 27 on the current Payment Estimate.	1	\$7,856.10	\$7,856.10
	3430	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material			-4,182	\$80.00	(\$334,560.00)
	3430	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0067) due to user kloepj1 overridding Payment Estimate Exception 64 on the current Payment Estimate.	4,182	\$80.00	\$334,560.00
	3440	AESTHETIC CONCRETE STAIN	Material			-1	\$3,654.00	(\$3,654.00
	3440	AESTHETIC CONCRETE STAIN	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0068) due to user kloepj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.	1	\$3,654.00	\$3,654.00
	3450	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material			-2,521	\$80.00	(\$201,680.00
	3450	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0069) due to user kloepj1 overridding Payment Estimate Exception 66 on the current Payment Estimate.	2,521	\$80.00	\$201,680.00
	3480	DRILLED SHAFTS (6 FT. 0 IN. DIA.)	Material			-246.16	\$485.00	(\$119,387.60)
	3480	DRILLED SHAFTS (6 FT. 0 IN. DIA.)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0070) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.	246.16	\$485.00	\$119,387.60
	3490	ROCK SOCKETS (5 FT 6 IN. DIA.)	Material			-108	\$2,555.00	(\$275,940.00)
	3490	ROCK SOCKETS (5 FT 6 IN. DIA.)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0071) due to user kloepj1 overridding Payment Estimate Exception 24 on the current Payment Estimate.	108	\$2,555.00	\$275,940.00
	5003	MISC.	Material			-7	\$1,400.00	(\$9,800.00)
	5003	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item	7	\$1,400.00	\$9,800.00

Revision 4/1/2020 Page 9 of 100



Pay Estimate Created Date: September 2, 2021

Progress Estimate Number 28 Contract ID 200515-F15 Pay Period Start August 16, 2021 Prime Contractor KCI Construction Company Pay Period End September 1, 2021 Net Change Order Amount \$839,574.30 Current Contract Amount \$25,109,319.30

ect ber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
222					Adjustment (0072) due to user kloepj1 overridding Payment Estimate Exception 13 on the current Payment Estimate.			
	5008	MISC.	Material			-1	\$400.00	(\$400.00
	5008	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0073) due to user kloepj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	1	\$400.00	\$400.00
	5013	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	Material			-202.8	\$567.75	(\$115,139.70
	5013	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0074) due to user kloepj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.	202.8	\$567.75	\$115,139.70
	5014	ROCK SOCKETS (3 FT 0 IN. DIA.)	Material			-76.7	\$917.10	(\$70,341.57
	5014	ROCK SOCKETS (3 FT 0 IN. DIA.)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0075) due to user kloepj1 overridding Payment Estimate Exception 23 on the current Payment Estimate.	76.7	\$917.10	\$70,341.57
	5015	REINFORCING STEEL (EPOXY COATED)	Material			-24,760	\$1.49	(\$36,892.40
	5015	REINFORCING STEEL (EPOXY COATED)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0076) due to user kloepj1 overridding Payment Estimate Exception 56 on the current Payment Estimate.	24,760	\$1.49	\$36,892.40
	5025	SEWER	Material			-147,772	\$1.00	(\$147,772.00
	5025	SEWER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0077) due to user kloepj1 overridding Payment Estimate Exception 73 on the current Payment Estimate.	147,772	\$1.00	\$147,772.00
	5026	CLASS B-1 CONCRETE (SUBSTRUCTURE)	Material			-99.8	\$1,404.00	(\$140,119.20
	5026	CLASS B-1 CONCRETE (SUBSTRUCTURE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0078) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.	99.8	\$1,404.00	\$140,119.20
	5029	SLAB ON CONCRETE NU- GIRDER	Material			-571	\$406.00	(\$231,826.00
	5029	SLAB ON CONCRETE NU- GIRDER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0080) due to user kloepj1 overridding Payment Estimate Exception 35 on the current Payment Estimate.	571	\$406.00	\$231,826.00
	5037	REINFORCING STEEL (EPOXY COATED)	Material			-31,150	\$1.19	(\$37,068.50
	5037	REINFORCING STEEL (EPOXY COATED)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0079) due to user kloepj1 overridding Payment Estimate Exception 58 on the current Payment Estimate.	31,150	\$1.19	\$37,068.50
	5038	PROTECTIVE COATING - CONCRETE BENTS AND	Material			-1	\$13,118.70	(\$13,118.70

Revision 4/1/2020 Page 10 of 100



Pay Estimate Created Date: September 2, 2021

Progress Estimate Number 28 Contract ID 200515-F15 Pay Period Start August 16, 2021 Prime Contractor KCI Construction Company Pay Period End September 1, 2021 Net Change Order Amount \$839,574.30 Current Contract Amount \$25,109,319.30

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount	
J6I2222		PIERS (EPOXY)							
	5038	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0081) due to user kloepj1 overridding Payment Estimate Exception 61 on the current Payment Estimate.	1	\$13,118.70	\$13,118.70	
	5044	SLOPE PROTECTION	Material			-489.6	\$150.00	(\$73,440.00)	
	5044	SLOPE PROTECTION	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0082) due to user kloepj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	489.6	\$150.00	\$73,440.00	
	5047	15 IN. PIPE GROUP C	Material			-88	\$70.00	(\$6,160.00)	
	5047	15 IN. PIPE GROUP C	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0083) due to user kloepj1 overridding Payment Estimate Exception 71 on the current Payment Estimate.	88	\$70.00	\$6,160.00	
	5048	18 IN. PIPE GROUP C	Material			-99	\$80.00	(\$7,920.00)	
	5048	18 IN. PIPE GROUP C	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0084) due to user kloepj1 overridding Payment Estimate Exception 72 on the current Payment Estimate.	99	\$80.00	\$7,920.00	
Total								\$1,384.72	

Revision 4/1/2020 Page 11 of 100



					Contract Project Information
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work
J6I2222	I-64-1 (61)	Interchange improvements	I-64	ST LOUIS CITY	from west of Ewing Ave to east of 21st Street

Totals by Jo	ob Numbers			
J6I2222		This Estimate	Previous	To Date
	Posted Item Pay Gross Item Adjustments	\$868,711.47 \$1,384.72	\$15,878,602.75 \$347,324.26	\$16,747,314.22 \$348,708.98
	Gross Item Pay	\$870,096.19	\$16,225,927.01	\$17,096,023.20
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damages	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$5,765.00	\$4,054.50	\$9,819.50

Revision 4/1/2020 Page 12 of 100



Exceptions (Discrepancies) This Estimate Period

Exception For Description Name of Exception Support (Proced BROSE Description Support Contract Control For Support (Proced BROSE Description Support Control C	Exceptions (Discrepancies) This Estimate Period			
Namour 1000, Material Sci 200000000, Material Sci 20000000, Popular Blaz Life Life Life Live Live Sci 2000000000000000000000000000000000000	Exceptions / Discrepencies	Explanation		Status
Number 1001, Materia Sel 310100000000, Autoria (1007 14A D. 17 - Age gas to previous characters (1007 14A D. 17 - Br. of the State (1007 14A D. 17 - Br. of	Number 1490, Material Set 304050696, Material 1007T1ABLDT5 - Agg Base Type 1 & 5	Aggregate material testing needs to be reported	kloepj1	Overridden
Number 1000. Malerial Ses 600119808. Alterial 10031. CPCIALD P.FCCP or Manurery Y Mar. LSDU. Appreçate malerial festing needs to be reported. Appreçate malerial festing needs to the reported. Appreçate malerial festing needs to be reported. A	Number 0160, Material Set 310500396, Material 1007T1ABLDT5 - Agg Base Type 1 & 5	Aggregate material testing needs to be reported	kloepj1	Overridden
Namber 1900, Material Stat 6021 201898, Material 1005A-RCINS C.A. Natural Sand for Cone Class A, Acceptance Action Control 1005A-Class C.A. in studients. Pages (20122). A stream 5021 140, Project tiern Line Extended Exception Type: Insufficient Materials: Project 201222, Item 6021 100, Project tiern Line Walting on the material report based off certification Walting on PAL Natural Sand of Cone Class A. Acceptance Action Control 1005D is insufficient. Materials: Project 3012222, Item 6035008, Project Item Line Namber 1970, Materials of 1005D is insufficient. Materials: Project 3012222, Item 6035008, Project Item Line Namber 1970, Materials of 1005D is insufficient. Materials: Project 3012222, Item 6035008, Project Item Line Namber 1970, Materials of 1005D is insufficient. Materials: Project 3012222, Item 6035008, Project Item Line Namber 1970, Materials of 1005D is insufficient. Materials: Project 3012222, Item 6035008, Project Item Line Namber 1970, Material 1005D is insufficient. Materials: Project 3012222, Item 6035008, Project Item Line Namber 1970, Material 1005D is insufficient. See 1005009, Material 10050	Number 1500, Material Set 502130896, Material 100510. CPCMLD - PCCP or Masonry 1" Max LS/DO,	Aggregate material testing needs to be reported	kloepj1	Overridden
Number 1505, Material St. 6002134086, Material 10054ACONS. CA. Natural 38and for Cone Class A, Acceptance Action Generic 10054ACONS. As insufficient State of the Cone Class A, Acceptance Action Generic 10054ACONS. As insufficient Materials Project, AUSZ22, then 0051000, Project Item Line Materials Project AUSZ22, then 0051000, Project Item Line Number 0140, Materials See 005000086, Materials Project AUSZ22, then 0050000, Project Item Line Number 0140, Materials Project AUSZ22, then 0050000, Project Item Line Number 0140, Materials Project AUSZ22, then 0050000, Project Item Line Number 0140, Materials See 10050008, Auszalians Project AUSZ22, then 0050000, Project Item Line Number 0140, Materials See 10050008, Auszalians Project AUSZ22, then 0050000, Project Item Line Number 0140, Materials See 10050008, Auszalians Project AUSZ22, then 0050000, Project Item Line Number 0140, Materials See 10050008, Auszalians Project AUSZ22, then 0050000, Project Item Line Number 0140, Materials See 10050008, Auszalians See 100500008, Auszalians See 10050008, Auszalians See 100500008, Auszalians See 100500008, Auszalians See 10050008, Auszalians Se	Number 1500, Material Set 502130896, Material 1005FACCNSCA - Natural Sand for Conc Class A,	Aggregate material testing needs to be reported	kloepj1	Overridden
Number 1970, Material Set 6000000000000000000000000000000000000	Number 1550, Material Set 502134096, Material 1005FACCNSCA - Natural Sand for Conc Class A,	Aggregate material testing needs to be reported	kloepj1	Overridden
Number 010, Material Set 60800080, Material 1027.MTBEA2016 - The Bar Ep Cid 30 YN 0.5M16 G* 000M2000, Acceptance Action Generic Notice RenforcingMiss in simulficient. Estimate Exception Type: Insufficient Materials: Project J082222, leme 0082011, Project liber Line Number 1020, Material Set 609101200, Project Misson Line Acceptance Action Generic Observable, Material Set 61910100, Material Set 609101200, Project J082222, leme 11910100, Project Ibern Line Number 5044, Material Set 61910100, Material Set 619000, Material Set 6190000, Material Set 619000	Number 1570, Material Set 606106096, Material 1065DE - Delineators, Acceptance Action Generic	Waiting on the material report based off certification	kloepj1	Overridden
Number 0440. Material Set 09011-0208. Material 05011CGB. A Concrete, Class B wider, Acceptance Action Genetic 0501CGB. As insufficient. Estimate Exception Type: Insufficient Materials: Project JBI2222, Item 6060201, Project Item Line Number 1200, Material 05011CGB. As insufficient. Estimate Exception Type: Insufficient Materials: Project JBI2222, Item 6060200, Project Item Line Number 1400, Material Set 06002008, Material 050810CBL Paved Drainage Material for Ditch Liner, Acceptance Action Genetic 050910CBL insufficient Materials: Project JBI2222, Item 6060200, Project Item Line Number 1400, Material Set 16006000B, Material 050810CBL Paved Drainage Material for Ditch Liner, Acceptance Action Genetic 050910CBL insufficient Materials: Project JBI2222, Item 6116010A, Project Item Line Number 0404, Material Set 1600600B, Material 050810. Project JBI2222, Item 6116010A, Project Item Line Number 0404, Material Set 1600600B, Material 050810. OPTIO. 1 Project JBI2222, Item 6116010A, Project Item Line Action Genetic 050910CBL as insufficient. Estimate Exception Type: Insufficient Materials: Project JBI2222, Item 6116010A, Project Item Line Action Genetic 050510. OPTIO. 1 Insufficient Materials: Project JBI2222, Item 614000A, Acceptance Action Genetic 100510. OPTIO. 1 Insufficient Materials: Project JBI2222, Item 614000A, Project Item Line Number 0508, Material 051406A, Material 05140B, OPTIO. 1 Project JBI2222, Item 61400A, Acceptance Action Genetic 050510. OPTIO. 1 Insufficient Materials: Project JBI2222, Item 61400A, Project Item Line Number 0508, Material 05140B, Material 05140B, Material 05140B, Acceptance Action Genetic 050510. OPTIO. 1 Insufficient Materials: Project JBI2222, Item 61400A, Project Item Line Number 0508, Material 05140B, Material 05140B, Acceptance Action Genetic 05050A, Material 05140B, Material 05140B, Acceptance Action Genetic 05050A,	Number 0410, Material Set 608500896, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr	Waiting on PAL	kloepj1	Overridden
Number 1520, Material Set 6090201108, Material 50510CEB. A : concrete, Class B Walfr, Acceptance Action Genetic 6007CEB. A is smitldent. Estimate Exception Type: Insufficient Materials: Project 812222, Item 6096020, Project Item Line Number 2600, Material 609610CB, Meterial 60960CB, Class B Walfr, Acceptance Action Genetic 60060PCD, is insufficient. Estimate Exception Type Insufficient Materials: Project 482222, Item 8116010A, Project Item Line Number 5044, Material Set 8118010AB6, Material 60961CB, a Concrete, Class B Walfr, Acceptance Action Genetic 6001CB, a Insufficient. Estimate Exception Type Insufficient Materials: Project 482222, Item 8146010A, Project Item Line Number 5004, Material 60960CB, Material 60960CB, Project Item Line Number 5008, Material 60960CB, Material 60960CB, Project Item Line Number 5008, Material 60960CB, Material 60	Number 0460, Material Set 609104296, Material 0501CCBA - Concrete, Class B w/Air, Acceptance	Waiting on 28 day break	kloepj1	Overridden
Number 0490, Material Set 609602096, Material 0698PDDL - Paved Drainage Material for Ditch Liner, Acceptance Action Generic 0699PDDL is insufficient. Estimate Exception Type Insufficient Materials: Project Ji802222, Item 6116010A, Project Item Line Number 5014, Material Set 6116010A96, Material 05010CB. A - Concrete, Class B w/Air, Acceptance Action Generic 05010CB. A is insufficient. Estimate Exception Type: Insufficient Materials: Project Ji802222, Item 6149002, Project Item Line Number 5014, Material Set 6116010A96, Material 105010. OPTLD 11 insufficient. Estimate Exception Type: Insufficient Materials: Project Ji802222, Item 6149002, Project Item Line Number 5014, Material Set 6116010A96, Material 106104PGTBP - Grates and Bearing Pfales, Acceptance Action Generic 05014PGTBP is insufficient. Estimate Exception Type: Insufficient Materials: Project Ji802222, Item 6149002, Project Item Line Number 5013, Material 106104PGTBP - Grates and Bearing Pfales, Acceptance Action Generic 0614PFINFCMSD in Material 106104PGTBP - Grates and Gearting Pfales, Acceptance Action Generic 0614PGTBP is insufficient. Estimate Exception Type: Insufficient Materials: Project Ji80222, Item 6149002, Project Item Line Number 5008, Material 501419FAINFCMSD in Material 6140PGTBP - Grates and Gearting Pfales, Acceptance Action Generic 0614PFINFCMSD is insufficient. Estimate Exception Type: Insufficient Materials: Project Ji80222, Item 6173000, Project Item Line Number 0615, Material 50140PGTBP - Grates and Generic 06090 (Set Ji8022), Item 6173000, Project Item Line Number 0615, Material 5010CGB1A is insufficient. Estimate Exception Type: Insufficient Materials: Project Ji802222, Item 6173000, Project Item Line Number 0615, Material 5010CGB1A is insufficient. Estimate Exception Type: Insufficient Materials: Project Ji802222, Item 624905, Project Item Line Number 0800, Material 5010CGB1A is insufficient. Estimate Exception Type: Insufficient Materials: Project Ji802222, Item 7011105, Project Item Line Number 5013, Material 5010CGB0	Number 1520, Material Set 609201196, Material 0501CCB. A - Concrete, Class B w/Air, Acceptance	Waiting on 28 day break	kloepj1	Overridden
Number 5044, Material Set 6116010A96, Material 0501CCB. A is numbficient. Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 6116010A, Project Item Line Number 5034, Material Set 6116010A, Baterial 10510.0PTLD 1 is insufficient. Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 6149902, Project Item Line Number 5030, Material Set 6149902, Material 0514DFGTBP - Grates and Bearing Plates, Acceptance Action Generic 05010.0PTLD 1 is insufficient. Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 6149902, Project Item Line Number 5030, Material Set 6149902, Material 0514DFGTBP - Grates and Bearing Plates, Acceptance Action Generic 0514DFGTBP is insufficient. Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 6149902, Project Item Line Number 5030, Material Set 6149902, Material 0514DFMNFCMSD - Mathole Frame and cover (M.S.D.), Acceptance Action Generic 0514DFMFMFCMSD is insufficient. Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 6173000, Project Item Line Number 0508, Material Set 61730006, Material 0514CDB1.4 is insufficient. Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 6173102, Project Item Line Number 0690, Material Set 61731026, Material 0514CDB1.4 is insufficient. Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 6173102, Project Item Line Number 0690, Material 36161731026, Material 0514CDB1.A is insufficient. Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 6749106, Project Item Line Number 0690, Material 36161731026, Material 36161706, Acceptance Action Generic 00904CDB1.DA is insufficient. Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7011105, Project Item Line Number 3090, Material Set 61731056, Material 3617011056, Material 0701FLCSLT - Drilled Shaft CSL steel pipe, Acceptance Action Generic 0701FLCSLT in sufficient. Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7011105, Pro	Number 0490, Material Set 609602096, Material 0609PDDL - Paved Drainage Material for Ditch Liner,	Waiting on the material report based off certification	kloepj1	Overridden
Number 5044, Material Set 6116010A99, Material 100510DPTLD1 is number 5044. Material Set 6116010A99, Material 100510DPTLD1 is number 5034. Material Set 61400902. Material 0614DFGTBP - Grates and Bearing Plates, Acceptance Action Generic 0714DFGTPP is number 5034. Material Set 61400902. Material 0614DFGTBP - Grates and Bearing Plates, Acceptance Action Generic 0714DFGTPP is insufficient. Materials: Project J8I2222, Item 6149902, Project Item Line Number 5008. Material Set 6149002. Material 0614DFMNFCMSD. Manhole Frame and cover (M.S.D.). Acceptance Action Generic 0714DFMNFCMSD is insufficient. Waterial Set 6149002. Material 0714DFMNFCMSD is insufficient. Waterial Set 6149002. Material 0714DFMNFCMSD is insufficient. Waterial Set 6149002. Material 0714DFMNFCMSD is insufficient. Waterial Set 617300098, Material 3611CGTB1 A - Concrete, Class B-1 wiAlr, Acceptance Action Generic 0715DFMNFCMSD is insufficient. Waterial Set 617300098, Material 3610CGB1 A - Concrete, Class B-1 wiAlr, Acceptance Action Generic 0715DFMNFCMSD is insufficient. Waterials Set 617300098, Material 3610CGB1 A - Concrete, Class B-1 wiAlr, Acceptance Action Generic 0715DGA100844 and Set 617300098, Material Set 617300098, Material Set 61730098, Material Set 7011058, Material 3099XX - See Remarks for Description of Material, Acceptance Action Generic 0719E0, Material 3099XX - See Remarks for Description of Material, Acceptance Action Generic 0719E0, Material Set 70111058, Material 3099XX - See Remarks for Description of Material Set 701110598, Material Set 701110598, Material 3099XX - See Remarks for Description of Material Set 701110598, Material Set 7011110598, Material Set 701110598, Material Set 701110598, Material Set 7	Number 5044, Material Set 6116010A96, Material 0501CCB. A - Concrete, Class B w/Air, Acceptance	Waiting on 28 day break	kloepj1	Overridden
Number 5003, Material 581 6149902, Material 0614DFGTBP - Grates and Bearing Plates, Acceptance Action Generic 0614DFGTBP is insufficient. Estimate Exception Type: Insufficient Materials: Project J0612222, Item 6149902, Project Item Line Number 5030, Material Set 16149920, Material Set 16149902, Material Set 16149904, Material Set 16149909, Material Set 16149909, Material Set 16149909, Material Set 16149910, Material Set 1614991, Material Set 16149	Number 5044, Material Set 6116010A96, Material 100510OPTLD1 - PCCP 1" Max LS/DO, Acceptance	Aggregate material testing needs to be reported	kloepj1	Overridden
Number 5008, Material Set 6149902, Material 0614DFMNFCMSD - Manhole Frame and cover (M.S.D.). Acceptance Action Generic of John Materials: Project J6i2222, Item 6173000, Project Item Line Number 0675, Material Set 617300066, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 6173102, Project Item Line Number 0680, Material Set 617300086, Material 100964DRL.DAA - Agg for Drainage Gr4 Alt A Limestone/DO, Acceptance Action Generic 100964DRL.DAA - Agg for Drainage Gr4 Alt A Limestone/DO, Acceptance Action Generic 100964DRL.DAA - Set Remarks for Description of Material Resident Exception Type: Insufficient Materials: Project J6i2222, Item 6249905, Project Item Line Number 0990, Material Set 624990596, Material 3099XX - See Remarks for Description of Material, Acceptance Action Generic 03999X is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 70111105, Project Item Line Number 9180, Material Set 701110596, Material 7071PLCSLT - Drilled Shaft CSL steel pipe, Acceptance Action Generic 0701PLCSLT is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 7011110, Project Item Line Number 9180, Material Set 701110596, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 701PLCSLT is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 7011110, Project Item Line Number 9480, Material Set 70111096, Material 0701PLCSLT - Drilled Shaft CSL steel pipe, Acceptance Action Generic 7071PLCSLT is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 7011110, Project Item Line Number 9480, Material Set 70111096, Material 701PLCSL - Drilled Shaft CSL steel pipe, Acceptance Action Generic 7071PLCSL is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 7011204, Project Item Line Number 9480, Material Set 70111096, Material 7019CPL	Number 5003, Material Set 6149902, Material 0614DFGTBP - Grates and Bearing Plates, Acceptance	Waiting on the material report based off certification	kloepj1	Overridden
Number 0675, Material Set 617300096, Material 0501CCB1.A is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 6173102, Project Item Line Number 0690, Material Set 617310296, Material 1009G4DRLDAA - Agg for Drainage Gr4 Alt A Limestone/DO, Acceptance Action Generic 1009G4DRLDAA is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 6249905, Project Item Line Number 0990, Material Set 624990596, Material 5180934, See Remarks for Description of Material, Acceptance Action Generic 3099X is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 62499059, Project Item Line Number 3180, Material Set 624990596, Material 30199X - See Remarks for Description of Material, Acceptance Action Generic 3099XX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011105, Project Item Line Number 3180, Material Set 701110596, Material 9019LCSLT - Drilled Shaft CSL steel pipe, Acceptance Action Generic 0701PLCSLT is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011105, Project Item Line Number 5013, Material Set 701110596, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 0705ECMLS is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011110, Project Item Line Number 3480, Material Set 701110596, Material 9019LCSLT - Drilled Shaft CSL steel pipe, Acceptance Action Generic 0701PLCSL is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011110, Project Item Line Number 3480, Material Set 701111096, Material 9019LCSL - Casing for Drilled Shafts, Acceptance Action Generic 0701PLCSL is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011204, Project Item Line Number 3490, Material Set 701110946, Material 9019LCSL - Casing for Drilled Shafts, Acceptance Action Generic 0701PLCSL is insufficient. Estimate Exception Type: Insufficient	Number 5008, Material Set 6149902, Material 0614DFMNFCMSD - Manhole Frame and cover (M.S.D.),	Waiting on the material report based off certification	kloepj1	Overridden
Number 0690, Material Set 617310296, Material 1009G4DRLDAA - Agg for Drainage Gr4 Alt A Limestone/DO, Acceptance Action Generic 1009G4DRLDAA is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 7011105, Project Item Line Number 0990, Material Set 624990596, Material 3099XX - See Remarks for Description of Material, Acceptance Action Generic 3099XX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 7011105, Project Item Line Number 3180, Material Set 701110586, Material 7019PLCSLT - Drilled Shaft CSL steel pipe, Acceptance Action Generic 0701PLCSLT is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 7011105, Project Item Line Number 3103, Material Set 701110586, Material 105GECMLS - Masonny Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 7011110, Project Item Line Number 3400, Material Set 701110986, Material Set 701110586, Material 54001PLCSLT - Drilled Shaft CSL steel pipe, Acceptance Action Generic 0701PLCSLT is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 7011110, Project Item Line Number 3400, Material Set 701111098, Material 701PLCA - Casing for Drilled Shafts, Acceptance Action Generic 0701PLCSLT is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 7011104, Project Item Line Number 3190, Material Set 70111204, Project J6i2222, Item 7011204, Project Item Line Number 3190, Material Set 701110486, Material 1005GECMLD - Masonny Grade D LS/DO, Acceptance Action Generic 1005GECMLD is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 7011204, Project Item Line Number 5014, Material Set 701120486, Material 41005GECMLS - Masonny Grade E LS/DO, Acceptance Action Generic 1005GECMLD is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 7011204, Project Item Line Number 50	Number 0675, Material Set 617300096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance	Waiting on 28 day break	kloepj1	Overridden
Number 0990, Material Set 624990596, Material 3099XX - See Remarks for Description of Material, Acceptance Action Generic 3099XX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011105, Project Item Line Number 3180, Material Set 701110596, Material 0701PLCSLT - Drilled Shaft CSL steel pipe, Acceptance Action Generic 0701PLCSLT is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011105, Project Item Line Number 5013, Material Set 701110596, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011110, Project Item Line Number 3480, Material Set 701111096, Material O701PLCSLT - Drilled Shaft CSL steel pipe, Acceptance Action Generic 0701PLCSLT is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011110, Project Item Line Number 3480, Material Set 701111096, Material Set 70111096, Material Set 70112049, Project Item Line Number 3490, Material Set 701120496, Material Set	Number 0690, Material Set 617310296, Material 1009G4DRLDAA - Agg for Drainage Gr4 Alt A	Aggregate material testing needs to be reported	kloepj1	Overridden
Number 3180, Material Set 701110596, Material 0701PLCSLT - Drilled Shaft CSL steel pipe, Acceptance Action Generic 0701PLCSLT is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011105, Acceptance Action Generic 1005GECMLS is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011110, Project Item Line Number 3480, Material Set 701111096, Material 0701PLCSLT - Drilled Shaft CSL steel pipe, Acceptance Action Generic 0701PLCSLT is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011110, Project Item Line Number 3480, Material Set 701111096, Material 0701PLCSLT - Drilled Shaft CSL steel pipe, Acceptance Action Generic 0701PLCSLT is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011110, Project Item Line Number 3480, Material Set 701111096, Material 0701PLCA - Casing for Drilled Shafts, Acceptance Action Generic 0701PLCA is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011204, Project Item Line Number 3190, Material Set 701120496, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011204, Project Item Line Number 5014, Material Set 701120496, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011204, Project Item Line Number 5014, Material Set 701120496, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011209, Project Item Line Aggregate material testing needs to be reported kloepj1 Overridden Voerridden Aggregate material testing needs to be reported Noerridden Aggregate material testing needs to be reported	Number 0990, Material Set 624990596, Material 3099XX - See Remarks for Description of Material,	Aggregate material testing needs to be reported	kloepj1	Overridden
Number 5013, Material Set 701110596, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011110, Project Item Line Number 3480, Material Set 701111096, Material O701PLCSLT - Drilled Shaft CSL steel pipe, Acceptance Action Generic 0701PLCSLT is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011110, Project Item Line Number 3480, Material Set 701111096, Material 0701PLCA - Casing for Drilled Shafts, Acceptance Action Generic 0701PLCA is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011204, Project Item Line Number 3190, Material Set 701120496, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011204, Project Item Line Number 3190, Material Set 701120496, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011204, Project Item Line Number 5014, Material Set 701120496, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011209, Project Item Line Aggregate material testing needs to be reported kloepj1 Overridden Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011209, Project Item Line Aggregate material testing needs to be reported	Number 3180, Material Set 701110596, Material 0701PLCSLT - Drilled Shaft CSL steel pipe,	Waiting on the material report based off certification	kloepj1	Overridden
Number 3480, Material Set 701111096, Material 0701PLCSLT - Drilled Shaft CSL steel pipe, Acceptance Action Generic 0701PLCSLT is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 7011110, Project Item Line Number 3480, Material Set 701111096, Material 0701PLCA - Casing for Drilled Shafts, Acceptance Action Generic 0701PLCA is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 7011204, Project Item Line Number 3190, Material Set 701120496, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 7011204, Project Item Line Number 5014, Material Set 701120496, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 7011209, Project Item Line Aggregate material testing needs to be reported kloepj1 Overridden Aggregate material testing needs to be reported kloepj1 Overridden Aggregate material testing needs to be reported kloepj1 Overridden Aggregate material testing needs to be reported kloepj1 Overridden	Number 5013, Material Set 701110596, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance	Aggregate material testing needs to be reported	kloepj1	Overridden
Number 3480, Material Set 701111096, Material 0701PLCA - Casing for Drilled Shafts, Acceptance Action Generic 0701PLCA is insufficient Materials: Project J6l2222, Item 7011204, Project Item Line Number 3190, Material Set 701120496, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011204, Project Item Line Number 5014, Material Set 701120496, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011209, Project Item Line Aggregate material testing needs to be reported kloepj1 Overridden Aggregate material testing needs to be reported kloepj1 Overridden Aggregate material testing needs to be reported kloepj1 Overridden	Number 3480, Material Set 701111096, Material 0701PLCSLT - Drilled Shaft CSL steel pipe,	Waiting on the material report based off certification	kloepj1	Overridden
Number 3190, Material Set 701120496, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011204, Project Item Line Number 5014, Material Set 701120496, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011209, Project Item Line Aggregate material testing needs to be reported kloepj1 Overridden	Number 3480, Material Set 701111096, Material 0701PLCA - Casing for Drilled Shafts, Acceptance	Waiting on the material report based off certification	kloepj1	Overridden
Number 5014, Material Set 701120496, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient. Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7011209, Project Item Line Aggregate material testing needs to be reported kloepj1 Overridden	Number 3190, Material Set 701120496, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance	Aggregate material testing needs to be reported	kloepj1	Overridden
	Number 5014, Material Set 701120496, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance	Aggregate material testing needs to be reported	kloepj1	Overridden
		Aggregate material testing needs to be reported	kloepj1	Overridden

Revision 4/1/2020 Page 13 of 100



Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Action Generic 1005GECMLS is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7019903, Project Item Line Number 1050, Material Set 7019903, Material 1010SGBF - Select Gran Backfill for Structural Sys, Acceptance Action Generic 1010SGBF is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7033009, Project Item Line Number 1060, Material Set 703300996, Material 1056TM - Tinting Material for Concrete, Acceptance Action Generic 1056TM is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7033009, Project Item Line Number 3420, Material Set 703300996, Material 1056TM - Tinting Material for Concrete, Acceptance Action Generic 1056TM is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7033009, Project Item Line Number 3440, Material Set 703300996, Material 1056TM - Tinting Material for Concrete, Acceptance Action Generic 1056TM is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7034003, Project Item Line Number 5026, Material Set 703400396, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7034003, Project Item Line Number 5026, Material Set 703400396, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7034212, Project Item Line Number 2670, Material Set 703421296, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Waiting on 28 day break	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7034212, Project Item Line Number 2670, Material Set 703421296, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Waiting on PAL	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 7034221, Project Item Line Number 3300, Material Set 703422196, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Waiting on PAL	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7034221, Project Item Line Number 3300, Material Set 703422196, Material 0501CCB2MDA - Concrete, Modified B-2 w/Air, Acceptance Action Generic 0501CCB2MDA is insufficient.	Waiting on 28 day break	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7034221, Project Item Line Number 5029, Material Set 703422196, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Waiting on PAL	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7034221, Project Item Line Number 5029, Material Set 703422196, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Waiting on 28 day break	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7034221, Project Item Line Number 5029, Material Set 703422196, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7034221, Project Item Line Number 5029, Material Set 703422196, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7034610, Project Item Line Number 2690, Material Set 703461096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Waiting on 28 day break	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7034610, Project Item Line Number 2690, Material Set 703461096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Waiting on PAL	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7040103, Project Item Line Number 2700, Material Set 704010396, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7040103, Project Item Line Number 2700, Material Set 704010396, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7040103, Project Item Line Number 2700, Material Set 704010396, Material 4066SPSM - Special Provision Special Mortar, Acceptance Action Generic 4066SPSM is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7040103, Project Item Line Number 2700, Material Set 704010396, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Waiting on 28 day break	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7040103, Project Item Line Number 2810, Material Set 704010396, Material 4066SPSM - Special Provision Special Mortar, Acceptance Action Generic 4066SPSM is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7040103, Project Item Line Number 2810, Material Set 704010396, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7040103, Project Item Line Number 2810, Material Set 704010396, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Waiting on 28 day break	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7040103, Project Item Line	Aggregate material testing needs to be reported	kloepj1	Overridden

Revision 4/1/2020 Page 14 of 100



Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Number 2810, Material Set 704010396, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7049904, Project Item Line Number 2720, Material Set 7049904, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7049904, Project Item Line Number 2720, Material Set 7049904, Material 4066SPSM - Special Provision Special Mortar, Acceptance Action Generic 4066SPSM is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7049904, Project Item Line Number 2830, Material Set 7049904, Material 4066SPSM - Special Provision Special Mortar, Acceptance Action Generic 4066SPSM is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7049904, Project Item Line Number 2830, Material Set 7049904, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7079901, Project Item Line Number 3350, Material Set 7079901, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7101000, Project Item Line Number 2730, Material Set 710100096, Material 1036RSSRECAB - Epoxy Ctd Sprl Stl Rein for Anch Bolts @, Acceptance Action Generic ReinforcingMisc is insufficient.	Waiting on PAL	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7101000, Project Item Line Number 5011, Material Set 710100096, Material 1036RSSRECAB - Epoxy Ctd Sprl Stl Rein for Anch Bolts @, Acceptance Action Generic ReinforcingMisc is insufficient.	Waiting on PAL	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7101000, Project Item Line Number 5015, Material Set 710100096, Material 1036RSSRECAB - Epoxy Ctd Sprl Stl Rein for Anch Bolts @, Acceptance Action Generic ReinforcingMisc is insufficient.	Waiting on PAL	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7101000, Project Item Line Number 5015, Material Set 710100096, Material 1036RSDFEC42M29 - Rein Steel EC No. 9/M29 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Waiting on PAL	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7101000, Project Item Line Number 5037, Material Set 710100096, Material 1036RSDFEC42M29 - Rein Steel EC No. 9/M29 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Waiting on PAL	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7101000, Project Item Line Number 5037, Material Set 710100096, Material 1036RSSRECAB - Epoxy Ctd Sprl Stl Rein for Anch Bolts @, Acceptance Action Generic ReinforcingMisc is insufficient.	Waiting on PAL	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7110200, Project Item Line Number 3355, Material Set 711020096, Material 1059PCECBP - Protective Coat Bents and Piers - Epoxy, Acceptance Action Generic 1059PCECBP is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7110200, Project Item Line Number 5038, Material Set 711020096, Material 1059PCECBP - Protective Coat Bents and Piers - Epoxy, Acceptance Action Generic 1059PCECBP is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7201000, Project Item Line Number 2940, Material Set 720100096, Material 0720MSEW - MSE Wall System -Bridge Approved Design, Acceptance Action Generic 0720MSEW is insufficient.	Waiting on Bridge to report the accepted MSE wall system submittal	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7201000, Project Item Line Number 2940, Material Set 720100096, Material 1010SGBF - Select Gran Backfill for Structural Sys, Acceptance Action Generic 1010SGBF is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7201000, Project Item Line Number 3430, Material Set 720100096, Material 1052MSEWMETS - Metalic Reinforcement Strips for MSE, Acceptance Action Generic 1052MSEWMETS is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7201000, Project Item Line Number 3430, Material Set 720100096, Material 0720MSEW - MSE Wall System -Bridge Approved Design, Acceptance Action Generic 0720MSEW is insufficient.	Waiting on Bridge to report the accepted MSE wall system submittal	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7201000, Project Item Line Number 3450, Material Set 720100096, Material 0720MSEW - MSE Wall System -Bridge Approved Design, Acceptance Action Generic 0720MSEW is insufficient.	Waiting on Bridge to report the accepted MSE wall system submittal	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7201000, Project Item Line Number 3450, Material Set 720100096, Material 1052MSEWMETS - Metalic Reinforcement Strips for MSE, Acceptance Action Generic 1052MSEWMETS is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7201000, Project Item Line Number 3450, Material Set 720100096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Waiting on 28 day break	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7201300, Project Item Line Number 3400, Material Set 7201300, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7201300, Project Item Line Number 3400, Material Set 7201300, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Waiting on 28 day break	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7250415, Project Item Line Number 5047, Material Set 725041596, Material 1020CPCSZC.015 - CulvPipe Zn Ctd Corrug Stl 15" 375mm, Acceptance Action Generic 1020CPCSZC.015 is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden

Revision 4/1/2020 Page 15 of 100



Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7250418, Project Item Line Number 5048, Material Set 725041896, Material 1020CPCSZC.018 - CulvPipe Zn Ctd Corrug Stl 18" 450mm, Acceptance Action Generic 1020CPCSZC.018 is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7269922, Project Item Line Number 5025, Material Set 7269922, Material 0200XXCS - Compacted Soil for Subgrade or Embankment, Acceptance Action Generic 0200XXCS is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7269922, Project Item Line Number 5025, Material Set 7269922, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Waiting on 28 day break	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7311053, Project Item Line Number 1190, Material Set 731105396, Material 1009G3DRLD - Agg for Drainage Gr3 Limestone/Dolomite, Acceptance Action Generic 1009G3DRLD is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 9017110, Project Item Line Number 1730, Material Set 901711096, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 9017401, Project Item Line Number 1740, Material Set 901740196, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 9017404, Project Item Line Number 1750, Material Set 901740496, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 9017407, Project Item Line Number 1760, Material Set 901740796, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 9018245, Project Item Line Number 1770, Material Set 901824596, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 9018245, Project Item Line Number 1770, Material Set 901824596, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Waiting on 28 day break	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 9019901, Project Item Line Number 1780, Material Set 9019901, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 9019902, Project Item Line Number 1830, Material Set 9019902, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 9019902, Project Item Line Number 1800, Material Set 9019902, Material 0902TSBTZCAB - Bolts Galv Anchor for Traffic Signals, Acceptance Action Generic 0902TSBTZCAB is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 9019902, Project Item Line Number 1820, Material Set 9019902, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Waiting on 28 day break	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 9019902, Project Item Line Number 1820, Material Set 9019902, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 9019902, Project Item Line Number 1820, Material Set 9019902, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 9020513, Project Item Line Number 1870, Material Set 902051396, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 9022708, Project Item Line Number 1910, Material Set 902270896, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 9022708, Project Item Line Number 1910, Material Set 902270896, Material 0902TSBTZCAB - Bolts Galv Anchor for Traffic Signals, Acceptance Action Generic 0902TSBTZCAB is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 9022708, Project Item Line Number 1910, Material Set 902270896, Material 1092TSPS - Traffic Signal Post(s) - All Types, Acceptance Action Generic 1092TSPS is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 9023255, Project Item Line Number 1960, Material Set 902325596, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 9024283, Project Item Line Number 1990, Material Set 902428396, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 9028311, Project Item Line Number 2060, Material Set 902831196, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 9029100, Project Item Line Number 2100, Material Set 902910096, Material 1005FACCNSCA - Natural Sand for Conc Class A,	Aggregate material testing needs to be reported	kloepj1	Overridden

Revision 4/1/2020 Page 16 of 100



Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Acceptance Action Generic 1005FACCNSCA is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 9031020, Project Item Line Number 2210, Material Set 903102096, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Waiting on 28 day break	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 9039901, Project Item Line Number 2330, Material Set 9039901, Material 0903HSSBPSST - Slip Base PSST Posts, Acceptance Action Generic 0903HSSBPSST is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 9039901, Project Item Line Number 2330, Material Set 9039901, Material 1080BRM - Bridge Material, Acceptance Action Generic 1080BRM is insufficient.	Waiting on Bridge to report material	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 9039901, Project Item Line Number 2330, Material Set 9039901, Material 0903HSOHTR - Overhead Truss Sign, Acceptance Action Generic 0903HSOHTR is insufficient.	Waiting on bridge to report material	kloepj1	Overridden
Estimate Exception Type: Item Overrun: Contract 200515-F15, Contract Project J6l2222, Project Item Line Number 2080, Contract Line Item Number 2080, Item 9028811, Minor Item.	Waiting on a change order to pay this item	kloepj1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 200515-F15, Contract Project J6l2222, Project Item Line Number 0710, Contract Line Item Number 0710, Item 6173600D, Minor Item.	Waiting on a change order to pay this item	kloepj1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 200515-F15, Contract Project J6l2222, Project Item Line Number 2020, Contract Line Item Number 2020, Item 9027300, Minor Item.	Waiting on a change order to pay this item	kloepj1	Acknowledged

Revision 4/1/2020 Page 17 of 100



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note: Posted Q	uantities	and valu	ies are	based on I	Report Generated date and can differ from the posted am	ount at the	time the Es	stimate was	Genera	ted.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200515-F15	J6I2222	0001	0010	2013000	CLEARING AND GRUBBING	2.00	0.00	2.00	ACRE	2.00	\$25,000.00	\$50,000.00
		0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.85	\$600,000.00	\$510,000.00
		0001	0025	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	155.00	0.00	155.00	SQFT	155.00	\$140.50	\$21,777.50
		0001	0040	2029901	MISC.REMOVAL OF ACM CONDUIT SYSTEM - TELEPHONE	1.00	0.00	1.00	LS	1.00	\$13,500.00	\$13,500.00
		0001	0045	2029903	MISC.MISCELLANEOUS ACM REMOVAL	80.00	0.00	80.00	LF	0.00	\$48.00	\$0.00
		0001	0050	2031000	CLASS A EXCAVATION	153,414.00	0.00	153,414.00	CUYD	143,072.00	\$15.00	\$2,146,080.00
		0001	0060	2036000	COMPACTING EMBANKMENT	106,637.00	11,081.00	117,718.00	CUYD	117,718.00	\$3.00	\$353,154.00
		0001	0070	2037075	COMPACTING IN CUT	45.00	0.00	45.00	STA	0.00	\$1.00	\$0.00
		0001	0080	2039901	MISC.STOCK PILE REMOVAL AT OLD 21ST STREET FOR MSD	1.00	0.00	1.00	LS	0.75	\$85,000.00	\$63,750.00
		0001	0090	2039907	MISC.Lightweight Fill	16,413.00	-16,413.00	0.00	CUYD	0.00	\$61.50	\$0.00
		0001	0100	2042010	SETTLEMENT GAUGE	10.00	0.00	10.00	EA	10.00	\$1,500.00	\$15,000.00
		0001	0110	2043010	PORE PRESSURE MEASURING DEVICE	3.00	0.00	3.00	EA	3.00	\$4,000.00	\$12,000.00
		0001	0120	2063000	CLASS 3 EXCAVATION	2,716.00	1,201.00	3,917.00	CUYD	3,416.00	\$15.00	\$51,240.00
		0001	0130	2071000	LINEAR GRADING CLASS 1	11.00	0.00	11.00	STA	3.00	\$800.00	\$2,400.00
		0001	0140	3040143	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	1,152.00	-64.00	1,088.00	SQYD	143.00	\$11.00	\$1,573.00
		0001	0150	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	72.00	0.00	72.00	SQYD	72.00	\$23.00	\$1,656.00
		0001	0160	3105003	GRAVEL (A) OR CRUSHED STONE (B)	540.00	2,888.00	3,428.00	SQYD	2,888.00	\$12.00	\$34,656.00
		0001	0170	4011207	BITUMINOUS PAVEMENT MIXTURE PG70-22, (BP-1)	1,950.80	0.00	1,950.80	TONS	0.00	\$77.75	\$0.00
		0001	0180	4030109	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125CLP MIX)	376.20	0.00	376.20	TONS	0.00	\$125.00	\$0.00
		0001	0190	4071005	TACK COAT	1,660.00	0.00	1,660.00	GAL	0.00	\$3.50	\$0.00
		0001	0200	5021108	CONCRETE PAVEMENT (8 IN. NON-REINF)	366.30	0.00	366.30	SQYD	366.30	\$49.00	\$17,948.70
		0001	0210	5021340	TYPE A2 SHOULDER	1,563.20	0.00	1,563.20	SQYD	519.96	\$36.00	\$18,718.56
		0001	0220	5041000	CONCRETE APPROACH PAVEMENT	105.20	0.00	105.20	SQYD	0.00	\$150.00	\$0.00
		0001	0230	6039901	WATER	1.00	0.00	1.00	LS	1.00	\$30,000.00	\$30,000.00
		0001	0240	6039901	WATER	1.00	0.00	1.00	LS	0.00	\$12,000.00	\$0.00
		0001	0250	6039903	WATER	20.00	0.00	20.00	LF	20.00	\$2,000.00	\$40,000.00
		0001	0260	6039903	WATER	150.00	7.00	157.00	LF	157.00	\$2,000.00	\$314,000.00
		0001	0270	6039903	WATER	570.00	-179.80	390.20	LF	390.20	\$400.00	\$156,080.00
		0001	0280	6039903	WATER	100.00	0.00	100.00	LF	100.00	\$400.00	\$40,000.00
		0001	0290	6049901	MISC.INSPECTION OF 9X7 CONCRETE ARCH SEWER	1.00	0.00	1.00	LS	0.00	\$6,000.00	\$0.00
		0001	0300	6049903	MISC.MODOT MANHOLE - ADJUST TO GRADE	24.00	0.00	24.00	LF	24.00	\$1,000.00	\$24,000.00
		0001	0310	6049903	MISC.MSD MANHOLE - ADJUST TO GRADE, 5' TO 10' RANGE	25.00	0.00	25.00	LF	18.40	\$1,000.00	\$18,400.00
		0001	0320	6049903	MISC.MSD MANHOLE - ADJUST TO GRADE, 10' TO 15' RANGE	23.00	0.00	23.00	LF	0.00	\$1,000.00	\$0.00
		0001	0330	6049903	MISC.MSD MANHOLE - ADJUST TO GRADE, 15' TO 20' RANGE	37.00	0.00	37.00	LF	18.20	\$1,000.00	\$18,200.00
		0001	0340	6049903	MISC.MSD MANHOLE - ADJUST TO GRADE, 25' TO 30' RANGE	28.00	0.00	28.00	LF	0.00	\$1,000.00	\$0.00
		0001	0350	6071012A	CHAIN-LINK FENCE (60 IN.)	586.00	0.00	586.00	LF	0.00	\$28.00	\$0.00
		0001	0360	6071040	DRIVE GATE (CHAIN-LINK)	2.00	0.00	2.00	EA	0.00	\$1,200.00	\$0.00
		0001	0370	6071050	CHAIN-LINK FENCE (RETAINING WALLS)	1,800.00	-963.00	837.00	LF	480.00	\$24.00	\$11,520.00
		0001	0380	6071102	MODIFIED CONCRETE GUTTER TYPE B	2,038.00	-1,085.00	953.00	LF	540.00	\$34.00	\$18,360.00
		0001	0390	6081012	TRUNCATED DOMES	60.00	0.00	60.00	SQFT	0.00	\$35.00	\$0.00
		0001	0400	6083006	6 IN. CONCRETE MEDIAN STRIP	529.80	0.00	529.80	SQYD	0.00	\$100.00	\$0.00
		0001	0410	6085008	PAVED APPROACH, 8 IN.	72.30	0.00	72.30	SQYD	72.30	\$125.00	\$9,037.50
		0001	0420	6086004	CONCRETE SIDEWALK, 4 IN.	1,152.10	-63.80	1,088.30	SQYD	142.40	\$51.00	\$7,262.40
		0001	0430	6086007	CONCRETE SIDEWALK, 7 IN.	15.30	-15.30	0.00	SQYD	0.00	\$65.00	\$0.00
		0001	0440	6089902	MISC.ADA CURB RAMP	16.00	0.00	16.00	EA	4.00	\$3,550.00	\$14,200.00
		0001	0450	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	301.00	0.00	301.00	LF	113.00	\$45.00	\$5,085.00
		0001	0460	6091042	CONCRETE GUTTER TYPE B	2,007.00	1,085.00	3,092.00	LF	268.00	\$30.00	\$8,040.00

Revision 4/1/2020 Page 18 of 100



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Report Generated date and can differ from the posted am Description	Bid Quantity	Net Change Order	Total Current Quantity	Generat Unit	Total Posted	Unit Price	Total Value POSTED
							Order	Quantity		Approved Qty		generated date)
00515-F15	J6I2222	0001	0470	6091060	PAVED DITCH	210.30	0.00	210.30	SQYD	0.00	\$81.00	\$0.00
		0001	0480	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	203.00	1,718.00	1,921.00	LF	181.00	\$15.00	\$2,715.00
		0001	0490	6096020	FURNISHING TYPE 2 ROCK DITCH LINER	24.00	233.40	257.40	CUYD	210.50	\$100.00	\$21,050.00
		0001	0500	6096042	PLACING TYPE 2 ROCK DITCH LINER	24.00	233.40	257.40	CUYD	210.50	\$100.00	\$21,050.00
		0001	0510	6097000	ROCK LINING	2.00	10.00	12.00	CUYD	0.00	\$1,000.00	\$0.0
		0001	0515	6099903	MISC.MODIFIED INTEGRAL CURB (2 IN. HEIGHT) TYPE A	320.00	0.00	320.00	LF	122.00	\$50.00	\$6,100.0
		0001	0520	6113020	FURNISHING TYPE 2 ROCK BLANKET	567.00	0.00	567.00	CUYD	0.00	\$48.00	\$0.0
		0001	0530	6113040	PLACING TYPE 2 ROCK BLANKET	567.00	0.00	567.00	CUYD	0.00	\$21.00	\$0.0
		0001	0540	6116010A	SLOPE PROTECTION	1.00	-1.00	0.00	SQYD	0.00	\$300.00	\$0.0
		0001	0550	6119907	MISC.Furnishing Modified Rock Blanket	1,151.00	0.00	1,151.00	CUYD	0.00	\$50.00	\$0.0
		0001	0560	6119907	MISC.Placing Modified Rock Blanket	1,151.00	0.00	1,151.00	CUYD	0.00	\$21.00	\$0.0
		0001	0570	6122012	IMPACT ATTENUATOR 55 MPH (SAND BARREL ARRAY)	5.00	0.00	5.00	EA	4.00	\$2,823.00	\$11,292.0
		0001	0580	6122020	REPLACEMENT SAND BARREL	12.00	0.00	12.00	EA	5.00	\$431.00	\$2,155.0
		0001	0590	6122030	IMPACT ATTENUATOR (RELOCATION)	9.00	0.00	9.00	EA	2.00	\$877.00	\$1,754.0
		0001	0600	6133020	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	148.50	0.00	148.50	TONS	0.00	\$62.00	\$0.0
		0001	0610	6133021	REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	528.50	0.00	528.50	SQYD	0.00	\$58.75	\$0.0
		0001	0620	6141024	GRATE AND BEARING PLATE (5 FT. X 3 FT. OR 1524 MM X 914 MM)	10.00	2.00	12.00	EA	4.00	\$1,400.00	\$5,600.0
		0001	0630	6141120	CURVED VANE GRATE AND FRAME (2 FT. X 2 FT. OR 600MM X 600MM)	72.00	-72.00	0.00	EA	0.00	\$700.00	\$0.0
		0001	0640	6149902	MISC.Parallel Grate and Bearing Plate (2 FT.x2FT.)	67.00	-57.00	10.00	EA	2.00	\$700.00	\$1,400.0
		0001	0650	6169901	MISC.TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.75	\$465,000.00	\$348,750.0
		0001	0660	6169902	MISC.MSD Manhole Frame and Cover	17.00	-17.00	0.00	EA	0.00	\$400.00	\$0.0
		0001	0670	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN (CONTRACTOR FURNISHED AND RETAINED)	8.00	0.00	8.00	EA	7.00	\$3,500.00	\$24,500.0
		0001	0675	6173000	CONCRETE TRAFFIC BARRIER, TYPE C	254.00	357.00	611.00	LF	485.00	\$145.00	\$70,325.0
		0001	0680	6173100	CONCRETE TRAFFIC BARRIER, TYPE D	1,787.00	-1,185.00	602.00	LF	0.00	\$90.00	\$0.0
		0001	0690	6173102	CONCRETE TRAFFIC BARRIER, TYPE D (RETAINING WALL)	2,413.00	1,085.00	3,498.00	LF	2,335.50	\$85.00	\$198,517.5
		0001	0700	6173103	CONCRETE TRAFFIC BARRIER, TYPE D (MOMENT SLAB)	440.00	0.00	440.00	LF	0.00	\$110.00	\$0.0
		0001	0710	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	2,488.00	0.00	2,488.00	LF	2,713.50	\$25.90	\$70,279.6
		0001	0720	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	4,013.00	0.00	4,013.00	LF	1,112.50	\$11.50	\$12,793.
		0001	0730	6179903	MISC.MODIFIED BARRIER WALL	315.00	0.00	315.00	LF	0.00	\$300.00	\$0.0
		0001	0740	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$2,269,999.84	\$0.0
		0001	0741	6181000	MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$2,162,092.84	\$2,162,092.8
		0001	0750	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	2.00	0.00	2.00	EA	0.00	\$600.00	\$0.0
		0001	0760	6189901	MISC.TEMPORARY RAILROAD CROSSING	1.00	0.00	1.00	LS	0.00	\$30,000.00	\$0.0
		0001	0765	6189916	MISC.ACCELERATING THE COMPLETION OF WORK REQUIRING RAILROAD FLAGGERS (INCENTIVE/DISINCENTIVE CLAUSE)	1,000.00	0.00	1,000.00	DLR	0.00	\$0.00	\$0.0
		0001	0770	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	505.00	0.00	505.00	LF	0.00	\$25.00	\$0.
		0001	0780	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	19.00	0.00	19.00	EA	0.00	\$320.00	\$0.
		0001	0790	6200027	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT	7.00	0.00	7.00	EA	0.00	\$450.00	\$0.0
		0001	0800	6200030	PREFORMED THERMOPLASTIC PAVEMENT MARKING, WORD (ONLY)	9.00	0.00	9.00	EA	0.00	\$450.00	\$0.0
		0001	0810	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	114.00	0.00	114.00	EA	0.00	\$200.00	\$0.0
		0001	0820	6200042	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	14.00	0.00	14.00	EA	0.00	\$50.00	\$0.
		0001	0830	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	21,905.00	0.00	21,905.00	LF	0.00	\$0.50	\$0.
		0001	0840	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	12,373.00	0.00	12,373.00	LF	0.00	\$0.50	\$0.
		0001	0850	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	4,999.00	0.00	4,999.00	LF	0.00	\$1.00	\$0.0
		0001	0860	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING	9,364.00	0.00	9,364.00	LF	0.00	\$0.50	\$0.0

Revision 4/1/2020 Page 19 of 100



Total Paid / All Items / All Estimates (Including this Estimate)

lote: Posted Qi	uantities	and Valu	ies are	based on F	Report Generated date and can differ from the posted am	ount at the	time the Es	timate was	Generat	ea.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200515-F15	J6I2222				PAINT, TYPE P BEADS					,		
		0001	0870	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	3,485.00	0.00	3,485.00	LF	0.00	\$0.50	\$0.00
		0001	0880	6206124A	24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	91.00	0.00	91.00	LF	0.00	\$10.00	\$0.00
		0001	0890	6206125A	24 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	84.00	0.00	84.00	LF	0.00	\$10.00	\$0.00
		0001	0900	6207001	PAVEMENT MARKING REMOVAL	7,291.00	0.00	7,291.00	LF	0.00	\$1.00	\$0.00
		0001	0910	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	56.00	0.00	56.00	EA	0.00	\$50.00	\$0.00
		0001	0920	6209902	MISC.ISLAND TUBULAR MARKER	8.00	0.00	8.00	EA	0.00	\$110.00	\$0.00
		0001	0930	6209902	MISC.PREFORMED THERMOPLASTIC PAVEMENT MARKING, LANE REDUCTION ARROW	8.00	0.00	8.00	EA	0.00	\$2,000.00	\$0.00
		0001	0940	6209902	MISC.TIER TWO INLAID PAVEMENT MARKER SYSTEM	8.00	0.00	8.00	EA	0.00	\$4,475.00	\$0.00
		0001	0950	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	2,356.00	0.00	2,356.00	SQYD	0.00	\$6.75	\$0.00
		0001	0960	6221003	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (GREATER THAN 3 IN. THICK)	10,196.00	0.00	10,196.00	SQYD	0.00	\$3.85	\$0.00
		0001	0970	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	150.00	0.00	150.00	SQYD	0.00	\$13.50	\$0.00
		0001	0980	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	3,917.00	172.10	4,089.10	SQYD	906.40	\$3.00	\$2,719.20
		0001	0990	6249905	MISC.Miscellaneous Granular Drainage Blanket	2,115.00	286.00	2,401.00	SQYD	2,401.00	\$15.50	\$37,215.50
		0001	1000	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.65	\$125,000.00	\$81,250.00
		0001	1010	7011105	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	30.00	0.00	30.00	LF	0.00	\$415.00	\$0.00
		0001	1020	7011107	DRILLED SHAFTS (4 FT. 6 IN. DIA.)	39.00	0.00	39.00	LF	0.00	\$415.00	\$0.00
		0001	1030	7011207	ROCK SOCKETS (4 FT 6 IN. DIA.)	6.00	0.00	6.00	LF	0.00	\$415.00	\$0.00
		0001	1040	7011600	SONIC LOGGING TESTING	1.00	0.00	1.00	EA	0.00	\$1,000.00	\$0.00
		0001	1050	7019903	MISC.Miscellaneous Stone Columns	6,535.00	-5,583.00	952.00	LF	952.00	\$25.00	\$23,800.00
		0001	1060	7033009	AESTHETIC CONCRETE STAIN	1.00	0.00	1.00	LS	1.00	\$6,110.88	\$6,110.88
		0001	1080	7061000	REINFORCING STEEL	5,740.00	0.00	5,740.00	LB	0.00	\$1.60	\$0.00
		0001	1090	7201000	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	3,394.00	0.00	3,394.00	SQFT	3,394.00	\$60.00	\$203,640.00
		0001	1100	7201200	SELECT GRANULAR BACKFILL FOR STRUCTURAL SYSTEMS	12,416.00	-478.00	11,938.00	CUYD	11,938.00	\$30.00	\$358,140.00
		0001	1110	7261015	15 IN. PIPE GROUP A	3,631.00	-921.00	2,710.00	LF	1,886.00	\$70.00	\$132,020.00
		0001	1120	7261018	18 IN. PIPE GROUP A	1,252.00	-169.00	1,083.00	LF	888.00	\$80.00	\$71,040.00
		0001	1130	7261024	24 IN. PIPE GROUP A	118.00	-118.00	0.00	LF	0.00	\$135.00	\$0.00
		0001	1140	7261030	30 IN. PIPE GROUP A	298.00	67.00	365.00	LF	365.00	\$250.00	\$91,250.00
		0001	1150	7261036	36 IN. PIPE GROUP A	54.00	0.00	54.00	LF	54.00	\$400.00	\$21,600.00
		0001	1160	7279901	MISC.MSD SPECIAL DRAINAGE STRUCTURE #"301"	1.00	0.00	1.00	LS	1.00	\$55,000.00	\$55,000.00
		0001	1170	7311022	PRECAST CONCRETE DROP INLET 2 FT X 2 FT	57.00	0.00	57.00	FT	40.00	\$350.00	\$14,000.00
		0001	1180	7311042	PRECAST CONCRETE DROP INLET 4 FT X 2 FT	178.00	-11.00	167.00	FT	133.00	\$450.00	\$59,850.00
		0001	1190	7311053	PRECAST CONCRETE DROP INLET 5 FT X 3 FT	56.00	18.00	74.00	FT	55.00	\$650.00	\$35,750.00
		0001	1200	7319913	MISC.MSD Standard 60" Manhole	56.00	1.00	57.00	FT	57.00	\$510.00	\$29,070.00
		0001	1210	7319913	MISC.MSD Standard Line 48" Manhole	76.00	7.00	83.00	FT	83.00	\$350.00	\$29,050.00
		0001	1220	7320615A	15 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	1.00	8.00	9.00	EA	9.00	\$800.00	\$7,200.00
		0001	1230	7320624A	24 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	2.00	-2.00	0.00	EA	0.00	\$1,000.00	\$0.00
		0001	1240	7320630A	30 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	1.00	0.00	1.00	EA	1.00	\$1,500.00	\$1,500.00
		0001	1245	8031000A	TURF TYPE TALL FESCUE SODDING	1,242.00	0.00	1,242.00	SQYD	0.00	\$8.50	\$0.00
		0001	1260	8059919	MISC.WARM OR COOL SEASON MIXTURES	9.00	0.00	9.00	ACRE	0.00	\$1,975.00	\$0.00
		0001	1270	8061003	SEDIMENT TRAP EXCAVATION	57.00	0.00	57.00	CUYD	0.00	\$25.00	\$0.00
		0001	1280	8061004	SEDIMENT TRAP ROCK	7.00	0.00	7.00	CUYD	0.00	\$100.00	\$0.00
		0001	1290	8061005	ROCK DITCH CHECK	2,613.00	0.00	2,613.00	LF	24.00	\$10.50	\$252.00
		0001	1300	8061007A	CURB INLET CHECK	111.00	0.00	111.00	EA	0.00	\$115.00	\$0.00
		0001	1310	8061016	SEDIMENT REMOVAL	267.00	0.00	267.00	CUYD	224.00	\$25.00	\$5,600.00

Revision 4/1/2020 Page 20 of 100



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract	Project	Category	Line	Item	Report Generated date and can differ from the posted am Description	Bid	Net	Total	General Unit	Total	Unit Price	Total Value POSTED
Nm.CONTRACT	No.		No.	Code		Quantity	Change Order	Current Quantity		Posted Approved Qty		To Date (See report generated date)
200515-F15	J6I2222	0001	1320	8061017	TEMPORARY SEEDING AND MULCHING	14.00	0.00	14.00	ACRE	1.60	\$1,500.00	\$2,400.00
		0001	1330	8061019	SILT FENCE	8,207.00	0.00	8,207.00	LF	2,340.00	\$2.25	\$5,265.00
		0001	1340	8064128	TYPE 1 TURF REINFORCEMENT MAT	913.00	0.00	913.00	SQYD	0.00	\$5.15	\$0.00
		0002	1350	3030600	FURNISHING ROCK BASE MATERIAL	3,355.00	0.00	3,355.00	SQYD	0.00	\$0.00	\$0.00
		0002	1360	3030610A	PLACING ROCK BASE	3,355.00	0.00	3,355.00	SQYD	0.00	\$0.00	\$0.00
		0002	1370	4030419	9 INCHES, ASPHALTIC CONCRETE PAVEMENT SP125CLP	2,073.00	0.00	2,073.00	SQYD	0.00	\$0.00	\$0.00
		0003	1380	3030600	FURNISHING ROCK BASE MATERIAL	3,363.00	0.00	3,363.00	SQYD	0.00	\$10.50	\$0.00
		0003	1390	3030610A	PLACING ROCK BASE	3,363.00	0.00	3,363.00	SQYD	0.00	\$5.50	\$0.00
		0003	1400	5021332	CONCRETE PAVEMENT (8 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)	2,073.00	0.00	2,073.00	SQYD	0.00	\$51.00	\$0.00
		0004	1410	4010150	TYPE A2 SHOULDER	206.10	0.00	206.10	SQYD	0.00	\$0.00	\$0.00
		0004	1420	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	304.00	0.00	304.00	LF	0.00	\$0.00	\$0.00
		0005	1430	5021340	TYPE A2 SHOULDER	206.10	0.00	206.10	SQYD	0.00	\$35.50	\$0.00
		0005	1440	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	304.00	0.00	304.00	LF	0.00	\$20.00	\$0.00
		0006	1450	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	20,740.00	0.00	20,740.00	SQYD	0.00	\$0.00	\$0.00
		0006	1460	4039905	MISC.11.5 INCHES, ASPHALTIC CONCRETE PAVEMENT SP125CLP	10,939.00	0.00	10,939.00	SQYD	0.00	\$0.00	\$0.00
		0006	1470	4039905	MISC.9.5 INCHES, ASPHALTIC CONCRETE PAVEMENT SP125CLP	6,859.00	0.00	6,859.00	SQYD	0.00	\$0.00	\$0.00
		0006	1480	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	2,017.00	0.00	2,017.00	LF	0.00	\$0.00	\$0.00
		0007	1490	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	20,910.00	-323.00	20,587.00	SQYD	14,680.67	\$6.50	\$95,424.36
		0007	1500	5021308	CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. JOINTS)	6,859.00	0.00	6,859.00	SQYD	6,019.00	\$51.00	\$306,969.00
		0007	1510	5021309	CONCRETE PAVEMENT (9 IN. NON-REINFORCED 15 FT. JOINTS)	10,939.00	-323.00	10,616.00	SQYD	4,396.90	\$54.00	\$237,432.60
		0007	1520	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	2,017.00	-1,225.00	792.00	LF	210.00	\$15.00	\$3,150.00
		0008	1530	4010150	TYPE A2 SHOULDER	3,806.80	0.00	3,806.80	SQYD	0.00	\$0.00	\$0.00
		0008	1540	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	3,319.00	0.00	3,319.00	LF	0.00	\$0.00	\$0.00
		0009	1550	5021340	TYPE A2 SHOULDER	3,806.80	0.00	3,806.80	SQYD	3,170.47	\$35.00	\$110,966.45
		0009	1560	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	3,319.00	-2,667.00	652.00	LF	512.00	\$15.00	\$7,680.00
		0010	1570	6061060	MGS GUARDRAIL	3,813.00	-62.00	3,751.00	LF	463.00	\$19.00	\$8,797.00
		0010	1580	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED	2.00	0.00	2.00	EA	0.00	\$2,850.00	\$0.00
		0010	1590	6061069	CURB) MGS BRIDGE APPROACH TRANSITION SECTION	2.00	0.00	2.00	EA	0.00	\$2,800.00	\$0.00
		0010	1600	6061070	(REGULAR/NO CURB) MGS VERTICAL CONCRETE BARRIER TRANSITION	11.00	0.00	11.00	EA	4.00	\$2,750.00	\$11,000.00
		0010	1610	6061080	MGS END ANCHOR	8.00	0.00	8.00	EA	1.00	\$1,000.00	\$1,000.00
		0010	1620		TYPE A CRASHWORTHY END TERMINAL (MASH)	12.00	0.00	12.00	EA	4.00	\$2,600.00	\$10,400.00
		0010	1630	6063019	TYPE E CRASHWORTHY END TERMINAL	1.00	0.00	1.00	EA	0.00	\$27.500.00	\$0.00
		0020	1640	9011330	LUMINAIRE. 1000 WATT HIGH PRESSURE SODIUM HIGH MAST	16.00	0.00	16.00	EA	0.00	\$1,018.00	\$0.00
		0020	1650	9013002	CONDUIT, 2 IN. RIGID, IN TRENCH	26.00	0.00	26.00	LF	0.00	\$10.45	\$0.00
		0020	1660	9013003	CONDUIT, 3 IN. RIGID, IN TRENCH	282.00	0.00	282.00	LF	120.00	\$11.00	\$1,320.00
		0020	1670	9013004	CONDUIT. 4 IN, RIGID. IN TRENCH	23.00	0.00	23.00	LF	0.00	\$12.35	\$0.00
		0020	1680	9014004	CONDUIT, 4 IN. RIGID, PUSHED	339.00	0.00	339.00	LF	0.00	\$26.60	\$0.00
		0020	1690	9015010	TRENCHING TYPE I	2,136.00	0.00	2,136.00	LF	949.00	\$3.80	\$3,606.20
		0020	1700	9015020	TRENCHING TYPE II	237.00	0.00	237.00	LF	106.00	\$3.80	\$402.80
		0020	1710	9016110	PULL BOX, PREFORMED CLASS 1	15.00	0.00	15.00	EA	5.00	\$765.00	\$3,825.00
		0020	1720	9016112	PULL BOX, PREFORMED CLASS 3	2.00	0.00	2.00	EA	1.00	\$1,343.00	\$1,343.00
		0020	1730	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	360.00	0.00	360.00	LF	360.00	\$0.55	\$198.00
		0020	1740	9017401	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE	800.00	0.00	800.00	LF	800.00	\$6.00	\$4,800.00
		0020	1750	9017404	NEUTRAL, 2 AWG CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE	2,190.00	0.00	2,190.00	LF	336.00	\$3.60	\$1,209.60
					NEUTRAL, 6 AWG							
		0020	1760	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	1,010.00	0.00	1,010.00	LF	310.00	\$2.90	\$899.00

Revision 4/1/2020 Page 21 of 100



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract	Project	Category	Line	Item	Report Generated date and can differ from the posted am Description	Bid	Net	Total	Generat Unit	Total	Unit Price	Total Value POSTED
Nm.CONTRACT	No.		No.	Code		Quantity	Change Order	Current Quantity		Posted Approved Qty		To Date (See report generated date)
200515-F15	J6I2222	0020	1770	9018245	POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	4.00	0.00	4.00	EA	4.00	\$1,068.00	\$4,272.00
		0020	1780	9019901	MISC.EXTERNAL CONDUIT SYSTEM ON STRUCTURE	1.00	0.00	1.00	LS	1.00	\$16,605.00	\$16,605.00
		0020	1790	9019902	MISC.150 FT HIGH MAST POLE	2.00	0.00	2.00	EA	0.00	\$34,530.00	\$0.00
		0020	1800	9019902	MISC.45 FT TOP MOUNT POLES, TYPE AT	4.00	0.00	4.00	EA	4.00	\$2,250.00	\$9,000.00
		0020	1810	9019902	MISC.ADJUST PULL BOX TO GRADE	1.00	0.00	1.00	EA	0.00	\$483.00	\$0.00
		0020	1820	9019902	MISC.BASE MOUNTED 240/480V COMBINATION POWER SUPPLY AND CONTROLLER	2.00	0.00	2.00	EA	0.33	\$7,258.00	\$2,395.14
		0020	1830	9019902	MISC.LED-C TOP-MOUNT LUMINAIRE	4.00	0.00	4.00	EA	4.00	\$572.00	\$2,288.00
		0020	1840	9019903	MISC.1 IN RIGID GALVANIZED STEEL CONDUIT	549.00	0.00	549.00	LF	0.00	\$15.85	\$0.00
		0020	1850	9019903	MISC.THHN CABLE 2C #6 AWG	1,830.00	0.00	1,830.00	LF	0.00	\$1.65	\$0.00
		0030	1860	9020213	SIGNAL HEAD, TYPE 3S	3.00	0.00	3.00	EA	0.00	\$761.00	\$0.00
		0030	1870	9020513	SIGNAL HEAD, TYPE 3B	37.00	0.00	37.00	EA	5.00	\$927.00	\$4,635.00
		0030	1880	9020514	SIGNAL HEAD, TYPE 4B	3.00	0.00	3.00	EA	0.00	\$1,038.00	\$0.00
		0030	1890	9020833	SH-FLAT SHEET - SIGNAL SIGN	133.00	15.00	148.00	SQFT	0.00	\$12.50	\$0.00
		0030	1900	9020834	SIGNAL SIGN, MOUNTING HARDWARE	41.00	2.00	43.00	EA	0.00	\$33.00	\$0.00
		0030	1910	9022708	POST, SIGNAL 8 FT. OR 2.4 M	18.00	0.00	18.00	EA	3.00	\$645.00	\$1,935.00
		0030	1920	9022715	POST, SIGNAL 15 FT. OR 4.6 M	1.00	0.00	1.00	EA	0.00	\$972.00	\$0.00
		0030	1930	9023230	POST, TYPE C, 30 FT. ARM OR 9.1 M ARM	1.00	0.00	1.00	EA	0.00	\$7,324.00	\$0.00
		0030	1940	9023235	POST, TYPE C, 35 FT. ARM OR 10.7 M ARM	1.00	0.00	1.00	EA	0.00	\$7,532.00	\$0.00
		0030	1950	9023250	POST, TYPE C, 50 FT. ARM OR 15.2 M ARM	1.00	0.00	1.00	EA	0.00	\$10,292.00	\$0.00
		0030	1960	9023255	POST, TYPE C, 55 FT. ARM	4.00	0.00	4.00	EA	1.00	\$11,930.00	\$11,930.00
		0030	1970	9023335	POST, TYPE B, LONGEST ARM 35 FT. OR 10.7 M	1.00	-1.00	0.00	EA	0.00	\$12,945.00	\$0.00
		0030	1980	9023345	POST, TYPE B, LONGEST ARM 45 FT. OR 13.7 M	1.00	-1.00	0.00	EA	0.00	\$12,439.00	\$0.00
		0030	1990	9024283	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	3.00	0.00	3.00	EA	1.00	\$13,359.00	\$13,359.00
		0030	2000	9024975	VIDEO DETECTION SYSTEM	4.00	0.00	4.00	EA	0.00	\$12,698.00	\$0.00
		0030	2010	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	1,320.00	14.00	1,334.00	LF	637.00	\$10.20	\$6,497.40
		0030	2020	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	844.00	0.00	844.00	LF	871.00	\$23.00	\$20,033.00
		0030	2030	9028208	CABLE, 8 AWG 1 CONDUCTOR, POWER	3,350.00	41.00	3,391.00	LF	0.00	\$0.95	\$0.00
		0030	2040	9028308	CABLE, 16 AWG 2 CONDUCTOR	3,730.00	-285.00	3,445.00	LF	0.00	\$0.50	\$0.00
		0030	2050	9028310	CABLE, 16 AWG 5 CONDUCTOR	3,750.00	-287.00	3,463.00	LF	0.00	\$1.10	\$0.00
		0030	2060	9028311	CABLE, 16 AWG 7 CONDUCTOR	6,790.00	-343.00	6,447.00	LF	1,176.00	\$1.60	\$1,881.60
		0030	2070	9028810	PULL BOX, PREFORMED CLASS 1	10.00	0.00	10.00	EA	2.00	\$602.00	\$1,204.00
		0030	2080	9028811	PULL BOX, PREFORMED CLASS 2	8.00	0.00	8.00	EA	10.00	\$1,221.00	\$12,210.00
		0030	2090	9028812	PULL BOX, PREFORMED CLASS 3	3.00	0.00	3.00	EA	1.00	\$1,642.00	\$1,642.00
		0030	2100	9029100	BASE, CONCRETE	44.00	-1.00	43.00	CUYD	10.30	\$1,160.00	\$11,948.00
		0030	2110	9029901	MISC.TRAFFIC SIGNAL MAINTENANCE AND PROGRAMMING	1.00	0.00	1.00	LS	0.35	\$65,520.00	\$22,932.00
		0030	2120	9029902	MISC.ATC TRAFFIC SIGNAL CONTROLLER	3.00	0.00	3.00	EA	0.00	\$3,214.00	\$0.00
		0030	2130	9029902	MISC.AUDIBLE PEDESTRIAN PUSH BUTTON AND SIGNING	24.00	0.00	24.00	EA	0.00	\$715.00	\$0.00
		0030	2140	9029902	MISC.COMBINATION PAD MOUNTED 120V/240V POWER	1.00	0.00	1.00	EA	0.00	\$14,267.00	\$0.00
		0030	2150	9029902	SUPPLY AND LIGHTING CONTROLLER WITH UPS MISC.CONCRETE TRANSFORMER PAD	1.00	0.00	1.00	EA	0.00	\$3,863.00	\$0.00
			2160	9029902	MISC.Countdown Pedestrian Signal Head, Type 1S	22.00	0.00	22.00	EA	0.00	\$450.00	\$0.00
		0030										
		0030	2170	9029902	MISC NETWORK CONNECTED SIGNAL MONITOR	1.00	0.00	1.00	EA EA	0.00	\$4,795.00	\$0.00
		0030	2180		MISC.3" DVC CONDUIT WITH DUIL TARE	3.00	0.00	3.00	LF	0.00	\$1,010.00	\$0.00
		0030	2190	9029903	MISC.3" PVC CONDUIT WITH PULL TAPE	255.00	0.00	255.00		0.00	\$10.20	\$0.00
		0040	2200	9031010	CONCRETE FOOTINGS, EMBEDDED	10.60	2.10	12.70	CUYD	0.00	\$1,400.00	\$0.00
		0040	2210	9031020	CONCRETE FOOTINGS, BOLT DOWN	82.30	-3.30	79.00	CUYD	56.32	\$1,200.00	\$67,584.00
		0040	2220	9031210	STRUCTURAL STEEL POSTS	3,150.00	1,760.00	4,910.00	LB	0.00	\$4.50	\$0.00
		0040	2230	9031220	PIPE POSTS	5,390.00	-300.00	5,090.00	LB	0.00	\$3.75	\$0.00

Revision 4/1/2020 Page 22 of 100



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract	Project	Category	Line	Item	Report Generated date and can differ from the posted ar Description	Bid	Net	Total	Generat Unit	Total	Unit Price	Total Value POSTED
Nm.CONTRACT	No.		No.	Code		Quantity	Change Order	Current Quantity		Posted Approved Qty		To Date (See report generated date)
200515-F15	J6I2222	0040	2240	9031270A	2 IN. PSST POST - 12 GA.	60.00	0.00	60.00	LF	0.00	\$12.00	\$0.00
		0040	2250	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	21.00	0.00	21.00	LF	0.00	\$40.00	\$0.00
		0040	2260	9035004A	SH-FLAT SHEET	598.00	0.00	598.00	SQFT	0.00	\$21.00	\$0.00
		0040	2270	9035011A	ST-STRUCTURAL	2,364.00	3.00	2,367.00	SQFT	1,698.00	\$24.00	\$40,752.00
		0040	2280	9035069A	SHF-FLAT SHEET FLUORESCENT	93.00	0.00	93.00	SQFT	0.00	\$24.00	\$0.00
		0040	2290	9035071A	STF-STRUCTURAL FLUORESCENT	390.00	0.00	390.00	SQFT	243.00	\$26.00	\$6,318.00
		0040	2300	9036036	TUBULAR SUPPORT, TYPE C-2315-20	2.00	0.00	2.00	EA	0.00	\$12,950.00	\$0.00
		0040	2310	9036042	TUBULAR SUPPORT, TYPE C-2018-28	2.00	-2.00	0.00	EA	0.00	\$20,000.00	\$0.00
		0040	2320	9039901	MISC.SIGN 12 CANTILEVER BOX TRUSS, 30 FT ARM	1.00	0.00	1.00	LS	0.00	\$29,000.00	\$0.00
		0040	2330	9039901	MISC.SIGN 4 SPAN BOX TRUSS (98 FT)	1.00	0.00	1.00	LS	1.00	\$66,000.00	\$66,000.00
		0040	2340	9039901	MISC.SIGN 8 SPAN BOX TRUSS (83 FT-5 IN)	1.00	0.00	1.00	LS	0.00	\$52,500.00	\$0.00
		0040	2350	9039901	MISC.SPECIAL STREET NAME BRIDGE MOUNTED SIGNS	1.00	0.00	1.00	LS	0.00	\$20,000.00	\$0.00
		0050	2360	9108208	CABLE, 8 AWG, 1 CONDUCTOR, POWER	2,510.00	0.00	2,510.00	LF	0.00	\$1.00	\$0.00
		0050	2370	9108408	WIRE, 8 AWG, BARE NEUTRAL	1,010.00	0.00	1,010.00	LF	0.00	\$1.00	\$0.00
		0050	2380	9109100	BASE, CONCRETE	2.00	0.00	2.00	CUYD	0.00	\$1,726.00	\$0.00
		0050	2390	9109230	DYNAMIC MESSAGE SIGN ASSEMBLY, INSTALLED	1.00	-1.00	0.00	EA	0.00	\$9,413.00	\$0.00
		0050	2400	9109901	MISC.ITS ASSET MANAGEMENT TOOL	1.00	0.00	1.00	LS	0.00	\$2,797.00	\$0.00
		0050	2410	9109902	MISC.ADJUST EXISTING P.B. TO GRADE	1.00	0.00	1.00	EA	0.00	\$1,335.00	\$0.00
		0050	2420	9109902	MISC.BURIED CABLE DELINEATOR POST	12.00	0.00	12.00	EA	1.00	\$100.00	\$100.00
		0050	2430	9109902	MISC.BUTTERFLY DMS STRUCTURE	1.00	0.00	1.00	EA	0.00	\$55,944.00	\$0.00
		0050	2440	9109902	MISC.CCTV EXTENSION POLE, 20' METALLICFINISH	1.00	0.00	1.00	EA	0.00	\$1,554.00	\$0.00
		0050	2450	9109902	MISC.FIBER OPTIC FUSION SPLICE	310.00	48.00	358.00	EA	272.00	\$39.00	\$10,608.00
		0050	2460	9109902	MISC.FIBER OPTIC JUMPER,SM, FURNISH AND INSTALL	34.00	0.00	34.00	EA	7.00	\$22.00	\$154.00
		0050	2470	9109902	MISC.FIBER OPTIC PIGTAIL, SM, FURNISH AND INSTALL	42.00	0.00	42.00	EA	26.00	\$10.00	\$260.00
		0050	2480	9109902	MISC.FIELD TERMINAL CABINET, TYPE 7, FURNISH AND INSTALL	1.00	0.00	1.00	EA	0.00	\$3,314.00	\$0.00
		0050	2490	9109902	MISC.INSTALL CCTV CAMERA ASSEMBLY	1.00	0.00	1.00	EA	0.00	\$883.00	\$0.00
		0050	2500	9109902	MISC.INSTALL CONDUIT INTO EXISTING BOX	5.00	0.00	5.00	EA	0.00	\$210.00	\$0.00
		0050	2510	9109902	MISC.ITS PULL BOX, CLASS 5	5.00	0.00	5.00	EA	0.00	\$1,842.00	\$0.00
		0050	2520	9109902	MISC.ITS PULL BOX, CLASS 2	1.00	0.00	1.00	EA	0.00	\$1,554.00	\$0.00
		0050	2530	9109902	MISC.SIGN STRUCTURE BASE MESH	1.00	0.00	1.00	EA	0.00	\$310.00	\$0.00
		0050	2540	9109902	MISC.UNDERGROUND FIBER CABLE SPLICE ENCLOSURE	2.00	2.00	4.00	EA	2.00	\$621.00	\$1,242.00
		0050	2550	9109902	MISC.WALL-MOUNTED FIBER INTERCONNECT CENTER, FURNISH AND INSTALL	7.00	0.00	7.00	EA	0.00	\$350.00	\$0.00
		0050	2560	9109903	MISC.24 STRAND, SINGLE MODE FIBER OPTIC CABLE	7,760.00	0.00	7,760.00	LF	7,760.00	\$1.85	\$14,356.00
		0050	2570	9109903	MISC.72 STRAND, SINGLE MODE FIBER OPTIC CABLE	4,200.00	0.00	4,200.00	LF	4,200.00	\$2.05	\$8,610.00
		0050	2580	9109903	MISC.CAT-5 ETHERNET CABLE	200.00	0.00	200.00	LF	0.00	\$1.70	\$0.00
		0050	2590	9109903	MISC.Conduit, PVC, PUSHED, 2"	399.00	0.00	399.00	LF	399.00	\$16.45	\$6,563.55
		0050	2600	9109903	MISC.CONDUIT, PVC, TRENCH, 2"	1,083.00	0.00	1,083.00	LF	0.00	\$5.90	\$0.00
		0070	2610	2163000	PARTIAL REMOVAL OF EXISTING BRIDGE DECK	2,033.00	0.00	2,033.00	SQFT	2,033.00	\$10.00	\$20,330.00
		0070	2620	2163502	PARTIAL REMOVAL OF SUBSTRUCTURE CONCRETE	1.00	0.00	1.00	LS	1.00	\$9,200.00	\$9,200.00
		0070	2630	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	41.00	0.00	41.00	LF	41.00	\$425.00	\$17,425.00
		0070	2640	5031010A	BRIDGE APPROACH SLAB (MAJOR ROAD)	59.00	0.00	59.00	SQYD	0.00	\$355.00	\$0.00
		0070	2650	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	1.00	0.00	1.00	CUYD	1.00	\$5,050.00	\$5,050.00
		0070	2660	7034001	CLASS B-1 CONCRETE	0.70	0.00	0.70	CUYD	0.70	\$12,650.00	\$8,855.00
		0070	2670	7034212	SLAB ON STEEL	212.00	2.00	214.00	SQYD	214.00	\$470.00	\$100,580.00
		0070	2680	7034214	CLASS B-2 CONCRETE	3.50	0.00	3.50	CUYD	3.50	\$6,530.00	\$22,855.00
		0070	2690	7034610	CORRAL CURB	182.00	0.00	182.00	LF	142.00	\$117.00	\$16,614.00

Revision 4/1/2020 Page 23 of 100



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Im.CONTRACT	Project No.	Category	Line No.	ltem Code	Report Generated date and can differ from the posted at Description	Bid Quantity	Net Change	Total Current	General Unit	Total Posted	Unit Price	Total Value POSTE To Date (See repo
	110.		110.	0000		quantity	Order	Quantity		Approved Qty		generated date)
00515-F15	J6I2222	0070	2700	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	1,275.00	45.00	1,320.00	SQFT	1,320.00	\$158.00	\$208,560.0
		0070	2710	7040113	CLEANING AND EPOXY COATING	6,834.00	-6,834.00	0.00	SQFT	0.00	\$3.36	\$0.0
		0070	2720	7049904	MISC.BARRIER CURB REPAIR (UNFORMED	195.00	-28.00	167.00	SQFT	148.00	\$175.00	\$25,900.0
		0070	2730	7101000	REINFORCING STEEL (EPOXY COATED)	850.00	0.00	850.00	LB	850.00	\$3.00	\$2,550.0
		0070	2740	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$1,584.52	\$0.0
		0070	2750	7123130	REHABILITATE BEARING	8.00	0.00	8.00	EA	0.00	\$3,712.50	\$0.0
		0070	2760	7123620	DRAINAGE SYSTEM (ON STRUCTURE)	1.00	0.00	1.00	LS	0.00	\$10,500.00	\$0.0
		0070	2770	7129901	MISC.FLUSH DRAINAGE SYSTEM AND EXPANSION JOINTS	1.00	0.00	1.00	LS	1.00	\$20,000.00	\$20,000.
		0070	2780	7129902	MISC.FATIGUE CRACK REPAIR	1.00	0.00	1.00	EA	1.00	\$6,516.00	\$6,516
		0070	2790	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	41.00	0.00	41.00	LF	41.00	\$490.00	\$20,090
		0071	2800	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	25.00	0.00	25.00	SQFT	0.00	\$158.00	\$0.
		0071	2810	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	1,483.00	886.00	2,369.00	SQFT	2,369.00	\$158.00	\$374,302
		0071	2820	7040113	CLEANING AND EPOXY COATING	5,621.00	-5,621.00	0.00	SQFT	0.00	\$3.04	\$0.
		0071	2830	7049904	MISC.BARRIER CURB REPAIR (UNFORMED)	142.00	189.00	331.00	SQFT	331.00	\$175.00	\$57,925.
		0071	2840	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$3,678.35	\$0
		0071	2850	7121000	FABRICATED STRUCTURAL CARBON STEEL (MISC)	290.00	0.00	290.00	LB	0.00	\$23.00	\$0
		0071	2860	7123130	REHABILITATE BEARING	5.00	0.00	5.00	EA	0.00	\$2,570.00	\$0
		0071	2875	7125111	INTERMEDIATE FIELD COAT (SYSTEM G)	1.00	0.00	1.00	LS	0.00	\$1,330.80	\$0
		0071	2885	7125112	FINISH FIELD COAT (SYSTEM G)	1.00	0.00	1.00	LS	0.00	\$475.20	\$0
		0071	2890	7129901	MISC.FLUSH DRAINAGE SYSTEM AND EXPANSION JOINTS	1.00	0.00	1.00	LS	1.00	\$20,000.00	\$20,000
		0071	2900	7129902	MISC.FATIGUE CRACK REPAIR	3.00	0.00	3.00	EA	2.00	\$2,040.00	\$4,080
		0072	2910	7121060	FABRICATED SIGN SUPPORT BRACKETS	1.00	0.00	1.00	LS	1.00	\$3,600.00	\$3,600
		0073	2920	2065500	TEMPORARY SHORING	1.00	0.00	1.00	LS	1.00	\$150,000.00	\$150,000
		0073	2930	7033009	AESTHETIC CONCRETE STAIN	1.00	0.00	1.00	LS	0.00	\$14,877.00	\$0
		0073	2940	7201000	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	8,672.00	0.00	8,672.00	SQFT	8,672.00	\$62.50	\$542,000
		0074	2955	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	258.00	-258.00	0.00	SQYD	0.00	\$145.00	\$(
		0074	2960	6079903	MISC.(60 IN.) DECORATIVE PEDESTRIAN FENCE	280.00	-280.00	0.00	LF	0.00	\$130.00	\$(
		0074	2970	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	820.00	7.00	827.00	LF	741.00	\$68.00	\$50,388
		0074	2980	7025001	DYNAMIC PILE TESTING	2.00	0.00	2.00	EA	2.00	\$2,325.00	\$4,650
		0074	2990	7027000	PILE POINT REINFORCEMENT	14.00	0.00	14.00	EA	14.00	\$80.00	\$1.120
									CUYD			1 /
		0074	3000	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	56.40	13.90	70.30		70.30	\$565.00	\$39,719
		0074	3010		TYPE D BARRIER	288.00	-288.00	0.00	LF	0.00	\$115.00	\$0
		0074	3020	7034221	SLAB ON CONCRETE NU-GIRDER	760.00	-760.00	0.00	SQYD	0.00	\$335.00	\$(
		0074	3030	7034630	CONCRETE CURB (BRIDGE RAIL)	306.00	-306.00	0.00	LF	0.00	\$75.00	\$1
		0074	3040	7056022	NU 43, PRESTRESSED CONCRETE NU-GIRDER	894.00	-894.00	0.00	LF	0.00	\$215.00	\$0
		0074	3050	7071000	CONDUIT SYSTEM ON STRUCTURE	1.00	-1.00	0.00	LS	0.00	\$5,927.00	\$0
		0074	3060	7121060	FABRICATED SIGN SUPPORT BRACKETS	1.00	0.00	1.00	LS	0.00	\$7,100.00	\$0
		0074	3070	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	0.00	\$2,500.00	\$(
		0074	3080	7161000	PLAIN NEOPRENE BEARING PAD	16.00	0.00	16.00	EA	16.00	\$200.00	\$3,200
		0074	3090	7201300	PIPE PILE SPACERS	14.00	-14.00	0.00	EA	0.00	\$1,000.00	\$0
		0074	3100	9019902	MISC.ORNAMENTAL LUMINAIRE	10.00	4.00	14.00	EA	0.00	\$1,658.00	\$0
		0075	3110	7033009	AESTHETIC CONCRETE STAIN	1.00	-1.00	0.00	LS	0.00	\$17,530.50	\$0
		0075	3120	7201000	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	7,637.00	-7,637.00	0.00	SQFT	0.00	\$110.00	\$
		0076	3130	7033009	AESTHETIC CONCRETE STAIN	1.00	-1.00	0.00	LS	0.00	\$6,525.00	\$0
		0076	3140	7201000	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	3,410.00	-3,410.00	0.00	SQFT	0.00	\$110.00	\$0
		0077	3150	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$146,000.00	\$146,000
		0077	3160	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	250.00	0.00	250.00	SQYD	0.00	\$155.00	\$0

Revision 4/1/2020 Page 24 of 100



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Q	uantities	and Valu	ues are	based on I	Report Generated date and can differ from the posted a	mount at the	time the Es	timate was	Generat	ted.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200515-F15	J6I2222	0077	3170	6079903	MISC.(60 IN.) DECORATIVE PEDESTRIAN FENCE	404.00	0.00	404.00	LF	0.00	\$130.00	\$0.00
		0077	3180	7011105	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	30.00	0.00	30.00	LF	25.50	\$490.00	\$12,495.00
		0077	3190	7011204	ROCK SOCKETS (3 FT 0 IN. DIA.)	30.00	0.00	30.00	LF	30.00	\$815.00	\$24,450.00
		0077	3200	7011300	VIDEO CAMERA INSPECTION	3.00	0.00	3.00	EA	3.00	\$450.00	\$1,350.00
		0077	3210	7011400	FOUNDATION INSPECTION HOLES	60.00	0.00	60.00	LF	60.00	\$140.00	\$8,400.00
		0077	3220	7011600	SONIC LOGGING TESTING	3.00	0.00	3.00	EA	3.00	\$2,100.00	\$6,300.00
		0077	3230	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	462.00	0.00	462.00	LF	462.00	\$75.00	\$34,650.00
		0077	3240	7025001	DYNAMIC PILE TESTING	2.00	0.00	2.00	EA	2.00	\$2,350.00	\$4,700.00
		0077	3250	7026000	PRE-BORE FOR PILING	252.00	0.00	252.00	LF	252.00	\$180.00	\$45,360.00
		0077	3260	7027000	PILE POINT REINFORCEMENT	14.00	0.00	14.00	EA	14.00	\$80.00	\$1,120.00
		0077	3270	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	49.60	0.00	49.60	CUYD	49.60	\$800.00	\$39,680.00
		0077	3280	7034003	CLASS B-1 CONCRETE (SUBSTRUCTURE)	60.30	0.00	60.30	CUYD	60.30	\$1,055.00	\$63,616.50
		0077	3290	7034219A	TYPE D BARRIER	404.00	0.00	404.00	LF	0.00	\$130.00	\$0.00
		0077	3300	7034221	SLAB ON CONCRETE NU-GIRDER	1,175.00	0.00	1,175.00	SQYD	1,116.25	\$290.00	\$323,712.50
		0077	3310	7034630	CONCRETE CURB (BRIDGE RAIL)	447.00	0.00	447.00	LF	0.00	\$62.00	\$0.00
		0077	3320	7056021	NU 35, PRESTRESSED CONCRETE NU-GIRDER	1,268.00	0.00	1,268.00	LF	1,268.00	\$210.00	\$266,280.00
		0077	3330	7061060	REINFORCING STEEL (BRIDGES)	18,420.00	-18,420.00	0.00	LB	0.00	\$1.00	\$0.00
		0077	3340	7071000	CONDUIT SYSTEM ON STRUCTURE	1.00	0.00	1.00	LS	0.00	\$26,383.00	\$0.00
		0077	3350	7079901	MISC.CONDUIT SYSTEM ON STRUCTURE - ATT TELPHONE	1.00	0.00	1.00	LS	1.00	\$3,730.00	\$3,730.00
		0077	3355	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS	1.00	0.00	1.00	LS	1.00	\$8,330.05	\$8,330.05
		0077	3370	7121060	(EPOXY) FABRICATED SIGN SUPPORT BRACKETS	1.00	0.00	1.00	LS	0.00	\$27,500.00	\$0.00
		0077	3380	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	0.00	\$2,500.00	\$0.00
		0077	3390	7161003	LAMINATED NEOPRENE BEARING PAD (TAPERED)	28.00	0.00	28.00	EA	28.00	\$425.00	\$11,900.00
		0077	3400	7201300	PIPE PILE SPACERS	14.00	0.00	14.00	EA	14.00	\$855.00	\$11,970.00
		0077	3410	9019903	MISC.ORNAMENTAL LUMINAIRE	12.00	0.00	12.00	LF	0.00	\$1,658.00	\$0.00
		0078	3420	7033009	AESTHETIC CONCRETE STAIN	1.00	0.00	1.00	LS	1.00	\$7,856.10	\$7,856.10
		0078	3430	7201000	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	4,182.00	0.00	4,182.00	SQFT	4,182.00	\$80.00	\$334,560.00
		0079	3440	7033009	AESTHETIC CONCRETE STAIN	1.00	0.00	1.00	LS	1.00	\$3,654.00	\$3,654.00
		0079	3450	7201000	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	2,521.00	0.00	2,521.00	SQFT	2,521.00	\$80.00	\$201,680.00
		0079	3460	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	0.80	\$655,000.00	\$524,000.00
		0080	3470		BRIDGE APPROACH SLAB (MAJOR ROAD)	81.00	0.00	81.00	SQYD	0.00	\$200.00	\$0.00
			3480	7011110	DRILLED SHAFTS (6 FT. 0 IN. DIA.)	380.40	0.00	380.40	LF	246.16	\$485.00	\$119,387.60
		0080	3490	701110	ROCK SOCKETS (5 FT 6 IN. DIA.)	108.00	0.00	108.00	LF	108.00	\$2,555.00	\$275,940.00
		0080	3500	7011203	VIDEO CAMERA INSPECTION	6.00	0.00	6.00	EA	4.00	\$550.00	\$2,200.00
		0080	3510	7011400	FOUNDATION INSPECTION HOLES	174.00	0.00	174.00	LF	174.00	\$155.00	\$26,970.00
			3520	7011600	SONIC LOGGING TESTING	6.00	0.00	6.00	EA	4.00	\$4,250.00	\$17,000.00
		0080	3530	7011000	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	430.00	0.00	430.00	LF	0.00	\$4,230.00	\$0.00
		0080	3540	7021212	DYNAMIC PILE TESTING	1.00	0.00	1.00	EA	0.00	\$2,700.00	
		0080										\$0.00
		0800	3550	7027000	PILE POINT REINFORCEMENT	5.00	0.00	5.00	EA	0.00	\$80.00	\$0.00
		0800	3560	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	21.70	0.00	21.70	CUYD	0.00	\$745.00	\$0.00
		0800	3570	7034003	CLASS B-1 CONCRETE (SUBSTRUCTURE)	379.50	0.00	379.50	CUYD	0.00	\$710.00	\$0.00
		0800	3580	7034212	SLAB ON STEEL	304.00	0.00	304.00	SQYD	0.00	\$335.00	\$0.00
		0800	3590		TYPE D BARRIER	1,779.00	0.00	1,779.00	LF	0.00	\$58.00	\$0.00
		0800	3600	7034221	SLAB ON CONCRETE NU-GIRDER	2,430.00	0.00	2,430.00	SQYD	0.00	\$340.00	\$0.00
		0800	3610	7056023	NU 53, PRESTRESSED CONCRETE NU-GIRDER	1,504.00	0.00	1,504.00	LF	0.00	\$270.00	\$0.00
		0800	3620	7056025	NU 70, PRESTRESSED CONCRETE NU-GIRDER	1,151.00	0.00	1,151.00	LF	0.00	\$270.00	\$0.00
		0800	3630	7061060	REINFORCING STEEL (BRIDGES)	170,450.00	0.00	170,450.00	LB	134,380.00	\$0.85	\$114,223.00

Revision 4/1/2020 Page 25 of 100



Total Paid / All Items / All Estimates (Including this Estimate)

vote: Posted Q	uantities	and Valu	ies are	based on I	Report Generated date and can differ from the posted am	ount at the	time the Es	timate was	Generat	ed.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200515-F15	J6I2222	0800	3640	7061070	MECHANICAL BAR SPLICE	480.00	0.00	480.00	EA	152.00	\$95.00	\$14,440.00
		0080	3650	7101000	REINFORCING STEEL (EPOXY COATED)	12,940.00	0.00	12,940.00	LB	0.00	\$1.15	\$0.00
		0080	3660	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$9,744.80	\$0.00
		0800	3670	7120900	EXPANSION DEVICE (FINGER PLATE)	23.00	0.00	23.00	LF	0.00	\$2,400.00	\$0.00
		0080	3680	7121121	FABRICATED STRUCTURAL LOW ALLOY STEEL (PLATE GIRDER) A709, GRADE 50	79,550.00	0.00	79,550.00	LB	0.00	\$3.19	\$0.00
		0800	3690	7123210	EARTH QUAKE RESTRAINER ASSEMBLIES	3.00	0.00	3.00	EA	0.00	\$13,125.00	\$0.00
		0080	3700	7123301	STEEL INTERMEDIATE DIAPHRAGM FOR P/S CONCRETE GIRDERS	30.00	0.00	30.00	EA	0.00	\$680.00	\$0.00
		0800	3710	7123620	DRAINAGE SYSTEM (ON STRUCTURE)	1.00	0.00	1.00	LS	0.00	\$80,000.00	\$0.00
		0800	3720	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	500.00	0.00	500.00	SQFT	0.00	\$81.40	\$0.00
		0800	3730	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	500.00	0.00	500.00	SQFT	0.00	\$2.00	\$0.00
		0800	3740	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	5,000.00	0.00	5,000.00	SQFT	0.00	\$6.65	\$0.00
		0800	3750	7125370A	FINISH FIELD COAT (SYSTEM G)	2,700.00	0.00	2,700.00	SQFT	0.00	\$2.38	\$0.00
		0800	3760	7129903	MISC.MODULAR EXPANSION JOINT SYSTEM	24.00	0.00	24.00	LF	0.00	\$2,400.00	\$0.00
		0800	3770	7151001	VERTICAL DRAIN AT END BENTS	1.00	0.00	1.00	EA	0.00	\$2,500.00	\$0.00
		0800	3780	7161000	PLAIN NEOPRENE BEARING PAD	8.00	0.00	8.00	EA	0.00	\$225.00	\$0.00
		0800	3790	7161002	LAMINATED NEOPRENE BEARING PAD	3.00	0.00	3.00	EA	0.00	\$250.00	\$0.00
		0800	3800	7161003	LAMINATED NEOPRENE BEARING PAD (TAPERED)	21.00	0.00	21.00	EA	0.00	\$320.00	\$0.00
		0800	3810	7162000	LAMINATED NEOPRENE BEARING PAD ASSEMBLY	16.00	0.00	16.00	EA	0.00	\$1,520.00	\$0.00
		0800	3820	7163000	TYPE N PTFE BEARING	3.00	0.00	3.00	EA	0.00	\$2,500.00	\$0.00
		0800	3830	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	24.00	0.00	24.00	LF	0.00	\$510.00	\$0.00
		0001	5001	6189901	MISC.Adjust Mobilization for Contract Bond	0.00	1.00	1.00	LS	1.00	\$107,907.00	\$107,907.0
		0001	5002	6141121	CURVED VANE GRATE AND FRAME (4 FT. X 2 FT. OR 1200MM X 600MM)	0.00	18.00	18.00	EA	2.00	\$1,400.00	\$2,800.00
		0001	5003	6149902	MISC.Parallel Grate and Bearing Plate (4 FT.x2FT.)	0.00	27.00	27.00	EA	10.00	\$1,400.00	\$14,000.00
		0050	5004	9109901	MISC.DMS Board Removal	0.00	1.00	1.00	LS	1.00	\$12,673.51	\$12,673.5
		0001	5005	6173700B	TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED	0.00	638.00	638.00	LF	638.00	\$40.79	\$26,024.03
		0001	5006	2063100	CLASS 3 EXCAVATION IN ROCK	0.00	18.50	18.50	CUYD	18.50	\$85.00	\$1,572.5
		0050	5007	9109901	MISC.Colored Dynamic Message Sign	0.00	1.00	1.00	LS	0.00	\$110,608.04	\$0.00
		0001	5008	6149902	MISC.MISC. MSD Manhole Frame and Cover	0.00	19.00	19.00	EA	6.00	\$400.00	\$2,400.00
		0001	5009	2032000	CLASS C EXCAVATION	0.00	1,139.90	1,139.90	CUYD	1,139.90	\$75.00	\$85,492.5
		0001	5010	7209901	MISC.Rock Fill Alternative Ground Improvement	0.00	1.00	1.00	LS	1.00	\$7,822.60	\$7,822.6
		0077	5011	7101000	REINFORCING STEEL (EPOXY COATED)	0.00	18,950.00	18,950.00	LB	18,950.00	\$1.33	\$25,203.50
		0001	5012	2029901	MISC.Barrier Wall Removal	0.00	1.00	1.00	LS	1.00	\$5,226.18	\$5,226.18
		0074	5013	7011105	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	0.00	202.80	202.80	LF	202.80	\$567.75	\$115,139.70
		0074	5014	7011204	ROCK SOCKETS (3 FT 0 IN. DIA.)	0.00	76.70	76.70	LF	76.70	\$917.10	\$70,341.5
		0074	5015	7101000	REINFORCING STEEL (EPOXY COATED)	0.00	24,760.00	24,760.00	LB	24,760.00	\$1.49	\$36,892.4
		0074	5016	7011300	VIDEO CAMERA INSPECTION	0.00	6.00	6.00	EA	6.00	\$577.50	\$3,465.00
		0074	5017	7011400	FOUNDATION INSPECTION HOLES	0.00	185.10	185.10	LF	185.10	\$136.50	\$25,266.1
		0074	5018	7011600	SONIC LOGGING TESTING	0.00	6.00	6.00	EA	6.00	\$4,593.00	\$27,558.0
		0074	5019	7061070	MECHANICAL BAR SPLICE	0.00	108.00	108.00	EA	108.00	\$140.70	\$15,195.60
		0001	5020	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	0.00	165.70	165.70	SQYD	165.70	\$110.00	\$18,227.00
		0001	5021	6131018	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	0.00	58.00	58.00	EA	58.00	\$12.00	\$696.00
		0001	5022	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	0.00	130.00	130.00	EA	130.00	\$15.00	\$1,950.00
		0001	5023	1046002	VALUE ENGINEERING	0.00	14,480.00	14,480.00	EA	14,480.00	\$1.00	\$14,480.00
		0001	5024	7269923	SEWER	0.00	701.00	701.00	LF	701.00	\$461.34	\$323,399.34
		0001	5025	7269922	SEWER	0.00	150,000.00	150,000.00	EA	147,772.00	\$1.00	\$147,772.00

Revision 4/1/2020 Page 26 of 100



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

ontract ONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
5-F15	J6I2222	0074	5026	7034003	CLASS B-1 CONCRETE (SUBSTRUCTURE)	0.00	99.80	99.80	CUYD	99.80	\$1,404.00	\$140,119.2
		0001	5027	2039907	MISC.MISC. Lightweight Fill	0.00	6,779.00	6,779.00	CUYD	4,693.00	\$64.50	\$302,698.5
		0074	5028	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	0.00	223.00	223.00	SQYD	0.00	\$149.00	\$0.00
		0074	5029	7034221	SLAB ON CONCRETE NU-GIRDER	0.00	1,269.00	1,269.00	SQYD	571.00	\$406.00	\$231,826.00
		0074	5030	7034630	CONCRETE CURB (BRIDGE RAIL)	0.00	377.00	377.00	LF	0.00	\$77.00	\$0.00
		0074	5031	7056022	NU 43, PRESTRESSED CONCRETE NU-GIRDER	0.00	1,485.00	1,485.00	LF	1,485.00	\$221.00	\$328,185.00
		0074	5032	7071000	CONDUIT SYSTEM ON STRUCTURE	0.00	1.00	1.00	LS	0.00	\$9,965.00	\$0.00
		0010	5033	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	0.00	50.00	50.00	LF	0.00	\$29.40	\$0.00
		0077	5034	6079903	MISC.(70in.) Decorative Pedestrian Fence	0.00	440.00	440.00	LF	0.00	\$152.25	\$0.00
		0074	5035	7026000	PRE-BORE FOR PILING	0.00	189.00	189.00	LF	189.00	\$154.00	\$29,106.00
		0074	5036	7034216	TYPE H BARRIER	0.00	446.00	446.00	LF	0.00	\$129.00	\$0.00
		0074	5037	7101000	REINFORCING STEEL (EPOXY COATED)	0.00	31,150.00	31,150.00	LB	31,150.00	\$1.19	\$37,068.50
		0074	5038	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	0.00	1.00	1.00	LS	1.00	\$13,118.70	\$13,118.70
		0074	5039	7123620	DRAINAGE SYSTEM (ON STRUCTURE)	0.00	1.00	1.00	LS	0.00	\$58,912.00	\$0.00
		0074	5040	7161002	LAMINATED NEOPRENE BEARING PAD	0.00	24.00	24.00	EA	24.00	\$300.00	\$7,200.00
		0074	5041	7161003	LAMINATED NEOPRENE BEARING PAD (TAPERED)	0.00	8.00	8.00	EA	8.00	\$360.00	\$2,880.00
		0030	5042	9023340	POST, TYPE B, LONGEST ARM 40 FT. OR 12.2 M	0.00	1.00	1.00	EA	0.00	\$15,863.40	\$0.00
		0030	5043	9023340	POST, TYPE B, LONGEST ARM 40 FT. OR 12.2 M	0.00	1.00	1.00	EA	0.00	\$15,319.50	\$0.00
		0074	5044	6116010A	SLOPE PROTECTION	0.00	544.00	544.00	SQYD	489.60	\$150.00	\$73,440.00
		0074	5045	1099902	MISC.Value Engineering Design Costs - VECP #20-29	0.00	214,535.00	214,535.00	EA	214,535.00	\$1.00	\$214,535.00
		0074	5046	1046002	VALUE ENGINEERING	0.00	279,927.42	279,927.42	EA	279,927.42	\$1.00	\$279,927.42
		0001	5047	7250415	15 IN. PIPE GROUP C	0.00	88.00	88.00	LF	88.00	\$70.00	\$6,160.00
		0001	5048	7250418	18 IN. PIPE GROUP C	0.00	99.00	99.00	LF	99.00	\$80.00	\$7,920.00
		0001	5049	7320618A	18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	0.00	2.00	2.00	EA	2.00	\$900.00	\$1,800.00
		0001	5050	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	0.00	5.30	5.30	CUYD	0.00	\$100.00	\$0.00
		0001	5051	6096041	PLACING TYPE 1 ROCK DITCH LINER	0.00	5.30	5.30	CUYD	0.00	\$100.00	\$0.00
		0001	5052	6044011	PIPE COLLAR, TYPE A	0.00	2.00	2.00	EA	0.00	\$2,468.00	\$0.00
		0001	5053	1099902	MISC. Value Engineering Design Costs VECP #20-49	0.00	46,410.00	46,410.00	EA	46,410.00	\$1.00	\$46,410.00
		0001	5054	1046002	VALUE ENGINEERING	0.00	102,477.40	102,477.40	EA	102,477.40	\$1.00	\$102,477.40
		0070	5055	7129901	MISC.Fabricated Structural Carbon Steel A150114	0.00	1.00	1.00	LS	0.00	\$40,590.00	\$0.00
		0070	5056	7129901	MISC.Field Application of Epoxy Mastic Primer A150114	0.00	1.00	1.00	LS	0.00	\$1,501.50	\$0.00
		0070	5057	7125112	FINISH FIELD COAT (SYSTEM G)	0.00	1.00	1.00	LS	0.00	\$1,501.50	\$0.00
		0070	5058	7125111	INTERMEDIATE FIELD COAT (SYSTEM G)	0.00	1.00	1.00	LS	0.00	\$1,501.50	\$0.00
		0070	5059	7125100	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	0.00	1.00	1.00	LS	0.00	\$19,215.00	\$0.00
		0071	5060	7129901	MISC.Fabricated Structural Carbon Steel A150115	0.00	1.00	1.00	LS	0.00	\$92,520.40	\$0.00
		0071	5061	7129901	MISC.Field Application of Epoxy Mastic Primer A150115	0.00	1.00	1.00	LS	0.00	\$2,478.00	\$0.00
		0071	5062	7125112	FINISH FIELD COAT (SYSTEM G)	0.00	1.00	1.00	LS	0.00	\$2,478.00	\$0.00
		0071	5063	7125111	INTERMEDIATE FIELD COAT (SYSTEM G)	0.00	1.00	1.00	LS	0.00	\$2,478.00	\$0.00
		0071	5064	7125100	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	0.00	1.00	1.00	LS	0.00	\$32,655.00	\$0.00
	Proiect J	612222 - To	tal Value	Posted to D	ate as of Report Generated Date							\$16,747,314.22

Revision 4/1/2020 Page 27 of 100



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J6I2222

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0020	2022010	REMOVAL OF IMPROVEMENTS	8/30/21	9/2/21	0.13	LS	EB 64 Jefferson exit ramp and existing Sign truss removal along Ramp B	0		0		Various areas around the job
0050	2031000	CLASS A EXCAVATION	8/30/21	9/2/21	1,000.00	CUYD	North side of I-64 at Ramp A	0		0		
0120	2063000	CLASS 3 EXCAVATION	8/25/21	9/2/21	170.00			5+00.00	17.74 LT	9+43.25	20.00 LT	This work was done over a week. This number is the result of all of the plan excavation (for these structure and place) of the man of the plan of the
			8/31/21	9/2/21	364.00	CUYD	DI 709, MH 911, MH 912, P-709, P-705, P-902, P-911, P-912	0		0		
0200	5021108	CONCRETE PAVEMENT (8 IN. NON-REINF)	8/18/21	9/2/21	64.40	SQYD	SOR Shoulder at Ramp D	0		0		
0380	6071102		8/30/21	9/2/21	82.00	LF		0		0		
0640	6149902	MISC. DRAINAGE FITTINGS	8/31/21	9/2/21	1.00	EA LS		4+18 0		0		
1060	7033009 7261015	AESTHETIC CONCRETE STAIN 15 IN. PIPE GROUP A	8/30/21 8/25/21	9/2/21	1.00 316.00			5+00.00		5+00.00		This work was completed over the last week.
	7201010	TO MICH IN E GROOT AT	O/LO/L1	O/L/L I	010.00	-	STA: 5+00.00 to 9.43.25	0.00.00		0.00.00		The work was completed over the last most.
			8/31/21	9/2/21	35.00		P-709	4+25				
1120	7261018	18 IN. PIPE GROUP A	8/25/21	9/2/21	131.00	LF	Pipes for structures #103, #105, and #110 122 LF between structures #105 and #110. Pipe structures #103 has 5 LF and #110 has 4 LF.					This work was conducted over the last week.
			8/31/21	9/2/21	107.00	LF	P-911, P-912	5+64				
				9/2/21	114.00	LF	P-902	29+00				
1170	7311022	PRECAST CONCRETE DROP INLET 2 FT X 2 FT	8/25/21	9/2/21	20.00	FT	Structure #104 is located at STA: 6+29.50 and #106 is located at STA: 5+00.00					This work was completed over a week or so.
1180	7311042	PRECAST CONCRETE DROP INLET 4 FT X 2 FT	8/25/21	9/2/21	22.00	FT	Structure #103 is located at STA: 6+29.51, #105 is located at STA: 5+00.00, #108 is located at STA: 5+00.00, #108 is located at STA: 8+75.00, #109 is located at STA: 5+43.25, and #110 is located at STA: 6+23.66					This work was completed over a week or so.
			8/31/21	9/2/21	3.00	FT	DI 709	4+25				
1210	7319913	MISC. MANHOLES AND DROP INLETS	8/25/21	9/2/21	8.00	FT	Structure #102 is located at STA: 6+27.90					This work was completed over a week or so.
			8/31/21	9/2/21	17.00		MH 911 & 912	5+64				
		15 IN. GROUP A FLARED END SECT	8/31/21	9/2/21	1.00	EA	FES 737	26+32				
1490	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	8/17/21	8/25/21 9/2/21	470.90 114.20			0		0		
			8/19/21	8/25/21	691.70			5+60		2+30		
							at the bottom of the ramp. Ramp C station to station. Part of gore point between NOR and Ramp C at about 6+92 to 6+60.					
			8/23/21	8/25/21	176.90 222.90			0		0		
			8/26/21	9/1/21	275.20		· · · · · · · · · · · · · · · · · · ·	0		0		
			8/30/21	9/1/21	271.60		I-64WB Ramp C A2 Shoulder & 9" Pavement	0		0		
1500	5021308	CONCRETE PAVEMENT (8 IN. NON-REINFORCED,	8/17/21	8/25/21	258.60	SQYD	NOR and Ramp C gore point to drop inlet	0		0		
			8/18/21	9/2/21	33.70	SQYD	SOR Lane 1 Taper Near Ramp D	0		0		
			8/23/21	8/25/21	114.40	SQYD	I-64 WB NOR/Ramp C Gore Area	0		0		
1510	5021309	CONCRETE PAVEMENT (9 IN. NON-REINFORCED,	8/17/21	8/25/21	212.00		Drop inlet on ramp C to E-joint	0		0		
			8/18/21	9/2/21 8/25/21	16.10 691.70		' '	5+60		2+30		Air percentage was above 9% in the first three truck
			0/13/21	GIZGIZ I	031.70	OQTD	at the bottom of the ramp. Ramp C station to station. Part of gore point between NOR and Ramp C at about 6+92 to 6+60.	3100		2130		were rejected by KCI.
			8/23/21	8/25/21	62.50			0		0		
			8/24/21	8/27/21 9/1/21	222.90 129.00		I-64 WB Ramp C I-64WB Ramp C 9" Pavement	0		0		
1550	5021340	TYPE A2 SHOULDER	8/26/21	9/1/21	275.20			0		0		
1000	0021010	THE SHOOLDER	8/30/21	9/1/21	142.60		I-64WB Ramp C A2 Shoulder	0		0		
1690	9015010	TRENCHING TYPE I	8/20/21	8/23/21	284.00	LF		0		0		
			8/26/21	9/1/21	332.00	LF	Lighting Circuit A1					Install in trenching 1/2 the cable conduit for lighting of
			8/27/21	0/1/21	333.00	1.5	Lighting Circuit A1					Install in trench 1/2 the cable conduit for lighting circ
1700	9015020	TRENCHING TYPE II	8/20/21	8/23/21	32.00		A2 from power supply to existing light tower on ramp A					
			8/26/21	9/1/21	37.00		Lighting circuit A1					Install in trenching 1/2 the cable conduit for lighting of
			8/27/21	9/1/21	37.00	1.5	Lighting for A1					Install in trench 1/2 the cable conduit for lighting circ
1710	9016110	PULL BOX, PREFORMED CLASS 1	8/27/21	8/23/21	1.00		E2 on ramp A					Install new pull box E2 further up slope for existing li tower. Called to be ATG but already damaged and in conflict with sewer work.
1730	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE & BRACKE	8/25/21	9/2/21	360.00	LF	B1, B2, B3, B4					The intersection of Jefferson and Ramp A, Ramp B, and SOR. These are marked in the plan book under lighting as B1, B2, B3, and B4.
1740	9017401	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS	8/26/21	9/1/21	400.00		Lighting circuit A1 Lighting for Circuit A1					Install in trenching 1/2 the cable conduit for lighting of A1 Install in trench 1/2 the cable conduit for lighting circular and the circu
1750	9017404	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS	8/20/21	8/23/21	336.00							
1760	9017407		8/26/21	9/1/21	310.00							Install remaining lighting cable conduit for Circuit B1
1770		POLE FOUNDATION (45 FT. OR 13.5 M	8/25/21	9/2/21	4.00	EA	Pole B1, B2, B3, B4					The intersection of Jefferson and Ramp A, Ramp B, and SOR. These are marked in the plan book under lighting as B1, B2, B3, and B4.
		MISC. HIGHWAY LIGHTING	8/25/21	9/2/21	4.00							The intersection of Jefferson and Ramp A, Ramp B, and SOR. These are marked in the plan book under lighting as B1, B2, B3, and B4.
1800		AND HOUSENED THE	015-1-	01417								
1820	9019902	MISC. HIGHWAY LIGHTING	8/26/21	9/1/21	0.33		Jefferson and I-64					Install lighting power supply at Jefferson and I-64
1820 1830	9019902 9019902	MISC. HIGHWAY LIGHTING	8/25/21	9/2/21	4.00	EA	Pole B1, B2, B3, B4					
1820	9019902 9019902	MISC. HIGHWAY LIGHTING				EA LF		0		0		The intersection of Jefferson and Ramp A, Ramp B, and SOR. These are marked in the plan book under

Revision 4/1/2020 Page 28 of 100



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
2100	9029100	BASE, CONCRETE	8/31/21	9/1/21	3.71	CUYD	Top of Ramp A	10+03.00		10+15.28		Pour traffic signal bases 1 and 2 at Jefferson and WB ramps.
2700	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	8/30/21	9/2/21	51.00	SQFT	Change Order 17 was approved so paying for the superstructure repairs that were completed earlier	0		0		
2810	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	8/30/21	9/2/21	886.00	SQFT	Change Order 17 was approved so paying for the superstructure repairs that were completed earlier	0		0		
2830	7049904	MISC.	8/30/21	9/2/21	189.00	SQFT	Change Order 17 was approved so paying for the superstructure repairs that were completed earlier	0		0		
3300	7034221	SLAB ON CONCRETE NU-GIRDER	8/16/21	8/25/21	176.25	SQYD	15% pay for rebar tied in place.					
			8/20/21	8/25/21	411.25	SQYD	Pay for concrete placement.					
3350	7079901	MISC. CONDUIT SYSTEM ON STRUCTURE	8/26/21	9/1/21	1.00	LS	Under Ewing Bridge					Complete Conduit installation under Ewing Bridge
3355	7110200	PROTECTIVE COATING - CONCRETE BENTS AND	8/30/21	9/2/21	1.00	LS	A8851 Bent 2	0		0		
3420	7033009	AESTHETIC CONCRETE STAIN	8/30/21	9/2/21	1.00	LS	A8852 Ewing North MSE Wall	0		0		
3440	7033009	AESTHETIC CONCRETE STAIN	8/30/21	9/2/21	1.00	LS	A8853 Ewing South MSE Wall	0		0		
5002	6141121	CURVED VANE GRATE AND FRAME(4 FT. X 2 FT	8/31/21	9/2/21	2.00	EA	DI 312 & 313	17+43		18+41		
5003	6149902	MISC. DRAINAGE FITTINGS	8/31/21	9/2/21	4.00	EA	DI 369, 379, 382, 383	1+50		4+18		
5029	7034221	SLAB ON CONCRETE NU-GIRDER	8/31/21	9/2/21	271.00	SQYD	A8831 partial slab payment increase for deck forming	0		0		
5038	7110200	PROTECTIVE COATING - CONCRETE BENTS AND	8/30/21	9/2/21	1.00	LS	A8831 Protective Coating Bents 2 & 3	0		0		
5048	7250418	18 IN. PIPE CULVERT GROUP C	8/31/21	9/2/21	99.00	LF	P-705	26+70				

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 4/1/2020 Page 29 of 100



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	0050	CLASS A EXCAVATION	Price FUEL		4	Sep 2, 2020	SYSTEM	\$24.92	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					4	Sep 2, 2020	SYSTEM	\$7.00	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					5	Sep 16, 2020	SYSTEM	\$349.60	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					7	Oct 16, 2020	SYSTEM	\$800.00	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					9	Nov 16, 2020	SYSTEM	\$1,020.00	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					10	Dec 2, 2020	SYSTEM	\$204.00	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					11	Dec 16, 2020	SYSTEM	\$1,142.60	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					13	Jan 19, 2021	SYSTEM	\$201.00	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					14	Feb 2, 2021	SYSTEM	\$3,086.82	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					17	Mar 16, 2021	SYSTEM	\$5,917.63	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					18	Apr 2, 2021	SYSTEM	\$397.80	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					19	Apr 16, 2021	SYSTEM	\$3,640.00	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					20	May 3, 2021	SYSTEM	\$2,497.82	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					21	May 17, 2021	SYSTEM	\$2,962.18	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					22	Jun 2, 2021	SYSTEM	\$1,579.26	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					28	Sep 2, 2021	SYSTEM	\$278.00	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$24,108.63	
				T-4-1				\$24,108.63	
			Price FUEL -	Total				\$24,100.03	
	0050 -	Total	Price FUEL -	Total				\$24,108.63	
	0050 -	Total COMPACTING EMBANKMENT	Material	Total	5	Sep 16, 2020	SYSTEM		This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		COMPACTING		Total	5		SYSTEM	\$24,108.63	Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment
		COMPACTING		Total		2020 Sep 16,		\$24,108.63 \$74,940.00	Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment
		COMPACTING		Total	5	2020 Sep 16, 2020 Oct 1,	SYSTEM	\$24,108.63 \$74,940.00 (\$74,940.00)	Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment
		COMPACTING		Total	5	2020 Sep 16, 2020 Oct 1, 2020	SYSTEM	\$24,108.63 \$74,940.00 (\$74,940.00) \$74,940.00	Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment
		COMPACTING		Total	5 6	2020 Sep 16, 2020 Oct 1, 2020 Oct 1, 2020 Oct 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$24,108.63 \$74,940.00 (\$74,940.00) \$74,940.00 (\$74,940.00)	Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment
		COMPACTING		Total	5 6 6 7	2020 Sep 16, 2020 Oct 1, 2020 Oct 1, 2020 Oct 16, 2020 Oct 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM	\$24,108.63 \$74,940.00 (\$74,940.00) \$74,940.00 (\$74,940.00) \$112,440.00	Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment
		COMPACTING		Total	5 6 6 7	2020 Sep 16, 2020 Oct 1, 2020 Oct 16, 2020 Oct 16, 2020 Nov 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$24,108.63 \$74,940.00 (\$74,940.00) \$74,940.00 (\$74,940.00) \$112,440.00	Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user hillto overridding Payment Estimate Item Adjustment (0010) due to user hillto overridding Payment
		COMPACTING		Total	5 6 7 7 8	2020 Sep 16, 2020 Oct 1, 2020 Oct 16, 2020 Oct 16, 2020 Nov 2, 2020 Nov 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$24,108.63 \$74,940.00 (\$74,940.00) \$74,940.00 (\$74,940.00) \$112,440.00 (\$112,440.00)	Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user hillto overridding Payment Estimate Item Adjustment (0010) due to user hillto overridding Payment
		COMPACTING		Total	5 6 7 7 8	2020 Sep 16, 2020 Oct 1, 2020 Oct 16, 2020 Oct 16, 2020 Nov 2, 2020 Nov 16, Nov 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$24,108.63 \$74,940.00 (\$74,940.00) \$74,940.00 (\$74,940.00) \$112,440.00 (\$112,440.00) (\$112,440.00)	Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Exception 1 on the current Payment Estimate.
		COMPACTING		Total	5 6 7 7 8 8	2020 Sep 16, 2020 Oct 1, 2020 Oct 16, 2020 Nov 2, 2020 Nov 16, 2020 Nov 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$24,108.63 \$74,940.00 (\$74,940.00) \$74,940.00 (\$74,940.00) \$112,440.00 (\$112,440.00) \$112,440.00 (\$112,440.00)	Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Exception 1 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	0060	COMPACTING EMBANKMENT	Material		11	Dec 16, 2020	SYSTEM	\$195,990.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user schlag1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					11	Dec 16, 2020	SYSTEM	(\$195,990.00)	
					12	Jan 4, 2021	SYSTEM	\$195,990.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
						12	Jan 4, 2021	SYSTEM	(\$195,990.00)
					13	Jan 19, 2021	SYSTEM	\$195,990.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schlag1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					13	Jan 19, 2021	SYSTEM	(\$195,990.00)	
					14	Feb 2, 2021	SYSTEM	\$197,490.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					14	Feb 2, 2021	SYSTEM	(\$197,490.00)	
					15	Feb 16, 2021	SYSTEM	\$197,490.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schlag1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					15	Feb 16, 2021	SYSTEM	(\$197,490.00)	
					16	Mar 2, 2021	SYSTEM	\$197,490.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					16	Mar 2, 2021	SYSTEM	(\$197,490.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0060 -						01/0==1/	\$0.00	
	0060 -	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	Material		22	Jun 2, 2021	SYSTEM	\$1,320.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		TYPE 1 AGGREGATE FOR	Material		22		SYSTEM		Estimate Item Adjustment (0008) due to user hillt5 overridding Payment
		TYPE 1 AGGREGATE FOR	Material			2021 Jun 2,		\$1,320.00	Estimate Item Adjustment (0008) due to user hillt5 overridding Payment
		TYPE 1 AGGREGATE FOR	Material		22	Jun 2, 2021 Jun 16,	SYSTEM	\$1,320.00 (\$1,320.00)	Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment
		TYPE 1 AGGREGATE FOR	Material		22	Jun 2, 2021 Jun 16, 2021 Jun 16,	SYSTEM	\$1,320.00 (\$1,320.00) \$1,518.00	Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment
		TYPE 1 AGGREGATE FOR	Material		22 23 23	Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1,	SYSTEM SYSTEM	\$1,320.00 (\$1,320.00) \$1,518.00 (\$1,518.00)	Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment
		TYPE 1 AGGREGATE FOR	Material		22 23 23 24	2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1,	SYSTEM SYSTEM SYSTEM SYSTEM	\$1,320.00 (\$1,320.00) \$1,518.00 (\$1,518.00) \$1,573.00	Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment
		TYPE 1 AGGREGATE FOR	Material		22 23 23 24 24	2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$1,320.00 (\$1,320.00) \$1,518.00 (\$1,518.00) \$1,573.00	Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment
		TYPE 1 AGGREGATE FOR	Material		22 23 23 24 24 25	2021 Jun 2, 2021 Jun 16, 2021 Jul 16, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$1,320.00 (\$1,320.00) \$1,518.00 (\$1,518.00) \$1,573.00 (\$1,573.00)	Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment
		TYPE 1 AGGREGATE FOR	Material		22 23 23 24 24 25 25	2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$1,320.00 (\$1,320.00) \$1,518.00 (\$1,518.00) \$1,573.00 (\$1,573.00) (\$1,573.00)	Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kloep)1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kloep)1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate.
		TYPE 1 AGGREGATE FOR	Material	- Total	22 23 23 24 24 25 25 26	2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$1,320.00 (\$1,320.00) \$1,518.00 (\$1,518.00) \$1,573.00 (\$1,573.00) \$1,573.00 (\$1,573.00)	Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kloep)1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kloep)1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate.
		TYPE 1 AGGREGATE FOR	Material - To		22 23 23 24 24 25 25 26	2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$1,320.00 (\$1,320.00) \$1,518.00 (\$1,518.00) \$1,573.00 (\$1,573.00) \$1,573.00 (\$1,573.00)	Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kloep)1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kloep)1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate.
		TYPE 1 AGGREGATE FOR			22 23 23 24 24 25 25 26 26	2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Jun 2, 2021	SYSTEM	\$1,320.00 (\$1,320.00) \$1,518.00 (\$1,518.00) \$1,573.00 (\$1,573.00) \$1,573.00 (\$1,573.00) \$1,573.00 (\$1,573.00) \$23.04	Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kloep)1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kloep)1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate. Reference Item Adjustment (0006) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		TYPE 1 AGGREGATE FOR	Material - To		22 23 23 24 24 25 25 26	2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021 Jun 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$1,320.00 (\$1,320.00) \$1,518.00 (\$1,518.00) \$1,573.00 (\$1,573.00) \$1,573.00 (\$1,573.00) \$1,573.00 (\$1,573.00) \$0.00	Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hillt5 overridding Payment Estimate Item Adjustment (0006) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks					
J6I2222	0140	TYPE 1	Price FUEL	- Total				\$27.50						
		AGGREGATE FOR BASE (4 IN. THICK)	Price FUEL -	· Total				\$27.50						
	0140 -	Total						\$27.50						
	0150	TYPE 5 AGGREGATE FOR BASE	Material		21	May 17, 2021	SYSTEM	\$1,656.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate.					
					21	May 17, 2021	SYSTEM	(\$1,656.00)						
					22	Jun 2, 2021	SYSTEM	\$1,656.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hillt5 overridding Payment Estimate Exception 2 on the current Payment Estimate.					
					22	Jun 2, 2021	SYSTEM	(\$1,656.00)						
					23	Jun 16, 2021	SYSTEM	\$1,656.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.					
					23	Jun 16, 2021	SYSTEM	(\$1,656.00)						
					24	Jul 1, 2021	SYSTEM	\$1,656.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hillt5 overridding Payment Estimate Exception 2 on the current Payment Estimate.					
					24	Jul 1, 2021	SYSTEM	(\$1,656.00)						
					25	Jul 16, 2021	SYSTEM	\$1,656.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user kloepj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.					
					25	Jul 16, 2021	SYSTEM	(\$1,656.00)						
					26	Aug 2, 2021	SYSTEM	\$1,656.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hillt5 overridding Payment Estimate Exception 2 on the current Payment Estimate.					
					26	Aug 2, 2021	SYSTEM	(\$1,656.00)						
				- Total				\$0.00						
			Material - To	tal				\$0.00						
				21	May 17, 2021	SYSTEM	\$13.82	Reference Item Price Adjustment Index Adjustment Type applied is FUEL						
				- Total				\$13.82						
			Price FUEL -	· Total				\$13.82						
	0150 -							\$13.82						
	0160	GRAVEL (A) OR CRUSHED STONE (B)	Material		18	Apr 2, 2021	SYSTEM	\$34,656.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.					
				1	18	Apr 2, 2021	SYSTEM	(\$34,656.00)						
										19	Apr 16, 2021	SYSTEM	\$34,656.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					19	Apr 16, 2021	SYSTEM	(\$34,656.00)						
										20	May 3, 2021	SYSTEM	\$34,656.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hillt5 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					20	May 3, 2021	SYSTEM	(\$34,656.00)						
				2'	21	May 17, 2021	SYSTEM	\$34,656.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate.					
					21	May 17, 2021	SYSTEM	(\$34,656.00)						
					22	Jun 2, 2021	SYSTEM	\$34,656.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hillt5 overridding Payment Estimate Exception 4 on the current Payment Estimate.					
					22	Jun 2, 2021	SYSTEM	(\$34,656.00)						



	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	0160	GRAVEL (A) OR CRUSHED STONE	Material	Туре	23	Jun 16, 2021	SYSTEM	\$34,656.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kloep 1 overridding Payment
		(B)			23	Jun 16,	SYSTEM	(\$34,656.00)	Estimate Exception 4 on the current Payment Estimate.
					24	Jul 1,	SYSTEM	\$34,656.00	This adjustment offsets the original system-generated Material Payment
					24	2021	SYSTEM	(\$34 SES 00)	Estimate Item Adjustment (0005) due to user herrmt1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					25	Jul 1, 2021 Jul 16,	SYSTEM	(\$34,656.00) \$34,656.00	This adjustment offsets the original system-generated Material Payment
					25	2021	STSTEIN	\$34,030.00	Estimate Item Adjustment (0010) due to user kloep1 overridding Payment Estimate Exception 4 on the current Payment Estimate Exception 4 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$34,656.00)	
					26	Aug 2, 2021	SYSTEM	\$34,656.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					26	Aug 2, 2021	SYSTEM	(\$34,656.00)	
					27	Aug 16, 2021	SYSTEM	\$10,656.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user herrmt1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$10,656.00)	
					28	Sep 2, 2021	SYSTEM	\$10,656.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$10,656.00)	
				- Total				\$0.00	
	0160 -	Total	Material - To	tal				\$0.00 \$0.00	
								\$0.00	
	0200	CONCRETE PAVEMENT (8 IN. NON-REINF)			0.4	84 47	OVICEEN	A4 700 00	
	0200	PAVEMENT (8 IN.	Material		21	May 17, 2021	SYSTEM	\$1,798.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 4 on the current Payment Estimate.
	0200	PAVEMENT (8 IN.	Material		21		SYSTEM	\$1,798.30 (\$1,798.30)	Estimate Item Adjustment (0008) due to user hillt5 overridding Payment
	0200	PAVEMENT (8 IN.	Material			2021 May 17,			Estimate Item Adjustment (0008) due to user hillt5 overridding Payment
	0200	PAVEMENT (8 IN.	Material		21	2021 May 17, 2021 Jun 2,	SYSTEM	(\$1,798.30)	Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0061) due to user hillt5 overridding Payment
	0200	PAVEMENT (8 IN.	Material		21	2021 May 17, 2021 Jun 2, 2021 Jun 2,	SYSTEM SYSTEM	(\$1,798.30) \$1,161.30	Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0061) due to user hillt5 overridding Payment
	0200	PAVEMENT (8 IN.	Material		21 22 22	2021 May 17, 2021 Jun 2, 2021 Jun 2, 2021 Jun 16,	SYSTEM SYSTEM	(\$1,798.30) \$1,161.30 (\$1,161.30)	Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0061) due to user hillt5 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment
	0200	PAVEMENT (8 IN.	Material		21 22 22 23	2021 May 17, 2021 Jun 2, 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,798.30) \$1,161.30 (\$1,161.30) \$14,366.80	Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0061) due to user hillt5 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment
	0200	PAVEMENT (8 IN.	Material		21 22 22 23 23	2021 May 17, 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jun 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,798.30) \$1,161.30 (\$1,161.30) \$14,366.80 (\$14,366.80)	Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0061) due to user hillt5 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user herrmt1 overridding Payment
	0200	PAVEMENT (8 IN.	Material		21 22 22 23 23 24	2021 May 17, 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,798.30) \$1,161.30 (\$1,161.30) \$14,366.80 (\$14,366.80) \$14,366.80	Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0061) due to user hillt5 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user herrmt1 overridding Payment
	0200	PAVEMENT (8 IN.	Material		21 22 22 23 23 24 24	2021 May 17, 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,798.30) \$1,161.30 (\$1,161.30) \$14,366.80 (\$14,366.80) \$14,366.80	Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0061) due to user hillt5 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user herrmt1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate.
	0200	PAVEMENT (8 IN.	Material		21 22 22 23 23 24 24 25	2021 May 17, 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Jul 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,798.30) \$1,161.30 (\$1,161.30) \$14,366.80 (\$14,366.80) \$14,366.80 (\$14,366.80)	Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0061) due to user hillt5 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hermt1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate.
	0200	PAVEMENT (8 IN.	Material		21 22 22 23 23 24 24 25 25	2021 May 17, 2021 Jun 2, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Aug 2,	SYSTEM	(\$1,798.30) \$1,161.30 (\$1,161.30) \$14,366.80 (\$14,366.80) \$14,366.80 (\$14,366.80) (\$14,366.80)	Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0061) due to user hillt5 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user herrmt1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate.
	0200	PAVEMENT (8 IN.	Material	- Total	21 22 22 23 23 24 24 25 25 26	2021 May 17, 2021 Jun 2, 2021 Jun 2, 2021 Jun 16, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021	SYSTEM	(\$1,798.30) \$1,161.30 (\$1,161.30) \$14,366.80 (\$14,366.80) \$14,366.80 (\$14,366.80) \$14,366.80 (\$14,366.80)	Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0061) due to user hillt5 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user herrmt1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate.
	0200	PAVEMENT (8 IN.	Material - To		21 22 22 23 23 24 24 25 25 26	2021 May 17, 2021 Jun 2, 2021 Jun 2, 2021 Jun 16, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021	SYSTEM	(\$1,798.30) \$1,161.30 (\$1,161.30) \$14,366.80 (\$14,366.80) \$14,366.80 (\$14,366.80) \$14,366.80 (\$14,366.80)	Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0061) due to user hillt5 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user herrmt1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hillt5 overridding Payment Estimate Item Adjustment (0009) due to user hillt6 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
J6I2222	0200	CONCRETE	Price FUEL	71		2021							
		PAVEMENT (8 IN. NON-REINF)			22	Jun 2, 2021	SYSTEM	(\$9.98)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL				
					23	Jun 16, 2021	SYSTEM	\$208.59	Reference Item Price Adjustment Index Adjustment Type applied is FUEL				
					27	Aug 16, 2021	SYSTEM	\$7.26	Reference Item Price Adjustment Index Adjustment Type applied is FUEL				
					28	Sep 2, 2021	SYSTEM	\$53.71	Reference Item Price Adjustment Index Adjustment Type applied is FUEL				
				- Total				\$287.77					
			Price FUEL -	Total				\$287.77					
	0200 -	Total						\$287.77					
	0210	TYPE A2 SHOULDER	Material		6	Oct 1, 2020	SYSTEM	\$14,241.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user kloepj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.				
					6	Oct 1, 2020	SYSTEM	(\$14,241.60)					
					7	Oct 16, 2020	SYSTEM	\$14,241.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user kloepj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.				
					7	Oct 16, 2020	SYSTEM	(\$14,241.60)					
					8	Nov 2, 2020	SYSTEM	\$14,241.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user hillt5 overridding Payment Estimate Exception 6 on the current Payment Estimate.				
					8	Nov 2, 2020	SYSTEM	(\$14,241.60)					
					9	Nov 16, 2020	SYSTEM	\$14,241.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user hillt5 overridding Payment Estimate Exception 6 on the current Payment Estimate.				
					9	Nov 16, 2020	SYSTEM	(\$14,241.60)					
					10	Dec 2, 2020	SYSTEM	\$14,880.96	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user kloepj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.				
					10	Dec 2, 2020	SYSTEM	(\$14,880.96)					
					11	Dec 16, 2020	SYSTEM	\$14,880.96	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user schlag1 overridding Payment Estimate Exception 6 on the current Payment Estimate.				
					11	Dec 16, 2020	SYSTEM	(\$14,880.96)					
					12	Jan 4, 2021	SYSTEM	\$14,880.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.				
								12	Jan 4, 2021	SYSTEM	(\$14,880.96)		
											13	Jan 19, 2021	SYSTEM
						13	Jan 19, 2021	SYSTEM	(\$14,880.96)				
						14	Feb 2, 2021	SYSTEM	\$14,880.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hillt5 overridding Payment Estimate Exception 6 on the current Payment Estimate.			
					14	Feb 2, 2021	SYSTEM	(\$14,880.96)					
							15	Feb 16, 2021	SYSTEM	\$14,880.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schlag1 overridding Payment Estimate Exception 6 on the current Payment Estimate.		
					15	Feb 16, 2021	SYSTEM	(\$14,880.96)					
						16	Mar 2, 2021	SYSTEM	\$14,880.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kloepj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.			
					16	Mar 2,	SYSTEM	(\$14,880.96)					



					_				
Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
612222	0210	TYPE A2	Material			2021			
		SHOULDER			17	Mar 16, 2021	SYSTEM	\$14,880.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					17	Mar 16, 2021	SYSTEM	(\$14,880.96)	
					18	Apr 2, 2021	SYSTEM	\$14,880.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kloepj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					18	Apr 2, 2021	SYSTEM	(\$14,880.96)	
					19	Apr 16, 2021	SYSTEM	\$14,880.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kloepj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					19	Apr 16, 2021	SYSTEM	(\$14,880.96)	
					20	May 3, 2021	SYSTEM	\$14,880.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					20	May 3, 2021	SYSTEM	(\$14,880.96)	
					21	May 17, 2021	SYSTEM	\$14,880.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hillt5 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$14,880.96)	
					22	Jun 2, 2021	SYSTEM	\$14,880.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hillt5 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$14,880.96)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	0210 -	Total						\$0.00	
	0270	WATER - UTILITY ITEM	Construction Stockpile		11	Dec 16, 2020	SYSTEM	(\$43,011.57)	Payment Estimate Item Adjustment generated Stockpile Transaction
					13	Jan 19, 2021	SYSTEM	(\$8,549.46)	Payment Estimate Item Adjustment generated Stockpile Transaction
					15	Feb 16, 2021	SYSTEM	(\$23,758.77)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$75,319.80)	
			Construction Construction Stockpile STMI	Stockpile - 1	Γotal			(\$75,319.80)	
					6	Oct 1, 2020	SYSTEM	\$75,319.80	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$75,319.80	
			Construction	Stockpile S1	ΓMI - Tota			\$75,319.80	
	0270 -	Total						\$0.00	
	0280	WATER - UTILITY ITEM	Construction Stockpile		11	Dec 16, 2020	SYSTEM	(\$13,214.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$13,214.00)	
			Construction	Stockpile - 1	Γotal			(\$13,214.00)	
			Construction Stockpile		6	Oct 1, 2020	SYSTEM	\$13,214.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$13,214.00	
			Construction	Stockpile S1	ΓΜΙ - Tota			\$13,214.00	
	0280 -	Total						\$0.00	
	0380	MODIFIED CONCRETE GUTTER TYPE B	Material		22	Jun 2, 2021	SYSTEM	\$15,062.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hillt5 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$15,062.00)	
					23	Jun 16, 2021	SYSTEM	\$15,572.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user kloepj1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
J6I2222	0380	MODIFIED	Material						Estimate Exception 19 on the current Payment Estimate.		
		CONCRETE GUTTER TYPE B			23	Jun 16, 2021	SYSTEM	(\$15,572.00)			
					24	Jul 1, 2021	SYSTEM	\$15,572.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user herrmt1 overridding Payment Estimate Exception 13 on the current Payment Estimate.		
					24	Jul 1, 2021	SYSTEM	(\$15,572.00)			
					25	Jul 16, 2021	SYSTEM	\$15,572.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 13 on the current Payment Estimate.		
					25	Jul 16, 2021	SYSTEM	(\$15,572.00)			
					26	Aug 2, 2021	SYSTEM	\$15,572.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hillt5 overridding Payment Estimate Exception 13 on the current Payment Estimate.		
					26	Aug 2, 2021	SYSTEM	(\$15,572.00)			
				- Total				\$0.00			
			Material - Tot	tal				\$0.00			
	0380 -	Total						\$0.00			
	0410	PAVED APPROACH, 8 IN.	Material		21	May 17, 2021	SYSTEM	\$9,037.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hillt5 overridding Payment Estimate Exception 19 on the current Payment Estimate.		
					21	May 17, 2021	SYSTEM	(\$9,037.50)			
					22	Jun 2, 2021	SYSTEM	\$9,037.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hillt5 overridding Payment Estimate Exception 19 on the current Payment Estimate.		
					22	Jun 2, 2021	SYSTEM	(\$9,037.50)			
					23	Jun 16, 2021	SYSTEM	\$9,037.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.		
					23	Jun 16, 2021	SYSTEM	(\$9,037.50)			
					24	Jul 1, 2021	SYSTEM	\$9,037.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user herrmt1 overridding Payment Estimate Exception 14 on the current Payment Estimate.		
					24	Jul 1, 2021	SYSTEM	(\$9,037.50)			
					25	Jul 16, 2021	SYSTEM	\$9,037.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.		
					25	Jul 16, 2021	SYSTEM	(\$9,037.50)			
						26	Aug 2, 2021	SYSTEM	\$9,037.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hillt5 overridding Payment Estimate Exception 14 on the current Payment Estimate.	
									26	Aug 2, 2021	SYSTEM
					27	Aug 16, 2021	SYSTEM	\$9,037.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user herrmt1 overridding Payment Estimate Exception 6 on the current Payment Estimate.		
					27	Aug 16, 2021	SYSTEM	(\$9,037.50)			
					28	Sep 2, 2021	SYSTEM	\$9,037.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.		
					28	Sep 2, 2021	SYSTEM	(\$9,037.50)			
				- Total				\$0.00			
			Material - To	tal				\$0.00			
			Price FUEL		21	May 17, 2021	SYSTEM	\$55.53	Reference Item Price Adjustment Index Adjustment Type applied is FUEL		
				- Total				\$55.53			



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J6I2222	0410	PAVED APPROACH, 8 IN.	Price FUEL -	Total				\$55.53		
	0410 -	Total						\$55.53		
	0420	CONCRETE SIDEWALK, 4 IN.	Material		22	Jun 2, 2021	SYSTEM	\$6,120.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hillt5 overridding Payment Estimate Exception 22 on the current Payment Estimate.	
					22	Jun 2, 2021	SYSTEM	(\$6,120.00)		
					23	Jun 16, 2021	SYSTEM	\$7,007.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 23 on the current Payment Estimate.	
					23	Jun 16, 2021	SYSTEM	(\$7,007.40)		
					24	Jul 1, 2021	SYSTEM	\$7,262.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user herrmt1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	
					24	Jul 1, 2021	SYSTEM	(\$7,262.40)		
					25	Jul 16, 2021	SYSTEM	\$7,262.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	
					25	Jul 16, 2021	SYSTEM	(\$7,262.40)		
					26	Aug 2, 2021	SYSTEM	\$7,262.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hillt5 overridding Payment Estimate Exception 15 on the current Payment Estimate.	
					26	Aug 2, 2021	SYSTEM	(\$7,262.40)		
				- Total					\$0.00	
			Material - To	tal				\$0.00		
	0420 -	Total						\$0.00		
	0440	MISC. CONCRETE	Material		23	Jun 16, 2021	SYSTEM	\$7,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.	
					23	Jun 16, 2021	SYSTEM	(\$7,100.00)		
					24	Jul 1, 2021	SYSTEM	\$10,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user herrmt1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	
					24	Jul 1, 2021	SYSTEM	(\$10,650.00)		
					25	Jul 16, 2021	SYSTEM	\$14,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	
					25	Jul 16, 2021	SYSTEM	(\$14,200.00)		
					26	Aug 2, 2021	SYSTEM	\$14,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hillt5 overridding Payment Estimate Exception 16 on the current Payment Estimate.	
					26	Aug 2, 2021	SYSTEM	(\$14,200.00)		
				- Total				\$0.00		
	0.4	Tatal	Material - To	tal				\$0.00		
	0440 - 0450	CONCRETE CURB (6 IN. HEIGHT AND	Material		25	Jul 16, 2021	SYSTEM	\$0.00 \$5,085.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment	
		` UNDER)			25	Jul 16, 2021	SYSTEM	(\$5,085.00)	Estimate Exception 17 on the current Payment Estimate.	
					26	Aug 2, 2021	SYSTEM	\$5,085.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hillt5 overridding Payment	
					26	Aug 2, 2021	SYSTEM	(\$5,085.00)	Estimate Exception 17 on the current Payment Estimate.	
						27	Aug 16, 2021	SYSTEM	\$5,085.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user herrmt1 overridding Payment
						2021			Lournate from Adjustment (0011) due to user hermit i overhading rayment	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
J6I2222	0450	CONCRETE CURB (6 IN. HEIGHT AND	Material						Estimate Exception 7 on the current Payment Estimate.		
		UNDER)			27	Aug 16, 2021	SYSTEM	(\$5,085.00)			
				- Total				\$0.00			
			Material - To	tal				\$0.00			
	0450 -	Total						\$0.00			
	0460	CONCRETE GUTTER TYPE B	Material		25	Jul 16, 2021	SYSTEM	\$8,040.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.		
					25	Jul 16, 2021	SYSTEM	(\$8,040.00)			
					26	Aug 2, 2021	SYSTEM	\$8,040.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user hillto overridding Payment Estimate Exception 18 on the current Payment Estimate.		
					26	Aug 2, 2021	SYSTEM	(\$8,040.00)	ZOSINIAO ZIAOGRAFII IO ON NIO SANONI SYNONI ZOSINIAO.		
					27	Aug 16, 2021	SYSTEM	\$8,040.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user herrmt1 overridding Payment Estimate Exception 8 on the current Payment Estimate.		
					27	Aug 16, 2021	SYSTEM	(\$8,040.00)			
					28	Sep 2, 2021	SYSTEM	\$8,040.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.		
					28	Sep 2, 2021	SYSTEM	(\$8,040.00)			
				- Total				\$0.00			
			Material - To	tal				\$0.00			
	0460 -	Total						\$0.00			
	0480	INTEGRAL CURB (6 IN. HEIGHT AND UNDER)	Material		16	Mar 2, 2021	SYSTEM	\$2,715.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user kloepi1 overridding Payment Estimate Exception 10 on the current Payment Estimate.		
					16	Mar 2, 2021	SYSTEM	(\$2,715.00)			
					17	Mar 16, 2021	SYSTEM	\$2,715.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.		
					17	Mar 16, 2021	SYSTEM	(\$2,715.00)			
					18	Apr 2, 2021	SYSTEM	\$2,715.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.		
					18	Apr 2, 2021	SYSTEM	(\$2,715.00)			
						19	Apr 16, 2021	SYSTEM	\$2,715.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	
							19	Apr 16, 2021	SYSTEM	(\$2,715.00)	
									2	20	May 3, 2021
					20	May 3, 2021	SYSTEM	(\$2,715.00)			
					21	May 17, 2021	SYSTEM	\$2,715.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user hillt5 overridding Payment Estimate Exception 22 on the current Payment Estimate.		
				21	21	May 17, 2021	SYSTEM	(\$2,715.00)			
					22	Jun 2, 2021	SYSTEM	\$2,715.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user hillt5 overridding Payment Estimate Exception 25 on the current Payment Estimate.		
				2	22	Jun 2, 2021	SYSTEM	(\$2,715.00)			
					23	Jun 16, 2021	SYSTEM	\$2,715.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment		



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	0480	INTEGRAL CURB (6 IN. HEIGHT AND	Material						Estimate Exception 28 on the current Payment Estimate.
		UNDER)			23	Jun 16, 2021	SYSTEM	(\$2,715.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0480 -	Total						\$0.00	
	0490	FURN. TYPE 2 ROCK DITCH LINER	Material		24	Jul 1, 2021	SYSTEM	\$21,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user herrmt1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$21,050.00)	
					25	Jul 16, 2021	SYSTEM	\$21,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$21,050.00)	
					26	Aug 2, 2021	SYSTEM	\$21,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user hillt5 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					26	Aug 2, 2021	SYSTEM	(\$21,050.00)	
					27	Aug 16, 2021	SYSTEM	\$21,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user herrmt1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$21,050.00)	
					28	Sep 2, 2021	SYSTEM	\$21,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$21,050.00)	
				- Total				\$0.00	
			Material - To					\$0.00 \$0.00	
	0490 -	Total	Material - To						
	0490 - 0675	Total CONCRETE TRAFFIC BARRIER, TYPE C	Material - To		3	Aug 17, 2020	SYSTEM	\$0.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		CONCRETE TRAFFIC BARRIER,			3		SYSTEM	\$0.00 \$0.00	Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment
		CONCRETE TRAFFIC BARRIER,				2020 Aug 17,		\$0.00 \$0.00 \$36,830.00	Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment
		CONCRETE TRAFFIC BARRIER,			3	2020 Aug 17, 2020 Sep 2,	SYSTEM	\$0.00 \$0.00 \$36,830.00 (\$36,830.00)	Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment
		CONCRETE TRAFFIC BARRIER,			3	2020 Aug 17, 2020 Sep 2, 2020 Sep 2,	SYSTEM SYSTEM	\$0.00 \$0.00 \$36,830.00 (\$36,830.00) \$36,830.00	Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment
		CONCRETE TRAFFIC BARRIER,			3 4	2020 Aug 17, 2020 Sep 2, 2020 Sep 2, 2020 Sep 16,	SYSTEM SYSTEM	\$0.00 \$0.00 \$36,830.00 (\$36,830.00) \$36,830.00	Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment
		CONCRETE TRAFFIC BARRIER,			3 4 4 5 5	2020 Aug 17, 2020 Sep 2, 2020 Sep 2, 2020 Sep 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$36,830.00 (\$36,830.00) \$36,830.00 (\$36,830.00)	Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment
		CONCRETE TRAFFIC BARRIER,			3 4 4 5 5	2020 Aug 17, 2020 Sep 2, 2020 Sep 16, 2020 Sep 16, 2020 Oct 1,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$36,830.00 (\$36,830.00) \$36,830.00 (\$36,830.00)	Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment
		CONCRETE TRAFFIC BARRIER,			3 4 4 5 5 6 6	2020 Aug 17, 2020 Sep 2, 2020 Sep 16, 2020 Sep 16, 2020 Oct 1, 2020 Oct 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$36,830.00 (\$36,830.00) \$36,830.00 (\$36,830.00) (\$36,830.00) \$66,845.00	Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment
		CONCRETE TRAFFIC BARRIER,			3 4 4 5 5 6 6 6	2020 Aug 17, 2020 Sep 2, 2020 Sep 16, 2020 Sep 16, 2020 Oct 1, 2020 Oct 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$36,830.00 (\$36,830.00) \$36,830.00 (\$36,830.00) (\$36,830.00) \$66,845.00	Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Exception 16 on the current Payment Estimate.
		CONCRETE TRAFFIC BARRIER,			3 4 4 5 5 6 6 7 7	2020 Aug 17, 2020 Sep 2, 2020 Sep 16, 2020 Sep 16, 2020 Oct 1, 2020 Oct 1, 2020 Oct 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$36,830.00 (\$36,830.00) \$36,830.00 (\$36,830.00) (\$36,830.00) \$66,845.00 (\$66,845.00)	Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Exception 16 on the current Payment Estimate.
		CONCRETE TRAFFIC BARRIER,			3 4 5 5 6 7 7	2020 Aug 17, 2020 Sep 2, 2020 Sep 16, 2020 Sep 16, 2020 Oct 1, 2020 Oct 1, 2020 Oct 16, 2020 Nov 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$36,830.00 (\$36,830.00) \$36,830.00 (\$36,830.00) \$66,845.00 (\$66,845.00)	Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Exception 16 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																							
J6I2222	0675	CONCRETE TRAFFIC BARRIER,	Material						Estimate Exception 14 on the current Payment Estimate.																							
		TYPE C			9	Nov 16, 2020	SYSTEM	(\$66,845.00)																								
					10	Dec 2, 2020	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.																							
					10	Dec 2, 2020	SYSTEM	(\$66,845.00)																								
							11	Dec 16, 2020	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user schlag1 overridding Payment Estimate Exception 14 on the current Payment Estimate.																					
					11	Dec 16, 2020	SYSTEM	(\$66,845.00)																								
					12	Jan 4, 2021	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kloepj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.																							
					12	Jan 4, 2021	SYSTEM	(\$66,845.00)																								
					13	Jan 19, 2021	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schlag1 overridding Payment Estimate Exception 14 on the current Payment Estimate.																							
					13	Jan 19, 2021	SYSTEM	(\$66,845.00)																								
					14	Feb 2, 2021	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hillt5 overridding Payment Estimate Exception 13 on the current Payment Estimate.																							
					14	Feb 2, 2021	SYSTEM	(\$66,845.00)																								
					15	Feb 16, 2021	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schlag1 overridding Payment Estimate Exception 21 on the current Payment Estimate.																							
					15	Feb 16, 2021	SYSTEM	(\$66,845.00)																								
												16	Mar 2, 2021	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kloepj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.																
								16	Mar 2, 2021	SYSTEM	(\$66,845.00)																					
							17	Mar 16, 2021	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kloepj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.																					
											17	Mar 16, 2021	SYSTEM	(\$66,845.00)																		
									18	Apr 2, 2021	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kloepj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.																			
																				18	Apr 2, 2021	SYSTEM	(\$66,845.00)									
																	19	Apr 16, 2021	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.											
																			19	Apr 16, 2021	SYSTEM	(\$66,845.00)										
																				2 2 2		2	2 2 2			20	May 3, 2021	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hillt5 overridding Payment Estimate Exception 19 on the current Payment Estimate.		
																								20	May 3, 2021	SYSTEM	(\$66,845.00)					
																									2	_	2	21	May 17, 2021	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hillt5 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hillts overridding Payment Estimate Exception 36 on the current Payment Estimate.																							
					22	Jun 2, 2021	SYSTEM	(\$66,845.00)																								



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	0675	CONCRETE TRAFFIC BARRIER, TYPE C	Material		23	Jun 16, 2021	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kloepj1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$66,845.00)	
					24	Jul 1, 2021	SYSTEM	\$70,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user herrmt1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$70,325.00)	
					25	Jul 16, 2021	SYSTEM	\$70,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$70,325.00)	
					26	Aug 2, 2021	SYSTEM	\$70,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hillt5 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					26	Aug 2, 2021	SYSTEM	(\$70,325.00)	
					27	Aug 16, 2021	SYSTEM	\$70,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user herrmt1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$70,325.00)	
					28	Sep 2, 2021	SYSTEM	\$70,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user kloepj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$70,325.00)	
				- Total				\$0.00	
		75 - Total							
	0075		Material - To	tal				\$0.00	
				tal	6	Oat 1	CVCTEM	\$0.00	This adjustment effects the existing austral agreement of Course Poursest
	0675 - 0690	CONCRETE TRAFFIC BARRIER, TYPE D (RETAINING WALL)	Material - To	tal	6	Oct 1, 2020	SYSTEM	\$0.00 \$15,385.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
		CONCRETE TRAFFIC BARRIER, TYPE D		tal	6		SYSTEM SYSTEM	\$0.00	Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment
		CONCRETE TRAFFIC BARRIER, TYPE D		tal		2020 Oct 1,		\$0.00 \$15,385.00	Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment
		CONCRETE TRAFFIC BARRIER, TYPE D		tal	6	2020 Oct 1, 2020 Oct 16,	SYSTEM	\$0.00 \$15,385.00 (\$15,385.00)	Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment
		CONCRETE TRAFFIC BARRIER, TYPE D		tal	6	2020 Oct 1, 2020 Oct 16, 2020	SYSTEM	\$0.00 \$15,385.00 (\$15,385.00) \$51,935.00	Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment
		CONCRETE TRAFFIC BARRIER, TYPE D		tal	6 7 7	2020 Oct 1, 2020 Oct 16, 2020 Oct 16, 2020 Nov 2,	SYSTEM SYSTEM	\$0.00 \$15,385.00 (\$15,385.00) \$51,935.00 (\$51,935.00)	Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user hillt5 overridding Payment
		CONCRETE TRAFFIC BARRIER, TYPE D		tal	6 7 7 8	2020 Oct 1, 2020 Oct 16, 2020 Oct 16, 2020 Nov 2, 2020 Nov 2,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$15,385.00 (\$15,385.00) \$51,935.00 (\$51,935.00) \$78,625.00	Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user hillt5 overridding Payment
		CONCRETE TRAFFIC BARRIER, TYPE D		tal	6 7 7 8 8 8	2020 Oct 1, 2020 Oct 16, 2020 Oct 16, 2020 Nov 2, 2020 Nov 2, 2020 Nov 16, Nov 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$15,385.00 (\$15,385.00) \$51,935.00 (\$51,935.00) \$78,625.00	Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user hillt5 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user hillt5 overridding Payment Estimate Item Adjustment (0005) due to user hillt5 overridding Payment
		CONCRETE TRAFFIC BARRIER, TYPE D		tal	6 7 7 8 8 8 9	2020 Oct 1, 2020 Oct 16, 2020 Oct 16, 2020 Nov 2, 2020 Nov 2, 2020 Nov 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$15,385.00 (\$15,385.00) \$51,935.00 (\$51,935.00) \$78,625.00 (\$78,625.00) \$79,900.00	Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user hillt5 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user hillt5 overridding Payment Estimate Item Adjustment (0005) due to user hillt5 overridding Payment
		CONCRETE TRAFFIC BARRIER, TYPE D		tal	6 7 7 8 8 8 9 9	2020 Oct 1, 2020 Oct 16, 2020 Oct 16, 2020 Nov 2, 2020 Nov 16, 2020 Nov 16, 2020 Dec 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$15,385.00 (\$15,385.00) \$51,935.00 (\$51,935.00) \$78,625.00 (\$78,625.00) \$79,900.00	Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user hillt5 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user hillt5 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Exception 17 on the current Payment Estimate.
		CONCRETE TRAFFIC BARRIER, TYPE D		tal	6 7 7 8 8 9 9 10	2020 Oct 1, 2020 Oct 16, 2020 Oct 16, 2020 Nov 2, 2020 Nov 16, 2020 Dec 2, 2020 Dec 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$15,385.00 (\$15,385.00) \$51,935.00 (\$51,935.00) \$78,625.00 (\$78,625.00) \$79,900.00 (\$79,900.00)	Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user hillt5 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user hillt5 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Exception 17 on the current Payment Estimate.
		CONCRETE TRAFFIC BARRIER, TYPE D		tal	6 7 7 8 8 9 9 10 10	2020 Oct 1, 2020 Oct 16, 2020 Oct 16, 2020 Nov 2, 2020 Nov 16, 2020 Dec 2, 2020 Dec 16,	SYSTEM	\$0.00 \$15,385.00 (\$15,385.00) \$51,935.00 (\$51,935.00) \$78,625.00 (\$78,625.00) \$79,900.00 (\$79,900.00) \$148,325.00	Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user hillt5 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user hillt5 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Exception 17 on the current Payment Estimate.
		CONCRETE TRAFFIC BARRIER, TYPE D		tal	6 7 7 8 8 9 9 10 10 11 11	2020 Oct 1, 2020 Oct 16, 2020 Oct 16, 2020 Nov 2, 2020 Nov 16, 2020 Nov 16, 2020 Dec 2, 2020 Dec 16, 2020 Dec 16, 2020	SYSTEM	\$0.00 \$15,385.00 (\$15,385.00) \$51,935.00 (\$51,935.00) \$78,625.00 (\$78,625.00) \$79,900.00 (\$79,900.00) \$148,325.00 (\$148,325.00)	Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user hillt5 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user hillt5 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Exception 17 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																													
J6I2222	0690	CONCRETE	Material			2021																																
		TRAFFIC BARRIER, TYPE D (RETAINING WALL)			13	Jan 19, 2021	SYSTEM	\$148,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schlag1 overridding Payment Estimate Exception 17 on the current Payment Estimate.																													
					13	Jan 19, 2021	SYSTEM	(\$148,325.00)																														
					14	Feb 2, 2021	SYSTEM	\$148,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hillt5 overridding Payment Estimate Exception 16 on the current Payment Estimate.																													
						14	Feb 2, 2021	SYSTEM	(\$148,325.00)																													
					15	Feb 16, 2021	SYSTEM	\$148,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schlag1 overridding Payment Estimate Exception 24 on the current Payment Estimate.																													
					15	Feb 16, 2021	SYSTEM	(\$148,325.00)																														
					16	Mar 2, 2021	SYSTEM	\$148,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 25 on the current Payment Estimate.																													
					16	Mar 2, 2021	SYSTEM	(\$148,325.00)																														
					17	Mar 16, 2021	SYSTEM	\$148,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.																													
					17	Mar 16, 2021	SYSTEM	(\$148,325.00)																														
					18	Apr 2, 2021	SYSTEM	\$148,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.																													
					18	Apr 2, 2021	SYSTEM	(\$148,325.00)																														
					19	Apr 16, 2021	SYSTEM	\$148,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.																													
							19	Apr 16, 2021	SYSTEM	(\$148,325.00)																												
										20	May 3, 2021	SYSTEM	\$194,565.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hillt5 overridding Payment Estimate Exception 22 on the current Payment Estimate.																								
						20	May 3, 2021	SYSTEM	(\$194,565.00)																													
										21	May 17, 2021	SYSTEM	\$194,565.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hillt5 overridding Payment Estimate Exception 35 on the current Payment Estimate.																								
																21	May 17, 2021	SYSTEM	(\$194,565.00)																			
											22	Jun 2, 2021	SYSTEM	\$194,565.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user hillt5 overridding Payment Estimate Exception 38 on the current Payment Estimate.																							
													2 2 2 2	22	Jun 2, 2021	SYSTEM	(\$194,565.00)																					
															2 2 2 2		2 2 2 2	23	Jun 16, 2021	SYSTEM	\$194,565.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 41 on the current Payment Estimate.																
																			2 2			23	Jun 16, 2021	SYSTEM	(\$194,565.00)													
																							2	2	2:	2	2	24					24	Jul 1, 2021	SYSTEM	\$194,565.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user herrmt1 overridding Payment Estimate Exception 23 on the current Payment Estimate.	
																													24	Jul 1, 2021	SYSTEM	(\$194,565.00)						
																																		25	Jul 16, 2021	SYSTEM	\$194,565.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
																																		2!	25			2
					26	Aug 2, 2021	SYSTEM	\$198,517.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user hillt5 overridding Payment																													



Description	erated Material Payment rrmt1 overridding Payment Estimate. erated Material Payment bepj1 overridding Payment
Page 26	rrmt1 overridding Payment Estimate. erated Material Payment bepj1 overridding Payment
2021 Estimate Item Adjustment (0014) due to user he Estimate Exception 16 on the current Payment	rrmt1 overridding Payment Estimate.
2021 28 Sep 2, 2021 29 SYSTEM \$198,517.50 This adjustment offsets the original system-general Estimate Item Adjustment (0017) due to user king the stimate of the current Payment	pepj1 overridding Payment
2021 Estimate Item Adjustment (0017) due to user kill Estimate Exception 16 on the current Payment	pepj1 overridding Payment
Total \$0.00	
Material - Total \$0.00	
Note	
Ortrun Overrun Overrun	
TRAFFIC BARRIER, CONT. FURN/RE 20 May 3, 2021 21 May 17, 2021 22 May 17, 2021 23 May 17, 2021 24 May 17, 2021 25,840.45) 26 Overrun - Total 27 Overrun - Total 28 System (\$5,840.45) Coverrun - Total (\$5,840.45) (\$5,840.45) (\$5,840.45)	
2021 2021 21 May 17, 2021 SYSTEM (\$5,840.45) Averaged Price Adjustment from this item on all of '0.00000' is applied (if non-zero). Overrun - Total (\$5,840.45) Overrun - Total (\$5,840.45) (\$5,840.45) O710 - Total (\$5,840.45)	It5 overridding Payment
2021 of '0.00000' is applied (if non-zero). Overrun - Total (\$5,840.45) Overrun - Total (\$5,840.45) O710 - Total (\$5,840.45)	
Overrun - Total (\$5,840.45) 0710 - Total (\$5,840.45)	previous payment estimates
0710 - Total (\$5,840.45)	
0990 MISC. GEOTEXTILE Material 6 Oct 1, 2020 \$11,470.00 This adjustment offsets the original system-general Estimate Item Adjustment (0019) due to user kleep the system of the current Payment Payment of the current Payment of the current Payment	pepj1 overridding Payment
6 Oct 1, SYSTEM (\$11,470.00)	
7 Oct 16, 2020 \$32,782.50 This adjustment offsets the original system-gen Estimate Item Adjustment (0017) due to user klief Estimate Exception 25 on the current Payment Item Adjustment (2017) and the control of the current Payment Item Adjustment offsets the original system-gen Estimate Item Adjustment (2017) are the control of the co	pepj1 overridding Payment
7 Oct 16, 2020 (\$32,782.50)	
8 Nov 2, 2020 SYSTEM \$32,782.50 This adjustment offsets the original system-general Estimate Item Adjustment (0011) due to user hill Estimate Exception 20 on the current Payment in Estimate Estimate Exception 20 on the Current Payment in Estimate Estim	It5 overridding Payment
8 Nov 2, 2020 SYSTEM (\$32,782.50)	
9 Nov 16, 2020 \$32,782.50 This adjustment offsets the original system-gen Estimate Item Adjustment (0011) due to user hill Estimate Exception 20 on the current Payment	It5 overridding Payment
9 Nov 16, SYSTEM (\$32,782.50)	
10 Dec 2, 2020 SYSTEM \$37,215.50 This adjustment offsets the original system-genestimate Item Adjustment (0011) due to user kleestimate Exception 20 on the current Payment	pepj1 overridding Payment
10 Dec 2, SYSTEM (\$37,215.50)	
11 Dec 16, 2020 SYSTEM \$37,215.50 This adjustment offsets the original system-genestimate Item Adjustment (0015) due to user so Estimate Exception 19 on the current Payment	hlag1 overridding Payment
11 Dec 16, SYSTEM (\$37,215.50)	
12 Jan 4, 2021 \$YSTEM \$37,215.50 This adjustment offsets the original system-gen Estimate Item Adjustment (0006) due to user kl Estimate Exception 20 on the current Payment	pepj1 overridding Payment
12 Jan 4, SYSTEM (\$37,215.50)	
13 Jan 19, 2021 \$37,215.50 This adjustment offsets the original system-genestimate Item Adjustment (0010) due to user so Estimate Exception 19 on the current Payment	
13 Jan 19, SYSTEM (\$37,215.50)	hlag1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks								
J6I2222	0990	MISC. GEOTEXTILE	Material		14	Feb 2, 2021	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 18 on the current Payment Estimate.								
					14	Feb 2, 2021	SYSTEM	(\$37,215.50)									
					15	Feb 16, 2021	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schlag1 overridding Payment Estimate Exception 26 on the current Payment Estimate.								
					15	Feb 16, 2021	SYSTEM	(\$37,215.50)									
					16	Mar 2, 2021	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment Estimate Exception 27 on the current Payment Estimate.								
					16	Mar 2, 2021	SYSTEM	(\$37,215.50)									
					17	Mar 16, 2021	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.								
					17	Mar 16, 2021	SYSTEM	(\$37,215.50)									
					18	Apr 2, 2021	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment Estimate Exception 23 on the current Payment Estimate.								
					18	Apr 2, 2021	SYSTEM	(\$37,215.50)									
					19	Apr 16, 2021	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user kloepj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.								
					19	Apr 16, 2021	SYSTEM	(\$37,215.50)									
					20	May 3, 2021	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hillt5 overridding Payment Estimate Exception 25 on the current Payment Estimate.								
					20	May 3, 2021	SYSTEM	(\$37,215.50)									
									21	May 17, 2021	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user hillt5 overridding Payment Estimate Exception 38 on the current Payment Estimate.				
														21	May 17, 2021	SYSTEM	(\$37,215.50)
						22	Jun 2, 2021	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user hillt5 overridding Payment Estimate Exception 41 on the current Payment Estimate.							
					22	Jun 2, 2021	SYSTEM	(\$37,215.50)									
													23	Jun 16, 2021	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 44 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$37,215.50)									
					24	Jul 1, 2021	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user herrmt1 overridding Payment Estimate Exception 24 on the current Payment Estimate.								
					24	Jul 1, 2021	SYSTEM	(\$37,215.50)									
					25	Jul 16, 2021	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 25 on the current Payment Estimate.								
					25	Jul 16, 2021	SYSTEM	(\$37,215.50)									
					26	Aug 2, 2021	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user hillt5 overridding Payment Estimate Exception 25 on the current Payment Estimate.								
					26	Aug 2, 2021	SYSTEM	(\$37,215.50)									
					27	Aug 16, 2021	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user herrmt1 overridding Payment Estimate Exception 17 on the current Payment Estimate.								



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																													
J6I2222	0990	MISC. GEOTEXTILE	Material	. , , , ,	27	Aug 16, 2021	SYSTEM	(\$37,215.50)																														
					28	Sep 2, 2021	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.																													
					28	Sep 2, 2021	SYSTEM	(\$37,215.50)																														
				- Total				\$0.00																														
			Material - To	tal				\$0.00																														
	0990 -	Total						\$0.00																														
	1050	MISC.	Material		8	Nov 2, 2020	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user hillt5 overridding Payment Estimate Exception 21 on the current Payment Estimate.																													
					8	Nov 2, 2020	SYSTEM	(\$23,800.00)																														
					9	Nov 16, 2020	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user hillt5 overridding Payment Estimate Exception 21 on the current Payment Estimate.																													
					9	Nov 16, 2020	SYSTEM	(\$23,800.00)																														
					10	Dec 2, 2020	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.																													
					10	Dec 2, 2020	SYSTEM	(\$23,800.00)																														
					11	Dec 16, 2020	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user schlag1 overridding Payment Estimate Exception 20 on the current Payment Estimate.																													
					11	Dec 16, 2020	SYSTEM	(\$23,800.00)																														
					12	Jan 4, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kloepj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.																													
							12	Jan 4, 2021	SYSTEM	(\$23,800.00)																												
					13	Jan 19, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schlag1 overridding Payment Estimate Exception 20 on the current Payment Estimate.																													
					13	Jan 19, 2021	SYSTEM	(\$23,800.00)																														
							14	Feb 2, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hillt5 overridding Payment Estimate Exception 31 on the current Payment Estimate.																											
													14	Feb 2, 2021	SYSTEM	(\$23,800.00)																						
																	15	Feb 16, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schlag1 overridding Payment Estimate Exception 39 on the current Payment Estimate.																	
																											15	Feb 16, 2021	SYSTEM	(\$23,800.00)								
												16	Mar 2, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kloepj1 overridding Payment Estimate Exception 35 on the current Payment Estimate.																						
																	17 17 18	17 17 18		17 17 18	17 17 18				16	Mar 2, 2021	SYSTEM	(\$23,800.00)										
																										1		1	1	1				17	Mar 16, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
																																			17	Mar 16, 2021	SYSTEM	(\$23,800.00)
																											18	Apr 2, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.							
																						18	1.	18	18							-	18	Apr 2, 2021	SYSTEM	(\$23,800.00)		
					19	Apr 16, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment																													



22		Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks								
	1050	MISC.	Material						Estimate Exception 28 on the current Payment Estimate.								
					19	Apr 16, 2021	SYSTEM	(\$23,800.00)									
					20	May 3, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hillt5 overridding Payment Estimate Exception 31 on the current Payment Estimate.								
					20	May 3, 2021	SYSTEM	(\$23,800.00)									
					21	May 17, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user hillt5 overridding Payment Estimate Exception 51 on the current Payment Estimate.								
					21	May 17, 2021	SYSTEM	(\$23,800.00)									
					22	Jun 2, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user hillt5 overridding Payment Estimate Exception 63 on the current Payment Estimate.								
							22	Jun 2, 2021	SYSTEM	(\$23,800.00)							
						23	Jun 16, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 66 on the current Payment Estimate.							
					23	Jun 16, 2021	SYSTEM	(\$23,800.00)									
					24	Jul 1, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user herrmt1 overridding Payment Estimate Exception 36 on the current Payment Estimate.								
					24	Jul 1, 2021	SYSTEM	(\$23,800.00)									
					25	Jul 16, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.								
					25	Jul 16, 2021	SYSTEM	(\$23,800.00)									
					26	Aug 2, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user hillt5 overridding Payment Estimate Exception 33 on the current Payment Estimate.								
													26	Aug 2, 2021	SYSTEM	(\$23,800.00)	
						2021											
					27	Aug 16, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user herrmt1 overridding Payment Estimate Exception 25 on the current Payment Estimate.								
					27	Aug 16,	SYSTEM	\$23,800.00 (\$23,800.00)	Estimate Item Adjustment (0016) due to user herrmt1 overridding Payment								
						Aug 16, 2021			Estimate Item Adjustment (0016) due to user herrmt1 overridding Payment								
					27	Aug 16, 2021 Aug 16, 2021 Sep 2,	SYSTEM	(\$23,800.00) \$23,800.00 (\$23,800.00)	Estimate Item Adjustment (0016) due to user herrmt1 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment								
			Motorist	- Total	27	Aug 16, 2021 Aug 16, 2021 Sep 2, 2021	SYSTEM	(\$23,800.00) \$23,800.00 (\$23,800.00)	Estimate Item Adjustment (0016) due to user herrmt1 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment								
	1050	Total	Material - To		27	Aug 16, 2021 Aug 16, 2021 Sep 2, 2021	SYSTEM	(\$23,800.00) \$23,800.00 (\$23,800.00) \$0.00	Estimate Item Adjustment (0016) due to user herrmt1 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment								
	1050 - 1060	Total AESTHETIC CONCRETE STAIN	Material - To		27	Aug 16, 2021 Aug 16, 2021 Sep 2, 2021	SYSTEM	(\$23,800.00) \$23,800.00 (\$23,800.00)	Estimate Item Adjustment (0016) due to user herrmt1 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment								
		AESTHETIC			27 28 28	Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 2, 2021	SYSTEM SYSTEM SYSTEM	(\$23,800.00) \$23,800.00 (\$23,800.00) \$0.00 \$0.00	Estimate Item Adjustment (0016) due to user herrmt1 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment								
		AESTHETIC			27 28 28 28	Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 2, 2021 Sep 2, 2021	SYSTEM SYSTEM SYSTEM	(\$23,800.00) \$23,800.00 (\$23,800.00) \$0.00 \$0.00 \$6,110.88	Estimate Item Adjustment (0016) due to user herrmt1 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment								
		AESTHETIC		tal - Total	27 28 28 28	Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 2, 2021 Sep 2, 2021	SYSTEM SYSTEM SYSTEM	(\$23,800.00) \$23,800.00 (\$23,800.00) \$0.00 \$0.00 \$6,110.88	Estimate Item Adjustment (0016) due to user herrmt1 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment								
		AESTHETIC CONCRETE STAIN	Material	tal - Total	27 28 28 28	Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 2, 2021 Sep 2, 2021	SYSTEM SYSTEM SYSTEM	(\$23,800.00) \$23,800.00 (\$23,800.00) \$0.00 \$0.00 \$6,110.88 (\$6,110.88)	Estimate Item Adjustment (0016) due to user herrmt1 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment								
	1060	AESTHETIC CONCRETE STAIN	Material Material - To	tal - Total	27 28 28 28	Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 2, 2021 Sep 2, 2021 Oct 16, 2020	SYSTEM SYSTEM SYSTEM	(\$23,800.00) \$23,800.00 (\$23,800.00) \$0.00 \$0.00 \$6,110.88 (\$6,110.88) \$0.00 \$0.00	Estimate Item Adjustment (0016) due to user herrmt1 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment								
	1060 -	AESTHETIC CONCRETE STAIN Total MECHANICALLY STABILIZED EARTH	Material Material - To	tal - Total	27 28 28 28 28	Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 2, 2021 Sep 2, 2021 Oct 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$23,800.00) \$23,800.00 (\$23,800.00) \$0.00 \$0.00 \$6,110.88 (\$6,110.88) \$0.00 \$0.00	Estimate Item Adjustment (0016) due to user herrmt1 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment								



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks						
J6I2222	1090	MECHANICALLY	Material						Estimate Exception 26 on the current Payment Estimate.						
		STABILIZED EARTH WALL SYS			8	Nov 2, 2020	SYSTEM	(\$203,640.00)							
					9	Nov 16, 2020	SYSTEM	\$203,640.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user hillt5 overridding Payment Estimate Exception 26 on the current Payment Estimate.						
					9	Nov 16, 2020	SYSTEM	(\$203,640.00)							
					10	Dec 2, 2020	SYSTEM	\$203,640.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.						
					10	Dec 2, 2020	SYSTEM	(\$203,640.00)							
						11	Dec 16, 2020	SYSTEM	\$203,640.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user schlag1 overridding Payment Estimate Exception 24 on the current Payment Estimate.					
									11	Dec 16, 2020	SYSTEM	(\$203,640.00)			
											12	Jan 4, 2021	SYSTEM	\$203,640.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
									12	Jan 4, 2021	SYSTEM	(\$203,640.00)			
					13	Jan 19, 2021	SYSTEM	\$203,640.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schlag1 overridding Payment Estimate Exception 21 on the current Payment Estimate.						
										13	Jan 19, 2021	SYSTEM	(\$203,640.00)		
					14	Feb 2, 2021	SYSTEM	\$203,640.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hillt5 overridding Payment Estimate Exception 49 on the current Payment Estimate.						
					14	Feb 2, 2021	SYSTEM	(\$203,640.00)							
				- Total	14		SYSTEM	(\$203,640.00) \$0.00							
			Material - To		14		SYSTEM	\$0.00 \$0.00							
	1090 -					2021		\$0.00 \$0.00 \$0.00							
	1090 -	SELECT GRANULAR BACKFILL FOR			7		SYSTEM	\$0.00 \$0.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.						
		SELECT GRANULAR				2021 Oct 16,		\$0.00 \$0.00 \$0.00	Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment						
		SELECT GRANULAR BACKFILL FOR			7	Oct 16, 2020	SYSTEM	\$0.00 \$0.00 \$0.00 \$41,310.00	Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment						
		SELECT GRANULAR BACKFILL FOR			7	Oct 16, 2020 Oct 16, 2020 Dec 16,	SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 \$41,310.00 (\$41,310.00)	Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user schlag1 overridding Payment						
		SELECT GRANULAR BACKFILL FOR			7 7 11	Oct 16, 2020 Oct 16, 2020 Dec 16, 2020 Dec 16, 2020	SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 \$41,310.00 (\$41,310.00) \$256,560.00	Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user schlag1 overridding Payment						
		SELECT GRANULAR BACKFILL FOR			7 7 11 11	2021 Oct 16, 2020 Oct 16, 2020 Dec 16, 2020 Dec 16, 2020 Jan 4,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 \$41,310.00 (\$41,310.00) \$256,560.00 (\$256,560.00)	Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user schlag1 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment						
		SELECT GRANULAR BACKFILL FOR			7 7 11 11 12	2021 Oct 16, 2020 Oct 16, 2020 Dec 16, 2020 Dec 16, 2020 Jan 4, 2021 Jan 4,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 \$41,310.00 (\$41,310.00) \$256,560.00 (\$256,560.00)	Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user schlag1 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment						
		SELECT GRANULAR BACKFILL FOR			7 7 11 11 12 12 12	2021 Oct 16, 2020 Oct 16, 2020 Dec 16, 2020 Dec 16, 2020 Jan 4, 2021 Jan 4, 2021 Jan 19,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 \$41,310.00 (\$41,310.00) \$256,560.00 (\$256,560.00) (\$256,560.00)	Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user schlag1 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schlag1 overridding Payment Estimate Item Adjustment (0013) due to user schlag1 overridding Payment						
		SELECT GRANULAR BACKFILL FOR			7 7 11 11 12 12 13	2021 Oct 16, 2020 Oct 16, 2020 Dec 16, 2020 Jan 4, 2021 Jan 19, 2021 Jan 19, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 \$41,310.00 (\$41,310.00) \$256,560.00 (\$256,560.00) \$256,560.00 (\$256,560.00)	Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user schlag1 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schlag1 overridding Payment Estimate Item Adjustment (0013) due to user schlag1 overridding Payment						
		SELECT GRANULAR BACKFILL FOR			7 7 11 11 12 12 13 13	2021 Oct 16, 2020 Oct 16, 2020 Dec 16, 2020 Jan 4, 2021 Jan 19, 2021 Jan 19, 2021 Feb 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 \$41,310.00 (\$41,310.00) \$256,560.00 (\$256,560.00) \$256,560.00 (\$256,560.00) \$256,560.00	Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user schlag1 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schlag1 overridding Payment Estimate Exception 24 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 24 on the current Payment Estimate.						
		SELECT GRANULAR BACKFILL FOR			7 7 11 11 12 12 13 13 14	2021 Oct 16, 2020 Oct 16, 2020 Dec 16, 2020 Jan 4, 2021 Jan 19, 2021 Jan 19, 2021 Feb 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 \$41,310.00 (\$41,310.00) \$256,560.00 (\$256,560.00) \$256,560.00 (\$256,560.00) \$256,560.00	Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user schlag1 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schlag1 overridding Payment Estimate Exception 24 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 24 on the current Payment Estimate.						



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks											
J6I2222	1100	SELECT GRANULAR BACKFILL FOR STRUCTURAL	Material		16	Mar 2, 2021	SYSTEM	\$256,560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Exception 50 on the current Payment Estimate.											
		STRUCTURAL			16	Mar 2, 2021	SYSTEM	(\$256,560.00)												
					17	Mar 16, 2021	SYSTEM	\$256,560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kloepj1 overridding Payment Estimate Exception 43 on the current Payment Estimate.											
					17	Mar 16, 2021	SYSTEM	(\$256,560.00)												
					18	Apr 2, 2021	SYSTEM	\$286,560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Exception 48 on the current Payment Estimate.											
					18	Apr 2, 2021	SYSTEM	(\$286,560.00)												
				- Total				\$0.00												
			Material - Tot				\$0.00													
	1100 -	Total						\$0.00												
	1160	MISC.	Material		9	Nov 16, 2020	SYSTEM	\$49,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user hillt5 overridding Payment Estimate Exception 29 on the current Payment Estimate.											
					9	Nov 16, 2020	SYSTEM	(\$49,500.00)												
					10	Dec 2, 2020	SYSTEM	\$55,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.											
					10	Dec 2, 2020	SYSTEM	(\$55,000.00)												
					11	Dec 16, 2020	SYSTEM	\$55,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user schlag1 overridding Payment Estimate Exception 27 on the current Payment Estimate.											
					11	Dec 16, 2020	SYSTEM	(\$55,000.00)												
					12	Jan 4, 2021	SYSTEM	\$55,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.											
					12	Jan 4, 2021	SYSTEM	(\$55,000.00)												
					13		SYSTEM	\$55,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schlag1 overridding Payment Estimate Exception 25 on the current Payment Estimate.											
					13	Jan 19, 2021	SYSTEM	(\$55,000.00)												
				- Total				\$0.00												
			Material - Tot	tal				\$0.00												
	1160 -	Total						\$0.00												
	1170	PRECAST CONCRETE DROP INLET 2 FT X 2 FT	Material		3	Aug 17, 2020	SYSTEM	\$2,450.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.											
					3			3	3	3	Aug 17, 2020	SYSTEM	(\$2,450.00)							
																			4	Sep 2, 2020
					4	Sep 2, 2020	SYSTEM	(\$4,200.00)												
					5	Sep 16, 2020	SYSTEM	\$4,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.											
					5	Sep 16, 2020	SYSTEM	(\$4,200.00)												
							6	6	Oct 1, 2020	SYSTEM	\$4,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.								
					6	Oct 1, 2020	SYSTEM	(\$4,200.00)												



oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
2222	1170	PRECAST CONCRETE DROP INLET 2 FT X 2 FT	Material	,	7	Oct 16, 2020	SYSTEM	\$4,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment Estimate Exception 30 on the current Payment Estimate.				
					7	Oct 16, 2020	SYSTEM	(\$4,200.00)					
				- Total				\$0.00					
			Material - To	tal				\$0.00					
	1170 -	Total						\$0.00					
	1180	PRECAST CONCRETE DROP INLET 4 FT X 2 FT	Material		3	Aug 17, 2020	SYSTEM	\$8,100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.				
					3	Aug 17, 2020	SYSTEM	(\$8,100.00)					
					4	Sep 2, 2020	SYSTEM	\$8,550.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.				
					4	Sep 2, 2020	SYSTEM	(\$8,550.00)					
					5	Sep 16, 2020	SYSTEM	\$8,550.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.				
					5	Sep 16, 2020	SYSTEM	(\$8,550.00)					
					6	Oct 1, 2020	SYSTEM	\$8,550.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 27 on the current Payment Estimate.				
					6	Oct 1, 2020	SYSTEM	(\$8,550.00)					
				- Total				\$0.00					
			Material - Total					\$0.00					
	1180 -				-			\$0.00					
	1190	PRECAST CONCRETE DROP INLET 5 FT X 3 FT	Material		6	Oct 1, 2020	SYSTEM	\$1,950.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.				
					6	Oct 1, 2020	SYSTEM	(\$1,950.00)					
					7	Oct 16, 2020	SYSTEM	\$15,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.				
					7	Oct 16, 2020	SYSTEM	(\$15,600.00)					
					25	Jul 16, 2021	SYSTEM	\$35,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kloepj1 overridding Payment Estimate Exception 71 on the current Payment Estimate.				
					25	Jul 16, 2021	SYSTEM	(\$35,750.00)					
					26	Aug 2, 2021	SYSTEM	\$35,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hillt5 overridding Payment Estimate Exception 75 on the current Payment Estimate.				
					26	Aug 2, 2021	SYSTEM	(\$35,750.00)					
									27	Aug 16, 2021	SYSTEM	\$35,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user herrmt1 overridding Payment Estimate Exception 71 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$35,750.00)					
					28	Sep 2, 2021	SYSTEM	\$35,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment Estimate Exception 75 on the current Payment Estimate.				
					28	Sep 2, 2021	SYSTEM	(\$35,750.00)					
				- Total				\$0.00					
			Material - Total										
	1190 -		Material - To	tal				\$0.00 \$0.00					



ject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
2222	1200	AND DROP INLETS	Material			2020			Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					3	Aug 17, 2020	SYSTEM	(\$5,610.00)	
					4	Sep 2, 2020	SYSTEM	\$5,610.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					4	Sep 2, 2020	SYSTEM	(\$5,610.00)	
					5	Sep 16, 2020	SYSTEM	\$5,610.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					5	Sep 16, 2020	SYSTEM	(\$5,610.00)	
					6	Oct 1, 2020	SYSTEM	\$10,710.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					6	Oct 1, 2020	SYSTEM	(\$10,710.00)	
					7	Oct 16, 2020	SYSTEM	\$10,710.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					7	Oct 16, 2020	SYSTEM	(\$10,710.00)	
			- Total				\$0.00		
		_	Material - To	tal				\$0.00	
	1200 -				0	0 : :	0)/2==	\$0.00	
	1210	MISC. MANHOLES AND DROP INLETS	Material		6	Oct 1, 2020	SYSTEM	\$3,850.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					6	Oct 1, 2020	SYSTEM	(\$3,850.00)	
					7	Oct 16, 2020	SYSTEM	\$12,950.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					7	Oct 16, 2020	SYSTEM	(\$12,950.00)	
					12	Jan 4, 2021	SYSTEM	\$1,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					12	Jan 4, 2021	SYSTEM	(\$1,750.00)	
					13	Jan 19, 2021	SYSTEM	\$1,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schlag1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					13	Jan 19, 2021	SYSTEM	(\$1,750.00)	
					14	Feb 2, 2021	SYSTEM	\$1,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hillt5 overridding Payment Estimate Exception 53 on the current Payment Estimate.
					14	Feb 2, 2021	SYSTEM	(\$1,750.00)	
					15	Feb 16, 2021	SYSTEM	\$1,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schlag1 overridding Payment Estimate Exception 52 on the current Payment Estimate.
					15	Feb 16, 2021	SYSTEM	(\$1,750.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1210 -	Total						\$0.00	
	1220	15 IN. GROUP A FLARED END SECT	Material		6	Oct 1, 2020	SYSTEM	\$800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					6	Oct 1, 2020	SYSTEM	(\$800.00)	
					7	Oct 16,	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Overrun Payment



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
J6I2222	1220	15 IN. GROUP A FLARED END SECT	Material			2020			Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 34 on the current Payment Estimate.				
					7	Oct 16, 2020	SYSTEM	(\$1,600.00)					
					8	Nov 2, 2020	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user hillt5 overridding Payment Estimate Exception 29 on the current Payment Estimate.				
					8	Nov 2, 2020	SYSTEM	(\$1,600.00)					
					9	Nov 16, 2020	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user hillto overridding Payment Estimate Exception 30 on the current Payment Estimate.				
					9	Nov 16, 2020	SYSTEM	(\$1,600.00)					
					10	Dec 2, 2020	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user kloepj1 overridding Payment Estimate Exception 30 on the current Payment Estimate.				
					10	Dec 2, 2020	SYSTEM	(\$1,600.00)					
									11	Dec 16, 2020	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user schlag1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					11	Dec 16, 2020	SYSTEM	(\$1,600.00)					
					12	Jan 4, 2021	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kloepj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.				
					12	Jan 4, 2021	SYSTEM	(\$1,600.00)					
					13	Jan 19, 2021	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schlag1 overridding Payment Estimate Exception 28 on the current Payment Estimate.				
					13	Jan 19, 2021	SYSTEM	(\$1,600.00)					
				- Total				\$0.00					
	1000	Total	Material - To					\$0.00					
		- Total			4	Son 2	SVSTEM	\$0.00 \$0.00	This adjustment offsets the original system generated Overrun Payment				
	1220 - 1290	ROCK DITCH CHECK			4	Sep 2, 2020	SYSTEM	\$0.00 \$0.00 \$252.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.				
		ROCK DITCH			4	2020 Sep 2, 2020	SYSTEM	\$0.00 \$0.00 \$252.00 (\$252.00)	Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.				
		ROCK DITCH				2020 Sep 2,		\$0.00 \$0.00 \$252.00	Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment				
		ROCK DITCH			4	2020 Sep 2, 2020 Sep 16,	SYSTEM	\$0.00 \$0.00 \$252.00 (\$252.00)	Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment				
		ROCK DITCH			5	2020 Sep 2, 2020 Sep 16, 2020 Sep 16,	SYSTEM	\$0.00 \$0.00 \$252.00 (\$252.00) \$252.00	Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment				
		ROCK DITCH			5	2020 Sep 2, 2020 Sep 16, 2020 Sep 16, 2020 Oct 1,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$252.00 (\$252.00) \$252.00	Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment				
		ROCK DITCH			4556	2020 Sep 2, 2020 Sep 16, 2020 Sep 16, 2020 Oct 1, 2020 Oct 1,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$252.00 (\$252.00) \$252.00 (\$252.00)	Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment				
		ROCK DITCH			4566	2020 Sep 2, 2020 Sep 16, 2020 Sep 16, 2020 Oct 1, 2020 Oct 1, 2020 Oct 1, 2020	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$252.00 (\$252.00) \$252.00 (\$252.00)	Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment				
		ROCK DITCH			45667	2020 Sep 2, 2020 Sep 16, 2020 Sep 16, 2020 Oct 1, 2020 Oct 1, 2020 Oct 16, 2020 Oct 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$252.00 (\$252.00) \$252.00 (\$252.00) \$252.00	Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment				
		ROCK DITCH			4 5 5 6 6 7 7	2020 Sep 2, 2020 Sep 16, 2020 Oct 1, 2020 Oct 1, 2020 Oct 16, 2020 Nov 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$252.00 (\$252.00) \$252.00 (\$252.00) \$252.00 (\$252.00)	Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Exception 35 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment				
		ROCK DITCH			4 5 5 6 6 7 7 8 8	2020 Sep 2, 2020 Sep 16, 2020 Sep 16, 2020 Oct 1, 2020 Oct 16, 2020 Oct 16, 2020 Nov 2, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$252.00 (\$252.00) \$252.00 (\$252.00) \$252.00 (\$252.00) \$252.00	Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Exception 35 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment				



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	1290	ROCK DITCH CHECK	Material		10	Dec 2, 2020	SYSTEM	\$252.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user kloepj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					10	Dec 2, 2020	SYSTEM	(\$252.00)	
					11	Dec 16, 2020	SYSTEM	\$252.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user schlag1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					11	Dec 16, 2020	SYSTEM	(\$252.00)	
					12	Jan 4, 2021	SYSTEM	\$252.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user kloepj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					12	Jan 4, 2021	SYSTEM	(\$252.00)	
					13	Jan 19, 2021	SYSTEM	\$252.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schlag1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					13	Jan 19, 2021	SYSTEM	(\$252.00)	
					14	Feb 2, 2021	SYSTEM	\$252.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 55 on the current Payment Estimate.
					14	Feb 2, 2021	SYSTEM	(\$252.00)	
					15	Feb 16, 2021	SYSTEM	\$252.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schlag1 overridding Payment Estimate Exception 54 on the current Payment Estimate.
					15	Feb 16, 2021	SYSTEM	(\$252.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
		· Total						\$0.00	
	1320	TEMPORARY SEEDING AND MULCHING	Material		25	Jul 16, 2021	SYSTEM	\$2,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 73 on the current Payment Estimate.
					25	Jul 16,	SYSTEM	(\$2,400.00)	
						2021			
				- Total		2021		\$0.00	
			Material - To			2021		\$0.00	
		·Total						\$0.00 \$0.00	
	1320 - 1330	Total SILT FENCE			4	Sep 2, 2020	SYSTEM	\$0.00 \$0.00 \$4,506.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					4	Sep 2,	SYSTEM	\$0.00 \$0.00	Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment
						Sep 2, 2020		\$0.00 \$0.00 \$4,506.75	Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment
					4	Sep 2, 2020 Sep 2, 2020 Sep 16,	SYSTEM	\$0.00 \$0.00 \$4,506.75 (\$4,506.75)	Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment
					5	Sep 2, 2020 Sep 2, 2020 Sep 16, 2020 Sep 16,	SYSTEM	\$0.00 \$0.00 \$4,506.75 (\$4,506.75) \$4,506.75	Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment
					5	Sep 2, 2020 Sep 2, 2020 Sep 16, 2020 Sep 16, 2020 Oct 1,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$4,506.75 (\$4,506.75) \$4,506.75	Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment
					4556	Sep 2, 2020 Sep 2, 2020 Sep 16, 2020 Oct 1, 2020 Oct 1,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$4,506.75 (\$4,506.75) \$4,506.75 (\$4,506.75) \$4,506.75	Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment
					4566	Sep 2, 2020 Sep 2, 2020 Sep 16, 2020 Oct 1, 2020 Oct 1, 2020 Oct 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$4,506.75 (\$4,506.75) \$4,506.75 (\$4,506.75) \$4,506.75	Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 33 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user kloepj1 overridding Payment
					45667	Sep 2, 2020 Sep 16, 2020 Sep 16, 2020 Oct 1, 2020 Oct 1, 2020 Oct 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$4,506.75 (\$4,506.75) \$4,506.75 (\$4,506.75) \$4,506.75 (\$4,506.75)	Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 33 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user kloepj1 overridding Payment
				tal - Total	45667	Sep 2, 2020 Sep 16, 2020 Sep 16, 2020 Oct 1, 2020 Oct 1, 2020 Oct 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$4,506.75 (\$4,506.75) \$4,506.75 (\$4,506.75) \$4,506.75 (\$4,506.75)	Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 33 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user kloepj1 overridding Payment
	1330		Material	tal - Total	45667	Sep 2, 2020 Sep 16, 2020 Sep 16, 2020 Oct 1, 2020 Oct 1, 2020 Oct 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$4,506.75 (\$4,506.75) \$4,506.75 (\$4,506.75) \$4,506.75 (\$4,506.75) \$4,506.75 (\$4,506.75)	Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 33 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user kloepj1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																	
J6I2222	1490	AGGREGATE FOR BASE (6 IN. THICK)	Material			2020			Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																	
					5	Sep 16, 2020	SYSTEM	(\$12,444.25)																		
					6	Oct 1, 2020	SYSTEM	\$14,110.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																	
					6	Oct 1, 2020	SYSTEM	(\$14,110.85)																		
					7	Oct 16, 2020	SYSTEM	\$17,094.16	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																	
					7	Oct 16, 2020	SYSTEM	(\$17,094.16)																		
						8	Nov 2, 2020	SYSTEM	\$17,094.16	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user hillto overridding Payment Estimate Exception 2 on the current Payment Estimate.																
										8	Nov 2, 2020	SYSTEM	(\$17,094.16)													
					9	Nov 16, 2020	SYSTEM	\$17,094.16	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user hillto overridding Payment Estimate Exception 2 on the current Payment Estimate.																	
							9	Nov 16, 2020	SYSTEM	(\$17,094.16)																
					10	Dec 2, 2020	SYSTEM	\$17,094.16	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																	
					10	Dec 2, 2020	SYSTEM	(\$17,094.16)																		
					11	Dec 16, 2020	SYSTEM	\$17,094.16	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user schlag1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																	
					11	Dec 16, 2020	SYSTEM	(\$17,094.16)																		
					12	Jan 4, 2021	SYSTEM	\$17,094.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user kloepj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																	
					12	Jan 4, 2021	SYSTEM	(\$17,094.16)																		
				13	Jan 19, 2021	SYSTEM	\$17,094.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schlag1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																		
							13	Jan 19, 2021	SYSTEM	(\$17,094.16)																
												14	Feb 2, 2021	SYSTEM	\$17,094.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hillt5 overridding Payment Estimate Exception 2 on the current Payment Estimate.										
																14	Feb 2, 2021	SYSTEM	(\$17,094.16)							
																		15	Feb 16, 2021	SYSTEM	\$17,094.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schlag1 overridding Payment Estimate Exception 2 on the current Payment Estimate.				
					15	Feb 16, 2021	SYSTEM	(\$17,094.16)																		
											1											16	Mar 2, 2021	SYSTEM	\$17,094.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
																	16	Mar 2, 2021	SYSTEM	(\$17,094.16)						
																				1		1				
					17	Mar 16, 2021	SYSTEM	(\$17,094.16)																		
										18	Apr 2, 2021	SYSTEM	\$17,094.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.												
					18	Apr 2,	SYSTEM	(\$17,094.16)																		



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks												
J6I2222	1490		Material			2021															
					19	Apr 16, 2021	SYSTEM	\$23,568.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.												
					19	Apr 16, 2021	SYSTEM	(\$23,568.16)													
					20	May 3, 2021	SYSTEM	\$24,747.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate.												
					20	May 3, 2021	SYSTEM	(\$24,747.26)													
					21	May 17, 2021	SYSTEM	\$25,904.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user hillt5 overridding Payment Estimate Exception 2 on the current Payment Estimate.												
					21	May 17, 2021	SYSTEM	(\$25,904.26)													
					22	Jun 2, 2021	SYSTEM	\$27,859.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate.												
					22	Jun 2, 2021	SYSTEM	(\$27,859.46)													
					23	Jun 16, 2021	SYSTEM	\$39,318.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user kloepj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.												
					23	Jun 16, 2021	SYSTEM	(\$39,318.96)													
					24	Jul 1, 2021	SYSTEM	\$53,139.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate.												
							24	Jul 1, 2021	SYSTEM	(\$53,139.26)											
					25	Jul 16, 2021	SYSTEM	\$59,894.06	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user kloepj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.												
						25	Jul 16, 2021	SYSTEM	(\$59,894.06)												
					26	Aug 2, 2021	SYSTEM	\$67,031.06	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate.												
					26	Aug 2, 2021	SYSTEM	(\$67,031.06)													
					27	Aug 16, 2021	SYSTEM	\$38,488.59	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user herrm11 overridding Payment Estimate Exception 1 on the current Payment Estimate.												
																	27	Aug 16, 2021	SYSTEM	(\$38,488.59)	
																			28	Sep 2, 2021	SYSTEM
					28	Sep 2, 2021	SYSTEM	(\$52,940.69)													
				- Total				\$0.00													
			Material - Tot	al				\$0.00													
			Price FUEL		5	Sep 16, 2020	SYSTEM	\$167.33	Reference Item Price Adjustment Index Adjustment Type applied is FUEL												
							6	Oct 1, 2020	SYSTEM	\$22.41	Reference Item Price Adjustment Index Adjustment Type applied is FUEL										
					7	Oct 16, 2020	SYSTEM	\$33.78	Reference Item Price Adjustment Index Adjustment Type applied is FUEL												
					19	Apr 16, 2021	SYSTEM	\$256.57	Reference Item Price Adjustment Index Adjustment Type applied is FUEL												
					20	May 3, 2021	SYSTEM	\$46.73	Reference Item Price Adjustment Index Adjustment Type applied is FUEL												
					21	May 17, 2021	SYSTEM	\$52.40	Reference Item Price Adjustment Index Adjustment Type applied is FUEL												
					22	Jun 2,	SYSTEM	\$88.56	Reference Item Price Adjustment Index Adjustment Type applied is FUEL												



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																	
J6I2222	1490		Price FUEL			2021																				
					23	Jun 16, 2021	SYSTEM	\$523.08	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																	
					24	Jul 1, 2021	SYSTEM	\$630.84	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																	
					25	Jul 16, 2021	SYSTEM	\$313.11	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																	
					26	Aug 2, 2021	SYSTEM	\$187.56	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																	
					26	Aug 2, 2021	SYSTEM	\$143.27	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																	
					27	Aug 16, 2021	SYSTEM	\$685.69	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																	
					28	Sep 2, 2021	SYSTEM	\$710.82	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																	
				- Total				\$3,862.15																		
			Price FUEL -	Total				\$3,862.15																		
	1490 -	- Total	Price FUEL - Total \$3,862.																							
	1500	CONCRETE PAVEMENT (8 IN. NON-REINFORCED,	Material		21	May 17, 2021	SYSTEM	\$4,080.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user hillt5 overridding Payment Estimate Exception 8 on the current Payment Estimate.																	
					21	May 17, 2021	SYSTEM	(\$4,080.00)																		
					23	Jun 16, 2021	SYSTEM	\$76,168.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user kloepj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.																	
					23	Jun 16, 2021	SYSTEM	(\$76,168.50)																		
					24	Jul 1, 2021	SYSTEM	\$127,591.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user herrmt1 overridding Payment Estimate Exception 7 on the current Payment Estimate.																	
					24	Jul 1, 2021	SYSTEM	(\$127,591.80)																		
					25	Jul 16, 2021	SYSTEM	\$155,835.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user kloepj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.																	
					25	Jul 16, 2021	SYSTEM	(\$155,835.60)																		
					26	Aug 2, 2021	SYSTEM	\$211,833.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user hillt5 overridding Payment Estimate Exception 7 on the current Payment Estimate.																	
					26	Aug 2, 2021	SYSTEM	(\$211,833.60)																		
					27	Aug 16, 2021	SYSTEM	\$265,638.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user herrmt1 overridding Payment Estimate Exception 3 on the current Payment Estimate.																	
					27	Aug 16, 2021	SYSTEM	(\$265,638.60)																		
																						28	Sep 2, 2021	SYSTEM	\$265,638.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0049) due to user kloepj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$265,638.60)																		
				- Total				\$0.00																		
			Material - To	tal				\$0.00																		
			Price FUEL		21	May 17, 2021	SYSTEM	\$61.44	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																	
					22	Jun 2, 2021	SYSTEM	(\$61.44)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																	
					23	Jun 16, 2021	SYSTEM	\$1,155.97	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																	
					24	Jul 1, 2021	SYSTEM	\$780.42	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																	
					25	Jul 16, 2021	SYSTEM	\$435.29	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																
J6I2222	1500	CONCRETE PAVEMENT (8 IN.	Price FUEL	75-	26	Aug 2, 2021	SYSTEM	\$863.02	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																
		NON-REINFORCED,			27	Aug 16, 2021	SYSTEM	\$1,216.56	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																
					28	Sep 2, 2021	SYSTEM	\$339.19	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																
				- Total				\$4,790.45																	
			Price FUEL -	Total				\$4,790.45																	
	1500 -	Total						\$4,790.45																	
	1510	CONCRETE PAVEMENT (9 IN. NON-REINFORCED,	Material		5	Sep 16, 2020	SYSTEM	\$49,717.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user kloepj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.																
					5	Sep 16, 2020	SYSTEM	(\$49,717.80)																	
					6	Oct 1, 2020	SYSTEM	\$63,768.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user kloepj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.																
						6	Oct 1, 2020	SYSTEM	(\$63,768.60)																
									7	Oct 16, 2020	SYSTEM	\$68,002.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user kloepj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.												
													7	Oct 16, 2020	SYSTEM	(\$68,002.20)									
					8	Nov 2, 2020	SYSTEM	\$68,002.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate.																
					8	Nov 2, 2020	SYSTEM	(\$68,002.20)																	
					9	Nov 16, 2020	SYSTEM	\$68,002.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate.																
					9	Nov 16, 2020	SYSTEM	(\$68,002.20)																	
					10	Dec 2, 2020	SYSTEM	\$68,002.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.																
					10	Dec 2, 2020	SYSTEM	(\$68,002.20)																	
					11	Dec 16, 2020	Estimate Item	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user schlag1 overridding Payment Estimate Exception 3 on the current Payment Estimate.																	
					11	Dec 16, 2020	SYSTEM	(\$68,002.20)																	
																		12	Jan 4, 2021	SYSTEM	\$68,002.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.			
																						12	Jan 4, 2021	SYSTEM	(\$68,002.20)
															13	Jan 19, 2021	SYSTEM	\$68,002.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schlag1 overridding Payment Estimate Exception 3 on the current Payment Estimate.						
									13	Jan 19, 2021	SYSTEM	(\$68,002.20)													
																						1			
		14 Feb 2, SYSTEM (\$6					SYSTEM	(\$68,002.20)																	
										1	15						15	Feb 16, 2021	SYSTEM	\$68,002.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schlag1 overridding Payment Estimate Exception 3 on the current Payment Estimate.				
					15	Feb 16, 2021	SYSTEM	(\$68,002.20)																	
					16	Mar 2, 2021	SYSTEM	\$68,002.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.																



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																			
J6I2222	1510	CONCRETE PAVEMENT (9 IN.	Material		16	Mar 2, 2021	SYSTEM	(\$68,002.20)																				
		NON-REINFORCED,			17	Mar 16, 2021	SYSTEM	\$68,002.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																			
					17	Mar 16, 2021	SYSTEM	(\$68,002.20)																				
					18	Apr 2, 2021	SYSTEM	\$68,002.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.																			
					18	Apr 2, 2021	SYSTEM	(\$68,002.20)																				
					19	Apr 16, 2021	SYSTEM	\$96,098.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kloepj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.																			
					19	Apr 16, 2021	SYSTEM	(\$96,098.40)	·																			
						20	May 3, 2021	SYSTEM	\$96,098.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user hillts overridding Payment Estimate Exception 3 on the current Payment Estimate.																		
									20	May 3, 2021	SYSTEM	(\$96,098.40)																
					21	May 17, 2021	SYSTEM	\$105,710.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user hillt5 overridding Payment Estimate Exception 12 on the current Payment Estimate.																			
													21	May 17, 2021	SYSTEM	(\$105,710.40)												
					22	Jun 2, 2021	SYSTEM	\$114,415.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hillt5 overridding Payment Estimate Exception 9 on the current Payment Estimate.																			
					22	Jun 2, 2021	SYSTEM	(\$114,415.20)																				
					23	Jun 16, 2021	SYSTEM	\$114,415.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user kloepj1 overridding Payment Estimate Exception 13 on the current Payment Estimate.																			
					23	Jun 16, 2021	SYSTEM	(\$114,415.20)																				
					24	Jul 1, 2021	SYSTEM	\$136,560.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user herrmt1 overridding Payment Estimate Exception 11 on the current Payment Estimate.																			
					24	Jul 1, 2021	SYSTEM	(\$136,560.60)																				
					25	Jul 16, 2021	SYSTEM	\$160,822.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kloepj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.																			
															25	Jul 16, 2021	SYSTEM	(\$160,822.80)										
																		26	Aug 2, 2021	SYSTEM	\$160,822.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user hillt5 overridding Payment Estimate Exception 11 on the current Payment Estimate.						
					26	Aug 2, 2021	SYSTEM	(\$160,822.80)																				
				- Total				\$0.00																				
			Material - To	tal	_		0)/0==	\$0.00																				
			Price FUEL		5	Sep 16, 2020	SYSTEM	\$230.91	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																			
								7	7	7	7	7	7	7	7	7	7	7	7						Oct 1, 2020	SYSTEM	\$65.26	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
																					Oct 16, 2020	SYSTEM	\$16.56	Reference Item Price Adjustment Index Adjustment Type applied is FUEL				
					19	Apr 16, 2021	SYSTEM	\$384.61	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																			
					21	May 17, 2021	SYSTEM	\$150.37	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																			
					22	Jun 2, 2021	SYSTEM	\$136.18	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																			



March Process Proces	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks												
25	J6I2222	1510	PAVEMENT (9 IN.	Price FUEL		24		SYSTEM	\$349.16	Reference Item Price Adjustment Index Adjustment Type applied is FUEL												
2021 2021			NON-REINFORCED,			25		SYSTEM	\$388.47	Reference Item Price Adjustment Index Adjustment Type applied is FUEL												
1503 1515 - 1568 1515 - 1568						27		SYSTEM	\$77.52	Reference Item Price Adjustment Index Adjustment Type applied is FUEL												
1500 Total						28		SYSTEM	\$1,224.00	Reference Item Price Adjustment Index Adjustment Type applied is FUEL												
1500 NTEGRAL CUER (I) Material 21 Mary 17, SYSTEM 215 May 18, SYSTEM 215					- Total				\$3,023.04													
1520 INTERGRAL CURS (6 N HGIGHT AND 1 2 2 2 2 2 2 2 2 2				Price FUEL -	Total				\$3,023.04													
N. HEICHT AND (INDER)		1510 -	Total						\$3,023.04													
22		1520	IN. HEIGHT AND	Material		21		SYSTEM	\$3,150.00	Estimate Item Adjustment (0039) due to user hillt5 overridding Payment												
2021 SySTEM (83,150.00) This adjustment (0035) due to user hills overridding Payment Estimate Exception 27 on the current Payment Estimate Exception 30 on the current Payment Estimate Payment Estimate Exception 30 on the current Payment Estimate Exception 30 on the current Payment Estimate Exception 30 on the current Payment E						21		SYSTEM	(\$3,150.00)													
2021 2021						22		SYSTEM	\$3,150.00	Estimate Item Adjustment (0035) due to user hillt5 overridding Payment												
2021 SySTEM Sq.150.00 This adjustment (0049) due to user kloep) forwinding Payment Estimate Exception 30 on the current Payment Estimate Exception 30 on the current Payment Estimate Estimate Exception 30 on the current Payment Estimate Estimate Exception 17 on the current Payment Estimate Es							22		SYSTEM	(\$3,150.00)												
2021 24											23		SYSTEM	\$3,150.00	Estimate Item Adjustment (0044) due to user kloepj1 overridding Payment							
2021 Estimate Exception 17 on the current Payment Estimate Exception 19 on the current Payment Estimate Estimate Estimate Exception 19 on the current Payment Estimate Estimate Estimate Exception 19 on the current Payment Estimate Est																		23		SYSTEM	(\$3,150.00)	
2021 25						24		SYSTEM	\$3,150.00	Estimate Item Adjustment (0036) due to user herrmt1 overridding Payment												
2021 Estimate Item Adjustment (0047) due to user kloopj1 overridding Payment								24		SYSTEM	(\$3,150.00)											
2021 26						25		SYSTEM	\$3,150.00	Estimate Item Adjustment (0047) due to user kloepj1 overridding Payment												
2021 Estimate Item Adjustment (0040) due to user hills overridding Payment										25		SYSTEM	(\$3,150.00)									
2021 27						26		SYSTEM	\$3,150.00	Estimate Item Adjustment (0040) due to user hillt5 overridding Payment												
2021 Estimate Item Adjustment (0035) due to user hermrit overridding Payment Estimate Exception 9 on the current Payment Estimate.						26		SYSTEM	(\$3,150.00)													
2021 28 Sep 2, 2021 29 SYSTEM \$3,150.00 Interview of the current Payment Estimate Exception 9 on the current Payment Estimate. Solution of the current Payment Estimate Exception 9 on the current Payment Estimate. Solution of the current Payment Estimate Exception 9 on the current Payment Estimate. Solution of the current Payment Estimate Exception 10 on the current Payment Estimate Estimate Exception 10 on the current Payment Estimate. Solution of the current Payment Estimate Exception 10 on the current Payment Estimate Estimate Exception 10 on the current Payment Estimate Estimate Exception 10 on the current Payment Estimate. Tock 16, SYSTEM (\$30,287.95) This adjustment offsets the original system-generated Overrun Payment Estimate Exception 10 on the current Payment Estimate. Tock 16, SYSTEM (\$30,287.95) Nov 2, SYSTEM \$30,287.95 This adjustment offsets the original system-generated Overrun Payment Estimate Exception 10 on the current Payment Estimate.						27		SYSTEM	\$3,150.00	Estimate Item Adjustment (0035) due to user herrmt1 overridding Payment												
2021 Estimafe Item Adjustment (0056) due to user kloepj1 overridding Payment Estimate Estimate Exception 9 on the current Payment Estimate.						27		SYSTEM	(\$3,150.00)													
TOTAL SO.00 Solution Succession Succ																		28	Sep 2,	SYSTEM	\$3,150.00	Estimate Item Adjustment (0056) due to user kloepj1 overridding Payment
Solution						28		SYSTEM	(\$3,150.00)	·												
Solution					- Total				\$0.00													
Solution				Material - To	tal				\$0.00													
TYPE A2 SHOULDER Material 6 Oct 1, 2020 SYSTEM \$14,224.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate. 6 Oct 1, 2020 7 Oct 16, 2020 SYSTEM \$30,287.95 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate. 7 Oct 16, 2020 SYSTEM \$30,287.95 This adjustment offsets the original system-generated Overrun Payment Estimate Exception 10 on the current Payment Estimate.		1520 -	Total																			
2020 7 Oct 16, 2020 \$30,287.95 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate. 7 Oct 16, 2020 \$YSTEM (\$30,287.95) 8 Nov 2, SYSTEM \$30,287.95 This adjustment offsets the original system-generated Overrun Payment		1550		Material		6		SYSTEM		Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment												
2020 Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate. 7 Oct 16, 2020 (\$30,287.95) 8 Nov 2, SYSTEM \$30,287.95 This adjustment offsets the original system-generated Overrun Payment						6	6	6	6	6	6	6	6	6	6	6	6	6		SYSTEM	(\$14,224.00)	
7 Oct 16, 2020 (\$30,287.95) 8 Nov 2, SYSTEM \$30,287.95 This adjustment offsets the original system-generated Overrun Payment					7	7	7		SYSTEM	\$30,287.95	Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment											
8 Nov 2, SYSTEM \$30,287.95 This adjustment offsets the original system-generated Overrun Payment						7		SYSTEM	(\$30,287.95)													
2020 Estimate Item Adjustment (0007) due to user hillit5 overridding Payment						8	Nov 2, 2020	SYSTEM	\$30,287.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user hillt5 overridding Payment												



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks															
J6I2222	1550	TYPE A2 SHOULDER	Material						Estimate Exception 8 on the current Payment Estimate.															
		SHOOLDER			8	Nov 2, 2020	SYSTEM	(\$30,287.95)																
					9	Nov 16, 2020	SYSTEM	\$30,287.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user hillt5 overridding Payment Estimate Exception 8 on the current Payment Estimate.															
					9	Nov 16, 2020	SYSTEM	(\$30,287.95)																
					10	Dec 2, 2020	SYSTEM	\$30,287.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user kloepj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.															
					10	Dec 2, 2020	SYSTEM	(\$30,287.95)																
								11	Dec 16, 2020	SYSTEM	\$30,287.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user schlag1 overridding Payment Estimate Exception 8 on the current Payment Estimate.												
					11	Dec 16, 2020	SYSTEM	(\$30,287.95)																
					12	Jan 4, 2021	SYSTEM	\$30,287.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.															
						12	Jan 4, 2021	SYSTEM	(\$30,287.95)															
					13	Jan 19, 2021	SYSTEM	\$30,287.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schlag1 overridding Payment Estimate Exception 8 on the current Payment Estimate.															
						13	Jan 19, 2021	SYSTEM	(\$30,287.95)															
					14	Feb 2, 2021	SYSTEM	\$30,287.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user hillt5 overridding Payment Estimate Exception 8 on the current Payment Estimate.															
					14	Feb 2, 2021	SYSTEM	(\$30,287.95)																
							15	Feb 16, 2021	SYSTEM	\$30,287.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schlag1 overridding Payment Estimate Exception 8 on the current Payment Estimate.													
					15	Feb 16, 2021	SYSTEM	(\$30,287.95)																
					16	Mar 2, 2021	SYSTEM	\$30,287.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.															
							16	Mar 2, 2021	SYSTEM	(\$30,287.95)														
												17	Mar 16, 2021	SYSTEM	\$30,287.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.								
																	17	Mar 16, 2021	SYSTEM	(\$30,287.95)				
															18	Apr 2, 2021	SYSTEM	\$30,287.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.					
					18	Apr 2, 2021	SYSTEM	(\$30,287.95)																
			1 2					15	2		15				1		19	Apr 16, 2021	SYSTEM	\$46,937.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.			
																	19	Apr 16, 2021	SYSTEM	(\$46,937.45)				
																		2		2		2		
												20	May 3, 2021	SYSTEM	(\$53,286.45)									
					21	May 17, 2021	SYSTEM	\$53,286.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user hillt5 overridding Payment Estimate Exception 16 on the current Payment Estimate.															
					21	May 17, 2021	SYSTEM	(\$53,286.45)																



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks														
J6I2222	1550	TYPE A2 SHOULDER	Material	. , , , ,	22	Jun 2, 2021	SYSTEM	\$53,286.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user hillt5 overridding Payment Estimate Exception 13 on the current Payment Estimate.														
					22	Jun 2, 2021	SYSTEM	(\$53,286.45)															
					23	Jun 16, 2021	SYSTEM	\$53,286.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user kloepj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.														
					23	Jun 16, 2021	SYSTEM	(\$53,286.45)															
					28	Sep 2, 2021	SYSTEM	\$1,386.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0057) due to user kloepj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.														
					28	Sep 2, 2021	SYSTEM	(\$1,386.00)															
				- Total				\$0.00															
			Material - To	tal				\$0.00															
	1550 -	Total						\$0.00															
	1560	INTEGRAL CURB (6 IN. HEIGHT AND UNDER)	Material		6	Oct 1, 2020	SYSTEM	\$3,375.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user kloepj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.														
					6	Oct 1, 2020	SYSTEM	(\$3,375.00)															
					7	Oct 16, 2020	SYSTEM	\$3,375.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user kloepj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.														
					7	Oct 16, 2020	SYSTEM	(\$3,375.00)															
					8	Nov 2, 2020	SYSTEM	\$3,375.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 10 on the current Payment Estimate.														
					8	Nov 2, 2020	SYSTEM	(\$3,375.00)															
					9	Nov 16, 2020	SYSTEM	\$3,375.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 10 on the current Payment Estimate.														
					9	Nov 16, 2020	SYSTEM	(\$3,375.00)															
					10	Dec 2, 2020	SYSTEM	\$3,375.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.														
					10	Dec 2, 2020	SYSTEM	(\$3,375.00)															
					11	Dec 16, 2020	SYSTEM	\$3,375.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user schlag1 overridding Payment Estimate Exception 10 on the current Payment Estimate.														
																			11	Dec 16, 2020	SYSTEM	(\$3,375.00)	
			1																	12	Jan 4, 2021	SYSTEM	\$3,375.00
									12	Jan 4, 2021	SYSTEM	(\$3,375.00)											
													1										13
					13	Jan 19, 2021	SYSTEM	(\$3,375.00)															
					14	Feb 2, 2021	SYSTEM	\$3,375.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user hillt5 overridding Payment Estimate Exception 10 on the current Payment Estimate.														
					14	Feb 2, 2021	SYSTEM	(\$3,375.00)															
					15	Feb 16, 2021	SYSTEM	\$3,375.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schlag1 overridding Payment Estimate Exception 10 on the current Payment Estimate.														
					15	Feb 16,	SYSTEM	(\$3,375.00)															



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	1560	INTEGRAL CURB (6 IN. HEIGHT AND	Material			2021			
		UNDER)			16	Mar 2, 2021	SYSTEM	\$3,375.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					16	Mar 2, 2021	SYSTEM	(\$3,375.00)	
					17	Mar 16, 2021	SYSTEM	\$3,375.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					17	Mar 16, 2021	SYSTEM	(\$3,375.00)	
					18	Apr 2, 2021	SYSTEM	\$3,375.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					18	Apr 2, 2021	SYSTEM	(\$3,375.00)	
					19	Apr 16, 2021	SYSTEM	\$4,575.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					19	Apr 16, 2021	SYSTEM	(\$4,575.00)	
					20	May 3, 2021	SYSTEM	\$7,380.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user hillt5 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					20	May 3, 2021	SYSTEM	(\$7,380.00)	
					21	May 17, 2021	SYSTEM	\$7,380.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user hillt5 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$7,380.00)	
					22	Jun 2, 2021	SYSTEM	\$7,380.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user hillt5 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$7,380.00)	
					23	Jun 16, 2021	SYSTEM	\$7,380.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user kloepj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$7,380.00)	
					24	Jul 1, 2021	SYSTEM	\$7,680.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user herrmt1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$7,680.00)	
					25	Jul 16, 2021	SYSTEM	\$7,680.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0048) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$7,680.00)	
					26	Aug 2, 2021	SYSTEM	\$7,680.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user hillt5 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					26	Aug 2, 2021	SYSTEM	(\$7,680.00)	
					27	Aug 16, 2021	SYSTEM	\$7,680.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user herrmt1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$7,680.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1560 -	Total						\$0.00	
	1570	MGS GUARDRAIL	Construction Stockpile		16	Mar 2, 2021	SYSTEM	(\$4,220.86)	Payment Estimate Item Adjustment generated Stockpile Transaction



Li	ne	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks					
15	70	MGS GUARDRAIL	Construction Stockpile		20	May 3, 2021	SYSTEM	(\$589.21)	Payment Estimate Item Adjustment generated Stockpile Transaction					
				- Total				(\$4,810.07)						
			Construction	Stockpile - 1	Γotal			(\$4,810.07)						
			Construction Stockpile		3	Aug 17, 2020	SYSTEM	\$38,968.86	Payment Estimate Item Adjustment generated Stockpile Transaction					
			STMI	- Total				\$38,968.86						
			Construction	Stockpile S	TMI - Tota			\$38,968.86						
			Material		20	May 3, 2021	SYSTEM	\$8,797.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user hillt5 overridding Payment Estimate Exception 10 on the current Payment Estimate.					
					20	May 3, 2021	SYSTEM	(\$8,797.00)						
					21	May 17, 2021	SYSTEM	\$8,797.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user hillt5 overridding Payment Estimate Exception 18 on the current Payment Estimate.					
					21	May 17, 2021	SYSTEM	(\$8,797.00)						
					22	Jun 2, 2021	SYSTEM	\$8,797.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user hillt5 overridding Payment Estimate Exception 15 on the current Payment Estimate.					
					22	Jun 2, 2021	SYSTEM	(\$8,797.00)						
					23	Jun 16, 2021	SYSTEM	\$8,797.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Paymer Estimate Exception 18 on the current Payment Estimate.					
						23	Jun 16, 2021	SYSTEM	(\$8,797.00)					
										24	Jul 1, 2021	SYSTEM	\$8,797.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user herrmt1 overridding Payme Estimate Exception 12 on the current Payment Estimate.
							24	Jul 1, 2021	SYSTEM	(\$8,797.00)				
						25	Jul 16, 2021	SYSTEM	\$8,797.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user kloepj1 overridding Paymer Estimate Exception 12 on the current Payment Estimate.				
							25	Jul 16, 2021	SYSTEM	(\$8,797.00)				
					26	Aug 2, 2021	SYSTEM	\$8,797.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user hillt5 overridding Payment Estimate Exception 12 on the current Payment Estimate.					
					26	Aug 2, 2021	SYSTEM	(\$8,797.00)						
					27	Aug 16, 2021	SYSTEM	\$8,797.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user herrmt1 overridding Payme Estimate Exception 5 on the current Payment Estimate.					
					27	Aug 16, 2021	SYSTEM	(\$8,797.00)						
					28	Sep 2, 2021	SYSTEM	\$8,797.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Paymer Estimate Exception 6 on the current Payment Estimate.					
					28	Sep 2, 2021	SYSTEM	(\$8,797.00)						
				- Total				\$0.00						
			Material - Tot	al				\$0.00						
15	70 -	Total						\$34,158.79						
15	80	MGS BRIDGE APP. TRANS SEC (EXT CURB)	Construction Stockpile STMI		3	Aug 17, 2020	SYSTEM	\$3,016.00	Payment Estimate Item Adjustment generated Stockpile Transaction					
		33.15)		- Total				\$3,016.00						
			Construction	Stockpile S	TMI - Tota			\$3,016.00						
15	80 -	Total						\$3,016.00						
15	90	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	Construction Stockpile STMI		3	Aug 17, 2020	SYSTEM	\$2,920.00	Payment Estimate Item Adjustment generated Stockpile Transaction					
		(,		- Total				\$2,920.00						



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
612222	1590	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	Construction	Stockpile S1	ГМI - Total			\$2,920.00	
	1590 -	Total						\$2,920.00	
	1600	MGS VERTICAL CONCRETE	Construction Stockpile		16	Mar 2, 2021	SYSTEM	(\$3,795.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		BARRIER TRANSITION			20	May 3, 2021	SYSTEM	(\$1,265.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$5,060.00)	
			Construction	Stockpile - 1	Γotal			(\$5,060.00)	
			Construction Stockpile STMI		3	Aug 17, 2020	SYSTEM	\$13,915.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STIVII	- Total				\$13,915.00	
			Construction	Stockpile S1	ГМI - Total			\$13,915.00	
	1600 -	Total						\$8,855.00	
	1610	MGS END ANCHOR	Construction Stockpile		16	Mar 2, 2021	SYSTEM	(\$532.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$532.00)	
			Construction	Stockpile - 1	Total			(\$532.00)	
			Construction Stockpile STMI		3	Aug 17, 2020	SYSTEM	\$4,256.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$4,256.00	
			Construction	Stockpile S	ГМI - Total			\$4,256.00	
	1610 -							\$3,724.00	
	1620	TYPE A CRASHWORTHY END TERMINAL	Construction Stockpile		16	Mar 2, 2021	SYSTEM	(\$4,473.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		(MASH)			20	May 3, 2021	SYSTEM	(\$1,491.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$5,964.00)	
				Stockpile - 1		A 47	0)/07514	(\$5,964.00)	
			Construction Stockpile STMI		3	Aug 17, 2020	SYSTEM	\$17,892.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			O a made madi a m	- Total	FB81 - T-4-1			\$17,892.00	
	1620 -	Total	Construction	Stockpile 5	i wii - Totai			\$17,892.00	
	1630	TYPE E CRASHWORTHY	Construction Stockpile		2	Aug 3, 2020	SYSTEM	\$11,928.00 \$18,995.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		END TERMINAL	STMI	- Total				\$18,995.00	
			Construction	Stockpile S	ΓΜΙ - Tot <u>a</u> l			\$18,995.00	
	1630 -	Total						\$18,995.00	
	1730	CABLE, 10 AWG 1 CONDUCTOR, POLE & BRACKE	Material		28	Sep 2, 2021	SYSTEM	\$198.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment Estimate Exception 76 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$198.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1730 -	Total						\$0.00	
	1740	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS	Material		28	Sep 2, 2021	SYSTEM	\$4,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment Estimate Exception 77 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$4,800.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1740 -	Total						\$0.00	
	1750	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS	Material		28	Sep 2, 2021	SYSTEM	\$1,209.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user kloepj1 overridding Payment Estimate Exception 78 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	1750	CABLE-CONDUIT, 1 IN., 2	Material	. , , , ,	28	Sep 2, 2021	SYSTEM	(\$1,209.60)	
		CONDUCTORS		- Total				\$0.00	
			Material - Tot	tai				\$0.00	
	1750 -	Total						\$0.00	
	1760	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS	Material		28	Sep 2, 2021	SYSTEM	\$899.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user kloepj1 overridding Payment Estimate Exception 79 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$899.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	1760 -	Total						\$0.00	
	1770	POLE FOUNDATION (45 FT. OR 13.5 M	Material		28	Sep 2, 2021	SYSTEM	\$4,272.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user kloepj1 overridding Payment Estimate Exception 80 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$4,272.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	1770 -	Total						\$0.00	
	1780	MISC. HIGHWAY LIGHTING	Material		3	Aug 17, 2020	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user kloepi1 overridding Payment
					3	Aug 17, 2020	SYSTEM	(\$16,605.00)	Estimate Exception 10 on the current Payment Estimate.
					4	Sep 2, 2020	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					4	Sep 2, 2020	SYSTEM	(\$16,605.00)	Zamace Zasopies 12 state states to Synant Zamace.
					5	Sep 16, 2020	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					5	Sep 16, 2020	SYSTEM	(\$16,605.00)	
					6	Oct 1, 2020	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
					6	Oct 1, 2020	SYSTEM	(\$16,605.00)	
					7	Oct 16, 2020	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
					7	Oct 16, 2020	SYSTEM	(\$16,605.00)	
					8	Nov 2, 2020	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user hillt5 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					8	Nov 2, 2020	SYSTEM	(\$16,605.00)	
					9	Nov 16, 2020	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user hillt5 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					9	Nov 16, 2020	SYSTEM	(\$16,605.00)	
					10	Dec 2, 2020	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					10	Dec 2, 2020	SYSTEM	(\$16,605.00)	
					11	Dec 16, 2020	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user schlag1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					11	Dec 16,	SYSTEM	(\$16,605.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	1780	MISC. HIGHWAY LIGHTING	Material			2020			
		LIGHTING			12	Jan 4, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					12	Jan 4, 2021	SYSTEM	(\$16,605.00)	
					13	Jan 19, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schlag1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					13	Jan 19, 2021	SYSTEM	(\$16,605.00)	
					14	Feb 2, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hillt5 overridding Payment Estimate Exception 56 on the current Payment Estimate.
					14	Feb 2, 2021	SYSTEM	(\$16,605.00)	
					15	Feb 16, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schlag1 overridding Payment Estimate Exception 55 on the current Payment Estimate.
					15	Feb 16, 2021	SYSTEM	(\$16,605.00)	
					16	Mar 2, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 51 on the current Payment Estimate.
					16	Mar 2, 2021	SYSTEM	(\$16,605.00)	
					17	Mar 16, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user kloepj1 overridding Payment Estimate Exception 44 on the current Payment Estimate.
					17	Mar 16, 2021	SYSTEM	(\$16,605.00)	
					18	Apr 2, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment Estimate Exception 58 on the current Payment Estimate.
					18	Apr 2, 2021	SYSTEM	(\$16,605.00)	
					19	Apr 16, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 66 on the current Payment Estimate.
					19	Apr 16, 2021	SYSTEM	(\$16,605.00)	
					20	May 3, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user hillt5 overridding Payment Estimate Exception 91 on the current Payment Estimate.
					20	May 3, 2021	SYSTEM	(\$16,605.00)	
					21	May 17, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user hillt5 overridding Payment Estimate Exception 111 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$16,605.00)	
					22	Jun 2, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user hillt5 overridding Payment Estimate Exception 122 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$16,605.00)	
					23	Jun 16, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 121 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$16,605.00)	
					24	Jul 1, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user herrmt1 overridding Payment Estimate Exception 80 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$16,605.00)	
					25	Jul 16, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	1780	MISC. HIGHWAY LIGHTING	Material						Estimate Exception 76 on the current Payment Estimate.
		LIGITING			25	Jul 16, 2021	SYSTEM	(\$16,605.00)	
					26	Aug 2, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hillt5 overridding Payment Estimate Exception 76 on the current Payment Estimate.
					26	Aug 2, 2021	SYSTEM	(\$16,605.00)	
					27	Aug 16, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user herrmt1 overridding Payment Estimate Exception 72 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$16,605.00)	
					28	Sep 2, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user kloepj1 overridding Payment Estimate Exception 82 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$16,605.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	1780 -	Total						\$0.00	
	1800	MISC. HIGHWAY LIGHTING	Material		28	Sep 2, 2021	SYSTEM	\$9,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user kloepj1 overridding Payment Estimate Exception 84 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$9,000.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	1800 -							\$0.00	
	1820	MISC. HIGHWAY LIGHTING	Material		28	Sep 2, 2021	SYSTEM	\$2,395.14	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user kloepj1 overridding Payment Estimate Exception 85 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$2,395.14)	
				- Total				\$0.00	
	1000		Material - Tot	tal				\$0.00	
	1820 -				00	0 0	0)/07514	\$0.00	Ti
	1830	MISC. HIGHWAY LIGHTING	Material		28	Sep 2, 2021	SYSTEM	\$2,288.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user kloepj1 overridding Payment Estimate Exception 83 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$2,288.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	1830 -							\$0.00	
	1870	SIGNAL HEAD, TYPE 3B	Material		21	May 17, 2021	SYSTEM	\$4,635.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user hillt5 overridding Payment Estimate Exception 112 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$4,635.00)	
					22	Jun 2, 2021	SYSTEM	\$4,635.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hillt5 overridding Payment Estimate Exception 123 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$4,635.00)	
					23	Jun 16, 2021	SYSTEM	\$4,635.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 122 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$4,635.00)	
					24	Jul 1, 2021	SYSTEM	\$4,635.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user herrmt1 overridding Payment Estimate Exception 81 on the current Payment Estimate.
					24	Jul 1,	SYSTEM	(\$4,635.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																					
J6I2222	1870	SIGNAL HEAD,	Material	Type		2021																								
		TYPE 3B			25	Jul 16, 2021	SYSTEM	\$4,635.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user kloepj1 overridding Payment Estimate Exception 77 on the current Payment Estimate.																					
					25	Jul 16, 2021	SYSTEM	(\$4,635.00)																						
					26	Aug 2, 2021	SYSTEM	\$4,635.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user hillt5 overridding Payment Estimate Exception 77 on the current Payment Estimate.																					
					26	Aug 2, 2021	SYSTEM	(\$4,635.00)																						
					27	Aug 16, 2021	SYSTEM	\$4,635.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user herrmt1 overridding Payment Estimate Exception 73 on the current Payment Estimate.																					
					27	Aug 16, 2021	SYSTEM	(\$4,635.00)																						
					28	Sep 2, 2021	SYSTEM	\$4,635.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user kloepj1 overridding Payment Estimate Exception 88 on the current Payment Estimate.																					
					28	Sep 2,	SYSTEM	(\$4,635.00)	Estimate exception of on the current Payment Estimate.																					
				- Total		2021		\$0.00																						
			Material - Tot					\$0.00																						
	1870 -	Total						\$0.00																						
	1910	POST, SIGNAL 8 FT. OR 2.4 M	Material		21	May 17, 2021	SYSTEM	\$1,935.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hillt5 overridding Payment Estimate Exception 113 on the current Payment Estimate.																					
					21	May 17, 2021	SYSTEM	(\$1,935.00)																						
					22	Jun 2, 2021	SYSTEM	\$1,935.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user hillt5 overridding Payment Estimate Exception 124 on the current Payment Estimate.																					
					22	Jun 2, 2021	SYSTEM	(\$1,935.00)																						
					23	Jun 16, 2021	SYSTEM	\$1,935.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 123 on the current Payment Estimate.																					
					23	Jun 16, 2021	SYSTEM	(\$1,935.00)																						
					24	Jul 1, 2021	SYSTEM	\$1,935.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user herrmt1 overridding Payment Estimate Exception 82 on the current Payment Estimate.																					
					24	Jul 1, 2021	SYSTEM	(\$1,935.00)																						
					25	Jul 16, 2021	SYSTEM	\$1,935.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user kloepj1 overridding Payment Estimate Exception 78 on the current Payment Estimate.																					
					25	Jul 16, 2021	SYSTEM	(\$1,935.00)																						
					26	Aug 2, 2021	SYSTEM	\$1,935.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user hillt5 overridding Payment Estimate Exception 78 on the current Payment Estimate.																					
					26	Aug 2, 2021	SYSTEM	(\$1,935.00)																						
							2		2		2	2	27								3					27	Aug 16, 2021	SYSTEM	\$1,935.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user herrmt1 overridding Payment Estimate Exception 74 on the current Payment Estimate.
														27	Aug 16, 2021	SYSTEM	(\$1,935.00)													
															2						2!	28	28	28	2		28	Sep 2, 2021	SYSTEM	\$1,935.00
					28	Sep 2, 2021	SYSTEM	(\$1,935.00)																						
				- Total				\$0.00																						
			Material - Tot					\$0.00																						



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks							
J6I2222	1910 -	Total						\$0.00								
	1960	POST, TYPE C, 55 FT. ARM	Material		21	May 17, 2021	SYSTEM	\$11,930.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user hillt5 overridding Payment Estimate Exception 116 on the current Payment Estimate.							
					21	May 17, 2021	SYSTEM	(\$11,930.00)								
					22	Jun 2, 2021	SYSTEM	\$11,930.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user hillt5 overridding Payment Estimate Exception 127 on the current Payment Estimate.							
					22	Jun 2, 2021	SYSTEM	(\$11,930.00)								
					23	Jun 16, 2021	SYSTEM	\$11,930.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment Estimate Exception 126 on the current Payment Estimate.							
					23	Jun 16, 2021	SYSTEM	(\$11,930.00)								
					24	Jul 1, 2021	SYSTEM	\$11,930.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user herrmt1 overridding Payment Estimate Exception 85 on the current Payment Estimate.							
					24	Jul 1, 2021	SYSTEM	(\$11,930.00)								
					25	Jul 16, 2021	SYSTEM	\$11,930.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user kloepj1 overridding Payment Estimate Exception 81 on the current Payment Estimate.							
					25	Jul 16, 2021	SYSTEM	(\$11,930.00)								
					26	Aug 2, 2021	SYSTEM	\$11,930.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user hillt5 overridding Payment Estimate Exception 81 on the current Payment Estimate.							
												26	Aug 2, 2021	SYSTEM	(\$11,930.00)	
					27	Aug 16, 2021	SYSTEM	\$11,930.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user herrmt1 overridding Payment Estimate Exception 77 on the current Payment Estimate.							
					27	Aug 16, 2021	SYSTEM	(\$11,930.00)								
					28	Sep 2, 2021	SYSTEM	\$11,930.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user kloepj1 overridding Payment Estimate Exception 92 on the current Payment Estimate.							
					28	Sep 2, 2021	SYSTEM	(\$11,930.00)								
				- Total				\$0.00								
			Material - To	tal				\$0.00								
	1960 -	Total						\$0.00								
	1990	CONTROLLER ASSEMBLY HOUSING,	Material		21	May 17, 2021	SYSTEM	\$13,359.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user hillt5 overridding Payment Estimate Exception 117 on the current Payment Estimate.							
					21	May 17, 2021	SYSTEM	(\$13,359.00)								
								22	Jun 2, 2021	SYSTEM	\$13,359.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user hillt5 overridding Payment Estimate Exception 129 on the current Payment Estimate.				
					22	Jun 2, 2021	SYSTEM	(\$13,359.00)								
					23	Jun 16, 2021	SYSTEM	\$13,359.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment Estimate Exception 128 on the current Payment Estimate.							
					23	Jun 16, 2021	SYSTEM	(\$13,359.00)								
					24	Jul 1, 2021	SYSTEM	\$13,359.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user herrmt1 overridding Payment Estimate Exception 87 on the current Payment Estimate.							
					24	Jul 1, 2021	SYSTEM	(\$13,359.00)								
					25	Jul 16, 2021	SYSTEM	\$13,359.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user kloepj1 overridding Payment Estimate Exception 82 on the current Payment Estimate.							



CONTINUE NAME	Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
HOUSING. 28	J6I2222	1990		Material	Туре	25		SYSTEM	(\$13,359.00)	
27						26	Aug 2,	SYSTEM	\$13,359.00	Estimate Item Adjustment (0025) due to user hillt5 overridding Payment
2011 2021						26		SYSTEM	(\$13,359.00)	
27 Aug 46 SYSTEM (\$13,359.00) This adjustment offsets the original system-generated Material Payment Estimate Exception 93 on the current Payment Estimate Exception 183 on the current Payment Estimate Payment Estimate Exception 183 on the current Payment Estimate Payment Estimate Exception 183 on the current Payment Estimate Payment Est						27		SYSTEM	\$13,359.00	Estimate Item Adjustment (0022) due to user herrmt1 overridding Payment
28 Sep 2 SYSTEM \$13.550.00 This adjustment offsets the Augustume (1000) are to see theight overriding Payment Estimate Exception 93 on the oursent Payment Estimate Estimate Exception 13 on the ourself Payment Estimate Estimate Estimate Exception 13 on the ourself Payment Estimate Estimate Exception 13 on the ourself Payment Estimate Estimate Exception 13 on the ourself						27		SYSTEM	(\$13,359.00)	Zamace Zacopien i o on the canonic symbol Zamace.
Separation Sep						28	Sep 2,	SYSTEM	\$13,359.00	
Total Section Sectio						28		SYSTEM	(\$13,359.00)	Estimate Exception 93 on the current Payment Estimate.
1980 - Total 1980 - Total 200					- Total		2021		\$0.00	
1990 - Total				Material - Tot						
PUSHED WITH TRACER WIRE Coverrun - Total (\$621.00) Coverrun - Total (\$621.00) (\$621.00) Coverrun - Total (\$621.00)		1990 -	Total							
			CONDUIT, 3 IN., PUSHED WITH	Overrun	Overrun	21		SYSTEM		
2020 CABLE, 16 AWG 7 CONDUCTOR Material 21 May 17, SYSTEM \$1,881.60 22 Jun 2, SYSTEM \$1,881.60 22 Jun 2, SYSTEM \$1,881.60 22 Jun 2, SYSTEM \$1,881.60 22 Jun 12, SYSTEM \$1,881.60 22 Jun 14, SYSTEM \$1,881.60 22 Jun 15, SYSTEM \$1,881.60 22 Jun 16, SYSTEM \$1,88			TRACER WIRE		Overrun - T	otal			(\$621.00)	
21				Overrun - To	tal				(\$621.00)	
CONDUCTOR 2021 1 May 17, SYSTEM (\$1,881.00) 2021 2 Jun 2, SYSTEM \$1,881.60 2 Jun 2, SYSTEM (\$1,881.60) 2 Jun 3, SYSTEM (\$1,881.60) 2 Jun 16, SYSTEM \$1,881.60 2 Jun 16, SYSTEM \$1,881.60 2 Jun 17, SYSTEM \$1,881.60 2 Jun 18, SYSTEM \$1,881.60 2 Jun 19, SYSTEM \$1,881.60 3 SYSTE		2020 -	Total						(\$621.00)	
22 Jun 2, 2021 23 Jun 2, 2021 24 Jun 2, 2021 25 Jun 2, 2021 26 Jun 2, 2021 27 Jun 2, 2021 28 Jun 2, 2021 29 Jun 2, 2021 29 Jun 2, 2021 20 Jun 16, 2021 20 Jun		2060		Material		21		SYSTEM	\$1,881.60	Estimate Item Adjustment (0025) due to user hillt5 overridding Payment
Estimate Item Adjustment (0025) due to user hillfs overridding Payment Estimate Exception 130 on the current Payment Estimate Estimate Exception 130 on the current Payment Estimate Payment Estimate Payment Estimate Payment Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment Estimate Exception 129 on the current Payment Estimate Payment Estimate Exception 129 on the current Payment Estimate Payment Estimate Exception 129 on the current Payment Estimate Payment Estimate Exception 129 on the current Payment Estimate Payment Estimate Exception 88 on the current Payment Estimate Payment Estimate Exception 88 on the current Payment Estimate Payment Estimate Exception 89 on the current Payment Estimate Payment Estimate Payment						21		SYSTEM	(\$1,881.60)	
23 Jun 16, 2021 24 Jul 1, 2021 25 Jul 16, 2021 26 Jul 16, 2021 27 Jul 16, 2021 28 System (\$1,881.60) 29 Jul 16, 2021 29 Jul 16, 2021 20 Jul 16, 2021 25 Jul 16, 2021 26 Aug 2, 2021 27 Aug 16, 2021 28 System (\$1,881.60) 29 System (\$1,881.60) 20 Jul 16, 2021 26 Aug 2, 2021 27 Aug 16, 2021 28 System (\$1,881.60) 29 System (\$1,881.60) 20 Jul 16, 2021 29 System (\$1,881.60) 20 Jul 16, 2021 20 Jul 16, 2021 20 Jul 16, 2021 20 Jul 16, 2021 26 Aug 2, 2021 27 Aug 16, 2021 28 System (\$1,881.60) 29 System (\$1,881.60) 20 Jul 16, 2021 29 Jul 16, 2021 20						22		SYSTEM	\$1,881.60	Estimate Item Adjustment (0025) due to user hillt5 overridding Payment
2021 Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment Estimate Exception 129 on the current Payment Estimate.						22		SYSTEM	(\$1,881.60)	
24 Jul 1, 2021 24 Jul 1, 2021 25 Jul 16, 2021 26 Jul 18, 2021 27 Jul 18, 2021 28 SySTEM \$1.881.60 29 SySTEM \$1.881.60 20 Jul 16, 2021 29 Jul 16, 2021 20 Jul 16, 2021 27 Aug 16, 2021 28 Sep 2, SySTEM \$1.881.60 28 Sep 2, SYSTEM \$1.881.60 29 SySTEM \$1.881.60 20 SySTEM \$1.881.60						23		SYSTEM	\$1,881.60	Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment
Estimate Item Adjustment (0021) due to user herrm11 overridding Payment Estimate Exception 88 on the current Payment Estimate. 24 Jul 1, 2021 (\$1,881.60) 25 Jul 16, 2021 (\$1,881.60) 26 Aug 2, 2021 (\$1,881.60) 26 Aug 2, 2021 (\$1,881.60) 27 Aug 16, 2021 (\$1,881.60) 27 Aug 16, 2021 (\$1,881.60) 28 Sep 2, 2021 (\$1,881.60) 28 Sep 2, 2021 (\$1,881.60) Estimate Item Adjustment (0028) due to user kloepj1 overridding Payment Estimate Exception 83 on the current Payment Estimate. Estimate Exception 83 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 83 on the current Payment Estimate Estimate Exception 83 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 83 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user herrm11 overridding Payment Estimate Exception 79 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 79 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 94 on the current Payment Estimate.						23		SYSTEM	(\$1,881.60)	
25 Jul 16, 2021 \$1,881.60 Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Exception 83 on the current Payment Estimate. 25 Jul 16, 2021 \$1,881.60 (\$1,881.60) 26 Aug 2, 2021 \$1,881.60 27 Aug 16, 2021 \$1,881.60 27 Aug 16, 2021 \$1,881.60 28 Sep 2, 2021 \$1,881.60 29 SYSTEM \$1,881.60 29 SYSTEM \$1,881.60 20 SYSTEM \$1,881.60						24		SYSTEM	\$1,881.60	Estimate Item Adjustment (0021) due to user herrmt1 overridding Payment
Estimate Item Adjustment (0028) due to user kloepj1 overridding Payment Estimate Exception 83 on the current Payment Estimate. 25 Jul 16, 2021 26 Aug 2, 2021 27 Aug 16, 2021 28 Sep 2, 2021 28 Sep 2, 2021 Estimate Item Adjustment (0028) due to user kloepj1 overridding Payment Estimate Item Adjustment (0026) due to user hillts overridding Payment Estimate Exception 83 on the current Payment Estimate. Estimate Exception 83 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user hermt1 overridding Payment Estimate Exception 79 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 79 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user kloepj1 overridding Payment Estimate Item Adjustment (0035) due to user kloepj1 overridding Payment Estimate Item Adjustment (0035) due to user kloepj1 overridding Payment Estimate Item Adjustment (0035) due to user kloepj1 overridding Payment Estimate Item Adjustment (0036) due to user kloepj1 overridding Payment Estimate Item Adjustment (0036) due to user kloepj1 overridding Payment Estimate Exception 94 on the current Payment Estimate.						24		SYSTEM	(\$1,881.60)	
26 Aug 2, 2021 SYSTEM \$1,881.60 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user hillt5 overridding Payment Estimate Exception 83 on the current Payment Estimate. 26 Aug 2, 2021 SYSTEM (\$1,881.60) 27 Aug 16, 2021 SYSTEM \$1,881.60 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user herrmt1 overridding Payment Estimate Exception 79 on the current Payment Estimate. 27 Aug 16, 2021 (\$1,881.60) 28 Sep 2, 2021 SYSTEM \$1,881.60 This adjustment offsets the original system-generated Material Payment Estimate Exception 79 on the current Payment Estimate. 28 Sep 2, 2021 SYSTEM \$1,881.60 Estimate Item Adjustment (0035) due to user kloepj1 overridding Payment Estimate Exception 94 on the current Payment Estimate.						25		SYSTEM	\$1,881.60	Estimate Item Adjustment (0028) due to user kloepj1 overridding Payment
Estimate Item Adjustment (0026) due to user hillt5 overridding Payment Estimate Exception 83 on the current Payment Estimate. 26 Aug 2, 2021 27 Aug 16, 2021 28 Sep 2, 2021 SYSTEM \$1,881.60 SYSTEM \$1,881.60 SYSTEM (\$1,881.60) This adjustment offsets the original system-generated Material Payment Estimate Exception 79 on the current Payment Estimate. 28 Sep 2, 2021 SYSTEM \$1,881.60 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user kloepj1 overridding Payment Estimate Item Adjustment (0035) due to user kloepj1 overridding Payment Estimate Exception 94 on the current Payment Estimate. 28 Sep 2, 2021 SYSTEM (\$1,881.60)						25		SYSTEM	(\$1,881.60)	
2021 \$\frac{2021}{2021}\$ \$\frac{1}{81,881.60}\$ This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user herrmt1 overridding Payment Estimate Exception 79 on the current Payment Estimate. 27 Aug 16, 2021 \$\frac{2021}{2021}\$ \$\frac{1}{81,881.60}\$ This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user kloepj1 overridding Payment Estimate Exception 94 on the current Payment Estimate. 28 Sep 2, 2021 \$\frac{2}{2021}\$ \$\frac{2}{81,881.60}\$ \$\frac{2}{81,88						26		SYSTEM	\$1,881.60	Estimate Item Adjustment (0026) due to user hillt5 overridding Payment
2021 Estimate Item Adjustment (0023) due to user herrmt1 overridding Payment Estimate Exception 79 on the current Payment Estimate. 27 Aug 16, 2021 (\$1,881.60) 28 Sep 2, 2021 \$1,881.60 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user kloepj1 overridding Payment Estimate Exception 94 on the current Payment Estimate. 28 Sep 2, 2021 \$1,881.60 (\$1,881.60)						26		SYSTEM	(\$1,881.60)	
2021 28 Sep 2, 2021 \$1,881.60 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user kloepj1 overridding Payment Estimate Exception 94 on the current Payment Estimate. 28 Sep 2, 2021 \$1,881.60 (\$1,881.60)						27		SYSTEM	\$1,881.60	Estimate Item Adjustment (0023) due to user herrmt1 overridding Payment
2021 Estimate Item Adjustment (0035) due to user kloepj1 overridding Payment Estimate Exception 94 on the current Payment Estimate. 28 Sep 2, 2021 (\$1,881.60)						27		SYSTEM	(\$1,881.60)	
2021						28		SYSTEM	\$1,881.60	Estimate Item Adjustment (0035) due to user kloepj1 overridding Payment
						28		SYSTEM	(\$1,881.60)	
					- Total				\$0.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	2060	CABLE, 16 AWG 7 CONDUCTOR	Material - To	tal				\$0.00	
	2060 -	· Total						\$0.00	
	2080	PULL BOX, PREFORMED CLASS 2	Overrun	Overrun	21	May 17, 2021	SYSTEM	(\$1,221.00)	
		01/100 2			28	Sep 2, 2021	SYSTEM	(\$1,221.00)	
				Overrun - T	otal			(\$2,442.00)	
			Overrun - To	tal				(\$2,442.00)	
	2080 -	· Total						(\$2,442.00)	
	2100	BASE, CONCRETE	Material		18	Apr 2, 2021	SYSTEM	\$2,320.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 59 on the current Payment Estimate.
					18	Apr 2, 2021	SYSTEM	(\$2,320.00)	
					19	Apr 16, 2021	SYSTEM	\$7,644.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 67 on the current Payment Estimate.
					19	Apr 16, 2021	SYSTEM	(\$7,644.40)	
					20	May 3, 2021	SYSTEM	\$7,644.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user hillt5 overridding Payment Estimate Exception 92 on the current Payment Estimate.
					20	May 3, 2021	SYSTEM	(\$7,644.40)	
					21	May 17, 2021	SYSTEM	\$7,644.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user hillt5 overridding Payment Estimate Exception 119 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$7,644.40)	
					22	Jun 2, 2021	SYSTEM	\$7,644.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user hillt5 overridding Payment Estimate Exception 131 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$7,644.40)	
					23	Jun 16, 2021	SYSTEM	\$7,644.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user kloepj1 overridding Payment Estimate Exception 130 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$7,644.40)	
					24	Jul 1, 2021	SYSTEM	\$7,644.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user herrmt1 overridding Payment Estimate Exception 89 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$7,644.40)	
					25	Jul 16, 2021	SYSTEM	\$7,644.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user kloepj1 overridding Payment Estimate Exception 84 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$7,644.40)	
					26	Aug 2, 2021	SYSTEM	\$7,644.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user hillt5 overridding Payment Estimate Exception 84 on the current Payment Estimate.
					26	Aug 2, 2021	SYSTEM	(\$7,644.40)	
					28	Sep 2, 2021	SYSTEM	\$11,948.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user kloepj1 overridding Payment Estimate Exception 95 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$11,948.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	2100 -	- Total						\$0.00	
	2210	CONCRETE FOOTINGS, BOLT DOWN	Material		3	Aug 17, 2020	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	2210	CONCRETE FOOTINGS, BOLT	Material		3	Aug 17, 2020	SYSTEM	(\$15,000.00)	
		DOWN			4	Sep 2, 2020	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					4	Sep 2, 2020	SYSTEM	(\$15,000.00)	
					5	Sep 16, 2020	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user kloepj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					5	Sep 16, 2020	SYSTEM	(\$15,000.00)	
					6	Oct 1, 2020	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment Estimate Exception 35 on the current Payment Estimate.
					6	Oct 1, 2020	SYSTEM	(\$15,000.00)	
					7	Oct 16, 2020	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
					7	Oct 16, 2020	SYSTEM	(\$15,000.00)	
					8	Nov 2, 2020	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user hillt5 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					8	Nov 2, 2020	SYSTEM	(\$15,000.00)	
					9	Nov 16, 2020	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user hillt5 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					9	Nov 16, 2020	SYSTEM	(\$15,000.00)	
					10	Dec 2, 2020	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					10	Dec 2, 2020	SYSTEM	(\$15,000.00)	
					11	Dec 16, 2020	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user schlag1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					11	Dec 16, 2020	SYSTEM	(\$15,000.00)	
					12	Jan 4, 2021	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
					12	Jan 4, 2021	SYSTEM	(\$15,000.00)	
					13	Jan 19, 2021	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schlag1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					13	Jan 19, 2021	SYSTEM	(\$15,000.00)	
					14	Feb 2, 2021	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hillt5 overridding Payment Estimate Exception 57 on the current Payment Estimate.
					14	Feb 2, 2021	SYSTEM	(\$15,000.00)	
					15	Feb 16, 2021	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schlag1 overridding Payment Estimate Exception 56 on the current Payment Estimate.
					15	Feb 16, 2021	SYSTEM	(\$15,000.00)	
					16	Mar 2, 2021	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 52 on the current Payment Estimate.
					16	Mar 2, 2021	SYSTEM	(\$15,000.00)	
					17	Mar 16,	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Material Payment



L	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks								
2 2	2210	CONCRETE FOOTINGS, BOLT DOWN	Material			2021			Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment Estimate Exception 45 on the current Payment Estimate.								
					17	Mar 16, 2021	SYSTEM	(\$15,000.00)									
					18	Apr 2, 2021	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 60 on the current Payment Estimate.								
					18	Apr 2, 2021	SYSTEM	(\$15,000.00)									
					19	Apr 16, 2021	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 68 on the current Payment Estimate.								
					19	Apr 16, 2021	SYSTEM	(\$15,000.00)									
					20	May 3, 2021	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user hillts overridding Payment Estimate Exception 93 on the current Payment Estimate.								
					20	May 3, 2021	SYSTEM	(\$15,000.00)									
					21	May 17, 2021	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user hillt5 overridding Payment Estimate Exception 120 on the current Payment Estimate.								
					21	May 17, 2021	SYSTEM	(\$15,000.00)									
					22	Jun 2, 2021	SYSTEM	\$50,784.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user hillt5 overridding Payment Estimate Exception 132 on the current Payment Estimate.								
					22	Jun 2, 2021	SYSTEM	(\$50,784.00)									
					23	Jun 16, 2021	SYSTEM	\$50,784.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user kloepj1 overridding Payment Estimate Exception 131 on the current Payment Estimate.								
													23	Jun 16, 2021	SYSTEM	(\$50,784.00)	
					24	Jul 1, 2021	SYSTEM	\$67,584.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user herrmt1 overridding Payment Estimate Exception 90 on the current Payment Estimate.								
					24	Jul 1, 2021	SYSTEM	(\$67,584.00)									
					25	Jul 16, 2021	SYSTEM	\$67,584.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user kloepj1 overridding Payment Estimate Exception 85 on the current Payment Estimate.								
					25	Jul 16, 2021	SYSTEM	(\$67,584.00)									
					26	Aug 2, 2021	SYSTEM	\$67,584.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user hillt5 overridding Payment Estimate Exception 85 on the current Payment Estimate.								
					26	Aug 2, 2021	SYSTEM	(\$67,584.00)									
					27	Aug 16, 2021	SYSTEM	\$67,584.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user herrmt1 overridding Payment Estimate Exception 80 on the current Payment Estimate.								
					27	Aug 16, 2021	SYSTEM	(\$67,584.00)									
					28	Sep 2, 2021	SYSTEM	\$67,584.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user kloepj1 overridding Payment Estimate Exception 96 on the current Payment Estimate.								
					28	Sep 2, 2021	SYSTEM	(\$67,584.00)									
				- Total				\$0.00									
2	2210 -	Total	Material - To	tal				\$0.00 \$0.00									
	2220	STRUCTURAL STEEL POSTS	Construction Stockpile		5	Sep 16, 2020	SYSTEM	\$7,567.11	Payment Estimate Item Adjustment generated Stockpile Transaction								
			STMI	- Total				\$7,567.11									
			Construction	Stockpile S	TMI - Total			\$7,567.11									



oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
2222	2220 -	Total						\$7,567.11	
	2230	PIPE POSTS	Construction Stockpile STMI		5	Sep 16, 2020	SYSTEM	\$10,734.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$10,734.00	
			Construction	Stockpile S	MI - Total			\$10,734.00	
	2230 -							\$10,734.00	
	2240	2 IN. PSST POST - 12 GA.	Construction Stockpile STMI		23	Jun 16, 2021	SYSTEM	\$259.20	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$259.20	
			Construction	Stockpile S	MI - Total			\$259.20	
	2240 -		O-matmustics		00	lum 40	OVOTEM	\$259.20	Decreased February Million and Adjusting and
	2250	POST ANCHOR FOR 2 IN. PSST - 12 GA.			23	Jun 16, 2021	SYSTEM	\$100.17	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$100.17	
	0050		Construction	Stockpile S	MI - Total			\$100.17	
	2250 -							\$100.17	
	2260	SH-FLAT SHEET	Construction Stockpile STMI		23	Jun 16, 2021	SYSTEM	\$4,724.20	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$4,724.20	
			Construction	Stockpile S	MI - Total			\$4,724.20	
	2260 -							\$4,724.20	
	2270	ST-STRUCTURAL	Construction Stockpile		25	Jul 16, 2021	SYSTEM	(\$2,190.22)	Payment Estimate Item Adjustment generated Stockpile Transaction
					26	Aug 2, 2021	SYSTEM	(\$19,686.22)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$21,876.44)	
			Construction	Stockpile - 1	otal			(\$21,876.44)	
			Construction Stockpile STMI		23	Jun 16, 2021	SYSTEM	\$30,495.60	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$30,495.60	
			Construction	Stockpile S	MI - Total			\$30,495.60	
	2270 - 2280	SHF-FLAT SHEET	Construction Stockpile		23	Jun 16,	SYSTEM	\$8,619.16 \$1,013.70	Payment Estimate Item Adjustment generated Stockpile Transaction
		FLUORESCENT	STMI	- Total		2021			
			Construction	Stockpile S1				\$1.013.70	
	2280 -	Takal			MI - Total			\$1,013.70 \$1.013.70	
		Total			MI - Total			\$1,013.70	
	2290	STF-STRUCTURAL FLUORESCENT			MI - Total	Jul 16, 2021	SYSTEM		Payment Estimate Item Adjustment generated Stockpile Transaction
	2290	STF-STRUCTURAL				Jul 16,	SYSTEM SYSTEM	\$1,013.70 \$1,013.70	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
	2290	STF-STRUCTURAL		- Total	25	Jul 16, 2021 Aug 2,		\$1,013.70 \$1,013.70 (\$1,341.00)	, ,
	2290	STF-STRUCTURAL	Stockpile		25 26	Jul 16, 2021 Aug 2,		\$1,013.70 \$1,013.70 (\$1,341.00) (\$2,279.70)	, ,
	2290	STF-STRUCTURAL	Stockpile Construction Construction Stockpile	- Total	25 26	Jul 16, 2021 Aug 2,		\$1,013.70 \$1,013.70 (\$1,341.00) (\$2,279.70) (\$3,620.70)	, ,
	2290	STF-STRUCTURAL	Stockpile Construction Construction	- Total	25 26 Total	Jul 16, 2021 Aug 2, 2021 Jun 16,	SYSTEM	\$1,013.70 \$1,013.70 (\$1,341.00) (\$2,279.70) (\$3,620.70) (\$3,620.70)	Payment Estimate Item Adjustment generated Stockpile Transaction
	2290	STF-STRUCTURAL	Construction Construction Stockpile STMI	- Total Stockpile - 1	25 26 	Jul 16, 2021 Aug 2, 2021 Jun 16, 2021	SYSTEM	\$1,013.70 \$1,013.70 (\$1,341.00) (\$2,279.70) (\$3,620.70) (\$3,620.70) \$5,811.00	Payment Estimate Item Adjustment generated Stockpile Transaction
	2290 -	STF-STRUCTURAL FLUORESCENT	Construction Construction Stockpile STMI	- Total I Stockpile - T - Total	25 26 	Jul 16, 2021 Aug 2, 2021 Jun 16, 2021	SYSTEM	\$1,013.70 \$1,013.70 (\$1,341.00) (\$2,279.70) (\$3,620.70) (\$3,620.70) \$5,811.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		STF-STRUCTURAL FLUORESCENT Total TUBULAR SUPPORT, TYPE	Construction Construction Stockpile STMI Construction Construction	- Total I Stockpile - T - Total	25 26 	Jul 16, 2021 Aug 2, 2021 Jun 16, 2021	SYSTEM	\$1,013.70 \$1,013.70 (\$1,341.00) (\$2,279.70) (\$3,620.70) (\$3,620.70) \$5,811.00 \$5,811.00	Payment Estimate Item Adjustment generated Stockpile Transaction
	2290 -	STF-STRUCTURAL FLUORESCENT Total TUBULAR	Construction Construction Stockpile STMI Construction Construction Stockpile	- Total I Stockpile - T - Total	25 26 Total 23	Jul 16, 2021 Aug 2, 2021 Jun 16, 2021	SYSTEM	\$1,013.70 \$1,013.70 (\$1,341.00) (\$2,279.70) (\$3,620.70) (\$3,620.70) \$5,811.00 \$5,811.00 \$2,190.30	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
	2290 -	STF-STRUCTURAL FLUORESCENT Total TUBULAR SUPPORT, TYPE	Construction Construction Stockpile STMI Construction Construction Stockpile	- Total I Stockpile - T - Total	25 26 Total 23	Jul 16, 2021 Aug 2, 2021 Jun 16, 2021 Nov 2, 2020 Aug 16,	SYSTEM	\$1,013.70 \$1,013.70 (\$1,341.00) (\$2,279.70) (\$3,620.70) (\$3,620.70) \$5,811.00 \$5,811.00 \$2,190.30 \$1,400.00	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
	2290 -	STF-STRUCTURAL FLUORESCENT Total TUBULAR SUPPORT, TYPE	Construction Stockpile STMI Construction Construction Stockpile STMI	- Total Stockpile - T - Total Stockpile ST	25 26 Total 23 TMI - Total 8	Jul 16, 2021 Aug 2, 2021 Jun 16, 2021 Nov 2, 2020 Aug 16, 2021	SYSTEM	\$1,013.70 \$1,013.70 (\$1,341.00) (\$2,279.70) (\$3,620.70) (\$3,620.70) \$5,811.00 \$5,811.00 \$2,190.30 \$1,400.00	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
	2290 -	Total TUBULAR SUPPORT, TYPE C-2315-20	Construction Stockpile STMI Construction Construction Stockpile STMI	- Total - Total - Total Stockpile ST	25 26 Total 23 TMI - Total 8	Jul 16, 2021 Aug 2, 2021 Jun 16, 2021 Nov 2, 2020 Aug 16, 2021	SYSTEM	\$1,013.70 \$1,013.70 (\$1,341.00) (\$2,279.70) (\$3,620.70) (\$3,620.70) \$5,811.00 \$5,811.00 \$2,190.30 \$1,400.00 \$16,900.00	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction



ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks					
2 :	2310	C-2018-28	STMI	- Total				\$1,400.00						
			Construction	Stockpile S	ГМI - Total			\$1,400.00						
	2310 -	Total						\$1,400.00						
1	2320	MISC. HIGHWAY SIGNING	Construction Stockpile STMI		8	Nov 2, 2020	SYSTEM	\$2,300.00	Payment Estimate Item Adjustment generated Stockpile Transaction					
			011111	- Total				\$2,300.00						
			Construction	Stockpile S	ΓMI - Total			\$2,300.00						
	2320 -							\$2,300.00						
1	2330	MISC. HIGHWAY SIGNING	Construction Stockpile		25	Jul 16, 2021	SYSTEM	(\$50,900.00)	Payment Estimate Item Adjustment generated Stockpile Transaction					
				- Total				(\$50,900.00)						
				1 Stockpile - 1				(\$50,900.00)						
			Construction Stockpile STMI		8	Nov 2, 2020	SYSTEM	\$2,600.00	Payment Estimate Item Adjustment generated Stockpile Transaction					
			OTIVII		23	Jun 16, 2021	SYSTEM	\$48,300.00	Payment Estimate Item Adjustment generated Stockpile Transaction					
				- Total				\$50,900.00						
			Construction	Stockpile S1	ΓΜΙ - Total			\$50,900.00						
			Material		25	Jul 16, 2021	SYSTEM	\$66,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user kloepj1 overridding Payment Estimate Exception 87 on the current Payment Estimate.					
					25	Jul 16, 2021	SYSTEM	(\$66,000.00)						
										26	Aug 2, 2021	SYSTEM	\$66,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user hillt5 overridding Payment Estimate Exception 87 on the current Payment Estimate.
					26	Aug 2, 2021	SYSTEM	(\$66,000.00)						
					27	Aug 16, 2021	SYSTEM	\$66,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user herrmt1 overridding Payment Estimate Exception 81 on the current Payment Estimate.					
					27	Aug 16, 2021	SYSTEM	(\$66,000.00)						
				28	28	Sep 2, 2021	SYSTEM	\$66,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user kloepj1 overridding Payment Estimate Exception 97 on the current Payment Estimate.					
					28	Sep 2, 2021	SYSTEM	(\$66,000.00)						
				- Total		2021		\$0.00						
			Material - Tot	tal				\$0.00						
	2330 -	Total						\$0.00						
1	2340	MISC. HIGHWAY SIGNING	Stockpile		8	Nov 2, 2020	SYSTEM	\$2,600.00	Payment Estimate Item Adjustment generated Stockpile Transaction					
			STMI	- Total				\$2,600.00						
			Construction	Stockpile S	ГМI - Total			\$2,600.00						
	2340 -	Total						\$2,600.00						
1	2650	CLASS B CONCRETE (SUBSTRUCTURE)	Material		16	Mar 2, 2021	SYSTEM	\$5,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 36 on the current Payment Estimate.					
					16	Mar 2, 2021	SYSTEM	(\$5,050.00)						
					17	Mar 16, 2021	SYSTEM	\$5,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.					
					17	Mar 16, 2021	SYSTEM	(\$5,050.00)						
					18	Apr 2, 2021	SYSTEM	\$5,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 30 on the current Payment Estimate.					
					18	Apr 2, 2021	SYSTEM	(\$5,050.00)						



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks													
J6I2222	2650	CLASS B CONCRETE	Material			2021			Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.													
		(SUBSTRUCTURE)			19	Apr 16, 2021	SYSTEM	(\$5,050.00)														
					20	May 3, 2021	SYSTEM	\$5,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user hillt5 overridding Payment Estimate Exception 35 on the current Payment Estimate.													
					20	May 3, 2021	SYSTEM	(\$5,050.00)														
					21	May 17, 2021	SYSTEM	\$5,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user hillt5 overridding Payment Estimate Exception 55 on the current Payment Estimate.													
					21	May 17, 2021	SYSTEM	(\$5,050.00)														
					22	Jun 2, 2021	SYSTEM	\$5,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user hillt5 overridding Payment Estimate Exception 67 on the current Payment Estimate.													
					22	Jun 2, 2021	SYSTEM	(\$5,050.00)														
					23	Jun 16, 2021	SYSTEM	\$5,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user kloepj1 overridding Payment Estimate Exception 69 on the current Payment Estimate.													
					23	Jun 16, 2021	SYSTEM	(\$5,050.00)														
						26	Aug 2, 2021	SYSTEM	\$5,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user hillt5 overridding Payment Estimate Exception 34 on the current Payment Estimate.												
					26	Aug 2, 2021	SYSTEM	(\$5,050.00)														
				- Total				\$0.00														
	2650 -	T-4-1	Material - To	tal				\$0.00														
	2660	CLASS B-1 CONCRETE	Material		27	Aug 16, 2021	SYSTEM	\$0.00 \$8,855.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user herrmt1 overridding Payment Estimate Exception 27 on the current Payment Estimate.													
					27	Aug 16, 2021	SYSTEM	(\$8,855.00)														
				- Total				\$0.00														
			Material - Tot	tal				\$0.00														
	2660 -				4.4	E 1 0	0)/07514	\$0.00														
	2670	SLAB ON STEEL	Material		14	Feb 2, 2021	SYSTEM	\$17,390.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user hillt5 overridding Payment Estimate Exception 32 on the current Payment Estimate.													
					14	Feb 2, 2021	SYSTEM	(\$17,390.00)														
													15					15	Feb 16, 2021	SYSTEM	\$17,390.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schlag1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
														15	Feb 16, 2021	SYSTEM	(\$17,390.00)					
					16	Mar 2, 2021	SYSTEM	\$34,780.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 39 on the current Payment Estimate.													
							1	16	Mar 2, 2021	SYSTEM	(\$34,780.00)											
					17	Mar 16, 2021	SYSTEM	\$34,780.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.													
					17	Mar 16, 2021	SYSTEM	(\$34,780.00)														
				18	18	Apr 2, 2021	SYSTEM	\$99,640.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.													
					18	Apr 2, 2021	SYSTEM	(\$99,640.00)														



ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
22	2670	SLAB ON STEEL	Material			2021			Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					19	Apr 16, 2021	SYSTEM	(\$99,640.00)	
					20	May 3, 2021	SYSTEM	\$99,640.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user hillt5 overridding Payment Estimate Exception 43 on the current Payment Estimate.
					20	May 3, 2021	SYSTEM	(\$99,640.00)	
					21	May 17, 2021	SYSTEM	\$100,580.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user hillt5 overridding Payment Estimate Exception 62 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$100,580.00)	
					22	Jun 2, 2021	SYSTEM	\$100,580.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user hillt5 overridding Payment Estimate Exception 74 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$100,580.00)	
					23	Jun 16, 2021	SYSTEM	\$100,580.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0048) due to user kloepj1 overridding Payment Estimate Exception 76 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$100,580.00)	
					24	Jul 1, 2021	SYSTEM	\$100,580.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user herrmt1 overridding Payment Estimate Exception 41 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$100,580.00)	
					25	Jul 16, 2021	SYSTEM	\$100,580.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0049) due to user kloepj1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$100,580.00)	
					26	Aug 2, 2021	SYSTEM	\$100,580.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user hillt5 overridding Payment Estimate Exception 38 on the current Payment Estimate.
					26	Aug 2, 2021	SYSTEM	(\$100,580.00)	
					27	Aug 16, 2021	SYSTEM	\$100,580.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user herrmt1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$100,580.00)	
					28	Sep 2, 2021	SYSTEM	\$100,580.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user kloepj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$100,580.00)	
				- Total				\$0.00	
	2670 -	Total	Material - Tot	tal				\$0.00 \$0.00	
	2690	CORRAL CURB	Material		19	Apr 16, 2021	SYSTEM	\$16,614.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user kloepj1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
					19	Apr 16, 2021	SYSTEM	(\$16,614.00)	
					20	May 3, 2021	SYSTEM	\$16,614.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user hillt5 overridding Payment Estimate Exception 48 on the current Payment Estimate.
					20	May 3, 2021	SYSTEM	(\$16,614.00)	
					20		SYSTEM	(\$16,614.00) \$16,614.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user hillt5 overridding Payment Estimate Exception 68 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	2690	CORRAL CURB	Material		22	Jun 2, 2021	SYSTEM	\$16,614.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user hillt5 overridding Payment Estimate Exception 80 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$16,614.00)	
					23	Jun 16, 2021	SYSTEM	\$16,614.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0049) due to user kloepj1 overridding Payment Estimate Exception 81 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$16,614.00)	
					24	Jul 1, 2021	SYSTEM	\$16,614.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user herrmt1 overridding Payment Estimate Exception 44 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$16,614.00)	
					25	Jul 16, 2021	SYSTEM	\$16,614.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user kloepj1 overridding Payment Estimate Exception 41 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$16,614.00)	
					26	Aug 2, 2021	SYSTEM	\$16,614.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user hillt5 overridding Payment Estimate Exception 47 on the current Payment Estimate.
					26	Aug 2, 2021	SYSTEM	(\$16,614.00)	
					27	Aug 16, 2021	SYSTEM	\$16,614.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user herrmt1 overridding Payment Estimate Exception 41 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$16,614.00)	
					28	Sep 2, 2021	SYSTEM	\$16,614.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0059) due to user kloepj1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$16,614.00)	
				- Total				\$0.00	
	0000		Material - To	tal				\$0.00	
	2690 - 2700	SUPERSTRUCTURE REPAIR (UNFORMED)	Material		17	Mar 16, 2021	SYSTEM	\$0.00 \$13,114.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
		(ON ONNED)			17	Mar 16,	SYSTEM	(\$13,114.00)	Estimate Exception of the earlors of ayrion Estimate.
					18	Apr 2, 2021	SYSTEM	\$33,022.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
					18	Apr 2, 2021	SYSTEM	(\$33,022.00)	
					19	Apr 16, 2021	SYSTEM	\$33,022.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user kloepj1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
					19	Apr 16, 2021	SYSTEM	(\$33,022.00)	
					20	May 3, 2021	SYSTEM	\$74,892.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user hillt5 overridding Payment Estimate Exception 50 on the current Payment Estimate.
					20	May 3, 2021	SYSTEM	(\$74,892.00)	
					21	May 17, 2021	SYSTEM	\$133,826.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user hillt5 overridding Payment Estimate Exception 70 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$133,826.00)	
					22	Jun 2, 2021	SYSTEM	\$169,060.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user hillt5 overridding Payment Estimate Exception 82 on the current Payment Estimate.
					22	Jun 2,	SYSTEM	(\$169,060.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	2700	SUPERSTRUCTURE	Material			2021			
		REPAIR (UNFORMED)			23	Jun 16, 2021	SYSTEM	\$195,604.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user kloepj1 overridding Payment Estimate Exception 83 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$195,604.00)	
					24	Jul 1, 2021	SYSTEM	\$200,502.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user herrmt1 overridding Payment Estimate Exception 46 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$200,502.00)	
					25	Jul 16, 2021	SYSTEM	\$200,502.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0051) due to user kloepj1 overridding Payment Estimate Exception 43 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$200,502.00)	
					26	Aug 2, 2021	SYSTEM	\$200,502.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user hillt5 overridding Payment Estimate Exception 49 on the current Payment Estimate.
					26	Aug 2, 2021	SYSTEM	(\$200,502.00)	
					27	Aug 16, 2021	SYSTEM	\$200,502.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user herrmt1 overridding Payment Estimate Exception 43 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$200,502.00)	
					28	Sep 2, 2021	SYSTEM	\$208,560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user kloepj1 overridding Payment Estimate Exception 41 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$208,560.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	2700 -	- Total						\$0.00	
		14100	Material		00	May 2	CVCTEM	¢47.4E0.00	This adjustment offsets the original system-generated Material Payment
	2720	MISC.	Material		20	May 3, 2021	SYSTEM	\$17,150.00	Estimate Item Adjustment (0330) due to user hills overridding Payment Estimate Exception 58 on the current Payment Estimate.
	2720	MISC.	Material		20		SYSTEM	(\$17,150.00)	Estimate Item Adjustment (0030) due to user hillt5 overridding Payment
	2720	MISC.	Material			2021 May 3,			Estimate Item Adjustment (0030) due to user hillt5 overridding Payment
	2720	MISC.	Material		20	2021 May 3, 2021 May 17,	SYSTEM	(\$17,150.00)	Estimate Item Adjustment (0030) due to user hillts overridding Payment Estimate Exception 58 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user hillts overridding Payment
	2720	MISC.	Material		20	2021 May 3, 2021 May 17, 2021	SYSTEM SYSTEM	(\$17,150.00) \$23,800.00	Estimate Item Adjustment (0030) due to user hillts overridding Payment Estimate Exception 58 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user hillts overridding Payment
	2720	MISC.	Material		20 21 21	2021 May 3, 2021 May 17, 2021 May 17, 2021 Jun 2,	SYSTEM SYSTEM	(\$17,150.00) \$23,800.00 (\$23,800.00)	Estimate Item Adjustment (0030) due to user hillt5 overridding Payment Estimate Exception 58 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user hillt5 overridding Payment Estimate Exception 78 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user hillt5 overridding Payment
	2720	MISC.	Material		20 21 21 22	2021 May 3, 2021 May 17, 2021 May 17, 2021 Jun 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	(\$17,150.00) \$23,800.00 (\$23,800.00) \$23,800.00	Estimate Item Adjustment (0030) due to user hillt5 overridding Payment Estimate Exception 58 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user hillt5 overridding Payment Estimate Exception 78 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user hillt5 overridding Payment
	2720	MISC.	Material		20 21 21 22 22	2021 May 3, 2021 May 17, 2021 May 17, 2021 Jun 2, 2021 Jun 2, 2021 Jun 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$17,150.00) \$23,800.00 (\$23,800.00) \$23,800.00 (\$23,800.00)	Estimate Item Adjustment (0030) due to user hillt5 overridding Payment Estimate Exception 58 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user hillt5 overridding Payment Estimate Exception 78 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user hillt5 overridding Payment Estimate Exception 90 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0051) due to user kloepj1 overridding Payment
	2720	MISC.	Material		20 21 21 22 22 22 23	2021 May 3, 2021 May 17, 2021 May 17, 2021 Jun 2, 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 201	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$17,150.00) \$23,800.00 (\$23,800.00) \$23,800.00 (\$23,800.00) \$25,550.00	Estimate Item Adjustment (0030) due to user hillt5 overridding Payment Estimate Exception 58 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user hillt5 overridding Payment Estimate Exception 78 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user hillt5 overridding Payment Estimate Exception 90 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0051) due to user kloepj1 overridding Payment
	2720	MISC.	Material		20 21 21 22 22 23 23	2021 May 3, 2021 May 17, 2021 May 17, 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jun 16, 2021 Jun 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$17,150.00) \$23,800.00 (\$23,800.00) \$23,800.00 (\$23,800.00) \$25,550.00	Estimate Item Adjustment (0030) due to user hillt5 overridding Payment Estimate Exception 58 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user hillt5 overridding Payment Estimate Exception 78 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user hillt5 overridding Payment Estimate Exception 90 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0051) due to user kloepj1 overridding Payment Estimate Exception 91 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user herrmt1 overridding Payment Estimate Item Adjustment (0041) due to user herrmt1 overridding Payment
	2720	MISC.	Material		20 21 21 22 22 23 23 24	2021 May 3, 2021 May 17, 2021 May 17, 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$17,150.00) \$23,800.00 (\$23,800.00) \$23,800.00 (\$23,800.00) \$25,550.00 (\$25,550.00)	Estimate Item Adjustment (0030) due to user hillt5 overridding Payment Estimate Exception 58 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user hillt5 overridding Payment Estimate Exception 78 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user hillt5 overridding Payment Estimate Exception 90 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0051) due to user kloepj1 overridding Payment Estimate Exception 91 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user herrmt1 overridding Payment Estimate Item Adjustment (0041) due to user herrmt1 overridding Payment
	2720	MISC.	Material		20 21 21 22 22 23 23 24 24	2021 May 3, 2021 May 17, 2021 May 17, 2021 Jun 2, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021	SYSTEM	(\$17,150.00) \$23,800.00 (\$23,800.00) \$23,800.00 (\$23,800.00) \$25,550.00 (\$25,550.00) \$25,550.00	Estimate Item Adjustment (0030) due to user hillt5 overridding Payment Estimate Exception 58 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user hillt5 overridding Payment Estimate Exception 78 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user hillt5 overridding Payment Estimate Exception 90 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0051) due to user kloepj1 overridding Payment Estimate Exception 91 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user herrmt1 overridding Payment Estimate Exception 54 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 54 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	2720	MISC.	Material		26	Aug 2, 2021	SYSTEM	(\$25,900.00)	
					27	Aug 16, 2021	SYSTEM	\$25,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user herrmt1 overridding Payment Estimate Exception 51 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$25,900.00)	
					28	Sep 2, 2021	SYSTEM	\$25,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0061) due to user kloepj1 overridding Payment Estimate Exception 49 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$25,900.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	2720 -	Total						\$0.00	
	2730	REINFORCING STEEL (EPOXY COATED)	Material		18	Apr 2, 2021	SYSTEM	\$2,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
					18	Apr 2, 2021	SYSTEM	(\$2,550.00)	
					19	Apr 16, 2021	SYSTEM	\$2,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user kloepj1 overridding Payment Estimate Exception 44 on the current Payment Estimate.
					19	Apr 16, 2021	SYSTEM	(\$2,550.00)	
					20	May 3, 2021	SYSTEM	\$2,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user hillt5 overridding Payment Estimate Exception 62 on the current Payment Estimate.
					20	May 3, 2021	SYSTEM	(\$2,550.00)	
					21	May 17, 2021	SYSTEM	\$2,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user hillt5 overridding Payment Estimate Exception 82 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$2,550.00)	
					22	Jun 2, 2021	SYSTEM	\$2,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user hillt5 overridding Payment Estimate Exception 96 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$2,550.00)	
					23	Jun 16, 2021	SYSTEM	\$2,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0052) due to user kloepj1 overridding Payment Estimate Exception 96 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$2,550.00)	
					24	Jul 1, 2021	SYSTEM	\$2,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user herrmt1 overridding Payment Estimate Exception 58 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$2,550.00)	
					25	Jul 16, 2021	SYSTEM	\$2,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0053) due to user kloepj1 overridding Payment Estimate Exception 53 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$2,550.00)	
					26	Aug 2, 2021	SYSTEM	\$2,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user hillt5 overridding Payment Estimate Exception 59 on the current Payment Estimate.
					26	Aug 2, 2021	SYSTEM	(\$2,550.00)	
					27	Aug 16, 2021	SYSTEM	\$2,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user herrmt1 overridding Payment Estimate Exception 53 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$2,550.00)	
					28	Sep 2, 2021	SYSTEM	\$2,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0062) due to user kloepj1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks													
J6I2222	2730	REINFORCING STEEL (EPOXY COATED)	Material		28	Sep 2, 2021	SYSTEM	(\$2,550.00)	Estimate Exception 54 on the current Payment Estimate.													
				- Total		2021		\$0.00														
			Material - Tot					\$0.00														
	2730 -	Total						\$0.00														
	2790	STRIP SEAL EXPANSION JOINT SYSTEM	Construction Stockpile		26	Aug 2, 2021	SYSTEM	(\$9,471.00)	Payment Estimate Item Adjustment generated Stockpile Transaction													
		OTOTEM		- Total				(\$9,471.00)														
			Construction	Stockpile - 1	Total			(\$9,471.00)														
			Construction Stockpile STMI		14	Feb 2, 2021	SYSTEM	\$9,471.00	Payment Estimate Item Adjustment generated Stockpile Transaction													
			0 1 11	- Total				\$9,471.00														
	2790 -	Total	Construction	Stockpile S	IVII - I otal			\$9,471.00 \$0.00														
			Motorial		10	An= 2	CVCTEN		This adjustment offsets the original system assessed Material December													
	2810	REPAIR (UNFORMED)	Material		18	Apr 2, 2021	SYSTEM	\$33,654.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment Estimate Exception 39 on the current Payment Estimate.													
					18	Apr 2, 2021	SYSTEM	(\$33,654.00)														
																		19	Apr 16, 2021	SYSTEM	\$73,628.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user kloepj1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
								19	Apr 16, 2021	SYSTEM	(\$73,628.00)											
					20	May 3, 2021	SYSTEM	\$131,140.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user hillt5 overridding Payment Estimate Exception 54 on the current Payment Estimate.													
					20	May 3, 2021	SYSTEM	(\$131,140.00)														
					21	May 17, 2021	SYSTEM	\$165,742.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0048) due to user hillt5 overridding Payment Estimate Exception 74 on the current Payment Estimate.													
					21	May 17, 2021	SYSTEM	(\$165,742.00)														
					22	Jun 2, 2021	SYSTEM	\$234,314.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user hillt5 overridding Payment Estimate Exception 86 on the current Payment Estimate.													
			2 2 2 2 2 2						22	Jun 2, 2021	SYSTEM	(\$234,314.00)										
																23	Jun 16, 2021	SYSTEM	\$234,314.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0053) due to user kloepj1 overridding Payment Estimate Exception 87 on the current Payment Estimate.		
										23	Jun 16, 2021	SYSTEM	(\$234,314.00)									
				24 Jul 1, 2021 24 Jul 1, 2021 25 Jul 16, 2021 25 Jul 16, 2021 25 Jul 16, 2021	24	2	2											24		SYSTEM	\$234,314.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user herrmt1 overridding Payment Estimate Exception 50 on the current Payment Estimate.
									2	24		SYSTEM	(\$234,314.00)									
											2	2	2	2	25		SYSTEM	\$234,314.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0054) due to user kloepj1 overridding Payment Estimate Exception 48 on the current Payment Estimate.			
											25		SYSTEM	(\$234,314.00)								
						SYSTEM	\$234,314.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0049) due to user hillt5 overridding Payment Estimate Exception 53 on the current Payment Estimate.														
					26	Aug 2, 2021	SYSTEM	(\$234,314.00)														
					27	Aug 16, 2021	SYSTEM	\$234,314.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user herrmt1 overridding Payment Estimate Exception 47 on the current Payment Estimate.													
					27	Aug 16, 2021	SYSTEM	(\$234,314.00)														



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	2810	SUPERSTRUCTURE REPAIR (UNFORMED)	Material		28	Sep 2, 2021	SYSTEM	\$374,302.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0063) due to user kloepj1 overridding Payment Estimate Exception 45 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$374,302.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	2810 -	Total						\$0.00	
	2830	MISC.	Material		28	Sep 2, 2021	SYSTEM	\$57,925.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0064) due to user kloepj1 overridding Payment Estimate Exception 51 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$57,925.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	2830 -	Total						\$0.00	
	2940	MECHANICALLY STABILIZED EARTH WALL SYS	Material		8	Nov 2, 2020	SYSTEM	\$81,250.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user hillt5 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					8	Nov 2, 2020	SYSTEM	(\$81,250.00)	
					9	Nov 16, 2020	SYSTEM	\$352,312.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user hillt5 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					9	Nov 16, 2020	SYSTEM	(\$352,312.50)	
					10	Dec 2, 2020	SYSTEM	\$514,875.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					10	Dec 2, 2020	SYSTEM	(\$514,875.00)	
					11	Dec 16, 2020	SYSTEM	\$514,875.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user schlag1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					11	Dec 16, 2020	SYSTEM	(\$514,875.00)	
					12	Jan 4, 2021	SYSTEM	\$542,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					12	Jan 4, 2021	SYSTEM	(\$542,000.00)	
					13	Jan 19, 2021	SYSTEM	\$542,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schlag1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					13	Jan 19, 2021	SYSTEM	(\$542,000.00)	
					14	Feb 2, 2021	SYSTEM	\$542,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user hillt5 overridding Payment Estimate Exception 50 on the current Payment Estimate.
					14	Feb 2, 2021	SYSTEM	(\$542,000.00)	
					15	Feb 16, 2021	SYSTEM	\$542,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schlag1 overridding Payment Estimate Exception 50 on the current Payment Estimate.
					15	Feb 16, 2021	SYSTEM	(\$542,000.00)	
					16	Mar 2, 2021	SYSTEM	\$542,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment Estimate Exception 49 on the current Payment Estimate.
					16	Mar 2, 2021	SYSTEM	(\$542,000.00)	
					17	Mar 16, 2021	SYSTEM	\$542,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 42 on the current Payment Estimate.
					17	Mar 16, 2021	SYSTEM	(\$542,000.00)	



roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
612222	2940	MECHANICALLY STABILIZED EARTH WALL SYS	Material		18	Apr 2, 2021	SYSTEM	\$542,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment Estimate Exception 44 on the current Payment Estimate.
					18	Apr 2, 2021	SYSTEM	(\$542,000.00)	
					19	Apr 16, 2021	SYSTEM	\$542,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user kloepj1 overridding Payment Estimate Exception 48 on the current Payment Estimate.
					19	Apr 16, 2021	SYSTEM	(\$542,000.00)	
					20	May 3, 2021	SYSTEM	\$542,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user hillt5 overridding Payment Estimate Exception 73 on the current Payment Estimate.
					20	May 3, 2021	SYSTEM	(\$542,000.00)	
					21	May 17, 2021	SYSTEM	\$542,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0049) due to user hillt5 overridding Payment Estimate Exception 93 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$542,000.00)	
					22	Jun 2, 2021	SYSTEM	\$542,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user hillt5 overridding Payment Estimate Exception 103 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$542,000.00)	
					23	Jun 16, 2021	SYSTEM	\$542,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0054) due to user kloepj1 overridding Payment Estimate Exception 103 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$542,000.00)	
					24	Jul 1, 2021	SYSTEM	\$542,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user herrmt1 overridding Payment Estimate Exception 65 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$542,000.00)	
					25	Jul 16, 2021	SYSTEM	\$542,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0055) due to user kloepj1 overridding Payment Estimate Exception 57 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$542,000.00)	
					26	Aug 2, 2021	SYSTEM	\$542,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user hillt5 overridding Payment Estimate Exception 63 on the current Payment Estimate.
					26	Aug 2, 2021	SYSTEM	(\$542,000.00)	
					27	Aug 16, 2021	SYSTEM	\$542,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user herrmt1 overridding Payment Estimate Exception 59 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$542,000.00)	
					28	Sep 2, 2021	SYSTEM	\$542,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0065) due to user kloepj1 overridding Payment Estimate Exception 62 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$542,000.00)	
			Material - Tot	- Total				\$0.00	
	2940 -	Total	waterial - Tol	icii —				\$0.00 \$0.00	
	2960	MISC. FENCING	Construction Stockpile		21	May 17, 2021	SYSTEM	(\$16,591.23)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$16,591.23)	
			Construction	Stockpile - 1			01/0===	(\$16,591.23)	
			Construction Stockpile STMI		4	Sep 2, 2020	SYSTEM	\$16,591.23	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$16,591.23	
			Construction	Stockpile S1	MI - Total			\$16,591.23	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	2960 -	· Total						\$0.00	
	3000	CLASS B CONCRETE (SUBSTRUCTURE)	Material		25	Jul 16, 2021	SYSTEM	\$20,396.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0056) due to user kloepj1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$20,396.50)	
					26	Aug 2, 2021	SYSTEM	\$39,719.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0051) due to user hillt5 overridding Payment Estimate Exception 35 on the current Payment Estimate.
					26	Aug 2, 2021	SYSTEM	(\$39,719.50)	
					27	Aug 16, 2021	SYSTEM	\$39,719.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user herrmt1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$39,719.50)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	3000 -	· Total						\$0.00	
	3170	MISC. FENCING	Construction Stockpile STMI		4	Sep 2, 2020	SYSTEM	\$23,938.77	Payment Estimate Item Adjustment generated Stockpile Transaction
			OTIVII	- Total				\$23,938.77	
			Construction	Stockpile S1	ΓΜΙ - Tota			\$23,938.77	
	3170 -	Total						\$23,938.77	
	3180	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	Material		21	May 17, 2021	SYSTEM	\$12,495.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user hillt5 overridding Payment Estimate Exception 39 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$12,495.00)	
					22	Jun 2, 2021	SYSTEM	\$12,495.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user hillt5 overridding Payment Estimate Exception 42 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$12,495.00)	
					23	Jun 16, 2021	SYSTEM	\$12,495.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user kloepj1 overridding Payment Estimate Exception 45 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$12,495.00)	
					24	Jul 1, 2021	SYSTEM	\$12,495.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user herrmt1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$12,495.00)	
					25	Jul 16, 2021	SYSTEM	\$12,495.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user kloepj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$12,495.00)	
					26	Aug 2, 2021	SYSTEM	\$12,495.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user hillt5 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					26	Aug 2, 2021	SYSTEM	(\$12,495.00)	
					27	Aug 16, 2021	SYSTEM	\$12,495.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user herrm11 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$12,495.00)	
					28	Sep 2, 2021	SYSTEM	\$12,495.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user kloepj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$12,495.00)	
				- Total				\$0.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	3180	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	Material - Tot	tal				\$0.00	
	3180 -	Total						\$0.00	
	3190	ROCK SOCKETS (3 FT 0 IN. DIA.)	Material		21	May 17, 2021	SYSTEM	\$24,450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user hillt5 overridding Payment Estimate Exception 46 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$24,450.00)	
					22	Jun 2, 2021	SYSTEM	\$24,450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user hillt5 overridding Payment Estimate Exception 54 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$24,450.00)	
					23	Jun 16, 2021	SYSTEM	\$24,450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user kloepj1 overridding Payment Estimate Exception 57 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$24,450.00)	
					24	Jul 1, 2021	SYSTEM	\$24,450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user herrmt1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$24,450.00)	
					25	Jul 16, 2021	SYSTEM	\$24,450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user kloepj1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$24,450.00)	
					26	Aug 2, 2021	SYSTEM	\$24,450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user hillt5 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					26	Aug 2, 2021	SYSTEM	(\$24,450.00)	
					27	Aug 16, 2021	SYSTEM	\$24,450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user herrmt1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$24,450.00)	
					28	Sep 2, 2021	SYSTEM	\$24,450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user kloepj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$24,450.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	3190 - 3270	CLASS B CONCRETE (SUBSTRUCTURE)	Material		20	May 3, 2021	SYSTEM	\$0.00 \$19,840.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user hillt5 overridding Payment Estimate Exception 32 on the current Payment Estimate.
		(SOBOTIVOCTORE)			20	May 3, 2021	SYSTEM	(\$19,840.00)	Estimate Exception of on the current ayment Estimate.
					21	May 17, 2021	SYSTEM	\$19,840.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user hillt5 overridding Payment Estimate Exception 52 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$19,840.00)	
					22	Jun 2, 2021	SYSTEM	\$19,840.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user hillt5 overridding Payment Estimate Exception 64 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$19,840.00)	
					23	Jun 16, 2021	SYSTEM	\$19,840.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user kloepj1 overridding Payment Estimate Exception 67 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$19,840.00)	



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
2222	3270	CLASS B CONCRETE	Material	- Total				\$0.00	
		(SUBSTRUCTURE)	Material - To	tal				\$0.00	
	3270 -	Total						\$0.00	
	3280	CLASS B-1 CONCRETE (SUBSTR)	Material		24	Jul 1, 2021	SYSTEM	\$63,616.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user herrmt1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$63,616.50)	
					25	Jul 16, 2021	SYSTEM	\$63,616.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user kloepj1 overridding Payment Estimate Exception 35 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$63,616.50)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	3280 -	Total						\$0.00	
	3300		Material		26	Aug 2, 2021	SYSTEM	\$68,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user hillt5 overridding Payment Estimate Exception 41 on the current Payment Estimate.
					26	Aug 2, 2021	SYSTEM	(\$68,150.00)	
					27	Aug 16, 2021	SYSTEM	\$153,337.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user herrmt1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$153,337.50)	
					28	Sep 2, 2021	SYSTEM	\$323,712.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user kloepj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$323,712.50)	
				- Total			\$0.00		
			Material - Total					\$0.00	
	3300 -	Total						\$0.00	
	3350	MISC. CONDUIT SYSTEM ON STRUCTURE	Material		28	Sep 2,		\$3,730.00	This adjustment offsets the original system-generated Material Payment
		OTTOOTOTE				2021	SYSTEM	\$3,730.00	Estimate Item Adjustment (0042) due to user kloepj1 overridding Payment Estimate Exception 53 on the current Payment Estimate.
		OTROCTORE			28		SYSTEM	(\$3,730.00)	Estimate Item Adjustment (0042) due to user kloepj1 overridding Payment
		SINGOTONE		- Total	28	2021 Sep 2,			Estimate Item Adjustment (0042) due to user kloepj1 overridding Payment
		OMOGIONE	Material - To		28	2021 Sep 2,		(\$3,730.00)	Estimate Item Adjustment (0042) due to user kloepj1 overridding Payment
	3350 -		Material - To		28	2021 Sep 2,		(\$3,730.00)	Estimate Item Adjustment (0042) due to user kloepj1 overridding Payment
	3350 -	Total PROTECTIVE COATING - CONCRETE BENTS			28	2021 Sep 2,		(\$3,730.00) \$0.00 \$0.00	Estimate Item Adjustment (0042) due to user kloepj1 overridding Payment
		Total PROTECTIVE COATING -				2021 Sep 2, 2021 Sep 2,	SYSTEM	(\$3,730.00) \$0.00 \$0.00	Estimate Item Adjustment (0042) due to user kloepj1 overridding Payment Estimate Exception 53 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user kloepj1 overridding Payment
		Total PROTECTIVE COATING - CONCRETE BENTS			28	2021 Sep 2, 2021 Sep 2, 2021 Sep 2,	SYSTEM	\$0.00 \$0.00 \$0.00 \$0.00 \$8,330.05	Estimate Item Adjustment (0042) due to user kloepj1 overridding Payment Estimate Exception 53 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user kloepj1 overridding Payment
		Total PROTECTIVE COATING - CONCRETE BENTS		tal - Total	28	2021 Sep 2, 2021 Sep 2, 2021 Sep 2,	SYSTEM	(\$3,730.00) \$0.00 \$0.00 \$0.00 \$8,330.05	Estimate Item Adjustment (0042) due to user kloepj1 overridding Payment Estimate Exception 53 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user kloepj1 overridding Payment
		PROTECTIVE COATING - CONCRETE BENTS AND	Material	tal - Total	28	2021 Sep 2, 2021 Sep 2, 2021 Sep 2,	SYSTEM	(\$3,730.00) \$0.00 \$0.00 \$0.00 \$8,330.05 (\$8,330.05)	Estimate Item Adjustment (0042) due to user kloepj1 overridding Payment Estimate Exception 53 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user kloepj1 overridding Payment
	3355	Total PROTECTIVE COATING - CONCRETE BENTS AND Total FAB. SIGN SUPPORT	Material - To Construction Stockpile	tal - Total	28	2021 Sep 2, 2021 Sep 2, 2021 Sep 2,	SYSTEM	(\$3,730.00) \$0.00 \$0.00 \$0.00 \$8,330.05 (\$8,330.05) \$0.00	Estimate Item Adjustment (0042) due to user kloepj1 overridding Payment Estimate Exception 53 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user kloepj1 overridding Payment
	3355 -	PROTECTIVE COATING - CONCRETE BENTS AND Total FAB. SIGN	Material Material - To Construction	tal - Total	28	Sep 2, 2021 Sep 2, 2021 Sep 2, 2021 Apr 16,	SYSTEM SYSTEM	(\$3,730.00) \$0.00 \$0.00 \$0.00 \$8,330.05 (\$8,330.05) \$0.00 \$0.00	Estimate Item Adjustment (0042) due to user kloepj1 overridding Payment Estimate Exception 53 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user kloepj1 overridding Payment Estimate Exception 60 on the current Payment Estimate.
	3355 -	Total PROTECTIVE COATING - CONCRETE BENTS AND Total FAB. SIGN SUPPORT	Material - To Construction Stockpile STMI	- Total	28	Sep 2, 2021 Sep 2, 2021 Sep 2, 2021 Apr 16, 2021	SYSTEM SYSTEM	(\$3,730.00) \$0.00 \$0.00 \$0.00 \$8,330.05 (\$8,330.05) \$0.00 \$0.00 \$14,500.00	Estimate Item Adjustment (0042) due to user kloepj1 overridding Payment Estimate Exception 53 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user kloepj1 overridding Payment Estimate Exception 60 on the current Payment Estimate.
	3355 -	PROTECTIVE COATING - CONCRETE BENTS AND Total FAB. SIGN SUPPORT BRACKETS	Material - To Construction Stockpile STMI	- Total	28	Sep 2, 2021 Sep 2, 2021 Sep 2, 2021 Apr 16, 2021	SYSTEM SYSTEM	(\$3,730.00) \$0.00 \$0.00 \$0.00 \$8,330.05 (\$8,330.05) \$0.00 \$0.00 \$14,500.00	Estimate Item Adjustment (0042) due to user kloepj1 overridding Payment Estimate Exception 53 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user kloepj1 overridding Payment Estimate Exception 60 on the current Payment Estimate.
	3355 - 3370	PROTECTIVE COATING - CONCRETE BENTS AND Total FAB. SIGN SUPPORT BRACKETS	Material - To Construction Stockpile STMI	- Total	28	Sep 2, 2021 Sep 2, 2021 Sep 2, 2021 Apr 16, 2021	SYSTEM SYSTEM	(\$3,730.00) \$0.00 \$0.00 \$0.00 \$8,330.05 (\$8,330.05) \$0.00 \$0.00 \$14,500.00 \$14,500.00	Estimate Item Adjustment (0042) due to user kloepj1 overridding Payment Estimate Exception 53 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user kloepj1 overridding Payment Estimate Exception 60 on the current Payment Estimate.
	3355 - 3370 -	Total PROTECTIVE COATING - CONCRETE BENTS AND Total FAB. SIGN SUPPORT BRACKETS Total PIPE PILE	Material - To Construction Stockpile STMI Construction	- Total	28 28 19	2021 Sep 2, 2021 Sep 2, 2021 Sep 2, 2021 Apr 16, 2021	SYSTEM SYSTEM SYSTEM	(\$3,730.00) \$0.00 \$0.00 \$0.00 \$8,330.05 (\$8,330.05) \$0.00 \$0.00 \$14,500.00 \$14,500.00 \$14,500.00	Estimate Item Adjustment (0042) due to user kloepj1 overridding Payment Estimate Exception 53 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user kloepj1 overridding Payment Estimate Exception 60 on the current Payment Estimate. Payment Estimate Item Adjustment generated Stockpile Transaction This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment



22	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
	3400	PIPE PILE SPACERS	Material						Estimate Exception 57 on the current Payment Estimate.
					19	Apr 16, 2021	SYSTEM	(\$11,970.00)	
					20	May 3, 2021	SYSTEM	\$11,970.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hillt5 overridding Payment Estimate Exception 82 on the current Payment Estimate.
					20	May 3, 2021	SYSTEM	(\$11,970.00)	
					21	May 17, 2021	SYSTEM	\$11,970.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user hillt5 overridding Payment Estimate Exception 102 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$11,970.00)	
					22	Jun 2, 2021	SYSTEM	\$11,970.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user hillt5 overridding Payment Estimate Exception 112 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$11,970.00)	
					23	Jun 16, 2021	SYSTEM	\$11,970.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user kloepj1 overridding Payment Estimate Exception 111 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$11,970.00)	
					24	Jul 1, 2021	SYSTEM	\$11,970.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user herrmt1 overridding Payment Estimate Exception 73 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$11,970.00)	
					25	Jul 16, 2021	SYSTEM	\$11,970.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user kloepj1 overridding Payment Estimate Exception 65 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$11,970.00)	
					26	Aug 2, 2021	SYSTEM	\$11,970.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user hillt5 overridding Payment Estimate Exception 70 on the current Payment Estimate.
					26	Aug 2, 2021	SYSTEM	(\$11,970.00)	
					07				
					27	Aug 16, 2021	SYSTEM	\$11,970.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user herrmt1 overridding Payment Estimate Exception 66 on the current Payment Estimate.
					27		SYSTEM	\$11,970.00 (\$11,970.00)	Estimate Item Adjustment (0027) due to user herrmt1 overridding Payment
						2021 Aug 16,			Estimate Item Adjustment (0027) due to user herrmt1 overridding Payment
					27	2021 Aug 16, 2021 Sep 2,	SYSTEM	(\$11,970.00)	Estimate Item Adjustment (0027) due to user herrmt1 overridding Payment Estimate Exception 66 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user kloepj1 overridding Payment
				- Total	27	2021 Aug 16, 2021 Sep 2, 2021 Sep 2,	SYSTEM	(\$11,970.00) \$11,970.00 (\$11,970.00) \$0.00	Estimate Item Adjustment (0027) due to user herrmt1 overridding Payment Estimate Exception 66 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user kloepj1 overridding Payment
	3400	Total	Material - To		27	2021 Aug 16, 2021 Sep 2, 2021 Sep 2,	SYSTEM	(\$11,970.00) \$11,970.00 (\$11,970.00) \$0.00	Estimate Item Adjustment (0027) due to user herrmt1 overridding Payment Estimate Exception 66 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user kloepj1 overridding Payment
	3400 - 3420	Total AESTHETIC CONCRETE STAIN	Material - To		27	2021 Aug 16, 2021 Sep 2, 2021 Sep 2,	SYSTEM	(\$11,970.00) \$11,970.00 (\$11,970.00) \$0.00	Estimate Item Adjustment (0027) due to user herrmt1 overridding Payment Estimate Exception 66 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user kloepj1 overridding Payment Estimate Exception 69 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment
		AESTHETIC			27 28 28	2021 Aug 16, 2021 Sep 2, 2021 Sep 2, 2021 Sep 2, 2021	SYSTEM SYSTEM SYSTEM	(\$11,970.00) \$11,970.00 (\$11,970.00) \$0.00 \$0.00	Estimate Item Adjustment (0027) due to user herrmt1 overridding Payment Estimate Exception 66 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user kloep/1 overridding Payment Estimate Exception 69 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0066) due to user kloep/1 overridding Payment
		AESTHETIC			27 28 28 28	2021 Aug 16, 2021 Sep 2, 2021 Sep 2, 2021 Sep 2, 2021 Sep 2, 2021	SYSTEM SYSTEM SYSTEM	(\$11,970.00) \$11,970.00 (\$11,970.00) \$0.00 \$0.00 \$7,856.10	Estimate Item Adjustment (0027) due to user herrmt1 overridding Payment Estimate Exception 66 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user kloep/1 overridding Payment Estimate Exception 69 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0066) due to user kloep/1 overridding Payment
		AESTHETIC		tal - Total	27 28 28 28	2021 Aug 16, 2021 Sep 2, 2021 Sep 2, 2021 Sep 2, 2021 Sep 2, 2021	SYSTEM SYSTEM SYSTEM	(\$11,970.00) \$11,970.00 (\$11,970.00) \$0.00 \$0.00 \$7,856.10	Estimate Item Adjustment (0027) due to user herrmt1 overridding Payment Estimate Exception 66 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user kloepj1 overridding Payment Estimate Exception 69 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0066) due to user kloepj1 overridding Payment
		AESTHETIC CONCRETE STAIN	Material	tal - Total	27 28 28 28	2021 Aug 16, 2021 Sep 2, 2021 Sep 2, 2021 Sep 2, 2021 Sep 2, 2021	SYSTEM SYSTEM SYSTEM	(\$11,970.00) \$11,970.00 (\$11,970.00) \$0.00 \$0.00 \$7,856.10 (\$7,856.10)	Estimate Item Adjustment (0027) due to user herrmt1 overridding Payment Estimate Exception 66 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user kloepj1 overridding Payment Estimate Exception 69 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0066) due to user kloepj1 overridding Payment Estimate Item Adjustment (0066) due to user kloepj1 overridding Payment
	3420	AESTHETIC CONCRETE STAIN	Material Material - To	tal - Total	27 28 28 28	2021 Aug 16, 2021 Sep 2, 2021 Sep 2, 2021 Sep 2, 2021 Sep 2, 2021	SYSTEM SYSTEM SYSTEM	(\$11,970.00) \$11,970.00 (\$11,970.00) \$0.00 \$0.00 \$7,856.10 (\$7,856.10) \$0.00	Estimate Item Adjustment (0027) due to user herrmt1 overridding Payment Estimate Exception 66 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user kloepj1 overridding Payment Estimate Exception 69 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0066) due to user kloepj1 overridding Payment
	3420	AESTHETIC CONCRETE STAIN Total MECHANICALLY STABILIZED EARTH	Material Material - To	tal - Total	27 28 28 28 28	2021 Aug 16, 2021 Sep 2, 2021 Sep 2, 2021 Sep 2, 2021 Apr 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$11,970.00) \$11,970.00) \$11,970.00) \$0.00 \$0.00 \$7,856.10 \$0.00 \$0.00 \$0.00	Estimate Item Adjustment (0027) due to user herrmt1 overridding Payment Estimate Exception 66 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user kloepj1 overridding Payment Estimate Exception 69 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0066) due to user kloepj1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user kloepj1 overridding Payment Estimate Item Adjustment (0029) due to user kloepj1 overridding Payment Estimate Item Adjustment (0029) due to user kloepj1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	3430	MECHANICALLY STABILIZED EARTH	Material						Estimate Exception 75 on the current Payment Estimate.
		WALL SYS			20	May 3, 2021	SYSTEM	(\$66,880.00)	
					21	May 17, 2021	SYSTEM	\$66,880.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0051) due to user hillto overridding Payment Estimate Exception 95 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$66,880.00)	
					22	Jun 2, 2021	SYSTEM	\$66,880.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user hillt5 overridding Payment Estimate Exception 105 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$66,880.00)	
					23	Jun 16, 2021	SYSTEM	\$66,880.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0055) due to user kloepj1 overridding Payment Estimate Exception 105 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$66,880.00)	
					24	Jul 1, 2021	SYSTEM	\$66,880.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user herrmt1 overridding Payment Estimate Exception 67 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$66,880.00)	
					25	Jul 16, 2021	SYSTEM	\$66,880.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0057) due to user kloepj1 overridding Payment Estimate Exception 59 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$66,880.00)	
					26	Aug 2, 2021	SYSTEM	\$66,880.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0052) due to user hillt5 overridding Payment Estimate Exception 65 on the current Payment Estimate.
					26	Aug 2, 2021	SYSTEM	(\$66,880.00)	
					27	Aug 16, 2021	SYSTEM	\$334,560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user herrmt1 overridding Payment Estimate Exception 61 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$334,560.00)	
					28	Sep 2, 2021	SYSTEM	\$334,560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0067) due to user kloepj1 overridding Payment Estimate Exception 64 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$334,560.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	3430 -							\$0.00	
	3440	AESTHETIC CONCRETE STAIN	Material		28	Sep 2, 2021	SYSTEM	\$3,654.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0068) due to user kloepj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$3,654.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	3440 -		Metail		10	A == 0	CVOTEL	\$0.00	This adjustment effects the adjustment of the control of the contr
	3450	MECHANICALLY STABILIZED EARTH WALL SYS	Material		18	Apr 2, 2021	SYSTEM	\$50,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user kloepj1 overridding Payment Estimate Exception 46 on the current Payment Estimate.
					18	Apr 2, 2021	SYSTEM	(\$50,400.00)	
					19	Apr 16, 2021	SYSTEM	\$181,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user kloep/1 overridding Payment Estimate Exception 53 on the current Payment Estimate.
					19	Apr 16, 2021	SYSTEM	(\$181,520.00)	
					20	May 3, 2021	SYSTEM	\$181,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user hillt5 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	3450	MECHANICALLY STABILIZED EARTH	Material						Estimate Exception 78 on the current Payment Estimate.
		WALL SYS			20	May 3, 2021	SYSTEM	(\$181,520.00)	
					21	May 17, 2021	SYSTEM	\$181,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0052) due to user hillt5 overridding Payment Estimate Exception 98 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$181,520.00)	
					22	Jun 2, 2021	SYSTEM	\$181,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user hillt5 overridding Payment Estimate Exception 109 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$181,520.00)	
					23	Jun 16, 2021	SYSTEM	\$181,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0056) due to user kloepj1 overridding Payment Estimate Exception 108 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$181,520.00)	
					24	Jul 1, 2021	SYSTEM	\$181,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user herrmt1 overridding Payment Estimate Exception 70 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$181,520.00)	
					25	Jul 16, 2021	SYSTEM	\$181,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user kloepj1 overridding Payment Estimate Exception 62 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$181,520.00)	
					26	Aug 2, 2021	SYSTEM	\$181,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0053) due to user hillt5 overridding Payment Estimate Exception 67 on the current Payment Estimate.
					26	Aug 2, 2021	SYSTEM	(\$181,520.00)	
					27	Aug 16, 2021	SYSTEM	\$201,680.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user herrmt1 overridding Payment Estimate Exception 63 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$201,680.00)	
					28	Sep 2, 2021	SYSTEM	\$201,680.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0069) due to user kloepj1 overridding Payment Estimate Exception 66 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$201,680.00)	
				- Total				\$0.00	
	3450 -	Total	Material - To	tai				\$0.00 \$0.00	
		DRILLED SHAFTS (6 FT. 0 IN. DIA.)	Material		22	Jun 2, 2021	SYSTEM	\$0.00 \$25,409.15	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0048) due to user hillt5 overridding Payment Estimate Exception 49 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$25,409.15)	
					23	Jun 16, 2021	SYSTEM	\$89,157.55	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0057) due to user kloepj1 overridding Payment Estimate Exception 52 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$89,157.55)	
					24	Jul 1, 2021	SYSTEM	\$89,157.55	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user herrmt1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$89,157.55)	
					25	Jul 16, 2021	SYSTEM	\$119,387.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0059) due to user kloepj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$119,387.60)	



oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
2222	3480	DRILLED SHAFTS (6 FT. 0 IN. DIA.)	Material		26	Aug 2, 2021	SYSTEM	\$119,387.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0054) due to user hillt5 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					26	Aug 2, 2021	SYSTEM	(\$119,387.60)	
					27	Aug 16, 2021	SYSTEM	\$119,387.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0048) due to user herrmt1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$119,387.60)	
					28	Sep 2, 2021	SYSTEM	\$119,387.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0070) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$119,387.60)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	3480 -	Total						\$0.00	
	3490	ROCK SOCKETS (5 FT 6 IN. DIA.)	Material		22	Jun 2, 2021	SYSTEM	\$95,378.15	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0049) due to user hillt5 overridding Payment Estimate Exception 59 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$95,378.15)	
					23	Jun 16, 2021	SYSTEM	\$214,006.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user kloepj1 overridding Payment Estimate Exception 62 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$214,006.80)	
					24	Jul 1, 2021	SYSTEM	\$214,006.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0048) due to user herrmt1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$214,006.80)	
					25	Jul 16, 2021	SYSTEM	\$275,940.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user kloepj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$275,940.00)	
					26	Aug 2, 2021	SYSTEM	\$275,940.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0055) due to user hillt5 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					26	Aug 2, 2021	SYSTEM	(\$275,940.00)	
					27	Aug 16, 2021	SYSTEM	\$275,940.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0049) due to user herrmt1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$275,940.00)	
					28	Sep 2, 2021	SYSTEM	\$275,940.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0071) due to user kloepj1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$275,940.00)	,
				- Total	28		SYSTEM	(\$275,940.00) \$0.00	
			Material - To		28		SYSTEM	\$0.00 \$0.00	
	3490 -					2021		\$0.00 \$0.00 \$0.00	
	3490 - 3630	Total REINFORCING STEEL (BRIDGES)			22	Jun 2, 2021	SYSTEM	\$0.00 \$0.00 \$0.00 \$26,851.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user hillt5 overridding Payment Estimate Exception 94 on the current Payment Estimate.
		REINFORCING				2021 Jun 2,		\$0.00 \$0.00 \$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user hillt5 overridding Payment
		REINFORCING			22	Jun 2, 2021 Jun 2,	SYSTEM	\$0.00 \$0.00 \$0.00 \$26,851.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user hillt5 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	3630	REINFORCING STEEL (BRIDGES)	Material		24	Jul 1, 2021	SYSTEM	\$84,192.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0049) due to user herrmt1 overridding Payment Estimate Exception 57 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$84,192.50)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	3630 -	Total						\$0.00	
	3760	MISC. STRUCTURAL STEEL	Construction Stockpile STMI		14	Feb 2, 2021	SYSTEM	\$26,016.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		CONSTRUCTION		- Total				\$26,016.00	
	0=00		Construction	1 Stockpile S	TMI - Tota			\$26,016.00	
	3760 -		:			5.1.0	OVOTEM	\$26,016.00	
	3830	STRIP SEAL EXPANSION JOINT SYSTEM	Construction Stockpile STMI	- Total	14	Feb 2, 2021	SYSTEM	\$5,544.00 \$5,544.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			Construction	Stockpile S	TMI - Tota			\$5,544.00	
	3830 -	Total						\$5,544.00	
	5003	MISC. DRAINAGE FITTINGS	Material		28	Sep 2, 2021	SYSTEM	\$9,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0072) due to user kloepj1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$9,800.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	5003 -	Total						\$0.00	
	5007	MISC. ITS	Construction Stockpile STMI		20	May 3, 2021	SYSTEM	\$75,000.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$75,000.00	
		_	Construction	Stockpile S	TMI - Tota			\$75,000.00	
	5007 -			Stockpile S			270	\$75,000.00	
	5007 -	Total MISC. DRAINAGE FITTINGS		n Stockpile S	TMI - Tota	Apr 16, 2021	SYSTEM		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user kloepj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
		MISC. DRAINAGE		stockpile S		Apr 16,	SYSTEM	\$75,000.00	Estimate Item Adjustment (0031) due to user kloepj1 overridding Payment
		MISC. DRAINAGE		a Stockpile S	19	Apr 16, 2021		\$75,000.00 \$400.00	Estimate Item Adjustment (0031) due to user kloepj1 overridding Payment
		MISC. DRAINAGE		a Stockpile S	19	Apr 16, 2021 Apr 16, 2021 May 3,	SYSTEM	\$75,000.00 \$400.00 (\$400.00)	Estimate Item Adjustment (0031) due to user kloepj1 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user hillt5 overridding Payment
		MISC. DRAINAGE		a Stockpile S	19 19 20	Apr 16, 2021 Apr 16, 2021 May 3, 2021 May 3, 2021	SYSTEM	\$75,000.00 \$400.00 (\$400.00) \$400.00	Estimate Item Adjustment (0031) due to user kloepj1 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user hillt5 overridding Payment
		MISC. DRAINAGE		a Stockpile S	19 19 20 20	Apr 16, 2021 Apr 16, 2021 May 3, 2021 May 3, 2021 May 17, 400	SYSTEM SYSTEM	\$75,000.00 \$400.00 (\$400.00) \$400.00	Estimate Item Adjustment (0031) due to user kloepj1 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user hillt5 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0053) due to user hillt5 overridding Payment
		MISC. DRAINAGE		Stockpile S	19 19 20 20 21	Apr 16, 2021 Apr 16, 2021 May 3, 2021 May 3, 2021 May 17, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$75,000.00 \$400.00 (\$400.00) \$400.00 (\$400.00)	Estimate Item Adjustment (0031) due to user kloepj1 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user hillt5 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0053) due to user hillt5 overridding Payment
		MISC. DRAINAGE		Stockpile S	19 19 20 20 21	Apr 16, 2021 Apr 16, 2021 May 3, 2021 May 3, 2021 May 17, 2021 Jun 2,	SYSTEM SYSTEM SYSTEM SYSTEM	\$75,000.00 \$400.00 (\$400.00) \$400.00 (\$400.00) (\$400.00)	Estimate Item Adjustment (0031) due to user kloepj1 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user hillt5 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0053) due to user hillt5 overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0051) due to user hillt5 overridding Payment Estimate Item Adjustment (0051) due to user hillt5 overridding Payment
		MISC. DRAINAGE		Stockpile S	19 19 20 20 21 21 22	Apr 16, 2021 Apr 16, 2021 May 3, 2021 May 3, 2021 May 17, 2021 Jun 2, 2021 Jun 2, 1021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$75,000.00 \$400.00 (\$400.00) \$400.00 (\$400.00) \$400.00 (\$400.00)	Estimate Item Adjustment (0031) due to user kloepj1 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user hillt5 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0053) due to user hillt5 overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0051) due to user hillt5 overridding Payment Estimate Item Adjustment (0051) due to user hillt5 overridding Payment
		MISC. DRAINAGE		a Stockpile S	19 19 20 20 21 21 22 22	Apr 16, 2021 Apr 16, 2021 May 3, 2021 May 37, 2021 May 17, 2021 Jun 2, 2021 Jun 2, 2021 Jun 16, 1000	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$75,000.00 \$400.00 (\$400.00) \$400.00 (\$400.00) \$400.00 (\$400.00)	Estimate Item Adjustment (0031) due to user kloepj1 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user hillt5 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0053) due to user hillt5 overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0051) due to user hillt5 overridding Payment Estimate Exception 35 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 35 on the current Payment Estimate.
		MISC. DRAINAGE		n Stockpile S	19 19 20 20 21 21 22 22 23	Apr 16, 2021 Apr 16, 2021 May 3, 2021 May 3, 2021 May 17, 2021 Jun 2, 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$75,000.00 \$400.00 (\$400.00) \$400.00 (\$400.00) \$400.00 (\$400.00) \$400.00	Estimate Item Adjustment (0031) due to user kloepj1 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user hillt5 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0053) due to user hillt5 overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0051) due to user hillt5 overridding Payment Estimate Exception 35 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 35 on the current Payment Estimate.
		MISC. DRAINAGE		n Stockpile S	19 19 20 20 21 21 22 22 23	Apr 16, 2021 Apr 16, 2021 Apr 16, 2021 May 3, 2021 May 17, 2021 Jun 2, 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jun 16, 2021 Jun 11,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$75,000.00 \$400.00) (\$400.00) \$400.00 (\$400.00) \$400.00 (\$400.00) \$400.00 (\$400.00)	Estimate Item Adjustment (0031) due to user kloepj1 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user hillt5 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0053) due to user hillt5 overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0051) due to user hillt5 overridding Payment Estimate Exception 35 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user kloepj1 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 38 on the current Payment Estimate.



ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
22	5008	MISC. DRAINAGE FITTINGS	Material						Estimate Exception 22 on the current Payment Estimate.		
		FITTINGS			25	Jul 16, 2021	SYSTEM	(\$400.00)			
					26	Aug 2, 2021	SYSTEM	\$400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0056) due to user hillt5 overridding Payment Estimate Exception 22 on the current Payment Estimate.		
					26	Aug 2, 2021	SYSTEM	(\$400.00)	Zounido Zoopion ZZ on die cancilit dynien Zounido.		
					27	Aug 16, 2021	SYSTEM	\$400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user herrmt1 overridding Payment Estimate Exception 14 on the current Payment Estimate.		
					27	Aug 16, 2021	SYSTEM	(\$400.00)			
					28	Sep 2, 2021	SYSTEM	\$400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0073) due to user kloepj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.		
					28	Sep 2, 2021	SYSTEM	(\$400.00)			
				- Total				\$0.00			
			Material - Tot	tal				\$0.00			
	5008 -	Total						\$0.00			
	5009	CLASS C EXCAVATION	Price FUEL		21	May 17, 2021	SYSTEM	\$154.54	Reference Item Price Adjustment Index Adjustment Type applied is FUEL		
				- Total				\$154.54			
			Price FUEL -	Total				\$154.54			
	5009 -	Total						\$154.54			
	5009 -	1.11	Material		22	Jun 2, 2021	SYSTEM	\$25,203.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0052) due to user hillt5 overridding Payment Estimate Exception 98 on the current Payment Estimate.		
							22	Jun 2, 2021	SYSTEM	(\$25,203.50)	
					23	Jun 16, 2021	SYSTEM	\$25,203.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0061) due to user kloepj1 overridding Payment Estimate Exception 98 on the current Payment Estimate.		
					23	Jun 16, 2021	SYSTEM	(\$25,203.50)			
					24	Jul 1, 2021	SYSTEM	\$25,203.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0051) due to user herrmt1 overridding Payment Estimate Exception 60 on the current Payment Estimate.		
					24	Jul 1, 2021	SYSTEM	(\$25,203.50)			
					25	Jul 16, 2021	SYSTEM	\$25,203.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0062) due to user kloepj1 overridding Payment Estimate Exception 54 on the current Payment Estimate.		
					25	Jul 16, 2021	SYSTEM	(\$25,203.50)			
				- Total				\$0.00			
			Material - To	tal				\$0.00			
	5011 -							\$0.00			
	5013	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	Material		14	Feb 2, 2021	SYSTEM	\$115,139.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user hillt5 overridding Payment Estimate Exception 19 on the current Payment Estimate.		
		,							Estimate Exception to on the outloner aymone Estimate.		
		,			14	Feb 2, 2021	SYSTEM	(\$115,139.70)	Estimate Exception to our tile surrount dynamic Estimate.		
		,			14		SYSTEM	(\$115,139.70) \$115,139.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schlag1 overridding Payment Estimate Exception 27 on the current Payment Estimate.		
						2021 Feb 16,	SYSTEM	,	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schlag1 overridding Payment		
					15	2021 Feb 16, 2021 Feb 16,	SYSTEM	\$115,139.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schlag1 overridding Payment		



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
5013	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	Material		17	Mar 16, 2021	SYSTEM	\$115,139.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
				17	Mar 16, 2021	SYSTEM	(\$115,139.70)	
				18	Apr 2, 2021	SYSTEM	\$115,139.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user kloepj1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
				18	Apr 2, 2021	SYSTEM	(\$115,139.70)	
				19	Apr 16, 2021	SYSTEM	\$115,139.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user kloepj1 overridding Paymen Estimate Exception 23 on the current Payment Estimate.
				19	Apr 16, 2021	SYSTEM	(\$115,139.70)	
				20	May 3, 2021	SYSTEM	\$115,139.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user hillt5 overridding Payment Estimate Exception 26 on the current Payment Estimate.
				20	May 3, 2021	SYSTEM	(\$115,139.70)	
				21	May 17, 2021	SYSTEM	\$115,139.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0055) due to user hillt5 overridding Payment Estimate Exception 43 on the current Payment Estimate.
				21	May 17, 2021	SYSTEM	(\$115,139.70)	
				22	Jun 2, 2021	SYSTEM	\$115,139.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0053) due to user hillto overridding Payment Estimate Exception 46 on the current Payment Estimate.
				22	Jun 2, 2021	SYSTEM	(\$115,139.70)	
				23	Jun 16, 2021	SYSTEM	\$115,139.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0062) due to user kloepj1 overridding Paymen Estimate Exception 49 on the current Payment Estimate.
				23	Jun 16, 2021	SYSTEM	(\$115,139.70)	
				24	Jul 1, 2021	SYSTEM	\$115,139.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0052) due to user herrmt1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
				24	Jul 1, 2021	SYSTEM	(\$115,139.70)	
				25	Jul 16, 2021	SYSTEM	\$115,139.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0063) due to user kloepj1 overridding Paymen Estimate Exception 27 on the current Payment Estimate.
				25	Jul 16, 2021	SYSTEM	(\$115,139.70)	
				26	Aug 2, 2021	SYSTEM	\$115,139.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0057) due to user hillto overridding Payment Estimate Exception 27 on the current Payment Estimate.
				26	Aug 2, 2021	SYSTEM	(\$115,139.70)	
				27	Aug 16, 2021	SYSTEM	\$115,139.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0051) due to user herrmt1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
				27	Aug 16, 2021	SYSTEM	(\$115,139.70)	
				28	Sep 2, 2021	SYSTEM	\$115,139.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0074) due to user kloepj1 overridding Paymen Estimate Exception 19 on the current Payment Estimate.
				28	Sep 2, 2021	SYSTEM	(\$115,139.70)	
			- Total				\$0.00	
F046	Total	Material - Tot	al				\$0.00	
5013	ROCK SOCKETS (3 FT 0 IN. DIA.)	Material		14	Feb 2, 2021	SYSTEM	\$0.00 \$70,341.57	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user hillts overridding Payment
				14	Feb 2,	SYSTEM	(\$70,341.57)	Estimate Exception 26 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	5014	ROCK SOCKETS (3	Material			2021			
		FT 0 IN. DIA.)			15	Feb 16, 2021	SYSTEM	\$70,341.57	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schlag1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
					15	Feb 16, 2021	SYSTEM	(\$70,341.57)	
					16	Mar 2, 2021	SYSTEM	\$70,341.57	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					16	Mar 2, 2021	SYSTEM	(\$70,341.57)	
					17	Mar 16, 2021	SYSTEM	\$70,341.57	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					17	Mar 16, 2021	SYSTEM	(\$70,341.57)	
					18	Apr 2, 2021	SYSTEM	\$70,341.57	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user kloepj1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					18	Apr 2, 2021	SYSTEM	(\$70,341.57)	
					19	Apr 16, 2021	SYSTEM	\$70,341.57	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user kloepj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					19	Apr 16, 2021	SYSTEM	(\$70,341.57)	
					20	May 3, 2021	SYSTEM	\$70,341.57	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user hillt5 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					20	May 3, 2021	SYSTEM	(\$70,341.57)	
					21	May 17, 2021	SYSTEM	\$70,341.57	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0056) due to user hillto overridding Payment Estimate Exception 49 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$70,341.57)	
					22	Jun 2, 2021	SYSTEM	\$70,341.57	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0054) due to user hillt5 overridding Payment Estimate Exception 57 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$70,341.57)	
					23	Jun 16, 2021	SYSTEM	\$70,341.57	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0063) due to user kloepj1 overridding Payment Estimate Exception 60 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$70,341.57)	
					24	Jul 1, 2021	SYSTEM	\$70,341.57	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0053) due to user herrmt1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$70,341.57)	
					25	Jul 16, 2021	SYSTEM	\$70,341.57	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0064) due to user kloepj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$70,341.57)	
					26	Aug 2, 2021	SYSTEM	\$70,341.57	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user hillt5 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					26	Aug 2, 2021	SYSTEM	(\$70,341.57)	
					27	Aug 16, 2021	SYSTEM	\$70,341.57	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0052) due to user herrmt1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$70,341.57)	
					28	Sep 2, 2021	SYSTEM	\$70,341.57	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0075) due to user kloepj1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks									
J6I2222	5014	ROCK SOCKETS (3 FT 0 IN. DIA.)	Material						Estimate Exception 23 on the current Payment Estimate.									
		TT OIN. DIA.)			28	Sep 2, 2021	SYSTEM	(\$70,341.57)										
				- Total				\$0.00										
			Material - To	tal				\$0.00										
	5014 -	Total						\$0.00										
	5015	REINFORCING STEEL (EPOXY COATED)	Material		14	Feb 2, 2021	SYSTEM	\$36,892.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user hillt5 overridding Payment Estimate Exception 42 on the current Payment Estimate.									
					14	Feb 2, 2021	SYSTEM	(\$36,892.40)										
					15	Feb 16, 2021	SYSTEM	\$36,892.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schlag1 overridding Payment Estimate Exception 47 on the current Payment Estimate.									
					15	Feb 16, 2021	SYSTEM	(\$36,892.40)										
					16	Mar 2, 2021	SYSTEM	\$36,892.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user kloepj1 overridding Payment Estimate Exception 46 on the current Payment Estimate.									
					16	Mar 2, 2021	SYSTEM	(\$36,892.40)										
					17	Mar 16, 2021	SYSTEM	\$36,892.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment Estimate Exception 39 on the current Payment Estimate.									
					17	Mar 16, 2021	SYSTEM	(\$36,892.40)										
					18	Apr 2, 2021	SYSTEM	\$36,892.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user kloepj1 overridding Payment Estimate Exception 42 on the current Payment Estimate.									
					18	Apr 2, 2021	SYSTEM	(\$36,892.40)										
					19	Apr 16, 2021	SYSTEM	\$36,892.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user kloepj1 overridding Payment Estimate Exception 46 on the current Payment Estimate.									
					19	Apr 16, 2021	SYSTEM	(\$36,892.40)										
					20	May 3, 2021	SYSTEM	\$36,892.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user hillt5 overridding Payment Estimate Exception 64 on the current Payment Estimate.									
								20	May 3, 2021	SYSTEM	(\$36,892.40)							
									21	May 17, 2021	SYSTEM	\$36,892.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0057) due to user hillt5 overridding Payment Estimate Exception 84 on the current Payment Estimate.					
					21	May 17, 2021	SYSTEM	(\$36,892.40)										
														22	Jun 2, 2021	SYSTEM	\$36,892.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0055) due to user hillt5 overridding Payment Estimate Exception 99 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$36,892.40)										
										23	Jun 16, 2021	SYSTEM	\$36,892.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0064) due to user kloepj1 overridding Payment Estimate Exception 99 on the current Payment Estimate.				
					23	Jun 16, 2021	SYSTEM	(\$36,892.40)										
														24	Jul 1, 2021	SYSTEM	\$36,892.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0054) due to user herrmt1 overridding Payment Estimate Exception 61 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$36,892.40)										
					25	Jul 16, 2021	SYSTEM	\$36,892.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0065) due to user kloepj1 overridding Payment Estimate Exception 55 on the current Payment Estimate.									
					25	Jul 16, 2021	SYSTEM	(\$36,892.40)										



Major Part	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
22	J6I2222	5015	STEEL (EPOXY	Material		26		SYSTEM	\$36,892.40	Estimate Item Adjustment (0059) due to user hillt5 overridding Payment
2025						26		SYSTEM	(\$36,892.40)	
2021 28 Sep 2 2021 29 29 29 29 29 29 29						27		SYSTEM	\$36,892.40	Estimate Item Adjustment (0053) due to user herrmt1 overridding Payment
2021 Sep 2, SYSTEM (536,092.40) Sep 2. SYSTEM (536,092.40)						27		SYSTEM	(\$36,892.40)	
Solid Soli						28		SYSTEM	\$36,892.40	Estimate Item Adjustment (0076) due to user kloepj1 overridding Payment
Material - Total Solid S						28		SYSTEM	(\$36,892.40)	
Solid					- Total				\$0.00	
SOTIO MECHANICAL DATA SPLICE Material 14 Fab 2, SYSTEM (\$2,532,80) This adjustment foliates the notiginal system-generated Material Pyryment Estimate Exception 41 on the current Payment Estimate. 1500 SOTIO TOTAL SOUND FURN A PLACE CONG MATL FOR FULL DEPTH 15 Fab 16, SYSTEM (\$18,227,00) 16 Mar 2, SYSTEM (\$18,227,00) 17 Mar 16, SYSTEM (\$18,227,00) 18 Apr 2, SYSTEM (\$18,227,00) 18 Apr 2, SYSTEM (\$18,227,00) 19 Apr 16, SYSTEM (\$18,227,00) 10 May 3, SYSTEM (\$18,227,00) 10 May 17, SYSTEM (\$18,227,00) 11 May 17, SYSTEM (\$18,227,00) 12 May 17, SYSTEM (\$18,227,00) 13 May 17, SYSTEM (\$18,227,00) 14 May 17, SYSTEM (\$18,227,00) 15 SYSTEM (\$18,227,00) 16 SHE SYSTEM (\$18,227,00) 17 Mar 16, SYSTEM (\$18,227,00) 18 Apr 2, SYSTEM (\$18,227,00) 19 Apr 16, SYSTEM (\$18,227,00) 10 May 3, SYSTEM (\$18,227,00) 10 May 3, SYSTEM (\$18,227,00) 11 May 17, SYSTEM (\$18,227,00) 12 May 17, SYSTEM (\$18,227,00) 13 May 17, SYSTEM (\$18,227,00) 14 May 17, SYSTEM (\$18,227,00) 15 SYSTEM (\$18,227,00) 16 May 17, SYSTEM (\$18,227,00) 17 May 18, SYSTEM (\$18,227,00) 18 May 17, SYSTEM (\$18,227,00) 19 May 17, SYSTEM (\$18,227,00) 10 May 17, SYSTEM (\$18,227,00) 11 May 17, SYSTEM (\$18,227,00) 12 May 17, SYSTEM (\$18,227,00) 13 May 17, SYSTEM (\$18,227,00) 14 May 17, SYSTEM (\$18,227,00) 15 May 17, SYSTEM (\$18,227,00) 16 March 18, SYSTEM (\$18,227,00) 17 May 18, SYSTEM (\$18,227,00) 18 May 17, SYSTEM (\$18,227,00) 19 May 17, SYSTEM (\$18,227,00) 20 May 18, SYSTEM (\$18,227,00) 20 May 17, SYSTEM (\$18,227,00) 20 May 18, SYSTEM (\$18,227,00) 20 May 17, SYSTEM (\$18,227,00) 21 May 17, SYSTEM (\$18,227,00) 22 May 2, SYSTEM (\$18,227,00) 23 May 17, SYSTEM (\$18,227,00) 24 May 17, SYSTEM (\$18,227,00) 25 May 18, SYSTEM (\$18,227,00) 26 May 18, SYSTEM (\$18,227,00) 27 May 18, SYSTEM (\$18,227,00) 28 May 18, SYSTEM (\$18,227,00) 29 May 18, SYSTEM (\$18,227,00) 20 May 18, SYSTEM (\$18,227,00) 20 May 18, SYSTEM (\$18,227,00) 20 May 18, SYST				Material - Tot	tal				\$0.00	
SPLICE		5015 -	Total						\$0.00	
Total Solid Total Solid Soli		5019		Material		14		SYSTEM	\$2,532.60	Estimate Item Adjustment (0024) due to user hillt5 overridding Payment
Solution Public Properties and Solution Properties and						14		SYSTEM	(\$2,532.60)	
Solid Full Solid Full Solid Full Solid Solid Full Fu					- Total				\$0.00	
FURN & PLACE CONC MATL FOR PULL DEPTH				Material - Tot	tal				\$0.00	
2021 Estimate Item Adjustment (00/22) due to user schlagt overridding Payment Estimate Exception 13 on the current Payment Estimate Exception 15 on the current Payment Estimate Estimate Exception 16 on the current Payment Estimate Estimate Exception 16 on the current Payment Estimate Estimate Estimate Exception 16 on the current Payment Estimate Estimate Estimate Exception 16 on the current Payment Estimate Estimate Exception 30 on the current Payment Estimate Estimate Estimate Exception 30 on the current P		5019 -	Total						\$0.00	
2021 16		5020	CONC MATL FOR	Material		15		SYSTEM	\$18,227.00	Estimate Item Adjustment (0022) due to user schlag1 overridding Payment
Estimate Item Adjustment (0025) due to user kloep)1 overridding Payment Estimate Exception 16 on the current Payment Estimate Exception 16 on the current Payment Estimate Estimate Exception 16 on the current Payment Estimate Estimate Exception 16 on the current Payment Estimate Item Adjustment (0022) due to user kloep)1 overridding Payment Estimate Item Adjustment (0022) due to user kloep)1 overridding Payment Estimate Exception 13 on the current Payment Estimate Estimate Exception 13 on the current Payment Estimate Item Adjustment (0028) due to user kloep)1 overridding Payment Estimate Item Adjustment (0028) due to user kloep)1 overridding Payment Estimate Exception 14 on the current Payment Estimate Exception 14 on the current Payment Estimate Exception 14 on the current Payment Estimate Estimate Item Adjustment (0035) due to user kloep)1 overridding Payment Estimate Exception 14 on the current Payment Estimate Exception 15 on the current Payment Estimate Exception 16 on the current Payment Estimate Exception 16 on the current Payment Estimate Estimate Item Adjustment (0041) due to user hill5 overridding Payment Estimate Exception 16 on the current Payment Estimate Estimate Exception 17 on the current Payment Estimate Exception 18 on the current Payment Estimate Estimate Item Adjustment (0058) due to user hill5 overridding Payment Estimate Exception 30 on the current Payment Estimate Estimate Item Adjustment (0058) due to user hill5 overridding Payment Estimate Exception 30 on the current Payment Estimate Estimate Item Adjustment (0058) due to user hill5 overridding Payment Estimate Exception 30 on the current Payment Estimate.						15		SYSTEM	(\$18,227.00)	
17 Mar 16, SYSTEM \$18,227.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 13 on the current Payment Estimate Payment Estimate Exception 13 on the current Payment Estimate Payment Estimate Exception 13 on the current Payment Estimate Payment Estimate Exception 13 on the current Payment Estimate Payment Estimate Exception 14 on the current Payment Estimate Payment Estimate Exception 14 on the current Payment Estimate Payment Estimate Exception 14 on the current Payment Estimate Payment Estimate Exception 14 on the current Payment Estimate Payment Estimate Exception 14 on the current Payment Estimate Payment Estimate Exception 14 on the current Payment Estimate Payment Estimate Exception 14 on the current Payment Estimate Payment Estimate Exception 14 on the current Payment Estimate Payment						16		SYSTEM	\$18,227.00	Estimate Item Adjustment (0025) due to user kloepj1 overridding Payment
Estimate Item Adjustment (0022) due to user kloep/1 overridding Payment Estimate Exception 13 on the current Payment Estimate. 17						16		SYSTEM	(\$18,227.00)	
2021						17		SYSTEM	\$18,227.00	Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment
Estimate Item Adjustment (0028) due to user kloepj1 overridding Payment Estimate Exception 14 on the current Payment Estimate. 18						17		SYSTEM	(\$18,227.00)	
2021 19						18		SYSTEM	\$18,227.00	Estimate Item Adjustment (0028) due to user kloepj1 overridding Payment
Estimate Item Adjustment (0035) due to user kloepj1 overridding Payment Estimate Exception 14 on the current Payment Estimate. 19						18		SYSTEM	(\$18,227.00)	
20 May 3, 2021 SYSTEM \$18,227.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user hillt5 overridding Payment Estimate Exception 16 on the current Payment Estimate. 20 May 3, 2021 SYSTEM (\$18,227.00) 21 May 17, 2021 SYSTEM \$18,227.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user hillt5 overridding Payment Estimate Exception 30 on the current Payment Estimate. 21 May 17, 2021 SYSTEM (\$18,227.00) 22 Jun 2, 2021 This adjustment offsets the original system-generated Material Payment Estimate Exception 30 on the current Payment Estimate. 23 Jun 2, 2021 This adjustment offsets the original system-generated Material Payment Estimate Exception 33 on the current Payment Estimate Estimate Exception 33 on the current Payment Estimate.						19		SYSTEM	\$18,227.00	Estimate Item Adjustment (0035) due to user kloepj1 overridding Payment
Estimate Item Adjustment (0041) due to user hillt5 overridding Payment Estimate Exception 16 on the current Payment Estimate. 20 May 3, 2021 21 May 17, 2021 22 Jun 2, 2021 Estimate Item Adjustment (0041) due to user hillt5 overridding Payment Estimate Exception 16 on the current Payment Estimate. Estimate Exception 16 on the current Payment Estimate. This adjustment (0058) due to user hillt5 overridding Payment Estimate Exception 30 on the current Payment Estimate. 21 May 17, 2021 Estimate Item Adjustment (0058) due to user hillt5 overridding Payment Estimate Exception 30 on the current Payment Estimate. 22 Jun 2, SYSTEM \$18,227.00 Estimate Item Adjustment (0056) due to user hillt5 overridding Payment Estimate Exception 33 on the current Payment Estimate.						19		SYSTEM	(\$18,227.00)	
2021 May 17, 2021 SYSTEM \$18,227.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user hillt5 overridding Payment Estimate Exception 30 on the current Payment Estimate. May 17, 2021 SYSTEM (\$18,227.00) SYSTEM \$18,227.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0056) due to user hillt5 overridding Payment Estimate Item Adjustment (0056) due to user hillt5 overridding Payment Estimate Exception 33 on the current Payment Estimate. 22 Jun 2, SYSTEM (\$18,227.00)						20		SYSTEM	\$18,227.00	Estimate Item Adjustment (0041) due to user hillt5 overridding Payment
2021 Estimate Item Adjustment (0058) due to user hillt5 overridding Payment Estimate Exception 30 on the current Payment Estimate. 21 May 17, 2021 22 Jun 2, 2021 SYSTEM (\$18,227.00) This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0056) due to user hillt5 overridding Payment Estimate Exception 33 on the current Payment Estimate. 22 Jun 2, SYSTEM (\$18,227.00)						20		SYSTEM	(\$18,227.00)	
2021 22 Jun 2, 2021 \$18,227.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0056) due to user hillt5 overridding Payment Estimate Exception 33 on the current Payment Estimate. 22 Jun 2, SYSTEM (\$18,227.00)						21		SYSTEM	\$18,227.00	Estimate Item Adjustment (0058) due to user hillt5 overridding Payment
2021 Estimate Item Adjustment (0056) due to user hillt5 overridding Payment Estimate Exception 33 on the current Payment Estimate. 22 Jun 2, SYSTEM (\$18,227.00)						21		SYSTEM	(\$18,227.00)	
						22		SYSTEM	\$18,227.00	Estimate Item Adjustment (0056) due to user hillt5 overridding Payment
LVL I						22	Jun 2, 2021	SYSTEM	(\$18,227.00)	



FULL DEPTH	oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
2021 24 3.0 ft, 3	2222	5020	CONC MATL FOR	Material		23		SYSTEM	\$18,227.00	Estimate Item Adjustment (0065) due to user kloepj1 overridding Payment
2021 2021						23		SYSTEM	(\$18,227.00)	
Total						24		SYSTEM	\$18,227.00	Estimate Item Adjustment (0055) due to user herrmt1 overridding Payment
Solid						24		SYSTEM	(\$18,227.00)	
15					- Total				\$0.00	
15				Material - To	tal				\$0.00	
FURN & INSTAL) (TYPE L		5020 -	Total						\$0.00	
10		5021	FURN & INSTAL)	Material		15		SYSTEM	\$696.00	Estimate Item Adjustment (0023) due to user schlag1 overridding Payment
2021 Settimate limit Agustment (0026) due to user Kloepit overridding Payment Estimate Exception 19 on the current Payment Estimate Description 19 on the current Payment Estimate Exception 19 on th						15		SYSTEM	(\$696.00)	
17						16		SYSTEM	\$696.00	Estimate Item Adjustment (0026) due to user kloepj1 overridding Payment
2021						16		SYSTEM	(\$696.00)	
2021 18						17		SYSTEM	\$696.00	Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment
2021 Estimate Item Adjustment (0029) due to user kloep)1 overridding Payment Estimate Exception 16 on the current Payment Estimate.						17		SYSTEM	(\$696.00)	
S021 Total S0.00						18		SYSTEM	\$696.00	Estimate Item Adjustment (0029) due to user kloepj1 overridding Payment
S0.00						18		SYSTEM	(\$696.00)	
South Sout					- Total				\$0.00	
Soze DOWEL BAR (ORILLING, FURNISHING AND INST 15 Feb 16, 2021 SYSTEM \$1,950.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 16 on the current Payment Estimate.				Material - To					\$0.00	
CRILLING, FURNISHING AND 15		5021 -	Total						\$0.00	
15		5022	(DRILLING, FURNISHING AND	Material		15		SYSTEM	\$1,950.00	Estimate Item Adjustment (0024) due to user schlag1 overridding Payment
Sewer Rigid Restinate			INST			15		SYSTEM	(\$1,950.00)	
Total \$0.00						16		SYSTEM	\$1,950.00	Estimate Item Adjustment (0027) due to user kloepj1 overridding Payment
Solution Solution						16		SYSTEM	(\$1,950.00)	
Source Sewer - Rigid Sew					- Total				\$0.00	
SEWER - RIGID PIPE Material PIPE Noveridding Payment Estimate Exception 53 on the current Payment Estimate. Material PIPE PIPE Material PIPE Noveridding Payment PIPE PIPE PIPE Noveridding Payment PIPE PIPE PIPE PIPE PIPE PIPE PIPE PIP				Material - To	tal				\$0.00	
PIPE 2021 Estimate Item Adjustment (0030) due to user kloepj1 overridding Payment Estimate Exception 53 on the current Payment Estimate. 18		5022 -	Total						\$0.00	
2021 19 Apr 16, 2021 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user kloepj1 overridding Payment Estimate Exception 61 on the current Payment Estimate. 19 Apr 16, 2021 Apr 16, 2021 This adjustment offsets the original system-generated Material Payment Estimate Exception 61 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user hillt5 overridding Payment Estimate Exception 86 on the current Payment Estimate. 20 May 3, SYSTEM (\$147,772.00)		5025		Material		18		SYSTEM	\$99,643.00	Estimate Item Adjustment (0030) due to user kloepj1 overridding Payment
2021 Estimate Item Adjustment (0036) due to user kloepj1 overridding Payment Estimate Exception 61 on the current Payment Estimate. 19 Apr 16, 2021 20 May 3, 2021 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user hillt5 overridding Payment Estimate Item Adjustment (0042) due to user hillt5 overridding Payment Estimate Exception 86 on the current Payment Estimate. 20 May 3, SYSTEM (\$147,772.00)						18		SYSTEM	(\$99,643.00)	
2021 SYSTEM \$147,772.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user hillt5 overridding Payment Estimate Exception 86 on the current Payment Estimate. 20 May 3, SYSTEM (\$147,772.00)						19		SYSTEM	\$147,772.00	Estimate Item Adjustment (0036) due to user kloepj1 overridding Payment
2021 Estimate Item Adjustment (0042) due to user hillt5 overridding Payment Estimate Exception 86 on the current Payment Estimate. 20 May 3, SYSTEM (\$147,772.00)						19		SYSTEM	(\$147,772.00)	
						20		SYSTEM	\$147,772.00	Estimate Item Adjustment (0042) due to user hillt5 overridding Payment
						20		SYSTEM	(\$147,772.00)	
21 May 17, SYSTEM \$147,772.00 This adjustment offsets the original system-generated Material Payment						21	May 17,	SYSTEM	\$147,772.00	This adjustment offsets the original system-generated Material Payment



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J6I2222	5025	SEWER - RIGID PIPE	Material			2021			Estimate Item Adjustment (0059) due to user hillt5 overridding Payment Estimate Exception 106 on the current Payment Estimate.	
					21	May 17, 2021	SYSTEM	(\$147,772.00)		
					22	Jun 2, 2021	SYSTEM	\$147,772.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0057) due to user hillt5 overridding Payment Estimate Exception 116 on the current Payment Estimate.	
					22	Jun 2, 2021	SYSTEM	(\$147,772.00)		
					23	Jun 16, 2021	SYSTEM	\$147,772.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0066) due to user kloepj1 overridding Payment Estimate Exception 115 on the current Payment Estimate.	
					23	Jun 16, 2021	SYSTEM	(\$147,772.00)		
					24	Jul 1, 2021	SYSTEM	\$147,772.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0056) due to user herrmt1 overridding Payment Estimate Exception 76 on the current Payment Estimate.	
					24	Jul 1, 2021	SYSTEM	(\$147,772.00)		
					25	Jul 16, 2021	SYSTEM	\$147,772.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0066) due to user kloepj1 overridding Payment Estimate Exception 68 on the current Payment Estimate.	
					25	Jul 16, 2021	SYSTEM	(\$147,772.00)		
						26	Aug 2, 2021	SYSTEM	\$147,772.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user hillt5 overridding Payment Estimate Exception 73 on the current Payment Estimate.
					26	Aug 2, 2021	SYSTEM	(\$147,772.00)		
					27	Aug 16, 2021	SYSTEM	\$147,772.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0054) due to user herrmt1 overridding Payment Estimate Exception 69 on the current Payment Estimate.	
					27	Aug 16, 2021	SYSTEM	(\$147,772.00)		
						28	Sep 2, 2021	SYSTEM	\$147,772.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0077) due to user kloepj1 overridding Payment Estimate Exception 73 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$147,772.00)		
								\$0.00		
				- Total				Ψ0.00		
			Material - To					\$0.00		
	5025 -									
	5025 - 5026	Total CLASS B-1 CONCRETE (SUBSTR)			20	May 3, 2021	SYSTEM	\$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user hillt5 overridding Payment Estimate Exception 38 on the current Payment Estimate.	
		CLASS B-1 CONCRETE			20			\$0.00 \$0.00	Estimate Item Adjustment (0043) due to user hillt5 overridding Payment	
		CLASS B-1 CONCRETE				2021 May 3,		\$0.00 \$0.00 \$140,119.20	Estimate Item Adjustment (0043) due to user hillt5 overridding Payment	
		CLASS B-1 CONCRETE			20	2021 May 3, 2021 May 17,	SYSTEM	\$0.00 \$0.00 \$140,119.20 (\$140,119.20)	Estimate Item Adjustment (0043) due to user hillt5 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user hillt5 overridding Payment	
		CLASS B-1 CONCRETE			20	2021 May 3, 2021 May 17, 2021	SYSTEM	\$0.00 \$0.00 \$140,119.20 (\$140,119.20) \$140,119.20	Estimate Item Adjustment (0043) due to user hillt5 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user hillt5 overridding Payment	
		CLASS B-1 CONCRETE			20 21 21	2021 May 3, 2021 May 17, 2021 May 17, 2021 Jun 2,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$140,119.20 (\$140,119.20) \$140,119.20 (\$140,119.20)	Estimate Item Adjustment (0043) due to user hillt5 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user hillt5 overridding Payment Estimate Exception 58 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user hillt5 overridding Payment	
		CLASS B-1 CONCRETE			20 21 21 22	2021 May 3, 2021 May 17, 2021 May 17, 2021 Jun 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$140,119.20 (\$140,119.20) \$140,119.20 (\$140,119.20) \$140,119.20	Estimate Item Adjustment (0043) due to user hillt5 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user hillt5 overridding Payment Estimate Exception 58 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user hillt5 overridding Payment	
		CLASS B-1 CONCRETE			20 21 21 22 22	2021 May 3, 2021 May 17, 2021 May 17, 2021 Jun 2, 2021 Jun 2, 2021 Jun 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$140,119.20 (\$140,119.20) \$140,119.20 (\$140,119.20) \$140,119.20	Estimate Item Adjustment (0043) due to user hillt5 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user hillt5 overridding Payment Estimate Exception 58 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user hillt5 overridding Payment Estimate Exception 70 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0067) due to user kloepj1 overridding Payment Estimate Item Adjustment (0067) due to user kloepj1 overridding Payment	
		CLASS B-1 CONCRETE			20 21 21 22 22 23	2021 May 3, 2021 May 17, 2021 May 17, 2021 Jun 2, 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 201	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$140,119.20 (\$140,119.20) \$140,119.20 (\$140,119.20) \$140,119.20 (\$140,119.20)	Estimate Item Adjustment (0043) due to user hillt5 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user hillt5 overridding Payment Estimate Exception 58 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user hillt5 overridding Payment Estimate Exception 70 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0067) due to user kloepj1 overridding Payment Estimate Item Adjustment (0067) due to user kloepj1 overridding Payment	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	5026	CLASS B-1 CONCRETE (SUBSTR)	Material		25	Jul 16, 2021	SYSTEM	\$140,119.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0067) due to user kloepj1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$140,119.20)	
					26	Aug 2, 2021	SYSTEM	\$140,119.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0061) due to user hillt5 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					26	Aug 2, 2021	SYSTEM	(\$140,119.20)	
					27	Aug 16, 2021	SYSTEM	\$140,119.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0055) due to user herrmt1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$140,119.20)	
					28	Sep 2, 2021	SYSTEM	\$140,119.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0078) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$140,119.20)	
				- Total				\$0.00	
			Material - Tot	ial				\$0.00	
	5026 -							\$0.00	
	5029	SLAB ON CONCRETE NU- GIRDER	Material		26	Aug 2, 2021	SYSTEM	\$69,426.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0062) due to user hillt5 overridding Payment Estimate Exception 43 on the current Payment Estimate.
					26	Aug 2, 2021	SYSTEM	(\$69,426.00)	
					27	Aug 16, 2021	SYSTEM	\$121,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0057) due to user herrmt1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$121,800.00)	
					28	Sep 2, 2021	SYSTEM	\$231,826.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0080) due to user kloepj1 overridding Payment Estimate Exception 35 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$231,826.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	5029 -		Construction 20 May 2 2VOTE					\$0.00	
	5034	MISC. FENCING	Construction Stockpile STMI		20	May 3, 2021	SYSTEM	\$32,885.60	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$32,885.60	
			Construction	Stockpile S	MI - Total			\$32,885.60	
	5037	REINFORCING STEEL (EPOXY COATED)	Material		20	May 3, 2021	SYSTEM	\$32,885.60 \$37.06	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user hillt5 overridding Payment Estimate Exception 66 on the current Payment Estimate.
					20	May 3, 2021	SYSTEM	(\$37.06)	Estimate Exception of the current Payment Estimate.
					21	May 17, 2021	SYSTEM	\$37,068.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0061) due to user hillt5 overridding Payment Estimate Exception 86 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$37,068.50)	
					22	Jun 2, 2021	SYSTEM	\$37,068.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0059) due to user hillt5 overridding Payment Estimate Exception 101 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$37,068.50)	
					23	Jun 16, 2021	SYSTEM	\$37,068.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0068) due to user kloepj1 overridding Payment Estimate Exception 101 on the current Payment Estimate.
					23	Jun 16,	SYSTEM	(\$37,068.50)	



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
22	5037	REINFORCING STEEL (EPOXY	Material			2021			
		COATED)			24	Jul 1, 2021	SYSTEM	\$37,068.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user herrmt1 overridding Payment Estimate Exception 63 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$37,068.50)	
					25	Jul 16, 2021	SYSTEM	\$37,068.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0068) due to user kloepj1 overridding Payment Estimate Exception 56 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$37,068.50)	
					27	Aug 16, 2021	SYSTEM	\$37,068.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0056) due to user herrmt1 overridding Payment Estimate Exception 57 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$37,068.50)	
					28	Sep 2, 2021	SYSTEM	\$37,068.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0079) due to user kloepj1 overridding Payment Estimate Exception 58 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$37,068.50)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	5037 -	Total						\$0.00	
	5038	PROTECTIVE COATING - CONCRETE BENTS AND	Material		28	Sep 2, 2021	SYSTEM	\$13,118.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0081) due to user kloepj1 overridding Payment Estimate Exception 61 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$13,118.70)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	5038 -	Total						\$0.00	
	5044	SLOPE PROTECTION	Material		27	Aug 16, 2021	SYSTEM	\$73,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user herrmt1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$73,440.00)	
					28	Sep 2,	SYSTEM	\$73,440.00	
						2021		\$73,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0082) due to user kloepj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					28	2021 Sep 2, 2021	SYSTEM	(\$73,440.00)	Estimate Item Adjustment (0082) due to user kloepj1 overridding Payment
				- Total	28	Sep 2,	SYSTEM		Estimate Item Adjustment (0082) due to user kloepj1 overridding Payment
			Material - To		28	Sep 2,	SYSTEM	(\$73,440.00)	Estimate Item Adjustment (0082) due to user kloepj1 overridding Payment
	5044 -	Total	Material - To		28	Sep 2,	SYSTEM	(\$73,440.00)	Estimate Item Adjustment (0082) due to user kloepj1 overridding Payment
	5044 - 5047	Total 15 IN. PIPE CULVERT GROUP C			28	Sep 2,	SYSTEM	(\$73,440.00) \$0.00 \$0.00	Estimate Item Adjustment (0082) due to user kloepj1 overridding Payment
		15 IN. PIPE				Sep 2, 2021		(\$73,440.00) \$0.00 \$0.00 \$0.00	Estimate Item Adjustment (0082) due to user kloepj1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0069) due to user kloepj1 overridding Payment
		15 IN. PIPE			25	Sep 2, 2021 Jul 16, 2021 Jul 16,	SYSTEM	(\$73,440.00) \$0.00 \$0.00 \$0.00 \$6,160.00	Estimate Item Adjustment (0082) due to user kloepj1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0069) due to user kloepj1 overridding Payment
		15 IN. PIPE			25	Sep 2, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2,	SYSTEM SYSTEM	(\$73,440.00) \$0.00 \$0.00 \$0.00 \$6,160.00 (\$6,160.00)	Estimate Item Adjustment (0082) due to user kloepj1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0069) due to user kloepj1 overridding Payment Estimate Exception 67 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0063) due to user hillt5 overridding Payment Estimate Item Adjustment (0063) due to user hillt5 overridding Payment
		15 IN. PIPE			25 25 26	Sep 2, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021	SYSTEM SYSTEM SYSTEM	(\$73,440.00) \$0.00 \$0.00 \$0.00 \$6,160.00 (\$6,160.00) \$6,160.00	Estimate Item Adjustment (0082) due to user kloepj1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0069) due to user kloepj1 overridding Payment Estimate Exception 67 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0063) due to user hillt5 overridding Payment Estimate Item Adjustment (0063) due to user hillt5 overridding Payment
		15 IN. PIPE			25 25 26 26	Sep 2, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16,	SYSTEM SYSTEM SYSTEM	(\$73,440.00) \$0.00 \$0.00 \$0.00 \$6,160.00 (\$6,160.00) (\$6,160.00)	Estimate Item Adjustment (0082) due to user kloepj1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0069) due to user kloepj1 overridding Payment Estimate Exception 67 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0063) due to user hillt5 overridding Payment Estimate Exception 72 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 72 on the current Payment Estimate.
		15 IN. PIPE			25 25 26 26 27	Sep 2, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	(\$73,440.00) \$0.00 \$0.00 \$0.00 \$6,160.00 (\$6,160.00) \$6,160.00 (\$6,160.00)	Estimate Item Adjustment (0082) due to user kloepj1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0069) due to user kloepj1 overridding Payment Estimate Exception 67 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0063) due to user hillt5 overridding Payment Estimate Exception 72 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 72 on the current Payment Estimate.

Sep 4, 2021



Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	5047	15 IN. PIPE	Material	- Total					
		CULVERT GROUP C	Material - To	tal				\$0.00	
	5047 -	Total						\$0.00	
	5048	18 IN. PIPE CULVERT GROUP C	Material		28	Sep 2, 2021	SYSTEM	\$7,920.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0084) due to user kloepj1 overridding Payment Estimate Exception 72 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$7,920.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	5048 -	Total						\$0.00	
	5049	18 IN. GROUP A FLARED END SECT	Material		25	Jul 16, 2021	SYSTEM	\$1,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0070) due to user kloepj1 overridding Payment Estimate Exception 72 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$1,800.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	5049 -	Total						\$0.00	
J6I2222 -	2 - Total							\$348,708.98	
Overall -	Overall - Total								