

Pay Estimate Created Date: September 16, 2021

Progress Estimate Number	Contract ID	200515-F15	Pay Period Start September 2, 2021	Original Contract Amount	\$24,269,745.00
29	Prime Contracto	r KCI Construction Compan	y Pay Period End September 15, 2021		
				Current Contract Amount	\$25,158,302.99

Approval Date		By User
September 16, 2021	Generated and Approved (and should be considered Draft) at the Project Office Level by	kloepj1
September 17, 2021	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	washas
September 17, 2021	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
June 1, 2022	June 1, 2022		68.63%

	Contract Informational Dates								
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract						
Acceptance Date									
Awarded Date	June 3, 2020	June 3, 2020							
Letting Date	May 15, 2020	May 15, 2020							
Notice to Proceed Date	July 6, 2020	July 6, 2020							
Open to Traffic Date									
Work Began Date									

Contract Total Pay For Estimate No. 29									
		This Estimate	Previous	To Date					
200515-F15									
	Total Posted Items Pay	\$519,278.59	\$16,747,314.22	\$17,266,592.81					
	Gross Item Adjustments	\$38,774.68	\$348,708.98	\$387,483.66					
	Incentive	\$0.00	\$0.00	\$0.00					
	Disincentive	\$0.00	\$0.00	\$0.00					
	Liquidated Damage	\$0.00	\$0.00	\$0.00					
	Other Contract Adjustments	\$0.00	\$9,819.50	\$9,819.50					
	,		\$17,105,842.70	\$17,663,895.97					
Contract Total Pa	avable This Estimate:	\$558.053.27							

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6I2222	0020	2022010	REMOVAL OF IMPROVEMENTS	LS	\$600,000.000	0.05	\$30,000.00
	0120	2063000	CLASS 3 EXCAVATION	CUYD	\$15.000	344	\$5,160.00
	0220	5041000	CONCRETE APPROACH PAVEMENT	SQYD	\$150.000	33.5	\$5,025.00
	0240	6039901	WATER	LS	\$12,000.000	1	\$12,000.00
	0380	6071102	MODIFIED CONCRETE GUTTER TYPE B	LF	\$34.000	307	\$10,438.00
	0460	6091042	CONCRETE GUTTER TYPE B	LF	\$30.000	127	\$3,810.00
	0620	6141024	GRATE AND BEARING PLATE (5 FT. X 3 FT. OR 1524 MM X 914 MM)	EA	\$1,400.000	2	\$2,800.00
	0640	6149902	MISC.Parallel Grate and Bearing Plate (2 FT.x2FT.)	EA	\$700.000	2	\$1,400.00
	0730	6179903	MISC.MODIFIED BARRIER WALL	LF	\$300.000	60	\$18,000.00
	1000	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	LS	\$125,000.000	0.1	\$12,500.00
	1110	7261015	15 IN. PIPE GROUP A	LF	\$70.000	487	\$34,090.00
	1120	7261018	18 IN. PIPE GROUP A	LF	\$80.000	190	\$15,200.00
	1170	7311022	PRECAST CONCRETE DROP INLET 2 FT X 2 FT	FT	\$350.000	11	\$3,850.00
	1180	7311042	PRECAST CONCRETE DROP INLET 4 FT X 2 FT	FT	\$450.000	22	\$9,900.00
	1190	7311053	PRECAST CONCRETE DROP INLET 5 FT X 3 FT	FT	\$650.000	4	\$2,600.00
	1310	8061016	SEDIMENT REMOVAL	CUYD	\$25.000	35	\$875.00
	1490	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	SQYD	\$6.500	1,361	\$8,846.50

Revision 4/1/2020 Page 1 of 108



Pay Estimate Created Date: September 16, 2021

Progress Estimate Number
29 Contract ID 200515-F15 Pay Period Start September 2, 2021 Original Contract Amount \$24,269,745.00
Prime Contractor KCI Construction Company Pay Period End September 15, 2021 Net Change Order Amount \$888,557.99
Current Contract Amount \$25,158,302.99

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6I2222	1510	5021309	CONCRETE PAVEMENT (9 IN. NON-REINFORCED 15 FT. JOINTS)	SQYD	\$54.000	1,361	\$73,494.00
	1650	9013002	CONDUIT, 2 IN. RIGID, IN TRENCH	LF	\$10.450	435	\$4,545.75
	1700	9015020	TRENCHING TYPE II	LF	\$3.800	460	\$1,748.00
	1850	9019903	MISC.THHN CABLE 2C #6 AWG	LF	\$1.650	1,420	\$2,343.00
	1860	9020213	SIGNAL HEAD, TYPE 3S	EA	\$761.000	1	\$761.00
	1870	9020513	SIGNAL HEAD, TYPE 3B	EA	\$927.000	8	\$7,416.00
	1910	9022708	POST, SIGNAL 8 FT. OR 2.4 M	EA	\$645.000	1	\$645.00
	1920	9022715	POST, SIGNAL 15 FT. OR 4.6 M	EA	\$972.000	1	\$972.00
	1950	9023250	POST, TYPE C, 50 FT. ARM OR 15.2 M ARM	EA	\$10,292.000	1	\$10,292.00
	1960	9023255	POST, TYPE C, 55 FT. ARM	EA	\$11,930.000	1	\$11,930.00
	1990	9024283	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	EA	\$13,359.000	0.12	\$1,603.08
	2000	9024975	VIDEO DETECTION SYSTEM	EA	\$12,698.000	0.8	\$10,158.40
	2040	9028308	CABLE, 16 AWG 2 CONDUCTOR	LF	\$0.500	1,870	\$935.00
	2050	9028310	CABLE, 16 AWG 5 CONDUCTOR	LF	\$1.100	1,930	\$2,123.00
	2060	9028311	CABLE, 16 AWG 7 CONDUCTOR	LF	\$1.600	2,464	\$3,942.4
	2160	9029902	MISC.Countdown Pedestrian Signal Head, Type 1S	EA	\$450.000	10	\$4,500.0
	2640	5031010A	BRIDGE APPROACH SLAB (MAJOR ROAD)	SQYD	\$355.000	59	\$20,945.0
	2720	7049904	MISC.BARRIER CURB REPAIR (UNFORMED	SQFT	\$175.000	19	\$3,325.00
	2930	7033009	AESTHETIC CONCRETE STAIN	LS	\$14,877.000	1	\$14,877.0
	3380	7151001	VERTICAL DRAIN AT END BENTS	EA	\$2,500.000	2	\$5,000.00
	3460	2160500	REMOVAL OF BRIDGES	LS	\$655,000.000	0.1	\$65,500.00
	5002	6141121	CURVED VANE GRATE AND FRAME (4 FT. X 2 FT. OR 1200MM X 600MM)	EA	\$1,400.000	7	\$9,800.00
	5008	6149902	MISC.MISC. MSD Manhole Frame and Cover	EA	\$400.000	2	\$800.00
	5029	7034221	SLAB ON CONCRETE NU-GIRDER	SQYD	\$406.000	191	\$77,546.0
	5032	7071000	CONDUIT SYSTEM ON STRUCTURE	LS	\$9,965.000	0.48	\$4,783.20
	5065	2022010	REMOVAL OF IMPROVEMENTS	LS	\$2,799.260	1	\$2,799.20
Project J6I2	222 - Total						\$519,278.59
Overall - To	tal						\$519,278.59

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item	Adjust	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6I2222	0060	COMPACTING EMBANKMENT	Material			-83,852	\$3.00	(\$251,556.00)
	0060	COMPACTING EMBANKMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	83,852	\$3.00	\$251,556.00
	0160	GRAVEL (A) OR CRUSHED STONE (B)	Material			-888	\$12.00	(\$10,656.00)
	0160	GRAVEL (A) OR CRUSHED STONE (B)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user kloepj1	888	\$12.00	\$10,656.00

Revision 4/1/2020 Page 2 of 108



Pay Estimate Created Date: September 16, 2021

Progress Estimate Number
29 Contract ID 200515-F15 Pay Period Start September 2, 2021 Original Contract Amount \$24,269,745.00
Prime Contractor KCI Construction Company Pay Period End September 15, 2021 Net Change Order Amount \$888,557.99
Current Contract Amount \$25,158,302.99

ect per	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
22					overridding Payment Estimate Exception 3 on the current Payment Estimate.			
	0220	CONCRETE APPROACH PAVEMENT	Material			-33.5	\$150.00	(\$5,025.00
	0220	CONCRETE APPROACH PAVEMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	33.5	\$150.00	\$5,025.00
	0240	WATER	Material			-1	\$12,000.00	(\$12,000.00
	0240	WATER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user kloepj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	1	\$12,000.00	\$12,000.0
	0410	PAVED APPROACH, 8 IN.	Material			-72.3	\$125.00	(\$9,037.5)
	0410	PAVED APPROACH, 8 IN.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.	72.3	\$125.00	\$9,037.5
	0460	CONCRETE GUTTER TYPE B	Material			-395	\$30.00	(\$11,850.00
	0460	CONCRETE GUTTER TYPE B	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.	395	\$30.00	\$11,850.00
(0490	FURNISHING TYPE 2 ROCK DITCH LINER	Material			-210.5	\$100.00	(\$21,050.0
	0490	FURNISHING TYPE 2 ROCK DITCH LINER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.	210.5	\$100.00	\$21,050.00
	0675	CONCRETE TRAFFIC BARRIER, TYPE C	Material			-485	\$145.00	(\$70,325.0
	0675	CONCRETE TRAFFIC BARRIER, TYPE C	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 27 on the current Payment Estimate.	485	\$145.00	\$70,325.0
	0730	MISC.	Material			-60	\$300.00	(\$18,000.0
	0730	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.	60	\$300.00	\$18,000.0
	0990	MISC.	Material			-2,401	\$15.50	(\$37,215.5
	0990	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.	2,401	\$15.50	\$37,215.5
	1050	MISC.	Material			-952	\$25.00	(\$23,800.0
	1050	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 40	952	\$25.00	\$23,800.00

Revision 4/1/2020 Page 3 of 108



Pay Estimate Created Date: September 16, 2021

Progress Estimate Number
29 Contract ID 200515-F15 Pay Period Start September 2, 2021 Original Contract Amount \$24,269,745.00
Prime Contractor KCI Construction Company Pay Period End September 15, 2021 Net Change Order Amount \$888,557.99
Current Contract Amount \$25,158,302.99

ct	Line	Item Description	Adjustment	Other Item	Comments	Adjustment	Line Item	Adjustment
er	No.		Туре	Adjustment Type		Quantity	Adjustment Unit Price	amount
22					on the current Payment Estimate.			
	1060	AESTHETIC CONCRETE STAIN	Material			-1	\$6,110.88	(\$6,110.88
	1060	AESTHETIC CONCRETE STAIN	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 41 on the current Payment Estimate.	1	\$6,110.88	\$6,110.88
	1190	PRECAST CONCRETE DROP INLET 5 FT X 3 FT	Material			-59	\$650.00	(\$38,350.00
	1190	PRECAST CONCRETE DROP INLET 5 FT X 3 FT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user kloepj1 overridding Payment Estimate Exception 90 on the current Payment Estimate.	59	\$650.00	\$38,350.00
	1490	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	1,361	\$0.30	\$406.94
	1490	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material			-9,505.722	\$6.50	(\$61,787.19
	1490	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user kloepj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	9,505.722	\$6.50	\$61,787.19
	1500	CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. JOINTS)	Material			-5,208.6	\$51.00	(\$265,638.6
	1500	CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. JOINTS)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0049) due to user kloepj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	5,208.6	\$51.00	\$265,638.60
	1510	CONCRETE PAVEMENT (9 IN. NON-REINFORCED 15 FT. JOINTS)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	1,361	\$0.86	\$1,167.7
	1520	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	Material			-210	\$15.00	(\$3,150.00
	1520	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0051) due to user kloepj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.	210	\$15.00	\$3,150.00
	1550	TYPE A2 SHOULDER	Material			-39.6	\$35.00	(\$1,386.00
	1550	TYPE A2 SHOULDER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0052) due to user kloepj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	39.6	\$35.00	\$1,386.0
	1570	MGS GUARDRAIL	Material			-463	\$19.00	(\$8,797.00
	1570	MGS GUARDRAIL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.	463	\$19.00	\$8,797.00
	1730	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	Material			-360	\$0.55	(\$198.00
	1730	CABLE, 10 AWG 1	Material		This adjustment offsets the original system-	360	\$0.55	\$198.00

Revision 4/1/2020 Page 4 of 108



Pay Estimate Created Date: September 16, 2021

Progress Estimate Number
29 Contract ID 200515-F15 Pay Period Start September 2, 2021 Original Contract Amount \$24,269,745.00
Prime Contractor KCI Construction Company Pay Period End September 15, 2021 Net Change Order Amount \$888,557.99
Current Contract Amount \$25,158,302.99

	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
222		CONDUCTOR, POLE AND BRACKET			generated Material Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 91 on the current Payment Estimate.			
1	1740	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 2 AWG	Material			-800	\$6.00	(\$4,800.00
1	1740	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 2 AWG	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 92 on the current Payment Estimate.	800	\$6.00	\$4,800.00
1	1750	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 6 AWG	Material			-336	\$3.60	(\$1,209.60
1	1750	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 6 AWG	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 93 on the current Payment Estimate.	336	\$3.60	\$1,209.60
1	1760	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	Material			-310	\$2.90	(\$899.00
1	1760	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment Estimate Exception 94 on the current Payment Estimate.	310	\$2.90	\$899.00
1	1770	POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	Material			-4	\$1,068.00	(\$4,272.00
1	1770	POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment Estimate Exception 95 on the current Payment Estimate.	4	\$1,068.00	\$4,272.00
1	1780	MISC.	Material			-1	\$16,605.00	(\$16,605.00
1	1780	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment Estimate Exception 97 on the current Payment Estimate.	1	\$16,605.00	\$16,605.00
1	1800	MISC.	Material			-4	\$2,250.00	(\$9,000.00
1	1800	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0025) due to user kloepj1 overridding Payment Estimate Exception 99 on the current Payment Estimate.	4	\$2,250.00	\$9,000.00
1	1820	MISC.	Material			-0.33	\$7,258.00	(\$2,395.14
1	1820	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0026) due to user kloepj1 overridding Payment Estimate Exception 100 on the current Payment Estimate.	0.33	\$7,258.00	\$2,395.14
1	1830	MISC.	Material			-4	\$572.00	(\$2,288.00
1	1830	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0024) due to user kloepj1 overridding Payment Estimate Exception 98 on the current Payment Estimate.	4	\$572.00	\$2,288.00

Revision 4/1/2020 Page 5 of 108



Pay Estimate Created Date: September 16, 2021

Progress Estimate Number
29 Contract ID 200515-F15 Pay Period Start September 2, 2021 Original Contract Amount \$24,269,745.00
Prime Contractor KCI Construction Company Pay Period End September 15, 2021 Net Change Order Amount \$888,557.99
Current Contract Amount \$25,158,302.99

	ine No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
2 1	850	MISC.	Material			-1,420	\$1.65	(\$2,343.00
1	850	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 103 on the current Payment Estimate.	1,420	\$1.65	\$2,343.00
18	860	SIGNAL HEAD, TYPE 3S	Material			-1	\$761.00	(\$761.00
1	860	SIGNAL HEAD, TYPE 3S	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0027) due to user kloepj1 overridding Payment Estimate Exception 104 on the current Payment Estimate.	1	\$761.00	\$761.00
18	870	SIGNAL HEAD, TYPE 3B	Material			-13	\$927.00	(\$12,051.00
1	870	SIGNAL HEAD, TYPE 3B	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0028) due to user kloepj1 overridding Payment Estimate Exception 105 on the current Payment Estimate.	13	\$927.00	\$12,051.00
19	910	POST, SIGNAL 8 FT. OR 2.4 M	Material			-4	\$645.00	(\$2,580.00)
19	910	POST, SIGNAL 8 FT. OR 2.4 M	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0029) due to user kloepj1 overridding Payment Estimate Exception 106 on the current Payment Estimate.	4	\$645.00	\$2,580.00
1	920	POST, SIGNAL 15 FT. OR 4.6 M	Material			-1	\$972.00	(\$972.00)
19	920	POST, SIGNAL 15 FT. OR 4.6 M	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0030) due to user kloepj1 overridding Payment Estimate Exception 109 on the current Payment Estimate.	1	\$972.00	\$972.00
1	950	POST, TYPE C, 50 FT. ARM OR 15.2 M ARM	Material			-1	\$10,292.00	(\$10,292.00)
19	950	POST, TYPE C, 50 FT. ARM OR 15.2 M ARM	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0031) due to user kloepj1 overridding Payment Estimate Exception 112 on the current Payment Estimate.	1	\$10,292.00	\$10,292.00
1	960	POST, TYPE C, 55 FT. ARM	Material			-2	\$11,930.00	(\$23,860.00)
1	960	POST, TYPE C, 55 FT. ARM	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0032) due to user kloepj1 overridding Payment Estimate Exception 113 on the current Payment Estimate.	2	\$11,930.00	\$23,860.00
1	990	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	Material			-1.12	\$13,359.00	(\$14,962.08)
1	990	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0033) due to user kloepj1 overridding Payment Estimate Exception 114 on the current Payment Estimate.	1.12	\$13,359.00	\$14,962.08
2	000	VIDEO DETECTION SYSTEM	Material			-0.8	\$12,698.00	(\$10,158.40)
2	000	VIDEO DETECTION SYSTEM	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0034) due to user kloepj1 overridding Payment Estimate Exception 115	0.8	\$12,698.00	\$10,158.40

Revision 4/1/2020 Page 6 of 108



Pay Estimate Created Date: September 16, 2021

Progress Estimate Number
29 Contract ID 200515-F15 Pay Period Start September 2, 2021 Original Contract Amount \$24,269,745.00
Prime Contractor KCI Construction Company Pay Period End September 15, 2021 Net Change Order Amount \$888,557.99
Current Contract Amount \$25,158,302.99

ect	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
22					on the current Payment Estimate.			
	2040	CABLE, 16 AWG 2 CONDUCTOR	Material			-1,870	\$0.50	(\$935.00
	2040	CABLE, 16 AWG 2 CONDUCTOR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0035) due to user kloepj1 overridding Payment Estimate Exception 116 on the current Payment Estimate.	1,870	\$0.50	\$935.00
	2050	CABLE, 16 AWG 5 CONDUCTOR	Material			-1,930	\$1.10	(\$2,123.00
	2050	CABLE, 16 AWG 5 CONDUCTOR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0036) due to user kloepj1 overridding Payment Estimate Exception 117 on the current Payment Estimate.	1,930	\$1.10	\$2,123.00
	2060	CABLE, 16 AWG 7 CONDUCTOR	Material			-3,640	\$1.60	(\$5,824.00
	2060	CABLE, 16 AWG 7 CONDUCTOR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0037) due to user kloepj1 overridding Payment Estimate Exception 118 on the current Payment Estimate.	3,640	\$1.60	\$5,824.00
	2100	BASE, CONCRETE	Material			-10.3	\$1,160.00	(\$11,948.00
	2100	BASE, CONCRETE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0038) due to user kloepj1 overridding Payment Estimate Exception 119 on the current Payment Estimate.	10.3	\$1,160.00	\$11,948.00
	2160	MISC.	Material			-10	\$450.00	(\$4,500.00)
	2160	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0039) due to user kloepj1 overridding Payment Estimate Exception 120 on the current Payment Estimate.	10	\$450.00	\$4,500.00
	2210	CONCRETE FOOTINGS, BOLT DOWN	Material			-56.32	\$1,200.00	(\$67,584.00)
	2210	CONCRETE FOOTINGS, BOLT DOWN	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0046) due to user kloepj1 overridding Payment Estimate Exception 121 on the current Payment Estimate.	56.32	\$1,200.00	\$67,584.00
	2330	MISC.	Material			-1	\$66,000.00	(\$66,000.00)
	2330	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0047) due to user kloepj1 overridding Payment Estimate Exception 122 on the current Payment Estimate.	1	\$66,000.00	\$66,000.00
	2340	MISC.	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			\$37,200.00
	2640	BRIDGE APPROACH SLAB (MAJOR ROAD)	Material			-59	\$355.00	(\$20,945.00)
	2640	BRIDGE APPROACH SLAB (MAJOR ROAD)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0053) due to user kloepj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	59	\$355.00	\$20,945.00
	2670	SLAB ON STEEL	Material			-214	\$470.00	(\$100,580.00)
	2670	SLAB ON STEEL	Material		This adjustment offsets the original system-	214	\$470.00	\$100,580.00

Revision 4/1/2020 Page 7 of 108



Pay Estimate Created Date: September 16, 2021

Progress Estimate Number
29 Contract ID 200515-F15 Pay Period Start September 2, 2021 Original Contract Amount \$24,269,745.00
Prime Contractor KCI Construction Company Pay Period End September 15, 2021 Net Change Order Amount \$888,557.99
Current Contract Amount \$25,158,302.99

ect per	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
22					generated Material Payment Estimate Item Adjustment (0054) due to user kloepj1 overridding Payment Estimate Exception 47 on the current Payment Estimate.			
	2690	CORRAL CURB	Material			-142	\$117.00	(\$16,614.00
	2690	CORRAL CURB	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0055) due to user kloepj1 overridding Payment Estimate Exception 55 on the current Payment Estimate.	142	\$117.00	\$16,614.00
	2700	SUPERSTRUCTURE REPAIR (UNFORMED)	Material			-820	\$158.00	(\$129,560.00
	2700	SUPERSTRUCTURE REPAIR (UNFORMED)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0056) due to user kloepj1 overridding Payment Estimate Exception 57 on the current Payment Estimate.	820	\$158.00	\$129,560.00
	2720	MISC.	Material			-167	\$175.00	(\$29,225.00
	2720	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0057) due to user kloepj1 overridding Payment Estimate Exception 63 on the current Payment Estimate.	167	\$175.00	\$29,225.00
	2730	REINFORCING STEEL (EPOXY COATED)	Material			-850	\$3.00	(\$2,550.00
	2730	REINFORCING STEEL (EPOXY COATED)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0058) due to user kloepj1 overridding Payment Estimate Exception 69 on the current Payment Estimate.	850	\$3.00	\$2,550.00
	2810	SUPERSTRUCTURE REPAIR (UNFORMED)	Material			-2,369	\$158.00	(\$374,302.00
	2810	SUPERSTRUCTURE REPAIR (UNFORMED)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0059) due to user kloepj1 overridding Payment Estimate Exception 60 on the current Payment Estimate.	2,369	\$158.00	\$374,302.00
	2830	MISC.	Material			-331	\$175.00	(\$57,925.00
	2830	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0060) due to user kloepj1 overridding Payment Estimate Exception 65 on the current Payment Estimate.	331	\$175.00	\$57,925.00
	2930	AESTHETIC CONCRETE STAIN	Material			-1	\$14,877.00	(\$14,877.00
	2930	AESTHETIC CONCRETE STAIN	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0061) due to user kloepj1 overridding Payment Estimate Exception 42 on the current Payment Estimate.	1	\$14,877.00	\$14,877.00
	2940	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material			-8,672	\$62.50	(\$542,000.00)
	2940	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0062) due to user kloepj1 overridding Payment Estimate Exception 77 on the current Payment Estimate.	8,672	\$62.50	\$542,000.00
	3180	DRILLED SHAFTS (3 FT. 6	Material			-25.5	\$490.00	(\$12,495.00)

Revision 4/1/2020 Page 8 of 108



Pay Estimate Created Date: September 16, 2021

Progress Estimate Number
29 Contract ID 200515-F15 Pay Period Start September 2, 2021 Original Contract Amount \$24,269,745.00
Prime Contractor KCI Construction Company Pay Period End September 15, 2021 Net Change Order Amount \$888,557.99
Current Contract Amount \$25,158,302.99

ct	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
22		IN. DIA.)						
	3180	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0041) due to user kloepj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.	25.5	\$490.00	\$12,495.00
	3190	ROCK SOCKETS (3 FT 0 IN. DIA.)	Material			-30	\$815.00	(\$24,450.00
	3190	ROCK SOCKETS (3 FT 0 IN. DIA.)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0042) due to user kloepj1 overridding Payment Estimate Exception 37 on the current Payment Estimate.	30	\$815.00	\$24,450.00
	3300	SLAB ON CONCRETE NU- GIRDER	Material			-1,116.25	\$290.00	(\$323,712.50
	3300	SLAB ON CONCRETE NU- GIRDER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0043) due to user kloepj1 overridding Payment Estimate Exception 49 on the current Payment Estimate.	1,116.25	\$290.00	\$323,712.50
	3350	MISC.	Material			-1	\$3,730.00	(\$3,730.00
	3350	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0044) due to user kloepj1 overridding Payment Estimate Exception 68 on the current Payment Estimate.	1	\$3,730.00	\$3,730.00
	3355	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	Material			-1	\$8,330.05	(\$8,330.05
	3355	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0040) due to user kloepj1 overridding Payment Estimate Exception 75 on the current Payment Estimate.	1	\$8,330.05	\$8,330.05
	3400	PIPE PILE SPACERS	Material			-14	\$855.00	(\$11,970.00
	3400	PIPE PILE SPACERS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0045) due to user kloepj1 overridding Payment Estimate Exception 84 on the current Payment Estimate.	14	\$855.00	\$11,970.00
	3420	AESTHETIC CONCRETE STAIN	Material			-1	\$7,856.10	(\$7,856.10
	3420	AESTHETIC CONCRETE STAIN	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0063) due to user kloepj1 overridding Payment Estimate Exception 43 on the current Payment Estimate.	1	\$7,856.10	\$7,856.10
	3430	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material			-4,182	\$80.00	(\$334,560.00
	3430	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0064) due to user kloepj1 overridding Payment Estimate Exception 79 on the current Payment Estimate.	4,182	\$80.00	\$334,560.00
	3440	AESTHETIC CONCRETE STAIN	Material			-1	\$3,654.00	(\$3,654.00)
	3440	AESTHETIC CONCRETE STAIN	Material		This adjustment offsets the original system- generated Material Payment Estimate Item	1	\$3,654.00	\$3,654.00

Revision 4/1/2020 Page 9 of 108



Pay Estimate Created Date: September 16, 2021

Progress Estimate Number
29 Contract ID 200515-F15 Pay Period Start September 2, 2021 Original Contract Amount \$24,269,745.00
Prime Contractor KCI Construction Company Pay Period End September 15, 2021 Net Change Order Amount \$888,557.99
Current Contract Amount \$25,158,302.99

oject mber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
2222					Adjustment (0065) due to user kloepj1 overridding Payment Estimate Exception 44 on the current Payment Estimate.			
	3450	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material			-2,521	\$80.00	(\$201,680.00
	3450	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0066) due to user kloepj1 overridding Payment Estimate Exception 81 on the current Payment Estimate.	2,521	\$80.00	\$201,680.00
	3480	DRILLED SHAFTS (6 FT. 0 IN. DIA.)	Material			-246.16	\$485.00	(\$119,387.60
	3480	DRILLED SHAFTS (6 FT. 0 IN. DIA.)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0067) due to user kloepj1 overridding Payment Estimate Exception 35 on the current Payment Estimate.	246.16	\$485.00	\$119,387.60
	3490	ROCK SOCKETS (5 FT 6 IN. DIA.)	Material			-108	\$2,555.00	(\$275,940.00
	3490	ROCK SOCKETS (5 FT 6 IN. DIA.)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0068) due to user kloepj1 overridding Payment Estimate Exception 39 on the current Payment Estimate.	108	\$2,555.00	\$275,940.00
	5003	MISC.	Material			-7	\$1,400.00	(\$9,800.00
	5003	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0069) due to user kloepj1 overridding Payment Estimate Exception 25 on the current Payment Estimate.	7	\$1,400.00	\$9,800.00
	5008	MISC.	Material			-3	\$400.00	(\$1,200.00
	5008	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0070) due to user kloepj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.	3	\$400.00	\$1,200.00
	5013	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	Material			-202.8	\$567.75	(\$115,139.70
	5013	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0071) due to user kloepj1 overridding Payment Estimate Exception 34 on the current Payment Estimate.	202.8	\$567.75	\$115,139.70
	5014	ROCK SOCKETS (3 FT 0 IN. DIA.)	Material			-76.7	\$917.10	(\$70,341.57
	5014	ROCK SOCKETS (3 FT 0 IN. DIA.)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0072) due to user kloepj1 overridding Payment Estimate Exception 38 on the current Payment Estimate.	76.7	\$917.10	\$70,341.57
	5015	REINFORCING STEEL (EPOXY COATED)	Material			-24,760	\$1.49	(\$36,892.40
	5015	REINFORCING STEEL (EPOXY COATED)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0073) due to user kloepj1 overridding Payment Estimate Exception 71 on the current Payment Estimate.	24,760	\$1.49	\$36,892.40
	5025	SEWER	Material			-147,772	\$1.00	(\$147,772.00

Revision 4/1/2020 Page 10 of 108





Pay Estimate Created Date: September 16, 2021

200515-F15 Pay Period Start September 2, 2021 Original Contract Amount \$24,269,745.00 **Progress Estimate Number** Prime Contractor KCI Construction Company Pay Period End September 15, 2021 Net Change Order Amount \$888,557.99
Current Contract Amount \$25,158,302.99 29

ject nber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
2222	5025	SEWER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0074) due to user kloepj1 overridding Payment Estimate Exception 88 on the current Payment Estimate.	147,772	\$1.00	\$147,772.00
	5026	CLASS B-1 CONCRETE (SUBSTRUCTURE)	Material			-99.8	\$1,404.00	(\$140,119.20
	5026	CLASS B-1 CONCRETE (SUBSTRUCTURE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0075) due to user kloepj1 overridding Payment Estimate Exception 45 on the current Payment Estimate.	99.8	\$1,404.00	\$140,119.20
	5029	SLAB ON CONCRETE NU- GIRDER	Material			-762	\$406.00	(\$309,372.00
	5029	SLAB ON CONCRETE NU- GIRDER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0078) due to user kloepj1 overridding Payment Estimate Exception 51 on the current Payment Estimate.	762	\$406.00	\$309,372.00
	5032	CONDUIT SYSTEM ON STRUCTURE	Material			-0.48	\$9,965.00	(\$4,783.20
	5032	CONDUIT SYSTEM ON STRUCTURE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0076) due to user kloepj1 overridding Payment Estimate Exception 66 on the current Payment Estimate.	0.48	\$9,965.00	\$4,783.20
	5037	REINFORCING STEEL (EPOXY COATED)	Material			-31,150	\$1.19	(\$37,068.50
	5037	REINFORCING STEEL (EPOXY COATED)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0077) due to user kloepj1 overridding Payment Estimate Exception 73 on the current Payment Estimate.	31,150	\$1.19	\$37,068.50
	5038	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	Material			-1	\$13,118.70	(\$13,118.70
	5038	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0079) due to user kloepj1 overridding Payment Estimate Exception 76 on the current Payment Estimate.	1	\$13,118.70	\$13,118.70
	5044	SLOPE PROTECTION	Material			-489.6	\$150.00	(\$73,440.00
	5044	SLOPE PROTECTION	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0080) due to user kloepj1 overridding Payment Estimate Exception 23 on the current Payment Estimate.	489.6	\$150.00	\$73,440.00
	5047	15 IN. PIPE GROUP C	Material			-88	\$70.00	(\$6,160.00
	5047	15 IN. PIPE GROUP C	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0081) due to user kloepj1 overridding Payment Estimate Exception 86 on the current Payment Estimate.	88	\$70.00	\$6,160.00
	5048	18 IN. PIPE GROUP C	Material			-99	\$80.00	(\$7,920.00
	5048	18 IN. PIPE GROUP C	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0082) due to user kloepj1 overridding Payment Estimate Exception 87 on the current Payment Estimate.	99	\$80.00	\$7,920.00

Page 11 of 108 Revision 4/1/2020



Pay Estimate Created Date: September 16, 2021

Progre		imate Number 29	Contract ID Prime Contra	200515-F actor KCI Cons		Pay Period Start September 2, 2021 Ori pany Pay Period End September 15, 2021 Ne Cu	t Change Ord	er Amount \$8	
Project Number	Line No.	Item Desc	cription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
Total									\$38,774.68

Revision 4/1/2020 Page 12 of 108



					Contract Project Information
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work
J6I2222	I-64-1 (61)	Interchange improvements	I-64	ST LOUIS CITY	from west of Ewing Ave to east of 21st Street

Totals by Jo	tals by Job Numbers								
J6I2222		This Estimate	Previous	To Date					
	Posted Item Pay	\$519,278.59	\$16,747,314.22	\$17,266,592.81					
	Gross Item Adjustments	\$38,774.68	\$348,708.98	\$387,483.66					
	Gross Item Pay	\$558,053.27	\$17,096,023.20	\$17,654,076.47					
	Incentive	\$0.00	\$0.00	\$0.00					
	Disincentive	\$0.00	\$0.00	\$0.00					
	Liquidated Damages	\$0.00	\$0.00	\$0.00					
	Other Contract Adjustments	\$0.00	\$9,819.50	\$9,819.50					

Revision 4/1/2020 Page 13 of 108



Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period Exceptions / Discrepancies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 2036000, Project Item Line Number 0060, Material Set 203600096, Material 0200XXCS - Compacted Soil for Subgrade or Embankment, Acceptance Action Generic 0200XXCS is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 3040506, Project Item Line Number 1490, Material Set 304050696, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 3105003, Project Item Line Number 0160, Material Set 310500396, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 5021308, Project Item Line Number 1500, Material Set 502130896, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 5021308, Project Item Line Number 1500, Material Set 502130896, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 5021340, Project Item Line Number 1550, Material Set 502134096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 5031010A, Project Item Line Number 2640, Material Set 5031010A96, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 5031010A, Project Item Line Number 2640, Material Set 5031010A96, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 5031010A, Project Item Line Number 2640, Material Set 5031010A96, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker, Acceptance Action Generic 1058PSBB is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 5031010A, Project Item Line Number 2640, Material Set 5031010A96, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Waiting on 28 day break	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 5031010A, Project Item Line Number 2640, Material Set 5031010A96, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Waiting on 28 day break	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 5031010A, Project Item Line Number 2640, Material Set 5031010A96, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Waiting on PAL	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 5031010A, Project Item Line Number 2640, Material Set 5031010A96, Material 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 5041000, Project Item Line Number 0220, Material Set 504100096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Waiting on 28 day break	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 5041000, Project Item Line Number 0220, Material Set 504100096, Material 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 5041000, Project Item Line Number 0220, Material Set 504100096, Material 1057JMTBE42019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Waiting on PAL	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 6039901, Project Item Line Number 0240, Material Set 603990196, Material 0603WL - Material for Waterline, Acceptance Action Generic 0603WL is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 6061060, Project Item Line Number 1570, Material Set 606106096, Material 1065DE - Delineators, Acceptance Action Generic 1065DE is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 6085008, Project Item Line Number 0410, Material Set 608500896, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Waiting on PAL	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 6091042, Project Item Line Number 0460, Material Set 609104296, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Waiting on 28 day break	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 6092011, Project Item Line Number 1520, Material Set 609201196, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Waiting on 28 day break	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 6096020, Project Item Line Number 0490, Material Set 609602096, Material 0609PDDL - Paved Drainage Material for Ditch Liner, Acceptance Action Generic 0609PDDL is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 6116010A, Project Item Line Number 5044, Material Set 6116010A96, Material 100510OPTLD1 - PCCP 1" Max LS/DO, Acceptance Action Generic 100510OPTLD1 is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 6116010A, Project Item Line Number 5044, Material Set 6116010A96, Material 0501CCBA - Concrete, Class B w/Air, Acceptance	Waiting on 28 day break	kloepj1	Overridden

Revision 4/1/2020 Page 14 of 108



Exceptions (Discrepancies) This Estimate Period

Number 5003, Material Set 6149902, Material 0614/DFGTBP - Grates and Bearing Plates, Acceptance Action Generic 0614DFGTBP is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 6149902, Project Item Line Number 5008, Material Set 6149902, Material 0614DFMNPCMSD - Manhole Frame and cover (M.S.D.), Acceptance Action Generic 0614DFMNPCMSD is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 6173000, Project Item Line Number 0875, Material Set 61730098, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1 is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 6173102, Project Item Line Number 0730, Material Set 61730029, Material 0504CB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 6179903, Project Item Line Number 0730, Material Set 6179903, Material Set 6179903, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 6179903, Project Item Line Number 0730, Material Set 6179903, Material 10505CB- Delineators, Acceptance Action Generic 0501CCB1.A is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 6179903, Project Item Line Number 0730, Material Set 6179903, Material 1010SGBF - Select Gran Backfill for Structural Sys, Acceptance Action Generic 1010SGBF is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 6249905, Project Item Line Number 0790, Material Set 6179903, Material 1010SGBF - Select Gran Backfill for Structural Sys, Acceptance Action Generic 1010SGBF is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 6249905, Project Item Line Number 0790, Material Set 6179903, Material 0701PLCSLT: Drilled Shaft CSL steel pipe, Acceptance Action Generic 0	Overridden Overridden Overridden Overridden
Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 6149902, Project Item Line Number 5003, Material Set 6149902, Material 0614DFGTBP - Grates and Bearing Plates, Acceptance Action Generic 0614DFGTBP insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 6149802, Project Item Line Number 6008, Material Set 6149902, Material 0614DFMNFCMSD - Manhole Frame and cover (M.S.D.), Acceptance Action Generic 0614DFTBNF Insufficient Materials: Project J6i2222, Item 6173000, Project Item Line Number 0730, Material Set 0149902, Material 6014DFMNFCMSD - Manhole Frame and cover (M.S.D.), Acceptance Action Generic 05014DFTBNF 2015 insufficient Materials: Project J6i2222, Item 6173102, Project Item Line Number 0730, Material Set 017300096, Material Set 017300096, Material Set 017300096, Material Set 017300096, Material 05014CB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 05014CB1.A insufficient Materials: Project J6i2222, Item 6173002, Project Item Line Number 0730, Material Set 01730096, Material Set 01730096, Material 00964DRLDAA - Agg for Drainage Gr4 Alt A Limestone/DO, Acceptance Action Generic 100964DRLDAA is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 6179903, Project Item Line Number 0730, Material Set 177903, Material 1065DE - Delineators, Acceptance Action Generic 05014CB1 A is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 6179903, Project Item Line Number 0730, Material Set 6179903, Material 1010SGBF - Select Gran Backfill for Structural Sys, Acceptance Action Generic 1005GBF in Insufficient Materials: Project J6i2222, Item 6179903, Project Item Line Number 0730, Material Set 6179903, Material 1010SGBF is Insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 6179903, Project Item Line Number 0730, Material Set 6179903, Material 1010SGBF is Insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 7011105, Project It	Overridden Overridden
Number 5003, Material Set 6149902, Material 0614DFGTBP - Grates and Bearing Plates, Acceptance Action Generic 0614DFGTBP is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 6149902, Project Item Line Number 5008, Material Set 6149902, Material 0614DFMNFCMSD - Manhole Frame and cover (M.S.D.), Acceptance Action Generic 0614DFMNFCMSD is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 6173000, Project Item Line Number 0675, Material Set 617300096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 6173102, Project Item Line Number 0690, Material Set 617310296, Material 5001CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 10005G4DRLDAA - Agg for Drainage Gri4 Alt A Linestone(D.O, Acceptance Action Generic 1009G4DRLDAA - Agg for Drainage Gri4 Alt A Linestone(D.O, Acceptance Action Generic 1009G4DRLDAA - Agg for Drainage Gri4 Alt A Linestone(D.O, Acceptance Action Generic 10005G4DRLDAA - Concrete, Class B-1 w/Air, Acceptance Action Generic 1001CCB1.A is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 6179903, Project Item Line Number 0730, Material Set 6179903, Material 1065DE - Delineators, Acceptance Action Generic 1001CCB1.A is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 6179903, Project Item Line Number 0730, Material Set 6179903, Material 1065DE - Delineators, Acceptance Action Generic 1010SGBF is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 6179903, Project Item Line Number 0730, Material Set 6179903, Material 505GE is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 6149905, Project Item Line Number 0730, Material Set 6179903, Material 3093XX - See Remarks for Description of Material, Acceptance Action Generic 0701PLCSLT is insufficient. Estimate	Overridden Overridden
Number 5008, Material Set 6149902, Material 0614DFMNFCMSD - Manhole Frame and cover (M.S.D.), Acceptance Action Generic 0614DFMNFCMSD is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 6173000, Project Item Line Number 0675, Material Set 61730096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 6173102, Project Item Line Number 0690, Material Set 617310296, Material 1009G4DRLDAA - Agg for Drainage Gr4 Alt A Limestone/DO, Acceptance Action Generic 1009G4DRLDAA is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 6179903, Project Item Line Number 0730, Material Set 6179903, Material Set	Overridden Overridden
Number 0675, Material Set 617300096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 6173102, Project Item Line Number 0690, Material Set 617310296, Material 1009G4DRLDAA - Agg for Drainage Gr4 Alt A Limestone/DO, Acceptance Action Generic 1009G4DRLDAA is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 6179903, Project Item Line Number 0730, Material Set 6179903, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 6179903, Project Item Line Number 0730, Material Set 6179903, Material 1065DE - Delineators, Acceptance Action Generic 0501CCB1.A is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 6179903, Project Item Line Number 0730, Material Set 6179903, Material 1005GBF - Select Gran Backfill for Structural Sys, Acceptance Action Generic 1010SGBF is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 6249905, Project Item Line Number 0790, Material Set 6179903, Material 3099XX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 6249905, Project Item Line Number 0990, Material 3099XX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 7011105, Project Item Line Number 3180, Material Set 701110596, Material 10701PLCSLT - Drilled Shaft CSL steel pipe, Acceptance Action Generic 0701PLCSLT is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 70111105, Project Item Line Number 5013, Material Set 701110596, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 0701PLCSLT is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 70111105, Project Item Line Number 5013, Material Set 701110596, Material Set 701110	Overridden
Number 0890, Material Set 617310296, Material 1009G4DRLDAA - Agg for Drainage Gr4 Alt A Limestone/DO, Acceptance Action Generic 1009G4DRLDAA is insufficient. Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 6179903, Project Item Line Number 0730, Material Set 6179903, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient. Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 6179903, Project Item Line Number 0730, Material Set 6179903, Material 1065DE - Delineators, Acceptance Action Generic 0501CB1.A is insufficient Materials: Project J6I2222, Item 6179903, Project Item Line Number 0730, Material Set 6179903, Material 1065DE - Delineators, Acceptance Action Generic 01065DE is insufficient. Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 6179903, Project Item Line Number 0730, Material Set 6179903, Material 1010SGBF - Select Gran Backfill for Structural Sys, Acceptance Action Generic 1010SGBF is insufficient. Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 6249905, Project Item Line Number 0990, Material Set 624990596, Material 3099XX - See Remarks for Description of Material, Acceptance Action Generic 3099XX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7011105, Project Item Line Number 3180, Material Set 701110596, Material 0701PLCSLT - Drilled Shaft CSL steel pipe, Acceptance Action Generic 0701PLCSLT is insufficient. Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7011105, Project Item Line Number 5013, Material Set 701110596, Material 1005GECMLS is insufficient. Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7011105, Project Item Line Number 5013, Material Set 70111096, Material 1005GECMLS - Amsonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	
Number 0730, Material Set 6179903, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 6179903, Project Item Line Number 0730, Material Set 6179903, Material 1065DE - Delineators, Acceptance Action Generic 1065DE is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 6179903, Project Item Line Number 0730, Material Set 6179903, Material 1010SGBF - Select Gran Backfill for Structural Sys, Acceptance Action Generic 1010SGBF is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 6249905, Project Item Line Number 0990, Material Set 624990596, Material 3099XX - See Remarks for Description of Material, Acceptance Action Generic 3099XX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011105, Project Item Line Number 3180, Material 5et 701110596, Material 0701PLCSLT - Drilled Shaft CSL steel pipe, Acceptance Action Generic 0701PLCSLT is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011105, Project Item Line Number 5013, Material Set 701110596, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficients: Project J6l2222, Item 7011110, Project Item Line Number 3480, Material Set 701111096, Materials: Project J6l2222, Item 7011110, Project Item Line Number 3480, Material Set 70111096, Material Or01PLCA - Casing for Drilled Shafts, Acceptance	a committed at a co
Number 0730, Material Set 6179903, Material 1065DE - Delineators, Acceptance Action Generic 1065DE is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 6179903, Project Item Line Number 0730, Material Set 6179903, Material Set 6182222, Item 6249905, Project Item Line Number 0990, Material Set 624990596, Material 3099XX - See Remarks for Description of Material, Acceptance Action Generic 3099XX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011105, Project Item Line Number 3180, Material Set 701110596, Material 0701PLCSLT - Drilled Shaft CSL steel pipe, Acceptance Action Generic 0701PLCSLT is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011105, Project Item Line Number 5013, Material Set 701110596, Material 1005GECMLS is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011105, Project Item Line Number 5013, Material Set 7011110596, Material 1005GECMLS is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011110, Project Item Line Number 3480, Material Set 701111096, Material 0701PLCA - Casing for Drilled Shafts, Acceptance	Verridden
Number 0730, Material Set 6179903, Material 1010SGBF - Select Gran Backfill for Structural Sys, Acceptance Action Generic 1010SGBF is insufficient. Estimate Exception Type: Insufficient Materials: Project J612222, Item 6249905, Project Item Line Number 0990, Material Set 624990596, Material 3099XX - See Remarks for Description of Material, Acceptance Action Generic 3099XX is insufficient. Estimate Exception Type: Insufficient Materials: Project J612222, Item 7011105, Project Item Line Number 3180, Material Set 701110596, Material 0701PLCSLT - Drilled Shaft CSL steel pipe, Acceptance Action Generic 0701PLCSLT is insufficient. Estimate Exception Type: Insufficient Materials: Project J612222, Item 7011105, Project Item Line Number 5013, Material Set 701110596, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient. Estimate Exception Type: Insufficient Materials: Project J612222, Item 7011110, Project Item Line Number 5013, Material Set 701110596, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient. Estimate Exception Type: Insufficient Materials: Project J612222, Item 7011110, Project Item Line Number 3480, Material 5et 701111096, Material Set 70111096, Material Set 701111096, Material Set 701111096, Material Set 70111096, Material Set	Overridden
Number 0990, Material Set 624990596, Material 3099XX - See Remarks for Description of Material, Acceptance Action Generic 3099XX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011105, Project Item Line Number 3180, Material Set 701110596, Material 0701PLCSLT - Drilled Shaft CSL steel pipe, Acceptance Action Generic 0701PLCSLT is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011105, Project Item Line Number 5013, Material Set 701110596, Materials: Project J6l2222, Item 7011105, Project Item Line Aggregate material testing needs to be reported Action Generic 1005GECMLS is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011110, Project Item Line Number 3480, Material Set 701111096, Material Set 701111096, Material O701PLCA - Casing for Drilled Shafts, Acceptance	Overridden
Number 3180, Material Set 701110596, Material 0701PLCSLT - Drilled Shaft CSL steel pipe, Acceptance Action Generic 0701PLCSLT is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011105, Project Item Line Number 5013, Material Set 701110596, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011110, Project Item Line Number 3480, Material Set 701111096, Material 0701PLCA - Casing for Drilled Shafts, Acceptance	Overridden
Number 5013, Material Set 701110596, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011110, Project Item Line Number 3480, Material Set 701111096, Material 0701PLCA - Casing for Drilled Shafts, Acceptance	Overridden
Number 3480, Material Set 701111096, Material 0701PLCA - Casing for Drilled Shafts, Acceptance	Overridden
Action Generic 0701PLCA is insufficient.	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7011110, Project Item Line Number 3480, Material Set 701111096, Material 0701PLCSLT - Drilled Shaft CSL steel pipe, Acceptance Action Generic 0701PLCSLT is insufficient. Waiting on the material report based off certification kloepj1 Ox	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011204, Project Item Line Number 3190, Material Set 701120496, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient. Aggregate material testing needs to be reported kloepj1 On the project Item Line Number 3190, Material Set 701120496, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011204, Project Item Line Number 5014, Material Set 701120496, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient. Aggregate material testing needs to be reported kloepj1 On On On On On On On On On O	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7011209, Project Item Line Number 3490, Material Set 701120996, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient. Aggregate material testing needs to be reported kloepj1 On On On On On On On On On O	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7019903, Project Item Line Number 1050, Material Set 7019903, Material 1010SGBF - Select Gran Backfill for Structural Sys, Acceptance Action Generic 1010SGBF is insufficient. Aggregate material testing needs to be reported kloepj1 On On On On On On On On On O	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7033009, Project Item Line Number 1060, Material Set 703300996, Material 1056TM - Tinting Material for Concrete, Acceptance Action Generic 1056TM is insufficient. Waiting on the material report based off certification kloepj1 On	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7033009, Project Item Line Number 2930, Material Set 703300996, Material 1056TM - Tinting Material for Concrete, Acceptance Action Generic 1056TM is insufficient. Waiting on the material report based off certification kloepj1 On	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7033009, Project Item Line Number 3420, Material Set 703300996, Material 1056TM - Tinting Material for Concrete, Acceptance Action Generic 1056TM is insufficient. Waiting on the material report based off certification kloepj1 Over 1056TM is insufficient.	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7033009, Project Item Line Number 3440, Material Set 703300996, Material 1056TM - Tinting Material for Concrete, Acceptance Action Generic 1056TM is insufficient. Waiting on the material report based off certification kloepj1 Ox	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7034003, Project Item Line Number 5026, Material Set 703400396, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient. Aggregate material testing needs to be reported Kloepj1 Ovacceptance Action Generic 1005GECMLS is insufficient.	Verridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7034003, Project Item Line Number 5026, Material Set 703400396, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient. Aggregate material testing needs to be reported kloepj1 Over 1005GDCMLD is insufficient.	
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7034212, Project Item Line Number 2670, Material Set 703421296, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7034212, Project Item Line Waiting on PAL kloepj1 Ox	Overridden Overridden

Revision 4/1/2020 Page 15 of 108



Exceptions (Discrepancies) This Estimate Period

Number 2970, Malerial Set 700421289, Malerial 1003CSBL - Concrete Sealer (CS) - Silure (B. Acoptance Action Gurrant 1950SSBL is marificant. Extinate Exocution Type Institution Mariants Project 401222, Item 7051221, Provett Item Line Number 2003, Malerial Set 70502729, Malerial Set 7050279, Malerial Set	Exceptions (Discrepancies) This Estimate Period				
Number 2071, Melecia Ser 7736/1278, Melecial 1950/5581, controlle Sealer (CS) - Siane (B. Carcelame Action Centre 1950/5581, in smillfellerie. Estimate Exception Type: Instifferient Maintains: Project all 2022, Item 770/227, Type Instifferient Mai	Exceptions / Discrepencies		Explanation	Entered Bv	Status
Number 300, Material 98 173022198, Ministrial 10550581L - Convolve Sealer (CS) - Slame (B, Acceptance Action Convent 1000,05811, includiors (Materials) Property (SESSLL - Convolve Sealer (CS) - Slame (B, Acceptance Action Convent 1000,05811, includiors) (SESSLL - Convolve Sealer (CS) - Slame (B, Acceptance Action Convent Sealer (CS) - Slame (B,		@,			
Number 2000, Material Sci 17042798, Material CRID CG38/LDA - Convertee, Modified B-2 wider, Acceptance Action Generic CRID CG25/LDA in insufficient. Editinate Exception Pyter Insufficient Materials Project Micro TOM 221, Project Item Life Number 2009, Material CRID CRID Micro Micr	Number 3300, Material Set 703422196, Material 1053CSSIL - Concrete Sealer (CS) - Silane		Waiting on PAL	kloepj1	Overridden
Number 6005. Material Set 70322196. Material SOS 1003221 (Set 100322)	Number 3300, Material Set 703422196, Material 0501CCB2MDA - Concrete, Modified B-2 w/Air,		Waiting on 28 day break	kloepj1	Overridden
Number 2009, Material Sex 703422196, Material 10050CDMLD. Homogroy Grade D LSIDO, Acceptance Action Generic 10050CDMLD in smulfiolent. Estimate Exception Type: Insufficient Materials: Project, Jenn 7034221, Project Item Line Quality Control of the Project Material Ser 70342219 Authorized Ser 703422219 Authorized Ser 703422219 Authorized Ser 703422219 Authorized Ser 70342222 Authorized S	Number 5029, Material Set 703422196, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Accept		Waiting on 28 day break	kloepj1	Overridden
Number 9209, Material Set 703422196, Material 1005GECMLS - Materia	Number 5029, Material Set 703422196, Material 1005GDCMLD - Masonry Grade D LS/DO, Acce		Aggregate material testing needs to be reported	kloepj1	Overridden
Number 5029, Material Set 703422796, Material 1053CSSIL - Concrete Sealer (CS) - Salane @. Estimate Exception Type: Insufficient Materials: Project JB2222, Item 7034610, Project Item Line Number 2800, Material Set 703461096, Material 1053CSSIL - Concrete Collage Set - Wikir, Acceptance Action Generic 1053CSCMS. In insufficient. Estimate Exception Type: Insufficient Materials: Project JB2222, Item 7034610, Project Item Line Number 2800, Material Set 703461096, Material 1053CSSIL - Concrete Sealer (CS) - Salane @. Estimate Exception Type: Insufficient Materials: Project JB2222, Item 7040103, Project Item Line Number 2700, Material Set 703461096, Material 1053CSSIL - Concrete Sealer (CS) - Salane @. Estimate Exception Type: Insufficient Materials: Project JB2222, Item 7040103, Project Item Line Number 2700, Material Set 704010396, Material 1055CSCMS. A salary of Sealer Line Number 2700, Material Set 704010396, Material 1055CSCMS. A salary of Sealer Materials Set 704010396, Material 1055CSCMS. A salary of Sealer Materials Set 704010396, Material 1055CSCMS. A salary of Sealer Materials Set 704010396, Material 1055CSCMS. A salary of Sealer Materials Set 704010396, Material 1055CSCMS. A salary of Sealer Materials Set 704010396, Material 1055CSCMS. A salary of Sealer Materials Set 704010396, Material 1055CSCMS. A salary of Sealer Materials Set 704010396, Material Set 704010396, M	Number 5029, Material Set 703422196, Material 1005GECMLS - Masonry Grade E LS/DO, Acce		Aggregate material testing needs to be reported	kloepj1	Overridden
Number 2800, Material Set 703461086, Material 0501CCB1 A - Concrete, Class B-1 w/kir, Acceptance Action Generic 0501CCB1 A Is insufficient. Estimate Exception Type: Insufficient Materials: Project, J802222, Item 7034610, Project Item Line Number 2800, Material Set 70346106, Material 1050SCSB1. Concrete Sealer (CS) - Slane @ Acceptance Action Generic 1053CSS11. is insufficient. Estimate Exception Type: Insufficient Materials: Project, J802222, Item 7040103, Project Item Line Number 2700, Material Set 704010386, Material 1050SCECMLS - Masonry Grade E LS/IDO, Acceptance Action Generic 1050SCSB1. is insufficient. Estimate Exception Type: Insufficient Materials: Project, J802222, Item 7040103, Project Item Line Number 2700, Material Set 704010386, Material 1050SCECMLS - Masonry Grade E LS/IDO, Acceptance Action Generic 1056FACCMS. CA - Natural Sand for Conc Class A. Acceptance Action Generic 1056FACCMS. CA is insufficient. Estimate Exception Type: Insufficient Materials: Project, J802222, Item 7040103, Project Item Line Number 2700, Material Set 704010386, Material O50TCCB2A - Concrete, Class B-2 w/Mr. Acceptance Action Generic 1056FACMS. CA is insufficient. Estimate Exception Type: Insufficient Materials: Project J802222, Item 7040103, Project Item Line Number 2700, Material Set 704010386, Material O50TCCB2A - Concrete, Class B-2 w/Mr. Acceptance Action Generic 1050FACMS - Insufficient Materials: Project J802222, Item 7040103, Project Item Line Number 2810, Material Set 704010386, Material O50TCCB2A - Concrete, Class B-2 w/Mr. Acceptance Action Generic 1050FACMS - Insufficient. Estimate Exception Type: Insufficient Materials: Project J802222, Item 7040103, Project Item Line Number 2810, Material Set 704010386, Material Set 70401038, Mater	Number 5029, Material Set 703422196, Material 1053CSSIL - Concrete Sealer (CS) - Silane		Waiting on PAL	kloepj1	Overridden
Number 290, Material Sat 703461066, Material 1053CSSIL - Concrete Sealer (CS) - Slane	Number 2690, Material Set 703461096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Accept		Waiting on 28 day break	kloepj1	Overridden
Number 2700, Material Set 704010396, Material 1005GECMLS - Masonny Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient. Estimate Exception Type: Insufficient Materials: Project J8/2222, Item 7040103, Project tem Line Number 2700, Material Set 70401036, Material Soft 7040103, Project Item Line Number 2700, Material Set 70401036, Material Soft 7040103, Project Item Line Number 2700, Material Set 70401036, Material Soft 7040103, Project Item Line Number 2700, Material Set 704010396, Material Soft 7040103, Project Item Line Number 2700, Material Set 704010396, Material Soft 7040103, Project Item Line Number 2810, Material Set 704010396, Material Soft 7040103, Project Item Line Number 2810, Material Set 704010396, Material Soft 7040103, Project Item Line Number 2810, Material Set 704010396, Material Soft 7040103, Project Item Line Number 2810, Material Set 704010396, Material Soft 7040103, Project Item Line Number 2810, Material Soft 704010396, Material Soft 704010396, Material Soft 7040103, Project Item Line Number 2810, Material Soft 704010396, Material Soft 7040103, Project Item Line Number 2810, Material Soft 704010396, Material Soft 7040103, Project Item Line Number 2810, Material Soft 704010396, Material Soft 7040103, Project Item Line Number 2810, Material Soft 704010396, Material Soft 704010396, Material Soft 7040103, Project Item Line Number 2810, Material Soft 704010396, Material Soft 7040904, Ma	Number 2690, Material Set 703461096, Material 1053CSSIL - Concrete Sealer (CS) - Silane		Waiting on PAL	kloepj1	Overridden
Number 2700, Material Set 704010396, Material 1005EACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005ACACNSCA is insufficient. Materials: Project J612222, Item 7040103, Project Item Line Number 2700, Material Set 704010396, Material 1005CECMLS - Masonny Grade E L5/IDO, Acceptance Action Generic 00501CCB2 A: insufficient. Materials: Project J612222, Item 7040103, Project Item Line Number 2810, Material Set 704010396, Material 1005CECMLS - Masonny Grade E L5/IDO, Acceptance Action Generic 00501CCB2 A: insufficient. Materials: Project J612222, Item 7040103, Project Item Line Number 2810, Material Set 704010396, Material 0501CCB2 A: Concrete, Class B-2 w/Air, Acceptance Action Generic 0505CCBC AII. Si insufficient. Set 704010396, Material 0501CCB2 A: Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2 A: Insufficient Materials: Project J612222, Item 7040103, Project Item Line Number 2810, Material Set 704010396, Material Set 70401039, Material Set 7040104,	Number 2700, Material Set 704010396, Material 1005GECMLS - Masonry Grade E LS/DO, Acce		Aggregate material testing needs to be reported	kloepj1	Overridden
Number 2700, Material Set 704010396, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient. Materials: Project J6i2222, Item 7040103, Project Item Line Number 2810, Material Set 704010396, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS in insufficient. Sin insufficient. Sin insufficient Materials: Project J6i2222, Item 7040103, Project Item Line Number 2810, Material Set 704010396, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient. Sin insufficient.	Number 2700, Material Set 704010396, Material 1005FACCNSCA - Natural Sand for Conc Clas		Aggregate material testing needs to be reported	kloepj1	Overridden
Number 2810, Material Set 704010396, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient Materials: Project J6i2222, Item 7040103, Project Item Line Number 2810, Material Set 704010396, Material 0501CCB2 A - Concrete, Class B-2 w/Air, Acceptance Action Generic 1005GECMLS in sinsufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 7040103, Project Item Line Number 2810, Material Set 704010396, Material 1005FACCNS. CA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNS. CA is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 704904, Project Item Line Number 2720, Material Set 7049094, Material Set 7049094, Project Item Line Number 2720, Material Set 7049094, Material Set 704909	Number 2700, Material Set 704010396, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Accept		Waiting on 28 day break	kloepj1	Overridden
Number 2810, Material Set 704010396, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 7040103, Project Item Line Number 2810, Material Set 704010396, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 7049904, Project Item Line Number 2720, Material Set 7049904, Material 0501CCB2.A is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 7049904, Project Item Line Number 2720, Material Set 7049904, Material 0501CCB2.A is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 7049904, Project Item Line Number 2720, Material Set 7049904, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient Materials: Project J6i2222, Item 7049904, Project Item Line Number 2720, Material Set 7049904, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 7049904, Project Item Line Number 2830, Material Set 7049904, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 7071000, Project Item Line Number 2032, Material Set 707100096, Material 1062JBHL - Junction Boxes for Highway Lighting, Acceptance Action Generic 1062JBHL is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i2222, Item 7071000, Project Item Line Number 5032, Material Set 707100096, Material	Number 2810, Material Set 704010396, Material 1005GECMLS - Masonry Grade E LS/DO, Acce		Aggregate material testing needs to be reported	kloepj1	Overridden
Number 2810, Material Set 704010396, Material 1005FACCNSCA is insufficient. Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7049904, Project Item Line Number 2720, Material Set 7049904, Material 1050FCMSCA is insufficient. Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7049904, Project Item Line Number 2720, Material Set 7049904, Material 1050FCMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient. Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7049904, Project Item Line Number 2720, Material Set 7049904, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient. Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7049904, Project Item Line Number 2830, Material Set 7049904, Material Set 7049904, Material Set 7049904, Project Item Line Number 5032, Material Set 7049904, Material Set 70490904, Material Set 7049904, Material Set 70490904,	Number 2810, Material Set 704010396, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Accept		Waiting on 28 day break	kloepj1	Overridden
Number 2720, Material Set 7049904, Material O501CCB2.A - Concrete, Class B-2 wi/Air, Acceptance Action Generic 0501CCB2.A is insufficient. Estimate Exception Type: Insufficient Materials: Project J612222, Item 7049904, Project Item Line Number 2720, Material Set 7049904, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient. Estimate Exception Type: Insufficient Materials: Project J612222, Item 7049904, Project Item Line Number 2830, Material Set 7049904, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient. Estimate Exception Type: Insufficient Materials: Project J612222, Item 7071000, Project Item Line Number 5032, Material Set 707100096, Material 1062JBHL - Junction Boxes for Highway Lighting, Acceptance Action Generic 1062JBHL is insufficient. Estimate Exception Type: Insufficient Materials: Project J612222, Item 7071000, Project Item Line Number 5032, Material Set 707100096, Material 1062JBHL - Junction Boxes for Highway Lighting, Acceptance Action Generic 1062JBHL is insufficient. Estimate Exception Type: Insufficient Materials: Project J612222, Item 7071000, Project Item Line Number 5032, Material Set 707100096, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient. Estimate Exception Type: Insufficient Materials: Project J612222, Item 7079901, Project Item Line Number 3350, Material Set 7079901, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient. Estimate Exception Type: Insufficient Materials: Project J612222, Item 7079901, Project Item Line Number 3350, Material Set 7079901, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient. Estimate Exception Type: Insufficient Materials: Project J612222, Item 7079901, Project Item Line Number 2730, Material Set 707100096, Material 1036RSSRECAB - Epoxy Ctd Sprl Stl Rein for Anch Bolts @, Acceptance Action Generic ReinforcingMisc is insuffici	Number 2810, Material Set 704010396, Material 1005FACCNSCA - Natural Sand for Conc Clas		Aggregate material testing needs to be reported	kloepj1	Overridden
Number 2720, Material Set 7049904, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7049904, Project Item Line Number 2830, Material Set 7049904, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7071000, Project Item Line Number 5032, Material Set 707100096, Material 1062JBHL - Junction Boxes for Highway Lighting, Acceptance Action Generic 1062JBHL is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7071000, Project Item Line Number 5032, Material Set 707100096, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7079901, Project Item Line Number 3032, Material Set 707100096, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7079901, Project Item Line Number 3350, Material Set 7079901, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7101000, Project Item Line Number 2730, Material Set 70100096, Mate	Number 2720, Material Set 7049904, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Accepta		Waiting on 28 day break	kloepj1	Overridden
Number 2830, Material Set 7049904, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7071000, Project Item Line Number 5032, Material Set 707100096, Material 1062JBHL - Junction Boxes for Highway Lighting, Acceptance Action Generic 1062JBHL is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7071000, Project Item Line Number 5032, Material Set 707100096, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7079901, Project Item Line Number 3350, Material Set 707901, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7079901, Project Item Line Number 3350, Material Set 7079901, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7101000, Project Item Line Number 2730, Material Set 710100096, Material 1036RSSRECAB - Epoxy Ctd Sprl Stl Rein for Anch Bolts @, Acceptance Action Generic ReinforcingMisc is insufficient.	Number 2720, Material Set 7049904, Material 1005GECMLS - Masonry Grade E LS/DO, Accepta		Aggregate material testing needs to be reported	kloepj1	Overridden
Number 5032, Material Set 707100096, Material 1062JBHL - Junction Boxes for Highway Lighting, Acceptance Action Generic 1062JBHL is insufficient. Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7071000, Project Item Line Number 5032, Material Set 707100096, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient. Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7079901, Project Item Line Number 3350, Material Set 7079901, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient. Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7079901, Project Item Line Number 2730, Material Set 7079901, Material Set 7079901, Material Set 7079901, Material Set 7079001, Material Set 707900096, Material 1036RSSRECAB - Epoxy Ctd Sprl Stl Rein for Anch Bolts @, Acceptance Action Generic ReinforcingMisc is insufficient.	Number 2830, Material Set 7049904, Material 1005GECMLS - Masonry Grade E LS/DO, Accepta		Aggregate material testing needs to be reported	kloepj1	Overridden
Number 5032, Material Set 707100096, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7079901, Project Item Line Number 3350, Material Set 7079901, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7101000, Project Item Line Number 2730, Material Set 710100096, Material 1036RSSRECAB - Epoxy Ctd Sprl Stl Rein for Anch Bolts @, Acceptance Action Generic ReinforcingMisc is insufficient. Waiting on the material report based off certification Waiting on PAL Waiting on PAL Waiting on PAL	Number 5032, Material Set 707100096, Material 1062JBHL - Junction Boxes for Highway Lighting		Waiting on the material report based off certification	kloepj1	Overridden
Number 3350, Material Set 7079901, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7101000, Project Item Line Number 2730, Material Set 710100096, Material 1036RSSRECAB - Epoxy Ctd Sprl Stl Rein for Anch Bolts @, Acceptance Action Generic ReinforcingMisc is insufficient. Waiting on PAL kloepj1 Overridden	Number 5032, Material Set 707100096, Material 1060EC - Electrical Conduit Material, Acceptance		Waiting on the material report based off certification	kloepj1	Overridden
Number 2730, Material Set 710100096, Material 1036RSSRECAB - Epoxy Ctd Sprl Stl Rein for Anch Bolts @, Acceptance Action Generic ReinforcingMisc is insufficient.	Number 3350, Material Set 7079901, Material 1060EC - Electrical Conduit Material, Acceptance A		Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222. Item 7101000. Project Item Line Waiting on PAL kloepi1 Overridden	Number 2730, Material Set 710100096, Material 1036RSSRECAB - Epoxy Ctd Sprl Stl Rein for A		Waiting on PAL	kloepj1	Overridden
Number 5011, Material Set 710100096, Material 1036RSSRECAB - Epoxy Ctd Sprl Stl Rein for Anch Bolts @, Acceptance Action Generic ReinforcingMisc is insufficient.			Waiting on PAL	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7101000, Project Item Line Number 5015, Material Set 710100096, Material 1036RSSRECAB - Epoxy Ctd Sprl Stl Rein for Anch Bolts @, Acceptance Action Generic ReinforcingMisc is insufficient. Waiting on PAL kloepj1 Overridden	Number 5015, Material Set 710100096, Material 1036RSSRECAB - Epoxy Ctd Sprl Stl Rein for A		Waiting on PAL	kloepj1	Overridden

Revision 4/1/2020 Page 16 of 108



Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7101000, Project Item Line Number 5015, Material Set 710100096, Material 1036RSDFEC42M29 - Rein Steel EC No. 9/M29 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Waiting on PAL	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7101000, Project Item Line Number 5037, Material Set 710100096, Material 1036RSDFEC42M29 - Rein Steel EC No. 9/M29 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Waiting on PAL	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7101000, Project Item Line Number 5037, Material Set 710100096, Material 1036RSSRECAB - Epoxy Ctd Sprl Stl Rein for Anch Bolts @, Acceptance Action Generic ReinforcingMisc is insufficient.	Waiting on PAL	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7110200, Project Item Line Number 3355, Material Set 711020096, Material 1059PCECBP - Protective Coat Bents and Piers - Epoxy, Acceptance Action Generic 1059PCECBP is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7110200, Project Item Line Number 5038, Material Set 711020096, Material 1059PCECBP - Protective Coat Bents and Piers - Epoxy, Acceptance Action Generic 1059PCECBP is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7201000, Project Item Line Number 2940, Material Set 720100096, Material 0720MSEW - MSE Wall System -Bridge Approved Design, Acceptance Action Generic 0720MSEW is insufficient.	Waiting on Bridge to report material	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7201000, Project Item Line Number 2940, Material Set 720100096, Material 1010SGBF - Select Gran Backfill for Structural Sys, Acceptance Action Generic 1010SGBF is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7201000, Project Item Line Number 3430, Material Set 720100096, Material 0720MSEW - MSE Wall System -Bridge Approved Design, Acceptance Action Generic 0720MSEW is insufficient.	Waiting on Bridge to report material	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7201000, Project Item Line Number 3430, Material Set 720100096, Material 1052MSEWMETS - Metalic Reinforcement Strips for MSE, Acceptance Action Generic 1052MSEWMETS is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7201000, Project Item Line Number 3450, Material Set 720100096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Waiting on 28 day break	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7201000, Project Item Line Number 3450, Material Set 720100096, Material 1052MSEWMETS - Metalic Reinforcement Strips for MSE, Acceptance Action Generic 1052MSEWMETS is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7201000, Project Item Line Number 3450, Material Set 720100096, Material 0720MSEW - MSE Wall System -Bridge Approved Design, Acceptance Action Generic 0720MSEW is insufficient.	Waiting on Bridge to report material	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7201300, Project Item Line Number 3400, Material Set 7201300, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Waiting on 28 day break	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7201300, Project Item Line Number 3400, Material Set 7201300, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7250415, Project Item Line Number 5047, Material Set 725041596, Material 1020CPCSZC.015 - CulvPipe Zn Ctd Corrug Stl 15" 375mm, Acceptance Action Generic 1020CPCSZC.015 is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7250418, Project Item Line Number 5048, Material Set 725041896, Material 1020CPCSZC.018 - CulvPipe Zn Ctd Corrug Stl 18" 450mm, Acceptance Action Generic 1020CPCSZC.018 is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7269922, Project Item Line Number 5025, Material Set 7269922, Material 0200XXCS - Compacted Soil for Subgrade or Embankment, Acceptance Action Generic 0200XXCS is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 7269922, Project Item Line Number 5025, Material Set 7269922, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Waiting on 28 day break	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 7311053, Project Item Line Number 1190, Material Set 731105396, Material 1009G3DRLD - Agg for Drainage Gr3 Limestone/Dolomite, Acceptance Action Generic 1009G3DRLD is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 9017110, Project Item Line Number 1730, Material Set 901711096, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 9017401, Project Item Line Number 1740, Material Set 901740196, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 9017404, Project Item Line Number 1750, Material Set 901740496, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 9017407, Project Item Line Number 1760, Material Set 901740796, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 9018245, Project Item Line Number 1770, Material Set 901824596, Material 1005FACCNSCA - Natural Sand for Conc Class A,	Aggregate material testing needs to be reported	kloepj1	Overridden

Revision 4/1/2020 Page 17 of 108



Exceptions (Discrepancies) This Estimate Period

xceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Acceptance Action Generic 1005FACCNSCA is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 9018245, Project Item Line Number 1770, Material Set 901824596, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Waiting on 28 day break	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 9019901, Project Item Line Number 1780, Material Set 9019901, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 9019902, Project Item Line Number 1830, Material Set 9019902, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 9019902, Project Item Line Number 1800, Material Set 9019902, Material 0902TSBTZCAB - Bolts Galv Anchor for Traffic Signals, Acceptance Action Generic 0902TSBTZCAB is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 9019902, Project Item Line Number 1820, Material Set 9019902, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 9019902, Project Item Line Number 1820, Material Set 9019902, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Aggregate material testing needs to be reported	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 9019902, Project Item Line Number 1820, Material Set 9019902, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Waiting on 28 day break	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 9019903, Project Item Line Number 1850, Material Set 9019903, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 9020213, Project Item Line Number 1860, Material Set 902021396, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 9020513, Project Item Line Number 1870, Material Set 902051396, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 9022708, Project Item Line Number 1910, Material Set 902270896, Material 0902TSBTZCAB - Bolts Galv Anchor for Traffic Signals, Acceptance Action Generic 0902TSBTZCAB is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 9022708, Project Item Line Number 1910, Material Set 902270896, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 9022708, Project Item Line Number 1910, Material Set 902270896, Material 1092TSPS - Traffic Signal Post(s) - All Types, Acceptance Action Generic 1092TSPS is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 9022715, Project Item Line Number 1920, Material Set 902271596, Material 1092TSPS - Traffic Signal Post(s) - All Types, Acceptance Action Generic 1092TSPS is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 9022715, Project Item Line Number 1920, Material Set 902271596, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 9022715, Project Item Line Number 1920, Material Set 902271596, Material 0902TSBTZCAB - Bolts Galv Anchor for Traffic Signals, Acceptance Action Generic 0902TSBTZCAB is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 9023250, Project Item Line Number 1950, Material Set 902325096, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 9023255, Project Item Line Number 1960, Material Set 902325596, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 9024283, Project Item Line Number 1990, Material Set 902428396, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 9024975, Project Item Line Number 2000, Material Set 902497596, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 9028308, Project Item Line Number 2040, Material Set 902830896, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 9028310, Project Item Line Number 2050, Material Set 902831096, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 9028311, Project Item Line Number 2060, Material Set 902831196, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I2222, Item 9029100, Project Item Line	Aggregate material testing needs to be reported	kloepj1	Overridden

Revision 4/1/2020 Page 18 of 108



Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Number 2100, Material Set 902910096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 9029902, Project Item Line Number 2160, Material Set 9029902, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 9031020, Project Item Line Number 2210, Material Set 903102096, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Waiting for 28 day break	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 9039901, Project Item Line Number 2330, Material Set 9039901, Material 1080BRM - Bridge Material, Acceptance Action Generic 1080BRM is insufficient.	Waiting on Bridge to report material	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 9039901, Project Item Line Number 2330, Material Set 9039901, Material 0903HSOHTR - Overhead Truss Sign, Acceptance Action Generic 0903HSOHTR is insufficient.	Waiting on Bridge to report material	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l2222, Item 9039901, Project Item Line Number 2330, Material Set 9039901, Material 0903HSSBPSST - Slip Base PSST Posts, Acceptance Action Generic 0903HSSBPSST is insufficient.	Waiting on the material report based off certification	kloepj1	Overridden
Estimate Exception Type: Item Overrun: Contract 200515-F15, Contract Project J6l2222, Project Item Line Number 0710, Contract Line Item Number 0710, Item 6173600D, Minor Item.	Waiting on a change order to pay this item	kloepj1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 200515-F15, Contract Project J6l2222, Project Item Line Number 2020, Contract Line Item Number 2020, Item 9027300, Minor Item.	Waiting on a change order to pay this item	kloepj1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 200515-F15, Contract Project J6l2222, Project Item Line Number 2080, Contract Line Item Number 2080, Item 9028811, Minor Item.	Waiting on a change order to pay this item	kloepj1	Acknowledged

Revision 4/1/2020 Page 19 of 108



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note: Posted Q	uantities	and valu	ies are	based on I	Report Generated date and can differ from the posted am	ount at the	time the Es	stimate was	Genera	ted.		i	
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)	
200515-F15	J6I2222	0001	0010	2013000	CLEARING AND GRUBBING	2.00	0.00	2.00	ACRE	2.00	\$25,000.00	\$50,000.00	
		0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.90	\$600,000.00	\$540,000.00	
		0001	0025	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	155.00	0.00	155.00	SQFT	155.00	\$140.50	\$21,777.50	
		0001	0040	2029901	MISC.REMOVAL OF ACM CONDUIT SYSTEM - TELEPHONE	1.00	0.00	1.00	LS	1.00	\$13,500.00	\$13,500.00	
		0001	0045	2029903	MISC.MISCELLANEOUS ACM REMOVAL	80.00	0.00	80.00	LF	0.00	\$48.00	\$0.00	
		0001	0050	2031000	CLASS A EXCAVATION	153,414.00	0.00	153,414.00	CUYD	143,072.00	\$15.00	\$2,146,080.00	
		0001	0060	2036000	COMPACTING EMBANKMENT	106,637.00	11,081.00	117,718.00	CUYD	117,718.00	\$3.00	\$353,154.00	
		0001	0070	2037075	COMPACTING IN CUT	45.00	0.00	45.00	STA	0.00	\$1.00	\$0.00	
		0001	0080	2039901	MISC.STOCK PILE REMOVAL AT OLD 21ST STREET FOR MSD	1.00	0.00	1.00	LS	0.75	\$85,000.00	\$63,750.00	
		0001	0090	2039907	MISC.Lightweight Fill	16,413.00	-16,413.00	0.00	CUYD	0.00	\$61.50	\$0.00	
		0001	0100	2042010	SETTLEMENT GAUGE	10.00	0.00	10.00	EA	10.00	\$1,500.00	\$15,000.00	
		0001	0110	2043010	PORE PRESSURE MEASURING DEVICE	3.00	0.00	3.00	EA	3.00	\$4,000.00	\$12,000.00	
		0001	0120	2063000	CLASS 3 EXCAVATION	2,716.00	1,201.00	3,917.00	CUYD	3,760.00	\$15.00	\$56,400.00	
		0001	0130	2071000	LINEAR GRADING CLASS 1	11.00	0.00	11.00	STA	3.00	\$800.00	\$2,400.00	
		0001	0140	3040143	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	1,152.00	-64.00	1,088.00	SQYD	143.00	\$11.00	\$1,573.00	
		0001	0150	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	72.00	0.00	72.00	SQYD	72.00	\$23.00	\$1,656.00	
		0001	0160	3105003	GRAVEL (A) OR CRUSHED STONE (B)	540.00	2,888.00	3,428.00	SQYD	2,888.00	\$12.00	\$34,656.00	
		0001	0170	4011207	BITUMINOUS PAVEMENT MIXTURE PG70-22, (BP-1)	1,950.80	0.00	1,950.80	TONS	0.00	\$77.75	\$0.00	
		0001	0180	4030109	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125CLP MIX)	376.20	0.00	376.20	TONS	0.00	\$125.00	\$0.00	
		0001	0190	4071005	TACK COAT	1,660.00	0.00	1,660.00	GAL	0.00	\$3.50	\$0.00	
		0001	01 0210 502	5021108	CONCRETE PAVEMENT (8 IN. NON-REINF)	366.30	0.00	366.30	SQYD	366.30	\$49.00	\$17,948.70	
			****	0210 502	5021340	TYPE A2 SHOULDER	1,563.20	0.00	1,563.20	SQYD	519.96	\$36.00	\$18,718.56
			0220	5041000	CONCRETE APPROACH PAVEMENT	105.20	0.00	105.20	SQYD	33.50	\$150.00	\$5,025.00	
			0230	6039901	WATER	1.00	0.00	1.00	LS	1.00	\$30,000.00	\$30,000.00	
		0001	01 0240 603	6039901	WATER	1.00	0.00	1.00	LS	1.00	\$12,000.00	\$12,000.00	
		0001		6039903	WATER	20.00	0.00	20.00	LF	20.00	\$2,000.00	\$40,000.00	
		0001	0260	6039903	WATER	150.00	7.00	157.00	LF	157.00	\$2,000.00	\$314,000.00	
		0001	0270	6039903	WATER	570.00	-179.80	390.20	LF	390.20	\$400.00	\$156,080.00	
		0001	0280	6039903	WATER	100.00	0.00	100.00	LF	100.00	\$400.00	\$40,000.00	
		0001	0290	6049901	MISC.INSPECTION OF 9X7 CONCRETE ARCH SEWER	1.00	0.00	1.00	LS	0.00	\$6,000.00	\$0.00	
		0001	0300	6049903	MISC.MODOT MANHOLE - ADJUST TO GRADE	24.00	0.00	24.00	LF	24.00	\$1,000.00	\$24,000.00	
		0001	0310	6049903	MISC.MSD MANHOLE - ADJUST TO GRADE, 5' TO 10' RANGE	25.00	0.00	25.00	LF	18.40	\$1,000.00	\$18,400.00	
		0001	0320	6049903	MISC.MSD MANHOLE - ADJUST TO GRADE, 10' TO 15' RANGE	23.00	0.00	23.00	LF	0.00	\$1,000.00	\$0.00	
		0001	0330	6049903	MISC.MSD MANHOLE - ADJUST TO GRADE, 15' TO 20' RANGE	37.00	0.00	37.00	LF	18.20	\$1,000.00	\$18,200.00	
		0001	0340	6049903	MISC.MSD MANHOLE - ADJUST TO GRADE, 25' TO 30' RANGE	28.00	0.00	28.00	LF	0.00	\$1,000.00	\$0.00	
		0001	0350	6071012A	CHAIN-LINK FENCE (60 IN.)	586.00	0.00	586.00	LF	0.00	\$28.00	\$0.00	
		0001	0360	6071040	DRIVE GATE (CHAIN-LINK)	2.00	0.00	2.00	EA	0.00	\$1,200.00	\$0.00	
		0001	0370	6071050	CHAIN-LINK FENCE (RETAINING WALLS)	1,800.00	-963.00	837.00	LF	480.00	\$24.00	\$11,520.00	
		0001	0380	6071102	MODIFIED CONCRETE GUTTER TYPE B	2,038.00	-1,085.00	953.00	LF	847.00	\$34.00	\$28,798.00	
		0001	0390	6081012	TRUNCATED DOMES	60.00	-10.00	50.00	SQFT	0.00	\$35.00	\$0.00	
		0001	0400	6083006	6 IN. CONCRETE MEDIAN STRIP	529.80	0.00	529.80	SQYD	0.00	\$100.00	\$0.00	
		0001	0410	6085008	PAVED APPROACH, 8 IN.	72.30	0.00	72.30	SQYD	72.30	\$125.00	\$9,037.50	
		0001	0420	6086004	CONCRETE SIDEWALK, 4 IN.	1,152.10	-63.80	1,088.30	SQYD	142.40	\$51.00	\$7,262.40	
		0001	0430	6086007	CONCRETE SIDEWALK, 7 IN.	15.30	-15.30	0.00	SQYD	0.00	\$65.00	\$0.00	
		0001	0440	6089902	MISC.ADA CURB RAMP	16.00	1.00	17.00	EA	4.00	\$3,550.00	\$14,200.00	
		0001	0450	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	301.00	0.00	301.00	LF	113.00	\$45.00	\$5,085.00	
		0001	0460	6091042	CONCRETE GUTTER TYPE B	2,007.00	1,085.00	3,092.00	LF	395.00	\$30.00	\$11,850.00	

Revision 4/1/2020 Page 20 of 108



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract	Project	Category	Line	Item	Report Generated date and can differ from the posted am Description	Bid	Net	Total	Genera Unit	Total	Unit Price	Total Value POSTE
Nm.CONTRACT	No.		No.	Code		Quantity	Change Order	Current Quantity		Posted Approved Qty		To Date (See repo generated date)
00515-F15	J6I2222	0001	0470	6091060	PAVED DITCH	210.30	0.00	210.30	SQYD	0.00	\$81.00	\$0.0
		0001	0480	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	203.00	1,718.00	1,921.00	LF	181.00	\$15.00	\$2,715.0
		0001	0490	6096020	FURNISHING TYPE 2 ROCK DITCH LINER	24.00	233.40	257.40	CUYD	210.50	\$100.00	\$21,050.0
		0001	0500	6096042	PLACING TYPE 2 ROCK DITCH LINER	24.00	233.40	257.40	CUYD	210.50	\$100.00	\$21,050.0
		0001	0510	6097000	ROCK LINING	2.00	10.00	12.00	CUYD	0.00	\$1,000.00	\$0.0
		0001	0515	6099903	MISC.MODIFIED INTEGRAL CURB (2 IN. HEIGHT) TYPE A	320.00	0.00	320.00	LF	122.00	\$50.00	\$6,100.0
		0001	0520	6113020	FURNISHING TYPE 2 ROCK BLANKET	567.00	0.00	567.00	CUYD	0.00	\$48.00	\$0.
		0001	0530	6113040	PLACING TYPE 2 ROCK BLANKET	567.00	0.00	567.00	CUYD	0.00	\$21.00	\$0.
		0001	0540	6116010A	SLOPE PROTECTION	1.00	-1.00	0.00	SQYD	0.00	\$300.00	\$0.
		0001	0550	6119907	MISC.Furnishing Modified Rock Blanket	1,151.00	0.00	1,151.00	CUYD	0.00	\$50.00	\$0.
		0001	0560	6119907	MISC.Placing Modified Rock Blanket	1,151.00	0.00	1,151.00	CUYD	0.00	\$21.00	\$0.
		0001	0570	6122012	IMPACT ATTENUATOR 55 MPH (SAND BARREL ARRAY)	5.00	0.00	5.00	EA	4.00	\$2,823.00	\$11,292.
		0001	0580	6122020	REPLACEMENT SAND BARREL	12.00	0.00	12.00	EA	5.00	\$431.00	\$2,155.
		0001	0590	6122030	IMPACT ATTENUATOR (RELOCATION)	9.00	0.00	9.00	EA	2.00	\$877.00	\$1,754.
		0001	0600	6133020	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	148.50	0.00	148.50	TONS	0.00	\$62.00	\$0
		0001	0610	6133021	REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	528.50	0.00	528.50	SQYD	0.00	\$58.75	\$0
		0001	0620	6141024	GRATE AND BEARING PLATE (5 FT. X 3 FT. OR 1524 MM X 914 MM)	10.00	2.00	12.00	EA	6.00	\$1,400.00	\$8,400
		0001	0630	6141120	CURVED VANE GRATE AND FRAME (2 FT. X 2 FT. OR 600MM X 600MM)	72.00	-72.00	0.00	EA	0.00	\$700.00	\$0
		0001	0640	6149902	MISC.Parallel Grate and Bearing Plate (2 FT.x2FT.)	67.00	-57.00	10.00	EA	4.00	\$700.00	\$2,800
		0001	0650	6169901	MISC.TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.75	\$465,000.00	\$348,750
		0001 06 0001 06	0660	6169902	MISC.MSD Manhole Frame and Cover	17.00	-17.00	0.00	EA	0.00	\$400.00	\$0
			0670	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN (CONTRACTOR FURNISHED AND RETAINED)	8.00	0.00	8.00	EA	7.00	\$3,500.00	\$24,500
			0675	6173000	CONCRETE TRAFFIC BARRIER, TYPE C	254.00	357.00	611.00	LF	485.00	\$145.00	\$70,325
			0680	6173100	CONCRETE TRAFFIC BARRIER, TYPE D	1,787.00	-1,185.00	602.00	LF	0.00	\$90.00	\$0
					CONCRETE TRAFFIC BARRIER, TYPE D (RETAINING WALL)	2,413.00	1,085.00	3,498.00	LF	2,335.50	\$85.00	\$198,517
		0001	0700	6173103	CONCRETE TRAFFIC BARRIER, TYPE D (MOMENT SLAB)	440.00	0.00	440.00	LF	0.00	\$110.00	\$0
		0001	0710	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	2,488.00	0.00	2,488.00	LF	2,713.50	\$25.90	\$70,279
		0001	0720	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	4,013.00	0.00	4,013.00	LF	1,112.50	\$11.50	\$12,79
		0001	0730	6179903	MISC.MODIFIED BARRIER WALL	315.00	0.00	315.00	LF	60.00	\$300.00	\$18,000
		0001	0740	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$2,269,999.84	\$0
		0001	0741	6181000	MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$2,162,092.84	\$2,162,092
		0001	0750	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	2.00	0.00	2.00	EA	0.00	\$600.00	\$0
		0001	0760	6189901	MISC.TEMPORARY RAILROAD CROSSING	1.00	0.00	1.00	LS	0.00	\$30,000.00	\$0
		0001	0765	6189916	MISC.ACCELERATING THE COMPLETION OF WORK REQUIRING RAILROAD FLAGGERS (INCENTIVE/DISINCENTIVE CLAUSE)	1,000.00	0.00	1,000.00	DLR	0.00	\$0.00	\$0
		0001	0770	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	505.00	0.00	505.00	LF	0.00	\$25.00	\$0
		0001	0780	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	19.00	0.00	19.00	EA	0.00	\$320.00	\$(
		0001	0790	6200027	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT	7.00	0.00	7.00	EA	0.00	\$450.00	\$(
		0001	0800	6200030	PREFORMED THERMOPLASTIC PAVEMENT MARKING, WORD (ONLY)	9.00	0.00	9.00	EA	0.00	\$450.00	\$(
		0001	0810	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	114.00	0.00	114.00	EA	0.00	\$200.00	\$0
		0001	0820	6200042	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	14.00	0.00	14.00	EA	0.00	\$50.00	\$(
		0001	0830	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	21,905.00	0.00	21,905.00	LF	0.00	\$0.50	\$
		0001	0840	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	12,373.00	0.00	12,373.00	LF	0.00	\$0.50	\$(
		0001	0850	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	4,999.00	0.00	4,999.00	LF	0.00	\$1.00	\$1
		0001	0860	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING	9,364.00	0.00	9,364.00	LF	0.00	\$0.50	\$0

Revision 4/1/2020 Page 21 of 108



Total Paid / All Items / All Estimates (Including this Estimate)

lote: Posted Qt	uantities	and Valu	ies are	based on F	Report Generated date and can differ from the posted am	ount at the	time the Es	timate was	Generat	ed.			
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)	
200515-F15	J6I2222				PAINT, TYPE P BEADS					,			
		0001	0870	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	3,485.00	0.00	3,485.00	LF	0.00	\$0.50	\$0.00	
		0001	0880	6206124A	24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	91.00	0.00	91.00	LF	0.00	\$10.00	\$0.00	
		0001	0890	6206125A	24 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	84.00	0.00	84.00	LF	0.00	\$10.00	\$0.00	
		0001	0900	6207001	PAVEMENT MARKING REMOVAL	7,291.00	0.00	7,291.00	LF	0.00	\$1.00	\$0.00	
		0001	0910	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	56.00	0.00	56.00	EA	0.00	\$50.00	\$0.00	
		0001	0920	6209902	MISC.ISLAND TUBULAR MARKER	8.00	0.00	8.00	EA	0.00	\$110.00	\$0.00	
		0001	0930	6209902	MISC.PREFORMED THERMOPLASTIC PAVEMENT MARKING, LANE REDUCTION ARROW	8.00	0.00	8.00	EA	0.00	\$2,000.00	\$0.00	
		0001	0940	6209902	MISC.TIER TWO INLAID PAVEMENT MARKER SYSTEM	8.00	0.00	8.00	EA	0.00	\$4,475.00	\$0.00	
		0001	0950	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	2,356.00	0.00	2,356.00	SQYD	0.00	\$6.75	\$0.00	
		0001	0960	6221003	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (GREATER THAN 3 IN. THICK)	10,196.00	0.00	10,196.00	SQYD	0.00	\$3.85	\$0.00	
		0001	0970	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	150.00	0.00	150.00	SQYD	0.00	\$13.50	\$0.00	
		0001	0980	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	3,917.00	172.10	4,089.10	SQYD	906.40	\$3.00	\$2,719.20	
		0001	0990	6249905	MISC.Miscellaneous Granular Drainage Blanket	2,115.00	286.00	2,401.00	SQYD	2,401.00	\$15.50	\$37,215.50	
		0001	1000	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.75	\$125,000.00	\$93,750.00	
		0001	1010	7011105	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	30.00	0.00	30.00	LF	0.00	\$415.00	\$0.00	
		0001	1020	7011107	DRILLED SHAFTS (4 FT. 6 IN. DIA.)	39.00	0.00	39.00	LF	0.00	\$415.00	\$0.00	
		0001	1030	7011207	ROCK SOCKETS (4 FT 6 IN. DIA.)	6.00	0.00	6.00	LF	0.00	\$415.00	\$0.00	
		0001	1040	7011600	SONIC LOGGING TESTING	1.00	0.00	1.00	EA	0.00	\$1,000.00	\$0.00	
		0001	1050	7019903	MISC.Miscellaneous Stone Columns	6,535.00	-5,583.00	952.00	LF	952.00	\$25.00	\$23,800.00	
		0001 1 0001 1 0001 1	1060	7033009	AESTHETIC CONCRETE STAIN	1.00	0.00	1.00	LS	1.00	\$6,110.88	\$6,110.88	
			1080	7061000	REINFORCING STEEL	5,740.00	0.00	5,740.00	LB	0.00	\$1.60	\$0.00	
			1090	7201000	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	3,394.00	0.00	3,394.00	SQFT	3,394.00	\$60.00	\$203,640.00	
			1100	7201200	SELECT GRANULAR BACKFILL FOR STRUCTURAL SYSTEMS	12,416.00	-478.00	11,938.00	CUYD	11,938.00	\$30.00	\$358,140.00	
		0001	1110	7261015	15 IN. PIPE GROUP A 3.	3,631.00	-921.00	2,710.00	LF	2,373.00	\$70.00	\$166,110.00	
		0001	1120	7261018		1,252.00	-169.00	1,083.00	LF	1,078.00	\$80.00	\$86,240.00	
		0001	1130	7261024	24 IN. PIPE GROUP A	118.00			0.00	LF	0.00	\$135.00	\$0.00
		0001	1140	7261030	30 IN. PIPE GROUP A	298.00	67.00	365.00	LF	365.00	\$250.00	\$91,250.00	
		0001	1150	7261036	36 IN. PIPE GROUP A	54.00	0.00	54.00	LF	54.00	\$400.00	\$21,600.00	
		0001	1160	7279901	MISC.MSD SPECIAL DRAINAGE STRUCTURE #"301"	1.00	0.00	1.00	LS	1.00	\$55,000.00	\$55,000.00	
		0001	1170	7311022	PRECAST CONCRETE DROP INLET 2 FT X 2 FT	57.00	0.00	57.00	FT	51.00	\$350.00	\$17,850.00	
		0001	1180	7311042	PRECAST CONCRETE DROP INLET 4 FT X 2 FT	178.00	-11.00	167.00	FT	155.00	\$450.00	\$69,750.00	
		0001	1190	7311053	PRECAST CONCRETE DROP INLET 5 FT X 3 FT	56.00	18.00	74.00	FT	59.00	\$650.00	\$38,350.00	
		0001	1200	7319913	MISC.MSD Standard 60" Manhole	56.00	1.00	57.00	FT	57.00	\$510.00	\$29,070.00	
		0001	1210	7319913	MISC.MSD Standard Line 48" Manhole	76.00	7.00	83.00	FT	83.00	\$350.00	\$29,050.00	
		0001	1220	7320615A	15 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	1.00	8.00	9.00	EA	9.00	\$800.00	\$7,200.00	
		0001	1230	7320624A	24 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	2.00	-2.00	0.00	EA	0.00	\$1,000.00	\$0.00	
		0001	1240	7320630A	30 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END	1.00	0.00	1.00	EA	1.00	\$1,500.00	\$1,500.00	
		0001	1245	8031000A	SECTION TURF TYPE TALL FESCUE SODDING	1,242.00	0.00	1,242.00	SQYD	0.00	\$8.50	\$0.00	
		0001	1260	8059919	MISC.WARM OR COOL SEASON MIXTURES	9.00	0.00	9.00	ACRE	0.00	\$1,975.00	\$0.00	
		0001	1270	8061003	SEDIMENT TRAP EXCAVATION	57.00	0.00	57.00	CUYD	0.00	\$25.00	\$0.00	
		0001	1280	8061004	SEDIMENT TRAP ROCK	7.00	0.00	7.00	CUYD	0.00	\$100.00	\$0.00	
		0001	1290	8061005	ROCK DITCH CHECK	2,613.00	0.00	2,613.00	LF	24.00	\$10.50	\$252.00	
		0001	1300	8061007A	CURB INLET CHECK	111.00	0.00	111.00	EA	0.00	\$115.00	\$0.00	

Revision 4/1/2020 Page 22 of 108



Total Paid / All Items / All Estimates (Including this Estimate)

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTEI To Date (See report generated date)
00515-F15	J6I2222	0001	1320	8061017	TEMPORARY SEEDING AND MULCHING	14.00	0.00	14.00	ACRE	1.60	\$1,500.00	\$2,400.0
		0001	1330	8061019	SILT FENCE	8,207.00	0.00	8,207.00	LF	2,340.00	\$2.25	\$5,265.0
		0001	1340	8064128	TYPE 1 TURF REINFORCEMENT MAT	913.00	0.00	913.00	SQYD	0.00	\$5.15	\$0.0
		0002	1350	3030600	FURNISHING ROCK BASE MATERIAL	3,355.00	0.00	3,355.00	SQYD	0.00	\$0.00	\$0.0
		0002	1360	3030610A	PLACING ROCK BASE	3,355.00	0.00	3,355.00	SQYD	0.00	\$0.00	\$0.0
		0002	1370	4030419	9 INCHES, ASPHALTIC CONCRETE PAVEMENT SP125CLP	2,073.00	0.00	2,073.00	SQYD	0.00	\$0.00	\$0.0
		0003	1380	3030600	FURNISHING ROCK BASE MATERIAL	3,363.00	0.00	3,363.00	SQYD	0.00	\$10.50	\$0.0
		0003	1390	3030610A	PLACING ROCK BASE	3,363.00	0.00	3,363.00	SQYD	0.00	\$5.50	\$0.0
		0003	1400	5021332	CONCRETE PAVEMENT (8 1/2 IN. NON-REINFORCED, 15 FT.	2,073.00	0.00	2,073.00	SQYD	0.00	\$51.00	\$0.0
		0004	1410	4010150	JOINTS) TYPE A2 SHOULDER	206.10	0.00	206.10	SQYD	0.00	\$0.00	\$0.0
		0004	1420	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	304.00	0.00	304.00	LF	0.00	\$0.00	\$0.0
		0005	1430	5021340	TYPE A2 SHOULDER	206.10	0.00	206.10	SQYD	0.00	\$35.50	\$0.0
		0005	1440	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	304.00	0.00	304.00	LF	0.00	\$20.00	\$0.0
		0006	1450	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	20,740.00	0.00	20,740.00	SQYD	0.00	\$0.00	\$0.0
		0006	1460	4039905	MISC.11.5 INCHES, ASPHALTIC CONCRETE PAVEMENT	10,939.00	0.00	10,939.00	SQYD	0.00	\$0.00	\$0.0
			1470	4039905	SP125CLP MISC.9.5 INCHES, ASPHALTIC CONCRETE PAVEMENT	6,859.00	0.00	6.859.00	SQYD	0.00	\$0.00	\$0.0
		0006			SP125CLP			.,,				
		0006	1480	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	2,017.00	0.00	2,017.00	LF	0.00	\$0.00	\$0.0
		0007	1490	3040506	` ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' '	20,910.00	-323.00	20,587.00	SQYD	16,041.67	\$6.50	\$104,270.8
		0007 1: 0007 1: 0008 1:	1500	5021308	CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. JOINTS)	6,859.00	0.00	6,859.00	SQYD	6,019.00	\$51.00	\$306,969.0
			1510	5021309	CONCRETE PAVEMENT (9 IN. NON-REINFORCED 15 FT. JOINTS)	10,939.00	-323.00	10,616.00	SQYD	5,757.90	\$54.00	\$310,926.6
			1520	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	2,017.00	-1,225.00	792.00	LF	210.00	\$15.00	\$3,150.0
			1530	4010150	TYPE A2 SHOULDER	3,806.80	0.00	3,806.80	SQYD	0.00	\$0.00	\$0.0
			1540	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	3,319.00	0.00	3,319.00	LF	0.00	\$0.00	\$0.0
		0009	1550	5021340	TYPE A2 SHOULDER	3,806.80	0.00	3,806.80	SQYD	3,170.47	\$35.00	\$110,966.4
		0009	1560	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	3,319.00	-2,667.00	652.00	LF	512.00	\$15.00	\$7,680.0
		0010	1570	6061060		3,813.00	-62.00	3,751.00	LF	463.00	\$19.00	\$8,797.0
		0010	1580	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED	2.00	0.00	2.00	EA	0.00	\$2,850.00	\$0.0
		0010	1590	6061069	CURB) MGS BRIDGE APPROACH TRANSITION SECTION	2.00	0.00	2.00	EA	0.00	\$2,800.00	\$0.0
			1600	6061070	(REGULAR/NO CURB) MGS VERTICAL CONCRETE BARRIER TRANSITION	11.00	0.00	11.00	EA	4.00	\$2,750.00	\$11,000.0
		0010	1610	6061080	MGS END ANCHOR	8.00	0.00	8.00	EA	1.00	\$1,000.00	\$1,000.0
		0010	1620	6063014		12.00	0.00	12.00	EA	4.00	\$2,600.00	\$1,000.0
		0010	1630	6063019	TYPE A CRASHWORTHY END TERMINAL (MASH) TYPE E CRASHWORTHY END TERMINAL	1.00	0.00	1.00	EA	0.00	\$27,500.00	\$10,400.0
		0010	1640	9011330	LUMINAIRE, 1000 WATT HIGH PRESSURE SODIUM HIGH MAST	16.00			EA	0.00	\$1,018.00	\$0.0
		0020		9013002		26.00	435.00	16.00 461.00	LF			\$4,545.7
		0020	1650		CONDUIT, 2 IN. RIGID, IN TRENCH CONDUIT, 3 IN. RIGID, IN TRENCH	282.00	0.00		LF	435.00	\$10.45 \$11.00	
		0020	1660	9013003	CONDUIT, 4 IN. RIGID, IN TRENCH	23.00	0.00	282.00	LF	120.00	\$11.00	\$1,320.0
		0020	1670			339.00	0.00	339.00	LF	0.00	\$12.35	\$0.0
		0020	1680	9014004	CONDUIT, 4 IN. RIGID, PUSHED TRENCHING TYPE I		0.00		LF	949.00	\$3.80	\$3.606.2
		0020	1690	9015010		2,136.00		2,136.00				\$3,000.2
		0020	1700		TRENCHING TYPE II	237.00	460.00	697.00	LF	566.00	\$3.80	, , , , ,
		0020	1710	9016110	PULL BOX, PREFORMED CLASS 1	15.00	0.00	15.00	EA	5.00	\$765.00	\$3,825.0
		0020	1720	9016112	PULL BOX, PREFORMED CLASS 3	2.00	0.00	2.00	EA	1.00	\$1,343.00	\$1,343.0
		0020	1730	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	360.00	0.00	360.00	LF	360.00	\$0.55	\$198.0
		0020	1740	9017401	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 2 AWG	800.00	0.00	800.00	LF	800.00	\$6.00	\$4,800.0
		0020	1750	9017404	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 6 AWG	2,190.00	0.00	2,190.00	LF	336.00	\$3.60	\$1,209.6
		0020	1760	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	1,010.00	0.00	1,010.00	LF	310.00	\$2.90	\$899.0

Revision 4/1/2020 Page 23 of 108



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Total Value POSTED To Date (See report generated date)	Unit Price	Total	Unit									Contract
		Posted Approved Qty	Onic	Total Current Quantity	Net Change Order	Bid Quantity	Description	Item Code	Line No.	Category	Project No.	Nm.CONTRACT
\$4,272.00	\$1,068.00	4.00	EA	4.00	0.00	4.00	POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	9018245	1770	0020	J6I2222	200515-F15
\$16,605.00	\$16,605.00	1.00	LS	1.00	0.00	1.00	MISC.EXTERNAL CONDUIT SYSTEM ON STRUCTURE	9019901	1780	0020		
\$0.00	\$34,530.00	0.00	EA	2.00	0.00	2.00	MISC.150 FT HIGH MAST POLE	9019902	1790	0020		
\$9,000.00	\$2,250.00	4.00	EA	4.00	0.00	4.00	MISC.45 FT TOP MOUNT POLES, TYPE AT	9019902	1800	0020		
\$0.00	\$483.00	0.00	EA	1.00	0.00	1.00	MISC.ADJUST PULL BOX TO GRADE	9019902	1810	0020		
\$2,395.14	\$7,258.00	0.33	EA	2.00	0.00	2.00	MISC.BASE MOUNTED 240/480V COMBINATION POWER SUPPLY AND CONTROLLER	9019902	1820	0020		
\$2,288.00	\$572.00	4.00	EA	4.00	0.00	4.00	MISC.LED-C TOP-MOUNT LUMINAIRE	9019902	1830	0020		
\$0.00	\$15.85	0.00	LF	549.00	0.00	549.00	MISC.1 IN RIGID GALVANIZED STEEL CONDUIT	9019903	1840	0020		
\$2,343.00	\$1.65	1,420.00	LF	3,250.00	1,420.00	1,830.00	MISC.THHN CABLE 2C #6 AWG	9019903	1850	0020		
\$761.00	\$761.00	1.00	EA	3.00	0.00	3.00	SIGNAL HEAD, TYPE 3S	9020213	1860	0030		
\$12,051.00	\$927.00	13.00	EA	37.00	0.00	37.00	SIGNAL HEAD, TYPE 3B	9020513	1870	0030		
\$0.00	\$1,038.00	0.00	EA	3.00	0.00	3.00	SIGNAL HEAD, TYPE 4B	9020514	1880	0030		
\$0.00	\$12.50	0.00	SQFT	148.00	15.00	133.00	SH-FLAT SHEET - SIGNAL SIGN	9020833	1890	0030		
\$0.00	\$33.00	0.00	EA	43.00	2.00	41.00	SIGNAL SIGN, MOUNTING HARDWARE	9020834	1900	0030		
\$2,580.00	\$645.00	4.00	EA	18.00	0.00	18.00	POST, SIGNAL 8 FT. OR 2.4 M	9022708	1910	0030		
\$972.00	\$972.00	1.00	EA	1.00	0.00	1.00	POST, SIGNAL 15 FT. OR 4.6 M	9022715	1920	0030		
\$0.00	\$7.324.00	0.00	EA	1.00	0.00	1.00	POST, TYPE C, 30 FT. ARM OR 9.1 M ARM	9023230	1930	0030		
\$0.00	\$7,532.00	0.00	EA	1.00	0.00	1.00	POST, TYPE C, 35 FT. ARM OR 10.7 M ARM	9023235	1940	0030		
\$10,292.00	\$10,292.00	1.00	EA	1.00	0.00	1.00	POST, TYPE C, 50 FT. ARM OR 10.7 M ARM	9023250	1950			
										0030		
\$23,860.00	\$11,930.00	2.00	EA	4.00	0.00	4.00	POST, TYPE C, 55 FT. ARM	9023255	1960	0030		
\$0.00	\$12,945.00	0.00	EA	0.00	-1.00	1.00	POST, TYPE B, LONGEST ARM 35 FT. OR 10.7 M	9023335	1970	0030		
\$0.00	\$12,439.00	0.00	EA	0.00	-1.00	1.00	POST, TYPE B, LONGEST ARM 45 FT. OR 13.7 M	9023345	1980	0030		
\$14,962.08	\$13,359.00	1.12	EA	3.00	0.00	3.00	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	9024283	1990			
\$10,158.40	\$12,698.00	0.80	EA	4.00	0.00	4.00	VIDEO DETECTION SYSTEM	9024975	2000			
\$6,497.40	\$10.20	637.00	LF	1,334.00	14.00	1,320.00	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	9025300	2010	0030		
\$20,033.00	\$23.00	871.00	LF	844.00	0.00	844.00	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	9027300	2020	0030		
\$0.00	\$0.95	0.00	LF	3,391.00	41.00	3,350.00	CABLE, 8 AWG 1 CONDUCTOR, POWER	9028208	2030	0030		
\$935.00	\$0.50	1,870.00	LF	3,445.00	-285.00	3,730.00	CABLE, 16 AWG 2 CONDUCTOR	9028308	2040	0030		
\$2,123.00	\$1.10	1,930.00	LF	3,463.00	-287.00	3,750.00	CABLE, 16 AWG 5 CONDUCTOR	9028310	2050	0030		
\$5,824.00	\$1.60	3,640.00	LF	6,447.00	-343.00	6,790.00	CABLE, 16 AWG 7 CONDUCTOR	9028311	2060	0030		
\$1,204.00	\$602.00	2.00	EA	10.00	0.00	10.00	PULL BOX, PREFORMED CLASS 1	9028810	2070	0030		
\$12,210.00	\$1,221.00	10.00	EA	8.00	0.00	8.00	PULL BOX, PREFORMED CLASS 2	9028811	2080	0030		
\$1,642.00	\$1,642.00	1.00	EA	3.00	0.00	3.00	PULL BOX, PREFORMED CLASS 3	9028812	2090	0030		
\$11,948.00	\$1,160.00	10.30	CUYD	43.00	-1.00	44.00	BASE, CONCRETE	9029100	2100	0030		
\$22,932.00	\$65,520.00	0.35	LS	1.00	0.00	1.00	MISC.TRAFFIC SIGNAL MAINTENANCE AND PROGRAMMING	9029901	2110	0030		
\$0.00	\$3,214.00	0.00	EA	3.00	0.00	3.00	MISC.ATC TRAFFIC SIGNAL CONTROLLER	9029902	2120	0030		
\$0.00	\$715.00	0.00	EA	24.00	0.00	24.00	MISC.AUDIBLE PEDESTRIAN PUSH BUTTON AND SIGNING	9029902	2130	0030		
\$0.00	\$14,267.00	0.00	EA	1.00	0.00	1.00	MISC.COMBINATION PAD MOUNTED 120V/240V POWER SUPPLY AND LIGHTING CONTROLLER WITH UPS	9029902	2140	0030		
\$0.00	\$3,863.00	0.00	EA	1.00	0.00	1.00	MISC.CONCRETE TRANSFORMER PAD	9029902	2150	0030		
\$4,500.00	\$450.00	10.00	EA	22.00	0.00	22.00	MISC.Countdown Pedestrian Signal Head, Type 1S	9029902	2160	0030		
\$0.00	\$4,795.00	0.00	EA	1.00	0.00	1.00	MISC.Install 55' Arm on Existing Signal Post	9029902	2170	0030		
\$0.00	\$1,010.00	0.00	EA	3.00	0.00	3.00	MISC.NETWORK CONNECTED SIGNAL MONITOR	9029902	2180	0030		
\$0.00	\$10.20	0.00	LF	255.00	0.00	255.00	MISC.3" PVC CONDUIT WITH PULL TAPE	9029903	2190	0030		
\$0.00	\$1,400.00	0.00	CUYD	12.70	2.10	10.60	CONCRETE FOOTINGS, EMBEDDED	9031010	2200	0040		
\$67,584.00	\$1,200.00	56.32	CUYD	79.00	-3.30	82.30	CONCRETE FOOTINGS, BOLT DOWN	9031020	2210	0040		
\$0.00	\$4.50	0.00	LB	4,910.00	1,760.00	3,150.00	STRUCTURAL STEEL POSTS	9031210	2220	0040		
ψ0.00	\$3.75	0.00	LB	5,090.00	-300.00	5,390.00	PIPE POSTS	9031220	2230	0040		

Revision 4/1/2020 Page 24 of 108



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Q	uantities	and Valu	ies are	based on I	Report Generated date and can differ from the posted a	mount at the	time the Es	timate was	Generat	ed.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200515-F15	J6I2222	0040	2240	9031270A	2 IN. PSST POST - 12 GA.	60.00	0.00	60.00	LF	0.00	\$12.00	\$0.00
		0040	2250	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	21.00	0.00	21.00	LF	0.00	\$40.00	\$0.00
		0040	2260	9035004A	SH-FLAT SHEET	598.00	0.00	598.00	SQFT	0.00	\$21.00	\$0.00
		0040	2270	9035011A	ST-STRUCTURAL	2,364.00	3.00	2,367.00	SQFT	1,698.00	\$24.00	\$40,752.00
		0040	2280	9035069A	SHF-FLAT SHEET FLUORESCENT	93.00	0.00	93.00	SQFT	0.00	\$24.00	\$0.00
		0040	2290	9035071A	STF-STRUCTURAL FLUORESCENT	390.00	0.00	390.00	SQFT	243.00	\$26.00	\$6,318.00
		0040	2300	9036036	TUBULAR SUPPORT, TYPE C-2315-20	2.00	0.00	2.00	EA	0.00	\$12,950.00	\$0.00
		0040	2310	9036042	TUBULAR SUPPORT, TYPE C-2018-28	2.00	-2.00	0.00	EA	0.00	\$20,000.00	\$0.00
		0040	2320	9039901	MISC.SIGN 12 CANTILEVER BOX TRUSS, 30 FT ARM	1.00	0.00	1.00	LS	0.00	\$29,000.00	\$0.00
		0040	2330	9039901	MISC.SIGN 4 SPAN BOX TRUSS (98 FT)	1.00	0.00	1.00	LS	1.00	\$66,000.00	\$66,000.00
		0040	2340	9039901	MISC.SIGN 8 SPAN BOX TRUSS (83 FT-5 IN)	1.00	0.00	1.00	LS	0.00	\$52,500.00	\$0.00
		0040	2350	9039901	MISC.SPECIAL STREET NAME BRIDGE MOUNTED SIGNS	1.00	0.00	1.00	LS	0.00	\$20,000.00	\$0.00
		0050	2360	9108208	CABLE, 8 AWG, 1 CONDUCTOR, POWER	2,510.00	0.00	2,510.00	LF	0.00	\$1.00	\$0.00
		0050	2370	9108408	WIRE, 8 AWG, BARE NEUTRAL	1,010.00	0.00	1,010.00	LF	0.00	\$1.00	\$0.00
		0050	2380	9109100	BASE, CONCRETE	2.00	0.00	2.00	CUYD	0.00	\$1,726.00	\$0.00
		0050	2390	9109230	DYNAMIC MESSAGE SIGN ASSEMBLY, INSTALLED	1.00	-1.00	0.00	EA	0.00	\$9,413.00	\$0.00
		0050	2400	9109901	MISC.ITS ASSET MANAGEMENT TOOL	1.00	0.00	1.00	LS	0.00	\$2,797.00	\$0.00
		0050	2410	9109902	MISC.ADJUST EXISTING P.B. TO GRADE	1.00	0.00	1.00	EA	0.00	\$1.335.00	\$0.00
		0050	2420	9109902		12.00	0.00	12.00	EA	1.00	\$100.00	\$100.00
		0050	2430	9109902	MISC.BUTTERFLY DMS STRUCTURE	1.00	0.00	1.00	EA	0.00	\$55,944.00	\$0.00
		0050 24 0050 24 0050 24	2440	9109902	MISC.CCTV EXTENSION POLE, 20' METALLICFINISH	1.00	0.00	1.00	EA	0.00	\$1,554.00	\$0.00
			2450	9109902	MISC.FIBER OPTIC FUSION SPLICE	310.00	48.00	358.00	EA	272.00	\$39.00	\$10,608.00
			2460	9109902	MISC.FIBER OPTIC JUMPER,SM, FURNISH AND INSTALL	34.00	0.00	34.00	EA		\$22.00	\$10,000.00
			2470	9109902		42.00		42.00	EA	7.00	\$10.00	
					MISC.FIBER OPTIC PIGTAIL, SM, FURNISH AND INSTALL		0.00			26.00		\$260.00
		0050	2480	9109902	MISC.FIELD TERMINAL CABINET, TYPE 7, FURNISH AND INSTALL	1.00	0.00	1.00	EA	0.00	\$3,314.00	\$0.00
		0050	2490	9109902	MISC.INSTALL CCTV CAMERA ASSEMBLY	1.00	0.00	1.00	EA	0.00	\$883.00	\$0.00
		0050	2500	9109902	MISC.INSTALL CONDUIT INTO EXISTING BOX	5.00	0.00	5.00	EA	0.00	\$210.00	\$0.00
		0050	2510	9109902	MISC.ITS PULL BOX, CLASS 5	5.00	0.00	5.00	EA	0.00	\$1,842.00	\$0.00
		0050	2520	9109902	MISC.ITS PULL BOX, CLASS 2	1.00	0.00	1.00	EA	0.00	\$1,554.00	\$0.00
		0050	2530	9109902	MISC.SIGN STRUCTURE BASE MESH	1.00	0.00	1.00	EA	0.00	\$310.00	\$0.00
		0050	2540	9109902	MISC.UNDERGROUND FIBER CABLE SPLICE ENCLOSURE	2.00	2.00	4.00	EA	2.00	\$621.00	\$1,242.00
		0050	2550	9109902	MISC.WALL-MOUNTED FIBER INTERCONNECT CENTER, FURNISH AND INSTALL	7.00	0.00	7.00	EA	0.00	\$350.00	\$0.00
		0050	2560	9109903	MISC.24 STRAND, SINGLE MODE FIBER OPTIC CABLE	7,760.00	0.00	7,760.00	LF	7,760.00	\$1.85	\$14,356.00
		0050	2570	9109903	MISC.72 STRAND, SINGLE MODE FIBER OPTIC CABLE	4,200.00	0.00	4,200.00	LF	4,200.00	\$2.05	\$8,610.00
		0050	2580	9109903	MISC.CAT-5 ETHERNET CABLE	200.00	0.00	200.00	LF	0.00	\$1.70	\$0.00
		0050	2590	9109903	MISC.Conduit, PVC, PUSHED, 2"	399.00	0.00	399.00	LF	399.00	\$16.45	\$6,563.55
		0050	2600	9109903	MISC.CONDUIT, PVC, TRENCH, 2"	1,083.00	0.00	1,083.00	LF	0.00	\$5.90	\$0.00
		0070	2610	2163000	PARTIAL REMOVAL OF EXISTING BRIDGE DECK	2,033.00	0.00	2,033.00	SQFT	2,033.00	\$10.00	\$20,330.00
		0070	2620	2163502	PARTIAL REMOVAL OF SUBSTRUCTURE CONCRETE	1.00	0.00	1.00	LS	1.00	\$9,200.00	\$9,200.00
		0070	2630	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT	41.00	0.00	41.00	LF	41.00	\$425.00	\$17,425.00
		0070	2640	5031010△	CONCRETE BRIDGE APPROACH SLAB (MAJOR ROAD)	59.00	0.00	59.00	SQYD	59.00	\$355.00	\$20,945.00
		0070	2650	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	1.00	0.00	1.00	CUYD	1.00	\$5,050.00	\$5,050.00
		0070	2660	7034001	CLASS B-1 CONCRETE	0.70	0.00	0.70	CUYD	0.70	\$12,650.00	\$8,855.00
		0070	2670	7034001	SLAB ON STEEL	212.00	2.00	214.00	SQYD	214.00	\$470.00	\$100,580.00
			2680	7034212	CLASS B-2 CONCRETE	3.50	0.00	3.50	CUYD	3.50	\$6,530.00	\$22,855.00
		0070										
		0070	2690	7034610	CORRAL CURB	182.00	0.00	182.00	LF	142.00	\$117.00	\$16,614.00

Revision 4/1/2020 Page 25 of 108



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Im.CONTRACT	Project No.	Category	Line No.	ltem Code	Report Generated date and can differ from the posted an Description	Bid Quantity	time the Es Net Change	Total Current	General Unit	Total Posted	Unit Price	Total Value POSTED To Date (See report	
	110.		110.	0000		quantity	Order	Quantity		Approved Qty		generated date)	
00515-F15	J6I2222	0070	2700	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	1,275.00	45.00	1,320.00	SQFT	1,320.00	\$158.00	\$208,560.00	
		0070	2710	7040113	CLEANING AND EPOXY COATING	6,834.00	-6,834.00	0.00	SQFT	0.00	\$3.36	\$0.00	
		0070	2720	7049904	MISC.BARRIER CURB REPAIR (UNFORMED	195.00	-28.00	167.00	SQFT	167.00	\$175.00	\$29,225.00	
		0070	2730	7101000	REINFORCING STEEL (EPOXY COATED)	850.00	0.00	850.00	LB	850.00	\$3.00	\$2,550.00	
		0070	2740	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$1,584.52	\$0.00	
		0070	2750	7123130	REHABILITATE BEARING	8.00	0.00	8.00	EA	0.00	\$3,712.50	\$0.00	
		0070	2760	7123620	DRAINAGE SYSTEM (ON STRUCTURE)	1.00	0.00	1.00	LS	0.00	\$10,500.00	\$0.0	
		0070	2770	7129901	MISC.FLUSH DRAINAGE SYSTEM AND EXPANSION JOINTS	1.00	0.00	1.00	LS	1.00	\$20,000.00	\$20,000.0	
		0070	2780	7129902	MISC.FATIGUE CRACK REPAIR	1.00	0.00	1.00	EA	1.00	\$6,516.00	\$6,516.0	
		0070	2790	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	41.00	0.00	41.00	LF	41.00	\$490.00	\$20,090.0	
		0071	2800	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	25.00	0.00	25.00	SQFT	0.00	\$158.00	\$0.0	
		0071	2810	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	1,483.00	886.00	2,369.00	SQFT	2,369.00	\$158.00	\$374,302.0	
		0071	2820	7040113	CLEANING AND EPOXY COATING	5,621.00	-5,621.00	0.00	SQFT	0.00	\$3.04	\$0.0	
		0071	2830	7049904	MISC.BARRIER CURB REPAIR (UNFORMED)	142.00	189.00	331.00	SQFT	331.00	\$175.00	\$57,925.0	
		0071	2840	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$3,678.35	\$0.0	
		0071	2850	7121000	FABRICATED STRUCTURAL CARBON STEEL (MISC)	290.00	0.00	290.00	LB	0.00	\$23.00	\$0.0	
		0071	2860	7123130	REHABILITATE BEARING	5.00	0.00	5.00	EA	0.00	\$2,570.00	\$0.0	
		0071	2875	7125111	INTERMEDIATE FIELD COAT (SYSTEM G)	1.00	0.00	1.00	LS	0.00	\$1,330.80	\$0.0	
		0071	2885	7125112	FINISH FIELD COAT (SYSTEM G)	1.00	0.00	1.00	LS	0.00	\$475.20	\$0.0	
		0071	2890	7129901	MISC.FLUSH DRAINAGE SYSTEM AND EXPANSION JOINTS	1.00	0.00	1.00	LS	1.00	\$20,000.00	\$20,000.0	
		0072 2 0073 2 0073 2	2900	7129902	MISC.FATIGUE CRACK REPAIR	3.00	0.00	3.00	EA	2.00	\$2,040.00	\$4,080.0	
			2910	7121060	FABRICATED SIGN SUPPORT BRACKETS	1.00	0.00	1.00	LS	1.00	\$3,600.00	\$3,600.0	
			2920	2065500	TEMPORARY SHORING	1.00	0.00	1.00	LS	1.00	\$150,000.00	\$150,000.0	
			2930	7033009	AESTHETIC CONCRETE STAIN	1.00	0.00	1.00	LS	1.00	\$14,877.00	\$14,877.0	
			2940	7201000	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	8,672.00	0.00	8,672.00	SQFT	8,672.00	\$62.50	\$542,000.	
		0074	2955	5031011A			-258.00	0.00	SQYD	0.00	\$145.00	\$0.	
		0074	2960	6079903	` '	258.00		280.00 -280.00	0.00	LF	0.00	\$130.00	\$0.0
		0074	2970	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	820.00	7.00	827.00	LF	741.00	\$68.00	\$50,388.0	
		0074	2980	7025001	DYNAMIC PILE TESTING	2.00	0.00	2.00	EA	2.00	\$2,325.00	\$4,650.0	
		0074	2990	7027000	PILE POINT REINFORCEMENT	14.00	0.00	14.00	EA	14.00	\$80.00	\$1,120.0	
			3000			56.40			CUYD	70.30	\$565.00	, , ,	
		0074		7032003	CLASS B CONCRETE (SUBSTRUCTURE)	288.00	13.90	70.30				\$39,719.	
		0074	3010	7034219A 7034221	TYPE D BARRIER SLAB ON CONCRETE NU-GIRDER		-288.00		LF	0.00	\$115.00 \$335.00	\$0.0	
		0074				760.00	-760.00	0.00	LF			\$0.0	
		0074	3030	7034630	CONCRETE CURB (BRIDGE RAIL)	306.00	-306.00	0.00		0.00	\$75.00	\$0.0	
		0074	3040	7056022	NU 43, PRESTRESSED CONCRETE NU-GIRDER	894.00	-894.00	0.00	LF	0.00	\$215.00	\$0.	
		0074	3050	7071000	CONDUIT SYSTEM ON STRUCTURE	1.00	-1.00	0.00	LS	0.00	\$5,927.00	\$0.	
		0074	3060	7121060	FABRICATED SIGN SUPPORT BRACKETS	1.00	0.00	1.00	LS	0.00	\$7,100.00	\$0.0	
		0074	3070	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	0.00	\$2,500.00	\$0.0	
		0074	3080	7161000	PLAIN NEOPRENE BEARING PAD	16.00	0.00	16.00	EA	16.00	\$200.00	\$3,200.	
		0074	3090	7201300	PIPE PILE SPACERS	14.00	-14.00	0.00	EA	0.00	\$1,000.00	\$0.	
		0074	3100	9019902	MISC.ORNAMENTAL LUMINAIRE	10.00	4.00	14.00	EA	0.00	\$1,658.00	\$0.	
		0075	3110	7033009	AESTHETIC CONCRETE STAIN	1.00	-1.00	0.00	LS	0.00	\$17,530.50	\$0.0	
		0075	3120	7201000	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	7,637.00	-7,637.00	0.00	SQFT	0.00	\$110.00	\$0.	
		0076	3130	7033009	AESTHETIC CONCRETE STAIN	1.00	-1.00	0.00	LS	0.00	\$6,525.00	\$0.	
		0076	3140	7201000	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	3,410.00	-3,410.00	0.00	SQFT	0.00	\$110.00	\$0.0	
		0077	3150	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$146,000.00	\$146,000.0	
		0077	3160	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	250.00	0.00	250.00	SQYD	0.00	\$155.00	\$0.0	

Revision 4/1/2020 Page 26 of 108



Total Paid / All Items / All Estimates (Including this Estimate)

lote: Posted Q	uantities	and Valu	ies are	based on F	Report Generated date and can differ from the posted a	mount at the	time the Es	timate was	Generat	ted.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200515-F15	J6I2222	0077	3170	6079903	MISC.(60 IN.) DECORATIVE PEDESTRIAN FENCE	404.00	0.00	404.00	LF	0.00	\$130.00	\$0.00
		0077	3180	7011105	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	30.00	0.00	30.00	LF	25.50	\$490.00	\$12,495.00
		0077	3190	7011204	ROCK SOCKETS (3 FT 0 IN. DIA.)	30.00	0.00	30.00	LF	30.00	\$815.00	\$24,450.00
		0077	3200	7011300	VIDEO CAMERA INSPECTION	3.00	0.00	3.00	EA	3.00	\$450.00	\$1,350.00
		0077	3210	7011400	FOUNDATION INSPECTION HOLES	60.00	0.00	60.00	LF	60.00	\$140.00	\$8,400.00
		0077	3220	7011600	SONIC LOGGING TESTING	3.00	0.00	3.00	EA	3.00	\$2,100.00	\$6,300.00
		0077	3230	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	462.00	0.00	462.00	LF	462.00	\$75.00	\$34,650.00
		0077	3240	7025001	DYNAMIC PILE TESTING	2.00	0.00	2.00	EA	2.00	\$2,350.00	\$4,700.00
		0077	3250	7026000	PRE-BORE FOR PILING	252.00	0.00	252.00	LF	252.00	\$180.00	\$45,360.00
		0077	3260	7027000	PILE POINT REINFORCEMENT	14.00	0.00	14.00	EA	14.00	\$80.00	\$1,120.00
		0077	3270	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	49.60	0.00	49.60	CUYD	49.60	\$800.00	\$39,680.00
		0077	3280	7034003	CLASS B-1 CONCRETE (SUBSTRUCTURE)	60.30	0.00	60.30	CUYD	60.30	\$1,055.00	\$63,616.50
		0077	3290	7034219A	TYPE D BARRIER	404.00	0.00	404.00	LF	0.00	\$130.00	\$0.00
		0077	3300	7034221	SLAB ON CONCRETE NU-GIRDER	1,175.00	0.00	1,175.00	SQYD	1,116.25	\$290.00	\$323,712.50
		0077	3310	7034630	CONCRETE CURB (BRIDGE RAIL)	447.00	0.00	447.00	LF	0.00	\$62.00	\$0.00
		0077	3320	7056021	NU 35, PRESTRESSED CONCRETE NU-GIRDER	1,268.00	0.00	1,268.00	LF	1,268.00	\$210.00	\$266,280.00
		0077	3330	7061060	REINFORCING STEEL (BRIDGES)	18,420.00	-18,420.00	0.00	LB	0.00	\$1.00	\$0.00
		0077	3340	7071000	CONDUIT SYSTEM ON STRUCTURE	1.00	0.00	1.00	LS	0.00	\$26,383.00	\$0.00
		0077	3350	7079901	MISC.CONDUIT SYSTEM ON STRUCTURE - ATT TELPHONE	1.00	0.00	1.00	LS	1.00	\$3,730.00	\$3,730.00
		0077	3355	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	1.00	\$8,330.05	\$8,330.05
		0077	3370	7121060	FABRICATED SIGN SUPPORT BRACKETS	1.00	0.00	1.00	LS	0.00	\$27,500.00	\$0.00
		0077 3	3380	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	2.00	\$2,500.00	\$5,000.00
			3390	7161003	LAMINATED NEOPRENE BEARING PAD (TAPERED)	28.00	0.00	28.00	EA	28.00	\$425.00	\$11,900.00
			3400	7201300	PIPE PILE SPACERS	14.00	0.00	14.00	EA	14.00	\$855.00	\$11,970.00
		0077	3410	9019903	MISC.ORNAMENTAL LUMINAIRE	12.00	0.00	12.00	LF	0.00	\$1,658.00	\$0.00
		0078	3420	7033009	AESTHETIC CONCRETE STAIN	1.00	0.00	1.00	LS	1.00	\$7,856.10	\$7,856.10
		0078	3430	7201000	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	4,182.00	0.00	4,182.00	SQFT	4,182.00	\$80.00	\$334,560.00
		0079	3440	7033009	AESTHETIC CONCRETE STAIN	1.00	0.00	1.00	LS	1.00	\$3,654.00	\$3,654.00
		0079	3450	7201000	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	2,521.00	0.00	2,521.00	SQFT	2,521.00	\$80.00	\$201,680.00
		0080	3460	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	0.90	\$655,000.00	\$589,500.00
		0080	3470	5031010A	BRIDGE APPROACH SLAB (MAJOR ROAD)	81.00	0.00	81.00	SQYD	0.00	\$200.00	\$0.00
		0080	3480	7011110	DRILLED SHAFTS (6 FT. 0 IN. DIA.)	380.40	0.00	380.40	LF	246.16	\$485.00	\$119,387.60
		0080	3490	7011209	ROCK SOCKETS (5 FT 6 IN. DIA.)	108.00	0.00	108.00	LF	108.00	\$2,555.00	\$275,940.00
		0080	3500	7011300	VIDEO CAMERA INSPECTION	6.00	0.00	6.00	EA	4.00	\$550.00	\$2,200.00
		0080	3510	7011400	FOUNDATION INSPECTION HOLES	174.00	0.00	174.00	LF	174.00	\$155.00	\$26,970.00
		0080	3520	7011600	SONIC LOGGING TESTING	6.00	0.00	6.00	EA	4.00	\$4,250.00	\$17,000.00
		0080	3530	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	430.00	0.00	430.00	LF	0.00	\$85.00	\$0.00
		0080	3540	7025001	DYNAMIC PILE TESTING	1.00	0.00	1.00	EA	0.00	\$2,700.00	\$0.00
		0080	3550	7027000	PILE POINT REINFORCEMENT	5.00	0.00	5.00	EA	0.00	\$80.00	\$0.00
		0080	3560	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	21.70	0.00	21.70	CUYD	0.00	\$745.00	\$0.00
		0080	3570	7034003	CLASS B-1 CONCRETE (SUBSTRUCTURE)	379.50	0.00	379.50	CUYD	0.00	\$710.00	\$0.00
		0080	3580	7034212	SLAB ON STEEL	304.00	0.00	304.00	SQYD	0.00	\$335.00	\$0.00
		0080	3590	7034219A	TYPE D BARRIER	1,779.00	0.00	1,779.00	LF	0.00	\$58.00	\$0.00
		0080	3600	7034221	SLAB ON CONCRETE NU-GIRDER	2,430.00	0.00	2,430.00	SQYD	0.00	\$340.00	\$0.00
		0080	3610	7056023	NU 53, PRESTRESSED CONCRETE NU-GIRDER	1,504.00	0.00	1,504.00	LF	0.00	\$270.00	\$0.00
		0080	3620	7056025	NU 70, PRESTRESSED CONCRETE NU-GIRDER	1,151.00	0.00	1,151.00	LF	0.00	\$270.00	\$0.00
			3630	7061060	REINFORCING STEEL (BRIDGES)	170,450.00	0.00	170,450.00	LB	134,380.00	\$0.85	

Revision 4/1/2020 Page 27 of 108



Total Paid / All Items / All Estimates (Including this Estimate)

vote: Posted Q	uantities	and Valu	ies are	based on I	Report Generated date and can differ from the posted am	ount at the	time the Es	timate was	Generat	ed.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200515-F15	J6I2222	0080	3640	7061070	MECHANICAL BAR SPLICE	480.00	0.00	480.00	EA	152.00	\$95.00	\$14,440.00
		0800	3650	7101000	REINFORCING STEEL (EPOXY COATED)	12,940.00	0.00	12,940.00	LB	0.00	\$1.15	\$0.00
		0080	3660	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$9,744.80	\$0.00
		0800	3670	7120900	EXPANSION DEVICE (FINGER PLATE)	23.00	0.00	23.00	LF	0.00	\$2,400.00	\$0.00
		0080	3680	7121121	FABRICATED STRUCTURAL LOW ALLOY STEEL (PLATE GIRDER) A709, GRADE 50	79,550.00	0.00	79,550.00	LB	0.00	\$3.19	\$0.00
		0800	3690	7123210	EARTH QUAKE RESTRAINER ASSEMBLIES	3.00	0.00	3.00	EA	0.00	\$13,125.00	\$0.00
		0080	3700	7123301	STEEL INTERMEDIATE DIAPHRAGM FOR P/S CONCRETE GIRDERS	30.00	0.00	30.00	EA	0.00	\$680.00	\$0.00
		0800	3710	7123620	DRAINAGE SYSTEM (ON STRUCTURE)	1.00	0.00	1.00	LS	0.00	\$80,000.00	\$0.00
		0800	3720	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	500.00	0.00	500.00	SQFT	0.00	\$81.40	\$0.00
		0800	3730	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	500.00	0.00	500.00	SQFT	0.00	\$2.00	\$0.00
		0800	3740	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	5,000.00	0.00	5,000.00	SQFT	0.00	\$6.65	\$0.00
		0800	3750	7125370A	FINISH FIELD COAT (SYSTEM G)	2,700.00	0.00	2,700.00	SQFT	0.00	\$2.38	\$0.00
		0800	3760	7129903	MISC.MODULAR EXPANSION JOINT SYSTEM	24.00	0.00	24.00	LF	0.00	\$2,400.00	\$0.00
		0800	3770	7151001	VERTICAL DRAIN AT END BENTS	1.00	0.00	1.00	EA	0.00	\$2,500.00	\$0.00
		0800	3780	7161000	PLAIN NEOPRENE BEARING PAD	8.00	0.00	8.00	EA	0.00	\$225.00	\$0.00
		0800	3790	7161002	LAMINATED NEOPRENE BEARING PAD	3.00	0.00	3.00	EA	0.00	\$250.00	\$0.00
		0800	3800	7161003	LAMINATED NEOPRENE BEARING PAD (TAPERED)	21.00	0.00	21.00	EA	0.00	\$320.00	\$0.00
		0800	3810	7162000	LAMINATED NEOPRENE BEARING PAD ASSEMBLY	16.00	0.00	16.00	EA	0.00	\$1,520.00	\$0.00
		0800	3820	7163000	TYPE N PTFE BEARING	3.00	0.00	3.00	EA	0.00	\$2,500.00	\$0.00
		0001 5 0001 5	3830	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	24.00	0.00	24.00	LF	0.00	\$510.00	\$0.00
			5001	6189901	MISC.Adjust Mobilization for Contract Bond	0.00	1.00	1.00	LS	1.00	\$107,907.00	\$107,907.00
			5002	6141121	CURVED VANE GRATE AND FRAME (4 FT. X 2 FT. OR 1200MM X 600MM)	0.00	18.00	18.00	EA	9.00	\$1,400.00	\$12,600.00
			5003	6149902	MISC.Parallel Grate and Bearing Plate (4 FT.x2FT.)	0.00	27.00	27.00	EA	10.00	\$1,400.00	\$14,000.00
		0050	5004	9109901	MISC.DMS Board Removal	0.00	1.00	1.00	LS	1.00	\$12,673.51	\$12,673.51
		0001	5005	6173700B	TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED	0.00	638.00	638.00	LF	638.00	\$40.79	\$26,024.02
		0001	5006	2063100	CLASS 3 EXCAVATION IN ROCK	0.00	18.50	18.50	CUYD	18.50	\$85.00	\$1,572.50
		0050	5007	9109901	MISC.Colored Dynamic Message Sign	0.00	1.00	1.00	LS	0.00	\$110,608.04	\$0.00
		0001	5008	6149902	MISC.MISC. MSD Manhole Frame and Cover	0.00	19.00	19.00	EA	8.00	\$400.00	\$3,200.00
		0001	5009	2032000	CLASS C EXCAVATION	0.00	1,139.90	1,139.90	CUYD	1,139.90	\$75.00	\$85,492.50
		0001	5010	7209901	MISC.Rock Fill Alternative Ground Improvement	0.00	1.00	1.00	LS	1.00	\$7,822.60	\$7,822.60
		0077	5011	7101000	REINFORCING STEEL (EPOXY COATED)	0.00	18,950.00	18,950.00	LB	18,950.00	\$1.33	\$25,203.50
		0001	5012	2029901	MISC.Barrier Wall Removal	0.00	1.00	1.00	LS	1.00	\$5,226.18	\$5,226.18
		0074	5013	7011105	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	0.00	202.80	202.80	LF	202.80	\$567.75	\$115,139.70
		0074	5014	7011204	ROCK SOCKETS (3 FT 0 IN. DIA.)	0.00	76.70	76.70	LF	76.70	\$917.10	\$70,341.57
		0074	5015	7101000	REINFORCING STEEL (EPOXY COATED)	0.00	24,760.00	24,760.00	LB	24,760.00	\$1.49	\$36,892.40
		0074	5016	7011300	VIDEO CAMERA INSPECTION	0.00	6.00	6.00	EA	6.00	\$577.50	\$3,465.00
		0074	5017	7011400	FOUNDATION INSPECTION HOLES	0.00	185.10	185.10	LF	185.10	\$136.50	\$25,266.15
		0074	5018	7011600	SONIC LOGGING TESTING	0.00	6.00	6.00	EA	6.00	\$4,593.00	\$27,558.00
		0074	5019	7061070	MECHANICAL BAR SPLICE	0.00	108.00	108.00	EA	108.00	\$140.70	\$15,195.60
		0001	5020	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	0.00	165.70	165.70	SQYD	165.70	\$110.00	\$18,227.00
		0001	5021	6131018	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	0.00	58.00	58.00	EA	58.00	\$12.00	\$696.00
		0001	5022	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	0.00	130.00	130.00	EA	130.00	\$15.00	\$1,950.00
		0001	5023	1046002	VALUE ENGINEERING	0.00	14,480.00	14,480.00	EA	14,480.00	\$1.00	\$14,480.00
		0001	5024	7269923	SEWER	0.00	701.00	701.00	LF	701.00	\$461.34	\$323,399.34
		0001	5025	7269922	SEWER	0.00	150,000.00	150,000.00	EA	147,772.00	\$1.00	\$147,772.00

Revision 4/1/2020 Page 28 of 108



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Project Category Line Item Description Bid Net Total Unit Total Unit Price Total Value POSTED

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200515-F15	J6I2222	0074	5026	7034003	CLASS B-1 CONCRETE (SUBSTRUCTURE)	0.00	99.80	99.80	CUYD	99.80	\$1,404.00	\$140,119.20
		0001	5027	2039907	MISC.MISC. Lightweight Fill	0.00	6,779.00	6,779.00	CUYD	4,693.00	\$64.50	\$302,698.50
		0074	5028	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	0.00	223.00	223.00	SQYD	0.00	\$149.00	\$0.00
		0074	5029	7034221	SLAB ON CONCRETE NU-GIRDER	0.00	1,269.00	1,269.00	SQYD	762.00	\$406.00	\$309,372.00
		0074	5030	7034630	CONCRETE CURB (BRIDGE RAIL)	0.00	377.00	377.00	LF	0.00	\$77.00	\$0.00
		0074	5031	7056022	NU 43, PRESTRESSED CONCRETE NU-GIRDER	0.00	1,485.00	1,485.00	LF	1,485.00	\$221.00	\$328,185.00
		0074	5032	7071000	CONDUIT SYSTEM ON STRUCTURE	0.00	1.00	1.00	LS	0.48	\$9,965.00	\$4,783.20
		0010	5033	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	0.00	50.00	50.00	LF	0.00	\$29.40	\$0.00
		0077	5034	6079903	MISC.(70in.) Decorative Pedestrian Fence	0.00	440.00	440.00	LF	0.00	\$152.25	\$0.00
		0074	5035	7026000	PRE-BORE FOR PILING	0.00	189.00	189.00	LF	189.00	\$154.00	\$29,106.00
		0074	5036	7034216	TYPE H BARRIER	0.00	446.00	446.00	LF	0.00	\$129.00	\$0.00
		0074	5037	7101000	REINFORCING STEEL (EPOXY COATED)	0.00	31,150.00	31,150.00	LB	31,150.00	\$1.19	\$37,068.50
		0074	5038	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	0.00	1.00	1.00	LS	1.00	\$13,118.70	\$13,118.70
		0074	5039	7123620	DRAINAGE SYSTEM (ON STRUCTURE)	0.00	1.00	1.00	LS	0.00	\$58,912.00	\$0.00
		0074	5040	7161002	LAMINATED NEOPRENE BEARING PAD	0.00	24.00	24.00	EA	24.00	\$300.00	\$7,200.00
		0074	5041	7161003	LAMINATED NEOPRENE BEARING PAD (TAPERED)	0.00	8.00	8.00	EA	8.00	\$360.00	\$2,880.00
		0030	5042	9023340	POST, TYPE B, LONGEST ARM 40 FT. OR 12.2 M	0.00	1.00	1.00	EA	0.00	\$15,863.40	\$0.00
		0030	5043	9023340	POST, TYPE B, LONGEST ARM 40 FT. OR 12.2 M	0.00	1.00	1.00	EA	0.00	\$15,319.50	\$0.00
		0074	5044	6116010A	SLOPE PROTECTION	0.00	544.00	544.00	SQYD	489.60	\$150.00	\$73,440.00
		0074	5045	1099902	MISC.Value Engineering Design Costs - VECP #20-29	0.00	214,535.00	214,535.00	EA	214,535.00	\$1.00	\$214,535.00
		0074	5046	1046002	VALUE ENGINEERING	0.00	279,927.42	279,927.42	EA	279,927.42	\$1.00	\$279,927.42
		0001	5047	7250415	15 IN. PIPE GROUP C	0.00	88.00	88.00	LF	88.00	\$70.00	\$6,160.00
		0001	5048	7250418	18 IN. PIPE GROUP C	0.00	99.00	99.00	LF	99.00	\$80.00	\$7,920.00
		0001	5049	7320618A	18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	0.00	2.00	2.00	EA	2.00	\$900.00	\$1,800.00
		0001	5050	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	0.00	5.30	5.30	CUYD	0.00	\$100.00	\$0.00
		0001	5051	6096041	PLACING TYPE 1 ROCK DITCH LINER	0.00	5.30	5.30	CUYD	0.00	\$100.00	\$0.00
		0001	5052	6044011	PIPE COLLAR, TYPE A	0.00	2.00	2.00	EA	0.00	\$2,468.00	\$0.00
		0001	5053	1099902	MISC.Value Engineering Design Costs VECP #20-49	0.00	46,410.00	46,410.00	EA	46,410.00	\$1.00	\$46,410.00
		0001	5054	1046002	VALUE ENGINEERING	0.00	102,477.40	102,477.40	EA	102,477.40	\$1.00	\$102,477.40
		0070	5055	7129901	MISC.Fabricated Structural Carbon Steel A150114	0.00	1.00	1.00	LS	0.00	\$40,590.00	\$0.00
		0070	5056	7129901	MISC.Field Application of Epoxy Mastic Primer A150114	0.00	1.00	1.00	LS	0.00	\$1,501.50	\$0.00
		0070	5057	7125112	FINISH FIELD COAT (SYSTEM G)	0.00	1.00	1.00	LS	0.00	\$1,501.50	\$0.00
		0070	5058	7125111	INTERMEDIATE FIELD COAT (SYSTEM G)	0.00	1.00	1.00	LS	0.00	\$1,501.50	\$0.00
		0070	5059	7125100	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	0.00	1.00	1.00	LS	0.00	\$19,215.00	\$0.00
		0071	5060	7129901	MISC.Fabricated Structural Carbon Steel A150115	0.00	1.00	1.00	LS	0.00	\$92,520.40	\$0.00
		0071	5061	7129901	MISC.Field Application of Epoxy Mastic Primer A150115	0.00	1.00	1.00	LS	0.00	\$2,478.00	\$0.00
		0071	5062	7125112	FINISH FIELD COAT (SYSTEM G)	0.00	1.00	1.00	LS	0.00	\$2,478.00	\$0.00
		0071	5063	7125111	INTERMEDIATE FIELD COAT (SYSTEM G)	0.00	1.00	1.00	LS	0.00	\$2,478.00	\$0.00
		0071	5064	7125100	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	0.00	1.00	1.00	LS	0.00	\$32,655.00	\$0.00
		0001	5065	2022010	REMOVAL OF IMPROVEMENTS	0.00	1.00	1.00	LS	1.00	\$2,799.26	\$2,799.26
		0020	5066	9019902	MISC.LED High Mast Luminaire	0.00	16.00	16.00	EA	0.00	\$2,146.73	\$0.00
	Project J	1612222 - To	otal Value	Posted to D	l Date as of Report Generated Date							\$17,266,592.80
200515-F15 Ove	rall - Tota	Value Pos	ted to Da	ate as of Rep	ort Generated Date							\$17,266,592.80

Revision 4/1/2020 Page 29 of 108



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J6l2222

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0020	2022010	REMOVAL OF IMPROVEMENTS	9/14/21	9/16/21	0.05	LS	Various locations	Mile 0		Mile 0		
0120	2063000	CLASS 3 EXCAVATION	9/3/21	9/13/21	148.00	CUYD	MH 203, MH 216, Structures # 211, 210, P-210, P-211, P-216	5+09.00		7+42.75		
			9/8/21	9/13/21	41.00	CUYD	Structures 204, 212, P-204, P-212					Ramp B
			9/14/21	9/16/21	108.00	CUYD	205, 206, 207, 209, 215, P-205, P-206, P-207, P-209,					Work done over the last several days.
				9/16/21	10.00	CLIVD	P-215 Adding 10 CY to adjust pay on 9/8 of this pay period	0		0		
			9/15/21	9/16/21	37.00		P-214, 214, 201	0		0		
0220	5041000	CONCRETE APPROACH PAVEMENT	9/14/21	9/16/21	33.50		I-64 WB Ramp E Concrete Approach- 33.5 SY	0		0		
0240	6039901	WATER - UTILITY ITEM	9/14/21	9/16/21	1.00	LS	Relocated fire hydrant in NW quadrant of Jefferson Ave &	0		0		
							64 on 9/1					
0380	6071102	MODIFIED CONCRETE GUTTER TYPE B	9/2/21	9/13/21	74.00 233.00	LF LF	I-64 EB S. Ewing Modified B Gutter Eastside I-64 WB N. Ewing Westside- 115'	0		0		
							I-64 WB N. Ewing Eastside- 118'					
0460		CONCRETE GUTTER TYPE B	9/14/21	9/16/21	127.00		I-64 WB just West of 22nd St	0		0		
0620	6141024 6149902	GRATES AND BEARING PLATES (5 FT X 3 FT) MISC. DRAINAGE FITTINGS	9/14/21	9/16/21	2.00		806 & 807 386 & 387	0		0		
0730	6179903	MISC. CONCRETE TRAFFIC BARRIER	9/14/21	9/16/21	60.00		Ramp A	U		U		
1000	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKI	9/14/21	9/16/21	0.10		Various surveying throughout the job for roadway,	0		0		
							drainage, and barrier					
1110	7261015	15 IN. PIPE GROUP A	9/3/21	9/13/21	109.00		P-211	6+31.50		7+42.75		
			9/8/21	9/13/21	72.00		P-212	7+42.75		8+17.00		
			9/14/21	9/16/21	63.00		P-209, P-205, P-207, P-206					Work done over the last several days.
				9/16/21	158.00		Adjusting pay for P-206 that was made on 9/14 of this pay period	0		0		
1100	7004040	ANN PIPE OPOUR A		9/16/21	85.00		P-214	F . 00 00		0.04.50		D 040 440 5
1120	7261018	18 IN. PIPE GROUP A	9/3/21	9/13/21	138.00	LF	P-216, P-210	5+09.00		6+31.50		P-216 (118LF) P-210 (20LF)
			9/8/21	9/13/21	18.00	LF	P-204	5+00.00		5+09.00		
			9/14/21	9/16/21	9.00	LF	P-215					Work done over the last several days.
				9/16/21	25.00	LF	Adjusting pay for P-215 that was made on 9/14 of this pay period	0		0		
1170	7311022	PRECAST CONCRETE DROP INLET 2 FT X 2 FT	9/14/21	9/16/21	17.00 -6.00		205, 207 Adjusting pay for DI 207 that was made on 9/14 of this	0		0		Work done over the last several days.
				0/10/21	0.00		pay period					
1180	7311042	PRECAST CONCRETE DROP INLET 4 FT X 2 FT	9/3/21	9/13/21	6.00		Inlet # 210 and # 211	6+31.50	20 RT	7+42.75	20 RT	
			9/8/21	9/13/21	3.00		Structure 204	5+00.00		5+00.00		
			9/14/21	9/16/21	8.00		206, 215, 209					Work done over the last several days.
4400	7044050	DECLAT COMPLETE DOOD BY ET 5 ET VA ET		9/16/21	5.00		201, 214	0.47.00		0.47.00		Ramp B
1190	7311053	PRECAST CONCRETE DROP INLET 5 FT X 3 FT	9/8/21	9/13/21	4.00	FI	Structure 212	8+17.00		8+17.00		Field measurement is 3.65 FT from flowline to the top the structure. Plan sheets show this value should be 1 FT; however this was not seen in the field.
1210	7319913	MISC. MANHOLES AND DROP INLETS	9/3/21	9/13/21	0.00	FT	MH #203 & #216	5+09.00	8.5 LT	6+31.50	6.0 LT	Manholes were placed on 9/2/21 See Gary's Explanation on Cogno's reports.
1310	8061016	SEDIMENT REMOVAL	9/14/21	9/16/21	35.00	CUYD	Various sediment removal for inlets through the job on 8/24 & 9/14	0		0		
1490	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	9/14/21	9/16/21	1,361.00	SQYD	I-64 WB after Ramp E Concrete Approach Lanes 1, 2, and 3	0		0		
1510	5021309	CONCRETE PAVEMENT (9 IN. NON-REINFORCED,	9/14/21	9/16/21	1,361.00	SQYD	I-64 WB after Ramp E Concrete Approach Lanes 1, 2, and 3	0		0		
1650	9013002	CONDUIT, 2 IN. RIGID, IN TRENCH	9/14/21	9/16/21	435.00	LF	Billboard Power Relocation at Ramp F	0		0		Change Order 18 was approved
1700	9015020	TRENCHING TYPE II	9/14/21	9/16/21	460.00	LF	Billboard power relocation at Ramp F	0		0		Change Order 18 was approved
1850	9019903	MISC. HIGHWAY LIGHTING	9/14/21	9/16/21	1,420.00	LF	Billboard power relocation at Ramp F	0		0		Change Order 18 was approved
1860	9020213	SIGNAL HEAD, TYPE 3S	9/15/21	9/16/21	1.00	EA	Jefferson					Install signal heads at Jefferson.
1870	9020513	SIGNAL HEAD, TYPE 3B		9/16/21	4.00		Jefferson					
			9/15/21	9/16/21	4.00	EA	Jefferson					Install signal heads at Jefferson.
1910	9022708	POST, SIGNAL 8 FT. OR 2.4 M	9/14/21		1.00	EA	Signal base 2 at WB ramps and Jefferson.					Work done on 9.10.21
1920		POST, SIGNAL 15 FT. OR 4.6 M		9/16/21	1.00		Ped post 1 at EB ramps and Jefferson.					Work done on 9.10.21
1950		POST, TYPE C, 50 FT. ARM OR 15.2 M ARM		9/16/21	1.00		Signal base 2 at EB ramps and Jefferson. Signal base 1 at WB ramps and Jefferson.					Work done on 9.10.21
1960	9023255	POST, TYPE C, 55 FT. ARM		9/16/21	1.00		,					Work done on 9.10.21
1990	9024283	CONTROLLER ASSEMBLY HOUSING, VIDEO DETECTION SYSTEM		9/16/21	0.12	EA	Jefferson and South intersection. Jefferson					Finish wiring controller
2000	9024973	VIDEO DETECTION STSTEM		9/16/21	0.56		Jefferson Signals					Install camera and wiring
2040	9028308	CABLE, 16 AWG 2 CONDUCTOR		9/16/21	1,870.00		Jefferson and south intersection at 64. Jefferson and west side of north intersection of 64.					1037 done on 9/13 883 done on 9/14
2050	9028310	CABLE, 16 AWG 5 CONDUCTOR	9/14/21	9/16/21	1,930.00	1 F	Jefferson and East and West ramps. Jefferson and south intersection at 64.					1049 from 9/13/21
2000	5520310	E. E.E., ISTANO G GONDOOTON	0,17/41	5, 10, Z I	1,000.00	Lr,	Jefferson and west side of north intersection of 64. Jefferson and East and West ramps.					881 from 9/14/21
2060	9028311	CABLE, 16 AWG 7 CONDUCTOR	9/14/21	9/16/21	2,464.00	LF	Jefferson and south intersection at 64. Jefferson and west side of north intersection of 64. Jefferson and East and West ramps.					2369 from 9/13/21 95 from 9/14/21
2160	9029902	MISC.	9/15/21	9/16/21	10.00	EA	Jefferson					Install Ped Heads
2640	5031010A	BRIDGE APPROACH SLAB (MAJOR ROAD)	9/3/21	9/15/21	59.00	SQYD	I-64 WB Ramp E Bridge A150114 Approach	0		0		
2720	7049904	MISC.	9/14/21	9/16/21	19.00	SQFT	Repairs installed at an earlier date	0		0		Change Order 17 was approved
2930	7033009	AESTHETIC CONCRETE STAIN	9/14/21	9/16/21	1.00	LS	MSE wall A79461	0		0		
3380	7151001	VERTICAL DRAIN AT END BENTS	9/7/21	9/13/21	1.00	EA	Ewing Bridge Bent 3.					
			9/14/21	9/16/21	1.00	EA	Bent 1 vertical drain	0		0		
3460	2160500	REMOVAL OF BRIDGES	9/14/21	9/16/21	0.10	LS	Payment update for bridge demolition (superstructure removed)	0		0		
5002	6141121	CURVED VANE GRATE AND FRAME(4 FT. X 2 FT	9/14/21	9/16/21	7.00	EA	DI 704, 713, 714, 715, 716, 717, & 718	0		0		
5008	6149902	MISC. DRAINAGE FITTINGS		9/16/21	2.00		MH 911 & 912	0		0		
5029	7034221	SLAB ON CONCRETE NU-GIRDER		9/16/21	191.00		22nd St. bridge steel					
5032		CONDUIT SYSTEM ON STRUCTURE	0/7/24	9/13/21	0.32	LS	22nd street bridge					Inspected by thill5

Revision 4/1/2020 Page 30 of 108



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
5032	7071000	CONDUIT SYSTEM ON STRUCTURE	9/8/21	9/13/21	0.16	LS	22nd street bridge					
5065	2022010	REMOVAL OF IMPROVEMENTS	9/14/21	9/16/21	1.00	LS	ADA ramp removal at the SE corner of the Jefferson bridge	0		0		Change Order 18 was approved

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 4/1/2020 Page 31 of 108



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	0050	CLASS A EXCAVATION	Price FUEL		4	Sep 2, 2020	SYSTEM	\$24.92	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					4	Sep 2, 2020	SYSTEM	\$7.00	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					5	Sep 16, 2020	SYSTEM	\$349.60	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					7	Oct 16, 2020	SYSTEM	\$800.00	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				9	Nov 16, 2020	SYSTEM	\$1,020.00	Reference Item Price Adjustment Index Adjustment Type applied is FUEL	
				10	Dec 2, 2020	SYSTEM	\$204.00	Reference Item Price Adjustment Index Adjustment Type applied is FUEL	
					11	Dec 16, 2020	SYSTEM	\$1,142.60	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					13	Jan 19, 2021	SYSTEM	\$201.00	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					14	Feb 2, 2021	SYSTEM	\$3,086.82	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					17	Mar 16, 2021	SYSTEM	\$5,917.63	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					18	Apr 2, 2021	SYSTEM	\$397.80	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					19	Apr 16, 2021	SYSTEM	\$3,640.00	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					20	May 3, 2021	SYSTEM	\$2,497.82	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					21	May 17, 2021	SYSTEM	\$2,962.18	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					22	Jun 2, 2021	SYSTEM	\$1,579.26	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					28	Sep 2, 2021	SYSTEM	\$278.00	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$24,108.63	
				T-4-1				\$24,108.63	
			Price FUEL -	Total				\$24,100.03	
	0050 -	Total	Price FUEL -	Total				\$24,108.63	
	0050 -	Total COMPACTING EMBANKMENT	Material	Total	5	Sep 16, 2020	SYSTEM		This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		COMPACTING		Total	5		SYSTEM	\$24,108.63	Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment
		COMPACTING		Total		2020 Sep 16,		\$24,108.63 \$74,940.00	Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment
		COMPACTING		Total	5	2020 Sep 16, 2020 Oct 1,	SYSTEM	\$24,108.63 \$74,940.00 (\$74,940.00)	Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment
		COMPACTING		Total	5	2020 Sep 16, 2020 Oct 1, 2020	SYSTEM	\$24,108.63 \$74,940.00 (\$74,940.00) \$74,940.00	Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment
		COMPACTING		Total	5 6	2020 Sep 16, 2020 Oct 1, 2020 Oct 1, 2020 Oct 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$24,108.63 \$74,940.00 (\$74,940.00) \$74,940.00 (\$74,940.00)	Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment
		COMPACTING		Total	5 6 6 7	2020 Sep 16, 2020 Oct 1, 2020 Oct 1, 2020 Oct 16, 2020 Oct 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM	\$24,108.63 \$74,940.00 (\$74,940.00) \$74,940.00 (\$74,940.00) \$112,440.00	Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment
		COMPACTING		Total	5 6 6 7	2020 Sep 16, 2020 Oct 1, 2020 Oct 16, 2020 Oct 16, 2020 Nov 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$24,108.63 \$74,940.00 (\$74,940.00) \$74,940.00 (\$74,940.00) \$112,440.00	Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user hillto overridding Payment Estimate Item Adjustment (0010) due to user hillto overridding Payment
		COMPACTING		Total	5 6 7 7 8	2020 Sep 16, 2020 Oct 1, 2020 Oct 16, 2020 Oct 16, 2020 Nov 2, 2020 Nov 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$24,108.63 \$74,940.00 (\$74,940.00) \$74,940.00 (\$74,940.00) \$112,440.00 (\$112,440.00)	Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user hillto overridding Payment Estimate Item Adjustment (0010) due to user hillto overridding Payment
		COMPACTING		Total	5 6 7 7 8	2020 Sep 16, 2020 Oct 1, 2020 Oct 16, 2020 Oct 16, 2020 Nov 2, 2020 Nov 16, Nov 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$24,108.63 \$74,940.00 (\$74,940.00) \$74,940.00 (\$74,940.00) \$112,440.00 (\$112,440.00) (\$112,440.00)	Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Exception 1 on the current Payment Estimate.
		COMPACTING		Total	5 6 7 7 8 8	2020 Sep 16, 2020 Oct 1, 2020 Oct 16, 2020 Oct 16, 2020 Nov 2, 2020 Nov 16, 2020 Nov 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$24,108.63 \$74,940.00 (\$74,940.00) \$74,940.00 (\$74,940.00) \$112,440.00 (\$112,440.00) \$112,440.00 (\$112,440.00)	Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Exception 1 on the current Payment Estimate.



	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
1010000	2000	001474.071110		Туре				4405.000.00	
J612222	J6I2222 0060	COMPACTING EMBANKMENT	Material		11	Dec 16, 2020	SYSTEM	\$195,990.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user schlag1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					11	Dec 16, 2020	SYSTEM	(\$195,990.00)	
					12	Jan 4, 2021	SYSTEM	\$195,990.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					12	Jan 4, 2021	SYSTEM	(\$195,990.00)	
					13	Jan 19, 2021	SYSTEM	\$195,990.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schlag1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					13	Jan 19, 2021	SYSTEM	(\$195,990.00)	
					14	Feb 2, 2021	SYSTEM	\$197,490.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					14	Feb 2, 2021	SYSTEM	(\$197,490.00)	
					15	Feb 16, 2021	SYSTEM	\$197,490.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schlag1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					15	Feb 16, 2021	SYSTEM	(\$197,490.00)	
					16	Mar 2, 2021	SYSTEM	\$197,490.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					16	Mar 2, 2021	SYSTEM	(\$197,490.00)	
					29	Sep 16, 2021	SYSTEM	\$251,556.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					29	Sep 16, 2021	SYSTEM	(\$251,556.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0060 -	Total						\$0.00	
	0060 - 0140	TYPE 1 AGGREGATE FOR	Material		22	Jun 2, 2021	SYSTEM	\$0.00 \$1,320.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		TYPE 1	Material		22	2021 Jun 2,	SYSTEM SYSTEM		
		TYPE 1 AGGREGATE FOR	Material			2021		\$1,320.00	Estimate Item Adjustment (0008) due to user hillt5 overridding Payment
		TYPE 1 AGGREGATE FOR	Material		22	Jun 2, 2021 Jun 16,	SYSTEM	\$1,320.00 (\$1,320.00)	Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment
		TYPE 1 AGGREGATE FOR	Material		22 23	Jun 2, 2021 Jun 16, 2021 Jun 16,	SYSTEM	\$1,320.00 (\$1,320.00) \$1,518.00	Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment
		TYPE 1 AGGREGATE FOR	Material		22 23 23	Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1,	SYSTEM SYSTEM	\$1,320.00 (\$1,320.00) \$1,518.00 (\$1,518.00)	Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment
		TYPE 1 AGGREGATE FOR	Material		22 23 23 24	2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1,	SYSTEM SYSTEM SYSTEM SYSTEM	\$1,320.00 (\$1,320.00) \$1,518.00 (\$1,518.00) \$1,573.00	Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment
		TYPE 1 AGGREGATE FOR	Material		22 23 23 24 24	2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$1,320.00 (\$1,320.00) \$1,518.00 (\$1,518.00) \$1,573.00	Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment
		TYPE 1 AGGREGATE FOR	Material		22 23 23 24 24 25	2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$1,320.00 (\$1,320.00) \$1,518.00 (\$1,518.00) \$1,573.00 (\$1,573.00) \$1,573.00	Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment
		TYPE 1 AGGREGATE FOR	Material		22 23 23 24 24 25 25	2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$1,320.00 (\$1,320.00) \$1,518.00 (\$1,518.00) \$1,573.00 (\$1,573.00) \$1,573.00	Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate.
		TYPE 1 AGGREGATE FOR	Material	- Total	22 23 23 24 24 25 25 26	2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$1,320.00 (\$1,320.00) \$1,518.00 (\$1,518.00) \$1,573.00 (\$1,573.00) \$1,573.00 (\$1,573.00)	Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate.
		TYPE 1 AGGREGATE FOR	Material - To		22 23 23 24 24 25 25 26	2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$1,320.00 (\$1,320.00) \$1,518.00 (\$1,518.00) \$1,573.00 (\$1,573.00) \$1,573.00 (\$1,573.00)	Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate.



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0140	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	Price FUEL			2021			
				23	Jun 16, 2021	SYSTEM	\$3.49	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				24	Jul 1, 2021	SYSTEM	\$0.97	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			- Total				\$27.50	
		Price FUEL -						
0140 -	Total							
0150		Material		21	May 17, 2021	SYSTEM	\$1,656.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hillt5 overridding Payment
	BASE			21	May 17,	SYSTEM	(\$1,656.00)	Estimate Exception 1 on the current Payment Estimate.
				22	Jun 2,	SYSTEM	\$1,656.00	This adjustment offsets the original system-generated Material Payment
				22		SVSTEM	(\$1.656.00)	Estimate Item Adjustment (0009) due to user hillt5 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					2021			
				23	Jun 16, 2021	SYSTEM	\$1,656.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				23	Jun 16, 2021	SYSTEM	(\$1,656.00)	
				24	Jul 1, 2021	SYSTEM	\$1,656.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hillt5 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				24	Jul 1, 2021	SYSTEM	(\$1,656.00)	
				25	Jul 16, 2021	SYSTEM	\$1,656.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user kloepj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				25	Jul 16, 2021	SYSTEM	(\$1,656.00)	
					26	Aug 2, 2021	SYSTEM	\$1,656.00
				26	Aug 2, 2021	SYSTEM	(\$1,656.00)	
			- Total				\$0.00	
		Material - To	tal				\$0.00	
		Price FUEL		21	May 17, 2021	SYSTEM	\$13.82	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			- Total				\$13.82	
		Price FUEL -	Total				\$13.82	
0150 -	Total						\$13.82	
0160	GRAVEL (A) OR CRUSHED STONE (B)	Material		18	Apr 2, 2021	SYSTEM	\$34,656.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				18	Apr 2, 2021	SYSTEM	(\$34,656.00)	
				19	Apr 16, 2021	SYSTEM	\$34,656.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				19	Apr 16, 2021	SYSTEM	(\$34,656.00)	
				20	May 3, 2021	SYSTEM	\$34,656.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hillt5 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				20	May 3, 2021	SYSTEM	(\$34,656.00)	
				21	May 17, 2021	SYSTEM	\$34,656.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hillts overridding Payment
								Estimate Exception 3 on the current Payment Estimate.
	1140 - 1150 - 11	1140 TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) 1150 TYPE 5 AGGREGATE FOR BASE 1150 GRAVEL (A) OR CRUSHED STONE	Type Type Type 1 AGGREGATE FOR BASE (4 IN. THICK) Price FUEL - Material - To Pric	1140 TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) 1150 AGGREGATE FOR BASE 1150 AGGREGATE FOR BASE 1150 AGGREGATE FOR BASE 1150 TYPE 5 AGGREGATE FOR BASE 1150 AGGREGATE FOR	Type	Type	Type	Type Adjustment Number Date By



oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
2222 016	0160	GRAVEL (A) OR CRUSHED STONE (B)	Material		22	Jun 2, 2021	SYSTEM	\$34,656.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hillt5 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$34,656.00)	
						23	Jun 16, 2021	SYSTEM	\$34,656.00
					23	Jun 16, 2021	SYSTEM	(\$34,656.00)	
					24	Jul 1, 2021	SYSTEM	\$34,656.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user herrmt1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$34,656.00)	
					25	Jul 16, 2021	SYSTEM	\$34,656.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$34,656.00)	
					26	Aug 2, 2021	SYSTEM	\$34,656.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hillts overridding Payment Estimate Exception 4 on the current Payment Estimate.
					26	Aug 2, 2021	SYSTEM	(\$34,656.00)	
					27	Aug 16, 2021	SYSTEM	\$10,656.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user herrmt1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$10,656.00)	
					28	Sep 2, 2021	SYSTEM	\$10,656.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$10,656.00)	
					2!	29	Sep 16, 2021	SYSTEM	\$10,656.00
					29	Sep 16, 2021	SYSTEM	(\$10,656.00)	
				- Total				\$0.00	
			Material - To	rial - Total					
	0160 - 0200	CONCRETE PAVEMENT (8 IN. NON-REINF)	Material		21	May 17, 2021	SYSTEM	\$0.00 \$1,798.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$1,798.30)	
					22	Jun 2, 2021	SYSTEM	\$1,161.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0061) due to user hillt5 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$1,161.30)	-
					23	Jun 16, 2021	SYSTEM	\$14,366.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kloepi1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$14,366.80)	
					24	Jul 1, 2021	SYSTEM	\$14,366.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user herrmt1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$14,366.80)	
					25	Jul 16, 2021	SYSTEM	\$14,366.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.



March 2015	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
NCHARLINES 28 Aug 2 SYSTEM \$14,96.80 This adjustment officed the coignal system generated Moterial Payment 2011 2	J6I2222	PAVEMENT (8 IN.	Material			2021				
Price UEL Total						26		SYSTEM	\$14,366.80	Estimate Item Adjustment (0009) due to user hillt5 overridding Payment
Material Total						26		SYSTEM	(\$14,366.80)	
Pipe PUEL 21					- Total				\$0.00	
22 Jun 2 22 Jun 2 22 Jun 16 29 StyTEM 2008 5 Reference flem Price Adjustment Index Adjustment Type applied is PUEL 20 Jun 16 57 20 StyTEM 2008 5 Reference flem Price Adjustment Index Adjustment Type applied is PUEL 20 Sep 2 StyTEM 2008 5 Reference flem Price Adjustment Index Adjustment Type applied is PUEL 20 Sep 2 StyTEM 2007 77 2007 2				Material - To	tal				\$0.00	
223 Jun 16, SYSTEM \$208.59 Reference team Price Adjustment Index Adjustment Type applied is FUEL 22 Jun 16, SYSTEM \$7.20 Reference team Price Adjustment Index Adjustment Type applied is FUEL 22 Sep 2, SYSTEM \$7.20 Reference team Price Adjustment Index Adjustment Type applied is FUEL 2021			Price FUEL		21		SYSTEM	\$28.19	Reference Item Price Adjustment Index Adjustment Type applied is FUEL	
27 Aug 16, SYSTEM S12, 20 SYSTEM S27.0 Reference item Price Adjustment Index Adjustment Type applied is FUEL. 28 Sep 2, 20 SYSTEM S27.77 28 Sep 2, 20 SYSTEM S27.77 28 Sep 2, 20 SYSTEM S27.77 28 SYSTEM S14, 241.60 TYPE A2 Malerial SHOULDER 8 O Ct 1, SYSTEM S14, 241.60 This adjustment offsets the original system-generated Overrun Payment Estimate Exception of an extra flammate break digitation (000)1 due to use strongly overrun flammate break digitation (000)1 due to use strongly overrun flammate break digitation (000)1 due to use strongly overrun flammate break digitation (000)1 due to use strongly overrun flammate break digitation (000)1 due to use strongly overrun flammate break digitation (000)1 due to use strongly overrun flammate break digitation (000)1 due to use strongly overrun flammate break digitation (000)1 due to use strongly overrun flammate break digitation (000)1 due to use fall stimulate. 8 Nov 2, SYSTEM S14,241.60 8 Nov 2, SYSTEM S14,241.60 9 Nov 16, SYSTEM S14,241.60 10 Dec 2, SYSTEM S14,241.60 11 Dec 16, SYSTEM S14,280.96 12 Jan 4, SYSTEM S14,280.96 13 Dec 16, SYSTEM S14,280.96 14 Dec 16, SYSTEM S14,280.96 15 Ann 19, SYSTEM S14,280.96 16 SYSTEM S14,280.96 17 This adjustment offsets the original system-generated Overrun Payment Estimate Exception 6 on the current Payment Estimate. 18 SYSTEM S14,280.96 19 Dec 2, SYSTEM S14,280.96 10 Dec 2, SYSTEM S14,280.96 11 Dec 16, SYSTEM S14,280.96 12 Jan 4, SYSTEM S14,280.96 13 Jan 19, SYSTEM S14,280.96 14 Feb 2, SYSTEM S14,280.96 15 SYSTEM S14,280.96 16 SYSTEM S14,280.96 17 Significant (000) due to use strongly overrun Payment Estimate Exception 6 on the current Payment Estimate. 18 SYSTEM S14,280.96 19 SYSTEM S14,280.96 10 Dec 2, SYSTEM S14,280.96 11 Dec 16, SYSTEM S14,280.96 12 Jan 4, SYSTEM S14,280.96 13 Jan 19, SYSTEM S14,280.96 14 Feb 2, SYSTEM S14,280.96 15 SYSTEM S14,280.96 16 SYSTEM S14,280.96 17 Significant (000) due to use						22		SYSTEM	(\$9.98)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
Price FUEL - Total S427.77 2207 - Total Price FUEL - Total S427.77						23		SYSTEM	\$208.59	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
28						27		SYSTEM	\$7.26	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
Price FUEL - Total Price FUEL - Total Price FUEL - Total S487.77						28	Sep 2,	SYSTEM	\$53.71	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
Price FUEL - Total					- Total				\$287.77	
SHOULDER				Price FUEL -	Total					
SHOULDER		0200 -	Total						\$287.77	
2020		0210		Material		6		SYSTEM	\$14,241.60	Estimate Item Adjustment (0004) due to user kloepj1 overridding Payment
Estimate Item Adjustment (0064) due to user klose) it overridding Payment Estimate Exception 8 on the current Payment Estimate. 7						6		SYSTEM	(\$14,241.60)	
8 Nov 2. SYSTEM \$14,241.60 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user hill5 overridding Payment Estimate Item Adjustment (0004) due to user hill5 overridding Payment Estimate Item Adjustment (0004) due to user hill5 overridding Payment Estimate Item Adjustment (0004) due to user hill5 overridding Payment Estimate Item Adjustment (0004) due to user hill5 overridding Payment Estimate Item Adjustment (0004) due to user hill5 overridding Payment Estimate Exception 6 on the current Payment Estimate Exception 6 on the current Payment Estimate Item Adjustment (0004) due to user kloep† overridding Payment Estimate Item Adjustment (0004) due to user kloep† overridding Payment Estimate Item Adjustment (0004) due to user kloep† overridding Payment Estimate Exception 6 on the current Payment Estimate Exception 6 on the current Payment Estimate Item Adjustment (0005) due to user schlag† overridding Payment Estimate Item Adjustment (0005) due to user schlag† overridding Payment Estimate Item Adjustment (0005) due to user kloep† overridding Payment Estimate Exception 6 on the current Payment Estimate Item Adjustment (0005) due to user schlag† overridding Payment Estimate Exception 7 on the current Payment Estimate Item Adjustment (0005) due to user schlag† overridding Payment Estimate Item Adjustment (0005) due to user schlag† overridding Payment Estimate Item Adjustment (0005) due to user schlag† overridding Payment Estimate Item Adjustment (0005) due to user schlag† overridding Payment Estimate Item Adjustment (0005) due to user schlag† overridding Payment Estimate Item Adjustment (0005) due to user schlag† overridding Payment Estimate Item Adjustment (0005) due to user schlag† overridding Payment Estimate Item Adjustment (0005) due to user schlag† overridding Payment Estimate Item Adjustment (0005) due to user schlag† overridding Payment Estimate Item Adjustment (0005) due to user hill5 overridding Payment Estimate Item Adjustment (0005) due to user hil						7		SYSTEM	\$14,241.60	Estimate Item Adjustment (0004) due to user kloepj1 overridding Payment
Estimate Item Adjustment (0004) due to user hillfs overridding Payment Estimate Exception 6 on the current Payment Estimate						7		SYSTEM	(\$14,241.60)	
9 Nov 16, SYSTEM \$14,241.60 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user hillt5 overridding Payment Estimate Item Adjustment (0004) due to user hillt5 overridding Payment Estimate Exception 6 on the current Payment Estimate. 9 Nov 16, SYSTEM (\$14,241.60) 10 Dec 2, SYSTEM \$14,880.96 11 Dec 16, SYSTEM \$14,880.96 11 Dec 16, SYSTEM \$14,880.96 11 Dec 16, SYSTEM \$14,880.96 12 Jan 4, 2021 13 Jan 19, SYSTEM \$14,880.96 15 SYSTEM \$14,880.96 16 SYSTEM \$14,880.96 17 This adjustment offsets the original system-generated Overrun Payment Estimate Exception 6 on the current Payment Estimate. 19 Dec 16, SYSTEM \$14,880.96 10 Dec 27, SYSTEM \$14,880.96 11 Dec 16, SYSTEM \$14,880.96 12 Jan 4, 2021 13 Jan 19, SYSTEM \$14,880.96 15 SYSTEM \$14,880.96 16 SYSTEM \$14,880.96 17 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user kicepj1 overridding Payment Estimate Exception 7 on the current Payment Estimate Item Adjustment (0015) due to user schiegh overridding Payment Estimate Exception 7 on the current Payment Estimate Item Adjustment (0016) due to user schiegh overridding Payment Estimate Exception 6 on the current Payment Estimate Item Adjustment (0008) due to user schiegh overridding Payment Estimate Item Adjustment (0008) due to user schiegh overridding Payment Estimate Item Adjustment (0008) due to user schiegh overridding Payment Estimate Exception 6 on the current Payment Estimate Item Adjustment (0008) due to user schiegh overridding Payment Estimate Item Adjustment (0008) due to user schiegh overridding Payment Estimate Item Adjustment (0008) due to user schiegh overridding Payment Estimate Item Adjustment (0008) due to user schiegh overridding Payment Estimate Item Adjustment (0008) due to user schiegh overridding Payment Estimate Item Adjustment (0008) due to user schiegh overridding Payment Estimate Item Adjustment (0008) due to user schiegh overridding Payment Estimate Item Adjustment (0008) d						8		SYSTEM	\$14,241.60	Estimate Item Adjustment (0004) due to user hillt5 overridding Payment
System S						8		SYSTEM	(\$14,241.60)	
2020 10 Dec 2, SYSTEM \$14,880.96 Estimate Item Adjustment (0004) due to user kloep foverridding Payment Estimate Item Adjustment (0004) due to user kloep foverridding Payment Estimate Item Adjustment (0008) due to user schlag foverridding Payment Estimate Exception 6 on the current Payment Estimate. 10 Dec 2, SYSTEM \$14,880.96 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user schlag foverridding Payment Estimate Exception 6 on the current Payment Estimate. 11 Dec 16, SYSTEM \$14,880.96 Solve for the current Payment Estimate Exception 6 on the current Payment Estimate Item Adjustment (0015) due to user kloep foverridding Payment Estimate Item Adjustment (0015) due to user kloep foverridding Payment Estimate Exception 7 on the current Payment Estimate. 12 Jan 4, SYSTEM \$14,880.96 Solve for the current Payment Estimate Item Adjustment (0015) due to user schlag foverridding Payment Estimate Item Adjustment (0008) due to user schlag foverridding Payment Estimate Item Adjustment (0008) due to user schlag foverridding Payment Estimate Item Adjustment (0008) due to user schlag foverridding Payment Estimate Exception 6 on the current Payment Estimate. 13 Jan 19, SYSTEM \$14,880.96 Solve for the current Payment Estimate Item Adjustment (0008) due to user schlag foverridding Payment Estimate Item Adjustment (0008) due to user schlag foverridding Payment Estimate Item Adjustment (0008) due to user schlag foverridding Payment Estimate Item Adjustment (0008) due to user hillto overridding Payment Estimate Item Adjustment (0008) due to user hillto overridding Payment Estimate Item Adjustment (0008) due to user hillto overridding Payment Estimate Item Adjustment (0008) due to user hillto overridding Payment Estimate Item Adjustment (0008) due to user hillto overridding Payment Estimate Item Adjustment (0008) due to user hillto overridding Payment Estimate Item Adjustment (0008) due to user hillto overridding Payment Estimate Item Adjustment (0008) due to user k						9		SYSTEM	\$14,241.60	Estimate Item Adjustment (0004) due to user hillt5 overridding Payment
Estimate Item Adjustment (0004) due to user kloepj1 overridding Payment Estimate Exception 6 on the current Payment Estimate. 10 Dec 2, 2020 11 Dec 16, SYSTEM \$14,880.96 11 Dec 16, SYSTEM \$14,880.96 11 Dec 16, SYSTEM \$14,880.96 12 Jan 4, 2021 13 Jan 19, 2021 14 Feb 2, 2021 Estimate Item Adjustment offsets the original system-generated Overrun Payment Estimate Exception 6 on the current Payment Estimate. Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 7 on the current Payment Estimate. Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schlag1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schlag1 overridding Payment Estimate Item Adjustment (0006) due to user schlag1 overridding Payment Estimate Item Adjustment (0006) due to user schlag1 overridding Payment Estimate Item Adjustment (0006) due to user schlag1 overridding Payment Estimate Item Adjustment (0006) due to user schlag1 overridding Payment Estimate Item Adjustment (0006) due to user schlag1 overridding Payment Estimate Item Adjustment (0006) due to user schlag1 overridding Payment Estimate Item Adjustment (0006) due to user schlag1 overridding Payment Estimate Exception 6 on the current Payment Estimate.						9		SYSTEM	(\$14,241.60)	
11 Dec 16, 2020 SYSTEM \$14,880.96 This adjustment offsets the original system-generated Overrun Payment Estimate Exception 6 on the current Payment Estimate Estimate Exception 6 on the current Payment Estimate. 11 Dec 16, 2020 SYSTEM (\$14,880.96) 12 Jan 4, 2021 SYSTEM \$14,880.96 This adjustment offsets the original system-generated Material Payment Estimate Exception 7 on the current Payment Estimate. 12 Jan 4, 2021 SYSTEM (\$14,880.96) 13 Jan 19, 2021 SYSTEM \$14,880.96 This adjustment offsets the original system-generated Material Payment Estimate Exception 7 on the current Payment Estimate. 13 Jan 19, 2021 SYSTEM \$14,880.96 This adjustment offsets the original system-generated Material Payment Estimate Estimate Exception 6 on the current Payment Estimate Estimate Exception 6 on the current Payment Estimate. 13 Jan 19, 2021 SYSTEM (\$14,880.96) 14 Feb 2, SYSTEM \$14,880.96 This adjustment offsets the original system-generated Material Payment Estimate Exception 6 on the current Payment Estimate. 14 Feb 2, SYSTEM \$14,880.96 This adjustment offsets the original system-generated Material Payment Estimate Exception 6 on the current Payment Estimate Estimate Exception 6 on the current Payment Estimate Estimate Exception 6 on the current Payment Estimate.						10		SYSTEM	\$14,880.96	Estimate Item Adjustment (0004) due to user kloepj1 overridding Payment
Estimate Item Adjustment (0008) due to user schlag1 overridding Payment Estimate Exception 6 on the current Payment Estimate. 11 Dec 16, 2020 12 Jan 4, 2021 SYSTEM \$14,880.96 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user kloep)1 overridding Payment Estimate Exception 7 on the current Payment Estimate. 12 Jan 4, 2021 SYSTEM (\$14,880.96) 13 Jan 19, 2021 SYSTEM \$14,880.96 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schlag1 overridding Payment Estimate Exception 6 on the current Payment Estimate. 13 Jan 19, 2021 SYSTEM (\$14,880.96) 14 Feb 2, SYSTEM \$14,880.96 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hillt5 overridding Payment Estimate Item Adjustment (0006) due to user hillt5 overridding Payment Estimate Item Adjustment (0006) due to user hillt5 overridding Payment Estimate Exception 6 on the current Payment Estimate.						10		SYSTEM	(\$14,880.96)	
2020 12 Jan 4, 2021 SYSTEM \$14,880.96 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 7 on the current Payment Estimate. 12 Jan 4, 2021 13 Jan 19, 2021 SYSTEM \$14,880.96 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schlag1 overridding Payment Estimate Exception 6 on the current Payment Estimate. 13 Jan 19, 2021 SYSTEM (\$14,880.96) 14 Feb 2, SYSTEM \$14,880.96 This adjustment offsets the original system-generated Material Payment Estimate Exception 6 on the current Payment Estimate. 15 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hillt5 overridding Payment Estimate Item Adjustment (0006) due to user hillt5 overridding Payment Estimate Exception 6 on the current Payment Estimate.						11		SYSTEM	\$14,880.96	Estimate Item Adjustment (0008) due to user schlag1 overridding Payment
Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 7 on the current Payment Estimate. 12 Jan 4, 2021 13 Jan 19, 2021 SYSTEM \$14,880.96 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schlag1 overridding Payment Estimate Exception 6 on the current Payment Estimate. 13 Jan 19, 2021 SYSTEM \$14,880.96 This adjustment (0008) due to user schlag1 overridding Payment Estimate Exception 6 on the current Payment Estimate. 14 Feb 2, SYSTEM \$14,880.96 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hillt5 overridding Payment Estimate Exception 6 on the current Payment Estimate. 14 Feb 2, SYSTEM (\$14,880.96)						11		SYSTEM	(\$14,880.96)	
2021 13 Jan 19, 2021 13 Jan 19, 2021 13 Jan 19, 2021 14 Feb 2, 2021 15 SYSTEM \$14,880.96 2021 16 This adjustment offsets the original system-generated Material Payment Estimate Exception 6 on the current Payment Estimate. 18 This adjustment (0008) due to user schlag1 overridding Payment Estimate Exception 6 on the current Payment Estimate. 19 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hillt5 overridding Payment Estimate Exception 6 on the current Payment Estimate. 19 This adjustment (0008) due to user schlag1 overridding Payment Estimate Item Adjustment (0006) due to user hillt5 overridding Payment Estimate Exception 6 on the current Payment Estimate.						12		SYSTEM	\$14,880.96	Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment
2021 Estimate Item Adjustment (0008) dué to user schlag1 overridding Payment Estimate Exception 6 on the current Payment Estimate. 13 Jan 19, 2021 14 Feb 2, SYSTEM \$14,880.96 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hillt5 overridding Payment Estimate Exception 6 on the current Payment Estimate. 14 Feb 2, SYSTEM (\$14,880.96)						12		SYSTEM	(\$14,880.96)	
2021 14 Feb 2, 2021 SYSTEM \$14,880.96 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hillt5 overridding Payment Estimate Exception 6 on the current Payment Estimate. 14 Feb 2, SYSTEM (\$14,880.96)						13		SYSTEM	\$14,880.96	Estimate Item Adjustment (0008) due to user schlag1 overridding Payment
2021 Estimate Item Adjustment (0006) due to user hillt5 overridding Payment Estimate Exception 6 on the current Payment Estimate. 14 Feb 2, SYSTEM (\$14,880.96)						13		SYSTEM	(\$14,880.96)	
						14		SYSTEM	\$14,880.96	Estimate Item Adjustment (0006) due to user hillt5 overridding Payment
						14		SYSTEM	(\$14,880.96)	



t L	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks					
2 0	0210	TYPE A2 SHOULDER	Material		15	Feb 16, 2021	SYSTEM	\$14,880.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schlag1 overridding Payment Estimate Exception 6 on the current Payment Estimate.					
					15	Feb 16, 2021	SYSTEM	(\$14,880.96)						
					16	Mar 2, 2021	SYSTEM	\$14,880.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kloepj1 overridding Paymer Estimate Exception 6 on the current Payment Estimate.					
					16	Mar 2, 2021	SYSTEM	(\$14,880.96)						
					17	Mar 16, 2021	SYSTEM	\$14,880.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Paymer Estimate Exception 5 on the current Payment Estimate.					
					17	Mar 16, 2021	SYSTEM	(\$14,880.96)						
					18	Apr 2, 2021	SYSTEM	\$14,880.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kloepj1 overridding Paymen Estimate Exception 6 on the current Payment Estimate.					
					18	Apr 2, 2021	SYSTEM	(\$14,880.96)						
					19	Apr 16, 2021	SYSTEM	\$14,880.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kloepj1 overridding Paymer Estimate Exception 6 on the current Payment Estimate.					
					19	Apr 16, 2021	SYSTEM	(\$14,880.96)						
					20	May 3, 2021	SYSTEM	\$14,880.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 6 on the current Payment Estimate.					
					20	May 3, 2021	SYSTEM	(\$14,880.96)						
						May 17, 2021	SYSTEM	\$14,880.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hillt5 overridding Payment Estimate Exception 15 on the current Payment Estimate.					
										21	May 17, 2021	SYSTEM	(\$14,880.96)	
					22	Jun 2, 2021	SYSTEM	\$14,880.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hillt5 overridding Payment Estimate Exception 12 on the current Payment Estimate.					
					22	Jun 2, 2021	SYSTEM	(\$14,880.96)						
				- Total				\$0.00						
			Material - To	tal				\$0.00						
0	0210 -	Total						\$0.00						
0	0220	CONCRETE APPROACH PAVEMENT	Material		29	Sep 16, 2021	SYSTEM	\$5,025.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.					
					29	Sep 16, 2021	SYSTEM	(\$5,025.00)						
				- Total				\$0.00						
			Material - To	tal				\$0.00						
			Material - 10					00.00						
0	0220 -	Total	material - 10					\$0.00						
)220 -)240	Total WATER - UTILITY ITEM	Material		29	Sep 16, 2021	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kloepj1 overridding Paymen Estimate Exception 17 on the current Payment Estimate.					
		WATER - UTILITY			29		SYSTEM SYSTEM		Estimate Item Adjustment (0007) due to user kloepj1 overridding Paymer					
		WATER - UTILITY		- Total		2021 Sep 16,		\$12,000.00	Estimate Item Adjustment (0007) due to user kloepj1 overridding Paymer					
		WATER - UTILITY				2021 Sep 16,		\$12,000.00 (\$12,000.00)	Estimate Item Adjustment (0007) due to user kloepj1 overridding Paymer					
0		WATER - UTILITY ITEM	Material			2021 Sep 16,		\$12,000.00 (\$12,000.00) \$0.00	Estimate Item Adjustment (0007) due to user kloepj1 overridding Paymer					
0	0240	WATER - UTILITY ITEM	Material			2021 Sep 16,		\$12,000.00 (\$12,000.00) \$0.00	Estimate Item Adjustment (0007) due to user kloepj1 overridding Paymer					
0	0240 -	WATER - UTILITY ITEM Total WATER - UTILITY	Material Material - To		29	2021 Sep 16, 2021	SYSTEM	\$12,000.00 (\$12,000.00) \$0.00 \$0.00	Estimate Item Adjustment (0007) due to user kloepj1 overridding Paymer Estimate Exception 17 on the current Payment Estimate.					



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks						
J6I2222	0270	WATER - UTILITY ITEM	Construction Stockpile	- Total				(\$75,319.80)							
			Construction	Stockpile - 1	Total			(\$75,319.80)							
			Construction Stockpile STMI		6	Oct 1, 2020	SYSTEM	\$75,319.80	Payment Estimate Item Adjustment generated Stockpile Transaction						
			OTIVII	- Total				\$75,319.80							
			Construction	Stockpile S	TMI - Total			\$75,319.80							
	0270 -	Total						\$0.00							
	0280	WATER - UTILITY ITEM	Construction Stockpile		11	Dec 16, 2020	SYSTEM	(\$13,214.00)	Payment Estimate Item Adjustment generated Stockpile Transaction						
				- Total				(\$13,214.00)							
			Construction	Stockpile - 1	Γotal			(\$13,214.00)							
			Construction Stockpile		6	Oct 1, 2020	SYSTEM	\$13,214.00	Payment Estimate Item Adjustment generated Stockpile Transaction						
			STMI	- Total				\$13,214.00							
			Construction	Stockpile STMI - Total				\$13,214.00							
	0280 -	Total						\$0.00							
			Material		22	lun 2	QVQTF14	\$15,062.00	This adjustment offsets the original austern generated Material Decree						
	0380	MODIFIED CONCRETE GUTTER TYPE B	Material		22	Jun 2, 2021	SYSTEM	\$15,062.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hillt5 overridding Payment Estimate Exception 16 on the current Payment Estimate.						
											22	Jun 2, 2021	SYSTEM	(\$15,062.00)	
													23	Jun 16, 2021	SYSTEM
									23	Jun 16, 2021	SYSTEM	(\$15,572.00)			
					24	Jul 1, 2021	SYSTEM	\$15,572.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user herrmt1 overridding Payment Estimate Exception 13 on the current Payment Estimate.						
									24	Jul 1, 2021	SYSTEM	(\$15,572.00)			
					25	Jul 16, 2021	SYSTEM	\$15,572.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 13 on the current Payment Estimate.						
					25	Jul 16, 2021	SYSTEM	(\$15,572.00)							
					26	Aug 2, 2021	SYSTEM	\$15,572.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hillt5 overridding Payment Estimate Exception 13 on the current Payment Estimate.						
					26	Aug 2, 2021	SYSTEM	(\$15,572.00)							
				- Total				\$0.00							
			Material - Tot	al				\$0.00							
	0380	· Total						\$0.00							
		PAVED APPROACH, 8 IN.	Material	Material		21	May 17, 2021	SYSTEM	\$9,037.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hillt5 overridding Payment Estimate Exception 19 on the current Payment Estimate.					
					21	May 17, 2021	SYSTEM	(\$9,037.50)							
					22	Jun 2, 2021	SYSTEM	\$9,037.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hillt5 overridding Payment Estimate Exception 19 on the current Payment Estimate.						
					22	Jun 2, 2021	SYSTEM	(\$9,037.50)							
					23	Jun 16, 2021	SYSTEM	\$9,037.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.						
					23	Jun 16, 2021	SYSTEM	(\$9,037.50)							
			24	24	Jul 1, 2021	SYSTEM	\$9,037.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user herrmt1 overridding Payment Estimate Exception 14 on the current Payment Estimate.							
						24	Jul 1,	SYSTEM	(\$9,037.50)						



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
222	0410	PAVED APPROACH,	Material			2021				
		8 IN.			25	Jul 16, 2021	SYSTEM	\$9,037.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	
					25	Jul 16, 2021	SYSTEM	(\$9,037.50)		
					26	Aug 2, 2021	SYSTEM	\$9,037.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hillt5 overridding Payment Estimate Exception 14 on the current Payment Estimate.	
					26	Aug 2, 2021	SYSTEM	(\$9,037.50)		
					27	Aug 16, 2021	SYSTEM	\$9,037.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user herrmt1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	
					27	Aug 16, 2021	SYSTEM	(\$9,037.50)		
					28	Sep 2, 2021	SYSTEM	\$9,037.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
					28	Sep 2, 2021	SYSTEM	(\$9,037.50)		
						29	Sep 16, 2021	SYSTEM	\$9,037.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					29	Sep 16, 2021	SYSTEM	(\$9,037.50)	Edulado Exceptión 10 on tilo darion 1 dynon Edulado.	
				- Total		2021		\$0.00		
			Material - To					\$0.00		
			Material - To		21	May 17, 2021	SYSTEM	\$55.53	Reference Item Price Adjustment Index Adjustment Type applied is FUEL	
				- Total				\$55.53		
			Price FUEL -	Total				\$55.53		
	0410 -	· Total						\$55.53		
	0410 - T	CONCRETE SIDEWALK, 4 IN.	Material		22	Jun 2, 2021	SYSTEM	\$6,120.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hillt5 overridding Payment	
		SIDEWALK, 4 IIV.							Estimate Exception 22 on the current Payment Estimate.	
					22	Jun 2, 2021	SYSTEM	(\$6,120.00)		
					22	Jun 2,	SYSTEM SYSTEM	(\$6,120.00) \$7,007.40		
						Jun 2, 2021 Jun 16,		, , , , ,	Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment	
					23	Jun 2, 2021 Jun 16, 2021 Jun 16,	SYSTEM	\$7,007.40	Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment	
					23	Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1,	SYSTEM	\$7,007.40 (\$7,007.40)	Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user herrmt1 overridding Payment	
					23 23 24	Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1,	SYSTEM SYSTEM	\$7,007.40 (\$7,007.40) \$7,262.40	Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kloep/1 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user herrmt1 overridding Payment	
					23 23 24 24	Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$7,007.40 (\$7,007.40) \$7,262.40	Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user herrmt1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment	
					23 23 24 24 25	Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$7,007.40 (\$7,007.40) \$7,262.40 (\$7,262.40)	Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user herrmt1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment	
					23 23 24 24 25 25	Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Jul 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$7,007.40 (\$7,007.40) \$7,262.40 (\$7,262.40) (\$7,262.40)	Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user herrmt1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hillts overridding Payment Estimate Item Adjustment (0012) due to user hillts overridding Payment	
				- Total	23 23 24 24 25 25 26	Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$7,007.40 (\$7,007.40) \$7,262.40 (\$7,262.40) \$7,262.40 (\$7,262.40)	Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user herrmt1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 15 on the current Payment Estimate.	
			Material - To		23 23 24 24 25 25 26	Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$7,007.40 (\$7,007.40) \$7,262.40 (\$7,262.40) \$7,262.40 (\$7,262.40)	Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user herrmt1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 15 on the current Payment Estimate.	
	0420 -	- Total	Material - To		23 23 24 24 25 25 26	Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$7,007.40 (\$7,007.40) \$7,262.40 (\$7,262.40) \$7,262.40 (\$7,262.40) \$7,262.40	Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user herrmt1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 15 on the current Payment Estimate.	
	0420 - 0440	Total MISC. CONCRETE			23 23 24 24 25 25 26	Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$7,007.40 (\$7,007.40) \$7,262.40 (\$7,262.40) \$7,262.40 (\$7,262.40) \$7,262.40 \$0.00	Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user herrmt1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hillto overridding Payment Estimate Item Adjustment (0012) due to user hillto overridding Payment	



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks				
J6I2222	0440	MISC. CONCRETE	Material	Type		2021							
OOIZZZZ	0440	MIGG. GONGRETE	Waterial		24	Jul 1, 2021	SYSTEM	\$10,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user herrmt1 overridding Payment Estimate Exception 16 on the current Payment Estimate.				
					24	Jul 1, 2021	SYSTEM	(\$10,650.00)					
					25	Jul 16, 2021	SYSTEM	\$14,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.				
					25	Jul 16, 2021	SYSTEM	(\$14,200.00)	·				
					26	Aug 2, 2021	SYSTEM	\$14,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hillt5 overridding Payment Estimate Exception 16 on the current Payment Estimate.				
					26	Aug 2, 2021	SYSTEM	(\$14,200.00)	7,000				
				- Total				\$0.00					
			Material - To	tal				\$0.00					
	0440 -	Total						\$0.00					
	0450	CONCRETE CURB (6 IN. HEIGHT AND UNDER)	Material		25	Jul 16, 2021	SYSTEM	\$5,085.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.				
					25	Jul 16, 2021	SYSTEM	(\$5,085.00)					
					26	Aug 2, 2021	SYSTEM	\$5,085.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hillt5 overridding Payment Estimate Exception 17 on the current Payment Estimate.				
							26	Aug 2, 2021	SYSTEM	(\$5,085.00)			
					27	Aug 16, 2021	SYSTEM	\$5,085.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user herrmt1 overridding Payment Estimate Exception 7 on the current Payment Estimate.				
					27	Aug 16, 2021	SYSTEM	(\$5,085.00)					
				- Total				\$0.00					
			Material - To	tal				\$0.00					
	0450 -							\$0.00					
	0460	CONCRETE GUTTER TYPE B	Material	ial	25	Jul 16, 2021	SYSTEM	\$8,040.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.				
					25	Jul 16, 2021	SYSTEM	(\$8,040.00)					
					26	Aug 2, 2021	SYSTEM	\$8,040.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user hillt5 overridding Payment Estimate Exception 18 on the current Payment Estimate.				
					:	2	2	2	26	Aug 2, 2021	SYSTEM	(\$8,040.00)	
					27	Aug 16, 2021	SYSTEM	\$8,040.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user herrmt1 overridding Payment Estimate Exception 8 on the current Payment Estimate.				
					27	Aug 16, 2021	SYSTEM	(\$8,040.00)					
					28	Sep 2, 2021	SYSTEM	\$8,040.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.				
					28	Sep 2, 2021	SYSTEM	(\$8,040.00)					
					29	Sep 16, 2021	SYSTEM	\$11,850.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.				
					29	Sep 16, 2021	SYSTEM	(\$11,850.00)					
				- Total				\$0.00					
			Material - To	tal				\$0.00					
	0460 -	Total						\$0.00					



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	0480	INTEGRAL CURB (6	Material	Туре	16	Mar 2,	SYSTEM	\$2,715.00	This adjustment offsets the original system-generated Material Payment
JOIZZZZ	0460	IN. HEIGHT AND UNDER)	Material		10	2021	STSTEM	\$2,715.00	Estimate Item Adjustment (0009) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					16	Mar 2, 2021	SYSTEM	(\$2,715.00)	
					17	Mar 16, 2021	SYSTEM	\$2,715.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					17	Mar 16, 2021	SYSTEM	(\$2,715.00)	
					18	Apr 2, 2021	SYSTEM	\$2,715.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					18	Apr 2, 2021	SYSTEM	(\$2,715.00)	
					19	Apr 16, 2021	SYSTEM	\$2,715.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					19	Apr 16, 2021	SYSTEM	(\$2,715.00)	
					20	May 3, 2021	SYSTEM	\$2,715.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hillt5 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					20	May 3, 2021	SYSTEM	(\$2,715.00)	
					21	May 17, 2021	SYSTEM	\$2,715.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user hillt5 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$2,715.00)	
					22	Jun 2, 2021	SYSTEM	\$2,715.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user hillt5 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$2,715.00)	
					23	Jun 16, 2021	SYSTEM	\$2,715.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$2,715.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0480 -							\$0.00	
	0490	FURN. TYPE 2 ROCK DITCH LINER	Material		24	Jul 1, 2021	SYSTEM	\$21,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user herrmt1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$21,050.00)	
					25	Jul 16, 2021	SYSTEM	\$21,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$21,050.00)	
					26	Aug 2, 2021	SYSTEM	\$21,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user hillt5 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					26	Aug 2, 2021	SYSTEM	(\$21,050.00)	
					27	Aug 16, 2021	SYSTEM	\$21,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user herrmt1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$21,050.00)	
					28	Sep 2, 2021	SYSTEM	\$21,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					28	Sep 2,	SYSTEM	(\$21,050.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																		
J6I2222	0490	FURN. TYPE 2	Material			2021																					
		ROCK DITCH LINER			29	Sep 16, 2021	SYSTEM	\$21,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.																		
					29	Sep 16, 2021	SYSTEM	(\$21,050.00)																			
				- Total				\$0.00																			
			Material - Tot	tal				\$0.00																			
	0490 -	· Total						\$0.00																			
	0675	CONCRETE TRAFFIC BARRIER, TYPE C	Material		3	Aug 17, 2020	SYSTEM	\$36,830.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																		
					3	Aug 17, 2020	SYSTEM	(\$36,830.00)																			
				4	Sep 2, 2020	SYSTEM	\$36,830.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																			
							4	Sep 2, 2020	SYSTEM	(\$36,830.00)																	
					5	Sep 16, 2020	SYSTEM	\$36,830.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.																		
									5	Sep 16, 2020	SYSTEM	(\$36,830.00)															
					6	Oct 1, 2020	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.																		
					6	Oct 1, 2020	SYSTEM	(\$66,845.00)																			
						7	Oct 16, 2020	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.																	
					7	Oct 16, 2020	SYSTEM	(\$66,845.00)																			
					8	Nov 2, 2020	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user hillt5 overridding Payment Estimate Exception 14 on the current Payment Estimate.																		
					8	Nov 2, 2020	SYSTEM	(\$66,845.00)																			
						9	Nov 16, 2020	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user hillt5 overridding Payment Estimate Exception 14 on the current Payment Estimate.																	
														9	Nov 16, 2020	SYSTEM	(\$66,845.00)										
									10	Dec 2, 2020	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.														
																		10	Dec 2, 2020	SYSTEM	(\$66,845.00)						
								1	1:								11	Dec 16, 2020	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user schlag1 overridding Payment Estimate Exception 14 on the current Payment Estimate.						
										11	Dec 16, 2020	SYSTEM	(\$66,845.00)														
										1		1		1:	1	1.	1	1	1	1			12	Jan 4, 2021	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kloepj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
																				12	Jan 4, 2021	SYSTEM	(\$66,845.00)				
																				1	13	13	13	13	1	1	
					1															13	Jan 19, 2021	SYSTEM	(\$66,845.00)				
					14	Feb 2, 2021	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hillt5 overridding Payment Estimate Exception 13 on the current Payment Estimate.																		



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks														
J6I2222	0675	CONCRETE TRAFFIC BARRIER,	Material		14	Feb 2, 2021	SYSTEM	(\$66,845.00)															
		TYPE C			15	Feb 16, 2021	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schlag1 overridding Payment Estimate Exception 21 on the current Payment Estimate.														
					15	Feb 16, 2021	SYSTEM	(\$66,845.00)															
					16	Mar 2, 2021	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kloepj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.														
					16	Mar 2, 2021	SYSTEM	(\$66,845.00)															
					17	Mar 16, 2021	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kloepj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.														
					17	Mar 16, 2021	SYSTEM	(\$66,845.00)															
					18	Apr 2, 2021	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kloepj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.														
					18	Apr 2, 2021	SYSTEM	(\$66,845.00)															
							19	Apr 16, 2021	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.												
									19	Apr 16, 2021	SYSTEM	(\$66,845.00)											
						20	May 3, 2021	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hillt5 overridding Payment Estimate Exception 19 on the current Payment Estimate.													
						20	May 3, 2021	SYSTEM	(\$66,845.00)														
					21	May 17, 2021	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hillt5 overridding Payment Estimate Exception 33 on the current Payment Estimate.														
					21	May 17, 2021	SYSTEM	(\$66,845.00)															
					22	Jun 2, 2021	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hillt5 overridding Payment Estimate Exception 36 on the current Payment Estimate.														
						22	Jun 2, 2021	SYSTEM	(\$66,845.00)														
								23	Jun 16, 2021	SYSTEM	\$66,845.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kloepj1 overridding Payment Estimate Exception 39 on the current Payment Estimate.											
																		23	Jun 16, 2021	SYSTEM	(\$66,845.00)		
					2 2 2 2 2 2	2 2 2 2 2 2			24	Jul 1, 2021	SYSTEM	\$70,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user herrmt1 overridding Payment Estimate Exception 22 on the current Payment Estimate.										
										24	Jul 1, 2021	SYSTEM	(\$70,325.00)										
								2		2:		25	Jul 16, 2021	SYSTEM	\$70,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment Estimate Exception 23 on the current Payment Estimate.							
												2	2		25	Jul 16, 2021	SYSTEM	(\$70,325.00)					
															2					26	Aug 2, 2021	SYSTEM	\$70,325.00
														26	Aug 2, 2021	SYSTEM	(\$70,325.00)						
												27	Aug 16, 2021	SYSTEM	\$70,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user herrmt1 overridding Payment Estimate Exception 15 on the current Payment Estimate.							
					27	Aug 16, 2021	SYSTEM	(\$70,325.00)															
					28	Sep 2,	SYSTEM	\$70,325.00	This adjustment offsets the original system-generated Material Payment														



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks										
J6I2222	0675	CONCRETE TRAFFIC BARRIER, TYPE C	Material			2021			Estimate Item Adjustment (0009) due to user kloepj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.										
		TTPEC			28	Sep 2, 2021	SYSTEM	(\$70,325.00)											
					29	Sep 16, 2021	SYSTEM	\$70,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 27 on the current Payment Estimate.										
					29	Sep 16, 2021	SYSTEM	(\$70,325.00)											
				- Total				\$0.00											
			Material - To	tal				\$0.00											
	0675 -	Total						\$0.00											
	0690	CONCRETE TRAFFIC BARRIER, TYPE D	Material		6	Oct 1, 2020	SYSTEM	\$15,385.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.										
		(RETAINING WALL)			6	Oct 1, 2020	SYSTEM	(\$15,385.00)											
					7	Oct 16, 2020	SYSTEM	\$51,935.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.										
					7	Oct 16, 2020	SYSTEM	(\$51,935.00)											
					8	Nov 2, 2020	SYSTEM	\$78,625.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user hillt5 overridding Payment Estimate Exception 17 on the current Payment Estimate.										
					8	Nov 2, 2020	SYSTEM	(\$78,625.00)											
					9	Nov 16, 2020	SYSTEM	\$79,900.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user hillt5 overridding Payment Estimate Exception 17 on the current Payment Estimate.										
							9	Nov 16, 2020	SYSTEM	(\$79,900.00)									
					10	Dec 2, 2020	SYSTEM	\$148,325.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.										
					10	Dec 2, 2020	SYSTEM	(\$148,325.00)											
					11	Dec 16, 2020	SYSTEM	\$148,325.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user schlag1 overridding Payment Estimate Exception 17 on the current Payment Estimate.										
					11	Dec 16, 2020	SYSTEM	(\$148,325.00)											
									12	Jan 4, 2021	SYSTEM	\$148,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.						
															12	Jan 4, 2021	SYSTEM	(\$148,325.00)	
										13	Jan 19, 2021	SYSTEM	\$148,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schlag1 overridding Payment Estimate Exception 17 on the current Payment Estimate.					
					13	Jan 19, 2021	SYSTEM	(\$148,325.00)											
													14	Feb 2, 2021	SYSTEM	\$148,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hillt5 overridding Payment Estimate Exception 16 on the current Payment Estimate.		
															14	Feb 2, 2021	SYSTEM	(\$148,325.00)	
																	15	Feb 16, 2021	SYSTEM
									15	Feb 16, 2021	SYSTEM	(\$148,325.00)							
												-	1	11	11	11	11		16
					16	Mar 2, 2021	SYSTEM	(\$148,325.00)											
						2021													



ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
22 (0690	CONCRETE TRAFFIC BARRIER, TYPE D	Material		17	Mar 16, 2021	SYSTEM	\$148,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
		(RETAINING WALL)			17	Mar 16, 2021	SYSTEM	(\$148,325.00)	
					18	Apr 2, 2021	SYSTEM	\$148,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kloep/1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					18	Apr 2, 2021	SYSTEM	(\$148,325.00)	
					19	Apr 16, 2021	SYSTEM	\$148,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					19	Apr 16, 2021	SYSTEM	(\$148,325.00)	
					20	May 3, 2021	SYSTEM	\$194,565.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hillt5 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					20	May 3, 2021	SYSTEM	(\$194,565.00)	
					21	May 17, 2021	SYSTEM	\$194,565.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hillt5 overridding Payment Estimate Exception 35 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$194,565.00)	
					22	Jun 2, 2021	SYSTEM	\$194,565.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user hillt5 overridding Payment Estimate Exception 38 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$194,565.00)	
					23	Jun 16, 2021	SYSTEM	\$194,565.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Paymen Estimate Exception 41 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$194,565.00)	
					24	Jul 1, 2021	SYSTEM	\$194,565.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user herrmt1 overridding Paymer Estimate Exception 23 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$194,565.00)	
					25	Jul 16, 2021	SYSTEM	\$194,565.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Paymen Estimate Exception 24 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$194,565.00)	
					26	Aug 2, 2021	SYSTEM	\$198,517.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user hillt5 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					26	Aug 2, 2021	SYSTEM	(\$198,517.50)	
					27	Aug 16, 2021	SYSTEM	\$198,517.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user herrmt1 overridding Paymer Estimate Exception 16 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$198,517.50)	
					28	Sep 2, 2021	SYSTEM	\$198,517.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Paymen Estimate Exception 16 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$198,517.50)	
				- Total				\$0.00	
	0600	Total	Material - Tot	al				\$0.00 \$0.00	
	0690 - 0710	TEMPORARY TRAFFIC BARRIER,	Overrun	Overrun	20	May 3, 2021	SYSTEM	\$0.00 \$5,840.45	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user hillts overridding Payment
		CONT. FURN/RE			20	May 3,	SYSTEM	(\$5,840.45)	Estimate Exception 94 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks							
J6I2222	0710	TEMPORARY TRAFFIC BARRIER,	Overrun	Overrun		2021										
		CONT. FURN/RE			21	May 17, 2021	SYSTEM	(\$5,840.45)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).							
				Overrun - To	otal			(\$5,840.45)								
			Overrun - To	tal				(\$5,840.45)								
	0710 -							(\$5,840.45)								
	0730	MISC. CONCRETE TRAFFIC BARRIER	Material		29	Sep 16, 2021	SYSTEM	\$18,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.							
					29	Sep 16, 2021	SYSTEM	(\$18,000.00)								
				- Total				\$0.00								
			Material - To	tal				\$0.00								
	0730 -	Total						\$0.00								
	0990	MISC. GEOTEXTILE	Material		6	Oct 1, 2020	SYSTEM	\$11,470.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 25 on the current Payment Estimate.							
					6	Oct 1, 2020	SYSTEM	(\$11,470.00)								
					7	Oct 16, 2020	SYSTEM	\$32,782.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 25 on the current Payment Estimate.							
												7	Oct 16, 2020	SYSTEM	(\$32,782.50)	
					8	Nov 2, 2020	SYSTEM	\$32,782.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user hillt5 overridding Payment Estimate Exception 20 on the current Payment Estimate.							
					8	Nov 2, 2020	SYSTEM	(\$32,782.50)								
					9	Nov 16, 2020	SYSTEM	\$32,782.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user hillt5 overridding Payment Estimate Exception 20 on the current Payment Estimate.							
					9	Nov 16, 2020	SYSTEM	(\$32,782.50)								
					10	Dec 2, 2020	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.							
					10	Dec 2, 2020	SYSTEM	(\$37,215.50)	Estimate Exception 25 on the earlown dynam Estimate.							
					11	Dec 16, 2020	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user schlag1 overridding Payment Estimate Exception 19 on the current Payment Estimate.							
					11	Dec 16, 2020	SYSTEM	(\$37,215.50)								
						12	Jan 4, 2021	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.						
					12	Jan 4, 2021	SYSTEM	(\$37,215.50)								
			1									13	Jan 19, 2021	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schlag1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
																13
					14	Feb 2, 2021	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 18 on the current Payment Estimate.							
					14	Feb 2, 2021	SYSTEM	(\$37,215.50)								
					15	Feb 16, 2021	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schlag1 overridding Payment Estimate Exception 26 on the current Payment Estimate.							
					15	Feb 16, 2021	SYSTEM	(\$37,215.50)								
					16	Mar 2, 2021	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment							



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks													
J6I2222	0990	MISC. GEOTEXTILE	Material						Estimate Exception 27 on the current Payment Estimate.													
					16	Mar 2, 2021	SYSTEM	(\$37,215.50)														
					17	Mar 16, 2021	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.													
					17	Mar 16, 2021	SYSTEM	(\$37,215.50)														
					18	Apr 2, 2021	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment Estimate Exception 23 on the current Payment Estimate.													
					18	Apr 2, 2021	SYSTEM	(\$37,215.50)														
					19	Apr 16, 2021	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user kloepj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.													
							19	Apr 16, 2021	SYSTEM	(\$37,215.50)												
						20	May 3, 2021	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hillt5 overridding Payment Estimate Exception 25 on the current Payment Estimate.												
								20	May 3, 2021	SYSTEM	(\$37,215.50)											
							21	May 17, 2021	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user hillt5 overridding Payment Estimate Exception 38 on the current Payment Estimate.											
					21	May 17, 2021	SYSTEM	(\$37,215.50)														
						22	Jun 2, 2021	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user hillt5 overridding Payment Estimate Exception 41 on the current Payment Estimate.												
					22	Jun 2, 2021	SYSTEM	(\$37,215.50)														
					23	Jun 16, 2021	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 44 on the current Payment Estimate.													
					23	Jun 16, 2021	SYSTEM	(\$37,215.50)														
					24	Jul 1, 2021	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user herrmt1 overridding Payment Estimate Exception 24 on the current Payment Estimate.													
					24	Jul 1, 2021	SYSTEM	(\$37,215.50)														
																		25	Jul 16, 2021	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
																		25	Jul 16, 2021	SYSTEM	(\$37,215.50)	
																				26	Aug 2, 2021	SYSTEM
					26	Aug 2, 2021	SYSTEM	(\$37,215.50)														
																		27	Aug 16, 2021	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user herrmt1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
																		27	Aug 16, 2021	SYSTEM	(\$37,215.50)	
					28	Sep 2, 2021	SYSTEM	(\$37,215.50)														
													29	Sep 16, 2021	SYSTEM	\$37,215.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.					
					29	Sep 16, 2021	SYSTEM	(\$37,215.50)														



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																		
J6I2222	0990	MISC. GEOTEXTILE	Material	- Total				\$0.00																			
			Material - To	tal				\$0.00																			
	0990 -	Total						\$0.00																			
	1050	MISC.	Material		8	Nov 2, 2020	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user hillt5 overridding Payment Estimate Exception 21 on the current Payment Estimate.																		
					8	Nov 2, 2020	SYSTEM	(\$23,800.00)																			
					9	Nov 16, 2020	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user hillt5 overridding Payment Estimate Exception 21 on the current Payment Estimate.																		
					9	Nov 16, 2020	SYSTEM	(\$23,800.00)																			
						10	Dec 2, 2020	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.																	
					10	Dec 2, 2020	SYSTEM	(\$23,800.00)																			
					11	Dec 16, 2020	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user schlag1 overridding Payment Estimate Exception 20 on the current Payment Estimate.																		
												11	Dec 16, 2020	SYSTEM	(\$23,800.00)												
													12	Jan 4, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kloepj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.										
					12	Jan 4, 2021	SYSTEM	(\$23,800.00)																			
					13	Jan 19, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schlag1 overridding Payment Estimate Exception 20 on the current Payment Estimate.																		
					13	Jan 19, 2021	SYSTEM	(\$23,800.00)																			
					14	Feb 2, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hillt5 overridding Payment Estimate Exception 31 on the current Payment Estimate.																		
					14	Feb 2, 2021	SYSTEM	(\$23,800.00)																			
						15	Feb 16, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schlag1 overridding Payment Estimate Exception 39 on the current Payment Estimate.																	
										15	Feb 16, 2021	SYSTEM	(\$23,800.00)														
																					16	Mar 2, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kloepj1 overridding Payment Estimate Exception 35 on the current Payment Estimate.		
																	16	Mar 2, 2021	SYSTEM	(\$23,800.00)							
															17	Mar 16, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.								
								17	Mar 16, 2021	SYSTEM	(\$23,800.00)																
																		1		1			18	Apr 2, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
																18	Apr 2, 2021	SYSTEM	(\$23,800.00)								
					19	Apr 16, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.																		
					19	Apr 16, 2021	SYSTEM	(\$23,800.00)																			
					20	May 3, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hillt5 overridding Payment Estimate Exception 31 on the current Payment Estimate.																		
					20	May 3,	SYSTEM	(\$23,800.00)																			



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks													
J6I2222	1050	MISC.	Material			2021																
					21	May 17, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user hillt5 overridding Payment Estimate Exception 51 on the current Payment Estimate.													
					21	May 17, 2021	SYSTEM	(\$23,800.00)														
					22	Jun 2, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user hillt5 overridding Payment Estimate Exception 63 on the current Payment Estimate.													
					22	Jun 2, 2021	SYSTEM	(\$23,800.00)														
					23	Jun 16, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 66 on the current Payment Estimate.													
					23	Jun 16, 2021	SYSTEM	(\$23,800.00)														
					24	Jul 1, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user herrmt1 overridding Payment Estimate Exception 36 on the current Payment Estimate.													
					24	Jul 1, 2021	SYSTEM	(\$23,800.00)														
					25	Jul 16, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.													
					25	Jul 16, 2021	SYSTEM	(\$23,800.00)														
					26	Aug 2, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user hillt5 overridding Payment Estimate Exception 33 on the current Payment Estimate.													
													26	Aug 2, 2021	SYSTEM	(\$23,800.00)						
							27	Aug 16, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user herrmt1 overridding Payment Estimate Exception 25 on the current Payment Estimate.											
					27	Aug 16, 2021	SYSTEM	(\$23,800.00)														
					28	Sep 2, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 25 on the current Payment Estimate.													
					28	Sep 2, 2021	SYSTEM	(\$23,800.00)														
					29	Sep 16, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 40 on the current Payment Estimate.													
					29	Sep 16, 2021	SYSTEM	(\$23,800.00)														
				- Total				\$0.00														
			Material - Tot	al				\$0.00														
	1050 -	Total						\$0.00														
	1060	AESTHETIC CONCRETE STAIN	Material		28	Sep 2, 2021	SYSTEM	\$6,110.88	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.													
					28	Sep 2, 2021	SYSTEM	(\$6,110.88)														
																	2	29	Sep 16, 2021	SYSTEM	\$6,110.88	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 41 on the current Payment Estimate.
					29	Sep 16, 2021	SYSTEM	(\$6,110.88)														
				- Total				\$0.00														
			Material - Tot	al				\$0.00														
	1060 -	Total						\$0.00														
	1090	MECHANICALLY STABILIZED EARTH WALL SYS	Material		7	Oct 16, 2020	SYSTEM	\$203,640.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.													
					7	Oct 16,	SYSTEM	(\$203,640.00)														



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																						
J6I2222	1090	MECHANICALLY	Material			2020																									
		STABILIZED EARTH WALL SYS			8	Nov 2, 2020	SYSTEM	\$203,640.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user hillt5 overridding Payment Estimate Exception 26 on the current Payment Estimate.																						
					8	Nov 2, 2020	SYSTEM	(\$203,640.00)																							
					9	Nov 16, 2020	SYSTEM	\$203,640.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user hillt5 overridding Payment Estimate Exception 26 on the current Payment Estimate.																						
					9	Nov 16, 2020	SYSTEM	(\$203,640.00)																							
					10	Dec 2, 2020	SYSTEM	\$203,640.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.																						
					10	Dec 2, 2020	SYSTEM	(\$203,640.00)																							
							11	Dec 16, 2020	SYSTEM	\$203,640.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user schlag1 overridding Payment Estimate Exception 24 on the current Payment Estimate.																				
					11	Dec 16, 2020	SYSTEM	(\$203,640.00)																							
									12	Jan 4, 2021	SYSTEM	\$203,640.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.																		
					12	Jan 4, 2021	SYSTEM	(\$203,640.00)																							
										13	Jan 19, 2021	SYSTEM	\$203,640.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schlag1 overridding Payment Estimate Exception 21 on the current Payment Estimate.																	
										13	Jan 19, 2021	SYSTEM	(\$203,640.00)																		
							14	Feb 2, 2021	SYSTEM	\$203,640.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hillt5 overridding Payment Estimate Exception 49 on the current Payment Estimate.																				
					14	Feb 2, 2021	SYSTEM	(\$203,640.00)																							
				- Total				\$0.00																							
			Material - Tot	tal				\$0.00																							
	1090 -	Total						\$0.00																							
	1100	SELECT GRANULAR BACKFILL FOR	Material		7	Oct 16, 2020	SYSTEM	\$41,310.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.																						
		STRUCTURAL			7	Oct 16, 2020	SYSTEM	(\$41,310.00)																							
													11	Dec 16, 2020	SYSTEM	\$256,560.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user schlag1 overridding Payment Estimate Exception 26 on the current Payment Estimate.														
																				11	Dec 16, 2020	SYSTEM	(\$256,560.00)								
																														12	Jan 4, 2021
																	12	Jan 4, 2021	SYSTEM	(\$256,560.00)											
															13	Jan 19, 2021	SYSTEM	\$256,560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schlag1 overridding Payment Estimate Exception 24 on the current Payment Estimate.												
					13	Jan 19, 2021	SYSTEM	(\$256,560.00)																							
																						1	1.	14	Feb 2, 2021	SYSTEM	\$256,560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hillt5 overridding Payment Estimate Exception 52 on the current Payment Estimate.			
									14	Feb 2, 2021	SYSTEM	(\$256,560.00)																			
					15	Feb 16, 2021	SYSTEM	\$256,560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schlag1 overridding Payment Estimate Exception 51 on the current Payment Estimate.																						



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks					
J6I2222	1100	SELECT GRANULAR	Material		15	Feb 16, 2021	SYSTEM	(\$256,560.00)						
		BACKFILL FOR STRUCTURAL			16	Mar 2, 2021	SYSTEM	\$256,560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Exception 50 on the current Payment Estimate.					
					16	Mar 2, 2021	SYSTEM	(\$256,560.00)						
					17	Mar 16, 2021	SYSTEM	\$256,560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kloepj1 overridding Payment Estimate Exception 43 on the current Payment Estimate.					
					17	Mar 16, 2021	SYSTEM	(\$256,560.00)						
					18	Apr 2, 2021	SYSTEM	\$286,560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Exception 48 on the current Payment Estimate.					
					18	Apr 2, 2021	SYSTEM	(\$286,560.00)						
				- Total				\$0.00						
			Material - Tot	tal				\$0.00						
	1100 -	Total						\$0.00						
	1160	MISC.	Material		9	Nov 16, 2020	SYSTEM	\$49,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user hillt5 overridding Payment Estimate Exception 29 on the current Payment Estimate.					
					9	Nov 16, 2020	SYSTEM	(\$49,500.00)						
									10	Dec 2, 2020	SYSTEM	\$55,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.	
					10	Dec 2, 2020	SYSTEM	(\$55,000.00)						
							11	Dec 16, 2020	SYSTEM	\$55,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user schlag1 overridding Payment Estimate Exception 27 on the current Payment Estimate.			
											11	Dec 16, 2020	SYSTEM	(\$55,000.00)
						12	Jan 4, 2021	SYSTEM	\$55,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.				
					12	Jan 4, 2021	SYSTEM	(\$55,000.00)						
					13	Jan 19, 2021	SYSTEM	\$55,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schlag1 overridding Payment Estimate Exception 25 on the current Payment Estimate.					
					13	Jan 19, 2021	SYSTEM	(\$55,000.00)						
				- Total				\$0.00						
			Material - Tot	tal				\$0.00						
	1160 -	Total						\$0.00						
	1170	PRECAST CONCRETE DROP INLET 2 FT X 2 FT	Material		3	Aug 17, 2020	SYSTEM	\$2,450.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.					
									3	Aug 17, 2020	SYSTEM	(\$2,450.00)		
					4	Sep 2, 2020	SYSTEM	\$4,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.					
					4	Sep 2, 2020	SYSTEM	(\$4,200.00)						
					5	Sep 16, 2020	SYSTEM	\$4,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.					
					5	Sep 16, 2020	SYSTEM	(\$4,200.00)						
					6	Oct 1, 2020	SYSTEM	\$4,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.					



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks														
J6I2222	1170	PRECAST CONCRETE DROP	Material		6	Oct 1, 2020	SYSTEM	(\$4,200.00)															
		INLET 2 FT X 2 FT			7	Oct 16, 2020	SYSTEM	\$4,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment Estimate Exception 30 on the current Payment Estimate.														
					7	Oct 16, 2020	SYSTEM	(\$4,200.00)															
				- Total				\$0.00															
			Material - Tot	tal				\$0.00															
	1170 -	Total						\$0.00															
	1180	PRECAST CONCRETE DROP INLET 4 FT X 2 FT	Material		3	Aug 17, 2020	SYSTEM	\$8,100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.														
					3	Aug 17, 2020	SYSTEM	(\$8,100.00)															
					4	Sep 2, 2020	SYSTEM	\$8,550.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.														
					4	Sep 2, 2020	SYSTEM	(\$8,550.00)															
						5	Sep 16, 2020	SYSTEM	\$8,550.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.													
											5	Sep 16, 2020	SYSTEM	(\$8,550.00)									
					6	Oct 1, 2020	SYSTEM	\$8,550.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 27 on the current Payment Estimate.														
					6	Oct 1, 2020	SYSTEM	(\$8,550.00)															
				- Total				\$0.00															
			Material - Tot	tal				\$0.00															
	1180 -	Total						\$0.00															
	1190	PRECAST CONCRETE DROP INLET 5 FT X 3 FT	Material		6	Oct 1, 2020	SYSTEM	\$1,950.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.														
					6	Oct 1, 2020	SYSTEM	(\$1,950.00)															
					7	Oct 16, 2020	SYSTEM	\$15,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.														
					7	Oct 16, 2020	SYSTEM	(\$15,600.00)															
																			25	Jul 16, 2021	SYSTEM	\$35,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kloepj1 overridding Payment Estimate Exception 71 on the current Payment Estimate.
																							25
													26	Aug 2, 2021	SYSTEM	\$35,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hillt5 overridding Payment Estimate Exception 75 on the current Payment Estimate.						
																			26	Aug 2, 2021	SYSTEM	(\$35,750.00)	
																		27	Aug 16, 2021	SYSTEM	\$35,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user herrmt1 overridding Payment Estimate Exception 71 on the current Payment Estimate.	
				27	27	Aug 16, 2021	SYSTEM	(\$35,750.00)															
						28	Sep 2, 2021	SYSTEM	\$35,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment Estimate Exception 75 on the current Payment Estimate.													
					28	Sep 2, 2021	SYSTEM	(\$35,750.00)															
								29	Sep 16, 2021	SYSTEM	\$38,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kloepj1 overridding Payment Estimate Exception 90 on the current Payment Estimate.											



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J6I2222	1190	PRECAST CONCRETE DROP	Material	, ,,	29	Sep 16, 2021	SYSTEM	(\$38,350.00)		
		INLET 5 FT X 3 FT		- Total				\$0.00		
			Material - To	tal				\$0.00		
	1190 -	Total						\$0.00		
	1200	MISC. MANHOLES AND DROP INLETS	Material		3	Aug 17, 2020	SYSTEM	\$5,610.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	
					3	Aug 17, 2020	SYSTEM	(\$5,610.00)		
					4	Sep 2, 2020	SYSTEM	\$5,610.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	
					4	Sep 2, 2020	SYSTEM	(\$5,610.00)		
					5	Sep 16, 2020	SYSTEM	\$5,610.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	
					5	Sep 16, 2020	SYSTEM	(\$5,610.00)		
					6	Oct 1, 2020	SYSTEM	\$10,710.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 30 on the current Payment Estimate.	
					6	Oct 1, 2020	SYSTEM	(\$10,710.00)		
						7	Oct 16, 2020	SYSTEM	\$10,710.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					7	Oct 16, 2020	SYSTEM	(\$10,710.00)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	1200 -							\$0.00		
	1210	MISC. MANHOLES AND DROP INLETS								
	1210		Material		6	Oct 1, 2020	SYSTEM	\$3,850.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.	
	1210		Material		6		SYSTEM	\$3,850.00 (\$3,850.00)	Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment	
	1210		Material			2020 Oct 1,			Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment	
	1210		Material		6	2020 Oct 1, 2020 Oct 16,	SYSTEM	(\$3,850.00)	Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment	
	1210		Material		6	2020 Oct 1, 2020 Oct 16, 2020 Oct 16,	SYSTEM	(\$3,850.00) \$12,950.00	Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment	
	1210		Material		6 7 7	2020 Oct 1, 2020 Oct 16, 2020 Oct 16, 2020 Jan 4,	SYSTEM SYSTEM	(\$3,850.00) \$12,950.00 (\$12,950.00)	Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment	
	1210		Material		6 7 7 12	2020 Oct 1, 2020 Oct 16, 2020 Oct 16, 2020 Jan 4, 2021 Jan 4,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$3,850.00) \$12,950.00 (\$12,950.00) \$1,750.00	Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment	
	1210		Material		6 7 7 12 12	2020 Oct 1, 2020 Oct 16, 2020 Oct 16, 2020 Jan 4, 2021 Jan 4, 2021 Jan 19,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$3,850.00) \$12,950.00 (\$12,950.00) \$1,750.00 (\$1,750.00)	Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schlag1 overridding Payment	
	1210		Material		6 7 7 12 12 13	2020 Oct 1, 2020 Oct 16, 2020 Oct 16, 2020 Jan 4, 2021 Jan 19, 2021 Jan 19, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$3,850.00) \$12,950.00 (\$12,950.00) \$1,750.00 (\$1,750.00) \$1,750.00	Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schlag1 overridding Payment Estimate Item Adjustment (0005) due to user schlag1 overridding Payment	
	1210		Material		6 7 7 12 12 13 13	2020 Oct 1, 2020 Oct 16, 2020 Oct 16, 2020 Jan 4, 2021 Jan 19, 2021 Jan 19, 2021 Feb 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$3,850.00) \$12,950.00 (\$12,950.00) \$1,750.00 (\$1,750.00) \$1,750.00	Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schlag1 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 26 on the current Payment Estimate.	
	1210		Material		6 7 7 12 12 13 13 14	2020 Oct 1, 2020 Oct 16, 2020 Oct 16, 2020 Jan 4, 2021 Jan 19, 2021 Jan 19, 2021 Feb 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$3,850.00) \$12,950.00 (\$12,950.00) \$1,750.00 (\$1,750.00) \$1,750.00 (\$1,750.00)	Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schlag1 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 26 on the current Payment Estimate.	
	1210		Material		6 7 7 12 12 13 13 14 14 14	2020 Oct 1, 2020 Oct 16, 2020 Oct 16, 2020 Jan 4, 2021 Jan 19, 2021 Jan 19, 2021 Feb 2, 2021 Feb 2, 2021 Feb 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$3,850.00) \$12,950.00 (\$12,950.00) \$1,750.00 (\$1,750.00) \$1,750.00 (\$1,750.00) (\$1,750.00)	Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schlag1 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hillt5 overridding Payment Estimate Exception 53 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 53 on the current Payment Estimate.	
	1210		Material	- Total	6 7 7 12 12 13 13 14 14 15	2020 Oct 1, 2020 Oct 16, 2020 Oct 16, 2020 Jan 4, 2021 Jan 19, 2021 Feb 2, 2021 Feb 16, 2021 Feb 16, 2021	SYSTEM	(\$3,850.00) \$12,950.00 (\$12,950.00) \$1,750.00 (\$1,750.00) \$1,750.00 (\$1,750.00) \$1,750.00 (\$1,750.00)	Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schlag1 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hillt5 overridding Payment Estimate Exception 53 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schlag1 overridding Payment Estimate Item Adjustment (0004) due to user schlag1 overridding Payment Estimate Item Adjustment (0004) due to user schlag1 overridding Payment	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																		
J6I2222	1210 -	Total						\$0.00																			
	1220	15 IN. GROUP A FLARED END SECT	Material		6	Oct 1, 2020	SYSTEM	\$800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.																		
					6	Oct 1, 2020	SYSTEM	(\$800.00)																			
					7	Oct 16, 2020	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 34 on the current Payment Estimate.																		
					7	Oct 16, 2020	SYSTEM	(\$1,600.00)																			
					8	Nov 2, 2020	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user hillt5 overridding Payment Estimate Exception 29 on the current Payment Estimate.																		
					8	Nov 2, 2020	SYSTEM	(\$1,600.00)																			
											9	Nov 16, 2020	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user hillt5 overridding Payment Estimate Exception 30 on the current Payment Estimate.												
												9	Nov 16, 2020	SYSTEM	(\$1,600.00)												
										10	Dec 2, 2020	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user kloepj1 overridding Payment Estimate Exception 30 on the current Payment Estimate.													
					10	Dec 2, 2020	SYSTEM	(\$1,600.00)																			
								11		11	Dec 16, 2020	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user schlag1 overridding Payment Estimate Exception 28 on the current Payment Estimate.													
									11	Dec 16, 2020	SYSTEM	(\$1,600.00)															
							12	Jan 4, 2021	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kloepj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.																
													12	Jan 4, 2021	SYSTEM	(\$1,600.00)											
					13	Jan 19, 2021	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schlag1 overridding Payment Estimate Exception 28 on the current Payment Estimate.																		
					13	Jan 19, 2021	SYSTEM	(\$1,600.00)																			
				- Total				\$0.00																			
			Material - To	tal				\$0.00																			
	1220 -	Total						\$0.00																			
	1290	ROCK DITCH CHECK	Material	Material	4	Sep 2, 2020	SYSTEM	\$252.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.																		
																				4	4	4	4	Sep 2, 2020	SYSTEM	(\$252.00)	
																			5	Sep 16, 2020	SYSTEM	\$252.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.				
					5	Sep 16, 2020	SYSTEM	(\$252.00)																			
					6	Oct 1, 2020	SYSTEM	\$252.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.																		
					6	Oct 1, 2020	SYSTEM	(\$252.00)																			
					7					7	Oct 16, 2020	SYSTEM	\$252.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Exception 35 on the current Payment Estimate.													
						7	Oct 16, 2020	SYSTEM	(\$252.00)																		
											8	Nov 2, 2020	SYSTEM	\$252.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 30 on the current Payment Estimate.												



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6l2222	1290	ROCK DITCH CHECK	Material	Турс	8	Nov 2, 2020	SYSTEM	(\$252.00)	
					9	Nov 16, 2020	SYSTEM	\$252.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					9	Nov 16, 2020	SYSTEM	(\$252.00)	
					10	Dec 2, 2020	SYSTEM	\$252.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user kloepj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					10	Dec 2, 2020	SYSTEM	(\$252.00)	
					11	Dec 16, 2020	SYSTEM	\$252.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user schlag1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					11	Dec 16, 2020	SYSTEM	(\$252.00)	
					12	Jan 4, 2021	SYSTEM	\$252.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user kloepj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					12	Jan 4, 2021	SYSTEM	(\$252.00)	
					13	Jan 19, 2021	SYSTEM	\$252.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schlag1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					13	Jan 19, 2021	SYSTEM	(\$252.00)	
					14	Feb 2, 2021	SYSTEM	\$252.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 55 on the current Payment Estimate.
					14	Feb 2, 2021	SYSTEM	(\$252.00)	
					15	Feb 16, 2021	SYSTEM	\$252.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schlag1 overridding Payment Estimate Exception 54 on the current Payment Estimate.
					15	Feb 16, 2021	SYSTEM	(\$252.00)	
				- Total				\$0.00	
	1290 -	Total	Material - To	tal				\$0.00 \$0.00	
	1320	TEMPORARY SEEDING AND MULCHING	Material		25	Jul 16, 2021	SYSTEM	\$2,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 73 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$2,400.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1320 - 1330	SILT FENCE	Material		4	Sep 2, 2020	SYSTEM	\$0.00 \$4,506.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					4	Sep 2, 2020	SYSTEM	(\$4,506.75)	
					5	Sep 16, 2020	SYSTEM	\$4,506.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					5	Sep 16, 2020	SYSTEM	(\$4,506.75)	
					6	Oct 1, 2020	SYSTEM	\$4,506.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					6	Oct 1, 2020	SYSTEM	(\$4,506.75)	
					7	Oct 16, 2020	SYSTEM	\$4,506.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user kloepj1 overridding Payment Estimate Exception 36 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																	
J6I2222	1330	SILT FENCE	Material		7	Oct 16, 2020	SYSTEM	(\$4,506.75)																		
				- Total				\$0.00																		
			Material - To	tal				\$0.00																		
	1330 -	Total						\$0.00																		
	1490	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		5	Sep 16, 2020	SYSTEM	\$12,444.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																	
					5	Sep 16, 2020	SYSTEM	(\$12,444.25)																		
					6	Oct 1, 2020	SYSTEM	\$14,110.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																	
					6	Oct 1, 2020	SYSTEM	(\$14,110.85)																		
					7	Oct 16, 2020	SYSTEM	\$17,094.16	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																	
											7	Oct 16, 2020	SYSTEM	(\$17,094.16)												
						8	Nov 2, 2020	SYSTEM	\$17,094.16	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user hillt5 overridding Payment Estimate Exception 2 on the current Payment Estimate.																
					8	Nov 2, 2020	SYSTEM	(\$17,094.16)																		
					9	Nov 16, 2020	SYSTEM	\$17,094.16	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user hillt5 overridding Payment Estimate Exception 2 on the current Payment Estimate.																	
					9	Nov 16, 2020	SYSTEM	(\$17,094.16)																		
					10	Dec 2, 2020	SYSTEM	\$17,094.16	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																	
					10	Dec 2, 2020	SYSTEM	(\$17,094.16)																		
					11	Dec 16, 2020	SYSTEM	\$17,094.16	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user schlag1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																	
					11	Dec 16, 2020	SYSTEM	(\$17,094.16)																		
											12	Jan 4, 2021	SYSTEM	\$17,094.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user kloepj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.											
					12	Jan 4, 2021	SYSTEM	(\$17,094.16)																		
										13	Jan 19, 2021	SYSTEM	\$17,094.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schlag1 overridding Payment Estimate Exception 2 on the current Payment Estimate.												
							13	Jan 19, 2021	SYSTEM	(\$17,094.16)																
								14	Feb 2, 2021	SYSTEM	\$17,094.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hillt5 overridding Payment Estimate Exception 2 on the current Payment Estimate.														
																	14	Feb 2, 2021	SYSTEM	(\$17,094.16)						
																			15	Feb 16, 2021	SYSTEM	\$17,094.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schlag1 overridding Payment Estimate Exception 2 on the current Payment Estimate.			
															15	Feb 16, 2021	SYSTEM	(\$17,094.16)								
						16	Mar 2, 2021	SYSTEM	\$17,094.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																
																						16	Mar 2, 2021	SYSTEM	(\$17,094.16)	
						17	Mar 16, 2021	SYSTEM	\$17,094.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment																



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																										
J6I2222	1490	TYPE 5 AGGREGATE FOR	Material						Estimate Exception 1 on the current Payment Estimate.																										
		BASE (6 IN. THICK)			17	Mar 16, 2021	SYSTEM	(\$17,094.16)																											
					18	Apr 2, 2021	SYSTEM	\$17,094.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																										
					18	Apr 2, 2021	SYSTEM	(\$17,094.16)																											
					19	Apr 16, 2021	SYSTEM	\$23,568.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																										
					19	Apr 16, 2021	SYSTEM	(\$23,568.16)																											
					20	May 3, 2021	SYSTEM	\$24,747.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hillt5 overridding Payment Estimate Exception 1 on the current Payment Estimate.																										
					20	May 3, 2021	SYSTEM	(\$24,747.26)																											
											21	May 17, 2021	SYSTEM	\$25,904.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user hillt5 overridding Payment Estimate Exception 2 on the current Payment Estimate.																				
										21	May 17, 2021	SYSTEM	(\$25,904.26)																						
					22	Jun 2, 2021	SYSTEM	\$27,859.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate.																										
								22	Jun 2, 2021	SYSTEM	(\$27,859.46)																								
						23	Jun 16, 2021	SYSTEM	\$39,318.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user kloepj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.																									
					23	Jun 16, 2021	SYSTEM	(\$39,318.96)																											
						24	Jul 1, 2021	SYSTEM	\$53,139.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate.																									
						24	Jul 1, 2021	SYSTEM	(\$53,139.26)																										
					25	Jul 16, 2021	SYSTEM	\$59,894.06	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user kloepj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.																										
																25	Jul 16, 2021	SYSTEM	(\$59,894.06)																
													26	Aug 2, 2021	SYSTEM	\$67,031.06	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate.																		
					26	Aug 2, 2021	SYSTEM	(\$67,031.06)																											
																	27	Aug 16, 2021	SYSTEM	\$38,488.59	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user herrmt1 overridding Payment Estimate Exception 1 on the current Payment Estimate.														
													27	Aug 16, 2021	SYSTEM	(\$38,488.59)																			
																	2	2	2	2	2	2:	2:	2:	28	28	28	28	28		28	Sep 2, 2021	SYSTEM	\$52,940.69	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kloep/1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
																															28	Sep 2, 2021	SYSTEM	(\$52,940.69)	
																														29	29	29	2		29
					29	Sep 16, 2021	SYSTEM	(\$61,787.19)																											
				- Total				\$0.00																											
			Material - To	tal				\$0.00																											
			Price FUEL		5	Sep 16, 2020	SYSTEM	\$167.33	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																										



J6I2222 1490 TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) Price FUEL 6 Oct 1, 2020 7 Oct 16, SYSTEM \$33.78 Reference Item Price Adjustment Index Adjustment Type Control of the Price Adjustment Index	
7 Oct 16, SYSTEM \$33.78 Reference Item Price Adjustment Index Adjustment Type	pe applied is FUEL
2020	pe applied is FUEL
19 Apr 16, SYSTEM \$256.57 Reference Item Price Adjustment Index Adjustment Type 2021	pe applied is FUEL
20 May 3, 2021 \$46.73 Reference Item Price Adjustment Index Adjustment Type	pe applied is FUEL
21 May 17, SYSTEM \$52.40 Reference Item Price Adjustment Index Adjustment Type 2021	pe applied is FUEL
22 Jun 2, 2021 \$SYSTEM \$88.56 Reference Item Price Adjustment Index Adjustment Type	pe applied is FUEL
23 Jun 16, 2021 \$523.08 Reference Item Price Adjustment Index Adjustment Type	oe applied is FUEL
24 Jul 1, 2021 \$SYSTEM \$630.84 Reference Item Price Adjustment Index Adjustment Type	oe applied is FUEL
25 Jul 16, 2021 \$313.11 Reference Item Price Adjustment Index Adjustment Type	oe applied is FUEL
26 Aug 2, 2021 \$187.56 Reference Item Price Adjustment Index Adjustment Type	oe applied is FUEL
26 Aug 2, 2021 \$YSTEM \$143.27 Reference Item Price Adjustment Index Adjustment Type	pe applied is FUEL
27 Aug 16, SYSTEM \$685.69 Reference Item Price Adjustment Index Adjustment Type 2021	pe applied is FUEL
28 Sep 2, 2021 \$YSTEM \$710.82 Reference Item Price Adjustment Index Adjustment Type	pe applied is FUEL
29 Sep 16, SYSTEM \$406.94 Reference Item Price Adjustment Index Adjustment Type 2021	pe applied is FUEL
- Total \$4,269.09	
Price FUEL - Total \$4,269.09	
1490 - Total \$4,269.09	
1500 CONCRETE Material 21 May 17, SYSTEM \$4,080.00 This adjustment offsets the original system-generated I PAVEMENT (8 IN. 2021 Estimate Item Adjustment (0036) due to user hillt5 over	
NON-REINFORCED, Estimate Exception 8 on the current Payment Estimate	
NON-REINFORCED, Estimate Exception 8 on the current Payment Estimate 21 May 17, SYSTEM (\$4,080.00)	Material Payment Verridding Payment
NON-REINFORCED, 21 May 17, 2021 (\$4,080.00) 23 Jun 16, SYSTEM 2021 23 SySTEM \$76,168.50 This adjustment offsets the original system-generated I Estimate Item Adjustment (0042) due to user kloepj1 or	Material Payment Verridding Payment
NON-REINFORCED, 21 May 17, 2021 (\$4,080.00) 23 Jun 16, 2021 SYSTEM \$76,168.50 This adjustment offsets the original system-generated I Estimate ltem Adjustment (0042) due to user kloepj1 or Estimate Exception 9 on the current Payment Estimate 23 Jun 16, SYSTEM (\$76,168.50)	Material Payment verridding Payment Material Payment verridding Payment
NON-REINFORCED, 21 May 17, 2021 23 Jun 16, 2021 23 Jun 16, 2021 24 Jul 1, SYSTEM (\$76,168.50) Estimate Exception 8 on the current Payment Estimate Estimate Exception 8 on the current Payment Estimate This adjustment offsets the original system-generated I Estimate Item Adjustment (0042) due to user kloepj1 or Estimate Exception 9 on the current Payment Estimate 23 Jun 16, 2021 24 Jul 1, SYSTEM \$127,591.80 This adjustment offsets the original system-generated I Estimate Item Adjustment (0032) due to user hermat to Estimate Item Adjustment (0032) due to user hermat to	Material Payment verridding Payment Material Payment verridding Payment
NON-REINFORCED, 21 May 17, 2021 (\$4,080.00) 23 Jun 16, 2021 SYSTEM \$76,168.50 This adjustment offsets the original system-generated I Estimate Item Adjustment (0042) due to user kloepj1 or Estimate Exception 9 on the current Payment Estimate 23 Jun 16, 2021 (\$76,168.50) 24 Jul 1, 2021 This adjustment offsets the original system-generated I Estimate Exception 9 on the current Payment Estimate 24 Jul 1, SYSTEM \$127,591.80 This adjustment offsets the original system-generated I Estimate Item Adjustment (0032) due to user hermat of Estimate Exception 7 on the current Payment Estimate 24 Jul 1, SYSTEM (\$127,591.80)	Material Payment verridding Payment Material Payment verridding Payment Material Payment verridding Payment
NON-REINFORCED, 21 May 17, 2021 (\$4,080.00) 23 Jun 16, 2021 SYSTEM \$76,168.50 This adjustment offsets the original system-generated I Estimate Exception 9 on the current Payment Estimate 23 Jun 16, 2021 (\$76,168.50) 24 Jul 1, 2021 SYSTEM \$127,591.80 This adjustment offsets the original system-generated I Estimate Item Adjustment (0032) due to user kloep1 or Estimate Exception 9 on the current Payment Estimate Estimate Item Adjustment (0032) due to user hermal of Estimate Item Adjustment (0032) due to user hermal of Estimate Exception 7 on the current Payment Estimate 24 Jul 1, 2021 SYSTEM (\$127,591.80) 25 Jul 16, 2021 This adjustment offsets the original system-generated I Estimate Item Adjustment (0046) due to user kloep1 or Estimate	Material Payment verridding Payment Material Payment verridding Payment Material Payment verridding Payment
NON-REINFORCED, Estimate Exception 8 on the current Payment Estimate	Material Payment verridding Payment Material Payment verridding Payment Material Payment verridding Payment verridding Payment
NON-REINFORCED, Estimate Exception 8 on the current Payment Estimate	Material Payment verridding Payment Material Payment verridding Payment Material Payment verridding Payment verridding Payment
NON-REINFORCED, Estimate Exception 8 on the current Payment Estimate	Material Payment verridding Payment Material Payment verridding Payment verridding Payment verridding Payment verridding Payment Material Payment verridding Payment verridding Payment verridding Payment
NON-REINFORCED, Estimate Exception 8 on the current Payment Estimate	Material Payment verridding Payment Material Payment verridding Payment verridding Payment verridding Payment verridding Payment Material Payment verridding Payment verridding Payment verridding Payment
NON-REINFORCED, 21 May 17, 2021 23 Jun 16, 2021 24 Jul 1, 2021 25 Jul 16, 2021 26 Jul 16, 2021 27 Jul 16, 2021 28 SYSTEM (\$4,080.00) 29 Jul 16, 2021 29 Jul 16, 2021 20 Jul 16, 2021 21 Jul 16, 2021 22 Jul 16, 2021 25 Jul 16, 2021 26 Aug 2, 2021 27 Aug 16, SYSTEM (\$211,833.60) 28 SYSTEM (\$211,833.60) 29 SYSTEM (\$211,833.60) 20 This adjustment offsets the original system-generated 1 Estimate Item Adjustment (0046) due to user kloepji or Estimate Exception 7 on the current Payment Estimate Estimate Item Adjustment (0046) due to user kloepji or Estimate Exception 7 on the current Payment Estimate Exception 7 on the current Payment Estimate Estimate Exception 7 on the current Payment Estimate Estimate Exception 3 on the current Payment Estimate 2 on Aug 16, SYSTEM 2626,638.60	Material Payment verridding Payment Material Payment verridding Payment verridding Payment verridding Payment Material Payment verridding Payment Material Payment verridding Payment verridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																	
J6l2222	1500	CONCRETE PAVEMENT (8 IN. NON-REINFORCED,	Material	,	29	Sep 16, 2021	SYSTEM	\$265,638.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0049) due to user kloepj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.																	
		,			29	Sep 16, 2021	SYSTEM	(\$265,638.60)																		
				- Total				\$0.00																		
			Material - To	tal				\$0.00																		
			Price FUEL		21	May 17, 2021	SYSTEM	\$61.44	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																	
					22	Jun 2, 2021	SYSTEM	(\$61.44)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																	
					23	Jun 16, 2021	SYSTEM	\$1,155.97	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																	
					24	Jul 1, 2021	SYSTEM	\$780.42	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																	
					25	Jul 16, 2021	SYSTEM	\$435.29	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																	
					26	Aug 2, 2021	SYSTEM	\$863.02	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																	
					27	Aug 16, 2021	SYSTEM	\$1,216.56	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																	
				28	Sep 2, 2021	SYSTEM	\$339.19	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																		
				- Total				\$4,790.45																		
			Price FUEL -	Total				\$4,790.45																		
	1500 -	Total						\$4,790.45																		
	1510	CONCRETE PAVEMENT (9 IN. NON-REINFORCED,	Material	Material		5	Sep 16, 2020	SYSTEM	\$49,717.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user kloepj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.																
								5	Sep 16, 2020	SYSTEM	(\$49,717.80)															
					6	Oct 1, 2020	SYSTEM	\$63,768.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user kloepj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.																	
					6	Oct 1, 2020	SYSTEM	(\$63,768.60)																		
					7	Oct 16, 2020	SYSTEM	\$68,002.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user kloepj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.																	
					7	Oct 16, 2020	SYSTEM	(\$68,002.20)																		
								8	Nov 2, 2020	SYSTEM	\$68,002.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate.														
														8	Nov 2, 2020	SYSTEM	(\$68,002.20)									
						5									9	Nov 16, 2020	SYSTEM	\$68,002.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate.							
									9	Nov 16, 2020	SYSTEM	(\$68,002.20)														
										1							1	1				10	Dec 2, 2020	SYSTEM	\$68,002.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
												10	Dec 2, 2020	SYSTEM	(\$68,002.20)											
																				11	Dec 16, 2020	SYSTEM	\$68,002.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user schlag1 overridding Payment Estimate Exception 3 on the current Payment Estimate.		
																		11	Dec 16, 2020	SYSTEM	(\$68,002.20)					
							12	Jan 4, 2021	SYSTEM	\$68,002.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.															



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
J6I2222	1510	CONCRETE PAVEMENT (9 IN. NON-REINFORCED,	Material		13	Jan 19, 2021	SYSTEM	\$68,002.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schlag1 overridding Payment Estimate Exception 3 on the current Payment Estimate.		
					13	Jan 19, 2021	SYSTEM	(\$68,002.20)			
					14	Feb 2, 2021	SYSTEM	\$68,002.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user hillt5 overridding Payment Estimate Exception 3 on the current Payment Estimate.		
					14	Feb 2, 2021	SYSTEM	(\$68,002.20)			
					15	Feb 16, 2021	SYSTEM	\$68,002.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schlag1 overridding Payment Estimate Exception 3 on the current Payment Estimate.		
					15	Feb 16, 2021	SYSTEM	(\$68,002.20)			
					16	Mar 2, 2021	SYSTEM	\$68,002.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.		
					16	Mar 2, 2021	SYSTEM	(\$68,002.20)	·		
					17	Mar 16, 2021	SYSTEM	\$68,002.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.		
					17	Mar 16, 2021	SYSTEM	(\$68,002.20)			
					18	Apr 2, 2021	SYSTEM	\$68,002.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.		
					18	Apr 2, 2021	SYSTEM	(\$68,002.20)			
							19	Apr 16, 2021	SYSTEM	\$96,098.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kloepj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					19	Apr 16, 2021	SYSTEM	(\$96,098.40)			
					20	May 3, 2021	SYSTEM	\$96,098.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user hillto overridding Payment Estimate Exception 3 on the current Payment Estimate.		
					20	May 3, 2021	SYSTEM	(\$96,098.40)			
					21	May 17, 2021	SYSTEM	\$105,710.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user hillto overridding Payment Estimate Exception 12 on the current Payment Estimate.		
					21	May 17, 2021	SYSTEM	(\$105,710.40)			
					22	Jun 2, 2021	SYSTEM	\$114,415.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hillt5 overridding Payment Estimate Exception 9 on the current Payment Estimate.		
					22	Jun 2, 2021	SYSTEM	(\$114,415.20)			
					23	Jun 16, 2021	SYSTEM	\$114,415.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user kloepj1 overridding Payment Estimate Exception 13 on the current Payment Estimate.		
					23	Jun 16, 2021	SYSTEM	(\$114,415.20)			
					24	Jul 1, 2021	SYSTEM	\$136,560.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user herrmt1 overridding Payment Estimate Exception 11 on the current Payment Estimate.		
					24	Jul 1, 2021	SYSTEM	(\$136,560.60)			
					25	Jul 16, 2021	SYSTEM	\$160,822.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kloepj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.		
					25	Jul 16, 2021	SYSTEM	(\$160,822.80)			
					26	Aug 2, 2021	SYSTEM	\$160,822.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user hillto overridding Payment Estimate Exception 11 on the current Payment Estimate.		



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	1510	CONCRETE PAVEMENT (9 IN.	Material		26	Aug 2, 2021	SYSTEM	(\$160,822.80)	
		NON-REINFORCED,		- Total				\$0.00	
			Material - To	tal				\$0.00	
			Price FUEL		5	Sep 16, 2020	SYSTEM	\$230.91	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					6	Oct 1, 2020	SYSTEM	\$65.26	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					7	Oct 16, 2020	SYSTEM	\$16.56	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					19	Apr 16, 2021	SYSTEM	\$384.61	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					21	May 17, 2021	SYSTEM	\$150.37	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					22	Jun 2, 2021	SYSTEM	\$136.18	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					24	Jul 1, 2021	SYSTEM	\$349.16	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					25	Jul 16, 2021	SYSTEM	\$388.47	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					27	Aug 16, 2021	SYSTEM	\$77.52	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					28	Sep 2, 2021	SYSTEM	\$1,224.00	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					29	Sep 16, 2021	SYSTEM	\$1,167.74	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$4,190.78	
			Price FUEL -	Total				\$4,190.78	
	1510 -	Total						\$4,190.78	
	1520	INTEGRAL CURB (6 IN. HEIGHT AND UNDER)	Material		21	May 17, 2021	SYSTEM	\$3,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user hillt5 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$3,150.00)	
					22	Jun 2, 2021	SYSTEM	\$3,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user hillt5 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$3,150.00)	
					23	Jun 16, 2021	SYSTEM	\$3,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user kloepj1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$3,150.00)	
					24	Jul 1, 2021	SYSTEM	\$3,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user herrmt1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$3,150.00)	
					25	Jul 16, 2021	SYSTEM	\$3,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user kloepj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$3,150.00)	
					26	Aug 2, 2021	SYSTEM	\$3,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user hillt5 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					26	Aug 2, 2021	SYSTEM	(\$3,150.00)	
					27	Aug 16, 2021	SYSTEM	\$3,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user herrmt1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$3,150.00)	
					28	Sep 2,	SYSTEM	\$3,150.00	This adjustment offsets the original system-generated Material Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	1520	INTEGRAL CURB (6 IN. HEIGHT AND UNDER)	Material			2021			Estimate Item Adjustment (0056) due to user kloepj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
		ONDER()			28	Sep 2, 2021	SYSTEM	(\$3,150.00)	
					29	Sep 16, 2021	SYSTEM	\$3,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0051) due to user kloepj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					29	Sep 16, 2021	SYSTEM	(\$3,150.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
		Total				0.14	OVOTELL	\$0.00	
	1550	TYPE A2 SHOULDER	Material		6	Oct 1, 2020	SYSTEM	\$14,224.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					6	Oct 1, 2020	SYSTEM	(\$14,224.00)	
					7	Oct 16, 2020	SYSTEM	\$30,287.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					7	Oct 16, 2020	SYSTEM	(\$30,287.95)	
					8	Nov 2, 2020	SYSTEM	\$30,287.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user hillt5 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					8	Nov 2, 2020	SYSTEM	(\$30,287.95)	
					9	Nov 16, 2020	SYSTEM	\$30,287.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user hillt5 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					9	Nov 16, 2020	SYSTEM	(\$30,287.95)	
					10	Dec 2, 2020	SYSTEM	\$30,287.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user kloepj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					10	Dec 2, 2020	SYSTEM	(\$30,287.95)	
					11	Dec 16, 2020	SYSTEM	\$30,287.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user schlag1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					11	Dec 16, 2020	SYSTEM	(\$30,287.95)	
					12	Jan 4, 2021	SYSTEM	\$30,287.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					12	Jan 4, 2021	SYSTEM	(\$30,287.95)	
					13	Jan 19, 2021	SYSTEM	\$30,287.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schlag1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					13	Jan 19, 2021	SYSTEM	(\$30,287.95)	
					14	Feb 2, 2021	SYSTEM	\$30,287.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user hillt5 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					14	Feb 2, 2021	SYSTEM	(\$30,287.95)	
					15	Feb 16, 2021	SYSTEM	\$30,287.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schlag1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					15	Feb 16, 2021	SYSTEM	(\$30,287.95)	
					16	Mar 2, 2021	SYSTEM	\$30,287.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					16	Mar 2, 2021	SYSTEM	(\$30,287.95)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	1550	TYPE A2 SHOULDER	Material		17	Mar 16, 2021	SYSTEM	\$30,287.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					17	Mar 16, 2021	SYSTEM	(\$30,287.95)	
					18	Apr 2, 2021	SYSTEM	\$30,287.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					18	Apr 2, 2021	SYSTEM	(\$30,287.95)	
					19	Apr 16, 2021	SYSTEM	\$46,937.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					19	Apr 16, 2021	SYSTEM	(\$46,937.45)	
					20	May 3, 2021	SYSTEM	\$53,286.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user hillt5 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					20	May 3, 2021	SYSTEM	(\$53,286.45)	
					21	May 17, 2021	SYSTEM	\$53,286.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user hillt5 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$53,286.45)	
					22	Jun 2, 2021	SYSTEM	\$53,286.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user hillt5 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$53,286.45)	
					23	Jun 16, 2021	SYSTEM	\$53,286.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user kloepj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$53,286.45)	
					28	Sep 2, 2021	SYSTEM	\$1,386.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0057) due to user kloepj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$1,386.00)	
					29	Sep 16, 2021	SYSTEM	\$1,386.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0052) due to user kloepj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					29	Sep 16, 2021	SYSTEM	(\$1,386.00)	
				- Total				\$0.00	
	1550 -	Total	Material - To	tal				\$0.00 \$0.00	
	1560	INTEGRAL CURB (6 IN. HEIGHT AND UNDER)	Material		6	Oct 1, 2020	SYSTEM	\$3,375.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user kloepj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
		-,			6	Oct 1, 2020	SYSTEM	(\$3,375.00)	
					7	Oct 16, 2020	SYSTEM	\$3,375.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user kloepj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					7	Oct 16, 2020	SYSTEM	(\$3,375.00)	
					8	Nov 2, 2020	SYSTEM	\$3,375.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					8	Nov 2, 2020	SYSTEM	(\$3,375.00)	
					9	Nov 16, 2020	SYSTEM	\$3,375.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user hillt5 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					9	Nov 16,	SYSTEM	(\$3,375.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	1560	INTEGRAL CURB (6	Material			2020			
		IN. HEIGHT AND UNDER)			10	Dec 2, 2020	SYSTEM	\$3,375.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					10	Dec 2, 2020	SYSTEM	(\$3,375.00)	
					11	Dec 16, 2020	SYSTEM	\$3,375.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user schlag1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					11	Dec 16, 2020	SYSTEM	(\$3,375.00)	
					12	Jan 4, 2021	SYSTEM	\$3,375.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					12	Jan 4, 2021	SYSTEM	(\$3,375.00)	
					13	Jan 19, 2021	SYSTEM	\$3,375.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schlag1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					13	Jan 19, 2021	SYSTEM	(\$3,375.00)	
					14	Feb 2, 2021	SYSTEM	\$3,375.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user hillt5 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					14	Feb 2, 2021	SYSTEM	(\$3,375.00)	
					15	Feb 16, 2021	SYSTEM	\$3,375.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schlag1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					15	Feb 16, 2021	SYSTEM	(\$3,375.00)	
					16	Mar 2, 2021	SYSTEM	\$3,375.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					16	Mar 2, 2021	SYSTEM	(\$3,375.00)	
					17	Mar 16, 2021	SYSTEM	\$3,375.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					17	Mar 16, 2021	SYSTEM	(\$3,375.00)	
					18	Apr 2, 2021	SYSTEM	\$3,375.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					18	Apr 2, 2021	SYSTEM	(\$3,375.00)	
					19	Apr 16, 2021	SYSTEM	\$4,575.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					19	Apr 16, 2021	SYSTEM	(\$4,575.00)	
					20	May 3, 2021	SYSTEM	\$7,380.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user hillto overridding Payment Estimate Exception 13 on the current Payment Estimate.
					20	May 3, 2021	SYSTEM	(\$7,380.00)	
					21	May 17, 2021	SYSTEM	\$7,380.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user hillto overridding Payment Estimate Exception 27 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$7,380.00)	
					22	Jun 2, 2021	SYSTEM	\$7,380.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user hillt5 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$7,380.00)	
					23	Jun 16, 2021	SYSTEM	\$7,380.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user kloepj1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	1560	INTEGRAL CURB (6 IN. HEIGHT AND	Material						Estimate Exception 33 on the current Payment Estimate.
		UNDER)			23	Jun 16, 2021	SYSTEM	(\$7,380.00)	
					24	Jul 1, 2021	SYSTEM	\$7,680.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user herrmt1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$7,680.00)	
					25	Jul 16, 2021	SYSTEM	\$7,680.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0048) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$7,680.00)	
					26	Aug 2, 2021	SYSTEM	\$7,680.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user hillt5 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					26	Aug 2, 2021	SYSTEM	(\$7,680.00)	
					27	Aug 16, 2021	SYSTEM	\$7,680.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user herrmt1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$7,680.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1560 -	Total						\$0.00	
	1570	MGS GUARDRAIL	Construction Stockpile		16	Mar 2, 2021	SYSTEM	(\$4,220.86)	Payment Estimate Item Adjustment generated Stockpile Transaction
					20	May 3, 2021	SYSTEM	(\$589.21)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$4,810.07)	
				ı Stockpile - 1			OVOTELA	(\$4,810.07)	
			Construction Stockpile STMI		3	Aug 17, 2020	SYSTEM	\$38,968.86	Payment Estimate Item Adjustment generated Stockpile Transaction
			Construction	- Total Stockpile S1	FML Total			\$38,968.86 \$38,968.86	
			Material	i Stockpile Si	20	May 3,	SYSTEM	\$8,797.00	This adjustment offsets the original system-generated Material Payment
			Waterial		20	2021	OTOTEM	ψο,737.00	Estimate Item Adjustment (0015) due to user hillts overridding Payment Estimate Exception 10 on the current Payment Estimate.
					20	May 3, 2021	SYSTEM	(\$8,797.00)	
					21	May 17, 2021	SYSTEM	\$8,797.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user hillt5 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$8,797.00)	
					22	Jun 2, 2021	SYSTEM	\$8,797.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user hillt5 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$8,797.00)	
					23	Jun 16, 2021	SYSTEM	\$8,797.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$8,797.00)	
					24	Jul 1, 2021	SYSTEM	\$8,797.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user herrmt1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$8,797.00)	
					25	Jul 16, 2021	SYSTEM	\$8,797.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					25	Jul 16,	SYSTEM	(\$8,797.00)	



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
222	1570	MGS GUARDRAIL	Material			2021			
					26	Aug 2, 2021	SYSTEM	\$8,797.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user hillt5 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					26	Aug 2, 2021	SYSTEM	(\$8,797.00)	
					27	Aug 16, 2021	SYSTEM	\$8,797.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user herrmt1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$8,797.00)	
					28	Sep 2, 2021	SYSTEM	\$8,797.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$8,797.00)	
					29	Sep 16, 2021	SYSTEM	\$8,797.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					29	Sep 16, 2021	SYSTEM	(\$8,797.00)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	1570 -	Total						\$34,158.79	
	1580	MGS BRIDGE APP. TRANS SEC (EXT CURB)	Construction Stockpile STMI		3	Aug 17, 2020	SYSTEM	\$3,016.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		COND)	OTIVII	- Total				\$3,016.00	
			Construction	Stockpile ST	MI - Tota			\$3,016.00	
	1580 -							\$3,016.00	
	1590	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	Construction Stockpile STMI		3	Aug 17, 2020	SYSTEM	\$2,920.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			0 1 11	- Total				\$2,920.00	
	4500	T-4-1	Construction	Stockpile S I	IMI - Tota			\$2,920.00	
	1590 - 1600	MGS VERTICAL	Construction		16	Mar 2,	SYSTEM	\$2,920.00 (\$3,795.00)	Doument Estimate Item Adjustment generated Steeknile Transaction
	1000	CONCRETE BARRIER	Stockpile		20	2021 May 3,	SYSTEM	(\$1,265.00)	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
		TRANSITION			20	2021	OTOTEM	, ,	Tayrion Estimate term repeatment generated etection managed
			0 1 11	- Total				(\$5,060.00)	
			Construction Construction Stockpile	- 5 тоскрпе - 1	3	Aug 17, 2020	SYSTEM	(\$5,060.00) \$13,915.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$13,915.00	
			Construction	Stockpile S1	ΓΜΙ - Tota			\$13,915.00	
	1600 -	Total						\$8,855.00	
	1610	MGS END ANCHOR	Construction Stockpile		16	Mar 2, 2021	SYSTEM	(\$532.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$532.00)	
			Construction	Stockpile - T	Total			(\$532.00)	
			Construction Stockpile STMI		3	Aug 17, 2020	SYSTEM	\$4,256.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$4,256.00	
			Construction	Stockpile S1	MI - Tota			\$4,256.00	
	1610 -				40		0)/2==:	\$3,724.00	
	1620	TYPE A CRASHWORTHY END TERMINAL	Construction Stockpile		16	Mar 2, 2021	SYSTEM	(\$4,473.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		(MASH)			20	May 3, 2021	SYSTEM	(\$1,491.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$5,964.00)	
			Construction	Stockpile - T	otal			(\$5,964.00)	



Li								
	ine Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
16	620 TYPE CRASHWORTH	Y Stockpile		3	Aug 17, 2020	SYSTEM	\$17,892.00	Payment Estimate Item Adjustment generated Stockpile Transaction
	END TERMINA (MASI		- Total				\$17,892.00	
	`		n Stockpile S	ΓΜΙ - Tota			\$17,892.00	
16	620 - Total						\$11,928.00	
	630 TYPE	E Construction		2	Viid 3	SYSTEM	\$18,995.00	Payment Estimate Item Adjustment generated Stockpile Transaction
10	CRASHWORTH END TERMINA	Y Stockpile	- Total	2	Aug 3, 2020	STSTEM	\$18,995.00	rayment Estimate tern Adjustitient generated Stockpile Transaction
							<u> </u>	
		Construction	n Stockpile S	I WII - I Ota			\$18,995.00	
16	630 - Total						\$18,995.00	
17	730 CABLE, 10 AWG CONDUCTOI POLE & BRACK	₹,		28	Sep 2, 2021	SYSTEM	\$198.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment Estimate Exception 76 on the current Payment Estimate.
				28	Sep 2, 2021	SYSTEM	(\$198.00)	
				29	Sep 16, 2021	SYSTEM	\$198.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 91 on the current Payment Estimate.
				29	Sep 16, 2021	SYSTEM	(\$198.00)	
			- Total				\$0.00	
		Material - To	tal				\$0.00	
17	730 - Total						\$0.00	
17	740 CABLE-CONDUIT, IN., CONDUCTOR	2		28	Sep 2, 2021	SYSTEM	\$4,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user kloep/1 overridding Payment Estimate Exception 77 on the current Payment Estimate.
				28	Sep 2, 2021	SYSTEM	(\$4,800.00)	
				29	Sep 16, 2021	SYSTEM	\$4,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 92 on the current Payment Estimate.
				29	Sep 16, 2021	SYSTEM	(\$4,800.00)	
			- Total				\$0.00	
		Material - To	tal				\$0.00	
17	740 - Total						\$0.00	
							φυ.υυ	
17	750 CABLE-CONDUIT, IN., CONDUCTOR	2		28	Sep 2, 2021	SYSTEM	\$1,209.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user kloepj1 overridding Payment Estimate Exception 78 on the current Payment Estimate.
17	IN.,	2		28		SYSTEM SYSTEM		Estimate Item Adjustment (0024) due to user kloepj1 overridding Payment
17	IN.,	2			2021 Sep 2,		\$1,209.60	Estimate Item Adjustment (0024) due to user kloepj1 overridding Payment
17	IN.,	2		28	2021 Sep 2, 2021 Sep 16,	SYSTEM	\$1,209.60 (\$1,209.60)	Estimate Item Adjustment (0024) due to user kloep/1 overridding Payment Estimate Exception 78 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloep/1 overridding Payment
177	IN.,	2	- Total	28	2021 Sep 2, 2021 Sep 16, 2021	SYSTEM	\$1,209.60 (\$1,209.60) \$1,209.60	Estimate Item Adjustment (0024) due to user kloep/1 overridding Payment Estimate Exception 78 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloep/1 overridding Payment
177	IN.,	2		28	2021 Sep 2, 2021 Sep 16, 2021	SYSTEM	\$1,209.60 (\$1,209.60) \$1,209.60 (\$1,209.60)	Estimate Item Adjustment (0024) due to user kloep/1 overridding Payment Estimate Exception 78 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloep/1 overridding Payment
	IN.,	255		28	2021 Sep 2, 2021 Sep 16, 2021	SYSTEM	\$1,209.60 (\$1,209.60) \$1,209.60 (\$1,209.60)	Estimate Item Adjustment (0024) due to user kloep/1 overridding Payment Estimate Exception 78 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloep/1 overridding Payment
17	IN., CONDUCTOR	Material - To		28	2021 Sep 2, 2021 Sep 16, 2021	SYSTEM	\$1,209.60 (\$1,209.60) \$1,209.60 (\$1,209.60) \$0.00	Estimate Item Adjustment (0024) due to user kloepj1 overridding Payment Estimate Exception 78 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment
17	IN., CONDUCTOR	Material - To		28 29 29	2021 Sep 2, 2021 Sep 16, 2021 Sep 16, 2021	SYSTEM SYSTEM SYSTEM	\$1,209.60 (\$1,209.60) \$1,209.60 (\$1,209.60) \$0.00 \$0.00	Estimate Item Adjustment (0024) due to user kloepj1 overridding Payment Estimate Exception 78 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 93 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user kloepj1 overridding Payment Estimate Item Adjustment (0025) due to user kloepj1 overridding Payment
17	IN., CONDUCTOR	Material - To		28 29 29 28	2021 Sep 2, 2021 Sep 16, 2021 Sep 16, 2021 Sep 2, 2021 Sep 2, 2021	SYSTEM SYSTEM SYSTEM	\$1,209.60 (\$1,209.60) \$1,209.60 (\$1,209.60) \$0.00 \$0.00 \$899.00	Estimate Item Adjustment (0024) due to user kloepj1 overridding Payment Estimate Exception 78 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 93 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user kloepj1 overridding Payment Estimate Item Adjustment (0025) due to user kloepj1 overridding Payment
17	IN., CONDUCTOR	Material - To		28 29 29 28 28	Sep 2, 2021 Sep 16, 2021 Sep 16, 2021 Sep 2, 2021 Sep 2, 2021 Sep 2, 2021 Sep 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$1,209.60 (\$1,209.60) \$1,209.60 (\$1,209.60) \$0.00 \$0.00 \$899.00 (\$899.00)	Estimate Item Adjustment (0024) due to user kloepj1 overridding Payment Estimate Exception 78 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 93 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user kloepj1 overridding Payment Estimate Exception 79 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment
17	IN., CONDUCTOR	Material - To		28 29 29 28 28 28	Sep 2, 2021 Sep 16, 2021 Sep 16, 2021 Sep 16, 2021 Sep 2, 2021 Sep 2, 2021 Sep 16, 2021 Sep 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$1,209.60 (\$1,209.60) \$1,209.60 (\$1,209.60) \$0.00 \$0.00 \$899.00 (\$899.00)	Estimate Item Adjustment (0024) due to user kloepj1 overridding Payment Estimate Exception 78 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 93 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user kloepj1 overridding Payment Estimate Exception 79 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment
17	IN., CONDUCTOR	Material - To	tal - Total	28 29 29 28 28 28	Sep 2, 2021 Sep 16, 2021 Sep 16, 2021 Sep 16, 2021 Sep 2, 2021 Sep 2, 2021 Sep 16, 2021 Sep 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$1,209.60 (\$1,209.60) \$1,209.60 (\$1,209.60) \$0.00 \$0.00 \$899.00 (\$899.00) (\$899.00)	Estimate Item Adjustment (0024) due to user kloepj1 overridding Payment Estimate Exception 78 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 93 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user kloepj1 overridding Payment Estimate Exception 79 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	1770	POLE FOUNDATION (45 FT. OR 13.5 M	Material		28	Sep 2, 2021	SYSTEM	\$4,272.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user kloepj1 overridding Payment Estimate Exception 80 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$4,272.00)	
					29	Sep 16, 2021	SYSTEM	\$4,272.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment Estimate Exception 95 on the current Payment Estimate.
					29	Sep 16, 2021	SYSTEM	(\$4,272.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1770 -	· Total						\$0.00	
	1780	MISC. HIGHWAY LIGHTING	Material		3	Aug 17, 2020	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					3	Aug 17, 2020	SYSTEM	(\$16,605.00)	
					4	Sep 2, 2020	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					4	Sep 2, 2020	SYSTEM	(\$16,605.00)	
					5	Sep 16, 2020	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					5	Sep 16, 2020	SYSTEM	(\$16,605.00)	
					6	Oct 1, 2020	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
					6	Oct 1, 2020	SYSTEM	(\$16,605.00)	
					7	Oct 16, 2020	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
					7	Oct 16, 2020	SYSTEM	(\$16,605.00)	
					8	Nov 2, 2020	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user hillt5 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					8	Nov 2, 2020	SYSTEM	(\$16,605.00)	
					9	Nov 16, 2020	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user hillt5 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					9	Nov 16, 2020	SYSTEM	(\$16,605.00)	
					10	Dec 2, 2020	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					10	Dec 2, 2020	SYSTEM	(\$16,605.00)	
					11	Dec 16, 2020	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user schlag1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					11	Dec 16, 2020	SYSTEM	(\$16,605.00)	
					12	Jan 4, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					12	Jan 4, 2021	SYSTEM	(\$16,605.00)	
					13	Jan 19, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schlag1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					13	Jan 19,	SYSTEM	(\$16,605.00)	·



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	1780	MISC. HIGHWAY	Material			2021			
		LIGHTING			14	Feb 2, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hillt5 overridding Payment Estimate Exception 56 on the current Payment Estimate.
					14	Feb 2, 2021	SYSTEM	(\$16,605.00)	
					15	Feb 16, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schlag1 overridding Payment Estimate Exception 55 on the current Payment Estimate.
					15	Feb 16, 2021	SYSTEM	(\$16,605.00)	
					16	Mar 2, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 51 on the current Payment Estimate.
					16	Mar 2, 2021	SYSTEM	(\$16,605.00)	
					17	Mar 16, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user kloepj1 overridding Payment Estimate Exception 44 on the current Payment Estimate.
					17	Mar 16, 2021	SYSTEM	(\$16,605.00)	
					18	Apr 2, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment Estimate Exception 58 on the current Payment Estimate.
					18	Apr 2, 2021	SYSTEM	(\$16,605.00)	
					19	Apr 16, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 66 on the current Payment Estimate.
					19	Apr 16, 2021	SYSTEM	(\$16,605.00)	
					20	May 3, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user hillto overridding Payment Estimate Exception 91 on the current Payment Estimate.
					20	May 3, 2021	SYSTEM	(\$16,605.00)	
					21	May 17, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user hillto overridding Payment Estimate Exception 111 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$16,605.00)	
					22	Jun 2, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user hillt5 overridding Payment Estimate Exception 122 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$16,605.00)	
					23	Jun 16, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 121 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$16,605.00)	
					24	Jul 1, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user herrmt1 overridding Payment Estimate Exception 80 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$16,605.00)	
					25	Jul 16, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment Estimate Exception 76 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$16,605.00)	
					26	Aug 2, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hillt5 overridding Payment Estimate Exception 76 on the current Payment Estimate.
					26	Aug 2, 2021	SYSTEM	(\$16,605.00)	
					27	Aug 16, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user herrmt1 overridding Payment



ject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
222	1780	MISC. HIGHWAY	Material						Estimate Exception 72 on the current Payment Estimate.
		LIGHTING			27	Aug 16,	SYSTEM	(\$16,605.00)	
					28	2021 Sep 2, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user kloepj1 overridding Payment
					28	Sep 2, 2021	SYSTEM	(\$16,605.00)	Estimate Exception 82 on the current Payment Estimate.
					29	Sep 16, 2021	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment
					29	Sep 16, 2021	SYSTEM	(\$16,605.00)	Estimate Exception 97 on the current Payment Estimate.
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	1780 -	Total						\$0.00	
	1800	MISC. HIGHWAY LIGHTING	Material		28	Sep 2, 2021	SYSTEM	\$9,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user kloepj1 overridding Payment Estimate Exception 84 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$9,000.00)	
					29	Sep 16, 2021	SYSTEM	\$9,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user kloepj1 overridding Payment Estimate Exception 99 on the current Payment Estimate.
					29	Sep 16, 2021	SYSTEM	(\$9,000.00)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	1800 -	Total						\$0.00	
	1820	MISC. HIGHWAY LIGHTING	Material		28	Sep 2, 2021	SYSTEM	\$2,395.14	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user kloepj1 overridding Payment Estimate Exception 85 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$2,395.14)	
					29	Sep 16, 2021	SYSTEM	\$2,395.14	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user kloepj1 overridding Payment Estimate Exception 100 on the current Payment Estimate.
					29	Sep 16, 2021	SYSTEM	(\$2,395.14)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	1820 -	Total						\$0.00	
	1830	MISC. HIGHWAY LIGHTING	Material		28	Sep 2, 2021	SYSTEM	\$2,288.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user kloepj1 overridding Payment Estimate Exception 83 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$2,288.00)	
					29	Sep 16, 2021	SYSTEM	\$2,288.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user kloepj1 overridding Payment Estimate Exception 98 on the current Payment Estimate.
					29	Sep 16, 2021	SYSTEM	(\$2,288.00)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	1830 -	Total						\$0.00	
	1850	MISC. HIGHWAY LIGHTING	Material		29	Sep 16, 2021	SYSTEM	\$2,343.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 103 on the current Payment Estimate.
					29	Sep 16, 2021	SYSTEM	(\$2,343.00)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	1850 -	Total						\$0.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	1860	SIGNAL HEAD, TYPE 3S	Material		29	Sep 16, 2021	SYSTEM	\$761.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user kloepj1 overridding Payment Estimate Exception 104 on the current Payment Estimate.
					29	Sep 16, 2021	SYSTEM	(\$761.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1860 -	· Total						\$0.00	
	1870	SIGNAL HEAD, TYPE 3B	Material		21	May 17, 2021	SYSTEM	\$4,635.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user hillt5 overridding Payment Estimate Exception 112 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$4,635.00)	
					22	Jun 2, 2021	SYSTEM	\$4,635.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hillt5 overridding Payment Estimate Exception 123 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$4,635.00)	
					23	Jun 16, 2021	SYSTEM	\$4,635.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 122 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$4,635.00)	
					24	Jul 1, 2021	SYSTEM	\$4,635.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user herrmt1 overridding Payment Estimate Exception 81 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$4,635.00)	
					25	Jul 16, 2021	SYSTEM	\$4,635.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user kloepj1 overridding Payment Estimate Exception 77 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$4,635.00)	
					26	Aug 2, 2021	SYSTEM	\$4,635.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user hillt5 overridding Payment Estimate Exception 77 on the current Payment Estimate.
					26	Aug 2, 2021	SYSTEM	(\$4,635.00)	
					27	Aug 16, 2021	SYSTEM	\$4,635.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user herrmt1 overridding Payment Estimate Exception 73 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$4,635.00)	
					28	Sep 2, 2021	SYSTEM	\$4,635.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user kloepj1 overridding Payment Estimate Exception 88 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$4,635.00)	
					29	Sep 16, 2021	SYSTEM	\$12,051.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user kloepj1 overridding Payment Estimate Exception 105 on the current Payment Estimate.
					29	Sep 16, 2021	SYSTEM	(\$12,051.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1870 -	· Total						\$0.00	
	1910	POST, SIGNAL 8 FT. OR 2.4 M	Material		21	May 17, 2021	SYSTEM	\$1,935.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hillt5 overridding Payment Estimate Exception 113 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$1,935.00)	
					22	Jun 2, 2021	SYSTEM	\$1,935.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user hillt5 overridding Payment Estimate Exception 124 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$1,935.00)	



ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
22	1910	POST, SIGNAL 8 FT. OR 2.4 M	Material		23	Jun 16, 2021	SYSTEM	\$1,935.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 123 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$1,935.00)	
					24	Jul 1, 2021	SYSTEM	\$1,935.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user herrmt1 overridding Payment Estimate Exception 82 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$1,935.00)	
					25	Jul 16, 2021	SYSTEM	\$1,935.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user kloepj1 overridding Payment Estimate Exception 78 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$1,935.00)	
					26	Aug 2, 2021	SYSTEM	\$1,935.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user hillt5 overridding Payment Estimate Exception 78 on the current Payment Estimate.
					26	Aug 2, 2021	SYSTEM	(\$1,935.00)	
					27	Aug 16, 2021	SYSTEM	\$1,935.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user herrmt1 overridding Payment Estimate Exception 74 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$1,935.00)	
					28	Sep 2, 2021	SYSTEM	\$1,935.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user kloepj1 overridding Payment Estimate Exception 89 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$1,935.00)	
					29	Sep 16, 2021	SYSTEM	\$2,580.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user kloepj1 overridding Payment Estimate Exception 106 on the current Payment Estimate.
					29	Sep 16, 2021	SYSTEM	(\$2,580.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
ı		- Total	Metarial		00	0 40	OVOTEM	\$0.00	This adjustment offsets the critical system are sented Material Description
	1920	POST, SIGNAL 15 FT. OR 4.6 M	Material		29	Sep 16, 2021	SYSTEM	\$972.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user kloepj1 overridding Payment Estimate Exception 109 on the current Payment Estimate.
					29	Sep 16, 2021	SYSTEM	(\$972.00)	
			Material - To	- Total				\$0.00 \$0.00	
	1920 -	- Total	Waterial - 10	Lai				\$0.00	
	1950	POST, TYPE C, 50	Material		29	Sep 16,	SYSTEM		
		FT. ARM OR 15.2 M ARM	iviateriai			2021	STSTEIN	\$10,292.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user kloepj1 overridding Payment Estimate Exception 112 on the current Payment Estimate.
			iviaterial		29		SYSTEM	(\$10,292.00)	Estimate Item Adjustment (0031) due to user kloepj1 overridding Payment
			iviaterial	- Total		2021 Sep 16,			Estimate Item Adjustment (0031) due to user kloepj1 overridding Payment
			Material - To			2021 Sep 16,		(\$10,292.00)	Estimate Item Adjustment (0031) due to user kloepj1 overridding Payment
	1950 -					2021 Sep 16,		(\$10,292.00)	Estimate Item Adjustment (0031) due to user kloepj1 overridding Payment
	1950 - 1960	ARM				2021 Sep 16,		(\$10,292.00) \$0.00 \$0.00	Estimate Item Adjustment (0031) due to user kloepj1 overridding Payment
		- Total POST, TYPE C, 55	Material - To		29	2021 Sep 16, 2021 May 17,	SYSTEM	(\$10,292.00) \$0.00 \$0.00	Estimate Item Adjustment (0031) due to user kloepj1 overridding Payment Estimate Exception 112 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user hillt5 overridding Payment
		- Total POST, TYPE C, 55	Material - To		29	2021 Sep 16, 2021 May 17, 2021 May 17,	SYSTEM	(\$10,292.00) \$0.00 \$0.00 \$0.00 \$11,930.00	Estimate Item Adjustment (0031) due to user kloepj1 overridding Payment Estimate Exception 112 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user hillt5 overridding Payment
		- Total POST, TYPE C, 55	Material - To		29 21 21	2021 Sep 16, 2021 May 17, 2021 May 17, 2021 Jun 2,	SYSTEM SYSTEM	(\$10,292.00) \$0.00 \$0.00 \$11,930.00 (\$11,930.00)	Estimate Item Adjustment (0031) due to user kloepj1 overridding Payment Estimate Exception 112 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user hillt5 overridding Payment Estimate Exception 116 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user hillt5 overridding Payment Estimate Item Adjustment (0023) due to user hillt5 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6l2222	1960	POST, TYPE C, 55 FT. ARM	Material	,		2021			Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment Estimate Exception 126 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$11,930.00)	
					24	Jul 1, 2021	SYSTEM	\$11,930.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user herrmt1 overridding Payment Estimate Exception 85 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$11,930.00)	
					25	Jul 16, 2021	SYSTEM	\$11,930.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user kloepj1 overridding Payment Estimate Exception 81 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$11,930.00)	
					26	Aug 2, 2021	SYSTEM	\$11,930.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user hillt5 overridding Payment Estimate Exception 81 on the current Payment Estimate.
					26	Aug 2, 2021	SYSTEM	(\$11,930.00)	
					27	Aug 16, 2021	SYSTEM	\$11,930.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user herrmt1 overridding Payment Estimate Exception 77 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$11,930.00)	
					28	Sep 2, 2021	SYSTEM	\$11,930.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user kloepj1 overridding Payment Estimate Exception 92 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$11,930.00)	
					29	Sep 16, 2021	SYSTEM	\$23,860.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user kloepj1 overridding Payment Estimate Exception 113 on the current Payment Estimate.
					29	Sep 16, 2021	SYSTEM	(\$23,860.00)	
				- Total				\$0.00	
	1960 -	Total	Material - Tot	tal				\$0.00 \$0.00	
	1990	CONTROLLER ASSEMBLY HOUSING,	Material		21	May 17, 2021	SYSTEM	\$13,359.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user hillt5 overridding Payment Estimate Exception 117 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$13,359.00)	
					22	Jun 2, 2021	SYSTEM	\$13,359.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user hillt5 overridding Payment Estimate Exception 129 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$13,359.00)	
					23	Jun 16, 2021	SYSTEM	\$13,359.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment Estimate Exception 128 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$13,359.00)	
					24	Jul 1, 2021	SYSTEM	\$13,359.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user herrmt1 overridding Payment Estimate Exception 87 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$13,359.00)	
					25	Jul 16, 2021	SYSTEM	\$13,359.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user kloepj1 overridding Payment Estimate Exception 82 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$13,359.00)	
					26	Aug 2,	SYSTEM	\$13,359.00	This adjustment offsets the original system-generated Material Payment
						2021			Estimate Item Adjustment (0025) due to user hillt5 overridding Payment Estimate Exception 82 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	1990	CONTROLLER ASSEMBLY HOUSING,	Material		27	Aug 16, 2021	SYSTEM	\$13,359.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user herrmt1 overridding Payment Estimate Exception 78 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$13,359.00)	
					28	Sep 2, 2021	SYSTEM	\$13,359.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user kloepj1 overridding Payment Estimate Exception 93 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$13,359.00)	
					29	Sep 16, 2021	SYSTEM	\$14,962.08	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user kloepj1 overridding Payment Estimate Exception 114 on the current Payment Estimate.
					29	Sep 16, 2021	SYSTEM	(\$14,962.08)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1990 -	· Total						\$0.00	
	2000	VIDEO DETECTION SYSTEM	Material		29	Sep 16, 2021	SYSTEM	\$10,158.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user kloepj1 overridding Payment Estimate Exception 115 on the current Payment Estimate.
					29	Sep 16, 2021	SYSTEM	(\$10,158.40)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
		· Total						\$0.00	
	2020	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	Overrun	Overrun	21	May 17, 2021	SYSTEM	(\$621.00)	
				Overrun - To	otal			(\$621.00)	
	0000	Tetal	Overrun - To	tal				(\$621.00)	
	2020 -		Metavial		20	Con 16	CVCTEM	(\$621.00)	This adjustment offsets the evisional system generated Metavial Daymont
	2040	CABLE, 16 AWG 2 CONDUCTOR	Material		29	Sep 16, 2021	SYSTEM	\$935.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user kloepj1 overridding Payment Estimate Exception 116 on the current Payment Estimate.
					29	Sep 16, 2021	SYSTEM	(\$935.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	2040 -							\$0.00	
	2050	CABLE, 16 AWG 5 CONDUCTOR	Material		29	Sep 16, 2021	SYSTEM	\$2,123.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user kloepj1 overridding Payment Estimate Exception 117 on the current Payment Estimate.
					29	Sep 16, 2021	SYSTEM	(\$2,123.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	2050 -	- Total						\$0.00	
	2060	CABLE, 16 AWG 7 CONDUCTOR	Material		21	May 17, 2021	SYSTEM	\$1,881.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user hillt5 overridding Payment Estimate Exception 118 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$1,881.60)	
					22	Jun 2, 2021	SYSTEM	\$1,881.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user hillt5 overridding Payment Estimate Exception 130 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$1,881.60)	
					23	Jun 16, 2021	SYSTEM	\$1,881.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user kloep 1 overridding Payment
						202.			Estimate Exception 129 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$1,881.60)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks								
J6I2222	2060	CABLE, 16 AWG 7 CONDUCTOR	Material			2021			Estimate Item Adjustment (0021) due to user herrmt1 overridding Payment Estimate Exception 88 on the current Payment Estimate.								
					24	Jul 1, 2021	SYSTEM	(\$1,881.60)									
					25	Jul 16, 2021	SYSTEM	\$1,881.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user kloepj1 overridding Payment Estimate Exception 83 on the current Payment Estimate.								
					25	Jul 16, 2021	SYSTEM	(\$1,881.60)									
					26	Aug 2, 2021	SYSTEM	\$1,881.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user hillt5 overridding Payment Estimate Exception 83 on the current Payment Estimate.								
					26	Aug 2, 2021	SYSTEM	(\$1,881.60)									
					27	Aug 16, 2021	SYSTEM	\$1,881.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user herrmt1 overridding Payment Estimate Exception 79 on the current Payment Estimate.								
					27	Aug 16, 2021	SYSTEM	(\$1,881.60)									
					28	Sep 2, 2021	SYSTEM	\$1,881.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user kloepj1 overridding Payment Estimate Exception 94 on the current Payment Estimate.								
						28	Sep 2, 2021	SYSTEM	(\$1,881.60)								
					29	Sep 16, 2021	SYSTEM	\$5,824.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user kloepj1 overridding Payment Estimate Exception 118 on the current Payment Estimate.								
					29	Sep 16, 2021	SYSTEM	(\$5,824.00)									
				- Total				\$0.00									
			Material - To	tal				\$0.00									
	2060 -		0	0	04	M 47	OVOTEM	\$0.00									
	2080	PULL BOX, PREFORMED CLASS 2	Overrun	Overrun	21	May 17, 2021 Sep 2,	SYSTEM	(\$1,221.00)									
				Overrun - T	-	2021	STSTEM	(\$2,442.00)									
			Overrun - To		Otai			(\$2,442.00)									
	2080 -	Total	Overruit 10	tai				(\$2,442.00)									
	2100	BASE, CONCRETE	Material		18	Apr 2, 2021	SYSTEM	\$2,320.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 59 on the current Payment Estimate.								
					18	Apr 2, 2021	SYSTEM	(\$2,320.00)									
					19							19	19	Apr 16, 2021	SYSTEM	\$7,644.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 67 on the current Payment Estimate.
								19	Apr 16, 2021	SYSTEM	(\$7,644.40)						
					20	May 3, 2021	SYSTEM	\$7,644.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user hillt5 overridding Payment Estimate Exception 92 on the current Payment Estimate.								
									20	20	May 3, 2021	SYSTEM	(\$7,644.40)				
					21	May 17, 2021	SYSTEM	\$7,644.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user hillt5 overridding Payment Estimate Exception 119 on the current Payment Estimate.								
					21	May 17, 2021	SYSTEM	(\$7,644.40)									
					22	Jun 2, 2021	SYSTEM	\$7,644.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user hillt5 overridding Payment Estimate Exception 131 on the current Payment Estimate.								
					22	Jun 2, 2021	SYSTEM	(\$7,644.40)									
					23	Jun 16, 2021	SYSTEM	\$7,644.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user kloep/1 overridding Payment								



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks														
J6I2222	2100	BASE, CONCRETE	Material						Estimate Exception 130 on the current Payment Estimate.														
					23	Jun 16, 2021	SYSTEM	(\$7,644.40)															
					24	Jul 1, 2021	SYSTEM	\$7,644.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user herrmt1 overridding Payment Estimate Exception 89 on the current Payment Estimate.														
					24	Jul 1, 2021	SYSTEM	(\$7,644.40)															
					25	Jul 16, 2021	SYSTEM	\$7,644.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user kloepj1 overridding Payment Estimate Exception 84 on the current Payment Estimate.														
					25	Jul 16, 2021	SYSTEM	(\$7,644.40)															
					26	Aug 2, 2021	SYSTEM	\$7,644.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user hillt5 overridding Payment Estimate Exception 84 on the current Payment Estimate.														
					26	Aug 2, 2021	SYSTEM	(\$7,644.40)															
					28	Sep 2, 2021	SYSTEM	\$11,948.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user kloepj1 overridding Payment Estimate Exception 95 on the current Payment Estimate.														
					28	Sep 2, 2021	SYSTEM	(\$11,948.00)															
					29	Sep 16, 2021	SYSTEM	\$11,948.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user kloepj1 overridding Payment Estimate Exception 119 on the current Payment Estimate.														
					29	Sep 16, 2021	SYSTEM	(\$11,948.00)															
				- Total				\$0.00															
			Material - To	tal				\$0.00															
	2100 -	Total						\$0.00															
	2160	MISC.	Material		29	Sep 16, 2021	SYSTEM	\$4,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user kloepj1 overridding Payment Estimate Exception 120 on the current Payment Estimate.														
					29	Sep 16, 2021	SYSTEM	(\$4,500.00)															
				- Total				\$0.00															
			Material - Tot	tal				\$0.00															
	2160 -							\$0.00															
	2210	CONCRETE FOOTINGS, BOLT DOWN	Material		3	Aug 17, 2020	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.														
					3	Aug 17, 2020	SYSTEM	(\$15,000.00)															
							4												4	Sep 2, 2020	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
								4	Sep 2, 2020	SYSTEM	(\$15,000.00)												
					5	Sep 16, 2020	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user kloepj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.														
															5	Sep 16, 2020	SYSTEM	(\$15,000.00)					
					6	Oct 1, 2020	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment Estimate Exception 35 on the current Payment Estimate.														
					6	Oct 1, 2020	SYSTEM	(\$15,000.00)															
					7	Oct 16, 2020	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment Estimate Exception 38 on the current Payment Estimate.														
					7	Oct 16, 2020	SYSTEM	(\$15,000.00)															
					8	Nov 2, 2020	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user hillt5 overridding Payment														



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	2210	CONCRETE FOOTINGS, BOLT	Material						Estimate Exception 32 on the current Payment Estimate.
		DOWN			8	Nov 2, 2020	SYSTEM	(\$15,000.00)	
					9	Nov 16, 2020	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user hillto overridding Payment Estimate Exception 33 on the current Payment Estimate.
					9	Nov 16, 2020	SYSTEM	(\$15,000.00)	
					10	Dec 2, 2020	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					10	Dec 2, 2020	SYSTEM	(\$15,000.00)	
					11	Dec 16, 2020	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user schlag1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					11	Dec 16, 2020	SYSTEM	(\$15,000.00)	
					12	Jan 4, 2021	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
					12	Jan 4, 2021	SYSTEM	(\$15,000.00)	
					13	Jan 19, 2021	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schlag1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					13	Jan 19, 2021	SYSTEM	(\$15,000.00)	
					14	Feb 2, 2021	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hillt5 overridding Payment Estimate Exception 57 on the current Payment Estimate.
					14	Feb 2, 2021	SYSTEM	(\$15,000.00)	
					15	Feb 16, 2021	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schlag1 overridding Payment Estimate Exception 56 on the current Payment Estimate.
					15	Feb 16, 2021	SYSTEM	(\$15,000.00)	
					16	Mar 2, 2021	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 52 on the current Payment Estimate.
					16	Mar 2, 2021	SYSTEM	(\$15,000.00)	
					17	Mar 16, 2021	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment Estimate Exception 45 on the current Payment Estimate.
					17	Mar 16, 2021	SYSTEM	(\$15,000.00)	
					18	Apr 2, 2021	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 60 on the current Payment Estimate.
					18	Apr 2, 2021	SYSTEM	(\$15,000.00)	
					19	Apr 16, 2021	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 68 on the current Payment Estimate.
					19	Apr 16, 2021	SYSTEM	(\$15,000.00)	
					20	May 3, 2021	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user hillt5 overridding Payment Estimate Exception 93 on the current Payment Estimate.
					20	May 3, 2021	SYSTEM	(\$15,000.00)	
					21	May 17, 2021	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user hillts overridding Payment Estimate Exception 120 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$15,000.00)	



t Li									
	ine.	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
2 22	210	CONCRETE FOOTINGS, BOLT DOWN	Material		22	Jun 2, 2021	SYSTEM	\$50,784.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user hillts overridding Payment Estimate Exception 132 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$50,784.00)	
					23	Jun 16, 2021	SYSTEM	\$50,784.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user kloepj1 overridding Payment Estimate Exception 131 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$50,784.00)	
					24	Jul 1, 2021	SYSTEM	\$67,584.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user herrmt1 overridding Payment Estimate Exception 90 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$67,584.00)	
					25	Jul 16, 2021	SYSTEM	\$67,584.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user kloepj1 overridding Payment Estimate Exception 85 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$67,584.00)	
					26	Aug 2, 2021	SYSTEM	\$67,584.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user hillts overridding Payment Estimate Exception 85 on the current Payment Estimate.
					26	Aug 2, 2021	SYSTEM	(\$67,584.00)	
					27	Aug 16, 2021	SYSTEM	\$67,584.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user herrmt1 overridding Paymen Estimate Exception 80 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$67,584.00)	
					28	Sep 2, 2021	SYSTEM	\$67,584.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user kloepj1 overridding Payment Estimate Exception 96 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$67,584.00)	
					29	Sep 16, 2021	SYSTEM	\$67,584.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user kloepj1 overridding Payment Estimate Exception 121 on the current Payment Estimate.
					29	Sep 16, 2021	SYSTEM	(\$67,584.00)	
				- Total				\$0.00	
								Ψ0.00	
			Material - To					\$0.00	
22	210 -	Total	Material - To						
	210 - 220	Total STRUCTURAL STEEL POSTS	Construction Stockpile		5	Sep 16, 2020	SYSTEM	\$0.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		STRUCTURAL	Construction		5		SYSTEM	\$0.00 \$0.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		STRUCTURAL	Construction Stockpile STMI	tal		2020	SYSTEM	\$0.00 \$0.00 \$7,567.11	Payment Estimate Item Adjustment generated Stockpile Transaction
22	220	STRUCTURAL	Construction Stockpile STMI	al - Total		2020	SYSTEM	\$0.00 \$0.00 \$7,567.11 \$7,567.11	Payment Estimate Item Adjustment generated Stockpile Transaction
22	220	STRUCTURAL STEEL POSTS	Construction Stockpile STMI Construction Construction Stockpile	al - Total		2020	SYSTEM	\$0.00 \$0.00 \$7,567.11 \$7,567.11	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
22	220 220 -	STRUCTURAL STEEL POSTS	Construction Stockpile STMI Construction	al - Total	ГМI - Total	2020 Sep 16,		\$0.00 \$0.00 \$7,567.11 \$7,567.11 \$7,567.11	
22	220 220 -	STRUCTURAL STEEL POSTS	Construction Stockpile STMI Construction Construction Stockpile STMI	- Total Stockpile S	「MI - Total	2020 Sep 16, 2020		\$0.00 \$0.00 \$7,567.11 \$7,567.11 \$7,567.11 \$10,734.00	
22	220 - 230	STRUCTURAL STEEL POSTS	Construction Stockpile STMI Construction Construction Stockpile STMI	- Total Stockpile S	「MI - Total	2020 Sep 16, 2020		\$0.00 \$0.00 \$7,567.11 \$7,567.11 \$7,567.11 \$10,734.00	
22 22 22	220 - 230	STRUCTURAL STEEL POSTS Total PIPE POSTS	Construction Stockpile STMI Construction Construction Stockpile STMI Construction Construction	- Total Stockpile S	「MI - Total	2020 Sep 16, 2020		\$0.00 \$0.00 \$7,567.11 \$7,567.11 \$7,567.11 \$10,734.00 \$10,734.00	
22 22 22	220 - 230 - 230 -	STRUCTURAL STEEL POSTS Total PIPE POSTS Total 2 IN. PSST POST -	Construction Stockpile STMI Construction Construction Stockpile STMI Construction Construction Stockpile STMI	- Total - Total - Total Stockpile S	5 FMI - Total	2020 Sep 16, 2020 Jun 16, 2021	SYSTEM	\$0.00 \$0.00 \$7,567.11 \$7,567.11 \$7,567.11 \$10,734.00 \$10,734.00 \$10,734.00 \$259.20	Payment Estimate Item Adjustment generated Stockpile Transaction
22 22 22 22	2220	STRUCTURAL STEEL POSTS Total PIPE POSTS Total 2 IN. PSST POST - 12 GA.	Construction Stockpile STMI Construction Construction Stockpile STMI Construction Construction Stockpile STMI	- Total - Total - Total - Stockpile S	5 FMI - Total	2020 Sep 16, 2020 Jun 16, 2021	SYSTEM	\$0.00 \$0.00 \$7,567.11 \$7,567.11 \$7,567.11 \$10,734.00 \$10,734.00 \$10,734.00 \$259.20 \$259.20	Payment Estimate Item Adjustment generated Stockpile Transaction
222 222 222 222	220 - 220 - 230 - 240 -	STRUCTURAL STEEL POSTS Total PIPE POSTS Total 2 IN. PSST POST- 12 GA.	Construction Stockpile STMI Construction Construction Stockpile STMI Construction Construction Stockpile STMI Construction	- Total - Total - Total Stockpile S	5 IMI - Total 23	2020 Sep 16, 2020 Jun 16, 2021	SYSTEM	\$0.00 \$0.00 \$7,567.11 \$7,567.11 \$7,567.11 \$10,734.00 \$10,734.00 \$10,734.00 \$259.20 \$259.20	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
222 222 222 222	2220	STRUCTURAL STEEL POSTS Total PIPE POSTS Total 2 IN. PSST POST - 12 GA.	Construction Stockpile STMI Construction Construction Stockpile STMI Construction Construction Stockpile STMI Construction	- Total - Total - Total Stockpile S - Total - Total Stockpile S	5 FMI - Total	2020 Sep 16, 2020 Jun 16, 2021	SYSTEM	\$0.00 \$0.00 \$7,567.11 \$7,567.11 \$7,567.11 \$10,734.00 \$10,734.00 \$10,734.00 \$259.20 \$259.20 \$259.20 \$100.17	Payment Estimate Item Adjustment generated Stockpile Transaction
222 222 222 222	220 - 220 - 230 - 240 -	STRUCTURAL STEEL POSTS Total PIPE POSTS Total 2 IN. PSST POST - 12 GA. Total POST ANCHOR FOR 2 IN. PSST - 12	Construction Stockpile STMI Construction Construction Construction Construction Construction Stockpile STMI Construction Construction Stockpile STMI Construction Stockpile STMI	- Total - Total Stockpile ST - Total - Total Stockpile ST - Total	5 SIMI - Total 23 SIMI - Total 23 SIMI - Total 23	2020 Sep 16, 2020 Jun 16, 2021	SYSTEM	\$0.00 \$0.00 \$7,567.11 \$7,567.11 \$7,567.11 \$10,734.00 \$10,734.00 \$10,734.00 \$259.20 \$259.20 \$259.20 \$10.17 \$100.17	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
222 222 222 222	220 - 220 - 230 - 240 -	STRUCTURAL STEEL POSTS Total PIPE POSTS Total 2 IN. PSST POST - 12 GA. Total POST ANCHOR FOR 2 IN. PSST - 12	Construction Stockpile STMI Construction Construction Construction Construction Construction Stockpile STMI Construction Construction Stockpile STMI Construction Stockpile STMI	- Total - Total - Total Stockpile S - Total - Total Stockpile S	5 SIMI - Total 23 SIMI - Total 23 SIMI - Total 23	2020 Sep 16, 2020 Jun 16, 2021	SYSTEM	\$0.00 \$0.00 \$7,567.11 \$7,567.11 \$7,567.11 \$10,734.00 \$10,734.00 \$10,734.00 \$259.20 \$259.20 \$259.20 \$100.17	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
222	2260	SH-FLAT SHEET	Construction Stockpile STMI		23	Jun 16, 2021	SYSTEM	\$4,724.20	Payment Estimate Item Adjustment generated Stockpile Transaction
			OTIVII	- Total				\$4,724.20	
			Construction	Stockpile S	TMI - Total			\$4,724.20	
	2260 -	Total						\$4,724.20	
	2270	ST-STRUCTURAL	Construction Stockpile		25	Jul 16, 2021	SYSTEM	(\$2,190.22)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total	26	Aug 2, 2021	SYSTEM	(\$19,686.22)	Payment Estimate Item Adjustment generated Stockpile Transaction
			0		F-4-1				
			Construction	i Stockpile - I		lum 16	CVCTEM	(\$21,876.44)	December 5 of the state of the
			Construction Stockpile STMI	- Total	23	Jun 16, 2021	SYSTEM	\$30,495.60 \$30,495.60	Payment Estimate Item Adjustment generated Stockpile Transaction
			Construction		FMI Total				
	0070	Total	Construction	i Stockpile S	I WII - I Otal			\$30,495.60	
ď	2270 -						0) (O==1)	\$8,619.16	
	2280	SHF-FLAT SHEET FLUORESCENT	Construction Stockpile STMI	Total	23	Jun 16, 2021	SYSTEM	\$1,013.70	Payment Estimate Item Adjustment generated Stockpile Transaction
			0 1 11	- Total				\$1,013.70	
			Construction	Stockpile S	IMI - I otal			\$1,013.70	
J	2280 -							\$1,013.70	
	2290	STF-STRUCTURAL FLUORESCENT	Construction Stockpile		25	Jul 16, 2021	SYSTEM	(\$1,341.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total	26	Aug 2, 2021	SYSTEM	(\$2,279.70)	Payment Estimate Item Adjustment generated Stockpile Transaction
			Construction		Fotal			(\$3,620.70)	
				i Stockpile - 1		lum 16	SYSTEM		Downsont Cotimate Hom Adjustment generated Stacknilla Transportion
			Construction Stockpile STMI	- Total	23	Jun 16, 2021	SYSTEM	\$5,811.00 \$5,811.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			Construction		ΓMI - Total			\$5,811.00	
	2290 -	Total		. Отооприо				\$2,190.30	
ľ	2300	TUBULAR SUPPORT, TYPE	Construction Stockpile		8	Nov 2, 2020	SYSTEM	\$1,400.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		C-2315-20	STMI		27	Aug 16, 2021	SYSTEM	\$16,900.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$18,300.00	
			Construction	Stockpile S	ΓΜΙ - Total			\$18,300.00	
	2300 -	Total						\$18,300.00	
	2310	TUBULAR SUPPORT, TYPE C-2018-28	Construction Stockpile STMI		8	Nov 2, 2020	SYSTEM	\$1,400.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		0-2010-20	511411	- Total				\$1,400.00	
			Construction	Stockpile S	ΓΜΙ - Total			\$1,400.00	
	2310 -	Total						\$1,400.00	
	2320	MISC. HIGHWAY SIGNING	Construction Stockpile STMI		8	Nov 2, 2020	SYSTEM	\$2,300.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			OTIVII	- Total				\$2,300.00	
			Construction	Stockpile S	ΓΜΙ - Total			\$2,300.00	
	2320 -	Total						\$2,300.00	
	2330	MISC. HIGHWAY SIGNING	Construction Stockpile		25	Jul 16, 2021	SYSTEM	(\$50,900.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$50,900.00)	
			Construction	Stockpile - 1	Γotal			(\$50,900.00)	
			Construction Stockpile STMI		8	Nov 2, 2020	SYSTEM	\$2,600.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			O TIVII		23	Jun 16, 2021	SYSTEM	\$48,300.00	Payment Estimate Item Adjustment generated Stockpile Transaction



ject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
222	2330	MISC. HIGHWAY SIGNING	Construction Stockpile STMI	- Total				\$50,900.00	
			Construction	Stockpile S	TMI - Total			\$50,900.00	
			Material		25	Jul 16, 2021	SYSTEM	\$66,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user kloepj1 overridding Payment Estimate Exception 87 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$66,000.00)	
					26	Aug 2, 2021	SYSTEM	\$66,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user hillt5 overridding Payment Estimate Exception 87 on the current Payment Estimate.
					26	Aug 2, 2021	SYSTEM	(\$66,000.00)	
					27	Aug 16, 2021	SYSTEM	\$66,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user herrmt1 overridding Payment Estimate Exception 81 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$66,000.00)	
					28	Sep 2, 2021	SYSTEM	\$66,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user kloepj1 overridding Payment Estimate Exception 97 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$66,000.00)	
					29	Sep 16, 2021	SYSTEM	\$66,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user kloepj1 overridding Payment Estimate Exception 122 on the current Payment Estimate.
					29	Sep 16, 2021	SYSTEM	(\$66,000.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	2330 -	Total						\$0.00	
	2340	MISC. HIGHWAY SIGNING	Construction Stockpile STMI		8	Nov 2, 2020	SYSTEM	\$2,600.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				Total	29	Sep 16, 2021	SYSTEM	\$37,200.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			O a made madia a	- Total	TAN . T-4-1			\$39,800.00	
	00.10		Construction	Stockpile S	I IVII - I Otal			\$39,800.00	
	2340 - 2640	BRIDGE APPROACH SLAB (MAJOR ROAD)	Material		29	Sep 16, 2021	SYSTEM	\$39,800.00 \$20,945.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0053) due to user kloepj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
		,			29	Sep 16, 2021	SYSTEM	(\$20,945.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	2640 -	Total						\$0.00	
	2650	CLASS B CONCRETE (SUBSTRUCTURE)	Material		16	Mar 2, 2021	SYSTEM	\$5,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					16	Mar 2, 2021	SYSTEM	(\$5,050.00)	
					17	Mar 16, 2021	SYSTEM	\$5,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					17	Mar 16, 2021	SYSTEM	(\$5,050.00)	
					18	Apr 2, 2021	SYSTEM	\$5,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					18	Apr 2, 2021	SYSTEM	(\$5,050.00)	
					19	Apr 16, 2021	SYSTEM	\$5,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	2650	CLASS B CONCRETE	Material		19	Apr 16, 2021	SYSTEM	(\$5,050.00)	
		(SUBSTRUCTURE)			20	May 3, 2021	SYSTEM	\$5,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user hillt5 overridding Payment Estimate Exception 35 on the current Payment Estimate.
					20	May 3, 2021	SYSTEM	(\$5,050.00)	
					21	May 17, 2021	SYSTEM	\$5,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user hillt5 overridding Payment Estimate Exception 55 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$5,050.00)	
					22	Jun 2, 2021	SYSTEM	\$5,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user hillt5 overridding Payment Estimate Exception 67 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$5,050.00)	
					23	Jun 16, 2021	SYSTEM	\$5,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user kloepj1 overridding Payment Estimate Exception 69 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$5,050.00)	
					26	Aug 2, 2021	SYSTEM	\$5,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user hillt5 overridding Payment Estimate Exception 34 on the current Payment Estimate.
					26	Aug 2, 2021	SYSTEM	(\$5,050.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	2650 -							\$0.00	
	2660	CLASS B-1 CONCRETE	Material		27	Aug 16, 2021	SYSTEM	\$8,855.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user herrmt1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$8,855.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	2660 -							\$0.00	
	2670	SLAB ON STEEL	Material		14	Feb 2, 2021	SYSTEM	\$17,390.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user hillt5 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					14	Feb 2, 2021	SYSTEM	(\$17,390.00)	
					15	Feb 16, 2021	SYSTEM	\$17,390.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schlag1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
					15	Feb 16, 2021	SYSTEM	(\$17,390.00)	
					16	Mar 2, 2021	SYSTEM	\$34,780.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
					16	Mar 2, 2021	SYSTEM	(\$34,780.00)	
					17	Mar 16, 2021	SYSTEM	\$34,780.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					17	Mar 16, 2021	SYSTEM	(\$34,780.00)	
					18	Apr 2, 2021	SYSTEM	\$99,640.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					18	Apr 2, 2021	SYSTEM	(\$99,640.00)	
					19	Apr 16, 2021	SYSTEM	\$99,640.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.



t	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
2	2670	SLAB ON STEEL	Material		19	Apr 16, 2021	SYSTEM	(\$99,640.00)	
					20	May 3, 2021	SYSTEM	\$99,640.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user hillt5 overridding Payment Estimate Exception 43 on the current Payment Estimate.
					20	May 3, 2021	SYSTEM	(\$99,640.00)	
					21	May 17, 2021	SYSTEM	\$100,580.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user hillt5 overridding Payment Estimate Exception 62 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$100,580.00)	
					22	Jun 2, 2021	SYSTEM	\$100,580.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user hillt5 overridding Payment Estimate Exception 74 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$100,580.00)	
					23	Jun 16, 2021	SYSTEM	\$100,580.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0048) due to user kloepj1 overridding Payment Estimate Exception 76 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$100,580.00)	
					24	Jul 1, 2021	SYSTEM	\$100,580.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user herrmt1 overridding Payment Estimate Exception 41 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$100,580.00)	
					25	Jul 16, 2021	SYSTEM	\$100,580.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0049) due to user kloepj1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$100,580.00)	
					26	Aug 2, 2021	SYSTEM	\$100,580.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user hillt5 overridding Payment Estimate Exception 38 on the current Payment Estimate.
					26	Aug 2, 2021	SYSTEM	(\$100,580.00)	
					27	Aug 16, 2021	SYSTEM	\$100,580.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user herrmt1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$100,580.00)	
					28	Sep 2, 2021	SYSTEM	\$100,580.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user kloepj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$100,580.00)	
					29	Sep 16, 2021	SYSTEM	\$100,580.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0054) due to user kloepj1 overridding Payment Estimate Exception 47 on the current Payment Estimate.
					29	Sep 16, 2021	SYSTEM	(\$100,580.00)	
			Material - To	- Total				\$0.00	
	2670 -	Total	wateriai - 10	lai				\$0.00 \$0.00	
	2690	CORRAL CURB	Material		19	Apr 16, 2021	SYSTEM	\$16,614.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user kloepj1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
					19	Apr 16, 2021	SYSTEM	(\$16,614.00)	
					20	May 3, 2021	SYSTEM	\$16,614.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user hillt5 overridding Payment Estimate Exception 48 on the current Payment Estimate.
					20	May 3,	SYSTEM	(\$16,614.00)	
						2021			



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	2690	CORRAL CURB	Material						Estimate Exception 68 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$16,614.00)	
					22	Jun 2, 2021	SYSTEM	\$16,614.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user hillt5 overridding Payment Estimate Exception 80 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$16,614.00)	
					23	Jun 16, 2021	SYSTEM	\$16,614.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0049) due to user kloepj1 overridding Payment Estimate Exception 81 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$16,614.00)	
					24	Jul 1, 2021	SYSTEM	\$16,614.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user herrmt1 overridding Payment Estimate Exception 44 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$16,614.00)	
					25	Jul 16, 2021	SYSTEM	\$16,614.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user kloepj1 overridding Payment Estimate Exception 41 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$16,614.00)	
					26	Aug 2, 2021	SYSTEM	\$16,614.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user hillt5 overridding Payment Estimate Exception 47 on the current Payment Estimate.
					26	Aug 2, 2021	SYSTEM	(\$16,614.00)	
					27	Aug 16, 2021	SYSTEM	\$16,614.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user herrmt1 overridding Payment Estimate Exception 41 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$16,614.00)	
					28	Sep 2, 2021	SYSTEM	\$16,614.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0059) due to user kloepj1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$16,614.00)	
					29	Sep 16, 2021	SYSTEM	\$16,614.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0055) due to user kloepj1 overridding Payment Estimate Exception 55 on the current Payment Estimate.
					29	Sep 16, 2021	SYSTEM	(\$16,614.00)	
				- Total				\$0.00	
	0000		Material - To	tal				\$0.00	
	2690 - 2700	SUPERSTRUCTURE REPAIR (UNFORMED)	Material		17	Mar 16, 2021	SYSTEM	\$0.00 \$13,114.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
		(OIAI OIAMED)			17	Mar 16, 2021	SYSTEM	(\$13,114.00)	Estimate Estimate.
					18	Apr 2, 2021	SYSTEM	\$33,022.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
					18	Apr 2, 2021	SYSTEM	(\$33,022.00)	
					19	Apr 16, 2021	SYSTEM	\$33,022.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user kloepj1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
					19	Apr 16, 2021	SYSTEM	(\$33,022.00)	
					20	May 3, 2021	SYSTEM	\$74,892.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user hillt5 overridding Payment Estimate Exception 50 on the current Payment Estimate.
					20	May 3, 2021	SYSTEM	(\$74,892.00)	



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
				Туре				****	
J6I2222	2700	SUPERSTRUCTURE REPAIR (UNFORMED)	Material		21	May 17, 2021	SYSTEM	\$133,826.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user hillt5 overridding Payment Estimate Exception 70 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$133,826.00)	
					22	Jun 2, 2021	SYSTEM	\$169,060.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user hillt5 overridding Payment Estimate Exception 82 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$169,060.00)	
					23	Jun 16, 2021	SYSTEM	\$195,604.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user kloepj1 overridding Payment Estimate Exception 83 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$195,604.00)	
					24	Jul 1, 2021	SYSTEM	\$200,502.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user herrmt1 overridding Payment Estimate Exception 46 on the current Payment Estimate.
					24	Jul 1,	SYSTEM	(\$200,502.00)	Estimate Exception 45 on the current ayrıcın Estimate.
					25	2021 Jul 16, 2021	SYSTEM	\$200,502.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0051) due to user kloepj1 overridding Payment Estimate Exception 43 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$200,502.00)	
					26	Aug 2, 2021	SYSTEM	\$200,502.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user hillt5 overridding Payment Estimate Exception 49 on the current Payment Estimate.
					26	Aug 2, 2021	SYSTEM	(\$200,502.00)	, · · · · · · · · · · · · · · · · · · ·
					27	Aug 16, 2021	SYSTEM	\$200,502.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user herrmt1 overridding Payment Estimate Exception 43 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$200,502.00)	
					28	Sep 2, 2021	SYSTEM	\$208,560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user kloepj1 overridding Payment Estimate Exception 41 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$208,560.00)	
					29	Sep 16, 2021	SYSTEM	\$129,560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0056) due to user kloepj1 overridding Payment Estimate Exception 57 on the current Payment Estimate.
					29	Sep 16, 2021	SYSTEM	(\$129,560.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	2700 -						01/0	\$0.00	
	2720	MISC.	Material		20	May 3, 2021	SYSTEM	\$17,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user hillt5 overridding Payment Estimate Exception 58 on the current Payment Estimate.
					20	May 3, 2021	SYSTEM	(\$17,150.00)	
					21	May 17, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user hillt5 overridding Payment Estimate Exception 78 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$23,800.00)	
					22	Jun 2, 2021	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user hillt5 overridding Payment Estimate Exception 90 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$23,800.00)	
					23	Jun 16, 2021	SYSTEM	\$25,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0051) due to user kloepj1 overridding Payment Estimate Exception 91 on the current Payment Estimate.
					23	Jun 16,	SYSTEM	(\$25,550.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks												
J6I2222	2720	MISC.	Material			2021															
					24	Jul 1, 2021	SYSTEM	\$25,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user herrmt1 overridding Payment Estimate Exception 54 on the current Payment Estimate.												
					24	Jul 1, 2021	SYSTEM	(\$25,550.00)													
					25	Jul 16, 2021	SYSTEM	\$25,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0052) due to user kloepj1 overridding Payment Estimate Exception 51 on the current Payment Estimate.												
					25	Jul 16, 2021	SYSTEM	(\$25,900.00)													
					26	Aug 2, 2021	SYSTEM	\$25,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user hillto overridding Payment Estimate Exception 57 on the current Payment Estimate.												
					26	Aug 2, 2021	SYSTEM	(\$25,900.00)													
					27	Aug 16, 2021	SYSTEM	\$25,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user herrmt1 overridding Payment Estimate Exception 51 on the current Payment Estimate.												
					27	Aug 16, 2021	SYSTEM	(\$25,900.00)													
					28	Sep 2, 2021	SYSTEM	\$25,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0061) due to user kloepj1 overridding Payment Estimate Exception 49 on the current Payment Estimate.												
					28	Sep 2, 2021	SYSTEM	(\$25,900.00)													
					29	Sep 16, 2021	SYSTEM	\$29,225.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0057) due to user kloepj1 overridding Payment Estimate Exception 63 on the current Payment Estimate.												
					29	Sep 16, 2021	SYSTEM	(\$29,225.00)													
				- Total				\$0.00													
			Material - To	tal				\$0.00													
	2720 -	Total						\$0.00													
	2730	REINFORCING STEEL (EPOXY COATED)	Material	Material	Material		18	Apr 2, 2021	SYSTEM	\$2,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment Estimate Exception 40 on the current Payment Estimate.										
					18	Apr 2, 2021	SYSTEM	(\$2,550.00)													
					19	Apr 16, 2021	SYSTEM	\$2,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user kloepj1 overridding Payment Estimate Exception 44 on the current Payment Estimate.												
						19	Apr 16, 2021	SYSTEM	(\$2,550.00)												
														20	May 3, 2021	SYSTEM	\$2,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user hillt5 overridding Payment Estimate Exception 62 on the current Payment Estimate.			
																	20	May 3, 2021	SYSTEM	(\$2,550.00)	
																		21	May 17, 2021	SYSTEM	\$2,550.00
															21	May 17, 2021	SYSTEM	(\$2,550.00)			
																	22	Jun 2, 2021	SYSTEM	\$2,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user hillt5 overridding Payment Estimate Exception 96 on the current Payment Estimate.
						22	Jun 2, 2021	SYSTEM	(\$2,550.00)												
					23	Jun 16, 2021	SYSTEM	\$2,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0052) due to user kloepj1 overridding Payment Estimate Exception 96 on the current Payment Estimate.												
					23	Jun 16, 2021	SYSTEM	(\$2,550.00)													
					24	Jul 1, 2021	SYSTEM	\$2,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user herrmt1 overridding Payment Estimate Exception 58 on the current Payment Estimate.												



### PRENT CONCENTS FROM TEST, IPPORTS CONATTO PROVIDED ### PRENT CONCENTS FROM TEST, IPPORTS FROM TE	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
25	J6I2222	2730	STEEL (EPOXY	Material		24		SYSTEM	(\$2,550.00)					
262 262			COATED)			25		SYSTEM	\$2,550.00	Estimate Item Adjustment (0053) due to user kloepj1 overridding Payment				
201 2021 2						25		SYSTEM	(\$2,550.00)					
27						26		SYSTEM	\$2,550.00	Estimate Item Adjustment (0047) due to user hillt5 overridding Payment				
201						26		SYSTEM	(\$2,550.00)					
27						27		SYSTEM	\$2,550.00	Estimate Item Adjustment (0042) due to user herrmt1 overridding Payment				
28						27		SYSTEM	(\$2,550.00)	Zennac Zisepien ee en een en en en en en en en en en				
2021 29						28	Sep 2,	SYSTEM	\$2,550.00	Estimate Item Adjustment (0062) due to user kloepj1 overridding Payment				
2021 29 Sep 16, SYSTEM (\$2,550.00) 2730 - Total 29 Sep 16, SYSTEM (\$2,550.00) 2730 - Total 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00 30.00						28		SYSTEM	(\$2,550.00)					
Total South Sout						29		SYSTEM	\$2,550.00	Estimate Item Adjustment (0058) due to user kloepj1 overridding Payment				
Strain S						29		SYSTEM	(\$2,550.00)					
2730 - Total 2790 STRIP SEAL Construction Stockpile - Total (39,471.00) Payment Estimate Item Adjustment generated Stockpile Transaction - Total (39,471.00)					- Total				\$0.00					
2790				Material - Tot	tal				\$0.00					
Sickpile 7-Total (93,471.00) Construction Stockpile 7-Total (93,471.00) Construction Stockpile 7-Total (93,471.00) Construction Stockpile 5-Total (93,471.00) Construction Stockpile 5-Total (93,471.00) Construction Stockpile 5-Total (93,471.00) Construction Stockpile 5-Total (93,471.00) Z780 - Total (93,471.00) Z810 SUPERSTRUCTURE (REPAIR (UNFORMED)) Apr 16, 2021 SYSTEM (933,654.00) 18 Apr 2, 2021 SYSTEM (93,654.00) 19 Apr 16, 2021 SYSTEM (93,654.00) 2021 SYSTEM (93,654.00) 2021 SYSTEM (93,654.00) 19 Apr 16, 2021 SYSTEM (93,654.00) 2021 SYSTEM (93,654.00) 2021 SYSTEM (93,654.00) 19 Apr 16, 2021 SYSTEM (93,654.00) 20 May 3, 2021 SYSTEM (93,64.00) 20 May 3, 2021 SYSTEM (93,64.00) 20 May 4, 2021 SYSTEM (93,64.00) 20 May 5, 2021 SYSTEM (93,64.00) 20 May 6, 2021 SYSTEM (93,64.00) 20 May 7, 2021 SYSTEM (93,64.00) 20 May 8, 2021 SYSTEM (93,64.00) 20 May 9, 2021 SYSTEM (93,64.00) 20 May 9, 2021 SYSTEM (93,64.00) 20 May 9, 2021 SYSTEM (93,64.00) 20 May 1, 2021 SYSTEM (93,64.00) 20 May 1, 2021 SYSTEM (93,64.00) 20 May 3, 2021 SYSTEM (93,64.00) 20 May 1, 2021 SYSTEM (93,64.00) 20 May 3, 2021 SYSTEM (94,64.00) 2		2730 -	Total						\$0.00					
Construction Stockpile - Total (\$9,471.00)		2790	EXPANSION JOINT			26		SYSTEM	(\$9,471.00)	Payment Estimate Item Adjustment generated Stockpile Transaction				
Construction Stockpile STMI -Total SyA71.00 SyA71.00 SyA71.00 SyA71.00 Stockpile STMI -Total SyA71.00 SyA7			0.0.2											
Stockpile STM -Total SyA71.00 SyA71.00 SyA71.0					Stockpile - 1									
2780 - Total \$9,471.00				Stockpile		14		SYSTEM	\$9,471.00	Payment Estimate Item Adjustment generated Stockpile Transaction				
Superstructure Supe														
SUPERSTRUCTURE REPAIR (UNFORMED) Material				Construction	Stockpile S	MI - Total								
Estimate Item Adjustment (0022) due to user kloep)1 overridding Payment Estimate Exception 39 on the current Payment Estimate. 18								0) (0 = =) (
2021 19 Apr 16, 2021 19 Apr 16, 2021 19 Apr 16, 2021 20 May 3, 2021 20 May 3, 2021 21 May 17, 2021 21 May 17, 2021 22 Jun 2, 2021 23 Jun 2, 2021 24 Jun 2, 2021 25 Jun 2, 2021 26 SYSTEM \$73,628.00 573,628.00 573,628.00 17 This adjustment offsets the original system-generated Material Payment Estimate Exception 40 on the current Payment Estimate. 27 This adjustment offsets the original system-generated Material Payment Estimate Exception 54 on the current Payment Estimate. 28 SYSTEM \$165,742.00 29 Jun 2, 2021 20 Jun 2, 2021 20 Jun 2, 2021 20 Jun 2, 2021 20 Jun 2, 2021 21 Jun 2, 2021 22 Jun 2, 2021 23 SYSTEM \$234,314.00 24 Jun 2, 2021 25 SYSTEM \$234,314.00 26 SYSTEM \$234,314.00 27 SYSTEM \$234,314.00		2810	REPAIR	Material			2021			Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment				
Estimate Item Adjustment (0027) due to user kloepj1 overridding Payment Estimate Exception 40 on the current Payment Estimate. 19						18		SYSTEM	(\$33,654.00)					
20 May 3, 2021 20 May 3, 2021 20 May 3, 2021 20 May 3, 2021 21 May 17, 2021 22 Jun 2, 2021 23 SYSTEM \$234,314.00 26 SYSTEM \$234,314.00 27 SYSTEM \$234,314.00 28 SYSTEM \$234,314.00 29 Jun 2, 2021 20 SYSTEM \$234,314.00 20 SYSTEM \$234,314.00 20 SYSTEM \$234,314.00 20 May 3, 2021 21 May 17, 2021 22 Jun 2, 2021 23 SYSTEM \$234,314.00 24 SYSTEM \$234,314.00 25 SYSTEM \$234,314.00 26 SYSTEM \$234,314.00 27 SYSTEM \$234,314.00 28 SYSTEM \$234,314.00										19		SYSTEM	\$73,628.00	Estimate Item Adjustment (0027) due to user kloepj1 overridding Payment
Estimate Item Adjustment (0032) due to user hillt5 overridding Payment Estimate Exception 54 on the current Payment Estimate. 20 May 3, 2021 21 May 17, 2021 22 May 17, 2021 23 May 17, 2021 24 May 17, 2021 25 SYSTEM (\$165,742.00) 26 SYSTEM (\$165,742.00) 27 May 17, 2021 28 Jun 2, 2021 29 Jun 2, 2021 20 Jun 2, 2021 20 SYSTEM (\$234,314.00) 20 SYSTEM (\$234,314.00) 20 SYSTEM (\$234,314.00) 20 SYSTEM (\$234,314.00)										19	19		SYSTEM	(\$73,628.00)
2021 SYSTEM \$165,742.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0048) due to user hillt5 overridding Payment Estimate Exception 74 on the current Payment Estimate. 21 May 17, 2021 SYSTEM (\$165,742.00) 22 Jun 2, 2021 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user hillt5 overridding Payment Estimate Item Adjustment (0044) due to user hillt5 overridding Payment Estimate Exception 86 on the current Payment Estimate. 22 Jun 2, 2021 SYSTEM (\$234,314.00)						20		SYSTEM	\$131,140.00	Estimate Item Adjustment (0032) due to user hillt5 overridding Payment				
Estimate Item Adjustment (0048) due to user hillt5 overridding Payment Estimate Exception 74 on the current Payment Estimate. May 17, 2021 SYSTEM (\$165,742.00) Jun 2, 2021 SYSTEM \$234,314.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user hillt5 overridding Payment Estimate Exception 86 on the current Payment Estimate. Jun 2, 2021 SYSTEM (\$234,314.00)						20		SYSTEM	(\$131,140.00)					
2021 22 Jun 2, 2021 SYSTEM \$234,314.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user hillt5 overridding Payment Estimate Exception 86 on the current Payment Estimate. 22 Jun 2, 2021 SYSTEM (\$234,314.00)						21		SYSTEM	\$165,742.00	Estimate Item Adjustment (0048) due to user hillt5 overridding Payment				
2021 Estimate Item Adjustment (0044) due to user hillt5 overridding Payment Estimate Exception 86 on the current Payment Estimate. 22 Jun 2, 2021 (\$234,314.00)						21		SYSTEM	(\$165,742.00)					
2021						22		SYSTEM	\$234,314.00	Estimate Item Adjustment (0044) due to user hillt5 overridding Payment				
						22		SYSTEM	(\$234,314.00)					
						23		SYSTEM	\$234,314.00	This adjustment offsets the original system-generated Material Payment				



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
222	2810	SUPERSTRUCTURE REPAIR (UNFORMED)	Material			2021			Estimate Item Adjustment (0053) due to user kloepj1 overridding Payment Estimate Exception 87 on the current Payment Estimate.
		(23	Jun 16, 2021	SYSTEM	(\$234,314.00)	
					24	Jul 1, 2021	SYSTEM	\$234,314.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user herrmt1 overridding Payment Estimate Exception 50 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$234,314.00)	
					25	Jul 16, 2021	SYSTEM	\$234,314.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0054) due to user kloepj1 overridding Payment Estimate Exception 48 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$234,314.00)	
					26	Aug 2, 2021	SYSTEM	\$234,314.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0049) due to user hillt5 overridding Payment Estimate Exception 53 on the current Payment Estimate.
					26	Aug 2, 2021	SYSTEM	(\$234,314.00)	
					27	Aug 16, 2021	SYSTEM	\$234,314.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user herrmt1 overridding Payment Estimate Exception 47 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$234,314.00)	
					28	Sep 2, 2021	SYSTEM	\$374,302.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0063) due to user kloepj1 overridding Payment Estimate Exception 45 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$374,302.00)	
					29	Sep 16, 2021	SYSTEM	\$374,302.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0059) due to user kloep/1 overridding Payment Estimate Exception 60 on the current Payment Estimate.
					29	Sep 16, 2021	SYSTEM	(\$374,302.00)	
				- Total				\$0.00	
	2810 -	Total	Material - To	tal				\$0.00 \$0.00	
	2830	MISC.	Material		28	Sep 2, 2021	SYSTEM	\$57,925.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0064) due to user kloepj1 overridding Payment Estimate Exception 51 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$57,925.00)	
					29	Sep 16, 2021	SYSTEM	\$57,925.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user kloepj1 overridding Payment Estimate Exception 65 on the current Payment Estimate.
					29	Sep 16, 2021	SYSTEM	(\$57,925.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	2830 -							\$0.00	
	2930	AESTHETIC CONCRETE STAIN	Material		29	Sep 16, 2021	SYSTEM	\$14,877.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0061) due to user kloepj1 overridding Payment Estimate Exception 42 on the current Payment Estimate.
					29	Sep 16, 2021	SYSTEM	(\$14,877.00)	
				- Total				\$0.00	
	0000		Material - To	tal				\$0.00	
	2930 - 2940	MECHANICALLY STABILIZED EARTH	Material		8	Nov 2, 2020	SYSTEM	\$0.00 \$81,250.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user hillt5 overridding Payment
		WALL SYS			8	Nov 2,	SYSTEM	(\$81,250.00)	Estimate Exception 22 on the current Payment Estimate.
						2020			
					9	Nov 16, 2020	SYSTEM	\$352,312.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user hillt5 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks												
J6I2222	2940	MECHANICALLY STABILIZED EARTH	Material						Estimate Exception 22 on the current Payment Estimate.												
		WALL SYS			9	Nov 16, 2020	SYSTEM	(\$352,312.50)													
					10	Dec 2, 2020	SYSTEM	\$514,875.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.												
					10	Dec 2, 2020	SYSTEM	(\$514,875.00)													
					11	Dec 16, 2020	SYSTEM	\$514,875.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user schlag1 overridding Payment Estimate Exception 21 on the current Payment Estimate.												
					11	Dec 16, 2020	SYSTEM	(\$514,875.00)													
					12	Jan 4, 2021	SYSTEM	\$542,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 24 on the current Payment Estimate.												
					12	Jan 4, 2021	SYSTEM	(\$542,000.00)													
					13	Jan 19, 2021	SYSTEM	\$542,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schlag1 overridding Payment Estimate Exception 22 on the current Payment Estimate.												
					13	Jan 19, 2021	SYSTEM	(\$542,000.00)													
					14	Feb 2, 2021	SYSTEM	\$542,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user hillt5 overridding Payment Estimate Exception 50 on the current Payment Estimate.												
					14	Feb 2, 2021	SYSTEM	(\$542,000.00)													
					15	Feb 16, 2021	SYSTEM	\$542,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schlag1 overridding Payment Estimate Exception 50 on the current Payment Estimate.												
					15	Feb 16, 2021	SYSTEM	(\$542,000.00)													
					16	Mar 2, 2021	SYSTEM	\$542,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment Estimate Exception 49 on the current Payment Estimate.												
						16	Mar 2, 2021	SYSTEM	(\$542,000.00)												
						17	Mar 16, 2021	SYSTEM	\$542,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 42 on the current Payment Estimate.											
							17	Mar 16, 2021	SYSTEM	(\$542,000.00)											
												18	Apr 2, 2021	SYSTEM	\$542,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment Estimate Exception 44 on the current Payment Estimate.					
																	18	Apr 2, 2021	SYSTEM	(\$542,000.00)	
															19	Apr 16, 2021	SYSTEM	\$542,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user kloepj1 overridding Payment Estimate Exception 48 on the current Payment Estimate.		
					19	Apr 16, 2021	SYSTEM	(\$542,000.00)													
																	20	May 3, 2021	SYSTEM	\$542,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user hillto overridding Payment Estimate Exception 73 on the current Payment Estimate.
																	20	May 3, 2021	SYSTEM	(\$542,000.00)	
					21	May 17, 2021	SYSTEM	\$542,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0049) due to user hillto overridding Payment Estimate Exception 93 on the current Payment Estimate.												
					2	2	2					2	21	May 17, 2021	SYSTEM	(\$542,000.00)					
					22	Jun 2, 2021	SYSTEM	\$542,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user hillto overridding Payment Estimate Exception 103 on the current Payment Estimate.												
					22	Jun 2, 2021	SYSTEM	(\$542,000.00)													



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
J6l2222	2940	MECHANICALLY	Material	Туре	23	Jun 16, 2021	SYSTEM	\$542,000.00	This adjustment offsets the original system-generated Material Payment
		STABILIZED EARTH WALL SYS			22		CVCTEM	(\$5.42.000.00)	Estimate Item Adjustment (0054) due to user kloepj1 overridding Payment Estimate Exception 103 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$542,000.00)	
					24	Jul 1, 2021	SYSTEM	\$542,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user herrmt1 overridding Payment Estimate Exception 65 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$542,000.00)	
					25	Jul 16, 2021	SYSTEM	\$542,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0055) due to user kloepj1 overridding Payment Estimate Exception 57 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$542,000.00)	
					26	Aug 2, 2021	SYSTEM	\$542,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user hillt5 overridding Payment Estimate Exception 63 on the current Payment Estimate.
					26	Aug 2, 2021	SYSTEM	(\$542,000.00)	7,
					27	Aug 16, 2021	SYSTEM	\$542,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user herrmt1 overridding Payment Estimate Exception 59 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$542,000.00)	
					28	Sep 2, 2021	SYSTEM	\$542,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0065) due to user kloepj1 overridding Payment Estimate Exception 62 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$542,000.00)	
					29	Sep 16, 2021	SYSTEM	\$542,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0062) due to user kloepj1 overridding Payment Estimate Exception 77 on the current Payment Estimate.
					29	Sep 16, 2021	SYSTEM	(\$542,000.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	2940 - 2960	MISC. FENCING	Construction Stockpile		21	May 17, 2021	SYSTEM	\$0.00 (\$16,591.23)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$16,591.23)	
			Construction	Stockpile - 1	Γotal			(\$16,591.23)	
			Construction Stockpile		4	Sep 2, 2020	SYSTEM	\$16,591.23	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$16,591.23	
			Construction	Stockpile S	ГМI - Total			\$16,591.23	
	2960 -	Total						\$0.00	
	3000	CLASS B CONCRETE (SUBSTRUCTURE)	Material		25	Jul 16, 2021	SYSTEM	\$20,396.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0056) due to user kloepj1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$20,396.50)	
					26	Aug 2, 2021	SYSTEM	\$39,719.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0051) due to user hillt5 overridding Payment Estimate Exception 35 on the current Payment Estimate.
					26	Aug 2, 2021	SYSTEM	(\$39,719.50)	
					27	Aug 16, 2021	SYSTEM	\$39,719.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user herrmt1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$39,719.50)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	



ect Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
22 3000	- Total						\$0.00		
3170	MISC. FENCING	Construction Stockpile STMI		4	Sep 2, 2020	SYSTEM	\$23,938.77	Payment Estimate Item Adjustment generated Stockpile Transaction	
			- Total				\$23,938.77		
0.450		Construction	n Stockpile S	MI - Total					
3180	FT. 6 IN. DIA.)	Material		21	May 17, 2021	SYSTEM	\$12,495.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user hillt5 overridding Payment Estimate Exception 39 on the current Payment Estimate.	
				21	May 17, 2021	SYSTEM	(\$12,495.00)		
				22	Jun 2, 2021	SYSTEM	\$12,495.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user hillt5 overridding Payment Estimate Exception 42 on the current Payment Estimate.	
				22	Jun 2, 2021	SYSTEM	(\$12,495.00)	Estimate Exception 42 on the current rayment Estimate.	
				23	Jun 16, 2021	SYSTEM	\$12,495.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user kloepj1 overridding Payment Estimate Exception 45 on the current Payment Estimate.	
				23	Jun 16, 2021	SYSTEM	(\$12,495.00)		
				24	Jul 1, 2021	SYSTEM	\$12,495.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user herrmt1 overridding Payment Estimate Exception 25 on the current Payment Estimate.	
				24	Jul 1, 2021	SYSTEM	(\$12,495.00)		
				25	Jul 16, 2021	SYSTEM	\$12,495.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user kloepj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.	
				25	Jul 16, 2021	SYSTEM	(\$12,495.00)		
				26	Aug 2, 2021	SYSTEM	\$12,495.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user hillt5 overridding Payment Estimate Exception 26 on the current Payment Estimate.	
				26	Aug 2, 2021	SYSTEM	(\$12,495.00)		
				27	Aug 16, 2021	SYSTEM	\$12,495.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user herrmt1 overridding Payment Estimate Exception 18 on the current Payment Estimate.	
				27	Aug 16, 2021	SYSTEM	(\$12,495.00)		
				28	Sep 2, 2021	SYSTEM	\$12,495.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user kloepj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.	
				28	Sep 2, 2021	SYSTEM	(\$12,495.00)		
					29	Sep 16, 2021	SYSTEM	\$12,495.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user kloepj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
				29	Sep 16, 2021	SYSTEM	(\$12,495.00)		
			- Total				\$0.00		
		Material - To	tal				\$0.00		
3180	- Total						\$0.00		
3190	ROCK SOCKETS (3 FT 0 IN. DIA.)	Material		21	May 17, 2021	SYSTEM	\$24,450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user hillt5 overridding Payment Estimate Exception 46 on the current Payment Estimate.	
				21	May 17, 2021	SYSTEM	(\$24,450.00)		
				22	Jun 2, 2021	SYSTEM	\$24,450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user hillt5 overridding Payment Estimate Exception 54 on the current Payment Estimate.	
				22	Jun 2, 2021	SYSTEM	(\$24,450.00)		
				23	Jun 16, 2021	SYSTEM	\$24,450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user kloepi1 overridding Payment	
	3170 3170 3180 3180	3170 - Total 3170 - Total 3180 DRILLED SHAFTS (3 FT. 6 IN. DIA.) 3180 - Total 3190 ROCK SOCKETS (3	Type	Type	Type Adjustment Number Type Adjustment Adju	Type	Type	Type	



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
222	3190	ROCK SOCKETS (3 FT 0 IN. DIA.)	Material						Estimate Exception 57 on the current Payment Estimate.
		,			23	Jun 16, 2021	SYSTEM	(\$24,450.00)	
					24	Jul 1, 2021	SYSTEM	\$24,450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user herrmt1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$24,450.00)	
					25	Jul 16, 2021	SYSTEM	\$24,450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user kloepj1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$24,450.00)	
					26	Aug 2, 2021	SYSTEM	\$24,450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user hillt5 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					26	Aug 2, 2021	SYSTEM	(\$24,450.00)	
					27	Aug 16, 2021	SYSTEM	\$24,450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user herrmt1 overridding Paymen Estimate Exception 22 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$24,450.00)	
					28	Sep 2, 2021	SYSTEM	\$24,450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user kloepj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$24,450.00)	
					29	Sep 16, 2021	SYSTEM	\$24,450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user kloepj1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
					29	Sep 16, 2021	SYSTEM	(\$24,450.00)	
				- Total				\$0.00	
	0100		Material - To	tal				\$0.00	
	3190 - 3270	CLASS B	Material		20	May 3,	SYSTEM	\$0.00 \$19,840.00	This adjustment offsets the original system-generated Material Payment
	3270	CONCRETE (SUBSTRUCTURE)	Waterial		20	2021	OTOTEM	ψ13,040.00	Estimate Item Adjustment (0020) due to user hillt5 overridding Payment
									Estimate Exception 32 on the current Payment Estimate.
					20	May 3, 2021	SYSTEM	(\$19,840.00)	Estimate Exception 32 on the current Payment Estimate.
					20		SYSTEM	(\$19,840.00) \$19,840.00	Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user hillts overridding Payment Estimate Exception 52 on the current Payment Estimate.
						2021 May 17, 2021		, , ,	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user hillt5 overridding Payment
					21	2021 May 17, 2021 May 17,	SYSTEM	\$19,840.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user hillt5 overridding Payment
					21	2021 May 17, 2021 May 17, 2021 Jun 2,	SYSTEM	\$19,840.00 (\$19,840.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user hillt5 overridding Payment Estimate Exception 52 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user hillt5 overridding Payment
					21 21 22	2021 May 17, 2021 May 17, 2021 Jun 2, 2021 Jun 2,	SYSTEM SYSTEM	\$19,840.00 (\$19,840.00) \$19,840.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user hillt5 overridding Payment Estimate Exception 52 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user hillt5 overridding Payment Estimate Exception 64 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment
					21 21 22 22	2021 May 17, 2021 May 17, 2021 Jun 2, 2021 Jun 2, 2021 Jun 16,	SYSTEM SYSTEM SYSTEM	\$19,840.00 (\$19,840.00) \$19,840.00 (\$19,840.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user hillt5 overridding Payment Estimate Exception 52 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user hillt5 overridding Payment Estimate Exception 64 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user kloep/1 overridding Payment Estimate Item Adjustment (0027) due to user kloep/1 overridding Payment
				- Total	21 21 22 22 22 23	2021 May 17, 2021 May 17, 2021 Jun 2, 2021 Jun 2, 2021 Jun 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$19,840.00 (\$19,840.00) \$19,840.00 (\$19,840.00) \$19,840.00 (\$19,840.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user hillt5 overridding Payment Estimate Exception 52 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user hillt5 overridding Payment Estimate Exception 64 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user kloep/1 overridding Payment Estimate Item Adjustment (0027) due to user kloep/1 overridding Payment
			Material - To		21 21 22 22 22 23	2021 May 17, 2021 May 17, 2021 Jun 2, 2021 Jun 2, 2021 Jun 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$19,840.00 (\$19,840.00) \$19,840.00 (\$19,840.00) \$19,840.00 (\$19,840.00) \$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user hillt5 overridding Payment Estimate Exception 52 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user hillt5 overridding Payment Estimate Exception 64 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user kloep/1 overridding Payment Estimate Item Adjustment (0027) due to user kloep/1 overridding Payment
	3270 - 3280	Total CLASS B-1 CONCRETE	Material - To		21 21 22 22 22 23	2021 May 17, 2021 May 17, 2021 Jun 2, 2021 Jun 2, 2021 Jun 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$19,840.00 (\$19,840.00) \$19,840.00 (\$19,840.00) \$19,840.00 (\$19,840.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user hillt5 overridding Payment Estimate Exception 52 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user hillt5 overridding Payment Estimate Exception 64 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user kloep/1 overridding Payment Estimate Item Adjustment (0027) due to user kloep/1 overridding Payment
		CLASS B-1			21 21 22 22 23 23	2021 May 17, 2021 May 17, 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$19,840.00 (\$19,840.00) \$19,840.00 (\$19,840.00) \$19,840.00 (\$19,840.00) \$0.00 \$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user hillt5 overridding Payment Estimate Exception 52 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user hillt5 overridding Payment Estimate Exception 64 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user kloepj1 overridding Payment Estimate Exception 67 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 67 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	3280	CLASS B-1 CONCRETE	Material						Estimate Exception 35 on the current Payment Estimate.
		(SUBSTR)			25	Jul 16, 2021	SYSTEM	(\$63,616.50)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	3280 -	Total						\$0.00	
	3300	SLAB ON CONCRETE NU- GIRDER	Material		26	Aug 2, 2021	SYSTEM	\$68,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user hillt5 overridding Payment Estimate Exception 41 on the current Payment Estimate.
					26	Aug 2, 2021	SYSTEM	(\$68,150.00)	
					27	Aug 16, 2021	SYSTEM	\$153,337.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user herrmt1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$153,337.50)	
					28	Sep 2, 2021	SYSTEM	\$323,712.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user kloepj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$323,712.50)	
					29	Sep 16, 2021	SYSTEM	\$323,712.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user kloepj1 overridding Payment Estimate Exception 49 on the current Payment Estimate.
					29	Sep 16, 2021	SYSTEM	(\$323,712.50)	
				- Total				\$0.00	
			Material - To	al				\$0.00	
	3300 -	Total						\$0.00	
	3350	MISC. CONDUIT SYSTEM ON STRUCTURE	Material		28	Sep 2, 2021	SYSTEM	\$3,730.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user kloepj1 overridding Payment Estimate Exception 53 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$3,730.00)	
					29	Sep 16, 2021	SYSTEM	\$3,730.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user kloepj1 overridding Payment Estimate Exception 68 on the current Payment Estimate.
					29	Sep 16, 2021	SYSTEM	(\$3,730.00)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	3350 -	Total						\$0.00	
	3355	PROTECTIVE COATING - CONCRETE BENTS	Material		28	Sep 2, 2021	SYSTEM	\$8,330.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user kloepj1 overridding Payment Estimate Exception 60 on the current Payment Estimate.
		AND			28	Sep 2, 2021	SYSTEM	(\$8,330.05)	
					29	Sep 16, 2021	SYSTEM	\$8,330.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user kloepj1 overridding Payment Estimate Exception 75 on the current Payment Estimate.
					29	Sep 16, 2021	SYSTEM	(\$8,330.05)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	3355 -	Total						\$0.00	
	3370	FAB. SIGN SUPPORT	Stockpile		19	Apr 16, 2021	SYSTEM	\$14,500.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		BRACKETS	STMI	- Total				\$14,500.00	
			Construction	Stockpile S1	MI - Total			\$14,500.00	
	3370 -	Total						\$14,500.00	
	3400	PIPE PILE SPACERS	Material		18	Apr 2, 2021	SYSTEM	\$11,970.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 49 on the current Payment Estimate.



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
222	3400	PIPE PILE SPACERS	Material		18	Apr 2, 2021	SYSTEM	(\$11,970.00)	
					19	Apr 16, 2021	SYSTEM	\$11,970.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 57 on the current Payment Estimate.
					19	Apr 16, 2021	SYSTEM	(\$11,970.00)	
					20	May 3, 2021	SYSTEM	\$11,970.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hillt5 overridding Payment Estimate Exception 82 on the current Payment Estimate.
					20	May 3, 2021	SYSTEM	(\$11,970.00)	
					21	May 17, 2021	SYSTEM	\$11,970.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user hillt5 overridding Payment Estimate Exception 102 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$11,970.00)	
					22	Jun 2, 2021	SYSTEM	\$11,970.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user hillt5 overridding Payment Estimate Exception 112 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$11,970.00)	
					23	Jun 16, 2021	SYSTEM	\$11,970.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user kloepj1 overridding Payment Estimate Exception 111 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$11,970.00)	
					24	Jul 1, 2021	SYSTEM	\$11,970.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user herrmt1 overridding Payment Estimate Exception 73 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$11,970.00)	
					25	Jul 16, 2021	SYSTEM	\$11,970.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user kloepj1 overridding Payment Estimate Exception 65 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$11,970.00)	
					26	Aug 2, 2021	SYSTEM	\$11,970.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user hillt5 overridding Payment Estimate Exception 70 on the current Payment Estimate.
					26	Aug 2, 2021	SYSTEM	(\$11,970.00)	
					27	Aug 16, 2021	SYSTEM	\$11,970.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user herrmt1 overridding Payment Estimate Exception 66 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$11,970.00)	
					28	Sep 2, 2021	SYSTEM	\$11,970.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user kloepj1 overridding Payment Estimate Exception 69 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$11,970.00)	
					29	Sep 16, 2021	SYSTEM	\$11,970.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user kloepj1 overridding Payment Estimate Exception 84 on the current Payment Estimate.
					29	Sep 16, 2021	SYSTEM	(\$11,970.00)	
			Material - To	- Total				\$0.00	
	3400 -	Total	waterial - 10	tel				\$0.00	
	3420	AESTHETIC CONCRETE STAIN	Material		28	Sep 2, 2021	SYSTEM	\$0.00 \$7,856.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0066) due to user kloepj1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$7,856.10)	
					29	Sep 16, 2021	SYSTEM	\$7,856.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0063) due to user kloepj1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	3420	AESTHETIC CONCRETE STAIN	Material						Estimate Exception 43 on the current Payment Estimate.
		CONCINETECTAM			29	Sep 16, 2021	SYSTEM	(\$7,856.10)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	3420 -	Total						\$0.00	
	3430	MECHANICALLY STABILIZED EARTH WALL SYS	Material		19	Apr 16, 2021	SYSTEM	\$66,880.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user kloepj1 overridding Payment Estimate Exception 50 on the current Payment Estimate.
					19	Apr 16, 2021	SYSTEM	(\$66,880.00)	
					20	May 3, 2021	SYSTEM	\$66,880.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user hillt5 overridding Payment Estimate Exception 75 on the current Payment Estimate.
					20	May 3, 2021	SYSTEM	(\$66,880.00)	Estimate Exception 15 on the sunott Laymont Estimate.
					21	May 17, 2021	SYSTEM	\$66,880.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0051) due to user hillt5 overridding Payment Estimate Exception 95 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$66,880.00)	
					22	Jun 2, 2021	SYSTEM	\$66,880.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user hillt5 overridding Payment Estimate Exception 105 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$66,880.00)	
					23	Jun 16, 2021	SYSTEM	\$66,880.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0055) due to user kloepj1 overridding Payment Estimate Exception 105 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$66,880.00)	
					24	Jul 1, 2021	SYSTEM	\$66,880.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user herrmt1 overridding Payment Estimate Exception 67 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$66,880.00)	
					25	Jul 16, 2021	SYSTEM	\$66,880.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0057) due to user kloepj1 overridding Payment Estimate Exception 59 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$66,880.00)	
					26	Aug 2, 2021	SYSTEM	\$66,880.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0052) due to user hillt5 overridding Payment Estimate Exception 65 on the current Payment Estimate.
					26	Aug 2, 2021	SYSTEM	(\$66,880.00)	
					27	Aug 16, 2021	SYSTEM	\$334,560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user herrmt1 overridding Payment Estimate Exception 61 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$334,560.00)	
					28	Sep 2, 2021	SYSTEM	\$334,560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0067) due to user kloepj1 overridding Payment Estimate Exception 64 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$334,560.00)	
					29	Sep 16, 2021	SYSTEM	\$334,560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0064) due to user kloepj1 overridding Payment Estimate Exception 79 on the current Payment Estimate.
					29	Sep 16, 2021	SYSTEM	(\$334,560.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	3430 -	Total						\$0.00	
	3440	AESTHETIC CONCRETE STAIN	Material		28	Sep 2, 2021	SYSTEM	\$3,654.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0068) due to user kloepj1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks												
J6I2222	3440	AESTHETIC	Material						Estimate Exception 28 on the current Payment Estimate.												
		CONCRETE STAIN			28	Sep 2, 2021	SYSTEM	(\$3,654.00)													
					29	Sep 16, 2021	SYSTEM	\$3,654.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0065) due to user kloepj1 overridding Payment Estimate Exception 44 on the current Payment Estimate.												
					29	Sep 16, 2021	SYSTEM	(\$3,654.00)	,												
				- Total				\$0.00													
			Material - To	tal				\$0.00													
	3440 -	Total						\$0.00													
	3450	MECHANICALLY STABILIZED EARTH WALL SYS	Material		18	Apr 2, 2021	SYSTEM	\$50,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user kloepj1 overridding Payment Estimate Exception 46 on the current Payment Estimate.												
					18	Apr 2, 2021	SYSTEM	(\$50,400.00)													
					19	Apr 16, 2021	SYSTEM	\$181,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user kloepj1 overridding Payment Estimate Exception 53 on the current Payment Estimate.												
					19	Apr 16, 2021	SYSTEM	(\$181,520.00)													
					20	May 3, 2021	SYSTEM	\$181,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user hillt5 overridding Payment Estimate Exception 78 on the current Payment Estimate.												
					20	May 3, 2021	SYSTEM	(\$181,520.00)													
					21	May 17, 2021	SYSTEM	\$181,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0052) due to user hillt5 overridding Payment Estimate Exception 98 on the current Payment Estimate.												
							21	May 17, 2021	SYSTEM	(\$181,520.00)											
					22	Jun 2, 2021	SYSTEM	\$181,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user hillt5 overridding Payment Estimate Exception 109 on the current Payment Estimate.												
					22	Jun 2, 2021	SYSTEM	(\$181,520.00)													
					23	Jun 16, 2021	SYSTEM	\$181,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0056) due to user kloepj1 overridding Payment Estimate Exception 108 on the current Payment Estimate.												
					23	Jun 16, 2021	SYSTEM	(\$181,520.00)													
					24	Jul 1, 2021	SYSTEM	\$181,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user herrmt1 overridding Payment Estimate Exception 70 on the current Payment Estimate.												
					24	Jul 1, 2021	SYSTEM	(\$181,520.00)													
																	25	Jul 16, 2021	SYSTEM	\$181,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user kloepj1 overridding Payment Estimate Exception 62 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$181,520.00)													
																26	Aug 2, 2021	SYSTEM	\$181,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0053) due to user hillt5 overridding Payment Estimate Exception 67 on the current Payment Estimate.	
															26	Aug 2, 2021	SYSTEM	(\$181,520.00)			
					27	Aug 16, 2021	SYSTEM	\$201,680.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user herrmt1 overridding Payment Estimate Exception 63 on the current Payment Estimate.												
					27	Aug 16, 2021	SYSTEM	(\$201,680.00)													
					28	Sep 2, 2021	SYSTEM	\$201,680.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0069) due to user kloepj1 overridding Payment Estimate Exception 66 on the current Payment Estimate.												
					28	Sep 2, 2021	SYSTEM	(\$201,680.00)													



t	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
2	3450	MECHANICALLY STABILIZED EARTH WALL SYS	Material		29	Sep 16, 2021	SYSTEM	\$201,680.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0066) due to user kloepj1 overridding Payment Estimate Exception 81 on the current Payment Estimate.
					29	Sep 16, 2021	SYSTEM	(\$201,680.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	3450 -	Total						\$0.00	
	3480	DRILLED SHAFTS (6 FT. 0 IN. DIA.)	Material		22	Jun 2, 2021	SYSTEM	\$25,409.15	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0048) due to user hillt5 overridding Payment Estimate Exception 49 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$25,409.15)	
					23	Jun 16, 2021	SYSTEM	\$89,157.55	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0057) due to user kloepj1 overridding Payment Estimate Exception 52 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$89,157.55)	
					24	Jul 1, 2021	SYSTEM	\$89,157.55	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user herrmt1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$89,157.55)	
					25	Jul 16, 2021	SYSTEM	\$119,387.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0059) due to user kloepj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$119,387.60)	
					26	Aug 2, 2021	SYSTEM	\$119,387.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0054) due to user hillt5 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					26	Aug 2, 2021	SYSTEM	(\$119,387.60)	
					27	Aug 16, 2021	SYSTEM	\$119,387.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0048) due to user herrmt1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$119,387.60)	
					28	Sep 2, 2021	SYSTEM	\$119,387.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0070) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$119,387.60)	
					29	Sep 16, 2021	SYSTEM	\$119,387.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0067) due to user kloepj1 overridding Payment Estimate Exception 35 on the current Payment Estimate.
					29	Sep 16, 2021	SYSTEM	(\$119,387.60)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	3480 -	Total						\$0.00	
	3490	ROCK SOCKETS (5 FT 6 IN. DIA.)	Material		22	Jun 2, 2021	SYSTEM	\$95,378.15	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0049) due to user hillt5 overridding Payment Estimate Exception 59 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$95,378.15)	
					23	Jun 16, 2021	SYSTEM	\$214,006.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user kloepj1 overridding Payment Estimate Exception 62 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$214,006.80)	
					24	Jul 1, 2021	SYSTEM	\$214,006.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0048) due to user herrmt1 overridding Payment
									Estimate Exception 34 on the current Payment Estimate.



ne [Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks		
			Туре							
90 ROC	K SOCKETS (5 FT 6 IN. DIA.)	Material		25	Jul 16, 2021	SYSTEM	\$275,940.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user kloepj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.		
				25	Jul 16, 2021	SYSTEM	(\$275,940.00)			
				26	Aug 2, 2021	SYSTEM	\$275,940.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0055) due to user hillt5 overridding Payment Estimate Exception 32 on the current Payment Estimate.		
				26	Aug 2, 2021	SYSTEM	(\$275,940.00)			
				27	Aug 16, 2021	SYSTEM	\$275,940.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0049) due to user herrmt1 overridding Payment Estimate Exception 24 on the current Payment Estimate.		
				27	Aug 16, 2021	SYSTEM	(\$275,940.00)			
				28	Sep 2, 2021	SYSTEM	\$275,940.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0071) due to user kloepj1 overridding Payment Estimate Exception 24 on the current Payment Estimate.		
				28	Sep 2, 2021	SYSTEM	(\$275,940.00)			
				29	Sep 16, 2021	SYSTEM	\$275,940.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0068) due to user kloepj1 overridding Payment Estimate Exception 39 on the current Payment Estimate.		
				29	Sep 16, 2021	SYSTEM	(\$275,940.00)			
			- Total				\$0.00			
		Material - Tot	al				\$0.00			
90 - Total							\$0.00			
		Material		22	Jun 2, 2021	SYSTEM	\$26,851.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user hillt5 overridding Payment Estimate Exception 94 on the current Payment Estimate.		
						22	Jun 2, 2021	SYSTEM	(\$26,851.50)	
				23	Jun 16, 2021	SYSTEM	\$84,192.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0059) due to user kloepj1 overridding Payment Estimate Exception 95 on the current Payment Estimate.		
				23	Jun 16, 2021	SYSTEM	(\$84,192.50)			
				24	Jul 1, 2021	SYSTEM	\$84,192.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0049) due to user herrmt1 overridding Payment Estimate Exception 57 on the current Payment Estimate.		
				24	Jul 1,	SYSTEM		Estimate Exception of on the current aymont Estimate.		
					2021		(\$84,192.50)	Edinate Exception of the daront raymont Edinate.		
			- Total		2021		(\$84,192.50)	Edinate Exception of the darking dynamic Edinate.		
		Material - Tot			2021		(. , ,	Edinate Exception of the constitution Edinate.		
30 - Total		Material - Tot			2021		\$0.00	Edinate Exception of the earth of dynam Edinate.		
60	MISC. STRUCTURAL	Construction Stockpile		14	Feb 2, 2021	SYSTEM	\$0.00 \$0.00	Payment Estimate Item Adjustment generated Stockpile Transaction		
60		Construction		14	Feb 2,		\$0.00 \$0.00 \$0.00			
60	STRUCTURAL STEEL	Construction Stockpile	al - Total		Feb 2, 2021		\$0.00 \$0.00 \$0.00 \$26,016.00			
60	STRUCTURAL STEEL	Construction Stockpile STMI	al - Total		Feb 2, 2021		\$0.00 \$0.00 \$0.00 \$26,016.00 \$26,016.00			
60 CC	STRUCTURAL STEEL	Construction Stockpile STMI	al - Total Stockpile ST		Feb 2, 2021		\$0.00 \$0.00 \$0.00 \$26,016.00 \$26,016.00 \$26,016.00 \$5,544.00			
60 CC	STRUCTURAL STEEL DNSTRUCTION STRIP SEAL ANSION JOINT	Construction Stockpile STMI Construction Construction Stockpile STMI	- Total Stockpile ST	MI - Total	Feb 2, 2021	SYSTEM	\$0.00 \$0.00 \$0.00 \$26,016.00 \$26,016.00 \$26,016.00 \$5,544.00	Payment Estimate Item Adjustment generated Stockpile Transaction		
60 CC	STRUCTURAL STEEL DNSTRUCTION STRIP SEAL ANSION JOINT	Construction Stockpile STMI Construction Construction Stockpile	- Total Stockpile ST	MI - Total	Feb 2, 2021	SYSTEM	\$0.00 \$0.00 \$0.00 \$26,016.00 \$26,016.00 \$26,016.00 \$5,544.00 \$5,544.00	Payment Estimate Item Adjustment generated Stockpile Transaction		
60 CC 60 - Total 30 EXP	STRUCTURAL STEEL DNSTRUCTION STRIP SEAL ANSION JOINT	Construction Stockpile STMI Construction Construction Stockpile STMI	- Total Stockpile ST	MI - Total	Feb 2, 2021	SYSTEM	\$0.00 \$0.00 \$0.00 \$26,016.00 \$26,016.00 \$26,016.00 \$5,544.00	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0072) due to user kloepj1 overridding Payment		
60 CC 60 - Total 30 EXP	STRUCTURAL STEEL DNSTRUCTION STRIP SEAL ANSION JOINT SYSTEM SC. DRAINAGE	Construction Stockpile STMI Construction Construction Stockpile STMI Construction	- Total Stockpile ST	MI - Total	Feb 2, 2021 Feb 2, 2021 Sep 2,	SYSTEM	\$0.00 \$0.00 \$0.00 \$26,016.00 \$26,016.00 \$26,016.00 \$5,544.00 \$5,544.00 \$5,544.00	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction This adjustment offsets the original system-generated Material Payment		
	190 - Total	FT 6 IN. DIÂ.)	Material - Total REINFORCING Material	POCK SOCKETS (5 FT 6 IN. DIA.) Address: FT 6 IN. DIA. Address: FT 7 IN. DIA.	POCK SOCKETS (5 FT 6 IN. DIA.) Material	ROCK SOCKETS (5 FT 6 IN. DIA.) Material	ROCK SOCKETS (5 FT 6 IN. DIA.) Material 25	ROCK SOCKETS (5 FT 6 IN. DIA.) Material		



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks															
J6I2222	5003	MISC. DRAINAGE FITTINGS	Material	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	29	Sep 16, 2021	SYSTEM	(\$9,800.00)																
				- Total				\$0.00																
			Material - Tot	tal				\$0.00																
	5003 -	Total						\$0.00																
	5007	MISC. ITS	Construction Stockpile STMI		20	May 3, 2021	SYSTEM	\$75,000.00	Payment Estimate Item Adjustment generated Stockpile Transaction															
				- Total				\$75,000.00																
			Construction	Stockpile S	TMI - Tota			\$75,000.00																
	5007 -	Total						\$75,000.00																
	5008	MISC. DRAINAGE FITTINGS	Material		19	Apr 16, 2021	SYSTEM	\$400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user kloepj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.															
				19	Apr 16, 2021	SYSTEM	(\$400.00)																	
							20	May 3, 2021	SYSTEM	\$400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user hillt5 overridding Payment Estimate Exception 18 on the current Payment Estimate.													
						20	May 3, 2021	SYSTEM	(\$400.00)															
													21	May 17, 2021	SYSTEM	\$400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0053) due to user hillt5 overridding Payment Estimate Exception 32 on the current Payment Estimate.							
														21	May 17, 2021	SYSTEM	(\$400.00)							
					22	Jun 2, 2021	SYSTEM	\$400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0051) due to user hillt5 overridding Payment Estimate Exception 35 on the current Payment Estimate.															
					22	Jun 2, 2021	SYSTEM	(\$400.00)																
					23	Jun 16, 2021	SYSTEM	\$400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user kloepj1 overridding Payment Estimate Exception 38 on the current Payment Estimate.															
					23	Jun 16, 2021	SYSTEM	(\$400.00)																
					24	Jul 1, 2021	SYSTEM	\$400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user herrmt1 overridding Payment Estimate Exception 21 on the current Payment Estimate.															
						24	Jul 1, 2021	SYSTEM	(\$400.00)															
							25	Jul 16, 2021	SYSTEM	\$400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0061) due to user kloepj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.													
												25	Jul 16, 2021	SYSTEM	(\$400.00)									
											20 21 21									26	Aug 2, 2021	SYSTEM	\$400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0056) due to user hillt5 overridding Payment Estimate Exception 22 on the current Payment Estimate.
														26	Aug 2, 2021	SYSTEM	(\$400.00)							
																		27	Aug 16, 2021	SYSTEM	\$400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user herrmt1 overridding Payment Estimate Exception 14 on the current Payment Estimate.		
																			27	Aug 16, 2021	SYSTEM	(\$400.00)		
															28	Sep 2, 2021	SYSTEM	\$400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0073) due to user kloepj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.					
												28	Sep 2, 2021	SYSTEM	(\$400.00)									
							29	Sep 16, 2021	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0070) due to user kloepj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.													
															29	Sep 16, 2021	SYSTEM	(\$1,200.00)						
				- Total				\$0.00																



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks													
J6l2222	5008	MISC. DRAINAGE FITTINGS	Material - To	tal				\$0.00														
	5008 -	Total						\$0.00														
	5009	CLASS C EXCAVATION	Price FUEL		21	May 17, 2021	SYSTEM	\$154.54	Reference Item Price Adjustment Index Adjustment Type applied is FUEL													
				- Total				\$154.54														
			Price FUEL -	Total				\$154.54														
	5009 -	Total						\$154.54														
	5011	REINFORCING STEEL (EPOXY COATED)	Material		22	Jun 2, 2021	SYSTEM	\$25,203.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0052) due to user hillt5 overridding Payment Estimate Exception 98 on the current Payment Estimate.													
					22	Jun 2, 2021	SYSTEM	(\$25,203.50)														
					23	Jun 16, 2021	SYSTEM	\$25,203.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0061) due to user kloepj1 overridding Payment Estimate Exception 98 on the current Payment Estimate.													
					23	Jun 16, 2021	SYSTEM	(\$25,203.50)														
					24	Jul 1, 2021	SYSTEM	\$25,203.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0051) due to user herrmt1 overridding Payment Estimate Exception 60 on the current Payment Estimate.													
					24	Jul 1, 2021	SYSTEM	(\$25,203.50)														
								25	Jul 16, 2021	SYSTEM	\$25,203.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0062) due to user kloepj1 overridding Payment Estimate Exception 54 on the current Payment Estimate.										
							25	Jul 16, 2021	SYSTEM	(\$25,203.50)												
				- Total				\$0.00														
			Material - To	tal				\$0.00														
	5011 -	Total						\$0.00														
	5013	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	Material		14	Feb 2, 2021	SYSTEM	\$115,139.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user hillt5 overridding Payment Estimate Exception 19 on the current Payment Estimate.													
					14	Feb 2, 2021	SYSTEM	(\$115,139.70)														
					15	Feb 16, 2021	SYSTEM	\$115,139.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schlag1 overridding Payment Estimate Exception 27 on the current Payment Estimate.													
					1										15	Feb 16, 2021	SYSTEM	(\$115,139.70)				
					16	Mar 2, 2021	SYSTEM	\$115,139.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.													
					16	Mar 2, 2021	SYSTEM	(\$115,139.70)														
					17	Mar 16, 2021	SYSTEM	\$115,139.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 23 on the current Payment Estimate.													
					17	Mar 16, 2021	SYSTEM	(\$115,139.70)														
			18	18	1									1	18	18	18	18	Apr 2, 2021	SYSTEM	\$115,139.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user kloepj1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					18	Apr 2, 2021	SYSTEM	(\$115,139.70)														
				19	19	Apr 16, 2021	SYSTEM	\$115,139.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user kloepj1 overridding Payment Estimate Exception 23 on the current Payment Estimate.													
					19	Apr 16, 2021	SYSTEM	(\$115,139.70)														
								20	20	May 3, 2021	SYSTEM	\$115,139.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user hillt5 overridding Payment Estimate Exception 26 on the current Payment Estimate.									
					20	May 3, 2021	SYSTEM	(\$115,139.70)														



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J6I2222	5013	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	Material		21	May 17, 2021	SYSTEM	\$115,139.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0055) due to user hillt5 overridding Payment Estimate Exception 43 on the current Payment Estimate.	
					21	May 17, 2021	SYSTEM	(\$115,139.70)		
					22	Jun 2, 2021	SYSTEM	\$115,139.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0053) due to user hillto overridding Payment Estimate Exception 46 on the current Payment Estimate.	
					22	Jun 2, 2021	SYSTEM	(\$115,139.70)		
					23	Jun 16, 2021	SYSTEM	\$115,139.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0062) due to user kloepj1 overridding Payment Estimate Exception 49 on the current Payment Estimate.	
					23	Jun 16, 2021	SYSTEM	(\$115,139.70)		
					24	Jul 1, 2021	SYSTEM	\$115,139.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0052) due to user herrmt1 overridding Payment Estimate Exception 26 on the current Payment Estimate.	
					24	Jul 1, 2021	SYSTEM	(\$115,139.70)		
					25	Jul 16, 2021	SYSTEM	\$115,139.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0063) due to user kloepj1 overridding Payment Estimate Exception 27 on the current Payment Estimate.	
					25	Jul 16, 2021	SYSTEM	(\$115,139.70)		
					26	Aug 2, 2021	SYSTEM	\$115,139.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0057) due to user hillto overridding Payment Estimate Exception 27 on the current Payment Estimate.	
					26	Aug 2, 2021	SYSTEM	(\$115,139.70)		
					27	Aug 16, 2021	SYSTEM	\$115,139.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0051) due to user herrmt1 overridding Payment Estimate Exception 19 on the current Payment Estimate.	
					27	Aug 16, 2021	SYSTEM	(\$115,139.70)		
						28	Sep 2, 2021	SYSTEM	\$115,139.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0074) due to user kloepj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$115,139.70)		
					29	Sep 16, 2021	SYSTEM	\$115,139.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0071) due to user kloepj1 overridding Payment Estimate Exception 34 on the current Payment Estimate.	
					29	Sep 16, 2021	SYSTEM	(\$115,139.70)		
				- Total				\$0.00		
	5013 -	Total	Material - To	tal				\$0.00 \$0.00		
	5014	ROCK SOCKETS (3 FT 0 IN. DIA.)	Material		14	Feb 2, 2021	SYSTEM	\$70,341.57	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user hillt5 overridding Payment Estimate Exception 26 on the current Payment Estimate.	
					14	Feb 2, 2021	SYSTEM	(\$70,341.57)		
					15	Feb 16, 2021	SYSTEM	\$70,341.57	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schlag1 overridding Payment Estimate Exception 34 on the current Payment Estimate.	
					15	Feb 16, 2021	SYSTEM	(\$70,341.57)		
					16	Mar 2, 2021	SYSTEM	\$70,341.57	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.	
					16	Mar 2, 2021	SYSTEM	(\$70,341.57)		
					17	Mar 16, 2021	SYSTEM	\$70,341.57	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.	
					17	Mar 16,	SYSTEM	(\$70,341.57)		



ct L	ine	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
22 50	014	ROCK SOCKETS (3 FT 0 IN. DIA.)	Material			2021							
		TT OIN. DIA.)			18	Apr 2, 2021	SYSTEM	\$70,341.57	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user kloepj1 overridding Payment Estimate Exception 27 on the current Payment Estimate.				
					18	Apr 2, 2021	SYSTEM	(\$70,341.57)					
					19	Apr 16, 2021	SYSTEM	\$70,341.57	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user kloepj1 overridding Paymen Estimate Exception 26 on the current Payment Estimate.				
					19	Apr 16, 2021	SYSTEM	(\$70,341.57)					
					20	May 3, 2021	SYSTEM	\$70,341.57	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user hillto overridding Payment Estimate Exception 29 on the current Payment Estimate.				
					20	May 3, 2021	SYSTEM	(\$70,341.57)					
					21	May 17, 2021	SYSTEM	\$70,341.57	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0056) due to user hillto overridding Payment Estimate Exception 49 on the current Payment Estimate.				
					21	May 17, 2021	SYSTEM	(\$70,341.57)					
					22	Jun 2, 2021	SYSTEM	\$70,341.57	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0054) due to user hillt5 overridding Payment Estimate Exception 57 on the current Payment Estimate.				
					22	Jun 2, 2021	SYSTEM	(\$70,341.57)					
					23	Jun 16, 2021	SYSTEM	\$70,341.57	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0063) due to user kloepj1 overridding Paymer Estimate Exception 60 on the current Payment Estimate.				
								23	Jun 16, 2021	SYSTEM	(\$70,341.57)		
										24	Jul 1, 2021	SYSTEM	\$70,341.57
						24	Jul 1, 2021	SYSTEM	(\$70,341.57)				
					25	Jul 16, 2021	SYSTEM	\$70,341.57	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0064) due to user kloepj1 overridding Paymen Estimate Exception 31 on the current Payment Estimate.				
					25	Jul 16, 2021	SYSTEM	(\$70,341.57)					
					26	Aug 2, 2021	SYSTEM	\$70,341.57	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user hillt5 overridding Payment Estimate Exception 31 on the current Payment Estimate.				
					26	Aug 2, 2021	SYSTEM	(\$70,341.57)					
					27	Aug 16, 2021	SYSTEM	\$70,341.57	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0052) due to user herrmt1 overridding Payment Estimate Exception 23 on the current Payment Estimate.				
					27	Aug 16, 2021	SYSTEM	(\$70,341.57)					
					28	Sep 2, 2021	SYSTEM	\$70,341.57	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0075) due to user kloepj1 overridding Paymer Estimate Exception 23 on the current Payment Estimate.				
					28	Sep 2, 2021	SYSTEM	(\$70,341.57)					
					29	Sep 16, 2021	SYSTEM	\$70,341.57	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0072) due to user kloepj1 overridding Paymen Estimate Exception 38 on the current Payment Estimate.				
					29	Sep 16, 2021	SYSTEM	(\$70,341.57)					
				- Total				\$0.00					
			Material - Tot	al				\$0.00					
5	014 -	Total						\$0.00					
50	015	REINFORCING STEEL (EPOXY COATED)	Material		14	Feb 2, 2021	SYSTEM	\$36,892.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user hillto overridding Payment Estimate Exception 42 on the current Payment Estimate.				



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks					
J6I2222	5015	REINFORCING STEEL (EPOXY	Material		14	Feb 2, 2021	SYSTEM	(\$36,892.40)						
		COATED)			15	Feb 16, 2021	SYSTEM	\$36,892.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schlag1 overridding Payment Estimate Exception 47 on the current Payment Estimate.					
					15	Feb 16, 2021	SYSTEM	(\$36,892.40)						
					16	Mar 2, 2021	SYSTEM	\$36,892.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user kloepj1 overridding Payment Estimate Exception 46 on the current Payment Estimate.					
					16	Mar 2, 2021	SYSTEM	(\$36,892.40)						
					17	Mar 16, 2021	SYSTEM	\$36,892.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment Estimate Exception 39 on the current Payment Estimate.					
					17	Mar 16, 2021	SYSTEM	(\$36,892.40)						
					18	Apr 2, 2021	SYSTEM	\$36,892.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user kloepj1 overridding Payment Estimate Exception 42 on the current Payment Estimate.					
					18	Apr 2, 2021	SYSTEM	(\$36,892.40)						
					19	Apr 16, 2021	SYSTEM	\$36,892.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user kloepj1 overridding Payment Estimate Exception 46 on the current Payment Estimate.					
					19	Apr 16, 2021	SYSTEM	(\$36,892.40)						
					20	May 3, 2021	SYSTEM	\$36,892.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user hillt5 overridding Payment Estimate Exception 64 on the current Payment Estimate.					
					20	May 3, 2021	SYSTEM	(\$36,892.40)						
					21	May 17, 2021	SYSTEM	\$36,892.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0057) due to user hillt5 overridding Payment Estimate Exception 84 on the current Payment Estimate.					
					21	May 17, 2021	SYSTEM	(\$36,892.40)						
						22	Jun 2, 2021	SYSTEM	\$36,892.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0055) due to user hillt5 overridding Payment Estimate Exception 99 on the current Payment Estimate.				
												22	Jun 2, 2021	SYSTEM
					23	Jun 16, 2021	SYSTEM	\$36,892.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0064) due to user kloepj1 overridding Payment Estimate Exception 99 on the current Payment Estimate.					
					23	Jun 16, 2021	SYSTEM	(\$36,892.40)						
					24	Jul 1, 2021	SYSTEM	\$36,892.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0054) due to user herrmt1 overridding Payment Estimate Exception 61 on the current Payment Estimate.					
					24	Jul 1, 2021	SYSTEM	(\$36,892.40)						
					25	Jul 16, 2021	SYSTEM	\$36,892.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0065) due to user kloepj1 overridding Payment Estimate Exception 55 on the current Payment Estimate.					
					25	Jul 16, 2021	SYSTEM	(\$36,892.40)						
					26	Aug 2, 2021	SYSTEM	\$36,892.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0059) due to user hillt5 overridding Payment Estimate Exception 61 on the current Payment Estimate.					
					26	Aug 2, 2021	SYSTEM	(\$36,892.40)						
					27	Aug 16, 2021	SYSTEM	\$36,892.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0053) due to user herrmt1 overridding Payment Estimate Exception 55 on the current Payment Estimate.					
					27	Aug 16, 2021	SYSTEM	(\$36,892.40)						
					28	Sep 2,	SYSTEM	\$36,892.40	This adjustment offsets the original system-generated Material Payment					



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks														
J6I2222	5015	REINFORCING STEEL (EPOXY COATED)	Material			2021			Estimate Item Adjustment (0076) due to user kloepj1 overridding Payment Estimate Exception 56 on the current Payment Estimate.														
		,			28	Sep 2, 2021	SYSTEM	(\$36,892.40)															
					29	Sep 16, 2021	SYSTEM	\$36,892.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0073) due to user kloepj1 overridding Payment Estimate Exception 71 on the current Payment Estimate.														
					29	Sep 16, 2021	SYSTEM	(\$36,892.40)															
				- Total				\$0.00															
			Material - To	tal				\$0.00															
	5015 -							\$0.00															
	5019	MECHANICAL BAR SPLICE	Material		14	Feb 2, 2021	SYSTEM	\$2,532.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user hillt5 overridding Payment Estimate Exception 41 on the current Payment Estimate.														
					14	Feb 2, 2021	SYSTEM	(\$2,532.60)															
				- Total				\$0.00															
			Material - Tot	tal				\$0.00															
	5019 -	Total						\$0.00															
	5020	FURN & PLACE CONC MATL FOR FULL DEPTH	Material		15	Feb 16, 2021	SYSTEM	\$18,227.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schlag1 overridding Payment Estimate Exception 13 on the current Payment Estimate.														
					15	Feb 16, 2021	SYSTEM	(\$18,227.00)															
					16	Mar 2, 2021	SYSTEM	\$18,227.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user kloepj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.														
					16	Mar 2, 2021	SYSTEM	(\$18,227.00)															
					17	Mar 16, 2021	SYSTEM	\$18,227.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment Estimate Exception 13 on the current Payment Estimate.														
					17	Mar 16, 2021	SYSTEM	(\$18,227.00)															
					18	Apr 2, 2021	SYSTEM	\$18,227.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user kloepj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.														
						18	Apr 2, 2021	SYSTEM	(\$18,227.00)														
					19	Apr 16, 2021	SYSTEM	\$18,227.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user kloepj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.														
						19	Apr 16, 2021	SYSTEM	(\$18,227.00)														
															20	May 3, 2021	SYSTEM	\$18,227.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user hillt5 overridding Payment Estimate Exception 16 on the current Payment Estimate.				
							20	May 3, 2021	SYSTEM	(\$18,227.00)													
			21 May 17, 2021 \$18,227.00 This adjustment offsets the original s Estimate Item Adjustment (0058) due Estimate Exception 30 on the current 21 May 17, 2021 \$18,227.00 This adjustment offsets the original s Estimate Exception 30 on the current 22 Jun 2, 2021 \$18,227.00 This adjustment offsets the original s Estimate Item Adjustment (0056) due																21		SYSTEM	\$18,227.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user hillt5 overridding Payment Estimate Exception 30 on the current Payment Estimate.
														21		SYSTEM	(\$18,227.00)						
										22		SYSTEM	\$18,227.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0056) due to user hillt5 overridding Payment Estimate Exception 33 on the current Payment Estimate.									
					23	Jun 16, 2021	SYSTEM	\$18,227.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0065) due to user kloepj1 overridding Payment Estimate Exception 36 on the current Payment Estimate.														
					23	Jun 16, 2021	SYSTEM	(\$18,227.00)															
					24	Jul 1,	SYSTEM	\$18,227.00	This adjustment offsets the original system-generated Material Payment														



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks					
612222	5020	FURN & PLACE CONC MATL FOR	Material			2021			Estimate Item Adjustment (0055) due to user herrmt1 overridding Payment Estimate Exception 20 on the current Payment Estimate.					
		FULL DEPTH			24	Jul 1, 2021	SYSTEM	(\$18,227.00)						
				- Total				\$0.00						
			Material - To	tal				\$0.00						
	5020 -	Total						\$0.00						
	5021	TIE BAR (DRILL, FURN & INSTAL) (TYPE L	Material		15	Feb 16, 2021	SYSTEM	\$696.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user schlag1 overridding Payment Estimate Exception 18 on the current Payment Estimate.					
					15	Feb 16, 2021	SYSTEM	(\$696.00)						
					16	Mar 2, 2021	SYSTEM	\$696.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user kloepj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.					
					16	Mar 2, 2021	SYSTEM	(\$696.00)						
					17	Mar 16, 2021	SYSTEM	\$696.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.					
										17	Mar 16, 2021	SYSTEM	(\$696.00)	
						18	Apr 2, 2021	SYSTEM	\$696.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user kloepj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.				
					18	Apr 2, 2021	SYSTEM	(\$696.00)						
			- Total					\$0.00						
			Material - To	tal				\$0.00						
	5021 -	Total						\$0.00						
	5022		(DRILLING, FURNISHING AND	Material		15	Feb 16, 2021	SYSTEM	\$1,950.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schlag1 overridding Payment Estimate Exception 16 on the current Payment Estimate.				
						15	Feb 16, 2021	SYSTEM	(\$1,950.00)					
								16	Mar 2, 2021	SYSTEM	\$1,950.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user kloepj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.		
					16	Mar 2, 2021	SYSTEM	(\$1,950.00)	Estimate Exception 10 on the content ayment Estimate.					
				- Total	16		SYSTEM	(\$1,950.00) \$0.00	Estimate Exception 10 on the carretter ayment Estimate.					
			Material - To		16		SYSTEM	(, ,	Estimate Exception 10 on the standard agricult Estimate.					
	5022 -	Total	Material - To		16		SYSTEM	\$0.00	Estimate Exception to on the state of a stat					
	5022 - 5025	Total SEWER - RIGID PIPE	Material - To		18		SYSTEM	\$0.00 \$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user kloepj1 overridding Payment Estimate Exception 53 on the current Payment Estimate.					
		SEWER - RIGID				2021 Apr 2,		\$0.00 \$0.00 \$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user kloepj1 overridding Payment					
,		SEWER - RIGID			18	Apr 2, 2021 Apr 2,	SYSTEM	\$0.00 \$0.00 \$0.00 \$99,643.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user kloepj1 overridding Payment					
		SEWER - RIGID			18	Apr 2, 2021 Apr 2, 2021 Apr 16,	SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 \$99,643.00 (\$99,643.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user kloepj1 overridding Payment Estimate Exception 53 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user kloepj1 overridding Payment					
		SEWER - RIGID			18 18 19	Apr 2, 2021 Apr 2, 2021 Apr 16, 2021 Apr 16, 2021	SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 \$99,643.00 (\$99,643.00) \$147,772.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user kloepj1 overridding Payment Estimate Exception 53 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user kloepj1 overridding Payment					
		SEWER - RIGID			18 18 19	Apr 2, 2021 Apr 2, 2021 Apr 16, 2021 Apr 16, 2021 May 3,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 \$99,643.00 (\$99,643.00) \$147,772.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user kloepj1 overridding Payment Estimate Exception 53 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user kloepj1 overridding Payment Estimate Exception 61 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user hillt5 overridding Payment					
		SEWER - RIGID			18 18 19 19	Apr 2, 2021 Apr 2, 2021 Apr 16, 2021 Apr 16, 2021 May 3, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 \$99,643.00 (\$99,643.00) \$147,772.00 (\$147,772.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user kloepj1 overridding Payment Estimate Exception 53 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user kloepj1 overridding Payment Estimate Exception 61 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user hillt5 overridding Payment					
		SEWER - RIGID			18 18 19 19 20 20	Apr 2, 2021 Apr 2, 2021 Apr 16, 2021 Apr 16, 2021 May 3, 2021 May 17, May 17,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 \$99,643.00 (\$99,643.00) \$147,772.00 (\$147,772.00) (\$147,772.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user kloepj1 overridding Payment Estimate Exception 53 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user kloepj1 overridding Payment Estimate Exception 61 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user hillt5 overridding Payment Estimate Exception 86 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 86 on the current Payment Estimate.					



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																					
J6I2222	5025	SEWER - RIGID PIPE	Material						Estimate Exception 116 on the current Payment Estimate.																					
		PIPE			22	Jun 2, 2021	SYSTEM	(\$147,772.00)																						
					23	Jun 16, 2021	SYSTEM	\$147,772.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0066) due to user kloepj1 overridding Payment Estimate Exception 115 on the current Payment Estimate.																					
					23	Jun 16, 2021	SYSTEM	(\$147,772.00)																						
					24	Jul 1, 2021	SYSTEM	\$147,772.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0056) due to user herrmt1 overridding Payment Estimate Exception 76 on the current Payment Estimate.																					
					24	Jul 1, 2021	SYSTEM	(\$147,772.00)																						
					25	Jul 16, 2021	SYSTEM	\$147,772.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0066) due to user kloepj1 overridding Payment Estimate Exception 68 on the current Payment Estimate.																					
					25	Jul 16, 2021	SYSTEM	(\$147,772.00)																						
										26	Aug 2, 2021	SYSTEM	\$147,772.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user hillt5 overridding Payment Estimate Exception 73 on the current Payment Estimate.																
												26	Aug 2, 2021	SYSTEM	(\$147,772.00)															
														27	Aug 16, 2021	SYSTEM	\$147,772.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0054) due to user herrmt1 overridding Payment Estimate Exception 69 on the current Payment Estimate.												
								27	Aug 16, 2021	SYSTEM	(\$147,772.00)																			
							28	Sep 2, 2021	SYSTEM	\$147,772.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0077) due to user kloepj1 overridding Payment Estimate Exception 73 on the current Payment Estimate.																			
					28	Sep 2, 2021	SYSTEM	(\$147,772.00)																						
					29	Sep 16, 2021	SYSTEM	\$147,772.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0074) due to user kloepj1 overridding Payment Estimate Exception 88 on the current Payment Estimate.																					
					29	Sep 16, 2021	SYSTEM	(\$147,772.00)																						
				- Total				\$0.00																						
			Material - To	tal				\$0.00																						
	5025 - 5026	CLASS B-1 CONCRETE (SUBSTR)	Material		20	May 3, 2021	SYSTEM	\$0.00 \$140,119.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user hillt5 overridding Payment Estimate Exception 38 on the current Payment Estimate.																					
																						20	May 3, 2021	SYSTEM	(\$140,119.20)					
																						21	May 17, 2021	SYSTEM	\$140,119.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user hillt5 overridding Payment Estimate Exception 58 on the current Payment Estimate.				
					21	May 17, 2021	SYSTEM	(\$140,119.20)																						
													:	2	2	2										22	Jun 2, 2021	SYSTEM	\$140,119.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user hillt5 overridding Payment Estimate Exception 70 on the current Payment Estimate.
				2 2	:	2	2	23	23	23										22	Jun 2, 2021	SYSTEM	(\$140,119.20)							
																23	Jun 16, 2021	SYSTEM	\$140,119.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0067) due to user kloepj1 overridding Payment Estimate Exception 72 on the current Payment Estimate.										
											23	Jun 16, 2021	SYSTEM	(\$140,119.20)																
													;							2			2						24	Jul 1, 2021
					24	Jul 1, 2021	SYSTEM	(\$140,119.20)																						



ect	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks										
		,	Туре	Adjustment Type	Number	Date	Ву												
22	5026	CLASS B-1 CONCRETE (SUBSTR)	Material		25	Jul 16, 2021	SYSTEM	\$140,119.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0067) due to user kloepj1 overridding Payment Estimate Exception 36 on the current Payment Estimate.										
					25	Jul 16, 2021	SYSTEM	(\$140,119.20)											
					26	Aug 2, 2021	SYSTEM	\$140,119.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0061) due to user hillt5 overridding Payment Estimate Exception 36 on the current Payment Estimate.										
					26	Aug 2, 2021	SYSTEM	(\$140,119.20)											
					27	Aug 16, 2021	SYSTEM	\$140,119.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0055) due to user herrmt1 overridding Payment Estimate Exception 28 on the current Payment Estimate.										
					27	Aug 16, 2021	SYSTEM	(\$140,119.20)											
					28	Sep 2, 2021	SYSTEM	\$140,119.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0078) due to user kloepj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.										
					28	Sep 2, 2021	SYSTEM	(\$140,119.20)											
					29	Sep 16, 2021	SYSTEM	\$140,119.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0075) due to user kloepj1 overridding Payment Estimate Exception 45 on the current Payment Estimate.										
					29	Sep 16, 2021	SYSTEM	(\$140,119.20)											
				- Total				\$0.00											
			Material - To	tal				\$0.00											
	5026 -	Total						\$0.00											
	5029	SLAB ON CONCRETE NU- GIRDER	-	Material	Material	Material	Material	Material	Material	Material	Material	Material	Material		26	Aug 2, 2021	SYSTEM	\$69,426.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0062) due to user hillt5 overridding Payment Estimate Exception 43 on the current Payment Estimate.
																		26	Aug 2, 2021
					27	Aug 16, 2021	SYSTEM	\$121,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0057) due to user herrmt1 overridding Payment Estimate Exception 36 on the current Payment Estimate.										
					27	Aug 16, 2021	SYSTEM	(\$121,800.00)											
					28	Sep 2, 2021	SYSTEM	\$231,826.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0080) due to user kloepj1 overridding Payment Estimate Exception 35 on the current Payment Estimate.										
					28	Sep 2, 2021	SYSTEM	(\$231,826.00)											
					29	Sep 16, 2021	SYSTEM	\$309,372.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0078) due to user kloepj1 overridding Payment Estimate Exception 51 on the current Payment Estimate.										
					29	Sep 16, 2021	SYSTEM	(\$309,372.00)											
				- Total				\$0.00											
			Material - To	tal				\$0.00											
	5029 -	Total						\$0.00											
	5032	CONDUIT SYSTEM ON STRUCTURE	Material		29	Sep 16, 2021	SYSTEM	\$4,783.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0076) due to user kloepj1 overridding Payment Estimate Exception 66 on the current Payment Estimate.										
					29	Sep 16, 2021	SYSTEM	(\$4,783.20)											
				- Total				\$0.00											
								\$0.00											
			Material - To	tal															
	5032 -	Total	Material - To	tal				\$0.00											
	5032 - 5034	Total MISC. FENCING	Construction Stockpile	tal	20	May 3, 2021	SYSTEM		Payment Estimate Item Adjustment generated Stockpile Transaction										
			Construction	tal - Total	20		SYSTEM	\$0.00	Payment Estimate Item Adjustment generated Stockpile Transaction										
			Construction Stockpile STMI			2021	SYSTEM	\$0.00 \$32,885.60	Payment Estimate Item Adjustment generated Stockpile Transaction										



ject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
222	5037	REINFORCING STEEL (EPOXY COATED)	Material		20	May 3, 2021	SYSTEM	\$37.06	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user hillt5 overridding Payment Estimate Exception 66 on the current Payment Estimate.
					20	May 3, 2021	SYSTEM	(\$37.06)	
					21	May 17, 2021	SYSTEM	\$37,068.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0061) due to user hillt5 overridding Payment Estimate Exception 86 on the current Payment Estimate.
					21	May 17, 2021	SYSTEM	(\$37,068.50)	
					22	Jun 2, 2021	SYSTEM	\$37,068.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0059) due to user hillt5 overridding Payment Estimate Exception 101 on the current Payment Estimate.
					22	Jun 2, 2021	SYSTEM	(\$37,068.50)	
					23	Jun 16, 2021	SYSTEM	\$37,068.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0068) due to user kloepj1 overridding Payment Estimate Exception 101 on the current Payment Estimate.
					23	Jun 16, 2021	SYSTEM	(\$37,068.50)	Estimate Estephinist of an account a symbol Estimate.
					24	Jul 1, 2021	SYSTEM	\$37,068.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user herrmt1 overridding Payment Estimate Exception 63 on the current Payment Estimate.
					24	Jul 1, 2021	SYSTEM	(\$37,068.50)	
					25	Jul 16, 2021	SYSTEM	\$37,068.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0068) due to user kloepj1 overridding Payment Estimate Exception 56 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$37,068.50)	
					27	Aug 16, 2021	SYSTEM	\$37,068.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0056) due to user herrmt1 overridding Payment Estimate Exception 57 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$37,068.50)	
					28	Sep 2, 2021	SYSTEM	\$37,068.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0079) due to user kloepj1 overridding Payment Estimate Exception 58 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$37,068.50)	
					29	Sep 16, 2021	SYSTEM	\$37,068.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0077) due to user kloepj1 overridding Payment Estimate Exception 73 on the current Payment Estimate.
					29	Sep 16, 2021	SYSTEM	(\$37,068.50)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	5037 -						a) (a==:	\$0.00	
	5038	PROTECTIVE COATING - CONCRETE BENTS AND	Material		28	Sep 2, 2021	SYSTEM	\$13,118.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0081) due to user kloepj1 overridding Payment Estimate Exception 61 on the current Payment Estimate.
		AND			28	Sep 2, 2021	SYSTEM	(\$13,118.70)	
					29	Sep 16, 2021	SYSTEM	\$13,118.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0079) due to user kloepj1 overridding Payment Estimate Exception 76 on the current Payment Estimate.
					29	Sep 16, 2021	SYSTEM	(\$13,118.70)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	5038 -	· Total						\$0.00	
	5044	SLOPE PROTECTION	Material		27	Aug 16, 2021	SYSTEM	\$73,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user herrmt1 overridding Paymen Estimate Exception 12 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$73,440.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I2222	5044	SLOPE PROTECTION	Material		28	Sep 2, 2021	SYSTEM	\$73,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0082) due to user kloepj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$73,440.00)	
					29	Sep 16, 2021	SYSTEM	\$73,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0080) due to user kloepj1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					29	Sep 16, 2021	SYSTEM	(\$73,440.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	5044 -	Total						\$0.00	
	5047	15 IN. PIPE CULVERT GROUP C	Material		25	Jul 16, 2021	SYSTEM	\$6,160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0069) due to user kloepj1 overridding Payment Estimate Exception 67 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$6,160.00)	
					26	Aug 2, 2021	SYSTEM	\$6,160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0063) due to user hillt5 overridding Payment Estimate Exception 72 on the current Payment Estimate.
					26	Aug 2, 2021	SYSTEM	(\$6,160.00)	
					27	Aug 16, 2021	SYSTEM	\$6,160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0059) due to user herrmt1 overridding Payment Estimate Exception 68 on the current Payment Estimate.
					27	Aug 16, 2021	SYSTEM	(\$6,160.00)	
					28	Sep 2, 2021	SYSTEM	\$6,160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0083) due to user kloepj1 overridding Payment Estimate Exception 71 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$6,160.00)	
					29	Sep 16, 2021	SYSTEM	\$6,160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0081) due to user kloepj1 overridding Payment Estimate Exception 86 on the current Payment Estimate.
					29	Sep 16, 2021	SYSTEM	(\$6,160.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	5047 -	Total						\$0.00	
	5048	18 IN. PIPE CULVERT GROUP C	Material		28	Sep 2, 2021	SYSTEM	\$7,920.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0084) due to user kloepj1 overridding Payment Estimate Exception 72 on the current Payment Estimate.
					28	Sep 2, 2021	SYSTEM	(\$7,920.00)	
					29	Sep 16, 2021	SYSTEM	\$7,920.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0082) due to user kloepj1 overridding Payment Estimate Exception 87 on the current Payment Estimate.
					29	Sep 16, 2021	SYSTEM	(\$7,920.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	5048 -	Total						\$0.00	
	5049	18 IN. GROUP A FLARED END SECT	Material		25	Jul 16, 2021	SYSTEM	\$1,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0070) due to user kloepj1 overridding Payment Estimate Exception 72 on the current Payment Estimate.
					25	Jul 16, 2021	SYSTEM	(\$1,800.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	5049 -	Total						\$0.00	
J6I2222 -	Total							\$387,483.66	
Overall -	Total							\$387,483.66	