Pay Estimate Created Date: May 17, 2021

Progress Estimate N 13	umber	Contract ID Prime Contractor	200515-H06 Robertson Contra	actors, Inc.	Pay Period Start Pay Period End		Original Contract Amount Net Change Order Amount Current Contract Amount	\$2,217,395.64 \$17,274.73 \$2,234,670.37		
Approval Date								By User		
May 17, 2021		the Project Office Level by	philpd1							
May 17, 2021		Resident Engineer Level by	bollis1							
May 18, 2021		Controllers Office Level by	ramses1							
Original Completion	n Date	Current Con	npletion Date	tion Date Actual Completion Date % of Current Contract A						
June 1, 2021		October	21, 2021				35.34%			
	Contrac	t Informational Dat	tes		Milesto	nes				
Date Description	Original	Completion Date	Current Comple	tion Date	No Milestones Exis	st for Contract				
Acceptance Date										
Awarded Date	June 3, 2	2020	June 3, 2020							
Letting Date	Letting Date May 15, 2020									
Notice to Proceed Date August 3, 2020 August 3, 20										
Open to Traffic Date										
Work Began Date										

Contract Total Pay For Estimate No. 13										
	This Estimate	Previous	To Date							
200515-H06										
Total Posted Items Pay	\$448,621.25	\$341,144.92	\$789,766.17							
Gross Item Adjustments	\$0.00	\$0.00	\$0.00							
Incentive	\$0.00	\$0.00	\$0.00							
Disincentive	\$0.00	\$0.00	\$0.00							
Liquidated Damage	\$0.00	\$0.00	\$0.00							
Other Contract Adjustments	\$0.00	\$0.00	\$0.00							
		\$341,144.92	\$789,766.17							
Contract Total Payable This Estimate:	\$448,621.25									

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J9S3063	0550	7021316	GALVANIZED CAST-IN-PLACE CONCRETE PILES (16 IN)	LF	\$85.000	3,618	\$307,530.00
	0560	7025001	DYNAMIC PILE TESTING	EA	\$3,000.000	1	\$3,000.00
	0570	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	CUYD	\$850.000	120.1	\$102,085.00
	0610	7061060	REINFORCING STEEL (BRIDGES)	LB	\$1.250	28,805	\$36,006.25
Project J9S30	63 - Total						\$448,621.25
Overall - Total							\$448,621.25

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9S3063	0060	POROUS BACKFILL	Material			-13.6	\$80.00	(\$1,088.00)
	0060	POROUS BACKFILL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user philpd1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	13.6	\$80.00	\$1,088.00
	0110	TYPE A2 SHOULDER	Material			-105.4	\$55.00	(\$5,797.00)
	0110	TYPE A2 SHOULDER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user philpd1	105.4	\$55.00	\$5,797.00



Pay Estimate Created Date: May 17, 2021

Progre	ess Esti 1	mate Number 3	Contract ID Prime Contr	20051 ractor Rober		ors, Inc. Pay Period End May 15, 2021 Net	inal Contract Change Orde ent Contract	r Amount \$	2,217,395.64 17,274.73 2,234,670.37
Project Number	Line No.	Item Desc	ription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9S3063						overridding Payment Estimate Exception 2 on the current Payment Estimate.			
	0120		MISC.	Material			-37.6	\$45.66	(\$1,716.82
	0120		MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user philpd1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	37.6	\$45.66	\$1,716.82
	0290	BARR	TE TRAFFIC IER, TYPE D NING WALL)	Material			-85	\$100.00	(\$8,500.00
	0290	BARR	TE TRAFFIC IER, TYPE D NING WALL)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user philpd1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	85	\$100.00	\$8,500.00
	0550	GALVANIZ PLACE CONC	ED CAST-IN- RETE PILES (16 IN)	Material			-3,618	\$85.00	(\$307,530.00
	0550	GALVANIZI PLACE CONC	ED CAST-IN- RETE PILES (16 IN)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user philpd1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	3,618	\$85.00	\$307,530.00
	0570		CONCRETE TRUCTURE)	Material			-43	\$850.00	(\$36,550.00
			CONCRETE TRUCTURE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user philpd1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	43	\$850.00	\$36,550.00
	0610	REINFOR	CING STEEL (BRIDGES)	Material			-28,805	\$1.25	(\$36,006.25
	0610	REINFOR	CING STEEL (BRIDGES)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user philpd1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	28,805	\$1.25	\$36,006.25
Total									\$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Со	ntract Project Informa	tion				
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work				
J9S3063	FAF-61-1(14)	61-1(14) Bridge replacement BUS 61 SCOTT over Route M and Railroad									
Totals by .	Job Numbers										
J9S3063	Posted Ite Gross Iter	n Adjustments	s iross Iter	n Pay	This Estimate \$448,621.25 \$0.00 \$448,621.25	Previous \$341,144.92 \$0.00 \$341,144.92	To Date \$789,766.17 \$0.00 \$789,766.17				
		ve I Damages Itract Adjustm	ents		\$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00						



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J9S3063, Item 2064000, Project Item Line Number 0060, Material Set 206400096, Material 1009G3DRLD - Agg for Drainage Gr3 Limestone/Dolomite, Acceptance Action Generic 1009G3DRLD is insufficient.	Robertson is working with Koehler to get a passing sample. QA and quarry tested sample passed. QA split from Koehler passed, but Koehler's test did not pass.	philpd1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3063, Item 4010150, Project Item Line Number 0110, Material Set 401015096, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	QC Testing complete and entered.	philpd1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3063, Item 4019905, Project Item Line Number 0120, Material Set 401990596, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	QC Testing complete and entered.	philpd1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3063, Item 6173102, Project Item Line Number 0290, Material Set 617310296, Material 1057JMDBEC6.10 - Dowel Bar Epoxy Ctd Gr60 1" @, Acceptance Action Generic ReinforcingMisc is insufficient.	Waiting on PAL from Saber Steel	philpd1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3063, Item 7021316, Project Item Line Number 0550, Material Set 702131696, Material 0702PLCPCCZC - Bearing Piles Shell Casing for CIP Galvd, Acceptance Action Generic 0702PLCPCCZC is insufficient.	QC testing not entered.	philpd1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3063, Item 7021316, Project Item Line Number 0550, Material Set 702131696, Material 0501CCB1 - Concrete, Class B-1 No Air, Acceptance Action Generic 0501CCB1 is insufficient.	QC testing not entered.	philpd1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3063, Item 7032003, Project Item Line Number 0570, Material Set 703200396, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	QC testing not entered.	philpd1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3063, Item 7061060, Project Item Line Number 0610, Material Set 706106096, Material 1036RSDFPL42M19 - Reinforcing Steel No. 6/M19 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Robertson is working with Saber to clear up PAL	philpd1	Overridden



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category		ltem Code	eport Generated date and can differ from the posted amo Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200515-H06	J9S3063	0001	0010	2013000	CLEARING AND GRUBBING	1.00	0.00	1.00	ACRE	0.70	\$5,000.00	\$3,500.00
		0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.45	\$16,500.00	\$7,425.00
		0001	0030	2031000	CLASS A EXCAVATION	1,512.00	0.00	1,512.00	CUYD	0.00	\$8.00	\$0.00
		0001	0040	2035500	EMBANKMENT IN PLACE	445.00	0.00	445.00	CUYD	0.00	\$12.00	\$0.00
		0001	0050	2036000	COMPACTING EMBANKMENT	1,260.00	0.00	1,260.00	CUYD	0.00	\$1.50	\$0.00
		0001	0060	2064000	POROUS BACKFILL	52.00	0.00	52.00	CUYD	13.60	\$80.00	\$1,088.00
		0001	0070	2071000	LINEAR GRADING CLASS 1	1.00	0.00	1.00	STA	0.50	\$2,000.00	\$1,000.00
		0001	0080	2072000	LINEAR GRADING CLASS 2	2.10	0.00	2.10	STA	0.00	\$3,800.00	\$0.00
		0001	0090	2159903	MISC.MODIFIED SHAOING SLOPES, CLASS III	375.00	0.00	375.00	LF	0.00	\$22.11	\$0.00
		0001	0100	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	1,552.00	0.00	1,552.00	SQYD	143.00	\$9.50	\$1,358.50
		0001	0110	4010150	TYPE A2 SHOULDER	452.10	0.00	452.10	SQYD	105.40	\$55.00	\$5,797.00
		0001	0120	4019905	MISC.OPTIONAL PAVEMENT	1,150.90	0.00	1,150.90	SQYD	37.60	\$45.66	\$1,716.82
		0001	0125	6079901	MISC.Temporary Fencing	1.00	0.00	1.00	LS	0.00	\$3,600.00	\$0.00
		0001	0130	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	186.00	0.00	186.00	LF	0.00	\$80.00	\$0.00
		0001	0140	6096020	FURNISHING TYPE 2 ROCK DITCH LINER	112.00	0.00	112.00	CUYD	0.00	\$30.00	\$0.00
		0001	0150	6096042	PLACING TYPE 2 ROCK DITCH LINER	112.00	0.00	112.00	CUYD	0.00	\$15.00	\$0.00
		0001	0160	6113020	FURNISHING TYPE 2 ROCK BLANKET	280.00	0.00	280.00	CUYD	118.40	\$28.00	\$3,315.20
		0001	0170	6113040	PLACING TYPE 2 ROCK BLANKET	280.00	0.00	280.00	CUYD	118.40	\$20.00	\$2,368.00
		0001	0180	6122008	IMPACT ATTENUATOR 40 MPH (SAND BARREL ARRAY)	2.00	0.00	2.00	EA	2.00	\$1,600.00	\$3,200.00
		0001	0190	6122020	REPLACEMENT SAND BARREL	2.00	0.00	2.00	EA	0.00	\$200.00	\$0.00
		0001	0200	6122030	IMPACT ATTENUATOR (RELOCATION)	2.00	0.00	2.00	EA	2.00	\$800.00	\$1,600.00
		0001	0210	6161005	CONSTRUCTION SIGNS	394.00	0.00	394.00	SQFT	394.00	\$7.00	\$2,758.00
		0001	0220	6161008	ADVANCED WARNING RAIL SYSTEM	3.00	3.00	6.00	EA	6.00	\$45.00	\$270.00
		0001	0230	6161009	FLAG ASSEMBLY	3.00	2.00	5.00	EA	5.00	\$20.00	\$100.00
		0001	0240	6161025	CHANNELIZER (TRIM LINE)	60.00	0.00	60.00	EA	55.00	\$15.00	\$825.00
		0001	0250	6161030	TYPE III MOVEABLE BARRICADE	6.00	5.00	11.00	EA	11.00	\$115.00	\$1,265.00
		0001	0260	6161031	TYPE III MOVEABLE BARRICADE WITH LIGHTS	6.00	0.00	6.00	EA	6.00	\$135.00	\$810.00
		0001	0270	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$3,500.00	\$7,000.00
		0001	0280	6173100	CONCRETE TRAFFIC BARRIER, TYPE D	65.00	0.00	65.00	LF	0.00	\$100.00	\$0.00
		0001	0290	6173102	CONCRETE TRAFFIC BARRIER, TYPE D (RETAINING WALL)	85.00	0.00	85.00	LF	85.00	\$100.00	\$8,500.00
		0001	0300	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	150.00	12.50	162.50	LF	162.50	\$38.00	\$6,175.00
		0001	0310	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	150.00	0.00	150.00	LF	137.50	\$15.00	\$2,062.50
		0001	0320	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$200,000.00	\$0.00
		0001	0321	6181000	MOBILIZATION	0.00	1.00	1.00	LS	0.00	\$183,059.00	\$0.00
		0001	0330	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	2.00	0.00	2.00	EA	0.00	\$600.00	\$0.00
		0001	0331	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	36.00	0.00	36.00	LF	0.00	\$25.00	\$0.00
		0001	0332	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	2.00	0.00	2.00	EA	0.00	\$350.00	\$0.00
		0001	0333	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	1,056.00	0.00	1,056.00	LF	1,053.00	\$1.25	\$1,316.25
		0001	0334	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	1,626.00	0.00	1,626.00	LF	1,608.00	\$1.25	\$2,010.00
		0001	0335	6205320	TEMPORARY REMOVABLE MARKING TAPE, 12 IN., WHITE	36.00	0.00	36.00	LF	11.00	\$3.75	\$41.25
		0001	0340	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING	2,406.00	0.00	2,406.00	LF	0.00	\$0.55	\$0.00
		0001	0350	6206001C		2,831.00	0.00	2,831.00	LF	0.00	\$0.55	\$0.00
		MARKING PAINT, TYPE P BEADS	MARKING PAINT, TYPE P BEADS									
		0001	0351	6207001	PAVEMENT MARKING REMOVAL	1,317.00	0.00	1,317.00	LF	1,317.00	\$0.75	\$987.75
		0001	0352	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	4.00	0.00	4.00	EA	4.00	\$100.00	\$400.0



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Vote: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note: Posted Q	uantities	and Valu	es are b	ased on R	eport Generated date and can differ from the posted am	ount at the	time the	Estimate wa	as Gene	rated.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200515-H06	J9S3063	0001	0353	6209902	MISC.PREFORMED THERMOPLASTIC PAVEMENT MARKING, SHEILD	2.00	0.00	2.00	EA	0.00	\$1,100.00	\$0.00
		0001	0360	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	796.00	0.00	796.00	SQYD	215.00	\$3.00	\$645.00
		0001	0370	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.15	\$10,000.00	\$1,500.00
		0001	0380	8051000A	SEEDING - COOL SEASON MIXTURES	1.50	0.00	1.50	ACRE	0.00	\$4,200.00	\$0.00
		0001	0390	8061005	ROCK DITCH CHECK	80.00	0.00	80.00	LF	22.00	\$18.00	\$396.00
		0001	0400	8061017	TEMPORARY SEEDING AND MULCHING	1.00	0.00	1.00	ACRE	0.00	\$900.00	\$0.00
		0001	0410	8061019	SILT FENCE	2,560.00	0.00	2,560.00	LF	165.00	\$3.00	\$495.00
		0001	0420	8064140	TYPE 3B EROSION CONTROL BLANKET	5,125.00	0.00	5,125.00	SQYD	0.00	\$2.10	\$0.00
		0001	0430	8065000	GEOSYNTHETIC REINFORCED SOIL SLOPE SYSTEM	1,500.00	0.00	1,500.00	SQFT	1,125.00	\$40.00	\$45,000.00
		0001	0440	8069902	MISC.FLOCCULANT SOCK	8.00	0.00	8.00	EA	0.00	\$150.00	\$0.00
		0010	0450	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	1,400.00	0.00	1,400.00	LF	0.00	\$22.21	\$0.00
		0010	0460	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	3.00	0.00	3.00	EA	0.00	\$3,342.26	\$0.00
		0010	0470	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	5.00	0.00	5.00	EA	0.00	\$3,227.88	\$0.00
		0070	0480	2061000	CLASS 1 EXCAVATION	560.00	0.00	560.00	CUYD	560.00	\$20.00	\$11,200.00
		0070	0490	2065500	TEMPORARY SHORING	1.00	0.00	1.00	LS	1.00	\$10,500.00	\$10,500.00
		0070	0500	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$105,000.00	\$105,000.00
		0070	0510	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	148.00	0.00	148.00	SQYD	0.00	\$215.00	\$0.00
		0070	0520	6071060	PEDESTRIAN FENCE (STRUCTURES)	275.00	0.00	275.00	LF	0.00	\$102.43	\$0.00
		0070	0530	6071067	(112 IN.) CURVED TOP PEDESTRIAN FENCE (STRUCTURES)	289.00	0.00	289.00	LF	0.00	\$168.43	\$0.00
		0070	0540	7021314	GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN)	882.00	0.00	882.00	LF	509.00	\$75.00	\$38,175.00
		0070	0550	7021316	GALVANIZED CAST-IN-PLACE CONCRETE PILES (16 IN)	3,618.00	0.00	3,618.00	LF	3,618.00	\$85.00	\$307,530.00
		0070	0560	7025001	DYNAMIC PILE TESTING	4.00	0.00	4.00	EA	4.00	\$3,000.00	\$12,000.00
		0070	0570	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	211.30	0.00	211.30	CUYD	149.80	\$850.00	\$127,330.00
		0070	0580	7034219A	TYPE D BARRIER	594.00	0.00	594.00	LF	0.00	\$125.00	\$0.00
		0070	0590	7034221	SLAB ON CONCRETE NU-GIRDER	1,019.00	0.00	1,019.00	SQYD	0.00	\$335.00	\$0.00
		0070	0600	7056022	NU 43, PRESTRESSED CONCRETE NU-GIRDER	1,308.00	0.00	1,308.00	LF	0.00	\$245.00	\$0.00
		0070	0610	7061060	REINFORCING STEEL (BRIDGES)	39,980.00	0.00	39,980.00	LB	31,354.00	\$1.25	\$39,192.50
		0070	0620	7123301	STEEL INTERMEDIATE DIAPHRAGM FOR P/S CONCRETE GIRDERS	20.00	0.00	20.00	EA	0.00	\$700.00	\$0.00
		0070	0630	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	1.00	\$2,000.00	\$2,000.00
		0070	0640	7161002	LAMINATED NEOPRENE BEARING PAD	7.00	0.00	7.00	EA	0.00	\$220.00	\$0.00
		0070	0650	7161003	LAMINATED NEOPRENE BEARING PAD (TAPERED)	23.00	0.00	23.00	EA	0.00	\$330.00	\$0.00
		0001	5001	6181000	MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$16,941.00	\$16,941.00
		0001	5002	9031010	CONCRETE FOOTINGS, EMBEDDED	0.00	4.00	4.00	CUYD	2.00	\$472.64	\$945.28
		0001	5003	9031210	STRUCTURAL STEEL POSTS	0.00	190.00	190.00	LB	130.00	\$19.43	\$2,525.90
		0001	5004	9019901	MISC.Pull Box Relocation and Pushed Cable Conduit	0.00	1.00	1.00	LS	1.00	\$10,467.47	\$10,467.47
					ate as of Report Generated Date							\$798,732.42
200515-H06 Ove	erall - Total	Value Pos	ted to Da	te as of Repo	ort Generated Date							\$798,732.42



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0550	7021316	GALVANIZED CIP CONCR PILES (16 IN)	5/6/21	5/17/21	2,033.00	LF	BU 61 - Bent 2 Piles	190+10.75	CL			Piles 7-19 and 21-33 driven to 67'. Each with one split for a total pay of 75'. Pile 20 driven to 75'. One splice for a total pay of 83'.
												75'x26 = 1950' + 83' = 2033'
			5/12/21	5/17/21	-441.00	LF	Overrun quantity to be placed on next change order.					
				5/17/21	2,026.00	LF	Bu 61 - Bent 3	190+10.75	CL			Piles 34-46 & 48-60 driven to 67'. Each with one splic 67+8x26 = 1950' Pile 48 driven to 68'. One splice. 68+8 = 76' 1950+76 = 2026'
0560	0560 7025001	DYNAMIC PILE TESTING	5/4/21	5/5/21	-1.00	EA	Overrun Quantity - To be included in the next change order					
				5/5/21	1.00	EA	BU 61 - Bent 2 pile 20 - Restrike	190+10.75	CL			
				5/5/21	1.00	EA	BU 61 - Bent 3 Pile 47 - Initial Test	191+21.75	CL			
			5/11/21	5/17/21	-1.00	EA	Overrun quantity to be included in next change order.					
				5/17/21	1.00	EA	BU 61 - Bent 4	191+79.61	CL			
0570	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	5/10/21	5/17/21	14.30	CUYD	BU 61 - Bent 2 East footing	190+10.75	CL			
			5/11/21	5/17/21	35.50	CUYD	BU 61 - Bent 2		CL	190+10.75		East column - 6.9cy Center and west footing - 14.3cy x 2 = 28.6cy
			5/12/21	5/17/21	13.80	CUYD	BU 61 - Bent 2 Columns	190+10.75	CL			West and center column - 6.9 x 2 = 13.8cy
			5/13/21	5/17/21	42.90	CUYD	BU 61 - Bent 3 Footings	191+21.75	CL			3 footings - 14.3 x 3 = 42.9cy
			5/14/21	5/17/21	13.60	CUYD	BU 61 - Bent 3 - 2 Columns	191+21.75	CL			2 Columns = 6.8 x 2 = 13.6cy
0610	7061060	REINFORCING STEEL (BRIDGES)	5/12/21	5/17/21	15,743.00	LB	BU 61 - Bent 2	190+10.75	CL			Footings & Columns - 7980 + 7763 = 15743 lbs
			5/13/21	5/17/21	7,965.00	LB	BU 61 - Bent 3 Piles & Footing	191+21.75	CL			
			5/14/21	5/17/21	5,097.00	LB	Bu 61 - Bent 3 - 2 Columns	191+21.75	CL			

roject	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post									
S3063	0210	December 3, 2020	218	Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		0.099	I-55 SB Off Ramp	19.50	1	Detour Route Assembly		19.5									
				R11-2 48x30 10.00 ROAD CLOSED		0.315	BU 61 S	3.00	10			30									
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		7.369	Route M E	19.50	1	Detour Route Assembly		19.5									
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		7.258	Route M E	19.50	1	Detour Route Assembly		19.5									
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		299.064	Route 61 S	19.50	1	Detour Route Assembly		19.5									
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		2.389	BU 61 S	32.00	1	BU 61 Closed 2 Miles Ahead		32									
					Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		121.954	I-55 S	19.50	1	Detour Route Assembly		19.5								
					R11-3a 60x30 12.50 ROAD CLOSED XX MILES AHEAD LOCAL TRAFFIC ONLY		1.482	BU 61 S	1.00	12.5			12.5								
				WO20-3 48x48 16.00 ROAD CLOSED AHEAD		0.819	BU 61 S	1.00	16			16									
				R11-2 48x30 10.00 ROAD CLOSED		0.620	BU 61 S	1.00	10			10									
				R11-2 48x30 10.00 ROAD CLOSED		0.537	BU 61 S	1.00	10			10									
				R11-2 48x30 10.00 ROAD CLOSED		0.444	BU 61 S	1.00	10			10									
		December 8, 2020	32	WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		7.045	Route M EB	1.00	16			16									
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		7.632	Route M EB	1.00	16			16									
		December 17, 2020	48	WO20-3a 4x4 16.00 ROAD CLOSED 500 FT		0.728	BU 61 SB	1.00	16			16									
								WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		0.025	BU 61 SB (I-55 SB Off Ramp)	1.00	16			16					
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		0.135	I-55 NB Off Ramp	1.00	16			16									
		March 19, 2021		F V (V V V		WO20-4 48x48 16.00 ONE LANE ROAD AHEAD		7.576	Route M EB	1.00	16			16							
							(\ () \ \	(S W (S W					WO20-7a 48x48 16.00 FLAGGER (SYMBOL)		7.196	Route M EB	1.00	16			16
									WO20-7a 48x48 16.00 FLAGGER (SYMBOL)		7.446	Route M EB	1.00	16			16				
									WO20-4 48x48 16.00 ONE LANE ROAD AHEAD		0.175	I-55 SB Off Ramp	1.00	16			16				
				WO20-7a 48x48 16.00 FLAGGER (SYMBOL)		0.215	I-55 SB Off Ramp	1.00	16			16									
				WO20-4 48x48 16.00 ONE LANE ROAD AHEAD		7.088	Route M EB	1.00	16			16									
	0210 - Total				_	_						394									



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks													
Floject	Line	Description	Туре	Adjustment Type	Number	Date	By	Amount	I VEITIGI KS													
J9S3063	0060	POROUS BACKFILL	Material		9	Mar 16, 2021	SYSTEM	\$1,088.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user petrid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.													
					9	Mar 16, 2021	SYSTEM	(\$1,088.00)														
					10	Apr 1, 2021	SYSTEM	\$1,088.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user petrid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.													
					10	Apr 1, 2021	SYSTEM	(\$1,088.00)														
						11	Apr 16, 2021	SYSTEM	\$1,088.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user petrid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.												
									11	Apr 16, 2021	SYSTEM	(\$1,088.00)										
					12	May 3, 2021	SYSTEM	\$1,088.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user petrid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.													
														12	May 3, 2021	SYSTEM	(\$1,088.00)					
					13	May 17, 2021	SYSTEM	\$1,088.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user philpd1 overridding Payment Estimate Exception 1 on the current Payment Estimate.													
					13	May 17, 2021	SYSTEM	(\$1,088.00)														
				- Total		1		\$0.00														
			Material - To	otal				\$0.00														
	0060 -	0 - Total						\$0.00														
	0100	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		9	Mar 16, 2021	SYSTEM	\$1,358.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user petrid1 overridding Payment Estimate Exception 3 on the current Payment Estimate.													
							9	Mar 16, 2021	SYSTEM	(\$1,358.50)												
					10	Apr 1, 2021	SYSTEM	\$1,358.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user petrid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.													
															10	Apr 1, 2021	SYSTEM	(\$1,358.50)				
						11	Apr 16, 2021	SYSTEM	\$1,358.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user petrid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.												
					11	Apr 16, 2021	SYSTEM	(\$1,358.50)														
				- Total				\$0.00														
			Material - To	otal				\$0.00														
	0100 -	Total						\$0.00														
	0110	TYPE A2 SHOULDER	Material		9	Mar 16, 2021	SYSTEM	\$5,797.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user petrid1 overridding Payment Estimate Exception 4 on the current Payment Estimate.													
					9	Mar 16, 2021	SYSTEM	(\$5,797.00)														
			11	10	10	1			10					1	1(1		10	Apr 1, 2021	SYSTEM	\$5,797.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user petrid1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				1	10		10					10	Apr 1, 2021	SYSTEM	(\$5,797.00)							
					11	Apr 16, 2021	SYSTEM	\$5,797.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user petrid1 overridding Payment Estimate Exception 3 on the current Payment Estimate.													
					11	Apr 16, 2021	SYSTEM	(\$5,797.00)														
					13	May 17, 2021	SYSTEM	\$5,797.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user philpd1 overridding Payment Estimate Exception 2 on the current Payment Estimate.													
					13	May 17,	SYSTEM	(\$5,797.00)														



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
063	0110	TYPE A2	Material			2021			
		SHOULDER		- Total				\$0.00	
			Material - To	otal				\$0.00	
	0110 -	lotal						\$0.00	
	0120	MISC.	Material		9	Mar 16, 2021	SYSTEM	\$1,716.82	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user petrid1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					9	Mar 16, 2021	SYSTEM	(\$1,716.82)	
					10	Apr 1, 2021	SYSTEM	\$1,716.82	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user petrid1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					10	Apr 1, 2021	SYSTEM	(\$1,716.82)	
					11	Apr 16, 2021	SYSTEM	\$1,716.82	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user petrid1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					11	Apr 16, 2021	SYSTEM	(\$1,716.82)	
					12	May 3, 2021	SYSTEM	\$1,716.82	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user petrid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					12	May 3, 2021	SYSTEM	(\$1,716.82)	
					13	May 17, 2021	SYSTEM	\$1,716.82	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user philpd1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					13	May 17, 2021	SYSTEM	(\$1,716.82)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0120 -	Total						\$0.00	
	0180	IMPACT ATTENUATOR 40 MPH (SAND BARREL ARRAY)	Material		3	Dec 16, 2020	SYSTEM	\$3,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user petrid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Dec 16, 2020	SYSTEM	(\$3,200.00)	
					4	Jan 4, 2021	SYSTEM	\$3,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user petrid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Jan 4,	SYSTEM SYSTEM	\$3,200.00	Estimate Item Adjustment (0005) due to user petrid1 overridding Payment
				- Total		Jan 4, 2021 Jan 4,			Estimate Item Adjustment (0005) due to user petrid1 overridding Payment
			Material - Te			Jan 4, 2021 Jan 4,		(\$3,200.00)	Estimate Item Adjustment (0005) due to user petrid1 overridding Payment
	0180 -	Total	Material - To			Jan 4, 2021 Jan 4,		(\$3,200.00) \$0.00	Estimate Item Adjustment (0005) due to user petrid1 overridding Payment
	0180 - 0210	Total CONSTRUCTION SIGNS	Material - Te			Jan 4, 2021 Jan 4,		(\$3,200.00) \$0.00 \$0.00	Estimate Item Adjustment (0005) due to user petrid1 overridding Payment
I		CONSTRUCTION			4	Jan 4, 2021 Jan 4, 2021 Dec 16,	SYSTEM	(\$3,200.00) \$0.00 \$0.00 \$0.00	Estimate Item Adjustment (0005) dué to user petrid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
I		CONSTRUCTION			3	Jan 4, 2021 Jan 4, 2021 Dec 16, 2020	SYSTEM	(\$3,200.00) \$0.00 \$0.00 \$1,750.00	Estimate Item Adjustment (0005) dué to user petrid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
I		CONSTRUCTION		otal	4 3 3 3	Jan 4, 2021 Jan 4, 2021 Dec 16, 2020 Dec 16, 2020 Jan 4,	SYSTEM SYSTEM SYSTEM	(\$3,200.00) \$0.00 \$0.00 \$1,750.00 (\$1,750.00) \$2,086.00 (\$2,086.00)	Estimate Item Adjustment (0005) due to user petrid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
I		CONSTRUCTION	Material	- Total	4 3 3 4	Jan 4, 2021 Jan 4, 2021 Dec 16, 2020 Dec 16, 2020 Jan 4, 2021 Jan 4,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$3,200.00) \$0.00 \$0.00 \$1,750.00 (\$1,750.00) \$2,086.00 (\$2,086.00) \$0.00	Estimate Item Adjustment (0005) due to user petrid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
I	0210	CONSTRUCTION SIGNS		- Total	4 3 3 4	Jan 4, 2021 Jan 4, 2021 Dec 16, 2020 Dec 16, 2020 Jan 4, 2021 Jan 4,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$3,200.00) \$0.00 \$0.00 \$1,750.00 (\$1,750.00) \$2,086.00 (\$2,086.00)	Estimate Item Adjustment (0005) dué to user petrid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		CONSTRUCTION SIGNS	Material	- Total	4 3 3 4	Jan 4, 2021 Jan 4, 2021 Dec 16, 2020 Dec 16, 2020 Jan 4, 2021 Jan 4,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$3,200.00) \$0.00 \$0.00 \$1,750.00 (\$1,750.00) \$2,086.00 (\$2,086.00) \$0.00	Estimate Item Adjustment (0005) dué to user petrid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
	0210	CONSTRUCTION SIGNS	Material Material - To	- Total	4 3 3 4	Jan 4, 2021 Jan 4, 2021 Dec 16, 2020 Dec 16, 2020 Jan 4, 2021 Jan 4,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$3,200.00) \$0.00 \$1,750.00 (\$1,750.00) \$2,086.00 (\$2,086.00) \$0.00 \$0.00	Estimate Item Adjustment (0005) dué to user petrid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.



May 18, 2021

Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
			Туре	Adjustment Type	Number	Date	Ву		
J9S3063	0220	ADVANCED WARNING RAIL SYSTEM	Material		4	Jan 4, 2021	SYSTEM	\$135.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user petrid1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					4	Jan 4, 2021	SYSTEM	(\$135.00)	
				- Total	1			\$0.00	
			Material - Total					\$0.00	
	0220 -	otal						\$0.00	
	0230	FLAG ASSEMBLY	Material		3	Dec 16, 2020	SYSTEM	\$60.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user petrid1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					3	Dec 16, 2020	SYSTEM	(\$60.00)	
					4	Jan 4, 2021	SYSTEM	\$60.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user petrid1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					4	Jan 4, 2021	SYSTEM	(\$60.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0230 -	Total						\$0.00	
	0240	CHANNELIZER (TRIM LINE)	Material		3	Dec 16, 2020	SYSTEM	\$585.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user petrid1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					3	Dec 16, 2020	SYSTEM	(\$585.00)	
					4	Jan 4, 2021	SYSTEM	\$585.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user petrid1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					4	Jan 4, 2021	SYSTEM	(\$585.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0240 -	Total						\$0.00	
	0250	TYPE III MOVEABLE BARRICADE	Material		3	Dec 16, 2020	SYSTEM	\$690.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user petrid1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					3	Dec 16, 2020	SYSTEM	(\$690.00)	
					4	Jan 4, 2021	SYSTEM	\$690.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user petrid1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					4	Jan 4, 2021	SYSTEM	(\$690.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0250 -	Total							
	0260	TYPE III MOVEABLE BARRICADE WITH	Material		3	Dec 16, 2020	SYSTEM	\$810.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user petrid1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
		LIGHTS			3	Dec 16, 2020	SYSTEM	(\$810.00)	
					4	Jan 4, 2021	SYSTEM	\$810.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user petrid1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					4	Jan 4, 2021	SYSTEM	(\$810.00)	
				- Total				\$0.00	
			Material - Te	otal				\$0.00	
	0260 -	Total						\$0.00	
	0270	CMS W/O COMMUNICATION INTERFACE,	Material		2	Dec 1, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user petrid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
3063	0270	CONT F/	Material		2	Dec 1, 2020	SYSTEM	(\$7,000.00)	
					3	Dec 16, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user petrid1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					3	Dec 16, 2020	SYSTEM	(\$7,000.00)	
					4	Jan 4, 2021	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user petrid1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					4	Jan 4, 2021	SYSTEM	(\$7,000.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0270 -	Total						\$0.00	
	0290	CONCRETE TRAFFIC BARRIER, TYPE D (RETAINING	Material		9	Mar 16, 2021	SYSTEM	\$8,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user petrid1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
		(RETAINING WALL)			9	Mar 16, 2021	SYSTEM	(\$8,500.00)	
					10	Apr 1, 2021	SYSTEM	\$8,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user petrid1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					10	Apr 1, 2021	SYSTEM	(\$8,500.00)	
					11	Apr 16, 2021	SYSTEM	\$8,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user petrid1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					11	Apr 16, 2021	SYSTEM	(\$8,500.00)	
					12	May 3, 2021	SYSTEM	\$8,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user petrid1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					12	May 3, 2021	SYSTEM	(\$8,500.00)	
					13	May 17, 2021	SYSTEM	\$8,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user philpd1 overridding Paymen Estimate Exception 4 on the current Payment Estimate.
					13	May 17, 2021	SYSTEM	(\$8,500.00)	
				- Total				\$0.00	
			Material - Te	Total				\$0.00	
	0290 -	Total						\$0.00	
	0300	TEMPORARY TRAFFIC BARRIER, CONT. FURN/RE	Material		3	Dec 16, 2020	SYSTEM	\$5,700.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user petrid1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					3	Dec 16, 2020	SYSTEM	(\$5,700.00)	
						4	Jan 4, 2021	SYSTEM	\$5,700.00
					4	Jan 4, 2021	SYSTEM	(\$5,700.00)	
					5	Jan 19, 2021	SYSTEM	\$6,175.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user petrid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	Jan 19, 2021	SYSTEM	(\$6,175.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0300 -	Total						\$0.00	
	0333	TEMPORARY REMOVABLE MARKING TAPE 4 IN.,	Material		3	Dec 16, 2020	SYSTEM	\$633.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user petrid1 overridding Payment Estimate Exception 10 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
J9S3063	0333	TEMPORARY REMOVABLE	Material	Туре	3	Dec 16, 2020	SYSTEM	(\$633.75)	
		MARKING TAPE 4			4	Jan 4, 2021	SYSTEM	\$633.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user petrid1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					4	Jan 4,	SYSTEM	(\$633.75)	Estimate Exception to on the current rayment Estimate.
				- Total		2021		\$0.00	
			Material - To					\$0.00	
	0333 -	333 - Total						\$0.00	
	0334	TEMPORARY REMOVABLE MARKING TAPE	Material		3	Dec 16, 2020	SYSTEM	\$957.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user petrid1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					3	Dec 16, 2020	SYSTEM	(\$957.50)	
					4	Jan 4, 2021	SYSTEM	\$957.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user petrid1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					4	Jan 4, 2021	SYSTEM	(\$957.50)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0334 -	Total						\$0.00	
	0335	TEMPORARY REMOVABLE MARKING TAPE	Material	/aterial	3	Dec 16, 2020	SYSTEM	\$41.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user petrid1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					3	Dec 16, 2020	SYSTEM	(\$41.25)	
					4	Jan 4, 2021	SYSTEM	\$41.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user petrid1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					4	Jan 4, 2021	SYSTEM	(\$41.25)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0335 -	0335 - Total						\$0.00	
	0390	ROCK DITCH CHECK	Material	<i>A</i> aterial	4	Jan 4, 2021	SYSTEM	\$216.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user petrid1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					4	Jan 4, 2021	SYSTEM	(\$216.00)	
					5	Jan 19, 2021	SYSTEM	\$216.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user petrid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					5	Jan 19, 2021	SYSTEM	(\$216.00)	
					6	Feb 2, 2021	SYSTEM	\$216.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user petrid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Feb 2, 2021	SYSTEM	(\$216.00)	
					7	Feb 16, 2021	SYSTEM	\$216.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user petrid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Feb 16, 2021	SYSTEM	(\$216.00)	
					8	Mar 2, 2021	SYSTEM	\$216.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user petrid1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					8	Mar 2, 2021	SYSTEM	(\$216.00)	
					9	Mar 16, 2021	SYSTEM	\$216.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user petrid1 overridding Payment Estimate Exception 20 on the current Payment Estimate.



May 18, 2021

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9S3063	0390	ROCK DITCH CHECK	Material		9	Mar 16, 2021	SYSTEM	(\$216.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0390 -	Total						\$0.00	
	0410	SILT FENCE	Material		5	Jan 19, 2021	SYSTEM	\$495.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user petrid1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					5	Jan 19, 2021	SYSTEM	(\$495.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0410 -	Total						\$0.00	
	0430	GEOSYNTHETIC REINFORCED SOIL SLOPE SYS.	Material		4	Jan 4, 2021	SYSTEM	\$45,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user petrid1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					4	Jan 4, 2021	SYSTEM	(\$45,000.00)	
					5	Jan 19, 2021	SYSTEM	\$45,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user petrid1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					5	Jan 19, 2021	SYSTEM	(\$45,000.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0430 -	Total						\$0.00	
	0540	GALVANIZED CIP CONCR PILES (14 IN)	Material		8	Mar 2, 2021	SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user petrid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					8	Mar 2, 2021	SYSTEM	(\$6,000.00)	
					9	Mar 16, 2021	SYSTEM	\$38,175.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user petrid1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					9	Mar 16, 2021	SYSTEM	(\$38,175.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0540 - 0550	- Total GALVANIZED CIP CONCR PILES (16 IN)	Material		13	May 17, 2021	SYSTEM	\$0.00 \$307,530.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user philpd1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					13	May 17, 2021	SYSTEM	(\$307,530.00)	
				- Total			\$0.00		
			Material - To					\$0.00	
	05 <u>50</u> -	Total						\$0.00	
	0570	CLASS B CONCRETE (SUBSTRUCTURE)	Material		9	Mar 16, 2021	SYSTEM	\$19,465.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user petrid1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					9	Mar 16, 2021	SYSTEM	(\$19,465.00)	
					13	May 17, 2021	SYSTEM	\$36,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user philpd1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					13	May 17, 2021	SYSTEM	(\$36,550.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0570 -	Total						\$0.00	
	0610	REINFORCING	Material		13	May 17,	SYSTEM	\$36,006.25	This adjustment offsets the original system-generated Material Payment



May 18, 2021

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9S3063	0610	STEEL (BRIDGES)	Material			2021			Estimate Item Adjustment (0003) due to user philpd1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					13	May 17, 2021	SYSTEM	(\$36,006.25)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0610 - Total								
J9S3063 - Total									
Overall -	Overall - Total								