ramses1



May 18, 2021

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: May 17, 2021

Progress Estimate Number 8		Contract ID Prime Contractor	200918-C02 Magruder Paving, LLC	Pay Period Start Pay Period End		Original Contract Amount Net Change Order Amount Current Contract Amount	\$2,681,859.59 (\$18,693.75) \$2,663,165.84			
Approval Date							By User			
May 17, 2021		Generated and Approved (and should be considered Draft) at the Project Office Level by								
May 17, 2021		Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by								

Ori	ginal Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
	December 1, 2021	November 1, 2021		41.09%

Reviewed and Approved at the Central Office Controllers Office Level by

Contract Informational Dat	Milestones	
Original Completion Date	Current Completion Date	No Milestones Exist for Contract
October 7, 2020	October 7, 2020	
September 18, 2020	September 18, 2020	
December 7, 2020	December 7, 2020	
	Original Completion Date October 7, 2020 September 18, 2020	September 18, 2020 September 18, 2020

Contract Total Pa	ay For Estimate No. 8			
		This Estimate	Previous	To Date
200918-C02				
	Total Posted Items Pay	\$73,631.57	\$1,020,566.86	\$1,094,198.43
	Gross Item Adjustments	\$0.00	\$797.40	\$797.40
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	•		\$1,021,364.26	\$1,094,995.83
Contract Total Pa	avable This Estimate:	\$73 631 57		

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount	
J3S3137	0070	2071000	LINEAR GRADING CLASS 1	STA	\$575.000	0.5	\$287.50	
	0170	6081000	CONCRETE MEDIAN	SQYD	\$115.280	104.2	\$12,012.18	
	0230	6086004	CONCRETE SIDEWALK, 4 IN.	SQYD	\$50.850	18.1	\$920.39	
	0620	8061006	ALTERNATE DITCH CHECK	LF	\$8.750	890	\$7,787.5	
	1040	2063300	CLASS 4 EXCAVATION	CUYD	\$110.000	4	\$440.0	
	1060	2163501	PARTIAL REMOVAL OF CULVERT-BRIDGE CONCRETE	LS	\$4,900.000	1	\$4,900.0	
	1070	7034040	CLASS B-1 CONCRETE (CULVERTS-BRIDGE)	CUYD	\$1,625.000	24	\$39,000.0	
	1080	7061020	REINFORCING STEEL (CULVERTS-BRIDGE)	LB	\$2.000	4,142	\$8,284.0	
Project J3S3137 - Total								
Overall - Tota							\$73,631,5	

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item	Adjustı	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J3S3137	0800	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material			-1,560.5	\$12.75	(\$19,896.38)
	0800	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item	1,560.5	\$12.75	\$19,896.38

Revision 4/1/2020 Page 1 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: May 17, 2021

Progress Estimate Number
8
Contract ID 200918-C02 Pay Period Start May 2, 2021 Original Contract Amount (\$18,693.75)
Pay Period End May 15, 2021 Original Contract Amount (\$18,693.75)
Current Contract Amount Current Contract Amount (\$18,693.75)

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J3S3137					Adjustment (0002) due to user mothee overridding Payment Estimate Exception 1 on the current Payment Estimate.			
	0860	CABLE, 16 AWG 2 CONDUCTOR	Material			-1,180	\$1.75	(\$2,065.00
	0860	CABLE, 16 AWG 2 CONDUCTOR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user mothee overridding Payment Estimate Exception 6 on the current Payment Estimate.	1,180	\$1.75	\$2,065.00
	0870	CABLE, 16 AWG 5 CONDUCTOR	Material			-1,190	\$2.00	(\$2,380.00)
	0870	CABLE, 16 AWG 5 CONDUCTOR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user mothee overridding Payment Estimate Exception 7 on the current Payment Estimate.	1,190	\$2.00	\$2,380.00
	0920	BASE, CONCRETE	Material			-4.9	\$1,140.00	(\$5,586.00
	0920	BASE, CONCRETE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user mothee overridding Payment Estimate Exception 8 on the current Payment Estimate.	4.9	\$1,140.00	\$5,586.00
	1070	CLASS B-1 CONCRETE (CULVERTS-BRIDGE)	Material			-24	\$1,625.00	(\$39,000.00
	1070	CLASS B-1 CONCRETE (CULVERTS-BRIDGE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user mothee overridding Payment Estimate Exception 2 on the current Payment Estimate.	24	\$1,625.00	\$39,000.00
otal								\$0.00

Revision 4/1/2020 Page 2 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

	Contract Project Information										
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work						
J3S3137	FAS S302(15)	Resurface and add shoulders	Y	PETTIS	from Quisenberry Road to Route 65						

als by Job Numbers									
3S3137	This Estimate	Previous	To Date						
Posted Item Pay Gross Item Adjustments	\$73,631.57 \$0.00	\$1,020,566.86 \$797.40	\$1,094,198.43 \$797.40						
Gross Item Pay	\$73,631.57	\$1,021,364.26	\$1,094,995.83						
Incentive	\$0.00	\$0.00	\$0.00						
Disincentive	\$0.00	\$0.00	\$0.00						
Liquidated Damages	\$0.00	\$0.00	\$0.00						
Other Contract Adjustments	\$0.00	\$0.00	\$0.00						

Revision 4/1/2020 Page 3 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J3S3137, Item 3040504, Project Item Line Number 0080, Material Set 304050496, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Working with contractor and KC District Materials to resolve.	mothee	Overridden
Estimate Exception Type: Insufficient Materials: Project J3S3137, Item 7034040, Project Item Line Number 1070, Material Set 703404096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	All required testing has been performed. Waiting on results to be entered into AASHTOWARE.	mothee	Overridden
Estimate Exception Type: Insufficient Materials: Project J3S3137, Item 7034040, Project Item Line Number 1070, Material Set 703404096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	All required testing has been performed. Waiting on results to be entered into AASHTOWARE.	mothee	Overridden
Estimate Exception Type: Insufficient Materials: Project J3S3137, Item 7034040, Project Item Line Number 1070, Material Set 703404096, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	All required testing has been performed. Waiting on results to be entered into AASHTOWARE.	mothee	Overridden
Estimate Exception Type: Insufficient Materials: Project J3S3137, Item 7034040, Project Item Line Number 1070, Material Set 703404096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	All required testing has been performed. Waiting on results to be entered into AASHTOWARE.	mothee	Overridden
Estimate Exception Type: Insufficient Materials: Project J3S3137, Item 9028308, Project Item Line Number 0860, Material Set 902830896, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Materials have been approved for use by KC District Traffic. Working with contractor and KC District Materials to get certifications entered into AASHTOWARE.	mothee	Overridden
Estimate Exception Type: Insufficient Materials: Project J3S3137, Item 9028310, Project Item Line Number 0870, Material Set 902831096, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Materials have been approved for use by KC District Traffic. Working with contractor and KC District Materials to get certifications entered into AASHTOWARE.	mothee	Overridden
Estimate Exception Type: Insufficient Materials: Project J3S3137, Item 9029100, Project Item Line Number 0920, Material Set 902910096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	All required testing has been performed. Waiting on results to be entered into AASHTOWARE.	mothee	Overridden

Revision 4/1/2020 Page 4 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	eport Generated date and can differ from the posted am Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200918-C02	J3S3137	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.40	\$38,500.00	\$15,400.00
		0001	0020	2031000	CLASS A EXCAVATION	1,971.00	0.00	1,971.00	CUYD	0.00	\$18.06	\$0.00
		0001	0030	2035500	EMBANKMENT IN PLACE	47.00	0.00	47.00	CUYD	0.00	\$114.01	\$0.00
		0001	0040	2036000	COMPACTING EMBANKMENT	1,643.00	0.00	1,643.00	CUYD	0.00	\$1.80	\$0.00
		0001	0050	2063000	CLASS 3 EXCAVATION	6.00	0.00	6.00	CUYD	6.00	\$60.00	\$360.00
		0001	0060	2063500	CULVERT CLEANOUT	29.00	0.00	29.00	EA	0.00	\$2,500.00	\$0.00
		0001	0070	2071000	LINEAR GRADING CLASS 1	114.10	0.00	114.10	STA	104.18	\$575.00	\$59,903.50
		0001	0080	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	2,189.00	0.00	2,189.00	SQYD	1,560.50	\$12.75	\$19,896.38
		0001	0090	3049910	MISC.TYPE 1 AGGREGATE FOR BASE (2 IN. THICK)	22.80	0.00	22.80	TONS	0.00	\$187.91	\$0.00
		0001	0100	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	23.00	0.00	23.00	TONS	0.00	\$212.98	\$0.00
		0001	0110	4013000	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	1,430.10	0.00	1,430.10	TONS	0.00	\$84.34	\$0.00
		0001	0120	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE	1,909.00	0.00	1,909.00	TONS	0.00	\$86.61	\$0.00
		0001	0130	4030101	ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP125C MIX)	3,791.00	0.00	3,791.00	TONS	0.00	\$89.95	\$0.00
		0001	0140	4071005	TACK COAT	6,435.00	0.00	6,435.00	GAL	0.00	\$2.75	\$0.00
		0001	0150	6042010	ADJUSTING MANHOLE	9.00	0.00	9.00	EA	7.00	\$400.00	\$2,800.00
			0160	6044011	PIPE COLLAR, TYPE A	3.00	0.00	3.00	EA	0.00	\$1,275.00	\$0.00
	0001	0170	6081000	CONCRETE MEDIAN	197.40	0.00	197.40	SQYD	149.80	\$115.28	\$17,268.94	
		0001	0180	6081010	CONCRETE CURB RAMP	777.90	0.00	777.90	SQYD	658.60	\$125.10	\$82,390.86
		0001	0190	6081012	TRUNCATED DOMES	1,083.00	0.00	1,083.00	SQFT	758.40	\$32.50	\$24,648.00
		0001 0	0200	6084023	SIDEWALK HAND-RAILING WITHOUT BALUSTERS	640.00	0.00	640.00	LF	0.00	\$95.00	\$0.00
			0210	6085007	PAVED APPROACH, 7 IN.	78.70	0.00	78.70	SQYD	53.50	\$62.00	\$3,317.00
			0220	6085008	PAVED APPROACH, 8 IN.	1,872.60	0.00	1,872.60	SQYD	1,507.00	\$65.00	\$97,955.00
		0001	0230	6086004	CONCRETE SIDEWALK, 4 IN.	6,392.20	0.00	6,392.20	SQYD	5,922.10	\$50.85	\$301,138.78
		0001										
		0001	0240	6091010	CONCRETE CUTTER TYPE A	177.00	0.00	177.00	LF	118.80	\$41.50	\$4,930.20
		0001	0250	6091041	CONCRETE GUTTER TYPE A	22.00	0.00	22.00	LF	0.00	\$28.95	\$0.00
		0001	0260	6091051	CURB AND GUTTER TYPE A	248.00	0.00	248.00	LF	237.00	\$36.75	\$8,709.75
		0001	0270	6091052	CURB AND GUTTER TYPE B	83.00	0.00	83.00	LF	13.00	\$40.00	\$520.00
		0001	0280	6091060	PAVED DITCH	24.00	0.00	24.00	SQYD	0.00	\$95.00	\$0.00
		0001	0290	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	459.00	0.00	459.00	LF	0.00	\$21.50	\$0.00
		0001	0300	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	13.00	0.00	13.00	CUYD	13.00	\$29.75	\$386.75
		0001	0310	6096020	FURNISHING TYPE 2 ROCK DITCH LINER	8.00	0.00	8.00	CUYD	8.00	\$35.10	\$280.80
		0001	0320	6096041	PLACING TYPE 1 ROCK DITCH LINER	13.00	0.00	13.00	CUYD	13.00	\$29.75	\$386.75
		0001	0330	6096042	PLACING TYPE 2 ROCK DITCH LINER	8.00	0.00	8.00	CUYD	8.00	\$28.00	\$224.00
		0001	0340	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$3,000.00	\$0.00
		0001	0350	6143012	MANHOLE FRAME AND COVER, TYPE 2	6.00	0.00	6.00	EA	6.00	\$525.00	\$3,150.00
		0001	0360	6161005	CONSTRUCTION SIGNS	1,649.00	0.00	1,649.00	SQFT	680.00	\$7.00	\$4,760.00
		0001	0370	6161009	FLAG ASSEMBLY	8.00	0.00	8.00	EA	8.00	\$30.00	\$240.00
		0001	0380	6161025	CHANNELIZER (TRIM LINE)	235.00	0.00	235.00	EA	150.00	\$15.00	\$2,250.00
		0001	0390	6161031	TYPE III MOVEABLE BARRICADE WITH LIGHTS	11.00	0.00	11.00	EA	0.00	\$200.00	\$0.00
		0001	0400	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	2.00	\$1,000.00	\$2,000.00
		0001	0410	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	6.00	0.00	6.00	EA	4.00	\$4,500.00	\$18,000.00
		0001	0420	6169902	MISC.ADA COMPLIANT BARRICADE	8.00	0.00	8.00	EA	8.00	\$110.00	\$880.00
		0001	0430	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.75	\$430,150.00	\$322,612.50
		0001	0440	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	4.00	0.00	4.00	EA	0.00	\$600.00	\$0.00
		0001	0450	6191000	PAVEMENT EDGE TREATMENT	19,927.00	0.00	19,927.00	LF	0.00	\$0.01	\$0.00

Page 5 of 14 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	eport Generated date and can differ from the posted am Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200918-C02	J3S3137	0001	0460	6200009	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE	649.00	0.00	649.00	LF	0.00	\$4.50	\$0.00
		0001	0470	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	183.00	0.00	183.00	LF	0.00	\$22.00	\$0.00
		0001	0480	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	28.00	0.00	28.00	EA	0.00	\$210.00	\$0.00
		0001	0490	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	76.00	0.00	76.00	EA	0.00	\$150.00	\$0.00
		0001	0500	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	25,081.00	0.00	25,081.00	LF	0.00	\$0.15	\$0.00
		0001	0510	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	25,065.00	0.00	25,065.00	LF	0.00	\$0.15	\$0.00
		0001	0520	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	39,477.00	0.00	39,477.00	SQYD	0.00	\$1.70	\$0.00
		0001	0530	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	1,060.00	0.00	1,060.00	SQYD	0.00	\$11.49	\$0.00
			0540	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.40	\$7,500.00	\$3,000.00
			0550	7261015	15 IN. PIPE GROUP A	4.00	0.00	4.00	LF	4.00	\$200.00	\$800.00
		0001	0560	7261024	24 IN. PIPE GROUP A	4.00	0.00	4.00	LF	4.00	\$205.00	\$820.00
		0001	0570	7261036	36 IN. PIPE GROUP A	6.00	0.00	6.00	LF	0.00	\$235.00	\$0.00
		0001	0580	7320615A	15 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	1.00	0.00	1.00	EA	1.00	\$235.00	\$235.00
		0001	0590	7320636A	36 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	1.00	0.00	1.00	EA	0.00	\$775.00	\$0.00
	0001 0001		0600	8051000A	SEEDING - COOL SEASON MIXTURES	6.30	0.00	6.30	ACRE	0.00	\$1,800.00	\$0.00
			0610	8061005	ROCK DITCH CHECK	49.00	0.00	49.00	LF	0.00	\$15.50	\$0.00
		0001	0620	8061006	ALTERNATE DITCH CHECK	6,338.00	0.00	6,338.00	LF	930.00	\$8.75	\$8,137.50
		0001 0630	0630	8061007A	CURB INLET CHECK	40.00	0.00	40.00	EA	25.00	\$130.00	\$3,250.00
		0001	0640	8061016	SEDIMENT REMOVAL	1,068.00	0.00	1,068.00	CUYD	0.00	\$1.00	\$0.00
		0001	0650	8061019	SILT FENCE	9,060.00	0.00	9,060.00	LF	0.00	\$2.15	\$0.00
		0001	0660	8064128	TYPE 1 TURF REINFORCEMENT MAT	5,545.00	0.00	5,545.00	SQYD	0.00	\$2.90	\$0.00
		0001	0670	8064129	TYPE 2 TURF REINFORCEMENT MAT	5,504.00	0.00	5,504.00	SQYD	0.00	\$3.10	\$0.00
		0001	0680	8064133	TYPE 1C EROSION CONTROL BLANKET	17,054.00	0.00	17,054.00	SQYD	0.00	\$1.90	\$0.00
		0020	0690	9011030	LIGHTING POLE, 30 FT. OR 9.0 M, TYPE AT	1.00	0.00	1.00	EA	0.00	\$3,525.00	\$0.00
		0020	0700	9011106	BRACKET ARM, 6 FT. OR 1.8 M	1.00	0.00	1.00	EA	0.00	\$340.00	\$0.00
		0020	0710	9011110	BRACKET ARM, 10 FT. OR 3.0 M	1.00	0.00	1.00	EA	0.00	\$875.00	\$0.00
		0020	0720	9011112	BRACKET ARM, 12 FT. OR 3.6 M	2.00	0.00	2.00	EA	0.00	\$915.00	\$0.00
		0020	0730	9011311	LUMINAIRE, LED-A	4.00	0.00	4.00	EA	0.00	\$775.00	\$0.00
		0020	0740	9015010	TRENCHING TYPE I	11.00	0.00	11.00	LF	0.00	\$12.00	\$0.00
		0020	0750	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	90.00	0.00	90.00	LF	0.00	\$1.50	\$0.00
		0020	0760	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	30.00	0.00	30.00	LF	0.00	\$4.25	\$0.00
		0020	0770	9018230	POLE FOUNDATION (30 FT. OR 9.0 M MOUNTING HEIGHT)	1.00	0.00	1.00	EA	0.00	\$1,220.00	\$0.00
		0030	0780	9020414	SIGNAL HEAD, TYPE 4C	4.00	0.00	4.00	EA	0.00	\$2,860.00	\$0.00
		0030	0790	9020811	SIGNAL HEAD, TYPE 1S, PEDESTRIAN	8.00	0.00	8.00	EA	0.00	\$525.00	\$0.00
		0030	0800	9020833	SH-FLAT SHEET - SIGNAL SIGN	38.00	0.00	38.00	SQFT	0.00	\$29.50	\$0.00
		0030	0810	9020834	SIGNAL SIGN, MOUNTING HARDWARE	12.00	0.00	12.00	EA	0.00	\$270.00	\$0.00
		0030	0820	9022708	POST, SIGNAL 8 FT. OR 2.4 M	8.00	0.00	8.00	EA	0.00	\$1,415.00	\$0.00
		0030	0830	9024944	DETECTOR, VEHICLE INDUCTION LOOP (2 CHANNEL - RACK MOUNTED)	10.00	0.00	10.00	EA	0.00	\$245.00	\$0.00
		0030	0840	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	9.00	0.00	9.00	LF	9.00	\$22.00	\$198.00
		0030	0850	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	298.00	0.00	298.00	LF	298.00	\$31.00	\$9,238.00
		0030	0860	9028308	CABLE, 16 AWG 2 CONDUCTOR	1,180.00	0.00	1,180.00	LF	1,180.00	\$1.75	\$2,065.00
		0030	0870	9028310	CABLE, 16 AWG 5 CONDUCTOR	1,190.00	0.00	1,190.00	LF	1,190.00	\$2.00	\$2,380.00
		0030	0880	9028311	CABLE, 16 AWG 7 CONDUCTOR	110.00	0.00	110.00	LF	0.00	\$2.50	\$0.00
		0030	0890	9028500	CABLE, LOOP DETECTOR, IN DUCT	3,030.00	0.00	3,030.00	LF	0.00	\$6.75	\$0.00

Page 6 of 14 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Im.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
00918-C02	J3S3137	0030	0900	9028811	PULL BOX, PREFORMED CLASS 2	4.00	0.00	4.00	EA	4.00	\$1,400.00	\$5,600.00
		0030	0910	9028812	PULL BOX, PREFORMED CLASS 3	1.00	0.00	1.00	EA	1.00	\$1,750.00	\$1,750.00
		0030	0920	9029100	BASE, CONCRETE	4.90	0.00	4.90	CUYD	4.90	\$1,140.00	\$5,586.00
		0030	0930	9029902	MISC.ACCESSIBLE PEDESTRIAN SIGNALS (PUSHBUTTONS)	8.00	0.00	8.00	EA	0.00	\$1,650.00	\$0.00
		0030	0940	9029902	MISC.GREEN SIGNAL HEAD LENS INSTALL	1.00	0.00	1.00	EA	0.00	\$275.00	\$0.00
		0040	0950	9031010	CONCRETE FOOTINGS, EMBEDDED	1.30	0.00	1.30	CUYD	0.00	\$1,800.00	\$0.00
		0040	0960	9031220	PIPE POSTS	940.00	0.00	940.00	LB	0.00	\$4.00	\$0.00
		0040	0970	9031270A	2 IN. PSST POST - 12 GA.	60.00	0.00	60.00	LF	0.00	\$15.00	\$0.00
		0040	0980	9031279	OMNIDIRECTIONAL POST ANCHOR FOR 2 IN. PSST - 7 GA.	15.00	0.00	15.00	LF	0.00	\$50.00	\$0.00
		0040	0990	9031280	2.5 IN. PSST POST - 12 GA.	13.00	0.00	13.00	LF	0.00	\$16.00	\$0.00
		0040	1000	9031282	OMNIDIRECTIONAL POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	3.00	0.00	3.00	LF	0.00	\$60.00	\$0.00
		0040	1010	9035004A	SH-FLAT SHEET	28.00	0.00	28.00	SQFT	0.00	\$20.00	\$0.00
	0040 1020 9035				SHF-FLAT SHEET FLUORESCENT	96.00	0.00	96.00	SQFT	0.00	\$25.00	\$0.00
		0040	1030	9039902	MISC.RELOCATE EXISTING SIGNS TO NEW POSTS	3.00	0.00	3.00	EA	0.00	\$175.00	\$0.00
		0070	1040	2063300	CLASS 4 EXCAVATION	10.00	-6.00	4.00	CUYD	4.00	\$110.00	\$440.00
		0070	1050	2065500	TEMPORARY SHORING	1.00	-1.00	0.00	LS	0.00	\$4,200.00	\$0.00
		0070	1060	2163501	PARTIAL REMOVAL OF CULVERT-BRIDGE CONCRETE	1.00	0.00	1.00	LS	1.00	\$4,900.00	\$4,900.00
		0070	1070	7034040	CLASS B-1 CONCRETE (CULVERTS-BRIDGE)	46.80	-4.00	42.80	CUYD	26.00	\$1,625.00	\$42,250.00
		0070	1080	7061020	REINFORCING STEEL (CULVERTS-BRIDGE)	6,820.00	-200.00	6,620.00	LB	4,142.00	\$2.00	\$8,284.00
		0071	1090	2063300	CLASS 4 EXCAVATION	10.00	-4.00	6.00	CUYD	6.00	\$110.00	\$660.00
		0071	1100	2065500	TEMPORARY SHORING	1.00	-1.00	0.00	LS	0.00	\$4,200.00	\$0.00
		0071	1110	2163501	PARTIAL REMOVAL OF CULVERT-BRIDGE CONCRETE	1.00	0.00	1.00	LS	1.00	\$4,900.00	\$4,900.00
		0071	1120	7034040	CLASS B-1 CONCRETE (CULVERTS-BRIDGE)	36.60	-5.00	31.60	CUYD	0.00	\$1,625.00	\$0.00
		0071	1130	7061020	REINFORCING STEEL (CULVERTS-BRIDGE)	6,140.00	-200.00	5,940.00	LB	0.00	\$2.00	\$0.00
		0070	5001	1046002	VALUE ENGINEERING	0.00	6,231.25	6,231.25	EA	0.00	\$1.00	\$0.00
	Project J	3S3137 - To	otal Value	Posted to D	ate as of Report Generated Date							\$1,098,902.71
0918-C02 Ove	rall - Total	Value Post	ed to Da	te as of Repo	ort Generated Date							\$1,098,902.71

Page 7 of 14 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J3S3137

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0070	70 2071000 LINEAR GRADING CLASS 1		5/13/21	5/13/21	0.10	STA	SE island at Thompson Blvd.	421+41 Rt		421+47 Rt		
				5/13/21	0.10	STA	SW island at Thompson Blvd.	420+93 Rt		421+00 Rt		
			5/14/21	5/14/21	0.10	STA	NE island at Thompson Blvd.	421+37 Lt		421+49 Lt		
				5/14/21	0.20	STA	NE island at Thompson Blvd.	420+76 Lt		420+97 Lt		
0170	6081000	CONCRETE MEDIAN	5/13/21	5/13/21	10.60	SQYD	SE island at Thompson Blvd.	421+41 Rt		421+47 Rt		
				5/13/21	14.00	SQYD	SW island at Thompson Blvd.	420+93 Rt		421+00 Rt		
			5/14/21	5/14/21	22.80	SQYD	NE island at Thompson Blvd.	421+37 Lt		421+49 Lt		
				5/14/21	56.80	SQYD	NW island at Thompson Blvd.	420+76 Lt		420+97 Lt		
0230	230 6086004 CONCRETE SIDEWALK, 4 IN.		5/14/21	5/14/21	8.70	SQYD	SE cut-thru at Thompson Blvd.	421+41 Rt		421+47 Rt		
				5/14/21	9.40	SQYD	SW cut-thru at Thompson Blvd.	420+93 Rt		421+00 Rt		
0620	8061006	ALTERNATE DITCH CHECK	5/10/21	5/10/21	890.00	LF	Route Y Left side Water Tower to Winchester (3) = 30' Winchester to Fairway Dr. (8) = 80' Fairway Dr. to N. Hedge Apple (4) = 40' Fairway Dr. to N. Hedge Apple to W. Country Club Dr. (6) = 60' West Country Club Dr. to Shady LN. (5) = 50' West Country Club Dr. to Shady LN. (5) = 50' Water Country Club Dr. to Shady LN. to Timber Ridge (15) = 150' Timber Ridge (15) = 150' Timber Ridge (15) = 150' Country Kilde Water Shady LN. (6) = 60' Willow Dr. (6) = 60' Willow Dr. to Country Club Entrance (7) = 70' Countr	292+00		400+00		
1040	2063300	CLASS 4 EXCAVATION	5/13/21	5/13/21	4.00	CUYD	Box Extension L05221	305+20				
1060	2163501	PARTIAL REMOVAL OF CULVERT-BRIDGE CONCRE	5/13/21	5/13/21	1.00	LS	Box Extension L05221	305+20 Lt & Rt				
1070	7034040	CLASS B-1 CONCRETE (CULVERTS-BRIDGE)	5/13/21	5/13/21	12.00	CUYD	L05221 box extension Rt	305+20 Rt				
			5/14/21	5/14/21	12.00	CUYD	L05221 box extension downstream	305+20 Lt				
1080	7061020	REINFORCING STEEL (CULVERTS-BRIDGE)	5/13/21	5/13/21	2,121.00	LB	L05221 box extension Rt w/Headwall	305+20 Rt				
			5/14/21	5/14/21	2,021.00	LB	L05221 box extension downstream	305+20 Lt				

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 4/1/2020 Page 8 of 14



Type Adjustment Number Date By Type										
1317 2009	Project	Line	Description		Adjustment				Amount	Remarks
Aur 16, SYSTEM \$9,812.40	S3137	0080	AGGREGATE	Material	.,,,,	3		SYSTEM	\$5,617.65	Estimate Item Adjustment (0003) due to user mothee overridding Payment
Estimate Item Adjustment (D00) due to user mother overridding Payment Estimate Exception 1 on the current Payment Estimate Payment Payment Estimate Exception 1 on the current Payment Estimate Exception 2 on the current Payment Estimate Exce						3		SYSTEM	(\$5,617.65)	
2021 5						4		SYSTEM	\$9,812.40	Estimate Item Adjustment (0005) due to user mothee overridding Payment
2021 Estimate Isom Adjustment (0007) due to user mothee overaiding Payment Estimate.						4		SYSTEM	(\$9,812.40)	
Concept						5		SYSTEM	\$19,896.38	Estimate Item Adjustment (0007) due to user mothee overridding Payment
2021 Estimate tem Aglustment (0004) oue to user mothee overridding Payment Estimate						5		SYSTEM	(\$19,896.38)	
2021 7						6		SYSTEM	\$19,896.38	Estimate Item Adjustment (0004) due to user mothee overridding Payment
2021 Estimate Item Adjustment (1000) quie to user mothee overridding Payment						6		SYSTEM	(\$19,896.38)	
2021 8						7		SYSTEM	\$19,896.38	Estimate Item Adjustment (0004) due to user mothee overridding Payment
2021 SySTEM SyS						7		SYSTEM	(\$19,896.38)	
-Total						8		SYSTEM	\$19,896.38	Estimate Item Adjustment (0002) due to user mothee overridding Payment
Material - Total						8		SYSTEM	(\$19,896.38)	
Price FUEL					- Total				\$0.00	
FUEL				Material - To	rial - Total					
2021						3		SYSTEM	\$27.09	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
1-Total 1-To						4		SYSTEM	\$38.99	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
Price FUEL - Total 080 - Total 0170 CONCRETE MEDIAN Material Material Local - Total - Total 0170 CONCRETE MEDIAN Material - Total - SYSTEM S3,758.13 - This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. - Total - SYSTEM S13,758.13 - This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate Issumate Exception 2 on the current Payment Estimate. - Total - Total - Total - This adjustment offsets the original system-generated Material Payment Estimate Issumate Exception 2 on the current Payment Estimate. - Total						5		SYSTEM	\$93.73	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
Signature Sign					- Total				\$159.81	
CONCRETE Material A mar 16, 2021 SYSTEM \$3,758.13 This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.				Price FUEL	- Total				\$159.81	
O170 CONCRETE MEDIAN Material A Mar 16, 2021 SYSTEM \$3,758.13 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user mothee overridding Payment Estimate Exception 2 on the current Payment Estimate. O170 - Total O180 CONCRETE CURB RAMP Material O180 CONCRETE CURB RAMP Material A Mar 1, SYSTEM (\$16,663.32) A Mar 1, SYSTEM SYST		0080 -	Total						\$159.81	
Total \$0.00			CONCRETE	Material		4		SYSTEM		Estimate Item Adjustment (0006) due to user mothee overridding Payment
Material - Total \$0.00						4		SYSTEM	(\$3,758.13)	
Solution					- Total				\$0.00	
O180 CONCRETE CURB RAMP Material Mar 1, 2021 SYSTEM \$16,663.32 This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. Mar 16, 2021 Mar 16, 2021 Mar 16, 2021 This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate Item Adjustment (0007) due to user mothee overridding Payment Estimate Item Adjustment (0007) due to user mothee overridding Payment Estimate Exception 3 on the current Payment Estimate. - Total Total				Material - To	otal				\$0.00	
O180 CONCRETE CURB RAMP Material Material Material Material Mar 1, 2021 This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. Mar 16, 2021 Mar 16, SYSTEM SYSTEM SYSTEM (\$16,663.32) This adjustment (0004) due to user mothee overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user mothee overridding Payment Estimate Exception 3 on the current Payment Estimate. Mar 16, 2021 SYSTEM		0170 -	Total						\$0.00	
2021 4 Mar 16, 2021 SYSTEM \$33,414.21 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user mothee overridding Payment Estimate Exception 3 on the current Payment Estimate. 4 Mar 16, 2021 SYSTEM (\$33,414.21) - Total \$0.00		0180	CONCRETE	Material		3		SYSTEM	\$16,663.32	Estimate Item Adjustment (0004) due to user mothee overridding Payment
2021 Estimate Item Adjustment (0007) due to user mothee overridding Payment Estimate Exception 3 on the current Payment Estimate. 4 Mar 16, 2021 \$0.00						3		SYSTEM	(\$16,663.32)	
- Total \$0.00						4		SYSTEM	\$33,414.21	Estimate Item Adjustment (0007) due to user mothee overridding Payment
						4		SYSTEM	(\$33,414.21)	
Material - Total \$0.00					- Total				\$0.00	
				Material - To	otal				\$0.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
J3S3137	0180 -	Total						\$0.00			
	0210	PAVED APPROACH, 7 IN.	Material		3	Mar 1, 2021	SYSTEM	\$1,581.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user mothee overridding Payment Estimate Exception 5 on the current Payment Estimate.		
					3	Mar 1, 2021	SYSTEM	(\$1,581.00)			
					4	Mar 16, 2021	SYSTEM	\$1,581.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user mothee overridding Payment Estimate Exception 4 on the current Payment Estimate.		
					4	Mar 16, 2021	SYSTEM	(\$1,581.00)			
				- Total				\$0.00			
			Material - To	otal				\$0.00			
			Price FUEL		3	Mar 1, 2021	SYSTEM	\$5.75	Reference Item Price Adjustment Index Adjustment Type applied is FUEL		
			TOLL		5	Apr 2, 2021	SYSTEM	\$12.17	Reference Item Price Adjustment Index Adjustment Type applied is FUEL		
				- Total				\$17.92			
			Price FUEL					\$17.92			
	0210 -	Total	THE FOLL	Total							
								\$17.92			
	0220	PAVED APPROACH, 8 IN.	Material		3	Mar 1, 2021	SYSTEM	\$26,981.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user mothee overridding Payment Estimate Exception 9 on the current Payment Estimate.		
									3	Mar 1, 2021	SYSTEM
					4	Mar 16, 2021	SYSTEM	\$48,366.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user mothee overridding Payment Estimate Exception 6 on the current Payment Estimate.		
					4	Mar 16, 2021	SYSTEM	(\$48,366.50)			
				- Total				\$0.00			
			Material - To	otal				\$0.00			
			Price FUEL		3	Mar 1, 2021	SYSTEM	\$102.12	Reference Item Price Adjustment Index Adjustment Type applied is FUEL		
					4	Mar 16, 2021	SYSTEM	\$155.94	Reference Item Price Adjustment Index Adjustment Type applied is FUEL		
					5	Apr 2, 2021	SYSTEM	\$361.61	Reference Item Price Adjustment Index Adjustment Type applied is FUEL		
				- Total	- Total			\$619.67			
			Price FUEL	- Total				\$619.67			
	0220 -	Total						\$619.67			
	0230	CONCRETE SIDEWALK, 4 IN.	Material		1	Feb 1, 2021	SYSTEM	\$123,184.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mothee overridding Payment Estimate Exception 1 on the current Payment Estimate.		
					1	Feb 1, 2021	SYSTEM	(\$123,184.12)			
					2	Feb 16, 2021	SYSTEM	\$172,401.84	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mothee overridding Payment Estimate Exception 1 on the current Payment Estimate.		
					2	Feb 16, 2021	SYSTEM	(\$172,401.84)			
					3	Mar 1, 2021	SYSTEM	\$172,401.84	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user mothee overridding Payment Estimate Exception 13 on the current Payment Estimate.		
					3	Mar 1, 2021	SYSTEM	(\$172,401.84)			
					5	Apr 2, 2021	SYSTEM	\$69,916.21	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user mothee overridding Payment Estimate Exception 2 on the current Payment Estimate.		
					5	Apr 2, 2021	SYSTEM	(\$69,916.21)			



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
137	0230	CONCRETE	Material	- Total				\$0.00	
		SIDEWALK, 4 IN.	Material - To	otal				\$0.00	
	0230 -	Total						\$0.00	
	0240	CONCRETE CURB (6 IN. HEIGHT AND	Material		2	Feb 16, 2021	SYSTEM	\$373.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user mothee overridding Payment Estimate Exception 3 on the current Payment Estimate.
		UNDER)			2	Feb 16, 2021	SYSTEM	(\$373.50)	
					3	Mar 1, 2021	SYSTEM	\$373.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user mothee overridding Payment Estimate Exception 14 on the current Payment Estimate.
					3	Mar 1, 2021	SYSTEM	(\$373.50)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0240 -	Total						\$0.00	
	0260	CURB AND GUTTER TYPE A	Material		2	Feb 16, 2021	SYSTEM	\$7,974.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user mothee overridding Payment Estimate Exception 4 on the current Payment Estimate.
					2	Feb 16, 2021	SYSTEM	(\$7,974.75)	
					3	Mar 1, 2021	SYSTEM	\$7,974.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user mothee overridding Payment Estimate Exception 15 on the current Payment Estimate.
					3	Mar 1, 2021	SYSTEM	(\$7,974.75)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0260 -	Total						\$0.00	
	0270	CURB AND GUTTER TYPE B	Material		2	Feb 16, 2021	SYSTEM	\$520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mothee overridding Payment Estimate Exception 5 on the current Payment Estimate.
					2	Feb 16, 2021	SYSTEM	(\$520.00)	
					3	Mar 1, 2021	SYSTEM	\$520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user mothee overridding Payment Estimate Exception 16 on the current Payment Estimate.
					3	Mar 1, 2021	SYSTEM	(\$520.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0270 -	Total						\$0.00	
	0350	MANHOLE FRAME AND COVER.	Material		2	Feb 16, 2021	SYSTEM	\$525.00	This adjustment offsets the original system-generated Material Payment
		COVER,				2021			Estimate Item Adjustment (0005) due to user mothee overridding Payment Estimate Exception 6 on the current Payment Estimate.
					2	Feb 16, 2021	SYSTEM	(\$525.00)	
		COVER,			2	Feb 16,	SYSTEM	(\$525.00) \$525.00	Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment
		COVER,				Feb 16, 2021 Mar 1,		\$525.00 (\$525.00)	Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user mothee overridding Payment
		COVER,		- Total	3	Feb 16, 2021 Mar 1, 2021 Mar 1,	SYSTEM	\$525.00	Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user mothee overridding Payment
		COVER,	Material - To		3	Feb 16, 2021 Mar 1, 2021 Mar 1,	SYSTEM	\$525.00 (\$525.00)	Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user mothee overridding Payment
	0350 -	COVER, TYPE 2	Material - To		3	Feb 16, 2021 Mar 1, 2021 Mar 1,	SYSTEM	\$525.00 (\$525.00) \$0.00	Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user mothee overridding Payment
	0350 - 0620	COVER, TYPE 2	Material - To		3	Feb 16, 2021 Mar 1, 2021 Mar 1,	SYSTEM	\$525.00 (\$525.00) \$0.00 \$0.00	Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user mothee overridding Payment



ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
37	0620	ALTERNATE	Material	- Total				\$0.00	
		DITCH CHECK	Material - To	otal				\$0.00	
	0620 -	Total						\$0.00	
	0630	CURB INLET CHECK	Material		1	Feb 1, 2021	SYSTEM	\$3,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user mothee overridding Payment Estimate Exception 5 on the current Payment Estimate.
					1	Feb 1, 2021	SYSTEM	(\$3,250.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0630 -							\$0.00	
	0840	CONDUIT, 3 IN., TRENCH WITH TRACER	Material		6	Apr 16, 2021	SYSTEM	\$198.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user mothee overridding Payment Estimate Exception 2 on the current Payment Estimate.
		WIRE			6	Apr 16, 2021	SYSTEM	(\$198.00)	
					7	May 3, 2021	SYSTEM	\$198.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user mothee overridding Payment Estimate Exception 2 on the current Payment Estimate.
					7	May 3, 2021	SYSTEM	(\$198.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0840 -	Total						\$0.00	
	0850	CONDUIT, 3 IN., PUSHED WITH TRACER	Material		6	Apr 16, 2021	SYSTEM	\$9,238.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user mothee overridding Payment Estimate Exception 3 on the current Payment Estimate.
		WIRE			6	Apr 16, 2021	SYSTEM	(\$9,238.00)	
					7	May 3, 2021	SYSTEM	\$9,238.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user mothee overridding Payment Estimate Exception 3 on the current Payment Estimate.
					7	May 3, 2021	SYSTEM	(\$9,238.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0850 -	Total						\$0.00	
	0860	CABLE, 16 AWG 2 CONDUCTOR	Material		6	Apr 16, 2021	SYSTEM	\$2,065.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user mothee overridding Payment Estimate Exception 4 on the current Payment Estimate.
					6	Apr 16, 2021	SYSTEM	(\$2,065.00)	
					7	May 3, 2021	SYSTEM	\$2,065.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user mothee overridding Payment Estimate Exception 4 on the current Payment Estimate.
					7	May 3, 2021	SYSTEM	(\$2,065.00)	
					8	May 17, 2021	SYSTEM	\$2,065.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user mothee overridding Paymen Estimate Exception 6 on the current Payment Estimate.
					8	May 17, 2021	SYSTEM	(\$2,065.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0860 -	Total						\$0.00	
	0870	0 CABLE, 16 AWG 5 CONDUCTOR	Material		6	Apr 16, 2021	SYSTEM	\$2,380.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user mothee overridding Payment
									Estimate Exception 5 on the current Payment Estimate.



Type Adjustment Type Date By Type										
CONDITION	roject	Line	Description		Adjustment				Amount	Remarks
B	S3137	0870	AWG 5	Material		7		SYSTEM	\$2,380.00	Estimate Item Adjustment (0008) due to user mothee overridding Payment
Balance Bala						7		SYSTEM	(\$2,380.00)	
Total						8		SYSTEM	\$2,380.00	Estimate Item Adjustment (0004) due to user mothee overridding Payment
Material - Total						8		SYSTEM	(\$2,380.00)	
					- Total				\$0.00	
				Material - To	otal				\$0.00	
Material		0870	Total							
PREFORMED 2021 Estimate tem Adjustment (0001) due to user mothee overridding Payment Estimate Es										
2021 7		0900	PREFORMED	Material						Estimate Item Adjustment (0001) due to user mothee overridding Payment
2021 Estimate [Estimate [Estimate [Estimate Exception 6 on the current Payment Estimate.]						6		SYSTEM	(\$5,600.00)	
2021 \$0.00						7		SYSTEM	\$5,600.00	Estimate Item Adjustment (0001) due to user mothee overridding Payment
Material - Total So.00						7		SYSTEM	(\$5,600.00)	
PULL BX PREFORMED					- Total				\$0.00	
PULL BOX PREFORMED CLASS 3 Material				Material - 1	otal				\$0.00	
PULL BOX PREFORMED CLASS 3 Material		0900 -	Total						\$0.00	
System			PREFORMED	Material		6		SYSTEM		Estimate Item Adjustment (0002) due to user mothee overridding Payment
2021 Estimate Item Adjustment (0002) due to user mothee overridding Payment Estimate Exception 7 on the current Payment Estimate.						6		SYSTEM	(\$1,750.00)	
2021 S0.00						7		SYSTEM	\$1,750.00	Estimate Item Adjustment (0002) due to user mothee overridding Payment
Material - Total S0.00						7		SYSTEM	(\$1,750.00)	
Solid					- Total				\$0.00	
Solid Section Solid Section Solid Section				Mate <u>rial - T</u>	otal				\$0.00	
BASE, CONCRETE Material 6		0910	Total							
2021 7 May 3, 2021 8 May 17, 2021 9 System 9 Syste			BASE,	Material		6		SYSTEM		Estimate Item Adjustment (0003) due to user mothee overridding Payment
Estimate Item Adjustment (0003) due to user mothee overridding Payment Estimate Exception 8 on the current Payment Estimate. 7 May 3, 2021 8 May 17, 2021 9 System (\$5,586.00) 1 This adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate. 9 0.00 9 O - Total 1070 CLASS B-1 CONCRETE (CULVERTS-BRIDGE) 8 May 17, 2021 8 Material - System Say,000.00 System Say,000.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user mothee overridding Payment Estimate Exception 2 on the current Payment Estimate. 8 May 17, 2021						6		SYSTEM	(\$5,586.00)	
2021 8 May 17, 2021 \$5,586.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mothee overridding Payment Estimate Exception 8 on the current Payment Estimate. 8 May 17, 2021 \$0.00						7		SYSTEM	\$5,586.00	Estimate Item Adjustment (0003) due to user mothee overridding Payment
2021 Estimate Item Adjustment (0001) due to user mothee overridding Payment Estimate Exception 8 on the current Payment Estimate. 8						7		SYSTEM	(\$5,586.00)	
- Total \$0.00 Material - Total \$0.00 O920 - Total \$0.00 CLASS B-1 CONCRETE (CULVERTS-BRIDGE) Material \$0.00 System Sys						8		SYSTEM	\$5,586.00	Estimate Item Adjustment (0001) due to user mothee overridding Payment
Material - Total \$0.00 0920 - Total 1070 CLASS B-1 CONCRETE (CULVERTS-BRIDGE) Material - Total \$0.00 System						8		SYSTEM	(\$5,586.00)	
1070 CLASS B-1 CONCRETE (CULVERTS-BRIDGE) 8 May 17, 2021 SYSTEM \$39,000.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user mothee overridding Payment Estimate Exception 2 on the current Payment Estimate.					- Total				\$0.00	
9920 - Total \$0.00 CLASS B-1 CONCRETE (CULVERTS- BRIDGE) \$0.00 Material 8 May 17, 2021 SYSTEM \$39,000.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user mothee overridding Payment Estimate Exception 2 on the current Payment Estimate.				Material - To	otal				\$0.00	
1070 CLASS B-1 CONCRETE (CULVERTS-BRIDGE) 8 May 17, SYSTEM \$39,000.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user mothee overridding Payment Estimate Exception 2 on the current Payment Estimate.		0000	T-4-1	material - 1	- Tail					
CONCRETE (CULVERTS- BRIDGE) CONCRETE 2021 Estimate Item Adjustment (0005) due to user mothee overridding Payment Estimate Exception 2 on the current Payment Estimate.										
8 May 17, SYSTEM (\$39,000.00)		1070	CONCRETE (CULVERTS-	Material		8		SYSTEM	\$39,000.00	Estimate Item Adjustment (0005) due to user mothee overridding Payment
			D. (IDOL)			8	May 17,	SYSTEM	(\$39,000.00)	

May 18, 2021



Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J3S3137		CLASS B-1	Material			2021			
		CONCRETE (CULVERTS- BRIDGE)		- Total				\$0.00	
			Material - To	otal				\$0.00	
	1070 -	Total						\$0.00	
J3S3137	J3S3137 - Total								
Overall -	Overall - Total								