

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: March 16, 2022

April 5, 2021

Final Estimate Num 11			200918-D01 Magruder Paving, LL		Period Start Period End	October 16 March 15,		Original Contract Amount Net Change Order Amount Current Contract Amount	\$2,623,429.22 (\$69,298.84) \$2,554,130.38		
Approval Date									By User		
April 6, 2022			at the Project Office Level by	oeschd1							
April 6, 2022			Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by								
April 7, 2022				Reviewe	d and Approve	d at the Cer	tral Offi	ce Controllers Office Level by	ramses1		
Original Completio	letion Date										
November 1, 20	21	Novem	ber 1, 2021	S	September 28,	2021		100.00%			
	Contract	Informational Da	ites		M	ilestones					
Date Description	Original	Completion Date	Current Completi	on Date	No Mileston	es Exist for 0	Contract				
Acceptance Date	March 8,	2022	March 8, 2022								
Awarded Date	October	7, 2020	October 7, 2020								
Letting Date	Septemb	er 18, 2020	September 18, 202	20							
Notice to Proceed Date	Decembe	er 7, 2020	December 7, 2020								
Open to Traffic Date											

Contract Total Pay For Estimate No. 11			
	This Estimate	Previous	To Date
200918-D01			
Total Posted Items Pay	\$2,670.00	\$2,551,460.38	\$2,554,130.38
Gross Item Adjustments	(\$52,815.88)	\$58,256.62	\$5,440.74
Incentive	\$0.00	\$0.00	\$0.00
Disincentive	\$0.00	\$0.00	\$0.00
Liquidated Damage	\$0.00	\$0.00	\$0.00
Other Contract Adjustme	ents \$0.00	\$0.00	\$0.00
·		\$2,609,717.00	\$2,559,571.12
Contract Total Payable This Estimate:	(\$50,145.88)		

April 5, 2021

Items Paid This Estimate Period

Work Began Date

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J5I3423	0800	6161005	CONSTRUCTION SIGNS	SQFT	\$6.250	144	\$900.00
	0100	6161025	CHANNELIZER (TRIM LINE)	EA	\$15.000	74	\$1,110.00
	0110	6161031	TYPE III MOVEABLE BARRICADE WITH LIGHTS	EA	\$110.000	6	\$660.00
Project J5I3423	- Total						\$2,670.00
Overall - Total							\$2,670.00

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

		ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5I3423	0190	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Other Item Adjustment	Retroreflectivity Adjustment	Inspector didn't withhold the 20% for retroreflectivity results.			(\$23,497.68)
	0200	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS		Retroreflectivity Adjustment	Inspector didn't withhold the 20% for retroreflectivity results.			(\$20,551.00)
	0210	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Other Item Adjustment	Retroreflectivity Adjustment	Inspector didn't withhold the 20% for retroreflectivity results.			(\$8,767.20)
Total								(\$52,815.88)


Revision 4/1/2020 Page 1 of 10



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Informatio	n
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J5I3423	I 70-3(274)	Pavement repair	I-70	CALLAWAY	from Saline County line	e to Montgomery County lin	ne
Totals by .	Job Numbe	ers					
J5I3423		d Item Pay Item Adjustm		s Item Pay	This Estimate \$2,670.00 (\$52,815.88) (\$50,145.88)	Previous \$2,551,460.38 \$58,256.62 \$2,609,717.00	To Date \$2,554,130.38 \$5,440.74 \$2,559,571.12
	Liquid	tive centive dated Damages Contract Adju			\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00

Revision 4/1/2020 Page 2 of 10





Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period No Exceptions Exist on Contract

Revision 4/1/2020 Page 3 of 10



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
00918-D01	J5I3423	0001	0010	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	1.00	3.00	EA	3.00	\$1,000.00	\$3,000.00
		0001	0020	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	9,942.40	-610.30	9,332.10	SQYD	9,332.10	\$233.00	\$2,174,379.30
		0001	0030	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	994.00	-61.00	933.00	SQYD	933.00	\$1.00	\$933.00
		0001	0040	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	16,422.00	13,015.00	29,437.00	LF	29,437.00	\$5.00	\$147,185.00
		0001	0050	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	3,542.00	7,263.00	10,805.00	EA	10,805.00	\$4.00	\$43,220.00
		0001	0060	6131017	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	3,850.00	-2,117.00	1,733.00	EA	1,733.00	\$7.50	\$12,997.50
		0001	0070	6131018	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	2,528.00	-1,160.00	1,368.00	EA	1,368.00	\$4.00	\$5,472.00
		0001	0080	6161005	CONSTRUCTION SIGNS	1,646.00	-512.58	1,133.42	SQFT	1,133.42	\$6.25	\$7,083.88
		0001	0090	6161008	ADVANCED WARNING RAIL SYSTEM	10.00	-10.00	0.00	EA	0.00	\$55.00	\$0.00
		0001	0100	6161025	CHANNELIZER (TRIM LINE)	452.00	-102.00	350.00	EA	350.00	\$15.00	\$5,250.00
		0001	0110	6161031	TYPE III MOVEABLE BARRICADE WITH LIGHTS	12.00	0.00	12.00	EA	12.00	\$110.00	\$1,320.00
		0001	0120	6161033	DIRECTIONAL INDICATOR BARRICADE	30.00	0.00	30.00	EA	30.00	\$20.00	\$600.00
		0001	0130	6161040	FLASHING ARROW PANEL	4.00	1.00	5.00	EA	5.00	\$750.00	\$3,750.00
		0001	0140	6161055	SEQUENTIAL FLASHING WARNING LIGHT	30.00	0.00	30.00	EA	30.00	\$50.00	\$1,500.00
		0001	0150	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	4.00	\$3,200.00	\$12,800.00
		0001	0160	6162004	TEMPORARY SHORT-TERM RUMBLE STRIPS	8.00	0.00	8.00	EA	8.00	\$250.00	\$2,000.00
		0001	0170	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.00	\$0.00	\$0.00
		0001	0180	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	16.00	8.00	24.00	LF	24.00	\$25.00	\$600.00
		0001	0190	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	509,344.00	24,694.00	534,038.00	LF	534,038.00	\$0.11	\$58,744.18
		0001	0200	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	403,614.00	24,532.00	428,146.00	LF	428,146.00	\$0.12	\$51,377.52
		0001	0210	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	24,892.00	-2,974.00	21,918.00	LF	21,918.00	\$1.00	\$21,918.00
	Project .	1513423 - To	tal Value	Posted to D	Date as of Report Generated Date							\$2,554,130.38
0918-D01 Ove	erall - Tota	I Value Pos	ted to Da	ate as of Rep	ort Generated Date							\$2,554,130.38

Revision 4/1/2020 Page 4 of 10



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0080	6161005	CONSTRUCTION SIGNS	1/19/22	1/19/22	144.00	SQFT	2-Road Work Ahead(32SQFT), 1-Rate Our Work Zone(8SQFT), 2-\$250 Fine(40SQFT), 2-Work Zone No Phone Zone(24SQFT), 1-End Road Work(8SQFT), 1- Speed Limit 70(12SQFT), 2-Road Work 22 Miles(20SQFT)					
0100	6161025	CHANNELIZER (TRIM LINE)	1/19/22	1/19/22	74.00	EA	Additional channelizers used in Boone County work zones on I-70.					
0110	6161031	TYPE III MOVEABLE BARRICADE WITH LIGHTS	1/19/22	1/19/22	6.00	EA	Additional Type III barricades used in Boone County & Callaway County ramp work along I-70.					

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 4/1/2020 Page 5 of 10



Material Pote Material Pot	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
Section Sect	J5I3423	0010	TRAILER MOUNTED	Overrun	Overrun	8		SYSTEM	\$1,000.00	Estimate Item Adjustment (0001) due to user woods6 overridding Payment
2021 9 Sup 30, SYSTEM \$1,000			ATTEN (TWA)			8		SYSTEM	(\$1,000.00)	
Continue Continue						9		SYSTEM	(\$1,000.00)	
Overrun - Total						9		SYSTEM	\$1,000.00	Estimate Item Adjustment (0001) due to user woods6 overridding Payment
Set 18 - Total					Overrun - To	otal			\$0.00	
DODD				Overrun - Tota	ıl				\$0.00	
PLACE CONC PULL DEFP		0010 -	Total						\$0.00	
FULL DEPTH		0020	PLACE CONC	Material		2		SYSTEM	(\$385,328.41)	
Material Credit										
2021 386,328.41				Material - Tota	ıl				(\$385,328.41)	
Material Credit - Total S385,328.41 Adjusting till material and testing catches up.				MaterialCredit		3		SYSTEM	\$385,328.41	
Other Item Adjustment OTHR 2 Apr 16, rennic \$385,328.41 Adjusting till material and testing catches up.					- Total				\$385,328.41	
Adjustment 2021 3 May 2, 2021 50.00				MaterialCredit	- Total				\$385,328.41	
2021 50.00					OTHR	2		rennic	\$385,328.41	Adjusting till material and testing catches up.
Other Item Adjustment - Total So.00								woods6	,	Taking back adjustment.
Subgrape Compaction Subgrape Compaction									\$0.00	
O300				Other Item Ad	justment - To	tal				
COMPACTION (6 IN .DEPTH) (PAVEM PAVEM PA		0020 -							\$0.00	
Charle		0030	COMPACTION	Material		2		SYSTEM	(\$165.38)	
MaterialCredit 3 May 2, 2021 \$165.38										
1-Total					1					
MaterialCredit - Total				MaterialCredit		3		SYSTEM		
Other Item Adjustment										
Adjustment 2021 3 May 2, 2021 3 Material - Total 30.00										
OTHR - Total S0.00					OTHR		2021			
Other Item Adjustment - Total \$0.00						3		woods6	` ′	.Taking back adjustment
\$0.00										
Down				Other Item Ad	justment - To	tal				
PAVEMENT REPAIR SAW CUT (FOR										
Sep 1, 2021 SYSTEM (\$1,937.75)		0040	PAVEMENT REPAIR SAW	Overrun	Overrun	8		SYSTEM	\$1,937.75	Estimate Item Adjustment (0002) due to user woods6 overridding Payment
Overrun - Total \$0.00			CUT (FOR			8		SYSTEM	(\$1,937.75)	
DOWEL BAR Material 2 Apr 19, 2021 (\$5,480.00)					Overrun - To	otal			\$0.00	
DOWEL BAR				Overrun - Tota	ıl				\$0.00	
CORILLING, FURNISHING AND INST		0040 -	Total						\$0.00	
AND INST - Total (\$5,480.00) Material - Total (\$5,480.00) MaterialCredit 3 May 2, 2021 \$5,480.00		0050	(DRILLING,	Material		2		SYSTEM	(\$5,480.00)	
MaterialCredit 3 May 2, 2021 \$YSTEM \$5,480.00					- Total				(\$5,480.00)	
2021				Material - Tota	ıl				(\$5,480.00)	
- Total \$5,480.00				MaterialCredit		3		SYSTEM	\$5,480.00	
					- Total				\$5,480.00	



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks						
3423	0050	DOWEL BAR	MaterialCredit	- Total				\$5,480.00							
		(DRILLING, FURNISHING AND INST	Other Item Adjustment	OTHR	2	Apr 16, 2021	rennic	\$5,480.00	Adjusting till material and testing catches up.						
					3	May 2, 2021	woods6	(\$5,480.00)	Taking back adjustment						
				OTHR - Tota	al			\$0.00							
			Other Item Ad	justment - To	tal			\$0.00							
			Overrun	Overrun	3	May 2, 2021	SYSTEM	(\$2,964.00)							
					4	May 17, 2021	SYSTEM	\$120.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user rennic overridding Payment Estimate Exception 1 on the current Payment Estimate.						
					4	May 17, 2021	SYSTEM	\$628.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user rennic overridding Payment Estimate Exception 1 on the current Payment Estimate.						
					4	May 17, 2021	SYSTEM	\$160.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user rennic overridding Payment Estimate Exception 1 on the current Payment Estimate.						
									4	May 17, 2021	SYSTEM	\$800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user rennic overridding Payment Estimate Exception 1 on the current Payment Estimate.		
					4	May 17, 2021	SYSTEM	\$408.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user rennic overridding Payment Estimate Exception 1 on the current Payment Estimate.						
					4	May 17, 2021	SYSTEM	(\$2,116.00)							
				5	Jul 16, 2021	SYSTEM	\$2,964.00	Unit price based on averaged overrun adjustments for installed quantity on al previous payment estimates. Price Adjustments of ',4.00000 - 4.00000, 'is applied (if non-zero).							
											7	Aug 16, 2021	SYSTEM	(\$560.00)	
						8	Sep 1, 2021	SYSTEM	\$916.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woods6 overridding Payment Estimate Exception 12 on the current Payment Estimate.					
					8	Sep 1, 2021	SYSTEM	(\$916.00)							
					9	Sep 30, 2021	SYSTEM		Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',4.00000 - 4.00000, 'is applied (if non-zero).						
				Overrun - T	otal			\$0.00							
			Overrun - Tota	al				\$0.00							
	0050 -	· Total						\$0.00							
	0070	TIE BAR (DRILL, FURN	Material		2	Apr 19, 2021	SYSTEM	(\$1,456.00)							
		& INSTAL) (TYPE L		- Total				(\$1,456.00)							
			Material - Tota	ıl				(\$1,456.00)							
		· 1			`	Ò	, i	Material - Total MaterialCredit		3			¢1 456 00		
			MaterialCredit		o .	2021	SYSTEM	\$1,456.00							
			MaterialCredit	- Total			STSTEIN	\$1,456.00							
			MaterialCredit MaterialCredit				STSTEM								
							rennic	\$1,456.00	Adjusting till material and testing catches up.						
			MaterialCredit Other Item	- Total		2021 Apr 16,		\$1,456.00 \$1,456.00	Adjusting till material and testing catches up. Taking back adjustment						
			MaterialCredit Other Item	- Total	2	Apr 16, 2021 May 2,	rennic	\$1,456.00 \$1,456.00 \$1,456.00	, , , , , , , , , , , , , , , , , , ,						
			MaterialCredit Other Item	OTHR	2 3	Apr 16, 2021 May 2,	rennic	\$1,456.00 \$1,456.00 \$1,456.00 (\$1,456.00)	, , , , , , , , , , , , , , , , , , ,						
	0070 -	· Total	MaterialCredit Other Item Adjustment	OTHR	2 3	Apr 16, 2021 May 2,	rennic	\$1,456.00 \$1,456.00 \$1,456.00 (\$1,456.00)	, ,						
	0070 - 0130	Total FLASHING ARROW PANEL	MaterialCredit Other Item Adjustment	OTHR	2 3 al	Apr 16, 2021 May 2,	rennic	\$1,456.00 \$1,456.00 \$1,456.00 (\$1,456.00) \$0.00	, , , , , , , , , , , , , , , , , , ,						



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J5I3423	0130	FLASHING ARROW	Overrun	Overrun	9	Sep 30, 2021	SYSTEM	(\$750.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	
		PANEL			9	Sep 30, 2021	SYSTEM	\$750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woods6 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
				Overrun - T	otal			\$0.00		
			Overrun - Tota	ıl				\$0.00		
	0130 -	Total						\$0.00		
	0180	PREF THERMO PVMT MARK, 24 IN WHIT	Material		8	Sep 1, 2021	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woods6 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
		24 110 001111			8	Sep 1, 2021	SYSTEM	(\$600.00)		
					9	Sep 30, 2021	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woods6 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					9	Sep 30, 2021	SYSTEM	(\$600.00)		
				- Total				\$0.00		
			Material - Tota	ıl				\$0.00		
			Overrun	Overrun	8	Sep 1, 2021	SYSTEM	\$200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 14 on the current Payment Estimate. Material Insufficiency Quantity 24.000; Overrun Quantity Balance 8.00.	
					8	Sep 1, 2021	SYSTEM	(\$200.00)		
					9	Sep 30, 2021	SYSTEM	(\$200.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	
					9	Sep 30, 2021	SYSTEM	\$200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 6 on the current Payment Estimate. Material Insufficiency Quantity 24.000; Overrun Quantity Balance 8.00.	
				Overrun - T	otal			\$0.00		
			Overrun - Tota	ıl				\$0.00		
	0180 -	Total						\$0.00		
	0190	6 IN. WHITE HIGH BUILD WATERBORNE PAINT	Material		8	Sep 1, 2021	SYSTEM	\$58,744.18	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woods6 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
		7,1141			8	Sep 1, 2021	SYSTEM	(\$58,744.18)		
					9	9	Sep 30, 2021	SYSTEM	\$58,744.18	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woods6 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					9	Sep 30, 2021	SYSTEM	(\$58,744.18)		
				- Total				\$0.00		
			Material - Tota					\$0.00		
			Other Item Adjustment	REFL	8	Sep 1, 2021	woods6	\$11,748.84	20% withheld for retroreflectivity results.	
		Adjustinoni		9	Sep 30, 2021	woods6	\$11,748.84	Giving 20% back since we have retro results.		
					9	Sep 30, 2021	woods6	\$2,887.28	bonus for retro results	
					11	Mar 16, 2022	woods6	(\$23,497.68)	Inspector didn't withhold the 20% for retroreflectivity results.	
				REFL - Tota	ı			\$2,887.28		
			Other Item Ad	justment - To	tal			\$2,887.28		
			Overrun	Overrun	8	Sep 1, 2021	SYSTEM	\$2,716.34	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 15 on the current Payment Estimate. Material Insufficiency Quantity 534038.000; Overrun Quantity Balance 24694.00.	
					8	Sep 1, 2021	SYSTEM	(\$2,716.34)		



June 1994 1995	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
PAINT	J5I3423	0190	HIGH BUILD	Overrun	Overrun	9		SYSTEM	(\$2,716.34)	
								SYSTEM		Estimate Item Adjustment (0006) overridding Payment Estimate Exception 7 on the current Payment Estimate. Material Insufficiency Quantity 534038.000;
						otal				
Sep 1, SYSTEM Sep 2, SYSTE				Overrun - Tota	al				\$0.00	
HIGH BUILD		0190 -	- Total						\$2,887.28	
		0200	HIGH BUILD WATERBORNE	Material		8		SYSTEM	\$51,377.52	Estimate Item Adjustment (0010) due to user woods6 overridding Payment
2021			FAINT			8		SYSTEM	(\$51,377.52)	
2021 30.00 Material - Total						9		SYSTEM	\$51,377.52	Estimate Item Adjustment (0009) due to user woods6 overridding Payment
Material - Total						9		SYSTEM		
Other item Adjustment					- Total	al			\$0.00	
Adjustment				Material - Tota	ıl				\$0.00	
9 Sep 30, woods6 \$2,553.46 bornus for retro results					REFL	8		woods6	\$10,275.50	20% withheld for retroreflectivity results.
2021						9		woods6	\$10,275.50	Giving 20% back since we have retro results.
2022 \$2,553.46						9		woods6	\$2,553.46	bonus for retro results
Other tem Adjustment - Total Support								woods6	(\$20,551.00)	Inspector didn't withhold the 20% for retroreflectivity results.
Overrun Overrun Overrun 8					REFL - Tota				\$2,553.46	
2021 Sep 30, SySTEM S2,943.84				Other Item Ad					\$2.553.46	
2021										
2021 9 Sep 30, SYSTEM \$2,943.84 This adjustment offsets the original system-generated Overrun Payment Estimate Exception 8 on the current Payment Estimate Material Insufficiency Quantity 428146.000; Overrun Quantity Balance 24532.00. Overrun - Total						8		SYSTEM		Estimate Item Adjustment (0009) overridding Payment Estimate Exception 16 on the current Payment Estimate. Material Insufficiency Quantity 428146.000;
2021 Setimate Item Adjustment (0008) overridding Payment Estimate Exception 8 on the current Payment Estimate. Material Insufficiency Quantity 428146.000; Overrun Quantity Balance 24532.00. Overrun - Total							2021 Sep 1,		\$2,943.84	Estimate Item Adjustment (0009) overridding Payment Estimate Exception 16 on the current Payment Estimate. Material Insufficiency Quantity 428146.000;
Overrun - Total \$0.00						8	2021 Sep 1, 2021 Sep 30,	SYSTEM	\$2,943.84	Estimate Item Adjustment (0009) overridding Payment Estimate Exception 16 on the current Payment Estimate. Material Insufficiency Quantity 428146.000; Overrun Quantity Balance 24532.00. Averaged Price Adjustment from this item on all previous payment estimates
Sep 1, 2021 SYSTEM Sep 1, 2021 Sound Sound Sound Sound Sound Sep 1, 2021 System Sound Sound Sep 1, 2021 Sound Sound Sound Sep 1, 2021 Sep 3, 2021 Sep 3, 2021 Sep 3, 2021 Sep 3, 2021 Sound Sep 3, 2021 S						8	2021 Sep 1, 2021 Sep 30, 2021 Sep 30,	SYSTEM SYSTEM	\$2,943.84 (\$2,943.84) (\$2,943.84)	Estimate Item Adjustment (0009) overridding Payment Estimate Exception 16 on the current Payment Estimate. Material Insufficiency Quantity 428146.000; Overrun Quantity Balance 24532.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 8 on the current Payment Estimate. Material Insufficiency Quantity 428146.000;
12 IN. WHITE HIGH BUILD WATERBORNE PAINT 8 Sep 1, 2021 SYSTEM \$21,918.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user woods6 overridding Payment Estimate Exception 8 on the current Payment Estimate. Total SO.00					Overrun	9	2021 Sep 1, 2021 Sep 30, 2021 Sep 30,	SYSTEM SYSTEM	\$2,943.84 (\$2,943.84) (\$2,943.84) \$2,943.84	Estimate Item Adjustment (0009) overridding Payment Estimate Exception 16 on the current Payment Estimate. Material Insufficiency Quantity 428146.000; Overrun Quantity Balance 24532.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 8 on the current Payment Estimate. Material Insufficiency Quantity 428146.000;
HIGH BUILD WATERBORNE PAINT				Overrun	Overrun - T	9	2021 Sep 1, 2021 Sep 30, 2021 Sep 30,	SYSTEM SYSTEM	\$2,943.84 (\$2,943.84) (\$2,943.84) \$2,943.84	Estimate Item Adjustment (0009) overridding Payment Estimate Exception 16 on the current Payment Estimate. Material Insufficiency Quantity 428146.000; Overrun Quantity Balance 24532.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 8 on the current Payment Estimate. Material Insufficiency Quantity 428146.000;
Sep 1, 2021 SYSTEM (\$21,918.00)		0200 -	- Total	Overrun	Overrun - T	9	2021 Sep 1, 2021 Sep 30, 2021 Sep 30,	SYSTEM SYSTEM	\$2,943.84 (\$2,943.84) (\$2,943.84) \$2,943.84 \$0.00 \$0.00	Estimate Item Adjustment (0009) overridding Payment Estimate Exception 16 on the current Payment Estimate. Material Insufficiency Quantity 428146.000; Overrun Quantity Balance 24532.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 8 on the current Payment Estimate. Material Insufficiency Quantity 428146.000;
Naterial - Total So.00			12 IN. WHITE HIGH BUILD WATERBORNE	Overrun - Tota	Overrun - T	8 9 9 otal	2021 Sep 1, 2021 Sep 30, 2021 Sep 30, 2021 Sep 31, 2021	SYSTEM SYSTEM SYSTEM	\$2,943.84 (\$2,943.84) (\$2,943.84) \$2,943.84 \$0.00 \$0.00 \$2,553.46	Estimate Item Adjustment (0009) overridding Payment Estimate Exception 16 on the current Payment Estimate. Material Insufficiency Quantity 428146.000; Overrun Quantity Balance 24532.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 8 on the current Payment Estimate. Material Insufficiency Quantity 428146.000; Overrun Quantity Balance 24532.00.
Other Item Adjustment REFL 8 Sep 1, 2021 woods6 \$4,383.60 20% withheld for retroreflectivity results 9 Sep 30, 2021 group woods6 \$4,383.60 Giving 20% back since we have retro results. 11 Mar 16, 2022 woods6 (\$8,767.20) Inspector didn't withhold the 20% for retroreflectivity results.			12 IN. WHITE HIGH BUILD WATERBORNE	Overrun - Tota	Overrun - T	8 9 9 ootal 8	Sep 1, 2021 Sep 30, 2021 Sep 30, 2021 Sep 30, 2021 Sep 30, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$2,943.84 (\$2,943.84) (\$2,943.84) \$2,943.84 \$0.00 \$0.00 \$2,553.46 \$21,918.00	Estimate Item Adjustment (0009) overridding Payment Estimate Exception 16 on the current Payment Estimate. Material Insufficiency Quantity 428146.000; Overrun Quantity Balance 24532.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 8 on the current Payment Estimate. Material Insufficiency Quantity 428146.000; Overrun Quantity Balance 24532.00.
Adjustment 2021 9 Sep 30, 2021 Giving 20% back since we have retro results. 11 Mar 16, 2022 Inspector didn't withhold the 20% for retroreflectivity results. REFL - Total \$0.00			12 IN. WHITE HIGH BUILD WATERBORNE	Overrun - Tota	Overrun - T	8 9 9 ootal 8	Sep 1, 2021 Sep 30, 2021 Sep 30, 2021 Sep 30, 2021 Sep 30, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$2,943.84 (\$2,943.84) (\$2,943.84) \$2,943.84 \$0.00 \$0.00 \$2,553.46 \$21,918.00)	Estimate Item Adjustment (0009) overridding Payment Estimate Exception 16 on the current Payment Estimate. Material Insufficiency Quantity 428146.000; Overrun Quantity Balance 24532.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 8 on the current Payment Estimate. Material Insufficiency Quantity 428146.000; Overrun Quantity Balance 24532.00.
2021 11 Mar 16, 2022 Inspector didn't withhold the 20% for retroreflectivity results. REFL - Total \$0.00			12 IN. WHITE HIGH BUILD WATERBORNE	Overrun - Tota	Overrun - Tal	8 9 9 ootal 8	Sep 1, 2021 Sep 30, 2021 Sep 30, 2021 Sep 30, 2021 Sep 30, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$2,943.84 (\$2,943.84) (\$2,943.84) \$2,943.84 \$0.00 \$0.00 \$2,553.46 \$21,918.00) (\$21,918.00)	Estimate Item Adjustment (0009) overridding Payment Estimate Exception 16 on the current Payment Estimate. Material Insufficiency Quantity 428146.000; Overrun Quantity Balance 24532.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 8 on the current Payment Estimate. Material Insufficiency Quantity 428146.000; Overrun Quantity Balance 24532.00.
			12 IN. WHITE HIGH BUILD WATERBORNE	Overrun - Tota Material Material - Tota Other Item	Overrun - T	8 9 9 9 otal 8 8 8	Sep 1, 2021 Sep 30, 2021 Sep 30, 2021 Sep 30, 2021 Sep 1, 2021 Sep 1, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$2,943.84 (\$2,943.84) (\$2,943.84) \$2,943.84 \$0.00 \$0.00 \$2,553.46 \$21,918.00) \$0.00 \$0.00	Estimate Item Adjustment (0009) overridding Payment Estimate Exception 16 on the current Payment Estimate. Material Insufficiency Quantity 428146.000; Overrun Quantity Balance 24532.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 8 on the current Payment Estimate. Material Insufficiency Quantity 428146.000; Overrun Quantity Balance 24532.00. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user woods6 overridding Payment Estimate Exception 8 on the current Payment Estimate.
			12 IN. WHITE HIGH BUILD WATERBORNE	Overrun - Tota Material Material - Tota Other Item	Overrun - T	8 9 9 9 otal 8 8 8	Sep 1, 2021 Sep 30, 2021 Sep 30, 2021 Sep 30, 2021 Sep 1, 2021 Sep 1, 2021 Sep 1, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM woods6	\$2,943.84 (\$2,943.84) (\$2,943.84) \$2,943.84 \$0.00 \$0.00 \$2,553.46 \$21,918.00) \$0.00 \$0.00 \$4,383.60	Estimate Item Adjustment (0009) overridding Payment Estimate Exception 16 on the current Payment Estimate. Material Insufficiency Quantity 428146.000; Overrun Quantity Balance 24532.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 8 on the current Payment Estimate. Material Insufficiency Quantity 428146.000; Overrun Quantity Balance 24532.00. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user woods6 overridding Payment Estimate Exception 8 on the current Payment Estimate.
Other Item Adjustment - Total \$0.00			12 IN. WHITE HIGH BUILD WATERBORNE	Overrun - Tota Material Material - Tota Other Item	Overrun - T	8 9 9 9 otal 8 8 9 9	Sep 1, 2021 Sep 30, 2021 Sep 30, 2021 Sep 31, 2021 Sep 1, 2021 Sep 1, 2021 Sep 30, 2021 Mar 16, 16, 16, 16, 16, 16, 16, 16, 16, 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM woods6	\$2,943.84 (\$2,943.84) (\$2,943.84) \$2,943.84 \$0.00 \$0.00 \$2,553.46 \$21,918.00) \$0.00 \$0.00 \$4,383.60 \$4,383.60	Estimate Item Adjustment (0009) overridding Payment Estimate Exception 16 on the current Payment Estimate. Material Insufficiency Quantity 428146.000; Overrun Quantity Balance 24532.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 8 on the current Payment Estimate. Material Insufficiency Quantity 428146.000; Overrun Quantity Balance 24532.00. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user woods6 overridding Payment Estimate Exception 8 on the current Payment Estimate.
			12 IN. WHITE HIGH BUILD WATERBORNE	Overrun - Tota Material Material - Tota Other Item	Overrun - T	8 9 9 9 8 8 8 9 111	Sep 1, 2021 Sep 30, 2021 Sep 30, 2021 Sep 31, 2021 Sep 1, 2021 Sep 1, 2021 Sep 30, 2021 Mar 16, 16, 16, 16, 16, 16, 16, 16, 16, 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM woods6	\$2,943.84 (\$2,943.84) (\$2,943.84) \$2,943.84 \$0.00 \$0.00 \$2,553.46 \$21,918.00) \$0.00 \$0.00 \$4,383.60 \$4,383.60 (\$8,767.20)	Estimate Item Adjustment (0009) overridding Payment Estimate Exception 16 on the current Payment Estimate. Material Insufficiency Quantity 428146.000; Overrun Quantity Balance 24532.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 8 on the current Payment Estimate. Material Insufficiency Quantity 428146.000; Overrun Quantity Balance 24532.00. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user woods6 overridding Payment Estimate Exception 8 on the current Payment Estimate.

Apr 8, 2022



Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5I3423	0210 -	Total						\$0.00	
J5I3423 -	- Total							\$5,440.74	
Overall -	Total							\$5,440.74	