

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: November 16, 2021

Progress Estimate Number	Contract ID	201016-C02	Pay Period Start	November 2, 2021	Original Contract Amount	\$5,716,989.09
18	Prime Contractor	Capital Paving & Construction, LLC	Pay Period End	2021	Net Change Order Amount Current Contract Amount	\$123,138.19 \$5,840,127.28

Approval Date		By User
November 17, 2021	Generated and Approved (and should be considered Draft) at the Project Office Level by	sandis1
November 17, 2021	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	sandis1
November 17, 2021	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
November 1, 2021	November 1, 2021		95.53%

	Contract Informational Dates									
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract							
02/22/2021										
Acceptance Date										
Awarded Date	November 5, 2020	November 5, 2020								
Letting Date	October 16, 2020	October 16, 2020								
Notice to Proceed Date	January 4, 2021	January 4, 2021								

Contract Total Pa	y For Estimate No. 18				
		This Estimate	Previous	To Date	
201016-C02					
	Total Posted Items Pay	\$23,462.69	\$5,555,824.91	\$5,579,287.60	
	Gross Item Adjustments	\$0.00	\$277,820.25	\$277,820.25	
	Incentive	\$0.00	\$77,259.04	\$77,259.04	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
			\$5,910,904.20	\$5,934,366.89	
Contract Total Pa	yable This Estimate:	\$23,462.69			

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount		
J4I3222	0020	2153000	SHAPING SLOPES, CLASS III	100F	\$685.000	2	\$1,370.00		
	0440	6061080	MGS END ANCHOR	EA	\$800.000	1	\$800.00		
	5003	6061063	MGS GUARDRAIL, 6 FT. POSTS, 3 FT 1.5 IN. SPACING	LF	\$34.150	87.5	\$2,988.13		
	5004	6069903	MISC.MGS Guardrail, 8 Ft. Posts, 3 Ft. 1 1/2 In. Spacing	LF	\$49.210	50	\$2,460.50		
	5005	6069901	MISC.Guard Cable and Cable Anchor at Route 7	LS	\$15,067.060	1	\$15,067.06		
	5006	6069902	MISC.Flume Coring for Guardrail Installation	EA	\$194.250	4	\$777.00		
Project J4l322	22 - Total						\$23,462.69		
Overall - Tota	Overall - Total								

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item	Adjust	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4I3222	0030	MISC.	Material			-734.3	\$72.05	(\$52,906.32)
	0030	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0021) due to user woodyb1	734.3	\$72.05	\$52,906.32

Revision 4/1/2020 Page 1 of 29



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: November 16, 2021

Progress Estimate Number
18 Contract ID 201016-C02 Pay Period Start November 2, 2021 Original Contract Amount \$5,716,989.09
Prime Contractor LLC Pay Period End November 15, 2021 November 2, 2021

								70,010,121.20
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4I3222					overridding Payment Estimate Exception 1 on the current Payment Estimate.			
	0120	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material			-1,458	\$4.25	(\$6,196.50)
	0120	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user woodyb1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	1,458	\$4.25	\$6,196.50
	0130	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	Material			-80	\$8.25	(\$660.00
	0130	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user woodyb1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	80	\$8.25	\$660.00
	0140	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	Material			-386	\$7.50	(\$2,895.00
	0140	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user woodyb1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	386	\$7.50	\$2,895.00
	0150	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS B PARTIAL DEPTH PAVEMENT REPAIR	Material			-91.97	\$181.66	(\$16,707.27
	0150	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS B PARTIAL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user woodyb1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	91.97	\$181.66	\$16,707.27
	0170	MISC.	Material			-16,193.1	\$2.98	(\$48,255.44
	0170	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user woodyb1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	16,193.1	\$2.98	\$48,255.44
	0250	CONCRETE TRAFFIC BARRIER, TYPE A	Material			-21	\$315.18	(\$6,618.78
	0250	CONCRETE TRAFFIC BARRIER, TYPE A	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user woodyb1 overridding Payment Estimate Exception 19 on the current Payment Estimate.	21	\$315.18	\$6,618.78
	0280	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material			-369	\$18.00	(\$6,642.00)
	0280	PREFORMED THERMOPLASTIC	Material		This adjustment offsets the original system- generated Material Payment Estimate Item	369	\$18.00	\$6,642.00

Revision 4/1/2020 Page 2 of 29



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: November 16, 2021

Progress Estimate Number

18
Contract ID
201016-C02
Pay Period Start
November 2, 2021
Original Contract Amount \$5,716,989.09
Prime Contractor
LLC
Pay Period Start
November 15, Pay Period End November 15, 2021
Pay Period End November 15, 2021
Original Contract Amount \$5,716,989.09
Pay Period End November 15, 2021
Current Contract Amount \$5,840,127.28

ject nber	Line No.	Item Description	Adjustment Type	Other Item Adjustment	Comments	Adjustment Quantity	Line Item Adjustment	Adjustment amount
		DAVEMENT MADISING OF	71-	Туре	A Produced (0040)		Unit Price	
222		PAVEMENT MARKING, 24 IN. WHITE			Adjustment (0010) due to user woodyb1 overridding Payment Estimate Exception 25 on the current Payment Estimate.			
	0290	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	Material			-423	\$18.00	(\$7,614.00
	0290	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user woodyb1 overridding Payment Estimate Exception 26 on the current Payment Estimate.	423	\$18.00	\$7,614.00
	0300	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material			-25	\$250.00	(\$6,250.00
	0300	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user woodyb1 overridding Payment Estimate Exception 27 on the current Payment Estimate.	25	\$250.00	\$6,250.00
	0410	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	Material			-12,262.5	\$19.50	(\$239,118.75
	0410	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user woodyb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	12,262.5	\$19.50	\$239,118.75
	0430	MGS LONG SPAN GUARDRAIL SECTION	Material			-1	\$2,200.00	(\$2,200.00
	0430	MGS LONG SPAN GUARDRAIL SECTION	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user woodyb1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	1	\$2,200.00	\$2,200.00
	0500	SIGNAL HEAD, TYPE 3S	Material			-1	\$1,080.00	(\$1,080.00
	0500	SIGNAL HEAD, TYPE 3S	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user woodyb1 overridding Payment Estimate Exception 28 on the current Payment Estimate.	1	\$1,080.00	\$1,080.00
	0510	SIGNAL HEAD, TYPE 3B	Material			-4	\$1,165.00	(\$4,660.00
	0510	SIGNAL HEAD, TYPE 3B	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user woodyb1 overridding Payment Estimate Exception 29 on the current Payment Estimate.	4	\$1,165.00	\$4,660.00
	0520	POST, TYPE BL, LONGEST ARM 50 FT. OR 15.2 M	Material			-1	\$21,220.00	(\$21,220.00
	0520	POST, TYPE BL, LONGEST ARM 50 FT. OR 15.2 M	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0016) due to user woodyb1 overridding Payment Estimate Exception 30 on the current Payment Estimate.	1	\$21,220.00	\$21,220.00
	0530	CONDUIT, 4 IN., TRENCH WITH TRACER WIRE	Material			-10	\$75.00	(\$750.00

Revision 4/1/2020 Page 3 of 29



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: November 16, 2021

Progress Estimate Number 18 Contract ID 201016-C02 Pay Period Start November 2, 2021 Original Contract Amount \$5,716,989.09

Prime Contractor Capital Paving & Construction, LLC Pay Period End November 15, 2021 Original Contract Amount \$5,716,989.09

Pay Period End November 15, 2021 Original Contract Amount \$5,716,989.09

Pay Period End November 15, 2021 Original Contract Amount \$5,716,989.09

Pay Period End November 15, 2021 Original Contract Amount \$5,716,989.09

Contract ID Prime Contract ID Prime Contract Original Contract Amount \$5,716,989.09

oject	Line	Item Description	Adjustment	Other Item	Comments	Adjustment	Line Item	Adjustment
mber	No.		Туре	Adjustment Type		Quantity	Adjustment Unit Price	amount
3222	0530	CONDUIT, 4 IN., TRENCH WITH TRACER WIRE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0017) due to user woodyb1 overridding Payment Estimate Exception 33 on the current Payment Estimate.	10	\$75.00	\$750.00
	0540	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	Material			-90	\$2.85	(\$256.50
	0540	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0018) due to user woodyb1 overridding Payment Estimate Exception 34 on the current Payment Estimate.	90	\$2.85	\$256.50
	0550	CABLE, 16 AWG 7 CONDUCTOR	Material			-30	\$37.00	(\$1,110.00
	0550	CABLE, 16 AWG 7 CONDUCTOR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0019) due to user woodyb1 overridding Payment Estimate Exception 35 on the current Payment Estimate.	30	\$37.00	\$1,110.00
	0560	BASE, CONCRETE	Material			-3.7	\$3,600.00	(\$13,320.0
	0560	BASE, CONCRETE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0020) due to user woodyb1 overridding Payment Estimate Exception 36 on the current Payment Estimate.	3.7	\$3,600.00	\$13,320.00
	5002	TACK COAT - LOW OR NON-TRACKING	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-2,614	\$3.85	(\$10,063.9
	5002	TACK COAT - LOW OR NON-TRACKING	Material			-44,957	\$3.85	(\$173,084.4
	5002	TACK COAT - LOW OR NON-TRACKING	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 38 on the current Payment Estimate. Material Insufficiency Quantity 44957.000; Overrun Quantity Balance 2614.00.	2,614	\$3.85	\$10,063.9
	5002	TACK COAT - LOW OR NON-TRACKING	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user woodyb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	44,957	\$3.85	\$173,084.4
	5003	MGS GUARDRAIL, 6 FT. POSTS, 3 FT 1.5 IN. SPACING	Material			-87.5	\$34.15	(\$2,988.1)
	5003	MGS GUARDRAIL, 6 FT. POSTS, 3 FT 1.5 IN. SPACING	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0023) due to user woodyb1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	87.5	\$34.15	\$2,988.12
	5004	MISC.	Material			-50	\$49.21	(\$2,460.5
	5004	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0022) due to user woodyb1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	50	\$49.21	\$2,460.5
al								\$0.00

Revision 4/1/2020 Page 4 of 29



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Information	n
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J4I3222	I 70-1(212)	Resurface	I-70	JACKSON	from Route 7 to Horsesh	oe Creek bridge	
Totals by	Job Numbe	rs					
J4I3222		d Item Pay Item Adjustm		s Item Pay	This Estimate \$23,462.69 \$0.00 \$23,462.69	Previous \$5,555,824.91 \$277,820.25 \$5,833,645.16	To Date \$5,579,287.60 \$277,820.25 \$5,857,107.85
	Liquio	tive centive lated Damages Contract Adju			\$0.00 \$0.00 \$0.00 \$0.00	\$77,259.04 \$0.00 \$0.00 \$0.00	\$77,259.04 \$0.00 \$0.00 \$0.00

Revision 4/1/2020 Page 5 of 29



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4I3222, Item 3049910, Project Item Line Number 0030, Material Set 304991096, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	QC, QA, and KC materials are working to resolve the exceptions.	woodyb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3222, Item 4071007, Project Item Line Number 5002, Material Set 407100796, Material 1015EASS1VH - Emulsified Asphalt - Trackless Tack, Acceptance Action Generic AspEmulsion is insufficient.	QC, QA, and KC materials are working to resolve the exceptions.	woodyb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3222, Item 6061061, Project Item Line Number 0410, Material Set 606106196, Material 1065DE - Delineators, Acceptance Action Generic 1065DE is insufficient.	QC, QA, and KC materials are working to resolve the exceptions.	woodyb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 6061063, Project Item Line Number 5003, Material Set 606106396, Material 1040GRSRCAT2 - Steel Beam for Class A Type 2 Guard Rail, Acceptance Action Generic 1040GRSRCAT2 is insufficient.	QC, QA, and KC materials are working to resolve the exceptions.	woodyb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 6061063, Project Item Line Number 5003, Material Set 606106396, Material 1065DE - Delineators, Acceptance Action Generic 1065DE is insufficient.	QC, QA, and KC materials are working to resolve the exceptions.	woodyb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 6061075, Project Item Line Number 0430, Material Set 606107596, Material 1065DE - Delineators, Acceptance Action Generic 1065DE is insufficient.	QC, QA, and KC materials are working to resolve the exceptions.	woodyb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 6069903, Project Item Line Number 5004, Material Set 606990396, Material 1040GRSRCAT2 - Steel Beam for Class A Type 2 Guard Rail, Acceptance Action Generic 1040GRSRCAT2 is insufficient.	QC, QA, and KC materials are working to resolve the exceptions.	woodyb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3222, Item 6131015, Project Item Line Number 0120, Material Set 613101596, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient.	QC, QA, and KC materials are working to resolve the exceptions.	woodyb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3222, Item 6131017, Project Item Line Number 0130, Material Set 613101796, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient.	QC, QA, and KC materials are working to resolve the exceptions.	woodyb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 6131017, Project Item Line Number 0130, Material Set 613101796, Material 1057JMDAEC6.11 - Dowel Assemblies Epoxy Ctd Gr60 1 1/4" @, Acceptance Action Generic ReinforcingMisc is insufficient.	QC, QA, and KC materials are working to resolve the exceptions.	woodyb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 6131017, Project Item Line Number 0130, Material Set 613101796, Material 1057JMDBEC6.11 - Dowel Bar Epoxy Ctd Gr60 1 1/4 @, Acceptance Action Generic ReinforcingMisc is insufficient.	QC, QA, and KC materials are working to resolve the exceptions.	woodyb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 6131018, Project Item Line Number 0140, Material Set 613101896, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient.	QC, QA, and KC materials are working to resolve the exceptions.	woodyb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 6131018, Project Item Line Number 0140, Material Set 613101896, Material 1057JMTBE42019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	QC, QA, and KC materials are working to resolve the exceptions.	woodyb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 6133018, Project Item Line Number 0150, Material Set 613301896, Material 0401BPPMBP1 - Plant Mix for Bit Pavement BP-1, Acceptance Action Generic AspLow is insufficient.	QC, QA, and KC materials are working to resolve the exceptions.	woodyb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 6139905, Project Item Line Number 0170, Material Set 613990596, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	QC, QA, and KC materials are working to resolve the exceptions.	woodyb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3222, Item 6139905, Project Item Line Number 0170, Material Set 613990596, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	QC, QA, and KC materials are working to resolve the exceptions.	woodyb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 6139905, Project Item Line Number 0170, Material Set 613990596, Material 1015EASS1H - Emulsified Asphalt SS-1H, Acceptance Action Generic AspEmulsion is insufficient.	QC, QA, and KC materials are working to resolve the exceptions.	woodyb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 6139905, Project Item Line Number 0170, Material Set 613990596, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	QC, QA, and KC materials are working to resolve the exceptions.	woodyb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 6171000, Project Item Line Number 0250, Material Set 617100096, Material 1057JMDBEC6.10 - Dowel Bar Epoxy Ctd Gr60 1" @, Acceptance Action Generic ReinforcingMisc is insufficient.	QC, QA, and KC materials are working to resolve the exceptions.	woodyb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 6171000, Project Item Line Number 0250, Material Set 617100096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	QC, QA, and KC materials are working to resolve the exceptions.	woodyb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 6171000, Project Item Line Number 0250, Material Set 617100096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	QC, QA, and KC materials are working to resolve the exceptions.	woodyb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 6171000, Project Item Line Number 0250, Material Set 617100096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	QC, QA, and KC materials are working to resolve the exceptions.	woodyb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 6171000, Project Item Line Number 0250, Material Set 617100096, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	QC, QA, and KC materials are working to resolve the exceptions.	woodyb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 6171000, Project Item Line Number 0250, Material Set 617100096, Material 1036RSDFEC42M13 - Rein Steel EC No. 4/M13 Gr	QC, QA, and KC materials are working to resolve the exceptions.	woodyb1	Overridden

Revision 4/1/2020 Page 6 of 29



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period Exceptions / Discrepencies	Explanation	Entered	Status
Exceptions / Discrependes	Ехріанаціон	By	Status
60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 6200015, Project Item Line Number 0280, Material Set 620001596, Material 1048PMPFWH - Performed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	QC, QA, and KC materials are working to resolve the exceptions.	woodyb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 6200018, Project Item Line Number 0290, Material Set 620001896, Material 1048PMPFYL - Performed Thermoplastic Marking Tape YL, Acceptance Action Generic 1048PMPFYL is insufficient.	QC, QA, and KC materials are working to resolve the exceptions.	woodyb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3222, Item 6200021, Project Item Line Number 0300, Material Set 620002196, Material 1048PMPFWHXX - Pref Mrk Tape Direct Indcat or Shape WH, Acceptance Action Generic 1048PMPFWHXX is insufficient.	QC, QA, and KC materials are working to resolve the exceptions.	woodyb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3222, Item 9020213, Project Item Line Number 0500, Material Set 902021396, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	QC, QA, and KC materials are working to resolve the exceptions.	woodyb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 9020513, Project Item Line Number 0510, Material Set 902051396, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	QC, QA, and KC materials are working to resolve the exceptions.	woodyb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3222, Item 9023450, Project Item Line Number 0520, Material Set 902345096, Material 0902TSBTZCAB - Bolts Galv Anchor for Traffic Signals, Acceptance Action Generic 0902TSBTZCAB is insufficient.	QC, QA, and KC materials are working to resolve the exceptions.	woodyb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3222, Item 9023450, Project Item Line Number 0520, Material Set 902345096, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	QC, QA, and KC materials are working to resolve the exceptions.	woodyb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3222, Item 9023450, Project Item Line Number 0520, Material Set 902345096, Material 1092TSPS - Traffic Signal Post(s) - All Types, Acceptance Action Generic 1092TSPS is insufficient.	QC, QA, and KC materials are working to resolve the exceptions.	woodyb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 9025400, Project Item Line Number 0530, Material Set 902540096, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient.	QC, QA, and KC materials are working to resolve the exceptions.	woodyb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 9028100, Project Item Line Number 0540, Material Set 902810096, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	QC, QA, and KC materials are working to resolve the exceptions.	woodyb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3222, Item 9028311, Project Item Line Number 0550, Material Set 902831196, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	QC, QA, and KC materials are working to resolve the exceptions.	woodyb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3222, Item 9029100, Project Item Line Number 0560, Material Set 902910096, Material 1036RSDFPL42M19 - Reinforcing Steel No. 6/M19 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	QC, QA, and KC materials are working to resolve the exceptions.	woodyb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3222, Item 9029100, Project Item Line Number 0560, Material Set 902910096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	QC, QA, and KC materials are working to resolve the exceptions.	woodyb1	Overridden
Estimate Exception Type: Item Overrun: Contract 201016-C02, Contract Project J4l3222, Project Item Line Number 5002, Contract Line Item Number 5002, Item 4071007, Minor Item.	Change order in progress	woodyb1	Overridden
Estimate Exception Type: Item Overrun: Contract 201016-C02, Contract Project J4l3222, Project Item Line Number 0040, Contract Line Item Number 0040, Item 4011211, Minor Item.	Change order is in progress	woodyb1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 201016-C02, Contract Project J4l3222, Project Item Line Number 0180, Contract Line Item Number 0180, Item 6139910, Minor Item.	Change order is in progress	woodyb1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 201016-C02, Contract Project J4l3222, Project Item Line Number 0350, Contract Line Item Number 0350, Item 6221001, Minor Item.	Change order is in progress	woodyb1	Acknowledged

Revision 4/1/2020 Page 7 of 29



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT		Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
201016-C02	J4I3222	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$25,450.00	\$25,450.00
		0001	0020	2153000	SHAPING SLOPES, CLASS III	134.00	2.00	136.00	100F	136.00	\$685.00	\$93,160.00
		0001	0030	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	734.30	0.00	734.30	TONS	734.30	\$72.05	\$52,906.32
		0001	0040	4011211	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-2)	6,988.70	0.00	6,988.70	TONS	8,581.39	\$57.98	\$497,548.99
		0001	0050	4030009	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP095BSM MIX)	30,494.70	0.00	30,494.70	TONS	29,813.08	\$82.14	\$2,448,846.39
		0001	0060	4071005	TACK COAT	42,343.00	-42,343.00	0.00	GAL	0.00	\$2.03	\$0.00
		0001	0070	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$500.00	\$1,000.00
		0001	0800	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	3,743.30	0.00	3,743.30	SQYD	2,556.80	\$208.20	\$532,325.76
		0001	0090	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	375.00	0.00	375.00	SQYD	0.00	\$1.00	\$0.00
		0001	0100	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	375.00	0.00	375.00	SQYD	0.00	\$1.00	\$0.00
		0001	0110	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER	9,624.00	0.00	9,624.00	LF	5,347.00	\$2.00	\$10,694.00
		0001	0120	6131015	AND INTERNAL SAW CUTS) DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	1,602.00	0.00	1,602.00	EA	1,458.00	\$4.25	\$6,196.50
		0001	0130	6131017	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	85.00	0.00	85.00	EA	80.00	\$8.25	\$660.00
		0001	0140	6131018	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	512.00	0.00	512.00	EA	386.00	\$7.50	\$2,895.00
		0001	0150	6133018	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS B PARTIAL DEPTH PAVEMENT REPAIR	112.60	0.00	112.60	TONS	91.97	\$181.66	\$16,707.27
		0001	0160	6133019	REMOVAL FOR CLASS B PARTIAL DEPTH PAVEMENT REPAIR	675.40	0.00	675.40	SQYD	664.62	\$71.21	\$47,327.59
		0001	0170	6139905	MISC.REMOVAL FOR CLASS C PARTIAL DEPTH RUMBLE STRIP REPAIR	16,363.00	0.00	16,363.00	SQYD	16,193.10	\$2.98	\$48,255.44
		0001	0180	6139910	MISC.FURNISHING AND PLACING BITUMINOUS MATERIAL FOR	2,585.60	0.00	2,585.60	TONS	2,603.31	\$52.96	\$137,871.30
		0001	0190	6161005	CLASS C PARTIAL DEPTH RUMBLE STRIP REPAIR CONSTRUCTION SIGNS	1,794.00	0.00	1,794.00	SQFT	1,468.11	\$5.00	\$7,340.55
		0001	0200	6161009	FLAG ASSEMBLY	19.00	0.00	19.00	EA	2.00	\$15.00	\$30.00
		0001	0210	6161024	CHANNELIZER (TRIM LINE) WITH LIGHT	607.00	0.00	607.00	EA	315.00	\$38.00	\$11,970.00
		0001	0220	6161034	DIRECTIONAL INDICATOR BARRICADE WITH LIGHT	93.00	0.00	93.00	EA	14.00	\$94.00	\$1,316.00
		0001	0230	6161040	FLASHING ARROW PANEL	4.00	0.00	4.00	EA	3.00	\$4,000.00	\$12,000.00
		0001	0240	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	-4.00	0.00	EA	0.00	\$1,000.00	\$0.00
		0001	0250	6171000	CONCRETE TRAFFIC BARRIER, TYPE A	50.00	0.00	50.00	LF	21.00	\$315.18	\$6,618.78
		0001	0260	6173000	CONCRETE TRAFFIC BARRIER, TYPE C	32.00	0.00	32.00	LF	0.00	\$298.50	\$0.00
		0001	0270	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$146,859.59	\$146,859.59
		0001	0280	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	455.00	0.00	455.00	LF	369.00	\$18.00	\$6,642.00
		0001	0290	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	441.00	0.00	441.00	LF	423.00	\$18.00	\$7,614.00
		0001	0300	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	25.00	0.00	25.00	EA	25.00	\$250.00	\$6,250.00
		0001	0310	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	127,559.00	0.00	127,559.00	LF	126,412.00	\$0.16	\$20,225.92
		0001	0320	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	104,914.00	0.00	104,914.00	LF	102,167.00	\$0.16	\$16,346.72
		0001	0330	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT. TYPE L BEADS	7,113.00	0.00	7,113.00	LF	6,046.00	\$0.30	\$1,813.80
		0001	0340	6207001	PAVEMENT MARKING REMOVAL	300.00	0.00	300.00	LF	300.00	\$1.00	\$300.00
		0001	0350	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	414,629.00	0.00	414,629.00	SQYD	417,497.79	\$0.65	\$271,373.56
		0001	0360	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	11,710.00	0.00	11,710.00	SQYD	11,231.92	\$2.50	\$28,079.80
		0001	0370	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	1,650.30	0.00	1,650.30	STA	1,650.30	\$13.00	\$21,453.90
		0010	0380	6061014	GUARDRAIL TYPE A WITH RUBRAIL	113.00	-113.00	0.00	LF	0.00	\$23.50	\$0.00
		0010	0390	6061050	GUARDRAIL TYPE E, 6 FT. POST, 3 FT1.5 IN. SPACING	138.00	-138.00	0.00	LF	0.00	\$23.50	\$0.00
		0010	0400	6061060	MGS GUARDRAIL	21,050.00	1,175.00	22,225.00	LF	22,225.00	\$16.25	\$361,156.25
		0010	0410	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	12,075.00	88.00	12,163.00	LF	12,163.00	\$19.50	\$237,178.50
		0010	0420	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	20.00	4.00	24.00	EA	24.00	\$2,400.00	\$57,600.00

Page 8 of 29 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
016-C02	J4I3222	0010	0430	6061075	MGS LONG SPAN GUARDRAIL SECTION	2.00	-1.00	1.00	EA	1.00	\$2,200.00	\$2,200.00
		0010	0440	6061080	MGS END ANCHOR	35.00	1.00	36.00	EA	36.00	\$800.00	\$28,800.00
		0010	0450	6061081	MGS BRIDGE APPROACH TRANSITION (THRIE-BEAM BRIDGE)	2.00	-2.00	0.00	EA	0.00	\$3,250.00	\$0.00
		0010	0460	6062300A	TRANSITION SECTION, 6.5 FT. POSTS	6.00	-6.00	0.00	EA	0.00	\$350.00	\$0.00
		0010	0470	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	42.00	3.00	45.00	EA	45.00	\$2,300.00	\$103,500.00
		0010	0480	6063017	TYPE C CRASHWORTHY END TERMINAL	3.00	0.00	3.00	EA	3.00	\$18,000.00	\$54,000.00
		0010	0490	6066620	GUARDRAIL ANCHOR, EMBEDDED	1.00	0.00	1.00	EA	1.00	\$4,000.00	\$4,000.00
		0030	0500	9020213	SIGNAL HEAD, TYPE 3S	1.00	0.00	1.00	EA	1.00	\$1,080.00	\$1,080.00
		0030	0510	9020513	SIGNAL HEAD, TYPE 3B	4.00	0.00	4.00	EA	4.00	\$1,165.00	\$4,660.00
		0030	0520	9023450	POST, TYPE BL, LONGEST ARM 50 FT. OR 15.2 M	1.00	0.00	1.00	EA	1.00	\$21,220.00	\$21,220.00
		0030	0530	9025400	CONDUIT, 4 IN., TRENCH WITH TRACER WIRE	10.00	0.00	10.00	LF	10.00	\$75.00	\$750.00
		0030	0540	9028100	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	90.00	0.00	90.00	LF	90.00	\$2.85	\$256.50
		0030	0550	9028311	CABLE, 16 AWG 7 CONDUCTOR	30.00	0.00	30.00	LF	30.00	\$37.00	\$1,110.00
		0030	0560	9029100	BASE, CONCRETE	3.70	0.00	3.70	CUYD	3.70	\$3,600.00	\$13,320.00
		0001	5001	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	0.00	4.00	4.00	EA	4.00	\$1,500.00	\$6,000.00
		0001	5002	4071007	TACK COAT - LOW OR NON-TRACKING	0.00	42,343.00	42,343.00	GAL	44,957.00	\$3.85	\$173,084.45
		0010	5003	6061063	MGS GUARDRAIL, 6 FT. POSTS, 3 FT 1.5 IN. SPACING	0.00	87.50	87.50	LF	87.50	\$34.15	\$2,988.12
		0010	5004	6069903	MISC.MGS Guardrail, 8 Ft. Posts, 3 Ft. 1 1/2 In. Spacing	0.00	50.00	50.00	LF	50.00	\$49.21	\$2,460.50
		0010	5005	6069901	MISC.Guard Cable and Cable Anchor at Route 7	0.00	1.00	1.00	LS	1.00	\$15,067.06	\$15,067.06
		0010	5006	6069902	MISC.Flume Coring for Guardrail Installation	0.00	4.00	4.00	EA	4.00	\$194.25	\$777.00
	Project .	J4I3222 - To	otal Value	Posted to D	Date as of Report Generated Date							\$5,579,287.56
016-C02 Ove	erall - Tota	I Value Pos	sted to Da	ate as of Rep	ort Generated Date							\$5,579,287.56

Page 9 of 29 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0020	2153000	SHAPING SLOPES, CLASS III	11/9/21	11/16/21	2.00	100F	I-70	20.409		29.337		CO 4 is now approved.
0440	6061080	MGS END ANCHOR	11/9/21	11/16/21	1.00	EA	I-70	24.819				CO 4 is now approved.
5003	6061063	MGS GUARDRAIL, 6 FT. POSTS, 3 FT 1.5	11/9/21	11/16/21	87.50	LF	I-70	20.409		29.337		CO 4 is now approved. C & H was contractor but C & H not showing up as contractor selection.
5004	6069903	MISC. GUARDRAIL ITEM	11/9/21	11/16/21	50.00	LF	I-70	20.409		29.337		CO 4 is now approved. C & H was contractor but C & H not showing up as contractor selection.
5005	6069901	MISC. GUARDRAIL ITEM	11/9/21	11/16/21	1.00	LS	I-70 Median east of Route 7	20.610				CO 4 is now approved. C & H was contractor but C & H not showing up as contractor selection.
5006	6069902	MISC. GUARDRAIL ITEM	11/9/21	11/16/21	4.00	EA	WB I-70 at Route BB	225.561				CO 4 is now approved. C & H was contractor but C & H not showing up as contractor selection.

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 4/1/2020 Page 10 of 29



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
J4I3222	0030	MISC. AGGREGATE FOR BASE	Material		16	Oct 19, 2021	SYSTEM	\$52,906.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.		
					16	Oct 19, 2021	SYSTEM	(\$52,906.32)			
					17	Nov 2, 2021	SYSTEM	\$52,906.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.		
					17	Nov 2, 2021	SYSTEM	(\$52,906.32)			
					18	Nov 16, 2021	SYSTEM	\$52,906.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user woodyb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
					18	Nov 16, 2021	SYSTEM	(\$52,906.32)			
				- Total				\$0.00			
			Material - To	tal				\$0.00			
	0030 -	Total						\$0.00			
	0040	BIT. PAVEMENT MIXTURE PG64-22 (BP-2)	Other Item Adjustment	ACAD	16	Oct 19, 2021	frizzm	\$22,863.59	AC adjustments for Line No. 0040. See 201016-C02_J4l3222_Asphalt Roadway Reports Line No. 0040_NW Outer Rd. Oak Grove and 201016-C02_J4l3222_Asphalt Roadway Reports Line No. 0040_Shoulders for details.		
				ACAD - Tota	al			\$22,863.59			
			Other Item A	djustment - T	otal			\$22,863.59			
			Overrun	Overrun	16	Oct 19, 2021	SYSTEM	(\$99,059.59)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL		
					16	Oct 19, 2021	SYSTEM	\$85,243.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 33 on the current Payment Estimate.		
							16	Oct 19, 2021	SYSTEM	\$13,815.69	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 33 on the current Payment Estimate.
					17	Nov 2, 2021	SYSTEM	(\$98,191.66)	Averaged Price Adjustment from this item on all previous payment estimates of '3.67146' is applied (if non-zero).		
				Overrun - T	otal			(\$98,191.66)			
			Overrun - To	Overrun - Total	Overrun - Total				(\$98,191.66)		
			Price FUEL		14	Sep 16, 2021	SYSTEM	\$294.35	Reference Item Price Adjustment Index Adjustment Type applied is FUEL		
					15	15	Oct 4, 2021	SYSTEM	\$15,616.79	Reference Item Price Adjustment Index Adjustment Type applied is FUEL	
					16	Oct 19, 2021	SYSTEM	\$15,595.11	Reference Item Price Adjustment Index Adjustment Type applied is FUEL		
				- Total				\$31,506.25			
			Price FUEL -	Total				\$31,506.25			
	0040 -	Total						(\$43,821.82)			
	0050	ASPH. CONC. MIXTURE PG 76-22 (SP095BSM)	Other Item Adjustment	ACAD	16	Oct 19, 2021	frizzm	\$202,417.60	AC adjustments for Line No. 0050. See 201016-C02_J4l3222_Asphalt Roadway Reports Line No. 0050_Mainline and 201016-C02_J4l3222_Asphalt Roadway Reports Line No. 0050_Ramps for details.		
				ACAD - Tota	al			\$202,417.60			
			Other Item A	djustment - T	otal			\$202,417.60			
			Price FUEL		13	Sep 2, 2021	SYSTEM	\$9,778.05	Reference Item Price Adjustment Index Adjustment Type applied is FUEL		
					14	Sep 16, 2021	SYSTEM	\$39,837.79	Reference Item Price Adjustment Index Adjustment Type applied is FUEL		
					15	Oct 4, 2021	SYSTEM	\$49,754.22	Reference Item Price Adjustment Index Adjustment Type applied is FUEL		
				- Total				\$99,370.06			
			Price FUEL -	Total				\$99,370.06			
	0050 -	Total						\$301,787.66			
	0080	FURN & PLACE CONC MATL FOR FULL DEPTH	Material		10	Jul 1, 2021	SYSTEM	\$81,468.66	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate.		
					10	Jul 1,	SYSTEM	(\$81,468.66)			



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks																
Project	Line	Description	Adjustment Type	Adjustment Type		Date	By	Amount	Remains																
J4I3222	0800	FURN & PLACE	Material			2021																			
		CONC MATL FOR FULL DEPTH			11	Jul 16, 2021	SYSTEM	\$532,325.76	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate.																
					11	Jul 16, 2021	SYSTEM	(\$532,325.76)																	
					12	Aug 17, 2021	SYSTEM	\$532,325.76	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate.																
					12	Aug 17, 2021	SYSTEM	(\$532,325.76)																	
					13	Sep 2, 2021	SYSTEM	\$532,325.76	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user frizzm overridding Payment Estimate Exception 5 on the current Payment Estimate.																
					13	Sep 2, 2021	SYSTEM	(\$532,325.76)																	
				- Total				\$0.00																	
			Material - To	tal				\$0.00																	
	0080 -	Total						\$0.00																	
	0120	DOWEL BAR (DRILLING, FURNISHING AND	Material		10	Jul 1, 2021	SYSTEM	\$595.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user frizzm overridding Payment Estimate Exception 7 on the current Payment Estimate.																
		INST			10	Jul 1, 2021	SYSTEM	(\$595.00)																	
					11	Jul 16, 2021	SYSTEM	\$6,196.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user frizzm overridding Payment Estimate Exception 7 on the current Payment Estimate.																
					11	Jul 16, 2021	SYSTEM	(\$6,196.50)																	
					12	Aug 17, 2021	SYSTEM	\$6,196.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user frizzm overridding Payment Estimate Exception 5 on the current Payment Estimate.																
					12	Aug 17, 2021	SYSTEM	(\$6,196.50)																	
					13	Sep 2, 2021	SYSTEM	\$6,196.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user frizzm overridding Payment Estimate Exception 6 on the current Payment Estimate.																
					13	Sep 2, 2021	SYSTEM	(\$6,196.50)																	
					14	Sep 16, 2021	SYSTEM	\$6,196.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user frizzm overridding Payment Estimate Exception 5 on the current Payment Estimate.																
					14	Sep 16, 2021	SYSTEM	(\$6,196.50)																	
															15	Oct 4, 2021	SYSTEM	\$6,196.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user frizzm overridding Payment Estimate Exception 5 on the current Payment Estimate.						
					15	Oct 4, 2021	SYSTEM	(\$6,196.50)																	
								16	Oct 19, 2021	SYSTEM	\$6,196.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user frizzm overridding Payment Estimate Exception 6 on the current Payment Estimate.													
								16	Oct 19, 2021	SYSTEM	(\$6,196.50)														
									17											17	17	Nov 2, 2021	SYSTEM	\$6,196.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user frizzm overridding Payment Estimate Exception 6 on the current Payment Estimate.
										17	Nov 2, 2021	SYSTEM	(\$6,196.50)												
													18	18	Nov 16, 2021	SYSTEM	\$6,196.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodyb1 overridding Payment Estimate Exception 8 on the current Payment Estimate.							
					18	Nov 16, 2021	SYSTEM	(\$6,196.50)																	
				- Total				\$0.00																	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																
J4I3222	0120	DOWEL BAR (DRILLING, FURNISHING AND INST	Material - To	tal				\$0.00																	
	0120 -	Total						\$0.00																	
	0130	DOWEL BAR (FURNISH AND INSTALL WITH	Material		10	Jul 1, 2021	SYSTEM	\$107.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user frizzm overridding Payment Estimate Exception 8 on the current Payment Estimate.																
		BASK			10	Jul 1, 2021	SYSTEM	(\$107.25)																	
					11	Jul 16, 2021	SYSTEM	\$660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user frizzm overridding Payment Estimate Exception 8 on the current Payment Estimate.																
					11	Jul 16, 2021	SYSTEM	(\$660.00)																	
					12	Aug 17, 2021	SYSTEM	\$660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user frizzm overridding Payment Estimate Exception 6 on the current Payment Estimate.																
					12	Aug 17, 2021	SYSTEM	(\$660.00)																	
									13	Sep 2, 2021	SYSTEM	\$660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 7 on the current Payment Estimate.												
												13	Sep 2, 2021	SYSTEM	(\$660.00)										
																					14	Sep 16, 2021	SYSTEM	\$660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user frizzm overridding Payment Estimate Exception 6 on the current Payment Estimate.
																			14	Sep 16, 2021	SYSTEM	(\$660.00)			
														15	Oct 4, 2021	SYSTEM	\$660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user frizzm overridding Payment Estimate Exception 6 on the current Payment Estimate.							
						15	Oct 4, 2021	SYSTEM	(\$660.00)																
					16	Oct 19, 2021	SYSTEM	\$660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user frizzm overridding Payment Estimate Exception 7 on the current Payment Estimate.																
						16	Oct 19, 2021	SYSTEM	(\$660.00)																
							17	Nov 2, 2021	SYSTEM	\$660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 7 on the current Payment Estimate.														
																17	Nov 2, 2021	SYSTEM	(\$660.00)						
																				18	Nov 16, 2021	SYSTEM	\$660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodyb1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	
					18	Nov 16, 2021	SYSTEM	(\$660.00)																	
				- Total				\$0.00																	
			Material - To	tal				\$0.00																	
	0130 -	Total						\$0.00																	
	0140	TIE BAR (DRILL, FURN & INSTAL) (TYPE L	Material		10	Jul 1, 2021	SYSTEM	\$525.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 11 on the current Payment Estimate.																
			11	11	11	11	1	11	11	10 11 11	11	11					10	Jul 1, 2021	SYSTEM	(\$525.00)					
													11	Jul 16, 2021	SYSTEM	\$2,895.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 11 on the current Payment Estimate.								
													11	Jul 16, 2021	SYSTEM	(\$2,895.00)									
					12	Aug 17, 2021	SYSTEM	\$2,895.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 9 on the current Payment Estimate.																



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4I3222	0140	TIE BAR (DRILL, FURN & INSTAL)	Material		12	Aug 17, 2021	SYSTEM	(\$2,895.00)	
		(TYPE L			13	Sep 2, 2021	SYSTEM	\$2,895.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 10 on the current Payment Estimate.
					13	Sep 2, 2021	SYSTEM	(\$2,895.00)	
					14	Sep 16, 2021	SYSTEM	\$2,895.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user frizzm overridding Payment Estimate Exception 9 on the current Payment Estimate.
					14	Sep 16, 2021	SYSTEM	(\$2,895.00)	
					15	Oct 4, 2021	SYSTEM	\$2,895.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user frizzm overridding Payment Estimate Exception 9 on the current Payment Estimate.
					15	Oct 4, 2021	SYSTEM	(\$2,895.00)	
					16	Oct 19, 2021	SYSTEM	\$2,895.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user frizzm overridding Payment Estimate Exception 10 on the current Payment Estimate.
					16	Oct 19, 2021	SYSTEM	(\$2,895.00)	
					17	Nov 2, 2021	SYSTEM	\$2,895.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 10 on the current Payment Estimate.
					17	Nov 2, 2021	SYSTEM	(\$2,895.00)	
					18	Nov 16, 2021	SYSTEM	\$2,895.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodyb1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					18	Nov 16, 2021	SYSTEM	(\$2,895.00)	
				- Total				\$0.00	
	0140 -	Total	Material - To					\$0.00	
	0140 - 0150	FURN & PLACE BIT. MATL FOR	Material - To		13	Sep 2, 2021	SYSTEM		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Exception 12 on the current Payment Estimate
		FURN & PLACE			13		SYSTEM	\$0.00 \$0.00	
		FURN & PLACE BIT. MATL FOR				2021 Sep 2,		\$0.00 \$0.00 \$16,707.27	Estimate Item Adjustment (0007) due to user frizzm overridding Payment
		FURN & PLACE BIT. MATL FOR			13	2021 Sep 2, 2021 Sep 16,	SYSTEM	\$0.00 \$0.00 \$16,707.27 (\$16,707.27)	Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user frizzm overridding Payment
		FURN & PLACE BIT. MATL FOR			13	2021 Sep 2, 2021 Sep 16, 2021 Sep 16,	SYSTEM SYSTEM	\$0.00 \$0.00 \$16,707.27 (\$16,707.27) \$16,707.27	Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user frizzm overridding Payment
		FURN & PLACE BIT. MATL FOR			13 14	2021 Sep 2, 2021 Sep 16, 2021 Sep 16, 2021 Oct 4,	SYSTEM SYSTEM	\$0.00 \$0.00 \$16,707.27 (\$16,707.27) \$16,707.27	Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user frizzm overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user frizzm overridding Payment
		FURN & PLACE BIT. MATL FOR			13 14 14 15	2021 Sep 2, 2021 Sep 16, 2021 Sep 16, 2021 Oct 4, 2021 Oct 4,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$16,707.27 (\$16,707.27) \$16,707.27 (\$16,707.27)	Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user frizzm overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user frizzm overridding Payment
		FURN & PLACE BIT. MATL FOR			13 14 14 15	2021 Sep 2, 2021 Sep 16, 2021 Sep 16, 2021 Oct 4, 2021 Oct 4, 2021 Oct 4, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$16,707.27 (\$16,707.27) \$16,707.27 (\$16,707.27) \$16,707.27	Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user frizzm overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user frizzm overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user frizzm overridding Payment Estimate Item Adjustment (0011) due to user frizzm overridding Payment
		FURN & PLACE BIT. MATL FOR			13 14 14 15 15 16	2021 Sep 2, 2021 Sep 16, 2021 Sep 16, 2021 Oct 4, 2021 Oct 4, 2021 Oct 19, 2021 Oct 19, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$16,707.27 (\$16,707.27) \$16,707.27 (\$16,707.27) \$16,707.27 (\$16,707.27)	Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user frizzm overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user frizzm overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user frizzm overridding Payment Estimate Item Adjustment (0011) due to user frizzm overridding Payment
		FURN & PLACE BIT. MATL FOR			13 14 14 15 15 16 16 16	2021 Sep 2, 2021 Sep 16, 2021 Sep 16, 2021 Oct 4, 2021 Oct 19, 2021 Oct 19, 2021 Nov 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$16,707.27 (\$16,707.27) \$16,707.27 (\$16,707.27) \$16,707.27 (\$16,707.27) \$16,707.27	Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user frizzm overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user frizzm overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user frizzm overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment
		FURN & PLACE BIT. MATL FOR			13 14 14 15 15 16 16	2021 Sep 2, 2021 Sep 16, 2021 Sep 16, 2021 Oct 4, 2021 Oct 19, 2021 Nov 2, 2021 Nov 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$16,707.27 (\$16,707.27) \$16,707.27 (\$16,707.27) \$16,707.27 (\$16,707.27) \$16,707.27	Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user frizzm overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user frizzm overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user frizzm overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment
		FURN & PLACE BIT. MATL FOR			13 14 14 15 15 16 16 17 17	2021 Sep 2, 2021 Sep 16, 2021 Sep 16, 2021 Oct 4, 2021 Oct 19, 2021 Nov 2, 2021 Nov 16, 16, 16, 16, 16, 16, 16, 16, 16, 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$16,707.27 (\$16,707.27) \$16,707.27 (\$16,707.27) \$16,707.27 (\$16,707.27) \$16,707.27 (\$16,707.27)	Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user frizzm overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user frizzm overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user frizzm overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 12 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
J4I3222	0150	FURN & PLACE	Material - To	tal				\$0.00					
		BIT. MATL FOR CL B PARTIAL	Other Item Adjustment	ACAD	16	Oct 19, 2021	frizzm	\$305.34	AC adjustments for Line No. 0150. See 201016-C02_J4l3222_Asphalt Roadway Reports Line No. 0150_Class B for details.				
				ACAD - Tota	al			\$305.34					
				FUEL	16	Oct 19, 2021	frizzm	\$326.71	Fuel price adjustments for Line No. 0150. See 201016-C02_J4l3222_Asphalt Roadway Reports Line No. 0150_Class B for details.				
				FUEL - Tota	d			\$326.71					
			Other Item A	djustment - T	otal			\$632.05					
	0150 -	Total						\$632.05					
	0170	MISC. PAVEMENT REPAIR	Material		13	Sep 2, 2021	SYSTEM	\$48,255.44	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user frizzm overridding Payment Estimate Exception 13 on the current Payment Estimate.				
					13	Sep 2, 2021	SYSTEM	(\$48,255.44)					
					14	Sep 16, 2021	SYSTEM	\$48,255.44	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user frizzm overridding Payment Estimate Exception 12 on the current Payment Estimate.				
					14	Sep 16, 2021	SYSTEM	(\$48,255.44)					
					15	Oct 4, 2021	SYSTEM	\$48,255.44	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user frizzm overridding Payment Estimate Exception 12 on the current Payment Estimate.				
					15	Oct 4, 2021	SYSTEM	(\$48,255.44)					
								16	Oct 19, 2021	SYSTEM	\$48,255.44	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user frizzm overridding Payment Estimate Exception 13 on the current Payment Estimate.	
					16	Oct 19, 2021	SYSTEM	(\$48,255.44)					
					17	Nov 2, 2021	SYSTEM	\$48,255.44	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user frizzm overridding Payment Estimate Exception 13 on the current Payment Estimate.				
					17	Nov 2, 2021	SYSTEM	(\$48,255.44)					
					18	Nov 16, 2021	SYSTEM	\$48,255.44	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodyb1 overridding Payment Estimate Exception 15 on the current Payment Estimate.				
					18	Nov 16, 2021	SYSTEM	(\$48,255.44)					
				- Total				\$0.00					
			Material - To	tal				\$0.00					
	0170 -	Total						\$0.00					
	0180	MISC. PAVEMENT REPAIR	Other Item Adjustment	ACAD	16	Oct 19, 2021	frizzm	\$8,642.99	AC adjustments for Line No. 0180. See 201016-C02_J4l3222_Asphalt Roadway Reports Line No. 0180_Class C for details.				
				ACAD - Tota	al			\$8,642.99					
					FUEL 16	16	Oct 19, 2021	frizzm	\$9,248.00	Fuel price adjustments for Line No. 0180. See 201016-C02_J4l3222_Asphalt Roadway Reports Line No. 0180_Class C for details.			
				FUEL - Tota	ıl			\$9,248.00					
			Other Item A	djustment - T	otal			\$17,890.99					
			Other Item Ad			Overrun Overrun	13	Sep 2, 2021	SYSTEM	\$937.92	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user frizzm overridding Payment Estimate Exception 17 on the current Payment Estimate.		
				13 14 14 15	13	Sep 2, 2021	SYSTEM	(\$937.92)					
					1		1	14	14	Sep 16, 2021	SYSTEM	(\$937.92)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
							14	Sep 16, 2021	SYSTEM	\$937.92	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user frizzm overridding Payment Estimate Exception 16 on the current Payment Estimate.		
						15	Oct 4, 2021	SYSTEM	(\$937.92)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).			
							15	Oct 4, 2021	SYSTEM	\$937.92	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user frizzm overridding Payment		



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
222	0180	MISC. PAVEMENT	Overrun	Overrun					Estimate Exception 26 on the current Payment Estimate.
		REPAIR			16	Oct 19, 2021	SYSTEM	(\$937.92)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					16	Oct 19, 2021	SYSTEM	\$937.92	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user frizzm overridding Payment Estimate Exception 34 on the current Payment Estimate.
					17	Nov 2, 2021	SYSTEM	(\$937.92)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				Overrun - T	otal			(\$937.92)	
			Overrun - To	tal				(\$937.92)	
	0180 -	Total						\$16,953.07	
	0190	CONSTRUCTION SIGNS	Material		10	Jul 1, 2021	SYSTEM	\$3,914.65	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 14 on the current Payment Estimate.
					10	Jul 1, 2021	SYSTEM	(\$3,914.65)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0190 -	Total						\$0.00	
	0200	FLAG ASSEMBLY	Material		10	Jul 1, 2021	SYSTEM	\$30.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Exception 15 on the current Payment Estimate.
					10	Jul 1, 2021	SYSTEM	(\$30.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0200 -	Total						\$0.00	
	0210	CHANNELIZER (TRIM LINE) WITH LIGHT	Material		10	Jul 1, 2021	SYSTEM	\$4,940.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user frizzm overridding Payment Estimate Exception 16 on the current Payment Estimate.
					10	Jul 1, 2021	SYSTEM	(\$4,940.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0210 -	Total						\$0.00	
	0230	FLASHING ARROW PANEL	Material		10	Jul 1, 2021	SYSTEM	\$8,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user frizzm overridding Payment Estimate Exception 17 on the current Payment Estimate.
					10	Jul 1, 2021	SYSTEM	(\$8,000.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0230 -	Total						\$0.00	
	0250	CONCRETE TRAFFIC BARRIER, TYPE A	Material		16	Oct 19, 2021	SYSTEM	\$15,759.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user frizzm overridding Payment Estimate Exception 17 on the current Payment Estimate.
					16	Oct 19, 2021	SYSTEM	(\$15,759.00)	
					17	Nov 2, 2021	SYSTEM	\$6,618.78	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user frizzm overridding Payment Estimate Exception 17 on the current Payment Estimate.
					17	Nov 2, 2021	SYSTEM	(\$6,618.78)	
					18	Nov 16, 2021	SYSTEM	\$6,618.78	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodyb1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					18	Nov 16, 2021	SYSTEM	(\$6,618.78)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0250 -	Total						\$0.00	



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
22	0280	PREF THERMO PVMT MARK, 24 IN WHIT	Material		17	Nov 2, 2021	SYSTEM	\$6,642.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user frizzm overridding Payment Estimate Exception 23 on the current Payment Estimate.			
					17	Nov 2, 2021	SYSTEM	(\$6,642.00)				
					18	Nov 16, 2021	SYSTEM	\$6,642.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodyb1 overridding Payment Estimate Exception 25 on the current Payment Estimate.			
					18	Nov 16, 2021	SYSTEM	(\$6,642.00)				
				- Total				\$0.00				
			Material - To	tal				\$0.00				
	0280 -	Total						\$0.00				
02	0290	PREF THERMO PVMT MARK, 24 IN YELLOW	Material		17	Nov 2, 2021	SYSTEM	\$7,614.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user frizzm overridding Payment Estimate Exception 24 on the current Payment Estimate.			
					17	Nov 2, 2021	SYSTEM	(\$7,614.00)				
					18	Nov 16, 2021	SYSTEM	\$7,614.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodyb1 overridding Paymen Estimate Exception 26 on the current Payment Estimate.			
					18	Nov 16, 2021	SYSTEM	(\$7,614.00)				
				- Total				\$0.00				
			Material - To	tal				\$0.00				
	0290 -	Total						\$0.00				
	0290 - T		PREF THERMO Ma	Material		17	Nov 2, 2021	SYSTEM	\$6,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user frizzm overridding Payment Estimate Exception 25 on the current Payment Estimate.		
				LT/RT ARROW	LIMI ARROW	LI/RT ARROW			17	Nov 2, 2021	SYSTEM	(\$6,250.00)
						18	Nov 16, 2021	SYSTEM	\$6,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user woodyb1 overridding Paymen Estimate Exception 27 on the current Payment Estimate.		
						18	18	Nov 16, 2021	SYSTEM	(\$6,250.00)	(\$6,250.00)	
				- Total				\$0.00				
			Material - To	tal				\$0.00				
	0300 -	Total						\$0.00				
	0310	6 IN. WHITE HIGH BUILD WATERBORNE	Material		17	Nov 2, 2021	SYSTEM	\$20,225.92	This adjustment offsets the original system-generated Material Payment			
									Estimate Item Adjustment (0013) due to user frizzm overridding Payment Estimate Exception 26 on the current Payment Estimate.			
		PAINT			17	Nov 2, 2021	SYSTEM	(\$20,225.92)				
		PAINT		- Total	17		SYSTEM	(\$20,225.92)				
		PAINT	Material - To		17		SYSTEM	(, , ,				
	0310 -		Material - To		17		SYSTEM	\$0.00				
	0310 - 0320	Total 6 IN. YELLOW HIGH BUILD WATERBORNE			17		SYSTEM	\$0.00 \$0.00				
		Total 6 IN. YELLOW HIGH BUILD				2021 Nov 2,		\$0.00 \$0.00 \$0.00	Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user frizzm overridding Payment			
		Total 6 IN. YELLOW HIGH BUILD WATERBORNE			17	Nov 2, 2021	SYSTEM	\$0.00 \$0.00 \$0.00 \$16,346.72	Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user frizzm overridding Payment			
		Total 6 IN. YELLOW HIGH BUILD WATERBORNE		tal - Total	17	Nov 2, 2021	SYSTEM	\$0.00 \$0.00 \$0.00 \$16,346.72 (\$16,346.72)	Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user frizzm overridding Payment			
		Total 6 IN. YELLOW HIGH BUILD WATERBORNE PAINT	Material	tal - Total	17	Nov 2, 2021	SYSTEM	\$0.00 \$0.00 \$0.00 \$16,346.72 (\$16,346.72)	Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user frizzm overridding Payment			
	0320	Total 6 IN. YELLOW HIGH BUILD WATERBORNE PAINT Total 12 IN. WHITE HIGH BUILD WATERBORNE	Material	tal - Total	17	Nov 2, 2021	SYSTEM	\$0.00 \$0.00 \$0.00 \$16,346.72 (\$16,346.72) \$0.00	Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user frizzm overridding Payment			
	0320	Total 6 IN. YELLOW HIGH BUILD WATERBORNE PAINT Total 12 IN. WHITE HIGH BUILD	Material Material - To	tal - Total	17	Nov 2, 2021 Nov 2, 2021 Nov 2, 2021	SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 \$16,346.72 (\$16,346.72) \$0.00 \$0.00	Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user frizzm overridding Payment Estimate Exception 28 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user frizzm overridding Payment			
	0320	Total 6 IN. YELLOW HIGH BUILD WATERBORNE PAINT Total 12 IN. WHITE HIGH BUILD WATERBORNE	Material Material - To	tal - Total	17 17 17	Nov 2, 2021 Nov 2, 2021 Nov 2, 2021 Nov 2,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$10.00 \$16,346.72 (\$16,346.72) \$0.00 \$0.00 \$1,813.80	Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user frizzm overridding Payment Estimate Exception 28 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user frizzm overridding Payment			



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks					
J4I3222	0330 -	Total						\$0.00						
	0350	COLDMILLING BIT. PAVT FOR REM OF SURF.	Overrun	Overrun	16	Oct 19, 2021	SYSTEM	\$1,864.71	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user frizzm overridding Payment Estimate Exception 35 on the current Payment Estimate.					
					16	Oct 19, 2021	SYSTEM	(\$1,864.71)						
					17	Nov 2, 2021	SYSTEM	(\$1,864.71)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).					
				Overrun - T	otal			(\$1,864.71)						
			Overrun - To	tal				(\$1,864.71)						
	0350 -	Total						(\$1,864.71)						
	0380	GUARDRAIL TYPE A WITH	Construction Stockpile		9	Jun 17, 2021	SYSTEM	(\$1,846.25)	Payment Estimate Item Adjustment generated Stockpile Transaction					
		RUBRAIL		- Total				(\$1,846.25)						
			Construction	Stockpile - 1	Γotal			(\$1,846.25)						
			Construction Stockpile		1	Feb 16, 2021	SYSTEM	\$1,846.25	Payment Estimate Item Adjustment generated Stockpile Transaction					
			STMI	- Total				\$1,846.25						
			Construction	Stockpile S	ΓΜΙ - Total			\$1,846.25						
			Material		9	Jun 17, 2021	SYSTEM	\$2,655.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.					
					9	Jun 17, 2021	SYSTEM	(\$2,655.50)						
								10	Jul 1, 2021	SYSTEM	\$2,655.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.		
						10	Jul 1, 2021	SYSTEM	(\$2,655.50)					
						11	Jul 16, 2021	SYSTEM	\$2,655.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.				
								11	Jul 16, 2021	SYSTEM	(\$2,655.50)			
						12	Aug 17, 2021	SYSTEM	\$2,655.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.				
					12	Aug 17, 2021	SYSTEM	M (\$2,655.50)						
					13	Sep 2, 2021	SYSTEM	\$2,655.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user frizzm overridding Payment Estimate Exception 2 on the current Payment Estimate.					
					13	Sep 2, 2021	SYSTEM	(\$2,655.50)						
										17	Nov 2, 2021	SYSTEM	\$2,655.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user frizzm overridding Payment Estimate Exception 3 on the current Payment Estimate.
					17	Nov 2, 2021	SYSTEM	(\$2,655.50)						
				- Total				\$0.00						
			Material - Tot	tal				\$0.00						
			Overrun	Overrun	16	Oct 19, 2021	SYSTEM	(\$2,655.50)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).					
					16	Oct 19, 2021	SYSTEM	\$2,655.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user frizzm overridding Payment Estimate Exception 36 on the current Payment Estimate.					
				Overrun - T	otal			\$0.00						
			Overrun - To	tal				\$0.00						
	0380 -	Total						\$0.00						
	0390	GUARDRAIL TYPE E, 6 FT. POST, 3 FT1.5	Material		7	May 17, 2021	SYSTEM	\$1,175.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.					



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks															
J4I3222	0390	GUARDRAIL TYPE E, 6 FT.	Material		7	May 17, 2021	SYSTEM	(\$1,175.00)																
		POST, 3 FT1.5			8	Jun 1, 2021	SYSTEM	\$2,056.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.															
					8	Jun 1, 2021	SYSTEM	(\$2,056.25)																
				- Total				\$0.00																
			Material - Tot	al				\$0.00																
	0390 -	Total						\$0.00																
	0400	MGS GUARDRAIL	Construction Stockpile		2	Mar 3, 2021	SYSTEM	(\$36,103.78)	Payment Estimate Item Adjustment generated Stockpile Transaction															
					3	Mar 16, 2021	SYSTEM	(\$40,951.63)	Payment Estimate Item Adjustment generated Stockpile Transaction															
					4	Apr 2, 2021	SYSTEM	(\$18,753.56)	Payment Estimate Item Adjustment generated Stockpile Transaction															
					5	Apr 16, 2021	SYSTEM	(\$24,116.81)	Payment Estimate Item Adjustment generated Stockpile Transaction															
					6	May 1, 2021	SYSTEM	(\$9,185.41)	Payment Estimate Item Adjustment generated Stockpile Transaction															
					7	May 17, 2021	SYSTEM	(\$53,836.73)	Payment Estimate Item Adjustment generated Stockpile Transaction															
					8	Jun 1, 2021	SYSTEM	(\$5,230.58)	Payment Estimate Item Adjustment generated Stockpile Transaction															
					9	Jun 17, 2021	SYSTEM	(\$23,843.75)	Payment Estimate Item Adjustment generated Stockpile Transaction															
				- Total				(\$212,022.25)																
			Construction	Stockpile - 1	「otal			(\$212,022.25)																
			Construction Stockpile		1	Feb 16, 2021	SYSTEM	\$212,022.25	Payment Estimate Item Adjustment generated Stockpile Transaction															
			STMI	- Total				\$212,022.25																
			Construction	Stockpile S1	「MI - Total			\$212,022.25																
			Material		2	Mar 3, 2021	SYSTEM	\$57,484.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.															
							2	Mar 3, 2021	SYSTEM	(\$57,484.38)														
					3	Mar 16, 2021	SYSTEM	\$122,687.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.															
					3	Mar 16, 2021	SYSTEM	(\$122,687.50)																
												4	Apr 2, 2021	SYSTEM	\$152,546.88	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.								
																4	Apr 2, 2021	SYSTEM	(\$152,546.88)					
																					5	Apr 16, 2021	SYSTEM	\$190,945.62
					5	Apr 16, 2021	SYSTEM	(\$190,945.62)																
					6	May 1, 2021	SYSTEM	\$205,570.62	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.															
					6	May 1, 2021	SYSTEM	(\$205,570.62)																
					7	May 17, 2021	SYSTEM	\$291,289.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user frizzm overridding Payment Estimate Exception 2 on the current Payment Estimate.															
					7	May 17, 2021	SYSTEM	(\$291,289.38)																
					8	Jun 1, 2021	SYSTEM	\$299,617.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user frizzm overridding Payment															



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks															
			Туре	Adjustment Type	Number	Date	Ву																	
J4I3222	0400	MGS GUARDRAIL	Material						Estimate Exception 2 on the current Payment Estimate.															
					8	Jun 1, 2021	SYSTEM	(\$299,617.50)																
				- Total				\$0.00																
			Material - Tot	tal				\$0.00																
			Overrun	Overrun	9	Jun 17, 2021	SYSTEM	(\$4,273.75)																
					16	Oct 19, 2021	SYSTEM	\$4,273.75	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',16.25000 - 16.25000, 'is applied (if non-zero).															
				Overrun - T	otal			\$0.00																
			Overrun - To	tal				\$0.00																
	0400 -	Total						\$0.00																
	0410	MGS GUARDRAIL, 8 FT. POSTS, 6	Construction Stockpile		3	Mar 16, 2021	SYSTEM	(\$11,862.83)	Payment Estimate Item Adjustment generated Stockpile Transaction															
		FT 3 IN			4	Apr 2, 2021	SYSTEM	(\$9,705.95)	Payment Estimate Item Adjustment generated Stockpile Transaction															
					5	Apr 16, 2021	SYSTEM	(\$29,271.91)	Payment Estimate Item Adjustment generated Stockpile Transaction															
					6	May 1, 2021	SYSTEM	(\$51,461.31)	Payment Estimate Item Adjustment generated Stockpile Transaction															
				- Total				(\$102,302.00)																
						Construction	Stockpile - 1	Total			(\$102,302.00)													
			Construction Stockpile STMI		1	Feb 16, 2021	SYSTEM	\$102,302.00	Payment Estimate Item Adjustment generated Stockpile Transaction															
			STIVII	- Total				\$102,302.00																
			Construction	Stockpile S	TMI - Total			\$102,302.00																
			Material		3	Mar 16, 2021	SYSTEM	\$18,768.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user frizzm overridding Payment Estimate Exception 2 on the current Payment Estimate.															
					3	Mar 16, 2021	SYSTEM	(\$18,768.75)																
						4	Apr 2, 2021	SYSTEM	\$34,125.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user frizzm overridding Payment Estimate Exception 2 on the current Payment Estimate.														
								4	Apr 2, 2021	SYSTEM	(\$34,125.00)													
					5	Apr 16, 2021	SYSTEM	\$80,437.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user frizzm overridding Payment Estimate Exception 2 on the current Payment Estimate.															
													5	Apr 16, 2021	SYSTEM	(\$80,437.50)								
												6	May 1, 2021	SYSTEM	\$184,518.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user frizzm overridding Payment Estimate Exception 2 on the current Payment Estimate.								
																				6	May 1, 2021	SYSTEM	(\$184,518.75)	
																					7	May 17, 2021	SYSTEM	\$214,743.75
					7	May 17, 2021	SYSTEM	(\$214,743.75)																
					8	Jun 1, 2021	SYSTEM	\$214,743.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user frizzm overridding Payment Estimate Exception 3 on the current Payment Estimate.															
					8	Jun 1, 2021	SYSTEM	(\$214,743.75)																
					9	Jun 17, 2021	SYSTEM	\$239,118.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 2 on the current Payment Estimate.															
							9	Jun 17, 2021	SYSTEM	(\$239,118.75)														
					10	Jul 1,	SYSTEM	\$239,118.75	This adjustment offsets the original system-generated Material Payment															



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																								
J4I3222	0410	8 FT. POSTS, 6	Material			2021			Estimate Item Adjustment (0002) due to user frizzm overridding Payment Estimate Exception 2 on the current Payment Estimate.																								
		FT 3 IN			10	Jul 1, 2021	SYSTEM	(\$239,118.75)																									
					11	Jul 16, 2021	SYSTEM	\$239,118.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user frizzm overridding Payment Estimate Exception 2 on the current Payment Estimate.																								
					11	Jul 16, 2021	SYSTEM	(\$239,118.75)																									
					12	Aug 17, 2021	SYSTEM	\$239,118.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user frizzm overridding Payment Estimate Exception 2 on the current Payment Estimate.																								
					12	Aug 17, 2021	SYSTEM	(\$239,118.75)																									
					13	Sep 2, 2021	SYSTEM	\$239,118.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user frizzm overridding Payment Estimate Exception 3 on the current Payment Estimate.																								
					13	Sep 2, 2021	SYSTEM	(\$239,118.75)																									
					14	Sep 16, 2021	SYSTEM	\$239,118.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user frizzm overridding Payment Estimate Exception 3 on the current Payment Estimate.																								
					14	Sep 16, 2021	SYSTEM	(\$239,118.75)																									
					15	Oct 4, 2021	SYSTEM	\$239,118.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user frizzm overridding Payment Estimate Exception 3 on the current Payment Estimate.																								
							15	Oct 4, 2021	SYSTEM	(\$239,118.75)																							
						16	Oct 19, 2021	SYSTEM	\$239,118.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate.																							
								16	Oct 19, 2021	SYSTEM	(\$239,118.75)																						
						17	Nov 2, 2021	SYSTEM	\$239,118.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate.																							
					17	Nov 2, 2021	SYSTEM	(\$239,118.75)																									
					18	Nov 16, 2021	SYSTEM	\$239,118.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodyb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.																								
					18	Nov 16, 2021	SYSTEM	(\$239,118.75)																									
				- Total				\$0.00																									
			Material - To	Overrun	9	Jun 17, 2021	SYSTEM	\$0.00 \$3,656.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 5 on the current Payment Estimate. Material Insufficiency Quantity 12262.500;																								
					9	Jun 17,	SYSTEM	(\$3,656.25)	Overrun Quantity Balance 187.50.																								
					10	Jul 1, 2021	SYSTEM	(\$3,656.25)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).																								
																														10	Jul 1, 2021	SYSTEM	\$3,656.25
							11	Jul 16, 2021	SYSTEM	(\$3,656.25)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).																						
									11	Jul 16, 2021	SYSTEM	\$3,656.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 14 on the current Payment Estimate. Material Insufficiency Quantity 12262.500; Overrun Quantity Balance 187.50.																				
													12	Aug 17, 2021	SYSTEM	(\$3,656.25)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).																
					12	Aug 17,	SYSTEM	\$3,656.25	This adjustment offsets the original system-generated Overrun Payment																								



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks										
413222	0410	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN	Overrun	Overrun		2021			Estimate Item Adjustment (0001) overridding Payment Estimate Exception 11 on the current Payment Estimate. Material Insufficiency Quantity 12262.500; Overrun Quantity Balance 187.50.										
					13	Sep 2, 2021	SYSTEM	(\$3,656.25)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).										
					13	Sep 2, 2021	SYSTEM	\$3,656.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) overridding Payment Estimate Exception 18 on the current Payment Estimate. Material Insufficiency Quantity 12262.500; Overrun Quantity Balance 187.50.										
					14	Sep 16, 2021	SYSTEM	(\$3,656.25)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).										
					14	Sep 16, 2021	SYSTEM	\$3,656.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) overridding Payment Estimate Exception 17 on the current Payment Estimate. Material Insufficiency Quantity 12262.500; Overrun Quantity Balance 187.50.										
					15	Oct 4, 2021	SYSTEM	(\$3,656.25)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).										
					15	Oct 4, 2021	SYSTEM	\$3,656.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) overridding Payment Estimate Exception 27 on the current Payment Estimate. Material Insufficiency Quantity 12262.500; Overrun Quantity Balance 187.50.										
				Overrun - T	otal			\$0.00											
			Overrun - To	tal				\$0.00											
	0410 - 0420	MGS BRIDGE	Construction		2	Mar 3,	SYSTEM	\$0.00 (\$1,468.00)	Payment Estimate Item Adjustment generated Stockpile Transaction										
		APP. TRANS SEC (REG/NO CURB)	Stockpile		3	2021 Mar 16, 2021	SYSTEM	(\$1,468.00)	Payment Estimate Item Adjustment generated Stockpile Transaction										
					4	Apr 2, 2021	SYSTEM	(\$7,340.00)	Payment Estimate Item Adjustment generated Stockpile Transaction										
															5	Apr 16, 2021	SYSTEM	(\$5,872.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
					6	May 1, 2021	SYSTEM	(\$4,404.00)	Payment Estimate Item Adjustment generated Stockpile Transaction										
					7	May 17, 2021	SYSTEM	(\$8,808.00)	Payment Estimate Item Adjustment generated Stockpile Transaction										
				- Total				(\$29,360.00)											
				ı Stockpile - 1		Fab 16	CVCTEM	(\$29,360.00)	Downant Fating to Hom Adjustment gangeted Chalmile Transaction										
			Construction Stockpile STMI		1	Feb 16, 2021	SYSTEM	\$29,360.00	Payment Estimate Item Adjustment generated Stockpile Transaction										
				- Total				\$29,360.00											
			Overrun	Stockpile ST			SYSTEM	\$29,360.00	This adjustment effects the original system reported Overwy Payment										
			Overrun	Overrun	7	May 17, 2021	STSTEM	\$2,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 8 on the current Payment Estimate.										
					7	May 17, 2021	SYSTEM	(\$2,400.00)											
					8	Jun 1, 2021	SYSTEM	(\$2,400.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).										
					8	Jun 1, 2021	SYSTEM	\$2,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 8 on the current Payment Estimate.										
					9	Jun 17, 2021	SYSTEM	(\$2,400.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).										
					9	Jun 17, 2021	SYSTEM	(\$2,400.00)											
					16	Oct 19, 2021	SYSTEM	\$4,800.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',2400.00000 - 2400.00000, 'is applied (if non-zero).										
				Overrun - T	otal			\$0.00											
			Overrun - To	tal				\$0.00											
	0420 -							\$0.00											
	0430	MGS LONG SPAN GUARDRAIL	Construction Stockpile		5	Apr 16, 2021	SYSTEM	(\$1,155.85)	Payment Estimate Item Adjustment generated Stockpile Transaction										



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																						
J4I3222	0430	SECTION	Construction Stockpile		16	Oct 19, 2021	SYSTEM	(\$1,155.85)	Payment Estimate Item Adjustment generated Stockpile Transaction																						
				- Total				(\$2,311.70)																							
			Construction	Stockpile - 1	Γotal			(\$2,311.70)																							
			Construction Stockpile STMI		1	Feb 16, 2021	SYSTEM	\$2,311.70	Payment Estimate Item Adjustment generated Stockpile Transaction																						
			STIVII	- Total				\$2,311.70																							
			Construction	Stockpile S	TMI - Total			\$2,311.70																							
			Material		5	Apr 16, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate.																						
					5	Apr 16, 2021	SYSTEM	(\$2,200.00)																							
				6	May 1, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate.																							
					6	May 1, 2021	SYSTEM	(\$2,200.00)																							
					7	May 17, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Exception 5 on the current Payment Estimate.																						
								7	May 17, 2021	SYSTEM	(\$2,200.00)																				
						8	Jun 1, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 5 on the current Payment Estimate.																					
									8	Jun 1, 2021	SYSTEM	(\$2,200.00)																			
					9	Jun 17, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user frizzm overridding Payment Estimate Exception 3 on the current Payment Estimate.																						
										9	Jun 17, 2021	SYSTEM	(\$2,200.00)																		
					10	Jul 1, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user frizzm overridding Payment Estimate Exception 3 on the current Payment Estimate.																						
					10	Jul 1, 2021	SYSTEM	(\$2,200.00)																							
					11	Jul 16, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Exception 3 on the current Payment Estimate.																						
					11	Jul 16, 2021	SYSTEM	(\$2,200.00)																							
												12	Aug 17, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Exception 3 on the current Payment Estimate.															
																			12	Aug 17, 2021	SYSTEM	(\$2,200.00)									
																							13	Sep 2, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate.				
																	13	Sep 2, 2021	SYSTEM	(\$2,200.00)											
					14	Sep 16, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate.																						
					14	Sep 16, 2021	SYSTEM	(\$2,200.00)																							
																										1	15	Oct 4, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate.
					15	Oct 4, 2021	SYSTEM	(\$2,200.00)																							
							16	Oct 19, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user frizzm overridding Payment Estimate Exception 5 on the current Payment Estimate.																				



ct L												
	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
2 0	0430		Material	31	16	Oct 19, 2021	SYSTEM	(\$2,200.00)				
					17	Nov 2, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user frizzm overridding Payment Estimate Exception 5 on the current Payment Estimate.			
					17	Nov 2, 2021	SYSTEM	(\$2,200.00)				
					18	Nov 16, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user woodyb1 overridding Payment Estimate Exception 6 on the current Payment Estimate.			
					18	Nov 16, 2021	SYSTEM	(\$2,200.00)				
				- Total				\$0.00				
			Material - To	tal				\$0.00				
d	0430 -	Total						\$0.00				
C	0440	MGS END ANCHOR	Construction Stockpile		2	Mar 3, 2021	SYSTEM	(\$1,054.02)	Payment Estimate Item Adjustment generated Stockpile Transaction			
					3	Mar 16, 2021	SYSTEM	(\$1,054.02)	Payment Estimate Item Adjustment generated Stockpile Transaction			
					4	Apr 2, 2021	SYSTEM	(\$2,635.06)	Payment Estimate Item Adjustment generated Stockpile Transaction			
					5	Apr 16, 2021	SYSTEM	(\$4,216.09)	Payment Estimate Item Adjustment generated Stockpile Transaction			
					6	May 1, 2021	SYSTEM	(\$3,688.81)	Payment Estimate Item Adjustment generated Stockpile Transaction			
				- Total				(\$12,648.00)				
			Construction Stockpile - Total					(\$12,648.00)				
			Construction Stockpile STMI		1	Feb 16, 2021	SYSTEM	\$12,648.00	Payment Estimate Item Adjustment generated Stockpile Transaction			
				- Total				\$12,648.00				
			Construction	Stockpile S	ΓΜΙ - Total			\$12,648.00				
			Overrun			Overrun	Overrun	9	Jun 17, 2021	SYSTEM	(\$1,600.00)	
							16	Oct 19, 2021	SYSTEM	(\$800.00)	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user frizzm overridding Payment Estimate Exception 38 on the current Payment Estimate.	
						16	Oct 19, 2021	SYSTEM	\$800.00	Unit price based on averaged overrun adjustments for installed quantity on a previous payment estimates. Price Adjustments of ',800.00000 - 800.00000,		
									applied (if non-zero).			
					17	Nov 2, 2021	SYSTEM	\$1,600.00	applied (if non-zero). Unit price based on averaged overrun adjustments for installed quantity on a			
				Overrun - T			SYSTEM	\$1,600.00 \$0.00	applied (if non-zero). Unit price based on averaged overrun adjustments for installed quantity on a previous payment estimates. Price Adjustments of ',800.00000 - 800.00000, applied (if non-zero).			
			Overrun - To				SYSTEM		applied (if non-zero). Unit price based on averaged overrun adjustments for installed quantity on a previous payment estimates. Price Adjustments of ',800.00000 - 800.00000, applied (if non-zero).			
0	0440 -	Total	Overrun - To				SYSTEM	\$0.00	applied (if non-zero). Unit price based on averaged overrun adjustments for installed quantity on a previous payment estimates. Price Adjustments of ',800.00000 - 800.00000, applied (if non-zero).			
	0440 - 0450	MGS BR APP TRANSITION	Construction Stockpile				SYSTEM	\$0.00 \$0.00	applied (if non-zero). Unit price based on averaged overrun adjustments for installed quantity on a previous payment estimates. Price Adjustments of ',800.00000 - 800.00000, applied (if non-zero).			
		MGS BR APP	Construction		otal	2021 Feb 16,		\$0.00 \$0.00 \$0.00	applied (if non-zero). Unit price based on averaged overrun adjustments for installed quantity on a previous payment estimates. Price Adjustments of ',800.00000 - 800.00000, applied (if non-zero).			
		MGS BR APP TRANSITION (THRIE-BEAM	Construction Stockpile STMI	tal	otal 1	Feb 16, 2021		\$0.00 \$0.00 \$0.00 \$4,134.00	applied (if non-zero). Unit price based on averaged overrun adjustments for installed quantity on a previous payment estimates. Price Adjustments of ',800.00000 - 800.00000, applied (if non-zero).			
0		MGS BR APP TRANSITION (THRIE-BEAM BRIDGE	Construction Stockpile STMI	tal - Total	otal 1	Feb 16, 2021		\$0.00 \$0.00 \$0.00 \$4,134.00 \$4,134.00	applied (if non-zero). Unit price based on averaged overrun adjustments for installed quantity on a previous payment estimates. Price Adjustments of ',800.00000 - 800.00000, applied (if non-zero).			
0	0450	MGS BR APP TRANSITION (THRIE-BEAM BRIDGE	Construction Stockpile STMI	tal - Total	otal 1	Feb 16, 2021		\$0.00 \$0.00 \$0.00 \$4,134.00 \$4,134.00	applied (if non-zero). Unit price based on averaged overrun adjustments for installed quantity on a previous payment estimates. Price Adjustments of ',800.00000 - 800.00000, applied (if non-zero).			
0	0450 0450 -	MGS BR APP TRANSITION (THRIE-BEAM BRIDGE Total TRANSITION SECTION, 6.5 FT.	Construction Stockpile STMI	tal - Total	otal 1 FMI - Total	Feb 16, 2021	SYSTEM	\$0.00 \$0.00 \$0.00 \$4,134.00 \$4,134.00 \$4,134.00	applied (if non-zero). Unit price based on averaged overrun adjustments for installed quantity on a previous payment estimates. Price Adjustments of ',800.00000 - 800.00000, applied (if non-zero). Payment Estimate Item Adjustment generated Stockpile Transaction This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user frizzm overridding Payment			
0	0450 0450 -	MGS BR APP TRANSITION (THRIE-BEAM BRIDGE Total TRANSITION SECTION, 6.5 FT.	Construction Stockpile STMI	tal - Total	1 IMI - Total	Feb 16, 2021 May 17, 2021 May 17,	SYSTEM	\$0.00 \$0.00 \$0.00 \$4,134.00 \$4,134.00 \$4,134.00 \$700.00	applied (if non-zero). Unit price based on averaged overrun adjustments for installed quantity on a previous payment estimates. Price Adjustments of ',800.00000 - 800.00000, applied (if non-zero). Payment Estimate Item Adjustment generated Stockpile Transaction This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user frizzm overridding Payment			
0	0450 0450 -	MGS BR APP TRANSITION (THRIE-BEAM BRIDGE Total TRANSITION SECTION, 6.5 FT.	Construction Stockpile STMI	tal - Total	otal 1 IMI - Total 7	Feb 16, 2021 May 17, 2021 May 17, 2021 Jun 1,	SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 \$4,134.00 \$4,134.00 \$4,134.00 \$700.00	applied (if non-zero). Unit price based on averaged overrun adjustments for installed quantity on a previous payment estimates. Price Adjustments of ',800.00000 - 800.00000, applied (if non-zero). Payment Estimate Item Adjustment generated Stockpile Transaction This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user frizzm overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment			
0	0450 0450 -	MGS BR APP TRANSITION (THRIE-BEAM BRIDGE Total TRANSITION SECTION, 6.5 FT.	Construction Stockpile STMI	tal - Total	1 TMI - Total 7 7 8	Feb 16, 2021 May 17, 2021 May 17, 2021 Jun 1, 2021 Jun 1, 1,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 \$4,134.00 \$4,134.00 \$4,134.00 \$700.00 (\$700.00)	applied (if non-zero). Unit price based on averaged overrun adjustments for installed quantity on a previous payment estimates. Price Adjustments of ',800.00000 - 800.00000, applied (if non-zero). Payment Estimate Item Adjustment generated Stockpile Transaction This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user frizzm overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment			



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4I3222	0460 -	Total						\$0.00	
	0470	TYPE A CRASHWORTHY	Construction Stockpile		2	Mar 3, 2021	SYSTEM	(\$4,494.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		END TERMINAL (MASH)			3	Mar 16, 2021	SYSTEM	(\$2,996.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
					4	Apr 2, 2021	SYSTEM	(\$5,992.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
					5	Apr 16, 2021	SYSTEM	(\$14,980.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
					6	May 1, 2021	SYSTEM	(\$14,980.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
					7	May 17, 2021	SYSTEM	(\$13,482.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
					8	Jun 1, 2021	SYSTEM	(\$5,992.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$62,916.00)	
			Construction	ion Stockpile - Total				(\$62,916.00)	
			Construction Stockpile STMI		1	Feb 16, 2021	SYSTEM	\$62,916.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			OTIVII	- Total				\$62,916.00	
			Construction	Stockpile S	ΓMI - Total			\$62,916.00	
			Overrun	Overrun	9	Jun 17, 2021	SYSTEM	(\$6,900.00)	
					16	Oct 19, 2021	SYSTEM	\$6,900.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',2300.00000 - 2300.00000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	0470 -	Total						\$0.00	
	0480	TYPE C CRASHWORTHY END TERMINAL	Construction Stockpile		17	Nov 2, 2021	SYSTEM	(\$35,600.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$35,600.00)	
			Construction	Stockpile - 1	Total			(\$35,600.00)	
			Construction Stockpile STMI		1 Feb 16, SYSTEM 2021			\$35,600.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$35,600.00	
			Construction	Stockpile STMI - Total				\$35,600.00	
	0480 -	Total						\$0.00	
	0490	GUARDRAIL ANCHOR, EMBEDDED	Construction Stockpile		9	Jun 17, 2021	SYSTEM	(\$2,412.50)	Payment Estimate Item Adjustment generated Stockpile Transaction
		LIVIDEDDED		- Total				(\$2,412.50)	
			Construction	Stockpile - 1	Γotal			(\$2,412.50)	
			Construction Stockpile STMI		1	Feb 16, 2021	SYSTEM	\$2,412.50	Payment Estimate Item Adjustment generated Stockpile Transaction
			511111	- Total				\$2,412.50	
			Construction	Stockpile S	ГМI - Total			\$2,412.50	
	0490 -	Total						\$0.00	
	0500	SIGNAL HEAD, TYPE 3S	Material		15	Oct 4, 2021	SYSTEM	\$1,080.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user frizzm overridding Payment Estimate Exception 16 on the current Payment Estimate.
					15	Oct 4, 2021	SYSTEM	(\$1,080.00)	
					16	Oct 19, 2021	SYSTEM	\$1,080.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user frizzm overridding Payment Estimate Exception 23 on the current Payment Estimate.
					16	Oct 19, 2021	SYSTEM	(\$1,080.00)	
					17	Nov 2, 2021	SYSTEM	\$1,080.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user frizzm overridding Payment Estimate Exception 32 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks								
J4I3222	0500	SIGNAL HEAD, TYPE 3S	Material		17	Nov 2, 2021	SYSTEM	(\$1,080.00)									
					18	Nov 16, 2021	SYSTEM	\$1,080.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user woodyb1 overridding Payment Estimate Exception 28 on the current Payment Estimate.								
					18	Nov 16, 2021	SYSTEM	(\$1,080.00)									
				- Total				\$0.00									
			Material - To	tal				\$0.00									
	0500 -	Total						\$0.00									
	0510	SIGNAL HEAD, TYPE 3B	Material		15	Oct 4, 2021	SYSTEM	\$4,660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user frizzm overridding Payment Estimate Exception 17 on the current Payment Estimate.								
					15	Oct 4, 2021	SYSTEM	(\$4,660.00)									
					16	Oct 19, 2021	SYSTEM	\$4,660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user frizzm overridding Payment Estimate Exception 24 on the current Payment Estimate.								
						16	Oct 19, 2021	SYSTEM	(\$4,660.00)								
					17	Nov 2, 2021	SYSTEM	\$4,660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user frizzm overridding Payment Estimate Exception 33 on the current Payment Estimate.								
											17	Nov 2, 2021	SYSTEM	(\$4,660.00)			
						18	Nov 16, 2021	SYSTEM	\$4,660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user woodyb1 overridding Payment Estimate Exception 29 on the current Payment Estimate.							
					18	Nov 16, 2021	SYSTEM	(\$4,660.00)									
				- Total				\$0.00									
			Material - To	tal				\$0.00									
	0510 -	Total						\$0.00									
	0520				15	Oct 4, 2021	SYSTEM	\$21,220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user frizzm overridding Payment Estimate Exception 18 on the current Payment Estimate.								
						15	Oct 4, 2021	SYSTEM	(\$21,220.00)								
										16	Oct 19, 2021	SYSTEM	\$21,220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user frizzm overridding Payment Estimate Exception 25 on the current Payment Estimate.			
					16	Oct 19, 2021	SYSTEM	(\$21,220.00)									
								17	Nov 2, 2021	SYSTEM	\$21,220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user frizzm overridding Payment Estimate Exception 34 on the current Payment Estimate.					
					17	Nov 2, 2021	SYSTEM	(\$21,220.00)									
								1	18	18	Nov 16, 2021	SYSTEM	\$21,220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user woodyb1 overridding Payment Estimate Exception 30 on the current Payment Estimate.			
					18	Nov 16, 2021	SYSTEM	(\$21,220.00)									
				- Total				\$0.00									
			Material - To	tal				\$0.00									
	0520 -							\$0.00									
	0530	CONDUIT, 4 IN., TRENCH WITH TRACER WIRE	Material		15	Oct 4, 2021	SYSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user frizzm overridding Payment Estimate Exception 21 on the current Payment Estimate.								
					15	Oct 4, 2021	SYSTEM	(\$750.00)									
													16	Oct 19, 2021	SYSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user frizzm overridding Payment Estimate Exception 28 on the current Payment Estimate.



ject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
3222	0530	CONDUIT, 4 IN., TRENCH WITH	Material		16	Oct 19, 2021	SYSTEM	(\$750.00)		
		TRACER WIRE			17	Nov 2, 2021	SYSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user frizzm overridding Payment Estimate Exception 37 on the current Payment Estimate.	
					17	Nov 2, 2021	SYSTEM	(\$750.00)		
					18	Nov 16, 2021	SYSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user woodyb1 overridding Payment Estimate Exception 33 on the current Payment Estimate.	
					18	Nov 16, 2021	SYSTEM	(\$750.00)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	0530 -	Total						\$0.00		
	0540	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRAC	Material		15	Oct 4, 2021	SYSTEM	\$256.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user frizzm overridding Payment Estimate Exception 22 on the current Payment Estimate.	
					15	Oct 4, 2021	SYSTEM	(\$256.50)		
					16	Oct 19, 2021	SYSTEM	\$256.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user frizzm overridding Payment Estimate Exception 29 on the current Payment Estimate.	
					16	Oct 19, 2021	SYSTEM	(\$256.50)		
					17	Nov 2, 2021	SYSTEM	\$256.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user frizzm overridding Payment Estimate Exception 38 on the current Payment Estimate.	
					17	Nov 2, 2021	SYSTEM	(\$256.50)		
					18	Nov 16, 2021	SYSTEM	\$256.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user woodyb1 overridding Paymen Estimate Exception 34 on the current Payment Estimate.	
					18	Nov 16, 2021	SYSTEM	(\$256.50)		
				- Total						
			Material - Total					\$0.00		
	0540 -	Total						\$0.00		
	0550	CABLE, 16 AWG 7 CONDUCTOR	Material		15	Oct 4, 2021	SYSTEM	\$1,110.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user frizzm overridding Payment Estimate Exception 23 on the current Payment Estimate.	
					15	Oct 4, 2021	SYSTEM	(\$1,110.00)		
					16	Oct 19, 2021	SYSTEM	\$1,110.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user frizzm overridding Payment Estimate Exception 30 on the current Payment Estimate.	
					16	Oct 19, 2021	SYSTEM	(\$1,110.00)		
						17	Nov 2, 2021	SYSTEM	\$1,110.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user frizzm overridding Payment Estimate Exception 39 on the current Payment Estimate.
					17	Nov 2, 2021	SYSTEM	(\$1,110.00)		
					18	Nov 16, 2021	SYSTEM	\$1,110.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user woodyb1 overridding Paymer Estimate Exception 35 on the current Payment Estimate.	
					18	Nov 16, 2021	SYSTEM	(\$1,110.00)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	0550 -	Total						\$0.00		
	0560	BASE, CONCRETE	Material		15	Oct 4, 2021	SYSTEM	\$13,320.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user frizzm overridding Payment Estimate Exception 24 on the current Payment Estimate.	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks					
J4I3222	0560	BASE, CONCRETE	Material	,	15	Oct 4, 2021	SYSTEM	(\$13,320.00)						
					16	Oct 19, 2021	SYSTEM	\$13,320.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user frizzm overridding Payment Estimate Exception 31 on the current Payment Estimate.					
					16	Oct 19, 2021	SYSTEM	(\$13,320.00)						
					17	Nov 2, 2021	SYSTEM	\$13,320.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user frizzm overridding Payment Estimate Exception 40 on the current Payment Estimate.					
					17	Nov 2, 2021	SYSTEM	(\$13,320.00)						
					18	Nov 16, 2021	SYSTEM	\$13,320.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user woodyb1 overridding Payment Estimate Exception 36 on the current Payment Estimate.					
					18	Nov 16, 2021	SYSTEM	(\$13,320.00)						
				- Total				\$0.00						
			Material - To	tal				\$0.00						
	0560 -	Total						\$0.00						
	5001	CMS WITH COMMUNICATION INTERFACE,	Material		10	Jul 1, 2021	SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user frizzm overridding Payment Estimate Exception 18 on the current Payment Estimate.					
		CONT F	CONT F			10	Jul 1, 2021	SYSTEM	(\$6,000.00)					
				- Total				\$0.00						
			Material - To	tal				\$0.00						
	5001 -	Total						\$0.00						
	5002		Material	Material		13	Sep 2, 2021	SYSTEM	\$14,726.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.				
					13	Sep 2, 2021	SYSTEM	(\$14,726.25)						
					14	Sep 16, 2021	SYSTEM	\$74,628.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.					
					14	Sep 16, 2021	SYSTEM	(\$74,628.40)						
					15	Oct 4, 2021	SYSTEM	\$159,547.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.					
					15	Oct 4, 2021	SYSTEM	(\$159,547.85)						
					16	Oct 19, 2021	SYSTEM	\$173,084.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user frizzm overridding Payment Estimate Exception 2 on the current Payment Estimate.					
								1	16	16	Oct 19, 2021	SYSTEM	(\$173,084.45)	
						17	Nov 2, 2021	SYSTEM	\$173,084.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user frizzm overridding Payment Estimate Exception 2 on the current Payment Estimate.				
						1	17	Nov 2, 2021	SYSTEM	(\$173,084.45)				
					18	Nov 16, 2021	SYSTEM	\$173,084.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodyb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.					
					18	Nov 16, 2021	SYSTEM	(\$173,084.45)						
				- Total				\$0.00						
			Material - To	tal				\$0.00						
			Overrun	Overrun	16	Oct 19, 2021	SYSTEM	\$5,501.65	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) overridding Payment Estimate Exception 37 on the current Payment Estimate. Material Insufficiency Quantity 44957.000; Overrun Quantity Balance 2614.00.					
						16	Oct 19,	SYSTEM	\$4,562.25	This adjustment offsets the original system-generated Overrun Payment				

Nov 18, 2021



Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4I3222	5002	TACK COAT - LOW OR NON- TRACKING	Overrun	Overrun		2021			Estimate Item Adjustment (0030) overridding Payment Estimate Exception 37 on the current Payment Estimate. Material Insufficiency Quantity 44957.000; Overrun Quantity Balance 2614.00.
					16	Oct 19, 2021	SYSTEM	(\$10,063.90)	
					17	Nov 2, 2021	SYSTEM	(\$10,063.90)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					17	Nov 2, 2021	SYSTEM	\$10,063.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) overridding Payment Estimate Exception 45 on the current Payment Estimate. Material Insufficiency Quantity 44957.000; Overrun Quantity Balance 2614.00.
					18	Nov 16, 2021	SYSTEM	(\$10,063.90)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					18	Nov 16, 2021	SYSTEM	\$10,063.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 38 on the current Payment Estimate. Material Insufficiency Quantity 44957.000; Overrun Quantity Balance 2614.00.
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	5002 -	Total						\$0.00	
	5003	MGS GUARDRAIL, 6 FT. POSTS, 3 FT 1.5	Material		18	Nov 16, 2021	SYSTEM	\$2,988.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user woodyb1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					18	Nov 16, 2021	SYSTEM	(\$2,988.12)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	5003 -	Total						\$0.00	
	5004	MISC. GUARDRAIL ITEM	Material		18	Nov 16, 2021	SYSTEM	\$2,460.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user woodyb1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					18	Nov 16, 2021	SYSTEM	(\$2,460.50)	
			- Total					\$0.00	
	Material - Total							\$0.00	
	5004 -	Total						\$0.00	
J4I3222 -	Total							\$277,820.25	
	Overall - Total								