

#### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: December 2, 2021

	Progress Estimate Number	Contract ID	201016-C02	Pay Period Start	November 16, 2021	Original Contract Amount	\$5,716,989.09
	19	Prime Contractor	Capital Paving & Construction, LLC	Pay Period End	December 1, 2021	Net Change Order Amount Current Contract Amount	\$182,701.93 \$5,899,691.02
H							

Original Compl	etion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amou	int Complete	
December 6, 2021	1 Reviewed and Approved at the Central Office Controllers Office Level by					
December 3, 2021	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level					
December 3, 2021		Generated and	Approved (and should be considere	d Draft) at the Project Office Level by	sandis1	
Approval Date					By User	

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
November 1, 2021	November 1, 2021		94.57%

	Contract Informational Dates						
Date Description	Original Completion Date	<b>Current Completion Date</b>	No Milestones Exist for Contract				
02/22/2021	November 17, 2021	November 17, 2021					
Acceptance Date							
Awarded Date	November 5, 2020	November 5, 2020					
Letting Date	October 16, 2020	October 16, 2020					
Notice to Proceed Date	January 4, 2021	January 4, 2021					

Contract Total P	ay For Estimate No. 19			
		This Estimate	Previous	To Date
201016-C02				
	Total Posted Items Pay	\$112.10	\$5,579,287.60	\$5,579,399.70
	Gross Item Adjustments	(\$3,823.00)	\$277,820.25	\$273,997.25
	Incentive	\$166,190.51	\$77,259.04	\$243,449.55
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	·		\$5,934,366.89	\$6,096,846.50
Contract Total Pa	avable This Estimate:	\$162,479,61		

### Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J4I3222	0040	4011211	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-2)	TONS	\$57.980	-4.64	(\$269.03)
	0050	4030009	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP095BSM MIX)	TONS	\$82.140	4.64	\$381.13
Project J4l3222 - Total							
Overall - Total							\$112.10

#### Contract Adjustments This Estimate

Adj Type	Entered By	Comments	Time Units	Rate	Amount
TSRIncentive	frizzm	TSR adjustment. See project files for information.			\$67,374.53
SPADIncentive	frizzm	Payfactor adjustment. See project files for information.			\$98,815.98

Overall - Total
These amounts are listed in the Incentive, Disincentive, Liquidated Damages or Other Contract Adjustments

\$166,190.51

Line Item	Adjust	tments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4I3222	0030	MISC.	Material			-734.3	\$72.05	(\$52,906.32)
	0030	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.	734.3	\$72.05	\$52,906.32

Revision 4/1/2020 Page 1 of 32

## Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: December 2, 2021

Progress Estimate Number
19 Contract ID 201016-C02 Pay Period Start 2021 Original Contract Amount \$5,716,989.09
Prime Contractor LLC Pay Period End December 1, 2021 Net Change Order Amount \$182,701.93
Current Contract Amount \$5,899,691.02

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4I3222	0040	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-2)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	-4.64	\$4.28	(\$19.87)
	0040	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-2)	Overrun		Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',61.65146 - 57.98000, 'is applied (if non-zero).	4.64	\$61.65	\$286.06
	0040	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-2)	Other Item Adjustment	Fuel Price				\$3.39
	0040	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-2)	Other Item Adjustment	Asphalt Cement Price Adjustment				\$5,359.37
	0050	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP095BSM MIX)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	4.64	\$4.28	\$19.87
	0050	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP095BSM MIX)	Other Item Adjustment	Fuel Price				\$626.66
	0050	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP095BSM MIX)	Other Item Adjustment	Asphalt Cement Price Adjustment				(\$5,964.48)
	0120	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material			-1,458	\$4.25	(\$6,196.50)
	0120	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 8 on the current Payment Estimate.	1,458	\$4.25	\$6,196.50
	0130	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	Material			-80	\$8.25	(\$660.00)
	0130	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 9 on the current Payment Estimate.	80	\$8.25	\$660.00
	0140	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	Material			-386	\$7.50	(\$2,895.00)
	0140	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Exception 12 on the current Payment Estimate.	386	\$7.50	\$2,895.00
	0150	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS B PARTIAL DEPTH PAVEMENT REPAIR	Material			-91.97	\$181.66	(\$16,707.27)
	0150	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS B PARTIAL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user frizzm overridding Payment Estimate Exception 14	91.97	\$181.66	\$16,707.27

Revision 4/1/2020 Page 2 of 32



## Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: December 2, 2021

Progress Estimate Number
19 Contract ID 201016-C02 Pay Period Start 2021 Original Contract Amount \$5,716,989.09
Prime Contractor LLC Pay Period End December 1, 2021 Net Change Order Amount \$182,701.93
Current Contract Amount \$5,899,691.02

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
413222					on the current Payment Estimate.			
	0170	MISC.	Material			-16,193.1	\$2.98	(\$48,255.44)
	0170	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user frizzm overridding Payment Estimate Exception 15 on the current Payment Estimate.	16,193.1	\$2.98	\$48,255.44
	0250	CONCRETE TRAFFIC BARRIER, TYPE A	Material			-21	\$315.18	(\$6,618.78)
	0250	CONCRETE TRAFFIC BARRIER, TYPE A	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user frizzm overridding Payment Estimate Exception 19 on the current Payment Estimate.	21	\$315.18	\$6,618.78
	0280	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material			-369	\$18.00	(\$6,642.00)
	0280	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user frizzm overridding Payment Estimate Exception 25 on the current Payment Estimate.	369	\$18.00	\$6,642.00
	0290	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	Material			-423	\$18.00	(\$7,614.00)
	0290	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user frizzm overridding Payment Estimate Exception 26 on the current Payment Estimate.	423	\$18.00	\$7,614.00
	0300	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material			-25	\$250.00	(\$6,250.00)
	0300	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user frizzm overridding Payment Estimate Exception 27 on the current Payment Estimate.	25	\$250.00	\$6,250.00
	0410	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	Material			-12,262.5	\$19.50	(\$239,118.75)
	0410	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user frizzm overridding Payment Estimate Exception 3 on the current Payment Estimate.	12,262.5	\$19.50	\$239,118.75
	0430	MGS LONG SPAN GUARDRAIL SECTION	Material			-1	\$2,200.00	(\$2,200.00)
	0430	MGS LONG SPAN GUARDRAIL SECTION	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user frizzm overridding Payment Estimate Exception 6 on the current Payment Estimate.	1	\$2,200.00	\$2,200.00
	0450	MGS BRIDGE APPROACH TRANSITION (THRIE-BEAM	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$4,134.00)

Revision 4/1/2020 Page 3 of 32



## Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: December 2, 2021

Progress Estimate Number 19
Contract ID 201016-C02 Pay Period Start 2021 Original Contract Amount \$5,716,989.09
Prime Contractor Capital Paving & Construction, LLC Pay Period End December 1, 2021 Net Change Order Amount \$182,701.93
Current Contract Amount \$5,899,691.02

Adjustmen amount	Line Item Adjustment Unit Price	Adjustment Quantity	Comments	Other Item Adjustment Type	Adjustment Type	Item Description	Line No.
						BRIDGE)	
(\$1,080.0	\$1,080.00	-1			Material	SIGNAL HEAD, TYPE 3S	0500
\$1,080.0	\$1,080.00	1	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0017) due to user frizzm overridding Payment Estimate Exception 28 on the current Payment Estimate.		Material	SIGNAL HEAD, TYPE 3S	0500
(\$4,660.0	\$1,165.00	-4			Material	SIGNAL HEAD, TYPE 3B	0510
\$4,660.0	\$1,165.00	4	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0018) due to user frizzm overridding Payment Estimate Exception 29 on the current Payment Estimate.		Material	SIGNAL HEAD, TYPE 3B	0510
(\$21,220.0	\$21,220.00	-1			Material	POST, TYPE BL, LONGEST ARM 50 FT. OR 15.2 M	0520
\$21,220.0	\$21,220.00	1	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0019) due to user frizzm overridding Payment Estimate Exception 30 on the current Payment Estimate.		Material	POST, TYPE BL, LONGEST ARM 50 FT. OR 15.2 M	0520
(\$750.0	\$75.00	-10			Material	CONDUIT, 4 IN., TRENCH WITH TRACER WIRE	0530
\$750.0	\$75.00	10	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0020) due to user frizzm overridding Payment Estimate Exception 33 on the current Payment Estimate.		Material	CONDUIT, 4 IN., TRENCH WITH TRACER WIRE	0530
(\$256.5	\$2.85	-90			Material	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	0540
\$256.5	\$2.85	90	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0021) due to user frizzm overridding Payment Estimate Exception 34 on the current Payment Estimate.		Material	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	0540
(\$1,110.0	\$37.00	-30			Material	CABLE, 16 AWG 7 CONDUCTOR	0550
\$1,110.0	\$37.00	30	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0022) due to user frizzm overridding Payment Estimate Exception 35 on the current Payment Estimate.		Material	CABLE, 16 AWG 7 CONDUCTOR	0550
(\$13,320.0	\$3,600.00	-3.7			Material	BASE, CONCRETE	0560
\$13,320.0	\$3,600.00	3.7	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0023) due to user frizzm overridding Payment Estimate Exception 36 on the current Payment Estimate.		Material	BASE, CONCRETE	0560
(\$10,063.9	\$3.85	-2,614	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).		Overrun	TACK COAT - LOW OR NON-TRACKING	5002
(\$173,084.4	\$3.85	-44,957			Material	TACK COAT - LOW OR NON-TRACKING	5002
\$10,063.9	\$3.85	2,614	This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0024) overridding Payment Estimate Exception 40 on the current Payment		Overrun	TACK COAT - LOW OR NON-TRACKING	5002

Revision 4/1/2020 Page 4 of 32



## Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: December 2, 2021

Progress Estimate Number
19 Contract ID 201016-C02 Pay Period Start 2021 Original Contract Amount \$5,716,989.09
Prime Contractor Contractor LLC Pay Period End December 1, 2021 Net Change Order Amount \$182,701.93
Current Contract Amount \$5,899,691.02

Adjustment amount	Line Item Adjustment Unit Price	Adjustment Quantity	Comments	Other Item Adjustment Type	Adjustment Type	Item Description	Line No.	Project Number
			Estimate. Material Insufficiency Quantity 44957.000; Overrun Quantity Balance 2614.00.					J4I3222
\$173,084.45	\$3.85	44,957	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0025) due to user frizzm overridding Payment Estimate Exception 2 on the current Payment Estimate.		Material	TACK COAT - LOW OR NON-TRACKING	5002	
(\$2,988.12	\$34.15	-87.5			Material	MGS GUARDRAIL, 6 FT. POSTS, 3 FT 1.5 IN. SPACING	5003	
\$2,988.12	\$34.15	87.5	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0027) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate.		Material	MGS GUARDRAIL, 6 FT. POSTS, 3 FT 1.5 IN. SPACING	5003	
(\$2,460.50	\$49.21	-50			Material	MISC.	5004	
\$2,460.50	\$49.21	50	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0026) due to user frizzm overridding Payment Estimate Exception 7 on the current Payment Estimate.		Material	MISC.	5004	
(\$3,823.00								otal

Revision 4/1/2020 Page 5 of 32



### Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(	Contract Project Information					
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work						
J4I3222	I 70-1(212)	Resurface	I-70	JACKSON	from Route 7 to Horsesh	oe Creek bridge					
Totals by	Job Numbe	rs									
J4I3222					This Estimate	Previous	To Date				
J4I3222	Poste	d Item Pay			This Estimate \$112.10	<b>Previous</b> \$5,579,287.60	<b>To Date</b> \$5,579,399.70				
J4I3222		d Item Pay Item Adjustm	ents								
J4I3222				Item Pay	\$112.10	\$5,579,287.60	\$5,579,399.70				
J4l3222		Item Adjustm		Item Pay	\$112.10 (\$3,823.00)	\$5,579,287.60 \$277,820.25	\$5,579,399.70 \$273,997.25				
J4I3222	Gross	Item Adjustm		Item Pay	\$112.10 (\$3,823.00) <b>(\$3,710.90)</b>	\$5,579,287.60 \$277,820.25 <b>\$5,857,107.85</b>	\$5,579,399.70 \$273,997.25 <b>\$5,853,396.95</b>				
J4I3222	Incent Disino	Item Adjustm	Gross	Item Pay	\$112.10 (\$3,823.00) ( <b>\$3,710.90)</b> \$166,190.51	\$5,579,287.60 \$277,820.25 <b>\$5,857,107.85</b> \$77,259.04	\$5,579,399.70 \$273,997.25 <b>\$5,853,396.95</b> \$243,449.55				

Revision 4/1/2020 Page 6 of 32



### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

#### **Exceptions (Discrepancies) This Estimate Period**

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4I3222, Item 3049910, Project Item Line Number 0030, Material Set 304991096, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Requested cert from contractor. frizzm 12/2/21	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 4071007, Project Item Line Number 5002, Material Set 407100796, Material 1015EASS1VH - Emulsified Asphalt - Trackless Tack, Acceptance Action Generic AspEmulsion is insufficient.	QC/QA and KC Materials continue working to resolve exception. frizzm 12/2/21.	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 6061061, Project Item Line Number 0410, Material Set 606106196, Material 1065DE - Delineators, Acceptance Action Generic 1065DE is insufficient.	QC/QA and KC Materials continue working to resolve exception. frizzm 12/2/21.	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 6061063, Project Item Line Number 5003, Material Set 606106396, Material 1040GRSRCAT2 - Steel Beam for Class A Type 2 Guard Rail, Acceptance Action Generic 1040GRSRCAT2 is insufficient.	QC/QA and KC Materials continue working to resolve exception. frizzm 12/2/21.	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 6061063, Project Item Line Number 5003, Material Set 606106396, Material 1065DE - Delineators, Acceptance Action Generic 1065DE is insufficient.	QC/QA and KC Materials continue working to resolve exception. frizzm 12/2/21.	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 6061075, Project Item Line Number 0430, Material Set 606107596, Material 1065DE - Delineators, Acceptance Action Generic 1065DE is insufficient.	QC/QA and KC Materials continue working to resolve exception. frizzm 12/2/21.	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 6069903, Project Item Line Number 5004, Material Set 606990396, Material 1040GRSRCAT2 - Steel Beam for Class A Type 2 Guard Rail, Acceptance Action Generic 1040GRSRCAT2 is insufficient.	QC/QA and KC Materials continue working to resolve exception. frizzm 12/2/21.	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 6131015, Project Item Line Number 0120, Material Set 613101596, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient.	Sent email to KC Materials requesting review of outstanding exceptions. frizzm 12/2/21.	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 6131017, Project Item Line Number 0130, Material Set 613101796, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient.	Sent email to KC Materials requesting review of outstanding exceptions. frizzm 12/2/21.	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 6131017, Project Item Line Number 0130, Material Set 613101796, Material 1057JMDAEC6.11 - Dowel Assemblies Epoxy Ctd Gr60 1 1/4" @, Acceptance Action Generic ReinforcingMisc is insufficient.	Sent email to KC Materials requesting review of outstanding exceptions. frizzm 12/2/21.	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 6131017, Project Item Line Number 0130, Material Set 613101796, Material 1057JMDBEC6.11 - Dowel Bar Epoxy Ctd Gr60 1 1/4 @, Acceptance Action Generic ReinforcingMisc is insufficient.	Sent email to KC Materials requesting review of outstanding exceptions. frizzm 12/2/21.	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 6131018, Project Item Line Number 0140, Material Set 613101896, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient.	Sent email to KC Materials requesting review of outstanding exceptions. frizzm 12/2/21.	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 6131018, Project Item Line Number 0140, Material Set 613101896, Material 1057JMTBE42019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Sent email to KC Materials requesting review of outstanding exceptions. frizzm 12/2/21.	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 6133018, Project Item Line Number 0150, Material Set 613301896, Material 0401BPPMBP1 - Plant Mix for Bit Pavement BP-1, Acceptance Action Generic AspLow is insufficient.	Sent email to KC Materials requesting review of outstanding exceptions. frizzm 12/2/21.	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 6139905, Project Item Line Number 0170, Material Set 613990596, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	This item is for removal of asphalt. Project Office to confer with KC Materials to inquire about why this item shows up as an exception. frizzm 12/2/21.	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 6139905, Project Item Line Number 0170, Material Set 613990596, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	This item is for removal of asphalt. Project Office to confer with KC Materials to inquire about why this item shows up as an exception. frizzm 12/2/21.	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 6139905, Project Item Line Number 0170, Material Set 613990596, Material 1015EASS1H - Emulsified Asphalt SS-1H, Acceptance Action Generic AspEmulsion is insufficient.	This item is for removal of asphalt. Project Office to confer with KC Materials to inquire about why this item shows up as an exception. frizzm 12/2/21.	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 6139905, Project Item Line Number 0170, Material Set 613990596, Material 0501CCPAQCQA - Concrete, Payment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	This item is for removal of asphalt. Project Office to confer with KC Materials to inquire about why this item shows up as an exception. frizzm 12/2/21.	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 6171000, Project Item Line Number 0250, Material Set 617100096, Material 1057JMDBEC6.10 - Dowel Bar Epoxy Ctd Gr60 1" @, Acceptance Action Generic ReinforcingMisc is insufficient.	QC/QA and KC Materials continue working to resolve exception. frizzm 12/2/21.	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 6171000, Project Item Line Number 0250, Material Set 617100096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	QC/QA and KC Materials continue working to resolve exception. frizzm 12/2/21.	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 6171000, Project Item Line Number 0250, Material Set 617100096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	QC/QA and KC Materials continue working to resolve exception. frizzm 12/2/21.	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 6171000, Project Item Line Number 0250, Material Set 617100096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	QC/QA and KC Materials continue working to resolve exception. frizzm 12/2/21.	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 6171000, Project Item Line Number 0250, Material Set 617100096, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	QC/QA and KC Materials continue working to resolve exception. frizzm 12/2/21.	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 6171000, Project Item Line Number 0250, Material Set 617100096, Material 1036RSDFEC42M13 - Rein Steel EC No. 4/M13 Gr	QC/QA and KC Materials continue working to resolve exception. frizzm 12/2/21.	frizzm	Overridden

Revision 4/1/2020 Page 7 of 32



### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

#### **Exceptions (Discrepancies) This Estimate Period**

Exceptions / Discrepencies	Explanation	Entered By	Status
60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J4I3222, Item 6200015, Project Item Line Number 0280, Material Set 620001596, Material 1048PMPFWH - Performed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	QC/QA and KC Materials continue working to resolve exception. frizzm 12/2/21.	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3222, Item 6200018, Project Item Line Number 0290, Material Set 620001896, Material 1048PMPFYL - Performed Thermoplastic Marking Tape YL, Acceptance Action Generic 1048PMPFYL is insufficient.	QC/QA and KC Materials continue working to resolve exception. frizzm 12/2/21.	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 6200021, Project Item Line Number 0300, Material Set 620002196, Material 1048PMPFWHXX - Pref Mrk Tape Direct Indcat or Shape WH, Acceptance Action Generic 1048PMPFWHXX is insufficient.	QC/QA and KC Materials continue working to resolve exception. frizzm 12/2/21.	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 9020213, Project Item Line Number 0500, Material Set 902021396, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	QC/QA and KC Materials continue working to resolve exception. frizzm 12/2/21.	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 9020513, Project Item Line Number 0510, Material Set 902051396, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	QC/QA and KC Materials continue working to resolve exception. frizzm 12/2/21.	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 9023450, Project Item Line Number 0520, Material Set 902345096, Material 0902TSBTZCAB - Bolts Galv Anchor for Traffic Signals, Acceptance Action Generic 0902TSBTZCAB is insufficient.	QC/QA and KC Materials continue working to resolve exception. frizzm 12/2/21.	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 9023450, Project Item Line Number 0520, Material Set 902345096, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	QC/QA and KC Materials continue working to resolve exception. frizzm 12/2/21.	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 9023450, Project Item Line Number 0520, Material Set 902345096, Material 1092TSPS - Traffic Signal Post(s) - All Types, Acceptance Action Generic 1092TSPS is insufficient.	QC/QA and KC Materials continue working to resolve exception. frizzm 12/2/21.	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 9025400, Project Item Line Number 0530, Material Set 902540096, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient.	QC/QA and KC Materials continue working to resolve exception. frizzm 12/2/21.	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 9028100, Project Item Line Number 0540, Material Set 902810096, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	QC/QA and KC Materials continue working to resolve exception. frizzm 12/2/21.	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 9028311, Project Item Line Number 0550, Material Set 902831196, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	QC/QA and KC Materials continue working to resolve exception. frizzm 12/2/21.	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 9029100, Project Item Line Number 0560, Material Set 902910096, Material 1036RSDFPL42M19 - Reinforcing Steel No. 6/M19 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	QC/QA and KC Materials continue working to resolve exception. frizzm 12/2/21.	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3222, Item 9029100, Project Item Line Number 0560, Material Set 902910096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	QC/QA and KC Materials continue working to resolve exception. frizzm 12/2/21.	frizzm	Overridden
Estimate Exception Type: Item Overrun: Contract 201016-C02, Contract Project J4l3222, Project Item Line Number 0350, Contract Line Item Number 0350, Item 6221001, Minor Item.	A change order is in process for this item. frizzm 12/2/21.	frizzm	Acknowledged
Estimate Exception Type: Item Overrun: Contract 201016-C02, Contract Project J4l3222, Project Item Line Number 0040, Contract Line Item Number 0040, Item 4011211, Minor Item.	A change order is in process for this item. frizzm 12/2/21.	frizzm	Acknowledged
Estimate Exception Type: Item Overrun: Contract 201016-C02, Contract Project J4l3222, Project Item Line Number 5002, Contract Line Item Number 5002, Item 4071007, Minor Item.	A change order is in process for this item. frizzm 12/2/21.	frizzm	Overridden
Estimate Exception Type: Item Overrun: Contract 201016-C02, Contract Project J4l3222, Project Item Line Number 0180, Contract Line Item Number 0180, Item 6139910, Minor Item.	A change order is in process for this item. frizzm 12/2/21.	frizzm	Acknowledged

Revision 4/1/2020 Page 8 of 32



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT		Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
201016-C02	J4I3222	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$25,450.00	\$25,450.00
		0001	0020	2153000	SHAPING SLOPES, CLASS III	134.00	2.00	136.00	100F	136.00	\$685.00	\$93,160.00
		0001	0030	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	734.30	826.70	1,561.00	TONS	734.30	\$72.05	\$52,906.32
		0001	0040	4011211	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-2)	6,988.70	0.00	6,988.70	TONS	8,576.75	\$57.98	\$497,279.96
		0001	0050	4030009	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP095BSM MIX)	30,494.70	0.00	30,494.70	TONS	29,817.72	\$82.14	\$2,449,227.52
		0001	0060	4071005	TACK COAT	42,343.00	-42,343.00	0.00	GAL	0.00	\$2.03	\$0.00
		0001	0070	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$500.00	\$1,000.00
		0001	0800	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	3,743.30	0.00	3,743.30	SQYD	2,556.80	\$208.20	\$532,325.76
		0001	0090	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	375.00	0.00	375.00	SQYD	0.00	\$1.00	\$0.00
		0001	0100	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	375.00	0.00	375.00	SQYD	0.00	\$1.00	\$0.00
		0001	0110	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER	9,624.00	0.00	9,624.00	LF	5,347.00	\$2.00	\$10,694.00
		0001	0120	6131015	AND INTERNAL SAW CUTS)  DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	1,602.00	0.00	1,602.00	EA	1,458.00	\$4.25	\$6,196.50
		0001	0130	6131017	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	85.00	0.00	85.00	EA	80.00	\$8.25	\$660.00
		0001	0140	6131018	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	512.00	0.00	512.00	EA	386.00	\$7.50	\$2,895.00
		0001	0150	6133018	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS B PARTIAL DEPTH PAVEMENT REPAIR	112.60	0.00	112.60	TONS	91.97	\$181.66	\$16,707.27
		0001	0160	6133019	REMOVAL FOR CLASS B PARTIAL DEPTH PAVEMENT REPAIR	675.40	0.00	675.40	SQYD	664.62	\$71.21	\$47,327.59
		0001	0170	6139905	MISC.REMOVAL FOR CLASS C PARTIAL DEPTH RUMBLE	16,363.00	0.00	16,363.00	SQYD	16,193.10	\$2.98	\$48,255.44
		0001	0180	6139910	STRIP REPAIR  MISC.FURNISHING AND PLACING BITUMINOUS MATERIAL FOR	2,585.60	0.00	2,585.60	TONS	2,603.31	\$52.96	\$137,871.30
		0001	0190	6161005	CLASS C PARTIAL DEPTH RUMBLE STRIP REPAIR CONSTRUCTION SIGNS	1,794.00	0.00	1,794.00	SQFT	1,468.11	\$5.00	\$7,340.55
		0001	0200	6161009	FLAG ASSEMBLY	19.00	0.00	19.00	EA	2.00	\$15.00	\$30.00
		0001	0210	6161024	CHANNELIZER (TRIM LINE) WITH LIGHT	607.00	0.00	607.00	EA	315.00	\$38.00	\$11,970.00
		0001	0220	6161034	DIRECTIONAL INDICATOR BARRICADE WITH LIGHT	93.00	0.00	93.00	EA	14.00	\$94.00	\$1,316.00
		0001	0230	6161040	FLASHING ARROW PANEL	4.00	0.00	4.00	EA	3.00	\$4,000.00	\$12,000.00
		0001	0240	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	-4.00	0.00	EA	0.00	\$1,000.00	\$0.00
		0001	0250	6171000	CONCRETE TRAFFIC BARRIER, TYPE A	50.00	0.00	50.00	LF	21.00	\$315.18	\$6,618.78
		0001	0260	6173000	CONCRETE TRAFFIC BARRIER, TYPE C	32.00	0.00	32.00	LF	0.00	\$298.50	\$0.00
		0001	0270	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$146,859.59	\$146,859.59
		0001	0280	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	455.00	0.00	455.00	LF	369.00	\$18.00	\$6,642.00
		0001	0290	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	441.00	0.00	441.00	LF	423.00	\$18.00	\$7,614.00
		0001	0300	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	25.00	0.00	25.00	EA	25.00	\$250.00	\$6,250.00
		0001	0310	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	127,559.00	0.00	127,559.00	LF	126,412.00	\$0.16	\$20,225.92
		0001	0320	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	104,914.00	0.00	104,914.00	LF	102,167.00	\$0.16	\$16,346.72
		0001	0330	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	7,113.00	0.00	7,113.00	LF	6,046.00	\$0.30	\$1,813.80
		0001	0340	6207001	PAVEMENT MARKING REMOVAL	300.00	0.00	300.00	LF	300.00	\$1.00	\$300.00
		0001	0350	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	414,629.00	0.00	414,629.00	SQYD	417,497.79	\$0.65	\$271,373.56
		0001	0360	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	11,710.00	0.00	11,710.00	SQYD	11,231.92	\$2.50	\$28,079.80
		0001	0370	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	1,650.30	0.00	1,650.30	STA	1,650.30	\$13.00	\$21,453.90
		0010	0380	6061014	GUARDRAIL TYPE A WITH RUBRAIL	113.00	-113.00	0.00	LF	0.00	\$23.50	\$0.00
		0010	0390	6061050	GUARDRAIL TYPE E, 6 FT. POST, 3 FT1.5 IN. SPACING	138.00	-138.00	0.00	LF	0.00	\$23.50	\$0.00
		0010	0400	6061060	MGS GUARDRAIL	21,050.00	1,175.00	22,225.00	LF	22,225.00	\$16.25	\$361,156.25
		0010	0410	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	12,075.00	88.00	12,163.00	LF	12,163.00	\$19.50	\$237,178.50
		0010	0420	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	20.00	4.00	24.00	EA	24.00	\$2,400.00	\$57,600.00

Revision 4/1/2020 Page 9 of 32



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
016-C02	J4I3222	0010	0430	6061075	MGS LONG SPAN GUARDRAIL SECTION	2.00	-1.00	1.00	EA	1.00	\$2,200.00	\$2,200.00
		0010	0440	6061080	MGS END ANCHOR	35.00	1.00	36.00	EA	36.00	\$800.00	\$28,800.00
		0010	0450	6061081	MGS BRIDGE APPROACH TRANSITION (THRIE-BEAM BRIDGE)	2.00	-2.00	0.00	EA	0.00	\$3,250.00	\$0.00
		0010	0460	6062300A	TRANSITION SECTION, 6.5 FT. POSTS	6.00	-6.00	0.00	EA	0.00	\$350.00	\$0.00
		0010	0470	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	42.00	3.00	45.00	EA	45.00	\$2,300.00	\$103,500.00
		0010	0480	6063017	TYPE C CRASHWORTHY END TERMINAL	3.00	0.00	3.00	EA	3.00	\$18,000.00	\$54,000.00
		0010	0490	6066620	GUARDRAIL ANCHOR, EMBEDDED	1.00	0.00	1.00	EA	1.00	\$4,000.00	\$4,000.00
		0030	0500	9020213	SIGNAL HEAD, TYPE 3S	1.00	0.00	1.00	EA	1.00	\$1,080.00	\$1,080.00
		0030	0510	9020513	SIGNAL HEAD, TYPE 3B	4.00	0.00	4.00	EA	4.00	\$1,165.00	\$4,660.00
		0030	0520	9023450	POST, TYPE BL, LONGEST ARM 50 FT. OR 15.2 M	1.00	0.00	1.00	EA	1.00	\$21,220.00	\$21,220.00
		0030	0530	9025400	CONDUIT, 4 IN., TRENCH WITH TRACER WIRE	10.00	0.00	10.00	LF	10.00	\$75.00	\$750.00
		0030	0540	9028100	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	90.00	0.00	90.00	LF	90.00	\$2.85	\$256.50
		0030	0550	9028311	CABLE, 16 AWG 7 CONDUCTOR	30.00	0.00	30.00	LF	30.00	\$37.00	\$1,110.00
		0030	0560	9029100	BASE, CONCRETE	3.70	0.00	3.70	CUYD	3.70	\$3,600.00	\$13,320.00
		0001	5001	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	0.00	4.00	4.00	EA	4.00	\$1,500.00	\$6,000.00
		0001	5002	4071007	TACK COAT - LOW OR NON-TRACKING	0.00	42,343.00	42,343.00	GAL	44,957.00	\$3.85	\$173,084.45
		0010	5003	6061063	MGS GUARDRAIL, 6 FT. POSTS, 3 FT 1.5 IN. SPACING	0.00	87.50	87.50	LF	87.50	\$34.15	\$2,988.12
		0010	5004	6069903	MISC.MGS Guardrail, 8 Ft. Posts, 3 Ft. 1 1/2 In. Spacing	0.00	50.00	50.00	LF	50.00	\$49.21	\$2,460.50
		0010	5005	6069901	MISC.Guard Cable and Cable Anchor at Route 7	0.00	1.00	1.00	LS	1.00	\$15,067.06	\$15,067.06
		0010	5006	6069902	MISC.Flume Coring for Guardrail Installation	0.00	4.00	4.00	EA	4.00	\$194.25	\$777.00
	Project .	1413222 - To	otal Value	Posted to D	Date as of Report Generated Date							\$5,579,399.67
16-C02 Ove	erall - Tota	I Value Pos	sted to Da	ate as of Rep	ort Generated Date							\$5,579,399.67

Page 10 of 32 Revision 4/1/2020



## Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J4l3222

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location		Offset/ Distance		Offset/ Distance	Comments
0040	4011211	BIT. PAVEMENT MIXTURE PG64-22 (BP-2)	12/1/21	12/2/21	-4.64	TONS	WB/EB 4' of left shoulder	229.373		20.616		
0050	4030009	ASPH. CONC. MIXTURE PG 76-22 (SP095BSM)	12/1/21	12/2/21	4.64	TONS	WB/EB 4' of left shoulder	229.373		20.616		

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 4/1/2020 Page 11 of 32





	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks						
22 (	0030	MISC. AGGREGATE FOR BASE	Material		16	Oct 19, 2021	SYSTEM	\$52,906.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.						
					16	Oct 19, 2021	SYSTEM	(\$52,906.32)							
					17	Nov 2, 2021	SYSTEM	\$52,906.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.						
					17	Nov 2, 2021	SYSTEM	(\$52,906.32)							
					18	Nov 16, 2021	SYSTEM	\$52,906.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user woodyb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.						
											18	Nov 16, 2021	SYSTEM	(\$52,906.32)	
					19	Dec 2, 2021	SYSTEM	\$52,906.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.						
					19	Dec 2, 2021	SYSTEM	(\$52,906.32)							
				- Total				\$0.00							
			Material - To	tal				\$0.00							
9	0030 -	Total						\$0.00							
(	0040	BIT. PAVEMENT MIXTURE PG64-22 (BP-2)	Other Item Adjustment	ACAD	16	Oct 19, 2021	frizzm	\$22,863.59	AC adjustments for Line No. 0040. See 201016-C02_J4l3222_Asphalt Roadway Reports Line No. 0040_NW Outer Rd. Oak Grove and 201016- C02_J4l3222_Asphalt Roadway Reports Line No. 0040_Shoulders for detail						
					19	Dec 2, 2021	frizzm	\$5,359.37							
				ACAD - Tota	al			\$28,222.96							
				FUEL	19	Dec 2, 2021	frizzm	\$3.39							
				FUEL - Tota	ı			\$3.39							
			Other Item A	Adjustment - Total				\$28,226.35							
			Overrun	Overrun	16	Oct 19, 2021	SYSTEM	(\$99,059.59)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL						
			Overrun	Overrun	16		SYSTEM SYSTEM	(\$99,059.59) \$85,243.90	Reference Item Price Adjustment Index Adjustment Type applied is FUEL  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 33 on the current Payment Estimate.						
			Overrun	Overrun		2021 Oct 19,		,	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment						
			Overrun	Overrun	16	2021 Oct 19, 2021 Oct 19,	SYSTEM	\$85,243.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 33 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 33 on the current Payment Estimate.						
			Overrun	Overrun	16	2021 Oct 19, 2021 Oct 19, 2021 Nov 2,	SYSTEM	\$85,243.90 \$13,815.69	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 33 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 33 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimate of '3.67146' is applied (if non-zero).  Unit price based on averaged overrun adjustments for installed quantity on a state of the control						
				Overrun - To	16 16 17 19	2021 Oct 19, 2021 Oct 19, 2021 Nov 2, 2021 Dec 2,	SYSTEM SYSTEM	\$85,243.90 \$13,815.69 (\$98,191.66) \$286.06 (\$97,905.60)	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 33 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 33 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimate of '3.67146' is applied (if non-zero).  Unit price based on averaged overrun adjustments for installed quantity on previous payment estimates. Price Adjustments of ',61.65146 - 57.98000, 'is						
			Overrun - To	Overrun - To	16 16 17 19 ootal	2021 Oct 19, 2021 Oct 19, 2021  Nov 2, 2021 Dec 2, 2021	SYSTEM SYSTEM SYSTEM	\$85,243.90 \$13,815.69 (\$98,191.66) \$286.06 (\$97,905.60) (\$97,905.60)	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 33 on the current Payment Estimate Destinate Exception 33 on the current Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 33 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimate of '3.67146' is applied (if non-zero).  Unit price based on averaged overrun adjustments for installed quantity on previous payment estimates. Price Adjustments of ',61.65146 - 57.98000, 'is applied (if non-zero).						
				Overrun - To	16 16 17 19 obtal	2021 Oct 19, 2021 Oct 19, 2021 Nov 2, 2021 Dec 2, 2021 Sep 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$85,243.90 \$13,815.69 (\$98,191.66) \$286.06 (\$97,905.60) (\$97,905.60) \$294.35	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 33 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 33 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimate of '3.67146' is applied (if non-zero).  Unit price based on averaged overrun adjustments for installed quantity on previous payment estimates. Price Adjustments of ',61.65146 - 57.98000, 'is applied (if non-zero).						
			Overrun - To	Overrun - To	16 16 17 19 14 15	2021 Oct 19, 2021  Oct 19, 2021  Nov 2, 2021  Dec 2, 2021  Sep 16, 2021  Oct 4, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$85,243.90 \$13,815.69 (\$98,191.66) \$286.06 (\$97,905.60) (\$97,905.60) \$294.35	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 33 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 33 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimate of '3.67146' is applied (if non-zero).  Unit price based on averaged overrun adjustments for installed quantity on previous payment estimates. Price Adjustments of ',61.65146 - 57.98000, 'is applied (if non-zero).  Reference Item Price Adjustment Index Adjustment Type applied is FUEL						
			Overrun - To	Overrun - To	16 16 17 19 obtal	2021 Oct 19, 2021 Oct 19, 2021 Nov 2, 2021 Dec 2, 2021 Sep 16, 2021 Oct 4,	SYSTEM SYSTEM SYSTEM SYSTEM	\$85,243.90 \$13,815.69 (\$98,191.66) \$286.06 (\$97,905.60) (\$97,905.60) \$294.35	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 33 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 33 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '3.67146' is applied (if non-zero).  Unit price based on averaged overrun adjustments for installed quantity on a previous payment estimates. Price Adjustments of ',61.65146 - 57.98000, 'is applied (if non-zero).						
			Overrun - To	Overrun - To	16 16 17 19 14 15	2021 Oct 19, 2021 Oct 19, 2021 Nov 2, 2021 Dec 2, 2021 Sep 16, 2021 Oct 4, 2021 Oct 19,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$85,243.90 \$13,815.69 (\$98,191.66) \$286.06 (\$97,905.60) (\$97,905.60) \$294.35	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 33 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 33 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '3.67146' is applied (if non-zero).  Unit price based on averaged overrun adjustments for installed quantity on a previous payment estimates. Price Adjustments of ',61.65146 - 57.98000, 'is applied (if non-zero).  Reference Item Price Adjustment Index Adjustment Type applied is FUEL						
			Overrun - To	Overrun - To	16  16  17  19  14  15  16	2021 Oct 19, 2021  Oct 19, 2021  Nov 2, 2021  Dec 2, 2021  Cct 4, 2021  Oct 19, 2021  Dec 2, 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$85,243.90 \$13,815.69 (\$98,191.66) \$286.06 (\$97,905.60) (\$97,905.60) \$294.35 \$15,616.79 \$15,595.11	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 33 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 33 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '3.67146' is applied (if non-zero).  Unit price based on averaged overrun adjustments for installed quantity on a previous payment estimates. Price Adjustments of ',61.65146 - 57.98000, 'is applied (if non-zero).  Reference Item Price Adjustment Index Adjustment Type applied is FUEL  Reference Item Price Adjustment Index Adjustment Type applied is FUEL						
			Overrun - To	Overrun - To tal - Total	16  16  17  19  14  15  16	2021 Oct 19, 2021  Oct 19, 2021  Nov 2, 2021  Dec 2, 2021  Cct 4, 2021  Oct 19, 2021  Dec 2, 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$85,243.90 \$13,815.69 (\$98,191.66) \$286.06 (\$97,905.60) (\$97,905.60) \$294.35 \$15,616.79 \$15,595.11 (\$19.87)	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 33 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 33 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '3.67146' is applied (if non-zero).  Unit price based on averaged overrun adjustments for installed quantity on a previous payment estimates. Price Adjustments of ',61.65146 - 57.98000, 'is applied (if non-zero).  Reference Item Price Adjustment Index Adjustment Type applied is FUEL  Reference Item Price Adjustment Index Adjustment Type applied is FUEL						
	0040 -	Total	Overrun - To Price FUEL	Overrun - To tal - Total	16  16  17  19  14  15  16	2021 Oct 19, 2021  Oct 19, 2021  Nov 2, 2021  Dec 2, 2021  Cct 4, 2021  Oct 19, 2021  Dec 2, 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$85,243.90 \$13,815.69 (\$98,191.66) \$286.06 (\$97,905.60) (\$97,905.60) \$294.35 \$15,616.79 \$15,595.11 (\$19.87)	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 33 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 33 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '3.67146' is applied (if non-zero).  Unit price based on averaged overrun adjustments for installed quantity on a previous payment estimates. Price Adjustments of ',61.65146 - 57.98000, 'is applied (if non-zero).  Reference Item Price Adjustment Index Adjustment Type applied is FUEL  Reference Item Price Adjustment Index Adjustment Type applied is FUEL						
	0040 - 0050	Total  ASPH. CONC.  MIXTURE PG 76-22 (SP095BSM)	Overrun - To Price FUEL	Overrun - To tal - Total	16  16  17  19  14  15  16	2021 Oct 19, 2021  Oct 19, 2021  Nov 2, 2021  Dec 2, 2021  Cct 4, 2021  Oct 19, 2021  Dec 2, 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$85,243.90 \$13,815.69 (\$98,191.66) \$286.06 (\$97,905.60) \$294.35 \$15,616.79 \$15,595.11 (\$19.87) \$31,486.38	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 33 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 33 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '3.67146' is applied (if non-zero).  Unit price based on averaged overrun adjustments for installed quantity on a previous payment estimates. Price Adjustments of ',61.65146 - 57.98000, 'is applied (if non-zero).  Reference Item Price Adjustment Index Adjustment Type applied is FUEL  Reference Item Price Adjustment Index Adjustment Type applied is FUEL						





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																									
J4I3222	0050	ASPH. CONC. MIXTURE PG	Other Item	ACAD		2021																												
		76-22 (SP095BSM)	Adjustment	ACAD - Tota	al			\$196,453.12																										
				FUEL	19	Dec 2, 2021	frizzm	\$626.66																										
				FUEL - Tota	ıl			\$626.66																										
			Other Item A	.djustment - T	otal			\$197,079.78																										
			Price FUEL		13	Sep 2, 2021	SYSTEM	\$9,778.05	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																									
					14	Sep 16, 2021	SYSTEM	\$39,837.79	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																									
					15	Oct 4, 2021	SYSTEM	\$49,754.22	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																									
					19	Dec 2, 2021	SYSTEM	\$19.87	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																									
				- Total				\$99,389.93																										
			Price FUEL -	Total				\$99,389.93																										
	0050 -	Total						\$296,469.71																										
	0800	FURN & PLACE CONC MATL FOR FULL DEPTH	Material		10	Jul 1, 2021	SYSTEM	\$81,468.66	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate.																									
					10	Jul 1, 2021	SYSTEM	(\$81,468.66)																										
									11	Jul 16, 2021	SYSTEM	\$532,325.76	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate.																					
																					11	Jul 16, 2021	SYSTEM	(\$532,325.76)										
										12	Aug 17, 2021	SYSTEM	\$532,325.76	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate.																				
								12	Aug 17, 2021	SYSTEM	(\$532,325.76)																							
																							13	Sep 2, 2021	SYSTEM	\$532,325.76	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user frizzm overridding Payment Estimate Exception 5 on the current Payment Estimate.							
					13	Sep 2, 2021	SYSTEM	(\$532,325.76)																										
				- Total				\$0.00																										
			Material - To	tal				\$0.00																										
	0080 -	Total						\$0.00																										
	0120	DOWEL BAR (DRILLING, FURNISHING AND	Material		10	Jul 1, 2021	SYSTEM	\$595.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user frizzm overridding Payment Estimate Exception 7 on the current Payment Estimate.																									
		INST			10	Jul 1, 2021	SYSTEM	(\$595.00)																										
													11	Jul 16, 2021	SYSTEM	\$6,196.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user frizzm overridding Payment Estimate Exception 7 on the current Payment Estimate.																	
					11	Jul 16, 2021	SYSTEM	(\$6,196.50)																										
																														12	Aug 17, 2021	SYSTEM	\$6,196.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user frizzm overridding Payment Estimate Exception 5 on the current Payment Estimate.
													12	Aug 17, 2021	SYSTEM	(\$6,196.50)																		
					13	13	Sep 2, 2021	SYSTEM	\$6,196.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user frizzm overridding Payment Estimate Exception 6 on the current Payment Estimate.																								
					13	Sep 2, 2021	SYSTEM	(\$6,196.50)																										
					14	Sep 16, 2021	SYSTEM	\$6,196.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user frizzm overridding Payment Estimate Exception 5 on the current Payment Estimate.																									





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
J4I3222	0120	DOWEL BAR (DRILLING,	Material		14	Sep 16, 2021	SYSTEM	(\$6,196.50)				
		FURNISHING AND INST			15	Oct 4, 2021	SYSTEM	\$6,196.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user frizzm overridding Payment Estimate Exception 5 on the current Payment Estimate.			
					15	Oct 4, 2021	SYSTEM	(\$6,196.50)				
					16	Oct 19, 2021	SYSTEM	\$6,196.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user frizzm overridding Payment Estimate Exception 6 on the current Payment Estimate.			
					16	Oct 19, 2021	SYSTEM	(\$6,196.50)				
					17	Nov 2, 2021	SYSTEM	\$6,196.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user frizzm overridding Payment Estimate Exception 6 on the current Payment Estimate.			
					17	Nov 2, 2021	SYSTEM	(\$6,196.50)				
					18	Nov 16, 2021	SYSTEM	\$6,196.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodyb1 overridding Payment Estimate Exception 8 on the current Payment Estimate.			
					18	Nov 16, 2021	SYSTEM	(\$6,196.50)				
					19	Dec 2, 2021	SYSTEM	\$6,196.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 8 on the current Payment Estimate.			
					19	Dec 2, 2021	SYSTEM	(\$6,196.50)				
				- Total				\$0.00				
			Material - To	tal				\$0.00				
	0120 -							\$0.00				
	0130	DOWEL BAR (FURNISH AND INSTALL WITH BASK	Material	Material	Material	Material		10	Jul 1, 2021	SYSTEM	\$107.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user frizzm overridding Payment Estimate Exception 8 on the current Payment Estimate.
					10	Jul 1, 2021	SYSTEM	(\$107.25)				
					11	Jul 16, 2021	SYSTEM	\$660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user frizzm overridding Payment Estimate Exception 8 on the current Payment Estimate.			
					11	Jul 16, 2021	SYSTEM	(\$660.00)				
					12	Aug 17, 2021	SYSTEM	\$660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user frizzm overridding Payment Estimate Exception 6 on the current Payment Estimate.			
					12	Aug 17, 2021	SYSTEM	(\$660.00)				
					13	Sep 2, 2021	SYSTEM	\$660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 7 on the current Payment Estimate.			
					13	Sep 2, 2021	SYSTEM	(\$660.00)				
					14	Sep 16, 2021	SYSTEM	\$660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user frizzm overridding Payment Estimate Exception 6 on the current Payment Estimate.			
					14	Sep 16, 2021	SYSTEM	(\$660.00)				
					15	Oct 4, 2021	SYSTEM	\$660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user frizzm overridding Payment Estimate Exception 6 on the current Payment Estimate.			
					15	Oct 4, 2021	SYSTEM	(\$660.00)				
					16	Oct 19, 2021	SYSTEM	\$660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user frizzm overridding Payment Estimate Exception 7 on the current Payment Estimate.			
					16	Oct 19, 2021	SYSTEM	(\$660.00)				





Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
J4I3222	0130	DOWEL BAR	Material	Туре		2021			Estimate Item Adjustment (0005) due to user frizzm overridding Payment
		(FURNISH AND INSTALL WITH			17	Nov 2,	SYSTEM	(\$660.00)	Estimate Exception 7 on the current Payment Estimate.
		BASK				2021		, ,	
					18	Nov 16, 2021	SYSTEM	\$660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodyb1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					18	Nov 16, 2021	SYSTEM	(\$660.00)	
					19	Dec 2, 2021	SYSTEM	\$660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 9 on the current Payment Estimate.
					19	Dec 2, 2021	SYSTEM	(\$660.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0130 -							\$0.00	
	0140	TIE BAR (DRILL, FURN & INSTAL) (TYPE L	Material		10	Jul 1, 2021	SYSTEM	\$525.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 11 on the current Payment Estimate.
					10	Jul 1, 2021	SYSTEM	(\$525.00)	
					11	Jul 16, 2021	SYSTEM	\$2,895.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 11 on the current Payment Estimate.
					11	Jul 16, 2021	SYSTEM	(\$2,895.00)	
					12	Aug 17, 2021	SYSTEM	\$2,895.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 9 on the current Payment Estimate.
					12	Aug 17, 2021	SYSTEM	(\$2,895.00)	
					13	Sep 2, 2021	SYSTEM	\$2,895.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 10 on the current Payment Estimate.
					13	Sep 2, 2021	SYSTEM	(\$2,895.00)	
					14	Sep 16, 2021	SYSTEM	\$2,895.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user frizzm overridding Payment Estimate Exception 9 on the current Payment Estimate.
					14	Sep 16, 2021	SYSTEM	(\$2,895.00)	
					15	Oct 4, 2021	SYSTEM	\$2,895.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user frizzm overridding Payment Estimate Exception 9 on the current Payment Estimate.
					15	Oct 4, 2021	SYSTEM	(\$2,895.00)	
					16	Oct 19, 2021	SYSTEM	\$2,895.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user frizzm overridding Payment Estimate Exception 10 on the current Payment Estimate.
					16	Oct 19, 2021	SYSTEM	(\$2,895.00)	
					17	Nov 2, 2021	SYSTEM	\$2,895.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 10 on the current Payment Estimate.
					17	Nov 2, 2021	SYSTEM	(\$2,895.00)	
					18	Nov 16, 2021	SYSTEM	\$2,895.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodyb1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					18	Nov 16, 2021	SYSTEM	(\$2,895.00)	
					19	Dec 2, 2021	SYSTEM	\$2,895.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Exception 12 on the current Payment Estimate.
					19	Dec 2,	SYSTEM	(\$2,895.00)	





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks									
J4I3222	0140	TIE BAR (DRILL,	Material			2021												
		FURN & INSTAL) (TYPE L		- Total				\$0.00										
			Material - To	tal				\$0.00										
	0140 -	Total						\$0.00										
	0150	FURN & PLACE BIT. MATL FOR CL B PARTIAL	Material		13	Sep 2, 2021	SYSTEM	\$16,707.27	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Exception 12 on the current Payment Estimate.									
					13	Sep 2, 2021	SYSTEM	(\$16,707.27)										
					14	Sep 16, 2021	SYSTEM	\$16,707.27	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user frizzm overridding Payment Estimate Exception 11 on the current Payment Estimate.									
					14	Sep 16, 2021	SYSTEM	(\$16,707.27)										
					15	Oct 4, 2021	SYSTEM	\$16,707.27	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user frizzm overridding Payment Estimate Exception 11 on the current Payment Estimate.									
					15	Oct 4, 2021	SYSTEM	(\$16,707.27)										
					16	Oct 19, 2021	SYSTEM	\$16,707.27	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user frizzm overridding Payment Estimate Exception 12 on the current Payment Estimate.									
					16	Oct 19, 2021	SYSTEM	(\$16,707.27)										
											17	Nov 2, 2021	SYSTEM	\$16,707.27	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Exception 12 on the current Payment Estimate.			
														17	Nov 2, 2021	SYSTEM	(\$16,707.27)	
					18	Nov 16, 2021	SYSTEM	\$16,707.27	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodyb1 overridding Payment Estimate Exception 14 on the current Payment Estimate.									
					18	Nov 16, 2021	SYSTEM	(\$16,707.27)										
										19	Dec 2, 2021	SYSTEM	\$16,707.27	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user frizzm overridding Payment Estimate Exception 14 on the current Payment Estimate.				
					19	Dec 2, 2021	SYSTEM	(\$16,707.27)										
				- Total	1027			\$0.00										
			Material - To	tal				\$0.00										
			Other Item	Other Item Adjustment	Other Item	ACAD	16	Oct 19, 2021	frizzm	\$305.34	AC adjustments for Line No. 0150. See 201016-C02_J4l3222_Asphalt Roadway Reports Line No. 0150_Class B for details.							
				ACAD - Tot	al			\$305.34										
				FUEL	16	Oct 19, 2021	frizzm	\$326.71	Fuel price adjustments for Line No. 0150. See 201016-C02_J4l3222_Asphalt Roadway Reports Line No. 0150_Class B for details.									
				FUEL - Tota				\$326.71										
			Other Item A	djustment - T	otal			\$632.05										
	0150 -	Total						\$632.05										
	0170	MISC. PAVEMENT REPAIR	Material		13	Sep 2, 2021	SYSTEM	\$48,255.44	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user frizzm overridding Payment Estimate Exception 13 on the current Payment Estimate.									
						13				1		13	13	13	Sep 2, 2021	SYSTEM	(\$48,255.44)	
							14	Sep 16, 2021	SYSTEM	Estimate Item Adjustment (0013) due to user frizzm over	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user frizzm overridding Payment Estimate Exception 12 on the current Payment Estimate.							
					14	Sep 16, 2021	SYSTEM	(\$48,255.44)										
					1	1		15	Oct 4, 2021	SYSTEM	\$48,255.44	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user frizzm overridding Payment Estimate Exception 12 on the current Payment Estimate.						
					15	Oct 4, 2021	SYSTEM	(\$48,255.44)										

Dec 13, 2021



### Line Item Adjustments by Estimate

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
0170	MISC. PAVEMENT REPAIR	Material		16	Oct 19, 2021	SYSTEM	\$48,255.44	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user frizzm overridding Payment Estimate Exception 13 on the current Payment Estimate.			
				16	Oct 19, 2021	SYSTEM	(\$48,255.44)				
				17	Nov 2, 2021	SYSTEM	\$48,255.44	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user frizzm overridding Payment Estimate Exception 13 on the current Payment Estimate.			
				17	Nov 2, 2021	SYSTEM	(\$48,255.44)				
				18	Nov 16, 2021	SYSTEM	\$48,255.44	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodyb1 overridding Paym Estimate Exception 15 on the current Payment Estimate.			
				18	Nov 16, 2021	SYSTEM	(\$48,255.44)				
					1:	19	Dec 2, 2021	SYSTEM	\$48,255.44	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user frizzm overridding Payment Estimate Exception 15 on the current Payment Estimate.	
				19	Dec 2, 2021	SYSTEM	(\$48,255.44)				
			- Total				\$0.00				
		Material - To	tal				\$0.00				
0170 -	Total						\$0.00				
0180 MISC. PAVEMENT REPAIR	Other Item Adjustment	ACAD	16	Oct 19, 2021	frizzm	\$8,642.99	AC adjustments for Line No. 0180. See 201016-C02_J4l3222_Asphalt Roadway Reports Line No. 0180_Class C for details.				
			ACAD - Tota	al			\$8,642.99				
			FUEL	16	Oct 19, 2021	frizzm	\$9,248.00	Fuel price adjustments for Line No. 0180. See 201016-C02_J4l3222_As Roadway Reports Line No. 0180_Class C for details.			
			FUEL - Tota	ıl			\$9,248.00				
		Other Item A	.djustment - T	otal			\$17,890.99				
		Overrun	Overrun	13	Sep 2, 2021	SYSTEM	\$937.92	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user frizzm overridding Payment Estimate Exception 17 on the current Payment Estimate.			
				13	Sep 2, 2021	SYSTEM	(\$937.92)				
				14	Sep 16, 2021	SYSTEM	(\$937.92)	Averaged Price Adjustment from this item on all previous payment estima of '0.00000' is applied (if non-zero).			
				14	Sep 16, 2021	SYSTEM	\$937.92	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user frizzm overridding Payment Estimate Exception 16 on the current Payment Estimate.			
				15	Oct 4, 2021	SYSTEM	(\$937.92)	Averaged Price Adjustment from this item on all previous payment estimof '0.00000' is applied (if non-zero).			
				15	Oct 4, 2021	SYSTEM	\$937.92	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user frizzm overridding Payment Estimate Exception 26 on the current Payment Estimate.			
				16	Oct 19, 2021	SYSTEM	(\$937.92)	Averaged Price Adjustment from this item on all previous payment estimof '0.00000' is applied (if non-zero).			
							16	Oct 19, 2021	SYSTEM	\$937.92	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user frizzm overridding Payment Estimate Exception 34 on the current Payment Estimate.
				17	Nov 2, 2021	SYSTEM	(\$937.92)	Averaged Price Adjustment from this item on all previous payment estima of '0.00000' is applied (if non-zero).			
			Overrun - T	otal			(\$937.92)				
		Overrun - To	tal				(\$937.92)				
0180 -	Total						\$16,953.07				
0190	CONSTRUCTION SIGNS	Material		10	Jul 1, 2021	SYSTEM	\$3,914.65	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 14 on the current Payment Estimate.			
				10	Jul 1, 2021	SYSTEM	(\$3,914.65)				
			- Total				\$0.00				
		Material - To	tal				\$0.00				
		Material - 10	tui								





ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
22	0200	FLAG ASSEMBLY	Material		10	Jul 1, 2021	SYSTEM	\$30.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Exception 15 on the current Payment Estimate.			
					10	Jul 1, 2021	SYSTEM	(\$30.00)				
				- Total				\$0.00				
			Material - To	tal				\$0.00				
	0200 -	Total						\$0.00				
	0210	CHANNELIZER (TRIM LINE) WITH LIGHT	Material		10	Jul 1, 2021	SYSTEM	\$4,940.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user frizzm overridding Payment Estimate Exception 16 on the current Payment Estimate.			
					10	Jul 1, 2021	SYSTEM	(\$4,940.00)				
				- Total				\$0.00				
			Material - To	tal				\$0.00				
	0210 -	Total						\$0.00				
	0230	FLASHING ARROW PANEL	Material		10	Jul 1, 2021	SYSTEM	\$8,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user frizzm overridding Payment Estimate Exception 17 on the current Payment Estimate.			
					10	Jul 1, 2021	SYSTEM	(\$8,000.00)				
	0230 - Total			- Total				\$0.00				
			Material - To	tal				\$0.00				
								\$0.00				
	0250		TRAFFIC	Material		16	Oct 19, 2021	SYSTEM	\$15,759.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user frizzm overridding Payment Estimate Exception 17 on the current Payment Estimate.		
						16	Oct 19, 2021	SYSTEM	(\$15,759.00)			
					17	Nov 2, 2021	SYSTEM	\$6,618.78	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user frizzm overridding Payment Estimate Exception 17 on the current Payment Estimate.			
					17	Nov 2, 2021	SYSTEM	(\$6,618.78)				
					18	Nov 16, 2021	SYSTEM	\$6,618.78	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodyb1 overridding Payment Estimate Exception 19 on the current Payment Estimate.			
					18	Nov 16, 2021	SYSTEM	(\$6,618.78)				
							19	Dec 2, 2021	SYSTEM	\$6,618.78	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user frizzm overridding Payment Estimate Exception 19 on the current Payment Estimate.	
					19	Dec 2, 2021	SYSTEM	(\$6,618.78)				
				- Total				\$0.00				
			Material - To	tal				\$0.00				
	0250 -	Total						\$0.00				
	0280	PREF THERMO PVMT MARK, 24 IN WHIT	Material		17	Nov 2, 2021	SYSTEM	\$6,642.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user frizzm overridding Payment Estimate Exception 23 on the current Payment Estimate.			
					17	Nov 2, 2021	SYSTEM	(\$6,642.00)				
						18	Nov 16, 2021	SYSTEM	\$6,642.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodyb1 overridding Payment Estimate Exception 25 on the current Payment Estimate.		
					18	Nov 16, 2021	SYSTEM	(\$6,642.00)				
					19	Dec 2, 2021	SYSTEM	\$6,642.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user frizzm overridding Payment Estimate Exception 25 on the current Payment Estimate.			
								19	Dec 2, 2021	SYSTEM	(\$6,642.00)	
					- Total				\$0.00			



## MoDOT

### Line Item Adjustments by Estimate

ct Line Description Adjustment Other Est. Created Cre										
et l	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
2 0	0280	PREF THERMO PVMT MARK, 24 IN WHIT	Material - To	tal				\$0.00		
0	)280 -	Total						\$0.00		
	0290	PREF THERMO PVMT MARK, 24 IN YELLOW	Material		17	Nov 2, 2021	SYSTEM	\$7,614.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user frizzm overridding Payment Estimate Exception 24 on the current Payment Estimate.	
					17	Nov 2, 2021	SYSTEM	(\$7,614.00)		
					18	Nov 16, 2021	SYSTEM	\$7,614.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodyb1 overridding Payment Estimate Exception 26 on the current Payment Estimate.	
					18	Nov 16, 2021	SYSTEM	(\$7,614.00)		
					19	Dec 2, 2021	SYSTEM	\$7,614.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user frizzm overridding Payment Estimate Exception 26 on the current Payment Estimate.	
					19	Dec 2, 2021	SYSTEM	(\$7,614.00)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
0	290 -	Total						\$0.00		
0	0300	PREF THERMO PVMT MARK, LT/RT ARROW	Material		17	Nov 2, 2021	SYSTEM	\$6,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user frizzm overridding Payment Estimate Exception 25 on the current Payment Estimate.	
					17	Nov 2, 2021	SYSTEM	(\$6,250.00)		
					18	Nov 16, 2021	SYSTEM	\$6,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user woodyb1 overridding Payment Estimate Exception 27 on the current Payment Estimate.	
					18	Nov 16, 2021	SYSTEM	(\$6,250.00)		
						19	Dec 2, 2021	SYSTEM	\$6,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user frizzm overridding Payment Estimate Exception 27 on the current Payment Estimate.
					19	Dec 2, 2021	SYSTEM	(\$6,250.00)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
0	300 -	Total						\$0.00		
0	0310	6 IN. WHITE HIGH BUILD WATERBORNE PAINT	Material		17	Nov 2, 2021	SYSTEM	\$20,225.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user frizzm overridding Payment Estimate Exception 26 on the current Payment Estimate.	
		FAINI			17	Nov 2, 2021	SYSTEM	(\$20,225.92)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
0	310 -	Total						\$0.00		
0	0320	6 IN. YELLOW HIGH BUILD WATERBORNE	Material		17	Nov 2, 2021	SYSTEM	\$16,346.72	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user frizzm overridding Payment Estimate Exception 28 on the current Payment Estimate.	
		PAINT			17	Nov 2, 2021	SYSTEM	(\$16,346.72)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
0	320 -	Total						\$0.00		
0	0330		Material		17	Nov 2, 2021	SYSTEM	\$1,813.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user frizzm overridding Payment Estimate Exception 30 on the current Payment Estimate.	
						17	Nov 2, 2021	SYSTEM	(\$1,813.80)	
		- Total					\$0.00			
		Material - To	tal				\$0.00			





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J4I3222	0330 -	Total						\$0.00		
	0350	COLDMILLING BIT. PAVT FOR REM OF SURF.	Overrun	Overrun	16	Oct 19, 2021	SYSTEM	\$1,864.71	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user frizzm overridding Payment Estimate Exception 35 on the current Payment Estimate.	
					16	Oct 19, 2021	SYSTEM	(\$1,864.71)		
					17	Nov 2, 2021	SYSTEM	(\$1,864.71)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	
				Overrun - T	otal			(\$1,864.71)		
			Overrun - To	tal				(\$1,864.71)		
	0350 -	Total						(\$1,864.71)		
	0380	GUARDRAIL TYPE A WITH	Construction Stockpile		9	Jun 17, 2021	SYSTEM	(\$1,846.25)	Payment Estimate Item Adjustment generated Stockpile Transaction	
		RUBRAIL		- Total				(\$1,846.25)		
			Construction	Stockpile - 1	otal			(\$1,846.25)		
			Construction Stockpile STMI		1	Feb 16, 2021	SYSTEM	\$1,846.25	Payment Estimate Item Adjustment generated Stockpile Transaction	
			STIVII	- Total				\$1,846.25		
			Construction	Stockpile S	MI - Total			\$1,846.25		
			Material		9	Jun 17, 2021	SYSTEM	\$2,655.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					9	Jun 17, 2021	SYSTEM	(\$2,655.50)		
					10	Jul 1, 2021	SYSTEM	\$2,655.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					10	Jul 1, 2021	SYSTEM	(\$2,655.50)		
						11	Jul 16, 2021	SYSTEM	\$2,655.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.
						11	Jul 16, 2021	SYSTEM	(\$2,655.50)	
						12	Aug 17, 2021	SYSTEM	\$2,655.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.
					12	Aug 17, 2021	SYSTEM	(\$2,655.50)		
					13	Sep 2, 2021	SYSTEM	\$2,655.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user frizzm overridding Payment Estimate Exception 2 on the current Payment Estimate.	
					13	Sep 2, 2021	SYSTEM	(\$2,655.50)		
					17	Nov 2, 2021	SYSTEM	\$2,655.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user frizzm overridding Payment Estimate Exception 3 on the current Payment Estimate.	
					17	Nov 2, 2021	SYSTEM	(\$2,655.50)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
			Overrun	Overrun	16	Oct 19, 2021	SYSTEM	(\$2,655.50)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	
					16	Oct 19, 2021	SYSTEM	\$2,655.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user frizzm overridding Payment Estimate Exception 36 on the current Payment Estimate.	
				Overrun - Total				\$0.00		
			Overrun - To	tal				\$0.00		
	0380 -	Total						\$0.00		
	0390	GUARDRAIL TYPE E, 6 FT. POST, 3 FT1.5	Material		7	May 17, 2021	SYSTEM	\$1,175.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.	





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks										
J4I3222	0390	GUARDRAIL TYPE E, 6 FT.	Material		7	May 17, 2021	SYSTEM	(\$1,175.00)											
		POST, 3 FT1.5			8	Jun 1, 2021	SYSTEM	\$2,056.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.										
					8	Jun 1, 2021	SYSTEM	(\$2,056.25)											
				- Total				\$0.00											
			Material - Tot	tal				\$0.00											
	0390 -	Total						\$0.00											
	0400	MGS GUARDRAIL	Construction Stockpile		2	Mar 3, 2021	SYSTEM	(\$36,103.78)	Payment Estimate Item Adjustment generated Stockpile Transaction										
					3	Mar 16, 2021	SYSTEM	(\$40,951.63)	Payment Estimate Item Adjustment generated Stockpile Transaction										
					4	Apr 2, 2021	SYSTEM	(\$18,753.56)	Payment Estimate Item Adjustment generated Stockpile Transaction										
					5	Apr 16, 2021	SYSTEM	(\$24,116.81)	Payment Estimate Item Adjustment generated Stockpile Transaction										
					6	May 1, 2021	SYSTEM	(\$9,185.41)	Payment Estimate Item Adjustment generated Stockpile Transaction										
					7	May 17, 2021	SYSTEM	(\$53,836.73)	Payment Estimate Item Adjustment generated Stockpile Transaction										
					8	Jun 1, 2021	SYSTEM	(\$5,230.58)	Payment Estimate Item Adjustment generated Stockpile Transaction										
					9	Jun 17, 2021	SYSTEM	(\$23,843.75)	Payment Estimate Item Adjustment generated Stockpile Transaction										
				- Total				(\$212,022.25)											
			Construction	Stockpile - 1	Γotal			(\$212,022.25)											
			Construction Stockpile STMI		1	Feb 16, 2021	SYSTEM	\$212,022.25	Payment Estimate Item Adjustment generated Stockpile Transaction										
			- Total	- Total				\$212,022.25											
			Construction Material	Stockpile S1	ГМI - Total			\$212,022.25											
				aterial	2	Mar 3, 2021	SYSTEM	\$57,484.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.										
						2	Mar 3, 2021	SYSTEM	(\$57,484.38)										
					3	Mar 16, 2021	SYSTEM	\$122,687.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.										
					3	Mar 16, 2021	SYSTEM	(\$122,687.50)											
															4	Apr 2, 2021	SYSTEM	\$152,546.88	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.
																		4	Apr 2, 2021
					5	Apr 16, 2021	SYSTEM	\$190,945.62	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.										
									,	ţ	5				5	Apr 16, 2021	SYSTEM	(\$190,945.62)	
					6	May 1, 2021	SYSTEM	\$205,570.62	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.										
							$\epsilon$	6	6		6	6	6	May 1, 2021	SYSTEM	(\$205,570.62)			
					7	May 17, 2021	SYSTEM	\$291,289.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user frizzm overridding Payment Estimate Exception 2 on the current Payment Estimate.										
					7	May 17, 2021	SYSTEM	(\$291,289.38)											
								8	Jun 1, 2021	SYSTEM	\$299,617.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user frizzm overridding Payment							





Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks											
			Туре	Adjustment Type	Number	Date	Ву													
J4I3222	0400	MGS GUARDRAIL	Material						Estimate Exception 2 on the current Payment Estimate.											
					8	Jun 1, 2021	SYSTEM	(\$299,617.50)												
				- Total				\$0.00												
			Material - Tot	tal				\$0.00												
			Overrun	Overrun	9	Jun 17, 2021	SYSTEM	(\$4,273.75)												
					16	Oct 19, 2021	SYSTEM	\$4,273.75	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',16.25000 - 16.25000, 'is applied (if non-zero).											
				Overrun - T	otal			\$0.00												
			Overrun - To	tal				\$0.00												
	0400 -	Total						\$0.00												
	0410	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN	Construction Stockpile		3	Mar 16, 2021	SYSTEM	(\$11,862.83)	Payment Estimate Item Adjustment generated Stockpile Transaction											
		F1 3 IIV			4	Apr 2, 2021	SYSTEM	(\$9,705.95)	Payment Estimate Item Adjustment generated Stockpile Transaction											
					5	Apr 16, 2021	SYSTEM	(\$29,271.91)	Payment Estimate Item Adjustment generated Stockpile Transaction											
					6	May 1, 2021	SYSTEM	(\$51,461.31)	Payment Estimate Item Adjustment generated Stockpile Transaction											
				- Total				(\$102,302.00)												
			Construction	Stockpile - 1	Γotal			(\$102,302.00)												
			Construction Stockpile STMI		1	Feb 16, 2021	SYSTEM	\$102,302.00	Payment Estimate Item Adjustment generated Stockpile Transaction											
			STIVII	- Total				\$102,302.00												
			Constructio	Stockpile S	TMI - Total			\$102,302.00												
			Material		3	Mar 16, 2021	SYSTEM	\$18,768.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user frizzm overridding Payment Estimate Exception 2 on the current Payment Estimate.											
					3	Mar 16, 2021	SYSTEM	(\$18,768.75)												
					4	Apr 2, 2021	SYSTEM	\$34,125.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user frizzm overridding Payment Estimate Exception 2 on the current Payment Estimate.											
							4	Apr 2, 2021	SYSTEM	(\$34,125.00)										
					5	Apr 16, 2021	SYSTEM	\$80,437.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user frizzm overridding Payment Estimate Exception 2 on the current Payment Estimate.											
					5	Apr 16, 2021	SYSTEM	(\$80,437.50)												
								6	May 1, 2021	SYSTEM	\$184,518.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user frizzm overridding Payment Estimate Exception 2 on the current Payment Estimate.								
					7 8			7					6		6	6	May 1, 2021	SYSTEM	(\$184,518.75)	
															7	7		7	May 17, 2021	SYSTEM
										7	May 17, 2021	SYSTEM	(\$214,743.75)							
														8	Jun 1, 2021	SYSTEM	\$214,743.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user frizzm overridding Payment Estimate Exception 3 on the current Payment Estimate.		
								8	Jun 1, 2021	SYSTEM	(\$214,743.75)									
				9	Jun 17, 2021	SYSTEM	\$239,118.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 2 on the current Payment Estimate.												
					9	Jun 17, 2021	SYSTEM	(\$239,118.75)												
				10	Jul 1,	SYSTEM	\$239,118.75	This adjustment offsets the original system-generated Material Payment												





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks								
J4I3222	0410	MGS GUARDRAIL, 8 FT. POSTS, 6	Material			2021			Estimate Item Adjustment (0002) due to user frizzm overridding Payment Estimate Exception 2 on the current Payment Estimate.								
		FT 3 IN			10	Jul 1, 2021	SYSTEM	(\$239,118.75)									
					11	Jul 16, 2021	SYSTEM	\$239,118.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user frizzm overridding Payment Estimate Exception 2 on the current Payment Estimate.								
					11	Jul 16, 2021	SYSTEM	(\$239,118.75)									
					12	Aug 17, 2021	SYSTEM	\$239,118.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user frizzm overridding Payment Estimate Exception 2 on the current Payment Estimate.								
					12	Aug 17, 2021	SYSTEM	(\$239,118.75)									
					13	Sep 2, 2021	SYSTEM	\$239,118.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user frizzm overridding Payment Estimate Exception 3 on the current Payment Estimate.								
					13	Sep 2, 2021	SYSTEM	(\$239,118.75)									
					14	Sep 16, 2021	SYSTEM	\$239,118.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user frizzm overridding Payment Estimate Exception 3 on the current Payment Estimate.								
					14	Sep 16, 2021	SYSTEM	(\$239,118.75)									
					15	Oct 4, 2021	SYSTEM	\$239,118.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user frizzm overridding Payment Estimate Exception 3 on the current Payment Estimate.								
					15	Oct 4, 2021	SYSTEM	(\$239,118.75)									
					16	Oct 19, 2021	SYSTEM	\$239,118.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate.								
							16	Oct 19, 2021	SYSTEM	(\$239,118.75)							
					17	Nov 2, 2021	SYSTEM	\$239,118.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate.								
								17	Nov 2, 2021	SYSTEM	(\$239,118.75)						
					18	Nov 16, 2021	SYSTEM	\$239,118.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodyb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.								
											18	Nov 16, 2021	SYSTEM	(\$239,118.75)			
												19	Dec 2, 2021	SYSTEM	\$239,118.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user frizzm overridding Payment Estimate Exception 3 on the current Payment Estimate.	
					19	Dec 2, 2021	SYSTEM	(\$239,118.75)									
				- Total				\$0.00									
			Material - Tot				0)/0==-	\$0.00									
		Overrun	Overrun	Overrun	Overrun	Overrun	Overrun	Overrun	Overrun	Overrun	Overrun	Overrun	9	Jun 17, 2021	SYSTEM	\$3,656.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 5 on the current Payment Estimate. Material Insufficiency Quantity 12262.500; Overrun Quantity Balance 187.50.
					9	Jun 17, 2021	SYSTEM	(\$3,656.25)									
					10	Jul 1, 2021	SYSTEM	(\$3,656.25)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).								
					1	10	Jul 1, 2021	SYSTEM	\$3,656.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 19 on the current Payment Estimate. Material Insufficiency Quantity 12262.500; Overrun Quantity Balance 187.50.							
				11		11	Jul 16, 2021	SYSTEM	(\$3,656.25)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).							
						11	Jul 16, 2021	SYSTEM	\$3,656.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 14							





PFT-058-0	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
12	J4I3222	0410	8 FT. POSTS, 6	Overrun	Overrun					on the current Payment Estimate. Material Insufficiency Quantity 12262.500; Overrun Quantity Balance 187.50.
2021   September			FT 3 IN			12		SYSTEM	(\$3,656.25)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
2021   13   Sap 2, SYSTEM   \$3,660.25   The adjustment effects the original system-generated Overnux Payment Estimate Item Adjustment (port of System Item Adjustment (port of System Item Item Constitution						12		SYSTEM	\$3,656.25	Estimate Item Adjustment (0001) overridding Payment Estimate Exception 11 on the current Payment Estimate. Material Insufficiency Quantity 12262.500;
2021   Septide						13		SYSTEM	(\$3,656.25)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
2021   14   Sept 6, SYSTEM   \$3,668.25   Sept 6, SYSTEM   \$3,668.25   Sept 6, SYSTEM   \$2,021   SYSTEM   \$3,669.25   Sept 6, SYSTEM   Sy						13		SYSTEM	\$3,656.25	Estimate Item Adjustment (0011) overridding Payment Estimate Exception 18 on the current Payment Estimate. Material Insufficiency Quantity 12262.500;
2021						14		SYSTEM	(\$3,656.25)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
15						14		SYSTEM	\$3,656.25	Estimate Item Adjustment (0015) overridding Payment Estimate Exception 17 on the current Payment Estimate. Material Insufficiency Quantity 12262.500;
Description   Construction   Const						15		SYSTEM	(\$3,656.25)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
Overrun - Total						15		SYSTEM	\$3,656.25	Estimate Item Adjustment (0028) overridding Payment Estimate Exception 27 on the current Payment Estimate. Material Insufficiency Quantity 12262.500;
New							run - Total			
May 3, SYSTEM   St. A68.00   Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile Transaction				Overrun - To	tal					
APP. TRANS SEC (REGINO CURB)   Stockpile   Apr 2,   2021				0 1 11				OVOTEM		
Apr 2,   SYSTEM   (\$7,340.00)   Payment Estimate Item Adjustment generated Stockpile Transaction		0420	APP. TRANS SEC				2021			, , , , , ,
2021   5   Apr 16, SYSTEM   (\$5,872.00)   Payment Estimate Item Adjustment generated Stockpile Transaction   2021   7   May 17, SYSTEM   (\$4,404.00)   Payment Estimate Item Adjustment generated Stockpile Transaction   7   May 17, SYSTEM   (\$8,808.00)   Payment Estimate Item Adjustment generated Stockpile Transaction   2021   7   SYSTEM   (\$29,360.00)   Payment Estimate Item Adjustment generated Stockpile Transaction   2021						3		SYSTEM	(\$1,468.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
2021   6   May 1, 2021   7   May 17, 2021   7   May 17, 2021   (\$8,808.00)   Payment Estimate Item Adjustment generated Stockpile Transaction						4		SYSTEM	(\$7,340.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
2021   7   May 17, SYSTEM   (\$8,808.00)   Payment Estimate Item Adjustment generated Stockpile Transaction						5		SYSTEM	(\$5,872.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
Construction Stockpile - Total  Construction Stockpile - Total  Construction Stockpile - Total  Construction Stockpile STMI - Total  Construction Stockpile STMI - Total  Construction Stockpile STMI - Total  S29,360.00  This adjustment offsets the original system-generated Overrun Payment Estimate term Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 8 on the current Payment Estimate.  7 May 17, SYSTEM (\$2,400.00)  8 Jun 1, SYSTEM (\$2,400.00)  8 Jun 1, SYSTEM S2,400.00  This adjustment offsets the original system-generated Overrun Payment Estimate Exception 8 on the current Payment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  9 Jun 17, SYSTEM (\$2,400.00)  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  16 Oct 19, SYSTEM \$4,800.00  Unit price based on averaged overrun adjustments for installed quantity on a previous payment estimates. Price Adjustments of '2,2400.0000 or sapplied (if non-zero).						6		SYSTEM	(\$4,404.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
Construction Stockpile - Total  Construction Stockpile STMI - Total  Overrun  Ov						7		SYSTEM	(\$8,808.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
Construction Stockpile STMI - Total \$29,360.00  Construction Stockpile STMI - Total \$29,360.00  Construction Stockpile STMI - Total \$29,360.00  Coverrun Overrun Overrun 7 May 17, 2021 \$10 May 17, 2021 \$2,400.00 This adjustment offsets the original system-generated Overrun Payment Estimate Exception 8 on the current Payment Estimate.  7 May 17, 2021 \$10 May 18,					- Total				(\$29,360.00)	
Stockpile   STMI   Total   \$29,360.00				Construction	Stockpile - 1	Γotal			(\$29,360.00)	
Construction Stockpile STMI - Total  Overrun  Overrun  Overrun  Overrun  Overrun  Overrun  Overrun  Overrun  Overrun  T  May 17, 2021  SYSTEM  S2,400.00  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 8 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of "0.00000" is applied (if non-zero).  SYSTEM  SYSTEM  SYSTEM  S2,400.00  Averaged Price Adjustment from this item on all previous payment estimates of "0.00000" is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 8 on the current Payment Estimate Symmetric Extended Item Adjustment from this item on all previous payment estimates of "0.00000" is applied (if non-zero).  SYSTEM  Oct 19, SYSTEM  S4,800.00  Unit price based on averaged overrun adjustments for installed quantity on a previous payment estimates. Price Adjustments of ",2400.00000" is applied (if non-zero).				Stockpile		1		SYSTEM	\$29,360.00	Payment Estimate Item Adjustment generated Stockpile Transaction
Overrun Overrun 7 May 17, 2021 \$2,400.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 8 on the current Payment Estimate.  7 May 17, SYSTEM (\$2,400.00)  8 Jun 1, SYSTEM (\$2,400.00) Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  8 Jun 1, SYSTEM \$2,400.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 8 on the current Payment Estimate.  9 Jun 17, SYSTEM (\$2,400.00) Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  9 Jun 17, SYSTEM (\$2,400.00)  10 Oct 19, SYSTEM \$4,800.00 Unit price based on averaged overrun adjustments for installed quantity on a previous payment estimates. Price Adjustments of ',2400.00000 'is applied (if non-zero).				STIVII	- Total				\$29,360.00	
Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 8 on the current Payment Estimate.  7 May 17, 2021 (\$2,400.00)  8 Jun 1, 2021 (\$2,400.00) Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  8 Jun 1, 2021 SYSTEM (\$2,400.00) This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 8 on the current Payment Estimate.  9 Jun 17, SYSTEM (\$2,400.00) Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  9 Jun 17, SYSTEM (\$2,400.00)  10 Oct 19, 2021 SYSTEM (\$2,400.00)  11 Unit price based on averaged overrun adjustments for installed quantity on a previous payment estimates. Price Adjustments of ',2400.0000 - 2400.0000 is applied (if non-zero).				Construction	Stockpile S	ΓΜΙ - Total			\$29,360.00	
2021  8 Jun 1, 2021  8 Jun 1, 2021  8 Jun 1, 2021  8 SYSTEM (\$2,400.00) Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  8 Jun 1, 2021  8 SYSTEM \$2,400.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 8 on the current Payment Estimate.  9 Jun 17, 2021  9 Jun 17, 2021  10 Oct 19, 2021  11 Oct 19, 2021  12 SYSTEM \$4,800.00 Unit price based on averaged overrun adjustments for installed quantity on a previous payment estimates. Price Adjustments of ',2400.00000 'is applied (if non-zero).				Overrun	Overrun	7		SYSTEM	\$2,400.00	Estimate Item Adjustment (0006) due to user frizzm overridding Payment
2021 of '0.00000' is applied (if non-zero).  8 Jun 1, 2021 \$2,400.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 8 on the current Payment Estimate.  9 Jun 17, 2021 \$YSTEM (\$2,400.00) Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  9 Jun 17, 2021 \$YSTEM (\$2,400.00)  16 Oct 19, 2021 \$YSTEM \$4,800.00 Unit price based on averaged overrun adjustments for installed quantity on a previous payment estimates. Price Adjustments of ',2400.00000 'is applied (if non-zero).						7		SYSTEM	(\$2,400.00)	
Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 8 on the current Payment Estimate.  9 Jun 17, 2021 (\$2,400.00) Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  9 Jun 17, 2021 (\$2,400.00)  16 Oct 19, 2021 \$4,800.00 Unit price based on averaged overrun adjustments for installed quantity on a previous payment estimates. Price Adjustments of ',2400.0000 'is applied (if non-zero).						8		SYSTEM	(\$2,400.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
2021 of '0.00000' is applied (if non-zero).  9 Jun 17, 2021 (\$2,400.00)  16 Oct 19, 2021 \$4,800.00 Unit price based on averaged overrun adjustments for installed quantity on a previous payment estimates. Price Adjustments of ',2400.0000 'is applied (if non-zero).						8		SYSTEM	\$2,400.00	Estimate Item Adjustment (0005) due to user frizzm overridding Payment
2021  16 Oct 19, SYSTEM \$4,800.00 Unit price based on averaged overrun adjustments for installed quantity on a previous payment estimates. Price Adjustments of ',2400.00000 - 2400.0000 'is applied (if non-zero).						9		SYSTEM	(\$2,400.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
2021 previous payment estimates. Price Adjustments of ',2400.00000 - 2400.00000 is applied (if non-zero).						9		SYSTEM	(\$2,400.00)	
Overrup Total						16		SYSTEM	\$4,800.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',2400.00000 - 2400.00000, 'is applied (if non-zero).
Social So					Overrun - T	otal			\$0.00	





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																	
J4I3222	0420	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	Overrun - To	tal				\$0.00																		
	0420 -	Total						\$0.00																		
	0430	MGS LONG SPAN GUARDRAIL	Construction Stockpile		5	Apr 16, 2021	SYSTEM	(\$1,155.85)	Payment Estimate Item Adjustment generated Stockpile Transaction																	
		SECTION			16	Oct 19, 2021	SYSTEM	(\$1,155.85)	Payment Estimate Item Adjustment generated Stockpile Transaction																	
				- Total				(\$2,311.70)																		
			Construction	Stockpile - 1	Γotal			(\$2,311.70)																		
			Construction Stockpile		1	Feb 16, 2021	SYSTEM	\$2,311.70	Payment Estimate Item Adjustment generated Stockpile Transaction																	
			STMI	- Total				\$2,311.70																		
			Construction	¹ Stockpile S⊺	ГМI - Total			\$2,311.70																		
			Material		5	Apr 16, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate.																	
					5	Apr 16, 2021	SYSTEM	(\$2,200.00)																		
					6	May 1, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate.																	
					6	May 1, 2021	SYSTEM	(\$2,200.00)																		
					7	May 17, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Exception 5 on the current Payment Estimate.																	
					7	May 17, 2021	SYSTEM	(\$2,200.00)																		
						8	Jun 1, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 5 on the current Payment Estimate.																
					8	Jun 1, 2021	SYSTEM	(\$2,200.00)																		
					9	Jun 17, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user frizzm overridding Payment Estimate Exception 3 on the current Payment Estimate.																	
							9	Jun 17, 2021	SYSTEM	(\$2,200.00)																
					10	Jul 1, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user frizzm overridding Payment Estimate Exception 3 on the current Payment Estimate.																	
																						10	Jul 1, 2021	SYSTEM	(\$2,200.00)	
						11	Jul 16, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Exception 3 on the current Payment Estimate.																
															11	Jul 16, 2021	SYSTEM	(\$2,200.00)								
																					12	Aug 17, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Exception 3 on the current Payment Estimate.	
																						12	Aug 17, 2021	SYSTEM	(\$2,200.00)	
								13	Sep 2, 2021	SYSTEM	(\$2,200.00)															
							14	Sep 16, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate.															
										14	Sep 16, 2021	SYSTEM	(\$2,200.00)													
					15	Oct 4,	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment																	





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J4I3222	0430	MGS LONG SPAN GUARDRAIL	Material			2021			Estimate Item Adjustment (0030) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate.	
		SECTION			15	Oct 4, 2021	SYSTEM	(\$2,200.00)		
					16	Oct 19, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user frizzm overridding Payment Estimate Exception 5 on the current Payment Estimate.	
					16	Oct 19, 2021	SYSTEM	(\$2,200.00)		
					17	Nov 2, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user frizzm overridding Payment Estimate Exception 5 on the current Payment Estimate.	
					17	Nov 2, 2021	SYSTEM	(\$2,200.00)		
					18	Nov 16, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user woodyb1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	
					18	Nov 16, 2021	SYSTEM	(\$2,200.00)		
					19	Dec 2, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user frizzm overridding Payment Estimate Exception 6 on the current Payment Estimate.	
					19	Dec 2, 2021	SYSTEM	(\$2,200.00)		
				- Total				\$0.00		
	0.400		Material - To	tal				\$0.00		
	0430 - 0440	MGS END	Construction		2	Mar 3,	SYSTEM	\$0.00 (\$1,054.02)	Payment Estimate Item Adjustment generated Stockpile Transaction	
	0440	ANCHOR	Stockpile		3	2021 Mar 16,	SYSTEM	(\$1,054.02)	Payment Estimate Item Adjustment generated Stockpile Transaction	
					3	2021	OTOTEW	(ψ1,034.02)	1 ayrıldır. Estimate terin Adjustificit generated Glockpile Transaction	
						4	Apr 2, 2021	SYSTEM	(\$2,635.06)	Payment Estimate Item Adjustment generated Stockpile Transaction
					5	Apr 16, 2021	SYSTEM	(\$4,216.09)	Payment Estimate Item Adjustment generated Stockpile Transaction	
					6	May 1, 2021	SYSTEM	(\$3,688.81)	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				(\$12,648.00)		
			Construction	n Stockpile - 1	otal 1	Feb 16,	SYSTEM	(\$12,648.00) \$12,648.00	Payment Estimate Item Adjustment generated Steelenile Transaction	
			Stockpile STMI	Total	'	2021	STSTEIN		Payment Estimate Item Adjustment generated Stockpile Transaction	
			Construction	- Total	TMI - Total			\$12,648.00 \$12,648.00		
			Overrun	Overrun		Jun 17, 2021	SYSTEM	(\$1,600.00)		
					16	Oct 19, 2021	SYSTEM	(\$800.00)	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user frizzm overridding Payment Estimate Exception 38 on the current Payment Estimate.	
					16	Oct 19, 2021	SYSTEM	\$800.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',800.00000 - 800.00000, 'is applied (if non-zero).	
					17	Nov 2, 2021	SYSTEM	\$1,600.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',800.00000 - 800.00000, 'is applied (if non-zero).	
				Overrun - Total				\$0.00		
	<b>0440 - To</b> 0450		Overrun - To	tal				\$0.00		
			0 : ::		40	D. C	OVOT-::	\$0.00	Demonstration to the Adia to t	
		TRANSITION S (THRIE-BEAM BRIDGE	Construction Stockpile		19	Dec 2, 2021	SYSTEM	(\$4,134.00)	Payment Estimate Item Adjustment generated Stockpile Transaction	
			BRIDGE		- Total				(\$4,134.00)	
				n Stockpile - T				(\$4,134.00)		
			Construction		1	Feb 16,	SYSTEM	\$4,134.00	Payment Estimate Item Adjustment generated Stockpile Transaction	





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
J4I3222	0450	MGS BR APP	Stockpile STMI			2021					
		TRANSITION (THRIE-BEAM	STIVII	- Total				\$4,134.00			
		BRIDGE	Construction	Stockpile S	TMI - Total			\$4,134.00			
	0450 -	Total						\$0.00			
	0460	TRANSITION SECTION, 6.5 FT. POSTS	Material		7	May 17, 2021	SYSTEM	\$700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user frizzm overridding Payment Estimate Exception 7 on the current Payment Estimate.		
					7	May 17, 2021	SYSTEM	(\$700.00)			
					8	Jun 1, 2021	SYSTEM	\$1,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Exception 7 on the current Payment Estimate.		
					8	Jun 1, 2021	SYSTEM	(\$1,400.00)			
				- Total				\$0.00			
			Material - Tot	tal				\$0.00			
	0460 -	Total						\$0.00			
	0470	TYPE A CRASHWORTHY	Construction Stockpile		2	Mar 3, 2021	SYSTEM	(\$4,494.00)	Payment Estimate Item Adjustment generated Stockpile Transaction		
		END TERMINAL (MASH)			3	Mar 16, 2021	SYSTEM	(\$2,996.00)	Payment Estimate Item Adjustment generated Stockpile Transaction		
					4	Apr 2, 2021	SYSTEM	(\$5,992.00)	Payment Estimate Item Adjustment generated Stockpile Transaction		
					5	Apr 16, 2021	SYSTEM	(\$14,980.00)	Payment Estimate Item Adjustment generated Stockpile Transaction		
					6	May 1, 2021	SYSTEM	(\$14,980.00)	Payment Estimate Item Adjustment generated Stockpile Transaction		
					7	May 17, 2021	SYSTEM	(\$13,482.00)	Payment Estimate Item Adjustment generated Stockpile Transaction		
							8	Jun 1, 2021	SYSTEM	(\$5,992.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$62,916.00)			
			Construction	ction Stockpile - Total				(\$62,916.00)			
			Construction Stockpile STMI		1	Feb 16, 2021	SYSTEM	\$62,916.00	Payment Estimate Item Adjustment generated Stockpile Transaction		
			STIVII	- Total				\$62,916.00			
			Construction	Stockpile S	TMI - Total			\$62,916.00			
			Overrun	Overrun	9	Jun 17, 2021	SYSTEM	(\$6,900.00)			
					16	Oct 19, 2021	SYSTEM	\$6,900.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',2300.00000 - 2300.00000, 'is applied (if non-zero).		
				Overrun - T	otal			\$0.00			
			Overrun - To	tal				\$0.00			
	0470 -		Construction		17	New 2	SYSTEM	\$0.00	Downert Estimate Hom Adjustment generated Str. In 11- Township		
	0480	TYPE C CRASHWORTHY END TERMINAL	Construction Stockpile		17	Nov 2, 2021	STOLEM	(\$35,600.00)	Payment Estimate Item Adjustment generated Stockpile Transaction		
				- Total				(\$35,600.00)			
				Stockpile - 1			a) / = =	(\$35,600.00)			
			Construction Stockpile STMI		1	Feb 16, 2021	SYSTEM	\$35,600.00	Payment Estimate Item Adjustment generated Stockpile Transaction		
			- Total					\$35,600.00			
			Construction	Stockpile S	TMI - Total			\$35,600.00			
	0480 -	Total						\$0.00			
	0490	GUARDRAIL ANCHOR,	Construction Stockpile		9	Jun 17, 2021	SYSTEM	(\$2,412.50)	Payment Estimate Item Adjustment generated Stockpile Transaction		
		EMBEDDED		EMBEDDED	- Total				(\$2,412.50)		
		C	Construction	Stockpile - 1	Total			(\$2,412.50)			
			Construction		1	Feb 16,	SYSTEM	\$2,412.50	Payment Estimate Item Adjustment generated Stockpile Transaction		





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4I3222	0490	GUARDRAIL ANCHOR,	Stockpile STMI			2021			
		EMBEDDED		- Total				\$2,412.50	
			Construction	n Stockpile S	TMI - Total			\$2,412.50	
		- Total						\$0.00	
	0500	SIGNAL HEAD, TYPE 3S	Material		15	Oct 4, 2021	SYSTEM	\$1,080.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user frizzm overridding Payment Estimate Exception 16 on the current Payment Estimate.
					15	Oct 4, 2021	SYSTEM	(\$1,080.00)	
					16	Oct 19, 2021	SYSTEM	\$1,080.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user frizzm overridding Payment Estimate Exception 23 on the current Payment Estimate.
					16	Oct 19, 2021	SYSTEM	(\$1,080.00)	
					17	Nov 2, 2021	SYSTEM	\$1,080.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user frizzm overridding Payment Estimate Exception 32 on the current Payment Estimate.
					17	Nov 2, 2021	SYSTEM	(\$1,080.00)	
					18	Nov 16, 2021	SYSTEM	\$1,080.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user woodyb1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					18	Nov 16, 2021	SYSTEM	(\$1,080.00)	
					19	Dec 2, 2021	SYSTEM	\$1,080.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user frizzm overridding Payment Estimate Exception 28 on the current Payment Estimate.
					19	Dec 2, 2021	SYSTEM	(\$1,080.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0500 -	- Total						\$0.00	
	0510	SIGNAL HEAD, TYPE 3B	Material		15	Oct 4, 2021	SYSTEM	\$4,660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user frizzm overridding Payment Estimate Exception 17 on the current Payment Estimate.
					15	Oct 4, 2021	SYSTEM	(\$4,660.00)	
						2021			
					16	Oct 19, 2021	SYSTEM	\$4,660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user frizzm overridding Payment Estimate Exception 24 on the current Payment Estimate.
					16	Oct 19,	SYSTEM	\$4,660.00 (\$4,660.00)	Estimate Item Adjustment (0023) due to user frizzm overridding Payment
						Oct 19, 2021			Estimate Item Adjustment (0023) due to user frizzm overridding Payment
					16	Oct 19, 2021 Oct 19, 2021 Nov 2,	SYSTEM	(\$4,660.00)	Estimate Item Adjustment (0023) due to user frizzm overridding Payment Estimate Exception 24 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user frizzm overridding Payment
					16	Oct 19, 2021 Oct 19, 2021 Nov 2, 2021	SYSTEM SYSTEM	(\$4,660.00)	Estimate Item Adjustment (0023) due to user frizzm overridding Payment Estimate Exception 24 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user frizzm overridding Payment
					16 17 17	Oct 19, 2021 Oct 19, 2021 Nov 2, 2021 Nov 16,	SYSTEM SYSTEM	(\$4,660.00) \$4,660.00 (\$4,660.00)	Estimate Item Adjustment (0023) due to user frizzm overridding Payment Estimate Exception 24 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user frizzm overridding Payment Estimate Exception 33 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user woodyb1 overridding Payment
					16 17 17 18	Oct 19, 2021 Oct 19, 2021 Nov 2, 2021 Nov 2, 2021 Nov 16, 2021 Nov 16, 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	(\$4,660.00) \$4,660.00 (\$4,660.00) \$4,660.00	Estimate Item Adjustment (0023) due to user frizzm overridding Payment Estimate Exception 24 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user frizzm overridding Payment Estimate Exception 33 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user woodyb1 overridding Payment
					16 17 17 18	Oct 19, 2021 Oct 19, 2021 Nov 2, 2021 Nov 16, 2021 Nov 16, 2021 Dec 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$4,660.00) \$4,660.00 (\$4,660.00) \$4,660.00	Estimate Item Adjustment (0023) due to user frizzm overridding Payment Estimate Exception 24 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user frizzm overridding Payment Estimate Exception 33 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user woodyb1 overridding Payment Estimate Exception 29 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user frizzm overridding Payment
				- Total	16 17 17 18 18	Oct 19, 2021 Oct 19, 2021 Nov 2, 2021 Nov 16, 2021 Nov 16, 2021 Dec 2, 2021 Dec 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$4,660.00) \$4,660.00 (\$4,660.00) \$4,660.00 (\$4,660.00)	Estimate Item Adjustment (0023) due to user frizzm overridding Payment Estimate Exception 24 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user frizzm overridding Payment Estimate Exception 33 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user woodyb1 overridding Payment Estimate Exception 29 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user frizzm overridding Payment
			Material - To		16 17 17 18 18	Oct 19, 2021 Oct 19, 2021 Nov 2, 2021 Nov 16, 2021 Nov 16, 2021 Dec 2, 2021 Dec 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$4,660.00) \$4,660.00 (\$4,660.00) \$4,660.00 (\$4,660.00)	Estimate Item Adjustment (0023) due to user frizzm overridding Payment Estimate Exception 24 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user frizzm overridding Payment Estimate Exception 33 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user woodyb1 overridding Payment Estimate Exception 29 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user frizzm overridding Payment
	0510 -3	- Total	Material - To		16 17 17 18 18	Oct 19, 2021 Oct 19, 2021 Nov 2, 2021 Nov 16, 2021 Nov 16, 2021 Dec 2, 2021 Dec 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$4,660.00) \$4,660.00 (\$4,660.00) \$4,660.00 (\$4,660.00) \$4,660.00 (\$4,660.00)	Estimate Item Adjustment (0023) due to user frizzm overridding Payment Estimate Exception 24 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user frizzm overridding Payment Estimate Exception 33 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user woodyb1 overridding Payment Estimate Exception 29 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user frizzm overridding Payment
	<b>0510</b> - 0520	-Total POST, TYPE BL, LONGEST ARM 50 FT. OR 15.	Material - To		16 17 17 18 18	Oct 19, 2021 Oct 19, 2021 Nov 2, 2021 Nov 16, 2021 Nov 16, 2021 Dec 2, 2021 Dec 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$4,660.00) \$4,660.00 (\$4,660.00) \$4,660.00 (\$4,660.00) \$4,660.00 (\$4,660.00)	Estimate Item Adjustment (0023) due to user frizzm overridding Payment Estimate Exception 24 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user frizzm overridding Payment Estimate Exception 33 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user woodyb1 overridding Payment Estimate Exception 29 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user frizzm overridding Payment





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
413222	0520	POST, TYPE BL,	Material			2021			
		LONGEST ARM 50 FT. OR 15.			16	Oct 19, 2021	SYSTEM	\$21,220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user frizzm overridding Payment Estimate Exception 25 on the current Payment Estimate.
					16	Oct 19, 2021	SYSTEM	(\$21,220.00)	
					17	Nov 2, 2021	SYSTEM	\$21,220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user frizzm overridding Payment Estimate Exception 34 on the current Payment Estimate.
					17	Nov 2, 2021	SYSTEM	(\$21,220.00)	
					18	Nov 16, 2021	SYSTEM	\$21,220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user woodyb1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					18	Nov 16, 2021	SYSTEM	(\$21,220.00)	
					19	Dec 2, 2021	SYSTEM	\$21,220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user frizzm overridding Payment Estimate Exception 30 on the current Payment Estimate.
					19	Dec 2, 2021	SYSTEM	(\$21,220.00)	
				- Total		2021		\$0.00	
			Material - To					\$0.00	
	0520 -	Total						\$0.00	
	0530	CONDUIT, 4 IN., TRENCH WITH TRACER WIRE	Material		15	Oct 4, 2021	SYSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user frizzm overridding Payment Estimate Exception 21 on the current Payment Estimate.
					15	Oct 4, 2021	SYSTEM	(\$750.00)	
					16	Oct 19, 2021	SYSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user frizzm overridding Payment Estimate Exception 28 on the current Payment Estimate.
					16	Oct 19, 2021	SYSTEM	(\$750.00)	
					17	Nov 2, 2021	SYSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user frizzm overridding Payment Estimate Exception 37 on the current Payment Estimate.
					17	Nov 2, 2021	SYSTEM	(\$750.00)	
					18	Nov 16, 2021	SYSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user woodyb1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					18	Nov 16, 2021	SYSTEM	(\$750.00)	
					19	Dec 2, 2021	SYSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user frizzm overridding Payment Estimate Exception 33 on the current Payment Estimate.
					19	Dec 2, 2021	SYSTEM	(\$750.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0530 -	Total						\$0.00	
	0540	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRAC	Material		15	Oct 4, 2021	SYSTEM	\$256.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user frizzm overridding Payment Estimate Exception 22 on the current Payment Estimate.
	POLE AND B			15 16	15	Oct 4, 2021	SYSTEM	(\$256.50)	
					16	Oct 19, 2021	SYSTEM	\$256.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user frizzm overridding Payment Estimate Exception 29 on the current Payment Estimate.
					16	Oct 19, 2021	SYSTEM	(\$256.50)	
					17	Nov 2, 2021	SYSTEM	\$256.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user frizzm overridding Payment Estimate Exception 38 on the current Payment Estimate.





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
413222	0540	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRAC	Material		17	Nov 2, 2021	SYSTEM	(\$256.50)	
					18	Nov 16, 2021	SYSTEM	\$256.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user woodyb1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
					18	Nov 16, 2021	SYSTEM	(\$256.50)	
					19	Dec 2, 2021	SYSTEM	\$256.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user frizzm overridding Payment Estimate Exception 34 on the current Payment Estimate.
					19	Dec 2, 2021	SYSTEM	(\$256.50)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0540 -	Total						\$0.00	
	0550	CABLE, 16 AWG 7 CONDUCTOR	Material		15	Oct 4, 2021	SYSTEM	\$1,110.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user frizzm overridding Payment Estimate Exception 23 on the current Payment Estimate.
					15	Oct 4, 2021	SYSTEM	(\$1,110.00)	
					16	Oct 19, 2021	SYSTEM	\$1,110.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user frizzm overridding Payment Estimate Exception 30 on the current Payment Estimate.
					16	Oct 19, 2021	SYSTEM	(\$1,110.00)	
					17	Nov 2, 2021	SYSTEM	\$1,110.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user frizzm overridding Payment Estimate Exception 39 on the current Payment Estimate.
					17	Nov 2, 2021	SYSTEM	(\$1,110.00)	
					18	Nov 16, 2021	SYSTEM	\$1,110.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user woodyb1 overridding Payment Estimate Exception 35 on the current Payment Estimate.
					18	Nov 16, 2021	SYSTEM	(\$1,110.00)	
					19	Dec 2, 2021	SYSTEM	\$1,110.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user frizzm overridding Payment Estimate Exception 35 on the current Payment Estimate.
					19	Dec 2, 2021	SYSTEM	(\$1,110.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0550 -	Total						\$0.00	
	0560	BASE, CONCRETE	Material		15	Oct 4, 2021	SYSTEM	\$13,320.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user frizzm overridding Payment Estimate Exception 24 on the current Payment Estimate.
					15	Oct 4, 2021	SYSTEM	(\$13,320.00)	
					16	Oct 19, 2021	SYSTEM	\$13,320.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user frizzm overridding Payment Estimate Exception 31 on the current Payment Estimate.
					16	Oct 19, 2021	SYSTEM	(\$13,320.00)	
					17	Nov 2, 2021	SYSTEM	\$13,320.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user frizzm overridding Payment Estimate Exception 40 on the current Payment Estimate.
					17	Nov 2, 2021	SYSTEM	(\$13,320.00)	
					18	Nov 16, 2021	SYSTEM	\$13,320.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user woodyb1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					18	Nov 16, 2021	SYSTEM	(\$13,320.00)	
					19	Dec 2,	SYSTEM	\$13,320.00	This adjustment offsets the original system-generated Material Payment





J4l3222     0560     BASE, CONCRETE     Material     19     Dec 2, 2021     SYSTEM (\$13,320.00)       - Total     \$0.00       Material - Total     \$0.00       0560 - Total	Material Payment erridding Payment
19	erridding Payment
Material - Total \$0.00	erridding Payment
	erridding Payment
0560 - Total \$0.00	erridding Payment
	erridding Payment
5001 CMS WITH COMMUNICATION INTERFACE, 2021 SYSTEM \$6,000.00 This adjustment offsets the original system-generated NEstimate Exception 18 on the current Payment Estimate	
CONT F 10 Jul 1, SYSTEM (\$6,000.00)	
- Total \$0.00	
Material - Total \$0.00	
5001 - Total \$0.00	
5002 TACK COAT - LOW OR NON-TRACKING  TACK COAT - LOW OR NON-TRACKING  TRACKING  TACK COAT - LOW OR NON-TRACKING  Sep 2, 2021  SYSTEM \$14,726.25  SYSTEM \$14,726.25  Estimate Item Adjustment (0014) due to user frizzm ow Estimate Exception 1 on the current Payment Estimate	erridding Payment
13 Sep 2, 2021 (\$14,726.25)	
14 Sep 16, 2021 \$74,628.40 This adjustment offsets the original system-generated N Estimate Item Adjustment (0018) due to user frizzm ow Estimate Exception 1 on the current Payment Estimate	erridding Payment
14 Sep 16, SYSTEM (\$74,628.40)	
15 Oct 4, 2021 \$159,547.85 This adjustment offsets the original system-generated N Estimate Item Adjustment (0038) due to user frizzm ove Estimate Exception 1 on the current Payment Estimate	erridding Payment
15 Oct 4, SYSTEM (\$159,547.85)	
16 Oct 19, 2021 \$173,084.45 This adjustment offsets the original system-generated N Estimate Item Adjustment (0031) due to user frizzm ove Estimate Exception 2 on the current Payment Estimate	erridding Payment
16 Oct 19, 2021 (\$173,084.45)	
17 Nov 2, 2021 \$173,084.45 This adjustment offsets the original system-generated N Estimate Item Adjustment (0027) due to user frizzm ove Estimate Exception 2 on the current Payment Estimate	erridding Payment
17 Nov 2, SYSTEM (\$173,084.45)	
18 Nov 16, 2021 \$173,084.45 This adjustment offsets the original system-generated N Estimate Item Adjustment (0002) due to user woodyb1 Estimate Exception 2 on the current Payment Estimate	overridding Payment
18 Nov 16, SYSTEM (\$173,084.45)	
19 Dec 2, 2021 \$173,084.45 This adjustment offsets the original system-generated N Estimate Item Adjustment (0025) due to user frizzm over Estimate Exception 2 on the current Payment Estimate	erridding Payment
19 Dec 2, 2021 (\$173,084.45)	
- Total \$0.00	
Material - Total \$0.00	
Overrun Overrun 16 Oct 19, 2021 \$5,501.65 This adjustment offsets the original system-generated of Estimate Item Adjustment (0029) overridding Payment on the current Payment Estimate. Material Insufficiency Overrun Quantity Balance 2614.00.	Estimate Exception 37
16 Oct 19, 2021 \$4,562.25 This adjustment offsets the original system-generated (Estimate Item Adjustment (0030) overridding Payment on the current Payment Estimate. Material Insufficiency Overrun Quantity Balance 2614.00.	Estimate Exception 37
16 Oct 19, 2021 (\$10,063.90)	
17 Nov 2, 2021 (\$10,063.90) Averaged Price Adjustment from this item on all previous of '0.00000' is applied (if non-zero).	us payment estimates
Nov 2, 2021 \$10,063.90 This adjustment offsets the original system-generated (Estimate Item Adjustment (0026) overridding Payment	

Dec 13, 2021



### Line Item Adjustments by Estimate

ject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4I3222	5002	TACK COAT - LOW OR NON- TRACKING	Overrun	Overrun					on the current Payment Estimate. Material Insufficiency Quantity 44957.000; Overrun Quantity Balance 2614.00.
					18	Nov 16, 2021	SYSTEM	(\$10,063.90)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					18	Nov 16, 2021	SYSTEM	\$10,063.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 38 on the current Payment Estimate. Material Insufficiency Quantity 44957.000; Overrun Quantity Balance 2614.00.
					19	Dec 2, 2021	SYSTEM	(\$10,063.90)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					19	Dec 2, 2021	SYSTEM	\$10,063.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) overridding Payment Estimate Exception 40 on the current Payment Estimate. Material Insufficiency Quantity 44957.000; Overrun Quantity Balance 2614.00.
				Overrun - T	otal			\$0.00	
			Overrun - Total					\$0.00	
	5002 -	Total						\$0.00	
	5003	6 FT. POSTS, 3 FT 1.5	Material		18	Nov 16, 2021	SYSTEM	\$2,988.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user woodyb1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					18	Nov 16, 2021	SYSTEM	(\$2,988.12)	
					19	Dec 2, 2021	SYSTEM	\$2,988.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate.
					19	Dec 2, 2021	SYSTEM	(\$2,988.12)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	5003 -	5003 - Total						\$0.00	
	5004	MISC. GUARDRAIL ITEM	Material		18	Nov 16, 2021	SYSTEM	\$2,460.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user woodyb1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					18	Nov 16, 2021	SYSTEM	(\$2,460.50)	
					19	Dec 2, 2021	SYSTEM	\$2,460.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user frizzm overridding Payment Estimate Exception 7 on the current Payment Estimate.
					19	Dec 2, 2021	SYSTEM	(\$2,460.50)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	5004 - Total							\$0.00	
3222 -	Total							\$273,997.25	
erall -	Total							\$273,997.25	