

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 2, 2022

Progress Estimate Number	Contract ID	201016-G01	Pay Period Start July 16, 2022	Original Contract Amount	\$2,987,500.00
28	Prime Contracto	orWest Plains Bridge & Grading	, LLC Pay Period End August 1, 2022	2 Net Change Order Amount	(\$10,820.89)
20				Current Contract Amount	\$2,976,679.11

Approval Date		By User
August 4, 2022	Generated and Approved (and should be considered Draft) at the Project Office Level by	reedys
August 4, 2022	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	howelj4
August 5, 2022	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
December 1, 2021	December 1, 2022		33.59%

	Contract Informational Date	tes	Milestones
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract
Acceptance Date			
Awarded Date	November 5, 2020	November 5, 2020	
Letting Date	October 16, 2020	October 16, 2020	
Notice to Proceed Date	January 4, 2021	January 4, 2021	
Work Began Date	April 4, 2022	April 4, 2022	

Contract Total Pa	ay For Estimate No. 28			
		This Estimate	Previous	To Date
201016-G01				
	Total Posted Items Pay	\$247,466.00	\$752,487.13	\$999,953.13
	Gross Item Adjustments	\$80,605.50	\$203,355.20	\$283,960.70
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	·		\$955,842.33	\$1,283,913.83
Contract Total Pa	avable This Estimate:	\$328.071.50		

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J7I3363	0010	2022010	REMOVAL OF IMPROVEMENTS	LS	\$70,000.000	0.96	\$67,200.00
	0540	2061000	CLASS 1 EXCAVATION	CUYD	\$42.000	60	\$2,520.00
	0640	7027000	PILE POINT REINFORCEMENT	EA	\$100.000	8	\$800.00
	0650	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	CUYD	\$605.000	40	\$24,200.00
	0720	7011104	DRILLED SHAFTS (3 FT. 0 IN. DIA.)	LF	\$190.000	201	\$38,190.00
	0730	7011203	ROCK SOCKETS (2 FT 6IN. DIA.)	LF	\$325.000	112	\$36,400.00
	0740	7011300	VIDEO CAMERA INSPECTION	EA	\$50.000	4	\$200.00
	0760	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	LF	\$47.000	473	\$22,231.00
	0780	7011104	DRILLED SHAFTS (3 FT. 0 IN. DIA.)	LF	\$190.000	115	\$21,850.00
	0790	7011203	ROCK SOCKETS (2 FT 6IN. DIA.)	LF	\$340.000	63	\$21,420.00
	0820	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	LF	\$47.000	265	\$12,455.00
Project J7I336	3 - Total						\$247,466.00
Overall - Total							\$247,466,00

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

		ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J7I3363	0430	SEEDING - COOL SEASON GRASSES	MaterialCredit			0.45	\$2,850.00	\$1,282.50

Revision 4/1/2020 Page 1 of 15



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 2, 2022

Progress Estimate Number
28

Contract ID 201016-G01 Pay Period Start July 16, 2022 Original Contract Amount \$2,987,500.00
Prime Contractor West Plains Bridge & Grading, LLC Pay Period End August 1, 2022 Net Change Order Amount (\$10,820.89)
Current Contract Amount \$2,976,679.11

ject nber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
363	0430	SEEDING - COOL SEASON GRASSES	Material			-0.45	\$2,850.00	(\$1,282.50
	0580	DRILLED SHAFTS (5 FT. 0 IN. DIA.)	MaterialCredit			21.7	\$1,530.00	\$33,201.00
	0580	DRILLED SHAFTS (5 FT. 0 IN. DIA.)	Material			-21.7	\$1,530.00	(\$33,201.00
	0580	DRILLED SHAFTS (5 FT. 0 IN. DIA.)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user rosenl2 overridding Payment Estimate Exception 8 on the current Payment Estimate.	21.7	\$1,530.00	\$33,201.00
	0590	ROCK SOCKETS (4 FT 6 IN. DIA.)	MaterialCredit			66.3	\$715.00	\$47,404.50
	0590	ROCK SOCKETS (4 FT 6 IN. DIA.)	Material			-66.3	\$715.00	(\$47,404.50
	0590	ROCK SOCKETS (4 FT 6 IN. DIA.)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user rosenl2 overridding Payment Estimate Exception 16 on the current Payment Estimate.	66.3	\$715.00	\$47,404.50
	0650	CLASS B CONCRETE (SUBSTRUCTURE)	Material			-40	\$605.00	(\$24,200.00
	0650	CLASS B CONCRETE (SUBSTRUCTURE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user rosenl2 overridding Payment Estimate Exception 19 on the current Payment Estimate.	40	\$605.00	\$24,200.00
	0720	DRILLED SHAFTS (3 FT. 0 IN. DIA.)	Material			-201	\$190.00	(\$38,190.00
	0720	DRILLED SHAFTS (3 FT. 0 IN. DIA.)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user rosenl2 overridding Payment Estimate Exception 1 on the current Payment Estimate.	201	\$190.00	\$38,190.00
	0730	ROCK SOCKETS (2 FT 6IN. DIA.)	Overrun			-32	\$325.00	(\$10,400.00
	0730	ROCK SOCKETS (2 FT 6IN. DIA.)	Material			-112	\$325.00	(\$36,400.00
	0730	ROCK SOCKETS (2 FT 6IN. DIA.)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user rosenl2 overridding Payment Estimate Exception 11 on the current Payment Estimate.	112	\$325.00	\$36,400.00
	0730	ROCK SOCKETS (2 FT 6IN. DIA.)	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0001) due to user rosenl2 overridding Payment Estimate Exception 23 on the current Payment Estimate.	32	\$325.00	\$10,400.00
	0760	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	Overrun			-32	\$47.00	(\$1,504.00
	0760	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0003) due to user rosenl2 overridding Payment Estimate Exception 24 on the current Payment Estimate.	32	\$47.00	\$1,504.00
	0780	DRILLED SHAFTS (3 FT. 0 IN. DIA.)	Material			-115	\$190.00	(\$21,850.00
	0780	DRILLED SHAFTS (3 FT. 0 IN. DIA.)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item	115	\$190.00	\$21,850.00

Revision 4/1/2020 Page 2 of 15



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 2, 2022

Pro	ogress Estimate Number	Contract ID	201016-G01	Pay Period Start July 16, 2022	Original Contract Amount	\$2,987,500.00
	28	Prime Contract	or West Plains Bridge & Grading	, LLC Pay Period End August 1, 2022	Net Change Order Amount	:(\$10,820.89)
	20				Current Contract Amount	\$2,976,679.11

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J7I3363					Adjustment (0007) due to user rosenl2 overridding Payment Estimate Exception 4 on the current Payment Estimate.			
	0790	ROCK SOCKETS (2 FT 6IN. DIA.)	Overrun			-3	\$340.00	(\$1,020.00)
	0790	ROCK SOCKETS (2 FT 6IN. DIA.)	Material			-63	\$340.00	(\$21,420.00)
	0790	ROCK SOCKETS (2 FT 6IN. DIA.)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user rosenl2 overridding Payment Estimate Exception 13 on the current Payment Estimate.	63	\$340.00	\$21,420.00
	0790	ROCK SOCKETS (2 FT 6IN. DIA.)	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0004) due to user rosenl2 overridding Payment Estimate Exception 25 on the current Payment Estimate.	3	\$340.00	\$1,020.00
Total								\$80,605.50

Revision 4/1/2020 Page 3 of 15



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Information	on
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J7I3363	I 49-2(407)	Bridge replacement	I-49	VERNON	on southbound bridge over	er Missouri and North Arka	ansas Railroad
Totals by .	Job Numb	ers					
J7I3363		ed Item Pay s Item Adjustm		Item Pay	This Estimate \$247,466.00 \$80,605.50 \$328,071.50	Previous \$752,487.13 \$203,355.20 \$955,842.33	To Date \$999,953.13 \$283,960.70 \$1,283,913.83
	Liqui	ntive centive dated Damages r Contract Adju			\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00

Revision 4/1/2020 Page 4 of 15



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

cceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
stimate Exception Type: Insufficient Materials: Project J7I3363, Item 7011104, Project Item Line lumber 0720, Material Set 701110496, Material 1005FACCNSCA - Natural Sand for Conc Class A, cceptance Action Generic 1005FACCNSCA is insufficient.	QA Test results are acceptable; QC and QC/QA is expected in the near future. At this time in an effort to work with the contractor MoDOT is temporarily accepting this material based on acceptable QA results.	rosenl2	Overridden
stimate Exception Type: Insufficient Materials: Project J713363, Item 7011104, Project Item Line lumber 0720, Material Set 701110496, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, cceptance Action Generic 100510CPCMLD is insufficient.	QA Test results are acceptable; QC and QC/QA is expected in the near future. At this time in an effort to work with the contractor MoDOT is temporarily accepting this material based on acceptable QA results.	rosenl2	Overridden
stimate Exception Type: Insufficient Materials: Project J7l3363, Item 7011104, Project Item Line lumber 0720, Material Set 701110496, Material 0701PLCSLT - Drilled Shaft CSL steel pipe, cceptance Action Generic 0701PLCSLT is insufficient.	CSL testing was not set up for these shafts. Currently it is MoDOT Acting RE decision to omit this requirement but the final decision has been move to the DCME. MoDOT will override this until final decision is made.	rosenl2	Overridden
stimate Exception Type: Insufficient Materials: Project J7l3363, Item 7011104, Project Item Line lumber 0780, Material Set 701110496, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance ction Generic 0501CCB2.A is insufficient.	QA Test results are acceptable; QC and QC/QA is expected in the near future. At this time in an effort to work with the contractor MoDOT is temporarily accepting this material based on acceptable QA results.	rosenl2	Overridden
stimate Exception Type: Insufficient Materials: Project J7l3363, Item 7011104, Project Item Line lumber 0780, Material Set 701110496, Material 0701PLCSLT - Drilled Shaft CSL steel pipe, cceptance Action Generic 0701PLCSLT is insufficient.	CSL testing was not set up for these shafts. Currently it is MoDOT Acting RE decision to omit this requirement but the final decision has been move to the DCME. MoDOT will override this until final decision is made.	rosenl2	Overridden
stimate Exception Type: Insufficient Materials: Project J7l3363, Item 7011104, Project Item Line lumber 0780, Material Set 701110496, Material 1005FACCNSCA - Natural Sand for Conc Class A, cceptance Action Generic 1005FACCNSCA is insufficient.	QA Test results are acceptable; QC and QC/QA is expected in the near future. At this time in an effort to work with the contractor MoDOT is temporarily accepting this material based on acceptable QA results.	rosenl2	Overridden
stimate Exception Type: Insufficient Materials: Project J7l3363, Item 7011104, Project Item Line lumber 0780, Material Set 701110496, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, cceptance Action Generic 100510CPCMLD is insufficient.	QA Test results are acceptable; QC and QC/QA is expected in the near future. At this time in an effort to work with the contractor MoDOT is temporarily accepting this material based on acceptable QA results.	rosenl2	Overridden
stimate Exception Type: Insufficient Materials: Project J7l3363, Item 7011108, Project Item Line umber 0580, Material Set 701110896, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance ction Generic 0501CCB2.A is insufficient.	QA Test results are acceptable; QC and QC/QA is expected in the near future. At this time in an effort to work with the contractor MoDOT is temporarily accepting this material based on acceptable QA results.	rosenl2	Overridden
stimate Exception Type: Insufficient Materials: Project J7l3363, Item 7011108, Project Item Line umber 0580, Material Set 701110896, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, cceptance Action Generic 100510CPCMLD is insufficient.	QA Test results are acceptable; QC and QC/QA is expected in the near future. At this time in an effort to work with the contractor MoDOT is temporarily accepting this material based on acceptable QA results.	rosenl2	Overridden
stimate Exception Type: Insufficient Materials: Project J713363, Item 7011108, Project Item Line lumber 0580, Material Set 701110896, Material 1005FACCNSCA - Natural Sand for Conc Class A, cceptance Action Generic 1005FACCNSCA is insufficient.	QA Test results are acceptable; QC and QC/QA is expected in the near future. At this time in an effort to work with the contractor MoDOT is temporarily accepting this material based on acceptable QA results.	rosenl2	Overridden
stimate Exception Type: Insufficient Materials: Project J7l3363, Item 7011203, Project Item Line umber 0730, Material Set 701120396, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, cceptance Action Generic 100510CPCMLD is insufficient.	QA Test results are acceptable; QC and QC/QA is expected in the near future. At this time in an effort to work with the contractor MoDOT is temporarily accepting this material based on acceptable QA results.	rosenl2	Overridden
stimate Exception Type: Insufficient Materials: Project J7l3363, Item 7011203, Project Item Line umber 0730, Material Set 701120396, Material 1005FACCNSCA - Natural Sand for Conc Class A, cceptance Action Generic 1005FACCNSCA is insufficient.	QA Test results are acceptable; QC and QC/QA is expected in the near future. At this time in an effort to work with the contractor MoDOT is temporarily accepting this material based on acceptable QA results.	rosenl2	Overridden
stimate Exception Type: Insufficient Materials: Project J7l3363, Item 7011203, Project Item Line umber 0790, Material Set 701120396, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, cceptance Action Generic 100510CPCMLD is insufficient.	QA Test results are acceptable; QC and QC/QA is expected in the near future. At this time in an effort to work with the contractor MoDOT is temporarily accepting this material based on acceptable QA results.	rosenl2	Overridden
stimate Exception Type: Insufficient Materials: Project J713363, Item 7011203, Project Item Line umber 0790, Material Set 701120396, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance ction Generic 0501CCB2.A is insufficient.	QA Test results are acceptable; QC and QC/QA is expected in the near future. At this time in an effort to work with the contractor MoDOT is temporarily accepting this material based on acceptable QA results.	rosenl2	Overridden
stimate Exception Type: Insufficient Materials: Project J7l3363, Item 7011203, Project Item Line umber 0790, Material Set 701120396, Material 1005FACCNSCA - Natural Sand for Conc Class A, cceptance Action Generic 1005FACCNSCA is insufficient.	QA Test results are acceptable; QC and QC/QA is expected in the near future. At this time in an effort to work with the contractor MoDOT is temporarily accepting this material based on acceptable QA results.	rosenl2	Overridden
stimate Exception Type: Insufficient Materials: Project J7I3363, Item 7011207, Project Item Line umber 0590, Material Set 701120796, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance ction Generic 0501CCB2.A is insufficient.	QA Test results are acceptable; QC and QC/QA is expected in the near future. At this time in an effort to work with the contractor MoDOT is temporarily accepting this material based on acceptable QA results.	rosenl2	Overridden
stimate Exception Type: Insufficient Materials: Project J713363, Item 7011207, Project Item Line umber 0590, Material Set 701120796, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, cceptance Action Generic 100510CPCMLD is insufficient.	QA Test results are acceptable; QC and QC/QA is expected in the near future. At this time in an effort to work with the contractor MoDOT is temporarily accepting this material based on acceptable QA results.	rosenl2	Overridden
stimate Exception Type: Insufficient Materials: Project J7l3363, Item 7011207, Project Item Line umber 0590, Material Set 701120796, Material 1005FACCNSCA - Natural Sand for Conc Class A, cceptance Action Generic 1005FACCNSCA is insufficient.	QA Test results are acceptable; QC and QC/QA is expected in the near future. At this time in an effort to work with the contractor MoDOT is temporarily accepting this material based on acceptable QA results.	rosenl2	Overridden
stimate Exception Type: Insufficient Materials: Project J7I3363, Item 7032003, Project Item Line lumber 0650, Material Set 703200396, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO,	QA Test results are acceptable; QC and QC/QA is expected in the near future. At this time in an effort to work with the contractor MoDOT is temporarily accepting this material	rosenl2	Overridden

Revision 4/1/2020 Page 5 of 15



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
	based on acceptable QA results.		
Estimate Exception Type: Insufficient Materials: Project J7l3363, Item 7032003, Project Item Line Number 0650, Material Set 703200396, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	QA Test results are acceptable; QC and QC/QA is expected in the near future. At this time in an effort to work with the contractor MoDOT is temporarily accepting this material based on acceptable QA results.	rosenl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J7l3363, Item 7032003, Project Item Line Number 0650, Material Set 703200396, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	QA Test results are acceptable; QC and QC/QA is expected in the near future. At this time in an effort to work with the contractor MoDOT is temporarily accepting this material based on acceptable QA results.	rosenl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J7l3363, Item 8051000A, Project Item Line Number 0430, Material Set 8051000A96, Material 0802MLST - Mulch Straw (Vegetative Mulch), Acceptance Action Generic 0802MLST is insufficient.	Waiting for contractor's material certifications for Straw.	rosenl2	Acknowledged
Estimate Exception Type: Item Overrun: Contract 201016-G01, Contract Project J7I3363, Project Item Line Number 0730, Contract Line Item Number 0730, Item 7011203, Minor Item.	QA Test results are acceptable; QC and QC/QA is expected in the near future. At this time in an effort to work with the contractor MoDOT is temporarily accepting this material based on acceptable QA results.	howelj4	Overridden
Estimate Exception Type: Item Overrun: Contract 201016-G01, Contract Project J7l3363, Project Item Line Number 0760, Contract Line Item Number 0760, Item 7021212, Minor Item.	QA Test results are acceptable; QC and QC/QA is expected in the near future. At this time in an effort to work with the contractor MoDOT is temporarily accepting this material based on acceptable QA results.	howelj4	Overridden
Estimate Exception Type: Item Overrun: Contract 201016-G01, Contract Project J7I3363, Project Item Line Number 0790, Contract Line Item Number 0790, Item 7011203, Minor Item.	QA Test results are acceptable; QC and QC/QA is expected in the near future. At this time in an effort to work with the contractor MoDOT is temporarily accepting this material based on acceptable QA results.	howelj4	Overridden
Estimate Exception Type: Item Overrun: Contract 201016-G01, Contract Project J7I3363, Project Item Line Number 0590, Contract Line Item Number 0590, Item 7011207, Minor Item.	QA Test results are acceptable; QC and QC/QA is expected in the near future. At this time in an effort to work with the contractor MoDOT is temporarily accepting this material based on acceptable QA results.	howelj4	Overridden

Revision 4/1/2020 Page 6 of 15



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note: Posted Q	uantities	and vail	les are	pased on F	Report Generated date and can differ from the posted am	ount at the	e time the i	Estimate wa	s Gener	rated.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
201016-G01	J7I3363	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$70,000.00	\$70,000.00
		0001	0020	2031000	CLASS A EXCAVATION	5,182.00	0.00	5,182.00	CUYD	2,800.00	\$10.00	\$28,000.00
		0001	0030	2036000	COMPACTING EMBANKMENT	2,875.00	0.00	2,875.00	CUYD	0.00	\$2.50	\$0.00
		0001	0040	2072000	LINEAR GRADING CLASS 2	36.40	0.00	36.40	STA	18.20	\$720.00	\$13,104.00
		0001	0050	2153000	SHAPING SLOPES, CLASS III	2.00	0.00	2.00	100F	2.00	\$700.00	\$1,400.00
		0001	0053	3030600	FURNISHING ROCK BASE MATERIAL	3,842.00	-980.00	2,862.00	SQYD	2,862.00	\$8.75	\$25,042.50
		0001	0057	3030610A	PLACING ROCK BASE	3,842.00	-980.00	2,862.00	SQYD	2,862.00	\$4.85	\$13,880.70
		0001	0060	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	5,799.00	0.00	5,799.00	SQYD	0.00	\$7.00	\$0.00
		0001	0070	4010150	TYPE A2 SHOULDER	1,647.00	0.00	1,647.00	SQYD	0.00	\$40.10	\$0.00
		0001	0080	4019905	MISC.OPTIONAL PAVEMENT - I-49	3,840.00	0.00	3,840.00	SQYD	0.00	\$51.40	\$0.00
		0001	0090	4019905	MISC.OPTIONAL PAVEMENT - TEMPORARY CROSSOVERS	3,326.00	0.00	3,326.00	SQYD	3,326.00	\$37.10	\$123,394.60
		0001	0100	5041000	CONCRETE APPROACH PAVEMENT	312.00	0.00	312.00	SQYD	0.00	\$130.00	\$0.00
		0001	0105	6071011A	CHAIN-LINK FENCE (48 IN.)	226.00	0.00	226.00	LF	0.00	\$49.00	\$0.00
		0001	0110	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	148.00	0.00	148.00	LF	0.00	\$11.78	\$0.00
		0001	0120	6094010	DRAIN BASIN	4.00	0.00	4.00	EA	0.00	\$5,325.00	\$0.00
		0001	0130	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	16.00	0.00	16.00	CUYD	0.00	\$32.50	\$0.00
		0001	0140	6096041	PLACING TYPE 1 ROCK DITCH LINER	16.00	0.00	16.00	CUYD	0.00	\$120.00	\$0.00
		0001	0150	6097000	ROCK LINING	8.00	0.00	8.00	CUYD	0.00	\$82.00	\$0.00
		0001	0160	6113020	FURNISHING TYPE 2 ROCK BLANKET	436.00	0.00	436.00	CUYD	0.00	\$45.00	\$0.00
		0001	0170	6113040	PLACING TYPE 2 ROCK BLANKET	436.00	0.00	436.00	CUYD	0.00	\$17.50	\$0.00
		0001	0180	6122019	IMPACT ATTENUATOR 70 MPH (SAND BARREL ARRAY)	2.00	0.00	2.00	EA	2.00	\$2,800.00	\$5,600.00
		0001	0190	6122020	REPLACEMENT SAND BARREL	4.00	0.00	4.00	EA	0.00	\$200.00	\$0.00
		0001	0200	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$400.00	\$800.00
		0001	0210	6161005	CONSTRUCTION SIGNS	1,211.00	132.00	1,343.00	SQFT	1,343.00	\$7.25	\$9,736.75
		0001	0220	6161008	ADVANCED WARNING RAIL SYSTEM	12.00	0.00	12.00	EA	12.00	\$100.00	\$1,200.00
		0001	0230	6161009	FLAG ASSEMBLY	4.00	0.00	4.00	EA	4.00	\$20.00	\$80.00
		0001	0240	6161025	CHANNELIZER (TRIM LINE)	210.00	0.00	210.00	EA	210.00	\$17.00	\$3,570.00
		0001	0250	6161031	TYPE III MOVEABLE BARRICADE WITH LIGHTS	8.00	0.00	8.00	EA	8.00	\$180.00	\$1,440.00
		0001	0260	6161034	DIRECTIONAL INDICATOR BARRICADE WITH LIGHT	28.00	0.00	28.00	EA	28.00	\$80.00	\$2,240.00
		0001	0270	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	2.00	\$1,250.00	\$2,500.00
		0001	0280	6161055	SEQUENTIAL FLASHING WARNING LIGHT	28.00	0.00	28.00	EA	28.00	\$80.00	\$2,240.00
		0001	0290	6161070	TUBULAR MARKER	228.00	50.00	278.00	EA	278.00	\$60.00	\$16,680.00
		0001	0300	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$4,000.00	\$8,000.00
		0001	0310	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	8.00	0.00	8.00	EA	8.00	\$600.00	\$4,800.00
		0001	0320	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	460.00	0.00	460.00	LF	460.00	\$29.50	\$13,570.00
		0001	0330	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$145,446.66	\$0.00
		0001	0331	6181000	MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$131,215.66	\$131,215.66
		0001	0340	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	1.00	0.00	1.00	EA	0.00	\$600.00	\$0.00
		0001	0350	6191000	PAVEMENT EDGE TREATMENT	1,480.00	0.00	1,480.00	LF	1,480.00	\$2.25	\$3,330.00
		0001	0360	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	5,644.00	0.00	5,644.00	LF	0.00	\$0.18	\$0.00
		0001	0370	6205903A		12,417.00	0.00	12,417.00	LF	0.00	\$0.19	\$0.00
		0001	0380	6207001	PAVEMENT MARKING REMOVAL	32,285.00	0.00	32,285.00	LF	14,453.00	\$0.40	\$5,781.20
		0001	0390	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	40,370.00	0.00	40,370.00	LF	40,370.00	\$0.12	\$4,844.40
		0001	0400	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	944.00	0.00	944.00	SQYD	0.00	\$3.50	\$0.00
		0001	0410	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	39.30	0.00	39.30	STA	0.00	\$345.00	\$0.00

Page 7 of 15 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Report Generated date and can differ from the posted an Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved	Unit Price	Total Value POSTED To Date (See report generated date)
201016-G01	J7I3363	0001	0420	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	Qty 0.60	\$40,000.00	\$24,000.00
		0001	0430	8051000A	SEEDING - COOL SEASON GRASSES	4.10	0.00	4.10	ACRE	0.45	\$2,850.00	\$1,282.50
		0001	0440	8061005	ROCK DITCH CHECK	90.00	0.00	90.00	LF	90.00	\$15.00	\$1,350.00
		0001	0450	8061016	SEDIMENT REMOVAL	37.00	0.00	37.00	CUYD	0.00	\$8.00	\$0.00
		0001	0460	8061019	SILT FENCE	2,944.00	0.00	2,944.00	LF	2,944.00	\$2.50	\$7,360.00
		0010	0470	6061060	MGS GUARDRAIL	2,100.00	0.00	2,100.00	LF	25.00	\$19.00	\$475.00
		0010	0480	6061070	MGS VERTICAL CONCRETE BARRIER TRANSITION	5.00	0.00	5.00	EA	2.00	\$2,190.00	\$4,380.00
		0010	0490	6061080	MGS END ANCHOR	1.00	0.00	1.00	EA	0.00	\$975.00	\$0.00
		0010	0500	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	4.00	0.00	4.00	EA	2.00	\$2,425.00	\$4,850.00
		0020	0510	9019400	TEMPORARY LIGHTING	1.00	-1.00	0.00	LS	0.00	\$37,500.00	\$0.00
		0030	0520	9025400	CONDUIT, 4 IN., TRENCH WITH TRACER WIRE	75.00	0.00	75.00	LF	0.00	\$20.00	\$0.00
		0030	0530	9027400	CONDUIT, 4 IN., PUSHED WITH TRACER WIRE	200.00	0.00	200.00	LF	0.00	\$30.00	\$0.00
		0070	0540	2061000	CLASS 1 EXCAVATION	310.00	0.00	310.00	CUYD	310.00	\$42.00	\$13,020.00
		0070	0550	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$62,000.00	\$62,000.00
		0070	0560	5031010A	BRIDGE APPROACH SLAB (MAJOR)	180.00	0.00	180.00	SQYD	0.00	\$315.00	\$0.00
		0070	0570	6071060	PEDESTRIAN FENCE (STRUCTURES)	300.00	0.00	300.00	LF	0.00	\$130.00	\$0.00
		0070	0575	6181010	RAILROAD ENGINEERING	1.00	0.00	1.00	LS			\$37,500.00
		0070	0580	7011108	DRILLED SHAFTS (5 FT. 0 IN. DIA.)	32.00	0.00	32.00	LF	21.70	\$1,530.00	\$33,201.00
		0070	0590	7011207	ROCK SOCKETS (4 FT 6 IN. DIA.)	48.00	0.00	48.00	LF	66.30	\$715.00	\$47,404.50
		0070	0600	7011300	VIDEO CAMERA INSPECTION	4.00	0.00	4.00	EA	4.00	\$250.00	\$1,000.00
		0070	0610	7011400	FOUNDATION INSPECTION HOLES	88.00	0.00	88.00	LF	88.00	\$91.90	\$8,087.20
		0070	0620	7011600	SONIC LOGGING TESTING	4.00	0.00	4.00	EA	4.00	\$1,500.00	\$6,000.00
		0070	0630	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	608.00	0.00	608.00	LF	285.80	\$70.00	\$20,006.00
		0070	0640	70272000	PILE POINT REINFORCEMENT	16.00	0.00	16.00	EA	8.00	\$100.00	\$800.00
			0650	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	382.30	0.00	382.30	CUYD	40.00	\$605.00	\$24,200.00
		0070							LF			
		0070	0660	7034219A 7034221	TYPE D BARRIER SLAB ON CONCRETE NU-GIRDER	575.00	0.00	1,242.00	SQYD	0.00	\$120.00 \$320.00	\$0.00
		0070				1,242.00						
		0070	0680	7056022	NU 43, PRESTRESSED CONCRETE NU-GIRDER	1,283.00	0.00	1,283.00	LF	0.00	\$270.00	\$0.00
		0070	0690	7061060	REINFORCING STEEL (BRIDGES) VERTICAL DRAIN AT END BENTS	47,400.00	0.00	47,400.00	LB	0.00	\$1.40	\$0.00
		0070	0700	7151001		2.00	0.00	2.00	EA	0.00	\$1,600.00	\$0.00
		0070	0710	7161002	LAMINATED NEOPRENE BEARING PAD	30.00	0.00	30.00	EA	0.00	\$134.78	\$0.00
		0071	0720	7011104	DRILLED SHAFTS (3 FT. 0 IN. DIA.)	201.00	0.00	201.00	LF	201.00	\$190.00	\$38,190.00
		0071	0730	7011203	ROCK SOCKETS (2 FT 6IN. DIA.)	80.00	0.00	80.00	LF	112.00	\$325.00	\$36,400.00
		0071	0740	7011300	VIDEO CAMERA INSPECTION	4.00	0.00	4.00	EA	4.00	\$50.00	\$200.00
		0071	0750	7011400	FOUNDATION INSPECTION HOLES	60.00	0.00	60.00	LF	60.00	\$63.00	\$3,780.00
		0071	0760	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	441.00	0.00	441.00	LF	473.00	\$47.00	\$22,231.00
		0071	0770	7039904	MISC.PRECAST CONCRETE WALL PANELS	1,335.00	0.00	1,335.00	SQFT	0.00	\$36.00	\$0.00
		0072	0780	7011104	DRILLED SHAFTS (3 FT. 0 IN. DIA.)	153.00	0.00	153.00	LF	115.00	\$190.00	\$21,850.00
		0072	0790	7011203	ROCK SOCKETS (2 FT 6IN. DIA.)	60.00	0.00	60.00	LF	63.00	\$340.00	\$21,420.00
		0072	0800	7011300	VIDEO CAMERA INSPECTION	4.00	0.00	4.00	EA	0.00	\$50.00	\$0.00
		0072	0810	7011400	FOUNDATION INSPECTION HOLES	60.00	0.00	60.00	LF	60.00	\$63.00	\$3,780.00
		0072	0820	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	329.00	0.00	329.00	LF	265.00	\$47.00	\$12,455.00
		0072	0830	7039904	MISC.PRECAST CONCRETE WALL PANELS	909.00	0.00	909.00	SQFT	0.00	\$39.00	\$0.00
		0001	5001	6181000	MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$14,231.00	\$14,231.00
		0001	5002	1094000	FORCE ACCOUNT	0.00	36,050.11	36,050.11	EA	36,050.11	\$1.00	\$36,050.11

Page 8 of 15 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
201016-G01 Ove	erall - Tota	I Value Pos	ted to Da	te as of Rep	ort Generated Date							\$999,953.12

Revision 4/1/2020 Page 9 of 15

20



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J7I3363

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0010	2022010	REMOVAL OF IMPROVEMENTS	8/1/22	8/2/22	0.96	LS		1055+00	0	961+61	0	The reason this line is being paid out is to cover anticipated changes in material cost associated with the delayed Construction & Maintenance Agreement
0540	2061000	CLASS 1 EXCAVATION	7/29/22	7/29/22	60.00	CUYD		952+00	0	1064+08	0	
0640	7027000	PILE POINT REINFORCEMENT	8/1/22	8/2/22	8.00	EA	South abutment	1055+00	0	961+61	0	
0650	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	8/1/22	8/2/22	40.00	CUYD		1055+00	0	961+61	0	
0720	7011104	DRILLED SHAFTS (3 FT. 0 IN. DIA.)	7/26/22	8/1/22	201.00	LF		952+00	0	1002+00	0	
0730	7011203	ROCK SOCKETS (2 FT 6IN. DIA.)	7/26/22	8/1/22	112.00	LF		1055+00	0	1064+08	0	
0740	7011300	VIDEO CAMERA INSPECTION	7/26/22	8/1/22	4.00	EA		952+00	0	1064+08	0	
0760	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN	7/26/22	8/1/22	473.00	LF		952+00	0	1002+00	0	
0780	7011104	DRILLED SHAFTS (3 FT. 0 IN. DIA.)	7/26/22	8/1/22	115.00	LF		952+00	0	1144+60	0	
0790	7011203	ROCK SOCKETS (2 FT 6IN. DIA.)	7/26/22	8/1/22	63.00	LF		952+00	0	1064+08	0	
0820	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN	7/26/22	8/1/22	265.00	LF		952+00	0	1144+60	0	

0790	7011203	ROCK SOCKETS	(2 FT 6IN. DIA.)	7/26/22	2 8/1/22	63.00	LF					952+00	0	1064+08 0			
0820	7021212	GALVANIZED STI	RUCTURAL STEEL PILES (12 IN	7/26/22	2 8/1/22	265.00	LF					952+00	0	1144+60 0			
			are details for Construction S					C4-4:	1 143-	1	Niverbas of House	CE Eh Ci		P	i-1 Ci	CE Eh Ci-l Ci	T-4-1 05 4- D4
J7I3363			Total Quantity Posted For DWR Date 1219		sign ii ecial Sign l	nformation Details		Station 1134+60	Log Mile	i49 NB	Number of Items 1.00	SF Each Sign			ial Sign) POINT OF PRESENCE	SF Each Special Sign	1 otal SF to Post
0710000	0210	may o, zozz	12.10		ecial Sign I			882+72		149 SB	1.00				POINT OF PRESENCE		32
						12.00 SPEED	LIMIT	1000+00		i49 NB	1.00	12					12
				R2-1	36x48 1	12.00 SPEED	LIMIT	1010+00		i49 NB	1.00	12					12
				R2-1	36x48 1	12.00 SPEED	LIMIT	1020+00		i49 NB	1.00	12					12
				XX R2-1	36x48 1	12.00 SPEED	LIMIT	1030+00		i49 NB	1.00	12					12
				XX R2-1	36x48 1	12.00 SPEED	LIMIT	1040+00		i49 NB	1.00	12					12
				XX R2-1	36x48 1	12.00 SPEED	LIMIT	1050+00		i49 NB	1.00	12					12
				XX R2-1		12.00 SPEED		971+62		i49 NB	1.00	12					12
				XX R2-1		12.00 SPEED		991+62		i49 NB	1.00	12					12
				XX				331102		HOND	1.00						12
				TRAFFI	IC (SYMBO			1000+00		i49 NB	1.00	16					16
				WO6-3 TRAFFI	48x48 IC (SYMBO	16.00 TWO DL)	WAY	1010+00		i49 NB	1.00	16					16
				WO6-3 TRAFFI	48x48 IC (SYMBO	16.00 TWO '	WAY	1020+00		i49 NB	1.00	16					16
				WO6-3 TRAFFI	48x48 IC (SYMBO	16.00 TWO '	WAY	1030+00		i49 NB	1.00	16					16
				WO6-3 TRAFFI	48x48 IC (SYMBO	16.00 TWO '	WAY	1040+00		i49 NB	1.00	16					16
				WO4-1a (ARRO)	aL 48x48 W SYMBO	3 16.00 MER	GE	1088+20		i49 NB	1.00	16					16
				WO20-6 RIGHT/	6a 48x48 CENTER/L	16.00 LEFT LANE C	LOSED	1088+20		i49 NB	1.00	16					16
				WO4-1a (ARRO)	aL 48x48 W SYMBO	3 16.00 MER	GE	929+12		i49 SB	1.00	16					16
					6a 48x48 CENTER/L	16.00 LEFT LANE C	LOSED	929+12		i49 SB	1.00	16					16
					48x48 IC (SYMBO	16.00 TWO	WAY	971+62		i49 NB	1.00	16					16
				WO6-3 TRAFFI	48x48 IC (SYMBO	16.00 TWO	WAY	991+62		i49 NB	1.00	16					16
				CONST	-7 72x36 ZONE	18.00 RAT	E OUR	1049+60		i49 NB	1.00	18					18
				CONST	-7 72x36 ZONE	18.00 RAT	E OUR	867+72		i49 SB	1.00	18					18
				GO20-5 (PLAQL		4 6.00 WOF	RK ZONE	1000+00		i49 NB	1.00	6					6
				GO20-5 (PLAQL		4 6.00 WOF	K ZONE	1010+00		i49 NB	1.00	6					6
				GO20-5 (PLAQL	iaP 36x24 JE)	4 6.00 WOF	K ZONE	1020+00		i49 NB	1.00	6					6
				GO20-5 (PLAQL	iaP 36x24 JE)	4 6.00 WOF	RK ZONE	1030+00		i49 NB	1.00	6					6
					aP 36x24	4 6.00 WOF	RK ZONE	1040+00		i49 NB	1.00	6					6
					aP 36x24	4 6.00 WOF	RK ZONE	1050+00		i49 NB	1.00	6					6
					iaP 36x24	4 6.00 WOF	RK ZONE	971+62		i49 NB	1.00	6					6
					iaP 36x24	4 6.00 WOF	RK ZONE	991+62		i49 NB	1.00	6					6
				WO7-3a		5.00 NEXT	xx	966+62		i49 NB	2.00	5					10
					iaP 36x24	4 6.00 WOF	RK ZONE	1059+60		i49 NB	2.00	6					12
					iaP 36x24	4 6.00 WOF	K ZONE	1080+25		i49 NB	2.00	6					12
					aP 36x24	4 6.00 WOF	RK ZONE	936+77		i49 SB	2.00	6					12
					iaP 36x24	4 6.00 WOF	RK ZONE	966+62		i49 NB	2.00	6					12
				WO13-1		6.25 ADVIS	SORY	1050+00		i49 NB	2.00	6.25					12.5
					48x24	8.00 END F	ROAD	1090+60			2.00	8					16
					48x24	8.00 END F	ROAD	926+77		i49 NB	2.00	8					16
						10.00 POAT	WORK	11111+60		i/Q NR	2.00	10					20

GO20-1 60x24 10.00 ROAD WORK 1144+60 NEXT XX MILES Revision 4/1/2020 Page 10 of 15

i49 NB

10



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

			are details for Construction Si Total Quantity Posted For DWR Date		Station Lo	g Mile Lo	ocation I	Number of Items	SE Each Sign	Special Sign	SF Each Special Sign	Total SE to Pos
,	0210		1219	GO20-1 60x24 10.00 ROAD WORK				2.00	10	Opecial digit	Or Each Opecial oigh	2
				NEXT XX MILES								
				R4-1 36x48 12.00 DO NOT PASS	1059+60	i49	9 NB 2	2.00	12			2
				R2-1 36x48 12.00 SPEED LIMIT XX	1080+25	i49	9 NB 2	2.00	12			2
				R2-1 36x48 12.00 SPEED LIMIT XX	1080+60	i49	9 SB 2	2.00	12			2
				CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE	1139+60	i49	9 NB 2	2.00	12			2
				CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE	877+72	i49	9 SB 2	2.00	12			2
				R2-1 36x48 12.00 SPEED LIMIT XX	936+77	i49	9 NB 2	2.00	12			2
				R2-1 36x48 12.00 SPEED LIMIT XX	936+77	i49	9 SB 2	2.00	12			2
				R4-1 36x48 12.00 DO NOT PASS	966+62	i49	9 NB 2	2.00	12			2
				CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE	ON RAMP	ON	N RAMP 2	2.00	12			2
				WO1-4L 48x48 16.00 REVERSE CURVE (SYMBOL LEFT ARROW)	1050+00	i49	9 NB 2	2.00	16			3
				WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD	1103+20	i49	9 NB 2	2.00	16			3
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD	1129+60	i49	9 NB 2	2.00	16			:
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD	887+72	i49	9 SB 2	2.00	16			;
				WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD	914+12	i49	9 SB 2	2.00	16			3
				WO6-3 48x48 16.00 TWO WAY TRAFFIC (SYMBOL)	966+62	i49	9 NB 2	2.00	16			5
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD	ON RAMP	ON	N RAMP 2	2.00	16			5
				GO20-5aP 36x24 6.00 WORK ZONE (PLAQUE)	1015+00	i49	9 NB 4	4.00	6			2
				GO20-5aP 36x24 6.00 WORK ZONE (PLAQUE)	1045+00	i49	9 NB 4	4.00	6			2
				GO20-5aP 36x24 6.00 WORK ZONE (PLAQUE)	981+62	i49	9 NB 4	4.00	6			2
				R4-1 36x48 12.00 DO NOT PASS	1015+00	i49	9 NB 4	4.00	12			4
				R4-1 36x48 12.00 DO NOT PASS	1045+00	i49	9 NB 4	4.00	12			4
				R4-1 36x48 12.00 DO NOT PASS	981+62	i49	9 NB 4	4.00	12			4
		June 20, 2022	124	See Special Sign Details	1015+00	NB	3 1	1.00		Deduct 1 XX Miles Add No Phone	2.00	
				R4-1 36x48 12.00 DO NOT PASS	1015+00	NB	3 2	2.00	12			
				GO20-5aP 36x24 6.00 WORK ZONE (PLAQUE)	1015+00	NB	В 5	5.00	6			3
				R2-1 36x48 12.00 SPEED LIMIT XX	1015+00	NB	3 3	3.00	12			3
				WO6-3 48x48 16.00 TWO WAY TRAFFIC (SYMBOL)	1015+00	NB	3 2	2.00	16			3
	0210 - Total		in the second second	in the second second								1342

Revision 4/1/2020 Page 11 of 15



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J7I3363	0090	MISC.	Material	Туро	22	May 2, 2022	SYSTEM	(\$65,704.10)	
				- Total				(\$65,704.10)	
			Material - Tota	ı				(\$65,704.10)	
			MaterialCredit		23	May 16, 2022	SYSTEM	\$65,704.10	
				- Total				\$65,704.10	
			MaterialCredit	- Total				\$65,704.10	
			Other Item	ACAD	22	May 2,	martik3	\$5,728.48	ASPHALT CEMENT PRICE ADJUSTMENT FOR HOT MIX ASPHALT (SY):::
			Adjustment			2022			Mix ID BB18-16; 1680 SY @ 7.25" Thick; 3.9% Virgin AC; \$167.5 Index Difference:::
									Mix ID BB18-16; 941 SY @ 4" Thick: 3.9% Virgin AC; \$167.5 Index Difference
					23	May 16,	martik3	\$7,664.82	FOR HOT MIX ASPHALT (SY):::
						2022			MIX ID SP125 21-40A; 3326 SY @ 1.75" THICK; 4.2% VIRGIN AC; \$247.50 INDEX DIFFERENCE:::
									MIX ID BB18-16; 941 SY @ 3.25" THICK; 3.9% VIRGIN AC; \$247.50 INDEX DIFFERENCE:::
									MIX ID BB18-16; 705 SY @ 7.25" THICK; 3.9% VIRGIN AC; \$247.50 INDEX DIFFERENCE
				ACAD - Tota	al			\$13,393.30	
			Other Item Adj	justment - To	tal			\$13,393.30	
	0090 -	Total						\$13,393.30	
	0200	TRUCK OR TRAILER MOUNTED ATTEN	Material		23	May 16, 2022	SYSTEM	(\$800.00)	
		(TMA)		- Total				(\$800.00)	
			Material - Tota	ı				(\$800.00)	
			MaterialCredit		24	Jun 2, 2022	SYSTEM	\$800.00	
				- Total				\$800.00	
			MaterialCredit	- Total				\$800.00	
	0200 -							\$0.00	
	0210	CONSTRUCTION SIGNS	Overrun	Overrun	23	May 16, 2022	SYSTEM	(\$58.00)	
					26	Jul 6, 2022	SYSTEM	\$58.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',7.25000 - 7.25000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - Tota	ıl				\$0.00	
	0210 -	Total						\$0.00	
	0290	TUBULAR MARKER	Overrun	Overrun	23	May 16, 2022	SYSTEM	(\$3,000.00)	
					26	Jul 6, 2022	SYSTEM	\$3,000.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',60.00000 - 60.00000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - Tota					\$0.00	
	0290 -	Total						\$0.00	
	0390	4 IN TEMPORARY PAVEMENT	Material		23	May 16, 2022	SYSTEM	(\$4,844.40)	
		MARKING PAINT		- Total				(\$4,844.40)	
			Material - Tota	ıl				(\$4,844.40)	
			MaterialCredit		24	Jun 2, 2022	SYSTEM	\$4,844.40	
				- Total				\$4,844.40	
			MaterialCredit	- Total				\$4,844.40	
	0390	Total						\$0.00	
	0330 -								



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J7I3363	0430	SEASON	Material			2022			
		GRASSES			24	Jun 2, 2022	SYSTEM	(\$1,282.50)	
					25	Jun 16, 2022	SYSTEM	(\$1,282.50)	
					26	Jul 6, 2022	SYSTEM	(\$1,282.50)	
					27	Jul 19, 2022	SYSTEM	(\$1,282.50)	
					28	Aug 2, 2022	SYSTEM	(\$1,282.50)	
				- Total				(\$7,695.00)	
			Material - Tota	l				(\$7,695.00)	
			MaterialCredit		24	Jun 2, 2022	SYSTEM	\$1,282.50	
					25	Jun 16, 2022	SYSTEM	\$1,282.50	
					26	Jul 6, 2022	SYSTEM	\$1,282.50	
					27	Jul 19, 2022	SYSTEM	\$1,282.50	
					28	Aug 2, 2022	SYSTEM	\$1,282.50	
				- Total				\$6,412.50	
			MaterialCredit	- Total				\$6,412.50	
	0430 -	Total						(\$1,282.50)	
	0470	MGS GUARDRAIL	Construction Stockpile		22	May 2, 2022	SYSTEM	(\$332.50)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$332.50)	
			Construction	Stockpile - To	otal			(\$332.50)	
			Construction Stockpile STMI		1	May 17, 2021	SYSTEM	\$27,930.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$27,930.00	
			Construction	Stockpile STI				\$27,930.00	
			Material		22	May 2, 2022	SYSTEM	(\$475.00)	
				- Total				(\$475.00)	
			Material - Tota					(\$475.00)	
			MaterialCredit		23	May 16, 2022	SYSTEM	\$475.00	
			MaterialCredit	- Total				\$475.00 \$475.00	
	0470 -	Total	MaterialGredit	Total				\$27,597.50	
	0470 -	MGS VERTICAL	Construction		22	May 2,	SYSTEM	(\$3,336.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
	0-00	CONCRETE	Stockpile		~~	2022	STOTEIVI	(ψυ,υυυ.υυ)	r aymont Estimate nom Aujustinom gonerated Stockpile Transaction
		BARRIER TRANSITION		- Total				(\$3,336.00)	
			Construction	Stockpile - To	otal			(\$3,336.00)	
			Construction Stockpile STMI		1	May 17, 2021	SYSTEM	\$8,340.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			GTIVII	- Total				\$8,340.00	
			Construction	Stockpile STI	MI - Total			\$8,340.00	
	0480 -	Total						\$5,004.00	
	0490	MGS END ANCHOR	Construction Stockpile STMI		1	May 17, 2021	SYSTEM	\$579.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$579.00	
			Construction	Stockpile STI	VII - Total			\$579.00	
	0490 -							\$579.00	
	0500	TYPE A CRASHWORTHY	Construction Stockpile		22	May 2, 2022	SYSTEM	(\$3,090.00)	Payment Estimate Item Adjustment generated Stockpile Transaction



roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
3363	0500	END TERMINAL (MASH)	Construction Stockpile	- Total				(\$3,090.00)	
			Construction	Stockpile - To	otal			(\$3,090.00)	
			Construction Stockpile		1	May 17, 2021	SYSTEM	\$6,180.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$6,180.00	
			Construction	Stocknile STI	MI - Total			\$6,180.00	
	0500 -	Total		отооприо от				\$3,090.00	
	0580	DRILLED SHAFTS (5 FT. 0 IN. DIA.)	Material		27	Jul 19, 2022	SYSTEM	(\$33,201.00)	
		(•••••			28	Aug 2, 2022	SYSTEM	\$33,201.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user rosenl2 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					28	Aug 2, 2022	SYSTEM	(\$33,201.00)	
				- Total				(\$33,201.00)	
			Material - Tota					(\$33,201.00)	
					20	A	CVCTEM		
			MaterialCredit		28	Aug 2, 2022	SYSTEM	\$33,201.00	
				- Total				\$33,201.00	
			MaterialCredit	- Total				\$33,201.00	
	0580 -	Total						\$0.00	
	0590	ROCK SOCKETS (4 FT 6 IN. DIA.)	Material		27	Jul 19, 2022	SYSTEM	(\$47,404.50)	
		(4 FT O IN. DIA.)			28	Aug 2, 2022	SYSTEM	\$47,404.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user rosenl2 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					28	Aug 2, 2022	SYSTEM	(\$47,404.50)	
				- Total				(\$47,404.50)	
			Material - Tota					(\$47,404.50)	
			MaterialCredit		28	Aug 2, 2022	SYSTEM	\$47,404.50	
				- Total				\$47,404.50	
			MaterialCredit	- Total				\$47,404.50	
			Overrun	Overrun	27	Jul 19, 2022	SYSTEM	(\$13,084.50)	
				Overrun - T	otal			(\$13,084.50)	
			Overrun - Tota					(\$13,084.50)	
	0590 -	Total						(\$13,084.50)	
			Mataric		20	A	SYSTEM		This adjustment effects the original quature are set of Material Day
	0650	CLASS B CONCRETE (SUBSTRUCTURE)	Material			2022		\$24,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user rosenl2 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					28	Aug 2, 2022	SYSTEM	(\$24,200.00)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0650 -	Total						\$0.00	
	0680	NU 43, PRESTRESSED	Construction Stockpile		14	Dec 1, 2021	SYSTEM	\$248,663.90	Payment Estimate Item Adjustment generated Stockpile Transaction
		CONC NU-GIRDER	STMI	- Total				\$248,663.90	
			Construction	Stockpile STI	MI - Total			\$248,663.90	
			Other Item Adjustment	OTHR		Dec 2, 2021	edelhb1	(\$248,663.90)	Withholding payment of materials stockpile until verification of inspection and approval of NU-Girders is received.
					15	Dec 15, 2021	edelhb1	\$248,663.90	Payment for stockpiled materials previously withheld from pay estimate 0014 due to lack of any report or documentation of inspection. The inspection report has since been received. Sample ID 21KCHJB024 has been reviewed and is ready for authorization once the material has been shipped.
				OTHR - Tota	al			\$0.00	
			Other Item Ad					\$0.00	
			Janet Relit Au	pasament - 10	recii				



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J7I3363	0680 -	Total						\$248,663.90	
	0720	DRILLED SHAFTS (3 FT. 0 IN. DIA.)	Material		28	Aug 2, 2022	SYSTEM	\$38,190.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user rosenl2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					28	Aug 2, 2022	SYSTEM	(\$38,190.00)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0720 -	Total						\$0.00	
	0730	ROCK SOCKETS (2 FT 6IN. DIA.)	Material		28	Aug 2, 2022	SYSTEM	\$36,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user rosenl2 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					28	Aug 2, 2022	SYSTEM	(\$36,400.00)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
			Overrun	Overrun	28	Aug 2, 2022	SYSTEM	\$10,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user rosenl2 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					28	Aug 2, 2022	SYSTEM	(\$10,400.00)	
				Overrun - To	otal			\$0.00	
			Overrun - Tota	al				\$0.00	
	0730 -	Total						\$0.00	
	0760	GALVANIZED STRUCTURAL STEEL PILES (12	Overrun	Overrun	28	Aug 2, 2022	SYSTEM	\$1,504.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user rosenl2 overridding Payment Estimate Exception 24 on the current Payment Estimate.
		STEEL PILES (12 IN			28	Aug 2, 2022	SYSTEM	(\$1,504.00)	
				Overrun - To	otal			\$0.00	
			Overrun - Tota	ıl				\$0.00	
	0760 -	Total						\$0.00	
	0780	DRILLED SHAFTS (3 FT. 0 IN. DIA.)	Material		28	Aug 2, 2022	SYSTEM	\$21,850.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user rosenl2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					28	Aug 2, 2022	SYSTEM	(\$21,850.00)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0780 -	Total						\$0.00	
	0790	ROCK SOCKETS (2 FT 6IN. DIA.)	Material		28	Aug 2, 2022	SYSTEM	\$21,420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user rosenl2 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					28	Aug 2, 2022	SYSTEM	(\$21,420.00)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
			Overrun	Overrun	28	Aug 2, 2022	SYSTEM	\$1,020.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user rosenl2 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					28	Aug 2, 2022	SYSTEM	(\$1,020.00)	
				Overrun - To	otal			\$0.00	
			Overrun - Tota	al				\$0.00	
	0790 -	Total						\$0.00	
J7I3363 -	Total							\$283,960.70	
Overall -	Total							\$283,960.70	