

## Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: May 17, 2021

Progress Estimate N 6	umber	Contract ID Prime Contractor	201120-C02 r Lehman Constru	ction, LLC	Pay Period Start Pay Period End		Original Contract Amount 1 Net Change Order Amount Current Contract Amount	\$1,294,337.00 \$3,332.48 \$1,297,669.48		
Approval Date								By User		
May 17, 2021		at the Project Office Level by	SIMST							
May 17, 2021		Resident Engineer Level by	rileyr1							
May 18, 2021		e Controllers Office Level by	ramses1							
Original Completion	Original Completion Date Current Completion Date Actual Co						ual Completion Date % of Current Contract Amount Complete			
December 1, 202	21	Decembe	er 1, 2021							
	Contract	Informational Dat	tes		Milesto	Milestones				
Date Description	Original	Completion Date	Current Complet	tion Date	No Milestones Exi	ist for Contrac	et			
Acceptance Date										
Awarded Date	Decembe	er 2, 2020	December 2, 202	0						
Letting Date	Novembe	er 20, 2020	November 20, 20	20						
Notice to Proceed Date	January 4	4, 2021	January 4, 2021							
Work Began Date										

Contract Total Pa	ay For Estimate No. 6				
		This Estimate	Previous	To Date	
201120-C02					
	Total Posted Items Pay	\$174,414.48	\$650,521.75	\$824,936.23	
	Gross Item Adjustments	\$0.00	\$20,562.00	\$20,562.00	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
			\$671,083.75	\$845,498.23	
<b>Contract Total Pa</b>	yable This Estimate:	\$174,414.48			

## **Items Paid This Estimate Period**

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount				
J3P3093	0260	7034212	SLAB ON STEEL	SQYD	\$226.000	757	\$171,082.00				
	5001	7129901	MISC.Cover Plate Modification	LS	\$944.730	1	\$944.73				
	5002	7129902	MISC.Structural Steel Repair	EA	\$2,387.750	1	\$2,387.75				
Project J3P3093 -	Total						\$174,414.48				
Overall - Total	Overall - Total										

## **Contract Adjustments This Estimate**

No Contract Adjustments Exist on Contract

Line Item /	Adjusti	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J3P3093	0260	SLAB ON STEEL	Material			-2,054	\$226.00	(\$464,204.00)
	0260	SLAB ON STEEL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user simst overridding Payment Estimate Exception 1 on the current Payment Estimate.	2,054	\$226.00	\$464,204.00
Total								\$0.00

Revision 4/1/2020 Page 1 of 7



## Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

	Contract Project Information											
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work							
J3P3093		Bridge deck replacement	41	SALINE	from 1.5 miles east of Rte. 65 over Rte. O and Mexico Sub Railroad							

## 

Revision 4/1/2020 Page 2 of 7



## Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

## **Exceptions (Discrepancies) This Estimate Period**

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J3P3093, Item 7034212, Project Item Line Number 0260, Material Set 703421296, Material 1036RSDFPL42M25 - Reinforcing Steel No. 8/M25 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Reports in AWP need to be updated.	SIMST	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3093, Item 7034212, Project Item Line Number 0260, Material Set 703421296, Material 1036RSDFPL42M19 - Reinforcing Steel No. 6/M19 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Reports in AWP need to be updated.	SIMST	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3093, Item 7034212, Project Item Line Number 0260, Material Set 703421296, Material 1036RSDFPL42M13 - Reinforcing Steel No. 4/M13 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Reports in AWP need to be updated.	SIMST	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3093, Item 7034212, Project Item Line Number 0260, Material Set 703421296, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	Reports in AWP need to be updated.	SIMST	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3093, Item 7034212, Project Item Line Number 0260, Material Set 703421296, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Reports in AWP need to be updated.	SIMST	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3093, Item 7034212, Project Item Line Number 0260, Material Set 703421296, Material 0705DPRCPS30 - Prestress Conc Deck Panel 3" (75 mm), Acceptance Action Generic 0705DPRCPS30 is insufficient.	Reports in AWP need to be updated.	SIMST	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3093, Item 7034212, Project Item Line Number 0260, Material Set 703421296, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Reports in AWP need to be updated.	SIMST	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3093, Item 7034212, Project Item Line Number 0260, Material Set 703421296, Material 1036RSDFEC42M25 - Rein Steel EC No. 8/M25 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Reports in AWP need to be updated.	SIMST	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3093, Item 7034212, Project Item Line Number 0260, Material Set 703421296, Material 1036RSDFPL42M16 - Reinforcing Steel No. 5/M16 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Reports in AWP need to be updated.	SIMST	Overridden

Revision 4/1/2020 Page 3 of 7



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
201120-C02	J3P3093	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.40	\$13,200.00	\$5,280.00
		0001	0020	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	44.00	0.00	44.00	SQFT	44.00	\$175.00	\$7,700.00
		0001	0030	2153000	SHAPING SLOPES, CLASS III	3.00	0.00	3.00	100F	0.00	\$750.00	\$0.00
		0001	0040	4011213	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-3)	40.30	0.00	40.30	TONS	0.00	\$250.00	\$0.00
		0001	0050	4071005	TACK COAT	196.00	0.00	196.00	GAL	0.00	\$3.50	\$0.00
		0001	0060	5041000	CONCRETE APPROACH PAVEMENT	356.00	0.00	356.00	SQYD	0.00	\$120.00	\$0.00
		0001	0070	6161005	CONSTRUCTION SIGNS	1,155.00	0.00	1,155.00	SQFT	974.00	\$7.00	\$6,818.00
		0001	0080	6161008	ADVANCED WARNING RAIL SYSTEM	3.00	0.00	3.00	EA	2.00	\$200.00	\$400.00
		0001	0090	6161009	FLAG ASSEMBLY	4.00	0.00	4.00	EA	0.00	\$50.00	\$0.00
		0001	0100	6161025	CHANNELIZER (TRIM LINE)	50.00	0.00	50.00	EA	50.00	\$15.00	\$750.00
		0001	0110	6161030	TYPE III MOVEABLE BARRICADE	9.00	0.00	9.00	EA	9.00	\$150.00	\$1,350.00
		0001	0120	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	5.00	0.00	5.00	EA	5.00	\$4,500.00	\$22,500.00
		0001	0130	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.75	\$75,835.00	\$56,876.25
		0001	0140	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	1,176.00	0.00	1,176.00	LF	0.00	\$0.65	\$0.00
		0001	0150	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,454.00	0.00	1,454.00	LF	0.00	\$0.65	\$0.00
		0001	0160	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	978.00	0.00	978.00	SQYD	0.00	\$15.00	\$0.00
		0001	0170	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.35	\$7,500.00	\$2,625.00
		0001	0180	8061016	SEDIMENT REMOVAL	16.00	0.00	16.00	CUYD	0.00	\$25.00	\$0.00
		0001	0190	8061019	SILT FENCE	1,600.00	0.00	1,600.00	LF	0.00	\$3.00	\$0.00
		0010	0200	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	500.00	0.00	500.00	LF	0.00	\$22.50	\$0.00
		0010	0210	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	4.00	0.00	4.00	EA	0.00	\$2,500.00	\$0.00
		0010	0220	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	4.00	0.00	4.00	EA	0.00	\$2,550.00	\$0.00
		0070	0230	2162500	REMOVAL OF EXISTING BRIDGE DECK	19,497.00	0.00	19,497.00	SQFT	19,497.00	\$6.50	\$126,730.50
		0070	0240	2169902	MISC.REMOVAL OF EXISTING BEARINGS	12.00	0.00	12.00	EA	12.00	\$1,600.00	\$19,200.00
		0070	0250	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	196.00	0.00	196.00	SQYD	0.00	\$195.00	\$0.00
		0070	0260	7034212	SLAB ON STEEL	2,162.00	0.00	2,162.00	SQYD	2,054.00	\$226.00	\$464,204.00
		0070	0270	7034219A	TYPE D BARRIER	876.00	0.00	876.00	LF	0.00	\$96.00	\$0.00
		0070	0280	7040101	SUBSTRUCTURE REPAIR (FORMED)	150.00	0.00	150.00	SQFT	0.00	\$125.00	\$0.00
		0070	0290	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$4,500.00	\$0.00
		0070	0300	7121250	STRENGTHENING EXISTING BEAMS	1.00	0.00	1.00	LS	1.00	\$34,150.00	\$34,150.00
		0070	0310	7123610	SLAB DRAIN	8.00	0.00	8.00	EA	8.00	\$384.00	\$3,072.00
		0070	0320	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	2,100.00	0.00	2,100.00	SQFT	0.00	\$45.00	\$0.00
		0070	0330	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	2,100.00	0.00	2,100.00	SQFT	0.00	\$5.50	\$0.00
		0070	0340	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	2,100.00	0.00	2,100.00	SQFT	0.00	\$2.75	\$0.00
		0070	0350	7125370A	FINISH FIELD COAT (SYSTEM G)	2,100.00	0.00	2,100.00	SQFT	0.00	\$2.75	\$0.00
		0070	0360	7126000	NON-DESTRUCTIVE TESTING	62.00	0.00	62.00	LF	62.00	\$35.00	\$2,170.00
		0070	0370	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	0.00	\$2,300.00	\$0.00
		0070	0380	7162000	LAMINATED NEOPRENE BEARING PAD ASSEMBLY	12.00	0.00	12.00	EA	12.00	\$2,450.00	\$29,400.00
		0070	0390	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	124.00	0.00	124.00	LF	62.00	\$619.00	\$38,378.00
		0070	5001	7129901	MISC.Cover Plate Modification	0.00	1.00	1.00	LS	1.00	\$944.73	\$944.73
		0070	5002	7129902	MISC.Structural Steel Repair	0.00	1.00	1.00	EA	1.00	\$2,387.75	\$2,387.75
	Project J	3P3093 - To	otal Value	Posted to D	ate as of Report Generated Date							\$824,936.23
201120-C02 Ove	rall - Total	Value Post	ted to Dat	te as of Repo	ort Generated Date							\$824,936.23

Revision 4/1/2020 Page 4 of 7



### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

## The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J3P3093

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0260	7034212	SLAB ON STEEL	5/14/21	5/17/21	757.00	SQYD	bridge A2875 concrete placement	79+36		83+42		
5001	7129901	MISC. STRUCTURAL STEEL CONSTRUCTION	5/14/21	5/17/21	1.00	LS	bridge A2875 span 6-7 girders 1-6	81+63		82+48		
5002	7129902	MISC.	5/14/21	5/17/21	1.00	EA	bridge A2875 bent 5 girder 3.	81+08				

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 4/1/2020 Page 5 of 7



# Line Item Adjustments by Estimate

Contract ID:190621-F01

t Lir	ine	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
93 00	070	CONSTRUCTION	Material	Туре	1	Mar 2,	SYSTEM	\$6,818.00	This adjustment offsets the original system-generated Material Payment
		SIGNS				2021			Estimate Item Adjustment (0001) due to user simst overridding Payment Estimate Exception 1 on the current Payment Estimate.
					1	Mar 2, 2021	SYSTEM	(\$6,818.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
00	)70 - '	Total						\$0.00	
008	080	ADVANCED WARNING RAIL SYSTEM	Material		1	Mar 2, 2021	SYSTEM	\$400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user simst overridding Payment Estimate Exception 2 on the current Payment Estimate.
		STOTE			1	Mar 2, 2021	SYSTEM	(\$400.00)	Estimate Exception 2 of the sentent ayribin Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
00	180 -	Total						\$0.00	
		CHANNELIZER	Material		1	Mor 2	SYSTEM		This adjustment affects the original custom generated Material Dayment
011	100	(TRIM LINE)	матела		1	Mar 2, 2021	SYSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user simst overridding Payment Estimate Exception 3 on the current Payment Estimate.
					1	Mar 2, 2021	SYSTEM	(\$750.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
01	100 -	Total						\$0.00	
01	0110 TYPE I MOVEABL	TYPE III MOVEABLE BARRICADE	Material		1	Mar 2, 2021	SYSTEM	\$1,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user simst overridding Payment Estimate Exception 4 on the current Payment Estimate.
					1	Mar 2, 2021	SYSTEM	(\$1,350.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
01	110 -	Total	Material - To	tal					
	120	Total  CMS W/O COMMUNICATION INTERFACE,	Material - To	tal	1	Mar 2, 2021	SYSTEM	\$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user simst overridding Payment Estimate Exception 5 on the current Payment Estimate.
	120	CMS W/O COMMUNICATION		tal	1		SYSTEM	\$0.00 \$0.00	Estimate Item Adjustment (0005) due to user simst overridding Payment
	120	CMS W/O COMMUNICATION INTERFACE,		tal - Total		2021 Mar 2,		\$0.00 \$0.00 \$22,500.00	Estimate Item Adjustment (0005) due to user simst overridding Payment
	120	CMS W/O COMMUNICATION INTERFACE,		- Total		2021 Mar 2,		\$0.00 \$0.00 \$22,500.00 (\$22,500.00)	Estimate Item Adjustment (0005) due to user simst overridding Payment
01:	120	CMS W/O COMMUNICATION INTERFACE, CONT F/	Material	- Total		2021 Mar 2,		\$0.00 \$0.00 \$22,500.00 (\$22,500.00) \$0.00	Estimate Item Adjustment (0005) due to user simst overridding Payment
01:	120 -	CMS W/O COMMUNICATION INTERFACE, CONT F/  Total MGS GUARDRAIL, 8 FT. POSTS, 6	Material - Tot  Construction Stockpile	- Total		2021 Mar 2,		\$0.00 \$0.00 \$22,500.00 (\$22,500.00)	Estimate Item Adjustment (0005) due to user simst overridding Payment
01:	120 -	CMS W/O COMMUNICATION INTERFACE, CONT F/	Material - Tot  Construction Stockpile	- Total	1	2021 Mar 2, 2021	SYSTEM	\$0.00 \$0.00 \$22,500.00 (\$22,500.00) \$0.00 \$0.00	Estimate Item Adjustment (0005) due to user simst overridding Payment Estimate Exception 5 on the current Payment Estimate.
01:	120 -	CMS W/O COMMUNICATION INTERFACE, CONT F/  Total MGS GUARDRAIL, 8 FT. POSTS, 6	Material - Tot  Construction Stockpile STMI	- Total tal	1	Mar 2, 2021  May 3, 2021	SYSTEM	\$0.00 \$0.00 \$22,500.00 (\$22,500.00) \$0.00 \$0.00 \$7,710.00	Estimate Item Adjustment (0005) due to user simst overridding Payment Estimate Exception 5 on the current Payment Estimate.
01: 01: 02:	120 - 120 - 1200 - 1200	CMS W/O COMMUNICATION INTERFACE, CONT F/  Total  MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN	Material - Tot  Construction Stockpile STMI	- Total tal - Total	1	Mar 2, 2021  May 3, 2021	SYSTEM	\$0.00 \$0.00 \$22,500.00) (\$22,500.00) \$0.00 \$0.00 \$7,710.00 \$7,710.00	Estimate Item Adjustment (0005) due to user simst overridding Payment Estimate Exception 5 on the current Payment Estimate.
01: 02:	120 - 120 - 1200 - 1200	CMS W/O COMMUNICATION INTERFACE, CONT F/  Total MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN  Total MGS BRIDGE APP. TRANS SEC	Material - Tot  Construction Stockpile STMI  Construction Stockpile	- Total tal - Total	1	Mar 2, 2021  May 3, 2021	SYSTEM	\$0.00 \$0.00 \$22,500.00 (\$22,500.00) \$0.00 \$0.00 \$7,710.00	Estimate Item Adjustment (0005) due to user simst overridding Payment Estimate Exception 5 on the current Payment Estimate.
01: 02:	120 - 1	CMS W/O COMMUNICATION INTERFACE, CONT F/  Total  MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN  Total  MGS BRIDGE	Material - Tot  Material - Tot  Construction Stockpile STMI  Construction	- Total tal - Total	1 5	2021 Mar 2, 2021 May 3, 2021	SYSTEM	\$0.00 \$0.00 \$22,500.00 (\$22,500.00) \$0.00 \$0.00 \$7,710.00 \$7,710.00 \$7,710.00	Estimate Item Adjustment (0005) due to user simst overridding Payment Estimate Exception 5 on the current Payment Estimate.  Payment Estimate Item Adjustment generated Stockpile Transaction
01: 01: 02:	120 - 1	CMS W/O COMMUNICATION INTERFACE, CONT F/  Total MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN  Total MGS BRIDGE APP. TRANS SEC	Material - Too  Construction Stockpile STMI  Construction Construction Stockpile STMI	- Total tal - Total 1 Stockpile ST	1 5 5 FMI - Total 5	Mar 2, 2021  May 3, 2021  May 3, 2021	SYSTEM	\$0.00 \$0.00 \$22,500.00) (\$22,500.00) \$0.00 \$0.00 \$7,710.00 \$7,710.00 \$7,710.00 \$6,672.00	Estimate Item Adjustment (0005) due to user simst overridding Payment Estimate Exception 5 on the current Payment Estimate.  Payment Estimate Item Adjustment generated Stockpile Transaction
01: 02: 02:	120 - 120 - 1200 - 1210	CMS W/O COMMUNICATION INTERFACE, CONT F/  Total MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN  Total MGS BRIDGE APP. TRANS SEC	Material - Too  Construction Stockpile STMI  Construction Construction Stockpile STMI	- Total - Total n Stockpile ST	1 5 5 FMI - Total 5	Mar 2, 2021  May 3, 2021  May 3, 2021	SYSTEM	\$0.00 \$0.00 \$22,500.00) (\$22,500.00) \$0.00 \$0.00 \$7,710.00 \$7,710.00 \$6,672.00	Estimate Item Adjustment (0005) due to user simst overridding Payment Estimate Exception 5 on the current Payment Estimate.  Payment Estimate Item Adjustment generated Stockpile Transaction
01: 01: 02: 02: 02:	120 - 120 - 1200 - 1210	CMS W/O COMMUNICATION INTERFACE, CONT F/  Total  MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN  Total  MGS BRIDGE APP. TRANS SEC (REG/NO CURB)  Total  TYPE A CRSHWTHY END	Material - Tot  Material - Tot  Construction Stockpile STMI  Construction Stockpile STMI  Construction Construction	- Total - Total n Stockpile ST	1 5 5 FMI - Total 5	Mar 2, 2021  May 3, 2021  May 3, 2021	SYSTEM	\$0.00 \$0.00 \$22,500.00 \$22,500.00) \$0.00 \$0.00 \$7,710.00 \$7,710.00 \$7,710.00 \$6,672.00 \$6,672.00	Estimate Item Adjustment (0005) due to user simst overridding Payment Estimate Exception 5 on the current Payment Estimate.  Payment Estimate Item Adjustment generated Stockpile Transaction
01: 01: 02: 02:	120 - 120 - 2200 -	CMS W/O COMMUNICATION INTERFACE, CONT F/  Total MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN  Total MGS BRIDGE APP. TRANS SEC (REG/NO CURB)  Total  TYPE A	Material - Tot  Material - Tot  Construction Stockpile STMI  Construction Stockpile STMI  Construction Construction	- Total - Total n Stockpile ST	1 5 FMI - Total	Mar 2, 2021  May 3, 2021  May 3, 2021	SYSTEM	\$0.00 \$0.00 \$22,500.00) \$22,500.00) \$0.00 \$0.00 \$7,710.00 \$7,710.00 \$7,710.00 \$6,672.00 \$6,672.00 \$6,672.00	Estimate Item Adjustment (0005) due to user simst overridding Payment Estimate Exception 5 on the current Payment Estimate.  Payment Estimate Item Adjustment generated Stockpile Transaction  Payment Estimate Item Adjustment generated Stockpile Transaction
01: 01: 02: 02: 02:	120 - 120 - 2200 -	CMS W/O COMMUNICATION INTERFACE, CONT F/  Total  MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN  Total  MGS BRIDGE APP. TRANS SEC (REG/NO CURB)  Total  CRSHWTHY END TERMINAL	Material - Total - Tot	- Total  - Total  1 Stockpile ST  - Total  1 Stockpile ST	1 5 FMI - Total 5 FMI - Total	May 3, 2021  May 3, 2021	SYSTEM	\$0.00 \$0.00 \$22,500.00) \$0.00 \$0.00 \$7,710.00 \$7,710.00 \$6,672.00 \$6,672.00 \$6,672.00 \$6,672.00 \$6,672.00	Estimate Item Adjustment (0005) due to user simst overridding Payment Estimate Exception 5 on the current Payment Estimate.  Payment Estimate Item Adjustment generated Stockpile Transaction  Payment Estimate Item Adjustment generated Stockpile Transaction
01: 01: 02: 02: 02:	120	CMS W/O COMMUNICATION INTERFACE, CONT F/  Total  MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN  Total  MGS BRIDGE APP. TRANS SEC (REG/NO CURB)  Total  CRSHWTHY END TERMINAL (MASH)	Material - Total - Tot	- Total  - Total  - Stockpile ST	1 5 FMI - Total 5 FMI - Total	May 3, 2021  May 3, 2021	SYSTEM	\$0.00 \$0.00 \$22,500.00 \$22,500.00) \$0.00 \$0.00 \$7,710.00 \$7,710.00 \$7,710.00 \$6,672.00 \$6,672.00 \$6,672.00 \$6,180.00 \$6,180.00	Estimate Item Adjustment (0005) due to user simst overridding Payment Estimate Exception 5 on the current Payment Estimate.  Payment Estimate Item Adjustment generated Stockpile Transaction  Payment Estimate Item Adjustment generated Stockpile Transaction
01: 01: 02: 02: 02:	120	CMS W/O COMMUNICATION INTERFACE, CONT F/  Total  MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN  Total  MGS BRIDGE APP. TRANS SEC (REG/NO CURB)  Total  CRSHWTHY END TERMINAL	Material - Tot  Material - Tot  Construction Stockpile STMI  Construction Stockpile STMI  Construction Stockpile STMI  Construction	- Total  - Total  - Stockpile ST	1 5 FMI - Total 5 FMI - Total	May 3, 2021  May 3, 2021	SYSTEM	\$0.00 \$0.00 \$22,500.00 \$22,500.00) \$0.00 \$0.00 \$7,710.00 \$7,710.00 \$7,710.00 \$6,672.00 \$6,672.00 \$6,672.00 \$6,672.00 \$6,180.00	Estimate Item Adjustment (0005) due to user simst overridding Payment Estimate Exception 5 on the current Payment Estimate.  Payment Estimate Item Adjustment generated Stockpile Transaction  Payment Estimate Item Adjustment generated Stockpile Transaction

May 18, 2021



# Line Item Adjustments by Estimate

Contract ID:190621-F01

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
3P3093	0260	SLAB ON STEEL	Material			2021						
					4	Apr 16, 2021	SYSTEM	\$188,710.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user simst overridding Payment Estimate Exception 1 on the current Payment Estimate.			
					4	Apr 16, 2021	SYSTEM	(\$188,710.00)				
					5	May 3, 2021	SYSTEM	\$293,122.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user simst overridding Payment Estimate Exception 1 on the current Payment Estimate.			
					5	May 3, 2021	SYSTEM	(\$293,122.00)				
								6	May 17, 2021	SYSTEM	\$464,204.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user simst overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	May 17, 2021	SYSTEM	(\$464,204.00)				
				- Total				\$0.00				
			Material - To	tal				\$0.00				
	0260 -	Total						\$0.00				
	0300	STRENGTHENING EXISTING BEAMS	Material		3	Apr 1, 2021	SYSTEM	\$17,075.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user simst overridding Payment Estimate Exception 12 on the current Payment Estimate.			
					3	Apr 1, 2021	SYSTEM	(\$17,075.00)				
				- Total				\$0.00				
			Material - To	tal				\$0.00				
	0300 -	Total						\$0.00				
3P3093	- Total							\$20,562.00				
verall -	Total							\$20,562.00				