

### **Missouri Department of Transportation** Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 21, 2021

Final Estimate Number 13	Contract ID Prime Contractor	201120-C08 Superior Bowen Asphalt Company, LLC	Pay Period Start Pay Period Er	October 16, 2021 October 21, 2021	Original Contract Amount Net Change Order Amount Current Contract Amo	\$1,268,980.49 (\$179,056.77) punt\$1,089,923.72	
Approval Date						By User	

November 4, Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by 2021	Approval Date													ı	By User
November 4, Reviewed and Approved at the Central Office Controllers Office Level by ramses:	October 21, 2021	Generated and Approved (and should be considered Draft) at the Project Office Level by													sandis1
	,	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by												holdtc	
	,	Reviewed and Approved at the Central Office Controllers Office Level by													ramses1

Original Completion Date	<b>Current Completion Date</b>	Actual Completion Date	% of Current Contract Amount Complete
October 29, 2021	October 29, 2021	June 28, 2021	100.00%

	Contract Informational Dates											
Date Description	Original Completion Date	<b>Current Completion Date</b>	No Milestones Exist for Contract									
Acceptance Date	October 22, 2021	October 22, 2021										
Awarded Date	December 2, 2020	December 2, 2020										
Letting Date	November 20, 2020	November 20, 2020										
Notice to Proceed Date	January 4, 2021	January 4, 2021										
Work Began Date	April 27, 2021	April 27, 2021										

Contract Total Pa	ay For Estimate No. 13				
		This Estimate	Previous	To Date	
201120-C08					
	Total Posted Items Pay	\$0.00	\$1,089,923.73	\$1,089,923.73	
	Gross Item Adjustments	\$0.00	\$31,324.36	\$31,324.36	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$25,830.30	\$25,830.30	
			\$1,147,078.39	\$1,147,078.39	
Contract Total Pa	yable This Estimate:	\$0.00			
Contract Total Pa	Other Contract Adjustments	\$0.00	\$25,830.30	\$25,830.30	

### **Items Paid This Estimate Period**

No Data Available

### Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

No Data Available


Page 1 of 12 Revision 4/1/2020



### Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Con	tract Project Information	on
Project Number	Federal Proj. Number	Project Description	Route	County		· ·	Location of Work
J4S3328	FAS S302(83)	Resurface	12	JACKSON	from I-435 to Spring Street		
Γotals by J	Job Numbe	ers					
J4S3328		d Item Pay Item Adjustm		Item Pay	This Estimate \$0.00 \$0.00 \$0.00	Previous \$1,089,923.73 \$31,324.36 \$1,121,248.09	To Date \$1,089,923.73 \$31,324.36 \$1,121,248.09
Incentive Disincentive Liquidated Damages Other Contract Adjustments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$25,830.30	\$0.00 \$0.00 \$0.00 \$25,830.30			

Revision 4/1/2020 Page 2 of 12





# Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

# Exceptions (Discrepancies) This Estimate Period No Exceptions Exist on Contract

Revision 4/1/2020 Page 3 of 12



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)	
201120-C08	J4S3328	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$3,150.00	\$3,150.00	
		0001	0020	2063500	CULVERT CLEANOUT	4.00	0.00	4.00	EA	4.00	\$2,421.30	\$9,685.20	
		0001	0030	2153000	SHAPING SLOPES, CLASS III	4.50	0.00	4.50	100F	4.50	\$610.00	\$2,745.00	
		0001	0040	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	1,709.90	-468.50	1,241.40	TONS	1,241.40	\$70.65	\$87,704.91	
		0001	0050	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	9,867.80	155.90	10,023.70	TONS	10,023.70	\$57.28	\$574,157.54	
		0001	0060	4071005	TACK COAT	11,904.00	-5,495.00	6,409.00	GAL	6,409.00	\$2.15	\$13,779.35	
		0001	0070	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	690.70	-356.07	334.63	SQYD	334.63	\$191.75	\$64,165.30	
		0001	0080	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	69.10	-69.10	0.00	SQYD	0.00	\$1.15	\$0.00	
		0001	0090	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	69.10	-69.10	0.00	SQYD	0.00	\$1.15	\$0.00	
		0001	0100	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	2,368.00	-1,012.00	1,356.00	LF	1,356.00	\$1.90	\$2,576.40	
		0001	0110	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	1,700.00	-1,389.00	311.00	EA	311.00	\$4.50	\$1,399.50	
		0001	0120	6133018	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS B PARTIAL DEPTH PAVEMENT REPAIR	140.80	-120.25	20.55	TONS	20.55	\$99.60	\$2,046.78	
		0001	0130	6133019	REMOVAL FOR CLASS B PARTIAL DEPTH PAVEMENT REPAIR	847.20	-768.20	79.00	SQYD	79.00	\$70.90	\$5,601.10	
		0001	0140	6161005	CONSTRUCTION SIGNS	739.00	184.00	923.00	SQFT	923.00	\$4.00	\$3,692.00	
		0001	0150	6161008	ADVANCED WARNING RAIL SYSTEM	2.00	0.00	2.00	EA	2.00	\$20.00	\$40.00	
		0001	0160	6161009	FLAG ASSEMBLY	20.00	-20.00	0.00	EA	0.00	\$20.00	\$0.00	
		0001	0170	6161025	CHANNELIZER (TRIM LINE)	165.00	175.00	340.00	EA	340.00	\$15.00	\$5,100.00	
	C		0180	6161031	TYPE III MOVEABLE BARRICADE WITH LIGHTS	2.00	0.00	2.00	EA	2.00	\$50.00	\$100.00	
			0190	6161034	DIRECTIONAL INDICATOR BARRICADE WITH LIGHT	14.00	-14.00	0.00	EA	0.00	\$25.00	\$0.00	
		0001	0200	6161040	FLASHING ARROW PANEL	2.00	1.00	3.00	EA	3.00	\$700.00	\$2,100.00	
		0001	0210	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	4.00	\$1,750.00	\$7,000.00	
	0001 0220 618			6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$98,500.00	\$98,500.00	
		0001	0230	6200003	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 4 IN., WHITE	3,194.00	0.00	3,194.00	LF	3,194.00	\$2.00	\$6,388.00	
		0001 024	0001 0240	0240 6200	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	918.00	-107.00	811.00	LF	811.00	\$10.00	\$8,110.00
		0001	0250	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	155.00	-11.00	144.00	LF	144.00	\$10.00	\$1,440.00	
		0001	0260	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	18.00	-4.00	14.00	EA	14.00	\$200.00	\$2,800.00	
		0001	0270	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	259.00	-38.00	221.00	EA	221.00	\$90.00	\$19,890.00	
		0001	0280	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	497.00	0.00	497.00	LF	497.00	\$1.00	\$497.00	
		0001	0290	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	49,747.00	50.00	49,797.00	LF	49,797.00	\$0.18	\$8,963.46	
		0001	0300	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	45,182.00	0.00	45,182.00	LF	45,182.00	\$0.18	\$8,132.76	
		0001	0310	6207001	PAVEMENT MARKING REMOVAL	922.00	0.00	922.00	LF	922.00	\$1.00	\$922.00	
		0001	0320	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	119,039.00	0.00	119,039.00	SQYD	119,039.00	\$0.78	\$92,850.42	
		0010	0330	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	1,075.00	0.00	1,075.00	LF	1,075.00	\$21.00	\$22,575.00	
		0010	0340	6062202A	BRIDGE ANCHOR SECTION, 7.5 FT. POSTS (SAFETY BARRIER CURB) (ROADWAY AND REHABILITATION WORK ONLY)	4.00	0.00	4.00	EA	4.00	\$1,870.00	\$7,480.00	
		0010	0350	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	6.00	0.00	6.00	EA	6.00	\$2,360.00	\$14,160.00	
		0001	0360	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$500.00	\$1,000.00	
		0030	0370	9028500	CABLE, LOOP DETECTOR, IN DUCT	1,240.00	0.00	1,240.00	LF	1,240.00	\$7.35	\$9,114.00	
	0001 5001 2069901 MISC. Culvert Cleanout		MISC.Culvert Cleanout	0.00	1.00	1.00	LS	1.00	\$1,701.00	\$1,701.00			
	0001 5002 6131017 DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR			0.00	36.00	36.00	EA	36.00	\$7.00	\$252.00			
		0001	5003	6131018	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	0.00	15.00	15.00	EA	15.00	\$7.00	\$105.00	
	Project J	4S3328 - To	otal Value	Posted to D	Date as of Report Generated Date							\$1,089,923.72	
201120-C08 Ove	rall - Total	Value Pos	ted to Dat	te as of Repo	ort Generated Date							\$1,089,923.72	

Revision 4/1/2020 Page 4 of 12



# Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 4/1/2020 Page 5 of 12



ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
8	0040	BIT. PAVEMENT	Other Item	ACAD	9	Sep 1,	weathc1	\$2,860.27	Job Number: J4S3328
		MIXTURE PG64-22 (BP-1)	Adjustment			2021		•,,	Line Number: 0040, 1.75", BITUMINOUS PAVEMENT MIXTURE PG 64-22 (BP-1) 21-37 Line Number: 0040, 1.75", ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C) 21-37 Line Number: 0050, 1.75", ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C) 21-37 Line Number: 0120, 1.75", BITUMINOUS PAVEMENT MIXTURE PG 64-22 (BP-1) 20-48
									Asphalt Cement Price Adjustment Breakdown
									Line No. 0040 (for Shoulders) - \$65.95 + \$2,794.32 = \$2,860.27 Line No. 0050 (for Mainline) - \$27,740.59 = \$27,740.59 Line No. 0120 (for Partial Depth Pavement Repairs) - \$38.43 = \$38.43
									Grand Total \$30,639.29
				ACAD - Tot	al			\$2,860.27	
			Other Item /	Adjustment -	Total			\$2,860.27	
	0040 -	Total						\$2,860.27	
	0050	ASPHALTIC CONCRETE MIXTURE PG	Material		2	May 17, 2021	SYSTEM	\$574,157.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user weathc1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		70-22 (SP125C MIX)			2	May 17, 2021	SYSTEM	(\$574,157.54)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Other Item Adjustment	ACAD	9	Sep 1, 2021	weathc1	\$27,740.59	Job Number: J4S3328
									Line Number: 0040, 1.75", BITUMINOUS PAVEMENT MIXTURE PG 64-22 (BP-1) 21-37 Line Number: 0040, 1.75", ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C) 21-37 Line Number: 0050, 1.75", ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C) 21-37 Line Number: 0120, 1.75", BITUMINOUS PAVEMENT MIXTURE PG 64-22 (BP-1) 20-48
									Asphalt Cement Price Adjustment Breakdown
									Line No. 0040 (for Shoulders) - \$65.95 + \$2,794.32 = \$2,860.27 Line No. 0050 (for Mainline) - \$27,740.59 = \$27,740.59 Line No. 0120 (for Partial Depth Pavement Repairs) - \$38.43 = \$38.43
									Grand Total \$30,639.29
				ACAD - Tot	al			\$27,740.59	
			Other Item /	Adjustment -	Total			\$27,740.59	
			Overrun	Overrun	2	May 17, 2021	SYSTEM	\$8,929.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 8 on the current Payment Estimate. Material Insufficiency Quantity 10023.700; Overrun Quantity Balance 155.90.
					2	May 17, 2021	SYSTEM	(\$8,929.95)	
					3	Jun 2, 2021	SYSTEM	(\$8,929.95)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					3	Jun 2, 2021	SYSTEM	\$8,929.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user weathc1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				Overrun - T	otal			\$0.00	
			Overrun - T	otal				\$0.00	
	0050 -	Total						\$27,740.59	
	0060	TACK COAT	Material		2	May 17, 2021	SYSTEM	\$13,529.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user weathc1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					2	May 17, 2021	SYSTEM	(\$13,529.95)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0060 -	Total						\$0.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks														
J4S3328	0070	FURN & PLACE CONC MATL FOR FULL DEPTH	Material		1	May 3, 2021	SYSTEM	\$24,415.53	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user weathc1 overridding Payment Estimate Exception 1 on the current Payment Estimate.														
		DEPTH			1	May 3, 2021	SYSTEM	(\$24,415.53)															
					2	May 17, 2021	SYSTEM	\$42,434.28	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Exception 3 on the current Payment Estimate.														
					2	May 17, 2021	SYSTEM	(\$42,434.28)															
					3	Jun 2, 2021	SYSTEM	\$64,165.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user weathc1 overridding Payment Estimate Exception 4 on the current Payment Estimate.														
					3	Jun 2, 2021	SYSTEM	(\$64,165.30)															
					4	Jun 16, 2021	SYSTEM	\$64,165.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user weathc1 overridding Payment Estimate Exception 2 on the current Payment Estimate.														
					4	Jun 16, 2021	SYSTEM	(\$64,165.30)															
					5	Jun 30, 2021	SYSTEM	\$64,165.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user weathc1 overridding Payment Estimate Exception 2 on the current Payment Estimate.														
					5	Jun 30, 2021	SYSTEM	(\$64,165.30)															
					6	Jul 16, 2021	SYSTEM	\$64,165.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user weathc1 overridding Payment Estimate Exception 2 on the current Payment Estimate.														
					6	Jul 16, 2021	SYSTEM	(\$64,165.30)															
					7	Aug 2, 2021	SYSTEM	\$64,165.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user weathc1 overridding Payment Estimate Exception 3 on the current Payment Estimate.														
					7	Aug 2, 2021	SYSTEM	(\$64,165.30)															
									8	Aug 16, 2021	SYSTEM	\$64,165.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user weathc1 overridding Payment Estimate Exception 2 on the current Payment Estimate.										
									8	Aug 16, 2021	SYSTEM	(\$64,165.30)											
								9	Sep 1, 2021	SYSTEM	\$64,165.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user weathc1 overridding Payment Estimate Exception 2 on the current Payment Estimate.											
					9	Sep 1, 2021	SYSTEM	(\$64,165.30)															
				- Total				\$0.00															
			Material - To	otal				\$0.00															
	(C	DOWEL BAR (DRILLING, FURNISHING			1	May 3, 2021	SYSTEM	<b>\$0.00</b> <b>\$918.00</b>	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user weathc1 overridding Payment Estimate Exception 3 on the current Payment Estimate.														
		AND INST			1	May 3, 2021	SYSTEM	(\$918.00)															
					:											2	May 17, 2021	SYSTEM	\$1,399.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.			
						2	May 17, 2021	SYSTEM	(\$1,399.50)														
						:													3	Jun 2, 2021	SYSTEM	\$1,399.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
																				3	Jun 2, 2021	SYSTEM	(\$1,399.50)
						4	Jun 16, 2021	SYSTEM	\$1,399.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user weathc1 overridding Payment Estimate Exception 4 on the current Payment Estimate.													



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks					
J4S3328	0110	DOWEL BAR (DRILLING,	Material		4	Jun 16, 2021	SYSTEM	(\$1,399.50)						
		FURNISHING AND INST			5	Jun 30, 2021	SYSTEM	\$1,399.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user weathc1 overridding Payment Estimate Exception 4 on the current Payment Estimate.					
					5	Jun 30, 2021	SYSTEM	(\$1,399.50)						
					6	Jul 16, 2021	SYSTEM	\$1,399.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user weathc1 overridding Payment Estimate Exception 4 on the current Payment Estimate.					
					6	Jul 16, 2021	SYSTEM	(\$1,399.50)						
					7	Aug 2, 2021	SYSTEM	\$1,399.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user weathc1 overridding Payment Estimate Exception 4 on the current Payment Estimate.					
						7	Aug 2, 2021	SYSTEM	(\$1,399.50)					
						8	Aug 16, 2021	SYSTEM	\$1,399.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user weathc1 overridding Payment Estimate Exception 4 on the current Payment Estimate.				
					8	Aug 16, 2021	SYSTEM	(\$1,399.50)						
									9	Sep 1, 2021	SYSTEM	\$1,399.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user weathc1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	
					9	Sep 1, 2021	SYSTEM	(\$1,399.50)						
									10	Sep 15, 2021	SYSTEM	\$1,399.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user weathc1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
											10	Sep 15, 2021	SYSTEM	(\$1,399.50)
				- Total				\$0.00						
			Material - To	otal				\$0.00						
	0110 -							\$0.00						
	0120	FURN & PLACE BIT. MATL FOR CL B PARTIAL	Material		1	May 3, 2021	SYSTEM	\$2,046.78	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.					
					1	May 3, 2021	SYSTEM	(\$2,046.78)						
					2	May 17, 2021	SYSTEM	\$2,046.78	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user weathc1 overridding Payment Estimate Exception 7 on the current Payment Estimate.					
					2	May 17, 2021	SYSTEM	(\$2,046.78)						
										3	Jun 2, 2021	SYSTEM	\$2,046.78	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user weathc1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					3	Jun 2, 2021	SYSTEM	(\$2,046.78)						
				- Total				\$0.00						
			Material - To	otal				\$0.00						
			Other Item Adjustment	ACAD	9	Sep 1, 2021	weathc1	\$38.43	Job Number: J4S3328  Line Number: 0040, 1.75", BITUMINOUS PAVEMENT MIXTURE PG 64-22 (BP-1) 21-37 Line Number: 0040, 1.75", ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C) 21-37 Line Number: 0050, 1.75", ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C) 21-37 Line Number: 0120, 1.75", BITUMINOUS PAVEMENT MIXTURE PG 64-22 (BP-1) 20-48					
									Asphalt Cement Price Adjustment Breakdown					



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J4S3328	0120	FURN & PLACE BIT. MATL FOR	Other Item Adjustment						Grand Total \$30,639.29	
		CL B PARTIAL		ACAD - Tot	al			\$38.43		
			Other Item	Adjustment -	Total			\$38.43		
	0120 -	· Total						\$38.43		
	0140	CONSTRUCTION SIGNS	Overrun	Overrun	4	Jun 16, 2021	SYSTEM	\$736.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user weathc1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	
					4	Jun 16, 2021	SYSTEM	(\$736.00)		
				Overrun - T	otal			\$0.00		
			Overrun - T	otal				\$0.00		
	0140 -	· Total						\$0.00		
	0170	CHANNELIZER (TRIM LINE)	Overrun	Overrun	4	Jun 16, 2021	SYSTEM	\$2,625.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user weathc1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	
					4	Jun 16, 2021	SYSTEM	(\$2,625.00)		
				Overrun - T	otal			\$0.00		
			Overrun - T	verrun - Total						
	0170 -	· Total						\$0.00		
	0200	FLASHING ARROW PANEL		Overrun	Overrun	4	Jun 16, 2021	SYSTEM	\$700.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user weathc1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					4	Jun 16, 2021	SYSTEM	(\$700.00)		
				Overrun - T	otal			\$0.00		
			Overrun - T	otal				\$0.00		
	0200 -							\$0.00		
		PREF THERMO PVMT MARK, 24 IN WHIT	PVMT MARK, 24							
	0240	PVMT MARK, 24	Material		3	Jun 2, 2021	SYSTEM	\$3,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user weathc1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	
	0240	PVMT MARK, 24	Material		3		SYSTEM	\$3,340.00 (\$3,340.00)	Estimate Item Adjustment (0006) due to user weathc1 overridding Payment	
	0240	PVMT MARK, 24	Material			2021 Jun 2,			Estimate Item Adjustment (0006) due to user weathc1 overridding Payment	
	0240	PVMT MARK, 24	Material		3	Jun 2, 2021 Jun 16,	SYSTEM	(\$3,340.00)	Estimate Item Adjustment (0006) due to user weathc1 overridding Payment Estimate Exception 8 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment	
	0240	PVMT MARK, 24	Material		3	Jun 2, 2021 Jun 16, 2021 Jun 16,	SYSTEM SYSTEM	(\$3,340.00) \$8,110.00	Estimate Item Adjustment (0006) due to user weathc1 overridding Payment Estimate Exception 8 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment	
	0240	PVMT MARK, 24	Material		3 4	Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jun 30,	SYSTEM SYSTEM	(\$3,340.00) \$8,110.00 (\$8,110.00)	Estimate Item Adjustment (0006) due to user weathc1 overridding Payment Estimate Exception 8 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment	
	0240	PVMT MARK, 24	Material		3 4 4 5	2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jun 30, 2021 Jun 30,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$3,340.00) \$8,110.00 (\$8,110.00) \$8,110.00	Estimate Item Adjustment (0006) due to user weathc1 overridding Payment Estimate Exception 8 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment	
	0240	PVMT MARK, 24	Material		3 4 4 5 5	2021 Jun 2, 2021 Jun 16, 2021 Jun 30, 2021 Jun 30, 2021 Jun 30, 2021 Jun 30,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$3,340.00) \$8,110.00 (\$8,110.00) \$8,110.00	Estimate Item Adjustment (0006) due to user weathc1 overridding Payment Estimate Exception 8 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment	
	UZHU	PVMT MARK, 24	Material		3 4 4 5 5 6	2021 Jun 2, 2021 Jun 16, 2021 Jun 30, 2021 Jun 30, 2021 Jul 16, 2021 Jul 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$3,340.00) \$8,110.00 (\$8,110.00) \$8,110.00 (\$8,110.00) \$8,110.00	Estimate Item Adjustment (0006) due to user weathc1 overridding Payment Estimate Exception 8 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment	
	UZHU	PVMT MARK, 24	Material		3 4 4 5 5 6 6 6	2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jun 30, 2021 Jun 30, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$3,340.00) \$8,110.00 (\$8,110.00) \$8,110.00 (\$8,110.00) \$8,110.00	Estimate Item Adjustment (0006) due to user weathc1 overridding Payment Estimate Exception 8 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate.	
	UZHU	PVMT MARK, 24	Material	- Total	3 4 4 5 5 6 6 7 7	2021 Jun 2, 2021 Jun 16, 2021 Jun 30, 2021 Jun 30, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$3,340.00) \$8,110.00 (\$8,110.00) \$8,110.00 (\$8,110.00) \$8,110.00 (\$8,110.00)	Estimate Item Adjustment (0006) due to user weathc1 overridding Payment Estimate Exception 8 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate.	
	UZ4U	PVMT MARK, 24	Material - To		3 4 4 5 5 6 6 7 7	2021 Jun 2, 2021 Jun 16, 2021 Jun 30, 2021 Jun 30, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$3,340.00) \$8,110.00 (\$8,110.00) \$8,110.00 (\$8,110.00) \$8,110.00 (\$8,110.00)	Estimate Item Adjustment (0006) due to user weathc1 overridding Payment Estimate Exception 8 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate.	
	0240 -	PVMT MARK, 24 IN WHIT			3 4 4 5 5 6 6 7 7	2021 Jun 2, 2021 Jun 16, 2021 Jun 30, 2021 Jun 30, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$3,340.00) \$8,110.00 (\$8,110.00) \$8,110.00 (\$8,110.00) \$8,110.00 (\$8,110.00) \$8,110.00 \$8,110.00	Estimate Item Adjustment (0006) due to user weathc1 overridding Payment Estimate Exception 8 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate.	
		PVMT MARK, 24 IN WHIT			3 4 4 5 5 6 6 7 7	2021 Jun 2, 2021 Jun 16, 2021 Jun 30, 2021 Jun 30, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$3,340.00) \$8,110.00 (\$8,110.00) \$8,110.00 (\$8,110.00) \$8,110.00 (\$8,110.00) \$8,110.00 (\$8,110.00)	Estimate Item Adjustment (0006) due to user weathc1 overridding Payment Estimate Exception 8 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate.	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
J4S3328	0250	PREF THERMO PVMT MARK, 24 IN YELLOW	Material	,	5	Jun 30, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user weathc1 overridding Payment Estimate Exception 6 on the current Payment Estimate.		
					5	Jun 30, 2021	SYSTEM	(\$1,440.00)			
					6	Jul 16, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user weathc1 overridding Payment Estimate Exception 6 on the current Payment Estimate.		
					6	Jul 16, 2021	SYSTEM	(\$1,440.00)			
					7	Aug 2, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user weathc1 overridding Payment Estimate Exception 6 on the current Payment Estimate.		
					7	Aug 2, 2021	SYSTEM	(\$1,440.00)			
				- Total				\$0.00			
			Material - To	otal				\$0.00			
	0250 -	Total						\$0.00			
			Material		4	lum 40	OVOTEM		This adjustment offs to the eniminal posterior and the trial December		
	0260	PREF THERMO PVMT MARK, LT/RT ARROW	Material		4	Jun 16, 2021	SYSTEM	\$2,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user weathc1 overridding Payment Estimate Exception 7 on the current Payment Estimate.		
					4	Jun 16, 2021	SYSTEM	(\$2,800.00)			
				- Total				\$0.00			
			Material - To	otal				\$0.00			
	0260 -							\$0.00			
	0270	PREF THERMO PVMT MARK, 30" WHT MIDBL	Material		3	Jun 2, 2021	SYSTEM	\$12,420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user weathc1 overridding Payment Estimate Exception 9 on the current Payment Estimate.		
								3	Jun 2, 2021	SYSTEM	(\$12,420.00)
					4	Jun 16, 2021	SYSTEM	\$19,890.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user weathc1 overridding Payment Estimate Exception 8 on the current Payment Estimate.		
					4	Jun 16, 2021	SYSTEM	(\$19,890.00)			
				- Total				\$0.00			
			Material - To	otal				\$0.00			
	0270 -	Total						\$0.00			
	0280	12 IN. WHITE HIGH BUILD WATERBORNE	Material		4	Jun 16, 2021	SYSTEM	\$497.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user weathc1 overridding Payment Estimate Exception 9 on the current Payment Estimate.		
		PAINT			4	Jun 16, 2021	SYSTEM	(\$497.00)			
				- Total				\$0.00			
			Material - To	otal				\$0.00			
	0280 -	Total						\$0.00			
	0290	4 IN. WHITE WATERBORNE PAVEMENT	Material		4	Jun 16, 2021	SYSTEM	\$8,963.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user weathc1 overridding Payment Estimate Exception 11 on the current Payment Estimate.		
		MARKING			4	Jun 16, 2021	SYSTEM	(\$8,963.46)			
				- Total				\$0.00			
			Material - To	otal				\$0.00			
			Material - To Other Item Adjustment	Other Item		8	Aug 16, 2021	weathc1	\$409.61	Adjustment based on the retro-reflectivity adjustment spreadsheet that was calculated for this line item.	
				REFL - Tota	ı			\$409.61			
			Other Item /	Adjustment -	Total			\$409.61			
		_	Other Item A	Overrun		Jun 16, 2021	SYSTEM	\$9.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 18 on the current Payment Estimate. Material Insufficiency Quantity 49797.000; Overrun Quantity Balance 50.00.		



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3328	0290	4 IN. WHITE WATERBORNE PAVEMENT MARKING	Overrun	Overrun	4	Jun 16, 2021	SYSTEM	(\$9.00)	
					5	Jun 30, 2021	SYSTEM	(\$9.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					5	Jun 30, 2021	SYSTEM	\$9.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user weathc1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					6	Jul 16, 2021	SYSTEM	(\$9.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					6	Jul 16, 2021	SYSTEM	\$9.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user weathc1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					7	Aug 2, 2021	SYSTEM	(\$9.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					7	Aug 2, 2021	SYSTEM	\$9.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user weathc1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					8	Aug 16, 2021	SYSTEM	(\$9.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					8	Aug 16, 2021	SYSTEM	\$9.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				Overrun - T	otal			\$0.00	
			Overrun - T	Overrun - Total					
	0290 -	Total						\$409.61	
	0300	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	Material		4	Jun 16, 2021	SYSTEM	\$8,132.76	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user weathc1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					4	Jun 16, 2021	SYSTEM	(\$8,132.76)	
				- Total				\$0.00	
			Material - Total					\$0.00	
			Other Item Adjustment	REFL	8	Aug 16, 2021	weathc1	\$275.46	Adjustment based on the retro-reflectivity adjustment spreadsheet that was calculated for this line item.
				REFL - Tota	ıl			\$275.46	
			Other Item	Adjustment -	Total			\$275.46	
	0300 -	Total						\$275.46	
	0330	MGS GUARDRAIL, 8 FT. POSTS, 6 FT. - 3 IN	Material		3	Jun 2, 2021	SYSTEM	\$22,575.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user weathc1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Jun 2, 2021	SYSTEM	(\$22,575.00)	
					4	Jun 16, 2021	SYSTEM	\$22,575.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user weathc1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Jun 16, 2021	SYSTEM	(\$22,575.00)	
					5	Jun 30, 2021	SYSTEM	\$22,575.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user weathc1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	Jun 30, 2021	SYSTEM	(\$22,575.00)	
					6	Jul 16, 2021	SYSTEM	\$22,575.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user weathc1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Jul 16, 2021	SYSTEM	(\$22,575.00)	
					7	Aug 2, 2021	SYSTEM	\$22,575.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user weathc1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Aug 2, 2021	SYSTEM	(\$22,575.00)	
					8	Aug 16, 2021	SYSTEM	\$22,575.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment



Material   Material	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
FT POSTS, 6FT   -3 IN	J4S3328	0330		Material						Estimate Exception 1 on the current Payment Estimate.
Substitution   Subs			FT. POSTS, 6 FT.			8		SYSTEM	(\$22,575.00)	
Color					- Total				\$0.00	
Material   Total				Material - To	otal				\$0.00	
SCOTION_TS   SCO		0330 -	Total						\$0.00	
South   South   State   Stat		0340	ANCHOR SECTION, 7.5	Material		3		SYSTEM	\$7,480.00	Estimate Item Adjustment (0009) due to user weathc1 overridding Payment
Material - Total   S0.00						3		SYSTEM	(\$7,480.00)	
10340 - Total   2021					- Total				\$0.00	
1				Material - Total					\$0.00	
TRAILER   MOUNTED ATTEN (TMA)		0340 -	Total						\$0.00	
3		0360	TRAILER MOUNTED	Material		3		SYSTEM	\$1,000.00	Estimate Item Adjustment (0002) due to user weathc1 overridding Payment
						3		SYSTEM	(\$1,000.00)	
0360 - Total   0370   CABLE, LOOP   DETECTOR, IN DUCT   DUCT   DUCT   0201   16   2021   2021   2021   2021   2021   2021   17 libis adjustment offsets the original system-generated Material Payment Estimate Exception 7 on the current Payment Estimate Exception 8 on 10   10   10   10   10   10   10   10					- Total				\$0.00	
CABLE, LOOP   DETECTOR, IN   DUCT				Material - To	Material - Total				\$0.00	
DETECTOR, IN DUCT		0360 -	Total						\$0.00	
2021   7   2021   7		0370	DETECTOR, IN	Material		6		SYSTEM	\$9,114.00	Estimate Item Adjustment (0007) due to user weathc1 overridding Payment
2021   Estimate Item Adjustment (0007) due to user weathor overridding Payment Estimate Exception 7 on the current Payment Estimate.   So. 00					7	6		SYSTEM	(\$9,114.00)	
2021   \$0.00						7		SYSTEM	\$9,114.00	Estimate Item Adjustment (0007) due to user weathc1 overridding Payment
Material - Total   \$0.00						7	Aug 2, 2021	SYSTEM	(\$9,114.00)	
Some					- Total				\$0.00	
DOWEL BAR (FURNISH AND INSTALL WITH BASK   Material - Total   10   Sep 15, 2021   SYSTEM   \$252.00   This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.   10   Sep 15, 2021   SYSTEM   (\$252.00)				Material - Total					\$0.00	
CFURNISH AND INSTALL WITH BASK		0370 -	0370 - Total							
10   Sep 15, 2021   SYSTEM (\$252.00)		5002	(FURNISH AND INSTALL WITH	Material		10		SYSTEM	\$252.00	Estimate Item Adjustment (0002) due to user weathc1 overridding Payment
Material - Total   \$0.00						10		SYSTEM	(\$252.00)	
Solid   Soli					- Total				\$0.00	
TIE BAR (DRILL, FURN & INSTAL) (TYPE L Total 10 Sep 15, 2021 SYSTEM \$105.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  10 Sep 15, 2021 SYSTEM (\$105.00)  - Total \$0.00  5003 - Total \$0.00  5003 - Total \$0.00				Material - Total					\$0.00	
FURN & INSTAL) (TYPE L 10 Sep 15, 2021 Estimate Item Adjustment (0003) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  - Total \$0.00  Material - Total \$0.00  5003 - Total \$0.00  J4\$3328 - Total \$31,324.36		5002 -	02 - Total							
2021   \$0.00		5003	FURN & INSTAL)	Material		10		SYSTEM	\$105.00	Estimate Item Adjustment (0003) due to user weathc1 overridding Payment
Material - Total \$0.00  5003 - Total \$0.00  J4\$3328 - Total \$31,324.36						10		SYSTEM	(\$105.00)	
5003 - Total       \$0.00         J4S3328 - Total       \$31,324.36					- Total				\$0.00	
J4S3328 - Total \$31,324.36				Material - Total					\$0.00	
		5003 -	Total						\$0.00	
Overall - Total \$31,324.36	J4S3328 -	Total							\$31,324.36	
	Overall -	Total							\$31,324.36	