

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: January 3, 2022

Progress Estimate Number 13	Contract ID Prime Contractor	201120-D02 Magruder Paving, LLC		Original Contract Amount Net Change Order Amount Current Contract Amount	(\$4,161.33)
Approval Date					Bv User

By User		Approval Date
snells1	Generated and Approved (and should be considered Draft) at the Project Office Level by	January 3, 2022
grahac1	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	January 4, 2022
ramses1	Reviewed and Approved at the Central Office Controllers Office Level by	January 5, 2022

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
November 1, 2021	November 1, 2021	October 25, 2021	100.00%

Contract Informational Dates Milestones

Date Description	Original Completion Date	Current Completion Date
Acceptance Date		
Awarded Date	December 2, 2020	December 2, 2020
Letting Date	November 20, 2020	November 20, 2020
Notice to Proceed Date	February 1, 2021	February 1, 2021
Work Began Date		

Date Description	Original Completion Date	Current Completion Date	Days Remaining on Milestone	Diary Charge Days
JSP- B Completion Date- Road User Costs	November 1, 2021	November 1, 2021	Milestone Complete	
Toda Oser Ooses	2021	2021		

Contract Total Pay For Estimate No. 13										
		This Estimate	Previous	To Date						
201120-D02										
	Total Posted Items Pay	\$51,100.00	\$3,076,357.94	\$3,127,457.94						
	Gross Item Adjustments	\$8,745.32	\$282,193.33	\$290,938.65						
	Incentive	\$0.00	\$73,997.59	\$73,997.59						
	Disincentive	\$0.00	\$0.00	\$0.00						
	Liquidated Damage	\$0.00	\$0.00	\$0.00						
	Other Contract Adjustments	\$0.00	\$136,830.58	\$136,830.58						
	•		\$3,569,379.44	\$3,629,224.76						
Contract Total Payable	e This Estimate:	\$59,845.32								

Items Paid This Estimate Period

Project Number Line Number Item Code		e Item Description		Unit Price	Current Installed Qty	Current Installed Amount			
J5P3379	0020	4019901	MISC.INFRARED SCANNING	LS	\$20,000.000	1	\$20,000.00		
	0030	4019901	MISC.INTELLIGENT COMPACTION	LS	\$31,100.000	1	\$31,100.00		
Project J5P3379	Project J5P3379 - Total								
Overall - Total	otal								

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

		ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5P3379	0020	MISC.	Other Item Adjustment	Other	This adjustment is for the Infrared Scanning on the project. Veta files and Summary Sheet are on file on e-projects. snells1			\$6,111.00
	0030	MISC.	Other Item Adjustment	Intelligent Compaction	Veta projects and summary sheet on file in e- projects. snells1			\$2,634.32
	0290	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Material			-1,606.5	\$59.50	(\$95,586.75)

Revision 4/1/2020 Page 1 of 17



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: January 3, 2022

Progress Estimate Number
13

Contract ID 201120-D02 Pay Period Start December 16, 2021 Original Contract Amount \$3,131,619.27
Prime Contractor Magruder Paving, LLC Pay Period End January 1, 2022 Net Change Order Amount Current Contract Amount \$3,131,619.27

Net Change Order Amount Current Contract Amount \$3,127,457.94

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5P3379	0290	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user snells1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	1,606.5	\$59.50	\$95,586.75
	0300	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Material			-15,535.4	\$61.51	(\$955,582.45)
	0300	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user snells1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	15,535.4	\$61.51	\$955,582.45
	5002	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material			-12	\$446.25	(\$5,355.00)
	5002	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user snells1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	12	\$446.25	\$5,355.00
Total								\$8,745.32

Revision 4/1/2020 Page 2 of 17



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Information			
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work		
J5P3379 FAS S402(20) Resurface 5 LACLEDE from 0.8 miles south of the Camden County line to 0.2 miles north of Lebanon									
Totale by	Job Numbe	re							
Totals by c	JOD HUITIDE								
•	JOB ITAINBE				This Estimate	Previous	To Date		
•		d Item Pay			This Estimate \$51,100.00	Previous \$3,076,357.94	To Date \$3,127,457.94		
J5P3379	Poste		ents						
•	Poste	d Item Pay		s Item Pay	\$51,100.00	\$3,076,357.94	\$3,127,457.94		
•	Poste	d Item Pay Item Adjustm		s Item Pay	\$51,100.00 \$8,745.32	\$3,076,357.94 \$282,193.33	\$3,127,457.94 \$290,938.65		
•	Poste Gross	d Item Pay Item Adjustm		s Item Pay	\$51,100.00 \$8,745.32 \$59,845.32	\$3,076,357.94 \$282,193.33 \$3,358,551.27	\$3,127,457.94 \$290,938.65 \$3,418,396.59		
•	Poste Gross Incent Disino	d Item Pay s Item Adjustm	Gross	s Item Pay	\$51,100.00 \$8,745.32 \$59,845.32 \$0.00	\$3,076,357.94 \$282,193.33 \$3,358,551.27 \$73,997.59	\$3,127,457.94 \$290,938.65 \$3,418,396.59 \$73,997.59		

Revision 4/1/2020 Page 3 of 17



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J5P3379, Item 4011209, Project Item Line Number 0290, Material Set 401120996, Material 0401BPPMBP1 - Plant Mix for Bit Pavement BP-1, Acceptance Action Generic AspLow is insufficient.	This exception does not show up on the Sampling Checklist. I have spoken with District Materials and they see no further testing needing to be submitted either. Snells1	snells1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3379, Item 4030103, Project Item Line Number 0300, Material Set 403010396, Material 0403SP125CLG - Superpave 12.5 mm, Des C 80 Gyros, Acceptance Action Generic AspHigh is insufficient.	This exception does not show up on the Sampling Checklist. I have spoken with District Materials and they see no further testing needing to be submitted either. Snells1	snells1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3379, Item 6061074, Project Item Line Number 0370, Material Set 6061074, Material 1065DE - Delineators, Acceptance Action Generic 1065DE is insufficient.	This exception does not show up on the Sampling Checklist. I have spoken with District Materials and they see no further testing needing to be submitted either. Snells1	snells1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3379, Item 6131010, Project Item Line Number 5002, Material Set 613101096, Material 1015EASS1 - Emulsified Asphalt SS-1, Acceptance Action Generic AspEmulsion is insufficient.	The Materials report needs to be finished by the Project Office. Snells1	snells1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3379, Item 6131010, Project Item Line Number 5002, Material Set 613101096, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	The Materials report needs to be finished by the Project Office. Snells1	snells1	Overridden

Revision 4/1/2020 Page 4 of 17



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
201120-D02	J5P3379	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$1,000.00	\$1,000.00
		0001	0015	2153000	SHAPING SLOPES, CLASS III	1.00	0.00	1.00	100F	1.00	\$1,200.00	\$1,200.00
		0001	0020	4019901	MISC.INFRARED SCANNING	1.00	0.00	1.00	LS	1.00	\$20,000.00	\$20,000.00
		0001	0030	4019901	MISC.INTELLIGENT COMPACTION	1.00	0.00	1.00	LS	1.00	\$31,100.00	\$31,100.00
		0001	0040	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$1,000.00	\$2,000.00
		0001	0050	6161005	CONSTRUCTION SIGNS	1,743.00	149.00	1,892.00	SQFT	1,892.00	\$8.00	\$15,136.00
		0001	0060	6161025	CHANNELIZER (TRIM LINE)	1,165.00	0.00	1,165.00	EA	1,165.00	\$20.00	\$23,300.00
		0001	0070	6161033	DIRECTIONAL INDICATOR BARRICADE	60.00	0.00	60.00	EA	60.00	\$75.00	\$4,500.00
		0001	0800	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	2.00	\$950.00	\$1,900.00
		0001	0090	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	6.00	-1.00	5.00	EA	5.00	\$2,200.00	\$11,000.00
		0001	0100	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$32,740.00	\$32,740.00
		0001	0110	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	2,632.00	188.00	2,820.00	LF	2,820.00	\$10.00	\$28,200.00
		0001	0120	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	71.00	5.00	76.00	EA	76.00	\$235.00	\$17,860.00
		0001	0130	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	21,418.00	0.00	21,418.00	LF	21,418.00	\$0.18	\$3,855.24
		0001	0140	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	136,493.00	0.00	136,493.00	LF	136,493.00	\$0.10	\$13,649.30
		0001	0150	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	101,348.00	102,304.00	203,652.00	LF	203,652.00	\$0.30	\$61,095.60
		0001	0153	6209901	MISC.Temporary Pavement Marking Paint - Segment 1	1.00	-1.00	0.00	LS	0.00	\$0.01	\$0.00
		0001	0157	6209901	MISC.Temporary Pavement Marking Paint - Segment 2	1.00	-1.00	0.00	LS	0.00	\$0.01	\$0.00
		0001	0170	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	7,545.00	0.00	7,545.00	SQYD	7,545.00	\$2.62	\$19,767.90
		0001	0180	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	985.70	0.00	985.70	STA	985.70	\$17.49	\$17,239.89
		0001	0190	6261001	BITUMINOUS CENTERLINE RUMBLE STRIP	1,051.80	0.00	1,051.80	STA	1,051.80	\$17.37	\$18,269.77
		0003	0270	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	773.40	1,676.80	2,450.20	TONS	2,450.20	\$25.20	\$61,745.04
		0003	0280	3105002	GRAVEL (A) OR CRUSHED STONE (B)	30.00	0.00	30.00	TONS	30.00	\$25.20	\$756.00
		0003	0290	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	9,917.70	-311.20	9,606.50	TONS	9,606.50	\$59.50	\$571,586.75
		0003	0300	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	29,906.30	1,169.10	31,075.40	TONS	31,075.40	\$61.51	\$1,911,447.85
		0003	0310	4039905	MISC.SYSTEM B GEOSYNTHETIC INTERLAYER (COMPOSITE PAVING FABRIC/REINFORCING GRID)	52,969.00	-39,947.00	13,022.00	SQYD	13,022.00	\$2.88	\$37,503.36
		0003	0320	4071005	TACK COAT	7,099.00	-387.00	6,712.00	GAL	6,712.00	\$2.00	\$13,424.00
		0003	0330	4079912	MISC.MODIFIED BONDED ASPHALTIC CONCRETE PAVEMENT	54,838.00	-19,143.00	35,695.00	GAL	35,695.00	\$1.00	\$35,695.00
		0003	0335	4138000	PCCP CRACK FILLING	119,180.00	-3,371.00	115,809.00	LF	115,809.00	\$1.10	\$127,389.90
		0003	0350	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	6,267.00	-505.00	5,762.00	SQYD	5,762.00	\$5.07	\$29,213.34
		0010	0360	6061060	MGS GUARDRAIL	50.00	0.00	50.00	LF	50.00	\$40.00	\$2,000.00
		0010	0370	6061074	MGS HEIGHT AND BLOCK TRANSITION	1.00	0.00	1.00	EA	1.00	\$1,000.00	\$1,000.00
		0010	0380	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	1.00	0.00	1.00	EA	1.00	\$3,200.00	\$3,200.00
		0001	5001	6207001	PAVEMENT MARKING REMOVAL	0.00	3,200.00	3,200.00	LF	3,200.00	\$1.04	\$3,328.00
		0001	5002	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	0.00	12.00	12.00	SQYD	12.00	\$446.25	\$5,355.00
					ate as of Report Generated Date							\$3,127,457.94
201120-D02 Ove	erall - Total	Value Post	ted to Dat	te as of Repo	ort Generated Date							\$3,127,457.94

Revision 4/1/2020 Page 5 of 17



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

$\underline{\textbf{The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.}$

Project: J5P3379

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0020	4019901	MISC.	12/30/21	1/3/22	1.00	LS	Rte. 5	236.012		247.580		
0030	4019901	MISC.	12/30/21	1/3/22	1.00	LS	Rte. 5	236.012		247.580		

0030	4019901 M	ISC.	12/3	0/21 1/3/22	1	1.00 LS Rte.	5		236.012	247.580				
	rmation bel	DWR Date	etails for Construction Signs (Total Quantity Posted For DWR Date		ole). Sign Info	rmation	Station	Log Mile	Location	Number of Items	SF Fach Sign	Special Sign	SF Each Special Sign	Total SF to Pos
J5P3379		June 16, 2021	372	WO20-1	48x48 1		_ 200011	0,880	SB Old Rte. 5 South end - right shoulder	1.00	16	zpzz.ai oigii	Spoola Sign	16
				WO20-1	48x48 1			0.137	SB Olathe Rd. right shoulder	1.00	16			16
					96x48	32.00 POINT OF		237.580	SB Route 5 right shoulder	1.00	32			32
				WO20-6a	48x48 1	6.00 T LANE CLOSED		236.156	SB Route 5 right shoulder	1.00	16			16
				WO8-11	48x48 1	6.00 UNEVEN		236.128	SB Route 5 right shoulder	1.00	16			10
				WO8-12	48x48 1	6.00 NO CENTER		236.100	SB Route 5 right shoulder	1.00	16			1
				WO6-3 4 TRAFFIC (S	48x48 16 SYMBOL)	6.00 TWO WAY		236.072	SB Route 5 right shoulder	1.00	16			10
				CONST-8 ZONE NO F	48x36 PHONE Z	12.00 WORK ONE		235.917	SB Route 5 right shoulder	1.00	12			1:
				GO20-1 6 NEXT XX M		0.00 ROAD WORK		235.822	SB Route 5 right shoulder	1.00	10			1
				GO20-2 4 WORK	48x24 8	.00 END ROAD		235.812	NB Rte. 5 right shoulder (Used SB LM)	1.00	8			
				CONST-7-4 WORK ZON	18 48x24 NE	8.00 RATE OUR		235.727	SB Route 5 right shoulder	1.00	8			
				WO20-1 A	48x48 10 DGE/RAM	6.00 IP WORK AHEAD		0.219	WB Jasmine Rd. right shoulder	1.00	16			1
				WO20-1 A		6.00 IP WORK AHEAD		0.886	NB Old Rte. 5 North end - right shoulder	1.00	16			1
				WO20-1 ROAD/BRID	48x48 10 DGE/RAM	6.00 IP WORK AHEAD		1.257	NB Olathe right shoulder	1.00	16			1
					DGE/RAM	IP WORK AHEAD		1.505	NB Olathe Dr. right shoulder	1.00	16			1
				WO20-1 ROAD/BRID	48x48 10 DGE/RAM	6.00 IP WORK AHEAD		1.733	WB Knoll Rd. right shoulder	1.00	16			1
					DGE/RAM	IP WORK AHEAD		1.873	WB Livingston right shoulder	1.00	16			1
				WORK ZON	NE	8.00 RATE OUR			NB Route 5 right shoulder		8			
				NEXT XX M	MILES	0.00 ROAD WORK			NB Route 5 right shoulder	1.00	10			1
				ZONE NO F	PHONE Z				NB Route 5 right shoulder	1.00	12			1
				PRESENCE	E	32.00 POINT OF			NB Route 5 right shoulder	1.00	32			3:
					DGE/RAM	IP WORK AHEAD		11.643	EB Rte. E - right shoulder	1.00	16			11
					DGE/RAM	IP WORK AHEAD		2.630	SB Kansas - right shoulder	1.00	16			1
					DGE/RAM	IP WORK AHEAD		2.913	SB Route VV right shoulder	1.00	16			1
		June 28, 2021	152		DGE/RAM	IP WORK AHEAD		1.486	Hamlock Rd.	1.00	16			1
					DGE/RAM	IP WORK AHEAD		0.889	Houston Rd.	1.00	16			1
					DGE/RAM	IP WORK AHEAD		0.236	N, Oakwood	1.00	16			1
					DGE/RAM	IP WORK AHEAD		0.233	South Oakwood	1.00	16			1
					DGE/RAM	IP WORK AHEAD		4,231	Orchard Rd,	1.00	16			1
				WORK				247.725	SB Rte. 5 just before Greenfield Rd. EB Julie Rd.	1.00	8			
				WO20-1 A ROAD/BRID	DGE/RAM	IP WORK AHEAD		2.952		1.00	16			1
				ROAD/BRID	DGE/RAM	IP WORK AHEAD		2.902	EB Independence Rd. SB Rte. BB	1.00	16			16
					DGE/RAM	IP WORK AHEAD		0.055	Jonquil Rd.	1.00	16			1
		August 31, 2021	1028	ROAD/BRID	DGE/RAM	IP WORK AHEAD 8.00 RATE OUR			Northbound Rte. 5		8			
		August 31, 2021	1026	WORK ZON	NE	18.00 RATE OUR			Northbound Rte. 5	1.00	18			1:
				WORK ZON	ΝE				Northbound Rte. 5	1.00	16			1
						16.00 TWO-WAY			Northbound Rte. 5	1.00	16			1
				LINE		6.00 UNEVEN			Northbound Rte. 5	1.00	16			1
				LANES WO20-6a					Northbound Rte. 5	1.00	16			1
				RIGHT/CEN	NTER/LEF	T LANE CLOSED			Northbound Rte. 5	1.00	16			1
				TRAFFIC		6.00 UNEVEN			Northbound Rte. 5	1.00	16			1
				LANES WO20-6a	48x48 1	6.00			Northbound Rte. 5	1.00	16			1
				RIGHT/CEN WO6-3(48)	NTER/LEF	T LANE CLOSED 16.00 TWO-WAY			Northbound Rte. 5	1.00	16			1
				TRAFFIC WO8-12		6.00 NO CENTER			Northbound Rte. 5	1.00	16			10
				LINE	. 5010	JENIER		101.024						

Revision 4/1/2020 Page 6 of 17



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line are details for Construction Signs (if applicable)

The info	rmation bel	ow this line are d	etails for Construction Signs (if applicab	ile).					1		1	
	Line Number		Total Quantity Posted For DWR Date		Sign Information	Statio	Log Mile	Location Neethberral Dtv 5			Special Sign	SF Each Special Sign	
J5P3379	0050	August 31, 2021	1028	LANES	48x48 16.00 UNEVEN			Northbound Rte. 5	1.00	16			16
				RIGHT/CEN	48x48 16.00 NTER/LEFT LANE CLOS		107.568	Northbound Rte. 5	1.00	16			16
				TRAFFIC	48x48 16.00 TWO-W	ΑY	108.557	Northbound Rte. 5	1.00	16			16
				LANES	48x48 16.00 UNEVEN		108.581	Northbound Rte. 5	1.00	16			16
				RIGHT/CEN	48x48 16.00 NTER/LEFT LANE CLOS		108.611	Northbound Rte. 5	1.00	16			16
				WO6-3(48) TRAFFIC	48x48 16.00 TWO-W	ΑΥ	109.665	Northbound Rte. 5	1.00	16			16
				WO8-12 LINE	48x48 16.00 NO CENT	ER	109.690	Northbound Rte. 5	1.00	16			16
				WO8-11 -	48x48 16.00 UNEVEN		109.710	Northbound Rte. 5	1.00	16			16
				WO20-6a RIGHT/CEN	48x48 16.00 NTER/LEFT LANE CLOS	ED	109.737	Northbound Rte. 5	1.00	16			16
				WO6-3(48) TRAFFIC	48x48 16.00 TWO-W	ΑY	110.778	Northbound Rte. 5	1.00	16			16
				WO8-11 -	48x48 16.00 UNEVEN		110.799	Northbound Rte. 5	1.00	16			16
				WO20-6a RIGHT/CEN	48x48 16.00 NTER/LEFT LANE CLOS	ED	110.820	Northbound Rte. 5	1.00	16			16
				WO6-3(48) TRAFFIC	48x48 16.00 TWO-W	ΑY	112.570	Northbound Rte. 5	1.00	16			16
				WO8-11	48x48 16.00 UNEVEN		112.604	Northbound Rte. 5	1.00	16			16
					48x48 16.00 NTER/LEFT LANE CLOS	ED	112.621	Northbound Rte. 5	1.00	16			16
					48x48 16.00 TWO-W		113.391	Northbound Rte. 5	1.00	16			16
					48x48 16.00 NO CENT	ER	113.405	Northbound Rte. 5	1.00	16			16
					48x48 16.00 UNEVEN		113.421	Northbound Rte. 5	1.00	16			16
				WO20-6a	48x48 16.00 NTER/LEFT LANE CLOS	ED	113.440	Northbound Rte. 5	1.00	16			16
					48x48 16.00 TWO-W		114.699	Northbound Rte. 5	1.00	16			16
					48x48 16.00 UNEVEN		114.719	Northbound Rte. 5	1.00	16			16
				WO20-6a	48x48 16.00		114.739	Northbound Rte. 5	1.00	16			16
				CONST-7-4	NTER/LEFT LANE CLOS 18_48x24 8.00 RATE O		235.727	Southbound Rte. 5 lt.	-1.00	8			-8
				WORK ZON	2 72x36 18.00 RATE 0	UR	235.727	Southbound Rte. 5 lt.	1.00	18			18
				WORK ZON	NE 48x48 16.00 NO CENT	ER	237.710	Southbound Rte. 5	1.00	16			16
					48x48 16.00 UNEVEN		237.737	Southbound Rte. 5	1.00	16			16
				WO20-6a	48x48 16.00		237.776	Southbound Rte. 5	1.00	16			16
				RIGHT/CEN	VTER/LEFT LANE CLOS 48x48 16.00 TWO-W		238.758	Southbound Rte. 5	1.00	16			16
				TRAFFIC	48x48 16.00 UNEVEN		238.785		1.00	16			16
				LANES	48x48 16.00		238.808	Southbound Rte. 5	1.00	16			16
				RIGHT/CEN	NTER/LEFT LANE CLOS 48x48 16.00 TWO-W		239.678	Southbound Rte. 5	1.00	16			16
				TRAFFIC	48x48 16.00 NO CENT		239.698		1.00	16			16
				LINE	48x48 16.00 UNEVEN			Southbound Rte. 5	1.00	16			16
				LANES									
				RIGHT/CEN	48x48 16.00 NTER/LEFT LANE CLOS			Southbound Rte. 5	1.00	16			16
				LINE	48x48 16.00 NO CENT	EK		Southbound Rte. 5	1.00	16			16
				LANES	48x48 16.00 UNEVEN			Southbound Rte. 5	1.00	16			16
				TRAFFIC	48x48 16.00 TWO-W			Southbound Rte. 5	1.00	16			16
				TRAFFIC	48x48 16.00 TWO-W			Southbound Rte. 5	1.00	16			16
				LINE	48x48 16.00 NO CENT	ER		Southbound Rte. 5	1.00	16			16
				LANES	48x48 16.00 UNEVEN			Southbound Rte. 5	1.00	16			16
				RIGHT/CEN	48x48 16.00 NTER/LEFT LANE CLOS			Southbound Rte. 5	1.00	16			16
				LINE	48x48 16.00 NO CENT	ER		Southbound Rte. 5	1.00	16			16
				WO8-11 -	48x48 16.00 UNEVEN		243.162	Southbound Rte. 5	1.00	16			16
				WO6-3(48) TRAFFIC	48x48 16.00 TWO-W	ΛΥ	243.198	Southbound Rte. 5	1.00	16			16
				WO6-3(48) TRAFFIC	48x48 16.00 TWO-W	ΑΥ	244.353	Southbound Rte. 5	1.00	16			16
				WO8-12 LINE	48x48 16.00 NO CENT	ER	244.375	Southbound Rte. 5	1.00	16			16
				WO8-11 -	48x48 16.00 UNEVEN		244.397	Southbound Rte. 5	1.00	16			16
				WO20-6a	48x48 16.00 NTER/LEFT LANE CLOS	ED	244.418	Southbound Rte. 5	1.00	16			16
				WO6-3(48) TRAFFIC	48x48 16.00 TWO-W	ΛΥ	245.515	Southbound Rte. 5	1.00	16			16

Revision 4/1/2020 Page 7 of 17



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

ect Line Numb	er DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Pos		
379 0050	August 31, 2021	1028	WO8-11 48x48 16.00 UNEVE LANES	N	245.534	Southbound Rte. 5	1.00	16			16		
			WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLO	SED	245.553	Southbound Rte. 5	1.00	16			1		
			WO6-3(48) 48x48 16.00 TWO- TRAFFIC	VAY	246.464	Southbound Rte. 5	1.00	16			1		
			WO8-12 48x48 16.00 NO CEN LINE	ITER	246.490	Southbound Rte. 5	1.00	16			1		
			WO8-11 48x48 16.00 UNEVE LANES	١	246.515	Southbound Rte. 5	1.00	16			1		
			WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLO	SED	246.539	Southbound Rte. 5	1.00	16			1		
			WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AH	EAD		Hazel Road	1.00	16			1		
	September 15, 2021	274	WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AH	EAD	Flagger		1.00	16			1		
			GO20-4 36x18 4.50 PILOT C FOLLOW ME	AR	Flagger		1.00	4.5			4		
			G020-5aP 36x24 6.00 WORK (PLAQUE)	ONE	Flagger		2.00	6			1		
			GO20-4a 42x30 8.75 PLEASE FOR PILOT CAR	WAIT	Flagger		2.00	8.75			17		
			R2-1 36x48 12.00 SPEED LI XX	MIT	Flagger		2.00	12			2		
			WO20-7a 48x48 16.00 FLAGG (SYMBOL)	ER	Flagger		2.00	16			3		
			WO3-4(48) 48x48 16.00 BE PREPARED TO STOP		Flagger		2.00	16			3		
					WO20-4 48x48 16.00 ONE LA ROAD AHEAD	NE	Flagger		2.00	16			3
			WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLO AHEAD	OSED	Flagger		2.00	16			:		
			WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLO	SED	Flagger		2.00	16			:		
			R4-7a 36x48 12.00 KEEP RIG (HORIZONTAL ARROW)	SHT	Flagger		2.00	12			2		

Revision 4/1/2020 Page 8 of 17



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3379	0020	MISC.	Other Item Adjustment	OTHR	13	Jan 3, 2022	snells1	\$6,111.00	This adjustment is for the Infrared Scanning on the project. Veta files and Summary Sheet are on file on e-projects.
				OTHR - Tota	al			\$6,111.00	SHOIS I
			Other Item	Adjustment -				\$6,111.00	
	0020 -	- Total						\$6,111.00	
	0030	MISC.	Other Item	INTC	13	Jan 3,	snells1	\$2,634.32	Veta projects and summary sheet on file in e-projects.
			Adjustment			2022			snells1
				INTC - Total				\$2,634.32	
	0000		Other Item	Adjustment -	Total			\$2,634.32	
		- Total			_		0)/0==1/	\$2,634.32	
	0050	CONSTRUCTION SIGNS	Overrun	Overrun	/	Sep 16, 2021	SYSTEM	\$664.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user snells1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					7	Sep 16, 2021	SYSTEM	(\$664.00)	
					8	Oct 4, 2021	SYSTEM	(\$664.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					8	Oct 4, 2021	SYSTEM	\$664.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user snells1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					9	Oct 18, 2021	SYSTEM	(\$664.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					9	Oct 18, 2021	SYSTEM	\$664.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user snells1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
		Overrun - Total						\$0.00	
			Overrun - T	otal				\$0.00	
	0050 -	- Total						\$0.00	
	0130	4 IN. YELLOW	Material		7	Sep 16,	SYSTEM	\$3,855.24	This adjustment offsets the original system-generated Material Payment
		HIGH BUILD WATERBORNE				2021			Estimate Item Adjustment (0008) due to user snells1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					7	2021 Sep 16, 2021	SYSTEM	(\$3,855.24)	
		WATERBORNE		- Total	7	Sep 16,	SYSTEM	(\$3,855.24) \$0.00	
		WATERBORNE	Material - To		7	Sep 16,	SYSTEM	, , ,	
		WATERBORNE	Material - To Other Item Adjustment		7	Sep 16,	SYSTEM snells1	\$0.00	Estimate Exception 10 on the current Payment Estimate. Adjustment calculated from Retroreflectivity testing performed by 3rd. party. Results and calculations can be found on e- projects.
		WATERBORNE	Other Item	otal REFL	12	Sep 16, 2021		\$0.00 \$0.00 \$122.19	Estimate Exception 10 on the current Payment Estimate. Adjustment calculated from Retroreflectivity testing performed by 3rd. party.
		WATERBORNE	Other Item Adjustment	otal REFL REFL - Tota	12	Sep 16, 2021		\$0.00 \$0.00 \$122.19	Estimate Exception 10 on the current Payment Estimate. Adjustment calculated from Retroreflectivity testing performed by 3rd. party. Results and calculations can be found on e- projects.
		WATERBORNE PAINT	Other Item Adjustment	otal REFL	12	Sep 16, 2021		\$0.00 \$0.00 \$122.19 \$122.19	Estimate Exception 10 on the current Payment Estimate. Adjustment calculated from Retroreflectivity testing performed by 3rd. party. Results and calculations can be found on e- projects.
		WATERBORNE PAINT	Other Item Adjustment	otal REFL REFL - Tota	12 Il Total	Sep 16, 2021 Dec 16, 2021	snells1	\$0.00 \$0.00 \$122.19 \$122.19 \$122.19 \$122.19	Estimate Exception 10 on the current Payment Estimate. Adjustment calculated from Retroreflectivity testing performed by 3rd. party. Results and calculations can be found on e- projects. snells1
	0130	WATERBORNE PAINT - Total 6 IN. WHITE HIGH BUILD WATERBORNE	Other Item Adjustment	otal REFL REFL - Tota	12	Sep 16, 2021		\$0.00 \$0.00 \$122.19 \$122.19	Estimate Exception 10 on the current Payment Estimate. Adjustment calculated from Retroreflectivity testing performed by 3rd. party. Results and calculations can be found on e- projects.
		WATERBORNE PAINT - Total 6 IN. WHITE HIGH BUILD	Other Item Adjustment	otal REFL REFL - Tota	12 Il Total	Sep 16, 2021 Dec 16, 2021 Sep 16,	snells1	\$0.00 \$0.00 \$122.19 \$122.19 \$122.19 \$122.19	Estimate Exception 10 on the current Payment Estimate. Adjustment calculated from Retroreflectivity testing performed by 3rd. party. Results and calculations can be found on e- projects. snells1 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user snells1 overridding Payment
		WATERBORNE PAINT - Total 6 IN. WHITE HIGH BUILD WATERBORNE	Other Item Adjustment	otal REFL REFL - Tota	12 Il Total	Sep 16, 2021 Dec 16, 2021 Sep 16, 2021 Sep 16, 2021	snells1	\$0.00 \$0.00 \$122.19 \$122.19 \$122.19 \$122.19 \$13,649.30	Estimate Exception 10 on the current Payment Estimate. Adjustment calculated from Retroreflectivity testing performed by 3rd. party. Results and calculations can be found on e- projects. snells1 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user snells1 overridding Payment
		WATERBORNE PAINT - Total 6 IN. WHITE HIGH BUILD WATERBORNE	Other Item Adjustment	REFL - Tota Adjustment -	12 Il Total	Sep 16, 2021 Dec 16, 2021 Sep 16, 2021 Sep 16, 2021	snells1	\$0.00 \$0.00 \$122.19 \$122.19 \$122.19 \$122.19 \$13,649.30	Estimate Exception 10 on the current Payment Estimate. Adjustment calculated from Retroreflectivity testing performed by 3rd. party. Results and calculations can be found on e- projects. snells1 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user snells1 overridding Payment
		WATERBORNE PAINT - Total 6 IN. WHITE HIGH BUILD WATERBORNE	Other Item Adjustment Other Item	REFL - Tota Adjustment -	12 Total 7	Sep 16, 2021 Dec 16, 2021 Sep 16, 2021 Sep 16, 2021	snells1	\$0.00 \$0.00 \$122.19 \$122.19 \$122.19 \$122.19 \$13,649.30 (\$13,649.30)	Adjustment calculated from Retroreflectivity testing performed by 3rd. party. Results and calculations can be found on e- projects. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user snells1 overridding Payment Estimate Exception 12 on the current Payment Estimate. Adjustment calculated from Retroreflectivity testing performed by 3rd. party. Results and calculations can be found on e- projects.
		WATERBORNE PAINT - Total 6 IN. WHITE HIGH BUILD WATERBORNE	Other Item Adjustment Other Item Adjustment Material Material - To Other Item	REFL - Tota Adjustment - - Total otal REFL	12 Total 7	Sep 16, 2021 Dec 16, 2021 Sep 16, 2021 Sep 16, 2021 Dec 16, 2021	snells1 SYSTEM SYSTEM	\$0.00 \$0.00 \$122.19 \$122.19 \$122.19 \$13,649.30 (\$13,649.30) \$0.00 \$0.00 (\$30.46)	Adjustment calculated from Retroreflectivity testing performed by 3rd. party. Results and calculations can be found on e- projects. snells1 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user snells1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
		WATERBORNE PAINT - Total 6 IN. WHITE HIGH BUILD WATERBORNE	Other Item Adjustment Other Item Adjustment Material Material - Tourish Tem Adjustment	REFL - Total Total REFL REFL REFL REFL	12 Total 7 7 12	Sep 16, 2021 Dec 16, 2021 Sep 16, 2021 Sep 16, 2021 Dec 16, 2021	snells1 SYSTEM SYSTEM	\$0.00 \$0.00 \$122.19 \$122.19 \$122.19 \$122.19 \$13,649.30 (\$13,649.30) \$0.00 (\$30.46)	Adjustment calculated from Retroreflectivity testing performed by 3rd. party. Results and calculations can be found on e- projects. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user snells1 overridding Payment Estimate Exception 12 on the current Payment Estimate. Adjustment calculated from Retroreflectivity testing performed by 3rd. party. Results and calculations can be found on e- projects.
	0140	WATERBORNE PAINT 6 IN. WHITE HIGH BUILD WATERBORNE PAINT	Other Item Adjustment Other Item Adjustment Material Material - Tourish Tem Adjustment	REFL - Tota Adjustment - - Total otal REFL	12 Total 7 7 12	Sep 16, 2021 Dec 16, 2021 Sep 16, 2021 Sep 16, 2021 Dec 16, 2021	snells1 SYSTEM SYSTEM	\$0.00 \$0.00 \$122.19 \$122.19 \$122.19 \$13,649.30 (\$13,649.30) \$0.00 (\$30.46) (\$30.46)	Adjustment calculated from Retroreflectivity testing performed by 3rd. party. Results and calculations can be found on e- projects. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user snells1 overridding Payment Estimate Exception 12 on the current Payment Estimate. Adjustment calculated from Retroreflectivity testing performed by 3rd. party. Results and calculations can be found on e- projects.
	0140	WATERBORNE PAINT 6 IN. WHITE HIGH BUILD WATERBORNE PAINT	Other Item Adjustment Other Item Material Material - To Other Item Adjustment Other Item	REFL - Total Total Total REFL REFL Adjustment -	12 Total 7 7 12 Il Total	Sep 16, 2021 Dec 16, 2021 Sep 16, 2021 Dec 16, 2021	snells1 SYSTEM SYSTEM snells1	\$0.00 \$0.00 \$122.19 \$122.19 \$122.19 \$13,649.30 (\$13,649.30) \$0.00 (\$30.46) (\$30.46)	Adjustment calculated from Retroreflectivity testing performed by 3rd. party. Results and calculations can be found on e- projects. snells1 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user snells1 overridding Payment Estimate Exception 12 on the current Payment Estimate. Adjustment calculated from Retroreflectivity testing performed by 3rd. party. Results and calculations can be found on e- projects. snells1
	0140	WATERBORNE PAINT 6 IN. WHITE HIGH BUILD WATERBORNE PAINT	Other Item Adjustment Other Item Material Material - To Other Item Adjustment Other Item	REFL - Total Total REFL REFL REFL REFL	12 Total 7 7 12 Il Total	Sep 16, 2021 Dec 16, 2021 Sep 16, 2021 Sep 16, 2021 Dec 16, 2021	snells1 SYSTEM SYSTEM	\$0.00 \$0.00 \$122.19 \$122.19 \$122.19 \$13,649.30 (\$13,649.30) \$0.00 (\$30.46) (\$30.46)	Adjustment calculated from Retroreflectivity testing performed by 3rd. party. Results and calculations can be found on e- projects. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user snells1 overridding Payment Estimate Exception 12 on the current Payment Estimate. Adjustment calculated from Retroreflectivity testing performed by 3rd. party. Results and calculations can be found on e- projects.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks															
J5P3379	0150	6 IN. YELLOW HIGH BUILD WATERBORNE	Other Item Adjustment	REFL - Tota	ıl			\$2,791.99																
		PAINT	Other Item	Adjustment -	Total			\$2,791.99																
	0150 -	Total						\$2,791.99																
	0270	MISC. AGGREGATE FOR BASE	Material		5	Aug 16, 2021	SYSTEM	\$34,143.23	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user snells1 overridding Payment Estimate Exception 1 on the current Payment Estimate.															
					5	Aug 16, 2021	SYSTEM	(\$34,143.23)																
					6	Sep 2, 2021	SYSTEM	\$61,745.04	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user snells1 overridding Payment Estimate Exception 1 on the current Payment Estimate.															
					6	Sep 2, 2021	SYSTEM	(\$61,745.04)																
					7	Sep 16, 2021	SYSTEM	\$61,745.04	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user snells1 overridding Payment Estimate Exception 1 on the current Payment Estimate.															
					7	Sep 16, 2021	SYSTEM	(\$61,745.04)																
					8	Oct 4, 2021	SYSTEM	\$61,745.04	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user snells1 overridding Payment Estimate Exception 1 on the current Payment Estimate.															
					8	Oct 4, 2021	SYSTEM	(\$61,745.04)																
					9	Oct 18, 2021	SYSTEM	\$61,745.04	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user snells1 overridding Payment Estimate Exception 1 on the current Payment Estimate.															
					9	Oct 18, 2021	SYSTEM	(\$61,745.04)																
				- Total				\$0.00																
			Material - To	otal				\$0.00																
			Overrun	Overrun	5	Aug 16, 2021	SYSTEM	\$14,653.55	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) overridding Payment Estimate Exception 8 on the current Payment Estimate. Material Insufficiency Quantity 1354.890; Overrun Quantity Balance 581.49.															
					5	Aug 16, 2021	SYSTEM	(\$14,653.55)																
					6	Sep 2, 2021	SYSTEM	(\$14,653.55)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).															
					6	Sep 2, 2021	SYSTEM	\$27,601.81	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) overridding Payment Estimate Exception 11 on the current Payment Estimate. Material Insufficiency Quantity 2450.200; Overrun Quantity Balance 1676.80.															
					6	Sep 2, 2021	SYSTEM	\$14,653.55	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 11 on the current Payment Estimate. Material Insufficiency Quantity 2450.200; Overrun Quantity Balance 1676.80.															
					6	Sep 2, 2021	SYSTEM	(\$27,601.81)																
					7	Sep 16, 2021	SYSTEM	(\$42,255.36)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).															
																				7	Sep 16, 2021	SYSTEM	\$42,255.36	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 15 on the current Payment Estimate. Material Insufficiency Quantity 2450.200; Overrun Quantity Balance 1676.80.
					8	Oct 4, 2021	SYSTEM	(\$42,255.36)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).															
					8	Oct 4, 2021	SYSTEM	\$42,255.36	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 11 on the current Payment Estimate. Material Insufficiency Quantity 2450.200; Overrun Quantity Balance 1676.80.															
					9	Oct 18, 2021	SYSTEM	(\$42,255.36)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).															
					9	Oct 18, 2021	SYSTEM	\$42,255.36	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 11 on the current Payment Estimate. Material Insufficiency Quantity 2450.200; Overrun Quantity Balance 1676.80.															



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3379	0270	MISC.	Overrun	Overrun - T	otal			\$0.00	
		AGGREGATE FOR BASE	Overrun - T	otal				\$0.00	
	0270 -	· Total						\$0.00	
	0280	GRAVEL (A) OR CRUSHED STONE (B)	Material		6	Sep 2, 2021	SYSTEM	\$756.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user snells1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					6	Sep 2, 2021	SYSTEM	(\$756.00)	
					7	Sep 16, 2021	SYSTEM	\$756.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user snells1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					7	Sep 16, 2021	SYSTEM	(\$756.00)	
					8	Oct 4, 2021	SYSTEM	\$756.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user snells1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					8	Oct 4, 2021	SYSTEM	(\$756.00)	
					9	Oct 18, 2021	SYSTEM	\$756.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user snells1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					9	Oct 18, 2021	SYSTEM	(\$756.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0280 -	· Total						\$0.00	
	0290	BIT. PAVEMENT MIXTURE PG64-22 (BP-1)	Material		6	Sep 2, 2021	SYSTEM	\$95,588.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user snells1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					6	Sep 2, 2021	SYSTEM	(\$95,588.54)	
					7	Sep 16, 2021	SYSTEM	\$95,588.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user snells1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					7	Sep 16, 2021	SYSTEM	(\$95,588.54)	
					8	Oct 4, 2021	SYSTEM	\$95,588.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user snells1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					8	Oct 4, 2021	SYSTEM	(\$95,588.54)	
					9	Oct 18, 2021	SYSTEM	\$95,588.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user snells1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					9	Oct 18, 2021	SYSTEM	(\$95,588.54)	
					10	Nov 2, 2021	SYSTEM	\$95,586.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user snells1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					10	Nov 2, 2021	SYSTEM	(\$95,586.75)	
					11	Nov 16, 2021	SYSTEM	\$95,586.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user snells1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					11	Nov 16, 2021	SYSTEM	(\$95,586.75)	
					12	Dec 16, 2021	SYSTEM	\$95,586.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user snells1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					12	Dec 16, 2021	SYSTEM	(\$95,586.75)	
					13	Jan 3, 2022	SYSTEM	\$95,586.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user snells1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					13	Jan 3,	SYSTEM	(\$95,586.75)	



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3379	0290	BIT. PAVEMENT	Material			2022			
		MIXTURE PG64-22 (BP-1)		- Total				\$0.00	
		,	Material - To	otal				\$0.00	
			Other Item	ACAD	5	Aug 16,	snells1	\$24,075.34	Adjustment for material placed from 08/02/21 to 08/15/21
			Adjustment			2021			snells1
					6	Sep 2,	snells1	\$17,773.11	This covers material placed between 08/16/2021 and 09/01/2021
						2021			snells1
					10	Nov 2, 2021	snells1	(\$0.13)	This Adjustment is being made to correct the AC Adjustment made on Estimate 0006 for this contract. The quantity reported was reduced on estimate 0010 due to rounding. This adjustment corrects the adjustment made on estimate 0006.
									snells1
				ACAD - Tot				\$41,848.32	
				FUEL	10	Nov 2, 2021	snells1	(\$0.10)	This Adjustment is being made to correct the system adjustment applied to this estimate. Quantity entered for this estimate is for rounding purposes only. The material was placed in August of 2021 so the Fuel Factor was different. An additional adjustment has been entered to zero out the System Generated Adjustment on this estimate.
									snells1
					10	Nov 2, 2021	snells1	\$0.12	This Adjustment is being made to override the system adjustment applied to this estimate. Quantity entered for this estimate is for rounding purposes only. The material was placed in August of 2021 so the Fuel Factor was different. This adjustment zeroes out the system adjustment applied to this estimate. A new fuel adjustment will be added to this estimate using the correct fuel factor.
									snells1
				FUEL - Tota	ıl			\$0.02	
			Other Item	Adjustment -	Total			\$41,848.34	
			Price FUEL		5	Aug 16, 2021	SYSTEM	\$19,265.80	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					6	Sep 2, 2021	SYSTEM	\$14,222.58	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					10	Nov 2, 2021	SYSTEM	(\$0.12)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total	10		SYSTEM	\$33,488.26	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			Price FUEL		10		SYSTEM	\$33,488.26 \$33,488.26	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
		- Total				2021		\$33,488.26 \$33,488.26 \$75,336.60	
	0290 -	ASPHALTIC CONCRETE MIXTURE PG			10		SYSTEM	\$33,488.26 \$33,488.26	Reference Item Price Adjustment Index Adjustment Type applied is FUEL This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user ellist2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		ASPHALTIC CONCRETE				2021 Aug 3,		\$33,488.26 \$33,488.26 \$75,336.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user ellist2 overridding Payment
		ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C			4	Aug 3, 2021 Aug 3,	SYSTEM	\$33,488.26 \$33,488.26 \$75,336.60 \$825,979.04	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user ellist2 overridding Payment
		ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C			4	Aug 3, 2021 Aug 3, 2021 Aug 16,	SYSTEM SYSTEM	\$33,488.26 \$33,488.26 \$75,336.60 \$825,979.04 (\$825,979.04)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user ellist2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user snells1 overridding Payment
		ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C			4 4 5	Aug 3, 2021 Aug 3, 2021 Aug 16, 2021 Aug 16, 2021	SYSTEM SYSTEM	\$33,488.26 \$33,488.26 \$75,336.60 \$825,979.04 (\$825,979.04) \$1,911,449.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user ellist2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user snells1 overridding Payment
		ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C			4 5 5	Aug 3, 2021 Aug 3, 2021 Aug 16, 2021 Aug 16, 2021 Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM	\$33,488.26 \$33,488.26 \$75,336.60 \$825,979.04 (\$825,979.04) \$1,911,449.70 (\$1,911,449.70)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user ellist2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user snells1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user snells1 overridding Payment Estimate Item Adjustment (0011) due to user snells1 overridding Payment
		ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C			4 4 5 5 6	Aug 3, 2021 Aug 3, 2021 Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$33,488.26 \$33,488.26 \$75,336.60 \$825,979.04 (\$825,979.04) \$1,911,449.70 (\$1,911,449.70)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user ellist2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user snells1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user snells1 overridding Payment Estimate Item Adjustment (0011) due to user snells1 overridding Payment
		ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C			4 4 5 5 6	Aug 3, 2021 Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$33,488.26 \$33,488.26 \$75,336.60 \$825,979.04 (\$825,979.04) \$1,911,449.70 (\$1,911,449.70) \$1,911,449.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user ellist2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user snells1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user snells1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate.
		ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C			4 4 5 5 6 6 7	Aug 3, 2021 Aug 3, 2021 Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$33,488.26 \$33,488.26 \$75,336.60 \$825,979.04 (\$825,979.04) \$1,911,449.70 (\$1,911,449.70) \$1,911,449.70 (\$1,911,449.70)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user ellist2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user snells1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user snells1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate.



The material was placed in August of 2021 so the Fuel Factor was different	J5P3379	79 030	CONCRETE							
MIX 9			70.00 (004050			9		SYSTEM	\$955,584.30	Estimate Item Adjustment (0005) due to user snells1 overridding Payment
2021 Estimate Item Adjustment (0005) due to user snells 10 verioding Payment Estimate Exception 2 on the current Payment Estimate Payment In Setimate Exception 2 on the current Payment Estimate Payment Estimate Exception 2 on the current Payment Estimate Payment Estimate Item Adjustment (0002) due to user snells 10 verioding Payment Estimate Exception 2 on the current Payment Estimate Payment Estimate Exception 2 on the current Payment Pa						9		SYSTEM	(\$955,584.30)	
11						10		SYSTEM	\$955,582.45	Estimate Item Adjustment (0005) due to user snells1 overridding Payment
2021 Settmafe Item Adjustment (0002) due to user snellst overridding Payment Estimate Exception 2 on the current Payment Estimate.						10		SYSTEM	(\$955,582.45)	
2021 12 Dec 16, SYSTEM \$955,582.45 Estimate Item Adjustment (0002) due to user snells1 overridding Payment Estimate Exception 2 on the current Payment Estimate Extimate Exception 2 on the current Payment Estimate Extimate Exception 2 on the current Payment Estimate Extimate Exception 2 on the current Payment Estimate Exception 2 on the current Payment Estimate Exception 2 on the current Payment Estimate Extimate Exception 2 on the current Payment Estimate Extimate Exception 2 on the current Payment Estimate Exception 2 on the current						11		SYSTEM	\$955,582.45	Estimate Item Adjustment (0002) due to user snells1 overridding Payment
2021 Estimate Item Adjustment (0002) due to user snells1 overridding Payment Estimate Exception 2 on the current Payment Estimate.						11		SYSTEM	(\$955,582.45)	
2021 13						12		SYSTEM	\$955,582.45	Estimate Item Adjustment (0002) due to user snells1 overridding Payment
Estimate Item Adjustment (0007) due to user snells1 overridding Payment Estimate Exception 2 on the current Payment Estimate. 13						12		SYSTEM	(\$955,582.45)	
Total S0.00 Material - Total S0.00 Other Item Adjustment ACAD 4 Aug 3, 2021 5 Aug 16, 2021						13		SYSTEM	\$955,582.45	Estimate Item Adjustment (0007) due to user snells1 overridding Payment
Other Item Adjustment ACAD 4 Aug 3, 2021						13		SYSTEM	(\$955,582.45)	
Other Item Adjustment ACAD 4 Aug 3, 2021 \$\ \ 2021 \] 5 Aug 16, 2021 \$\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \					- Total				\$0.00	
Adjustment 2021				Material - T	otal				\$0.00	
2021 Nov 2, 2021 10 Nov 2, 2021 Nov 2, 2021 Nov 2 snells1 (\$0.09) This Adjustment is being made to correct the AC Adjustment made on Estimate 0010 due to rounding. This adjustment corrects the adjustment made on estimate 0010 due to rounding. This adjustment corrects the adjustment made on estimate 0006. snells1 ACAD - Total \$99,210.75 FUEL 10 Nov 2, 2021 Nov 2, 2021 Septimate 0010 due to rounding. This adjustment corrects the adjustment made on estimate 0010 due to rounding. This adjustment corrects the adjustment made on estimate 0010 due to rounding. This adjustment corrects the adjustment made on estimate 0010 due to rounding. This adjustment adjustment applied to this estimate. Quantity entered for this estimate is for rounding purposes on The material was placed in August of 2021 so the Fuel Factor was different An additional adjustment has been entered to zero out the System General					ACAD	4		ellist2	\$39,210.84	
10 Nov 2, 2021 Snells1 (\$0.09) This Adjustment is being made to correct the AC Adjustment made on Estimate 0006 for this contract. The quantity reported was reduced on estimate 0010 due to rounding. This adjustment corrects the adjustment made on estimate 0006. snells1 FUEL 10 Nov 2, 2021 Snells1 (\$0.10) This Adjustment is being made to correct the System adjustment applied to this estimate. Quantity entered for this estimate is for rounding purposes of The material was placed in August of 2021 so the Fuel Factor was different An additional adjustment has been entered to zero out the System Generat						5		snells1	\$60,000.00	
Estimate 0006 for this contract. The quantity reported was reduced on estimate 0010 due to rounding. This adjustment corrects the adjustment made on estimate 0006. snells1 FUEL 10 Nov 2, 2021 (\$0.10) This Adjustment is being made to correct the system adjustment applied to this estimate. Quantity entered for this estimate is for rounding purposes of The material was placed in August of 2021 so the Fuel Factor was different An additional adjustment has been entered to zero out the System Generat										snells1
FUEL 10 Nov 2, 2021 Snells1 (\$0.10) This Adjustment is being made to correct the system adjustment applied to this estimate. Quantity entered for this estimate is for rounding purposes of The material was placed in August of 2021 so the Fuel Factor was different An additional adjustment has been entered to zero out the System Generate.						10		snells1	(\$0.09)	Estimate 0006 for this contract. The quantity reported was reduced on estimate 0010 due to rounding. This adjustment corrects the adjustment
FUEL 10 Nov 2, 2021 This Adjustment is being made to correct the system adjustment applied to this estimate. Quantity entered for this estimate is for rounding purposes of The material was placed in August of 2021 so the Fuel Factor was different An additional adjustment has been entered to zero out the System Generate.										snells1
2021 this estimate. Quantity entered for this estimate is for rounding purposes of The material was placed in August of 2021 so the Fuel Factor was different An additional adjustment has been entered to zero out the System Generate.					ACAD - Tota	al			\$99,210.75	
					FUEL	10		snells1	(\$0.10)	this estimate. Quantity entered for this estimate is for rounding purposes only. The material was placed in August of 2021 so the Fuel Factor was different. An additional adjustment has been entered to zero out the System Generated
snells1										snells1
2021 this estimate. Quantity entered for this estimate is for rounding purposes of The material was placed in August of 2021 so the Fuel Factor was different This adjustment zeroes out the system adjustment applied to this estimate.						10		snells1	\$0.12	This Adjustment is being made to override the system adjustment applied to this estimate. Quantity entered for this estimate is for rounding purposes only. The material was placed in August of 2021 so the Fuel Factor was different. This adjustment zeroes out the system adjustment applied to this estimate. A new fuel adjustment will be added to this estimate using the correct fuel factor.
FUEL - Total \$0.02					FUEL - Tota				\$0.02	OTIVITO I
Other Item Adjustment - Total \$99,210.77				Other Item						
Overrun Overrun 5 Aug 16, SYSTEM (\$75,988.77) Reference Item Price Adjustment Index Adjustment Type applied is FUEL								SYSTEM		Reference Item Price Adjustment Index Adjustment Type applied is FUEL
5 Aug 16, SYSTEM \$75,988.77 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception						5	Aug 16,	SYSTEM	\$75,988.77	Estimate Item Adjustment (0009) overridding Payment Estimate Exception 7 on the current Payment Estimate. Material Insufficiency Quantity 31075.430;
6 Sep 2, 2021 SYSTEM (\$75,854.59) Averaged Price Adjustment from this item on all previous payment estimate of '3.37123' is applied (if non-zero).						6		SYSTEM	(\$75,854.59)	Averaged Price Adjustment from this item on all previous payment estimates of '3.37123' is applied (if non-zero).
						6		SYSTEM	\$75,854.59	Estimate Item Adjustment (0010) overridding Payment Estimate Exception 12 on the current Payment Estimate. Material Insufficiency Quantity 31075.430;
7 Sep 16, SYSTEM (\$75,854.59) Averaged Price Adjustment from this item on all previous payment estimate						7	Sep 16,	SYSTEM	(\$75,854.59)	Averaged Price Adjustment from this item on all previous payment estimates



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3379	0300	ASPHALTIC	Overrun	Overrun		2021			of '3.37123' is applied (if non-zero).
		CONCRETE MIXTURE PG 70-22 (SP125C MIX)			7	Sep 16, 2021	SYSTEM	\$75,854.59	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 16 on the current Payment Estimate. Material Insufficiency Quantity 15535.430; Overrun Quantity Balance 1169.13.
					8	Oct 4, 2021	SYSTEM	(\$75,854.59)	Averaged Price Adjustment from this item on all previous payment estimates of '3.37123' is applied (if non-zero).
					8	Oct 4, 2021	SYSTEM	\$75,854.59	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 12 on the current Payment Estimate. Material Insufficiency Quantity 15535.430; Overrun Quantity Balance 1169.13.
					9	Oct 18, 2021	SYSTEM	(\$75,854.59)	Averaged Price Adjustment from this item on all previous payment estimates of '3.37123' is applied (if non-zero).
					9	Oct 18, 2021	SYSTEM	\$75,854.59	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 12 on the current Payment Estimate. Material Insufficiency Quantity 15535.430; Overrun Quantity Balance 1169.13.
				Overrun - To	otal			\$0.00	
			Overrun - T	otal				\$0.00	
			Price FUEL		4	Aug 3, 2021	SYSTEM	\$43,244.72	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					5	Aug 16, 2021	SYSTEM	\$61,517.64	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					10	Nov 2, 2021	SYSTEM	(\$0.12)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$104,762.24	
			Price FUEL	- Total				\$104,762.24	
	0300 -	Total						\$203,973.01	
	0310	MISC.	Material		4	Aug 3, 2021	SYSTEM	\$37,502.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user ellist2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					4	Aug 3, 2021	SYSTEM	(\$37,502.38)	
					5	Aug 16, 2021	SYSTEM	\$37,502.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user snells1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					5	Aug 16, 2021	SYSTEM	(\$37,502.38)	
					6	Sep 2, 2021	SYSTEM	\$37,502.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user snells1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					6	Sep 2, 2021	SYSTEM	(\$37,502.38)	
					7	Sep 16, 2021	SYSTEM	\$37,502.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user snells1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					7	Sep 16, 2021	SYSTEM	(\$37,502.38)	
					8	Oct 4, 2021	SYSTEM	\$37,502.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user snells1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					8	Oct 4, 2021	SYSTEM	(\$37,502.38)	
					9	Oct 18, 2021	SYSTEM	\$37,502.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user snells1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					9	Oct 18, 2021	SYSTEM	(\$37,502.38)	
					10	Nov 2, 2021	SYSTEM	\$37,502.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user snells1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					10	Nov 2, 2021	SYSTEM	(\$37,502.38)	
					11	Nov 16, 2021	SYSTEM	\$37,502.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user snells1 overridding Payment Estimate Exception 3 on the current Payment Estimate.



J5P3379 0310 MISC. Material	nt Number	Created Date	Created By	Amount	Remarks
	11	Nov 16, 2021	SYSTEM	(\$37,502.38)	
- Total				\$0.00	
Material - Total				\$0.00	
0310 - Total				\$0.00	
0320 TACK COAT Material	5	Aug 16, 2021	SYSTEM	\$7,344.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user snells1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
	5	Aug 16, 2021	SYSTEM	(\$7,344.00)	
	6	Sep 2, 2021	SYSTEM	\$13,424.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user snells1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
	6	Sep 2, 2021	SYSTEM	(\$13,424.00)	
	7	Sep 16, 2021	SYSTEM	\$13,424.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user snells1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
	7	Sep 16, 2021	SYSTEM	(\$13,424.00)	
	8	Oct 4, 2021	SYSTEM	\$13,424.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user snells1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
	8	Oct 4, 2021	SYSTEM	(\$13,424.00)	
	9	Oct 18, 2021	SYSTEM	\$13,424.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user snells1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
	9	Oct 18, 2021	SYSTEM	(\$13,424.00)	
- Total				\$0.00	
Material - Total				\$0.00	
0320 - Total				\$0.00	
0330 MISC. NON Material STANDARD	4	Aug 3, 2021	SYSTEM	\$15,956.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user ellist2 overridding Payment
TACK COAT					Estimate Exception 3 on the current Payment Estimate.
TACK COAT	4	Aug 3, 2021	SYSTEM	(\$15,956.00)	
TACK COAT	5		SYSTEM	(\$15,956.00) \$35,992.00	
TACK COAT		2021 Aug 16,			Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user snells1 overridding Payment
TACK COAT	5	2021 Aug 16, 2021 Aug 16,	SYSTEM	\$35,992.00	Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user snells1 overridding Payment
TACK COAT	5	2021 Aug 16, 2021 Aug 16, 2021 Sep 2,	SYSTEM	\$35,992.00 (\$35,992.00)	Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user snells1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user snells1 overridding Payment
TACK COAT	5 6	2021 Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 2,	SYSTEM SYSTEM	\$35,992.00 (\$35,992.00) \$35,992.00	Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user snells1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user snells1 overridding Payment
TACK COAT	5 6 6	2021 Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 2, 2021 Sep 16,	SYSTEM SYSTEM SYSTEM	\$35,992.00 (\$35,992.00) \$35,992.00	Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user snells1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user snells1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user snells1 overridding Payment
TACK COAT	5 5 6 6 7	2021 Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 2, 2021 Sep 16, 2021 Sep 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$35,992.00 (\$35,992.00) \$35,992.00 (\$35,992.00) \$35,992.00	Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user snells1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user snells1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user snells1 overridding Payment
TACK COAT	5 5 6 6 7	2021 Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 2, 2021 Sep 16, 2021 Oct 4,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$35,992.00 (\$35,992.00) \$35,992.00 (\$35,992.00) (\$35,992.00)	Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user snells1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user snells1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user snells1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user snells1 overridding Payment Estimate Item Adjustment (0010) due to user snells1 overridding Payment
TACK COAT	5 5 6 7 7	2021 Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 16, 2021 Sep 16, 2021 Oct 4, 2021 Oct 4,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$35,992.00 (\$35,992.00) \$35,992.00 (\$35,992.00) \$35,992.00 (\$35,992.00)	Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user snells1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user snells1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user snells1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user snells1 overridding Payment Estimate Item Adjustment (0010) due to user snells1 overridding Payment
TACK COAT	5 5 6 7 7 8	2021 Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 16, 2021 Sep 16, 2021 Oct 4, 2021 Oct 4, 2021 Oct 18,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$35,992.00 (\$35,992.00) \$35,992.00 (\$35,992.00) (\$35,992.00) \$35,992.00 (\$35,992.00)	Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user snells1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user snells1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user snells1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user snells1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 7 on the current Payment Estimate.
TACK COAT	5 5 6 7 7 8 8	2021 Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 16, 2021 Sep 16, 2021 Oct 4, 2021 Oct 4, 2021 Oct 18, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$35,992.00 (\$35,992.00) \$35,992.00 (\$35,992.00) \$35,992.00 (\$35,992.00) (\$35,992.00)	Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user snells1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user snells1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user snells1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user snells1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 7 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
I5P3379	0330 -	Total						\$0.00	
	0335	PCCP CRACK FILLING	Material		1	Jun 16, 2021	SYSTEM	\$55,397.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user snells1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					1	Jun 16, 2021	SYSTEM	(\$55,397.10)	
					2	Jun 30, 2021	SYSTEM	\$127,389.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user snells1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					2	Jun 30, 2021	SYSTEM	(\$127,389.90)	
					3	Jul 16, 2021	SYSTEM	\$127,389.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user snells1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Jul 16, 2021	SYSTEM	(\$127,389.90)	
					4	Aug 3, 2021	SYSTEM	\$127,389.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user ellist2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					4	Aug 3, 2021	SYSTEM	(\$127,389.90)	
					5	Aug 16, 2021	SYSTEM	\$127,389.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user snells1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					5	Aug 16, 2021	SYSTEM	(\$127,389.90)	
					6	Sep 2, 2021	SYSTEM	\$127,389.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user snells1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					6	Sep 2, 2021	SYSTEM	(\$127,389.90)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0335 -	Total						\$0.00	
	0370	MGS HEIGHT AND BLOCK TRANSITION	Material		6	Sep 2, 2021	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user snells1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					6	Sep 2, 2021	SYSTEM	(\$1,000.00)	
					7	Sep 16, 2021	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user snells1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					7	Sep 16, 2021	SYSTEM	(\$1,000.00)	
					8	Oct 4, 2021	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user snells1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					8	Oct 4, 2021	SYSTEM	(\$1,000.00)	
					9	Oct 18, 2021	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user snells1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					9	Oct 18, 2021	SYSTEM	(\$1,000.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0370 -	Total						\$0.00	
	5002	FURN & PLACE CONC MATL FOR FULL	Material		12	Dec 16, 2021	SYSTEM	\$5,355.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user snells1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
		DEPTH			12	Dec 16, 2021	SYSTEM	(\$5,355.00)	
								\$5,355.00	

Jan 6, 2022



Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3379	5002	FURN & PLACE CONC MATL FOR FULL DEPTH	Material		13	Jan 3, 2022	SYSTEM	(\$5,355.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	5002 - Total							\$0.00	
J5P3379 - Total							\$290,938.65		
Overall - Total							\$290,938.65		