

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: January 25, 2022

Final Estimate Number	Contract ID	201120-D02	•	•	Original Contract Amount	
15	Prime Contractor	Magruder Paving, LLC	Pay Period End	January 25, 2022	Net Change Order Amount	(\$4,161.33)
13					Current Contract Amount	\$3,127,457.94

Approval Date		By User
April 27, 2022	Generated and Approved (and should be considered Draft) at the Project Office Level by	grahac1
April 27, 2022	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	holdtc
May 3, 2022	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
November 1, 2021	November 1, 2021	October 25, 2021	100.00%

Con	tract informational	Dates
Date Description	Original Completion Date	Current Completion Date
Acceptance Date	March 2, 2022	March 2, 2022
Awarded Date	December 2, 2020	December 2, 2020
Letting Date	November 20, 2020	November 20, 2020
Notice to Proceed Date	February 1, 2021	February 1, 2021
Work Began	June 14, 2021	June 14, 2021

Milestones												
Date Description	Original Completion Date	Current Completion Date	Days Remaining on Milestone	Diary Charge Days								
JSP- B Completion Date- Road User Costs	November 1, 2021	November 1, 2021	Milestone Complete									
			2									

Contract Total Pa	y For Estimate No. 15			
		This Estimate	Previous	To Date
201120-D02				
	Total Posted Items Pay	\$0.00	\$3,127,457.94	\$3,127,457.94
	Gross Item Adjustments	\$0.00	\$290,938.65	\$290,938.65
	Incentive	\$0.00	\$73,997.59	\$73,997.59
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	(\$240.65)	\$156,306.08	\$156,065.43
	·		\$3,648,700.26	\$3,648,459.61
Contract Total Pa	yable This Estimate:	(\$240.65)		

Items Paid This Estimate Period

Date

No Data Available					
Contract Adjustments This	<u>Estimate</u>				
Adj Type	Entered By	Comments	Time Units	Rate	Amount
ABIROther Contract Adjustment	grahac1	Rte. 5 Southbound alternating Passing Lane IRI Bonus. Calculations on file in eProjects.			\$1,441.49
ABIROther Contract Adjustment	grahac1	Deducting Rte. 5 Southbound Driving Lane IRI Bonus from Estimate 0014 due to error in lane width. Revised adjustment applied to Estimate 0015.			(\$8,669.27)
ABIROther Contract Adjustment	grahac1	Rte. 5 Northbound Driving Lane IRI Bonus. Calculations on file in eProjects.			\$9,656.63
ABIROther Contract Adjustment	grahac1	Deducting Rte. 5 Northbound Driving Lane IRI Bonus from Estimate 0014 due to error in lane width. Revised adjustment applied to Estimate 0015.			(\$10,806.23)

Revision 4/1/2020 Page 1 of 18



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: January 25, 2022

Final Estimate Number 15		1120-D02 Pay Peri- gruder Paving, LLC Pay Peri-	od Start January 16, 2 od End January 25, 2		er Amount (\$4,161.33)					
Adj Type	Entered By	Comments	Time Units	Rate	Amount					
ABIROther Contract Adjustment	grahac1	Rte. 5 Southbound Driving Lane IRI Bonus. Calculations on file in eProjects.			\$7,846.72					
ABIROther Contract Adjustment	grahac1	Rte. 5 Northbound alternating Passing Lane IRI Bonus. Calculations on file in eProjects.			\$290.01					
verall - Total These amount										
e Item Adjustments This	<u>Estimate</u>									

No Data Available


Revision 4/1/2020 Page 2 of 18



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Information					
Project Number	Federal Proj. Number	Project Description	Route	County		Location of Work from 0.8 miles south of the Camden County line to 0.2 miles north of Lebanon					
J5P3379	FAS S402(20)	Resurface	5	LACLEDE	from 0.8 miles south of th	ne Camden County line to 0.2	miles north of Lebanon				
Totals by	Job Numbe	rs									
J5P3379					This Estimate	Previous	To Date				
J5P3379	Poste	d Item Pay			This Estimate \$0.00	Previous \$3,127,457.94	To Date \$3,127,457.94				
J5P3379		d Item Pay Item Adjustm	ents								
J5P3379				s Item Pay	\$0.00	\$3,127,457.94	\$3,127,457.94				
J5P3379		Item Adjustm		s Item Pay	\$0.00 \$0.00	\$3,127,457.94 \$290,938.65	\$3,127,457.94 \$290,938.65				
J5P3379	Gross	Item Adjustm		s Item Pay	\$0.00 \$0.00 \$0.00	\$3,127,457.94 \$290,938.65 \$3,418,396.59	\$3,127,457.94 \$290,938.65 \$3,418,396.59				
J5P3379	Incent Disino	Item Adjustm	Gross	s Item Pay	\$0.00 \$0.00 \$0.00 \$0.00	\$3,127,457.94 \$290,938.65 \$3,418,396.59 \$73,997.59	\$3,127,457.94 \$290,938.65 \$3,418,396.59 \$73,997.59				

Revision 4/1/2020 Page 3 of 18





Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period No Exceptions Exist on Contract

Revision 4/1/2020 Page 4 of 18



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Project Category Line Item Description Bid Net Total Unit Total Unit Price Total Value POSTED

ontract ONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTEI To Date (See repor generated date)			
20-D02	J5P3379	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$1,000.00	\$1,000.0			
		0001	0015	2153000	SHAPING SLOPES, CLASS III	1.00	0.00	1.00	100F	1.00	\$1,200.00	\$1,200.0			
		0001	0020	4019901	MISC.INFRARED SCANNING	1.00	0.00	1.00	LS	1.00	\$20,000.00	\$20,000.0			
		0001	0030	4019901	MISC.INTELLIGENT COMPACTION	1.00	0.00	1.00	LS	1.00	\$31,100.00	\$31,100.0			
		0001	0040	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$1,000.00	\$2,000.0			
		0001	0050	6161005	CONSTRUCTION SIGNS	1,743.00	149.00	1,892.00	SQFT	1,892.00	\$8.00	\$15,136.0			
		0001	0060	6161025	CHANNELIZER (TRIM LINE)	1,165.00	0.00	1,165.00	EA	1,165.00	\$20.00	\$23,300.0			
		0001	0070	6161033	DIRECTIONAL INDICATOR BARRICADE	60.00	0.00	60.00	EA	60.00	\$75.00	\$4,500.0			
		0001	0800	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	2.00	\$950.00	\$1,900.0			
		0001	0090	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	6.00	-1.00	5.00	EA	5.00	\$2,200.00	\$11,000.0			
		0001	0100	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$32,740.00	\$32,740.0			
		0001	0110	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	2,632.00	188.00	2,820.00	LF	2,820.00	\$10.00	\$28,200.0			
	0001		0001	0001	0001	0120	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	71.00	5.00	76.00	EA	76.00	\$235.00	\$17,860.0
		0001	0130	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	21,418.00	0.00	21,418.00	LF	21,418.00	\$0.18	\$3,855.2			
		0001	0140	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	136,493.00	0.00	136,493.00	LF	136,493.00	\$0.10	\$13,649.			
		0001	0150	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	101,348.00	102,304.00	203,652.00	LF	203,652.00	\$0.30	\$61,095.			
		0001	0153	6209901	MISC.Temporary Pavement Marking Paint - Segment 1	1.00	-1.00	0.00	LS	0.00	\$0.01	\$0.			
		0001	0157	6209901	MISC.Temporary Pavement Marking Paint - Segment 2	1.00	-1.00	0.00	LS	0.00	\$0.01	\$0.			
		0001	0170	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	7,545.00	0.00	7,545.00	SQYD	7,545.00	\$2.62	\$19,767.			
		0001	0180	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	985.70	0.00	985.70	STA	985.70	\$17.49	\$17,239.			
		0001	0190	6261001	BITUMINOUS CENTERLINE RUMBLE STRIP	1,051.80	0.00	1,051.80	STA	1,051.80	\$17.37	\$18,269.			
		0003	0270	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	773.40	1,676.80	2,450.20	TONS	2,450.20	\$25.20	\$61,745.			
		0003	0280	3105002	GRAVEL (A) OR CRUSHED STONE (B)	30.00	0.00	30.00	TONS	30.00	\$25.20	\$756.			
		0003	0290	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	9,917.70	-311.20	9,606.50	TONS	9,606.50	\$59.50	\$571,586.			
		0003	0300	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	29,906.30	1,169.10	31,075.40	TONS	31,075.40	\$61.51	\$1,911,447.			
		0003	0310	4039905	MISC.SYSTEM B GEOSYNTHETIC INTERLAYER (COMPOSITE PAVING FABRIC/REINFORCING GRID)	52,969.00	-39,947.00	13,022.00	SQYD	13,022.00	\$2.88	\$37,503.			
		0003	0320	4071005	TACK COAT	7,099.00	-387.00	6,712.00	GAL	6,712.00	\$2.00	\$13,424.			
		0003	0330	4079912	MISC.MODIFIED BONDED ASPHALTIC CONCRETE PAVEMENT	54,838.00	-19,143.00	35,695.00	GAL	35,695.00	\$1.00	\$35,695.			
		0003	0335	4138000	PCCP CRACK FILLING	119,180.00	-3,371.00	115,809.00	LF	115,809.00	\$1.10	\$127,389.			
		0003	0350	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	6,267.00	-505.00	5,762.00	SQYD	5,762.00	\$5.07	\$29,213			
		0010	0360	6061060	MGS GUARDRAIL	50.00	0.00	50.00	LF	50.00	\$40.00	\$2,000			
		0010	0370	6061074	MGS HEIGHT AND BLOCK TRANSITION	1.00	0.00	1.00	EA	1.00	\$1,000.00	\$1,000.			
		0010	0380	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	1.00	0.00	1.00	EA	1.00	\$3,200.00	\$3,200			
		0001	5001	6207001	PAVEMENT MARKING REMOVAL	0.00	3,200.00	3,200.00	LF	3,200.00	\$1.04	\$3,328			
F		0001	5002	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	0.00	12.00	12.00	SQYD	12.00	\$446.25	\$5,355			
	Project J	5 P3379 - To	tal Value	Posted to D	Date as of Report Generated Date							\$3,127,457			

Revision 4/1/2020 Page 5 of 18



The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work. The information below this line are details for Construction Signs (if applicable). Total Quantity DWR Date Sign Information SF Fach Project Line Station Location Number SF Special Total Posted For DWR Number Mile Each of Items Special SF to Sign Date Sign Post SB Old Rte. 5 South J5P3379 0050 June 16, 372 WO20-1 48x48 16.00 0,880 1.00 16 16 2021 ROAD/BRIDGE/RAMP WORK AHEAD end - right shoulder WO20-1 48x48 16.00 SB Olathe Rd. right 0.137 1.00 16 16 ROAD/BRIDGE/RAMP WORK AHEAD shoulder SPECIAL 7 96x48 32.00 POINT OF PRESENCE SB Route 5 right 32 32 237.580 1.00 shoulder 236.156 SB Route 5 right 1.00 16 16 RIGHT/CENTER/LEFT LANE CLOSED shoulder 48x48 16.00 UNEVEN SB Route 5 right WO8-11 16 236.128 1.00 16 LANES shoulder WO8-12 SB Route 5 right 48x48 16.00 NO CENTER 1.00 16 16 236.100 LINE shoulder WO6-3 48x48 16.00 TWO WAY 236.072 SB Route 5 right 1.00 16 16 TRAFFIC (SYMBOL) shoulder CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE SB Route 5 right 12 12 235.917 shoulder GO20-1 60x24 10.00 ROAD WORK 235.822 SB Route 5 right 1.00 10 10 NEXT XX MILES shoulder GO20-2 48x24 8.00 END ROAD 235.812 NB Rte. 5 right 8 8 1.00 shoulder (Used SB LM) CONST-7-48 48x24 8.00 RATE OUR 235.727 SB Route 5 right 1.00 8 8 WORK ZONE shoulder WO20-1 48x48 16.00 WB Jasmine Rd. 16 16 0.219 1.00 ROAD/BRIDGE/RAMP WORK AHEAD WO20-1 48x48 16.00 NB Old Rte. 5 North 0.886 1.00 16 16 ROAD/BRIDGE/RAMP WORK AHEAD end - right shoulder WO20-1 48x48 16.00 1.257 NB Olathe right 1.00 16 16 ROAD/BRIDGE/RAMP WORK AHEAD shoulder NB Olathe Dr. right 1.505 1.00 16 16 ROAD/BRIDGE/RAMP WORK AHEAD shoulder WO20-1 48x48 16.00 WB Knoll Rd. right 1.733 16 16 1.00 ROAD/BRIDGE/RAMP WORK AHEAD WO20-1 48x48 16.00 WB Livingston right 1.873 1.00 16 16 ROAD/BRIDGE/RAMP WORK AHEAD CONST-7-48 48x24 8.00 RATE OUR 104.978 NB Route 5 right 1.00 8 8 WORK ZONE shoulder GO20-1 60x24 10.00 ROAD WORK 105.085 NB Route 5 right 1.00 10 10 NEXT XX MILES shoulder 48x36 12.00 WORK 105.183 NB Route 5 right 1.00 12 12 ZONE NO PHONE ZONE shoulder SPECIAL 7 96x48 32.00 POINT OF NB Route 5 right 32 32 105.297 1.00 **PRESENCE** shoulder WO20-1 48x48 16.00 11.643 EB Rte. E - right 1.00 16 16 ROAD/BRIDGE/RAMP WORK AHEAD shoulder WO20-1 48x48 16.00 2.630 SB Kansas - right 1.00 16 16 ROAD/BRIDGE/RAMP WORK AHEAD shoulder 48x48 16.00 2.913 SB Route VV right 1.00 16 16 ROAD/BRIDGE/RAMP WORK AHEAD shoulder June 28 152 48x48 16.00 1.486 Hamlock Rd. 1.00 16 16 2021 ROAD/BRIDGE/RAMP WORK AHEAD WO20-1 48x48 16.00 16 0.889 Houston Rd. 1.00 16 ROAD/BRIDGE/RAMP WORK AHEAD WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD 0.236 N, Oakwood 1.00 16 16 WO20-1 48x48 16.00 0.233 South Oakwood 1.00 16 16 ROAD/BRIDGE/RAMP WORK AHEAD 16 48x48 16.00 4.231 Orchard Rd. 16 ROAD/BRIDGE/RAMP WORK AHEAD GO20-2 48x24 8.00 END ROAD SB Rte. 5 just before 8 247.725 1.00 8 WORK Greenfield Rd. WO20-1 48x48 16 00 FB Julie Rd 16 16 2 952 1.00

Revision 4/1/2020 Page 6 of 18

ROAD/BRIDGE/RAMP WORK AHEAD



The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

				for Construction Signs (if applica		Loc	Location	Number	QF.	Special	SE Each	Total	
Project	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Tota SF to Post	
P3379	0050	June 28, 2021	152	WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		2.902	EB Independence Rd.	1.00	16				
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		16.730	SB Rte. BB	1.00	16				
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		0.055	Jonquil Rd.	1.00	16				
		August 31, 2021	1028	CONST-7-48 48x24 8.00 RATE OUR WORK ZONE		105.085	Northbound Rte. 5	-1.00	8				
				CONST-7-72 72x36 18.00 RATE OUR WORK ZONE		105.085	Northbound Rte. 5	1.00	18				
				WO6-3(48) 48x48 16.00 TWO-WAY TRAFFIC		105.355	Northbound Rte. 5	1.00	16				
				WO8-12 48x48 16.00 NO CENTER LINE		105.383	Northbound Rte. 5	1.00	16				
				WO8-11 48x48 16.00 UNEVEN LANES		105.416	Northbound Rte. 5	1.00	16				
				WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		105.448	Northbound Rte. 5	1.00	16				
				WO6-3(48) 48x48 16.00 TWO-WAY TRAFFIC		106.431	Northbound Rte. 5	1.00	16				
				WO8-11 48x48 16.00 UNEVEN LANES		106.463	Northbound Rte. 5	1.00	16				
					WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		106.480	Northbound Rte. 5	1.00	16			
				WO6-3(48) 48x48 16.00 TWO-WAY TRAFFIC		107.505	Northbound Rte. 5	1.00	16				
				WO8-12 48x48 16.00 NO CENTER LINE		107.524	Northbound Rte. 5	1.00	16				
				WO8-11 48x48 16.00 UNEVEN LANES		107.549	Northbound Rte. 5	1.00	16				
				WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		107.568	Northbound Rte. 5	1.00	16				
				WO6-3(48) 48x48 16.00 TWO-WAY TRAFFIC		108.557	Northbound Rte. 5	1.00	16				
				WO8-11 48x48 16.00 UNEVEN LANES		108.581	Northbound Rte. 5	1.00	16				
				WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		108.611	Northbound Rte. 5	1.00	16				
				WO6-3(48) 48x48 16.00 TWO-WAY TRAFFIC		109.665	Northbound Rte. 5	1.00	16				
				WO8-12 48x48 16.00 NO CENTER LINE		109.690	Northbound Rte. 5	1.00	16				
				WO8-11 48x48 16.00 UNEVEN LANES		109.710	Northbound Rte. 5	1.00	16				
				WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		109.737	Northbound Rte. 5	1.00	16				
				WO6-3(48) 48x48 16.00 TWO-WAY TRAFFIC		110.778	Northbound Rte. 5	1.00	16				
				WO8-11 48x48 16.00 UNEVEN LANES		110.799	Northbound Rte. 5	1.00	16				
				WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		110.820	Northbound Rte. 5	1.00	16				
				WO6-3(48) 48x48 16.00 TWO-WAY TRAFFIC		112.570	Northbound Rte. 5	1.00	16				
				WO8-11 48x48 16.00 UNEVEN LANES		112.604	Northbound Rte. 5	1.00	16				
				WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		112.621	Northbound Rte. 5	1.00	16				
				WO6-3(48) 48x48 16.00 TWO-WAY TRAFFIC		113.391	Northbound Rte. 5	1.00	16				
				WO8-12 48x48 16.00 NO CENTER LINE		113.405	Northbound Rte. 5	1.00	16				
				WO8-11 48x48 16.00 UNEVEN		113.421	Northbound Rte. 5	1.00	16				

Revision 4/1/2020 Page 7 of 18



The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project	Line	DWR Date	Total Quantity	for Construction Signs (if application Sign Information	Station	Log	Location	Number	SF	Special	SF Each	Tota										
roject	Number	DVVR Date	Posted For DWR Date	Sign information	Station	Mile	Location	of Items	Each Sign	Sign	Special Sign	SF to										
P3379	0050	August 31,	1028	LANES																		
		2021		WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		113.440	Northbound Rte. 5	1.00	16													
				WO6-3(48) 48x48 16.00 TWO-WAY TRAFFIC		114.699	Northbound Rte. 5	1.00	16													
				WO8-11 48x48 16.00 UNEVEN LANES		114.719	Northbound Rte. 5	1.00	16													
			WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		114.739	Northbound Rte. 5	1.00	16														
				CONST-7-48 48x24 8.00 RATE OUR WORK ZONE		235.727	Southbound Rte. 5 lt.	-1.00	8													
				CONST-7-72 72x36 18.00 RATE OUR WORK ZONE		235.727	Southbound Rte. 5 lt.	1.00	18													
				WO8-12 48x48 16.00 NO CENTER LINE		237.710	Southbound Rte. 5	1.00	16													
				WO8-11 48x48 16.00 UNEVEN LANES		237.737	Southbound Rte. 5	1.00	16													
				WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		237.776	Southbound Rte. 5	1.00	16													
				WO6-3(48) 48x48 16.00 TWO-WAY TRAFFIC		238.758	Southbound Rte. 5	1.00	16													
				WO8-11 48x48 16.00 UNEVEN LANES		238.785	Southbound Rte. 5	1.00	16													
				WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		238.808	Southbound Rte. 5	1.00	16													
				WO6-3(48) 48x48 16.00 TWO-WAY TRAFFIC		239.678	Southbound Rte. 5	1.00	16													
				WO8-12 48x48 16.00 NO CENTER LINE		239.698	Southbound Rte. 5	1.00	16													
				WO8-11 48x48 16.00 UNEVEN LANES		239.720	Southbound Rte. 5	1.00	16													
				WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		239.750	Southbound Rte. 5	1.00	16													
														WO8-12 48x48 16.00 NO CENTER LINE		240.238	Southbound Rte. 5	1.00	16			
				WO8-11 48x48 16.00 UNEVEN LANES		240.256	Southbound Rte. 5	1.00	16													
				WO6-3(48) 48x48 16.00 TWO-WAY TRAFFIC		240.266	Southbound Rte. 5	1.00	16													
				WO6-3(48) 48x48 16.00 TWO-WAY TRAFFIC		241.362	Southbound Rte. 5	1.00	16													
				WO8-12 48x48 16.00 NO CENTER LINE		241.379	Southbound Rte. 5	1.00	16													
				WO8-11 48x48 16.00 UNEVEN LANES		241.393	Southbound Rte. 5	1.00	16													
				WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		241.417	Southbound Rte. 5	1.00	16													
				WO8-12 48x48 16.00 NO CENTER LINE		243.152	Southbound Rte. 5	1.00	16													
				WO8-11 48x48 16.00 UNEVEN LANES		243.162	Southbound Rte. 5	1.00	16													
				WO6-3(48) 48x48 16.00 TWO-WAY TRAFFIC		243.198	Southbound Rte. 5	1.00	16													
				WO6-3(48) 48x48 16.00 TWO-WAY TRAFFIC		244.353	Southbound Rte. 5	1.00	16													
				WO8-12 48x48 16.00 NO CENTER LINE		244.375	Southbound Rte. 5	1.00	16													
				WO8-11 48x48 16.00 UNEVEN LANES		244.397	Southbound Rte. 5	1.00	16													
				WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		244.418	Southbound Rte. 5	1.00	16													
				WO6-3(48) 48x48 16.00 TWO-WAY TRAFFIC		245.515	Southbound Rte. 5	1.00	16													

Revision 4/1/2020 Page 8 of 18



The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line are details for Construction Signs (if applicable). Project Line **DWR** Date **Total Quantity** Sign Information Log Location Number Special SF Each Total Posted For DWR Date Special Sign Number Mile of Items Each SF to Sign Post J5P3379 0050 August 31, 1028 WO8-11 48x48 16.00 UNEVEN 245.534 Southbound Rte. 5 1.00 16 16 2021 LANES WO20-6a 48x48 16.00 245.553 Southbound Rte. 5 1.00 16 16 RIGHT/CENTER/LEFT LANE CLOSED WO6-3(48) 48x48 16.00 TWO-WAY Southbound Rte. 5 1.00 16 16 246.464 WO8-12 48x48 16.00 NO CENTER 246.490 Southbound Rte. 5 1.00 16 16 LINE WO8-11 48x48 16.00 UNEVEN 246.515 Southbound Rte. 5 1.00 16 16 LANES WO20-6a 48x48 16.00 246.539 Southbound Rte. 5 1.00 16 16 RIGHT/CENTER/LEFT LANE CLOSED WO20-1 48x48 16.00 Hazel Road 1.00 16 16 ROAD/BRIDGE/RAMP WORK AHEAD WO20-1 48x48 16.00 September 15, 2021 274 Flagger 1.00 16 16 ROAD/BRIDGE/RAMP WORK AHEAD GO20-4 36x18 4.50 PILOT CAR FOLLOW ME Flagger 1.00 4.5 4.5 G020-5aP 36x24 6.00 WORK ZONE 2.00 6 12 Flagger (PLAQUE) GO20-4a 42x30 8.75 PLEASE WAIT 2.00 8.75 Flagger 17.5 FOR PILOT CAR R2-1 36x48 12.00 SPEED LIMIT 12 Flagger 2.00 24 WO20-7a 48x48 16.00 FLAGGER Flagger 2 00 16 32 WO3-4(48) 48x48 16.00 BE PREPARED TO STOP Flagger 2.00 16 32 WO20-4 48x48 16.00 ONE LANE ROAD AHEAD Flagger 2.00 16 32 WO20-5 48x48 16.00 Flagger 2.00 16 32 RIGHT/CENTER/LEFT LANE CLOSED AHEAD WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED Flagger 2.00 16 32 R4-7a 36x48 12.00 KEEP RIGHT 2.00 12 24 Flagger (HORIZONTAL ARROW) 0050 - Total

Revision 4/1/2020 Page 9 of 18



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3379	0020	MISC.	Other Item Adjustment	OTHR	13	Jan 3, 2022	snells1	\$6,111.00	This adjustment is for the Infrared Scanning on the project. Veta files and Summary Sheet are on file on e-projects. snells1
				OTHR - Tota	al			\$6,111.00	SIGIST
			Other Item	Adjustment -				\$6,111.00	
	0020 -	- Total						\$6,111.00	
	0030	MISC.	Other Item	INTC	13	Jan 3,	snells1	\$2,634.32	Veta projects and summary sheet on file in e-projects.
			Adjustment			2022			snells1
				INTC - Total				\$2,634.32	
			Other Item	Adjustment -	Total			\$2,634.32	
		- Total						\$2,634.32	
	0050	CONSTRUCTION SIGNS	Overrun	Overrun		Sep 16, 2021	SYSTEM	\$664.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user snells1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					7	Sep 16, 2021	SYSTEM	(\$664.00)	
					8	Oct 4, 2021	SYSTEM	(\$664.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					8	Oct 4, 2021	SYSTEM	\$664.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user snells1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					9	Oct 18, 2021	SYSTEM	(\$664.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					9	Oct 18, 2021	SYSTEM	\$664.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user snells1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				Overrun - T	otal			\$0.00	
			Overrun - T	otal				\$0.00	
	0050 -	- Total						\$0.00	
	0130	4 IN. YELLOW HIGH BUILD WATERBORNE							
	0130	HIGH BUILD WATERBORNE	Material		7	Sep 16, 2021	SYSTEM	\$3,855.24	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user snells1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
	0130	HIGH BUILD	Material		7		SYSTEM	\$3,855.24 (\$3,855.24)	Estimate Item Adjustment (0008) due to user snells1 overridding Payment
	0130	HIGH BUILD WATERBORNE	Material	- Total		2021 Sep 16,			Estimate Item Adjustment (0008) due to user snells1 overridding Payment
	0130	HIGH BUILD WATERBORNE	Material - To			2021 Sep 16,		(\$3,855.24)	Estimate Item Adjustment (0008) due to user snells1 overridding Payment
	0130	HIGH BUILD WATERBORNE				2021 Sep 16,		(\$3,855.24) \$0.00	Estimate Item Adjustment (0008) due to user snells1 overridding Payment
	0130	HIGH BUILD WATERBORNE	Material - To	otal REFL	7	2021 Sep 16, 2021	SYSTEM	(\$3,855.24) \$0.00 \$0.00 \$122.19	Estimate Item Adjustment (0008) due to user snells1 overridding Payment Estimate Exception 10 on the current Payment Estimate. Adjustment calculated from Retroreflectivity testing performed by 3rd. party.
	0130	HIGH BUILD WATERBORNE	Material - To Other Item Adjustment	otal REFL REFL - Tota	7 12	2021 Sep 16, 2021	SYSTEM	(\$3,855.24) \$0.00 \$0.00	Estimate Item Adjustment (0008) due to user snells1 overridding Payment Estimate Exception 10 on the current Payment Estimate. Adjustment calculated from Retroreflectivity testing performed by 3rd. party. Results and calculations can be found on e- projects.
	0130	HIGH BUILD WATERBORNE	Material - To Other Item Adjustment	otal REFL	7 12	2021 Sep 16, 2021	SYSTEM	(\$3,855.24) \$0.00 \$0.00 \$122.19 \$122.19	Estimate Item Adjustment (0008) due to user snells1 overridding Payment Estimate Exception 10 on the current Payment Estimate. Adjustment calculated from Retroreflectivity testing performed by 3rd. party. Results and calculations can be found on e- projects.
		HIGH BUILD WATERBORNE	Material - To Other Item Adjustment	otal REFL REFL - Tota	7 12	2021 Sep 16, 2021	SYSTEM	(\$3,855.24) \$0.00 \$0.00 \$122.19	Estimate Item Adjustment (0008) due to user snells1 overridding Payment Estimate Exception 10 on the current Payment Estimate. Adjustment calculated from Retroreflectivity testing performed by 3rd. party. Results and calculations can be found on e- projects.
		HIGH BUILD WATERBORNE PAINT Total 6 IN. WHITE HIGH BUILD WATERBORNE	Material - To Other Item Adjustment	otal REFL REFL - Tota	7 12	2021 Sep 16, 2021	SYSTEM	\$0.00 \$0.00 \$122.19 \$122.19	Estimate Item Adjustment (0008) due to user snells1 overridding Payment Estimate Exception 10 on the current Payment Estimate. Adjustment calculated from Retroreflectivity testing performed by 3rd. party. Results and calculations can be found on e- projects.
	0130	HIGH BUILD WATERBORNE PAINT Total 6 IN. WHITE HIGH BUILD	Material - To Other Item Adjustment	otal REFL REFL - Tota	7 12 Il Total	2021 Sep 16, 2021 Dec 16, 2021	SYSTEM snells1	\$0.00 \$0.00 \$122.19 \$122.19 \$122.19	Estimate Item Adjustment (0008) due to user snells1 overridding Payment Estimate Exception 10 on the current Payment Estimate. Adjustment calculated from Retroreflectivity testing performed by 3rd. party. Results and calculations can be found on e- projects. snells1 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user snells1 overridding Payment
	0130	HIGH BUILD WATERBORNE PAINT Total 6 IN. WHITE HIGH BUILD WATERBORNE	Material - To Other Item Adjustment	otal REFL REFL - Tota	7 12 Il Total	2021 Sep 16, 2021 Dec 16, 2021 Sep 16, 2021 Sep 16,	SYSTEM snells1	\$0.00 \$0.00 \$122.19 \$122.19 \$122.19 \$122.19 \$13,649.30	Estimate Item Adjustment (0008) due to user snells1 overridding Payment Estimate Exception 10 on the current Payment Estimate. Adjustment calculated from Retroreflectivity testing performed by 3rd. party. Results and calculations can be found on e- projects. snells1 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user snells1 overridding Payment
	0130	HIGH BUILD WATERBORNE PAINT Total 6 IN. WHITE HIGH BUILD WATERBORNE	Material - To Other Item Adjustment	REFL - Tota Adjustment -	7 12 Il Total	2021 Sep 16, 2021 Dec 16, 2021 Sep 16, 2021 Sep 16,	SYSTEM snells1	\$0.00 \$0.00 \$122.19 \$122.19 \$122.19 \$122.19 \$13,649.30	Estimate Item Adjustment (0008) due to user snells1 overridding Payment Estimate Exception 10 on the current Payment Estimate. Adjustment calculated from Retroreflectivity testing performed by 3rd. party. Results and calculations can be found on e- projects. snells1 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user snells1 overridding Payment
	0130	HIGH BUILD WATERBORNE PAINT Total 6 IN. WHITE HIGH BUILD WATERBORNE	Material - To Other Item Adjustment Other Item	REFL - Tota Adjustment -	7 12 Il Total 7	2021 Sep 16, 2021 Dec 16, 2021 Sep 16, 2021 Sep 16,	SYSTEM snells1	\$0.00 \$0.00 \$122.19 \$122.19 \$122.19 \$122.19 \$13,649.30 (\$13,649.30)	Estimate Item Adjustment (0008) due to user snells1 overridding Payment Estimate Exception 10 on the current Payment Estimate. Adjustment calculated from Retroreflectivity testing performed by 3rd. party. Results and calculations can be found on e- projects. snells1 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user snells1 overridding Payment Estimate Exception 12 on the current Payment Estimate. Adjustment calculated from Retroreflectivity testing performed by 3rd. party. Results and calculations can be found on e- projects.
	0130	HIGH BUILD WATERBORNE PAINT Total 6 IN. WHITE HIGH BUILD WATERBORNE	Material - To Other Item Adjustment Other Item Material Material - To Other Item	REFL - Tota Adjustment - - Total otal REFL	7 12 I Total 7	2021 Sep 16, 2021 Dec 16, 2021 Sep 16, 2021 Sep 16, 2021 Dec 16, 2021	system snells1 System System	\$0.00 \$0.00 \$122.19 \$122.19 \$122.19 \$122.19 \$13,649.30 (\$13,649.30) \$0.00 \$0.00 (\$30.46)	Estimate Item Adjustment (0008) due to user snells1 overridding Payment Estimate Exception 10 on the current Payment Estimate. Adjustment calculated from Retroreflectivity testing performed by 3rd. party. Results and calculations can be found on e- projects. snells1 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user snells1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
	0130	HIGH BUILD WATERBORNE PAINT Total 6 IN. WHITE HIGH BUILD WATERBORNE	Material - To Other Item Adjustment Other Item Adjustment Material - To Other Item Adjustment	REFL - Total Total REFL - Total REFL REFL	7 12 17 12 12 11 12 11	2021 Sep 16, 2021 Dec 16, 2021 Sep 16, 2021 Sep 16, 2021 Dec 16, 2021	system snells1 System System	\$0.00 \$0.00 \$122.19 \$122.19 \$122.19 \$122.19 \$13,649.30 (\$13,649.30) \$0.00	Estimate Item Adjustment (0008) due to user snells1 overridding Payment Estimate Exception 10 on the current Payment Estimate. Adjustment calculated from Retroreflectivity testing performed by 3rd. party. Results and calculations can be found on e- projects. snells1 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user snells1 overridding Payment Estimate Exception 12 on the current Payment Estimate. Adjustment calculated from Retroreflectivity testing performed by 3rd. party. Results and calculations can be found on e- projects.
	0130	HIGH BUILD WATERBORNE PAINT Total 6 IN. WHITE HIGH BUILD WATERBORNE PAINT	Material - To Other Item Adjustment Other Item Adjustment Material - To Other Item Adjustment	REFL - Tota Adjustment - - Total otal REFL	7 12 17 12 12 11 12 11	2021 Sep 16, 2021 Dec 16, 2021 Sep 16, 2021 Sep 16, 2021 Dec 16, 2021	system snells1 System System	\$0.00 \$0.00 \$122.19 \$122.19 \$122.19 \$122.19 \$13,649.30 (\$13,649.30) \$0.00 \$0.00 (\$30.46)	Estimate Item Adjustment (0008) due to user snells1 overridding Payment Estimate Exception 10 on the current Payment Estimate. Adjustment calculated from Retroreflectivity testing performed by 3rd. party. Results and calculations can be found on e- projects. snells1 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user snells1 overridding Payment Estimate Exception 12 on the current Payment Estimate. Adjustment calculated from Retroreflectivity testing performed by 3rd. party. Results and calculations can be found on e- projects.
	0130	HIGH BUILD WATERBORNE PAINT Total 6 IN. WHITE HIGH BUILD WATERBORNE	Material - To Other Item Adjustment Other Item Adjustment Material - To Other Item Adjustment	REFL - Total Total REFL - Total REFL REFL	7 12 17 12 12 11 12 11	2021 Sep 16, 2021 Dec 16, 2021 Sep 16, 2021 Sep 16, 2021 Dec 16, 2021	system snells1 System System	\$0.00 \$0.00 \$122.19 \$122.19 \$122.19 \$122.19 \$13,649.30 (\$13,649.30) \$0.00 \$0.00 (\$30.46)	Estimate Item Adjustment (0008) due to user snells1 overridding Payment Estimate Exception 10 on the current Payment Estimate. Adjustment calculated from Retroreflectivity testing performed by 3rd. party. Results and calculations can be found on e- projects. snells1 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user snells1 overridding Payment Estimate Exception 12 on the current Payment Estimate. Adjustment calculated from Retroreflectivity testing performed by 3rd. party. Results and calculations can be found on e- projects.
	0130	HIGH BUILD WATERBORNE PAINT Total 6 IN. WHITE HIGH BUILD WATERBORNE PAINT	Material - To Other Item Adjustment Other Item Adjustment Material - To Other Item Adjustment Other Item Adjustment	REFL - Total Total REFL - Total REFL REFL	7 12 Total 7 12 ITotal Total	2021 Sep 16, 2021 Dec 16, 2021 Sep 16, 2021 Sep 16, 2021 Dec 16, 2021	system snells1 System System	\$0.00 \$0.00 \$122.19 \$122.19 \$122.19 \$122.19 \$13,649.30 (\$13,649.30) \$0.00 (\$30.46)	Estimate Item Adjustment (0008) due to user snells1 overridding Payment Estimate Exception 10 on the current Payment Estimate. Adjustment calculated from Retroreflectivity testing performed by 3rd. party. Results and calculations can be found on e- projects. snells1 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user snells1 overridding Payment Estimate Exception 12 on the current Payment Estimate. Adjustment calculated from Retroreflectivity testing performed by 3rd. party. Results and calculations can be found on e- projects.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks							
J5P3379	0150	6 IN. YELLOW HIGH BUILD WATERBORNE	Other Item Adjustment	REFL - Tota	ı			\$2,791.99								
		PAINT	Other Item /	Adjustment -	Total			\$2,791.99								
	0150 -	Total						\$2,791.99								
	0270	MISC. AGGREGATE FOR BASE	Material		5	Aug 16, 2021	SYSTEM	\$34,143.23	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user snells1 overridding Payment Estimate Exception 1 on the current Payment Estimate.							
					5	Aug 16, 2021	SYSTEM	(\$34,143.23)								
					6	Sep 2, 2021	SYSTEM	\$61,745.04	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user snells1 overridding Payment Estimate Exception 1 on the current Payment Estimate.							
					6	Sep 2, 2021	SYSTEM	(\$61,745.04)								
					7	Sep 16, 2021	SYSTEM	\$61,745.04	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user snells1 overridding Payment Estimate Exception 1 on the current Payment Estimate.							
					7	Sep 16, 2021	SYSTEM	(\$61,745.04)								
					8	Oct 4, 2021	SYSTEM	\$61,745.04	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user snells1 overridding Payment Estimate Exception 1 on the current Payment Estimate.							
					8	Oct 4, 2021	SYSTEM	(\$61,745.04)								
					9	Oct 18, 2021	SYSTEM	\$61,745.04	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user snells1 overridding Payment Estimate Exception 1 on the current Payment Estimate.							
					9	Oct 18, 2021	SYSTEM	(\$61,745.04)								
				- Total				\$0.00								
			Material - To	otal				\$0.00								
			Overrun	Overrun	5	Aug 16, 2021	SYSTEM	\$14,653.55	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) overridding Payment Estimate Exception 8 on the current Payment Estimate. Material Insufficiency Quantity 1354.890; Overrun Quantity Balance 581.49.							
					5	Aug 16, 2021	SYSTEM	(\$14,653.55)								
					6	Sep 2, 2021	SYSTEM	(\$14,653.55)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).							
					6	Sep 2, 2021	SYSTEM	\$27,601.81	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) overridding Payment Estimate Exception 11 on the current Payment Estimate. Material Insufficiency Quantity 2450.200; Overrun Quantity Balance 1676.80.							
					6	Sep 2, 2021	SYSTEM	\$14,653.55	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 11 on the current Payment Estimate. Material Insufficiency Quantity 2450.200; Overrun Quantity Balance 1676.80.							
					6	Sep 2, 2021	SYSTEM	(\$27,601.81)								
					7	Sep 16, 2021	SYSTEM	(\$42,255.36)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).							
						7	Sep 16, 2021	SYSTEM	\$42,255.36	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 15 on the current Payment Estimate. Material Insufficiency Quantity 2450.200; Overrun Quantity Balance 1676.80.						
					8	Oct 4, 2021	SYSTEM	(\$42,255.36)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).							
												8	Oct 4, 2021	SYSTEM	\$42,255.36	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 11 on the current Payment Estimate. Material Insufficiency Quantity 2450.200; Overrun Quantity Balance 1676.80.
					9	Oct 18, 2021	SYSTEM	(\$42,255.36)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).							
					9	Oct 18, 2021	SYSTEM	\$42,255.36	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 11 on the current Payment Estimate. Material Insufficiency Quantity 2450.200; Overrun Quantity Balance 1676.80.							



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																													
J5P3379	0270	MISC. AGGREGATE	Overrun	Overrun - T	otal			\$0.00																														
	FOR BASE	Overrun - T	otal				\$0.00																															
	0270 - Total						\$0.00																															
	0280	GRAVEL (A) OR CRUSHED STONE (B)	Material		6	Sep 2, 2021	SYSTEM	\$756.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user snells1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																													
					6	Sep 2, 2021	SYSTEM	(\$756.00)																														
					7	Sep 16, 2021	SYSTEM	\$756.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user snells1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																													
					7	Sep 16, 2021	SYSTEM	(\$756.00)																														
					8	Oct 4, 2021	SYSTEM	\$756.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user snells1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																													
					8	Oct 4, 2021	SYSTEM	(\$756.00)																														
					9	Oct 18, 2021	SYSTEM	\$756.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user snells1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																													
					9	Oct 18, 2021	SYSTEM	(\$756.00)																														
			Material - T	- Total				\$0.00																														
				otal				\$0.00																														
	0280 -	Total						\$0.00																														
	0290	BIT. PAVEMENT MIXTURE PG64-22 (BP-1)	RE		6	Sep 2, 2021	SYSTEM	\$95,588.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user snells1 overridding Payment Estimate Exception 3 on the current Payment Estimate.																													
					6	Sep 2, 2021	SYSTEM	(\$95,588.54)																														
					7	Sep 16, 2021	SYSTEM	\$95,588.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user snells1 overridding Payment Estimate Exception 3 on the current Payment Estimate.																													
					7	Sep 16, 2021	SYSTEM	(\$95,588.54)																														
					8	Oct 4, 2021	SYSTEM	\$95,588.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user snells1 overridding Payment Estimate Exception 3 on the current Payment Estimate.																													
					8	Oct 4, 2021	SYSTEM	(\$95,588.54)																														
					9	Oct 18, 2021	SYSTEM	\$95,588.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user snells1 overridding Payment Estimate Exception 3 on the current Payment Estimate.																													
					9	Oct 18, 2021	SYSTEM	(\$95,588.54)																														
																																		10	10	Nov 2, 2021	SYSTEM	\$95,586.75
					10	Nov 2, 2021	SYSTEM	(\$95,586.75)																														
					11	Nov 16, 2021	SYSTEM	\$95,586.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user snells1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																													
					11	Nov 16, 2021	SYSTEM	(\$95,586.75)																														
					12	Dec 16, 2021	SYSTEM	\$95,586.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user snells1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																													
					12	Dec 16, 2021	SYSTEM	(\$95,586.75)																														
					13	Jan 3, 2022	SYSTEM	\$95,586.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user snells1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																													
					13	Jan 3,	SYSTEM	(\$95,586.75)																														



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3379	0290	BIT. PAVEMENT MIXTURE	Material			2022			
		PG64-22 (BP-1)			14	Jan 18, 2022	SYSTEM	\$95,586.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user snells1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					14	Jan 18, 2022	SYSTEM	(\$95,586.75)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Other Item Adjustment		5	Aug 16, 2021	snells1	\$24,075.34	Adjustment for material placed from 08/02/21 to 08/15/21 snells1
					6	Sep 2, 2021	snells1	\$17,773.11	This covers material placed between 08/16/2021 and 09/01/2021 snells1
					10	Nov 2, 2021	snells1	(\$0.13)	This Adjustment is being made to correct the AC Adjustment made on Estimate 0006 for this contract. The quantity reported was reduced on estimate 0010 due to rounding. This adjustment corrects the adjustment made on estimate 0006.
									snells1
				ACAD - Tota	al			\$41,848.32	
				FUEL	10	Nov 2, 2021	snells1	(\$0.10)	This Adjustment is being made to correct the system adjustment applied to this estimate. Quantity entered for this estimate is for rounding purposes only. The material was placed in August of 2021 so the Fuel Factor was different. An additional adjustment has been entered to zero out the System Generated Adjustment on this estimate.
									snells1
					10	Nov 2, 2021	snells1	\$0.12	This Adjustment is being made to override the system adjustment applied to this estimate. Quantity entered for this estimate is for rounding purposes only. The material was placed in August of 2021 so the Fuel Factor was different. This adjustment zeroes out the system adjustment applied to this estimate. A new fuel adjustment will be added to this estimate using the correct fuel factor.
									snells1
				FUEL - Tota	ıl			\$0.02	
			Other Item						
			Other Item	Adjustment -	Total			\$41,848.34	
			Other Item A	Adjustment -	Total	Aug 16, 2021	SYSTEM	\$41,848.34 \$19,265.80	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			Price	Adjustment -			SYSTEM SYSTEM		Reference Item Price Adjustment Index Adjustment Type applied is FUEL Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			Price	Adjustment -	5	2021 Sep 2,		\$19,265.80	, , , , , ,
			Price	- Adjustment -	5	2021 Sep 2, 2021 Nov 2,	SYSTEM	\$19,265.80 \$14,222.58	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			Price	- Total	5	2021 Sep 2, 2021 Nov 2,	SYSTEM	\$19,265.80 \$14,222.58 (\$0.12)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
	0290 -	- Total	Price FUEL	- Total	5	2021 Sep 2, 2021 Nov 2,	SYSTEM	\$19,265.80 \$14,222.58 (\$0.12) \$33,488.26	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
	0290 - 0300	ASPHALTIC CONCRETE MIXTURE PG	Price FUEL	- Total	5	2021 Sep 2, 2021 Nov 2,	SYSTEM	\$19,265.80 \$14,222.58 (\$0.12) \$33,488.26 \$33,488.26	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
		ASPHALTIC CONCRETE	Price FUEL	- Total	5 6 10	2021 Sep 2, 2021 Nov 2, 2021	SYSTEM	\$19,265.80 \$14,222.58 (\$0.12) \$33,488.26 \$75,336.60	Reference Item Price Adjustment Index Adjustment Type applied is FUEL Reference Item Price Adjustment Index Adjustment Type applied is FUEL This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user ellist2 overridding Payment
		ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C	Price FUEL	- Total	5 6 10	2021 Sep 2, 2021 Nov 2, 2021 Aug 3, 2021	SYSTEM SYSTEM SYSTEM	\$19,265.80 \$14,222.58 (\$0.12) \$33,488.26 \$33,488.26 \$75,336.60 \$825,979.04	Reference Item Price Adjustment Index Adjustment Type applied is FUEL Reference Item Price Adjustment Index Adjustment Type applied is FUEL This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user ellist2 overridding Payment
		ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C	Price FUEL	- Total	5 6 10	2021 Sep 2, 2021 Nov 2, 2021 Aug 3, 2021 Aug 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$19,265.80 \$14,222.58 (\$0.12) \$33,488.26 \$33,488.26 \$75,336.60 \$825,979.04	Reference Item Price Adjustment Index Adjustment Type applied is FUEL Reference Item Price Adjustment Index Adjustment Type applied is FUEL This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user ellist2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user snells1 overridding Payment
		ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C	Price FUEL	- Total	5 6 10 4 4 5	2021 Sep 2, 2021 Nov 2, 2021 Aug 3, 2021 Aug 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$19,265.80 \$14,222.58 (\$0.12) \$33,488.26 \$33,488.26 \$75,336.60 \$825,979.04 (\$825,979.04) \$1,911,449.70	Reference Item Price Adjustment Index Adjustment Type applied is FUEL Reference Item Price Adjustment Index Adjustment Type applied is FUEL This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user ellist2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user snells1 overridding Payment
		ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C	Price FUEL	- Total	5 6 10 4 4 5	2021 Sep 2, 2021 Nov 2, 2021 Aug 3, 2021 Aug 16, 2021 Aug 16, 2021 Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$19,265.80 \$14,222.58 (\$0.12) \$33,488.26 \$33,488.26 \$75,336.60 \$825,979.04 (\$825,979.04) \$1,911,449.70 (\$1,911,449.70)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL Reference Item Price Adjustment Index Adjustment Type applied is FUEL This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user ellist2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user snells1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user snells1 overridding Payment Estimate Item Adjustment (0011) due to user snells1 overridding Payment
		ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C	Price FUEL	- Total	5 6 10 4 4 5 5 6	2021 Sep 2, 2021 Nov 2, 2021 Aug 3, 2021 Aug 16, 2021 Sep 2, 2021 Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$19,265.80 \$14,222.58 (\$0.12) \$33,488.26 \$33,488.26 \$75,336.60 \$825,979.04 (\$825,979.04) \$1,911,449.70 (\$1,911,449.70)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL Reference Item Price Adjustment Index Adjustment Type applied is FUEL This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user ellist2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user snells1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user snells1 overridding Payment Estimate Item Adjustment (0011) due to user snells1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3379	CONCRETE MIXTURE PG	Material	Туре	8	Oct 4, 2021	SYSTEM	\$955,584.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user snells1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
		70-22 (SP125C MIX)			8	Oct 4, 2021	SYSTEM	(\$955,584.30)	Zamilac Zacopacia i sir no carron aj non Zamilaco
					9	Oct 18, 2021	SYSTEM	\$955,584.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user snells1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					9	Oct 18, 2021	SYSTEM	(\$955,584.30)	
					10	Nov 2, 2021	SYSTEM	\$955,582.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user snells1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					10	Nov 2, 2021	SYSTEM	(\$955,582.45)	
					11	Nov 16, 2021	SYSTEM	\$955,582.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user snells1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					11	Nov 16, 2021	SYSTEM	(\$955,582.45)	
					12	Dec 16, 2021	SYSTEM	\$955,582.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user snells1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					12	Dec 16, 2021	SYSTEM	(\$955,582.45)	
					13	Jan 3, 2022	SYSTEM	\$955,582.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user snells1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					13	Jan 3, 2022	SYSTEM	(\$955,582.45)	
					14	Jan 18, 2022	SYSTEM	\$955,582.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user snells1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					14	Jan 18, 2022	SYSTEM	(\$955,582.45)	
				- Total				\$0.00	
			Material - To					\$0.00	
			Other Item Adjustment			Aug 3, 2021	ellist2	\$39,210.84	AC price adjustment from 7/16/2021 to 8/01/2021 ellist2
					5	Aug 16, 2021	snells1	\$60,000.00	Adjustment for material placed from 08/02/21 to 08/15/21 snells1
					10	Nov 2, 2021	snells1	(\$0.09)	This Adjustment is being made to correct the AC Adjustment made on Estimate 0006 for this contract. The quantity reported was reduced on estimate 0010 due to rounding. This adjustment corrects the adjustment made on estimate 0006.
				ACAD To	-1			600 040 75	snells1
				ACAD - Tota		Nov 2, 2021	snells1	\$99,210.75 (\$0.10)	This Adjustment is being made to correct the system adjustment applied to this estimate. Quantity entered for this estimate is for rounding purposes only. The material was placed in August of 2021 so the Fuel Factor was different. An additional adjustment has been entered to zero out the System Generated Adjustment on this estimate.
									snells1
					10	Nov 2, 2021	snells1	\$0.12	This Adjustment is being made to override the system adjustment applied to this estimate. Quantity entered for this estimate is for rounding purposes only. The material was placed in August of 2021 so the Fuel Factor was different. This adjustment zeroes out the system adjustment applied to this estimate. A new fuel adjustment will be added to this estimate using the correct fuel factor. snells1
				FUEL - Tota	ıl			\$0.02	onoile i
			Other Item	Adjustment -				\$99,210.77	
			Overrun	Overrun		Aug 16,	SYSTEM	(\$75,988.77)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
						2021			



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3379	0300	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C	Overrun	Overrun	5	Aug 16, 2021	SYSTEM	\$75,988.77	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 7 on the current Payment Estimate. Material Insufficiency Quantity 31075.430; Overrun Quantity Balance 1169.13.
		MIX)			6	Sep 2, 2021	SYSTEM	(\$75,854.59)	Averaged Price Adjustment from this item on all previous payment estimates of '3.37123' is applied (if non-zero).
					6	Sep 2, 2021	SYSTEM	\$75,854.59	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) overridding Payment Estimate Exception 12 on the current Payment Estimate. Material Insufficiency Quantity 31075.430; Overrun Quantity Balance 1169.13.
					7	Sep 16, 2021	SYSTEM	(\$75,854.59)	Averaged Price Adjustment from this item on all previous payment estimates of '3.37123' is applied (if non-zero).
					7	Sep 16, 2021	SYSTEM	\$75,854.59	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 16 on the current Payment Estimate. Material Insufficiency Quantity 15535.430; Overrun Quantity Balance 1169.13.
					8	Oct 4, 2021	SYSTEM	(\$75,854.59)	Averaged Price Adjustment from this item on all previous payment estimates of '3.37123' is applied (if non-zero).
					8	Oct 4, 2021	SYSTEM	\$75,854.59	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 12 on the current Payment Estimate. Material Insufficiency Quantity 15535.430; Overrun Quantity Balance 1169.13.
					9	Oct 18, 2021	SYSTEM	(\$75,854.59)	Averaged Price Adjustment from this item on all previous payment estimates of '3.37123' is applied (if non-zero).
					9	Oct 18, 2021	SYSTEM	\$75,854.59	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 12 on the current Payment Estimate. Material Insufficiency Quantity 15535.430; Overrun Quantity Balance 1169.13.
				Overrun - To	otal			\$0.00	
			Overrun - To	Total	4	Aug 3,	SYSTEM	\$0.00 \$43,244.72	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			FUEL		5	2021 Aug 16,	SYSTEM	\$61,517.64	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					10	2021 Nov 2,	SYSTEM	(\$0.12)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total		2021		\$104,762.24	
			Price FUEL					\$104,762.24	
	0300 -	Total						\$203,973.01	
	0310	MISC.	Material	aterial	4	Aug 3, 2021	SYSTEM	\$37,502.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user ellist2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					4	Aug 3, 2021	SYSTEM	(\$37,502.38)	
					5	Aug 16, 2021	SYSTEM	\$37,502.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user snells1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					5	Aug 16, 2021	SYSTEM	(\$37,502.38)	
					6	Sep 2, 2021	SYSTEM	\$37,502.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user snells1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					6	Sep 2, 2021	SYSTEM	(\$37,502.38)	
					7	Sep 16, 2021	SYSTEM	\$37,502.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user snells1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					7	Sep 16, 2021	SYSTEM	(\$37,502.38)	
					8	Oct 4, 2021	SYSTEM	\$37,502.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user snells1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					8	Oct 4, 2021	SYSTEM	(\$37,502.38)	
					9	Oct 18, 2021	SYSTEM	\$37,502.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user snells1 overridding Payment Estimate Exception 5 on the current Payment Estimate.



Project	Lina	Deceriation	Adiustos	Other	Eat	Crostad	Croctad	Amerint	Domestic
	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3379	0310	MISC.	Material		9	Oct 18, 2021	SYSTEM	(\$37,502.38)	
					10	Nov 2, 2021	SYSTEM	\$37,502.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user snells1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					10	Nov 2, 2021	SYSTEM	(\$37,502.38)	
					11	Nov 16, 2021	SYSTEM	\$37,502.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user snells1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					11	Nov 16, 2021	SYSTEM	(\$37,502.38)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
		- Total						\$0.00	
	0320	TACK COAT	Material		5	Aug 16, 2021	SYSTEM	\$7,344.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user snells1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					5	Aug 16, 2021	SYSTEM	(\$7,344.00)	
					6	Sep 2, 2021	SYSTEM	\$13,424.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user snells1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					6	Sep 2, 2021	SYSTEM	(\$13,424.00)	
					7	Sep 16, 2021	SYSTEM	\$13,424.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user snells1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					7	Sep 16, 2021	SYSTEM	(\$13,424.00)	
					8	Oct 4, 2021	SYSTEM	\$13,424.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user snells1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					8	Oct 4, 2021	SYSTEM	(\$13,424.00)	
					9	Oct 18, 2021	SYSTEM	\$13,424.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user snells1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					9	Oct 18,	SYSTEM	(\$13,424.00)	
						2021			
				- Total		2021		\$0.00	
			Material - To			2021		\$0.00 \$0.00	
	0320 -	Total						\$0.00 \$0.00	
	0320 -	Total MISC. NON STANDARD TACK COAT			4		SYSTEM	\$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user ellist2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		MISC. NON STANDARD			4	Aug 3,	SYSTEM	\$0.00 \$0.00	Estimate Item Adjustment (0009) due to user ellist2 overridding Payment
		MISC. NON STANDARD			4 4 5	Aug 3, 2021		\$0.00 \$0.00 \$15,956.00	Estimate Item Adjustment (0009) due to user ellist2 overridding Payment
		MISC. NON STANDARD				Aug 3, 2021 Aug 3, 2021 Aug 16,	SYSTEM	\$0.00 \$0.00 \$15,956.00 (\$15,956.00)	Estimate Item Adjustment (0009) due to user ellist2 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user snells1 overridding Payment
		MISC. NON STANDARD			5	Aug 3, 2021 Aug 3, 2021 Aug 16, 2021	SYSTEM SYSTEM	\$0.00 \$0.00 \$15,956.00 (\$15,956.00) \$35,992.00	Estimate Item Adjustment (0009) due to user ellist2 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user snells1 overridding Payment
		MISC. NON STANDARD			5	Aug 3, 2021 Aug 3, 2021 Aug 16, 2021 Aug 16, 2021 Sep 2,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$15,956.00 (\$15,956.00) \$35,992.00	Estimate Item Adjustment (0009) due to user ellist2 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user snells1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user snells1 overridding Payment
		MISC. NON STANDARD			5 6	Aug 3, 2021 Aug 3, 2021 Aug 16, 2021 Sep 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$15,956.00 (\$15,956.00) \$35,992.00 (\$35,992.00) \$35,992.00	Estimate Item Adjustment (0009) due to user ellist2 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user snells1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user snells1 overridding Payment
		MISC. NON STANDARD			5 5 6	Aug 3, 2021 Aug 3, 2021 Aug 16, 2021 Sep 2, 2021 Sep 2, 2021 Sep 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$15,956.00 (\$15,956.00) \$35,992.00 (\$35,992.00) (\$35,992.00)	Estimate Item Adjustment (0009) due to user ellist2 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user snells1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user snells1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user snells1 overridding Payment Estimate Item Adjustment (0014) due to user snells1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J5P3379	0330	MISC. NON	Material						Estimate Exception 7 on the current Payment Estimate.	
		STANDARD TACK COAT			8	Oct 4, 2021	SYSTEM	(\$35,992.00)		
					9	Oct 18, 2021	SYSTEM	\$35,992.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user snells1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
					9	Oct 18, 2021	SYSTEM	(\$35,992.00)		
				- Total				\$0.00		
			Material - To	otal				\$0.00		
	0330 -	Total						\$0.00		
	0335	PCCP CRACK FILLING	Material		1	Jun 16, 2021	SYSTEM	\$55,397.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user snells1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					1	Jun 16, 2021	SYSTEM	(\$55,397.10)		
					2	Jun 30, 2021	SYSTEM	\$127,389.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user snells1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					2	Jun 30, 2021	SYSTEM	(\$127,389.90)		
					3	Jul 16, 2021	SYSTEM	\$127,389.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user snells1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
			Material - To		3	Jul 16, 2021	SYSTEM	(\$127,389.90)		
					4	Aug 3, 2021	SYSTEM	\$127,389.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user ellist2 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
					4	Aug 3, 2021	SYSTEM	(\$127,389.90)		
					5	Aug 16, 2021	SYSTEM	\$127,389.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user snells1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	
					5	Aug 16, 2021	SYSTEM	(\$127,389.90)		
						6	Sep 2, 2021	SYSTEM	\$127,389.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user snells1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					6	Sep 2, 2021	SYSTEM	(\$127,389.90)		
				- Total				\$0.00		
				otal				\$0.00		
	0335 -	Total						\$0.00		
	0370	MGS HEIGHT AND BLOCK TRANSITION	Material		6	Sep 2, 2021	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user snells1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	
					6	Sep 2, 2021	SYSTEM	(\$1,000.00)		
					7	Sep 16, 2021	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user snells1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	
					7	Sep 16, 2021	SYSTEM	(\$1,000.00)		
					8	Oct 4, 2021	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user snells1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	
					8	Oct 4, 2021	SYSTEM	(\$1,000.00)		
					9	Oct 18, 2021	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user snells1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	
					9	Oct 18, 2021	SYSTEM	(\$1,000.00)		
				- Total				\$0.00		





Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
				Туре					
J5P3379	0370	MGS HEIGHT AND BLOCK TRANSITION	Material - To	otal				\$0.00	
	0370 -	Total						\$0.00	
	5002	FURN & PLACE CONC MATL FOR FULL	Material		12	Dec 16, 2021	SYSTEM	\$5,355.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user snells1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
		DEPTH			12	Dec 16, 2021	SYSTEM	(\$5,355.00)	
					13	Jan 3, 2022	SYSTEM	\$5,355.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user snells1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					13	Jan 3, 2022	SYSTEM	(\$5,355.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	5002 -	Total						\$0.00	
J5P3379 -	Total							\$290,938.65	
Overall -	Total							\$290,938.65	