

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 20, 2021

Progress Estimate Number Contract ID 201218-B02 Pay Period Start October 1, 201		\$2,014,127.80
Prime Contractor Mid-River Asphalt, Inc. Pay Period End October 15, 20	21 Net Change Order Amount	(\$200.01)
	Current Contract Amount	\$2,013,927.79

Approval Date		By User
October 20, 2021	Generated and Approved (and should be considered Draft) at the Project Office Level by	haggaj1
October 20, 2021	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	baxtem1
October 21, 2021	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
November 1, 2021	November 1, 2021		95.80%

Date Description	Original Completion Date	Current Completion Date
Acceptance Date		
Awarded Date	January 6, 2021	January 6, 2021
Letting Date	December 18, 2020	December 18, 2020
Notice to Proceed Date	March 8, 2021	March 8, 2021
Work Began Date		

Contract Informational Dates

Date Description	Original Completion Date	Current Completion Date	Days Remaining on Milestone	Diary Charge Days
Milestone - Calendar Time - JSP B - Calendar Days, J2P3201	August 19, 2021	August 19, 2021	Milestone Complete	
Milestone - Calendar Time - JSP B - Calendar Days, J2S3189	August 24, 2021	August 24, 2021	Milestone Complete	
Milestone - Calendar Time - JSP B - Calendar Days, J2S3308	August 25, 2021	August 25, 2021	Milestone Complete	

Milestones

Contract Total Pa	y For Estimate No. 7			
		This Estimate	Previous	To Date
201218-B02				
	Total Posted Items Pay	\$3,650.59	\$1,925,763.07	\$1,929,413.66
	Gross Item Adjustments	\$8,400.85	\$112,709.38	\$121,110.23
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	•	-	\$2,038,472.45	\$2,050,523.89
Contract Total Pa	yable This Estimate:	\$12,051.44		

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J2P3201	0040	6161005	CONSTRUCTION SIGNS	SQFT	\$4.500	97	\$436.50
Project J2P3	201 - Total						\$436.50
J2S3189	0130	4091048	EMULSIFIED ASPHALT, SEAL COAT	GAL	\$1.980	-555	(\$1,098.90)
	0160	6161005	CONSTRUCTION SIGNS	SQFT	\$4.500	97	\$436.50
Project J2S3	189 - Total						(\$662.40)
J2S3238	0230	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	TONS	\$50.800	1	\$50.80
	0320	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	SQYD	\$8.000	182	\$1,456.00
Project J2S3	238 - Total						\$1,506.80
J2S3303	0350	4071005	TACK COAT	GAL	\$1.930	-97	(\$187.21)
Project J2S3	303 - Total						(\$187.21)
J2S3308	0470	4091048	EMULSIFIED ASPHALT, SEAL COAT	GAL	\$1.980	555	\$1,098.90
	0500	6161005	CONSTRUCTION SIGNS	SQFT	\$4.500	324	\$1,458.00
Project J2S3	308 - Total						\$2,556.90
Overall - Tota	al						\$3,650.59

Revision 4/1/2020 Page 1 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 20, 2021

Progress Estimate Number 7 Contract ID 201218-B02 Pay Period Start October 1, 2021 Original Contract Amount \$2,014,127.80 Pay Period End October 15, 2021 Net Change Order Amount (\$200.01) \$2,013,927.79

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Project	Line	Item Description	Adjustment	Other Item	Comments	Adjustment	Line Item	Adjustment
Number	No.	nom Besonption	Туре	Adjustment Type	Comments	Quantity	Adjustment Unit Price	amount
J2P3201	0020	SEAL COAT AGGREGATE, GRADE A2	Other Item Adjustment	Other	5% of the final quantity of line item pay was withheld on previous estimates, pending completion of CRE2.0 Reports by the contractor. This adjustment restores withheld pay.			\$7,209.97
	0110	24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-48	\$10.00	(\$480.00)
	0110	24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user haggaj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	48	\$10.00	\$480.00
J2S3189	0140	SEAL COAT AGGREGATE, GRADE A2	Other Item Adjustment	Other	5% of the final quantity of line item pay was withheld on previous estimates, pending completion of CRE2.0 Reports by the contractor. This adjustment restores withheld pay.			\$2,302.55
J2S3238	0230	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	1	\$3.35	\$3.35
	0230	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Other Item Adjustment	Fuel Price	Quantity correction had to be made to this item for 1 ton of asphalt. Because the DWR where the correction was posted was a different estimate period then that in which the material was placed and accepted, the SYSTEM generated Fuel Adjustment was in error when checked with manual calculations. This adjustment corrects the total Fuel Adjustment paid in AWP for this Line Item to the total manually calculated.			(\$0.66)
J2S3303	0330	MISC.	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-528.39	\$11.52	(\$6,087.05)
	0410	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material			-30	\$25.00	(\$750.00)
	0410	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user haggaj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	30	\$25.00	\$750.00
	0420	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material			-1	\$350.00	(\$350.00)
	0420	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user haggaj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	1	\$350.00	\$350.00
J2S3308	0480	SEAL COAT AGGREGATE, GRADE A2	Other Item Adjustment	Other	5% of the final quantity of line item pay was withheld on previous estimates, pending completion of CRE2.0 Reports by the contractor. This adjustment restores withheld			\$4,972.69

Revision 4/1/2020 Page 2 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 20, 2021

Progre	ess Est	imate Number 7	Contract ID Prime Contr	20121a ctor Mid-Ri		Pay Period Start October 1, 2021 Pay Period End October 15, 2021 N	Net Ch		Amount (\$20	00.01)
Project Number	Line No.	Item Desc	cription	Adjustment Type	Other Item Adjustment Type	Comments		Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
							pay.			
Total										\$8,400.85

Revision 4/1/2020 Page 3 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Information				
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work			
J2P3201	FAF-79-1(80)	Seal coat	79	LINCOLN	from Pike County line	to Route N near Winfield				
J2S3189	FAS- S202(017)	Seal coat	EE	LINCOLN	from Route Y to Rout	e 47 near Winfield				
J2S3238	FAS S201(65)	Resurface	W	LINCOLN	from Route B to Rout	e KK near Brussells				
J2S3303	FAS S201(74)	Resurface	В	LINCOLN	from Route 61 to Rou	ite 79 at Elsberry				
J2S3308	FAS- S202(018)	Seal coat	Е	LINCOLN	from Route O north ju	unction to Route UU in Silex				
otals by .	Job Numbers									
J2P3201	Posted Ite	n Adjustments	s Gross Ite	m Pay	This Estimate \$436.50 \$7,209.97 \$7,646.47	Previous \$361,568.02 \$12,074.22 \$373,642.24	To Date \$362,004.52 \$19,284.19 \$381,288.71			
	Liquidate	<u> </u>			\$0.00 \$0.00	0 \$0.00 0 \$0.00				
J2S3189	Posted Ite	n Adjustments	s Gross Ite	m Pay	This Estimate (\$662.40) \$2,302.55 \$1,640.15	Previous \$101,690.70 \$2,745.03 \$104,435.73	To Date \$101,028.30 \$5,047.58 \$106,075.88			
		ive d Damages ntract Adjustm	ents		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00			
J2S3238	Posted Ite	n Adjustments	s Gross Ite	m Pay	This Estimate \$1,506.80 \$2.69 \$1,509.49	Previous \$446,049.20 \$35,491.48 \$481,540.68	To Date \$447,556.00 \$35,494.17 \$483,050.17			
		ive d Damages ntract Adjustm	ents		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00			
J2S3303	Posted Ite	n Adjustments	s Gross Ite	m Pay	This Estimate (\$187.21) (\$6,087.05) (\$6,274.26)	Previous \$814,033.25 \$57,119.92 \$871,153.17	To Date \$813,846.04 \$51,032.87 \$864,878.91			
		ive d Damages ntract Adjustm	ents		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00			
J2S3308	Posted Ite	m Adjustments	s Gross Iter	m Pay	This Estimate \$2,556.90 \$4,972.69 \$7,529.59	Previous \$202,421.90 \$5,278.73 \$207,700.63	To Date \$204,978.80 \$10,251.42 \$215,230.22			
		ive d Damages ntract Adjustm	ents		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00			

Revision 4/1/2020 Page 4 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J2S3303, Item 6200015, Project Item Line Number 0410, Material Set 620001596, Material 1048PMPFWH - Performed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Material was accepted for use on project. Sample Records could not be authorized prior to estimate generation.	haggaj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3303, Item 6200021, Project Item Line Number 0420, Material Set 620002196, Material 1048PMPFWHXX - Pref Mrk Tape Direct Indicat or Shape WH, Acceptance Action Generic 1048PMPFWHXX is insufficient.	Material was accepted for use on project. Sample Records could not be authorized prior to estimate generation.	haggaj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J2P3201, Item 6206124A, Project Item Line Number 0110, Material Set 6206124A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient.	Material was accepted for use on project. Sample Records could not be authorized prior to estimate generation.	haggaj1	Overridden
Estimate Exception Type: Item Overrun: Contract 201218-B02, Contract Project J2S3303, Project Item Line Number 0330, Contract Line Item Number 0330, Item 3049910, Minor Item.	No Remark was entered by Engineer	haggaj1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 201218-B02, Contract Project J2S3303, Project Item Line Number 0340, Contract Line Item Number 0340, Item 4020520, Minor Item.	No Remark was entered by Engineer	haggaj1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 201218-B02, Contract Project J2S3238, Project Item Line Number 0240, Contract Line Item Number 0240, Item 4071005, Minor Item.	No Remark was entered by Engineer	haggaj1	Acknowledged

Revision 4/1/2020 Page 5 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

tract Project No.			aseu on R	eport Generated date and can differ from the posted amo	unt at the t	ime the	Louinate wa	s Gener	ated.		
	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
B02 J2P3201	0001	0010	4091048	EMULSIFIED ASPHALT, SEAL COAT	72,828.00	0.00	72,828.00	GAL	72,444.00	\$1.98	\$143,439.12
	0001	0020	4094002	SEAL COAT AGGREGATE, GRADE A2	260,100.00	0.00	260,100.00	SQYD	260,100.00	\$0.68	\$176,868.00
	0001	0030	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$1.00	\$0.00
	0001	0040	6161005	CONSTRUCTION SIGNS	2,220.00	0.00	2,220.00	SQFT	870.00	\$4.50	\$3,915.00
	0001	0050	6161009	FLAG ASSEMBLY	4.00	-4.00	0.00	EA	0.00	\$10.00	\$0.00
	0001	0060	6161025	CHANNELIZER (TRIM LINE)	100.00	0.00	100.00	EA	0.00	\$20.00	\$0.00
	0001	0070	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$1,500.00	\$3,000.00
	0001	0800	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$7,200.00	\$7,200.00
	0001	0090	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING	174,008.00	0.00	174,008.00	LF	174,008.00	\$0.10	\$17,400.80
	0001	0100	6206001C	PAINT, TYPE P BEADS 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	94,616.00	0.00	94,616.00	LF	94,616.00	\$0.10	\$9,461.60
	0001	0110	6206124A	24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	48.00	0.00	48.00	LF	48.00	\$10.00	\$480.00
	0001	0120	6209903	MISC.6" WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	48.00	0.00	48.00	LF	48.00	\$5.00	\$240.00
Project .	2P3201 - To	tal Value	Posted to D	ate as of Report Generated Date							\$362,004.52
J2S3189	0001	0130	4091048	EMULSIFIED ASPHALT, SEAL COAT	18,962.00	0.00	18,962.00	GAL	17,883.00	\$1.98	\$35,408.34
	0001	0140	4094002	SEAL COAT AGGREGATE, GRADE A2	67,722.00	0.00	67,722.00	SQYD	67,722.00	\$0.68	\$46,050.96
	0001	0150	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$1.00	\$0.00
	0001	0160	6161005	CONSTRUCTION SIGNS	990.00	0.00	990.00	SQFT	574.00	\$4.50	\$2,583.00
	0001	0170	6161009	FLAG ASSEMBLY	4.00	-4.00	0.00	EA	0.00	\$10.00	\$0.00
	0001	0180	6161025	CHANNELIZER (TRIM LINE)	100.00	0.00	100.00	EA	0.00	\$1.00	\$0.00
	0001	0190	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$7,200.00	\$7,200.00
	0001	0200	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	55,408.00	0.00	55,408.00	LF	55,408.00	\$0.10	\$5,540.80
	0001	0210	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT	42,452.00	0.00	42,452.00	LF	42,452.00	\$0.10	\$4,245.20
Project	2S3189 - To	tal Value	Posted to D	MARKING PAINT, TYPE P BEADS ate as of Report Generated Date							\$101,028.30
J2S3238	0001	0220	3105002	GRAVEL (A) OR CRUSHED STONE (B)	518.00	0.00	518.00	TONS	190.34	\$34.00	\$6,471.56
		0230	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	8,274.80	0.00	8,274.80	TONS	7,429.56	\$50.80	\$377,421.65
	0001	0200				0.00	===	GAL			
	0001	0240	4071005	TACK COAT	7,574.00	0.00	7,574.00	GAL	7,753.00	\$1.93	\$14,963.29
			4071005 6123000A	TACK COAT TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	7,574.00	0.00	2.00	EA	7,753.00 2.00	\$1.93 \$1.00	\$14,963.29 \$2.00
	0001	0240							,		
	0001	0240	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$1.00	\$2.00
	0001 0001 0001	0240 0250 0260	6123000A 6161005	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) CONSTRUCTION SIGNS	2.00	0.00	2.00	EA SQFT	2.00	\$1.00 \$4.50	\$2.00 \$3,285.00
	0001 0001 0001 0001	0240 0250 0260 0270	6123000A 6161005 6161009	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) CONSTRUCTION SIGNS FLAG ASSEMBLY	2.00 1,691.00 4.00	0.00 0.00 -4.00	2.00 1,691.00 0.00	EA SQFT EA	2.00 730.00 0.00 0.00	\$1.00 \$4.50 \$10.00	\$2.00 \$3,285.00 \$0.00
	0001 0001 0001 0001 0001	0240 0250 0260 0270 0280	6123000A 6161005 6161009 6161025	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) CONSTRUCTION SIGNS FLAG ASSEMBLY CHANNELIZER (TRIM LINE)	2.00 1,691.00 4.00 100.00	0.00 0.00 -4.00 0.00	2.00 1,691.00 0.00 100.00	EA SQFT EA	2.00 730.00 0.00 0.00	\$1.00 \$4.50 \$10.00 \$1.00	\$2.00 \$3,285.00 \$0.00 \$0.00
	0001 0001 0001 0001 0001	0240 0250 0260 0270 0280 0290	6123000A 6161005 6161009 6161025 6181000 6206000C	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) CONSTRUCTION SIGNS FLAG ASSEMBLY CHANNELIZER (TRIM LINE) MOBILIZATION 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING	2.00 1,691.00 4.00 100.00	0.00 0.00 -4.00 0.00	2.00 1,691.00 0.00 100.00	EA SQFT EA EA	2.00 730.00 0.00 0.00	\$1.00 \$4.50 \$10.00 \$1.00 \$25,430.00	\$2.00 \$3,285.00 \$0.00 \$0.00 \$25,430.00
	0001 0001 0001 0001 0001 0001	0240 0250 0260 0270 0280 0290	6123000A 6161005 6161009 6161025 6181000 6206000C	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) CONSTRUCTION SIGNS FLAG ASSEMBLY CHANNELIZER (TRIM LINE) MOBILIZATION 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT	2.00 1,691.00 4.00 100.00 1.00 82,262.00	0.00 0.00 -4.00 0.00 0.00	2.00 1,691.00 0.00 100.00 1.00 82,262.00	EA SQFT EA EA LS LF	2.00 730.00 0.00 0.00 1.00 82,262.00	\$1.00 \$4.50 \$10.00 \$1.00 \$25,430.00 \$0.10	\$2.00 \$3,285.00 \$0.00 \$0.00 \$25,430.00 \$8,226.20
Project	0001 0001 0001 0001 0001 0001 0001 000	0240 0250 0260 0270 0280 0290 0300 0310 0320	6123000A 6161005 6161009 6161025 6181000 6206000C 6206001C 6224010	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) CONSTRUCTION SIGNS FLAG ASSEMBLY CHANNELIZER (TRIM LINE) MOBILIZATION 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS MODIFIED COLDMILLING (DEPTH TRANSITIONS) ate as of Report Generated Date	2.00 1,691.00 4.00 100.00 1.00 82,262.00 75,883.00	0.00 0.00 -4.00 0.00 0.00 0.00	2.00 1,691.00 0.00 100.00 1.00 82,262.00 75,883.00	EA SQFT EA EA LS LF LF SQYD	2.00 730.00 0.00 0.00 1.00 82,262.00 75,883.00	\$1.00 \$4.50 \$10.00 \$1.00 \$25,430.00 \$0.10	\$2.00 \$3,285.00 \$0.00 \$0.00 \$25,430.00 \$8,226.20 \$7,588.30
Project J2S3303	0001 0001 0001 0001 0001 0001 0001 0001 283238 - To	0240 0250 0260 0270 0280 0290 0300 0310	6123000A 6161005 6161009 6161025 6181000 6206000C 6206001C 6224010	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) CONSTRUCTION SIGNS FLAG ASSEMBLY CHANNELIZER (TRIM LINE) MOBILIZATION 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS MODIFIED COLDMILLING (DEPTH TRANSITIONS)	2.00 1,691.00 4.00 100.00 1.00 82,262.00 75,883.00	0.00 0.00 -4.00 0.00 0.00 0.00	2.00 1,691.00 0.00 100.00 1.00 82,262.00 75,883.00	EA SQFT EA EA LS LF	2.00 730.00 0.00 0.00 1.00 82,262.00 75,883.00	\$1.00 \$4.50 \$10.00 \$1.00 \$25,430.00 \$0.10	\$2.00 \$3,285.00 \$0.00 \$0.00 \$25,430.00 \$8,226.20 \$7,588.30 \$4,168.00
	0001 0001 0001 0001 0001 0001 0001 000	0240 0250 0260 0270 0280 0290 0300 0310 0320	6123000A 6161005 6161009 6161025 6181000 6206000C 6206001C 6224010	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) CONSTRUCTION SIGNS FLAG ASSEMBLY CHANNELIZER (TRIM LINE) MOBILIZATION 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS MODIFIED COLDMILLING (DEPTH TRANSITIONS) ate as of Report Generated Date	2.00 1,691.00 4.00 100.00 1.00 82,262.00 75,883.00	0.00 0.00 -4.00 0.00 0.00 0.00	2.00 1,691.00 0.00 100.00 1.00 82,262.00 75,883.00	EA SQFT EA EA LS LF LF SQYD	2.00 730.00 0.00 0.00 1.00 82,262.00 75,883.00 521.00	\$1.00 \$4.50 \$10.00 \$1.00 \$25,430.00 \$0.10 \$8.00	\$2.00 \$3,285.00 \$0.00 \$0.00 \$25,430.00 \$8,226.20 \$7,588.30 \$4,168.00
	0001 0001 0001 0001 0001 0001 0001 0001 0001	0240 0250 0260 0270 0280 0290 0300 0310 0320 otal Value	6123000A 6161005 6161009 6161025 6181000 6206000C 6206001C 6224010 Posted to D	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) CONSTRUCTION SIGNS FLAG ASSEMBLY CHANNELIZER (TRIM LINE) MOBILIZATION 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS MODIFIED COLDMILLING (DEPTH TRANSITIONS) ate as of Report Generated Date MISC.PERMANENT AGGREGATE EDGE TREATMENT BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE	2.00 1,691.00 4.00 100.00 1.00 82,262.00 75,883.00 800.00	0.00 0.00 -4.00 0.00 0.00 0.00 0.00	2.00 1,691.00 0.00 100.00 1.00 82,262.00 75,883.00 800.00	EA SQFT EA EA LS LF LF SQYD	2.00 730.00 0.00 0.00 1.00 82,262.00 75,883.00 521.00	\$1.00 \$4.50 \$10.00 \$1.00 \$25,430.00 \$0.10 \$8.00	\$2.00 \$3,285.00 \$0.00 \$0.00 \$25,430.00 \$8,226.20 \$7,588.30 \$4,168.00 \$70,297.23
	0001 0001 0001 0001 0001 0001 0001 0001 0001 0001	0240 0250 0260 0270 0280 0290 0300 0310 0320 stal Value 0330 0340	6123000A 6161005 6161009 6161025 6181000 6206000C 6206001C 6224010 Posted to D 3049910 4020520	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) CONSTRUCTION SIGNS FLAG ASSEMBLY CHANNELIZER (TRIM LINE) MOBILIZATION 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS MODIFIED COLDMILLING (DEPTH TRANSITIONS) ate as of Report Generated Date MISC.PERMANENT AGGREGATE EDGE TREATMENT BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	2.00 1,691.00 4.00 100.00 1.00 82,262.00 75,883.00 800.00	0.00 0.00 -4.00 0.00 0.00 0.00 0.00	2.00 1,691.00 0.00 100.00 1.00 82,262.00 75,883.00 800.00	EA SQFT EA LS LF LF SQYD TONS	2.00 730.00 0.00 0.00 1.00 82,262.00 75,883.00 521.00 6,102.19	\$1.00 \$4.50 \$10.00 \$1.00 \$25,430.00 \$0.10 \$8.00 \$11.52 \$51.76	\$2.00 \$3,285.00 \$0.00 \$0.00 \$25,430.00 \$8,226.20 \$7,588.30 \$4,168.00 \$70,297.23 \$667,652.24
	0001 0001 0001 0001 0001 0001 0001 0001 0001 0001 0001	0240 0250 0260 0270 0280 0290 0300 0310 0320 0340 0350	6123000A 6161005 6161009 6161025 6181000 6206000C 6206001C 6224010 Posted to D 3049910 4020520 4071005	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) CONSTRUCTION SIGNS FLAG ASSEMBLY CHANNELIZER (TRIM LINE) MOBILIZATION 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS MODIFIED COLDMILLING (DEPTH TRANSITIONS) ate as of Report Generated Date MISC.PERMANENT AGGREGATE EDGE TREATMENT BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT	2.00 1,691.00 4.00 100.00 1.00 82,262.00 75,883.00 800.00 5,573.80 12,722.60	0.00 0.00 -4.00 0.00 0.00 0.00 0.00 0.00 0.00	2.00 1,691.00 0.00 100.00 1.00 82,262.00 75,883.00 800.00 5,573.80 12,722.60	EA SQFT EA LS LF LF SQYD TONS TONS GAL	2.00 730.00 0.00 0.00 1.00 82,262.00 75,883.00 521.00 6,102.19 12,899.00 13,673.00	\$1.00 \$4.50 \$10.00 \$1.00 \$25,430.00 \$0.10 \$8.00 \$11.52 \$51.76 \$1.93	\$2.00 \$3,285.00 \$0.00 \$0.00 \$25,430.00 \$8,226.20 \$7,588.30 \$4,168.00 \$70,297.23 \$667,652.24
	0001 0001 0001 0001 0001 0001 0001 000	0240 0250 0260 0270 0280 0290 0300 0310 0320 stal Value 0330 0340 0350 0360	6123000A 6161005 6161009 6161025 6181000 6206000C 6206001C 6224010 Posted to D 3049910 4020520 4071005 6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) CONSTRUCTION SIGNS FLAG ASSEMBLY CHANNELIZER (TRIM LINE) MOBILIZATION 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS MODIFIED COLDMILLING (DEPTH TRANSITIONS) ate as of Report Generated Date MISC.PERMANENT AGGREGATE EDGE TREATMENT BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00 1,691.00 4.00 100.00 1.00 82,262.00 75,883.00 800.00 5,573.80 12,722.60 13,878.00 2.00	0.00 0.00 -4.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00	2.00 1,691.00 0.00 100.00 1.00 82,262.00 75,883.00 800.00 5,573.80 12,722.60 13,878.00 2.00	EA SQFT EA EA LS LF LF SQYD TONS TONS GAL EA	2.00 730.00 0.00 0.00 1.00 82,262.00 75,883.00 521.00 6,102.19 12,899.00 13,673.00	\$1.00 \$4.50 \$10.00 \$1.00 \$25,430.00 \$0.10 \$8.00 \$11.52 \$51.76 \$1.93 \$1.00	\$2.00 \$3,285.00 \$0.00 \$0.00 \$25,430.00 \$8,226.20 \$7,588.30 \$4,168.00 \$70,297.23 \$667,652.24 \$26,388.89 \$0.00
	0001 0001 0001 0001 0001 0001 0001 000	0240 0250 0260 0270 0280 0290 0300 0310 0320 0340 0350 0360 0370	6123000A 6161005 6161009 6161025 6181000 6206000C 6206001C 6224010 Posted to D 3049910 4020520 4071005 6123000A 6161005	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) CONSTRUCTION SIGNS FLAG ASSEMBLY CHANNELIZER (TRIM LINE) MOBILIZATION 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS MODIFIED COLDMILLING (DEPTH TRANSITIONS) ate as of Report Generated Date MISC.PERMANENT AGGREGATE EDGE TREATMENT BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) CONSTRUCTION SIGNS	2.00 1,691.00 4.00 100.00 1.00 82,262.00 75,883.00 800.00 5,573.80 12,722.60 13,878.00 2.00 2,218.00	0.00 0.00 -4.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00	2.00 1,691.00 0.00 100.00 1.00 82,262.00 75,883.00 800.00 5,573.80 12,722.60 13,878.00 2.00 2,218.00	EA SQFT EA LS LF LF SQYD TONS TONS GAL EA SQFT	2.00 730.00 0.00 0.00 1.00 82,262.00 75,883.00 521.00 6,102.19 12,899.00 13,673.00 0.00	\$1.00 \$4.50 \$10.00 \$1.00 \$25,430.00 \$0.10 \$8.00 \$11.52 \$51.76 \$1.93 \$1.00 \$4.50	\$2.00 \$3,285.00 \$0.00 \$0.00 \$0.00 \$25,430.00 \$8,226.20 \$7,588.30 \$4,168.00 \$70,297.23 \$667,652.24 \$26,388.89 \$0.00 \$4,065.75
	0001 0001 0001 0001 0001 0001 0001 000	0240 0250 0260 0270 0280 0290 0300 0310 0320 0340 0350 0360 0370 0380	6123000A 6161005 6161009 6161025 6181000 6206000C 6206001C 6224010 Posted to D 3049910 4020520 4071005 6123000A 6161005 6161009	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) CONSTRUCTION SIGNS FLAG ASSEMBLY CHANNELIZER (TRIM LINE) MOBILIZATION 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS MODIFIED COLDMILLING (DEPTH TRANSITIONS) ate as of Report Generated Date MISC.PERMANENT AGGREGATE EDGE TREATMENT BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) CONSTRUCTION SIGNS FLAG ASSEMBLY	2.00 1,691.00 4.00 100.00 1.00 82,262.00 75,883.00 800.00 5,573.80 12,722.60 13,878.00 2.00 2,218.00 4.00	0.00 0.00 -4.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00	2.00 1,691.00 0.00 100.00 1.00 82,262.00 75,883.00 800.00 5,573.80 12,722.60 13,878.00 2.00 2,218.00 0.00	EA SQFT EA LS LF LF SQYD TONS TONS GAL EA SQFT EA	2.00 730.00 0.00 0.00 1.00 82,262.00 75,883.00 521.00 6,102.19 12,899.00 13,673.00 0.00	\$1.00 \$4.50 \$10.00 \$1.00 \$25,430.00 \$0.10 \$8.00 \$11.52 \$51.76 \$1.93 \$1.00 \$4.50 \$10.00	\$2.00 \$3,285.00 \$0.00 \$0.00 \$0.00 \$25,430.00 \$8,226.20 \$7,588.30 \$4,168.00 \$70,297.23 \$667,652.24 \$26,388.89 \$0.00 \$4,065.75 \$0.00

Page 6 of 16 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
201218-B02	J2S3303	0001	0420	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	1.00	0.00	1.00	EA	1.00	\$350.00	\$350.00
		0001	0430	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	100,912.00	0.00	100,912.00	LF	100,912.00	\$0.10	\$10,091.20
		0001	0440	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	43,143.00	0.00	43,143.00	LF	43,143.00	\$0.10	\$4,314.30
		0001	0450	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	15,988.00	0.00	15,988.00	SQYD	5,486.50	\$0.82	\$4,498.93
		0001	0460	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	1,438.00	0.00	1,438.00	SQYD	375.00	\$0.82	\$307.50
	Project J	2S3303 - To	tal Value	Posted to D	vate as of Report Generated Date							\$813,846.04
	J2S3308	0001	0470	4091048	EMULSIFIED ASPHALT, SEAL COAT	40,952.00	0.00	40,952.00	GAL	39,590.00	\$1.98	\$78,388.20
		0001	0480	4094002	SEAL COAT AGGREGATE, GRADE A2	146,255.00	0.00	146,255.00	SQYD	137,440.00	\$0.68	\$93,459.20
		0001	0490	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$1.00	\$0.00
		0001	0500	6161005	CONSTRUCTION SIGNS	1,632.00	0.00	1,632.00	SQFT	1,253.00	\$4.50	\$5,638.50
		0001	0510	6161009	FLAG ASSEMBLY	4.00	-4.00	0.00	EA	0.00	\$10.00	\$0.00
		0001	0520	6161025	CHANNELIZER (TRIM LINE)	100.00	0.00	100.00	EA	0.00	\$1.00	\$0.00
		0001	0530	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$7,200.00	\$7,200.00
		0001	0540	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	111,633.00	0.00	111,633.00	LF	111,633.00	\$0.10	\$11,163.30
		0001	0550	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	91,296.00	0.00	91,296.00	LF	91,296.00	\$0.10	\$9,129.60
	Project J	2S3308 - To	tal Value	Posted to D	vate as of Report Generated Date							\$204,978.80
201218-B02 Ove	erall - Total	Value Pos	ted to Dat	te as of Repo	ort Generated Date							\$1,929,413.66

Page 7 of 16 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work,

D	roi	200	٠.	12	D31	201

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted		Location	Offset/ Distance	Offset/ Distance	Comments
0040	6161005	CONSTRUCTION SIGNS	10/1/21	10/20/21	97.00	SQFT	Quantity Correction, Signs used on Route 79.			

Project: J2S3189

Line Number	Item Code	Description		DWR Approval Date		Units	Location	From Station/ Log Mile	Offset/ Distance	Offset/ Distance	Comments
0130	4091048	EMULSIFIED ASPHALT, SEAL COAT	10/1/21	10/20/21	-555.00	GAL	Quantity Correction, Route EE				
0160	6161005	CONSTRUCTION SIGNS	10/1/21	10/20/21	97.00	SQFT	Quantity Correction, Signs used on Route EE				

Project: J2S3238

Line Number	Item Code	Description	DWR Date	DWR Approval Date		Units	Location		Offset/ Distance	Comments
0230	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SUR	10/1/21	10/20/21	1.00	TONS	Quantity Correction.			
0320	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	10/1/21	10/20/21	182.00	SQYD	Quantity Correction.			

Project: J2S3303

Line Number	Item Code	Description			Quantity Posted			Offset/ Distance		Comments
0350	4071005	TACK COAT	10/1/21	10/20/21	-97.00	GAL	Quantity Correction			

Project: J2S3308

Line Number	Item Code	Description		DWR Approval Date		Units	Location	Offset/ Distance	Offset/ Distance	Comments
0470	4091048	EMULSIFIED ASPHALT, SEAL COAT	10/1/21	10/20/21	555.00	GAL	Quantity Correction.			
0500	6161005	CONSTRUCTION SIGNS	10/1/21	10/20/21	324.00	SQFT	Quantity Correction, Signs Used On Route E			

<u>The information below this line are details for Construction Signs (if applicable).</u>

No Data Available

Revision 4/1/2020 Page 8 of 16



Droinet	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
Project	Line	Description	Type	Adjustment Type	Number	Date	By	Amount	remarks
J2P3201	0010	EMULSIFIED ASPHALT,	Other Item Adjustment	ACAD	2	Aug 2, 2021	haggaj1	\$19,284.19	Adjustment calculated using department approved methods with the following factors: 72444 Gallons at 60 Degrees F.
		SEAL COAT		ACAD - Tota	al			\$19,284.19	
				OTHR	2	Aug 2, 2021	haggaj1	(\$28,687.80)	Per Section 409, Seal Coat Work may not be accepted until 14 Days after completion of the work. Per direction from MoDOT Management, 20% Withheld and will be paid back to contractor upon acceptance of the work.
					3	Aug 15, 2021	haggaj1	\$28,687.80	20% was withheld on previous estimate, pending acceptance of Seal Coat work. This Adjustment releases the withheld amount.
				OTHR - Tota	al			\$0.00	
			Other Item	Adjustment -	Total			\$19,284.19	
	0010 -	Total						\$19,284.19	
	0020	SEAL COAT	Material		2	Aug 2	SYSTEM	\$176,868.00	This adjustment affects the original system generated Material Doyment
	0020	AGGREGATE, GRADE A2	Material		2	Aug 2, 2021	STSTEW	\$170,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user haggaj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					2	Aug 2, 2021	SYSTEM	(\$176,868.00)	
					3	Aug 16, 2021	SYSTEM	\$176,868.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user phillf2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					3	Aug 16, 2021	SYSTEM	(\$176,868.00)	
					4	Sep 2, 2021	SYSTEM	\$176,868.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user haggaj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					4	Sep 2, 2021	SYSTEM	(\$176,868.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Other Item Adjustment	OTHR	2	Aug 2, 2021	haggaj1	(\$35,373.60)	Per Section 409, Seal Coat Work may not be accepted until 14 Days after completion of the work. Per direction from MoDOT Management, 20% Withheld and will be paid back to contractor upon acceptance of the work.
					3	Aug 15, 2021	haggaj1	\$28,163.63	20% was withheld on previous estimate, pending acceptance of Seal Coat work. Seal Coat has been accepted and this Adjustment releases the withheld amount except 5% being withheld due to CRE2O report has not been submitted as of this estimate. A total payment of \$28,163.63 will be released on estimate 0003.
					7	Oct 20, 2021	haggaj1	\$7,209.97	5% of the final quantity of line item pay was withheld on previous estimates, pending completion of CRE2.0 Reports by the contractor. This adjustment restores withheld pay.
				OTHR - Tota	al			\$0.00	
			Other Item /	Adjustment -	Total			\$0.00	
	0020 -	Total						\$0.00	
	0090	WATERBORNE PAVEMENT	Material		4	Sep 2, 2021	SYSTEM	\$17,400.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user haggaj1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
		MARKING			4	Sep 2, 2021	SYSTEM	(\$17,400.80)	
					5	Sep 16, 2021	SYSTEM	\$17,400.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user haggaj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					5	Sep 16, 2021	SYSTEM	(\$17,400.80)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Other Item Adjustment	OTHR	4	Sep 2, 2021	haggaj1	(\$8,700.00)	This adjustment is to withhold a portion pavement marking pay. This portion will be paid after acceptance for retroreflectivity.
					6	Oct 1, 2021	haggaj1	\$8,700.00	40% was withheld on Estimate 0004 pending retroreflectivity testing. Testing was completed and material met retroreflectivity specifications. This adjustment is to pay the contractor the withheld amount
				OTHR - Tota	al			\$0.00	
			Other Item	Adjustment -	Total			\$0.00	
	0090 -	Total						\$0.00	



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J2P3201	0100	4 IN. YELLOW WATERBORNE PAVEMENT	Material	.,,,,,	4	Sep 2, 2021	SYSTEM	\$9,461.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user haggaj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
		MARKING			4	Sep 2, 2021	SYSTEM	(\$9,461.60)	
					5	Sep 16, 2021	SYSTEM	\$9,461.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user haggaj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					5	Sep 16, 2021	SYSTEM	(\$9,461.60)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Other Item Adjustment	OTHR	4	Sep 2, 2021	haggaj1	(\$4,700.00)	This adjustment is to withhold a portion pavement marking pay. This portion will be paid after acceptance for retroreflectivity.
					6	Oct 1, 2021	haggaj1	\$4,700.00	40% was withheld on Estimate 0004 pending retroreflectivity testing. Testing was completed and material met retroreflectivity specifications. This adjustment is to pay the contractor the withheld amount
				OTHR - Tota	ıl			\$0.00	
			Other Item	Adjustment -	Total			\$0.00	
	0100 -	- Total						\$0.00	
	0110	24 IN. WHITE WATERBORNE PAVEMENT	Material		6	Oct 1, 2021	SYSTEM	\$480.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user haggaj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
		MARKING			6	Oct 1, 2021	SYSTEM	(\$480.00)	
					7	Oct 20, 2021	SYSTEM	\$480.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user haggaj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					7	Oct 20, 2021	SYSTEM	(\$480.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0110 -	- Total						\$0.00	
J2P3201 -	Total							\$19,284.19	
								♥10,±04.10	
J2S3189	0130	EMULSIFIED ASPHALT, SEAL COAT	Other Item Adjustment	ACAD	2	Aug 2, 2021	haggaj1	\$5,047.58	Adjustment calculated using department approved methods with the following factors: 18962 Gallons at 60 Degrees F.
J2S3189	0130			ACAD - Tota			haggaj1		
J2S3189	0130	ASPHALT,			al		haggaj1	\$5,047.58	
J2S3189	0130	ASPHALT,		ACAD - Tota	al	2021 Aug 2,		\$5,047.58 \$5,047.58	factors: 18962 Gallons at 60 Degrees F. Per Section 409, Seal Coat Work may not be accepted until 14 Days after completion of the work. Per direction from MoDOT Management, 20%
J2S3189	0130	ASPHALT,	Adjustment	ACAD - Total	2 3	Aug 2, 2021 Aug 15,	haggaj1	\$5,047.58 \$5,047.58 (\$7,508.95)	factors: 18962 Gallons at §0 Degrees F. Per Section 409, Seal Coat Work may not be accepted until 14 Days after completion of the work. Per direction from MoDOT Management, 20% Withheld and will be paid back to contractor upon acceptance of the work. 20% was withheld on previous estimate, pending acceptance of Seal Coat
J2S3189		ASPHALT, SEAL COAT	Adjustment	ACAD - Tota OTHR	2 3	Aug 2, 2021 Aug 15,	haggaj1	\$5,047.58 \$5,047.58 (\$7,508.95) \$7,508.95 \$0.00 \$5,047.58	factors: 18962 Gallons at §0 Degrees F. Per Section 409, Seal Coat Work may not be accepted until 14 Days after completion of the work. Per direction from MoDOT Management, 20% Withheld and will be paid back to contractor upon acceptance of the work. 20% was withheld on previous estimate, pending acceptance of Seal Coat
J2S3189		ASPHALT,	Adjustment	ACAD - Total	al 2 3 al Total	Aug 2, 2021 Aug 15,	haggaj1	\$5,047.58 \$5,047.58 (\$7,508.95) \$7,508.95 \$0.00	factors: 18962 Gallons at §0 Degrees F. Per Section 409, Seal Coat Work may not be accepted until 14 Days after completion of the work. Per direction from MoDOT Management, 20% Withheld and will be paid back to contractor upon acceptance of the work. 20% was withheld on previous estimate, pending acceptance of Seal Coat
J2S3189		ASPHALT, SEAL COAT	Adjustment	ACAD - Total	2 3	Aug 2, 2021 Aug 15,	haggaj1	\$5,047.58 \$5,047.58 (\$7,508.95) \$7,508.95 \$0.00 \$5,047.58	factors: 18962 Gallons at §0 Degrees F. Per Section 409, Seal Coat Work may not be accepted until 14 Days after completion of the work. Per direction from MoDOT Management, 20% Withheld and will be paid back to contractor upon acceptance of the work. 20% was withheld on previous estimate, pending acceptance of Seal Coat
J2S3189	0130 -	ASPHALT, SEAL COAT -Total SEAL COAT AGGREGATE,	Adjustment Other Item	ACAD - Total	al 2 3 al Total	Aug 2, 2021 Aug 15, 2021 Aug 2, 2021	haggaj1	\$5,047.58 \$5,047.58 (\$7,508.95) \$7,508.95 \$0.00 \$5,047.58	factors: 18962 Gallons at 80 Degrees F. Per Section 409, Seal Coat Work may not be accepted until 14 Days after completion of the work. Per direction from MoDOT Management, 20% Withheld and will be paid back to contractor upon acceptance of the work. 20% was withheld on previous estimate, pending acceptance of Seal Coat work. This Adjustment releases the withheld amount. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user haggaj1 overridding Payment
J2S3189	0130 -	ASPHALT, SEAL COAT -Total SEAL COAT AGGREGATE,	Adjustment Other Item	ACAD - Total	3 3 Total	Aug 2, 2021 Aug 15, 2021 Aug 2, 2021 Aug 2, 2021 Aug 2, 4 2021	haggaj1 haggaj1 SYSTEM	\$5,047.58 \$5,047.58 (\$7,508.95) \$7,508.95 \$0.00 \$5,047.58 \$5,047.58 \$46,050.96	factors: 18962 Gallons at 80 Degrees F. Per Section 409, Seal Coat Work may not be accepted until 14 Days after completion of the work. Per direction from MoDOT Management, 20% Withheld and will be paid back to contractor upon acceptance of the work. 20% was withheld on previous estimate, pending acceptance of Seal Coat work. This Adjustment releases the withheld amount. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user haggaj1 overridding Payment
J2S3189	0130 -	ASPHALT, SEAL COAT -Total SEAL COAT AGGREGATE,	Adjustment Other Item	ACAD - Total	3 3 Total 2	Aug 2, 2021 Aug 15, 2021 Aug 2, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16, 4	haggaj1 haggaj1 SYSTEM	\$5,047.58 \$5,047.58 (\$7,508.95) \$7,508.95 \$0.00 \$5,047.58 \$5,047.58 \$46,050.96	factors: 18962 Gallons at 60 Degrees F. Per Section 409, Seal Coat Work may not be accepted until 14 Days after completion of the work. Per direction from MoDOT Management, 20% Withheld and will be paid back to contractor upon acceptance of the work. 20% was withheld on previous estimate, pending acceptance of Seal Coat work. This Adjustment releases the withheld amount. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user haggaj1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user phillf2 overridding Payment
J2S3189	0130 -	ASPHALT, SEAL COAT -Total SEAL COAT AGGREGATE,	Adjustment Other Item	ACAD - Total	3 3 3 1 Total 2 2 2 3	Aug 2, 2021 Aug 15, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16, 2021 Aug 16, 4021	haggaj1 haggaj1 SYSTEM SYSTEM SYSTEM	\$5,047.58 \$5,047.58 (\$7,508.95) \$7,508.95 \$0.00 \$5,047.58 \$5,047.58 \$46,050.96 (\$46,050.96)	factors: 18962 Gallons at 60 Degrees F. Per Section 409, Seal Coat Work may not be accepted until 14 Days after completion of the work. Per direction from MoDOT Management, 20% Withheld and will be paid back to contractor upon acceptance of the work. 20% was withheld on previous estimate, pending acceptance of Seal Coat work. This Adjustment releases the withheld amount. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user haggaj1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user phillf2 overridding Payment
J2S3189	0130 -	ASPHALT, SEAL COAT -Total SEAL COAT AGGREGATE,	Adjustment Other Item	ACAD - Total	3 3 1 Total 2 2 3 3 3	Aug 2, 2021 Aug 15, 2021 Aug 2, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16, 2021 Aug 16, 2021 Sep 2,	haggaj1 haggaj1 SYSTEM SYSTEM SYSTEM	\$5,047.58 \$5,047.58 (\$7,508.95) \$7,508.95 \$0.00 \$5,047.58 \$5,047.58 \$46,050.96 (\$46,050.96) (\$46,050.96)	factors: 18962 Gallons at 60 Degrees F. Per Section 409, Seal Coat Work may not be accepted until 14 Days after completion of the work. Per direction from MoDOT Management, 20% Withheld and will be paid back to contractor upon acceptance of the work. 20% was withheld on previous estimate, pending acceptance of Seal Coat work. This Adjustment releases the withheld amount. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user haggaj1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user phillf2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
			Туре	Adjustment Type	Number	Date	Ву		
J2S3189	0140	SEAL COAT	Material - To	otal				\$0.00	
		AGGREGATE, GRADE A2	Other Item Adjustment	OTHR	2	Aug 2, 2021	haggaj1	(\$9,210.19)	Per Section 409, Seal Coat Work may not be accepted until 14 Days after completion of the work. Per direction from MoDOT Management, 20% Withheld and will be paid back to contractor upon acceptance of the work.
					3	Aug 15, 2021	haggaj1	\$6,907.64	20% was withheld on previous estimate, pending acceptance of Seal Coat work. Seal Coat has been accepted and this Adjustment releases the withheld amount except 5% being withheld due to CRE20 report has not been submitted as of this estimate. A total payment of \$6,907.64 will be released on estimate 0003.
					7	Oct 20, 2021	haggaj1	\$2,302.55	5% of the final quantity of line item pay was withheld on previous estimates, pending completion of CRE2.0 Reports by the contractor. This adjustment restores withheld pay.
				OTHR - Tota	al			\$0.00	
			Other Item	Adjustment -	Total			\$0.00	
	0140 -	· Total						\$0.00	
	0200	4 IN. WHITE WATERBORNE PAVEMENT	Material		4	Sep 2, 2021	SYSTEM	\$5,540.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user haggaj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
		MARKING			4	Sep 2, 2021	SYSTEM	(\$5,540.80)	
					5	Sep 16, 2021	SYSTEM	\$5,540.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user haggaj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					5	Sep 16, 2021	SYSTEM	(\$5,540.80)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Other Item Adjustment	OTHR	4	Sep 2, 2021	haggaj1	(\$2,700.00)	This adjustment is to withhold a portion pavement marking pay. This portion will be paid after acceptance for retroreflectivity.
					6	Oct 1, 2021	haggaj1	\$2,700.00	40% was withheld on Estimate 0004 pending retroreflectivity testing. Testing was completed and material met retroreflectivity specifications. This adjustment is to pay the contractor the withheld amount
				OTHR - Tota	al			\$0.00	
			Other Item	Adjustment -	Total			\$0.00	
	0200 -	Total						\$0.00	
	0210	4 IN. YELLOW WATERBORNE PAVEMENT	Material		4	Sep 2, 2021	SYSTEM	\$4,245.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user haggaj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
		MARKING			4	Sep 2, 2021	SYSTEM	(\$4,245.20)	
					5	Sep 16, 2021	SYSTEM	\$4,245.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user haggaj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					5	Sep 16, 2021	SYSTEM	(\$4,245.20)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Other Item Adjustment	OTHR	4	Sep 2, 2021	haggaj1	(\$2,100.00)	This adjustment is to withhold a portion pavement marking pay. This portion will be paid after acceptance for retroreflectivity.
					6	Oct 1, 2021	haggaj1	\$2,100.00	40% was withheld on Estimate 0004 pending retroreflectivity testing. Testing was completed and material met retroreflectivity specifications. This adjustment is to pay the contractor the withheld amount
				OTHR - Tota	al			\$0.00	
			Other Item	Adjustment -	Total			\$0.00	
	0210 -	Total						\$0.00	
J2S3189	Total							\$5,047.58	
J2S3238	0220	GRAVEL (A) OR CRUSHED STONE (B)	Material		4	Sep 2, 2021	SYSTEM	\$3,389.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user haggaj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Sep 2, 2021	SYSTEM	(\$3,389.80)	



				1					
Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
			1,750	Туре	rtarribor	Date	D,		
J2S3238	0220	GRAVEL (A) OR CRUSHED STONE (B)	Material		5	Sep 16, 2021	SYSTEM	\$6,471.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user haggaj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					5	Sep 16, 2021	SYSTEM	(\$6,471.56)	
					6	Oct 1, 2021	SYSTEM	\$6,471.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user haggaj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					6	Oct 1, 2021	SYSTEM	(\$6,471.56)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0220 -	Total						\$0.00	
	0230	BITUMINOUS PAVEMENT MIXTURE	Material		4	Sep 2, 2021	SYSTEM	\$373,162.07	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user haggaj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
		PG64-22 (SUR			4	Sep 2, 2021	SYSTEM	(\$373,162.07)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Other Item Adjustment	ACAD	4	Sep 2, 2021	haggaj1	\$23,417.64	Adjustment was calculated using department approved spreadsheets with following factors: 7346.71 Tons with a Virgin AC of 3.00%
					5	Sep 16, 2021	haggaj1	\$267.19	Adjustment calculated electronically using department approved Excel Spreadsheets with the following data: 82.85 Tons of Mix ID SL 19-21, with a virgin AC of 3.00%.
				ACAD - Tota	al			\$23,684.83	
				FUEL	7	Oct 20, 2021	haggaj1	(\$0.66)	Quantity correction had to be made to this item for 1 ton of asphalt. Because the DWR where the correction was posted was a different estimate period then that in which the material was placed and accepted, the SYSTEM generated Fuel Adjustment was in error when checked with manual calculations. This adjustment corrects the total Fuel Adjustment paid in AWP for this Line Item to the total manually calculated.
				FUEL - Tota	ıl			(\$0.66)	
			Other Item	Adjustment -	Total			\$23,684.17	
			Price FUEL		4	Sep 2, 2021	SYSTEM	\$19,754.08	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					5	Sep 16, 2021	SYSTEM	\$198.04	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					7	Oct 20, 2021	SYSTEM	\$3.35	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$19,955.47	
			Price FUEL	- Total				\$19,955.47	
	0230 -	Total						\$43,639.64	
	0240	TACK COAT	Material		4	Sep 2, 2021	SYSTEM	\$14,963.29	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user haggaj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					4	Sep 2, 2021	SYSTEM	(\$14,963.29)	
					5	Sep 16, 2021	SYSTEM	\$14,963.29	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user haggaj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					5	Sep 16, 2021	SYSTEM	(\$14,963.29)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Overrun	Overrun	4	Sep 2, 2021	SYSTEM	\$345.47	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 23 on the current Payment Estimate. Material Insufficiency Quantity 7753.000; Overrun Quantity Balance 179.00.
					4	Sep 2,	SYSTEM	(\$345.47)	
						2021			



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
J2S3238	0240	TACK COAT	Overrun	Type Overrun	5	Sep 16, 2021	SYSTEM	(\$345.47)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					5	Sep 16, 2021	SYSTEM	\$345.47	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) overridding Payment Estimate Exception 14 on the current Payment Estimate. Material Insufficiency Quantity 7753.000; Overrun Quantity Balance 179.00.
					6	Oct 1, 2021	SYSTEM	(\$345.47)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				Overrun - T	otal			(\$345.47)	
			Overrun - T	otal				(\$345.47)	
	0240 -	Total						(\$345.47)	
	0300	4 IN. WHITE WATERBORNE PAVEMENT	Material		4	Sep 2, 2021	SYSTEM	\$8,226.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user haggaj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
		MARKING			4	Sep 2, 2021	SYSTEM	(\$8,226.20)	
					5	Sep 16, 2021	SYSTEM	\$8,226.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user haggaj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					5	Sep 16, 2021	SYSTEM	(\$8,226.20)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Other Item Adjustment	OTHR	4	Sep 2, 2021	haggaj1	(\$4,100.00)	This adjustment is to withhold a portion pavement marking pay. This portion will be paid after acceptance for retroreflectivity.
				OTHR - Tota	al			(\$4,100.00)	
			Other Item /	Adjustment -	Total			(\$4,100.00)	
	0300 -	Total						(\$4,100.00)	
	0310	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	Material		4	Sep 2, 2021	SYSTEM	\$7,588.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user haggaj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
		WARKING			4	Sep 2, 2021	SYSTEM	(\$7,588.30)	
					5	Sep 16, 2021	SYSTEM	\$7,588.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user haggaj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					5	Sep 16, 2021	SYSTEM	(\$7,588.30)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Other Item Adjustment	OTHR	4	Sep 2, 2021	haggaj1	(\$3,700.00)	This adjustment is to withhold a portion pavement marking pay. This portion will be paid after acceptance for retroreflectivity.
				OTHR - Tota	al			(\$3,700.00)	
			Other Item /	Adjustment -	Total			(\$3,700.00)	
	0310 -	Total						(\$3,700.00)	
J2S3238 -	Total							\$35,494.17	
J2S3303	0330	MISC. AGGREGATE FOR BASE	Material		5	Sep 16, 2021	SYSTEM	\$20,246.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user haggaj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	Sep 16, 2021	SYSTEM	(\$20,246.75)	
					6	Oct 1, 2021	SYSTEM	\$70,297.23	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user haggaj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Oct 1, 2021	SYSTEM	(\$70,297.23)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Overrun	Overrun	6	Oct 1, 2021	SYSTEM	\$6,087.05	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 6 on the current Payment Estimate. Material Insufficiency Quantity 6102.190;



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J2S3303	0330	MISC. AGGREGATE FOR BASE	Overrun	Overrun					Overrun Quantity Balance 528.39.
					6	Oct 1, 2021	SYSTEM	(\$6,087.05)	
					7	Oct 20, 2021	SYSTEM	(\$6,087.05)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				Overrun - T	otal			(\$6,087.05)	
			Overrun - T	otal				(\$6,087.05)	
	0330 -	· Total						(\$6,087.05)	
	0340	BITUMINOUS PAVEMENT MIXTURE	Other Item Adjustment	ACAD	5	Sep 16, 2021	haggaj1	\$41,599.28	Adjustment calculated electronically using department approved Excel Spreadsheets with the following data: 12899 Tons of Mix ID SL 19-21, with a virgin AC of 3.00%.
		PG64-22 (SUR		ACAD - Tota	al			\$41,599.28	
			Other Item	Adjustment -	djustment - Total				
			Overrun	Overrun	5	Sep 16, 2021	SYSTEM	(\$9,552.13)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				Overrun - Total				(\$9,552.13)	
			Overrun - T	otal	al				
			Price FUEL		5	Sep 16, 2021	SYSTEM	\$30,833.77	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$30,833.77	
			Price FUEL	- Total				\$30,833.77	
	0340 -	- Total						\$62,880.92	
	0350	TACK COAT	Material		5	Sep 16, 2021	SYSTEM	\$26,576.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user haggaj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					5	Sep 16, 2021	SYSTEM	(\$26,576.10)	
				- Total				\$0.00	
			Material - To					\$0.00	
	0350 -	- Total	Material - To						
	0350 - 0410	PREF THERMO PVMT MARK,	Material - To		6	Oct 1, 2021	SYSTEM	\$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user haggaj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		PREF THERMO			6		SYSTEM SYSTEM	\$0.00 \$0.00	Estimate Item Adjustment (0005) due to user haggaj1 overridding Payment
		PREF THERMO PVMT MARK,				2021 Oct 1,		\$0.00 \$0.00 \$750.00	Estimate Item Adjustment (0005) due to user haggaj1 overridding Payment
		PREF THERMO PVMT MARK,			6	2021 Oct 1, 2021 Oct 20,	SYSTEM	\$0.00 \$0.00 \$750.00 (\$750.00)	Estimate Item Adjustment (0005) due to user haggaj1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user haggaj1 overridding Payment
		PREF THERMO PVMT MARK,			6	2021 Oct 1, 2021 Oct 20, 2021 Oct 20,	SYSTEM	\$0.00 \$0.00 \$750.00 (\$750.00)	Estimate Item Adjustment (0005) due to user haggaj1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user haggaj1 overridding Payment
		PREF THERMO PVMT MARK,		otal - Total	6	2021 Oct 1, 2021 Oct 20, 2021 Oct 20,	SYSTEM	\$0.00 \$0.00 \$750.00 (\$750.00) \$750.00	Estimate Item Adjustment (0005) due to user haggaj1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user haggaj1 overridding Payment
		PREF THERMO PVMT MARK, 24 IN WHIT	Material	otal - Total	6	2021 Oct 1, 2021 Oct 20, 2021 Oct 20,	SYSTEM	\$0.00 \$0.00 \$750.00 (\$750.00) \$750.00 (\$750.00)	Estimate Item Adjustment (0005) due to user haggaj1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user haggaj1 overridding Payment
	0410	PREF THERMO PVMT MARK, 24 IN WHIT	Material	otal - Total	6	2021 Oct 1, 2021 Oct 20, 2021 Oct 20,	SYSTEM	\$0.00 \$0.00 \$750.00 (\$750.00) \$750.00 (\$750.00) \$0.00	Estimate Item Adjustment (0005) due to user haggaj1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user haggaj1 overridding Payment
	0410	PREF THERMO PVMT MARK, 24 IN WHIT	Material Material - To	otal - Total	7	2021 Oct 1, 2021 Oct 20, 2021 Oct 20, 2021 Oct 1,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$750.00 (\$750.00) \$750.00 (\$750.00) \$0.00 \$0.00	Estimate Item Adjustment (0005) due to user haggaj1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user haggaj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user haggaj1 overridding Payment
	0410	PREF THERMO PVMT MARK, 24 IN WHIT	Material Material - To	otal - Total	6 7 7	2021 Oct 1, 2021 Oct 20, 2021 Oct 20, 2021 Oct 20, 2021 Oct 1, 2021	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$750.00 (\$750.00) \$750.00 (\$750.00) \$0.00 \$0.00 \$350.00	Estimate Item Adjustment (0005) due to user haggaj1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user haggaj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user haggaj1 overridding Payment
	0410	PREF THERMO PVMT MARK, 24 IN WHIT	Material Material - To	otal - Total	6 7 7 6 6	2021 Oct 1, 2021 Oct 20, 2021 Oct 20, 2021 Oct 1, 2021 Oct 1, 2021 Oct 1, 2021 Oct 20,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$750.00 (\$750.00) \$750.00 (\$750.00) \$0.00 \$0.00 \$350.00	Estimate Item Adjustment (0005) due to user haggaj1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user haggaj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user haggaj1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user haggaj1 overridding Payment Estimate Item Adjustment (0004) due to user haggaj1 overridding Payment
	0410	PREF THERMO PVMT MARK, 24 IN WHIT	Material Material - To	otal - Total	6 7 7 6 6 7	2021 Oct 1, 2021 Oct 20, 2021 Oct 1, 2021 Oct 1, 2021 Oct 1, 2021 Oct 20, 2021 Oct 20, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$750.00 (\$750.00) \$750.00 (\$750.00) \$0.00 \$0.00 \$350.00 (\$350.00)	Estimate Item Adjustment (0005) due to user haggaj1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user haggaj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user haggaj1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user haggaj1 overridding Payment Estimate Item Adjustment (0004) due to user haggaj1 overridding Payment
	0410	PREF THERMO PVMT MARK, 24 IN WHIT	Material Material - To	- Total	6 7 7 6 6 7	2021 Oct 1, 2021 Oct 20, 2021 Oct 1, 2021 Oct 1, 2021 Oct 1, 2021 Oct 20, 2021 Oct 20, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$750.00 (\$750.00) \$750.00 (\$750.00) \$0.00 \$0.00 \$350.00 (\$350.00)	Estimate Item Adjustment (0005) due to user haggaj1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user haggaj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user haggaj1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user haggaj1 overridding Payment Estimate Item Adjustment (0004) due to user haggaj1 overridding Payment
	0410 - 0410 - 0420	PREF THERMO PVMT MARK, 24 IN WHIT	Material - To	- Total	6 7 7 6 6 7	2021 Oct 1, 2021 Oct 20, 2021 Oct 1, 2021 Oct 1, 2021 Oct 1, 2021 Oct 20, 2021 Oct 20, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$750.00 (\$750.00) \$750.00 (\$750.00) \$0.00 \$0.00 \$350.00 (\$350.00) \$350.00	Estimate Item Adjustment (0005) due to user haggaj1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user haggaj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user haggaj1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user haggaj1 overridding Payment Estimate Item Adjustment (0004) due to user haggaj1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J2S3303	0430	MARKING	Other Item Adjustment	OTHR - Tota	- Total			(\$4,036.00)	
			Other Item	Other Item Adjustment - Total					
	0430 -	- Total						(\$4,036.00)	
	0440	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	Other Item Adjustment	OTHR	6	Oct 1, 2021	haggaj1	(\$1,725.00)	This adjustment is to withhold 40% of posted quantity, pending retroreflectivity testing, and will be released upon acceptance for retroreflectivity.
				OTHR - Tota	al			(\$1,725.00)	
			Other Item	Adjustment - Total				(\$1,725.00)	
	0440 -	0 - Total						(\$1,725.00)	
J2S3303	- Total							\$51,032.87	
J2S3308	0470	EMULSIFIED	Other Item	ACAD	2	Aug 2,	haggaj1	\$10,251.42	Adjustment calculated using department approved methods with the following
	0470	ASPHALT,	Adjustment	710715	_	2021	naggaj.	ψ10,201112	factors: 38511 Gallons at 60 Degrees F.
		SEAL COAT		ACAD - Tota	al			\$10,251.42	
				OTHR	2	Aug 2, 2021	haggaj1	(\$15,250.36)	Per Section 409, Seal Coat Work may not be accepted until 14 Days after completion of the work. Per direction from MoDOT Management, 20% Withheld and will be paid back to contractor upon acceptance of the work.
					3	Aug 15, 2021	haggaj1	\$15,250.36	20% was withheld on previous estimate, pending acceptance of Seal Coat work. This Adjustment releases the withheld amount.
				OTHR - Tota	OTHR - Total			\$0.00	
			Other Item /	Other Item Adjustment - Total				\$10,251.42	
	0470 -	Total						\$10,251.42	
	0480	SEAL COAT AGGREGATE, GRADE A2	Material		2	Aug 2, 2021	SYSTEM	\$99,453.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user haggaj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					2	Aug 2, 2021	SYSTEM	(\$99,453.40)	
					3	Aug 16, 2021	SYSTEM	\$93,459.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user phillf2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Aug 16, 2021	SYSTEM	(\$93,459.20)	
					4	Sep 2, 2021	SYSTEM	\$93,459.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user haggaj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					4	Sep 2, 2021	SYSTEM	(\$93,459.20)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Other Item Adjustment	OTHR	2	Aug 2, 2021	haggaj1	(\$19,890.70)	Per Section 409, Seal Coat Work may not be accepted until 14 Days after completion of the work. Per direction from MoDOT Management, 20% Withheld and will be paid back to contractor upon acceptance of the work.
					3	Aug 15, 2021	haggaj1	\$14,918.01	20% was withheld on previous estimate, pending acceptance of Seal Coat work. Seal Coat has been accepted and this Adjustment releases the withheld amount except 5% being withheld due to CRE2O report has not been submitted as of this estimate. A total payment of \$14,918.01 will be released on estimate 0003.
					7	Oct 20, 2021	haggaj1	\$4,972.69	5% of the final quantity of line item pay was withheld on previous estimates, pending completion of CRE2.0 Reports by the contractor. This adjustment restores withheld pay.
				OTHR - Total				\$0.00	
			Other Item Adjustment - Total					\$0.00	
	0480 -	Total						\$0.00	
	0540	4 IN. WHITE WATERBORNE PAVEMENT MARKING	Material		4	Sep 2, 2021	SYSTEM	\$11,163.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user haggaj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					4	Sep 2, 2021	SYSTEM	(\$11,163.30)	
					5	Sep 16, 2021	SYSTEM	\$11,163.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user haggaj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					5	Sep 16,	SYSTEM	(\$11,163.30)	





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J2S3308	0540	4 IN. WHITE WATERBORNE PAVEMENT MARKING	Material			2021			
				- Total				\$0.00	
			Material - Total					\$0.00	
			Other Item Adjustment	OTHR	4	Sep 2, 2021	haggaj1	(\$5,500.00)	This adjustment is to withhold a portion pavement marking pay. This portion will be paid after acceptance for retroreflectivity.
					6	Oct 1, 2021	haggaj1	\$5,500.00	40% was withheld on Estimate 0004 pending retroreflectivity testing. Testing was completed and material met retroreflectivity specifications. This adjustment is to pay the contractor the withheld amount.
				OTHR - Total				\$0.00	
			Other Item	Other Item Adjustment - Total					
	0540 -	- Total						\$0.00	
	0550	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	Material		4	Sep 2, 2021	SYSTEM	\$9,129.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user haggaj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					4	Sep 2, 2021	SYSTEM	(\$9,129.60)	
					5	Sep 16, 2021	SYSTEM	\$9,129.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user haggaj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					5	Sep 16, 2021	SYSTEM	(\$9,129.60)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Other Item Adjustment	OTHR	4	Sep 2, 2021	haggaj1	(\$4,500.00)	This adjustment is to withhold a portion pavement marking pay. This portion will be paid after acceptance for retroreflectivity.
					6	Oct 1, 2021	haggaj1	\$4,500.00	40% was withheld on Estimate 0004 pending retroreflectivity testing. Testing was completed and material met retroreflectivity specifications. This adjustment is to pay the contractor the withheld amount
				OTHR - Total				\$0.00	
			Other Item	Other Item Adjustment - Total					
	0550 -	· Total						\$0.00	
J2S3308	J2S3308 - Total								
Overall -	Total							\$121,110.23	