

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: July 16, 2021

Progress Estimate Number	Contract ID	201218-B06	Pay Period Start	July 1, 2021	Original Contract Amount	\$1,591,332.04
8	Prime Contractor	Emery Sapp & Sons, Inc.	Pay Period End	July 15, 2021	Net Change Order Amount Current Contract Amount	

proval Date		By User
16, 2021	Generated and Approved (and should be considered Draft) at the Project Office Level by	shrumt1
16, 2021	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	lincom
19, 2021	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
November 1, 2021	November 1, 2021		27.01%

	Milestones		
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract
Acceptance Date			
Awarded Date	January 6, 2021	January 6, 2021	
Letting Date	December 18, 2020	December 18, 2020	
Notice to Proceed Date	February 8, 2021	February 8, 2021	
Work Began Date			

Contract Total Pa	y For Estimate No. 8				
		This Estimate	Previous	To Date	
201218-B06					
	Total Posted Items Pay	\$0.00	\$431,963.87	\$431,963.87	
	Gross Item Adjustments	\$0.00	\$12,524.64	\$12,524.64	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
			\$444,488.51	\$444,488.51	
Contract Total Pag	yable This Estimate:	\$0.00			

Items Paid This Estimate Period

No Data Available

Contract Adjustments This Estimate

		etments Exist on Contract ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J2S3347	0260	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material			-887	\$11.20	(\$9,934.40)
	0260	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user shrumt1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	887	\$11.20	\$9,934.40
	0300	SIDEWALK HAND-RAILING WITHOUT BALUSTERS	Material			-38	\$231.75	(\$8,806.50)
	0300	SIDEWALK HAND-RAILING WITHOUT BALUSTERS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user shrumt1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	38	\$231.75	\$8,806.50
	0390	MISC.	Material			-8	\$1,960.00	(\$15,680.00)
	0390	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user shrumt1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	8	\$1,960.00	\$15,680.00
Total								\$0.00

Revision 4/1/2020 Page 1 of 9



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Information	n
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J2S3300	FAS S201(56)	Resurface	В	LEWIS	from Rte. 61 north of Can	ton to south of LaGrange a	t Rte. 61
J2S3347	FAS S201(78)	Sidewalk improvements	В	LEWIS	from Henderson Ave. to C	oak St. in Canton and from	Poage St. to Polk St. in LaGrange
Totals by J	lob Numbe	rs					
J2S3300					This Estimate	Previous	To Date
		d Item Pay Item Adjustme		_	\$0.00 \$0.00	\$6,834.00 \$12,524.64	\$6,834.00 \$12,524.64
			Gross I	tem Pay	\$0.00	\$19,358.64	\$19,358.64
	Incent				\$0.00	\$0.00	\$0.00
		entive			\$0.00	\$0.00	\$0.00
		lated Damages			\$0.00	\$0.00	\$0.00
	Other	Contract Adjus	tments		\$0.00	\$0.00	\$0.00
J2S3347					This Estimate	Previous	To Date
0200041	Posto	d Item Pay			\$0.00	\$425,129.87	\$425,129.87
		ltem Adjustme	nts		\$0.00	\$0.00	\$0.00
	51033	nom Adjustine		tem Pay	\$0.00	\$425,129.87	\$425,129.87
	Incent	ilvo			\$0.00	\$0.00	\$0.00
	Disino				\$0.00	\$0.00	\$0.00
		lated Damages			\$0.00	\$0.00	\$0.00
		Contract Adius	tments		\$0.00	\$0.00	\$0.00

Revision 4/1/2020 Page 2 of 9



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J2S3347, Item 3040504, Project Item Line Number 0260, Material Set 304050496, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	waiting on materials to clean up line item	shrumt1	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3347, Item 6084023, Project Item Line Number 0300, Material Set 6084023, Material 0712STSR - Railing for Steps or Handrail, Acceptance Action Generic 0712STSR is insufficient.	waiting on materials	shrumt1	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3347, Item 6149902, Project Item Line Number 0390, Material Set 6149902, Material 0614DFGTBP - Grates and Bearing Plates, Acceptance Action Generic 0614DFGTBP is insufficient.	waiting on materials	shrumt1	Overridden

Revision 4/1/2020 Page 3 of 9



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

te: Posted Q	luantities	and valu	es are L	aseu on K	eport Generated date and can differ from the posted amo	ount at the i	iiiie uie i	_Sumate wa	3 Oction	aleu.		
Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
01218-B06	J2S3300	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.00	\$3,000.00	\$0.00
		0001	0020	2153000	SHAPING SLOPES, CLASS III	3.00	0.00	3.00	100F	0.00	\$1,600.00	\$0.00
		0001	0030	3105002	GRAVEL (A) OR CRUSHED STONE (B)	283.00	0.00	283.00	TONS	0.00	\$60.00	\$0.00
		0001	0040	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	14,586.90	0.00	14,586.90	TONS	0.00	\$63.40	\$0.00
		0001	0050	4071005	TACK COAT	16,471.00	0.00	16,471.00	GAL	0.00	\$2.00	\$0.00
		0001	0060	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$750.00	\$0.00
		0001	0070	6161005	CONSTRUCTION SIGNS	995.00	0.00	995.00	SQFT	0.00	\$7.00	\$0.0
		0001	0800	6161009	FLAG ASSEMBLY	4.00	0.00	4.00	EA	0.00	\$23.00	\$0.0
		0001	0090	6161025	CHANNELIZER (TRIM LINE)	270.00	0.00	270.00	EA	0.00	\$21.00	\$0.0
		0001	0100	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	0.00	\$2,300.00	\$0.0
		0001	0110	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$36,000.00	\$0.0
		0001	0111	6181000	MOBILIZATION	0.00	1.00	1.00	LS	0.00	\$29,166.00	\$0.0
		0001	0120	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	3.00	0.00	3.00	EA	0.00	\$315.00	\$0.0
		0001	0130	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	102,900.00	0.00	102,900.00	LF	0.00	\$0.11	\$0.0
		0001	0140	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	81,110.00	0.00	81,110.00	LF	0.00	\$0.11	\$0.0
		0001	0150	6206125A	24 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	230.00	0.00	230.00	LF	0.00	\$4.50	\$0.0
		0001	0160	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	51,259.00	0.00	51,259.00	SQYD	0.00	\$0.80	\$0.0
		0001	0170	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS) 2,978.00 0.00 2,978.00 SQYD 0.00							\$0.0
		0010	0180	6061011A	GUARDRAIL TYPE A, 7 FT. POST, 3 FT 1.5 IN SPACING	38.00	0.00	38.00	LF	0.00	\$36.00	\$0.
		0010	0190	6061060	MGS GUARDRAIL	38.00	0.00	38.00	LF	0.00	\$29.10	\$0.0
		0010	0200	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	3.00	0.00	3.00	EA	0.00	\$3,400.00	\$0.
		0010	0210	6062202A	BRIDGE ANCHOR SECTION, 7.5 FT. POSTS (SAFETY BARRIER CURB) (ROADWAY AND REHABILITATION WORK ONLY)	1.00	0.00	1.00	EA	0.00	\$2,015.00	\$0.
		0010	0220	6062304	ASYMETRICAL TRANSITION SECTION, 7.5 FT. POSTS	1.00	0.00	1.00	EA	0.00	\$675.00	\$0.
		0010	0230	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	3.00	0.00	3.00	EA	0.00	\$3,135.00	\$0.
		0010	0240	6066610	END ANCHOR	1.00	0.00	1.00	EA	0.00	\$1,350.00	\$0.
		0001	5001	6189901	MISC.Mobilization Contract Bond	0.00	1.00	1.00	LS	1.00	\$6,834.00	\$6,834.
	Project J	2S3300 - To	otal Value	Posted to D	late as of Report Generated Date							
	J2S3347	0004			ace as of Report Generaled Date							\$6,834
		0001	0250	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$62,700.00	
		0001	0250			1.00	0.00	1.00	LS SQYD	1.00	\$62,700.00 \$11.20	\$62,700
				2022010	REMOVAL OF IMPROVEMENTS							\$62,700 \$9,934
		0001	0260	2022010 3040504	REMOVAL OF IMPROVEMENTS TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	887.00	0.00	887.00	SQYD	887.00	\$11.20	\$62,700 \$9,934 \$31,360
		0001	0260	2022010 3040504 6042020	REMOVAL OF IMPROVEMENTS TYPE 5 AGGREGATE FOR BASE (4 IN. THICK) ADJUSTING BASIN OR INLET	887.00 8.00	0.00	887.00	SQYD EA	887.00 8.00	\$11.20 \$3,920.00	\$62,700. \$9,934. \$31,360. \$48,048.
		0001 0001 0001	0260 0270 0280	2022010 3040504 6042020 6081010	REMOVAL OF IMPROVEMENTS TYPE 5 AGGREGATE FOR BASE (4 IN. THICK) ADJUSTING BASIN OR INLET CONCRETE CURB RAMP	887.00 8.00 295.00	0.00	887.00 8.00 295.00	SQYD EA SQYD	887.00 8.00 286.00	\$11.20 \$3,920.00 \$168.00	\$62,700. \$9,934. \$31,360. \$48,048. \$19,084.
		0001 0001 0001 0001	0260 0270 0280 0290	2022010 3040504 6042020 6081010 6081012	REMOVAL OF IMPROVEMENTS TYPE 5 AGGREGATE FOR BASE (4 IN. THICK) ADJUSTING BASIN OR INLET CONCRETE CURB RAMP TRUNCATED DOMES	887.00 8.00 295.00 446.00	0.00 0.00 0.00	887.00 8.00 295.00 446.00	SQYD EA SQYD SQFT	887.00 8.00 286.00 426.00	\$11.20 \$3,920.00 \$168.00 \$44.80	\$62,700. \$9,934. \$31,360. \$48,048. \$19,084.
		0001 0001 0001 0001 0001	0260 0270 0280 0290 0300	2022010 3040504 6042020 6081010 6081012 6084023	REMOVAL OF IMPROVEMENTS TYPE 5 AGGREGATE FOR BASE (4 IN. THICK) ADJUSTING BASIN OR INLET CONCRETE CURB RAMP TRUNCATED DOMES SIDEWALK HAND-RAILING WITHOUT BALUSTERS	887.00 8.00 295.00 446.00 38.00	0.00 0.00 0.00 0.00	887.00 8.00 295.00 446.00 38.00	SQYD EA SQYD SQFT LF	887.00 8.00 286.00 426.00 38.00	\$11.20 \$3,920.00 \$168.00 \$44.80 \$231.75	\$62,700 \$9,934 \$31,360 \$48,048 \$19,084 \$8,806 \$17,908
		0001 0001 0001 0001 0001	0260 0270 0280 0290 0300 0310	2022010 3040504 6042020 6081010 6081012 6084023 6085008	REMOVAL OF IMPROVEMENTS TYPE 5 AGGREGATE FOR BASE (4 IN. THICK) ADJUSTING BASIN OR INLET CONCRETE CURB RAMP TRUNCATED DOMES SIDEWALK HAND-RAILING WITHOUT BALUSTERS PAVED APPROACH, 8 IN.	887.00 8.00 295.00 446.00 38.00	0.00 0.00 0.00 0.00 0.00 76.00	887.00 8.00 295.00 446.00 38.00 213.20	SQYD EA SQYD SQFT LF SQYD	887.00 8.00 286.00 426.00 38.00 213.20	\$11.20 \$3,920.00 \$168.00 \$44.80 \$231.75 \$84.00	\$62,700. \$9,934. \$31,360. \$48,048. \$19,084. \$8,806. \$17,908.
		0001 0001 0001 0001 0001 0001	0260 0270 0280 0290 0300 0310	2022010 3040504 6042020 6081010 6081012 6084023 6085008 6086004	REMOVAL OF IMPROVEMENTS TYPE 5 AGGREGATE FOR BASE (4 IN. THICK) ADJUSTING BASIN OR INLET CONCRETE CURB RAMP TRUNCATED DOMES SIDEWALK HAND-RAILING WITHOUT BALUSTERS PAVED APPROACH, 8 IN. CONCRETE SIDEWALK, 4 IN.	887.00 8.00 295.00 446.00 38.00 137.20 399.50	0.00 0.00 0.00 0.00 0.00 76.00	887.00 8.00 295.00 446.00 38.00 213.20 399.50	SQYD EA SQYD SQFT LF SQYD SQYD	887.00 8.00 286.00 426.00 38.00 213.20 377.30	\$11.20 \$3,920.00 \$168.00 \$44.80 \$231.75 \$84.00 \$76.15	\$62,700 \$9,934 \$31,360 \$48,048 \$19,084 \$8,806 \$17,908 \$28,731 \$2,700
		0001 0001 0001 0001 0001 0001 0001	0260 0270 0280 0290 0300 0310 0320	2022010 3040504 6042020 6081010 6084023 6085008 6086004 6089902	REMOVAL OF IMPROVEMENTS TYPE 5 AGGREGATE FOR BASE (4 IN. THICK) ADJUSTING BASIN OR INLET CONCRETE CURB RAMP TRUNCATED DOMES SIDEWALK HAND-RAILING WITHOUT BALUSTERS PAVED APPROACH, 8 IN. CONCRETE SIDEWALK, 4 IN. MISC.TYPE E PRECAST SLAB	887.00 8.00 295.00 446.00 38.00 137.20 399.50	0.00 0.00 0.00 0.00 0.00 76.00 0.00	887.00 8.00 295.00 446.00 38.00 213.20 399.50	SQYD EA SQYD SQFT LF SQYD SQYD SQYD	887.00 8.00 286.00 426.00 38.00 213.20 377.30	\$11.20 \$3,920.00 \$168.00 \$44.80 \$231.75 \$84.00 \$76.15	\$62,700. \$9,934. \$31,360. \$48,048. \$19,084. \$8,806. \$17,908. \$28,731. \$2,700.
		0001 0001 0001 0001 0001 0001 0001 000	0260 0270 0280 0290 0300 0310 0320 0330	2022010 3040504 6042020 6081010 6081012 6084023 6085008 6086004 6089902	REMOVAL OF IMPROVEMENTS TYPE 5 AGGREGATE FOR BASE (4 IN. THICK) ADJUSTING BASIN OR INLET CONCRETE CURB RAMP TRUNCATED DOMES SIDEWALK HAND-RAILING WITHOUT BALUSTERS PAVED APPROACH, 8 IN. CONCRETE SIDEWALK, 4 IN. MISC.TYPE E PRECAST SLAB MISC.REINFORCED CONCRETE SIDEWALK, 4*	887.00 8.00 295.00 446.00 38.00 137.20 399.50 3.00 216.60	0.00 0.00 0.00 0.00 0.00 76.00 0.00	887.00 8.00 295.00 446.00 38.00 213.20 399.50 3.00 216.60	SQYD EA SQYD SQFT LF SQYD SQYD SQYD EA	887.00 8.00 286.00 426.00 38.00 213.20 377.30 3.00 216.60	\$11.20 \$3,920.00 \$168.00 \$44.80 \$231.75 \$84.00 \$76.15 \$900.00	\$62,700. \$9,934. \$31,360. \$48,048. \$19,084. \$8,806. \$17,908. \$28,731. \$2,700. \$18,194.
		0001 0001 0001 0001 0001 0001 0001 000	0260 0270 0280 0290 0300 0310 0320 0330 0340	2022010 3040504 6042020 6081010 6081012 6084023 6085008 6086004 6089902 6089905	REMOVAL OF IMPROVEMENTS TYPE 5 AGGREGATE FOR BASE (4 IN. THICK) ADJUSTING BASIN OR INLET CONCRETE CURB RAMP TRUNCATED DOMES SIDEWALK HAND-RAILING WITHOUT BALUSTERS PAVED APPROACH, 8 IN. CONCRETE SIDEWALK, 4 IN. MISC.TYPE E PRECAST SLAB MISC.REINFORCED CONCRETE SIDEWALK, 4* MISC.REINFORCED CONCRETE SIDEWALK, 8*	887.00 8.00 295.00 446.00 38.00 137.20 399.50 3.00 216.60	0.00 0.00 0.00 0.00 0.00 76.00 0.00 0.00	887.00 8.00 295.00 446.00 38.00 213.20 399.50 3.00 216.60 241.00	SQYD EA SQYD SQFT LF SQYD SQYD EA SQYD SQYD	887.00 8.00 286.00 426.00 38.00 213.20 377.30 3.00 216.60 241.00	\$11.20 \$3,920.00 \$168.00 \$44.80 \$231.75 \$84.00 \$76.15 \$900.00 \$84.00	\$62,700 \$9,934 \$31,360 \$48,048 \$19,084 \$8,806 \$17,908 \$28,731 \$2,700 \$18,194 \$22,931 \$2,576
		0001 0001 0001 0001 0001 0001 0001 000	0260 0270 0280 0290 0300 0310 0320 0330 0340 0350	2022010 3040504 6042020 6081010 6084023 6085008 6086004 6089902 6089905 6089905 6099010	REMOVAL OF IMPROVEMENTS TYPE 5 AGGREGATE FOR BASE (4 IN. THICK) ADJUSTING BASIN OR INLET CONCRETE CURB RAMP TRUNCATED DOMES SIDEWALK HAND-RAILING WITHOUT BALUSTERS PAVED APPROACH, 8 IN. CONCRETE SIDEWALK, 4 IN. MISC.TYPE E PRECAST SLAB MISC.REINFORCED CONCRETE SIDEWALK, 4" MISC.REINFORCED CONCRETE SIDEWALK, 8" CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	887.00 8.00 295.00 446.00 38.00 137.20 399.50 3.00 216.60 241.00	0.00 0.00 0.00 0.00 0.00 76.00 0.00 0.00	887.00 8.00 295.00 446.00 38.00 213.20 399.50 3.00 216.60 241.00	SQYD EA SQYD SQFT LF SQYD SQYD EA SQYD SQYD LF	887.00 8.00 286.00 426.00 38.00 213.20 377.30 3.00 216.60 241.00	\$11.20 \$3,920.00 \$168.00 \$44.80 \$231.75 \$84.00 \$76.15 \$900.00 \$84.00 \$95.15 \$56.00	\$62,700. \$9,934. \$31,360. \$48,048. \$19,084. \$8,806. \$17,908. \$28,731. \$2,700. \$18,194. \$22,931. \$2,576.
		0001 0001 0001 0001 0001 0001 0001 000	0260 0270 0280 0290 0300 0310 0320 0330 0340 0350 0360	2022010 3040504 6042020 6081010 6081012 6084023 6085008 6086004 6089902 6089905 6089905 6091010	REMOVAL OF IMPROVEMENTS TYPE 5 AGGREGATE FOR BASE (4 IN. THICK) ADJUSTING BASIN OR INLET CONCRETE CURB RAMP TRUNCATED DOMES SIDEWALK HAND-RAILING WITHOUT BALUSTERS PAVED APPROACH, 8 IN. CONCRETE SIDEWALK, 4 IN. MISC.TYPE E PRECAST SLAB MISC.REINFORCED CONCRETE SIDEWALK, 4" MISC.REINFORCED CONCRETE SIDEWALK, 8" CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S CONCRETE GUTTER TYPE B	887.00 8.00 295.00 446.00 38.00 137.20 399.50 3.00 216.60 241.00	0.00 0.00 0.00 0.00 0.00 76.00 0.00 0.00 0.00 0.00	887.00 8.00 295.00 446.00 38.00 213.20 399.50 3.00 216.60 241.00 46.00	SQYD EA SQYD SQFT LF SQYD SQYD EA SQYD SQYD LF	887.00 8.00 286.00 426.00 38.00 213.20 377.30 3.00 216.60 241.00 46.00	\$11.20 \$3,920.00 \$168.00 \$44.80 \$231.75 \$84.00 \$76.15 \$900.00 \$84.00 \$95.15 \$56.00	\$62,700.0 \$9,934.4 \$31,360.0 \$48,048.0 \$19,084.8 \$8,806.6 \$17,908.8 \$28,731.4 \$2,700.0 \$18,194.4 \$22,931.7 \$62,641.6
		0001 0001 0001 0001 0001 0001 0001 000	0260 0270 0280 0290 0300 0310 0320 0330 0340 0350 0360 0370	2022010 3040504 6042020 6081012 6084023 6085008 6086004 6089902 6089905 608905 6091010 6091042 6099903	REMOVAL OF IMPROVEMENTS TYPE 5 AGGREGATE FOR BASE (4 IN. THICK) ADJUSTING BASIN OR INLET CONCRETE CURB RAMP TRUNCATED DOMES SIDEWALK HAND-RAILING WITHOUT BALUSTERS PAVED APPROACH, 8 IN. CONCRETE SIDEWALK, 4 IN. MISC.TYPE E PRECAST SLAB MISC.REINFORCED CONCRETE SIDEWALK, 4* MISC.REINFORCED CONCRETE SIDEWALK, 8* CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S CONCRETE GUTTER TYPE B MISC.CURB AND GUTTER TYPE B, SPECIAL	887.00 8.00 295.00 446.00 38.00 137.20 399.50 3.00 246.60 46.00 12.00 1,646.00	0.00 0.00 0.00 0.00 0.00 76.00 0.00 0.00 0.00 0.00 0.00	887.00 8.00 295.00 446.00 38.00 213.20 399.50 3.00 216.60 241.00 46.00 12.00 1,646.00	SQYD EA SQYD SQFT LF SQYD EA SQYD EA SQYD LF LF	887.00 8.00 286.00 426.00 38.00 213.20 377.30 3.00 216.60 241.00 46.00 12.00 1,598.00	\$11.20 \$3,920.00 \$168.00 \$44.80 \$231.75 \$84.00 \$76.15 \$900.00 \$84.00 \$95.15 \$56.00 \$39.20	\$6,834.0 \$62,700.0 \$9,934.4 \$31,360.0 \$48,048.0 \$19,084.8 \$8,806.5 \$17,908.8 \$28,731.4 \$2,700.0 \$18,194.4 \$22,931.1 \$2,576.0 \$672.0 \$15,680.0 \$11,715.0

Revision 4/1/2020 Page 4 of 9



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
01218-B06	J2S3347	0001	0420	6161009	FLAG ASSEMBLY	3.00	0.00	3.00	EA	3.00	\$22.40	\$67.20
		0001	0430	6161025	CHANNELIZER (TRIM LINE)	60.00	0.00	60.00	EA	60.00	\$22.40	\$1,344.00
		0001	0440	6161030	TYPE III MOVEABLE BARRICADE	12.00	0.00	12.00	EA	4.00	\$123.15	\$492.60
		0001	0450	6169902	MISC.DETECTABLE PEDESTRIAN BARRICADE	8.00	0.00	8.00	EA	7.00	\$72.80	\$509.60
		0001	0460	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$36,200.00	\$36,200.00
		0001	0470	6200009	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE	610.00	0.00	610.00	LF	0.00	\$6.75	\$0.00
		0001	0480	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	28.00	0.00	28.00	EA	0.00	\$303.00	\$0.00
		0001	0490	6209903	MISC.PAINT CURB YELLOW	506.00	0.00	506.00	LF	0.00	\$2.25	\$0.00
		0001	0500	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$11,500.00	\$11,500.0
		0001	0510	8059901	MISC.SEEDING	1.00	0.00	1.00	LS	0.80	\$5,600.00	\$4,480.00
		0001	0520	8061006	ALTERNATE DITCH CHECK	20.00	0.00	20.00	LF	20.00	\$11.20	\$224.0
		0001	0530	8061007A	CURB INLET CHECK	28.00	0.00	28.00	EA	14.00	\$168.00	\$2,352.0
		0001	0540	8061016	SEDIMENT REMOVAL	36.00	0.00	36.00	CUYD	0.00	\$25.00	\$0.0
		0001	0550	8061019	SILT FENCE	353.00	0.00	353.00	LF	353.00	\$5.60	\$1,976.80
		0001	0560	8069901	MISC.TEMPORARY SEEDING AND MULCHING	1.00	0.00	1.00	LS	0.00	\$1,150.00	\$0.0
		0040	0570	9031010	CONCRETE FOOTINGS, EMBEDDED	1.80	0.00	1.80	CUYD	1.80	\$2,700.00	\$4,860.0
		0040	0580	9031270A	2 IN. PSST POST - 12 GA.	224.00	0.00	224.00	LF	224.00	\$18.00	\$4,032.0
		0040	0590	9031273	POST ANCHOR FOR 2 IN. PSST - 7 GA.	42.00	0.00	42.00	LF	42.00	\$45.00	\$1,890.0
		0040	0600	9035004A	SH-FLAT SHEET	6.00	0.00	6.00	SQFT	0.00	\$45.00	\$0.00
		0040	5002	6161005	CONSTRUCTION SIGNS	0.00	1.00	1.00	SQFT	1.00	\$1,400.00	\$1,400.0
	Project J	2S3347 - To	otal Value	Posted to D	ate as of Report Generated Date							\$425,129.8
1218-B06 Ove	rall - Total	Value Post	ted to Dat	te as of Repo	ort Generated Date							\$431,963.84

Revision 4/1/2020 Page 5 of 9



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work. The information below this line are details for Construction Signs (if applicable).

Project	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
J2S3347	0400	April 29, 2021	148	R11-2 48x30 10.00 ROAD CLOSED	461+00		Madison st.	1.00	10			10
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD	451+00		rt. B	1.00	16			16
				WO20-4 48x48 16.00 ONE LANE ROAD AHEAD	453+00		rt. B	1.00	16			16
				WO20-7 48x48 16.00 FLAGGER (SYMBOL) WITH FLAGS	455+00		rt. B Lt	1.00	16			16
				WO20-7 48x48 16.00 FLAGGER (SYMBOL) WITH FLAGS	466+00		Rt. B LT	1.00	16			16
				R9-11AL 24x18 3.00 SIDEWALK CLOSED AHEAD (LEFT)	461+00		madison st.	1.00	3			3
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD	470+00		rt. B LT	1.00	16			16
				R9-11AL 24x18 3.00 SIDEWALK CLOSED AHEAD (LEFT)	461+00		Madison dr.	1.00	3			3
				R9-11AL 24x18 3.00 SIDEWALK CLOSED AHEAD (LEFT)	461+00		Madison st.	1.00	3			3
				R9-11AL 24x18 3.00 SIDEWALK CLOSED AHEAD (LEFT)	461+00		madison st	1.00	3			3
				WO20-4 48x48 16.00 ONE LANE ROAD AHEAD	468+00		rt. B Lt	1.00	16			16
	0400 - To	tal										118

Revision 4/1/2020 Page 6 of 9



Line Item Adjustments by Estimate

Contract ID:190621-F01

Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
				Туре					
J2S3300	0180	GUARDRAIL TYPE A, 7 FT.	Construction Stockpile		1	Apr 1, 2021	SYSTEM	\$484.50	Payment Estimate Item Adjustment generated Stockpile Transaction
		POST, 3 FT - 1.5	STMI	- Total				\$484.50	
			Construction	Stockpile S	TMI - Total			\$484.50	
	0180 -	Total						\$484.50	
	0190	MGS GUARDRAIL	Construction Stockpile STMI		1	Apr 1, 2021	SYSTEM	\$514.14	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$514.14	
			Construction	Stockpile S	TMI - Total			\$514.14	
	0190 -							\$514.14	
	0200	MGS BRIDGE APP. TRANS SEC (REG/NO	Construction Stockpile STMI	- Total	1	Apr 1, 2021	SYSTEM	\$4,971.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		CURB)	0		FRAL T-4-1			\$4,971.00	
	0000		Construction	Stockpile S	I WII - I Otal			\$4,971.00	
	0200 -							\$4,971.00	
	0210	BRIDGE ANCHOR SECTION, 7.5	Construction Stockpile STMI	Total	1	Apr 1, 2021	SYSTEM	\$1,142.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		FT. POSTS	O a made a di	- Total	T			\$1,142.00	
			Construction	Stockpile S	TMI - Total			\$1,142.00	
	0210 -							\$1,142.00	
	0220	ASYMETRICAL TRANSITION SECTION, 7.5	Construction Stockpile STMI		1	Apr 1, 2021	SYSTEM	\$168.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		FT. POSTS		- Total				\$168.00	
			Construction	Stockpile S	TMI - Total			\$168.00	
	0220 -	Total						\$168.00	
	0230	TYPE A CRASHWORTHY END TERMINAL	Construction Stockpile STMI		1	Apr 1, 2021	SYSTEM	\$4,668.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		(MASH)		- Total				\$4,668.00	
			Construction	Stockpile S	TMI - Total			\$4,668.00	
	0230 -							\$4,668.00	
	0240	END ANCHOR	Construction Stockpile STMI	Total	1	Apr 1, 2021	SYSTEM	\$577.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			0 1 "	- Total n Stockpile STMI - Total				\$577.00	
	0040	Takal	Construction			\$577.00			
loosses	0240 -	Total						\$577.00	
J2S3300 - J2S3347		TYPE 5 AGGREGATE	Material		3	May 3, 2021	SYSTEM	\$12,524.64 \$2,329.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user shrumt1 overridding Payment
		FOR BASE			3	May 3,	SYSTEM	(\$2,329.60)	Estimate Exception 1 on the current Payment Estimate.
						2021		,	
					4	May 16, 2021	SYSTEM	\$5,577.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user shrumt1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	May 16, 2021	SYSTEM	(\$5,577.60)	
					5	Jun 1, 2021	SYSTEM	\$5,577.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user shrumt1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	Jun 1, 2021	SYSTEM	(\$5,577.60)	
					6	Jun 16, 2021	SYSTEM	\$9,934.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user shrumt1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Jun 16, 2021	SYSTEM	(\$9,934.40)	
					7	Jun 30, 2021	SYSTEM	\$9,934.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user shrumt1 overridding Payment Estimate Exception 1 on the current Payment Estimate.



Line Item Adjustments by Estimate

Contract ID:190621-F01

April	ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
S	47	0260	AGGREGATE	Material	Туре	7		SYSTEM	(\$9,934.40)	
Total						8		SYSTEM	\$9,934.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user shrumt1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
						8		SYSTEM	(\$9,934.40)	
SIDEWALK Material					- Total				\$0.00	
SCICKMALM Material A				Material - To	tal				\$0.00	
HAND-RAILING 2021		0260 -	Total						\$0.00	
4			HAND-RAILING WITHOUT	Material		4		SYSTEM	\$8,806.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user shrumt1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
2021 SysTem (88.806.50)						4		SYSTEM	(\$8,806.50)	
2021 6 Jun 16 SYSTEM \$8,806.50 This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.						5		SYSTEM	\$8,806.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user shrumt1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
2021						5		SYSTEM	(\$8,806.50)	
2021						6		SYSTEM	\$8,806.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user shrumt1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
2021 Estimate Item Adjustment (0003) due to user shrumrt1 overridding Payme Estimate Exception 2 on the current Payment Estimate.						6		SYSTEM	(\$8,806.50)	
2021 8						7		SYSTEM	\$8,806.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user shrumt1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
2021 SYSTEM Estimate Item Adjustment (0002) due to user shrumt overridding Paym Estimate Exception 2 on the current Payment Estimate.						7		SYSTEM	(\$8,806.50)	
2021 S0.00						8		SYSTEM	\$8,806.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user shrumt1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
Material - Total S0.00						8		SYSTEM	(\$8,806.50)	
Osophage					- Total				\$0.00	
Overrun				Material - Total					\$0.00	
APPROACH, 8 IN.									\$0.00	
6 Jun 16, 2021 (\$3,057.60) 7 Jun 30, 2021 \$YSTEM \$6,384.00 Unit price based on averaged overrun adjustments for installed quantity previous payment estimates. Price Adjustments of ',84,00000 - 84,0000 applied (if non-zero). Overrun - Total \$0.00 Overrun - Total \$0.00 MISC. CONCRETE Material 3 May 3, 2021 \$YSTEM \$900.00 CONCRETE \$0.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user shrumt1 overridding Payment Estimate Exception 2 on the current Payment Estimate. 3 May 3, SYSTEM \$0.00 Material - Total \$0.00 Material - Total \$0.00 Material - Total \$0.00 MISC. PAVED DRAINAGE Material 3 May 3, SYSTEM \$14,896.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user shrumt1 overridding Payment Estimate Item Adjustment (0003) due to user shrumt1 overridding Payment Estimate Item Adjustment (0003) due to user shrumt1 overridding Payment Estimate Exception 3 on the current Payment Estimate.		0310	APPROACH, 8	Overrun	Overrun		2021			
Dverrun - Total Overrun - Total So.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. 3 May 3, SYSTEM (\$900.00) - Total So.00 Material - Total So.00 Overrun - Total So.00 This adjustment offsets the original system-generated Material Payment So.00 Overrun - Total So.00 This adjustment offsets the original system-generated Material Payment So.00 Overrun - Total So.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user shrumt1 overridding Payment Estimate Exception 3 on the current Payment Estimate. 3 May 3, SYSTEM (\$14,896.00)						6		SYSTEM	(\$3,057.60)	
Overrun - Total \$0.00 O310 - Total						7		SYSTEM	\$6,384.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',84.00000 - 84.00000, 'is applied (if non-zero).
Solution					Overrun - Total				\$0.00	
Material Materi				Overrun - Total					\$0.00	
CONCRETE 2021 Bestimate Item Adjustment (0002) due to user shrumt1 overridding Paym Estimate Exception 2 on the current Payment Estimate. 3 May 3, 2021 - Total \$0.00 Material - Total \$0.00 0330 - Total \$0.00 Misc. PAVED DRAINAGE DRAINAGE 3 May 3, 2021 3 May 3, SYSTEM (\$14,896.00) 1 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user shrumt1 overridding Paym Estimate Exception 3 on the current Payment Estimate. 3 May 3, SYSTEM (\$14,896.00)									\$0.00	
2021 - Total \$0.00 Material - Total \$0.00 0330 - Total \$0.00 MISC. PAVED DRAINAGE DRAINAGE 3 May 3, 2021 3 May 3, SYSTEM \$14,896.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user shrumt1 overridding Payment Estimate Exception 3 on the current Payment Estimate.		0330	CONCRETE	Material		3		SYSTEM	\$900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user shrumt1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
Material - Total \$0.00 0330 - Total \$0.00 0380 MISC. PAVED DRAINAGE DRAINAGE Material 3 May 3, SYSTEM \$14,896.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user shrumt1 overridding Paym Estimate Exception 3 on the current Payment Estimate. 3 May 3, SYSTEM (\$14,896.00)						3		SYSTEM	(\$900.00)	
Solution									\$0.00	
0380 MISC. PAVED DRAINAGE Material DRAINAGE Material 3 May 3, 2021 SYSTEM \$14,896.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user shrumt1 overridding Payment Estimate Exception 3 on the current Payment Estimate. 3 May 3, SYSTEM (\$14,896.00)				Material - Total					\$0.00	
DRAINAGE 2021 Estimate Item Adjustment (0003) due to user shrumt1 overridding Paym Estimate Exception 3 on the current Payment Estimate. 3 May 3, SYSTEM (\$14,896.00)		0330 -	Total						\$0.00	
		0380		Material		3		SYSTEM	\$14,896.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user shrumt1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
						3		SYSTEM	(\$14,896.00)	
- Total \$0.00					- Total				\$0.00	

Jul 19, 2021



Line Item Adjustments by Estimate

Contract ID:190621-F01

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J2\$3347	0380	MISC. PAVED DRAINAGE	Material - To	Material - Total					
	0380 -	380 - Total						\$0.00	
	0390	MISC. DRAINAGE FITTINGS	Material		5	Jun 1, 2021	SYSTEM	\$9,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user shrumt1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					5	Jun 1, 2021	SYSTEM	(\$9,800.00)	
					6	Jun 16, 2021	SYSTEM	\$15,680.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user shrumt1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					6	Jun 16, 2021	SYSTEM	(\$15,680.00)	
					7	Jun 30, 2021	SYSTEM	\$15,680.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user shrumt1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					7	Jun 30, 2021	SYSTEM	(\$15,680.00)	
					8	Jul 16, 2021	SYSTEM	\$15,680.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user shrumt1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					8	Jul 16, 2021	SYSTEM	(\$15,680.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0390 -	Total						\$0.00	
J2S3347	- Total							\$0.00	
Overall -	Total							\$12,524.64	